Available from

NRC/GPO Sales Program

Superintendent of Documents Government Printing Office Washington, D. C. 20402

A year's subscription consists of 12 issues for this publication.

Single copies of this publication are available from National Technical Information Service, Springfield, VA 22161

Microfiche of single copies ure available from NRC/GPO Sales Program Washington, D. C. 20655

Title List of Documents Made Publicly Available

June 1-30, 1983

Division of Technical Information and Document Control Office of Administration
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555



CONTENTS

Preface	
Arrangement of Items by Docket Number	
Alphabetic Arrangement of Docket Items by Facility Name	xvii
Docketed Items	
Low Level Radwaste Disposal Sites — Docket 27	i
Domestic Licensing of Source Material — Docket 40	1
Domestic Licensing of Production and Utilization Facilities — Docket 50	7
Domestic Licensing of Special Nuclear Material — Docket 70	
Packaging of Radioactive Material for Transport and Transportation of	
Radioactive Material Under Certain Conditions — Docket 71	381
Licensing of Independent Spent Fuel Storage — Docket 72	
Nondocketed Items	
10 CFR — Commission Meeting Records	389
ACRS — Advisory Committee on Reactor Safeguards	
ADVCM — NRC Advisory Committees	
COMMISSION — NRC Commissioners	
CONTRACT — NRC Contracts and Modifications	
FOIA — Freedom of Information Act Requests and Releases	
GEN TECH IS — Generic Technical Issues	415
I&E — Inspection and Enforcement	
MISC — Public Document Room Miscellaneous	
NUREG — NUREG Reports and Related Correspondence	
ORG — Correspondence with Other Organizations	441
PR — Proposed Rule	
PRM — Petition for Rulemaking	445
PROJ — Projects - Predocket Licensing	445
PT 21 — Noncompliance Reports and Related Correspondence	
QA999 — Quality Assurance Inspections	
REGGD — Regulatory Guides	
RES — Research and Technical Assistance Reports	452
REVIEW GROUP — NRC Research Review Groups	
SECY — Position Papers Before the Commission	453
STATE PROG — State Programs	
TOPREP — Vendor Reports and Related Correspondence	455
WASH — Regulatory Publications - Pre-Nureg Series	
WASTE MGT — Nuclear Waste Management	
XPORTLIC — Export and Import Licenses	460
Personal Author Index	
Corporate Source Index	
Report Number Index	527
Cross Reference of Enclosures to Principal Documents	529
Appendix A — Definitions of Docket 50 Categories	A-1
Appendix B — Definitions of Nondocketed Categories	B-1

PREFACE

The Title List of Documents Made Publicly Available is a monthly publication. It contains descriptions of the information received and generated by the U.S. Nuclear Regulatory Commission (NRC) This information includes (1) docketed material associated with civilian nuclear power plants and other uses of radioactive materials and (2) nondocketed material received and generated by NRC pertinent to its role as a regulatory agency. As used here, docketed does not refer to Court dockets; it refers to the system by which NRC maintains its regulatory records. This series of documents is indexed by a Personal Author Index, a Corporate Source Index, and a Report Number Index.

The docketed information contained in the *Title List* includes the information formerly issued through the Department of Energy publication *Power Reactor Docket Information*, last published in January 1979. Microfiche of the docketed information listed in the *Title List* is available for sale on a subscription basis from the National Technical Information Service (NTIS). See NOTES at the end of the Preface for the complete NTIS address.

We encourage your comments, criticisms, and suggestions. In particular, if there are title descriptions that are not meaningful, please let us know so that we can correct the data base. In so far as possible, we would like this document to be a valuable part of your reference material.

DOCKETED ITEMS

The listings within Docket 50 are divided into the categories used for filing and searching in the NRC Public Document Room. Those categories are:

- A. Application/construction stage documents and correspondence
- B. Utility Preliminary Safety Analysis Report (PSAR), amendments
- C. Utility Environmental Report (ER), amendments and correspondence
- D. NRC Draft and Final Environmental (Impact) Statements (DES and FES), and correspondence
- E. NRC Safety Evaluation Report (SER), supplements and correspondence
- F. Security, medical, emergency and fire-protection plans
- G. Adjudicatory correspondence
- H. General correspondence
- I. Financial information
- J. Insurance and indemnity information
- K. Utility Final Safety Analysis Report (FSAR) and amendments
- L. Limited work authorization and related correspondence
- M. Antitrust correspondence
- N. Antitrust hearing transcripts
- O. Advisory Committee on Reactor Safeguards (ACRS) reports and correspondence
- P. Operating license stage documents and correspondence
- Q. Inspection reports, IE Bulletins and correspondence
- R. Periodic operating reports and related correspondence
- S. Reportable occurrences. LERs and related correspondence
- T. Hearing transcripts on non-antitrust matters
- U. Congressional/executive correspondence
- V. Licensing operators and related correspondence

- W. Decommissioning stage documents and correspondence
- X. Onsite low-level wastes storage

Appendix A sets forth those categories and describes the materials available in each. Omission of a category in the listing for a docket indicates that no documents in that category were filed in the time period of the report.

The principal elements of the entries in the list are:

P. Operating license stage documents & correspondence

2 3

8203090028 Responds to 820201 ltr requesting documents re environ qualification of electrical equipment. All nonproprietary repts will be provided to Franklin Research Ctr by 820408. Proprietary repts will be provided to NRC by 820510.

4 MILLS, L.M. 5 Tennessee Valley Authority. 6 82/03/04. 7 VASSALLO, D.B. Operating Reactors Branch 2. 8 Ip. 1216:254. 24XFiche: 50-259, 82/03/04, 8203090028.

- NRC/PDR Document category (see Appendix A).
- 2. NRC Accession Number (year, month, day, and sequence number of item).
- 3. Description of information contained in the document.
- 4. Personal author(s). An asterisk in this position indicates that there is no personal author.
- 5. Corporate, agency or nonindividual source.
- 6. Date of document described.
- 7. Recipient of document and NRC or corporate affiliation.
- 8. Pages in this document.
- 9. The NRC 48X microfiche designation for this document. This five-digit portion of this entry is the number of the microfiche copy of this document that is available to NRC staff who have access to 48X microfiche files.
- 10. This three-digit portion of this entry is the number of the frame on which this document starts.
- 11. The 24X Fiche designation consists of the docket number followed by the date of the document and the accession number for the document. This designation provides the information needed by subscribers to the National Technical Information Service docket microfiche to locate the document fiche.
- 12. If this space is blank, the document is available to the public only in the NRC Public Document Room, 1717 H St., N.W., Washington, D.C. 20555. If this space is filled, it gives other sources for copies of the document. The entry may be "Available at NRC" for sale; "Available at NTIS"; or "Available at GPO."

The Docketed Items list is arranged sequentially by Docket Number, category, and then by date of principal items. Entries indented and preceded by a dash are items that were submitted as enclosures to principal items. In general, indented items are not in accession number sequence. If the docketed document has a contract (FIN) number or a formal report number, it will appear in the last line of the item following entry 5.

NONDOCKETED ITEMS

The nondocketed items are divided into the categories used for filing and searching in the NRC Public Document Room. These categories and their symbols are:

10CFR — Commission Meeting Records
ACRS — Advisory Committee on Reactor Safeguards
COMMISSION — NRC Commissioners
CONTRACT — NRC Contracts and Modifications
DISCLOSURE — Financial Disclosure Information
FOIA — Freedom of Information Act Requests and Releases
GEN TECH IS — Generic Technical Issues

1&E - Inspection and Enforcement

MISC — Public Document Room Miscellaneous

NUREG - NUREG Reports and Related Correspondence

ORG — Correspondence with Other Organizations

PR -- Proposed Rule

PRM - Petition for Rulemaking

PROJ — Projects—Predocket Licensing

PT21 - Noncompliance Reports and Related Correspondence

QA999 — Quality Assurance Inspections

REGGD - Regulatory Guides

RES — Research and Technical Assistance Reports

REVIEW GRP — NRC Research Review Groups

RM — Rulemakings

SECY — Position Papers Before the Commission

STATE PROG — State Programs

TOPREP — Vendor Reports and Related Correspondence

WASH - Regulatory Publications-Pre-NUREG Series

WASTE MGT - Nuclear Waste Management

XPORTLIC - Export and Import Licenses

Appendix B sets forth these categories and describes the material available in each. Omission of a category in the listing for a docket indicates that no documents in that category were filed in the time period of the report.

The principal elements of the nondocketed items are:

NUREG-NUREG Reports and Related Correspondence

8203090207 NUREG/CR-1672 V02

RISK ASSESSMENT METHODOLOGY DEVELOPMENT FOR WASTE ISOLATION IN GEOLOGIC MEDIA. Technical Review of Documents NUREG/CR-1262, NUREG/CR-1376, NUREG/CR-1377, NUREG/CR-1397 & NUREG/CR-1608.

5 - STEVENS, C.A., FULLWOOD, R.A., BASIN, S.L. Science Applications, Inc.

FIN B-6694. SAI-262-81-PA. 82/02/28. Division of Risk Analysis.

123 p. Available at NRC. \$6,00. \$12176;217.

- 1. Nondocketed category
- 2. NRC Accession Number (year, month, day, and sequence number of item)
- NRC Report Number
- 4. Title and description of information contained in the document
- 5. Personal author(s). An asterisk in this position indicates that there is no personal author.
- 6. Corporate, agency or other nonindividual source.
- 7. Contract or financial (FIN) number (if any). If the document has a sceondary report number, it will appear following this entry.
- 8. Secondary report number assigned by originator.
- 9. Date of document described.
- NRC organizational recipient.
- 11. Pages in document.
- 12. All NUREG-series documents are available for purchase at NRC. Information on ordering documents is given below. All NUREG-series documents are also available at NTIS. Information on ordering from NTIS is also given below.
- 13. Price for which NRC sells the document.

- 14. The NRC 48X microfiche designation for this document. This five-digit portion of this entry is the number of the microfiche copy of this document that is available to NRC staff who have access to 48X microfiche files
- 15. This three-digit portion of this entry is the number of the frame on which this document starts.

The Nondocketed Items list is arranged sequentially by Accession Number within category. Indented items preceded by a dash are enclosures to unindented items.

NOTES:

1. The address for NRC is:

Director
Division of Technical Information and Document Control
U.S. Nuclear Regulatory Commission
Washington, D.C 20555

To place orders, send check or money order, payable to the Superintendent of Documents. GPO Deposit Account holders may charge their orders by calling (301) 492-9530.

2. The address for NTIS is:

National Technical Information Service Springfield, Virginia 22161

To place orders for or to obtain price information about NRC publications at NTIS, either write to NTIS or call the Sales Desk at (703) 557-4650. Specify the NRC report number and title when you place your order. Publications can be charged to American Express credit cards; supply the chargecard number when placing your order.

3. The address for the PDR is:

1717 H Street, N.W. Washington, D.C. 20555

To place orders, either write to the NRC PDR or call (202) 634-3274. When ordering documents listed in this publication, please identify the Document Accession Number for each citation.

Paper copy and microfiche of the documents listed in this title list may be purchased. Reproduction charges for duplication are as follows: (1) paper to paper is \$0.05 per page except for oversized documents and engineering drawings, which vary from \$0.50 to \$1.00 per square foot; (2) microform to paper is \$0.05 a page for pages on microfiche and is \$0.20 a square foot for a full-size print or \$0.25 for a reduced-size print (18" x 24") of a drawing on an aperture card; and (3) microform to microform is \$0.10 per microfiche and \$0.20 per aperture card. Orders completed for mailing or for a special delivery service will have an additional fee for the actual mailing, shipping, or delivery service rate. Unless a user requests special packing materials, there is no additional charge by the contractor for handling and wrapping materials.

Please acknowledge a willingness to assume charges for all orders but do not send payments. Orders will be processed and mailed with a bill from Literature Research Company. An account may be established with the Literature Research Company by calling (703)-941-8018.

ARRANGEMENT OF ITEMS BY DOCKET NUMBER

Docket	Name	Page	Docket Name		Page
Low Level Disposal Sites — Docket 27			40-8452	Bear Creek Uranium Co., Casper, WY	4
27-039	Sheffield, IL, U.S. Ecology, Inc.	1	40-8502	Wyoming Mineral Corp., Lakewood, CO	4
27-047	Barnwell, SC, Chem-Nuclear Systems, Inc.		40-8584	Minerals Exploration Co., Los Angeles, CA	5
27-048	Richland, WA, U.S. Ecology, Inc.		40-8585	Wyoming Mineral Corp., Lakewood, CO	5
Domestic Licen	sing of Source Material — Docket 40		40-8586	Kerr-McGee Nuclear Corp., Oklahoma City, OK	5
40-0086	W. R. Grace & Co., Pompton Plains, NJ	1	40-8610	Stepan Chemical Co., Maywood, NJ	5
40-0299	Union Carbide Corp., Grand Junction, CO	1	40-8631	Army, Dept. of, Rock Island, IL	5
40-0672	Nuclear Metals, Inc., Concord, MA	2	40-8663	Nuclear Dynamics, Inc., Phoenix, AZ	5
40-1162	Western Nuclear, Inc., Jeffrey City, WY	2	40-8674	Plateau Resources, Ltd., Grand Junction, CO	5
40-1341	Tennessee Vailey Authority, Chattanooga, TN	2	40-8681	Energy Fuels Nuclear, Inc., Denver, CO	5
40-2061	Kerr-McGee Chemical Corp.,		40-8684	Western Nuclear, Inc., Lakewood, CO	6
	Oklahoma City, OK	2	40-8697	Rocky Mountain Energy Co., Denver, CO	6
40-2259	Pathfinder Mines Corp., Riverton, WY	2	40-8698	Plateau Resources, Ltd., Grand Junction, CO	6
40-3392	Allied Chemical Corp., Morristown, NJ	3	40-8714	Cleveland-Cliffs Iron Co., Cleveland, OH	6
40-3453	Atlas Mineral, Inc., Denver, CO	3	40-8722	Brush Wellman, Inc., Cleveland, OH	6
40-4492	Federal-American Partners, Riverton, WY	3	40-8728	Teton Exploration Drilling Co., Inc.,	•
40-6264	Michigan Chemical Corp., St. Louis, MI	3		Casper, WY	7
40-6500	Energy, Dept. of, Canonsburg, PA	3	40-8745	Ogle Petroleum, Inc., Casper, WY	7
40-6622	Pathfinder Mines Corp., Shirley Basin, WY	3	40-8768	Kerr-McGee Nuclear Corp., Oklahoma City, OK	7
40-6940	Kawecki Berylco Industries, Inc., Boyertown, PA	3	40-8783	Uranerz USA, Inc., Casper, WY	7
40-7580	Fansteel, Inc., North Chicago, IL	3	40-8786	Uranium Resources, Inc., Richardson, TX	7
40-7869	Plateau Resources, Ltd., Grand Junction, CO	3	40-8794	MolyCorp., Inc., Los Angeles, CA	7
40-8027	Kerr-McGee Nuclear Corp., Oklahoma City, OK	3	Domestic Licer Docket 50	nsing of Production and Utilization Facilities —	
40-8035	Cotter Corp., Roswell, NM	4	50-2	Univ. of Michigan Research Reactor	7
40-8064	Exxon Minerals Co. USA, Houston, TX	4	50-2	Indian Point Station, Unit 1	7
40-8084	Rio Algom Corp., Moab, UT	4		Pennsylvania State Univ. Research Reactor	8
40-8348	Minerals Exploration Co., Los Angeles, CA	4	50-5 50-6	•	8
40-8380	Rocky Mountain Energy Co., Broomfield, CO	4	50-6 50-8	Battelle Memorial Institute Research Reactor North Carolina State Univ. Research Reactor	8

Docket	Name	Page	Docket	Name	Page
50-10	Dresden Nuclear Power Station, Unit 1	8	50-186	Univ of Missouri Research Reactor	22
50-14	Battelle Memorial Institute Critical Facility	9	50-188	Kansas State Univ. Research Reactor	22
50-16	Enrico Fermi Atomic Power Plant, Unit 1	9	50-192	Univ. of Texas Research Reactor	22
50-20	Massachusetts Institute of Technology Research Reactor	9	50-193	Rhode Island & Providence Plantations AEC	22
50-27	Washington State Univ. Research Reactor	9	50-199	Manhattan College Research Reactor	22
50-27	Yankee-Rowe Nuclear Power Station	9	50-201	West Valley Reprocessing Plant	22
50-54	Union Carbide Research Reactor	11	50-206	San Onofre Nuclear Station, Unit 1	23
50-57	State Univ. of New York Research Reactor	11	50-208	Columbia Univ. Research Reactor	25
50-62	Univ of Virginia Research Reactor	11	50-213	Haddam Neck Plant	26
50-02	General Electric Test Reactor	12	50-219	Oyster Creek Nuclear Power Plant	28
50-72	Univ. of Utah Research Reactor	12	50-220	Nine Mile Point Nuclear Station, Unit 1	30
50-72	Catholic Univ. of America Research Reactor	12	50-223	Univ. of Lowell Research Reactor	32
50-89	General Atomic Co.	12	50-224	Univ. of California Research Reactor	32
50-97	Cornell Univ. Zero Power Reactor	12	50-225	RPI Critical Experiment	32
50-111	North Carolina State Univ. Research Reactor	13	50-237	Dresden Nuclear Power Station, Unit 2	32
50-112	Univ. of Oklahoma Research Reactor	13	50-243	Oregon State Univ. Research Reactor	35
50-116	Iowa State Univ. Research Reactor	13	50-244	Robert Emmet Ginna Nuclear Plant, Unit 1	35
50-128	Texas A&M Univ. Research Reactor	13	50-245	Millstone Nuclear Power Station, Unit 1	38
50-131	Omaha Veterans Administration Hospital		50-247	Indian Point Station, Unit 2	40
	Research Reactor	14	50-249	Dresden Nuclear Power Station, Unit 3	44
50-133	Humboldt Bay Power Plant, Unit 3	14	50-250	Turkey Point Plant, Unit 3	46
50-134	Worcester Polytechnic Institute Research Reactor	14	50-251	Turkey Point Plant, Unit 4	48
50-141	Stanford Univ. Research Reactor	14	50-254	Quad-Cities Station, Unit 1	50
50-142	UCLA Training Reactor	14	50-255	Palisades Nuclear Plant	52
50-146	Saxton Nuclear Experimental Facility	16	50-259	Browns Ferry Nuclear Power Station, Unit 1	54
50-148	Univ. of Kansas Research Reactor	16	50-260	Browns Ferry Nuclear Power Station, Unit 2	57
50-151	Univ. of Illinois Research Reactor	16	50-261	H. B. Robinson Plant, Unit 2	61
50-155	Big Rock Point Nuclear Plant	16	50-263	Monticello Nuclear Generating Plant	63
50-156	Univ. of Wisconsin Research Reactor	20	50-265	Quad-Cities Station, Unit 2	64
50-157	Cornell Univ. Research Reactor	21	50-266	Point Beach Nuclear Plant, Unit 1	66
50-163	General Atomic Co.	21	50-267	Fort St. Vrain Nuclear Generating Station	68
50-166	Univ. of Maryland Research Reactor	21	50-269	Oconee Nuclear Station, Unit 1	71
50-170	National Naval Medical Center	21	50-270	Oconee Nuclear Station, Unit 2	72
50-182	Purdue Univ. Research Reactor	22	50-271	Vermont Yankee Nuclear Power Station	74
50-184	National Bureau of Standards Reactor	22	50-272	Salem Nuclear Generating Station, Unit 1	77

Docket	Name	Page	Docket	Name	Page
50-274	U S. Geological Survey Research Reactor	79	50-326	Univ. of California at Irvine Research Reactor	169
50-275	Diablo Canyon Nuclear Power Plant, Unit 1	80	50-327	Sequoyah Nuclear Plant, Unit 1	169
50-277	Peach Bottom Atomic Power Station, Unit 2	85	50-328	Sequoyah Nuclear Plant, Unit 2	171
50-278	Peach Bottom Atomic Power Station, Unit 3	88	50-329	Midland Plant, Unit 1	173
50-280	Surry Power Station, Unit 1	91	50-330	Midland Plant, Unit 2	177
50-281	Surry Power Station, Unit 2	92	50-331	Duane Arnold Energy Center	182
50-282	Prairie Island Nuclear Station, Unit 1	94	50-333	James A. Fitzpatrick Nuclear Power Plant	183
50-285	Fort Calhoun Station, Unit 1	96	50-334	Beaver Valley Power Station, Unit 1	185
50-286	Indian Point Station, Unit 3	98	50-335	St. Lucie Plant, Unit 1	188
50-287	Oconee Nuclear Station, Unit 3	102	50-336	Millstone Nuclear Power Station, Unit 2	190
50-289	Three Mile Island Nuclear Station, Unit 1	104	50-338	North Anna Power Station, Unit 1	193
50-293	Pilgrim Nuclear Power Station, Unit 1	109	50-339	North Anna Power Station, Unit 2	195
50-294	Michigan State Univ. Research Reactor	112	50-341	Enrico Fermi Atomic Power Plant, Unit 2	197
50-295	Zion Nuclear Power Station, Unit 1	112	50-344	Trojan Nuclear Plant	199
50-296	Browns Ferry Nuclear Power Station, Unit 3	113	50-346	Davis-Besse Nuclear Power Station, Unit 1	202
50-298	Cooper Nuclear Station	116	50-348	Joseph M. Farley Nuclear Plant, Unit 1	205
50-301	Point Beach Nuclear Plant, Unit 2	118	50-352	Limerick Generating Station, Unit 1	208
50-302	Crystal River Nuclear Plant, Unit 3	120	50-353	Limerick Generating Station, Unit 2	212
50-304	Zion Nuclear Power Station, Unit 2	122	50-354	Hope Creek Nuclear Station, Unit 1	217
50-305	Kewaunee Nuclear Power Plant	124	50-355	Hope Creek Nuclear Station, Unit 2	218
50-306	Prairie Island Nuclear Station, Unit 2	125	50-356	Univ. of Illinois LOPRA Research Reactor	218
50-309	Maine Yankee Atomic Power Plant	127	50-358	William H. Zimmer Nuclear Station, Unit 1	218
50-311	Salem Nuclear Generating Station, Unit 2	130	50-361	San Onofre Nuclear Station, Unit 2	222
50-312	Rancho Seco Nuclear Generating Station	132	50-362	San Onofre Nuclear Station, Unit 3	227
50-313	Arkansas Nuclear One, Unit 1	135	50-364	Joseph M. Farley Nuclear Plant, Unit 2	230
50-315	Donald C. Cook Nuclear Power Plant, Unit 1	138	50-366	Edwin I. Hatch Nuclear Plant, Unit 2	232
50-316	Donald C. Cook Nuclear Power Plant, Unit 2	140	50-367	Bailly Generating Station	236
50-317	Calvert Cliffs Nuclear Power Plant, Unit 1	142	50-368	Arkansas Nuclear One, Unit 2	236
50-318	Calvert Cliffs Nuclear Power Plant, Unit 2	145	50-369	William B. McGuire Nuclear Station, Unit 1	239
50-320	Three Mile Island Nuclear Station, Unit 2	147	50-370	William B. McGuire Nuclear Station, Unit 2	241
50-321	Edwin I. Hatch Nuclear Plant, Unit 1	150	50-373	LaSalle County Station, Unit 1	244
50-322	Shoreham Nuclear Power Station	153	50-374	LaSalle County Station, Unit 2	247
50-323	Diablo Canyon Nuclear Power Plant, Unit 2	160	50-382	Waterford Generating Station, Unit 3	250
50-324	Brunswick Steam Electric Plant, Unit 2	162	50-387	Susquehanna Steam Electric Station, Unit 1	252
50-325	Brunswick Steam Electric Plant, Unit 1	165	50-388	Susquehanna Steam Electric Station, Unit 2	256

Docket	Name	Page	Docket	Name	Page
50-389	St. Lucie Plant, Unit 2	257	STN-50-457	Braidwood Station, Unit 2	338
50-390	Watts Bar Nuclear Plant, Unit 1	261	50-458	River Bend Station, Unit 1	340
50-391	Watts Bar Nuclear Plant, Unit 2	265	50-459	River Bend Station, Unit 2	342
50-394	California State Polytech College Research Reactor	269	50-460	WPPSS Nuclear Project, Unit 1	343
50-395	Virgil C. Summer Nuclear Station, Unit 1	269	50-461	Clinton Power Station, Unit 1	345
50-396	Univ. of Virginia Cavalier Reactor	209	50-462	Clinton Power Station, Unit 2	346
50-397	WPPSS Nuclear Project, Unit 2	271	STN-50-470	CESSAR System 80	346
50-400	Shearon Harris Nuclear Power Plant, Unit 1	273	STN-50-482	Wolf Creek Generating Station	346
50-401	Shearon Harris Nuclear Power Plant, Unit 2	278	STN-50-483	Callaway Plant, Unit 1	349
50-404	North Anna Power Station, Unit 3	281	50-496	Montague Nuclear Power Station, Unit 1	351
50-407	Univ. of Utah Research Reactor	281	50-497	Montague Nuclear Power Station, Unit 2	352
50-409	La Crosse Boiling Water Reactor	281	STN-50-498	South Texas Project, Unit 1	352
50-410	Nine Mile Point Nuclear Station, Unit 2	284	STN-50-499	South Texas Project, Unit 2	354
50-412	Beaver Valley Power Station, Unit 2	286	STN-50-508	WPPSS Nuclear Project, Unit 3	356
50-413	Catawba Nuclear Station, Unit 1	287	STN-50-509	WPPSS Nuclear Project, Unit 5	357
50-414	Catawba Nuclear Station, Unit 2	290	50-513	WPPSS Nuclear Project, Unit 4	357
50-416	Grand Gulf Nuclear Station, Unit 1	293	50-514	Pebble Springs Nuclear Plant, Unit 1	357
50-417	Grand Gulf Nuclear Station, Unit 2	297	50-515	Pebble Springs Nuclear Plant, Unit 2	358
50-423	Millstone Nuclear Power Station, Unit 3	299	STN-50-517	Jamesport Nuclear Station, Unit 2	358
50-424	Alvin W. Vogtle Nuclear Plant, Unit 1	300	STN-50-518	Hartsville Nuclear Plant, Unit 1	358
50-425	Aivin W. Vogtle Nuclear Plant, Unit 2	302	STN-50-519	Hartsville Nuclear Plant, Unit 2	358
50-438	Bellefonte Nuclear Plant, Unit 1	303	STN-50-520	Hartsville Nuclear Plant, Unit 3	358
50-439	Bellefonte Nuclear Plant, Unit 2	306	STN-50-521	Hartsville Nuclear Plant, Unit 4	359
50-440	Perry Nuclear Power Plant, Unit 1	309	50-522	Skagit Nuclear Power Project, Unit 1	359
50-441	Perry Nuclear Power Plant, Unit 2	312	50-523	Skagit Nuclear Power Project, Unit 2	359
50-443	Seabrook Nuclear Station, Unit 1	315	STN-50-528	Palo Verde Nuclear Station, Unit 1	360
50-444	Seabrook Nuclear Station, Unit 2	318	STN-50-529	Palo Verde Nuclear Station, Unit 2	363
50-445	Comanche Peak Steam Electric Station,	2.0	STN-50-530	Palo Verde Nuclear Station, Unit 3	366
	Unit 1	321	50-537	Clinch River Breeder Reactor	369
50-446	Comanche Peak Steam Electric Station, Unit 2	325	STN-50-546	Marble Hill Nuclear Station, Unit 1	370
STN-50-447	GESSAR-238	328	STN-50-547	Marble Hill Nuclear Station, Unit 2	372
STN-50-454	Byron Station, Unit 1	329	STN-50-553	Phipps Bend Nuclear Station, Unit 1	373
STN-50-455	Byron Station, Unit 2	333	STN-50-554	Phipps Bend Nuclear Station, Unit 2	373
STN-50-456	Braidwood Station, Unit 1	337	STN-50-556	Black Fox Station, Unit 1	373
		55,	STN-50-557	Black Fox Station, Unit 2	374

:ket	Name	Page	Docket	Name	Page
nestic Licensing of Special Nuclear Material - Docket 70			70-2548	Dover General Hospital, Dover, NJ	379
70-0008	Battelle Memorial Institute, Columbus, OH	374	70-2669	Robert Packer Hospital, Sayre, PA	379
70-0025	Rockwell International Corp., Canoga Park, CA	375		Cincinnati Gas & Electric Co., Cincinnati, OH	379
70-0084	Iowa State Univ., Ames, IA	375	70-2850	Weber State College, Ogden, UT	380
70-0115	Washington, Univ. of, Seattle, WA	375	70-2892	Auxilio Muto Hospital, Hato Rey, PR	380
70-0121	Interior, Dept of, Denver, CO	375	70-2910	Tennessee Valley Authority, Chattanooga, TN	380
70-0124	Teledyne Isotopes, Inc., Westwood, NJ	375	70-2926	Detroit Edison Co., Detroit, MI	380
70-0134	Wisconsin, Univ. of, Madison, WI	375	70-2929	Army, Dept. of, Ft. McClellan, AL	380
70-0135	Babcock & Wilcox Co., Apollo, PA	375	70-2945	Union Electric Co., St. Louis, MO	380
70-0143	Nuclear Fuel Services, Inc., Erwin, TN	375	70-2947	Illinois Power & Light Co., Decatur, IL	380
70-0258	Illinois, Univ. of, Urbana, IL	376	70-2950	Washington Public Power Supply System, Richland, WA	380
70-0267	New York, State Univ. of, Buffalo, NY	376	70-2953	Connecticut, Univ. of, Storrs, CT	380
70-0364	Babcock & Wilcox Co., Apollo, PA	376	70-2968	Cleveland Electric Illuminating Co.	2.2.1
70-0371	UNC Naval Products, Inc., Uncasville, CT	376		Cleveland, OH	380
70-0498	Eastern Michigan Univ., Ypsilanti, MI	376	70-2982	Rochester, Univ of, Rochester, NY	380
70-0687	Union Carbide Corp., Tuxedo, NY	376	70-2984	Arizona Public Service Co., Phoenix, AZ	380
70-0698	Westinghouse Electric Corp., Pittsburgh, PA	377	70-2985	Duke Power Co., Charlotte, NC	381
70-0734	GA Technologies, Inc., San Diego, CA	377	Packaging of R	tadioactive Material for Transport and Transpor	tation
10-0754	General Electric Co., Pleasanton, CA	377			71
'0-0820	United Nuclear Corp., Wood River Junction, RI	377	71-0002	ATCOR Engineered Systems, Inc.	381
'0-0824	Babcock & Wilcox Co., Lynchburg, VA	377	71-0086	Alpha-Omega Services, Inc.	381
'0-1113	General Electric Co., Wilmington, NC	377	71-0210	Gulf Nuclear, Inc.	381
0-1143	Westinghouse Electric Corp., Pittsburgh, PA	378	71-0250	Transnuclear, Inc.	381
0-1151	Westinghouse Electric Corp., Pittsburgh, PA	378	71-0302	Associated Piping & Engineering Corp.	381
0-1201	Babcock & Wilcox Co., Lynchburg, VA	378	71-0367	Navy, Dept. of	381
0-1207	Navy, Dept. of, Silver Spring, MD	378	71-0498	Gearhart-Owen Industries	381
0-1224	Teleflex, Inc., North Wales, PA	378	71-4909	Model: GE 21PF-1, General Electric Co.	381
0-1257	Exxon Nuclear Co., Inc., Richland, WA	379	71-4960	Model: LLD-1, Energy, Dept. of	381
0-1308	General Electric Co., San Jose, CA	379	71-5026	Model: CNS 14-190, Chem-Nuclear Systems, Inc.	381
0-1402	Abington Memorial Hospital, Abington, PA	379	71-5097	Model: 44, Energy, Dept. of	382
3-1549	Nuclear Fuel Services, Inc., Erwin, TN	379	71-5170	Model: Steel Ingot Skid & Box 37,	202
0-1739	Tri-State Motor Transit Co., Joplin, MO	379	<u>.</u>	Energy, Dept. of	382
3-1764	Nuclear Fuel Services, Inc., Erwin, TN	379	71-5364	Model: NPI-67-0442, Neutron Products, Inc.	382
)-2375	Pacific Gas & Electric Co., San Francisco, CA	379	71-5450	Model: RCC, -1, -2, -3, -4, Westinghouse Electric Corp.	382

Docket	Name	Page	Docket	Name	Page
71-5467	Model. Mark VR, VE & Mark 15,	382	71-6550	Model 6-GS-1, Energy, Dept. of	384
	Energy, Dept. of	362	71-6553	Model PADUCAH Tiger, Energy, Dept. of	384
71-5469	Model. HNPF Spent Fuel Shipping Cask, Energy, Dept. of	382	71-6574	Model: HN-200, Hittman Nuclear & Development Corp.	384
71-5507	Model: HFIR Spent Fuel Element Shipping Cask, Energy, Dept. of	382	71-6601	Model: CNS 8-120, Chem-Nuclear Systems, Inc.	384
71-5552	Model: Gas Cylinder Fire Impact Shield, Energy, Dept. of	382	71-6613	Model: 702, Technical Operations, Inc.	384
71-5595	Model: L&M ORNL Uranium Shielded Cask,	250	71-6639	Model: MH-1A, Energy, Dept. of	384
	Energy, Dept. of	382	71-6679	Model. 6679, U.S. Ecology	384
71-5597	Model: Tungsten Shielded Cask, Energy, Dept. of	382	71-6698	Model: NFS-4, Nuclear Fuel Services, Inc.	384
71-5607	Model: T-2, Energy, Dept. of	382	71-6717	Model: 6717-B, Gamma Industries	384
71-5608	Model: BR 63-0101, Energy, Dept. of	382	71-9006	Model: 500-SU, Automation Industries, Inc	385
71-5641	Model: UNC-2500, United Nuclear Corp.	382	71-9010	Model: NLI-1/2, NL Industries, Inc.	385
71-5645	Model: AL-L 8, Energy, Dept. of	382	71-9015	Model: TN-8, -8L, No Users	385
71-5753	Model: ORNL Loop Transport Cask,	202	71-9016	Model: TN-9, No Users	385
71 5702	Energy, Dept. of	382	71-9017	Model: SNAP-23A 1000, Navy, Dept. of	385
71-5795	Model: None, Energy, Dept. of	383	71-9029	Model: 676 & 676B, Technical	
71-5796	Model: 181375, 181361, Advanced Medical Systems, Inc.	383		Operations, Inc.	385
71-5828	Model: TREAT, Energy, Dept. of	383	71-9032	Model: 650, Technical Operations, Inc.	385
71-5885	Model: AL-L 11, Energy, Dept. of	383	71-9033	Model: 660 & 660E, Technical Operations, Inc.	385
71-5907	Model: ORNL in Pile Capsule, Energy, Dept. of	383	71-9035	Model: 680 & 680E, Technical Operations, Inc.	385
71-5957	Model: BMI-1, Battelle Columbus Laboratory	383	71-9039	Model: 715, Technical Operations, Inc.	385
71-5971	Model: GE-200, General Electric Co.	383	71-9056	Model: SPEC 2-T, Source Production & Equipment Co.	385
71-6003	Model: M-130, Energy, Dept. of	383	71-9070	Model: N-55, Energy, Dept. of	386
71-6088	Model: D-38, Oak Ridge National Lab	383			360
71-6104	Model: ANL-390-SPM, Energy, Dept. of	383	71-9080	Model: 9080, Hittman Nuclear & Development Corp.	386
71-6115	Model: R1010-0032, Energy, Dept. of	383	71-9086	Model: HN-100, Series 1, Hittman Nuclear &	386
71-6142	Model: Bettis Waste, Energy, Dept. of	383	71 0000	Development Corp.	200
71-6244	Model: 6244, Chem-Nuclear Systems, Inc.	383	71-9089	Model: HN-100S, Hittman Nuclear & Development Corp.	386
71-6272	Model: 6272, U.S. Ecology	383	71-9096	Model: CNS 21-300, Chem-Nuclear Systems, Inc.	386
71-6345	Model: ANL-402-SPM & 403-SPM, E.I. du Pont de Nemours	383	71-9100	Model: KKP-20-4950, Kerr-McGee Nuclear	386
71-6346	Model: FSV-1, General Atomic Co.	384	61 D100	Corp.	500
71-6357	Model: NNFD-10, Babcock & Wilcox Co.	384	71-9108	Model: CNS 6-75, Chem-Nuclear Systems, Inc.	386
71-6400	Model: 6400, Westinghouse Electric Corp.	384	71-9110	Model: MX-IC-100, Magnaflux Corp.	386-
71-6421	Model: CBE-14, Energy, Dept. of	384	71-9111	Model: CNS 6-80-2, Chem-Nuclear Systems, Inc.	386

]	Docket	Name	Page	Docket	Name	Page
	71-9132	Model T-3, Energy, Dept. of	387	71-9165	Model. 855, Technical Operations, Inc.	387
	71-9133	Model. C-10, Gamma Industries	387	71-9174	Model: F-147, Atomic Energy of Canada, Ltd.	388
	71-9134	Model: ETR, Exxon Nuclear Idaho Co	387	71-9176	Model NUPAC 14/210L & 14/210H,	500
	71-9135	Model: Century S & SA, Cen. Univ. S & SA, Gamma Industries	387	71-9170	Nuclear Packaging, Inc	388
	71-9141	Model: 900, Technical Operations, Inc	387	71-9178	Model NUPAC 7/100, Nuclear Packaging, Inc	388
	71-9142	Model: MRC-20WC, Monsanto Research		71-9179	Model: NUPAC 6/100L & 6/100 H, Nuclear	
	71-7142	Corp.	387	,,,,,,	Packaging, Inc.	388
	71-9143	Model: 920, Technical Operations, Inc.	387	71-9182	Model: Husman Irraditor, Agriculture, Dept. of	388
	71-9147	Model: 850, Technical Operations, Inc.	387	71 0500	•	-
	71-9151	Model: HN-100, Series 3, Hıttman Nuclear &		71-9508	Model: DOT Spec 6M, Energy, Dept. of	388
		Development Corp.	387	71-9510	Model: GPHS, Energy, Dept. of	388
	71-9152	Model: CNS 1-13CII, Chem-Nuclear Systems, Inc.	387	71-9851	Model: Lithium Hydroxide Fire/Impact Shield, Energy, Dept. of	388
	71-9156	Model: IR-50, Industrial Nuclear Co.	387	71-9852	Model: DT-14, Energy, Dept. of	388
	71-9157	Model: IR-100, Industrial Nuclear Co.	387			
	71-9159	Model: NUPAC Series A, Nuclear Packing,		Licensing of L	ndependent Spent Fuel Storage — Docket 72	
	,1 ,103	Inc.	387	72-0001	Morris Operations, General Electric Co.	388
	71-9163	Model: GNG-20, Gulf Nuclear, Inc.	387			

ALPHABETIC ARRANGEMENT OF DOCKET ITEMS BY FACILITY NAME

Name	Docket	Page	Name	Docket	Page
Barnwell, SC, Chem-Nuclear Systems, Inc.	27-047	1	Pathfinder Mines Corp., Shirley Basin, WY	40-6622	3
Richland, WA, US Ecology, Inc.	27-048	1	Plateau Resources, Ltd., Grand Junction, CO	40-7869	3
Sheffield, Il, U.S. Ecology, Inc.	27-039	l	Plateau Resources, Ltd., Grand Junction, CO	40-8674	5
Domestic Licensing of Source Material — Docket 4	Λ		Plateau Resources, Ltd., Grand Junction, CQ	40-8698	6
	40-3392	3	Rio Algom Corp., Moab, UT	40-8084	4
Allied Chemical Corp., Morristown, NJ		5	Rocky Mountain Energy Co., Broomfield, CO	40-8380	4
Army, Dept. of, Rock Island, IL	40-8631		Rocky Mountain Energy Co., Denver, CO	40-8697	6
Atlas Mineral, Inc., Denver, CO	40-3453	3	Stepan Chemical Co., Maywood, NJ	40-8610	5
Bear Creek Uranium Co., Casper, WY	40-8452	4	Tennessee Valley Authority, Chattanooga, TN	40-1341	2
Brush Wellman, Inc., Cleveland, OH	40-8722	6	Teton Exploration Drilling Co., Inc., Casper, WY	40-8728	7
Cleveland-Cliffs Iron Co, Cleveland, OH	40-8714	6	Union Carbide Corp., Grand Junction, CO	40-0299	1
Cotter Corp., Roswell, NM	40-8035	4	Uranerz USA, Inc., Casper, WY	40-8783	7
Energy Fuels Nuclear, Inc., Denver, CO	40-8681	5	Uranium Resources, Inc., Richardson, TX	40-8786	7
Energy, Dept. of, Canonsburg, PA	40-6500	3	W. R. Grace & Co., Pompton Plains, NJ	40-0086	1
Exxon Minerals Co. USA, Houston, TX	40-8064	4	Western Nuclear, Inc., Jeffrey City, WY	40-1162	2
Fansteel, Inc., North Chicago, IL	40-7580	3	Western Nuclear, Inc., Lakewood, CO	40-8684	6
Federal-American Partners, Riverton, WY	40-4492	3		40-8502	4
Kawecki Berylco Industries, Inc., Boyertown, PA	40-6940	3	Wyoming Mineral Corp., Lakewood, CO		
Kerr-McGee Chemical Corp., Oklahoma City, OK	40-2061	2	Wyoming Mineral Corp., Lakewood, CO	40-8585	5
Kerr-McGee Nuclear Corp., Oklahoma City, OK	40-8027	3	Domestic Licensing of Production and Utilization I	Facilities —	
Kerr-McGee Nuclear Corp., Okiahoma City, OK	40-8586	5	Docket 50	50.404	200
Kerr-McGee Nuclear Corp., Oklahoma City, OK	40-8768	7	Alvin W. Vogtle Nuclear Plant, Unit 1	50-424	300
Michigan Chemical Corp., St. Louis, MI	40-6264	3	Alvin W. Vogtle Nuclear Plant, Unit 2	50-425	302
Minerals Exploration Co., Los Angeles, CA	40-8348	4	Arkansas Nuclear One, Unit 1	50-313	135
Minerals Exploration Co., Los Angeles, CA	40-8584	5	Arkansas Nuclear One, Unit 2	50-368	236
MolyCorp., Inc., Los Angeles, CA	40-8794	7	Bailly Generating Station	50-367	236
Nuclear Dynamics, Inc., Phoenix, AZ	40-8663	5	Battelle Memorial Institute Critical Facility	50-14	9
•			Battelle Memorial Institute Research Reactor	50-6	8
Nuclear Metals, Inc., Concord, MA	40-0672	2	Beaver Valley Power Station, Unit 1	50-334	185
Ogle Petroleum, Inc., Casper, WY	40-8745	7	Beaver Valley Power Station, Unit 2	50-412	286
Pathfinder Mines Corp., Riverton, WY	40-2259	2	Bellefonte Nuclear Plant, Unit 1	50-438	303

Name	Docket	Page	Name	Docket	Page
Bellefonte Nuclear Plant, Unit 2	50-439	306	Donald C. Cook Nuclear Power Plant, Unit 2	50-316	140
Big Rock Point Nuclear Plant	50-155	16	Dresden Nuclear Power Station, Unit 1	50-10	8
Black Fox Station, Unit 1	STN-50-556	373	Dresden Nuclear Power Station, Unit 2	50-237	32
Black Fox Station, Unit 2	STN-50-557	374	Dresden Nuclear Power Station, Unit 3	50-249	44
Braidwood Station, Unit I	STN-50-456	337	Duane Arnold Energy Center	50-331	182
Braidwood Station, Unit 2	STN-50-457	338	Edwin I. Hatch Nuclear Plant, Unit 1	50-321	150
Browns Ferry Nuclear Power Station, Unit 1	50-259	54	Edwin I. Hatch Nuclear Plant, Unit 2	50-366	232
Browns Ferry Nuclear Power Station, Unit 2	50-260	57	Enrico Fermi Atomic Power Plant, Unit 1	50-16	9
Browns Ferry Nuclear Power Station, Unit 3	50-296	113	Enrico Fermi Atomic Power Plant, Unit 2	50-341	197
Brunswick Steam Electric Plant, Unit 1	50-325	165	Fort Calhoun Station, Unit 1	50-285	96
Brunswick Steam Electric Plant, Unit 2	50-324	162	Fort St. Vrain Nuclear Generating Station	50-267	68
Byron Station, Unit 1	STN-50-454	329	General Atomic Co.	50-163	21
Byron Station, Unit 2	STN-50-455	333	General Atomic Co.	50-89	12
California State Polytechnic College Research Reactor	50-394	269	General Electric Test Reactor	50-70	12
Callaway Plant, Unit 1	STN-50-483	349	GESSAR-238	STN-50-447	328
Calvert Cliffs Nuclear Power Plant, Unit 1	50-317	142	Grand Gulf Nuclear Station, Unit 1	50-416	293
Calvert Cliffs Nuclear Power Plant, Unit 2	50-318	145	Grand Gulf Nuclear Station, Unit 2	50-417	297
Catawba Nuclear Station, Unit 1	50-413	287	H. B. Robinson Plant, Unit 2	50-261	61
Catawba Nuclear Station, Unit 2	50-414	290	Haddam Neck Plant	50-213	26
Catholic Univ of America Research Reactor	50-77	12	Hartsville Nuclear Plant, Unit 1	STN-50-518	358
CESSAR System 80	STN-50-470	346	Hartsville Nuclear Plant, Unit 2	STN-50-519	358
Clinch River Breeder Reactor	50-537	369	Hartsville Nuclear Plant, Unit 3	STN-50-520	358
Clinton Power Station, Unit 1	50-461	345	Hartsville Nuclear Plant, Unit 4	STN-50-521	359
Clinton Power Station, Unit 2	50-462	346	Hope Creek Nuclear Station, Unit 1	50-354	217
Columbia Univ Research Reactor	50-208	25	Hope Creek Nuclear Station, Unit 2	50-355	218
Comanche Peak Steam Electric Station, Unit 1	50-445	321	Humboldt Bay Power Plant, Unit 3	50-133	14
Comanche Peak Steam Electric Station, Unit 2	50-446	325	Indian Point Station, Unit 1	50-3	7
Cooper Nuclear Station	50-298	116	Indian Point Station, Unit 2	50-247	40
Cornell Univ. Research Reactor	50-157	21	Indian Point Station, Unit 3	50-286	98
Cornell Univ. Zero Power Reactor	50-97	12	Iowa State Univ. Research Reactor	50-116	13
Crystal River Nuclear Plant, Unit 3	50-302	120	James A. Fitzpatrick Nuclear Power Plant	50-333	183
Davis-Besse Nuclear Power Station, Unit 1	50-346	202	Jamesport Nuclear Station, Unit 2	STN-50-517	358
Diablo Canyon Nuclear Power Plant, Unit 1	50-275	80	Joseph M. Farley Nuclear Plant, Unit 1	50-348	205
Diablo Canyon Nuclear Power Plant, Unit 2	50-323	160	Joseph M. Farley Nuclear Plant, Unit 2	50-364	230
Donald C. Cook Nuclear Power Plant, Unit 1	50-315	138	Kansas State Univ. Research Reactor	50-188	22

Name	Docket	Page	Name	Docket	Page
Kewaunee Nuclear Power Plant	50-305	124	Oyster Creek Nuclear Power Plant	50-219	28
La Crosse Boiling Water Reactor	50-409	281	Palisades Nuclear Plant	50-255	52
LaSalle County Station, Unit 1	50-373	244	Palo Verde Nuclear Station, Unit 1	STN-50-528	360
LaSalle County Station, Unst 2	50-374	247	Palo Verde Nuclear Station, Unit 2	STN-50-529	361
Limerick Generating Station, Unit !	50-352	208	Palo Verde Nuclear Station, Unit 3	STN-50-530	366
Limerick Generating Station, Unit 2	50-353	212	Peach Bottom Atomic Power Station, Unit 2	50-277	85
Maine Yankee Atomic Power Plant	50-309	127	Peach Bottom Atomic Power Station, Unit 3	50-278	88
Manhattan College Research Reactor	50-199	22	Pebble Springs Nuclear Plant, Unit 1	50-514	357
Marble Hill Nuclear Station, Unit 1	STN-50-546	370	Pebble Springs Nuclear Plant, Unit 2	50-515	358
Marble Hill Nuclear Station, Unit 2	STN-50-547	372	Pennsylvania State Univ. Research Reactor	50-5	8
Massachusetts Institute of Technology Res. Reactor	50-20	9	Perry Nuclear Power Plant, Unit 1	50-440	309
Michigan State Univ. Research Reactor	50-294	112	Perry Nuclear Power Plant, Unit 2	50-441	312
Midland Plant, Unit 1	50-329	173	Phipps Bend Nuclear Station, Unit 1	STN-50-553	373
Midland Plant, Unit 2	50-330	177	Phipps Bend Nuclear Station, Unit 2	STN-50-554	373
Millstone Nuclear Power Station, Unit 1	50-245	38	Pilgrim Nuclear Power Station, Unit 1	50-293	109
Millstone Nuclear Power Station, Unit 2	50-336	190	Point Beach Nuclear Plant, Unit 1	50-266	66
Millstone Nucler Power Station, Unit 3	50-423	299	Point Beach Nuclear Plant, Unit 2	50-3 01	118
Montague Nuclear Power Station, Unit 1	50-496	351	Prairie Island Nuclear Station, Unit 1	50-282	94
Montague Nuclear Power Station, Unit 2	50-497	352	Prairie Island Nuclear Station, Unit 2	50-306	125
Monticello Nuclear Generating Plant	50-263	63	Purdue Univ. Research Reactor	50-182	22
National Bureau of Standards Reactor	50-184	22	Quad-Cities Station, Unit 1	50-254	50
National Naval Medical Center	50-170	21	Quad-Cities Station, Unit 2	50-265	64
Nine Mile Point Nuclear Station, Unit 1	50-220	30	Rancho Seco Nuclear Generating Station	50-312	132
Nine Mile Point Nuclear Station, Unit 2	50-410	284	Rhode Island & Providence Plantations AEC	50-193	22
North Anna Power Station, Unit 1	50-338	193	River Bend Station, Unit 1	50-458	340
North Anna Power Station, Unit 2	50-339	195	River Bend Station, Unit 2	50-459	342
North Anna Power Station, Unit 3	50-404	281	Robert Emmet Ginna Nuclear Plant, Unit 1	50-244	35
North Carolina State Univ. Research Reactor	50-8	8	RPI Critical Experiment	50-225	32
North Carolina State Univ. Research Reactor	50-111	13	Salem Nuclear Generating Station, Unit 1	50-272	77
Oconee Nuclear Station, Unit 1	50-269	71	Salem Nuclear Generating Station, Unit 2	50-311	130
Oconee Nuclear Station, Unit 2	50-270	72	San Onofre Nuclear Station, Unit 1	50-206	23
Oconee Nuclear Station, Unit 3	50-287	102	San Onofre Nuclear Station, Unit 2	50-361	222
Omaha Veterans Administration Hospital	20 40		San Onofre Nuclear Station, Unit 3	50-362	227
Research Reactor	50-131	14	Saxton Nuclear Experimental Facility	50-146	16
Oregon State Univ. Research Reactor	50-243	35	Seabrook Nuclear Station, Unit 1	50-443	315

Name	Docket	Page	Name	Docket	Page
Seabrook Nuclear Station, Unit 2	50-444	318	Univ of Missouri Research Reactor	50-186	22
Sequoyah Nuclear Plant, Unit 1	50-327	169	Univ of Oklahoma Research Reactor	50-112	13
Sequoyah Nuclear Plant, Unit 2	50-328	171	Umv. of Texas Research Reactor	50-192	22
Shearon Harris Nuclear Power Plant, Unit 1	50-400	273	Univ. of Utah Research Reactor	50-407	281
Shearon Harris Nuclear Power Plant, Unit 2	50-401	278	Univ. of Utah Research Ractor	50-72	12
Shoreham Nuclear Power Station	50-322	153	Univ of Virginia Cavalier Reactor	50-396	271
Skagit Nuclear Power Project, Unit 1	50-522	359	Univ of Virginia Research Reactor	50-62	11
Skagit Nuclear Power Project, Unit 2	50-523	359	Univ. of Wisconsin Research Reactor	50-156	20
South Texas Project, Unit 1	STN-50-498	352	Vermont Yankee Nuclear Power Station	50-271	74
South Texas Project, Unit 2	STN-50-499	354	Virgil C Summer Nuclear Station, Unit 1	50-395	269
St. Lucie Plant, Unit 1	50-335	188	Washington State Univ. Research Reactor	50-27	9
St. Lucie Plant, Unit 2	50-389	257	Waterford Generating Station, Unit 3	50-382	250
Stanford Univ. Research Reactor	50-141	14	Watts Bar Nuclear Plant, Unit 1	50-390	261
State Univ. of New York Research Reactor	50-57	11	Watts Bar Nuclear Plant, Unit 2	50-391	265
Surry Power Station, Unit 1	50-280	91	West Valley Reprocessing Plant	50-201	22
Surry Power Station, Unit 2	50-281	92	William B. McGuire Nuclear Station, Unit 1	50-369	239
Susquehanna Steam Electric Station, Unit 1	50-387	252	William B. McGuire Nuclear Station, Unit 2	50-370	241
Susquehanna Steam Electric Station, Unit 2	50-388	256	William H. Zimmer Nuclear Station, Unit 1	50-358	218
Texas A&M Univ. Research Reactor	50-128	13	Wolf Creek Generating Station	STN-50-482	346
Three Mile Island Nuclear Station, Unit 1	50-289	104	Worcester Polytechnic Institute	50 124	14
Three Mile Island Nuclear Station, Unit 2	50-320	147	Research Renctor	50-134	14
Trojan Nuclear Plant	50-344	199	WPPSS Nuclear Project, Unit 1	50-460	343
Turkey Point Plant, Unit 3	50-250	46	WPPSS Nuclear Project, Unit 2	50-397	271
Turkey Point Plant, Unit 4	50-251	48	WPPSS Nuclear Project, Unit 3	STN-50-508	356
U.S. Geological Survey Research Reactor	50-274	79	WPPSS Nuclear Project, Unit 4	50-513	357
UCLA Training Reactor	50-142	14	WPPSS Nuclear Project, Unit 5	STN-50-509	357
Union Carbide Research Reactor	50-54	11	Yankee-Rowe Nuclear Power Station	50-29	9
Univ. of California at Irvine Res. Reactor	50-326	169	Zion Nuclear Power Station, Unit 1	50-295	112
Univ. of California Research Reactor	50-224	32	Zion Nuclear Power Station, Unit 2	50-304	122
Univ. of Illinois LOPRA Research Reactor	50-356	218	Domestic Licensing of Special Nuclear Material	- Docket 70	
Univ. of Illinois Research Reactor	50-151	16	Abington Memorial Hospital, Abington, PA	70-1402	379
Univ. of Kansas Research Reactor	50-148	16	Arizona Public Service Co., Phoenix, AZ	70-2984	380
Univ. of Lowell Research Reactor	50-223	32	Army, Dept. of, Ft. McClellan, AL	70-2929	380
Univ. of Maryland Research Reactor	50-166	21	Auxilio Muto Hospital, Hato Rey, PR	70-2892	380
Univ. of Michigan Research Reactor	50-2	7	Babcock & Wilcox Co., Apollo, PA	70-0135	375

Name	Docket	Page	Name	Docket	Page
Babcock & Wilcox Co , Apollo, PA	70-0364	376	Union Electric Co., St. Louis, MO	70-2945	380
Babcock & Wilcox Co., Lynchburg, VA	70-1201	378	United Nuclear Corp , Wood River Junction, RI	70-0820	377
Babcock & Wilcox Co., Lynchburg, VA	70-0824	377	Washington Public Power Supply System, Richland, WA	70-2950	380
Battelle Memorial Institute, Columbus, OH	70-0008	374	•	70-0115	375
Cincinnati Gas & Electric Co., Cincinnati, OH	70-2838	379	Washington, Univ. of, Seattle, WA Weber State College, Ogden, UT	70-2850	380
Cleveland Electric Illuminating Co., Cleveland, OH	70-2968	380	Westinghouse Electric Corp , Pittsburgh, PA	70-0698	377
Connecticut, Univ. of, Storrs, CT	70-2953	380	Westinghouse Electric Corp., Pittsburgh, PA	70-1143	378
Detroit Edison Co., Detroit, MI	70-2926	380	Westinghouse Electric Corp., Pittsburgh, PA	70-1151	378
Dover General Hospital, Dover, NJ	70-2548	379	Wisconsin, Univ. of, Madison, WI	70-0134	375
Duke Power Co., Charlotte, NC	70-2985	381	Product of York and Manufal for Theorem and an	d Tunnanauta	tlan.
Eastern Michigan Univ., Ypsilanti, MI	70-0498	376	Packaging of Radioactive Material for Transport an of Radioactive Material Under Certain Conditions		
Exxon Nuclear Co., Inc., Richland, WA	70-1257	379	Alpha-Omega Services, Inc.	71-0086	381
GA Technologies, Inc., San Diego, CA	70-0734	377	Associated Piping & Engineering Corp.	71-0302	381
General Electric Co., Pleasanton, CA	70-0754	377	ATCOR Engineered Systems, Inc.	71-0002	381
General Electric Co., San Jose, CA	70-1308	379	Gearhart-Owen Industries	71-0498	381
General Electric Co., Wilmington, NC	70-1113	377	Gulf Nuclear, Inc.	71-0210	381
Illinois Power & Light Co., Decatur, IL	70-2947	380	Model, 181375, 181361, Advanced Medical	71-5796	383
Illinois, Univ. of, Urbana, IL	70-0258	376	Systems, Inc.	71-5097	382
Interior, Dept. of, Denver, CO	70-0121	375	Model: 44, Energy, Dept. of		
Iowa State Univ., Ames, IA	70-0084	375	Model: 500-SU, Automation Industries, Inc.	71-9006	385
Navy, Dept. of, Silver Spring, MD	70-12 07	378	Model: 6-GS-1, Energy, Dept. of	71-6550	384
New York, State Univ. of, Buffalo, NY	70-0267	376	Model: 6244, Chem-Nuclear Systems, Inc.	71-6244	383
Nuclear Fuel Services, Inc., Erwin, TN	70-0143	375	Model: 6272, U.S. Ecology	71-6272	383
Nuclear Fuel Services, Inc., Erwin, TN	70-1764	379	Model: 6400, Westinghouse Electric Corp.	71-6400	384
Nuclear Fuel Services, Inc., Erwin, TN	70-1549	379	Model: 650, Technical Operations, Inc.	71-9032	385
Pacific Gas & Electric Co., San Francisco, CA	70-2375	379	Model: 660 & 660E, Technical Operations, Inc.	71-9033	385
Robert Packer Hospital, Sayre, PA	70-2669	379	Model: 6679, U.S. Ecology	71-6679	384
Rochester, Univ. of, Rochester, NY	70-2982	380	Model: 6717-B, Gamma Industries	71-6717	384
Rockwell International Corp., Canoga Park, CA	70-0025	375	Model: 676 & 676E, Technical Operations, Inc.	71-9029	385
Teledyne Isotopes, Inc., Westwood, NJ	70-0124	375	Model: 680 & 680E, Technical Operations, Inc.	71-9035	385
Teleflex, Inc., North Wales, PA	70-1224	378	Model: 702, Technical Operations, Inc.	71-6613	384
Tennessee Valley Authority, Chattanooga, TN	70-2910	380	Model: 715, Technical Operations, Inc.	71-9039	385
Tri-State Motor Transit Co., Joplin, MO	70-1739	379	Model: 850, Technical Operations, Inc.	71-9147	387
UNC Naval Products, Inc., Uncasville, CT	70-0371	376	Model: 855, Technical Operations, Inc.	71-9165	387
Union Carbide Corp., Tuxedo, NY	70-0687	376	Model: 900, Technical Operations, Inc.	71-9141	387

Name	Docket	Page	Name	Docket	Page
Model: 9080, Hittman Nuclear & Development Corp.	71-9080	386	Model: HN-100, Series 3, Hittman Nuclear & Development Corp.	71-9151	387
Model: 920, Technical Operations, Inc.	71-9143	387	Model: HN-100S, Hittman Nuclear & Development Corp.	71-9089	386
Model: AL-L 11, Energy, Dept. of	71-5885	383	Model: HN-200, Hittman Nuclear &		
Model: AL-L 8, Energy, Dept. of	71-5645	382	Development Corp.	71-6574	384
Model: ANL-390-SPM, Energy, Dept. of	71-6104	383	Model: HNPF Spent Fuel Shipping Cask, Energy, Dept. of	71-5469	382
Model: ANL-402-SPM & 403-SPM, E.I. du Pont de Nemours	71-634 5	383	Model: Husman Irraditor, Agriculture, Dept. of	71-9182	388
Model: Bettis Waste, Energy, Dept. of	71-6142	383	Model: IR-100, Industrial Nuclear Co.	71-9157	387
Model: BMI-1, Battelle Columbus Laboratory	71-5957	383	Model: IR-50, Industrial Nuclear Co.	71-9156	387
Model: BR 63-0101, Energy, Dept. of	71-5608	382	Model: KKP-20-4950, Kerr-McGee Nuclear Corp.	71-9100	386
Model: C-10, Gamma Industries	71-9133	387	Model: L&M ORNL Uranium Shielded Cask,		
Model: CBE-14, Energy, Dept. of	71-6421	384	Energy, Dept. of	71-5595	382
Model: Century S & SA, Cen. Univ. S & SA Gamma Industries	71-9135	387	Model: Lithium Hydroxide Fire/Impact Shield, Energy, Dept. of	71-9851	388
Model: CNS 1-13CII, Chem-Nuclear Systems,	G1 0150	201	LLD-1, Energy, Dept. of	71-4960	381
Inc.	71-9152	387	Model: M-130, Energy, Dept. of	71-6003	383
Model: CNS 14-190, Chem-Nuclear Systems, Inc.	71-5026	381	Model: Mark VR, VE & Mark 15, Energy Dept. of	71-5467	382
Model: CNS 21-300, Chem-Nuclear Systems, Inc.	71-9096	386	Model: MH-1A, Energy, Dept. of	71-6639	384
Model: CNS 6-75, Chem-Nuclear Systems, Inc.	71-9108	386	Model: MRC-20WC, Monsanto Research Corp.	71-9142	387
Model: CNS 6-80-2, Chem-Nuclear Systems, Inc.	71-9111	386	Model: MX-IC-100, Magnaflux Corp.	71-9110	386
Model: CNS 8-120, Chem-Nuclear Systems, Inc.	71-6601	384	Model: N-55, Energy, Dept. of	71-9070	386
Model: D-38, Oak Ridge National Lab	71-6088	383	Model: NFS-4, Nuclear Fuel Services, Inc.	71-6698	384
Model: DOT Spec 6M, Energy, Dept. of	71-9508	388	Model: NLI-1/2, NL Industries, Inc.	71-9010	385
Model: DT-14, Energy, Dept. of	71-9852	388	Model: NNFD-10, Babcock & Wilcox Co	71-6357	384
Model: ETR, Exxon Nuclear Idaho Co.	71-9134	387	Model: None, Energy, Dept. of	71-5795	383
Model: F-147, Atomic Energy of Canada, Ltd.	71-9174	388	Model: NPI-67-0442, Neutron Products, Inc.	71-5364	382
Model: FSV-1, General Atomic Co.	71-6346	384	Model: NUPAC 14/210L & 14/210H, Nuclear Packaging, Inc.	71-9176	388
Model: Gas Cylinder Fire Impact Shield, Energy, Dept. of	71-5552	382	Model: NUPAC 6/100L & 6/100H, Nuclear Packaging, Inc.	71-9179	388
Model: GE 21PF-1, General Electric Co.	71-4909	381	Model: NUPAC 7/100, Nuclear Packaging, Inc.	71-9178	388
Model: GE-200, General Electric Co.	71-5971	383	Model: NUPAC Series A, Nuclear Packing, Inc.	71-9159	387
Model: GNG-20, Gulf Nuclear, Inc.	71-9163	387	Model: ORNL in Pile Capsule, Energy, Dept. of	71-5907	383
Model: GPHS, Energy, Dept. of	71-9510	388	Model: ORNL Loop Transport Cask,	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	
Model: HFIR Spent Fuel Element Shipping Cask, Energy, Dept. of	71-5507	382	Energy, Dept. of	71-5753 71-6553	382 384
Model: HN-100, Series 1, Hittman Nuclear & Development Corp.	71-9086	386	Model: PADUCAH Tiger, Energy, Dept. of Model: R1010-0032, Energy, Dept. of	71-6333	383

Name	Docket	Page	Name	Docket	Page
Model RCC, -1, -2, -3, -4,			Model TN-9, No Users	71-9016	385
Westinghouse Electric Corp	71-5450	382	Model: TREAT, Energy, Dept. of	71-5828	383
Model: SNAP-23A 1000, Navy, Dept. of	71-9017	385	Model: Tungsten Shielded Cask,		
Model: SPEC 2-T, Source Production &			Energy, Dept of	71-5597	382
Equipment Co.	71-9056	385	Model: UNC-2500, United Nuclear Corp	71-5641	382
Model. Steel Ingot Skid & Box 37, Energy, Dept. of	71-5170	382	Navy, Dept. of	71-0367	381
Model: T-2, Energy, Dept. of	71-5607	382	Transnuclear, Inc.	71-0250	381
Model: T-3, Energy, Dept. of	71-9132	387	Licensing of Independent Spent Fuel Storage -	Docket 72	
Model: TN-8, -8L, No Users	71-9015	385		- Docket 12	
			Morris Operations, General Electric Co.	72-0001	388

DOCKETED ITEMS

LOW LEVEL RADWASTE DISPOSAL SITES DOCKET 27-039 BHEFFIELD, IL, U 8 ECOLOBY, INC

8306240391 Forwards results of Sheffield analysis & listing of samples collected in 1983 awaiting lab analysis Updated analysis rept will be submitted M/o enc!

HAMEL, H A Illinois, State of, Dept Nuc Safety (formerly Dept Public Health), 83/06/13 SCHAFNER, J NRC - No Detailed Affiliation Given ip 18987, 347

DOCKET 27-047 BARNWELL, BC, CHEM-NUCLEAR SYSTEMS, INC.

8306210497 Trip rept of 830411-13 visit to Barnwell.80 & Columbia,80 to familiarize DA Widmeyer w/facility personnel.components, layout & operations to assume NRC project manager role PANGBURN, 0 C . WIDMAYER, D A. Low Level Waste Licensing Branch 83/06/06 HAWKINS,E F Low Level Waste Licensing Branch 3pp 18936,267.

8306240394 Ack receipt of 830302 ltr re impact of iOCFR61 on rate changes Price increases only partially attributed to iOCFR61 implementation EBENNACK, D.O. Chem-Nuclear Bystems, Inc. 83/06/10 BROWNING, R.E. Division of Wasta Management ip 19987 348

DOCKET 27-048 RICHLAND, WA, U S, ECOLOGY, INC.

8306020225 Ack receipt of ltr re Amend 3 to License 16-19204-01. Change incomprehensible w/o adequate background Brisfing requested MENINICK, J Yakima Indian Nation. 83/04/27 HAWKINS.E F L Level Waste Licensing Branch ip 19701.011

8304020222 Forwards monthly SNM receipt & burial rapt for Apr 1993, per License Condition 6 & rept of isotopic activity required by Btabe of WA Wio encls HRIGHT, B. V. US Ecology, Inc (formerly Nuclear Engineering) 83/05/11 HAWKINB, E. Low Level Waste Licensing Brench ip. 18701-014

8306210435 Forwards draft use application to determine if all requirements necessary to receive & bury high integrity container at facility addressed Request for approval will not be submitted until meeting to discuss draft held. HIPSHER.W.M. US Ecology. Inc. (formerly Nuclear Engineering) 83/05/17. KIRNER.N. Meahington, State of 27pp 18937.001

8306240487 Forwards monthly BNM receipt & burial rept for May 1983, per License Condition 6 & rept of isotopic activity, per State of HA License Wh-1019-2 WRIGHT, B V. US Ecology, Inc. (formerly Nuclear Engineering), 83/06/13, HAHKING, E. Low Level Waste Licensing Branch. ip. 18998:066.

DOMESTIC LICENSING OF SOURCE MATERIAL

DOCKET 40-0086 W R. GRACE & CO . POMPTON PLAINS, NJ

830A010103 Responds to B30311 ltr & reaffirms B30218 position that DDE will not assume responsibility for remedial actions at Pompton Plains site. DDE plans no further action unless addl legislative authority provided.

BAUBLITZ.J E Energy, Dapt. of. B3/04/11 PAGE.R.G. Uranium Fuel Licensing Branch Bpp 18686.351.

8306010263 Forwards RD Closeout Insp Rept 40-0086/74-01 on 740731, 0801 & 02 & 0720, per 830417 request, KINNEMAN, J D Region 1, Office of Director 83/04/26. TONGUE, T. D. W. R Grace & Co. ip 18672, 255.

DOCKET 40-0299 UNION CARBIDE CORP , GRAND JUNCTION, CO

- 8304070467 Forwards application to amend License BVA-648 increasing capacity of A-9 pit tailings area Approval requested by 820515.
 - 830515. LYONS,P J. Union Carbide Corp. 83/03/28 PETTENGILL.H Uranium Recovery Licensing Branch ip. 19781:134.
- ~~8306070470 Application for amend to License SUA~648, increasing capacity of A~9 pit tailings area * Union Carbide Corp 83/03/31, 208ap 18781*135.
- 8304020314 Forwards corrected "40CFR190 Data Summary for 1982." Summary indicates that estimated dose commitment at JE Ranch is 0. HDNO.T. Union Carbide Corp. 83/04/27. HOOLBEY.R. Uranium Recovery Field Office ip. 18715
- --8306020320 Corrected "400FR190 Data Summary for 1982." WONG.T Union Carbide Corp 83/04/27, Spp. 18715.272.
- 8306080350 Forwards eight oversize figures for use in reviewing amend to License BUA-648 to increase capacity of A-9 pit tailings area Aperture cards are available in PDR LUTKIN.H.H. Water, Waste & Lend, Inc. 83/04/RZ. PETTENOILL, H. Uranium Recovery Licensing Branch ip 18790:294
- 8304020198 Forwards corrected version of 830402 ltr re temporary closure of Gas Hills U Mill, tr should be dtd 830502. LYONS,P J Union Carbide Corp. 83/05/09. PETTENGILL,H. Uranium Recovery Licensing Branch. ip. 18701:068.
- --8366020201 Confirms B30429 telcon that milling of mins are through Qas Hills U Mill will be curtailed on B30601 Amend to License BUA-648 mesded to increase A-9 tailings pit capacity. LYONB:P J. Union Carbide Corp. B3/05/02 PETTENGILL, H Urantum Recovery Licensing Branch. ip. 18701:069.
- 9304020259 Forwards R Williams observations re evaporation pond spill at Cas Hills, MV site Contaminated soils not removed & deposited in A-9 pit due to bad wasther.
 PETTENGILL. H. J. Uranium Recovery Field Office. 83/05/10, BROWN: O.D. Division of Vendor & Tachnical Programs ip. 18700:324
- --8306020269 Submits observations re evaporation pond spill at East Ogs Hills, HY site Spill discovered on B30405 in form of seepage at toe of embankment separating evaporation ponds from tailings disposal pit. HILLIAMS, R. E. R. E. Hilliams & Associates, Inc. B3/04/18, PETTENGILL, H. Uranium Recovery Licensing Branch, Rep. 18700; 327,
- B304020340 Rejects 830225 request for amend to License 8UA-448 to postpone claemup of contaminated soils resulting from windblown tailings. Cleenup should be completed by 830801. PETTENGILL, H. J. Uranium Recovery Field Office, 83/05/11. BEVERLY, R. Q. Union Carbide Corp. 2pp. 18715 317.
- 8906220116 Advises that plans & specs signed by State of MY engineer & addl copy of application required to process application to increase A-7 pit tailings area capacity.

 LABARGE.F. Myoming, State of, 83/05/12, LYONS, P. J. Union Cartide Corp. ip. 18937-362,
- 8306220118 Advises that plans & space signed by State of WY angineer required to process application for A-7 pit collection sys.

 LABARGE, F. Hyoming. State of, 83/05/13, LYOMS, P. J. Union Carbida Corp. ip. 18937-361.

OCKET 40-0572 NUCLEAR METALB, INC., CONCORD, MA

- 30&0&0167 Forwards IE Insp Repts 40-0672/81-03,40-0672/82-01 & 40-0672/82-02 on 810115,820419-20 & 0804 & notice of
- violation MARTIN.T T. Division of Engineering & Technical Programs 83/05/23 TUFFIN.H.B Nuclear Matals, Inc. 2pp. 16728 118
- -8306060169 Notice of violation from insps on 810115,820419-20 & 0804 * Region 1, Office of Director 83/05/23 1p 18728 120
- -8306060172 IE Insp Rept 40-0672/81-03 on 810115. Noncompliance noted radioactive mat1 transported in inadequate packages & package w/dangerous quantity of flammable gas received. NICOLOSI.J. KINNEMAN.J Region 1. Office of Director. 83/04/29. Spp 18728 121.
- -8306060177 IE Insp Rept 40-0672/82-01 on 820429 Noncompliance noted, containers of radioactive eat! that evolved quantity of dangerous gas transported NICOLOSI.J. KINNEMAN.J. Region 1. Office of Director 83/04/29 17pp. 18728 126
- -8306060179 IE Insp Rept 40-0672/82-02 on 820804 Noncompliance noted, radioactive math transported in inadequate package NICOLO81,J. KINNEMAN.J. Region 1: Office of Director 83/04/29 21pp. 18728 143
- CKET 40-1162 WESTERN MUCLEAR, INC , JEFFREY CITY, WY
- 06200074 Addendum to "Oroundwater & Burface Water Monitoring Results.Fourth Quarter.1982" 80006N.9. Western Nuclear. Inc. (subs. of Phelps Dudge Corp.). 83/04/29 PETTENGILL.H J. Uranium Recovery Licensing Branch 27pp. 18908.179
- 06220136 Requests Western Nuclear rept, "Reclamation Flam,Mill Site & Tailings Disposal Area" & 820219.22 & 0302 ltrs re radiological & hydrologic issues SETFFERT.8 9 Wyoming, State of 83/05/13 PETTENGILL,H J Uranium Recovery Field Gefice ip 18937-352
- CKET 40-1341 TENNERBEE VALLEY AUTHORITY, CHATTANGOOA, TN
- G6020903 Forwards revised License BUA-BI6 License will not expire until NRC completes FE6 & BER re decommissioning of Edgemont U Mill. BHITH: R D Ursnium Recovery Field Office: 83/04/06 Tennesse Valley Authority ip 19715-154.
- 9306020509 Ravised License SUA-Bló extending license in entirety until NRC determines in FES & SER that decommissioning Edgement U Mill tailings site is adequate.

 NRC No Detailed Affiliation Given 83/04/06 16pp. 18715.155.
- 06200155 Updates B21022 submittal re Edgemont Mill unresolved item from IE Insp Rept 40-1341/82-01 on 820616. Beeg in uninhabited area outside restricted site boundary isolated by fencing & restricting access. MILLS,L M Tennessee Valley Authority. B3/05/17. BMITH.D. Uranium Recovery Field Office 5pp. 18909, 164.
- 0.6210307 Application for amend to License SUA-Bib to accommodate disposal of up to 12,000 cubic yards of residual radioactive setts. Const of repository scheduled to begin in Aug or Sept upon receipt of State of SD copperative agreement. FUCKER, M. K. Energy, Dapt. of. 83/06/01. BMITH, D. Uranium Recovery isld Office 2pp 18923-361
- 06210428 Discusses license amend & other documentation necessary to accommodate disposal of vicinity property matts.

 **PUCKER.M K. Energy, Dept of 83/06/01. SMITH.D. Uranium Recovery Field Office 2pp 18937-031.
- KET 40-2061 KERR-HOGEE CHEMICAL CORP., DKLAHOMA CITY, DK
- 6080293 FGIA request for list of addressess receiving DEB re ecommissioning of Rame Earths Facility. Mest Chicago: IL ubsquent to Hay 1982 PELMAN, H J Harold J Bpelman & Associates. 83/03/93, D: f Rules and Records. 2pp. 18792.145.

- 8304080297 Responds to FOIA request for list of addressees receiving DES re decommissioning of Rare Earths Facility. West Chicago, IL subsequent to May 1982 Forwards mailing list for DES Addressees receiving DES after May 1982 not identified FELTON, J M Division of Rules and Records 83/04/06 SPELMAN, H J Harold J Spelman & Associates 1p 18792 147
- ---8306080302 "Distribution List.Kerr-McGee West Chicago DE8 " * NRC No Detailed Affiliation Given 83/04/06 8pp 18792 148
- 8306010069 Fowards response to JL Grant ltr commenting on thorium plant closure rept Differences exist due to lack of access or possession of ref documents PORTE A Radiation Safety Services, Inc. 83/04/08 FILMER.P L Harold J Spelman & Associates, Epp. 18697.082
- 8304060362 Issues Amenda 5 & 6 to License STA-583 authorizing dismantling of Bldgs 2,10,11,14,16 & 21 at West Chicago site. PAGE.R G Uranium Fuel Licensing Branch 83/05/27 SHELLEY.W J. Kerr-McGee Chemical Corp (subs of Kerr-McGee Corp) 1p. 18751:282
- --B306060367 Bafety evaluation supporting Amends 5 & 6 to License BTA-583.authorizing dismantling of Bldgs 2,10,11,14,16 & 21 at West Chicago site NIXON,W A Uranium Fuel Licensing Branch. B3/05/27 App 18751-283
- 8906080397 Fowards completed eligibility form for inorganic chemical mfg industries that may be subj to pretreatment regulations Factifity shut down since 1973
 DENNY, I L. Kerr-McGee Chemical Corp. (subs. of Kerr-McGee Corp.) 83/05/27 ROBICHAUD, R. R. Environmental Protection Agency 2pp 18787-346.
- 8306200042 Forwards Radiation Bafety Svcs, Inc response to JL Grant ltr re assessment of Law Engineering Testing Co West Chicago thorium plant closure root Delay in receipt of response due to unission of name from distribution list SPELMAN. H. J Harold J Spelman & Associates 83/05/28 NIXON, H. A. NRC No Detailed Affiliation Given Spp 18919 310
- 8304080144 FINAL ENVIRONMENTAL STATEMENT RELATED TO THE DECOMMISSIONING OF THE RARE EARTHS FACILITY, WEST CHICAGO, ILLINOIS, Dacket No. 40-2041 # Division of Fuel Cycle & Material Safety NUREQ-0904, 83/05/31 522pp Available at NRC \$10.00. 18788-001,
- 8304020343 Advises that time for Commission to review presiding officer decision expired Commission declined review Decision became final agency action on B30527 and CHILK, S. J. Office of the Secretary of the Commission 83/06/01, Kerr-McOse Chemical Corp. (subs of Kerr-McOse Corp.) ip.
- 8306070435 Forwards FR notice of availability of FES re decommissioning of Rare Earths facility.

 FAGE.R.O. Uranium Fuel Licensing Branch. 83/06/02. SHELLEY, H. J. Kerr-McGee Chemical Corp. (subs of Kerr-McGee Corp.) 1p 19776:349
- --8306070442 Notice of opportunity for hearing & evailability of FEB for decommissioning of Rare Earths facility PAGE, 0 Uranium Fuel Licensing Branch 83/05/27 App 18776:350
- DOCKET 40-2259 PATHFINDER MINES CORP., RIVERTON, WY
- 8306130406 Comments on Fourth Quarter 1982 environ manitoring data for Pathfinder Mines Corp Lucky Mc Hill Radionuclide data for groundwater monitoring walls will be submitted in Apr 1983 1983 MOOLSEY,R T , PETTENGILL,H J Uranium Recovery Field Office 83/03/11 Region 4, Office of Director 3pp. 18823:092, 63/03/11
- 8306160696 Bubmits waste metls disposal program. Hastes are monitored by radiation staff & classified according to contamination level level PGYSER, R W Pathfinder Mines Corp 83/03/24 HOOLSEY, R. T Uranium Recovery Field Office 3pp 18876-273
- 8304020263 Updates status of pumpback sys & contaminated groundwater plume at Lucky Mc Mill site Surface expression of contaminated groundwater plume still exists.
 WILLIAMS,R.E. R.E. Williams & Associates, Inc. 83/04/18.
 PETTENGILL.H Uranium Recovery Licensing Branch 3pp 18700.323

- 8306160234 "Quarterly Effluent Monitoring Rept for Fourth Quarter 1982 " H/830512 ltr HARDOROVE,T W Pathfinder Mines Corp 83/05/12. HOOLSEY,R T Uranium Recovery Field Office 3pp 18861 236.
- 8304220121 Forwards comments on renewal application re final reclamation plan & seepage control Considerable upgrading of plan to assure long-term stabilization recommended FREUDENTHAL, N. Wyoming, State of. 83/05/23 BMITH.D. NRC No Detailed Affiliation Given 10pp 18977-034
- DOCKET 40-3392 ALLIED CHEMICAL CORP . MORRISTOWN, NJ
- 8304080404 Forwards response to environ questions; per 830425 ltr re Bource Matl License 8U9-824 CIPOLLA, A J Allied Chemical Gorp. 83/05/27 HYNGARDEN, S. Uranium Fuel Licensing Branch 286pp, 18791-219
- DOCKET 40-3453 ATLAS MINERAL, INC., DENVER, CO
- 8304200437 Tabulates contract costs incurred & manhours expended in reviewing 821024 application for Amend 11 to License 8UA-917
- OARCIA, P. PETTENGILL, H. Uranium Recovery Field Office 83/05/15 MILLER, W. O. License Fee Management Branch 1p. 19920.011.
- B306200107 Informs that Mosb Wash interim operation phase mods complete per revised Condition 16,6td 830228 BLUBAUGH, R E Atlas Minerals, 83/05/17, BMITH, D. Uranium Recovery Licensing Branch. 1p. 18908-202.
- 830617046B Informs of 821004 official opening of U recovery field ofc in Lakewood, Co Future correspondence should be sent to Lakewood field ofc, effective 830601. Washington, DC ofc being phased out SMITH.R D. Uranium Recovery Field Office, 83/05/23 BLUBAUOH, R Atlas Minerals App. 18874 356
- DOCKET 40-4492 FEDERAL-AMERICAN PARTNERS, RIVERTON, WY
- 830.6200067 Confirms understanding per 830.511 telcon that work can begin on Willow Eprings Draw w/o completing design mods & requirements specified in Amend 14 to License 8UA-667. Rerouting of draw may be delayed due to bed weather ANDRUB, N. J. Federal American Partners 83/05/18, LINEHAN, J. Uranium Recovery Field Office. 2pp. 18908:171.
- DOCKET 40-6264 MICHIGAN CHEMICAL CORP., ST. LOUIS, MI
- 8306210434 Discusses site evaluation & closeout of docket file. Consent Judgement requirements & proposed notations on granite marker & in land deeds adequate to protect public from radioactive conteminants on site. CROW.W.T., PAGE,R & Uranium Fuel Licensing Branch. 83/06/08. Uranium Fuel Licensing Branch. 3pp. 16936-357.
- 8306170479 Confirms 830601 telcon re Velsical Chemical Corp site in 8t Louis, MI Stabilization plan implementation imposed by 821227 consent judgement adequate to protect public & environ from radioactive contaminants PAGE.R. 9 Uranjum Fuel Licensing Branch 83/06/09. RADEMACHER, J. W. Velsical Chemical Corp ip. 18894:321.
- DOCKET 40-6500 ENERGY: DEPT OF, CANONEBURG, PA
- 8304030504 Summary of data from Mound radon program monitoring network in Canonsburg: PA for 820129-0430. CAR designators in table to be used w/maps of Canonsburg area sent to NRC on 830415 RUDY: C R Monsanto Research Corp 83/04/22. CROW. M.T. Assistant Director for Fuel Cycle Safety & Licensing. 2pp. 18735:003.
- 830401007D Summary of Canonsburg outdoor menitoring data mound radon program for 820429-0729, RUDY.C.R. Honsanto Co. 83/04/29, GRDH, W.T. Uranium Fuel Licensing Branch, 2pp. 18686:248,
- 8305030194 Bummary of data from Mound/radon program radon monitoring network in Canonsburg.PA area for 821029-830128. Indoor radon monitoring commenced on 821119 at new site not marked on location map. RUDY.C.R. Monsanto Research Corp. 83/05/10. CRCM, W.T. Assistant Director for Fuel Cycle Safety & Licensing. App. 18793:335.

- 830&010479 Comments on items of interest Amend issued to License SUB-1010, authorizing disposal of treated liquid raffinate via injection in deep salt water aquifier. PAGE.R 0 Uronium Fuel Licensing Branch 83/05/26, DAVIB, J. 0. Office of Nuclear Material Safety & Safeguerds, Director ip. 18686.358.
- 8306070430 Submits current items of interest re issuance of License SNM-1915 on 830531 & 830526 meeting w/DOE to discuss UNITRCA program PAGE/R Q Uranium Fuel Licensing Branch 83/06/02, DAVIS, J. 6. Office of Nuclear Material Safety & Safeguards Director. 3pp 18780-345
- 8306280030 Summary of 830609 meeting w/DDE in Albuquerque, NM re DES for remedial action at Canonsburg, PA site. NMSB meeting schedule encl PAGE, R. O. Uranium Fuel Licensing Branch 83/06/16, DAVIS, J. 9. Office of Nuclear Material Bafety & Bafeguards, Director. 2pp.
- 8306290101 Summary of 830617 mesting w/DDE on proposed remedial action plan for Canonsburg.PA site DDE informed of addl info required to continue technical review of plan.Notice of 830707 meeting w/EPA encl.
 PAGE.R.O. Uranium Fuel Licensing Branch 83/06/22 DAVIE, J.O. Office of Nuclear Haterial Sefety & Sefeguerds, Director. Epp. 17046 178.
- DOCKET 40-6622 PATHFINDER MINES CORP. , SHIRLEY BASIN, WY
- 8306140168 Requests add1 info or explanations on Questions 2(a),2(b) & 3 re slope stabilization & PMF in order to respond completely to request for add1 info re application for licensing.

 RUSBELL-J E. Pethfinder Mines Corp. 83/05/05, PETTENGILL-H.J. Uranium Recovery Licensing Branch. ip 18844:185.
- DOCKET 40-6940 KAMECKI BERYLCO IND., INC., BOYERTOWN, PA
- 8306280610 Discusses IE Insp Rept 40-6940/83-01 conducted on 830607 & OB No noncompliance noted Mejor areas inspected radiation safety; procedures & representative records, interviews w/personnel & measurements taken by inspector MARTIN.T.T Division of Engineering & Technical Programs, 83/06/82, COYLE, F. KBI Corp 2p. 19015-359.
- 8306270611 Summary of B30607 & OB site safety inspe in Boyentown Revers & Resding, PA. COOL, D. A. Division of Fuel Cycle & Material Safety. B3/06/22. Division of Fuel Cycle & Material Safety. 2pp. 19047:083.
- DOCKET 40-7580 FANSTEEL, INC., NORTH CHICAGO, IL
- 8304030469 Trip rept of 830505 mesting w/licensee & State of CM Water Resources Board at site in Muskopee.CM re application for add1 ponding capacity.

 RHODES.M.J. Uranium Fuel Licensing Branch. 83/05/26. Uranium Fuel Licensing Stanch. ip. 18735:277.
- DOCKET 40-7869 PLATEAU RESOURCES, LTD., GRAND JUNCTION, CO
- 8306130347 "Effluent Monitoring Rept" for Jul-Dec 1982 for Shortaring Canyon leaching facility.

 GERDEMAN.F.M. Plateau Resources, Ltd. 83/04/19. Region 4. Diffice of Director. 11pp. 18822:276.
- DOCKET 40-8027 KERR-MCGEE NUCLEAR CORP. , OKLAHOMA CITY, DK
- 6306130344 Repts release of nuclides in effluents to unrestricted areas during Second Half 1982. BHELLEY, M. J. Kerr-McGes Chemical Corp. (subs. of Kerr-McGes Gorp.). 83/02/21 BROWN, O D. Region 4, Office of Director. 3pp. 18823:002.
- 8306080152 Forwards IE Insp Rept 40-8027/83-01 on 830214-18 & notice of violation
 BRONN, 9. D. Region 4, Office of Director. 83/04/06 BHELLEY, M. J.
 Kerr-McGes Nuclear Corp. 2ap. 18772:175.
- --8306080186 Notice of violation from insp on 830814-18. * Region 4. Office of Director. 83/04/06. 2pp. 18772:177.

- ---8306080163 IE Insp Rept 40-8027/83-01 on 830214-18 Noncompliances noted failure to perform direct radiation surveys & properly sample stack effluent One unresolved item re location of air sampler heads & air flow rates identified, SHOPENN,N M. SPITZBERG,D. B. EVERETT,R. J. Region 4, Office of Director 83/03/24, iipp 18772 179.
- 8304020213 Forwards list of formal site visit questions re EIA on license renewal. Hritten responses needed by 630613 RHODES M Uranium Fuel Licensing Branch 83/05/24 SHELLEY, W J Karr-HcQew Nuclear Corp. 6pp. 18701 048.
- 8306030186 Trip rept of attendance at 830504 meeting w/Kerr-McOee Nuclear Corp in Gore.OK re questions concerning environ review of vandor license renewal application RMODES.M.J Uranium Fuel Licensing Branch. 83/05/26. Uranium Fuel Licensing Branch. 1p 19733 320
- 8306140767 Forwards request for additinfo re evaluation of 820924 renewal application for License BUB-1010 Comments on initial review encl. Formal response to comments expected by 830715. Maeting to discuss draft response suggested. KOBLA.8 M. Uranium Fuel Licensing Branch 83/06/02. SHELLEY.W J. Kerr-McOse Nuclear Corp. 5pp. 18945-333.
- 8305240343 Forwards leach test results of composite sample of line fluoride sludge per request Quantity of U leached w/water leach test negligible, substantiating soundness of proposed oneits burtal.

 BHELLEY, U. Kerr-McOse Corp. 83/06/06 PAQE, R. O. Uranium Fuel Licensing Branch 2pp. 18999.181

DOCKET 40-BOSS COTTER CORP. , ROSHELL, NM

8305050415 Summary of 830505 meeting w/DOE.Bechtel & State of MO representatives in 8t Louis. MO to legislation on decontamination of former Cotter Corp site, List of attendess enci CROM. M T. Uranium Fuel Licensing Branch. 83/05/31. Uranium Fuel Licensing Branch 2pp 18748:357

DOCKET 40-8064 EXXON MINERALB CD USA, HOUSTON, TX

- 8306060318 Proposes mod to excursion parameters monitoring frequency from bimonthly to monthly Hod would affect Conditions 30 & 31 of License BUA-1064 & portions of Tables 2 & 3 in 830917 submittel old Example 6140419 LINEHAN, J J. Uranium Recovery Field Office 7pp. 18751 354.
- 8306020294 Withdraws Comment 3 re expanded R&D pilot U solution mine. Licensee supplied adequate data to justify limited sampling suite currently being analyzed Wells M-3,4 & 5 should be included in post-restoreation monitoring program FREUDENTHAL,N., SMITH,M. Myoning, State of 83/04/25. SMITH,R.D. Uranium Recovery Field Office. 7pp 18700:316
- 8306070456 Notifies of mod restoration program at Highland expanded RAD pilot U in situ mine. Use of reverse osmosis sys will be terminated. Bempla groundwater sweep program will be implemented.

 8HANNON.J.B. Exxon Corp. 83/05/03. LINEHAN.J.J. Uranium Recovery Field Office. 1p 18780*311.
- 8305210454 Forwards Land Guality Div & Water Quality Div reviews of Exten 820917 math re restoration of original pilot in situ U mine. FREUDENTHAL, N Wyoming, State of 83/05/06, SMITH, R. D. Uranium Recovery Field Office. 22pp. 18935: 316,
- 8306200421 Reaffirms position that max practical restoration achieved & femonstrated for original pilot in situ U mine at Highland.per 820929 & 830406 submittals. OLCHRIST.J.E. Exton Corp. 83/05/17. LINEHAN, J.J. Uranium Recovery Field Offics. 2pp. 18919-292.

DOCKET 40-9094 RID ALGOH CORP., HOAS, UT

- 306070163 Forwards IE Insp Rept 40-8084/82-02 on 821214-16 & notice of violation RNOWN 9.D. Region 4. Office of Director, 83/02/02 LAHTON, H D. Rio Algom, Ltd 2pp. 18792-322
- --8306090167 Notice of violation from Insp on 821214-16. * Region 4. Office of Director. 83/02/02 2pp 18792.324.

- --B306090175 IE Insp Rept 40-8084/82-02 on 821214-16 Noncompliance noted occupational overexposure of one minor to airborne soluble U & to airborne U ore dust to two minors & feilure to rept overexposures to NRC & individuals SPITZDERG, D B , CAIN, C L , EVERETT, R. J. Region 4, Office of Director 63/01/21 18pp 18792-326
- 8306R00171 Forwards data derived from 1981 vegetation sampling under discontinued License Condition 18 Data should be inserted in 1981 environ menitoring rept Addendum to "Semiannual Environ Monitoring Rept.Jul-Dec 1982," enc1 HARDY, B L Rio Algom. Ltd 83/05/04 HABTLER, S Uranium Recovery Licensing Branch 1p 18909-315
- --8306200175 Data derived from vegetation sampling during 1981 * Rio Algom, Ltd. 83/03/04 ip 18909 316
- --83062002B5 Addendum to "Semiannual Environ Monitoring Rept, Jul-Dec 1982." LANTON, M D Rio Algom, Ltd 83/05/09 38pp 18909 317
- 8306210431 Reviews licenses Jul-Dec 1982 environ monitoring rept submitted per 10CFR40 65 & License Conditions 36 & 49 Rept lacks sample analyses for Th-230.Pb-210 & Po-210 due to commercial lab delays WASTLER.S.L., LINEHAN.J J Uranium Recovery Field Office 83/05/18 Uranium Recovery Field Office 3pp 18937 028
- DOCKET 40-8348 MINERALS EXPLORATION CO , LOS ANGELES, CA
- 8306280106 Forwards memos discussed at 830511 mesting Memos are internal & do not represent official final div decisions on restoration issue ENGELMANN,R Wyoming, State of, 83/05/12 VDLK,B Union Energy ip 19042 302

DOCKET 40-8380 ROCKY MOUNTAIN ENERGY CD , BROOMFIELD, CO

- 8304160567 Forwards quarterly & monthly well data for Jon-Mar 1983. No further mining or restoration planned for Second Quarter 1983 SPIELES, P. R. Rocky Mountain Energy Co 83/04/30 SMITH, R D Uranium Recovery Field Office 3pp 18866 015
- --8306160576 Guarterly & monthly well data for Jan-Mar 1983 * Rocky Mountain Energy Co 83/04/30 13pp. 18866-018.
- 8306200276 Advises that Patterns 1.2 & 3 sufficiently restored so well closeout of Nine Hile Lake R&D Project can be authorized Vendor must secure surface owner release & advisa well permit applicants in area of groundwater canditions. BHAFFER.R., SUDIN.R. Wyoming, State of 83/05/20 OLDHAM,K.R. Rocky Mountain Energy Co 2pp 18709:357
- 8306200425 Advises that future applicants for well permits near Nine Mile Lake will be notified of deteriorated state of groundwater. Monitoring of plume movement suggested, BEACH. 9. Rocky Mountain Energy Co. 1p. 18720.026

DOCKET 40-8452 BEAR CREEK URANIUM CD . CABPER. WY

- 8305090224 Concurs w/preferred tailings disposal alternative of expanding present area Const of dam raise may not begin until dam stability review performed & license amend issued SMITH.R.O. Uranium Recovery Field Office. 83/05/18 Bear Creek Uranium Co App. 18809 205
- --8306090228 Discusses Amend 20 to Source Hatl License BUA-1310 re tailings mgt alternative of expansion of disposal area. PANGURN, O C., PETTENGILL, H J Uranium Recovery Field Office 83/05/18. Uranium Recovery Field Office 16pp 1809 209.

DOCKET 40-8502 WYOMING MINERAL CORP , LAKEHOOD, CO

- 8306130245 "Irigaray Mine Site Bamiennual Activity & Monitoring Rept for Jul-Dec 1982 " W/830215 ltr RUTLEDDE,C Wyaming Mineral Corp. 82/12/31 BROWN,C. Region 4, Office of Director. 11pp 18824-300.
- 8306020338 Issues Amend 5 to Source Matl License SUA-1341 changing License Condition 10 to incorporate radiation protection organization chart submitted by licensee on 830308 SMITH, B. Urenium Recovery Field Office 83/05/05 Wyoming Mineral Corp. 1p. 18715-316.

- 8306200182 Requests instructions & guidelines for preparing & filing, w/fee application, renewal of License SUA-1341 under 10cFR170 31-2D RUTLEDGE, C Wyoming Mineral Corp 83/05/16 ROSS,F Uranium Recovery Field Office ip 18709 182
 - Recovery Field Defice
- 8306160215 "Water Quality Data on Excursion Hells, Irigaray Mine Site, Jan-May 1983 " W/830526 ltr RUTLEDGE.C Hyoming Mineral Corp 83/05/26 SMITH.R D Uranium Recovery Field Office 2pp 18861 174
- 8306240436 Updates 821008 & 830127 status repts on Monitor Wells 978 & 9732, for Jan-May 1983, per 830526 telcon, Monitoring parameters for wells diminished to below NRC action level in four recent analyses RUTLEDGE, C. Wyoming Mineral Corp. 83/05/26 BMITH, R.D. Uranium Recovery Field Office. 2pp. 18997-239
- DOCKET 40-8584 MINERALS EXPLORATION CO., LOS ANGELES, CA
- 830-6140689 Requests amend to License BUA-1350, modifying environ & plant monitoring programs & procedures placing mill & toilings in environmentally acceptable condition SNYDER, H.L. Union 76 Minerals Exploration Co 83/04/12. SMITH, R. D. NRC No Detailed Affiliation Given. 7pp. 18845, 356
- 8304040415 Advises that liner manufacturer or installer for tailings cell liner not yet selected Specific installation details & plans unavailable installation specs will be provided prior to installation SNYDER.H L. Union Minerals. 83/04/22 QARCIA:P Uranium Recovery Field Office 1p 18748:356
- 8304020500 Confirms 830428 telcon re-possible reportable incident concerning disposal of low grade ore, mixed mill effluents & waste into internal mine pit waste dump. Attempt to locate mixed ore & effluents for removal planned.

 DYKERB, L. Q. Union 76 Minerals Exploration Co 83/04/29 BMITH, R D Uranium Recovery Field Office, 1p. 18715.183
- 8304200179 Forwards insp rept on 830422 re interim stabilization & citizen O Beach complaint. Containment pond residue, drilling, sampling & analysis procedure outline & description of incidents surrounding complaint requested, ENGELMANN.R. Wyoming, State of 83/05/09, DYKERS, L. O Union 76 Minerals Exploration Co 13pp 18909-169,
- 8306200111 Trip rept of attendance at 830510 maeting w/State of MY Dept of Environ Quality & Himeral Exploration Co in Chayenne MY re request for license to construct new tailings disposal facility at Sweetwater Hill in Red Desert HILLIAMB, R E R.E Williams & Associates, Inc. 83/05/11. GARCIA, P Uranium Recovery Field Office 3pp 18708: 233.
- 8306270177 Advises of administrative changes, CZ Hill will replace LQ Pykers as project manager of Sweetwater U Mine. TJ Klein will handle HL Bnyder former responsibilities. HOPKINB.J.M Union 76 Minerals Exploration Co. 83/05/25. SMITH.R.D Uranium Recovery Field Office. 1p. 18999-349.
- 8306220113 Responds to R Williams 830811 comments on meetings in SOCIONIS Respons to Milliams BUDDII comments on meetings in Cheyanna-MY re modified tailings proposal Response clarifies conclusions inconsistent w/Williams conclusions Further evaluation of issue recommended freeDENTHAL, N Wyoming, State of, 83/05/27, LINEHAN, J. Uranium Recovery Field Défice 2pp 18977:338
- 8306200423 Responds to request for rept on 830519 Visit to Sweetwater Mill. Six wells used to monitor groundwater at site. Bank erosion continuing problem w/pond. Leak detection sys checked daily MITCHELL,D.H. Battelle Hemorial Institute, Pacific Northwest Laboratory 83/06/01, PETYENGILL,H.J. Uranium Recovery Field Office, 1p. 18919 274
- DOCKET 40-8585 WYOMING MINERAL CORP., LAKEWOOD, CO
- 8304020515 Responds to B30308 request for amend to License BUA-1351 re appointment of corporate radiation protection officer. No amend required since new officer meets qualifications included in license. Case closed BMITH.R.D. Urenium Recovery Field Office B3/05/10. Wyoming Mineral Corp. ip. 18715.145.
- 8306090495 Discusses review of semiannual effluent monitoring rept for Bingham Canyon Extraction Plant for Jul-Dec 1982 Rept adequate. No further licensing action required. YOUNGY / PETTENDILL-H.J. Uranium Recovery Field Office 83/05/18. Uranium Recovery Field Office. 1p. 18815:167.

- DOCKET 40-8586 KERR-MCGEE NUCLEAR CORP , OKLAHOMA CITY, OK
- 8306020331 Issues Amend 1 to Bource Matl License BUA-i330 revising Conditions 4 & 29 to extend expiration date of license & require submittal of rept on site decommissioning activities

 BMITH,R D Uranium Recovery Field Office 83/04/29 Kerr-MccCorp 2pp 18715 307
- --B306020334 Advises of 830429 issuance of amend to Bource Matl License BUA-1330 extending expiration date of license, Amend initiated by NRC & is exempt from fees JOHNBON, T L., PETTENGILL.H J. Uraniom Recovery Field Office, B3/04/29 MILLER, W.O. License Fee Management Branch. ip. 18715-309.
- DOCKET 40-9410 STEPAN CHEMICAL CO., MAYHOOD, NJ
- 8306020238 Forwards application for renewal of License STC-1333, authorizing burial of alkeline thorium phosphate tailings at listed locations SWANSON, E. A Stepan Chemical Co Cycle & Material Safety ip 18 89/09/16. Division of Fuel ip 18700, 358.
- --8306020243 Application for renewal of License STC-1333, authorizing burial of alkaline thorium phosphate tailings at listed SWANBON, E. A. Stepan Chemical Co. 83/03/15 4pp. 18700: 359.
- 8306270238 Ack receipt of 830115 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 40-8610/80-01.
 Comprehensive environ rept required prior to NRC review of 830321 license renewal application.
 MARTIN.T.T Division of Engineering & Technical Programs. 83/06/16.
 JACOBSON.R L. Mayer, Brown & Platt. 2pp. 18988:260.
- --8306270239 Responds to NRC 821215 ltr re violations noted in 1E Insp. Repts 40-8610/80-01. Stepen not legally limble for presence of thorium on property between fence & railroad tracks. JACOBSON, R. L. Mayer, Brown & Platt. JACOBSON, R. L. Stepen Chemical Co. 83/01/15. MARTIN.T.T. Division of Engineering & Technical Programs 7pp. 18988-262
- DOCKET 40-8631 ARMY, DEPT, DF, ROCK IBLAND, IL
- 8306210148 PNO-III-83-046. on 830610, contaminated water from Heldon Epring Chemical Plant appeared to be draining into sits sewape sys due to dislodged mechanical plug. Cause unknown. Plug replaced NICHOLBON,N., SCHUMACHER,M. Region 3. Office of Director 83/06/15. 2pp. 18915 246
- DOCKET 40-8863 NUCLEAR DYNAMICS, INC., PROENTY, AZ
- 8306090172 Forwards IE Insp Rept 40-8663/83-01 on 830316.No noncompliance noted.

 BROWN, O D. Region 4, Office of Director. 83/04/15, STOICK, A. F. NO Resources, Inc. 2pp. 18792:281
- --8306090179 IE Insp Rept 40-8663/83-01 on 830316. No noncompliance noted.
 Insp consisted of site visit to determine status, review of records re past operation to ongoing monitoring programs.
 Facility inactive since Sept 1979.
 BPITZBERG, D. B.: EVERETT, R. J. Region 4. Office of Director.
 83/04/13. 3pp. 18792:283.
- DOCKET 40-8474 PLATEAU RESOURCES, LTD., GRAND JUNCTION, CO
- 8306220311 Application for amend to License Conditions 10 % 17 of License SUA-1326, due to organizational changes GERDEMAN,F.W. Plateau Resources, Ltd 83/05/06. SMITH,R.D. Uranium Resovery Licensing Branch. 3pp. 18977:152.
- DOCKET 40-BABI ENERGY FUELB NUCLEAR, INC., DENVER, CO
- 8306230027 Forwards final rapt. *1981 Excavations on White Mess Ban Juan County, UT. * Excavations conducted to comply w/License Conditions 45 & 47 Rapt should complete archeological work for current phase of tailings sys. RDBERTS, H. R. Energy Fuels Nuclear, Inc. 83/06/01. 9ILLEN, D. Uranium Recovery Field Office. ip. 18982:028.

- --8306230030 *1981 Ercavations on White Mess. San Juan County, UT* final rept
 DAVIS.W E Plano Archaeological Consultants 83/02/28 574pp
- 8306000181 Forwards IE Insp Rept 40-8681/82-01 k IE Enforcement Conference Rept 40-8681/82-02 on 821102-04 k 1207, respectively BROWN, 0. D. Region 4, Office of Director 83/03/07 VINCELETTE: M D Energy Fuels Nuclear, Inc. 2pp. 18772 261.
- --8304080190 IE Insp Rept 40-8681/82-01 on 821102-04 Noncompliance noted-failure to rept worker overexposure to airborne soluble U. to use source sett per license application & to post airborne rafloactivity areas
 CAIN.C.L., EVERETT.R. J. Region 4, Office of Director 82/12/09, 11pp 18772 263.
- ---8306080193 IE Enforcement Conference Rept 40-8681/82-02 on 821207 Major area discussed findings of NRC insp on 821102-04 Licenses will use approved respiratory protection program & expanded surveys in mill yellowcake areas CAIN.G L. EVERETT.R J Region 4, Diffice of Director 82/12/13 2pp. 18772 274
- 8306220274 Act receipt of 830407 payment of civil penalties proposed in NRC B30222 ltr.Corrective actions will be examined during subsequent insps.

 AKELRAD.J.A Director's Office, Office of Inspection and Enforcement, 83/04/21 VINCELETTE, H D Energy Fuels Nuclear, Inc. 20s. 18926 031
- B305020305 Forwards amend to memorandum of agreement between NRC & Advisory Council on Historic Preservation re mitigation of adverse effects of White Mesa U Hill project Signature requested.
 SHITH-R.D. Urenium Recovery Field Office 83/05/03 SHITH-R T Utah. State of. ip 18715.275.
- --8306020308 Amend to memorandum of agreement between NRC & Advisory Countil on Historic Preservation re mitigation of adverse affects of White Mesa U Hill project PETTEMPILL. HJ MRC - No Detailed Affiliation Given, * Advisory Council on Historic Preservation, 63/05/03 4pp 18715 276
- 830.6020324 Issues Amend 21 to Source Matl License SUA-1358 revising Conditions 40.41.45.47 & Table A re archaeological sites affected by White Mess Project Deadline for recovery of all "eligible" archaeological sites eliminated SHITH.D. Uranium Recovery Field Office. 83/05/11. Energy Fuels Nuclear, Inc. 3pp. 18715-300
- --8306020328 Recommends issuance of Amend 21 to License 8UA-1358 revising Conditions 40.41,45.47 & Table A changing archaeological site designations from "eligible" to "contributing" & eliminating deadline for refovery eliminating deadline for refovery eliLEN.D.M., LINEHAN.J J Uranium Recovery Field Office 83/05/11. Uranium Recovery Field Office, 4pp. 18715.303
- 8304090489 Presents NRC review of data in environ monitoring rept for Fourth Quarter 1982 Licenses has now reverted to semiannual reporting in Feb k Aug of each yr. No significant variations identified office Office

DOCKET 40-BAS4 WESTERN NUCLEAR, INC., LAKEHOOD, CO.

- 8306230032 Forwards design of multi-well pumping test planned for summer for R&D Site 2 to Christensen Rench, for review Proposed pumping test should be discussed at 830319 meeting.

 800DEN,0 Western Nuclear, Inc (subs of Phelps Dodge Corp).
 83/05/11, LINCHAN, J C. Uranium Recovery Field Office. 22pp
- DOCKET 40-8497 ROCKY MOUNTAIN ENERGY CO . DENVER, CO
- 830&i60327 "Guarterly Environ Monitoring Rept for First Quarter 1983." BPIELES.P. R. Rocky Mountain Energy Co. 83/04/18 SMITH.R.D. Uraniua Recovery Field Office 18pp 19859.288
- 8305200150 Advises that restoration of groundwater within Pattern II well field meets applicable groundwater use classification stds per Parmit 479. Decision based on company into & confirmation water samples collected on 830208-09 SUNDIN.R.E Hypming, State of 83/05/04 YELLICH, J. A Rocky Mountain Energy Co. 2pp 18909 126

- B306070450 Responds to B30504 discussion w/NRC re extension to license to authorize decommissioning activities Ltr requesting license stansion will be submitted at least 30 days prior to B30930 expiration date.

 NEUMANN,M R Rocky Mountain Energy Co B3/05/05 LINEHAN,J Uranium Recovery Licensing Branch ip 18780 359
- DOCKET 40-8698 PLATEAU RESOURCES, LTD , GRAND JUNCTION, CO
- B306090129 Forwards IE Insp Rept 40-8698/82-02 & IE Enforcement Conference Rept 40-8698/83-01 on 821123 & 830111, respectively BACHN.0 D Region 4, Office of Director, 83/03/07 FISHER, B D Flateau Resources, Ltd 2pp 18792
- --8306090132 IE Insp Rept 40-8678/82-02 on 821123 Noncompliance noted, failure to rept worker overexposures to airborne soluble U & to maintain bloessay program in accordance w/license requirements
 CAIN.C L , EVERETY.R J. Region 4, Office of Director 83/01/26
 Spp 18792 230
- ---8306090138 IE Enforcement Conference Rept 40-8690/83-01 on 830111. Major areas discussed findings of NRC insp on 821123 Licensee will implement engineering controls, retrain personnel & modify procedures
 GAIN.C L., EVERETT.R J Region 4, Office of Director 83/01/26
 2pp 18792 235.
- 830&140356 Forwards revised surety estimates in response to License Condition 39, to better reflect costs of decommissioning & reclamation Discussion of Proposed method of capping tailings impoundment also enc!

 GERDEMAN.F W Plateau Resources, Ltd 83/04/11 SMITH.R D. NRC No Detailed Affiliation Given. 1p 18854.143.
- --8306140367 "Interim Surety Estimates for Decommissioning & Reclamation," Shootaring Canyon processing facility. a Plateau Resources, Ltd. 83/04/30 NRC No Datailed Affiliation Given Spp 18854.144
- 830A220271 Ack receipt of 830324 payment of civil penalties proposed in NRC 830222 ltr. Corrective actions will be examined during subsequent insps
 AXELRAD.J A. Director's Office. Office of Inspection and Enforcement 83/04/21 FISHER.B.O. Plateau Resources, Ltd. 2pp 1802A 029.
- DOCKET 40-8714 CLEVELAND-CLIFFS IRON CO., CLEVELAND, OH
- 8305170459 "Quarterly Rept, Jan-Mar 1983," W/one oversize figure, Aperture card is available in PDR.W/830427 ltr WDDEK,D J. Cleveland-Cliffe Iron Co. 83/04/27, LINCHAN,J Uranium Recovery Licensing Branch, 29pp 18894-273
- 8306200036 Forwards 830519 ltr to N Freudenthal confirming 830511 meeting results re-water quality restaration Cooperation & input appreciated. 82006484. J.A. Oddrey & Bundahl. 83/05/23 LINSHAN.J. Uranium Recovery Field Office 5pp. 18908 357
- DOCKET 40-8722 BRUSH WELLMAN, INC., CLEVELAND, OH
- 8306:30243 "NRG Rept for Effluent Monitoring of Stack Emissions,"
 Jul-Dec 1982 Stacks need not be monitored in future because
 baseline data now achieved.per license suppl W/830222 ltr.
 ATHOOD.M D Brush Wellman, Inc 83/02/22 Region 4. Office of
 Director Sipp 18826.329
- 8306080119 Discusses IE insp of License SUA-1354 on 830131-0201 & forwards notice of violation BROWN 9 D Region 4. Defice of Director 83/03/01 VALIQUETTE, J. Brush Wellman. Inc 2pp. 18773.044
- --8306080124 Notice of violation from insp on 830131-0201 Noncompliance noted semiannual repts for First Quarters 1981 & 82 failed to identify pronounced increase in measured RN-222 levels at two offsite locations.

 * Region 4. Office of Director 83/03/01 2pp 18773 046.

- DOCKET 40-8728 TETON EXPLORATION DRILLING CO , INC , CASPER, WY
- 8306220126 Forwards P Pucel & C McCarty review of Teton Exploration Co M-zone restoration-stability repts Rept supercedes 830511 rough draft FREUDENTHAL.N Wyoming, State of 83/05/16 SMITH.R.D Uranium Recovery Licensing Branch 14pp 18977 137

DOCKET 40-8745 DOLE PETROLEUM, INC., CASPER, WY

8306130367 Presents info required in semiannual ALARA audit per License 8VA-1396. Condition 17 Region IV licenses rept

Exclusion encl BROWN, K J Ogle Petroleum, Inc 83/02/15 Director 4pp 18822 320.

DOCKET 40-8768 KERR-MCGEE NUCLEAR CORP , OKLAHOMA CITY, DK

8306240444 Forwards evaluation of Kerr-McGee O aand in situ project R&D testing license application Application not acceptable.
Permit rev requested
FREUDENTHAL.N Hyoming, State of 83/05/26 SMITH,D NRC - No Detailed Affiliation Given 15pp 18997 238

8306220140 "G-Sand In Situ U Racovery R&D Project/Converse County, WY, "

First Quarter 1983, M/830531 ltr BHELLEY, W.J. Kerr-McGes Corp. 83/05/31 SMITH R.D. Uranium Recovery Licensing Branch. 53pp. 18977-044

DOCKET 40-8783 URANERZ USA, INC., CASPER, WY

8306210353 "First Quarterly Rept, Jan-Mar 1983" Withree oversize drawings Aperture cards are available in PDR SOMERVILLE: K. G. Uranerz USA: Inc. 83/05/23 LINEHAN, J. J. Uranium Recovery Licensing Branch. 100pp 18936-275

DOCKET 40-8786 URANIUM RESOURCES, INC., RICHARDSON, TX

830.6210.451 Informs of decommissioning of North Platts R&D Facility.
Plant will be mothballed until commercial operations begin
Reverse osmosis unit to be returned to Aquatic Design Sys.

PELIZZA, M. S. Uranium Resources, Inc. 83. Cycle & Material Bafety 3pp. 18935-340 83/04/27 Division of Fuel

8306090028 Forwards Vol 2 to "North Platte Technical Rept, Restoration," including verification samples indicating return of groundwater to assentially baseline quality Final varification samples will be obtained in Aug. PELIZZA-M 8 Uranium Resources, Inc. 83/04/28. L Uranium Recovery Licensing Branch ip. 18798-025.

LINEHAN, J. J.

--8306090035 Vol 2 to "North Platte Technical Rept.Restoration" * Uranium Resources, Inc. 83/04/30. 152pp 18798.026

830,6020477 Accepts interim decommissioning plan for wellfield & process facility dtd 821014 Addl info needed includes location & depths of soil samples & means of stabilizing sand & sludge remaining in evaporation ponds.

LINEHAN, J. J. Uranium Recovery Field Office 83/04/29. Uranium Resources, Inc. 2pp. 18715-205.

830.6220130 Confirms telcon re decommissioning reverse osmosis Unit.
Alpha probe calibr acceptable Unit will be released as scheduled

scheduled PELLIZZA, M. S. Uranium Resources, Inc. 83/06/01. GARCIA; P. Uranium Resoury Field Offics. 1p. 18937.360

830.6210.425 Forwards Uranium Resources, Inc second semiennual ALARA audit of radiation safety program per License Condition 35.
Bicassay results within action levels in Table ; of Reg Guide B. 22
PELIZZA: M. S. Uranium Resources, Inc. 83/06/05, LINEHAN, J. J. Uranium Recovery Field Office. 5pp. 18937-033.

DOCKET 40-8794 MOLYCORP. , INC. , LOB ANGELES, CA

830.6020230 Application for amend to License SMB-1408, authorizing processing of 180,000 lbs yttrium-bearing ore currently located at York, PA & Louviers, CD facilities Process DOYLE, W. E. Molycorp, Inc. 83/04/2: Affiliation Given 4pp. 18700:347 83/04/22, 800NO, A. NRC - No Detailed

- 8306140442 Authorizes amend to Source Matl License SMS-1408 re processing of source matl for recovery of yttrium. PAGE,R O Uranium Fuel Licensing Branch 63/06/06 WARHOL,W.N Holycorp, Inc Ip 18854 066
- --8306140446 Discusses review of amend to Bource Matl License BMB-1408 authorizing processing of source matl for recovery of yttrium Amend should be issued BOONO.A. CR64H.H.T. Uranium Fuel Licensing Branch. 83/06/06 Uranium Fuel Licensing Branch. 2pp 18854.067

DOMESTIC LICENSING OF PRODUCTION AND UTILIZATION FACILITIES

DOCKET 50-2 UNIV OF MICHIGAN RESEARCH REACTOR

- G. Inspection reports, IE Bulletins & correspondence
- 8305270185 Forwards IE Insp Rept 50-002/83-02 on 830516-18. No noncompliance noted
 PAPERIELLO,C.J. Region 3. Office of Director, 83/06/10 KERN,W
 Michigan, Univ of 2pp 18791;332 24% Fiche.50-002,83/06/10.
 8306270185
- --8306270187 IE Insp Rept 50-002/83-02 on #30516-18 No noncompliance noted. Major areas inspected: radiation protection & radwaste programs, including qualifications, audits, training & radiation protection procedures ORANT, W B : OREOER, L. R Region 3; Office of Director. 83/06/10. 7pp. 18971.334. 24% Fiche: 50-002.83/06/10.8306270185

DOCKET 50-3 INDIAN POINT STATION, UNIT 1

- G Inspection reports, IE Bulletins & correspondence
- 8305110458 IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in Hell Logging Device" Svc list encl.
 TAYLOR.J.M Division of Safeguards & Inspection Programs (Post 830103) 83/08/26. Consolidated Edison Co of New York, Inc. 125pp 18831:043 24x Fiche:50-000.83/05/26.8305110458.
- 8305110460 IE Info Notice 83-34, "Event Notification Info Workshoet." Buc list encl.
 JORDAN, E.L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/05/26 Consolidated Eddson Co. of New
 York, Inc. 115pp. 18732-085, 24X Fiche: 50-000, 83/05/26, 8305110460
- 8305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods Withdrawn at BHRs." Svc list encl.
 JORDAN, E. L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/05/31, Consolidated Edison Co. 18732-208. RAX Fiche: 80-000, 83/05/31, 8305110461
- B305110464 IE Info Notice B3-36, *Impact of Security Practices on Safe Operations." Byo list and JORDAN E.L. Division of Emergency Preparedness & Engineering Response (Post 803103). B3706/09. Consolidated Edison Co. of New York, Inc. 119pp 18830.280. 24X Ficha-30-000.83/06/09.B305110464.
- 8305110470 IE Info Notice 83-38, "Defective Heat Sink Adhesive & Seismically Induced Chatter in Relays Within Printed Circuit Cands," Syc list encl.
 JURDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co. of New York, Inc. 118pp. 18920:225 24X Fiche, 50-000, 83/06/13, 8305110470.
- 830A090010 IE Info Notice 83-37, "Transformer Failure Resulting From Degraded Internal Connection Cables." Syc list encl JDRDAN.E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13. Consolidated Edison Co. of New York. Inc. 243pp. 18921:001. 24X Fiche: 50-000.83/06/13.8306090010
- B305110475 IE Info Notice B3-40, "Need to Environmentally Qualify Epoxy Grouts & Sealars." Svc list encl. JORDAN E.L. Division of Emergency Preparadness & Engineering Response (Post B30103). B3/06/22. Consolidated Edison Go. of New York, Inc. 115pp. 19021:179. 24X Fichs.50-000.83/06/22.8305110475
- 8305110477 IE Info Notice 83-41, "Actuation of Fire Suppression Sys Causing Inoperability of Safety-Related Equipment." Syc list enci. JORDAN, E. L. Division of Emergency Preparedness & Enginesting Response (Post 830103). 83/06/22. Consolidated Edison Co. of New York, Inc. 120pp 18997:007 24% Fiche: 80-000, 83/06/22,8305110477.
- 8305110479 IE Info Notice 83-42, "Reactor Hode Switch Malfunctions."

Byc list encl.

JDRDAN-E.L. Division of Emergency Preparadness & Engineering
Response (Post 830103). 83/06/23. Consolidated Edison Co. of New
York, Inc. 116pp. 18996; 242. 24% Fiche: 50-000, 83/06/23, 8305110479.

- 8305110483 IE Info Notice 83-43, "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints." Svc list encl JORDAN E L Division of Emergency Preparedness & Engineering Response (Post 830103). 83/06/24 Consolidated Edison Co of New York Inc. 116pp. 19046 297 24X Fiche 50-000.83/06/24,8305110483
- R Pariodic operating reports & related correspondence
- 8306270171 Forwards revised pages to samiannus1 effluent & waste disposal repts for Jan-June 1982 & Jul-Dec 1982, re "Radiological Impact on Man" sections O'TOOLE, J D Consolidated Edison Co of New York, Inc. 83/06/16 ALLAN, J N Region 1. Office of Director Ip 18991 358 24X Fiche 50-003.83/06/16.8306270171.
- --8308270179 Revised pages to semiannual effluent & waste disposal rept.
 Jan-June 1982
 Consolidated Edison Co. of New York, Inc. 83/06/16 3pp.
 18991 359 24X Fiche 50-003.83/06/16.8306270171
- --8305270184 Revised pages for semiannual effluent & waste disposal rept. Jul-Dec 1982
 Consolidated Edison Co. of New York. Inc. 83/06/16 3pp. 18991 362 24% Fichs 50-003.83/06/16.8305270171
- DOCKET 50-5 PENNSYLVANIA STATE UNIV RESEARCH REACTOR

 P Operating license stage documents & correspondence
- 8306240157 Application for amend to License R-2; modifying 821018 amend request to eliminate use of non-TRIGA fuel elements All other conditions unchanged CURRINGHAM, R O Pennsylvania State Univ 83/05/23 THOMAS, C Standardisation & Special Projects Branch 2pp 18981:039 24X Fiche 50-005,83/05/23,8305240157
- V. Operator Examinations
- 8306/40467 Estends invitation to attend 830627 meeting in King of Prussia, PA to discuss transfer of reactor operator licensing function from Bethesda. MD to Region I of: 81AA08TECKI.R Division of Project & Resident Programs 83/06/09, CUNNINGHAM, R O Pennsylvania State Univ. 2pp. 18834 318. 24X Fiche 50-005, 83/06/09, 8306140467
- DOCKET 50-6 BATTELLE HEMORIAL INST. RESEARCH REACTOR
- G Inspection reports. IE Bulletins & correspondence
- 8308230127 Responds to FDIA request for five categories of documents respont fuel at facilities App A & B documents respond to Items 1.2.4 & 5 forwards App B Documents 1 & 5-11. No documents located for Item 3 FELTON J M. Division of Rules and Records 83/04/13 AUDIN.L. Affiliation Unknown 3pp 18982.047 24X Fiche: 50-014.83/04/13.8308230129
- DOCKET 50-8 NORTH CAROLINA STATE UNIV. RESEARCH REACTOR
- J Insurance k indeanity information
- 830A220286 Unesecuted Amend 17 to Indemnity Agreement E-7, revising attachment, Item 2.

 BALTIMAN, J Assistant Director for State 2 Licensee Relations 83/06/14 13 18940 350 24X Fiche: 50-008, 83/06/14, 8306220286
- DOCKET 50-10 DREBDEN ARCLEAR POWER STATION, UNIT 1
- F. Security, medical, emergency & fire protection plans
- 8308210314 FOIA request for MRC records re security violations & safeguards symmes at nuclear facilities OCLDENSERO, O Scripps-Howard Newspapers, 83/04/22 FELTON, J H Office of Administration, 2pp 18925, 198 24X Fisher 50-000, 83/04/22, 8308210314.

- 8306210306 Partial response to FOIA request for NRC records re security violations & safeguards events at nuclear facilities Repts listed on App A evailable in FDR Bearch for addl documents subj to request continuing FELTON, J M Division of Rules and Records 83/05/16 GOLDENDERO, & Scripps-Howard Newspapers 2pp. 18925 196 24X Fiche 50-000,83/05/16,8306210306
- 8306090247 Confirms 830601 telcon re changes to exercise windows for Dresden & Byron Nuclear Power Stations Dresden partial exercise will be conducted during who f 830912 w/Dyron full-scale exercise beginning who 6 831144 JCNES, E E Illinois, State of 83/06/01 KEPPLER, J Region 3, Office of Director ANDERSON, J Federal Emergency Management Agency WAONER, O Commonwealth Edison Co ip 18795 319 24X Fiche 50-000,83/06/01,8306090247
- 8306210355 Releases public version of revised emergency plan implementing procedure FELTON.J M Division of Rules and Records, 83/05/05 Document Management Branch 1p 18935 293 24X Fiche 50-010,83/05/05, 8306210355
- --8306210357 Public version of Rev 1 to Emergency Plan Implementing Procedure EPIP 300-12. "Initiation of Environ Monitoring Activities by Rad/Chem Director "Receipt form encl. WE30516 itr SCOTT.D J Commonwealth Edison Co 83/05/11 DENTON, H R. Office of Nuclear Reactor Regulation. Director 19pp 18935 294 24X Fiche. 50-010. 83/06/06. 8306210355
- 8304100218 Responds to IE Insp Repts 50-010/83-01, 50-297/83-01 & 50-249/83-01 Corrective action surveillance notification program developed for annual distribution of public info brochures on exergency planning FARRAR. D L Commonwealth Edison Co. 83/06/07 PAPERIELLO, C J. Region 3, Office of Director. 4pp 18805-113 24X Fiche 50-010,83/06/07,8304100218
- 830&160214 Submits correction to 830&01 ltr Date of reassessment will be made prior to 830&01, not 831&01

 JONES, E E Illinois, State of 83/06/09 KEPPLER, J Region 3, Office of Director, ANDERSON, J Federal Emergency Management Agency WAGNER, G Commonwealth Edison Co. 1p. 18861 358 24X Ficher 50-000, 83/06/09, 830&160214
- J Insurance & indomnity information
- 8306140003 Forwards Endorsement 145 to NELIA Policy NF-43 & Endorsement 122 to MAELU Policy MF-36
 03TEN. J Commonwealth Edison Co 83/06/07 SALTZMAN, J Assistant Director for State & Licensee Relations 3pp 18938:216 24X
 Fiche: 50-010, 83/06/07, 8306140003
- 9 Inspection reports: IE Bullatine & correspondence
- 8305110458 IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in Well Logging Device" Svc list encl
 TAYLOR, J H Division of Safeguards & Inspection Programs (Post 830103), 83/05/26, Consolidated Edison Co of New York, Inc. 125pp. 18831-043 24% Fiche 50-000,83/05/26,8305110458,
- 8305110460 IE Info Notice 83-34, "Event Notification Info Worksheet."

 Byc list encl
 JORDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/05/26 Consolidated Edison Co. of New
 York, Inc. 115pp. 18732 085 24X Fiche 50-000,83/05/26,8305110460
- B305110461 IE Info Notice B3-35, "Fuel Movement W/Control Rods Withdrawn at BHRs " Svc list encl. JURDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) B3/05/31 Consolidated Edison Co. of New York, Inc. 116pp 18732 208 24X Fichs 50-000, B3/05/31, 8305110461.
- B30610021B Responds to IE Insp Repts 50-010/B3-01, 50-237/83-01 & 30-249/83-01 Carrective action surveillance notification program developed for annual distribution of public info brochures on emergency planning FARRAR, D. L. Commonwealth Edison Co. 83/06/07 PAPERIELLO, C. J. Region 3, Office of Director App 18805-113, 24X
- B305110464 IE Info Notice B3-36, "Impact of Security Practices on Bafe Operations " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) B3/06/07, Consolidated Edison Co of New York, Inc. 119pp 18830:280 24X Fiche 50-000, B3/06/07, B305110464

DOCKETED ITEMS

- 8305110470 IE Info Notice 83-38, "Defective Heat Sink Adhesive & Seismically Induced Chatter in Relays Within Printed Circuit Cards " Bvc list encl JURDAN, EL Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co of New York, Inc 118pp 18920 225 24% Fiche 50-000,83/06/13,8305110470
- 8306090010 IE Info Notice 83-37, "Transformer Failure Resulting From Degraded Internal Connection Cables" Svc list encl JURDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co. of New York, Inc. 243pp 18921 001 24X Fiche, 50-000, 83/06/13, 8306090010.
- 8305110475 IE Info Notice 83-40. "Need to Environmentally Qualify
 Epoxy Grouts & Sealers " Svc list encl
 JCRDAN,E L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/06/22 Consolidated Edison Co of New
 York, Inc 115pp 19021-179 24X Fiche, 50-000.83/06/22.8305110475.
- 8305110477 IE Info Notice 83-41, "Actuation of Fire Suppression Sys Causing Inoperability of Safety-Related Equipment " Svc list encl, JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/22 Consolidated Edison Co of New York, Inc. 120pp 18977 007 24X Fiche 50-000.83/06/22.8305110477
- 8305110479 IE Info Notice 83-42. "Reactor Mode Switch Malfunctions "
 Svc list encl
 JORDAN: E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/04/23 Consolidated Edison Co of New
 York, Inc 114pp 18976,242, 24X Fiche 50-000:83/04/23.8305110479
- 8305110483 IE Info Notice 83-43, "Improper Bettings of Intermediate Range (IR) High Flux Trip Setpoints," Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/24 Consolidated Edison Co of New York, Inc 116pp 19046-297, 24X Fichs, 50-000, 83/06/24, 8305110483.
- R Periodic operating reports & related correspondence
- 8306130275 "Semiannual Rept of Radioactive Effluents 1982." W/830302 ltr. SCOTT,D J Commonwealth Edison Co. 83/03/02 KEFPLER,J & Region 3. Office of Director 20pp, 18823.277. 24X Fiche.50-010,83/03/02, 8306130275
- 8306130454 Forwards corrected "1981 Rept of Occupational Personnel Radiation Doses Contract Workers," per Reg Guide 1, 16
 Number of people per mannem should be listed in maint not engineering category WAGNER, 9, P. Commonwealth Edison Co., 83/06/07, KEPPLER, J. 0 Region 3, Office of Director, 1p. 18921:179, 24X Fiche: 50-010,83/06/07, 8304130454
- ---8306130457 Forwards corrected "1981 Rept of Occupational Personnel Radiation Doses Contract Horkers," per Reg Quide 1 id.

 Number of people per mannem should be listed in maint not engineering category

 HAQNER, O. P. Commonwealth Edison Co. 83/06/06 KEPPLER, J. Q. Region 3, Office of Director. 1p 18821:180 24X

 Ficher 50-010, 83/06/07, 8306130454.
- --8306130460 Corrected "1981 Rept of Occupational Personnel Radiation Doses Contract Workers "

 ** Commonwealth Edison Co. 83/06/06 9pp 188R1:181. 24X Fiche: 80-010.83/06/07.8306130454.
- 8 Reportable occurrences, LERs & related correspondence
- 8306270282 Potential Part Ri rept re discrepancy in welding of turnbuckle assembly, turnbuckle-bult interface & on top plate assembly variable springs. 8,8007 Grade B bults not ABME Section IX matl Investigation underway. KARADIANIS, J. A. Elcen Matal Products Co. 83/06/17. KEPPLER, J. O. Region J. Office of Director 2pp. 18996:207. 24X Fiche 50-000,83/06/17,8306270282.
- DOCKET 50-14 BATTELLE MEMORIAL INST. CRITICAL FACILITY
 P. Operating license stage documents & correspondence
- 8306230123 FDIA request for five categories of documents re spent fuel at facilities AUDIN,L. Affiliation Unknown. 83/03/05. Diffice of Administration. 2pp 18982:045 24X Fichs: 50-014,83/03/05,8306230123

- 8306230129 Responds to FOIA request for five categories of documents respent fuel at facilities. App A & E documents respond to Items 1.2.4 & 5 Forwards App B Documents 1 & 5-11. No documents located for Item 3.

 FELTON, J M Division of Rules and Records 83/04/13. AUDIN, L Affiliation Unknown 3pp 18982 047. 24X Fiche. 80-014.83/04/13, 8306290129
- DOCKET 50-16 ENRICO FERMI ATOMIC POWER PLANT, UNIT 1
- J Insurance & indomnity information
- 8306090022 Unexecuted Amend 25 to Indomnity Agreement 8-20, delating Items 3 & 4 re license numbers & location, respectively.

 GALTZMAN, J Assistant Director for State & Licensee Relations.

 G3/05/31 1p. 18797 361 24X Fiche 50-016/03/05/31/8306090022.
- 8306090037 Unexecuted Amend 24 to Indemnity Agreement 8-20.adding Wolverine Power Supply Cooperative as licenses.

 8ALTZMAN.J. Assistant Director for State & Licenses Relations.
 83/05/31 p. 18777.360 24% Fichs.50-016.83/05/31.8306090039.
- DOCKET 50-20 MASSACHUSETTS INST OF TECH RES REACTOR
 V Operator Examinations
- 8306140531 Extends invitation to attend 830627 meeting in King of Prussia-PA to discuss transfer of reactor operator licensing function from Bethasde-MD to Region I ofc STAROSTECKI, R. Division of Project & Resident Programs 83/06/09. CLARK, L. Massachusetts Institute of Technology. 2pp. 18834:320. 24X Fiche. 50-020. 83/06/09. 8306140531.
- DOCKET 50-27 HABHINGTON STATE UNIV REBEARCH REACTOR

 F Sacurity, medical, emergency & fire protection plans
- 8306200154 Requests add1 info within 30 days re review of 821027 MA Bits Univ reactor swargency plan. Plan reviewed against App E to 10CFRBO, Rev 1 to Reg Guide 2, 6 & ANSI/ANS 15.16-1982. THOMAS. C.O. Standardization & Special Projects Branch. 83/06/10. WILBON, N.E. Hashington State Univ. 1p. 19046-132, 24X Fiche: 50-027.83/06/10.8306200154.
- --8306290018 "Emergency Plan Review,"

 * Division of Emergency Preparedness & Engineering Response (Post 830103). 83/05/31, 3pp. 19046.134. 24X Fiche: 30-027,83/06/10,830620154
- 8306200151 Ack receipt of B30610 ltr requesting add1 info re Uct 1982 MA State Univ reactor emergency plan. Submittel of requested info within 30 days impossible due to previous commitments Extension of submittel for 70 days requested WILBON, W.E. Hashington Blate Univ. 83/06/14. THOMAS. C.O. Standardization & Special Projects Branch. 1p. 18703:118 24X Fiche: 30-027,83/06/14.8306200151.
- --8306200154 Requests add1 info within 30 days re review of 821027 MA State Univ reactor emergency plan Plan reviewed against App E to 10CFR30,Rev 1 to Reg Quide 2 6 & ANSI/ANB 15, 16-1982. THOMAS, C. O Standardization & Special Projects Branch. 83/06/10 WILBON,M.E. Washington State Univ. 1p. 19046:132 24X Fiche: 50-027,83/06/14,8306200151.
- DOCKET 50-29 YANKEE-ROHE NUCLEAR POHER STATION
- F. Security, medical, emergency & fire protection plans
- B306010096 Forwards IE Insp Rept 50-029/B3-08 on B30503-04. No noncompliance noted.

 MARTIN T T. Division of Engineering & Technical Programs. B3/Q5/17.

 HEIDER L. H. Yankse Atomic Electric Co. 2pp. 18674:103. 24X

 Fiche 50-029,83/05/17.8306010096.
- --B306010100 IE Insp Rept 50-029/83-08 on B30503-04.No noncompliance noted Hajor areas inspected: prompt public notification sys. COHEN.I., GURDON,C., GROCKER.H.W. Region i Office of Director, 83/05/i6. 6pp. 18674:105. 24X Fiche: 30-029,83/05/17,8306010096.
- 8304090289 Releases public version of change to emergency plan. FELTON.J.M. Division of Rules and Records. 83/06/01, Document Management Branch. 1p. 18810:015. 24X Fiche: 50-029,83/06/01,8306090289.

--8306070291 Public version of Change 4 to emergency plan, consisting of agreement itr between licensee & States of VT & MA & Rev 4 to App H re public notification sys, Receipt form ancl. MARKT.D Yankes Atomic Flectric Co 83/05/18, 10pp, 18810:016 24X Fiche: 50-029, 83/06/01, 8306070289

J Insurance & indemnity information

- 8306150253 Forwards exemption approving 820628 request for relief from 10CFR50, 54(w) property insurance requirement CAUTCHFIELD.D. Operating Reactors Branch 5. 83/06/10 KAY, J. A Yankee Abomic Electric Co. 2pp. 18649-196
- --8306180257 Exemption from requirements of 10CFR50, 54(w) re excess property insurance supplied by Nuclear Electric Insurance Limited: EEI American Nuclear Insurers & Mutual Atomic Energy Reinsurance Pool, PURPLE, R. A. Division of Licensing 83/06/10 Yanker Atomic Electric Co. 5pp. 18849:198. 24X Fiche 50-029,83/06/10,8306180283.
- 8306230283 Forwards Endorsement 105 to NELIA Policy NF-76 & Endorsement 37 to MAELU Policy MF-26.
 SINIBI.J.M Marsh & McLonnan, Inc. 83/06/16 BALTZMAN.J.D.
 Assistant Director for State & Licensee Relations. 3pp. 18745/155
 24X Fiche.50-029,83/06/16.8306230283.

P Operating license stage documents & correspondence

- 8306170398 Submits addl info re capability of proposed integrated system plant cooldown. Results of preliminary analysis indicate cooldown could be accomplished within 150 h. Requests approval be granted prior to 830701.

 KAY. J. A. Yankee Atomic Electric Co. 83/06/09 CRUTCHFIELD, D. Operating Reactors Stranch S. ip. 18879:316 24X

 Fiche: 50-029, 83/06/09, 8306170398.
- 830.6210017 Forwards Cycle XVI "Yankes Nuclear Power Btation Haim Steam Line Break Analysis." Review & approve) requested by 831001. KAY, J. A. Yankes Atomic Electric Co. 83706/10. CRUTCHFIELD, D. Operating Reactors Branch 5 2p. 18918.140. 24X Fiche: 50-029, 83706/10, 8306210017.
- ---8306210024 "Yankee Nuclear Power Station Hein Steam Line Break Analysis " FUJITA:N., KENDALL.J.N., GUIMOND,P.J Yankee Atomic Electric Co. YAEC-1361 83/05/31. 114pp. 18918.142. 24X Fiche:50-029,83/06/10,8306210017.
- 8306200326 Notification of 830622 meeting w/util in Bethesde, MD to discuss seismic analysis for design of spent fuel pool racks, Agenda ancl. LYONS, J.E. Operating Reactors Branch 5 83/06/17. CRUYCHFIFLD, D. Operating Reactors Branch 5 4pp 18700; 360. 24X Ficher 50-029, 83/06/17, 8306300326.
- 8306290311 Forwards final seismic input for SEP Topic III-6: "Seismic Design Considerations." NUREQ-0825 conclusions valid based on conservative structural analysis methods & linear elastic analysis.

 CRUTCHFIELD.D. Operating Reactors Branch 5. 83/06/22. KAY, J, A Yankee Atomic Electric Co. 35pp. 19055, 316. 24X Fiche: 50-029, 83/06/22. 8306290311.
- 8306290241 Forwards eafsty evaluation conditionally approving licenses 830310 request from relief from Generic Ltr 82-28 & NUREQ-0737. Item II.F. 2 requirements to install reactor vessel level sys Addi info needed within 30 days. CRUTCHFIELD.D. Operating Reactors Branch 5. 83/06/27. KAY. J. A. Yankse Atomic Electric Co. 11pp. 19056.247. 24X Fiche: 50-029.83/06/27.8306290241.

G. Inspection reports, IE Bulletins & correspondence

- R3060R0337 Advises that IE Bulletin 83-03, required actions inapplicable Emergency diseas generators do not use rewwater for cooling nor does cooling ass contain check valves Nater treated w/anti-freeze. Generators air cooled. HEIDER: L. M. Yantes Atomic Electric Co. B3/05/16. ALLAN, J. M. Region 1, Office of Director. 1p. 18694. R87. R4X Fichs. 50-029, 83/05/16. 8306020337.
- 830&01007& Forwards IE Insp Rept 50-027/83-08 on 830503-04.No noncompliance noted.

 HARTIN: T. Division of Engineering & Technical Programs. 83/05/17
 HEIDER.L.H. Yantee Atomic Electric Co. 2pp. 18674:103 24X
 Fichs: 50-029

- --8306010100 IE Insp Rept 50-029/83-08 on 830503-04 No noncompliance noted Major areas inspected, prompt public notification sys COHEN.1., GORDON C . CROCKER: H W Region 1. Office of Director B3/05/16 6pp 18674 105. 24X Fiche 50-029,83/05/17,8306010096
- 8306070302 Responds to IE Bulletin B3-04, "Failure of Undervoltage Trip Function of Reactor Trip Breakers," per NRC 830511 request Burveillance test performed for each plant startup in accordance w/approved procedure HEIDER, L. H. Yankes Atomic Electric Co. 83/05/24 ALLAN, J. M. Region I. Office of Director 2pp. 18740 303 24X Fiche 50-029,83/05/24,8306070302
- 8306010160 Act receipt of B20512 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-029/83-07
 MARTINATT Division of Engineering & Technical Programs 83/05/25
 HEIDERAL H Yankee Atomic Electric Co 2pp. 18673 039 24K
 Fichs 50-029,83/05/25,8306010160
- --8306010165 Responds to NRC 830413 ltr re violations noted in IE Insp. Rept 50-029/83-07 Corrective actions areas cleaned prior to placerd placement, tape placed over corners & two addl steel restraining bands placed on drum tops. HEIDERL H. Yankes Atomic Electric Co. 83/05/12 ALLAN, J.M. Region 1. Office of Director 5pp. 18673.041 24X Fiche 50-029,83/05/25,8306010160
- 8305110458 IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in Hell Logging Device" Evc list enci TAYLOR J M Division of Safeguards & Inspection Programs (Post 830103), 83/05/26 Consolidated Edison Co of New York, Inc 125pp 18831 043, 24X Fiche 50-000,83/05/26,8305110458
- 8303110460 IE Info Notice 83-34, "Event Notification Info Worksheet"
 8vc list encl
 JDRDAN.E L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/05/26 Consolidated Edison Co of New
 York, Inc. 115pp. 18732 085 24X Fiche 50-000,83/05/26,8305110460
- 8308110441 IE Info Notice B3-35. "Fuel Movement W/Control Rods Withdrawn at BURs." Svc list ancl JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post B30103) B3/05/31 Consolidated Edison Co of New York. Inc 116pp 18732 208. 24X Fiche 50-000,83/05/31,8305110441
- B30&140067 Proposes visual exam of four inlet nozzles, respective inner radii & safe-ends & Ultrasonic exam of four outlet nozzles, respective inner radii & safe-ends, per reactor vessel insp program.

 KAY, J.A Yankee Atomic Electric Co 83/06/06 CRUTCHFIELD, D. Operating Reactors Brench 5 3pp 18838 264. 24X Fiche: 50-029, 83/06/06. 830&140067.
- 8305110464 IE Info Notice 83-96. "Impact of Security Practices on Bafe Operations." Byo list encl.

 JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/09. Consolidated Edison Co. of New York, Inc. 119pp 18830-280 24X Fiche. 50-000, 83/06/09, 8305110464
- 8305110470 IE Info Notice 83-38. "Defective Heat Bink Adhesivs & Beismically Induced Chatter in Relays Within Printed Circuit Cards." Svc list encl JURDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co. of New York, Inc. 118pp 18920-225 24X Fiche, 50-000, 83/06/13, 8305110470
- 8306090010 IE Info Notice 83-37. "Transformer Failure Resulting From Degraded Internal Connection Cables." Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103), 83/06/13 Consolidated Edison Co. of New York, Inc. 243pp 18921-001 E4X Fiche 50-000,83/06/13,8306090010.
- 8306200361 Ack receipt of 830301 & 0429 ltrs informing NRC of steps taken to correct violations noted in IE Insp Rept 50-029/82-15 Corrective actions re Items A 1 & B adequate Contention that no violation exists re Item A 2 disputed STAROSTECKI,R. Division of Project & Resident Programs 83/06/14, HEIDER,L N Yankee Atomic Electric Co 2pp 18901.032 24% Fiche, 50-029, 83/06/14, 8306200361
- --8306200365 Supple 830301 response to NRC 830124 ltr re violations noted in IE Insp Rept 50-029/82-15 Corrective actions safety class drawing issued showing in-core instrumentation flux thimble paths & defining safety class boundaries HEIDER.L.H Yankee Atomic Electric Co 83/04/29 ALLAN, J. M Region 1, Office of Director 4pp 18701 034. 24X Fiche 50-029.83/06/14,8306200361

- --8306200369 Responds to NRC B30124 ltr re violations noted in IE Insp Rapt 30-029/82-15 Corrective actions personnel reinstructed re evaluation of design change & NRC operations ctr notified of gassous radioactive release Item A 2 disputed HEIDER.L H Vankes Atomic Electric Co 83/03/01. HAYNES, R C Region 1, Office of Director 3pp 18901 038, 24X Fiche 50-029,83/06/14,8306200361
- B3D5110475 IE Info Notice B3-40. "Need to Environmentally Qualify
 Epoxy Grouts & Sealers " Svc list enc!
 JORDAN, EL Division of Emergency Preparedness & Engineering
 Response (Post 830103) B3/06/22 Consolidated Edison Co of New
 York, Inc 115pp 19021 179 24X Fiche, 50-000, B3/06/22, B305110475
- G305ii0477 IE Info Notice B3-41, "Actuation of Fire Suppression Bys Causing Inoperability of Safety-Related Equipment," Svc list ent!

 JORDAN,E i Division of Emergency Preparedness & Engineering Response (Post B30103) 83/06/22 Consolidated Edison Co of New York, Inc 120pp. 18997.007 24X Fiche. 50-000. B3/06/22,8305110477.
- 8305110479 IE Info Notice 83-42, "Reactor Mode Switch Malfunctions "
 Svc list encl
 JORDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/06/23, Consolidated Edison Co of New
 York, Inc 116pp. 18996, 242, 24X Fiche. 50-000, 83/06/23, 8305110479
- 8308110483 IE Info Notice 83-43, "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints " Svc list encl. JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/24, Consolidated Edison Co. of New York, Inc. 116pp. 19046:297. 24X Fiche. 50-000. 83/06/24. 8305110483.

R Periodic operating reports & related correspondence

- 830.6020137 Monthly operating rept for Mar 1983.W/830406 ltr. BATTERSON.8 , HEIDER, L. H. Yankee Atomic Electric Co. 83/04/06 Office of Resource Management, Director 6pp. 18691 238 24X Fiche: 50-029, 83/04/06.8308020139.
- 8304:60382 Monthly operating rapt for Apr 1983 W/830512 ltr 8ATTERSON,8 , HEIDER.L.H. Yankee Atomic Electric Co 83/05/12 App 18840 117. 24X Fiche 50-029.83/05/12.8304140382.

8 Reportable occurrences, LERs & related correspondence

- 8306280144 LER 83-017/03L-0. on 830816. Masoneilan containment isolation valve TV-CI-401B isolated & disassembled to repair gasket leak Caused by failure of bottom flangs gasket, Gasket replaced & sus returned to svc. M/830615 ltr FRENCH. L. D. AUTIO, H. A. Yankee Atomic Electric Co 83/05/16. ALLAN. J. M. Region i. 0ffice of Director 2pp. 19018 185. 24X Fiche 50-029, 83/05/16, 8306280144.
- 8306170033 LER 83-014/03L-0: on 830429, while performing functional test of control room ventilation fire dampers following mod to fire detection systone damper failed to close. Caused by failure of heating element W/830527 ltr.
 MAY.E L. AUTIO.H.A. Vanke Atomic Electric Co. 83/05/27.
 ALLAN.J H. Region i. 0ffice of Director. 2pp. 18882: 227. 24X Fiche. 50-029, 83/05/27, 8306170033.
- 8306170418 LER 83-015/03L-0: on 830506 during Mode 1 operation, Y177, 115-kV line opened for routine maint, contrary to Tech Specs 3 8 1.1 a Caused by scheduled maint insp of 115-kV transformers. No corrective action necessary, M/830603 ltr. RICE.D A , AUTIO, H. A Yankee Atomic Electric Co. 83/06/03. ALLAN, J H. Region 1, 0ffice of Director. 2pp. 18879: 007. 24X Fichs. 50-029, 83/06/03, 8306170418.
- 8306170339 LER 83-016/03L-0. on 830511, containment isolation valve TV-CI-4018 & steam generator 2 blowdown monitor isolated to repair gasket leak. Caused by bottom flange gasket failure Gasket replaced W/830610 ltr.
 FRENCH. L. D. , AUTIO, H. H. Yankee Atomic Electric Co. 83/06/10, ALLAN, J.M. Region 1, Diffice of Director, 2pp. 18880-284, 24X Ficher 50-029, 83/06/10, 8306170339.
- 8306280107 Updated LER 82-041/03L-1:on 821116.loop i channel initiation setpoint found outside Tech Spec limit Caused by main control board indicator drift. Indicator replaced & channel recalibr Procedure to be revised w/830614 ltr.
 MAY.E.L., AUTIO.H A. Yankse Atomic Electric Co. 83/06/14.
 ALLAN.J.M. Region i. Office of Director. 2pp. 19018:182. 24X
 Fiche 50-029.83/06/14.8306280107.

V Operator Examinations

8306140523 Extends invitation to attend 830627 meeting in King of Prussia.PA to discuss transfer of reactor operator licensing function from Bethesda.MD to Region I ofc STARQSTECKI,R Division of Project & Resident Programs. 83/06/09. HEIDER,L H Vankes Atomic Electric Co 2pp. 18838-122. 24X Fiche 50-029,83/06/09.8306140523

DOCKET 50-54 UNION CARBIDE RESEARCH REACTOR

P Operating license stage documents & correspondence

8304070364 Advises that fuel element cladding allow changed to comply w/Tech Specs, requiring high purity aluminum cladding. B&M contracted to fabricate new fuel element. RVZICKA.M.O. Union Carbids Corp. 83/06/02 THOMAS.C. G. Standardization & Special Projects Branch 1p. 18795: 067. 24X Fiche: 50-054, 83/06/02. 8306070364.

V. Operator Examinations

8306140651 Extends invitation to attend B30627 meeting in King of Prussia, PA to discuss transfer of reactor operator licensing function from Bethesda, MD to Region I of: STAROSTECKI, R Division of Project & Resident Programs. 83/06/09. MCGOVERN.J.J. Union Carbide Corp. 2pp 18842:082 24X Fiche: 50-054,83/06/09,8306140651.

DOCKET 50-57 STATE UNIV. OF NEW YORK RESEARCH REACTOR

E. NRC Safety Evaluation Report (SER), supple & correspondence

8306210317 SAFETY EVALUATION REPORT RELATED TO REMEMAL OF THE OPERATING LICENSE FOR THE RESEARCH REACTOR AT THE STATE UNIVERSITY OF NEW YORK AT SUFFALD. Docket No. 50-57.

* Division of Licensing NURES-0982. 83/05/31. 88pp. Available at NRG 44 50 18924:282. 24% Fiche:50-087.83/05/31.8306210317.

G. Inspection reports, IE Bulletins & correspondence

- 8306170050 Ack receipt of 830511 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-057/82-01 & 70-0247/82-01 MRTIN, T.T. Division of Engineering & Technical Programs. 83/06/0 HENRY, L. 9. New York, State Univ. of, Buffelo. 2pp. 18802:210 24X Fichs:50-057,83/06/01,8306170050.
- --8306170052 Responds to NRC 830427 ltr re violations noted in IE Insp Repts 50-057/82-01 & 70-0267/82-01. Corrective actions: new reactor engineer added to assume responsibility for accountability actions & records. Fuel burnup code andified, HERRY.L. 0 New York, Bitate Univ. of, Buffalo. 83/05/11. HARTIN.T.T. Division of Engineering & Technical Programs. 1p. 18882 212 24X fiche: 50-057,83/06/01,8306170050.
- 8306140741 Ack receipt of 830510 ltr informing NRC of steps taken to correct violations noted in IE Insp Rapt 50-057/83-01. Mgt controls to improve nuclear safety committee performance noted.

 8TARCHTECKI,R. Division of Project & Resident Progrems. 83/06/03, HENRY,L. Q. New York. State Univ. of, Buffelo. ip. 18841:159, 24X Fiche: 50-057.83/06/03,8306140741.

V. Operator Examinations

8306140351 Extends invitation to attend 830627 meeting at Ming of Prussis:PA to discuss transfer of reactor operator licensing function from Bathesda,MD to Region I ofc.
8TAROSTECKI.R. Region i Office of Director. 83/06/09. HENRY,L.O. New York, State Univ. of, Buffalo 2pp. 18841;163 24X Fiche: 50-057,83/06/09.8306140351.

DOCKET 50-42 UNIV. OF VIRGINIA REBEARCH REACTOR

F Security, medical, emergency & fire protection plans

8304220228 Forwards request for add1 info re Univ of VA research reactor 820827 emergency plan to continue review per 10CFR80. App E. Reg Quide 2 & Rev 1 & ANBI/ANB-15, 15-1982 requirements. Info requested within 30 days of 1tr date, THOMAS.C. 0 Stendardization & Special Projects Branch. 82/06/10. BRENIZER.U.8. Virginia. Univ. of, Charlottssville, VA. 18977:355. 24% Fiche. 50-062,83/06/10.8306220228.

O Reportable occurrences, LERs & related correspondence

8306140005 RD, on 830530, reactor shot down when shutdown margin during criticality violated Tech Spers Caused by difference in partial fuel element added on 830526 Reactor shut down 830506 Control rods resultar Procedures changed RENIZER, J 8 Virginia, Univ. of, Charlotteaville, VA 83/06/09 0'REILLY, J P. Region 2, Office of Director, 2pp 18838 242 24X Fiche 50-062,83/06/09.8306140005

DOCKET 50-70 GENERAL ELECTRIC TEST REACTOR

Adjudicatory correspondence

8306060287 Order extending time until 830703 for Commission to act to review ALAB-720. Commissioners. 1p 18730.017. 24X Fiche: 50-070.83/06/02. 8304040287.

8 Reportable occurrences, LERs & related correspondence

B306160470 Part 21 rept re broten spring-steel bands on 60 amp fuse clips. ILBCC Corp requested to determine cause of breakage. OE metallurgically testing broten bands.

DMYER.P W. General Elsetric Co B3/05/10. DEYGONO, R C Director's Office. Gffice of Inspection and Enforcement 7pp 16862: 252. 24X

Fiche: 50-070.83/05/10.8306160470

DOCKEY 50-72 UNIV OF UTAH RESEARCH REACTOR

F Security, medical, emergency & fire protection plans

B306160189 Releases public version of emergency plan.
FELTON, J. H. Division of Rules and Records 83/06/06. Document Branch, 1p. 18893-095, 24X Fiche 50-072,83/06/06, Document

--8305160194 Public version of "Emergency Plan for Training & Research Reactors " M/830512 ltr. SANDQUIET.0 M. BROPHY.0 J. Utah, Univ of UTEC ME 82-100 82/11/01. Office of Nuclear Reactor Regulation, Director R/pp 18893:096 24X Fiche.50-072.63/06/06.6306160189

Q. Inspection reports. IE Bulletins & correspondence

8306140226 Forwards IE losp Rept 50-072/03-01 on 830421-22 & notice of violetion.
BEIDLE, H. C. Region 4. Office of Director 83/05/11. JACOBS
Utah, Univ of 2pp 18632, 280 R4x Ficher 50-078, 83/05/11. JACOBB.H R. 8306140226

-8306140236 IE Insp Rept 50-072/83-01 on 830421-22 Moncompliance noted failure to perform required reactor startup surveillance Testing to perform requires reactor scartop surveillence tests.
MURPHY, M E , JCHNSON, H D Region 4, Office of Director. 83/05/11. 5pp. 18832 291. 24X Fiche: 50-072, 83/05/11, 8304140226.

DOCKET 50-77 CATHOLIC UNIV. OF AMERICA REDEARCH REACTOR

G. Inspection reports. JE Bulletins & correspondence

8306200343 Forwards IE Insp Rept 50-077/83-02 on 830511-13 & notice of Violation. STAROSTECKI.R STAROBIECHI, R Division of Project & Resident Programs 83 STAROBIECHI, R Division of America: Machington, DC 2pp. 18900, 264, 24% Fiche 50-077, 83/06/06, 8306200343 83/06/06.

--B306200347 Notice of violation from insp on 930511-13.

* Region 1, Office of Director B3/06/06. 1p. 18900: 266 g4x
Fichs 50-077.83/06/06.8306200343.

--8306200353 IE Inap Rept 30-077/83-02 on 83051i-13. Noncompliance noted: failure of reactor safety committee to meet at least twice sach yr in CVSI & CVS2 Committee to meet at least twice KINNEY, W M. Region in Office of Director. 83/06/02 7pp 18900:067. 24X Fiche: 50-077.83/06/06.8306200343.

8306280347 Ack receipt of 830613 ltr infurming NRC of steps taken to correct violations noted in IF Insp Rept 50-77/83-02 BTAROSITICAL R Division of Project & Resident Programs RELNWOFER W Catholic Univ of America, Washington, BC 17001 267 24% Fichs 50-07/,03/06/23 B306280347

--8308200351 Responds to NRC 8 10806 itr re violations noted in IE Insp.
Rept 50-077/D3-02 Corrective actions reactor safety
committee will meet at least twice each yr
JORDAN, E.D. Catholic Univ. of America, Hashington, DC 83/06/13
BTAROBICKI, R. Division of Project & Resident Programs 1p.
19001 288 24x Fichs 50-077, 83/06/23, 8308280347

V Operator Examinations

8306140443 Extends invitation to attend 830627 meeting in King of Prossis,PA to discuss transfer of reactor operator licensing function from Bethesds,HB to Region I ofc STARDSTECKI,R Bivision of Project & Resident Programs 87/06/HRANG,Y C Catholic Univ of America, Mashington, BC \$\text{Opp}\$ 18038 023 24X Fichs 50-077,83/06/09.8306140443

DOCKET SO OF DENERAL ATOMIC CO

F. Becurity, medical, emergency & fire protection plans

B306280171 Forwards IE Insp Repts 50-089/03 02 & 50-140/83 02 on 830509-1P & notice of violation Present level of resources allocated to radiation protection program inadequate Insp frequency will be increased BOOKHI C. Repion 5: Office of Director B3/05/27 PARKER, J & Technologies, Inc. / General Atomic Co. 2pp. 19014 136 24X Fichs 50-089:83/05/27.83062001/1 PARKER, J H . QA

--8306280105 IE Insp Repts 50 009/03 02 & 50-163/83 02 on B30509-12 Noncompliance noted failure to post notice of violation repradiological working conditions.per 1001819 11(e) YURAS-0 P. RENGLAHGKI.F A. BURK.H L. Repion 5. Office of B3/05/27 10pp 19014 139 24X Fichs 50-089,83/05/27,

8306220240 Forwards request for add1 info rs QA Tachnologies, Inc. research reactor 021102 seergency plan to continue review per 1001880. App E. Reg. Quids 2 6. Rev. 1 & ANBI/ANB-15 16-1702 requirements Info requested within 30 days of itr date 100480. C. O. Standardisation & Operal Projects Branch 03/06/80484. B. QA Technologies, Inc. /Qansrel Atomic Co. 6pp 18977. 026 28% Fithe 50-009, 03/06/10, 830680240 03/06/10

Q Inspection reports: 1C Bulletins & correspondence

8306280171 Forwards 1E Insp Repts 50 009/03-02 & 50-163/03 02 on B30509-12 & notice of violation Present level of resources allocated to rediction protection program inadequate losp frequency will be increased B00KH C Region 5. Office of Director B3/05/27 PARKIR.U.N Technologies, Inc. / General Atomic Co 2pp 19014 136 24X Fichs 50-009/03/27, 6306200171. PARKER, J. N. OA

--0306200177 Notice of violation from insp on 030509-12 MENGLAMBKI, F.A. Region 5, Office of Director. 0370 19014, 138 24X Fichs, 50-089, 03705727, 0306280171 03705/R7 1p

--B306280105 IE Imap Repts 50 089/83 02 & 50-163/83-02 an 830809-12 Noncompliance motes; failure to post notice of violation reradiological working conditions; per 100R819, 11(e) YUMAB, O. P., MEMBLAHOKI, F.A., BOOK, H.E., Region 5, Office of Director 03/03/87, 10pp 19014-139 84X Fiche 50-089, 83/05/27, 830408023 0306200171.

DOCKET BO-97 CORNELL UNIV. ZERO POWER REACTOR F. Becurity, medical, emergency & fire protection plans

830623023B Forwards proposed physical security plan Plan withheld (ref 100FR2 790)
CLARKID D. Cornell Univ 83/06/17 THOMAR.C. 0 Blandardization & Bascial Projects Branch ip 18948:253. 24X Fiche: 50-097, 83/06/17.

Q Inspection reports, Id Bulletins & correspondence

8306140248 Ack receipt of BOOB18 ltr informing NRC of steps taken to correct violations noted in IE lnsp Repts 80-097/83-01 & 80-157/83-01. BTARGETECKI, R Division of Project & Resident Programs 03/06/06 BTREE(T, N B. Cornell Univ | p. 18030-011 R4X Fichs: 50-097, 03/06/06, 8306140248

DOCKETED ITEMS

--8306140253 Responds to NRC 830421 ltr re violations noted in IE Insp. Rept 50-157/83-01 Corrective actions TRIOA operations audited insp. findings reviewed at safety committee meeting & annual audit of tickler file required CLARK, D. D. Cornell Univ. 83/05/18, BTAROSTECKI, R. Division of Project & Resident Programs 2pp. 18833 012 24X Fiche 50-097,83/06/06.8306140248

V Operator Examinations

8306140553 Extends invitation to attend 830627 meeting in King of Prussia, PA to discuss transfer of reactor operator licensing function from Bethesds, MD to Region I ofc BTAROSTECKI.R Division of Project & Resident Programs 83/06/09 STREETI.W.B Cornell Univ. 2pp 18834 206 24X Fichs 50-097, 83/06/09, 8306140853

DOCKET 50-111 NORTH CAROLINA STATE UNIV. RESEARCH REACTOR

J. Insurance & indemnity information

B306210424 Forwards FR notice of availability of order terminating License R-63.8ER supporting order & Amend 17 to Indemnity Agreement E-7 for signature CRUTCHFIELD.D Operating Reactors Branch 5 83/06/13 COCKRELL.R Q North Carolina State Univ 2pp 18937.038 24% Fiche 50-111.83/06/13.8306210424.

830A220280 Advises of elimination of annual fee for Amend 17 to Indemnity Agreement E-7, terminating License R-63 DINITZ, I Office of State Programs, Director B3/06/14 PUQLIBELA S. Division of Accounting 1p 18740-355 24X Fiche 50-111,83/06/14,830A220280

8306220286 Unexecuted Amend 17 to Indemnity Agreement E-7. revising attachment: Item 2 BALTIMAN, J Assistant Director for State & Licensee Relations. 83/06/14 1p 18940 350 24X Fiche 50-008.83/06/14,8306220286

P Operating license stage documents & correspondence

8306210424 Forwards FR notice of availability of order terminating License R-63.8ER supporting order & Amend 17 to Indemnity Agreement 6-7 for signature.
CRUTCHFIELD.D. Operating Reactors Branch 5. 83/06/13
CDCKRELL.R O North Carolina State Univ 2pp. 18937.038 24X
Fichs 50-111.83/06/13.8306210424.

~-8306210426 Order terminating License R~63 PURPLE.R A Assistant Director for Licensing 83/06/13 2pp. 18937 040 R4X Fiche. 50-111, 83/06/13, 6306210424

~-8306210430 BER supporting order terminating License R-63 R-3 reactor dismantled & disposed of per licensee 800605 dismantling plan. All radioactive components & activated concrete shield matl shipped to Richland. WA # Office of Nuclear Reactor Regulation, Director, 83/06/13, 3pp. 18937-042 24X Fiche 50-111.83/06/13,8306210424

DOCKET 50-112 UNIV OF DILAHOMA REGEARCH REACTOR

P. Operating license stage documents & correspondence

8304280567 Forwards revised "SAR Update & Review," & Tech Specs for 20-yr renewal of License R-83.
TERRELL, C W Oklahoma, Univ of. 83/06/20 THOMAS, C. O Standardization & Special Project Branch 1p 19018:130, 24X Fichs 50-112,83/06/20,8306280569.

--8306280581 "SAR Update & Review for Univ of OK AON-211P Reactor." * Oklahoma: Univ. of. 83/05/18, 14pp. 19018 131. 24X Fiche: 50-112: 83/06/20: 8306280849.

--8306280594 Tech Specs 1.0 through 6.0 re safaty limits & limiting safety sys settings, limiting conditions for operation, surveillance requirements, design features & controls. * Oklahome, Univ of 83/05/18, 33pp. 19018; 147. 24X Fiche: 50-112, 83/06/20, 8306280569.

G. Inspection reports, IE Bulletins & correspondence

B306060128 Forwards IE Insp Rept 50-112/83-01 on 830402-22 % notice of violation.

MADSEN.Q.L. Region 4: Office of Director, 83/05/17. EQLE.D.M. Oklahoma, Univ of. 2pp. 18722, 298 24X Fiche. 50-112, 83/05/17, 8306060128

--8306060131 Notice of violation from insp on 830420-22 * Region 4, Office of Director 83/05/17 ip 18722 300. 24 Fiche 50-112,83/05/17,8306060128

--8306060133 IE Insp Rept 50-112/63-01 on 630420-22 Noncompliance notedfailure to plot flow rate data since Oct 1977 while performing water purification sys flow rate check procedure. REDAND.R T. WEBTERMAN.T F. CROSSMAN.W A Region 4. Office of Director 83/05/17 10pp 18722 301 24X Fiche 50-112,83/05/17. 8306060128

DOCKET 50-116 IDWA STATE UNIV RESEARCH REACTOR F Security, medical, emergency & fire protection plans

8306270288 Informs that emergency plan does not meet requirements of App E to 10CRS50, Reg Guide 2 & & ANSI/ANB-15 76-1982, "Emergency Planning for Research Resectors " Add1 info requested must be submitted by 830801.

THOMAS. C O Standard(ration & Special Projects Branch, 83/06/20 HENDRICKBON, R 10wa State Univ 4pp 19046:118 24X Fichs 50-116.83/06/20.8306290258

G. Inspection reports. IE Bulletins & correspondence

8306100275 Submits corrected data for application to renew License R-59 & advises that computer printout records summarizing SNM inventory results for 1981 & 1982 corrected in response to 1E Insp Repts 80-116/83-01 **C7-0084/83-01 **HENDRICKBON-R Iowa State Univ. 83/05/19, PIRTLE 9 L. Region 3. Office of Director 2pp 18805-142 24X Fichs 50-116-83/05/19, 8304100278

DOCKET 50-128 TEXAS A&M UNIV RESEARCH REACTOR

H General correspondence

8306010296 Forwards Region IV organization chart & ofc directory in response to 830509 request, W/o and I. MADSEN. O. L. Region 4. Office of Director. 83/05/27 FELTZ, D. E. Texas ARM Univ., College Station, TX, 1p, 18672:189. 24X Fiche: 50-128,83/05/27,8306010296.

--8306010278 Requests copy of Region IV organization chart.
FELTZ.D E Texas AM Univ., College Station, TX. 83/05/09
MADSEN,G L. Region 4, Office of Director 1p. 18672.170. 24X
Fiche: 50-128,83/05/27.8306010296.

P Operating license stage documents & correspondence

830401035B Forwards "Completion & Results of Phase I of Nuclear Science Ctr Reactor Post-Damage Pulse Test Program for Full FLIP TRIQA Core "Pulse test planned at Phase I level to study fuel characteristics FELTZ, D. E Texas A&M Univ. College Station, TX B3/04/29, CROSSHAN.B Region 4, Diffice of Director 1p. 18482-121 24X Fichs: 50-128,83/04/29,830401035B.

--B306010361 "Completion & Results of Phase I of Nuclear Science Ctr Reactor Post-Damage Pulse Test Program for Full FLIP TRIGA Cure " JENNINOS,F. Texas A&M Univ , College Station, TX 83/04/30. 16pp. 19682,122 24x Fiche: 50-128:83/04/27,8306010358.

8306020612 Forwards repts on univ TRIOA bowed fuel elements, proposed pulsing program, results of Phase 1 of, "Post-Damage Pulse Test Program for Full Fifp TRIOA Core," & SER for license renewal application. 4/0 entis
THOMAB, C. D. Standardization & Special Projects Branch. 83/05/25.
BERLINDER, C. Core Performance Branch. 1p 18715-046. 24X
Fiche 50-128,83/05/25,8306020612.

8304040213 Forwards revised Page 29 of Tech Specs correcting error in Item 3.8 re primary coolant conditions.
FELTX.D.E., Texas ARM Univ., College Station, TX. 83/05/30.
BERNARDH Standardization & Special Projects Branch 2pp
18727.340 24X Fiche: 50-128,83/05/30,8306060213.

--8306060216 Revised Page 27 of Tech Space correcting error in Item 3.8 re primary coolant conditions.

* Texas A&M Univ., College Station, TX. 83/05/30. ip. 18727.362. 24X Fiche: 50-129, 83/05/30, 8306060213.

R. Periodic operating reports & related correspondence

830A010389 "Nineteenth Progress Rept of Texas A&M Univ Nuclear Ctr, 1982 " DEIGL.H.O., HEAD, J G . LAND, R. J Texas A&M Univ . College Station, TX, DRO-6207-15, 83/04/30 89pp 18674; 154. 24X Fiche: 50-128, 83/04/30, 8306010389.

DOCKET 50-131 CHAHA VET. ADMIN HOSP RESEARCH REACTOR F. Security, medical, emergency & fire protection plans

8306220216 Forwards request for add1 info re Gmaha Veterans
Administration Medical Ctr research reactor 821021 emergency
plan to continue review per 100FR50, App E, Guide & 6, Rev 1 &
ANSI/ANBI-15-16-1762 requirements
THOMAS C.D Standardization & Special Projects Branch. 83/06/10,
TURCOTTE, R 1 Vet Admin. Hosp Coshe, NE 5pp 18951; 010 24%
Fiche 50-131, 83/06/10, 8306220216

DOCKET 50-133 HUMBOLDT BAY POWER PLANT: UNIT 3

F Security, medical, emergency & fire protection plans

B306150R24 Advises that 830425 changes to security plan do not decrease effectiveness of plan & are acceptable VASSALLO,D B Operating Reactors Branch 2. 83/06/06 CRANE,P A Pacific Ges & Electric Co 2pp. 18870 066 24X Fiche 50-133.83/06/06.8306150R24

H General correspondence

8306070036 Provides names & addresses for appropriate distribution of technical correspondence re facilities SCHUYLER.J.C. Pacific Cas & Electric Co. 83/06/02 DENTON, H R Office of Nuclear Reactor Regulation. Director. EIBENHUT.D.G. Division of Licensing MARTIN.J.B. Region 5. Office of Director. 2pp. 18737-337 24X Fiche: 50-000,83/06/02.8306070036

Q. Inspection reports: IE Bullatins & correspondence

8305ii0458 IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in Well Logging Device." Syc list encl.
TAYLOR.J N Division of Safeguards & Inspection Programs (Post 630103), 83/05/26 Consolidated Edison Co of New York, Inc 125pp. 18831 043. 24X Fiche.50-000.83/05/26.8305110458.

8305110460 IE Info Notice 83-34, "Event Notification Info Horksheet."
Syc list encl
JORDAN, E.L. Bivision of Emergency Preparedness & Engineering
Response (Post 830103) 83/05/26 Consolidated Edison Co of New
York, Inc. 115pp. 18732-085 24X Fichs: 50-000, 83/05/26, 8305110460.

8305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods Withdrawn at BWRs " Bvc list ancl. UCRDAN.E.L. Division of Emergency Preparadness & Engineering Response (Post 830103), 83/05/31. Consolidated Edison Co. of New York, Inc. 116pp 18732: 208, 24X Fiche-50-000,83/05/31,8305110461.

8305110444 IE Info Notice 83-34, "Impact of Security Practices on Safe Operations," Syc list encl.
JORDAN E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/09 Consolidated Edison Co. of New York: Inc. 119pp. 18830-280. 24X Fiche: 50-000, 83/06/09, 8308110444.

8305110470 IE Info Notice 83-38, "Defective Heat Sink Adhesive & Seismicelly Induced Chatter in Relays Within Printed Circuit Cards," See list encl.
JORDAN, E.L. Davision of Emergency Preparedness & Engineering Response (Post 830103), 83/06/13. Consolidated Edison Co. of New York, Inc. 118pp 18920:225 24X Fiche. 50-000, 83/06/13.8305110470.

830 6090010 IE Info Notice 83-37, "Transformer Failure Resulting From Degraded Internal Connection Cables," Svc list enci.
JORDAN, E. Division of Emergency Preparedness & Engineering Response (Post 830103). 83706/13. Consolidated Edison Co. of New York, Inc. 243pp. 18921.001. RAX Fiche: 80-000, 83/06/13,8306090010.

8304210080 Responds to IE Bullstin 83-03 re check valve failure in raw mater cooling sys of diesel generators Plant utilizes emergency propone generator w/closed loop jacket cooling water sys. No check valves in engine jacket cooling sys. BRAND, D. A. Pacific Gas & Electric Co. 83/04/15. HARTIN, J. B. Region 5, Office of Director. Spp. 18911:232, 24X Fiche: 80-133,83/04/15,8304210080

8305110475 IC Info Notice 83-40, "Need to Environmentally Qualify Epory Grouts & Sealers " Svc list encl JORDAN.C.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 03/06/22. Consolidated Edison Co. of New York. Inc. 115pp 19021 179. 24X Fiche 50-000,83/06/22,830511047

8305110477 IE Info Notice 83-41. "Actuation of Fire Suppression Sys-Causing Inoperability of Bafety-Related Equipment " Svc list encl JORDAN,C L. Division of Emergency Preparedness & Engineering Response (Past 830103) 83/06/22 Consolidated Edison Co of Net York Inc 120pp 18997 007. 24X Fiche 80-000.83/06/22.830511047,

8305110479 IE Info Notice 83~42. "Reactor Mode Switch Molfunctions " 8vc list encl JORDANSE L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/23 Consolidated Edison Co of New York, Inc 116pp 18996 242 24X Fiche. 50~000.83/06/23.8305110479

8305110483 IE Info Notice 83-43. "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints "Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 03/06/24 Consolidated Edison Co of New York, Inc. 116pp 19046-297. 24X Fichs 50-000.83/06/24, 8305110483

R. Periodic operating reports & related correspondence

8304020309 Monthly operating rept for Mar 1983. W/830404 1tr DERMB.P S., WECKB.C D. Pacific Cas & Electric Co. 83/04/01 6pp. 18694:276. 24X Fiche: 50-133.83/04/01.6304020309

830&1&04&4 Monthly operating rapt for Apr 1903 W/830504 ltr DERMS,P.S., MEEMS,E.D. Pacific Cas & Electric Co. 63/05/04 Office of Resource Management. Director Spp 18863 046 24X Fichs: 80-133.83/05/04.830&1&0461

DOCKET 80-134 WORGESTER POLYTECH INST RESEARCH SEACTOR
V. Operator Examinations

830&140&30 Extends invitation to attend 830&27 meeting in Kinp of Prossis. PA to discuss transfer of reactor operator literaing function from Bethesda. NO to Region I of: 8TAROSIECKI.R Division of Project & Resident Programs. 83/06/04 MILBUR.L. C Worestor Polybechnic Inst 2pp. 18833 178, 24X Fiche: 50-134.83/06/09,830&140&30

DOCKET 50-141 STANFORD UNIV RESEARCH REACTOR

Decommissioning Stage Documents & Correspondence

830627006B Forwards safety evaluation & order terminating License R-60 M/o Amend II to Indemnity Agreement E-19 CRUTCHFIELD, D. Operating Reactors Branch 5 83/06/21 FINSTON,R A Stanford Univ., Stanford, CA. 2pp. 19046-142, 24X Fichs 50-141-83/06/21.830629/0068

--8306290073 Order terminating License R-60 EIBENNUT, D. O. Division of Licensing 83/06/21 Stanford Univ., Stanford, CA Dpp 19046, 144 24X Fiche, 50-141, 83/06/21, 8306290068.

--8305290077 Safety evaluation supporting termination of License R-60 * Office of Nuclear Reactor Regulation, Director 63/06/21, 3pp 19046-146 24X Fichs, 50-141,63/06/21,8306290068

--B306290080 Forwards IE Insp Rept 50-141/82-02 on 820916 & 1105.Plant not contaminated above Reg Ouide 1.86 limits Util estimate for biological shield occupancy reasonable.Wo encl. BOOK:PE. Region 5. Office of Director, 83/03/11 ERICKSON,P.R BEandardization & Special Projects Branch. 1p 19046:149 24X Fichs: 50-141,83/06/21.8306290068.

DOCKET 50-142 UCLA TRAINING REACTOR

G. Adjudicatory correspondence

830A020161 Forwards UCLA application for amend & amend to Feb 1980 renewal application for License R-71.in response to ABLB 830511 memorandum & order ABLB order directing NRC to inventory SNM forwarded to Region V for action 4000MeAD.C, P Hearing Branch 4. B2/05/31 FRYE.J.H., BRIGHT, 0 C. LUERKE, E.A. Atomic Safety and Licensing Board Panel 1p. 18691:056 24X Fiche: 50-142, 63/05/31, B3060R0161.

- 8306070399 Forwards prof qualification statements for UCLA witnesses at upcoming safety hearing Other statements will be sent when received W/o encl CORMIER, W H California, Univ. of, Los Angeles. 83/06/01 FRYE, J H , BRIGHT, Q O , LUEBKE, E A Atomic Safety and Licensing Board Panel 2pp 18742.001 24X Fiche 50-142,83/06/01.8306070399.
- 8306060282 Errate to ASLB 830511 memorandum & order ruling on NRC motion for summary disposition of Contention XX OL amend reduced BNM amount VCLA authorized to possess.
 FRYE.J H. Atomic Safety and Licensing Board Panel. 83/06/02.
 Office of the Executive Legal Director 2pp 18729 036 24X
 Fiche 50-142.83/06/02.8306060282
- B306070416 Requests for clarification of ASLB 830513 order scope of upcoming hearing UCLA must be allowed to present testimony on seismic questions to answer issue of worst case accident. Cartificate of Byc encl CORMERNU H California, Univ. of, Los Angeles 83/06/0 Bafety and Licensing Board Panel. 4pp. 18742-260, 24X Fiche. 50-142, 83/06/02, 8306070416 83/04/02 Atomic
- 830.61503B2 Response opposing UCLA 830.602 motion, requesting leave to introduce testimony on seismic matters at safety hearings, deferred by ASLB in 8305i3 memorandum & order re Contention XVII Declaration of Svc sncl.

 HIRSCH D Committee to Bridge the Oap. 83/06/09 Atomic Bafet and Licensing Board Fanel. 9pp. 18847:24B. 24X

 Fiche 50-142.63/06/09.8306150382
- 8306150392 Advises that prefiled testimony for upcoming inherent safety hearings should be received by parties before 830615 HIRSCH,D Committee to Bridge the Gap 83/06/07 MOODHEAD,C P. Hearing Branch 4. CORMIER,W California, Univ. of, Los Angeles. 1p. 18847 151. 24X Fiche.50-142,83/06/07,8306150392
- 8306160616 Memorandum & order ruling on UCLA request for clarification of ABLE 830513 ruling on Contention XVII UCLA testimony on seismic questions deferred. Testimony will be relevant only if NRC analysis incorrect.

 BRIGHT. 9 O., LUEBKE. E. A., FRYE. J. H. Atomic Bafety and Licensing Board Panel. B3706/13 California. Univ. of. Los Angeles. 3pp. 18866.031. 24X Fiche: 50-142,83/06/13,8306160616.
- B306210275 Confirms add1 testimony sent by express mail on B30604. WOODMEAD, C.P. Hearing Branch 4. B3/O6/16. HIRSCH, D. Committee to Bridge the Gap ip 18915-146. 24X Fiche: 50-142, 83/06/16, 8306210275
- 8306210280 Lists NRC exhibits for Jul 1983 hearings & forwards two exhibits not previously served.

 MODDHEAD, C P Hearing Branch 4. 83/06/17. FRYE, J. H., BRIGHT, Q. D., LUESKE, E. A Atomic Sefety and Licensing Board Fanel. 25pp 18914-245 24X Fiche 50-142,83/06/17,8306210280.
- 8306230303 Forwards corrected proposed findings of fact & conclusions of law re Contention II WOODHEAD,C,P. Hearing Branch 4 83/06/20 LAURENBON,JA, Atomic Safety and Licensing Board Panel. 1p. 18742,175 24X Fiche 50-142,83/06/20,8306230303
- ---B306230305 Proposed findings of fact & conclusions of law. * Office of the Executive Legal Director B3/06/R1. / 18942.177 24X Fiche: 50-142,83/06/R0,8306230303 46pp.
- B306230301 Forwards corrected NRC B30620 proposed findings of fact & conclusions of law.
 WDODHEAD.C.P. Hearing Branch 4. B3/06/21, LAURENBON.J.A. Atomic Bafety and Licensing Board Panel. ip. 18742-127, 24X
 Fiche 50-142,83/06/21,8306230301.
- 8306280828 Forwards proposed findings of fact & conclusions of law re special proceeding on Contention III. W/o encl. CORMIER.W. H California, Univ. of. Los Angeles. 83/06/23. LAURENBOW, J. A. Atomic Bafety and Licensing Board Panel. ip 19019.289. 24X Fiche 50-142,83/06/23,8306280525.
- B304270546 Forwards proposed findings of fact & conclusions of law, THOMPSON.D Nuclear Law Center, THOMPSON,D Committee to Bridge the Gap B3/06/23. LAMENBON,J.A. Atomic Bafety and Licensing Board Panel. 1p. 19052:241, 24X Fiche:50-142,83/06/23.8306290546.
- ---B306290552 Proposed findings of fact & conclusions of law.

 ** Committee to Bridge the Qap. 83/06/23. 52pp. 19052:242. 24%
 Fiche:50-142.83/06/23.8306290544.
- 8304280086 Motion for extension until 830701 to file reply briefs to proposed findings of fact & conclusions of law Certificate of Svc encl.

 HOODHEAD, C. P. Hearing Branch 4, 83/06/24, Atomic Sefety and Licensing Board Penel. 4pp. 19001 157. 24X Fichs. 50-142.83/06/24, 8306280086

- 8306280860 Forwards "Analysis officif-Shutdown Behavior in BPERT I Reactor," AEC R&D rept dtd 590723, WOODHEAD, C P Hearing Branch 4 83/06/24 FRYE, J. H. , BRIGHT, G. O. , LUEBKE, E. A Atomic Safety and Licensing Board Panel 42pp. 19017, 338 24X Fiche 50~142,83/06/24,8306200560.
- R Periodic operating reports & related correspondence
- 8306280595 "Nuclear Energy Lab Annual Rept.1982." M/830622 1tr HEG8T, M. F. California, Univ of. Los Angeles. 82/12/31. BERNARD, M Standardization & Special Projects Branch 21pp. 19017-165. 24X Fiche 30-142.83/06/22.8306280395
- T Hearing transcripts on non-antitrust matters
- 8304010013 Transcript of 630525 hearing in Los Angeles, CA re proposed renewal of Pacility license, Pp 184-470 Supporting documentation and.

 * Atomic Safety and Licensing Board Panel. 83/05/25. U00pp. 18664, 191. 24X Ficher 50-142, 83/05/25, 8306010013
- 8304020115 Transcript of 830526 hearing in Los Angeles, CA re proposed license renewal. Pp 471-782.

 * Atomic Safety and Licensing Board Panel 83/05/26. 327pp 18672: 199. 24% Fichs. 30-142: 83/05/26. 8306020115.
- 8306130371 Forwards QE Cort & P Nongy testimony, HODDHEAD,C.P. Hearing Branch % 83/06/09 FRYE.J.H., BRIGHT.Q.D., LUEBKE A Atomic Safety and Licensing Board Panel. ip. 18821-231. 24X Fiche: 50-142, 83/06/09, 8306130371.
- ~-B306130377 Testimony of QE Cort clarifying underlying bases of "Fuel Tamps in Argonaut Reactor Core Following Hypothetical DBA." Fuel melt impossible in svent of LDCA w/or w/o core crushing. Prof qualifications encl.
 CORT, Q. E. NRC ~ No Detailed Affiliation Given CORT, Q. E. Los Alamos Beisntific Laboratory 83/06/09 17pp. 18821:232, 24X Fiche: 50-142,83/06/09,8306130371.
- --8306130379 Testimony of P Neogy clarifying bases & methods used in "Transient Analysis of UCLA Argonaut." Prof qualifications encl. NEOGY, P NRC - No Detailed Affiliation Given Brookhaven National Laboratory 83/06/09. 19pp. 18821-249. 24X Ficha, 50-142, 83/06/09, 8306130371.
- 8306160009 Forwards 8 Hawley & H Bernard testimony, completing NRC testimony Piling for Jul 1793 hearing.
 HODDHEAD, C P Hearing Branch 4. 83/06/14. FRYE, J. H., BRIGHT, G. O., LUEBKE, E. A. Atomic Safety and Licensing Board Panel 1p 18861.176 24X Fiche: 50-142.83/06/14.8306160009.
- --8306160010 Testimony of SC Hawley explaining & clarifying analytical bases for conclusion in NUREO/CR-2079, "Analysis of Credible Accidents for Argonaut Reactors," Prof qualifications encl.

 HAMLEY.8.C. NRC - No Detailed Affiliation Given HAMLEY.8 C.

 Battelle Hemorial Institute, Pacific Northwent Laboratory,

 83/06/14. 20pp. 18861:177. 24X Fiche: 50-142, 83/06/14, 8306160009.
- --8306160017 Testimony of H Bernard explaining & clarifying bases & assumptions used in SER, Bection 14 re unalysis of consequences of postulated accidents. Prof qualifications enci BERNARD, H. Standardization & Special Projects Branch. 83/06/14. 14pp. 18861:197. 24X Fiche.50-142.83/06/14.8306160009.
- 8306170373 Forwards direct tastimony. HIRECH.D. Committee to Bridge the Cap. 83/06/14 and Licensing Board Panel. 1p. 18879: 067. 24X Fiche: 50-142, 83/06/14, 8306170373. 83/06/14.
- --8306170379 Testimony of B Norton, L Wayne, M Kaku, R Finston, R Kohm, M Pulido, D DuPont, S Aftergood, L Foster, D Hirach & S Plothin, questioning inherent reactor safety.
 NORTON, B , HAYNE, L., KAKU, M. Committee to Bridge the Gap.
 83/06/14. 29pp. 18879: 068. 24X Fiche: 50-142, 83/06/14, 8306170373.
- ~~8306170390 Testimony of B Norton, M Katu, R Kohn, D Hirsch, 8 Aftergood, M Pulido & D DuPont, as Panel I re concepts of inherent safety applied to reactor. NORTON, B , KAKU, M , KOHM, R. Committee to Bridge the Gep. 83/06/14. 78pp. 18879:097. 24X Fiche: 50-142: 83/06/14. 8306170373.
- ---8306170417 Testimuny of B Norton, M Kaku, R Kohn, M Pulido, B Plotkin, D Hirsch, B Aftergood & D DuPont, as Panel III recore disruption & related accidents. Reactor not inherently protected against mechanical damage NORTON, B., KAKU, M., KOHN, R. Committee to Bridge the Gap 83/06/14, 23pp. 18879:218, 24K Ficher 50-142,83/06/14,8306170373.

--8306170426 Testimony of L Hayne, R Finston, S Aftergood, L Foster, M Keku, B Norton, R Kohn, B Plottin, M Pulido, D Dupont & D Hirsch, as Panel IV re radiation dones from accidental release of fission products. Beclaration of 8vc encl.
HAYNELL, FINSTON, R., AFTERGOOD, S., Committee to Bridge the Gap 83/06/14 52pp. 18879 241. 24X Ficher 50-142,83/06/14,8306170373

DOCKET 50-146 BAXTON MUCLEAR EXPERIMENTAL FACILITY

- P. Operating license stage documents & correspondence
- 8306160030 FOIA request for four documents re Baxton Test Reactor GRABER, L.D. MUS Corp. 83/04/12. Division of Rules and Records ip. 18872:315. 24X Fiche:50-146,83/04/12,8306160030.
- 8306160026 Responds to FOIA request for four decuments re Sexton Test Reactor Requested ltrs available in PDR Sexton 741124 ltr to NNC not located. FELTON, J M. Division of Rules and Records. 83/04/20, 9RABER, L D. NUS Corp 1; 18872-314. 24X Fiche-50-146.83/04/20.8306160026.

DOCKET 50-148 UNIV. OF KANSAS RESEARCH REACTOR

- P. Operating license stage documents & correspondence
- 8306080309 FOIA request for three documents re Univ of KS Research Reactor BARNES: C. Affiliation Unknown 83/03/08. FELTON: J. N. Division of Rules and Records. 1p. 18790.303. 24X Fiche: 30-148:83/03/08.
- 8306080313 Responds to FOIA request for three documents ra Univ of KS Research Reactor. Forwards documents responsive to Items 1 & 2 of request. Releasability determination for Item 3 re imap rept Under review FELTON. J. H. Division of Rules and Records. 83/04/06 BARNES, C Affiliation Uninown. Ip 18790:304 24% Fishe: 50-148.83/04/06.8304080313
- --8306080316 Forwards responses to 731106 questions, indicating specified locations on floor plan.
 BHITH-W.P. Kansas: Univ. of. 73/12/06. ZIEMANN,D L. Atomic Energy Commission. Directorate of Licensing Spp. 18770:305 24X Fiche: 50-148,83/04/06.8306080313.
- G. Inspection reports, IE Bulletine & correspondence
- 8306030448 Addl response to FOIA request for three documents re Univ of KB Research Reactor (License R-78) Forwards GL Madsen 830324 ltr transmitting notice of violation & JE Insp Rept 50-148/83-01.
 FELTON, J. M. Division of Rules and Records, 83/04/19, BARNES, C. Affiliation Uninown 1p, 18735:329, 24X Fiche: 50-148,83/04/19, 8306030448

DOCKET 50-151 UNIV. OF ILLINGIS RESEARCH REACTOR

- Q. Inspection reports: IE Bullatins & correspondence
- 8306100217 Forwards IE Imap Repts 50-151/83-01 & 50-356/83-01 on 830504-05.No noncompliance noted, PAPERIELLO.C.J. Region 3. Office of Director. 83/05/25. MILEY. 9 H IIIIncis. Univ. of. Urbana-Champaign 2pp. 18805:189. 24X Fichs: 50-151,83/05/25.8306100217.
- --8306100220 IE Insp Repts 50-131/83-01 & 50-336/83-01 on 830504-05. No noncompliance hoted. Major areas inspected: radwaste mpt & radiation protection program, audits, training, procedures & instruments & equipment, ORANT, W. S. OREGER, L. R. Region 3, Office of Director, 83/05/23, 6pp. 18905; 191. 24X Fiche: 50-151, 83/05/25, 8306100217.
- 8306090023 Responds to violation noted in IE inag rept.
 Forwards data showing that calibr checks performed on
 dosimeters on 830616.
 BECK. 9. P. Illinois, Univ. of, Urbsna-Champaign. 63/05/31.
 ORANT. H. B. Region G. Office of Director. 2pp. 18792. 356, 24X
 Fichs: 50-151:83/05/31,8306090023.

DOCKET 50-155 BIG ROCK POINT NUCLEAR PLANT

- F Security, medical, emergency & fire protection plans
- 8306090118 Advises of approval of emergency response plan for facility, subj to verification of adequacy of public alerting & notification mys
 MCLQUOHLIN.D Federal Emergency Management Agency 83/05/16
 DIRCKS.W.J Office of the Executive Director for Operations 1p
 18793 329. 24% fiche 50-155,83/05/16.8306090118
- 8306100055 Describes integrated assessment of open issues & schedule for issue resolution & documents util response to environ equipment qualification & Generic Lts 82-33 re AVRED-0737 TOMER.K A Consumers Power Co 83/06/01 CRUTCHFIELD.D Operation Reactors Branch 5 113pp 18804 048 24X Fiche 80-155.83/06/01.
- B306070227 Approves State of MI emergency response plan & associated local plans w/condition that adequacy of public alerting & notification eys be verified per FEMA/NRC joint criteria listed in NUREG-0654/FEMA-REP-1, Rev 1, App 3
 PAPERIELLO, C. J. Region 3, Diffice of Director 83/06/06
 DEWITT, R. B. Consumers Power Co. 2pp 18796 235 24X
 Fiche 50-155,83/06/06,8306070227
- B30610008B Forwards IE Bafeguards Insp Rept 50-155/83-08 on B30502-05 No noncompliance noted MILLER, J. R. Region 3. Office of Director B3/06/06 DEWITT.R.B Consumers Fower Co 2pp 18802 091 24X Fiche 50-155.83/06/06. 830610008B
- --8306100093 IE Safeguards Insp Rept 50-155/83-08 on 830502-05 No noncompliance noted Major areas inspected review of security plan & implementing procedures security organization & program Details withheld (ref 100FR73 21).

 CHRISTOFFER, 0 . STAPLETON, B W . CREED, J R . Region 3. Office of Director 83/06/06 2pp 18802 093 24X Fiche 50-155,83/06/06,8306100088
- B306140217 Releases public version of revised site emergency plan FELTON, J. M. Division of Rules and Records. 63/06/06 Document Management Branch. 1p 18844 227 24X Fiche: 50-155, 83/06/06, 8306140217
- --8306140223 Forwards public version of Rev 68 to site emergency plan * Consumers Power Co 83/05/05 Office of Nuclear Reactor Regulation, Director 1p 18844-228 24X Fiche: 90-185, 83/06/06, 8306140217.
- --8306140227 Public version of Rev 68 to site emergency plan * Consumers Power Co 83/05/05, 27pp 18844 227, 24X Fiche: 50-155, 83/06/06, 8306140217,
- 8306200014 Releases public version of revised emergency plan FELTON.J M Division of Rules and Records. 83/06/06 Document Management Branch, 1p. 18909.062 24% Fiche 80-180.83/06/06, 830650014
- --8306200015 Public version of Rev 68 to emergency plan, consisting of corrections to rev record W/830526 ltr & receipt form.

 + Consumers Power Co. 83/05/20 3pp 18707 063 24X Fiche. 90-155, 83/06/06, 8306200014.
- 8306170218 Forwards Rev 9 to security plan Rev withheld (ref 100FR79.21).

 VANDEHALLE,D.J. Consumers Power Co. 83/06/09 CRUTCHFIELD.D. Operating Reactors Branch 5 2pp. 18882:314 24X Fiche 30-135,83/06/09.8306170218
- 8306210173 Forwards detailed scenario for emergency plan exercise scheduled for 830725-26 BORDINE.T.C Consumers Power Co. 83/06/13, KEPPLER, J. G. Region G. Office of Director 16pp. 16915.171 24X Fiche 50-135,83/06/13, B30621073
- 8306220065 Forwards Region III 830606 ltr to util endorsing FEMA 830516 ltr to NRC approving State of MI & local emergency plans.

 9ALLO, J. Isham, Lincoln & Beale GALLO, J. Consumers Power Co 83/06/20 BLOCH, P.B., PARIS, D. H., SHON, F. J. Atomic Sefety and Licensing Board Panel. 4pp 18930-180, 24% Fiche. 50-155, 83/06/20, 8306220065
- 830.6240285 Forwards response to NRC 830504 & 09 ltrs re security & suitability, training & qualification plans, respectively.
 Response withheld (10CFR73, 21).
 VANDEWALLE, D. J. Consumers Power Co 83/06/20. CRUTCHFIELD, D Operating Reactors Branch 5. 2pp. 18980-151. 24X
 Fiche 50-000, 83/06/20, 8306240285.

Q Adjudicatory correspondence

- 8306010450 Natics of withdrawal as counsel for intervenors & motion for extension to 830701 to submit outstanding documents until new counsel obtained Certificate of Svc encl SEMMEL, H Christo-Maria 83/05/27 3pp 18674 312 24X Fiche 50-155,83/05/27.8306010450
- 8306070372 Withdraws 830602 motion re criticality.provisionally filed by telex 0'NEILL, J D'Neill, J 83/05/30 Commissioners ip 18741 299. 24X Fichs 50-155,83/05/30,8306070372
- --8306070375 Motion for Commission review of ALAB-725 Exceptions listed Beent fuel pool presents unforgiving design unless geometric configuration safe O'NEILL-J Q'Neill. J 83/06/02 Commissioners 7pp 18741 300 24X Fiche 50-155.83/05/30.8306070372
- 8306020337 Motion for leave to respond to Christa-Maria, J Mills & J Bier 830317 reply to licensee 830121 response to 820914 order directing licensee to demonstrate deficiencies resmargency planning issues Certificate of Svc encl COPELAND, V O Consumers Power Co COPELAND, V O Lisham, Lincoln & Besle 83/06/01 Atomic Bafety and Licensing Board Panel 5pp 18693 180 24% Fiche 50-195,83/06/01,8306020339.
- 8304070424 Agrees w/Bammel 830524 ltr re outstanding emergancy planning issues issues of bus drivers & accuracy of BEW rept must be resolved 0'NEILL.J O'Neill, J. 83/04/01 BLOCH,P B , PARIS,O H , SHON,F. J. Atomic Safety and Licensing Board Panel. 2pp 10742 183 24X Fiche 50-155,83/04/01,8304070424.
- 8306080232 Motion to reconsider ABLB 830427 Dacision ALAB-725 Concerns include lack of safety-related equipment for spent fuel coaling.use of average temp in calculations.void fraction & fuel.

 BIER.J. Christa-Maria 83/06/02. Atomic 8afety and Licensing Appeal Panel. 2pp 18770 230 24X Fiche: 50-155.83/06/02.
- --8306080235 Advises that motion to reconsider ASLS 830427 Decision ALAB-725 should be corrected to read motion for Commission review of ASLS 830427 Decision ALAB-725 BIER, J.A. Christa-Maria, 83/06/06 PALLADINO, N. Commissioners ip 18770, 233 24X Fiche 50-155, 83/06/02, 8304060832.
- 8304080081 Response to intervenors 830527 motion for extension until 830701 to file response No filings due from intervenors before 830701, Opposes intervenors filing of add1 mat1 on emergency planning issues Certificate of Svc encl.

 BACHMANN.R.O Hearing Branch 1: 83706706, Atomic Sefety and Licensing Board Panel 4pp. 18773-264, 24x Fiche.50-155.83706706.
- 8306150405 Reply opposing intervenor 830517 motion re util misrepresentations Allegations of misconduct wholly unfounded OALLO.J. Consumers Power Co GALLO.J Isham, Lincoln & Beale 83/06/09 Atomic Bafety and Licensing Board Panel App 18847.045. 24% Fiche 50-155.83/06/09.8306150405.
- --8306150409 Affidavit of DJ VandeWalle in response to intervenor allegations of misrapresentation re util request to expand spent fuel atomage capacity VANDEWALLE, DJ. Consumers Power Co. 83/06/02 App. 18847-051, 24X Fiche 50-155, 83/06/09, 8306150405
- --8306150413 Affidavit of JB Jandovitz justifying util plans to inspect reactor vessel w/fuel in vessel instead of w/fuel removed. Centificate of Bvc ancl. JANDOVITZ. JB. Consumers Power Co. 83/06/02 20pp. 18847-055. 24X Fiche: 50-155, 83/06/09, 8306150405.
- 830&1703&3 Answer opposing Christa-Maria, Mills & Bier B30&02 separate patitions for review of ALAB-725 vacating & remanding LBP-B2-97, Petitions fail to satisfy Commission regulation requirements & stds for review W/Certificate of Svc. RACHMANN: R Q, Hearing Branch 1. GODDARD. R. J. Hearing Branch 3 83/06/16 Commissioners. 12pp 18880:181, 24X Fiche 50-155, 83/06/16, 830&170363.
- B306240405 Forwards Director's Decision DD-B3-09, denying Christa-Maria, J Bier & J Mills B30516 petition requesting NRG revoke or suspend DL, Notice of issuance of Director's Decision also encl.

 DENTON H, R. Office of Nuclear Reactor Regulation, Director.
 B3/06/16, CHRISTA-MARIA Christa-Maria App. 18998.020, 24X
 Fichs: 50-155, 89/06/16, 8306240405

- --8306240410 Director's Decision DD-83-09 denying Christa-Maria. J Sier & J Mills 830516 petition requesting NRC revoke or suspend OL DENTON, H R Office of Nuclear Reactor Regulation, Director. 83/06/16 5pp 18998 024. R4X Fichs. 50-135, 83/06/16, 8306240405
- --8306240415 Notice of issuance of Director's Decision DD-83-09, denying Christa-Maria, J Bier & J Mills 8305i6 patition requesting NRC revoke or suspend DL DENTON, HR Office of Nuclear Reactor Regulation, Director 83/06/16 2pp 18798 029 24X Fiche 80-155,83/06/16.8306240405.
- --8306240419 Forwards Director's Decision DD-83-09 denying Christa-Maria, J Bisr & J Mills 830516 pstition under 10CFR2, 206 requesting NRC revoke or suspend OL Notice of issuance of Director's Decision also encl.

 DENTON, H R. Office of Nuclear Reactor Regulation, Director 83/06/16 BiER, J Affiliation Unknown, 4pp 18998, 031, 24X Fichs 50-155,83/06/16,8306240405.
- --8306240421 Forwards Director's Decision DD-83-09, denying Christa-Meria, J Bier & J Mills 830516 petition under IOCFR2, 206 requesting NRC revole or suspend OL. Notice of issuance of Director's Dacision also encl DENTON, M. R. Office of Nuclear Reactor Regulation, Director. 83/06/16 MILLs, J E. Affiliation Unknown 4pp. 18998, 042, 24X Fichs 50-155,83/06/16,8306240405
- --8306240422 Discusses H Semmel 830516 petition under 10CFR2.206
 requesting revocation or suspension of DL based on alleged
 felse statements made during outgoing spent fuel expension
 proceedings Petition can be answered quickly
 BURNES 0 Regional Operations & Enforcement Division. 83/06/02.

 DENTON, H R Office of Nuclear Reactor Regulation, Director. 1p.
 18998-053 24X Fichs 50-155, 83/06/16.8306240405
- --83062404R3 Requests proceeding under 10CFR2.206 be instituted to revoke or suspend DL until 10-yr inep at plant conducted w/all fuel removed from reactor core.

 8EMMEL.H Antioch School of Law. Washington, DC. BEMMEL.H.
 Christa-Haris. 83/05/16
 Director 2pp. 18798.054. 24X Fiche: 80-155,83/06/16,8306R40405.
- 8306220023 Bubmits schedule of target dates for filing documents & testimony prior to commencement of resumed hearings. Order of issue presentation listed.

 OALLO, J. Isham, Lincoln & Beale. GALLO, J. Consumers Power Co. 83/06/17. BLOCH P B , PARIS, O, H., 8HON, F. J. Atomic Bafety and Licensing Board Panel 2pp. 18730:207. 24% Fiche 50-155,83/06/17, 8306220023.
- 830.6220105 Response apposing J O'Neill & JA Bier patition for Commission review of ALAB-725, No important question of law or policy rejection error of fact demonstrated & no new issues reised. Certificate of Byc encl THORNTON.P. Consumers Power Co. THORNTON.P. Isham, Lincoln & Beale, 83/06/17. Commissioners 7pp 18726:248, 24% Fiche 50-155,83/06/17,8306220105.
- 8305220065 Forwards Region III 830606 ltm to util endomsing FEMA 830536 ltm to NRC approving State of MI & local emergency plans.

 9ALLO, J. Isham, Lincoln & Beals. 9ALLO, J. Consumers Power Co.
 83/06/20 8L0CH, P. B. PARIB, D. H., BHON, F. J. Atomic Sefety and Licensing Board Panel. 4pp. 18730; 130. 24X Fiche: 80-155,83/06/20,8306220065
- 8306220102 Forwards add1 info re structural integrity of concrete in spent fuel pool at elevated temps & work papers, "Crack Spacing of Two-Way 91ab" "OALLO, J. Isham. Lincoln & Beale. GALLO, J. Consumers Power Co. 83/06/20. BLOCH, P. B. PARIB, D. H. , SHON, F. J. Atomic Bafety and Licensing Board Panel. 151pp. 18927:019. 24% Fiche: 50-150, 83/06/20.8306220102.
- 8306230007 Response opposing intervenor 830817 motion alleging util misrepresentation re need to remove fuel from reactor vessel prior to inservice imp. Allegations unsubstantiated. ODDARD, R. J. Hearing Branch 3, B3/06/20, Atomic Bafety and Licensing Board Panel. 20pp. 18747:072, 24X Fiche: 50-155,83/06/20,8306230007.
- --8306230010 Affidavit of DJ VandeWalle is urgency of util request to expand fuel storage capability Further delays in licensing proceedings could jeopardize continued plant operation. Certificate of Svc encl VANDEWALLE, D. J. Consumers Power Co. 83/05/05, 8pp. 18947:112. 24% Fiche: 50-155, 83/06/20 8306/20007.

- 8306270173 Advises of 830607 & OB military fighter aircraft flying over or in vicinity of facility. Events may be pertinent to Contention II-D re risks associated w/sircraft flying in site vicinity.

 COPELAND, V 9. Isham, Lincoln to Beale. COPELAND, V, Q. Consumers Power Co. 83706/20. BLOCH, F, PARIS, O H, BHON, F, J. Atomic Safety and Licensing Board Panel. 2pp 18991:347. 24%

 Fiche: 50-155,83/06/20,8306270173
- 8306280552 Memorandum & order denying Christa-Maria 830517 motion remistepresentation by licensee No misrepresentations occurred Parties must exercise restraint so no reputations will be unduly affected by filings BLOCH.P.B., PARIB, O.H., BHOW.R.J., Atomic Sefety and Licensing Board Panel 83/06/24, Christa-Maria, 3pp 19018-023 24X Fichs. 50-155,83/06/24,8306280552.
- 8306290506 Recommends mods to applicant proposed schedule of target dates. ODDDARD, R J Hearing Branch 3. 83/06/28. BLOCH, P. 8 . SHON, F. J., PARES, D. H. Atomic Safety and Licensing Sound Panel. 1p 19052-21 24X Fiche, 50-155. B3/06/28, 8306290506.
- P. Operating license stage documents & correspondence
- B30601028: Forwards evaluation of SEP Topic V-5, "RCPS Leakage Detection Sys " Evaluation satisfies B30228 commitment to provide detailed description of plant leakage detection sys. TONER, K. A. Consumers Power Co. 83/05/25. CRUTCHFIELD.D Operating Reactors Branch 5. 34pp. 18672:200. 24X Fishe: 50-155,83/05/25,8306010281.
- 8306010362 Provides explanation of circumstances surrounding containment integrated last test repairs & justification for actions taken, per 80518 teleon request BORDINE, T. Consumers Power Co. 83/05/25, CRUTCHFIELD, D. Operating Reactors Branch 5. 4pp. 18682:117. 24X Ficher 50~155,83/05/25,8308010382.
- 830.6020283 Forwards ray to 801219 response to NURES-0737. Item I.C.6. "Quidance on Procedures for Verifying Correct Performance of Operating Activities." per 821222 Tech Base change re shift technical advisor.

 30RDINE.T.C. Consumers Power Co. 83/05/25 CRUTCHFIELD, D. Operating Reactors Branch 5. 2pp. 18690. SIB. 24% Fiche: 50-135.83/05/25.83060R0283
- 8304030223 Application for amend to License DPR-6, changing Tech Specs to revise procedure for reactor startup if neutron source strength below currently specified min count rate on out-of-core nuclear instrumentation.

 VANDEMALLE, D. J. Consumers Power Co. 83/05/27. CRUTCHFIELD, D. Operating Reactors Branch 5. Spp. 18703: 351. 24X Fiche: 50-155,83/05/27,8304030223.
- --8306030230 Proposed Tech Spacs revising procedure for reactor startup if neutron source strength below currently specified min count rate on out-of-core nuclear instrumentation. # Consumers Power Co. 83/05/27. Spp. 18703:354. 24X Ficha:50-155,83/05/27,8366030223.
- 8304050117 Responds to NRC 830424 BER for environ qualification of safety-related electrical equipment requesting reaffirmation of justification for continued operation (JCD) & info for items in NRC Categories I, B. II. A. IV. Add J. JCD not required TONER, K. A. Consumers Power Co. 83/05/31, CRUTCHFIELD, D. Operating Reactors Branch 5. App. 18722: 271, 24X Fiche: 50-155, 83/08/31, 8304060119.
- 8306060144 Informs that incorporation of model Tech Spac definition of "operable-operability" inappropriate for plant. Existing administrative controls seat intent of model Tech Spac definition for musillary sys.

 BORDINE T.C. Consumers Power Co. 83/05/31. CRUTCHFIELD, D. Operating Reactors Branch S. 2pg. 18719:231, 24X Fiche: 50-135,83/05/31,8306060144.
- 8306080045 Forwards responses to BER on BEP Topics III-6 & III-ii resisaic design considerations & component integrity, respectively. Insp recomended to reduce seismic capacity uncertainty. Structural enalysis adequate.

 TONER, K. A. Consumers Power Co. 83/06/01. CRUTCHFIELD, D. Operating Reactors Branch 5, 243pp. 18774: 233. 24X Fichs: 50-155, 83/06/01, 8306080045
- 8306160625 Forwards "Review of Operating Experience History of Big Rock Foint Through 1981 for NRC SEP* & responses to util 830114 comments on draft rept transmitted by NRC 820910 ltr. Rept will be included as app to integrated plant BAR. CRUTCHFIELD, D. Operating Reactors Branch 5, 83/06/02, VANDEWALLE, D. J. Consumers Power Co. 2pp. 18864: 223, 24% Fiche: 50-185,83/06/02,8306160625.

- --8305i60631 "Review of Operating Experience History of Big Rock Point Through 1981 for NRC SEP " GUYMON,R H. MAYB.O T. Dak Ridge National Laboratory KUKIELKA.C. Bcience Applications. Inc. DRNL/NBIC-202 83/04/30 Office of Nuclear Reactor Regulation. Director 178pp 18864 225 24X Fiche: 30-153, 83/04/02, 8306i60625
- 8306100127 Requests analysis of thermal gradient temporal effects in spent fuel pool structure to demonstrate conservative assessment, per 839602 meeting. Response needed prior to restant approval.

 CRUTCHFIELD. D. Operating Reactors Branch 5 83/06/06 VANDEWALLE, D. J. Consumers Power Co. 11pp 16802 035 24X Fither 50-155.83/06/06,8306100129.
- 8304100222 Forwards Rev 1 to evaluation of SEP Topic V-5, "RCPB Leakage Detection," replacing 830825 submittal Evaluation provides PRA cost/benefit data concluding that installation of add1 leak detection instrumentation not cost-justified TONER, K.A. Consumers Power Co. 83/06/06, CRUTCHFIELD, D. Operating Reactors Branch 5, 37pp 19805-146, 24X Fichs. 50-155,83/06/06,8306100222,
- 8306130051 Forwards revised evaluation of RCPB leakage detection mys at facility per BEP Topic V-5. Summary comment re conformance of mys to recommendations of Reg Guide 1.45 either modified or eliminated M/o encl.

 TONER, K. A. Consumers Power Co. 83/06/06 CRUTCHFIELD, D. Operating Reactors Branch 5. 2pp 16824-245. 24X Fiche. 50-155, 83/06/06: 8306130051.
- 8306100224 Summary of B30507-11 onsite meetings w/util re expanded SEP integrated assessment program EMCH, R. L. Operating Reactors Branch 5, 83/06/08, Operating Reactors Branch 5, 83/06/08, 8304.078 Branch 5, 5pp 18807-217, 24X Fiche 50-155,83/06/08, 8304.078 Branch 5, 830
- 8306150003 Forwards responses to NRC concerns to 830110 Amend 6 to License DPR~6 covering spent fuel rack addition. On 830516. SER identified flye remaining unresolved items.including shear key capacity & effects of cracking on length. BORDINE, T. C. Consumers Power Co. 83/06/08 CRUTCHFIELD, D. Operating Reactors Branch 5 79pp. 18852:087 24X Fiche: 50-155.83/06/08,8306150003
- 8306160380 Forwards response to NRC concerns on Amend 2 to License DFR-6 re spent fuel rack addition, Technical justification re orthotropic plate assumptions & transient time provided. BORDINE: T. C. Consumers Power Co. 83/06/10. CRUTCHFIELD, D. Operating Resectors Branch 5. 27pp. 18857; 251. 24X Fiche: 50-155, 83/06/10, 8306160380
- 830.616.0849 Forwards final evaluation of SEP Topic V-5, "RCPB Leakage Datection," based on review of util 8305.25 submittal. Evaluation will be basic input to integrated safety assessment Topic complets. CRUTCHFIELD.D. Operating Reactors Branch 5, 83/06/13 VANDEMALLE, D. Constumers Power Co. 6pp. 18865-117, 24X Fichs: 50-155,83/06/13,8306160549
- 8306150152 Summary of 830602 meeting w/util & NUS Corp in Bethesds: MD re thermal/structural analysis of spent fuel pool Effects of NRC concerns on analyses would be insignificant, EMCH.R. L. Operating Reactors Branch 5. 83/06/14. Operating Reactors Branch 5 4pp. 18846:324 24X Fiche 50-155,83/06/14. 8306150152.
- 8306200192 Forwards FR notice of consideration of issuance of amend to License DPR-6 & proposed no significant hazards consideration determination & opportunity for hearing. Amend permits operation w/Exxon H-3 fuel assemblies GRUTCHFIELD, D. Operating Reactors Branch 5. 83/06/14 VANDEHALLE, D. J. Consumers Fower Co. Spp. 18903.185. 24X Fiche: 50-155,83/06/14,8306200192.
- --8306200197 FR notice of consideration of issuance of amend to License DPR-6 & proposed no significant hazards consideration determination & opportunity for hearing Amend permits operation w/Exxon H-3 fuel assemblies.

 CRUTCHFIELD.D. Operating Reactors Branch 5. 83/06/14 App. 18903; 188. 24X Fiche: 50-155.83/06/14.8306200192.
- B30.6200230 Forwards evaluation of SEP Topic V-12 A, "Water Purity of BWR Primary Coolant," Evaluation addresses adequacy of condensate treatment sys administrative controls Rev to existing Tech Specs unwarranted TONER.K.A. Consumers Power Co. B3/06/14, CRUTCHFIELD.D. Operating Reactors Branch 5, Bpp. 18902-322, 24X Fiche: 50-155, B3/06/14, B306200230

DOCKETED ITEMS

- 8306200367 Corrects NRC 821129 final SER of util SAR for SEP Topic III-4 B re turbine missiles, incorporating GE probabilistic analysis Final SER should be revised to incorporate listed corrections TONER, K A Consumers Power Co. 83/06/14 CRUTCHFIELD, D Operating Reactors Branch 5 2pp 18899 054 24X Fiche 50-155,83/06/14,830620036/
- 8306230278 Forwards evaluation of BEP Topic VI-1, "Organic Matls & Post-Accident Chemistry " Likelihood of significant atress corrosion cracking very low due to low concentrations of chlorides & acceptable pH level TONER, K A Consumers Power Co. 83/06/17, CRUTCHFIELD, D. Operating Reactors Branch 5, Spp. 18945 142, 24X Fiche 50-155,83/06/17,83062028
- 8306220102 Forwards add1 info re structural integrity of concrete in spent fuel pool at elevated temps & work papers, "Crack Spacing of Two-Way Slab" GALLO, J. Consumers Power Co 83/06/20 BLOCH, P.B., PARIS, O.H., SHON, F.J. Atomic Bafety and Licensing Board Papel 151pp. 18927-019 24X Fiche 50-155, 83/06/20, 8306220102
- 8304240004 Forwards vendor info rept, "Containment Water Level Monitoring," in response to 830415 request for add1 info re NUREO-0737. Items II F i 4 & II F i 5, "Containment Pressure Monitor" & "Containment Water Level Monitor "BORDINE.T.C Consumers Power Co. 83/06/20, CRUTCHFIELD.D. Operating Reactors Branch 5 16pp 18781, 273, 24X Fichs 50-155, 83/06/20, 8306240004
- 8306240139 Requests relief from fulfilling 820930 review of seismic Category I structures per 8EP Topic III 7.8 to determine if differences between structural code utilized for original plant design & current criteria TONER.K A Consumers Power Co. 83/06/20 CRUTCHFIELD.D Operating Reactors Branch 5 2pp 18981.087 24X Fiche 50-135,83/06/20,830.690.039
- 8306280559 Forwards documents to assist w/evaluation of 830601 submittel re integrated assessment of Open issues Results of primary collent sys safety relief valve test in response to NUREO-0737. Item II D. I. provided in util 8:1001 1t W/n encl BLANCHARD, D. F. Carolina Power & Light Co. 83/06/20 RUBIN, M. NRC No Detailed Affiliation Given 4pp. 19017, 310 24X Fiche. 50-155, 83/06/20, 8306280559
- 8306270125 Requests exemption from 10CFR50, App J, Bection III. A &(b) requirements, re integrated leak rate testing per B30617 talcon.
 BORDINE, T, C. Consumers Power Co 83/06/21 CRUTCHFIELD, D Operating Reactors Branch 5, ip 18788; 086 24X Fiche 50-155, 83/06/21, 8306870125.
- 8306270076 Discusses and PRA evaluations to SEP Topic VI-4.

 "Containment Isolation Sys," per 830228 commitment Only periodic stroke testing of MBIV & periodic leak testing of syc airline check valves cost offective TONER, K. A. Consumers Power Co. 83/06/22 CRUTCHFIELD. D. Operating Reactors Branch 5. 2pp 17013 OBS. 24X Fiche. 50-155, 83/06/22, 8306270076
- --8306270079 "SEP Topic VI-4, Containment Isolation Sys PRA Evaluations." * Consumers Power Co. 83/06/22, 31pp 19013.090. 24X Fiche: 50-155, 83/06/22, 8306270076
- ---8306270109 "BEP Topic III-5. A. High Energy Line Break Inside Containment -- FRA."
 - * Consumers Power Co 83/06/22, 48pp, 19013.310. 24X Fiche: 50-155,83/06/22,8306270107,
- 8306270391 Forwards justification for SEP Topics II-3.A. II-3.B. II-3.B. II-3.B. I.I-3.B. III-3.B. IIII-3.B. III-3.B. II-3.B. I

- 8306270412 Forwards corrections to PRA evaluations submitted to NRC on 830331 re SER on SEP Topic IX-5, "Ventilation Bys " Evaluations address impact loss of ventilation would have on various rooms & present cast-benefit analysis of ands. TONER.K A Consumers Fower Co 83/06/23, CRUTCHFIELD.D. Operating Reactors Branch 5 20pp 19053:150. 24X Fichs 50-155.83/06/23.8306290412
- 8306280442 Advises that based on review of B01217 submittal re NUREO-0737. Item II K 3 21, "Restart of Core Spray & LPCI Sys." Issue resolved CRUTCHFIELD, D Operating Reactors Branch 5. 83/06/R7 VANDEWALLE, D J Consumers Power Co 4pp 19020 184 R4X Fiche 50-155.83/06/27.8306280442
- 8306300027 Forwards safety evaluation of util responses to NRC 781129 Itr re Generic Item 8-24. "Containment Purging/Venting During Normal Operations " Radiological consequences of LOCA during purging acceptable Item closed. CRUTCHFIELD.D. Operating Reactors Branch 5 63/06/28. VANDEWALLE.D J. Consumers Power Co 5pp. 19120.238 24X Fichs 50-155,83/06/28,8306300027
- --8306300034 Bafety evaluation of util responses to MRC 781129 ltr re Generic Item B-24, "Containment Purging/Venting During Normal Operations "Issue of purge & vent valve operability resolved except for two open items # Office of Nuclear Reactor Regulation, Director, 83/06/28, 9pp 19120-243, 24X Fiche: 50-155, 83/06/28, 8306300027
- Q Inspection reports, IE Bulletins & correspondence
- B30511045B IE Info Notice B3-32. "Ruptured Am-241 Bources Contained in Well Logging Device." By: list encl. TAYLOR.J.M. Division of Bafeguards & Inspection Programs (Post B30103) B3/05/26. Consolidated Edison Co of New York. Inc. 125pp 18831 043. 24X Fiche 50-000, B3/05/26, B30511045B.
- 8305110460 IE Info Notice 83-34, "Event Notification Info Worksheet."

 Byc list encl
 JORDAN, E L. Division of Emergency Preparedness & Engineering
 Response (Post 830103), 83/05/26 Consolidated Edison Co of New
 York, Inc. 115pp. 18732:085. 24X Fiche 50-000,83/03/26,8305110460,
- B306100226 Forwards IE Insp Rept 80-155/83-06 on B30425-28.No noncompliance noted.

 PAPERIELLO, J. Region 3. Office of Director B3/05/26
 DEWITT, R. B. Consumers Fower Co. 2pp. 18605: 312, 24X
 Fiche 50-155,83/05/26,8306100226,
- --8306100229 IE Insp Rept 50-155/83-06 on 830425-28. No noncompliance noted Major areas inspected redistion protection program including qualifications, audits, training, radiation protection procedures, exposure control & TMI action items. LOVENDALE, P. C. . OREGER, L. R. Region 3, Office of Director. 83/05/24 7pp 18805-314, 24% Fiche 50-155, 83/05/26, 8306100226
- 8305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods Withdrawn at BWRs " Svc list encl. JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). B3/05/31. Consolidated Edison Co. of New York, Inc. 116pp 18732-208. 24X Fiche, 50-000,83/05/91,8305110461.
- 8306100088 Forwards IE Bafeguards Insp Rept 50-155/83-08 on 830502-05, No noncompliance noted MILLER, J.R. Region 3, Office of Director, 83/06/06, DEWITT, R. B. Consumers Power Co. 2pp. 18802:091 24X Fiche:50-195:83/06/06, 8306100088
- --8306100093 IE Safeguards Insp Rept 50-155/83-08 on 830502-05. No noncompliance noted Major areas inspected review of security plan & implementing procedures, security organization & program. Details withheld (ref 10CFR/3, 21) character security organization & Director 83/06/06. 2pp. 18802:093. 24X Fiche 50-105, 83/06/06, 8306100088
- 8306230431 Forwards IE Insp Rept 50-155/83-10 on 830512-13 & 21-24. No noncompliance noted LITTLE: N. 8 Region 3. Office of Director. 83/06/08 DEWITT, R. B. Consumers Power Co. 2pp 18743.233 24X Fiche 50-155.83/06/08, 8306230431.
- --8306230440 IE Insp Rept 50-i55/83-i0 on 830512-i3 & 21-24, No noncompliance noted Major areas inspected:review of inservice insp procedures, work activities, NDE, personnel certifications & data, MARD: K D . DANIELBON, D H. Region 3, Office of Director. 83/06/09, 7pp. 18743:235. 24X Fiche: 50-i55:83/06/09.8306230431

- 8305110464 IE Info Notice 83-36, "Impact of Security Practices on Safe Operations " Swc list encl JURDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/09 Consolidated Edison Co of New York, Inc 119pp 18830 280 24% Fiche 50-000,83/06/09,8305110464
- 8306170355 Responds to IE Bulletin 83-03, "Check Valve Failures in Raw Water Cooling Sys of Diesel Generators " Bulletin not applicable to plant since check valve not used at facility.

 JOHNBON.B D Consumers Power Co 83/06/07 KEPPLER.J 0 Region 3. Office of Director 4pp 18881 001 24X Fiche 50-155,83/06/09,8306170358
- 830615021B Discusses results of review of relief requests re inservice insp Relief granted in part from requirements of Section XI of ABME Boiler & Pressure Vessel Code SER encl CRUTCHFIELD, D. Dperating Reactors Branch 5 83/06/10 VANDEWALLE, D. Consumers Power Co 4pp 18846 018 24X Fichs 50-155.83/06/10.8306150218
- --8305150222 Bafety evaluation granting in part, requests for relief from inservice insp requirements

 * Operating Resttors Branch 5 83/06/10, 16pp 18846 022 24x
 Fichs 50-155,83/06/10,8306150218
- 8306270169 Forwards IE Insp Rept 50-195/83-07 on 830509-12 No noncompliance noted PAPERIELLO.C.J. Region 3, Office of Director 83/06/10 DEWITTA B Consumers Power Co. 2pp 18992 010 24X Fiche. 50-155,83/06/10,8306270169
- --8306270174 IE Insp Rept 50-155/83-07 on 830509-12 No noncompliance noted Major areas inspected; radiological environ monitoring program, analytical measurement GC, confirmatory measurements program & previous insp items.

 JANUSKA, A G., DEBIMANN.M J , SCHUMACHER, M C Region G, Diffice of Director, 83/06/10. 6pp 18992 012 24X Fichs 50-155.83/06/10. 8306270169
- 8305110470 IE Info Notice 83-38, "Defective Heat Bink Adhesive & Beismirelly Induced Chatter in Relays Within Printed Circuit Cards," Syc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83706/13. Consulidated Edison Co of New York, Inc. 118pp 18920 225 24x Fichs 50-000,83/06/13.8305110470
- 8306090010 IE Info Notice 83-37. "Transformer Failure Resulting From Degraded Internal Connection Cables " Svc list encl. URDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/13 Consolidated Edison Co of New York, Inc 843pp 18921 001 24% Fiche 50-000,03/06/13.8304090010
- B306210095 Ack receipt of B30826 ltr informing NRC of steps teken to correct violations noted in IE Insp Rept 50-155/83-04 BHAFER.W.D. Region 3, Office of Director B3/06/14, DEWIYT, R.B. Consumers Power Co. ip 18914:160 24X Fiche 50-155:83/06/14, B306210095
- ~-8306210102 Responds to NRC 830427 ltr re violations noted in IE Insp. Rept 50-155/83-04 Corrective actions: four pieces of 1/4-inch stainless steel tubing taped in per Procedure 13-3, Rev 35, "Matl Control," & valve & HX openings taped closed VANDEMALLE.D.J. Consumers Power Co. 83/05/26. KEPPLER.J.O. Region 3, Office of Director. Spp. 18914: 161 24X Fiche: 50-155, 83/06/14, 8306210095.
- 830.6230512 Requests util remit Class III fee for 781.222 application requesting relief from certain inservice insp requirements of 100FR90.05e(g) since review involved consideration of single safety tasus
 D1008.R.M. License Fee Management Brench. 83/06/16
 VANDEMALLE.D T. Consumers Power Co. ip. 18782-044. 24X
 Fiche: 50-155.63/06/16.8306230512.
- 8305110475 IE Info Notice 83-40, "Need to Environmentally Qualify Epoxy Grouts & Sealers " Syc list encl.
 JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83706/22. Consolidated Edison Co. of New York, Inc. 115pp. 19081 179 24X Fiche: 50-000,83/06/82,8305110475.
- 8305110477 IE Info Notice 83-41, "Actuation of Fire Suppression Bys Causing Inoperability of Safety-Releted Equipment " Svc list ancl. JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/22. Consolidated Edison Co. of New York, Inc. 120pp. 18997.007. 24X Fiche: 50-000,83/96/22,8305110477.

- 8306270376 Submits add1 info re Ceneric Ltr 81-03 concerning implementation of NUREG-0313. "Intergranular Stress Corrosion Cracting of Pressure Doundary Piping & Safe Ends "per B30415 request Inservice insp program not appropriate B0RDINE; T C Consumers Power Co B3/06/22 CRUTCHFIELD.D Operating Reactors Branch 5 5pp 18993 308 24X Fichs 50-155,83/06/22,8306270376
- 8305110479 IE Info Notice 83-42, "Reactor Mode Bwitch Malfunctions," Svc list encl JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/23 Consolidated Edison Co. of New York, Inc. 116pp 18996 242 24X Fiche 50-000,83/06/23,8305110479
- 8305110483 IE Info Notice 83-43, "Improper Settings of Intermediate Range (IR) High Flux Trip Betpoints " Svc list enc) JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/24 Consolidated Edison Co of New York, Inc. 116pp. 19046 297 24X Fiche 50-000,83/06/24,8305110483
- R Periodic operating reports & related correspondence
- 8304040095 Monthly operating rept for Mar 1983, W/830404 1tr AMSTUFZ, B., HOFFMAN, D.P. Consumers Power Co. 83/04/04 4pp 18719; 348 24% Fiche. 50~159, 83/04/04, 8304040095
- 8306160566 Monthly operating rept for Apr 1983 W/830503 ltr HOFFMAN, D.P. AMSTUTZ/S Consumers Power Co 83/05/05 Director's Office, Office of Inspection and Enforcement 5pp 18866:270. 24X Fichs 50~155,83/05/02,8306160866
- 8305260226 Revised Table RSD-E-06B listing high, low & average concentrations for environ monitoring rept for 1982 submitted 830329 BORDINE: T Consumers Power Co 83/05/19 KEPPLER: J O Region 3, Office of Director 2pp 18625.041 24X Fiche 50-155,03/05/19,8305260226
- 8303260265 Corrected annual anviron monitoring rapt.1982, raplacing Table RBD-E-06B to correct high.low & average concentration for highest average sampling location BORDINE.T C Consumers Power Co. 63/05/19 KEPPLER.J 9 Region 3, Office of Director. 3pp 18626 3R1 24X Fiche 50-155,63/05/19,830526265
- 8 Reportable occurrences, LERs & related correspondence
- 8306230241 LER 83-001/03L-0 on 830820, one of two steam drum level suitches in each protection channel operated below required set point of 8 inches below drum ctr line Caused by error in calibr techniques W/830617 ltr BORDINE, T. C. Consumers Power Co 83/06/17 KEPPLER, J. 9 Region 3, Office of Director 2pp 18945, 233 24X Fiche 50-155, 83/06/17, 8306230241
- 8306230330 PND-111-83-050 on 630617, w/circuit breakers for core spray valves closed, core spray valves opened Approx 600 gallons lake water injected into reactor vessel, raising chloride concentration Event not reported within 1 h HDL2MER, H . JACKIM, I Region 3, Office of Director 83/06/17 ip 18742 274. 24% Fishe 50-155,03/06/17.0306230300.
- T. Hearing transcripts on non-antitrust matters
- 8306090005 Transcript of 830607 telephone conference in Bethesda, MD, Pp 2:646-2,665.

 * Atomic Safety and Licensing Board Panel 83/06/07 41pp 18773 330. 24% Fichs. 50-155.83/06/07,8306090005.
- DOGKET SO-154 UNIV OF WISCONBIN RESEARCH REACTOR

 F Sacurity, medical, emergency & fire protection plans
- 8304040270 Ack receipt of 830509 ltr informing NRC of steps taken to correct violations noted in IE insp rept MILLER, J R Region 3. Office of Director. 83/06/01 CABHHELL, R. J. Misconsin, Univ. of. Medison ip. 18730:018 24X Fiche 50-156,83/06/01.8394060270.
- --B306060272 Responds to NRC B30504 ltr re violations noted in IE insprept, Corrective actions, copies of current security plan retrieved & destroyed or stamped & stored per 10CFR73 21. CASHMELL, R. J. Wisconsin, Univ. of, Madison. B3/05/09 MILLER, J. R. Region 3, Office of Director ip. 18730 019 P4X Ficher 50-136, B3/06/01, 8306060270.

1

- @ Inspection reports, IE Bulletins & correspondence
- 9304060270 Ack receipt of 930507 ltr informing NRC of steps taken to correct violations noted in IE insp rept MILLER.J R Region 3. Office of Director 93/06/01 CASHWELL.R J Hisconsin. Univ of Madison ip 18730 Ole 24X Fiche 50-156.63/06/01.8306060270
- --8306060272 Responds to NRC 830504 ltr re violations noted in IE insprept, Corrective actions copies of current security plan retrieved & destroyed or stamped & stored per 10CFR73 21 CASHMELL, R. J. Wisconsin, Univ. of, Madison 83/05/09 MILLER, J. Region 3, Office of Director 1p 18730 019 24X Ficha 50-186,83/06/01,8306060270
- 8306270162 Forwards IE Insp Repts 50-154/83-03 & 70-0134/83-01 on 830519-20 No noncompliance noted PAPERIELLO, C J Region 3, Office of Director 83/06/08 CASHMELL, R J Wisconsin, Univ of, Madison 2pp 18972 024 24X Fiche 50-156,83/06/08,8306270162.
- --8306270167 IE Insp Repts 50-154/83-03 & 70-0134/83-01 on 830519-20. No noncompliance noted Major areas inspected radiation protection & radwaste mgt program, including organization & qualifications & logs & records, FAUL, R A . GREGER: L R Region 3, Office of Director 83/06/08 6pp. 18972 028 24X Fiche 50-136,83/06/08,8306270162

DOCKET 50-157 CORNELL UNIV RESEARCH REACTOR

- F Security, medical, emergency & fire protection plans
- 8306230238 Forwards proposed physical security plan Plan withheld (ref 100FR2 770)
 CLARK D. D Cornell Univ 83/06/17 THOMAS, C D Standardization & Special Projects Branch 1p 18945 253 24X Fiche 50-097,83/06/17,8306230238
- G Inspection reports: IE Bulletins & correspondence
- B306140248 Ack receipt of B30518 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-077/83-01 & 50-157/83-01. BTAR08TECKI, R Division of Project & Resident Programs 83/06/06, STREETI, H. B Cornell Univ ip. 18833.011 24X Fiche 50-077.83/06/06, 8306140248
- --8306i40253 Responds to NRC 830421 ltr re violations noted in IE Insp. Rept 50-157/83-01 Corrective actions TRIGA operations audited, insp. findings reviewed at safety committee meeting & annual audit of tickler file required CLARK, D D Cornell Univ 83/05/18, 8TARDSTECKI, R. Division of Project & Resident Programs 2007 1833.012 24X Fiche 50-07,83/06/06,8306i40248
- V Operator Examinations
- B306140553 Extends invitation to attend B30627 meeting in King of Prussia.PA to discuss transfer of reactor operator licensing function from Bethesds, MD to Region 1 ofc BTAROBTECKI,R Division of Project & Resident Programs B3/06/09. BTREETT,W B Cornell Univ 2pp, 18834 204 24% Fiche 80-097,83/06/09.8306140653

DOCKET 50-163 GENERAL ATOMIC CD

- F. Security, medical, emergency & fire protection plans
- 8305280171 Forwards IE Insp Repts 50~087/83-02 & 50~163/83-02 on 830509-12 & notice of violation Present level of resources allocated to radiation protection program inadequate. Insp frequency will be increased.

 BOCK.M.E. Region 5. Office of Director 83/05/27 PARKER, J. W. 9A Technologies, Inc. / Jonewal Atomic Co. 2pp 19014, 136. 24X Fichs. 50-089, 83/05/27, 8306280171
- --8304280177 Notice of violation from insp on 830509-12 WENSLANDRIJE, A. Region 5, Office of Director, 83/05/27 ip. 19014 138 24X Fiche 50-089, 83/05/27, 8306280171.
- ---B306280185 IE Insp Repts 50-087/83-02 & 50-163/83-02 on 630509-12 Noncompliance noted: failure to post notice of violation re radiological working conditions, per IOCFR19 11(e). YUHAB, G.P. Region 5. Office of Director. 83/05/27. 10pp 19014-137. 24X Fiche; 50-087, 83/05/27, 6306280171.

- 6306220240 Forwards request for add1 info re OA Technologies, Inc research reactor 821102 emergency plan to continue review par 10CFR50, App E, Reg Outde 2 6. Rev 1 k AN81/AN8-15 16-1982 requirements Info requested within 30 days of itr date THOMA8, C O Btandardization & Special Projects Branch 83/06/10 MOMRY, W R QA Technologies, Inc / Oeneral Atomic Co App 18777 026 24X Fiche 50-089, 83/06/10.8306220240
- G Inspection reports. IE Bulletins & correspondence
- 8306280171 Forwards IE Insp Repts 50-089/83-02 & 50-163/83-02 on 830509-12 & notice of violation Present level of resources allocated to radiation protection program inadequate Insp frequency will be increased BOOK.H E Region 5. Office of Director 83/05/27 PARKER.J.W. QA Technologies. Inc /0eneral Atomic Co 2pp 19014 136 24X Fiche 50-089.83/05/27.8306280171
- --8304280177 Notice of violation from insp on 830509-12. WENSLAWSKI.F A. Region 5. Office of Director 83/05/27 ip. 19014.138 24X Fiche.50-089.83/05/27.8304280171.
- --8306280185 IE Insp Repts 50-089/83-02 & 50-163/83-02 on 830509-12.

 Noncompliance noted failure to post notice of violation re
 radiological working conditions, per 10CFR19 11(e).

 YUHAB, @ P , MENSLAMSKI, F A , BOOK, H E Region 5, Office of
 Director 83/05/27 10pp 19014 139 24X Fichs 50-089,83/05/27,
 8306280171.

DOCKET 50-146 UNIV OF MARYLAND REBEARCH REACTOR

- F Becurity, medical, emergency & fire protection plans
- 8306210328 Forwards request for add1 info re Univ of MD research reactor 821027 emergency plan to continue review per 10CFR30. App E. Reg Quide 2 & Rev 1 & ANBI/ANB-15. 16-1782 requirements Info requested within 30 days of itr date. THOMAS. C O Standardization & Special Projects Branch 83/06/07 TOLL. J S. Maryland, Univ of 5pp 18721-340. 24X Fichs 50-166.83/06/07.8306210328

DOCKET 50-170 NATIONAL NAVAL MEDICAL CENTER

- E NRC Safety Evaluation Report (SER), supple & correspondence
- 8306210378 BAFETY EVALUATION REPORT RELATED TO THE RENEWAL OF THE OPERATINO LICENSE FOR THE RESEARCH REACTOR AT THE ARMED FORCES RADIOBIOLOGY RESEARCH INSTITUTE, Docket No. 30-170.

 * Division of Licensing. NUREG-0882 S01 83/05/31. 11pp.
 Available at NRC. *3,00 189/37.261 24X Fichs 50-170,83/05/31. 8306210378
- Q Adjudicatory correspondence
- 8306060316 Advises of Citizens for Nuclear Reactor Safety/licensee agreement to discontinue litigation of admissible contentions except emergency plan contention in TRIQA reactor proceeding.

 ENTHISLE:E B Citizens for Nuclear Reactor Safety, Inc. 83/05/23.

 HOYT.H. Atomic Safety and Licensing Board Panel 7pp 18729: 163, 24X Fiche. 50-170, 83/05/23, 8306060316
- 830615039) Forwards gupplemental BEH, NUREQ-0882 re NRC review of licensee emergency plan, M/o encl, BACHMANN, R O Hearing Branch 1. 83/06/10 HDYT, M , HILL, E. E., 8CHINK, D. R. Atomic Safety and Licensing Board Panel. 1p. 18847 028 24X Fiche 80-170, 83/06/10, 8306150391
- B306220056 Ack receipt of B30316 ltr re EIA & negotiations for relicensing of AFRRI nuclear reactor & cobalt irradiation facility. Issues re monitoring results, oversight committee & emergency plan should be addressed.

 BCULL,D L. OILCHRIBT.C.W. Montgomery County, MD 83/06/14.

 PALLADINO, N Commissioners. ORFIT,H.A. Defense. Dept. of, Defense Nuclear Agency. 2pp 18930.025. 24X Fiche 50-000,83/06/14, B306220056.
- ---8306220063 Responds to 830215 ltr re ungoing license renewal proceedings NRC decision not to issue EIS will be reexamined PLAINE-H H. Office of the General Counsel. 83/03/16 GILCHRIST, C W., BCULL, D L. Montgomery County, MD 2pp 18930; 027 24X Fiche. 50-000, 83/04/14, 8306220056

V. Operator Examinations

8306140628 Extends invitation to attend 830627 meeting in King of Prussia: PA to discuss transfer of reactor operator licensing function from Bethesda: MD to Region I ofc.
8TAROSTECKI.R. Division of Project & Resident Programs. 83/06/09.
ADCOCK.B.R. Armed Forces Radiobiological Research Institute. 2pp. 18833: 180 24% Fiche 50-170,83/06/09.8306140628

DOCKET 50-192 PURDUE UNIV. REBEARCH REACTOR

B Reportable occurrences. LERs & related correspondence

8306230282 RD on 830614, scaled source w/Ru-106 leak tested.Results showed 0.005 uCi activity removed by smear. Second test on 830617 showed 0.00016 uCi removed. Bource removed from use BORN.9.8 Purdue Univ. 83/06/17 SRENIAMSKI.D. Region 3, Office of Director 2pp. 18945:217 24X Fiche 50-182.83/06/17.8306230282.

DOCKET 50-194 NATIONAL BUREAU OF STANDARDS REACTOR

V Operator Examinations

8306140182 Extends invitation to attend 830627 meeting in King of Prussia. PA to discuss transfer of reactor operator licensing function from Bethesda. MD to Region I ofc. STAROSTECKI, R Division of Project & Resident Programs 83/06/09 CARTER. R. B. Commerce. Dept. of, National Bureau of Standards 2pp 18939-074. 24X Fiche: 50-184.83/06/09.8306140152.

830&140278 Extends invitation to attend 830&27 meeting in King of Prussis, PA to discuss transfer of reactor operator licensing function from Bethesda. MD to Region I ofc.
8TAROBIECKI, R Division of Project & Resident Programs 83/06/09 KERR, F. Maryland, Univ. of 2pp 18832:234, 24% Fichs: 50-184,83/06/09,8306140278.

DOCKET 50-186 UNIV. OF MISSOURI RESEARCH REACTOR

F Security, medical, emergency & fire protection plans

8306:50165 Forwards physical security plan. Plan withheld (ref 10CFRZ.790 & 10CFRZ.21).

MCKIBBEN.J.C.: MCGINTY.D.M. BUQOER, H. Missouri. Univ. of, Columbia 83/06/10. THOMPSON.C. D. Standardization & Special Projects Branch 2pp 18846:005, 24X Fiche: 50-186, 83/06/10, 8306:50165.

DOCKET BO-188 KANSAB STATE UNIV. RESEARCH REACTOR

H General correspondence

B306160227 Advises of appointment of J Higginbotham as reactor supervisor, effective B30601.

FAN.R.E. Kannas State Univ. B3/06/10 MILLER, J.R. Standardization & Special Projects Branch. 2pp. 18861: 239. 24X

Fiche, 50-188, 83/06/10, 8306160229

DOCKET 50-192 UNIV. OF TEXAB RESEARCH REACTOR

F. Becurity, medical, emergency & fire protection plans

83040R0702 Forwards request for info identified in encl emergency plan review by 830709. Plan does not currently meet requirements of App E to 100FR50 k guidance criteria set forth in Rev 1 to Reg Guide 2 & & ANSI/ANB-15.

8305290403 Forwards request for add1 info re physical security plan. Requested info required by 830705 W/o encl THOMAB.C.O. Beandardization & Special Projects Branch. 83/05/24. KLEIN D. E. Tesas. Univ. of. Austin. TX. 1p. 19053:126 24X Fichs: 50-192, 83/05/24. 8306290403.

DOCKET 50-193 RHODE ISLAND & PROVIDENCE PLANTATIONS AEC
F Security, medical, smergency & fire protection plans

830&080327 Requests route approval for shipment of spent fuel from Narragansett,RI to Savannah River,SC Mods to last routes made to avoid travel through doubtoum Nesterly,RI DIMEGLIC.A F Rhode Island, State of 83/05/27 HILLMAN.C Division of Safeguards 2pp 18789 339 24% Fiche 50-193,83/05/27,830&080329

8306210348 Forwards approved route for transport of spent fuel from Narragansett RI to Savannah River, SC, in response to 830527 request BHERR.T B Material Transfer Safeguards Licensing Branch 83/06/08 BHERR.T B Material Transfer Safeguards Licensing Branch 83/06/08 Fiche: 50-173, 83/06/08, 8306210348.

O Inspection reports, IE Bulletins & correspondence

8306160238 Forwards IE Insp Rept 50-193/83-01 on 830425-28 & notice of violation BTAROSTECKI.R Division of Project & Resident Programs 83/05/27 DIMEDLIO, A.F. Rhode Island & Providence Plantation 2pp 18861 309 24X Fiche 50-193,83/05/27.8306160238

--8306160239 Notice of violation from insp on 830425-28 * Region 1. Office of Director 83/05/27 ip 18861 311 24X Ficha 80-193.83/05/27.8306160238

--B306160246 IE Insp Rept 50-193/83-01 on 830425-28 Noncompliance noted failure to formally appoint alternate to position of health physicist upon temporary vacancy & to post autide door into HX room as high radiation area KINEV, W W. ELBABSER, T. C. Region 1, Office of Director 83/05/20 7pp 18861 312 24X Fiche 50-193,83/05/27,8306160238

V Operator Examinations

8306140098 Extends invitation to attend 830627 meeting in King of Prussia.PA to discuss transfer of reactor operator licensing function from Bethesda.HD to Region I of STARDSTECKI.R Division of Project & Resident Programs B3/06/09 DIMEGUIO.A.F. Rhode Island, State of 2pp 18839 107 24X Fichs 50-193,82706/09,8306140098.

DOCKET 50-179 MANHATTAN COLLEGE REBEARCH REACTOR

H. General correspondence

B306280389 Notifies that Q Kane appointed chief reactor supervisor, effective B30702. Appointment will be noted in license renewal application being prepared KANE,R B. Hanhattan College. B3/06/21. BERNARD,H Standardization & Special Projects Branch ip 19001.361 24X Fiche: 80-199, B3/06/21, B306280389

V. Operator Examinations

8306140625 Extends invitation to attend 830627 meeting in King of Prussia,PA to discuss transfer of reactor operator licensing function from Bethesda,MD to Region I ofc.
8TAROSTECKI,R. Division of Project & Resident Programs 83/06/09 KANE,R. Manhattan College 2pp. 18842 084 24X
Ficha 50-199,83/06/09,8306140625

DOCKET 50-201 WEBT VALLEY REPROCESSING PLANT

P. Operating license stage documents & correspondence

9304010094 OEOLOGIC AND MYDRDLOGIC RESEARCH AT THE WESTERN NEW YORK NUCLEAR SERVICE CENTER, WEST VALLEY, NEW YORK, Annual Report.
August 1981 - July 1982.
ALBANESE, J.R., ANDERSON, S.L., DUNNE, L.A. New York, State of, FIN B-6350 NURSO/CR-3207, B3/03/31 Division of Health, Siting & Waste Management 414pp Available at NRC \$8.50, 18687 304, 24X Fiche 50-201,83/03/31.8304010094.

8306150216 Trip rept of site visit to observe test equipment operation & discuss waste mgt techniques w/DDE personnel & Dupont Corp. List of participants encl.

BOYLE.R. High Level Waste Licensing Management Branch. CLARK, A.T., NRC - No Detailed Affiliation Given 83/05/25 ROUSE, L. C. NRC - No Detailed Affiliation Given. BELL.M. J. High Level Waste Licensing Management Branch. 9pp. 18870:036. 24X Fiche: 50-201,83/05/25, 8306150216.

- 8306290620 Forwards "Analysis of Terminal Waste Form Belection for West Valley Demonstration Project" Rept discusses basis for selection of borosilicate glass COFFMAN.F E Energy. Dept of 83/06/14 DAVIB.J 0 Office of Nuclear Material Bafety & Bafeguards. Director 2pp 19047.055 24X Fiche 50-201.83/06/14.8306290620
- --B306270626 "Analysis of Terminal Waste Form Selection for West Valley Demonstration Project "

 * Energy, Dept of WVDP-100 83/06/14 24pp 17047 057, 24X Fiche 50-201.83/06/14,8306270620
- 8306270566 Advises that BOE has selected borosilicate glass as waste form for immobilizing West Valley high level wastes Appropriate tests of wastes required HANNUH W H Energy, Dept of 83/06/17 CLARK, A T Advanced Fuel & Spent Fuel Licensing Branch ip 19047 188, 24X Fiche: 50-201, 83/06/17, 8306270566

DOCKET 50-204 BAN ONOFRE NUCLEAR STATION, UNIT 1

- F Security, medical, emergency & fire protection plans
- 8304070251 Forwards IE Insp Repts 50-204/83-10,50-341/83-19 & 50-342/83-17 on 830411-27 & notice of violation BISHOP.T W. Region 5, Office of Director, 83/05/16. PAPAY, L T. Southern California Edison Co. 2pp 18746 088 24X Fiche: 50-206,83/05/16,8304070251
- --8306070R61 IE Insp Repts 50-206/83-10.50-361/83-19 & 50-362/83-17 on 830411-27 Noncompliance noted failure to install fully 8-h emergency lighting units in access/egress routes 860MN.K.M Region 5. Office of Director 83/05/11 11pp 18746 092 24X Fiche.50-206.83/05/16.8306070251
- 8304010142 Advises that add1 fire protection Tech Spec changes will be submitted as separate amend applicant supersading Proposed Change 92 by 830901 Add1 fire protection mods in progress KRIEGER.R W Southern California Edison Co. 83/05/24 CRUTCHFIELD. Operating Reactors Branch 5 ip 18674.044. 24X Fiche 30~206.83/05/24.8306010142.
- 8306160011 Advises that 830323 Rev 9 to physical security plan consistent W/10CFR73 21 provisions & does not decrease plan effectiveness. Changes acceptable RNIGHTON: 0 W. Licensing Branch S 83/06/06. DIETCH: R Southern California Edison Co HOLCUMBE San Diego Qes & Electric Co 3pp. 18872 148 24% Fiche: 50-206:83/06/06:8306160011
- 8306280076 Forwards IE Insp Rept 50-206/83-09 on 830323 No noncompliance noted. NORDERHAUQ.L. Region 5. Office of Director 83/06/07 PAPAY.L T Southern California Edison Co 2pp. 19001.168 24X Ficha 50-206.83/06/07.8306280076
- --8304280081 IE Insp Rept 50-204/83-09 on 830323. No honcompliance noted Major areas inspected, emergency plan exercise & associated critiques KUNIHIRO, D. M., SCHUSTER, M. D. Region 5, Office of Director 83/04/06 Spp 19001 170. 24X Fiche: 50-204, 83/04/07, 8304280074
- 8304220291 Responds to 830406 ltr re changes to physical security plan.
 Changes consistent w/10CFR50, 54(p) & do not decrease
 effectiveness of plan.
 KNIOHTON, C W Licensing Branch 3 83/06/10 DIETCH, R. Bouthern
 California Edison Co. HOLCOMBE, J C. Ban Diego Qus & Electric Co.
 3pp 18940:344 24X Fiche 50-206,83/06/10.8306220291
- 8304220294 Responds to 830323 ltr re Rev 2 to guard training & qualification plan Changes consistent w/10GFR30 54(p) provisions & do not decrease effectiveness of plan. KNIGHTON, G. M. Licensing Branch 3. 83/06/10. DIETCH, R. Bouthern California Edison Co MOLCOMBE J. C. San Diego Ges & Electric Co. Spp. 18940 312. 24X Fiche 50-206.83/06/10.8304220294.
- 8306230520 Responds to 830427 ltr re temporary changes to physical security plan Changes consistent w/10CFR50 54(p) requirements & acceptable.
 KNIGHTON, G. M. Licensing Branch 3. 83/06/10. DIETCH. R. Southern California Edison Co. HOLCOMBE. J. C. San Diego Gas & Electric Co. 2pp 18954; 361. 24X Ficher 50-206, 83/06/10, 8306230520.
- 8305230495 Ack receipt & provides evaluation of changes to emergency plan implementing procedures submitted in 821029 & 831103 ltrs. Changes do not decrease effectiveness of emergency response planning NORDERHAUD, L. R. Division of Radiological Safety & Safeguards Program 83/05/20. BASKIN, K. P. Southern California Edison Co. ip 18941:360 24X Fichs 80-206,83/06/20,8306230455.

J Insurance & indemnity information

- 8306270172 Forwards Endorsements 95,96 & 97 to NELIA Policy NF-146, & Endorsements 83,84 & 83 to MAELU Policy MF-38 & Endorsement 38 to NELIA Policy N8-282 ROCCO. J Southern California Edison Co 83/06/13 DINIT2. I. Antitrust & Economic analysis Branch (Utility Finance) Bpp 1899; 349. 24% Ficher 30-206,83/06/13,8306270172.
- P Operating license stage documents & correspondence
- 8306070019 Final response to FOIA request for documents re current efforts by NRC to upgrade santhquake resistance at facility Forwards documents listed in app. Handwritten document withheld (ref FOIA Exemption 5)
 FELTON, J M Division of Rules and Records 83/04/05. HHARTON, R. J. 8an Diego, Univ. of, 8an Diego, 8an Diego, 8an Diego, 9an Diego, 9a
- --B205170474 Forwards 820506 mean w/Bystematic Evaluation Program Branch recommendations re seismic reanalysis program DIRCKS.N J. Office of the Executive Director for Operations. B2/05/07, PALLADING.N J., GILINBKY.V , AHEARNE.J. F. Commissioners 2pp 18781-352 24X Fiche: 50-206.83/04/05, 8306070019
- --B208050024 Forwards response to 820618 request for commente on Director's Decision 81-19 denying 10CFR2 206 relief re restart & emergency planning DIRCKB, H J Office of the Executive Director for Operations, 82/07/22, AHEARNE, J Commissioners App 18781:354, 24% Fiche 50-206,83/04/05,8306070019
- --8306070021 Requests meeting to discuss encl questions on BECY-82-63 re Director's Decision denying 100FR2 206 relief concerning interin seismic adequacy, AHEARNE, J. Commissioners 82/04/20 Office of Policy Evaluations 5pp. 18781-347. 24X Fiche 50-206,83/04/05, 8306070019.
- --8306070028 Approves SECY-82-63 re Director's Decisions 81-17 & 81-20 denying request for 10FR2 206 relief Comments on SECY-82-63 re misclassification of turbine blog complex encl.
 AHEARNE, J. F. Commissioners, B2/05/03, CHILK, S. J. Office of the Secretary of the Commission 2pp 18782-008, 24X Fiche 50-206,83/04/05.8306070019.
- 830A080207 Bummary of 830A01 mesting w/util re plan for managing retrofit items License amend schedule, w/proposed safety-based integrated schedule, will be submitted on or about 831115 List of attendess & handouts exit PAULSON, W.A. Operating Reactors Branch 5 83/06/03. Operating Reactors Branch 5 83/06/03. Operating Reactors Branch 5, 3pp 18771 274. 24X Fiche. 30-206.83/06/03. 8306080209.
- --8304080210 "Plan for Menaging Plant Retrofit," * Bouthern California Editon Co. 83/04/01, 23pp. 18771: 277, 24% Fiche: 80-204, 83/04/03, 8304080209.
- 8306070049 Notification of 830617 meeting w/util in Bethesda, MD to discuss NRC 830402 request for addl info we saismic reanalysis vertical response spectrum.

 PAULBON, M. A. Operating Reactors Brench 5. 83/06/06. CRUTCHFIELD, D. Operating Reactors Branch 5. 8pp. 18740.056. 24X fiche: 50-206.83/06/06.8306070049.
- 8306130386 Forwards Amend & to Topical Rept 8CE-1-A, "OA Program," & miscellaneous documents per Final Rule 10CFR50. 54(a). Rept supercades program described in FSAR, App D, BASKIN, K. P. Southern California Edison Co. 83/06/09. MARTIN, J. B. Region 5. Office of Director. 3pp. 18021; 271. 24X Fiche: 50-206, 83/06/09, 8306130386.
- --8306130392 Amend 6 to Topical Rept BCE-1-A, "GA Program."

 * Southern California Edison Co. BCE-1-A A06. BS/04/30. 200pp.
 18821; 274. 24% Fiche: 50-206, 83/06/09, 8306130386
- 8306140019 Bubmits description & basic premise for "Plan for Early Return to Power" & "Plan for Managing Plant Retrofit" & discusses implementation of each plan.

 DIETCH: R. Bouthern California Edison Co. 83/06/10. DENTON: H. R. Office of Nuclear Reactor Regulation, Director. 3pp. 18838: 327. 24X Fiche: 50-206: 83/06/10, 8306140019
- 8306190303 Responds to 830402 request for add1 info re vertical ground response spectrum used for BEP Topic III-6, "Belismic Design Considerations." Add1 info requirements & actions will be determined following meetings w/NRC.

 8ABKIN.K.P. Bouthern California Edison Co. 83/06/13
 CRUICHFIELD,D. Operating Reactors Branch 5. ip. 18849:203. 24X Fiche. 50-206.83/06/13.8306150303.

- 830.6200156 Delineates activities associated w/continuation of work to resolve differences resulting from BEP Proposed corrective actions to resolve open items will be provided in last Querter of 1983

 BABKIN, K.P. Southern Celifornia Edison Co. 83/06/13.

 CRUTCHIELD, D. Operating Reactors Branch 5 ip. 18903 112. 24X

 Fiche: 50-206, 83/06/13, 8306200156.
- 830.6.220004 Forwards replacement Page 2 for R Distch 830.6.10 ltr re util plans for continuation of work at facility. Replacement page supplied to clarify possible problems of interpretation due to tupographical errors KRIEOER.R W Southern California Edison Co. 83/06/16 CRUTCHFIELD. D Operating Reactors Branch 5 2pp 18928 001. 24X Fiche. 50-206, 63/06/16. 830.6220004.
- B306220095 Forwards plan for managing plant retrofit to assist in raducing capital expenditures & to improve capacity factor. NRR concurrence requested.
 DIETCH, R. Sauthern California Edison Co. 83/06/17 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 26pp 18926-222 24X Fichs: 80-204, 83/06/17, 8306220090.
- 8305240203 Forwards "Reactor Coolant Pump Rotor Seizure/Shaft Break Accident Analysis," in response to 820210 request for addl info re SEP Topic XV-7. Environ consequence analysis unnecessary. KRIEGER, R. W. Southern California Edison Co. 83/06/17. CRUTCHFIELD.D. Operating Reactors Branch 5. Ip 18980, 250 24X Fiche: 50-206: 83/06/17. 8306240203
- ---8306240208 "Reactor Coolant Pump Rotor Seizure/Shaft Break Accident Analysis." ELLENBERGER, B., BLACKBURN, T. A., Southern California Edison Co 82/03/11, 12pp. 18980 251, 24% Fiche; 50-206, 83/06/17, 8306240203.
- 8306240175 Bunnary of 830617 meeting woutil & TERA in Bethesda, MD re NRC 830402 request for addl info re vertical reanalysis response spectrum PAULEON, H.A. Operating Reactors Branch 5. 83/06/22. Operating Reactors Branch 5. 4pp 18980; 158. 24X Fiche: 50-206, 83/06/22.
- 830.6290415 Submits add! info re SEP Topic IX-5 Temp profile analysis for 4.160 & 480-volt rooms w/new ventilation sys to be provided prior to startup Addi dc switchgear & inverter room ventilation analysis forthcoming BASKIN, K.P. Southern California Edison Co. 83/06/24. CRUTCHFIELD, D. Operating Reactors Branch 5. 2pp. 19053:171. 24X Fichs: 50-206,83/06/24,8306290415.
- 8305280466 Forwards response to 820303 request for info re as-built facility differing from licensing bases assumed in assessment of BEP Topic VI-4. "Containment Isolation Sys." KRIEOER,R.M. Southern California Edison Co. 83/05/28. CRUTCHFIELD, D. Operating Reactors Branch 5. 17pp 19018: 246 24X Fiche: 50-206, 83/06/28, 8306280466
- O Inspection reports. IE Bulletins & correspondence
- B306160046 FDIA request, on behalf of EE Kent, for records prepared by UB govt employees re Alliance for Burvival, T Carpenter &/or ongoing NRC investigation of facilities. CARPENTER, T. Orange County Alliance for Burvival. B3/03/14 Office of Administration. ip. 18893:031. 24% Fiche: 50-206, B3/03/14, B306160046.
- 8306100009 Add1 response to FOIA request for documents dtd 820101 or after re BALP. Forwards App A documents Documents also available in FDR.
 FELTON.J M. Division of Rules and Records. 83/04/11. CLARK.R. 8an Francisco Exeminer. 3pp. 18815:252 24X Fiche: 50-000.83/04/11, 8306100009
- -- 8306100014 Submits schedule 4-- barre TALP Board meetings for

or. 82/03/19. gulation, Director ip. 5100009.

nators for Reactor nators will be board members (S Miner and). 82/03/24. Region IX

- 8306160052 Responds to FOIA request for records prepared by US govt employees me Alliance for Survival.T Carpenter &/dr ongoing NRC investigation of facilities Forwards App A documents Bearch for add1 documents in progress FELTON.J M Division of Rules and Records 83/04/14 CARPENTER, T Orange County Alliance for Survival 2pp 18893 032 24x Fiche 50-206.83/04/14.8306160052
- 8306160197 Responds to FOIA request for documents re FOIA Request 82-618. Forwards App A documents Documents 18 % 19(d) partially deleted (ref FOIA Exemption 6) FELTON. J M Division of Rules and Records 83/04/25 GARDE. II P. Government Accountability Project 4pp 18893 125 24X Fiche 50-206.83/04/25.8306160197
- --830AiA0200 Forwards FDIA request Releasability determinations indicated in response ltrs to requester No action required FELTON-J M Division of Rules and Records 83/03/24 DIETCH, R. Bouthern California Edison Co ip 1889
- --8306160200 Forwards FOIA request Releasability determinations indicated in response ltrs to requester No action required FELTON-J M Division of Rules and Records 63/03/24 DIETCH-R Southern California Edison Co. ip 18893
- --8306160207 Requests disclasure determination for listed documents subj to FOIA Request 82-618
 ORIMBLEY,D H. Division of Rules and Records 83/02/07
 ALEXANDER,I. Region 5, Office of Director 2pp 18893 148 24
 Fichs 50-206,83/04/25,8306160197
- --8306160218 Forwards documents re 8 Parde FOIA request on behalf of EE Kent, for documents regarding 621120 IE rept "Special NRC Insp of San Onofre 1,2 & 3 (FOIA-62-618)" W/o encl FORTUNA, R A Office of Investigation 63/01/24 CARR, J C Division of Rules and Records 3pp 18893 150 24X Fiche 50-206,83/04/25,8306140197
- --B306160223 Request disclosure determination for document originated by ofc re FOIA Request 82-618 by noon on 930119
 CARR.J.C. Division of Rules and Records 83/01/12 WILBON, V Office of Nuclear Reactor Regulation, Director 2pp 18893 157 24X Fiche 50-206,83/04/25,8306160197
- --B306160230 Submits list of Region V Ofc of Investigation File Serials 26-42. "BONGS-Allegations Re: Welding of Piping by EE Kent," Case 5-82-021 Serials 1-25 previously provided in response to FOIA Request 62-528 SHACKLETON. O C Office of Investigation 83/01/03 FORTUNA. R. A Office of Investigation 3pp 18893 159 24X Fiche 50-206.83/04/25.8306160197
- ---8306160243 Forwards list of documents available at Region V re B Oards FOIA Request 82-618 on EE Hent behalf, for documents concerning 821130 IE rept "Special NRC Insp of San Onofre 1:2 & 3"

 ALEXANDER I, Region 5, Dffice of Director, 83/12/28 REED, C A. Division of Rules and Records Spp. 18893 162 24X Fiche 50-206.83/04/25,8306160197
- --8306160253 Forwards OC Bhackleton 821109 memo transmitting documents subj to FDIA Request 82-528 Review of Documents 1, 2, 10 & 19 by Region V recommended Confidentiality not sought by EE Kent FORTUNA.R. A. Office of Investigation 82/12/10, CARR, J C. Division of Rules and Records. 1p 18893-165. 24X Fichs. 30-206, 83/04/25, 8306160197
- ---8306160263 Forwards list of documents responsive to FOIA Request BZ-528 re EE Kent allegations concerning facilities from Oct 1980 to present Region V not aware of allegation until Oct 1982 SHACKLETON, O. C. Region 5, Office of Director, 82/11/09 FORTUNA, R A Office of Investigation 5pp. 18893 166 24X Fichs 30-206,83704/23,8306160197
- --8305160276 Requests info responsive to FOIA Request 82-528 for documents re EE Kent allegation concerning facilities from Oct 1980 to present be forwarded to Div of Rules & Records by 821116.
 CARN, J. G. Division of Rules and Records 82/11/04 KINE, C. Director's Office, Office of Inspection and Enforcement ALEXANDER, I Region 5, Office of Director BOWERS, H. Office of Director & Auditor. 19 18893:171, 24X Fiche, 50-206, 83/04/25, 8306160197.
- --8306160281 Forwards list of documents responsive to FDIA Request 82-528 re EE Kent allegations concerning facilities from Oct 1980 to present per 822104 memo. Related info encl. CNPELKEN, R. H. Region 5, Office of Director. 82/11/17. CARR, J. C. Division of Rules and Records Spp. 18893, 174, 24X Fiche 50-206, 83/04/25, 8306160197.

- --8306160301 Forwards FOIA Request 82~618 for documents re 821130 IE rept **Special NRC Insp of San Onofre 1.2 & 3 " Documents responsive to request should be forwarded to Div of Rules & Records by 830104
- 8304140070 Addl response to FUIA request for records prepared by US govt employees re Alliance for Survival, T Carpenter Morongoing NRC investigation of facilities IE Insp Repts 30-206/82-31, 50-361/82-31 & 50-362/82-27 available in PDR FELTON, J M Division of Rules and Records 83/04/28 CARPENTER, T Drange County Alliance for Survival 2pp 18892 338 24X Fiche 50-206,83/04/28,8306160070
- B304070240 Forwards IE Insp Repts 50-206/83-13,50-361/83-21 & 30-362/83-19 on 830401-29 No noncompliance noted B18HDP.T W Region 5. Office of Director 83/05/13 PAPAY.L T Southern California Edison Cv 2pp 18746 047 24X Fiche 50-206.83/05/13.8306070240
- --8306070244 [E Insp Repts 50-206/83-13,50-361/83-21 & 50-362/83-19 on 830401-29 No noncompliance noted Major creas inspected plant operations during long-term shutdown, monthly maint & surveillance activities & LERs MILLER, L., XIRSCH, D. F. Region 5, Office of Director 63/05/12 6pp 18746 049 24% Fichs 50-206,63/05/13,8304070240
- 8304070333 Forwards IE Insp Repts 50-204/83-09,50-341/83-17 & 50-342/83-20 on 830329-0406 No noncompliance noted ROOK, HE Region 5, Office of Director 83/05/13 PAPAY, L T. Bouthern California Edison Co. 2pp 18741 077 24X Fichs 50-204,63/05/13,8304070333
- --8306070339 IE Insp Repts 50-206/83-08,50-361/83-17 & 50-362/83-20 on 830329-0406 No noncompliance noted Major areas inspected lab GA program, including independent confirmatory measurements re Region V mobile lab HAMADA.0 H., TEMPLE.0 M., OARCIA,E Region 5, Office of Director 83/05/12 10pp 18741 079 24X Fichs 50-206,83/05/13,8306070333
- 8306070251 Forwards IE Insp Repts 50-206/83-10,50-361/83-19 & 50-362/83-17 on 930411-27 & notice of violation BISHOP, T W Region 5, Office of Director 83/05/16 PAPAY, L T. Bouthern California Edison Co 2pp. 18746.088 24X Fiche 50-206,83/05/16.8306070251
- --B306070299 Notice of violation from insp on B30411-27 KIRBCH D F. Region 5, Office of Director B3/05/16 2pp 18746 090 24% Fiche 50-206, B3/05/16, B306070251
- --8306070261 IE Insp Repts 50-206/83-10.50-361/83-19 & 50-362/83-17 on 830411-27 Noncompliance noted failure to install fully 8-h emergency lighting units in access/egrees routes 8COMN.K M , KIRSCH.D F Region 5, Office of Director 83/05/11 11pp 18746 092 24X Fiche 50-206.83/05/14.8306070251
- 8305110458 IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in Well Logging Device" Svc list encl TAYLOR, J M Division of Bafeguards & Inspection Programs (Post 830103) 83/05/24 Consolidated Edison Co of New York, Inc 125pp 18831 043, 24% Fichs 50-000,03/05/26,8305110458
- 8308110460 IE Info Notice 93-34, "Event Notification Info Worksheet"
 Byc list ancl
 JURDAN, E Division of Emergency Preparedness & Engineering
 Response (Post 830103), 83/05/26 Consolidated Edison Co of New
 York, Inc. 115pp 18732.085 24X Ficho 50-000,83/05/26,8305110460
- B303110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods Withdrawn at IWRs " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/03/31 Consolidated Edison Co. of New York, Inc 116pp 18732 208 24X Fiche 50-000,83/05/31,8309110461
- ©306100111 Responds to IE Bulletin 83-03 re testing of check valves in diesel generator cooling water sys Four check valves will be included in inservice testing program. W/two oversize drawings Aperture cards are available in PDR HAYNES, J © Southern California Edison Co. 83/06/07, MARTIN, J 8 Region 5, Office of Director Spp. 18801 259 24X Fichs. 50-206, 83/06/07, 83061001[1.
- ©30.6280076 Forwards IE Insp Rapt 50-206/83-09 on 830323. No noncompliance noted.
 NORDERHAUD, L. Region 5, Office of Director 83/06/07. PAPAY, L. T. Southern California Edison Co. 2pp. 19001.168 24X
 Fiche. 50-206, 83/06/07, 8306280076.

- --8306280081 IE Insp Rept 50-206/83-09 on 830323 No noncompliance noted Major areas inspected emergency plan exercise & associated critiques KUNIHIRO. D M. SCHUSTER, M D Region 5, Office of Director 83/06/06 5pp 19001 170 24X Fiche 50-206/83/06/07.8306280076
- 8305110464 IE Info Notice 83-34, "Impact of Security Practices on Bafe Operations " Svc list and JORDAN, E L Division of Emergency Preparedness & Engineering Response (Pact 830103) 83/06/09 Consolidated Edison Co. of New York, Inc. 119pp 18830 280 24x Fiche 50-000, 83/06/09,8305110464.
- 8305110470 IE Info Notice 83-38, "Defective Heat Bink Adhesive & Seismically Induced Chatter in Relays Hithin Printed Circuit Cards," Bvc list encl JORDAN, EL Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co. of New York, Inc. 118pp 18920 225 24X Fiche 50-000,83/06/13,8305110470,
- 830A090010 IE Info Notice 83-37, "Transformer Failure Resulting From Degraded Internal Connection Cables." Svc list encl JORDAN.E.L. Division of Emergency Preparadness & Engineering Response (Post 830103) 8370A/13 Consolidated Edison Co., of New York, Inc 243pp 18921:001 24X Fiche 50-000,83/06/13.8304090010
- 8306280477 Forwards IE Insp Rept 50-206/83-15 on 830502-31.No noncompliance noted BISHOP, TW Region 5, Office of Director 83/06/14 PAPAY, L T Bouthern California Edison Co 2pp 17020 119 24X Fiche 50-206,83/06/14:8306280477
- --8306280480 IE Insp Rept 50-206/83-15 on 830502-31. No noncompliance noted Major areas inspected, plant operations during long-term shutdown monthly maint & survaillance activities, LERs & previous insp items MILLER, L. KIRSCH, D. F. Region 5, Office of Director, 83/06/14 app 17020 121 24X Fichs 50-206, 83/06/14, 8306280477.
- B305110475 IE Info Notice B3-40, "Need to Environmentally Qualify Epoxy Grouts & Bealers " Svc list enc! JURDAN.E L. Division of Emergency Preparedness & Engineering Response (Post B30103) B3/06/22 Consolidated Edison Co of New York, Inc 115pp 17021 179, 24X Fiche 50-000, 83/06/22, 8305110475.
- 8305110477 IE Info Notice 83-41, "Actuation of Fire Suppression Sign Causing Inoperability of Safety-Related Equipment " Svc list enc! JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 63/06/22 Consolidated Edison Co. of New York, Inc. 120pp 18997 007 24% Fiche 50-000, 63/06/22, 8305110477
- 8305110479 IE Info Notice 83-42, "Reactor Mode Switch Malfunctions,"

 8vc list encl

 JORDAN E L Division of Emergency Preparedness & Engineering

 Response (Post 830103) 83/06/23 Consolidated Edison Co of New

 Vork, Inc 116pp 18996 242 24X Fiche 50-000,83/06/23.8305110479
- 8305110483 IE Info Notice 83-43, "Improper Bettings of Intermediate Range (IR) High Flux Trip Setpoints " Svc list encl JORDAN E L Division of Emergency Prepapedness & Engineering Response (Post 830103) 83/06/24 Consolidated Edison Co of New York, Inc 116pp 19046 297 24X Fiche 50-000,83/06/24,8305110483
- R Periodic operating reports & related correspondence
- 8306160455 Monthly operating rept for Apr 1983. W/830513 ltr 8PEER, M., RAY, H.E. Bouthern California Edison Co. 83/05/13. App. 18863 088. 24% Ficher 50-206, 83/05/13, 8306160455.
- U Congressional/Executive Correspondence
- 8211160565 Forwards Community Energy Action Network 821018 ltr & Los Angeles Times article re potential problem w/welds at factities CRANSTON, A Senate 82/10/29 KRANHERER, C Office of Congressional Affairs. 3pp 18893 056. 24X Fiche 50-206.83/04/14, 8306160052
- DOCKET 50-208 COLUMBIA UNIV RESEARCH REACTOR
- G Inspection reports, IE Bulletins & correspondence
- 8306090010 IE Info Notice 83-37, "Transformer Failure Resulting From Degraded Internal Connection Cables" Svc list encl. JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co. of New York, Inc. 243pp 18921 001 24X Fiche 50-000,83/06/13,8306090010.

DOCKET 50-213 HADDAM NECK PLANT

- F Security, medica), emergency & fire protection plans
- 8306160053 Rev 5 to Emergency Plan Implementing Procedura EPIP 1 5-8 "Emergency Operations Facility (EOF), Emergency Radiological Surveys."

Burveys."
CLOSIUS, O.J. Connecticut Yankee Atomic Power Co 83/04/20 16pp
18841.284. 24X Fiche 50-213,83/04/20,8306160053

8306010303 Forwards IE Insp Rept 50-213/83-11 on 830422-24 No

- 3305010303 Forwards It has kept 30-213/83-11 to 33-42-24 No noncompliance noted. MARTIN.T T Division of Engineering & Technical Programs 83/05/17 COUNSIL, W Q Connecticut Yankes Atomic Power Co Pap 18672 332 24% Fichs. 50-213, 83/05/17, 8306010303
- 8306150334 Releases public version of revised emergency plan implementing procedures FELTON.J.M. Division of Rules and Records. 83/06/06. Document Management Branch ip 18868-280 24X Fiche: 50-213, 83/06/06, 8306150334
- --8306150338 Forwards public version of revised emergency plan implementing procedures, including Procedures EPIP 1 5-10 re offsite emergency radiological surveys, EPIP 1, 5-20 re reentry & recovery & EPIP 1 5-30 re chemistry technician. GOUNBIL M. 9. Connecticut Yankes Atomic Power Co 83/04/22 ETSENNUT, D 0 Division of Licensing. 1p 18868-281. 24X Fiche: 50-213, 83/06/96, 8306150334.
- --8306150341 Public version of revised emergency plan implementing procedures, including Procedures EPIF 1 3-10 re offsite sergency radiological surveys, EPIF 1 5-20 re reentry & recovery & EPIF 1, 3-30 re chemistry technician.

 a Connecticut Yankes Atomic Power Co 83/04/08 EISENHUT, D Q Division of Licensing, 55pp 16868: 282, 24X Fichs. 50-213, 83/06/06, 8306150334.
- 8306230092 Releases public version of revised emergency plan implementing procedures. FELTON, J M Division of Rules and Records. 83/06/06 Document Management Brench 1p. 18951:135, 24X Fiche, 50-213, 83/06/06, 8306230092
- --8306230100 Forwards emergency plan implementing procedures, including Procedures EPIP 1.5-4 ms alert.EPIP 1.5-5 re site area seergency & EPIP 1.5-6 re general emergency. COUNSIL.H. 9. Connecticut Yankes Atomic Power Co. 83/05/09 DAVision of Licensing. 2p 18951.136. 24X Fichs: 50-213.83/06/06.8306230092.
- --B306230102 Public version of revised emergency plan implementing procedures including Procedures EPIP 1.5-4 re elect. EPIP 1.5-5 re site area swergency & EPIP 1.5-6 re general emergency.

 **Connecticut Yankee Atomic Power Co. B3/04/20, 177pp. 18751-138 24X Fiche: 50-213.82/06/06.8306230092
- 8305230426 Forwards safeguards contingency plan, Plan withheld, COWBIL.W.O. Connecticut Yankee Atomic Power Co. 83/06/08 Office of Nuclear Restor Regulation, Director 2pp. 18943, 209 24X Fiche: 80-213, 83/06/08, 8306230426.
- 8306280204 Forwards IE Insp Rept 50-213/83-10 on 830411-15 & 19-21.No noncompliance noted.

 MARTIN.T. Division of Engineering & Technical Programs. 83/06/13.

 COUNSIL.W 0 Connecticut Yentee Atomic Power Co. 2pp. 19014:166
 24% Fiche: 30-213.83/06/13,8306280204.
- --8306280210 IE Insp Rept 50-213/83-10 on 830411-15 & 19-21.No noncompliance noted Major areas inspected; follow up of emergency preparedness items from prior appraisal performed 81109-20 detailed in IE Insp Rept 50-213/81-14.
 84ITH.R.H., CROCKERH M. Region 1, Diffice of Director, 83/06/09, 10pp 19014:168, 24X Fiche:50-213,83/06/13,8306280204.

H General correspondence

- 8306060090 Requests ray to "cc" distribution list for NRR correspondence reflecting position & title changes within utils COUNSIL.W G Connecticut Yankee Atomic Power Co COUNSIL,W G. Northeast Utilities COUNSIL,W G Northeast Nuclear Energy Co. (subs of Northeast Utilities) 83/05/31 CLARK,R A Operating Reactors Branch 3 CRUTCHFIELD,D Operating Reactors Branch 5 3pp 18719 360 24X Fiche 50-000,83/05/31,8306060090
- O Advisory Committee on Reactor Safeguards reports & correspondence
- B306200153 Hinutes of ACRS Bubcommittee on BEP on Haddam Neck Nuclear Plant B30407 meeting in Washington DC of integrated plant safety assessment Proposed agenda & attendance list encl # ACRS — Advisory Committee on Reactor Safeguards B3/05/14 ACRS — Advisory Committee on Reactor Safeguards B3/05/14 ACRS — Advisory Committee on Reactor Safeguards 14pp 18909 150, 24X Fiche 50-213, 63/05/14, 8306200153
- 8305020075 Discusses ACRS 277th maeting on 830512-14 re results of Phase II of BEP as applied to facility Issue re protection against extreme external events requires resolution EBERBOLE, J C ACRB Advisory Committee on Reactor Safeguards 83705/17 PALLADINO. N J Commissioners 3pp 18701-283 24X Fiche: 50-213, 83705/17, 8304020095
- 8305180470 Advises that NRC will revise draft integrated plant SAR reflecting addl info provided by licenses, responding to recommendations & comments made by NRC consultants & incorporating licenses exhedular commitments DIRCKE, W J Diffice of the Executive Director for Operations 83/05/08 EBERSOLE, J C ACRB Advisory Committee on Reactor Safeguards App 18854 158. 24X Fiche 50-213,83/06/08,8306150490
- --8306010208 Summerizes ACRS 277th meeting on 630812-14 re SEP review of plant Several issues re protection against extreme external events unresolved EBERSOLE, J. C. ACRS Advisory Committee on Reactor Bafeguards 83/05/17 PALLADINO, N. J. Commissioners 3pp 18854-161 24X Fichs 50-213,83/06/08.8306150490
- P. Operating license stage documents & correspondence
- 8306010340 Forwards Rev 13 to comporate organization for nuclear incidents procedures manual table of contents & Rev 3 to CONI 4 02, "On-Call Manager of Radiological Consequence Assessment, Responsibilities & General Guidelines " W/o encl COUNSIL, W G , SEARS.C F. Connecticut Yankee Atomic Power Co. COUNSIL, W G , Northeast Nuclear Energy Co (subs of Northeast Utilities), 83/05/18 EISEMHUT.D C. Division of Licensing 1; 18682.271. 24% Fiche: 50-000.83/05/18,8306010340
- 830&0&0243 Forwards "Environ Qualification of Safety-Related Electrical Equipment." per 10CFRSO 49 Info responds to 821213 SER items re identification of equipment & preventive maint programs & 830404 ltr COUNSIL, N O , SEARS C F Connecticut Yankes Atomic Power Co 83/08/20 EISENHUT.D G Division of Licensing 86pp 18718 045 24X Fiche 50-213,83/05/20,6306060243
- 8306060207 Notifies that Apr 1983 rept, "Bhaking-Table Testing for Seismic Evaluation of Electrical Raceway Sys," applicable to facilities for SEP Yopic III-6 re seismic design NUREO-0824 k NUREO-0826 commitments partially satisfied.

 GOWNSIL-W G. Northwest Nuclear Energy Co (subs. of Northeast Utilities) COUNSIL-W G. CONNECTEUT Vankes Atomic Power Co. GOWNSIL-W Q. Northeast Utilities (SI/05/26 CRUTCHFIELD,D Operating Reactors Branch 5. 19 18727 295 24X Fiche 50-000,63/05/26.8306060207.
- 8306100114 Forwards listing of scheduled completion dates for 82P integrated assessment open issues requiring add1 action by util Each issue resolution documented in draft NUREG-0826 Topic VI-7 C. I resolution outlined COUNSIL, W. Q. Connecticut Yankee Atomic Power Co. 83/06/02, CRUTCHFIELD, D. Operating Reactors Branch S. 15pp 18802, 186 24X Fiche: 50-213, 83/06/02, 8306100114.
- 8306170231 Confirms applicability of Rev 2 to Mestinghouse WCAP-9558, "Mechanistic Fracture Evaluation of Reactor Coolant Pipe Containing Postulated Circumferential Through Wall Creck "Results still valid since loads below values used in rept COUNSIL.W.G. Connecticut Yankee Atomic Power Co. 83/06/08, CRUTCHFIELD, D Operating Reactors Branch 5. 1p 18882:325, 24X Fiche. 50-213, 83/06/08, 8306170231
- 8306160412 Forwards draft Rev 5 to "QA Program Topical Rept "
 GOUNSIL, M. G. Northeast Utilities Service Co. GOUNSIL, H.Q.
 Northeast Utilities 83/06/09, MURLEY, TE Region 1, Office of
 Director. Opp. 18859 090. 24X Fiche: 50-000, 83/06/09, 8306160412.

- --8306160424 Draft Rev 5 to "QA Program Topical Rept "
 * Northeast Utilities 83/06/07 135pp 18859.096 24X
 Ficha 50-000.83/06/09.8306160412
- 830&240200 Forwards listed revs to Corporate Organization for Nuclear Incidents procedure manual, per Section V of App E to LOGFRSO, W/o enci COUNSIL, W @ Connecticut Yankee Atomic Power Co COUNSIL, W @ Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL, W @ Northeast Utilities 83/06/17 EISENHUT, D @ Division of Licensing 2pp 18980 263 24X Fiche 50-000,83/06/17,8306240200
- 8306270318 Notification of 830707 meeting w/utils in Bethesda, MD to discuss NULAP-5 & FRAPCON-2 computer programs used in licensee small break LOCA analyses ERICKSON, P Operating Reactors Branch 5 83/06/24, CRUTCHFIELD, D Operating Reactors Branch 5 2pp 18994 039 24X Fiche 50-213, 63/06/24, 8306270318
- @ Inspection reports, IE Bulletins & correspondence
- 8304010303 Forwards IE Insp Rept 50-213/83-11 on 830422-24 No noncompliance noted MARTIN.T T Division of Engineering & Technical Programs 83/05/1 COUNSIL.W & Connecticut Yankas Atomic Power Co. 2pp 18672-332 24X Fichs: 50-213,83/05/17,8306010303
- --9306010306 IE Insp Rept 50-213/83-11 on 830422-24 No noncompliance noted Major areas inspected licensee annual emergency full-scale exercise performed on 830423 BMITH;R H Region I. Office of Director CROCKER;H W. Division of Engineering & Technical Programs 83/05/12 &pp 18672, 334 24X Fiche 50-213, 83/05/17, 8306010303
- 8305110458 IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in Hell Logging Device" Svc list encl TAYLOR, J M Division of Bafeguards & Inspection Programs (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 125pp 18831 043 24X Fiche 50-000,83/05/26,8305110458
- 8305110460 IE Info Notice 83-34, "Event Notification Info Worksheet."

 Bvc 11st encl

 JORDAN, E. L. Division of Emergancy Preparedness & Engineering
 Response (Post 830103) 83/05/26 Consolidated Edison Co. of New
 York, Inc 115pp. 18732 085 24X Fiche 50-000,83/05/26,8305110440.
- B305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods Withdrawn at BWRs" Svc list encl JGRDAN,E L. Division of Emergency Preparadness & Engineering Response (Post 830103) 83/05/31 Consolidated Edison Co of New York, Inc 116pp 1873R 208 24X Fiche: 50-000,83/05/31,8305110461
- B306170391 Responds to IE Bulletin 83-03, "Check Valve Failures in Raw Mater Cooling Bys of Diesel Generators" No check valves installed in loop of piping to diesel generators from svc water piping.

 COUNSIL, W. O. Northeast Nuclear Energy Co. (subs. of Northeast Utilities), COUNSIL, W. O. Connecticut Yankee Abomic Power Co. COUNBIL, W. O. Connecticut Yankee Abomic Power Co. COUNBIL, W. O. Northeast Utilities B3/05/31 MURLEY, T. E. Region 1, Office of Director 3pp. 18880.240, 24x Fiche: 50-000, 83/05/31, 830A(70391)
- 8306210098 Forwards IE Insp Rept 50-213/83-14 on 830509-13, No noncompliance noted.

 MARTINIT, Division of Engineering & Technical Programs 83/06/07, COUNSIL, W. G. Connecticut Yankee Atomic Power Co. 2pp. 18914-140 24% Fiche 50-213,83/06/07,8306210098
- --8306210103 IE Insp Rept 50-213/83-14 on 830509-13. No noncompliance noted. Major areas inspected post-refueling startup testing including control rod drop times, critical boron concentration, control rod worth & boron worth. PETRONE, C D , BETTENHAUSEN.L. Region 1, Diffice of Director. 83/06/02, 8pp. 18914:142, 24% Fiche 50-213,83/06/07,8306210098.
- B305110464 IE Info Notice 83-36, "Impact of Security Practices on Bafe Operations " Svc list encl, JORDAN-E.L Division of Emergency Preparedness & Engineering Response (Post 830103). 83/06/09, Consolidated Edison Co of New York, Inc 119pp. 16830:280, 24X Fiche. 50-000,83/06/09.8305110464.
- ₽305110470 IE Info Notice 83-38, "Defective Heat Bink Adhesive & Seismically Induced Chatter in Relays Within Printed Circuit Cards." Svc list encl.
 JORDAN L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13. Consolidated Edison Co of New York: Inc. 118pp. 18920:225. 24X Fiche: 50-000, 83/06/13, 8305110470.

- 8306090010 IE Info Notice 83-37. "Transformer Failure Resulting From Degraded Internal Connection Cables." Svc list encl. JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Conscil
- 8304280204 Forwards IE Insp Rept 50-213/83-10 on 830411-15 & 19-21 No noncompliance noted
 MARTIN:T T Division of Engineering & Technical Programs 83/04/13 CDUNSIL:N G Connecticut Yankee Atomic Fower Co. 2pp 19014:166, 24X Fiche 50-213.83/04/13.8306280204
- --8306280210 IE Insp Rept 50-213/83-10 om 830411-15 & 19-21 No noncompliance noted Major areas inspected follow up of amergency preparedness items from prior appraisel performed 811109-20 debailed in IE Insp Rept 50-213/81-14 SMITH.R H. CROCKER.H W. Region 1, Df41ce of Director. 83/06/09.10pp 19014 168. 24X Ficher 50-213/83/06/13/8306280204.
- 8306200397 Ack receipt of 830408 ltr informing NRC of steps taken to correct violations noted in IE Inap Rept 50-213/83-03. Rev 4 to 830324 Surveillance Procedure SUR 5 1-104 satisfies Tech Spec 4 2. Notice of violation withdrawn.

 MARTIN.T T. Division of Engineering & Technical Programs, 83/06/15 COLMBIL.M.9. Connecticut Yankse Atomic Power Co 2pp. 18899: 047. 24X Fiche, 50-213. 83/06/15.8306200387.
- --8306200391 Responds to NRC 830309 ltr re violations noted in IE Insp. Rept 50-213/83-03 Surveillance Procedure SUR 5, 1-104 meets intent of Tech Spec 4 2, Table 4. 2-2 re min equipment checks. No violation exists.

 COUNSIL, N 9 Connecticut Yantee Atomic Power Co. 83/04/08 MARTIN, T. T. Division of Engineering & Technical Programs. 3pp. 18899, 049. 24X Fichs. 50-213, 83/04/15, 8306200387
- 8306270001 Forwards "Connecticut Yankee 1983 Outage Inservice Insp Rept." QRAVES,R H Connecticut Yankee Atomic Power Co 83/06/17. ALLAN.J.M Region 1. Office of Director. 1p. 18988-160 24X Fiche 50-213,83/06/17,8306270001
- --8306270004 "Connecticut Yankee 1983 Outage Inservice Insp Rept." DELAMRENGE: J. L. Connecticut Yankee Atomic Fower Co. 83/06/17. 83pp. 1898: 161 24X Fiche: 50-213.83/06/17.8306270001.
- 8305110475 IE Info Notice 83-40. "Need to Environmentally Qualify
 Epoxy Grouts & Sealers." Syc list encl.
 JORDAN E L. Division of Emergency Preparadness & Engineering
 Response (Fost 830103) 83706/22 Consolidated Edison Co. of New
 York, Inc. 115pp. 19021,179. 24X Fiche: 50-000,83/06/22,8305110475.
- B305110477 IE Info Notice 83-41, "Actuation of Fire Suppression Sys Causing Inoperability of Safety-Related Equipment " Syc list enc! JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) B3/06/22. Commolidated Edison Co. of New York, Inc. 120pp 18997:007. 24X Fiche: 50-000, 83/06/22, 8305110477.
- 8305110479 IE Info Notice 83-42, "Reactor Mode Switch Halfunctions."

 8vc list encl
 JORDAN,E L. Division of Emergency Preparedness & Engineering
 Response (Post 830103). 83/06/23. Consalidated Edison Co. of New
 York, Inc. 116pp. 18996; 242. 24X Fiche; 50-000, 83/06/23, 8305110479.
- 8305110483 IE Info Notice 63-43, "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints." Svc list encl JORDAN, E.L Division of Emergency Prepersedness & Engineering Response (Post 830103), 83/06/24, Conselidated Edison Co. of Naw York, Inc. 114pp. 17046:277, 24X Fiche 50-000,83/06/24.8305110483.
- R. Pariodic operating reports & related correspondence
- 8304020248 Monthly operating rept for Mar 1983. W/830414 ltr. ELMS.A., GRAVES.R.H. Connecticit Yanker Atomic Power Co. 83/04/14. 11pp. 18690: 279. 24X Fiche: 50-213. 83/04/14. 830402068.
- 8306160459 Monthly Operating Rapt 83-4 for Apr 1983, W/830514 ltr. ELMB.A., ORAVES.R.H. Connecticut Yankse Atomic Power Co. 83/04/30. Office of Resource Management, Director. 10pp. 18863:058. 24X Fiche: 50-213, 83/04/30, 8306160459
- 8 Reportable occurrences, LERs & related correspondence
- 8306170051 LER 83-031/03L-0: on 830504, during surveillance testing, HP61 pump A failed to reach shutoff head of 1,400 psi,psr Procedure 8UR 5,1-4-6 Causad by incorrect acceptance criteria. Procedure revised W/830531 ltr. CL091UB; 0 J.; ORAVES.R.H. Connecticut Yankee Atomic Power Co. 83/05/31. ALLAN,J.H. Region 1, Office of Director. 3pp. 18878; 278. 24X Fichs: 50-213,83/05/31,8306170051.

- 8306170301 LER 83-010/03L-0, on B30807, following svc water low flow alarm, rvc water filters indicated 0 psi Gaused by filter B plugging up w/river sitt due to rain & high river conditions. Filter A cleaned H/B30831 ltr CL081US.0 J., GRAVES.R H Connecticut Yankes Atomic Power Co 83/05/31 ALLAN.J H Region i. Office of Director 3pp 18878 194 24% Fiche 50-213, 83/05/31, 8306170301
- 830&170347 LER 83-009/03L-0 on B30505, charging pump A could not be manually rotated for routine surveillance test Caused by binding due to solidified horic acid. Pump uncoupled from motor & turned over N/800531 ltr. CLOSIUS: 0 J. GRAVEE.R H. Connecticut Yankee Atomic Power Co B3/05/31 ALLAN.J M. Region J. Office of Director Jpp 18881 022 24X Fiche.50-213.83/05/31,8306170347
- 8305270361 LER 83-012/03L-0 on 830517, following removal of diese1 generator E02A for normal preventative maint; generator load unable to increase above 2,800 kH. Caused by diese1 generator governor voltage setting drift N/830614 ltr CLOBIUS: GRAVES.R H Connecticut Vantee Atomic Power Co B3/06/14. ALLANJ.J. H Region 1. Office of Director 2pp 18973 186 24X Fiche 50-213,83/06/14,8306270361
- 8306270228 Part 21 rept re improper latching between control rod drive shafts & control rod cluster assemblies in reactor vessel initially reported on 830620 Insp underway CDUNSIL.N 0 Northeast Nuclear Energy Co (subs of Northeast Utilities). 83706722 DEYOUNG.R C Director's Office. Office of Inspection and Enforcement 3pp 18988 237. 24X Fiche 50-213.83706722.8306270228

V Operator Examinations

B305i40104 Extends invitation to attend 830527 meeting in King of Prussia, PA to discuss transfer of reactor operator licensing function from Bathesda. MD to Region I ofc STAROBTECKI.R Division of Project & Resident Programs. B3/05/09. COUNSIL.W G Connecticut Yankse Atomic Power Co 2pp 18839 080. 24X Fiche 50-213.83/05/09.8305140104

DOCKET 50-219 OYSTER CREEK NUCLEAR POWER PLANT

- F Security, medical, emergency & fire protection plans
- 8306200340 Forwards draft objectives for annual NRC/FEMA observed exercise to be conducted on 830524 Exercise will address deficiencies identified in 820316 exercise to will test integrated capability for emergency response FIEDLER.P.B General Public Utilities QPU Service Corp. 63/02/14 MARTIN.T T Division of Engineering t Technical Programs 7pp. 18900 201 24X Fiche 50-219,83/02/14,8306200340
- 9304040217 Forerds IE Insp Rept 50-219/83-11 on 830405-0502 No noncompliance noted and project the sident Programs 63/05/83 FIEDLER.P.B. Division of Project the Resident Programs 63/05/83 FIEDLER.P.B. General Public Utilities GPU Service Corp 2pp. 18732, 335 24K Fiche: 50-219, 83/05/23, 8346040217.
- ~-8306060220 IE Insp Rept 50-219/83-11 on 830405-0502 No noncompliance noted Major areas inspected follows of previous insp findings, review of plant operations log is record review, plant tours, physical security is radiation protection CCMGILLC: THOMAS.U. MEIMIO.R. Region 1. Office of Director, 83/05/17 9pp. 18732, 337. 24X Fishe 50-219,83/05/23,8306060217.
- 8304090041 Forwards IE Enforcement Conference Rept 50-219/83-12 on 830418 Meeting improved util understanding of NRC concerns re violations noted in IE Insp Rept 50-219/83-07 ALLANJ. H. Region 1, Office of Director. 83/05/26 FIEDLER, P. B. General Public Utilities GPU Service Corp. 2pp. 18793-280. 24X Fiche: 50-219,83/05/26,8304090041.
- --8306090044 IE Enforcement Conference Rept 50-219/83-12 on 830418 Major areas discussed ARC concerns re recent insp findings concerning licenses implementation & mpt of physical security program Bafeguards info deleted (ref 100FR73, 21) BAILEY,R J > 60DY, A T. Region 1, Office of Director, 83/05/18, 3pp 18793-282, 24X Fiche 50-219,83/05/26,8306090041.
- 8306210145 Discusses IE insp on 830314-17 & forwards notice of violation & proposed imposition of civil penalty. Violation involves failure to control access to protected area from outside protected area.

 ALLANJUM Region 1: Office of Director. 83/06/01. FIEDLER, P. B. General Public Utilities OPU Bervice Corp. 3pp. 18914:197. 24X Fiche 50-219.83/06/01.8306210145

- --8306210149 Notice of violation & proposed imposition of civil penalty in amount of \$40,000 Noncompliance noted degradation of portions of protected area barrier Safeguards info deleted (ref 10CFR73 21)
 ALLAN.J.M. Region 1, Office of Director 83/04/01 4pp 18914 200 24% Fiche 50-219,83/04/01,8306210145
- 8306090024 Releases public version of revised emergency plan implementing procedures FELTON.J M Division of Rules and Records 83/06/06 Document Management Branch ip 18797 114 24X Ficha 50-219,83/06/06,8306090024.
- --830A090027 Forwards public version of revised emergency plan implementing procedures including Procedures EPIP-5 regeneral emergency, EPIP-1 re classification of emergency canditions & EPIP-3 re alert FIEDLER.P B General Public Utilities GPU Service Corp 83/05/17 Region i. Office of Director ip 18797 115, 24% Fiche: 50-219.83/06/06.8306090024
- --9306090031 Public version of revised emergency plan implementing procedures, including Procedures EPIP-5 re general emergency, EPIP-1 re classification of emergency conditions & EPIP-3 re alert

 9 General Public Utilities GPU Service Corp 83/05/05 232pp 18797 116 24% Fiche 50-219,83/06/06,8306090024
- 8304170204 Ack receipt of operational GA plan for TMI-1 & Oyster Creek under review by GA Branch, per 10CFR50 54. Future revs/changes to program will be reviewed by Engineering Programs Branch. Region I

 MARTIN.T T Division of Engineering & Technical Programs 83/06/13

 HUKILLH D Oeneral Public Utilities QPU Service Corp 2pp 18882.304 24X Fiche 50-000.83/06/13.8306170204

H General correspondence

- 8306130174 Responds to 830323 ltr addressed to WJ Dircks & forwards "Priority Concerns of Licensed Nuclear Operators at TMI & Oyster Greek & Buggested Action Steps" & "Review of Current & Projected Expenditures & Manpower Utilization for OPU "CUNNINGHAM.Q.H Office of the Executive Legal Director 83/06/12 LEWIS, M 2pp 18851 001 24X Fiche 50-000.83/06/13.8306150174
- --8305150185 "Revism of Current & Projected Expenditures & Manpower Utilization for OPU Nuclear Corp "

 * Basic Energy Technology Associates 83/02/28 161pp 18851.059 24X Fiche 50-000,83/06/13.8306150174

I. Financial information

- 8305020461 Forwards Annual Financial Rept 1982 FIEDLER,P B General Public Utilities - OPU Service Corp 93/04/2: Office of Nuclser Reactor Regulation, Director ip 18281.07i 24X Fiche-50-219,83/04/27.830502046i
- P. Operating license stage documents & correspondence
- 830&0i0404 Forwards operational GA plan for TMI-1 & Dyster Creek Nuclear Stations.per iOCFR50 54(a)(2), W/o and HUKILL.H General Public Utilities GPU Service Corp 83/05/23 Region 1. Office of Director 1p. 18679;314 24X Fiche 50-000,83/05/23.830&010404.
- 8306140642 Forwards evaluation of BWR Owners Group generic response to NUREG-0737. Item II K 3.18. "Automatic Depressurization Sys Logic Mods." Two of seven BWR Owners Group alternatives acceptable Selection of option within 45 days requested CRUTCHFIELD. D Operating Reactors Branch 5 83/06/03 FIEDLER, P & General Public Utilities GPU Hervice Corp 2pp. 18833'264 24% Fiche 50-217,83/06/03,8306140642
- B304130384 Bubmits findings re integrated assessment of SEP Topic III. 3.C. "Flooding Potential & Protection Requirements " Sill & entry floor slevations not susceptible to flooding FIEDLER.P B. General Public Utilities GPU Bervice Corp. B3/06/06 CRUTCHFIELD, D. Operating Reactors Branch 5. 2pp 18822 342 241 Fichs. 50-219, 83/06/06.8306130384.
- B306200157 Advises that 821210 Tech Spec Change Request 100 for shubber surveillance not fee exempt Remittance requested DIOGB.R.H License Fee Management Branch 83/06/13, FIEDLER,P.J. General Public Utilities ~ GPU Service Corp. 1p 18908-270 24X Fiche. 50~219, 83/06/13, 8306200157

DOCKETED ITEMS

- 8306280406 Estimates that dilution pump sys renovation program will be completed by Nov 1983, based on anticipated receipt date of diffusers & required installation time FIEDLER.P B General Public Utilities CPU Service Corp 83/06/15 ORIER.B H Region 1, Office of Director 2pp 19014 057 24X Fiche 80-219.83/06/15.8306280406
- 8306210158 Forwards order confirming commitment to implement post-TMIrelated Items II B 3, "Post-Accident Bampling" & II E 4 2 7, "Isolate Purge & Vent Valves on Radiation Signal " CRUTCHFIELD, D Operating Reactors Branch 5 83/06/17 FIELDER, P B General Public Utilities - OPU Service Corp 3pp 18916 352 24X Fiche 50-219,83/06/17,8306210158
- ~-8306210166 Order confirming licensee commitments on post-TMI-related Items II B 3, "Post Accident Sampling" & II E 4 2, "Isolate Purge & Vent Valves on Radiation Signal"

 E18ENHUT, D 0 Division of Licensing B3/06/17 General Public Utilities GPU Bervice Corp Spp 18916 335 24%
 Fiche 50-219, 63/06/17, 8306210158
- 8306220074 Forwards safety evaluation & technical evaluation rept re util response to 801222 generic ltr. "Control of Heavy Loads " Guidelines in NUREG-0612 satisfied & Phase acceptable CRUTCHFIELD. D Operating Reactors Branch 5 83/06/21 FIEDLER,P General Public Utilities GPU Service Corp 2pp 18726 060 24 Fiche 50-219,83/06/21,8306220074
- ---8306220083 Bafety evaluation ro util response to Generic Technical Issue A-36, "Control of Heavy Loads " NUREO-0612 guidelines satisfied Phase 1 acceptable * Office of Nuclear Reactor Regulation, Director 83/06/21 2pp 18926 062 24X Fiche 50-219.83/06/21.8306220074
- --8306140424 "Control of Heavy Loads (C-10), JCP&L Dyster Creek Nuclear Power Plant: "technical evaluation rept BDMDERGER, C. Franklin Institute/Franklin Research Center NRC-03-81-130 TER-C5506-377 83/06/10 81N9H; A. NRC - No Detailed Affiliation Oiven 32pp 18726-064 24X Fiche 50-219,83/06/21,8306220074
- 8306240854 Advises that proposed schedule & interim resolution remonitoring & annunciation of dc power sys acceptable.

 Verification of interim resolution & long-term mod will be referred to IE Description of battery integrity requested CRUTCHFIELD.D. Operating Reactors Branch 5 83/06/22 FIEDLER, P. B. General Public Utilities QPU Bervice Corp 4pp 18781 317 24X Fiche 50-217,83/06/22,8306240254
- 8306280155 Informs that 830606 response to open item in integrated plant BAR (NUREG-0822) re flooding elsvation acceptably resolves item Corrective actions re diesel generator bldg entrances also acceptable.
 CRUTCHFIELD, D. Operating Reactors Branch 5 83/06/23 FIEDLER, P. B. General Public Utilities QPU Bervice Corp. 2pp. 19014:316 24X Fiche 50-217,83/06/23,8306280155
- 8306280176 Forwards order confirming 811224 commitment to install permanent screm discharge sys mods prior to operation in Cycle 10 Proposed model Tech Specs also encl CRUTCHFIELD, D Operating Reactors Branch 5 83/06/24 FIEDLER, P.B. General Public Utilities OPU Service Corp. 2pp 19014:239, 24X Fiche 50-219,83/06/24.8306280176
- --B3062801B1 Order confirming util B11224 commitments to install long-term BWR scram discharge sys mods in conformance w/NRC generic SER before operation in Cycle 10 EISENMUT, D Division of Licensing B3/06/24. General Publi Utilities OPU Service Corp 35pp, 19014-241 24X Fiche 50-219, B3/06/24, B306280176
- 8306270538 Requests methodology & acceptance criteria to be used in evaluating anchorage of 4:160-volt switchgear panels by 831;30. Review will be included in integrated plant SAR suppl CRUTCHFIELD, Operating Reactors Branch 5, 83/06/24. FIEDLER, P. B. General Public Utilities GPU Bervice Corp 2pp. 19053.029. 24X Fichs. 50-219, 83/06/24, 8306290538

G. Inspection reports, IE Bulletins & correspondence

8306210480 Ack receipt of 830322 payment of civil penalties imposed by 830215 order Corrective actions described in 821230 correspondence will be examined during future inspanance AXELRAD, J. A. Enforcement Staff. 83/03/24 FIEDLER, P. B. General Public Utilities - OPU Service Corp. 2pp. 18935:343 24X Fiche. 50-217, 83/03/24, 8306210450

- 8304020445 Forwards IE Insp Rept 50-219/83-10 on 830406-08 No noncompliance noted MARTIN.T Division of Engineering & Technical Programs 83/05/20 FIEDLER,P B General Public Utilities QPU Service Corp 18694 080 24x Fiche 50-219,83/05/20,8306020445
- --8306020447 IE Insp Rept 50-219/83-10 on 830404-09 No noncompliance noted Major areas inspected implementation of radiation protection program during outage, including procedure implementation & exposure control HHITE, J R , MCBRIDE, M H , SHANBAKY, M M Region 1. Diffice of Director 83/05/13 6pp 18694 082 24X Fiche 50-219,83/05/20,8306020445
- 8306060217 Forwrds IE Insp Rept 50-219/83-11 on 830405-0502 No noncompliance noted STAROSTECKI, R Division of Project & Resident Programs 83/05/23 FIEDLER, P B General Public Utilities QPU Service Corp 2pp 18722 335 24X Fishe 80-219,83/05/23,8306060217.
- --8306060220 IE Insp Rept 50-219/83-11 on B30405-0502 No noncompliance noted Major areas inspected followup of previous insp findings review of plant operations log & record review, plant tours, physical security & radiation protection COMPILL.C . THOMAS, J . KEIMIO.R R Region 1, Office of Director 83/05/17 9pp 18792 337 24X Fiche 50-219.83/05/23.8306060217
- 8306020341 Forwards supplemental response to IE Bulletin 82-03, "Stress Corrosion Cracking in Thick-Hall, Large-Diameter Stainless Steel Recirculation Piping at BLR Plants "
 FIEDLER, P.B. General Public Utilities ~ GPU Service Corp. 83/05/25, Ragion I. Office of Director 27pp 18474:271 24X
 Fiche 50-217,83/05/25,8306020341
- 8305110458 IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in Well Logging Device " Svc list encl. TAYLOR. J. M Division of Bafaguards & Inspection Programs (Post 830103) 83/05/26 Consolidated Edison Co. of New York, Inc. 125pp 18831:043 24X Fiche 50-000.83/05/26.8305110458.
- 8305110460 IE Info Notice 83-54, "Event Notification Info Worksheet."
 Byc list encl
 JORDAN, E. Division of Emergency Preparadness & Engineering
 Response (Post 830103) 83/03/26 Consolidated Edison Cp of New
 York, Inc 115pp 18732.088, 24X Fiche, 50-000,83/05/26,8305110460,
- 8306010066 EN-83-037 on 830601, notice of violation & proposed imposition of civil penalty in amount of #40,000 to be issued. Action based on failure to control access into protected area & to properly handle intrusion alarms.
 RDSANO,R. AXELRAD, J. Director's Office. Office of Inspection and Enforcement 63/05/26 ip 18674-088 24X Fiche 50-219,83/05/26,830610064
- 8304090041 Forwards IE Enforcement Conference Rept 50-219/83-12 on B30418 Meeting improved util understanding of NRC concerns re violations noted in IE Insp Rept 50-219/83-07 ALLAN, J H Region 1, Office of Director B3/05/26 FIEDLER, P. B. Ceneral Public Utilities GPU Service Corp 2pp. 18793, 280, 24X Fiche 50-219, 83/05/26, 8304090041
- --B306090044 IE Enforcement Conference Rept 50-217/83-12 on B30418, Major areas discussed, NRC concerns re recent insp findings concerning licensee implementation & mat of physical security program Safeguards info deleted (ref lOCFR73, 21), BAILEY, R J , 90DY, A T Region 1, Office of Director, 83/05/18, 3pp 18793-282 24% Fichs: 50-217.83/05/28.8386070041.
- 8306210085 Responds to IE Bulletin 83-03 re check valve failures in raw water cooling sys of diesel generators No check valves in closed loop diesel segime cooling sys for either diesel generator at plant, Bulletin not applicable.
 FIEDLER,P S. General Public Utilities QPU Service Corp Region 1. Office of Director, 2pp. 18914-136, 24X Fiche. 50-219, 83/05/27, 8306210085.
- 8305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods Withdrawn at BWRs." Svc list encl JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/31. Consolidated Edison Co of New York, Inc. 116pp. 18732.208, 24% Fiche 50-000,83/05/31,8305110461.
- 8304210145 Discusses IE insp on 830314-17 & forwards notice of violation & proposed imposition of civil penalty. Violation involves failure to control access to protected area from outsids protected area ALLAN, J. M. Region 1. Office of Director 83/06/01. FIEDLER, P. B. General Public Utilities OPU Bervice Corp. 3pp. 18914-177. 24% Fiche. 50-219,83/06/01.8306210145

- --8306210149 Notice of violation & proposed imposition of civil penalty in amount of \$40,000 Noncompliance noted degradation of protected area barries Safeguards info deleted (ref 10CFR73 21)
 ALLANJ M Region 1, Office of Director 83/06/01 App 18914,200 244 Fichs. 50-219,83/06/01.8306210145
- B306090320 Forwards request for add1 info re IE Bullotin 80-ii,
 "Matonry Wall Design" Info requested within 30 days of ltr
 receipt
 CRUTCHFIELD.D Operating Reactors Branch 5 83/06/08 FIEDLER,P B
 General Public Utilities GPU Service Corp 5pp 18795 170 24X
 Fiche 50-219,83/06/08.8306090320
- 8306160250 Ack receipt of 830506 ltr informing NRC of steps taken to correct violations noted in IE Imag Rept 50-219/83-04
 STAROSTECKI.R Division of Project & Resident Programs 63/06/08
 FIEDLER, P B General Public Utilities QPU Bervice Corp 2pp
 18861 252 24X Fiche 50-219.83/06/08.8306160250
- --8306160258 Responds to NRC 830406 ltr re violations noted in IE Insp Rept 50-217/83-04 Corrective actions add1 authorized escort provided for visitor & watchean reinstructed an proper package search techniques. FIEM.ER/P B General Public Utilities - GPU Service Corp 83/05/06 BIARGBTECKI, R. Division of Project & Resident Programs App 18861 254 24X Fiche 50-217,83/06/08,8306160250
- 8303110444 JE Info Natice 83-35, "Impact of Security Practices on Safe Operations " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83706/07 Consolidated Edison Co of New York, Inc. 117pp 18830 280 24X Fiche 50-000.83/06/07.8305110464.
- 8305:10470 IE Info Notice 83-30, "Defective Heat Bink Adhesive & Saimmically Induced Chatter in Relays Mithin Printed Circuit Cards " Svc list encl.

 JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co. of New York, Inc. 118pp 18920.225 24X Fichs 50-000,83/06/13,8305110470
- 830A090010 IE Info Notice 83-37, "Transformer Failure Resulting From Degraded Internal Connection Cables" Svc list and JORDAN.E.L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co. of New York, Inc. 243pp 18921 001 24X Fiche. 50-000, 83/06/13.8306090010
- 8305110475 IE Info Notice 83-40. "Need to Environmentally Quality
 Epozy Grouts & Sealers " Syc list encl
 JORDAN, E. L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/06/22 Consolidated Edison Co of New
 Yort, Inc. 115pp 17021.179. 24X Fiche.50-000.83/06/22.8305110475
- B305i10477 IE Info Notice B3-41, "Actuation of Fire Buppression Bys Causing Inoperability of Bafety-Related Equipment " Svc list encl. JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post B30103) B3706/22 Consolidated Edison Co of New York, Inc. 120pp 18997-007 24X Fiche 50-000,83/06/22,8305110477
- 8305110479 IE Info Notice 83-42, "Reactor Mode Switch Melfunctions."
 Bvc list encl
 JORDAN. E. Division of Emergency Preparedness & Engineering
 Response (Post 830103). 83/06/23 Consolidated Edison Co of New
 York, Inc 116pp. 18996 242 24X Fiche 80-000, 83/06/23, 8305110479.
- 8305110483 IE Info Notice 83-43, "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints," Svc list encl. JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/24 Consolidated Edison Co. of New York, Inc. 1168p. 19046-297 24X Fiche 50-000, 83/06/24, 8305110483
- R. Periodic operating reports & related correspondence
- 8304020070 Monthly operating mept for Mar 1783 W/830418 ltr FIEDLER,P B , BARAN.R. General Public Utilities - GPU Service Carp. 83/04/07 iipp 18491-187. 24X Fiche 50-219,83/04/07.8304020070.
- 830&060252 "Annual Rapt for Dec 1981 Nov 1982 on Brudy of Hoodborer Populations in Relation to Oyster Creek Generating Station "
 M/830523 It of HOORE, C. I. HOORATH, R.A. Battelle New Empland Marine Research Laboratory. 83/05/15 150pp 18727.044. 24X
 Fiche-36-219,83/05/25,8306060252
- 8304090235 "Study of Woodborer Populations in Relation to Oyster Creek Gamerating Station." progress rapt for 32nd quarter ending 830420 W303601 1tr
 HILLMAN.R.E., BELMORE.C.I. Battelle New England Marine Research Laboratory. FIEDLER.P B Gameral Public Utilities OPU Service Corp. 15193. 83705/31 Region i. Office of Director 25pp 18797.019 24X Fiche: 50-219, 83/05/31, 8304090235.

- S Reportable occurrences, LERs & related correspondence
- 8306020398 LER 83-007/03L-0 on 830418, during monthly 10 h operability test of standby gas treatment sys II, high differential pressure across both HEPA filters observed Caused by plugging of filters Filters replaced W/830520 ltr HAGER, C., FIEDLER, P. B. General Public Utilities GPU Service Corp 83/05/20 Region i, Office of Director 4pp 18695 009 24X Fiche 50-219, 83/05/20, 8306020398
- 830&020353 Updated LER 82~055/01X-i on 82i115, stack gas sample pump is thermal overload protector tripped Pump failed to produce normal flow when restarted Caused by impeller vanes Pump is rebuilt H/830825 Itr CHARTERINA.J., FIEDLER.P.B. General Public Utilities OPU Service Corp. 83/05/25 Region i. Office of Director 4pp 18694 324 24X Fiche 50-219,83/05/25,8306020353
- 830&030269 LER 82-062 has been canceled. * Jersey Central Power & Light Co 83/05/31 Region 1. Office of Director 1p 18703 343. 24X Fiche 50-219,83/05/31,830&0302&9
- 8306140022 PNO-I-83-056: on 830606, chloring gas released into atmosphere for approx 15 minutes Causad by leak in 3/4-inch plastic pipe on outlet of chlorination evaporator All fuel removed from vessel & vessel drained, COWGILL, CONNER Region i. Office of Director. 83/06/07 i 18838:234 24% Fichs 50-219,83/06/07,8306140022
- V Operator Examinations
- 8306i40371 Extends invitation to attend 830627 meeting in King of Prussis.PA to discuss transfer of reactor operator licensing function from Bethesda.MD to Region I ofc STAROBIECKI,R. Division of Project & Resident Programs 82706/09 FIEDLER.P.B General Public Utilities GPU Service Corp. 2pp 18832.121 24X Fichs 50-219.83/06/09.8306140371
- DOCKET 50-220 NINE MILE POINT NUCLEAR STATION, UNIT 1

 F Becurity, medical, emergency & fire protection plans
- 8306060223 Forwards IE Insp Rept 50-220/83-08 on 830401-30 % motice of violation STARRATECKI, R. Division of Project & Resident Programs 83/05/23 RHODE, 9 K Niagara Mohawk Power Corp 2pp 18728.014 24X Fiche:50-220,83/05/23,8306060223
- --8306060224 Notice of violation from insp on 830401-30 * Region 1, Office of Director 83/05/23 1p 18728 014 24X Fiche: 50-220, 83/05/23, 8304060223,
- --8304040227 IE Inep Rept 50-220/83-08 on 830401-30. Noncompliance noted failure to control use of Jumpers. HUDSON, S.D.: DOERFLEIN, L.T.: MCRREARTY, R.A. Region 1. Office of Director 83/05/18 9pp 18728.015. 24X Fiche 50-220, 83/05/23, 8304040223
- 8306010360 Bubmits alternative solutions to alleviate potential spurious operation of valves listed in 821203 suppl to 821001 App R submittal Requirements for valves 40-30, 40-31 & 38-02 not required. Annual, C.V. Niagara Mohawk Power Corp 83/05/26, VASSALLD, D. B. Operating Reactors Branch 2, 2pp 18681 361, 24X Fiche, 50-220, 83/05/26, 8306010360.
- 8306010258 Informs that recent App R-related mod resulted in 10% of independence of two remote shutdown panels Change to panels does not alter conclusions re safe shutdown capability per fire area or subarsa LEMPOES.T.E. Nisgara Mohawk Power Corp 83/05/27 VASSALLO, D B. Operating Reactors Branch 2. ip. 18672.291. 24X Fiche.50-220.83/05/27.8306010258.
- 8304030352 Advises that beckup metaorological instrumentation will not be installed at facility.per NUREO-0737. Suppl 1. Software problems w/meteorological dispersion modeling unresolved. Interim sys described in 820401 Itr utilized. LEMPOES.T.E. Niagara Mohawk Power Corp. 83/05/27. VASBALLO, D.B. Operating Reactors Branch 2. ip 18706-126. 24X Fiche: 50-220, 83/05/27, 8306030352.
- 8306150626 Forwards exemption from schedular requirements of 10CFR50, App E. Bection IV. F re annual emergency preparedness exercise, par 830309 request Exemption permits exercise to be conducted during while 6 830928 VASBALLO, D B. Operating Reactors Branch 2. 83/05/27. RHODE, Q. K. Niegara Mohawk Power Gerp. 2pp. 18967. 273. 24X

- --8306150428 Exemption from schedular requirements of 10CFR50, App E, Section IV F re annual emergency preparedness exercise PURPLE, R A Division of Licensing 83/05/27 Niegara Hohawk Power Corp 4pp 18847 275 24X Fiche 50-220,83/05/27, 8306150626
- 8306300241 Forwards diagram depicting proposed location of new training ctr per Suppl 1 to NUREO-0737. Ctr will house new emergency operations facility & is tentatively scheduled for completion in Spring 1984
 MANGAN, C V Niagara Mohawk Power Corp 83/06/24 VASSALLO, D B Operating Reactors Branch 2 2pp 19122 309 24X
 Fiche 50-220,83/06/24,8306300241

J Insurance & indemnity information

- 8306020158 Forwards Endorsement 82 to NELIA Policy NF-161 RUSHMORE, J W Niagara Mohawk Power Corp 83/05/27 SALTZMAN, J Assistant Director for State & Licansee Relations 2pp 18690 354 24X Fiche 80-220,83/05/27,8306020158.
- 8306020199 Forwards Endorsement 68 to MAELU Policy MF-46 RUSHMORE, J W Niagara Mohawk Power Corp. 83/05/27. SALTZMAN, J Office of State Programs, Director, 2pp 18690 252 24X Fiche 50-220.63/05/27,8306020189

P. Operating license stage documents & correspondence

- 8306010063 Submits clarification to 830425 response to Item 7 of Generic Ltr 83-02 re NURICO-0737 Tech Specs Failures of valves to close & challenges to valves to be reported per Tech Spec 6 9 2 & 6.9.16, respectively MANQAN, C. V. Niagars Mohawk Power Corp. 83/05/26 VABSALLO, D. B. Operating Reactors Branch 2 ip 18674-087 24X Fiche 50-220, 83/05/26, 8306010063.
- B306070430 Informs that review of submittals re-stress reanalysis of replaced primary sys piping completed Reanalysis results acceptable. VABSALLO, D. B. Operating Reactors Branch 2 83/05/27, RHODE, O. K. Niagars Mohewk Power Corp. 2pp. 18815-240, 24X Fiche-50-220.83/05/27.8306090430
- --8306070432 Safety evaluation supporting results of stress reanalysis of primary sys piping replacement
 * Office of Nuclear Reactor Regulation, Director, 83/05/27, 10pp 18815 242 24X Fichs 50-220,83/05/27,8306090430
- 8306070034 Notifies that Tech Specs for installation of Class IE protection packages on reactor protection motor generator sets will be submitted within 60 days of NRC concurrence w/proposed mod submitted on 321201.

 MANQAN, C. V. Niagama Mohawk Power Corp. 83/06/01. VASSALLO, D. B. Operating Reactors Branch 2 ip. 18739-336 24X Fiche 50-220.83/06/01.8306070034.
- 8306150631 Forwards request for add1 info re 821201 response to Multiflant Action Item C-11 on BHR reactor protection sys.in order to complete review. Info must be received within 45 days of ltr receipt. VASBALLO, D. B. Operating Reactors Branch 2 83/06/03 RHODE, G. K. Niagara Mohawh Power Corp. 4pp. 18867.343 24X Fiche 50-220,83/06/03.8306150631
- 8306100143 Requests add1 time to complete control room habitability study per TMI Item III. D. 3 4 Assumptions used performing control room dose assessment reexamined. Study completion expected by Dec 1983.

 MANGAN.C. V Niagara Mohawk Power Corp 83/06/06. VASSALLO, D. B. Operating Reactors Branch 2. 2pp. 18801:209. E4X Fiche: 50-220, 83/06/06, 8306100143.
- B306280509 Suppl to 780321 application to amend License DPR-63, revising Tach Spec Sections 5.5 & 5 d rm spent fuel pool. Also clarifies info in 781220 & 21 ltrs & forwards spent fuel pool structural analysis.

 MANGAN, C. V Niagara Mohawk Power Corp. B3/06/24. VABBALLD, D. B. Operating Reactors Byranch 2 Sipp. 19017-241. 24X Fiche: 50-220, 83/06/24, 8306280509.
- --8306280513 Proposed Tech Spec Sections 5 % 5.6 re spent fuel pool * Niegera Mohauk Power Corp. 83/06/24. 16pp. 19017; 272. 24X Fiche 50-220, 83/06/24, 8306280509.

Q. Inspection reports. IE Bulletins & correspondence

8306060223 Forwards IE Insp Rept 50-220/83-08 on 830401-30 & notice of violation STAROSTECKI, R. Division of Project & Resident Programs. 83/05/23 RHODE, G. K. Niegara Mohauk Power Corp. 2pp. 18728: 014. 24X Fiche: 50-220, 83/05/23, 8306060223

- --8306060224 Notice of violation from insp on 830401-30 * Region 1, Office of Director. 83/05/23 lp 18728:014 24X Fiche 50-220.83/05/23.8306060223
- --8306060227 IE Insp Rept 50-220/83-08 on 830401-30 Noncompliance noted failure to control use of jumpers HUBBON 8 D. DDERFLEIN, L T., MCBREARTY, R A Region 1. Office of Director 83/05/18 9pp 18728,015 24x Fiche 50-220,83/05/23,8306060223
- 8304010402 Ack receipt of 830513 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-220/83-03 MARTIN, T T Division of Engineering & Technical Programs, 83/05/25. RHODE, 9 K Niagara Mohauk Power Corp. 2pp. 18477. 330 24X Fichs 50-220,83/05/25,8304010402
- --8306010412 Responds to NRC 830407 ltm re violations noted in 1E Insp. Rept 50-220/83-03 Corrective actions source storage cabinets received source inventory & Procedure 8-RTP-35A & 358 training completed & Yech Spec amend submitted on 830503. LEMPGES.T.E. Niagara Hohawk Power Corp. 83/05/13. MARTIN.T.T. Division of Engineering & Technical Programs. Spp. 18679; 332. 24X Fiche 50-220.83/05/25,8306010402
- 8305110459 IE Info Notice 83-92, "Ruptured Am-241 Sources Contained in Well Logging Device" Svc list encl.
 TAYLOR, J M. Division of Safeguards & Inspection Programs (Post B30109) 83/03/26. Consolidated Edison Co. of New York. Inc 125p 1883: 040, 24X Fichs 50-000,83/05/26.8305110458.
- 8305110460 IE Info Notice 83-34, "Event Notification Info Worksheet "
 Svc list encl.
 JDRDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 930103), 83/05/26 Consolidated Edison Co. of New
 York, Inc. 115pp 18732,085 24X Fiche 50-000;83/05/26,8305110460.
- 8305110461 IE Info Notice 83-35, "Fuel Hovement M/Control Rods Withdrawn at BWRs " 8vc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103), 83/05/31 Consolidated Edison Co. of New York, Inc. 116pp 18732, 208 24X Fiche: 50-000, 83/05/31, 8305110461.
- 8306160341 Forwards IE Insp Rept 50-220/83-09 on 830412-15 & notice of violation MARTIN.T T Division of Engineering & Technical Progress 83/06/01. RHODE: 0. K Niagara Mohawk Power Corp 2pp. 18861:138, 24X Fiche: 80-220:83/06/01:8306160341
- --8306160344 Notice of violation from inap on 830412-15.

 * Region i, Office of Director 83/06/01 ip. 18861,160, 24X Fiche, 50-280, 63/06/01, 6306160341.
- --8306160348 IE Insp Rept 50-220/83-09 on 830412-15 Noncompliance noted. failure to inventory matl within reactor cavity railing, per Tech Specs NIMITZ,R.L. SHANBAKY,M.M. Region 1, Office of Director. 83/05/27. 10pp. 18861.161 24X Fiche.50-220,83/06/01,8306160341.
- 8305110464 IE Info Notice 83-36, "Impact of Security Practices on Sefs Operations " Svc list encl. JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/06/09. Consolidated Edison Co. of New York, Inc. 117pp. 18830: 280 24X Fiche: 50-000,83/06/09,8308110464
- 8305110470 IE Info Notice 83-38, "Defective Heat Sink Adhesive & Seismically Induced Chatter in Relays Within Frinted Circuit Cards." Syc list encl.
 JURDAN, E.L. Division of Emergency Preparedness & Engineering Response (Fost 830103). 83/06/13, Consolidated Edison Co. of New York, Inc. 118pp 18920-225. 24X Fiche. 50-000, 83/06/13, 8305110470.
- B306090010 IE Info Notice B3-37, "Transformer Failurs Resulting From Dagraded Internal Connection Cables," Bvc list encl.
 JORDAN, E.L. Division of Emergency Preparadness & Engineering Response (Post 830103), 83/06/13, Consolidated Edison Co. of New York, Inc. 243pp. 18921:001. 24X Fiche: 50-000, 83/06/13, 8306090010.
- B305110475 IE Info Notice B3-40, "Need to Environmentally Qualify Epoxy Grouts & Sealers," Syc list encl.
 JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830(03), 83/06/22, Consolidated Edison Co. of New York, Inc. 115pp. 19021:179. 24X Fiche: 50-000; B3/06/22, B305110475.
- B305110477 IE Info Notice B3-41, "Actuation of Fire Suppression Bys Causing Inoperability of Safety-Related Equipment "Svc list enci. JORDAN E.L. Division of Emergency Preparedness & Engineering Response (Post B30103). 83/06/22 Consolidated Edison Co. of New York: Inc. 120pp. 18977 007. 24X Fiche: 50-000:83/06/22,8305110477.

- 8305110477 IE Info Notice 83-42, "Reactor Mode Switch Malfunctions" Byc list encl. JORDAN,E.L. Division of Emergency Preparadness & Engineering Response (Post 830103) 63/06/23 Consolidated Edison Co of New York, Inc. 116pp. 16976 242, 24X Fichs 50-000,83/06/23,8305110479.
- 8305110483 IE Info Notice 83-43, "Improper Settings of Intermediate Range (IR) High Flux Trip Betpoints " Bvc list encl. JOHDAN, E. L. Division of Emergency Preparadness & Engineering Response (Post 830103). 83/06/24. Consolidated Edison Co. of New York, Inc. 116pp. 17046-277. 24X Fichs 50-000,83/06/24,8305110483
- B3062B0422 Forwards "Design Criteria for Reanalysis of Bafety-Related Masonry Walls." per NRC B305i3 request for addl info. MANOAN, C V Niagara Mohawk Power Corp B3/06/24 VABSALLO, D. B Operating Reactors Branch 2. ip. 19020-302. 24X Fichs.50-220, B3/06/24, B3062B0422
- --B306280424 "Design Criteria for Resnalysis of Safety-Related Masonry Halls, Nine Mile Point Unit i." 8 Niagsra Mohawk Power Corp B3/06/30 2pp. 19020:303 R4X Fiche: 50-220:83/06/24:8306280422

R Periodic operating reports & related correspondence

- 830.6020094 Monthly operating rept for Mar 1983 W/830408 ltr ROMAN.T.W., LEMPGERT E Niagara Mohawk Power Corp. 83/04/01, Director's Defice, Defice of Inspection and Enforcement. 7pp. 18691,170. 24% Ficher 50-220.83/04/01
- 8306200214 Monthly operating rept for May 1983 W/830613 ltr ROMAN, T. W. MANOAN, C. V. Niegara Mohawk Power Corp. 83/06/02. 18pp. 18903:218 24X Fiche: 50-220,83/06/02:8306200214.

8. Reportable occurrences. LERs & related correspondence

8306060199 LER 83-009/03L-0:on 830426, control room ventilation systemoved from syc for mods to control room wall, per LER 83-06 Temporary flexible ducting in place during mods. Mods completed, Ventilation systemomed to syc. W/630526 ltr RABY, J., LEMPOCS, T. E. Niagara Mohawk Power Corp. 83/05/24. ALLAN, J.M. Rapion i. Office of Director. 2pp. 18727:291. 24% Fichs: 50-220.83/05/24.8304040199.

V. Operator Examinations

830Ai40697 Extends invitation to attend 830A27 meeting in King of Prussia, PA to discuss transfer of reactor operator licensing function from Bethesda-MD to Region I ofc.
STAROSTECKI,R. Division of Project & Resident Programs. 83/06/09.
RMODE, O. K. Niagara Mohawi Power Corp. 2pp. 18841:349. 24X
Fichs: 50-220, 83/06/09, 8306140697.

DOCKET 50-223 UNIV. OF LOWELL RESEARCH REACTOR

V. Operator Examinations

8306140635 Extends invitation to attend 830627 meeting in King of Prussia.PA to discuss transfer of reactor operator licensing function from Bethesde.MD to Region I ofc.
8TAROSTECKI.R. Division of Project & Remident Programs 83/06/09.
8EGMIAW.L.E. Lowell. Univ. of 2pp. 18843:048. 24X
Fiche 50-223.83/06/09.8306140635.

DOCKET 50-224 UNIV OF CALIFORNIA REBEARCH REACTOR

F. Becurity, medical, emergency & fire protection plans

B306220296 Forwards request for addl info re Univ of CA research reactor B21025 smarqency plan to continue review per App E to 100FR50.Rev 1 to Reg Guide 2.6 & ANBI/ANB-15 16-1982 requirements. Info requested within 30 days of itr date. THOMAS.C.O. Stendardization & Special Projects Stanch. B3/06/09. KAPLAN.B.N. California. Univ. of. Berbeley. 6pp. 18940:306. 243 Fiche:50-224.83/06/09.8306220296.

DOCKET 50-225 RPI CRITICAL EXPERIMENT

V. Operator Examinations

8306140255 Requests attendence at 830627 meeting in King of Prussia, PA to discuss transfer of reactor operating licensing function from Bethesday MD to Region I of:, 8TAROSTECKI, R. Division of Project & Resident Programs, 83/06/09, LAMEY, R. T. Renseleer Polytechnic Inst. 2pp. 18833:017, 24X Fichs, 50-225, 83/06/09, 8306140255.

- DOCKET 50-237 DRESDEN NUCLEAR POWER STATION, UNIT 2

 F Security, medical, emergency & fire protection plans
- B306210314 FDIA request for NRC records re security violations & safeguards events at nuclear facilities.

 GOLDENDERO, G Scripps-Howard Nowspapers B3/04/22 FELTON, J M Office of Administration 2pp 18925 198 24X

 Fiche 50-000, B3/04/22, 8306210314
- B304210306 Partial response to FDIA request for NRC records resecurity violations & safeguards events at nuclear facilities Repts listed on App A available in PDR Search for addl documents subj to request continuing FELTON, J M Division of Rules and Records 83/05/16 QDLDENHERO, 0 Scripps-Hnuard Newspapers 2pp 18925 194 24X Fiche 50-000, 83/05/16, 8306210306
- 8306070247 Confirms 830601 telcon re changes to exercise windows for Dresden & Byron Nuclear Power Stations Dresden partial exercise will be conducted during who f 830712 w/Byron full-scale exercise beginning who of 831114

 JONES E Illinois, State of, 83/06/01 KEPPLER, J Region 3, Office of Director. ANDERSUN, J Federal Emergency Management Agency MAQNER, Q Commonwealth Edison Co lp 18795 317 24X

 Fiche, 50-000, 83/06/01, 8306070247
- 8304210355 Releases public version of revised emergency plan implementing procedure FELTON, J.M. Division of Rules and Records 83/04/06 Document Management Branch. ip 18935-293 24X Fiche 50-010,83/06/06, 8306210355.
- --8306210397 Public version of Rev 1 to Emergency Plan Implementing Procedure EPIP 300-12. "Initiation of Environ Monitoring Activities by Rad/Chem Director "Receipt form encl W/830516 ltr BCOTT, D. J. Commonwealth Edison Co. 83/05/11 DENTON. H.R. Offic of Nuclear Reactor Regulation, Director 19pp 18935-294 24X Fichs 50-010,83/05/06:8306210355
- 83D&100218 Responds to IE Insp Repts 50-010/83-01,50-237/83-01 & 50-249/83-01. Corrective action surveillance notification program developed for annual distribution of public info brochures on emergency planning FARRAR, D L. Commonwealth Edison Co 83/06/07 PAPERIELLU, C J Region 3, Office of Director, 4pp 18805-113 24X Fiche 50-010,83/06/07.8306100218
- 8306160214 Submits correction to 830401 ltr Date of reassessment will be made prior to 830801 not 831001.
 JONES E Illinois, State of, 83706709, KEPPLER, J Region 3.
 Office of Director ANDERSON, J Federal Emergency Management Agency WAONER, © Commonwealth Edison Co ip 18861-358 24X Fiche, 50-000, 83706709, 8306160214

P Operating license stage documents & correspondence

- 830&010308 Advises that maint procedures & schedules described in SER for SEP Topic III-4 B. "Turbine Missiles" & Section 4 6 of integrated plant BAR constitute adequate interim assurance of low probability of missile generation CRUTCHFIELD, D. Operating Reactors Branch 5 83/05/31. FARRAR, D.L. Commonwealth Edison Co. 2pp 18672 319 24X Fiche 50-237.83/05/31, B30&010308.
- B304070174 Discusses util interpretation of 100FR50.49, "Environ Qualification of Electrical Equipment Important to Safety for Nuclear Power Plants." Intent of rulemaking is to require upgrade program for replacement aquipment not parts FARRAR.D.L. Commonwealth Edison Co. 83/06/03. DENTON, H.R. Office of Nuclear Resector Regulation, Director. 3pp 18796.090 24X Fichs. 50-000.83/06/03.8306090194
- 830.6140408 Forwards evaluation of BHR Owners Group generic response to NUREQ-0737, Item II, K 3 18: "Mod of Automatic Depressurization Bys Logic-Feasibility for Increased Diversity for Some Event Bequences." Two options listed. CRUTCHFIELD, D. Operating Reactors Branch S. 83/06/03, FARRAH, D. L. Commonwealth Edison Co. Rpp 18837:354, 24X Fichs. 50-237,83/06/03,83061640408.
- 8306090227 Informs that response to Generic Ltr 83-08 will be submitted by 830713 Info will include stress repts to determine mod to vacuum breakers on Mark I containments RYBAK.B. Commonwealth Edison Co. 83/06/06. DENTON, H R. Office of Nuclear Reactor Regulation. Director. ip 18796: 234 24X Fiche: 50-000, 83/06/06. 8306090227.

- 8306130425 Provides overview of plan for checking for clamp interferences on main steam line anubbers Sargent & Lundy reviewing addl snubber test data Results expected by 830622 RYBAN B Commoniwealth Edison Co 83706/06 KEPPLER. J O Region 3. Office of Director 2pp 18823 145 24X Fiche 50-237,83/06/06,8304130429
- 8306160233 Advises that manufacturers whose repts were used in technical evaluation repts as environ qualification of electrical equipment have been contacted List of proprietary pages detailed in util 930513 1th W/OE affidavit RYBAK, B Commonwealth Edison Co 83/06/06 DENTON, H R Office of Nuclear Reactor Regulation, Director Spp 18861 304 24X Fiche 50-000, 83/06/06, 8306160233
- 8306100128 Forwards safety evaluation & technical evaluation rept,
 "Monitoring of Electric Power to Reactor Protection Sys for
 Dresden Nuclear Power Station Units 2 & 3 " Proposed mods
 acceptable
 CRUTCHFIELD.D Operating Reactors Branch 5 83/06/09. FARRAR,D L
 Commonwealth Edison Co 3pp 18801 181 24X Fiche 50-237,83/06/09,8306100128
- --B306100131 Safety evaluation re monitoring of electric power to reactor protection sys Proposed mods providing automatic protection of sys components from sustained abnormal power supply acceptable

 * Office of Nuclear Reactor Regulation, Director 83/06/09 2pp 18801-184 24X Fichs 50-237,83/06/09,8304100128
- --8306100135 "Monitoring of Electric Power to Reactor Protection Sys for Dreaden Nuclear Power Station Units 2 & 3," technical evaluation rept SELAN, J C Lawrence Livermore Laboratory FIN A-0250 UCID-19705 83/05/18 NRC No Detailed Affiliation Given. 7pp 18801 186 24X Fichs 50-237, 83/06/09, 8306100128
- 8306200265 Forwards "Dresden Nuclear Power Station Unit R Reactor Vessel Irradiation Surveillance Program Analysis of Capsule Number 8 "Results support 820331 amend request that existing pressure temp curves be effective through 10 EFPY RYDAK, D Commonwealth Edison Co 83/06/10 SCHMENCER, A Licensing Branch 2 2pp 17021 308 24X Fiche 50-237,83/06/10,8306200265.
- --B306270003 "Dreaden Nuclear Power Btation Unit 2 Reactor Vessel Irradiation Surveillance Program Analysis of Capsule Number 8 "
 NORRIB, E B , LINDHOLM, U B Bouthwest Research Institute.
 SWRI-6701-002 B3/03/31 57pp. 19021
- 830.6240030 Application to amend Licenses DPR-19 & DPR-25, extending time limits for inoperability of ECCS ring header snubbers Also updates Unit 3 Tables 3 6 1 2 & b to reflect changes in type of snubbers installed.
 RYBAK, B. Commonwealth Edison Co 83/06/13 DENTON, H. R Dffice of Nuclear Reactor Republishon. Director 2pp. 18781:095. 24X Fiche:50-237,83/06/13,8306240030
- --8306240035 Proposed Tech Specs extending time limits for inoperability of ECCS ring header snubbers & updating Unit 3 Tables 3 6 1.0 % b to reflect type of snubbers installed 4 Commonwealth Edison Co. 83/06/13 20pp, 18981 097. 24X Fiche 50-237.83/06/13,8306240030
- 8306270247 Requests extension of Mark I containment completion date, All work on ECCS suction head snubbers will be completed by 830728, Description of remaining work current status & reasons for delay encl.

 RYBAK, B. Commonwealth Edison Co. 83/06/16. DENTON, H.R. Office of Nuclear Reactor Regulation, Director App. 18988, 278. 24x

 Fiche. 50-237, 83/06/16, 8306270247.
- 8306280564 Forwards confirmatory order to 820316 commitment to install permanent scram discharge sys mode by 850101 or prior to operation in Cycle 10, Proposed model Tech Specs provided for guidance also encil CRUTCHFIELD, D. Operating Reactors Branch 5. 83/06/24, FARRAR, D.L. Commonwealth Edison Co. 2pp. 19018, 029. 24X Fiche. 50-237, 83/06/24, 8306280544
- --8306280870 Confirmatory order resutil 820316 commitment to install permanent scram discharge sys mods by 850101 or prior to operation in Cycle 10 EIBENIUT.P.9 Division of Licensing 63/06/24. Commonwealth Edison Co. Spp. 17018 031. 24X Fiche 50-237,83/06/24,8306280564.
- --8306280575 Proposed model Tach Space for installation of parmament scram discharge sys mode.

 * NRC No Detailed Affiliation Given. 63/06/24 30pp. 19018.036 24X Fiche:50-237.83/06/24.8306280564.

- Q Inspection reports. IE Bulletins & correspondence
- 8304220144 Ack receipt of payment of civil penalty & 830317 response to 830216 notice of violation & proposed imposition of civil panalty AXELRAD, J A Director's Office, Office of Inspection and Enforcement 83/03/31 O'CONNOR, J Commonwealth Edison Co 2pp 18937 348 24X Fiche 50-237,83/03/31,8306220144,
- 830AZ20218 Ack receipt of 830414 payment of proposed civil penalties Response to notice of violation & proposed imposition of civil penalties will be evaluated & corrective actions examined during future inaps
 AXELRAD.J A Enforcement Staff 83/04/21. REED, C Commonwealth Edison Co 2pp 18950 357 24X Fiche 50-000,83/04/21,830A220218
- 8305260238 Responds to violations noted in IE Insp Repts 50-237/83-08 & 50-247/83-07 Corrective actions radiation protection agt personnel increased surveillance of respiratory devices & addl radiation control technician added. FARRAR.D.L Commonwealth Edison Co. 83/05/20 KEPFLER, J. Q. Ragion 3, Office of Director 5pp 18599 355, 24X Fiche 50-237,83/05/20,8305260238
- 8305110458 IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in Well Logging Device" Svc list encl
 TAYLOR, J H Division of Sefequards & Inspection Programs (Post
 830103) 83/05/26 Consolidated Edison Co of New York, Inc.
 125pp 18831 043 24X Fiche 50-000,83/05/26,8305110458
- 8305110460 IE Info Notice 83-34, "Event Notification Info Workeheet"

 8vc list encl
 JORDAN: EL Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/05/26. Consolidated Edison Co. of New
 York, Inc 115pp 18732 085 24x Fiche: 50-000, 83/05/26, 8305110460.
- 8306100101 Forwards IE Insp Repts 50-237/83-13 & 50-249/83-11 on 830426 No noncompliance noted.

 LITTLE.W S Region 3, Office of Director. 83/05/27. REED, C. Commonwealth Edison Co 2pp 18802-332. 24% Fichs: 50-237, 83/05/27, 8306100101
- ---8306100105 IE Insp Repts 50-237/83-13 & 50-249/83-11 on 830426, No noncompliance noted Major areas inspected; licensee action re IE Bulletin 80-11, "Masonry Wall Design."
 NORTON, J.F., WillLIAMB, C.C. Region 3, Office of Director, 83/05/27, 4pp. 18802, 334. 24X Fiche 50-237, 83/05/27, 8306100101.
- B305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods Withdrawn at BMRs " Svc list enc! JORDAN,E L, Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/31 Consolidated Edison Co. of New York, Inc. 116pp, 18732 208 24X Fiche: 50-000,83/05/31,8305110461.
- 8306130338 Confirms plan discussed on 830601 for 830620 enforcement conference to discuss post-maint problems & significance of missing snubber on torus.

 NDRELIUS, C E Division of Project & Resident Programs. 83/06/03. REED. C Commonwealth Edison Co ip 18823 001 24X Fiche. 50-237, 83/06/03. 8306130338
- 8306100149 Forwards Rev 3 to "160-Day Rept in Response to IE Bulletin 80-11 for Dresden 2 & 3 & Quad Cities 1 & 2, " RYBAK.B Commonwealth Edison Co 83/06/06 KEPPLER.J Q. Region 3, Office of Director 2pp 18804.161 24X Fiche 50-000.83/06/06, 8306100149
- --8306100156 Rev 3 to "180-Day Rept in Response to IE Bulletin 80-11 for Dresden 2 & 3 & Guad Cities 1 & 2."
 # Communicatin Edison Co. 83/05/09. 129pp. 18804:163. 24X Fichs: 50-000.83/06/06.8306100149.
- 8306100074 Forwards response to IE Bullstin 83-03 re dissel generator cooling water check valves. Plants utilize Mission Duo-Check valves employing hinge-to-pin design for protection against vibration-induced failure.

 BARNES, P. L. Commonwealth Edison Co. 83/06/07, KEPPLER. J. 9. Region 3, Office of Director. 7pp. 18802:238. 24X Fiche: 50-000, 83/06/07, 830610094.
- 8306100218 Responds to IE Insp Repts 50-010/83-01,50-237/83-01 & 50-249/83-01, Corrective action surveillance notification program developed for annual distribution of public info brochures on emergency planning. FARRAR, D. L. Commonwealth Edison Co. 83/06/07. PAPERIELLO, C. J. Region G. Uffice of Director. 4pp. 18805: j13. 24X Fiche, 50-010,83/06/07,8306100218

DOCKETED ITEMS

- 8305170380 Forwards response to IE Bulletin 83-03 re diesel generator cooling water check valves. Valves at Dresden & LaSalle acceptable w/o further into Rept on valve Failures at Quad Cities will be submitted within 90 days of into completion BARNES, P L. Commonwealth Edison Co. 83/06/07. KEPPLER, J @ Region 3. Office of Director 7pp 18880-211. 24X Fiche: 50-000.83/06/07. 8306170380
- 8306270387 Forwards inservice inspired for Jan 1983 inspired BMM reactor pressure vessel & GE primary sys piping SCOTT.D J. Commonwealth Edison Co. 83/06/08, KEPPLER, J. G. Region S. Office of Director 1p. 18993-252. 24X Fiche. 50-237, 63/06/08, 6306270367
- --8304270392 Inservice insp rept on 830110-0329.B&W reactor pressure vessel & GE grimery sys piping inspected.

 # Commonwealth Edison Co 83/06/08 38pp. 18993 253 24X Fich: 50-237,83/06/08.8306270387.
- 8305110464 IE Info Notice 83-36, "Impact of Security Practices on Safe Operations," Syc list and, JORDAN, E. Division of Emergency Preparadness & Engineering Response (Post 830103) 83/06/09, Consolidated Edison Co. of New York, Inc. 119pp 18830-280 24X Fiche-50-000, 83/06/09, 8305110464
- 8305110470 IE Info Notice 83-38, "Defective Heat Sink Adhesive & Seismically Induced Chatter in Relays Mithin Printed Circuit Cards: "Syc list encl. JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83706/13, Consolidated Edison Co. of New York, Inc. 118pp. 18920-225 24X Fiche: 50-000, 83/06/13, 8305110470.
- 8304090010 IE Info Notice 83-37, "Transformer Failure Resulting From Degraded Internal Connection Cables," Syc list encl JORDAN, E. Division of Emergency Preparedness & Engineering Response (Fost 830103). 83706/13. Consolidated Edison Co. of New York: Inc 243pp. 18921:001. 24X Fiche 50-000, 83/06/13, 8306090010
- B306300235 Forwards IE Insp Repts 50-237/83-12,50-249/83-10, 50-234/83-13 & 50-265/83-11 on 820412-14 & 0506 & 16 & notice of violation.

 LITTLE.M.B. Region 3. Office of Director 83/06/16. REED,C Commonwealth Edison Co. 2pp. 19122:279 24X Fiche:50-000,83/06/16,8306300235.
- ---8306300238 Natice of violation from insp on 830412-14 & 0506 & 16.
 LITTLE, W. B. Region 3. Office of Director. 83/06/16. 2pp
 19122. 281 24X Fiche: 50-000. 83/06/16. 8306300235.
- ----8306300246 IE Insp Repts 50-237/83-12.50-249/83-10.50-254/83-13 & 50-245/83-11 on 830412-14 & 0506 & 16 Noncompliance noted as-built confinguration (for pipe anchor RI33 in pressure suppression suppression supplicated from original design.

 YIN, I. Y., DANIELSON D. H. Region 3, Diffice of Director. 83/06/15, 9pp. 19122 283 24X Fiche: 50-000, 83/06/16, 8306300235.
- 8305110475 IE Info Notice 83-40, "Need to Environmentally Qualify Epoxy Grouts & Sealers " Syc list and I JORDAN, E.L. Division of Emergancy Preparadness & Engineering Response (Post 830103). 83706/22. Consolidated Edison Co. of New York, Inc. 115pp 19021 179, 24X Fiche: 50-000, 83/06/22, 8305110475
- 8305110477 IE Info Notice 83-41, "Actuation of Fire Suppression Bys Causing Inoperability of Safety-Related Equipment." Svc list encl. JORDAN, E.L. Division of Emergency Preparadness & Engineering Response (Post 830103). 83/06/22. Consolidated Edison Co. of New York, Inc. 120pp, 18997:007. 24X Fiche. 50-000, 83/06/22, 8305110477.
- 8305110479 IE Info Notice 83-42, "Reactor Mode Switch Melfunctions."
 Byc list encl.
 JORDAN,E.L. Division of Emergency Preparadness & Engineering
 Response (Post 830103). 83706/23. Consolidated Edison Co. of New
 York, Inc. 116pp. 18976:242. 24X Fiche: 50-000,83/06/23,8305110479.
- 8305110493 IE Info Notice 83-43, "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints." Byo list encl. JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Fost 830103), 82/06/24. Consolidated Edison Co. of New York, Inc. 116pp 19046:297 24X Fiche. 30-000, 83/06/24, 8305110483.
- R. Periodic operating reports & related correspondence
- 8304130275 "Bemiannual Rept of Radioactive Effluents 1982 " W/890302 ltr.
 80077,D.J. Commonwealth Edison Co. 83/03/02. KEPPLER.J.O. Region 3, Office of Director. 20pp. 18823: 277. 24X Fiche: 50-010, 83/03/02, 8304130275

- 8306140086 Monthly operating repts for May 1983 W/830601 ltr BCHROEDER, B A , 800TT. D J Commonwelth Edison Co 83/06/01 Director's Office, Office of Inspection and Enforcement 18p; 18838 347 24X Fichs 50-237,83/06/01.8306140086
- 8306130454 Forwards corrected "1981 Rept of Docupational Personnel Radiation Doses Contract Workers," per Reg Quide 1 16
 Number of people per mannem should be listed in maint not engineering category
 WAGNER, O. P. Commonwealth Edison Co. 83/06/07 KEPPLER, J. G. Region 3, Office of Director 1p. 18821 179 24X Fiche 50-010,83/06/07, 83/06/30454
- --8306130457 Forwards corrected "1981 Rept of Occupational Personnel Radiation Doses Contract Workers," per Reg Quide 1 16 Number of people per manrem should be listed in maint not engineering category WAONER, O P Commonwealth Edison Co 83/06/06 KEPPLER, J Q Region 3, Office of Director 10 18821 180 24X Fiche 50-010,83/06/07.8306130454
- --8306130460 Corrected "1981 Rept of Occupational Personnel Radiation Doses -- Contract Workers."

 * Commonwealth Edison Co 83/06/06 9pp 18921 181 24x
 Fiche 50-010, 83/06/07, 8306130454
- B3062200B6 Advises that V Biron farm will provide milk samples For radiological monitoring program Herd totals 130 coms. including 50 milking coms. Addl info re Biros farm will be provided in annual environ rept QOLDEN, J C. Commonwealth Edison Co B3/06/15 KEPPLER, J G Regio 3, Office of Director Ip 18927 187 24X Fiche 50-237,83/06/15,830620086
- 8 Reportable occurrences, LERs & related correspondence
- 8306060232 Updated LER 83-013/03X-1 on 830211, power lead from welding machine become disconnected & grounded to torus base metal causing arc strike which fused coper/forass into metal Cause considered accident W/830523 ltr
 TANO WEE, D. SCOTT, D. J. Commonwealth Edison Co. 83/05/23.
 KEPPLER.J. O. Region 3, Office of Director. 3pp. 18728 288 24X
 Fiche 50-237,83/05/23.8306060232
- 8396030218 LER 83-034/03L-0 on B30427, drywell floor drain sump pumped at interval exceeding Tech Spec limit Caused by personnel failure to follow Operating Order 26-83 ensuring compliance w/Tech Spec requiring pumping at 4 h interval W/830525 itr SCOTT, D J , COEN, R. Commonwealth Edison Co 83/05/25 KEPPLER, J @ Region 3. Office of Director 3pp 16704, 025 24X Fiche 50-237, 83/05/25, 8306030218
- 8304040040 LER 83-035/03L-0 on 830427, low pressure coolent injection HX discharge valve MO2-1501-3B failed to open Cause undetermined Control circuitry inspected by electrical & instrument maint & found satisfactory W620525 ltr COYLE.L.M. SCOTT, J. Commonwealth Edison Co. 83/05/25 KEPPLER.J.O. Region 3, Office of Director. 3pp. 18719 128 24X Fiche 50-237,83/05/25,8304040040
- 8306070246 LER 83-036/03L-0 on 830502, drywell floor drain leakage exceeded Tech 8pec limits due to bonnet leakage on feedwater check valve 2-220-0580 Caused by failed bonnet seal ring Seal ring replaced Leakage to be monitored W/830531 ltr. CHRISTEL, 8, 8007T.D J. Commonwealth Edison Co 83/05/31 KEPPLER, J O Region 3, Office of Director 3pp 18744 213, 24) Fiche. 50-237, 83/05/31, 8306070246.
- 8306130382 LER 83-037/03L-0 on 830504, average power range Monitor 4 rod block setpoint exceeded Tech Spec limit of 12% Caused by instrument drift Monitor adjusted & tested satisfactorily W/830531 ltr SEVERLY, K F. 86071. D. J. Commonwealth Edison Co. 83/05/31 KEPPLER, J. 0 Region 3, Office of Director 3pp 18822 347 24% Fiche: 50-237, 83/05/31, 8306130382
- 8306130348 LER 83-039/03L-0 on 830505, during normal operation, unidentified leak from drywell discovered Caused by packing leak on recirculation discokerse bypass valve 2-202-7A causing overflow of equipment drain sump W/830601 ltr TURNQUEST.L. SCOTT.D.J. Commonwealth Edison Co. 83/06/01 KEPPLER.J.9 Region 3, Office of Director 3pp 18823 005 24 Fiche: 50-237,83/06/01,8306130348
- 8306130437 LER 83-040/03L-0; on 830507, during MBIV 10% closure test Procedure DOS 250-1; NSO received half-scram signal on RP8 channel A Caused by ground on 10 limit switch relay 570-102E circuit, ground will be corrected H/830601 ltr. MAXWELL,D., SCOTT,D J Commonwealth Edison Co 83/06/01. KEPPLER,J.9. Region 3, Office of Director 3pp 18821; 212 24% Fiche: 50-237, 83/06/01, 8306130439.

- 8306130374 LER 83-042/03L-0 on 830512, condenser low vacuum scram switch 503D tripped at vacuum of 22 8 inches while performing DIS 500-6 Caused by instrument drift Barksdale switch DIT-H189S adjusted & exercised W/830603 ltr BEVERLY, K.P., 8COTT.D.J. Commonwealth Edison Co. 83/06/03 KEPPLER.J.9 Region 3, Office of Director 3pp 18822 344 24X Fiche 50-237,83/06/03,8306130374
- 8306270282 Potential Part 21 rept re discrepancy in welding of turnbuckle assembly, turnbuckle-bolt interface & on top plate assembly variable springs 2A307 Grade B bolts not ASME Section IX mat! Investigation underway KARADIANIS, J A Eleen Metal Products Co 83/06/17 KEPPLER, J Q Region 3, Uffice of Director 2pp 18976 207 24X Fiche 50-000,83/06/17.8306270282
- 8306270279 PND-III-83-052 on 830620.electrical fire occurred in generator exciter.forcing shutdown of unit for 2-3 wks. 8 toning process caused short in rings/brush manifold assembly Damaga extensive TONGUE.T. SHAFER.W Region 3, Office of Director 83/06/21 ip 18996 172 24X Fiche 50-237.83/06/21.8306270279

DOCKET 50-243 ORECON STATE UNIV RESEARCH REACTOR Q Inspection reports, IE Bulletins & correspondence

- 8306070285 Forwards IE Insp Rept 50-243/83-01 on 830511-12 No noncompliance noted 800KH E Region 5, Office of Director 83/05/20 PARBUNB, T D Oregon State Univ 5pp 18741 166 24X Fiche 50-243,83/05/20, 8306070285
- --8306070287 IE Insp Rept 50-243/83-01 on 830511-12 No noncompliance noted Major areas inspected radiation control program, environ protection, transportation activities & processing of IE info notices

 GARCIA.E M. WENBLAWSKI.F., BOOK.H E. Region 5, Office of Director 83/05/20 5pp 18741 168 24X Fiche 50-243.83/05/20, 8306070285

S Reportable occurrences, LERs & related correspondence

- 830&070044 RO on 830523, discovered insp of transient control rod not conducted since 810317 Caused by misinterpretation of Yech Space Surveillance time intervals will be modified per ANSI/ANS 15 1-1982 guidelines WAND.C H Oregon State Univ 63/05/25 Region 5, Office of Director 2pp 18740 001 24X Fiche: 50-243, 83/05/25, 830&070044.
- DOCKET 50-244 ROBERT EMMET GINNA NUCLEAR PLANT, UNIT 1

 F Security, medical, emergency & fire protection plans
- 8304070258 Forwards Rav i8 to security plan, delineating frequency for testing emergency power annunciator sys Rev withheld (ref 100FR73 21) MAIER.J. E. Rochester Gas & Electric Corp. 83/05/19 ALLAN, J N Region I, Office of Director 1p 18740 339 24X Fiche 30-244, 83/05/19, 8304070838
- 8306020381 Forwards IE Insp Rept 50-244/83-08 on 830418-22 No noncompliance noted MARTIN.T Division of Engineering & Technical Programs 83/05/20 MAIER.JE Rochester Gas & Electric Corp. 2pp 18695.142 24X Fichs: 50-244,83/05/20,8306020381
- --8306020389 IE Insp Rept 50-244/83-08 on 830418-22 No noncompliance noted Major areas inspected; emergency preparedness items from prior appraisal performed on 81102-13, TERC.N.M. CUREN.I., CROCKER.H.W. Region 1, Office of Director. 83/05/19 14pp 18695-144, 24X Fiche, 50-244, 83/05/20, 8306020381
- 8306020400 Forwards IE Insp Rept 50-244/83-09 on 830419-22 No moncompliance noted MARTIN T T Division of Engineering & Technical Programs 83/05/20. MAIER, J. E. Rochester Gas & Electric Corp. 2pp 18695 033 24X Fichs 50-244,83/05/20,8306020400.
- --8306020403 IE Insp Rept 50-244/83-07 on 830419-22. No noncompliance noted Hajor areas inspected security plan & implementing procedures, security organization & program audit records & repts, testing & maint & locks keys & combinations DUNLAP.J.M. 90DY.A.T. Region 1. Office of Director 63/05/18, 3pp. 18695.035. 24X Fiche 50-244,83/05/20,8306020400

- 8306060174 Summary of 830518 meeting w/Mestinghouse re review of Mestinghouse generic safety parameter display sys concerning MCAP-10170. "Emergency Response Facility Design & V&V Process "Vendor will append man-in-the loop results DICK: 0 F Operating Reactors Branch 5 83/06/02 CRUTCHFIELD, D. Operating Reactors Branch 5 17pp 18728: 164 24X Fiche 50-244, 83/06/02.8306060174.
- 8306170008 Advises that LABL vital area analysis program personnel will revisit plant site to gather addl info due to major mods & redirection of program by NRC ALLAN.J M Region 1. Office of Director 83/06/13 MAIER, J E. Rochester Oas & Electric Corp 2pp 18882 275 24X Fiche 50-244,83/06/13/8306170008

Q Adjudicatory correspondence

8306160571 Order requesting party status repts by 830715 re expected issuances; suggested procedure re discovery, prehearing conference & hearings; proposed agends if prehearing conference suggested & renoticing of procedure.

OROSSMAN, H Atomic Safety and Licensing Board Panel. 83/06/15, 2pp 18866 283 24X Fiche, 50-244, 83/06/15, 8306160571

J Insurance & indemnity information

- 830A020128 Forwards Endorsements 73 & 74 to MAELU Policy MF-47 & Endorsements 87 & 88 to NELIA Policy NF-170.
 SINISI.U.M Marsh & McLennan; Inc 83/05/26. BALTZMAN, J. Assistant Director for State & Licensee Relations 5pp 18491.222, 24X Ficher 80-244,83/05/26,830A020128
- P Operating license stage documents & correspondence
- 830.6020079 Forwards visual aids used at 830512 & 20 meetings re steam generator sleeving Beb proprietary "Ginne Bleeving Repair Spring 1983 Steam Generator Repid Sleeving Program." Rept withheld (ref 10CFR 790)
 MAIER. J. E. Rochester Ges & Electric Corp. 83/05/24. CRUTCHFIELD, D, Operating Reactors Branch 5 35pp 18691-135. 24X
 Fiche 50-244,83/05/24,8306020079
- 830A0A0057 Forwards info & rept re BEP Topic III-7. B. "Design Codes, Design Criteria & Load Combinations " As result of review, util has identified two commitments re scupper installation & diesel generator bldg concrete wells, MAIER, J. E. Rochester Gas & Electric Corp. 83/05/27. CRUTCHFIELD, D. Dpersating Reactors Branch 5 lipp. 18719 271, 24X Fiche 50-244,83/05/27,830A0A0057.
- --8306060057 "Evaluation of Concrete Code Changes, 'Design Codes, Design Criteria & Load Combinations' Portion of UBNRC SEP Topic III-7 B "
 ADAMETZ, J M , MODRE, T L Gilbert/Commanwealth Cos. 83/05/23, 34pp 18719 282 24X Ficher 50-244,83/05/27,8308060057
- 830.6060296 Requests clarification of 830201 response to 821213 safety evaluation on environ qualification of safety-related electrical equipment Proprietary info should be identified per entl guidelines within 30 days of receipt of 1th CRUTCHFIELD D Operating Reactors Branch 5. 83/05/31. MAIER, J. E. Rochester Pas & Electric Corp. 6pp. 18726:347. 24X Fichs. 50-244,83/05/31,8306060296
- 8306060255 Summary of 830520 meeting w/util & BMW re steam penerator tube sleaving program. Agenda & viewgraphs encl. Bafety avaluation will be issued prior to permitting criticality. DICK. Q F. Operating Reactors Branch 5 83/06/02 Operating Reactors Branch 5 83/06/02 Operating Reactors Branch 5, 17pp 18727:207. 24X Fiche: 50-244,83/06/02,8306060255.
- 8306140895 Forwards Rev O to proprietary "Steam Generator Evaluation, Bpring 1983 Outage, Strength Testing of Semiable Bleaves Explosively Expanded Into Locked Tubes - Re Ginna Station, "Rept withheld (ref 10CFR2.790).

 MAIER, J. E. Rochester Gas & Electric Corp. 83/06/09. CRUTCHFIELD, D. Operating Resctors Branch 5. ip. 18833;059. 24X

 Fichs: 30-244,83/06/09,8306140595
- B306170032 Discusses NRC B30428 ltr re blocking of safety injection signal during cooldown Tech Specs will be submitted to reflect clarification of permissible bypass conditions. No Tech Bpac mod required for steam line isolation MAIER. J. E. Rochester Cas & Electric Corp. B3706709. CRUTCHFIELD, D. Operating Reactors Branch 5. ip. 18892, 232 24X Fiche: 50-244, 83/06/09, 8306170032.

- 8305200314 Forwards "RE Ginna Nuclear Power Station Containment Vessel Tendons Response to NRC Review Comments on Tendon Evaluation." supporting util conclusion that stress relaxation of tendon major cause of large force losses.

 HAIER, J.E. Rochester Gas & Electric Corp. 83/06/13 CRUTCHFIELD, D. Operating Reactors Branch 5. lp. 18899 243 24X

 Fiche: 50-244,83/06/13,8306200314
- --8306200316 "RE Ginna Nuclear Power Station Containment Vessel Tendons, Response to NRC Review Comments on Tendon Evaluation " FULTON.J.F. HERR.J.C. CHEN.C. Gilbert/Commonwealth Cos 83/06/09 56pp 18899 244. 24X Fiche 50-244,83/06/13,8306200314
- 8306200235 Forwards proprietary version of safety evaluation finding pretensioning mod to previously approved sleaving process acceptable for locked up tubes in steam generators. Bafety evaluation withheld CRUYCHFIELD. D. Operating Reactors Branch 5 83/06/16 MAIER, J E Rochester Ges & Electric Corp. 3pp. 18902. 151 24X Fiche 50-244.83/06/16.8306200235
- 8305240177 Responds to SEP Topic III-5 B. "Pips Break Outside Containment " Installation of jet impingement shields to protect main steam safety & relief valves not needed. Item resolved.

 MAIER, J E. Rochester Cas & Electric Corp. 83/06/16 CRUTCHFIELD. D. Operating Reactors Branch 5 Spp 18781 030. 24X Fiche 50-244.83/06/16.8306240177
- B3062403ti Discusses analysis used to meet current SRP seismic criteria for refueling mater storage tank (RMBT), per SEP Topic III-6. Preliminary results w/input & acceptance parameters encl Final analysis will be available by 830715.

 MAIER, J. E. Rochester Qas & Electric Corp. 83/06/16. CRUTCHFIELD, D. Operating Reactors Branch 5. 24pp. 18979, 148 24X

 Fiche: 50-244, 83/06/16.8306240311.
- --8305240312 "Design Input Bocument Index for 'Evaluation of Sodium Hydroxide Tank.'" CAMPBELL,D R Gilbert/Commonwealth Cos. 3572. 82/10/25. 17pp 18777-172 24X Fichs. 50-244.83/06/16.8306240311
- 8306210157 Forwards environ svaluation & notice of availability reconversion of provisional OL DPR-18 to full-tarm OL Evaluation determined no substantial changes in proposed actions relevant to environ concerns MIRAGLIA:F.J. Assistant Director for Bafety Assessment. 83/06/17 MAIRN.J E Rochester Ges & Electric Corp Spp. 18915 193 24X Fiche: 50-244,83/06/17,8306210157
- --8306210163 Environ evaluation re-conversion of provisional OL DPR-18 to full-term OL * Office of Nuclear Reactor Regulation, Director 83/06/17 18pp. 18915; 198 24% Fiche: 50-244,83/06/17,8306210107.
- --B306210168 Notice of availability of environ evaluation of conversion of provisional DL DPR-18 to full-term CL. FALLSON, H.A. Operating Reactors Branch 5 83/06/17 2pp 18915:216, 24X Fiche:50-244,83/06/17,8306210157.
- 8306240298 Forwards Rev 3A to App C to GA manual describing inservice pump & valve testing program for Jan 1981 Dec 1990. Rev includes commitments to test valves performing pressure isolation function from RCPB.

 MAIER, J. E. Rochester Gas & Electric Corp. 83/06/20 CRUTCHFIELD, D Operating Reactors Branch 5 ip. 18979 189. 24% Fiche: 50-244, 83/06/20, 8306240298.
- --8306240302 Rev 3A to App C to GA manual re inservice pump & valve testing program for Jan 1981 Dec 1790
 ANDERSON, C. R. Rochester Oes & Electric Corp. 83/06/15 37pp. 18979: 190. 24% Fiche 50-244, 83/06/20, 8306240298
- 8306270360 Forwards add1 info requested 830407 re containment pressure monitor, containment water level monitor & containment hydrogen monitors installed per requirements of THI Items II F. 1.4, II. F. 1.5 & II. F. 1.6, respectively MAIGR, J. E. Rochester Oas & Electric Corp., 83/06/20, CRUTCHFIELD, D. Openating Rescrete Branch 5. 10pp. 18973:176, 24X Fiche: 50-244, 83/06/20, 8306270360.
- 8306270257 Forwards JH Taylor affidavit supporting 830609 request to withhold rept summarizing testing performed to support pretensioning of steam generator tubes for sleeying from public disclosure.

 MAICR.J.E. Rochester Cas & Electric Corp. 83/06/21. CRUTCHFIELD.D. Operating Reactors Branch 5. App. 18786, 270. 24X
 Fiche: 80-244, 83/06/21, 8306270257

- G Inspection reports. IE Bulletins & correspondence
- 8306020381 Forwards IE Insp Rept 50-244/83-08 on 830418-22 No noncompliance noted MARTIN TT Division of Engineering & Technical Programs 83/05/20 MAIER, J E Rochester Cas & Electric Curp 2pp 18695 142 24X Fiche 50-244.83/05/20,8306020381
- --8304020389 IE Imap Rept 50-244/83-08 on 830418-22 No noncompliance noted Major areas inspected emergency preparedness items from prior appraisal performed on 811102-13 TERC.N M. COHEN.I. CROCKER.H W. Region 1. Office of Director 83/05/19 14pp 18695 144 24X Fiche 50-244.83/05/20.830602038:
- 830.6020.400 Forwards IE Insp Rept 50-244/83-09 on 830419-22 No noncompliance noted MARTIN.T T Division of Engineering & Technical Programs 83/05/20 MAIER, JE Rochester Gas & Electric Corp 2pp 18695 033 24X Fiche 50-244.83/05/20.8306020400
- ---9304020403 JE Insp Rept 50-244/83-09 on B30419-22 No noncompliance noted Major areas inspected, security plan & implementing procedures, security organization & program audit, records & repts, testing & maint & locks, keys & combinations DUNLAP, J.M., GDDY.A T. Region 1, Office of Director 83/05/18 3pp. 18493-035 24X Fiche 50-244,83/05/20,8304020400
- 8306020427 Forwards IE Insp Rept 50~244/83-06 on 830331-0401 No noncompliance noted MARTIN T T Division of Engineering & Technical Programs 83/05/20 MAIER, J E Rochester 04s & Electric Corp 2pp 18694 113 24X Fiche 50-244,83/05/20,8306020427
- --9306020434 IE Insp Rept 50-244/83-06 on 930331-0401 No noncompliance noted Major areas inspected 830331 personnel injury event. including personnel esposure, notifications, high radiation area control, individual work hours & training NIMITZR L , SIAMBAKY, M M Repion 1, Office of Director 83/05/13 8pp 18694 115 24X Fiche 50-244,83/05/20,8306020427
- G3D402045B Forwards IE Insp Rept 50-244/B3-07 on B30411-15 No noncompliance noted MARTIN.T T Division of Engineering & Technical Programs B3/05/20 MAIER.J E Rochester das & Electric Corp 2pp. 18693 278 24X Fiche-50-244,83/05/20.830402045B
- --8306020460 IE Insp Rept 50-244/83-07 on 830411-15 No noncompliance noted Major areas inspected radiation protection program, including status of previously identified items.personnel selection, qualification & training & exposure controls COLLINS,D J. SHANBAKY.M M Region 1, Office of Director 83/05/18 9pp 18693 280 24X Fiche 50-244,83/05/20,8306020458
- 830.607.0079 Forwards visual aids used at 830.512 & 20 meetings re steam generator sleeving & B&W proprietary "Olinna Sleeving Repair Spring 1983 Steam Generator Rapid Sleeving Program " Rept withheld (ref 100FR2 790), MAIER. J. E. Rochester Gas & Electric Corp. 83/05/24 CRUTCHFIELD.D Operating Reactors Branch 5 35pp 18691 135, P4X Fiche 50-244,83/05/24,8306020079
- 8305110458 IE Info Natice 83-32, "Ruptured Am-241 Sources Contained in Heil Lagging Device " Svc list encl TAYLOR, J. M. Division of Bafeguards & Inspection Programs (Post 830103) 83/08/26. Cansolidated Edison Co. of New York, Inc 125pp 18831 043 24X Fiche 50-000,83/05/26,8305110458
- 8305110460 IE Info Notice 83-34, "Event Notification Info Worksheet a Swc list encl.

 JORDAN, E L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/05/26 Consolidated Edison Co of New
 York, Inc 115pp. 18732.085 24X Fiche 50-000,83/05/26,8305110460
- 8306020074 Notification of 830601 significant licenses meeting in Kins of Prussia.PA to discuss enforcement issues KISTER.H.B Region 1, Office of Director 83/05/26. Region 1, Office of Director 1p 18701/336 24X Fiche.50-244.83/05/26.8306020074
- 830.6060036 Bpecifies provisions incorporated into procedures re NRC positions for SEP Topic III-3 C. "Inservice Insp of Water-Control Structures." Topic detailed in final integrated plant BAR. NUREG-0821.
 MAIER-J.E. Rochester Cas & Electric Corp. 83/05/26 GRUTCHFIELD.D Operating Reactors Branch 5 Epp. 18723 298. 24X Fiche 50-244,83/05/26,8304040036.
- 8305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods Withdrawn at BWRs," Bvc list anc! JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/31, Consolidated Edison Co of New York, Inc 116pp, 18732;208 24X Fiche 50-000,83/05/31,8305110461

- 8306160361 Forwards IE Insp Rept 50-244/83-10 on 830408-0507 & natice
 - SUBJOUSDIFT OF WARDS IN THE REPT SU-244/83-10 ON 830408-0507 of Violation
 STARDSTECKI, R Division of Project & Resident Programs 8
 MAIER, J E Rochester Oas & Electric Corp 2pp 18860 076
 Fiche 50-244.83/05/31.8306160361 83/05/31
- --8306160365 Notice of violation from insp on 830408-0507 * Region 1. Office of Director 83/05/31 lp IBB Fiche 50-244.83/05/31.8306160361 18860 078 P4X
- --8306160372 IE Insp Rept 50-244/83-10 on 830408-0507 Noncompliance nated failure to perform surveillance testing specified in inservice pump & valve test program ZIMMERMAN.R P Region I. Office of Director KISTER.H II Division of Project & Resident Programs 83/05/55 Ilpp 18860 079 24X Fiche 50-244.83/05/31.8306160361
- B306140025 Responds to IE Bulletin 83-03, "Check Valve Failures in Raw Water Cooling Bys of Diese) Generators "Backflow test performed on B30420 No leakage indicated Integrity of valve internals confirmed MAIER, J. E. Rochester Oas & Electric Corp. B3/06/08 ALLAN, J. M. Region 1. Office of Director Spp. 18838 231 24X Fiche 50-244,83/06/08,8306140025
- 8306210019 Responds to 1E Bulletin 83-03, "Check Valve Failures in Raw Water Cooling Bys of Diesel Generators "Inservice test program will be modified to include leak testing to confirm integrity of valve internals during each refueling shutdown MAIER, J E Rochester Cass & Electric Corp. 83/06/08 ALLAN, J M Region 1. Office of Director 3pp. 18912 280 24% Fiche: 50-244, 83/06/08, 8306210015
- 8306230195 Forwards IE Insp Rept 50-244/83-ii on 830502-06 No noncompliance noted STAROSTECKI,R Division of Project & Resident Programs 03/0 MAIER,J E Rochester Gas & Electric Corp 2pp 18946 352 Fiche 50-244.83/06/08.8306230195
- --B306230177 IE Insp Rept 50-244/83-11 on B30502-06 No noncompliance noted Major areas inspected actions taken to comply w/ NUMEG-0737. Item II B 2 re design review of plant shielding BAUNACK. W H , EAPEN. P K Region I, Office of Director KISTER. H B Division of Project & Resident Programs B3/06/07 7pp 18946 254 24X Fiche 50-244.03/06/08.8306230195
- 8305110444 IE Info Notice 83-36, "Impact of Security Practices on Bafe Operations " Svc list encl | Svc list encl | Operations | Svc list encl | Operations | Operation
- 8306140410 Documents tube R34C84 removal from B steam generator 2 hot lag Results of BMI analyses will be submitted in Fall 1983. Sequence of events & eddy current insp results enc! MAIER, J E Rochester Oas & Clectric Corp. 83/06/10 CRUTCHFIELD, Deersting Reactors Branch 5 10pp 18838.081 24X Fiche 50-244.83/06/10.8306140410 CRUTCHFIELD, D
- B306150309 Responds to IE Bulletin B3-05, "ASME Nuclear Code Pumps & Spare Parts MPg by Hayward Tyler Pump Co " Subj pumps not used at facility.

 MAIER, J E Rochester Gas & Electric Corp B3/06/10 ALLAN. J M. Region 1. Dffice of Director. 1p. 10847:204 24% Fichs 50-244,83/06/10,8306150309
- 8305i10470 lE Info Notice 83-38, "Defoctive Heat Bink Adhesive & Seismically Induced Chatter in Relays Within Printed Circuit Cards " Syc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co of New York, Inc. 118pp. 18920-225 24X Fiche 50-000,83/06/13,8305110470
- 8304090010 IE Info Nôtice 83-37, "Transformer Failure Resulting From Degraded Internal Connection Cables" Bvc list encl JORDAN, EL Division of Emergency Proparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co of New York, Inc 243pp 18721 601, 24X Ficha 50-000,83/06/13.8306090010.
- 8304150013 Advises that tubesheet sleeving of no more than 30 tubes acceptable repair technique per inservice insp program Bafety evaluation encl CRUTCHFIELD.D Operating Reactors Branch 5 83/06/13 MAICR, J E Rochester Oas & Electric Corp. 2pp. 18846.328 24X Fiche: 50-244,83/06/13,8306150013
- ---8305150014 Bafety evaluation accepting tubesheet sleeving of no more than 30 tubes as repair technique per inservice insp program * Office of Nuclear Reactor Regulation, Director. 83/06/13 4pp 18846.330 24% Fiche 50-244.83/06/13.8306190013

- 8306220022 Discusses steam generator slerving eddy current exam. Util pursuing improvements in techniques w/goal of improving sensitivity by mixing frequencies for unwanted signal suppression & alternate probe designs
 MAIER. J E Rochester Gas & Electric Corp 83/06/14. CRUICHFIELD. D
 Operating Reactors Branch 5 | p 18930 211 24%
 Fiche 50-244.83/06/14.8306220022
- 8306230317 Forwards IE Enforcement Conference Rept 50-244/83-16 on NOBESICAL Forwards IE Enforcement Conference Rept 30-244/83-1.
 830601 & notice of violation re improper post-maint test for containment personnel hatch noted in IE Insp Rept 50-244/83-05 W/o notice of violation STAROSTECKI.R Division of Project & Resident Programs 83 MAIER, J E Rochester Cas & Electric Corp 2pp 18944 166 Fichs 30-244.83/06/21,8306230317
- --8306230322 IE Enforcement Conference Rept 50-244/83-16 on 830401 Major areas discussed failure to perform proper post-maint testing on containment personnel hatch.
 ZIMMERMAN.R P Region 1. Office of Director KISTER,H B
 Division of Project & Resident Programs 83/06/16 3pp.
 18944.168 24X Fiche 50-244,63/06/21,8306230317.
- 8305110475 IE Info Notice 83-40, "Need to Environmentally Qualify
 Epoxy Grouts & Sealers," Svc list encl
 JORDAN, E L Division of Emergency Preparadness & Engineering
 Response (Post 830103), 83/06/22 Consolidated Edison Co of New
 York, Inc 115pp 19021 179 24X Fiche 50-000,83/06/22,8305110475
- 9305110477 IE Info Notice 83-41. "Actuation of Fire Buppression Sys Causing Inoperability of Safety-Related Equipment." Syc list Division of Emergency Preparedness & Engineering Post 830103) 83/06/22 Consolidated Edison Co. of New 120pp, 18997,007 24% Fiche 50-000,83/06/22,8305110477 JORDAN, E L D Response (Post York, Inc.
- 8305110479 IE Info Notice 83-42, "Reactor Mode Switch Malfunctions " 305110479 IE into Notice Borner Research No. 1007 Into No.
- 83051104B3 IE Info Notice 83-43, "Improper Bettings of Intermediate Range (IR) High Flux Trip Setpoints." Svc list encl. JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/24 Consolidated Edison Co. of New York, Inc. 116pp 19046.297 24X Fiche 50-000.83/06/24,8305110483
- R Periodic operating reports & related correspondence
- 8306020274 Monthly operating rept for Mar 1983 H/830404 ltr. MCNAMARA, A E , 8NOH, B A Rochester Gas & Electric Corp. 83/04/04 7pp 18690 298 24X Fiche, 50-244, 83/04/04, 8306020274.
- 8306160485 Monthly operating rept for Apr 1783 H/830506 ltr SNOW B A , MCNAMARA-A E Rochester Cas & Electric Corp 83/05/06 Office of Management and Program Analysis, 6pp 18864 128, 24X Fiche 50-244,83/05/06,8306160485
- 8306020451 "Annual Rept of Facility Changes, Tests & Experiments Conducted W/o Prior Approval & Challenges to Primary & Gacondary Bys PORVs & Safety Valves, 1781 "
 MAIER, J. E. Rochester Cas & Electric Corp. 83/05/20 ALLAN, J. M. Region 1, Office of Director 22pp. 18693 348 24X
 Fichs 50-244,83/05/20,8306020451.
- 8304020453 "Annual Rept of Facility Changes, Tests & Experiments Conducted M/o Prior Approval & Challenges to Primary & Secondary Bus PDRVs & Safety Valves: 1982." MAIER.J. E Rochester Qas & Clectric Corp. 83/05/20 ALLAN.J N Region 1, Dffice of Director 32pp 10493.306 24X Fiche 50-244,83/05/20,8306020453.
- B Reportable occurrences, LERs & related correspondence
- B30A170201 LER B3-01B/03L-0 on B2012A,RCB average temp reduced to less than 350 F & both reactor coolant pumps inoperable. Caused by personnel follower to incorporate Tech Bpecs. W/B30B27 ltr.
 MEYER.T.A. MAIER,J E. Rochester Gas & Electric Corp. 83/05/27.
 ALLAN,J M. Region I. Office of Director 4pp. 18877.020. 24X
 Fiche 30-244.03/05/27.8306170201
- 8306210034 LER B3-017/03L-0 on B30501, RNR pumps A & B took suction from refueling water storage tank (RUST) for filling reactor refueling cavity RNR pump stopped & flow dropped to zero Caused by power failure to MCC D circuit. W/B30831 ltr.
 LARIZZA, 0 f , MAIER, J E Rochester Das & Electric Corp. B3/05/31.
 ALLAN, J M Region 1, Office of Director. 3pp 18912:288. 24% Fiche 50-244,83/05/31,8306210034.

V Operator Examinations

8306140243 Requests attendance at B30627 meeting in King of Prussia.PA to discuss transfer of reactor operator licensing function from Bethesda.MD to Region I of:
8TAROSTECKI.R. Division of Project & Resident Programs 83/06/09 MAIRR.J E Rochester Oax & Electric Corp 2pp 18833 003 24X Fichs 50-244.83/06/09.8306140243

DOCKET 50-245 MILLSTONE NUCLEAR POWER STATION, UNIT 1 F Security, medical, emergency & fire protection plans

830&07013& Forwards Rev 16 to modified amended security plan. Rev withheld (ref 10CFR2 790 & 10CFR73 21)
COUNSILH & Northeast Nuclear Energy Co. (subs. of Northeast Utilities)
COUNSILH & Northeast Utilities 83/05/12
ALLAN.J.H Region 1, Defice of Director. 1p 18739.215 24X
Fichs.50-245,83/05/12.830&07013&

8304090238 Forwards IE Insp Repts 50-245/83-11 & 50-336/83-13 on B30417-0507 No noncompliance mated 8TAROBTECKI.R. Division of Project & Resident Programs 83/05/27 COUNSIL.W & Northeast Nuclear Energy Co (subs of Northeast Utilities). 2pp. 18795-299. 24X Fichs: 50-245,83/05/27,8304090238

--B306090241 IE Insp Repts 50-245/83-11 t 50-336/83-13 on 830417-0507 No noncompliance noted Major areas inspected evaluations of plant operations startup testing equipment alignments the readiness; radiation protection to physical security BHEDLOSKY, J T, LIPINSKI, D.R. Region I, Dffice of Director ELSABSER, T C. Division of Project & Resident Programs B3/05/20, 17pp. 18795:301. 24X Fichs: 30-245,83/05/27,8306090238

8304200307 Ack receipt of 830225 & 0415 ltrs informing NRC of steps taken to correct violations noted in IE inap Repts 50-245/83-01 & 50-336/83-01 Confirms understanding that uninterruptable power supply sys was operable by 830501. MARTIN.T.T. Division of Engineering & Technical Programs 83/06/15. COUMBIL.W 0 Northeast Nuclear Energy Co (subs of Northeast Utilities) 2pp 18700 164 24X Fiche: 50-245,83/06/15,8306200307

~-8306200313 Responds to NRC Itr re violations noted in IE Insp.
Repts 50-245/83-01 & 50-336/83-01 Forwards info requested
during IE security insp Info withheld (ref 105F873.21 &
105F82.7901.
COUNSIL.H G. Northeast Nuclear Energy Co (subs of Northeast
Utilities). COUNSIE.H.G. Northeast Utilities, 63/02/25.
HAYNES,R C. Region I, Office of Director. ip 18900:166 24X
Fiche: 50-245.83/06/15.8306200307.

--8306200322 Responds to MRC ltr re violation noted in IE Insp Repts 50-245/83-01 & 50-336/83-01. Forwards info requested during IE security insp Info withheld (ref 10CFR73, 21 & 10CFR2,790).

COUNSIL, H O. Northeast Nuclear Energy Co (subs. of Northeast Utilities). COUNSIL, H O. Northeast Utilities 83/04/15 ALLAN, J M Region I. Office of Director. Ip. 18706 167, 24% Fiche: 50-245,83/06/15,8306200307.

H General correspondence

8304060070 Requests rev to "cc" distribution list for NRR correspondence reflecting position & title changes within utils. COUNSIL, W. O. Connecticut Yankse Atomic Power Co. COUNSIL, W. O. Northeast Utilities COUNSIL, W. O. Northeast Nuclear Energy Co (subs. of Northeast Utilities). B9/05/31 CLARK, R. Operating Reactors Branch 3. CRUTCHFIELD D. Operating Reactors Branch 5. 3pp. 18719:360. 24X Fichs:50-000, B3/05/31, B306060090

I Financial information

8304110736 Forwards financial info for Connecticut Light & Power Co & Hastern Massachusetts Electric Co for 1782, Rept for Mortheast Nuclear Energy Co will be available on or about 830415.
BISHOP, R. W. Northeast Utilities. 83/04/05. Office of Nuclear Reactor Regulation, Director. 71pp. 17916:248, 24% Fichs: 50-245, 83/04/05, 8304110936

P. Operating license stage documents & correspondence

8304060031 Add1 response to FOIA request for three categories of documents of FRA of reactor safety study methodology application program repts & interim reliability evaluation program repts. Forwards App A documents. Bearch continuing. FELTON.J.M. Division of Rules and Records. 83/04/07 8HoLLY, 8 C, Union of Concerned Scientists. 3pp 18782:001. 24X Fiche: 50-000.83/04/07.8304040051.

- --821182033R Forwards "Effect of Resolution of Millstone Unit 1 SEP Issues on Probabilistic Calculations of Risk" & risk-based perspective of selected SEP issues
 ERNBT.N L. Assistant Director for Technology Review 82/11/15
 MIRAGLIA:F Assistant Director for Safety Assessment 12pp
 18752 079: 24X Fiche 50-000,83/04/07,8306060051
- --B211220337 "Effect of Resolution of Millstone Unit 1 SEP Issues on Probabilistic Calculations of Risk" SPULAK.R G . STACK.D . AMICD,P Science Applications, Inc SAND82-2429 82/11/15 NRC - No Detailed Affiliation Given 108pp 18752 091 24X Fiche 50-000.83/04/07.8304040051
- --8306060061 Statement on background, issues, current states & future action re interim & natl reliability evaluation programs
 * NRC No Detailed Affiliation Given 82/12/31 Ppp
 18752 059 24X Fiche 50-000,83/04/07,8306060051

8305310226 INTERIM RELIABILITY EVALUATION PROGRAM ANALYSIS OF THE MILLSTONE POINT UNIT I NUCLEAR POWER PLANT Docket No 50-245 (Northeast Utilities) CURRY, J J , GALLAGHER, D M , MODARRES, M Sandia Laboratories FIN A-1241 NUREG/CR-3085 Vol. 83/04/30 Division of Risk Analysis 2019p 18682 277 24X Fiche 50-245.83/04/30,8305310226

830&010,340 Forwards Rev 13 to corporate organization for nuclear incidents procedures manual table of contents & Rev 3 to CONI 4 02. "On-Call Manager of Radiological Consequence Assessment, Responsibilities & General Guidelines " W/o encl COUNSIL, W 6 . SEARB, C F Connecticut Yankee Atomic Power Co COUNSIL, W 0 . Northeast Nuclear Energy Co (subs of Northeast Utilities) B3/05/18 EISENIUT, D 6 Division of Licensing 1p 18682 271 24X Fiche 50-000, 83/05/18, 8306010340

B30608005B Forwards info re environ qualification of electrical equipment including in-containment environ avo conditions, methods used to identify equipment per 10CFR50 47(b)(2) & preventative maint program COUNSIL,W 0, BEARB,C F, Northeast Nuclear Energy Co (subs of Northeast Utilities B3/05/20 EIGENHUT,D 0 Division of Licensing 419pp 18775 116 24X Fiche 50-245,83/05/20,8304080058

B306060207 Notifies that Apr 1783 rept. "Shaking-Table Teating for Beismic Evaluation of Electrical Raceway Bys." applicable to facilities for SCP Topic III-6 re seismic design NUREO-0824 k NUREO-0826 commitments partially satisfied COUNSIL.W 9 Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL.W 0 Connecticut Yankee Abomic Power Co COUNSIL.W 0 Northeast Utilities 83/05/26 CRUTCHFIELD, D Operating Reactors Branch 5 1p 18797 295 24X Fiche 50-000.B3/05/26.8304060207

8306070232 Advises that NUREO-OB24, Bection 4 1.6 concerns resolved, based on util 830113 response, per SEP Topic II-3 D 1, "Capability of Operating Plant to Cope W/Design Basis Flooding Conditions" Procedure OP 514A revised by 830727 COUNSIL. W 0 Northeast Nuclear Energy Co (subs. of Northeast Utilities) COUNSIL. W 0 Northeast Utilities 83706703 CRUICHFIELD, D Operating Reactors Branch 5 2pp 18795 344 24X Fichs 50-245,83706703,8306090232

B304160283 Notice of consideration of issuance of amends to Licenses DPR-21 & DPR-65 & proposed no significant herards consideration determination & opportunity for hearing CLARK, R. A. Operating Reactors Branch 3 B3/06/03 10pp 18873-010 24X Fiche 50-245, 83/06/03, 8306160283

830608019B Informs that requirements of TMI Item II B 2.2. "Design Review of Plant Bhislding & Environ Gualification of Equipment for Spaces/Sys Which May Be Used in Post-Accident Operations:" met CRUTCHIELD, D. Operating Reactors Branch 5 83/06/07 COUNSIL, H. Northeast Nuclear Energy Co. (subs of Northeast Utilities) 6pp 18772 233 24X Pichs 50-245.83/06/07,8306080198

8306070267 Forwards safety evaluation of BWR Owners Group response to NUREO-0737. Item II K 3 18. "Mod of Automatic Depressuritation Bys Logic... " Acceptable options include slimination of high drywell pressure permissive GRUTCHFIELD.D Operating Reactors Branch 5 83/06/08 COUNSIL, W 6 Northeast Nuclear Energy Co (subs of Nuclear Energy Co (subs of Northeast Nuclear Energy Co (subs of N

--B306090272 Bafety evaluation of BWR Owners Group response to NUREO-0737. Item II K 3 IB. "Mod of Automatic Depressurization Sys Logic.,." Acceptable options include elimination of high drywoll pressure permissive.

" Office of Nuclear Reactor Regulation. Director 83/06/08 5 19795-282 24X Fichs 50-245,83/06/08,8306090267

- 8306130356 Forwards safety evaluation supporting util decision not to remoute reactor water cleanup sys return line per NUREO-0619 Decision based on value-impact analysis & sleeve
 - leakage measurements BHEA, J. J. Operating Reactors Branch 5 83/06/09 COUNSIL. Northeast Nuclear Energy Co. (subs. of Northeast Utilities) 18822 153 24X Fiche 50-245.83/06/09.8306130356 COUNSIL.W C
- --8306130358 Bafety evaluation supporting util decision not to reroute reactor water cleanup sys return line per NUREO-0619
 Docision based on value-impact analysis & sleeve leakage measurements * Office of Nuclear Reactor Regulation, Director 18822 155 24X Fiche 50-245,83/06/09,8306130356 83/04/09 200
- 8304140412 Forwards draft Rev 5 to "GA Program Topical Rept "
 GDUNSIL, N G Northeast Utilities Service Co CDUNSIL, N G
 Northeast Utilities B3/04/09 MURLEY, T E Region I, Office of
 Director 6pp 18839 090 24X Fiche 50-000, 83/04/09,8206140412
- --8306160424 Draft Rev 5 to "GA Program Topical Rept "
 * Northeast Utilities 83/06/07 135pp 18859 096 24X
 Fiche 50-000 83/06/09 8306160412
- B304230289 Forwards addd info per TMI ltem II K 3 28 re qualification of automatic depressurization sys accumulators in response to NRC B30218 request M/two oversize drawings Aperture cards are available in PDR CDUMBIL, W Q Northeast Nuclear Energy Co (subs of Northeast Utilities) 83/06/15 CRUTCHFIELD, D Operating Reactors Branch 5 19pp 18942 108 24X Fiche, 50-245, 83/06/15, 8306230289
- B304240200 Forwards listed revs to Corporate Organization for Nuclear Incidents procedure manual, per Section V of App E to 100FR50 M/o encl Counscitut Yankee Atomic Power Co COUNSIL, W O TOURHOO N/A encl COUNBIL,N & Connecticut Yankee Atomic Power Co COUNBIL,N & Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNBIL,N & Northeast Utilities B3/06/17 EISENHUT,D & Division of Licensing 2pp 18980 263 24X Fichs.50-000,B3/06/17,
- 8306280534 Forwards proprietary Suppl 7 to "STR Bundle Bubmittal Millstone-1. Begmented Test Rod Dundle." updating 741003 rept.per Reload 2 license amend 00 Sherwood affidavit encl Rept withhald (ref 10CFR2 790).

 GOUNSIL.W 0 Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL.M.O. Northeast Utilities 83/06/17.

 CRUTCHFIELD.D Operating Reactors Branch 5 Spp 19016, 292, Fiche 50-245, 83/06/17, 8306280534 19016,292, 24X
- 8304280412 Forwards response to 830422 request for add1 info re Rev 1 to NUREQ-0313 concerning leakage detection sys CDUNBIL, W Q Northeast Nuclear Energy Co. (subs. of Northeast Utilities), CDUNBIL, W Q Northeast Utilities 83/06/21 CRUTCHFIELD, D Operating Reactors Branch 5. 95pp 19020 188 24% Fiche. 50-245, 83/06/21, 8306280412
- 8306280321 Discusses impact of NUREO-0824.8EP Topic III-4 B. "Turbine Missiles," on control valve surveillance testing program No changes to current testing program No changes to current testing program warranted litem closed. COUNSIL.W O Northeast Nuclear Energy Co (subs. of Northeast Utilities) COUNSIL.W Q Northeast Utilities, 63/06/22 CRUTCHFIELD,D. Operating Reactors Branch 5 2pp 19001-312, Fiche. 50-245, 63/06/22, 8306280321 19001-312, 24X
- BSQ6280478 Provides info re SEP Topic VI-4, "Containment Isolation Sys." to resolve concern raised by NUREG-0824, "Integrated Plant BaPety Assessment." for which NRC unable to determine adequacy of penetrations X-211A & X-204 COUNSIL, W G Northeast Nuclear Energy Co. (subs. of Northeast Utilities) COUNSIL, W G Northeast Utilities BS/06/22, CRUCKHIFIELD, D. Operating Reactors Branch 5 2pp 19018; 313, 24X Fichs 50-248, 83/06/22, 8306280478.
- B30-6300140 Informs that add1 nondegree personnel will be assigned to shift technical advisor position per NUREQ-0737. Item I A 1 i Info re experience, college sduc & current operator licenses encl COUNSIL, H. 9 Northeast Nuclear Energy Co. (subs. of Northeast Utilities) COUNSIL, H 9 Northeast Utilities B3/04/22, GRUTCHFIELD, D Operating Reactors Branch 5 CLARK, R A Operating Reactors Branch 5 CLARK, R & Operating Reactors Branch 5 S10-245,83/04/22, B30-6300-140. B306300140.
- 830.6290406 Forwards safety evaluation of licenses compliance w/ NUREQ-0737, Item II B. i. "RCS Vents." based on review of encl LLL technical evaluation rept. High point vents on primary coolant side of isoletion condenser not required. CRUTCHFIELD.D. Operating Reactors Branch 5. 83706/27 COUNSIL, W. O Northeast Nuclear Energy Co. (subs. of Northeast Utilities) App. 19053:140 24X Fichs. 50-245,83706/27,8306290406.

- --8306270413 "Belected Operating Reactor Issues Program II RCB Vents (NUREG-0737, Item II B 1), " final technical evaluation rept HELD. J T Energy Incorporated * Lawrence Livermore Laboratory FIN A-0250 TF-382/0823A 83/04/06 ALBERTHAL, © Division of Licensing 4pp 19053 146 24X Fiche 80-245.83/06/27,8306270406
- G Inspection reports, IE Bullotins & correspondence
- 8304040160 Forwards IE Insp Repts 50-245/83-06 & 50-336/83-08 on B30227-0416 & notice of violation STAROSTECKI.R Region 1. Office of Director. B3/05/23 COUNBIL.W Q Northeast Nuclear Energy Co. (subs of Northeast Utilities) 2pp 18719 205. 24X Fiche 50-245.83/05/23.8306060160
- --8306060165 Notice of violation from insp on 830227-0416
 * Region 1, Office of Director 83/05/23, 1p 187
 Fichs 50-245,83/05/23,8306060160 19719 207 244
- --830&0&0171 IE Insp Repts 50-245/83-06 & 50-33&/83-08 on 830227-0416 Noncompliance noted failure to maintain reactor power below 89% while monitoring core linear heat rate w/ex-core detector monitoring sus SHEDLOBKY, J T, LIPINGKI, D, R., ELBASSER, T C Region 1, Office of Director, 83/05/21 19pp. 18719, 208, 24% Fiche 50-245, 83/05/23, 830&040160
- 8305110458 IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in Well Logping Device," Svc list encl.
 TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103), 83/05/26. Consolidated Edison Co. of New York, Inc. 125pp 18831.043 24X Fiche.50-000.83/05/26,8305110458.
- 8305110460 IE Info Notice 83-34, "Event Notification Info Workshoot " 305110460 LE Info Notice 83-34, "Event Notification info worksheet " Svc list enc! JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 115pp 18732 085 24X Fiche; 50-000.83/05/26.8305110460
- 8306090238 Forwards IE Insp Repts 50-245/83-11 & 50-336/83-13 on 830417-0507. No noncompliance noted 8TAROSTECKI.R. Division of Project & Resident Programs. 83/05/27 COUNSIL.H Q. Northeast Nuclear Energy Co. (subs. of Northeast Utilities) 2pp. 18795.297. 24X Fiche 50-245.83/05/27.8306090238. STAROSILON...
 COUNSIL.W Q. Nort
- --8306090241 IE Insp Repts 50-245/83-11 & 50-336/83-13 on 830417-0507. No noncompliance noted Mejor areas inspected: evaluations of plant operations, startup testing, equipment alignments & readiness, radiation protection & physical security.

 8HEDLOSKY, J. T. LIFINGKI, D. Region i, Office of Director. ELBASBER, T. C. Division of Project & Resident Programs B3/05/20.

 17pp 18795 301 24X Fichs. 50-245, 83/05/27, 8306090238.
- 8305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods Withdrawn at BWRs " 8vc list enci JORDAN E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/05/31 Consolidated Edison Co. of New York Inc. 116pp 18732-208 24X Fichs.50-000,83/05/31,8305110461
- 8306170391 Responds to IE Bulletin 83-03. "Check Valve Failures in Raw Water Gooling Sys of Diesel Generators " No check valves installed in loop of piping to diesel generators from syc AGE VALUES IN loop of piping to diesal generators from syc water piping
 GUNNBIL, M.Q. Northeast Nuclear Energy Co. (subs. of Northeast
 Utilities). CDUNBIL, W.O. Connecticut Yankes Atomic Power Co.
 CDUNBIL, W.O. Northeast Utilities 83/03/31, MURLEY, T.E. Regio
 Diffice of Director. 3pp 18880-240. 24X Fiche: 50-000, 83/05/31,
 8306170391 Region L
- B305110464 IE Info Notice 83-36, "Impact of Security Practices on Sefe Operations," Syc list encl.
 JORDAN E L. Division of Emergency Preparedness & Engineering Response (Post 830103) B3/06/07 Consolidated Edison Co. of New York, Inc. 119pp 18830 280 24% Ficher 50-000,83/06/09,8305110464.
- 8305110470 IE Info Notice 83-38, "Defective Heat Sink Adhesive & SOSIO470 IE Info Notice 83-38. "Defective Heat Sink Adnesive & Beismically Induced Chatter in Relays Within Printed Circuit Cards." Svc list encl.
 JORDAN E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/06/13. Consolidated Edison Co. of New York, Inc. 118pp. 18920.225. 24X Fiche.50-000.83/06/13.8305110470
- 830A090010 IE Info Notice 83-37, "Trensformer Failure Resulting From Degraded Internal Connection Cables " Svc list encl. JORDAN.E.L. Division of Emergency Preparadness & Engineering Response (Post 830103) 83/06/13. Consolidated Edison Co. of New York, Inc. 243pp. 18921.001, 24X Fiche: 50-000, 83/06/13,8306090010.

- 8306200307 Ack receipt of 830225 & 0415 ltrs informing NRC of steps taken to correct violations noted in IE Insp Repts 50-245/83-01 & 50-336/83-01 Confirms understanding that uninterruptable power supply says was operable by 830501.

 MARTIN.T.T Division of Engineering & Technical Programs 83/06/15.

 COLMBIL.W Q Northeast Nuclear Energy Co (subs. of Northeast Utilities) 2pp 18900-164 24X Fiche 50-245,83/06/15.8306200307
- --BJ06200313 Responds to NRC ltr re violations noted in IE Insp.
 Repts 50-245/83-01 & 50-036/83-01 Forwards into requested
 during IE security insp. Info withheld (ref 100FR73 21 &
 100FR2 790).
 COUNBILL W G. Northwast Nuclear Energy Co (subs. of Northwast
 Utilities). COUNBILL N. O. Northwast Utilities, 83/02/25
 HAYNES, R C. Repion 1. Office of Director 1p. 18900 166, 24X
 Fiche: 50-245.83/06/15, 8306200307.
- --B306200322 Responds to NRC ltr re violation noted in IE Inap Repts 50-245/83-01 & 30-336/83-01. Forwards info requested during IE security insp. Info withheld (ref locFR3 21 & locFR2 790) COUNSIL.H 0. Northeast Nuclear Energy Co. (subs of Northeast Utilities). COUNSIL.N 0. Northeast Utilities 83/04/15. ALLAN.J.H. Region I. Office of Director ip 18900 167, 24X Fichs. 50-245.83/06/15. B306200307.
- 8305110475 IE Info Notice 93-40, "Need to Environmentally Qualify Epaxy Grouts & Seslers " Byt list and!, JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/22 Consolidated Edison Co of New York, Inc 115pp. 19021 179 24X Fiche, 50-000, 83/06/22, 8305110475
- 8305110477 IE Info Notice 83-41, "Actuation of Fire Suppression Sys Causing Inoperability of Safety-Related Equipment " Syc list and! JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/22. Consolidated Edison Co. of New York, Inc. 120pp 18997.007. 24X Fiche 50-000.83/06/22.8305110477
- 8305110479 IE Info Natice 83-42, "Reactor Mode Switch Malfunctions." Svc list encl. JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/06/23. Consolidated Edison Co. of New York, Inc. 116pp. 18996-242 24X Fiche 50-000,83/06/23,8305110479
- 8305110483 IE Info Notice 83-43, "Improper Settings of Intermediate Range (IR) High Flux Yrip Setpoints," Syc list encl.
 JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103), 83706/24 Consolidated Edison Co. of New York, Inc. 116pp. 19046:297 24X Fichs: 50-000,83706/24,8305110483.
- R. Periodic operating reports & related correspondence
- 8305020084 Monthly operating rept for Mar 1983 H/830415 ltr.
 HARRAN.Q., MROCZKA,E.J. Northeast Nuclear Energy Co. (subs. of
 Northeast Utilities) MROCZKA,E.J. Northeast Utilities. 83/04/02
 Diffice of Resource Management, Director. App. 18591:210, 24X
 Fiche: 50-245, 83/04/02, 8306020084.
- 8306160388 Monthly operating rept for Apr 1983 W/830512 ltr. HARRAN 9.: NROCKA,E.J. Northeast Utilities, HROCKA,E.J. Northeast Nuclear Energy Co (subs of Northeast Utilities). 83/05/03. 6pp. 18861 132. 24X Fichs: 30-245.83/05/03,8306160388.
- 8306060263 Documents understanding that 30-day extension for submittal of semiannual mati balance rept for Oct 1782 Mar 1783 acceptable; per 830427 & 0503 discussions Extension necessary due to coaputer groblems at OE.

 COUNSILIM, O Northeast Nuclear Energy Co. (subs of Northeast Utilities). COUNSILIM O. Northeast Utilities. 83/05/04.

 BURNETIRE, NRC No Detailed Affiliation Given. 1p 18727:025.

 24X Fiche-50-245,83/05/04.8305060263.
- 8 Reportable occurrences, LERs & related correspondence
- 8306010434 Updated LER 83-012/03x-1:on 830326.during repair of containment leakage.LPCI/CB valve permissive interlock switch valved out of exc. Caused by switch not restored to proper lineup after testing. H/830823 ltr
 THULL,T.S. HERBERT,R.J. HROCZKA,E.J. Northeast Nuclear Energy Co. (subs of Northeast Utilities). 83/03/23. HURLEY,T E. Region 1, Dffice of Director 3pp. 18674:151, 24X Fiche 50-245.83/05/23, 8306010434.
- 830A020397 RO 83-02.on 830283, excessive levels of activity observed in tample of averals Dose consequences evaluated for First Quarter 1983 by using effluent transport models. No operational corrective actions necessary.

 HROCKALE J., NERBERT.R.J., Northeast Nuclear Energy Co. (subs. of Northeast Utilities). HROCKALE J. Northeast Utilities 83/05/24 MURLEY.T.E. Region 1. Office of Director. 3pp. 18695:100 24X Fiche: 50-245.83/05/24.8306020397.

- 8306030319 LER 83-017/03L-0 on 830502, during reactor low pressure pumpstant functional & calibr test, pressure switch 263-54A tripped at 379 psig Caused by setpoint drift Switch adjusted & tested satisfactorily H/830527 itr
 THULL.T B, HROCZKA.E J Northeast Nuclear Energy Co (subs of Northeast Utilities) MROCZKA.E J Northeast Utilities B3/05/\$\frac{1}{24}\$\frac{1}{2}\$ MURLEY,T E Region 1, Dffice of Director 3pp. 18708.26b 24\$\frac{1}{2}\$
- 8304030326 tER 83-016/03t-0 on B30502, pressure switch 263-55A tripped at 1:107 psig. exceeding Tech Spec requirements of less than or equal to 1:085 psig Caused by setpoint drift Switch recalible W/830527 ltr.
 THULL.T B. HRDCZKA.E J. Northeast Nuclear Energy Co. (subs. of Northeast Utilities) MRDCZKA.E J. Northeast Utilities B3/05/2, MURLEY.T E. Region 1: Office of Director. 3pp. 18708 268 24% Fiche 50-245,83/05/27.8306030326
- 8306170046 LER 83-019/03L-0 on 830503, during reactor low pressure value permissive functional & calibr test pressure switch 263-52A tripped at 364 paig Caused by setpoint drift Pressure switch adjusted to proper setpoint & tested W.800602 Ltr THULLITS, MRDCZKA,E J. Northeast Nuclear Energy Co. (subs. of Northeast Utilities) MRGCZKA,E J. Northeast Utilities B3/05/02 MRRCZKA,E J. Southeast Utilities B3/05/02 MRRCZKA,E J. Southeast Utilities B3/05/02 Fiche 50-245,83/06/02,8306170046
- 8306170300 RO 83-20/1P on B30407.crack indication identified on 1 x & inch weldolet weld. Weldolet supports nipple & flange to relief valve 1-CU-73 investigation & encapsulation of weld for repair in progress HRDCZKA.E J Northeast Nuclear Energy Co (subs of Northeast Utilities B3/06/08 MRDCZKA.E J Northeast Utilities B3/06/08 MRDCZKA.E J Northeast Utilities B3/06/08 MRDCZKA.E J Northeast Utilities B3/06/08 Fiche 50-R45.83/06/08 B306170300
- 8306270129 LER B3-021/031-0 on 830517, time delay relays 590-125A & B tripped at Jimits exceeding Tech Specs Caused by tolerance established on surveillance data sheets less than setpoint accuracy of relays Setpoints decreased W/B306/6 ltr THULL.T 8, MROCZKA,E J Northeast Nuclear Energy Co (subs of Northeast bilities) MRDCZKA,E J Northeast Utilities. B3/05/16 MRRLEY,T E Region 1, Office of Director 4pp 18988-014 24x Fiche, 50-245,83/06/16.8306270129
- 8306230001 PNB-I-83-015 on 830616, unannounced narcotics search of site initiated & one mariguans cigarette found in pocketbook belonging to contract security watchperson Individuals employment terminated MADDEN. W. of ODY, A. JOYNER, J. Region 1. Office of Director 83/06/17. 1p 18947.077 24X Fiche 50-245,83/06/17.8306230001
- V Operator Examinations
- 830&140453 Extends invitation to attend 830&27 meeting in King of Prussia.PA to discuss transfer of reactor operator licensing function from Bethesda,MD to Region I ofc BTAROSTECKI.R Division of Project & Resident Programs. 83/06/09 GOUNSIL.W @ Northeast Nuclear Energy Co. (subs of Northeast Utilities). 2pp 18834-311 24X Fiche 50-248.83/06/09.8306140453
- BOCKET 50-247 INDIAN POINT STATION, UNIT 2

 F Security, medical, emergency & fire protection plans
- 8304010365 Forwards IE Insp Rept 50-247/83-11 on 830405-0502 & notice of violation STAROSTECKI,R. Division of Project & Resident Programs 63/05/16 O'TOOLE,J D Consolidated Edison Co of New York, Inc 3ep. 18682.073 24X Fiche: 50-247,83/05/16.8306010365
- --8306010370 Notice of violation from Insp on 830405-0502 Safeguards in! deleted (ref 10CFR73 21) * Region I. Office of Director 83/05/16 Ip 18692.076 24x Fiche. 50-247.83/05/16,8306010365
- --6306010378 IE Insp Rept 50-247/83-i1 on 630405-0502 Noncompliance noted; failure to follow procedures Safeguards into deleted (yet 10CFR73 21). FOLEY, T., KOLTAY, P. Region i, Office of Director KIBTER, H B. Division of Project & Resident Programs 83/05/11. 14pp. 18482 077 24X Fiche 50-247,83/05/16.8306010345
- 8306090299 Confirms by ltr of intent, contract to make buses available during evacuation caused by radiological emergency VHAAD, E.R. Consolidated Edison Co. of New York, Inc. * Power Authority of the State of New York, CORNIN, 8 Affiliation Unknown B3/06/01 CORNIN, 8 Affiliation Unknown ip 18798-238 24X Fiche. 50-247, 83/06/01.8304090299

- B30A090317 Confirms, by 1tr of intent, contract to make buses available during evacuation caused by radiological emergency VHAAD, E R Consolidated Edison Co of New York, Inc BAYNE, J P Power Authority of the State of New York * Affiliation Unknown B3/06/01 SILVANIO.J Affiliation Unknown ip 18795 230 24X Fithe 50-247.83/06/01.8304090317
- B304090325 Confirms by 1tr of intent.contract to make buses available during evacuation casued by radiological emergency # Consolidated Edison Co of New York. Inc. BAYON, J.P. Power Authority of the State of New York MURPHY, J. Liberty Lines Transit, Inc. B3704/02 MURPHY, J. Liberty Lines Transit, Inc. Ip. 18795-049 24X Fiche 50-247,83/06/02.8306090325
- B306090340 Confirms, by 1tr of intent, contrart to make buses available during evacuation caused by radiological emergency * Consolidated Edison Co of New York, Inc BAYON, J.P. Power Authority of the State of New York * Riverdale Transit Corp B3/06/02 MURPHY, J. Riverdale Transit Corp 1p 18794 321 24x Fiche 50-247, 83/06/02, 8306090340
- 8306150206 Staff requirements memo re 830526 oral presentations in Bethesda. MD re emergency planning & preparedness at Indian Point List of participants encl CHILK, 8 J Office of the Secretary of the Commission 83/06/07
- 8306170396 Forwards FEMA B3060B ltr to NRC.providing current evaluation of plant offsite emergency planning HASBELL.D F Hearing Dranch 2 B3/06/09 QLEASON, J P. BHON, F J. PARIB, O H Atomic Safety and Licensing Board Panel 46pp 18879 333 24% Ficho 50-247,83/06/09.8306170396
- 8306200030 Staff requirements memo re 830607 discussion & vote in Washington, DC on continued operation of Indian Point Commission agreed by vote of 3-2 to allow continued operation CHILK, B. J. Office of the Secretary of the Commission 83/06/14 Office of the Secretary of the Commission 19 18708 356 24X Fichs 50-247,83/06/14,8306200030

Q Adjudicatory correspondence

- 8305160024 Forwards I Levi affidavit clarifying 830211 testimony on suggested method of making sensible probability judgments described in Boction 5 HARTZMAN:R M Friends of the Earth 83/05/10 GLEABON, J P Atomic Safety and Licensing Board Panel Ip 18452 353 P4X Fiche 50-247.83/09/10,8305160024
- B306010451 Supports continued operation of Pacility Impact of shutdown would be devastating O'SHAUDINGESY Affiliation Unknown B3/05/20 PALLADINO,N J Commissioners 2pp 18674 352 24X Fiche 50-247, B3/05/20, B306010451
- 8304040180 Response opposing util 830509 motion for reconsideration.

 Deposition inadmissible as evidence under federal pules

 POBNER.P Parents Concerned About Indian Point 83/05/20 Atomic

 Bafety and Licensing Board Panel 3pp 18728 181 24X

 Fiche 50-247,83/05/20.8304040180
- B30601045B Requests extension of B30609 deadline for planners to provide adequate emergency evacuation Util acting in good faith in expressing concern for quality of life of community residents
 BARNETF, T Affiliation Unknown B3/05/24 PALLADINO, N J Commissioners 1p 18674 327 24X Fiche 50-247, B3/05/24, B30601045B
- 8306010348 Response supporting licensee 830509 motion for reconsideration of ruling on admissibility of DP McOuire disposition Admission of testimony would not prejudice parties W/Certificate of Svc HASSELL,D F Hearing Granch | 83/05/31 Atomic Sefety and Licensing Doard Panel lipp, 18681 336 24X Fiche 50-247,83/05/31,8306010348
- 8306020443 Order requesting comments on encl rept re PRA by 830620. QLEASON, J P Atomic Safety and Licensing Board Papel 83/05/31 Consolidated Edison Co of New York, Inc. 1p. 18694 011 24X Ficher 50-247, 83/05/31, 8306020443
- --8306020448 Forwards final rept, "Analysis of PRA Testimony Indian Point ASLB Hearings, Commission Question 1 " Rept conclusions coincide w/conclusions in 830502 ltr
 AMICO,P J Applied Risk Technology Corp 83/06/01 @LEASON.JP, SHON,F J, PARIS,O H Atomic Safety and Licensing Board Panel.
 1p 18694 012 24X Fiche 50-247,83/05/31,8306020443

- ~~8306020452 "Analysis of PRA Testimony Indian Point ASLB Hearings, Commission Question 1." final rept ANICO.F J Applied Rist Technology Corp ARTECH-83-001 83706701 NRC - No Detailed Affiliation Given 67pp 18694 013 24X Fiche 50-247,83705/31.8306020443
- 8306200290 Affidavit of RA Rosen on Commission Question 6 3 EBRO model underestimated average 1982 seltwater PWR capacity by 9.5% Value of model should be assessed based on ability to track experience over period of time ROSEN, R A greater New York Council on Energy 83/05/31 5pp 18901 055 24% Fiche 50-247,83/05/31,8306200290
- 8306070414 Response opposing Friends of the Earth/Nsw York City Audubon Soc request to file I Levi affidavit. Testimony by affidavit improper since no cross-examination possible Certificate of Svc encl
 BRANDENBURG, B Consolidated Edison Co of New York, Inc.
 COLARULLI, P F Power Authority of the State of New York
 COLARULLI, P F Horgan Associates B3/06/03 Atomic Bafety and Licensing Board Panel 7pp 18742 264 24% Fiche 50-247,83/06/03, 8306070414.
- 8306070421 Expresses views on plant emergency preparedness in light of newly submitted state of NY interim plan Conceptual problems & inaccuracies identified in plan for implementing compensating measures for Rockland County HOLT, J. Public Interest Research Group. New York 83/06/03, PALLADING, N.J. AMEARNE, J.F., OLLINBKY, V. Commissioners 4pp. 18742 198 24X Fiche 50-247, 83/06/03, 8306070421
- 8304080200 Comments on "Governors Plan" prepared by NY State Disaster Commission Evacuation of wheelchair & bedridden patients & shelter for 1,200 mentally retarded patients overlooked FLEISHER, Z S West Branch Conservation Association 63/06/06 PALLADINO, N, GILINGKY, V, AHEARNE, J, F. Commissioners. 16pp. 18770 235 24X Ficher 50-247,83/06/06,8306080200
- 8304090359 Responds to Commission 830526 meeting questions & updates miscellaneous responses Record Justifies continued plant operation Commission would be fully justified in suspending further enforcement action CONHAY, J T Consolidated Edison Co of New York, Inc. BAYNE, J.P. Power Authority of the State of New York 83/06/07. PALLADINO, N.J., OIL INBKY, V. AHEARNE, J F Commissioners. 3pp 18795.036 24X Fiche 50-247,83/06/07.8306090357
- 8304090300 Recommendations for emergency plenning process.Plans should originate at local govt level & should be supported & enforced at state & federal govt levels # Public Interest Research Ordup. New York # Parents Concerned About Indian Paint 83706/08, 2pp 18795:239, 24% Fiche 50-247,83706/08,8306090300
- 8304090308 Btatement on role of federal, state & local govts & utils in planning, testing & executing emergency response procedures HOLT, J. Public Interest Research Group; New York, 63/06/08, 3pp 18795, 117 24% Fichs 50-247, 83/06/08, 8306090308.
- 9306100086 Forwards evaluation of offsite emergency planning, providing factual basis for use in Commission 830609 licensing decision BRAGO, J S Federal Emergency Management Agency. 83/06/08 PALLADING, N J Commissioners, 45pp, 18802.046 24X Ficher 90-247, 83/06/08.8306100086
- 8306100207 Hemorandum & order denying licensee 830507 motion for reconsideration of ABLB 830427 ruling disallowing admission into evidence of DP McQuire deposition Federal rule inapplicable & no exceptional circumstances shown.

 OLEABON: JF Atomic Bafety and Licensing Board Panel 83/06/08. Consolidated Edison Co of New York. Inc. 4pp 18805-202, 24X Fiche 50-247,83/06/08,8306100209
- 8306i30434 Order ruling I Levi affidavit, filed by Friends of the Earth & New York City Audubon Boc on B30510, inadmissible Affidavit provides add1 substantive testimony & will not be admitted unless witness available for cross-examination, QLEABON, J. P. Atomic Safety and Licensing Board Panel. B3/06/09, Friends of the Earth 2pp 18821, 192 24X Fiche: 50-247, 83/06/09, 8306130434.
- 8306170372 Advises that NRC will file comments on Amico final rept.
 Separate comments on interim ltr rept will not be filed.
 MODRE, J E Hearing Branch 1. 83706/09. OLEABON, J P., BHON, F J.,
 PARIS, O H Atomic Sefety and Licensing Board Panel. 1p 18860 Rio.
 24X Fiche 50-247,83/06/09.8306170372.
- 8306170396 Forwards FEMA 630608 ltm to NRC providing current evaluation of plant offsite emergency planning.
 HASBELL, D F. Hearing Branch 2 63/06/09, GLEASON, J. P., SHON, F. J., PARIS, O H. Atomic Safety and Licensing Board Panel 46pp, 18879 333 24X Ficher 50-R47, 83/06/09, 8306170396.

- 8306150387 Response to ASLB consultant, PJ Amico, 830502 ltr re insues on accident probability requiring additestimony. New York City Auduben Scr/Friends of the Earth comments endorsed Certificats of Syc encl.
 WEISS, E.R. Union of Concerned Scientists WEISS, E.R. Public Interest Research Oroup, New York WEISS, E.R. Harmon & Weiss 83/06/10 7pp 18847.152 24X Fiche: 50-247, 83/06/10, 8306150387
- 830615042? Advises that utils will respond to PJ Amico summary ltr rept & final rept on 830620.

 BRANDENBURG.B Consolidated Edison Co. of New York. Inc.
 COLARULLIP F Horgan Associates. COLARULLIP F Power Authority of the State of New York B3/06/10 CLEABON.JP. PARIS.D H.,
 SHON.F.J Atomic Sefety and Licensing Board Panel ip. 18847 089 24X Fiche 50-247,83/06/10,8304150429.
- 8306200324 Responds to P Amico 830502 ltr rept re recommendations for add1 testimony on FRA Reopening record on FRA would unduly prolong proceeding HARTZMAN.R.M. Friends of the Earth HARTZMAN.R.M. New York City Audubon Society. 83706/10 QLEASON.J.P., SHON.F.J., PARIS.O H Atomic 8afety and Licensing Board Panel. 2pp. 18701:018 24X Fiche 50-247.83706/10.8306200324
- 8306230376 Response to PJ Amico 830802 ltr to ASLB & analysis of PRA testimony. Areas in which add1 testimony recommended do not present issues materially affecting record & are too costly #/Gentificate of 8vc BRANDENBURG, B Consolidated Edison Co of New York, Inc COLARULIJF F Power Authority of the State of New York COLARULIJF F Norgan Associates, 83/06/20 19pp 18943 258, 24% Fiche 50-247, 83/06/20, 8306230376
- 8306240290 Response to ABLE consultant P Amico rept re add1 testimony on Commission Question i No add1 testimony necessary for complete record.

 MOOREJJ, MCGURREN, H. J. Hearing Branch i 83/06/20 i5pp 18979-241. 24X Fiche. 50~247.83/06/20.8306240290
- --B306240295 Affidavit of JF Meyer & RM Bernero re ASLB consultant P Amico B30601 rept. MARCH 1, J Code used to assess core-melt accident progression & containment loading cheracteristics K/Prof qualifications

 MEYER, J F Reactor Systems Branch BERNERD, R M Accident Source Term Program Office. 83/06/17 12pp 18979 256 24% Fiche 50-247.83/06/20,8306240290.
- --8306240301 Affidavit of QB Varnado re ASLB consultant PJ Amico recommendation to provide expert testimony on risk significance of sebotage NRC studies & PRA do not estimate risk of sebotage Prof qualifications encl VARNADO Q B. Sendia Laboratories 83/06/07. 4pp. 18979 268, 24X Fichs, 50-247, 83/06/20, 8306240290.
- --B30624030B Affidavit of HW Woods re ABLB consultant PJ Amico B30601 rept. Testimony on conditional probability of core melt & release due to pressurized thermal shock event unavailable. Wypref qualifications & Certificate of Bvc WODDB, H. H. NRC No Detailed Affiliation Given B3/06/16. 7pp, 18979, 272. 24X Fiche 30-247, B3/06/20, B306240290
- 6306230350 Motion for extension until 830711 to file proposed findings of fact. Time needed since intervenors filing consolidated findings to one atty suffered death in family. Certificate of 8vc enci. MEI89.E.R. Union of Goncerned Scientists. WEI89.E.R. Harmon & Weiss. 83/06/21 Abomic Safety and Licensing Board Fanel Opp. 18943,281. 24X Fiche'50-247.83/06/21.8306230350.
- 8306230346 Motion for immediate reconsideration of Commission 830610 Order CLI-83-16 permitting continued glant operation Commission did not consider current status of emergency planning in decision Certificate of Bvc enci MOLTIJ. Fublic Interest Research Group, New York 83/06/22 Commissioners. 12pp 18942:284 24X Fichs 50-247,83/06/22,8306230346.
- 8305270140 Order granting intervenor 830521 motion for extension of deadline until 830711 to file proposed findings Extension applies to all parties. Consolidation effort constructive OLEASONJ P. Atomic Barsty and Licensing Board Panel. 83/05/22 Union of Concerned Scientists. 2pp 19013 350 24% Fichs: 50-247.63/05/22.8305270140.
- 830.6270160 Answer opposing intervenor motion for extension of time to aubmit proposed findings. Motion is attempt to delay hearings. If intervenor motion pranted, extension should apply to all parties. Certificate of Suc esci.

 BRANDENBURG. B. Consolidated Edison Co. of New York, Inc. COLARULI, P.F. Power Authority of the State of New York COLARULI, P.F. Horgan Associates. B3/06/22. Atomic Safety and Licensing Spard Panel. 6pp. 18992:037. 24X Fiche: 50-247, 83/06/22, 8306270160.

- B304290550 Request 2-wk extension to file findings of fact for Commission Questions 3 & 4 Atty familiar w/case resigned HILLER, F Q Hestchester County, NY B3706722 GLEAGON, J P Atomic Bafety and Licensing Board Panel ip 17082 216 24X Fiche 50-247, 83/06/22, 8306290550
- 8304270159 Response supporting PIRG of NY motion for reconsideration of Commission 830609 decision, permitting facility operation w/o restriction despite continued noncompliance w/emergency planning requirements Certificate of Svc encl WEIBS.E R Union of Concerned Scientists 83/06/23 Commissioners Apa 18992 043 24X Fiche 50-247,83/06/23, B304270159
- 8306270267 Memorandum advising that ASLB will not reopen record to receive further testimony on Commission Question 1, ASLB consultant PJ Amico recommended addl testimony immaterial & covers topic sufficiently addressed or is unavailable QLEASDN.JP Atomic Safety and Licensing Board Panel 83/06/24 2pp 18970 202 24X Fiche 50-247,83/06/24,8306270267

H General correspondence

- B3040B0171 Opposes facility shutdown FRENCH.J F Affiliation Unknown B3/06/02 PALLADINO.N J Commissioners ip 18770 234 24X Fiche 50-247.83/06/02.83040B0191
- 8306200098 Requests NRC 830609 determination re facility OLs be reversed, per uncl Rockland County Resolution 302 Request based on inability of FEMA to assure that public health & safety can be protected within 10-mile lone W/o stated encl THORSEN.E O. SCHOENDERGER, I Rockland County, NY 83/06/13 Office of Nuclear Reactor Regulation, Director 1p 18903 336 24% Fiche 50-247.83/06/13.8306200098
- J Insurance & indemnity information
- B30602031B Forwards Endorsements 134 & 118 to NELIA Policy NF-100 & MAELU Policy MF-29, respectively DJEMAL.A Harsh & McLennau, Inc. B3/05/26 BALTZMAN, J. Assistant Director for State & Licenses Relations. 3pp. 18694 273 24X Fichs 50-247,83/05/26.8306020318
- P Operating license stage documents & correspondence
- 8306070343 Responds to Generic Ltr B2-16 re NUREO-0737 Tech Specs for listed TMI items Some Tech Specs incorporated.some not applicable & some unnecessary O'TOOLE.J D Consolidated Edison Co of New York, Inc 83/05/3 E18ENHUT.D G Division of Licensing App 18742 031 24% Fiche: 50-247,83/05/31,8306070343
- 8306200257 Forwards add1 info in support of 830504 application for amend to License DPR-26, requesting changes to Tech Specs re reactor cavity level monitoring instrumentation Info submitted in response to 830506 telcon O'TOOLE. J D Consolidated Edison Co of New York, Inc 83/06/14 VARGA, 6 A Operating Reactors Branch i 5pp iS901 179 24X Fiche 50-247,03/06/14,0306200257
- O Inspection reports. IE Bulletins & correspondence
- 8304010345 Forwards IE Insp Rept 50-247/83-11 on 830405-0502 & notice of violation STAROSTECKI, R Division of Project & Resident Programs 83/05/16 0/TOOLE.J D. Consolidated Edison Co of New York, Inc 3pp 18682 073 24X Fiche 50-247,83/05/16.8306010365
- --8306010370 Notice of violation from insp on 830405-0502 Bareguards into deleted (ref 100FR73 21),

 * Region 1, Office of Director 83/05/16 ip 18682 076 .24X
 Fichs 50-247,83/05/16,8306010365
- --8306010378 IE Inap Rept 50-247/03-11 on 830405-0502 Noncompliance noted failure to follow procedures Safeguards info deleted (ref 10CR73.21)
 FOLEY, T. KOLTAY, P. Region 1, Office of Director, KIBTER, H.B. Division of Project & Resident Programs 83/05/11 14pp. 18482 077 24X Fiche 50-247.63/05/16.8306010365
- 8304010115 Ack receipt of B30416 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-247/83-05 MARYIN T Division of Engineering & Technical Programs. B3/05/25 0*TOOLE, J. D. Consolidated Cfison Co of New York, Inc 2pp 18673, 342 24X Fiche, 50-247, B3/05/25, B306010115

- --8306010126 Responds to NRC 830317 ltr re violations noted in IE Insp Rept 50-247/83-05 Corrective actions cask handling procedure reviewed, approved & implemented & advance transport notification sent to governor Disputes Violation B O'TOOLE, J D Consolidated Edison Co of New York, Inc 83/04/16 MARTIN, T T Division of Engineering & Technical Programs 12pp 18673 344 24% Fiche 50-247,83/05/25.6306010115
- 830 5110458 IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in Well Logging Device" Syc list encl TAYLOR, J M Division of Safeguards & Inspection Progrems (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 125pp 18831 043 24X Fiche 50-000.83/05/26.8305110458
- 8305110460 IE Info Notice 83-34, "Event Notification Info Worksheet"
 Svc list encl
 JORDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/05/26 Consolidated Edison Co of New
 York, Inc 115pp 18732 085 24X Fiche 50-000, 83/05/26, 8305110460
- 8305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods Withdrawn at DMRs " Svc list encl JORDAN, EL Division of Emergency Preparedness & Engineering Rasponse (Post 830103) 83/05/31 Consolidated Edison Co. of New York, Inc. 114pp 18732 208 24X Fiche 50-000,83/05/31,8305110461
- 8305110464 IE Info Notice 83-36, "Impact of Security Practices on Safe Operations," Svc list encl JORDAN E L Division of Emergency Proparedness & Engineering Response (Post 830103) 83/06/09 Consolidated Edison Co. of New York, Inc. 119pp 18830 280 24X Fiche 50-000,83/06/09,8305110464
- 8306170226 Ack receipt of 830525 ltr informing NRC of steps taken to correct violations noted in IE lnsp Rept 50-247/83-10
 STARGETECKI, R. Division of Project & Resident Programs 83/06/10, 0/1006E, J D. Conspillate Edison Co. of New York. Inc. 2pp 18882 290 24% Fiche 50-247,83/06/10,8306170226
- --8306170830 Responds to NRC 830425 ltr re violations noted in IE Insp Rept 80-247/83-10 Corrective actions continuous fire watch established until investigation of alternate matis & feasibility of repairing penetration seals complete O'TOOLE, J D Consolidated Edison Co of New York, Inc 83/05/25 STARGBTECKI.R Division of Project & Resident Programs Bpp 18882 292 24X Fiche, 50-247, 83/06/10,8306170226
- 8306230203 Forwards IE Insp Rept 50-247/B3-12 on 830503-31.No noncompliance noted 8TAROSTECKI, R Division of Project & Resident Programs 83/06/10. 0'TOOLE.J D Consolidated Edison Co of New York, Inc. 2pp. 18745-283 24X Fiche 50-247.83/06/10.8306230203
- --8306230212 IE Insp Rept 50-247/83-12 on 830503-31 No noncompliance noted Major areas inspected licensee action on previously identified insp findings, facility operations review, plant trips. TMI action items & surveillance FOLEY, T., KOLTAY, P. Region I, Defice of Director, COLLINB, 9 Division of Project & Resident Programs. 83/06/07 14pp 18945 285 24X Fiche 50-247, 83/06/10,8306230203
- 8305110470 IE Info Notice 83-38, "Defective Heat Sink Adhesive & Bejsmically Induced Chatter in Relays Within Printed Circuit Cards," Byc list encl.
 JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/06/13 Consolidated Edison Co. of New York, Inc. (18pp. 18720-225 24X Fichs 50-000, 83/06/13, 8305110470.
- 830&690010 IE info Notice 83-37, "Transformer Failure Resulting From Degraded Internal Connection Cables " Syc list enc! JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 8370&/13 Consolidated Edison Co. of New York, Inc. 243pp 18921 001. 24X Fichs 50-000, 8370&/13, 830&690010.
- 8306240225 Responds to IE Bulletin 83-03, "Check Valve Failure in Raw Mater Cooling Sys of Diesel Generators " No check valves in svc water sys leading to or exiting from diesel generators Bulletin not applicable O'TOOLE.J D Consolidated Edison Co of New York, Inc 83/06/17, DEVOUNG, R Director's Office. Office of Inspection and Enforcement ip 18980-236 24X Ficha 50-247, 83/06/17, 8306240225.
- 8305110475 IE Info Notice 83-40, "Need to Environmentally Qualify Epoxy Grouts & Bealers," Svc list encl JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/22 Consolidated Edison Co. of New York, Inc. 115pp 19021.179 24X Fiche: 50-000, 83/06/22, 8305110475.
- 8305110477 IE Info Notice 83-41. "Actuation of Fire Suppression Sys Causing Inoperability of Safety-Related Equipment " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/22. Consolidated Edison Co. of New York: Inc. 120pp. 18977.007. 24X Fiche 50-000, 83/06/22, 8305110477

- 8309110479 IE Info Notice 83-42, "Reactor Mode Switch Halfunctions " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/23 Consolidated Edison Co. of New York, Inc. 116pp 18976 242 24X Fichs 50-000,83/06/23,8305110479
- 8305110483 IE Info Notice 83-43, "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints." Svc list encl JORDAN: E.L. Division of Emergency Preparedness & Engineering Response (Fost 830103) 83/06/24 Consulidated Edison Co of New York, Inc. 116pp 19046 297 24X Fichø 50-000,83/06/24,8305110483
- R Periodic operating reports & related correspondence
- 8306020276 Monthly operating rapt for Mar 1983 W/830415 ltr EICH:E: O'TOOLE, J D Consolidated Edison Co of New York, Inc. 83/04/04 8pp 18690 290 24% Fiche. 50-247, 83/04/04, 8306020276
- 8306160462 Monthly operating rept for Apr 1983 W/830315 ltr EICH,E, D'TBOLE,J D Consolidated Edison Co of New York, Inc. 83/05/04 McDDNALD,W 9 Office of Resource Management, Director, 12pp 18863 096 24% Fichs 50-247,83/05/04,8306160462
- 830.6270171 Forwards revised pages to semiannual effluent & waste disposal repts for Jan-June 1782 & Jul-Dec 1782, re "Radiological Impact on Man" sections O'TOOLE, J. D. Consolidated Edison Co. of New York, Inc. 83/06/16
- --8306270179 Revised pages to semiannual effluent & waste disposal rept, Jan-June 1982 * Consolidated Edison Co of New York, Inc. 83/04/16. 3pp 18991 359 24X Fiche: 50-003,83/06/16,8306270171
- --8306270184 Revised pages for semiannual effluent & waste disposal rept, Jul-Dec 1982 * Consolidated Edison Co of New York, Inc 83/06/16, 3pp. 18991-362 24X Fiche 50-003,83/06/16,8306270171
- 9 Reportable occurrences, LERs & related correspondence
- 8306170415 LER 83-012/03L-0. on 830419, reactor cavity continuous sump level monitor LI-3302 indicated above 20-ft, but independent cavity level alarm did not annunciate Reactor cavity found dry Caused by instrument drift. H/830519 ltr. MOONEY. J. p. TIDDLE, J.D. Consolidated Edison Co. of New York, Inc. 83/05/19 HURLEY.T. E. Region 1, Office of Director. Spp 18879 004 24X Fichs 50-247,83/05/19,8306170415
- 8306170323 LER 83-020/03L-0 on 830420, high steam flow bistable FC449A setpoint found higher than Tach Spac Ismit Caused by defective internal do power supply board. Board replaced & bistable reset MOONEY, J.P., O'TODLE, J.D. Consolidated Edison Co., of New York, Inc. 83/03/20 ALLAN, J.M. Region 1, Office of Director 2pp. 18078; 244. 24X Fiche: 50-247, 83/05/20, 8306170323.
- 830&170405 LER B3-013/03L-0 on B30420, during surveillance testing of containment isolation valves, valve 1702 did not fully close Cause not stated Bhaft & inside of actuator cleaned Air motor disphrage replaced as preventive measure, W/830520 itr. HINRICH, 0, 0'TOULE, J.D. Consolidated Edison Co. of New York, Inc. 83/03709 MURLEY, T.E. Region 1, Office of Director. 2pp. 18879 318 24X Ficher 80-247, 83/05/20, 830&170405.
- 8306170044 LER 83-014/03L-0 on 830421.charging pump R1 developed leak & declared inoperable Caused by defective head gasket on cylinder head 4.0asket replaced HINRIGHTS, 0, 0 TOOLE, J.D. Consolidated Edison Co. of New York, Inc. 83/05/21 ALLAN, J.M. Region 1, Office of Director, 2pp. 18878:293, 24X Fiche: 50-247,83/05/21,8306170044
- 8306170189 LER 83-017/03L-0 on 830422, leak observed in isolation valve seal water sys. Caused by damage to 3/8-inch stainless steel weld connection FH10016. Neld repeired H/830522 ltr. HINRICHB. 6 , 0'f100LE. J. D. Consolidated Edison Co. of New York, Inc. 83/05/22 ALLAN. J. M. Region i. Office of Director. 2pp 18878. 327 24% Fichs 30-247.83/05/22.8306170189
- 8304170197 LER 83-021/03L-0.on 830422. analysis revealed adsorption afficiency for methyl iodine of 82 2%. Cause under investigation. Charcool filters replaced W/830522 ltr. HINRICHB.C. O'TOOLE.J.D. Consolidated Edison Co. of New York, Inc. 83/05/22, ALLAN.J.M. Region 1, Office of Director. 3pp 18878-321. 24% Fiche: 50-247, 83/05/22, 8306170197.

- 8306170271 LER 83-019/03L-0. on 830422, valve 743, nonautomatic containment isolation valves in RHR pusp minifilm line would not operate Gause not stated Reach rods disconnected & valve stee & universal joints cleaned & lubricated W/830522 lth HJRRICHS. D. 0700LE. J.D. Consolidated Edison Co. of New York, Inc 83/05/22 ALLAN, J. H. Region is Office of Director Spp 18978 252, 24% Fiche 50-247,83/05/22,8306170271
- 830&170397 LER 83-016/03L-0.on 830422.boron injection tank level channel 944F became imperable Caused by extroneous level indirection due to boric acid solidification in instrument impulse lime Affected impulse lime cleaned, M/830522 ltr. HOONEY, J. P., 0 TOOLE J. D. Consolidated Edison Go. of New York, Inc 83/03/22 ALLAN, J. R. Region L. Office of Director 2pp 18879 017 24X Fiche: \$0-247.83/05/82,8306170397.
- 8306170410 LER 83-018/03L-0 on 830422 plant shutdown commenced when binding of velve 1870 could not be corrected within Tech Spec time period, Gause not stated, Binding alleviated by lubricating valve stem & universal joints W/820322 ltm. HINRICHS.9, 0'TOOLEJD Consolidated Edizon Co. of New York, Inc 83/05/22 ALLANJ M Region I. Office of Director 2pp 18979 025, 24X Fichs 30-247.83/05/22,8306170410.
- B305170200 LER 83-015/03L-0 on 830427, shutdown initiated when contactment spray gump 21 did not neet operability criteria Repeirs not completed within allowable time period Caused by high vitrations. Pump replaced M/B30527 ltr
 HIRRICHS: 0 . 0/100LE: J D Consolidated Edison Co of New York, Inc 83/03/27, ALLAN, U H Region 1, Office of Director Spp 18878: 324 24X Fichs 50-247, 83/05/27, 8306/170200.
- 8306230349 PNO-1-83-065 on 830617, contract between util & Util Horkers of America Local 1-2 expired Union/mgt turnover conducted w/o incident Reverification of sys lineups & insp of equipment completed Media attention evident.

 OREENMAN.E 0 Region 1, Office of Director. 83/06/20 ip 18943 280 24X Fiche: 50-247, 83/06/20, 8306230349

T Hearing transcripts on non-antitrust matters

- 8306020709 Transcript of Commission 830526 meeting in Hashington, DC, re marriency planning & preparedness Pp 1-117. Bupporting documentation and 1.

 Commissioners 83/05/26 234pp. 18716:001, 24X Fiche: 50-247,83/05/26,8306020709
- 8306090347 Statement before House of Representatives Subcommittee on Energy Conservation & Power re smerpency planning Public must be involved in planning & testing process Parents Concerned About Indian Point 83/04/08, 4pp. 18794-336, 24X Fichs 50-247,83/06/08,8306090347
- 8306090350 Testimony of J Holt, K Toscani & P Posner before House of Representatives Subcommittes on Energy Conservation & Power re-public role in plenning, testing & implementing emergency response procedures.

 MOLIT. J. Public Interest Research Group, New York TUBCANI, K., POSNER, F. Parents Concerned About Indian Point.

 18794-340 24% Fiche-50-247, 83/06/08, 8306090330
- 8306180500 Transcript of 830609 Commission discussion & vote on sacrgancy planning deficiancies at Indian Point in Mashington, DC Pp 1-24 Commissioners 63/06/09 30pp 18868: 249. 24X Fichs. 50-247, 83/06/09, 8306150500
- 8306200342 Forwards corrections to special proceeding transcripts, BRANDENBURD, B. Power Authority of the State of New York, COLARULLI, P. F. Consolidated Edison Co. of New York, Inc. COLARULLI, P. F. Morgan Associates 83/06/15 GLEASON, J. P. PARIS, O. H. SHON, F. J. Atomic Safety and Licensing Board Panel 1p. 18900: 211. 24X Fishs 50-247, 83/06/15, 8306200342
- --B30A20034b Corrections to special proceeding transcripts.

 # Power Authority of the State of New York # Consolidated
 Edison Co of New York Inc. 83/06/15, 52pp 18700 212 24X
 Fichs. 50-247, B3/06/15, B306200342
- B30624001B Transcript of Commission B30617 brisfing on Indian Point labor issues in Mashington, DC, Pp 1-44 Commissioners, B3/06/17 47sp. 18987: 293 24X Fichs: 50-247, 83/06/17, 830624001B

- U Congressional/Executive Correspondence
- 8306030186 Responds to 030506 request for clarification of Registration of views of public & parties to special grocesding in 030607 Jectsion Comments from Licensess, goving agencies & public invited PALLADING:N J Commissioners 03/05/12 OTTINOFN:R I strucks of Rep. Energy & Commerce Opp 18/93/02/0 DAY Fichs 50 DAY. 8306030196
- --8306030158 Requests Commission 830505 order by revised to stryet reaffor parties to safety investigation views on sholdown New requested by 830511 OTTINGER,R.L. House of Rep., Emergy & Commerce 113705744 FALLADING.N. Commissioners, 2pp 10733 328 248 Fichs: 80-247, 83705712, 8306030186

V. Operator Examinations

- 830Ai4037D Extends invitation to attend 0.30A2/ meeting in King 0.3
 Prossia.PA to discuss transfer of reactor operator
 licensing function from BethesdardD to Region I ofe
 STANDETECKI,R Division of Project & Resident Programs 0.400a af
 D.400LE,J.D. Consolidated Edigon Co. of New York: Int 2pp
 18832-112 24X Fiche 50-247, 03/04/07, 03/04/4027D
- DOCKET 50-849 DRESDEN NUCLEAR POWER STATEN. UNIT ST F. Security, medical, emergency & fire protection plans
- B306210314 FOIA request for NRC records to security violations & sefeguards events at nuclear Parilities G1/04/22 IN 1987 PROCESSERO, G Sectops-Housed Newspapers G1/04/22 IN 1987 PROCESSERO, G1/04/22 G1/04/22, G1/04/23, G1/04/23, G1/04/23, G1/04/23, G1/04/24, G1/04/
- 8306210306 Partial response to FDIA request for NHC records re asimple violations & safeguards events at nuclear facilities Regts listed on Aps A symilable in PDH Bearch for addl documents subj to request continuing FELTON, J. M. Division of Rules and Records 83/05/16. On the sector Scripps-Howard Newspapers. Spp 18/25; 196. DAX Fichs 80-000,83/05/16.8306210306
- B306090247 Confirms B30601 telenn re changes to exercise windows for Dresden & Dyron Nuclear Power Stations Dresden partial exercise will be conducted during whose B100912 w/Hyron hull-scale exercise beginning wit of 833514 JONES E Thinois, State of B12006/01 KEPPLER, J. Region 3. Office of Director. AMDERBON, J. Federal Emergency Hanagement Agency. MAGMEN. O. Commonwealth Edison Co. ip 18795-314 p48 Fichs: 80-000, 83/06/01, 0306090247.
- 8306210385 Releases public varsion of revised amorgoncy plan implementing procedure FELTON, J. H. Division of Rules and Records. DD/96/06 Document Hanagement Branch. Ip 18935 R93 RAX Fichs 50-010-83/06/06. 8306210385
- --830AR10357 Public version of Rev I to Emergency Plan Employmenter Procedure EPIP 300-12, "Initiation of Environ Honitoring Activities by Rad/Chem Director," Receipt form encl WR0051A ltr., Branch Commonwealth Edison Co 83/05/11 DENION: I SCOTT, D. J. Commonwealth Edison Co 83/05/11 DENION: I SCOTT, D. J. Commonwealth Edison Co 83/05/11 DENION: I Series of Noclear Reactor Regulation, Director 19pp 18735 R94 248 Fiche: 50-010,83/06/06,8306210355
- 6306100218 Responds to IE loss Hepts 50-010/83-01, 50-237/93-01 & 30-249/83-01. Corrective action survaillance notification program developed for annual distribution of public line tractures on emergency planning FARRAR, D. L. Commonwealth Edison Co. 03/06/07 PAPEHIELLO.C. 3 Region 3. Office of Director, 4pp. 10005 113 24X Fichs. 50-010, 63/06/07, 6306100218.
- 830660214 Submits correction to B30601 ltr Date of reassessment will be made prior to B30801, not B31601.

 JONESTE E. Illinois, State of, B3_06/09 KEPPLER, J. Region 3. Office of Director. ANDERSON, J. Federal Emergency Hanagement Agency HAOMER, 9. Commonwealth Edison Co. Is 18861 339 24E Fiche 30-000, B3/06/09, B306160214.
- f. Operating license stage documents & correspondence
- 830A09019A Discusses util interpretation of IOCFRBO. 49. "Environ qualification of Electrical Equipment Important to Refety for Nuclear Power Plants." Intent of rulemaking is to require upgrade program for replacement equipment not parts FARBAR.D.L. Commonwealth Edison Co. 83/06/03. DENTON, H. R. Office of Nuclear Rescar Regulation, Director. 3pp 18796.090 241

- 830.6140408 Forwards evaluation of BWR Owners Group generic response to NUREQ-0737. Item JI K 3 16. "Mod of Automatic Depressivization Sys Logic-Feasibility for Increased Diversity for Bone Event Sequences "Two options listed CRUTCHFIELD.D Operating Reactors Branch 5 83/06/03 FARRAN.D L Commonwealth Edison Co 2pp 18837 354 24X Fiche 50-237.83/06/03.8306140408
- 830&090227 Informs that response to Generic Ltr 83-08 will be submitted by 830713 Info will include stress repts to determine mod to vacuum breakers on Mark I containments
 RYBAK.B Commonwealth Edison Co. 8370&704 DENTON.H R Office of Nuclear Reactor Regulation. Director ip 18796-234 24X
 Fichs 50-000.8370&704.830&090227
- 8306160233 Advises that manufacturers whose repts were used in technical evaluation repts re environ qualification of electrical equipment have been contacted List of proprietary pages detailed in util 830513 ltr W/9C affidavit RVBAK.8 Commonwealth Edison Co 83/06/06 DENTON.H R Office of Nuclear Reactor Regulation. Director 5pp 18861 304 24% Fiche 50-000,83/06/06.8306160233
- 8306130226 Application for amend to License DPR-25, proposing changes to Tech Spec Tables 3 6 1 a & h re sefety-related hydraulic & mechanical snubbers, respectively Changes have no effect on piging stresses Amend fee oncl
 RYBAK, B Commonwealth Edison Co 83/06/07 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 18824 311 24x
 Fiche 50-249,83/06/07.8306130226
- --8306:30230 Proposed Tech Spec Tables 3 6 i a & b re safety-related hydraulic & mechanical snubbors.respectively * Commonwealth Edison Co 83/06/07 2pp 18824 312 24X Fiche 50-249.83/06/07.8306:30226
- 8304130254 Confirms 830410 meeting in Glen Ellyn, IL to discuss design data supporting analysis indicating that missing snubber on torus was not significant item
 NORELIUG, C E Division of Project & Resident Programs 83/06/07
 REED, C Commonwealth Edison Co Ip 18823 317 24X
 Fiche 50-249,83/06/07.8306130254
- 830&10012B Forwards safety ovaluation & technical evaluation rept,
 "Monatoring of Electric Power to Reactor Protection Sys for
 Dresden Nuclear Power Station Units 2 & 3 " Proposed mods
 acceptable
 CRUTCHFIELD.D Operating Reactors Branch 5 83/06/09 FARRAR.D L
 Commonwealth Edison Co 3pp 18801 181 24X Fichs 50-237,03/06/09,
 830&10012B
- --8305100131 Safety evaluation re monitoring of electric power to reactor protection sys Proposed mods providing automatic protection of sys components from sustained abnormal power supply acceptable

 * Office of Nuclear Reactor Regulation, Director, 83/06/07 Ppp. 18801.184 24X Fiche 80-237.83/06/07,8306100128
- --8304100135 "Monitoring of Electric Power to Reactor Protection Bys for Dresden Nuclear Power Station Units 2 % 3," tschnical evaluation rept BELAN.J C Lawrence Livermore Laboratory FIN A-0250 UCID-19705 B3/05/18 NRC - No Detailed Affiliation Given 9pp 18801 188 24X Fiche. 50-237. B3/06/09. 83061001RB
- 8306240030 Application to amend Licenses DPR-19 & DPR-29, extending time limits for imperability of ECCB ring header snubbers Also updates Unit 3 Tables 3 & 1 2 & b to reflect changes in type of anobhers installed RYBAK.B Commonwealth Edison Co. 83/06/13 DENTON, HR Office of Nuclear Resultation, Director 2pp 18781 095, 24X Fiche.50-237.83/06/13,8306240030
- --8306240035 Proposed Tech Specs extending time limits for inoperability of ECCS ring header snubbers & updating Unit 3 Tables 3 & 1 a & b to reflect type of snubbers installed.

 * Commonwealth Edison Co. 83/06/13 20pp 1898: 097 24X Fiche: 50-237, 83/06/13, 8306240030
- G Inspection reports. IE Bulletins & correspondence
- 8306220218 Ack receipt of 830414 payment of proposed civil penalties, Response to notice of violation & proposed imposition of civil penalties will be avaluated & corrective actions examined during future insps.
 AXELRAD.J A Enforcement Staff 83/04/21, REED.C Commonwealth Edison Co 2pp. 18950-357 24X Fiche 80-000.83/04/21.8306220218

- 8305260238 Responds to violations noted in IE Insp Repts 50-237/83-08 & 50-249/83-07 Corrective actions radiation protection mgt personnel increased surveillance of respiratory devices & add1 radiation control technician added FARRAR.D L Commonwealth Edison Co 83/05/20 KEPPLER.J G Region J. Office of Director 5pp 18599-355 24% Fiche 50-237,83/05/20,8305260238
- 8305110458 IE Info Notice 83-32, "Ruptured Am-241 Bources Contained in Well Logging Davice" Syc list encl
 TAYLOR. J M Division of Safeguards & Inspection Programs (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 125pp 18831 043 24X Fiche 50-000.83/05/26.8309110458.
- 8305110460 IE Info Notice 83-34, "Event Notification Info Worksheet."

 8vc list encl
 JORDAN E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/05/26 Consolidated Edison Co. of New
 York, Inc. 115pp 18732 085 24K Fiche 50-000,83/05/26,8305110460
- 8306100101 Forwards IE Insp Repts 50-237/83-13 & 50-249/83-11 on 830426 No noncompliance noted LITTLE, W S Region 3, Office of Director 83/05/27 REED, C Commonwealth Edison Co 2pp 18802 332 24X Fiche 50-237,83/05/27,830610101
- --8306100105 IE Insp Repts 50-237/83-13 % 50-249/83-11 on 830426, No noncompliance noted Major areas inspected licenses action re IE Bullatin 80-11, "Masonry Wall Design" NORTON J F, WILLIAMB.C C Rejion 3, Office of Director 83/05/27, 4pp 18802 334 24X Fichs 50-237,83/05/27,8306100101.
- 8305110461 IE Info Notice 83-35, "Fuel Movement H/Control Rods Withdrawn at BMRs " Svc list encl. JORDAN.E.L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/31. Consolidated Edison Co of New York, Inc 116pp 18732 208 24X Fiche; 50-000,83/05/31,8305110461
- 8306130338 Confirms plan discussed on B30601 for B30620 enforcement conference to discuss post-maint problems & significance of missing snobber on torus NORELIUB.C E Division of Project & Resident Programs. B3/06/03. REED.C. Commonwealth Edison Co. Jp 18823-001 24X Fiche 50-237.83/06/03.8306130338
- 8306100149 Forwards Rev 3 to "180-Day Rept in Response to IE Bulletin 80-11 for Dresden 2 & 3 & Guad Cities 1 & 2." RYBAK.B Commonwealth Edison Co 83/06/06. KEPPLER.J 9. Region 3. Diffice of Director 2pp 18804.161 24X Fiche 50-000.83/06/06. 8306100149
- ~-8306100156 Rev 3 to "180-Day Rept in Response to IE Bulletin 80-11 for Dreaden 2 t 3 t Quad Cities 1 t 2 "

 ** Commonwealth Edison Co. 83/03/09. 129pp. 18804:163. 24X
 Fichs 50-000.83/04/06.8306100149
- B306100094 Forwards response to IE Bulletin 83-03 re diesel generator cooling water check valves. Plants utilize Mission Duo-Check valves employing hings-to-pin design for protection against vibration-induced failure.

 BARNES, P.L. Commonwealth Edison Co. B3/06/07. KEPPLER, J. Q. Region 3, Office of Director 7pp 18802 238 24% Fiche: 50-000, B3/06/07, B306100094.
- 8304100218 Responds to IE Insp Repts 50-010/83-01, 50-237/83-01 & 50-249/83-01 Corrective action; surveillance notification program developed for annual distribution of public info brochures on emergency planning FARRAR, D. L. Commonwealth Edison Co. 83/06/07. PAPERIELLO, C. J. Region 3. Office of Director 4pp. 18805, 113 24% Fiche 50-010, 83/06/07, 8306100218
- 830Ai70380 Forwards response to IE Bullstin 83-03 re diesel generator cooling water check valves Valves at Dresden & LaBalle acceptable w/o further insp. Rept on valve failures at Qued Cities will be submitted within 90 days of insp completion. BARNES, P. L. Commonwealth Edison Co. 83/06/07. KEPPLER. J. Q. Region 3, Office of Director 7pp. 18880 211. 24X Fiche, 50-000, 83/06/07, 8306170380
- 8305110464 IE Info Notice 83-36, "Impact of Security Practices on Safe Operations." Svc list encl.
 JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/09. Consolidated Edison Co. of New York, Inc. 119pp. 18830,280, 24X Fiche 50-000,83/06/09.8305110464.
- 8305110470 IE Info Notice 83-38, "Defective Heat Bink Adhesive & Beismicelly Induced Chatter in Relays Within Printed Circuit Cards " Syc list encl JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13, Consolidated Edison Co of New York, Inc. i18pp. 18920:225 24% Fiche, 50-000, 83/06/13, 8305110470

- 8304090010 IE Info Notice 83-37. "Transformer Failure Resulting From Degraded Internal Connection Cables " Svc list encl JORDAN E. L. Division of Emergency Preparedness & Engineering Response (Fost 8301031. 83/06/13 Consqlidated Edison Co of New York, Inc. 243pp. 18921 001. 24% Fiche 50-000,83/06/13,8306090010
- 8306300235 Forwards IE Insp Repts 50-237/83-12.50-249/83-10, 50-254/83-13 & 50-265/83-11 on 820412-14 & 0506 & 16 & notice of violation.
 LITTLE: W S. Region 3, Office of Director 83/06/16 REED.C Commonwealth Edison Co 2pp 19122.279 24X Fichs 50-000,83/06/16,8306300235.
- --8306300238 Notice of Violation from insp on 830412-14 & 0906 & 14 LITTLE, W 8 Region 3, Office of Director, 83/06/16 2pp, 19122:281 24% Fiche 50-000:83/06/16:8306300235
- --8306300246 IE Insp Repts 50-237/83-12,50-249/83-10,50-254/83-13 & 50-265/83-11 on 830412-14 & 0506 & 16. Noncompliance noted: as-built confirmeration (for pips anchor RI33 in pressure suppression sys) differed from original design YIN.I.T., DANIELBON.D M. Region 3, Office of Director. 83/06/15 9pp 19122:283 24X Fiche 50-000,83/06/16,8306300235
- 8305110475 IE Info Notice 83-40, "Need to Environmentally Qualify
 Epoxy Grouts & Sealers." Svc list encl
 JORDAN E.L. Division of Emergency Preparedness & Engineering
 Response (Past 830103). 83/06/22. Consolidated Edison Co. of New
 York. Inc. 115pp. 19021 179. 24X Fiche: \$0-000, 83/06/22, 8305110475.
- 8305110477 IE Info Notice 83-41, "Actuation of Fire Suppression Bys Causing Inoperability of Safety-Related Equipment " Syc list and!. JORDAN: E.L. Division of Emergency Preparedness & Engineering Response (Fost 830103). 83706/22. Consolidated Edison Co. of New York: Inc. 120pp. 18997:007. 24X Fiche. 50-000, 83706/22, 8305110477.
- 8305110479 IE Info Notice 83-42, "Reactor Mode Switch Halfunctions "

 8vc list encl
 JORDAN E. L. Division of Emergency Preparedness & Engineering
 Response (Post 830103). 83/06/23. Consolidated Edison Co. of New
 York, Inc. 116pp. 18996;242, 24X Fiche. 50-000,83/06/23,8305110479.
- 8305110483 IE Info Motice 83-43, "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints." Syc list encl. JORDAN, E. L. Division of Emergency Preparefness & Engineering Response (Post 830103) 83/66/24. Consolidated Edison Co. of New York, Inc. 116pp 19046, 297. 24X Fiche. 50-000, 83/06/24, 8305110483
- R. Periodic operating reports & related correspondence
- 8306/30275 "Semiannual Rept of Radioactive Effluents 1982 " W/830302 ltr. ltr. SCOTT, D. J. Commonwealth Edison Co. 83/03/02 KEPPLER, J. Q. Region 3. Office of Director, 20pp. 18820: 277 24X Fiche: 50~010, 83/03/02, 8306/30275.
- 8304140086 Monthly operating repts for May 1983 W/830401 ltr. 86HR0EDER, B A , 860TT. D J. Commonwealth Edison Co. 83/04/01. Director's Office of Inspection and Enforcement 18pp. 18836-347. 24X Fichs. 50-237, 83/04/01
- 8306130454 Forwards corrected "1981 Rept of Occupational Personnel Radiation Doses Contract Workers," per Reg Guide 1.14 Number of people per mannem should be listed in maint not engineering category.

 MAGNER.O.P. Commonwealth Edison Co. 83/06/07. KEPPLER.J.G. Region 3. Office of Director 1p. 18821:179. 24X Fiche:50-010.83/06/07. 8306130454
- --8306130457 Pormards currected "1981 Rept of Occupational Personnel Radiation Doses Contract Workers," per Reg Quide 1.16 Number of people per manrem should be listed in maint not engineering category, WAGNER.0.P Commonwealth Edison Co. 83/06/06. KEPPLER.J.O. Region 3. Diffice of Director. 1p. 19821:180. 24X Fiche:50-010.83/06/07.8306190454
- --8306130460 Corrected *1981 Rept of Occupational Personnel Radiation Doses -- Contract Workers, **

 # Commonwealth Edison Co 83/06/06. 9pp. 18821:181 24X
 Fiche: 50-010,83/06/07,8306130454.

- 8 Reportable occurrences, LERs & related correspondence
- 830&070234 Updated LER 81-033/01X-1 on 811023.Unit 2/3 diesel generator (D/O) tripped due to high cooling water temp & Unit 3 D/O manually tripped during testing Caused by failure of cooling water pump discharge valve W/830523 ltr MOLLAND, P. 600TT, D. J. Commonwealth Edison Co. 83/05/23 KEPPLER, J. O. Region 3, Office of Director 4pp 18746 142 24X Fichs 50-249,83/05/23.8306070234
- 8304070279 LER 83-018/03L-0 on B30502, LPCI core spray pump pressure alarm annunciated & cleared after close signal sent to core spray valve MO 1402-25A tripping indicating lights & breaker Caused by incorrect trip setting W/630531 ltr ANANDAPPA.A. SCOIT.D J Commonwealth Edison Co 83/09/31 KEFFLER.J O Region 3. Office of Director 3pp 16744 083 24X Fiche 50-249,83/05/31,0304070279
- 8306130346 LER 83-017/03L-0 on B30504, after actuation of HPC1 deluge sys.weight releasing lever of deluge valve tripped Probably caused by misaligned trip linkage Solenoid & valve linkage disassembled/assembled who anomalies noted W/830531 ltr MERRITT. 8. 560TT, D. J. Commonwealth Edison Co. 83/05/31 KEPPLER. J. G. Region 3. Office of Director 3pp 18022 212 24X Fiche 80-249,83/05/31,8306130346
- 8306130325 LER 83-021/01T-0 on 830523, differential pressure switches PS 1349A & B actuated above Toch Sper limit Caused by instrument drift Switches reset Trip point repeatability verified W/830601 ltr
 CHRISTEL B . SCOTT, D J Commonwealth Edison Co 83/06/01
 KEPPLER J G Region 3, Office of Director App 18822 173 24X Fiche 50-249,83706/01,8304130325
- 8306170409 LER 63-019/03L-0 on B30521.MSIV 203-18 found w/closure time of 2 7 s exceeding Tech Spec limit of 3 to 5 s Caused by misself state of the second of the second
- 8306270111 Updated LER 83-003/03X-1 on 830105, pinhole leak found on connecting pips weld between 3-1201-10 inch A & 3-1292-2 inch line A of water cleanup sys Probably caused by intergranular stress corresion cracking W/830603 ltr MERRITY, S. SCOTY, D. J. Commonwealth Edison Co. 83/06/03 KEPPLERJ & Region 3, 0ffice of Director 3pp. 18988 094 24X Fichs. 50-249,83/06/03,8306270111
- 830.6270083 LER 63-020/03L-0 on 830.52i, when control rod drive (CRD) 0-6 pulled from core after scram & addl withdrawal signal applied, overtravel alarm came up & position indication lost Gaused by detached CRD inner filter W/630.613 ltr New York, Inc 8370.67.13 KEPFLER, J O Region 3, Office of Director 3pp 19013 122 24X Fiche 50-249, 63/06/13, 8306.270083
- 8306270282 Potential Part 21 rept re discrepancy in welding of turnbuckle assembly, turnbuckle-bolt interface & on top plate assembly variable springs 84307 Grade B bolts not ABME. Section IX matl Investigation underway. KARAOIANIB. J.A. Elcen Hetal Products Co. 83/06/17 KEPPLER, J @ Region 3. Dffice of Director 2pp 18796, 207 24X Fiche 50-000,83/06/17,8306270282
- DOCKET 50-250 YURKEY POINT PLANT, UNIT 3
 F Security, medical, emergency & fire protection plans
- 8304070050 Forwards IC Safaguards Insp Repts 50-250/83-17 & 50-251/83-17 on 830420-22.0502-05 & 10-12 No noncompliance noted DANCE H C Division of Project & Resident Programs 83/06/01. UHRIOR E Fibrida Power & Light Co 2pp 18740 053 24X Fichs 30-250.83/06/01.3304070050
- ~-8306070061 IE Bafeguards Insp Repts 50~250/83-17 & 50~251/83-17 on 830420-22,0502-05 & 10~12 No noncompliance noted Major areas inspected licenses investigation of two closed valves in auxiliary feedwater sys, Details withheld (ref 100FR73,21) TODIN-N Region 2. Office of Director MCQUIRG.D R. Division of Emergency Preparadness & Materials 8afety 89/05/31 ip. 18740-055 24% Fiche 50~280,83/06/01.8306070050
- 8306130435 Forwards, for review, Rev 1 to 830408 fire protection rept. Rev provides apecific info & Justification for 100FRSO. App R. exemption requests. Exemptions unnecessary for Fire Areas/ Zones D.E. 82.87, 91 & 92
 UHRIG, R.E. Florida Power & Light Co 83/06/06 EISENHUT, D. Q. Division of Licensing 1p 18821:036 24X Fiche 50-250, 83/06/06, 8306130435

- --8306130441 Rev 1 to "Fire Protection Rept "
 * Florida Power & Light Co 83/06/30 141pp 18821 037 24X
 Fiche 50-250.83/06/06.8306130435
- 8306230371 Confirms recent conversations w/util re control of access into containment during shutdown Security plan changes requested within 60 days of ltr receipt Safeguards info withheld (ref 10CFR73 21)
 VARQA, B A Operating Reactors Brench I 83/06/20 UHRIO, R E Florida Power & Light Co ip 18744 135 24X Fiche 50-250, 83/06/20,8306230371

J Insurance & indemnity information

- 8304010378 Forwards Endorsement 43 to NELIA Policy NF-185 & Endorsement 55 to MAELU Policy MF-55 DUCK,J R March & McLennan, Inc. 83/05/20 SALTZMAN,J Assistant Director for State & Licensea Relations 3pp 18682 237 24X Fichs, 50-250, 83/05/20, 8304010394
- 630.6230125 Forwards Endorsement 66 to NELIA Policy NF-185 & Endorsement 56 to MAELU Policy MF-55.

 DUCK.J R Marsh & McLennan, Inc 83/06/16, SALTZMAN,J Assistant Director for State & Licensee Relations 3pp 18947 054 24X Fiche 50-250,83/06/16,8306230125
- P Operating license stage documents & correspondence
- 8306030056 Ack receipt of 821027 application & 830307 rev re proposed revised pump & valve inservice tost program Remittance of Class III & I fees requested DIOOS,R M License Fee Management Branch 83/05/27 UHRIG.R.E. Florida Power & Light Ce ip 18793 203 24X Fiche 50-250, 83/05/27,8306030056
- 830.6090352 Application for amend to Licenses DPR-31 & DPR-41, revising Tech Specs to support fuel design change from Westinghouse low parasitic fuel assembly to optimized fuel assembly & use of new Westinghouse wet annular burnable absorber rods UHRIG.R.E. Florida Fower & Light Co 83/06/03 EISENHUT.D Q Division of Licensing 3pp 18795 003 EAX Fiche 50-250,83/06/03,8306090352
- ---8306090355 Proposed Tech Specs supporting fuel design change from Westinghouse low parasitic fuel assembly to optimized fuel assembly & use of new Westinghouse wet annular burnable absorber rods # Floride Power & Light Co. 83/06/03. 21pp. 18795 006. 24X Fiche 80-250,83/06/03.8306090352
- B306160335 Forwards response to B30422 request for add1 info re Criteria 2,10 & 11 of NUREO-0737. Item II B 3, "Post-Accident Bampling." Interim core damage estimate guidelines will be submitted by B30630 UHRIG.R E Florida Power & Light Co B3/06/10 VARGA.B A Operating Reactors Branch i 3pp. 18861 171. 24X Fiche 50-250, B3/06/10, B306160335

Q Inspection reports, IE Bulletins & correspondence

- 8304i40577 Confirms mgt meeting on 8303i4 at Region II ofc to discuss recent insp findings re failure to properly evaluate radiation exposures at facility. Proposed meeting agenda encl
 O'REILLY, J.P. Region 2, Office of Director 83/03/15, UHRIO, R. E. Florida Power & Light Co. 2pp 18844:160 24X
 Fiche: 50-250, 83/03/15, 8306140577.
- 8306140393 Confirms 830428 enforcement meeting at Region II ofcs to discuss recent incident of unavailability of auxiliary feedwater w/Unit 3 operating at full power, per 830422 tolcon. Proposed agenda encl O'REILLY.J P Region 2, Office of Director. 83/04/26. UHRIO, R E Florida Power & Light Co. Rpp. 18832:096, 24X Fiche: 50-250, 83/04/26, 8306140393.
- 8305110458 IE Info Notice 83-32, "Ruptured Am-R41 Sources Contained in Nell Logging Device" Syc list encl. TAYLOR, J. M. Division of Safeguards & Inspection Programs (Post 830103), 83065/26. Consolidated Edison Co. of New York, Inc. 125pp 18831.043. 24X Fiche: 50-000, 83/05/26, 8305;10458.
- 8305110460 IE Info Notice 83-34, "Event Notification Info Worksheet." Svc list encl. JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/05/26 Consolidated Edison Co. of New York, Inc. 115pp. 18732:085 24X Fiche. 50-000, 83/05/26, 8305110460.

- 8305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods Withdrawn at INRs " Bvc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/08/31 Consolidated Edison Co. of New York. Inc. 116pp 18732 208 24X Fiche 80-000,83/05/31,8305110461.
- 8304290204 Forwards IE Insp Repts 50-250/83-13 & 50-251/83-13 on 830503-06 No noncompliance noted DANCE, H C Region 2. Office of Director 83/05/31 UHR10, R, E. Florida Power & Light Co 2pp 17056: 227 24X Fiche 50-250, 83/05/31, 8306270204
- --8306290212 IE Insp Repts 50-250/83-13 & 50-251/83-13 on 830503-06 No noncompliance noted Major areas inspected containment integrated leakage rate testing BROURS,E. JAPE,F Region 2, Office of Director 83/05/24. App 19056 231 24X Fichs 50-250,83/05/31,8306270204
- 8306070050 Forwards IE Bafeguards Insp Repts 50-250/83-17 & 50-251/83-17 on 830420-22,0502-05 & 10-12 No noncompliance noted DANCE, H C Division of Project & Resident Progress 83/06/01, UHR19, R E Florida Power & Light Co 2pp 18740-053 24X Fichs 50-250,83/06/01,8306070050
- --8306070061 IE 8afeguards Insp Repts 50-230/83-17 & 50-231/83-17 on 830420-22,0502-05 & 10-12 No noncompliance noted Major areas inspected licensee investigation of two closed valves in auxiliary feedwater sys Details withheld (ref 10CR73, 21) TOBIN, M. Region 2, Office of Director McOUIRE, D.R. Division of Emergency Preparadness & Materials Safety, 83/05/31 ip. 18740 055 24X Fiche 50-250,83/06/01.8306070050
- 8306080003 Forwards Util response to Enforcement Action B3-31 & payment of proposed civil penalty O'REILLY, J.P. Region 2, Office of Director. 83/06/03 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 1p, 18772 354 24X Fiche 50-250,83/06/03.8306080003
- --830A080004 Responds to NRC proposed civil penalty re violations noted in IE Insp Repts 50-250/83-06 & 50-251/83-06 Corrective actions: operating instructions revised detailing duties during outage & nonoutage conditions for technicians UHRIGAR E Florida Power & Light Co 83/06/01. O'REJLLY, J. P. Region 2, Office of Director. Spp. 18772: 355. 24X Fithe 50-290, 63/06/03.8306080003.
- 8306290398 Responds to IE Bulletin 83-03, "Check Valve Failures in Raw Water Gooling Bys of Diesel Generators" Glossed cooling radiator sys contains no check valves. Bulletin not applicable.

 URRIGARE. Florida Power & Light Co. 83/06/08 0'REILLY, J P Region 2, Office of Director 2pp. 17052-183, 24X Fiche. 50-000, 83/06/08, 8306290398
- B305110464 IE Info Notice 83-36, "Impact of Security Practices on Safe Operations " Svc list enc! JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) B3/06/09 Consolidated Edison Co. of New York, Inc. 117pp. 18830:280. 24X Fiche. 50-000.83/06/09.8305110464.
- 8305110470 IE Info Notice 83-38, "Defective Heat Sink Adhesive & Beismically Induced Chatter in Relays Within Printed Circuit Cards " Svc list encl JORDAN, E.L. Division of Emergency Preparadness & Engineering Response (Post 830103) 83/06/13, Consolidated Edison Co. of New York, Inc. 118pp 18920:225, 24x Fiche 50-000,83/06/13,8305110470.
- 8306090010 IE Info Notice 83-37, "Transformer Failure Resulting From Degraded Internal Connection Cables" Svc list encl.
 JORDAN.E.L. Division of Emergency Preparadness & Engineering Response (Post 830103) 83/06/13. Connectidated Edison Co. of New York, Inc. 243pp. 18921.001. 24X Fiche: 50-000.83/06/13.8306090010.
- 8306290341 Ack recsipt of 830512 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-250/83-07 & 50-251/83-07.

 LEWIS, R.C. Division of Project & Resident Programs, 83/06/16, UHR10, R E. Floride Power & Light Co. 1p 19055-245, 24X Fichs, 50-250, 83/06/16, 8306290341
- --8306270345 Responds to NRC 830411 ltr re violations noted in IE Insp. Repts 50-250/83-07 & 50-251/83-07 Corrective actions' requests for relief from ABME Code requirements will be documented prior to insp. Disputes noncompliance for Unit 4. UHRIG.R.E. Florids Power & Light Co 83/05/12. O'REILLY, J. P. Region 2. Office of Director. 4pp. 17055.246. 24X Fiche. 50-250.83/06/16.8306270341.

- --8306290349 Forwards IE Insp Repts 50-250/83-07 & 50-251/83-07 on 830315-18 & notice of violation DANCE. H C Division of Project & Resident Programs 83/04/11 UHRIG.R.E Florida Power & Light Cn 2pp 19055 280 24% Fiche: 50-250, 83/04/14, 8306290341
- --8306290354 Notice of violation from insp on 830313-18 4 Region 2, Office of Birector 83/04/11, 2pp 19055 252 24X Ficha 50-250,83/06/16,8306290341
- --B306290357 IE Insp Repts 50-250/83-07 & 50-251/83-07 on 830315-18
 Noncompliance noted pump & valve inservice testing & component inservice insp not performed per ASME Boiler & Pressure Vessel Code, Section XI.
 KLEINBORGE, M P . BLAKEJ J Region 2, Office of Director B3/04/07 9pp 19055-254 24X Fiche, 80-230, 83/06/16, 8306290341.
- B305110475 IE Info Notice B3-40, "Need to Environmentally Qualify Epoxy Grouts & Sealers." Svc list encl.
 JORDAM.E.C. Division of Emergency Freparadness & Engineering Response (Post B301031, 83/06/22 Consolidate Edison Co
- 8305110477 IE Info Notice 83-41, "Actuation of Fire Suppression Bys Causing Inoperability of Safety-Related Equipment " Syc list encl JGROAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103), 83/06/22 Consolidated Edison Co of New York, Inc. 120pp. 18797.007 24X Ficher 50-000,83/06/22,8305110477.
- 8305110479 IE Info Notice 83-42, "Reactor Mode Switch Malfunctions "
 Svt list encl
 JORDAN, E.L. Division of Emergency Preparadness & Engineering
 Response (Post 830103) 83/06/23 Consolidated Edison Co of New
 York, Inc. 116pp 18976-242 24X Fiche-50-000,83/06/23,8305110479.
- 8305110483 IE Info Notice 83-43, "Improper Bettings of Intermediate Range (IR) High Flux Trip Setpoints " Syc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/24, Consolidated Edison Co. of New York, Int. 116pp 19046:297 24X Fiche: 50-000,83/06/24,8305110483
- R Periodic operating reports & related correspondence
- 830A02021A Monthly operating repts for Mar 1983, W/830415 ltr. PACE.P L , WILLIAMS, J.W. Florida Power & Light Co. B3/04/15, Office of Resource Management, Director 13pp. 18690 256 24X Fiche 50-000, 83/04/15, 8306020214
- B30616063B Monthly operating repts for Apr 1783 W/830516 ltr PACE.P.L., WILLIAMS.J W Florida Power & Light Co B3/05/16. Office of Resource Managament, Director 17pp. 18866.105 24X Fiche 50-900.83/05/16.8306160638
- 8 Reportable occurrences: LERs & related correspondence
- 830&210071 RD on 830516, several fire barrier penetrations breached for longer than 7 days. Caused by implementation of design changes, including new computer room & auriliary power upgrads, Hourly fire watch established UHRIO,R E Fiorida Power & Light Co 83/06/16. DENTON,H.R Office of Nuclear Reactor Regulation, Director ip 18912-309, 24X Fiche-50-250,83/06/16,8306210071
- 8304280148 Updated LER 83-006/01X-1 on 830405.notified that some masonry walls in control bldg do not comply w/original designs. Insp within control bldg completed & expanded to include outside walls Repairs scheduled W/830620 ltr ARIAG.J., WILLIAMS.J.W. Florida Power & Light Co. 93/06/20, 0'REILLY.J.P. Region 2. Office of Director. 3pp. 19015.105 24X Fiche 50-250.63/06/20,8306280148.

8304140127 Requests approved ref matl re operator exams by 830314. Missing deadline will result in delay in administering exams. Applications should be submitted at least 60 days prior to first exam scheduled for who of 830502 DANCE, H C Division of Project & Resident Programs 63/02/17, #fillid#6.J L. Floride Fower & Light Co. 4pp 18839:163, 24% Fiche:50-250.83/02/17,8306140127.

- DOCKET 50-251 TURKEY POINT PLANT, UNIT 4

 F Security, medical, emergency & fire protection plans
- 8306070050 Forwards IE Bafeguards Insp Repts 50-250/83-17 t 50-251/83-17 on 830420-22,0502-05 & 10-12 No nuncompliance noted DANCE, H. C. Division of Project & Resident Programs 83/04/0 UHRIQ, R. E. Florida Power & Light Co. 2pp 18740-053 24X Fiche 50-250-83/06/01,8306070050
- --8306070061 IE Safeguards Insp Repts 50-250/83-17 & 50-291/83-17 on 830420-22,0502-05 & 10-12 No honcompliance noted Major areas inspected licenses investigation of two closed valves in auxiliary feedwater sys Details withheld (ref 10CFR73 21) TOBIN.W Region 2. Office of Director 83/05/31 ip 18740-055-24% Fiche 50-250.83/06/01,8306070050
- 8306130435 Forwards, for review, Rev 1 to 830408 fire protection rept Rev provides specific info & justification for IOCFRSO. App R. exemption requests Exemptions unnecessary for Fire Areas/Zones D.E. 82.97.71 & 92
 URRIO, R E Florida Power & Light Co 83/06/06 EISCNHUT, D O Sivision of Licensing 1p 18821 036 24x Fiche 50-250, 83/06/06, 8306130435
- --8306130441 Rev 1 to "Fire Protection Rept"
 # Florida Power & Light Co 83/06/30 141pp 18821 037 24K
 Fiche 50-250.83/06/06.8306130435
- 830A230371 Confirms recent conversations w/util re control of access into containment during shukdown Becurity plan changes requested within AO days of itr receipt Bafeguards info withheld (ref 100FR73 21)
 VARGA, B. A Operating Reactors Branch 1 83/04/20 UHRIG.R E. Florida Power & Light Co ip 18744 135. 24X Fiche 50-250, 83/04/20,8306230371
- J Insurance & indemnity information
- 8304010398 Forwards Endorsement 45 to NELIA Policy NF-185 & Endorsement 55 to HAELU Policy HF-55 DUCK,J R Harsh & McLennan, Inc. 83/05/20 SALTZMAN,J Assistant Director for State & Licensee Relations Spp. 18682,237 24X Fichs 50-250,83/05/20,8304010398
- 8306230125 Forwards Endorsement & to NELIA Policy NF-185 & Endorsement 56 to MACLU Policy MF-55 DUCK, J R Harsh & McLennan, Inc. 83/06/16 SALTZMAN, J Assistant Director for Bates & Licenses Relations Spp. 18747-054. 24X Fiche 50-250,83/06/16,8306230125
- P Operating license stage documents & correspondence
- 830.6030056 Ack receipt of 821027 application & 830307 rev re proposed revised pump & valve inservice test program Remittance of Class III & I fees requested DIOGS, R H License Fee Management Branch. 83/05/27 UHRIG, R, E Florida Power & Light Co ip 18793.203 24X Fiche 50-250, 83/05/27, 8366030056
- 8306090382 Application for amend to Licenses DPR-31 & DPR-41, revising Tech Space to support fuel design change from Westinghouse low parasitic fuel assembly to optimized fuel assembly & use of new Westinghouse wet annuion turnable absorber rods UHRIG, R. E Florida Power & Light Co. 83/06/03, EISENHUT, D Q. Division of Licensing 3pp 18795.003. 24X Fiche. 50-250, 83/06/03, 8306070322.
- --8306090355 Proposed Tech Specs supporting fuel design change from Westinghouse low parasitic fuel assembly to optimized fuel assembly & use of new Westinghouse wet annular hurnable absorber rods # Florida Power & Light Co. 83/06/03 2ipp. 18795 006. 24% Fiche: 50-250, 83/06/03, 8306090352.
- 8306160335 Forwards response to 830422 request for add1 info re Criteria 2, 10 & 11 of NUREQ-0797. Item II B, 3, "Post-Accident Bampling " Interim core damage estimate guidelines will be submitted by 830630. UHRIQ.R.E. Florida Power & Light Co. 83/06/10 VARQA.B A. Operating Rescurs Branch 1, 3pp. 18861 171, 24X Fiche 50-250, 83/06/10, 8306160335.

- Q Inspection reports. IE Bulletins & correspondence
- 8306140577 Confirms mgt meeting on 830316 at Region II ofc to discuss recent insp findings re failure to properly evaluate radiation exposures at facility Proposed meeting agenda enci
 - enci O'REILLY, J.P. Region 2, Office of Director 83/03/15 UHRIG, R E Florida Pawer & Light Co. 2pp 18844 160 24X Fiche 50-250,83/03/15.8306140577
- 8306140393 Confirms 830428 enforcement meeting at Region II ofcs to discuss recent incident of unaveilability of auxiliary feedwater w/Unit 3 operating at full power.per 830422 telcon Proposed agenda encl O'REILLY.JP Region 2. Office of Director 83/04/26 UMRIO.R E Fiorida Power & Light Co 2pp 18832 096 24X Fiche 50-250.83/04/26.8306140393
- 8305110458 IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in Well Logsing Device" Svc list encl TAYLOR, J. M. Division of Safeguards & Inspection Programs (Post 830103), 83/05/26 Consolidated Edison Co of New York, Inc 125pp 18831 043 24X Fithe 50-000,83/05/24,8305110458
- 8305110460 IE Info Notice 83-34, "Event Notification Info Worksheet "
 Svc list enc!
 JORDAN, C L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/05/26 Consolidated Edison Co of New
 York, Inc 119pp 18732 088 24X Fiche 50-000,83/05/26,8305110460
- 8306270204 Forwards IE Insp Repts 50-250/83-13 & 50-251/83-13 on 830503-06 No noncompliance noted BANCE, H C Region 2. Office of Director 83/05/31 UHRIO, R E Florida Power & Light Co 2pp 19056 229 24X Fiche 50-250,83/05/31
- --8306270212 IE Insp Repts 50-250/83-13 & 50-251/83-13 on 830503-06 No noncompliance noted Major areas inspected containment integrated leakage rate testing BROKE, E, JAPE, F. Region 2, Office of Director, 83/05/24 App. 19056 231 24X Fiche 50-250,83/05/31,8306290204
- 8304070050 Forwards IE Bafeguards Insp Repts 50-250/83-17 & 50-251/83-17 on 830420-22.0502-05 & 10-12 No noncompliance noted DANCE. H. C Division of Project & Resident Programs 83/04/01. UHRIG, R E Florida Power & Light Co. 2pp 18740 053 24X Fiche 50-250,83/04/01.8304070050
- --8304070041 IE Befaguards Insp Repts 50-250/B3-17 & 50-251/B3-17 on B30420-22,0502-05 & 10-12 No noncompliance noted Major areas inspected licensee investigation of two closed valves in auxiliary feedwater sys Details withheld (ref 10CFR73 21) TODIN.W Region 2. Office of Director MCOUIRE, D R Division of Emergency Preparedness & Materials Safety. 83/05/31 ip 18740 055, 24X Fiche 50-250,83/06/01,8304070050
- 8306080003 Forwards util response to Enforcement Action 93-31 & payment of proposed civil penalty O'REILLY, J P Region 2, Office of Director, 83/06/03 DEYOUNG, R. C Director's Office, Office of Inspection and Enforcement 1p 18772 334 24X Fiche 50-250, 63/06/09, 8306080003
- --8306080004 Responds to NRC proposed civil penalty re violations noted in XE Insp Ropts 50-250/83-06 & 50-251/83-06 Corrective actions, operating instructions revised detailing duties during outage & nonoutage conditions for technicisms UHRIG, R E Florida Power & Light Co 83/06/01 0'REILLY, J. P Region 2, Office of Director 8pp 18772-355 24X Fichs 50-250,83/06/03,8306080003
- B30627037B Responds to IE Bulletin 83-03, "Check Valve Failures in Raw Water Gooling Bys of Diesel Generators" Closed cooling radiator sys contains no check valves Bulletin not applicable
 UHR10,R.E. Florida Power & Light Co B3/06/08 O'REILLY, J.P. Region 2, Office of Director. 2pp 19052 183 24X
 Fiche 50-000,83/06/08,8306290398.
- B30511Q464 IE Info Notice B3-36, "Impact of Security Practices on Safe Operations " Syc list encl.

 JORDAN,E L Divinion of Emergency Preparadness & Engineering Response (Post 830103) 63/06/09 Consolidated Edison Co. of New York, Inc 119pp 18830 280 24% Fithe: 50-000, 83/06/09, 8305110464
- 8305110470 IE Info Notice 83-38. "Defective Heat Bink Adhesive & Belemically Induced Chatter in Relays Within Printed Circuit Cards." Byc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co. of New York, Inc. 118pp 18920, 225 24X Fiche 50-000, 83/06/13, 8305110470

- 8306290341 Ack receipt of 830512 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-250/B3-07 & 50-250/B3-07 &
- --8306290345 Respands to NRC 830411 ltr re violations noted in IE Imap Repts 50-250/83-07 & 50-251/83-07 Corrective actions: requests for relief from ABME Code requirements will be documented prior to insp Disputes noncompliance for Unit 4 UHRIG.R E Florida Power & Light Co 83/05/12 0'REILLY, J. P. Region 2. Office of Director 4pp 19055 246 24% Fichs 50-250,83/06/16,8306290341
- --8306270347 Forwards IE Insp Repts 50-250/83-07 & 50-251/83-07 on 830315-18 & notice of violation DANCE.H C Division of Project & Resident Programs 83/04/11. UHRIG.R E Florida Power & Light Co 2pp 17055 250 24X Fiche 50-250.83/06/16.8306270341.
- --8306290354 Notice of violation from insp on 830315-18 # Region 2: Office of Director 83/04/11 2pp. 19055.252, R4X Fiche 50-250.83/06/16.8306290341
- --8306270357 IE Insp Repts 50-250/83-07 & 50-251/83-07 on 830315-18 Noncompliance noted pump & valve inservice testing & component inservice insp not performed per ASME Boiler & Pressure Vessel Code, Section XI.
 KLEINSORGE, H P. BLAKE, J.J. Region 2, Office of Director.
 B3/04/07 9pp 19055 254 24% Fiche 50-250.83/06/16.6306290341
- 8305:10475 IE Info Notice 83-40, "Need to Environmentally Qualify
 Epoxy Grouts & Bealers," Svc list encl
 JORDAN E L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/06/22 Consolidated Edison Co of New
 York, Inc 115pp, 19021 179 24X Fiche, 50-000, 83/06/22, 8305110475.
- 8305i10477 IE Info Notice 83-41, "Actuation of Fire Suppression Sys Causing Imperability of Safety-Related Equipment " Svc list encl JORDAN, E.L. Division of Emergency Preparadness & Engineering Response (Post 830103) 83706/22 Consolidated Edison Co of New York, Inc 120pp 18997.007, 24X Fiche.50-000, 83/06/22, 8305110477.
- 8305110479 IE Info Notice 83-42, "Reactor Mode Switch Malfunctions' M Byc list encl JORDAN, E.L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/23 Consolidated Edison Co. of New York: Inc. 116pp. 18796, 242 24X Fiche, 80-000, 83/06/R3, 8305110479.
- 8305110483 IE Info Notice 83-43, "Improper Bettings of Intermediate Range (IR) High Flux Trip Setpoints " Svc list encl JORDAN, E. L. Division of Emergency Preparadness & Engineering Response (Post 830103), 83706/24 Consolidated Edison Co. of New York, Inc. 116pp, 19046:297 24X Fiche 50-000,83/06/24,8305110483.
- R Periodic operating reports & related correspondence
- 8306160638 Monthly operating rapts for Apr 1983 W/830516 ltr. PACE:P L , WILLIAMS.J W Florida Power & Light Co. 83/05/16, Office of Resource Management, Director 17pp 18866.105. 24X Fichs 50-000,83/05/16,8306160638
- S Reportable occurrences, LERs & related correspondence
- 8306210197 Updated LER 83-001/01X-1:on 830331, while in refueling shutdown, discrepancies identified in bolting of platform framing steel to containment liner embedments. Bolts improperly installed, Deficiencies corrected, W/830610 ltr. ARIAS, J. WILLIAMB, J. W. Florida Power & Light Co. 83/06/10, O'REILLY, J. P. Region 2, Office of Director 3pp. 18914, 155, 24x Fiche 50-251, 83/06/10, 8306210197.
- B306270200 LER B3-005/01T-0:pn B30601, mechanical maint supervisor determined that safaty-related snubber inoperable due to incomplete mod to attachment. Gaused by personnel error & procedure deficiencies. Mod completed M/830615 ltr. ARIAB. J. WILLIAMB. J. M. Florida Power & Light Co. 83/06/15 O'REILLY, J.P. Region 2, Office of Director. 3pp. 18991;280, 24x Fiche: 50-251, B3/06/15, 8306270200.
- B306210071 RO on B30516, several fire barrier penetrations breached for longer than 7 days Caused by implementation of design changes, including new computer room & auxiliary power upgrade, Hourly fire watch established UHRIG.R E Floride Power & Light Co 83/06/16 DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 1p 18912-309. 24% Fiche. 50-250, 83/06/16.8306210071

8306140127 Requests approved ref matline operator sxams by 830314 Missing deadline will result in delay in administering exams Applications should be submitted at least 60 days prior to first exam scheduled for whof 830502 DANCE.H C Division of Project & Resident Programs 83/02/17 HILLIAMS.J L Florida Power & Light Co 4pp 18839 163 24X Fiche: 50-250.83/02/17.8306140127

DOCKET 50-254 GUAD-CITIES STATION, UNIT 1

F Security, medical, emergency & fire protection plans

- B306130405 Forwards IE Insp Repts 50-254/83-15 & 50-265/83-13 on B30510-13 No noncompliance noted PAPERIELLO.C J Region 3. Office of Director 63/05/27 REED.C Commonwealth Edison Co 2pp 18923 064 24% Fiche 50-254,83/05/27,
- --8306130412 IE Insp Repts 50-254/83-15 & 50-265/83-13 on 830510-13 No noncompliance noted Major areas inspected emergency preparedness exercise PHILLIPS.N . PLOSKI.T . OLOSKSEN.N W Region 3. Office of Director 83/05/27 26pp 18823 066 24X Fiche 50-254,83/05/27,8306130405
- 8306160071 Releases public version of revised emergency plan implementing procedures FELTON.J H Division of Rules and Records 83/06/07 Document Management Branch 1p 18872 349 24X Fiche 50-254,83/06/07,8306160071
- ---B306160077 Public version of Rev 11 to Emergency Plan Implementing Procedure GEP 550-0. "Emergency Equipment & Supplies" & Rev 5 to GEP 550-TI, "Environ Sampling Supplies." Receipt form encl * Commonwealth Edison Co 83/05/04 Office of Nuclear Reactor Regulation, Director 6pp. 18872 350 24% Fiche 50-254,83/06/07,8306160071

P Operating license stage documents & correspondence

- 8306090174 Discusses util interpretation of 10CFR50 49, "Environ Gualification of Electrical Equipment Important to Sefety for Nuclear Power Plants" Intent of rulemaking is to require upgrade program for replacement equipment not parts FARRAR, D. L. Commonwealth Edison Co. 83/06/03 DENTON, H. R. Dffice of Nuclear Resctor Regulation, Director 3pp 18796,090 24X Fiche 50-000,83/06/03,8306090194
- 8306090227 Informs that response to Generic Ltr 83-08 will be submitted by 830713 Info will include stress repts to determine mod to vacuum breakers on Mark I containments Ry9ANB Commonwealth Edison Co. 83/06/06 DENTON, H R Dffice of Nuclear Reactor Regulation, Director 19 18796-234 24X Fiche: 50-000, 83/06/06, 8306090227.
- 8306160233 Advises that manufacturers whose repts were used in technical evaluation repts re environ qualification of electrical equipment have been contacted List of proprietary pages detailed in util 830513 itr W/GE affidavit HYBAM.B. Commonwealth Edison Co. 83/06/06 DENTON.H R. Office of Nuclear Reactor Regulation, Director. 5pp 19861-304 24X Fiche 50-000.83/06/06.8306160233
- 8306270108 Discusses final mods to be installed per NRC B10113 & 820119 orders & extension of examptions for Mark I containment work Completion of minor mods expected during next outage, scheduled for Spring 1984
 RYBAX.B Commonwealth Edison Co 83/06/15 DENTON, H R. Office of Nuclear Reactor Regulation, Director 2pp 18988 115 24X
 Fichs 50-254,83/06/15,8306270108
- 8306270324 Advises that beta spectra measurements will be conducted at facilities on 830628-29 for NRC project, "Beta Particle Heasurement & Dosimetry Requirements at NRC-Licensed Facilities" RATHBUN.L A. Battelle Memorial Institute, Pacific Northwest Laboratory FIN 8-2448 83/06/17. KEPPLER,J Q. Region 3. Office of Director. 1p 18994 074 24% Fiche 50-254, B3/06/17. B306270324.
- 8306300237 Advises that listed mode will be complete by Spring 1984 outage, per 830615 request for extension of Mark I containment program RYBAN, 8. Commonwealth Edison Co. 83/06/22 DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 2pp. 19119:339, 24X Fiche: 50-254, 83/06/22, 8306300237,

- G Inspection reports: IE Bulletins & correspondence
- 8306220218 Ack receipt of 830414 payment of proposed civil panalties Response to notice of violation & proposed imposition of civil penalties will be evaluated & corrective actions examined during future insps AXELRAD, A Enforcement Staff 83/04/21 REED, C Commonweelth Edison Co 2pp 18980 357 248 Fichs 50-000,83/04/21,8306220218
- 8306030139 Forwards IE Insp Repts 50-254/62-14 & 50-269/62-12 on 830419-20 No noncompliance noted LITTLE: W S Region 3. Office of Director 82/09/17 REED, C Commonwealth Edison Co 2pp 18704 291 24X Fichs 50-254, 83/05/17, 8306030139
- --8306030143 IE Insp Repts 50-254/82-14 & 50-265/83-12 on 830419-20 No noncompliance noted Major areas inspected action re IE Bulletin 80-11. "Masonry Wall Design "
 NORTON, J F , WILLIAMS, C Region 3. Office of Director 83/05/16 4pp 18704 293 24X Fiche 50-254/83/05/17.8306030137
- 8306010179 Informs of results of NRC review of relief requests from inservice insp requirements Relief granted in part, por encl safety evaluation VASSALLO.D B Operating Reactors Branch 2 03/05/19 FARRAR, D L Commonwealth Edison Co 3pp 18696 010 24X Fiche 50-254,83/05/19,83/05/19,
- --8306010182 Safety evaluation supporting in part & denying in part, requests for relief from inservice insp requirements
 * Dffice of Nuclear Reactor Regulation. Director 83/05/19 9pp
 18696 013 24X Fiche 50-254.83/05/19.8306010179
- --8209200365 "Quad Cities Nuclear Power Station Units 1 & 2 Inservice Insp Program." technical evaluation rept * Science Applications. Inc NRC-03-82-096. SAI-186-028-30 82/09/17 NRC No Detailed Affiliation Given 45pp 18696 023 24X Fiche 50-254.83/05/19.8306010179
- 8305110458 IE Info Notice 83-32. "Ruptured Am-241 Sources Contained in Well Logging Device" Svc list encl
 TAYLOR.J M Division of Safegouards & Inspection Programs (Post 830103) 83/05/26 Consolidated Edison Co of New York
- 8305ii0460 lE Info Notice 83-34, "Event Notification Info Worksheet." Eve list encl JORDAN, E. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/09/24 Consolidated Edison Cu of New York, Inc 115pp 18732 085 24X Fiche 50-000,83/09/26,8305110460
- 8306130405 Forwards IE Insp Repts 50-254/83-15 & 50-265/83-13 on 830510-13 No noncompliance noted PAPERIELLO,C.J. Region 3. Office of Director, 83/05/27 REFD.C Commonwealth Edison Co. 2pp 18823 064, 24X Fiche 50-254,83/05/27,8306130405
- --8306130412 IE Insp Repts 50-254/83-15 & 50-265/83-13 on 830510-13 No noncompliance noted Major areas inspected emergency preparedness exercise PHILLIPB.H., PLOSKI,T., GLOERSEN,N W. Region 3, Office of Director 83/05/27 26pp 18823 066 24X Fiche 50-254.83/05/27.8306130405
- 8305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods Withdrawn at BWRs " Svc list encl JORDAN, E L. Division of Emergency Preparadness & Engineering Response (Poet 830103) 83/05/31 Consolidated Edison Co. of New York, Inc. 116pp 18732 208 24X Ficher 50-000, 83/05/31, 8305110461
- 8304040208 Ack receipt of 830405 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-254/82-24 & 50-245/82-29 SPESSAB, R L Division of Engineering 83/05/31 REED, C Commonwealth Edison Co 1p. 18727.351. 24X Fiche: 50-254,83/05/31,8304040208
- --8304060212 Responds to NRC 830309 ltr re violations noted in IE Insp. Rapts 50-254/82-24 & 50-265/82-28 Corrective actions onsite review conducted on 830228 documenting computer program used for integrated leak rate test. RYBAK, B. Commonwealth Edison Co. 83/04/05 KEPPLER, J. Q. Region 3, Office of Director. App. 18727-352 24X Fichs 50-254, 83/08/31,8306060208
- 8306070175 Forwards corrected Page 1 to 1E Insp Repts 50-254/83-14 & 50-265/83-12 on 830419-20. No noncompliance noted LITILE: W 8. Region 3. Office of Director 83/06/03. REED, C. Commonwealth Edison Co. 1p 18736.331 24X Fiche.50-254,83/06/03. 8306070175.

- --8306070190 Corrected Page 1 to IE Insp Repts 50-254/83-14 & 50-255/83-12 on 830419-20 No noncompliance noted Major areas inspected licensee action re IE Dullstin 80-11, "Masonry Wall Design " NORTON.J F. WILLIAMS.C C Region 3, Office of Director 83/06/02 ip 18736 332 24X Fiche 50-254, 83/06/03.6306070175
- 8306100149 Forwards Rev 3 to "180-Day Rept in Response to IE Bulletin 80-11 for Dresden 2 & 3 & Quad Cities 1 & 2 " RYBAK,B Commonwealth Edison Co 83/06/06 KEPPLER,J 0 Region 3, Office of Director 2pp 18804 161 24X Fiche 50-000,83/06/06, 8306100149
- --8306100156 Rev 3 to "180-Day Rept in Response to IE Bulletin 80-11 for Dresden 2 & 3 & Guad Cities 1 & 2 "

 # Commonwealth Edison Co 83/05/09 127pp 18804 163 24X
 Fiche 50-000.B3/06/06.B306100147
- 8304100094 Forwards response to IE Bulletin 83-03 re diesel generator cooling water chack valves Plants utilize Mission Duo-Check valves employing hinge-to-pin design for protection against vibration-induced failure
 BARNEB.P L Commonwealth Edison Co 83/06/07 KEPPLER, J 0 Region 3, Office of Director, 7pp. 18802 238 24X Fiche 50-000,83/06/07,8306100094
- 8304170380 Forwards response to IE Bulletin B3-03 re diesel generator cooling water check valves Valves at Dresden & LaSalle acceptable w/o further inap Rept on valve failures at Quad Cities will be submitted within 90 days of inap completion BARNEB, P. L. Commonwealth Edison Co. 83/06/07 KEPPLER. J. @ Regio. 3. Office of Director 7pp 18880 211 24X Fiche 50-000,83/06/07,8306170380
- B305110464 IE Info Notice B3-36, "Impact of Security Practices on Bafe Operations " Svc list enc!

 JORDAN E L Division of Lmergency Preparedness & Engineering Response (Post B30103) B3/06/09 Consolidated Edison Co of New York, Inc 119pp 18830 280 24X Fiche 50-000,83/06/09,8305110464
- 8305110470 IE Info Notice 83-38, "Defective Heat Sink Adhesive & Seismically Induced Chatter in Relays Within Printed Circuit Cards " Syc list encl JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83706/13 Consolidated Edison Co of New York, Inc. 118pp 18920, 225 24X Fiche, 50-000, 83706/13, 8305110470
- B306090010 IE Info Notice B3-37, "Transformer Failure Resulting From Degraded Internal Connection Cables " Svc list encl JURDAN,E L Division of Emergency Preparedness & Engineering Response (Post 630103) B3/06/13 Consolidated Edison Co. of New York, Inc. 243pp 18921 001 24X Fiche 50-000, B3/06/13, B306090010
- 8308220067 Summarizes revised schedule for util review of automated analytical instrumentation sys multiplet analysis capability per IE Insp Repts 50-254/82-13 & 50-265/82-15 RYBAK. B Commonwealth Edison Co 83/06/13, PAPERIELLO, C J Region 3, Office of Director 2pp 18928 180 24X Fiche, 50-254, 83/06/13, R30A290647
- 8304200149 EN-83-043, on 830421, notice of violation & proposed imposition of civil penalties in amount of \$150,000 will be issued re Security Level III violations concerning shutting down reactor by inserting control rods in reverse order BARBER, 0 , AXELRAD, J. Director's Office, Office of Inspection and Enforcement 83/04/16, ip. 18903, 120, 24X Fichs 50-234,83/04/16,830420149
- 8306300235 Forwards IE Insp Repts 50-237/83-12.50-249/83-10. 50-254/83-13 & 50-265/83-11 on 820412-14 & 0506 & 16 & notice of violation LITTLE.W S Region G. Office of Director. 83/06/16 REED.C Commonwealth Edison Co 2pp. 19122.279 24X Fichs.50-000.83/06/16.8306300235.
- --8306300238 Notice of violation from insp on 830412-14 & 0506 & 16. LITTLE,W 8 Region 3. Office of Director. 83/06/16 2pp 19122 281 24X Fiche.50-000,83/06/16.8306300235
- --8306300R46 IE Insp Repts 50-237/83-12,50-247/83-10,50-284/83-13 & 50-265/83-1i on 830412-14 & 0506 & 16. Noncompliance noted, as-built confirguration (for pipe anchor RI33 in pressure suppression sus differed from original design YIN.1 T , DANIELBON, D. H. Region 3, Office of Director 83/06/15 9pp 19122 283, 24X Ficha,50-000,83/06/16,8306300235
- B30622002B Ack receipt of B30509 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-254/B2-26 & S0-245/B2-26 & KEPLER, J Q Region 3, Office of Director, B3/06/17 REED, C Commonwealth Edison Ca. ip. 18930.036, 24X Fiche 90-254,83/06/17, B306220028

- --B306220034 Responds to NRC B30411 ltr re violations noted in IE Insp Repts 50-254/B2-26 & 50-265/B2-26 Corrective actions startup procedure revised to include sign-off space verifying alarm has cleared REED. C Commonwealth Edison Co B3/05/09 Director's Office, Office of Inspection and Enforcement 7pp 18930 037 24X Fiche 50-254,83/06/17,8306220028
- 8306270293 Forwards notice of violation & proposed imposition of civil penalties to be issued to licensee Action based on improper manipulation of control rods which occurred during IE safety insp on 830310-11 KEPPLER.J & Region 3. Office of Director 83/06/21 D'CONNOR.J.J Commonwealth Edison Co. App. 18970 141 24X Fiche 50-254, 83/06/21.8306270293
- --8306270R98 Notice of violation & proposed imposition of civil ponalties in amount of \$150,000 based on improper manipulation of control rode which occurred during IE safety insp on 830310-11

 KEPPLER:J 0 Region 3, Office of Director. 83/06/21, 5pp. 18790 145 24X Fiche 50-254,83/06/21,8306270293
- 8305110475 IE Info Notice 83-40, "Need to Environmentally Qualify Epoxy Grouts & Sealers." Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83706/22 Consolidated Edison Co of New York, Inc 115pp 19021 179 24X Fiche. 50-000, 83/06/22, 8305110475
- 8305110477 IE Info Notice 83-41, "Actuation of Fire Suppression Sys Causing Inoperability of Bafety-Related Equipment " Syc list encl.
 JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post B30103) 83/06/22 Consolidated Edison Co. of New York, Inc. 120pp. 18997 007 24X Fiche. 50-000, 83/06/22, 8305110477.
- 8305110479 IE Info Notice 83-42, "Reactor Mode Switch Malfunctions."

 Syc list encl

 JORDAN, E. Division of Emergency Preparadness & Engineering

 Response (Post 830103) 83/06/23 Consolidated Edison Co. of New

 York, Inc. 116pp 18996-242 24X Fiche 50-000.83/06/23.8305110479
- 8305110483 IE Info Notice 83-43, "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints," Svc list encl.
 JORDAN E L Division of Emergency Preparedness & Engineering Response (Post 830103). 83/06/24 Consolidated Edison Co. of New York, Inc. 116pp 19046:297 24X Fiche, 50-000, 83/06/24, 8305110483
- R Periodic operating reports & related correspondence
- 8306170314 Monthly operating repts for May 1983. W/830606 ltr.
 WEINFURTER, E. MIBAK.A. A. KALIVIANAKIB.N. Gommonwealth Edison Co.
 83706/06. Director's Office of Price of Inspection and Enforcement
 22pp 18877 042 24X Fiche: 50-254.83/06/06.8306170314.
- 8 Reportable occurrences, LERs & related correspondence
- B306130337 LER B3-020/03L-0 on B30510, while performing monthly Exercise GDB 1600-1, Div II indicating lights for vacuum breater 1-1601-39F did not operate when valve exercised Caused by slight binding in vacuum breaker main shaft W/B30526 ltr. #, KALIVIANAKIS.N Commonwealth Edison Co B3/05/26. KEPPLER, J. Q. Region 3, Office of Director. 4pp. 18822-273 24X Fiche. 50-254, B3/05/26. B306130337
- 8306130329 LER 83-021/01T-0: on 830520, pinhole leak discovered on reactor continuous head vent line, Caused by slag entrapment within weld during initial installation Indication removed & rewelded W/830601 ltr
 TIETZ.G., KALIVIANANIS.N Commonwealth Edison Co. 83/06/01.
 KEPPLER.J. Region 3. Défice of Director 5pp. 18822-356 24% Fiche 50-254.83/06/01.8306130329
- 8304300043 LER 83-023/03L-0. on 830522, electromatic relief valve opened for no obvious reason at aprrox 60 psig Caused by electromatic relief pilot velve assembly stuck in open position Pilot valve replaced, W/830608 ltr.
 COOK, D., KALIVIANAKIB, N. Commonwealth Edison Co., 83/06/08, KEPPLER, J. Q., Region 3, Office of Director 4pp. 19120, 223 24X Fiche: 50-254, 83/06/08, 8306300043.
- B306270252 LER B3-022/03L-0 on B30523,RCIC steem supply valve MD-i-1301-16 did not give open position indication when operated from control room, Valve Pound open. Caused by loose wire on open limit switch W/830616 ltr. RUBTICK, R, KALIVIANAKIB, N. Commonwealth Edison Co. 83/06/16. KEPPLER, J. Q. Region 3, Office of Director. 2pp. 18990: 225 24X Fiche 50-254,83/06/16,8306270252

8306270282 Potential Part 21 rept re discrepancy in welding of turnbuckle assembly, turnbuckle-bolt interface & on top plate assembly variable springs SA307 Grade B bolts not ABME Section IX matl Investigation underway KARADIANIS. J A Elcen Metal Products Co 83/06/17 KEPPLER. J G Region 3. Defice of Director 2pp 18976 207 24X Fiche: 50-000,83/06/17,8306270282

DOCKET 50-255 PALISADES NUCLEAR PLANT

- F. Security, medical, emergency & fire protection plans
- 8306090201 Releases public version of Rev O to Emergency Plan Implementing Procedure EI 7 I. "Post-Accident Sampling " FELTON.J M Division of Rules and Records 83/06/01 Document Management Branch is 18809 236 24X Fichs 50-255.83/06/01, 8306090201
- --8306090203 Public version of Rev 0 to Emergency Plan Implementing Procedure El 7 1. "Post-Accident Sampling " W/830519 ltr & receipt form EMBREY.B Consumers Power Co 83/05/19 14pp 18809 237 24X Fiche 50-255,83/06/01.8306090201.
- 8306090285 Releases public version of revised emergency plan implementing procedure FELTON. JM Division of Rules and Records 83/06/01 Document Management Branch 1p 18810-026 24X Fiche. 50-255, 83/06/01, 830680285
- --B305090287 Public version of Rev O to Emergency Plan Implementing Procedure El-7 5, "Boron: Mannitol Titration Method Post-Accident " W/630820 Itr & receipt form EMBREY, B Consumers Power Co 63/05/19 Spp 19810 027. 24X Fiche: 50-255.63/06/01.8305090285
- 8306140828 Releases public version of revised emergency plan implementing procedure.
 FELTON.U M Division of Rules and Records 83/06/01 Bocument Management Branch 1p 18853:206 24X Fiche, 50-255, 83/06/01, 8306140828
- --8306140831 Public version of Rev O to Emergency Plan Implementing Procedure EI-7 6, "Quantitative Analysis of Chloride in Post-Accident Solution " W/830820 ltr & receipt form. EMBREY, B Consumers Power Co 63/05/18 7pp 18853 208, 24x Fichs 50-255,83/06/01,8306140828
- 8306130088 Advises that 830505 changes to security plan do not decrease effectiveness of plan & are consistent w/100FR30 54(p) & are acceptable CRUTCHFIELD.D Decreting Reactors Branch 5 83/04/06 VANDEWALLE, D.J. Consumers Power Co. 2pp 18872 123 24X Fiche 50-235,83/04/06,8306150088
- 8306130334 Forwards "Suppl 1 to NUREC-0737, Milestone Activity --Bubmittal of Updated Detailed Control Room Design Review Program Plan " TONER: K A. Consumers Power Co 83/06/07 CRUTCHFIELD, D. Operating Reactors Branch 5. 1p 18822:197. 24X Fiche 50-255,83/06/07, 8306130334
- --8306130335 "Suppl 1 to NUREQ-0737, Milestone Activities Submittal of Updated Detailed Control Room Design Review Program Plan " = Consumers Power Co 83/06/07, 12pp 18822, 198 24x Fiche: 50-255, 83/06/07, 8306130334
- 8306220025 Confirms B30623 security enforcement meeting in Olen Ellyn, IL to review breach of security event on B30523, corrective actions & to discuss enforcement actions. REPPLER, J. Q Region 3, Office of Director. B3/06/16 SELBY, J D Consumers Power Co ip 18728 215 24x Fiche: 50-255, 83/06/16, B306220025
- 9306300014 Forwards IE Insp Rept 50-255/83-13 on 830501-31. No nonecampliance noted BHAFER, H.D. Region 3, Office of Director 83/06/16. DEWITT, R.B. Consumers Power Co 2pp 17120 255. 24x Fichs, 50-205, 83/06/16, 8306300014.
- --B304300021 IE Imsp Rapt 50-255/83-13 on B30501-31.No noncompliance noted Major areas inspected: LERs: operational safety. surveillance maint, reactor trip & miscellaneous items JORGENBER: 8 L., HELLER: J K., BOYD. D. C. Region D. Office of Director. 83/06/16. 7pp. 19120:257 24X Fiche: 50-255, B3/06/16. 8306300014.

- 8306240289 Forwards response to NRC 830506 & 09 ltrs re security & suitability, training & qualification plans, respectively Response withheld (1006R73 21) VANDEWALLE, D. J. Consumers Power Co. 83/06/20 CRUTCHFIELD, D. Operating Reactors Branch S. 2pp 18980 151 24x Fiche 50-000, 83/06/20, 8308240285
- J Insurance & indomnaty information
- 9306210151 Forwards Endorsements 79 & 68 to NELIA Policy NF-179 & MAELV Policy MF-50, respectively FROUNFELKER, R Consumers Power Co. 93/06/14 SALTZMAN, J. Antitrust & Economic analysis Branch (Utility Finance) 4pp 18915 243 24% Fishe 50-255.83/06/14,8306210151
- P Operating license stage documents & correspondence
- 8306030362 Forwards revs to "Environ Qualification of Safety-Related Electrical Equipment." in response to SER open items per NRC request Rev affects Encls 1.2.4 & 5 re schedule of equipment qualification for Items I B.II A.II B & IV TONER.K A Consumers Power Co. 83/05/20 CRUTCHFIELD.D Operating Reactors Branch 5 279pp 18703 001 24X Fiche 50-255.83/05/20, 8306030342
- 8304040145 Forwards Engineering Analysis EA-83-8R0-005, "Add1 Resistive Isolation Devices for RPS/F&P Computer Interconnections," per util 820214 commitment re SEP Topic VIII-1 A TONER, K A Consumers Power Co 83/05/27 CRUTCHFIELD, D Operating Reactors Branch 5 3pp 18/19 131 24X Fiche 80-255.83/05/27.
- --8304040149 "Addl Resistive Isolation Devices for RPS/F&P Computer Interconnections " * Gunsumors Power Co EA-B3-GRQ-005 63/04/18 28pp 18719 134 24X Fiche 50-255.63/05/27.6306060145
- 8306060044 Responds to 830505 amend application Forwards FR notice of consideration of issuance of amend re intervals between testing certain components & sys CRUTCHFIELD, D. Operating Reactors Branch 5 83/05/31 VANDEWALLE, D. J. Consumers Fower Co. 2pp. 18719 233 24x Fiche 30-255,83/05/31,8306060044
- --B306060047 Natice of consideration of issuence of emend to provisional OL & proposed na significant hazards cansideration determination & opportunity for hearing re surveillance test frequency GRUTCHFIELD.D Operating Reactore Branch 5 B3/05/31 /pp 18719 235 24% Fiche 50-25D.83/05/31.8306060044
- 8304070042 Forwards safety evaluation of proposed resolution of integrated plant SAR Section 4 27 re svc & cooling water sys. Mods acceptable.
 WAMBACH.T V. Operating Reactors Branch 5 83/05/31.
 VANDEWALLE.D J Consumers Power Co 2pp 18740 100 24x
 Fichs. 50-255, 63/05/31, 8304070042
- --8306070063 Safety evaluation on integrated plant SAR Saction 4 27 ra svc & cooling water sys * Operating Reactors Branch 5 83/05/31 3pp 18740 102 24X Fiche 80-255,83/05/31,8306070062
- 8306070247 Forwards BER of 821101 response to integrated plant safety assessment rept Section 4 28 re ventilation sys Proposed mods acceptable HAMBACH.TV. Operating Reactors Branch 5 93/06/03 VANDEWALLE, D. J. Consumers Fower Co. 2pp 18740 314 24X Fiche 50-255, 83/06/03.8306070247
- --8306070250 BER of util 821101 response to integrated plant safety analysis rept, Section 4 28 ro ventilation sys Issues resolved 8 Office of Nuclear Reactor Regulation, Director 83/06/03 3pp 18740 316 24X Ficher 50-255,83/06/03,8306070247
- 8306160376 Advises that design of electrical penetrations similar to other SEP plents Probability of electrical failure low & any leakage path due to penetration failure would be small Issue completed No Further action required MAMBACH, T. V. Operating Reactors Branch 5. 83/06/10 VANDEMALLE, D. J. Consumers Power Co. 4pp. 18860-191 24X Fiche. 50-255, 83/06/10, 8306160396.
- 8304220020 Provides util action plan to close BEP Topic III-6,
 "Seismic Design Considerations,"
 TONER K A Consumers Power Co 83/04/15 CRUTCHFIELD, D Operating
 Reactors Branch 5. Spp. 18928 216, 24X Fishe 50-285, 83/06/15,
 8306220020

- 8306230374 Withdraws 810505 Tech Spec change request re steam generator insp program & 810602 & 0702 suppls to change request JOHNSON, B D Consumers Power Co 83/06/15 CRUTCHFIELD, D Operating Reactors Branch 5 ip 18942 346 24X Fiche 50-255, 83/06/15, 8306230374
- 830.6230413 Supplements 830202 ltm discussing alternative to automatic isolation of V-79 exhaust sys when radiation detected, per NUREO-0737. Item II F I i Explanation of why alternatives to proposed mod investigated discussed JOHNSON. II D. Consumers Power Co. 83/06/17 KEPPLER. J. G. Region C. Office of Director. 3pp. 18941-340. 24X Fiche 50-255,83/06/17.
- 8306280439 Forwards evaluation of integrated plant SAR, Sections 4 9 & 4 15 re pipe break inside containment & RCFB leakage detection requirements Section 4 7 complete Corrective measures required for Section 4 15 within 90 days WAMBACH, TV Operating Reactors Branch 5 83/06/22 VANDEWALLE,D J Consumers Power Co 8pp 19018 329 24X Fiche 50-255,83/06/22,8304280439
- 630.6290323 Forwards safety evaluation of proposed resolution of classification of structures, sys & components issue in Section 4 5 of integrated plant safety assessment rept (NUREO-0820) Info acceptable to resolve open items WAMDACH: T Operating Reactors Branch 5 83/06/27 VANDEWALLE, D J Consumers Power Co 7pp 19055 306 24X Fiche 50-255.83/06/27.8306290323

O Inspection reports, IE Bulletins & correspondence

- 8305110458 IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in Well Logging Device" Svc list enc).
 TAYLOR, J M Division of Bafeguards & Inspection Programs (Post 830103) 83/05/26. Cansolidated Edison Ca of New York, Inc 125pp 18831 043 24X Fiche 50-000,83/05/26,8305110458
- 8305110460 IE Info Notice 82-34, "Event Notification Info Worksheet"
 Syc list encl
 JORDAN.C L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/05/26 Consolidated Edison Co of New
 York, Inc 115pp 18732 085 24X Fiche 50-000.83/05/26.8305110460
- 8305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods Withdrawn at BWRs " Svc list one! JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/31 Consolidated Edison Co. of New York, Inc. 1166p 18732:208 24X Fiche 50-000,83/05/31,8305110461
- G30407006B Responds to B30310 IE Bulletin B3-03, "Check Valve Failure in Raw Mater Cooling Sys of Diesel Generators "Design of couling water flow path to diesel generators does not utilize check valves IE Bulletin 82-03 not applicable JOHNBON, D D Consumers Power Co B3/05/31 KEPPLER, J. & Region 3, Office of Director 2pp 10740:093 24X Fiche 50-255, 83/05/31, 830407006B
- 8305110464 IE Info Notice 83-36. "Impact of Security Practices on Bafe Operations" Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/09 Consolidated Edison Cn of New York, Inc. 117pp 18830 280 24X Fiche, 50-000, 83/06/09, 8308110464
- 8306190376 Forwards addendum Table 11, confirmatory measurements program data sharts to be included in IC Insp Rept 50-255/82-22 transmitted 821020 PAPERIELLO,C J. Region 3, Office of Director 83/06/10 DEMITTR B. Consumers Power Co. 2pp 18823 273 24X Fiche 80-255,83/06/10,8306130376
- B305110470 IE Info Notice B3-38. "Defective Heat Sink Adhesive & Beismically Induced Chattan in Relays Within Printed Circuit Cards." Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co of New York. Inc 118pp 18920 225 24X Fiche 50-000.83/06/13,8305110470
- 8304090010 IE Info Notice 83-37, "Transformer Failure Resulting From Degraded Internal Connection Cables" 8vc list encl.
 JORDAN,E L Division of Emergency Preparadness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co of New York, Inc. 243pp. 18921 001 24X Fichs 50-000.83/06/13,8306090010.
- 8306230374 Withdraws 810505 Tech Spec change request re steam generator insp program & 810602 & 0702 suppls to change request JOHNSON, B. D. Consumers Power Co. 83/06/15 CRUTCHFIELD, D. Gperating Reactors Branch 5 1p 18742 346 24X Fichs. 50-253, 83/06/15, 8306230374

- 8306300014 Forwards IE Insp Rept 50-255/83-13 on 830501-31. No noncompliance noted SHAFER: N D Region 3: Office of Director 83/06/16 DEWITT: R B Consumers Power Co. 2pp 19120 255 24X Fiche- 60-255: 83/06/16. 8306300014
- --8306300021 IE Insp Rept 50-255/83-13 on 830501-31 No noncompliance noted Major areas inspected LERs, operational safety, surveillance, maintreactor trip & miscellancous items JORGENSEN, B L , HELLER, J K , BDYD, D C Region 3, Office of Director 63/06/16 7pp 19120 257 24X Fichs 50-235,83/06/16, 8306500014
- 8305110475 IC Info Notice 83-40, "Need to Environmentally Qualify
 Epoxy Grouts & Sealors " Svc list encl
 JORDAN, E. L. Division of Emergency Preparedness & Engineering
 Response (Fost 830103) 83706/22 Consolidated Edison Co of New
 York, Inc 113pp 19021 179 24X Fiths 50-000, 83706/22, 8305110475.
- 8305110477 IE Info Natice 83-41: "Actuation of Fire Suppression Sys-Causing Inoperability of Safety-Related Equipment" Syc list encl JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/22 Consolidated Edison Co. of New York, Inc. 120pp 18997 007 24X Fiche 50-000,83/06/22,8305110477.
- 8305110479 lE Info Notice 83-42, "Reactor Mode Switch Malfunctions," Svc list encl
 JORDAN, E. Division of Emergency Preparedness & Engineering Response (Post 830103) 83706/23 Consolidated Edison Co of New York, Inc 116pp 18996 242 24X Fiche 50-000, 83706/23, 8305110479,
- 8305110483 IE Info Notice 83-43. "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/24 Consolidated Edison Co of New York, Inc 116pp 19046.297 24X Fiche 50-000, 83/06/24, 8305110483

R Periodic operating reports & related correspondence

- 8306100179 Forwards revised Tables RBD-E-03A & RBD-E-03D to 1982 radiological environ monitoring rept. Rev reflects review of rept on unit of measure for air sample.

 JOHNSON, B D Consumers Power Co 83/05/18, KEPFLER, J. © Region 3, Office of Director. ip 14805, 253, 24X Fiche 50-255, 83/05/18, 8306100179
- --830610018; Revised Tables RBD-E-03A & RBD-E-03D for 1982 radiologica) environ monitoring rept. # Consumers Power Co 83/05/18 3pp. 18805: 254. 24X Fiche 50-255,83/05/18,8306100179
- 8304130310 Monthly operating rept for May 1983 W/830408 ltr.
 PETERBON, D A . KENNEDY, D M Consumers Power Co. 83/04/08 NRC No Detailed Affiliation 20ven Spp 18823 323 24X
 Fichs 30-255, 83/04/08, 8304130310
- 8306230287 Corrects statement in environ operating rept for 1982 re use of herbicides Small quantity of herbicides aprayed on site property during 1982 JOHNBON, B D Consumers Power Co 83/06/16 KEPPLER, J Q, Region 3, Uffice of Director ip 18945 164 24X Fiche, 50-255, 83/06/16, 8306820887

8 Reportable occurrences, LERs & related correspondence

- Bii209056i RO on 7308i2.MBIV CV05i0 failed to close following shutdown at cooldown at plant Caused by handening of valve packing. Packing will be removed & components clashed BERELL.R.B Consumers Fower Co 73/08/22 0'LEARY, J.F. Atomic Energy Commission. Directorate of Licensing. ip 65760:206 24X Fiche: 80-255, 73/08/22: Bii209056i.
- 8306070236 LER 83-034/01T-0 on 830516,D safety injection tank T-820 level fell below Tech Spec limit during routine sampling. Caused by delay in fill operations due to feilure of relief valve RV-3161 to reseat within 1 h.W/830831 ltr JOHNBON: 8 D Consumers Power Co 83/05/31 KEPPLER, J C. Region 3, Office of Director 2pp. 18741-157, 24X Fiche SO-255,63/05/31,8306070236
- 8304070248 LER 83-032/03L-0 on 830429, declaration of operability signature found incomplete for maint order on fire barrier penetration Caused by personnel oversight re new maint order closeout procedures. W630531 its UDHN80N: 8 D Consumers Power Co. 83/05/31 KEPPLER, J. 0. Region 3, Office of Director 2pp. 18740-328 24% Fichs. 50-255, 83/05/31, 8306070248.

- 8306070282 LER 83-033/03L-0 on 830428. D safety injection tank T-82D sampling indicated boron concentration below Tech Specifiat Caused by minor leakage past loop check valve & SIT check valve or fill & drain valve W/830531 km JOHNSON, B D Consumers Power Co 83/05/31 KEPPLER, J G Region 3. Office of Director 2pp 18741 212 24X Fiche 50-255, 83/05/31, 8306370582
- B306130394 LER B3-035/03L-0 on B30505, safety injection tank (BIT) C reached Tech Spec limit of 19B inches Caused by minor leakage past loop chack valve & SIT check valve or fill & drain valve Leak rate being monitored W/830603 ltr JOPASON, B D Consumers Power Co B3/06/03 KEPPLER, J G Region 3, Dffice of Director 2pp 18823 016 24X Fiche 50-255, 83/06/03, 8306130394
- 8306220013 LER 83-036/03L-0 on 830515, during normal power operation, safety injection tank (SIT) D level reached Tech Spec limit Caused by minor leakage past loop check valve & SIT check valve or fill & drain valve Leak monitored W/830610 ltr JORNSON, B D Consumers Power Co 83/06/10 KEPPLER, J @ Region 3, Defice of Director 2pp 18927 342 24X Fiche 50-255,83/06/10.
- 830522027 Telecopy RO on 830510, safety injection tank C (T-82C) because imperable due to low level resulting from sampling Caused by lifting of ratiof valve Low level switch cleared KRICH,R M Consumers Power Co. 83/06/13 Region 3, Office of Director 1p 18930 044 24X Fiche 50-255.83/06/13.8306220029
- 8306270063 LER 83-039/01T-0 on 830603, hydrogen recombiners simultaneously loaded to respective MCC for surveillance testing, contrary to standing order Caused by inadequate surveilliance procedure. W/830617 ltr
 JCHMSON, 8 D Consumers Power Co 83/06/13 KEPPLER, J Q Region 3 Diffice of Director 2pp. 18995 219 24X Fiche 50-255, 83/06/13, 8306270063
- 8306220256 LER 83-037/01T-0 on 830601, rack mounted circuit board replaced w/one from stock resulting in total loss of value control during restoration of automatic control of CV-0737A Caused by faulty rack mounted circuit board W/830615 ltr JDHWSON, B D Consumers Power Co B3/06/15 KEPPLER, J O Region 3 Office of Director 3pp 18926 026 24X Fiche 50-255,83/06/15,8306220256
- 8306270432 LER 83-038/01T-O on 830603.W/T-B2C (safety injection tank C) inoperable due to routine evolution & tank T-B2D became inoperable due to low level Caused by leakage past fill & drain valve Valves to be inspected W/B30617 ltr.

 JOHNSON, B D Consumers Power Co 63/06/17 KEPPLER, J. C. Region 3, Office of Director 2pp. 18993 043 24X Fiche 50-255.83/06/17, 8306270432
- 8305270435 LER 83-040/01T-0 on 830507, safety injection tank D sample showed boron concentration below Tech Spec limit of 1,720 ppm Caused by minor leakage past loop check valve Valves will be checked during nest outage W/030520 tr JOHNSON.8 D Consumers Power Co 83/05/20 KEPPLER, J @ Region 3. Office of Director 2pp. 18793 067 24X Fiche 50-255,83/05/20. 8305270435

DOCKET 50-257 JULICH TESTING REACTOR

- G Inspection reports. IE Bullstins & correspondence
- 8305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods
 Withdrewn at BURKs " Svc list enc!
 JCRDAN.E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/05/31 Consolidated Edison Co. of New
 York, Inc 116pp 18732.208. 24X Fiche 50-000,83/05/31,8305110461.
- B304090010 IE Info Notice 83-37, "Transformer Failure Resulting From Degraded Internal Connection Cables" 8vc list and JORDAN, E.L. Division of Emergency Preparadness & Engineering Response (Post 830103). 83/06/13 Consolidated Edison Co of New York, Inc. 243pp 18921 001, 24% Fiche, 50-000, 83/06/13, 8306090010
- R Periodic operating reports & related correspondence
- 83060R0216 Monthly operating repts for Har 1983 W/830415 ltr PAGE:P L., WILLIAMS, J W. Florida Power & Light Co 83/04/15 Office of Resource Management, Director 13pp. 18690: 236 24X Fiche. 50-000. 83/04/15, 8306020216

- DOCKET 50-259 BROWNS FERRY NUCLEAR POWER STATION, UNIT 1

 F Security, medical, emergency & fire protection plans
- 8306140107 Forwards summary of 830315 meeting at Region II ofc re proposed security mods for future const activities at facilities List of attendees encl LEWIS,R C Division of Project & Resident Programs 83/03/25 PARRIS
- 8306270007 Forwards revised physical security plan, reflecting NRC B30412 comments Rev withhold (ref 10CFR73 21) MILLS.L M Tennessee Valley Authority B3/06/03 G'REILLY, J P Region 2, Office of Director ip 18988 153 24X Fiche 50-259,83/06/03,8306270007
- 8306210010 Forwards "Program Plan for Control Room Design Reviews for all TVA Nuclear Plants," in response to Generic Ltr 82~33 re upgrade of emergency plans KAMMER.D S Tennessee Valley Authority, 83/06/09 ADENSAM, C Licensing Branch 4 3pp 18913 001 24X Fiche 50-000,83/06/09,8306210010
- --8306210016 Procedure B62207 10, "Program Plan for Control Room Dosign Reviews for all TVA Nuclear Plants " * Tennessee Valley Authority 83/06/09 200pp 18913 004 24X Fiche 50-000,83/06/09,8306210010
- 8306230201 Notification of 830621 meeting w/util in Bethesde, MD to discuss potential rev to App R submittal based on revised criteria w/respect to analyses on loss of offsite power & availability of other onsite units & condensate pumps CLARK.D Operating Reactors Branch 2 83/06/16 VASSALLO, D. D Operating Reactors Branch 2 19 18754, 357 24X Fiche 50-259, 83/06/16, 8306230201
- B306210194 Ack receipt of B30603 ltr informing NRC of steps taken to correct violations noted in IE Safeguards Insp Repts 50-259/83-10. 50-260/83-10. \$50-294/83-10 CLEWIS.R C Division of Project & Resident Programs B3/06/17 PARRIS.H & Tennessee Valley Authority 1p 18917-030 24X Fiche 50-259,83/06/17,8306210194
- --8306210203 Forwards response to NRC 830429 ltm re violations noted in IE 8afaguards Inap Repts 50-259/83-10,50-260/83-10 & 50-294/83-10 Corrective actions withheld (ref 100FR73,21) MILLS.L M Tennessee Valley Authority 83/06/03 D'REILLY, / P Region 2, Office of Director ip 18919 031 24X Fiche 50-259,83/06/17,8306210194
- --8306210213 Forwards IE Safeguards Insp Repts 50-259/83-10.50-260/83-10 & 50-276/83-10 on 830404-08 & notice of violation Notice of violation withheld (ref 10CFR73 21)

 LEWIS.R C Division of Project & Resident Programs 83/04/27

 PARRIS.H 9 Tennessee Valley Authority. 2pp 18717 032 24X

 Fiche 50-259.83/06/17.8306210194
- --8306210224 IE Safeguards Insp Repts 50-259/83-10, 50-260/83-10 & 50-274/83-10 on 830404-08 Noncompliance noted failure to follow access control procedures Details withheld (ref 10CFR73, 21)
 MORRED E Region 2, Office of Director 83/04/27 ip 18919 034 24X Fiche 50-259, 83/06/17, 8306210194
- P Operating license stage documents & correspondence
- 8304060051 Addl response to FOIA request for three categories of documents re PRA of reactor safety study methodology application program repts & interim reliability evaluation program repts Forwards App A documents Search continuing FELTON. J M Division of Rules and Records 83/04/07 8HOLLY, 8 C Union of Concerned Scientists 3pp 18792 001 24X Fiche 50-000.83/04/07,8306060051
- --8306060061 Statement on background, issues, current status & future action re interim & nati reliability evaluation programs * NRC No Detailed Affiliation Given 82/12/31 2pp. 18752 059 24X Fichs 50-000, 83/04/07, 8306060051
- 8304020180 Forwards safety evaluation re valve operability for 10,18 & 20-inch butterfly valves used for purge or vent of containments. Info submitted fails to demonstrate valve ability to close against pressure buildup during LOCA VASSALLD, D. B. Operating Reactors Branch 2 83/05/19 PARRIS, H. Q. Tennessee Valley Authority 3pp 18701 113 24% Fichs 50-259,83/05/19,8306/020180

- --8306020187 Safety evaluation re valve operability for 10.18 & 20-inch butterfly valves used for purge or vent of containments Info submitted fails to demonstrate valve ability to close against pressure buildup during LUCA # Office of Nuclear Reactor Regulation, Director 83/05/19 App 18701 116 24X Fiche 50-259.83/05/19.8306020180
- 8306150260 Forwards "Control of Heavy Loads (C-10), TVA, Browns Ferry Nuclear Power Station, Units 1, 2 & 3, " draft technical evaluation rept Conference call requested within 4 to 5 wks to discuss review results VASSALLO, D B Operating Reactors Branch 2 83/05/26 PARRIS, H Q Tennesce Valley Authority 2pp 18867 322 24X Fiche 50-259,83/05/26,8306150260
- --8306150266 "Control of Heavy Loads (C-10),TVA,Browns Ferry Nuclear Power Station,Units 1.2 & 3." draft technical evaluation rept BOMBERGER,C, AHMED,N, SARGENT,IH Franklin Institute/Franklin Research Center NRC-02-81-130 TER-C5506-337/338/33 83/04/05. CLEMENBON,F NRC - Na Detailed Affiliation Given 25pp 18849 324 24X Fiche 50-259,83/05/26,8306150260
- --8306150272 "Synopsis of Issues Associated w/NUREG-0612 "
 # Operating Reactors Branch 2 83/05/26 | 11pp 18849 349 24X
 Fiche 50-259,83/05/26,8306150260
- 8306150243 Suppl 6 to 820914 application for amend to Licenses DPR-33, DPR-52 & DPR-68, changing Tech Specs 3 10 C & 4 10 C re min depth of water required over single irradiated fuel assemblies during handling MILLS,L M Tennesses Valley Authority 83/06/03 DENTON,H R Office of Nuclear Reactor Regulation, Director 2pp 18846 127 24X Fiche 50-259,63/06/03.8306150243
- --8306150248 Proposed changes to Tech Specs 3 10.C & 4 10 C re min depth of water required over single irradiated fuel assemblies during handling * Tennessee Valley Authority 83/06/03 10pp 18846 129 24X Fiche 50-259,83/06/03,8306150243,
- 8306140656 Forwards response to 830517 request for info re 8ER, Section 4 O, on containment purge & vent valves Operability of valves justified under LOCA conditions MILLS,L M Tennessee Valley Authority 83/06/07 DENTON,H R Office of Nuclear Reactor Regulation, Director 7pp 18834 ODE 24X Fiche.50-259,83/06/07,8306140656
- 8306160507 Application for emergency amend to Licenses DPR-33,DPR-52 & DPR-48, changing Tech Spec standby gas treatment sys required surveillance interval to once per operating cycle MILLS,L M Tennessee Valley Authority 83/06/13 DENTON.H R Office of Nuclear Reactor Regulation, Director 2pp 18864 157 24X Fiche 50-289,83/06/13,8306160507.
- --8306160523 Proposed Tech Specs changing standby gas treatment sys required surveillance interval to once per operating cycle Justification for emergency nature of proposed Tech Spec change encl
 - change encl * Tennesses Valley Authority 83/06/13. 5pp. 19864 159 24X Fichs 50-259,83/06/13.8306160507
- 8306210014 Confirms agreement w/NRC re interpretation of Tech Spec 4 7 8 3 a requirements Spec satisfied by commitment to actuate annually standby gas treatment blowers in primary containment isolation sys logic. Tech Spec 169 ne peded MILLS.L M Tennesses Valley Authority. 83/06/16. DENTON, H R Office of Nuclear Reactor Regulation. Director 2pp 18911 387 24X Fiche 50-259, 83/06/16, 8306210014
- 8306290400 Application to amend Licenses DPR-32 DPR-52 & DPR-68, changing Tech Specs to require annual rept of main steam safety/relief valve actuations, in response to NUREO-0737, Itam II K 3 3 & Generic Ltr 83 02 MILLS, L M Tennesses Vallay Authority 83/06/20 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 2pp 19033 133 24X Fiche. 50-259, 83/06/20, 8306490400
- --830627040B Proposed Tech Spec revs.requiring annual rept of main/steam safety/relief valve actuations in response to NUHEO-0737, Itum II K 3 3 & Generic Ltr 83-02 * Tennessee Valley Authority 83/06/20 5pp. 17053 135 24X Fiche 50-259,83/06/20,8306270400.
- 8306240354 Notification of B30629 meeting w/util in Bethesde.MD to discuss util analysis on intervening combustibles & separation of circuits CLARK.D. Operating Reactors Branch 2 83/06/22 VASSALLO.D B Operating Reactors Branch 2 2pp. 18799.157 24X Fiche 50-259.83/06/22.8306240354

- 8306280415 Supple 821220 response to NUREQ-0313 request for addl info Ferrite content of cast austenitic stainless steel ranges from 15 to 20% Valves highly resistant to intergranular stress corrustion cracking MILLS.L M Tennesses Valley Authority 83/06/22 DENTON, H R, Office of Nuclear Reactor Regulation, Director 2pp 19018 351 24X Fiche 50-259, 83/06/22:8306280415
- 8306280567 Advises that GE equipment items discussed in 830520 ltr reenviron qualification reclassified as nonproprietary.
 MILLS,L M Tennessee Valley Authority 83/06/23 DENTON.H R
 Office of Nuclear Reactor Regulation, Director 1p. 19018 028, 24:
 Fiche 50-259,83/06/23,8306280567
- 8306300177 Discusses continuing problem re extreme length of time required for approval & resulting backlog of pending requests for Tech Spec changes Majority of changes administrative & require minimal review time MILLS, L M Tennesses Valley Authority. 83/06/27 DENTON, H R. Office of Nuclear Reactor Regulation. Director. 3pp 19122 044. 24X Fiche 50-259, 83/06/27, 8306300177
- 8306280080 LOBS OF DHR BEQUENCES AT BROWNS FERRY UNIT ONE ACCIDENT SEQUENCE ANALYSIS CODK, D H., GREENE, S R., HARRINGTON, R M. Oak Ridge National Laboratory FIN 18-0432 NUREG/CR-2973 83/06/30 Division of Accident Evaluation 180pp 19068 295 24X Fiche 50-259, 83/06/30, 83062800080
- G Inspection reports: 1E Bulletins & correspondence
- 8306290218 Forwards IE Insp Repts 50-257/83-03, 50-260/83-03 & 50-276/83-03 on 830110-14 & notice of violation LEWIB.R C Division of Project & Resident Programs 83/03/21 PARRIS, H.O. Tennessee Valley Authority 2pp 17056 135. 24X Fiche 50-259, 83/03/21, 8306290218
- --8306290224 Notice of violation from insp on 830110-14 * Region 2, Office of Director 83/03/21 9pp 19056 137 24) Fiche 50-259,83/03/21,8306290218
- --8306270728 IE Insp Repts 50-259/83-03,50-260/83-03 & 50-294/83-03 on 830110-14 Noncompliance noted failure to perform evaluation of radiation hazards to personnel & employee failure to wear gloves in contaminated zone DEBS B T , BARR, K P. Region 2, Office of Director 83/03/03 9pp 19056 139, 24% Fiche 50-259,83/03/21,8306290218
- 8306140543 Confirms mgt meeting on 830421 in Chattanooge, TN to review results of first phase of annual appraisal of regulatory performance, per 830328 telcon
 LEWIS.R C Division of Project & Resident Programs 83/04/12
 PARRIS.H G. Tennessee Valley Authority, 3pp. 18834:176. 24X
 Fiche 30-000,83/04/12,8306140543.
- 8304140422 Confirms B30501 mgt mesting at sits to discuss mgt controls for refueling operations, per B30519 telcon
 LEWIS, R. C. Division of Project & Resident Programs B3/05/23
 PARRIA, H. G. Tennesses Valley Authority 3pp 18838, 049 24X
 Fiche 50-259, 83/05/23, 8304140422
- 8306140685 Forwards IE Insp Repts 50-259/83-17, 50-260/83-17 & 50-276/83-17 on 830509-12 No noncompliance noted VERRELLI,D M Division of Project & Resident Programs 83/05/25, PARRIS,H G Tennessee Valley Authority 2pp 18841 336 24% Fiche 50-259,83/05/25,8306140685.
- --8306140492 IE Insp Repts 50-269/83-17,50-260/83-17 & 50-296/83-17 on 830509-12 No noncompliance noted Major areas inspected followup on IE Bulletin 80-11: "Masonry Wall Design." LENAMAN,J J, CONLON.T E Region 2: Office of Director, 83/05/25, 5pp. 18841 338 24X Fichs 50-259,83/05/25,8306140685
- 8305110458 IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in Well Logging Device" Syc list encl. TAYLOR, J. M Division of Safeguards & Inspection Programs (Post 830103) 83/05/26 Contalidated Edison Co of New York, Inc 125pp. 18831 043, 24X Fiche 50-000,83/05/26,8305110458.
- 8305110460 IE Info Notice 83-34, "Event Notification Info Workshept."
 Svc list encl.
 JORDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/05/26 Consolidated Edison Co of New
 York, Inc. 115pp 18732 085 24X Fichs 80-000,83/05/26,8305110460
- 8306150625 Requests approval for M Toker to visit site on 830613 in order to observe exam of fuel removed from reactors. Specific info for discussion listed. VASSALLO.D.B Operating Reactors Dranch 2 83/05/27. PARRIS.H Q Tennessee Valley Authority 3pp 18867-285 24X Fiche 50-299.83/05/27.8306150625

- 5110461 IE Info Notice 83-35. "Fuel Movement H/Control Rods ithdrawn at BMRs " Svc list ent! DRDAN.E.L. Division of Emergency Preparedness & Engineering esponsy (Post 830103). 83/05/31 Consolidated Edison Co. of New ork, Inc. 116pp 1873R: 208. 24x Fiche 50-000,83/05/31,8305110461.
- 6140251 Ack receipt of 830525 itr informing NRC of steps taken to arrect violations noted in IE Insp Repts 50-259/83-09, 0-260/83-09 & 50-276/83-09.

 6240783-09 & 50-276/83-09.

 6240783-09 & 50-276/83-09.

 6240783-09 & 50-276/83-09.

 6250783-09 & 50-276/83-09.

 6250783-09 & 50-276/83-09.

 6250783-09 & 63-06/90 & 63-06
- 306140266 Responds to NRC 830418 itr re violations noted in IE Insp. Repts 50-289/83-09. 50-260/83-09 & 50-296/83-09 Corrective actions all conduit supports for safety-related equipment corrected by work plan or maint request.

 KAHHER.D 8 Tempessee Valley Authority 83/05/25. 0'REILLY.J P. Region 2. 0ffice of Director 6pp. 18892 837 24X

 Fiche: 50-289.83/06/02.8306140281
- 306140276 Furwards IS Insp Repts 50-259/83-09.50-260/83-09 to 50-296/83-09 on 830826-0325 to notice of violation LEWIB.R C. Division of Project to Resident Programs 83/04. PARRIB.R Q Tennessee Valley Authority, 2pp 18832 243 Fiche: 50-259.83/06/02.8306.140251
- 106140284 Notice of Violetion from insp on 830226~0325. * Region 2: Office of Director 83/04/18 2pp 181 Fiche. 80-259, 83/06/02, 8306140251. 18832 245 P4X
- O6140297 IE Insp Repts 50-259/83-09, 50-260/83-09 & 50-296/83-09 on 830226-0325. Noncompliance nated failure to meet design flow requirements & failure to have QA review & insp on maint requests PAULK, O. L. Region 2. Office of Director. CANTRELL, F. 8 Division requests
 PAULK, O.L. Region 2, Office of Director, CANTRELL, F. 8 Div.
 of Project & Resident Programs, 83/04/13 14pp 18832, 247,
 Fiche, 50-259, 83/04/02, 8306140251

- 10464 IC Info Notice 83-36, "Impact of Bacurity Practices on Safe Tations." Eve list enel "DANE L. Division of Emergency Preparedness & Engineering ponce (Post 830103). 83/06/09. Consolidated Edison Co. of New k. Inc 119pp. 18830: 280 24X Fiche 50-000.83/06/09.8305110464
- 90199 Ack receipt of 830425 ltr informing NRC of steps taken to rect violations noted in IE Insp Repts 50-259/83-03, 260/03-03 k 80-294/83-03.

 260/03-03 k 80-294/83-03.

 IS.R.C. Division of Project & Resident Programs. 83/06/09.

 RIS.H.C. Tennesses Valley Authority. 1p. 19056: 221. 24X he: 50-259, 93/06/09, 8306290195.
- 6290203 Forwards response to NRC 820321 1tr ry violations noted in E Insp Repts 50-259/83-03, 80-260/83-03 & 50-296/83-03 lolation re Pallure to perform rediction haterds evaluation smiled. Personnel counseled on radiological control MMER. D 9. Tennessee Valley Authority 83/04/25 Q'REILLY, J. Pagion 2. Office of Director. Spp 19056. 222, 24X iche: 50-259, 83/04/09, 8306490198.
- 10470 IE Info Notice 80-38, "Defective Heat Sink Adhesive & Inically Induced Chatter in Relays Within Printed ult Cards," By: list encl.

 AMN.E.L. Division of Emergency Preparedness & Engineering of the Property Preparedness of Engineering of New Inc. 118pp 18920:225 24X Fiche; 50-000,80/06/13,8305110470
- ODIO IE Info Notice B3-37, "Transformer Failure Resulting From aded Internal Connection Cables" Svc list encl.
 ANIE L. Division of Emergency Preparedness & Engineering onns (Fost 830103). 83/06/13 Consolidate Edison Co. of New Inc. 243pp. 18921:001. 24x Fiche 50-000,83/06/13,8306090010.
- 0277 Ack receipt of 830323 ltr informing NRC of steps taken to ect violations notes in IE Ines Repts 50-259/83-12, 40/83-12 & 50-296/83-12.

 B.R.G. Division of Project & Resident Programs 83/06/14.

 IS.H.G. Tennesse Valley Authority. ip. 19056:038 24% e: 50-259,83/06/14,8306290277

- --8306290283 Responds to NRC 830422 ltr re violations noted in IF Insp Repts 50-259/83-j2.50-260/83-I2 & 50-296/83-I2 Corrective actions radiological incident repts issued for each instance cived MILLS.L M Tennessee Valley Authority 83/05/23 Region 2, Office of Director 5pp 19056 039 24X Fiche 50-259,83/06/14.8306290277 B'RCILLY, J P
- --8306270288 Forwards IE Insp Repts 50-259/83-12.50-260/83-12 & 50-276/83-12 on 830321-25 & notice of violation LEWIS.R C Division of Project & Resident Programs 83/04/PARRIS.H G Tennessee Valley Authority 2pp 17056 044 Fiche 50-259.83/06/14.8306270277
- --8306290292 Notice of violation from insp on 830321-25
 * Region 2, Office of Director 83/04/22 2pp 19056 046
 Fiche 50-259,83/06/14,8306290277
- --8306290297 IE Insp Repts 50-269/83-12.50-260/83-12 & 50-294/83-12 on 830321-25 Noncompliance noted radioactive wasts operator inside contamination zone w/o protective clothing or Testiation monitors

 DEBS. D T , BARR.K P Region 2, Defice of Director 6

 App 19056 048 24% Fiche 50-289, 83/06/14.830629027 83/04/20
- 8305290250 Forwards response to IE Bulletin 83-03 re check valve failures in raw water cooling sys of diesel generators. Current test program sufficient to verify integrity of check valves

 MILLS,L N Tennessee Velley Authority 93/06/15 O'REILLY, J P
 Region 2, Office of Director Opp 19056 081 24X

 Fiche 50-259,83/06/15,8306290250
- 8306270272 Ack receipt of supplemental 830610 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 80-259/61-28,50-260/81-28 & 50-296/61-20 LEWIG.R C Division of Project & Resident Programs, 83/06/16 PARRIS.H 0 Tennessee Valley Authority ip, 19056-054 P4X Fiche 50-259,83/06/16.8306290272
- ~*8306290275 Supplemental response to NRC Bil031 lt; re violations noted in IE Insp Repts 50-259/81-28, 50-260/81-28 & 50-296/81-29 Corrective actions five pump air vent valves removed & replaced w/stronger & improved upper float guides MILLS,L M Tennessee Valley Authority B3/06/10 O'REILLY,J P Region 2, OPfice of Director 39 19056,055 24X Fiche:50-259,83/06/16,8306290272
- 8304210194 Ack receipt of 830403 ltr informing NRC of steps taken to correct violations noted in IE Safeguards Insp Repts 50-259/83-10, 50-240/83-10 t 50-276/83-10.

 LEWIS, R C Division of Project & Resident Programs 83/06/17 PARRIS H G Tennessee Valley Authority ip. 18919 030 24% Fiche 50-259,83/06/17,8306210194
- --8306210203 Forwards response to NRC 830429 ltr re violations noted in IE Safeguards Inap Repts 50-259/83-10.50-260/83-10 & 50-276/83-10 Corrective actions withheld (ref 100FR73.21) HILLS.L M Tennessee Valley Authority 83/06/03 O'REILLY, J P Region 2. Dffice of Director. ip 18919 031 24X Fiche 50-259.83/06/17,83062)0194
- --8306210213 Forwards IE Safeguards Insp Repts 50-259/83-10.50-260/83-10 & 50-276/83-10 on 830404-08 & notice of violation Notice of violation withheld (ref 100FR73 21)
 LEMIS.R C. Division of Project & Resident Programs 83/04/29
 PARRIS.H 9. Tennesses Valley Authority 2pp 18719 032 24X
 Fichs 50-259-83/06/17,8306210194
- --8306210224 IE Safeguards Insp Repts 50-259/83-10,80-260/83-10 & 30-296/83-10 on 830404-08 Noncompliance noted failure to follow access control procedures Details withheld (ref 10CFR73 21) MODRE, D. E. , NCGUIRE, D. R. Region 2, Office of Director 83/04/27 1p 18919 034, 24% Fichs 50-259,83/06/17,8306210194
- 8306290483 Approves issuance of BALP Repts 50-259/83-04, 50-260/83-04, 50-296/83-04, 50-328/83-04, 50-328/83-04, 50-390/83-07, 50-391/83-06, 50-438/83-06 & 50-439/83 Od for Jul 1981 Dec 1982.No reply required
 0'REILLY, J P. Region 2, Office of Director 83/06/17, PARRIS, H Q.
 Tennessee Valley Authority 3pp 19050.212 24X
 Fiche.50-000,83/06/17,8306290483.
- -8306290490 Forwards SALP Repts 50-259/83-04,50-260/83-04, 50-296/83-04,50-327/83-04,50-328/83-04,50-390/83-07, 50-391/83-06,50-438/83-06 & 50-439/83-06 for Jul 1981 Dec LEMIS, R C. Division of Project & Resident Programs. 83/04/13 PARRIB, H G. Tennessee Valley Authority. Spp. 19050 215 249 Fiche 50-000,83/06/17,8306290483.

- --8306290503 SALP Repts 50-259/03-04.50-260/03-04.50-29/63-04. 50-327/03-04.50-328/03-04.50-390/03 07.50-391/03-06. 50-438/03-06 & 50-439/03-06 for Jul 1901 - Det 1902 * Region 2. Office of Director 83/04/13 92pp 19050 210 240 Fiche 50-000.03/06/17.030629040
- --8306290510 Cumment; on SALP Repts 50-259/83-04, 50-260/83-04, 50-294/83-04, 50-327/83-04, 50-328/83-04, 50-390/83 07, 50-391/83-06, 50-438/83-04 & 50-439/83-06 for Jul 1981 Dec 1982 MILLS.L M Tennessee Valley Authority 83/05/10 O'REILLY, Region 2. Office of Director 20p 19050 310 24X Fichs 50-259, 83/06/17, 8306290483
- 83051104/5 IE Info Notice 83-40, "Need to Environmentally Qualify
 Epoxy Grouts & Sealers " Svc list encl
 JORDAN.E | Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/06/22 Consolidated Edison Co of New
 York, Inc 115pp 17021 179 24X Fiche 50-000.83/06/22.8305110475
- 8305110477 IE Info Notice B3-41, "Actuation of Fire Suppression Sys Causing Inoperability of Bafety-Related Equipment" Syc list enc! JORDAN, E. L. Division of Emergency Preparedness & Engineering
 - JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 8301031 83/06/22 Consolidated Edison Co. of New York, Inc. 120pp 18997 007 24X Fichs 50-000.83/06/22,8305110477
- 8305110479 IE Info Natice 83-42, "Reactor Mode Switch Malfunctions" Svc list encl JORDAN.C L Division of Lamergency Preparedness & Engineering Response (Post 830103) 83/06/23 Consolidated Edison Ca of New York, Inc 116pp 18996 242 24X Fiche 50-000 83/06/23 8305110479
- 8305110483 IE Info Notice 83-43, "Improper Sottings of Intermediate Range (IR) High flux Trip Betpoints " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/24 Consolidated Edison Co of New York, Inc 116pp 19046 297 24X Fiche 50-000.83/06/24.8305110483
- R Periodic operating reports & related correspondance
- 8306160482 Monthly operating ropts for Apr 1983 W/830511 ltr THOM,T . COFFEY.J A Tennessee Valley Authority 83/05/01 Office of Management and Program Analysis 39pp 18864 085 24X Fiche 50-259, 83/05/01.8306160482
- B Reportable occurrences, LERs & related correspondence
- 830&0102&9 Deficiency rept re inability of prompt notification sysmobile sirens to complete routes in required time Initially reported on 830809 Addl sirens will be procured & mobile routes modified full compliance expected by 830901 MILLS.L.M. Tennessee Valley Authority 183/05/23 O'REILLY, J.P. Region 2. Office of Director 2pp 106/4 324 24X Fiche 50-259,03/05/23,830&0102&9
- 8304070072 LER 83-023/017-0 on 830513, while performing inep per IE Bulletin 83-02; crack-like indications detected & confirmed by ultrasonic inep in weld KR-1-37 Cause not stated Weld will be repaired tofore startup H/B305:25 ltr HOLDER, E T , GREEN, H J Tennessee Valley Authority 83/05/25 G/REILLY, J P. Ragion 2, Office of Director 3pp 18739 195 PAX Fiche 50-259,83/05/25,63060/0072
- 8306070087 LER 83-024/01T-0 on E30517.design review of diesel generator room ventilation indicated sys may not keep electrical components below design max temp limits Dissipated heat loads underestimated Ducting being installed W/305027 ltr ELY.J O. GREEN.H J Tennesse Valley Authority 83/05/27 G'REELLY.J P. Region 2. Office of Director 3pp 18/3/ 247 24X Fichs 50-257.83/05/27.830607008/
- 8306070241 LER 83-022/03L-0 on B30429, downstream HEPA filters in standby gas treatment sys trains A & B exceeded Tech Spec 18-month test frequency Caused by presume) error Procedure 81 4 7 B-4 review rescheduled, ELY.J O . CREEN.H J Tennessee Valley Authority 83/05/27 O'REILLY.J P Region 2. Office of Director 3pp 18746-044 24% Fiche 50-259, 83/05/27, 8306078/41
- 8306070157 LER B3-025/03L-0 on B30502, standby gas treatment mys circuitry switch 1-Pd18-64-15 found set above max Tech Spec limit Caused by incorrect switch setting Setpoint corrected Caution tags placed on panel W/B30601 Jtr BASS, & W. GRIEN, H. J. Tennesser Valley Authority B3/06/01 D'REILLY, J. P. Region 2. Office of Director 3pp 18807 202 PAX Fiche 50-259,83/06/01.8306070157

- 8306070043 PNO-II-83-044 util amounced scheduling of enforcement conference w/NRC for 830601 to discuss officeding of 130 fuel bundles into high density Puel rack not verified for borat content BUTCHER, R.C., CANTRELL, F.S. Region 2, Office of Director 83/06/0R 2pp 18739 361 24% Fiche 50-259,83/06/02,8306070043
- 8306210270 Updated LER 82-053/01X-1 on 820730, secondary containment integrity could not be confirmed Caused by displaced relief panel allowing Isablage from turbine bldg into containment Panel replaced & leakage paths sealed W/830615 ltr WILLIAMSON, B. GRIERNH J. Tennessee Valley Authority. 83/06/15, 07REILLY, J. P. Region 2, Office of Director 4pp 18915 037 24) Fiche 50-259, 83/06/15, 8306210270
- 8306300139 LER 80-027/03L-0 on 830526, discovered that Surveillance Instruction 4 B 3 4-3 for reactor bldg vent monitoring system to the performed within required interval Caused by personnel error Calibr performed W/830621 ltm CAMPUELL.0 D. GREEN.H J Tennesse Valley Authority, 83/06/21 GREELLY.J P. Region 2. Office of Director 3pp 19122 317 24X Fiche 50-259,03/06/21.8306300139
- 8306300208 LER 83-026/03L-0 on 830525, containment atmosphere dilution tank B lovel transmitter LT-84-13A indicated above Tech Spec limit Caused by transmitter zero drift Transmitter recalibr W/830622 ltr [RBY, B J , ORREN. H J Tennessee Valley Authority 83/06/22 G 'REILLY, J P Region 2, Office of Director 3pp 19122 118 24X Fichs 50-259, 83/06/22, 8306300208
- 8305300066 Updated LER B3-009/01X-0 on 800823 design review of emergency diesel generator engine coalers showed coalers may not be able to maintain cooling water below hot setpoint Caused by design error Setpoint raised W/830623 ltr ELY, J D. GREEN, H J Tennessee Valley Authority 83/06/23 D'REILLY, J P. Region 2, Office of Director. 3pp 19120 269 24X Fiche 50-259, 83/06/23, 8306300066
- V Operator Examinations
- 830614068/ Discusses operator & senior operator licensing exams & schedule to facilitate written & oral exams to be administered during wk of 830627 Approved ref matl listed in snci requested by 830427 VERRELLI, D M Division of Project & Resident Programs. 83/03/80, OREEN, H J Tennessee Valley Authority 3pp. 18041 346 24X Fiche 50-259, 83/03/30, 830614068/
- 8306140626 Responds to 830330 request for renewal of OT McChristian Senior Operator License SCP-2938-2 License expired McChristian should reapply for license NRC will consider request for waiver of exams VERRELLI,D M Division of Project & Resident Programs 83/05/12 OREEN,H J Tennessee Valley Authority 1p 18842 086 R4X Fiche 50-259, 83/05/12,8306140676
- X Onsite Storage of Low Level Waste
- 8306060102 Responds to 830422 ltr re determination of free for low level radwasts amend applications fee determination acceptable MILLS,L H Tennesses Valley Authority 63/06/01 MILLER, W O License fee Management Branch ip 18/19/359 24X Fiche 80-000.63/06/01.8306060102
- DOCKET 50-240 BROWNS FERRY NUCLEAR POWER STATION, UNIT 2 F Security, medical, emergency & firs protection plans
- 8306i40107 Forwards summary of 830315 meeting at Region II oft re proposed security mods for future const activities at facilities List of attendees end LEHIBLE C Division of Project & Resident Programs. 63/03/25 PARRIS
- 8306270007 Forwards revised physical security plan, reflecting NRC 830412 comments Rev withheld (ref 10CFR73 21) HILLS,L H Tennesses Valley Authority 83/06/03, 0'REILLY, J. P. Region P. Office of Director ip 18988 153, 24X Fiche 50-259,83/06/03,8306270007
- 8306210010 Forwards "Program Plan for Control Room Design Reviews for all TVA Nuclear Plants." in response to Generic Ltr 82-33 re upgrade of emergency plans
 KAMMCR.D 8 Tennessee Valley Authority 83/06/09 ADENSAM.E
 Licensing Branch 4 3pp 18913 001. 24X Fiche 50-000.83/06/09,
 8306210010

- --8306210016 Procedure B62207 10, "Program Plan for Control Room Design Reviews for all TVA Nuclear Plants " # Tennessee Valley Authority 83/06/09 200pp 18913 004 24X Fiche: 50-000.83/06/09.8306210010
- 8306230201 Notification of 830621 meeting w/util in Bethesda. MD to discuss potential rev to App R submittal based on revised criteria w/respect to analyses on loss of offsite gower & availability of other onsite units & condensate pumps CLARK. D Operating Reactors Branch 2 83/06/16 VASSALLO, D B Operating Reactors Branch 2 83/06/16 VASSALLO, D B Fiche: 50-259, 83/06/16, 8306230201
- 3306210194 Ack receipt of 830603 ltr informing NRC of steps taken to correct violations noted in IE Safeguards Insp Repts 50-259/83-10, 50-260/83-10 & 50-296/83-10.
 LEWIS.R C Division of Project & Resident Programs. 83/06/17 PARRIS.H G Tennessee Valley Authority ip 18919 030 24X Fiche: 50-259, 83/06/17, 8306210194
- --8306210203 Forwards response to NRC 830427 ltr re violations noted in IE 8afeguards Insp Repts 50-259/83-10.50-260/83-10 & 50-296/83-10 Corrective actions withheld (ref 100FR73 21) MILLS, L M Tennessee Valley Authority. 83/06/03 O'REILLY, J P Region 2, Office of Director 1p. 18919 031 24X Fiche 50-259.83/06/17.8306210194
- -8306210213 Forwards IE Bafeguards Insp Repts 50-259/83-10,50-260/83-10 & 50-296/83-10 on B30404-08 & notice of violation Notice of violation withheld (ref 10CFR/3 21) LEWIS.R C. Division of Project & Resident Programs 63/04/29 PARRIE.H O. Tennessee Valley Authority 2pp. 18717 032 24X Fiche:50-259,83/06/17,8306210194
- -8306210224 IE Bafeguards Insp Repts 50-259/83-10,50-260/83-10 & 30-276/83-10 on 830404-08 Moncompliance noted: failure to follow access control procedures Details withheld (ref 10CFR73.21)
 MODRE, D E. Region 2, Office of Director 83/04/27 ip 18919 034, 24% Fiche 50-299,63/06/17,8306210194
- . Operating license stage documents & correspondence
- 306020180 Forwards safety evaluation re valve operability for 10,18 & 20-inch butterfly valves used for purge or vent of containments Info submitted fails to demonstrate valve ability to close against pressure buildup during LOCA VASSALLO,D.B. Operating Reactors Branch 2 83/05/19 PARRIB,H 0 Tennesse Valley Authority 3pp 18701 113 24X
- -8306020187 Safety evaluation re valve operability for 10,18 & 20-inch butterfly valves used for purge or vent of containments Info submitted fails to demonstrate valve ability to close against pressure buildup during LUCA # Office of Nuclear Reactor Regulation, Director 83/05/19, App 18701; (16. 24X Fiche: 50-259, 83/05/19, 8306020180
- 304150240 Forwards "Control of Heavy Loads (C-10), TVA, Browns Ferry Nuclear Power Station.Units 1,2 & 3," draft technical evaluation rept Conference cell requested within 4 to 5 wits to discuss review results VASSALLO, D B Operating Reactors Branch 2 63/05/26 PARRIB, H G. Tennesses Valley Authority 2pp. 18849:322 24X Fiche, 50-259, 83/05/26, 8304150240
- 8306150266 "Control of Heavy Loads (C-10), TVA, Browns Ferry Nuclear Power Station, Units 1:2 & 3." draft technical evaluation rept.

 BOMBERGER, C., ALMED, N., BARGENT, I.H. Franklin Institute/Franklin Research Center NRC-03-81-130, TER-05306-337-338/33 83/04/05 CLEMENSON, F. NRC No Detailed Affiliation Given 25pp 18849:324 24X Fichs 30-259, 83/03/26, 8306150260
- ObidO453 Application for amend to Licenses DPR-52 & DPR-68, changing Tech Specs to allow operation w/increased core flow MILLS, L. M. Tennessee Valley Authority 83/06/02. DENTON, H. R. Office of Muclear Resctor Regulation, Director 2pp 18863-312. 24X Fichs: 50-260, 83/06/02, 8306160453
- 8306160456 Proposed Tach Spec changes allowing operation w/increased core flow # Tennessee Valley Authority. 83/06/02 14pp 18865-314 24% Fiche: 50~260,83/06/02,8306160453.
- O6150243 Suppl & to 820914 application for amend to Licenses DPR-33. DPR-52 & DPR-68, changing Tech Specs 3.10.0 & 4.10 C re ain depth of water required over single irradiated fuel assemblies during handling.
 MILLS,L.M. Tennessee Valley Authority. 83/06/03 DENTON.H R Office of Nuclear Reactor Regulation. Director 2pp. 18846.127 24X Fiche: 50-259, 83/06/03, 8306150243

- --8306150248 Proposed changes to Trch Specs 3 10 C & 4 10 C re min depth of water required over single irradiated fuel assemblies during handling # Tennessee Valley Authority 83/06/03 10pp 18846 129 24X fiche 50-259.83/06/03.8306150243
- 830.6140.656 Forwards response to 830.519 request for info re BLR, Section 4 0, on containment purge & vent valves Operability of valves justified under LDCA conditions
 MLLG,L M Tennessee Valley Authority 83/06/07 DENTON,H R Office of Nuclear Reactor Regulation, Director 7pp 18834 008 24% Fiche: 50-259,83/06/07,8306140696
- 8306160507 Application for emergency amend to Licenses DPR-33, DPR-52 & DPR-6B, changing Tech Spec standby gas treatment sys required surveillance interval to once per operating cycle MILLS, L M Tennessee Valley Authority 83/06/13 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 18864 157 24X Fiche. 50-259, 83/06/13, 8306160507
- --8306160523 Proposed Tech Specs changing standby gas treatment sysrequired surveillance interval to once per operating cycle Justification for emergency nature of proposed frech Spec change encl # Tennessee Valley Authority 83/06/13 5pp 18864 159 24X Fiche 50-259,83/06/13,8306160507
- 8306210014 Confirms agreement w/NRC re interpretation of Tech Spec 4 7 B.3 a requirements Spec satisfied by commitment to actuate annually standby gas treatment blowers in primary containment isolation sys logic Tech Spec 189 needed MILLS, L.M. Tennessee Valley Authorsty 83/06/16 DENTON, H.R. Defice of Nuclear Reactor Regulation. Director 2pp 18911 357 24X Fiche 50-259, 83/06/16, 8306210014
- 830A270400 Application to amend Licenses DPR-33, DPR-52 & DPR-AB, changing Tech Specs to require annual rept of main steam safety/relief valve actuations, in response to NUREG-0737, Item II K 3 3 & Generic Lt 83-02 MILLS, L H Tennessee Valley Authority 83/06/20 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 19053 133 24X Fiche 50-259,83/06/20,8306270400.
- --8306290408 Proposed Tech Spec revs, requiring annual rept of main/steam safety/relief valve actuations, in response to NUREG-0737, Item II K. 3 3 & Generic Ltr 83-02 W Tennessee Valley Authority 83/06/20 Spp 19053 135 24X Fiche 50-259,83/06/20,8306290400
- 8306240354 Notification of 830629 meeting w/util in Bethesda.MD to discuss util analysis on intervening combustibles & separation of circuits CLARK.D Operating Reactors Branch 2 09/06/22 VASSALLO, D B Operating Reactors Branch 2. 29p 18999 157 24X Fichs 50-259,83/06/22,8306240354
- 8306280415 Supple 821220 response to NUREC-0313 request for add1 info Ferrite content of cast austenitic stainless steel ranges from 15 to 20% Valves highly resistant to intergranular strass corrosion cracking. MILLS.L M Tennessee Valley Authority 83/04/22 DENTON.H R Office of Nuclear Reactor Regulation. Director. 2pp 19018 351 24% Fiche 50-259,83/04/22.8306280415
- 8306280567 Advises that QE equipment items discussed in 830520 ltr re environ qualification reclassified as nonproprietary MILLS,L M Tennessee Valley Authority 83/06/23 DENTON,H R Office of Nuclear Reactor Regulation, Director ip 17018 028 24X Fiche 50-259,83/06/23,8306280567
- 8306300177 Discusses continuing problem releatment length of time required for approval & resulting backlog of pending requests for Tech Spec changes, Majority of changes administrative & require minimal review time MILLS.L. M. Tonnessee Valley Authority 83/06/27 DENTON, M. R. Office of Nuclear Reactor Regulation, Director 3pp 19122-044 24X Fiche 50-259.63/06/27,8306300177
- O Inspection reports. IE Bulletins & correspondence
- 8306290218 Forwards IE Ensp Repts 50-259/83-03,50-260/83-03 & 50-276/83-03 on 830110-14 & notice of violation LEWIS,R C Division of Project & Resident Programs 83/03/21 PARRIEN # Tennessee Valley Authority 2pp 19056 135 24X Fiche 50-259,83/03/21,8306290218
- --8306270224 Notice of violation from insp on 830110~14 * Region 2. Office of Director 83/03/21 9pp 19056-137 24X Fichs: 50-259.83/03/21.8306290216

- --8306290228 IE Insp Repts 50-259/83-03.50-260/83-03 & 50-296/83-03 on 1062/0222 It is nept to the solution of all or to perform evaluation of radiation hazards to personnel & employee failure to wear gloves in contaminated zone DEBS.B T. GARR, K.P. Region 2. Office of Director 83/03/03/9pp 19056 139 24X Fiche 50~259,83/03/21,8306290218 83/03/03
- 8306140543 Confirms mgt meeting on B30421 in Chattanogga.TN to review results of first phase of annual appraisal of regulatory performance.per B30328 telcon LEHIS.R C Division of Project & Resident Programs 63/04/12 PARRIB.H O Tennessee Valley Authority 3pp 19834 176 24X Fiche 50-000.63/04/12.8306140543
- 8306140041 Forwards results of testing required by IE Bulletin BO-OA, "Engineered Safety Feature (EBF) Reset Controls " Two valves each in HPCI sys & RCIC sys do not remain closed on reset of sys line isolation signal KAMMER, D S Tennessee Valley Authority 83/05/12 O'REILLY, J P, KAMMER, D 8 Tennessee Valley Authority 83/05/12 O'REILLY, J P. Region 2, Office of Director 2pp 18838 251 24X Fichs 50-260, 63/05/12, 8306140041
- 8306140422 Confirms 830601 mgt meeting at site to discuss mgt controls for refueling operations, per 830519 telcon LEWIS, R C Division of Project & Resident Programs 83/05/23 PARRIE, H O Tennessee Valley Authority 3pp 18038 049 24K Fiche 50-259, 83/05/23, 8306140422
- 8306140685 Forwards IE Insp Repts 50-259/03-17.50-260/83-17 & 50-276/83-17 on 830509-12 No noncompliance noted VERRELLI,D M Division of Project & Resident Programs 83/08/2 PARTED,H G Tennessee Valley Authority 2pp 16841 336 24X Fiche 50-259,83/05/25.8306140685 83/08/25
- --8306140692 IE Insp Repts 50-259/03-17.50-260/83-17 & 50-294/83-17 on 830509-12 No noncompliance noted Major areas inspected followup on IE Bulletin 80-11. "Masonry Wall Design " LENAHAN, J J., CONLON, T E Region 2. Office of Director 83/05/25 5pp. 18841 338 24X Fiche 50-259.83/05/25.8306140685
- 8305110458 IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in Well Logging Device" Svc list encl TAYLOR, J M Division of Bafeguards & Inspection Programs (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 125pp 18831 043 24X Fiche 50-000,83/05/26,8305110458
- 8305110460 IE Info Notice 83-34. "Event Nutification Info Worksheet "
- 8306150625 Requests approval for M Tokar to visit site on 830613 in order to observe exam of fuel removed from reactors Specific info for discussion listed VASSALLO,D B Operating Reactors Branch 2 83/05/27 PARRIS,H C Tennessee Valley Authority, 3pp 18867 285 24X Fichs 50-259,83/05/27.8306150625
- 8305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods Withdrawn at BWRs " Svc list encl JORDAN, E L Division of Emergency Preparadness & Engineering Response (Post 830103) 83/05/31. Consolidated Edison Co of New York, Inc 114pp 18732 208 24X Fiche, 50-000, 83/05/31, 8305110461.
- 8306140251 Ack receipt of 830525 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-259/83-09, 50-260/83-09 & 50-296/83-09
 LEWIS,R C. Division of Project & Resident Programs 63/06/02
 PARRIS,H Q Tennessee Valley Authority Ip 18932,236 24X
 Fiche.50-259,83/06/02,8306140251
- --B306140266 Responds to NRC B30418 ltr re violations noted in IE Insp Repts 50-259/83-09, 50-260/83-09 & 50-296/83-09 Corrective actions: all conduit supports for safety-related equipment corrected by work plan or maint request KAMMER: D 8. Tennesses Valley Authority B3/05/25 O'REILLY, J P Region R. Office of Director App 18832: 237 24X Fiche: 50-259, 83/06/02, 8306140251
- --8306140276 Forwards IE Insp Repts 50-259/83-09, 50-260/83-09 & 50-296/83-09 on 830226-0325 & notice of violation LEWIS, R C Division of Project & Resident Programs 83/04/18 PARRIS H O Tannessee Valley Authority 2pp. 18832 243 24) Fiche 50-259, 83/06/02, 8306140251
- --8306140284 Natice of violation from insp on 830226-0325.

 * Region 2, Office of Director 83/04/18 2pp, 18832 245 24x
 Fiche 50-259,83/06/02,8306140251

- --8306140297 IE Insp Repts 50-259/83-09, 50-260/83-09 & 50-296/83-09 on 830226-0325 Noncompliance noted faiture to meet design flow requirements & failure to have GA review & insp on maint requests
 PAULK, G L. Region 2, Office of Director CANTRELL, F 8 Division of Project & Resident Programs 83/04/13 14pp 18832 247 24X Fiche 50-259, 83/06/02, 8306140251
- 8306090331 Forwards response to IE Bulletin 60-11 re masonry wall design wall displacement analysis Masonry walls will remain stable under max differential bldg displacement & other loads caused by DBE MILLS.L M Tennessee Valley Authority 83/06/03 DENTON.H R. Office of Nuclear Reactor Regulation. Director 3pp 18795 078 24X Fichs 50-259,83/06/03.8306090331
- B305110464 IE Info Notice 83-36, "Impact of Security Practices on Safe Operations " Svt list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) B3/06/09 Consolidated Edison Co of New York: Inc 119pp 18830 280, 24X Fiche 50-000,83/06/09,8305110464.
- 8306290195 Ack receipt of 830425 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-259/83-03, 50-260/83-03 & 50-296/83-03 LEWIS:R C Division of Project & Resident Programs. 83/06/09 PARRIS:H © Tennasses Valley Authority ip 19056, 221 24X Fiche 50-259, 83/06/09, 8306290195
- --8306290203 Forwards response to NRC 830321 ltr re violations noted in IE Insp Repts 50-259/83-03,50-260/83-03 & 50-296/83-03 utilization re failure to perform radiation hazards evaluation denied Personnel counseled on radiological control. KAMMER, D S Tennessee Valley Authority 83/04/25, 0'REILLY, J. P. Region 2, Office of Director Spp. 19056: 222 24X Fiche 50-259,03/06/09.8306290195
- 8305110470 IE Info Notice 83-3B, "Defective Heat Bink Adhesive & Beismically Induced Chatter in Relays Within Printed Circuit Cards " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83706/13 Consolidated Edison Co. of New York, Inc. 118pp 18720 225 24X Fiche 50-000, 83/06/13,8305110470.
- 8306090010 IE Info Notice 83-37, "Transformer Failure Resulting From Regraded Internal Connection Cables" Svc list encl JURDAN.E L Division of Emergency Preparadness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co. of New York, Inc 243pp 18921 001 24X Fichs.50-000.83/06/13,8306090010.
- 8306290277 Ack receipt of 830523 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-259/83-12, 50-260/83-12 & 50-296/83-12. CEMIS.R C Division of Project & Resident Programs. 83/06/14 PARRIES H 9 Tennessee Valley Authority 1p 19056,038 24X Fiche 50-259,83/06/14.8306290277
- --8306290283 Responds to NRC 830422 ltr re violations noted in IE Insp Repts 50-259/83-12,50-260/83-12 & 50-296/83-12 Corrective actions radiological incident repts issued for each instance cited MILLB.L M Tennessee Velley Authority, 83/05/23 O'REILLY, J P. Region 2, Office of Director 5pp 19056 039 24X Fiche 50-259,83/06/14,8306290277.
- --8306290RBB Forwards IE Insp Repts 50-259/83-12, 50-260/83-12 & 50-296/83-12 on 830321-28 & notice of violation, LEWIS.R C Division of Project & Resident Programs, 83/04/PARTIS.H Q Tennessee Valley Authority 2pp 19056:044, Fiche 50-259,83/06/14,8306290277.
- --8306290292 Notice of violation from insp on 830321-R5
 * Region 2, Office of Director 83/04/22, Rpp 19056:046, 24%
 Fich* 50-259,83/06/14,8306290277
- --8306290297 IE Insp Repts 50-259/83-12,50-260/83-12 & 50-294/83-12 on 830321-25 Noncompliance noted radioactive waste operator inside contemination zone w/o protective clothing or radiation monitors DEBS, D T , BARR, K P. Region 2, Office of Director. 83/04/20, opp 19056 048 24X Fiche 50-259,83/04/14,8306290277
- 8306270250 Forwards response to IR Bulletin 83-03 re check valve failures in raw water cooling sys of diesel generators, Current test program sufficient to verify integrity of check WILLS.L M Tennessee Valley Authority 63/06/15. D'REILLY.J.P. Region 2. Office of Director. 3pp 19054 081. 24X Fiche 50-259.83/06/15.8306290250.

- 6290272 Ack receipt of supplemental 830610 ltr informing NRC of taps taken to correct violations noted in IE Insp Repts 0-259/01-28.50-260/81-28 & 50-276/91-28 EMIS.R C Division of Project & Resident Programs 83/06/16 ARRIS.H C. Tannesses Valley Authority. ip 19056-054 24X ichs 50-259.83/06/16.8306290272
- 306270275 Supplemental response to NRC BilO31 ltr re violations noted in IE Insp Repts 50-259/81-28,50-260/81-28 & 30-296/81-28 Corrective actions five pump air vent valves removed & replaced w/stronger & improved upper float guides MILLS.L M. Tennessee Valley Authority 83/06/10 O'REILLY.J P. Region 2. Office of Director 3pp 19056:055 24X Fiche 50-259,83/06/16,8306290272
- 621019A Ack receipt of B30603 ltr informing NRC of steps taken to orrect violations noted in IE Baf4guards Insp Repts 0-287/83-10, 50-260/83-10 & 50-296/83-10 EWIS,R C. Division of Project & Resident Programs 83/06/17 ARRIS.H 0 Tennesse Valley Authority. 1p 18919,030 24% iche.50-259,83/06/17,8306210194
- 1306210203 Forwards response to NRC 830429 ltr re violations noted in IE 8afeguards Insp Repts 50-259/83-10, 50-260/83-10 & 50-296/83-10 Corrective actions withheld (ref 10CFR73 21) HILLBIL H Tennessee Valley Authority 83/06/03, O'REILLY, J P Repion 2, Office of Director 19 18919:031, 24x Fichs:50-259,83/06/17,8306210194
- 3305210213 Forwards IE Safeguards Insp Repts 50-259/83-10,50-260/83-10 & 50-295/83-10 on 830404-08 & notice of violation Notice of violation withheld (ref 100FR73 21) LEWIB.R C. Division of Project & Resident Programs. 83/04/29. PARRIB.H O Tennesses Valley Authority 2pp 18919-032, 24X Fichs 50-259,83/06/17,8306210194.
- 306210224 IE Sefeguards Insp Repts 50-259/83-10,50-260/83-10 & 50-296/83-10 on 830404-08 Noncompliance noted: failure to failow access control procedures. Details withheld (ref 10CFR73.E1).
 MORE, D E , MCGUIRE, D R. Region 2, Office of Director 83/04/27 is. 18919:034 24% Fichs.50-259,83/06/17,8304210194.
- 16290483 Approves issuance of BALP Repts 50-259/83-04,50-260/83-04, 10-296/83-04,50-327/83-04,50-328/83-04,50-390/83-07, 10-391/83-06,50-438/83-06 & 50-439/83-06 for Jul 1981 Dec 1982 No reply required
- 1982 No reply required
 1982 No reply required
 1982 LLV, J.P. Region 2. Office of Director. 83/06/17. PARRIE, H.Q.
 Tennesses Valley Authority 3pp. 19050 212 24X
 Tiche 50-000,83/06/17,8306290483.
- 1306270470 Forwards BALP Repts 50-259/83-04, 50-260/83-04, 50-296/83-04.50-327/83-04, 50-328/83-04, 50-397/83-07, 50-391/83-06, 50-438/83-06 50-439/83-06 for Jul 1981 Dec 1982. C. Division of Project & Resident Programs, 83/04/19ARIS, H 0 Tennesses Valley Authority, 3pp 19050, 215 2 Fiche, 50-000, 83/06/17, 8306290483.
- 3306290803 BALP Repts 50-259/83-04,50-260/83-04,50-296/83-04, 50-327/83-04,50-328/83-04,50-390/83-07,50-391/83-06, 50-438/83-06 & 50-439/83-06 for Jul 1981 - Dec 1982 * Region 2. Dffice of Director 83/04/13 92pp, 19050 218 24) Fiche: 50-000,83/06/17,8306290483
- 3306290510 Comments on SALP Repts 50-259/83-04,50-260/83-04, 50-296/83-04,50-327/83-04,50-328/83-04,50-390/83-07, 30-391/83-06,50-438/83-06 & 50-439/83-06 for Jul 1981 - Dec 1982. MILLS,L M Tennessee Valley Authority, 83/05/10 O'REILLY
- 1704. MILLS,L M Tennessee Valley Authority. 83/05/10 O'REILLY,J P Region 2. Office of Director 2pp. 17050-310 24X Fiche-50-259.83/06/17.8306290483
- JS110475 IE Info Notice 83-40, "Need to Environmentally Gualify Spoxy Grouts & Sealers," Syc list encl JORDAN, E. Division of Emergency Preparadness & Engineering Response (Post 830103) 83/06/22 Consolidated Edison Co. of New Yorks Inc. 115pp. 19021:179. 24X Fiche 50-000,83/06/22,8305110478,
- 05110477 IE Info Notice 83-41, "Actuation of Fire Suppression Hys Causing Inoperability of Bafety-Related Equipment " Svc list encl.
- encl. JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103), 83/06/22. Consolidated Edison Co. of New York, Inc. 120pp. 18997'007. 24% Fiche,50-000,83/06/22,8305110477.
- 05110479 IE Info Notice 83-42. "Reactor Mode Bwitch Malfunctions." Byc list encl. JORDAM, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/06/23. Consolidated Edison Co. of New York, Inc. 116pp. 18996-242. 24X Fichs 50-000,83/06/23,8305110479

- 8305110483 IE Info Notice 83-43, "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints " Svc list encl JORDAN, E L Division of Emergency Proparedness & Engineering Ramponee (Post 830103) 83/04/24 Consolidated Edison Co of New York, Inc 116pp 19046 297 24X Fiche 50-000,83/06/24,8305110483
- R Periodic operating reports & related correspondence
- 8306160482 Monthly operating repts for Apr 1983 W/830511 ltr THOM.T , COFFEY, J A Tennessee Valley Authority 83/05/01 Office of Management and Program Analysis 39pp 18864 085 24X Fiche 50-259,83/05/01.8306160482
- 8 Reportable occurrences, LERs & related correspondence
- 8306010269 Deficiency rapt re inability of prompt notification sys mobile strens to complete routes in required time Initially reported on 830502 Addl strens will be procured & mobile routes modified Full compliance expected by 830901 MILLS.L M Tennessee Valley Authority 83/05/23 O'REILLY, J P Region 2, Office of Director 2pp 18674 324. 24% Fiche 50-259.63/05/23.8306010269
- 830-6010237 Updated LER 81-050/03X-4 on 811003, containment atmosphere torus hydrogen analyzer 2-H2M-76-104 removed from svc for corrective maint Caused by water in sensing lines Design Change Request P-2693 evaluated W/830524 ltr QREEN.H J, BURNS,R Tennessee Vallay Authority 83/05/24 0'REELLY,J P. Region 2, Office of Director 2pp 18672 300, 24X Fiche 50-260,83/05/24.8306010237
- 8306070084 LER 83-023/03L-0 on 830602, while performing 8T 4 1, A-6 drywell pressure switch found operating above Tech Spectrip setting, initiating drywell high pressure half scram Caused by setpoint driet W/830527 ltr CHAMBERS, 6 T , GREEN, H J Tennessee Valley Authority 83/05/27 0'REILLY, J P. Region 2, Office of Director 4pp 18739 202 24X Fiche 50-260, 83/05/27, 8306070084
- 8306070099 LER 83-022/03L-O on 830503.screm discharge vol scram switch failed to operate. Reactor protection sys logic switch tripped upon actuation Caused by Magnetrol model switch drift outside operating hand Switch adjusted W/830527 ltm 000DMRN, D.C., ORCEN, H.J. Tennessee Valley Authority 83/05/27 07REELLULY, J.P. Region 2, Office of Director, 3pp. 18737-361 24X Fiche 50-260,83/05/27.8306070099.
- 8306210226 LER 83-025/03L-0: on B30520, pressure switch PB-3-228 as-found setpoint set above Tech Spec limits during performance of BI 4 1.4-5 Caused by calibr drift. Barksdale B2T-A128B pressure switch recalibr W/830614 ltr.
 ODDDWIN.D C . OREEN.H J Tennessee Valley Authority. 83/06/14 D'REILLY.J P. Region 2. Office of Director 4pp 18916 031. 24X Ficher 50-260,83/06/14,8306210226
- 8306270090 LER 83-024/03L-0 on 830515, recirculation pump 2A tripped after isolation valve 2-24-744 failed closed Caused by shaered coupling plas. Crane Model XF-3600 valve rapaired & pump returned to svc. M/830614 ltr LOCHBAUM, D. GREEN, H. J. Tennessee Valley Authority 83/06/14 0/4651LY, J. P. Region 2, Office of Director 3pp 18988 082 24X Fiche 50-260.83/06/14.8306270090
- 8306170294 PND-II-83-047 on B30613 standby gas treatment sys train B declared inoperable due to problems w/Filter heaters Cause not stated Event involved no equipment damage no personnel error or injury & no radioactive releases BUTGHERR C , VERRELLI, D M Region 2, Office of Director B3/06/15, 2pp 18879 048 24% Fiche 90-260, 63/06/15, 8306170294
- 8306210136 LER 83-027/03L-0 on 830520, differential pressure switch for pressure suppression chamber-reactor didg vacuum breakers found operating above Tech Spec limits Caused by switch drift Bwitch 2-PDIB-64-20 recalibr W/830615 ltr CHAMBERS, 6 T. OREEN, H.J. Tennessee Valley Authority. 83/06/15 0'REILLY, J.P. Region 2. Office of Director 3pp 18914-189 24X Fiche 50-260,83/06/15,8306210136
- 8306270327 Updated LER 83-014/03X-1 on 830330.air operator of main steam relief valve PCV-i-i80 found assembled incorrectly. Caused by personnel failure to follow procedure Valve repaired & insp procedure vested W/830616 ltr. HOLDER,E T , OREEN,H J Tennessee Valley Authority 83/06/16, 0'REELLY,J P, Region 2, Office of Director 3p 18973 051 24X Fiche 50-260,83/06/16,6306270327
- 8306280375 LER 83-026/03L-0 on 830521, during rod sequence exchange, calculated R factor less than R setpoint Caused by R factor calculated out during power shaping rod moves Rod pattern adjusted & verified W/830617 ltr.
 WINOG M.D., OREEN H J Tennessee Valley Authority 83/06/17 G'REILLY, J P. Region 2, Office of Director 3pp 19014-067 24X Fichs 50-260, 83/06/17, 8306280375

- 8304300224 LER 83-028/03L-0 on 830526, during normal operation, HPCI systeclared inoperable due to blown inverter fuse Fuse replaced HPCI turbine control valve failed to open due to misadjusted rod Rod adjusted W/830622 ltr CARTER, 9, ORECN, H J Tennessee Valley Authority 83/06/22 G/REILLY, J P. Region 2, Office of Director 3pp 19119 203 24X Fiche 50-260, 83/06/22, 8306300224
- 8306300181 LER 83-029/03L-O on 830528 during normal operation, drywell radiation monitor RE-90-256 sample pump tripped Caused by blown fuse Fuse replaced & drywell air sampling sys returned to sve W/830624 itr CARTER, S. OREFN, H. J. Tennessee Vallay Authority 83/06/24 G.REILLY, J.P. Region 2, Défice of Director 3pp 19122 196 24X Fiche 50-240, 83/06/24, 8306300181

- 8306140687 Discusses operator & senior operator licensing exams & schedule to facilitate written & oral exams to be administered during wk of 830627 Approved ref matl listed in encl requested by 830427
 VERRELLI.D M Division of Project & Resident Programs 83/03/30 OREEN.H.J Tennessee Valley Authority 3pp 18841 346 24X Fiche 50-259,83/03/30,8306140687
- 8306140626 Responds to 830330 request for renewal of QT McChristian Benior Operator License 80P-2938-2 License expired McChristian should reapply for license NRC will consider request for walver of exams VERRELLI.D M Division of Project & Resident Programs 83/05/12 GREEN, H J Tennessee Valley Authority 1p 18842 086 24X Fiche 50-259,83/05/12.8306140626
- X Onsite Storage of Low Level Waste
- 8304060102 Responds to 830422 ltr re determination of fees for low level radwaste amend applications fee determination acceptable MILLS.L M Tennessee Valley Authority 83/04/01 MILLER.W O License Fee Management Branch ip 18719 389 24X Fiche 50-000.63/06/01.8304060102
- DOCKET 50-261 H B ROBINSON PLANT, UNIT 2
- F Security, medical, emergency & fire protection plans
- 8306140678 Ack receipt of 830131 ltr informing NRC of corrective actions taken in response to 821101 confirmation of action ltr re emergency preparedness program
 LEMIG.R C Division of Project & Resident Programs 83/03/31
 FURR.B J Carolina Power & Light Co ip 18841 268 24X
 Fiche 50-000,83/03/31.8306140678
- --830614070B Bubmits status of corrective actions for deficiencies noted in B21101 confirmation of action ltr re emergency preparedness program UTLEY,E E Carolina Power & Light Co 83/01/31 O'REILLY,J P Region 2, Office of Director 2pp 18841.269 24X Fiche 50-000,63/03/31,8306140698
- 8306090391 Releases public version of revised emergency response plan FELTON, J M Division of Rules and Records 83/06/01. Document Management Branch 1p 18814 084. 24% Fiche 50-261,83/06/01,8306090391
- ~-8306070374 Public version of Rev 13 to emergency response plan ZIMMERMAN, 8 R Carolina Power & Light Co. 83/05/16 312pp 18814 085 24X Fiche: 50-261, 83/06/01, 8306070371
- 8304080122 Forwards add1 info re App R exemption requests for pipe alley, component cooling water pump room & reactor coolent pump bay areas Exemption request for pipe alloy withdrawn W/two oversize drawings Aperture cards are available in PDR, EURY, L. W Carolina Power & Light Co 83/06/07 VAR9A, B A Operating Reactors Branch 1, 102pp, 18770 257 24X Fiche, 50-261, 83/06/07, 8306080122,
- 8306290420 Forwards 1E Insp Rept 50-261/83-13 on 830502-06. No noncompliance noted VERRELLI,D M Division of Project & Resident Programs. 83/06/08 UTLEY,E E Carolina Power & Light Co Rpp 17053.181 24X Fiche: 50-261,83/06/08.8306290420.
- ---8304290426 IE Insp Rept 50-261/83-13 on B30502-06 No noncompliance noted Major areas inspected emergency preparedness CLINE.W E., DECKER.T R. Region 2, Diffice of Director. JENKINB, O R. Division of Emergency Preparedness & Materials Safety. B3/06/07 7pp 19053-183 24X Fiche 50-261,83/06/08,8306290420

830.6220273 Confirms telcon w/IE re acceptability of emergency response facilities Locations of alternate locations for offsite personnel to assemble to communicate w/emergency operations facilities acceptable HURFORD, N J Carolina Power & Light Co B3/06/17 DENTON, H, R Office of Nuclear Reactor Regulation, Director, ip 18926-033 24% Fiche 50-000.83/06/17.8306220273

Q Adjudicatory correspondence

- B306i60007 Advises that NRC will prepare E18 for steam generators ABLB will be informed of projected issuance date KARMAN, M Hearing Branch 1 83/06/14, MARGULIES, MB, HETRICK, DL, KLINE, JR, Atomic Bafety and Licensing Board Panel Ip 1886i 356 24X Fichs 50-26i,83/06/14,8306i60007
- P Operating license stage documents & correspondence
- B30.6070153 Responds to B21013 ltr finding util position on NUREO-0737, Item II K 3 25 re power on pump seals acceptable Addl info re component cooling water pumps 8 & C clarified Both pumps automatically tripped by containment spray sys ZIMMERMAN,8 R Carolina Fower & Light Co 83/05/31 VARQA,9 A Operating Reactors Branch 1 2pp 18736 241 24% Fiche 50-261,83/05/31,8306070153
- 8306070101 Responds to 821001 ltr re util 801231 response to NUREO-0737. Item III. D 3 4. "Control Room Habitability." Cantrol room HVAC sys modified to reduce unfiltered lemiage Evaluations & recommendations re NUS-3676 encl. EURY.L W Carolina Power & Light Co 83/06/02 VARGA, S A Operating Reactors Branch 1 17pp 18738 347 24X Fiche 50-261.83/06/02.8306070101
- 8306100260 Forwards updated response to 830321 k 23 requests for add1 info re final steam generator repair rept.

 ZIMMERMAN,8 R Carolina Power & Light Co. 83/06/03 VARQA,8 A Operating Reactors Branch 1 22pp 18807 013 24X

 Ficha 50-261,83/06/03,8306100260
- 8306170460 Notification of 630628 meeting w/util in Bethesda. HD to discuss plans for repair/replacement of steam generators Agenda encl.
 REGUA. G Operating Reactors Branch 1 83/06/14 VAROA. 8 A Operating Reactors Branch 1 4pp 18706 355. 24X Fiche. 50-261. 63/06/14. 8306170460
- 8306200018 Notification of 830624 meeting w/util in Bethesda, MD to discuss & schedule multi-plant actions, NUREQ-0737 & plant-specific open items.
 REGUA, Q Operating Reactors Branch 1, 83/06/14, VARQA, 8 A Operating Reactors Branch 1 3pp 18709 121 24X Fiche: 50-261, 83/06/14, 8306200018
- 8306220005 Documents 830606 telcon re util 830209 response to NUREGO737. Item II.E 1 2. "Auxiliary Feedwater Sys Automatic Initiation & Flow Indication " Bypass signals do not block indicator, annunciator or reactor trip signals ZIMMERMAN.B R Carolina Power & Light Co. 83/06/17 VARQA, 8. A. Operating Reactors Branch 1 2pp. 18927 360 24% Fiche 50-261, 83/06/17, 8306220005
- 8304280003 Informs of progress made since 820719 meeting re Unresolved Bafety Issue A-47. "Bafety Implications of Control 8ys."

 Task Action Plan for A-47 completed Sept 1982 & EQ&O contracted for plant design review List of Info needed Sncl. EISENHUT.D.Q. Division of Licensing 83/06/20 UTLEY.E E Carolina Power & Light Co 34pp. 19044-043. 24X

 Fiche 50-261.83/06/20.8306280003
- G Inspection reports, IE Bulletins & correspondence
- 830&i40078 Confirms 830328 enforcement meeting at Region II oft to discuss recent events at Brunswick 1 re standby gas treatment deluge sus & visolation involving radwaste shipments from Robinson 2 per 830322 telcon Agenda encl O'REILLY, J.P. Region 2, Office of Director. 83/03/25 UTLEY, E.E. Carolina Power & Light Co 2pp. 18838.342 24X Fiche 50-000,83/03/25,8306140078
- 8306140678 Ack receipt of 830131 ltr informing NRC of corrective actions taken in response to 821101 confirmation of action ltr re emergency preparadness program LEWIG.R C. Division of Project & Resident Programs. 83/03/31. FURR. B J Carolina Power & Light Co ip. 18841.268 24X Fiche.50-000.83/03/31.8306140678

- --8306140708 Submits status of corrective actions for deficiencies noted in 821101 confirmation of action ltr re emergency preparedness program

 UTLEY, E. E. Carolina Power & Light Co. 83/01/31 0'REILLY, J.P. Region 2, Office of Director. Zpp. 18841 269 24X fiche 80-000, 83/03/31,8306140678
- 8306140264 Supple 810119 response to IE Bulletin 80-15, describing relocation of emergency notification sys (EMS) power supply to emergency power source EMS to be relocated in new technical support ctr presently under const. FURR.B. J. Carolina Power & Light Co. 83/04/29 D'REILLY, J.P. Region 2, Office of Director 2pp 18832:219 24X Fiche: 50-261,83/04/29,8306140264.
- 8306140399 Confirms B30510 mgt meeting in Raleigh: NC to review BALP program (first phase) results: per 830412 telcon Proposed agenda encl.

 LEMIS: R. C. Division of Project & Resident Programs 83/04/29 UTLEV: E. E. Caroline Power & Light Co. 3pp. 19832 093 24X Fiche: 50-000, 83/04/29; 8306140399
- 8305110458 IE Info Notice 83-32, "Ruptures Am-241 Sources Contained in Well Logging Device." Svc list encl TAYLOR. J.M Division of Sefaguards & Inspection Programs (Post 830103). 83/05/26 Consolidated Edison Co of New York, Inc 125pp 18831:043 24X Fiche: 30-000,83/05/26,8305110458
- 8305110460 IE Info Notice 83-34, "Event Notification Info Worksheet" Ext list entl. JORDAN,E L. Division of Emergency Preparadness & Engineering Response (Post 830103). 83/05/26. Consolidated Edison Co. of New York, Inc. 115pp. 18732.085 24X Fiche.50-000,83/05/26,8305110460
- 8308110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods Mithdrawn at BURa " Eve list encl JORDAN, E. L. Division of Emergency Preparadness & Engineering Response (Post 830103). 83/05/31. Consolidated Edison Co. of New York: Inc. 116pp 18732 208 24X Fiche 50-000,83/05/31,8305110461.
- 8306070172 Ack receipt of 830426 ltr requesting TLD data collected during steam generator inso for independent analysis of bata dose Data will be provided as soon as available.

 ZIMMERMAN, 8 R Caroline Power & Light Co 83/05/31 VARGA, 8, A Operating Reactors Branch 1 ip. 18/36:279. 24X Fiche:50-261,83/05/31,8306070172.
- 8306290247 Responds to IE Bulletin 83-03, "Check Valve Failures in Raw Water Cooling Sus of Diesel Generators." No check valves installed in branch connection piping from main svc water headers to diesel generator components FURR: B J Carolina Power & Light Co 83/06/08, D'REILLY, J. P. Region 2, Office of Director ip. 19056, 084, 24X Fiche: 50-261, 83/06/08, 8306290247
- B306290420 Forwards IE Insp Rept 50-261/83-13 on 830502-06.No noncompliance noted. VERRELLI,D M. Division of Project & Resident Programs. 83/06/08. UTLEY, E.E. Carolina Power & Light Co. 2pp 19053-181 24X Fiche: 50-261,83/06/08.8306290420.
- 8305110464 IE Info Notice 83-36, "Impact of Becurity Practices on Safe Operations." By: list and, JORDAN, E.L. Division of Emergency Preparadness & Engineering Response (Post 830103) 83/06/09. Consolidated Edison Co. of New York, Inc. 11999. 18830 280. 24X Fichs 30-000,63/06/09,8305110464.
- 8305110470 IE Info Notice 83-38. "Defective Heat Sink Adhesive & Beiemically Induced Chatter in Relays Within Printed Circuit Cards." Swc list encl. JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13, Consolidated Edison Co of New York, Inc. 118pp. 18920:225 24X Ficher 50-000, 83/06/13, 8305110470.
- 8304090010 IE Info Notice 83-37, "Transformer Failure Resulting From Degraded Internal Connection Cables." Byc list encl. JORDAN, E. L. Division of Energency Preparedness & Engineering Response (Post 830103). 83/06/13. Consolidated Edison Co. of New York, Inc. 243pp. 18921:001 24X Fichs 50-000,83/06/13,8306090010.

- B306#90524 Approves issuance of SALP rept Notes improvement in safety-related activities, emergency preparedness & security & safeguards Weaknesses in QA program will be monitored O'REILLY, J.P. Region 2, Office of Director B3/06/14 UTLEY, E. Carolina Power & Light Co. Spp. 19049 282 24X Fiche 30-000,83/06/14,8306290524
- --B306270531 Forwards BALF Repts 50-325/83-09, 50-324/83-09, 50-241/83-07, 50-400/83-10 & 50-401/83-10 for Jan 1982 Jan 1983 Evaluation will be discussed in Raleigh.NC on 830510 LEMIS,R C Division of Project & Resident Programs 83/05/03, UTLEY,E E Carolina Power & Light Co 2pp 19049 287 24X Fiche 50-000,83/06/14.8306270524
- --8306290537 BALP rept for Jan 1982 Jan 1983 * Region 2. Office of Director 83/05/03 64pp 19049 289 24X Fiche 50-000,83/06/14,8306290524
- --B306290853 Responds to B30503 BALP rept For Jan 1982 Jan 1983 Reduced NRC attention may be appropriate for Category 1 re fire protection NRC attention should be maintained at normal levels for emergency preparedness UYLEY.E E Carolina Fower & Light Co B3/05/20 U'REILLY, J P Region 2. Office of Director lopp 19049 354 24X Fichs 50-000, 63/06/14, 8306290524
- --8306290555 Forwards replacement Page 2 to Attachment 2 of 830520 ltr which commented on SALP rept EURY, L W Carolina Power & Light Co 83/05/27 O'REILLY, J P Region 2. Office of Director 2pp 19050 009 24X Fiche 50-000,83/06/14,8306390524
- 8306240470 Forwards request for eddl info needed for Franklin Research Ctr review of 830204 response to IE Bulletin 80-11 un masonry wail design Info should be submitted by 830725 VARQA, 8.A. Operating Reactors Branch 1 83/06/17 UTLEY, E E Carolina Power & Light Co Spp. 18998 082 24X Fichs. 50-261.83/06/17.8306240470
- 8305110475 IE Info Notice 83-49, "Need to Environmentally Gualify
 Epoxy Grouts & Sealers " Svc list encl
 JDROAN, E. L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/06/22. Consolidated Edison Co. of New
 York Inc. 118pp 17021:177. 24X Fiche 50-000.83/06/22.8305110475
- 8305110477 IE Info Notice 83-41, "Actuation of Fire Suppression Sys Causing Inoperability of Safoty Related Equipment " Syc list encl. JORDAN.C.L Division of Emergency Preparedness & Engineering Response (Post 830103). 83/06/22 Consolidated Edison Co. of New York. Inc. 120pp. 18997:007 24X Fiche: 50-000.83/06/22.8305110477
- B305110479 IE Info Notice B3-42, "Reactor Mode Bwitch Maifunctions " Bvc list encl JORDAN-E.L. Division of Emergency Preparedness & Engineering Response (Post B30103) B3706/23 Consolidated Edison Co of New York, Inc 116pp. 18996-242 24X Fiche 50-000,83706/23,8305110479
- 8305110483 IE Info Notice 83-43, "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints "Svc list encl URDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/24 Consolidated Edison Co. of New York, Ync 114pp 17046-277. 24X Fiche 50-000, 83/06/24, 8305110483
- R. Periodic operating reports & related correspondence
- 8306160420 Monthly operating rept for Apr 1783 W/830510 ltr NORRIB.H.R., STARKEY.R.B. Caroline Power & Light Co. B3/05/02, DEYCUNG.R.C. Director's Office, Office of Inspection and Enforcement. 4pp. 18860:033. 24X Fichs.50-261,83/05/02,8306160420
- 8306140405 Monthly operating rept for May 1983 W/830610 ltr.
 NORRIB.H.R., BTARKEY.R.B Caroline Power & Light Co 83/06/02
 DEYOUNG.R.C. Director's Office, Office of Inspection and
 Enforcement, Spp. 18838:091. 24X Fiche: 50-261,83/06/02.8306140405.
- 8 Reportable occurrences, LERs & related correspondence
- 8306070161 LER 83-006/03L-0: on 830427, during testing of spare pump installed to replace syc water pump A.pump tripped on overcurrent Apparently caused by internal binding of sheft as result of debris in impeller assembly, W/830526 ltr. COX.H.T. STARKEY.R.B. Carolina Power & Light Co. B3/05/26 O'REILLY, J.P. Region 2. Office of Director. App. 18736: 284, 24X Ficher 50-261, 83/05/26, 8306070161.

- 8306070182 LER 83-007/03L-0 on 830429, PORV RC-455C failed to meet required cycle time & failed to open fully on subsequent attempt Caused by galling of valve plug to cage due to rubbing of stainless steel in dry condition W/830527 lor COX, H T . STARKEY, R B Carolina Power & Light Co 83/05/27 O'REILLY, J P. Region 2. Office of Director 4pp 16736 321 24X Fiche 50-261.83/05/27,8306070182
- 8306200002 LER 83-008/03L-0 on 830506, safety injection accumulator level transmitters found out of calibr Caused by instrument drift Transmitters recalibr & replacement mod developed W/830606 ltr COX.H T . STARKEY, R B Carolina Power & Light Co 83/06/06 O'REILLY, J P Region 2. Office of Director 3pp 18904 022 24X Fiche 50-261,03/06/06,8306200002
- 8304200188 LER 83-009/03L-0 on 830507, w/unit shut down for steam generator insp outage, flow transmitter FT-495, loop C steam flow found out of calibr Caused by instrument drift Transmitter recalibr % returned to svc W/830607 ltr COX, H T . STARKEY, R B Carolina Power & Light Co 83/06/07 O'REILLY, J P Region 2. Office of Director Spp 18703 180 24% Fiche 50-261, 83/06/07, 8306200188
- B306200107 LER B3-010/01T-0 on B30525, review of eddy current data revealed 137 & 206 defective tubes identified in stoam generators B & C. respectively All defective tubes taken out of svc W/830608 ltr COX.H T . STARKEY, R B Carolina Power & Light Co B3/06/08 O'REILLV.J P. Region 2. Office of Director 3pp 18903 255 24X Fiche 50-261, B3/06/08, B306200109

DOCKET 50-263 MONTICELLO NUCLEAR GENERATING PLANT F Security, medical, emergency & fire protection plans

- B306060247 Forwards 1E Insp Rept 50-263/83-07 on B30402-0501 No noncompliance noted SHAFER, W D Region 3, Office of Director B3/05/19 LARSON, C E Northern Btates Power Co 2pp 18727 R35 24X Fiche 50-263, B3/05/19, 8306060247
- --8306060251 IE Insp Rept 50-263/83-07 on 830402-0501. No noncompliance noted Major areas inspected operational safety verification, including physical security plan implementation, onsite review committee & personnel changes BROUN, C H. MALKER, R D. Region 3, Office of Director. 83/05/19 3pp 18727 237 24X Fiche. 50-243, 83/05/19, 8306060247
- 8304100095 Forwards finalized rept re emergency preparedness insp followup on 830516-20 Procedures for containment air sampling completed & implemented MARTIN, J B., THOMAS, W V Battelle Memorial Institute, Pacific Northwest Laboratory 83/05/25 PATTERSON, J Region 3, Diffice of Director. 17pp 18802 245 E4X Fiche. 50-263,83/05/25,8306100095.
- 8304140430 Bubmits addl info to closs out open items identified in 810212 fire protection SER per App R, Soction III. 0 2 requirements Cable tray penetrations & supply ducting verified for 3 h resistance.

 MUSOLE, D. Northern States Power Co 83/06/07 Office of Nuclear Rescator Regulation, Director 4pp 18860-226 24X
 Fiche 50-263,83/06/07,8306140430
- 8306200108 Informs of change in design of control room ventilation sys smoke detection & isolation sys to upgrade control room ventilation bys to satisfy NUREO-0737.

 Item III D 3 4 requirements.

 MUSOLF, D Northern States Power Co. 83/06/13 Office of Nuclear Reactor Regulation, Director 1p 16703 258 24X

 Fiche. 50-263, 83/06/13, 8306200108.
- 8306210074 Forwards Rev 13 pages to security plan Pages withheld (ref 10CFR73 21).

 MUSOLF, D Northern States Fower Co 83/06/14 Office of Nuclear Reactor Regulation, Director 2pp 18914 150. 24X

 Fiche 50-263,83/06/14.8306210074.
- 8306210072 Forwards IE Bafeguards Insp Rept 50-263/83-08 on 830510-13 & notice of violation Notice of violation withheld (raf 10CFR73 21)
 MILLER, J.R. Region 3. Office of Director 83/06/15. LARSON, C.E. Northern States Fower Co. 2pp. 18714; 220 24X
 Fiche: 50-263, 83/06/15.8306210072
- --B306210075 IE Befeguards Insp Rept 50-263/83-08 on 830510-13.

 Noncompliance noted portions of protected area intrusion elarm sys failed to function as described Details withheld (ref 100FR73 21)

 KNICELEY, J R . STAPLETON, B W . CREED, J R Region 3, Office of Director. B3/06/14 Ppp 18714 222 E4X Fiche. 50-263, 83/06/15, 8306210072.

- 8306280459 Informs that operational data for completion of HEPA filtration sys extended to 831001 due to difficulty in adopting ventilation sys to accommodate demands of HEPA filtration per Suppl 1 to NURE-0707 MUSOLF.D Northern States Power Co 83/06/20 Office of Nuclear Reactor Regulation, Director ip 19018 3RB 24X Fiche 50-000,83/06/20,8306280459
- P Operating license stage documents & correspondence
- B306010441 Bubmits response to 10CFR50 49, "Environ Qualification of Electrical Equipment Important to Safety for Nuclear Power Plants "Master list of safety-related electrical equipment and!
 HUSDLF.D M Northern States Power Co B3/05/19, Office of Nuclear Reactor Regulation, Director 30pp 18674, 272. 24X
 Fiche 50-R63/83/05/19,8306010441
- 8304150576 Forwards safety evaluation of util submittals re NUREQ-0737, Item II B 2 on plant shielding mods Item resolved.
 VASSALLO,D B Operating Reactors Branch 2, 83/05/23 MUSOLF, D. M
 Northern States Power Co 4pp. 18847:034, 24X
 Fiche 50-243.83/05/23.8304150576
- 8306020523 Notification of 830616 meeting w/util, Rechtml & QE in Bethesda, MD to discuss pipe cracks in recirculation sys piping NICOLARAS. H. Operating Reactors Branch R. 83/05/25. VASSALLO, D. B. Operating Reactors Branch R. ip. 18715, 143. 24X Fiche 30-263, 83/05/25, 8306020523.
- 8306230034 Notification of 830616 mgeting w/util. OE & Bechtel in Bethesds, MD to discuss preliminary plans for modifying recirculation sys plping NIGOLARAS: H Operating Reactors Brench 2 83/05/25, VASSALLO, D. B. Operating Reactors Brench 2 1p. 18754, 342, 24X Fiche 50-263:83/05/25,8306230034
- 6306150466 Forwards safety evaluation of util submittals on NUREG-0737 Items 1 A.2 1 4, "Upgrading Reactor Operator & Benior Reactor Operator Training" & Il. B 4, "Training for Mitigating Core Damage" Items resolved VASSALLO, D B Operating Reactors Branch 2 83/04/03. MUSOLF, D. M. Northern States Power Co 5pp 18867, 214 24X Fiche: 50-263, 83/06/03, 8306150466.
- 8306170353 Forwards Rev i to "Sus Description Sefety Relief Valve Blowdown Control Sys for Monticello Nuclear Generating Plant "Rept describes control sys mods to be implemented during 1984 refueling outsige MUSILF,D Northern States Fower Co. 83/06/13, Office of Nuclear Reactor Regulation, Director 1p 10880:163 24X Fiche 50-263,83/06/13,8306170353.
- --8306170354 Rev 1 to "Bys Description Bafety Relief Valve Blowdown Control Bys for Honticsllo Nuclear Generating Plant."
 RETMERS 0 A . BETMA 0 E . NAAF, D E . NUTECH Engineers, Inc. NSP-48-1103 R01. B3/05/18. 14pp. 18880.164 24X
 Fiche, 50-263, 83/06/13, 8306170353.
- Q Inspection reports, IE Bulletins & correspondence
- B305040483 Informs that revised process as stated in response to violation noted in IE Insp Rept 50-263/82-11 will not be in full effect until B30401. Rev involved substantial changes in areas not originally anticipated LARSON, C.E. Northern States Power Co. B3/04/26 NORELIUS, C.E. Division of Engineering ip 18343.144. 24X Fiche: 50-263, B3/04/26, 8305040453.
- 8306060247 Forwards IE Insp Rept 50-263/83-07 on 830402-0501. No noncompliance noted.

 8HAFER: W D. Region 3, Office of Director. 83/05/19. LARBON, C. E. Northern States Power Co. 2pp. 18727-235, 24X
 Fiche: 50-263,83/05/19.8306060247.
- --830404025i IE Insp Rept 50-263/83-07 on 830402-0501. No noncompliance noted Major areas inspected operational safety verification, including physical security plan implementation, onsits review committee & personnel changes.

 BROWN.C.H. WALKER,R.D. Region 3. Office of Director, 83/05/19.

 3pp. 18727, 237, 24X Fiche 50-263, 83/05/19, 8306060247.
- 8304100095 Forwards finalized rept of emergency preparedness insp followup on 830514-20. Procedures for containment air sampling completed & implemented. MARTIN. J B., THOMAS. W V Battelle Hemorial Institute, Pacific Northwest Laboratory. 83/05/25 PATTERSON. J. Region 3. Office of Director 17pp 19802, 245. 24X Ficher 50-263, 83/05/25, 8304100095.

- 8305110458 IE Info Notice 83-32. "Ruptured Am-241 Bources Contained in Well Logging Device" Svc list encl
 TAYLOR, J M Division of Sefeguards & Inspection Programs (Post B30103) 83/05/26 Consolidated Edison Co of New York, Inc
 125pg 18631.043 24X Fiche: 50-000, 83/05/26, 8305110458
- 8305110460 IE Info Notice 83-34, "Event Notification Info Worksheet"
 Syc list encl
 JORDAN, Et Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/05/26 Consolidated Edison Co of New
 York, Inc 115pp 18732 085, 24X Fichs: 50-000, 83/05/26, 8305110460
- 8304040084 Commends NRC re results of piping insplat BWRs
 Lesi-before-break concept continues to sustain validity of
 technical bases. Utils giving consideration to more permanent
 measures.
 NEILS, 9 H. Northern States Power Co. 63/05/26 DENTON, H.R. Office
 of Nuclear Reactor Regulation, Director 2pp 18719-335, 24X
 Fiche 50-000,83/05/26,8304040084
- B305110461 IE Info Notice B3-38, "Fuel Movement W/Control Rods Withdrawn at BWRs." Syc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) B3705/31. Consolidated Edison Co of New York, Inc 116pp. 18732, 208 24X Fichs 50-000, B3/05/31, B308110461
- 8306170134 Responds to IE Butletim 83-03. All applicable check valves will be tested in accordance w/bulletim following reva to surveillance test procedures & installation of described adds during 1984 refueling outage
 LARBON.C E. Northern Etates Power Co 83/06/08, KEPPLER, J & Region 3. Office of Director. 2pp. 18878 347 24X
 Fiche: 50-263,83/06/08,8306170134
- 8305i10464 IE info Notice 83-36, "Impact of Security Practices on Safe Operations." Svc list encl.
 JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103). 83/06/07 Consolidated Edison Co. of New York Inc. 119pp. 18830 280 24X Fiche 50-000.83/06/09.9305110464
- 8305110470 IE info Notice 83-36, "Defective Heat Sink Adhesive & Saismically Induced Chatter in Relays Within Printed Circuit Cards " Svc list encl JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Post 830103), 83/04/13 Consolidated Edison Co. of New York, Inc. 118pp. 18920:225 24X Fiche: 50-000, 83/04/13:8305110470.
- 8305090010 IE Info Notice 83-37, "Transformer Failure Resulting From Degraded Internal Connection Cables." Svc list encl. JCRDAN.E.L. Division of Emergency Praparedness & Engineering Response (Post 830103), 83/05/13 Consolidated Edison Co. of New York, Inc. 243pp 18921:001, 24X Fiche 50-000,83/06/13,8305090010
- 8306210072 Forwards IE Befeguards Insp Rept 50-263/83-08 on 830510-13 & notice of violation. Notice of violation withheld (ref 100FR73, 21)
 MILLER, J. R. Region 3, Office of Director. 83/06/15 LARSON, C. E. Northern States Power Co. 2pp. 18914-220 24X
 Fiche: 50-263: 83/06/15, 8306210072.
- --8306210075 IE Safeguards Insp Rept 50-263/83-08 on 830510-13, Noncompilance noted portions of protected area intrusion alera sys failed to function as described Details withheld (ref 10CFR73, 21).

 KNICELEY, J.R., STAPLETON, B.W., CREED, J.R. Region 3, Office of Director 83/06/14 2pp 18914; 222 24X Fichs. 50-263, 83/06/15, 8306210072.
- 6306210177 Ack receipt of 830511 ltr informing NRC of steps taken to correct violations noted in IE lnsp Rept 50-263/83-01 KEPPLER, J. Q. Region 3, Office of Director. 83706/15 LARBON, C. E. Northern States Power Co. ip. 18915-158 24X Fiche, 50-263, 83/06/15, 8306210177.
- 8305110475 IE Info Notice 83-40, "Need to Environmentally Qualify
 Epoxy Grouts & Bealers," Svc list entl.
 JORDAN, E. L. Division of Emergency Preparedness & Engineering
 Response (Post 830103). 83/06/22, Consolidated Edison Co of New
 York, Inc. 115pp. 19021.179, 24X Fiche: 50-000,83/06/22,8305110475
- B305110477 IE Info Notice 83-41, "Actuation of Fire Suppression Bys Causing Inoperability of Bafety-Related Equipment," Svc list encl.

 JORDAN, E. L. Division of Emergency Preparadness & Engineering Response (Post B30103). B3/06/22. Consolidated Edison Co. of New York: Inc. 120pp. 18997.007. 24X Fisher 50-000.83/06/22.8305110477.
 - Notice 83-42, "Reactor Mode Switch Malfunctions."
 - ision of Emergency Preparedness & Engineering .30103). 83/06/23. Consolidated Edison Co. of New ip. 18996: 242. 24X Fiche: 50-000: 83/06/23: 8305110479

- 8305110483 IE Info Notice 83-43, "Improper Bettings of Intermediate Range (IR) High Flux Trip Setpoints " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/24 Consolidated Edison Co of New York, Int 114pp 17046 297 24X Fiche 50-000, 83/06/24, 8305110483
- R Periodic operating reports & related correspondence
- 8305020088 Monthly operating rept for Mar 1983 W/830412 ltr MYRABO.A L. MURQLE.D. Northern States Power Co. 83/04/05 Office of Resource Management, Director 5pp 18691 198 24X Fiche 50-263,83/04/05.8305020088
- 8306200105 Monthly operating rept for May 1983 #/830610 ltr MYRABD.A.L. MUBOLF.D Northern States Power Ca 83/06/02 Office of Resource Management. Director 5pp 18903 269 24X Fiche 50-263.83/06/02.8306200105.
- S. Reportable occurrences, LERs & related correspondence
- 8306130438 LER 83-010/03L-0 on 830226 during surveillance testing, outboard MSIV.AD-2-868 closed faster than value stated in Tech Spec Table 3 7 1 Caused by oil leak from needle valve assembly on bottom dashpot culinder head W/830601 ltr RUBY.G T . MUSULF.D Northern States Fower Co 83/06/01 Region 3. Offsce of Director 2pp 18821 190 24X Fiche 50-263.83/06/01, 8306130438
- DOCKET 50-265 QUAD-CITIES STATION, UNIT 2
- F Security, medical, emergency & fire protection plans
- 8305130405 Forwards IE Insp Repts 50-254/83-15 & 50-255/83-13 on 830510-13 No noncompliance noted PAPERIELLO,C.J. Region 3. Office of Director 83/05/27 REED,C Commonwealth Edison Co 2pp 18823 064 24X Fiche.50-254,83/05/27, 8306130405
- --8306130412 IE Insp Repts 50-254/83-15 & 50-265/83-13 on 830510-13 No noncompliance noted Major areas inspected: smergency preparedness exercise PHILLIPS.H., SMITH.M., AXELBON,W L. Region 3, Office of Director 83/05/27 R
- 8304i60071 Releases public version of revised emergency plan implementing proceduras FELTON, J M Division of Rules and Records, 83/06/07 Document Management Branch ip 18872-349, 24X Fiche: 50-254.83/06/07.8306i60071.
- --8306160077 Public version of Rev 11 to Emergency Plan Implementing Procedure GEP 550-0. "Emergency Equipment & Supplies" & Rev 5 to GEP 550-T1, "Environ Sampling Supplies." Receipt form encl # Commonwealth Edison Co. 83/05/04 Office of Nuclear Reactor Regulation, Director. App 18872-350. 24X Fiche: 50-254, 83/06/07, 8306160071
- P Operating license stage documents & correspondence
- 8306090174 Discusses util interpretation of 10CFR50 49. "Environ Qualification of Electrical Equipment Important to Baffaty for Nuclear Power Plants " Intent of rulemaking is to require upprade program for replacement equipment not parts. FARRAR, D. L. Commonwealth Edison Co. B3/04/03. DENTON, R. Office of Nuclear Reactor Regulation. Director 3pp. 18794.090 24X Fiche; 50-000, 83/04/03, 8304090194
- 8304090227 Informs that response to Generic Ltr 83-08 will be submitted by 830713 Info will include stress repts to determine mod to vacuum breakers on Mark I containments RYBAK, B Commonwealth Edison Co. 83/06/06 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 18796 234 24X Fichs, 50-000, 83/06/06, 8306090227
- 8306160233 Advises that manufacturers whose repts were used in technical evaluation repts re environ qualification of electrical equipment have been contacted List of proprietary pages detailed in util 830513 ltr W/GE affidavit RYBAK,B Commonwealth Edison Co. 83/06/06 DENTON.H R Office of Nuclear Reactor Regulation. Director Spp. 18861, 304. 24X Fiche, 50-000, 83/06/06, 8306160233
- 8306270324 Advises that beta spectra measurements will be conducted at facilities on 830628-27 for NRC project. "Beta Particle Measurement & Dosimetry Requirements at NRC-Licensed Facilities"

 RATHBUN.L.A. Battelle Memorial Institute, Pacific Northwest Laboratory FIN B-2448 83/06/17 KEPPLER.J Q Region 3, Office of Director ip 1874 074. 24X Fiche, 30-234,83/06/17,8306270324,

G Inspection reports: IE Bulletins & correspondence

- B30622021B Ack receipt of B30414 payment of proposed civil penalties Response to notice of violation & proposed imposition of civil penalties will be evaluated & corrective actions examined during future insps AXELRAD, J A Enforcement Staff B3/04/21 REED, C Commonwealth Edison Co 2pp 18950 357 24X Fiche 50-000.83/04/21.830622021B
- 8306030137 Forwards IE Insp Repts 50-254/82-14 & 50-265/82-12 on B30419-20 No noncompliance noted LITTLE: N S Region 3. Office of Director 83/05/17 REED.C Commonwealth Edison Co 2pp 18704 291 24X Fiche 50-254,83/05/17,
- --8306030143 IE Insp Repts 50~254/82-14 & 50~265/83-12 on 830419-20 No noncompliance noted Major areas inspected action re IE Bulletin 80-11, "Masonry Wall Design"
 NORTON, J F , WILLIAKS, C C Region 3, Office of Director 83/05/16 4pp 18704 293 24X Fiche 50~254,83/05/17,8306030139
- 8306010179 Informs of results of NRC review of relief requests from inservice insp requirements Relief granted in part, per encl safety evaluation VARSALLO, D II Operating Reactors Branch R 83/05/19 FARRAR, D L Commonwealth Edison Co Spp 18696 010 R4X Fiche 50-254,83/05/19,830601079
- --830A010182 Safety evaluation supporting in part & denying in part, requests for relief from inservice insp requirements # Office of Nuclear Reactor Regulation, Director 83/05/19 9pp 18696 013 24X Fiche 50-254.03/05/17.830A010179
- --8209200365 "Quad Cities Nuclear Power Station Units 1 & 2 Inservice Insp Program." technical evaluation rept * Science Applications, Inc. NRC-03-82-096 SAI-186-028-30 S2/09/17 NRC NO Datailed Affiliation Given 45pp 18696 023 24% Fiche 50-254.83/05/19.8306010179
- 8305110458 IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in Well Logging Device" Svc list encl TAYLOR, J. M. Division of Safeguards & Inspection Programs (Post 830103) 83/05/26 Consolidated Edison Co. of New York, Inc. 125pp 18831 043 24X Fiche 50-000,83/05/26,8305110458
- 8305110460 IE Info Notice 83-34, "Lyent Notification Info Worksheet," Syc list encl JORDAN, E. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co. of New York, Inc. 115pp 18732 085 24X Fiche 50-000,83/05/26,8305110460.
- 8306130405 Forwards 1E Insp Repts 50~254/83-15 & 50~265/83-13 on 830510-13 No noncompliance noted PAPERIELLO.C J Region 3. Office of Director 83/05/27 REED, C Commonwealth Edison Co 2pp 18823 064 24X Fiche 50~254,83/05/27,8306130405
- --8306130412 IE Insp Repts 80-254/83-15 & 50-265/83-13 on 830510-13 No noncompliance noted Major areas inspected emergency preparathese exercise PHILLIPS M , PLOBKI.T , GLOERSEN.N W Region 3, Office of Director 83/05/27 26pp 18829 066 24X Fiche 50-254,83/05/27,8306130405
- 8305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods Withdrawn at BWRs " Svc list encl JORDAN:E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/31 Consolidated Edison Co. of New York, Inc. 116pp 18732 208. 24X Fiche 50-000,83/05/31,8305110461
- 830404020B Ack receipt of 830405 ltr informing NRC of steps taken to correct violations noted in IC Insp Repts 50-254/82-24 & 50-265/82-28

 8PESSARD, R. L. Division of Engineering 83/05/31 REED. C. Commonwealth Edison Co. ip 18727 351 24X Fichs 50-254, 83/05/31. 8306060208.
- --8306060212 Responds to NRC 830309 1tr re violations noted in IE Insp Repts 50-234/82-24 & 50-265/82-28. Corrective actions onsite review conducted on 830228 documenting computer program used for integrated lask rate test. RYBAK, B Commonwealth Edison Co 83/04/05 KEPPLER, J Q Region 3. Office of Director App. 18727-352 24X Fichs 50-254, 83/05/31,8306060208
- B304070175 Forwards corrected Page 1 to 1E Inap Repts 50-254/83-14 & 30-265/83-12 on B30417-20 No noncompliance noted LITTLE, H S Region 3, Office of Director 83/06/03 REED.C Commonwealth Edison Co ip 18/36 331 24X Fiche 50-254,83/06/03,8306070175

- --8306070190 Corrected Page 1 to IE Insp Repts 50-254/83-14 & 50-265/83-12 on 830419-20 No noncompliance noted Major areas inspected licensee action re IE Bulletin 80-11.

 "Masonry Wall Design "
 NORTON, J F, WILLIAMS, C C Region 3, Office of Director 83/06/02 1p 19736 332 24X Fithe 50-254,83/06/03,8306070175.
- 8306100149 Forwards Rev 3 to "180-Day Rept in Response to IE Bullstin 80-11 for Dresden 2 & 3 & Quad Cities 1 & 2 "
 RYBAK.B Commonwealth Edison Co 83/06/06, KEPPLER, J 9 Region 3, Office of Director 2pp 18804 161 24X Fiche 50-000, 83/06/06, 830640049
- --8306100156 Rev 3 to "180-Day Rept in Response to IE Bulletin 80-11 for Dresden 2 & 3 & Guad Cities 1 & 2" Commonwealth Edison Co 83/05/09. 129pp 18804 163. 24K Fiche 50-000.83/05/06.8306100149
- B306100094 Forwards response to IE Bulletin 83-09 re diesel generator cooling water check valves Plants utilize Mission Duo-Check valves employing hings-to-pin design for protection against vibration-induced failure
 BARNEB.P.L. Commonwealth Edison Co. 83/06/07. KEPPLER.J.O. Region 3, Office of Director 7pp 18802 238 24% Fiche: 50-000, 83/06/07, 830410084
- 830A170380 Forwards response to IE Bulletin 83-03 re diesel generator cooling water check valves Valves at Dresden & LeBalle acceptable w/o further insp Rept on valve failures at Quad Cities will be submitted within 90 days of insp completion.

 BARNES, P. L. Commonwealth Edison Co. 83/06/07. KEPPLER, J. Q. Region 3, Office of Director 7pp 18880 211 24X Fiche: 50-000, 83/06/07, 830A170360
- 8305110464 IE Info Notice 83-36, "Impact of Security Practices on Safe Operations " Syc list encl JURDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/09 Consolidated Edison Co. of New York, Inc. 119pp, 18830-280 24X Fiche: 50-000,83/06/09,8305110464.
- 8305110470 IE Info Notice 83-38, "Defective Heat Sink Adhesive & Beismically Induced Chatter in Relays Within Printed Circuit Cards" Byc list encl JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co. of New York, Inc. 118pp 18920 225 24X Fiche 50-000,83/06/13,8305110470.
- 8306090010 IE Info Notice 83-37. "Transformer Failure Resulting From Degraded Internal Connection Cables " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co of New York. Inc 243pp 18921 001 24X Fiche 50-000,83/06/13,8306090010
- B306220067 Summerizes revised schedule for util review of automated analytical instrumentation sys multiplet analysis capability per IE losp Repts 50-254/62-13 & 50-265/62-15 RYBAK. B Commonwealth Edison Co. 83/06/13. PAPERIELLO.C. J. Region 3. Office of Director. 2pp. 18926-180. 24% Fiche.50-254,83/04/13,8306220067
- 8306300235 Forwards IE Insp Repts 50-237/83-12.50-249/83-10.
 50-254/83-13 & 50-265/83-11 on 820412-14 & 0506 & 16 k
 notice of violation
 LITLE.W 8 Region 3. Office of Director 83/06/16 REED.C.
 Commonwealth Edison Co 2pp 19122-279 24X Fiche: 50-000, 83/06/16.
- --8306300238 Notice of violation from inep on 830412-14 & 0506 & 16, LITTLE,W B Region 3, Office of Director. 83/06/16, 2pp, 19122 281, 24X Fiche:50-000,83/06/16,8306300235.
- --8306300246 IE Insp Rapts 50-237/83-12, 50-249/83-10, 50-254/83-13 & 50-265/83-11 on 830412-14 & 0506 & 16 Noncompliance noted as-built confinguration (for pipe anchon Ri33 in pressure suppression sys) differed from original design. YIN.I, T. Region 3. Office of Director. 83706/15, 9pp. 19122-283. 24X Fiche 50-000,83706/16,83063000235.
- 8306220028 Ack receipt of 830509 ltr informing NRC of steps taken to correct viglations noted in IE lnsp Repts 50-254/82-26 & 50-255/82-26 KEPPLER, J. G. Region 3, Office of Director 83/06/17, REED, C. Commonwealth Edison Co. 1p 18730 036, 24X Fichs, 50-254, 83/06/17, 8306220028.
- --8306220034 Responds to NRC 830411 ltr re violations noted in IE Insp Repts 50-254/82-26 & 50-265/82-26 Corrective actions.startup procedure revised to include sign-off space verifying alarm has cleared REED.C Commonwealth Edison Co 83/05/09. Director's Office. Office of Inspection and Enforcement. 7pp. 18930:037. 24X Fichs 50-254.83/06/17.8306220028.

- 8305110475 IE Info Notice 83-40. "Need to Environmentally Qualify Epoing Oracles & Sealers " Sec list enc!

 JORDAN, E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/06/22 Consolidated Edison Co Response (Post B30103) 83/06/22 Consolidated Edison Co of New York, Inc. 115pp. 19021:179 24X Fiche:50-000.B3/06/22.B305110475
- 8305110477 IE Info Notice 83-41, "Actuation of Fire Suppression Sys Causing Inoperability of Safety-Related Equipment," Svc list enci JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/22 Consolidated Edison Co. of New York, Inc. 120pp 18997 007 24X Fichs 50-000, 83/06/22, 8305110477
- 8305110479 IE Info Notice 83-42, "Reactor Mode Switch Malfunctions " Sve list encl JORDAN, E. L. : Svc list enc: JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/23 Consolidated Edison Co. of New York, Inc. 116pp 18796:242 24X Fiche 50-000,83/06/23,8305110479
- 8305110483 IE Info Notice 83-43, "Improper Settings of Intermediate Range (IR) High Flux Trip Betpoints." Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/24 Consolidated Edison Co. of New York, Inc. 116pp. 19046:297. 24X Fiche: 50-000,83/06/24,8305110483.
- R. Periodic operating reports & related correspondence
- 8306170314 Monthly operating repts for Hay 1983. W/B30606 ltr WEINFURTER, E., MIBAK, A., KALIVIANAKIB, N. Commonwealth Edison Co. 83/06/06. Director's Office. Office of Inspection and Enforcement 22pp. 18877:042. 24X Fichs 50-254.83/06/06.8306170314.
- 8. Reportable occurrences, LERs & related correspondence
- 8306170344 LER 83-008/03L-0.on 830520.RHR pump 28 room watertight door could not be shut tightly Caused by bent pivot arm. Arm repaired & RHR 8 loop declared operable. W/830607 ltr. EAGLE, J., KALIVIANAKIS, N. Commonwealth Edison Co. 83/06/07 KEPPLER, J. Region 3, Office of Director 2pp. 18880-291. 24X Ficae. 30-265, 83/06/07, 8306170344.
- 8306270282 Potential Part 21 rept re discrepancy in welding of turnbuckle assembly turnbuckle-bolt interface & on top plats assembly variable springs. 8A307 Grade B bolts not ASME Section IX matl. Investigation underway KARAGIANIB. J. A. Elsen Metal Products Co. 83/06/17 KEPPLET Region 3. Office of Director 2pp. 18996: 207. 24X Fichs: 50-000.83/06/17,8306270282.
- DOCKET 50-266 POINT BEACH NUCLEAR PLANT, UNIT 1
- F. Becurity, medical, emergency & fire protection plans
- 8306020199 Requests route approval for irradiated fuel shipments from QE Morris facility at Morris, IL to reactor site in Twa Rivers.WI. Bafeguards info withheld (ref 10CR72 21).

 DANEBE, F. L. Nuclear Assurance Corp. 83/05/10 HILLMAN, C. D. of Bafeguards 3ep. 18701:064 24X Fichs. 50-266, 83/05/10, 8306020199.
- 8306060156 Provides update to 830428 ltr re mods proposed to support App R exemption requests, based on 830523 insp of Unit 2 A05 & A06 switchgear cabinets.
 FAY.C.W. Hisconsin Electric Power Co. B3/05/31. DENTON.H.R Office of Nuclear Reactor Regulation, Director, CLARK.R.A Operating Reactors Branch 3 2pp. 18728 103, 24X Fiche: 50-266, 83/05/31, 8306060136,
- 8306140218 Responds to 830510 request for approval for shipment of spent reactor fuel from Morris, IL to facility. Route approved ger 100FR73, 37. Sanitized data re arrangements & approved per 100FN/3.37. Denivious action for the following stanch.
 BHERR, T. B. Material Transfer Safeguards Licensing Branch.
 DAMESE, F. L. Nuclear Assurance Corp. 7pp. 18844.315. 2
 Fichs: 50-266, 83/06/02, 8306140218. 83/06/02.
- 8306090177 Ack receipt of 830408 & 0523 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-266/83-01 & 50-301/83-01. PAPERIELLO, C. J. Region 3. Office of Director. 83/06/06 BURSTEIN S. Wisconsin Electric Power Co. ip. 18796:081. 24X Fiche: 50-266,83/06/06,8306090177.
- --8306070185 Responds to NRC 830308 ltr re violations noted in IE Insp Repts 50-266/83-01 & 50-301/83-01 Notice of violation imagpropriately based on implementation of listed (tems. Fifteen-minute notifications inconsistent w/minor syents FAV.C. W. Wisconsin Electric Power Co. 83/04/08. KEPPLER, J 0 Region 3, Office of Director. 3pp 18796:082, 24X Fiche: 50-266,83/06/06,8306090177.

- 8306130447 Notifies that LASL vital area analysis program personnel will reanalyze original sites visited during early stages of program Revist necessary to gather addl info due to major mode & redirection by NRC HIND, J A Division of Radiological & Materials Safety Programs 83/06/08 BURSTEIN.S Wisconstin Ejectric Fower Co 2pp 18821 209 24X Fiche 50-266.83/06/08.8306130447
- B3D6130431 Forwards SER re compliance w/NUREG-0737. Item III A t 2. "Min Staffing Levels for Emergency Bituations " Provisions for onshift staffing & augmentation acceptable HIND. J A Division of Radiological & Materials Safety Programs B3/06/10, BURBTEIN.S Wisconsin Electric Power Co Bpp 18821 215 24X Fiche 50-266,83/06/10,8306130431
- 8306210100 Responds to 830603 ltr advising of status of util request to locate emergency operations facility at corporate headquarters in Milwaukee.WI New communication apparatus & revised procedures enhance emergency capabilities FAY.C W Wisconsin Electric Power Co 83/06/16 DEYDUNG,R C Director's Office, Office of Inspection and Enforcement 2pp 18914 138 24X Fiche 50-266,83/06/16,8306210100
- 8306230356 Ack receipt of NRC 830603 ltr re status of util request to locate emergency operations facility (EOF) at corporate headquarters in Milwaykes MI Past communication difficulties unrelated to divided EOF concept unrelated to divided EOF concept
 FAY.C W Wisconsin Electric Power Co 83/06/16 DEYDUNG,R C
 Director's Diffice, Office of Inspection and Enforcement 2pp
 18743 317 24% Fiche 50-266,83/06/16,8306230356
- Adjudicatory correspondence
- 8304090298 Order extending time until 830708 for Commission to act to review ALAB-719
 CHILK, 9 J Office of the Secretary of the Commission. 83/
 Commissioners 1p. 18795 237 24X Fiche 50-266,83/06/07,
- J Insurance & indemnity information
- 8306070404 Forwards Endorsement 71 to NELIA Policy NF-178 & Endorsement 58 to MAELU Policy MF-53
 DUNDAS: H J Hisconsin Electric Power Co 83/05/18 Antitrust & Economic analysis Branch (Utility Finance). 3pp 18741 352, 24X
 Fiche 50-266,83/05/18,8306070404
- P Operating license stage documents & correspondence
- 8306010428 Advises of failure to complete installation & place in operation portions of radioactive monitoring equipment for compliance w/NUREO-0737. Item II.F 1 i, "Noble Gas Monitoring " Completion expected by 830630 FAY.C H Hisconsin Electric Power Co. 83/05/25 DENTON, H. R. Office of Muclear Reactor Regulation, Director. CLARK, R A Operating Reactors Branch 3 3pp 18679 321 24X Fiche 50-266,83/05/25,8306010428,
- B30610001B Requests route approval for irradiated fuel shipments from West Valley, NY to Two Rivers. WI.

 DANESE. F. L. Nuclear Assurance Corp. B3/05/26 HILLMAN, C. Divisiof Bafeguards 3pp. 18815.306 24X Fiche.50-264.83/05/26, B306100018 HILLMAN, C. Division
- 8304070084 Provides results of chlorine, boron & pH analyses performed for chemical test matrix per NUREO-0737. Item II B 3, Criterion i0, to demonstrate analytical capabilities in presence of interfering ion concentrations FAY, C W Misconein Electric Power Co 83/06/03 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 18737 350 24X Fiche, 50-266, 83/06/03, 8306070086
- 8306200267 Forwards latest rev of FSAR Section 1 B.describing QA program.per 10CFR90 54(a)(2) Changes do not reduce QA program commitments previously accepted by NRC Bubstantive changes summarised.

 FAY.C W. Misconsin Electric Power Co 83/06/10, KEPPLER, J Q Region G. Office of Director 36pp 18901.063 24% Fiche 50-266,83/06/10,8306200267
- 8306200260 Informs of further delay in implementing post-TMI-related issues due to delay in shipment of auxiliary safety instrumentation panels from vendor in response to 830314 response to 830314 order or Management of 830314 order FAY.C W Hisconsin Electric Power Co 83/06/16 DENTON. Office of Nuclear Reactor Regulation. Director CLARK,R A Operating Reactors Branch 3 4pp 18901 173 24X Fiche: 50-266,83/06/16,8306200260.

- 830.6210091 Requests mod to WPDES Permit WI-0000957-2, removing pH limitations on sewage treatment plant & retention pond effluents Mod will allow operation of plant & pond w/reduced additions of dissolved solids to environ LINGLE.J W Wisconsin Electric Pawer Co 83/06/16 Wisconsin Electric Pawer Co 83/06/16 Wisconsin State of 3pp 18914 088 24X Fiche 50-266.83/06/16.8306210091
- 8306270275 Requests mod to WPDES Permit WI-0000957-2 to remove pH limitations on sewage treatment plant & retention pond effluents Removal of limits will allow operation w/reduced additions of dissolved solids to environ LINGLE, J W Wisconsin Electric Power Co 83/06/16 Wisconsin State of 2pp 18996 170 24X Fiche 50-266.83/06/16.8306270275
- 8306280443 Proposes hardware mod to ensure automatic initiation of auxiliary feedwater flow to affected operating unit w/o operator action Mod only affects motor driven auxiliary feedwater pumps & motor-operated isolation valves FAY, C H Wisconsin Electric Power Co 83/06/20 DENTON, H R Office of Nuclear Reactor Regulation, Director CLARK, R A Operating Reactors Branch 3 3pp 19019 174 24X Fiche 50-266,83/06/20,8306280443
- 8306270146 Informs that util response to NUREQ-0737. Items II F 1 4, II F 1 5 & II F 1 6 acceptable re installation of containment pressure, water level & hydrogen monitoring sys. SER encl CLARK, R A Operating Reactors Branch 3 83/06/21 FAY, C W Wisconsin Electric Power Co Bpp 17046 258 24X Fiche 50-266.83/06/21.8306290146
- 8306280397 Requests extension of deadline for certain environ qualification items, listed in SER in Categories II A II C. until 3 months after meeting held to renolve deficiencies BURSTEIN, S Wisconsin Electric Power Co 63/06/22 DENTON, H R Office of Nuclear Reactor Regulation, Director CLARK, R A Operating Reactors Branch 3 2pp 17001 359 24X Fiche 50-266,83/06/22,8306280397
- Q Inspection reports. IE Bulletins & correspondence
- 8305110458 IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in Well Logging Device" Syc list encl TAYLOR, J M Division of Bafeguards & Inspection Programs (Post 830103) 83/05/26. Consolidated Edison Co of New York, Inc. 125pp 18831 043 24X Fiche 50-000,83/05/26,8305110458
- 8305110460 IE Info Notice 83-34. "Event Notification Info Worksheet"
 Svc list encl
 JORDAN, C L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/05/26 Consolidated Edison Co of New
 York, Inc 115pp 18732 085 24X Fiche 50-000, 83/05/26, 8305110460
- 8305110461 IE Info Notice 83-95, "Fuel Movement W/Control Rods Withdrawn at BWRs " Svc list encl JORDAN E. L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/31 Consolidated Edison Co of New York, Inc 116pp 18732 208 24X Fiche 50-000,83/05/31,8305110461
- 8306070324 Confirms 830616 meeting w/util at Region III ofc to discuss SALP Interested parties should submit advance notification by 830613
 NORELIUS, C E Division of Project & Resident Programs 83/06/01
 BURSTEIN, S Hisconsin Electric Power Co ip 18746-080 24X
 Fiche 50-266,83/06/01.8306070324
- B304090177 Ack receipt of B3040B & 0523 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-266/83-01 & 50-301/83-01 PAPERIELLO, C. J. Region 3. Office of Director. B3/06/06 BURSTEIN. B. Wisconsin Electric Power Co. 1p. 18796 081 24X Fiche 50-266, 83/06/06, 8306090177
- --8306090185 Responds to NRC 830308 ltr re violations noted in IE Insp Repts 50-264/83-01 & 50-301/83-01. Notice of violation imappropriately based on implementation of listed items Fifteen-minute notifications inconsistent w/minor events. FAY, C. W. Wisconsin Electric Power Co 83/04/08 KEPPLER, J & Region 3, Office of Director 3pp. 18796 082. 24X Fichs 50-266.83/06/06.8306070177.
- 8306i30i46 Advises that no check valves installed in flow path of cooling water for diesel generators in response to IE Bulletin 83-03 re check valve failures in raw water cooling sys of diesel generators

 BURSTEIN 8. Wisconsin Electric Power Co. 83/06/06, KEPPLER, J & Region 3, Office of Director. ip 18824:277 24X

 Fiche 50-266,63/06/06.8306i30i46

- 9305110464 IE Info Notice 83-36. "Impact of Security Practices on Safe Operations "Svc list and JORDAN, E L Division of Emergency Preparadness & Engineering Response (Post 930103) 83/06/09 Consolidated Edison Co of New York, Inc 117pp 18830 280 24X Fiche 50-000,83/06/09,8305110464
- 8306230274 Forwards IE Insp Repts 50-266/83-10 & 50-301/83-10 on B30523-26 No noncompliance noted STREETER. J F Region 3. Office of Director 83/06/10 BURBTEIN, S. Wisconsin Electric Power Co 2pp 18745 127 24X Fiche 50-266,83/06/10,8306230274
- --8306230R79 IE Insp Repts 50-266/83-10 & 50-301/83-10 on 830523-26 No moncompliance noted Major areas inspected nonlicensed personnel training & licensed personnel training & licensed personnel requalification programs

 HABBE, R A . HAHKINS, F C Region 3, Office of Director 83/06/10, 4pp 18945 131 24% Fiche 50-266,83/06/10,8306230274
- 8305110470 IE Info Notice 83-38, "Defective Heat Bink Adhesive & Seismically Induced Chatter in Relays Within Printed Circuit Cards " Svc list encl JURDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co of New York, Inc. 118pp 18920 225 24X Fiche: 50-000, 83/06/13, 8305110470,
- 8304090010 IE Info Notice 83-37, "Transformer Failure Resulting From Degraded Internal Connection Cables" Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co. of New York, Inc. 243pp 18921 001, 24% Ficher 50-000, 83/06/13, 8306090010.
- 8306230260 Ack receipt of 830525 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-266/83-04 & 50-301/83-04
 NORELIUB, C E Division of Project & Resident Programs. 83/06/20. BURSTEIN 8 Hisconsin Electric Power Co 1p 18945: 072 24X
 Fiche 50-266,83/06/20,8306230260
- --8306230261 Responds to NRC 830425 ltr re violations noted in IE Insp Repts 50-266/83-04 & 50-301/83-04. Corrective actions: Procedure HF 2 4 re containment entry check-in/check-out sys deleted on 830520 FAV.C W Misconsin Electric Power Co 83/05/25 KEPPLER, J 9. Region 3. Office of Director 2pp 18945-073. 24X Fiche, 50-266, 83/06/20, 8306230260
- 8305110475 IE Info Notice 83-40, "Need to Environmentally Qualify Epoxy Grouts & Sealers " Syc list encl. JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/22 Consolidated Edison Co. of New York, Inc. 115pp 19021 179 24X Fiche: 50-000, 83/06/22, 8305:10475.
- 8305110477 IE Info Notice 83-41. "Actuation of Fire Suppression Sys Causing Inoperability of Safety-Related Equipment." Syc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/22. Consolidated Edison Co. of New York, Inc. 120pp 18997 007. 24% Fiche: 50-000.83/06/22.8305110477.
- 8305110479 IE Info Notice 83-42, "Reactor Mode Switch Malfunctions " Svc list and J JORDAN, E. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/23 Consolidated Edison Co. of New York, Inc. 116pp. 18996.242 24X Ficher 50-000,83/06/23,8305110479.
- 8305110483 IE Info Notice 83-43, "Improper Bettings of Intermediate Range (IR) High Flux Trip Betpoints " Svc list enc! JURDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/24, Consolidated Edison Co. of New York, Inc. 114pp 19046;297 R4X Fiche: 50-000, 83/06/24, 8305110483.
- R. Periodic operating reports & related correspondence
- 8304200137 Monthly operating repts for May 1983 W/830413 ltr. FAY.C W Wisconsin Electric Power Co 83/06/06 9pp. 18901:046. 24X Fiche. 50-266, 83/06/06, 8306200137.
- S Reportable occurrences, LERs & related correspondence
- 8305020208 Forwards LER 83-003/017-0. BURBTEIN:8 Wisconsin Electric Power Co. 83/04/17 KEPPLER, J. C. Region 3. Office of Director ip 18277. 271. 24X Fiche:50-266, 83/04/19. 8305020288.

- --8305020231 LER 83-003/017-0 on 830406, critical control power failure alarm received Caused by breakers accidentally opened by contractor personnel setting up to pull wires for control board mods Breakers closed FAY,C.W Misconsin Electric Power Co 83/04/19 Region 3. Office of Director. 2pp 18277 272 24X Fiche 50-266.83/04/19, 8308020208
- 8306060078 NPDES noncompliance.on 830525.daily max pH effluent limit exceeded Util commenced investigation of incident Ltr to be sent to Dept of Natural Resources outlining results & corrective action FAYLC W Wisconsin Electric Power Co 83/05/27 Wisconsin, State of 1p 18723 022, 24% Fiche 50-266.83/05/27.8306060078
- 8306300058 NPDES noncompliance notification on 830525, pH of retention pord discharge exceeded limits Caused by leaks in retaining board used to sighon sludge from pond to discharge Leaks repaired on 830526 FAY.C W Hisconsin Electric Power Co 83/06/23 Wisconsin, State of 1p 19120 237 24X Fichs 50-266.83/06/23,8306300058
- DOCKET 50-267 FORT ST. VRAIN NUCLEAR GENERATING STATION

 F Security, medical, emergency & fire protection plans
- 8306300104 Forwards exclusion area boundary, emergency planning zone survey team inventory, listed in Health Physics Procedure HPP-37 & Surveillance Procedure SR-HE-3-8A, in response to NRC 821102 let & IE Insy Rept 50-267/82-14.

 LEE.O.R Public Service Co of Colorado 82/11/17, MADSEN, 0 L. Region 4, Office of Director 4pp 17048:222 24X Fiche, 50-267/82/11/17, 8306300104.
- ---8306300107 Rev 15 to Health Physics Procedure HPP-37, "Radiological Emergency Respiratory Protection Inventory List" + Public Service Co of Colorado 82/10/01 14pp. 19048, 226 24% Fichs 50-267.82/11/17,8306300104
- --8306300iii Rev 1 to Surveillance Procedure SR-HE-3-BA, "Radiation Protection Dept - On/Offsite Emergency Monitoring Exercise," * Public Service Co of Colorado 82/09/30 7pp 19048, 240. 24X Fiche 50-267-82/11/17,8306300104
- 8304010293 Extends invitation to attend 830417 masting in Denver, CO to discuss various emergency planning & preparedness topics including NRC.FEMA.State of CO & Weld County roles in emergency response & evaluation COLLINS.J. T Region 4. Office of Director. 83/05/25, LEE, O R. Public Service Co. of Colorado 2pp 18672, 198 24X Fiche. 50~267, 83/05/25, 8304010293
- 8306070199 Forwards responses to open items in IE Emergency Preparedness Appraisal Rept 50-267/83-03 HEPA & charcoal filter equipment installed on technical support ctr ventilation sys MARCHBOURG, D W Public Service Co of Colorado, 83/05/27, COLLINS.J.T Region 4, Office of Director, 21pp. 18747-095, 24X Fiche 50-267,83/05/27,8306070199
- 8306140277 Requests remittance of Class II feet for review of 820420, 0914 & 830407 applications of review committee, shift staffing & fire protection. Basis for fee determination discussed MILLER.W.O. License Fee Management Branch. 83/05/31 LEE.O.R. Public Service Co. of Colorado. 2pp 18844.306. 24X Fiche 50-247,83/05/31,8306140277.
- 8306130459 Recommends License DPR-34 be amended incorporating 830328 rays to security plan Copy of response to licenses requested.

 EIBENAUT, D © Division of Licensing. 83/06/06, 0A0LIARDD, J. E Division of Resident, Reactor Project & Engineering Programs ReppiB830:174, 24X Fichs. 50-267, 83/06/06, 8306130459,
- 8306210368 Releases public version of revised emergency plan implementing procedures FELTON.J.M. Division of Rules and Records 83/06/06 Document Hanagement Branch 1p. 16937:090, 24X Fiche: 50-267, 83/06/06, 8306210368
- --8304210373 Forwards public version of revised emergency plan implementing procedures, including Procedures RERP Phone List re Issue 17. RERP-CR-UE re Issue 18 & RERP-CR-ALERT re Issue 18 Who encis.

 MARCHBOURG, D. W. Public Service Co. of Colorado.
 COLLING, J. T. Region 4. Office of Director. 3pp 18937:091, 24X Fiche. 50-267. 83/05/06. 8306210368

- 8306300130 Ack receipt of 830506 ltr re 830331 natice of deviation contained in IE Insp Rept 50-267/83-03 implementation of corrective actions will be reviewed during future insp Emergency plan procedures must be clarified MADEEN.0 L. Region 4. Office of Director 83/06/06 LEE.0 R Public Service Co of Colorado 2pp 19122 329 24X Fiche \$0-267.83/06/06,8306300130
- B306300059 Forwards corrected pages to radiological emergency exercise scheduled for B30615
 HAREMBQURG,D H Public Service Co of Colorado B3/06/07
 HONTGQUERY,J . COLLINS,J T Region 4. Office of Director lipp
 19120 R79. 24X Fiche 50-267,69/06/07.8306300059
- P Operating license stage documents & correspondence
- 830&010335 Responds to NRC 830&13 order re environ qualification of safety-related electrical equipment, per 10CFR50 49 Environ qualification records audit will be completed by 831231 LEE, O R Public Service Co of Colorado 83/05/17 COLLINS, J T Region 4, Office of Director 8pp 18881 279 24x Fiche: \$0-267,83/05/17.830&0103355
- 8304070103 Forwards "Results of PGX Graphite Surveillance, Fort St Vraim," per Tech Spec SR5 2 2P BREY.H L. Public Service Co of Colorado 83/05/19 COLLINS, J T Region 4, Office of Director 2pp 18738 284 24X Fiche 50-267,83/05/19.8304070103
- --8306070106 "Results of POX Graphite Surveillance,Fort St Vrain "
 BEAVAN,L A Public Service Co of Colorado 906624 82/10/21
 59pp 18738 286 24% Fiche 50-267,83/05/19,8306070103
- 8304010343 Forwards application for amend to License DPR-34, revising App A Tach Space to inservice surveillance requirements for snubbers in secondary RCS LEE, O R Public Service Co of Colorado 83/05/20 CDLLING, J T. Region 4, Office of Director 2pp 18681 293 24X Fichs \$0-267,83/05/20,8304010343
- --8304010344 Application for amend to License DPR-34, revising App A Tech Specs 4.3 & 5 3 re inservice surveillance requirements for snubbers in secondary RCB LEG. OR. Public Service Co of Colorado 83/05/20 2pp 18481-275 24X Fiche 50-247,83/05/20.8304010343
- --8306010345 Proposed Tech Specs 4 3 & 5 3 re inservice surveillance requirements for snubbers in secondary RCB * Public Service Co of Colorado 83/05/20 37pp i8681.277.24X Fiche 50-267,83/05/20,8306010343
- 8306010411 Forwards application to amend License DPR-34, revising App B. environ protection plan (nonradiological), Tech Specs LEE.C R Public Service Co of Colorado 83/05/20, COLLINB, J T Region 4. Office of Director Spp 18679 341 24X Fiche: 50-267, 83/05/20, 8306010411
- --8306010416 Application to amend License DPR-34, revising App B. environ protection plan (nonradiological), Tech Specs LEE, Q R Public Service Co. of Colorado 83/05/20 2pp 18679 344 24X Fiche 50-267, 83/05/20, 8306010411
- ---B306010419 App B Tech Specs re environ protection plan (nonradialogical) * Public Service Co of Colorado B3/05/20 12pp 18679, 346 24X Fiche 50-267, 83/05/20, 8306010411
- B304040130 Forwards payment of free for review of amend to License DFR-34, changing Tech Spec Section 4 4 1 WAREMEDURG, D. Public Service Co. of Colorado. B3/05/24 COLLING, J. T. Region 4, Office of Director. 2pp. 18719.007 24X Fiche 50-267, B3/05/24, B306060130
- 8306070319 Advises that add1 requirements incorporated in Tech Specs w/Amend 28 issued on 821015, assuring acceptable percent region peaking factor surveillance Further changes not necessary MADBEN.O L. Region 4. Office of Director 83/05/26 LEE,O R Public Service Co of Colorado. Rpp 18746-061 24X Fiche 80-247,83/05/26,8306070319
- 8306140279 Requests remittance of Class II fees for review of 820420, OP14 & 830407 applications re review committee shift staffing & fire protection. Basis for fee determination discussed MILLER, W D License Fee Management Branch. 89/05/31. LEE, O R. Public Service Co. of Colorado. 2pp. 18844-306. 24X Fiche: 50-267, 83/05/31, 8306140279.

- 8306060139 Requests FR publication of notice of consideration amending License DPR-34 re radiological effluents & proposed no significant hazards consideration determination & opportunity for hearing MADSEN, 0 L Region 4. Office of Director 83/06/01 CLARK, R A Operating Reactors Branch 3 3pp 13719 019 24X Fiche 50-267.83/06/01.8306060139
- 8306160286 Outlines plan to complete review & update Tech Spec requirements for inservice insp & testing pertaining to other reactor auxiliary & support sys that perform safety function for postulated design basis events BREY.H L. Public Service Co of Colorada 83/06/01 COLLINS.J T Region 4. Office of Director 2pp 18861 011, 24X Fiche 50-267.83/06/01.8306160286
- B305160541 Forwards GA Co Repts 905505, 906577 & GA-A16B29 describing results of exams on fuel elements w/cracked webs Repts convey belief that cracks in fuel block graphite webbing do not intersect fuel holes

 BREY, H L Public Service Co of Colorada 83/06/02 COLLINS, J T Region 4, Office of Director 1p 18865 148 24X

 Piche 50-267, 83/06/02, 8306160541
- ---8306160545 "NDE of Fort St Vrain Fuel Element 1-2415 "
 SAURWEIN, J J 9A Technologies, Inc /General Atomic Co. 904505
 82/05/17 7pp 18845 149 24X Fiche 50-247,83/06/02,8306160541
- --8306160860 "Visual Exam Results of Segment 2.Fort St Vrain Fuel Elements 1-2415.1-0172,2-2693.1-0108 & 5-0801 " KETTEVER,J W GA Technologies, Inc /Oeneral Atomic Co. 906577 83/04/04. 21pp 18865 158 24% Fiche:50-267.83/06/02.8306160841
- --8306160564 "NDE of 54 Fuel & Reflector Elements From Fort St Vrain Core Segment 2 "
 SAURMEIN, J. J. GA Technologies, Inc./General Atomic Co. GA-A16829 82/10/31 196pp 18865 179 24X Fiche 50-267,83/06/02, 8306160541
- 8306280354 Submits list of NRC & in-house project electrical commitments
 BREY.H L Public Service Co of Colorado 83/06/03 WAONER,P
 Region 4. Office of Director 3pp 19001 269 24X
 Fiche 50-267,83/06/03,8306280354
- 8306090344 Ack receipt of 830520 application to change Tech Specs re hydraulic snubber testing & surveillance requirements for mechanical snubbers Payment of Class III fee requested. DIGOB, R M License Fee Management Branch. 83/06/06 LEE.O R. Public Service Co. of Colorado. 1p. 18797, 109, 24X Fichs. 50-267, 83/06/06.8306090344
- 8306280343 Forwards description of changes incorporated in updated FSAR, GA program through Amend 32 & of changes to updated FSAR GA program since 830311 Changes since 830311 will be included in Jul 1983 FBAR rev

 LEE, O R Public Service Co of Colorado, 83/06/09, COLLINS, J. T Region 4. Office of Director 20pp 17001.240 24X

 Fiche 50-267,83/06/09,8306280343
- H306140733 Forwards amend fees re B30407 & 19 applications for license amends WAREMBOURG, D. W. Public Bervice Co. of Colorado, B3/06/10 MILLER, W. D. License Fee Management Branch. 1p 18841:091 24X Fiche. 50-267, 83/06/10, 8306140733
- 8306160220 Requests publication in monthly FR of notice of consideration of issuance of amend to License DPR-34 & proposed no significant hazards consideration determination & opportunity for hearing MADSEN, 9 L. Region 4. Office of Director 83/06/10 CLARK, R. A. Operating Reactors Branch 3 2pp 18861, 300, 24X Fiche 50-267, 83/06/10.8306160220.
- G Inspection reports, IE Bulletins & correspondence
- 830&300104 Forwards exclusion area boundary, emergency planning zone survey team inventory, listed in Health Physics Procedure HPP-37 & Burveillance Procedure SR-HE-3-SA, in response to NRC 821102 ltr & IE Insp Rept 50-267/82-14

 LEE, O R Public Service Cg of Colorado. 82/11/17 MADSEN, Q L. Region 4, Office of Director App 17048-222, 24X

 Fiche 50-267, 82/11/17, 8306300104
- --8306300107 Rev 15 to Health Physics Procedure HPP-37, "Radiological Emergency Respiratory Protection Inventory List" * Public Service Co of Colorado, 82/10/01, 14pp. 19048-226. 24X Fiche 50-267,82/11/17,8306300104

- --8306300111 Rev 1 to Surveillance Protedure SR-HE-3-8A. "Radiction Protection Dept On/Offsite Emergency Monitoring Exercise."

 *** Public Service Co of Colorado 82/07/30 7pp 19048-240 24% Fiche 50-267.82/11/17,8306300104
- 8306080042 Forwards IE Insp Rept 50-267/82-29 on 821213-17 No noncompliance noted MADBEN.O L Region 4. Office of Director 83/03/21 LEE.D.R. Public Service Co of Colorado 3pp 18773 151, 24X Fiche 50-267.83/03/21.8306080042
- --B3060B0046 IE Insp Rept 50-267/B2-29 on B21213-17 No noncompliance noted Major areas inspected radiochemistry program including staffing training program, sample collection, sample treatment & analysis & lab instrument calibr NICHOLABIJ B., WIBELR: MURRAY.B. Region 4. Office of Director B3/02/24 20pp. 18773 155. 24X Fiche 50-267,83/03/21,83060B0042
- 8306010132 Forwards IE Insp Rept 50-267/83-09 on 830411-15 & notice of violation MADSEN, GL Region 4, Office of Director 83/05/14 LEE, O R. Public Service Co of Colorado 2pp 18674 025 24X Fiche: 50-267, 83/05/14, 8306010132
- --8306010135 Notice of violation from insp on 830411-15 * Region 4, Office of Director 83/05/14 2pp. 18674 027, 24% Fiche 50-267, 83/05/14, 8306010132
- --8306010141 IE Insp Rept 50-267/83-09 on 830411-15 Noncompliance noted; failure to follow Procedures GCIM-1 & Gi2 ra GC/GA dept measuring & test equipment program & results.
 REDANO,R T , WESTERMAN,T.F. Region 4, Office of Director 83/05/13 12pp 18674 029 24X Fiche 50-267,83/05/14,8306010132
- 8304010335 Responds to NRC 830413 order re-environ qualification of safety-related electrical equipment per 100FR80 49 Environ qualification records audit will be completed by 831231 LEE.O R Public Bervice Co of Colorado 83/05/17. COLLINS, J. T. Region 4. Office of Director. 8pp 18681.279. 24X Fiche 50-267.83/05/17.830&010335
- 8304040125 Forwards IE Insp Rept 50-R47/83-10 on 830401-30 No noncompliance noted MADSEN, Q.L. Region 4, Office of Director 83/05/20, LEE, Q, R Public Service Co of Colorado 2pp. 18722; 289, 24X Fiche 50-267, 83/05/20, 8304040125.
- --8306060126 IE Insp Rept 50-267/83-10 on 830401-30 No noncompliance noted Major areas inspected operational safety verification, surveillance, maint, bulletin followup, followup of previous insp findings & review of periodic & special repts.

 DICKERSON.H W., PLUMLEE, G. L., WEBTERMAN, T. F. Region 4, Office of Director B3/05/19 7.9p. 18722;291 24X Fiche: 50-267,83/05/20,8306060125
- 8305110458 IE Info Notice 83-32. "Ruptured Am-241 Sources Contained in Well Logging Device" Svc list encl. TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/05/26 Consolidated Edison Co. of New York, Inc. 125pp. 18831:043 24X Fiche 50-000,83/05/26.8305110458
- 8303110460 IE Info Notice 83-34, "Event Notification Info Workshept."
 Svc list encl
 JURDON.E L Division of Emergency Preparedness & Engineering
 Response (Post 830103). 83/05/26 Consolidated Edison Co. of New
 York, Inc. 115pp 18732 085 24X Fiche. 50-000, 83/05/26, 8305110460.
- 830A070199 Forwards responses to open items in IE Emergency Preparedness Appraisal Rept 50-267/83-03, HEPA & charcosl filter equipment installed on technical support ctr ventilation sys. WAREMBURG, D. W. Public Service Co of Colorado 83/05/27. COLLING J. T. Region 4, Office of Director. 21pp. 18747:095 24X Fiche: 50-267,83/05/27,8304070199.
- 8305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods Withdrawn at BWRs." Svc list encl.
 JORDANIE L Division of Emergency Preparedness & Engineering Response (Post 8030103) 83/05/31. Consolidated Edison Co. of New York, Inc. 116pp. 18732: 208, RAX Fiche. 50-000, 83/05/31, 8305110461.
- 6306160286 Dutlines plan to complete review & update Tech Spec requirements for inservice insp & testing pertaining to other reactor auxiliary & support sys that perform safety function for postulated design basis events.

 88EY.H L. Public Service Co. of Colorado. 83/06/01. COLLING.J.T. Region 4. Office of Director 2pp. 18861:011. 24X
 Fiche.50-267.83/06/01.6306160286.

- 8304300130 Ack receipt of 830506 ltr re 830331 notice of deviation contained in IE Insp Rept 50-267/83-03 Implementation of corrective actions will be reviewed during future insp Emergency plan procedures must be clarafied MADSEN.9 L Region 4. Office of Director 83/06/06 LEE.0 R Public Bervice Co of Colorado. 2pp. 19122 329 24X Fiche 50-267,83/06/06.8306300130
- 830A210253 Responds to NRC 830514 ltr re violations noted in IE Insp Rept 50-267/83-09 Corrective actions measuring & test equipment maint/history cards reviewed & calibrs updated Procedure GC-1 revised to include quarterly review HAREMBDURG, D.W. Public Service Co of Colorado 83/06/07 COLLING.J T Region 4, Office of Director 3pp 18714 OCI 24X Fiche 50-267,83/06/07,8306210253
- 8306210011 Clarifies proposed solution to Open Item 3 re radwaste sysidentified in IE Insp Repts 50-267/78-15 & 50-267/83-06 Resolution will be included in next FSAR rev. scheduled for 830722.

 BREV.H.L. Public Service Co. of Colorado. 83/06/08. COLLINS, J T. Region 4, Office of Director. 2pp. 18910-335. 24X Ficher 50-267,83/06/08,8306210011
- 8305110464 IE Info Notice 83-36, "Impact of Security Practices on Safe Operations" Syc list encl JORDAN, E. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/09 Consolidated Edison Co of New York, Inc 117pp 18830 280 24X Fiche 50-000,83/06/09,8305110464
- 8305110470 IE Info Notice 83-38, "Defective Heat Sink Adhesive & Beigmicelly Induced Chatter in Relays Within Printed Circuit Cards " Syr list encl.
 JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83706/13 Consolidated Edison Co. of New York, Inc. 118pp 18920 225. 24X Fiche 50-000,83/06/13,8305110470
- 8304090010 IE Info Notice 83-37, "Transformer Failure Resulting From Degraded Internal Connection Cables." Svc list encl JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103), 83704/13, Consolidated Edison Co. of New York, Inc. 243pp 18921-001 24X Fiche 50-000,83/04/13,8304090010
- 8305110475 IE Info Notice 83-40, "Need to Environmentally Gualify Epoxy Grouts & Sealers " Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/22 Consolidated Edison Co. of New York, Inc. 115pp 19021.179 24X Fiche: 50-000.83/06/22.8305110475
- 8305110477 IE info Notice 83-41. "Actuation of Fire Suppression Sys Causing Inoperability of Safety-Related Equipment " Svc list encl. JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/06/22 Consolidated Edison Co of New York Inc. 120ap. 18997.007. 24X Fiche 50-000.83/06/22.8305110477
- 8305110479 IE Info Notice 83-42, "Reactor Mode Switch Melfunctions" Svc list encl JDROAM.E L Division of Emergency Preparedness & Engineering Response (Post 830103) B3/06/23 Consolidated Edison Co. of New York, Inc 116pp 18996:242 24X Fiche: 50-000, 83/06/23, 8305110479
- 8305110483 IE Info Notice 83-43, "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints." Svc list encl JDRDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83706/24 Consolidate Edison Co of New York, Inc 116pp. 19046-297 24X Fiche 50-000.83706/24.8305110483
- R. Pariodic operating reports & related correspondence
- 8306160434 Monthly operating rept for May 1783 W/830614 ltr FULLER,C.H. WAREMBOURQ,D Public Service Co of Colorado. 83/06/09. Director's Office. Office of Inspection and Enforcement 10pp. 18861:131 24x Fiche 50-267,83/06/09,8306160434
- 8 Reportable occurrences, LERs & related correspondence
- 8306060134 LER 63-017/01T-0:on B30512, insp performed per IE Bulletin B3-03 identified six of eight check valves frozen in midposition. Caused by corrosion & rusting valve internal parts. Valves cleaned & internal components replaced MAREMBOURGO, D. Public Service Co of Colorado B3/05/26, GOLLINS, J.T. Region 4, Office of Director. 7pp. 18719-009 24X Fiche. 50-267, 83/05/26, 8306060134.
- 8304280217 Forwards updated LERs 78-027/03X-6,79-032/03X-2 & 79-035/03X-1,et al. WAREMBOURG, D. Public Service Co. of Colorado 83/04/06 COLLINS, J. T. Region 4, Office of Director 2pp. 19001 061 24X Fiche: 50-247,83/04/04,8304280217

- --8306280228 Updated LER 78-027/03X-6 on 780706. numerous failures of ITT Barton Model 289 pressure differential switches reported Caused by dirt accumulation & exidation on contact surfaces Switches replaced w/Model 752 pressure transmitters * Public Service Co of Colorado 83/06/06 Region 4, Office of Director Spp 19001 063 24X Fithe 50-267,83/06/06.
- --8306280R36 Updated LER 79-032/03X-2 on 790913, during testing, four of 12 helium circulator seal malfunction pressure differential switch units would not trip Caused by dirt accumulation in electrical switches Switches replaced Public Service Co of Colorado 63/06/06 Region 4, Office of Director 5pp 19001 068 24X Fiche 80-267, 83/06/06, 8306280217
- --8306280246 Updated LER 79-056/03X-1 on 791030 during testing, seven of 12 helium circulator seal malfunction pressure differential switch units tripped outside limits Caused by dirt accumulation in electrical switches Suitches replaced * Fublic Bervice Co of Colorado 83/06/06 Region 4. Dffice of Director Spp 19001 073 24X Fiche 50-267,83/06/06,8306280217
- --8306280260 Updated LER 80-007/03X-1 on 800219, during testing, two of 12 helium circulator seal malfunction pressure differential switch units thipped outside limits Caused by dirt accumulation in electrical switches Switches replaced Public Service Co of Colorado 83/06/06 Region 4, Office of Director Spp 19001 078 24X Fiche 50-267,83/06/06,8306280217
- --8306280262 Updated LER 80-016/03X-1 on 800322 during testing, four of 12 helium circulator seal malfunction pressure differential switch units tripped outside limits Caused by dirt accumulation in electrical switches Switches replaced Public Bervice Co of Colorado 83/06/06 Region 4, Office of Director 5pp 19001 083 24X Fiche 50-267,83/06/06,83/06280217
- --8306280266 Updated LER 80-020/03X-i on 800418, during testing, two of 12 helium circulator seal malPunction pressure differential switch units tripped outside limits Caused by dirt accumulation in electrical switches Switches replaced * Public Service Co of Colorado 83/06/06 Region 4, Office of Director 5pp 19001 088 24X Fiche, 50-267, 83/06/06, 83/08/2021,
- --8306280272 Updated LER 80-026/03X-1 on 800524, during testing, eight of 12 helium circulator seal malfunction pressure differential switch units tripped outside limits Caused by dirt accumulation in electrical switches Switches replaced Public Service Co of Colorado 83/06/06 Region 4, Office of Director Spp 19001.093 24X Fiche 50-267.63/06/06, 8306280217
- --8306280278 Updated LER 80-034/03X-1 on 800619, during testing, two of 12 halium circulator seal malfunction pressure differential switch units tripped outside limits. Caused by dirt accumulation in electrical switches Buitches replaced

 * Public Service Co of Colorado 83/06/06 Region 4, Office of Director 5pp 19001 098 24X Fiche 50-267, 83/06/06, 8306280217
- --B3062B02B3 Updated LER B0-041/03X-1 on B00721.during testing, one of 12 helium circulator seal malfunction pressure differential switch units tripped outside limits Caused by dirt accumulation in electrical switches Switches replaced Public Service Co of Colorado B3/06/06 Region 4, Office of Director App 19001:103 24X Fiche 50-267.B3/06/06.
- --8306280288 Updated LER 80-051/03X-1 on 800922 during testing, five of 12 helium circulator seal malfunction pressure differential suitch units tripped outside limits. Caused by dirt accumulation in electrical suitches Suitches replaced * Fublic Service Co of Colorado 83/06/06 Region 4, Office of Director 3pp 19001:109 24X Fiche 50-267,83/06/06,8306280217
- ---B306280293 Updated LER 80-072/03X-1 on B01117.during testing, three of 12 helium circulator seal malfunction pressure differential switch units tripped outside limits. Caused by dirt accumulation in electrical switches, Switches replaced Public Service Co of Colorado 83/06/06 Region 4, Dffice of Director. Spp 19001:114, 24X Fiche: 50-267,83/06/06,8306280217.
- --B306280298 Updated LER 81-006/03X-1 on 810107, during annual testing & calibr, six of 12 helium circulator seal malfunction pressure differential switch units tripped outside limits. Caused by dirt accumulation in electrical switches Switches replaced, * Public Service Co of Colorado B3/06/06, Region 4, Office of Director, Spp. 17001.180, 24X Fiche.50-267,83/06/06,8306280217

- ---B306280302 Updated LER 81-016/03X-1 on B10213, during testing, three of 12 helium circulator seal malfunction pressure differential switch units tripped outside limits Caused by dirt accumulation in electrical switches Switches replaced Public Service Co of Colorado B3/06/06 Region 4, Office of Director 5pp 19001 IR5 24X Fiche 50-267, B3/06/06, 8306280217
- --8306280309 Updated LER 81-024/03X-1 on 810317, during testing, five of 12 helium circulator seal malfunction pressure differential switch Units tripped outside limits Caused by dirt accumulation in electrical switches Switches replaced Public Service Co of Colorado 87/06/06 Region 4, Office of Director 5pp 19001 190 24X Fiche 50-267,83/06/06, 83/06/06 0306200217
- --8306280313 Updated LER 81-047/09X-1 on B10807.during testing, one of 12 holium circulator seal malfunction pressure differential switch units tripped outside limits Caused by dirt accumulation in electrical switch Switch replaced # Public Service Co of Colorado 83/06/06 Region 4, Office of Director 5pp 19001 195 24X Fiche 50-267,83/06/06,830680317 8306280217
- 8306300187 LER 83-018/03L-0 on 830517, w/reactor shutdown, all outside power lost due to high winds & snow Emergency diesel generator load shedding & sequencing relays failed to operate Caused by coil failures Relays tested W/830616 ltr WAREMBOURG, D Public Service Co of Colorado 83/06/16 CCULINS, J T Region 4, Office of Director 7pp 19119 256 24X Fiche 50-267,83/06/16.6306300187
- 8306300098 LER 83-019/017-0 on 830606, discovered that reactor operated between 5% power & shutdown w/o operable analytical moisture monitors on 830603 Coused by accidental isolation moisture monitors on B30603 Caused by accidental isolation of sample paths to monitors NCVACHEM.F., WARENBOURG, D. Public Bervice Co. of Colorado B3706/17 COLLING. J. T. Region A. Office of Director Bp; 19122 001 24% Fiche 50-267, B3/06/17, B306300098
- DOCKET 50-269 DODNCE NUCLEAR STATION, UNIT 1
- F Security, medical, emergency & fire protection plans
- 8306090361 Forwards request for exemption from emergency operations facility (EOF) location requirements per Generic Ltr 82-33 Proposed EOF to be located 125 air miles from facility.w/ Proposed EOF to be located 125 air miles from facility.w/ joint news ctr remaining in Oconee.NC TUCKER:H B Duke Power Co 83/06/03 DENTON,H.R. Office of Nuclear Reactor Regulation, Director STOLZ,J F Operating Reactors Branch 4 28pp 18795 037 24X Fiche 50-267,83/06/03.8306090361
- 8306170285 Forwards IE 8afeguards Insp Repts 50-269/83-14 50-270/83-14 & 50-287/83-14 on 830509-13 No noncompliance DANCE, H C Division of Project & Resident Programs TORREN H B Duke Power Co App 18877, 233. 24X Fiche. 50-249, 83/06/15, 8306/170285 83/06/15
- --8306170307 IE Safoguards Insp Repts 50-267/83-14, 50-270/83-14 to 830507-13 No noncompliance noted Major areas inspected security plan & implementing procedures & security organization mgt Safeguards info deleted (ref 100FR73.21), TILLMAN, A Region R, Office of Director 83/06/15 2pp. 18877:235 24X Fishe 50-269, 83/06/15, 8306170285
- B30624003B Advises that preliminary fee review of B30603 request for exemption from location requirements of emergency operations facility determined that Class III appropriate DIGGS.R M License Fee Management Branch B3/06/15 TUCKER.H.B Duks Power Co ip 18987.229 24% Fiche 50-269.B3/06/15, B30624003B
- P Operating license stage documents & correspondence
- 8304060051 Add1 response to FOLA request for three categories of documents on PRA of reactor safety study methodology application program repts to interim reliability evaluation program repts. Forwards App A documents. Search continuing FELTON, J M Division of Rules and Records 83/04/07. SHOLLY, S C Union of Concerned Scientists 3pp 18752:001 24X Fiche: 50-000, 83/04/07. 8306060051
- --B306060076 Discusses interim actions taken to reduce impact of turbine bldg flooding Doors between turbine & auxiliary bldgs at basement level scaled shut; component cooling water crossover valves closed & condensate cooler isolated TUCKER; H. B. Duke Power Co B2/12/01 D'REILLY, J. P. Region 2, Office of Director 2pp 18752, 178, 24K Fiche 50-000, 83/04/07, 830000001

- --B3060600B5 Provides info on boron precipitation clogging HP1 lines & failure of operator to switch to hot leg injection in order to flush out boron residue from core during recirculation line obtained from PRAs DAVIG.5 NRC No Detailed Affiliation Given B3/02/24 THADANI.A NRC No Detailed Affiliation Given 6pp 18752 206 24X Fiche 50-000,83/04/07.8306060051
- 8306020103 Proposes 830609 meeting in Bethesda, MD to discuss Suppl 6 to SER for McGuire & SER for standby shutdown facility for Operating Reactors Branch 4 83/05/17 TUCKER Co 1p 18701 279 24X Fichs 50-000,83/08/17, STOLZ, J F Duke Power Co 8306020103
- 830607005: Forwards summary of B30512 meeting w/util & B&W, in response to B30327 request for add1 info re reactor vessel surveillance capsule dosimetry results contained in BAM-1697 M 1077 TUCKER H B Duke Power Co 83/05/27 DENTON, H R Office of Nuclear Reactor Repulation, Director BTDLZ, J F Operating Reactors Branch 4 App. 18740 059 24X Fiche 50-269,83/05/27,8306070051.
- 8304030122 Forwards add1 info to sid in completion of review re MWREG-0737, Items II F 1 4. II F 1 5 & II F 1 6, per 830110 ltr request & justification concerning ltem II. F 1 5 Amend to 830318 confirmatory order requested TUCKER. H B Duke Power Co 83/05/31 DENTON, H R Office of Nuclear Reactor Regulation, Director 87012, J F Operating Reactors Branch 4 15pp 18704 302 24% Fiche 50-269,83/05/31,8306030122
- 8306070272 Forwards BAM-1784, "B&M Duners Group Bolting Task Force
 Bummary Rept of NRC/B&M Owners Group 830506 Meeting on
 Reactor Vessel Internals Bolting "Agrees w/overall
 findings.w/exception re neutron noise surveillance
 TUCKER.H B Duke Power Co 83/05/31 DENTON.H R Office of
 Nuclear Reactor Regulation. Director 6702.J F Operating Reactors
 Branch 4 2pp 18744 086 24X Fiche 50-269.83/05/31.8306070272
- --8306070280 Forwards BAM-1784. "B&W Owners Group Bolting Task Force Bummary Rept of NRC/B&W Owners Group 830506 Meeting on Reactor Vessel Internals Bolting."
 TAYLOR, J H Dabcock & Wilcax Operating Plants Owners Group, TAYLOR, J H Dabcock & Wilcax Co 83/05/20 MINCR, 8 NRC No Detailed Affiliation given 1p. 18744 088 24X Fiche, 50-269, 83/05/31, 8306070272
- --8306070286 "B&W Owners Group Bolting Task Force Suwmary Rept of NRC/B&W Owners Group 830506 Heating on Reactor Vessel Internals Bolting " Babcock & Wilenx Co. DAU-1764 83/05/31 124pg, 18744:089. 24X Fiche 50-247, 83/05/31, 8306070272
- 8306140738 Forwards topical repts, "Boundary Analytical Assessment of NUREO-0630 on LOCA & Operating kW/Ft Limits," per 830602
- TUCKER, H. B. Duke Power Co. 83/06/26 DENTON, H. R. Dffice of Nuclear Reactor Regulation, Director STOLZ, J. F. Operating Reactors Branch 4 lp. 18845 ODI 24X Fiche 50-267, 83/06/06, 8306140738.
- ---8306140746 "Boundary Analytical Assessment of NUREO-0630 on LOCA & Operating kW/Ft Limits "

 * Babcotk & Wilcox Co 77--1141256-00, B3/06/06 29pp, 18845,002 24X Fichs 30-269,83/06/06,8306140739
- --8906140752 "Bounding Analytical Assassment of NUREO-0630 on LDCA & Operating MV/Ft Limits "

 # Babcock & Wilcox Co 77-1140895-00 83/06/06 29pp 18845-032 24X Fichs. 50-269, 83/06/06. 8306140738.
- 8306200185 Summary of 830512 meeting w/util & B&W in Bethesda, MD re neutron dosimetry & uppershelf matl properties provided in Topical Repts BAW-1697 & BAW-1699. List of attendess, agenda & viewgraphs encl. SUERMANN.J F Operating Reactors Branch 4 83/06/06 Operating Reactors Branch 4 35pp 18909:183 24X Fiche:50-269.83/06/06. 8306200185
- 8306140377 Forwards revised Table D-i, "Preliminary Stress Level Comparison." showing value of stress concentration factor & higher calculated peak stresses Higher peak stresses do not affect conclusions from 830506 weeting fleeting summary sncl. TAYLOR, J. H. Babcock & Wilcox Co 83/06/07, MINER, S. NRC No Detailed Affiliation Given 2pp 18843 067. 24X Fiche 50-000,83/06/07,8306140377.
- 8304220275 Informs that 830310 proposed wide-range hot leg level/ reactor vessel haad monitoring satisfactory Evaluation & addl info request re conformance of addl inadequate core cooling instrumentation sys components to NUREO-0737: sncl. STOLZ, J F Operating Reactors Branch 4 83/04/08. TUCKER, H. B Duke Power Co 10pp 18977: 195 24X Fiche: 50-249, 83/04/08, 8304220275

Q Inspection reports, IE Bulletins & correspondence

- 8306080402 Confirms 830513 telcon re proposed site/corporate visit on 830525-27 to review masonry wall const.drawings & calculations re review of IE Bulletin 80-11 response Agenda enci 8TOLZ, J F Operating Reactors Branch 4 83/05/20 TUCKER.H B Bute Power Co .4pp. 18789 342. 24X Fichs 50-269,83/05/20,8306080402
- 8305110458 IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in Well Logging Device" Syc list encl
 TAYLOR, J M Division of Safeguards & Inspection Programs (Post
 830103) 83/05/26 Consolidated Edison Co of New York, Inc
 125pp 18831 043. 24X Fiche 50-000,83/05/26,830\$110458
- 8305110460 IE Info Notice 83-34, "Event Notification Info Worksheet"
 Svc list encl
 JORDAN E L Division of Emergency Preparadness & Engineering
 Response (Post 830103). 83/05/26 Consolidated Edison Co of New
 York Inc 115pp 18732:085 24X Fiche 50~000.83/05/26.8305110460
- 8304010310 EN-83-038 notice of violation & proposed imposition of civil panalties in amount of \$180,000 to be issued on B30402 Action based on three Saverity Level III violations refailure to maintain primary containment integrity.

 9ARBER, 0, AXELRAD, Director's Office, Office of Inspection and Enforcement B3/05/27 ip 18472 317 24% Fiche 50-249.83/05/27, 8304010310
- 8305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods Withdrawn at BWRs " Svc list encl JORDAN: E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/31 Consolidated Edison Co. of New York, Inc. 116pp 18732:208 24X Fichs.50-000.83/05/31,8305110461.
- 8306220171 Discusses IE insp on 830317-28 & forwards notice of violation & proposed imposition of civil penalty O'REILLY.J.P. Region 2. Office of Director. 83/06/02, TUCKER.H B. Duke Fower Co App 18937 281 24% Fiche 50-269,83/06/02,830620171
- --8306220175 Notice of violation & proposed imposition of civil penalty in amount of \$180,000 Noncompliance noted inadequate procedures to ensure that air lock sys restored to operability after meint D'AEILLY.J.P. Birector's Office, Office of Inspection and Enforcement. 83/06/02 4pp 18937 285 24X Fiche 50-269,83/06/02,8306220171
- 8306290245 Informs that response to IE Bulletin 83~03, Item 4 refailures of check valves used in diesel generator water cooling sys, will be submitted by 830622 TUCKER.H.B Duke Power Go. 83/06/08 O'REILLY.J P Region 2. Office of Director ip 19056-095 24X Fiche 50-269, 83/06/08, 8306290245
- 8305110464 IE Info Notice 83-36, "Impact of Security Prectices on Safe Operations." Svc list encl JORDAN E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/09 Consolidated Edison Co of New York, Inc 119pp. 18830-280 24X Fichs 50-000,83/06/09.8305110464.
- 8305t10470 IE Info Notice 83-38, "Defective Heat Sink Adhesive & Seismically Induced Chatter in Relays Within Printed Circuit Cards " Svc list encl.
 JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83706/13 Consolidated Edison Co. of New York, Inc. 118pp. 18920 225 24X Fiche 50-000, 83/06/13, 8305110470
- 8306090010 IE Info Notice 83-37, "Transformer Failure Resulting From Begraded Internal Connection Cables," Bvc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Fost 830103) 83706/13 Consolidated Edison Co of New York, Inc 243pp. 18921 001 24X Fiche 50-000,83706/13,8304090010
- 8306170285 Forwards IE Safeguards Insp Repts 50-249/83-14 30-270/83-14 t 50-287/83-14 on 830809-13 No noncompliance noted. DANCE.H C. Division of Project & Resident Programs 83/06/15 TUCKER, H. B. Duke Power Co. 2pp. 18877 203. R4X Fiche: 50-249,83/06/15,8306/70285
- --8306170307 IE Safaguards Insp Repts 50-269/83-14, 50-270/83-14 to 50-287/83-14 on 630509-13 No noncompliance noted Major areas inspected security plan & implementing procedures & security organization agt. 8afaguards info deleted (ref 100FR73 21).
 TILLMAN.A. ENNIB. J. Region 2. Office of Director MCGUIRE.D. R Division of Emergency Preparedness & Materials Safety 83/06/15 2pp. 18877, 235. 24x Fiche 50-269, 83/06/15,8306170285

- 8305110475 IC Info Notice 83-40, "Need to Environmentally Qualify
 Epoxy Grouts & Sealers" Svc list encl
 JORDANIE L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83706/22 Consolidated Edison Co. of New
 York, Inc. 115pp 17021 177 24X Fiche 80-000,83706/22,8305110475
- B305110477 IE Info Notice B3-41, "Actuation of Fire Suppression Sys Causing Inoperability of Safety-Related Equipment "Syc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post B30103) B3/06/22 Consolidated Edison Co of New York, Inc 120pp 18997 007 24X Fiche 50-000, B3/06/22, B305110477
- 8305110477 IE Info Notice 83-42, "Reactor Mode Switch Malfunctions" 8vc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/23 Consolidated Edison Co of New York, Inc. 116pp 18996 242 24X Fiche 30-000,83/06/23,8305110479
- 8305110483 IE Info Notice 83-43. "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/24 Canabilisted Edison Co of New York, Inc 116pp 19046 297 24X Fiche 50-000,83/06/24,8305110483
- R Periodic operating reports & related correspondence
- 8306170297 Monthly operating repts for May 1983 W/830615 ltr REAVIS, J A , TUGKER.H B Duke Power Co 83/06/15 17pp 18878 177 24X Fiche 30-269,83/06/15,8306170297
- 8 Reportable occurrences. LERs & related correspondence
- 9306300220 Part 21 rept re loose locking clips used to secure terminal boards to rear terminal panels of safety-related instrument cabinets. Initially reported on 821203 All B&W plants notified
 TAYLOR, J H Babcock & Wilcox Co. 92/12/03 DEYOUNO, R C
 Director's Office, Office of Inspection and Enforcement App
 19121 356 24X Fichs 50-269, 82/12/03, 8306300220
- DOCKET 50-270 OCONEE NUCLEAR STATION, UNIT 2

 F Security, medical, emergency & fire protection plans
- 8306090361 Forwards request for exemption from emergency operations facility (EGF) location requirements per Generic Ltr 82-33 Proposed EGF to be located 12b air miles from facility. w/ joint news ctr remaining in Ocones. NC TUCKER. H B Duke Power Co 83/06/03 DENTON. H R Diffice of Nuclear Reactor Regulation, Director 8TOLZ. J F Operating Reactors Branch 4 28pp. 18795 039 24X Fiche. 50-269. 83/06/03. 8306090361
- 8306170285 Forwards IE Bafeguards Insp Repts 50-269/83-14 50-270/83-14 & 50-287/83-14 on 830509-15 No noncompliance noted BANCE, H. C. Division of Project & Resident Programs 83/06/15 TUCKER, H. B. Duke Power Co. 2pp 18877 233 24X Fiche 50-269.83706/15.8306170285
- --8306170307 IE Safeguards Insp Repts 50-269/83-14,50-270/83-14 & 50-287/83-14 on 830509-13 No noncompliance noted Major areas inspected security plan & implementing procedures & security organization mgt Safeguards info deleted (ref 10CFR73 21) TILLMAN,A Region 2, Office of Director 83/06/15 2pp 18877 235 24X Fichs 50-269.83/06/15,8306170285
- 8305240038 Advises that preliminary fee review of 830503 request for exemption from location requirements of emergency operations facility determined that Class III appropriate DIGOS,R M License Fee Management Branch 83/05/15 TUCKER,H B Buke Power Co ip 18987 229 24X Fiche 50~259,83/05/15,8305240038
- P Operating license stage documents & correspondence
- 830606081 Add1 response to FDIA request for three categories of documents re PRA of reactor safety study methodology application program repts & interim reliability evaluation program repts. Forwards App A documents Search continuing FELTON. J M Division of Rules and Records 83/04/07 SHOLLY, 8 C Union of Concerned Scientists 3 pp 18752.001, 24% Fiche 50-000,83/04/07,8304040081.

- --830&060074 Discusses interim actions taken to reduce impact of turbine bldg flooding Doors between turbine & auxiliary bldgs at basement level sealed shut component cooling water crossover valves closed & condensate cooler isolated TUCKER.H B Duke Power Co 92/12/01 O'REILLY, J.P. Region 2, Office of Director 2pp 18/52 19B 24X Fiche 50-000.83/04/07, 8306060051
- --B3060600BB Provides info on boron precipitation clogging HPI lines & failure of operator to switch to hot leg injection in order to flush out boron residue from core during recirculation info obtained from PRAs

 DAVIS.B NRC No Detailed Affiliation Given 83/02/24

 THADANI,A NRC No Detailed Affiliation Given App 18752 206

 24X Fiche 50-000,83/04/07,8306060051
- 8306020103 Proposes 830608 meeting in Bethesda.MD to discuss Suppl A to SER for McGuire & SER for standby shutdown facility for Deconse STOLZ.J F. Operating Reactors Branch 4 83/05/17 TUCKER.H B Duke Power Co ip 18701 279 24X Fiche 50-000.83/05/17, 6306020103
- 8304070051 Forwards summary of 830512 meeting w/util & B&W.in response to 830327 request for add1 info re reactor vessel surveillance capsule dosimetry results contained in BAW-169/ & 1679
 TUCKER, H B Duke Power Co B3/05/27 DENTON, H R Office of Nuclear Reactor Regulation, Birector BTOLZ. J F Operating Reactors Branch 4 4pp 18740 059 24X Fiche 50-269.83/05/27.8304070051
- 8306030122 Forwards addl info to aid in completion of review re NUREC-0737, Items II F | 4, II F | 5 & II F | 6, per 830110 ltr request & justification concerning Item II F | 1.5 Amend to 830318 confirmatory order requested TUCKER, H B Duke Power Co 83/05/31 DENTON, H R Office of Nuclear Reactor Regulation, Director & SUULZ, J F Operating Reactors Branch 4 15pp 18704 302 24X Fiche 50-249, 83/05/31.8306030122
- 8304070272 Forwards BAW-1784, "B&W Owners Group Bolting Task Force Summary Rept of NRC/B&W Owners Group G30506 Meeting on Reactor Vessel Internals Bolting " Agrees w/overall findings, w/exception re neutron noise surveillance TUCKER, H B Duke Power Co B3/05/31 DENTON, H R Office of Nuclear Reactor Regulation, Director STGLZ, J F Operating Reactors Branch 4 2pp 18744 086 24X Fiche 50-269, 83/05/31,8304070272
- --8306070280 Forwards BAM-1784, "B&W Owners Group Bolting Task Force Summary Rept of NRC/B&W Owners Group 830506 Meeting on Reactor Vessel Internals Bolting "TAYLOR.J H Babcock & Wilcox Operating Plants Owners Group TAYLOR.J H Babcock & Wilcox Co 83/05/20 MINER.S NRC No Detailed Affiliation Given in 19 18/44 088 24X Fiche.50-269.83/05/31.8306070278
- ---8306070286 "B&W Owners Oroup Bolting Task Force Summary Rept of NRC/B&W Owners Group 830506 Neeting on Reactor Vessel Internals Bolting " # Babcock & Wilrox Co BAW-1784 B3/09/31 124pp. 18744 089 24X Fichs 50-269, B3/05/31, B306070272
- 8306140738 Forwards topical repts, "Boundary Analytical Assessment of NUREO-0630 on LOCA & Operating kW/Ft Limits:" per 830602 request TUCKER, H B Duke Power Co 83/06/26. DENTON, H R Office of Nuclear Reactor Regulation, Director, 6TOLZ, J F. Operating Reactors Branch 4 1p. 18845 001 24X Fichs 50-269,83/06/06.8306140738.
- --8306140752 "Bounding Analytical Assessment of NUREG-0630 on LOCA & Operating kW/Ft Limits "

 * Babeeck & Wilcox Ge 77-1140895-00 83/06/06 29pp. 18845 032 24X Fiche 50-269, 83/06/06, 8306140739.
- 8306200185 Summary of 830512 meeting w/util & B&W in Bethesda, MD re neutron dosimetry & uppershelf mat! properties provided in Topical Repts BAM-1697 & BAW-1699 List of attendees, agenda & viewgraphs enc! SUERMANN, J F Operating Reactors Branch 4 83/06/06 Operating Reactors Branch 4 35pp 18909*183 24X Fiche*50-269.83/06/06, 8306200185
- 8306140377 Forwards revised Table D-i, "Preliminary Stress Level Comparison," showing value of stress concentration factor & higher calculated peak stresses will her peak stresses do not affect conclusions from 830506 meeting. Meeting summary ancl. TAYLOR, J H Babcock & Wilcox Co. 83706/07, MINER, \$ NRC Np Detailed Affiliation Given 2pp. 18843-067 24% Fichs 50-000, 83/06/07, 8306140377

- 8306220275 Informs that 830310 proposed wide-range hot leg level/ reactor vess! head monitoring satisfactory Evaluation & add1 info request re conformance of add! inedequate core cooling instrumentation sys components to NUREO-0737; ent STOLZ.J F Operating Reactors Branch 4 83/06/08 TUCKER.H B Duke Power Co 10pe 19777 155 24X Fiche 50-269.83/06/08. 830620275
- G Inspection reports, IE Bulletins & carrespondence
- 8306080402 Confirms 830513 telcon re proposed site/corporate visit on 830525-27 to review masonry wall const.drawings & calculations re review of IE Bulletin 80-11 response Agenda encl
 STOLZ.J F Operating Reactors Branch 4 83/05/20, TUCKER.H B
 Duke Power Co 4pp 18789 342 24X Fiche 50-269.83/05/20, 8306080402
- 8308110458 IE Info Nobice 83-32, "Ruptured Am-241 Sources Contained in Well Logging Device" Svc list encl TAYLOR.J M Division of Safeguards & Inspection Programs (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 125pp 18831 043 24X Fiche: 50-000, 83/05/26, 8305110458
- 8305110460 IE Info Notice 83-34, "Event Notification Info Worksheet."
 Svc list encl
 JORDAN, E.L Division of Emergency Preparadness & Engineering
 Response (Post 830103) 83/05/26 Consolidated Edison Co. of New
 York, Inc 115pp 18732 085 24X Fiche 50-000,83/05/26,8305110460,
- 8305110461 lE Info Notice 83-35, "Fuel Movement H/Control Rods Withdrawn at BWRs " Svc list encl JORDAN:E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/31 Consolidated Edison Co. of New York: Inc 116pp 18732 208 24X Fiche 50-000.83/05/31.9305110461
- 8306220171 Discusses IE insp on 830317-28 & forwards notice of violation & proposed imposition of civil penalty.

 O'REILLY, J P Region 2, Office of Director 83/06/02 TUCKER, H.B. Duke Power Co. App 18937-281 24X Fiche 50-267, 83/06/02, 830620171
- --8306220175 Notice of violation & proposed imposition of civil penalty in amount of \$180.000 Noncompliance noted inadequate procedures to ensure that air lock sys restored to operability after maint O'RETILLYJ P Director's Office, Office of Inspection and Enforcement 83/06/02 4pp 18937 285 24X Fiche 50-269.83/06/02.8306220171
- 8306290245 Informs that response to IE Hulletin 83-03, Item 4 refailures of check valves used in dissel generator water cooling sys, will be submitted by 830622 TUCKER, H B Duke Power Co 83/04/08 O'REILLY, J. P. Region 2, Office of Director, ip. 17084 085, 24X Fiche, 50-269, 83/06/08, 830620245
- 8305110464 IE Info Notice 83-36, "Impact of Security Practices on Bafe Operations " Svc list encl JORDAN.E.L. Division of Emergency Preparedness & Engineering Response (Post 930103) 83/06/09 Consolidated Edison Co of New York, Inc 119pp 18830:280 24X Fiche.50-000,83/06/09,8305110464
- 8305110470 IE Info Notice 83-38, "Defective Heat Bink Adhesive & Beismically Induced Chatter in Relays Within Printed Circuit Cards." Syc list encl JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co. of New York, Inc. 118pp. 18920 225 24X Fiche, 50-000, 83/06/13, 8305110470,
- 8306090010 IE Info Notice 83-37, "Transformer Failure Resulting From Degraded Internal Connection Cables," Bvc list encl JORDAN.E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13. Consolidated Edison Co. of New York, Inc. 243pp 18921-001 24X Fiche 50-000,83/06/13,8306090010.
- 8306170285 Forwards IE Safeguards Insp Repts 50-269/83-14 50-270/83-14 & 50-287/83-14 on 830509-13, No noncompliance noted DANCE, H.C. Division of Project & Resident Programs 83/06/15 TUCKER, N.B. Duke Power Co. 2pp 18877 233 24X Fiche 50-269, 83706/15, 8306170285
- ---B306170307 IE Safeguards Insp Repts 50-269/B3-14, 50-270/B3-14 & 50-287/B3-14 on B30509-13. No noncompliance noted Major areas inspected, security plan & implementing procedures & security organization mgt. Safeguards info deleted (ref 10CFR/3 21). TILLMAN.A. ENNIB.J Region 2, Office of Director McGUIRE, D R. Division of Emergency Preparedness & Materials Safety 89/06/15 2pp 18877 235. 24X Fiche 50-269,83/06/15,8306170265.

- 8305110475 IE Info Natice 83-40, "Need to Environmentally Qualify
 Epoxy Grouts & Sealers " Svc list entl
 JORDANAE L Division of Emergency Preparedness & Engineering
 Rasponse (Post 830103) 83706/22 Consolidated Edison Co of New
 York, Inc 115pp 19021 179 24% Fiche 50-000,83706/22,8305110475
- 8305110477 IE Info Notice 83-41, "Actuation of Fire Suppression Sys Causing Inoperability of Safaty-Ralated Equipment" Svc list
 - entl
 JORDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/06/22 Consolidated Edison Co of New
 York, Int 120pp 18777 007 24X Fiche 50-000,83/06/22,8305110477
- 8305110479 IE Info Notice 83-42, "Reactor Mode Switch Malfunctions "
- 305110479 IE Info Notice 83-42, "Heactor code Bulton colonial Evolution of Emergency Preparedness & Engineering JORDAN E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/23 Consolidated Edison Colon New York, Inc. 116pp 18794 242 24X Fiche 30-000,83/06/23,8305110479
- 8305110483 IE Info Notice 83-43, "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints " Svc 11st encl JORDAN E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/24 Consolidated Edison Co of New York, Inc. 116pp 17046 277 24X Fishe 50-000,83/06/24,8305110483
- R. Periodic operating reports & related correspondence
- 8306170297 Monthly operating repts for May 1983 W/830615 ltr REAVIS.J.A. TUCKER.H B Duke Power Co 83/06/15 17pp 18878 177 24X Fiche:50~269.83/06/15.8306170297.
- DOCKET 50-P71 VERMONT YANKEE NUCLEAR POWER STATION. F Security, medical, emergency & fire protection plans
- 8306010301 Forwards IE Insp Rept 50-271/83-12 on 830503-04 No noncompliance noted MARTIN.T T Division of Engineering & Technical Programs 83/08/ MURPHY.W P Vermont Yankoe Nuclear Power Gorp 2pp. 18672 303 24X Fiche: 50-271,83/05/17,8306010301
- --830&010304 IE Insp Rept 50-271/83-12 on 830503-04 No noncompliance noted Major areas inspected gublic prompt notification sys COMEN.I., GORDON.C., CRDCKER.H W Region 1, Office of Director 83/05/16 pp 18672 305 24% Fiche 50-271,83/05/17.830&010301
- 8305070344 Forwards IE Insp Rept 50-271/83-01 on 830104-31 & notice of violation. BTARDBTECKI,R Division of Project & Resident Programs 83/05/ HURPHY,W.P Verment Yankae Nuclear Power Corp 2pp 18748 037 24X Ficha 50-271,83/05/24,8306070344 99705724
- --8304070353 IE Insp Rept 50-271/83-01 on 830104-0131 Noncompliance noted failure to follow health physics survey procedure to failure to maintain valve lineups per approved procedures RAYMOND, N. J., \$\text{HIGGINS.J.T.}, QALLO.R M Region i, Office of Director 83/05/19 24pp 18742-041 24X Fiche 50-271,83/05/24,8306070344
- 8306010435 Proposed Change 110 to License DPR-28.deleting Tech Spec provision for annual site evacuation drill Tech Spec requirement duplicated by 100FR50.App E HEIDER.L. H Vermont Yankee Nuclear Power Corp 83/05/26 EISENHUT.D 0 Division of Licensing 3pp 18674 268 24X Fiche 50-271,83/05/26.8306010435
- --B306010436 Proposed Tech Spec change deleting provision for annual site evacuation drill

 * Vermont Vankee Nuclear Power Corp 83/05/26 ip 18674 271

 #24X Fiche 80-271.83/05/26.8306010435
- 8306150290 Releases public version of revised emergency plan implementing procedures FELTON, J M Division of Rules and Records 83/06/06 Docum Management Branch. 1p 18869 276. 24X Fiche 50-271.83/06/06. 8306150290 Document
- --8306150293 Forwards public version of revised emergency plan implementing procedures, including Procedures OP 3500 re unusual events OP 3501 re alert & OP 3502 re site area amergency
 MARKT, D Yankee Atomic Electric Co. 43705703 NRC - No. Patailed Affiliation Given ip. 18849 277 Fiche. 50-271, 83/04/06, 8204150290.

- --8306150299 Public version of revised emergency plan implementing procedures; including Procedures OP 3500 re unusual events. OP 3501 re alert & OP 3502 re site aica emergency MARKT. D Yankee Atomic Electric Ca 83/03/03 Office of Nuclear Reactor Regulation, Director 40pp 18869 278 24X Fiche 50-271,83/06/06.8306150290
- 8304280112 Forwards Temporary Change 83-1 to physical security plan 304280112 Forwards Temporary Change 83-1 to physical security plan Change withheld MURPHY-W P Vermont Yankee Nuclear Power Corp 83/06/14 VASSALLO D B Operating Reacture Branch 2 1p 19001 130 24X Fiche 30-271,83/06/14.8306280112
- H General torrespondence
- 8304210029 Opposes facility restart Uniesolved safety issues re inadequate pipe supports & cracked feedwater nozzle preclude safe operation Petition to follow RICHARDSON.C Vermont Yankee Decommissioning Alliance 83/06/16 ROONEY,V, VASSALLO.D Operating Reactors Branch 2 ip 18912 296 24X Fiche 50-271,83/06/16,8306210029
- 1 Financial information
- 8304200073 Forwards annual financial statements for 1980,1981 & 1982, per 10CFR50 71(b)
 SINCLAIR, J B Vermont Yankee Nuclear Fower Corp 83/06/15
 DENTON, IR Office of Nuclear Reactor Regulation, Director 1896
 18904 001 24X Fiche 50-271,83/06/15,8306200073
- P Operating license stage documents & correspondence
- 8304010244 Application to amend License DPR-28, consisting of Proposed Change 107, revising Tech Spec Figure 3 & 1 re reactor vessel 306010246 Application to amend License DMM-RB, consisting to Change 107, revising Tech Spec Figure 3 6 i re reactor ver pressure temp limitations to permit reactor operation to power output of 1 330E8 MHH(t)
 HEIDERLL H Vermont Yankor Nuclear Power Corp 83/05/26
 EISENHUT, D 6 Division of Licensing 4pp 18673 026
 Fiche 50-271,83/05/26.83060102/46 03/05/26 73 026 - 24x
- --8306010248 Proposed Change 107 revising Tech Spec Figure 3 & 1 re reactor vessel pressure temp limitations for operation through 1 33088 MWH(t) ** Verment Yankee Nuclear Pawer Corp 83/05/26 3pp 18673 030 24X Fiche, 50-271,83/05/26,8306010246
- 830A010379 Application to amend License IPR-20, modifying App A Tech Specs to reflect new limiting conditions for operation & surveillance requirements for RGS leakage monitoring sys HEIDER.L N Vermont Yankee Nuclear Power Corp 03/05/26 EISENHUT.D G Division of Licensing 3pp 18682 153 24X Fiche.50-271,83/05/26,8304010379
- --8306010383 Proposed Tech Specs re limiting conditions for operation & surveillance requirements for RCS loakage monitoring sys
 * Vermont Yankee Nuclear Power Corp 83/05/26 App 18682 156
 24X Fiche 50-271,83/05/26,8306010377
- 8304010435 Proposed Change 110 to License DPR-28, deleting Tech Spec provision for annual site evacuation drill Tech Spec requirement duplicated by 10CfR50.App L HEIDER.L H Vermont Yankee Nuclear Power Corp 83/05/26 EISEN#UT.D Q Division of Licensing 3pp 18674-268 24X Fiche.50-271,83/05/26.8304010435
- --8306010436 Proposed Tach Spec change deleting provision for annual site evacuation drill

 * Vermont Vankoe Nuclear Power Corp 83/05/26 ip 18674 271
 24X Fiche 50-271,83/05/26,8306010435
- 8306020174 Forwards response to 820712 commitment to perform feedwater noitle integrity evaluation during 1983 outage Post-outage results of NDT exoms per NRC 830126 request & afridavit for uithholding proprietary info (ref 10CFR2 /90) also encl 8 INCLAIR. J B Vermont Yankee Nuclear Power Corp 83/05/26 VA88ALLO. D B Operating Reactors Branch 2 3pp 18695 051 24X Fiche 50-271.83/05/26.8306020174
- --8304020178 "Insp Program Bummary " ** Nuclear Energy Service, Inc 83/05/26 App 18495 054 Fiche 50-271,83/05/26,8304020174 24X
- --8306020184 Rev I to Procedure 80A7516. "Ultrasonic Exem Procedure for Reactor Vessel Feedwater Nozzle Inner Radius " ALLING.N E Nuclear Energy Service, Inc 83/01/28 33pp 18695 060 24X Fiche 50-271.83/05/26.8306020174

- 8306130498 Forwards synopsis of resolutions to open items re control of heavy loads at nuclear power plants.per NUREG-0612 guidelines Braft final technical evaluation rept & request for add info encl VASSALLO, D B Operating Reactors Branch 2 83/05/26 SINCLAIR, J B Vermont Yankee Nuclear Power Corp 13pp 18830 107 24X Fiche 50-271.83/05/26.8306130495
- 8304030112 Provides updated list of qualified electrical equipment important to safety per 830411 request List includes equipment scheduled to be qualified or replaced Diagrams of locations of control equipment encl
 SINCLAIR.J B Vermont Yankee Nuclear Power Corp 83/05/31
 EISENHVI.D G Division of Licensing App 18704 352 249
 Fiche 50-271.83/05/31.8306030112
- 8306090303 Responds to 801001 lt; re mode to scram discharge sys Scram discharge vols; new instrument vols; instrumentations & associated piping & valves installed seismically Operation justified during mode HEIDER, L. H. Vermont Yankee Nuclear Power Corp. 83/06/06 VASSALLO, D. B. Operating Reacture Branch 2 2pp. 18795 177 24X Fiche 80-271, 83/06/06, 8306090,303
- 8306140285 Forwards justification for continued operation re 830411 request for add1 info concerning environ qualification of safety-related electrical equipment Similarity of isolation valves in containment sys verified by Target Rock SINCLAIR, J B Vermont Yankee Nuclear Power Corp 83/06/07 EISENHUT, D C Division of Litemening 7pp 18832 227 24X Fiche 50-271,83/06/09.8306140285
- 8306150161 Requests extension of implementation date for torus mods to 90 days following startup from current refueling outage All internal mods & all torus-related mods complete Extension applies only to torus-attached piping HEIDER, L. H. Vermont Yankee Nurlear Power Corp. 83/06/13 EISENHUT, D. G. Division of Licensing 2pp. 18846-319 24X Fiche 50-271,83/06/13.8306/50161
- 8306220044 Forwards response to 830414 request for add1 info re Mark 1 containment long-term program
 SINCLAIR, J B Vermont Yanker Nuclear Power Corp 83/06/17
 VASSALLO, D B Operating Reactors Branch 2 1p 18932 243 24X
 Fich
- --8306220053 Procedure 5960-3 "Responses to NRC Request for Info, Mark 1 Torus Program Plant Unique Rept "
 * Teledyne Engineering Bervices B3/06/10 31pp 18932 244.
 24 Fiche 50-271, B3/06/17, B306/20044
- 830&240170 Forwards list of proposed amends submitted prior to 830506 effective date of Interim Final Rule ADFRI4864.per Generic Ltr 83-17 Copies of amend proposels to be prenoticed & provided to designated state official SINCLAIR.JB Vermont Yankee Nuclear Power Corp 83/06/17 VASSALLO.D B Operating Reactors Branch 2 3pp 18781:036 24X Fiche 50-271.83/06/17.8306240170
- Q Inspection reports, IE Bulletins & correspondence
- 8306010301 Forwards IE Insp Rept 50-271/83-12 on 830503-04 No noncompliance noted MARTIN.T T Division of Engineering & Technical Programs 83/05/17 MURPHY.W P Vermont Yankos Nuclear Power Corp. 2pp 18672,303 24X Fiche 50-271,83/05/17,8306010301
- --8306010304 IE Insp Rept 50-271/83-12 on 830503-04 No noncompliance noted Major areas inspected public prompt notification sys COHEN,1, GORDON.C., CROCKER,H W Region 1, Office of Director 83/05/16 Spp 18672-305 24X Fiche 50-271,83/05/17,8306010301
- 8304070344 Forwards IE Insp Rept 50-271/83-01 on 830104-31 & notice of violation 8TAROSTECKI,R Division of Project & Resident Programs, 03/05/24 MURPHY,W P. Vermont Yankee Nuclear Power Corp. 2pp 18742 037 24X Fiche 50-271,83/05/24,8306070344
- --8306070346 Notice of violation from insp on 830104-31 * Region 1, Office of Director. 83/05/24 2pp. 18742 039 24X Fiche 50-271,83/05/24,8306070344
- --8304070353 IE Insp Rept 50-271/83-01 on 830104-0131 Noncompliance noted failure to follow health physics survey procedure & failure to maintain valve lineups per approved procedures RAYMOND.W J. WIGGINS, J T., GALLO, R. M. Region 1, Office of Director 83/05/17 24pp 18742 041 24X Fiche 50-271,83/05/24,8304070344

- 8305110458 IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in Well Lagging Device" Svc list encl
 TAYLOR, J M Division of Bafeguards & Inspection Programs (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 125p 18831 043 24x Fiche 50-000,83/05/26,8305110458
- 8305110460 IE Info Notice 83-34, "Event Notification Info Worksheet "
 Svc list encl
 JURDON, C L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/05/26 Consolidated Edison Co of New
 York, Inc 115pp 18732 085 24X Fiche 50-000,83/05/26,8305110460
- 8306020174 Forwards response to 820912 commitment to perform feedwater nozzle integrity evaluation during 1983 outage Post-outage results of NDT exams per NRC 830124 request & affidavit for withholding proprietary info (ref 10CR2 790) also encl. SINCLAIR, J B Vermont Yankee Nuclear Power Corp. 83/05/26 VABSALLO, D B Operating Reactors Branch 2 3pp 18495 051 24K Fiche: 50-271,83/05/26,8306020174
- --8306020178 "Insp Program Bummary " * Nuclear Energy Service, Inc 83/05/26 6pp 18695 054 24X Fiche 50-271,83/05/26,8306020174,
- 8306070358 Forwards IE Insp Rept 50-271/83-13 on 830502-05 & notice of violation STAROBTECKI,R Division of Project & Resident Programs 83/05/26 MURPHY,W P Vermont Yankee Nuclear Power Corp 2pp 18795 027, 24X Fiche 50-271,83/05/26,8306090358
- --8306090360 Natice of violation from insp on 830502-05 * Region I. Office of Director 83/05/26 ip 18795 029 24X Fiche 50-271,83/05/26,8306090358
- --8306090366 IE Insp Rept 50-271/83-13 on 830502-05 Noncompliance noted failure to follow established documentation & review procedure for implementation of engineering design change to cables C1845HRAS & C1844CRB1 HT091NB.J T., QALLO.R M Region i. Office of Director 83/05/20. 6pp 18795-030 24X Fiche 50-271.83/05/26.8306090358
- 8305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods Withdrawn at BWRs " 8vc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/31 Consolidated Edison Co. of New York, Inc 116pp 18732 208 24X Ficher 50-000,83/05/31,8305110461.
- 8306160003 Forwards 1E Insp Rept 50-271/83-02 on 830201-0411 & notice of violation STAROSTECKI, R Division of Project & Resident Programs, 83/06/01. MURPHY, W P Vermont Yankse Nuclear Power Corp. 2pp. 18861, 325. 24X Fiche 50-271,83/06/01,8306160003.
- --8306160005 Notice of violation from insp on 830201-0411 * Region 1. Office of Director 83/06/01 1p 18861 327 24X Fiche 50-271.83/06/01.8306160003
- --B306160006 IE Insp Rept 50-271/83-02 on 830201-0411 Noncompliance noted failure to post contaminated area & to control work in contaminated area RAYMOND, N J . COLLINS, B J . EICHENHOL7, H . Region 1, Gffice of Director 83/05/20 28pp. 18861-320 24X Fiche 50-271, B3/06/01, 8306160003
- 8306080076 Forwards response to IE Bullatin 83-02 re use of ultrasunic exam techniques for inservice insp program to assure integrity of recirculation sys piping for continued operation. Criteria selected & insp results encl MURPHY, W P Vermont Yankee Nuclear Power Corp 83/06/03 VASSALLO, D B Operating Reacture Branch 2 174pp 18773 268 24X Fichs 50-271,83/06/03,8306080076
- 8306200174 Forwards IE Insp Rept 50-271/83-07 on 830412-0502 & notice of violation 8TAROBIECKI, R. Division of Project & Resident Programs. 83/06/06 MURPHY, W.P. Vermont Yanker Nuclear Power Corp. 2pp. 18903-126. 24X Fiche, 50-271, 83/06/06, 8306200174
- --8306200177 Notice of violation from insp on 830412-0502 * Region I. Office of Director 83/06/06 ip 18703; 128 24X Fiche 50-271,83/06/06,8306200174
- --B306200181 IE Insp Rept 50-271/B3-09 on B30412-0502 Noncompliance noted. Installation & Test Procedure SPN-70115-770 re torus internal mode not followed for gusset platas, RAYMOND, N J . HOLDEN, C F . GALLO, R M Region 1, Office of Director B3/06/03, 14pp JB903 129 24X Fichs 50-271, B3/06/06, B306200174

- 8305110464 IE Info Notice 83-36, "Impact of Security Practices on Safe Operations " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/09 Consolidated Edison Co of New York, Inc 119pp 18830 280 24X Fiche 50-000,83/06/09,8305110464
- 8306140489 Forwards updated into re results of post-overlay weld joint insp, in response to IE Bulletin 83-02. "Stress Corrosion Cracking in Large Diameter Stainless Steel Recirculation Bys Piping at BHR Plants."

 MURPHY. M. P. Vermont Yankee Nuclear Power Corp. 83/06/09

 VASSALO, D. B. Operating Reactors Branch 2 3pp 18843 074 24X

 Fichs 50-271,03/06/09.6306140489
- 8305110470 IE Info Notice 83-38, "Defective Heat Sink Adhesive & Seismically Induced Chatter in Relays Within Printed Circuit Cards " Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Fost 830103) 83/06/13. Consolidated Edison Co. of New York, Inc. 118pp 18920 228 24% Fiche 50-000,83/06/13,8305110470
- 8306090010 IE Info Notice 83-37. "Transformer Failure Resulting From Degraded Internal Connection Cables " Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co. of New York, Inc 243pp 18921 001 24% Fiche 50-000,83/06/13,8304090010
- 8306280472 Forwards IE Insp Rept 50-271/83-11 on 830503-06 No Documentiance noted

 MARTIN T.Y Division of Engineering & Technical Programs 83/04/
 MUSPHYN P. Vermont Yankee Nuclear Power Corp. 2pp. 19018-315

 24X Fiche 50-271.83/04/13.8306280472
- --8306280474 IE Insp Rept 50-271/83-11 on 830503-06.No noncompliance noted Major areas inspected licensee radiation protection program personnel training & internal & external exposure
 - control. MCBRIDE.M H , BHANDAKY.M Region i, Dffice of Director 83/06/08 App 19018.317 24% Fiche 50-271.83/06/13.8306280472
- 8306200398 Responds to IE Bulletin 83-02 re commitment to implement revised leakage monitoring provisions Insp &/or mod of recirculation & other RCPB piping sys for next refueling dutage planned MURPHY, H.P. Vermont Yankse Nuclear Power Corp 83/06/13 VABSALLO, D B. Operating Reactors Branch 2 Spp 18899 Fiche 50-271,83/06/15,8306200388. 10899 034. 24X
- 8306210223 Responds to natice of violation & proposed imposition of civil penalty from IE Insp Rept 50-271/83-04. Corrective actions movement of fuel within spant fuel pool terminated & automatic features of standby gas treatment say restored MURPHY. W P Vermont Yankee Nuclear Power Corp. 83/06/16 DEYOUNDR. R.C Director's Office, Office of Inspection and Enforcement 6pp 18916-035 24% Fiche 50-271,83/06/16.8306210223
- 8306210118 Responds to NRC 630510 ltr re proposed civil penalty & JE Insp Rept 50-271/63-04. Annunt of penalty should be reduced due to shorter length of time secondary containment was compromised & prompt corrective action HURPHY, W P. Vermont Yankse Nuclear Power Corp. 63/06/17 DEYOUND, R C Director's Office, Office of Inspection and Enforcement 3pp. 18918-114. 24X Fiche, 50-271, 83/06/17, 8306210118
- 8306230075 Confirmatory Action Ltr 83-04 re error in specing table Porthermal & dead weight stresses w/ANSI B3: I for installation of piping supports in svc water sys, 8afety analysis to be parformed & documented.

 8TAROBITECKI, R. Division of Project & Resident Programs 83/06/17 HURPHY, H.P. Vermont Yankee Nuclear Power Corp. 2pp. 18947, 173
 24X Ficher 50-271, 83/06/17, 8306230075
- 8306280164 Forwards SALP rept on 830613 for assessment period May 1982 Apr 1983 Neeting scheduled for 830628 to discuss BYARDSTECKI.R. Division of Project & Resident Programs. 83/06/2 MURPHY, M.P. Vormont Yantes Nuclear Power Corp. 2pp. 19014 278. 24X Fiche: 50-271, 83/06/21, 8306280164. 03/04/21
- --8306280166 BALP rept on 830613 * Region 1, Office of Director, 83/06/13, 34pp, 19014 280, 24x Fiche: 50-271,83/06/21,8306280164,
- 830A280170 Ack receipt of 830414 ltr responding to human factors review forwarded in NRC 830211 ltr. Agrees that level of technical training provided to nuclear safety engineer did not affect response to 820424 loss of feedwater translent.

 STAROSIECKI. R Division of Project & Resident Programs 83/06/21.
 MURPHY: N P. Vernont Yankee Nuclear Power Corp. 2pp 19014 355.
 24X Fiche: 50-271. 83/06/21. 830A280170

- --830A280173 Responds to NRC 830211 ltr forwarding human factors review evaluating shift technical advisor/control room design Lists salient features of program to enhance & redefine existing program
 NURPHY.W P Vermont Yankee Nuclear Power Corp 83/04/1
 STAROSTECKI.R Division of Project & Resident Programs
 19014 357 24X Fiche 50-271,83/06/21.8306280170
- B305110475 lE Info Natice B3-40, "Need to Environmentally Qualify
 Epoxy Grouts & Sualers " Svc list encl
 JORDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) B3/06/22 Consolidated Edison Co of New
 York Inc 115pp 17021 177 24X Fische 50-000,83/06/22,8305110475
- 8305110477 IE Info Notice 83-41, "Actuation of Fire Suppression Sys Causing Inoperability of Safety-Related Equipment " Svc list ancl. JORDAN.E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/22 Consolidated Edison Co. of New York. Inc. 120pp 18997 007 24X Fiche 50-000.83/06/22.8305110477
- 8305110479 IE Info Notice 83-42. "Reactor Mode Switch Malfunctions " Notited to the encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/23 Consolidated Edison Co of New York, Inc 116pp 18996 242 24X Fiche 50-000,83/06/23.8305110479
- B305110483 IE Info Notice 83-43. "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints " Svc list encl JDRDAN,E L Division of Emergency Preparedness & Engineering Response (Post B30103) B3/06/24 Consolidated Edison Co of New York, Inc 114pp 17046 297 24X Fiche 50-000.83/06/24,8305110483
- R Periodic operating reports & related correspondence
- B30617006B Monthly Operating Rept B3-05 for May 1983 W/B30609 1tr BURGER.F J. MURPHY.W P Vermont Yankee Nuclear Power Corp B3/06/09 Office of Resource Managemont, Director 7pp 18882 203 24X Fiche: 50-271, B3/06/09, B30617006B
- 8 Reportable occurrences, LERs & related correspondence
- 8306170264 LER B3-013/03L-0 on B30413, while reactor shutdown, weekly environ air sample for B30405-12 at Btation ATI 3 not obtained. Caused by technician Failure to test for sys vacuum Technician reinstructed in procedure W/830513 ltr PELLETIER, J P Vermont Yankee Nuclear Power Corp 83/05/1: ALLAN, J H Region 1. Office of Director 2pp 18878 161. Fiche 50-271, 83/05/13, 8306170264 93/05/13
- 8306140154 PNO-I-83-054.on 830604.ECCS actuation signal caused HPCl & RCIC sys to actuate, but sys failed due to lack of steam (reactor temp at 185 F) Open RCIC & HPCl lines created Treator temp at 100 / / Opt. 100 / Opt. 100
- 8306170039 LER 83-014/03L-0 on 830510, discovered surveillance frequency SOBIJOUSY LEM 03-014-01-0 on HSUDIO-015COVERED SURVEILLANCE FREQUE for SVC water processas monito: exceeded Tech Speca Caused by schedule error Analysis immediately performed Applicable personnel reinstructed W4803607 ltr PELLETIER, J P Vermont Yankee Nuclear Power Corp B3/06/07 MURLEY,T E Region 1. Office of Director 2pp 18882 225, 24X Fiche. 50-271,83/06/07.8306170039
- 8304140474 PND-I-83-058: on 830408. Yankee Atomic Electric Corp notified licensee of two support problems w/ECC8 suction piping attached to torus & svc water piping for cooling water to uninterruptible power supplies HOLDEN, KISTER Region 1, Office of Director 83/04/09 1; 18834 335 24X Fiche: 50-271.83/04/09.8306140474
- 8306170332 PNO-I-83-061: on 830615, while conducting mod to reactor water level sensing lines, false low reactor water & low-low reactor water level signals generated, initiating ECCS & starting emergency diesel generators

 OALLO, KISTER Region 1, Office of Director 83/06/15, ip 18800.362 24X Fiche.50-271,83/06/15,8306170332.

8306140032 Requests attendance at 830627 meeting w/Region I in King of Prussia-PA to discuss transfer of reactor operator of Prussia-PA to discuss transfer of reactor operator licensing function from Bethesda, MD to Region I of: BTAROBIECKI, R Division of Project & Resident Programs, MURPHY. N. P. Varmont Yankes Nuclear Power Corp. 2pp 1 83/06/09. 18838, 333 24X Fiche, 50-271, 83/06/09, 8306140032.

- DOCKET 50-272 BALEM NUCLEAR GENERATING BIATION, UNIT 1

 F Security, medical, emergency & fire protection plans
- 8306070150 Forwards Submittal 3 to security training & qualification plan Submittal withheld (ref 10CFR73 Pl)
 LIDEN.E A Public Service Electric & Gas Co of New Jersey
 83/05/02 Region 1. Office of Director 2pp 18736 291 24X
 Fiche 50-272,83/05/02.8306070150
- 8306070164 Requests that revocation of (hapter 9 be taken into account during review of Rev 8 to security plan & that approval of plan not be delayed by review of Chapter 9 Notice withdrawing Chapter 9 & Procedure EP7 enc.)

 LIBEN.E A Public Service Electric & Gas Co of New Jersey 83/05/12 Region 1, Office of Director 3pp 18736 281 24X Fiche 50-272,83/05/12.8306070164
- B306020232 Forwards Rev O to Salem Generating Station Emergency Operating Procedures Generation Package," per Suppl 1 to NURGO-0737 (Generic Ltr 82-33) LIDENIE A Public Service Electric & Gas Co of Now Jersey B3/05/20 VARGA, B A Operating Reactors Branch 1 ip 18689 Ooi 24% Fiche 50-272,83/05/20,8306020232
- --8306020240 Rev O to "Balem Generating Station Emergency Operating Procedures Generation Package " GUELLER.J , FRY.L , BERKLEY,J Public Service Electric & Gas Co of New Jersey 83/04/20 166pp 18689 002 24X Fiche. DO-272.83/05/20.8306020232
- B3061704B1 Forwards safety evaluation of util submittals re fire protection rule, incorporating BNL technical input Facilities in compliance w/App R to 10CFR50, Items 111 G & 111 L re safe shutdown in relay cable spreading or control room VARQA: B A Operating Reactors Branch 1 B3/05/31 UDERITZ.R.A Public Bervice Flectric & Gas Co of New Jersey 2pp 18894 307 24X Fiche 50-272.83/05/31.83061704B1
- --8306170483 Safety evaluation of util compliance w/App R to 10CFR50.
 Items III 9 3 & III L Facility design provides train of sys
 necessary to achieve & maintain safe shutdown conditions
 * Office of Nuclear Reactor Regulation, Director 83/05/31 8pp
 18894 309 24X Fiche 50-272.83/05/31.8306170481
- 8304090049 Forwards Rev 8. Amend 1 to security plan Rev withheld (ref 100FR73 21) LIDEN,E A Public Service Electric & Gos Co of New Jersey 83/06/03. Region I. Office of Director 2pp 18793 311 24X Fiche 50-272,83/06/03.8306090049
- 8304230471 Forwards IE Bafeguards Insp Repts 50-272/83-17 & 50-311/83-14 on 830514-20 No noncompliance noted MARTIN,T T Division of Engineering & Technical Programs 83/06/08 UDERITZ,R A Public Bervice Electric & Oas Co of New Jersey 2pp 18941 302 24X Fiche 50-272,83/06/08,8306230471
- --8306230475 IE Safeguards Insp Repts 50-272/83-17 & 50-311/83-16 on 830516-20 No noncompliance noted Major areas inspected security plan, contingency plan & previously identified items

 SMITH, G C , GODY, A T Region 1, Office of Director, 83/06/06 3pp 18741-304 24X Fiche 50-272,83/06/08,8306230471

H General correspondence

- B3Q6140043 Requests JM Zupko & A Nassman be added to svc list for all correspondence re facilities HJ Midura should be deleted LIDEN.E A Public Service Electric & Gas Co of New Jersey B3/06/06 VARGA, S A Departing Reactors Branch 1 ip 10838 319 24% Fiche: 50-272,83/06/06,8306140043
- B306140604 Comments on recent near melt-down at facility NRC should begin to enforce regulations as required by law & shut down obviously accident-prone plants
 BATY.D. Affiliation Unknown B3/06/08 NRC No Detailed Affiliation Given 2pp 18833.060 24X Fiche 50-272,83/06/08,8306140604.
- P Operating license stage documents & correspondence
- 8306020562 Clarifies 830219 & 21 environ qualification BERs Upon completion of plant-specific review of all plants, cross-ref of nonqualified equipment will be conducted to determine if same equipment in other plants determined qualified VARQA.B.A Operating Reactors Branch 1 83/05/23 UPERITZ, R A. Public Service Electric & Oas Co. of New Jersey 3pp 18715.120 24X Fiche 50-272,83/05/23,8306020562

- 830&030141 Submits long-term operational verification program for Westinghouse DB-50 reactor trip breakers Data will be used to assess reliability of undervoltage trip attachments Results of program expected in Oct 1783

 UDERITZ.R A Public Service Electric & Gas Co of New Jersey B3/03/31 EISENHUID D Division of Licensing 8pp 18704 283
 24X Fiche 50-272,83/05/31.830&030141
- 8306150064 COPPER IN THE INTAKE AND DISCHARGE ZONES OF THE SURRY AND SALEM NUCLEAR POWER STATIONS HARRISON.F.L. BISHOP.D J. RICE.D W. Lawrence Livermore Laboratory FIN A-0119 NURCO/CR-2965 83/05/31 Division of Health. Biting & Haste Management 51pp Available at NRC \$4.00 18869 221 24X Fiche 50-000.83/05/31.8306150064
- 8306220198 Forwards Vol 5, Number 4 to NUREG-0070, "Rept to Congress on AOs:" for Fourth Quarter CY82 One AO reported at NRC licensees re inoperability of containment spray sys Agreement states reported no AOs AHEARNE, J F Commissioners 83/06/02 O'NEILL, T P House of Rep BUSH, O H W Senate 2pp 18940 024 24X Fiche 50-000, 83/06/02, 8306220198
- 8306140059 Forwards "Analysis of Valve/Operator Interface Hardware for Containment Pressure & Vacuum Relief Valves 1 & 2 VC B," in response to NRC 830517 request LIDEN.E A Public Service Electric & Oas Co of New Jersey. 83/06/07. VAROA.S A Operating Reactors Branch 1 3pp 18838 267 24X Fiche. 50-272, 83/06/07, 8306140059
- --B306140063 "Analysis of Valve/Operator Interface Hardware for Containment Pressure & Vacuum Relief Valves 1 & 2 VC 5 "
 FOLEY, H. WOOL, J C. KRAHER: E W Public Service Electric & Oas
 Co of New Jersey 83/06/03 16pp 18B38 270 24X
 Fiche 50-272,83/06/07.8306140059
- 8306160438 Forwards RA Uderitz affidavit per 830607 response to NRC 830517 ltr re valve operability reviews for 10-inch pressure/vacuum relief valves used for purge or vent of containments
 LIDEN, E. A. Public Service Electric & Gas Co. of New Jørsey 83/06/08 VARGA.8 A. Operating Reactors Branch 1 2pp 18860:074 24X Fiche 50-272,83/06/08,8306160438
- 8306270299 Application for amend to Licenses DPR-70 & DPR-75, revising Amend Requests 79-01 & Bi-19 re radiological effluent & administrative controls & Tech Spacs re surveillance testing & reporting requirements for reactor trip breakers LIDEN.E A Public Service Electric & Cas Co of New Jersey, 82/06/17 VARGAS Operating Reactors Branch 1 Jpp 18994:278 24X Fiche, 50-272, 83/06/17, 8306270299
- --8306270304 Proposed Tech Specs revising radiological effluent & administrative controls & surveillance testing & reporting requirements for reactor trip breakers * Public Service Electric & Oas Co. of New Jersey. 83/06/17 249pp 18994 281 24X Fiche 50-272.83/06/17,8306270299
- 8306270313 Responds to 830523 clarification of SERs re environ qualification of safety-related electrical equipment requesting review of equipment in Categories IV, I. B & II. A LIDEN, E A Public Bervice Electric & Gas Co. of New Jersey 83/06/21 VAROA, B A Operating Reactors Branch I 3pp 19055; 313, 24X Fiche 50-272, 83/06/21,8306290313
- 8306300190 Forwards Offsite Dose Calculation Manual per NRC 790118
 1tr
 LIDEN.E A. Public Service Electric & Fas Co of New Jersey
 83/06/24 VARQA:8 A Operating Reactors Branch 1, 1p 19122 199
 24X Fiche.50-272,83/06/24.8304300190
- --8306300194 Offsite Dose Calculation Manual

 * Public Service Electric & Gas Co of New Jersey 83/03/31,
 75pp. 19122 200 24X Fiche 50-272,83/06/24,8306300190.
- G Inspection reports. IE Bulletins & correspondence
- 8306240046 Discusses IE insp on 830302-06 & forwards notice of violation & proposed imposition of civil penalty. DEYOUNG, R C Director's Office, Office of Inspection and Enforcement. 83/05/05 SMITH, R Public Service Electric & Qas Cq. of New Jersey App 18987 217. 24X Fiche 50-272,83/05/05,8306240046.
- --8306240049 Notice of violation & proposed imposition of civil penalty in amount of \$850,000 Noncompliance noted reactor trip breaker failed to automatically open Pollowing receipt of valid trip signal.

 DEYOUNG.R.C. Director's Diffice Office of Inspection and Enforcement 63/05/05 Bpp 18987. 221. 24% Fiche' 50-272, 83/05/05, 8306240046

- 8305110458 IE Info Notice 83-32. "Ruptured Am-241 Sources Contained in Well Logging Device." Svc list encl TAYLOR.J M Division of Bafeguards & Inspection Programs (Post 830103) 83/05/26 Consolidated Edison Co of New Yor¹, Inc 125pp 18831 043 24% Fiche 50-000,83/05/26,8305110458
- 8305110460 IE Info Notice 83-34, "Event Notification Info Horksheet"

 Byc list encl

 JORDAN, E.L. Division of Emergency Preparedness & Engineering

 Response (Post 830103) 83/05/26 Consolidated Edison Co. of New

 York, Inc. 115pp 18732 085 24X Fiche 50-000,83/05/26.8305110460.
- 8305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods Withdrawn at BWRs " Byo list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/31 Consolidated Edison Co of New York, Inc. 116pp 18732 208, 24% Fiche 50-000,83/05/31,830511046t
- 8305140256 Ack receipt of 830317 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-272/82-36 & 80-311/82-33 BTARDSTECKI.R Division of Project & Resident Programs 83/05/31 UDERITZ.R A Public Service Electric & Gas Co of New Jersey. Ip 18033 019. 24X Fiche: 50-272.83/05/31.8305140256
- --8306140261 Responds to NRC 830215 ltr re violations noted in IE Insp Repts 50-272/82-36 & 50-311/82-33 Corrective actions Operations Directive 12.7ech Spec Interpretations.expanded to include encl Quide-11 & footnotes added to logs UDERITZ.R A Public Service Electric & Gas Co of New Jorsey. 83/03/17. HAYNES.R C. Region 1. Diffice of Director STANOSTECKI.R. Division of Project & Resident Programs 3pp. 18933-020 24X Fiche 50-272,83/05/31.8306140254
- 8304140130 Forwards IE Insp Repts 50-272/83-12 % 50-311/83-13 on 830324-0510 % notice of violation 814803264-0510 % notice of violation 8148032641, R. Division of Project & Resident Programs 83/05/31 UDERITZ.R.A Public Service Electric & Gas Co. of New Jersey 2pp 18862 005. 24% Fiche 50-272,83/05/31,8304140130
- ---8306160137 Notice of violation from insp on 830326-0510 * Region i, Diffice of Director 83/05/31 ip 18862 007 24X Fiche 50-272,83/05/31,8306160130
- --B306160144 IE Insp Repts 50-272/83-12 & 50-311/83-13 on B30326-0510 Noncompliance noted failure to submit timely LERs NORRHOLM, L.J., SUMMERG, R.J., TRIPP, L.E. Region 1, Office of Director, 83/05/27, 17pp 18862:008, 24X Fiche:50-272,83/05/31,8306160130,
- 8306070177 Requests 30-day extension for response to 830509 notice of violation & proposed imposition of civil penalties Belay due to complexity of issues & consideration of available options
 UDERITY.R A. Public Service Electric & Gas Co. of New Jersey 83706/01. DEVOUND.R.C Director's Office. Office of Inspection and Enforcement 2pp 18736.327 24% Fiche 50-272.83/06/01.8306070177.
- 8306160440 Ack receipt of 830415 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-272/83-01 & 50-311/83-01 MARTIN.T.T Division of Engineering & Technical Programs 83/06/07 UDERITZ, R A Public Service Clectric & Gas Co of New Jersey. ip 18844-214 24X Fichs.50-272.83/06/07.8306160440
- --830616044B Responds to NRC 830304 ltr requesting addl info reviolations noted in IE Insp Repts 50-272/83-01 & 50-311/83-01. Corrective actions: Neter N-137 returned to vendor for repair cost estimate.

 UDERITZ, R A Public Service Electric & Oas Co. of New Jersey. 83/04/15. MARTIN.T.T Division of Engineering & Technical Programs. 3pp. 18864 215. 24X Fiche 50-272.83/06/07.8306160440
- 8306210176 Responds to IE Bulletin 83-03, "Check Valve Failures in Raw Hater Cooling Sys of Diesel Generators " Affected check valves associated w/sech diesel generator listed LIDEN.E.A. Public Service Electric & Oas Co of New Jersey 83/06/07 ALLAN.J.M Region 1. Office of Director Spp 18715 237. 24X Fiche. 50-272, 83/06/07. 8306210176.
- 8306230471 Forwards IE Safeguards Insp Repts 50-272/83-17 & 50-311/83-16 on 830516-20. No noncompliance noted.

 MARTIN, T. T. Division of Engineering & Technical Programs. 83/06/08. UDERITZ, R. A. Public Service Electric & Gas Co. of New Jersey 2pp 18941-302. 24X Fiche 50-272,83/06/08.8306230471.
- --8306230475 IE Bafeguards Insp Repts 50-272/83-17 & 50-311/83-16 on 830516-20. No noncompliance noted Major areas inspected: security plan; contingency plan & previously identified items.
 SMITH, C.C., 90BY, A.T. Region 1, Office of Director. 83/06/06. 3pp. 18941-304 24% Fiche 50-272, 83/06/06, 8306230471.

- 8305110464 IE Info Notice 83-36, "Impact of Security Practices on Safe Operations" Svt. list encl JORDAN, E. L. Division of Emergency Preparedness & Enganeering Response (Post 830103) 83/06/09 Consolidated Edison Co. of New York, Inc. 119pp 19830 280 24X Fiche 50-000.83/06/09.8305110464
- 8305110470 IE Info Notice 83-38. "Defective Heat Sink Adhesive & Seismically Induced Chatter in Relays Within Printed Circuit Cards " Syc list encl JORDAN,E I Division of Emergency Preparedness & Engineering Response (Past 830103) 83/06/13 Consolidated Edison Co of New York, Inc. (18pp. 18920 225 24% Fiche 50-000, 83/06/13, 8305110470
- 8306090010 IE Info Notice 83-37, "Transformer Failure Resulting From Degraded Internal Connection Cables " Svc list encl JORDAN-E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co of New York, Inc 243pp 18921 001 24X Fiche 50-000,83/06/13,8306090010
- 8305110475 IE Info Notice 83-40, "Need to Environmentally Qualify
 Epoxy Grouts & Sealers " Svc list encl
 JERDAN, E L. Division of Emergency Preparedness & Engineering
 Response (Past 830103) 83/06/22 Consolidated Edison Co of New
 York, Inc 115pp 19021 179 24X Fiche 50-000,83/06/22,8305110475
- B305110477 IE Info Notice B3-41, "Actuation of Fire Suppression Sys Causing Inoperability of Safety-Related Equipment " Svc list enci JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post B30103) B3/06/22 Consolidated Edison Co of New York, Inc 120pp. 18997 007 24X Fiche 30-000, 03/06/22, 8305110477
- 8305i10479 IE Info Notice 83-42. "Reactor Mode Switch Malfunctions " 8vc list encl JORDANNE L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/23 Consolidated Edison Co of New York, Inc 116pp 18996 242 24X Fiche 50-000, 83/06/23, 8305i10479
- 8305110483 IE Info Notice 83~43, "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints " Svc list encl JORDAN: E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/24 Consolidated Edison Co of New York, Inc 116pp 19046 297 24X Fiche 50-000, 83/06/24, 8305110483
- R Periodic operating reports & related correspondence
- 8306150267 Forwards annual radiological rept for 1982, "Artificial Island Radiological Environ Monitoring Program " LIDEN, E A Public Service Electric & Gas Co of New Jørsey 83/06/02 ALLAN.J M Region 1. Office of Director ip 18049 263 24X Fiche 50-272,83/06/02,8306150267
- --8306150270 "Artificial Island Radiological Environ Monitoring Program," annual radiological rept for 1982 LIDENIE A Public Service Electric & Qas Co of New Jersey RMC-TR-83-03 83/04/20 134pp 18849 264 24X Fiche 50-272,63/06/02,8306150267
- 8306280542 "NPDE9 Discharge Monitoring Repts for May 1983 " W/830606 ltr MILLER, L K Public Service Electric & Oas Co of New Jersey 83/06/06 21pp 19019 343 24% Fiche, 50-272, 83/06/06, 8306280542
- 8306200240 "Annual Environ Operating Rept (Nonradiological), 1982 "
 W/830608 ltr
 LIDEN,E A Public Service Electric & Cas Co of New Jersey
 83/06/08 ALLAN,J M., BORES,R J. Region 1, Office of Director
 19pp 18902 129 24X Fiche 50-272, 83/06/08, 8306200240
- 8306200226 Monthly operating repts for May 1983.W/B30610 ltr MILLER, L K . ZUPKO, J M Public Service Electric & Gas Co of New Jersey B3/06/10 Director's Office, Office of Inspection and Enforcement 14pp, 18702 308 24X Fiche 50-272.83/06/10, 8306200226
- S. Reportable occurrences, LERs & related correspondence
- 830&0704&1 Forwards draft rept, "AEOD Study on Implications of ATW8
 Events at Balem Nuclear Power Plant on NRC Program for
 Collection & Analysis of Operational Experience." Review
 & comments requested by 830&10
 HELTEMESIC. J. Director's Office 83/05/26, DENTON, H.R. Office of
 Nuclear Reactor Regulation. Director DAVIS. J. G. Office of Nuclear
 Material Safety & Safeguards, Director. MINGQUE, R. B. Office of
 Nuclear Regulatory Research, Director. 106pp 16702; 356 24X
 Fiche \$0-272,83/03/24,830&070461

- 8306030197 Staff requirements memo informing of Commission 830513 briefing in Washington.DC on NUREC-1000. "Generic Implications of ATMS Events at Salem Nuclear Power Plant "Operating criteria requested CHILK.S J Diffice of the Secretary of the Commission 83/05/27 DIRCKS, W J Diffice of the Executive Director for Operations 1 18733 313 24X Fiche 90-272,83/05/27.8306030157
- 8306030349 Forwards "Review of PSE&G Corrective Action Program re Reactor Trip Breaker Failures at Salem Generation Station, Unit i " UBERITZ.R A Public Service Electric & Gas Co of New Jersey 83/08/31 EIGENHUT,D Q Division of Licensing ip 18706 127 24X Fiche 50-272.03/05/31,8306030349
- --8306030351 "Review of PBE&G Corrective Action Program re Reactor Trip Breaker Failures at Salem Generating Station,Unit 1 " * Basic Energy Technology Associates 83/05/27 31pp 18706 128 24X Fithe 50-272,83/05/31,8306030349
- 8306170144 LER 83-020/03L-0 on 830506.pins found installed in two spring hangers supporting resistance temp device hypass lines Hanger pins removed & tested & procedure devoloped for lead shielding installation W/830602 ltr FRAHM.R , ZUPKD.J M Public Service Ljectric & Gas Co of New Jersey 83/06/01 ALLAN,J Region I, Office of Director Ap, 18978 351 24X Fichs 90-272.83/06/01.8306170144
- 8306170338 LER 83-022/04L-0 on 830513, entimated 131 uCi of activity released when 350 gallons low level radioactive water pumped into ground Caused by contaminated piping penetration area Control measures implemented W183060) itr FRAHM.R. ZUPKD.J M. Public Service Clectric & Oas Co. of New Jersey 83/06/01 ALAN.J. Region i. Office of Director 5pp 18880 279 24X Ficher 50-272.83/06/01.8306170338
- 8306170381 LER 83-021/03L-0 on 830507, emergency diesel generator 1A tagged out due to broken differential current relay Coused by personnel accidentally breaking glass relay cover Relay cleaned W/830602 ltr FRAHM R. ZUPKO J M Public Service Electric & Cas Co of New Jersey 83/06/01 ALLAN, J Region 1, Office of Director 4pp. 18880 049 24X Fiche 50-272,83/06/01,8306170381
- 8305210189 Supplemental LER 82-035/99X-1 on 820525, fire pump 2 failed to start Caused by damaged fire pump electrical sys voltage regulator/alternator.due to faulty wiring harness Damaged components replaced W/830505 ltr FRAHM.R., ZUPKD, J M Public Service Electric & Qas Co of New Jersey 83/05/01 ALLAN, J Region 1, Office of Director App 18915 018 24% Fiche 50-272,83/05/01,83056210189
- 8306280488 Supplemental LER 82-083/03X-1 on 821102.control room operator observed temp recorder for air temp-delta T channels not printing Caused by failure of pinion gear on chart drive motor Motor replaced W/830606 ltr FRAHM, R, ZUPKO, J M Public Service Electric & Oas Co of New Jersey 83/06/01 ALLANJ Region i, Office of Director App 19018 298 24X Fiche 50-272.83/06/01.8306280488
- 8306190455 Forwards NRR comments on draft AO rept to Congress for First Quarter 1983 DENTON H R Office of Nuclear Reactor Regulation, Director 83/06/07 HELTEMES C J Director's Office 3pp 18830 176 24X Fiche 50-000,83/06/07,8306130455
- 8306280256 Supplemental LER 82-091/01X-1 on 821130, operator discovered leakage from weld of evc water piping to component cooling HX 12 Caused by extensive biofouling & corrosion of circumferential welds W/830614 ltr FRAHM.R. XUPKU.M. Public Service Electric & Oas Co of New Jersey 83/06/08 ALLANJ Region 1, Office of Director 5pp 19014 106 24X Fichs 50-272,83/06/08,8306280256.
- B306240452 Comments on AEOD study re implications of Salem ATHS events on NRC program for collection & analysis of operational experience, per B30526 request Bummary of trip breaker failures at Farley 1 & 2 encl.

 DENTON, H R Dffice of Nuclear Reactor Regulation, Director, B3706/10 HELTEMEGC J, Director's Dffice 6pp 18998-117 24X Fiche, 50-272, 83/06/10, 8306240452
- 8306270269 LER 83-025/03L-0. on 830525, containment air particulate monitor indicated alarm condition w/o receiving purge/pressure relisf isolation function. Causad by channel output alarm relay wire ball out of place. W/830614 ltr. FRAHH.R : ZUPKO. J M Public Service Electric & Gas Co. of New Jersey. 83/06/14. ALAN. J M Region 1. Office of Director 5pp. 18990 204 24% Ficha 50-272.83/06/14.8306270269.

- 8306270343 LER 83-023/01T-0 on 830602, notification received from Westinghouse re-potential increased power peaking in bottom of core Procedures will be implemented to insure operation within Tech Spec limits W/830615 itr FRAHM.R. ZUPKO.J M. Public Service Electric & Oas Co. of New Jersey 83/06/15 ALLAN.J. Region in Diffice of Director 4pp 18993 129 24X Fiche 50-272,83/06/15.8306270343
- U Congressional/Executive Correspondence
- B3060603BB Responds to B30407 ltr re ATHB events & reactor trip breaker malfunctions Language used in 1E bulletins revised to ensure specific & general responses PALLADINO.N J Commissioners 83/05/16 MARKEY.E J House of Rep , Interior & Insular Affairs 24pp 18732 347 24X Fichs 50-272,83/05/16,83060603BB
- --8306060392 Requests info re unreported breaker failures, reporting requirements & reliability of 25 cycle pre-startup testing to better understand LER sys.

 MARKEY,E J. House of Rep., Interior & Insular Affairs 83/04/07.

 PALLADINO,N J. Commissioners 2pp 18753 018 24%

 Fiche 50-272,83/05/16.8306060388
- 8306150533 Responds to 830304 ltr requesting info & responses to questions re 830222 & 25 events Failures of safety sys & broader implications for nuclear power industry discussed FALLADINO, N J Commissioners 83706/02 BIDEN, J R Benate 27pp 18866 334 24X Fiche 50-272,83/06/02.8306150333
- --8306150543 Expresses concern re 830822 & 25 events when manual shutdown of reactor required following failures of automatic safety sys Investigation by NRC requested prior to restart Questions encl for NRC response BIDEN.J R Senate 83/03/04 PALLADING.N J Commissioners.

 3pp 18867 023 24X Fiche 50-272.03/04/02.8306150533

- 8306140036 Requests NRC concurrence in special requalification training program for JD Driscoll Failure of reactor trip breakers in late Fab & ensuing investigation & corrective action development prevented attendance w/scheduled shift.

 LIDEN: E A Public Service Electric & Gas Co of New Jersey 83/06/08 VARGA: 8 A Operating Reactors Branch 1 2pp. 18838-309, 24X Fiche 50-272,83/06/08,8306140036
- 8306140403 Extends invitation to attend 830627 mesting in King of Prussia,PA to discuss transfer of reactor operator licensing function from Bethesda MD to Region I ofc.

 8TAROBIECKI,R Division of Project & Resident Programs 83/06/09.

 UDERITZ,R A Public Service Electric & Gas Co of New Jersey. 2pp. 18638 001 24X Fiche 50-272,83/06/09,8306140403
- DOCKET 50-274 U.S. GEOLOGICAL SURVEY RESEARCH REACTOR
- F Security, medical, emergency & Fire protection plans
- 8306240140 Forwards IE Bafeguards Insp Repts 50-274/83-02 & 70-0121/83-02 on 830418-20 No noncompliance noted. MADBEN, 6 L. Region 4. Office of Director 83/06/20 MILLARD, H. Interior. Dept of. Geological Survey 2pp. 18980
- --8306240148 IE Safeguards Insp Rapts 50-274/83-02 & 70-0121/83-02 on 830418-20. No noncompliance noted Major areas inspected. nuclear matl control & accountability, including facility organization & operations Details withheld (ref 10CFR2 790). CALDWELL, R A , KELLY, J A. F , MESTERMAN, T. F Region 4, Office of Director 83/06/15 ip 18980-164 24X Fiche, 50-274, 83/06/20, 8306240140.
- G Inspection reports, IE Bulletins & correspondence
- 8306240140 Forwards IE Bafeguards Insp Repts 50-274/83-02 & 70-0121/83-02 on 830418-20 No noncompliance noted MADSEN, O. L. Region 4. Office of Director 83/06/20. MILLARD, H Interior, Dept of, Oeological Survey. 2pp 18980, 162, 24X Fiche. 50-274, 83/06/20, 8306240140
- ---8306240148 IE Safaguards Insp Repts 50-274/83-02 & 70-0121/83-02 on 830418-20. No noncompliance noted Major areas inspected nuclear matl control & accountability, including facility organization & operations, Details withheld (ref 10CFR2 790). CALDMELL.R.A , KELLY, J A. F , WESTERMAN, T F. Region 4, Diffice of Director 83/06/15 ip. 18780.164 24X Fiche.50-274,83/06/20,8306240140

- DOCKET 50-275 DIABLO CANYON NUCLEAR POWER PLANT, UNIT 1

 F Security, medical, smargency & fire protection plans
- 8304040155 Notifies that 830418 response to Generic Ltr 82-33 re emergency response capability indicating schedule for implementation of Reg Guide 1 97.Rev 2.would be provided by 830815, supersedes 811022 commitment SCHVLER, J D Pacific Cas & Elactric Co 83/05/31 KNIGHT, G W Licensing Branch 3 2pp 18728 101 24X Fiche. 50-275, 83/05/31, 8304040155
- 8306170196 Ack receipt & provides evaluation of various changes to emergency plan & corporate emergency plan implementing procedures Changes do not decrease effectiveness of emergency response planning NONDERHAUGAL R Region 5. Office of Director 83/06/13 CRANE,P A Pacific Oas & Electric Co 2pp 18882 302 24% Ficha 50-275,83/06/13,8306170196
- 8306170305 Act receipt of Dec 1982, Rev I to San Luis Obispo County swergency response plan FEMA will provide NRC w/written confirmation of results of evaluations NORDERHAUG, L R Region 5, Office of Director 83/06/13 CRANE, P A Pacific Oas Electric Co ip 18877 145 24X Fiche 50-275, 83/06/13, 8306170305

O Adjudicatory correspondence

- 8305040415 Responds to 830421 ltr requesting that meeting be arranged between NRC & person alleging improprieties in PO&E/Bechtel reverification program Individual not inclined to meet w/NRC fearing PO&E/Bechtel reprisals FLEISCHAKER, D. Fleischeker, D. S. 83/04/28 EISENHUT, D. G. Division of Licensing 4pp 18319.327 24X Fiche 50-275,83/04/28,8305040415
- 830A0A01612 Response supporting Governor Deukmejian B30518 motion to reopen record in licensing proceeding re const GA Further evidence newded re const GA/GC Certificate of Suc encl. REYMOLDS.J.R Jaint Intervenors-Diablo Canyon REYMOLDS.J.R Center for Law in the Public Interest 83/05/31 Atomic Safety and Licensing Board Panel. App 18728 184 24% Fiche 50-275,83/05/31.83G40A0182
- 8304060275 Response opposing Joint Intervenors 830510 & Governor Dautaejian 830517 motions to reopen record on const GA.Const GA program vigorous, thorough & in full compliance w/NRC regulations Certificate of 8vc encl NORTON.8 Pacific 0es & Electric Co NORTON.8 Norton, Burke, Berry & French 83/05/31 Atomic Safety and Licensing Appeal Panel 630pp 18730 031 24X Fiche 50-275,83/05/31,8306060275.
- 830&07040& Response supporting Governor Deukmejian 830518 motion to reopen record on const QA Disclosure of thousands of deficiencies warrants reopening Certificate of Svc encl.
 REYNOLDS.J R Joint Intervenors-Diablo Cannon 83/05/31. Atomic Safety and Licensing Appeal Panel 5pp 18742 275. 24X
 Fiche 50-275,83/05/31.8306070406
- B306150314 Notice of appearance in proceeding Centificate of Svc encl. HAVIAN, E. Joint Intervenors-Diablo Canuon. HAVIAN, E. Center for Law in the Public Interest B3/06/02 Spp. 18849 I32 24X Fiche 50-275, 83/06/02, 8306150314
- B306150230 Response opposing Joint Intervenors 830510 & Overnor Daufmejian B30518 motions to reopen record on const GA Movante fail to establish significance of info to GA findings in ABLB 810717 decision. Certificate of Svc encl CHANDLER.L J Hearing Branch 2 83/06/06. Atomic Safety and Licensing Board Panel 196pp. 18850 044 24% Fiche 50-275, 83/06/06,8306150230.
- 830&090307 Order allowing Joint Intervenors & Governor Deukmejian to reply to responses to motions to reopen record on const GA; by B30&20 SHOCHMAER.C. J Atomic Safety and Licensing Appeal Panel 83/06/07. Joint Intervenors-Diablo Canyon 2pp. 18795,171. 24X Fichs: 50-275,83/06/07,830&090309
- 8306150435 Petition for review of ABLB 830518 Decision ALAB-72B, to establish schedule for briefing on issues raised & to reverse ABLAB rulings in ALAB-72B Certificate of Svc encl. REYNOLDB, J. R. Joint Intervenors-Diablo Canyon. REYNOLDB, J. R. Center for Lew in the Public Interest 83/06/08, Commissioners, 15gp. 18847.030. 24X Fiche 50-275.83/06/08.8306150435
- 830 &1 & 08.79 First document production request. Related correspondence NORTON, 9. Pacific Gas & Electric Co. NORTON, 9. Norton, Burke, Berry & Franch. 83/06/10 Joint Intervenors-Diablo Canyon. App. 1886 &: 161. 24X Fichs 50-275, 83/06/10.8306160579.

- --8306160584 First set of interrogatories Related correspondence NORTON.B Pacific Gas & Electric Co NORTON.B Norton, Durke, Berry & French 83/06/10 California, State of 17pp 18866 167 24X Fiche 50-275,83/06/10.8306160579
- --B306160595 First set of interrogatories Cortificate of Svc encl Related correspondence NORTON.B Pacific Gas & Electric Co NORTON.B Norton, Burke, Berry & French 83/06/10 Joint Intervenors-Diablo Canyon 19pp 18866-184 24X Fiche 50-275,83/06/10.8306160579
- B306140702 Notice of withdrawal of appearance in proceeding Certificate of Svc encl
 QCLDBERG.J R Hearing Branch 2 83/06/13 3pp 18841 27; 24X
 Fiche 50-275, B3/06/13, B306140702
- 830622003B Response opposing util & NRC responses to intervenor motions to reopen issue on const GA NRC ignored util improper & rampant disregard of GA requirement & obscssion w/hearing speed & scheduling. Certificate of Bvc cncl
 REYNOLDB.J R Juint Intervenors-Diablo Canyon REYNOLDB.J R
 Center for Law in the Public Interest 83/06/17 Atomic Safety and Licensing Appeal Panel 11pp 19930.180 24X
 Fiche 90-275,83/06/17,8306R20038
- B306220045 Reply to responses of NRC & util to Governor Deukmejion mation to reopen record on const QA Submits new evidence of safety regulation violations & contends NRC & util response unacceptable KAUFMAN.F H. California, State of B3/06/17 Atomic Safety and Licensing Appeal Panel 45pp 18727 259 24% Fiche 50-27%, B3/06/17, B306220045
- --8306220052 Affidavit of R Hubbard re breakdowns in design & const QA/ QC program & implementation Util & NRC did not include significant items in const QA review Implementation of QA/QC measures unacceptable. Certificate of Syc enci HUBBARD.R B California. State of 83/06/15 14pp 18727 305 24X Fiche 50-275, 83/06/17. 8306220045
- 8306240275 Response opposing Joint Intervenors 830608 petition for review of ALAB-728 No important safety, procedural, common defense, antitrust or public policy issues raised Certificate of Svc encl
 CHANDLER, L. J. Hearing Branch 2 83/06/23 Commissioners 14pp 18980:080 24X Fiche. 50-275, 83/06/23, 8306240275
- 8306280522 Answer apposing Joint Intervenors 830608 petition for review of ALAB-728 Joint Intervenors fail to respond to rationale of ABLAB decision Certificate of Svc encl
 CRANE, P A Pacific Gas & Electric CO B3/06/23 Commissioners.
 7pp 19019 317 24X Fiche 50-275,83/06/23,8306280522
- 8306290535 Advises of concerns re evidence presented at 830614 independent design verification program meeting w/util/ Bechtel licensing team Util fails to appraciate meaning/ necessity of program Related correspondence. REYNOLDB.J R. Center for Law in the Public Interest REYNOLDB.J R. Joint Intervenors-Diablo Canyon 83/06/23 DENTON, H R Office of Nuclear Reactor Regulation, Director App 19052 318 24X Fiche: 50-275.83/06/23, 8306290535
- B306280520 Proposes schedule for reopened hearings on design GA NORTON. Il Pacific Gas & Electric Co B3/06/24. Atomic Safety and Licensing Appeal Panel 3pp 19017: 186 24X Fiche 50-275, 83/06/24, 8306280520.
- 8304300052 Order scheduling 830717 hearing on Governor Deukmejian & Joint Intervenors motions to reopen record on const GA issue.NRC to provide ASLB & parties w/NRC insprepts on const GA by 83070B
 BHOEMAKER, C. J. Atomic Befety and Licensing Appeal Panel 83/06/28
 Office of the Executive Legal Director 4pp 19120 189, P4X
 Fiche 50-275,83/06/28,8304300092
- B306300064 Requests that arrangements be made for removal & storage of security matls in NRC storage room Room requires repair & is needed for other purposes CHANDLER, L. J. Hearing Branch 2, 83/06/29, BTRUMHABBER, M. California, State of 1p 19121 011 24X Fiche 50-275,83/06/29,830630064.

H General correspondence

8306010336 Expresses alarm re recent news rept that POLE officials had seen preliminary drafts of NRC investigation rept concerning GA violations. NRC investigation requested. REYNOLDS.J.R. Joint Intervenors—Diable Canyon. REYNOLDS.J.R. Center for Law in the Public Interest. 83/05/25 ETSENHUT, D.Q. Division of Licensing App 18680-072. 24X Fiche-50-275.83/05/25, 8306010336.

- 8306070036 Provides names & addresses for appropriate distribution of technical correspondence or Pacifities 8CHUYLER, J O Pacific Qas & Electric Co 83/06/02 DENTON, H R Office of Nuclear Reactor Regulation, Director EISCNRUT, D C Division of Licensing MARTIN, J B Region 5, Office of Director 2pp 18739 337 24X Fiche 50-000,83/06/02,8306070036
- P Operating license stage documents & correspondence
- B30&020&19 Notification of B30520 meeting w/util & Westinghouse in Monroeville.PA to discuss seismic qualification of main control board SCHIERLING.H Licensing Branch 3 83/05/18 KNIGHTON.G W Licensing Branch 3 4pp 18702 359 24X Fiche 50-275.83/05/18.830&020&19
- 8305110468 Board Notification 83-74 forwards info items for design verification program including verification of effects of high energy line cracks & semimonthly status rept M/o encl EISENHUT, D, G Division of Licensing 03/05/27 PALLADING, N J. of Linkky, V , AHEARNE, J F Commissioners 3pp 24X Fiche 50-275,83/05/27.8305110448
- 830.6070270 Forwards application for amend to License DPR-76 changing level of reporting of manager & GA to executive vice president of facilities & electric resources development SCHUYLER, J O Pacific Gas & Electric Co 83/05/27 DENTON, H R Office of Nuclear Reactor Regulation, Director ip 18740 274 24X Fiche 50-275,83/05/27.8306070270
- --B306070275 Application for amend to License BPR-76 changing level of reporting of manager & QA to executive vice president of facilities & electric resources development BCHUYLER.J O Pacific Gas & Electric Co B3/05/27 2pp 18740 297 24X Fiche 50-275.83/05/27.8306070270
- --8306070278 Proposed Tech Specs thanging reporting level of manager & QA to executive vice president of facilities & electric resources development * Pacific Gas & Electric Co 83/05/27 2pp 18740 297 24X Fichs 50-275,83/05/27,8306070270
- 8306030162 Forwards response to Generic Ltr 83-10C re plans & schedules for resolution of TM1 Action Item II K 3 5, "Automatic Trip of Reactor Coolent Pumps" Util not required to submit analyses supporting selection of pump trip criteria SCHUYLER, J 0 Pacific Gas & Electric Co 83/05/31 EISENHUT, D 0 Division of Licensing 7pp 18703-344 24X Fiche 50-275, 83/05/31, 8306030162
- 8304070463 Forwards design verification program status summary as of 830506 Engineering effort & mod const required to be completed prior to fuel load DIRCKS, W J. Office of the Executiva Director for Operations 83705/31 PALLADING, N J., OILINBKY, V., AHEARNE, J F., Commissioners 12pp 18780 318 24X Fithe 50-275,83/05/31,8306070463
- 8306240473 Summary of 830520 meeting w/Hestinghouse & util in Monroeville,PA re seismic qualification of main control board SCHIERLING,H Licensing Branch 3 83/05/31 KNIGHTON, 0 W Licensing Branch 3 4pp 10997-357 24X Fiche 50-275,83/05/31, 8306240473
- 8306080068 Describes independent design verification program position on satsmic reevaluation of turbine bldg & intake structure Corrective action reviewed from standpoint of both licensing & technical considerations WRAY,R. Teledyne Engineering Services. 83/06/03 DENTON,H R Office of Nuclear Reactor Regulation, Director MATIN,J B Region 5, Office of Director MANEAIIS,O A Pacific Oss & Clastric Co. 2pp 19773 191 24X Fiche, 50-275, 83/06/03, 8306080068
- 8306080199 Board Notification BN-83-77 forwards JR Reynolds 830525 & DC Eisenhut 830603 ltrs addressing allegation re prerelease of NRC rept on allegad deficiences in GA program implementation at facility EIEENHUT.D C Division of Licensing. 83/06/03 PALLADING.N., GILINSKY.V. AHEARNE.J Commissioners. 9pp. 18772-223 24X Fichs 50-275,83/06/03,8306080199
- ~-B3060B020i Ack receipt of B30525 ltr re potential prerelease of NRC rept. Ofc of Inspector & Auditor requested to investigate matter Commission & ASLAD will be informed EIBENHUT, D. Division of Licensing, B3/06/03, REYNOLDB, J. R. Center for Law in the Public Interest 2pp 18772 231 24X Fiche, 50-275, 83/06/03, 83060B0199

- 830A240474 Ack receipt of 830525 ltr re potential prerelease of NRC rept re independence of design verification program Ofc of Inspector & Auditor requested to investigate Commission & ASLAD being informed via board notification EISENHUT.D O Division of Licensing 83/O6/O3 REYNOLDS, J. R. Center for Law in the Public Interest 4pp. 18798 071 24X Fiche 50-275.83/O6/O3.8306240474
- 8306240464 Forwards request for add1 info needed to complete review of safety-related masonry walls & necessary corrective actions based on review of 810701 submittel Info requested within 60 days of litr receipt KNIGHTON.0 W Liconsing Branch 3 83/06/07. CRANE.P Pacific Cas & Electric Co 5pp 18998 103 24% Fiche 50-275,83/06/07.
- 8306140031 Forwards background for two articles published in Telegram—Tribune re welding deficiencies Info confirms misunderstanding between util & reporter At no time did util review NRC drafts of subj rept SCHUYLER.J O Pacific Gas & Electric Co 83/06/09 EISENHUT.D 0 Division of Licensing 2pp 18838 331 24X Fiche 50-275.83/06/09, 8308140031
- 8306280491 Forwards 1tr from project info specialist giving background for two articles in Ban Luis Obispo Telegram-Tribune No one from util reviewed any NRC draft repts
 8CHUYLER.J O Pacific Cas & Electric Co B3/06/09, E18ENHUT.D.Q.
 Division of Licensing 2pp 19018 295 24X Fiche: 50-275, 83/06/09, 8706990551
- 8305110471 Board Notification 83-78 forwards matls re independent design verification program by participating organizations info relevant to safety issue on design adequacy of plant EISENHUT, D.G. Division of Licensing 83/06/10 PALLADING, N. OILINSKY, V. AHEARNE, J. Commissioners 3pp 18847.313 24X Fiche 50-275,83/06/10.8305110471.
- --8305230345 Trip rept of 830406-07 visit to sits & Bechtel ofcs in San Francisco, CA re insp of technical calculations supporting Diablo Cangon project internal technical program POLK: H Structural & Geotechnical Engineering Branch. 83/05/13, LEAR: O Structural & Geotechnical Engineering Branch. 5pp 18848-025 24X Fichs 50-275,83/06/10,8305110471.
- --8305230135 Trip rept of 830329-30 site meetings w/independent design verification program personnel & licensee re progress on analysis of turbline bids & containment annulus steel structure & auxiliary/fuel handling bids POLK.H E Btructural & Gentechnical Engineering Branch 83/05/16. LEAR,G Structural & Gentechnical Engineering Branch 5pp. 18848 030 24x Fiche 50-275,83/06/10,830510471.
- --8306150R76 Transcript of 830520 meeting in Monroeville,PA re seismic qualification of panel on main control board.Pp 1-125 Supporting documentation encl # Commissioners 83/05/20 182pp. 18848 052 24X Fiche 50-275,83/06/10,8305110471
- ~-8306150281 Transcript of NRC independent design verification program 830521 meeting in Boston MA Pp 1-90 * Commissioners 83/05/21, 92pp 18848-234, 24X Fiche 50-273-83/06/10,8305110471
- 8306210111 Comments on util 790914 & 1228 submittals re moderate energy line breaks. Info responds to NRC request to evaluate plant design for effects of line breaks on equipment required for safe shutdown Shield barrier requirements sliminated. SCHUYLER, J. D. Pacific Qas & Electric Co. 83/06/15 KN10HTON, Q. W. Licensting Branch 3 ip 18914.178 24X Fichs.50-275.83/06/15, 8306210111
- 8305110481 Board Notification 83-81: forwards 830609 ltr from JD Schuyler providing info on allegation that util received preliminary NRC rept prior to official release. EISENHUT. D 0 Division of Licensing 83/06/17. PALLADINO, N. J., OILINSKY, V., AHEARNE, J. F. Commissioners. 2pp 18926:034. 24X Fiche. 50-275, 83/06/17, 8305110481
- 8306170313 Advises of B30614 meeting w/util & consultants in San Francisco.CA to discuss status of Phase I engineering open item & Phase I programs COOPER, W E , CRAOIN.J G , Teledyne Engineering Services. 83/06/17. DENTON.H R , MARTIN.J S , NRC No Detailed Affiliation Given, MANEATIS.9 A . Affiliation Unknown ip. 18877.068 24X Fiche.50-275,83/06/17,8306170313.
- 8306170328 Announces 830615 meeting w/NRC in San Francisco, CA to discuss auxiliary bldg structures & polar crans/rail sefort, as part of independent design verification program. COOPER. W E. CRAGIN. J. G. Telsdyne Engineering Services. 83/06/17 DENTON, H R. MARTIN. J B. SCHIERLING. M.E. NRC No Detailed Affiliation Given. 1p. 18878:251. 24X Fiche. 50-275.83/06/17, goods.70388.

- K305110489 Board Notification 63-080 forwards ltrs & repts re status of activities performed as part of design verification efforts Encls include M Reich 630517 ltr.TM Bishop 830519 lt & "Semianothly Status Rept for May 1983" W/o ancl. EISENHUT, D. G. Division of ticensing 63/06/20 PALLADIND, N. J. GILINSKY, V. A. HARNE, J. F. Commissioners 3pp 18993:038 24X Fiche 50-275,83/06/20,8305110489
- 306280332 Forwards revised schedule for completion of activities required for fuel loading, low power testing & full power operation Tanget schedule for licensing milestones encl Const will be completed by 830902 w/fuel loaded by 830930 SCHUYLER, J C. Pacific Oas & Electric Co. 83/06/23 EISENHUT, D C. Division of Licensing Spp 19001, 318 24X Fiche. 50-275, 83/06/23, 8306280332
- 306280388 Forwards application to amend License DPR-76, changing Tech Space re containment spray timing Class III amend fee encl 8CHUYLER.J O. Pacific Gas & Electric Co. 83/06/23. DENTON, H R Diffice of Nuclear Reactor Regulation, Director 1p 19014 001 24 Fiche: 50-275,83/06/23,8306280388
- -8306280394 Application for amend to License DPR-76, changing Tech Space we containment spray timing BCHUYLER, J. 0. Pacific Gas & Electric Co 83/06/23 3pp 19014.002 24X Fiche, 50-275, 93/06/23, 8306280388.
- -8306280396 Proposed Tech Baec changes re containment spray timing * Pacific Oss & Electric Co. 83/06/23 52pp 19014:005 24: Fiche.50-275,03/06/23,8306280388
- 306280565 Expresses concern re util failure to rept that auxiliary bldg slabs not qualified for in-plane loadings, per independent design verification program 830614 meeting restatus of error open items.

 REYNOLDS, J. R. Joint Intervenors-Dieblo Canyon, REYNOLDS, J. R Center for Law in the Public Interest. 83/36/23, DENTON: H Dffice of Nuclear Reactor Regulation. Director App 19017 332 24X Fiche. 50-275,83/06/23,8306280565.
- 306300211 Forwards Rev O to "Guppl for As-Builts "
 BCHUYLER, J. D Pacific Qas & Electric Co. 83/06/24 EISENHUT, D O
 Division of Licensing. Ip. 19119 IB4 24X Fiche: 50-275, 83/06/24, 83063000211
- -8306300217 Rev O to "Suppl for As-Builts" * Pacific Cas & Electric Co. 83706/24 18pp. 19119-185 24X Fichs: 50-275, 83706/24, 8306300211.
- 105110499 Board Notification 83-87 forwards info item re design verification program
 EIBENHUT, D. Division of Licensing 83/06/27, PALLADING, N.J.,
 BILINSKY, V., ROBERTS, T.M. Commissioners, 2pp. 19053, 035 24X
 Fichs; 50-273, 83/06/27, 8305110499,
- 8306290476 Notification of 830617 meeting w/BML, RL Cloud Assoc, TES, Bechtel & util in Bethesda, MD to discuss saismic analysis of buried tanks SCHIERINO, H. Licensing Branch 3. 83/06/15 KNIGHTON, O. W. Licensing Branch 3 20pp. 24X Ficher 50-275, 83/06/27, 8305110499.
- O5110500 Board Notification 83-089; forwards PNO-V-83-22A dtd 830A23 re add1 potential violations of min wall thickness of RCS cicins.
- piping.
 EIBENAUT, D. O. Division of Licensing 83/06/29 PALLADING, N J
 GILINBRY, V., AMEARNE, J.F. Commissioners. 3pp. 19122:040. 24X
 Fiche: 50-275,83/06/29,8305110500.
- Inspection reports, IE Sulleting & correspondence
- Odiococy Addl response to Folk request for documents dtd 820101 or after re SALF.Forwards App A documents. Documents also available in PPR.
 FELTON.J M Division of Rules and Records. B3/04/11. CLARK.R. Bar Francisco Examiner. 3pp. 18813.252 24X Fiche. 50-000, 83/04/11. B306100009.
- B306100014 Bubmits acheduls for Region V BALP Board meetings for B20928-B30823 ENGELKEN, R.H. Region 5, Office of Diractor, B2/03/19, DENTON, H.R. Office of Nuclear Reactor Regulation, Director, DAVIG. J. O Office of Nuclear Material Bafety & Bafeguards, Director MICHELBON, C. Director's Office, ip. 18815: 255 24% Fiche: 50-000, B3/04/11, B306100009.
- B306100036 Discusses assignment of BALP coordinators for Reactor Operations Projects Brench Pacifities. Coordinators will be responsible for preparing input data used by board members in analyzing functional areas. Draft note from 8 Miner and STERNBERG, D. M. Region 5, Office of Director. 82/03/24, Region 5, Office of Director. 82/03/24, Fiche: 50-000,83/04/11,8306100009.

- 830&0703&0 Forwards 1E Insp Repts 50-275/83-15 & 50-323/83-12 on 830&18-22 No noncompliance noted 818HOP.T W Region 5. Office of Director 83/05/03 CRANE.P A Pacific Gas & Electric Co 2pp 18742 116 24X Fiche 50-275.83/05/03.830&0703&0
- --8306070369 IE Imsp Repts 50-275/83-15 & 50-323/83-12 on 830418-22 No noncompliance noted Major areas inspected const activities & mods to annulus structural steel, ventilation durt supports, containment spray piping supports & carcuit breakers BUHDDIN, J F. 7 XHETZ10,6 B Region 5. Office of Director 83/04/29, 5pp 18742 118 24X Fiche 50-275,83/05/03,8306070360
- 8306070093 Forwards IE Insp Repts 50-275/83-14 & 50-323/83-11 on 830301-02 & 31 No moncompliance noted BISHOP.T W Region 5. Office of Director 83/05/11 CRANE,P A Pacific Gas & Electric Co 2pp 18739 135 24X Fiche 50-275,83/05/11,8306070093
- --8306070098 IE Insp Repts 50-275/83-14 & 50-323/83-11 on 830301-02 & 31 No nuncompliance noted Major areas inspected IE bulletins & circulars, followup on previous licenses commitments & independent insp.

 MORRILL, P. J. KIRSCH, D. F. Region 5, Office of Director 83/05/09 4pp 18739 137 24% Fichs 50-275,83/05/11,8306070093
- 8305110458 IE Info Notice 83-32, "Ruptured Am-241 Bources Contained in Well Logging Device " Svc list encl TAYLOR, J M. Division of Safeguards & Inspection Programs (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 125pp 18831 043 24X Fichs 50-000,83/05/26,8305110458
- B305110460 IE Info Nutice B3-34, "Event Notification Info Worksheet" 8vc list encl. JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post B30103) B3/05/26 Consolidated Edison Co of New York, Inc. 115pp 18732 085 24x Fiche 50-000,83/05/26,8305110460
- 8304280189 Forwards IE Insp Repts 50-275/83-17 & 50-328/83-13 on B30403-30 & notice of violation W/o notice of violation B18HOP, T W Region 5. Office of Director 83/05/26 CRANE, P A Pacific Gas & Electric Co 2pp 19014 124 24X Fiche: 50-275,83/05/26,8306280189
- --8306280174 IE Insp Repts 50-275/83-17 & 50-323/83-13 on 830403-30 Noncompliance noted failure of general const personnel to inform plant manager of observed damage to RCB piping CARLSON, J. D. MENDONCA, M. M. KIRBCH, D. F. Region 5. Office of Director 83/05/25 10pp 19014 1P6 24X Fiche 50-275,83/05/26,8306280187
- 8305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods Withdrawn at BWRs " Svc list encl JORDAN.E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 80705/31 Consolidated Edison Co of New York, Inc 116pp 18732 208 24X Fiche 50-000,83705/31,8305110461.
- 8304300041 Responds to IE Bullstin re check valve failures in raw water cooling sys of dissel generators Check valves not used in closed-loop jacket cooling water sys.

 SCHUYLER, J O, CRANE, P A Pacific Gas & Electric Co 83/06/06

 MARTIN, J B Region 5, Office of Director 2pp 17168, 127 24X

 Fichs 50-275,83/06/04.8306300041
- 8305110464 IE Info Notice 83-36. "Impact of Security Practices on Safe Operations " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/09 Consolidated Edison Co. of New York, Inc 119pp 18830 280 24X Fiche 50-000,83/06/09,8305110464
- 8305110470 IE Info Notice 83-38, "Defective Heat Sink Adhesive & Beismically Induced Chatter in Relays Within Printed Circuit Cards" "Byt list enc!
 JURDAN,E, L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13, Consolidated Edison Co. of New York, Inc. 118pp 18920,225 24x Fiche 50-000,83/06/13,8305110470
- 8304090010 IE Info Notice 83-37, "Transformer Failure Resulting From Degraded Internal Connection Cables " Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83704/13 Consolidated Edison Co of New York, Inc 243pp. 18921:001 24X Fishe 50-000,83704/13,8304090010
- 8305110475 IE Info Notice 83-40, "Need to Environmentally Qualify Epoxy Grouts & Bealers" Svc list encl.

 JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/22. Consolidated Edison Co. of New York, Inc. 115pp. 19021 179 24X fiche 50-000,83/06/22,8305110475

- 8305110477 IE Info Notice 83-41, "Actuation of Fire Suppression Sys Causing Inoperability of Safety-Related Equipment " Syc list
 - enci JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/22 Consolidated Edison Co of New York, Inc 120pp 18997 007 24X Fiche 50~000,83/06/22,8305110477
- 8305110479 IE Info Notice 83-42, "Reactor Mode Switch Malfunctions"
 - 3051104/9 IE 1876 Notice 83-42. Theatter Mode Switch Maifunctions " Svc list encl JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/23 Consolidated Edison Co of New York, Inc. 116pp 18996 242 24X Fichs 50-000,83/06/23,8305110479
- B309110483 IE Info Notice 83-43, "Improper Bettings of Intermediate Range (IR) High Flux Trip Setpoints "Svc list oncl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) B3/06/24 Consolidate Edison Co of New York, Inc 116pp 19046 297 24X Fiche 50-000,83/06/24,8305110483
- B305j10492 Board Notification B3-B3 forwards info re violations of NRC reporting requirements re min wall thickness on RCS piping EISENHUT.D 0 Division of Licensing B3/06/24 FALLADINO.N J , OILINSKY, V AHEARNE.J F Commissioners 3pp 18996 228 24X iche 50-275, 83/04/24, 8305110492
- --8306270342 Forwards IE Insp Rept 50-275/83-20 on 830523-0606 & notice of violation. W/o notice of violation BIBHOP, T W Region 5, Office of Director 89/06/17 BCHUYLER, J D. Pacific Gas & Electric Co. 2pp 17046 104. 24X Fiche 50-275,83/06/24,8305110492
- --B306270344 Notice of violation from insp on 630523-0606 KIRSCH, D F Region 5, Office of Director 83/06/17. 18996, 233 24X Fiche 50-275, 83/06/24, 8305110492 83/06/17. 2pp
- --8305270350 IE Insp Rept 50-275/83-20 on 830523-0606 Noncompliance noted licensee failed to promptly notify NRC of materially reportable conditions re min well thickness on RCS piping HERNANDEZ.G H. MENDONCA.M M. KIRBCH.D.F. Region 5. Office of Director. 83/06/17 6pp. 18796; 236 24X Fiche 50-275,83/06/24,8305110492
- B30.6300083 Ack receipt of 830519 ltr informing NRC of steps taken to correct violations noted in IC Insp Rept 50-279/83-08 BIBHOP, T W. Region 5. Office of Director. B3/06/24 BCHUYLER, J C. Pacific Gas & Electric Co. ip. 19048 335 24X Fiche, 50-275, B3/06/24, B306300083.
- --8306300089 Supplemental response to NRC 830329 ltr re violations noted in IE Insp Rept 50-275/83-08 Corrective actions reinsp of 10% of fillet welded connections complete Insufficient training of new welders & inspectors cause of deficiencies CRANE,P A Pacific Gas & Electric Co. 83/05/19 MARTIN.J.8. Region 5, Office of Director. Spp 19048.336. 24% Fichs 80-278.83/06/24.8306300083
- --8306300093 Responds to NRC 830327 ltr re violations noted in IE Insp Rept 50-275/83-08. Corrective actions: HP Foley Procedure GCP-5A will be revised to clarify requirements for stemping walds by welders & inspectors CRAME.P.A. Pacific Oas & Electric Co. 83/04/25 MARTIN.J.B Region 5, Office of Director 4pp. 17048.341. 24X Ficher 50-275,83/06/24,8306300083
- A Periodic operating reports & related correspondence
- 8306020214 Monthly operating rept for Mar 1783 W/830411 ltr. KELLY, W. J., THORNBERRY, R. C. Pacific Gas & Electric Go 83/04/11. Office of Resource Management. Director. 9pp. 18691.120 24X Fiche 50-273, 83/04/11.8306020214
- 8306160535 Monthly operating rept for Apr 1983.W/830503 ltr KELLY,W J. THORNBERRY,R C. Pacific Gas & Electric Co. B3/05/03 Office of Menagement and Program Analysis. 5pp. 18864.044 24X Fishe 50-275.83/05/03.8306160535
- 8304010347 Forwards updated sections of Phase I final rept for design varification program, covering fuel handling & turbine bldgs. Large-bore & small-bore piping & HVAC equipment results. GRANE, P.A. Pacific Gas & Electric Go. 83/05/18. EISENHUT, D. O. Division of Licensing 262pp. 18680:151 24X Fiche. 50-275, 82/05/18 2620-10247 83/05/18, 8306010347
- B304010317 Forwards "Dieblo Canyon Nuclear Power Plant Independent Design Verification Program," semimonthly rept for May 1983 COOPER.W E. Teledyne Engineering Services B3/05/27. DENTON.H.R Office of Nuclear Reactor Regulation, Director. MANEATIS, 0.A. Pacific Que & Electric Co. MARTIN.J B Region 5, Office of Director ip. 18480 Q01 24X Fiche 50-275,83/05/27.8304010317

- --8306010317 "Diablo Canyon Nuclear Power Plant Independent Design Verification Program," semimonthly rept for May 1783 * Teledyne Engineering Bervices 83/05/27 49pp 18680:002, 24% Fichs 50-275,83/05/27.8306010317
- 8304070272 Forwards design verification program.semimonthly Rept 38 for 830510-23 per Commission Order CLT-81-30 8CHUYLER, J O Pacific Gas & Electric Co 83/05/27 DENTON, H R. Office of Nuclear Reactor Regulation, Director 1p 18741, 217 24X Fiche 50-275, B3/05/27, B306070292
- --8306070297 "Diablo Canyon Verification Program," semimonthly Rept 3B 706/7027/ "Diaplo Canyon Verification Program," semimonenty Rept : for 830510-23 * Pacific Gas & Electric Co 83/05/27 64pp 18741 218, 24X Fiche 50-275,83/05/27,8306070292
- 8306170293 Discusses preliminary dreft of revised interim technical rapts re latest revs concerning independent design verification program Documents provided for info & not comment H/o encl
 COOPER, W.E. Teledyne Engineering Services 83/05/27.
 8CHIERLING, H.E. Diffice of Nuclear Reactor Rayllation, Director FRAY, R. Bechtel Corp. BISHOP, T.E. Region 5. Office of Director 3pp. 18878 171 24X Fiche 50-275,83/05/27,8306170293.
- 8306100130 Forwards "Diablo Canyon Nuclear Power Plant Unit 1 Independent Design Verification Program," third text submittal of final rept Next submittal scheduled for 830415 & final submittal scheduled for 830415 & final submittal scheduled for 830430 COOPER, W E Teledyne Engineering Services. 83/05/31 DENTON, H. R Office of Nuclear Reactor Regulation, Director MARTIN, J. B. Region 5, Office of Director. MARCATIB. 04. Pacific 0as & Electric Co. 2pp 16806 069. 24% Fiche 50-275,83/05/31,8304100130
- --8306100134 "Diable Canyon Nuclear Power Plant Unit 1 Independent Design Verification Program," third text submittal of final rept.

 * Teledyne Engineering Services. 83/05/31. 183pp 18806.071.
 24X Fiche 50-275,83/05/31,8306100130
- 830610016B Forwards Rev i to "Verification of High Energy Line Break & Internally Generated Missile Review Gutside Containment for Auxiliary Feedwater Bys & Control Room Ventilation & Pressurization Gys." Interim Technical Rept 23
 KRECHTING, J.E. Btone & Hebster, Inc. 83/06/02, DENTON, H.R. Office of Nuclear Reactor Regulation, Director MARTIN, J.B. Region 5, Office of Director MANEATIS, 9.4 Pacific Gas & Electric Co. 1p. 18806,035 24X Fiche 50-275,83/06/02,830610016B Dffice
- --8306100171 Rev 1 to "Verification of High Energy Line Break & NOALOUTT NEV I to "Verification or high Energy line Break & Internally Generated Missile Review Outside Containment for Auxiliary Feedwater Bys & Control Room Ventilation & Pressurization Bys." Interim Technical Rept 23, BESTAKF Stone & Webster, Inc 83/05/27, 32pp 18806-0 Fiche 50-275,63/06/02,8306100168 18806-036 24X
- 8304140524 Forwards "Diable Canyon Verification Program, Samimonthly Schuyler, J. D. Pacific Cas & Electric Co. 83/06/10 DENTON, H. R. Office of Nuclear Reactor Regulation Director, MARTIN. J. B. Region 5, Office of Director ip, 18863 328 24X Fichs. 50-275,83/06/10,
- --8306160527 "Diable Canyon Verification Program, Semimonthly Rept 39, "
 * Pacific Gas & Electric Co 83/06/10, 66pp, 18863-327 24X
 Fichs, 50-275, 83/06/10, 8306160526
- 8306170308 Forwards Open Itam Repts 1123-1132 for independent design verification program semimonthly repts Conflict of interest statements for individuals assigned to program completed DENISBON.E Robert L. Claud Associates, Inc. B3/06/10 DENITON, H. R. Office of Nuclear Reactor Regulation, Director MARTIN.J.S. Region 5, Office of Director MAREATIN.J. B. Region 12pp. 18877 133 24X Fiche.50-275.83/06/10,8306170308.
- 8306170312 Forwards "Diable Canyon Nuclear Power Plant Independent Dawign Verification Program June Second Friday Semimonthly Rest: Design vertices.

 Rept."

 COOPER, W. E. Teledyne Engineering Bervices. 83/06/10. DENTON, H.R. Office of Nuclear Reactor Regulation. Director. MARTIN, J.B. Regio 5. Office of Director MANEATIS. 9. A Pacific Gas & Electric Co. 1p 18877 069. 24X Fiche 50-275.83/06/10,8306170312. Region
- -8306170315 "Dieblo Canyon Nuclear Power Plant Independent Design Verification Program June Second Friday Bemimonthly Rept. " * Teledyne Engineering Services. 83/06/10 35pp 18877:070. 24X Fiche. 80-275.83/06/10,8306170312. 18877: 070.
- 8306170350 Forwards June 1983 semimonthly open item rept.
 KRECHTING, J.E. Stone & Webster Engineering Corp. B3/06/10
 DENTON, H.R. Défice of Nuclear Reactor Regulation, Director
 MARTIN, J.B. Region 5, Office of Director HANEATIB, Q.A. Pacific
 Gas & Electric Co., 13pp. 18879-027 24X Fiche 50-275, 83/06/10,
 B306170350

- 8306170270 Forwards corrected pages to Apps 01 & 02 to draft Interim Technical Repts 36 & 38 W/o encis COOPER.W E Teledyne Engineering Services. 83/06/13 MORRE.T S Atomic Safety and Licensing Board Panel ip 18878:154 24X Fiche: 50-275,83/06/13.8306170270
- 6306210162 Forwards "Phase II Final Rept Design Verification Program," per 811119 ltr specifying requirements for add1 info BRAND, D A Pacific 9as & Electric Co 83/06/13 DENTON, H R. Office of Nuclear Reactor Regulation, Director. 1p 18915 290 24: Fiche. 50-275,83/06/13.8306210162
- --8306210171 "Phase II Final Rept. Design Verification Program " * Pacific Gas & Electric Co 83/06/30 100pp 18915 291 24X Fiche. 50-275. 83/06/13. 8306210162.
- 8306200249 Forwards "Diablo Canyon Nuclear Fower Plant Unit I Independent Design Verification Program Final Rept," fourth text submittal Final text submittal scheduled for 830630 COOPER, N E. Teledyne Engineering Services 83/06/15, DENTON, H R. Office of Nuclear Reactor Regulation, Director MARTIN, J B Region 5, Office of Director MANEATIS, Q. A Pacific Gas & Electric Co 2pp 18901 111, 24% Fiche 50-275, 83/06/15, 830620249.
- --8306200252 "Diablo Canyon Nuclear Power Plant Unit 1 Independent Design Verification Program Final Rept." Fourth text submittal * Tetadyne Engineering Services. 83/05/16. 59pp 18901 [13 24% Fiche 50-275,83/06/15,8306200249
- 8305110489 Board Notification 83-080. forwards ltrs & repte re status of activities performed as part of design verification efforts Encls include M Reich 830517 ltr. TH Bishop 830517 ltr & "Bemisonthly Status Rept for May 1983" W/v encl EISEMAUT, D. G. Division of Licensing 83/06/20, PALLADINO, N. J. O'LLINEKY, V. A HEARNEJ, J. Commissioners 3pp 18993 038, 24% Fiche 50-275,83/06/20,8305110489
- 8304280483 Forwards Errata 2 to Rev 0 to "Independent Design Verification Program Final Rept " GOOPER, M E. Teledune Engineering Services 83/06/20 DENTON, H R Office of Nuclear Reactor Regulation, Director. MARTIN, J. B. Region D. Office of Director. MANEATIS, 2, A. Pacific Gas & Electric Co. 24pp. 19018 263 24X Fiche 50-275,83/06/20,8306280483.
- 8306270416 Forwards Rev 3 to "Independent Design Verification Program, Final Rept."

 COOPER, M.E. Teledyne Engineering Services, 83/06/22 DENTON, H R. Office of Nuclear Reactor Regulation, Director MARTIN, J B. Region 5, Office of Director MANEATIB, G. A. Pacific Qas & Electric Co Zpp 18992:152 24X Fishe 50-275,83/06/22,8306270416
- --8306270477 Rev 3 to "Independent Dasign Verification Program, Final Rept " + Yeledyne Enginearing Services 83/06/21. 180pp. 18992:156 24X Fichs. 50-275, 83/06/22, 8306270416.
- 8305110495 Board Notification 83-086 forwards SMW "June Semimonthly Rept." RL Cloud Assoc "June Open Items Repts." & Taledyns Engineering SVcs "Independent Design Verification Program TEB June Semimonthly Rept "
 EISEMHUT.D. 0. Division of Licensing 83/06/24 PALLADING.N.J., OLLINGS.V.V., AHEARNE.J.F. Commissioners. 3pp. 0 18992.336 24X Fiche: 80-275,83/06/24,8305110495.
- 8305110498 Board Notification 83-85 forwards Teledyne Engineering Sycs "Independent Design Verification Program Final Rept Fourth Test Submittal." Info will be considered in formulating recommendation re reinstatement of low power license EISEN-NUT, D.O. Division of Licensing. 83/06/24. PALLADINO, N., GILINSKY, V., AMEARNE, J. Commissioners. Spp. 19015 108. 24X Fiche: 30-275, 83/06/24, 8305110498.
- 9306280469 Forwards "Diable Canyon Nuclear Plant Independent Design Verification Program," semimenthly status rept for June 1983 COOPER, H.E. Teledyne Engineering Services 83/06/24. DENTON, H.R. Office of Nuclear Reactor Regulation, Director. MARTIN, J.B. Region 5, Office of Director HANEATIS, G.A. Pacific Oas & Electric Co. ip. 19020-044 24% Fiche: 50-275, 83/06/24, 8306280469.
- --8306280470 "Diablo Canyon Nuclear Power Plant Independent Design Verification Program," semimonthly rept for June 1983 A Teledyne Engineering Services. 89/06/24 71pp 19020-045. 24X Fiche: 50-275, 83/06/24, 8306280469.

- 8304290397 Forwards Rev 1 to "Final Rept on Const GA Evaluation of OF Atkinson Co." Interim Technical Rept 36 & Rev 2 to "Final Rept on Const GA Evaluation of Hismor & Becker," Interim Technical Rept 39 B W/o Interim Rept 39 SESTAKIF Stone & Webster Engineering Corp 83/06/24 DENTON.H R Office of Nuclear Reactor Replation. Director MANEATIS, G A Pacific Gas & Electric Co MARTN.J B Region 5. Office of Director 1p 19055 041 24X Fiche 50-275,83/06/24.8306290397
- --8306290401 Rev I to "Final Rept on Const GA Evaluation of GF Atkinson Co," Interim Technical Rept 36 BESTAK.F Stone & Webster Engineering Corp 83/06/20 149pp 19055 043 24X Fiche 50-275.83/06/24.8306290397
- --8306290545 Rev 2 to "Independent Design Verification Program, Final Rept on Const GA Evaluation of Wismer & Becker "Interim Technical Rept 38 SEBTAK, F Stone & Webster Engineering Corp 83/06/20 226pp 19049 051 24X Fiche 50-275,83/06/24,8306290397
- 8 Reportable occurrences. LERs & related correspondence
- 8306090174 PNO-V-83-020 on 830504,100 uC; Cs-137 check spurce found missing from gas decay tank discharge monitor RE-22 Licensee believes source stolen On 830415,9 uC; Cs-137 source found missing All sources removed from monitors OARCIA, E, WENSLAWSKI,F Region 5, Office of Director 83/05/04 p 18792,270 24X Fichs 50-275,83/05/04,8306090174
- 8306100067 LER 83-007/01T-0 on 830509, water leaked from weld area of reinforcement pad on branch connection to non-vital loop C component cooling water sys Caused by flow in root pass of shop weld Repairs to be made W/830523 ltr KELLY, H J , SHIFFER, J D Pacific Oas & Electric Co 83/05/23 HARTIN, J B Region 5. Office of Director 3pp 18802 175 24X Fiche 50-275,83/05/23,8306100067
- 8306100082 LER 83-006/01T-0 on 830510, possible undersize condition found on weld MID-RC 2-17 Cause under investigation Below min wall thickness welds to be analyzed or repaired per ASME Section XI W/830523 ltr
 KELLY, W J , BHIFFER J D Pacific Gas & Electric Co 83/05/23 MARTIN, J B Region 5, Office of Director 3pp 18802 229 24) Fiche 50-275, 83/05/23, 8306100082
- 8306230422 LER 83-005/04X-0 on 830502.prior to fuel Joad & following Coalings earthquake.unusual event declared based on earthquake motion felt at plant w/ 5 q full upscale indication Caused by faulty reset switch W/B30601 itr KELLY,N J . BHIFFER.J D Pacific Oas & Electric Co 83/06/01 MARIIN,J B Region 5. Office of Director 3pp 18943 211 24X Fichs 50-275,83/06/01,8306230422
- 8306230365 LER 83-009/03L-0 on 830505, power switch to plant vent indine sampler (RE-24) found in off position Power switch inadvertently moved to off position during const Const personnel cautioned W/830606 ltr KELLY,W J. SHIFFER.J D Pacific Oss & Electric Co 83/06/06 MARTIN,J.B. Region 5. Defice of Director 2pp 18944 126 24X Fiche 50-275,83/06/06,8306230365
- 8306210164 LER 83-008/03L-0.on 830510.const electrician inadvertently deenergized new fuel storage area monitor (RM-5) & oily water separator effluent line monitor (RM-3).resulting in loss of bus 1-1A caused by lifting wrong wire M/830607 ltr. KELLY.W J. SMIFTER.J D Pacific Qas & Electric Co 83/06/07 MARTIN.J. B Region 5. Office of Director 2pp 18718 097 24X Fiche:50-275,83/06/07.8306210164
- 8306210044 LER 63-014/01T-O: on 630526.during adjustment of Limitorque operator, binding of torque switch observed. Cause under investigation Torque switch mounting bolts substituted for original bolts. W/630607 itr
 KELLY.W J. SHIFFER.J D Pacific Cas & Electric Co 83/06/09 MARTIN.J B Region 5. Diffice of Director 2pp 18712:277 24X Fiche: 50-275, 83/06/09.83062:0044
- 8306210078 LER 83-010/03L-0 on 830514.prior to fuel load, power to all main control room annunciators lost during const in annunciator cabinets Caused by electrician touching hot wire to ground, short circuiting panel W/630403 itr.
 KELLY.N.J., SHIFFER.J D Pacific Oas & Electric Co 83/06/13 MARTIN.J B Region 5, Office of Director 3pp 18911 229, 24% Fichs 50-275, 83/06/13, 8306210078
- 830628042i LER B3-013/03L-0 on B305i8.prior to fuel load, air sample pumps for plant vent radiation monitors RM-14A & B tinoperable Caused by removal of control & instrument fuses for work inside RM28 A & B cabinet W/8306i7 ltr KELLY.M. J. BHIFFER, J D Patific Cas & Electric Co. B3/06/17. MARTIN. J B Region 5. Office of Director, 3pp 19018 303 24X Fiche: 50-273,83/06/17.830628042i.

- 8306280523 LER 83-012/03L-0 on 830518 prior to fuel load, air sample pumps for plant vent radiation monitors found tripped Caused by excessive debris clogging radiation monitor filter paper due to const artivities M/830617 ltr
 KELLY, W J , SHIFFER, J D Pacific Oas & Electric Co 83/06/17 MARTIN, J B Region 5. Office of Director ip 19019 313 24X Fiche 50-275,83/06/17,8306280523
- 8306280526 LER 83-011/03L-0 an 830518 prior to fuel load discovered source check of oily water separator effluent line monitor not performed monthly Caused by administrative error during procedure rev W/B30617 ltr KELLY, W J , SHIFFER, J D Pacific Oas & Electric Co 83/06/17 MARTIN. J B Region 5. Office of Director 3pp 19019 286 24% Fiche 50-275,83/06/17.8306280526
- 8305110486 Board Notification 83-72 forwards info item re potential violation of min wall thickness on RCB pipe at facility Region V currently examining licensee response to incident EISENHUT, D G Division of Licensing 83/06/20 PALLADING, N, GILINSKI, V, AHCARNE, J Commissioners 3pp 18780 146 24X Fiche 50-275,83/06/20,8305110486
- ---8306240316 Confirms 830910 telcon re potential for one weld in reactor coolant loop 2 below min wall thickness Ultrasonic thickness testing indicates that pipe to pipe weld in reactor coolant pump less than design min wall thickness SHAFFER. J D Pacific Gas & Electric Co 83/05/11 MARTIN, J E Region 5, Office of Director 1p 18900 149 24X Fiche 50-275.63/06/20.8305110486
- 8305110488 Board Notification 83-73 forwards 830507 ltr & PNO-V-83-021 re potential for inadequate welds in component cooling water piping sys
 EISENHUT, D @ Division of Licensing 83/06/20 PALLADING, N J .
 GILINGKY, V . AHEARNE, J F Commissioners App 18978 003 24X
 Fiche 50-275,83/06/20,8305110488
- 8304280017 PNO-V-83-022A on B30522, personnel determined that RCS piping in areas of welds other than reported on B30510 may be less than min wall thickness Reduction in wall thickness occurred during original preservice exam KIRSCH, D F Region 5, Office of Director 83/04/23 ip 19001 119 24X Fiche 50-275,83/04/23,8306280017

T Hearing transcripts on non-antitrust matters

- 8305110471 Board Notification 83-78 forwards matts re independent design verification program by participating organizations. Info relevant to safety issue on design adequacy of plant EIBENHUT, D @ Division of Licensing 83/06/10 PALLADING, N, GILINSKY, V, AHEARNE, J Commissioners 3pp. 18847-313 24X Fiche 50-275,03/06/10.8305110471
- --8306150276 Transcript of 830520 meeting in Monroeville.PA re seismic qualification of panel on main control board Pp i-J25
 Supporting documentation encl
 * Commissioners 83/05/20 182pp 18848 052 24X
 Fiche 50-275.83/06/10.8305110471
- --8306150281 Transcript of NRC Independent design verification program 830521 meeting in Boston MA Pp 1-90.

 * Cammissioners 83/05/21 92pp 19848 234 24X Fiche 50-275.83/06/10.8305110471.
- 8305110499 Board Notification 83-87 forwards into item re design verification program
 EISENHUT, D & Division of Licensing 83/06/27 PALLADINO, N. J. oILINSKY, V. ROBERTS, T. M. Commissioners 2pp 19053 035 24x
 Fiche 30-275, 83/06/27, 8305110499
- --8306290470 Transcript of 830617 public meeting in Bethesda, MD re design verification program. Pp 1-45

 * Commissioners 83/06/17 48pp 24X Fiche: 50-275, 83/06/27,
- --B306290476 Notification of 830617 meeting w/BNL, RL Cloud Assoc, TEB, Bechtel & util in Bethesda, MD to discuss seismic analysis of buried tanks SCHIERLING, H Licensing Branch 3 83/06/15 KNIGHTON, G W Licensing Branch 3 20pp. 24X Fiche 50-275, 83/06/27, 8305110499

V Operator Examinations

8306240465 Approves B30315 request for variance in std cold license certification on program, allowing abbreviated 5 wk version of Phase II program for 11 on-shift operators, KNICHTION 6 W. Liconsing Branch 3 B3706/13 CRANE, F A. Pacific Oak & Electric Co 2pp 18998 101 24X Fiche 50-275,83/06/13,830620465

- DOCKET 50-277 PEACH BOTTOM ATOMIC POWER STATION, UNIT 2

 F. Security, medical, emergency & fire protection plans
- B304030094 Informs that NUREG-0737, Item III A 2 1. "Emergency Preparedness, Upgrade Emergency Plans to App E.10CFR50." complete Item closed STOLZ, J.F. Operating Reactors Branch 4 B3/05/18 BAUER, E. Q. Philadelphia Electric Co. 3pp. 18733 293 24X Fichs 50-277, 83/05/18, 8306030096
- 8304070223 Forwards IE Insp Repts 50-277/83-09 & 50-278/83-09 on B30402-0512 No noncompliance nated BTAROSTECKIR Division of Project & Resident Programs B3/05/24, DALTROFF, S L Philadelphia Electric Co 2pp. 18744 112 24X Fichs 50-277, 83/05/24, 8306070223
- --8306070226 IE Insp Repts 50-277/83-09 & 50-278/83-09 on 830402-0512 No noncompliance noted Major areas inspected accessible portions of facilities, operational safety; radiation protection, physical security & control room activities.

 BLOUGH, A R . WILLIAMS. J. H. . MCSREARTY: R A Region 1. Office of Director 83/05/23 14pp 18746.114 24X Fiche.50-277.83/05/24, 8304070223
- 8306060157 Forwards "Fire Protection Mod Progress Rept," per 830225
 1tr.Request for exemptions re smoke detection & penstration
 seals & description of addl administrative controls dealing
 w/transignt combustibles also enr!
 BOYER,V 8 Philadelphia Electric Co 83/05/27 EISENHUT,D 0,
 Division of Licensing 8pp. 18732 059. 24X Fiche 50-277,83/05/27,
 8306060157
- --8306060158 "Fire Protection Mod Progress Rept " W/four oversize drawings Aperture cands are available in PDR * Philadelphia Electric Co 83/05/27 9pp 18732 067. 24X Fiche 50-277.83/05/27,8306060157
- 8306140381 Releases public version of revised emergancy plan implementing procedures FELTON, J M Division of Rules and Records 83/06/06 Document Management Branch 1p 18853 216 24% Ficher50-277,83/06/06, 8306140381
- --830&140371 Forwards public version of revised emergency plan implementing procedures, including Procedures EP-201 retechnical support ctr activation. EP-207 re radiation protection team activation & EP-207C re first aid DALTROFF, 8 L Philadelphia Clactric Go 83/05/24, ALLAN, J. M. Region i, Office of Director 2pp 18853: 217 24X Fichs 50-277,83/04/06.8306140381
- --8306140398 Public version of revised emergency plan implementing procedures, including Procedures EP-201 re technical support ctr activation, EP-205 re radiation protection team activation & EP-207C re first aid.

 ** Philadelphia Electric Co 83/04/25 145pp. 18853:219, 24% Fiche 50-277,83/04/06,8306140381
- 8306200159 Ack receipt of 830504 ltr informing NRC of steps taken to correct violations noted in IE Imap Repts 50-277/83-04 & 50-27683-04,
 MARTIN.T T Division of Engineering & Technical Programs. 83/06/14
 DALTROFF.8 L. Philadelphia Electric Co. 2pp. 16902 357, 24X
 Fichs 50-277,63/06/14.8306200159
- --8306200165 Responds to NRC 830404 ltr re violations noted in IE Insp Rapts 50-277/83-04 & 50-278/83-04 Corrective actions withheld (ref 10CFR2 790 & 73.21) DALTROFF.8.L. Philadelphia Electric Co 83/05/04. MARTIN.T.T. Division of Engineering & Technical Programs. ip. 18902-359. 24) Fiche 50-277.83/06/14.8306200159

P Operating license stage documents & correspondence

- 630-6030110 Forwards mafety evaluation re BHR Owners Group 601230 response to NUREO-0737, Item II K. 3. 45, "Depressurization W/Other Than Automatic Depressurizations 64s "No mod to plant design or operation required 8TOLZ.J F. Operating Reactors Branch 4, 83/05/18 BAVER, E G. Philadelphia Electric Co 2pp 16733: 297, 24X Fiche 50-277, 63/05/18, 630-6030110.
- 8304020279 Forwards responses to NRC questions addressed at 830520 meeting & provides description of augmented leak detection sus & interim surveillance requirements

 DALTROFF, B L Philadelphia Electric Co 83/05/23. EISEMHUT, D Q
 Division of Licensing 81pp. IB694.108, R4X Fiche. 50-277,83/05/23.

 8306020299

- --8306020303 Rev 4 to Procedure PB 83-1. "Ultrasonic Exam of Welds in
 - Pipe,"
 # General Electric Co B3/04/05 53pp 18694 166 24X Fiche: 50-277, 83/05/23, 8306020299
- 8306020325 Informs that lead responsibility transferred from Region I to NRR for review of pipe crack indications evaluation of response to IE Bulletin 83-02 approval of Unit 3 restart & acceptability of continued operation of Unit 2 BTOLZ, J F Operating Reactors Branch 4 83/05/23 DAUER, E 0 Philadelphia Electric Co 2pp 19715 299 24X Fiche 50-277, 83/05/23, 8306020325
- 8306020378 Forwards "Creck Orouth Analysis of Peach Bottom Unit 2 RHR Flaw," providing addl info to support continued operation of facility, per Util 830523 Its DALTROFF,8 L. Philadelphia Electric Co 83/05/26 E18ENHUT, D 0 Division of Licensing ip 18495 122 24X Fiche 50-277, 83/05/26, 8304037378 Division of Licensing 8304020378
- ---8306020379 "Crack Growth Analysis of Peach Bottom Unit 2 RHR Flaw "
 RANGANATH, S. General Electric Co 83/05/25 19pp. 18695 123
 24X Fiche 50-277, 83/05/26, 8306020378
- 8306070363 Responds to 830202 request for add1 info re NUREG-0737. Item II K 3 R8, "Verify Qualification of Accumulators on Automatic Depressurization Bys Valvas." H/ans oversize drawing Aparture card is available in PDR DALTROFF, S L Philadelphia Electric Co 83/06/02 SYDLZ. J F Operating Reactors Bysanch 4 lipp i8743 075 24% Fiche 50-277,83/06/02,8304070363
- --B306070374 Rev O to "Burveillance Test: ST 2 1 23A, Calibr of PT/PR 8102A & PT/FI/PB/DPS 8143A " + Philadelphia Electric Co 82/06/07 16pp 18743 087 24X Fiche: 50-277, B3/06/02, B306070363
- --8306070376 Rev 0 to "Burveillance Test.ST 2 1 238. Calibr of PT/PR 81028 & PT/PI/PS/OPB 81438."

 * Philadelphia Electric Co 82/07/15 1600 18743 103 24X
 - e c:/raznazumo 81438." + Philadelphia Electric Co 82/07/15 16pp 18743 103 24X Fiche=50-277.83/06/02.8306070363
- --8305070379 Rev O to "Surveillance Test ST 2 5 30A, Calibr of FT-8130A,
- --8306070383 Rev 5 to "Surveillance Test ST 7 9 2, Daily Check of Seismic Cas Supply Sottle Pressures"

 * Philadelphia Electric Co 83/03/17 lipp 18743.125 24X
 Fiche 50-277.83/06/02,8306070363
- --8306070387 Rev O to "Burveillance Test. ST 20 129, LLRT ADB Back-Up Bupply Penetrations N-47 & N-1028 " * Philadelphia Electric Co 82/05/23 15pp 18743 136 24X Fiche: 50-277, 63/06/02, 6306070363
- --B306070391 Rev O to "Surveillance Test BT 30 131.AD8 Accumulator Check Valve & Bolennid Valve LLRT" * Philadelphia Electric Co. 81/10/14. Iipp 18743.151 24X
- --8304070395 Rev 3 to "Burveillance Text-BT 13 28, ADS Relief Valve Solenoid Valve Functional." * Philadelphia Electric Co 83/03/17 5pp 18743 142 24X Fichs. 50-277.83/04/02,8304070363

Fiche 50-277,83/06/02,8306070363

- --8306070398 Nev 1 to "Burveillance Test.ST 2 6 3A, Calibr Check of PT-9202A & PR-9102A (Green Pen)." + Philadelphia Electric Co. 83/03/11. I6pp 18743 167 24X Fiche: 50-277, 83/06/02, 8306070363
- --8306070403 Rev 1 to "Burveillance Test:87 2 6 238, Calibr Check of PT 91028 & PR 9102 (Green Pen) " + Philadelphia Electric Co. 83/03/10 18pp. 18743.189, 24X Ficha:50-277.83/03/02,8306070363
- 8304090219 Forwards revised Tech Spec Pages 36 & 36m to limiting condition of operation to make 811223 application for emend to Tech Specs re reactor protection sys consistent w/model Tech Spec.per NRC 830511 telcon request DALTROFF.8 L Philadelphia Electric Co 83/06/02, 8TOLZ, J F Operating Reactors Branch 4. 2pp 18796, 115 24X Fiche: 50-277, 83/06/02, 8306090219
- --8306090226 Revised Tech Spec Pages 36 to 36a changing limiting condition of operation to be consistent w/model Tech Bpec re reactor protection sys.

 * Philadelphia Electric Co. 83/06/02, 2pp 18796.117 24X
 - 83/06/02, 2_{PP} 18796.117 24% Fiche: 50-277, 83/06/02, 8306090219

- 8305170471 Forwards evaluation of BWR Owners Group generic response to NUREO-0737. Item II K 3 18 "Automic Depressurization Bys Logic Mods" Two of seven alternatives acceptable One alternative should be chosen for facility mod STOLZ, J F Operating Reactors Branch 4 83/06/03 BAUER, E G Philadelphia Electric Co 9pp 18894 338 24X Fiche 50~277,83/06/03.8306170471
- 8306280138 Forwards "Control of Heavy Loods Philadelphia Electric Co, Peach Bottom Atomic Power Station Units 2 & 3," draft technical evaluation rept STGLZ.J F Operating Reactors Branch 4 83/06/14 BAUER.E Q Philadelphia Electric Co 2pp 19043 359 24X Fichs 30-277,83/06/14,8306280138
- --8306060329 "Control of Heavy Loads: Peach Bottom Atomic Power Station, Units 2 & 3." draft technical evaluation rept BDMBERGER, C R Franklin Institute/Franklin Research Center NRC-03-81-130 TER-C5506-379/380 83/05/17 NRC No Detailed Affiliation Given 45pp 19043 361 24X Fiche 50-277,83/06/14, 8306280138
- 8306280156 Forwards revised safety evaluation re degraded grid voltage protection for Class IE power sys.based on review of util 820512,0722 & 1029 submittals & LLL technical evaluation rept Class IE adequately protected 8TCLZ, J.F. Operating Reactors Branch 4 83/06/14 BAUER, E.Q. Philadelphia & Electric Co. 3pp. 19046 072 24X Fiche 50-277,83/06/14.8306280156
- --8306280162 Revised safety evaluation re degraded grid voltage protection for Class IE sys Proposed electrical design mods acceptable Office of Nuclear Reactor Regulation, Director 19046-075 24X Fichs 50-277.83/06/14.8306280156 83/06/08 7pp
- --8306280167 Supplementary safety evaluation re proposed testing Frequency for depraded grid protection sys Request for 6-month test should be denied Testing should be performed monthly Office of Nuclear Reactor Regulation, Director 9046 079 24% Fiche 30-277,83/06/14,8306280156 83/06/14 5pm
- --B304070100 Rev 1 to "Proposed Design Mods & Tech Spec Changes on Grid Voltage Degradation for Peach Bottom Atomic Power Station, Units 2 & 3," technical evaluation rept BELAN, J C Lawrence Livermore Laboratory FIN A-0250 UCID-19115 ROI B3/03/11 NRC No Detailed Affiliation Given 10pp 19045 084 24X Fiche: 50-277, 83/06/14, 8306280156
- B306270261 Forwards application for amend to Licenses DPR-44 & DPR-56 revising list of shock suppressors to reflect mode made since last amend to B10324 application BRADLEY.E J Philadelphia Electric Co B3/06/22 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 19990 181 24X Fiche. 50-277, 83/06/22, 8306270261
- ---8306270264 Application for amend to Licensus DPR-44 & DPR-56, revising list of shock suppressors to reflect mode made since last amend to 810324 application BAUER.E 0 . BRADLEY.E J Philadelphia Electric Co 83/06/22 5pp 18990 182 24X Fiche 80-277,83/06/22,8306270261
- --8306270268 Proposed Tech Spec Table 3 ii D i revising list of shock suppressors to reflect mods made since last amend to 810324 application
 * Philadelphia Electric Co 83/06/22 3pp 18790 187 24X Fiche 50-277,83/04/22,8306270261
- O Inspection reports. IE Bulletins & correspondence
- 8304220181 Discusses IE insps on Bii013-820915 & forwards notice of violation & proposed imposition of civil penalty HAYNES.R C Region i. Office of Director 83/03/29 DDYER, V Philadelphia Electric Co 6pp 18977 318 24X Fiche 80-277,83/03/29,8304220181
- --B306220191 Notice of violation & proposed imposition of civil penalty in amount of \$140.000 Noncompliance noted improper valve lineups, inadequate valve lineup verifications, improper use of test procedures & inadequate monitoring of parameters HAYNEB,R C Region 1, Office of Director 83/03/29 Bpp 18777 324, 24X Fiche: 50-277.83/03/29.8306220181
- 8306030291 Fowards IE Enforcement Conference Repts 50-277/83-13 # 50-27/83-13 on #30504 Na noncompliance noted

 # TARRUSTECKI, R Division of Project & Resident Programs. #37/05/20,

 DALTROFF, B L Philadelphia Electric Co 2pp 18708 336, 24X

 Fichs 50-277, 83/05/20, 8306030291

- --8306030312 IE Enforcement Conference Repts 50-277/83-13 & 50-278/83-13 on 830506 No noncompliance noted Major topics discussed violations of procedural controls & Tech Spec requirements BLOUGH.A R , WILLIAMS.J H , MCCABE,E C Region 1. Office of Director 83/05/13 4pp 18708 337 24X Fiche 50-277,83/05/20,8306030271
- 8306020279 Forwards responses to NRC questions addressed at 830520 meeting & provides description of augmented leak detection sys & interim surveillance requirements DALTROFF.S L Philadelphia Electric Co 83/05/23 EISENHUT.D @ Division of Licensing Sipp 18694 158 24X Fiche 50-277,83/05/23,830602099
- --8306020303 Rev 4 to Procedure PB 83-1. "Ultrasonic Exam of Welds in Pipe " * General Clectric Co 83/04/05 53pp 18694 166 24X Fiche 50-277,83/05/23,8306020299
- 8304020325 Informs that lead responsibility transferred from Region I to NRR for review of pipe crack indications, evaluation of response to IE Bulletin 83-02, approval of Unit 3 restart & acceptability of continued operation of Unit 2 STOLZ, J F Operating Reactors Branch 4 83/05/23 BAUER, E G Philadelphia Electric Co 2pp 18715 299 24X Fiche 50-277,83/00/23,8304020325
- 8306060162 Forwards IE Insp Repts 50-277/83-12 & 50-278/83-12 on 830418-22 & notice of violation MARTIN.T T Division of Engineering & Technical Programs 83/05/23 DALTROFF.8 L Philadelphia Electric Co 2pp 18719 197 24X Fiche 50-277.83/05/23.8306060162
- --8306060166 Notice of violation from insp on 830418-22 * Region 1, Office of Director B3/05/23 lp 18719 199 24X Fiche 50-277,88/05/23,8306060162
- --8306060170 IE lnsp Repts 50-277/83-12 & 50-278/83-12 on 830418-22 Nancompliance noted failure to follow jumper log procedures & GA plan RICHARDS, B. ANDERSON, C Region 1, Diffice of Director 83/05/16 5pp 18719 200 24X Fiche 50-277,83/05/23,8306060162
- 8306070223 Forwards IE Insp Repts 50-277/83-07 & 50-278/83-09 on 830402-0512 No noncompliance noted 8TAROSTECKI, R Division of Project & Resident Programs, 83/05/24 DALTROFF, 8 L Philadelphia Electric Co 2pp 18746, 112 24X Fiche 50-277, 83/05/24, 8306070223
- --8306070226 IE Insp Repts 50-277/83-09 & 50-278/83-09 on 830402-0512 No noncompliance noted Major areas inspected accessible partions of facilities operational safety radiation protection, physical security & control room activities BLOUGH. A R. WILLIAMS, J. H. MCBREARTY, R. A. Region 1, Office of Director 83/05/23 lépp 18746 114 24X Fiche 50-277,83/05/24,8306070223
- 8303110458 IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in Well Logging Device." Svc list encl TAYLOR, J M. Division of Safeguards & Inspection Programs (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc. 125pp 18831 043 24X Fiche 50-000,83/05/26,8305110458
- 8305110460 IE Info Notice 83-34, "Event Notification Info Worksheet" Svc list entl.
 JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26. Consolidated Edison Co. of New York, Inc. 115pp 18732,085 24X Fiche, 50-000, 83/05/26, 8305110460
- 8305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods Withdrawn at BWRs " Svc list encl.

 JURDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/31 Consolidated Edison Co of New York, Inc 116pp 18732-808, 24X Fiche 50-000,83/05/31,8305110461.
- 830&1&0054 Notification of 830&1& significant licensee meeting in Delta, PA to discuss BALP
 TRIPP, L E. Region 1, Office of Director, 83/0&/02. DIRCKS, W J,
 Office of the Executive Director for Operations STELLO. V. Regional
 Operations & Generic Requirements DEVOUNO.R C. Director's Office,
 Office of Inspection and Enforcement 1p 18892 327, 24X
 Fichs 50-277,83/0&/02,830&1&0054
- 8306200125 Forwards IE Insp Repts 50-277/83-11 & 50-278/83-11 on B30419-22 No noncompliance noted MARTIN.T T. Division of Engineering & Technical Programs 83/06/06. DALTROFF.8 L. Philadelphia Electric Co 2pp 18903-291 24X Fichs 50-277.83/06/06.8306200125

- --8306200130 IE Insp Repts 50-277/83-11 t 50-278/83-11 on 830419-22. No noncompliance noted Major areas inspected inservice testing of pumps & valves: local leak rate testing, integrated leak rate testing & facility tours
 PULLANI,S V , BETTENHAUSEN,L Region 1, Office of Director 83/06/01 10pp 18903 293 24% Fiche 50-277: 83/06/06.8306200125
- 8305110464 IE Info Notice 83-36, "Impact of Security Practices on Safe Operations " Bvc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/07 Consolidated Edison Co of New York, Inc 117pp 18830 280 24X Fiche 50-000,83/06/09,8305110464
- 8306140258 Ack receipt of 830526 itr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-277/83-07 & 50-278/83-07 MARTIN.T T Division of Engineering & Technical Programs B3/06/09 DALTROFF, BL Philadelphia Electric Co ip. 18833.027 24X Fichs 50-277,83/06/09.8306140288
- --8306140262 Responds to NRC B30429 ltr re violations noted in IE Insp. Repts 50-277/83-07 & 50-278/83-07 Corrective action, radiation area immediately reposted & health physicist assigned to amonitor reactor bldg. GALLAOHER, J. W. Philadelphia Electric Co. 83/05/26 MARTIN, T. T. Division of Engineering & Technical Programs 2pp 18833-028 24X Fiche 50-277,83/06/09,8306140258
- 8304140483 Ack receipt of 830517 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-277/82-10, 50-278/82-10, 50-278/82-14 & 50-278/82-14
 STAROSTECKI.R Division of Engineering & Technical Programs 83/06/10 DALTROFF, & L Philadelphia Electric Co 1p. 18844:124
 24X Fichs 50-277,83/06/10,8306140483
- --8306160486 Responds to NRC B30418 ltr re violations noted in IE Insp. Repts 50-277/82-10, 50-278/82-10, 50-277/82-14 & 50-278/82-14 Corrective actions personnel reinstructed re procedural controls governing operation

 DALTROFF, B L Philadelphia Electric Co. 83/05/17. STAROSTECKI, R. Division of Project & Residont Programs Spp. 18864 125 24X Fiche. 50-277, 83/06/10, 8306160483
- B3062B0235 Responds to IE Bulletin 83-03, "Check Valve Failures in Raw Mater Cooling Bys of Diesel Generators." Two check valves identified which could fail & possibly prevent coolant from reaching diesel generators
 QALLAGHER, J W Philadelphia Electric Co. 83/06/10 ALLAN, J. M Region 1, Dffice of Director Spp 19015 030 24%
 Fichs 50-277,83/06/10,83062B0235.
- 8305110470 IE Info Notice 83-38, "Defective Heat Sink Adhesive & Beismically Induced Chatter in Relays Within Printed Circuit Cards "Syc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103), 83/06/13 Consolidated Edison Co. of New York, Inc. 118pp 18920 225 24X Fiche 50-000,83/06/13,8308110470
- 8306090010 IE Info Notice 83-37, "Transformer Failure Resulting From Degraded Internal Connection Cables " Byo list and.
 JURDAN E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co of New York, Inc. 243pp. 18721 001 24X Fiche 80-000,83/06/13,8306090010
- 8306200159 Ack receipt of 830504 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-277/83-04 & 50-278/83-04 MARTIN.T. T Division of Engineering & Technical Programs B3/06/14 DALTROFF,S L Philadelphia Electric Co 2pp. 18902 357 24X Fiche.50-277,83/06/14.8306200159
- --8306200165 Responds to NRC 830404 ltr re violations noted in IE Insp Repts 50-277/83-04 & 50-278/83-04, Corrective actions withheld (ref 100FR2 790 & 73 21) DALTROFF,8 L. Philadelphia Electric Co 83/05/04, MARTIN, T. T. Division of Engineering & Tschnical Programs. 1p 18902:359, 24X Fiche 50-277,83/06/14,8306200159,
- 8305110475 IE Info Notice 83-40, "Need to Environmentally Qualify Epoxy Grouts & Sealers " Svc list encl.
 JORDAN.E L. Division of Emergency Preparadness & Engineering Response (Post 630103) 83706/22 Consolidated Edison Co. of New York, Inc. 115pp 19021-179 24X Fiche. 50-000, 83/06/22, 8305110478,
- 8305ii0477 IE Info Notice 83-41. "Actuation of Fire Suppression Sys Causing Inoperability of Safety-Related Equipment "Syc list enc! JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 630i03). 83/06/22 Consolidated Edison Co. of New York, Inc. 120pp 18997 007. 24X Fiche 50-000, 63/06/22, 8305ii0477

- 8305110479 IE Info Notice 83-42, "Reactor Mode Switch Malfunctions "
 Svc list end.
 JORDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post B30103) 83/06/23 Consolidated Edison Co of New
 York, Inc. 116pp 18996 242 24X Fiche, 50-000, 83/06/23, 8305110479
- 8305110483 IE Info Notice 83-43. "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints " Svc list encl JORDAN E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/24. Consolidated Edison Co of New York, Inc. 116pp 17046 277 24X Fiche 50-000,83/06/24.8305110483.

R. Periodic operating reports & related correspondence

- 8306170163 Rev i to "Peach Bottom Atomic Power Station Units 2 & 3 Semiannual Effluent Release Rept 14, Jul-Dec 1982. " W/830606 1tr FLEISCHMANN, R. ALDEN, W.M. Philadelphia Electric Co. 82/12/31 ALLAN, J.M. Region I. D
- 8306160379 Monthly operating repts for Apr 1983 H/830512 ltr ALDEN, H M . CODNEY, H. J. Philadelphia Electric Co 83/05/09 10pp. 18860 092 24X Fiche. 50-277, 83/05/09, 8306160379.
- 8306210076 Monthly operating repts for May 1983 W/830615 itr ALDEN.M.H., CODNEY.M.J. Philadelphia Electric Co., 83/06/10 Director's Office, Office of Inspection and Enforcement 12pp 18913 350. 24X Fiche 50-277,83/06/10

S. Reportable occurrences, LERs & related correspondence

- 8306020277 LER 83-0i1/OiT-0: on 830506, during forced outage, indications found in heat affected zone of 20-inch RHR shutdown cooling suction line weld Gaused by interprenular attrast corrosion cracting Mater sensitive tape applied to welds N/830520 ltr COONEY, M. J. Philadelphia Electric Co. 83/05/20. ALLAN, J M Region 1. Office of Director. 7pp 18690-325 24X Fiche 50-277, 83/05/20, 830602077
- 8306020279 Forwards responses to NRC questions addressed at 830520 meeting & provides description of augmented leak detection sys & interins surveillance requirements:

 DALTROFF, S.L. Philadelphia Electric Co. 83/05/23. EISENHUT, D. C. Division of Licensing 81pp. 18674 158. 24X Fiche 50-277,83/05/23,8306020279
- 8306020396 LER 83-004/03L-0. on 830424, refueling floor ventilation radiation monitor REZ-17-432D experienced downscale spike Caused by defective Geger/Hueller tube Tube replaced k faulty connector rebuilt.
 COOMEY. M. J. Philadelphia Electric Co. 83/05/24, ALLAN, J. M. Regior I. Office of Director. 1p 18694 361. 24X Fiche: 50-277, 83/05/24, 8306020396.
- 8305170017 LER 83-012/01T-0 on 830511, inadequaries found in fire walls & penetration seals in eight emergency switchgear rooms & four emergency battery rooms, Caused by const or design error. W/830525 ltr.

 COONEY, M. J. Philadelphis Electric Co. 83/05/25. ALLAN. J M. Region i. Office of Director. 5pp 18882:247 24X Fiche: 50-277, 83/05/25, 8305170017
- 8304170278 LER 83-010/03L-0. on 830427, sample line flow mater indicated no flow & 3-way selector valve 8V-2524 found stuck, Caused by dirt buildup inside solenoid valve, (ABCO Model 8-36-734). Valve tapped & flow returned.

 COONEY, M J Philadelphia Electric Co. 83/05/26 ALLAN, J. M. Region in Diffice of Director. ip 18878:057 24% Fiche 50-277, 83/05/26, 8304170278
- 8306200144 LER 83-013/03L-0 on B30503, fluctuating readings observed on indine monitor & downscale reading found on gas monitor. Caused by poor connections in drywall air sampling radiation detector circuitry due to exidation buildup on connectors. COONEY. M. J. Philadelphia Electric Co 83/06/01. ALLAN, J. M. Regios 1, Office of Director. 1p. 18903:246 24X Fiche: 50-277, 83/06/01. 8306200144.

V. Operator Examinations

8306140536 Extends invitation to attend 830627 meeting in King of Prussia, PA to discuss transfer of reactor operator licensing function from Bathesday MD to Region I ofc STAROSTECKI.R. Division of Project & Resident Programs 83/06/09. DALTROFF, B. L. Philadelphia Electric Co. 2pp. 18834; 336. 24% Fichs: 50-277, 83/06/09, 8306140536.

- DOCKET 50-278 PEACH BOTTOM ATOMIC POWER STATION, UNIT 3

 F Security, medical, emergency & fire protection plans
- 8304030096 Informs that NUREG-0737, Item 111 A 2 i, "Emergency Preparadness, Upgrade Emergency Plans to App E. 10CFR50." complete Item closed STOLI.J F Operating Reactors Branch 4 83/05/18 BAVER, E Q Philadelphia Electric Co 3pp 18733 E93 24X Fiche: 50-277, 83/05/18, 8304030096
- B306070223 Forwards IE Insp Repts 50-277/B3-09 & 50-278/B3-09 on B30402-0512 No noncompliance noted STARGSTECKI.R Division of Project & Resident Programs B3/05/24 DALTRUFF.B L Philadelphia Electric Co 2pp 18746 112 24x Fiche 50-277, B3/05/24, B304070223
- --8306070226 IE Insp Repts 50-277/83-09 & 50-278/83-09 on 830402-0512 No noncompliance noted Major areas inspected accessible portions of Pacilities, operational safety, radiation protection, physical security & control room activities IGUOH, A.R., TRIPP, L.E. Region 1, Office of Director 83/05/23 16pp 18746 114 24% Fichs 50-277,88/05/24,8306070223
- 830&060137 Forwards "Fire Protection Mod Progress Rept," per 830225
 Itr Request for exemptions re smoke detection & penetration
 seals & description of addl administrative controls dealing
 w/transient combustibles also enci
 BOYER, V S Philadelphia Electric Co 03/05/27 FISENHUT, D 0
 Division of Licensing Bpp 18732.057 24X Fiche 50-277,63/05/27,8306060157
- --8306060158 "Fire Protection Mod Progress Rept " W/four oversize drawings Aperture cards are available in PDR * Philadelphia Electric Co 83/05/27 9pp 18732 067 24X Fiche 50-277,83/05/27,8306060157
- 83061403B1 Releases public version of revised emergency plan implementing procedures FELTON.J H Division of Rules and Records 83/06/06 Document Management Branch ip 18853.216 24X Fiche 50-277,83/06/06,83061403B1.
- --8306140371 Forwards public version of revised emergency plan implementing procedures, including Procedures EP-201 retechnical support ctr activation, EP-205 re radiation protection team activation & EP-207C refirst aid DALTROFF, S. L. Philadelphia Electric Co 83/05/24 ALLAN, J M Region 1. Office of Director 2pp 18853 217 24X Fiche 50-277,83/06/06,83061403B1
- --8306i40398 Public version of revised emergency plan implementing procedures including Procedures EP-201 re tachnical support ctr activation.EP-205 re radiation protection team activation & EP-207C re first aid

 * Philadelphia Electric Co 83/04/25 148pp 18853 219 24X Fiche.50-277.83/06/06/8306i4038i
- 8306200159 Ack receipt of 830504 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-277/83-04 & 50-278/83-04 MARTIN.I T Division of Engineering & Technical Programs 83/06/14 DALTROFF.8 L. Philadelphia Electric Co. 2pp. 18902.357 24X Fichs 50-277, 83/06/14, 8306200159
- ~-8306200i65 Responds to NRC 830404 ltr re violations noted in IE Insp Repte 50-277/83-04 & 50-278/83-04. Corrective actions withheld (ref 106FR2, 790 & 73 21) DALTROFF, S. L. Philadelphia Electric Co 83/05/04 MARTIN, T T Division of Engineering & Technical Programs. ip 18902 359, 24X Fiche 50-277,83/06/14,8306200159
- P Operating license stage documents & correspondence
- 8306030110 Forwards safety evaluation re BWR Owners Group 801230 response to NUREG-0737. Item II K 3 45. "Depressurization M/Other Than Automatic Depressurization Sys " No mod to plant design or operation required.

 BTOLZ, J F Operating Reactors Branch 4. 83/05/18 BAUER, E G. Philadelphia Electric Co 2pp. 18733-297. 24X Fiche: 50-277, 83/05/18, 8306030110.
- 8305020350 Fowards missing Tech Spec Page 142e of Amend 92 to License DPR-56. Issued 830504. Amend changed Yech Specs to permit reactor operation w/Reload 5 core (Cycle 6). GEARS. Q. Operating Reactors Branch 4 83/05/19. BAUER. E Q. Philadelphia Electric Co. 2pp. 18716;346 24X Fiche: 50-278. 83/05/19. 8306020360.

- --8306020572 Page 1420 to Amend 92 to License DPR-56, issued 830504, changing Tech Specs to permit operation w/Reload 5 Core changing Tech Spess to permit operation w/Neload 5 Core (Cycle 6) * NRC - No Detailed Affiliation Given 83/05/19 ip 18716 348
 - 24X Fiche 50-278, 83/05/17, 8304020340
- 8304020325 Informs that lead responsibility transferred from Region 1 to NRR for review of pipe crack indications, evaluation of response to IE Bulletin 83-02 approval of Unit 3 restart & acceptability of continued operation of Unit 2 STOLZ, U F Operating Reactors Branch 4 B3/05/23 BAUER, E 0 Philadelphia Electric Co 2pp 18715 299 24X Fiche 50-277,03/05/23,8304020325
- 8306070363 Responds to B30202 request for add1 info re NUREQ-0737, Item II K 3 28. "Verify Qualification of Accumulators on Automatic Depressurization Sys Valves " H/one eversize drawing Aperture card is available in PDR DALTROFF. St. Philadelphia Electric Co B3/06/02 STOLZ, J F Operating Reactors Branch 4 lipp 18743 075 24X Fiche 50-277,83/06/02,8306070363
- --B30607038J Rev 5 to "Surveillance Test ST 7 9 2.Daily Check of Soismic Gas Hupply Bottle Pressures " * Philadelphia Electric Co B3/03/17 11pp 18743 125 24X Fiche 50-277, 83/06/02, 8306070363
- --8306070391 Rev O to "Surveillance Test ST 30 131,ABS Accumulator Check Valve & Sulenoid Valve LLRT " + Philadelphia Electric Co 61/10/14 11pp 18743 151 24X Fiche 50-277,83/06/02,8306070363
- --8306070395 Rev 3 to "Surveillence Test ST 13 28, ADS Relief Valve Solenoid Valve Functional " * Philadelphia Electric Co 83/03/17 5pp 18743 162 24X Fiche 50-277, 83/06/02, 8306070363
- --8306070398 Rev 1 to "Surveillance Test ST 2 & 3A. Calibr Check of PT-9202A & PR-9102A (Green Pen) " * Philadelphia Electric Co 83/03/11 16pp 18743 167 24X Fiche 80-277.63/06/02.8306070363
- --0306070403 Rev i to "Burveillance Tost.8T 2 & 230,Calibr Check of PT 91020 & PR 9102 (Green Pen) " * Philadelphia Electric Co 03/03/10 18pp 10743·183 24X Fiche 50-277.03/06/02,8306070363
- 8304070217 Forwards revised Tech Spec Pages 36 & 36a to limiting condition of operation to make 811223 application for amond to Tech Space re reactor protection sys consistent w/model Tech Spec.per NRC 830511 telcon request DALTROFF.8 L. Philadelphia Electric Co. 83/04/02 STOLZ, J F Operating Reactors Branch 4. 2pp. 18796 115 24X Fiche 50-277,83/06/02,8306070217
- --8306090226 Revised Tech Spec Pages 36 & 36a changing limiting condition of operation to be consistent w/model Tech Spec re reactor protection sys
 * Philadelphia Electric Co 83/06/02 2pp 18796.117 R4X
 Fiche. 50-277, 83/06/02.8306090219
- 8306170471 Forwards svaluation of BWR Owners Oroup generic response to NUREG-0737. Item II K 3 18 "Automic Depressurization Sys Logic Mods " Two of seven alternatives acceptable. One alternative should be chosen for facility mod.

 STOLZ, J F Operating Reactors Branch 4 83/06/03 BAUER, E © Philadelphia Electric Co 9pp 16094 038 24X
 Fiche 50-277, 83/06/03, 8306170471
- 8306240476 Informs of GE 830520 request for generic approval of Type 1 Mybrid 1 control rods during Refuel 5 Charges will not be attributed to util docket or util organization 8TOL2.J F Operating Reactors Branch 4 83/06/14 BAUER.E 0 Philadelphia Electric Co 2pp 18997 355 24X Fiche 50-278,83/06/14.8306240476
- 8304280138 Forwards "Control of Heavy Loads, Philadelphia Electric Co. Peach Bottom Atomic Power Station, Units 2 t 3." draft technical evaluation rept STOLZ, J F Operating Reactors Branch 4, 83/06/14, RAVER, E, 0 Philadelphia Electric Co. 2pp 19043 359 24X Fiche. 50-277, 83/06/14. 8306280138
- -8305050327 "Control of Heavy Loads, Peach Bottom Atomic Power Station, Units 2 & 3," draft technical evaluation rept. BUMBERGER, C.R. Franklin Institute/Franklin Research Center. NRC-03-81-130 TER-05506-379/200. B3/05/17 NRC No Detailed Affiliation Given 45pp. 19043 361. 24X Fiche 50-277,83/06/14, 8306280138

- 8306280196 Forwards revised safety evaluation re degraded grid voltage protection for Class IE power sys.based on review of util 820512.0722 & 1029 submittals & LLL technical evaluation rept Class IE adequately protected 8TOLZ.J F Operating Reactors Branch 4 83/06/14 BAUER.E 9 Philadelphia Electric Co 3pp 19046-072 24X Fiche 50-277.83/06/14.8306280156
- ~-8306280162 Revised safety evaluation re degraded grid voltage protection for Class IE sys Proposed electrical design mods acceptable 83/06/08 7pp
 - Office of Nuclear Reactor Regulation, Director 19046 075 24X Fiche 50-277.83/06/14.8306280156
- --8306280167 Supplementary safety evaluation re proposed testing frequency for degraded grid protection sys Request for 6-month test should be denied Testing should be performed
 - monthly * Office of Nuclear Reactor Regulation, Director 19046 079 24X Fiche 50-277,83/06/14.8306280156 83/06/14. 5pp
- --B304070100 Rev 1 to "Proposed Design Mods & Tech Spec Changes on Grid Voltage Degradation for Peach Bottom Atomic Power Station, Units 2 & 3" technical evaluation rept SELAN.J C Lawrence Livermore Laboratory FIN A-0250, UCID-19115 ROI B3/03/11. NRC No Detailed Affiliation Given 10pp 19046 084 24X Fiche 50-277,83/06/144.8306280156
- 8306270261 Forwards application for amend to Licenses DPR-44 & DPR-56 JUDA/URBOL FORWARDS APPLICATION FOR AMEND to Licenses DFR-44 & DF revising list of shock suppressors to reflect mode made since last amend to 810324 application BRADLEY, E J Philadelphia Electric Co 83/06/22, DENTON, H. R. Dffice of Nuclear Reactor Regulation, Director, 1p 18990 181 Ficha 50-277,83/06/22,8306270261
- --8306270264 Application for amend to Licenses DPR-44 & DPR-96, revising list of shock suppressors to reflect mode made since last amend to 810324 application 8AUER, E 0. BRADLEY, E J. Philadelphia Electric Co. 83/06/5pp 18970 182 24X Fiche 50-277, 83/06/22,8306270261
- --8306270268 Proposed Tech Spec Table 3, 11 D i revising list of shock suppressors to reflect mods made since last amend to 910324 application ** Philadelphia Electric Co 83/06/22 3pp 18990 197, 24X Fiche 50-277.83/06/22
- O Inspection reports: IE Bulletins & correspondence
- 8306220181 Discusses IE insps on 811013-820915 & forwards notice of violation & proposed imposition of civil penalty HAYNES.R C Region 1. Office of Director 83/03/29 BOYER, V Philadelphia Electric Co Opp 18977 318, 24% Fiche 50-277,83/03/29,8306220181
- --8306220191 Notice of violation & proposed imposition of civil penalty in amount of \$140.000 Noncompliance noted improper valve lineups, inadequate valve lineup verifications, improper use of test procedures & inadequate monitoring of parameters HAYNES, R C Region i. Office of Director 83/03/29 Bpp 18977-324 24x Fiche 50-277,83/03/29,8306220181
- 8306030291 Fowards IE Enforcement Conference Repts 30-277/83-13 & 50-278/83-13 on 830506 No noncompliance noted.
 STARCHTECKI, R. Division of Project & Resident Programs 83/05/20 DALTROFF, B L. Philadelphia Electric Co. 2pp. 16708 336 24X Fichs 50-277,83/05/20,8306030291
- --8306030312 IE Enforcement Conference Repts 50-277/83-13 & 50-278/83-13 on 830506 No noncompliance noted Major topics discussed: violations of procedural controls & Tech Spec requirements. BLOUGH, A R, WILLIAMS, J H, MCCABE, E C. Region 1, Office of Director 83/05/13 4pp. 18708;337. 24% Fiche 50-277,83/05/20,8306030291
- 8304020325 Informs that lead responsibility transferred from Region I to NRR for review of pipe crack indications, evaluation of response to IE Bujletin 83-02. approval of Unit 3 restart & acceptability of continued operation of Unit 2. BTOLZ.J F Operating Reactors Branch 4 83/05/23, BAUER.E 0. Philadelphia Electric Co. 2pp 18715-299, 24X Fiche 50-277,83/05/23,8306020325
- 8304040142 Forwards IE Insp Repts 50-277/83-12 & 50-278/83-12 on 830418-22 & notice of violation HARTIN.T T Division of Engineering & Technical Programs. 83/05/23 DALTROFF, BL Philadelphia Electric Co 29p. 18719-197. 24X Fichs. 50-277, 83/05/23, 8304040142.
- --8306060166 Notice of violation from insp on 830418-22,
 * Region 1, Office of Director 83/05/23, ip 18719, 199 24X
 Fiche, 80-277, 83/05/23, 8306060162

- --8306060170 IE Imap Repts 50-277/63-12 & 50-278/83-12 on 830418-22
 Noncompliance noted failure to follow jumper log procedures
 & GA plan
 RICHARDS B. ANDERSON, C. Region 1. Office of Director 83/05/16
 - RICHARDS, 8 . ANDERSON, C Region 1, Office of Director 83/05/16 5pp. 18719 200 24% Fiche 50-277, 83/05/23, 8306060162
- 8304070223 Forwards IE Insp Repts 50-277/83-09 & 50-278/83-09 on B30402-0512 No noncompliance noted BTAROSTECKIR. Division of Project & Resident Programs. B3/05/24 DALTROFF,S.L. Philadelphia Electric Co 2pp 18746.112 24X Fiche: 50-277,83/05/24,8306070223
- --8306070226 IE Insp Repts 50-277/83-09 & 50-278/83-09 on 830402-0512 No noncompliance nated Major areas inspected accessible portions of facilities operational safety radiation protection, physical security & control room activities BLOUGH, A R , WILLIAMS, J H , MCBREARTY, R A Region 1, Office of Director 83/05/23 16pp 18746 114 24X Fiche 50-277,83/05/24,8306070223
- 830511045B IE Info Notice B3-32, "Ruptured Am-241 Sources Contained in Well Logging Device" Svc list encl TAYLOR, J M Division of Bafeguards & Inspection Programs (Post B30103) B3/05/26. Consolidated Edison Co of New York, Inc 125pp 18831-043 24X Fiche 50-000,83/05/24,8305110458.
- 8305110460 IE Info Notice 83-34, "Event Notification Info Worksheet"
 Byc list encl
 JORDAN, E.L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/05/26. Consolidated Edison Co. of New
 York, Inc. 115pp. 18732,085 24X Fiche 50-000,83/05/26,8308110460
- 8305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods Withdrawn at BWRs " Svc list encl. JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/05/31 Consolidated Edison Co. of New York, Inc. 116pp 18732,208 24X Fiche 50-000,83/05/31,8305110461
- 8306160054 Notification of 830616 significant licenses meeting in Delta:PA to discuss BALP TRIFF.L.E Region 1. Office of Director 83/06/02. DIRCKS, W. J. Office of the Executive Director for Operations STELLD.V Regional Operations & Generic Requirements DEVOUNG.R C Director's Office. Office of Inspection and Enforcement 1p. 18872 327 24% Fiche. 50-277,83/06/02.8306160054
- 8308200125 Forwards IE Insp Repts 50-277/83-11 & 50-278/83-11 on 830819-22.No noncompliance noted MARTIN, T. T. Division of Engineering & Technical Programs B3/06/06 DALTROFF, 8 L. Philadelphia Electric Co. 2pp. 18903 291 24X Fichs 50-277, 83/06/06.8308200125
- --8306200130 IE Insp Repts 50-277/83-11 & 50-278/83-11 on 830419-22 No noncompliance noted Major areas Inspected, inservice testing of pumps & valves, local leak rate testing, integrated leak rate testing & facility tours.
 PULLANI, B V , BETTERHAUSENL Region 1, Office of Director 83/06/01. 10pp 18903.293. 24X Fichs 50-277,83/06/06,8304200125
- 8305110464 IE Info Notice 83-36, "Impact of Security Practices on Bafe Operations." Svc list encl.
 JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/09. Consolidated Edison Co. of New York, Inc. 119pp. 18830 280. 24X Fiche: 50-000,83/06/09,8305110464
- 8306140258 Act receipt of 830526 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-277/83-07 & 50-279/83-07 MARTIN, T. T. Division of Engineering & Technical Programs B3/06/09, DALTROFF, B. L. Philadelphia Electric Co. ip. 18833-027 24X Fiche, 50-277, 83/06/09, 8306140258,
- --8306140262 Responds to NRC 830429 ltr re violetions noted in IE Insp Repts 50-277/83-07 & 50-278/83-07, Corrective action, radiation area lamediately reposted & health physicist assigned to anotior reactor bldg. OALLAGHER, J.W. Philadelphia Electric Co. 83/05/26, MARTIN, T.T. Division of Engineering & Technical Programs. 2pp. 18833 028, 24X Fiche: 50-277, 83/06/09, 8306140258
- B3061604B3 Ack receipt of B30517 ltr informing NRC of steps taken to correct violations noted in IE Imap Repts 50-277/82-10, 50-276/82-10, 50-277/82-14 & 80-276/82-14 STAROSTECKI.R. Division of Engineering & Technical Programs B3/06/10. DALTROFF.S.L. Philadelphia Electric Co ip 18864:124 24X Fiche:50-277,83/06/10.8306160483.

- --8306160486 Responds to NRC 830418 ltr re violations noted in IF Insp Repts 50-277/82-10,50-278/82-10,50-277/82-14 & 50-278/82-14 Corrective actions personnel reinstructed re procedural controls governing operation DALTROFF,8 L Philadelphia Electric Co 83/05/17 STAROSTECKI,R Division of Project & Resident Programs 3pp 18864 125 24X Fiche 50-277,83/06/10,8306160483
- 8306280235 Responds to IE Bulletin B3-03, "Check Valve Failures in Raw Mater Cooling Sys of Diesel Generators " Two check valves identified which could fail & possibly prevent coolant from reaching diesel generators GALLAGHER, J W Philadelphie Electric Co. 83/06/10 ALLAN, J M Region 1, Office of Director 8pp 19015 030 24X Fiche 50-277, 83/06/10, 8306280235
- 8305110470 IE Info Notice 83-38, "Defective Heat Sink Adhesive & Seismicelly Induced Chatter in Relays Within Printed Circuit Cards "Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co of New York, Inc 118pp 18920 225 24X Fiche 50-000,83/06/13.8305110470
- 8304070010 IE Info Notice 83-37, "Transformer Failure Resulting From Degraded Internal Connection Cables " Svc list enc]
 JURDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co. of New York, Inc. 243pp 18721 001 24X Fiche 50-000.83/06/13.8306090010
- 8306200159 Ack receipt of 830504 ltr informing NRC of steps token to correct violations noted in 1E Inap Repts 50-277/83-04 & 50-278/83-04 MARTIN.T T Division of Engineering & Technical Programs B3/06/14 DALTROFF.9 L Philadelphia Electric Co 2pp 18902 357 24% Fiche, 50-277, 83/06/14, 8306200159
- --B306200165 Responds to NRC 830404 ltr re violations nated in IE Insp Repts 50-277/83-04 & 50-278/83-04 Corrective actions withheld (ref JOCFR2 790 & 79 21) DALTROFF, S L Philadolphia Electric Co 83/05/04 MARTIN.T T Division of Englineering & Technical Programs ip 18702 359 24X Fiche: 50-277,83/06/14.8306200159
- 8305110475 lE Info Notice 83-40. "Need to Environmentally Qualify
 Epoxy Grouts & Sealers " Svc list encl
 JORDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/06/22 Consolidated Edison Co of New
 York, Inc 115pp. 19021 179 24X Fiche 50-000,83/06/22,8305110475
- 8305110477 IE Info Notice B3-41, "Actuation of Fire Suppression Sys-Causing Inoperability of Bafety-Related Equipment " Svc list enc! JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/22 Consolidated Edison Co. of New York, Inc. 120pp 18997 007 24X Fiche 50-000.83/06/22,8305110477
- 8305it0479 IE Info Notice 83-42, "Reactor Mode Switch Molfunctions" Syc list encl JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/06/23 Consolidated Edison Co. of New York, Inc. 116pp 18976 242 24X Fiche 50-000.83/06/23.8305110479
- 8305110483 IE Info Natice 83-43, "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Fost 830103) 03/06/24 Consolidated Edison Co of New York, Inc 116pp 19046 297 24% Fiche 50-000,83/06/24,8305110483
- R Periodic operating reports & related correspondence
- 8306170163 Rev 1 to "Peach Bottom Atomic Power Station Units 2 & 3 Semiannual Effluent Release Rept 14, Jul-Der 1982 " W/830606 1tr FLEISCHMANN, R. ALDEN, W. M. Philadelphia Electric Co. 82/12/31 ALLAN, J. W. Region 1, Office of Director 11pp 18878 332 24X Fiche 50-277,82/12/31.8306170163
- 8306160379 Monthly operating repts for Apr 1983 W/830512 ltr ALDEN,W M : COUNEM J Philadelphia Electric Go B3/05/09 10p 18860:092 24X Fichs 50-277.83/05/09,8306160379
- 8306210076 Monthly operating repts for May 1983 W/830615 ltr ALDEM, W M. COONEY, M J Philadelphia Electric Co 83/06/10 Director's Office, Office of Inspection and Enforcement iPpp 18913 350 24% Fichs 50-277.83/06/10.8306210076

- S Reportable occurrences. LERs & related correspondence
- B306010438 Forwards LER 83-012/-017-0 Detailed event analysis encl CODNEY, M J Philadelphia Electric Co 83/05/09 ALLAN, J M Regio 1. Office of Director 3pp 18679 316 24% Fiche 50-278,83/05/09,
- --8304010445 LER 83-012/01T-0 on 830425, during refueling outage, while JUDOLOGYS CLER BS-012-011-00 on B30425, outing refueling disage, while performing NDE, intergranular stress corrosion cracking indications found in heat affected ione of 12 welds Caused by stress corrosion Weld insp increased COONEY.M J Philadelphia Electric Co 83/05/09 Region 1. Office of Director 1p 18679 315 24X Fiche 50-278,83/05/09,8304010438

/ Operator Examinations

- #306140536 Extends invitation to attend #30627 meeting in King of Prussia.PA to discuss transfer of reactor operator licensing function from Bethesda.MB to Region I ofc STAROBTECKI.R Division of Project & Resident Programs #83/06/09 DALTROFF.B L Philadelphia Electric Co 2pp 18834 336 24X Fichs 50-277.83/06/09.8306140536
- MCKET 50-280 SURRY POWER STATION, UNIT 1
 - Security, medical, emergency & fire protection plans
- 306140621 Forwards IE Insp Repts 50-280/82-31 & 50-281/82-31 on 821604-31 Enforcement action addressed in JP O'Reilly 830324 ltr
- 830324 1tr DANCE.H C Division of Project & Resident Programs 83/03/25 STEMART.W L Virginia Electric & Power Co 2pp 18043 009 24X Fiche.50-200.83/03/25.8306140621
- -8306140627 IE Insp Repts 50-280/82-31 & 50-281/82-31 on B21004-31 Inoperable containment spray chemical addition tunk identified following Unit 1 startup BURKE, D. J. DAVIS: M. J. Region 2. Office of Director, JULIAN, C Division of Project & Resident Programs 83/03/24 8pp 18843:011 24X Fiche 50-280, 83/03/25, 8306140621
- 306140550 Confirms IE enforcement conforence on 830405 at Region II ofc to discuss mgt of health physics operations Proposed
- ore to discuss myt or health physics operations (Proposed agends ent)
 O'RETLLY,J P Region 2, Office of Director 83/04/01, STEWART,W L
 Virginis Electric & Power Co 2pp 18834 204 24X
 Fiche 50~280.83/04/01,8306140050
- 306170327 Application supplementing 810921 & 820415 proposed changes
- to Tech Specs re fire protection sys, by deleting reporting requirements from Spec 3 21 STEWARTH L. Virginia Electric & Power Co 83/06/14 DE STEWARTH L. Virginia Electric & Power Co 83/06/14 DE Gffice of Nuclear Reactor Regulation, Director, VARGA: 8 A Operating Reactors Brench 1 Spp 18877 001 24X Fiche 80-280,83/06/14.8306170327 VARGA, 8 A.
- -8306170331 Suppl to proposed Tech Specs rs firs protection Mys. * Virginia Electric & Power Co 83/06/14 10pp. 19877.004 24X Fiche, 50-280, 83/06/14, 83061/0327

Insurance & indemnity information

- 106300113 Endorsement 44 to NELIA Policy NF-240 * Nuclear Energy Liability Insurance Association 19121 069 24X Fiche: 50-280, 83/06/01, 8306300113 83/06/01 Ip.
- Utility Final Safety Analysis Report (FBAR) & amends
- 06300149 Forwards Rev i to updated FBAR Rev current as of 830101. STEWART.W L. Vinginia Electric & Power Co 83/06/22 DENTON.H R Office of Nuclear Reactor Regulation, Director 1p. 19115.135. Fiche 80-280.83/06/28.8306300149
- 8306300151 Rev 1 to updated FBAR * Virginia Electric & Power Co 83 24X Fiche 50-280, 83/06/22, 8306300149 83/06/22 646pp. 19115.136
- Operating license stage documents & correspondence
- D4040051 Add1 response to FDIA request for three categories of documents re PRA of reactor safety study methodology application program repts & interim reliability evaluation program repts Forwards App A documents Search continuing. FELTON, J M Division of Rules and Records, 83/04/07 SHOLLY, 9 C, Jnion of Concerned Scientists 3pp 18752 001, 24X Fiche: 50-000,83/04/07.8306060051

- --8306050085 Provides info on boron precipitation clogging HPI lines & Solves Provises into an aoron precipitation cloging HPI failure of aperator to switch to hat leg injection in order to flush out boron residue from core during recirculation. Indo obtained from PRAD DAVIS. S. NRC - No Detailed Affiliation Given 83/02/24 THADANIA NRC - No Detailed Affiliation Given App 187 24X Fiche 50-000, 83/04/07, 8304060051
- 8306030441 Forwards "Control of Heavy Loads (C-10), Surry Power Station Units 1 & 2," draft technical evaluation rept & summary of add1 info required to complete review Response requested within 60 days VARGA.S A Deprating Reactors Branch 1 83/05/14. STEWART.W L Virginia Electric & Power Co 2pp 18735 287 24x Fiche 50-280.83/05/16.8306030441.
- ---B306030444 "Control of Heavy Loads (C-10), Surry Power Station Units 1 & 2," draft technical evaluation rept
 VOSBURY, F W , BARGENT, I. H Franklin Institute/Franklin Research
 Center NRC-03-B1-130 YER-C5506-395/396 DR, B3/01/14 NRC -No Datailed Affiliation Given. 40pp 18735 289, 24X
 Fiche 50-280, B3/05/14, 8306030441
- 8304150064 COPPER IN THE INTAKE AND DISCHARGE ZONES OF THE SURRY AND SALEM NUCLEAR POWER STATIONS
 HARRISON,F L , BISHOP,D J., RICE,D.W Lawrence Livermore Laboratory.
 FIN A-0119 NUREC/CR-2955 B3/05/31 Division of Health. Biting & Waste Management Sipp Available at NRC \$4 00 18847,221
 24% Fiche,50-000,63/05/31,8306150064
- 8306100170 Updates 821112 ltr providing info on schedule for submitting results of motor-operated valve studies & replacement of valves w/unsatisfactory starting capabilities Permanent schedule will be provided by 831215.

 STEMART, W. L. Virginia Electric & Power Cn 83/06/03 DENTON, H R Office of Nuclear Reactor Regulation. Director VARGA. S. A Operating Reactors Oranch 1 2pp 18805 263 24X Fiche 50~280,83/06/03,8306100170
- 8306170281 Advises that 821227 commitment to complete installation & testing of post-accident sampling sys per NUREO-0737. Item
 II 8 3 by 83060; has been met Final procedures for sys will be complete by 830701
 BTEMART.W L. Virginia Electric & Power Co 83/06/14 DENTON, H R, Office of Nuclear Reactor Regulation, Director EISENHUT, D 9, Division of Licensing 2pp 18877-025 24X Fiche, 50-280, 83/06/14, 8306170281
- 8306170327 Application supplementing 810521 & 820415 proposed changes to Tech Space re fire protection system deleting reporting requirements from Space 3 21 STEMART.W L. Virginia Electric & Power Co. 83/06/14 DENTON.H.R Office of Nuclear Reactor Regulation, Director VAROA, B A. Operating Reactors Branch i 3pp. 18877 001. 24X Fiche 50-280,83/06/14,8306170327
- --8306170331 Suppl to proposed Tech Specs re fire protection sys. * Virginia Electric & Power Go 83/06/14. 10pp 18877 004. 24X Fiche 50-280.83/06/14.8206170327
- 8306220033 Application to amend Licenses DPR-32 & DPR-37, changing Tech Specs by adding addl accident monitoring instrumentation & reactor vessel head vents per NUREG-0737, Items II F J & reactor vessel head vents per NUREG-0/37. Items II F | & II B | respectively
 BTEWART.W L. Virginia Electric & Power Co | 83/06/16 | DEN
 Office of Nuclear Reactor Regulation, Director | VAROA.8 A.
 Operating Reactors Branch | 3pp. 18927:233 | 24X
 Fiche 50-280.83/06/16.8306220033.
- --8306220047 Proposed Tech Specs adding addl accident monitoring instrumentation & reactor vessel hand vents, per MUREG-0737, Items II F. i & II B linespectively,
 * Virginia Electric & Power Co 83/06/16, 83pp. 18927, 237, 24X Ficher 50-280, 83/06/16, 8306280033
- Q Inspection reports: IE Bulletins & correspondence
- 8306140556 Confirms mgt meeting on 830217 in Richmond, VA to review results of first phase of annual appraisal of regulatory performance. Proposed meeting agenda encl. LEWIS.R.C. Division of Project & Resident Programs. 83/02/08. STEWART.W L. Virginia Electric & Power Co. 3pp. 19834 217 2/Fiche. 50-000, 83/02/08. 8306140556.
- 8306140328 Confirms 830309 enforcement conference w/util to discuss JUDI 40328 Confirms 83339 enforcement conference w/btil to d. Unit I 821016 incident re containment apray sys chemical addition tank being valved out when required to be operable by Tech Specs Proposed meeting agenda encl O'REILLY, J P Region 2, Office of Director 83/03/04 BTI Virginia Electric & Power Co 2pp 18832 215. 24X Ficher 50-280,83/03/04,8306140328 63/03/04 STEWART, J. L.

- 8306i40621 Forwards IE Insp Repts 50-280/82-31 & 50-281/82-31 on 821004-31 Enforcement action addressed in JP O'Reilly 830224 ltr
 DANCE, H C. Division of Project & Resident Programs 83/03/25 STEMART, M L Virginia Electric & Power Co. 2pp. 18843 009 24X Fiche 50-280,83/03/25,8306140621
- --8306140627 IE Insp Repts 50-280/82-31 & 50-281/82-31 on 821004-31 Insperable containment spray chemical addition tank identified following Unit 1 startup BURKE, D J . DAVIS.M J. Region 2. Office of Director JULIAN.C Division of Project & Resident Programs 83/03/24 8pp. 18843-011. 24X Fiche.50-280.83/03/25.8206140621.
- 830.6140710 Submits confirmation of action ltr re B30408 & 11 telcons & B30405 enforcement meeting in Atlanta. GA re util failure to perform adequate radiological air sampling & to monitor personnel radiation exposure O'REILLY, J.P. Region 2. Office of Director. B3/04/II STEMART, W L Virginia Eisechric & Power Co. 2pp 18841:290 24X Fiche: 50-280, B3/04/II, B306140710
- 8306140397 Forwards IE Insp Repts 50-280/03-12 & 50-281/83-12 on B30415-21. No noncompliants noted DANCE, H. C. Region 2. Office of Director B3/05/17 STEWARY, W L Virginia Electric & Power Co 2pp 18832 084 24X Fiche: 50-280, 83/05/17, 8306140397.
- --8306440400 IE Insp Repts 50-280/83-12 & 50-281/83-12 on B30415-21 No moncompliance noted Major areas inspected containment integrated leakage rate testing & pipe supports & restraints BROOKS,E H., JAPE.F. Region 2, Office of Director. B3/05/12 3pp 18832:086. 24X Fiche 50-280.83/05/17.8306140397
- 8305110458 IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in Well Logging Device" Svc list encl
 TAYLOR, J M Division of Safeguerds & Inspection Programs (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc.
 125pp 18831-043 24X Fiche, 50-000, 83/05/26, 8305110458
- 8305;10460 IE Info Notice 83-34, "Event Notification Info Worksheet" Svc list end:
 JURABAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103), 83/05/26 Consolidated Edison Co. of New York, Inc. 115pp. 18732-085, 24X Fiche 50-000,83/05/26,8305110460.
- 8305110461 IE Info Notice 83-35, "Fuel Hovement W/Control Rods Hithdrawn at BWRs " Svc list encl. JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Poet 830103), 83/05/31 Consolidated Edison Co. of New York, Inc. 116pp 18732 208 24X Fishe 50-000,83/05/31,8305110461
- 8306290331 Forwards response to IE Bulletin B3-08, "Check Valve Failures in Raw Water Cooling Bys of Diesel Generators "Burry has no valves in emergency diesel generator cooling sys. Raw cooling water sys not used at North Anna. BIEWART.W L. Virginia Electric & Power Co. B3/06/08 U'REILLY, J. P. Region 2. Office of Director Spp. 17055 303 24X Fiche. 50-000, 63/06/08, 6306290331.
- 8305110464 IE Info Notice 83-36. "Impact of Security Practices on Safe Operations." Syc list encl JORDAN.E.L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/09 Comsolidated Edison Co of New York, Inc. 117pp 18830:280, 24X Fiche 50-000,83/06/09,8305110464
- 8305110470 IE Info Notice 83-38, "Defective Heat Sink Adhesive & Seismically Induced Chatter in Releys Within Printed Circuit Cards." Syc list encl.
 JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/06/13 Consolidated Edison Co. of New York, Inc. 118pp 18920.225, 24X Ficher 50-000, 83/06/13, 8305110470.
- 8304200219 Revises 830403 response to Enforcement Action 83-34 contained in IE imap rept re whole body counts & other outage-related requirements Corrected Page 3 and 1.

 STEWART.W.L. Virginia Electric & Power Co. 83/04/15 DEYGUNG.R.C. Director's Office, Office of Inspection and Enforcement 2pp 18902, 284. 24% Fiche: 50-280, 83/04/15, 8306200219.
- 8305110475 IE Info Notice B3-40, "Need to Environmentally Qualify Epoxy Grouts & Sealers," Svc list encl JORDAN E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83706/22. Compolidated Edison Co of New York: Inc. 115pp. 19021.179. 24X Fiche.50-000.83/05/22.8305110475.
- 8305110477 IE Info Natice 83-41, "Actuation of Fire Suppression Sys Causing Inoperability of Bafety-Related Equipment," Syc list encl JORDAN, E. L. Division of Emergency Preparadness & Engineering Response (Post 830103) 83/06/22 Consolidated Edison Co. of New York: Inc. 120pp 18997:007 24X Fiche: 50-000,83/06/22,8305110477

- B305110479 IE Info Notice 83-42, "Reactor Mode Switch Malfunctions "
 Syc list encl
 JORDAN E L Division of Emergency Preparedness & Engineering
 Response (Post B30103) B3/06/23 Consolidated Edison Co of New
 York, Inc 116pp 18996 242 24X Fiche 50-000,83/06/23,8305110479
- 8305110483 IE Info Notice 83-43, "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints " Svc list encl JURDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/24 Consolidated Edison Co of New York, Inc 114pp 17044 297 24X Fiche 50-000.83/06/24.8305110483
- R Periodic operating reports & related correspondence
- 8306020159 Forwards monthly operating repts for Mar 1983 & corrected pages to health physics rept for monthly operating repts for Jan & Feb 1983
 STEWART.W L Virginia Electric & Power Co 83/04/14 HALLER,N N Office of Resource Management. Director 1p 18691 006 24X
 Fiche 50-280,83/04/14,8306020159
- --8306020162 Monthly operating repts for Mar 1983 JONES.V Virginia Electric & Power Co 83/04/19 47pp 18691 007 24% Fichs 50-280,83/04/14.8306020159
- --8306020168 Correct page to health physics rept for monthly operating rept for Jan 1983 a Virginia Electric & Power Co 83/04/14 1p 18691 054 24x Fiche 50-280, 83/04/14, 8306020159
- --8306020173 Corrected page to health physics rept for monthly operating rept for Feb 1983 * Virginia Electric & Power Co 83/04/14 1p 18691 085 24% Fiche 50-280,83/04/14,8306020159
- B Reportable occurrences, LERs & related correspondence
- 8306070220 LER 83-021/03L-0 on 830427.Periodic Tests 18 15 & 18 l6 rr degraded protection function H train & J train, revealed emergency bus separation & diesel start time delay setpoint tolerance exceeded Delays reset W/830519 ltr WILSON, J L Virginia Electric & Power Co 83/05/19 C 'AE\$LLY.JP Region 2, Office of Director 4pp 18746 144 P4X Fiche 50-280,83/05/19,8306070220
- 8306210285 LER 83-023/03L-0 on 830513, steam generator bloudown released to discharge canal w/o monitor Caused by procedures not requiring flow verification in radiation monitor Blowdown checklist will be modified W/830610 ltr WILSON, J L , WILSON, J L , Virginia Electric & Power Co 83/06/10 D'AEILLY, J P Region 2. Office of Director 3pp 18715 017 241 Fiche 50-280,83/06/10.8306210285.
- 8306270005 LER 83-024/03L-0 on 830517.RHR pump B removed from sycinardering RHR loops inoperable Caused by pump cavitation dure to inaccurate standpipe level indication RCS level increased RHR pump vented & returned to syc W/B30616 ltr WILBON.J L Virginia Electric & Power Co B3/06/16 O'RCHLY.JP Region 2. Office of Director 3pp 18788 154 24X Fiche 50-280.83/06/16.8306270005.
- DOCKET 50-281 SURRY POWER STATION, UNIT 2
- F. Security, medical, emergency & fire protection plans
- 8306140621 Forwards IE Insp Repts 50-280/82-31 & 50-281/82-31 on 821004-31 Enforcement action addressed in JP O'Reilly 830324 ltr
 DANCE H C Division of Project & Resident Programs 83/03/25 STEMART, W L Virginia Electric & Power Co 2pp 18843:009 24X Fichs 50-280, 83/03/25, 8306140621
- --8306140627 IE Insp Repts 50-280/82-31 & 50-281/82-31 on 921004-31 Insperable containment spray chemical addition tank identified following Unit I startup BURKE, D J Region 2, Office of Director B3/03/24 Opp 18843:011 24X Fichs 50-280,83/03/25,8306140621
- 8306140550 Confirms IE enforcement conference on 830405 at Region [1] ofc to discuss mgt of health physics operations Proposed agenda encl.

 U'REILLY, J P Region 2, Office of Director. 83/04/01 STEWART, N L Virginia Electric & Power Co 2pp 18834:204 P4X

 Fichs. 50-280, 83/04/01, 8306140550

- 8306170327 Application supplementing 810921 & 820415 proposed changes to Tech Spacs to fire protection sys, by deleting reporting requirements from Spac 3 21 STEWART.W L. Virginia Election & Power Co. 83/06/14 DENION, H.R. Office of Nuclear Reactor Regulation. Director 3pp 18877 001 24X Fiche 50-280, 83/06/14, 8306170327
- J Insurance & indemnity information
- 8306300113 Endorsement 44 to NELIA Policy NF-240

 * Nuclear Energy Liability Insurance Association 83/06/01 ip 19121 049 24% Fiche 50-280.83/06/01.8306300113
- K Utility Final Bafety Analysis Report (FBAR) & amends
- 8306300149 Forwards Rev 1 to updated F9AR Rev current as of 830101 STEWART.W.L. Virginia Electric & Power Co. 83/06/22 DENTON.H R Office of Nuclear Reactor Regulation. Director 1p. 19115-135 24X Fithe 50-280,83/06/22,8306300149
- --8306300151 Rev 1 to updated FSAR * Virginia Electric & Power Co 83/06/22 646pp 19115 136 24X Fiche 50-200,83/06/22,0306300149
- P Operating licenso stage documents & correspondence
- 8306060051 Add1 response to FUIA request for three categories of documents re FRA of reactor safety study methodology application program repts & interim reliability evaluation program repts Forwards App A documents Search continuing FELTON, J M Division of Rules and Records 83/04/07 SHOLLY,8 C Union of Concerned Scientists 3pp 18752 001 24X Fiche 50-000,83/04/07,8306060051
- --8306060085 Provides info on boron precipitation clagging HPl lines & failure of operator to switch to hot leg injection in order to flush out boron residue from core during recirculation Info obtained from PRAS

 DAVIS, S. NRC. No Detailed Affiliation Given 83/02/24

 THADANI, A. NRC. No Detailed Affiliation Given App. 18752 206

 24X Fiche 50-000,83/04/07,8306060051
- 8306030441 Forwards "Control of Heavy Loads (C-10), Surry Power Station Units 1 & 2," draft technical evaluation rept & summary of addl info required to complete review Response requested within 60 days
 VARGA: 8 A Operating Reactors Branch 1 83/05/16 STEWARF, W L.
 Virginia Electric & Power Co 2pp 18/35 287 24X
 Fiche 50-280,83/05/16,8306030441
- --8306030444 "Contiol of Heavy Loads (C-10). Surry Power Station Units 1 & 2," draft technical evaluation rept VOBBURY, F W . SARGENT. I H Franklin Institute/Franklin Research Center NRC-03-Bi-130 TER-C5506-395/396 DR 83/01/14 NRC -- No Detailed Affiliation Given 40pp 18735 289 24% Fiche 50-280.83/05/16.8306030441
- 8306150064 COPPER IN THE INTAKE AND DISCHARGE ZONED OF THE SURRY AND SALEM NUCLEAR POWER STATIONS
 HARRISON, F. L. KNRZOVICH, J. P. Lawrence Livermore Laboratory FIN A-0117. NUREG/CR-2965 83/05/31 Division of Health, Siting & Waste Management 51pp Available at NRC \$4 00 18869 221 24X Fiche 50-000,83/05/31,8306150064
- 8306100170 Updatos 821112 ltr providing info on achedule for submitting results of motor-operated valve studies & replacement of valves w/unsatisfactory starting capabilities fermanent schedule will be provided by 831215

 STEWART.W L. Virginia Electric & Power Co. 83/06/03 DENTON, H. R. Office of Nuclear Reactor Regulation, Director. VARGA, B. A. Operating Reactors Branch i 2pp 18805 263 24% Fiche: 50-280, 83/06/03, 8306100170
- 8306170281 Advises that 821227 commitment to complete installation & testing of post-accident sampling sys per NUREQ-0737. Item II 8 3 by 830601 has been met Final procedures for sys will be complete by 830701 STEWART.W L Virginia Electric & Power Co. 83/06/14. DENTON.H R. Office of Nuclear Reactor Regulation, Director EISENHUT.D.Q. Division of Licensing 2pp 18877 025 24% Fiche: 50-280,83/06/14.83061/0281

- 8306170327 Application supplementing 810921 & 820415 proposed changes to Tech Specs re fire protection system deleting reporting requirements from Spec 3 21 STEMART. H. L. Virginia Electric & Power Co. B3/06/14 DENTON, H.R. Office of Nuclear Reactor Regulation. Director VARGA, 8 A Operating Reactors Branch 1 Spp. 18977-001 24X Fiche 50-280,83/06/14,8306170327
- --8306170331 Suppl to proposed Tech Specs re fire protection sys * Virginia Electric & Power Co = 83/06/14 10pp, 18877 004 24 Fiche 50-280.83/06/14, 8306170327
- 8306220033 Application to amend Licenses DPR-32 & DPR-37, changing Tech Specs by adding addl accident monitoring instrumentation & reactor vessel head vents per NUREG-0737. Items II F 1 & II B 1 respectively STEWART, W L Virginia Electric & Power Co 83/06/16 DENTON, H R. Office of Nuclear Reactor Regulation, Director VARGA, 8 A Operating Reactors Branch 1 3pp 18927 233 24X Fiche 50-280,83/06/16,8306220033
- --8306220047 Proposed Tech Specs adding addl accident monitoring instrumentation & reactor vessel head vents.per NUREQ-0737. Items II F i & II 8 1.respectively * Virginia Electric & Power Co 83/06/14 23pp 18927 237 24) Fichs 50-280.83/06/16.8306220033
- G Inspection reports, IE Bulletins & correspondence
- 8306140556 Confirms mgt meeting on 830217 in Richmond, VA to review results of first phase of annual appraisal of regulatory performance Proposed meeting agenda encl LEMIS.R C Division of Project & Resident Programs 83/02/08. STEMARTH L Varginia Electric & Power Co 3pp 18834 217 24) Fiche 50-000.83/02/08.8306140556
- B306140328 Confirms B30309 enforcement conference w/util to discuss Unit I 821016 incident re containment spray sys chemical addition tank being valved out when required to be operable by Tech Specs Proposed meeting agenda encl O'REILLY, J P Region 2, Office of Director B3/03/04 BYEWART, J L Virginia Electric & Power Co 2pp 18932 215 24X Fiche 50-280,83/03/04,8306140328
- 9306140621 Forwards IE Insp Repts 50-280/82-31 & 50-281/82-31 on 821004-31 Enforcement action addressed in JP D'Reilly 830324 ltr
 DANCE.H C Division of Project & Resident Programs 83/03/25, STEMART.M L, Virginia Electric & Power Co Rpp 18843 009 24X Fiche.50-280,83/03/25,8306140621
- --B306140627 IE Insp Repts 50-280/82-31 & 50-281/82-31 on 821004-31 Inoperable containment spray chemical addition tank identified following unit 1 startup BURKE,D J, DAVIB.M J Region 2. Defice of Director JULIAN,C Division of Project & Resident Programs 83/03/24, Bpp. 18843 011 24X Fiche 90-280.83/03/25, 8306140621.
- 8304140710 Submits confirmation of action ltr re 830408 & 11 telcons & 830405 enforcement meeting in Atlanta. GA re util failure to perform adequate radiological air sampling & to monitor personnel radiation exposure
 O'REILLY, J.P. Region 2, Office of Director. 83/04/11. BTEHART, W.L. Virginia Electric & Power Co. 2pp. 18841 270 24X
 Fiche 50-280.83/04/11.8304140/10
- 8306140377 Forwards IE Insp Repts 50-280/83-12 & 50-281/83-12 on 830418-21 No noncompliance noted DANCE, H C Region 2: Office of Director. 83/05/17 BTEWART, W. L., Virginia Electric & Power Co 2pp 18832 084. 24X Fiche 50-280.83/05/17.8306140397
- --B306140400 IE Insp Repts 50-280/B3-12 & 50-281/B3-12 on 830415-21 No noncompliance noted Major aleas inspected containment integrated leakage rate testing & pipe supports & restraints,
 BROOKB:E H , JAPE, F Region 2, Office of Director, B3/05/12, 3pp 18832 086 24% Fiche 50-280, 83/05/17, 8306140397
- 8305110458 IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in Well Logging Device." Syc list encl TAYLOR.J M Division of Safeguards & Inspection Programs (Post 830103) 83/05/26. Consolidated Edison Co of New York, Inc 125pp 18831.043 24X Fiche 50-000.83/05/26,8305110458
- 8305110460 IE Info Notice 83-34, "Event Notification Info Worksheet,"
 Byc list enc!
 JOROAN, E.L. Division of Emergency Preparedness & Engineering
 Response (Post 830103), 83/05/26 Consolidated Edison Cp. of New
 York, Inc. 115pp. 18732 085, 24X Fiche 50-000, 83/05/26, 8305110460.

- 8305(1046) IE Info Notice B3-35. "Fuel Movement W/Control Rods Withdrawn at DWRs " Svc list encl JORDAN:E L. Division of Emergency Preparedness & Engineering Response (Pust 830103) 83/05/31 Consolidated Edison Co. of New York, Inc. 116pp 18732 208. 24X Fiche 50-000,83/03/31,8305110461
- 8306290331 Forwards response to IE Bulletin B3-08, "Check Valve Failures in Raw Water Cooling Sys of Diesel Generators "
 Surry has no valves in emergency diesel gemerator cooling sys Raw cooling water sys not used at North Anna STEWART, W L Virginia Electric & Power Co B3/06/08 D'REJLLY, J P Region 2, Office of Director 3pp 17055 303 24X fiche.50-000,83/06/08,8306270331
- 8305110464 IE Info Notice 83-36, "Impact of Security Practices on Sefe Operations " Syc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83706/07 Consolidated Edison Co of New York, Inc 119pp. 18830 280 24% Ficha 50-000,83706/09,8305110464
- 8305110470 IE Info Notice 83-38, "Defective Heat Bink Adhesive & Beismically Induced Chatter in Relays Within Printed Circuit Cards " Svc list encl JORDAN.E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co of New York, Inc. 188pp. 18920:225 24X Fiche.50-000.83/06/13,8305110470
- 8304090010 IE Info Notice 83-37: "Transformer Failure Resulting From Degraded Internal Connection Cables" Byc list encl JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) B3/06/13 Consolidated Edison Co. of New York, Inc. 243pp 18921 001, 24X Fiche 50-000,83/06/13,8306090010
- 8306170138 Withdraus 830503 extension request for first 10-yr ABME Section XI inservice insp program Relief requested from code requirements re insp tolerance band for completion of interval insp requirements limited to 1 yr BTEWART, W L. Virginia Electric & Power Co 83/06/14 DENTON, H R Office of Nuclear Reactor Regulation, Director VARGA, B A Operating Reactors Branch i 3pp 18878 355 24X Fiche 80-281.83/06/14.8306170138
- 8306200R19 Revises 830603 response to Enforcement Action 83-36 contained in IE insp rept re whole body counts & other outage-related requirements Corrected Page 3 encl STEMART, W.L. Virginia Electric & Power Co. 03/06/15 DEVOUND, R.C. Director's Office, Office of Inspection and Enforcement 2pp 18702 286 24X Fiche 50-280,83/06/15,8306200219
- 8305110475 IE Info Notice B3-40, "Need to Environmentally Gualify
 Epory Grouts & Sealers " Svc list encl
 JBRDAN.E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/06/22 Consolidated Edison Co of New
 York Inc 115pp 19021 179 24X Fiche 50-000, B3/06/22, 8305110475
- 8305110477 IE Info Notice 83-41, "Actuation of Fire Buppression Bys Causing Inoperability of Safety-Related Equipment " Svc list and I JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/22 Consolidated Edison Co. of New York, Inc. 120pp 18997 007 24X Fiche 50-000,83/06/22,8305110477
- B305110479 IE Info Notice 83-42, "Reactor Mode Switch Malfunctions,"
 Evc list encl.
 JORDAN, E. L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) B3/04/23 Consolidated Edison Co. of New
 York: Inc. 116pp 18996 242 24X Fiche 50-000,83/06/23,8305110479
- 8305110483 lE Info Notice 83-43, "Improper Bettings of Intermediate Range (IR) High Flux Trip Betpoints " Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/24. Consolidated Edison Co. of New York: Inc. 116pp 19046 297 24X Fiche 30-000,83/06/24.8305110483
- R Periodic operating reports & related correspondence
- 8306020159 Forwards monthly operating repts for Har 1983 & corrected pages to health physics rept for monthly operating repts for Jan & Feb 1983.

 STEHART: H L Virginia Electric & Power Co. 83/04/14. HALLER, N M Office of Resource Management, Director 1p. 18691 006. 24X Fiche 50-280,83/04/14.8306020159
- ---8304020162 Monthly operating repts for Mar 1983, JONES.V Virginia Electric & Power Co 83/04/19 47pp 18491:007 24% Fiche 50-280,83/04/14.8304020189
- --8306020168 Correct page to health physics rept for monthly operating rept for Jan 1783.

 * Virginia Electric & Power Co. 83/04/14. 1p 18691.054. 24X Fisher 50-280.83/04/14.8306020159.

- ~-8306020173 Corrected page to health physics rept for monthly operating rept for Feb 1983

 * Virginia Electric & Power Co 83/04/14 ip 18691 055 24X
 Fiche 50-280.63/04/14,8306020159
- 8305160375 Monthly operating repts for Apr 1983 W/830513 ltr JONES, V., STEWART, W.L. Virginia Electric & Power Co. 83/05/13 48pp 18861 074 24% Fichs 50-280.83/05/13.8306160375
- S Reportable accurrences, LERs & related correspondence
- 8306070238 Forwards LEAs 83-022/03L-0 & 83-023/03L-0 WILBONJ L Vinginia Electric & Power Co 83/05/27 O'REJLLY, J P Region 2, Office of Director 1p 18744 222 24X Fiche 50-281,83/05/27,8306070238
- ~-8306070243 LER 83-022/03L-0 on 830430.PT-27 revealed amp readings for heat tracing panel 8.circuits 5A & 22A.below acceptance criteria Caused by excessive heat Defective heat tracing replaced & tested Design change prepared WILGON.J L Virginia Electric & Power Co 83/05/27 Region 2. Office of Director 2pp 18744 223 24X Fiche 50-281.83/05/27. 8306070238
- --B306070245 LER 83-023/03L-0 on 830511.PT 2/B revealed amp readings for heat tracing panel 7.circuit 28A.below acceptance criteria Caused by boric acid buildup on heat tape.corroding terminals & resulting in open circuit Heat tracing replaced HILSON,J L Virginia Electric & Power Co 83/05/27 Region 2, Office of Director 2pp 18744 225 24X Fiche 50~281.83/05/27, 8306070238
- 8304100184 LER 83-024/03L-0: on 830517.PT-27D revealed that ampere readings for heat tracing Panel 8.Circuit 13C below acceptance criteria in PT-27D Caused by excessive heat Defective heat tracing replaced W/830403 ltm WILSON, J.L. Virginia Electric & Power Co 83/06/03 O'REJLLY, J.P. Region 2. Office of Director 3pp 18806 021 24X Fiche 50-281,83/06/03,8306100186
- 8306270351 Forwards LERs 83-025/03L-0 & 83-026/03L-0 WILBON, J. L. Virginia Electric & Power Co 83/06/13 O'REILLY, J. P. Region 2, Office of Director ip 18973 143 24X Fiche 80-281: 83/06/13: 8306270351
- --B306270357 LER 83-025/03L-0. on 630518, w/unit at 100% power, MDV-8W-2028 failed to close electrically from control room Caused by rust buildup between clutch & motor operator housing Rust removed MILBON, J. L. Virginia Electric & Power Co. 63/06/13, Region 2, Office of Director. 2pp. 18993 144, 24% Fiche, 50-281, 83/06/13, 8306-2031
- --B306270364 LER 83-026/03L-0 on B30616. w/unit at 100% power, breaker for MDV-SM-2028 found open & motor grounded Cause Disknown Breaker could have been accidentally bumped Motor dried due to masiture & breaker closed WILBON, J. L. Virginia Electric & Power Co B3/06/13 Region 2, Office of Director 3pp 18993.146 24% Fiche: 50-281,83/06/13,8306270391.
- 8306300199 LER 83-027/OSL-0, on 830523, PT-27C revealed that amp reading for heat tracing panel B. circuit 22A below Tech Spec Limit. Caused by excessive heat Heat tracing replaced Design change initiated W/830620 WILSON, J. L. Virginia Electric & Power Co. B3/06/20 G'REILLY, J.P. Region 2. Gffice of Director. 3pp 19122 177 24X Fiche. 80-281, 83/06/20, 8306300199.
- DOCKET 50-282 PRAIRIE IGLAND NUCLEAR STATION, UNIT 1
 F. Security, medical, emergency & fire protection plans
- 8306100059 "Control Room Design Review Plan.Prairie Island Nuclear Cenerating Plant," response to Generic Ltr 82-33, Suppl 1 to NUREG-0737 W/630527 ltr NUSDLF, D. Northern States Power Co 83/05/27 47pp 18802 123 24X Fiche 50-282,83/05/27,8306100059
- B306090237 Forwards "Emergency Operating Procedures Generation Package," in response to Generic Ltr 82-33. Suppl 1 to NUREO-0737. MUSDLF, D. Northern States Power Co. 83/05/31. Office of Nuclear Reactor Repulation. Director in 18797-001 24X Fichs: 50-282.83/05/31.8306090237

- 8306090254 Releases public version of revised amergency plan implementing procedures FELTON.J M Division of Rules and Records 83/06/01 Document Management Branch ip 18809 261 24X Fiche 50-282,83/06/01,830609054
- --8306090257 Forwards public version of revised emergency plan implementing procedures, including Procedures A 2-301 re emergency evacuation, A 2-3-2 re assembly point activation & A 2-303 re search & rescue WARD, E C Northern States Power Co 83/05/17 Region 3, Office of Director 1p 18809 262 24X Fichs 50-282,83/06/01,830690258
- --830&0702&1 Public version of revised emergency plan implementing procedures, including Procedures A 2-301 re emergency evacuation, A 2-302 re assembly point activation & A 2-303 re search & rescue FEY, F L Northern States Power Co 83/05/09 112pp 18809 263 24X Fichs 80-282,83/06/01,8306090254
- 8306090263 Forwards Rev 9 pages for security plan Pages withheld (ref 10CFR73) MUSQLF,D Northern States Power Co 83/06/06 Office of Nuclear Reactor Regulation, Director ip 10795 279 24X Fiche 50-282,83/06/06,8306090263
- B306230073 Releases public version of revised emergency plan implementing procedures FELTON, J.M. Division of Rules and Records B3/06/06 Document Management Branch ip 18982: 186 24X Fiche 50-282, 83/06/06, B306230073
- --B304230077 Forwards public version of revised emergency plan implementing procedures, including Procedures F3-3 re responsibilities during notification of unusual event & F3-13 re offsite dose calculation MARD, C C Northern States Power Co B3/05/16 Region 3, Office of Director 1p 18782 187 24X Fiche 50-282,83/04/06, B304230073
- --8306230087 Public version of revised emergency plan implementing procedures, including Procedures F3-3 re responsibilities during notification of unusual event/f3-13 re offsite dose calculation & F3-14 2 re operations emergency surveys SCHUELKE, D. A. Northern States Power Co. 83/04/26 Region 3, Office of Director 91pp 18782 188 24X Fiche 50-282,83/06/06,8306230073
- 8306280459 Informs that operational data for completion of HEPA filtration sys extended to 831001 due to difficulty in adopting ventilation sys to accommodate demands of HEPA filtration per Suppl 1 to NUREO-0737 MUSOLF, D. Northern States Power Co. 83/06/20 Office of Nuclear Reactor Regulation, Director ip 19018 328 24X Fiche 50-000, 83/06/20, 8306280459
- P Operating licenso stage documents & correspondence
- 8304010349 Forwards updated equipment lists reflecting plant mods, current NRC views & licensee continuing review in response to 10CFR50 49. "Environ Qualification of Electrical Equipment Important to Safety for Nuclear Power Plants "MUSOLF, D M Northern States Power Co 83/05/19 Office of Nuclear Reactor Regulation, Director 60pp. 18680 091 24X Fiche 50-282,83/05/19.8306010349
- 8304090230 Submits 30-day response to NRC B30425 safety evaluation of environ qualification of safety-related electrical equipment. Facility can operate safely while environ qualification deficiencies being resolved MUBOLF.D. Northern States Power Co. 83/05/27. Office of Nuclear Reactor Regulation, Director 2pp 18795 344 24X Fiche. 50-282, 83/05/27, 8304090230
- 8304200281 Advises that justification for continued operation reenviron qualification of safety-related electrical equipment acceptable Rosemount transmitters 1152 Series D reclassified from NRC Category II B to II C.

 CLARK.R A Operating Reactors Branch 3 83/06/03. MUSDLF, D. M Northern Btates Power Co 2pp 18919. 264. 24X

 Fiche 50-282, 93/06/03, 8306200281
- ---8306200283 Safety evaluation supporting justification for continued operation w/sefety-related equipment unqualified * Office of Nuclear Reactor Regulation, Director 63/06/06 2pp. 18919,266 24X Fiche. 50-282. 83/05/03,8306200281

- 830&170053 Concurs w/findings contained in technical evaluation rept, "Control of Heavy Loads" Duidelines in NUREO-0612, Section 5 i 1 satisfied, per util 810402, 0715, 0831 & 1209, 820203 & 1108 & 830408 submittals CLARK, R A Derrating Reactors Branch 3 B3/06/06 MUSOLF, D. M. Northern States Power Co 2pp 18906 314 24X Fiche 50-282, 83/06/06, 8306170053
- --8306170058 Safety evaluation supporting util Phase I actions re control of heavy loads NUREG-0612, Section 5 1 1 guidelines satisfied # Office of Nuclear Reactor Regulation, Director 18706 316 24x Fiche 50-282,83706706,8306170053
- ~-8305230021 "Control of Heavy Loads (C-10), Prairis Island Nuclear Generating Plant, Units 1 & 2," technical evaluation rept VOSBURY, F M Franklin Institute/Franklin Research Center. NRC-03-81-130 TER-C5506-384/385 83/05/17 NRC No Detailed Affiliation Given 3ipp. 66794 188 24X Fiche 50-282,83/06/06,8306170083
- 8306200370 Forwards safety & licensing portion of Westinghouse Apr 1982 rept. providing addi info re fuel assembly failure effect on insertion of control rods or core cooling geometry MUSOLF, D. Northern States Power Co. 83/06/07. Office of Nuclear Reactor Regulation, Director 2pp 18899-052 24X Fiche 50-882,83/06/07,8306200370.

4 Inspection reports: IE Bulletins & correspondence

- 8305110458 IE Info Notice 83-32, "Ruptured Am-241 Bources Contained in Well Logging Davice." Svc list encl TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/05/26 Connolidated Edison Co of New York, Inc 125pp 18831 043 24X Fiche 50-000,83/05/26,8305110458.
- 8305110460 IE Info Notice 83-34, "Event Notification Info Worksheet," 8vc 1ist encl. JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co. of New York, Inc. 115pp. 18732 085, 24X Fiche 50-000,83/05/26,8305110460.
- 8304040004 Commends NRC re results of piping insp at BMRs.
 Leak-before-break concept continues to sustain validity of
 technical bases Utils giving consideration to more permanent
 measures
 NEILS, G. H. Northern States Power Co. 83/05/24 DENTON, H. Office
 of Nuclear Reactor Regulation, Director 2pp 18719-335 RAX
 Fiche 80-000.83/05/26.8306040084.
- 8305110461 IE Info Notice 83-39, "Fuel Movement W/Control Rods Withdrawn at BWRs " Svc list encl JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/08/31 Consolidated Edison Co. of New York, Inc 116pp 18732 208 24X Fiche 50-000,83/05/31,8308110461.
- 8306170232 Submits list of affected valves, test method & test schedule in response to IE Bulletin 83-03. Inservice insp program will be revised to include testing of listed valves. LARBON, C. E. Northern States Power Co. 83/06/08 REPPLER, J. 9. Region 3, Office of Director 2pp. 19878 284. 24X Fiche: 50-282,83/06/08,8306170232.
- 8305110464 IE Info Notice 83-36, "Impact of Security Practices on Safe Operations," Svc list encl JORDAN,E L. Division of Emergency Preparadness & Engineering Response (Post 830103) 83/06/09 Consolidated Edison Co. of New York, Inc 119pp 18830:280. 24X Fiche, 50-000, 83/06/09, 8305110464
- 8305110470 IE Info Notice 83-38, "Defective Heat Sink Adhesive & Seismically Induced Chatter in Relays Within Printed Circuit Cards," Svc list encl.
 JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/06/13 Consolidated Edison Co. of New York, Inc. 118pp 18720:225 24X Fiche: 50-000, 83/06/13, 830510470.
- 8306090010 IE Info Notice 83-37, "Transformer Failure Resulting From Degraded Internal Connection Cables." Svc list encl
 JORDAN.E.L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/06/13 Consolidated Edison Co of New
 York, Inc. 243pp 18921.001. 24X Fiche.50-000.83/06/13,8306090010.
- 8305110475 IE Info Notice 83-40, "Need to Environmentally Guslify
 Epoxy Grouts & Sealers." Syc list enc!
 JORDAN.E.L. Division of Emergency Preparedness & Engineering
 Response (Post 830103). 83/06/22. Consolidated Edison Co. of New
 York, Inc. 115pp. 19021; 179, 24X Fiche 50-000, 83/06/22, 8305110475.

- 8305110477 IE Info Notice 83-41, "Actuation of Fire Suppression Sys Causing Inoperability of Safety-Related Equipment " Syc list
- enci JORDANJE L snc: JOHDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83705/22 Consolidated Edison Co of New York, Inc. 120pp. 1899/ 007 24X Fiche 50-000.63/06/22.6305110477.
- 8305110479 IE Info Notice 83-42, "Reactor Mode Switch Malfunctions."
- Svc list encl, JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). B3/06/23 Consolidated Edison Co. of New York, Inc. 116pp. 18996 242 24X Fiche.50-000,83/06/23,8305110479
- 8305110483 IE Info Notice 83-43, "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints " Svc list and JORDAN E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/24 Consolidated Edison Co. of New York, Inc 116pp. 19046:297 24X Fiche 50-000,83/06/24,8305110403
- 830.6280340 Requests relief from requirement re 10-yr inservice insp of reactor coolent pump casing welds of ASME Boiler & Pressure Vessel Code/Section XI, "Inservice Insp " Request submitted as Rey 9 to inservice insp & testing program MUSOLF.D Northern States Power Co. 83/06/24 Office of Nuclear Resctor Regulation. Director. 30p 19014 070 24X Fiche 50-282.63/06/24.8306280340
- --8306280345 Rev 9 to "ASME Code Section XI Inservice Insp & Testing
 - * Northern States Power Co. 83/05/24 9pp 19014 073. 24X Fichs.50-282,83/05/24:8306280340
- R. Pariodic operating reports & related correspondence
- 8306020167 Monthly operating repts for Mar 1983 W/830411 ltr MUSDLF,D , DUGSTAD,D Northern States Power Co 83/04/05 18691:075. 24X Fighs 50-282,83/04/05,8306020167. 900.
- 8306140002 Honthly operating repts for May 1983 W/830607 ltr. DU9STAD.D., MUSCLE, D. Northern States Power Co. 83/06/07 of Resource Management, Director 7pp. 18838-219 24X Fiche: 50-282, 83/06/07. 8306140002 Office
- DOCKET 50-265 FORT CALHOUN STATION, UNIT 1
- F. Security, medical, emergency & fire protection plans
- 8305090029 Releases public version of changes to radiological emergency response plan. FELTON, J. H. Division of Rules and Records, 83/04/01 Document Hanggement Branch ip 18798-022 24X Fiche: 50-285,83/04/01,8306090029
- --8306090032 Forwards public version of changes to radiological emergency response plan W/o encl JONES, W.C. Cmaha Public Power District. 83/0 Region 4. Office of Director ip 18798-023 Fiche: 50-285, 83/06/01, 8306090029. 83/05/11. CDLLINB.J T.
- 8306160346 Releases public version of changes to emergency plan implementing procedures. FELTON.J.M. Division of Rules and Records. 83/06/06 Docum Management Brench. 1p. 18872: 168. 24X Fiche: 50-285,83/06/06.
- --8306160354 Forwards public version of changes to emergency plan implementing procedures. M/o antl.
 JONES, W. C. Omeha Public Fower District B3/03/25 COLLINB, J. T. Region 4. Office of Director 1s. 18872.169 24X Fiche: 50-285.83/06/06,8306160346
- 8306210357 Releases public version of changes to emergency plan implementing procedures FELTON.J.H Division of Rules and Records 83/05/06. Docum Hananament n. Ip. 18935:292. 24X Fichs:50-285,83/05/06.
 - mion of changes to emergency plan enci ler District, 83/04/27, COLLINS.J.T . ip. 18935:291 24X 0359.

- P Operating license stage documents & correspondence
- 8306300069 Forwards status of evaluation for sampling waste decay tanks & data from RCB gas sampling program, in response to NRC 830329 ltr to mfC 830327 ltr JONES,W C Dmaha Public Power District 83/04/28 Region 4. Office of Director 96pp 1904B 001 P4) Fiche 50-205,83/04/28,8306300069 SETOLE, U.C.
- 8306060183 Forwards list of revised alternate shutdown panel (AI-185) drawings as of 830420 Drawing 13007 42-ESK-11D canceled JONES.N.C. Dmaha Public Power District 83/05/02 SEIOLE.N.C Region 4, Office of Director 4pp 18719 162 24X Fiche 50-265.83/05/02.8306060183
- B306010003 Notice of consideration of issuance of amend to OL & proposed no significant hazards consideration determination & opportunity for hearing re RCS pressure-temp limit curves Encl determination available in Central Files only CLARKR A Operating Reactors Branch 3 83/05/12 9pp 18483 232 24X Fiche-50-285.83/05/12,8306010003
- B305080247 Advises that proposal to bupass certain reactor protection sys channels for more than 48 h.per B10722 application & B20615 & 1027 ltrs, unacceptable for listed reasons Addl info requested within 30 days of receipt of ltr CLARK.R A Operating Reactors Branch 3 B3/05/R3 JONES, W C Omaha Public Power District 18pp 18785 331 24X Fiche 50-285,83/05/23,8304080249
- 8306160157 Discusses 830412 meeting w/utils re damage to reactor thermal shield support lugs at St Lucie 1 Safety svaluation concluding that continued operation justified end CLARK.R A Operating Reactors Branch 3 83/06/01 JONES.W C Umaha Public Power District 2pp 18892 355 24X Fiche 50-285,83/06/01.8306160159
- --8306160164 Safaty evaluation supporting continued operation of facility based on until familiarity w/thermal shield concerns * NRC No Detailed Affiliation Given, 83/06/01 4pp 18892 357 24% Fiche 50-285,83/06/01,8306160159
- 8306100102 Application to amond License DPR-40, changing Tach Specs re proposed apent fuel storage rack mod JONES.W C Chaha Public Power District 83/06/06 CLARK, R A Operating Reactors Dranch 3, ip 18802 211 24X Fiche 50-285,83/06/06.8306100102
- --8306100106 Proposed Tach Specs re spent fuel storage rack mod * Omaha Public Power District 83/06/06 15pp 18802;212 24X Fichs 50-285.83/06/06.8306100102
- 6304130240 Comments on NUREG/CR-2337, Vols 1 & 4, "Aquatic Impacts From Operation of Three Midwestern Nuclear Power Stations "Author evaluation & conclusions differ from util understanding gained in studies Supporting info encl JONES W C Omeha Fublic Power District 83/06/06 VOLLMER, R H Division of Engineering 40ps 18824 174 24X Fiche 50-285,83/06/06,8306130260
- 8306160691 Forwards in-process OL amend requests currently being evaluated by NRC, in response to final rules, effectave 830506, specifying that when licensees request amend to OL, licensee must notify appropriate State designee TOURIONY, E 9 Operating Reactors Branch 3 83/04/06 SIMMONS, H E North Datota, State of 2pp 18876 288 24X Fiche: 50-285, 83/06/06, 8306160671
- 8306200065 Monthly notice of amends to OLs involving no significant hazards consideration notice of consideration of issuance of amend to License DPR-40 & proposed no significant hazards determination & opportunity for hearing CLARK, R A Operating Reactors Branch 3 83/06/07 16pp 18908 311, 24% Firhe, 50-285, 83/06/07, 8306200065
- 8306290081 Requests FR notice of consideration of issuance of amend to License DPR-34 & proposed no significant hazards consideration determination re add1 assurance that objectives of App I met CLARK.PLA Operating Reactors Branch 3 83/06/13, KREUTZER.P.M. Operating Reactors Branch 3 83/06/13, Z4X Fichs: 50-285,83/06/13,8306290081.
- B306270105 Forwards results of C-E analysis of effects of dropped thermal shield-per B30601 request Results do not differ significantly from NRC preliminary assessment. JUNES.W C Omaha Public Power District, B3/06/17, CLARK.R.A. Operating Reactors Branch 3 2pp, 18908,113 24X Fichs.50-285,83/06/17,8306270105.

- B306290158 Forwards safety evaluation concluding that requirements of TMI Items II F 1 4 A II F 1 5 & II F 1 6 re containment pressure, water level & hydrogen monitors met Items resolved CLARK, R A Operating Reactors Branch 3 B3/06/17 JONES, W C Omaha Public Power District 9pp 19046 271 24% Fiche 50-285, B3/06/17, B306290150
- 8306240347 Requests publication of FR notice re issuance of Amend 74 to License DPR-40 concerning RCG pressure-tamp limits for operation to 7 0 effective full power yrs CLARK,R A Operating Reactors Branch 3 63/06/20 MREUTZER.P M Operating Reactors Branch 3 ip 16797 170 24X Fiche 50-265,63/06/20.8306240347
- 8304280073 Forwards Amend 74 to License DPR-40 & safety evaluation Amend revises Tech Specs for RC9 pressure-temp limits for operation to 7 0 effective full power yrs Tomonovy, E 0 Operating Reactors Branch 3 83/04/20 JGNF8, W C Omaha Public Power District 2pp 17042 321 24X Fiche 50-285,63/06/20,6306280073
- --8306280075 Amend 74 to License DPR-40, revising Tech Specs for RCB pressure-temp limits for operation to 7 O effective full power yes CLARK, R A Operating Reactors Branch 3 B3/06/20 18pp 19042 323 24X Fiche 50-285, 83/06/20, 8306280073
- --8306280078 Safety evaluation supporting Amend 74 to License DPR-40 * Office of Nuclear Reactor Regulation, Director 63/06/20 3pp 19042 341 24X Fichs 50-285,83/06/20,8304280073
- B30.6280233 Forwards correct version of App A. "Mechanical Errors From NUREO/CR-2337.Vol 1.Aquatic Impacts From Operation of Three Midwestern Nuclear Power Plants " Draft version inadvertently attached to B30.606 submittal JONES.W C Omaha Public Power District B3/06/22 VOLLMER.R H Division of Engineering 10pp 17015 088 24X Fiche 50-285.83/06/22.8304280233
- 830.6280.487 Discusses problems w/post-accident sampling sys (PASS) microprocessor.on-line pH meter sample flow & ion chromatograph Proposed PABB completion per NUREO-0737. Itum II B 3, scheduled for 830730 JONES.W C Omaha Public Power District 83/06/23 CLARK.R A Operating Reactors Branch 3 3pp 19019 186 24X Fiche 50-285,83/06/23.8306280487
- 830.6280464 Responds to 830523 ltr re Tech Spec amend application concerning inoperability of reactor protection sys (RPS) channels Heating requested to resolve differences between util & NRC Tech Spec amend proposals
 JONES, W.C. Omaha Public Power District 83/06/24 CLARK, R.A. Operating Reactors Branch 3 2pp 19020 133 24X
 Fiche 50-285,83/06/24,830628(464
- Q Inspection reports: IE Bulletins & correspondence
- 8304080231 Ack receipt of B30223 ltr informing NRC of steps taken to correct violations noted in 1E Insp Rept 50-285/82-21 Addl info re sampling equipment & techniques especially for gases: requested within 30 days of ltr date SEIDLE.W C Region 4. Office of Director 83/03/29 JONES.W C Omaha Public Power District 2pp 18771 001 24X Fiche 50-285,83/03/29,8304080231
- --8306080236 Responds to NRC 830119 ltr re violations noted in IE Insp. Rept 50-285/82-21. Corrective actions program implemented to cross-calibr Canberra & TN-11 gemma espectrometer sys. Program expected to be completed by 803401 JONES, W.C. Omnha Public Power District, 83/02/23 SEIDLE, W.C. Region 4, Office of Director 1p. 107/1 003 P4X Fiche 50-285,83/03/29,8306080231
- 8304080109 Forwards IE Insp Rept 50-285/83-03 on 830117-21 & notices of violation & deviation SEIDLE.W C Region 4. Office of Director 83/04/13 JONES.W.C Omaha Public Power District 2pp 18771 253 24X Fiche 50-285,83/04/13.8304080107
- --8304080129 Notice of violation from insp on 830117-21 * Region 4, Office of Director 83/04/13 ip 18771:255 24X Fiche 50-285,83/04/13,8304080109
- --8306080134 Notice of deviation from insp on 830117-21. * Region 4, Office of Director 83/04/13 ip 18771 256 24X Fiche 50-285,83/04/13,8306080109

- --8306080211 IE Insp Rept 50-285/83-03 on 830117-21 Noncompliance notedbag containing radioactive meth observed in noncompactible waste bin & w/o hot spot sticker attached WILBORN, L. MURRAY, B. JOHNSON, W.D. Ragion 4. Office of Director 83/03/29 12pp 18771 257 24X Fiche 50-285,83/04/13,8304080109
- 8306090349 Forwards IE Insp Rept 50-285/83-06 on 830307-11 No noncompliance noted SEIDLE, W C Region 4, Office of Director 83/04/13 JONES, W C Omaha Public Power District 3pp 18793 150 24X Fiche 50-285,83/04/13,8306090349
- --8306090354 IE Insp Rept 50-285/83-06 on 830307-ii No noncompliance noted Major areas inspected radwaste sys & qualification criteria for supervisor of chemical radiation protection CHANEY.H D , MURRAY.B , JOHNSON,W D Region 4. Defice of Director, 83/04/12 17pp 18795 153 24X Fiche 50-285,83/04/13,8306070349
- 8306:30364 Responds to IE Bulletin 83-03 re check valve failures in dissel generator raw water cooling sys. Check valves not used at facility JONES, W. C. Gmaha Public Power District 83/05/20 COLLING, J. T. Region 4, Office of Director 3pp 19822, 161, 24X Fiche 80-285,83/05/20,8306130364
- 8305110458 IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in Well Logging Device" Syc list encl TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/05/26, Consolidated Edison Co. of New York, Inc. 125pp 18831 043 24K Ficher 50-000, 83/05/26, 8305110458
- 8305110460 IE Info Notice 83-34, "Event Notification Info Worksheet"
 Byc list encl
 JORDAN.E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/05/26 Consolidated Edison Co. of New
 York, Inc 115pp 18732 085 24X Fiche 50-000,83/05/26,8305110460
- 8305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods Withdrawn at BWRs." Svc. list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/31 Consolidated Edison Co. of New York, Inc. 116pp 18732 208 24X Fichs. 50-000, 83/05/31, 8305110461
- 8306160159 Discusses 830412 meeting w/utils re damage to reactor thermal shield support lugs at 9t Lucie 1 Safety evaluation concluding that continued operation justified encl. CLARK, R A Operating Reactors Branch 3 83/06/01 JONES. H C Omaha Public Power District. 2pp 10872 355 24X Fiche 50-285,83/06/01.8306160159
- --8305160164 Safety evaluation supporting continued operation of facility based on until familiarity w/thermal shield concerns * NRC No Detailed Affiliation Given 83/06/01. 4pp. 18892 357 24X Fiche 50-285.83/06/01.8306160159
- B306130117 Ack reciept of B30520 ltr informing NRC of steps taken to correct violations noted in IE lnsp Rept 50-285/83-09.
 BEIDLE, W C Region 4. Office of Director. 63/06/06 JONES, W C Omska Public Power District 1p 18824 295 24X
 Fiche 50-285,83/06/06.B306130117
- --8306130130 Responds to NRC B30422 ltr re violations noted in IE Insp Rept 50-285/83-09 Corrective actions change to Standing Order 9-30 to require that spot changes be specifically noted within text of procedures initiated JONES: W C Omaha Public Power District B3/05/20. BEIDLE, W. C. Region 4. Office of Director. 20p 18824 296, 24X Fiche 50-285, 83/06/06, 8306130117
- 8305110464 IE Info Notice 83-36, "Impact of Security Practices on Safe Operations." Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/07 Consolidated Edison Co. of New York, Inc 117pp 18830.280. 24X Fiche 50-000.83/06/09.8305110464.
- 8305110470 IE Info Notice 83-38. "Defective Heat Sink Adhesive & Seismirally Induced Chatter in Relays Within Printed Circuit Cands " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13. Consolidated Edison Co. of New York, Inc 118pp. 18920 225 24% Ficher 50-000,83/06/13,8308110470.
- 8306090010 IE Info Notice 83-37, "Transformer Failure Resulting From Degraded Internal Connection Cables " Byc list encl, JURDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13. Consolidated Edison Co. of New York, Inc. 243pp. 18921 001 24X Fishe 50-000,83/06/13,8306090010.

Yorks Inc

- 8305110475 IE Info Notice 83-40, "Need to Environmentally Qualify Epoxy Grouts & Sealers " Svc list encl. JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83706/22 Consolidated Edison Co. of New York, Inc. 115pp 1902: 179 24X Fiche 50-000,83706/22,8308110475
- 0305110477 IE Info Notice 83-41, "Actuation of Fire Suppression Sys Causing Inoperability of Safety-Related Equipment " Syc list Division of Emergency Preparadness & Engineering tost 830103) 83/06/22 Consolidated Edison Co. of New 120pp 18997 007. 24X Fiche, 50-000, 83/06/22, 8305110477 JORDAN, E L. D. Response (Post
- 8305110479 IE Info Notice 83-42; "Reactor Mode Switch Malfunctions." Bvc list encl. JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/23 Consolidated Edison Co. of New York, Inc. 1146p 18996-242 24X Fishe 50-000.83/06/23,8305110479
- 8305110483 IE Info Notice 83-43, "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints " Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/06/24 Consolidated Edison Co of New York, Inc. 114pp 19046, 297 24x Fiche 50-000, 83/06/24, 8305110483
- R. Periodic operating reports & related correspondence
- B306200358 Monthly operating rapt for May 1983. W/630644 ltr.

 MATTHENS, T. P., JUNES, W. C. Omaha Public Power District 83/06/14

 DEYOUNG, R. C. Director's Office, Office of Inspection and
 Enforcement 11pp, 18901 020 24% Fiche: 50-285, 83/06/14,
 8306200358.
- S Reportable occurrences, LERs & related correspondence
- 8304040277 Corrected LER 82-017/03L-; on 820830, valve position indication not noticed for inboard containment isolation valves HCV-820B & 821B, associated w/hydrogen monitor VA-81A Caused by failure of Conex environ seals. W/830525 ltr CORE.M.R., JONES.W.C. Omaha Fublic Power District. 82/09/27 BEIDLE.W.C. Region 4, Office of Director, 6pp. 18727,043, 24X Fichs. 50-285,82/09/27,8304040299
- DOCKET 50-286 INDIAN POINT STATION, UNIT 3
- F Security, medical, emergency & fire protection plans
- 8306200403 Forwards exercise objectives & scenario outline for small-scale emergency preperedness exercise scheduled for 830602; in response to NRC 811026 exercise quidalines BRONS.J.C. Power Authority of the State of New York. 83/03/17 HAYNES.R.C. Region 1: Office of Director. 8pp 18899.304 24X Fiche.50-286,83/03/17.8306200403
- --8306200411 Forwards small-scale emergency preparedness exercise scenario per guidelines established in NRC 811026 ltr. Benario outline & expected time frame for events also encl. BRDNS.U.C. Power Authority of the State of New York 82704/2: ALLAN.U.A. Region 1, DPPIce of Director. 195pp. 18899:311. Fiche: 50-286:83703/17.8306200403 04/22
- 8304030343 Ack receipt of 830128 ltr in response to NRC 821104 ltr re
 IE Insp Rept 50-286/82-09. Effective coverage by radial-type
 notals not addressed in safety evaluation. Addl info
 requested 830228 not received
 MARTIN.T T. Division of Engineering & Technical Fragrams. 83/05/2:
 BRONS, J. C. Power Authority of the State of New York. Zpp.
 18705:012. 24X Fiche: 50-286, 83/05/23, 8306030343
- --8306030345 Forwards add1 info re installation of radial pattern sprinkler neurles in lieu of previously committed closed head horizontal side-wall type per IE Insp Rept 50-286/82-09. BROWS.J.C. Power Authority of the State of New York 63/01/28. MARTIN.T.T. Division of Engineering & Technical Programs. 5pp 18705:014. 24X Fiche: 50-286.83/05/23.8306030343
- 3306220243 Forwards SERs on seismic qualification of auxiliary faadwater sus & fire protection interim measures re restart. Plant provides sufficient alectrical redundancy & reliability for interim operation.

 VARGA.S.A. Operating Reactors Branch 1, 83/05/27, BAYNE, J.P. Power Authority of the State of New York, 5pp. 18951:116, 24% Fiche: 50-286,83/05/27,8306220243
- -830622025i Bafety evaluation re seismic qualification of auxiliary feedwater sys. Bys capable of withstanding BSE since open items re turbins automatic speed control & instrument air pipings identified in encl technical rept, resolved a Office of Nuclear Reactor Regulation, Director, 83/05/27, 12pp. 1895i; 12i, 24X Fiche; 50-286, 83/05/27, 8306220243.

- --8306220261 Safety evaluation re fire protection interim measures Licensee actions demonstrate that interim alternate power supplies will be available until long-term 10CFR50.App R, requirements satisfied # Office of Nuclear Reactor Regulation, Director 83/05/27 2pp 18991 133 24X Fiche 50-286.83/05/27.0306220243
- 8306090297 Confirms by ltm of intent, contract to make buses available during evacuation caused by radiological emergency, VHAAD, E R Consolidated Edison Co. of New York, Inc. * Power Authority of the State of New York, CORWIN, S Affiliation Unknown 83/06/01 CORWIN, S Affiliation Unknown ip 18775 238 24X Ficha 50-247,83/06/01,8306090279
- 8306090317 Confirms, by ltr of intent, contract to make buses available during evacuation caused by radiological emergency VHAAD, E.R. Consolidated Edison Co. of New York, Inc. BAYNE, J.P. Power Authority of the State of New York * Affiliation Unknown 83/06/01 SILVANIO, J. Affiliation Unknown ip 18795 230 24% Fichs 50-247, 83/06/01,8306090317
- 8306070325 Confirms by ltr of intent, contract to make buses available during evacuation casued by radiological emergency * Consolidated Edison Co of New York Inc BAYON, J.P. Power Authority of the State of New York MURPHY, J. Liberty Lines Transit, Inc 19 18793 067 24X Fiche 50-247, 83/06/02, 8306090325
- 8306090340 Confirms, by lir of intent, contract to make buses available during evacuation caused by radiological emergency # Consolidated Edison Co of New York, Inc. BAYON, J.P. Power Authority of the State of New York # Riverdale Transit Corp. 83/06/02 MURPHY, J. Riverdale Transit Corp. 1p. 18794 321 24X Fiche: 50-247, 83/06/02, 8306090340
- 8306090302 Forwards application for amend to License DPR-64, changing Tach Bpecs re fire protection mods, in response to SA Varga 830421 itr Procedures re alternate electrical feed sys operation will be at site prior to startup BAYNE, J.P. Power Authority of the State of New York 83/06/03 VARGA, 8 A Operating Reactors Branch 1 2pp 16795-242 24X Fiche: 50-286, 83/06/03, 8306070302
- ---8306070304 Application to amend License DPR-64, changing Tech Spec Sections 3 3,3.14 & 4 12 re fire protection mode, in response to BA Varge 830421 ltr BAYNE, J.P. Power Authority of the State of New York 83/06/03 1p. 18795 244 24X Fiche 50-286,83/06/03,8306070302
- --8306070307 Proposed Tech Specs re fire protection :
 * Power Authority of the State of New York 83.
 18775 245 24X Fiche 50-286,83/06/03,8306070302 B3/06/30 11pp
- 8306150206 Staff requirements memo re 830526 oral presentations in Bathsada, MD re emergency planning & preparedness at Indian Point List of participants ent GHILK, BJ Office of the Becretary of the Commission 83/06/07 Office of the Secretary of the Commission 83/06/07 Fiche 30-247, 83/06/07, 8366150206
- 8306170396 Forwards FEMA 830608 ltr to NRC, providing current evaluation of plant offsite emergency planning HABBELL.D F Hearing Branch 2 83/06/09 CLEASON, J P. Atomic Bafety and Licensing Board Panel 46pp 18879 333 24X Fichs 80-247,83/06/09,8306170396
- 8304200030 Staff requirements memo re 830409 discussion & vote in Washington.DC on continued operation of Indian Point Commission agreed by vote of 3-2 to allow continued oberation. operation, CHILK, B.J. Office of the Secretary of the Commission. 83/ Office of the Secretary of the Commission 1p 18708-356 Fiche: 50-247,83/06/14,8306200030. 83/06/14 356 24X
- 830.421013B Requests clarification of NRC position re approval of security plan rays Util will adhere to revised security plan until NRC authorization received to commence 2-yr implementation period.

 BAYNE, J.P. Power Authority of the State of New York. 83.

 VARQA: B.A. Operating Reactors Branch 1 2pp 18916 347

 Fiche: 50-286,83/06/15.8306210138.
- @ Adjudicatory correspondence
- 830401045: Bupports continued operation of facility. Impact of shutdown would be devastating.
 O'SHAUGHNESSY Affiliation Unknown 83/05/20. PALLADINO,N.J.
 Commissioners 2pp. 18674:352 24X Fiche 50-247,83/05/20, 6306010451

- 8304040180 Response opposing util 830509 motion for reconsideration Deposition inadmissible as evidence under federal rules POBNER, P Parents Concerned About Indian Point 83/05/20 Atomic 84/8ty and Licensing Board Panel 3pp 18728 181 24X Fichs 50-247,83/05/20,8304040180
- 8306010458 Requests extension of 830609 deadling for planners to provide edequate emergency evacuation Util acting in good faith in expressing concern for quality of life of community residents
 BARNETT, T Affiliation Unknown 83/05/24 PALLADING, N J Commissioners ip 18674 327 24X Fiche 50-247,83/05/24,83/05/24,83/05/24
- 8306010348 Response eupporting licenses 830509 motion for reconsideration of ruling on admissibility of DP McGuire disposition Admission of testimony would not prejudice parties H/Certificate of Svc HASSELL.DF Hearing Branch i 83/05/31 Atomic Bafety and Licensing Board Panel 11pp 18681 336 24X Fiche 50-247,83/05/31,8306010348
- B306020443 Order requesting comments on encl rept re PRA by 830620 OLEASON.JP Atomic Safety and Licensing Board Panel 63/05/31 Consolidated Edison Co of New York, Inc 1p 18674 011 24X Fiche 50-247.83/05/31.8306020443.
- --B306020448 Forwards final rept. "Analysis of PRA Testimony Indian Point ASLB Hearings.Commission Guestion 1 " Rept conclusions coincids w/conclusions in B30502 ltr AMICO,P J. Applied Risk Technology Corp 83/04/01 GLEA80N.J P. SHON.F J. PARIB.O H Atomic Safety and Licensing Board Panel ip. 18694 012, 24X Fiche 50-247,83/05/31,8306020443
- --B30&020452 "Analysis of PRA Testimony Indian Point ASLB Hearings, Commission Guestion i," final rept AMICO,P, J Applied Risk Technology Corp ARTECH-83-001 B3/O&/01 NRC - No Detailed Affiliation Given 67pp, 18674 013 24X Fiche 50-247,83/05/31.830&020443
- 8306200270 Affidavit of RA Rosen on Commission Gusstion 6 3 EBR0 model underestimated average 1982 saltwater PWR capacity by 9 5% Value of model should be assessed based on ability to track experience over period of time ROSEN/RA Greater New York Council on Energy 83/05/31. Spp 18701.055 24% Fiche 50-247/83/05/31/8306200270
- 8306070414 Response opposing Friends of the Earth/New York City Audubon Boc request to file I Lovi affidavit Testimony by affidavit improper since no cross-examination possible Certificate of Svc encl
 BRANDENBURG, B Consolidated Edison Co. of New York, Inc.
 COLARULLI, F F Power Authority of the State of New York
 COLARULLI, F, F. Morgan Associates 83/06/03 Atomic Safety and Licensing Board Panel 7pp 18742 264 24X Fiche 50-247,83/06/03.
- 830&070421 Expresses views on plant emergency preparedness in light of nawly submitted state of NY interim plan. Conceptual problems & inaccuracies identified in plan for implementing compensating measures for Rockland County HOLT, J Public Interest Research Group, New York 83/06/03 PALLADING, N J . AHEARNE, J F . G IL INSKY. V Commissioners 4pp 18742 198 24X Fichs 50-247,83/06/03,8306070421
- B306080200 Comments on "Governors Plan" prepared by NY State Disaster Commission Evacuation of wheelchair & bedridden patients & shelter for 1:200 mentally retarded patients overlooked FLEISHER, Z. 8 West Branch Conservation Association B3/06/06 PALLADING, N. GILINBRY, V. AHEARNE, J. F. Commissioners 16pp 18770, 235. 24X Fiche 50-247, B3/06/06, B306080200.
- B3GAO9G359 Responds to Commission B3DB26 meeting questions & updates miscellaneous responses Record justifies continued plant operation Commission would be fully justified in suspending further enforcement action.

 GUNHAY.J.T. Consolidated Edison Co of New York. Inc. BAYNE.J.P., Power Authority of the State of New York 83/O6/O7 FALLADING,N.J., OILINBKY.V., AHEARNE.J.F., Commissioners. 3pp. 18795-036-24X Fiche 50-247-83/O6/O7,8306090359.
- 8306090300 Recommendations for emergency planning process Plans should originate at local govt level & should be supported & enforced at state & federal govt levels * Public Interest Research Group, New York, * Parents Concerned About Indian Point, 83/06/08 2pp, 18795; 239, 24% Fiche: 50-247, 83/06/08, 8306090300.
- 8306070308 Statement on role of federal, state & local govts & utils in planning testing & executing emergency response procedures. HOLT, J. Public Interest Research Group, New York, 83/06/08, 3pp, 18795; ii9 24X Fiche: 50-247, 83/06/08, 8306070308.

- 8306100086 Forwards evaluation of offsite emergency planning, providing factual basis for use in Commission 830609 licensing decision BRA00.J B Federal Emergency Management Agency 83/06/08 PALLADINO.N J Commissioners 45pp 18802:046 24X Fiche 50-247.83/06/08.8306100086
- 8305100207 Memorandum & order denying licensee 830507 motion for reconsideration of ASLB 830427 ruling disallowing admission into evidence of DP McGuire deposition Federal rule inapplicable & no exceptional circumstances shown.

 QLEABON.J P Atomic Sefety and Licensing Board Panel 63/05/08 Consolidated Edison Co of New York, Inc 4pp iB805:202, 24X Fiche: 50-247.83/05/08.8305100209
- 8304i30434 Order ruling I Lavi affidavit, filed by Friends of the Earth & New York City Audubon Soc on 8305i0, inadmissible. Affidavit provides addl substantive testimony & will not be admitted unless witness available for cross-examination GLEASON. J P Atomic Bafety and Licansing Board Panel 83/06/09 Friends of the Earth 2pp 1882i 192 24% Fiche 50-247,83/06/09,8306130434
- 8306170372 Advises that NRC will file comments on Amico final rept Separate comments on interim ltr rept will not be filed MODRE, J E Hearing Branch 1 83/06/09, GLEASON, J, F, SHON, F, J,, PARTS, O H Atomic Safety and Licensing Board Panel 1p 18880; 210, 24% Fiche 50-247, 83/06/09, 8306170372
- 8306170396 Forwards FEMA 83060B ltr to NRC, providing current evaluation of plant offsite emergency planning HABSELL, DF Hearing Branch 2 83/06/09 QLEABON, J. P., BHON, F. J., PARIB, O H Atomic Safety and Licensing Board Panel. 46pp. 18879-333 24X Fichs 50-247, 83/06/09, 8306170396
- 8306150309 Response to ABLB consultant, PJ Amico, 830502 ltr re issues on accident probability requiring addl testimony New York City Audubon Boc/Friends of the Earth comments endorsed Certificate of Byc encl HEISS, E.R. Union of Concerned Scientists, WEISS, E.R. Public Interest Research Group, New York, WEISS, E.R. Harmon & Weiss, 83/06/10 7pp 18847 152. R4X Fiche 50-247, 83/06/10, 8306150389.
- 8306150427 Advises that utils will respond to PJ Amico summary Itr rept & final rept on 830620
 8RANDENBURG, B. Consolidated Edison Co. of New York, Inc COLARULLI, P. F. Horgan Associates. COLARULLI, P. F. Power Authority of the State of New York B3/06/10. GLEABON, J. P., PARIS, D. H., SHON, FJ Atomic Safety and Licensing Board Panel ip, 18847:087.
 24% Fiche 50-247, 83/06/10, 8306150427
- 8306200324 Responds to P Amico 830502 ltr rept re recommendations for add1 testimony on PRA Reopening record on PRA would unduly prolong proceeding HARTZMAN.R M. Friends of the Earth. HARTZMAN.R M. New York City Auduban Society. 83/06/10. GLEASON.J.P., SHON.F J. PARIS.O H. Atomic Safety and Licensing Board Panel 2pp. 18701 018, 24% Fichs 50-247.83/06/10.8306200324
- 8304230376 Response to PJ Amico 830502 ltr to ABLB & analysis of PRA testimony. Areas in which addl testimony recommended do not present issues materially affecting record & are too costly M/Centificate of 8vc.

 BRANDENBURG, B Consolidated Edison Co. of New York, Inc. COLARULLI, P. F. Power Authority of the State of New York. COLARULLI, P. Morgan Associates, 83/06/20 19pp 18943; 258, 24X Fichs. 50-247, 83/06/20, 8304230374
- 8306240270 Response to ASLB consultant P Amico rept re add1 testimony on Commission Guestion 1. No add1 testimony necessary for complete record.

 MODRE, J. MCOURREN, H. J. Hearing Branch 1 83/06/20, 15pp. 18779: 241. 24X Fiche 50-247.83/06/20,8306240290.
- --8306240295 Affidavit of JF Heyer & RM Bernero re ABLB consultant
 P Amico 830601 rept MARCH I i Code used to assess core-melt
 accident progression & containment loading characteristics,
 W/prof qualifications
 MEYER: JF. Reactor Systems Branch BERNERO, R. M. Accident Source
 Term Progrem Diffice. 83/06/17. 12pp. 18979:286
 Fiche: 80-247,83/06/20,8306240290
- --8306240301 Affidavit of QB Varnado re ABLB consultant PJ Amico recommendation to provide expert testimony on risk significance of sabotage. NRC studies & PRA do not estimate risk of sabotage. Prof qualifications encl. VARNADD.Q. B Bandia Laboratories, 83/06/07 App. 18979. 268. 24X Fiche. 50-247, 83/06/20, 8306240290

- --8306240305 Affidavit of HW Woods re ABLB consultant PJ Amico 830601 rept Testimony on conditional probability of core melt & release due to pressurized thermal shock event unavailable M/prof qualifications & Certificate of Svc WOODB: H W. NRC No Detailed Affiliation Given 83/06/16 7sp 18779, 272 24K Fiche 50-247, 83/06/20, 8306240270
- 8306230346 Motion for immediate reconsideration of Commission 830610 Order CLI-83-16 permitting continued plant operation Commission did not consider current status of emergency planning in decision. Certificate of Svc encl HOLT. J. Public Interest Research Group. New York 83/06/22 Commissioners. 12pp. 18942 284. 24X Fiche 50-247,63/06/22, app. 18942 284. 284 Fiche 50-247,63/06/22, app. 18942 284 Fiche 50-247,63/06/2
- 830.6270140 Order granting intervenor 830.621 motion for extension of deadline until 83071; to file proposed findings. Extension applies to all parties Consolidation effort constructive OLEASON, J.P. Atomic Bafety and Licansing Board Panel 83/06/22. Union of Concerned Scientists. 2pp. 19013 360 24X Fiche 80-247,83/06/22,830.6270140
- 830.6270160 Answer opposing intervenor motion for extension of time to subsit proposed findings, Motion is attempt to delay hearings If intervenor motion granted examption should apply to all parties Certificate of Bvc encl.

 BRANDENBURG, B. Consolidated Edison Co of New York, Inc COLARULLI, P. F. Power Authority of the State of New York.

 COLARULLI, P. F. Horgen Associates. 83/06/22 Atomic Safety and Licensing Board Panel. Spp. 18792:037. 24X Fichs 50-247:83/06/22, 8306270160.
- B306270550 Request 2-wk extension to file findings of fact for Commission Gusstions 3 & 4 Atty familiar w/case resigned. MILLER, F. O. Heatchester County, NY B3/06/22 OLEASON, J.P. Atomic Bafety and Licensing Board Panel 1p 19052, 216 24X Fiche 50-247, 03/06/22, 8306270550.
- 830.6270159 Response supporting PIRG of NY motion for reconsideration of Commission 830.609 decision.permitting facility operation \(\nu/\)o restriction daspite continued noncompliance \(\nu/\)emergency planning requirements. Certificate of Svc encl.

 HEIRS, E. R. Union of Concerned Scrientists 83/06/23,
 Commissioners 6pp. 18992:043 24X Fiche 50-247,83/06/23,
 8306270159
- 8306270267 Memorandum advising that ABLB will not reopen record to receive further testimony on Commission Question 1 ABLB consultant PJ Amico recommended add1 testimony immoterial & covers topic sufficiently addressed or is unavailable.

 9LEASON.J P. Atomic Bafety and Licensing Board Panel 83/04/24
 2pp 18990:202 24X Fiche:50-247,83/04/24,8304270267

H General correspondence

- 8306080191 Opposes facility shutdown. FRENCH.JF. Affiliation Unknown 83/06/02. PALLADING.N J Commissioners 1p. 18770:234. 24X Fiche: 50-247.83/06/02. 8306080191
- B306200098 Requests NRC 830609 determination re facility GLs be reversed, per enc? Rockland County Resolution 302. Request based on inability of FEMA to assure that public health & safety can be protected within 10-mile zone W/o stated ench. THORREON E D., SCHOENBERGER/I Rockland County, NY. 83/06/13. Office of Nuclear Resolution Director 19. 18903 336 24X Fiche: 50-247,83/06/13,8306200098

I. Financial information

- 8306:30111 "Annual Financial Rept 1982." W/B30607 ltr. DYBON.J.B., BAYNE.J.P. Power Authority of the State of New York B3/06/07. Office of Nuclear Reactor Regulation. Director. 41pp. 18827.224 24% Fiche: 80-000.83/06/07.8306130111
- P. Operating license stage documents & correspondence
- 830&140598 "Relped Safety Evaluation, Indian Point Nuclear Plant Unit 3, Cycle 4 " M/830&09 ltr.

 8KARITKA.J, ARLQTII.M.Q., BAYNE.J P. Power Authority of the State of New York. 82/02/28, 34pp. 18633:141, 24X Fiche.50-286, 82/02/28.830&140598.
- 830A030224 Notifies that util name changed from Power Authority of State of NY to New York Power Authority New name does not reflect change in status, but clarifies public identity.

 84YNE, J.P. Power Authority of the State of New York. 83/05/27.

 DENTON: H.R. Office of Nuclear Reactor Regulation. Director. 2pp. 18703: 332. 24X Fichs. 80-000.83/05/27.8306030224.

- 8306150627 Forwards Amend 47 to istense DPR-64, safety evaluation, EIA & notice of issuance & availability Amends modify license to reflect repairs & mods to steam generator tubes & girth welds

 VARQA, B A Operating Reactors Branch J B3/05/27 BAYNE, J P
 Power Authority of the State of New York App 18867 288 24%

 Fiche 50-286,83/05/27,8304150427
- --8306150630 Amend 47 to License DPR-64, modifying license to reflect repairs & mods to steam generator tubes & girth welds VARGA.8 A Operating Reactors Branch 1 83/05/27 13pp 18867 292 24X Fiche 50-286,63/05/27,8306150627
- --8306150634 Bafety evaluation supporting Amend 47 to License DPR-64, * Office of Nuclear Reactor Regulation, Director 83/04/27 22pp 19867 305 24X Fiche 50-286.83/05/27.8306150627
- --8306150637 EIA suppor*ing Amend 47 to License DPR-64 * Office of Nuclear Reactor Regulation, Director 83/05/27 10pp 18867 327 24% Fiche 50-286.83/05/27.8306150627
- --8306150638 Notice of issuance & availability of Amend 47 to License DPR-64 VARGA, S A Decrating Reactors Branch 1 63/05/27 6pp 18867 337 84X Fiche 50-286,63/05/27,8306150627
- 8306070185 Forwards application to amend License DPR-64 to conform requirements of GL-82-16 concerning NUREG-0797 Tech Epecs BAYNE.J P. Power Authority of the State of New York B3/06/01 EISENHUY.D 0 Division of Licensing Epp 18736 304 24X Fiche 50-286,83/06/01.8306070185
- --8305070197 Application to amend License DPR-64 changing Tech Specs in accordance w/requirements of Generic Ltr 82-16 re NUREG-0737 items BAYNE, J.P. Power Authority of the State of New York 83/06/01 12pp 18736 306 24% Fiche. 50-286, 83/06/01, 8306070185
- 8304080034 Forwards 30-day response to 821230 ltr & 830428 clarification of SER for environ qualification of safety-related electrical equipment. NRC Category II B & IV equipment not in use at facility BAYNE, J P Power Authority of the State of New York 83/06/01 VARGA, B A Operating Reactors Branch 1 55pp 18773 090 24X Fiche 50-286.83/06/01,8304080034
- 8306200211 Summary of 830408 meeting w/util in Bathesda, MD re steam generator girth weld & secondary water chemistry List of attenders & viewgraphs describing girth weld repair effort encl
 NEIOHBORB, D Operating Reactors Branch 1, 83/06/02, Operating Reactors Branch 1 19pp 18909 218 24X Fiche 50-286, 83/06/02, 8306200211
- 8304090302 Forwards application for amend to License DPR-64, changing Tech Specs re fire protection mods, in response to SA Varga 830421 ltr Procedures re alternate electrical feed sys operation will be at site prior to startup BAYNE, J.P. Power Authority of the State of New York 83/06/03 VAR96.8 A Operating Reactors Branch 1 2pp 18795-242 24X Fiche 50-286, 83/06/03, 8306090302
- --8306090304 Application to amend Liconse DPR-64 changing Tech Spec Sections 3 3.3 14 & 4 12 ro fire protection mode, in response to 84 Varga 830421 Itr BAYNE, J P Power Authority of the State of New York 83/06/03 ip 18795 244. 24% Fiche 50-286,83/06/03,8306090302
- --8306090307 Proposed Tech Specs re fire protection mods * Power Authority of the State of New York 83/06/30 lipp 18795: 245 24% Fiche 50~286, 83/06/03, 8306090302.
- B306100113 Forwards add1 info re time frame for providing access to hydrogen recombiner panel area per B30215 commitment to NVREQ-0737. Item II B. 2. "Plant Bhielding." Hydrogen recombiner panel access time of 5 days appropriate.
 BAYNE, J. P. Fower Authority of the State of New York, B3/06/03 EISENHUT, D Q. Division of Licensing 5pp 18802 018 24X Fiche 50-286, B3/06/03, B306100113
- 8306100253 Forwards draft std radiological effluent Tech Epecs, for technical review & comments Formal amend application will be submitted by 830930
 BAYNE, J.P. Power Authority of the State of New York 83/06/06 VARGA, S.A. Openating Reactors Branch 1 ip 18807.065 24X Fichs: 50-286, 83/06/06, 8306100253
- --8306100256 Draft std radiological effluent Tech Specs.

 * Power Authority of the State of New York 83/04/30 60pp.
 18807.066. 24X Fiche 50-286.83/06/06.8306100253

- B306140277 Informs that analysis of inlet & discharge piping for relief & safety valves refined to reflect more realistic conditions, per B30215 Itr & TMI Action Item II D I Listed aptions will be considered if overstress condition revealed BAYNE.J P Power Authority of the State of New York B3/06/08 VAROA.S A Operating Reactors Branch I 2pp 18832 225 24X Fiche 50-286,83/06/08,83061402/7
- 8306160450 Forwards results of stram generator tube insp & tube repair programs implemented during 1982/83 maint & refueling outage, per 821018 submittal Info satisfies Tech Spec 4 9 2 requirements

 BAYNE,J P Power Authority of the State of New York 83/06/10 VARQA, B A Operating Reactors Branch 1 34pp 18864 049 24% Fiche 50-286,83/06/10.8306160450
- 8306170249 Advises that schedule for unavailability analysis of ATHS mitigating sys actuation circuitry sys will be submitted after final designs & equipment selection completion, in accordance w/schedule requirements of ATHS final rule BAYNE, J.P. Power Authority of the State of New York 83/06/13 VARGA. 8 Depetating Reactors Branch P. 2pp. 18078-274 24X Fiche 50-286,83/06/13,8306170249
- 8306200401 Forwards Rev 1 to "Reload Bafrty Evaluation. Indian Point Nuclear Plant Unit 3.Cycle 4 " Proposed Tech Spec changes reflecting steam generator equivalent tube plugging level of 24% submitted via util 830505 ltr
 BAYNE.J P Power Authority of the State of New York 83/06/15 VAROA.8 A Operating Reactors Branch 1 2pp 18899 016 24% Fiche 50-286,83/06/15.8306200401
- --8306200402 Rev 1 to "Reload Safety Evaluation, Indian Point Nuclear Plant Unit 3, Cycle 4" EKARITKALJ, ARLOTTI.M G Westinghouse Electric Corp 02/03/31 16pp 18899 018 24X Fiche 50-286.8'1/06/15.8306200401
- 8306210144 Suppls 821012 & 830510 responses to NUREQ-0737. Item 11 B 3, "Post-Accident Bampling Sys "Commitment to Criterian 7(b) re background radiation levels fulfills item requirement BAYNELJ P Power Authority of the State of New York 83/06/1/ EISENHUT.D G Division of Licensing 4pp 18914 092 24X Fiche 50-286.83/06/17.8306210144
- 8306210178 Forwards "Offsite Dose Calculation Manual," for 830606 radiological effluent Tech Specs
 PAYNC, J.P. Power Authority of the State of New York 83/06/17
 VARQA, 8 A Operating Reactors Branch J. Jp. 18918 257 24X
 Fiche 50-286,83/06/17.8306210170
- --B306210188 "Offsite Dose Calculation Manual "
 * Power Authority of the State of New York 83/06/30 93pp
 16918 258 24X Fiche 50-286.83/06/17.8306210178
- B306240413 INVESTIGATION OF THE SHELL CRACKING ON THE STEAM GENERATORS OF INDIAN POINT NO 3 Docket No 50-286 (Consolidated Edison Company)
 CZAJIKOWSKI, C Brookhaven National Laboratory FIN A-3400
 NUREO/CR-3281 B3/06/30 Division of Engineering 51pp
 Available at NRC \$4 00 18998 273 24X Fiche 50-286,83/06/30,8306240413
- O Inspection reports: IE Bulletins & correspondence
- 830&030343 Ack receipt of 830128 ltr in response to NRC 821104 ltr re
 IE Insp Rept 50-286/82-09 Effective coverage by radial-type
 nowile not addressed in safety evaluation Addl info
 requested 83028 not received
 MARTIN.T T Division of Engineering & Technical Programs 83/05/29,
 BRONS, J C Power Authority of the State of New York 2pp
 18705 012 24X Fiche 50-286, 83/05/29, 8306030343
- --8306030345 Forwards add1 info re installation of radial pattern sprinkler noizles in lieu of previously committed closed head, horizontal side-wall type, per II Insp Rept 50-286/82-09
 BRONS, J C Power Authority of the State of New York 83/01/28 MARTIN, T Division of Engineering & Technical Programs 5pp 18705 014 24% Fiche 50-286, 83/05/28, 8306030343
- B306060264 Forwards IE Insp Rept 50~286/83~08 on B30412~15 No noncompliance noted Corrective artions re violations noted in B30117 & 0217 ltrs verified MARTIN.T T Division of Engineering & Technical Programs B30/05/23 B80NS, J C Power Authority of the Btate of New York 2pp 18727 026 24X Fiche 50~286, B3/05/23, B306060264
- --8306060267 IE Insp Rept 50-286/83-08 on 830412-15 No noncompliance noted Major areas inspected status of previously identified items; package selection; procedures; training, audits; transuranic determinations & girth weld ALARA consideration CLEMONS, P. MCBRIDE, M. SHANDAKY, M. Region 1. Office of Director 83/05/20 5pp 18727 0P0 24X Fichs 50-286,83/09/23,8306080264

- 8306070046 Forwards IE Insp Rept 50-206/83-11 on 830416-0515 No noncompliance noted

 83705/24.

 83705/24.

 83705/24.

 83705/24.

 83705/24.

 83705/24.

 83705/24.
- --8306070092 IE Insp Rept 50-286/83-ii on B30416-0515 No noncompliance noted Major areas inspected shift logs.plant bour, surveyillance, maintreview of monthly operating rept & damage to chemical & vol control sys holdup tank KENNY,T J. ROBBBACH,L W. KIBTER, H. Region I. Office of Director. B3/05/19 9pp 18740-070 24X Fichs 50-286-83/05/24,8306070046.
- 8305110458 IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in Well Logging Device" Svc list and TAYLOR, J M Division of Safeguards & Inspection Programs (Post B30103) B3/05/26 Consolidated Edison Co of New York, Inc 125p 18831 043 24X Fiche 80-000,03/05/26,8305110458
- B305110460 IE Info Notice 83-34, "Event Notification Info Worksheet."
 Byo list encl
 JORDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/05/26 Consolidated Edison Co of New
 York, Inc. 118pp 18732 085. 24X Fiche 50-000,83/05/26,8305110460
- 8305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods Withdrawn at BMRs " Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/31. Consolidated Edison Co. of New York, Inc. 116pp 18732 208 24X Fiche 50-000.83/05/31,8305110461.
- 8306210068 Responds to IE Bulletin 83-03, "Check Valve Failures in Raw Water Cooling Bys of Diesel Generators " No check valves in piping boundary at facility BRONS, J C Power Authority of the State of New York 83/06/07, ALLAN, J M Region i, Office of Director ip 18912 361 24X Fiche 50-286,83/06/07,8306210068
- 8305110464 IE Info Notice 83-36, "Impact of Security Prectices on Safe Operations" Syc list encl.

 JORDANIE L Division of Emergency Preparedness & Engineering Response (Post 830103) 83706/07 Consolidated Edison Co. of New York. Inc. 119p 18830 280. 24X Fiche 50-000,83/06/09,8305110464.
- 8306160450 Forwards results of steam generator tube insp & tube repair programs implemented during 1982/83 maint & refueling outage, per 821018 submittel Info satisfies Tech Bpec 4 9 2 requirements

 84YNG, J P Power Authority of the State of New York, 83/06/10 VARQA, 8 A Operating Reactors Branch J 34pp 18864-049 24X Fishe 50-286,83/06/10,8306160450
- 8305110470 IE Info Notice 83-38, "Defective Heat Sink Adhesive & Beismically Induced Chatter in Relays Within Printed Circuit Cards" Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83706/13 Consolidated Edison Co. of New York, Inc. 118pp 18720 225. 24X Fiche 50-000,83/06/13,8305110470.
- 8304090010 JE Info Notice 83-37, "Transformer Failure Resulting From Degraded Internal Connection Cables," Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co. of New York, Inc 243pp 18921 001 24X Fiche 50-000,83/06/13,8306090010.
- 8305110475 IE Info Notice 83-40, "Need to Environmentally Gualify
 Epoxy Groute & Sealers " Svc list ent!
 JORDAN,E L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83706/22 Consolidated Edison Co. of New
 York, Inc. 115pp 19021 179. 24X Fiche. 50-000.83/06/22.8305110475.
- 8305110477 IE Info Notice 83-41, "Actuation of Fire Buppression Bys Causing Inoperability of Bafety-Related Equipment " Svc list encl JORDAN, E. L. Division of Emergency Preparadness & Engineering Response (Past 830103) 83/04/22 Consolidated Edison Co. of New York, Inc. 120pp. 18997 007. R4X Fiche 50-000,83/04/22,8305110477.
- 8305110479 IE Info Notice 83-42, "Reartor Mode Switch Malfunctions."

 Byo list encl
 JORDAN.E L. Division of Emergency Preparedness & Engineering
 Response (Past 830103) 83706/23 Consolidated Edison Co. of New
 York, Inc. 116pp 18996 242 24X Ficha 50-000,83706/23,8305110479.
- 8305110483 IE Info Notice 83-43, "Improper Settings of Intermediate Renge (IR) High Flux Trip Setpoints " Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/24. Consolidated Edison Co of New York, Inc 116pp 19046 297 24X Fichs 30-000,83/06/24.8305110483.

R Periodic operating reports & related correspondence

8306160385 Monthly operating rept for Apr 1983 M/830509 ltr KELLY.L., BRONS.J C. Fower Authority of the State of New York 83/05/01 Office of Resource Management, Director 7pp 18860 067. 24X Fiche 50~286.83/05/01.8306160385

8 Reportable occurrences. LERs & related correspondence

- 830&010346 LER 83-001/03L-0 on 830422, during processing of water from chemical & vol control sys holdup tank 33 to waste sys, partial deformation of tank accurred due to low pressure. Caused by vacuum due to closed vent W/830513 ltr GUMBLE.F. W. BRONEJ J C Power Authority of the State of New York 83705713. ALLAN.J M. Region 1. Office of Director 3pp 18680 076 24X Fiche 50-286.83/05/13.8306010346
- 8306020450 LER 83-002/03L-D on 830512, during refueling outage, small lask identified on RHR miniflow line at weld joint between valve 1870 & line 337 Cause not stated Lask isolated, section of pipe repaired & downstream reducer replaced W/830524 ltr OUMBLE,F.W. BRONG, J C Power Authority of the State of New York 82/05/24 ALLAN, J M Region 1, Office of Director 3pp 18674-008 24X Fiche 50-286,83/05/24,8306020450
- 8306140690 PND-I-83-059 on 83060B, several trips experienced during startup Caused by feedwater flow inconsistency w/steam generator level demand Secondary boron soak performed KENNY.T. COLLINS.S. Region J. Office of Director. 83/08/09 ip. 18841 343 24X Fiche 50-286.83/06/09.8306140690
- 8306230002 PNC-I-B3-064 on B30618, electrical generator/turbine trip caused reactor to trip Investigation revealed fault originated within main generator End turns on some windings malted & portions of internals covered w/carbon GREENMAN.E 0, Region 1, Office of Director 83/06/20 Ip 18947-078 24X Fichs 50-286.83/06/20.8306230002

T Hearing transcripts on non-antitrust matters

- 8304020709 Transcript of Commission 830526 meeting in Washington, DC. To emergency planning & preparadness Pp 1-117 Supporting documentation encl # Commissioners 83/05/26 236pp. 18718 001 24X Fiche, 50-247, 83/05/26, 8304020709
- 8306090347 Statement before House of Representatives Subcommittee on Energy Conservation & Power re emergency planning Public must be involved in planning & testing process # Perents Concerned About Indian Point 83/06/08 4pp 18794-336 24X Fiche 50-247,83/06/08,8306090347
- 8304090350 Testimony of J Holt, K Toscani & P Posner before House of Representatives Subcommittee on Energy Conservation & Power re public role in planning, testing & implementing emergency response procedures

 HOLT, J. Public Interest Research Group, New York TOSCANI, K, POSNER, P Parents Concerned About Indian Point 83/06/08 24pp 18794:340, 24X Fichs 50-247,83/06/08.0306090330.
- B306150500 Transcript of B30609 Commission discussion & vate on smergency planning deficiencies at Indian Point in Washington, BC Pp 1-24
 Commissioners. B3/06/09 30pp 18868 249 24X Fiche. 50-247,83/06/09.8306150500
- 8306200342 Forwards corrections to special proceeding transcripts BRANDENBURG, B Power Authority of the State of New York COLARULLI, P F Consolidated Edison Co of New York, Inc. COLARULLI, P F Horgan Associates 83/06/15 OLEABON, J. P. PARIS, O H. SHON, F. J. Atomic Safety and Licensing Board Panel. ip. 18900 211. 24X Fiche 50-247,83/06/15,8306200342
- --030A200346 Corrections to special proceeding transcripts

 # Power Authority of the State of New York. * Consolidated
 Edison Co of New York Inc. 83/06/15 52pp 18900.212 24X
 Fiche 50-247.83/06/15.8306200342
- B30624001B Transcript of Commission B30617 briefing on Indian Point Labor issues in Washington.DC Pp 1-44, + Commissioners B3706/17, 47pp 16987,293 24x Fiche: 50-247,83/06/17,830624001B

U Congressional/Executive Correspondence

- 8306030156 Responds to 830506 request for clarification of 830505 order re consideration of views of public & parties to operial proceeding in 830609 decision Comments from licensees, govt agencies & public invited PACLADENO.N J Commissioners 83/05/12 OTTINGLR.R L House of Rep. Energy & Commerce 2pp 18733 326 24X Fiche 50-247, 83/05/12.8306030156
- --8306030158 Requests Commission 830505 order be revised to stress need for parties to safety investigation views on shutdown Rev requested by 830511
 OTTINGER,R L. House of Rep., Energy & Commerce 83/05/06
 PALLADINO,N Commissioners 2pp 10/33 328 24X
 Fithe 50-247,03/05/12,8306030156

V Operator Examinations

8306140291 Extends invitation to attend 830627 meeting in King of Prussia:PA to discuss transfer of reactor operator licensing function from Bethesda:MD to Region I ofc
STAROBTECKI,R Division of Project & Resident Programs 83/06/09
BRONS,J C Power Authority of the State of New York 2pp
18832 217 24X Fiche 50-286.83/06/09.8306140291

DOCKET 50-287 OCONEE NUCLEAR STATION, UNIT 3

F. Security, medical, emergency & fire protection plans

- 8306090361 Forwards request for exemption from emergency operations facility (EOF) location requirements per Generic Ltr 82-33 Propose EOF to be located 125 air miles from facility, w/ joint news ctr remaining in Oconee. NC TUCKER, H B Duke Power Co 83/06/03 DENTON, H R Office of Nuclear Reactor Regulation. Director STULZ, J F Operating Reactors Branch 4 20pp 18775 037 247 Fiche 50-269,83/06/03,8306090361
- 8306170285 Forwards IE Bafeguards Imap Repts 50-269/83-14 50-270/83-14 & 50-287/83-14 on 830509-13 No noncompliance noted BANCE H C Division of Project & Resident Programs 83/06/13 TUCKER H B Duke Power Co 2pp 18877 233 24X Fichs 50-269.83/06/15.8306170285
- --8304170307 IE Bafeguards Inep Repts 50-269/83-14, 50-270/83-14 to 50-287/83-14 on 630509-13 No moncompliance noted Major areas inspected sacurity plan t implementing procedures to security organization mgt Safeguards info deleted (ref 10CFR/3 21) TILLMAN.A Region 2. Office of Director 63/06/15 2pp 18877 235 24x Fiche 50-269, 63/06/15, 6306170265
- B30684003B Advises that preliminary fee review of 830603 request for exemption from location requirements of emergency operations facility determined that Class III appropriate DIGGER M License Fee Management Branch 83/06/15 TUCKLR, H B Duke Fower Co Ip 18987 229 24X Fiche 50-269.03/06/15, B306240038

P Operating license stage documents & correspondence

- 8306060051 Addl response to fOlA request for three categories of documents re PRA of reactor safety study methodology application program repts & interim reliability evaluation program repts forwards App A documents Search continuing FELTON, J M Division of Rules and Records 83/04/07 SHOLLY, B C Union of Concerned Scientists 3pp 10752 001 24X Fiche 50-000,83/04/07,8306060051
- --B10921031B Responds to &10820 memo re transmittal of NUREG/CR-1659, Vol 2. to licenses for comments Util comments on rept already requested DERNERG.R M Division of Risk Analysis 81/08/20 NOVAK, T M Assistant Directur for Operating Reactors 2pp 18732 018 24X Fiche 90-000.83/04/07,8306026081
- --B3060600B0 Forwards background info re PRA studies Review of Sandia Natl Lebs interim reliability evaluation program studies discussed H/o entl BYOLZ, J Operating Reactors Branch 4 B3/01/19 LAINAB, C C Assistant Director for Operating Reactors 2pp 18752 200 24X Fiche 50-000,83/04/07,8306060051
- --8306060085 Provides info on boron precipitation clagging HP1 lines & failure of operator to switch to hot leg injection in order to flush out boron residue from core during recirculation info obtained from PRAs

 DAVIB.8 NRC No Detailed Affiliation Given 83/02/24

 THADANIA NRC NO Detailed Affiliation Given 4pp 18752 206

 24X Fiche 50-000,83/04/07,8306060051

- 8304020103 Proposes 830608 meeting in Bethesda.MD to discuss Suppl 6 to SER for McGuire & SER for standby shutdown facility for Oconee STOLZ.J F Operating Reactors Branch 4 83/05/17 TUCKER.H B
 - STOLZ, J F Operating Reactors Branch 4 83/05/17 TUCKER, H B Dute Power Co 1p 18701 277 24X Fichs 50-000,83/05/17, 8306020103
- 8306150504 Forwards request for addl info re 830310 proposed amend to License DPR-55 & proposed rev to Tech Spec on expansion of storage capacity of spent fuel pool Info requested within 30 days of ltr receipt
 STOLZ, J F Operating Reactors Branch 4 83/05/23 TUCKER, H B Duke Power Co 3pp 18854 356 24X Fiche 50-287,83/05/23,8306150504
- 8306070051 Forwards summary of 830512 meeting w/util & D&W, in response to 830327 request for additinfore reactor vessel survestilance capsule dosimetry results contained in BAW-1697 to 1697
 TUCKER, H B Duke Power Co. 83/05/27 DENTON, H R DPfice of Nuclear Reactor Regulation, Director STOL2, J F Operating Reactors Branch 4 4pp 18740 059 24X Fiche 50-269,83/05/27,8306070051
- 9306030122 Forwards add1 info to aid in completion of review re NUREO-0737. Items II F 1 4. II F 1 5 & II F 1 6. per 830110 ltr request & justification concerning Item II F 1 5 Amend to 830318 confirmatory order requested
 TUCKER: H D Duke Power Co 83/05/31 DENTON, H R Office of Nuclear Reactor Regulation, Director 8TOLZ, J F Operating Reactors Branch 4 15pp 18704 302 24X Fiche 50-269, 83/05/31. 8306030122
- 8306070272 Forwards BAM-1784, "BBM Dwners Oroup Bolting Task Force Summary Rept of NRC/BBM Dwners Oroup 830506 Meeting on Reactor Vessel Internals Bolting " Agrees w/overall findings.w/exception re neutron noise sulveillance TUCKER; H B Duke Power Co 83/05/31 DENTON; H R Office of Nuclear Reactor Regulation, Director STOL7, JF Operating Reactors Branch 4 2pp 18744 086 24% Fiche 50-269,83/05/31,8306070272
- --B306070280 Forwards HAM-1784. "B&W Owners Group Bolting Task Force Summary Rept of NRC/B&W Owners Oroup D30506 Meeting on Reactor Vessel Internals Bolting "TAYLOR, JH Babcock & Wilcox Operating Plants Owners Group TAYLOR, JH Babcock & Wilcox Co D3/05/20 MINER, S NRC No Detailed Apriliation Given in 19 18744 OBB 24x Fiche 50-269,83/05/31,8306070272
- --8306070286 "B&W Currers Group Bolting Task Force Summary Rept of NRC/B&W Currers Group 830506 Meeting on Reactor Vessel Internals Bolting "

 # Babcock & Wilcox Co BAW-1784 83/05/31 124pp 18744 089 24X Fiche 50-249, 83/05/31, 8306070272
- 8304080375 Forwards review of "Reactor Safety Study Methodology Applications Program Ocones 3 FWR Power Flant (NURES/CR-1455,2 of 4) " Review identified dominant core melt sequences & required licensing actions.

 870LZ.J F Operating Reactors Branch 4 83/06/01, TUCKER.H B. Duks Power Co 14pp 18787 277 24X Fiche 50-287,83/06/01,8304080375
- 8304200185 Summary of 830512 meeting w/util & B&W in Bethesda, MD renewtron dosinetry & uppershalf matl properties provided in Topical Repts BAW-1697 & BAW-1699 List of attendees, agenda & viewgraphs encl
 8UERMANN, J F Operating Reactors Branch 4 83/06/06 Operating Reactors Branch 4 35pp 18909, 183 24X Fiche 50-269, 83/06/06, 8306200185
- 8306220275 Informs that 830310 proposed wide-range hot leg level/
 reactor vessel head monitoring satisfactory Evaluation &
 addl info raquest re conformance of addl inadaquate core
 cooling instrumentation sys components to NUREO-0737, encl
 8TOLZ, JF Operating Reactors Branch 4 83706708, TUCKER, H B,
 Duke Power Co 10pp 18977 155 24X Fiche 50-269,83706708,
 8306220275
- B306300174 Forwards responses to 830523 request for add1 info re spent fuel pool Info suppls 830310 ltr TUCKER, H B Duke Power Co. 83/06/24. DENTON, H R Diffice of Nuclear Reactor Regulation, Director STDL7, J. F. Operating Reactors Branch 4 9pp 19122 047 24X Fiche, 50-287, 83/06/24, 8306300174
- G Inspection reports, IE Bulletins & correspondence
- 8305080402 Confirms 830513 telcon re proposed site/corporate visit on 830525-27 to review masonry wall const.drawings & calculations re review of IE Bulletin 80-11 response Agenda and!

 STOLZ, J. F. Operating Reactors Branch 4 83/05/20, TUCKER, H. B. Duke Power Co. 4pp. 18789:342 24X Fiche 50-267,83/05/20, 8306080402

- 8305110458 IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in Well Logging Devace " Svr list encl TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc. 125pp 18831 043 24X Fiche 50-000, 83/05/26, 8305110458.
- 8305110460 IE Info Notice 83-34, "Event Notification Info Worksheet "
 Svc list encl
 JORDAN,E L Division of Emergency Preparedness & Engineering
 Response (Pout 830103) 83/05/26 Consolidated Edison Co of New
 York, Inc 115pp 18732 085 24X Fiche 50-000,83/05/26,8305110460
- 8306010310 EN-83-038 notice of violation & proposed imposition of civil penalties in amount of \$180.000 to be issued on 830602 Action based on three Severity Level III violations refailure to maintain primary containment integrity BARBER. 0 . AXELRAD, J Director's Office. Office of Inspection and Enforcement 83/08/27 ip 18672 317 24X Fiche 50-249,83/05/27,8306010310
- 8305i10461 IE Info Notice 83-35, "Fuel Movement W/Control Rods Withdrawn at BWRs " Svc list encl. JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/31 Consolidated Edison Co. of New York, Inc. 116pp 18732 208 24X Fiche 50-000,83/05/31,8305110461
- 8306220171 Discusses IE insp on 830317-28 & forwards notice of violation & proposed imposition of civil penalty O'REILLY, J P Region 2. Office of Director 83/06/02 TUCKER, H. B. Duke Power Co 4pp 18937 281 24X Fichs 50-269, 83/06/02, 8306220171
- --8306220175 Notice of violation & proposed imposition of civil penalty in amount of \$180,000 Noncompliance noted.inadequate procedures to ensure that air lock sys restores to operability after maint O'REILLY, J P Director's Office Office of Inspection and Enforcement 83/06/02 4pp 18937 285, 24X Fiche 50-249,83/06/02,8306220171
- 8306290245 Informs that response to IE Bulletin 83-03, Item 4 refailures of check valves used in diesal generator water cooling sys, will be submitted by 830622 TUCKER. H B Duke Power Co 8306/09 G'REILLY, J P. Region 2, Defice of Director ip 19056 085 24X Fiche. 50-269, 83/06/08, 830620245
- 8305110464 IE Info Notice 83-36. "Impact of Security Practices on Bafe Operations " Syc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83706/09 Consolidated Edison Co of New York, Inc 119pp 18830 280 24X Fiche 50-000,83706/09,8305110464.
- 8305110470 IE Info Notice 83-38, "Defective Heat Sink Adhesive & Seismically Induced Chatter in Relays Within Printed Circuit Cards " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co of New York, Inc 118pp 18920, 225 24X Fiche, 50-000, 83/06/13, 8305110470
- 8306090010 IE Info Notice 83-37, "Transformer Failure Resulting From Degraded Internal Connection Cables" Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103). 83/06/13 Consolidated Edison Co of New York, Inc. 243pp 18921,001 24X Fiche 50-000,83/06/13,8306090010.
- 8306170285 Forwards IE Safeguards Insp Repts 50-269/83-14 50-270/83-14 & 50-287/83-14 on 830509-13 No noncompliance noted DANCE, H C Division of Project & Resident Programs 83/06/15, TUCKER, H B Duke Power Co 2pp 18877-233 24X Fiche 50-269, 83/06/15, 8306170285
- --8306170307 IE Bafeguards Insp Repts 30-269/83-14, 50-270/83-14 & 50-287/83-14 on 830809-13, No noncompliance noted Major areas inspected, security plan & implementing procedures & security organization mgt Bafeguards into deleted (ref 100FR73.21) TILLMAN.A . CNNIB.J. Region 2, Office of Director. MCGUIRE, D.R. Division of Emergency Preparedness & Materials Bafety 83/06/15, 2pp 16877-235, 24X Fither 50-269, 83/06/15, 8306170285
- 8305110475 IE Info Notice 83-40, "Need to Environmentally Qualify
 Epoxy Grouts & Sealers " Syc list and I
 JORDAN,E.L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/06/22 Consolidated Edison Co of New
 York, Inc | 115pp | 19021 179 | 24X Ficha 50-000,83/06/28,8305110475.
- 8305110477 IE Info Notice 83-41, "Actuation of Fire Suppression Sys Causing Inoperatility of Safety-Related Equipment," Svc list encl JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/22 Consolidated Edison Co. of New York, Inc. 120pp 18977.007 24% Fichs 50-000,83/06/22.8305110477.

- 8305110479 IE Info Notice 83-42. "Reactor Mode Switch Malfunctions "
 Svc list encl
 JORDAN, E.L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/06/23 Consolidated Edison Co of New
 York, Inc. 116pp 18996-242 24X Fiche 80-000,83/06/23,8305110479
- 8305110483 IE Info Notice 83-43, "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints " Svc list encl. JORDAN E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/24 Consol
- R Periodic operating reports & related correspondence
- 8306170277 Monthly operating rapts for May 1983 H/830615 ltr REAVIS, J A., TUCKER, H.B. Dute Power Co. 83/06/15 17pp 18878 177 24X Fichs 50-269, 83/06/15, 8306170297
- 8 Reportable occurrences, LERs & related correspondence
- 8306210190 LER 83-006/03L-0 on 830513 during attempt to replace cell in battery 3PB, power lost from emergency feedwater pump turbing auxiliary oil pump duped by personnel failure to follow procedure Personnel counsaled W/830610 ltr. PETTY.J C. TUCKER.H B Duke Power Co 83/06/JO O'REILLY, J P. Region 2. Office of Director. Spp. 18914 119. 24X Fiche 50-287,83/06/10.8306210190
- 830A220007 Part 21 rept re adequacy of fittings supplied by Tubs-Line Corp through Capitol Pipe & Steel Products Co for use on new auxiliary feedwater headers of steam generators. Flanges not heat-treated as required by mall specs.

 TAYLOR. J. H. Babcock & Hilcox Co 83/06/17 DEYOUND. R C Director's Office Office of Insection and Enforcement 4pp iB927-354. 24X Fiche 50-000. B3/06/17.8306220007.
- 8306300015 RD on 830527, certain containment isolation valves may have failed in non-E8 position due to loss of dc power. Investigation & rept will be completed & reviewed by 830708

 TUCKER, H. B. Duke Power Co. 83/06/24 D'REILLY, J P. Region 2, Defice of Director. ip. 19168 128, 24% Fiche. 50-287, 83/06/24, 830630015
- DOCKET 50-289 THREE MILE ISLAND NUCLEAR STATION, UNIT 1 F. Security, medical, emergency & fire protection plans
- 8304240319 Ack receipt of 830504 ltr re emergency into brochures, Util proposes to effect distribution primarily by direct mail to agricultural community within plume exposure pathway emergency planning zone.

 ROGANJR. E. General Public Utilities QPU Service Corp 83/05/31, HALLOHELL.P. Pennsylvania, Commonwealth of, 1p. 18980, 153 24X Fiche: 30-289, 83/05/31, 8306240319.
- 8306090268 Releases public version of revised emergency plan FELTON.J M. Division of Rules and Records. 83/06/01 Document Management Branch, 1p. 18798: 259. 24% Fiche: 50-289, 63/06/01, 8306090268.
- --8306090271 Public version of Rev 4 to emergency plan Receipt form enc1 CLARK, P. R. General Public Utilities - GPU Service Corp 83/04/21, 301pp. 18798.260 24% Fiche, 50-289, 83/04/01, 8306090268
- 8306100120 Forwards Rev 17 to security plan. Rev withheld (ref 10CFR73 21) Rev completes replacement of existing plan except for exhibits following Exhibit 1 2 TMI-2 addendum should be retained.

 HUKICLI H D. General Public Utilities GPU Bervice Corp. 83/06/03 DENTON, H. R. 0ffice of Nuclear Reactor Regulation. Director. 1802.030. 24X Fichs 50-289, 83/06/03.8306100120
- 8306220293 Releases public version of revised emergency plan implementing procedure. FLITON, J. Division of Rules and Records. 83/06/06. Document Management Brench. ip 18940-315 24X Fiche 50-289, 83/06/06, 8306820293
- --8306220298 Public version of Rev 6 to Emergency Plan Implementing Procedure 1004, 31: "Airborne Radioactivity Sampling & Analysis." Receipt form encl. BRADY.J. A General Public Utilities GPU Service Corp. 63/05/24 28pp. 18940:316. 24X Fiche: 50-289, 63/06/06, 8306220293.

- 8306150025 Releases public varsion of revised administrative procedures & revised emergency plan implementing procedure FELIDM. J M Division of Rules and Records 83/06/07 Document Management Branch 1p 18872 004 24% Fiche 50-289,83/06/07,8306150025
- --8306150030 Public version of revised Administrative Procedures 1053 re emergency equipment readiness & 1055 re maintaining emergency preparedness & revised Emergency Plan Implementing Procedure 1004 33 re reactor coolant NELSON,M A , TOOLE.R General Public Utilities -- OPU Service Corp 83/08/02 43pp 18872 005 24X Fiche 50-289,83/06/07, 8306150025
- 8306140732 Forwards Rev O to "fire Protection Mods to TM1 Unit 1 (Since Browns Ferry Incident)"
 HUKILL H D general Public Utilities - GPU Service Corp 83/06/09 EISENHUTID G Division of Licensing 3pp 18840 210 24X Fiche 50-289, 83/06/09, 8306140732
- --B306140737 Rev 0 to "Fire Protection Mods to TMI Unit I (Since Browns Ferry Incident) " W/one oversize thank Aperture card is available in PDR HAFER, D I , BOUTROBS F 0 , BRANNEN, W A Gilbert/Commonwealth Cos 2468 R00 83/06/01. 155pp 18840 213 24% Ficho 50-289, 83/06/09.8306140732
- 8306170204 Ack receipt of operational GA plan for TMI-1 & Gyster Creek under review by GA Branch, per 10CFRBO 54 Future reve/changes to program will be reviewed by Engineering Programs Branch, Region I

 MARTIN, T T

 HURTILL, H D

 General Public Utilities GPU Bervice Corp

 18882, 304

 24X Fiche 50-000, 83/06/13, 8306170204
- O Adjudicatory correspondence
- 8305010351 Comments on 830524 Commission meeting & on IE Insp Rept 50-289/83-10 Continued ref to Hartman allegations clouded purpose & results of revalsdation effort Bafe operation assured DIECKAMP, H. General Public Utilities - GPU Service Corp. 83/05/27 PALLADIND.N J. Commissioners App. 18682 141 24X Fiche: 50-289, 83/05/27, 8306010351
- 830.6010454 Forwards H Dieckamp comments on II Insp Rept 50-289/83-10 & related Commission 830524 meeting Certificate of Svc encl W/o comments
 BLAKE, E. Bhaw, Pittman, Potta & Trowbridge BLAKE, E. Hatropolitan Edison Co 83/05/31 CHILK, 8 J Office of the Secretary of the Commission 4pp 18674 318 24X
 Fichs 50-289,83/05/31.8306010454
- 8304020441 Order extending time until 830624 for Commission to act to review ALAB-724 CHILK.S.J Office of the Secretary of the Commission 83/05/31 Commissioners ip 18693 240 24X Fiche 80-289,83/05/31,8306020441
- 8304040190 Motion for extension of time to file comments re IC Insp Rept 50-289/83-10 in response to 830523 order AAMODT,M M Asmodts. The 83/05/31 Commissioners lp 18728-280 24X Fiche 50-289,83/05/31,8306060190
- 8304070420 Comments on IE Insp Rept 50-287/83-10 & Commission 830524 briefing Insp rept does not address issue of mgt integrity Significant number of TMI-1 & GPU mgt personnel could have been involved in events surrounding Hartman allegations AAMODT, N D . AAMODT, M M Aamodts. The 83/05/31 42pp 18742 202 24X Fiche: 50-289, 83/05/31,8306070420
- 8306090339 Requests NRC documents re Hartman allegations & memoranda on whether NRC attys or senior staff aware of I Martin views re-record falsification & whether Martin views reported to ABLB or Commission
 OILINBKY, V Commissioners 83/05/31. DIRCKB, W J Office of the Executive Director for Operations 2pp 18795:110 24X Fiche: 50-289,83/05/31. 8306090399
- 8304020355 Advises of inability to meet 830400 deadline for commenting on BRW trial record. Physical exhaustion will not be risked & substandard work based on sloppy research will not be submitted to meet arbitrary deadline W/Certificate of Svc DDROBHON. J. Three Mile Island Alert. 83/04/01 PALLADING.N J. GLINBKY.V . AHEARNE. J. F. Commissioners 4pp 18694 258 24X Fiche 50-289, 83/04/01, 8304020355

- 8306030329 Requests available evidence & conclusions re falsification of TMI-2 records per H Hartman Mor 1980 allegations Info should include NRC analyses & repts.mgt review records & specific citations supporting NRC statement BLAKE.E L Shaw Pittman. Potts & frowbridge 83/06/01 PLAINE.H H Office of the General Counsel 3pp 18708-350 24X Fiche 50-289.83/06/01.8306030379
- 8306070271 Forwards PA Governor Thornburgh 830602 It: & supplemental comments on immediate effectiveness of partial initial decisions re mpt issues Filings constitute Commonwealth of PA comments on Commission 830524 meeting ADLER, R W Pennsylvania, Commonwealth of, 83/06/02 CHILK, S J Office of the Secretary of the Commission ip 18742 130 24x Fiche 50-289,83/06/02.8306070271
- --8306070277 Urges postponement of restall decision until issues re aperator cheating TMI-2 cleanup & operator compotence & integrity resolved THORNBURGH.D Pennsylvania, Communutalth of, 83/06/02 PALLADIND.N J Commissioners 2pp 18742 131 24% Ficke 50-289,83/06/02.83060/02/1
- --8306070407 Supplemental comments on immediate effectiveness of partial initial decisions re mpt issues in response to Commission 830523 order soliciting comments on Commission 830524 briefing Issues must be investigated W/Certificate of 8vc ABLER,R W Pennsylvania, Commonwealth of, 83/06/02 12pp 18742 133 24X Fichs 50-289,83/06/02/8306070271
- 8306060279 Comments on NRC 830524 Commission briefing on revalidation of NRC position supporting licensee mpt NRC briefing violates due process rights Mgt issues not addressed sufficiently Certificate of 8vc encl
 DOROSHOW, J. Three Mile Island Alert 83/06/03 10pp 18729 026
 24X Fiche 50-289,83/06/03,8306060279
- B304070390 Order extending time until 830403 for Aamedts to file comments on IC Insp Rept 50-209/63-10
 CHILK: 8 J Office of the Secretary of the Commission 83/04/03
 Aamodts, The 1p 18742 018 24X Fithe 50-289,83/04/03,8304070390
- 830&070418 Comments on Commission 830524 briefing on leak rate falsification & objection to exparte communication Briefing violates due process since intervenous not given reasonable opportunity to confront evidence Certificate of Svc encl HEISS, E.R. Union of Concerned Scientists 83/06/03 11pp 18742 259 24X Fiche 50-289.83/06/03.8306070418
- B306080173 Response opposing THI Alert B30519 request for adjudicatory hearing on steam generator repair amend Request should be denied w/o prejudice re TMI Alert ability to file subsequent request Por hearing per recent notice W/Certificate of Svc RAMSON, R J. Hearing Branch 4 83/06/03 Commissioners 15pp 18771 331 24X Fiche 50-289,83/06/03.8306080173
- 830-6150324 Corrected FR notice, originally insued B30531, extending date by which licensees may request hearing & parties may file written petition for leave to intervent to B30630 re 830509 application for amend to License DPR-50 STOLE, J.F. Operating Reactors Branch 4 83/06/03 3pp 18067-339 24% Fiche 50-289.83/06/03.8304150324
- 8306090297 Errata to Aamodt comments re IC Insp Rept 50-289/83-10 & Commission 830524 briefing re Hartman motter Certificate of Syc encl AAMODT. M Aamodts. The 83/06/06 4pp 18795 293 24X Fiche 50-289,83/06/06.8306090297
- 8306070211 Response apposing TMI Abert 830523 motion to reopen record relicensee mgt competence & integrity Certificate of Svc spnt!

 BLAKE.E.L Metropolitan Edison Co. BLAKE.E.L. Shaw, Pittman. Patts & Troubridge 83/06/07 Atomic 8afety and Licensing Appeal Panel. 48pp 18796 031 24% Fiche 50-229,83/06/07.8306090211
- 8306070343 Advises that 830531 memp to W Dircks re Hartman allegations & NRC reply to memp should be served on parties PLAINE, H H Office of the General Counsel 83/06/07 GILINSKY, V Commissioners to 18794 334 24% Ficho 50-289, 83/06/07, 8306090343
- B30413040B Response to util B30523 reply opposing NRC 830421 brief on review of ALAM-698 & response to util B30523 motion for leave to file affidavit Util should be required to staff emergency operations facility H/Certificate of Svc GRAY.J R Hearing Branch 4 83/06/07 Commissioners 22pp 18823 095 24X Fiche 50-289,83/06/07.8306130408

- B306090338 Forwards MJ Direks 830607 memo to Commissioners re NRC recommendations for completion of restart review GCLDBERG, J R Hearing Branch 2 B3/06/08 EDLES, O J , KOHL, C N, , BVCK, J H Atomic Safety and Licensing Appeal Panel 14pp 18795 096 24X Fiche 50-289,83/06/08,8306090338
- 8306150427 Errata to Aamodt comments re IE Insp Rept 50-289/83-10 & Commission 830524 briefing re Hartman matter Certificate of Svc encl AAMODT: M Aamodts: The 83/06/08 Ap 18847 085 24X Fiche 80-289,83/06/08.8306150427
- 8306130390 Forwards util 830610 ltr to Commission re mgt integrity issues
 BLAKE, E.L. Shaw, Pittman, Potts & Trombridge 83/06/10 CHILK, 8 J
 Office of the Secretary of the Commission 1p 18821 023 24X
 Fiche 50-289,83/06/10
- --B306i30395 Discusses mgt integrity issues Util confident in capability & integrity of mgt organization & personnel Certificate of Byc encl
 DIECKAMP. H General Public Utilities -- GPU Service Corp
 B3/06/10 PALADIMA. W Commissioners 9pp 18821 024 24X
 Fiche 50-289,83/06/10,8306i30390
- 8306180410 Forwards corrected Page 4 to GPU 830610 ltr to NRC ra assignment of personnel to provide overview assessment, analysis or audit of plant activities BLAKE, E.L. Shaw, Pittman, Poits & Trowbridge BLAKE, E.L. Metropolitan Edison Co. 83706/10 CHILK, S.J. Office of the Secretary of the Commission Spp. 18847 121 24X Ficke 50-269, 83706/10, 8306150410
- 8306190245 Answer to THI Alert 830523 motion to reapen record on issue of util mgt competence & integrity Moves to defer ruling on motion pending further development of open issues W/ Certificate of Sac OULBERG, J. R. Hearing Branch 2 HAONER, M. E. Hearing Branch 4 B3706/13 Atomic Safety and Licensing Appeal Panel 18pp 18846 110 24X Fiche 50-269,83/06/13,8306150245
- 8306160600 Opposes segaration of util mgt from actions of util employers Issues ro restart concern individual & local community control in determining atd & quality of life HGCHENDONER. L. Daughin County, PA 83/06/13. PALLADINO, N J Cammissioners 2pp 18866 095 24X Fiche 50-289,83/06/13.
- 8306160604 Petition for review of ASLAB 830526 Decision.ALAB-729. Issues re adequacy of DHR not resolved Certificate of Svc encl WEISS.E R Union of Concerned Scientists WEISS.E R Harmon & Heiss 83/06/13 Commissioners 10pp 18865 086 24X Fiche 50-289.81/06/13.8306160604
- B306160008 Forwards WJ Pircks 830610 memu to Commission in response to Commissioner Gilinsky B30531 memo re Hartman allegations. W/o encl WAGNER, M E Hearing Branch 4 C3706/14, EDLES, C. J., KOHL, C. N., BUCK, J. H. Atomic Bafety and Licensing Appeal Panel 1p 18861 357. 24X Fiche 50-289, B3/06/14, B306160008
- 8306160297 Comments on EDD 830607 proposal re TMI-1 restart Restart w/o addressing questions re operator cheating & util response to cheating & util response to cheating & util competence & intogrity.unacceptable, Centificato of Svc encl
 WEISB.E Union of Concerned Scientists 83/06/14 7pp. 18860-060 24X Fiche 50-289,83/06/14.8306160297.
- 8306160594 Urges restart deferral until significant issuem resolved. QAGE.K National Lawyers Guild. Houston Chapter 83/06/14. PALLADINO, N J. GILINSKY, V. RODERTS, T M. Commissioners. ip. 18866 101 24X Fichs 30-209.83/06/14.8306160594
- B306200328 Order scheduling 830720 oral argument on MM Asmodt 820903, N & M Asmodt 830416 & TMI Alert 830523 motions to reopen record in Behseds, NO Parties must inform ASLAB of participation by 830630
 TOMPKINS, B A Atomic Safety and Licensing Appeal Panel 83/06/16, 792 18900 353 24% Fiche, 50-289, 83/06/16, 8306200328
- 8306220042 Notice of withdrawsl of appearance in proceeding Certificate of Svc encl
 STRAUBE, M. Affiliation Unknown 83/06/16 4pp. 18930.175 24X
 Fiche 50-289,83/06/16.8306220042.
- B306220046 Notice of withdrawal of appearance in proceeding Certificate of Evc enci ADLER, R W Pennsylvania, Commonwealth of, B3/06/17 4pp. 18928 204 24X Fichs. 50-289, 83/06/17,8306220046

- 8306220142 Comments on M Dischamp 830527 & 0610 ltrs re immediate affectiveness of restart Dischamp concealment of info detrimental to most evidences util policy of expediency Cartificate of Svc encl AAMODT, N O , AAMODT, M M Aamodts, The B3/06/18 Spp 18926 166 24X Fiche 50-289,83/06/18,8306220142
- 8305220147 Comments to NRC 830515 briefing of Commission on util compliance w/open items to 830515 briefing of Commission replant staffing to avoid employment of personnel involved in falsification of leak rates Certificate of Svc enc! AAMODI, M M. Aamodts, The 83/05/18 App 18725 170 24% Fichs, 50-289, 83/06/18, 8305220147
- 830A220068 Motions to provide info & to lift order of confidentiality of reopened hearing Order of confidentiality should be lifted to permit discussion of staffing per Dircis & Dieclamp ltrs Certificate of Svc encl AAMDDT.M M Aamodts, The E3/06/20 Atomic Safety and Licensing Appael Panel 5pp. 18930 100 24% Fiche 50-289,83/06/20,8306220068
- 8306220071 Forwards INPO 830610 draft rept on restart evaluation & INPO May 1783 rept re corp assistance visit Svc list encl.

 BLAKE, E L Shaw, Pittman, Potts & Trowbridge BLAKE, E L Matropolitan Edison Co 83/06/20. EDLES, 6 J. BUCK, J H., KOML, C N Atomic Safety and Licensing Appeal Panel 46pp 18927 ISB 24X Fichs: 50-289,83/06/20,8306220071
- 8306230367 Order extending time until 830715 for Commission to act to review ALAB-724
 CHILK:8.J Office of the Secretary of the Commission. 83/06/21.
 Commissioners ip 18944-128 24X Fiche 50-289.83/06/21,
 8306230367
- 8304280532 Supports restart Four yes more than sufficient time to reactivate TMI-: SPANO.J.R American Society of Utility Investors 83/04/21 PALLADING.N J. NRC - No Detailed Affiliation Given 1p 19019 007. 24X Fiche 50-289
- 830.6280538 Provides Borough of Highspire, Dauphin County, PA Resolution 4-83, supporting Governor of Pennsylvania position on TMI-1 restart, in 830.602 itr TMI-2 should be deconstantated & defusied TMI should be closed permanently PGRTHEMORE, W. Dauphin County, PA 83/06/21 PALLADING, N. J. Commissioners ip 19020,001 24X Fiche 50-289,83/06/21,830.6280558
- 8306300076 Request for hearing re util request for Tech Spec rev to address steam generator tube repair techniques other than plugging, Fublic perceives significant hazards considerations GREP 83/06/21 CHILK, B Office of the Secretary of the Commission, 2pp. 19122 093. 24% Fichs. 50-289, 83/06/21.8306300076
- 8306230360 Responds to 830601 ltr requesting evidence on NRC staff member statement at Commission 830524 meeting refalsification of leak rate testing record Statement that NRC aware records falsified does not reflect NRC views PLAINC, H. H. Office of the General Counse) 83/06/22 ELAKE, E. Bhaw, Pittman, Potte & Trowbridge, 1g. 18943.331, 24X Fiche, 50-289, 63/06/22, 8306230360
- 8306240279 Forwards DELD 830614 memo to HR Denton re util untimely submittal of Basic Energy Technology Acsoc, Inc & Rohrer-Hisbler-Reglogle, Inc repts Hatter to be referred to Dfc of Investigations DIRCKS, W. J. Diffice of the Executive Director for Operations, 83/06/22 PALLADINO, N. J. (BLIMEKY, V. AMEARNE, J. Commissioners 1p. 18960:134 24X Fiche, 50-289, 83/06/22, 8306240279.
- --8306240281 Advises that licensee failed to meet duty to make Board notifications & obligations under Section 186 by failing to provide Rohrer-Hibler-Replogie. Inc & Basic Energy Technology Assoc, Inc repts in timely manner CUNNINGHAM.9 H. Office of the Executive Legal Director 83/06/14. DENTON, H.R. Office of Nuclear Reactor Repulation, Director 9pp. 18980:135 24X Fiche 50-289,83/06/22,8306240279.
- 8306270388 Expresses concern re NRC proposal to waive exam of QPU corp mgt policies & to focus on allegations of individual misconduct. QPU established mgt policies & practices should be investigated.

 BMEDLEY, R. Three Mile Island Alert B3/06/22. Commissioners. 1s. 18973.303, 24X Fiche 30-287.83/06/22.8306270388.
- 8306270265 Forwards Chairman Palladino statement on Commissioner Gilinsky 830622 tentative conclusions to restart. CHILK.B. J. Office of the Secretary of the Commission 83/06/23. Office of the Executive Legal Director. 1p. 18990-210 24% Fichs: 50-289, 83/06/23, 8306270265.

- --8306270270 Chairman Palladino statement on Commissioner Gilinsky tentative conclusions on restart Comments premature since relevant info unavailable PALLADINO, N J Commissioners 83/06/23 ip 18970 211 24X Ficha 50-289,83/06/23,8306270265
- B306270273 Forwards Commissioner Ahearne & Asselstine statements on Commissioner Ollinsky B30622 tentative conclusions retrestant CMLK.5 J Office of the Secretary of the Commission B3/06/23 Office of the Executive Legal Director ip 18996-190 ,4X Fiche 50-209, B3/06/23, B306270273
- --830627027B Commissioner Asselstine statement re Commissionor Gilinsky tentative conclusions on restart Agrees w/Chairman Palladino that immediate Commission decision premature since relevant info currently unavailable ASSFLSTINE Commissioners 83/06/23 Ip 18996 191 24X Fiche 50-289,83/06/23.8306270273
- --8306270281 Commissioner Abearne statement re Commissioner Gilinsty tentative conclusions on restart Agrees w/Chairman Pallading statement AHEARNE, J. Commissioners 83/06/23 ip 18996 192 24X Fiche 50-289,83/06/23.83062/02/3
- 8306270286 Order directing that party answers to MM Annolt 800691 motion for provision of info & to lift order of candidentiality of reopened hearing, be filed by 830627 SHOEMAKER.C J. Atomic Safety and Licensing Appeal Panel 2pp 18796 176 24% Ficho 50-289, 83/06/23, 8306270286
- 8306270320 Forwards Commissioner Oilinsky 830622 memo re restart CHLK.8 J Office of the Secretary of the Commission 83/06/23 Office of the Executive Legal Director 1p 18994 041 P4X Ficho 50-289.83/06/23.8306270320
- --8306270323 Presents tentative conclusions re restart Continued shortcomings in util performance show conditions that led to accident have not been corrected Top mgt must be replaced to resolve problems
 OILINGKY, V Commissioners 83/06/22 Office of the Executive Legal Director 31pp 18794 042 24X Fiche 50-289,83/06/23,8306270320
- 8304300095 Submits comments opposing Commission 830331 proposed no significant hazards determination re util proposed Tech Spec amend addressing steam generator tube repairs utilizing methods other than plugging DDROSIDM.) Three Mile Island Alert 83/06/23 Office of the Secretary of the Commission 2pp 19120 013 24% Fiche 50-289,83/06/23.8306300095
- --8306300097 Affidavit of PL Lujanac that TMI Alert planning rouncil officially endorsed TMI Alert 830519 request for hearing on graposed license amend re steam generator tube repair on 830607 LUJANAC.P L. Three Mile Island Alert 83/06/16 1p. 19120 Ol6 24% Fiche 30-289, 83/06/23, 8306300095
- 8306280527 Response of Ltr-Designated Individuals 0,VV & W. apposing Aamodt B30620 motion for provision of info to lift order of confidentiality of reopened hearing No substantial change in circumstances shown VOIOT.H H Affiliation Unknown VDIOT.H H LeBoeuf, Lamb, Leiby & MacRae B3/06/27 Atomic Safety and Licensing Appeal Panel 3pp 19019 266 24X Fiche SO-289,83/06/27,8306280327
- --8306280930 Response of individuals employed at TH1 on 790328, apposing Amout 830620 request for matls from federal grand jury NRC lacks jurisdiction since grand jury matls can be disclosed only by court order Certificate of 8vc encl V010T.H H Affiliation Unknown 83/06/27 Atomic Bafety and Licensing Appeal Panel 6pp 19019 280 24X Fiche 50-289,83/06/27,8306280527
- 830.6290379 Answer opposing Aamodt 830.621 motion for provision of info & to lift order of confidentiality of reopened procedure
 Request for resumes of all new amployees excessively burdensome W/Gertificate of Bvc
 8AUSER. D B Metropolitan Edison Co BAUSER. D B Shaw, Pittman, Potts & Troubridge 83/06/27 Atomic Safety and Licensing Board
 Panel 9pp 19030 106 24% Fiche. 50-289, 83/06/27, 8006270379
- 8306270558 Answer opposing Aamodt 830601 motions for provision of info & to lift order of confidentiality Motion premature & overly broad in scope. Mation requesting info treated as discovery request for production of documents W/certificate of 8vc WAONER, M E. Hearing Branch 4 83/06/27 Atomic Safety and Licensing Appeal Panel 475pp. 19050 313 24X Fiche 50-209,83/06/27,8306290558

- 8306300039 Response supporting Aamodt 830621 motion for provision of info re mgt competence & integrity issues Info directly relevant Certificate of Svc encl HEISS, E.R. Union of Concerned Scientists 83/06/27 Atomic Safety and Licensing Appeal Panel App. 19120 358 24X Fiche 50-289,83/06/27.8306300039
- 8306290372 Answer apposing UCS 830613 petition for Commission review of ALAB-729 No question of fact, law or policy affecting public health & safety presented for review Certificate of Svc encl CUTCHIN, J M Hearing Branch 4 83/06/28 Commissioners 12ap
 - CUTCHIN, J M Hearing Branch 4 83/06/28 Commissioners 12pp 19055 202 24X Fiche 50-289, 83/06/28, 8306290372
- 8306300050 Answer opposing UCS 830613 petition for review of ALAB-729 Petition does not clearly identify issues needing review Four factors not addressed Certificate of Svc enc. 1 BAXTER, T A Metropolitan Edison Co 83706/28 Commissioners 12pp 19121 019 24X Fiche 50-289,83/06/28,8306300050
- 8306300087 Forwards util & Pickard, Lowe & Qarrick correspondence re investigation of potential safety issues BLAKE, E.L. Shaw, Pittman, Potts & Trowbridge BLAKE, E.L. Metropolitan Eduson Co BJ/06/28 EDLES, O.J. BUCK, J.H., KOHL, O.N. Atomic Safety and Licensing Appeal Panel 147pp 19120 042 24X Fiche 50-289, 83/06/28, 8306300087

H General correspondence

- 8306060142 Supports restart NRC incompetence & ineptitude displayed in encl 830525 news article
 HILLIAMB, J O American Group Co 83/05/27 DENTON, H R Office of Nuclear Reactor Regulation, Director Spp 18727 247 24X
 Fichs 50~289, 83/05/27, 8306060142
- 8306130389 Discusses restart issues LEE, J Affiliation Unknown 83/06/06 Commissioners 5pp 18623 017 24X Fiche 50-289,83/06/06,8306130389
- 8306100237 Ack receipt of 830602 ltr opposing restart of Unit 1 Ltr will be placed in docket file GILINSKY,V Commissioners 83/06/08 HURST.A Affiliation Unknown ip 18805 135 24% Fiche 50-289,63/06/08,8306100237
- --B306100311 Opposes restart of Unit 1 RURBT. A Affiliation Unknown B3/06/02 NRC - No Detailed Affiliation Given 3pp 18805 136 24X Fiche 50-289,83/06/08, 8306100237
- 8306150174 Responds to 830523 ltr addressed to WJ Dircks & Forwards
 "Priority Concerns of Licensed Nuclear Operators at TMI &
 Gyster Greek & Buggested Action Bteps" & "Review of Current
 & Projected Expenditures & Manpawer Utilization for GPU "
 CUNNINGHAM.O H Office of the Executive Legal Director 83/06/13
 LEWIS.M I Lewis, M 2pp 18851.001 24X Fiche 50-000,83/06/13,8306150174
- --B306150179 "Priority Concerns of Licensed Nuclear Operators at TMI & Gyster Creek & Suggested Action Bleps," final rept
 D'ARCY,P F. SAVER.J R Affiliation Unknown 83/03/15 56pp.
 18891 003 24X Fichs 50-000.83/06/13,8306150174
- --8306130185 "Review of Current & Projected Expenditures & Manpower Utilization for OPU Nuclear Corp "

 * Basic Energy Technology Associates 83/02/28 161pp 18851:059 24X Fiche 50-000,83/06/13.8306150174
- 8306170377 Lists L Brown comments on restart GGLDSMITH,R Commissioners 83/06/13 Commissioners, 1p 18880 278 24X Fichs.50-289,83/06/13,8306170377
- 8306170385 Opines that NRC approach to separate corporate institution from corporate employees legally presumptuous & solidifies contention that NRC in collusion w/utils.

 LEE.J Affiliation Unknown. 83/06/13 Commissioners 4pp 18880 066 24X Fiche 50-289,83/06/13.8506170385
- 8306270370 Opposes decision to allow restart before serious questions re integrity & competence of TM1 mgt & staff resolved.
 FINAMORE,B.A., COCHRAN,T.B. Natural Resources Defense Council 83/06/23, PALLADINO,N.J. GILINSKY,V., ROBERTS,T.M. Cammissioners 1p. 18993 314 24% Fiche 50-289,83/06/23,8306270370.
- 8306270303 Disagrees w/Commissioner Oilinsky attack on NRC chairman, president of GPU & president of GPU Nuclear GPU affort to recover from Mar 1979 accident commended WALBKE, C. Atomic Industrial Forum 83/06/24. PALLADINO, N, J Commissioners. Ip. 18995 287 24X Fiche. 50-289, 83/06/24, 8306270303

- P Operating license stage documents & correspondence
- 8305060487 Provides add1 info per 830413 verbal request re emergency feedwater seismic qualification HUKILL.H D Ceneral Public Utilities GPU Service Corp 83/05/02 STO(2,J F Operating Reactors Branch 4 2pp 18348 139 24X Fiche 50-289,83/05/02,8305060487
- B306010404 Forwards operational QA plan for TMI-1 & Dyster Creek Nuclear Stations.per 10CFR50 54(a)(2) W/o encl HUKILL.H General Public Utilities - GPU Service Corp Region 1. Office of Director 1p 18679 314 24X Fiche 50-000,83/05/23,8306010404
- B306150297 Notice of consideration of issuance of amend to License DPR-50 & proposed no significant hazards consideration determination & opportunity for hearing Amend reviews Tach Spacs to recognize steam generator tube repair techniques STOLZ, JF Operating Reactors Branch 4 B3/05/24 9pp. 18870:017 24X Fiche 50~269, 83/05/24, 8306150297
- 8306060181 Forwards revised list of fees paid & fees due indicating over payment by util re amend applications Agrees w/Items 1-4 in NRC 830425 ltr but takes exception w/Item 5 re steam generator repairs Refund requested HUKILL.H D General Public Utilities GPU Service Corp 83/06/01 MILLER, W O License Fee Management Dranch 2pp 18728 184 24% Fiche 50-287,83/06/01.8306060181
- 8306200246 Forwards list of procedures reviewed, changed if appropriate & typical examples of controls that exist to assure equipment returned to evc.per NUREG-0608.80ppl 1

 HUKILL, H D Opneral Public Utilities QPU Bervice Corp Region 1, Office of Director 15pp 18901 187 24%

 Fiche 50-289,83/06/01.8306200246
- 830.6.22.0.178 Forwards Vol 5. Number 4 to NUREO-0090, "Rept to Congress on AOs." for Fourth Quarter CY82 One AO reported at NRC licensees re inoperability of containment spray sys Agreement states reported no AOS AHEARNE, J.F. Commissioners 83/06/02 O'NEILL, T.P. House of Rep. BUSH.0 H W. Senate 2pp. 18940.024 24X Fiche 50-000,83/06/02,8306220198
- --8306220268 Discusses importance of carefully analyxing 830222 record of hearing on util/D&W litigation to determine whether record contains info bearing on questions of competence & character requirements of OL holder Questions per TMT-2 accident encl. UDALL:M K House of Rep. Interior & Insular Affairs 83/02/25. PALLADING.N Commissioners 2pp 18940.112 24X Fiche 50-000.83/06/02.8306820198
- 8306160606 Requests that NRR review listed B&W-9PU lawsuit documents re facility restart Conclusions & recommendations will be integrated into averall NRC conclusions on mgt integrity DIRCKS.W J Office of the Executive Director for Operations 83/06/07 PALLADINON.J.; OILINERY.V. AHERNE.J.F. Commissioners 13pp 16884 315 24X Ficher 50-289, 83/06/07, 8306160606.
- 8306220207 Advises of NRC actions initiated to reach current position re impact of mgt integrity on restart Review should focus on past performance of individuals identified by various allegations; reviews & investigations particles of the Executive Director for Operations, 83/06/07 PALLADINO, N J. GILINSKY, V., AHEARNE, J. Commissioners i3pp 18951:020 24X Fiche 50-289,83/06/07,8306220207.
- 830609033B Forwards WJ Dircks 830607 memo to Commissioners re NRC recommendations for completion of restart review.
 OOLDBERG.J.R Hearing Branch 2 83706/0B EDLEB.G.J. KOHL.C.N., BUCK.J. H Atomic Safety and Licensing Appeal Panel. 14pp.
 18795 096 24% Fiche 50-289.83/06/08.8306090338
- 8304140014 Forwards amend for & steam generator repair program review fee.per 830507 Tech Spec Change Request 125 & request for approval of steam generator repair HUKILL.H D General Public Utilities GPU Service Corp 83/06/08. 8TOLZ.J F Operating Reactors Branch 4 ip. 18838:324. 24X Fiche 50-289,83/06/08.8306140014.
- 8306140480 Forwards revised schedule for post-accident instrumentation transmitted by 830520 ltr re environ qualification of electrical equipment (100FR50, 47), Date of referenced ltr corrected, Original encl should be replaced HUKILL, H D. General Public Utilities QPU Service Corp 83/06/08, DENTON, H.A. Difice of Nuclear Reactor Regulation, Director 2pp. 18843, 279 24X Fiche 50-289, 83/06/08, 8306140480

- 8304140623 Advises that util will join other B&W owners in performing supplemental generic analyses to quantify reactor coolant pump trip subcooling margins: per 830518 discussion, Schedule will be submitted in Jul 1983.

 HUMILL.H D General Public Utilities GPU Service Corp. 83/06/08 STOLT.J.F Operating Reactors Branch 4. 1p. 18833 359 24X Fiche 50-289,83/06/08:8306140623
- 8306170475 Requests current schedules on hot functional testing & plant readiness for criticality & power escalation testing lidentification of schedules of items controlling restart & any updated info requested by 830613. EIBENHUT, D 0 Division of Licensing 83/06/08 HUKILL, H D, Oeneral Public Utilities GPU Bervice Corp. 3pp. 18894-332, 24% Fiche, 50-289, 83/06/08, 8306170475.
- 8306220224 Forwards draft tables reflecting status of NUREQ-0752, NUREQ-0737, NUREQ-0680 & NUREQ-0746 restart certification items. Neeting proposed for 830614 to discuss status of items listed in encl 870L7. J F. Operating Reactors Branch 4 83/06/09 HUKILL, H D General Public Utilities GPU Service Corp 35pp 18950 312 24X Fiche, 50-289, 83/06/09, 8306220224.
- 8305140586 Forwards restart milestone schedule, including hot functional testing & zero physics testing, in response to NRC 830509 request M/four oversize charts. Aperture cards are available in PDR.
 HUKILL, H. D. General Public Utilities GPU Service Corp 83/05/10 EISENSUT, D. O Division of Licensing. 2pp. 18841 294 24X Fiche: 50-269,63/05/10,8305140586
- 830Ai70256 Informs of post-repair testing results of repaired once-through steam generators & plans to proceed w/remainder of test program Drip, bubble & eddy current testing exams conducted. Add1 plugging repairs will be made.

 HURILL, H D. Deneval Public Utilities GPU Service Corp 83/06/13

 STOLZ, J F. Operating Reactors Branch 4. 5pp 18678:165 24X

 Fiche 50-289,83/06/13,8306170256.
- 8308220318 Requests FR publication of notice of consideration of issuance of amend to License DPR-50 & proposed no significant hazards consideration determination re steam generator repair techniques.

 STOLZ.J F Operating Reactors Branch 4, 83/06/14 CLARK.R A Operating Reactors Branch 3, 2pp. 18977, 150 24X Fiche. 50-289, 83/06/14.8306220318.
- 8306280036 Forwards evaluation & request for add1 info on responses to 821210 order re MAREQ-0737, Item II.F 2. *Detection of Inadequate Core Cooling.** (Clarification requests within 30 days. Digital indicators acceptable STOLZ.J.F Operating Reactors Branch 4. 83/06/14, HJKILL.H.D. Central Public Utilities QPU Bervice Corp. 8pg 19042:348. 24% Fichs:50-289,83/06/14,8306280036.
- 8305210361 Notification of 830520 meeting w/util in Bethesda, MD to discuss actions taken to reinforce confidence in capability & integrity of util organization & personnel associated w/facility.

 VAN VLIET, J. Operating Reactors Branch 4 83/05/17 8TOL2, J F Operating Reactors Branch 4 2pp. 18937 226. 24x Fichs: 50-289, 83/05/17, 8305210361.
- 8306220071 Forwards INPO 830610 draft rept on restart evaluation & INPO May 1983 rept re corp assistance visit. Svc list encl.
 8LAME.E.L. Shaw, Pittman, Potts & Troubridge. BLAME.E.L.
 Metropolitan Edison Co. 83706/20. EDLES, O.J., BUCK, J. H., KDH., C. N.
 Atomic Safety and Licensing Appeal Panel. 46pp. 18927. 188, 24X
 Fiche: 50-289, 83/06/20, 8306220071.
- 8306270231 Forwards application to amend License DPR-50, consisting of Tach Spec Change Request 127 re canterline fuel melt limit, flux to pump trip setpoint & quadrant tilt.

 HUKILL.H D. General Public Utilities GPU Service Corp. B3/06/20.

 BTOLZ.J F. Operating Reactors Branch 4. 1pp. 18988:240. "24X Fiche.50-289,83/06/20.8306270231.
- ---8306270233 Application to seend License DPR-50, consisting of Tech Spec Change Request 127 re centerline fuel selt limit, flux to pump trip setpoint & quadrant tilt HMILL.H.D @eneral Public Utilities - QPU Bervice Corp 83/06/20. 5pp. 18988 241 24X Fiche, 50-289, 83/06/20, 8306270231.
- --8306270234 Proposed Tech Space re analyses of significant hezards considerations. • General Public Utilities - OPU Service Corp. 83/06/20. App 18788: 245. 24X Fiche: 50-289, 83/06/20, 8306270231

- 8306300087 Forwards util & Pickard, Lowe & Garrick correspondence re investigation of potential safety issues BLAKE.E.L. Shaw, Pittman, Potts & Trowbridge BLAKE, E.L. Metropolitan Edison Co. 83/06/28 EDLES, G.J., BUCK, J.H., KOHL, O.N. Atomic Bafety and Licensing Appeal Panel 147pp 19120 042 24X Fiche 50-289, 83/06/28, 8306300084
- G Inspection reports, IE Bulletins & correspondence
- 830.6200438 FOIA request for NRC Investigation Rept 1-83-003 refacilities. KILCOVRE.J.J Kilcovne, J.J 83/03/28 FELTON.J Division of Rules and Records ip 18920 018 24X Fiche 50-289,83/03/28, 830.240438
- 8306200434 Responds to FOIA request for NRC Investigation Rept 1-83-003 re facilities Rept withheld (ref FOIA Exemptions 5 & 7) FELTON, J M Division of Rules and Records 83/05/02 KILCOYNE, J Kilcoyne, J J ip 18920 017 24X Fiche 50-289, 83/05/02, 8306200434
- 8305110458 IE Info Natice 83-32. "Ruptured Am-241 Sources Contained in Well Logging Device " Svc list encl TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/08/26 Consolidated Edison Co of New York, Inc 125pp. 18831 043 24X Fiche 50-000.83/05/26.8305110458
- 8305110460 IE Info Notice 83-34, "Event Notification Info Worksheet" Syc list entl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103). 83/05/26 Consolidated Edison Co. of New York, Inc. 115pp 18732.085 24X Fiche 50-000.83/05/26,8305110460
- 8305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods Withdrawn at BWRs " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/31 Consolidated Edison Co of New York Inc 114pp 18732:208 24X Fiche 50-000.83/05/31.8305110461
- 8306150005 Forwards IE Insp Rept \$0-289/83-11 on 830329-0512 No noncompliance noted STAROSTECKI,R Division of Project & Resident Programs B3/06/02 HWKILL,H D Ceneral Public Utilities - GPU Service Corp 2pp 18846-348 24X Fichs: 50-289,83/06/02,8306150005
- --8306180008 IE Insp Rept 50-289/83-11 on 830329-0512 No noncompliance noted Major areas inspected licensee action on previous insp findings.plant operation (shutdown), including steam generator repairs.restart mods & small break analysis YOUND.F., BARR.K., CONTE.R Region I. Office of Director 83/06/02 9pp 18846 350 24X Fiche 50-289,83/06/02.8306150005
- 8306280366 Responds to IE Bulletin 83-03 Emergency diesel generators at facility differ from those described in bulletin Problems not experienced w/emergency diesel generator check valves HUKILL.H D General Public Utilities OPU Service Corp 83/06/08 Region 1, Defice of Director 3pp 17018 187 24X Fiche 50-289,83/06/08.8306280366
- 8305110444 IE Info Notice 83-36, "Impact of Security Practices on Safe Operations " Svc list enc! JORDAN,E.L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/07 Consolidated Edison Co of New York Inc 117pp, 18830:280 24X Fiche 50-000.83/06/07.8305110464
- 8305110470 IE Info Notice 83-38. "Defective Heat Sink Adhesive & Seismically Induced Chatter in Relays Within Printed Circuit Cards " Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co. of New York, Inc. 118pp 18920: 225 24X Fiche 50-000, 83/06/13, 8305110470
- 8304090010 IE Info Notice 83-37. "Transformer Failure Resulting From Degraded Internal Connection Cables " 8vc list encl JURDAN,EL Division of Emergency Preparedness & Engineering Response (Post 830103), 83/06/13 Consolidated Edison Co. of New York, Inc. 243pp 18921-001, 24X Fiche 50-000,83/06/13,8306090010
- 8305110475 IE Info Notice 83-40, "Need to Environmentally Qualify
 Epoxy Grouts & Smalers." Svc list encl
 JORDAN, E. L. Division of Emergency Preparedness & Engineering
 Response (Post 830103). 83/06/22, Consolidated Edison Co. of New
 York, Inc. 115pp. 19021-179 24X Fiche 50-000,83/06/22,8305110475
- 8305110477 IE Info Notice 83-41, "Actuation of Fire Suppression Sys Causing Inoperability of Safety-Related Equipment " Svc list encl. JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/06/22 Consolidated Edison Co. of New York. Inc. 120pp. 18997:007 24X Fiche 50-000.83/06/22.8305110477.

- 8305110479 IE Info Notice 83-42, "Reactor Mode Switch Malfunctions "
 Svc list encl
 JORDAN, E L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/06/23 Consolidated Edison Co of New
 York, Inc 116pp 18996 242 24X Fiche 50-000,83/06/23,8305110479
- 8306300078 Forwards revised page to 820920 summary of stresses in block wall elements per 830427 telcon, in response to IE Bulletin 80-11 Rev reflects stresses following reinforcement repairs of reactor bldg elevator shaft HUKILLH D General Public Utilities GPU Service Corp 83/06/23 STOLZ, J F Operating Reactors Branch 4 2pp 19048 330 24X Fiche 50-289,83/06/23,8306300078
- 8305110483 IE Info Notice 83-43, "Improper Bettings of Intermediate Range (IR) High Flux Trip Setpoints " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/24 Consolidated Edison Co of New York, Inc 116pp 19046 297 24X Fiche 50-000,83/06/24,8305110483
- R Periodic operating reports & related correspondence
- 8306010407 Correction to annual operating rept 1981 containing info on total aircraft movements at Harrisburg Intl Airport,
 MUKILL, H D General Public Utilities ~ GPU Service Corp 83/05/11.
 Region 1, Office of Directon 2pp 18679 312 24X
 Fiche: 50-289,83/05/11,8306010407
- 8304070215 Forwards "TMI Aquatic Study, Apr 1783 " RESSLER, M.C General Public Utilities - CPU Bervice Corp B3/06/01 HICKEY, C NRC - No Detailed Affiliation Given 1p 18747 021 24X Fiche 50-289, 83/06/01.8306070215
- --8306070219 "TMI Aquatic Study, Apr 1983 "
 NAMBACCI, 9 A. Irhthyological Associates, Inc 83/04/30 19pp 18747.022 24X Fiche 50-289, 83/06/01, 8306070215
- B306300162 Forwards "TMI Aquatic Btudy, Monthly Rept for May 1983," prepared by Ichthoyological Assoc. Inc. RESBLER, W.C. General Public Utilities QPU Bervice Corp. B3/06/2; HICKEY, C. MGC No Detailed Affiliation Given. Jp. 17119 280, 24X Fiche 50-289, 83/06/27, 8306300162
- --8306300164 "TMI Aquatic Study, Monthly Rept for May 1983 "
 NARPACCI, G A Ichthgological Associates, Inc 83/05/31 23pp
 19119.281, 24X Fiche 50-289, 83/06/27, 8306300162.
- 8 Reportable occurrences. LERs & related correspondence
- 830A010353 LER 83-013/03L-0 on 830419, while in cold shutdown, relay room carbon dioxide fire protection sys pressure fell below Tech Speck Caused by seat leakage through bleeder valve Fire watch posted New valve installed W/830518 ltr STEPHENBON, C.J., HUKILL, H.D. General Public Utilities GPU Bervice Corp., 83/05/18 Region 1, Office of Director App 18681-357 24X Fiche: 50-289,83/05/18,830A010353
- B306200127 Updated LER B2-002/03L-1 on BP0128, during long-term cold shutdown, leakage deposits observed on 2-inch nipple which connects auxiliary bldg side of valve MD0-V4. Caused by stress corresion cracking Pipe replaced W/B30606 ltr BTEPHENBON, C, J. HUKILL, H D. General Public Utilities QPU Bervice Corp. B3/06/06. Region 1, Office of Director Spp 18703, 315 24X Fichs 50-289, B3/06/06. B306200127
- B30A2i0247 Forwards updated LERs B3-003/01T-1 & B2-011/99X-1. HUKILL, H. D. General Public Utilities - GPU Service Corp B3/06/06 Ragion 1. Office of Director, ip 18915.061 24X Fiche 50-289,83/06/06.8306210247
- --B306210254 Updated LER 82-011/99X-1 on 820831, notification received from Wyle Lebs that PORV severely corroded Caused by use of acid sulfyr compounds Spare valve installed STEPHEN8ON.C. J. General Public Utilities QPU Service Corp. B3/06/06. Region 1. Defice of Director. 1p. 18915.062, 24X Fichs 50-289, 83/06/06. 8306210247
- --B306210288 Updated LER 63-003/01T-1 on B30211, PORV special inspreyealed corrosion Caused by use of acid sulfur compounds PORV internals replaced & leak tested & pressurizer steam space inspected BTEPHENSON.C. J. General Public Utilities QPU Service Corp. B3/06/06 Region 1, Office of Director. 10pp 18915 063 24X Fiche: 50-289, 83/06/06, 8306210247

- 8306210040 LER 83-015 on 830611.oxygen concentration in miscellaneous waste storage tank gas space exceeded Toch Spec limits
 Nitrogen used to purge oxygen from mys & reduce concentration
 TOOLE, R. J. General Public Utilities OPU Service Corp. 83/06/14, MURLEY, T. E. Region 1. Office of Director ip. 18912-336 24X
 Fichs 50-289,83/06/14.8306210040
- 8306280365 LER 83-014/03L-0 on 830518, while in long-term cold shutdown. liquid radioactive effluent monitor RM-L6 found inoperable RM-L6 functioned properly after monitor switch turned off & on RMS recorder charts will be monitored M/830617 ltr STEPHENBON, C J . HUKILL.H D General Public Utilities GPU Service Corp 83/06/17 MURLEY.T E Region 1. Office of Director App. 19001 200 24X Fiche 50-289,83/06/17.8306280365
- T Hearing transcripts on non-antitrust matters
- 8306170450 Transcript of Commission 830615 briefing in Washington, DC re status of certification in TMI-I restart proceeding Fp 1-36 Supporting documentation encl * Commissioners 83/06/15 80pp. 18706 234 24X Fiche 50-289, 83/06/15, 8306170450
- V Operator Examinations
- 8306140170 Extends invitation to attend 830627 meeting in King of Prussia,PA to dicuss transfer of reactor operator licensing function from Bathada,MD to Region I ofc. STAROSTECKI,R. Division of Project & Resident Programs 83/06/09. HUKILL,H D General Public Utilities GPU Service Corp. 2pp 18839 036 24X Fiche 50-289,83/06/09.8306140170
- DOCKET 50-299 PILORIM NUCLEAR POWER STATION, UNIT 1
 P Operating license stage documents & correspondence
- 8305240436 Forwards add1 info on implementation of Rev I to NUREQ-0313. in response to NRC 830408 request W/two oversize drawings Aparture cards are available in PDR HARRINGTON, W D Boston Edison Co 83/05/20 VASBALLO, D B. Operating Reactors Branch 2 8pp 18573 224 24X Fiche 50-293.83/05/20.8305240436
- --8305240443 Rev 4 to Procedure 22 A 16, "Ultrasonic Exam of Piping Welds "
 DEEDS, P. E. Pembody International Corp. 80/02/22 24pp 18573 232 24X Fiche 50-293,83/05/20,8305240436.
- ~-8305240448 Ray 53 to Procedure BMRI-NDT-600-3, "Manual Ultramonic Exam of Pressure Piping Welds" * Bouthwest Ressarch Institute 79/07/31, 41pp 18573 256 24X Fiche, 50-273, 83/05/20, 8305240436.
- --B305240455 Rev 3 to Procedure SHRI-NDT-700-5, "Mechanized Exam of Vessel Components, Vessel Welds & Piping Welds."

 * Southwest Research Institute 79/09/30 20pp. 19573:297 24X Fithe: 50-293, 83/05/20, 8305240436
- --8305240461 Rev & to Procedure SHRI-NDT-700-5. "Mechanized Ultrasonic Exam of Vessel Components, Vessel Helds & Piping Helds." + Bouthwest Research Institute 81/02/28 28pp. 18573:317 24X Fiche: 50-293,83/05/20.8305240406
- 8306010334 Bubmits response to Generic Ltr B3-02 re implementation of NUREG-0737 items No Tech Spec changes required for Items I A.1.1.3.1 A.1.3.1 E.4.1.1I.E.4.2.5.II.E.4.2.6. II.E.4.2.5.II.E.4.2.6. II.E.4.2.7.II.K.3.3.1 K.3.13.1 K.3.22 & III.K.3.15. HARRINGTON.W D Boston Edison Co. 83/05/24. EISEMBUT.D. 0. Division of Licensing. 2pp 18672:315. 24% Fiche 50-293.83/05/24. B306010334.
- 830A070167 Application to amend License DPR-95, revising Tech Baccs to expand operating region of power/flow map & provide associated changes in average power range sonitor flux scram & rod block trip settings. (Propused Change 83-05.) HARRINOTON, W. D. Boston Edison Co. 83/05/31. VASSALLO, D. B. Operating Reactors Branch 2 ip. 18739-004 24X Fichs 50-293, 83/05/31, 8306070167
- --8306070170 Proposed Tach Specs expanding operating region of power/flow map & providing associated changes in average power range monitor flux scram & rod block trip settings

 * Boston Edison Co. 83/05/31, 11pp. 18739,005 24X
 Fiche. 50-293,83/05/31,8306070167
- --8306070174 *GE BWR Extended Load Line Limit Analysis for Pilgrim Nuclear Power Station Unit 1 Cycle 6. * FISCHER, D. L. GRIDLEY, R. I. General Flectric Co. MFMG-92198

- 8306070045 Clarifies misconception in 830513 safety evaluation submitted in response to NUREG-0737. Item II F 1-3 re containent high-range radiation monitors High-range drywell radiation monitors & procedures in place when response sent HARRINGTON.W D Boston Edison Co 83/06/01 VASSALI.O.D B Operating Reactors Branch 2 ip 18737:343 24X Fiche 50-293.83/06/01.8306070045
- 830.607034B Forwards fee for 830405 proposed changes to Tech Spec Sections 2.2.2 B & Table 3 ii i.ger 10CFR170 HARRINGTON, M. D. Boston Edison Co. 83706/01 VASSALLO, D B. Operating Reactors Branch 2 ip 18742 152 24X Fiche 50-293.83/06/01.8306070348
- 8306140613 Forwards Rev 1 to TR-5310-1, "Mark I Containment Program Plant Unique Analysis Rept of Torus Suppression Chamber for Pilgrim Station, Unit 1 HARRINOTON, H D Boston Edison Co 83/06/07 VASSALLO, D B. Operating Reactors Branch 2 ip 18837 001 24X Fiche, 50-293, 83/06/07, 8306140613
- 8306220196 Advises that 830426 submittal of addl info re deletion of annual aerial photography acceptable Confirmation of romaitment to implement modified breatwater monitoring program within 30 days requested VASSALLO.D.B Operating Reactors Branch 2 83/06/07 HARRINOTON, M.D Beston Edison Co 3pp. 18951 040. 24X Fiche.50-293.83/06/07.8306220196
- B306150011 Forwards detailed design description of implementation of NUREO-0737, Item II F 1.6. "Containment Atmospheric Monitor," per B30411 request Task to be completed by 840601 HARRINGTON.N D Boston Edison Co 63/06/09 VASBALLO, D N Operating Reactors Branch 2 14pp 18846 334. 24X Fiche 50-293,83/06/09,830615001
- 9306220003 Forwards "Offsite Dose Calculation Manual," per 930415 commitment re redicipical effluent & environ monitoring Tack Spacs.
 HARRINGTON W B Boston Edison Co 93/06/16 VASSALLO, D B Operating Reactors Branch 2 ig 18728.078 24X Fiche 50-273,83/06/16.8306220003
- --8306220009 "Offsite Dose Calculation Hanual." * Boston Edison Co 83/06/10 88pp 18928:079 24x Fiche 50-293,83/06/16,8306220003
- B306280331 Forwards add1 Class III fee for proposed Tech Spec Change 83-8 re mar critical power ratio limits & safety relief valva simmer margin.per 830620 request. HARRINGTON, M.D. Boston Edison Co. 83/06/23 VASSALLO, D.B. Operating Reactors Branch 2 p. 19001 222, 24X Fiche: 50-293, 83/06/23, 8306280331
- G. Inspection reports, IE Bulletins & correspondence
- 830&020409 Forwards IE Insp Rept 50-293/83-12 on 83042&-29 & notice of violation.

 MARTIN, T T Division of Engineering & Technical Programs. 83/05/18

 HARRINGTON, N D Boston Edison Co 2pp 18693-208 24X

 Fichs: 50-293, 83/05/18, 830&020409
- --8306020413 Notice of violation from insp on 830426-29, * Region 1, Office of Director 83/05/18 2pp 18693.210 24X Fichs. 50-293, 83/05/18, 8304020409
- --8306020416 IE Ensp Rept 50-293/83-12 on 830426-29. Noncompliance noted, failure to control high radiation areas per Tech Spec 6.13 & failure to post airborne radioactivity areas per 100FR20, 203

 MHTTE.J.R., SHANBAKY.M.M. Region 1, Office of Director. 83/05/16
 9pp 18693.212 24X Fiche:30-293,83/05/18.8306020409
- 8304030119 Grants relief, in part/from inservice insp requirements of ACME Boller & Pressure Vessel Code, per 790724 request Gafety evaluation, technical evaluation rept & notice of granting of relief encl.

 VASSALLO, D. B. Operating Reactors Branch 2, 83/05/19, HARRINGTON, M. D. Boston Edison Co. Spp. 18734 239, 24% Ficher 50-293, 83/05/19, 8304030119.

- --8209200370 "Pilgrim Nuclear Power Station Unit 1 Inservice lump Program," technical evaluation rept * Science Applications, Inc. NRC-03-02-096 SAI--186-028-33 82/09/17 NRC - No Detailed Affiliation Given 3App 18734 252 24X Fiche 50-293,83/09/19,8306030119
- --8306030134 Notice of granting relief, in part, from ASME Code Bection XI inservice insp requirements VASSALLO,D B Operating Reactors Branch 2 83/05/19 2pp 18734 288 24X Fiche 50-293,83/05/19,8306030119
- B305110458 IE Info Notice B3-32, "Ruptured Am-241 Bources Contained in Well Logging Device" Svc list encl TAYLOR, J M Division of Safeguards & Inspection Programs (Post B30103), B3/05/24 Consolidated Edison Co of New York, Inc. 125pp 16831 043 24X Fiche 50-000, B3/05/26, B305110458
- 8305110460 IE Info Notice 83-34, "Event Notification Info Workshoot "
 Svc list encl
 JGROAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/05/26 Consolidated Edison Co of New
 York, Inc 115pp 18732 085 24x Fiche 50-000,83/05/26,8305110460
- 8305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rodo Withdrawn at BWRs " Svc list enci JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/31 Consolidated Edison Co of New York, Inc 116pp 18732 208 24X Fiche 50-000.83/05/31,6308110461
- 8306200158 Forwards IE Insp Rept 50-293/83-09 on 830404-0503 & notices of violation & deviation
 8TARDSTECKI.R. Division of Project & Resident Programs 83/06/06
 HARRINGTON, W D Boston Edison Co Rpp 18903 080 24X
 Fiche 50-293,83/06/06.8306200158
- --8306200161 Notice of violation from insp on 830404-0503 * Region 1. Office of Director 83/06/06 2pp 18703 084 24X Fiche 50-293,83/06/06,8306200158
- --8306200162 Notice of deviation from insp on 830404-0503 * Region 1, Office of Director, 63/06/06 1p 10903 086 24X Fishe 50-293,63/06/06.8306200150
- 8306170325 Forwards summary of 830510 mgt meeting w/util in Hoston.MA
 re status of performance improvement program Apr 1783
 milestones complete
 STAROSTECKI,R Division of Project & Resident Programs 83/06/07
 HARRINGTON,W D Boston Edison Co. 5pp 18878 246 24X
 Fiche. 50-293,83/06/07,8306170325
- 8304140632 Advises that 830828 response, Rev 2 to performance improvement program to 820118 order, acceptable & incorporates 820927 comments Effectiveness of program implementation should be stressed at future meetings ALLAN. J. M. Region 1, Office of Director 83706708 HARRINGTON, W. D. Buston Edison Co. 2pp. 18043-060 24X Fiche 50-273, 83706708.
- 8306230389 Forwards IE Insp Rept 50-293/83-13 on 830510-13 & notice of violation.

 MARTIN.T T Division of Engineering & Technical Programs 63/06/08 HARRINGTON, W D Boston Edison Co 2pp 18943 IIE 24X

 Fiche 50-293.63/06/08
- --8306230372 Notice of Violation from insp on 830510-13 * Region 1: Office of Director 83/06/08, lp 18943:114 24X Fichs 50-273,83/06/08,8306230389,
- --8304230397 IE Insp Rept 50-273/83-13 on 830510-13. Noncompliance noted failure to follow procedures for chloride analysis mixed indicator solution & to review vendor lab procedures for strontium & tritium analyses of effluent samples.

 KOTTAN. J. J. PASCIAK. W Region 1. Office of Director 83/04/02 7pp. 18943.115. 24X Fiche 50-273,83/04/03,8306230389
- 8305110464 IE Info Notice 83-36, "Impact of Security Practices on Safe Operations." Svc list encl.
 JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/07 Consolidated Edison Co. of New York, Inc. 119pp. 18830-280, 24X Fiche 50-000, 83/06/09, 8305110464

- 8306140657 Ack receipt of 83093; ltr informing NRC of steps taken to correct violations noted in 1L Insp Rept 50-293/83-07 STARGSTECKI,R Division of Project & Resident Programs 83/06/09 HARRINGTON,W D Boston Edison, Co Ip 18834 005 24X Fiche 50-293,84/06/09.8306140657
- --8306140662 Responds to NRC 830502 ltr re violations noted in IE Insp Rept 50-293/83-07 Corrective actions personnel counseled for failing to implement requirements of Procedure TP 82-43 re standby gas treatment sys HARRINOTON W D Boston Edison Co 83/05/31 STAROSTECKI, R Division of Project & Resident Programs 2pp 18834 006 24X Fiche 50-273,83/06/09.8306140657
- B305110470 IE Info Notice B3-3B, "Defective Heat Sink Adhesive & Seismicelly Induced Chatter in Relays Within Printed Circuit Cards " 5ve list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post B30103) B3/06/13 Consolidated Edison Co of New York Int 1889 18920 225 24X Fiche 50-000.83/06/13.8305110470
- B306090010 IE Info Notice B3-37, "Transformer Failure Resulting from Degraded Internal Connection Cables " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) B3/06/13 Consolidated Edison Co of New York, Inc 243pp 18921 COL 24X Fichs 50-000.83/06/13.8306090010
- 9306280357 Forwards IE Insp Rept 50-293/83-08 on 830509-13 & notice of violation MARTIN,T T Division of Engineering & Technical Programs 83/06/13 HARRINGTON.W.D Boston Edison Co 2pp 19020 283 24X Fiche. 50-293,83/06/13
- --8306280363 Notice of violation from insp on 830509-13 * Region 1. Office of Director 83/06/13 ip 19020 285 24X Fiche 50-293-83/06/13,8306280357
- --8306280484 IE Insp Rept 50-293/83-08 on 830509-13 Noncompliance noted failure to conduct radiological environ monitoring program audit at required frequency & failure to submit 1982 radiological environ monitoring program rept on time JACKBUN.T J. STRUCKMAYER.R. PASCIAK.W Region 1. Office of Director 83/06/07. 7pp 19020 286 24X Fiche 50-273.83/06/13.8306280357
- 8306240172 Informs that Rev 1 to ASME testing program for pumps & valves will be sent by 830715 Rev concerns second 10-ur insp interval for period 821208-921207 Submittal will also contain relief requests HARRINOTON, 9 D. Boston Edison Co 83/06/17 VASSALLD, D B Operating Reacture Dranch 2 1p 18981 035 24X Fiche 50-293,83/06/17,8306240172
- 8305110475 IE Info Notice 83-40, "Need to Environmentally Qualify
 Epoxy Grouts & Sealers " Svr list encl
 JORDÁN,E L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/06/22, Consolidated Edison Co. of New
 York, Inc. 115pp 19021 179 24X Fiche 50-000,83/06/22,8305110475,
- 8305110477 IE Info Notice 83-41, "Actuation of Fire Suppression Sys Causing Inoperability of Safety-Related Equipment " Svc list enc! JORDAN, C. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/22 Consolidated Edison Co. of New York, Inc. 120pp 18997 007 24X Fiche 50-000,83/06/22,8305110477
- 8305110479 IE Info Notice 83-42, "Reactor Mode Switch Malfunctions,"
 Bvc list encl
 JORDAN,E L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/06/23 Consolidated Edison Co. of New
 York, Inc 116pp 18776,242 24X Fiche 50-000,83/06/23,8305110479
- 8305110483 IE Info Notice 83-43, "Improper Settings of Intermediate Renge (IR) High Flux Trip Sotpoints." Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/24 Consolidated Edison Co of New York, Inc. 114pp 19046 297 24X Fiche, 50-000, 83/06/24, 8305110483.
- R Periodic operating reports & related correspondence
- 8306020154 Monthly operating rept for Mar 1983, W/830413 ltr. HARRINGTON, W D , WHITNEY, G G Boston Edison Ca 83/04/13 7pp. 18690: 347 24X Fiche 50-293, 83/04/13, 8306020154

S Reportable occurrences, LLRs & related correspondence

- 8306010386 Updated LER 81-059/03L-1 on 811002, acceptance criteria for Test 8 7 3, "Secondary Containment Leak Rate Test," not met Caused by damper alignment reducing capability Engineering evaluations added to procedule W/830509 let HARRINOTON, W D , VENDER, J Boston Edison Co 83/05/09 Region 1, 0ffice of Director 2pp 18682 171 24X Fiche 50-273,83/05/09,8306010386
- B306010393 LER 83-020/01T-0 on 830429. Terh Spec Sections 3 11 D & 4 11 D not incorporated Sections issued w/Amend 39 k inadvertently deleted by Amend 42 Caused by personnel error Procedural change initiated W/830512 ltr WHITNEY. G Q , HARRINGTON, W D Boston Edison Co B3/05/12 Region 1. Office of Director 3pp 18682 231 24X Fiche 50-293, 83/05/12, 8306010393
- 8304010157 LER B3-023/03L-0 on B30420 & D504, dissel generator fuel pump belt A broke Causad by improper installation Detailed instructions written & belt replaced W/830513 ler HHITMEY.0 0 . HARRINGTON.W D Boston Edison Co 83/05/13 Region 1, Office of Director 2pp 18673 336 24X Fiche 50-293,83/05/13, 8306010157
- 8304010322 LER 83-019/03L-0 on B30410, sprinkler head supply pipe on top of turbine stop valves found severed w/water running from pipe Probably caused by pipe Patigue due to vibration Pipe threaded installed & visually inspected W/830513 ltr.

 GRAHAM.E T . HARRINGTON.W D Boston Edison Co B3/05/13 Region 1. Office of Director 2pp 18682 275 24% Fiche 50-293,83/05/13,8304010322
- 8306010060 LER 83-024/03L-0 on 830421, drywell airborne leak detection sys (C-19) particulate channel found inoperable Caused by failure of heat tracing on sensing line to particulate detector Heat tracing repaired W/830516 ltr.
 WHITNEY, 0 0 . HARRINGTON, W D Boston Edison Co 83/05/16 Region 1. Office of Director 2pp 18674.084 24X Fiche 50-293,83/05/16,8306010060
- B306010275 Updated LER 82-047/03X-1 on 821008, water leak observed on 74-ft elevation of reactor bldg in reactor water cleanup holding pump room Caused by socket weld cracks in vent assembly have assembly have assembly histalled W/B30016 ltr VENDER, J. HARRINGTON, W.D. Hoston Edison Co. 83/05/16 Region 1, Office of Director 2pp 18672 241. 24X Fiche: 50-293, 83/05/16, 8306010275
- 8306020417 LER 83-025/03L-0 on 830425, during fire protection surveillance, sliding door in switchgmar room did not fully close. Caused by interference between knot in counterweight rops & security barrier Knot removed, W/830524 ltr.

 HARRINGTON W D , WHITNEY, 0 0 Boston Edison Co. 83/05/24, Region 1, Office of Director 2pp 18694 125 24X Fiche, 50-293, 83/05/24, 8306020419
- 8304020454 Updated LER 82-034/03X-2: on 820826, both HPC1 area smoke datector sys made inoperable to purform corrective maint due to moisture inside detectors Caused by condensation from steam lask Detectors replaced W/830524 ltr
 VENDER.J. HARRINGTON.W.D. Boston Edison Co. 83/05/24. Region 1, Office of Director 2pp 18673 304 24X Fiche. 50-293,83/05/24, 8306020456
- 8306210206 Updated LER 83-005/01X-1 on 830216,util operated w/o 0.25% dalta K shutdown margin required per Tech Spec 3 3 A J Caused by inappropriate cold critical eigenvalue used in GE calculations WESO053 it.
 VARNER, D M, HARRINOTON, H. D. Boston Edison Co 83/05/31 Region 1, Defice of Director 5pp 18919 022 24% Fiche, 50-293,83/05/31,8306210206
- 8306210184 Updated LER 81-05B/01X-1 on B11026, during refuel outage, cable spreading room carbon dioxide sys declared inoperative fallowing abort of special operability test, Caused by design deficiency Halon 1301 flooding sys inatalled W/830608 ltr VERRELLI, D M , HARRINGTON, W D Boston Edison Co 83/06/08 Region 1, Office of Director, Spp. 18915 154 24X Fiche, 50-293,83/06/08,8306210184
- 8306280072 LER 83-026/03L-0 on 830915, during insp of control rod drive piping, number of vent valve plugs discovered missing No leaks abserved. Caused by inadequate pracedures Missing plugs replaced. Procedures modified W/830613 ltr WHITMEY, 0 0, HARRINOTON, W. D. Boston Edison Co. 83/06/13 Region 1, Oefice of Director. 2pp 19001, 175. 24X Fiche: 50-273, 83/06/13, 8306280072

B306280358 LER 83-028/03L-0 on B30518 diesel generator fuel hooster pump belt B parted Caused by broken belt clip & conditions not allowing immediate replacement of belt D when belt A broken Belt B replaced 4/630613 ltr
HHITNEY,,0 0, HARRINOTON,W D Boston Edison Co 83/06/13 Region 1, Office of Director 2pp. 17001 274 24X Fiche 50-293.83/06/13.8306280358

V Operator Examinations

8306140055 Extends invitation to attend 830627 meeting in King of Prussia, PA to discuss transfer of reactor operator licensing function from Bethesds, PMD to Region I of STARDSTECKI, R Division of Project & Resident Programs 83/06/09 HARRINGTON, W D Boston Edison Co 2pp 18838 337 24X Fichs 50-293, 83/06/09,8306140055

DOCKET 50-294 MICHIGAN STATE UNIV RESEARCH REACTOR

F Security, medical, emergency & fire protection plans

8306210333 Forwards request for add1 info re MI State Univ research reactor 821006 emergency plan to continue review per requirements 10CFR50. App E. Reg Quide 2 6. Rev I & ANSI/ANS-15 16-1982 info requested within 30 days of itr date. THOMAS. C O Standardization & Special Projects Branch 83/06/10 MILKINSON. B W Michigan State Univ App 18921 334 24X Fichs 50-294,83/06/10.6306210333

DOCKET 50-295 ZION NUCLEAR POWER STATION, UNIT 1

F. Security, medical, emergency & fire protection plans

8306210314 FOIA request for NRC records be security violations & safeguards events at nuclear facilities OLDENBERG.G Scripps-Howard Newspapers 83/04/22 FELTON, J M Office of Administration Ppp 18725 178, 24X Fiche 50-000, 83/04/22, 8306210314

8306210306 Partial response to FOIA request for NRC records re security violations & safeguards events at nuclear facilities Repts listed on App A available in PDR. Bearch for add1 documents subj to request continuing FELTON. J M Division of Rules and Records 83/05/16. GULDENBERG. G Scripps-Howard Newspapers 2pp 18925 176. 24X Fichs 50-000, 83/05/16, 8306210306

8306130294 Forwards FEMA final exercise evaluations of offsite emergency preparedness exercise conducted on 810729, 1007 & 8303118 No major exercise deficiencies noted HIND, J A Region 3. Office of Director 83/06/09. REED, C Commonwealth Edison Co 2pp 18823 334 24X Fiche: 50-295, 83/06/09, 8306130294

P Operating license stage documents & correspondence

8306030508 Forwards draft "Control of Heavy Loads (C-10), Zion Station Units 1 & 2," per responses to NRC 800701 request for review of provisions for handling & control of heavy loads in conformance w/NUMEG-0612 Add guidance encl VARGA: 8 diperating Reactors Branch 1 83/05/19. FARRAR, D L Commonwealth Edison Co. 15pp 18735.006 24X Fiche 50-275, 83/05/19,8306030508

--8304030512 Draft "Control of Heavy Loads (C-10), Zion Station Units 1 & 2, " technical evaluation rept.

SARGENT, I H. VITO, D J Franklin Institute/Franklin Research Center NRC-03-e1-130 TER-C5504-403/404 DR, B2/11/30 CLEMENSON, F NRC - No Detailed Affiliation Given 3Opp 18735 021 24% Fiche 50-275,83/05/17,8304030508

8304090194 Discusses util interpretation of 10CFR50.49, "Environ Qualification of Electrical Equipment Important to Bafety for Nuclear Power Plants " Intent of rulemaking is to require upgrade program for replacement equipment not parts FARRARD L. Commonwealth Edison Co. 83/06/03. DENTON.H.R Office of Nuclear Reactor Regulation, Director 3pp. 18796:090, 24X Fiche: 50-000, 83/06/03, 8308090194

8306210073 Supple 830813 ltr re NUREO-0737. Item II.F.i.5. "Containment Water Level Monitoring Sys " Lower value of transmitter error should be used for calculating of overall loop uncertainties LENTING.F 9. Commonwealth Edison Co. 83/06/15. DENTON, H R. Office of Nurlear Reactor Regulation, Director. 1p. 18912: 291. 24X Ficha: 50-295.83/06/15.8306210073.

8304230219 Forwards addl info on control room human factors items remuisance alarms, prioritization of multiple alarms & communications w/breathing apperatus, in response to 930511 telcon
LENTINE: G. Commonwealth Edison Co. 83/06/16 DENTON, H.R. Office of Nuclear Reactor Regulation, Director 19pp 18945-264 P4X
Fiche 50-295,83/06/16.8306230219

G. Inspection reports: IE Bulletins & correspondence

9306060218 Forwards IE Insp Repts 50-295/63-04 & 50-304/63-04 pn B30305-0429 & notice of violation SHAPER: W D Region 3. Office of Director 83/05/19 REED. C Communication to 2pp 18/27 J06 24X Fiche 50-295/63/05/19, 8306060218

--B306060219 Notice of violation from insp on B30305-0429 SHAPERN D Region 3. Office of Director B3/05/19 Σμρ 18727-308 24X Fiche 50-299, 83/05/19, 0306060218

--B306060221 IE Insp Repts 50-F95/B3-04 & 50-304/B3-04 on 830305-0429 Noncompliance noted failure to provide procedures to account for plant condition changes after instrument calibr & failure to keep high radiation door locked MATERS.J R. DUNAMAY.F R. HARTMANN.P L. Region 3. Office of Director 83/05/18 12pp 18727 310 24X Fiche 50-295.83/05/19. 8306060210

8305110458 IE Info Notice 83-32. "Ruptured Am-241 Sources Contained in Well Logging Device" Svc list oncl TAYLOR, J M Division of Safequards & Inspection Programs (Post 830103) 83/08/24 Consolidated Edison Co of New York, Inc 125pp 18801 043 24X Fithe 50-000, 03/05/26, 8305110458

8305110460 IE Info Notice 83-34, "Evont Notification Info Worksheet"
Svc list end
JGRDAN,E L Division of Emergency Proparedness & Engineering
Response (Post 830103) 83/05/26 Consolidated Edison Co of New
York, Inc. 115pp 18732-085 24X Fiche 50-000.83/05/26,8305110460

8305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods Withdrawn at DWRs " Svc list encl JORDAN, EL Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/31 Consolidated Edison Co of New York, Inc. 116pp 18732 208 24X Fiche 50-000, 83/05/31, 8305110461

8304090125 Confirms B30602 telcon request for 1-wk extension to reply to notice of violation & proposed imposition of civil penalty Request granted KEPPLER.J O Region 3. Office of Director 83/06/06 D'CONNOR.J J. Commonwealth Edison Co 1p 18795 298 24X Fiche 50-295,83/06/06.8306090415

B30&100074 Forwards response to LE Bulletin 83-03 rs diesal generator cooling water check valves Plants utilize Mission Duo-Check valves employing hinge-to-pin design for protection against vibration-induced failure
BARNES, P. L. Commonwealth Edison Co. B3/06/07 KEPPLER, J. G. Region 3, Office of Director 7pp 18802 238 24X Fiche 50-000,83/06/07, B306100094

B3061703B0 Forwards response to IE Bulletin 83-03 re diesel generator cooling water check valves Valves at Dresden & LaBelle acceptable w/o further insp Rept on valve failures at Quad Cities will be submitted within 70 days of insp completion BARNES,P L Communwealth Edison Co 83/06/07 KEPPLER,J Q Region 3, Office of Director 7pp 18880 211 24X Fiche 50-000,83/06/07,8306170380

8305110464 IE Info Notice 83-36, "Impact of Security Practices on Safe Operations" Svc list encl JORDAN, E. L. Divinion of Emergency Preparedness & Engineering Response (Post 830103) 83705/07 Consolidated Edison Co. of New York, Inc. 119pp 18830 280 24X Fiche: 50-000, 83705/07, 8305110464

8305110470 IE Info Notice 83-38. "Defective Heat Sink Adhesive & Seismically Induced Chatter in Relays Within Printed Circuit Cards " Svc list encl JURDAN, C. Davision of Emergency Preparadness & Engineering Response (Past 830103) 83706/13 Consolidated Edison Co. of New York, Inc. 118pp 18720 225, 24% Fiche 50-000,83706/13,8305110470

B304090010 IE Info Notice B3-37, "Transformer Failure Resulting From Degraded Internal Connection Cables " Svc list and.

JURDAN, E Division of Emergency Preparedness & Engineering Response (Post B30103) B3/06/13 Consolidated Edison Co. of New York, Inc 243pp. 18921 001 24X Fiche 50-000. B3/06/13.0306090010

- 8306170277 Forwards addendum consisting of confirmatory measurements program data sheet for IE Insp Repts 50-295/82-30 & 50-304/82-27 re 81-89 & 8-90 Info will close Open Itoms 295/82-30-0 & 304/82-27-01 PAPERIELLO,C J Region 3, Office of Director 83/06/14 RECD,C Commonwealth Edison Co Spp 18878 268 24X Fiche 50-295,83/06/14,83061/027/
- 8306220026 Ack receipt of B3052h lt: Informing NRC of steps taken to correct violations noted in IL lisp Repts 50-275/83-07 & 50-304/83-06 PAPERIELLO, C. J. Region 3. Office of Director 83/06/17 RLFD, C. Commonwealth Edison Co. 1p. 10928-210 24X Fiche 50-275,83/06/17, 820430024
- 8305110475 IC Info Notice 83 40, "Need to Environmentally Quality Epoxy Grouts & Scalers" Svc list encl JORDAN, E L. Division of Emergency Proparedness & Engineering Response (Post 830103) 83/06/29 Consolidated Edison Co. of New York, Inc. 115pp 19021 177 247 Fiche 50-000 83/06/22, 0305110475
- 8305110477 IE Info Notice 83-41, "Actuation of Fire Suppression Sys Causing Inoperability of Safety Related Equipment " Syc list encl JORDAN, C L Division of Lacygency Properedness & Ingineering Response (Post 830103) 83/06/22 Consolidated Edison Co of New York, Inc 120pp 18997 00/ PAX Fiche 50-000,83/06/22,8305110477
- 8305110479 IE Info Notice 83-42, "Reactor Mode Switch Ma)functions "
 Syc list ent!

 JORDAN, I. Division of Lamergency Preparedness & Engineering
 Response (Post 830103) 83706/23 Consolidated Edison Cn. of New
 York, Inc. 114pp 18996 P42 24X Fiche 50-000.83706/23.8305110479
- 8306300197 Ack receipt of 830610 ltr informing NRC of steps taken to correct violations noted in II lnsp Ropts 50-295/83-04 & 50-304/83-04 SHAFER W D Region 3. Office of Director 83/06/79 REED, C Commonwealth Edison Co ip 19122 178 24X Fiche 50-295,83/06/23,8306300197
- --8306300216 Responds to NRC 820519 ltr re violations noted in IE Insp Repts 50-275/83-04 & 50-304/83 04 Corrective actions entire Radialogical Protection Procedure 1190-1 will be kept at work site W/calibr sheet FARRAR, D L Cummonwealth Editon Co 83/06/16 KEMPLER, J G Region 3, Office of Directon 3pp 19122 184 24X Fiche 50-295,83/06/23.8306300177
- 8305110483 IE Info Notice 83-43, "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints " Svc list enc! JURDAN, EL Division of Lawrgency Proparedness & Engineering Response (Post 830103) 83/06/24 Consolidated Edison Co. of New York, Inc. 116pp 17046 27/ 24X Fithe 50-000, 63/06/24, 6305110483
- 8304290329 Forwards "Inservice Insp & Tost Program, Becond Interval, Zion Nuclear Power Station "Programs applicable for 120-month interval beginning 831231 for Unit 1 & 840919 for Unit 2
 LENTINE, F Q Consolidated Edison Co of New York, Inc 83/06/27 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p. 19054 027 24X Fichs 50-295, 03/06/27, 8306290329
- --8306270335 "Inservice Insp & lest Program, becond Interval, Zion Nuclear Power Station " * Consolidated Edison Cn of New York, Inc 83/06/27 358pp. 19054 028 24% Fiche 50-295, 83/06/27, 8306290329
- R Periodic operating reports & related correspondence
- 8304070233 "Zion Nuclear Generating Station," second evaluation, a Institute of Nuclear Power Operations 83/04/30 38pp 18741.117 24X Fiche 50-275,83/04/30,8306070233
- B306140412 Monthly operating repts for May 1783 W/B30608 ltr AUSTIN 0 : ORACESER, K L Commonwealth Edison Co 83/06/08 Director's Office Office of Inspection and Enforcement 12pp. 18838.049 E4X Fiche 50-295,84/06/08.8306140412
- 8 Reportable occurrences, LERs & related correspondence
- 830.6100064 LER 83-013/03L-0 on 830430 gas cubicle radiation monitor ORTPR028 failed & would not respond to chick source Caused by atout check source due to accumulated grime Tobe, through which check source travels, cleaned W/820602 ltr WILLIAMS.V S., ORAESER, K. L. Commonwealth Edison Co. 83/06/02. KEPPLER, J G. Region 3, Office of Director. 2pp. 18803 067 24% Fiche: 50-275, 83/06/02, 8306100064

- 8306130307 Updated 83-012/03X-1 on 830413, Class 1 pipe tunnel iodine monitor iRTPR078 failed low Caused by personnel incorrectly adjusting high voltage setting on 830412 High voltage readjusted W/830403 Itr WILLIAMS.V S . ORAESSER.K L Communealth Edison Co 83/06/03 KEPPLER.J O Region 3. Office of Director 2pp 18823 297 24X Fiche 50-275,83/06/03,8306130307
- 8306:30351 LER 83-014/01T-0 on 830521. Suring prolonged forced reduction in power, routing extended cycle analysis revealed original final acceptance criteria analysis not still bounding Gaused by inaccerate core depietion models W/830603 ltr CHIN.R Y. GRAESBER.K L Commonwealth Edison Co B3/06/03 KEPPLER.J O Region 3, Office of Director 2pp 18822 324 24X Fiche 50-295,83/06/03.8306130351
- 8306220060 PNO-11I-83-044 on 830614, radiation chamistry lab foreman found shot twice No known connection exists between apparent murder & employment BOYD.D , SHAFER, W. Region 3, Office of Director 83/06/15 1p. 18930 174 24X Fiche 50-295.63/06/15.8306220060
- 8306230438 PND-III-B3-048 on B30615, contractor employee reentered plant unescorted after triggering contamination monitor on exiting plant Employee instructed to proceed to radiation protection of clocated in vital area for decontamination CREED. J. MILLER. J. HIND. J. Region 3. Office of Director. 83/06/17 1p 18742 078 24X Fiche 50-295,83/06/17.8306230438
- 8306270168 LER 83-015/03L-O on 830425, reactor coolent wide-range pressure indicator iP1-403 found reading low Caused by degradation of two de v709 amplifiers & gain factor switch on summator iP1-403 Summator replaced W/830617 1tr CANTWELL,PF, ORAESEER,X L. Commonwealth Edison Co. 83/06/17 KEPPLER,J C. Region 3, Office of Director 2pp 18972 018 24X Fiche 50-295.63/06/17.8306270168
- DOCKET 50-294 BROWNB FERRY NUCLEAR POWER STATION, UNIT 3
- 8306140107 Forwards summary of 830315 meeting at Region 11 ofc re proposed security mods for future const activities at facilities List of attendees encl LEMIS,R C Division of Project & Resident Programs 83/03/25, PARRIB,H G, Tennessee Valley Authority 4pp 18839,082 24X Fichs 50-259,83/03/25,8306140107
- 8306270007 Forwards revised physical security plan, reflecting NRC 830412 comments, Rev withheld (ref 10CFR73 21) HILLS, L M Tennessee Valley Authority 83/06/03, 0'REILLY, J P Region 2, 0ffice of Director 1p 18988 153 24X Fiche 50-259,83/06/03,8306270007
- 8306210010 Forwards "Program Plan for Control Room Design Reviews for all TVA Nuclear Plants," in response to Generic Ltr 82-33 re upgrade of emengency plans KAMMER, D.B. Tennessae Valley Authority 83/06/09, ADENSAM, E. Licensing Branch 4 Spp 18713 001 24X Fiche 50-000,83/06/09, 8306210010
- --8306210016 Procedure B62209 10. "Program Plan for Control Room Design Reviews for all TVA Nuclear Plants " # Tennesses Valley Authority 83/06/09. 200pp 18913 004 24X Fiche 80-000.83/06/09.8306210010
- 8306230201 Notification of 830621 meeting w/util in Bethesda, MD to discuss potential rev to App R submittal based on revised criteria w/respect to analyses on loss of offeite power & availability of other ensite units & condensate pumps. CLARK, D Operating Reactors Branch 2 83/06/16 VASSALLO, D. B. Operating Reactors Branch 2 1p 18794 337 24X Fiche 50-259,83/06/16,8306230201
- 8306210194 Ack receipt of 830603 ltr informing NRC of steps taken to correct violations noted in 1E Safeguards insp Repts 50-259/93-10, 50-269/83-10 & 50-296/83-10 & 50-296/83-10 LEMIS, R C Division of Project & Resident Programs. 83/06/17 PARRIS.H Q Tennessee Valley Authority ip 18919,030 24X Fiche 50-259,83/06/17,8306210194
- --B306210203 Forwards response to NRC B30429 ltr re violations noted in IE Safeguards Insp Repts 50-269/83-10.50-260/83-10 & 50-296/83-10. Corpective actions withheld (ref 10CFR73, 21). MILLS, L. M. Tennessee Valley Authority, 83/06/03 0/REILLY, J. P. Region 2, Office of Director ip 18719 031, 24X Fiche 50-259, 83/06/17, 8306210194.

- --8306210R13 Forwards IE Safeguards Insp Repts 50-259/83-10,50-240/83-10 & 50-296/83-10 on 830404-08 & notice of violation Notice of violation withheld (ref 100FR73 21)
 LEHIB,R C Division of Project & Resident Programs 83/04/29 PARRIG.H O Tennessee Valley Authority 2pp 18919 032 24X
 Fiche 50-259,83/06/17,8306210194
- --B306210224 IE Bafeguards Insp Repts 50-257/B3-10.50-260/B3-10 & 50-294/B3-10 on B30404-08 Noncompliance noted failure to follow access control procedures Details withheld (ref 10CFR73 21).

 MODRE D E Region 2. Office of Director B3/04/27 lp 18719-034 24X Fiche 50-259.83/06/17.8306210194

O Adjudicatory correspondence

- 8306230350 Motion for extension until 830711 to file proposed findings of fact Time needed since intervenors filing consolidated findings & one atty suffered death in family Cartificate of Svc encl HEISS.E R Union of Concerned Brientists WEISS.E R Harmo Weiss. 83/06/21 Atomic Sofety and Licensing Board Panel 18743 201. 24X Fiche 50-247,83/06/21,8306230350 6рр
- P. Operating license stage documents & correspondence
- 830.6020180 Forwards safsty evaluation re valve operability for 10.18 & 20-inth butterfly valves used for purge or vent of containments. Info submitted fails to demonstrate valve ability to close against pressure buildup during LOCA VASSALLO.D B. Operating Reactors Branch 2 83/05/19 PARRIS.H 0 Tennesses Valley Authority 3pp 18701 113 24X Fiche: 50-259,83/05/19.8306020180
- --B3060201B7 Bafety evaluation re valve operability for 10.18 t 20-inch butterfly valves used for purgs or vent of containments Info submitted fails to demonstrate valve ability to close against pressure buildup during LOCA # Office of Nuclear Reactor Regulation, Director B3/05/19 4pp 1B701 116 24X Fiche 50-259.83/05/19.8306020180
- 8306150260 Forwards "Control of Heavy Loads (C-10), TVA, Browns Ferry Nuclear Power Station, Units 1, 2 & 3, " draft technical evaluation rept Conference call requested within 4 to 5 wits to discuss review results VASSALLO, D 8 Operating Reactors Branch 2 83/05/26 PARRIS. H & Tensesse Valley Authority 2pp 18849 322 24X Fiche 50-259, 83/05/26, 8306150260
- ---8306150266 "Control of Heavy Loads (C-10), TVA Browns Ferry Nuclear Power Station.Units 1.2 & 3." draft technical evaluation BOMBERGER.C., AHMED.N., SARGENT,I H. Franklin Institute/Franklin Research Center NRC-03-81-130 TER-C5506-337/338/33 B3/04/05 CLEMENSON.F NRC - No Detailed Affiliation Given. 25pp 18869 324. 24X Fiche 50-259,83/05/26.8306150260
- 8306160483 Application for amend to Licenses DPR-52 & BPR-68, changing Tech Specs to allow operation w/increased core flow MILLS,L H Yennessee Valley Authority B3/06/02 DENYON, H R Office of Nuclear Reactor Regulation, Director 2pp 18863 312 24X Fiche 50-260, 83/06/02, 8306160483
- --8305160436 Proposed Tech Spec changes allowing operation w/increased core flow. * Tennesse Valley Authority B3/06/02 14pp. 18863-314 24X Fiche 50-260,83/06/02,8306160453.
- 8306150243 Suppl 6 to 820914 application for amend to Licenses DPR-33, DPR-52 & DPR-68, changing Tech Specs 3 10 C & 4.10 C re min depth of water required over single irradiated fuel assemblies during handling.

 MILLS.L M. Tennessee Valley Authority 83/06/03 DENTON, H R Office of Nuclear Reactor Regulation. Director. 2pp 18846 127 24X Fiche: 50-259, 83/06/03, 8306150243
- --B30615024B Proposed changes to Tech Specs 3 10 C t 4 10.C re min depth of water required over single irradiated fuel assemblies during handling * Tennessee Valley Authority 93/06/03 10pp. 18846 129 1 Ficher 50-259, 83/06/03, 8306150243 83/06/03 10pp, 18846 129 24X
- 830&140&5& Forwards response to 830519 request for info re BER, Baction 4.0 on containment purge & vent valves Operability of valves justified under LDCA conditions MILLB.L.M. Tannessee Valley Authority 83/06/07 DENTON, H. R Office of Nuclear Reactor Regulation, Director. 9pp 18834:008 24X Fichs. 80-289.83/06/07:830&14065&

- 8306160507 Application for emergency amend to Licenses DPR-33,DPR-52 & DPR-68, changing Tech Spec standby gas treatment sys required surveillance interval to once per operating cycle MILES,L M Tennessee Valley Authority 83/08/13 DENTON.H R Gffice of Nuclear Reactor Regulation, Director 2pp 18844 157 24X Fiche 50-259, 83/04/13, 8304140507
- --8306160523 Proposed Tech Specs changing standby gas treatment sys required surveillance interval to once per operating cycle Justification for emergency nature of proposed Tech Spec change encl # Tennessee Valley Authority B3/06/13 5pp 18864 159 Firb # 50-259, B3/06/13, B306160507
- 8305210014 Confirms agreement w/NRC re interpretation of Tech Spec A 7 B 3 a requirements Spec satisfied by commitment to actuate annually standby gas treatment blowers in primary containment isolation sys logic Tech Spec 189 needed MICLS.L M Tennessee Valley Authority 83/05/16 DENTON.H & Office of Nuclear Reactor Regulation. Director 2pp 18911 357 247 Eleks 20-25-88, 83/05/16, 8306210014 24X Fiche 50-259, 83/06/16, 8306210014
- B306270400 Application to amend Licenses DPR-33.DPR-52 & DPR 68, changing Tech Specs to require annual rept of main steam safety/relief valve actuations, in response to NUREG-0737, Item II K.3 3 & Generic Ltr 63-02 MILLS.L M Tennessee Valley Authority B3/04/20 DENTON.H R Office of Nuclear Reactor Regulation. Director 2pp 17053 1: 24% Fiche 50-257, B3/04/20, B306270400
- ---8306290408 Proposed Tech Spoc revs, requiring annual rept of main/steam safety/relief valve actuations, in response to NUREO-0737, Item II K 3 3 & Generic Ltr 63 02 * Tennessee Valley Authority 83/06/20 5pp 17053 135 24% Fiche 50-259,83/06/20,8306270400
- B306240394 Notification of B30639 meeting w/util in Bethesda.ND to discuss util analysis on intervoning combustibles & separation of circuits CLARK.D Operating Reactors Branch 2 B3/06/22 VA9BALLO,D B Operating Reactors Branch 2 Bp 18799 15/ 24X Fiche 50-259.83/06/22.8306240354
- 8306280415 Supple 821220 response to NUREO-0313 request for addl info Ferrite content of cast austenitic stainless steel ranges from 15 to 20% Valvas highly resistant to intergranular stress corrosion cracking MILLE, L. M. Tennessee Valley Authority 83/06/22 DENTON, H.R. Office of Nuclear Reactor Regulation, Director 2pp 19018, 351 24X Fiche 50-289, 83/06/22, 8306280415
- 8305280947 Advises that GE equipment items discussed in 830520 ltr re environ qualification reclassified as nonproprietary MILLE,L M Tennessee Valley Authority 83/06/23 DENTON.H R Office of Nuclear Reactor Regulation, Director ip 19018 028 2/ Fiche 50-259,83/06/23,8305280567
- 8306300177 Discusses continuing problem re extreme length of time required for approval & resulting backlog of pending requests for lech Spec changes Majority of changes administrative & require minimal review time MILLS.L M Tennessee Valley Authority 83/06/27 DENTON.H R Office of Nuclear Reactor Regulation, Director 3pp 19122 04/24X Fiche 50-259.83/06/27,8306300177 19122 044
- Q Inspection reports, 18 Bulletins & correspondence
- 8304270218 Forwards IE Insp Repts 50-259/83-03,50-260/83-03 & 50-276/83-03 on 830110-14 & notice of violation LEWIS,R C. Division of Project & Resident Programs 83/03, PARRIS,H G. Tennessee Valley Authority 8pp 17054 135 Fiche 50-259,83/03/21.8306270218 83/03/21
- -8306290224 Notice of Violation from insp on 830110-14 * Region 2: Office of Director 83/03/21 9pp 1 Fiche 50-259,83/03/21,8306290218 19055-137 248
- --8306290228 IE Insp Repts 50-259/83-03,50-260/83-03 & 50-296/83-03 on B30110-14 Noncompliance noted failure to perform evaluation of radiation hazards to personnel & employee failure to wrar gloves in contaminated zone DEDB.D T . BARR.K P Region 2. Office of Director. B3/03/0.7pp 17056-139 24X Fiche 50-259,83/03/21,8306270218 83/03/03
- 8306140543 Confirms mgt meeting on 830421 in Chattanoogs, TN to review results of first phase of annual appraisal of regulatory performance, per 830328 telon.
 LEMIB, R.C., Division of Project & Resident Programs 83/04/12 PARRIS, H.G., Tennessee Valley Authority 3pp 18834.176. 24% Fiche.50-000,83/04/12,8306140543

- 8306140041 Forwards results of testing required by IF Bulletin 80-06, "Engineered Safety Feature (ESF) Reset Controls " Two valves each in HPC1 sys & RCIC sys do not remain closed on reset of sys line isolation signal KAMMER, D 8 Tennessee Valley Authority 83/05/12 0'REILLY, J P Region R. Office of Director 2pp 18038 251 24X Fiche 50-260, 63/05/12.8306140041
- 8306140422 Confirms 830601 mpt meeting at site to discuss mgt controls for refueling operations, per 830519 telcon LEMIS.R.C. Division of Project & Resident Programs 83/05/23 PARRIS.H.O. Tennessee Valley Authority 3pp 18838 049 24X Fiche 50-259,83/05/23.8306140422
- 8306140685 Forwards IE Insp Repts 50-259/83-17,50-260/83-17 & 50-276/83-17 on 830509-12 No noncompliance noted VERRELLI.D M Division of Project & Resident Programs 83/05/25 PARRIB.H Q Tennessee Valley Authority 2pp 18841 336 24X Fiche 50-259,83/05/25,8306140685
- --8306140692 IE Insp Repts 50-259/83-17,50-260/83-17 & 50-296/83-17 on 830509-12 No noncompliance noted Major areas inspected followup on IE Bulletin B0-11. "Masonry Wall Design "LENNHAN.J J, CONLON,T L Region 2. Office of Director 83/05/25 5pp 18841 338 24X Fiche 50-259,83/05/25,8306140685
- 8305110458 IE Info Notice 83-32, "Ruptured Am-P41 Sources Contained in Hell Logging Device" Svc list encl TAYLUN, J M Division of Safeguards & Inspection Programs (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 125pp 18831 043 24X Fiche 50~000,83/05/26,8305110458
- 8305110460 IE Info Notice 83-34, "Event Notification Info Worksheet" 8vc list encl 8vc list encl JURDAN, C L Division of Emergency Proparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 115pp 18732 085 24X Fiche 50-000,83/05/26,8305119460
- B305110461 IE Info Notice B3-35, "Fuel Movement W/Control Rods Withdrawn at BWRs" Svc list encl JORDAN, E L Division of Emergency Proparedness & Engineering Response (Post B30103) 83/05/31 Consolidated Edjson Co of New York, Inc 116pp 18732 208 24X Fiche S0-000,83/05/31,8305110461
- 8306140251 Ack receipt of 830525 ltr informing NRC of steps taken to correct violations noted in IL lnsp Repts 50-259/83-09, 30-260/83-09 & 50-296/83-09
 LEMIS.R C Division of Project & Resident Programs. B3/06/0P PARRIS.H 0 Tennessee Valley Authority, ip 18632 236 24X
 Fichs 50-259,83/06/02,8306140251
- --8304140244 Responds to NRC 830418 ltr 1e violations noted in 1E Insp Repts 50-259/83-09,50-260/83-09 & 50-296/83-09 Corrective actions all conduit supports for safety-related equipment corrected by work plan or maint request KAMMER.D 8 Tennessee Valley Authority, 83/05/25, 0'RCILLY, J P Region 2. Office of Director App 18932 237 24X Fiche 50-259,83/06/02,8306140251
- --8306140276 Forwards IE Insp Repts 50-259/83-09, 50-260/83-09 & 50-276/83 09 on 830926-0325 & notice of violation LEWIB.R C Division of Project & Resident Programs 83/04/18 PARRIS.H O Tennessee Valley Authority 2pp 18832 243 24% Fichs 50-259,83/06/02,8306140251
- --8306140284 Notice of violation from insp on 830226-0325 * Region 2, Office of Director 83/04/18 2pp 18832 245 24X Fiche 50-299,83/06/02,8306140251
- --8306140297 IE Insp Repts 50-259/83-09,50-260/83-09 & 50-296/83 09 on 830226-0325 Noncompliance noted failure to meet design flow requirements & failure to have GA review & insp on maint requests PAULK.6 L. Region 2. Office of Director CANTRELL,F S Division of Project & Resident Programs 83/04/13 14pp 18832 247 24X Fichs 50-259,83/06/02,8306140251
- 830.6090331 Forwards response to 1E Builetin 80-11 re masonry wall design well displacement analysis Masonry walls will remain stable under max differential bldg displacement & other loads caused by DBE.

 MILLS, i M Tennesse Valley Authority 83/06/03 DENTON, H R Office of Nuclear Reactor Regulation, Director. 3pp 18795.076 24% Fiche 50-259,63/06/03.6306070331
- 8305110464 IR Info Notice 83-36, "Impact of Security Practices on Safe Operations " Syc list encl JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/09 Consolidated Edison Co of New York, Inc 119pp 18830 280 24X Fiche 50-000,83/06/09,8305110464

- 8306290195 Ack receipt of 830425 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-259/83-03, 50-260/83-03 & 50-260/83-03 & 50-260/83-03 & EWIS.R C Division of Project & Resident Programs 83/06/09 PARRIS.H G Tennessee Valley Authority 1p 19056 221 24X Fiche 50-259,83/06/09,8306270195
- --8306290203 Forwards response to NRC B30321 ltr re violations noted in IE Insp Repts 50-259/B3-03, 50-260/B3-03 & 50-296/B3-03 Violation re failure to perform radiation hazards evaluation denied Personnel counseled on radialogical control KAMMER, D S Tennesse Valley Authority B3/04/25 O'REILLY, J P Region 2, Dffice of Director 5pp 19056 222 24X Fiche 50-259, 83/06/09, 8306290195
- 8305110470 IE Info Notice B3-3B, "Defective Heat Sink Adhesive & Seismirally Induced Chatter in Relays Within Printed Circuit Cards" Syr list encl JORDAN, E. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co of New York, Inc. 118pp. 18920 225 24X Fiche 50-000,83/06/13,8305110470
- 8306090010 IE Info Notice 83-37, "Transformer Failure Resulting From Degraded Internal Connection Cables" Svc list encl JURDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83706/13 Consolidated Edison Co. of New York: Inc. 243pp 18921 001 24X Fiche 50-000.83/06/13.8306090010
- 8306290277 Ack receipt of 830523 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-259/83-12, 30-260/83-12 & 50-296/83-12 LEWIS,R C Division of Project & Rasident Programs 63/06/14, PARRIB.
- --8306270283 Respunds to NRC 830422 ltr re violations noted in IE Insp Repts 50-259/83-12,50-260/83-12 & 50-276/83-12 Corrective actions radiological incident repts issued for each instance cited MILLEIL M Tennessee Valley Authority 83/05/23 D'REILLY, J P Region 2, Office of Director 5pp 19056 039 24X Fiche 50-259,83/06/14,8306290277
- --8304270288 Forwards IE Insp Repts 50-257/83-12,50-260/83-12 k
 50-276/83-12 on 830321-25 k notice of violation
 LEWIS.R C Division of Project & Resident Programs 83/04/22,
 PARTS,H O Tennessee Valley Authority 2pp 17056,044, 24X
 Fiche 50-259,83/06/14,8304270277
- --8306270292 Notice of violation from insp on 830321-25
 * Region 2. Office of Director 83/04/22 2pp 19056 046 24X
 Fiche 80-259.83/06/14.8306290277
- --8306270277 IE Insp Repts 50-259/83-12,50-260/83-12 & 50-296/83-12 on 830321-29. Noncompliance noted radioactive waste operator inside contamination zone w/o protective clothing or radiation monitors
 DEBS, B T . DARR, K P Region 2. Office of Director 93/04/20 App 19056 048 24X Fithe, 50-259, 83/06/14, 8306290277
- 8306270250 Forwards response to IE Bulletin 83-03 re check valve failures in rew water cooling sys of diesel generators. Current test program sufficient to verify integrity of check valves
 MILLS, L M Tennessee Valley Authority 83/06/15 0'REILLY, J P. Region 2, Office of Director. 3pp 17056.081 24X
 Fiche 50-287,83/06/15,8306290250
- 8306270272 Ack receipt of supplemental 830610 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 30-229/81-28, 50-240/81-28 & 50-276/81-28 LENIS, R C Division of Project & Resident Programs. 83/06/16. PARRIS, H Q Tennessee Valley Authority Ip 19056-054, 24% Fiche: 50-259, 83/06/16, 8306270272
- --8306290275 Supplemental response to NRC 811031 ltr re violations noted in lE Insp Repts 50-259/81-28, 50-260/81-28 & 50-296/81-28 corrective actions five pump air vent valves removed & replaced w/stronger & improved upper float guides MILLS, L.M. Tennessee Valley Authority 83/06/10, 0'REILLY, J. P. Region 2, Office of Director. 3pp 19056:095 24X Ficha 50-259.83/06/16.8306890272.
- 63062i0194 Ack receipt of 830603 ltr informing NRC of steps taken to correct violations noted in IE Safeguards Insp Repts 50-259/83-10, 50-260/83-10 & 50-296/83-10 LEWIB.R.C Division of Project & Resident Programs 63/06/17, PARRIB, H Q Tennesses Valley Authority ip 18919-030 24X Fiche. 50-259, 83/06/17, 8306210194

- --8306210203 Forwards response to NRC 830429 ltr re violations noted in IE Bafeguards Insp Repts 50-259/83-10.50-260/83-10 & 50-296/83-10 Corrective actions withheld (ref 10CFR/3 21) MILLS.L H Tennessee Valley Authority 83/06/03 0'REILLY, J P Region 2. Office of Director 1p 18919 031 24X Fiche 50-259,83/06/17.8306210194
- --B306210213 Forwards IE Safeguards Insp Repts 50-259/83-10.50-260/83-10 & 50-296/83-10 on B30404-08 & notice of violation Notice of violation withheld (ref IDCRY3 21)

 LEWIG, R. C. Division of Project & Resident Programs B3/04/29

 PARRIS, M. G. Tennessee Valley Authority 2pp 18919 032 24X

 Fiche 50-259, 03/06/17, 8306210194
- --8306210224 IE Bafeguards Insp Repts 50-259/83-10.50-260/83-10 & 50-276/83-10 on 830404-08 Noncompliance noted failure to follow access control procedures Details withheld (ref 10CFR73 21)
 MOORE.D E. MCOUIRE.D R. Region 2. Office of Director 83/04/27 ip 18919 034 24% Fichs 50-259.83/06/17.8306210194
- 8305290483 Approves issuance of SALP Repts 50-259/83-04,50-260/83-04, 50-276/83-04,50-327/83-04,50-328/83-04,50-390/83-07, 50-376/83-06,50-388/83-04,50-390/83-07, 50-376/83-06,50-439/83-06 for Jul 1981 Dec 1982 No reply required O'REILLY, JP. Region 2, Office of Director 83/06/17 PARRIS. H 0 Tennessee Valley Authority Jpp 19050 212 24X Fiche 50-000,83/06/17,8306290483
- --8306270470 Forwards SALP Repts 50-257/83-04, 50-260/83-04, 50-276/83-04, 50-27/83-04, 50-327/83-04, 50-327/83-04, 50-397/83-07, 50-397/83-06, 50-438/83-06 & 50-439/83-06 For Jul 1981 Dec 1982 LEMB: R C Division of Project & Resident Programs 83/04/13 PARRIS.H 9 Tennesses Valley Authority 3pp 19050 215 24X Fichs 50-000.83/04/17,8306270483
- --8306270503 SALF Repts 50-259/83-04,50-260/83-04,50-276/83-04, 50-327/83-04,50-328/83-04,50-390/83-07,50-391/83-06, 50-438/83-06 & 50-439/83-06 for Jul 1981 - Dec 1982 8 Region 2. Office of Director 83/04/13 92pp 17050 218 24X Fichs 50-000,83/06/17,8306290483
- --8306270510 Comments on BALP Repts 50-259/83-04, 50-260/83-04, 50-296/83-04, 50-327/83-04, 50-328/83-04, 50-390/83-07, 50-391/83-06, 50-438/83-06 & 50-439/83-06 for Jul 1981 Dec 1982 HILLB, L M Tennessee Valley Authority 83/05/10 G'REILLY, J P. Region 2, Office of Director 2pp 19050 310 24X Fiche 50-259, 83/06/17, 8306290483
- 8305110475 IE Info Notice 83-40. "Need to Environmentally Qualify
 Epozy Grouts & Sealers " Svc list encl
 JORDAN, E. L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) B3/06/22 Consolidated Edison Co of New
 York, Inc. 115pp 19021 179 24X Fiche 50-000, 83/06/22, 8305110475
- 8305110477 IE Info Notice 83-41. "Actuation of Fire Suppression Systems Inoperability of Safety-Related Equipment " Syc list
 - enci JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Past 830103) 83/06/22 Consolidated Edison Co. of New York, Inc. 120pp 18997 007 24X Fiche 50-000,83/06/22,8305110477
- 8305110479 IE Info Natice 83-42, "Reactor Hode Switch Helfunctions."

 Svc list encl
 JORDAN.E L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83706/23 Consolidated Edison Co of New
 York. Inc 116pp 18996 242 24X Fiche 50-000,83706/23,8305110479
- 8305110483 IE Info Notice 83-43, "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints " Svc list and JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/24 Consolidated Edison Co. of New York, Inc. 116pp 19046 297 24X Fiche 50-000,83/06/24,8305110483
- R Periodic operating reports & related correspondence
- 8306160482 Monthly operating repts for Apr 1983 W/830511 ltr THOM: T. COFFEY. J. A. Tennessee Valley Authority 83/05/01 Office of Management and Program Analysis 39pp 18864 085 24X Ficha 50-259.83/05/01.8306160482
- S Reportable occurrences. LERS & related correspondence
- 8306010269 Deficiency rept re inability of prompt notification symmetries sirens to complete routes in required time Initially reported on 830502 Addi sirens will be procured & mobile routes modified Full compliance expected by 830901 MILLB.L M Tennesses Vellsy Authority 83/05/23 O'REILLY, J.P., Region 2. Office of Director 2pp 18674-324 24x

- 8306070059 Telecopy RO 50-286/8331 on 830520 reactor low pressure switches PS-3-748 & PS-68-96, switch 2 found below Tech Specialists Caused by setpoint drift Setpoints reset & Design Change Request DCR 1398 initiated to replace switches COFFEY, J.A. Tennessee Valley Authority 83/03/24 Region 2. Office of Director ip 18740 079 24X Fiche 50-276, 03/05/24, 8306070059
- 8306070266 LER B3-028/03L-0 on B30429, while investigating blown fuse in annunication, relay 164-K79 failed Caused by coil over heating melting spool math & stuck armature in energized position Relay replaced W/B30527 tr
 CHRISTOPHER W. GREEN H. J. Tennessee Valley Authority 03/05/27 0'REILLY. J. P. Region 2. Office of Director 3pp 10/40 331 24X
 Fiche 50-294, 83/05/27, 8306070266
- 8306170423 LER 83-029/03L-0 on B30504, during insp of 3EA 480-valt reactor motor operated valve board motor generator set, generator side flywheel bearing found damaged Caused by mispositioning of row balls Bearing replaced W/830601 ltr AARON.J. GREEN.H J Tennessee Valley Authority 83/06/01 07/EELLY.J.P. Region 2, Office of Director Jpp 18879 (162) 14X Fiche 50-296,83/06/01.8306170423
- 8306100192 LER 83-031/01T-0 on 830520 while performing 8J 4 2 B-7, pressure switches 3-P8-3-748 switches 1 & 2 & 3-P9-68-76 switch 2 had as-found calibr values below Tech Spec limits Caused by setpoint drift Switches recalibr W/830022 ltr CHAMBERS.0 T . GREEN.H J Tonnesses Valley Authority 83/06/02 O'REILLY,J P Region 2, Office of Director App 18807 222, 24 Fiche 50-296,83/06/02.8306100192
- 8306130163 LER 83-030/03L-0 on 830504.hydrogen analyzer II removed from tot to replace defective hydrogen sample inlet pump motor Caused by worn end buil Pump & motor assembly replaced & SI 4 7 H successfully completed W/830602 ltr CARTER 9 . ORGEN, H J Tennessee Valley Authority. 83/04/02 O'REILLY JF Region 2 Office of Director 3pp 18824 263 24X Fiche 50-296.83/06/02.8306130163
- 8304170294 PNO-II-83-047 on 830413, standby gas treatment sys train B declared inoperable due to problems w/filter heaters Cause not stated Event involved no equipment damage, no personnel error or injury & no radioactive releases BUTCHER, R C , VERRELLIO M Region 2, Office of Director 2pp 18879, 048, 24X Fiche 50-240, 83/04/15, 8306170274
- 8306270274 Updated LER B3-026/03x-1. on B30411. during attempt to establish EECW flow rate to 3 emergency diesel (ED) generator coolers, head on HX found cracked Caused by mfg defect apparently due to inservice stresses W/B30616 ltr HOLDER, E T , GREEN, H J Tennessee Valley Authority B3/06/16 O'REILLY, J P Region 2. Office of Director 3pp 18796-193 24X Fiche, 50-296, 83/06/16, 8308270274
- B306270371 Updated LER B2-064/03X-1 on B20215 radiochemcial lab personnel discovered inlet sample hose on 3-70-250 turbine & reactor zone exhaust CAM disconnected Cause unknown Hose reconnected H/B30616 ltr
 THORRELD , GREEN, H J Tennessee Valley Authority B3/06/16
 0'REILLY, J P Region 2: Office of Director 3pp 18993 203 24X

V Operator Examinations

- 8306140687 Discusses operator & senior operator licensing exams & schedule to facilitate written & oral exams to be administered during wk of 830627 Approved ref matl listed in ancl requested by 830427
 VERRELLI, D M Division of Project & Resident Programs 80703/30 QREEN, H J Tennessee Valley Authority 3pp. 18841-346 24X
 Fiche 50-259, 83/03/30, 8306140687.
- 8306140626 Responds to 830330 request for renewal of QT McChristian Senior Operator License BDP-2938-2 License expired McChristian should reapply for license NRC will consider request for waiver of exams VERRELLI, D. M. Division of Project & Resident Programs 83/05/12 GREEN, H. J. Tannessee Valley Authority ip 18842 086 24% Fiche 50-259, 83/05/12, 8306140626.

DOCKET 50-298 COOPER NUCLEAR BIATION

- F. Security, medical, emergency & fire protection plans
- 8306140716 Submits followup response to 16 of 19 open items identified in NRC 830217 ltr re IE Emergency Preparedness Appraisal Rept 50-298/82-34 on 821206-10.
 PILANT, J M Nebraska Public Power District 83/05/13 MADSEN, C. L. Region 4. Office of Director. 9pp 18841 323 24X
 Fichs. 50-298, 83/05/13, 8306140716

- 8306080061 Forwards addl info re alternative shutdown capability, clarifying 830318 documentation of 830303 meeting concerning util 820628 request for exemption from Section III 0 of 10CFR50.0pp R Approval of exemption requested PILANT. J M Nebraska Public Power District 83/06/02 VASSALLD, D B Operating Reactors Branch 2 33pp 18774 082 24X Fiche. 50-278, 83/06/02, 8306080061
- 8306200106 Forwards rept of change to Rev 3 to safeguards plan
 Description of changes withheld (ref 10CFR2 790 &
 10CFR73 21)
 PILANT. J M Nebraska Public Power District 83/06/08 Office of
 Nuclear Reactor Regulation. Director 1p 18903 265 24X
 Fichs 50-298,83/06/08,8306200106
- 8306160351 Forwards IE Safeguards Insp Rept 50-298/83-08 on 830405-07 No noncompliance noted MADSEM, Q L. Region 4. Office of Director 83/06/10 PILANT, J M Nebraska Public Power District 2pp 18859 241 24X Fiche 80-298.83/06/10.8306160351
- --8306160362 IE Bafeguards Insp Rept 50-298/83-08 on 830405-07 No noncompliance noted Major areas inspected safeguards contingency plan & response to emergency drill Details withheld (100FR73 21)
 KELLY.JA . BROWN, 0 D . WESTERMAN, T F Region 4. Office of Director 82/03/08 ip 18859 243 24X Fiche 50-298.83/06/10, 8306160351
- J Insurance & indemnity information
- 8306060261 Forwards Endorsement 60 to NELIA Policy NF-200 & Endorsement 47 to MAELU Policy MF-70 PILANT, J M Nebraska Public Power District 83/05/31 Office of Nuclear Reactor Regulation, Director 3pp 18727 174 24X Fichs 50-298.03/05/31.8306060261
- P Operating license stage documents & correspondence
- 8306i60466 Forwards revised P&IDs Updated index encl W/o P&IDs PILANT, J M Nebraska Public Power District 83/03/07. COLLINS, J T Region 4: Office of Director 7pp 18862 310 24X Fiche 50-298.83/03/07.8306i60466
- 8306160464 Forwards addl GA program, App D info, in response to NRC 830415 request Next formal rev to updated SAR scheduled for Jul 193 PILANT, J M Nebraska Public Power District 83/04/25 COLLINS, J T Region 4, Offlice of Director 72pp 18863, 239, 24X Fiche: 50-298, 83/04/25, 8306160464
- 830.6070386 Forwards request for add1 info re response to enc1 "Control of Heavy Loads at Nuclear Power Plants: Phase i, Nebraska Public Power District: Cooper Nuclear Station " Draft technical evaluation rept enc1 Info requested in 60 days VASSALLO,D 8 Operating Reactors Branch 2 83/05/26 PILANT, J H Nebraska Public Power District 13pp 18814 042 24X Fiche: 50-298, 83/05/26, 8306070386
- --8306070388 "Control of Heavy Loads (C-10), Nebraska Public Power District, Cooper Nuclear Station," draft technical evaluation rept.

 VOBBURY, F., VITO, D., SARGENT, I H Franklin Institute/Franklin Research Center NRC-03-81-130 TER-C5506-346 DRFF 82/12/30 CLEMENBON, F NRC No Detailed Affiliation Given 27pp 18814 055 24X Fiche 50-298,83/05/26,8306070386
- 8306100133 Forwards responses to Apr 1983 request for info re Mark I containment long-term program plant-unique analysis rept loads evaluation (MEDE-24840)
 PILANT, J. N. Nebraska Public Power District 83/06/02
 VASSALLO
- 8306210315 Advises that addl sum required to complete fees for 821124 application for Tech Spec changes. Item 2 re scram discharge vol & Item 3 concerning reactor protection sys each involved separate safety issue DIGOS, R.M. License Fee Management Branch 83/06/15 PILANT, J.M. Nebraska Public Power District. 1p 18922, 357 24X Fiche: 50-298, 83/06/15, 8306210315
- 8306270208 Ack receipt of B30609 response to 820809 order modifying license. Submittal of enalysis of recommendations in LRS Consultant. Inc rept can be extended to 830815 GOLLING. J. T. Region 4. Office of Director. 83/06/21 JONES. C. R. Nebraska Public Power District. 2pp 18991 258 24X Fiche. 50-298, 83/06/21. 8306270208.

- 8304280384 Clarifies 830422 response to request for add1 info re NUREO-0737. Item II B 3, "Post-Accident Sampling Sys." per NRC 830831 telcon In-core temp invicators not in use at plant per Reg Ouide 1 97 & Generic Ltr 82-33 FILANT. J M Nobraska Public Power District 83/06/21. VASSALO, D B Operating Reactors Branch 2 Rpp. 19014 085 24X Fiche 50-298.83/06/21.8306280384
- 8306280444 Requests 60-day extension for responding to 830511 request for add1 info re NUREO-0737. Item II K. 3 28, "Qualification of Automatic Depressurization Bys Accumulators" Extension due to personnel changes & add1 time needed by AE PILANT. J M Nebraska Public Power District 83/06/21 VASSALLO, D 8 Operating Reactors Branch 2 2pp 19020 176 24X Fiche 50-298.83/06/21.8306280444
- G Inspection reports, IE Bulletins & correspondence
- 8306220135 Ack receipt of 830316 ltr t payment of civil penalties imposed by NRC 830218 ltr IE will address issue of matifalse statements

 AXELRAD, J A Director's Office, Office of Inspection and Enforcement 83/03/29 JONES, C R Nebraska Public Power District 2pp 18937 353 24X Fiche 50-298, 83/03/29, 8306220135
- 8306270236 Forwards IE Insp Rept 50-298/83-04 on 830314-17 No noncompliance noted MADSEN, Q L Region 4, Office of Director 83/05/03 PILANT, J M Nebraska Public Power District 2pp 18988-251 24X Fiche 50-290,83/05/03,8306270236
- --8306270237 IE Insp Rept 50-278/83-04 on 830314-17 No noncompliance noted Major areas inspected environ protection program, including organization & administration audits, radiological environ monitoring & nonradiological environ monitoring WILBORN.L., HURRAY.B., WEBTERMAN.T.F. Region 4, Office of Director 83/04/29 7pp 18988-253, 24X Fiche 50-298,83/05/03,8306270234.
- 8306140716 Bubmits followup response to 16 of 17 open items identified in NRC 830217 ltr re IE Emergency Preparadness Appraisal Rept 50-298/82-34 on 821206-10 PILANT, J M Nebraska Public Power District. 83/05/13, MADSEN, G. L. Region 4, Office of Director 7pp 18041 323 24X Fiche 50-298,83/05/13,8306140716
- 830602036B Forwards safety evaluation & notice of granting relief from ABME Code Section XI inservice insp requirements Program required to be revised in 120-month intervals.

 VASSALLO, D.B. Operating Reactors Branch 2 83/03/19 PILANT, J M Nebraska Public Power District 3pp 18715 068 24X Fiche 50-298,83/05/19,8306020568
- --9306020574 Bafety evaluation granting in part & denying in part, requests for relief from inservice insp requirements.

 * Office of Nuclear Reactor Regulation, Director 83/05/19, 9pp 18715.071. 24X Fiche 50-298.83/05/19,8306020368
- --8306020583 "Cooper Nuclear Station Inservice Insp Program," technical avaluation rept.

 * Brience Applications, Inc NRC-03-82-076, 186-028-04
 82/07/02 NRC No Detailed Affiliation Given 36pp
 18715 080 24X Fiche 50-298,83/05/19,8306020568
- --8306020587 Notice of granting in part & denying in part relief from ASME Code Section XI inservice insp requirements. VASBALLO, D B Operating Reactors Branch 2 83/05/19 2pp 18715:118 24X Fiche 50-276,83/05/19,8306020568
- 8304080217 Ack receipt of 830411 ltr informing NRC of steps taken to correct violation & deviation noted in IE Insp Rept 50-299/82-32 MADSEN.9. L Region 4: Office of Director. 83/05/19 filant, J M Nebraska Public Power District ip 18771.156. 24X Fiche 50-298, 83/05/19, 8306080217.
- --8304080219 Responds to NRC 830307 ltr re violation & deviation noted in IE Insp Rept 50-298/82-32 Corrective ections, employee completed medical physicals & monitoring program of physicals established PILANT, J M. Nebraska Public Power District 83/04/1i. MADED, Q L. Region 4, Office of Director 4pp. 18771.157. 24X Fiche 50-298,83/05/19,8306080217.
- 8305110498 IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in Well Logging Davice" Svc list encl.
 TAYLOR, J M. Division of Bafaguards & Inspection Programs (Post 830103). 83/05/26 Consolidated Edison Co. of New York, Inc. 125pp 18831.043 24X Fiche 50-000, 83/05/26, 8305110458.

- B305110460 IE Info Notice 83-34. "Event Notification Info Morksheet"
 Svc list encl
 JORDAN, E L Division of Emergency Preparedness & Engineering
 Response (Post B30103) 93/05/26 Consolidated Editon Co of New
 York, Inc 115pp. 18732 OB5 24X Fiche 50-000.83/05/26.8305110460
- 8305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods Withdrawn at BWRs " Svc list encl JORDAN,E. L Division of Emergency Preparedness & Engineering Response (Post 830103) 83705/31 Consolidated Edison Co of New York, Inc (16pp 18732 208, 24X Fiche: 50-000, 83705/31, 8305110461
- 8306210009 Forwards IE Insp Rept 50~298/83~09 on 830502~06 No noncompliance hoted MADSEN.9 L. Region 4. Office of Director 83/05/31 PILANT, J M Nebraska Public Power District. 2pp 18912 273 24X Fiche: 50~298.83/05/31.8304210009
- --8306210012 IE Insp Rept 50-298/83-09 on 830502-06 No noncompliance noted Major areas inspected: QA/QC administration & design change arograms. Two open items re operator exams & design change identified REDANG.R T. , WESTERMAN.T F Region 4. Office of Director 83/05/25 5pp 18912 275 24% Fiche 80-298/83/05/31/8306210009
- 8306210114 Forwards IE Insp Rept 50-298/83-06 on 830301-0430 No noncompliance noted. MADSEN, 0. L. Region 4: Office of Director 83/05/31 PILANT, J M. Nebraske Public Power District 2pp 18914 Q74. 24X Fiche, 50-298, 83/05/31: 8306210114.
- --8306210129 IE Insp Rept 50-298/83-06 on 830301-0430 No noncompliance noted Major areas inspected operational safety verifications, monthly surveillance & maint observations, IF builetin followup & independent insp effort DUBDIG, D L. WESTERNAN, T F Region 4, Office of Director 83/05/26 12pp 18914 076 24X Fiche 50-298,83/05/31,8304210114
- 8305110464 IE Info Natice 83-36, "Impact of Security Practices on Safe Operations " Syc list encl.

 JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83706/09. Consolidate Edison Co. of New York. Inc. 119pp 18830-280 24X Fichs 50-000-83706/09,8305110464
- 8306160351 Forward: IE Safeguard: Insp Rept 50-298/83-08 on 830405-07 No noncompliance noted MADBEN, G.L. Region 4: Office of Director 83/06/10. FILANT, J M Nebrask: Public Power District 2pp 18857-241 24X Fithe. 80-298
- --8306160362 IE Bafaguards Insp Rept 50-278/83-08 on 830405-07 No noncompliance noted Major areas inspected safeguards contingency plan & response to emergency drill Details withheld (100ERF3 21)

 KELLY, J.A., BROWN, 0 D. WESTERHAN, T.F. Region 4, Office of Director, 82/03/08 lp. 18855.243 24X Fiche: 50-298,83/06/10,8306160351.
- 8305110470 IE Info Notice 83-38, "Defective Heat Bink Adhesive & Beismicslly Induced Chatter in Relays Within Printed Circuit Cards." Byc list encl.
 JCRDAN.E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83705/13 Consolidated Edison Co of New York, Inc. 118pp. 18920,225. 24X Fiche 50-000,83/06/13,8305110470
- 8306090010 IE Info Notice 83-37, "Transformer Failure Resulting From Degraded Internal Connection Cables" Svc list encl JORDAN, EL Division of Emergency Preparedness & Engineering Response (Past 830103) 83706/13 Consolidated Edison Co of New York, Inc 243pp. 18921 001, 24X Fiche: 50-000, 83/06/13, 8306090010.
- 8305110475 IE Info Notice 83-40, "Need to Environmentally Qualify
 Epoxy Grouts & Sealers " Syc list encl
 JORDAN,E.L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/06/22, Consolidated Edison Co. of New
 York, Inc. 115pp 19021 179 24X Fiche 50-000,83/06/22,8305110475
- 8305110477 IE Info Notice 83-41, "Actuation of Fire Suppression Bys Causing Inoperability of Safaty-Related Equipment," Svc list encl. JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/06/22 Consolidated Edison Co. of Naw York, Inc. 120pp. 18997.007, 24X Fishe 50-000,83/06/22,6305110477
- 8305110477 IE Info Notice 83-42, "Reactor Mode Switch Halfunctions,"
 Eve list encl,
 JORDANIE L. Division of Emergency Preparedness & Engineering
 Response (Post 830103). 83/06/23 Consolidated Edison Co. of New
 York, Inc. 116pp 18996:242 24X Fiche: 50-000, 83/06/23, 8305110479

- B3051104B3 IE Info Notice 83-43. "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints " Svc list encl JURDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post B30103) B3/06/24 Consolidated Edison Co of New York, Inc. 116pp 17046 297 24X Fichs 50-000.83/06/24.83051104B3
- R Periodic operating reports & related correspondence
- 8306020148 Monthly operating rept for Mar 1983 W/830405 ltr BALLINGER, P L , LESSOR, L C Nebraska Public Power District 83/04/05 5pp 18690 356 24X Fiche 50-298,83/04/05,8306020148
- B306160477 Monthly operating rept for Apr 1983 W/830502 ltr BALLINGER, P L , THOMASON, P V Nebraska Public Power District B3/05/02 Uffice of Resource Management, Director 5pp 18862 232 24% Fiche 50-296, B3/05/02, 8306160477
- 8304140488 Monthly operating rept for Apr 1983 W/830510 ltr BALLINGER, P. L., THUMASGN.P. V. Nebraska Public Power District 83/05/10 Office of Management and Program Analysis 2pp 18844 134 24% Fiche 50-298,83/05/10,8304160488
- S Reportable occurrences, LERs & related correspondence
- 8304010262 PNO-IV-83-019A on 830517.liconsee committed to perform insp of recirculation sys piping welds including RHR sys inlet & outlet I connections Four welds in need of repair, due to intergranular stress corrosion cracking DUBOIS, D. WESTERMAN.T F Region 4. Office of Director 83/05/27 ip 18672 288 24X Fichs 50-298.83/05/27,6306010262
- 8306130337 LER 83-005/03L-0 on 830505, scram discharge vol drain value CRD-CV-ADV33 failed to close per Tach Specs Caused by grafoil packing working between valve stem & body Valve repacked M/830644 itr THOMASON.P V . BALLINGER.P L Nebraska Public Pawer District 83/06/04 COLLING.J T Region 4, Office of Director 3pp 18822 277 24X Fiche 50-298,83/06/04,8306130339
- 8306160494 LER 83-006/03L-0 on 830509, during performance of Surveillance Procedure 6 3 10 9 1, four RHR mechanical enubbers frozen Caused by RHR shubdoom cooling creating water hammer & overloading snubbers w/830608 ltr
 BALLINGER, PL . THOMASON, PV Nebraska Public Power District 83/06/08 COLLINS, J T Region 4, Office of Director. 3pp 18864 153 24X Ficha 50-298,83/06/08,8306160494
- 8306270163 LER 83-007/03L-0 on 830518 during refueling both standby gas treatment sys diesel generators found inoperable Caused by personnel failure to follow Tech Sper requirements Requirements reviewed & clarified W/830616 ltr WIRE K R . THOMASON P V Nebraska Public Power District 83/06/16 COLLING JT Region 4. Office of Director 3pp 18992 023 24X Fiche 50-298.83/06/16.8306270163
- DGCKET 50-301 PDINT BEACH NUCLFAR PLANT, UNIT 2

 F Security, medical, emergency & fire protection plans
- 8304040156 Provides update to 830428 ltr re mods proposed to support App R exemption requests based on 830523 insp of Unit 2 A05 & A06 switchgear cabinets
 FAY.C W. Hisconsin Electric Power Co 83/05/31 DENFON, H R
 Office of Nuclear Reactor Regulation, Director CLARK, R A
 Operating Reactors Branch 3 2pp 18728 103 24X
 Fiche 50-266,83/05/31,8306060156
- B304090177 Ack receipt of 830408 & 0523 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-246/83-01 & 50-301/83-01 PAPERIELLO, C J Region 3. Office of Director 83/06/06 BURSTEIN 5 Wisconsin Electric Power Co 1p 18796 081 24X Fiche, 50-264, 83/06/06. 8306970177
- --8306090185 Responds to NRC 830308 ltr re violations noted in IE Insp. Repts 50-266/83-01 & 50-301/83-01 Notice of violation inappropriately based in implementation of listed stems fifteen-minute notifications inconsistent w/minor events FAY.C W. Wisconsin Electric Power Co. 83/04/08. KEPPLER, J G. Region 3. Office of Director 3pp. 18796 082 24X Fichs 50-246,83/06/06.8306090177
- 8306130447 Notifies that LASL vital area analysis program personnel will reamalyse original sites visited during early stages of program Revist necessary to gether addl info due to major mods & redirection by NRC HIND, J. A. Division of Radiological & Materials Safety Programs. 83/06/08. BURSTEIN: S. Wisconsin Electric Power Co. 2pp 18821-209 24X Fiche: 50-266,83/06/08.8306130447

- 8306130431 Forwards SER re compliance w/NUREQ-0737. Item III A 1 2. "Min Staffing Levels for Emergency Situations " Provisions for onshift staffing & augmentation acceptable HIND, J A Division of Radiological & Materials Safety Programs 83/66/10 BURSTEIN: S Wisconsin Electric Power Co Spp 18921 215 24X Fiche 50-266.83/06/10.8306130431
- 8306210100 Responds to 830603 ltr advising of status of util request to locate emergency operations facility at corporate headquarters in Milwaukee, MI New communication apparatus & revised procedures enhance semegnency capabilities FAY, C H Misconsin Electric Power Co 83/06/16 DEYOUNO, R C Director's Office, Office of Inspection and Enforcement Spp 18914 138 24% Fiche 50-266,83/06/16,8306210100
- 830.6230356 Ack receipt of NRC B30.603 ltr re status of util request to locate amergency operations facility (EUF) at corporate headquarters in Milwaukee. WI Past communication difficulties unrelated to divided EOF concept
 FAY.C W Wisconsin Electric Power Co B3/06/16 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 2pp 18743 317 24X Fiche 50-266,83/06/16.8306230356
- J Insurance & indemnity information
- 8306070404 Forwards Endorsement 71 to NELIA Policy NF-17B & Endorsement 58 to MAELU Policy MF-53 BUNDAS.W J Wisconsin Electric Power Co 83/05/18 Antitrust & Economic analysis Branch (Utility Finance) 3pp 18741 352 24X Fiche 50-266,83/05/18,8306070404
- P Operating license stage documents & correspondence
- 630&010428 Advises of Pailure to complete installation & place in operation portions of radioactive monituring equipment for compliance w/NURCO-0737.1tem II F I I "Noble Gas Monitoring "Completion expected by 630&300 FAY.C W Hisconsin Electric Power Co 63/05/25 DENTON.H R Office of Nuclear Reactor Regulation, Director CLARK.R A Operating Reactors Granch 3 3pp 18679 321 24X Fiche 50-266,83/05/25.830&010408
- B306070086 Provides results of chloring boron & pH analyses performed for chemical test matrix,per NUREQ-0737. Item II B 3, Criterion 10, to demonstrate analytical capabilities in presence of interfering ion concentrations FAY.C W Wisconsin Electric Power Co B3/06/03 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 18737 350 24X Fiche 50-266, 83/06/03. 8306070086.
- 9306200267 Forwards latest rev of FSAR Section I B. describing QA program, per 10CFR80 54(a)(2) Changes do not reduce QA program commitments previously accepted by NRC Substantive changes summarized FAY, C W Misconsin Electric Power Co 83/06/10 KEPPLER, J Q Ragion J. Office of Director. 36pp 18901 063 24X Fichs 50-266,83/06/10.8306200267
- 8306200260 Informs of further delay in implementing post-TMI-related issues due to delay in shipment of auxiliary safety instrumentation panels from vendor, in response to 830314 order FAY. C.M. Wisconsin Electric Power Co. 83/06/16 DENTON, N.R. Office of Nuclear Reactor Regulation, Director CLARK, R.A. Operating Reactors Branch 3. 4pp. 18701-173 24X Fichs. 50-266, 83/06/16, 8306200260
- 836210091 Requests mod to WPDFS Permit WI-0000957-2, removing pH limitations on sewage treatment plant & retention pond effluents Mod will allow operation of plant & pond w/reduced additions of dissolved solids to environ LINGLE, J W Wisconsin Electric Power Co 83/06/16 Wisconsin State of 3pp 18914 088 24X Fiche, 50-266, 83/06/16, 8306210091
- 8306270275 Requests mod to WPDES Permit WI-0000757-2 to remove pH limitations on sewage treatment plant & retention pond effluents Removal of limits will allow operation w/reduced additions of dissolved solids to environ LINGLE, J W. Wisconsin Electric Power Co. 83/06/16 Wisconsin State of 2pp 18996 170 24X Fichs 50-266.83/06/16,8306270275
- 8304280443 Proposes hardware mod to ensure automatic initiation of auxiliary feedwater flow to affected operating unit w/o operator action Mod only affects motor driven auxiliary feedwater pumps & motor-operated isolation valves FAY, C W. Wisconsin Electric Power Co. B3/06/20. DENTON, H. R. Office of Nuclear Reactor Regulation, Director GLARK, R. A. Operating Reactors Branch 3. 3pp. 17019-174. 24X Ficher 50-266, 83/06/20, 8306280443

- 8306270146 Informs that util response to NUREG-0737. Items II F 1 4, II F 1 5 & II F 1 6 acceptable re installation of containment pressure water level & hydrogen monitoring sys SER encl CLARK. R A Operating Reactors Branch 3 83/06/21 FAY, C W Hisconsin Electric Power Co 8pp 17046 258 24X Fiche 30-266.83/06/21.8306270146
- 8305280397 Requests extension of deadline for certain environ qualification items, listed in SER in Categories II A & II C, until 3 months after meeting held to resolve deficiencies BURSTEIN, B Wisconsin Electric Power Co 83/05/22 DENTON, H R Office of Nuclear Reactor Regulation, Director CLARK, R A Operating Reactors Branch 3 2pp 19001 359 24X Fiche 50-266,83/06/22.6306280397
- G Inspection reports, IE Bulletins & correspondence
- 8305110458 IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in Well Logging Device " Svc list enc!
 TAYLOR: J M Division of Baffguards & Inspection Programs (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 125pp 18831 043 24X Ficher 50-000, 83/05/26, 83051;0458
- 8305110460 IE Info Notice 83-34, "Event Motification Info Worksheet" 8vc list encl
 JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc. 115pp 18732 085 24X Fiche 50-000.83/05/26.8305110460.
- 8305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods Withdrawn at DWRs" Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/31 Consolidated Edison Co of New York, Inc. 114pp 18732, 208 24X Fiche: 50-000, 83/05/31, 8305110461.
- 8306070324 Confirms 830616 mesting w/util at Region III ofc to discuss SALP Interested parties should submit advance notification by 830613
 NORELIUS.C E Division of Project & Resident Programs 93/06/01
 BURSTEIN.S Wisconsin Electric Power Co 1p 18746 080. 24X
 Fiche 50-266, 83/06/01.8306070324
- B306170013 Grants relief from requirement to perform volumetric insp of reactor coolent pump (RCP) casing welds & visual exam of interior surface of RCP casing.providing alternate exam described in safety evaluation performed.per B30163 ltr. CLARK.R. A Dograting Reactors Branch 3. B3/06/01 FAY.C E Wisconsin Electric Power Co 4pp 18707.335 24X Fichs 50-301.63/06/01.8306170013
- --8306170016 Safety evaluation supporting request for exemption from requirement to perform volumetric insp of reactor coolant pump (RCP) casing provided proposed alternative exams substituted

 * NRC No Detailed Affiliation Given 83/06/01 7pp 18907.339 24X Fiche 50-301.83/06/01.8306170013
- --B306170019 Notice of granting of relief from certain requirements of ABME Code Baction XI inservice insp requirements. CLARKIR A Operating Reactors Branch 3. B3/06/01 2pp 18707 346 24X Fiche 30-301.83/06/01.8306170013
- 8304090177 Ack receipt of 830408 & 0523 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-266/83-01 & 50-301/83-01 PAPERIELLO.C.J. Region 3. Office of Director. 83/06/06 BURSTEIN 8 Wisconsin Electric Power Co ip 18776 081, 24X Fiche. 50-266, 83/06/06. 8306090177
- --B306090185 Responds to NRC B30308 ltr re violations noted in IE Insp. Repts 50-266/83-01 & 50-201/83-01, Notice of violation inspragniately based on implementation of listed items. Fiftteen-minute notifications inconsistent w/minor syents. FAY.C W. Wisconsin Electric Power Co. B3/04/08, KEPPLER, J. Q. Region 3, Office of Director 3pp. 18796, 082 24X Fiche 50-266, 83/06/06, 8306090177
- 8306i30i46 Advises that no check valves installed in flow path of cooling water for diesel generators, in response to IE Bulletin 83-03 re check valve failures in raw water cooling sys of diesel generators

 BURBTEIN 8 Hisconsin Electric Power Co 83/06/06 KEPPLER, J 9, Region 3, Office of Director in 18824 277 24X

 Fichs. 50-266, 83/06/06, 8306i30i46
- 8305110464 IE Info Notice 83-36, "Impact of Security Practices on Safe Operations " Svc list encl JURDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/07 Consolidated Edison Co of New York, Inc 117pp 18830 280, 24% Fiche 50-000,83/06/09,8305110464.

- 8306230274 Forwards IE Insp Repts 50-266/83-10 & 50-301/83-10 on 830523-26 No noncompliance noted 8TREETER, J F Region 3, Diffice of Director 83/06/10 BURSTEIN, 9 Misconsin Electric Power Co 2pp. 18945 127. 24X Fiche: 50-266.83/06/10.8306230274
- --8306230279 IE Insp Repts 50-266/83-10 & 50-301/83-10 on 830523-24 No noncompliance mated Major areas inspected nonlicensed personnel training & licensed personnel requalification programs
 HABBER A , HAWKINS F C Region 3, Office of Director 49p 18945:131 24% Fiche 50-266,83/66/10,8306230274
- 8305110470 IE Info Notice 83-38, "Defective Heat Bink Adhesive & Seismicelly Induced Chatter in Relays Within Printed Circuit Cards" Syc list encl.
 JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (
- 8306090010 IE Info Notice 83-37, "Transformer Failure Resulting From Degraded Internal Connection Cables " Svc list encl JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83706/13 Consolidated Edison Co of New York, Inc. 243pp. 18921 001. 24X Firhe 50-000,83/06/13,8306090010
- 8306230260 Ack receipt of 830525 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-266/83-04 & 50-301/83-04.
 NORELIUS, C. E. Division of Project & Resident Programs. B3/06/20.
 BURSTEIN, S. Wisconsin Electric Power Co. ip 18745 072 24%
 Fiche 50-266.83/06/20.8306230260
- --8306230261 Responds to NRC 830425 ltr re violations noted in IE Insp. Repts 50-266/83-04 & 50-301/83-04. Conrective actions. Procedure HP 2 4 re containment entry Check-in/Check-out sys deleted on 830520 FAY.C.W. Hisconsin Electric Power Co 83/05/25 KEPPLER.J. G Region G. Office of Director 2pp 18945:073 24X Fiche 50-266.83/06/20.8306230260
- B305110475 IE Info Notice B3-40, "Need to Environmentally Guslify
 Egoxy Grouts & Bealers " Svc list encl
 JORDAN E L Division of Emergency Preparedness & Engineering
 Response (Past 830103). 83706/22 Consolidated Edison Co. of New
 York, Inc. 115pp 19021 179 24X Fiche 50-000, B3/06/22, B305110475.
- 8305110477 IE Info Notice 83-41. "Actuation of Fire Suppression Sys-Causing Inoperability of Safety-Related Equipment." Syc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Ppst 830103). 83/06/22. Consolidated Edison Co. of New Yorl, Inc. 120pp. 18997 007. 24X Fiche. 50-000, 83/06/22, 8305110477
- 8305110479 IE Info Notice 83-42, "Reactor Mode Switch Malfunctions." Byz list encl. JORDAN, E. L. Division of Energency Preparedness & Engineering Response (Post 830103) 83/06/23 Consolidated Edison Co. of New York, Inc. 116pp 18996, 242 24X Fiche 50-000, 83/06/23, 8305110479.
- 8305110483 IE Info Natice 83-43, "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints " Byo list encl JORDAN: E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/24 Consolidated Edison Co. of New York: Inc. 116pp. 19046-297 24X Fiche 50-000,83/06/24,8305110483.
- R Periodic operating reports & related correspondence
- 8306200137 Monthly operating rapts for May 1983.W/830613 ltr.
 FAY.C W Wisconsin Electric Power Co 83/06/06 9pp 18901-046
 24% Fithe: 50-266,83/06/06,8306200137
- 8. Reportable occurrences, LERs & related correspondence
- 8306060078 NPDES noncompliance; on 830525, daily max pH effluent limit exceeded, Util commenced investigation of incident Ltr to be sent to Dept of Natural Resources outlining results & corrective action PAY.C.M. Wisconsin Electric Power Co. 83/05/27, Wisconsin, State of, Ip. 1878:1022 24X Fiche: 50-266, 83/05/27, 8306060078
- 8306210207 LER 83-007/01T-0. on 830823, higher than normal levels of I-131 in primary coolant prompted investigation of fuel assemblies, Probably caused by fretting at bottom spring clip grid elevation optimized fuel assemblies, 203. W/830806 ltr. FAY. C. M., BURGTEIN, 8 Wisconsin Electric Power Co. 83/06/06. KEPPLERJ. 9 Region 3, Office of Director. Spp. 18918:122 24X Fiche: 50-301,83/06/06,8306210207.

- 8306300058 NPDES noncompliance notification on 830525, pH of retention pord discharge exceeded limits Caused by leaks in reteining board used to sighon sludge from pond to discharge Leaks repaired on 830526
 FAY.C W Wisconsin Electric Power Co 83/06/23 Wisconsin, State of 1p 19120 237 24x Fithe 50-266.83/06/23,8306300098
- DOCKET 50-302 CRYBTAL RIVER NUCLEAR PLANT, UNIT 3
- F Security, medical, emergency & fire protection plans
- 8306140040 Confirms B30124 enforcement meeting at Region II ofc to discuss apparent violations associated w/changing operational mode boron injection flow path surveillance testing & fire barriers Agenda encl 4/o encl D'REILLY, J P Region 2, Office of Director 83/01/19 HANCOCK, J A Florida Power Corp 2pp 18938 335 24% Fiche 50-302,89/01/19,8306140040
- 8304030132 Ack receipt of 830325 ltr requesting waiver of 3 month histus between submittal of procedures generation package & initiation of training on upgraded emergency procedures. Waiver granted STOLZ.JF Operating Reactors Branch 4 83/05/17 WILCUS.W S Flortida Power Corp 2pp 18733 306 24X Fiche 50-302,83/05/17,8306030132
- 8304030293 Informs that NUREQ-0737. Item III A 2 1, "Emergency Preparedness. Upgrade Emergency Plans to App E. 10CFR50." completed Item closed STOLZ, J F. Operating Reactors Branch 4 83/05/17 WILGUS, W S Florida Power Corp 3pp 18734 067 24X Fiche 50-302,83/05/17.
- 8306140447 Ack receipt of 830428 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-302/83-07 DANCE, H C Division of Project & Resident Programs 83/05/27 WILOUS, W B Florida Power Corp ip 18836 349 24% Fiche 50-302,83/05/27,8306140447
- --8306140467 IE Insp Rept 50-302/83-07 on 830129-0228 Noncompliance noted failure to follow Procedure OP-401 when pressurizing core flood tank A on 830225
 SIETKA:TF Region 2, Office of Director BROWNLEE,V L Division of Project & Resident Programs 83/03/28 7pp 18836-355 24X
 Fiche 50-302.83/05/27.8306140447
- 8306070300 Forwards proposed schedule for completing requirements of NUREO-0737. Suppl 1. "Emergency Response Capability," per 830510 meeting Commitments from 830415 ltr remain unchanged WILGUB. W 8 Florida Power Corp 83/05/31 870L2, J F. Operating Reactors Branth 4 8pp 18740 305 24X Fiche 50-302,83/05/31,8306070300
- 8306300225 Application to amend License DPR-72.consisting of Request 109.allowing compensatory action other than establishment of continuous fire watch when penetration fire barrier found monfunctional MESTAFER.0 R Florida Power Corp 83/06/24 DENTON, H R Office of Nuclear Reactor Regulation, Director 6pp. 19119 165 24X Fichs.50-302.83/06/24.8306300225
- --B306300229 Proposed Tech Spets 3/4 7 12 re fire barrier penetrations * Florida Power Corp 83/06/24 2pp 19119 171 24X Fichs:50-302,83/06/24,8306300225
- H General correspondence
- 9306010049 Advises that R Hernan is operating reactor project manager for facility, effective 830516
 FAIRTILE,M B Operating Reactors Branch 4 83/05/19 WILGUS,W S Florida Power & Light Co 2pp 18686 359 24X
 Fiche 50-302,83/05/19,8306010049
- 1. Financial information
- 8306030320 Forwards Annual Financial Repts for 1982 for Florida Progress Corp & Cities of Tallahasses CoalarKissimmee & Leasburg, FL Comprehensive financial info also encl WESTAFER: 0 R Fiorida Power Corp 83/05/26 DENTON, H R Office of Nuclear Reactor Regulation, Director 32ipp. 18706:185 24X Fichs 50-302,83/05/26,8306030320
- --8306030322 Annual Financial Rept.1982 * Florida Power Corp 83/02/18 3pp 18706 332 24X Fich*.50-302.83/05/26.8306030320.
- --8306030323 Annual Financial Rept for FY ending 820930, * Tallehasse.FL 83/05/26 139pp 18707 011, 24X Fiche: 50-302,83/05/26,8306030320,

- --8304030325 Annual Financial Rept For FY ending 820930 * Ocala, FL 83/05/26 153pp 19707 146 24X Fiche 50-302.83/05/26.830400320
- --8306030327 Annual Financial Rept for FY ending 820930 • Kissimmee.FL 83/01/03 160pp 18707 304 24X Fiche 50-302,83/05/26,8306030320
- --8306030328 Annual Financial Rept for FY ending 820930 * Leesburg.FL 83/05/26 161pp 18708 104 24X Fiche 50-302.83/05/26.8306030320
- P Operating license stage documents & correspondence
- B30505051 Addl response to FOIA request for three categories of decoments re FRA of reactor safety study methodology application program repts & interim reliability evaluation program repts Forwards App A documents Search continuing FELTON.J M. Division of Rules and Records 83/04/07 SHOLLY, 8 C Union of Concerned Scientists 3pp 10792 001 24X Fiche: 50-000,83/04/07.8306060051
- --B30A0A006i Statement on background.issues.current status & future action re interim & natl reliability evaluation programs e NRC - No Detailed Affiliation Given B2/12/31 2pp 18752 059 24X Fiche 50-000.03/04/07.8304060051
- --8306050080 Forwards background info re PRA studies. Review of Bandia Natl Labs interim reliability evaluation program studies discussed M/o encl STOLZ, J Operating Reactors Branch 4 93/01/19 LAINAS, O C Assistant Director for Operating Reactors 2pp 18752 200 24X Fiche 50-000,83/04/07,8306060051
- --B3060600B5 Provides info on boron precipitation clogging HP1 lines & failure of operator to switch to hot leg injection in order to flush out boron residue from core during recirculation linfo obtained from FHAs

 DAVIB.8 NRC No Detailed Affiliation Given B3/02/24

 THADANIA NRC No Detailed Affiliation Given &pp 18752 206

 24X Fiche 50-000,83/04/07,8306060091
- 8306020543 Requests responses to 12 open items in encl 830301 & 02 meeting minutes re inservice testing program 870L7. J.F. Operating Reactors Branch 4 83/05/17 WILGUS,W S Fiorida Power Corp 20pp 18715 123 24X Fiche 50-302,83/05/17,8306020543
- B30602018B Forwards Franklin Research Ctr draft technical evaluation rept, "Control of Heavy Loads (C-10). Florada Power Co. Crystal River Unit 3 " Guidance document, "Synopsis of Issues Associated w/NUREO-0612." also entl STCLZ.J F. Operating Reactors Branch 4 83/05/17 WILGUS.W.8 Florida Power Corp. 2pp 18701 072 24x Fiche 50-302.83/05/17. 8306020188
- --8306020196 "Control of Heavy Loads (C-10).Florida Power Co, Crystal River Unit 3," draft technical evaluation rept.
 BDMBERGER, C., VOBBURY, F.W. Franklin Institute/Franklin Research Center NRC-03-81-130 TER-C580A-947 DRFT 83/01/28
 CLEMENBON, F. NRC No Detailed Affiliation Given 39pp
 18701-074 24X Fiche 50-30P.83/05/17.8306020188
- 8306150621 Forwards request for add1 info re 810805 Generic Ltr 81-21, "Natural Circulation Cooldown," Info must be received by 830801 in order to complete review by 830930 STOLZ-J F Operating Reactors Branch 4 83/05/20 WILQUS, W 8 Florids Power Corp App 18067 279 24X Fiche 50-302,83/05/20,83/05/26
- 830A150262 Forwards notice of consideration of issuance of amend to License DPR-72 & proposed no significant hazards consideration determination & opportunity for hearing on 830331 amend application re Cycle 5 reload HERNAN R Operating Reactors Branch 4. 63/05/27, WILOUS, M. 8 Florids Power Corp 2pp 18870 026 24X Fiche 50-302,83/05/27, 8306150282.
- --8306150286 Notice of consideration of issuance of amend to License DPR-72 & proposed no significant hazards consideration determination & opportunity for hearing re Cycle 5 reload, STOL7.J.F. Operating Reactors Branch 4 83/05/31 Bpp 16870 028. 24% Fiche 50-302,83/05/27.8306150282,
- 8306140377 Forwards revised Table D-1, "Preliminary Stress Level Comparison," showing value of atress concentration factor & higher calculated peak stresses. Higher pusk stresses do not affect conclusions from 830506 meeting Meeting summary enci TAYLOR, J H Babcock & Wilcox Co. 83/06/07 MINER, B NRC No Detailed Affiliation Given 2pp 18844 001 24% Fiche, 50-900, 83/06/07, 8306140377

- 8306230427 Forwards analysis rept re fuel failures at facility resulting from combination of indine spixing & overly stringent Tech Specs, in response to 811210 ltr Tech Spec change proposed for RCS indine activity level HESTAFER. OR Florida Power Curp 83/06/10 870L2.J.F. Licensing Branch 4 16pp 18941 343 24X Fiche 30-302, 83/06/10,8306230429
- 8306200033 Advises that final submittal of pump & valve program will be forwarded within 90 days following receipt of SER Final submittal will include additions due to mods accomplished during Refuel IV Rev 4 to program encl WESTAFER, G R Florida Power Corp 83/06/14 DENTON, H. R Office of Nuclear Reactor Regulation, Director 10 19121 081 24X Fiche 50-302.83/06/14.8306200033
- --8306300062 Rev 4 to pump & valve program * Florida Power Corp 83/06/14 274pp 19121 082 24x Fiche 50-302,83/06/14,8306200033
- 8306220049 Forwards Vols 3 & 4 to "Environ Qualification of Class IE Equipment " Data combined w/830520 response to NRC 830111 SER. provides complete response to NRE0-0888. IE Bulletin 79-018 & recently published rule 10CFRS0 49.
 WESTAFER. 0 R Florida Power Corp 83/06/15 BTDLZ. J F Operating Reactors Branch 4 2pp 18928 231 24X Fich m: 50-302,83/06/15,8306220049
- ~~8306220055 Vols 3 & 4 to "Environ Qualification of Class I& Equipment." * Gilbert/Commonwealth Cos 83/06/15 507pp. 18928 233 24X Fiche 50~302,83/06/15,8306220049
- 830.6230.465 Submits add1 info supporting B30.301 Tech Spec Change Request 82 rs Cycle 5 operation w/reactor coolant pump power monitors Response time for pump status based on reactor coolant power pump monitor trip should be 1.44 w HESTAFER, 6 R Florida Power Corp 83/06/17 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 18941 334, 24x Fichs 50-302.83/06/17.8306230465
- 8306240259 Updates status of DAM-1784 re internals botting repair activities B&W stress analysis plus sargins afforded by util repair plans, assure safety of reactor internals for return to full power.

 WESTAFER, O R Florida Fower Corp 83/06/20, 8YOLZ, J F. Operating Reactors Branch 4 Spp 18981 310 24X Fiche: 50-302,83/06/20, 8306240289
- 8306300225 Application to amend License DPR-72, consisting of Request 109, allowing compensatory action other than establishment of continuous fire watch when penetration fire barrier found nonfunctional.

 WESTATER, O.R. Florida Power Corp. 83/06/24 DENTON, H.R. Office of Nuclear Reactor Regulation, Director 5pp 19119, 165. 24%

 Fiche. 50-302, 83/06/24, 8306300225
- --8306300229 Proposed Tech Specs 3/4 7 12 re fire barrier penetrations * Florida Power Corp 83/06/24 2pp. 19119 171 24X Fiche, 50-302, 83/06/24, 8306300225
- G Inspection reports, IE Bulletins & correspondence
- 8306140040 Confirms 830124 enforcement meeting at Region II oft to discuss apparent violations associated w/changing operational mode boron injection flow path, surveillance testing & fire barriers Agenda encl M/o encl.

 D'REILLY, J. P. Region 2, Office of Director. 83/01/19 HANCOCK, J. A. Florida Power Corp. Rpp. 18838-035 24X Fiche-50-302,83/01/19, 8306140040
- 8305110458 IE Info Notice 63-32, "Ruptured Am-241 Bources Contained in Hell Logging Device " Syc list encl TAYLOR.) M Division of Bafeguards & Inspection Programs (Post 830103) 83/05/26 Consolidated Edison Co. of New York, Inc. 125pp 18831 043 24X Fiche.50-000,83/05/26,83051(0458.
- 8305i10460 IE Info Notice 83-34, "Event Notification Info Worksheet." 8vc list encl JORDAN.C.L Division of Emergency Preparedness & Engineering Response (Post 630103) 83/05/26 Consolidated Edison Co. of New York, Inc 115pp 18732-085 E4X Fiche.50-000,83/05/26,8305i10460.
- 8306140447 Ack receipt of 830428 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-302/83-07 DANCE, H C Division of Project & Resident Progress 83/05/27 WILGUS, M B Florids Power Corp ip 18836:349. 24X Ficher 50-302,83/05/27,8306140447

- --8306140451 Responds to NAC 830329 ltr re violations noted in 1E Insp Rept 80-302/83-07 Corrective actions operations personnel reinstructed on importance of using procedures involving ECCB MESTAPER, G R Floride Power Corp 83/04/28 O'REILLY, J P Region 2, Defice of Director 2pp 18836 350 24X Fiche 50-302,83/05/27,8306140447
- --8306140455 Forwards IE Insp Rept 50-302/83-07 on 830129-0228 & notice of violation DANCE,H C Division of Project & Resident Programs 83/03/29 HANCDCK,J A Florida Power Corp 2pp 18836 352 24X Fiche 50-302.83/05/27.8306140447
- --8306140462 Notice of violation from insp on 830129-0228 • Region 2. Office of Director 83/03/29 ip 18836 354. 24X Fiche 50-302.83/05/27.8306140447
- --8306140469 IE Insp Rept 50-302/83-07 on 830129-0228. Noncompliance noted failure to follow Procedure OP-401 when pressurizing core flood tank A on 830225 STETKA, T F Region 2, Office of Director BROWNLEF, V L Division of Project & Resident Programs. 83/03/28 7pp 16836-355 24X Fiche 50-302.83/05/27,8306140447
- 8306290377 Forwards IE Insp Rept 50-302/83-15 on 830502-04 No noncompliance noted DANCE.H C Division of Project & Resident Programs 83/05/27 HILGUS.W B Florida Power Corp 2pp 19059 192 24X Fiche 50-302,83/05/27,8306290377
- --8306270380 IE Insp Rept 50-302/83-15 on 830502-06 No noncompliance noted. Major areas inspected refueling outage radiation protection organization, procedures, advanced planning (ALARA), exposure control & respiratory protection program KARE, J B Region 2, Office of Director BARR.K P. Division of Engineering & Radiological Safety Programs 83/05/26 Bpp 19055 194. 24X Fiche. 50-302.83/05/27,8306290377
- 8305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods Withdrawn at 84Rs " Svc list encl. JORDAN E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/31 Consolidated Edison Co of New York Inc 116pp 18732 208 24X Fiche 50-000,83/05/31,8305110461
- 8306140437 Responds to IE Bulletin 83-03, "Check Valve Failure in Raw Hater Cooling Sys of Diesel Generators "Check valve insp will be performed Euring 830319 refueling outage WILCOUGH 9 Florida Power Corp 83/05/31 0'REILLY, J.P. Region 2, Office of Director Spp 18808 032 24X Fiche.50-302,83/05/31,
- 8305110464 IE Info Natice 83-36, "Impact of Security Practices on Safe Operations " Svc list and JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/09 Consolidated Edison Co of New York, Inc 117pp 18830 280 24% Fichs 50-000,83/06/09,8305110444
- 8305110470 IE Info Notice 83-38. "Defective Heat Sint Adhesive & Beismically Induced Chatter in Relays Within Printed Circuit Cards" Svc list encl JORDAN: E L Bivision of Emergency Preparedness & Engineering Response (Post 830103). B3/06/13 Consolidated Edison Co of New York, Inc 1882 18920 225 24% Fiche 50-000,83/06/13,8305110470
- B306090010 IE Info Notice 83-37, "Transformer Failure Resulting From Degraded Internal Connection Cables " Bvc list enci JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co of New York, Inc. 243pp 18921-001 24X Fiche 50-000,83/06/13,8306090010
- 8306220049 Forwards Vols 3 & 4 to "Environ Qualification of Class IE Equipment" Data combined w/830820 response to NRC 830111 SER. provides complete response to NURCO-058B. IE Bulletin 77-01B & recently published rule 10CFRS0 49. WESTAFER. OR Florida Power Corp. 83/06/15 STQLZ, J.F. Operating Reactors Branch 4, 2pp. 18928-231 24X Fiche. 50-302, 83/06/15, 8306220049.
- --8306220055 Vols 3 % 4 to "Environ Qualification of Class IE Equipment." # Gilbert/Commonwealth Cos 83/06/15 507pp 18928 233 24X Fiche. 50-302, 83/06/15, 8306220049
- 8303110475 IE Info Notice 83-40, "Need to Environmentally Qualify
 Epoxy Grouts & Bealers " Svc list and JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Poxt 830103) 83/06/22. Consulidated Edison Co. of New York Inc 115pp 17021 179 24X Fiche 50-000,83/06/22,8305110475

- B305110477 IE Info Notice 83-41, "Actuation of Fire Suppression Sys Causing Inoperability of Safety-Related Equipment" Syc list enc! JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83706/22 Consolidated Edison Co. of New York, Inc. 120pp 18997 007 348 Fiche 50-000,83706/22,8305110479
- \$305110479 IE Info Notice \$3-42, "Reactor Mode Switch Malfunctions"
 Svc list encl
 JORDAN & L Division of Emergency Preparedness & Engineering
 Response (Post 8301031 83/06/23 Consolidated Edison Co of New
 York, Inc 116pp 18996 242 24% Fiche 50~000,83/06/23,8305110479
- 8305110483 IE Info Notice 93-43, "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints " Svc list encl JURDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/24 Consolidated Edison Co of New York, Inc 116pp 19046 297 24X Fiche 50-000,83/06/24.8305110483
- R Periodic operating reports & related correspondence
- 8306170221 Suppl to "Annual Environ Operating Rept Radiological for 1992" W/830613 ltr MCKEE.PF. REUSCHAEFER.E. WESTAFER, G.R. Florida Power Corp 83/06/07 O'/REILLY.J. F. Region 2. Office of Director 108pp 18883 299 24X Fichs 50-302,83/06/07,0306170221
- 8304230449 Monthly operating rept for May 1983 W/830413 BOGART.D S, WESTAFER: G R Florida Power Corp B3/04/13 DEYOUNG.R C Director's Office Office of Inspection and Enforcement Spp 18742 O79 24X Fichs 50-302,83/04/13.8304230449
- S Reportable occurrences, LERs & related correspondence
- 8306070273 LER 83-022/01T-0 on 830516.two pinhole leaks found in piping on downstream side of two Nuclear Svr HX discharge isolation valves Caused by insufficient surveillence & design inadeguacy on inner PVC liner W/830527 ltr BUFE, J L . WESTAFER, G R Floride Power Corp 83/05/27 D'REILLY, J P. Region 2. Office of Director 4pp 18744 078 24X Fiche 50-302,83/05/27,83060702/3
- 8306070165 LER 83-021/03L-0 on 830504, three hydraulic snubbers failed functional test during Dec outage & 107 snubbers failed test during Refuel IV Caused by spal failure & valve assembly contamination All snubbers modified W/830531 itr TAYLOR, 8 C , WESTAFER, 9 R Florida Power Corp 83/06/01 D'REILLY, J P Region 2, Office of Director 13pp 18809 186 24% Fiche 50-302, 83/06/01, 8306070165
- V Operator Examinations
- 9306140353 Responds to B2121/ request for renewal of MP Holmes license which expired on B21214 Written exam will be waived upon request Only oral exam required since MP Holmes passed annual written requalification exam

 DANCE, H C Division of Project & Resident Programs 83/03/30 HANCOCK, J A Florida Power Corp ip 18832 151 24X Fiche. 50-302,83/03/30,8306140353
- 8304140347 Advises that written & oral operator licensing exams scheduled for wk of 830725 Approved ref math, as agreed in telcon, must be furnished by 820531 Administration of operator licensing written exam procedures encl DANCE, H C Division of Project & Resident Programs 83/05/24 WILCUS, W S Florida Power Corp 3pp 18832 183 24X Fiche 50-302,83/05/24,8306140347
- DOCKET 50-304 ZION NUCLEAR POWER STATION, UNIT 2
 F Security, medical, emergency & fire protection plans
- 8304210314 FOIA request for NRC records re security violations & safeguards events at nuclear facilities ODLDENBERG, 6 Scripps-Howard Newspapers 83/04/22 FELTON, J M Office of Administration 2pp 18925 198 24X Fiche 50-000,83/04/22,8304210314
- 8306210306 Partial response to FOIA request for NRC records re security violations & safeguards events at nuclear facilities Repts listed on App A available in PDR Search for add documents subject on the subject continuing FELTON. J M Division of Rules and Records 89/05/16 GOLDENSERG. G Scripps-Howard Newspapers 2pp. 18925 196 24X Fiche. 50~000.83/05/16.8306210306

- B306130294 Forwards FEMA final exercise evaluations of offsite smargency preparedness exercise conducted on 810729,1007 & B30118 No major exercise deficiencies noted HIND. J A Region 3. Office of Director B3706/09 REED. C Commonwealth Edison Co 2pp 18823 3J4 24X Fiche 50-295,83/06/09, 8204479304
- P Operating license stage documents & correspondence
- 9306030508 Forwards draft "Cuntrol of Heavy Loads (C-10). Zion Station Units 1 & 2," per responses to NRC 800731 request for review of gravisions for handling & control of heavy loads in conformance w/N/REG-0612 Addl guidance encl VAROA. S A. Operating Reactors Branch 1 83/05/19 FARRAR, D L Commonwealth Edison Co. 15pp 18735 006 24X Fiche 50-295, 83/05/19,8306030508
- --8306030512 Draft "Control of Heavy Loads (C-10), Zion Station Units 1 & 2:" technical evaluation rept BARGENT, I H. VITO, D. J. Franklin Institute/Franklin Research Center NRC-03-BI-130 TER-05906-403/404 DR 82/11/30 CLEMENBON, F. NRC No Detailed Affiliation Qiven 30pp 18735 021 24X Fiche 50-295,83/05/17,830603050B
- 8306090194 Discusses util interpretation of 10CFRS0 49, "Environ Qualification of E)ectrical Equipment Important to Safety for Nuclear Power Plants " Intent of rulemaking is to require upgrade program for replacement equipment not parts FARRAR.D L. Commonwealth Edison Co. 83/06/03 DENION H.R. Diffication of Nuclear Reactor Regulation. Director 3pp 18796 090 24X Fiche. 50-000, 83/06/03, 8306090194
- 8304210073 Suppls 030513 Itr re NUREO-0737. Item II F I 5. "Containment Water Lavel Monitoring Sys " Lower value of transmitter error should be used for calculating of overall loop uncertainties

 LENTINE, F O Commonwealth Edison Co 03/06/15 DENTON. H R Office of Nuclear Reactor Regulation, Director Ip 18912 291 24X Fiche 50-295.83/06/15.8306210073
- 8306230219 Forwards add1 info on control room human factors items re nuisance alarms, prioritization of multiple alarms & communications w/breathing apparatus, in response to 830511 talcon
 LENTINE, F G Commonwealth Edison Co 83/06/16 DENTON, H R Office of Nuclear Reactor Regulation, Director 19pp 18945-264 24X Fiche 50-298,83/06/16,8306230219
- @ Inspection reports, IE Bulletins & correspondence
- 8304060218 Forwards IE Insp Repts 50-295/83-04 & 50-304/83-04 on 830305-0429 & notice of violation 9HAFER: W D Region 3, Office of Director 83/05/19 REED, C Commonwealth Edison Co 2pp 1872/306 24X Fichs 50-295.83/05/19, 8306060218
- --8306040219 Notice of violation from insp on 830305-0429 SMAFER, WD Region 3, Office of Director 83/05/19 2pp 18727 308 24X Fiche 50-295,83/05/19,8306060819
- --B306040221 IE Insp Repts 50-295/83-04 & 50-304/83-04 on 830305-0429 Noncompliance noted failure to provide procedures to account for plant condition changes after instrument calibr & failure to icep high radiation door locked MATERS.JR. DUNAWAY.FR. HARTMANN.PL. Region 3. Office of Director B3/05/18 12pp 18/27 310 24X Fiche 50-295.83/05/19, 8306040218
- 8305110458 IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in Hell Logging Device" Syc list encl TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 125pp 18831 043 24X Fiche 50-000,03/05/26,8305110458
- B305110460 IE Info Notice 83-34, "Event Notification Info Workshoet" Svc list onc) JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co. of New York: Inc. 115pp 18732 08b 24X Fiche 50-000,83/05/26.8305110460
- B305110461 IE Info Notice B3-35, "Fuel Movement W/Control Rods Withdrawn at BMRs " Syc list encl JORDAN E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/31 Consolidated Edison Co. of New York, Inc. 116pp 18732 208 24X Fichs 50-000,83/05/31,8305110461
- 8306090125 Confirms 830602 telcon request for 1-wk extension to reply to notice of violation & proposed imposition of civil penalty Request granted KEPPLER, J. 9 Region 3. Office of Director 83/06/06 O'CONNOR, J. Commonwealth Edison Co. 1p 18/95 290 24X Fiche 50-29b,83/06/06.8308090125

- 8306100094 Forwards response to IE Bulletin 83-03 re diesel generator cooling water check valves Plants utilize Mission Duo-Check valves employing hings-to-pin design for protection against vibration-induced failure
 BARNES, P. L. Commonwealth Edison Co. 83/06/07 KEPPLER, J. Q. Region 3, Defice of Director 7pp. 18802 238 24X Fiche. 50-000, 83/06/07, 8306100094
- 830&170380 Forwards response to IE Bulletin 83-03 re diesel generator cooling water check valves Valves at Dresden & LaBalls acceptable w/o further insp Rept on valve failures at Quad Cities will be submitted within 90 days of insp completion BARNES, P.L. Commonwealth Edison Co. 83/06/07 KEPPLER, J.Q. Region 3, Office of Director 7pp 18880 211 24X Fiche 50-000, 83/06/07, 8306170380
- 8305110464 IE Info Notice 83-36, "Impact of Security Practices on Safe Operations " Svc list encl JORDAN, E. L. Division of Emergency Preparadness & Engineering Response (Post 830103) 83706/09, Consolidated Edison Co. of New York, Inc. 119pp 18830 280 24X Fiche 50-000,83/06/09.8305110464
- 8305110470 lE Info Notice 83-38, "Defective Heat Bink Adhesive & Beismicelly Induced Chatter in Relays Within Printed Circuit Cards." Syc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co of New York, Inc 118pp 18920 825 24X Fiche 50-000,83/06/13,8305110470.
- 8306090010 IE Info Notice 83-37, "Transformer Failure Resulting From Degraded Internal Connection Cables" Svc list encl JURDAN.E L Division of Emergency Preparedness & Engineering Response (Fost 8330103) 83706/13 Consolidated Edison Co of New York, Inc 243pp 18921 001 24X Fiche.50-000.89/06/13,8306090010.
- 8306170277 Forwards addendum consisting of confirmatory measurements program data sheet for IE Insp Repts 50-295/82-30 & 50-304/82-27 re 8r-87 % 8r-90 Info will close Open Items 295/82-30-0 & 304/82-27-01 PAPERIELLO.C J Region 3, Office of Director 83/06/14 REED.C Commonwealth Edison Co 3pp 18878 268 24% Fighs 50-295,83/06/14,8306170277
- 8306220026 Ack receipt of 830525 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-295/83-07 & 50-304/83-06 PAPERIELLO, C J Region 3. Office of Director 83/06/17 REED, C Commonwealth Edison Co ip 18928-210 24X Fiche 50-295,83/06/17,
- 8305110475 IE Info Notice 83-40, "Need to Environmentally Qualify
 Epoxy Grouts & Bealers " Byc list encl
 JORDAN, E. L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/06/22 Consolidated Edison Co. of New
 York, Inc. 115pp 19021 179 24X Fiche 50-000,83/06/22,8305110475
- 8305110477 IE Info Notice 83-41, "Actuation of Fire Buppression Sys Causing Inoperability of Bafety-Related Equipment " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/22 Consolidated Edison Co. of New York, Inc 120pp 18997 007 24X Fiche 50-000,83/06/22,8305110477.
- 8305110479 IE Info Notice 83-42, "Reactor Mode Switch Malfunctions "
 Syc list encl
 JORDAN.E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83706/23 Consolidated Edison Co of New
 York, Inc. 116pp 18976 242 24X Fiche. 50-000, 83706/23, 8305110479
- 8306300197 Ack receipt of 830616 ltr informing NRC of steps taken to correct violations noted in IE insp Repts 50-295/83-04 & 50-304/83-04.

 SHAFER, W. D. Region 3. Office of Director 83/06/83 REED, C. Commonwealth Edison Co. ip 19122 183 24X Fiche 50-295, 83/06/23, 8306300197
- ---B306300216 Responds to NRC 830519 ltr re violations noted in 1E Insp Repts 50-295/83-04 & 50-304/83-04 Corrective actions, entire Radiological Protection Procedure 1190-1 will be kept at work site w/calibr sheet FARRAR, D L Commonwealth Edison Co B3/06/16 KEPPLER, J O. Region 3, Office of Director 3pp 19122 184, 24X Fiche 50-275,83/06/23,8306300197
- 8305110483 IE Info Notice 83-43, "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints," Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83706/24 Consolidated Edison Co of New York: Inc 116pp 17046 277 24X Fiche. 50-000:83/06/24.8305110483.

- 8306280377 Forwards response to Item 4 of IE Bulletin 92-02, "Degradation of Threaded Fasteners in RCPB of PHR Plants "
 Insp requirements included in all appropriate maint procedures
 BARNES,P.L. Commonwealth Edison Co. 83/06/24 KEPPLER.J 0 Region
 3. Office of Director 4pp 19014 087 24% Fiche: 50-304.83/06/24, 8306280377
- 8306270329 Forwards "Inservice Insp & Test Program, Second Interval, Zion Nuclear Power Station "Programs applicable for 120-aonth interval beginning 831231 for Unit 1 & 840719 for Unit 2.
 LENTINE, F Q. Consolidated Edison Co. of New York, Inc. 83/06/27 DENTON, N. 0ffice of Nuclear Reactor Regulation, Director 1p. 19054:027 244 Fishe 50-275.83/06/27,8306290339
- --8306290335 "Inservice Insp & Test Program, Second Interval, Zion Nuclear Power Station "
 * Consolidated Edison Co. of New York, Inc. 83/06/27 358pp 19054-028 24X Fiche 50-275,83/06/27,8306290329
- R Periodic operating reports & related correspondence
- 8304070233 "Zion Nuclear Generating Station," second evaluation, # Institute of Nuclear Power Operations 83/04/30 38pp 18741.117. 24X Fiche 50-295.83/04/30.8306070233
- 8306140412 Monthly operating repts for May 1983 W/830408 ltr AUSTIN.O., GRAESEER.K.L. Commonwealth Edison Co. 83/06/08 Director's Office of Inspection and Enforcement 12pp. 18838 069 24X Fiche: 50-295.83/06/08.8306140412
- 8 Reportable occurrences, LERs & related correspondence
- 8306060250 LER 83-013/017-0 on 830512 during air pressure test of one cooling bank on 2C reactor containment fan cooler.six leaking tubes verified Caused by internal pitting Two tubes removed for visual & metallurgical axam W/830526 ltr. WOODS, J., GRAESSER, K.L. Commonwealth Edison Co. 83/05/26 KEPPLER.J O. Region 3. Office of Director 3pp 18727 229 24X Fiche: 50-304, 83/05/26, 8306060250
- 8304040148 LER 83-014/C3L-0 on 830427, during visual insp. snubbers MSRS 150-2.MSRS 150-11 & SIRS 2135 failed to lock up in bension &/or compression Caused by hydraulic fluid leak due to poor seal condition W/830527 ltr oRAEBSER, K L., PETROMSKI, S. E. Commonwealth Edison Co. 83/05/27 KEPPLER, J G. Region 3, Office of Director. 3pp. 18719 228 24; Fichs. 50-304, 83/05/27, 8304040148
- 8306210234 LER 83-015/03L-0. an 830516 & 19. pressurizer level channels 2L-460 & 2L-461 found out of tolerance Caused by transmitter (Barton Hodel 386) drift. Transmitters recaller & will be environmentally qualified W/830613 ltr. CANTHELL.PF ORAESSER,K L Commonwealth Edison Co 83/06/13 KEPPLER,J 9 Region 3. Office of Director. 2pp 18917-001 24X Fiche: 50-304,83/06/13.8306210234.
- 8306220060 PNO-III-B3-044. on B30614, radiation chemistry lab foreman found shot twice No known connection exists between apparent surder & amployment BOYD. D. BHAFER, W. Region 3. Office of Director 63/06/15 jp 18730, 174 24% Fiche: 50-275, 83/06/15, 8306220060
- 8306230438 PNO-III-83-048 on B30615, contractor amplayee reentered plant unescorted after triggering contamination monitor on exiting plant. Employee instructed to proceed to radiation protection of clocated in vital area for decontamination CREED. J. MILLER, J. HIND. J. Region 3. Office of Director 83/06/17. ip 18942.078 24X Fiche 50-295, 83/06/17, 8306230438
- 830A270221 LER 83-016/03L-0 on 830619, while at 89% power, 28 M8IV continuity lights for train A & B would not light Caused by loose fuse clips due to repeated use Clips tightened Clip clamps will be instabled W/830A20 ltr.

 OAJIC, Z., GRAESSER, K. L. Commonwealth Edison Co. 83/06/20 KEPPLER, J. Q. Region 3, Office of Director. 2pp. 18990 219 24%

- --830616004B Public version of revised Radiological Emergency Response Plan Implementing Procedures EP-ENV 5A, "LCS-1 Operation," & EP-ENV-5B, "MS-3 Operation " W/830429 ltr Revised index
 - enci LUONIA-C K. OFFSLER.C W Washington Public Power Supply System 83/04/29 DENTON.H R Office of Nuclear Reactor Regulation. Director 17pp 18892 310 24% Fiche 50-305.83/06/06.8306160043
- B306:130306 Advises that Rev 1 to emergency plan meets planning stds of iOCFR50 47(b) & requirements of App E to IOCFR50 Any proposed changes to plan should be provided to NRC per 1OCFR50 54(q)
 PAPERIELLO,C J Region 3, Office of Director B3/06/10
 OIESLER,C H Wisconsin Public Service Corp 1p 18823 328 24X
 Fichs 50-305,83/06/10,8306130306
- J Insurance & indemnity information
- 8306070070 Forwards Endorsements 61 & 48 to NELIA Policy NF-204 & MAELU Policy MF-71, respectively GIESLER.C W Wisconsin Public Service Corp 83/06/01 DINIT2, I Antitrust & Economic analysis Branch (Utility Finance) 3pp 18740 090 24% Fichs 50-305,83/06/01,8306070070
- P Operating license stage documents & correspondence
- 8306010065 Forwards "Control of Heavy Loads (C-10), Kewaunes Nuclear Power Plant," draft technical evaluation rept for review & comment Conference call to discuss rept scheduled for wk of 830610 VAR9A: 9 A. Operating Reactors Branch 1 83/05/14 GIESLER, C W Hisconstin Public Bervice Corp 2pp 18695 332 24X Fiche 50-305,83/05/14:8306010065
- --B305200714 "Control of Heavy Loads (C-10), Kewaonea Nuclear Power Plant," draft technical evaluation rept VOBBURY, F W. BCMBERGER, C. Franklin Institute/Franklin Research Center NRC-03-B1-130 TER-C5506-363 DRFY B3/04/29 SARGENT, I H. NIKC No Detailed Affiliation Given 38pp 18696 001 24X Fiche 50-305,83/05/16,8306010065
- 830602064B Forwards list of outstanding amends under License DPR-43-per telcon. Subsequent amend requests to be sent directly from util M/o sec! GROTENHUIS. A Operating Reactors Branch ! 83/05/19 RIEDERER. C Hisconsin Public Bervice Corp 2pp 18716 275 24X Fiche 50-305,83/05/19.830602064B
- 8306020395 Forwards Rev 1 to 830506 proposed change to Tech Specs correcting potential deficiency re containment cooling sys operability OIESLER.C W Wisconsin Public Service Corp 83/05/27 VARGA,S A Operating Reactors Branch 1 App 19695 167 24X Fiche 50-305,83/05/27.8306020395
- B306100189 Restates previous commitment to install redundant radiation monitor in control room HVAC sys.per NVREG-0737.Item
 III D 3 4, "Control Room Habitability," in response to
 B30401 request
 OIEBLER.C W Wisconsin Public Service Corp B3/06/06 VARGA,S A
 Operating Reactors Dranch 1 5pp 13805 257 24X
 Fiche 50-805.83/06/06.8306100189
- 830614004B Forwards revised pages to Cycle IX reload safety evaluation Pages reflect redesigned core pattern
 OIESLER: C W Wisconsin Public Service Corp 83/06/10 VARGA, S A Operating Reactors Branch I 10pp 18838, 290 24X
 Fiche 50-308,83/06/10,830614004B
- 8304200102 Submits achedule for resolution of TMI Action Plan Item II K 3 5, "Automatic Trip of Reactor Coolant Pumps," in response to Generic Ltr 83-10D Pump trip setpoint procedures will be implemented by end of 1985 refuel outage GIESLER, C H Wiscensin Public Service Corp 83/06/15 EISENHUT, D 0 Division of Licensing 4pp 18903 330 24X Fiche 50-305.83/06/15.8306200102
- 8306280373 Rev to application for Amend 54 to License DPR-43.changing Tech Specs re offsite organization for plant mgt & technical support Revised figure encl
 QIEBLER, C W Wisconsin Public Service Corp 83/06/24 DENTON, H R
 Office of Nuclear Reactor Regulation, Director. 2pp 19001 278
 24X Fiche. 50-305, 83/06/24, 8306280373
- --8306280378 Revised Tech Spec 6 2 i re offsite organization for plant mgt & technical support * Wisconsin Public Service Corp 83/06/24 ip 19001-280 24X Fichs 50-305.83/06/24,8306280373

- G Inspection reports, IE Bulletins & correspondence
- 8305110458 IE Info Notice 83-32, "Ruptured Am-241 bources Contained in Meil Logging Device" Syc list encl
 TAYLOR. J M Division of Safeguards & Inspection Programs (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc
 125pp 16831 043 24X Fiche 50-000,83/05/26,8305110458
- 8305110460 IE Info Notice 83-34. "Event Notification Info Worksheet" Svc list encl
 JORDAN, E. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/05/26 Consolidated Edison Co of New
 York, Inc. 115pp 18732 085 24X Fiche 50-000,83/05/26,8305110460
- 8306130330 Forwards IE Insp Rept 50-305/83-06 on 830418-22 No noncompliance noted PAPERIELLO.C J Division of Emergency Preparedness & Operational Support. 83/05/27 GIESLER.C W Wisconsin Public Service Corp 2pp 18822 262 24X Fiche 50-305/83/05/27/8306130330
- --8306130333 IE Insp Rept 50-305/83-06 on 830418-22 No noncompliance noted Major areas inspected ALARA exposure controls parting & controls transportation activities, TMI action items & effluent control instrumentation PAUL.R A . GRANT, W B . GREGER, L R Region 3, Office of Director 83/05/24 9pp 18822 264 24X Fiche 50-305,83/05/27.8306130330
- 8305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods Withdrawn at BWRs" Svc list encl JORDAN, EL Division of Emergency Preparedness & Engineering Response (Post 830103) 63/05/31 Consolidated Edison Co of New York Inc 116pp 18732 208 24X Fiche 50-000,83/05/31,8305110461
- 8306170056 Advises that no check valves installed in steam generator cooling water piping flow path in response to IE Rulletin 63-03. "Check Valve Failures in Raw Water Cooling Sys of Diesel Generators."

 OIESLER.C W Wisconsin Public Service Corp. 83/06/07 KLPPLER, J 0 Region 3, Office of Director. ip. 18078 301 P4X

 Fiche 50-305,83/06/07.8306170056
- 8306160617 Forwards response to two items of noncompliance identified in IE Insp Rept 50-305/83-03 & update on status of commitments to ensure quality of radiological measurement program OIESLER, C. W. Hisconsin Public Service Corp. 83/06/08 HIND, J.A. Division of Emergency Preparedness & Operational Support 5pp 18866-126 24X Fiche 50-305/83/06/08/8306160619
- 8305110464 IE Info Notice 83-36, "Impact of Becurity Practices on Bafe Operations " Syc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/09 Consolidated Edison Co of New York, Inc 119pp 18830 280 24% Fiche 50-000,83/06/09,8305110464
- 8305110470 IE Info Notice 83-38, "Defective Heat Sink Adhesive & Seismically Induced Chatter in Relays Within Printed Circuit Cards." Syx list encl JDRDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co. of New York, Inc. 118pp 18920 225 24X Fiche 50-000,83/06/13,8305110470
- 8304090010 IE Info Notice 83-37, "Transformer Failure Resulting From Degraded Internal Connection Cables." Byo list encl JORDAN.E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/13 Consolidated Edison Co. of New York. Inc 243pp 18921 001. 24X Fiche 50-000, 83/04/13, 8304090010
- 8304210037 Ack receipt of 830511 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 80-305/83-01.
 Nancompliance Item 1 a warranted & assigned appropriate severity level Item 2 recategorized as Severity Level V. NORELIUS, C E Division of Project & Resident Programs. 83/06/14 0165LER.C.W Warchesin Public Service Corp 2pp 18912-339 24x Fiche 50-305.83/06/14.8306210037
- --8306210041 Responds to NRC B30411 ltr re violations noted in IE Insp Rept 50-305/83-01 Corrective actions personnel reinstructed in tagging requirements Contends that Item 1 a warrants no noncompilance action & Item 2 should be Severity Level V. GIEBLER: G W Misconsin Public Bervice Corp. 83/05/11 NORELIUS, C E. Division of Project & Resident Programs. 14pp 18912-341 24X Fiche. 50-305.83/06/14,8306210037
- B306270329 Forwards IE Insp Rept 50-305/83-04 on B30303-0429 & notice of violation.
 NORELIUS, C E Division of Project & Resident Programs B3/06/17,
 OIESLER, C. H. Misconsin Public Service Corp 2pp. 18993, Q54. 24X
 Ficher 50-305, B3/06/17, 8306270329

- --8306270335 Notice of violation from insp on 830303-0429 NORELIUS, C E Division of Project & Resident Programs 83/06/17 2pp 18993 056 24X Fiche 50-305, 83/06/17,8306270329
- --8306270341 IE Insp Rept 50-305/83-04 on 830303-0427 Noncompliance noted limiting condition for operation exceeded for RCS leakage detection NELSON,R L , JACKIM I N Region 3, Office of Director 83/06/17 9pp 18993 058 24X Fiche 50-305,83/06/17,8306270329
- 8305110475 IE Info Notice 83-40. "Need to Environmentally Qualify
 Epoxy Grouts & Sealers " Syc list enc!
 JORDAN: E.L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/06/22 Consolidated Edison Co. of New
 York: Inc. 115pp 19021 179 24X Fiche 50-000:83/06/22:8305110475
- 8305110477 IE Info Notice 83-41, "Actuation of Fire Suppression Bys Causing Inoperability of Safety-Related Equipment " Bvc list enc! JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/22 Consolidated Edison Co of New York, Inc 120pp 18979 007 24X Fische 50-000,83/06/22,8308110477.
- 8305110477 IE Info Notice 83-42, "Reactor Mode Switch Malfunctions "
 Byc list encl
 JORDAN,E.L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/06/23 Consolidated Edison Co. of New
 York, Inc. 116pp 18996-242 24X Fiche 50-800,83/06/23,8305110479.
- 8305;10483 IE Info Notice 83-43. "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints " Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/24 Consolidated Edison Co of New York, Inc 116pp 19046 297 24X Fiche 50-000.83/06/24.8305110483
- R Periodic operating reports & related correspondence
- 8304140001 Monthly operating rept for May 1983.W/830610 ltr. RUITER, G H , GIEBLER, C W Wisconsin Public Bervice Corp B3/06/01. Director's Office Office of Inspection and Enforcement App 18840 201 g4% Fichs 80-305.83/06/01,8306140001
- 8 Reportable occurrences, LERs & related correspondence
- 8306270110 LER 83-013/03L-0 on 830520, App J Type B & C local leak rate testing identified six containment isolation valves w/ unacceptable as-found leakage Cause not stated. Valves repaired & tested satisfactorily W/830617 ltr
 BERNHOFT, B, HILTUNEN, E, QIEBLER, C W Wisconsin Public Service Corp. 83/06/17 KEPPLER, J G. Region 3, Office of Director Spp. 18988, 060 24X Fiche 50-305, 83/06/17, 8306270110
- DOCKET 50-306 PRAIRIE ISLAND NUCLEAR STATION, UNIT 2

 F. Security, medical, emergency & fire protection plans
- 8304100059 "Control Room Design Review Flam Prairie Island Nuclear Generating Flant," response to Generic Ltr 82-33, Suppl 1 to NUREO-0737 W/830527 ltr MUSOLF. D Northern States Power Co 83/05/27 47pp 18802 123. 24% Fichs. 50-282, 83/05/27, 8306100059
- 8306090237 Forwards "Emergency Operating Procedures Generation Package." in response to Generic Ltr 82-33,8uppl 1 to NUREG-0737.

 MUBDLF.D Northern States Power Co. 83/05/31. Office of Nuclear Reactor Regulation, Director 1p 18797 001 24X

 Fiche 50-282,83/05/31,8306090237.
- --8306090239 "Emergency Operating Procedures Generation Package."

 * Northern States Power Co 83/05/31 16pp 18797:002. 24X
 Fiche 50-282.83/05/31.8306090237
- 8306090263 Forwards Rev 9 pages for security plan. Pages withheld (ref 100FR73).

 MUSDLF, D. Northern States Power Co 83/06/06 Office of Nuclear Reactor Regulation, Director, ip 18795 279 24x

 Fiche: 50-282, 83/06/06, 8306090263.
- 8306230073 Releases public version of revised emergency plan implementing procedures FELTON, J. H. Division of Rules and Records. 83/06/06 Document Management Branch 1p. 18782-186, 24X Fiche: 50-282,83/06/06,8306230073,

- --830A230079 Forwards public version of revised emergency plan implementing procedures, including Procedures F3-3 re responsibilities during notification of unusual event & F3-13 re offsite dose calculation
 MARD, E.C. Northern States Power Co. 83/05/16 Region 3, Office of Director ip 18982 187 24X Fiche 50-282,83/06/06,830A230073
- --B306230087 Public version of revised emergency plan implementing procedures, including Procedures F3-3 re responsibilities during notification of unusual event F3-13 re offsite dose calculation & F3-14 2 re operations emergency surveys SCHUELKE, D A Northern States Power Co 63/04/26 Region 3, Gffice of Director 71pp 18982 188 24X Fiche 50-282,83/06/06,8306230073
- 830&280459 Informs that operational data for completion of HEPA filtration sys extended to 831001 due to difficulty in adopting ventilation sys to accommodate demands of HEPA filtration per Suppl i to NUREO-0737 MUSOLF.D. Northern States Power Co 83/06/20 Office of Nuclear Resolution. Director ip 19018 328 24X Fiche 50-000,83/06/20.8306280459

P. Operating license stage documents & correspondence

- 8306010349 Forwards updated equipment lists reflecting plant mode, current NRC views & licensee continuing review in response to 100FR60 49. "Environ Guallication of Electrical Equipment Important to Safety for Nuclear Power Plants." MUSCLF.D M. Northern States Power Co. 83/05/19. Office of Nuclear Results of Repulsition, Director 60pp. 18680 091 24X Fiche. 50-282.63/05/19.8306010349
- 830.6090230 Bubmits 30-day response to NRC 830.425 safety evaluation of environ qualification of safety-related electrical equipment Facility can operate safety while environ qualification deficiencies being resolved MUSDLF, D. Northern States Power Co. 83/03/27 Office of Nuclear Resolved R
- 8306200281 Advises that justification for continued operation resolvent qualification of safety-related electrical equipment acceptable. Rosemount transmitters 1152 Series D reclassified from NRC Category II B to II C.

 CLARK, R A Operating Reactors Branch 3 83/06/03 MUSULF, D M Northern States Power Co 2pp. 18919 264 24X

 Fiche. 50-282, 83/06/03, 8306200281
- --8306200283 Safety evaluation supporting justification for continued operation w/safety-related equipment unqualified * Office of Nuclear Reactor Regulation, Director 83/06/06 2pp 18919.266 24% Fiche 50-282,83/06/03,8306200281
- 8306170053 Concurs w/findings contained in technical evaluation rept, "Control of Heavy Loads " Guidelines in NUREG-0612, Section 5 1.1 setisfied, per util 810402, 0715, 0831 & 1209, 820203 & 1108 & 830409 submittals CLARM, R. A. Operating Reactors Branch 3 83/06/06 MUSOLF, D M Northern States Power Co. 2pp. 18706:314 R4X Fiche, 50-282, 83/06/06, 8306170053
- --8306170058 Safety evaluation supporting util Phase I actions of control of heavy loads MUREQ-0612, Section 5 I I guidelines satisfied.

 * Office of Nuclear Reactor Regulation, Director 83/06/06 Ip 18906, 316 24% Fiche: 50-282, 83/06/06, 8366170053
- --8305230021 "Control of Heavy Loads (C-iO), Prairie Island Nuclear Generating Plant Units 1 & 2," technical evaluation rept VOSBURY, F.M. Frantlin Institute/Franklin Research Center NRC-03-81-130 TER-C5506-384/385 83/05/17 NRC - No Detailed Affiliation Given 31pp 66794 188 24X Fiche 50-282,83/06/06, 8306170083
- 8306200390 Forwards safety & licensing portion of Westinghouse Apr 1982 rapt, providing addl info re fuel assembly failure effect on insertion of control rods or core cooling geometry MSOLF.D. Northern States Power Co 83/06/07 Office of Nuclear Reactor Regulation, Director. 2pp. 18899.052. 24X Fiche: 50-282, 83/06/07, 8306200390

G Inspection reports: IE Bulletins & correspondence

8305110458 IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in Hell Logging Davice" Svc [1st enc].

TAYLOR, J. M Division of Safeguards & Inspection Programs (Post 830103), 83/05/26, Consolidated Edison Co. of New York, Inc 125pp 18831:043 24X Ficher-50-000, 83/05/26, 8305110458.

- 8305110460 IE Info Notice 83-34, "Event Notification Info Worksheet "
 Svc list encl
 JORDAN, E.L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/05/26 Consolidated Edison Co of New
 York, Inc. 115pp. 18732 085—24X Fiche 50-000.83/05/26,G305110460
- 8306060084 Commends NRC re results of piping insp at BMRs
 Leak-before-break concept continues to sustain validity of
 technical bases Utils giving consideration to more permanent
 measures
 NELS, G H Northern States Power Co 83/05/26 DENTON, H R Office
 of Nuclear Reactor Regulation, Director 2pp 18719 335 247
 Fiche 50-000, 83/05/26, 83080800084
- 8305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods Withdrawn at BWRs " Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/31 Consolidated Edison Co. of New York, Inc. 116pp 18732 208 24X Fiche 50-000,83/05/31,8305110461
- 8304170232 Submits list of affected valves, test method & test schedule in response to IE Bulletin 83-03 Inservice insp program will be revised to include testing of listed valves LARSON.C E Northern Status Power Co 83/06/08 KEPPLER, J G Region 3, Office of Director 2pp 18078 284 24X Fiche 50-282,83/06/08,8306170232
- 8305110464 IE Info Notice 83-36. "Impact of Security Practices on Safe Operations" Syc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83706/09 Consolidated Edison Co. of New York: Inc. 119pp 18830 280 24X Fiche 50-000.83706/09,8305110464
- 8305110470 IE Info Notice 83-36. "Defective Heat Bink Adhesive & Seismically Induced Chatter in Relays Within Printed Circuit Cards " Svc Iist encl JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co of New York, Inc. 118pp 18720 225, 24X Fiche 50-000,83/06/13,8305110470
- 8306090010 IE Info Notice 83-37, "Transformer Failure Resulting From Degraded Internal Connection Cables" Bvc list encl JURDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/13 Consolidated Edison Co. of New York, Inc. 243pp 18921 001 24X Fiche 50-000,83/06/13,8306090010
- 8305110475 IE Info Notice 83-40, "Need to Environmentally Qualify
 Epoxy Grouts & Sealers " Svc list encl
 JORDAN E L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/05/22 Consolidated Edison Co of New
 York, Inc. 115pp 19021,179 24X Fiche 50-000,83/06/22,8305110475
- 8305110477 IE Info Notice 83-41, "Actuation of Fire Suppression Sys Causing Inoperability of Safety-Related Equipment" Svc list enc1 JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/22 Consolidated Edison Co. of New York, Inc 120pp 18997 007, 24X Fichs 50-000,83/06/22,8305110477
- 8305110479 IE Info Notice 83-42, "Reactor Mode Switch Malfunctions "
 Svc list ent!
 JORDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/06/23 Consolidated Edison Co of New
 York, Inc 116pp 18996 242 24X Fiche 50-000,83/06/23,8305110479
- 8305110483 IE Info Notice 83-43, "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints " Svc list encl JORDAN:E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/24 Consolidated Edison Co of New York, Inc 116pp 19046-297 24X Fiche 50-000,83/06/24.8305110483
- 8306280340 Requests relief from requirement re 10-yr inservice insp of reactor coolent pump casing wolds of ASME Boiler & Pressure Vessel Code. Section XI. "Inservice Insp." Request submitted as Rev 9 to inservice insp & testing program MUSQLF.D Northern States Power Co 83/06/24 Office of Nuclear Reactor Regulation. Director 3pp 19014 070 24X Fiche: 50-282, 83/06/24, 8306280340
- --8306280345 Rev 9 to "ABME Code Section XI Inservice Insp & Testing Program" * Northern States Power Co 83/06/24, 9pp 19014 073 24X Fichs 50-282,83/06/24,8306280340

R Periodic operating reports & related correspondence

B306020167 Monthly operating repts for Mar 1983 W/830411 ltr MUSDLF, D. DUGSTAD, D. Northern States Power Co. 83/04/05 9pp 18691:075. 24X Fiche, 50-282,83/04/05,8306020167

- 8306140002 Monthly operating repts for May 1983 W/830607 ltr DUGSTAD.D., MUSDLF.D. Northern States Power Co. 83/06/07 of Resource Management, Director 9pp 18838 219 24X Office Fiche 50-282, 83/06/07, 8306140002
- 9 Reportable occurrences. LERs & related correspondence
- 8306160264 PNO-III-83-042 on 830608, unit shut down to investigate source of RCS leakage Source of leakage determined to be from four steem generator manways Repairs expected to take 3 to 5 days JACKIW,I , SHAFER,W Region 3, Office of Director 18861 266 24X Fiche 50-306,83/06/10,8306160264 B3/06/10 1p
- DOCKET 50-309 MAINE YANKEE ATOMIC POWER PLANT F Security, medical, emergency & fire protection plans
- 83040300B9 Informs that onsite & offsite emergency preparedness adequate & emergency plans upgraded per NUREO-0737. Item III A 2 1 Item complete CLARK, R A Operating Reactors Branch 3 83/05/20 GARRITY, J H Maine Yankee Atomic Power Co 3pp 18/33 280 24X Fiche 50-309, 83/05/20, 8306030089
- 8306170166 Forwards "Summary of Public Emergency Alerting Bys (PEAS) Siren Testing, Apr & May 1783 " Plans to correct deficiencies in PEAS submitted in 830331 itr GARRITY, J H Maine Yankee Atomic Power Co 83/06/02 ALLAN, J M Region 1. Office of Director 2pp 1888 263 24X Piche 50-309, 83/06/02.8306170166
- --8306170177 "Summary of Public Emergency Alerting Sys (PEAS) Siren Testing, Apr & May 1983 " * Maine Yankee Atomic Power Co 83/05/31 29pp 18883,265 24X Fiche 50-309,83/06/02,8306170166
- 8306140265 Releases public version of revised oversize Figure 2 50.0-1 FELTON.J M Division of Rules and Records 83/06/06. Document Management Branch 1p 18844 335 24X Fiche 50-309, 83/06/06. 8306140265
- --8306140273 Forwards public version of oversize Figure 2 50 0-1.
 smergency condition classification table Table replaces
 Pages 5A through 17C of Rev 4 to Procedure 2 50 0.Apprture
 card available in FDR
 * Maine Yankee Atomic Power Co 83/04/27 NRC No Detailed
 Apriliation Given 3pp 18844 336. 24X Fiche 50-309,83/06/06,8306140265
- 8304150263 Forwards State of ME plans to correct emergency preparedness deficiencies identified by FEMA.por 830511 site meeting AddI info on radiological exposure control will be submitted to FEMA within 1 wk GARRITY, J H Maine Vankee Atomic Power Co 83/06/06 ALLAN, J. M. Region 1, Office of Director 15pp 18849 176 24X Fiche: 50-309, 83/06/06, 8306150263.
- 8304170240 Notifies that representative from LASL will be contacting site in near future to establish schedule for revisit as part of CY83 & 84 reanalysis of original 10 sites visited during vital area analysis program ALLAN.J.M Region 1. Office of Director. 83/06/13. RANDAZZA,J B Haine Yankes Atomic Power Co. 2pp 18078 163 24X Fiche 50-309.8704/13.8704/17340. Fiche, 50-309, 83/06/13, 8306170260
- 830.6230361 Forwards analysis of postulated fires in reactor coolent pump bays. Rept supports 920701 request for exemption from Section 111 O of App R requirements re installation of lubricating oil collection sys qualified for SBE OROCE.R H. Maine Vankee Atomic Power Co 83/06/21. CLARK,R. A Obstating Reactors Branch 3 Rep 18943 332 24X Fiche: 50-309, 83/06/21.8306230361
- --8306230366 Analysis of postulated fires in reactor coolant pump bays * Maine Yankee Atomic Power Co 83/06/21, 50pp 18743;334, 24X Fiche 50-309,83/06/21,8306230361
- G. Adjudicatory correspondence
- 8306010391 Third set of interrogatories re spent fuel pool storage & sys expension & requests for production of documents
 Certificate of Svc encl
 MILLER, D. & Affiliation Unknown 83/05/27 Maine Yankee Atomic
 Power Co. 14pp 18682 213 24X Fiche, 50-309, 83/05/27, 8306010391 14рр

- 8304020358 Response to NRC 830516 apposition to 830427 renewal of motion for complete & specific disclosure & request for leave to file same Certificate of Svc encl MILLER, D 8 Bensible Maine Power 83/05/29 Atomic Smfety and Licensing Board Panel 4pp 18694 269 24X Fichs 50-309,83/05/29,83040358 MILLER, D S Sensible M Licensing Board Panel 6304020358
- 8304060309 Response opposing Sensible Mains Power motion to comps1 util answers to interrogatories & document requests & request for leave to file motion Motion untimely Good causs not shown Certificate of Svc ancl DIGNAN, T G , GAD, R K Mains Yankes Atomic Power Co DIGNAN, T, Q Ropes & Gray B3/05/31 Atomic Safety and Licensing Board Pans1 28pp 187279 102 24% Fiche 50-309, 63/05/31, 8304060305
- 8304040332 Response opposing Sensible Maine Power (SMP) motion for extension of discovery period SMP did not diligently prosecute original discovery period Certificate of Sw. encl. DIGNAN, T 0, GAD, R K Maine Yankee Atomic Power Co DIGNAN, T 0 Ropes & Gray 83/05/31 Atomic Safety and Licensing Board Panel Spp 18724 353 24X Fiche 50-309, 83/05/31.8304040332
- 8306070290 Interrogatories & request for production of documents Certificate of Syc ancl DIGNAN.TO, OAD.R K Maine Yankee Atomic Power Co DIGNAN.T & Ropes & Gray 83/06/02 Maine. State of 66pp 18744.012 Fiche 80-309.83/06/02.8306070290 DIONAN, T O
- 8306070296 Interrogatories & request for production of documents Centificate of Byr encl
 DIGNAN, T. G., GAD, R. K. Maine Yankee Atomic Power Co. DIGNAN, T. G.
 Ropes & Gray 83/06/02 Sensible Maine Power. 66pp 18741.008 24X Fiche 50-309,83/06/02,8306070296
- 8306090218 Confirms agreement re future proceeding schedule Meeting suggested within next 2 wks to discuss scheduling & substantive matters impacting on schedule AHRENS:P Maine, State of 83706/06 LEBBY, R.P. Hearing Branch 3 ip 18796 114 24% Fiche, 50-309, 83/06/06, 8306090218
- 8306150236 Response to first set of interrogatories & requests for documents. Prof qualifications & Certificate of Svc encl QUDDARD, R. J. Hearing Brench 3 83/06/06 Bensible Mains Power, 123pp 18850-241 24% Fiche 50-309, 83/06/06, 8306150236.
- 8306090296 Advises that parties will discuss scheduling & related matters & rept results to ASLB ASLB should suspend ruling on Bensible Maine Power 830523 motion to extend discovery pending discussion results

 GODDARD, R J, LESSY, R P Hearing Brench 3 83/06/07 LAZD, R M,

 MORRIS, P A, HAND, C H Atomic Bafety and Licensing Board Panel.

 2pp 18795, 231 24X Fiche 50-309.83/06/07,8306090296
- 8306100191 Forwards third set of interrogatoriss & requests for production of documents to util Related correspondence.

 8TERN, P Maine. State of 83/06/07. Docksting & Services Branch. ip 18805.326 24% Fiche 50-309.83/06/07.8306100191
- --8306100193 Third set of interrogatories & requests for production of documents, Certificate of Svr encl Related correspondence.

 ARRENS.P., STERN.P Mains, State of 83/06/07 Mains Yankes
 Abomic Power Co., 21pp. 18805 327 24X Fichs 50-309,83/06/07,8306100191.
- 8306100204 Forwards third set of interrogatories & requests for production of documents Related correspondence.
 8TERN.P. Maine. State of 83/06/07 Docksting & Services Branch.
 1p 18805.207 24X Fichs 50-309.83/06/07.8306100204.
- --8306100205 Third set of interrogatories & requests for production of documents. Certificate of Bvc encl Related correspondence AHRENB.F., STERN.P Maine: State of. 83/06/07 Office of the Executive Legal Director Rope 18805, 210, 24x Fiche 50-309, 83/06/07, 8306100204.
- 8306150278 Order extending time until 830715 for Commission to act to review Director's decision dtd 830214. CHILK 8 J Office of the Secretary of the Commission 83/06/10.
- 8306150241 Response to first set of interrogatories & request for documents Prof qualifications & Certificate of Svc encl. OCDDARD.R. J. Hearing Branch 3 83/06/13 Maine, State of. 148pp. 18864.139 24X Ficher50-309.83/06/13.8306180241.
- 8304230011 Response to 830319 second set of interrogetories & request for documents Certificate of Byc encl.

 9000ARD.R.J Hearing Brench 3. 83/06/20. Maine. State of. 43pp. 18447-130. 24% Fiche.30-309.83/06/20.8306230011

- P. Operating literae stage documents & correspondence
- 800,6010037 Submits list of topics to be discussed at 800525 meeting re-operational GA program HARTIM, I T Division of Engineering & Technical Programs 83/05/19 RANDAZIA.J B Haine Yantee Atomic Power Co. 2pp. 18681, 287 24X Fische 50-309, 83/05/19, 8306010337.
- 8306030231 Advises that proposed Change A3 to Teth Specs we containment leakage testing acceptable-however air cannot be used as test medium in Type C testing & add3 Tech Specs must be proposed to specify test pressure Safety evaluation encl CLARKER A. Operating Reactors Branch 3 83/05/20 GARRITY.J H. Maine Yambee Atomic Power Co 2pp 18733 348 24% Fishe 50-309.82/05/20.8306030231.
- ---8304000225 Safety evaluation supporting proposed Change 43 to Tech Space re-containment leakage Easting Air cannot be used as test medium in Type C testing & add I Tech Specs must be proposed to specify test pressure a DEFice of Nuclear Reactor Regulation, Director. 83/05/20 2pp 18732-350 24x Fichs 50-309.83/05/20.8306030231
- 8306020015 Requests performance or documentation of completion of load test of reactor vessel head lifting fixture for control of Assay loads. Phase I within 120 days Ouisdelines for response a complete draft technical evaluation rept encl CLAMK.R A. Operating Reactors Branch 3 83/05/24 GARRITY. J H Maine Yearles Atsout Power to 16pp 1870; 146 24X Fichs 50-309.83/05/24.8308020015
- --B306020037 *Control of Heavy Loads (C-10). Hains Yantee Atomic Power Co. Main Yantee Muclear Power Station. " draft technical evaluation rept YITO.D J. BITMERGER.C., SARGENT.I H. Frantlin Institute/Frantlin Rasarck Conter. NEC-03-81-130. TER-C5506-345 DRFT B2/12/30 CLEMENSON.F NRC No Detailed Affiliation Given Papp 18701 162 24X Ficha 50-309, 83/05/24, 8306020015
- 8306020505 Forwards safety evaluation on status of thermal shield support atructure Followsh k monitoring investigation of faifure sectantism recommended Continued operation acceptable CLARK.R.A. Operating Reactors Branch 3 83/05/25 GARRITY, J. H. Haine Yanies Atomic Power Co. 3pp. 187/3 148 24X Fiche 50-309,83/05/25,830600505
- --8306020513 Bafety evaluation supporting justification for continued exeration re thereal shield integrity a Operating Reactors Branch 3. 83/05/25. 3pp 18715 151, 24X Fiche 50-309, 83/05/25, 8306020505
- 8306020146 Former4s info supporting post-implementation review of post-accident sampling sys Eleven criteria from MREQ-0737, Item I B 3 addressed Description of reactor coolant & containment air post-accident sampling sys enci. GARRITY, J. H. Meine Vanies Atomic Power Co. B3/05/26. CLARK, R A Operating Reactors Branch 3 28pp 18694 130, 24x Fiche. 50-309.83/05/26.8306320146.
- 8304060310 Forwards revised Table 6 1 showing current spent fuel discharge projections we spent fuel storage modifies B11005 like. Revs do not alter proposed action or evaluation Alternative to reracting program encl. GARRITY.J H. Maine Yankes Atomic Power Co. 83/05/26 CLARK.R.A. Operating Reactors Branch 3 15pp 18729 187, 244 F16ks, 50-309, 83/05/26, 8306060310
- BD04020524 Discusses status of B20827 tommitment to perform comprehensive stress analyses of reactor vessel closure head a internals lifting rigs to provide scope is schedule of effort Results scheduled for submittal by B20831 GARRITY-J H. Maine Yenkes Atomic Power Co. 83/05/27. CLARK.R.A Devaking Reactors Branch 3. 2pp. 18693 241 24x Fiche 50-304.83/05/27.8306020524.
- 8:306090377 Informs that 8:11123 response to Generic Ltr 8:-21 re natural circulation continues acceptable. Final resolution of gracedure adequacy deferred to TNI Action Item I.C. 1.

 Shemberg of natural circulation condown tests requested CLAMAR. A. Operating Reacters Branch 3 83/05/31. GARRITY, J H Heine Yambre Atomic Power Co. 295. 18814.033, 24X
 Fiche. 90-309, 83/05/31, 8306090377.

- 830A210304 Summary of 830510 meeting w/util.Weston Grophysical Corp.
 Cygna Energy Svc & Stevenson & Assoc re seismic safety
 margin program status rept Viewgraphs & resumes encl
 HEITNER.K L. Operating Reactors Granch 3 83706706 CLAMK. R A
 Operating Reactors Branch 3 122pp 18789 200 24X
 Fiche 50-309,83706/66.8306210304
- 830A220223 Informs of actions required to avoid degraded conditions of offsite power supplies, per completed review of 830324 submittal re 821214 offsite power supply degradation incident SFR encl CLARK, R. A. Operating Reactors Branch 3 83/06/08 GARRITY, J. H. Haine Vankee Atomic Power Co. 4pp. 18950 347 RAX Fichs 50-309, 83/06/08, 8306220283
- --8306220226 Safety evaluation finding licensee commitment to upgrade
 Surowise line to conform w/-BAR after const acceptable Land
 flow analysis reflecting modified sys & development of
 periodic reassessment procedures required
 KANG-F Office of Nuclear Reactor Regulation, Director
 App 18750 381 24X Fiche 50-309.83/04/00.8306220223
- 8306240359 Notification of 830628 meeting w/util in Wiscosset. HT- to discuss auxiliary feedwater sys evaluation HEINER/K L. Operating Reactors Branch 3 83/06/21. CLANK, H A Operating Reactors Branch 3 19 18999.155 24X Fiche 50-309,83/06/21,8306240359.
- 8306290190 Requests proposed Tech Specs re limiting overtime for staff personnel which comply w/guidelines furnished in 820615 ltr Proposal dtd 830121 unacceptable CLARK, R.A. Operating Reactors Branch 3 83/06/21 OARRITY. J if Hains Yankee Atomic Power Co. 3pp. 17046-287 24X Fiche 50-309,83/06/21,8306290190
- 8306280009 Forwards "Heine Yankee Beismic Apalysis " Study employed both rotation & historic methods of seismic analysis of Haine Yankee ORACE, R H Yankee Atomic Electric Co ORACE, R H Haine Yankee Atomic Power Co. 83706/24 CLARK, R. A Gerating Reactors Mranch 3 2pp 19000 007, 24X Fighe 50-309, 63/06/24, 63062800009.
- ~-8306280011 "Maine Yankee Seismic Amalysis "

 Yankee Atomic Electric Co YAEC-1286 83/06/03 2//pp
 19000.009 24x Fiche 50-309,83/06/24,8306280009
- G Inspection reports, IE Bulletins & correspondence
- 8306060257 Discusses IE Insp Rept 50-307/02-05 on 820023-0500 & forwards notice of violations Response providing add1 actions completed or planned to improve control of design changes per 820928 Itr requested STARDHECKISE Division of Project & Resident Programs. B3/05/23. RANDAZZA, J B Maine Yanker Atomic Power Co App 10727 201 24% Fiche. 50-309, 83/05/23, 8306060257
- --B306060258 Notice of violation from insp on B20323-0503 Noncompliances noted procedures re design control not appropriate to effectively control plant design & failure to effectively correct pips support clearance identified in pravious insp * Region 1, Office of Director B3/05/23 2pp 18727-205 24% Fiche 50-309,83/05/23,8306060257.
- 8305110458 IE Info Notice 83-30, "Ruptured Am-R41 Sources Contained in Well Logging Device" Svc list encl.
 TAYLOR, J. M. Division of Safeguards & Inspection Programm (Post 830103), 83/05/26 Consolidated Edison Co. of New York, Inc., 125pp 18831:043 24X Fiche: 50~000, 83/05/26, 8305110458.
- 8305110460 IE Info Notice 83-34, "Event Notification Info Worksheet "
 Svc list encl
 JORDAN, E.L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/05/26 Consolidated Edison Co. of New
 York, Inc. 115pp. 18732.083. 84X Fiche: 50~000,83/05/26,8309140460
- 8306030282 Fowards IE Enforcement Conference Rept 50-309/83-05 on 830421. No noncompliance noted STAROSTECKI, R Division of Project & Resident Programs. 837/85/27. RANDAZZA, J B Maine Yankee Atomic Power Co. 2pp. 18708:342 24% Fichs: 50-309, 83/05/27, 8306030202.
- --8306030316 IE Enforcement Conference Rept 50-309/83-05 on 830A21. No noncompliance noted Hajar topics discussed; violations re degradation of MPSI sys.

 GALLO, R H, GREENMAN, E. Q. Region 1, Office of Director. 83705/04
- 8305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rads Nithdrawn at BMRs." But list encl JORDAN. E.L. Division of Emergency Proparedness & Engineering Response (Post 830103). 83/05/31 Consolidated Edison Co. of New York, Inc. 116pp. 18732, 208. 24% Fiche 50-000, 83/05/31, 8303110461

- 8306100276 Responds to Action Item 4 of IE Bulletin 83-03 re check valve failures in diesel generators raw cooling water sys Preventive maint program revised to require that one check valve be inspected each refueling interval RANDAZZA, J B Maine Yankee Atomic Power Co 83/06/07 ALLAN, J M Region 1, Defice of Director 3pp 1DB05 139 24X Fiche 50-309,83/06/07.8306100276
- 8306210175 Responds to IE Bulletin 83-03 & IC Info Notice 82-08 re check valve failures in diesel generator raw water cooling sys Listed HX inlot & outlet check valves will be inspected during next refueling outage RANDATZA.J B Maine Yankee Atomic Power Co 83/06/07 ALLAN.J M Region 1. Office of Director 3pp 18918 101 24X Fiche 80-309,83/06/07.8306210175
- 8306170469 Forwards SER, technical evaluation rept & notice of granting relief from inservice insp requirements Relief granted for Code requirements determined impractical to perform CLARK, A Operating Reactors Branch 3 83/06/08 GARRITY, J H Maine Yankee Atomic Power Co 3pp 18894 230 24X Fiche 50-309,83/06/08.8306170469
- --8306170472 Safety evaluation re util requests for relief from inservice insp requirements of ASME Reiler & Pressure Vessel Code.
 Section XI Relief from requirements determined impractical to perform granted
 * Office of Nuclear Reactor Regulation. Director 83/06/08 9pp 18894 233 24X Fiche 30-389.83/06/08.8306170469
- --8303220042 "ME Yankee Atomic Power Plant Inservice Insp Program," technical evaluation rept * Dattelle Hemorial Institute, Pacific Northwest Laboratory FIN B-2157 83/02/25 NRC - No Detailed Affiliation Given 29pp 18894 243 24X Fiche 50-309,83/06/08.8306170469
- --B306170474 Notice of granting of relief from inservice insprequirements of AGME Boiler & Pressure Vassel Code
 * NRC No Detailed Affiliation Given 83/06/08 1p 18894 272
 24X Fiche 50-309.83/06/08.8306170469
- B305110464 IE Info Notice 83-36, "Impact of Security Practices on Safe Operations " Syc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Rasponse (Post 830103) 63/06/09 Consolidated Edison Co of New York, Inc 117pp 18830 280 24X Fiche 80-000,83/06/09,8305110464
- 8305110470 IE Info Notice 83-30, "Defective Heat Sink Adhesive & Seismically Induced Chatter in Relays Within Printed Circuit Cards." Svc list encl JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 800103) 83/06/13 Consolidated Edison Co of New York. Inc. 118pp 18920 225 24X Fiche 50-000.83/06/13.8305110470
- 8304070010 IE Info Notice 83-37, "Transformer Failure Resulting From Degraded Internal Connection Cables," Svr list entl JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13, Consolidated Edison Co. of New York, Inc. 243pp 18921 001 24X Fiche 50-000,83/06/13,8306090010
- R306290486 Responds to NRC B30920 ltr re violations noted in IE Insp Rept 50-309/83-05 & G30520 proposed civil penalty. Corrective actions design change developed to modify 8 pump interlock & warning signs placed on safeguards pumps RANDAZZA,J B Maine Yankse Atomic Power Co B3/06/17, DEYGUNG,R C Director's Office Of Inspection and Enforcement App. 19053 031 24X Fiche 50-309,83/06/17,8306290486
- 8305110475 IE Info Notice 83-40, "Need to Environmentally Qualify
 Epoxy Grouts & Sealers " Svc list encl.
 JORDAN.E L Division of Emergancy Preparedness & Engineering
 Response (Post 830103) 83/06/22 Consolidated Edison Co. of New
 York, Inc 115pp. 19021.179, 24X Fiche.50-000,83/06/22,8305110475
- G305110477 IE Info Notice 83-41, "Actuation of Fire Suppression Bys Causing Inoperability of Safety-Related Equipment " Svc list enc! JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post B30103) B3/06/22, Consolidated Edison Co. of New York, Inc. 120pp 18997.007 24X Fiche. 50-000, 83/06/22, G305110477.
- 8305110479 IE Info Notice 83-42, "Reactor Mode Switch Malfunctions "
 Svc list encl
 JORDAN, EL Division of Emergency Preparadness & Engineering
 Response (Post 830103) 83/06/23 Consolidated Edison Co of New
 York, Inc 116pp. 18996: 242. 24X Fiche: 50-000, 83/06/23, 8305110479.
- 8305110483 IE Info Notice 83-43, "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints," Svc list encl. JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/24. Consolidated Edison Co of New York, Inc. 116pp. 19046 297. 24X Fithe 50-000,83/06/24,8305110483.

- R Periodic operating reports & related correspondence
- B306020152 Monthly operating rept for Mar 1983 W/B30413 ltr BATTERSON.5 , GROCE.R H Maine Yankee Atomic Power Co B3/04/13. HARTFIELD.R A Management Information Branch 5pp 18691.001 24X Ficha 50-309,83/04/13.8306020152
- 8306160444 Monthly operating rept for Apr 1983 W/830512 ltr BATTERSON.B. GRACE, R H Maine Yankes Atomic Power Co 83/05/12. HARTFIELD.R A Management Information Branch 5pp 18864 218 24X Fiche 50-309,83/05/12.8306160444
- 8306020352 Forwards microfiche of annual 50 59 rept Equipment unavailable to provide for 24 1 reduction ratio & 78 frames per sheet, per B20809 NRC request. W/o fiche OARRITY. J H Mains Yankee Atomic Power Co B3/05/24, ALLAN, J. N Region 1, Office of Director ip 18494-323 24X Fiche 50-309, 83/05/24, 83060R0352
- B Reportable occurrences: LERs & related correspondence
- 830401040B LER 83-018/017-0 on B30516, portion of gaseous radioactive datay drum different from one inadvertently released. Release terminated when discharge activity level exceeded setpoint. Caused by personnel error WOOD, E. C. Maine Yankes Atomic Power Co. B3/05/17 Region 1, Office of Director ip IR679 340 24X Fich. 50-309,83/05/17, B306010408
- 6306030341 LER 63-014/03L-0. on 630425, during full power operation, Section 207 of 115 kV reserve station avoid line became unavailable when struck by lightning while alternate out of avoid for upgrading Damaged arrestors replaced W/830525 itr STEVENB. J L. GARRITY. J H. Maine Yanker Atomic Power Co. 63/05/25 ALLAN. J H. Region 1. Diffice of Director, 3pp. 18704, 360. 24X Fiche 50-309, 83/05/25, 8306030341
- 8306020425 Revised LER 83-018/017-0 on 830516 portion of geneous radioactive decay drum D inadvertently released rather than permit-specified drum B Caused by personnel error Personnel reinstructed in reading permits WR30527 1tr STEVENS: J L , OARRITY, J H Maine Vankee Atomic Power Co 83/05/27, ALLAN, J M. Region 1. Office of Director 4pp. 18693: 221, 24X Fiche 50-309,83/03/27.8306020425
- 8306170186 LER B3-016/03L-0 on B30504, while performing ECCB hot monthly surveillance testing, safeguards recirculation stop valve BIA-M-54 failed to operate Caused by mechanical binding of valve stem Maint program to be upgraded, W/830602 ltr.
 LAFLAMME, S J, QARRITY, J H Maine Yankee Atomic Power Co B3/06/02 ALLAN, J M Region 1, Office of Director 3pp. 18878;271 24X Fiche 50-309,83/06/02,8306170186
- 8306130455 Forwards NRR comments on draft AO rept to Congress for First Guarter 1903
 DENTON, HR Office of Nuclear Reactor Regulation, Director, 83/06/07 HELTEMEB.C J Director's Office 3pp 18830,176 24X
 Fiche 50-000.83/06/07.8306130455
- 8306170430 LER 83-017/03L-0 on 830509, B30B17 & 18, cooling water outlet stop valve PCC-M-43 to RHR HX Pailed to spen from main control board, Caused by misadjusted valve motor operator torque settings H/830608 ltr MCALLISTER.8 A , GARRITY, J H Maine Yankse Atomic Power Co 83/06/08 ALLAN, J, N Region 1, Office of Director 4pp. 18879:009 24X Fiche 50-309,83/06/08,8306170430
- 6306270295 LER B3-019/03L-0 on 830516, operable auxiliary feedwater pump tagged out of svc during installation of heavy shielding door. Caused by movement of massive door creating safety hazard forcing degraded mode operation. M(830611 ltr. TAYLOR, J H , OARRITY, J H, Maine Yanker Atomic Fower Co B3/06/16, MURLEY, T. E. Region 1, Office of Director 3pp 18990, 13B 24X Fiche: 50-309, 83/06/16, 8306370295
- V Operator Examinations
- 8306140619 Extends invitation to attend 830627 meeting in King of Prussia-PA to discuss transfer of reactor operator licensing function from Bethesds, ND to Region I ofc.

 81ARCBIECKI, R. Division of Project & Resident Programs 83/06/09 RANDAZA-J B. Maine Yankes Atomic Power Co. 2pp 18841 260. 24X Ficha: 50-309,83/06/09,8306140619

- DOCKET 50-311 SALEM NUCLEAR GENERATING STATION. UNIT 2

 F Security, medical, emergency & fire protection plans
- 8306070150 Forwards Submittal 3 to security training & qualification plan Submittal withheld (ref 10CFR73 21)
 LIDEN.E A Public Service Electric & Gas Co of New Jersey
 83705/02 Region 1. Office of Director 2pp 18734 291 24X
 Fiche 50-272, B3/05/02, B306070150
- 8305070164 Requests that revocation of Chapter 9 be taken into account during review of Rev 8 to security plan & that approval of plan not be delayed by review of Chapter 9 Notice withdrawing Chapter 9 & Procedure SP7 encl
 LIDEN, E A Public Service Electric & Gas Co of New Jersey 83705712 Region 1. Office of Director 3pp 18736 281 24X
 Fiche 50-272,83/05/12.8306070164
- 8306020232 Forwards Rev O to Salem Generating Station Emergency
 Operating Procedures Generation Package." per Suppl I to
 NUREO-0737 (generic Ltr 82-33).
 LIDEN.E A public Service Electric & Gas Co of New Jersey
 B3/05/20 VAROA.5 A Operating Reactors Branch I ip 18689 001
 24X Fiche 50-272.83/05/20,8306020232
- --8306020240 Rev O to "Salem Generating Station Emergency Operating Procedures Generation Package " GUELLER.J, FRY.L. BERKLEY.J Public Service Electric & Gas Co of New Jersey 83704/20 166pp 18689 002 24X Fiche 50-272,83/05/20,8306020232
- 8304090052 Requests that proposed mod completion dates be included in amend to License DPR-75 to include 10CFR50.App R. Section III 9 2.re Fire Area P20-1 Submittal within 30 days of ltr receipt requested VAROA S A Operating Reactors Branch 1 83/05/31 UDERITY, R A Public Service Electric & Ons Co of New Jersey 2pp 18797-358 24X Fiche 50-311.83/05/31.8306090052
- 8306170481 Forwards safety evaluation of util submittals re fire protection rule incorporating BML technical input Facilities in compliance w/App R to 100FR50, Items 111 0 & 111 L re safe shutdown in relay cable spreading or control room VARGA:8 A Operating Reactors Branch | 83/05/31 UDERITZ:R A Public Service Electric & Gas Co of New Jersey 2pp 16894 307 24X Fiche 50-272:83/05/31:8305/70481
- --8306170483 Bafety evaluation of util compliance w/App R to 10CFRSO, Itsas III 0 3 & III L Facility design provides train of sysnecessary to achieve & maintain safe shutdown conditions office of Nuclear Reactor Regulation, Director 83/05/31 Spp 18894 309 24X Fiche 50~272.83/05/31.8306170481.
- 8306090049 Forwards Rev B. Amend I to security plan Rev withheld (ref 106FR73 21)
 LIDEN,E.A. Public Service Electric & Oas Co. of New Jersey 83706/03 Region I. Diffice of Director 2pp 18793 311 g
- B30&230471 Forwards IE Sefeguards Insp Repts 50-272/83-17 & S0-311/83-16 on 830516-20 No noncompliance noted MARTIN.T. I Division of Engineering & Technical Programs 83/06/08 UDERITZ, R A Fublic Stryics Electric & Gas Co of New Jersey 2pp 18941 302 24X Fiche. 50-272.83/06/08,8304230471
- --8305230475 IE Bafeguards Insp Repts 50-272/83-17 & 50-311/83-16 on 830516-20 No noncompliance noted Major areas inspected accurity plan contingency plan & previously identified items
 SMITH, Q C Region 1, Office of Director 83/05/06 3pp
 18941 304 24X Fiche: 50-272, 83/06/08, 8306230471
- H. General correspondence
- 8306140043 Requests JM Zupko & A Nassman be added to avo list for all correspondence re facilities HJ Midura should be deleted LIDEN.E A Public Service Electric & Oas Co of New Jersey 83706/06 VARQAS A Operating Reactors Branch I ip 18838-319 24X Ficha 50-272,83706/06,8306140043
- P. Operating license stage documents & correspondence
- 830.6020562 Clarifies 830219 t 21 environ qualification SERs Upon completion of plant-specific review of all plants, cross-ref of nonqualified equipment will be conducted to determine if same equipment in other plants determined qualified VARGA.B A. Operating Reactors Branch 1 83/05/23 UDERITZ, R. A Public Service Electric & Gas Co. of New Jersey 3pp 18715:120 24X Fiche. 50-272, 83/05/23, 8306020562

- B306030141 Submits long-term operational verification program for Westinghouse DB-50 reactor trip breakers Data will be used to assess reliability of undervoltage trip attachments Results of program expected in Oct 1960 UDERITZ, RA Public Service Flectric & Gas Co of New Jurkey B3/05/31 EISENHUT, DQ Division of Licensing Epp 18/04 PB3 24X Fiche 50-272,83/05/31,8306030141
- 8306190064 COPPER IN THE INIAKE AND DISCHARGE ZONES OF THE SURRY AND SALEM NUCLEAR POWER STATIONS
 HARRISON,F L , DISHOP,D J , RICE,D W Lawrence Livermore Laboratory
 FIN A-0119 NURES/CR-2965 83/05/31 Division of Hoalth, Biting
 & Waste Management 51pp Available at NRC \$4.00 18849 221
 24X Fiche 50-000.83/05/31.8306150064
- B306140059 Forwards "Analysis of Valve/Uperator Interface Hordware for Containment Pressure & Vacuum Relief Valvos 1 & 2 VC 5, " in response to NRC 830519 request LIDEN,E A Public Service Llectric & Gas Co of New Jorany 83/06/07 VARGA S A Operating Reactors Branch 1 3pp 10838 DA/ 24X Fiche 50-272,83/06/07.8306140059
- --8306140063 "Analysis of Valve/Operator Inturface Hardware for Containment Pressure & Vacuum Relief Valves 1 & 2 VC 5 " FOLEY, J M. WDDL, J C., KRAMER, E W. Public Service Electric & Qas Co. of New Jersey 63/06/03 16pp 18036 270 24X Fiche 50-272.83/06/07.8306140059
- B30616043B Forwards RA Uderitz affidavit per 830607 response to NRC 830919 ltr re valve operability reviews for 10-inch pressure/vacuum relief valves used for purge or vent of containments
 LIDEN,E A Public Service Electric & Gas Co of New Jersey 83706708 VARGA:B A Operating Reacturs Branch 1 Ppp 18860 074 24X Fiche 50-272,83706708,830616043B
- 8306270299 Application for amend to Licenses DPR-70 & DPR-75, revising Amend Requests 79-01 & 81-19 re radiological effluent & administrative controls & Tech Specs re surveillance testing & reporting requirements for reactor trip breakers LIDEN, & A Public Service Electric & Qas Ca of New Jersey 83/04/17 VAROA & Operating Reactors Dranch 1 3pp 10994 278 24X Fiche 50-272,83/06/17,8306270299
- --8306270304 Proposed Tech Specs revising radiological offluent & administrative controls & survoillance testing & reporting requirements for reactor trip breakers & Public Service Electric & Oas Co. of New Jersey 83/06/17 247pp 18794 281 24X Fiche 50-272,03/06/17,8306270279
- 8306270313 Responds to 830523 clarification of BERs re environ qualification of safety-related electrical equipment raquesting review of equipment in Categories IV.I B & II A LIDEN, E A Public Service Electric & Gas Co of New Jersey 83/06/21 VARGA.8 A Operating Reactors Branch 1 3pp 19055.313 24X Fiche 50-272.83/06/21.8306290313
- 8306300190 Forwards Offsite Dose Calculation Manual per NRC 790118 ltr LIDEN,E.A Public Service Electric & Cas Co. of New Jersey 83/06/24 VAROA; S A Operating Reactors Branch 1 lp 19122-199 24X Fiche 50-272,83/06/24,8306300190
- --8306300194 Offsite Dose Calculation Manual * Public Service Electric & Gas Co of New Jersey 83/03/31 75pp 19122 200 24X Fiche 50-272,83/06/24,8306300190
- G Inspection reports, IE Bulletins & correspondence
- 8306240046 Discusses IE insp on 830302-06 & forwards notice of violation & proposed imposition of civil penalty DEYOUNG, R.C. Director's Office, Office of Inspection and Enforcement 83/05/05 SHITH, R Public Service Electric & Gas Co of New Jersey 4pp 18987 217 24X Fiche 50-272, 83/05/05,
- --8306240049 Notice of violation & proposed imposition of civil penalty in amount of 4850.000 Noncompliance noted, reactor trip breaker failed to automatically open following receipt of valid trip signal DEYOUNG, R C Director's Office, Office of Inspection and Enforcement. 83/05/05 Spp 18987.221 24X Fiche 50-272.83/05/05.8306240046
- 8305110458 IE Info Notice 83-32, "Ruptured Am-241 Bources Contained in Well Logging Device" Svc list encl
 TAYLOR, J M Division of Safeguards & Inspection Progrems (Post 830103) 83/05/26. Consolidated Edison Co of New York, Inc. 125pp 18831 043, 24X Fiche 50-000, 83/05/26, 8305110458.

- 8305110460 IC Info Notice 83-34. "Event Notification Info Worksheet "
 Svc list encl
 JORDAN, L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/05/26 Consolidated Edison Co. of New
 York, Inc. 115pp 18732 085 24X Ficho 50-000/83/05/26.0305110460
- 8305110461 IE Info Notice 83-35. "Fuel Movement W/Control Rods Withdrawn at DHRs " Svc list chil JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 63/05/31 Consolidated Edison Co of New York, Inc. 116pp 18732 208 24X Fiche 50-000,83/05/31,8305110461
- B306140256 Ack receipt of B30317 ltr informing NRC of steps token to correct violations noted in 11 Insp Repts 50-272/B2-36 & 50-311/B2-33
 STARDSTECKI, R Division of Project & Resident Programs G3/05/31
 UDERITZ, R A Public Service Flectric & Oas Co of New Jersey ip 18833 017 24X fishe 50-272, US/05/31, 8706140256
- --8306140261 Responds to NRC 830215 ltr re violations noted in II. Insp Repts 50-272/82 36 & 50-311/82-33 Corrective actions Operations Directive 12.Tech Spec interpretations, expanded to include encl Guide-11 & Poolnotos added to logs UDERITZ,R A Public Service Flectric & Gas Co of New Jersey 83/03/17 | IMANUS,R C Region 1, Office of Director STARDSTECKI,R Division of Project & Resident Programs 3pp 18833 020 24% Fiche 50-272,83/05/31,8306140256
- 8306160130 Forwards IE Insp Repts 50-272/83-12 & 50-311/83-13 on B30326-0510 & notice of violation STAROSTECKI.R Division of Project & Resident Programs 83/05/31 UDERTIZ.R A Public Service Flectric & Gas Ca of New Jersey 2pp 18862,005 24X Fiche 50-272,83/05/31.8306160130
- --830&1&0137 Notice of violation from insp on 830324-0510 * Region 1, Office of Director 83/05/31 ip 18842 007, 24% Fiche: 50-279,83/05/31,830&1&0130
- --8306160144 IE Insp Repts 50-272/83-12 & 90-311/83-13 on 830326-0510 Noncompliance noted failure to submit timely LERs NORRHOLD, L. J. SUMMERS.R J. TRIPP.L E Region 1, Office of Director 83/05/27 17pp 18962 OOD 24X Fiche 50-272,83/05/31, 8306160130
- 830607617/ Requests 30-day extension for response to 870505 notice of violation & proposed imposition of civil penalties Delay due to complexity of issues & consideration of available options

 UDERITY.R A Public Service Electric & ONE Co. of New Jarsey
 83704/01 DEYBUNG.R C. Director's Office Office of Inspection and Enforcement 2pp 18736-327 24X Fiche 50-272,83/06/01,8304070177
- 8306160440 Ack receipt of 830415 ltr informing NRC of steps taken to correct violations noted in it limp Repts 50-272/83-01 & 50-317/83-01 & 50-317/83-01 MARTIN, T 1 Division of Engineering & Technical Programs 83/06/07 UDERITZ, R A Public Service Electric & Cas Co of New Jersey 1p 18864 214 24% Fische 50-272,83706/07,8306160440
- --B30616044B Responds to NRC B30304 ltr requesting addl info reviolations noted in IE Insp Repts 50 2/2/83-01 & 50-311/83-01 Corrective actions Meter M-I3/ returned to vendor for repair cost estimate

 UDERITZ.R A Public Bervict Cletric & Gas Co of New Jersey

 83/04/15 MARIJN.T T Division of Engineering & Technical

 Progrems 3pp 18844 215 24X Fiche 50-272.83/06/07.8306160440
- 8396219176 Responds to IE Bulletin B3-03. "Check Valve Failures in Raw Mater Cooling Sys of Diesel Generators " Affected check valves associated w/each diesel generator listed.

 LIDEN, E. A. Public Service Liectric & Oas Co. of New Jersey 83706/07 ALLAN, J. M. Region I. Office of Director Spp. 18915 239 24X Ficha 50-272, 83/06/07, 8906210176
- 8308230471 Forwards IE Bafeguards Insp Ropts 50-272/83-17 & 50-311/83-18 on 830518-20 No noncompliance noted MARTIN T Division of Engineering & Technical Programs 83/08/08 UDERITZ: R A. Public Bervice Electric & Gas Co of New Jersey 2pp 18941 302 24% Fiche 50-272,83/08/08,0308230471
- --8306230475 IE Safeguards Insp Repts 50-272/83-17 & 50-311/83-16 on 830516-20 No noncompliance noted Major areas inspected ascurity plan, contingency plan & previously identified items.

 SHITH 9.C. GDDY, A.T. Region 1. Office of Director 83/06/06 Spp. 18741 304 24X Fiche 50-272,03/06/08,8306230471
- 8305110464 IE Info Notice 83-36, "Impact of Security Practices on Safe Operations." Syc list encl JORDAN, E. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/09, Consolidated Edison Co. of New York, Inc. 119pp 18830 280 P4X Fiche 50-000,83/06/09,8305110464

- 8305110470 IE Info Notice 83-38, "Defective Heat Sink Adhesive & Seismically Induced Chatter in Relays Within Printed Circuit Cards " Syc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co of New York, Inc. 118pp 18920 225 24X Fiche 50-000,83/06/13.8305110470.
- 8306090010 IE Info Notice B3-37, "Transformer Failure Resulting From Degraded Internal Connection Cables " Svc list encl JURDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83706/13 Consolidated Edison Co of New York, Inc 243pp 18921 001 24X Fiche 50-000.83/06/13.8306090010
- 8305110475 IE Info Notice 83-40, "Need to Environmentally Gualify
 Epoxy Grouts & Sealers " Syc list encl
 JDRDAN.E L Division of Emergency Preparedness & Engineering
 Response (Post 800103) 83/06/22 Consolidated Edison Co of New
 York, Inc 115pp 19021 179 24X Fiche 50-000.83/06/22.8305110475
- B305i10477 IE Info Notice B3-41. "Actuation of Fire Suppression Bys Causing Inoperability of Safety-Related Equipment" Svc list encl
 JORDAN, C L. Division of Emergency Preparedness & Engineering Response (Post B30103) B3/06/22 Consolidated Edison Co of New York, Inc 120pp 18977 007 24X Firhe 50-000, B3/06/22.8305110477
- B305110479 IE Info Notice 83-42, "Reactor Mode Switch Malfunctions."

 Svc list encl.

 JCRDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/23 Consolidated Edison Co. of New York, Inc. 116pp 18996 242 24X Fiche 50-000,83/06/23,8309110479
- 8305110483 IE Info Notice 83-43, "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints " Svc list encl JORDAN.E L Division of Emergoncy Preparedness & Engineering Response (Post 830103) 83/06/24 Concolidated Edison Co. of New York, Inc. 116pp 19046 297 24X Fiche 50-000.83/06/24,8305110483
- R Periodic operating reports & related correspondence
- 8306150267 Forwards annual radiological rept for 1982. "Artificial Island Radiological Environ Monitoring Program "
 LIDEN.E A. Public Service Electric & Oas Co. of New Jersey.
 83/06/02 ALLAN.J M. Region 1. Office of Director 1p 18849: 263, 24X Fiche 50-272,83/06/02.8206150267
- --8306150070 "Artificial Island Radiological Environ Monitoring Program," annual radiological rept for 1982 LIDEN,F A Public Service loctric & Gas Co of New Jersey RMC-TR-83-03 83/04/20 136pp, 18849 264 24X Fiche 50-272,83/06/02,8306150267
- 8306280342 "NPDES Discharge Monitoring Repts for May 1983 " W/830606 1tr MILLER,L K Public Service Llectric & Oas Co of New Jersey 83/06/06 21pp 19019 343 24X Fichs 50-272,83/06/06,8306280542.
- 8306200240 "Annual Environ Operating Rept (Nonradiological),1982 " H/830608 itr LIDEN E A Public Service Cleetric & Gas Co. of New Jersey 83/06/08 ALLAN, J M. BORES, R. J. Region 1, Office of Director, 19pp 18902 129 24X Fichs 50-272,83/06/08,8306200240
- B306200132 Monthly operating rept for May 1983.W/B30610 ltr MILLER, L K , ZUPKO, J M Public Service Electric & Qas Co of New Jersey B3/06/10 Director's Office, Office of Inspection and Enforcement 12pp 18903 300 24X Fiche 50-311,83/06/10, B306200132
- 8 Reportable occurrences. LERs & related correspondence
- 8306010328 LER 83-017/01P on 830425, discovered blank installed in line providing vent path for RCB w/both pressurizar overpressurization protection sys valves imperable. Cause under investigation Detailed rept within 14 days ZUPKO, J M Public Service Electric & Gas Co of New Jersey. 83/05/10 ALANJ Region 1, Office of Director ip, 10481, 276 24X Fichs-50-311,03/05/10,8304010328
- 8306030344 Supplemental LER 82-060/03X-1 on 820722, accumulator 24 declared inoperable when level found below operating band Accumulator 23 later declared inoperable Caused by level indication drift Level transmitters replaced H/830513 ltr FRAHM.R., ZUPKD.J M. Public Service Electric & Gas Co. of New Jersey 83/05/11 ALLAN.J Region 1. Office of Director 5pp 18705 007 24X Fiche 50-311,83/05/11,8306030344

- 8304020406 iER 83-017/01T-0 on 830425 blank discovered installed on pressuriter relief line, isolating RCS ventpath Gaused by personnel misunderstanding Personnel counseled W/830519 ltr FRAHK, R., ZUPKO, J. M. Public Service Electric & Gas Co. of New Jersey 83/05/19 ALLAN. J. Region I. Office of Director Spg. 18695 162 24X Fishe 50-311.83/05/18.8306020406
- B30403018B LER 83-019/03L-0 on B30430 vital instrument bus 20 desnargized & tagged out for maint-resulting in loss of power range channel N-44 Caused by shift supervisor being unaware of deenergization W/830520 ltr FRAHM, R., ZUPKO, J M Public Service Electric & Oos Co of New Jersey B3/05/20 ALLAN, J Region J, Office of Director 4pt 18703 309 24X Fiche 50-311.83/05/20.8306030188
- 8304030301 LER 83-018/03L-0 on 830428.duting pre-test insp of fuel handling area ventilation systroughing filter elements found installed in MEPA filter location in normal filter train Filters replaced Procedures revised W/830526 ltr FRAMM, R , ZUPMO, J M Public Bervice Electric & Cas Co of New Jersey 83/05/25 ALLAN, J Region i, Office of Director 4pg 18704 021 24% Fiche 50-311,83/05/25,8304030301
- 8306030157 Staff requirements memo informing of Commission 830513 briefing in Mashington.DC on NUREO-1000. "Generic Implications of ATMS Events at Salem Nutlear Power Plant "Operating criteria requested CHILK.B J Office of the Secretary of the Commission 83/05/27 DIRCKS, J. Office of the Executive Director for Operations 19 18733 313 24X Fiche 50-272,83/05/27.8306030187
- 8306170021 LER 83-020/03L-0 on 830512. senior shift supervisor natified that control room emergency air conditioning sys design not consistent w/Tech Bacc Burveillance Requirement 4 7 4 1 0 ? License change to be submitted W/830609 ltr FRAMM.R. ZUPKO.J M. Public Bervice Electric & Gas Co. of New Jersey 83/06/01 ALLAN.J M. Region 1. Office of Director App 18882.240 24X Fiche.50-311.83/06/01.8306170021
- 8306170153 LER 83-024/03L-0 on 830514 & 15.RHR sys suction valve closed eliminating flow in operating RHR loop Caused by deenergized vital instrument bus 2B & failure of comparator 2PC-4054-8; respectively Comparator replaced W/830609 ltr FRAHR, R., ZUPKO, J. M. Public Service Electric & Oas Co. of New Jarsey 83/06/08. ALAN, J. Region 1, 07fice of Director 4pg 18678 343. 24% Fiche 50-311.63/06/08, G306170153
- 830&170207 LER 83-021/01T-0 on 830525 vital instrument inverter PC deenergized for planned maint rendering associated bus train inoperable Containment integrity could not be established within 8 h time limit #/830608 ttr
 FRANNIR / ZUPKO, J M Public Service Electric & Oas Co of New Jersey 83/06/08 ALLAN, J Region 1. Office of Director Spp 18878 316 24% Fiche 50-3|1.83/06/08.8306170207
- 8306270188 LER 83-025/03L-0 on 830524, RHR pump & fuel handling bldg exhaust fam 21 tripped Caused by floating togic line & internal circuitry noise in safeguards equipment control sys Testing design change issued M/830614 ltr FRANM.R. / IUPKO.J M. Public Service Electric & Gas Co of New Jersey 83/06/08 ALLAN.J. Region 1. Defice of Director 4pp 18991 328. 24X Fiche 50-311.83/06/08.8306270188
- 8306170362 LER 83-022/017-0 on 830530.vital instrument inverter PC failed, rendering associated electrical bus train inoperable Caused by personnel failure to complete test Procedures to be reviewed.W303050 ltr FRANM.R., ZUPKO.J N Public Service Electric & Oas Co of New Jersey, 83/06/10, ALLAN,J Region 1, Office of Director. Spp 18880 327 24% Fiche 50-311.83/06/10.8306170362
- 830623034 PND-I-83-066.on 830620.Fire discovered in 480-volt vital switchgear room Source of fire was phase C of 28 480 transforper.Fire extinguished Cause of fire under investigation SUMMERS.R. COLLING.S. Region J. Office of Director. 83/06/20 ip 16942 348 24X Fiche 50-3ii.83/06/20.8306230334.

V Operator Examinations

- 8306140036 Requests NRC concurrence in special requalification training program for JD Driscoll Failure of reactor trip breakers in late Feb & ensuing investigation & corrective action development prevented attendance w/scheduled shift.

 LIDEN, E. A. Public Service Electric & Oas Co. of New Jersey 83/06/09 VARAN S A. Opprating Reactors Branch I. 2pp. 18838 309 24X Fiche. 50-272, 83/06/08, 8306149036
- 8306140403 Extends invitation to attend 630627 meeting in King of Prussis, PA to discuss transfer of reactor operator licensing function from Sethesda, MD to Region I of: STARDSTECKI, R Division of Project & Resident Programs 83/06/09 UDERITZ, R. A Public Service Electric & Que Co. of New Jersey. 2pp. 18838: 001 24X Fiche 50-272, 83/06/09,8306140403

- OUCKET 50-312 RANCHO SECO NULLEAR GENERATING STATION

 F Security, medical, emergency & fire protection plans
- 8306060400 Responds to FOIA request for lists of personnel in specified depts of nuclear plants & in state depts of health physics/ radiology Forwards listed documents Document partially withheld (ref FOIA Exemption 6) FELTON.) M Division of Rules and Records 83/04/06 WESI.D K Affiliation Unknown 2pp 18751 292 24X Fiche 50-312,83/04/06, exception
- 8306080123 Forwards "Emergency Preparedness Evaluation Rept" ro review of upgraded emergency plan & revs through 13 Deficiencies noted Requests page changes to plan correcting deficiencies or justification why revs unmecessary SCARANO, R A Division of Radiological Safety & Safeguards Program 83/05/27 RODRIGUEZ, R J Sacramento Municipal Utility District 2pp 18773 008 24X Fichs 50-312,83/05/27,8306080123
- --8306080127 "Emergency Preparedness Evaluation Rept "
 * Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/27 34pp 18773 010 24X Fiche 50-312.83/05/27.8306080123
- B306280175 Forwards IE Emergency Preparedness Insp Rept 50-312/83-09 on B30328-0401 No noncompliance noted NORDERHAUG, L R Region 5, Office of Director G3/05/27 MATIMOE, J J Sacramento Municipal Villity District 2pp 1904 149 24% Fiche 50-312/83/05/27/8306280175
- --B3062B0183 IE Emergency Preparedness lump Rept 50-312/83-09 on 83032B-0401 No noncompliance noted Major areas inspected corrective actions re 21 significant findings identified in 810831 immediate action ltt & pmergency detection NORTH-H S , GCHUSTER, M D Region 9. Office of Director 83/05/24 15pp 19014 151 24X Fiche 50-312.83/05/27.8306280175
- 8306140591 Forwards Amend II to security plan Amend withheld (ref 1007873 21) RODRIGUEZ.R J Sacramento Municipal Utility District 83/06/09 Operating Reacture Dranch 4 1p 18844 159 24X Fiche 50-312.83/06/09.8306140591
- 8304170375 Ack receipt of 830105 & 0201 changes to emergency plan implementing procedures Changes do not decrease effectiveness of emergency response planning NORDERHAUD, L.R. Region 5, Office of Director 83/04/13 ROBRIQUEZ, R.J. Sacramento Municipal Utility District 1p 18880 311 24X Fiche 50-312.83/04/13.8306170375
- 8304230393 Discusses test program for state & tri~county (San Joaquin, Amador & Sacramento Counties) voice notification sys, effective 830627 RODRIOUEZ, R.J. Sacramento Municipal Utility District 83/06/17 MARTIN.J.P. Region 5. Office of Director KEARNS, J.J. California, State gf. BARBER, 0. San Joaquin County, CA. 2pp. 18943-129 24X Fiche 50-312,83/06/17.8304P30373
- O Adjudicatory correspondence
- 8306230337 Notice of LC Lampher & firm of Hill.Christopher & Philligs removal from svc list Certifiate of Bvc encl LANPHER, L C Kirkpatrick, Lockhart, Hill, Christopher & Phillips B3/06/21 2pp 18742 349 24X Fiche 50-312,83/06/21,8306230337
- J Insurance & indemnity information
- 8306270325 Forwards NELIA Policy X83-0007, MAELU Policy XTA-1389, Endorsements 1-7 to MAELU Policy TA-1380 & Endorsements 1-6 to NELIA Policy 1666 RDDRIGUEZ,R J. Secramento Municipal Utility District 83/06/20 8ALIZMAN,J B Antitrust & Economic analysis Branch (Utility Finance) 83pp 19346 170 24X Fiche 50-312,83/06/20,8306270325
- P. Operating license stage documents & correspondence
- 830402031? Fowards generic safety evaluation supporting continued operation of PWRs w/Dresser safety valves on primary sys Valve ring settings adequate to meet min capacities for limiting transfert for interim operation \$100.7 F Operating Reactors Branch 4 83/05/18 RODRIQUEZ,R J. Sacramento Municipal Utility District 2pp 18715 281 P4X Fiche 50-312,83/05/18.8306020317

- 8305010399 Informs that add1 clad swell & rupture model calculations in progress.per NURCO-0630 implementation schedule Final rept will be issued by 630620 ROBRIGUEZ,R J Sacramento Municipal Utility District 83/05/23 STDLZ,J F Operating Reactors Branch 4 ip 18682 240 24x Fiche 80-312.83/05/23.8306010399
- B306140751 Forwards request for add) info in response to Generic Ltr B2-21 re natural circulation cooldown Response requested within 60 days STGLZ: J F Operating Reactors Branch 4 B3/05/25 RODRIQUEZ, N J Bacramento Municipal Utility District App 18845 339 24X Fiche 50-312, 83/05/25,8306140751
- 8306070216 Corrected Board Notification 83-21C forwards Figure: 1-6 inadvertently omitted from 830428 submittal re auxiliary feedwater effectiveness at BRM-designed plants EISENHUT, D. G. Division of Licensing 83/05/26 Atomic 8afety and Licensing Appeal Panel 2pp 18742 157 24X Fiche 50-312,83/05/26,830670216
- 8304090393 Forwards request for add1 info re three open items concerning controls for handling heavy loads Franklin Research Gtr draft technical evaluation encl Response requested within 40 days of receipt of 1tr STOLZ, J F Operating Reactors Branch 4 83/05/31 RODRIGUEZ, R J Bacramento Municipal Utility District 13pp 18815 037 24X Fiche 50-312,83/09/31.8306090393
- --830A070397 "Control of Heavy Loads, Sacramento Municipal Util District, Rancho Seco Nuclear Generating Station," draft technical evaluation rept
 VOSBURY,F W. VITO,D J., SANGENT,1 H. Franklin Institute/Franklin Research Center NRC-03-81-130 TER-05287-388 DRFT 83/01/13
 CLEMENSON,F NRC No Detailed Affiliation Given 20pp
 18815-050 24X Fiche 50-31P.83/05/31.8306070393
- 830A090233 Provides info for resolution of NUREO-073/. Item II E 1 i apen items re review of upgraded auxiliary feedwater sys RDBRIGUEZ.R J Sacramento Municipal Utility District 63/04/03 STOLZ, J F Openating Reactors Branch 4 2pp 18795 342 24X Fichm. 50-312, 83/04/03. 8304090233
- 0304170402 Application for amend to License DPR-54, revising Tech Spec Table 4 1-1 re requirement for nuclear instrumentation calibr RODRIQUEZ,R J Sacramento Munical Utility District 03/06/04 EISENHUT,D G Division of Licensing 2pp 18879 019 24X Fiche. 50-312,83/06/06,8306170402
- --8306170407 Proposed Tech Spec Table 4 1-1, requiring nuclear instrumentation (NI) calibr only when heat balance measured power level exceeds NI measured power level by more than 2 percentage points # Sacramento Municipal Utility District 83/06/06 ip 18879 021 24X Fiche 50-312,83/06/06,8306170402
- 8306140126 Forwards response to B30524 telcon request for add1 info re spent fuel pool expansion Procedure for reracking as followup to B30217 meeting also provided RODRIGUEZ.R J Sacramento Municipal Utility District, 83/06/07 81012.J F Operating Reactors Branch 4 3pp 18837 087 24X Fiche 50-312.83/06/07.8306140126
- 8306140377 Forwards revised Table D-1, "Preliminary Stress Loye)
 Comparison," showing value of stress concentration factor &
 higher calculated peak stresses Higher peak stresses do not
 affect conclusions from 830506 mueting. Maeting summary encl
 TAYLOR, J H. Dabcock & Wilcox Co. 83706/07 MINER, B. NRC No
 Detailed Affiliation Given. 2pp. 18843-067 24X
 Fiche 50-000,83706/07,8306140377
- B306220206 Summary of B30217 meeting w/util & contractor in Orthesda, HD re proposed spent fuel pool expansion Supporting documentation enci
 MINER, B Operating Reactors Branch 4 83/06/08 Operating Reactors Branch 4 83/06/08 Operating Reactors Branch 4 55pp 16777 256 24X Fiche 50-312,83/06/08.
- 8306210048 Provides status of HPI/makeup norile thermal sleeve investigation No evidence of fuel failure found as result of thermal sleeve pieces residing in reactor vessel Sketch of thermal sleeve recovered from lower grid assembly encl RODRIGUEZ.R.J Bacramento Municipal Utility District 83/06/13 BTOLZ.J.F Operating Reactors Branch 4 3pp 18912 306 24X Fiche 50-312,83/06/13,8306210048
- 8306220040 Notifies of error in 830506 ltr re containment instrumentation upgrades per NURFG-0737, Items, II F i 4, II F i 5 & II F i, 6 Existing instrument display is indicator not recorder.
 RODR190E2, R J Bacramento Municipal Utility District 83/06/I. RODR190E2, R J Bacramento Municipal Utility District 83/06/I. EYOLZ, J. F Operating Reactors Branch 4 2pp 18928 208 24% Fiche 80-312,83/06/17,8306220040.

- 8306220075 Clarifies info provided in 830502 ltr re NUREO-0737. Item II B 3 "Post-Accident Sampling Sys (PABS)." per 830526 request Equipment ordered to allow powering of analyzer & salenaid valves from reliable source within 3 & RODRIGUEZ.R J Sacramento Municipal Utility District 83/06/17 STOLZ.J F Operating Reactors Branch 4 &pp 18930.164. 24X Fiche 50-312.83/06/17.6306220075
- 8306220150 Provides add1 info re 830428 request for exemption to allow delay until plant startup following Cyrle 8 for upprading loss of main feedwater portion of anticipatory reactor trip sys per TMI Item II K 2 10 RODRIGUEZ, R J Sacramento Municipal Utility District 83/06/17 STGLZ, JF Operating Reactors Branch 4 2pp 18786 196 R4X Fiche 50-312.83/06/17.8306220150
- 8306230447 Responds to NRC 830603 & 10 telcon requests for addl info re NUREO-0737. Item II B 2. "Plant Shielding." RODRIGUEZ.R J Bacramento Municipal Utility District 83/06/17 MARTIN.JB Resion 5. Office of Director 4pp 18742.083. 24X Fiche 50-312.83/06/17.8306230447
- 8304270240 Forwards "Bounding Analytical Assessment of NUREQ-0600 Models on LOCA kW/Ft Limits" RDDRIGUEZ:R J Sacramento Municipal Utility District 83/06/20 STOLZ:J F Operating Reactors Branch 4 2pp. 18790 231 24X Fiche 50-312,83/06/20,8304270260
- 8306270133 Forwards add1 info re NUREG-0737, Item II E i.i. "Auxiliary Feedwater Sys Upgrade Review." per 830502 & 0603 ltrs.in response to NRC 820407 ltr Condensate storage tank not damaged by wind loads generated by 175 mph winds RODRIGUEZ.R J Sacramento Nunicipal Utility District. 83/06/21. STOLZ.J R Operating Reactors Branch 4. Spp. 1870B 011 24X Fiche 50-312.83/06/21.8306270133
- O Inspection reports. IE Bulletins & correspondence
- 8306100009 Add1 response to FOIA request for Socuments dtd 820101 or after re SALP.Forwards App A documents Documents also available in FDR FELTON.J M Division of Rules and Records 83/04/11 CLARK.R. Ban Francisco Examiner 3pp 10815 252 24X Fichs 50-000.83/04/11, 8306100007
- --8306100014 Submits schedule for Region V SALP Board meetings for BR0920-830523
 ENORLKEN,R II Region 5. Office of Director 82/03/19
 DENTON,H R Office of Nuclear Reactor Regulation, Director, DAVIS,J G Office of Nuclear Material Safety & Bafguards, Director MICHGI BON, C. Director's Office ip 18815 259 24X Fiche 50-000.83/04/11.830610D009.
- --B306100032 Requests brief performance analysis & recommended conclusion for each functional area inspected, based on review of summary of inspectivities & analyses of LERs & noncompliance items issued from Jul 1781 Bept 1782.

 STERNBERO, D M Repion 5. Office of Director. B2/03/23, YOUNG, T, CANTER, H, C'BRIEN, J Region 5. Office of Director ip 18815, 286 24X Fiche 50-000, 83/04/11, 8306100009
- --8306100036 Discusses assignment of SALP coordinators for Reactor Operations Projects Branch facilities Coordinators will be responsible for preparing input data used by board members in analyzing functional areas Draft note from 8 Miner encl STERNBERO,D, M Region 5. Office of Director. 82/03/24. Region 5. Office of Director. 82/03/24. Region 5. Office 06 Director. 82/03/24.
- --8306100038 Forwards input to BALP rept CHCKSHI.N Structural Engineering Branch. 82/10/18, MINER, B. NRC - No Detailed Affiliation Given Spp. 18815 271. 24X Fiche 50-000.83/04/11,8306100009
- --8306100039 Forwards evaluation of licenses performance for safeguards licensing portion of SALP review per Sternberg 821014 memo Util has responded quickly & accurately to NRC-initiated comments & suggestions MCCORNE.6 W. Power Reactor Bafeguards Licensing Branch. 82/11/04 NDRDERHAUO, L. Region 5, Office of Director Spp 18815.288 24X Fiche 50-000.83/04/11.8306100009.
- --8306100040 Forwards brist description of investigative activities of seven cases re BALF during Jul 1981 Sept 1982, Allegation against contract personnel using controlled drugs during outages still pending.

 SHACKLETON, D G Region 5, Office of Director. B2/11/10, WILLETT, D. Region 5, Office of Director 2pp 18815 291. PAX Fiche 50-000,83/04/11,8306100009

- --8306100044 Comments on 821014 memo re SALP Board review of facility NORTH-H Region 5. Office of Director 82/11/10 WILLETT.D Region 5. Office of Director 2pp 18815 293 24X Fiche 50-000,83/04/11,8306100009
- --8306109047 Forwards SALP rept inadvertently omitted from 821202 ltr & revised agenda for SALP 830105 meeting STERNBERG, D M Repion 5, Office of Director 82/12/15 MATTHMELJ J Sacramento Kunicipal Utility District 1p 18815, 304 24X Fiche 50-000, 83/04/11, 8306100009
- 830&0703&4 Forwards IE Insp Rept 50-312/83-10 on 830310-0429 & notice of violation.
 STERNBERO, D M Region 5, Diffice of Director 83/05/09 RODRIGUEZ, R Sacramento Municipal Utility District 2pp 18743 062 24X Fiche 50-312
- --8306070378 Notice of violation from insp on 830310-0427 YOUNG, T. Region 5, Office of Director 83/05/09 ip 18743 064 24% Fiche 50-312-83/05/09,8306070364.
- --8306070385 IE Insp Rept 50-312/83-10 on 830310-0429 Noncompliance noted failure to rept 830326 & 0401 degradation in fuel cladding within 24 h. CARTER, H L , D'BRIEN.J P , YGUNO, T Region 5. Office of Director 83/05/06 9pp. 18743 065 24X Fiche 50-312.83/05/09.8306070364
- 8306070057 Forwards IE Insp Rept 50-312/83-11 on 830411-15 No noncompliance noted.
 STERNBERG, D M Region 5, Office of Director 83/05/12 RODRIGUEZ, R J. Secremento Municipal Utility District. 2pp 18739, 320 24x Fiche 50-312, 83/05/12, 8306070057
- --8306070065 IE Insp Rept 50-312/83-11 on 830411-15 No noncompliance moted Major areas inspected inservice insp program & implementing procedures, inservice insp activities & quality records
 HABNER, H. J. ZWETZIG, G. B. Region 5, Office of Director 83/05/11
 Spp. 18739-322 24X Fiche. 50-312,83/05/12,8306070057
- 8306070152 Forwards IE Insp Rept 50-312/83-12 on 830411-15 & notice of Violation. 8CARANO.R A Division of Radiological Bafety & Safeguards Program 83/05/47, RODRIQUEZ.R J Sacramento Municipal Utility District 2pp 18736:243 24X Fiche 50-312.83/05/17.8306070152
- --8306070157 Natice of violation from insp on 830411-15 WENSLAMSKI, F A. Region 5. Office of Director 83/05/17 18736,245 24 Fiche 50-312,83/05/17.8306070152
- --0306070176 IE Insp Rept 50-312/83-12 on 830411-15 Noncompliance noted failure to post & control radioactive contaminates areas, to properly package & identify packaged radioactive contaminated mat1 & enforce frisking requirements.

 CILLIS.M. WENBLAWSKI.F. A. BOOK.H. E. Region 5, Office of Director 83/05/17 i5pp 18736 247. 24X Fiche 50-312,83/05/17, 8306070152
- 830511045B IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in Hell Logging Device " Syr list encl. TAYLOR, J H Division of Safeguards & Inspection Programs (Post 830103). 83/05/26 Consolidated Edison Co. of New York, Inc 125pp. 18831 043 24X Fiche 50-000,83/05/26,8305110458
- 8305:10460 IE Info Notice 83-34, "Event Notification Info Worksheet" Svc list enc! JORDAN, E. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26. Convolidated Edison Co of New York, Inc. 118pp 18732 085 24x Fiche 50-000, 83/05/26, 8305;10460
- 8306280175 Forwards IE Emergency Preparedness Insp Rept 50-312/83-09 on 830328-0401 No noncompliance noted NORDERHAUDLE Region 5. Office of Director 83/05/27 HATTIMOELJ J. Sacramento Municipal Utility Dietrict 2pp. 19014
- --B3062B0183 IE Emergency Preparedness Insp Rept 50-312/B3-07 on B3032B-0401.No noncompliance noted Major areas inspected corrective actions re 21 significant findings identified in B10831 immediate action 1tr & emergency detection NORTH-H.9, SCHUSTER.M D Region 5, Office of Director B3/05/24, 15pp. 14014:151, 24x Fiche.50-312,83/05/27,8306280175
- 8305110461 IE Info Notice 83-35, "Fuel Movement W/Control Robs Withdrawn at BWRs." Svc list encl UCROAN.E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 89/05/31 Consolidated Edison Co. of New York, Inc. 116pp. 18732: 208. 24X Fiche: 50-000, 83/05/31,8305110461

- 8305110464 IE Info Natice 83-36. "Impact of Security Practices on Sofe Operations " Svc) 1st encl JORDAN, E. L. Division of Emergency Properodomss & Engineering Response (Post 830103) 83/06/09 Consolidated Edison to of New York, Inc. 119pp 18830 280 24X Fiche 50-000,83/06/09.8305110464
- 8306280R1B Forwards IE Insp Rept 50-312/83-15 on 830516-18 No noncompliance noted SYERNBERG, D M Region 5, Office of Director 83/06/10 RODRIGUEZ, R J Sacramento Municipal Utility District 2pp 19014,179 24X Fiche 50-312,83/06/10.8306280218
- --8306280226 IE Insp Rept 50-312/B3-15 on B30516-18 No noncompliance noted Major areas inspected allegations re electrical const inadequacies IE mgt meeting conducted 830518 Insp Fandings summarized Allegations not substantiated BURDIIN.J C. ZWETZIO.6 B Region 5. Office of Director 83/06/09 4pp 17014 181 24X Fiche 50-312,83/06/10.6306200216
- 8305110470 IE Info Notice 83-36, "Defective Heat Sink Adhesive & Seismically Induced Chatter in Relays Within Printed Circust Cards " Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co of New York, Inc. 118pp 18920 225 24X Fiche 50-000.83/06/13,8305110470
- 8304690010 IE Info Notice 83-37, "Transformer Failure Resulting Irom Degraded Internal Connection Cables " Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison to of New York, Inc. 243pp 18921 001 24X Fiche 50-000,83/06/13,8306090010
- 8305110475 IE Info Notice 83~40, "Need to Environmentally Quality
 Epoxy Grouts & Sealers " Svc]ist encl
 JORDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83706/22 Consolidated Edison & of New
 York, Inc 115pp 17021 179 24X Fiche 50~000.83706/22,83051104/5
- 8305110477 IE Info Notice 83-41, "Actuation of Fire Suppression Sus Causing Inoperability of Safety-Related Equipment " Syr list enc! JDRDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830102) 83/06/22 Compolidated Edison Co of New York, Inc 120pp 18997 007 24X Fiche 50-000,03706/22,030511017
- 8305110479 IE Info Natice 83-42, "Reactor Mode Switch Malfunctions" Svc list encl JORDAN, C L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/23 Consolidated Edison Co of New York Inc 110pp 18996 242 24X Fiche 50-000,83/06/23,8305t10479
- 8303110483 IE Info Notice 83-43, "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints " Syc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Past 830103) 83/06/24 Consolidated Edison Co of New York, Inc 116pp. 19046-297 24X Fiche 50-000,83/06/24,830511048)
- 8306300007 Ack receipt of 830606 ltr informing NRC of steps taken to correct violations noted in IE lnsp Rept 50-312/83-10
 STERNBERG, D M Region 5, Office of Director 83/06/24
 RODRIGUEZ, R J Sacramento Municipal Utility District 1p
 19121 031 24X Fiche: 50-312,83/06/24,83063000007
- --83063000ii Responds to NRC 830507 ltr re violations noted in Ji Insp Rept 50-312/83-10 Corrective actions during Cycle & proper closure of penetrations prior to leaving cold shutdown will be verified by performing local loak rate test RODRICUEZ,R J Sacramento Municipal Utility District 83/06/06 MARTIN,J B Region 5. Office of Director App 19121 032 24X Fichs 50-312.83/06/24,8306300007
- R Periodic operating reports & related correspondence
- 8306210056 Monthly operating rept for May 1983 W/030608 ltr. COLOMBO,R , OUBRE,R P Sacramento Municipal Utility District 83/06/08 Director's Office, Office of Inspection and Enforcement 8pp 18911 344 24% Fithe 50-312,83/06/08,8308210026
- S Reportable occurrences, LERs & related correspondence
- 8306:00070 Part 21 rept re abnormal indications in upper core barrel bolting identified during ultrasonic testing Initially reported on 830328 Bamples to be removed from internals & azamined TAYLOR.J H Babcock & Wilcox Co 83/04/11 DEYDUNG, R C Director's Office. Diffice of Inspection and Enforcement 5pp. 18802 095 24X Fiche 50-312.83/04/11.8306100090

- 8306070067 Revised LER 83-008/03L-1 on 830215, commitment made in response to 810908 SER to isolate auxiliary steam line penetrating HPI pump A room not implemented Caused by personnel not aware of requirement W/830820 itr COLOMBOR W. RODRIOUEZR J. Sacramento Municipal Utility District 83/04/19 MARTIN, J B. Region 3, Office of Director Spp 18740 095 24X Fiche 50-312,83/04/19,8306070067
- B306170358 LER B3-016/03L-0 on B30331.during surveillance testing on snubbers.10 snubbers mfg by Grannell & Dergen-Patterson failed acceptance criteria Caused by defective seals.body corrosion & water in fluid Valves rebuilt W/B3042B ltr CQLCMB0.R W. RODRIGUEZ.R J. Sacramento Municipal Utility District B3704/2B MARTIN.J B Region 5. Défice of Director 2pp 18880 218 24X Fache 50-312, B3/04/28, B306170358
- 8306170223 RO on 830324-0505, cooling tower circulating basin drained for maint Folsom Canal also inoperable from 830408-26 From 18008-26 From 18008-26 From 18008-26 From 18008-26 From 18008-26 From 18008-26 Price 50-312,83/05/26,8306170223
- 8306070069 Part 21 rept re defective Woodward governor/artivator, Type E0D-13C Pointer discs machined to remove 1/16 inch from diameter Activator overhauled Util will replace brushes when spare parts available RODRIGUEZ, R. J. Sacramento Municipal Utility District. 83/05/27 MARTIN, J. B. Region 5. Defice of Director 3pp 18776 175 P4X Fiche 50-312,83/05/27,8306070069
- 8304090304 Part 21 rept re defective Woodward Governor Co activator,
 Type EGB-13C Pointer discs machined to reduce disc diameter
 Commission notified of potential generic problem Brushes in
 125-valt dc motor found worn after everhaul by manufacturer
 RODRIGUEZ.R. J Bacramento Municipal Utility District 83/05/27
 MARTIN.J B Region 5. Office of Director 4pp 18795 187 24X
 Fiche 50-312,83/05/27,8304090304
- 8304170290 LER 83-022/03L-0 on 830507.cooling water to reactor bldg emergency cooling unit A 500c motor found to be drawing locked rotor current preventing valve from stroking Female control disconnect switch found spread apart W/830603 ltr COLOMBO.R W. RODRIGUEZ.R J. Sacramento Municipal Utility District 83/06/03 MARTIN.J B. Region 5. Office of Director 2pp 18877-015 24X Fiche 50-312.83/06/03.8306170290
- 8306230394 Followup LER 82-020/03L-1 on 870726, nitrogen added to pressurizer liquid sample line, causing contamination of nitrogen sys & once-through steam generators due to water flowing into sys W/830607 ltr COLOMBO.R.W. RODRIOUEZ, R. J. Sacramento Municipal Utility District 83/06/07 MARTIN, J.B. Region 5, Office of Director App 18943 122 24X Fiche 50-312, 83/06/07, 8306230396
- B306230372 Part 21 rept re Brand-Rex Co Typa 3/C 12 wire cable deficiency Initially reported on 830613 Six suspect wire reals quarantined Records researched to insure suspect cable not used in Class I areas RODRIOUEZ, R J Sacramento Municipal Utility District 83/06/16 MARTIN, J B Region 5, Office of Director 4pp 18742 300 24) Fiche 50-312,83/06/16,8306230372
- B306230410 LER B3-024/03L-0 on B30519, breaker 524806 tripped on ground fault 4500 Caused by cable jacket & insulation damaged furing installation Cable will be repulled & spliced to eliminate ground. W/B30618 ltr COLOMBO.R W , RODRIGUEZ.R J Bacramento Municipal Utility District B3/06/16 MARTIN.J B Region 5, Office of Director App 18943 134 24% Fiche. 50-312, 83/06/16, 8306230410
- DOCKET 50-313 ARKANBAS NUCLEAR ONE, UNIT 1

 F Security, medical, emergency & fire protection plans
- 8306070298 Submits supplemental response to IE Insp Repts 50-313/82-33 & 50-368/82-33 Completion date for revised procedures refire barriers changed to 830531, Add1 time necessary to incorporate App R changes
 MARSHALLIJ R Arkanses Power & Light Co 83/04/12 SEIDLE, H C
 Region 4, Office of Director. 1p. 18740, 313 24X
 Fiche 30-313,83/04/12,8306070298
- 8306010101 Forwards IE Insp Repts 50-313/83-05 & 50-368/63-05 on 830314-17 No noncompliance noted Open items will be examined during future insp SEIDLE W C Region 4: Office of Director 83/05/12. GRIFFIN.J.M. Arkansas Fower & Light Co Rpp 18674.117, 24X Fichs 50-313.83/03/12.8304010101

- --8306010107 IE Insp Repts 50-313/83-05 & 50-368/83-05 on 830314-17. No noncompliance noted Major areas inspected licensee performance & capabilities during full-scale exercise of emergency plans & procedures

 HACKNEY.C A , BANOART.R L , HOLLEY.W L. Region 1, Office of Director 83/05/09 2Bpp 18674 119 24X Fiche 50-313.83/05/12, 8306010101
- B306030073 Forwards safety evaluation re safe shutdown capability in event of fire Commitment requested for source range neutron flux monitoring capability & schedules for submittals by B30528
 BTOLZ.J F Operating Reactors Branch 4 CLARK.R.A Operating Reactors Branch 3 83/05/13 GRIFFIN.J M Arkansas Power & Light Co 2pp 18733 249 24X Fiche 50-313.83/05/13.8306030073
- --8306030078 Safety evaluation re 10CFRSO App R. Items III 0 3 & III L, re safe shutdown capability. Util design acceptable # Office of Nuclear Reactor Regulation, Director 83/05/13 13pp 18733 251 24X Fichs. 50-313.83/05/13,8306030073
- 8306090313 Documents recent telcon re 830315 Tech Spec change request to increase emergency plan & contingency plan audit fraquency Spec applies to both plans.
 MARBHALL.J.R. Arkansas Power & Light Co. 83/05/17 COLLINS.J.T. Region 4. Dépice of Director. pp. 18/95 227 24X Piche 30-313,83/05/17.8306090313
- 8306090248 Provides status of transient brochure distribution program
 Purchase order for holders issued & delivery expected by
 B30606
 MARSHALL, J. R. Arkansas Power & Light Co. 83/05/23 COLLING, J. T.
 Region 4. Office of Director 1p. 18795;318 24X
 Fiche 50-313,83/05/23,8306090248
- 8306060063 Ack receipt of 830429 partial response to 820425 Emergency Plan Evaluation Repts 50-313/81-22 & 50-368/81-21 Response addressing all outstanding deficiencies by revised plan or schedule for plan rev requested BEIDLE, W C Region 4, Office of Director, 83/05/31 GRIFFIN, J M Ankansas Power & Light to 2pp 18723 271 24X Fiche 50-313,83/05/31.8306060063
- --8306060067 Responds to NRC 820625 evaluation of emergency plans. Nuclear contingency plan & procedures & emergency plan being reviewed & revised Response to deficiencies identified by revs encl MARSHALL, J.R. Arkansas Power & Light Co 83/04/29 COLLINS, J.T. Region 4. Office of Director 17pp 18723 279 24X Fiche 50-313,83/05/31.8306060063
- 8304080012 Notifies of commitment to install source range monitoring capability on alternate shutdown sys.per 830513 ltr & 100FR50 App R MARSHALL.J.R. Arkansas Power & Light Co. 83/04/03 STOLZ.J.F. Operating Reactors Branch 4 CLARK.R.A. Operating Reactors Branch 3 2pp 18773.247 24x Fiche.50-313.85/04/03.8304080012
- 8306150032 Releases public version of revised emergency plan implementing procedure. FELTON.JM Division of Rules and Records 83/06/07. Document Management Branch 1p 18871 288 24X Fiche 50-313,83/06/07, 8306180032
- ---8306150034 Public version of Rev 5 to Emergency Plan Implementing Procedure 1903 60, "Emergency Bupplies & Equipment," LEVINE,J M Arkansas Power & Light Co 63/05/05 76pp. 18671 289 24X Fiche 50-313,83/06/07,8306150032
- 8306200056 Releases public version of revised emergency plan implementing procedure.
 FELTON.J M Division of Rules and Records 89/06/07 Document Management Branch ip 18908 295 24X Fiche 50-313,83/06/07.
 8306200056
- --8306200060 Public version of Rev 3 to Emargency Plan Implementing Procedure 1903 01. "Organization & Use of Emergency Plan Implementing Procedures " Receipt form encl. LEVINE, J M Arkansas Power & Light Co 83/04/28. NRC No Detailed Affiliation Given dop 10908, 296. 24X Fich: 50-313, 83/04/07. 8306200056
- 8306140135 Notifies that 1 h fire barriers installed by 830422, per 830329 request for schedular exemption: from App R requirements for installation of barriers to 830801.

 HARSHALLJR Arkanses Power & Light Co. 83/06/08 870LZ, J, F Operating Reactors Branch 4 CLARK, R. A. Operating Reactors Branch 3 1p 18839, 073. 24X Fiche 50-313, 83/06/08, 8306140138

- 8306230474 Submits add1 info re radiation filtration sys for emergency control ctr (ECC).per NUREG-0737. Suppl 1 on emergency response Radiation filtration sys designed to be manually activated Statch of ECC filtration sys encl.
 Arkansas Power & Light Co 83/06/17 STOLZ.J.F. Operating Reactors Branch 4 3pp 18941 307 24X Fichs. 50-313.83/06/17.8306230474
- 830.6240469 Requests exemption from 10CFR50 48(c) for all barriers, penetrations & fire suppression/detection sys be made more specific & detailed by identifying each area requiring examption Behedule for submittal requested in 20 days. STOLZ-J F Operating Reactors Branch 4 CLARK-R A Operating Reactors Branch 4 CLARK-R A Detains Branch 3 B3/06/17 0RIFFIN-J M Arkansas Power & Light Co. 2pp. 18978 085 24X Fichs 50-313,83/06/17,8306240469
- J Insurance & indemnity information
- 8306030294 Forwards certificate of insurance, Policy X82-002 for CY83 MARBHALL, J.R. Artenses Power & Light Co. 83/04/22 DINITZ, I Office of Resource Management, Director 2pp 19703 327 24X Fich# 50-313, 83/04/22, 8304030294
- P Operating license stage documents & correspondence
- 8306060051 Add1 response to FOIA request for three categories of documents re FRA of reactor setaty study methodology application program repts & interim reliability evaluation program repts. Farwards App A documents Bearch continuing FELTON, J M Division of Rules and Records 83/04/07 SMOLLY, B C Union of Concerned Scientists 3pp 18752-001 24X Fichs. 50-000.83/04/07, 8306060051.
- --8207280024 Discusses NUREO/CR-2787. "Interim Reliability Evaluation Program Analysis of AR Nuclear One-Unit I Nuclear Power Plant: "first final rept on four integrated reliability avaiuation program Phase II studies.

 BERNERO,R M Division of Risk Analysis 82/06/24. HANAUER.9 H. Division of Human Factors Safety Spp. 18752 074 24X Fiche 50-000 83/04/07.8306060051
- --8306060061 Statement on background, issues, current status & Puture action re interim & nath reliability evaluation programs.
 * NRC No Detailed Affiliation Given B2/12/31. 2pp.
 18752:059. 24X Fiche.50-000.83/04/07.8306060051
- B306010024 Forwards "Policy Btatement re Alcohol/Brug Abuse & Theft," issued as part of util policies & procedures manual.per 830307 commitment.
 MARSHALL.J R. Arkansas Power & Light Co. 83/05/12 COLLINS.J.T Region 4. 076:ce of Director ip 18674.070. 24X Fiche 50-313.83/05/12.8306010024.
- 8305090313 Documents recent telcon to 830315 Tech Spec change request to increase emergency plan & contingency plan audit frequency. Spec applies to both plans.

 MARSHALL-J R Arkansas Power & Light Co 83/05/17. COLLING. J. T Region 4. Office of Director. ip. 18795 227. 24X

 Fiche: 50-313, 63/05/17, 8306090313
- 8304020135 Comments on App B Tech Spec revs.per 830311 ltr issuing Amends 72 & 40 to Licenses DPR-52 & NPF-6, respectively.
 Util will routinely provide NRC w/changes to NPDES discharge permit. MARSHALL.J.R. Ar MARSHALL-V.R. Ariansas Power & Light Co 83/05/20 STDLZ.J.F Operating Reactors Branch 4 CLARK.R.A Operating Reactors Branch 3. 2pp. 18691:244. 24X Fiche:50-313,83/05/20.8306020135
- 8306010267 Withdraws request for exemption from requirements to install reactor vessel head vents. as installation of vents subsequently decided upon & completed during fifth refueling outage.

 MARSHALL, J. R. Arkansas Power & Light Co. 83/05/24, 8YOLZ, J.F. MARSHALL, J.R. Arkansas Power & Light Co. 83 Operating Reactors Branch 4. 1p 18672-251 Fichs: 50-313,83/05/24,8306010267
- 8306:30499 Forwards SER re justification for continued operation re environ qualification of safety-related electrical equipment. STDLZ.J.F equipment. STOLZ.J.F Operating Reactors Branch 4 83/05/2. Artansas Power & Light Co. 3pp. 18854:348 24X Fiche:30-313.83/05/24.8306150499 89/05/24. GRIFFIN. J. M
- --8306130501 Bafety evaluation supporting 830228 & 0428 ltrs in response to 830126 ltr re SER of environ qualification of safety-related equipment "Office of Nuclear Reactor Regulation, Director 83/05/24, 5pp. 18854;351, 24X Fiche; 50-313,83/05/24,8306150499.

- 8306150519 Forwards request for add1 info re 811118 response to 810505 Generic Ltr 81-21. "Natural Circulation Cooldown " Info should be received within 45 days of ltr receipt BTOLZ,J F Operating Reactors Branch 4 83/05/24 GRIFFIN,J H Arkansas Fower & Light Co 5pp 18866 329 24X Fiche 50-313.83/05/24.8306150519
- 8306010314 Submits update on D&W Owners Group plans to install shunt trip feature to reactor trip sys scram breakers Arkansas Power & Light Co will submit design info during wk of 830530 Owners group endorses facility shunt trip design WALLACE, E Q Babcock & Wilcox Operating Plants Owners Group. WALLACE, E Q General Public Utilities ~ GPU Bervice Corp 83/05/27 EISENHUT, D.O. Division of Licensing ip 18672 310 24% Fichs 50-313.83/05/27,8306010314
- 8306070193 Responds to 830322 ltr re open issues of NUREO-0737, Item II E 1 1. "Auxiliary Feedwater Sys Evaluation " Review of Recommendations GL-2 re environ qualification & GL-4 re flow test to be completed by 830731 MARSHALL, J R Arkansas Power & Light Co 83/05/31 STOL2, J Operating Reactors Branch 4 2pp 18736 296 24% Fichs 50-313,83/05/31,8306070193
- B306200059 Advises that NUREO-0737, Items II F 1 4, II F 1 5 & II F 1.6 requirements resolved per B01219, B20726 & B3040B submittals Environ qualification of equipment will be reviewed separately, SER encl.
 B70LZ.J.F. Operating Reactors Branch 4 CLARK.R.A Operating Reactors Branch 3, B3/06/06 QRIFFIN.J.H Arkansos Power & Light Co 7pp 18708 302 24X Fiche 50-313, B3/06/06, B306200059.
- 830.6140377 Forwards revised Table D-1. "Preliminary Stress Level Comparison," showing value of stress concentration factor & higher calculated peak stresses Higher peak stresses do not affect conclusions from 830506 meeting Meeting aummany encl TAYLOR, J H Babcock & Milcox Co 83/06/07 MINER. S NRC No Detailed Affiliation Given 2pp 18844 001 24X Fiche 50-000,83/06/07,8306140377
- B306160324 Forwards design info re addition of shunt trip to reactor protection sys trip breakers for NRC review & approval Shunt trip capability poses no unreviewed safety question W/two oversize diagrams Aperture cards are available in PDR MARSHALL-JR Arkansas Fower & Light Co 83/06/07 970L2, JF. Operating Reactors Branch 4 49pp 18862 258 24x Fiche 50-313,83/06/07,8306160324
- 8306160493 Forwards "Bounding Analytical Assessment of NUREO-0430 Models on LOGA kW/ft Limits," reflecting use of FLECSET heat transfer correlation as compensating model to reduce impact of NUREO-0430 models or numew-us;0 mpagis MARSHALL:J.R Arkansas Power & Light Co 83/06/00 Operating Reactors Branch 4 ip 18862.083 24X Fichs 50-313.83/06/08.8306160493 83/04/08
- --B306160497 "Bounding Analytical Assessment of NUREO-0630 Hodels on LOCA HW/ft Limits "
 # Babcock & Wilcox Co 77-1143707-00 83/06/08 18862 085 24% Fiche 50-313,83/06/08 8306160493
- 8306/70275 Responds to NRC 830509 request for submittal of license amend applications incorporating snubber surveillance program into App A Tech Bpecs, Program outlined in 830228 ltr will be followed pending NRC review of ANSI 0M-4 8td MARSHALL, J.R. Arkansas Power & Light Co. 83/06/10 STOLZ, J.F. Operating Reactors Branch 4 CLARK, R.A. Operating Reactors Branch 3 2pp 18878 257 24X Fiche 50-313,83/06/10,8306170275
- 8306170408 Documents commitment to administratively impose temporary restrictions on plant operating LOCA limits as result of NUREQ-0630, per 830608 telcon Review of FLECSET data requested MARSHALL, J.R. MARSHALL, J R. Arkenses Power & Light Co 83/06/10 Operating Reactors Branch 4 3pp 18879 022 24X Fichs. 50-313, 83/06/10, 8306170408
- 8305230514 Requests remittance of Class III fee since review of 820502 application raquesting exemption from certain requirements of 10CFR50 44(c)(3)(iii) re reactor vessel head vents begun prior to 830524 application withdrawal DIQGER M License Fee Management Branch. 83/06/j6 GRIFFIN, J M Arkansas Power & Light Co ip 18951 362 24X Fichs. 50-313, 83/06/16, 8306230514
- O. Inspection reports, IE Bulletine & correspondence
- 8304080172 Forwards IE Insp Rept 50-313/82-34 & 50-368/82-37 on 821213-16 & notice of violation 8EIDLE,W C. Region 4. Office of Director. 83/03/04 GRIFFIN Arkansas Power & Light Co 2pp. 18771 161. 24X Fiche 50-313,83/03/04,8306080192

- --83060B0197 Notice of violation from insp on 821213-16 * Region 4. Office of Director 83/03/04 2pp 18771 163 24X Fiche 50-313 83/03/04.83060B0192
- --8306080838 IE Insp Rept 50-313/82-36 & 50-368/82-3/ on 821213-16
 Noncompliance noted update of Unit I FSAR showed radiation
 romes less than 100 m/h, when actual survey data indicated
 radiation levels exceeded 100 m/h
 CHANEY.H D. WILBORN.L . MUKRAY.B Region 4. Dffice of Director
 83/02/28 17pp 18771 165 24X Fishe 50-313.83/03/04.8306080192
- 8306160537 Responds to 821025 IE Insp Repts 50-313/82-14 & 50-368/82-11. Item 8 re control room dose calculations Item re NURE9-0737. Item II 8 2. "Plant Shielding," closed MARSHALL, J R Arkansas Power & Light Co 83/03/24 COLLINS, J T Region 4. Office of Director 2pp 18063 II5 24X Fiche 50-313.83/03/24.8306160537
- 8304070298 Bubmits supplemental response to IE Insp Repts 50-313/88-33 & 50-368/82-33 Completion date for revised procedures refire barriers changed to 830931 Addl time necessary to incorporate App R changes
 MARSHALL-JR Arkanses Power & Light Co 83/04/12 SEIDLE, W C Region 4, Office of Director 1p 18740 313 24X
 Fiche 50-313,83/04/12.8306070790
- 8306220204 Ack receipt of 83040/ payment of civil penalties proposed by NRC 830308 ltr Corrective actions will be examined during future insp AXELRAD, J A Enforcement Staff 83/04/12 MARSHALL, J R Arkansas Power & Light Co 2pp 18977 307 24X Fiche 50-313,83/04/12.
- 830&010101 Forwards IE Insp Repts 50-313/83-05 & 50-368/83-05 on 830314-17 No noncompliance noted Open items will be examined during future insp SEIDLE, W C Region 4. Office of Director 83/05/12 GRIFIN, J M Arkansas Power & Light Co Ppp 18674 117 24X Fiche 50-313,83/05/12.830&010101
- ---8304010107 IE Insp Repts 50-313/83-05 & 50-368/83-05 on 830314-17 No noncompliance noted Major areas inspected licensee performance & capabilities during full-scale exercise of emergency plans & procedures.
 HACKNEY, C A . BANGART, R L . HOLLEY, U L Region 1. Office of Director 03/05/09 20pp 18674 117 24X Fiche 50-313,83/05/12,8305010101
- 8306140359 Forwards IE Insp Repts 50-313/83-09 & 50-368/83-09 on B30401-30 No noncompliance noted SEIDLE, W C Region 4: Office of Director 83/05/18 GRIFFIN, J M. Arkansas Power & Light Co 2pp 18832 143 24X Fiche 50-313,83/05/18:8304140359
- --8306140363 IE Insp Repts 80-313/83-07 & 50-368/83-07 on 830401-30. No noncompliance noted Major areas inspected operational safety verification following no reactor trip breaker failure & plant startup after refueling CALLAN.L J. CUMMINS.J L. JOHNSON,M D. Region 4. Office of Director 83/05/16 App. 18832-145 24X Fichs 50-313,83/05/18,8306140359
- B306130222 Updates status of efforts & progress re drawing control Progress made in progrem to update mylars transferred from corporate of As of B30511.2.714 drawings updated & reissued Info responds to IC Hylletin CO-06 MARSHALL.JR Arkansas Power & Light Co 83/09/23 SEIDLE, W C Region 4. Office of Director Spp 18926 324 24X Fichs 50-313,83/05/23,8306130222
- 8305110458 IE Info Notice 83-32. "Ruptured Am-241 Sources Contained in Well Logping Device" Svc list encl
 TAYLOR, J M. Division of Safeguards & Inspection Programs (Post
 830103) 83/05/26 Consolidated Edison Co of New York, Inc
 125pp 18831.043 24X Fiche 50-000,83/05/26,8305110458
- 8305110460 IE Info Notice 83-34, "Event Notification Info Worksheet" 8vc list enti JORDAN, EL Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co. of New York. Inc 115pp 18732 085 24X Fiche 50-000.83/05/26.8305110460.
- 8305110461 IE Info Notice 83-35. "Fuel Movement W/Control Rods Withdrawn at BWRs." Svc list enc! JORDAN, E.L. Division of Emergency Proparedness & Engineering Response (Post 830103) 83/05/31 Consolidated Edison Co. of New York, Int. 116pp 18732 208 24X Fiche 80-000,83/05/31,9305110461

- 8306060063 Ack receipt of 830429 partial response to 820625 Emergency Plan Evaluation Repts 50-313/81-22 % 50-368/81-21 Response addressing all outstanding deficiencies by revised plan or schedule for plan rev requested SEIDLE.W C Region 4. Office of Director 83/05/31 ORIFFIN, J M Arkansas Power & Light Co 2pp 18723 271 24% Fiche 50-313.83/05/31.8306060063
- --8306060607 Responds to NRC B20625 evaluation of emergency plans Nuclear contingency plan & procedures & emergency plan being reviewed & revised Response to deficiencies identified by revs encl
 MARBHALLJR Arkansas Power & Light Co 83/04/29 COLLINS, J T Region 4, Office of Director 17pp 18723 273 24X
 Fiche 50-313,83/05/31,8306060063
- B306070380 Ack receipt of B30517 ltr informing NRC of steps taken to correct violations noted in 1E lnsp Repts 50-313/83-06 & 50-380/83-06 BEIDLE, W. C. Region 4. Office of Director 83/06/02 ORIFFIN, J. M Arkansas Power & Light Co. 2pp 18741 346 24X Fiche 50-313,83/06/02,8304070380
- --8306070384 Responds to NRC 830418 ltr re violations noted in IE Insp Repts 50-313/83-06 & 50-368/83-06 Corrective actions; procedures revised to define interface responsibilities & coordination required for radioactive shipments MARBHALL.J.R. Arkansas Power & Light Co. 83/05/17 BEIDLE.W C Region 4. Office of Director 4pp 18741 348 24X Fiche 50-313,83/06/02,83060/0380
- 8305110464 IE Info Notice 83-36, "Impact of Security Practices on Safe Operations" Svc list encl JORDAN, C. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/07 Consolidated Edison Co. of New York, Inc. 117pp 18830 280 24X Fiche 50-000, 83/06/09, 8305110464
- B306140050 Responds to IE Bulletin 83-03, "Check Valve Failures in Raw Water Copling Sys of Diesel Generators " Check valves described in bulletin not employed at facilities Bulletin not applicable MAREHALL, J. R. Arkansas Power & Light Co. 83/06/10 STOLZ, J. F. Operating Reactors Branch 4 CLARK, R. A. Operating Reactors Branch 3 ip 18838 288 24X Fiche 50-313, 83/06/10,8306140050
- 8305110470 IE Info Notice 83-38, "Defective Heat Sink Adhesive & Seismically Induced Chatter in Relays Within Printed Circuit Cards" Svc list encl JORDAN, C. L. Division of Emergency Preparedness & Engineering Response (Post 830103), 83/06/13 Consolidated Edison Co. of New York, Inc. 118pp 18920 225, 24% Fiche 50-000, 83/06/13, 8305110470.
- 8304090010 IE Info Notice 83-37, "Transformer Failure Resulting From Degraded Internal Connection Cables" Svc list and JURDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/13 Consolidated Edison Co. of New York, Inc. 243pp 18921 001 24X Fich# 50-000,83/06/13,8304090010
- 8306160524 Ack receipt of 830324 ltr informing NRC of corrective actions taken on open item identified in IE Insp Repts 50-313/82-14 & 50-368/82-11 Btatus of open item will be reviewed in future insp SEIDLE, W C. Region 4. Office of Director 83/06/13 GRIFFIN, J. M. Arkansas Power & Light Co ip 18862 231 24X Fiche, 50-313,83/06/13,8306160524.
- 8305110475 IE Info Notice 83-40, "Need to Environmentally Qualify
 Epoxy Grouts & Sealers " Syc list encl
 JORDAN, C L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/06/22 Consolidated Edison Co. of New
 York, Inc 115pp. 19021 J79. 24X fiche 50-000,83/06/22,8305110475
- 9305110477 IE Info Natice 83-41, "Actuation of Fire Suppression Systems of Inoperability of Safety Related Equipment," Syc list sact JORDAN, C. Division of Emergency Preparedness & Engineering Response (Past 830103) 83/06/22 Consolidated Edison Co. of New Yorks Inc. 120pp. 18997 007, 24x Fiche 50-000,83/06/22,83051j0477
- 8305110479 IE Info Notice 83-42, "Reactor Mode Switch Melfunctions." Svc list encl. JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/23 Consolidated Edison Co. of New York, Inc 116pp 18996.242 24X Fiche 50-000,83/06/23.8305110479
- 8305110483 IE Info Notice 83-43, "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints " Bvc list encl. JORDAN, C. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/66/24 Consolidate Edison Co. of New York, Inc 116pp 19046-297, 24X Ficher 50-000, 83/06/24, 8305110483.

- 8306300075 Ack receipt of 830427 & 0527 ltrs informing NRC of steps taken to correct violations noted in IE Insp Repts 50-313/83-02 & 50-368/83-02 8 EDLE: W C Region 4. Defice of Director 83/06/27 GRIFFIN.J M Arkansas Pawer & Light Co ip 19114-247 24% Fiche 50-313,83/06/27.8306200075
- --8306300079 Responds to NRC 830513 ltr re violations noted in 1E lnsp Repts 50-313/83-02 & 50-368/83-02 Corrective actions review of all design change packages, closed out since administrative procedures revised, espected by 830701 MARSHALL, J R Arkansas Power & Light Co. 83/05/27 SEIDLE, U C Region 4, Office of Director. 2pp 1914 248 24X Fiche 50-313,83/04/27,8306300075

R Periodic operating reports & related correspondence

- B3060200Bi Monthly operating rept for Mar 1983 W/B3042B ltr.
 MDRTON.K L : MARBHALL.J R Arransas Fower & Light Co 63/04/27
 HALLER,N M 0ffice of Resource Management, Director 7pp
 18691 216 24X Ficher 50-313-83/04/27, B3060200Bi
- 8306130057 Advises that add1 time required to review annual environ operating rept Rept will be submitted by 830531 MARSHALL.JR Arkenses Power & Light Co 83/04/29 COLLING.JT Region 4. Office of Director 1p 18824 244. P4X Fiche: 50-313,83/04/29.8306130057
- 8304040253 Bubmits regulatory response & commitment control programfourth monthly progress rept Review of priority assignment schame completed Next status rept will be sent by 830614 MARBHALL.J.R Arkansas Power & Light Co. 83/05/13 COLLINS, J T Region 4: Office of Director 3pp. 1872 226 24X Fichs. 50-313, 83/05/13, 83/0604028
- 8306160561 Monthly operating rept for Apr 1983 W/830516 ltr MARSHALL,J R , MORTON,K V Arkenses Power & Light Co. 83/05/15 BASSETT,H 8 Division of Data Automation & Management Information 7pp. 18865 128 24K Fiche 30-313,83/05/15,8306160561
- 8306210125 Forwards 1982 annual environ monitoring rept W/o encl. MARSHALL, J. R. Ankansas Power & Light Co. 83/06/03. COLLINS, J. T. Region 4. Office of Director Ip. 18918 133 24X Fichs 50-313.83/06/03.8306210125

8. Reportable occurrences, LERs & related correspondence

- 8306430409 NPDES noncompliance notification on 830406, during routine surveillance of oils water separator. Light oil film discovered being discharged from Outfall COS Caused by leak from feedwater pump lube oil sys Bldg oil sumps cleaned GRIFFIN. J. Arkansas Power & Light Co. 83/04/20 CDLLINS, J.T. Region 4, Office of Director 5pp. 18823, 240. 24X Fiche 50-313,83/04/20,8306130409
- 8306160469 LER 83-012/03L-0 on 830519. w/plant heatup/startup in progress, suxiliary feedwater pump P-75 outboard mechanical seal failed Gause unknown Seal rebuilt & reinstalled W/830609 ltr MCE00ENBERO.D., MARSHALL.J.R. Arkansas Power & Light Co 83/06/09 SEIDLE.W.C. Region 4. Office of Director. 2pp 18863 231 24X Fiche 80-313, 83/06/09. 8306160469
- 8306i606i4 LER 83-011/03L-0:on 830524, while performing annual surveillance on electric driven emergency feedwater pump P-78 butboard thrust bearing temp observed to be high Caused by excessive thrust bearing clearance. W/30609 ltr MOEQGENBERO, D.: MARSHALL, U.R. Arkansas Power & Light Co. 83/06/09 BEIDLE.W.C. Region 4. 0ffice of Director. 3pp. 18866 140, 24% Fiche 50-313,83/06/09.8306160614.
- 8306160317 PNO-IV-83-020A, on 830609, reactor tripped. Cause undetermined Trip breaker AKRA failed to close due to personnel failure to follow procedure Closing procedure revised & operations personnel trained.

 MUNNICUTT, D. M. CALLAN, L. J. Region 4, DfPice of Director 83/06/10 p. 18866 143 24X Fiche. 50-313, 83/06/10, 8306160317
- 8306160644 PNO-1V-83-020 on 830609, unit tripped from 97% power from unknown cause. Reactor will remain in cold shutdown until cause determined. On 830610, two ac-supplied reactor trip breakers failed to close Cause under investigation HUNNICUIT. D. H., CALLAN. L. J. Region 4. Office of Director 83/06/10 ip. 18866; 100. 24% Fiche 50-313, 83/06/10, 8306160644.
- B305210003 LER B3-013/03L-0 on B30520, while raising steam generator level for set layup, emergency forduster pump P-78 indicated flow money. I see a set that the set of the se

V Operator Examinations

- 8304220042 Forwards sample questions & answer keys for reactor operator & senior reactor operator requalification exams, per Generic Ltr 82:18 Program beneficial to operator training MARSHALL, J.R. Arkansas Power & Light Co. 83/06/15 870L2. J.F. Operating Reactors Branch 4 CLARK, R.A. Operating Reactors Branch 3 748pp 18930-215 24X Fiche 50-313,83/06/15,830623006/
- DOCKET 50-315 DONALD C COOK NUCLEAR POWER PLANT, UNIT 1

 F Security, medical, emergency & fire protection plans
- 8304100271 Forwards IE Bafeguards Insp Repts 50-315/83-06 & 50-316/83-07 on 830411-15 & notice of violation Notice of violation & rept details withheld (ref 10CFR73 21) MILLER, J R Region 3, Office of Director 83/06/07 DOLAN, J E American Electric Power Service Corp DOLAN, J E Indians & Militar & Electric Co 4pp 18806 254 24% Fiche 50-315,83/06/07,83061002M
- --8306100273 IE Bafeguards Insp Repts 50-315/83-06 & 50-316/8:1-07 on B30411-13 Noncompliance noted agreement w/contractor contains no provisions per security plan & security plan for key control not being followed Safequards info withheld CHRISTOFFER. Q. BELANGER. J. L. CREED. J. R. Region 3. Office of Director 83/06/06 2pp 18806-256 24X Fiche 50-315,83/06/07.8306100271
- 0306300213 Responds to B20730 ltr re emergency preparedness appraisal rept & B20630 notice of violation Adequate performance demonstrated during B21021 exercise Exam of misrepresentation of facts in progress KEPPLER. J Q. Region 3. Office of Director B3/06/07 DDLAN, J E American Electric Power Service Corp DOLAN, J E Indiana & Michigan Electric Co 3pp 19122 101 24X Fiche 50-315.83/06/09,8306300213
- --8306210065 Responds to NRC 830506 ltr re violations noted in IF Into Repts 50-316/83-04 & 50-316/83-05 Corrective actions fire watch established using closed circuit TV I h & 20 minutes after identification of missed surveillance ALEXICH: M P Indiana & Michigan Electric Co 83/06/06 KEPPLER: J G Region 3, Office of Director 3pp 18912 336 P4F Fiche 50-315,83/06/14,8306210057
- 8306210343 Notification of 830683 meeting w/util in Bethesda.MD to discuss App R exemption requests & fire protection safe shutdown analysis WIGGINTON.D Operating Reactors Branch I 83/06/16 VARGA.S A Operating Reactors Branch I 2pp 10921 299 24X Fiche 50-315,83/96/16.8306210343
- 8306230333 Forwards response to 830413 ltr re deficiency in approved physical security plan Response withheld ALEXICH-M P Indiana & Michigan Electric Co 83/06/20 DENTON UR Office of Nuclear Reactor Regulation, Director 1p, 18942-347 24X Fiche 50-315,83/06/20,8306230333

P. Operating license stage documents & correspondence

- 8304020007 Forwards revised Pages 6-23 & 3/4-7 9 for fech Spot changes re record retention Pages reflect changes made in Amends 50,53,68 & 71
 WIGGINTON D Deprating Reactors Branch 1 B3/05/13 DDLAN, J Indiana & Michigan Power Co 200 18702 347 24X
 Fiche 50-315,83/05/13,8306020009
- --8306020012 Revised Pages 6-23 & 3/4 7-6 & 7 for Tech Spec changes site in Amends 50, 53, 68 & 71 re records retention * Operating Reactors Brench | 83/05/13 App 18702 349, 24% Fiche 50-315, 83/05/13, 83/05/1009
- 8306030290 Forwards addl guidance on acceptable solutions to open this re-control of heavy loads in compliance w/NUREO-0612 & draft "Control of Heavy Loads (C-10). Donald C Cook Nuclear Plent Units 1 & 2," technical evaluation rept. VAROA: 5 A Operating Reactors Branch 1 83/05/16 DOLAN: J Indiana & Michigan Electric Co 14pp. 18734-086 24X Fiche 50-315:83/05/16.8306030290

- --8306030279 Draft "Control of Heavy Loads (C-10), Donald C Cook Nuclear Power Plant Units 1 & 2," technical evaluation rept VOSDURY, F W Franklin Institute/Franklin Research Center NRC-03-81-130 TER-C5506-344/345 DR 93/02/24 CLEMENSON, F NRC - No Detailed Affiliation Given 33pp 18734 100 24X Fiche 50-315,83/05/16,8306030270
- 8306020281 Responds to 830510 ltr requesting addl info re status of NUREG-0737. Item II F i Installation of Unit 2 high range containment monitor trending & recording function completed Monitor operational HUNTER, R S Indiana & Michigan Electric Co 83/05/27 DENTON, H Office of Nuclear Reactor Regulation, Director 3pp 18690 315 24X Fiche 50-315,83/05/27,8306020281
- 8306070208 Responds to 830208 Coneric Lt: 83-100 on plans & schedule for resolving NUREG-0737. Item II K 3 5 re trip criteria for reactor coolant pumps Util will follow guidance provided by Hestinghouse & Westinghouse Owners Group ALEXICH:N P Indiana & Michigan Electric Co 83/06/02 EISENHUT.D G Division of Licensing lipp 18747 054 24X Fiche 50-315, 83/06/02 8306070208
- B306210167 Responds to 830501 ltr re payment of processing free for B11111 application, revised on B30225, for review of Tech Spec changes fee encl ALEXICH, MP Indiana & Michigan Electric Co B3/06/21. DENTON, HR Office of Nuclear Reactor Regulation, Director 1p 18915 256 24X Fichs 50-315,83/06/21,8306210167
- 830.6270312 Forwards info re reactor vessel level instrumentation sys, in response to Generic Ltr 82-28 concerning inadequate core cooling instrumentation In-core thermacouple sys will be upgraded to NUREG-0737. Item II F 2 requirements
 HERINO, R F Indiana & Michigan Electric Co 83/06/22
 EISENHUT, D G Division of Licensing 19pp 18993 353 24X
 Fiche 50-313, 83/06/22, 8306270312
- Q Inspection reports. IE Bulletins & correspondence
- 8305110458 IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in Well Logging Device " Svc list encl TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 125pp 18831-043 24X Fiche 50-000,83/05/26,8305110458
- 8305110440 IE Info Notice 83-34, "Event Notification Info Worksheet" Svc list encl JORDANNE L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consulidated Edison Co of New York, Inc 115pp 18732 085 24X Fiche 50-000,83/05/26.8305110460
- 8305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods Withdrawn at BWRs " Syc list enc! JORDAN E. L. Division of Emergency Preparedness & Engineering Response (Fost 830103) 83/05/31, Consolidated Edison Co of New York, Inc 116pp 18732 208 24X Fiche 50-000,83/05/31,8305110461
- B30613025B Forwards IE Insp Repts 50-315/83-07 & 90-316/83-0B on B30425-27 & 0507 & notice of violation STREETER.J F Region 3, Office of Director B3/06/01 DDLAN,J E, American Electric Power Service Corp DDLAN,J.E. Indiana & Michigan Electric Co 2pp 18883 306 24X Fichø 50-315,03/06/01,0306190258
- --8306130263 Notice of violation from insp on 830425-27 & 0507 STREETER, J F Region 3. Office of Director 83/06/01 2pp. 18823 308 24% Fiche 50-315,83/06/01,8306130258
- --8306130273 IE Insp Repts 50-315/83-07 & 50-316/83-08 on 830425-29 & O509 Noncompliance noted incomplete record storage procedures & failure to provide 2-h fire resistant door on records storage vault CHOULES,N,C, SUTHIN,R,N, HAWKINS,F,C, Region 3, Dêfice of Director 83/05/26 9pp. 18823.310. 24X Fiche 50-315,83/06/01,8306130288
- B306100271 Forwards IE Safeguards Insp Repts 50-315/83-06 & 50-316/83-07 on 830411-15 & notice of violation Notice of violation & rept details withheld (ref 100FR73, 21).
 MILLER, J. R. Region 3, Office of Director B3/06/07 DDLAN, J. E. American Electric Power Service Corp. DDLAN, J. E. Indiana & Michigan Electric Co. 4pp. 18806:254 24X Fiche 50-315,83/06/07,8306100271.
- --8306100273 IE Bafeguards Insp Rapts 50-315/83-06 & 50-316/83-07 on 830411-15. Noncompliance noted agreement w/contractor contains no provisions per security plan & security plan for key control not being followed Safeguards info withheld CHRISTOFFER, 0. BELANGER, J L . CREED, J R Region 3. Defice of Director 83/06/06 2pp. 18806 256, 24X Fiche 30-315,83/06/07,8306100271.

- 8305110444 IE Info Notice 83-36, "Impact of Security Practices on Safe Operations" Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/09 Consolidated Edison Co of New York, Inc 119pp 16830 280 24X Fichs 50-000,83/06/09.8305110444
- 8306170129 Submits response to IE Bulletin 03-03, "Check Valve Failures in Raw Water Cooling Sys of Diesel Generator" List of Joh orders for check valves encl
 ALEXICH,M P Indiana & Michigan Electric Co 83/06/09
 KEPPLER,J 0 Region 3, Office of Director 5pp 19878 302, 24X
 Fiche 50-315,83/06/09,8306170129
- 8306300213 Responds to 820730 ltr re emergency preparedness appraisal rept & 820630 notice of violation Adequate performance demonstrated during 821021 exercise Exam of misrepresentation of facts in progress KEPPLER, J Q Region 3, Office of Director 83/06/09 DDLAN, J E American Electric Power Service Corp DDLAN, J E, Indiana & Michigan Electric Co 3pp 19122 101 24X Ficha 50-315,83/06/09,8306300213
- 8305110470 IE Info Notice 83-38, "Defective Heat Sink Adhesive & Seismically Induced Chatter in Relays Within Printed Circuit Cards" Syc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) B3/06/13 Consolidated Edison Co. of New York, Inc. 118pp. 18920 225 24X Fiche 50-000,83/06/13,8305110470
- 8306090010 IE Info Notice 83-37. "Transformer Failure Resulting From Degraded Internal Connection Cables "Svc list encl. JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co. of New York, Inc 243pp 18921 001 24X Fiche 50-000,83/06/13,8306090010
- 8306210057 Ack receipt of 830606 ltr informing NRC of steps taken to correct violations nated in IE Insp Repts 50-315/83-04 & 50-316/83-05 SHAFER.W D Region 3. Office of Director 83/06/14 DOLAN, J.E. American Electric Power Service Corp DOLAN, J E Indiana & Michigan Electric Co ip 18912 355 24X Fichs 80-315,83/06/14,8306210057.
- --B306210065 Responds to NRC 830806 ltr re violations noted in IE Insp Repts 50-315/83-04 & 50-316/83-05 Corrective actions fire watch established using closed circuit TV I h & 20 minutes after identification of missed surveillance ALEXICH M P Indiana & Michigan Electric Co. 83/06/06. KEPPLER, J G Region 3, Office of Director 3pp 18912:356 24X Ficher 50-315,83/06/14,8306210057.
- 8305110475 IE Info Notice 83-40, "Need to Environmentally Qualify
 Epsky Grouts & Bealers " But list encl.
 JORDAN E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/06/22 Consolidated Edison Co of New
 York, Inc 115pp 19021 179 24X Fiche 50-000,83/06/22,8305110475.
- 8305110477 IE Info Notice 83-41, "Actuation of Fire Suppression Bys Causing Inoperability of Safety-Related Equipment " Svc list encl | JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/22 Consolidated Edison Co of New York, Inc. 120pp 18997 007 24X Fiche 50-000,83/04/22,8305110477.
- 8305110479 IE Info Notice 83-42, "Reactor Mode Switch Malfunctions." Svc list encl JORDAN,E L. Division of Emergency Pregaredness & Engineering Response (Post 830103) 83/06/23. Consolidated Edison Co of New York, Inc 116pp 18996 242 24X Fiche 50-000,83/06/23,8305110479,
- 8305110483 IE Info Notice 83-43. "Improper Settings of Intermediate Range (IR) High Flux Trip Betpoints "Svc list encl JORDAN, EL Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/24. Consolidated Edison Co of New York, Inc 116pp 19046 297 24X Fiche.50-000.83/06/24.8305110483
- R Periodic operating reports & related correspondence
- 8304020109 Forwards monthly operating rept for Mar 1983 & revised monthly operating rept Feb 1983
 BMITH-W.O Indiana & Michigan Electric Co 83/04/12 Oppice of Resource Management. Director 1p. 18491, 255. 24X
 Fiche 50-315
- ---8306020111 Monthly operating rept for Mar 1983 MIGHT.A Indiana & Michigan Electric Co 83/04/12. 6pp 18691-256 24X Ficha.50-315,83/04/12.8306020109
- --8306020118 Revised monthly operating rept for Feb 1783 MICHT.A. Indiana & Michigan Electric Co 83/03/02. Ip 18691.261. 24X Fiche: 50-315, 83/04/12, 8306020109.

- 8304140343 Forwards monthly operating rept for Apr 1983 & revised monthly operating rept for Man 1983 correcting error in cumulative value for Item 17.gross electrical energy generated (MAH).

 8MITH.H © Indiana & Michigan Electric Co 83/05/11 Office of Resource Management. Director 1p 18859 232 24X Fiche.50-315.83/05/11.8304160343
- --8306160367 Monthly operating rept for Apr 1983 TETZLAFF, A L. Indiana & Michigan Electric Co. 83/05/04 7pp 18859 234. 24X Fiche 50-315,83/05/11,8306160343.
- S. Reportable occurrences, LERs & related correspondence
- B306060183 Forwards LERs 83-039/03L-0 & 83-040/03L-0 SMITH.N 0 Indiana & Michigan Electric Co 83/05/27 KEPPLER, J 0 Region 3, Office of Director. 1p 18728 192 24X Fiche 30-315.83/05/27.8306080183
- --8306060186 LER 83-040/03L-0; on 830804, primary & secondary temp instrument trains for meteorological instrumentation found out of spec Caused by inability to calibr temp processor for secondary instrument train Train recalibr. PALMER, R. A. Indiana & Michigan Electric Co. 83/05/27 Region 3, Office of Director ip. 18728.194 24X Fiche: 50-315,83/05/27,8306060183
- 830A21012B Forwards LERs 83-041/03L-0 & 83-042/03L-0. SMITH, M. 9. Indiana & Michigan Electric Co. 83/06/06 KEPPLER, J. 0 Region 3. Office of Director 19. 18915, 153 24X Fiche 30-315.83/06/06.830621012B
- ~~830&210134 LER 83~041/03L~0° on 830509, during surveillance test on automatic lead sequence timing relays, two relay timers found to exceed Tech Spec tolerance Caused by instrument drift Relay timers will be replaced PALMER, R.A. Indiana & Michigan Electric Co. 83/06/06 Region 3, Office of Director 1p. 18715 151. 24x Fiche: 50-315,83/06/06,8306210128.
- --B306210142 LER B3-042/OSL-0 on B30512. during surveil lance test on pressurizer pressure protection set III. high pressure reactor trip bistable would not trip. Caused by defective high pressure reactor trip bistable Bistable replaced. PALMER.R.A. Indiana & Michigan Electric Co. 83/06/06. Region 3. Office of Director ip 18915 152 24X Fiche 50-315,83/06/06.8306210128
- 8306210038 LER 83-047/01T-0: on 830525, during audit, discovered testing of steam generator stop valve not performed during 830327 startup. Caused by ambiguoup due dates on status upgrade sheets Lists reviewed & dates clarified, M/830508 ltr 8TEPHENS, T.R. 8MTTH-W.O. Indians & Michigan Electric Co. 83/06/08 KEPPLER, J.C. Region 3, Office of Director. 3pp. 18912-301. 24X Fiche: 50-315,83/06/08,8306210038
- 8306210259 Forward: LER: 83-043/03L-0, 83-044/03L-0, 83-045/03L-0 & 83-046/03L-0 | Sandano & Michigan Electric Co 83/06/08 | KEPPLER, J Q. Ragion 3, Office of Director. Ip 18915 041. 24x Fich: 50-315:83/06/08:8306210259.
- --8306210267 LER 83-043/03L-0: on B30513; control room emergency pressurization charcoal filter fire/trouble alarm received. Caused by high resistance settings for presilerm & Alarm Alarm settings adjusted to proper values. FALMER.R.A. Indiana & Michigan Electric Co. 83/06/08 Region 3, Office of Director. ip. 18915:042, 24X Fiche 50-315,83/06/08,8306210257.
- ---8306210273 LER B3-044/03t-0 on 830515 containment sump flow monitoring recorder 1-C8-001 chart paper did not advance Caused by ripped holes in paper Chart paper realigned on drive wheel. FALMER,R.A. Indiana & Michigan Electric Co. B3/06/08 Region 3. Gffice of Director. 1p. 18915:040. 24% Fiche:50-315,B3/06/08,B306210257.

- --8306210277 LER 83-045/03L-0 on 830519, fire Door 519 would not latch Cause not stated Strike plate replaced & door closer mechanism adjusted ROBINSON.D Indiana & Michigan Electric Co 83/06/08 Region 3. Office of Director 1p 18715 044 24X fiche 50-315, 83/06/08, 8306210257
- ~-8306210284 LER 83-046/03L-0 on 830511, cast centrifugal charging pusp 600-volt breaker miniflow valve found open Cause not determined Shiftly valve insps initiated Corrective actions not planned.

 MCRPHY, C E Indiana & Michigan Electric Co 83/06/08 Region 3, Office of Director 2pp 18915 045 24X Fiche 50-315, 83/06/08,8306210289
- 8306270433 Forwards LER_b 83-048/03L-0,83-049/03L-0 & 83-050/03L-0 SMITH-# 0 Indiana & Michigan Electric Co 83/06/16 KEPFLER, J C Region 3, Offfice of Director ip 18992 052 24X Fiche,50-315,83/06/16,8306270433
- --8306270435 LER 83-048/03L-0 on 830518, security guard discovered dissel room CD cardox sys isolated w/no names on entry board & no personnel in room Caused by technician error Need for full compliance w/fire protection rules emphasized PALMER, R A Indiana & Michigan Electric Co 83/06/14 Region 3. Office of Director ip 18992 053 24X Fiche 50-315,83/06/16,8306270433
- --B306270444 LER B3-049/03L-0 on B30520, review of surveillance log revealed containment air lock 3-day door tests not performed in required time Caused by lack of understanding Test responsibility assigned to one individual PALMER,R A , SMITH,W G Indiana & Michigan Electric Co B3/06/16 Region 3, 0ffice of Director Rpp 18992 054 24X Fiche 50-315, 83/06/16, 8305270433
- --8306270449 LER 83-050/03L-0 on 830523, five 4-kV bus degraded voltage relays 27-T11A-1 & 2 & 27-T11D-1, 2 & 3, found to have exceeded tolerance Caused by instrument drift Diosel generator load shedding relays readjusted PALMER, R A Indiana & Michigan Electric Co. 83/06/16 Region 3, Office of Director 1p 18992 056 24X Fiche: 50-315,83/06/16,8306270433
- B306300039 RO on B30612, performance of Train B boron injection tant inlet piping heat trace circuitry questioned, but train not declared inoperable until 830616 Investigation underway.

 BHITH W G Indiana & Michigan Electric Co B3/06/17 KEPPLER. J G Region 3. Office of Director ip 19121, 001 24X

 Fiche 50-315, 83/06/17, 8306300035
- DOCKET 50-316 DONALD C. COOK NUCLEAR POWER PLANT, UNIT 2 F Security, medical, emergency & fire protection plans
- B304100271 Forwards IE Safeguards Insp Repts 50-315/83-06 & S0-316/83-07 on B30411-19 & notice of violation Notice of violation & rept details withheld (ref lOCFR73 21).

 MILLER, J. R. Region 3, Office of Director B3/06/07 DDLAN, J. E. American Electric Fower Sarvice Corp. App. 18806-254 24% Fishes 50-319, 83/06/07, 3030410027.
- --8306100273 IE Safeguards Insp Repts 50-315/83-06 & 50-316/83-07 on 830411-15 Noncompliance noted agreement w/contractor contains no provisions per security plan & security plan for key control not being followed Safeguards info withheld CHRISTOFFER. Region 3, Office of Director, 83/06/06 2pp 18806 256 24% Fiche 50-315,83/06/07,8306100271
- 8306300213 Responds to 820730 ltm re emergency preparedness appraisal rept & 820630 notice of violation. Adequate performance demonstrated during 821021 exercise. Exam of misrepresentation of facts in progress.

 KEPPLER, J 9 Region 3, Office of Director.

 American Electric Power Service Corp | 19122 | 101 | 24% | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101 | 101
- 8904210057 Ack receipt of 830606 ltr informing NRC of steps taken to correct violations noted in 1E Insp Repts 50-315/83-04 & 50-316/83-05.

 8HAFER: W D Region 9: Office of Director. 83/06/14 DDLAN, J E American Electric Power Bervice Corp 1p 18912, 355 24% Fiche, 50-315, 83/06/14, 8304210057
- --8306210065 Responds to NRC 830506 ltr re violations noted in IE lnsp Repts 50-319/83-04 & 50-316/83-05. Corrective actions firs watch established using closed circuit TV i h & 20 minutes after identification of missed surveillance. ALEXIGH M P Indiana & Michigan Electric Co 83/06/06 KEPPLER, J. O. Region 3, Office of Director. 3pp. 18912 356 24% Fichs 50-315,83/06/14,8306210057

- 8306210343 Natification of 830623 meeting w/util in Bethesda, ND to discuss App R elemption requests & fire protection safe shutdown analysis WIGGINTON, D Operating Reactors Branch 1 93/06/16 VARGA, S A Operating Reactors Branch 1 2pp 15/21 299 24X Fiche 50-315,83/06/16,8306210343
- 8308230333 Forwards response to 830413 ltr re deficiency in approved physical security plan Response withheld ALEXICH, M.P. Indiana & Michigan Electric Co. 93/06/20 DENTON, H.R. Office of Nuclear Reactor Regulation, Director ip 18942 347 24X Fiche 50-315,83/06/20.8304230333
- P Operating license stage documents & correspondence
- 8306020009 Forwards revised Pages 6-23 & 3/4-7 9 for Tech Spec changes re record retention Pages reflect changes made in Amends 50.53,64 & 71 WIGGINTON.D Operating Reactors Branch 1 83/05/13 DOLAN, J Indiana & Michigan Power Co 2pp 18/02 347 24X Fithe 50-315.83/05/13.8306020009
- --8306020012 Revised Pages 6-23 & 3/4 7-6 & 7 for Tech Spec changes made in Amends 50.53.68 & 71 re records retention + Operating Reactors Branch 1 83/05/13 4pp 18702 349 24X Fiche 50-315.63/05/13.8306020009
- B306030290 Forwards add1 guidance on acceptable solutions to open items re control of heavy loads in compliance w/NURCO-0612 & draft "Control of Heavy Loads (C-10), Donald C Cook Nuclear Plant Units i & 2, " technical evaluation rept VARGA. S A Uperating Reactors Branch 1 B3/05/16 DOLAN, J Indiana & Michigan Electric Co 14pp 18/34 086 24% Fiche 50-315.83/05/16.8306030290
- --0306030299 Braft "Control of Heavy Loads (C-10), Donald C Cook Nuclear Fower Plant Units 1 & 2," technical evaluation rept VDSUURY, F W franklin Institute/Franklin Research Conter NRC-03-01-130 TER-C5506-344/345 DR 03/02/24 CLEMENSON, F NRC - No Detailed Affiliation Given 33pp 18734 100 24X Fiche 50-315,03/05/16,8304030290
- BIO6070208 Responds to BIO208 Generic Lt: BJ-10D on plans & schedule for resolving NUREO-0737. Item II K 3 5 re trip criteria for reactor collant pumps Util will follow gusdance provided by Westinghouse & Westinghouse Denores Group ALEXICH.M P Indiana & Michigan Electric Co BI/06/02 EISENNUT, D G Division of Licensing llpp 18747-054 24X Fiche 50-315.83/06/02.8306070208
- 830621016/ Responds to 830501 ltr re payment of processing fees for Billil application revised on 830225, for review of Tech Spec changes fee encl ALEXICH.M P Indiana & Michigan Electric Co 83/06/21 DENTUN, H R Office of Nuclear Reactor Regulation, Director 1p 18915 256 24% Ficho 50-315,83/06/21,830621016/
- B306270312 Forwards info re reactor vessel level instrumentation sysin response to Generic Ltr B2-28 concerning inadequate core coaling instrumentation in-core thermocouple sys will be upgraded to NMFG-0737, Item II F 2 requirements HERING.R F Indiana & Michigan Clottric Co 83/06/22 EISENHUT, D & Division of Licensing 19pp 18973 353 24X Fiche 50-315,83/06/22,8306270312
- O Inspection reports. IE Bulletins & correspondence
- 8305110458 IE Info Notice 83-32. "Ruptured Am-241 Sources Contained in Well Logging Device" Svc list encl TAYLOR, J.M. Division of Spřeguards & Inspection Programs (Post 630103) 83/05/26 Consolidated Edison Co. of New York, Inc 125pp 18831 043, 24% Fiche 50-000,03/05/26.8305110458
- 8305110460 IE Info Notice 83-34, "Event Notification Info Worksheet,"
 Syc list encl.
 JORDAN,E L Divinion of Emergency Preparedness & Engineering
 Response (Post 830103) 83/05/26 Consolidated Edison Co of New
 York, Inc 115pp 18732 085 24X Fiche 50-000, 83/05/26, 8305110460
- 8305110461 IE Info Notice 83-35. "Fuel Movement W/Control Rods Withdrawn at BWRs " Svc list encl JORDAN E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/31. Consolidated Edison Co of New York, Inc 116pp 19732 208 24X Fiche 50-000, 83/05/31, 8305110461

- 8306130298 Forwards IE lnsp Repts 50-315/83-07 & 50-316/83-08 on 830425-29 & 0509 & notice of violation 87REETER.JF Region 3, Office of Director 83/06/01 DOLAN,JE American Electric Power Service Corp DOLAN,JE Indiana & Michigan Electric Co 2pp 10823 306 24X Fiche 50-315,83/06/01.8306130258
- --8306130263 Notice of violation from insp on 830425-29 t 0509 STREETER, J F Region 3. Office of Director 83/06/01 2p 18823 308 24X Fiche 50-315,83/06/01,8306130258
- --8306130273 IE Insp Repts 50-315/83-07 & 50-316/83-08 on 830428-29 & 0507 Noncompliance noted incomplete record storage procedures & failure to provide 2-h fire resistant door on records storage vault CHDULES.N C , SUTHIN,R N , HAHKINS.F C Region 3, Office of Director 83/05/26 9pp 18923 310 24X Fiche, 50-315, 83/06/01, 8306130258
- 8306100271 Forwards IE Safeguards Insp Repts 50-315/83-06 & 50-316/83-07 on 830411-15 & natice of violation Notice of violation & rept details withheld (ref 10CFR73 21) MILLER, J. R. Region 3, Office of Director. 83/06/07 DDLAN, J. E. American Electric Power Service Corp. DDLAN, J. E. Indiana & Michigan Electric Co. 4pp. 18806-254 24X Fichs 50-315/83/06/07/8206100271,
- --8306100273 IE Safeguards Insp Repts 50-315/83-06 & 50-316/83-07 on 830411-15 Noncompliance noted agreement w/contractor contains no provisions per security plan & security plan for key control not being followed Safeguards info withheld CHRISTOFFER 0 . BELANGER J. L. CREED, J. R. Region 3. Office of Director 83/06/06 2pp 18806-256 24X Fiche 50-315.83/06/07, 8306100271
- 8305110464 IC Info Notice 83-36, "Impact of Security Practices on Safe Operations " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/09 Consolidated Edison Co of New York, Inc 119pp 18830 280 24X Fiche: 50-000,83/06/09,8305110464
- 8306170129 Submits response to IE Sulletin 83-03, "Check Valve Failures in Raw Mater Cooling Sys of Diesel Generator" List of job orders for check valves encl
 ALEXICH, M.P. Indiana & Michigan Electric Co. 83/06/09
 KEPPLER, J. G. Region 3, Office of Director. 5pp. 18878-302, 24X
 Fiche 80-315,83/06/09,8306170129
- 830.6300213 Responds to 820730 ltr re emergency preparedness appraisel rept & 820630 notice of violation Adequate performance demonstrated during 821021 exercise Exam of misrepresentation of Facts in progress KEPPLER, J G Region 3. Office of Director 83/06/09. DDLAN, J E American Electric Power Service Corp DDLAN, J E Indiana & Michigan Electric Co 3pp 19122 101 24% Fiche 50-315,83/06/09.8306300213
- 8305110470 IE Info Notice 83-38, "Defective Heat Bink Adhesive & Beiemically Induced Chatter in Relays Within Printed Circuit Cards " Syc list encl.

 JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co of New York, Inc. 118pp 18920 225 24X Fiche 50-000, 83/06/13,8305110470
- 8306090010 IE Info Notice 83-37. "Transformer Failure Resulting From Degraded Internal Connection Cables" Buc list encl JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 8 30103) 83/06/13 Cansolidated Edison Co. of New York, Inc. 243pp 18921 001. 24X Fiche: 50-000,83/06/13,8306090010
- 8306210057 Ack receipt of 830606 ltr informing NRC of steps taken to correct violations noted in IC Inap Repts 50-315/83-04 & 50-316/83-05 SHAFER, H D Region 3. Office of Director. 83/06/14 DOLAN, J. E. American Electric Power Service Corp DOLAN, J. E. Indiana & Michigan Electric Co 1p 18912 355, 24X Fiche 50-315,83/06/14,8306210057.
- --8306210065 Responds to NRC 830506 ltr re violations noted in IE Insp. Repts 50-315/83-04 & 50-316/83-05 Corrective actions fire watch established using closed circuit TV 1 h & 20 minutes after identification of missed surveillance. ALEXICH, M P Indians & Michigan Electric Co. 83/06/06. KEPPLER, J G. Region 3, Office of Director 3pp. 18912, 356 24X Fichs 50-315,83/06/14,8306210057
- 8305110475 IE Info Notice 83-40, "Need to Environmentally Qualify Epoxy Grouts & Smalers " Svc list encl.

 JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/22 Consolidated Edison Co. of New York. Inc 115pp 19021.179 24X Fiche 50-000, 83/06/22,8305110475.

- 8305110477 IE Info Nutice 83-41, "Actuation of Fire Suppression Sys Causing Inoperability of Bafety-Related Equipment " Svc list
- encl JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/22 Consolidated Edison Co. of New York, Inc. 120pp 18997 007 24X Fiche 50-000, 83/06/22, 8305110477
- 8305110479 JE Info Notice 83-42, "Reactor Mode Switch Malfunctions "
- 3031104/V IE Into Notice 83-42, "Reactor Mode Subtem Mateunctions " Byc list encl.
 JORDAN E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/06/23 Consolidated Edison Co of New
 York, Inc. 116pp 18996-242 24X Fichs 50-000 83/06/23 8305110479
- 8305110483 IE Info Notice 83-43, "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints "Svc list enci JORDAN E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/24 Consolidated Edison Co of New York, Inc. 116pp 19046-297 24X Fiche 50-000.83/06/24,8305110483
- R Periodic operating reports & related correspondence
- 8306020186 Monthly operating rept for Mar 1983 W/830412 ltr MIGHT.A., LEASE.R.B., 5VENSSON.B A Indiana & Michigan Electric Co 83/04/12 8pp. 18690 245 24X Fiche 50-316,83/04/12.8306020186
- 8306160384 Monthly operating rept for Apr 1983 W/830511 ltr TETZLAFF, A L., SMITH, W Q Indiana & Michigan Electric Co & Office of Resource Management, Director 7pp 18859. 280 Fichs 50-316,83705/04.8304160384 83/05/04
- S Reportable occurrences, LERs & related correspondence
- 8306060183 Forwards LERs 83-039/03L-0 & 83-040/03L-0 SHITH,W 0 Indians & Michigan Electric Co 83/05/27 Region 3. Office of Director Ip 18728 192 24X Fiche 50-315,83/05/27,8306060183 KEPPLER, J @
- --8306060186 LER 93-040/03L-0 on 830504, primary & secondary temp instrument trains for meteorological instrumentation found out of spec Caused by inability to calibr temp processor for secondary instrument train Train recalibr PALMER, R A Indiana & Michigan Electric Co 83/05/27, Region 3, Office of Director 1p 18728 194 24X Fiche 50-315, 83/05/27, 83/060187 8304040183
- 8306060269 Forwards LERs 83-046/03L-0 & 83-047/03L-0. SHITH, N. G. Indiana & Michigan Electric Co. 8: Region 3, Dffice of Director ip 18730 020 Fiche 50-314,83/05/27,8305060269 93/05/27 KEPPLER J Q
- ~-B306060271 LER 83-047/03L-0 on 830503, during surveillance test on solid state protection sys train B, logic test position tested unsatisfactorily, affecting power range high flux rate trip Gaused by failed logic card A-212 Card replaced PALMER.R A Indiana & Michigan Electric Co. B3/05/27 Region 3. Office of Director ip 18730 021 24X Fiche 50-316,83/05/27, B306060269
- --8306060273 LER 83-046/03L-0 on 830428.N-train battery room pyroalarm Accordance of Bi-quarticles on Biother, Netrain Dattery Foom pyromiand detector R-33A millioners of S3 auxiliary bldg detectors inoperable Caused by rain leaking through roof shorting out detector Pyromians tensinal block replaced. CARTEAUX, P. Indiana & Michigan Electric Co. 83/05/27. Region 3, Office of Director ip. 18730.022 24X Fiche 50-316.83/05/27.8306060269
- 830.6210074 RO on 830.603, during operational surveillance tast, both containment spray sys made inoperable for approx 15 minutes. Error discovered in independent verification of valve lineup immediate action taken to restore spray sys. TOWM.EY.E.L. Indiana & Michigan Electric Co. 83/06/03 KEPPLER.J.G. Region 3. Office of Director ip 18911 362 2-Fiche.50-316.83/06/03.8306210074 18911 362 24X
- B306210325 RO. on B30609, maint personnel discovered gauge had been ramoved from outside wall of outer airlock door providing vant path from containment to auxiliary bldg when inner airlock door open, Pressure gauge reinstalled, TOHMLEY, E. L. Indiana & Michigen Electric Co. B3/06/03 KEPPLER, J. G. Region 3, Office of Director ip 18914:035 24X Fiche 50-316,83/06/03,8306210325
- 8306270158 LER B3-049/01T-0 on 630602, pressure gauge discovered missing from outside wall of outer air lock door in upper containment Cause under investigation Pressure gauge replaced W/830626 ltr.
 PALMER.R.A. SMITH, W.O. Indiana & Michigan Electric Co. 83/06/16, KEPPLER.J.Q. Region 3. Office of Director. 3pp. 18992-049 PAK Fiche: 50-316, 83/06/16, 8306270158

- 8306270161 LER 83-048/017-0 on 830603, operators inadvertently closed manual isolation valve on HX of nontested train, rendering trains inoperable Caused by personnel error Personnel counseled W/830616 Itr KRAUSE DF. SMITH W 0 Indiana & Michigan Electric Co 83 KEPPLER J 0 Region 3. Office of Directo: 3pp 18992 034 Fiche 50-316.83/06/16.8306270161 03/06/16
- DOCKET 50-317 CALVERT CLIFFS NUCLEAR POWER PLANT, UNIT 1 F Security, medical. emergency & fire protection plans
- 8306070229 Forwards roys to training & qualification plan Revs withheld (ref 10CFR73 21) BOWHAKERN J Baltimore Oas & Electric Co 83/02/23 HAYNES,R C Region 1. Office of Director ip 18/46 111 24X Fiche 50-317.83/02/23,8306070299
- 8306010477 Informs that NUREG-0737. Item III A 2 1, "Emergency Preparedness, Upgrade Emergency Plans to App E.10CFR50." completed Item closed CLARK.R A Operating Reactors Branch 3 83/05/11 LUNDVAL Baltimore Gas & Electric Co 3pp 18688 359 24X Fichs 50-317.83/05/11,8306010477
- 8306190082 Releases public version of revised emergency plan Implementing procedure FELTON, JR Division of Rules and Records 83/06/01 Docum Management Brench 1p 18871 169 24X Fiche 50-317, 83/06/01,
- --B3061500B6 Public version of Nev 10 to Emergency Plan Implementing Pracedure ERPIP 4 1 17, "Security Yourn" W/B30519 ltr R receipt Form RUSSELL.L B Baltimore Gas & Electric Co B3/05/11 12pp 18871 170 24X Fichs 50-317,83/06/01,83061500B2
- 8306270195 Rev 2 to Emergency Response Plan Implementing Procedure ERPIF 4 4 7 6. "Post-Accident Sampling Sys & Analysis " RUSSELL.J B Daltimora Gas & Electric Co 82/04/01 37pp 18991 207 24X Fiche 50-317.83/04/01.8306270195
- 9305270164 Rev 9 to Emergency Response Plan Implementing Procedure ERPIP 5 1. "Communications " RUSSELL.JB: MALL.OF Baltimore Gas & Electric Co 83/06/15 11pp 18908 023 24X Fiche 50-317.83/06/15.8305270164
- 8304280461 Discusses util 830315 response to violations noted in IE Insp Repts 50-317/82-28 & 50-318/82-24 & results of 830419 meeting re response to two security violations Addl info required Comments withheld (ref 10CFR73 21) MARTIN T. T. Division of Engineering & Technical Programs 83/06/22 BOUMMAKER, N. J. Baltimare Gas & Electric Co. 2pp. 19019 183 24X Fiche 50-317.83/86/22.8304280461
- --B306280465 Responds to NRC 630216 ltr re violations noted in IE Insp. Repts 50-317/82-28 & 50-318/82-24 Items I & 2 not valid violations Details withhold (ref [0CFR73 21) BOWMAKER, N J Baltimore Oas & Electric CO B3/03/15, MARTIN, I I Division of Engineering & Technical Programs Ip 19019 185 24X Fiche: 50-317, 83/06/22, 8306280461
- P Operating license stage documents & correspondence
- 8305050051 Add1 response to FOIA request for three categories of documents re PRA of reactor safety study methodology application program repts & interim reliability evaluation program repts Forwards App A documents Search continuing FELTON.J.M Division of Rules and Records 83/04/07 SHOLLY,8 C Union of Concerned Scientists. 3pp 18752 001 24X Fiche 80-000,83/04/07.8304040051
- --8306060061 Statement on background, issues, current status & future action re interim & nath reliability evaluation programs
 * NRC No Detailed Affiliation Given 82/12/31 2pp
 18752 059 24X Fiche 50-000.83/04/07.8306060051
- 8304010034 Requests publication in monthly FR of notice of consideration of issuance of amend to DL & proposed no significant hazards determination re onsite organization & snubber surveillance Encl available in Contral Files only CLARK, R A Operating Reactors Branch 3 83/05/25 Operating Reactors Branch 3. 2pp 18483 241 24X Fiche, 50-317, 83/05/25, 8306010034

- B306070047 Discusses reactor coolant pump seal ability to perform adequately after extended loss of component cooling water, per NUREG-0737, Item II X 3 25 "Effect of Loss of Alternating Current Power on Pump Seals " Item resolution requested OLSON,R C Baltimore Gas & Licctric Co B3/05/25 CLARK,R A Operating Reactors Branch 3 2pp 18740 003 24X Fiche 50-317,83/05/25.8304070047
- 9304070156 Forwards response to questions re MacBeth critical heat flux correlation used in Unit 1 Cycle 6 & Unit 2 Cycle 5 steam
 line break analysis, per 830415 request
 LUNDVALL, A E Baitimpre Gas & Clectric Co 83/05/25 CLARK, R A
 Operating Reacture Branch 3 5pp 19/36 217 24X
 Fiche 50-317,83/05/25,8304070154
- --8306070197 Forwards section of Idaho Nuclear Corp Rept Ny-123-69 re statistical verification of MacBath correlation KLTNG.C L. Combustion Engineering. Inc. /3/08/01 SALAH, S Atomic Energy Commission 15pp 187.16 222 24X Fiche 50-317, 83/05/25, 8306070156
- 8306070427 Notification of 830601 meeting w/util, EQ&O, ORNL & C-E in Bethesda. MD to review control sys on clant design for resolution of Unresolved Safety Issue A-47 "Safety Inplications of Control Sys " SZUKIEWICZ. A J Generic Issues Branch 83/05/26 KNIEL, K Generic Issues Branch 3pp 18780 348 24X Fichs 50-317, 83/05/26, 8306070427
- 8306060105 Application to amend Licenses DPR-53 & DPR-69, revising Tech Spec Page 3/4 6-19 re operability of containment isolation valves LUNDVALL, A E Baltimore Gas & Electric Co 83/05/27 CLARK, R A Operating Reacture Branch 3 Spp 10/19 354 R4X Fiche 50-317,83/05/27,8306060105
- --8306060109 Proposed Tech Spec 3/4 6-19 re operability of containment isolation valves * Baltimore Gas & Electric Co 83/05/27 2pp 18719 357 24X Fiche 50-317,83/05/27,8306060105
- 8306090424 Forwards safety evaluation & technical evaluation rept, "Control of Heavy Loads" Guidelines of NUREG-0612 satisfied CLARK.R A Operating Reactors Branch 3 83/05/27 LUNDYALL,A F Baltimore Gas & Electric Co 2pp. 18809 107 24X Fiche 50-317.83/05/27.8306090426
- --B306090492 Safety evaluation accepting util response to "Centrol of Heavy Loads Phase I " Item resolved * NRC - No Detailed Affiliation Given 83/05/27 2pp [8809 109 24X Fiche 50-317,83/05/27,8306090426
- --8306030310 "Control of Heavy Loads (C-10) Calvert Cliffs Nuclear Power Plants Units 1 & 2," technical evaluation rept BOMBERGER, C Franklin Institute/Franklin Research Center NRC-03-81-130 TER-C5506-342 83/05/31 CLEMENBON, F NRC No Detailed Affiliation Given 28pp 18809 111 24X Fiche 50-317,83/05/27,8306090426
- 8306290194 Forwards FR notice of consideration of issuance of amend to License DPR-53 & opportunity for prior hearing re 630307 application for revised limiting conditions for operation concerning containment tendons CLARK.R.A Operating Reactors Branch 3 83/06/07 LUNDVALL.A E Baltimore Gas & Electric Co 3pp 17046 290 24X Fiche 50-317,83/06/07,8306290194.
- --8306290202 Notice of consideration of issuance of amend to License DPR-35 & apportunity for prior hearing re-containment tendons CLARK, R. A. Operating Reactors Branch 3 83/06/07 4pp 19046 293 24X Fiche 50-317.83/06/07.8306290194
- @ Inspection reports, IE Bulletins & correspondence
- 8304010318 Forwards IE Insp Repts 50~317/63~11 & 50~318/83~ii on 830412~0510 & notice of violation STAROSTECKI,R Division of Project & Resident Programs. 03/05/16 LUNDVALL,A E Baltimore Gas & Electric Co 2pp 18682 249 24X Fiche.50~317.83/05/16.8304010318
- --8306010320 Notice of violation from insp on 830412-0510 * Region 1, Office of Director 83/05/16, 2pp, 18682,251 24X Fiche. 50-317,83/05/16,8306010318

- --8306010324 IE Insp Repts 50-317/83-11 & 50-318/83-11 on 830412-0510 Noncompliance noted failure to procedurally require HEPA filter surveillance following fire & failure to perform required affilient sampling ARCHITZEL, R E , TRIMBLE, D C , MCCABE, E C Region 1, Office of Director 83/03/16 15pp 18682 253 24X Fiche 50-317, 83/05/16, 8306010318
- 8304020402 Forwards IE Insp Repts 50-317/82-08 & 30-318/83-08 on 830404-08 & notice of violation MARTIN.T T Division of Engineering & Technical Programs 83/05/20 LUNDVALL.A E Baltimore Qas & Electric Co 3pp 18695 038 24X Fiche 50-317,83/05/20,8304020402
- --8306020404 Notice of violation from insp on 830404-08 * Region 1. Office of Director 83/05/20 2pp 18695 041, 24X Fiche 50-317,83/05/20,8306020402
- --8306020407 IE Insp Repts 50-317/83-08 & 50-318/83-08 on 830404-08 Noncompliance noted failure to follow procedures re effluent sample confirmatory measurements & re records & repts in plant chemistry & radiochemistry areas KOTTAN.J J. JANG.J C. PASCIAK.W J. Region 1, Office of Director 83/05/17 8pp 18695 043 24X Fiche 50-317,83/05/20.8306020402
- 8306060371 Advises that 830517 submittal on main steam line break analysis will be reviewed per IC Bulletin 80-94. "Analysis of PWR Moin Bteam Line Break W/Continued Feedwater Addition" Importance of review of bulletin stressed CLARK, R A Operating Reactors Branch 3 83/05/23 LUNDVALL, A E Baltimore Cas & Electric Co 2pp 18750 336 24% Fiche 50-317,83/05/23,8306040371
- B304070140 Forwards IE Insp Repts 50-317/B3-10 & 50-318/B3-10 on B30411-15 No noncompliance noted MARTIN.T T Division of Engineering & Technical Programs B3/05/24 LUNDVALL.A E Baltimore Gas & Electric Co 2pp 18737 233 24X Fichs 50-317.83/05/24.8304070140
- --8306070146 IE Insp Repts 50-317/83-10 & 50-318/83-10 on 830411-15 No noncompliance noted Major areas inspected: licenses actions on previous insp findings, audit program, organization & GC & surveillance program review MEYER, 0, PRELL, J. Region 1, Office of Director CAPHTON, D.L. Division of Engineering & Technical Programs 83/05/11 8pp 18737-235 24% Fiche 50-317.83/05/24.8306070140
- 8305110458 IE Info Notice 83-32. "Ruptured Am-241 Bources Contained in Hell Logging Device" "Svc list encl TAYLOR. J M Division of Bafeguards & Inspection Programs (Post B30103) 83/05/26 Consolidated Edison Co of New York, Inc. 125pp 18831 043 24X Fiche 50-000.83/05/26,8305110458
- B305110460 IE Info Notice 83-34, "Event Notification Info Worksheet."
 Svc list encl
 JORDAN, E.L Division of Emergency Preparedness & Engineering
 Response (Post B30103) 83/05/26 Consolidated Edison Co of New
 York, Inc. 115pp 18732 085 24X Fiche 50-000, 83/05/26, 8305110460,
- 8305110461 IE Info Notice 83-38, "Fuel Movement W/Control Rods Withdrawn at BWRs " Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/08/31 Consolidated Edison Co of New York, Inc 116pp 18732 208, 24X Fiche, 50-000, 83/08/31,8305110461
- 8306210121 Forwards responses to IE Bulletin 83-03, "Check Valve Failures in Raw Water Cooling Sys of Diesel Generators "Check valves only verified tested in reverse direction Only one valve failure identified in 16 yrs of operation LUNDVALL.A E Bajtimore Cas & Electric Co. 83/06/07 ALLAN, J. M. Region 1. Office of Director. App 18714: 174 24X Fiche 50-317,83/06/07.8306210121
- 8306i3000i Forwards main steam line break final containment response analysis to IR Bulletin 80-04 & results of statistical evaluation performed for strengthened matls used in containment
 LUNDVALL, A E Baltimore Gas & Electric Co 83/06/08, CLARK, R. A Operating Reactors Branch 3. 13pp. 18924 250, 24%
 Fiche 50-317,83/06/09,8306J30001.
- 8305110464 IE Info Notice 83-36, "Impact of Security Practices on Safe Operations " Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/09, Consolidated Edison Co. of New York, Inc. 117pp 18830 280 24X Fiche, 50-000, 83/06/09, 8305110464
- 8306230383 Forwards IE Insp Repts 50-317/83-12 & 80-318/83-12 on 830509-13 No noncompliance noted MARTIN, T Division of Engineering & Technical Programs 83/06/09. LUNDVALL, A E Daltimore Gas & Electric Co. 2pp 18944 136 24X Fiche 50-317,83/06/09,8306230383

- 8305110470 IE Info Notice 63-38, "Defective Heat Sink Adhesive & Seismically Induced Chatter in Relays Within Printed Circuit Cards "Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co of New York, Inc. 118pp 18920 225 24X Fithe 50-000.83/06/13.8305110470
- 8304090010 IE Info Notice 83-37, "Transformer Failure Resulting From Degraded Internal Connection Cables" Sec list encl JURDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 837/06/13 Consolidated Edison Co of New York, Inc 243pp 18921 001 24X Fiche 50-000,83/06/13,8304090010
- 8306160323 Ack receipt of 830420 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-317/83-03 & 50-318/83-03 MARTIN.T Y Division of Engineering & Technical Programs 83/06/14 LUNDVALL, A E Daltimore Gas & Electric Co 2pp 18860-056 24% Fichs 50-317.63/06/14.8306160323
- --8306160330 Responds to NRC 830322 itr re violations noted in IE Insp Repts 50-317/83-03 & 50-318/83-03 Corrective actions aperture card reader reproducing capability disabled foreign print log revised & new OA procedure proposed LUNDVALL.A E Baltimore Oas & Electric Co 83/04/20 MARTIN.T T Division of Engineering & Technical Programs 2pp 18860 058 24X Fiche 50-317,83/06/14,8306160323
- 8308110475 TE Info Notice 83-40, "Need to Environmentally Qualify
 Epuzy Grouts & Sealers " Svc list encl
 JORDAN,E L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/06/22 Consolidated Edison Co. of New
 York, Inc. 115pp 19021:179 24X Fiche 50-000,83/06/22,8305110475
- 8305110477 IE Info Natice 83-41, "Actuation of Fire Suppression Sys Causing Inaperability of Safety-Related Equipment " Svc list enci JDRDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/22 Consolidated Edison Co of New York Inc 120pp 18997 007. 24X Fishe 50-000.83/06/22.8305110477
- 8306280461 Discusses util 630315 response to violations noted in IE
 Insp Repts 50-917/82-28 & 50-918/82-24 & results of
 B30419 meeting re response to two security violations Addl
 info required Comments withheld (ref 10CFR73 21)
 MARTIN.T.T Division of Engineering & Technical Programs 83/06/21
 80UMAKER.N J Baltimore Gas & Electric Co 2pp 19019 183 24X
 Fiche 50-317,83/06/22.8306280461
- --8306280465 Responds to NRC 830216 ltr re violations noted in IE Insp Repts 50-317/82-28 & 50-318/82-24 Items i & 2 not valid violations Details withheld (ref 100FR73, 21) BOWMAKER, N. J. Baltimore Cas & Electric Co 83/03/15 MARTIN-T T Division of Engineering & Technical Programs. ip 17019 185 24X Fiche 50-317, 83/06/22, 8306280461
- B305110479 lE Info Notice 83-42, "Reactor Mode Buitch Malfunctions "
 Svc list encl
 JDRDAN,E L. Division of Emergency Preparedness & Engineering
 Response (Post B30103) 83/06/23 Consolidated Edison Co of New
 York, Inc. 116pp. 18996 242 24X Fiche 50-000,83/06/23,8305110479
- 8305110483 IE Info Notice 83-43, "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints " Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83706/24 Consolidated Edison Co. of New York: Inc. 116pp. 19046-297 24X Fishe 50-000, 03/04/24, 0305110483
- R Periodic operating reports & related correspondence
- 8306170018 Monthly operating repts for May 1983 W/830614 ltr LOTITO.E.M Baltimore Cas & Electric Co 83/06/14 Director's Office, Office of Inspection and Enforcement, 11pp. 1882, 259 24X Fiche: 50-317, 83/06/14, 8306170018
- 8 Reportable occurrences, LERs & related correspondence
- B3061600B1 Responds to FOIA request for eight categories of records recertain sys in C-E designed nuclear power plants. Forwards App A documents identified in Categories 5 & A Category B document not located. Remaining documents filed in NRR FELTON, JM. Division of Rules and Records B3/04/19 BELL.N Coalition for Safe Power. App 18893 204 R4X Fiche: 50-317,83/04/19,8306160081

- --8306160083 Submits daily highlight re diesel generator failures at facility on 820603 Incident caused by paralleling of diesel generators w/buses powered from offsite source licensee investigating incident

 JAFFE, D.H. Operating Reactors Branch 3 82/06/04 DENTON, H.R.,
 CARTER, J. EISENHUT, D.G. NRC No. Detailed Affiliation Given 18
 18894 229 24X Fiche 50-317,83/04/19,8306160081
- 8306010264 Updated LER 83-009/03X-2 on 830210, discovered snubber 2-15-10 not included in Tech Spec & surveillance missed on snubber 1-15-8 Caused by snubber being incorrectly tagged Snubber will be correctly tagged FARRELL, E V, RUBSELL, L B Kaltimore Gas & Electric Co 83/05/12 ALLAN, J M Region 1. Office of Director 3pp 18672 252 24X Fiche 50-317, 83/05/12, 8306010264
- B304010277 LER B3-017/03L-0 on B3041B,ESF actuation sys Cabinet ZD deenergized in order to replace failed isolation module Isolator for BL stream generator isolation signal logic module replaced & cabinet reenergized W/B30512 ltr LA01EWBK1.J S. BASSO.L F. RUSSILL. B. Baltimbre Gas & Electric Co. 83/05/12 ALLANJ.J M. Region 1, Office of Director 2pp 18672 E39 24X Fiche 50-317,83/05/12.8506010277
- 8306010300 LER 83-015/03L-0 on 830415, plant computer failed, rendering income detector monitoring sys inoperable Caused by out-of-step selection of multiple anning inputs to analog control board, resulting in blown power fuse M/830512 ltr
 LAOIEMSKI,J S , RAYMOR.J W , RUBBELL, L B Baltimore Gas & Clertric Co 83/05/12 ALLAN,J M Region I. Office of Director 2pp 18672 182 24X Fiche 50-317,83/05/12,8304010300
- 8306070077 LER 83-021/017-0 on 830429, to address concorns of JE
 Bulletin 80-04, steam line break event reanalysed assuming
 failed open main feed reg valve Operating procedures
 modified to require manual feed sys trip W/830512 ltr
 BOHMAN.M E. RUSSELL.L B. Baltimore Gas & Electric Co. 83/05/12
 ALLAN.J M. Region 1, Office of Director 2pp 18737 359 24X
 Fichs 50-317.83/05/12,8306070077
- 830&010307 LER BG-023/OGL-0 on 830419, containment pump (CS) glarm would not clear, rendering sump insperable per Tech Spec 3 4 6 1 Sump drained until alarm cleared Cause not determined W/830519 ltr
 JUNGE, M. A. RAYNOR, J. W. RUSSELL, L. B. Baltimore Gas & Electric Co. 83/05/19 ALLAN, J. M. Region 1. Office of Director 2pp 18672 321 24X Fiche 50-317, 83/05/19, 8306010307
- 8306020423 Updated LER 81-044/03X-1 on 810614, during routine shutdown.

 MSIV 12 would not shut within required time limit Caused by
 nonsteel ring binding stem Ring replaced Purchase spec
 revised W/630519 ltr

 DAVIG.8 N , WEIR.S M , RUSSELL.L Beltimore Gas & Electric Co
 83/08/19 ALLAN.J M Region I, Office of Director 3pp
 18673 201 24X Fiche 90-317.83/05/17.8306020423
- 8306020433 Updated LER 81-024/03X-1 on 810404, during routine shutdown.
 MSIV 12 closing time exceeded Tech Spec limit Caused by
 monsteel ring binding stem Ring replaced Purchase spec
 revised W/830519 ltr
 DAVIS.8 M, WEIR.P J. RUSSELL.L Baltimore Gas & Electric Co
 83/08/17 ALLAN.J M Region i, Office of Director Spp
 18693.225 24X Fichs 50-317.83/08/19.8306020433
- B306020467 LER B3-020/03L-0 on B30423 wold leak found in sealing sys for 11A reactor coolant pump located in heat affected zone of weld juining Caused by vibration-induced fatigue Pipe replaced & Flanges eliminated W/B30519 ltr MENDERLICH, R L . CARTHRIGHT. W B . RUSSELL, L B Baltimore Gas & Electric Co B3/05/19 ALLAN, J M Region J. Office of Director Zpp 18693 292 24X Fiche 50-317,83/05/19,8306020467
- 8304020434 RO on 830412 oyster samples collected from Camp Conoy sampling location & analyzed for gamma-emitting radionuclides per Tech Spec requirements Based on average sliver activity level in oyster samples, dose insignificant FUHRMAN.O.R Baltimore Oas & Electric Co 83/05/23 Rogion 1. Office of Director 2pp 18694 102 24x Fiche 50-317.83/05/23.83060204346
- 830620026B NPDES noncompliance notification on 830520, during receipt of load of bulk aqueous ammonia, storage tank overflowed & 50-100 gallons of ammonia solution entered Outfall 002 Caused by improper attention during chemical transfer RUBSELL,t. B. Baltimore Oas & Clectric Co. 83/05/24 ALLAN, J. M. Region 1, Office of Director 3pp. 18701 060 24X Fiche: 50-317, 83/05/24, 830620026B
- B306170031 LER B3-024/03L-0 on B30427, during startup insp, heat damaged snubber discovered on piping between pressurizer & power operated relief blocking valve Caused by damaged reservoir on snubber 1-64-1 Anubber replaced W/830525 ltr PIERINGER.P. JENNINGS.R T. RUSSELL.L. B. Baltimore Gas & Electric Co. B3/05/25. ALLAN.J M. Region 1. Office of Director 3pp 18882 233 24X Fiche 50-317.83/05/25,8306170031

- 830.6210108 Updated LER 83-002/03x-i on BJ0106.containment sump valve MOV-5462 would not operate Caused by excessively worn worm gear Gean replaced Frequency of preventive maint will be increased to every refueling outage W/830526 itr LAGIEMBKI, J S. UNKLE, T J. RUSSELL, L. B. Baitimore Gos & flectric Co. 83/05/26 ALLAN, J M. Keglenni. Office of Director Jpp 18914 111 24X Fiche 50-317.03/05/26.0306210108
- 8306170011 LER 83-027/04X-0 on BJ0412, syster samples collected from Camp Canny location showed Ag-110m higher than background activity Caused by natural tendency of systers to bisconcentrate environ silver W/830602 ltr BROBST, 8 E. RUSSILL.L. B. Baltimore Gos & Electric Co. GJ/06/02 ALLAN, J. M. Region 1. 0ffice of Director. 2pp. 18882 2/3 24X Fiche 50-317,83/06/02,8306170011
- 9306200089 Updated LER 80-046/03X-1 on 800816, containment RMS pump failed, resulting in loss of containment gaseous & particulate radiation monitors Caused by corrosion & subsequent vane wrar/failure due to humidity H/830602 ltr DAVIS, S.M., CARTHRIGHT, W.B., RUSBELL, I.B. Baltimore Gas & Electric Co. 83/06/02 ALLAN, J.M. Region 1, Uffice of Director 3pp 18703-340 24X Fiche 50-317,83/06/02,8306200089
- 830.6200208 Updated LER 82-056/03X-1 on 620707, during normal operation, containment particulate & gaseous RMS sample pump tripped & would not restart Caused by failure of shaft coupling Coupling replaced W/830602 it.
 LAGIEMSKI.J S. CARTWRIGHT, W B. RUSSELL, B. Baltimore Gas & Electric Co. 83/06/02 ALLAN, J M. Region I. Diffice of Director 3pp 18903 21? 24X Fiche 50-317.83/06/02.8306200208
- 8306280447 LER 83-028/01T-0 on B3052/ discovered that both ECCS pump room air coolers out of svc from B30524-25 Caused by failure to realize potential safety significance of coolers prior to isolation for maint W/830408 IL WENDERLICH, R L , RUSSELL, L B Baltimore Gas & Electric Co B3/06/08 ALLAN, J M Region 1, Office of Director 2pp 19019 177 24X Fiche 30-317,83/06/08,8306280447
- 8306210086 Updated LER 82-028/03X-1 on 820604, while performing surveillance testing, loss of redundant shutdown cooling loop & operable boration flow path experienced Caused by improper bus fives Proper fuses installed W/830609 ltr BASEO, L.F., RUSSELL, L.B. Baltimare Oas & Electric Co. 83/06/09 ALLAN, J.M. Region 1, Office of Director. 3pp. 18914 131 24X Fiche 50-317,83/06/09.8306210086
- B306210101 Updated IER 79-031/01X-1 on 790731, during Pallowup testing on EFB actuation sys Undervoltage lagic circuit A.15-volt de power supplies to undervoltage lagic A & B would not respond when signaled W/830607 ltr
 BABSOLE F. RUSSELLLE B Baltimore Car & Clectric Co 83/06/07 ALLAN, J M Region 1. Office of Director 3pp 18714 217 24X Ficho 50-317,83/06/07,8306210101
- V Operator Examinations
- 8306140/14 Extends invitation to attend 830627 meeting in King of Prussia.PA to discuss transfer of licrosing function from Sethesda.MD to Region I ofc STAROSTICKI,R Division of Project & Resident Programs 83/06/09 LUNDVALL.A E Baltimore Gas & Electric Co 2pp 18841 292 24X Fiche 50-317.83/06/09.8306140/14
- BOCKET 50-318 CALVERT CLIFFS NUCLEAR POWER PLANT, UNIT P
 F Security, medical, emergency & fire protection plans
- 8304070229 Forwards revs to training & qualification plan Revs withheld (ref 10CFR73 Pl)
 BOHMAKER, N J Baltimore Gas & Electric Co 83/02/23 HAYNES, R C Region 1, Office of Director 1p 18744 H11 24X
 Fiche 50-317,83/02/23,8304070229
- 8306010477 Informs that NURIG-0737. Item III A 2 1. "Lmergency Preparedness. Upgrade Emergency Plans to App E. 1007850." completed Item closed CLARK.R A Operating Reactors Branch 2 83/05/11 LUNDVALL.A E Baltimore 9as & Electric Co 3pp 18608 359 24X Fiche 50-317.83/05/11.830601047/
- 83061500B2 Releases public version of revised emergency plan implementing procedure FELTON, J M Division of Rules and Records 83/06/01 Document Management Branch ip 188/1:167 24X Fiche 50-317,83/06/01, 83061500B2

- ---8306150086 Public version of Rev 10 to Emergency Plan Implementing Procedure ERPIP 4 1 17. "Security Team " H/830519 ltr & receipt form RUSSELL.L, B Baltimore Gas & Electric Co 83/05/11 12pp 18871 170 24X Fiche 50-317,83/06/01,8306150082
- 8306270195 Rev 2 to Emergency Response Plan Implementing Procedure ERPIP 4 4 7 6. "Post-Accident Sampling Sys & Analysis " RUSSELJ 8 Baltimore Oas & Electric Co 83/06/01 37pp 18991 287 24X Fiche 50-317.83/06/01.8306270195
- 8306270164 Rev 9 to Emergency Response Plan Implementing Procedure ERPIP 5 1: "Communications" RUBSELL, J B. MALL, G F. Baltimore Oas & Electric Ca 83/06/15 11pp 18988 023 24X Fichs 50-317.83/06/15,8306270164
- 8306280461 Discusses util 830315 response to violations noted in IE
 Insp Repts 50-317/82-28 & 50-318/82-24 & results of
 830419 meeting re response to two security violations Addl
 info required Comments withheld (ref !OCFR73 2!)
 MARTIN T T Division of Engineering & Technical Programs
 83/06/22
 80MMAKERN J Baltimore Gas & Electric Co 2pp 19019 183 24X
 Fiche 50-317.83/06/22.8306280461
- --B306280465 Responds to NRC B30216 ltr re violations noted in IE Insp Repts 50-317/02-28 & 50-318/82-24 Items 1 & 2 not valid violations Details withhold (ref 10CFR73 21) BCWMAKER, N J Baltimore Gas & Electric Co B3/03/15 MARTIN, T T Division of Engineering & Technical Programs ip 19019 185 24% Fiche 50-317, 83/06/22, 8306280461
- ${\it P}$ -Operating license stage documents & correspondence
- 8306060051 Add1 response to FD1A request for three categories of documents of PRA of reactor safety study methodology application program repts & interim reliability evaluation program repts Forwards App A documents Gearch continuing FELTON, J M Division of Rules and Records 83/04/07 SHOLLY, 8 C Union of Concerned Scientists 3pp 18752 001 24% Fiche 50-000,83/04/07,8306060051
- 6306010036 Requests publication in monthly FR of notice of consideration of issuance of amend to DL & proposed no significant hazards determination re onsite organization & snubber surveillance Encl available in Central Files only CLARK.R A Operating Reactors Branch 3 83/05/25 Operating Reactors Branch 3 83/05/25 Operating Reactors Branch 3 2pp 18683 241 24x Fiche 50-317.83/05/25.8306010036
- 8306070047 Discusses reactor coolant pump sual ability to perform adequately after extended loss of component cooling water, per NUREO-0237. Item II K 3 25 "Effect of Loss of Alternating Current Power on Pump Seals" item resolution requested OLSON.R C Baltimore Gas & Electric Co 83/05/25 CLARK.R A Operating Reactors Branch 3 2pp 18740 003 24X Fiche 50-317.83/05/25.8306070047
- 8306070156 Forwards response to questions re MacReth critical heat flux correlation used in Unit 1 Cycle 6 & Unit 2 Cycle 5 steam line break analysis.per 830415 request LUNDVALL, A E Daltimore Qas & Electric Co 83/05/25 CLANK, R. A Operating Reactors Branch 3 5pp 10/36 217 24X Fiche 50-317,83/05/25,8306070156
- 8306070427 Notification of 830601 meeting w/util, EQ&O, ORNL & C-E in Bethesda. MD to review control sys on plant design for resolution of Unresolved Safety Issue A-47 "Safety Implications of Control Sys "
 8ZUKIEWICZ, A J Generic Issues Branch B3/05/26 KNIEL, K Generic Issues Branch 3pp 18780 348 24X Fiche 50-317, 83/05/26, 8306070427
- 8304040105 Application to amend Licenses DPR-53 & DPR-69, revising Tech Spec Page 3/4 6-19 re operability of containment isolation valves LUNDVALL,A E Bultimore Gas & Electric Co B3/05/27 CLARK,R A Operating Reactors Branch 3 Spp 18719 354 24X Fiche 30-317.83/05/27.8304040105
- --8306060109 Proposed Tech Spec 3/4 6-19 re operability of containment isolation valves * Baltimore Gas & Electric Co 83/05/27, 2pp 18719.357 24% Fiche 50-317.83/08/27.8306060105
- 8304090426 Forwards safety evaluation & technical evaluation rept, "Control of Heavy Loads," Guidelines of NUREO-0612 satisfied CLARK, R.A. Operating Reactors Branch D. 83/05/27, LUNDVALL, A.E. Baltimore Qus. & Electric Co. 2pp. 18809 107 24X Fiche 30-317, 83/05/27, 8384090426

- --8306090492 Safety evaluation accepting util response to "Control of Heavy Loads Phase I" Item resolved a NRC - No Detailed Affiliation Given 63/05/27 Ppp \$8807 109 24X Fiche 50-317.62/05/27.8306090426
- --8306030310 "Control of Heavy Loads (C-10) Calvert Cliffs Nuclear Power Plants Units 1 & 2," technical evaluation rept BOMBERGER.C Franklin Institute/Franklin Research Center NRC-03-81-130 TER-C5504-342 83/05/31 CLEMENSON.F NRC No Detailed Affiliation Given 20pp. 18809 III 24X Fiche 50-317.83/05/27.8304090426
- @ Inspection reports: IE Bulletins & correspondence
- 8306010318 Forwards IE Insp Repts 50-317/83-11 & 90-318/83-11 on 830412-0510 & notice of violation 8TAROSTECKI.R Division of Project & Resident Programs 83/05/16 LUNDVALL, A E Baltimore Gas & Electric Co 2pp 18692 247 24X Fichs 50-317,83/05/14,8306010318
- --830&010320 Natice of violation from insp on 830412-0510 * Region 1, Office of Birector. 83/05/16 2pp. 18&82 251 24X Fiche 90-317,83/05/16,830&010318
- --8306010324 IE Insp Repts 50-317/83-11 & 50-318/83-11 on 930412-0510 Noncompliance noted failure to procedurally require HEPA filter surveillance following fire & failure to perform required effluent sampling ARCHITZEL, R E . TRIMBLE, D C . MCCABE, E C. Region 1, Office of Director 83/05/16 iSpp 18682 499 24X Fiche 50-317,83/05/16,8306010318
- 8306020402 Forwards IE Insp Regts 50-317/83-08 & 50-318/83-08 on 830404-08 & notice of violation MARTIN, F T Division of Engineering & Technical Programs 83/05/20 LUNDVALL, A E Baltimore Cas & Electric Co 3pp 18475 038 24X Fiche 50-317.83/05/20.8306020402
- --8306020404 Notice of violation from insp on 830404-08 * Region 1. Office of Director 83/05/20 2pp 18695 041 24X Fishe 50-317,83/05/20,8306020402
- --8306020407 IE Insp Repts 50-317/83-08 & 50-318/83-08 on 830404-08
 Nancompliance noted failure to follow procedures re effluent
 sample confirmatory measurements & re records & repts in
 plant chemistry & radiochemistry areas
 KOTTAN, J. J. JANG, J. C., PASCIAK, W. J. Region 1, Office of Director
 83/05/17 8pp 18495 040 24X Fishe 50-317.83/05/20.8304020402
- 8304040371 Advises that 830517 submittal on main steam line break analysis will be reviewed per IE Bulletin 80-04, "Analysis of PHR Main Steam Line Break M/Continued Feedwater Addition " Importance of review of bulletin stressed CLARK, R A Operating Reactors Branch 3 83/05/23 LUNDVALL, A E Baltimore Oas & Electric Co 2pp 18750 336 24X Fichs, 50-317, 83/07/23, 8306060371
- 8306070140 Forwards IE Insp Repts 80-317/83-10 & 50-318/83-10 on 830411-15. No noncompliance noted MARTIN T. T. Division of Engineering & Technical Programs 83/05/24 LUNDVALL, A E galtimore Gas & Electric Co. 2pp 18739 233 24X Fichs 50-317,83/05/24-8306070140
- --8306070146 IE Insp Repts 50-317/83-10 & 50-318/83-10 on 830411-15 No noncompliance noted Major areas inspected. Hismses actions on previous insp findings audit program organization & GC & surveillance program review MEYER.0 PRELLU. Region i, Office of Director. CAPHYON, D L Division of Engineering & Technical Programs. B3/05/11 Spp 18739 235 24X Fiche 50-317,83/05/24.8306070140
- 8305110458 IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in Hell Logging Device" Syc list enci
 TAYLOR, J. H. Division of Bafeguards & Inspection Programs (Post 830183) 83/05/26 Consolidated Edison Co. of New York, Inc.
 125pp 18831:043 24X Ficher 50-000, 83/05/26, 8305110458,
- 8305110460 IE Info Notice 83-34, "Event Notification Info Worksheet" Svc list entl
 JORDAN,E L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/05/26 Consolidated Edison Co of New
 York, Inc 115pp. 18732.085 24x Fiche 50-000.83/05/26.8305(10460
- 8305110461 IE Info Notice 83-35, "Fuel Hovement W/Control Rods Withdrawn at BHRs," Svc list encl, JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/31 Consolidated Edison Co of New York, Inc. 116pp. 18732 208 24X Fiche: 50-000,83/05/31,8305110461

- 8306210121 Forwards responses to IE Bulletin 83-03, "Check Valve Failures in Raw Water Cooling Sys of Diesel Generators "Check valves only verified tested in reverse direction Only one valve failure identified in 16 yrs of operation LUNDVALL, A E Baltimore Gas & Electric Co B3/06/07 ALLAN, J M Region in Office of Director App 18914 174 24x Fache 50-317.83/06/07,8306210121
- 8306130001 Forwards main steam line break final containment response analysis re IE Bulletin 80-04 & results of statistical evaluation performed for strengthened mutls used in containment LUNDVALL. A E Beltimore Gas & Electric Co 83/06/08 CLARK.R A Operating Reactors Branch 3 13pp 18024 250 24% Fishe 50-317.83/06/08.8306130001
- 8305110464 IE Info Notice 83-36, "Impact of Security Practices on Safe Operations " Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/09 Consolidated Edison to of New York, Inc. (19pp. 18830-280 24X Fiche 50-000,83/06/09,8305110464
- 8306230383 Forwards IE Insp Rupts 50-317/63-12 & 50-318/83-12 un 830509-13 No nuncompliance noted MARTIN.7 T Division of Engineering & Technical Programs 63/06/09 LUNDVALL.A E Baltimore Gas & Electric Co 2pp 18944 176 24X Fiche 50-317,83/06/09,8306230383
- --8306230388 IE Inop Repts 50-317/83-12 & 50-318/83-12 on 830509-13 No noncompliance noted Major areas inspected follows on previously identified inspliems, radioactive met) transport & QA audits of radioactive met) transport CULLINS, D. J. SHANJAMY, M. M. Region 1, Office of Director B3/06/07 Spp 16944 138 EAX Fichs 50-317,83/06/09,8306230383
- 8305110470 IE Info Notice 83-38. "Defective Heat Sink Adhesive & Seismically Induced Chatter in Relays Within Printed Circuit Caids " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison to of New York, Inc 118pp 18920 225 24X Fiche 50-000,83/06/13,8305110470
- 8304090010 IE Info Notice 83-37. "Transformer Failure Resulting From Degraded Internal Connection Cables" Svc list encl JORDAN, EL Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/13 Consolidated Edison Co. of New York, Inc. 243pp 18921 001 24X Fiche 50-000,83/04/13,8306090010
- 8306160323 Ack receipt of 830420 ltr informing NRC of steps taken to correct violations noted in II Insp Repts 50-317/83-03 & 50-318/83-03 MARTIN, T.Y. Division of Engineering & Technical Programs 83/06/14 LUNDVALL, A.E. Baltimore Gas & Electric Co. 2pp. 18860-056—24X Fiche 50-317,83/06/14,8306160323
- --8306160330 Responds to NRC 830322 ltr re violations noted in IF Insp Repts 50-317/83-03 & 50-318/83-03 Corrective actions aperture card reader reproducing capability disabled, foreign print log revised & new GA procedure proposed LUNDVALLA E Baltimore Oas & Electric Co 83/04/20 MARTIN.7 7 Division of Engineering & Technical Programs 2pp 18060 058 24X Fiche 50-317,83/06/14.8306160323
- 8305110475 IC Info Notice 83-40. "Need to Environmentally Gualify
 Epoxy Grouts & Sealers " Svc list encl
 JORDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83706/22 Consolidated Edison Co. of New
 York, Inc. 115pp 19021 177 24X Fiche 50-000.83/06/22.8305110475
- 8305110477 lE Info Notice 83-41, "Actuation of Fire Suppression Sys Causing Inoperability of Safety-Related Equipment" Svc list encl JORDAN.E L Division of Emergency Preparadness & Engineering Response (Post 830103) 83/06/22 Consolidated Edison Co of New York, Inc 12069 18997 007 24X Fiche 50-000,83/06/22,830511047/
- B306280461 Discusses util B30319 response to violations noted in IE
 Insp Repts 80-317/82-20 & 50-318/82-24 & results of
 B30419 meeting re response to two security violations. Addl
 info required Comments withheld (ref IOCFR73 21)
 MARTIN. I T Division of Engineering & Technical Programs 83/06/22
 BDDWMAKER.N. J Baltamore Gas & Flectic Co 2pp 17019 183 24X
 Fiche 50-317.63/06/22.6306280461
- ---8306280465 Responds to NRC 830216 ltr re violations noted in IE Insp Repts 50-317/82-26 & 50-318/82-24 Itoms 1 & 2 not valid violations Details withheld (ref 10CFR73 21) BOMMAKER.N.J. Baltimore Gas & Electric Co 83/03/15 MARTIN.T 7 Division of Engineering & Technical Programs 1p 17019 185 24X Fichs 30-317,83/06/22,8306280461

- B305110479 IE Info Notice B3-42. "Reactor Mode Switch Malfunctions "
 Svc list encl
 JORDAN.EL Division of Emergency Preparedness & Engineering
 Response (Post B30103) 83/06/23 Consolidated Edison Co of New
 York, Inc. 116pp 18996 242 24X Ficho 50-000, B3/06/23, B305110479
- 8305110489 IE Info Notice 83-4%, "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints "Evol list encl JORDAN, E. & Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/24 Consolidated Edison Co. of New York, Inc. 116pp 19046 297 24X Fiche 50-000,83/06/24,8305110483

8 Periodic operating reports & related currespondence

- 9306170018 Monthly operating repts for May 1983 W/830614 ltr LOTITO.E M Baltimore Cas & Flectric Co 83/06/14 Director's Office, Office of Inspection and Enforcement lipp 18882 259 24X Fiche 50-317.83/06/14/8306170018
- S Reportable occurrences. LERs & related correspondence
- 830&010270 LER 83~020/03L~0 on 830415, exhaust damper to ECCS room exhaust fan 22 found disconnected from actuator & in shut position Caused by separation of damper lever arm from bushing due to wear Level arm staked in place 8/830512 ltr PIERINGER, P. A. L.YONS W. T. RUSSELL, B. Baltimore Cas & Electric Co. 83/05/12 ALLAN, J.M. Region 1. Office of Director 2/pp 18672 249 24% Fichs 50-318.83/05/12.830&010270
- 830AD10273 tER 83-024/03L-0 on 830418, charging pump 22 removed from svc upon discovery of leak on discharge relief valve line Caused by crack in sucket weld between coupling & inlet pipe of relief valve, due to vibration Weld repaired W/830512 ltr JUNGE, M A : HUSEBY, D E : RUSSFLL: L B Baltimore Gas & Electric Co 83/05/12 ALLAN, J M Region i. Office of Director 3pp 18672 243 24% Fiche 50-318,83/05/12,8304010273
- 8306010299 Updated LER 81-050/03X-1 on 811020 reactor protective sys Channel B thermal margin/low pressure trip unit bypassed for maint after receiving spurious asymmetric steam generator trips. Caused by failed signal isolator W/030312 ltr LAQIEMSKI. J S. HINKLE. L S. RUSSLLL, D Boltimore Oas & Llectric Co B3/05/12 AllANJ M Region I. Dfice of Director Ppp 18472 184 24X Fiche 50-318,83/05/12,8306010299
- 930&020374 Updated LER 82-050/03X-1.on BPJ017.MBIV 21 stroked shut in 12 % exceeding 3 & s Tech Spec limit Caused by valve packing junk ring binding stem Ring replaced w/proper ring made of mild steel & purchase spec revised W/830819 ltr HENDERLIGHTR L., WEIR.P J. RUBSELL.L B Baltimore One & Llectric Co 83/05/19 ALLANJ W Region 1, Office of Director 3pp 18695 110 24X Fiche 50-918.83/05/19.8306020374
- B306020430 Revised LER B1-007/03X-1 on B10118,MBIVs 21 & 22 failed to shut within required time limit Caused by galled stems of packing junk ring Rings replaced W/B30517 ltr RUSSELL,L B. DAVIS.8 M. WEIK.P J. Baltimore Cas & Electric Co 83/05/19 ALLAN.J M. Rugion 1. Defice of Director 3pp 18674 109 24X Fiche 50-318,83/05/19,0306020430
- 8306020438 Updated LER 81-040/03L-1 on 810973 during surveillance testing. MSIV 22 closing time exceeded Tech Bpec limit Caused by nonsteel ring binding stem Ring replaced Purchase spec revised W/B30519 ltr
 WENDERLICH, R. L. WEIR: P. J., RUSSELL, L. B. Baltimore Gas & Clectric Co. 83/05/19 AlLAN, J. M. Region 1. Office of Director. Spp. 18694.099 24X Fiche 50-318.83/05/19.8306020438
- B305020435 RD on B30412, system samples collected from Comp Consy sampling location & analysed for gamma-emitting radionuclides per Tech Spec requirements Rased on average silver activity level in system samples, doses insignificant FUHRMAN, 9 R Baltimore Gas & Electric Co B3/05/23 Rogion 1, Office of Director 2pp 18694 102 24X Fiche 50-317, 83/05/23, 8305020436.
- 830420026B NPDEB moncompliance notification on 830320, during receipt of load of bulk aqueous ammonia, storage tank overflowed & 50-100 gallons of ammonia solution entered Outfall 002 Caused by impreper attention during chemical transfer RUSBELL, L D Baltimore Oas & Electric Co 83/05/24 ALLAN, J M Region 1. Office of Director 3pp 18901 060 24X Fiche 50-317,83/05/24,830620026B
- 8306170072 LER 83-025/03L-0 on 830424, saltwater inlet valves to circulating water pump room air coolers SM5250 & SM5251 discovered open while automatic safety injection activation signal disabled Caused by inadequate procedure W/830525 ltr MENDERLICH, R L , PAVIS, 0 S , RUSSELL, L B Baltimore Cas & Electric Ca. 83/05/25 ALLANJ M Region J, Office of Director. 3pp. 18882 244. 24% Fiche 50-318,83/05/25,8306170072

- 8306210099 Updated LER 83-001/03X-I on B30104.vital inverter 21 tripped, resulting in loss of vital instrument bus 2Y01 & deenergizing pressure controller 2-PIC-103 Caused by use of improper bus fuses W/830526 Itr PAVIS.0 S , DASSOL F , RUSSELL.L B Baltimore Cas & Electric Co. 83/05/26 ALLAN, J M Region 1, Office of Director 3pp 18914 214 24X Fiche 50-318,63/05/26.83062:0099
- 8304210159 Updated LER 82-055/03X-1 on 821228.vital ac inverter 22 failed, cousing 120-volt ac vital bus 22 to deenergize Caused by improper vital instrument bus fuses Proper fuses installed W/830526 it vital bus 22 to deenergize Caused by improper vital instrument bus fuses Proper fuses installed W/830526 it vital bus 22 to deenergize Caused by improper vital instrument bus fuses Proper fuses & Electric Co 83/08/26 ALAN, J M Region 1, Office of Director Spp. 18915 248 24X Fiche 50-318, B3/05/26.B306210159
- 8306210246 Revised LER 82-032/03X-1 on 820706, during routine surveillance, diesel generator 21 would not start Caused by broken inlet air check valve diet Generator repaired Countreweighting protedures revised 4/200826 ltr LAGIEWSKI, J S , HUBEBY, D E , RUSSELL, L B Baltimore Gws & Electric Co 83/05/26 ALLAN J R Region 1, Office of Director App 18917 011 24X Fiche 50-318,83/05/26,8306210246
- 8306170420 LER 83-021/03L-0 on 830504.containment sump alarms declared imperable Caused by defective alarm card, Alarm card replaced, Annunciator alarm will be checked daily H/830602 ltr

 JUNGE, M. A., RAYNOR, J. W., RUSSELL, L. B. Baltimore Que & Electric Co., 83/06/02 ALLAN, J. M. Region 1, Office of Director. 2pp 18879 060 24X Fiche 50-318, 83/06/02,8306170420.
- 8306200118 Updated LER 80-047/03X-1 on 901014, during normal operation, containment RMS pump failed resulting in loss of containment gaseous & particulate radiation monitors Caused by corrosion Pump replaced W/830602 ltr
 LAGIEWSKI, J S., CARTWRIGHT, W B., RUBBELL, L B. Baltimpre Gas & Electric Co. 83/06/02 ALLAN, J M. Rogion 1, Office of Director.

 3pp 18903 326 24X Fichs 50-318,83/06/02,8306200118
- 8306210046 Updated LER 80-029/03X-1 on 800416, steam generator isolation signal block B permitted steam generator isolation signal B to be blocked & LOCI sequencer alarmed Caused by voltage disturbance in inverter output W/830607 ltr

 BASEDLE F. RVBSELLL B Baltimore Cas & Electric Co 83/06/09, ALLAN, J N Region I, Office of Director Spp. 18911:326 24X Fiche 30-318,83/06/09,8306210046
- 8304280172 LER 83-028/03L-0 on 830516, accumulator 12 on M8IV 21 found to have ruptured bladder No cause stated Accumulator repaired & M8IV declared operable M8IV 21, accumulator 5, will be replaced during next hot shutdown, W/830609 ltr PIERINDER, P A , MEIR, P J , RUSBELL, L B, Baltimore Gas & Electric Co 83/06/09 ALLAN, J M Region L, Office of Director 2pp 19014 276 24X Fiche 50-318, 83/06/09, 8306280172.
- 8306280462 LER 83-029/03L-0 on 830515, during startup, dose equivalent I-131 determined to be 1 38 uCi per g Caused by indine spiking due to leaking fuel pins & change in power level.

 Bampling frequency increased W/830609 ltr

 JUNGEM A : RUBBELL.L D Beltimpre Cas & Electric Co. 83/06/09.

 ALLAN.J.M Region 1: Office of Director Spp 19018 324 24X

 Fiche: 50-318, 83/06/09, 8306280462
- 6306280352 LER 63-026/03L-0 on B30515, MSIV 21 stroked shut in 3.62 s. exceeding Tech Spec limit Caused by loose arm on position switch 2-25-4043A Arm adjusted & tightened & full-stroke test will be performed during next shutdown W/630613 ltr PIERINGER.P A , HINKLE,L 9 , RUSSELL.L B Baltimore Osa & Electric Co. B3/06/13 ALLAN,J M Region I, Office of Director Ppp. 19001:208 24X Fichs 50-318,83/06/13,8306280352

V Operator Examinations

- 8306140714 Extends invitation to attend 830627 meeting in King of Pressla.PA to discuss transfer of litensing function from Bethesda.ND to Region I ofc STARDSTECKI.R Division of Project & Resident Programs. 83/06/09. UND
- DOCKET 50-320 THREE MILE ISLAND NUCLEAR STATION, UNIT 2

 F. Security, medical, emergency & fire protection plans
- B304040260 Forwards IE Insp Regt 50-320/83-05 on 830404-0501 & notice of violation BTAROBIECKI, R. Division of Engineering & Technical Programs. B3/05/23. KANGA, B K. General Public Utilities OPU Service Corp 2pp 18727

- --8306060262 Notice of violation from insp on 830404-0501 * Ragion I. Office of Director 83/05/23 lp 18727 015. 24X Fiche: 50-320,83/05/23,8306080260
- --8306050266 JE Insp Rept 50-380/83-05 on 930404-0501 Noncompliance noted failure to implement recovery mode procedure fully during processing of reactor bldg sump water through submerged demineralizer sys MEBE.J 9 . BELL.J M . DARR.K R Region 1. Office of Director 83/05/20 9pp 18727 014 24X Fiche 50-320,83/05/23,8306060260
- 8306240319 Ack receipt of 830504 ltr re emergency info brochures Util proposes to effect distribution primarily by direct mail to agricultural community within plume exposure pathway emergency planning ione RODAN, R. E. Deneral Public Utilities 6PU Service Corp. 83/05/31 NALLOMELL.P. Pennsylvania. Commonwealth of, ip 18980 153 24X Ficha 50-289,83/05/31,8306240319

G Adjudicatory correspondence

- 8304030007 FOIA request for rept or memo to Commissioners reviewing evidence in recently-terminated lawsuit between OPU & P&W in federal court. Southern District of NY HEI68, E R Union of Concerned Scientists 83/02/23 FELTON, J Division of Rules and Records ip 18733 043 24X Fichs. 50-320, 93/02/23, 8306030007
- 830A0802A: FOIA request for R Parks 56-page affidavit sent to US Dept of Labor ROMAND:F R Air and Water Pollution Potrol 83/03/31. Division of Rules and Records ip 18787.177 24X Fiche.50-320.83/03/31. 830A0802A1
- 830A030010 Responds to FOIA request for rept or memo to Commissioners reviewing evidence in recently-terminated lawsuit between 9PU & B4H in federal court, Southern District of NY Rept available in PDR FELTON, J M Division of Rules and Records 83/04/01 HEISS, E R Union of Concerned Scientists 1p. 18732 044 24X Fiche: 50-320,83/04/01.8306030010
- 8306080262 Responds to FDIA request for R Parks 56-page affidevit sent to US Dept of Labor Forwards T Devine 830323 itr transmitting RD Parks 830321 affidavit & RD Parks 830316 ltr to Bechtel.
 FELTON-J H Division of Rules and Records 83/04/12 RONAND, F R Air and Water Pollution Patrol. 19 16787 178 24X Fichs. 50-320,83/04/12,8306080262
- 8304030329 Requests available evidence & conclusions re falsification of TMI-R records per H Harbman Mar 1980 allegations Info should include NRC snaiyses & repts, mgt review records & specific citations supporting NRC statement.

 BLAKE,E L. Shaw, fittman, Potts & Troubridge 83/04/01
 PLAINE,H H Office of the Ceneral Counsel 3pp 18708 350 24X
 Fiche 50-289,83/04/01.8304030329
- B30.6280387 Requests, under FOJA: to examine all files, documents, repts, ltrs.memos & other info re probe conducted by I Martin in 1980 pertinent to leak rate data on water & hydrogen levels at facility in 1978 Review of future info also requested MELLTON.B.L. Hepford, Swarts, Hensker & Horgen B3/06/24 DENTON,H.R. Office of Nuclear Reactor Regulation, Director 2pp 19001-272, 24% Fiche: 50-320,83/06/24.8306280387.

| Qeneral correspondence

- 306020043 Responds to 830502 ltr re 830328 NY Times article concerning safety & effectiveness of cleanup, Addi info re review & regulation of cleanup program encl.

 DENTON, H R Office of Nuclear Reactor Regulation, Director, 83705/24 COLEMAN, L S. New Jersey, State of, 3pp 18699-338 24X Fiche: 50-320,83705/24A 8306020043.
- 8306020047 Requests review of questions raised in B30328 NY Times article is safety & effectiveness of cleanup program Article enc!
 COLEMAN.L 8 New Jersey, State of. B3/05/02, PALLADING,N. Commissioners, 4pp. 18700 009. 24X Fiche 50-320.83/05/24, 8306020043
- O6190460 Responds to 830510 ltr re-public input to programmatic EIS on cleanup. Processed accident-generated water disposal mathod will require Commission approval BNYDER, B. J. TMI Program Office. 83/06/07 HENDRICKS, M 4ffiliation Unknown. 2pp. 18869:178, 24X Fiche 50-320,83/06/07, 3306150460.

- --8306150461 Expresses shock & disenchantment w/lack of govt concern own public view of cleanup efforts
 HENDRICKS,M Affiliation Unknown 83/05/10 SNYDFR.B J TMI Program Office Ip 18869-200 24X Fiche 50-320,83/06/07.
 8306150460
- P Operating license stage documents & correspondence
- 830.6280202 FOIA request for copies of all permits allowing radioactive matts in sawage or sewage studge from plants or sanitary landfills since 820101 or any repts from TMI conceining levels of radiation or radionuclide contamination MUNT.B P Three Mile Island Alert 83/04/07 Uffice of Administration 1p 19043 214 24X Fiche 50-320.83/04/07.
- 6306280206 Partial response to FUIA request for copies of permits allowing radioactive matts in sewage or sewage studge from TMI plant transported to area sewage treatment plants or landfills Forwards App A documents Search continuing FELTON.J M Division of Rules and Records 63/05/06 HUNT. B Three Mile Island Alert 2pp 19043 P15 24X Fiche 50-320. 63/05/06. 6306280206
- --8306280211 Submits evaluation results of contaminated sewage in Gate / sawage holding tank Concentrations of radionuclides in sawage in accordance w/1007.820 303 Ca-137 & tritium concentrations O 023% mpr & 0 0057% mpc, respectively LAZARSKI.R F Region 1, Office of Birector 83/01/27 BARRETI.L H 7MI Program Office 4pp 19043 261 24% Fiche 50-320.83/05/06.8304280206
- ~-8306280216 forwards info re Gate 7 sewage holding tank, located outside west entrance to turbine bldg Info consists of effluent & waste disposel & liquid effluent to summation of all releases

 BYRNE, J Region I, Office of Director 83/02/04 BARKETI.L M
 TMI Program Office 33pp 19043 265 24X Fiche 50-320.83/05/06, 83/05280206
- --8306280220 Forwards GPU 830031 memo & related info ro contamination in Gate 7 sewage holding tanks Info results of King NY Times article & Gischel affidovit BARRETILL H TMI Program Office 83/04/06 WARD.8 Region 1. Office of Director 49pp 19043 297 24X Fiche 50-320.83/05/06,8306280200.
- B306030164 Bubmits status rept re Commission activities concerning allegations raised by QPU employees & Former employees on mids to plant sys & components w/o proper review, tests & approval PALLADINO.N J Commissioners B3/05/12 MINNICH, J Advisory Council for Decontamination or TMI Unit 2 1p 18733 332 24X Fichs 50-320.83/05/12,8306030164
- 8304230497 Notification of contract execution, Mod 1 to "Provision of Technical Assistance to Assess Psychological Stress Related to Decontamination & Disposal of Radwaste at TMI-2" Contractor Homan Design Group SMITH.P.A Administrative Contracts Branch FIN 8-7598 83/05/13 DENTON, H R Office of Nuclear Reactor Regulation, Director. CLEARY, D P NCC No Detailed Affiliation Given 1p 18782 035 24X Fiche 50-320.83/05/13.830623049/
- --8306230501 Mod 1, deabligating balance of funds, to "Provision of Technical Assistance to Assess Paychological Stress Related to Decontemination & Disposal of Radwaste at TMI Unit 2" BAUM. A S Human Design Group SMITH.P A Administrative Contracts Branch. FIN N-75.8 83/05/13 ip 18902 036 24X Fiche 50-520.83/05/13,8306/200497
- 8304030498 Forwards corrected page previously issued w/830504 Amend 21 to License DPR-73 SNYDER.8 J THI Program Office 83/05/19 KANGA,8 K General Public Ubilities GPU Service Corp Jp 18735 227 24X Fiche 50-320,83/05/19.8304030498
- --830A030500 Corrected pages to Tech Specs issued w/Amend 21 to license DPR-73 * TMI Program Office 83/05/19 9pp, 18735 228 24X Fiche 50-320,83/05/19,830A030498
- 8306020076 Responds to Committee on Interior & Insular Affairs 830504 request for documentation re cleanup activities & 790328 incident.

 KANGA, B K General Public Utilities ~ GPU Service Corp 83/05/27.

 BARRETT, L H TM1 Program Office, 29Jpp 18691 266 24X

 Fich = 50-320, 83/05/27, 8306020076

- 8306160682 Forwards list of questions & clarification of items requiring response re review of underhidd characterization SERs Majority of items discussed during 030525 meeting w/util
- 8306220198 Forwards Vol 5, Number 4 to NUREO-0090, "Rept to Congress on AGs," for Fourth Quarter CVB2 One AG reported at NRC licensees re independifity of containment spray sys Agreement states reported no AOs AHEARNELJF Commissioners 83/06/02 O'NEILL, I P House of Rep 2pp 18740 024 24X Fiche 50-000, 83/06/02, 8306220198
- --8306220264 Agrees w/830225 view that URW/util litigation should be carefully reviewed Responses to Guestions 2 through 5 raised in 830225 ltr encl
 AHEARNE, J.F. Commissioners 83/06/01 UDALL, N.K. House of Rep.
 Interior & Insular Affairs 5pp 10940 107 ,44X
 Fiche 50-000,83/06/02,8306220198
- --8306220268 Discusses importance of carefully analyzing B30222 record of hearing on util/B&W litigation to determine whether record contains info bearing on questions of competence & character requirements of OL holder Questions per IMI-2 accident encl UDALL:N K House of Rep. Interior & Insular Affairs B3/02/85 PALLABINO, N Commissioners 2pp 18940 112 24X Fiche 50-000.83/06/02.830620198
- 8306220161 Requests cooperation in responding to BNML info requests to assist in preparation of suppl to preliminary DIS Staff member should be designated as coordinator SNYDER, B J TML Program Office 03/06/08 KANOA, B K General Public Utilities GPU Service Corp 7pp 18937 328 24X Fiche 50-320,83/06/08,8306220161
- 8306170282 Advises that J Flaniqan will be coordinator for DNML work suppl to programmatic EIS, in response to 830600 lti KANGALB K General Public Utilities GPU Bervice Corp 83/06/13 SNYDER, B J TMI Program Office ip 18878 170 24X Fishs 50-320,83/06/13,8306170282
- 830.6220035 Forwards proposed Rev / to organization plan for facility. changing organization charts to indicate realignment of functions reporting to recovery operations section NRC approval & implementation date requested KANCA, B K General Public Utilities ~ GPU Service Corp 83/06/14 SANCAF, B J THI Program Office 3pp 18930 206 24X Fiche 50-320,83/06/14.8306220035
- 8306200357 Forwards fees incurred for review of underhead characterization study Documents consist of single safety issue.

 KANGA:B K General Public Utilities OPU Service Corp. 63/06/15 SMYDER:B J TMI Pregram Office ip 18901-031 24X Fiche.50-320.83/06/15.8306200357
- 830.6280074 Requests util provide, within 30 days of ltr receipt, justification for instances where lock Spec surveillance exemption invoked due to occupational exposure Enforcement action will be taken if issues not expeditiously addressed SNYDER.B J TMI Program Office B3/06/15 KANGA, B K General Public Utilities GPU Service Corp 3pp 19042 344 24X Fiche 50-320,83/06/15,8306280074
- 8306220054 Forwards Addendum I to polar trans load test SER for review addendum incorporates responses to NRC & other comments related test & operating procedures Changes discussed W/o micl. KANGA.B K General Public Utilities GPU Service Corp 83/06/17 BARRETT.L H THI Program Office 2pp 18930 023 24X Fiche 50-320,83/06/17,8306220054
- G Inspection reports, 1E Bulletins & correspondence
- 8306200438 F01A request for NRC Investigation Rept 1-83-003 re facilities KILCOYNE, J J Kilroyne, J J 83/03/28 FELION, J Division of Rules and Records 1p 18920 018 24X Fichs 50-289,83/03/28, 8306200438
- G304200434 Responds to FOIA request for NRC investigation Rept 1-63-003 re facilities Rept withheld (ref FOIA Lxemptions 5 & 7) FELTON.J H Division of Rules and Records 83/05/02 KILCOYNE,J J Kilcoyne, J J 1p 18920 017 24X Fiche 50-289,83/05/02, 6306200434
- B30602000B Confirms B30516 identification of housekeeping & industrial safety hazard artions in response to 330505 insp
 BARRETTIL H TM1 Program Office B3/05/16 KANGA, B K General Public Villites GPU Barvice Corp 3pp 18702 353 24X
 Fiche. 50-320, 03/05/16, 8306020000

- B306060260 Forwards IE Insp Rept 50-320/80-05 on 830404-0501 & notice of violation STAROSTECKI, R Division of Engineering & Technical Programs 83/05/23 KANGA, N K General Public Utilities GPU Service Corp 2pp 18727 013 24X Ficht 50-320.B3/05/23.B306060260
- --8306060262 Notice of violation from insp on 830404-0501 * Region 1. Office of Director 83/05/23 ip 18727 015 24X Fiche 50-320,83/05/23,8306060260
- --8306060266 IE Insp Rept 50-320/83-05 on 830404-0501 Noncompliance noted failure to implement recovery mode procedure fully during processing of reactor bldg sump water through submerged demineralizer sys WIEDE, J. S. DELL, J. M., DARR, K. R. Region 1, Office of Director 83/05/20 9pp 18727 016 24X Fiche 50-320,83/05/23,8306060260
- 8305110450 IC Info Notice 83-32. "Ruptured Am-241 Sources Contained in Well Logging Device " Svc list encl TAYLOR, J M Division of Gafeguards & Inspection Programs (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 125pp 18031 043 24% Fiche 50-000. 83/05/26 8305110459
- 8305;10460 IE Info Notice 83-34, "Event Notification Info Worksheet"
 Svc list encl
 JORDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/05/26 Consolidated Edison Co of New
 York, Int. i15pp 18732 085 24X Fiche 50-000,83/05/26,8305110460,
- B305110461 IE Info Nutice B3-35. "Funt Movement W/Control Rode Withdrawn at HWKs " Syc list enci JORDAN E L Division of Emergency Preparedness & Engineering Response (Post B30103) B3/05/31 Consolidated Edison Co of New York, Inc. 116pp 18732 208 P4X Fiche 90-000,83/05/31,8308110461
- 8304080331 Staff requirements memo re Commission 830524 brising on NRC revalidation of mgt competence identified in insps on 830518 & 19 CHILK: 8 J Office of the Secretary of the Commission 83/06/02. DIRCKS, W J Office of the Executive Director for Operations in 18789 355 24X Fiche 50-320, 83/06/02, 8308080331
- 830613013/ Responds to 830310 IC Bulletin 83-03, "Check Valve Failures in Raw Water Cooling Sys of Digas! Generators " Inservice test program includes theck valves in flow path of cooling water for diesel generators No change required. KANGA-B K General Public Utilities PU Bervice Corp. 83/06/07 ALLAN-J M Region 1. Office of Director 2pp 18024 282 24X Fiche 50-320, 83/06/07.8306130137
- 8305110464 IE Info Notice 83-36, "Impact of Becurity Practices on Bafe Operations " Svc list encl JORDAN, E L Divinion of Emergency Preparadness & Engineering Response (Post 830103) 83/06/09 Consolidated Edison Co of New York, Inc 119pp 18830 280 24X Fithe 80-000,83/06/09,8305110464
- 8306140600 Forwards Pickerd, Lowe & Carrick, Inc investigation rept on allegations recurs of polar crane Util response to rept ent Additions for theoming in response to rept recommendations
 ARNOLD, R.C. General Public Ut; lities GPU Service Corp 83/06/07, 9NYDER, B. J. THI Program Office 144pp 18834-021, R4X Fiche 50-320, 83/06/09, 8306140600
- 8305110475 IE Info Notice 83-40, "Need to Environmentally Qualify
 Epoxy Grouts & Sealert " Bvc list encl
 JORDAN E L Division of Larrgency Preparedness & Engineering
 Response (Post 830103) B3/06/22 Consolidated Edison Co of New
 York, Inc 115pp 19021 179 24X Fiche 50-000,83/06/22,8305110475,
- 8305110477 IE Info Notice 83-41, "Actuation of Fire Suppression Bys Causing Inoperability of Safety-Related Equipment," Svc list encl, JORDAN, E. L. Division of Emergency Properedness & Engineering Response (Past 830103) 83704782 Consulidated Edison Co. of New York, Inc. 120pp 18997 007 PAX Fiche; 50-000, 8370472, 8305110477.
- 8305110479 IE Info Notice 83-42, "Reactor Mode Switch Malfunctions." Byc list encl. JORDAN.C I Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/23 Consolidated Edison Co. of New York, Inc. 116pp 18996 842 84X Fichs 50-000,83/06/23,8305110479

8305110483 IE Info Notice 83-43. "Improper Settings of Intermediate Range (IR) High Flux Trip Betpoints " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/24 Consolidated Edison Co of New York, Inc. 116pp 17046 277 24X Fishe 50-000.63/06/24.6305110483

R Periodic operating reports & related correspondence

- 830&010407 Correction to annual operating rept 1981 containing info on total aircraft movements at Harrisburg Intl Airport HWKILL-H D General Public Utilities GPU Service Corp 83/05/11 Region 1. Office of Director 2pp 18679 312 24X Fiche 50-289,83/05/11.830&010407
- B306020654 TMI Program Ofc weekly status rept for wk of B30515-21.
 BARRETT-L H TMI Program Office 83/05/23 DENTON.W R Office of Nuclear Reactor Regulation, Director SNYDER.B J TMI Program Office lipp 18716-258 24% Fiche 50-320-83/05/23,8304020654.
- B306200044 Submits TMI Program Ofc weekly status rept for wk of B30522-28 BARRETI,L H TMI Program Office 83/05/27 DENTON.H R Office of Nuclear Reactor Regulation, Director SMYDER,B.J TMI Program Office 15pp 18908 271 24X Fiche 50-320.83/05/27.8306200044
- 8306070215 Forwards "TMI Aquatic Study, Apr 1983 "
 RESSLER, W C General Public Utilities CPU Service Corp B3/06/01
 HICKEY, C. NRC No Detailed Affiliation Given Ip 1874/ 021
 24X Fiche, 50-289, 83/06/01,8306070215
- --8306070219 "TMI Aquatic Study.Apr 1983 " NARDACCI.0 A Ichthyological Associates, Inc 83/04/30 19pp 18747 022 24% Ficha 50-289,83/06/01,8306070215
- 8306200031 Submits TMI Program Ofc weekly status rept for wk of B30829-0040 BENTON, H R Office of BARRETT, L H TMI Program Office 83/06/06 DENTON, H R Office of Nuclear Reactor Regulation, Director SMYDER, B J TMI Program Office 9pp 18919 295 24X Fiche 50-320, 83/06/06, 83/06200031
- 8305160643 Forwards TMI Program Oft weekly status rept for wk of 830605-11 BARRETT.L H TMI Program Office 83/06/13 DENTON.H R Office of Nuclear Reactor Regulation, Director SNYDER.B J. TMI Program Office lipp 18864-330 24X Fiche 50-320,83/06/13,8306160643
- 8306280658 Bubmits TMI Program Ofc weekly status rept for 830612-18 BARRETT,L H TMI Program Office 83/06/20 DENTON,M R Office of Nuclear Reactor Regulation, Director SNYDER,B J. TMI Program Office 10pp 24x Fiche 50-320,83/06/20,8306280658
- 8306300162 Forwards "TMI Aquatic Study, Monthly Rept for Hay 1983, "
 prepared by Ichthoyological Assoc, Inc
 RESBLER, W C General Public Utilities CPU Service Corp 83/06/27
 HICKEY, C MRC No Detailed Affiliation Given. 1p. 19119 280
 24X Fiche 50-289,83/06/27,8306300162
- --830A300164 "THI Aquatic Study, Monthly Rept for May 1983 "
 NARBACCI, 0 A Ichthyological Associates, Inc. 83/05/31 23pp.
 19119 281 24X Fiche 50-289, 83/06/27, 830A300162

S Reportable occurrences, LERs & related correspondence

- 8306010329 LER 83-013/03L-0 on 830418.control room operator opened wrong breaker.tripping auxiliary & fuel handling bldg ventilation sys & control bldg chlorine monitors Caused by operator error. Breaker closed W/830518 ltr.
 WELLS.R. XANGALS K Gameral Public Utilities QPU Service Corp. 83/05/18 ALLAN, J M Region 1. Office of Director. 3pp 18682-268, 24X Fiche 50-320.83/05/18.8306010329
- 8306170025 LER 83-014/03L-0: on 830506, air intake tunnel Halon Sys actuated causing actuation of deluge sys & tripped auxiliary & fuel handling bldgs supply & exhaust fans Caused by welding near air intake tunnel. Sys secured W/830606 ltr WELLS.R.; XANOA.B.K General Public Utilities CPU Service Corp. 83706/06 ALLAN, U.M. Region I. Office of Director 4pp 18882: 236 24X Fiche. 50-320,83/06/06:8306170025

V. Operator Examinations

830&140224 Extends invitation to attend 830&27 meeting in King of Prussia, PA to discuss transfer of reactor operator licensing function from Bethesda, MD to Region I off.
8TARMETERKIR Division of Project Resident Progress KANOA, E. K. 9engral Public Utilities - GPU Bervice Corp 18832-286. 24X Fiche 50-320,83/06/09,8306140224

- DOCKET 50-321 EDMIN I HATCH NUCLEAR PLANT, UNIT 1

 F Security, medical, emergency & fire protection plant
- 8308030233 Forwards revised response to (60/01 requests for exempting from 10CH850 4B & App R requirements, per 830330 request Nev reflects compliance w/10CH850 40 & App R requirements & responds to 830120 droft 51R concurs GUCWAL I Georgia Power (6 83/05/27 570LZ, J [(Ipenating Reactors Branch 4 164pp 16/05 023 24X Fiche 50~301.01/05/27 8308030233
- 830&140711 Approves issuance of SALP Repts 50-32178 1-06, 80, 864761 (**
 50-42481-05 & 50-425/83-06 for Jul 1981 Oct 1903
 LEWIS,R C Division of Project & Resident Program (14/06/0)
 KELLY,R J Googja Power to Jpp 10041 196 74X
 Fiche 50-000,83/06/01,8306140/11
- --8306140719 Advises of 83031/ meeting in Atlanta, GA to discuss FAFP Repts 50-321/83-06,50-366/83-06,50-424/83-06 & 50-425/83-10 (A for Jul 1981 (Rt 1982 LEMB&R C Division of Project & Resident Programs BIMOMA, KELLY, I Georgia Power Ca 2pp 18841 199 24X Fichs 50-000,83706/01.8306140711
- --8306140730 SAIP Repts 50-321763-06, 50-966763-06, 50-424781 OA A 50-425763-06 for Jul 1981 Oct 1982 No significant util weaknesses identified * Region 2. Office of Director 83703709 SBpp 18841 Cl 14 Fichs 50-000, 83704701, 8306140711
- --830&140/43 Ack receipt of SALP Repts b0-321/83-0&, to 366/04 07, 50-424/83-0& k 50-425/83 0& for Jul 1981 ~ Oct 1982 Evaluation arceptable BECKHAN.J T Georgia Power & 83/04/18 GYRLILLY, J.P. Regis 2, Office of Director Ip 18841 037 24X Fiche 90 000, 01/05/c3 8304140711
- 8306150133 Releases public vernion of rovised emergency plan implementing procedures FELTON.J M Division of Rules and Records 83/06/01 Research Management Branch 1p 18872/092 PAX Fiche 50-3P1.83/06/01. 8306150133
- --8306180137 Forwards public version of revised emergency plan implementing procedures, including Procedures HNP-2-4517 or battery fire, HNP-4890 re exercises & drills & HNP-4691 to actions for personnel in site area emergency NIX,H C Georgia Power Co 83/05/18 Office of Noclear Result. Regulation, Director in 18672-099 P4X Ficho 50-321,8 PARALL. 8306150133
- --8306150141 Public version of revised emergency plan implementing procedures, including Procedures HNP-2-4219 re battery fire. HNP-4690 re exercises & drills & HNP-4691 re actions for personnel in site area emergency SUMNER. L. Georgia Power Co. 83/05/06 26pp 186772 094 .48 Fiche 50-321,83/06/01,8306150133
- 8306140237 Releases public version of revised emergency plan implementing procedures FELTON, J M Division of Rule: and Records 83706706 Bottacht Management Branch ip 18844 258 24% Fiche 50 -321,81706786.
- --8306140246 Forwards public version of revised emergency plan implementing procedures, including Procedures HNP-0137 is portable ion chamber Model RD 2A; HNP 0143 re low vol air sampler Model H-809 vt & HNP-4200 re fire procedure NIX; H C Georgia Power Co. 03/05/24 Office of Nuclear Resilva Regulation, Director App. 18844 259 24X Fiche 50-321,03/06/64 8306140237
- --8306140284 Public version of revised emergency plant implementing procedures, including Procedures HNP-8137 re-portable ion chamber Model RD-2A, HNP-8143 re-low-vol air sampler Model H-807 VI & HNP-4200 re-peneral fire procedure, w Georgia Power Co-83/05/24 3/pp 18844 243 24x Fiche 50-321, 83/06/06, 8306140237
- 8306190037 Releases public version of revised emergency plan implementing procedures FELTON.J M Division of Rules and Records 83/06/07. Durweshi Management Branch ip 18871 182 24X Fiche 50-391.83/06/07.

- ~-8305150041 Forwards public version of revised emergency plan implementing procedures including Procedures HNP-8155 re

 Qamma-10 portal monitor operation, HNP-4623 re site emergency shift supervisor % HNP-4625 re rally point leader

 NIX.H C Georgia Pawer Co 83/04/25 Diffice of Nuclear Reactor Regulation, Director ip 18871 183 P4X Fiche 50-321,83/06/07,8305150037
- ~~8306150044 Public version of revised emergency plan implementing procedures; including Procedures HNP-8156 re gamma-10 portal monitor operation; HNP-4623 re site emergency-shift supervisor & HNP-4626 re rally point leader NIX.H C Georgia Power Co 63/04/15 105pp 10871 184 P4X Fiche 50-321,83/06/07.8306150037
- 8306220307 Releases public version of revised emergency plan implementing procedures FELTON, J M Division of Rule: and Records 83/05/07 Document Management Branch ip 18940 114 24X Fiche 50-321.83/06/07, 8306220307
- ~-8306220313 Forwards public version of revised emergency plan implementing procedures, including Pracedures HNP-8004 repersonnel desimeter program, HNP-8016 reshipment of radiactive math & HNP-462P recontrol room operators NIX.H C Goorgia Power Co D3/05/04 Office of Nuclear Reactor Regulation, Director ip 18940 Lib 24X Ficho 50-321,83/06/07,830-2020-2023
- --83052R0310 Public version of revised emergency plan implementing procedures, including Procedures HNP-0004 re personne) dosimeter program, HNP-8015 re shipment of radioactive matl & HNP-4692 re control room operators ROGERS, W H , NIX, H C Grorgia Power Co 83/04/26 Office of Nuclear Reactor Regulation, Director 181pp 18940 114 PAX Fithe 50-321, 63/05/07, 6306220307
- 8306170202 Forwards addl info to justify 020701 10CFR50 48 & App R schedula exemption requests discussed at 830330 meeting Plan being developed to complete maint & design changes M/two oversize drawings Aperture cards available in PDR GUCHALT Georgia Power Co 03706/14 STOLE, J F Operating Reactors Dranch 4 4pp 18002 277 24X Fiche 50-321,83/06/14, 13704173.00

l Financial information

- 8304070123 Forwards Annual Linguicial Repts, 1782 QUCWALL T. Georgia Power Co. 83706/02 DENTGN.H R. Office of Nuclear Reactor Regulation, Director 1p. 18739-038 24X Fiche 50-000, 03706/02, 8306070173
- --83060/0127 Annual Financial Rept,1982 VGGYLE,A W The Southern Co 83/03/10 51pp 18739 039. 24X Fiche 80-000,83/06/02,83060/01/3
- --8306070130 Annual Financial Rept. 1982 8CHERER, R W. MILLER, J H. Georgia Power Co. 83/03/07 36pp 18737 091 24% Fiche 50-000, 83/04/07, 8306070123
- P Operating license stage documents & correspondence
- 8304030127 Informs that responsibility transferred from Region II to NRR Div of Licensing for all licensing actions re evaluation of util resolution of pipe cracking issues Acceptable resolution required prior to restart 870LZ, J F Operating Reactors Branch 4 83/05/17 RECKHAM, J 7 Operata Power Co 2pp 18733 304 24X Fiche 50-391,83/05/17,8306030127
- 8304070224 Forwards Rev O to "LI Hotch Nuclear Plant Units 1 & ? Environ Qualification of Class IE Equipment," in response to IE Bulletin 79-018 & 10CrRt0 49 requirements GUCWA.L T Georgia Fower Co 83/05/20, STOLZ, J F Operating Reactors Branch 4 219pp. 18746 192 24X Fiche 50-321,83/05/20, 8308070224
- 8306070129 Requests withdrawal of 820430 proposed Tech Spec changes re safety-related snubber insp & surveillance requirements Inoperable snubber conditions defined in proposed changes do not reflect actual operability concerns QUCWALL 1 Georgia Power Co 83/05/31 STOLZ.Jf. Operating Reactors Branch 4 1p 18709.7854 RAX Fiche 50-381,83/05/31, 8306070129
- B304070351 Application for amend to Licenses DPR-57 & NPF-5, revising dose equivalent iodine Tech Specs to reflect current requirements Info resolving outstanding purge & vent valve operability issues encl
 BECKHAM.J.T Georgia Power Co B3/05/31 STOLZ, J.F. Operating Reactors Branch 4 34pp 18742 071 24X Fiche, 50-321,83/05/31,8304070351

- --8306070357 Proposed changes to dose equivalent iodine Tech Specs & preliminary proposed Tech Specs for drywell & suppression chamber purge sys

 9 Georgia Power Co 83/05/31 5pp 18742 103 24X
 Fiche 50-321,83/05/31,8306070351
- 8306220219 Presents alternatives to automatic depressurilation sysingic to eliminate need for manual actuation for core coverage per TMI Item II K 3 iB implementation schedule & proposed Tech Specs requested within 45 days of itr receipt STOLY, J F Operating Reactors Branch 4 83/06/03 BECKHAM, J T Georgia Power Co 2pp 18951 001 P4X Fiche 50-321.83/06/03, 870630030
- 83061400/5 Advises that SER & trchnical evaluation repts re environ qualification of safety-related electrical equipment do not contain proprietary into Repts may be placed in PDR QUCMALT Georgia Power Co 83706/08 BTOLZ.
- 8304i40247 Forwards evaluation results demonstrating as-built acceptability of wetweil/drywoil vacuum breakers on Mark I containments, in response to Generic Ltr 83-08 GUCHA.L T Georgia Power Co 83/06/09 8TOLZ, J F Operating Reactors Branch 4 14pp 18859 329 24x Fiche. 50-321,83/04/09,8306160267
- 8306220002 Application for amend to Licenses DPR-57 & NPF-5 changing Tech Specs 3/4 6-2,8 3/4 6-6 & adding 3/4 6-46 for Unit 2 & 3 7-10a.3 7-34.3 7-34a & adding 3 7-10b & 3 7-34b for Unit 1 re purg & vent valve operability BECKHAM.J T Georgia Power Co 83/06/15. STOLZ,J F Operating Reactors Branch 4 5pp 18928 003 24X Fiche 50-321.83/06/15, 830620002
- --8306220010 Proposed changes to Tech Specs 3/4 6-2, B 3/4 6-6 & added 3/4 6-46 for Unit 2 & 3 7-10a, 3 7-34, 3 7-34a & adding 3 7-10b & 3 7-34b for Unit 1 re purge & vent valve operability # Georgia Power Co 83/06/15 55pp 18928 00B 24X Fiche 50-321.63/06/15, B306220002
- 8306210335 Notification of B30623 meeting w/util in Atlanta. GA to discuss status of Region II review of inservice pump & valve test program & questions re program RIVENBARK, O Operating Reactors Branch 4 B3/06/20 BYOLZ, J Operating Reactors Branch 4 2pp 19935 313 24% Fiche 50-321, 83/06/20, 8306210335
- G Inspection reports, IE Bulletins & correspondence
- B306140116 Forwards summary of 1E mgt martings on B30318 & 22 w/util to discuss condition of electrical cable trays & associated equipment & lack of mgt controls

 O'REILLY, J P Region 2, Office of Director B3/04/0B KELLY, R, J Georgia Power Co 4pp 18839 092 24% Fiche 50-321, 83/04/0B, B306140116
- 8306070224 Forwards Rev O to "EI Hatch Nuclear Plant Units 1 & 2 Environ Qualification of Class IE Equipment," in response to IE Bulletin 79-018 & 10CFRSO 49 requirements OUCHALL T Georgia Power Co 83/05/20 BTOLZ, J F Operating Reactors Branch 4 219pp 18746 152 24X Fiche, 50-321, 83/05/20, 8306070224
- 8304140515 Forwards IE Insp Repts 50-321/83-14 & 80-344/83-14 on 830424-27 & 0503-05 No noncompliance noted DANCE H C Division of Project & Resident Programs 83/05/25 KELLYR J. Georgia Power Co 2pp 18843,238 24X Fiche 50-321,83/05/25,8304140515
- --8306140322 IE Insp Repts 60-321/83-14 & 50-366/83-14 on 830426-29 & 0503-05 No moncompliance noted Major areas inspected inservice inspiprevious enforcement matters & welding Meeting held to discuss IE Bulletin 83-02 insp results CROWLEY, B. R. Region 2, Office of Director BLAKE, J. Division of Engineering & Radiological Safety Programs 83/05/23 15pp 18849 240 24X Fiche 50-321,63/05/25,8306140515
- 8305110458 IE Info Notice 83-32, "Ruptured Am-241 Bources Contained in Well Logging Device " Svc list encl TAYLOR, J M Division of Safeguards & Inspection Programs (Post B30103) B3/05/26. Consolidated Edison Co of New York, Inc. 125pp 18931-043. 24X Fiche 50-000, 83/05/26, 8305110458
- 8305ii0440 IE Info Notice 83-34, "Event Notification Info Worksheet" Byc list encl. JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co. of New York, Inc. 115pp 18732:085 24X Fiche 50-000, 83/05/26, 8305110440

- 8305110461 IE Info Notice 83-35. "Fuel Movement W/Control Rods Withdrawn at BWRs " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/31 Consolidated Edison Co of New York, Inc 114pp 18732 208 24X Fiche 50-000, 83/05/31, 830511046f
- 8304020179 EN-83-039 notice of violation & proposed imposition of civil penalty in amount of \$40,000 will be issued in May 1983 Proposed action based on licensee failure to ensure restoration of electrical cable tray sys BARBER, G., AXELRAD, J. Director's Office, Office of Inspection and Enforcement 83/05/31 ip 18691-092 24X Fiche 50-321.83/05/31.
- 930A070129 Requests withdrawal of 820430 proposed Tech Spec changes re safety-related snubber insp & surveillance requirements Inoperable snubber conditions defined in proposed changes do not reflect actual operability concerns GUCHA.L T Georgia Power Co 83/05/31 910LZ.J F Operating Reactors Branch 4 ip 18739 254 24X Fiche 50-321,83/05/31, 830A070129
- 8306140711 Approves issuance of SALP Repts 50-321/83-06,50-366/83-06, 50-424/83-06 & 50-425/83-06 for Jul 1981 Oct 1982 LEMIS,R C Division of Project & Resident Programs 83/06/01 KELLYR J Georgia Power Co Jpp 18841 196 24X Fichs 50-000.83/06/01.8306140711
- --8306140719 Advises of 830317 meeting in Atlanta.QA to discuss BALP Repts 50-321/83-06,50-366/83-06,50-484/83-06 & 50-425/83-06 for Jul 1981 - Oct 1982 LEMIS.R C Division of Project & Resident Programs 83/03/09 KELLY.R J Georgia Power Co 2pp 18841 199 24X Fiche 50-000.83/06/01.83061407/1
- --8306140730 SALP Repts 50-321/83-06.50-366/83-06.50-424/83-06 to 50-425/83-06 for Jul 1981 Oct 1982 No significant util weaknesses identified a Region 2. Office of Director 83/03/09, 38pp 18841 R01 24X Fiche 50-000.83/06/01.8306140711
- --8306140743 Ack receipt of SALP Repts 50-321/83-06.50-366/83-06. 50-424/83-06 & 50-425/83-06 for Jul 1781 - Oct 1782 Evaluation acceptable BECKHAM.J T Georgia Power Co 83/04/18 D'REILLY.J P Region 2. Office of Director ip 18841 237 24X Fiche 50-000.83/06/01. 8306140711
- 8306240006 Discusses IE insp on 830227-0326 & forwards notice of violation & proposed imposition of civil penalty D'REILLY, J P. Region 2. Office of Director 83/06/02 KELLY, R J Georgia Power Co. Spp. 18987-341 24X Fiche 50-321.83/06/02.8306240006
- --8306240014 Notice of violation & proposed imposition of civil penalty in amount of 440,000 Noncompliance noted failure to restore cable tray sys to quality conditions & lack of GA planning for mods & maint re electrical cable tray installation O'REILLY, J.P. Region 2, Office of Director 83/06/02 App 18987-344 24X Fichs 50-321.63/06/02.6306240606
- 8306290455 Submits add) response to IE Bulletin 81-03 Fire protection sign uses water from deep well Bus not susceptible to clam infiltration Mytilus spinot present in Altamaha River in vicinity of plant
 BECKHAM.J T Paorgia Power Co 83/06/02 D'REILLY.J.P Region 2. Office of Director 2pp 19052 181 24X Fiche 50-021,83/06/02. 8306290455
- 8306140075 Advises that SER & technical evaluation repts re environ qualification of safety-related electrical equipment do not contain proprietary info Repts may be placed in PDR, OUCHAL T Georgia Power Co. 83706/08 BTDLZ.J F Operating Reactors Branch 4 1p 18839:114 24X Fiche 50-321.83/06/0B, 8306140075
- 8306270264 Responds to IE Bulletin 83-03 re check valve failures in raw water coaling sys of diesel generators No check valves installed in cooling water sys at facilities BECKHAM.J T. Georgia Power Cn 83/06/08 D'REILLY.J P Region 2 Office of Director 3pp 19056 075 24% Fiche 50-321,83/06/08. 8306270264
- 8305110464 JE Info Notice 83-36. "Impact of Becurity Practices on Safe Operations." Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/09 Consolidated Edison Co of New York, Inc. 119pp 18830-280 24X Fiche 50-000,83/06/09,8305110464

- 8305110470 IE Info Notice 83-36, "Defective Heat Sink Adhesive & Beismically Induced Chatter in Relays Within Printed Circuit Cards " Syc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83706/13 Consolidated Edison Co. of New York, Inc. 118pp. 18920-225 24X Fiche 50-000,83706/13,8305110470
- 8306090010 IE Info Notice 83-37, "Transformer Failure Resulting From Degraded Internal Connection Cables "Syc list enc]
 JORDAN, E. L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/06/13 (Onsolidated Edison Co. of New
 York, Inc. 243pp 1892) 001 24% Fiche 50-000,83/06/13,8306070010
- 8306390254 Ack recaipt of 830526 ltr informing NRC of steps taken to correct violations noted in It Insp Repts 90-321/83-07 t 50-366/83-07

 LEGIS.R C Division of Project & Resident Programs 83/05/16

 KELLY.R J Georgia Power Co ip 19056-058 24X

 Fiche 50-321,83/06/16-8306290059
- --8306290265 Responds to NRC 830421 ltr re violations noted in 16 lasp Repts 50-321/83-07 & 50-366/83-07 Corrective actions valve handwheels being painted orange, adjustable wrenches lemoved & procedures for key lock switches revised BECKHAM, J T Georgia Power Ca 83/05/26 O'REILLY, J P Region 2, Office of Director App 19056 059 24X Fiche 50-3P1, 83/06/16,8306290254
- --B306290278 Forwards IE Insp Repts 50-321/83-07 & 50-366/83-07 on 830122-0226 & notice of violation LEMIS.R C Division of Project & Resident Programs 83/04/21 KELLY.R J Georgia Power Co 2pp 19056 063 24X Fiche 50-321,83/06/16,8306270254
- --8306290284 Notice of violation from insp on 830122-0226 * Region 2, Office of Director 83/04/21 2pp 19056-065 14x Fiche 50-321,83/06/16,8306290254
- --8306290293 IE Insp Repts 50-321/83-07 & 50-366/83-07 an 830122 0628 Noncompliance noted failure to implement procedures properly re-primary containment atmospheric control sys & operation of safety-related sys CRLENJAKAR V , HOLMES-RAY, P. Region 2, Office of Director BROWNLEG. V L. Division of Paject & Resident Programs 62/04/12 6pp 19056 067 24% Fiche 50-321, 83/06/16, 8306290254
- 8305290298 Act receipt of 830583 itr informing NRC of steps taken to correct violations noted in II. Insp. Repts 50-321/83-08 & 50-366/87-08

 LEWIS.R.C. Division of Project & Resident Programs KELLY.R.J. Georgia Power Co. ip 19056-017 24X

 Fiche 50-321.83/06/16.8308290.79
- ~-8306290303 Responds to NRC 830421 ltr re violations noted in II Insp. Repts 80-321/83-08 & 50-366/83-08 Corrective actions. Procedure HNP-9 will be reviewed & revised to clarify requirements for revising procedures. GUCHA.L T. Georgia Power Co. 83/05/23 D'REILLY, J.P. Region 2. Office of Director. 2pp. 19056-018 24X Ficho 50-321.83/06/16.8306270298
- ~~8306290312 Forwards IE Insp Repts 50-921/83-08 & 50-966/83-08 on 830314-10 & 25 & notice of violation LEWIS.R C Division of Project & Resident Programs 83/04/21 KELLY.R J Georgia Power Co. 2pp 19056 020 24X Fiche 50-321,83/06/16,8306290298
- --8306290317 Notice of Violation from insp on 830314-18 & 25 * Region 2, Office of Director 83/04/21 ip 19056 022 24% Fiche 50-321,83/06/16,8306290298,
- --8306290332 IE Insp Repts 50-331/83-08 % 50-366/83 08 on 830314-18 % 75 Noncompliance moted failure to revise Procedure HNP-2-3801. Rev 17. per Procedure HNP-9 requirements GIRARD.E H , ROSS.W J. BLAKE, J J Region 2, Office of Director 83/04/20 13pp 19056 083 24X Fiche 50-321,83/06/16,8306290290
- 8305110475 IE Info Natice 83-40, "Need to Environmentally Gualify
 Epoxy Grouts & Spalers " Svc list enc!
 JORDAN, E L Division of Emergency Preparedness & Engineering
 Remponse (Post 830103) 83/06/22 Consolidated Edison Co of New
 York, Inc 115pp. 19021 179 24X Fiche 50-000, 03/06/22.8305110473
- G305110477 IE Info Notice 83-41, "Actuation of Fire Suppression Sys Causing Inoperability of Safety-Related Equipment "Syc list enc!

 JORDAN E L. Division of Emergency Proparedness & Enginesing Response (Post B30103) 83/06/22 Consolidated Edison Co of New York, Inc 120pp 18997.007 24X Fiche 50-000, G3/06/22, G308110477

- 8305110479 IE Info Notice 83-42: "Reactor Made Switch Malfunctions "
- Svc list encl

 JGRDAN, E. L. Division of Emergency Preparedness & Ingineering

 Response (Post 830103)
 83/06/27
 Consolidated Edison Co. of New York. Inc.

 116pp
 18996-242
 24X Fiche 50-000.83/06/23.8305110479
- 8304300085 Responds to 830402 nutice of violation & proposed impositions of rivil penalties for violations noted in IE Insp Repts 50-321/83-09, 50-321/83-10. 50-364/83-09 & 50-366/83-10 Corrective actions Procedure INP-6921 levised BECKHAM, J T Georgia Power Co 83/06/23 Director's Office, Office of Inspection and Enforcement 6pp 19048 254 24X Fische 50-321,03/06/23.8306300085
- 8305i10483 iE Info Natice 83-43. "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/24 Consolidated Edison Co of New York, Inc 116pp 19046 297 24X Fiche 50-000,63/06/24,8305110483
- R Periodic operating reports & related correspondence
- 8306170382 Monthly operating rept for May 1783 W/830610 ltr REDWANZ,F.J., NIX.H C Georgia Power Co 83/06/10 Director's Office, Office of Inspection and Enforcement 23pp 18880 255 2AX Fiche: 50-321,83/06/10.8306170382
- S Reportable occurrences, LERs & related correspondence
- B305310144 RD 50-321/83-05 on B30407, w/onit at 100% power, alarm silented on 243-8005 fire detection panel due to performance of mods Panel not restored to operable status within Tech Spec limits Continuous fire watch assigned NIX.H C Georgia Power Co 83/05/16 O'REILLY, J P Region 2, Office of Director Spp 18659 044 24X Fiche 50-321.83/05/16.
- 83060700B0 LER 83-050/03L-0 on 830429, plant svc water pump 1A tripped Caused by component failure due to pump motor winding insulation breakdown Motor repaired & required testing performed W/830523 ltr
 TIPPS, 8 B. NIX.H C Georgia Power Co 83/05/29 G'REILLY, J.P. Region 2. Office of Director 4pp 18/37 355 24X
 Ficha 50-321,03/05/23,8306070000
- 830.6070247 LER 83-049/03L-0 on B30505, sanitary water supply valve X42-F073D found open but not locked open Caused by personnel error Personnel counseled M/630523 lt; TIPPS B B. NIX,H C Georgia Power Co 83/05/23 0'REILLY, J P Region 2. Office of Director 4pp 10742 067 24X Fiche 50-321,03/05/23,8306070347
- G306200261 LER G3-052/03L-0 on G30506, alorms received indicating trouble w/diesel generator auxiliaries, Generator untied & tripped Caused by normal supply breaker control power toggle switch being in off position Position adjusted W/B30602 ltr TIPPS G B , NIX.H C Georgia Power Co B3/06/02 O'REILLY, J P Region 2, Office of Director 4pp 10701 107 24X Fiche 50-321, 83/06/02, 8306200261
- 8304200374 LER 83-053/03L-0 on 830508.10 & 16. fission product particulate radiation monitor (1D11-K631) & fission product iodine monitor (1D11-K632) found inoperable Caused by component failure 1D11-K631 parts replaced W/830606 ltr TTPPS.8 B, NIX.H C Georgia Power Co 83/06/06 O'REILLY, J P Regian P, 0Ffice of Director Spp. 18901 041 24X Fiche 50-321.83/06/06.8306200374
- 8306200202 LER 83-037/03L-0 on B30510.while performing hydrogen & oxygen analyzer instrument procedure (HNP-1-3882), hydrogen analyzer (IP33-N002A) indicated incorrectly Causad by Failed current transmitter Transmitter replaced W/B30609 litr TIPPS B B, NIX.H C Georgia Power Co B3/06/07 D'REILLY, J P Region 2. Office of Director App 18903 202 24X Fiche 50-321,83/06/09,8306200202
- 9306280361 LER 83-055/03L-0 on 830517,RHR HX bypass valve (it]1-F048B) would not cycle completely open or closed Caused by loose valve atom not retainer Retainer reinstalled & locked by staking W/030615 ltr
 TIPPS B B, NIXH C Georgia Power Co 83/06/15 O'REILLY, J. P
 Region 2, Dffice of Director App 19001 204 24X
 Fiche: 50-321,83/06/15,8306280361.
- 830&200203 PNO-II-83-048 on 830&15, facility automatically shut down due to turbine trip caused by loss of power to electro hydraulic control sys Facility to be down until 830&20 for replacement of safety relief valves ROGGE, J. DANCE, H.C. Region P. Office of Director 83/06/16 2pp 18903 206 24% Fiche 50-321,83/06/16,830&200203

V. Operator Examinations

- 8306140486 Forwards summary of 830503 meeting re NRC policies on senior operator licensing exam Tech Spec memorization requirements the state exam requirements specified in draft Examiner Std ED-402 List of attenders encl
 DANCE H C. Division of Project & Resident Programs 83/05/24
 BECKHAM, J T Georgia Power Co 4pp 18843 090 24X
 Fiche 50-000,83/05/24,8306140486
- --8306140493 Requests meeting to discuss NRC policies on senior operator licensing exam Tech Spec memorization requirements Summary of Tech Spec sections covering required memorization encl BECKHAM. J T Goorgia Power Co 83/03/11 MLSON. B Region 2, Office of Director 2pp 18843 094 24% Fiche 50-000,83/05/24,8306140496

DOCKET 50-322 SHOREHAM NUCLEAR POWER STATION

- A Application/construction stage documents & correspondence
- 830 &0 &0 347 Board Notification B3-67 forwards info re errors in computer analyses for Mark II containments Rept providing results of evaluations performed by StW re Shoreham Mark II containment also encl
 NOVAK, T M Assistant Director for Licensing 83/05/17 Atomic Safety and Licensing Board Panel 7pp 18753 079 24X
 Fiche 50-000, 83/05/19, 8304040349
- --B306060352 Final deficiency rept to GNDSH & rocking acceleration data transmittal discrepancy Initially reported on 821029 & B30318, respectively No changes to plant design required QA Category I load transmittals will be reviewed MILLIGAN, H Long Island Lighting Co B3/04/20 ALLAN, J M Region 1, Office of Director App 18753 085 24X Fiche 50-000, B3/05/19, B306060349
- --8305050399 "Regt on Effects of Discrepancies in QHOSH Computer Porgram Used by S&H & in Labeling of Rocking Acceleration Units on Design of Shoreham Nuclear Power Station Unit 1 " # Stone & Hebster Engineering Corp 83/04/30 87pp 18753-089, 24X Fichs 50-000, 83/05/19, 8305060349
- 8304020495 Notification of cancellation of 830524 meeting w/
 representatives of Suffolk County in Bethesda: MD to
 evaluate positions re CP extension
 CARUSO.R Licensing Branch 2 83/05/20 BCHMENCER.A Licensing
 Branch 2 4pp 18715 192 24X Fiche 50-322.83/05/20.8304020495
- 8306150250 Forwards Teledyne Engineering Bvc 820520 ltr transmitting independent design review documents Certificate of Bvc encl BORDENICK.8 M Hearing Branch 3 83/05/27 BRENNER.L., CARPENTER.J. , MORRIS.P A Atomic 86fety and Licensing Board Panel 10pp 18846 099 24X Fiche 50-322,83/05/27,8306150250
- 8306130236 Forwards summary of disposition of NRC generic 1trs for CY81 & CY82
 SMITH J L Long Island Lighting Co 83/06/07. DENTDN.H R Diffice of Nuclear Reactor Regulation. Director 7pp 18826 304 24x
 Fiche 50-322,03/06/07
- 8306130477 Notification of B30509 menting w/util in Bethesda, HD to discuss proof & review process for Tech Space CARUSO, R Licensing Branch 2 83/06/07 SCHWENCER, A. Licensing Branch 2 4pp 18830 167 24X Fiche 50-322:83/06/07.8306130477
- 8306210220 Forwards mat1 presented at Anderson, Greenwood & Co (AGCo) vacuum breaker test program owners group 830607 meeting w/ MRC re dynamic testing & analysis of AGCo vacuum breaker valve assemblies
 O'CONNOR, D M Bechtel Corp 83/06/17, HOWSTON, R W Division of Systems Integration (post 811005) 91pp 18919, 038, 24X
 Fiche, 50-000, 63/06/17, 8306210220
- 8306230004 Forwards Teledyne Engineering Bycs 830606 ltr w/attachments re independent design verification program Certificate of Byc encl BORDENICK. B M Hearing Branch 3 83/06/21 DREMNER.L., CARPENTER.J L., MORRIS, P.A. Atomic Safety and Licensing Board Panel 12pp 18747 080 24X Ficher 50-322.83706/21.8306230004

- E NRC Bafety Evaluation Report (SER), supple & correspondence
- 830407003B Informs that preservice insp program completed & available for onsite review Program should close out SER Open Item 19 BMITH, J i. Long Island Lighting Co 83/06/02 DENTON. H R Office of Nuclear Reactor Regulation, Director 2pp 18739-339. 24X Fiche 50-322,83/06/02.830607003B
- 8306070013 Responds to request for environ qualification status of reactor bldg flood level alarms, ser SER Open Item 61 reserved discharge vol (NUREQ-0803) Testing program completed Documentation available for onsite review in approx 2 wis SMITH, V L. Long Island Lighting Co. 83/06/03 PENTON.H R. Off of Nuclear Reactor Regulation, Director 3pp 18736-359 24X Fichs 50-322,83/06/03,8306070013
- B306i30326 Forwards technical justification of single frequency/single axis testing method.per SER. Buppl 3 Info should resolve concerns re applicability of testing method BMITH.J L Long Island Lighting Co B3/06/06 DENTON.H R Defice of Nuclear Reactor Regulation, Director 4pp 18822 240 24X Fiche:50-322,83/06/06.8306i30326
- --B306130328 Rev 2 to "Seismic Qualification Reevaluation, Class IE Equipment for Shoreham Nuclear Power Station, Unit 1 " RAMADAS, E 9 Beimce Applications, Inc * General Electric Co 029-04-80-PA RO2. B1/04/03 Spp 10822-244 24X Fiche 50-322, B3/06/06, B306130326
- --8306130331 "Seismic Gualification Reevaluation, Class IE Equipment, Differential Pressure Transmitter for Shoreham Nuclear Power Station, Unit 1." SHERBIN, N. C. HARDY, R. N., LURIA, N. General Electric Co. 83/02/08 8pp 18822 249 24X Fiche 50-322,83/06/06,8306130326
- --8306130332 Rev 23 to "Dynamic Qualification.Recirculation Discharge Gate Valve for Shoreham Nuclear Power Station.Unit 1." LE.H General Electric Co B31-F031 R23 82/11/22 5pp 1882 257 24% Fiche:50-322.83/06/06.8306130326
- 8306240230 Forwards CE "Shoreham Common Sensors Failures Evaluation Rept." to resolve SER Open Issue 47 Control sys failures, caused by common hydraulic headers will not result in consequences outside scope of FEAR analyses.

 SMITH-J L Long Island Lighting Co 83/06/20 DENTON, H R Dff: of Nuclear Reactur Regulation, Director. Jpp 18780,187. 24x
 Fiche 50-322,63/06/20,8306240230 Office
- --8306240232 "Bhoreham Common Sensors Failures Evaluation Rept " CIHI.J J General Electric Co 83/05/31 46pp 18980 190 Fiche, 50-322,83/06/20,8396240230 18980 190, 24X
- 8306280947 Forwards revised Table 3 9.28-3 of FBAR, per SER Item 10. denoting fuel lift under combined SSE & LOCA loadings as zero Value based on 842 moneticedence probability at 50% confidence level.consistent w/MEDE-21175-3-P SHITH.J L. Long Island Lighting Co 83/06/20 DENION.H R. Off of Nuclear Reactor Regulation, Director App. 19018 102 24% Fichs 50-322, 83/06/20, 8306280547 Office
- 8306240250 Discusses Suppl 3 to SER re Item 62, "Remote Shutdown Panel." Info should be sufficient to close item as confirmatory issue for fuel load SMITH. J L. Long Island Lighting Co 83/06/21 DENTON, H R O of Nuclear Reactor Regulation, Director, Spp 16980 165 24x Fiche: 50-322,83/06/21:8306240250 Office
- 8304280445 Forwards Central Physics Corp evaluation results of items in corporate scope of review. Info should be sufficient to class BER open items BHITH.J.L. Long Island Lighting Co. 83/06/23. DENTON.H R. Offic of Nuclear Reactor Regulation. Director. 6pp. 19020-178-24X Fichs. 50-322, 83/06/23, 8306280449
- F Security, medical, emergency & fire protection plans
- 8306150609 Releases public version of transmittal notices FELTON.J M Division of Rules and Records 83/06/07 Pocus Management Branch 1P 18867:265 24% Fiche 80-322,83/06/07, 6306130609
- --8306150615 Forwards public version of transmittal notices indicating that confirmation of receipt of controlled documents not received Verification of receipt requested KEATINO, L. A. Teledyne Engineering Services. B3/04/19. DENTON, H. R. Office of Nuclear Reactor Regulation. Director 7pp 18867 286 24% Fichs. 50-322, 83/06/07, 8306150609

- 8306160072 Releases public version of revised emergency preparedness plan & implementing procedures

 FELTON.J M Division of Rules and Records 83/06/09 Docum

 Management Branch 1p 18873 001 24% Fiche 50-322, 83/06/09,

 8306160072
- --8306160087 Forwards public version of Rev 4 to emergency prepaledness plan & revised emergency preparedness implementing procedures FPIP 1-1 re unusual event, EPIP 1-2 re alert & EPIP 1-5 re notifications SMITH.J L. Long Island Lighting Co. 83/05/31 DENTON, H & Office of Nuclear Reactor Regulation Director 1p 18873 002 24X Fache 50-322, 83/06/09, 8306160072
- --8304140089 Public version of Rev 4 to emergency preparedness plan * Long Island Lighting Co 83/05/31 200pp 18873 003 24% Fiche 50-322,83/04/09,8304140072
- --B304140091 Public version of revised emergency plan implementing procedures, uncluding Procedures EPIP 1-1 re unusual event.

 EPIP 1-2 re alert & EPIP 1-5 re notifications Revised index encl index enci * Long Island Lighting Co 83/05/16 1,000pp 18873 224 24X Fiche 50-322:83/06/09.8206160072
- 8306160076 Releases public version of offsite radiological emergency response plan & implementing procedures FELTON. IM Dévision of Rules and Records 83/06/09 Document Management Branch Ip 18865 001 24% Fiche 50-322,83/06/09.
- --8304160100 Forwards public version of offsite radiological emergency response plan. App A & addendum to App A & offsite radiological emergency response plan implementing procedures.

 BMITH-J L Long Island Lighting Co 83/06/03 DENFONNIR.

 Office of Nuclear Reactor Regulation. Director Jpp 18685

 24X Fiche 50-322,83/06/09.8306160096
- --8308160104 Public version of offsite radiological emergency response plan Oversize drawings onch Aperture cards available in PDR = Long Island Lighting Co 82/10/31 1,100pp 18865 005 24% Fichs 50-322,83/05/09,8306160096
- ~-830616010B Public varsion of local offsite radiological emergency response plan implementing procedures, including Procedure OPIP 3 5 1 re dounwind surveying Two oversize drawings encl Aperture cards available in PDR * Long Island Lighting Co 83/05/02 750pp 18889 041 24X Fiche 30-322.83/06/09,8306160076
- 830A270305 Forwards ANL rept, "Element-By-Element Review of LILCO Transition Module of Shoreham Nuclear Power Station Offsite Radiological Emergency Response Plan," in response to 830A01 request.

 KRIMM.R W Federal Emergency Monagement Agency 83/06/23

 JORDAN.E L Division of Emergency Preparedness & Engineering

 Response (Post 830103) Spp 18995 266 24X Fiche 50-322,83/06/23. FI304270305
- --8306270308 "Element-By-Element Review of LILCO Transition Module of Bhoreham Nuclear Power Station Offsite Radiological Emergency Response Plan " * Argonne National Laboratory 83/06/22 19pp 18995 268 24% Fiche 50-322,83/06/23,8306270305 18995 268 24X
- 8306280034 Releases public version of revised emergency plan implementing procedures FELTON,J N. Division of Rules and Records 83/06/23. Docum Management Branch lp 19043 001 24X Fiche 80-922,83/06/23, G306280034 Document
- --8306280042 Forwards public version of revised Emergency Plan Implementing Procedures EPIP 2-8 re post-accident gaseaus effiuent sample analysis & EPIP 1-0 re classification of dwergency action levels
 SMITH, J L. Long Island Lighting Co. 83/06/08 DENTON, H R. Office of Nuclear Reactor Regulation, Director 2pp 19043 24X Fiche 50-322,83/06/23,8306280034 19043 003
- ---8306280046 Public version of revised Emergency Plan Implementing Procedures EPIP 2-8 re post-accident gaseous efficient sample analysis & EPIP 1-0 re classification of emergency action levels * Long Island Lighting Co 83/04/06 205pp 19049-005 24X Fiche: 50-322, 83/04/23, 8304280034

8306290673 Submits daily highlight for 830623 re FEMA identified technical discrepancies in util transition offsite emergency plan Plan acceptability will not be determined until legal questions resolved & drills performed CARUSO.R Licensing Branch 2 83/06/27 DENTON.H R . CASE.F C . CARTER. J Office of Nuclear Reactor Regulation. Director ip 19047 200 24% Fiche 50-332,83/06/23,8306290673

Q Adjudicatory correspondence

- 8304150211 Forwards executed Addendum 1 to resolution of Sufficie County Contention 13(a) to GA/GC - operations replacing 630516 telecom version
 - Contention 13(4) to any Contention 13(4) to the copy version BORDENICK.B M Hearing Branch 3 83/05/20 BRENNER,L J, MORRIS.P A. CARPENTER,J L Atomic Bafety and Licensing Board Panel 2pp 18846 007 24% Fiche 50-322.83/05/20.83061502!1
- --8306150214 Addendum 1 to resolution of Suffalk County Contention 13(a) re GA/GC operations, changing dates in Paragraphs II A, I) B & II C & adding statement to Paragraph II C BORDENICK, B H Hearing Branch 3 EARLEY, A F Long Island Lighting Ca DYNNER, A R Suffalk County, NY 83/05/16 2pp 18846 009 24X Fiche 50-322,83/05/20,8306150211
- 8306150250 Forwards Teledyne Engineering Svc 820520 1tr transmitting independent design review documents Cartificate of Svc encl BORDENICK, B M Hearing Branch 3 83/05/27 BRENNER, L , CARPENTER, J L , MORRIS, P A Atomic Safety and Licensing Board Panel 10pp 18846 099 24% Fiche 50-322,83/05/27,8306150250
- 8306020181 Comments on util-county disagreements re unresolved GA/GC aperations, in response to 830517 k 23 ltrs Matters discussed in stated ltrs need not be litigated or mediated by ASLG BORDENICK, B M. Hearing Branch 3 83/05/31 DYNNER, A R. Kirkpatrick, Lockhart Hill, Christopher & Phillips 2pp 18670 230 24X Fiche 50-322.83/05/31.8306020181
- 8306020446 Forwards portion of ABLAH Decision ALAD-729 re sysinteractions & NRC const of term "important to safety"
 Reasonable progress demonstrated & adequate justification for operation of facility shown AAMBON 8 J. Hearing Branch 4 83/05/31 BRENNER, L., CARPENTER, J. L., MORRIS, P. A. Atomic Safety and Licensing Board Panel 2pp 18693 243, 24X Fiche 50-322,83/05/31,8306020446
- 8304040184 Response to util & NRC opposition to Suffalk County 830502 motion & 830510 addendum to motion for level to file new contentions re emergency diesel generators Proposed contention should be admitted BROWN, H H Suffalk County, NY BROWN, H H Kirkpatrick, Lockhart, Hill, Christopher & Phillips 83/05/31 Atomic Safety and Licensing Spord Panel 4Opp 18728 195 24X Fiche 50-322,83/05/31,8306060184
- --8306060188 Affidavit of MW Goldsmith advocating further investigation into facility diesel generator problems Prof qualifications & Certificate of Buc encl.
 GOLDSMITH.M W Buffolk County, NY GOLDSMITH.M W Energy Research Group, Inc. 83/05/31 36pp 18728 235 24X Fichs 50-322,83/05/31,8306060184
- 8306180404 Confirms 830820 telcon between A Dynner & R Caruso re cancellation of 830824 meeting on outil request for CP extension Meeting should be rescheduled within 10 days EISENMUT.D 0 Division of Licensing 83/06/01 BROWN.H H Kirkpatrick Lockhart. Hill, Christopher & Phillips 4pp 18868.353 24% Fiche 50-322.83/06/01.8306190404
- 8306060372 Reply to util 830516 & NRC 830523 filings as suppl to Sufferly County findings & opinion on Sufferly County Contention in Util Failed to address need to consider check valves in safety-related sys M/Certificate of Svc LANPHER, L C Suffolk County, NY LANPHER, L C. Kirkpatrick, Lockhart, Hill, Christopher & Phillips 83/06/02 9pp 18730 008 24X Fiche, 50-322, 83/06/02, 8306060272
- 8306270399 Demands limited appearance hearings be held LABCELLE: K E Affiliation Unknown 83/06/02 LAURENSON, J A Atomic Bafety and Licensing Board Pamel 2pp 18994 138. 24X Fiche 50-322.83/06/02.8306270399
- 8306060312 Informs that Teledyne Engineering Svcs will issue final independent design verification program rept on 830711 RORDENICK, B M. Hearing Branch 3 83/06/03 BRENNER, L., MORRIG, P. A., CARPENTER, J. L. Atomic Bafety and Licensing Board Panel 2pp 18729-383 24X Fich# 50-322,83/06/03,8306060312

- 830a070381 Forwards executed MW Goldsmith affidavit supporting Suffolk County response to util & NRC opposition to motion for leave to file new contention to emergency diesel generators Related correspondence MILLER, MS Kirkpatrick, Lockhart, Hill, Christopher & Phillips MILLER, MS Suffolk County, NY 83706703 BRENNER, L, BORDENICK, BM, REVELEY, NT Atomic Safety and Licensing Board Panel Ip 18741 321 24X Fiche 50-322,83706703,8306070381
- --8306070386 Executed affidavit of MW Coldsmith demonstrating issues raised in Suffolk County proposed contention on diesel generators timely raised & present significant issues re generators affect function Certificate of Svc encl GULDSMITH, M W Buffolk County, NY COLDSMITH, M W Energy Research Group, Inc. 83/06/02 22pp 18741 322 24X Fiche 50-328,83/06/03,8306070381
- 8304070405 Corrects util 830524 memorandum of svc for supplemental emergency planning info Certificate of Svc encl CHRISTMAN, J N Hunton & Williams 83/06/03 LAURENSON, J A , KLINE, J R., LIVINGSTON, N B Atomic Bafety and Licensing Board Panel. 3pp 18742 281 24X Fiche. 50-322, 63/06/03, 6306070405
- 8306080171 Forwards util response to Suffolk County submission rediesel generators Suffolk county unwarranted attack on util.
 util counsel & NRC w/o basis Leave to submit response to demonstrate no issues of fact exist requested.
 ELLIS, Y B Hunton & Williams ELLIS, T B Long Island Lighting Co.
 83/06/03 BRCNNER, L , CARPENTER, J. H , MORRIS, P A Atomic Safety and Licensing Spard Panel 2pp 18772 278 24X Fiche 50-322,83/06/03,8306080171
- --8306080177 Response to Suffolk County submission re diesel generators Submittel allegations & implications faire Reopening of record not merited Discontinuities in cylinder blocks will not affect safety

 ELLIB.T 8 Long Island Lighting Co ELLIB.T 8 Hunton & Hilliams 83/06/03 2pp 18772 280 24% Fiche 50-322,83/06/03,8306080171
- --8304080182 Affidavit of EJ Youngling, demonstrating existence of no cracks in cylinder block castings which will propagate or adversely affect angines Certificate of Byc encl.
 YOUNGLING,E J Long Island Lighting Co. 83/04/03. Bpp.
 18772 282 24X Fiche 50-322,83/04/03,8304080171
- 8306080181 Order scheduling 830610 party conference in Bethesda, MD to clarify legal & technical points re Suffolk County motion to admit new contention on emergency diesel generators BRENNER, L. Aromic Safety and Licensing Board Panel 83/06/06. 2pp 18772 190 24X Fiche 50-322, 83/06/06, 8306080151.
- 8304:3039B Requests limited appearance hearings be held on Long Island before formal litigation begins PETIT.MR, FOX.C. PRICE.W. Affiliation Unknown 83/06/06. LAUREMBON, J A Atomic Bafety and Licensing Board Panel 13pp 18823.260 24X Fiche 50-322:83/06/06.8304130398
- 8306080149 Response to util memorandum of svc of supplemental emergency planning info ASLB should reject proposed emergency plans until agreement reached w/entities to perform assigned duties Crrtificate of Svc pncl.
 BROWN.H H. SUffolk County, NY. BROWN.H H. Kirkpatrick, Lockhart, Hill, Christopher & Phillips 93/06/07. Atomic Sefety and Licensing Board Panel 14pp 18772 132 24X Fiche. 50-322,83/06/07,8306080169
- 8304090214 Motion requesting Commission to reject util plans which do not provide adequate accident response preparedness & to conclude OL proceeding Certificate of Svc encl BROWN, H. H. Buffolk County, NY. BROWN, H. Kinkpatrick, Lockhart, Hill, Christopher & Phillips 83/06/07 Commissioners, 10pp 18796-001 24X Fiche 50-322,83/06/07.8306090216
- 8304070258 Advises that util proposal, per 830512 order re submission of util plan in absence of state & local govt plans, is simply unimplementable compendium of speculative & hypothetical alternatives, facility shutdown recommended COHALAN, P. F. Suffolk County, NY 83706/07, PALLADING, N. J., GILINGRY, V. ABSELSTINE, J. K. Commissioners, 3pp. 18774-316, 24X Fichs 50-322, 83/06/07, 8306070258
- 830.6090295 Status rept on schedule for filing emergency planning contentions Four was sufficient to produce dreft contentions Contentions should address util/county plan & util interim plans Certificate of Svc encl.

 MCCLESKEY, K.E. Long Island Lighting Co MCCLESKEY, K.E. Hunton & Williams. 83/06/07 5pp 18798-287 24X Fiche-50-322,63/06/07, 8306090295

- 9306100240 Forwards response to Suffolk County submission of data redicael generators & JC Higgins unexecuted affidavit recracked swergency diesel generator engine block BCRDENICK, B M Hearing Brench 3 83/06/08. BRENNER, L, MORRIS, P A, CAPPENTER, J L. Atomic Safety and Licensing Board Panel 2pp 18807 126 24% Fiche 50-322,83/06/08,8306100240
- --B306100242 Response to Suffolk County B30526 submission of data re diesel generators Util promptly informed NRC of surface crack indications in diesel generator camehaft block area. Certificate of Syc encl. BCRDENICK.B M Hearing Branch 3 83/06/08 9pp 18807 128 24X Fiche 50-322,83/06/08,8306100240
- 8306130404 Motion for low-power QL Partial initial decision needed on full-power operation for issues on which record complete Certificate of Svc encl REVELEY.H T Long Island Lighting Co REVELEY.H T Hunton & Williams 83/06/08 Atomic Safety and Licensing Board Panel 15pp 18823 245 24X Fiche 50-322,83/06/08,8306130404.
- 8306:304:11 Forwards motion for low-power QL Request involves evaluation of onsite emergency preparedness, contested health & safety issues & offsite emergency preparedness H/o encl REVELEY, W T Long Island Lighting Co 83/06/08 BRENNER, L CARPENTER, J N , MORRIS, P A Atomic Safety and Licensing Board Panel 5pp 18823 235. 24X Fiche 50-322,83/06/08,8306/30411
- 8306130423 Rept on disagreements w/util re GA/GC operations Seven disagreements; all within scope of litigation, remain DYNMER.A R. Buffolk County, NY DYNMER.A R. Kirkpatrick, Lockhart, Hill. Christopher & Phillips 83/06/08 75pp 18823.147 24X Fiche 50-322.83/06/08.8306130423
- 8306130446 Notice of appearance in proceeding Certificate of Svc encl MONAGHAN, J A Long Island Lighting Co MUNAGHAN, J A. Hunton & Hilliams 83/06/08 3pp. 18821 203 24X Fiche 50-322,83/06/09, 8306130446
- 8306150378 Response opposing util 830526 filing of five emergency plans in compliance w/ASLB 830420 memorandum & order Plans do not meet ASLB order criteria Certificate of Svc encl SHAPIROR. North Shore Committee Against Nuclear & Thermal Pollution. 83/06/08 Atomic Safety and Licensing Board Panel 7pp 18847 258 24% Fiche 50-322.83/06/08.8306150378
- 8306160305 Supports limited appearance hearings prior to formal litigation to be held on Long Island LERMAN.D H Affiliation Unknown 83/06/08 LAURENBON.J A Atomic Bafety and Licensing Board Panel 1p 18859 231 24X Fiche 50-322.83/06/08.8306160305
- B306130387 Forwards srecuted JC Higgins affidavit re diesel generators BORDENICK, B M Hearing Branch 3 83/06/09 BRENNER, L , MORRIS, P A , CARPENIER, J L Atomic Safety and Licensing Board Panel 2pp 18823 011 24% Fiche 50-322, 83/06/09, 8306130387
- --8306130391 Affidavit of JC Higgins re diesel generators Util informed affiant of surface crack indications in camehaft blocks of diesel generators on 830330 Cracks caused by casting & cooling block, not preoperational testing RIGGINS, J C NRC No Detailed Affiliation Given 83/06/09 3pp 18923 013 24% Fiche 50-322,83/06/09,8306130387
- 8306150395 Forwards Buffult County status rept re need for addl time to file draft emergency planning contentions.per ASLB 830505 order
 - order
 MCHURRAY, C. M. Kirkpatrick, Lockhart, Hall, Christopher & Phillips
 MCHURRAY, C. M. Suffolk County, NY 83/06/09 LAURENSON, J. A. Ato,
 Bafety and Licensing Board Panel 1p 18847 001 24X
 Fichs 50-322,83/06/09,8306150395 LAURENSON, J A Atomic
- --8306150401 Status rept requesting addl time to file draft emergency planning contentions if util transition plan only subj of contentions extension needed until 830818 to submit draft contentions. Certificate of Svc encl.

 HCMURRAY, C.M. Suffelk County, NY HCMURRAY, C.M. Kirkpatrick, Lockhart, Hill, Christopher & Phillaps. 83/06/09. Atomic Safet Fiche 50-322,83/06/09,8306150395
- 8306130414 Response to ASLB 830526 question re passive mechanical valve failures Encl affidavit responds to question.

 REPKA, D A Hearing Branch 3 83/06/10 ip. 18823: 224 24X

 Fichs: 50-322, 83/06/10, 8306130414
- ---8306130418 Affidavit of R Caruso responding to ABLB B30326 question repassive mechanical valve failures Discusses NRC resolution of generic equipment problems Prof qualifications & Cartificate of Svc encil CARUSO.R Division of Licensing 83/06/10, 10pp 18823 225 24X Fiche 50-322,83/06/10,8306130414.

- 8306150292 Order denying Suffolk County 630609 request for addl 14## 1
- 8306150300 Order excusing parties from filing draft or final contentions result alternative emergency plans until etil establishes consent of one or more govt entities to participate in emergency plan functions.

 LAURENBON.J A Atomic Safety and Liconbing Board Panel #4/05/11/3pp 18849 167 24X Ficho 90-322, 83/06/10, 8306190 100
- 8306150370 Response to ASLE 630526 memorandum & order directing clarification of certain matters re Contentian 8C 11 fively safety-related check valve included in intervice testing program & tested in one of three ways FLANAGAN, D D Long Island Lighting Co FLANAGAN, D D thintain & Williams 83/06/10 3pp 18847 288 24X Fiche 50 45-6-6/106/14 83061503/0
- --8306150373 Affidovit of JA Rigert, addressing questions no seasety related check valve categories & testing RIGERT, J.A. Long Island Lighting Co. 03/06/09 hpp. 11/047 _ / s 24X Fiche 50-322, 83/06/10. 6306150370
- --8306190381 Affidavit of JF Alexander, addressing independent watels engineering group evaluation of valve failures Contificate of Svc encl
 ALEXANDER, J f Long Island Lighting Co 83/06/09 App 18847 296 24x Fiche 50-322.83/06/10.8306150370
- 8306150416 Order adding EL Fructs to see list & deleting DI Denver Poss FRUCCI.E L Atomic Safety and Licensing Board Panel (1997) 1, 18847 128 P4X Fiche 50-322,83/06/10,8306(504)6
- 8306150379 Response supporting Suffelk County & North Charp Crolling for Safe Energy motion for order striking portions of util 830526 filing Emergency plans devoid of legal or practical substance Certificate of Svc end.

 DOUGHERTY, J. B. Shoreham Opponents Conlition 83/06/13 Atras, Safety and Licensing Board Panel App. 16847 235 24x Fiche 50-322,63/06/13,6306150379
- B306i50397 Motion for immediate decision rejecting util transition plan Plan does not involve state & county govt participation, therefore adequate emergency preparedness not provided Certificate of Byc encl
 BROWN, H H Philadelphia Electric Co BROWN, H H Kirkpatict
 Lockhart, Hill, Christopher & Phillips B3/06/13 Commissions
 Spp 18847 132 24X Fiche 50-322,83/06/13,8306i5039/
- 8306170394 Petition of Citizens for Orderly Energy Policy, Inc. for Isanto intervene in emergency planning hearing Member affidavets, notice of appearance & Certificate of Svc encl.

 SWARTZ, L. Affiliation Unknown. SWARTZ, L. Pacific Legal

 Foundation. B3/06/14 Atomic Safety and Licensing Board Parel.

 23pp. 18879, 293—24X Ficho. 50-322, 83/06/14, 8306170394
- 8306160287 Response opposing Suffolk County 830607 & 13 motions \$7.0 Commission ruling on util plan for emergency preparedness & immediate Commission decision rejecting transition plan CHRISTMAN.J N Lung Island Lighting Co CHRISTMAN.J N Huntor & Williams 83/06/15 Commissioners 14pp 18959 014 ;4x Fiche 50-022,83/06/15,8306160987
- 8306200337 Confirms ASLB 830615 oral granting of Suffolk County required for extension to 830627 for County to answer util 830600 motion for low power OL NRC response date extended antil B30630 DYNNER, A. R. Kirkpatrick, Lockhart, Hill, Christopher & Phillaps B3/06/15 DRENNER, L. B., CARPENTER, J. L., MORRIB, P. A. Atumic Baffet, and Licensing Board Panel 1p 18900 178 24X Fiche S0-322,63/06/15,6306200337

ī

- 8304220094 Submits correct title & address for J Noverro SITLER.P Long Island Lighting Co 13/06/15. Docketing & Services Branch 1p 18926 210 24X Fiche 50-320.67/06/15.
- 8306220088 Forwards affidavits supporting Citizens for Orderly Interst Policy. Inc B30614 petition to intervene SWARTZ, L. Pacific Legal Foundation B3/06/16 LAURENBEN. J. A. KLINE, J. R., LIVINGBION. B. Atomic Safety and Licensing Scard Partl p. 18926-054 PAX Fiche 50-322, 83/06/16, 8306220088

- --8306220093 Suppl to Citizens for Orderly Inergy Policy 830614 petition to Intervene consisting of J Foloy, Ab Inilly MK Kane, JJ Cadwell & JP ludusi affidavits & Affiliation Unknown 83/06/09 Atomic Safety and Licensing

 - 19926 055 . 5pp 24X Fiche 50-322,83/06/14.
- B306220017 Advises that util presentation to Region 1 personnel on aspects of diesel generators scheduled for 830630 in King of Prussia PA IE Ngt Meeting Rept 50-322/81-20 to be issued
 - Related correspondence
 ELLIS.T S Hunton & Williams LLUIS.T S Long Island Lighting Co
 82/06/17 BRENNER.L , MCRRIS.P A , CAMPENTER.J H Atomic Safety and
 Licensing Board Panel 1p 18927 32.2 24X Fiche 50-322.83/06/17.
- 8306220134 Reply to util % NRC submissions on Suffolk County Contration II Facts in util & NRC affidavits must be scrutinized carefully LANPHERIL C Suffolk County, NY LANPHERIL C Kirkpatrick, Lockhart, Hill. Christopher & Phillips 83/06/20 ip 18926 156 24% Fiche 50-322,83/06/20.8306220134
- --8306270141 Affidavit of DG Bridenbaugh re info in record on Suffolk 306290141 Affidavit of BG Bridenbaugh re info in record on Buffo. County Contention II re passive mechanical value failuse Discusses deficiencies in inservice testing program Certificate of Svc BRIBENIAUGH, D. Suffolk County, NY 83/06/17 9pp 18926 157 24x Fiche 50-329,83/06/20,8306220134
- B306230004 Forwards Teledyne Engineering Svcs 830606 ltm Wattachments re independent dosign verification program Cortificate of Svc encl BORDENICK.B M. Hearing Branch 3 83/06/21 BRENNER, L., CARPENIER, J. L., MORRIS, P. A., Atomic, Safety and Licensing Board Panel Lapp 16947 080 24% Ficho 50-322,83/06/21,8306230004
- 8304230008 Response apposing Suffalk County D30407 & 13 motions for summary rejection of util offsite emergency transition plan Rejection w/o review & hearing could deny apportunity to present case on merits W/Certificate of svc REPKA, D A Hearing Branch 3 03/06/71 Commissioners 10pp 18947 120 244 Fiche 50-322,88706/21.8306230008
- 0305270390 Requests to make limited appearance statements at 830714
 - hearings FORST,M., KING,W., FOX.C. Affiliation Unknown 83/06/21 of the Secretary of the Commission 'rp 18993 304 24 Fichs 50-322,83/06/21,8306270390
- B3052B0572 Requests to make limited appearance statement at morning session of B30714 hearings FORAT, H Affiliation Unknown B3/06/21 Office of the Secretary of the Commission 2pp 19017 310 24X Fiche 50-322,83/06/21,
- 8306270144 Memorandum & order granting in part & denying in part Suffolk County 830502 motion to admit new contention researcements diesel generators BRENNER.L Atomic Safety and Licensing Board Panel 83/06/22 Suffolk County, NY 49pp 1/012 197 24X Fiche 50-322,63/06/22,8306270144
- B306270280 Citizens for Orderly Energy Policy. Inc draft contentions
 Util can develop emergency plan, per NRC & FEMA stds, to
 protect public health & safety adequately in event of
 emergency Certificate of Svc rncl
 BMARTZ.L L Affiliation Unknown BMARTZ.L L Pacific Legal
 Foundation BJ/06/22 Atomic Safety and Liconsing Board Panel
 11pp 18996 209 24X Fichs 50-322, 63/06/22, 8306270260
- 8396280601 Consolidated draft emergency planning contentions of Suffolk County, Shoreham Opponents (belition, North Shore Committe & Town of Southhampton, based on util transition plan LETSCHE, K. J. Suffolk County, NY LETSCHE, K. J. Kirkpatrick, Lockhart, Hill, Christopher & Phillips 83/06/23 Atomic Safety and Liconsing Board Panel 174pp 19015, 169 24X Fiche, 50-322, 83/06/23, 8306280601
- --8306280608 Draft emergency planning contentions of Town of Bouthampton Certificate of Svc encl SHEA.J F Southampton, NY SHEA.J [Twomey, Latham & Shea 83/06/22 Abomic Safety and Licensing Board Panel Bpp 19015-343 24X Fiche 50-382.03/06/23,0306280601
- OSO6290393 Motion to amend ave list by deleting M Kelly & adding J Feinberg. Notice of appearance & Certificates of Svc encl FEINBERG, J D Long Island Lighting Co FEINBERG, J D New York, State of, Energy Office 83706/23 Atomic Safety and Licensing Board Panel 5pp 19055 274 24X Fiche 50-322.83706/23.8306290393

- 8306290933 Advises that Town of Southampton joins in consolidated draft emergency planning contentions Finalized contentions to be submitted on 830707.will delineate which intervenor will participate on litigation of individual contentions MCMURRAY.C M Kirkpatrick, Lockhart, Hill, Christopher & Phillips B3/06/23 LAURENSON,JA, KLINE,JR, LIVINGSTON,MS Atomic Safety and Licensing Board Panel ip 19052 315 24X Fiche 50-322,03/06/23,8306290°33
- 8306280506 Forwards FEMA 830623 Findings on util transition plan for offsite emergency preparedness
 REPKA,D A Hearing Branch 3 83/04/24 LAURENSDN,JA,
 LIVINGSTUN,M S, KLINE,JR Atomic Safety and Licensing Board Panel
 22pp 19017 212 24X Fiche 30-322,8J/04/24,8306280506
- 8306290480 Forwards answer opposing util motion for low power OL Offsits emergency preparedness insufficient to support full power OL Motion premature since ASLB cannot issue initial decision on controverted matters DYNNER, A R Kirkpatrick, Lockhart, Hill, Christopher & Phillips DYNNER, A R Suffolk County, NY 83/06/27 REENKER, L J. CARPENTER, J L. Atomic Safety and Licensing Board Panel 5pp 19052 073 24X Fiche 50-320, 63/06/27, 8306290480
- --8306290485 Answer apposing util B30608 motion for low power CL Commission has not ruled on certified question on emergency planning Motion premature since ABLB cannot issue partial initial decision

 DYNNER, A R Suffolk County, NY DYNNER, A R Kirkpatrick, Lockhart, Hill, Christophur & Phillips B3/06/27 Atomic and Licensing Board Panel 55pp 19032 098 24X

 Fiche 50-322,83/06/27,8306290480 Atomic Safetu
- --8306290492 Motion for leave to file contentions re onsite emergency preparedness Revised onsite plan defective & incapable of adequate implementation since County relied upon to participate in & implement plan Certificate of Svc encl DYNNER.AR Suffolk County, NY 83/06/27 Atomic Safety and Licensing Board Panel 22pp 19057 183 24X Fichs 50-322,83/06/27,8306290480
- 8306290505 Clarifies petition to intervene re BNL dependence on power supplied by PABNY & LILCO PASNY supplies 75% of power over LILCO transmission lines LILCO supplies 25% of power SWARTZ.L L Pacific Legal Foundation 83/06/27 LAURENBON.J.A., KLINE,J R., LIVINGSTON.M 8 Atomic Safety and Licensing Board Panel ip 19052 214 24% Fiche 50-322,83/06/27.8306290505
- 63043000Bi Motion for leave to file contentions re onsite emergency preparedness Contentions not capable of final resolution during Phase I emergency planning matters Certificate of Svc encl
 DYNNER.A R Suffolk County, NY DYNNER.A R Kirkpatrick: Lockhart,
 Hill, Christopher & Phillips 83/06/R7 Atomic Safety and
 Licensing Board Panel 23pp 17121 043 24x Fiche 50-322,83/06/27,
 8306300001
- 8306300094 Response to Citizens for Orderly Energy Policy, Inc 830614 petition to intervene Suffalk County does not appose petition, but doubts NRC requirements and Certificate of Svc encl.

 Buffalk County, NY LETSCHE, K J Kirkpatrick.

 Letschart, Hill, Christopher & Phillips B3/06/27 Atomic
 and Licensing Board Panel. 5pp 19048 346 24X

 Fiche 50-322,83/06/27,8304300074 Atomic Bafetu
- 8306300147 Answer supporting Citizens for Orderly Energy Policy, Inc 830614 petition to intervene in proceeding on emergency planning issues Criteria for untimely intervention met Certificate of Svc encl REVELEY, W T Long Island Lighting Co REVELEY, W T Long Island Lighting Co REVELEY, W T Hunton & Williams 83/06/27 Atomic Sefety and Licensing Board Panel. Spp 19122 298 24X Fiche SO-322.83/06/27,8306300147.
- 830.6300070 Response conditionally supporting util 830.608 motion for low-power DL If Commission does not accept directed cartification of emergency preparedness issue & items resolved, DL should be issued H/Certificate of Syc. BORDENICK. B M Hearing Branch 3 83/06/29 Atomic Safety and Licensing Board Panel 8pp 19121 003 24X Fiche 50-322,83/06/29,8306300070
- B30630007i Response opposing Citizens for Orderly Energy Policy, Inc B30614 petition to intervene Citizens lack standing to intervene since no injury in fact shown as result of action W/Certificate of Bvc REPKA, D. A Hearing Branch 3 B3/06/29 Atomic Safety and Licensing Board Panel 17pp 19122 347 24X Fiche: 50-322,83/06/19, B306300071,

H Owneral correspondence

- 830&14031& Responde to 830413 ltm. Forwarding constituent H Jaffe 830407 ltm re-further development of nuclear power Issue re-safety classification of structures.sys & components will not delay plant completion & licensing DIRCKS.W J Office of the Executive Director for Operations 83708723 LENT.N F House of Rep. App. 18844 337 24% Fichs 80-322,83708723,8306140316
- --8306140323 Forwards constituent H Jaffe 830409 ltr re allegations that NRC halting efforts to develop nuclear power by delaying nuclear power plant licensing.

 LENT:N F House of Rep 83/04/13 COMDS:F NRC No Detailed Affiliation Given 4pp 18844 344 24% Fiche 50-322,83/05/23.

 8306140316
- 8306020347 Opposes facility restart MACLEOD.B. Affiliation Unknown 83/05/26 BRENNER.L Atomic Safety and Licensing Board Panel 1p 18694 320 24X Fiche: 50-322, 83/05/26, 8306020347
- 8304080194 Requests limited appearance hearings re emergency evaluation planning be held on Long Island HICKEY, M., EBBALL, J., NICOTERA, C. Affiliation Unknown. 83/05/28 LAURENSON, J. Atomic Safety and Licensing Board Panel 12pp 18772 239. 24X Fichs 50-322,83/05/28,8304080194.
- 8306130401 Eigresses concern re util-sponsored emergency plan Commission, not ASLB, must decide issue PETIT, M. R. Affiliation Unknown, 83/06/06 MORRIS, P Atomic Safety and Licensing Board Panel 2pp, 18923-045. 24X Fiche. 50-322, 93/06/06, 8306130401
- 8306270288 Bupports independent insp of plant BTIMKROTH T.J. Apriliation Unknown 83/06/13 LAURENSON NRC - No Detailed Afriliation Given 1p 18976 198 24X Fiche 30-322.83/06/13,8308270288
- 8306290501 Demands public hearings re emergency planning
 TERMIN.A Affiliation Unknown 83/06/23 LAURENSON, J.A. Atomic
 Bafety and Licensing Board Panel ip 19052 330 24X
 Fichs 50-322, 83/06/23, 8306290501
- 8306270526 Requests removal of JP Novarro from svc list Related correspondence SITLER, Long Island Lighting Co 93/06/23 Docketing & Services Branch ip 17052.327 24X Fishe 50-382,83/06/23,8306270526
- Q Inspection reports: IE Bulletins & correspondence
- 8308080210 Forwards 1E Insp Rept 50-322/83-13 on 830428-29 No noncompliance noted STAROBTECKI.R Division of Project & Resident Programs. 82/05/23 FOLLOCK.M S. Long Island Lighting Co 2pp 18727.276 24X Fiche: 30-322,83/05/23,8308080210.
- --8306060215 IE Insp Rept 50-322/83-13 on 830426-28. No noncompliance noted, Major areas inspected action on previously identified items, work activities, procedures & records re current status & conduct of const & const GA activities CERNE; A C Region 1. Office of Director. QALLO,R, M Division of Project & Resident Programs 83/05/18 8pp, 18727 278, 24% Fiche: 50-322,83/05/23,8306040210
- 8306060265 Forwards IE Insp Rept 50-322/83-14 on 830427-29 & 0506. No noncompliance noted.

 STAROBIECKI.R. Division of Project & Resident Programs. 83/05/25 POLLOCK.M S Long Island Lighting Co 2pp 18727:033 24X Fiche: 50-322.83/05/25.8306060265.
- --8306060268 IE Insp Rept 50-322/83-14 on 830427-29 t 0506 No noncompliance noted Major areas inspected licenses actions taken to comply w/requirements in NUREQ-0737, Item II. B. 2, "Design Review of Plant Shielding "
 KELLY.E. Region I. Office of Director, GALLO.R.M Division of Project & Resident Programs 83/05/23 Bpp 18727-035, 24x Ficher 50-322,83/05/25,8306060265.
- 8305110458 IE Info Notice 63-32, "Ruptured Am-241 Sources Contained in Well Lagging Device." Svc list encl.
 TAYLOR.J.M Division of Safeguards & Inspection Progrems (Post 830103). 83/05/26 Consolidated Edison Co. of New York, Inc. 125pp. 18831:043. 24X Fiche: 50-000,83/05/26.8305110458.
- 8305110460 IE Info Notice 83-34, "Event Notification Info Worksheet."
 Syc list encl.
 JORDANAEL. Division of Emergency Preparadness & Engineering
 Response (Post 830103) 83/05/26. Consolidated Edison Co. of New
 York, Inc. 115pp. 18732:085 24X Fiche 50-000,83/05/26.8305110460.

- 8304020071 Notification of 8J0402 significant licensee meeting w/otification in Mickeyille, NY to discuss SALP MCGABE, E.C. Region 1, Office of Director 83/05/24 Region 1, Office of Director 1p 18/01/33/ P4X Fiche 50-J22,83/05/24, 8304020071
- 8306090067 Forwards IE Insp Rept 50-322/63-10 on 830401-0509 & notice of violation STARDSTECKI, R Division of Project & Resident Programs 83/05/47 PGLLOCK, M S Long Island Lighting Co 2pp 18773-290 24X Fishe 50-322, 83/05/27, 8306090067
- --8306090069 Notice of violation from insp on 830401-0509 # Region 1. Office of Director 83/05/27 ip 18793 292 24x Fishe 50 322.83/05/27.8306090067
- --8306090074 IE Insp Rept 50-322/83 10 on 830401-0507 Noncompliance noted failure to assure that changes to emergency diesel generator test procedures distributed & used HIGGINS, J. C., ACCABELE C., KUNKLE, B.L. Region 1, Office of Director 83/05/25 14pp 18793 297 24X Fiche 50-322,83/05/2).
- 8304070128 Forwards IE Insp Rept 50-327/83-11 on 830405-14 No noncompliance noted MARTIN 7 T Division of Engineering & Technical Programs 83/05/23 POLLOCK,M S Long Island Lighting Co 2pp 18792 237 P4X Ficher 50-322, 83/05/27, 8306090128
- --B306090131 IE lasp Rept 50-382/83-11 on 830405-16 No noncompliance noted Major areas inspected structural acceptance test results evaluation, preoperational tert program, including status & implementation NICHOLAS: H H: VARELA: A A: BETTENHAUSEN.L Region 1: Office of Director G3/05/23 I3pp 18792 237 24X Ficho 50-322.83/05/27, 8306090128
- 8305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods Mithdrawn at BWRs " Svc list encl JORDAN,E L Division of Lawrgency Preparedness & Engineering Response (Post 830103) 83/05/31 Consolidated Edison Co of New York, Inc 116pp 18732 208 24X Fiche 50-000,83/05/31,6305110461
- 8306070321 Submits add1 confirmatory info re containment liner piping penetrations per NRC 830520 teleon Info submitted should enable closure of IE Bulletin 80.08 as fuel lead requirement SMITH. J L. Long Island Lighting Co 83/05/31 DENTON.H R Office of Nuclear Reactor Regulation, Director 3pp 18746 081 24X Fiche 50-322.83/05/31.8306070321
- B306070440 Provides list of options available to correct deficiencies in separation of electrical cables & laceways noted in 1E Insp Rept 50-322/79-07 SCHWENCER, A Licensing Branch 2 B3/05/31 PDLLOCK, N 8 Lang Island Lighting Co 4pp 18/76 359 24X Fiche 50-322,83/05/31,8306070440
- 8306140332 Ack receipt of 830509 ltr informing NRC of steps taken to correct violations noted in IL Insp Rept 50-322/83-05
 8TAROSTECKIR Division of Project & Resident Programs 83/05/31
 PDLLOCK/M 9 Long Island Lighting Co
- ~-8306140358 Responds to NRC 830330 ltr re violations noted in IE Intp Rept 50-322/83-05 Corrective actions Bailey Meter Co 120-volt ac.8 7 amp/24-volt dc.20 amp power supplies certified to provide 24-volt dc.30 output at power supply MUSELER.W J Long Island Lighting Co 83/05/07 STAROSTECKI.R Division of Praject & Resident Programs 7pp 18832 160 24% Fiche: 50-322,83/05/31.8306140332
- 8306140739 Forwards preservice insp plan transmittal & inservice insp field change authorization Receipt ack requested SMITH J L Long Island Lighting Co 83/06/01 DENTON, H R Office of Nuclear Reactor Regulation, Director 4pp 18841 096 24X Fiche 50-322,83/06/01.8306140739
- 8306070038 Informs that preservice insp program completed & available for onsite review Program should close out SER Open Item 19 BHITH J L Long Island Lighting Co 83706702 DENTON H R Office of Nuclear Reactor Regulation, Director 2pp 18737, 337, 24% Fiche: 50-322.83706702.8306070038
- 830&140494 Ack receipt of 830517 ltr informing NRC of steps taken to correct violations & deviations noted in IE Insp Rept 50-322/83-08. Exceptions to ESF reset position will be reviewed STAROSTECKI, R Division of Project & Resident Programs 83/06/03 POLLUCK, M S Long Island Lighting Co 2pp 18843 077 P4X Fichs 50-322,83/06/03,8306140494

- --8306/40498 Responds to NRC 830415 ltm to violations & deviations noted in IE Insp Rept 50-322/83-08 Corrective actions util startup personnel reviewed field installation of internal wiring to verify wiring installation PCLLOCK,M S Long Island Lighting Co 83/05/17 STAROSTECKI,R Division of Project & Resident Programs 10pp 19843 079 24X Fiche 50-322.83/06/03.8306140494
- 6306210104 Forwards IE Insp Rept 50-322/63-14 on 830510-12 No noncompliance noted MARTIN. 7 T. Division of Engineering & Technical Programs 83/04/07 POLLOGK, M. 6. Lung Island Lighting Co. 2pp. 18914 181 24X Fiche. 50-322
- --8306210107 IE Insp Rept 50-322/03-16 on 830510-12 No noncompliance noted Major areas inspected licenses work & QC activities recorrective action for significant deficiencies & other outstanding items NARROH, L., DURK, J. P. Region 1, Office of Director 83/96/05, 5pp 18714 183 24X Fiche 50-322,07/06/07,8306210104
- 8305140507 Provides add1 enginering review in effort to completely resolve confusion associated w/complex issue re ESF reset control (IC Bulletin 80-06)
 SMITH, J. L. Long Island Lighting Co. 89/06/08 DENTUN, H.R. Offic of Nuclear Reacts Regulation, Director App. 18093-097 24X
 Fiche 50-322,83/06/08,8306140607
- --B30&140&15 Forwards response to 830415 ltr Porwarding IE Insp Rept 50-382/83-08 & App B addressing notice of deviation re II Bulletin 80-06, "EBF Reset Controls" POLEOCK,N S Long Island Lighting Co 83/05/17 BTAROSTECKI,R Region I, Office of Director 15pp 18833 103 24X Fiche 50-322,83/06/08,8306140607
- 8305110444 IE Info Notice 83-36, "Impact of Security Practices on Safe Operations " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83706/09 Consolidated Edison Co of New York, Inc 119p 18830 280 24X Fishe 50-000,83706/09,8305110464
- 8305110470 IE Info Notice B3-30, "Defective Heat Sink Adhesive & Seismically Induced Chatter in Rolays Within Printed Circuit Cards" Svr list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83706/13 Consolidated Edison Co. of New York, Inc. 118pp 18720 225 24X Fishe 50-000, 83706/13, 8305110470
- 8306090010 IE Info Notice 83-37, "Transformer Failure Resulting From Degraded Internal Connection Cobles" Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Pesponee (Post 830103) 83706/13 Consolidated Edison Co. of New York, Inc. 243pp 18921 001 24X Fiche 50-000,83706/13,8306090010
- 8305110475 IE Info Notice 83-40, "Need to Environmentally Quolyfy Eppry Grouts & Seplers " Svc list encl JURDAN,C L Division of Emergency Preparedness & Engineering Response (Post 830103) 83706/22 Consolidated Edison Co. of New York, Inc. 115pp 17021 177 24X Fiche 50-000, 03/04/22, 0305110475
- 8305110477 IE Info Notice 83-41. "Actuation of Fire Suppression Sys Causing Inoperability of Safety Related Equipment " Syr list enc! JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/22 Consolidated Edison Co. of New York, Inc. 120pp 18997 007 24X Fiche 50-000, 83/06/22, 8309110477
- B305110477 lE Info Notice B3-42, "Reactor Mode Switch Ma)functions "
 Swc list encl
 JORDAN,C L. Division of Emergency Preparedness & Engineering
 Response (Post B30103) B3/06/23 Consolidated Edison Co of New
 York, Inc. 116pp 18996 242 24X Fiche 50-000, B3/06/23, 0305110479
- 8306280265 Clarifies util understanding of insp requirements for jet pump hold-down beams Beams retensioned per vendor recommendations & will be included in plant inservice insp program Commitment obviates need for add1 preservice insp SMITH, J. L. Long Island Lighting Co. 83/06/23 DENTON.H R. Office of Nuclear Reactor Regulation, Director Spp. 17015-014 24X fiche 50-322,83/06/23.8306280265
- 8305110483 IE Info Notice 83-43, "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints " Svc list enc) JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/24 Consolidated Edison Co. of New York, Inc. 116pp 19046 297, 24X Fiche 50-000,83/06/24,0305110483

- S Reportable occurrences, LERs & related correspondence
- 8304010432 Interim deficiency rept re failure of two Darling Valve Comotor-operated globe valves in RHR sys Initially reported on 830330 Procedure devised by vendor to preclude malfunction SMITH.J L Long Island Lighting Co 87/05/06 AlLAN.J M Region 1. Office of Director 4pp 18679 306 24X Fiche 50-322,83/05/06.8306010432
- 830401001: Interim deficiency rept re failure of Drown Boveri K-line 480-volt load ctr circuit breaker prop latch essemblies Initially reported on 830418 Prop latch essemblies mfg in Dec 1974 & Jan & Feb 1975 will be replaced SMITH.J L Long Island Lighting Co 83/05/18 ALLAN,J M, Region 1. Office of Director 3pp 18673 269 24X Fiche 50-322,83/05/18,8306010011
- 8306060349 Board Notification B3-67 forwards info re errors in computer analyses for Mark II containments Rapt providing results of evaluations performed by SAM re Shoreham Mark II containment also encl
 NOVAK.T M Assistant Director for Licensing 83/05/19 Atomic Safety and Licensing 803/05/19 Park Park 19 18753 079 24X
 Fiche 80-000.83/05/19.8306060349
- --B306060352 Final deficiency rept re QHDSH & rocking acceleration data transmittal discrepancy. Initially reported on B21039 & B30318 respectively No changes to plant design required GA Category I load transmittals will be reviewed MILLIGAN, M H Long Island Lighting Co B3/04/20 ALLAN, J M Region 1, Office of Director App 18753 085 24X Fiche 50-000, B3/05/19, B306060349
- 8306020455 Interim deficiency rept re failure of two high pressure fuel oil injector lines on emergency standby diesel generators initially reported on 830419 Program initialted to replace existing fuel oil injector line tubing SMITM-J.L. Long Island Lighting Co. 83/05/20 ALLAN.J M. Region 1, Office of Director. App. 18693-301 24% Fiche 50-322.83/05/20, 8306020455
- T Hearing transcripts on non-antitrust matters
- 8304080439 Forwards Commission determination statement withholding transcript of 830224 meeting from public disclosure CHILK 9 J Office of the Secretary of the Commission 83/05/18, Public Document Branch ip 18792 213 24X Fichs 50-322.83/05/18, 8304080439
- --8306080442 Commission determination statement withholding transcript of 830224 meeting from public disclosure CHILK/S J Office of the Secretary of the Commission 83/05/18 Office of the Secretary of the Commission 1p 18792,214, 24X Fiche 50-322,83/05/18,8306080439
- 8306140263 Transcript of 830610 hearing in Bethesda, MD Pp 21,179-21,438 ** Atomic Safety and Licensing Board Panel 83/06/10. 260pp 18842 103 24% Fiche 50-322,83/06/10,8306140263
- U Congressional/Executive Correspondence
- 8306020229 Forwards ensuer to Subcommittee on Nuclear Regulation Guestion 7, in response to 830411 ltr on FY82-83 Authorization Act. Saction 5 re current offsite emergency planning controversy PALLADING, N J Commissioners 83/05/09, OTTINGER, R L. House of Rep 1p 18701 Oct 24X Firms 50-322,83/05/09,8306020229,
- --8306020242 Forwards answer to Subcommittee on Nuclear Regulation Question 7, in response to 830411 Itr on FV82-83 Authorization Act, Section 5 re current offsite emergency planning contraversy PALLADINO, N J Commissioners 83/05/09 DOWNEY, T. J. House of Rep 6pp 18701 002 24X Fiche 50-322,83/05/09,8306020727
- --B306020248 Emphasizes that NRC must not take undue liberties w/1982 Authorization Act. Section 5 re offsite emergency preparedness NRC cannot consider local govt plam developed by util if plan officially approved by local govt DONNEY, T. J. DITINOEK, R. L. House of Rep. B3/04/11 PALLADINO, N J. Commissioners 3pp 18701 008, 24X Fiche 50-322.83/05/09.8304020229
- 8306030170 Designates MJ Dircks, Executive Director for Operations, as representative to fact finding panel on facility per 830422 request PALLADINO, N J Commissioners 83/05/10 CU0MO, M M. New York, State of 2pp. 18733 333 24X Fiche 50-322, 83/05/10, 8306030170.

- --8306030176 Requests assistance & participation in fact finding panel re-scientific & economic issues surrounding debate on proposed nuclear power plant CUMMO.N H. Hew York, State of 83/04/22 Commissioners 1p 18733-334 24X Fiche 50-322-83/05/10.6306030170
- V. Operator Examinations
- 830&140074 Requests attendance at B30&27 meeting w/Region I in King of ProssimpPA to discuss transfer of reactor operating licensing function from Bethesda, MB to Region I ofc STAROSTECKI, R Division of Project & Resident Programs 63/06/09 POLLOCK, N B Long Island Lighting Co 2pp. 18038 344 24X Fiche 50-322, 83/06/09.830&140074

DOCKET 50-323 DIABLO CANYON NUCLEAR POWER PLANT, UNIT P

- A Application/construction stage documents & correspondence
- 8306030162 Forwards response to Generic Ltr B3-100 re plans & scheduler for resolution of TMI Action Item II K 3 5. "Automatic Trip of Reactor Coolant Pumps " Util not required to submit enalyses supporting selection of pump trip criteria SCHNYLER, J & Pacific Gen & Electric Co 83/05/31 EISENNUI, D 0 pivision of Licensing 7pp 18703 344. 24X Fiche 50-275,83/05/31. Division of Licensing 7pp #306030162
- 8305070463 Forwards design verification program status summary as of 830806. Engineering affort & mad const required to be campleted prior to fuel load.
 DIRCKE, W J Office of the Executive Director for Operations 83/05/31. PALLADING, N J , 011, NRKY, V , AHEARNE, J, F Commissioners 12pp. 18780-318 24X Fiche: 50-275, 83/05/31, 8306070463
- 8306240464 Forwards request for add1 info meded to complete review of safety-related mesonry walls & necessary corrective actions based on review of 810701 submittal. Info requested within 60 days of itr receipt KNICHTON,O.W. Licensing Branch 3 83/06/07 CRANE,P Pacific Cost & Electric Co. Spp. 18978 IOS 24X Fiche 50-275,83/06/07,8306240464
- 8304140031 Forwards background for two articles published in Telegram-Tribune re-walding deficiencies. Info confirms misunderstanding between util & reporter. At no time did util review NRC drafts of subj rept
 8CHAYLER, J. O. Pacific Gas & Electric Co 83/06/09 EISENHUT. D 0 Division of Licensing. 2pp. 19839-331 24X Fiche. 50-275. 83/06/09, 8304440031
- 830&210111 Comments on util 790914 t 1228 submittals re moderate energy line breats [nfo responds to NRC request to evaluate plant design for effects of line breats on equipment required for safe shutdown Shield barrier requirements eliminated SCHUYLER, J. O. Pacific Oas & Electric Co. 8370&/15 KNICHTON, G. W. Licensing Branch 3. ip 18914.178 24K Fiche.50-275,8370&/15,830&210111
- F Becurity, medical, emergency & firs protection plans
- 8306170194 Ack receipt & provides evaluation of various changes to semrgyrou plan & corporate emergency plan implementing procedures Changes do not decrease effectiveness of semrgency response planning.
 NORDERHAUGLE Region 5, Dffice of Director 83/06/: Pacific Gas & Electric Co 2pp. 18882,302 24X
 Fiche: 50-275,83/06/13,8306170176 83/04/13. CRANE, P. A
- B30&170305 Ack receipt of Dec 1982. Rev 1 to San Luis Obispo County emergency response plan FEMA will provide NRC w/written confirmation of results of evaluations.

 NORDERHAMO, L. R. Region 5. Office of Director. 83/06/13 CRANE, P. A. Pacific Oas & Electric Co. 1p. 18877 145 24X

 Fiche 50-276.63/06/13,830&170305
- Q. Adjudicatory correspondence
- B3G6060182 Response supporting Povernor Daukasjian 830518 motion to reopen record in licensing proceeding to const GA Further evidence needed to const GA/QG, Certificate of Svc encl. REYNOLDS, J.R. Joint Intervenors-Diablo Conyon, REYNOLDS, J.R. Center Por Law in the Public Interest, 83/05/31. Atomic Baand Licensing Spand Panel. App. 15728-186, 24% Fiche: 50-275,83/05/31.8306060182. Atomic Bafety

- 8308086875 Response opposing Joint Intervenors 830510 & Covernor Deukmejian 830517 motions to reopen record on const GA Const GA program vigorous, thorough & in full compliance w/NRC ua program vigurous: Nortong & XX rull tempilance wrknic regulations Certificate of Sv. encl NORTON: B Parific Gas & Electric Co NORTON: B Norton: Durke, Berry & French 93/05/31 Panel 630pp 18730 031 44X Fiche 50-275, 83/05/31, 8306060275
- 8306070406 Response supporting Governor Drukmejian 930518 motion to reapen record on const GA Disclosure of thousands of deficiencies warrants reopening Certificate of Svc encl REYNOLOS, JR Joint Intervenors-Diable Canyon 93/05/31 Atom Safety and Licensing Appeal Ponel Spp 18742 275 244 Fiche 50-275,83/05/31.8306070406
- 8304150314 Notice of appearance in proceeding Certificate of Byt end HAVIAN.F. Joint Intervenors-Diable Cangon HAVIAN.E. Center for Law in the Public Interest 83/04/02 5pp 18849 132 24X Fiche 50-275,83/04/02.8306150314
- 8306150230 Response opposing Joint Intervenors 830510 & Governor Deukmejion 830518 motions to reopen record on const GA Movants fail to establish significance of info to GA findings in ASLB 810717 decision Certificate of Svc encl CHANDLER.L J Hearing Branch 2 83706706 Atomic Safety and Licensing Board Panel 176pp 18850 044 24X Fiche 50-27h, 83706706.8306150230
- 8306090309 Order allowing Joint Intervenors & Governor Deukmajian to reply to responses to motions to reopen record on const GA, by 830620 SWOMMAKER, C. J. Atomic Safety and Licensing Appeal Panel Joint Intervenors-Diablo Canyon 2pp 18795 191 241 Ficher 50-275, 83/04/07, 8304090309
- 8306150435 Potition for review of ASLB GD0518 Decision ALAB-728, to establish schedule for briefing on issues raised & to reverse ASLAB rulings in ALAB-728 Centificate of Syc encl REYNOLDS, J. R. Joint Intervenors-Diable Canyon REYNOLDS, J. R. Center for Law in the Public Interest B3/06/08 Commissioners 15pp 18847.030 24X Fiche 50-275,83/06/08.8306150435
- 8306160579 First document production request Related correspondence MORTON, D. Pacific Cas & Electric Co. MORTON, B. Morton, Burie, Berry & French 83/06/10 Joint Intervenors-Diablo Canyon & 18866-161 24X Fiche 50-275,83/06/10,8306160579
- -8306160584 First set of interrogatories Related correspondence NORTON. B Pacific Gas & Electric Co NORTON, B. Norton, Burbe, Barry & French 83/06/10 California, State of 17pp 18866 167 24x Fiche 50-275,83/06/10,8306160579
- ~-8306160575 First set of interrogatories Certificate of Svc encl Related ' correspondence NORTON, B Pacific Gas & Electric Co NORTON, B Norton, Burke, Berry & French, 83/06/10. Joint Intervenors-Diable Canyon 17pp 18866 184 24X Fiche 50-275,83/06/10,8306160579
- 8305140702 Notice of withdrawal of appearance in proceeding Certificate of Byc encl GDLDBERGJ R Hearing Branch 2 83/06/13 3pp 18841 2/1 24X Fiche 50-275.83/06/13.8306140702
- 830.6220038 Response opposing util & NHC responses to intervenor muticus to reopen issue on const QA NRC ignored util improper & rampant disregard of QA requirement & obsession w/hearing speed & scheduling Certificate of Svc enc!
 REYNCLDS, J R Joint Intervenors-Diablo Canyon REYNOLDS, J R.
 Center for Law in the Public Interest B3/06/17 Atomic Bafety and Licensing Appeal Panel lipp 13730 180 24X
 Fiche: 50-275, B3/06/17, B306220038
- 8304220045 Reply to responses of NRC & util to Governor Deukmejian motion to reopen record on const QA Bubmits new evidence of safety repulation violations & contends NRC & util response unacceptable.

 KAUFMAN, P. H. California, State of B3/06/17 Atomic Bafety and Licensing Appeal Panel 45pp 18927 259 24X Fiche 50-275, 83/06/17,8306220045
- ~~B30A220052 Affidavit of R Hubbard re breakdowns in design & const QA/ GC program & implementation Util & NRC did not include significant items in const QA review Implementation of QA/GC measures unacceptable Certificate of Svc encl HUBBARD.R.B. California. State of 83/06/15 14pp 18927 305 24X Fiche: 50-275,83/06/17,8304220045
- 8306240275 Response apposing Joint Intervenors 830608 petition for review of ALAB-728 No important safety, procedural, common defense, antitrust or public policy issues reised Certificate of Svc encl.

 CHANDLER, L. J. Hearing Branch 2, 83/06/23 Commissioners 14pp 18980 080 24% Fiche 50-275,83/06/23,8306240275

- 8306280522 Answer apposing Joint Intervenors 830608 pitition for review of ALAB-728 Joint Intervenors fail to respond to rationale of ASLAB decision Certificate of Svc end CRANE, P. A. Partific Gas & Electric Co. 83/06/23 Commissioners 7pp. 19019-317 24X Fiche 50-275,83/06/23,8306280522
- 8306290935 Advises of concerns in evidence presented at 630614 independent design verification program meeting w/vtil/Bechtel licensing team Util fails to appreciate meaning/necessity of program Related correspondence REVNDLOS.JR Center for Law in the Public Interest REYNDLOS.JR Jaint Intervenors-Diabla Canyon 63706729 DENTUN.NR Uffice of Nuclear Reactor Regulation. Director 6pp 19052 318 24X Fiche 50-275,83/06/23.8306290535
- 8306280520 Proposes schedule for reopened hearings on design 0A NORTON, B Pacific Gas & Electric Co 03/06/24 Atomic Safety and Licensing Appeal Panel 3pp 19017 186 24% Fiche 30-279,83/06/24, 8306280520
- 830.6300052 Order scheduling 830/17 hearing on Governor Deukmejian & Joint Intervenors motions to reopen record on const 6A issue NRC to provide ASLB & parties w/NRC insprepts on const 6A by 830708
 SHGEMAKER, C. J. Atomic Safety and Licensing Appeal Panel 83/06/28
 Office of the Executive Legal Director 4pp 19120 189 24X
 Fiche 50-275,83/06/28,8306000052
- 8304300044 Requests that arrangements be made for removal & storage of security mails in NRC storage room Room requires repair & is needed for other purpose.

 CHANDLER.L J Hearing Branch 2 B3/06/29 STRUMWASSER.M California, State of ip 19121 Off 24X Fiche 50-P75,83/06/29,8304300044

H General correspondence

- 830&010336 Expresses alarm re recent news rept that POME officials had seen proliminary drafts of NRC investigation rept concerning OA violations NRC investigation requested REYNOLDS, JR Johnt Intervenors-Dioblo Cangon REYNOLDS, JR Center for Law in the Public Interest 83/03/25 FISENHUT, D G Division of Licensing 4pp 18680 07? 24X Fiche 50-275,83/05/25,83/05/10334
- 8306070036 Provides names & addresses for appropriate distribution of technical correspondence re facilities
 SCHUYLER, J C Pacific Gas & Electric Co 83/06/02 DENTON, H R Office of Nuclear Reactor Regulation, Director EisENHUT. D Q Division of Licensing MARTIN. J B Region 5. Office of Director 2pp 18739 337 24% Fiche 50-000.83/06/02,0304070036
- O Inspection reports: IE Bulletins & correspondence
- 8306100007 Addl response to FOIA request for documents dtd 820101 or after re SALP Forwards App A documents Documents also available in FDR FELTON, J M Division of Rules and Records 83/04/11 CLARK, R San Francisco Elaminer 3pp 18815-252 24X Fiche 50-000.03/04/11, 8306100007
- ~~8306100014 Submits schedule for Region V SALP Board meetings for B20924-030523 ENGELKEN,R II Region 5, Office of Director 82/03/17 DENTON,H R Office of Nuclear Reactor Regulation, Director 1p 18015 255 24X Fiche 50-000.83/04/11.8306100007
- --8306100036 Discusses assignment of SALP coordinators for Reactor Operations Projects Branch facilities Coordinators will be responsible for preparing input data used by board members in analyzing functional areas Draft note from 8 Miner encl STERNBERO.D M Region 5, Office of Director 82/03/24 Region 5, Office of Director 11pp 16815 F57 24X Fichs 50-000,83/04/11,8306100009
- 8304070360 Forwards IE Insp Repts 50-275/83-15 & 60-323/83-12 on 830418-22 No noncompliance noted 815H0P.T.W Region 5. Office of Director 83/05/03 CRANF.P A Pacific Gas & Electric Co Ppp 18742 116 24X Fiche 50-275.83/05/03.8304070360
- --8306070369 IE Insp Repts 50-275/83-15 & 50-323/83-12 on 830418-22 Nu noncompliance noted Major areas inspected constractivities & mods to annulus structural steel ventilation duct supports, containment spray piping supports & circuit breakers BURDOIM. J F. ZHETZIO. G B. Region 5. OPPics of Director 83/04/29 Spp 18742 188 24X Fiche 50-275,80/05/03.8304070360

- 8306070093 Forwards lE Insp Repts 50-275/E3-14 & 50-323/83-11 on BJ0301-02 & 31 Nu noncompliance noted BISHOP.T W Region 5. Office of Director 83/05/11 CRANE, P A Pacific Gas & Electric Co 2pp 18739 135 24X Fiche 50-275,83/05/11,8306070093
- --8306070098 IE Insp Repts 50-275/83-14 & 50-323/83-11 on 830301-02 & 31 No noncompliance noted Major areas inspected IE bulletins & circulars followup on previous licensee commitments & independent insp MORRILL, P. J., KIRSCH. D. F. Region 5. Office of Director 83/05/09 4pp 18739 137 248 Fichs 50-275/83/05/11.8306070093
- 8305110458 IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in Well Logging Device" "Svc list enc! TAYLOR.J M Division of Bafeguards & Inspection Programs (Post B30103) B3/05/26 Consolidated Edison Co of New York, Inc 125pp 18831 043 24X Fiche 50-000,83/05/26,8305110458
- 8305110460 IE Info Notice 83-34, "Event Notification Info Worksheet"
 Svc list ent)
 JORDAN,E L Division of Emergency Preparedness & Engineering
 Response (Past 830103) 83/05/26 Consolidated Edison Co of New
 York, Inc. 115pp 18732-085 24% Fiche 50-000,83/05/26,8305110460
- 8306280189 Forwards IE Insp.Repts 50-275/B3-17 & 50-323/83-13 on B30403-30 & notice of violation W/d notice of violation BISHDP.T W Region 5. Uffice of Director B3/05/26 CRANE, P A Pacific Gas & Electric Co 2pp 19014 124 24X Fiche 50-275,83/05/26,8306280189
- --8306280194 IE Insp Repts 50-275/83-17 & 50-323/83-13 on 830402-30 Noncompliance noted failure of general const personnel to inform plant manager of observed damage to RCS piping CARLSON, J D, MENDONCA, M M, KIRSCH, D F, Region 9, Office of Director 83/05/25 10pp 17014 126 24X Fichs 50-275,83/09/24, 8306280189
- 8305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods Withdrawn at BWRs " Svc list encl JORDAN, C. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/31 Consolidated Edison Co. of New York, Inc. 114pp 18732 208 24X Fiche 50-000,83/05/31,8305110461
- 8306300041 Responds to IE Bulletin re check valve failures in raw water cooling sys of dissel generators Chock valves not used in closed-loop jacket cooling water sys SCHUYLER, J D. CRANE, P. A. Pacific Gas & Electric Co. 83/06/06 MARTIN, J B. Region 5, Office of Director Rpp. 19468 129 24X Fiche 50-275,83/06/96,8306300041
- 8305110444 IE Info Notice 83-34. "Impact of Security Practices on Sefa Operations " Svc list encl JORDAN.C.L. Division of Emergency Preparedness & Engineering Response (Post B30103) 83/06/09 Consolidated Edison Co. of New York, Inc. 119pp 18830 280 24X Fiche 50-000,83/06/09.8305110464
- 8305110470 IE Info Notice 83-38, "Defective Heat Sink Adhesive & Seismically Induced Chatter in Relays Within Printed Circuit Cards." Syc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83704713 Consolidated Edison Co of New York, Inc. 118pp 18920 225 24X Fiche 50-000, 83704713, 8305110470.
- 8306090010 IE Info Notice 83-37, "Transformer Failure Resulting From Degraded Internal Connection Cables" Svc list ancl JORDAN, Et. Division of Emergency Preparedness & Engineering Response (Post 830103) 83706/13 Consolidated Edison Co of New York, Inc. 243pp 18921 001 24X Fiche 30-000,83/06/13,8306090010
- 8305110475 lE Info Notice 83-40, "Need to Environmentally Qualify
 Epoxy Grouts & Sealers " Svc list encl.
 JORDAN.E.L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83706/22 Consolidated Edison Co. of New
 York, Inc. 115pp. 19021 179 24X Fithe 50-000,83/06/22,8305110475
- 8305110477 IE Info Notice 83-41, "Actuation of Fire Suppression Bys Causing Inoperability of Safety-Related Equipment " Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/22 Consolidated Edison Co. of New York, Inc. 120pp 18997 007 24X Fiche 50-000,83/06/22,8305110477,
- 8305110479 IE Info Notice 83-42, "Reactor Mode Bwitch Malfunctions " Svc list ent! JORDAN, E. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/06/23 Consolidated Edison Co of New York, Inc. 115pp 18996-242 24X Fiche 50-000.83/06/23.8305110479.

- 8305110483 IE Info Notice 83-43, "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints " Svc list encl JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83705/24 Consolidated Edison Co. of New York, Inc. 116pp 19046, 297 24X Fiche 50-000, 83/06/24, 8305110483
- R Periodic operating reports & related correspondence
- 8306210162 Forwards "Phase II Final Rept Besign Verification Program," per Biffig ltr specifying requirements for addl info BRAND.D. A Pacific Gas & Electric Co 83/06/13 DENTON.H R Office of Nuclear Reactor Regulation, Director 1p 18915 290 24% Fiche 50-275,83/06/13,8306210162
- --8306210171 "Phase II Final Rept.Design Verification Program" * Pacific Gas & Electric Co 83/06/30 100pp 18915 291. 24X Fiche 50-275,83/06/13,8306210162
- 8 Reportable occurrences. LERS & related correspondence
- 8305110488 Board Notification 83-73 forwards 830509 ltm t PNO-V-B3-021 re-potential for inadequate wolds in component cooling water siging sys
 EISEMHUT, D.O. Division of Licensing 83/06/20 PALLADINO, N.J.,
 OILINSKY, V., AMEARNE, J.F. Commissioners, App. 18778 003 24X
 Ficha 50-275,83/06/20,8305110488
- V. Operator Examinations
- 8306240465 Approves 830315 request for variance in std cold license certification on program allowing abbreviated 5 wk varsion of Phase II program for II on-shift operators KNIORTON, 0 W Licensing Branch 3, 83/06/13 CRANE, P A Pacific Oas & Electric Co 2pp 18998 101 24X Fiche 50-275,83/06/13, 8306240465.
- DOCKET 50-324 BRUNSWICK STEAM ELECTRIC PLANT, UNIT 2 F Security, medical, amergency & fire protection plans
- 8305140698 Ack receipt of 830131 ltr informing NRC of corrective actions taken in response to 821101 confirmation of action ltr re emergency preparadness program LEMIS.R.C. Division of Project & Resident Programs 83/03/31 FURR.B.J. Canaline Power & Light Co. ip 18841.R68 24X Fiche. 50-000,83/03/31,8306140698
- --8306140708 Submits status of corrective actions for deficiencies noted in 821101 confirmation of action ltr re emergency preparatness program UTLEY.E E Carolina Power & Light Co. 83/01/31 O'REILLY, J P Ragion 2. Office of Director. 2pp 18841 269 24X Fiche. 30-000,83/03/31.8306140698
- 8306220273 Confirms telcon w/IE re acceptability of emergency response facilities Locations of alternate locations for offsite personnel to assemble to communicate w/emergency operations facilities acceptable HURFORD.W J Carolina Power & Light Co 83/06/17. DENTON.H R. Office of Nuclear Reactor Regulation. Director ip. 18926 030 24) Fiche: 50-000, 83/06/17. 8306220273
- J. Insurance & indomnity information
- 8306210082 Forwards Endorsement 49 to NELIA Policy NF-218. BARHAM,C D Caroline Power & Light Co 83/06/13 SALTIMAN, J Antitrust & Economic enelysis Branch (Utility Finance). 2pp 18911.237. 24X Fiche 30-324.83/06/13.8306210082.
- 8306210109 Forwards Endorsement 42 to MAELU Policy MF-80 BARHAN, C W Carolina Power & Light Co 83/06/13 SALTZMAN, J NRC - No Detailed Affiliation Given. 2pp. 18914 179 24X Fiche: 50-324,83/06/13,8306210109
- P. Operating license stage documents & correspondence
- 8304020020 Informs that, besed on review of BMR Dwners Group 801230 response to NUREO-0737. Item II K 3 45. "Depressurization H/Other Than Automatic Depressurization Sys." complete VABBALLO, D. B. Operating Reactors Branch 2 83/05/18 UTLEY, E E. Carolina Power & Light Co. 7pp. 18702-034 24X Fiche. 50-324, 83/05/18, 8304020020.

- B30608080 Forwards nonproprietary & proprietary versions of NF-1583 04, "Verification of CPM. Ref PWR Thermal-Hydraulic Hethods Using FIBMR Code "Affidavit ont? Proprietary version withheld (ref lOCTR2 790)

 ZIMMERMAN S R Carolina Power & Light Co B3/05/31 VASALLA, D & Operating Reactors Branch 2 App 13/71 029 24X

 Fiche 50-324,83/05/31.8304080080
- --8306080083 Nonproprietary "Verification of CP&L Ref BWR Thermal Hydraulic Methods Using FIBWR Code " FOPE.M A. KUNIYA.R K Carolina Power & Light Co NF-1583 04 (NP) 83/05/18 41pp 187/1 035 24% Fiche 50-324.83/65/.il, 8306080080
- 8306076038 Responds to B30414 request for addl info re structural Aspects of Mark I containment program plant-unique analysis rept Util in process of obtaining info from United Enganeers & Constructors Response util be provided by B30805
 ZIMMERMAN, 8 R Carolina Power & Light (a B3/06/02 VASSALLP,8 g Operating Reactors Branch 2 ip 18/J/J 335 24X
 Fiche 50-324,69/06/02,8306070035
- B305150464 Forwards request for add1 ando re review of structura) aspects of plant-unique analysis rept for Mark I long-term containment program Meeting should be held within 3 wks to discuss response VASSALLO, D B Operating Reactors Branch 2 B3/06/03 UTHIY, EF Carolina Power & Light Co 5pp 18869 206 24% Fiche 50-324, B3/06/03, B306150464
- 6306240246 Discusses justification for continued safe operation of facility pending NRC issuance of necessary Tech Spec revs to support Cycle 4 Revs replant sus actuation instrumentation expected within 30 days of startup HOME.P W Carolina Power & Light Co 03/06/20 VASSALLO, D β Operating Reactors Branch 2 3pp 10/00 J68 24% Fiche 50-324.83/06/20.8306240/46
- 8306240008 Forwards "Reactor Containment Bldg Integrated Leak Rate Test " Test failed acceptance criteria during initial performance Next integrated leak rate test scheduled for Fall 1783 maint outage DIETZ, C.R. Carolina Power & Light Co. 83/06/21 DENTON, H.R. Office of Nuclear Reactor Regulation, Director ip 1898! 117 24; Fiche 50-324,83/06/21.8306240008
- --8306240012 "Reactor Containment Bldg Integrated Leak Rate Test" LEVINSON, E.D. General Physics Corp. GP-R-74002 82/07/31 175pp 18981 118 24X Fiche 50-324,83/06/21,8306240008
- 8306270225 Forwards results of plant-unique calculations which for bases for mod program in response to Grouic Ltr 83-08.
 "Mod of Mark I Containment Vacuum Breakers"
 ZIMMERMAN.S R Carolina Power & Light Co 83/06/23 VASUALLO.D B Operating Reactors Breach 2 85pp 10788 293 24X
 Fiche 50-324,83/06/23.8306270225
- --8306270226 Rev 1 to "Improved Dynamic Vacuum Breaker Valve Response for Brunswick Plant " 4 Continuum Dynamics, Inc. 62/09/30 27pp 18987-016 24X fiche, 50-324, 83/06/23, 83/06270225
- --B306270230 Rev O to "Mark I Vacuum Breaker Improved Valve Bunamit Model - Model Development & Validation " SULLIVAN, J M Continuum Dynamics, Int B2-31 ROO 82/08/31 40pp 18989 043 24% Fiche 50-324,83/06/23,8306270225
- 830.6280.524 Bupplemental application for amend to Licenses DPR-71 & DPR-62 revising Tech Specs re RCIC sys actuation instrumentation.per Generic Ltr 83-02 & NUREG-0737 items HOWE.P. N Carolina Power & Light Co 83/06/23 VASSALLO, D B Operating Reactors Branch 2 App 19017 290 247 Fiche 50-324.83/06/23.8306280524
- --8306280944 Revised Tech Specs re RCIC sys actuation instrumentation * Carolina Power & Light Co 83/06/23 21pp 19019 294 24K Fiche: 50-324, 83/06/23, 8306280524
- Q Inspection reports, IE Bulletins & correspondence
- B306140735 Confirms IE mgt meeting on B3031B at plant site to discuss status of facility improvement program Proposed meeting agenda encl
 O'REILLY,J P. Region 2, Office of Director 83/03/10. UILEY,E F
 Carolina Power & Light Co. 2pp. 18841 092 24X
 Fiche. 50-324, 83/03/10,8304140735

- B30614069B Ack receipt of B30131 ltr informing NRC of corrective actions taken in response to B21101 confirmation of action ltr re emergency preparedness program
 LEWIS.R C Division of Project & Resident Programs B3703/31
 FURR.B J Carolina Power & Light Co ip 18841 268 24X
 Fische 50-000.83/03/31.830614069
- --8306140708 Submits status of corrective actions for deficiencies noted in 821101 confirmation of action ltr re emergency preparedness program UTLEY.C E Carolina Power & Light Co 83/01/31 O'REILLY, J P Region 2, Office of Director 2pp 18841 269 24X Fiche 50-000,83/03/31.63061406/B
- 8306140397 Confirms 830510 mgt mesting in Raleigh, NC to review SALP program (first phase) results, per 830412 telcon Proposed agenda encl
 LEWIS, R C Division of Project & Resident Programs B3/04/29
 UTLEY, E E Carolina Power & Light Co 3pp 18832 093 24X
 Fiche 50 000,83/04/29,8306140399
- 830614054/ Responds to Rev I to II Dulletin 82-03 re reactor recirculation & RHR sys Defective welds repaired using weld overlay technique Weld indication tables & isometric drawings of defective weld locations on the HOME.P W Carolina Power & Light Co 83/05/16 U'REILLY, J P Region 2, Office of Director 7pp 18043 281 24X Fiche 50-324.83/05/16.830614054/
- --B306140549 "Design Rept for Recarculation Sys Weld Overlay Repairs at Brunswick Steam Electric Plant, Unit 1 "
 CHARNLEY, J E. REEVES, P E. ADAMS, R II NUICCH Engineers, Inc CPL-09-102 ROO B3/05/05 75pp 18843 288 24X
 Fiche 50-384,03/05/16,8306140547
- 8306020107 Fowards safety evaluation & notice of granting relief from inservice inspirequirements VABSALLO, D. D. Operating Reactors Branch 2 83/05/19 UTLEY, E. E. Carolina Power & Light Co. Spp. 18701-120 24X Fiche 50 324.83/05/19.8306020107
- --8306020116 Bafety evaluation granting in part & denying in part, requests for exemption from inservice insp requirements * Office of Nuclear Reactor Regulation Director 83/05/19 App 18701 123 24% Fichs 50-324.63/05/19.8306020107
- ---8306020270 Notice granting in part & drnying in part.relief from ASMF Code Section XI inservice insp requirements VASBALLO,D D. Uperating Reactors Branch 2 83/05/19 2pp 18701 144 24X Fichs 50-324,83/05/19,8306020107
- B3D&OlO311 Forwards "Environ Qualification of Electrical Equipment, Brunswick Steam Electric Plant, Units 1 & 2 10CR+50 49 ~ 90 Day Response, "Vols I & II. per IE Bulletin 79-01B & B30411 request List of items to be qualified uncl UTLEY.E E Carolina Power & Light Co B3/05/20 VABBALLO, D B Operating Reactors Branch 2 79/pp 18669 147 24X Fiche 50-324.83/05/20,8306010311
- 8306140396 Ack receipt of 830505 ltr informing NRC of steps taken to correct violations noted in 1E Special Training Assessment Repts 50-324/03-04 & 50-325/03-04
 VERRELLI,D M Division of Project & Resident Programs 83/05/24
 UTLEY,E L Carolina Power & Light Co ip 18838 003 24X
 Fiche.50-324.83/05/24,8306140396
- --8306140404 Responds to NRC 830207 ltm re violations noted in IF Special Training Assessment Repts 50-324/83-04 & 50-325/83-04 Corrective actions orientation for new employees accomplished in accordance w/TI-301 BIETZ, C R Carolina Power & Light Co 83/05/05 O'REILLY, J P Region 2, Office of Director 3pp 18838 004 24X Fiche 50-324,83/05/24,8306140396
- --8306140413 Forwards IE Special Training Assessment Repts 50-324/83-04 & 50-325/83-04 on B30110-14 No noncompliance noted Significant weaknesses identified VERRELLI,D M Division of Project & Resident Programs 63/02/07 UTLEY,E E Carolina Power & Light Co 2pp 18838 007 24X Fiche 50-324,83/05/24,8306140396
- --8306140423 IE Special Training Assessment Repts 50-324/83-04 k 50-325/83-04 on B30110-14 No noncompliance noted Major areas inspected licensed & nonlicensed operator training training training HERL, C W. CABIMIT, M E. RAGLIN, K A. Region 2, Office of Director 83/02/03 10pp 18838 009 24X Fichs 50-324, 83/09/24, 8306140376

- 8306140194 Forwards IE Mgt Meeting Repts 50-324/83-19 & 50-325/83-19 on 830518 Concerns re violations of regulatory requirements & mgt control raised 0 (REILLY, J.P. Region 2, Office of Director 83/05/25 UTLEY, E.E. Carolina Power & Light Co. 2pp. 18833 033 24% Fiche 50-324, 83/05/25, 8306140194
- --8306140201 IE Mgt Meeting Repts 50-324/83-19 & 30-325/83-19 on 830518 Major areas discussed enforcement issues resulting from recent events at site involving inoperability of Unit 2 condenser offgas monitoring sys LEWIS.R C. Division of Project & Resident Programs 89/05/24 3pp 18833 039 24X Fiche 50-324.83/05/25,8306140194
- 8305110458 IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in Well Logging Device" "Syc list encl
 TAYLOR.J M Division of Safeguerds & Inspection Programs (Post
 830103) 83/05/26 Consolidated Edison Co of New York, Inc
 125pp 18831 043 24% Fiche 50-000.83/05/26.8305110458
- 8305110460 IE Info Notice 83-34, "Event Notification Info Worksheet" Svc list encl
 JOROBN.EL Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/05/26 Consolidated Edison Co of New
 York, Inc. 115pp 18732 085 24X Fiche 50-000,83/05/26,8305110460
- B306140693 Ack receipt of B30523 ltr documenting B30527 commitment date for G-list procedure rev. in response to IE Insp Repts 30-924/802-49 & 50-925/802-45 VERRELLI.D M Division of Project & Resident Programs B3/05/27 UTLEY.E Carolina Power & Light Co ip 18843 006 24X Fichs 50-324.83/05/27.8306140653
- 8305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods Withdrawn at BMRs " Svc list encl JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 800103) 807/05/31 Consolidated Edison Co. of New York, Inc. 116pp 18732 208 24X Fiche 50-000,83/05/31,8305110461
- 8304140677 Ack receipt of 830520 ltr informing NRC of steps taken to correct violations noted in IF Insp Rapts 50-324/83-05 & 50-325/83-05
 VERRELLI, D M Division of Project & Resident Programs H3/06/07.
 UTLEY, E C Carolina Power & Light Co ip 18841 351 24x
 Fichs 50-324,83/06/07,8306140677
- --83051406B2 Responds to NRC 830407 ltr re violations noted in IE Inap Repts 50-324/83 05 & 50-325/83-05 Corrective actions. operating procedures revised to accurately reflect desired position of fuel oil manual ff11 valves DIETZ.C R Carplina Power & Light Co 83/05/20 O'REILLY, J P Region 2. Office of Director 2pp 18841 352 24X Fiche 50-324,83/06/07,8306140677
- --B3061406BB Ack receipt of IE Insp Repts 50-324/83-05 & 50-325/83-05 & notice of violation Response to rept will be submitted by 830520 DIETZ.C R Carolina Power & Light Co B3/05/05 O'REILLY, J. P Region 2, Office of Director 1p 19841 354 24X Fiche 50-324.63/06/07.8306140677
- --8306140693 Forwards IE Insp Repts 50-324/83-05 & 50-325/83-05 on 830215-0315 & notice of violation VERRELLI,D M Division of Project & Resident Programs 83/04/07 UTLEY,E E Carolina Power & Light Co 2pp 18841 355 24X Fichs 50-324,83/06/07,8306140677
- --8306140699 Notice of violation from Insp on 830215-0315 * Region 2: Office of Director 83/04/07. ip. 18841-357 24X Fiche 50-324,8306407,8306140677
- --B306440705 IE Insp Repts 50-324/83-05 t 50-325/83-05 on 830215-0315 Noncompliance noted inadequate operating procedures for filling emergency power dissel generator fuel oil tanks t lack of ventilation of svc water valves MYERS.D D. GANNER.L.W. Region 2. Office of Director BEMIS.P Division of Project & Resident Programs 83/04/07 9pp 18841 358 24x Fiche 50-324,83/04/07,8306440677
- B306290402 Responds to IE Bulletin B3-03, "Check Valve Failures in Raw Water Cooling Sys of Diesel Generators," per B30310 ltr. TECHNO check valves used at facilities Valve arrangement drawings encl HOME: PW Caroling Power & Light Co B3/06/08 D/REILLY: J P Region 2, Office of Director App 19053 127, 24X Fiche 50-324: B3/06/08. B306290402
- 8305110464 IE Info Notice 83-36. "Impact of Becurity Practices on Bafe Operations " Svc)ist encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/07 Consolidated Edison Co. of New York Inc 117pp 18830: 280 24X Fiche, 50-000, 83/06/07, 8305110464

- 8305110470 IE Info Notice 83-38, "Defective Heat Sink Adhesive & Selamically Induced Chatter in Relays Within Printed Circuit Cards " Sec list entl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co of New York Inc (18pp. 18920 225 24% Fiche 50-000,83/06/13.8305110470
- 8306090010 IE Info Notice 83-37, "Transformer Failure Resulting From Degraded Internal Connection Cables " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co of Naw York, Inc 243pp 18921 001 24X Fiche 50-000,83/06/13.8306090010
- B306290524 Approves issuance of SALP regit Notes improvement in safety-related activities emergency preparedness & security & safeguards Heaknesses in GA program will be monitored O'REILLY, J P. Region 2, Office of Director 83/06/14 UTLEY, E E Caroline Power & Light Co. 5pp. 19049, 202 24X Fiche 50-000, 83/06/14, B306290524
- --8306270531 Forwards SALP Regts 50-325/83-09,50-324/83-09,50-261/83-0/,
 50-400/83-10 & 50-401/83-10 for Jan 1982 Jan 1983
 Evaluation will be discussed in Raleigh, NC on 830510
 LEHIS, R C Division of Project & Resident Programs 83/05/03
 UTLEY, E E Carolina Power & Light Co 2pp 19049 287 24X
 Fiche 50-000.83/05/14.8306290524
- --8306290537 SALP rept for Jan 1982 Jan 1983 * Region 2. Office of Director 83/05/03 64pp 19049 289 24X Fiche: 50-000, 83/06/14.8306290524
- --8306270553 Responds to 830503 SALP rept for Jan 1982 Jan 1983 Reduced NRC attention may be appropriate for Category I re fire protection NRC attention should be maintained at normal lavels for emergency preparedness

 UTLEY, E. Carolina Fouer & Light Co. 83/05/20. O'REILLY, J.P. Region 2, Office of Director 16pp 19049 354 24X

 Fiche: 50-000, 83/06/14, 8306290524.
- --8306290555 Forwards replacement Page 2 to Attachment 2 of 830520 ltr
 which commented on SALP rept.
 EURY, L W Carolina Power & Light Co 83/05/27, D'REILLY, J P
 Region 2, Office of Director 2pp 19050 009, 24X
 Fiche 50-000,83/06/14,8306290524
- 8305110475 IE Info Notice 83-40. "Need to Environmentally Gualify
 Epoxy Grouts & Sealers " Syr list enc)
 JURDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 630103) 83/06/22 Consolidated Edison Co of New
 York, Inc. 115pp 19021 179. 24X Fiche 50-000.83/06/22.8305110475
- 8305110477 IE Info Natice 83-41, "Actuation of Fire Suppression Sys-Causing Inoperability of Safety-Related Equipment." Syc list encl. JORDAN E. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/22 Commolidated Edison Co. of New York, Inc. 120pp. 18797 007, 24X Fiche: 50-000,83/06/22.8305110477.
- B305110479 IE Info Notice 82-42, "Reactor Mode Switch Malfunctions "
 Svc list encl
 JORDAN.E.L Division of Emergency Preparedness & Engineering
 Response (Post B30103) 63/06/23 Consolidated Edison Co of New
 York, Inc. 116pp. 18996 242 24X Fiche 50-000,83/06/23,0305110479
- B3051104B3 IE Info Notice 83-43. "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints." Suc list encl JDRDAN, E.L. Division of Emergency Preparedness & Engineering Response (Fost B30103) B3706/24 Consolidated Edison Co. of New York, Inc. 116pp. 19046 297. 24x Fiche 50-000,83/06/24,8305110483
- 8306900102 Ack receipt of 830502 ltr in response to notice of yiolation to proposed imposition of civil penalities from insps on 820712-14 to 20-22 Corrective actions responsive to problems but initiated only after yiolations confirmed.

 DEYOUND.R.C Director's Office. Office of Inspection and Englanders. UTLEY, E. Carolina Power to Light Co. Jops 19048: 207. 24% Fiche. 50-324, 83/06/28, 8306300102.
- --8304300108 Order imposing civil penalties in amount of \$400,000 for violations identified during inspe on \$20712-14 & 20-22, DEYDUNG, R C Director's Diffice, Office of Inspection and Enforcement \$3706/28, Caroline Fourt & Light Co. Spp. 19048: 210, 24% Fiche: 50-324,83/06/28,8306300102.
- R. Periodic operating reports & related correspondence
- 8306140214 Monthly operating repts for May 1983 M/830607 ltr HARRISON.F., DIETX.C R Carolina Power & Light Co. 83/06/07. DEYOUNG.R.C Director's Defice. Office of Inspection and Enforcement. 14pp. 18832 272 84X Fiche: 50-324.83/06/07.

- S Reportable occurrences, LEAs & related correspondence
- 8306140629 Confirms 830518 ansite enforcement meeting to discuss regulatory sesses re isolation of Unit 7 condenser offgas radiation maintons, per 830516 tolion Pioposed agenda encl O'REILLY, J.P. Region 2, Office of Director 83/05/16 Unity, i Carolina Power & Light Co. 2pp. 18842-087 24X Fiche 50-324.83/05/16.8306140629
- 8306010109 LER 83-036/03L-0 on B30424, routine surveillance rovening that primary containment multi-plant temp recorder showed temp indications but pristed erratically Caused by failed 5 s timing relay which prevented printing W/830518 ltr PASTVA, N J. DIETZ, C R. Carolina Power & Light Co. 83/05/18 0.78ELLY, J P. Region 2, Office of Director 2pp 106/3 JAD 741 Fiche 50-324, 83/05/18, 8306010109
- B30&010105 Updated LER 82-131/03L-2 on 821206.1/2 automatic reactor acram signal received due to instrument downscale signal from main steam/line realiation monitor D.P-D12-RN-K603D Caused by lose of high voltage input to relay W/830523 ltr PASTVA-M J. DICTZ, C.R. Carolina Pawer & Light Co. B3/05/P3 O'REILLY-J.P. Region 2. Office of Director. 2pp. 18474-060 PMJ Fiche 50-324.83/05/23,8304010105
- 8306010388 RO on 830507, main condenser steam jet all ejector uffgas radiation monitors A & B failed to indicate power level Caused by closure of root isolation valves to each monitor Shift personnel counseled DIETZ, C R Carolina Power & Light Co 87/05/23 G'REILLY, J P Region 2. Offste of Director Spp 18682 174 24X Fichs 50-324,83/05/23,8306010788
- 8304070097 LER 83-040/03L-0 on 830426, while performing operability tell of remote shutdown RHR sys flow monitoring instrumentation PT-55 8PC, determined RHR sys flow transmitter 2-E11-F1-3330 had no output response to applied test signal W/830526 ltr PASTVA, M J , DIET/L CR Carolina Power & Light Co 83/05/26 O'REILLY, J P Region 2, Office of Director 2pp 18739 2/0 241 Fiche 50-324,83/05/26,8306070097
- 8304070141 Suppl to special RO rept on UKO509, main condenser blees jet air ejector offgas radiation monitors A & B found not indicating as expected for 2, 300 power level Caused by closure of root isolation valves.

 DIETZ, C R Carolina Power & Light Co. 83/05/29 O'REILLY, J P. Region 2, Office of Birector 5 pp. 18,39 257 24X
 Fishe 50-324, 83/05/29, 8306070141
- B306070102 Updated LER B3-002/03L-2 on B30102 during performance of PT-0B 1 6. indicator 2-CAC-LR 2602 should level of -31 inches while redundant indicators 2-CAC-LI-2601-1 & 3 & local level indicator showed level of -29 inches M/B30531 ltr PASTVA, M J. DIETZ, C R. Carolina Power & Light Co. B3/05/31 C'REILLY, J P. Region 2, Office of Director 3pp. 18739 197 24% Fichs 50-324, 83/05/31, 8306070102
- 8306070235 Updated LER 83-026/03L-2 on 830313, suppression pool level indicator/recorder 2-CAC-LR-2602 showed out-of-oper low level while redundant level indicators showed normal level Caused by transmitter LY-2602 out of catior W/830531 ltr PASTVA.M J. DIETZ.C R. Carolina Power & Light Co. 83/05/31 O'/REILULY.J P. Region 2. Office of Director 3pp 18741 159 P4M Fiche 50-324, 83/05/31.8306070235
- 8304070342 RO increased Co-60 activity found in two bottom sediment samples collected 830405 & 06 No Co-60 found in surface water samples from intake & discharge canals during Apr 1983 No radiation hazard or exposure to public observed DIETZ.C R Carolina Power & Light Co 83/05/31 O'REILLY.J P Region 2. Office of Director 2pp 18/41 294 24X Fiche 50-324.83/05/31.8304070342
- 8306100177 RO on 830521.during power operation.electrical panels 4085 k HB8 discovered deenergized Basic ground rules by which test & const personnel may operate squipment not well understood at time of discovery DIETZ, C R Carolina Power & Light Ca 83/06/03 D'REILLY, J P Region 2, Office of Directur 3pp 18806 032 24X Fiche 50-324,83/06/03,8306100177
- 8306130455 Forwards NRR comments on draft AU rept to Congress for First Quarter 1983 DENTON H R Office of Nuclear Reactor Regulation, Director 83/06/07, HELTEMES, C J Director's Office 3pp 18830 176 24X Fiche 50~000.83/06/07.8306130455
- 8304200003 LER 83-049/03L-0 on B30511.main steam line channel instrument 2-D12-RM-K603D found actuating out of specified tolerances Caused by tener diode VR5 failure in channel instrument drawer VR5 replaced W/830609 ltr PARTVA.H J. DIETZ.C R Carolina Foue: & Light Co 83/06/09. 0/REILLY.J P Region 2. Office of Director 2pp 18903-360 Pfiche: 50-324, 83/06/09.8306200003

- 8306270119 RD on 830512 & 19.Fire Doors 106 109 & 201 declared inoperable due to high differential air pressure across each door preventing automatic self-closure Evaluation of air pressure problem underway DIETZ, C R. Carolina Power & Light Co. 83/06/09 O'REILLY, J P. Region 2. Office of Director 1p. 19/88 112 249 Fiche 50-324,83/06/09.83062/0117
- 8306270196 RD on 830504. Limiting condition for operation initiated for imperable Fire Door 208 on 49 ft elevation of control bldg Caused by misaligment of door within door frame Door to be repaired upon irrelipt of parts DIETZ.C R Carolina Power & Light Co. 87/06/09 0'REILLY.J P. Region 2. Office of Director 19 189'01 286 24X Fiche 50-324.83/06/09.83062/0196
- B306210096 LER B3-047/03L-0 on B30913, during supervisory technical review of completed test procedure for fire suppression water sys valve operability test, two sys valves not covered Test procedure temporarily revised M/330610 ltr PASTVAN J. DICTA, CR Carolina Power & Light Co B3/06/10 D'RE1LLY, J.P. Region 2, Office of Director Spp. 18914-211 24X Fiche 50-324, B3/06/10, B306210096
- B306270061 LER B3-04B/O3L-0 on BJ0520, surveillance revealed primary containment atmosphere oxygen analyzer 2-(AC-AT-1259-2 drywell oxygen concentration 1% higher than redundant analyzer Caused by calibr drift W/830614 ltr PABTVA, M J. DIETZ, C R. Carolina Power & Light Co. B3/06/14 O'REILLY, J P. Region 2, Office of Director. 2pp. 1898 058 242 Fiche 50-324,83/06/14,8306270061
- 8306270245 RO on 830513 limiting condition of operation initiated for Fire Door PO2 in diesel generator bldg Poor ineperable due to high differential air pressure encountered across door preventing solf-closure DIETZ.C R Carelina Power & light (p. 83/06/14 U'REILLY.J P Region 2. Dffice of Director ip 18708 27/ 24X Fiche 50-324.83/06/14.8306270745
- 8306270199 (ER 83-0.35/03L-0 on E30520, reactor water cleanup differential flow indicator 2-631 Rd15 indicated bigh Gaused by low output signal from flow transmitter FT NO12 Transmitter calibr & returned to see W/030615 ltr PASTYA,M J. DILTZ, C R. Curolina Power & Light Co. B3/06/15 O'REILLY, J.P. Region 2, Office of Director 3pp 18991 281 PAX Fichs 50-324,83/06/15,83062/0199
- B306270277 LER B3-041/03L-0 on B70520, rad drift annunciation received for control red 38-35 Caused by problem in rod position indication probe Annunciator cleared Problem will be resolved during Bept 1983 outage W/B30617 ltr PASTWA, N J. DILTZ, C R. Carolina Power & Light Co. B3/06/1/ O'REILLY, J P. Region 2. Office of Director 2pp 18796 169 20X Fiche 50-324, B3/06/17, B30627077
- B3DA300193 RG on B30502; gamma analysis of bottom sediment sample detected excessive Co-60 activity Bumpling Frequency increased from memiannually to monthly Sample represents seventh monthly sample

 DIETZ.C R Carolina Power & Light Co B3/06/17 O'REILLY, J P
 Region 2. Office of Director 2pp 19122 191 24X

 Fichs 50-324, 83/06/17, 8306300193
- 8306300031 Advises that LER 2-03-51 ro imperable C51 low level switch 2E41-181 N003 on 830924 will be submitted by 830707 DIETZ,C R Carolina Power & Light Co 83706723 D'REILLY,J P Region 2, Office of Director 1p 17120 312 24X Fiche 50-324,83706723,8306300031
- B706300012 LER 8.3-052/09L-0 on 830526, smake observed emanating briefly from RHK sys flow transmitter signal convertors 2-Eli-FY-33.8 & indicator did not show expected indication Caused by test leads shorting to ground 8/030624 lt; PASTVA.M J. DILTZ.C R. Carolina Power & Light Co. B3/06/24 O'REILLY.J P. Region 2. Office of Director 2np. 19120 315 P4X Fiche 50-324,03/06/24,830630001P
- B3Q6300242 RO on B30504 during shutdown operations, limiting conditions for operations (LCO) initiated for inoperable Fire Door 203 Caused by door minalignment Due to job planning canaiderations. /-day time frome of LCO exceeded DIETZ, C R Carolina Power & Light Co 03/06/24 D/RLILLY, J P Region 2. Office of Director ip 17:19 350 24X Fiche 50-324.83/06/24.8306300242
- 0306300106 EN-83-011A on 8302)G notice of violation & proposed imposition of civil penalties will be issued in amount of \$4600.000 Action based on failure to penform Tech Spec surveillances on sefety sys & components BARRER.0. AXCLRAD.J Director's Office. Office of Inspection and Enforcement 83/04/28 ip 19048-214, 24X Fiche 50-324.83/04/20.8304300104

V Operator Examinations

- 8306j40141 Requests approved ref matl re operator exams by 820225
 Missing deadline will result in delay in administering
 exams Applications should be submitted at least 60 days
 prior to first exam scheduled for wk of 830425
 VERRELLI.D M Division of Project & Resident Programs 83/02/07
 HOWE, J P Carolina Power & Light Co 4pp 18839 167
 Fiche 50-324.83/02/07.8306140141
- 8306140533 Confirms administration of written & oral requalification exams at facility during wk of 830627 Approved ref math must be furnished by 830425 O'REILLY.J P. Region 2. Office of Director 83/04/15 UTLEY.F E Carolina Power & Light Co. 3pp. 18834-323 24X Fiche 50-324,83/04/15,8306140533
- 8306140376 Ack receipt of 830505 Itr informing NRC of steps taken to correct vialations noted in If Special Training Assessment Repts 50-324/83-04 & 50-325/83-04 VERRELLI.D M Division of Project & Resident Programs 82/05/24 UTLEY.E F Carolina Power & Light Co ip 18838 003 24X Fiche 50-324-83/05/24-8306140396
- --8306140404 Responds to NRC 830207 ltr re violations noted in IE Special Training Assessment Repts 50-324/83-04 & 50-325/83-04 Corrective actions orientation for new employees accomplished in accordance w/TI-301 DIETZ.CR Carolina Power & Light Co 83/05/05 D'REILLY, J P Region 2, Office of Director 3pp 18638 004 24X Fiche 50-324.03/05/24.8306140396
- --8306140413 Forwards IE Special Training Assessment Repts 50-324/63-04 & 50-325/63-04 on 830110-14 No noncompliance noted Significant weaknesses identified VERRELLI.D N Division of Project & Resident Programs 83/02/07 UTLEY.C E Carulina Power & Light Co 2pp 18838 00/ 24X Fichs 50-324-83/05/24-8306140396
- --8306140423 IE Bpecial Training Assessment Repts 50-324/83-04 & 50-325/83-04 on 830110-14 No nuncompliance noted Major areas inspected licensed & nonlicensed operator training & requalification programs & on-shift/real time training HEHL, C W. CASHATT.M E., RAGLIN, K A. Region 2, Office of Director 83/02/03 10pp 18838 007 24x Fiche 50-324,83/05/24,8306140396
- DOCKET 50-325 DRUNSWICK STEAM ELECTRIC PLANT, UNIT I

 F. Security, medical, emergency & fire protection plans
- 8306140698 Ack receipt of 830131 ltr informing NRC of corrective actions taken in response to 821301 confirmation of action ltr re emergency preparedness program LEWIS.R C Division of Project & Resident Programs 83/03/31. EWR.D J Carolina Power & Light Co ip 18841 268 24X Fiche, 50-000, 83/03/31. 8306140698
- --8306140708 Bubmits status of corrective actions for deficiencies noted in 821101 confirmation of action ltr re emergency preparedness program
 UTLEY, E E Carolina Power & Light Co 83/01/31 O'REHLLY, J P
 Region 2. Office of Director 2pp 18841 269 24X
 Fiche 50-000, 83/03/318, 8306140498
- B306220273 Confirms telcon w/lL re acceptability of emergency response facilities Locations of alternate locations for offsite personnel to assemble to communicate w/emergency operations facilities acceptable HURFORD.W J Carolina Power & Light Co 83/04/17 DENTON.H R Office of Nuclear Reactor Regulation, Director Ip 18726-033 24X Fiche 80-000.83/04/17.8306220273
- J Insurance & indomnity information
- 8306210082 Forwards Endorsement 49 to NELIA Policy NF-21B BARHAM, C D Caroling Power & Light Co 83/06/13 SALTZMAN, J Antitrust & Economic analysis Branch (Utility Finance) 2pp 18911 237 24% Fiche 50-324,83/06/13,8306210082
- B306210109 Forwards Endorsement 42 to MAFLU Policy MF-60 BARHAM.C W Carolina Power & Light Co B3/06/13 SALTZMAN.J NRC - No Detailed Affiliation Olven 2pp 18914 179 24X Fiche 50-324, 83/06/13, 8306210109

- P Operating license stage documents & correspondence
- 830.6020699 Notice of consideration of issuance of amend to Liceuse DRR-71 & proposed no significant hazards consideration deteraination, incorporating limiting conditions for spatistion during fourth fuel cycle VASBALLO.8 8 Operating Reactors Branch 2 83/05/16 5pp 18715 320 24x Fight 50-325.83/05/16.8708020899
- 8305020020 Informs that based on review of BMR Duners Group B01230 response to MUREG-0737, Item II K 3 45. "Depressursation W/ Dibur Thin Automatic Depressursation Sys," complete vASGALLG.0 B Operating Reactors Branch 2 83705/18 UTLEY, E F Carolina Power & Light Co. 7ep. 18702-336 24X Fichs 50-324, 83705/18.8308020020
- 8306090080 Forwards nonproprietary & proprietary vertions of NF-1983 O4. "Verification of CPML Ref BUR Thermal-Hydraulic Hitches Using FIBMR Code" Aftifavit entl Proprietary version withheld (ref IOCFR2 790) INVERNAMES R Carolina Power & Light Co 83/05/31 VASSALLO, D & Operating Reactors Branch 2 App 18771 029 24X Fiche 50-324.83/05/31.8304080080
- 8306070035 Responds to B30414 request for add1 info re structural Aspects of Mark I containment program plant-unique analysis rest Util in process of obtaining info from United Engineers & Constructors Response will be provided by #30805 IIMMERNAM, 8 R. Carolina Power & Light Co. 83/06/02 VASSALLO, D.B. Gjerating Reactors Branch 2 to 18739 335 24X Fiche 50-324.83/06/02.8306070035
- 8306150464 Forwards request for add) anfo re review of structural aspects of plant-unique analysis rept for Mart I long-term confidence program Meeting should be held within 3 who to discuss response VASCALLO, D.B. Operating Reactors Branch 2 83/06/03 UTLEY, F.E. Caralina Power & Light Co. App. 18869 206 24% Fichs 50-324,83/06/03.8306150464
- 8306240145 Application to Amend License DFR-71, changing Tech Specs re souther listings, drywell sump instrumentation numbers, remote that down panel instrumentation numbers to solidation of MUREO-0737 mode for startup HOME, P. W. Carofina Power to Light Co. 83/06/20 DENTON, H. 8. Office of Muclear Reactor Regulation, Director 2pp 18981-041 24x Fishs 50-325,83/06/20,8306240145
- --8306240149 Revised Tech Spec he snubber listings, drywell susp instrumentation numbers remote shutdown panel instrumentation numbers & installation of NUREG-0737 mods for startup a Cerolina Pawer & Light Co 83/06/20 44pp 1898: 042 24x Fichs 50-325.83/06/20.8306240145
- 830A240246 Discusses justification for continued safe operation of facility pending ARC issuance of herestery Tack Spec revs to support Cycle 4 Revs re plant tys actuation instrumentation expected within 30 days of startup MCME, P W Carolina Power t Light Co 83706320 VASSALLD, D B Operating Reactors Branch 2 Spp. 18780 168 24X Picks 50-324,83706320,8306240246
- #306270225 Forwards results of plant-unique calculations which form bases for mos program in response to Generic Ltr 83-08, "Net of Neck I Centainsent Vacuum Brakers " IPMERNAMS R Carolina Power & Light Co 83/06/23 VASSALLO, D 8 Descriting Reactors Branch 2 85pp. 18988 293 24x Fichs 30-324, 83/06/23, 8306270225
- --8304270226 Rev i to "Improved Dynamic Vacuum Breaker Valve Response for Brunswick Plant" Continuum Dynamics. Inc 82/09/30 27pp 18989 016 24x
 Fiche, 50-324.83/06/23.8306270225
- --8304270230 Rrv O to "Mark I Vacuum Breaker Improved Valve Dynamic Model Model Development & Validation."
 SULLIVAN.J K Continuum Dynamics: Inc. 82-31 800 82/08/31 4091 18799 043. 24% Fiche 50-324.83/06/23.8306270825
- #206280924 Bugglemental application for smend to Licenses DPR-71 & DPR-A2/revising Tech Sprea re RCIC syst actuation instrumentation; per Generic Ltr #3-02 & MAREG-0737 items. MCME.P is Caroline Pours & Light Co #3706/23 VASSALLO, D B Gprasting Reactors Branch 2 499 19019 290, 24% Fichs; 30-324,83/06/23,8306280524

- --0306280544 Revised Tech Specs re RCLL sys actuations turtimenutall • Carolina Power & Light (a 03/06/2) Pipp 19019 Pub. 4s Fiche 50-324-03/06/23,8306900524
- G Inspection reports. IC Bulletine & correspondence
- 8306140078 Confirms 830328 appointment meeting at Region [1] of the discuss recent events at Bronnwick I are standby posterestent deluge sys & violation involving redwaste shipments from Robinson 2 per 830322 tilcon Agenda encl Q'REILLY, J.P. Region 2. Offsic of Disctor 8370779 till \$\delta i\] Carolina Power & Light Co. 2pp (88038 242 24x) fiche 50-000,83703725,8306140078
- 8306140698 Ack receipt of 830131 ltr imporming NRC of correction actions taken in response to U21101 confirmation of action ltr re emergency preparedness program LEMES, C. Division of Project & Nessdent Programs (FI/O)2/11 FURK & J. Carolina Power & Light Co. ip 10841 PA() 24% Fiche 50-000,83/03/31,8306140498
- --830514070B Submits status of corrective actions for deficient training 21101 confirmation of action 1th re-emergency preparedness program
 UTLEVIE E. Canalina Power & Light Co. US/01/31 11/81 let 1 1 1 Hegion 2. Office of Director Pop 18(4) 269 PAX
 Fiche 50-000, 89703/31, 3063106978
- 8306140399 Confirms 830510 mgt meeting in Raleigh, NC to review ".fl" program (first phase) results, per B.30412 tolkon Prepused agenda enct LEWIS, R.C. Division of Project & Resident Programs & #104422 UTLEV.E.E. Carolina Power & #1ght Co. 3pp 188322 GW2 ...ax Fiche 50-000.83/04/29,8304140397
- 8306140547 Responds to Rev I to IE Bulletin 82-03 re reacted recirculation & RHR sys Defective welds repaired using weld overlay technique Held indication tables & isometric drawings of defective weld locations procl HOME, F W Carolina Power & Light Co 03/03/14 U'RLHLY. P Region 2. Office of Director 7pp 18843 291 34X Fiche 50-324, 83/05/16, 8306140847
- ---8306140549 "Design Rept for Recirculation Sys Weld Overlay Repairs of Brunswick Steam Electric Plant, Unit 1" CHARMLEY, J E. REEVES, P. F. ADAMS.R. H. NUTECH Engineers, The GPL-09-102 ROD 83/05/05 /5pp 18043 280 24X Fiche 50-324,83/05/16.8306140547
- 830.6020107 Fowards safety evaluation & notice of granting relief file inservice insprequirements. VASSALLO,D B. Operating Reactors Branch 2 03/05/19 Uffliv.E & Carolina Power & Light Co. Opp. 18701-120 24x Fichs 50-324,83/05/19.8304020107
- --8306020116 Safety evaluation granting in part & donying in part, requests for exemption from inservice insp requirements.

 Office of Nuclear Reactor Regulation, Director. 63705/17 FVP 18701-183 24X Fiche SO-324, 83/05/17, 8306020107
- --8304020290 Notice granting in part & denying in part, relief from A "
 Code Section XI inservice inop requirements
 VASSALLO, D B Operating Reactors Branch 2 83/05/19 **pp
 18701 144 24X Fiche 50-324, 83/05/19, 8304070107
- B30&010311 Forwards "Environ Qualification of Liestrical Equipment. Branswick Steam Electric Plant. Units 1 t. 2 ~ LOCRESO 49 ~ 40 Day Response, " Vols 1 t. Il.per 1E Bulletin 79-01B & B30411 request List of items to be qualified and UTLEY, E & Carolina Power & Light Co. B3/05/20 VASSALLU, D. R. Operatino Reacture Branch 2 797pp 10649 147 24X Fiche 50-324, B3/05/20, B306010311
- BJ06140094 Ack receipt of BJ0505 ltr informing NRC of steps taken to correct violations noted in II Special Training Assessment Repts 50-324/83-04 & 50-325/83-04 VERRELLIA M Division of Project & Resident Programs GD/U5/24 VELEY, E. Carolina Power & Light Co. ip 18808 000 24X Fiche 50-324,83/05/24,8306140076

- --8306140404 Responds to NRC 830207 Itr re violations noted in If Special Training Assessment Repts 50-324/83 04 & 50-325/83-04 Corrective actions orientation for new employees accomplished in accordance w/TI-301 DIETZ.C R Carolina Fower & Light Co 83/05/05 D'REILLY.J P Region 2. Office of Director Jpp 18038 004 24X Fiche 50-324,8306140396
- --8306140413 Forwards IE Special Training Assessment Repts 50-324/83-04 & 50-325/83-04 on 830110-14 No noncompliance noted Significant weaknesses identified VERRELLI, D.M. Division of Project & Resident Programs G3/02/07 UTLEY, E.E. Caroline Power & Light Co. 2pp. 18838-007 24X Fiche 50-324,83/05/24,8306140396
- --8306140423 IE Special Training Assessment Repts 50-324/83-04 & 50-325/83-04 on 830110-14 No noncompliance noted Major areas inspected licensed & nonlicensed operator training & requalification programs & on-shift/real time training HEHLC N. CASHATT, N.E., RAGLIN, K.A. Region 2. Office of Director 837/02/03 10pp 18838 007 247 Fiche 50-324,83/05/24, 8306140376
- 8306140194 Forwards IE Mgt Mceting Ropts 50-324/83-19 & 50-329/83-19 on 830518 Concerns re violations of regulatory requirements & mgt control raised O'REILLY, J.P. Region 2. Office of Director 83/05/25 UTLEY, E.C. Carolina Power & Light Co. 2pp 1883,3 033 24X Fiche 50 324,03/05/25,8306140194
- --8306140201 IE Mgt Neuting Repts 50-324/83-19 & 50-525/83-19 on 830518 Major areas discussed enforcement issues resulting from recent events at site involving inoperability of Unit 2 condenser offgas monitoring sys LEMIS.R C. Division of Project & Resident Programs 83/05/24 3pp 16833 035 24x fiche 50-324,83/05/25,8306140174
- 8305110458 IE Info Notice 83-32. "Ruptured Am-241 Sources Contained in Mell Logging Device" Svc list encl TAYLOR, J M Division of Safeguards & Inspection Programs (Post B30103) 83/05/26 Consolidated Edison Co of New York, Inc 125pp 18831 043 24X Fiche 50 000.63/05/26.8305110458
- 8305;10460 TC Info Notice 82-34, "Event Notification Info Worksheet" Svc list encl
 JORDAN, El Division of Emergency Preparedness & Ingineering
 Response (Post 830103) 97/05/26 Consolidated Edison Co of New
 York, Inc 115pp 18732 085 24X Ficha 50-000,83/05/26,8305;10460
- 8306140693 Ack receipt of 8305,23 ltr documenting 8305,27 commitment date for G-list procedure rev.;18 response to IF Insp Repts 50-324,08-45 & 50-325,022-45 VERRELLI,D M Division of Project & Mesident Programs 83/05/27 UTLEY,E.L Carolina Power & Light Co ip 18843 006 24X Tithe 50-324,83/05/27,8306140673
- 8305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods Withdrawn at BWRs " Svc list encl JORDAN E L Division of Emergency Preparedness & Engineering Response (Post 830103) 53/05/31 Consolidated Edison Co of New York: Inc 116pp 18732 208 P4X Fiche 50-000,83/05/31,8308110461
- 8306140677 Ack receipt of 830520 ltr informing NRC of steps taken to correct violations noted in IL Insp Repts 50-324/83-05 & 90-328/83 05
 VERRELLI.D M Division of Project & Resident Programs G3/06/07
 UTLEY, E. F. Carolina Power & Light Co. 1p. 18841 351
 249
 Fische 50-324.03/06/07, 8306140677
- --8306140682 Responds to NRC 8J0407 lt; re violations noted in IE Insp Repts 50-384/83-05 & 50-385/03-05 Corrective actions operating procedures revised to accurately reflect desired position of fuel oil manual fill valves DIETZ.C R Carolina Power & Light Cn 83/05/20 O'REJILY, J P Region 2. Office of Director 2pp 18841 352 24X Fiche 50-324.83/06/07.8306140677
- ~-8306140688 Ack receipt of IE Insp Repts 50-324/83-05 & 50-325/83-05 & notice of violation Response to rept will be submitted by 830520 DIETZ, C R. Carolina Power & Light Co. 83/05/05 O'REILLY, J P. Region C. Office of Directo. lp. 16841-394 P4X Fiche 50-324,83/06/07,83061406/7.
- --8306140693 Forwards IE Insp Repts 50-924/83-05 & 50-925/83-05 on 830215-0315 & notice of violation VERRELLI,D M Division of Project & Resident Programs 83/04/07 UTLEY,E F. Caroline Power & Light Co 2pp 18841 355 24X Fiche 50-924,83/06/07.89061406/7
- --8306140699 Notice of violation from insp on 830215 0315 * Region 2, Office of Director 83/04/07 ip 18841 35/ 24X Fiche, 50-324, 83/06/07, 83061406//

- --8306140705 IE Insp Repts 50-324/83-05 & 50-325/83-05 on 830215-0315 Noncompliance moted inadequate operating procedures for filling emergency power disest generatin fuel oil tanks & lack of ventilation of svc water valves MYERS.D O. AARNER.L W Region 2. Diffice of Director BEMIS,P Division of Project & Resident Programs 83/04/07 7pp. 18841 358 24% Fiche 50-324,83/06/07,8306140677
- 8306290402 Responds to IE Bulletin 83-03, "Check Valve Failures in Raw Water Cooling Sys of Diesel Generators," per 830310 ltr TECHNO check valves used at facilities Valve arrangement drawings encl HOME.P W Carolina Power & Light Co 83/06/08 O'REILLY, J P Region 2, Office of Director 6pp 17053 127 24X Fiche 50-324.83/06/08.8308290402
- 8305110464 IE Info Notice 83-36. "Impact of Security Practices on Safe Operations " Sv. list enc! JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/07 Consolidated Edison Co. of New York, Inc. 119pp 18830 280 24X Fiche 80-000.83/06/07.8305110464.
- B305110470 IE Info Notice B3-38, "Defective Heat Sink Adhesive & Seismically Induced Chatter in Relays Mathin Printed Circuit Cards" "Syc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post B30103) B2/06/13 Consolidated Edison Co. of New York, Inc. 1889 18920 225 24X Fiche 50-000,83/06/13,8388110470
- 8306090010 IE Info Natice 83-37. "Transformer Failure Resulting From Degraded Internal Connection Cables" Sv: list encl JORDAN, E. D. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co. of New York, Inc. 243pp 18921 001 24X Fiche 50-000,83/06/13.8306090010
- B306290524 Approves issuance of BALP rept Notes improvement in safety-related activities, emergency preparedness & security & safeguards Weaknesses in GA program will be monstored O'REILLY, J P Region 2, Office of Director 83/06/14 UTLEY, E E Carolina Power & Light Co 5pp 19049 282 24X Fiche 50-000, 83/06/14, 8306290524
- ---8306290531 Forwards SALP Repts 50-325/83-09, 50-324/83-09, 50-261/83-07, 50-400/83-10 & 50-401/83-10 for Jan 1782 Jan 1783 Evaluation will be discussed in Raloiqio, NC on 830510 LEMIS.R C Division of Project & Resident Programs 83/05/03 UTLEY.E C Carolina Power & Light Cn 2pp 19049 287 24% Fischa 50-000.83706/14.8306270524
- --8306270537 SALP rept for Jan 1982 Jan 1983 # Region 2: Office of Director 83/05/03, 64pp, 19049 287 Fiche 50-000.83/06/14.8306270524
- --8306290553 Responds to 810503 BALP rept for Jan 1982 Jan 1983 Reduced NRC attention may be appropriate for Category 1 re fire protection NRC attention should be maintained at normal levels for emergency preparadness

 UTLEY, F.C. Carolina Power & Light Co. B3/05/20 D'REILLY, J. P. Region 2, Office of Director, 16pp 19049 354 24X

 Fiche 50-000.83/06/14.8306290524
- --8306270555 Forwards replacement Page 2 to Attachment 2 of 830520 ltr which commented on SALP rept EURY.L. W Carelina Power & Light Co 83/05/27 G'REILLY, J, P Region 2, Office of Director 2pp 17050 007 24X Fiche 50-000,83/06/14,8306270524
- B305110475 IE Info Notice 83 40, "Need to Environmentally Qualify
 Epoxy Grouts & Sealers" Svc list encl
 JORDAN,E L Division of Emergency Preparedness & Engineering
 Response (Pust 830103) B3706/22 Consolidated Edison Co of New
 York, Inc. 115pp 19021 177 SAX Fichs 50-000,83/06/22,8305110475
- 8305110477 IE Info Notice 83-41, "Actuation of Fire Buppression Bys Causing Inoperability of Safety-Related Equipment " Bvc list enc! JORDAN, C. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/22 Consolidated Edison Co. of New York, Inc. 120pp 1897 007 24X Ficho 50-000.83/06/22.030810477.
- 8305110479 IE Info Notice 83-42, "Reactor Mode Switch Molfunctions " Syc list entl JORDAN, E L Division of Lawrency Preparedness & Engineering Response (Post 830103) 83706/23 Consulidated Edison Co of New York, Inc. 114pp 18996 242 24X Fiche 50-000,83706/23,8308)10479.
- 8305110483 IE Info Notice 83-43. "Improper Settings of Intermediate Range (1R) High Flux Trip Setpoints " Svc list encl, JORDAN: C L Division of Emergency Preparadness & Engineering Response (Post 8300103) 83/06/24 Consolidated Edison Co. of New York, Inc 116pp 19046-297 24X Fiche 50-000.83/06/24.8305110483.

- 830&280489 Lists commitments to implement add1 monitoring & restrictive limits on unidentified RCS lenkage per NUREG-0313. Rev I. in response to IE Dulletin 83-02 Plans to be submitted to NRC 3 months prior to nest refueling outage HQUELP W Caroline Power & Light Co 62706/24 VASSALLD. D B Operating Reactors Branch 2 2pp 17018 311 24X Fiche 50-325,83706/24.8306280489
- 8304300102 Act receipt of 83050? Its in response to notice of violation & proposed imposition of civil penalities from inspection 820712-14 & 20-22 Corrective actions responsive to problems but initiated only after violations confirmed BEYOUNG.R C Director's Office. Office of Inspection and Enforcement 83/06/28 VILEY.E Carolina Power & Light Co Spp. 19048-207 24% Fiche 50-324,83/06/29.0306300102
- --8306300108 Order imposing civil penalties in amount of \$600,000 for violations identified during insps on 820712-14 to 20-22 DEVOUND, R C Director's Office, Office of Inspection and Enforcement B3/06/28 Carolina Power & Light Co App 19048 210 24X Fiche 50-324.83/06/28.8306300102
- R Periodic operating reports & related correspondence
- 8306140214 Monthly operating repts for May 1983 N/850607 ltr HARRISON, F., DIETZ, C.R. Carolina Power & Light Co. 83/06/07 DEYGUNG, R.C. Director's Office, Office of Inspection and Enforcement 14pp, 18832 272 24X Fichs 50-324,83/06/07, 8306140214
- S Reportable occurrences. LERs & related correspondence
- B306140629 Confirms 830518 onsite enforcement meeting to discuss regulatory issues re isolation of Unit 2 condenser offgas radiation monitors, per 830516 teleon Proposed agenda encl O'REILLY, J.P. Region 2, Office of Director 83/05/16 UTLEY, E.F. Carolina Power & Light Co. Ppp. 18842 087 24X Fiche 50-324,83/05/16,8306140629
- 830&010118 LER 83-01&/O3L-0 on 830425 routine surveillance revealed electrolyte levels of 125-volt dc Div 1 & II battery cells out of allowable level band mark Caused by changes in ambient battery room temps W/830523 ltr PABTVA.M J. DIETZ, C R Carolina Power & Light Co 83/05/23 O'REILLY, J P. Region 2, Office of Director 2pp 18673 358 24X Fiche 50-325,83/05/23,8308010118
- 8306070053 LER 83-023/03L-0 on 830426, loss of offsite power occurred when 230 kV bus tripped Fire reported in 4160/480 transformer between smergency bus E-2 & E-6 Caused by personnel error Trip signal cleaned W/830524 ltr PDULK, R. M. DIETZ, C. R. Carolina Power & Light Co. 83/05/24 D/REILLY, J. P. Region 2, Office of Director. Spp. 18740-063-24X Fiche; 50-325, 83/05/24, 8306070053
- 8306070081 LER 83-019/03L-0 on 830425, standby liquid control sys relief valves i-641-F029A & B lifted at setpoints exceeding Tech Specs Caused by out of tolerance relief valve settings Valves adjusted W/830525 ler PABIVA: M J . DIETZ.C R Carolina Power & Light Co 83/05/25 O'REILU.J P Region 2. Office of Director 3pp 18737 352 24X Fiche 30-325,83/05/25,8306076081
- 8304070342 RO increased Co-40 activity found in two bottom sediment samples collected 830405 & 06 No Co-40 found in surface water samples from intake & discharge canals during Apr 1983 No radiation hazard or exposure to public observed DIETZ-C R Carolina Power & Light Co 62/05/31 O'REILLY, J P Region P. Office of Director 2pp 18/41 294 24X Fiche 80-324,63/05/31.8306070342
- 8304090136 RO on 630426 fire barrier limiting condition for operation in thated for augmented offgas bldg door Mod time frame excessed 7-day specified period fire watches will remain in effect DIETZ.C.R Carolina Power & Light Co 63/06/01 G'REILLY, J.P., Region 2. Diffice of Director. Ip 19//5 296 24X Fichs 50-325.83/06/01,8304090134
- 8306100127 LER 83-018/03L-0 on 830503 & 14 average power range monitor D inoperable due to failed power supply First failure cadeed by defective diede CRI thyrister SCRI & capacitor CI Cause of B30514 Failure undetermined W/B30602 ltr PASTVA, M J, DIETZ, C R Capacitor Power & Light Co 83/06/02 D'REILLY, J P. Region 2, Office of Director 3pp 18802 011 24X Fiche 50-325,83/06/02,8306100127
- 8306:30455 Forwards NRR comments on draft AO rept to Congress for First Quarter 1983 DENTON.H R Office of Nuclear Reactor Regulation, Director 83/06/07, PELTREBIC J Director's Office 3pp 18830 176 24X Fiche 80-000.83/06/07.8306130455

- 8306270098 RO on 830504-05 Two | 117 doors (Je7-115) rendered imperable to facilitate maint work & high differential all pressure across door prevented self-closure, respectively Fire watches in effect
 PIETZ C R Carolina Fower A Light (o. 87/04/09 B'REILLY, J P. Region 2, Defice of Director | h. 19708 139 24X
 Fiche 50-325, 83/06/09, 8306270070
- 8306210174 LER 83-022/03L-0 on 830513, during routine surveillance, fire hose Station 2-A00-58 declared inaperable due to bent hose real Caucod by opening valve w/hose on real Mose replaced H/930510 1t1

 PASTVA.M.J. DIETZ.C R. Carolina Power & Light Co. 83/06/10

 D'REILLY, J.P. Renjon 2 Office of Director 2pp. 16915-107 741

 Fiche 50-325, 83/06/10-83062101/4
- 8306270291 RO on 830513, limiting condition for operation initiated for Fire Door 213 in diesel generator bldg boor encountered high differential air pressure across door preventing self-closure Engineering evaluating pressure problem DIETZ.C R. Carolina Power & Light Co. 83/06/17. 0'RCILLY, J F. Region 2. Office of Director | p. 170'96 184 24% Fiche 50-325, 63/06/17, 6306270291
- 8306300193 RD on 830502, gamma analysis of bottom sediment sample detected excessive Co-60 activity Sampling Frequency increased from semiannually to monthly Sample represents seventh monthly sample DIETZ, C R Carolina Power & Light Co. 83/06/17 O'REILLY, J P Region 2. Office of Director 2pp. 19122 191 24X Fiche 50-324, 83/06/17, 8306300193
- 8304300203 LER 83-020/03L-0 on (#0024, intermediate range monitor A indicated instrument upscale Caused by moisture accumulation in monitor detector coble undervessel connector Connector replaced W/830423 itr
 PASIVA, M. J. DIETZ. C. R. Caralina Pawer & Light Co. 83/06/23 d'REILLY, J. P. Region 2, Offsite of Director 2pp. 19119 397 248 Fiche 50-325, 03/06/23.8306300203
- 8306300106 EN-83-011A on 830219, notice of violation & proposed imposition of civil penalties will be issued in amount of \$600,000 Action based on fullure to perform lech Spec surveillances on safety syr & components BARBER, 0, AXFLRAD, J Director's Office Office of Inspection and Enforcement B3/06/28 ip 19048 216 24X Fiche to-324,83/06/28.
- V Operator Examinations
- 830614014) Requests approved ref mail re operator exams by 8202P9
 Missing deadline will result in delay in administering exams Applications should be cubmitted at least 60 days grior to first exam scheduled for which 830425
 VERRELLID M Division of Project & Resident Programs
 HOME J F Carolina Power & Light Co. 4pp. 18837-167
 Fiche 50-324,83/02/07,8306140141
- 8306140533 Confirms administration of written & oral requalification exams at facility during whof 830627 Approved ref matt must be furnished by 830425
 O'REILLY, J.P. Rogion 2, Office of Director 83/04/15
 UPLLY, F.E. Carolina Power & Light Co. Typ. 16834 323 24x
 Fiche 50-324, GJ/04/15, 8306140533
- 8306140396 Ack receipt of 830505 ltr informing NRC of steps taken to correct violations noted in 1. Special limining Assessment Repts 50-324/03-04 V-0329/07 04
 VERRELLI, D M Division of Project & Resident Programs 83/05/24
 UTLEY, E E Carolina Power & Light Co. 1p. 18838 007 24X
 Fichs 50-324,83/05/24,8306140776
- --8306140404 Responds to NRC 830207 ltm re violations noted in 16 Special Training Assessment Ropts 50-324/83 04 & 50-325/85-04 Corrective actions orientation for new employees accomplished in accordance w/TI-301 DIETZ.C R Carelina Power & Light Co. 83/05/05 0'REILLY, J P Region 2, Office of Director 3pp 18038 004 24X Fiche 50-324, 83/05/24, 8306140396
- ~-B306140413 Forwards IE Special Training Assessment Repts 50-324/83-04
 50-325/83-04 on B30110-14 No noncompliance noted Significant
 weaknesses identified
 VERRELLI,D M Division of Project & Rosident Programs 83/02/07
 UTLEY.C E Carolina Power & Light Co. 2pp. 10038-007
 Piche.50-324,8304140376
- --8306140483 IE Special Training Assessment Repts 50-324/83-04 & 50-325/83-04 on 830110-14 No noncompliance noted Major areas inspected licensed & nonlicensed operator training & requalification programs & on-shift/real time training HEML, G.W. HUNGO, J.F. Region 2, Office of Director BEMIS, P. Division of Project & Resident Programs 83/02/03 10pp 18838 009 24X Fiche 50-324,83/05/24,8306140396

- DOCKET 50-J26 UNIV OF CALIFORNIA AT INVINI MES BEACHING

 5 Reportable occurrences TIRs 5 it late 1 correspondence
- 8306210186 RO on B30600, fast transient (antial rod failed to return completely to core following membed triam Caused by air cylinder being dru Light eil added to cylinder Maint checklists under review for postible its MILLER, 6 C. California Univ. of, living B3706/16
 Standardiation & Special Projects Branch ip 10915-253 P4X
 Fiche 50-326.81/06/16.8306/10006
- DOCKET 50 327 SEGUDYAH NUCLEAR PLANT, UNTIL 1
- F. Security, medical, emorgency & fire protection plans
- 8304140535 forwards IE Insp Nepts 50-32/83 06 & 50-328/83-06 on 830328-0401 No noncompliance noted VERRELLIUM Division of Project & disident Programs 83/05/23 PARRIS, II 6 Temps see Vallen Authoratu 2pp 19843 248 Fichs 50 327,83/05/23,8304140535
- --8306140542 IE Insp Repts 50-567/83 06 & 50-328/83-06 on 830328 0401 No noncompliance noted Major aleas inspected emergency preparedness Deficiency in emergency detection & classification program noted MARSTON, R R Region 2, Office of Director JENKING, G R Diristin of Long gency Preparedness & Naterial Safety 6,705/17 9pp 18842-770 /MX Fiche 50-327.03/05/23 8706140535
- 8304070132 Forwards sev to physical security plan Rev withheld (ref 10CFR73 21) MTLLS,L M Tennessee Valley Authority 83705/31 ADENSAM,F Licensing Branch 4 lp 10739 ,277 ,24X Fiche 50 327,83705/21, 8306070132
- B304150091 Releases public version of rovised emergency plan implementing procedures FELTON, J M Division of Rule: and Records 83/04/04 Document Management Branch ip 1887; 125 24/ Fiche 50 32/,03/04/04, 8304150091
- --B306150094 Forwards public version of revised emergency plan implementing procedures, and luding fractedures 80N-IP-2 renotification of unusual event, 60N-IP-3 related to 30N-IP-4 related are emergency KAMMER. B 5 Tennessee Valley Authority 83/04/26 DENION, H R Office of Nuclear Reactor Regulation. Director in 18072, 126 248 Fishe 50 327, 83/04/06.03 (06150091
- --8306150098 Public version of revised emergency plan implementing procedules including Procedules 50N-1P-2 re notification of onusual event, 50N-1P-3 re above & 50N-1P-4 re site area emergency NODLES 4. N. termessee Valley Authority 83/03/10 21pp 16872 127 24X Fiche 50 32/, 63/06/06. 6.306150091
- 3306150510 Discussed steps to be taken to resolve outstanding fire protection issues fech Spec should be amended to include frequency of fire hazards training & drills should be held once per 72 days ivaluation encl ADFNSAM.E G Licensing Branch 4 83/06/06 PARRIS.N G Jennesfer Valley Authoraty Epp 18826 329 24X Fiche 50-527,83/06/06,8306150510
- 1306210010 Forwards "Program Plan for Control Room Design Reviews for all TVA Nuclear Plants." in response to Generic Ltt 82 33 re upgrade of emergency plans.

 KANNER. D S Tounessee Valley Authority 03/06/07 ADENBAN. F. Licensiting Branch 4 3pp 18913 001 24X Fichs 50-000,83/06/07,8306210010
- -8306210016 Procedure B62209 10. "Program Plan for Control Moom Design Reviews for all TVA Nuclear Plants " * Tempessee Valley Authority B3/06/09 200pp 18713 004 24X Fiche 50 000,03/06/09,8306210010
- Operating license stage documents & correspondence
- 304060051 Addl response to FUIA request for three cutopories of documents re PRA of reactor cafety study methodology application program repts & interim reliability evaluation program repts forwards App A documents Search continuing FELTON, J.M. Division of Rules and Records 83/04/07 SHINIY. B.C. Union of Concerned Strength S

- --83060600B5 Provides info on boron precipitation clogging HP1 lines & failure of operator to switch to hot lag injection in order to flush out boron residue from core during recirculation into obtained from PRAs

 DAVIS, B. NRC No Detailed Affiliation Given 83/02/24

 THADANIA NRC No Detailed Affiliation Given Spp 18752 206
 24X Fiche 50-000.83/04/07,8306060051
- B3060B020B Advises that partial response to SER open items re environ qualification of safety-related electrical equipment will be submitted by 830701 & remaining info by 830729 MILEST MILEST
- B306080212 Requests meeting to discuss integrated mod schedule for Unit 2, mod deferrals proposed & justifications provided Scheduled outages, coupled w/normal forced outage rate, could result in lack of sufficient operating reserves HILLS.L M Tennessee Valley Authority B3/06/02 ADENBAM, E Licensing Branch 4 36pp 18771 216 24X Fiche 50-327,83/06/02,8306080212
- 8306210027 Forwards Rev 7 to "Sequoyah Nuclear Plant Offsite Dose Calculation Manual" MILLS.L M Tennessee Valley Authority 83/06/15 ADENSAM.E Licensing Branch 4 ip 189/11 P41 P4X Fiche 50-327, 83/06/15, 8306210027
- --8306210032 Rev 7 to "Bequoyah Nuclear Plant Defeite Dose Calculation Manual" " * Tennessee Valley Authority 83/03/23 81pp 18911 262 24x Fiche 80-327,83/06/15,8306210027
- 8306210115 Application for amend to Licenses DPR-77 & DPR-79, changing Tech Spec 4 8 1 1 2 d 11 re surveillance for dissel generator Class III fee for Unit 1 & Class I fee for Unit 2 will be forwarded MILLS.L M Tennessee Valley Authority 83/06/15 ADENSAM.E Licensing Branch 4 2pp 18914 102 24X Ficher50-327.83/06/15, 8306210115
- --8306210117 Proposed changes to Tech Bpet 4 8 1 1 2 d.11 re surveillance for dissel generator * Tennessee Valley Authority 83/06/15 4pp 18914 104 24X Fiche 50-327,83/06/15.8306210115
- 8305210180 Agrees w/NRC 830520 fee determination Fee will be submitted by wire transfer MILLS.L M Tennessee Valley Authority 83/06/15 MILLER.W D License Fee Management Branch ip 18718 256 24X Fiche 50-327,83/06/15.8304210180
- B306280178 Forwards 830615 change request for NPDES Permit TN0026450 re 60-day extension of submittal of thermal pluma rept required by Part III E MILLGL M Tennessee Valley Authority 83/06/22 ADENBAM.E. Licensing Branch 4 2pp 17015 084 24X Fiche.50-327.83/06/22, 830/280178
- Q Inspection reports, IE Bullotins & correspondence
- BD06140543 Confirms mgt meeting on BD0421 in Chattanoogm. TN to review results of first phase of annual appraisal of regulatory performance, per B00288 telcon
 LEWIS.R.C Division of Project & Resident Programs BD/04/12
 PARRIS.H.G Tennessee Valley Authority 3pp 18834 176 P4X
 Fishe 50-000.03/04/12.8306140543
- 8306140386 Forwards IE Insp Repts 50-327/83-07 & 50-328/83-07 un 830306-0405 No noncompliance noted VERRELLI, D M Region 2, Office of Director 83/05/17. PARRIB, H 0, Tennessee Valley Authority 2np 18932 076 24X Fiche 50-327,83/05/17,8306140386
- ---8306140370 IE Insp Repts 50-327/83-07 & 50-328/83-07 on 830304-0405 No noncompliance noted Major at was inspected operational safety yezification, lE bulletin closeaut & LFR review & independent insp effort FORD.E J , BULLER, S D Region 2, Office of Director, QUICK, D R Division of Project & Resident Programs 83/05/17. App 18802 078 24X Fichs 50-32/,83/05/17,8306140386
- 8306140535 Forwards IE Insp Repts 50-32//83-06 & 50-328/83-06 on 830328-0401 No noncompliance nated VERRELLI.D M Division of Project & Resident Programs 83/05/23, PARRISH 0 Tennessee Valley Authority 2pp. 18843, 268 24X Fiche 50-327, 83/05/23, 8306140505

- --8306140542 IE Insp Repts SO-327/83-06 & 50-328/83-06 on 830320-0401 No nancompliance noted Major areas inspected emergency preparedness Deficiency in emergency detection & classification program noted MARBION, R R. Region 2, Office of Director JENKINS, 9 R. Division of Emergency Preparedness & Materials Safety 83/05/17 9pp 18843-270 24X Fiche 50-327,83/05/23.8306140535
- 8305110458 IE Info Notice 83-32, "Ruptured Am-241 Bources Contained 11)
 Well Logging Device " Bvc list encl
 TAYLOR, J H Division of Safeguards & Inspection Programs (Post
 830(03), 83/05/26 Consolidated Edison Co of New York, Inc
 125pp 18831 043 24X Fiche 50-000, 83/05/26, 8305110458
- 8305110460 IE Info Notice 83-34, "Event Notification Info Horisheet" Buc 11st encl JORDAN, E. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison to of New York, Int. 115pp 18732-085 24X Fiche 50-000, 83/05/26, 8305110460
- 8306140137 Ack receipt of 830511 ltr informing NRC of steps taken to correct violations moted in IE Insp Repts 50-327/83-05 & 50-328/83-05 LEWIG:R C Division of Project & Resident Programs 83/05/26 PARRIS:H. 0 Tennessee Valley Authority ip 18837 115 24% Fithe 50-327/83/05/26.8306140137
- --B306440142 Responds to NRC 830414 ltr re violations noted in IE Insp Repts 50-327/83-05 & 50-328/83-05 Corrective actions training eletings held w/each operations shift group stressing importance of proper sys alignment MILLS: L M Tennesses Valley Authority 83/05/11 D'REILLY, J P Region 2, Office of Director 4pp 18839 116 24X Fichs 50-327,83/05/24,8306140137.
- --8306440143 Forwards IE Insp Repts 50-327/83-05 & 50-328/83-05 on 830206-0305 & notice of violation LEMIS.R C Division of Project & Resident Programs 83/04/14 PARRIS.H G Tennessee Valley Authority 2pp 18639.120 24x Fichs 50-327,83/05/26,8306140137.
- ~-8306140149 Notice of violation from insp on 830206-0305 * Region 2, Defice of Director 83/04/14, 2pp 18839 122 24x Fiche 50-327,83/05/26,8306140137
- --8306140162 IE Insp Repts 50-327/83-05 & 50-328/83-05 on 830206-0305 Noncompliance noted during planned release from cask decontamination tank, valve 0-77-573 was open, allowing release of approx 5,300 gallons from monitor tank FORDs. J. BUTLERS D. Region 2. Office of Director QUICK, D. N. Division of Project & Resident Programs 83/04/07 7pp 18839 124 24x Fiche 50-327,83/05/26,8306140137
- 8305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods Withdrawn at BMRs " Svc list encl JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Post 830103), 83/05/31 Consolidated Edison Co. of New York, Inc. 116pp 18732;208 24X Fichs 50-000.83/05/31.8306140461
- 8304290388 Forwards response to 1E Bulletin 83-03, "Check Valve Failures in Raw Mater Cooling Sys of Diesel Generators "ERCH supply & discharge check valves will be disassembled & visually inspected at least once every 24 months. MILLS,L M Tennessee Valley Authority 83/06/07 O'REILLY, J P Region 9. Diffice of Director 2pp 19055-293 24X Fiche 50-327,83/06/07,8306290388
- 8305110464 IE Info Notice 83-36, "Impact of Security Practices on Safo Operations" Syc list encl.

 JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103), 83/06/09 Consolidated Edison Co. of New York, Inc. 117pp 18830 280 24X Fiche 50-000, 83/06/09, 8305110464
- 8305110470 IE Info Notice 83-38, "Defective Heat Sink Adhesive & Seismically Induced Chatter in Relays Within Printed Circuit Cards " Syc list and JORDAN,E.L. Division of Emergency Preparadness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co of New York Inc. 118pp. 18920.225 24X Fiche: 50-000,83/06/13.8305110470.
- 8306090010 IE Info Notice 83-37, "Transformer Failure Resulting From Degraded Internal Commection Cables " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13. Consolidated Edison Co. of New York, Inc 243pp 18921.001. 24X Fiche-50-000,83/06/13,8306090010
- 8304270483 Approves issuance of SALP Repts 50-259/83-04, 50-260/83-04, 50-296/83-04, 50-327/83-04, 50-328/83-04, 50-390/83-07, 50-391/83-06, 50-438/83-06 & 50-439/83-06 for Jul 1981 Dec 1982 No reply required O'REILLY, J.P. Region 2, Biffice of Director. 83/06/17 PARRIS, H G ESCALE, July Authority. 3pp. 24X Fichs: 50-000, 83/06/17, 8306290483.

- --8306270490 Forwards SALP Ropts 50-259/87 04.50-260/83 04. 50-296/83-04.50-327/83-04.50-328/83 04.50-390/83 07. 50-391/83-06.50-438/83-06 & 50-439/83-06 for Jul 1981 - Dr. 1982 LEHIS.R C Division of Project & Resident Programs B3/04/1) PARRIS.H G lennessee Valley Authority 3pp 24x Fiche 50-000.83/06/17.8306290/883
- --8306390503 SALP Repts 50-259/83-04.50 2/0/83-04.50 2/6/83-04. 50-327/83-04.50-328/83-04.50-390/83-07.50-391/83 06. 50-438/83-06 & 50-439/83 06 for Jul 1981 - Dec 1982 * Region 2. Office of Director 89/04/13 92μμ P4X Fiche 50-000.83/06/17.8306290483
- --8306290510 Comments on SALP Repts 50-259/83-04,50-260/83 04, 50-296/83-04,50-327/83-04,50-328/83 04,50-390/83 07, 50-391/83-06,50-438/83-06 & 50-439/83 06 for Jul 1781 Iki 1982 MILLS,L M Tennessee Valley Authority 83/05/10 0'REILLY,J'P Region 2, Office of Director 2pp 24X Fiche 50-259,83/06/17,8306290483
- 8305110475 IE Info Notice 83-40, "Need to Environmentally Qualify Epoxy Grouts & Sealers " Svc list encl JORDAN,E L Division of Energincy Preparedness & Engineering Response (Post 830103) 83706/22 Consolidated Edison Co of New York, Inc 115pp 19021 179 24X Fiche 50-000.83706/22,030516475
- 8305110477 IE Info Notice 83-41, "Actuation of Fire Suppression Sys-Causing Inoperability of Bafety Related Equipment " Svc list encl JURDAN, Et Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/22 Consolidated Edison Co of No. York, Inc. 120pp 18997 007 24X Fiche 50-000,84/06/22,0.0031104/
- 9305110479 IE Info Notice 83-42, "Reactor Mode Switch Mulfunctions" Svc list encl
 JORDAN, EL Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/23 Consolidated Edison Co of New York, Inc. 116pp 18996-242 24X Fiche 50-000,83/06/23,8305]10479
- 8305110483 IE Info Notice 83-43, "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints " Svc list encl JORDAN, EL Division of Languency Preparedness & Engineering Response (Post 830103) 83/06/24 Consolidated Edison Cn of New York, Inc 116pp 19046 297 24X Fiche 50-000, 03/06/24, 830511048)
- R Periodic operating reports & related correspondence
- 8306020197 Monthly operating repts for dar 1983 W/830414 ltr MASON C C . DUPREE, D C . EDDINGS, M Tennessee Valley Authority 83/04/14 27pp 18691 093 24X Fiche 50-327,83/04/14,8306020197
- B306140526 "NPDCS Discharge Monitoring Rept,Feb-Apr 1983 " EL-ASHRY, M Y Tennessee Valley Authority 83/05/28 90pp 18838 126 24% Fiche 50-327,83/05/28,8306140526
- S Reportable occurrences, LERs & related correspondence
- B306010020 LER 83-065/03L-0 on B30502, during performance of Surveillance Instruction 166 21, train A emergency gas treatment sys room cooler declared inoperable Caused by short in solenoid valve coil Coil replaced W/B30524 ltr CARVER, A M., GREEN, A M., HARDING, M.R. Tennessee Valley Authority B3/05/24 U/RCILLY, J.P. Region 2, Office of Director 2pp 18674 068 24X Fiche 50-327,83/05/24,8306010020
- 8304010394 LER 83-057/03L-0 on 830426, subtooling margin monitor declared inoperable due to plont process computer failure Caused by power failure Computer supplied by maint power while inverter repaired W/630024 ltr RGGERS.H R. HARDING.M R. GREEN.H J. Tennessee Valley Authority 83/05/24 0'REILLY.J P. Region 2, Opfice of Director 2pp 18692 235, 24X Fichs 50-327.03/05/24,8306010396
- B304070284 LER 83-067/017-0 on B30518, start bus 18 failed due to phase to-phase fault Tech Spec 3 8 1 1 action statement 'a' entered Diesel generator not operable within 1-h limit Caused by bus sleeve insulation degradation W/830831 ltr LUDH10.W C , HARDING-M R , OREEN.H J Tennessee Valley Authority B3/05/31 0/REILLY,JP Region 2, Office of Director 4pp 18741 162 24X Fichs 50-327.83/05/31.6306070284
- 8306070039 LER 83-066/03L-0 on 830506, while changing out one upper head injection level switch & recalibr others, three or four switches found out of tolerance Probably caused by instrument drift Switches recalibr M/830601 ltr LUDWIO, W C , HARDING M R , GREEN, H J Tennessee Valley Authority 83/06/01. 0/REILLY, J P Region 2, Office of Director 2pp 18739, 338 24X Fiche 50-307, 63/06/01.8206070039

- 8306200167 LER 83-071/03L-0 on 830512.waste gas disposal sys bxygen analyser O-02AN-43-5000 found out of calibr & declared imperable Caused by analyser zero adjustment drift Analyser recalibr & returned to svc M/M30609 ltr
 DUGGIN. G E , MARDING, M R , GRILLN, H J Tennessee Valley Authority 83/06/09 0'REILLY, J P Region 12 Defice of Director 2pp 18903 112 24X Fiche 50-327,83/06/09,0306200167
- 8306200332 LER 83-070/03L-0 on 830512 diesel generator 1A-A declared inoperable when unit tripped on high crankcase pressure due to cooling water leak Caused by oil cooler failure due to normal end of life Cooler teplaced W/830609 1tr LUDWIO.W C, HARDING.M R. ORLEN.H J Tennesse Valley Authority 837060/09 0 (REILLY.J P. Region 2. Office of Director 2pp 18700 199 24X Fiche 50-327.83/06/09.8308200332
- 830.6210.218 LER 83-075/03L-0 on 830516, power usage not indicated on kW meter for hydrogen recombiner Caused by failure of GE Silicon control rectifier. Model 8C.55M. due to normal rnd of component life Meter circuit repaired W/830613 ltr LUDNIG.W C. HARDING.M R., GREEN.H J. Tennessee Valley Authority 837.06/13 0/8ELLY.J P. Region 2. Office of Director 2pp 18919 035 24X Fiche 50~327.83/06/13.6306210218
- 8306270250 LER 83-076/03L-0 on 830530, condensate demineralizer liquid effluent line radiation monitor D-RM-90-225 declared inoperable due to loss of sample flow Caused by normal wear causing pump failure W/B30616 ltr
 ROCER8.H R . IARDING.H R . GREEN.H J Jennessee Valley Authority B3/06/46 0/REILLY.J P. Region 2. Office of Director 2pp 16970 221 24% Fiche 50-327.83/06/16.8306270250
- 8306280192 LER 83-079/01T-0 on 830607.notified by Nanconformance Rept BGNNEDB304 re possibility of block wall failing during tornado Caused by incorrect leading used in original calculations Plocedure revised W/830620 Its ROOERS.H R. HARDING.M R., ORCEN.H J. Tennessee Valley Authority 83/06/20 0/8FILLY.J P. Region R. Office of Director 3pp 19015 077 24X Fiche 50-327.83/06/20.8306280192
- X Onsite Storage of Low Level Waste
- 8306060102 Responds to 830422 ltr re datermination of fees for low level radwaste amend applications fee determination accepteable MILLS.L M Tennessee Valley Authority 83/06/01 MILLER.W D License fee Nanagement Branch 1p 18719 399 24X Fiche 50-000.63/06/01.8304060102
- DOCKET 50-328 SERUDYAH NUCLEAR PLANT, UNIT 2

 F Security, medical, emergency & fire protection plans
- 8306140535 Forwards IE Insp Repts 50-327/83-06 & 90-328/83-06 on 830328-0401 No noncompliance noted VERRELLI,D M Division of Project & Resident Programs 83/05/23 PARRIS,H G. Tennessee Valley Authority 2pp 18843 P&B 24X Fiche 50-327.83/05/23,8306140535
- --8306140942 IE Insp Repts 50-327/83-06 & 50-328/83-06 on 830328-0401 No noncompliance noted Major areas inspected emergency preparedness Deficiency in emergency detection & classification program noted MARETGN.R R Region 2. Defice of Director 83/05/17 9pp. 18843 270 24X Fiche 50-327,83/05/23,8306140535
- B306070132 Forwards rov to physical security plan Rev Withheld (ref 10CFR73 21)
 MILLB, L M Tennessee Valley Authority B3/05/31 ADENSAM, E Licensing Branch 4 ip 18739 227 P4X Fiche 50-327, 83/05/31, 8306070132
- 8394150091 Releases public version of revised emergency plan implementing procedures FELTON, J M Division of Rules and Records 83/04/06 Document Management Branch 1p 18872 125 24X Fiche 50-327,83/04/06,8306150091
- --B306180094 Forwards public version of revised emergency plan implementing procedures including Procedures BGN-IP-2 re notification of unusual event.BGN-IP-3 re alert & SGN-IP-4 re site area emergency KAMMER.D 9 Tennessee Valley Authority. 83/04/25 DENTON.H R Office of Nuclear Reactor Regulation. Director. 1p 188/2 126 24% Fiche 50-327.83/06/06.8306150091
- --8306180098 Public version of revised emergency plan implementing procedures including Procedures SQN-IP-2 re notification of unusual event BGN-IP-3 re alert & SQN-IP-4 re site area emergency NOBLEGILM Tennessee Valley Authority 83/03/10 21pp 18872 127 24% Fiche 50-327, 83/06/06, 8306180091.

- 8306150510 Discusses steps to be taken to resolve outstanding fire protection issues Tech Spec should be amended to include frequency of fire hazards training & drills should be held once per 92 days Evaluation encl ADEMBAM. E 0 Licensing Branch 4 83/06/06 PARRIS. H @ Tennessee Valley Authority 8pe 18866 321 24% Fiche 50-327.83/06/06, 8306150510
- 8304210010 Forwards "Program Plan for Control Room Design Reviews for all TVA Nuclear Plants." in response to Generic Ltr 82-33 re upgrade of emergency plans KAMMER. D S Tennessee Valley Authority 83/06/09 ADENBAM. E Licensing Branch 4 3pp 18913 001 24X Fiche 50-000.83/06/09, 8306210010
- --B306210016 Procedure B62209 10, "Program Plan for Cuntrol Room Design Reviews for all TVA Nuclear Plants" + Tennessee Valley Authority B3/06/09 200pp 18913 004 24X Fiche 50-000, B3/06/09, B306230010
- P Operating license stage documents & correspondence
- B306060051 Add1 response to FDIA request for three categories of documents re PRA of reactor safety study methodology application program repts & interim reliability evaluation program repts Forwards App A documents Search continuing FELTON, J M Division of Rules and Records 83/04/07 SHDLLY, 8 C Union of Concerned Scientists 3pp 18752 001 24X Fishe 50-000, 83/04/07, 8304060051
- ---83040400085 Provides info on horon precipitation clugging HP1 lines & failure of operator to switch to hot leg injection in order to flush out baron residue from care during recirculation Info obtained from PRAs

 BAYER, S. NRC No Detailed Affiliation Given 83/02/24

 THADANIAN NRC NO Detailed Affiliation Given 6pp 18752 206

 24X Fiche 50-000,83/04/07,8306060051
- 9306140299 Advises that action required by 830216 Amend 14 to License DPR-79 & Generic Ltr 83-07 complete based on util negotiation w/DDE re disposal of high level waste or spent nuclear fuel ADENSAM. E Q Licensing Branch 4 93/06/01 PARRIS.H 0 Tennessee Valley Authority 2pp 18844 333 24% Fiche 50-328,83/06/01.8306/40299
- 8304080208 Advises that partial response to SER open items re environ qualification of safety-related electrical equipment will be submitted by 830701 & remaining info by 830729 MILLS, L M Tennessee Valley Authority 83/04/02 ADENBAM, E. Licensing Branch 4 2pp 18771-183 24X Fiche. 50-327, 83/06/02, 8304080208
- 8304080212 Requests meeting to discuss integrated mod schedule for Unit 2.mod deferrals proposed & justifications provided Scheduled outages.coupled whommal forced outage rate.could result in lack of sufficient operating reserves MILLS.L M Tennessee Valley Authority 83/06/02 ADENSAM.E Licensting Branch 4 36pp 18771 214 24X Fiche 50-327,83/06/02.8304080212
- 8306210027 Forwards Rev 7 to "Bequeyah Nuclear Plant Offsite Dose Calculation Manual " MILLS.L. M Tennessee Valley Authority 83/06/15 ADENSAM.E. Licensing Branch 4 ip 18911 261 24X Fichø 50-327.83/06/15. 8306210027
- --8306210032 Rev 7 to "Bequoyah Nuclear Plant Dffsite Dose Calculation Manual."

 * Tennessee Valley Authority, 83/03/23 Bipp 18911-262, 24X Fiche 50-327,83/06/15.8306210027
- 8306210115 Application for amend to Licenses DPR-77 & DPR-79, changing Tech Spec 4 8 1 1 2 d 11 re surveillance for diesel generator Class III fee for Unit 1 & Class I fee for Unit 2 will be forwarded MILLS.L.M Tennessee Valley Authority 83/06/15 ADENSAM, E Licensing Branch 4 2pp 18714 102 24X Fiche.50-327,83/06/15,8306210115
- --8304210117 Proposed changes to Tech Spec 4 8 1,1 2 d 11 re surveillance for dissel generator # Tennessee Valley Authority B3/06/15 4pp 18914 104 R4X Fichs.50-327,63/06/15,8306210115
- 8306210180 Agrees w/NRC 830520 fee determination fee will be submitted by wire transfer MILLS,L.M Tennessee Valley Authority 83/06/15 MILLER,W.O. License Fee Management Branch 1p 18718 256 P4X Fiche 50-327,83/06/15,8306210180

- 8306230272 Application for amend to License DPR-79, proposing changes to license conditions re-post-accident sampling Description of proposed changes justification & significant hazards determination for proposed license conditions encl MILLS, L. M. Tennessee Valley Authority. 83/06/16 ADENSAM. E. Licensing Branch 4, 17pp. 18945-112 24% Fishe 50-328,83/06/16,8306230272
- 8306230444 Application to amend License BPR-79, temporarily changing Tech Bace surveillance requirements for rod drop times (Tech Baces 4, 1, 3, 4, c) & for full-length control rod position limit switches in Table Tech Specs 4, 3, 3, 5 MILLS, L.H. Tennessee Valley Authority 83/06/21 ADENSAM, E Licensing Branch 4, 2pp 18942 100 24x Fiche 50-328, 83/06/21, 8306230444
- --8306230453 Proposed temporary changes to Tech Specs 4 1 3 4 c resouveillance requirements for rod drop time & Tech Specs 4 3 3 5 re full-length control rod position limit switches * Tennessee Valley Authority 83/06/21 4pp 18942 102, 24X Fiche 50-328,83/06/21,8308230444
- 8305280178 Forwards 830515 change request for NPDES Permit TN0026450 re 60-day extension of submittal of thermal plume rept required by Part III E MILES.L M. Tennesser Valley Authority 83/06/22 ADENSAM.E Litersing Branch 4 2pp. 19015-084 24X Fiche 50-327.83/06/22, 8306280178.
- Q Inspection reports: IE Bulletins & correspondence
- 8306140843 Compires Mgt meeting on 830421 in Chattanooga. Th to review results of first phase of annual appraisal of regulatory performance, per 830328 telcon LEMIB. R C Division of Project & Resident Programs 83/04/12 PARRIS, H C. Tennessee Valley Authority. 3pp 18834:176 24X Fiche 50-000,83/04/12,8306140543
- 8306140386 Forwards IE Insp Repts 50-327/83-07 & 50-328/83-07 un 830306-0405 No noncompliance noted VERRELLI,D M Region 2, Office of Director 83/05/17 PARRIS.H O Tennessee Valley Authority 2pp 18832 076. 24% Fiche. 50-327,83/05/17,8306140386
- 830Ai40535 Forwards IE Insp Repts 50-327/83-06 & 50-328/83-06 on B30328-0401.No noncompliance noted. VERRELLI,D M Division of Project & Resident Programs. 83/05/23 PARRIS,H 9. Tennessee Valley Authority 22p 18843 268. 24X Fichs.50-327,83/05/23.8306140535
- --B306140542 IE Insp Repts 50-327/B3-06 & 50-328/B3-06 on B3032B-0401 No moncompliance noted Major areas inspected emergency praparedness, Deficiency in emergency detection & classification program noted MARBIDNAR R. Region 2. Office of Director JENKINS G R. Division of Emergency Preparedness & Haterials Safety B3/05/17 9pp 18843-270. 24X Fiche-50-327, B3/05/23, B306140535
- 8305110458 IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in Well Logging Device" Svc list encl
 TAYLOR.J. M Division of Safeguards & Inspection Programs (Post 830103) 83/05/26, Consolidated Edison Co of New York, Inc
 125pp. 18831 043. 24X Fiche: 50-000, 83/05/26, 8305110458
- 8305110460 IE Info Notice 83-34, "Event Notification Info Horksbeet " Byc list and JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). B3/05/26 Consolidated Edison Co. of New York, Inc. 115pp, 18732-085 24X Fiche 50-000.83/05/26.8305110460
- 830&140137 Ack receipt of 830511 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-327/83-05 & 50-328/83-05.
 LEMIS.R.C. Division of Project & Resident Programs 83/05/26 PARRIS.H O. Tennessee Valley Authority 19 18839-115 24X Fichs: 50-327,83/05/26.8306140137
- --8305140142 Responds to NRC 830414 ltr re violations noted in IE Insp. Repts 50-327/83-05 & 50-328/83-05, Corrective actions training meetings held w/each operations shift group stressing importance of proper syst alignment, MILLS-L M. Tennessee Valley Authority, 83/05/11 0/REILLY, J.P. Region 2, Office of Director App 18839 116, 24X Fiche 50-327, 83/05/26, 8306140137.

- --8306140145 Forwards IE Insp Repts 50-327/83-05 & 50-328/83 0) on 830204-0305 & notice of violation LEMIS.R C Division of Project & Resident Programs 83/04/14 PARRIS.H G Tennessee Valley Authority 2pp 18039 120 241 Fiche 50-327.83/05/24.8306140137
- --8306140149 Notice of Violation From insp on 830206-0205 * Region 2: Office of Director 83/04/14 2pp 180,39 122 340 fiche 50-327:83/05/26,8306140137
- --B306140162 IE Insp Repts 50-327/B3-05 & 50-328/B3-05 on B30296 056 Noncompliance noted during planned release from cask decontamination tank-valve 0-77-573 was open allowing release of approx 5,300 gallons from monitor tank FORD, E.J., BUTLER, S.D. Region 2, Office of Director QUICK, D.R. Division of Project & Resident Programs B3/04/07 7pp 18839 124 24X Fiche 50-327, B3/05/26, B306140137
- 8305110441 IE Info Notice 83-35, "Fuel Novement W/Control Rods Withdrawn at BWRs " Byc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/31 Consolidated Edison Co of Mrs ' York, Inc 1166p 18732 208 24X Fichs 50-000,83/05/31,03051048 .
- 8306290388 Forwards response to 1E Bulletin 83-03, "Check Valve Failures in Raw Water Cooling Sys of Dresel Generators "ERCW supply & discharge check valves will be disassembled & visually inspected at least once every 24 months HILLS, L.M. Tennessee Valley Authority 83/06/07 O'REILLY, J.P. Region 2. Office of Director 2pp 19055 293 24X Fiche 50-327,83/06/07,8306290388
- 8305110464 IE Info Notice 83-36, "Impact of Security Proctices as Sit Operations " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) 83/06/09 Consolidated Edison Co. of Mar
- 8305110470 IE Info Notice 83-38, "Defective Heat Sink Adhesive & Seismically Induced Chatter in Relays Within Printed Circuit Cards" Svc list and JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co of New York, Inc. 1189p 18920 225 24X Fiche 50-000, 63/06/13, 83051699
- 8306090010 IE Info Notice 83-37, "Transformer Failure Resulting Free Degraded Internal Connection Cables " Svc list encl JORDAN E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co of New York Inc 243pp 18921 001 24% Fiche 50-800 83/06/13,830669000
- 8304290483 Approves issuance of SALP Repts 50~259/83-04, 50-260/81 04, 50-296/83-04, 50-327/83-04, 50-328/83-04, 50-390/83-07, 50-391/83-06, 50-438/83-06 & 50-439/83-06 for Jul 1981 Der 1982 No reply required O'REILLY, J.P. Region 2, Office of Director 83/06/17 PARMIS,N.Q Tennessee Valley Authority 3pp 24X Fiche 50-000, 83/06/17, 8306290483
- --8306290490 Forwards SALP Repts 50-259/83-04.50-260/83-04. 50-296/83-04.50-327/83-04.50-328/83-04.50-390/83-07. 50-391/83-06.50-438/83-06 & 50-439/83-06 for Jul 198t - Bec 1982. LEMIS.R C Division of Project & Resident Programs 83/04/13 PARRIS.H O. Tennessee Valley Authority 3pp 24X Fiche.50-000.83/06/17.8306290483
- --8306290803 SALP Repts 50-259/83-04,50-260/83-04,50-296/83-04, 50-327/83-04,50-328/83-04,50-390/83 07,50-391/83-06, 50-438/83-06 & 50-439/83-06 for Jul 1981 - Dec 1982 * Region 2. Office of Director 83/04/13 92pp 24X Fichs 50-000,83/06/17,8306290483
- --8306290510 Comments on SALP Repts 50-259/83-04.50-260/83-04. 50-294/83-04.50-327/83-04.50-328/83-04.50-390/83-07. 50-391/83-06.50-438/83-06 & 50-439/83-06 for Jul 1981 - Pec 1982 MILLS, L. M Tennessee Valley Authority 83/05/10 0'RCILLY, J P Region 2. Office of Director 2pp 24X Fiche 50-259. 83/06/17. 8306290483.
- 8305110475 IE Info Notice 83-40. "Need to Environmentally Gualify
 Epoxy Grauts & Sealers " Syc last encl
 JURDAN,E L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/06/22 Consolidated Edison Co of Nee
 York, Inc. 115pp 19021 179. 24X Fiche 50-000,83/06/22,8305110475
- 8305110477 IE Info Notice 83-41, "Actuation of Fire Suppression Sus Causing Inoperability of Safety-Related Equipment " Svc list encl. JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/22 Consolidated Edison Co. of New York, Inc. 120pp. 18997 007 24X Fiche 50-000,83/06/22,8305110471

- 305110479 IE Info Notice 83-42, "Reactor Mode Switch Malfunctions "
- SVc 13st encl
 Svc 1st encl
 JORDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83706/23 Consolidated Edison Co of New
 York, Inc. 116pp. 18996-242 24X Fiche 50~000,83706/23,8305110479
- 305:10483 IE Info Notice 83-43, "Improper Settings of Intermediate Bange (IR) High Flux Trip Setpoints "Svc list encl JORDAN E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/24 Consolidated Edison Co. of New York, Inc. 116pp 17046-277 24X Fiche 50-000.03/96/24.0305110483
- Periodic operating reports & related correspondence
- 06020197 Monthly operating repts for Mar 1983 W/B30414 lts MASON, C C . DUPREED C . EDDINGS.M Tennessee Valley Abdorboty 83/04/14 27pp 18691 093 24% Fiche 50-327.83/04/14.8306020197
- | 18838 | 126 | 24X | Fiche | 50-327, 83/05/28, 83004140526
- Reportable occurrences, LERs & related correspondence
- Ob010014 Updated LER B3-004/03%-I on 8,010/, during performance of Surveillance Instruction (8I) 51 low boron concentration discovered in refueling water storage tank Cause not stated to leakage paths discovered W/80524 lt. CARVER, A M., GRIERN, H J., HARDING, M R. Tonnessee Valley Authority B3/05/24 0 "RCILLY, J P. Region 2, Office of Director 2pp 18673 264 24X Fiche 50-328,83/05/24,0306010014
- D6010169 LER B3-061/03L-O on B30429, stram generator 2 pressure indicator failed low & declared inoperable Caused by failed Forboro model current-to-current module due to faulty transistors replaced W030922 ltr 4006R9, H R, HARDING-M R, GREIN-H J Tennessee Valley Authority 37/05/24 0 1/8ELLY-J P Region 2 Office of Director 2pp 18673 03/ 24X Fiche 50-328,03/05/24,6306010169
- 14070218 LER 93-04B/O3L-0 on B30504, during routine filling of cold leg 2 accumulator, safety injection pump inadvertently left in, resulting in accumulator being overfilled & overpressurized Caused by personnel error W/B30401 ltr UDW16.W C , MARDING.W R , GRICH.H J Tennessee Valley Authority B3706/01 0/KLILLY.J P. Region 2. Office of Director Ppp 8746 150 24% Fiche 50-328, B3/06/01, B306070218
- MAIO0173 LER 83-072/03L-0 on M30506, while in Mode 1, remote shutdown team generator I pressure indicator declared inoperable due of failing high Caused by loose connection on oscillator onnection repaired & isolator recaliby W/030603 ltr OCERB, H R , MARDING M R , ORLEN, H J Tennessee Valley Authority 13/06/03 D'MCILLY, J P. Region 2, D. Pfster of Director 2pp 8805 324 24% Fiche 50-328, M3/06/03, M304100173
- 6130242 LER B3-069/OSL-0 on 830508,RCB subcooling margin monitor eclared inoperable due to loss of plant process computer aused by breaker operation on power grid sys Computer estarted & monitor returned to sys W/B30603 ltm.

 COCRES, H R , HARDINO,M R , ORLEN,H J Tennesser Valley Authority 3/06/O3 0 MCELLY,J P Region 2, Office of Director 2pp 8826 307 24X Fiche 50-328,83/06/O3,8306130242
- 6210290 LER B3-073/03L-0 on 830517, shield bldg exhaust gaseous ffluent radiation monitor D-RM-90-100 failed to meet urvaillance requirements Caused by weak photomultiplier ube Tube replaced M/930614 ltr
 DCCRB, H R . HARDING, H R . GREEN, H J Tonnesses Valley Authority 3/06/14 D/RCILL(Y, J P Region 2, Office of Director 2pp 8915 125 24X Fiche 50-328, 83/06/14, 0306210290
- 5210090 LER 82-074/03L-0 on 830917.due to failure of plant process amputer.RCS subcooling margin monitor declared inoperable aused by power interruption Computer restarted & monitor sturned to svc W/830415 ltr
 DGERS, H R . HARDING, M R . GRIEN, H J Tennessee Valley Authority 3704/15 0/REILLY, J P. Region 2. Dffice of Director 2pp 3914 166 24% Fiche 50-328,83/06/15,8306210090
- ;210106 LER 83-078/03L-0 on B30523.steam generator liquid effluent ine radiation monitor 2-RM-90-120/121 declared inoperable ;e to loss of sample flow Caused by loose tubing connection monitor flow switch Connection tightened W/B30615 ltr DERB.H R, HARDINO, M R, GREEN.H J Tennessee Valley Authority V06/13, D/RCILLY, J P. Region 2, Office of Director 2pp 1914.114 24X Fiche 50-328,83/06/15,8306210106.

- X Onsite Storage of Low Level Waste
- 8306060102 Responds to 830422 ltr re determination of fees for low level radwaste amend applications Fee determination Augustable
 MILLB.L M Tennessee Valley Authority 83/06/01
 License Fee Management Branch Ip 18719 359 24X
 Fiche 50-000,83/06/01,8306060102
- DOCKET 50-329 MIDLAND PLANT, UNIT 1
- A Annilication/construction stage documents & correspondence
- 830A1A0035 FOLA request, on behalf of FF Kent, for documents on Jul 1985 on the state of th 830A1A0035
- 8306i60031 Clarifies NRC final response to FOIA request for documents re Zack Co &/or work performed by Zack in const of facilities App D Document 5 deleted since document identical to App A Document 135
 FELTON, J M Division of Rules and Records 83/04/14
 PRENDEROART, R Prenderpast, R J ip 18872 356 24X
 Fiche 50-000.83/04/14.8306i60031
- B30AiA0033 Responds to FDIA request for documents re Jul 1982 stop work order issued to util Request withdrawn.per B30AiA telcon between requester & N Toms Case closed.
 FELTON.J M Division of Rules and Records B3/04/14 GARDE.B Ouvernment Accountability Project 1p 18892 333 24% Fiche 50-329.B3/04/14.B30AiA0033
- 830&150220 Forwards M Srinivasan 830121 memo responding to Region III request for NRR position on applicant exceptions to Reg Guide 1 27 re emergency disse) generator exhaust syshangers NRR position on issue underveloped HILGOVE. M N Hearing Branch 2 83/05/13 BERNABELL Government Accountability Project 4pp 18846 314 24X Fiche 50-329, 83/05/13, 8306150220
- 8304030191 Summary of 830208 meeting w/applicant, NUTECH Corp & Structural Mechanics Assoc in Bethesda. MD re seismic & dynamic equipment qualification program Attendence list, meeting agenda & viewgraphs encl HERNAN, R W Licensing Branch 4 83/05/19 Licensing Branch 4 107pp 18734 132 24X Fiche 50-329, 83/05/19, 8304030191
- B304020601 Requests deletion of LL Bishop from TERA Corp independent design & const verification program list ADENBAM,E 0 Licensing Branch 4 B3/05/24 LEVIN.H. TERA Corp. 2pp 18715 056 24% Fiche 50-329, B3/05/24, B306020601
- 830.6020611 Board Notification 83-21C forwards evaluation of Board Notification BN-83-21 re effectiveness of auxiliary feedwater spray potentially significant w/respect to achieving & maintaining natural circulation in BMH reactors NOVAK.T M Assistant Director for Licensing. 83/05/24 Atom Safety and Licensing Soard Panel Spp 18715 047 24% Fichs 50-329.83/05/24.8306020611
- B306070449 Summary of B30322 meeting w/otil & consultants in Betheads, MB re reactor vessel builting weld (WF-70) anomaly (Unresolved Safety Issue A-11) Attendance list encl. HERNAN, R. W. Licensing Branch 4, 487.0525 Licensing Branch 4, 489 18780 355 24% Fiche 50-329, 83/05/25, 8306070449.
- 8306040189 Lists remedial soils work activities authorized for HARRIBON, J J. Region 3, Office of Director 83/05/27, HILLER, B Consumers Power Co 2pp 18728 274, 24X Fiche 50-329, 83/05/27, 8306060189
- --8306050192 Requests work authorization for evoluter pump structure underpinning program & train B evoluter pipe replacement MOUNEY. J A Consumers Power Co 63/05/25. HARRISON, J J Region 3, Office of Director 1p 18728 275 24X Fiche: 50-329, 63/05/27, 8306060189
- 8306070454 Summary of 830511 meeting w/util & BAN in Bethesda.MD re natural circulation cooldown capabilities & reactor vessel head vent installation Attendance list & agenda encl. HERNAN.R N Licensing Branch 4 83/05/31 Licensing Branch 4 8pp 18782 305 24X Fiche 50-329, 83/05/31, 8306070454
- 8306070425 Summary of 830419-21 meetings w/util, Bechtel & NRC Cassload Forecast Panel re const completion schedules Supporting documentation encl HOOD, D. Licensing Branch 4 83/06/01. Licensing Branch 4, 111pp 18782-159, 24X Fiche 50-329, 93/06/01, 8306070425

- 8306070321 Forwards proposed remedial soils work activity lists for June & Jul 1983, per ASLS 830430 order for review, comment & authoritation HODNEY, J. A. Consumers Power Co. 83/06/01 HARRISON, J. J. Region J. Defice of Director. 23pp 18795 127 24X Fishe 50-329, 83/06/01, 830A690394
- 8306i3036B Forwards Rev 2 to Bechtel Field Instruction FIC-5 100.
 "Sicavation Permit Sys." for review Rev increases scope of work to include excavations associated w/underpinning of auxiliary bldg & syc water pump structure
 MILLER, B B Consumers Power Co 83/06/02 HARRISON, J Region 3, Office of Director 1p 18822 164 24x Fiche 50-329,83/06/02,8306i30368,
- --B206130372 Rev 2 to Field Instruction FIC-5 100, "Escavation Permit 8ys " LEUTSCH.R., MARVEY, S., NEUVILLG.C.L. Bethtel Corp. 83/06/01 19pp 18822 165 24X Fishe 50-227,83/06/02,8306130368
- 8306100268 Forwards "Const Completion Program" & Rev | to "Quality Verification Program," per listed submittals COOK.J W Consumers Power Co 83/06/03 KEPPLER, J & Region 3, Office of Director 3pp 18606 259 24% Fishe 50-329,83/06/03.8306100268
- --8306100269 "Const Completion Program "
 * Consumers Power Co 83/06/03 3/pp 18808 282 24% Fichs 50-329.83/06/03.8306100268
- ~-8306100272 Rev 1 to "Quality Verification Program Midland Nuclear Co Generation Plant Units 1 & 2" * Consumers Power Co PRO483-0014A-0L07 Rt 83/09/24 64pp 18806 297 24X Fichs 50-329,83/06/03.8306100268
- 830&13030B Forwards chronology of vendor participation in initial overview of const completion program
 BARANON S W Stone & Webster Engineering Corp B3/06/03
 KEPPLER.J O Region 3, Office of Director 3pp 18823 331 24x
 Fiche 50-329.83/06/03.8306130308
- 8306140377 Forwards revised Table D-1. "Proliminary Stress Level Comparison," showing value of stress concentration factor & higher calculated peak stresses Higher peak stresses do not affect conclusions from 830506 meeting Neeting Summary and TAYLON, J H. Dabdock & Milcor Co. 83/06/07 MINER, S. NRC No Detailed Affeilation Given. 2ps. 18844-001 24x
 Fiche 50-000,83/06/07,8306140377
- 8304140924 Forwards repts & procedures re sys interaction program Documents are to be used in identification phase of graginam CDOW.J W. Consumers Power Co. 83705/07 DENTON.H R. Diffic of Nuclear Reactor Regulation. Director 2pp 18837-018 24X Fiche.50-329.83706/07.8306140524
- --8306140532 Rev 1 to "Program Hanual Spatial Bys Interaction Program/ Beismic Midland Energy Ctr " CARRHEAN, A R Mark C Jones Engineering Consultants, Inc 83/06/06. 114pp 18837 020 24X Fiche 50-329.83/06/07, 8306140524
- --8306140534 Rev 2 to "GA Manual"
 COMAN.X Mark D. Jones Engineering Consultants, Inc. 83/01/12
 32pp 18837 134 24% Fiche: 50-329, 83/06/07, 8306140524
- --8306140539 Rev 2 to "Midland Energy Ctr Spatial Bys Interaction Program/Seismic MOJEC Project Quality Plan " DURAND,R J Hart G Jones Engineering Consultants: Inc 83/06/02 15pp 18837 166 24X Fishe 50-329,83/06/07,8306140524
- --8306140540 Rev 2 to 8301-PIP-1-0. "Procedure for Project Interface Control." DVRAND.R.J. Mark 9. Jones Engineering Consultants, Inc. 83/06/01 6pp. 18837 181. 24X Fiche: 50-329,83/06/07.8306140524
- --8306140544 Rev 2 to STD-1-0, "Qualifications of QA Audit Personnel"
 DURAND,R J. Mark G Jones Engineering Consultants, Inc. 83/04/01
 7pp. 18837:187, 24% Fiche 50-329,83/04/07,8306140524.
- --8306140546 Rev 2 to 8301-WTP-1-Q, "Procedure for Documentation of Postviated Interactions,"

 DURAND.R. J. Mark 0 Jones Engineering Consultants, Inc. 83/06/01

 7pp. 18837 194. 24X Fiche 50-329,83/06/07.8306140524
- --8306140548 Rev 2 to B301-WTP-2-0, "Procedure for Training of SSIP/S Walkdown Team Members"

 DURANDR J Hark C. Jones Engineering Consultants; Inc. 83/06/01.

 7pp. 18837:201 24X Fiche.50-329.83/06/07.8306140524.

- ~-8306140552 Rev 2 to 8301-WTP-3-(), "Procedure for Performing Walls", of 851P/5 Targets "
 DURAND: R J Mark 6 Jones Engineering Consultants, two App 18837 208 24X Fiche 50-329, 83/06/07, 8306140524
- --8306140555 Rev 2 to ATP-1-0, "Procedure for Control of Project Correspondence" * Mark G Jones Engineering Consultants, Inc. 83/05/26 10; 18837 214 24X Fiche 50-329, 83/06/07, 8306140524
- ~-8306140557 Rev 3 to ATP-2-G, "Procedure for Distribution & Verifying Implementation of Guality Related Procedures"

 * Mark G Jones Engineering Consultants, Inc. 8,7/06/01 top: 18837 224 24X Fiche 50-329,83/06/07,8306140594
- --8306140560 Rev 1 to ATP-4-0, "Procedure for Providing MOME 0A Program " * Mark 9 Jones Engineering Consultants, Inc. 83/01/20 5;p 18837 230 24X Fiche 50-329,83/06/07.8306140924
- --8306140566 Rev 1 to ATP-5-0, "Procedure for Providing Project Orientation " * Mark G Jones Engineering Consultants, Inc. 83/01/28 5pp 19837 235 24% Fiche 50 329,03/06/07,8306140524
- --8306140573 Rev 2 to AFP-6-0, "Procedure for Performing Internal 0: Audits"

 DURAND, R J Mark 0 James Engineering Conseltants, Inc. 89/65/

 8pp 18837 240 247 Fiche 50-329,03/06/07,8306140524
- --8306140579 Rev 2 to ATP-7-0, "Procedure for Training NOJEC Audit 1; i Members " DURANDAR J Mark 9 Jones Engineering Consultants, Inc. 81/09/0; 5pp 18837 248 24X Fiche 50-329,83/06/07,8306140524
- --0306140507 Rev 2 to ATP-0-0, "Procedure for Control of Computer Programs " DURAND, R J Mark 0 Jones Engineering Consultants, Inc 03/08/01 6pp 18837 253 24X Fiche 50-329.83/06/07.8306140524
- --8306140992 Rev 1 to ATP-9-8, "10CFR21-Procedure for Reportina Of Defects & Moncompliance" * Mark Q Jones Engineering Consultants, Inc 83/05/26 7ep 18837 289 24X Fiche 50-329,83/06/07,8306140524
- ~~8306140597 Rev 1 to ATP-10-Q, "Procedure for Document Control"

 DURAND, R J Mark 6 Jones Engineering Consultants, Inc 83/08/61

 App 18837 286 24X Fiche 50-329,83/06/07,8306140524
- --8306140605 Rev I to ATP-11-0, "Procedure for Identification, Documentation & Corrective Action for Nonconformances" DURAND:R J Mark G Jones Engineering Consultants, Inc 7pp 18837-274 24X Fiche 50-319,83/06/07,8306140524
- 8306160235 Requests authorization to perform listed remedial soils soils on const of new ring beam
 MODNEY, J.A. Consumers Power Co. 83/06/08 HARRISON, J.J. Region 3
 Office of Director 1p 18861 235 24% Fiche 50-329,83/06/08
 8306160235
- B306170477 Summary of B30413 meeting w/util & TERA Corp in Dethesda. No re independent design & const verification program Items discussed included protocol for reporting & communications & TERA team organization H000.0 Licensing Branch 4 B3/06/09 Licensing Branch 4, 49, 18894 325 24X Fiche 50-329, 83/06/09, B306170477
- 8306270242 Requests authorization to install svc water pump structure dewatering wells to elevation 570 ft Evaluation of continuous sampling of borings encl Withree oversize drawings Aperbure cares are available in PDR MODNEY, J A Consumers Power Co 93/06/10 HARRISON, J J Region 3 Office of Director 38pp 18970 150 24X Fiche 50-329,83/06/10. 8306270242
- 830.6230.250 Requests authorization to beam work on installation of dewatering discharge sys. including headers, tank, pumps & slectrical (Activity 207050635)
 MODNEY, J.A. Cansumers fower Co. 83706/13 HARRISON, J.J. Region 3, Office of Director. 1p. 18745-227 24X Fiche 50-329,83706/13-8306230250.
- 8306230121 Forwards Rev O to const implementation overview organization chart dtd 830601.

 BARANOW, S W Stone & Webster, Inc. 83/06/15 KCPPLER, J @ Region 3, Office of Director 5pp 18947 049 24X Fiche 50-329,83/06/15.

 8306230121.

- 8306270309 forwards project GA plan & GC instruction, developed to implement const implementation overview of const completion program for review & comment BARANOM, S W Stone & Webster, Inc. 83/06/16 KEPPLER, J G Region 3, Office of Director Topp 18995 dPa 24X Fiche 50-329,83/06/16, 83062/0709
- B306270262 Forwards mgt review committee const implementation overview observations of 830601 meeting re quality verification program Quality verification program Conditionally approved DARAHOW, S.W. Stone & Webster, Inc. 63/06/17 KEPPIER.J.G. Region 3. 0ffice of Director Spp. 18970-191 24% Fiche 50-329.83/06/17, 8306270262
- 830A27033A Authorizes listed inmedial soils work activities scheduled for June 1983 HARRISON, J. Region 3, Office of Director 83/06/20 MILLER, D.B. Consumers Power Co. 2pp. 18993 141 24X Fiche 50-329, 83/06/20, 830A270336
- 8306270367 Requests details of remedial soils activities in Section in of Attachment A, scheduled for month of Jul 1983 & identified as critical work Work activities in Section 3 acheduled for month of Jul 1983 reviewed & determined noncritical HARRIBON, J.J. Region 3, Office of Director 83706/21 MILLER, D. B. Consumers Power Co. 3pp. 18993-315 24X Fiche 50-329,83706/21, 232627847
- 8304270438 Summary of 830604 meeting w/d Miller, util counsel, re testimong by Region 111 witnesses in fecilities proceeding LEWIS,8 H Region 3, Office of Director 83/06/21 Region 3, Office of Director ip 18792-066 PAX Fiche 50-327.83/06/21, 8304270438
- B30&280070 Restorates position that all sufety-related equipment needed for safe shutdown must be demonstrated to be functional during & after seismic marpin earthquake Adherence necessary for acceptance of setsmic qualification NGVAK.T M Assistant Director for Littining 83/06/21 (MCK, J W Consumers Power Co Spp. 1704P 316 24X Fiche 50-329, 83/06/21, 830A-20070
- B306270150 Forwards const completion program dtd 830610 for review & approval Response requested by B30701 Quality verification plan/statistical sampling plan review not needed until B30902 Licensee can begin team training on 830620 W/o encl WARNICK,R F Region 3, Office of Director 83/06/23 EISCNIGT,D 6 Division of Licensing TAYLOR,J M Division of Bafeguards & Inspection Programs (Post 830103) Ip 18993 041 24X Fiche 50-329,83/06/23,8306270150
- 8306270339 Authorizes util to proceed w/scheduled romedial soils activities (207050605,207050600 & 207050633) for June 1983 MARRISON, J. Region 3, Office of Director 83706/P3 MILLER, D D Consumers Power Co. 2pp 18973 125 24X Ficho 50-329,83706/23, B306270339
- --8306270349 Requests author) ration to install remaining ejector wells & piezometers, per remedial soils work activities (207050608) & 207050600)

 HOUNEY, J.A. Consumers Power Co. 89/06/10 HARRISON, J. Region 3, Office of Director ip 18993 127 24X Fiche 50-329, 83/06/28.
- B306290493 Discusses noncompliance w/ponetration flued head mutl specs to forwards "Reclassification of Flued Head Fittings at Middland Pinnt Units 1 & 2 "

 DEWLITER B Consumers Power Co B3/06/23 DENTON, H R Office of Nuclear Reactor Regulation, Director 27pp 19049 ODI 24X

 Fiche 50-329,83/06/23,8306290493
- --8306270474 "Reclassification of Flood Head Fittings at Midland Plant Units 1 & 2 " BYRONJ D . EGAN. 0 R Aptech Engineering Services 83/06/30 27pp 19049 029 24x Fiche 50-329.83/06/83.8306270493
- 8306280539 Advisos that review of IERA expanded engineering program plan for independent design & const verification program completed No comments or questions generated MARNICK.R.F. Region 3. Office of Director 83/06/24 NDVAK.T M Assistant Director for Licensing in 17019 374 24% Fiche 50-329.83/06/24.8306280537
- 8306300065 Documents 830622 telron between R Wieland & R Landsman Util intends to install expansion anchors for formwork & concrete mudmat for new borated water storage tank under Activities 31215007 & 32215007 MODNEY, J A Consumers Power Co 83/06/24 HARRISON, J J Region 9, Office of Director 1p 19190 272 P4X Fiche 50-329,83/06/24, 8306300065

- 8306300101 Informs of completion of preliminary review of 830610 submittal re const completion program Initiation of program training activities authorized MARNICK, R. F. Region 3. Office of Director 83/06/27 CDDK, J. W. Consumers Power Co. 2pp. 19048-097 24X Fiche 50-329.83/06/27.8306300101
- ---B306300105 Forwards Rev 1 to "Const Completion Program," incorporating comments & changes suggested by Region III Rev 2 to "Quality Verification Program," included as app COUK. J W Consumers Power Co B3/06/10 KEPLER, J G Region 3, Office of Director 3pp 19048 099 24% Fiche 50-329, B3/06/27, B306300101
- --8306300109 Rev 1 to "Const Completion Program" Viewgraphs encl * Consumers Power Co 83/06/10 38pp 19048 102 24X Fiche 50-329.83/06/27.8306300101
- --8306300112 Rev 2 to "Guality Verification Program"
 * Consumers Power Co 83/06/10 67pp 19048 140 24X
 Ficha 50-329.83/06/27.8306300101
- E NRC Safety Evaluation Report (SER), suppls & correspondence
- 8304020062 Forwards request for add1 info necessary to complete review of seismic mergin review.Vol 1, "Methodology & Criteria." identified in Suppl 2 to SER ADENSAME G Operating Reactors Branch 4 83/05/26 CODK, J W Consumers Power Co 7pp 18701 342 24X Fiche 50-327,83/05/26,8304020062
- 8306030B10 Forwards request for add1 info re SER Confirmatory Issues 15,18 & 19 Issue 19 reclassified as open item ADENBAM,E @ Licensing Branch 4 83/05/31 COOK,J W Consumers Power Co 5pp 18735 062 24X Fiche 50-329,83/05/31.8304030510
- B30&2B00&4 Forwards request for add1 info re seismic margin review Vol VI, "Inprated Water Storage Tank & Foundation," per Suppl 2 to 8ER ADENSAM.E O Liconsing Branch 4 B3/0&/21 CODK.J W Consumer Power Co &pp 19042 310 24X Fiche 50-329,83/0&/21.830&2800&4.
- F Security, medical, emergency & fire protection plans
- 8306090114 Forwards consolidated Regional Assistance Committee comments for five unrated planning elements Comments should be part of initial FEMA findings & determination of effectiveness of offsite emergency planning MCLOUGHLIN, D Federal Emergency Management Agency 83/05/18 DIRCKS, W J Office of the Executive Director for Operations 5pp 18793 324 24X Fiche 50-329,83/05/18.8306090114.
- 8306180344 Releases public version of revised replacement pages to Bay, Baginaw & Midland County emergency preparedness plans FELTON, J M Division of Rules and Records 83/06/06 Document Management Branch 1p 18869 004 24X Fiche 50-329,83/06/06,8306150344
- --8306150346 Forwards public version of revised replacement pages to nuclear accident apps to Bay, Saginaw & Midland County amergancy preparedness plans in response to FEMA 821214 interim findings
 COOK.J W Consumers Power Co B3/03/30 DENTON, H R Office of Nuclear Reactor Regulation, Director 7pp 18369 005 24X Fiche 50-329, 83/06/06, 8306150344
- ---8306180351 Public version of revised replacement pages to nuclear accident apps to Bay.Baginew & Midland County emergency preparedness plans
 * Consumers Pluwer Co 83/03/30 139pp 18869 012 24X
 Fichm 50-329,83/06/06,8306150344,
- G Adjudicatory correspondence
- B306150220 Forwards M Srinivasan B30121 memo responding to Region III request for NRR position on applicant exceptions to Reg Quide 1 27 re emergency diesel generator exhaust sys hangers NRR position on issue undeveloped HTLCOVE. M N Hearing Branch 2 B3/05/13 BERNABEL, L Covernment Accountability Project. App. 18846-314 24X Fiche 80-327,83/05/13,8306150220
- 830&150274 Concurs w/util 830412 ltr identifying portions of AB Savage deposition transcript to be admitted into evidence w/ exception Page 101.Lines 19 · 24.outside scope of contention
 WILCOVE. M Nearing Branch 2 83/05/13 BECHHOEFER, C .
 CDWAN, F. P . HARBOUR, J Atomic Bafety and Licensing Board Panel,
 2pp 18849 174. 24X Fiche 50-329,83/05/13,8306150274.

- 830&020AB9 Memorandum & order granting in part.applicant 830509 revised motion requiring lead intervenors to submit cross-examination plans & establish time limits on cross-examination BECH-MERER.C Atomic Safety and Licensing Board Panel 83/05/31 Consumers Power Co 14pp 18693 166 24X Fiche 50-329,83/05/31, applications
- 8306060315 Advises that M Cioni degosition rescheduled for 830608 in Chicago, IL Svc list onel PROCTOR: D Isham, Lincoln & Deale 83/06/01 KELLEY, F J Hichigan, State of CHERRY, M M Cherry, M M /Cherry, Flynn & Kanter MARSHALL, M M Mershall, M H 2pp 18/29 185 24X Fiche 80-329,83/06/01.8306060315
- 8306080206 Requests info re total number of wells & amount of electricity required to operate wells for dewatering MARSHALL, H H Mapleton Intervenors 83/06/01 Commissioners pp. 18771.232 24X Fiche 50-327.83/06/01.8306080206
- 8304130420 Notice of scheduling of evidentiary hearings on GA/GC for 830627-0701 & if necessary for 830725-27. in Hidland, MI BECHHOEFER.C. Atomic Safety and Licensing Board Panel 83/06/09 lp 18821-230 24X Fiche 50-329, 83/06/09, 8306130420
- 8306;40660 Farwards NRC 8203:7 ltr.transmitting IE Insp Rept 50-4[0/8]-[3 & notice of violation.psr 830608 evidentiary hearing commitment HRIGHT.N A Hearing Branch & 83/06/09 BERNABEI, L Government Accountability Project Ip 18833 284 24X Fiche 50-329,83/06/09, 8306;40660
- 8305140727 Responds to 830501 ltr ASLB. in 830428 ruling, denied 830422 request for production of documents on dowstering issue since discovery ended MRIGHT.N A Hearing Branch 2 63/05/09 MARSHALL.H H Mayleton Intervenue. Ip 1884: 009 24X Fiche 50-329.83/05/09.8306140727
- 8305200306 Advises that AT Howard deposition scheduled for 830544-16 being continued Svc list encl. Related correspondence PROCTOR, 8, D isham. Lincoln & Beale. 83/06/13 KELLEY, F J Hichigan, State of KELLEY, F J Cherry, M M /Cherry, Flynn & Kanter Marshall, W H Marshall, W H 2pp 18700 168 24X Fichs: 80-327, 83/06/13, 8306200306
- 8306220006 Advises that L Hallberg deposition originally scheduled for 830621, continued. New date will be announced 8vc list encl Related correspondence PROCTOR. 8 I Isham, Lincoln & Beale 83/06/16 BECHHOFFER, C Atomic Safety and Licensing Board Panel RELLEY, F J Michigan. State of 2pp. 18927 358 24X Fiche 50-327,83/06/16,8306220006
- 8306220069 Advises of 830623 & 24 depositions of L Clark & T Devine, respectively Svc list encl.Related correspondence. PROCTOR, S D Isham, Lincoln & Beele 83/06/16 KARR, J & Karr & Lyons 2pp 16930 172 24X Ficher 50-329,83/06/16,8306220069
- 8306270154 Forwards corrected copy of 820307 notice of violation package for Niegare Mohawk Power Corp. WRIGHT.N A Hearing Branch 2, 83706722 BERNABE; L. Government Accountability Project 1p 19012-148 24X Fiche 50-329,83706/22,8306270154
- B30629049B Notice of appearance in proceeding Cartificate of Byc encl KARR, J H Government Accountability Project KARR, J H, Karr & Lyon B3/06/27 App 19052 331 24X Fiche 50-329, 83/06/27, 8306270498
- 8306290530 Motion to quash util subposes commanding testimony at proceedings to identify whistleblowers Subposes violate first amend of US Constitution Commission cannot issue subposes in violation of confidentiality promise KARR: J W Government Accountability Project 4 Karr & Lyons 83/06/27 Atomic Safety and Licensing Board Panel. 13pp 19053 001 24% Fiche: 50-329, 83/06/27.8306290530
- ---B306290551 Affidavit of L Clark re representation of whistleblowers If Govt Accountability Project required to make whistleblowers, ultimate damage will be to public interest in full & free flow of info on important issues Certificate of Syc encl CLARA, L. Government Accountability Project B3/06/24. 15pp 19053, 014 24X Fichs 50-329, 83/06/27, 8306290530

M. Antitrust correspondence

B30&030242 Forwards FR notice of finding of no significant antitrust changes & time for filing of requests for resvaluation REGANN H Siting Analysis Branch 83/05/24, COMBS.T Docketing & Services Branch. 2pp 18734 024 24X Fiche; 50-329, B3/05/24, R30A000040

- --B306030246 Notice of finding of no significant antitrust changes & ties for filing of requests for leevaluation REGAN, W.H. Biting Analysis Branch 03/09/24 2pp 18/JA 026 24X Fiche 50-329:83/05/24.8/06/030249
- 8306140345 Forwards FR notice of finding of no significant antitrust changes since CP reviews & of time for filing requests for reevaluation REGAN, W H Site Analysis Branch 83/05/24 CODK, J W Consumers Power Co 2pp 18854
- --830&140350 Notice of finding of no significant antitrust changes since CP review & of time for filing requests for reevaluation REGAN.W H 81te Analysis Branch B3/05/24 12pp 18854 12H 24X Fiche 50-324.83/05/24.8306140345
- 8306140360 Forwards FR notice of finding of no significant antitrost changes since CP review & of time for filing requests for reevaluation
 REGAN, W H Site Analysis Branch 83/05/24 COMBS, T Docketing & Bervices Branch 2pp 18844 349 PAX Fiche 50-324,83/05/24,8306140360
- Q Inspection reports. IE Bulletine & correspondence
- 8305110458 IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in Well Logging Device " Svc list enc! TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/05/24 Consolidated Edison Co of New York, luc 125pp 18831 043 24X Fichs 50-000,83/05/26,8305110458
- 8305110460 IE Info Notice 83-34, "Event Notification Info Horksheet "
 Eve list encl
 JORDAN,E L Division of Emergency Preparadness & Engineering
 Response (Post 830103) 83/05/26 Consolidated Edison Co of New
 York, Inc | 115pp 18732 085 24X Fiche 50-000,83/05/26,8305110460
- 8306070243 Forwards IE Insp. Repts 50-329/83-06 & 50-330/83-06 on 830329-31 & 0401 & notice of violation WARNICK.R F. Region 3. Office of Director 83/05/27 COOK, J W Consumers Power Co. 2pp. 18/95-321 24X Fiche 50-329.83/05/2/.8306090243
- --8304090245 IE Insp Repts 30-329/83-04 & 50-330/83-06 on 830029-31 & O401 Noncompliance noted failure to follow policy procedures re control of purchased metl & svcs 61MON.J A. 8ATHER.A. HARRISON.J J Region 3. Office of Director 83/05/23 App 16775 324 24x Fiche 50-329.83/05/27.830609024J
- 8305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods Withdrawn at BWRs " Svc list enc! JORDAN E L Division of Emergency Preparedness & Engineering Response (Past 830103) 83/05/31 Consolidated Edison Co of New York, Inc 116pp 18732 208 24x Fiche 50-000,83/05/31,8305110461
- 8304000048 Ack receipt of 830513 ltr informing NRC of steps taken to correct violations noted in IF Insp Repts 50-329/83-05 & 50-330/83-05 WARNICKIR, F. Region 3, Office of Director 83/05/31 CORK, J W Consumers Power Co. ip 18719 247 P4X Fichs, 50-329, 03/05/31, 830606048
- --8304040035 Responds to NRC 830304 ltr re violations noted in It Insp. Repts 50-329/83-05 & 50-330/83-05 Corrective actions Bethtel maint form written to cover installed 0 & non-Q mechanical snubbers & 100% initial insp will be performed COOM.J W Consumers Power to 63/05/13 KEPPLER.J 0 Region 3, Office of Director 4pp 18719 248 24X Fiche 50-329,83/05/31,8306060048
- B306210443 Requests Region III inspect adequacy of util program to initially verify & periodically check for continued presence & effectiveness of Boraflex as neutron poison in spent fuel racks
 CROHLW T Uranium Fuel Licensing Branch B3/06/08 HARRIBON, J Region 3, Office of Director 3pp 18735 359 24X
 Fiche 50-329, B3/06/08, B306210443
- 8305110464 IE Info Notice 83-36, "Impact of Security Practices on Safe Operations " 8vc list encl JORDAN, C. L. Division of Emergency Proparodness & Engineering Response (Post 830103) 63706/09 Consolidated Edison Co. of New York, Inc. 119pp 18830, 280 24X Fiche 50-000, 83706/09, 8305110484

- 83051:0470 IE Info Nutice 83-38, 'Defective Heat Sink Adhesive & Seismically Induced Chatter in Relays Within Printed Circuit Cards '' Svc list end JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 84/04/13 Chinollidated Edison Co. of New York. Inc. 118pp. 18990-225 247 Fiche 50-000.83/04/13.8305110470
- 8306090010 IE Info Notice 83-37, "Transformer Failure Resulting From Degraded Internal Connection (ables " 5vc list encl JORDAN E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co of New York Inc 243pp 18921 001 24X Fiche 50-000.83/06/13.8306090010
- 8305110475 IE Info Notice 83-40. "Need to Environmentally Qualify
 Epory Grouts & Sealers " Svc list entl
 JORDAN, E. L. Division of Emergency Proparedness & Engineering
 Response (Post 830103) 83/06/22 Consolidated Edison Co. of New
 York, Inc. 115pp. 19021 179 24X Fithe 50-000,83/06/22,8305110475
- 8305110477 IE Info Notice 83-41, "Actuation of Fire Suppression Sys Causing Inoperability of Safety-Related Equipment " Syr list enci JOSPAN, E. I. Division of Emergency Preparedness & Engineering
 - JORDAN.C L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/27 Consolidated Edison Co of New York, Inc 120pp 18997 007 24X Fiche 50-000,83/04/22,8305110477
- B305110479 IE Info Notice B3-42, "Reactor Mode Switch Malfunctions " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post B30103) 83/06/23 Consolidated Edison Co of New York, Inc. 116pp 18996 242: 24X Fiche 50-000, B3/06/23, B305110479
- 8305110483 IE Info Notice 83-43. "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints "Eve list encl JORDAN,E L Division of Lawryency Preparedness & Engineering Response (Post 830103) 83/04/24 Consolidated Edison Co of New York, Inc 116pp 19046 29/ 24X Fiche 50-000,83/06/24,8305110483
- R Periodic operating reports & related correspondence
- B304030172 Forwards Bechtel, B&W & util nunconformance repts for Apr 1983 CODK, J. W. Consumers Power Co. 83/05/25 DEYDUNG, R. C. Director's Office, Office of Inspection and Enforcement. 73pp. 18/09-096. 24X Fiche 50-329, 83/05/25, 83040301/2
- 8306270067 Forwards "Independent Design & Const Verification Program, Monthly Status Rept No 1.Period Inception Through 830527 "
 LEVIN.N A TERA Corp 83/05/27 KEPPLER, J G Region 3, Office of Director EISENNUT.D G Division of Licensing CODN, J W Consumers Power Co 3pp 17013 017 24% Fich 6 50-329.83/05/27, 830627067
- --8306270069 "Independent Design & Const Verification Program Monthly Status Rept No 1.Period Inception Through 830327 " TULODICSKI, D TERA Corp 03/05/27 45pp 19013 020 24X Fishe 50-329,83/05/27.83082/0067
- S Reportable occurrences. LLRs & related correspondence
- 8304070242 Interim Deficiency Rept 82-06 re B&W steam generator auxiliory feedwater header design change Internal headers stabilized Mod will be completed upon receipt of thermal sleeves Next rept by 830801 CODK, J W Consumers Fower Co 83/05/31 KEPPLER, J G Region 3, Office of Director 2pp 18/44 244 24X Fiche 50-329,83/05/31,8306070242
- 8306130281 Interim deficiency rept re underrated terminal strips & use of terminal blocks w/o proper environ qualification in Limitorque valve operators Bechtel has requested addl info from Limitorque re qualifying terminal block types COOK.J W Consumers Power Co 83/06/07 KEPPLER.J © Region 3, Office of Director 12pp 18824 128 24X Fiche 50-329,82/06/07,8306130881
- 8306170448 Board Notification 83-79 forwards Zack Rept on welder record discrepancies Rept documents Zack investigation & subsequent decision that item does not constitue IOCFR21 deficiency W/o encl NOVAK/TM Assistant Director for Licensing 83/06/09 Atomic Safety and Licensing Board Panel 2pp 18906 361 24X Fiche, 30-329, 83/06/09/8306170448
- 8306210302 Interim deficiency rept re adequacy of shear reinforcements at major containment penetrations As-designed & as-built containment satisfactory Revs to FSAR initiated final or interim rept expected by 631031 COOK, J W Consumers Power Co 83/06/13 KEPPLER, J G Region 3, Office of Director 2pp 18914 015 24X Fiche 50-324, 83/06/13, 8306510302

- 830.6220007 Part 21 rept re adequacy of fittings supplied by Tube-Line Corp through Capitol Pipe & Steel Products Co for use on new auxiliary feedwater headers of steem generators Flanges not heat-treated as required by mail specs
 TAYLOR. J H Babcock & Willox Co 83/06/17 DEYOUNG. R C
 Director's Office Office of Inspection and Enforcement App 18927 354 24% Fiche 50-000, 83/06/17, 83068200007
- 8306270181 PNO-III-83-051 on 830621.util authorized to proceed U/installation of electrical penetration area temporary support beams & excavation under auxiliary bldg Workers laid off 830617 & 18 recalled LANDBMAN.R., HARRISON.J. Region 3, Office of Director 83/06/21 tp 18791 344 24X Fiche 50-329.83/06/21.8306270181
- T Hearing transcripts on non-antitrust matters
- 8304070073 Transcript of 830601 evidentiary hearing in Midland. MI Pp 16.367-16.552 * Atomic Safety and Licensing Board Panel 83/06/01 188pp 18740 105 24x Fiche 50-329.83/06/01.8306070073
- 8306070180 Transcript of 830602 evidentiary hearing in Midland, M1 Pp 15,533-16,765 * Atomic Safety and Licensing Board Panel 83/06/02 205pp 18737 128 24X Fiche 50-329,83/06/02,8306070180
- 8306070187 Transcript of 830603 hearing in Midland, MI Pp 16, 766-16, 967 4 Atomic Bafety and Licensing Board Panel 83/06/03 205pp 18738 001 24% Fichs 50-329, 83/06/03, 8306070187
- 8304070162 Transcript of 830604 evidentiary hearing in Midland.MI Pp 16,768-17.104 Supporting documentation encl * Atomic Safety and Licensing Board Panel 83/06/04 210pp 18736 001 24X Fiche 50-329,83/06/04.8306070162
- B306100063 Transcript of B30606 evidentiary hearing in Midland.MI Pp 17.105-17.195 * Atomic Safety and Licensing Board Panel B3/06/06 B9pp 18802 338 24X Fiche 50-329.B3/06/06.B306100063
- 8304130215 Transcript of 830607 evidentiary hearing in Midland, MJ, Pp 17.196-17.412 * Atomic Safety and Licensing Doard Panel 83/06/07 213pp 18827 011 24X Ficho 50-329, 83/06/07.8306130215
- B306140103 Transcript of B3060B evidentiary hearing in Midland.MI, Pp 17.413-17.637

 * Atomic Bafety and Licensing Board Panel B3/06/0B, 13ipp. 18837 286 24X Fiche 50-329,83/06/08.8306140103
- 830.6150.142 Transcript of 830.609 evidentiary hearing in Midland.MJ Pp 17.630-17.065

 * Atomic Safety and Licensing Board Panel 83/06/09 86pp 18851 220 24X Fiche 50-329.83/06/09.8306150142
- 8306140108 Transcript of 830610 evidentiary hearing in Midlend M1 Pp 17.866-17.977 * Atomic Safety and Licensing Goard Panel 83/06/10 115pp. 18839 171 24X Fiche 50-329.83/06/10.8306140108
- B306200016 Transcript of Commission B30615 brisfing in Washington, BC restatus of GA & soil settlement at facility, Pp 1-64.

 Bupporting documentation encl

 Commissioners B3706/15 76pp 18909 238 24X

 Fiche, 50~329, 83/06/15, 8306200016
- V Operator Examinations
- 830.4270271 Advises that MO Jones Engineering Consultants. Inc (MOJEC) training program, evaluated on 830.608, satisfactory & may be implemented immediately Spatial sys interaction program procedures approved by util & issued by HOJEC.

 BARANOH, S. W. Stone & Webster, Inc 83/06/17, KEPPLER, J G Region 3, Office of Director ip 18790-207 24% Fiche 50~327, 83/06/17, 8306270271
- DOCKET 50-330 MIDLAND PLANT, UNIT 2

 A Application/construction stage documents & correspondence
- 9306160035 FDIA request, on behalf of EE Kent, for documents re Jul 1982 stop work order issued to util GARDE, D Government Accountability Project 83/02/16 Office of Administration ip 18892 334 24X Fiche: 50-327,83/02/16, 8306160035

- 8306160031 Clarifies NRC final response to FOIA request for documents re Zack Co &/or work performed by Zack in coast of facilities App D Document 5 deleted since document identical to App A Document 135
 FELTON.J M Division of Rules and Records 83/04/14
 PRENDEROAST.R Prendergast, R J 1p 18072 396 24X
 Fichs 50-000.83/04/14.8306160031
- 8306i60033 Responds to FDIA request for documents re Jul 1982 stop work order issued to util Request withdrawn, per 8304i4 telcon between requester & N Toms Caste closed FELTON, J M Division of Rujes and Records 83/04/i4 GARDE, D Government Accountability Project. Ip 18892 333 24X Fichs 80-329,83/04/i4,8306i60033
- 8306150220 Forwards M Srinivasan 830121 memo responding to Region III request for NRR position on applicant exceptions to Reg Ouide 1 29 re emergency diesel generator exhaust sys hangers NRR position on issue undeveloped.

 HILCOVE, M N Hearing Branch 2 83/05/13 BERNABELL Covernment Accountability Project 4pp 18846-314 24X Fiche 50-329, 83/05/13, 8306180220
- 8304030191 Summary of B30208 meeting w/applicant.NUTECH Corp & Structural Mechanics Assoc in Bethesda.MD re seismic & dynamic equipment qualification program Attendance list, meeting agenda & viewgraphs enc!
 HERNAN,R W Licensing Branch 4 83/05/19 Licensing Branch 4 107pp 18734-132 24% Fichs 50-329,83/05/19.8306030191
- 8304020401 Requests deletion of LL Bishop from TERA Corp independent design & const verification program list ABENBAN-E 0 Licensing Branch 4 83/05/24 LEVIN-H TERA Corp 2pp 18715 056 24% Fiche 50-329, 83/05/24, 8304020401
- 8304020611 Board Notification 83-21C forwards evaluation of Board Notification EN-83-21 re effectiveness of auxiliary feedwater spray potentially significant w/respect to achieving & maintaining natural circulation in B&W reactors NDVAK, T.M Assistant Director for Licensing 83/05/24 Atomic Bafety and Licensing Board Panel 3pp 18715 047 24X Fiche, 50-329, 83/05/24, 8306020611
- 830&070449 Summary of 830322 meeting w/util & consultants in Bethenda, MD re reactor vessel beltline weld (WF-70) anomaly (Unresolved Safety Issue A-ii) Attendants list enc) HERNAN, R W Licensing Branch 4 83/05/25 Licensing Branch 4 4pp 18780 355 24X Fiche 50-329,83/05/25,8306070449
- 8304060189 Lists remedial soils work activities authorized for June 1983 HARRISON J J. Region 3, Office of Director 83/05/27 MILLER, D B Consumers Power Co 2pp 18728 274 24X Fiche 50-327,83/05/27, 8308060189
- --8306060192 Requests work authorization for svc water pump structure underpinning program % train B svc water pipe replacement MODNEY, J A Consumers Power Co 83/05/25 HARRISON, J J Region 3, Office of Director ip 18728 275 24X Fiche 50-329,83/05/27,8306060189
- 8306070454 Summary of 830511 meeting w/util & B&W in Bethesda,MD re natural circulation cooldown capabilities & reactor vessel head vent installation Attendance list & agenda encl HERNAN,R W Licensing Branch 4 B3/05/31 Licensing Branch 4 Bpg 18782-305, 24X Fiche 50-329,83/05/31,8306070454
- 8306070425 Summary of 830419-21 meetings w/util. Bechtel & NRC Caseload Forecast Panel re const completion schedules. Supporting documentation encl HOOD, D. Licensing Branch 4 93/06/01 Licensing Branch 4, 111pp 18782:159 24X Fiche 50-329,83/06/01,8306070425
- B306130368 Forwards Rev 2 to Bechtel Field Instruction FIC-5 100. "Excavation Permit Sys." for review Rev increases scope of work to include excavations associated w/underpinning of auxiliary bldg & svc water pump structure, MILLER, D.B. Consumers Power Co. 83/06/02 HARRISON, J. J. Region 3, Office of Director is 18922-164 24% Ficher 50-329,83/06/02,8306130368
- 8305100268 Forwards "Const Completion Program" & Rev I to "Quality Verification Program," per listed submittals COOK-J W. Consumers Power Co. 83/06/03 KEPPLER, J. Q. Region 3, Office of Director 3pp 18806-259 24X Fiche. 50-329,83/06/03,8306100268

- --8306100267 "Const Completion Program" * Consumers Power Co 83/06/03 3/pp 18806 242 24X Fiche 50-329,83/06/03,8306100268
- --83061002/2 Rev 1 to "Guality Verification Program Midland Nuclear Co Generation Plant Units 1 & P " * Consumers Power Co PRO483-0014A GLO7 Rt 83/05/24 64pp 18806 297 24X Firne 50-527,83/06/04,8306100268
- 830&130308 Forwards chronology of vendor participation in initia) overview of const completion program BARANDW-S W Stone & Webster Engineering Corp 83/06/03 KEPPLER.J G Region 3, Office of Pirecto; 3pp 18823 331 24% Fiche 50~329.83/06/03.8306130308
- 8306140377 Forwards revised Table D-1, "Preliminary Stress Level Comparison," showing value of stress concentration factor & higher calculated peak stresses Higher peak stresses do not affect conclusions from 830306 meeting Neeting summary enci TAYLOR. J H Babcock & Wilcox Co 83/06/07 MINER. S NRC No Detailed Affiliation Given 2pp 18044 001 24X Fiche 50-000.83/06/07.8306140377
- 8306140524 Forwards repts & procedures re sys interaction program Documents are to be used in identification phase of program CCOK.J W Consumers Power Co 83/06/07 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 18837 OIB 24X Fiche 50-329.83/06/07.8306140524
- --8306140532 Rev 1 to "Program Manual Spatial Sys Interaction Program/ Salamic Midland Energy Ctr " CARRIBAN, A R Mark & Jones Engineering Consultants, Inc 83/06/06 114pp 18837 020 24X Fiche 50-329,83/06/07, 8306140524
- --8306140534 Rev 2 to "GA Manual" COMAN.K Mark 6 Jones Engineering Consultants, Inc 83/01/12 32pp 18837 134 24% Fich: 50-329,83/06/07,8306140524
- --8306140539 Rev 2 to "Midland Energy Ctr Spatial Sys Interaction Program/Seismic MOVEC Project Guality Plan " DURAND.R J. Mark G Jones Engineering Consultants. Inc 83/06/06 15pp 18837 166 24X Fiche 50-329,83/06/07,8306140524
- --8306440540 Rev 2 to 8301-PIP-1-Q, "Procedure for Project Interface Control" DURAND,R J Mark 0 Jones Engineering Consultants, Inc 63/06/0 6pp 18837 191 24X Fichs 50-329,83/06/07,8306140524
- --8306140544 Rev 2 to 6TD-1-G. "Qualifications of QA Audit Personnel" DURAND,R J Mark G Jones Engineering Consultants, Inc 83/04/01 7pp 18837 187 24% Fiche 50-327,83/06/07,8306140524
- ~-8306140546 Rev 2 to 8301-WYP-1-Q, "Protedure for Documentation of Postulated Interactions " DURAND.R J Mark 0 Janes Engineering Consultants, Inc 83/06/01 7pp 18837 194 24X Fiche 50-327,83/06/07,8306140524
- --8306140548 Rev 2 to 8301-WFP-2-0, "Procedure for Training of SSIP/5 Walkdown Team Members" DURAND, R J Mark 0 Jones Engineering Consultants, Inc 7pp 18837 201 24% Fiche 50-329.83/06/07,8306140524
- --8306140552 Rev 2 to 8301-WTP-3-9, "Procedure for Performing Walkdowns of 881P/B Targets " DURAND:R J Mark & Jones Engineering Consultants, Inc 83/06/01 4pp 18837-208 24X Fichs 50-329,63/06/07.8306140524
- --8306140555 Rev 2 to ATP-1-G, "Procedure for Control of Project Correspondence " * Mark G Jones Engineering Consultants, Inc 83/05/26 10pp 18837 214 24X Fiche 50-329,83/06/07,8306140524
- --8306140557 Rev 3 to ATP-2-8, "Procedure for Distribution & Verifyind Implementation of Quality Related Procedures"

 * Mark 9 Jones Engineering Consultants, Inc 83/06/01 App 18837 224 24X Fiche 50-329,83/06/07,8306140524
- --8306140560 Rev 1 to ATP-4-0, "Procedure for Providing MOJEC GA Program" * Mark Q Jones Engineering Consultants, Inc 83/01/28 5pp 18837:230 24X Fiche 50-329,83/06/07.8306140524
- ~~8306140566 Rev 1 to ATP-5-0, "Procedure for Providing Project Grientation." * Mark 0 James Engineering Consultants, Inc 83/01/28 5pp 18837 235 24X Fiche 50-329:83/06/07.8306140524

- +-83061405/3 Rev 2 to ATP-6-0, "Procedure for Performing Internal QA Audats
 - Audits "DuRAND.R J Mark 9 Jones Engineering Consultants, Inc Bpp 18037 240 24% Fiche 50-329,83/06/07,8306140524
- --8306140579 Rev 2 to ATP-7-0. "Procedure for Training MGJEC Audit Team
 - Members " DURAND.R J Nark G Jones Engineering Consultants, Inc 5pp 16837 248 24% Fiche 50-329,83/04/07,8306140524
- --- 8306140587 Rev 2 to ATP-8-0, "Procedure for Control of Computer
 - Programs "
 DURAND,R J Mark G Jones Engineering Consultants, Inc.
 App. 18837 253 24% Fiche 50-329,83/06/07,8306140524
- --8306140592 Rev 1 to ATP-9-0, "10CFRP1-Procedure for Reporting Of
 - Defects & Noncompliance "

 * Mark G Jones Engineering Consultants, Inc E
 18837 259 24X Fiche 50-329,83/06/07,8306140524
- --8306140597 Rev 1 to ATP-10-0, "Procedure for Document Control"
 DURAND, R J Mark 0 Jones Engineering Consultants, Inc 83/
 8pp 18837 266 24% Fithe 50-329,83/06/07,8306140524 83/06/01
- --8305140605 Rev 1 to ATP-11-G, "Procedure for Identification, Documentation & Corrective Action for Nonconformances " DURANDER J Mark 9 Jones Engineering Consultants Inc 7pp 18837 274 24% Fiche 30-329,83/06/07,8306/07,84 83/06/01
- 8306160235 Requests authorization to perform listed remedial smals work
- MODNEY, J. A. Consumers Power (b. 09/06/08 HARRISON, J. J. Region 3, Office of Director 1p 18061 235 24X Fiche 50-329, 83/06/08, 8306160235
- 8306170477 Summary of B30413 meeting w/util & TERA Corp in Bethesda. HD re independent design & const verification program Items discussed included protocol for reporting & communications & TERA team organization & TERA team organization Branch 4 83/06/07 Licensing Branch 4 4pp 18894 325 24X Fiche 50~329.83/06/09.8306170477

- B305270242 Requests authorization to install svc water pump structure dewatering wells to elevation 570 ft Evaluation of continuous sampling of borings encl W/three eversize drawings Aperture cards are available in PDR MODNEY, J A Consumers Power to B3/06/10 HARRISON, J J Region 3 Office of Director 38pp 18790 150 24X Fichs 50-329,83/06/10, 8304270242
- G306230250 Requests authorization to beam work on installation of dewatering discharge sys.including headers, tank, pumps & electrical (Activity 20705063) MODREY, J.A. Consumers Power to 01/06/13 HARRISON, J. Region Office of Director 1p 18945-227 24X Fichs 50-329,83/06/13. 8304230250
- 8306230121 Forwards Rev O to const implementation overview organization
- Chart and GOGOI

 BARANOW, S W Stone & Webster, Inc. 93/06/15 KEPPLER, J G Region
 3, Office of Director 5pp 18947 049 24X Fiche 50-329,83/06/15,6306236121
- 8308270309 Forwards project QA plan & QC instruction, developed to
- Locarous v rorwards project (A plan & QC instruction, developed to implement const implementation overview of const completion program, for review & comment BARANOM, S W Stone & Webster, Inc. 83/04/16 KEPPLER, J G Region 3, Office of Director 10pp 18995 22. 24X Fiche 50-329,83/04/16.8306270309
- 8306270262 Forwards mgt review committee const implementation overview observations of 630601 meeting re quality verification program Quality verification program conditionally approved BARANDM, S.W. Stone & Websten; Inc. 83/06/17 KEPPLER, J.Q. Region 3, Defice of Director 5pp 18990 191 24X Fiche 50-329,83/06/17,83/070262
- Q304270336 Authorizes listed remedial soils work activities scheduled for June 1983 HARRISON J J Region 3. Office of Director 63/06/20 MILLER, D B Consumers Power Co 2pp 18793 161 24X Fiche 50-327, 63/06/20, 9306270336
- B306270367 Requests details of remedial soils activities in Section i of Attachment A, scheduled for month of Jul 1983 & identified as critical work Work activities in Section 3 scheduled for month of Jul 1983 reviewed & determined noncritical HARRIBON. J. Region 3. Office of Director B3/06/21 MILLER, D B Consumers Power Co. 3pp. 18993-315 24X Fiche 50-329, 83/06/21, B306270367

- 8306270438 Summery of 830606 meeting w/M Miller.util counsel.je testimony by Region III witnesses in facilities proceeding LEWIS.S H Region 3, Office of Director 83/06/21 Region 3, Office of Director ip 18992 066 24% Fiche 50-329,83/06/21, 8304270436
- B306280070 Reiterates position that all safety-related equipment needed for safe shutdown must be demonstrated to be functional during & after seismic margin parthquake Adherence necessary for acceptance of seismic qualification NGVAN, T.M. Assistant Director for Licensing B3706/21 CDGN, J & Consumers Power Co. 5pp. 17042-316 24X Fiche 50-327, 83/06/21, 2304-23047. B30A2B0070
- 8306270150 Forwards const completion program dtd B30610 for review & approval Response requested by 830701 Guality verification plan/statistical sampling plan review not needed until B30902 Licensee can begin team training on 830620 W/o encl. WARNICK, R F Region 3. Office of Director 83/06/23 EISENHUT, D 0 Division of Licensing TAVLOR, J M Division of Safeguards & Inspection Programs (Post 830103) ip 18973 041 24X Fiche 50-329, 63/06/23, 8306270150
- 8306270339 Authorizes util to proceed w/scheduled remedial soils activities (207050605, 207050600 & 207050635) for June 1983 HARRISON, J Region 3, Office of Director 83/06/23 MILLER, D Consumers Pawer Co 2pp 18993 125 24X Fiche 50-329, 83/06/23, 8306270339 MILLER, D B
- --8306270349 Requests authorization to install remaining ejector wells & pierometers.per remedial soils work activities (207050605 & 207050600)
 MODNEY.J A Consumers Power Co 83/06/10 HARRISON.J J Region 3. Office of Director 1p 18493 127 24X Fiche 50-329,83/06/23,83/06/20339
- 8306270493 Discusses noncompliance w/penetration flued head matl specs to forwards "Reclassification of Flued Head Fittings at Midland Plant Units 1 to 2"
 DEWITT, R B Consumers Power Co 83/06/23 DENTON, H R Office of Nuclear Reactor Regulation, Director 27pp 17049 001 24X
 Fiche 50-329,83/06/23,8306270493
- --8306290476 "Reclassification of Flued Head Fittings at Midland Plant Units i & 2 " BYRON.J D . EGAN.G R Aptrch Engineering Services 83/06/30 27p 19049 029 24% Fiche 50-329,83/06/23,8306290493
- 8306280537 Advises that review of TERA expanded engineering program plan for independent design & const verification program completed No comments or questions generated MARNICK, R F Region 3, Office of Director 83/06/24 NOVAK, T M. Assistant Director for Licensing Ip 19019 324, 24X Fiche 50-329.83/06/24.8306280539
- 8306300065 Documents 830622 telcon between R Wieland & R Landsman Util intends to install expansion anchors for formucrk & concrete mudmat for new borated water storage tank under Activities 31215007 & 32215007 MODNEY, J A Consumers Power Co 63/06/24 HARRIBON, J J Reg. Office of Director ip 19120 272 24X Fiche 50-329, 63/06/24
- B306300101 Informs of completion of preliminary review of B30610 submittal re-const completion program Initiation of program training activities authorized WARNICK.R F Region 3. Office of Director B3/06/27 CDDK, J W. Consumers Power Co. Epp. 1904B 097 24X Fiche 50-327,83/06/27.
- --8306300105 Forwards Rev 1 to "Const Completion Program," incorporating comments & changes suggested by Region III Rev 2 to "Quality Verification Program," included as app CODK, J W Consumers Power Co 83/06/10 KEPLER, J 0. Region 3, Office of Director 3pp 19048 099 24X Fiche 50-329,83/06/27, 220430101 8304300101
- --8306300109 Rev 1 to "Const Completion Program." Viewgraphs and * Consumers Power Co 83/06/10 38pp 19048 102 24X Fiche 50-329,83/06/27,8306300101
- ---8306300112 Rev 2 to "Quelity Verification Program" * Consumers Power Co 83/06/10 67pp 19048 140 24x Ficha 50-329,83/06/27,8306300101

E NAC Safety Evaluation Report (SER), suppls & correspondence

- 8306020062 Forwards request for additinfo necessary to complete review of saismic margin review. Vol. 1. "Methodology & Criteria," identified in Suppl 2 to SER ADENSAM.E G. Operating Reactors Branch 4. 83/05/26. COOK.J D. Consumers Power Co. 7pp. 18701-342. 24X Fiche. 50-329, 83/05/26. 8306020062
- 8304030510 Forwards request for add1 info ro SER Confirmatory Issues 15.18 & 19 Issue 17 reclassified as open item ADENSAME 0 Licensing Branch 4, 83/05/31 CODK.J W Consumers Power Co 5pp. 18735 062 24X Fiche 50-329,83/05/31,8306030510
- 8306280064 Forwards request for add1 info re seismic margin review Vol VI. "Borated Water Storage Tank & Foundation:" per Suppl 2 to SER ADENSAM.E. O Licensing Branch 4 83/06/21 COOK.J W Consumers Power Co. 6pp. 19042 310 24% Fiche.50-329,83/06/21.8306280064
- F Security, medical, emergency & fire protection plans
- 8306090114 Forwards consolidated Regional Assistance Committee comments for five unrated planning elements Comments should be part of initial FEMA findings & determination of effectiveness of offsite emergency planning MCLDUGHLIN.D. Federal Emergency Management Agency 83/05/18 DIRKCR.Y J Office of the Executive Director for Operations 5pp 18793 324 24X Fiche 50-329.83/05/18.8306090114
- 8306190344 Releases public version of revised replacement pages to Bay, Baginaw & Hidland County exergency preparedness plans FELTON.J M Division of Rules and Records 83/06/06 Document Management Branch ip 18869 004 24X Fichs 50-329,83/06/06,8306150344
- --8306150346 Forwards public version of revised replacement pages to nuclear accident apps to Bay, Saginaw & Midland County emergency preparedness plans in response to FEMA 821214 interim findings
 COOK, J. W. Consumers Power Co. 83/03/30 DENTON, H.R. Depice of Nuclear Reactor Regulation, Director 7pp 18869 005 224X
 Fiche 50-329,83/06/06.8306150344
- --8306180351 Public version of revised replacement pages to nuclear accident apps to Bay, Saginaw & Midland County emergency preparedness plans & Consumers Power Co 83/03/30 139pp. 18869, 012 24X Fiche 50-329, 83/06/06, 8306150344

Q Adjudicatory correspondence

- 930A150220 Forwards M Srinivasan 830121 memo responding to Region III request for NRR position on applicant exceptions to Reg Quide 1.29 re emergency diesel generator exhaust sys hangers. NRR position on issue undeveloped WILCOVEM.N Mearing Branch 2 83/05/13 BERNAMEI, Covernment Accountability Project. 4pp. 1684A 314. 24X Fiche 50-329,83/05/13,830A150200
- 8306150274 Concurs w/util 830412 ltr identifying portions of AB Savagn deposition transcript to be admitted into evidence w/ exception.Page 101.Lines 19 24.outside scope of contention MILCOVE.M.N. Hearing Branch 2 83/05/13 BECHHDEFER.C. COMAN.F.P. HARBOUR.J. Atomic Safety and Licensing Board Panel 2pp. 18849.174 24X Fiche.50-329.83/05/13.8306150274
- B304020489 Memorandum & order granting in part, applicant 830509 revised motion requiring lead intervenors to submit cross-examination plans & establish time limits on cross-examination BECH-ORFER: C Atomic Sefety and Licensing Board Panel 83/05/31 Consumers Power Co 14pp 18493.146 24X Fiche 50-329.83/05/31, 8304020489
- 8306060315 Advises that M Cioni deposition rescheduled for 830608 in Chicago, IL Svc list encl
 PROCTOR, 8. D Isham, Lincoln & Beale, 83/06/01 KELLEY, F. J.
 Michigan, State of CHERRY, M M Cherry, M M /Cherry, Flynt, &
 Kanter MARSHALL, W H Harshall, W H. 2pp. 18727 185 24X
 Fichs, 50-327, 83/06/01, 8306060315.

mber of wells & amount of 's for dewatering 83/06/01 Commissioners /06/01.8306080206

- 8304130420 Notice of scheduling of evidentiary bearings on 9A/QC for 830427-0701 & if necessary, for 630725, 29, in Midland, NI BECHHOEFER. C. Atomic Safety and Licensing Board Panel 83/06/09 1p 18821 230 24X Firks 90-329, 83/06/09, 8304130420
- B306140660 Furwards NRC B20317 ltr.transmitting IE lnsp Rept 50-410/81-13 & notice of violation.per B3060B evidentiary hearing commitment WRIGHT.N A Hearing Branch : B3/06/69 BERNABCI.L Government Accountability Project 1p 1883 284 24X Fichs 50-329,83/06/09, B306140660
- B306140727 Responds to B30601 ltm ASLB.in B3042B ruling deniad B30462 request for production of decoments on dewatering issue since discovery ended WRIGHT.N A Hearing Branch 2 B3/06/07 MARSHALL,W H Hapleton Interveners ip 18841 009 24% Fiche 50-329.83/06/09.8306140727
- 8306200306 Advises that AT Howard deposition scheduled for 830614-16 being continued SVC list encl Related currespondence PROCTOR, S D Isham, Lincoln & Beale 83/06/13 KELLEY,F J Michigan, State of KELLEY,F J Cherry, M M /Cherry, Flynn & Kanter MARSHALL, H M Anishall, H H 2pp 18900 168 24X Fiche 50~329,83/06/13,8306200306
- 8306220006 Advises that L Hallberg deposition, originally scheduled for B30621; continued New date will be announced Svc list encl Related correspondence PROCTOR, S Isham, Lincoln & Beale 83/06/16 BECHHOFFER, C Atomic Safety and Licensing Board Panel KELLEY, F J Michigan, State of 2pp 18727 358 P4X Fiche 50-329,83/06/16,8306220006
- 8306220069 Advises of 830623 & 24 depositions of L Clark & T Devine, respectively Svc list encl Related correspondence PROCTOR, 8 D Isham, Lincoln & Beale B3/06/16 KARR, J W Korr & Lyans 2pp 1830 172 24X Fiche 50-529, 83/06/16, 8306220069
- 8306270154 Forwards corrected copy of 820307 notice of violation package for Niagara Mahawk Power Corp WRIGHT.N A Hearing Branch 2 83/06/22 BERNABLI, L Government Accountability Project 1p 19012 148 24X Fiche 50-329, 83/06/22.
- 830629049B Notice of appearance in proceeding Certificate of but encl KARR.J H Government Accountability Project KARR.J H Karr & Lyons 83/06/27 App 19052 331 24% Fiche 80-329.83/06/27, 830.29048B
- 8306290530 Mation to quash util subpoens commanding testimony at proceedings to identify whistleblowers Subpoens violate first amend of US Constitution Commission cannot issue subpoens in violation of confidentiality promise KARR.J W Government Accountability Project * Karr & Lyons 83/06/27 Atomic Safety and Licensing Board Panel 13pp 19053 001 24% Fiche 50-329.83/06/27.8306290530
- ~~8306270551 Affidavit of L Clark re representation of whistleblowers if Govt Accountability Project required to name whistleblowers, ultimate damage will be to public interest in full & free flow of info on important issues Certificate of Svc encl CLARK.L Government Accountability Project 83/06/24 15pp 19053 014 24% Fiche 50-329.83/06/27,8306290530

M Antitrust correspondence

- 8306030242 Forwards FR notice of finding of no significant antitrust changes & time for filing of requests for reevaluation REGAN W H Siting Analysis Branch 83/05/24 COMBS.T Docketing & Services Branch 2pp 18734 024 24X Fiche 50-329.03/05/24. 8306030242
- --8306030246 Notice of finding of no significant antitrust changes & time for filing of requests for reevaluation REGAN,W H Siting Analysis Branch 03/05/24 2pp 18/94 024 24% Fiche 50-327,83/05/24,8306030242
- 8304:40345 Forwards FR notice of finding of no significant antitrust changes since CP reviews & of time for filing requests for reevaluation
 REGAN W H Site Analysis Branch B3/05/24. COOK, J W Consumers Power Co 2pp 18854
- --8306140350 Notice of finding of no significant antitrust changes since CP review & of time for filing requests for reevaluation REGAN:H H Bite Analysis Branch 83/05/24. 12pp 18854 131 24% Fiche 50-329, 83/05/24, 8306140345

- 8306140360 Forwards FR notice of finding of no significant antitrust changes since CP review & of time for filing requests for reevaluation
 REGAN, W H Site Analysis Dranch 83/05/24 COMBS, 1 Docketing & Services Branch 2pp 19844 349 24% Fiche 50-329,83/05/24,8306140360

O Insection reports, IE Bulletins & correspondence

- 8305110458 IE Info Notice 83-32. "Ruptured Am-241 Sources Contained in
 - Well Logging Device "Svc list one! TAYLOR.J M Division of Safeguards & Inspection Programs (Post 830103) 83/09/26 Consolidated Edison Co of New York, Inc 125pp 18831 043 24X Fiche 50-000,83/05/26,8305110458
- 8305110460 IE Info Notice 83~34. "Event Notification Info Worksheet "
- Svc list encl JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co. of New York, Inc. 115pp 18732-085 24X Fiche 50-000.83/05/26.8308110460
- 8306090243 Forwards IE Insp Repts 50-329/83-06 & 50-330/83-06 on 830329-31 & 0401 & notice of violation HARNICK,R F. Region 3. Office of Director 83/05/27 COOK, J W Consumers Power Co. 2pp 18795 321 24X Fiche 50-329, 83/05/27,
- 0304070243
- --8306090244 Notice of violation from insp on 830329-31 & 0401 HARNICK,R F Region 3, Office of Director 83/05/27 1p 18795 323 24X Fiche 50-329,83/05/27,8306090243
- --8306090245 IE Insp Repts 30-329/83-06 & 50-330/83-06 on 830329-31 & 0401 Noncompliance noted failure to follow policy procedures re control of purchased mail & svcs SINON.J A. SATHER.A. HARRISON.J J. Region 3. Office of Director 83/05/23 4pp 18795 324 24X Fiche 50-329,83/05/27.8306090243
- 8305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods Withdrawn at BWRs " Svc list encl JORDAN.C L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/31 Consolidated Edison Co. of New York, Inc. 116pp 18732 208 24X Fiche 50-000.83/05/31.8305110461 116pp
- 8304040048 Ack receipt of 830513 ltr informing NRC of steps taken to correct violations noted in IC Insp Repts 50-329/83-05 t 50-330/83-05 MARNICK,R F Region 3, Office of Director 83/05/31 CODK, J W Consumers Power Co ip 18719 247 24X Fichs 50-329,83/05/31. 8306060048
- --8306060055 Responds to NRC 830304 ltr re violations noted in IE Insp Repts 50-329/83-05 & 50-330/83-05 Corrective actions Bechtel maint form written to cover installed Q & non-Q mechanical snubbers & 100X initial insp will be performed CQOK,J W Consumers Fower Co 83/05/13 KEPPLER,J, Q Region 3, Dffice of Director 4pp 18719 24U PAX Fiche 50-329,83/05/31, B30400004
- 8306210443 Requests Region III inspect adequacy of util program to initially verify & periodically check for continued presence & effectiveness of Boraflex as newtron poison in spent fuel CROW, W.T. Uranium Fuel Licensing Dranch 93/6 Region 3, Office of Director 3pp 10735-359 Fiche 50-329, 83/06/08, 8306210443 93/04/08 HARRISON. J 359 24X
- 9305110464 IE Info Notice 83-36, "Impact of Security Practices on Safe Operations " Svc list encl JORDAN, C.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/07 Consolidate Edison Co of New York, Inc. 119pp 18830 280 24X Fiche 50-000, 83/06/09, 8305110464
- 8305110470 IE Info Notice 83-38, "Defective Heat Sink Adhesive & Seismically Induced Chatter in Relays Within Printed Circuit Cards" Sye list encl JURDAN.E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83706/13 Consolidated Edison to of New York, Inc. 110pp 18920 225 24X Fichs 50-000, 83706/13, 8305110470
- 9304090010 IE Info Notice 93-97, "Transformer Failure Resulting From Degraded Internal Connection Cables " Svc list enc., JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co. of New York, Inc. 243pp 18921 CO1, 24X Fiche 50-000,83/06/13,8304090010
- 8305110475 IC Info Notice 83-40, "Need to Environmentally Qualify
 Epoxy Grouts & Sealers " Byc list encl
 JORDAN, E. L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/06/22 Consolidated Edison Co of New
 York, Inc. 115pp 19021 177 24X Fiche 50-000,83/06/22,8305110475

- B305110477 IE Info Notice B3-41, "Actuation of Fire Suppression Sys Causing Inoperability of Safety-Related Equipment" Svc list
 - enci JORDAN, E.L. Division of Emergency Preparedness & Engineering Reaponse (Post 830103) 83/06/22 Consolidated Edison Co. of New York, Inc. 120pp 18997 007 24X Fiche 50~000,83/06/22,8305110477
- 8305110479 IE Info Notice 83-42, "Reactor Mode Switch Halfunctions "
 - 3051104/Y IE Amb Hottle 2 mm Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/23 Consolidated Edison Co of New York, Inc 116pp 18996 242 24X Fiche 50-000,83/06/23,8305110479.
- 8305110483 IC Info Notice 83-43, "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints " Svc list encl JURDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/24 Consolidated Edison Co of New York, Inc 116pp 19046 297 24X Fiche 50-000,83/06/24,8305110483
- R Periodic operating reports & related correspondence
- 8305030172 Forwards Bechtel, B&W & util nonconformance repts for Apr 1983 1703 COOK.J W Consumers Power Co 83/05/25 DEYOUNO.R C Director's Office. Office of Inspection and Enforcement 73pp 18709 094 24X Fiche 50-329.83/05/25.8304030172
- 8306270067 Forwards "Independent Design & Const Verification Program.

 Monthly Status Rept No 1.Poriod Inception Through 830527 "
 LEVIN.H A TERA Corp 83/05/27 KEPPLER, J O Region 3, Diffice of Director EISENRUT, Do Division of Licensing CODK, J W Consumers Power Co 3pp 19013 017 24X Fiche 80-329,83/05/27, 830A2700A7
- --8306270067 "Independent Design & Const Verification Program, Monthly Status Rept No 1. Period Inception Through 830527, " TULODIESKI, D. TERA Corp. 83/05/27 65pp. 19013.020 24X Ficha 50-327.83/05/27.8306270067

S Reportable occurrences, LERs & related correspondence

- 830&070242 Interim Deficiency Rept 82~06 re BbW steam generator auxiliary feedwater header design change Internal headers stabilized Mod will be completed upon receipt of thermal steeves Next rept by 830801 CODK, J W Consumers Power Co 83/05/31, KEPPLER, J 9, Region 3 Office of Director 2pp 18744 244 24X Fiche; 50~329, 83/05/31, REPOLER, J 9, Region 3 OFFICE OF Director 2pp 18744 244 24X Fiche; 50~329, 83/05/31,
- 8306130281 Interim deficiency rept re underrated terminal strips & use of terminal blocks w/o proper environ qualification in Limitorque valve operators Bechtel has requested addl info from Limitorque re qualifying terminal block types CODK, J W Consumers Power Co 83/06/07 KEPPLER, J Q Region 3, Office of Director 12pp 18824 128 24X Fiche 50-329,83/06/07,8306130281
- 8306170448 Board Notification 83-79 forwards Zack Rept on welder record discrepancies Rept documents Zack investigation & subsequent decision that item does not constitue IOCFR21 deficiency W/o encl W/O BRC! NOVAK,T M Assistant Director for Licensing. B3/06 Bafety and Licensing Board Panel 2pp 18906 341 Ficha 50-329,83/06/09,8306170448
- 8306210302 Interim deficiency rept re adequacy of shear reinforcements at major containment penetrations As-designed & as-built containment satisfactory Revs to FBAR initiated Final or interim rept expected by 631031.

 COOK, J W Consumers Power Co 83/06/13 KEPPLER, J, Q Region 3, Office of Director 2pp 18914 015 24X Fiche, 50-329, 83/06/13, 830451302
- 830.6320007 Part 21 rept re adequacy of fittings supplied by Tube-Line Corp through Capitol Pipe & Steal Products Co for use on new auxiliary feedwater headers of steam generators. Flanges not heat-treated as required by mot 1 sprcs
 TAYLOR, J H Babcock & Wilcox Co 83/06/17 DEYOUNG, R C
 Director's Dffice, Office of Inspection and Enforcement 4pp
 18927 354 24X Fiche 50-000,83/06/17,8306220007
- 8306270181 PNG-III-83-051 on 830621.util authorized to proceed u/installation of electrical penetration area temporary support beams & excavation under auxiliary bldg Workers laid off 830617 & 18 recalled LANDSHAM, R. HARRISON, J. Region 3, Office of Director 83/6 pp. 18971 344 24X Fiche 50-329.83/06/21,8306270181. 83/06/21.

T Hearing transcripts on non-antitrust matters

- 8306070073 Transcript of 830601 evidentiary hearing in Midland MI Pp
 - 16, 367-16, 352. * Atomic Safety and Licensing Board Panel 83/06/01 188pp 18740 105 24% Ficke 50-329,83/06/01,8306070073
- 8306070180 Transcript of 830602 evidentiary hearing in Midland, MI Pp
- 15,553-16,765 * Atomic Bafsty and Licensing Board Panel 83/06/02 205pp 18/37 128 24% Fiche 50-327,83/06/02,8306070180
- 8305070187 Transcript of 830603 hearing in Midland, MI Pp 16,766-
- 16,967. * Atomic Safety and Licensing Board Panel 83/06/03 205pp 18738.001 24% Fiche 50-329,83/06/03.8306070187
- 8306070162 Transcript of 830604 evidentiary hearing in Midland.HI Pp 16.768-17.104 Supporting documentation encl * Atomic Sefety and Licensing Board Panel 83/06/04 210µp 18736 001 24X Fichs 50-329.83/06/04.8306070162
- 8306:00063 Transcript of 830606 evidentiary hearing in Midland, MI Pp 17, 108-17, 175 > Atomic Sefety and Licensing Board Panel 83/06/06 89pp 18802 338 24X Fiche 50-329, 83/06/06, 8306100063
- 8306130215 Transcript of 830607 evidentiary hearing in Midland, MI Pg 17,196-17,412 * Abomic Safety and Licensing Board Panel 83/06/07 213pp 18827-011 24X Fiche 50-329,83/06/07,8306130215
- 8306140103 Transcript of 83060B evidentiary hearing in Midland. MI
- Pp 17.413-17.637 # Atomic Safety and Licensing Board Panel 83/06/08 131pp 18839 286 24% Fiche 50-329.83/06/08.8306140103
- 8306150142 Transcript of 830609 evidentiary hearing in Midland. MJ
- Pp 17.638-17.845. * Atomic Safety and Licensing Doard Panel 83/06/09 85pp 18851 220. 24% Fiche: 50-327.83/06/09.8306150142
- 830A140108 Transcript of 830A10 evidentiary hearing in Midland, MJ
- Pp 17.866-17.977. # Atomic Safety and Licensing Board Panel. 89/06/10. 115pp 18837 171 24X Fiche: 50~329.83/06/10.8306140108
- 8306200016 Transcript of Commission 830615 briefing in Washington, DC restatus of GA & soil settlement at facility Pp 1-64
 Supporting documentation encl

 * Commissioners 83/06/15 76pp 18909 238, 24X
 Status 840-208, 82/04/15 90/440001
- Fich# 50-329,83/06/15,8306200016

V. Operator Examinations

- B306270271 Advises that MG Jones Engineering Consultants. Inc (MGJEC) training program, evaluated on B30608, satisfactory & may be implemented immediately Spatial sys interaction program procedures approved by util & issued by MGJEC BARANOWS W. Btone & Webster. Inc. B3/06/17. KEPPLER.J G Region 3, Office of Director ip 18990 209 24X Fiche 50-327, B3/06/17, PRO18070274 8306270271.
- DOCKET 50-331 DUANE ARNOLD ENERGY CENTER
- A, Application/construction stage documents & correspondence
- B305110464 IE Info Notice B3-36, "Impact of Security Practices on Bafe Operations." Svc list anci JORDAN.E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) B3/06/09 Consolidated Edison Co of New York Inc 119pp 18830:280 24X Fiche 50-000.83/06/09.8305110464
- F. Security, medical, emergency & fire protection plans
- 8306130363 Informs that LASE vital area analysis program personnel will JUDIOUGES INFORMS that LASE vital area analysis program personne resmally:e original sites visited in early stages of program during CYBS & CYBS Revisit mecassary to gather addl info due to major mods & reduction of program by NRC.
 HIND. J. A. Division of Radiological & Materials Safety Programs 83/06/08 LIU, L. Iowa Electric Light & Power Co. ip 18821-24X Fiche 50-331,83/06/08,8306130363

J. Insurance & indomnity information

- 8306030167 Forwards Endorsement 58 to NELIA Policy NF-214 & Endorsement SALTZMAN, J S Assistant Director for State & Licensee Relation
 - SALTZMAN, J S Assistant Director for State & Licensee Relations 3pp 18704 035 24X Fiche 50 331,83/05/27,8306030167
- P Operating license stage documents & correspondence
- 8306020205 Forwards safety evaluation re valve operability for 18-inch butterfly valves used for purge or vent of containments Info submitted fails to demonstrate valve ability to close against containment pressure buildup during LUCA VASSALLO, D B Operating Reactors Branch 2 83/05/20 LIU.L Iswa Electric Light & Power Co Opp 18/01 057 24X Fiche 50-331,83/05/20,8306020205
- --8306020209 Safety evaluation re demonstration of containment purge & vent valve operability for 10 inch butterfly valves Info submitted fails to demonstrate valve ability to close against containment pressure buildup during LOCA # Office of Nuclear Reactor Regulation, Director 83/05/20 2pp 18701 060 24% Fiche 50-331.03/05/20.830602005
- 8306160389 Forwards response to NRC 830520 request for info re assessment of containment purge & vent valve operability Valves will close during design basis LOCA Valves will not be sealed MCOAUGHY,R W lowa Electric Light & Power Co = 83/06/10 DENTON,H R Office of Nuclear Reactor Regulation, Director 7pp 18860 210 24X Fiche 50-331,83/06/10,8306140389
- 930623034B Forwards response to NRC 830420 request for addl info re Mark I containment long-term program NUTECH rept "Mark I Containment Ring Girder Modelling & Stress Evaluation Utilizing Eccentric Beams" encl MCGAUCHY, R W lows Electric Light & Power Co 83/06/20 DENIU Dffice of Nuclear Reactor Regulation. Director App 18743 Oil 24% Fiche 50-331.83/06/20.8306230348
- ~-B30623035; "Mark I Containment Ring Girder Modelling & Stress Evaluation Utilizing Eccentric Beams" CHANG.D K. STURKEY, J. J. BALLARD, T.A. NUTECH Engineers, Inc MKI-03-008 60/04/20 41pp 18942-017 24X Fiche 50-331,83/06/20,8306230348
- 8306270420 Application for Proposed Change RTS-124, Rev 2 to License JOBS 1942 Application for Proposed Change RTS-124, Nev 2.to License DPR-49, changing Tech Specs re single recirculation loop operation to be consistent w/Cycle 7 reload licensing amend Changes supersede 801017 changes MCGAUGHY. R W lowe Electric Light & Power Co 83/06/24 DENTON. H R Office of Nuclear Reactor Regulation, Director 5pp 18973 069 24X Fichs 50-331,83/06/24,8306270420
- --8306270426 Proposed Change RTS-124, Rev 2 re single retirculation loop operation, changing Tech Specs to be consistent w/Cyrle 7 reload licensing amend
 # Iowa Electric Light & Power Co 83/06/24 41pp 18793 074
 24X Fiche 50-331,83/06/24,8306270420
- Q Inspection reports, IE Bulletins & correspondence
- 8305110458 IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in Well Logging Device" Svc list encl
 TAYLOR, J M Division of Bafeguards & Inspection Programs (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc
 125pp 18831 043 24X Fiche 50-000,83/05/26,8305110458
- 8305110460 IE Info Notice 83-34, "Event Notification Info Worksheet" 305110460 IE into notice of E... Svc list entl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co. of New York, Inc. 115pp 18732 085 24% Fiche 50-000,83/05/26.8305110469
- 8305110461 IE Info Notice 83-35, "Fuel Mayement W/Control Rods Withdrawn at BWRs " Syc list enc! JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/31 Consolidated Edison Co. of New York, Inc. 114pp 18732 208 24X Fiche 50-000,83/05/31,8305110461
- 8304070154 Ack receipt of 830228 ltr updating NRC on plan of action to upgrade regulatory performance Matters will be examined in subsequent insp Discussion of update planned after SALP 830623 meeting NORELIUS,C E Division of Project & Resident Programs 83/05/31 LIU.L. lowa Electric Light & Power Co 1p 18736 270 24X Fiche 50~331,83/05/31.8306070154

- 830&09031& Ack receipt of 830518 ltr informing NRC of steps taken to correct violations noted in IE lnsp Rept 50-331/83-01 SHAFER.W D Region 3. Office of Director 83/06/03 LIU.L lowa Electric Light & Power Co. ip 18795-123 24X Fichs 50-331,83/06/03,8306090316
- --8306090326 Responds to NRC 830418 ltr re violations noted in IE Insp Rept 50-331/83-01 Corrective actions vessel head insulation removal/installation procedures revised & thermometer calibrator ordered ROOT, L. D. Inwa Electric Light & Power Co. RC 83/05/18 KEPPLER, J. O. Region 3, Office of Director 3pp 18795 124 24X Fiche 50-331,83/04/03,8306090316
- 8306140590 Forwards response to Items 1-4 of IE Bulletin 83-03, "Check Valve Failures in Raw Water Cooling Sys of Diesel Generators" Inservice test program will be modified to provide for disassembly & insp of valves MCGAUGHY,R W I Iowa Electric Light & Power Co 83/06/08 KEPPLER,J G Region 3, Office of & Power Co 2pp 18844 156 24X Fiche 50-331,83/06/08,8306140570
- 8305110470 IE Info Notice 83-38, "Defective Heat Bink Adhesive & Seismically Induced Chatter in Relays Within Printed Circuit Cards " Svc list encl JURDAN, L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co of New York, Inc. 118pp 18720 225 24X Fiche 50-000,83/06/13,8305110470
- 8304090010 IE Info Notice 83-37, "Transformer Failure Resulting From Degraded Internal Connection Cables" Svc list encl JORDAN, C L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/66/13 Consolidated Edison Co. of New York, Inc. 243pp. 18921 001 24X Fiche 50-000,83/06/13,8306090010
- 8306270089 Advises that info re doses for tasks & dose rates for various areas of Pacility provided to NRC on informal basis during B30614 unannounced insp MINECK, D.L. Iowa Electric Light & Power Co. 83/06/14 KEPPIFR, J & Region 3. Office of Director ip 18788 122 24X Fiche 50-331, 83/06/14-8306270089
- 8305110475 IE Info Notice 83-40, "Need to Environmentally Qualify
 Epoxy Grouts & Sealers " Svc list encl
 JORDAN, E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/06/22 Consolidated Edison to of New
 York, Inc 115pp 19021 179 24X Fichs 50-000.83/06/22.9305110475
- B305110477 IE Info Notice 83-41. "Actuation of Fire Suppression Bys Causing Inoperability of Safety-Related Equipment" Sec list encl JORDAN, C. L. Division of Emergency Preparedness & Engineering Response (Post 830103) B3/06/22 Consolidated Edison Co. of New York, Inc. 120pp 18997 007 24X Fichs 50-000/03/06/22,0305110477
- B305110479 IE Info Notice B3-42. "Reactor Mode Switch Malfunctions " Svc list encl JDRDAN.E L Divirion of Emergency Preparedness & Engineering Response (Post 830103) B3/06/23 Consolidated Edison Co of New York, Inc 116pp 18996 242 24X Fiche 90-000,83/06/23.8305110479
- 8305110483 IE Info Notice 83-43, "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints " Svc list encl JORDAN.C. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/24 Consolidated Edison Co. of New York, Inc. 116pp 19046 297 24X Fiche 50-000.83/06/24.8305110483
- R Periodic operating reports & related correspondence
- 8306130375 NPDES noncompliance notification during Apr.monthly average suspended solids effluent concentration exceeded permitted monthly average Caused by large number of personnel onsite to support refueling outage MCOAUCHY.R W Jows Electric Light Power Co 83/04/08 KEPPLER.J Q Region 3, Office of Director ip 18822 184 24X Fiche 30-331.83/06/08.8306130375
- --8306130378 "Operation Permit Bys Monthly Monitoring Rept for Apr 1983 "
 ADAMS, L T lows Electric Light & Power Co 83/06/08 2pp
 18822 185 24X Fichs 50-331.83/06/08.8306130375
- B306200223 Monthly operating rept for May 1783 W/B30615 ltr ANDERSEN.M , MINECK.D L Inwa Electric Light & Power Co Director's Office. Office of Inspection and Enforcement 18902 277 24X Fiche 50-331.83/06/15.8306200223

- S Reportable occurrences, LERs & related correspondence
- 8306060209 LER 83-014/03L-0 on 830428, relay B21-K2A did not pick up as required on high flow signal Caused by sticking plunger in flow meter & Paulty capacitor in flow switch circuit Plunger freed & capacitor replaced W/830527 ltr
 KIBLER, D. R. MINECK, D. L. John Electric Light & Power Ca 83/05/27
 KEPPLER, J. G. Region 3, Office of Director 2pp 18727 358 24X
 Fiche 50-331,83/05/27,8306060209
- 830&100103 RG on 830527, both divs of hydrogen/oxygen analyzers determined inoperable Orderly shutdown commenced On 830527, A sys returned to operable status MINECK.D L Iowa Electric Light & Power Co 83/05/27 KEPPLER.J Q Region 3, Office of Director ip 18803 072 24X Fiche 50-331.83/05/27.830&100103
- 8306130327 PND-III-83-040 on 830605, licensee noticed increase in chloride concentration in reactor cooling water from leak or leaks in main condenser tubes Condenser tubes repaired or plugged Chlorine level reduced CLARDYL , JORDAN.M , SHAFER, W Region G. Office of Director 83/06/07 ip 18822 355 24X Fiche 50-331,83/06/07,8306130327.
- 8306130375 NPDES noncompliance notification during Apr.monthly average suspended solids effluent concentration exceeded permitted monthly average Caused by large number of personnel onsite to support refueling outage MCOAUOHY,R W Iowa Electric Light & Power Ca 83/06/08 KEPPLER,J O Region 3, Office of Director ip 18822 184 24X Fiche 50-331,89/06/08,8306130375
- --8306130378 "Operation Permit Bys Monthly Monitoring Rept for Apr 1983 "
 ADAMS, L T Town Electric Light & Power Co 83/06/08 2pp
 18822 185 24X Fiche 50-331,83/06/08,8306130375
- 8306170337 LER 83-021/01T-0: on 830527, containment H202 analyzer channel A rendered inoperable Caused by celibr difficulties due to fouled pressure regulators resulting from sys contamination. Tech 8gecs revised W/830610 ltr MILLER, W J. MINECK, D L. Inwa Electric Light & Power Co. 83/06/10 KEPPLER, J Q Region 3, Office of Director 3pp 18881.019. 24X Fiche 50-331,83/06/10,8306170337
- 8306210242 PNO-III-B3-045 on B30614, bomb threat received from male caller complaining of increased electric rates & state & federal economic policies Bheriff & FBI notified CHRISTOFFER, G. CREED.J. Region 3. Office of Director. B3/06/15, ip 16916-351 24X Fiche 50-331, B3/06/15, B306210242
- 8306270290 LER 83-015/031-0: on 830517, during rautine surveillance, 4 kV essential bus degraded voltage relay 127/A1 tripped out of spec at 8.6 s Gaused by instrument drift Time setting adjusted & relay tested satisfactorily M/830616 ltr KIBLER, D.R. MINECK, D.L. Iowa Electric Light & Power Co 83/06/16 KEPPLER, J.Q. Region 3, Office of Director 2pp 18796 182 24X Fiche 50-331, 83/06/16, 8306270290
- DOCKET 50-333 JAMES A FITZPATRICK NUCLEAR POWER PLANT F Security, medical, emergency & fire protection plans
- 8306i40158 Ack receipt of 830527 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-333/83-06.

 STARDSTECKI.R Division of Project & Resident Programs 83/06/09.

 MONEILL, C A Power Authority of the State of New York ip 18839 031 24% Fiche 50-333,83/06/09.8306140158.
- --B306140169 Responds to NRC 830428 ltr re violations noted in IE Insp Rept 50-333/83-06 Corrective actions out of date annunciator response procedures revised Pathway & area transversed by amployees outside restricted area surveyed MCNETLL.C A Power Authority of the State of New York. 83/05/27 8TARGSTECKI.R Division of Project & Resident Programs 2pp 18839:032 24X Fiche.50-333,83/06/09.8306140158.
- B30617003B Informs that LABL Vital Area Analysis (VAA) Program personnel will be reanalyzing original 10 sites visited during early stages of VAA program.during CYB3 & B4 Revisit necessary to gather addl info due to major NRC mods ALLAN.J.M Region i, Office of Director B3/06/13 MCNEIL.C A. Power Authority of the State of New York 2pp 1887B: 291 24X Fiche 30-333.83/06/13.8306170038.
- B306200279 Advises that Class III fee appropriate for portion of B10319 application proposing mode & alternate safe shutdown capability to meet App R requirements Remittance requested, MILLER, W O License Fee Management Branch B3/06/14 BINCLAIR, L W Power Authority of the State of New York ip 18919 263 24X Fiche 50-333,83/06/14.83062002/9.

- 8306230456 Forwards corrected cover sheet for IE Insp Rept 50-333/83-08 Insp dates changed from 630321-0426 to 630321-25.
 - 830221-25.

 MARTIN, T Y. Division of Engineering & Technical Programs 83/06/20

 MCNEILL, C A Power Authority of the State of New York 1p

 18942.057 24% Fiche 50-333.83/06/20.8306230456
- --8306230459 Forwards IE Insp Rept 50-333/83-08 on 830321-25 & notice of violation MARTIN.T.T Division of Engineering & Technical Programs 83/05/27 MCNEILL.C A Power Authority of the State of New York 2pp 18942 058 24X Fiche 50-333,83/04/20,8306230456
- --8308230463 Notice of violation from insp on 830321-25 * Division of Engineering & Technical Programs B3/05/27 2pp 18942 060 24% Fiche 50-333.83/06/20.8306230456
- --8306230469 IE Insp Rept 50-333/83-08 on 830321-25 Noncompliance noted.feilure to establish adequate procedures for respiratory protection squipment & failure to implement procedures controlling radiation work permits NCBRIDE.M.H. SHANBAKY.M Region 1. Office of Director 83/05/26 14pp 18942 062 24X Fiche:50-333,83/06/20.8306230456

I Financial information

- 8304130111 "Annual Financial Rept 1982 " W/830407 ltr DYSON, J. B. BAYNE, J. P. Power Authority of the State of New York 83/04/07 Office of Nuclear Reactor Regulation, Director Alpp 18927 224 24% Fiche 50-000,83/04/07.8306130111.
- P Operating license stage documents & correspondence
- 8306030032 Responds to 830311 request for exemption from schedular requirement of 10CFR30 49, environ qualification of equipment Confirms submittal date of 830620 vASSALLO.D B Operating Reactors Branch 2 83/05/27 BAYNE, J P fower Authority of the State of New York 2pp 18733 174 24X Fichs.50-333,83/05/27,8306030032
- 8306030224 Notifies that util name changed from Power Authority of State of NY to New York Power Authority New name does not reflect change in status, but clarifies public identity. BAYNE, J. P. Power Authority of the State of New York 83/05/27. DENTON, H. R. Office of Nuclear Reactor Regulation. Director 2pp 18702 332. 24X Fiche: 50-000.83/05/27.8306030224
- 8306060121 Forwards evaluations submitted re NUREO-0612. "Control of Heavy Loads at Nuclear Power Plants " Handling shielded shipping casks over spent fuel pool will be prohibited until measures taken to reduce probability of cask drop.

 BAYNE.J P. Power Authority of the State of New York 83/06/02 VASSALD.D. 8 Operating Reactors Granch 2 14pp 18722 275 24) Fiche 30-333,83/06/02.8306060121.
- 8306070303 Advises that individual program plan will be submitted by 831019 referencing BMR Dumers Group generic program plan re NRC 830419 Generic Ltr 83-18. Suppl 1 to NUREG-0737, Item I. D. I. "Control Room Design Review" 84YNG.J. P. Power Authority of the State of New York 83/06/03 VASSALO, D B Operating Reactors Brench 2 2pp 18740 301 24X Fiche 50-333,83/06/03,8306070303
- 8306100100 Reaffirms justifications for continued operation for equipment identified as Categories Ib. IIa & IV for which qualification programs still in progress Qualification info not accurate representation AddI items and SAYNE, JP. Power Authority of the State of New York 83/06/06 VASSALLO,D B. Operating Reactors Branch 2 37pp 18802 266 24X Fichs 50-333,83/06/06 8306100100
- 8304140318 Informs that add1 info requested on 830511 re NUREC-0737, Item I1 K 3 28, "Qualification of Automatic Depressurization Sys Accompilators," will be provided by 830930. BAYNE.J.P. Power Authority of the State of New York 83/06/07 VABSALLO.D.B. Operating Reactors Branch 2, Sop 18832 207. 24X Fichs. 50-333, 83/06/09, 8306140318
- 8306230170 Forwards Offsite Dose Calculation Hanual to accompany proposed radiological effluent Tech Sprcs submitted on 830427.

 BAYNEJ P Power Authority of the State of New York 83/06/21.

 VASSALLO, D. B. Operating Reactors Branch 2 ip 18944 171. 24X Fiche. 50-333, 83/06/21, 8306230170.
- --8306230174 Offsite Dose Calculation Hanual * Power Authority of the State of New York. 83/06/21. 204pp 18944:172 24X Fiche: 50-333, 83/06/21, 8306230170.

- 8306280508 Forwards addl info re compliance w/NVREG-073/, Item-II F & 4, "Containment Pressure Monitor" & II F & 5, "Containment Water Level Monitor," per 030408 commitment BAYNE, J P Power Authority of the State of New York 83/06/23 VASSALLO, D & Operating Reactors Branch 2 7pp 19017 288 24X Fiche 50-333,83/06/23.8306280508
- Q Inspection reports. IE Bulletins & correspondence
- B304010227 Forwards IE Insp Rept 50-333/B3-10 on B30412-15 & notice of deviation

 MARTINI T Division of Engineering & Technical Programs G3/05/26

 MCNEILL.C A Power Authority of the State of New York Pap
 18672 349 24X Fiche 50-333/B3/05/16/B306010227

f

- --8306010229 Notice of deviation from insp on 830412-15 * Region 1. Office of Director 83/05/16 2pp 18672;351, 24x Fiche 50-333.83/05/16.8306010227
- --8306010231 IE Insp Rept 50-333/83-10 on 830412-15 Deviation noted. Failure to meet commitment to include all safety-related valves in test program & failure to establish max allowed strake times for power operated valves REKITO, WA BETTENHAUSEN, L. Region 1, Office of Director 83/05/06 10pp 18672 353 24X Fiche 50-333,83/05/16.8304010227
- 9304040230 Forwards IE Insp Rept 50-333/83-09 on 830401-30 & notice of violation STAROSTECKI, R Division of Project & Resident Programs 83/05/23 MCNEILL, C A Power Authority of the State of New York 2pp 18726 329 24X Fiche 50-333,83/05/23,8306060230
- --8306060234 Notice of violation from insp on 830401-30 * Region 1, Office of Director 83/05/23 Ppp 16726 371 24X Fiche 50-333.83/05/23.8306060230
- --8306050237 IE Insp Rept 50-333/03-09 on 830401-30 Noncompliance noted failure to implement or establish adequate measuring & test equipment controls properly LINVILLE, J.C., DOERFLEIN, L.T., KIBTER, H.B. Region 1, Office of Director 83/05/17 14pp 18726-333 24X Fiche 50-333,83/05/2J,8306060230
- 8306130481 Forwards request for addl info re masonry wall design per IE Bulletin 80-11 response Info requested within 45 days VASSALLO.D B Operating Reactors Branch 2 83/05/25 BAYNE.J P Power Authority of the State of New York 3pp 18830 164 24% Fiche 80-333,83/05/25,8306130481
- 8305110458 IE Info Notice 83-32, "Ruptured Am~241 Sources Contained in Hell Logging Device" Svr list encl TAYLOR, J M Division of Bafeguards & Inspection Programs (Post 830103) 83/05/26 Consol)dated Edison Co of New York, Inc 125pp 18831 043 24X Fiche 50-000.83/05/26.8305)10458
- 8305110460 IE Info Notice 83-34, "Event Notification Info Morksheet"
 Svc list encl
 JORDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/05/26 Consolidated Edison Co of New
 York, Inc. 115pp 18732-085 24X Fiche 50-000,83/05/26.8305110460
- 8305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods Withdrawn at BWRs " Syc list encl JORDAN, E. Division of Emergency Preparedness & Engineering Response (Past 830103) 83/05/31 Cansolidated Edison Co of New York, Inc 114pp 18732 208 24X Fiche 50-000,83/05/31,8305110461
- 8306440147 Act receipt of 830421 ltr informing NRC of steps taken to correct violations noted in IE lines Rept 50-333/83-04 Improvement on proposed 830801 issue date for procedure describing delegation of audit functions encouraged 871AROSTECKIR Division of Project & Resident Programs 63/05/31 MCNEILLIC A Power Authority of the State of New York 18839 076 24X Fichs 50-333,63/05/31,8396140147
- --8306140153 Responds to NRC 830321 itr re violations noted in IE Insp Rapt 50-333/83-04 Corrective actions two surveillance addits re limiting conditions of perations performed Program addressing audit Functions, per Procedure 18 1.6eveloped MCMEILL, C A Power Authority of the State of New York BTANDSTECKIR, Division of Project & Resident Programs 18839,078 24X Fische 50-333,83/05/31,8306140147
- 8306210156 Responds to IE Bulletin 83-03, "Check Valve Failures in Raw Mater Cooling Sys of Diesel Generators" Pump & valve program will be modified to include check valves in Alow path of cooling water for diesel generators
 MCNEILL.C A Power Authority of the State of New York 83/06/08
 BEYCOMOR, R C Director's Office. Office of Inspection and Enforcement 2pp 18915 191 24X Fiche 50-333,83/06/08,8306210156

- 8305110464 If Info Notice 83-36. "Impact of Security Practices on Safe
- 305110464 IF Info Notice 83-36. "Imput of Seturity Practices on Safe Operations "Syc list end! JORDANIE L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/07 Consolidated Edison Cn of New York. Inc. 119pp. 16830-280 24X Fiths 50-000.83/06/07.8305110464
- 8306(40158 Ack receipt of 83052/ ltr informing NRC of steps taken to correct violations noted in IL Insp Rept 50-333/83-06
 STAROSITCKLR Division of Project & Resident Programs 63/06/09
 MCNEILL, C A Power Authority of the State of New York ip 18839-031 24X Fiche 50-333,83/06/09,8306440158
- --8306140167 Responds to NRC 830428 ltr 1e violations noted in IE Insp Rept 80-33783-06 Corrective actions out of date annunciator response procedures revised Pathway & area transversed by employees out-ide restricted area surveyed MCNETILL, C A Power Authority of the State of New York 93/05/27 STANGSTLCKIR Division of Project & Resident Programs Ppp 18839 032 24X Fiche 50-333,83/06/09,8306140158
- 83051104/0 IE Info Notice 83-30. "Defective Heat Sink Adhesive & Seismically Induced Chatter in Relays Within Printed Circust Cards " Syc list end JURDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co. of New York, Inc. 118pp 18920 225 24X Fishe 50-000, 83/06/13, 8305110470
- 8304090010 IE Info Notice 83-37, "Transformer Failure Resulting From Degraded Internal Connection Cables" Byo list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co of N 18921 001 24X Ficha 50-000 83/06/13 8306090010 243pp
- 0306200338 Ack receipt of 83053) itr informing NRC of steps taken to correct violations noted in If Insp Rept 50-333/82-28 STARGSTECKI, R Division of Project & Resident Programs 83/06/14 MONETLL.C A Power Authority of the State of New York 1p 18900 200 24X Fiche 50-333.83/06/14.8306200338
- --8305200344 Responds to NRC 830303 ltr re violations noted in 1E lnsp Rept 50-333/82-28 Corrective actions work procedure revised to include insp & hold points as appropriate during biomnial review of procedure
 MCNEILL.C A Power Authority of the State of New York B3/05/31
 STAROSTECKI.R Division of Project & Resident Programs 2pp
 18900 209 24X Fiche 50-333,83/05/14.8306200338
- 8306230454 Forwards corrected cover sheet for IE Insp Rept 50-333/83-00 Insp dates changed from 830921-0426 to 83/06/20
- --6306230457 Forwards IE Insp Rept 50-333/83-08 on 830321-25 & notice of violation

 MARTIN. T T Division of Engineering & Technical Programs
 83/05/27 MCNCILL,C A Power Authority of the State of New York
 2pp 18942 058 24% Fiche 50-333,03/06/20,8306230456
- --8306230463 Notice of violation from inso on 830321-25 * Division of Engineering & Tochnical Programs 83/05/2/ 2pp 18942 060 24% Fiche 50-333,83/06/20,8306230456
- ---8306230469 IE Insp Rept 50-333/83-08 on 830321-25 Noncompliance noted failure to establish adequate procedures for respiratory protection equipment & Pailure to implement procedures controlling radiation work permits HCDRIDE,M H. SHANBAKY,M Region 1, Dffice of Director 83/05/26-14pp 18742-062 24X Firm 50-333,63/06/20,8306230456
- B3G5110475 IE Info Notice 83-40, "Need to Environmentally Gunlify
 Epory Grouts & Sealers " Svc list encl
 JGRDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) B3/06/22 Consolidated Edison Co
- 8305110477 IE Info Notice 80-41, "Actuation of Fire Suppression Bya Causing Inoperability of Safety Related Equipment " Byc lict encl. enci. JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 800103) 83/06/22 Consolidated Edison Co. of New Yark. Inc. 120pp \18997\007\24%\Fiche\30-000\83/06/22\809\$110477
- 8305110479 IE Info Notice 83-42, "Reactor Mode Switch Malfunctions " 10:110477 IE HIP NOTES A. S. SVC 1164 enc!

 JORDAN, C. L. Division of Emergency Preparedness & Engineering

 Response (Post 830103), 83/06/23 Consolidated Edison Co. of New

 York, Inc. 116pp 18976-242 24X Fiche 50-000,83/06/23,8305110477

- 8305(1048) IE Info Notice 83-43, "Improper Settings of Intermediate
 Range (IR) High Flux Trip Setpoints " Svc list encl
 JORDAN, E. L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/06/24 Consolidated Edison Co. of New
 York, Inc. 116pp 19046 29/ 24X Fiche 50-000.83/06/24.8305110483
- R Periodic operating reports & related correspondence
- 830610001/ Monthly operating rept for May 1983 W/830603 ltr CODK, J. MCNEILL.C A Power Authority of the State of New York 83/06/03 Director's Office, Office of Inspection and Enforcement 7pp 18802 104 24% Fiche 50-333,83/06/03,8306100017
- S Reportable occurrences, LERs & related correspondence
- 8306010112 Updated LER 81-082/03X-2 on 811230 erratic reading noted on source range monitors & intermediate range monitor instruments Caused by low voltage on 24-volt dc batteries

 Battery rechaige restored sys to normal W/830518 ltr

 LISENO, R T, NCREILL, C A Power Authority of the State of New York

 83/08/16 ALLAN, J R Region I. Office of Director 2pp

 18673 334 24X Fiche 50-333.83/05/16.8306010112
- 830.6010.312 Updated LER 80-006/03X-1 on 800106.core spray injection valve 14-MOV-12A improperly operated during 791221 surveil lance test Caused by misoperation of valve circuit breaker overload tip device WF830517 1tr GHILDS.V. MCNEILL, C.A. Power Authority of the State of New York 83/05/17 ALAN.J M. Region 1. Dffice of Director 3pp 18672 312 24X Fiche 50-333,83/05/17,8306010312
- 8306200139 LER 83-019/03L-0 on 830501.LPC1 independent power supply Inverte: B indicated minor trouble alarm Caused by failed gate firing module printed circuit board Board replaced Inverter returned to svc W/830531 ltr MCNETILL.C A Power Authority of the State of New York Stalland, J M Region 1, Office of Director Jpp 18903 266 Fichs 50-333.83/05/20.8306200137 83705720
- 830.6200375 LER B3-018/04T-0 on B30426, standby gas treatment sys A charcoal failed offsite methyl iodide efficiency test Caused by defective test instrument Charcoal replaced W/B3060! Itr MULCAHEY.E . MCNEILL.C A Power Authority of the State of New York. B3/05/31 ALLAN.J M Region J. Diffice of Director Jpp 18899 098 24X Fiche 50-333,83/05/31.8306200375
- 8306140080 PND-I-83-057 on 630607. while preparing weld on 3-inch control rod drive (CRD) return header for ultrasonic exam; through well crack found in weld 4 ft from reactor pressure vessel CRD return noille Header cut out KIBTER, H. KEIMIG, R. Region I. Office of Director 83/06/08 lp. 18838 346 24X Fiche 50-333.63/06/08.8306140080
- 8306280486 LER B3-020/03L-0 on B30520.during monthly valve cycling 305280486 LER B3-020/03L-0 on B30920. during monthly valve exting surveillance test of 23 MD-60 (HPC) outboard containment isolation bypass valve).valve motor tripped on overload Caused by hard valve packing N/030620 Itr PETERS, R, MCNEILL, CA Power Authority of the Btate of New York B3/06/20 MURLTY, I E Region 1, Office of Director, 2pp 19018 28/ 24X Fiche 50-333,63/06/20.6306280486
- V Operator Examinations
- 8306140665 Extends invitation to attend 830627 meeting in King of Pressia.PA to discuss transfer of reactur operator licensing function from Bothesda.MD to Region I ofc STAROBIECKI.R. Division of Preject & Resident Programs 83/06. MCNEILL,C A Power Authority of the State of New York. 2pp 18842 06/ 24X Fiche 50-333.83/06/09.8306140665 83/04/09
- DOCKET 50-334 DEAVER VALLEY POWER STATION, UNIT 1 F Security, modical, emergency & fire protection plans
- 8306070264 Forwards corrected Page 2-4 of Rev 4 to physical security plan training qualification plan & approval sheet Encls withheld (ref 100FR73.21)
 GAREY, J. Duquesne Light Co. 83/04/22 ALLAN, J. M. Region. 1,
 Office of Director Ip. 18740-934 24% Fiche 50-334, 83/04/22, 8306070264
- 8306070076 Forwards Nev II to Issue 2 of physical security plan Rev withheld (ref 100182 790)
 GAREY, J J Duquesne Light Co 83/04/29 ALLAN, J H. Region 1, Office of Director 2pp 18/39 208 24X Fiche 50-334,83/04/29, 83060700/6

- 8306010326 Forwards IE Safeguards Insp Rept 50-334/83-09 on 840418-22 No noncompliance noted MARTIN.T 7 Division of Engineering & Technical Programs 83/05/17 CAREY.J.J Duguesne Light Co 2pp 18679 358 24X Fiche 50-334.83/05/17.8306010326
- --B306010327 IE Bafeguards Insp Rept 50-334/83-09 on B30418-22 No noncompliance noted Major areas inspected physical barriers (protected area), security sys power supply, access control (personnel) & detection aids (protected area, vital areas) SMITH, 0 C., 60DY, A T. Region I. Office of Director 83/05/13 3pp 18679 360 24% Fiche 50-334,83/05/17,8306010326
- 8304060200 Forwards IE Insp Rept 50-334/83-08 on 830405-0502 & notice of violation STAROBTECKI, R Division of Project & Resident Programs 83/05/23 CAREY, J J Duquesne Light Co 2pp 18727 256 24X Fichs, 50-334, 83/05/23, 8304040200
- --8306060204 Natice of violation from insp on 830405-0502 * Region i. Diffice of Director 83/05/23 ip 18727 258. 24X Fiche:50-334.83/05/29, 8304040200
- --B30&0&0B14 IE Insp Rept 50-334/83-00 on B30405-0502 Noncompliance noted failure to demonstrate ECCS valve operability within specified surveillance interval TROSKOBKI.W M. TRIPPL E. Region J. Office of Director B3/05/17, 22pp. 18727 259 24X Fiche 50-334,83/05/23.830&0&0200
- 8306090189 Advises of plan to deviate from originally scheduled emergency preparedness exercise dates of Feb 1984 & 1985
 Dates changed to June to allow for testing under various weather conditions Two previous exercises performed in Feb CAREY, J J Duquesne Light Co 83/05/01 VARGALS A Operating Rescors Branch 1 2pp 18/95.079 PAX Fiche 50-334.83/06/01, 8306090189
- 8306280490 Forwards SALP rept for evaluation period Dec 1781 Nov 1782 Fire protection & housekeeping rating upgraded to Category 2 MURLEY, T E Region 1. Office of Director 83/06/23 CARCY, J J Duquesne Light Co 4pp 17019.189 24X Fiche 50-334.83/06/23, 8308280490
- --8306280492 Forwards SALP rept conducted on 830124 for Der 1981 Nov 1982 Meeting scheduled for 830215 at site to discuss assassment STAROSTECKI,R Division of Project & Resident Programs B3/02/07 CAREY, J Duquesne Light Co 2pp 14019,193 24X Fichy 50-334,83/06/83,8306280490
- --8306280495 Responds to NRC 830207 ltr re results of SALP Board review Reconsideration of rating given to Item 5, "Fire Protection & Housekeeping," requested CAREY-J J Buquesne Light Co 83/03/02 HAYNES, R C Region 1, Office of Director 7pp 19019 195, 24X Fiche: 50-334, 03/06/23, 8306280490
- --8306280497 SALP rept for Dec 1981 Nov 1982 * Region 1, Office of Director 83/01/24. 32pp 19019 202 24X Fishe: 50-334.8306280490.
- P Operating license stage documents & correspondence
- 8306020674 Informs that NUREC-0737. Items II F & 4, "Containment Pressure Manitor," & II.F & 5, "Containment Hydrogen Manitor" completed Items closed VARCA.8 A Operating Reactors Branch I 83/05/17 CAREY, J. J. Duquesne Light Co. 6pp 18716 249. 24X Fiche 50-334, 83/05/17, 8306020476
- 8306090190 Forwards revised pages to Tech Specs for Amend 66 to License DPR-66, per 830426 Proposed Change Request 84 correcting administrative errors
 TAM.P.B Operating Reactors Branch 1 83/05/25 CAREY, J J Doquesne Light Co. 2pp 18809-256 P4X Fiche 50-334,83/05/25,8306090190
- --8306070193 Rev to Amend 66 to License DPR-66, consisting of Fech Spec page changes to correct administrative errors "Operating Reactors Branch 1 83/05/25 3pp 18909 25B 24X Fiche: 50-334,83/05/25,8306090190.
- 8304030243 Forwards request for add1 anfo re N-1 loop operation Response required within 60 days of receipt of lit to meet Dec 1963 target close out date.

 VARGA: 8 A Operating Reactors Branch 1 83/05/27. CAREY, J J. Duquesne Light Co. 5pp 18704:029 24X Ficha: 50-334, 83/05/27, 8306030243

- 830&03024/ Informs that WCAP 10176, "Second Cycle Performance of Beaver Valley, Unit 1/100/" provides excellent description of comprehensive fuel example formed to unlexams provide confirmation of satisfactory performance of fuel design VARGA/S A Operating Reactory Branch 1 83/05/2/ CAREY, J Duquesne Light Co 2pp 18/14/062 24X Fiche 50-334/83/05/2/, 830&0:0247
- 8306090360 Requests authorization for removal of interim operating restrictions on automatic tod control, effective w/(yrle 4, since DNB design basis met for dropped rod accident CAREY.J J Duquesne Light Co. 83/05/-/ VAROA,S A Operating Reactors Branch 1 2pp 187/4 319 .44X Fiche 50-334.83/05/2/, 8306090368
- 830&140&39 Application to amend License DPR &&, consisting of Rev 1 to 781004 Tech Sprc Change Request 34, revising reactor vessel overpressure protection systat low temps

 CAREY.J J Duquesne Light Co 83708781 VARGA. A Operating Reactors Branch 1 2pp 10048 020 247 Fishe 50-534.83705731.8308440687
- --8306140643 Proposed Tech Speci to reactivity control sys.RCS & ECCS

 * Dequesing Light Co 03/05/J1 15pp 18843 005 24X
 Ficha 50-334.83/05/31 8306140637
- B306080073 Comments on deviation in procurement of chemical addition pumps specifically, plan to procure pumps w/o N stamp per B30214 ltr Based on listed provisions deviation acceptable VAR6A, S A Operating Reactors Dranch J 83/05/03 CARLY, J Duquesne Light Co 2pp 18/8/273 P4X Fiche 50 334,83/06/03,8306080073
- 8306200334 Advises that implementation data for Reg Guide 1 137, "Twel Oil Bys for Standby Diesel Generators," delayed until B40201 Revised schedule necessary due to excavation required to install new fuel oil tank.per BCP 370 CAREY, J. Duquesne Light Co. 83705/07 VARGA, S.A. Operating Reactors Branch 1 lp 18719 214 27X Fiche 50-334, 83705/07, 8306200334
- Q Inspection reports: 2E Bulletins & correspondence
- 8306010326 Forwards IE Safequards Insp Rept 50-334/83-09 on B30418-22 No noncompliance noted MARTIN 1 Division of Engineering & lechnical Programs 83/05/17 CAREY J Duquesne Light to 2pp 186/9 358 24X Fiche 50-334.03/05/17.8304010306
- --8306010327 IE Safiguards Insp Rept 50-534/83-09 on 830418-52 No noncompliance noted Major area-inspected physical barriers (protected area), security sus power tupply access control (personnel) & detection aids (protected area-vibal areas) SMITH.6 C. GDDY. A T. Region 1. Office of Director 83/05/13 3pp 18679 360 24x Fiche 50 334.83/05/17.8306010326
- 9306060200 Forwards IE Insp Rept 50-334/83-08 on 830405 0502 & notice of violation STARDSTLCKI, R Davision of Project & Resident Programs 93/05/23 CAREY, J J Duquesne Light (o Ppp 1872/ 256 24X Fiche 50-334,83/05/23,830406000
- --8306060204 Notice of violation from insp on 830405-0502 * Region 1, Office of Director 83/05/23 lp 18727 P58 P4X Ficho 50-334,83/05/23,830600000
- --8306060214 IE Insp Rept 50 334/84-0B on 830405-0502 Noncompliance noted failure to demonstrate ECCS valve operability within specified survaillance interval TROBNORK, W N TRIPP.L E Region 1. Office of Director 83/05/17 22pp 18727 257 24X Fichs 50-334.83/05/23.8306060200
- B306100104 forwards fees for reliew of 300517 application for relief from ABME Code inservice tusp requirements for RHR ngzzle-to-vessel weld volumetric exam SIEBER, J.D. Duquesne Light (n. 83/05/24 License Fee Management Branch 3pp 18803 073 24) Fiche 50-334,83/05/24,8306100104.
- 8305110458 IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in Well Legging Device" Sv. list end!
 TAYLOR, J M Division of Safequards & Inspection Programs (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 125pp 18801 040 24% Fich. 50 000,83/05/26.8305110458
- 8305110460 IE Info Notice 80-34, "Event Nutification Info Workshoet" Svc list encl JORDAN,E L Division of Lmeigency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 115pp 18732 085 24X Fiche 50-000,83/05/26,8305110460

- 8306030290 Ack receipt of 830516 ltr informing NRC of steps taken to correct violations noted in 11 linsp Ript 50-334/83 07 STAROSTELER, Division of "roject & Risident Programs B3/05/26 CAREY, J. J. Duquerne Light Co. Ppp 10/04 001 24X Fiche 50-334,83/07/24,8304070098
- --8306030303 Responds to NRC 830420 ltm re violations noted in IL Insp. Rept 50-334/83-07 Corrective action supplemental repts prepared for little LERs reviewed for issuence prior to 8305/7 CAREY, J. Duquesne Light (n. 83705/18 STAROSTECKI.R Division of Project & Resident Programs App. 18704 003 24X Fiche 50-334,83705/28,83060/8278
- 8305110461 IE Info Notice 83 35, "Tuel Movement W/Control Rods Withdrawn at BWRs " Syc list (Infl JURDAN, E L Division of Lawyency Preparedness & Engineering Response (Post 830103) 87/05/31 Consolidated Edison Co of New York, Inr 116pp 18732 203 24X Fithe 50-000.83/05/31,0305110461
- 8306f40620 Forwards response to 1E Nulletin 83-03, "Check Valve Farlures in Raw Water Cooling Typ of Diesel Generators" Valve integrity verification procedures will be performed lines required to complete Item 5 forthcoming GAREY, J. J. Duqueine Light on 193708/07 Region 1, Office of Director 8pp 18841 250 (14X Fishe 50-334,83/06/07,8308140820)
- 0306280435 Responds to IE Bulletin 03-03, "(heck Valve Failures in Raw Hater Couling Sys of Diesel Ginerators " Info requested by Action Items 1.2, 3 & 4 re pump & valve inservice program encl
 - encl CAREY, J. J. Duquesne Light Co. 93/06/07 Region 1, Office of Director Upp 19018-340 14% Fiche 10-334,83/06/07,8306280435
- 8305110464 IE Info Notice 83 Jb. "Impact of Security Practices on Safe Operations " Svt list encl JORDAN, E. I. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/07 Consolidated Edison Co. of New York, Inc. 117pp 16830 P80 247 Fiche 50-000,83/06/09.8305110464
- 8305110470 IE Info Notice 83-36, "Defective Heat Sink Adhesive & Seismically Induced Chatter in Relays Within Printed Circuit Cards" Syc list end JORDAN, E.L. Division of Louigency Preparedness & Engineering Response (Port 830103) 83/06/13 Consolidated Edison Co. of New York, Inc. 118pp 18720 225 24X Fiche 50-000, B3/06/13, B305110470
- 8304070010 IE Info Notice 83-37, "Transformer Failure Resulting From Degraded Internal Connection Cables" Svc list encl JORDAN, E. L. Division of Lawrigincy Preparedness & Ingineering Response (Post 830103) 83/06/13 Concolidated Edison Co. of New York, Inc. 243pp. 18721 001 24X Fishs 50-000, 83/06/13, 8304070010
- 8305110475 IE Info Notice 83-40, "Need to Environmentally Qualify
 Epoxy Grouts & Sealers " 9vc list encl
 JORDAN,E L Division of Lawygancy Preparedness & Engineering
 Response (Poxt 830103) 83/04/22 Causolidated Edison Co of New
 York, Inc 115pp 19021 177 24X Fiche 50-000,83/04/22,8305110475
- 8305110477 IE Info Notice 83-41, "Actuation of Fire Suppression Sys Causing Inoperability of Safety-Related Equipment " Svc list enc! JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/22 Consolidated Edison Co. of New York, Inc. 120pp 18997 007 P4X Fithe 50-000,83/06/22,8305110477
- 8305110477 IE Info Notice 83-42. "Reactor Mode Switch Malfunctions " Bvc list encl JORDAN.L. L. Division of Lmongency Preparedness & Engineering Response (Post 830103) 83/06/23 Consolidated Edison (n of New York, Inc 116pp 18996 Pd.: 24X Fichs 50-000,83/06/23,8305110479
- 8306280490 Forwards SALP rept for evaluation period Dec 1781 ~ Nov 1982 Fire protection & housekeeping rating upgraded to Category 2 MRLEY, T E Region 1, Office of Director 83/06/23 CARLY, J J Duquesne Light Co 4pp 17019 187 24X Fiche 50-034, 83/06/23. 8306280490
- --8306280492 Forwards SALP rept conducted on 830124 for Dec 1981 Nov 1982 Meeting scheduled for 130215 at site to discuss assessment STAROSIECKI,R Division of Project & Resident Programs 83/02/0/ GAREY, J. Dinquesne Light Co. 2pp 19019 193 24X Fiche 50-334,83706/23,830648(M470)
- --8306280495 Responds to NRC 83020/ lfr re results of SALP Board review Reconsideration of rating given to Item 5, "Fire Protection & Housekeeping," requested CAREY, J J Duquesne Light Co. 83/03/08 HAYNES, R C. Region 1, Office of Director 7pp 19019 195 24X Fiche 50-334,83/06/23,830606040

- --8306280497 SALP rept for Det 1981 Nov 1982 * Region 1, Office of Director 89/01/24 32pp 19017 202 24% Fiche 50-334.83/06/23.8306200490
- 8305110483 IC Info Notice 83-43, "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints " 5vc list encl JORDAN, C. L. Division of Lawigency Preparedness & Engineering Response (Post 830103) 8370674 Combalidated Editon Co. of New York, Inc. 116pp 19046 297 24X Fiche 50-000.83706/24,8305110483
- R Periodic operating reports & related correspondence
- 8306020218 Monthly operating rept for Mar 1983 W/830406 ltr HGLTZ, J L , CAREY, J Duquerne Light Co 83/04/06 Office of Resource Management, Director 4pp 18690 269 24X Fiche 50-334, G3/04/06, 8306020;18
- 83061604/6 Monthly operating rept for Apr 1983 W/830505 ltr HOLTZ.JI, CARCY.JJ Dogosne Light Co 83/05/05 Office of Resource Management. Directo: Spp 10862:237 24X Fiche 50-334,63/05/05.83061604/6
- B306070120 NPDES monthly discharge monitoring repts for Apr 1983 M/B30525 ltr FEITHMECHT, C Duquesue Light Co 83/05/25 REID, R W Operating Reactors Branch 4 14pp 18739 282 24X Fiche 50-334,83/05/25,8304070120
- 8306300210 "NPDES Discharge Monitoring Rept for May 1983 " W/830627 1tr FEITKNECHT.C. STLED.L S Duquesne Light Co 83/06/24 REID.R W Operating Reactors Branch 4 14pp 19119 150 24X Fiche 50-334.83/06/24.8306300210
- 5 Reportable occurrences. Like & related correspondence
- 8304110818 Forwards LER 63-008/03L 0 LACEY.W B Duquesne Light Co 83/03/10 HAYNES,R C Region I. Office of Director 2pp 17919 334 24X Fiche 50-334,83/03/10, 8304110818
- --B304110B27 LER B3-008/03L-O on B3021B, during routine surveillance test on turbine driven auxiliory feedwater pump, pump packing overheated Caused by burr on follower rubbing pump shaft Follower hand dressed Pump repacked DRUGA, R J Duquesne Light Co B3/03/08 Region 1, Dffice of Director 2pp 17919 336 24% Fiche 50-334,63/03/10.6304110B18
- 8304010302 Updated LER 83-002/03X-1 on 830107,138 kV bus 1 lost Caused by inadvertent operation of bus pack-up timer relay Relay tested satisfactorily Cause of actuation unknown Possible causes listed W/830503 ltr
 LACEY.W 5 Duquesne Light Co 83/05/02 ALLAN, J M Region 1, Office of Director 4pp 19672 178 24X Fiche 50-334,83/05/02,
- 8306010295 Updated LER 81~083/03X-1 on 810906 nuclear instrumentation power range monitor N44 failed low due to power supply problems Power supply replaced Failed monitor sent to Mestinghouse for repair M/G30509 lt: LACEY.W S Duquesne Light Co 83/05/05 ALLAN.J M Region 1. Office of Director 4pp 18672 191 24X Fiche 50-334.83/05/05, P2044104305
- 8306020440 LER 83-013/03L-0 un 830505, during normal operation, chlorine detector B wick observed dry while electrolyte reservoir indicated full Caused by binding level indicator Indicator freed W/830519 itr
 LACEY, W S Duquesne Light Co 83/05/18 ALLAN, J M Region I, Office of Director 4pp 19649 187 24X Fiche 50-334, 83/05/18, 8306020440
- 8306020324 Updated LER B1-048/03X-1 on 810503, while putting RHR sys in operation, one RHR pump suction valve would not open Cause unknown Adjustment made to torque switch bypass limit switch & all wiring connections inspected W/830520 ltr LACEY.W S Duquesne Light Co 83/08/20 ALLAN.J.M Region 1, Office of Director App 18694 281 24X Fiche 50-324,83/05/20,8306020324
- 8306020383 Updated LER 81-042/0JX-1 on 310428, block valve MOV-RC-535 failed to shot as indicated by control room valve status light Cause undetermined Motor limit switch assembly replaced H/830520 ltr
 LACEY, W.S. Duquesne Light Co. 83/05/FO. ALLAN, J.M. Region 1. 0 Ffice of Director 4pp. 18494-356. 24X Fiche 50-334, 83/05/20, 833/05/3333

- 8306170030 Updated LER 83-014/03L-0 on 830803.monthly valve ricoke tests of refueling water storage tank to low head safety injection yamp suction valves not conducted Caused by deficiency in surveillance program W/S:/0601 ltr LACEY.W 8 Duquesne Light Co 83/06/02 ALLAN.J M Region 1, Office of Director 4pp 18078 287 24x Fiche 70-939,83/06/02,830A170300
- 8306200382 LER 83-012/03L-0 an 830509.15 & 14 core cooling monitor falled, rendering data retrieval impossible Gaused by broken card cage & defective card in spare core cooling monitor unit Card cage repaired W/830603 itr
 LACEY, W S Duquesne Light Co 83/06/03 ALLAN, J N Region 1.
 Office of Director 4pp 18699 012 24X Fiche 50-334,83/06/03,8306200382
- 8306210248 PNS-[-83-014 on 830615 control room received low seal flow alarm & lost indication of seal leak-off flow on reactor coalant pump IC Valve CH210 found closed Licenses intervisuing personnel working in containment area MCKEOHN.M . 000V, JOYMER Region 1, Office of Director 83/06/16 200 18915 251 24X Fichs 50-334,83/06/06,8306210248
- 9306290139 LER 83-015/O3L-O on 830524, during normal power operation, relay 51-VDJOAX experienced spurious actuation, causing inadvertent isolation of emergency bus 1DF from normal supply Caused by personnel error 8/830617 ltr LACEY, W S Duquesne Light Co 83/06/17 ALLAN, J M Region 1. Office of Director 4pp 19014-329 24X Fiche 50-334.83/06/17, 8306280139
- 8306230462 PNS-I-83-014A updates PNS-I-83-014 re possible equipment tampering on 830615 On 830617.FBI concluded no evidence of deliberate equipment tampering evident Valve probably inadversetantly closed BAILEY Region 1. Office of Director 63/06/20 ip 18741 328 24X Fiche 50-334.83/06/20.8306230462

V Operator Examinations

- 8306020042 Notification of 830609 significant licenses meeting in King of Prussia,PA to discuss qualifications for reactor operator licensing KELLER,R M Region 1, Office of Director 83/05/26 Region 1, Office of Director 83/05/26, 83/05/26, 83/05/2042
- 830&1400&2 Extends invitation to attend 830&27 meeting in King of Prussia:PA.to discuss transfer of reactor operator licensing function from Bethesda, MD to Region I of STAROSTECKI, R Division of Project & Resident Programs 83/06/09 CAREY, J J Duguesne Light Co 2pp 188:8 339 24X Fichs 50-334,83/06/09.8304140062
- DOCKET 50-335 ST LUCIE PLANT, UNIT 1

 F Security, medical, emergency & fire protection plans
- 8306140646 Confirms 830223 onsite enforcement meeting to discuss incident re vital area security door left ajar on 830104, per 830217 teleon Proposed meeting agenda enct 0'REILLY.J P Region 2. Office of Director \$3/07/18 UHRIG.R & Florida Power & Light Co 2pp 18841 240 24X Fiche 50-335.83/02/18.8306140646
- 8306140538 Forwards IE Insp Repts 50-335/83-06 & 50-389/83-20 on 830314-18 No mencempliance noted DANCE.H C Division of Project & Resident Programs 89/05/18 UMRIG.R E Florida Power & Light Co 2pp 18834.165 24X Fichs 50-335
- --8306140541 IE Insp Repts 50-335/83-06 & 50-389/83-20 on 830314-18 No noncompliance noted Major areas inspected emergency planning HUFFMAN.0.N Region 2. Office of Director JENKIN9.0 R Division of Emergency Preparedness & Materials Safety 83/05/17 App. 18834-167 24X Fiche 50-335.83/05/18.8306140838
- 8304140302 Forwards IE Insp Repts 50-335/83-18 & 50-399/83-41 on 830506. No noncompliance noted DANCE, M C Division of Project & Resident Programs 83/05/23 UNRIG, R E Florida Power & Light Ca 2pp 18832 098 24X Fiche 50-335,83/05/23,8304140382
- --8306140310 IE insp Repts 50-335/83-18 & 50-389/83-41 on 830506 No nancompliance noted Major areas inspected Emergency preparedness accountability drill HUFFMAN, 0 N Region 2, Office of Director JENKINS, 0 R Division of Emergency Preparedness & Naterials 84fety 83/05/19 App 18832,100 24X Fiche 50-335,83/05/23,8306140302

- 8306290209 Forwards IE Insp Rept. 50-335/80-17 & 50-389/83-39 on 830509-13 No noncompliance noted DANCE,H (Division of Project & Resident Programs B3/06/01 UHRIG,R E Florada Power & Ladut (a 2pp 19056 114 24x Fiche 50-335,84/06/01.8306290/09
- --B306290221 IE Insp Repts 50-335/B3-17 & 50-389/B3-57 on B30507-13 No noncompliance noted Major areas inspected enforcement responses, insp followup items, containment cable tray coverb App R electrical cable recounting HUNT, M D , CONLON, T E Region 2, Office of Director B3/05/26 App 19056 116 24X Fishe 50-335, B3/06/01, B306290209
- 8306140023 Releases public version of revised offnormal emergency plan implementing procedures
 FELTON, J.M. Division of Rule, and Records 83/06/06 Document
 Management Branch 1p 1883/166 24X fishe 50-335,83/06/06,
 8306140023
- --8305140033 Forwards public version of revised offnormal emergency plan implementing procedures, including Procedures 2-0030131 replant annunciator summary, P-0030141 re-control reominates sibility & 2-0440030 ru SDC/LP51 offnormal operation METHY, CM Florida Power & Light Co 83/05/17 Office of Nuclear Reactor Regulation, Director ip 18831 167 24X Fiche \$0-335,83/06/06,8306140073
- --8306140038 Public version of revised offnormal emergency plant implementing procedures, including Procedures 2-0030131 replant annunciator summary, 2-0030141 recontrol room inacessibility & 2-0040030 re SBC/UPGI offnormal operation * Florida Power % Light Co 83/05/12 263pp 19831 168 24X Fiche 50-335,83/06/06,8306140023
- 9306220225 Releases public vorsion of revised offnormal & emergency aperating procedures
 FELTON, J M Division of Rules and Records 83/06/06 Decument Management Branch 1p 189/7-167 24X Fiche 50-335,83/06/06, 8306220225
- --8306220230 Forwards public version of revised offnormal & emergency operating procedures, including Procedures 2-0030140 re blackout operation, 2-0030143 re total loss of power & 2-0250030 re emergency boration WETHY.C M Florida Power & Light Co. 83/04/27 Director's Office, Office of Inspection and Enforcement ip 1897/ IAS 24x Fiche 50-335,83/06/06,8306220205
- --8306220236 Public version of revised offnormal & emergency operating procedures, including Procedures 2-0030140 re blackout operator.2-0030143 re total loss of ac power & 2-0250030 re emergency boration * Florida Power & Light Co #3/04//6 Director's Uffice. Office of Inspection and Enforcement #7pp 189/7 149 24% Fiche 50-335,83/06/06.8306220225

J Insurance & indemnity information

- B306270103 Amend B to Indemnity Agreement B-76, adding Orlando Utils Commission of City of Orlando.FL as litensus BALT2MAN. J Assistant Director for State & Liconsce Relations B3/03/28 jp 18988 117 24% Fichs 50-335,83/03/28,8306270107
- 8306270128 Amend 9 to Indemnity Agreement D-76, adding Florida Municipal Flower Agency as licensee 8ALTZMAN, J. Assistant Director for Stata & Licensee Relations 83703/29 ip 18988-092 24X Fiche 50-335,83703/29,8306270128
- 8306270210 Unexecuted Amend 10 to Indomnity Agreement B-76, substituting listed litem 3 re license numbers SALTZMAN, J Assistant Director for State & Licensee Relations, 8304/06 Jp 18971 218 24% Fiche 50-335,83/04/06,8306270210
- P Operating license stage documents & correspondence
- 8306080[6] "Radiological Effluent Tech Specs (RETS) Implementation St Lucie Unit 1 Nuclear Generating Plant" SIMPSON.F B , SERRANO.W., DUCL.S W ECRG, Inc FIN A-6459 EGG-PHYS-6241 63/04/26 Division of Systems Integration (post 811005) 49pp 18789 279 24X Fiche 50-335,83/04/26,8306080161
- 8306140784 Notifies of review of Rev I to 830300 process control program Program contains necessary process parameters to boundary conditions to assure that dewatering of bead resin will be complete w/no free liquid Program acceptable KNIGHTUN, 9 M Licensing Blanch 3 83/05/10 UHRIG.R E Florida Power & Light Co 2pp 18845 331 24X Fiche 50-335,83/05/10.8306140784

- 8304080251 Forwards "Control of Heavy Loads (C-10) St Lucie Unit 1," draft technical rept.per util response to Section 2 1 of 801222 generic lti re NUREG-0612 Completion of review by 830617 requested CLARK.R A Operating Reactors Branch 2 83/05/24 UHRIG.R F Florida Power & Light Co 2pp 18787 137 24X Fichs 50-335,83/05/24,8306080251
- --8304080257 "Control of Heavy Loads (C-10) St Lucir Unit 1," draft technical evaluation rept BOMBERGER, C. AMMED.N. Franklin Institute/Franklin Research Center NRC-03-81-130 TCR-C5504-394 DRFT 83/04/29 CLEMENBON, F. NRC - No Detailed Affiliation Given 34pp 18787 141 24X Fiche 50-335,83/05/24,8304080251
- B306020046 Notification of B30603 meeting w/util & C E in Bethesda.MD to discuss loose parts monitoring sys & installed ex-core instrumentation
 BELLS.D F Operating Reactors Branch & B3/05/25 CLARK.R A
 Operating Reactors Branch & 2pp 18701 355 24X
 Fiche 50-335.83/05/25,8306020046
- 8304080094 Notice of consideration of issuance of amend to License DRR-67 & proposed no significant hazards consideration determination & opportunity for hearing re improved & larger capacity 125-volt do battory sys CLARK, R A Operating Reactors Branch 3 83/05/25 9pp 18789 327 24% Fiche 50-335,83/05/25,8304080094
- 8306140414 Informs that interim plan to reduce blocked position from 50 to 140 degrees acceptable pending review of 830/15 rept re out of plane upstream allow SRP 6 2 4 & Positions 6 & 7 of TMI Action 1tem il C 42 closed CLARK, R A Operating Reactors Branch 3 83/05/27 UHRIO.R E Florida Power & Light Co 6pp 18054 072 24X Fiche 50-335,63/05/27,8306140414
- B306160288 Notice of consideration of issuance of amend to License DPR-67 & proposed no significant hazards consideration determination & opportunity for hearing CLARK.R A Operating Reactors Branch 3 83/05/27 9pp 18893 001 24X Fiche 50 335.83/05/27.8306160288
- 8306100087 Discusses updated submittal dates for reactor vessel internals & thermal shield recovery programs as followup to safety assessment provided at 830603 meeting HRIGAR E Florida Power & Light Co 83/06/07 CLARK, R A Operating Reactors Branch 3 3pp 18002 23H 24X Fichs 50-335,83/06/07,8306100087
- 830.6210311 Requests FR publication of notice of consideration of issuance of amend to License DPR-67 & proposed no significant hazards consideration determination & opportunity for hearing resurveillance requirements CLARK, R A Operating Reactors Branch 3 83/06/13 CLARK, R A Operating Reactors Branch 3 83/06/13 CLARK, R A Fichs 50-335,83/06/13,8306210311
- B306170319 Notifies that vendor safety analysis to support installation of mods to auxiliary feedwater systeturned to vendor for reenalysis

 UHRIG.R E Florida Power & Light Cn B3/06/15 CLARK, R A

 Operating Reactors Branch 3 ip 18070 P16 P4X

 Fiche 50-935.89/06/15.8306170317
- 830,6290249 Advises that methodology used to calculate beta done for radiation profile for equipment qualification net acceptable Resubmittal of beta analysis based upon methodology in NURICO-058B required by B20630 CLARK. R A Operating Reactors Branch 3 83/06/17 Florida Power & Light Co 2pp 19046 116 24X Fiche 50-335,83/06/17,8306290247
- 8306280250 Forwards assessment of safety impacts of removal of thermal shield from facility, per 830419 commitment Assessment addresses Cycle & reload safety analysis of plant recovery program unalysis of plant recovery program UnRIG, R E Florida Power & Light Co 83/06/23 CLARK, R A Operating Reactors Brench 3 32pp. 17014 197 24X Fiche 50-335,83/06/23,8306280250
- 8306280356 Comments on plant recovery program to reactor vessel internals & thermal shield (gamma heating effect of removal of thermal shield) Gamma heating slight benefit to vessel integrity
 UHRIG: R E Floride Power & Light Co G3/06/23, CLANK, R A Operating Reactors Branch S. 2pp 19014 095 24X
 Fiche: 50-335,83/06/23,8306280356

- G Inspection reports: IE Bulletins & correspondence
- 8304140422 Submits confirmation of action ltr re 830411 telcon & 830203 mgt meeting on deficiencies in operating & emergency procedures Actions to be taken to correct deficiencies listed O'REILLY, J.P. Region 2. Office of Director 83/04/11 ADDMAT, E.A. Florida Power & Light Co. 2pp. 18843 007 24X Fiche 50-335, 83/04/11, 8304140622
- 8306140343 Forwards IE Insp Rept 50-335/80-14 on 830425-27 No noncompliance noted DANCE, H C Division of Project & Resident Programs 83/05/17 UHRIG.R E Florida Power & Light Co 2pp 18832 176 24X Fiche 50-335.83/05/17.8306140343
- --8306140347 IE Insp Rept 50-335/83-14 on 830425-27 No noncompliance noted Major areas inspected inservice insp review of program procedures; observation of work & LER followup KLEINBORGE, W P , BLAKE, J J Region 2. Office of Director 83/05/12 Spp 18832 178 24X Fiche 50-335,83/05/17,8306140343
- 8304140538 Forwards IE Insp Repts 50-335/83-06 & 50-389/83-20 on B30314-18 No noncompliance noted DANCE.H C Division of Project & Resident Programs 83/05/18 UHRIG.R E Florida Power & Light Co 2pp 18834 145 24X Fichs 50-335,83/05/18,8306140538
- --8306140541 IE Insp Repts 50-335/83-06 & 50-389/83-20 on 830314-18 No noncompliance noted Major areas inspected amergency planning HUFFMAN, 9 N Region 2, Office of Director JENKINS, 9 R Division of Emergency Preparedness & Materials Safety 83/05/17. App 18834 167 24X Fiche 50-335,83/05/18,8306140538
- 830.6140190 Forwards IE Insp Rept 50-335/83-16 on 830426-29 No noncompliance noted DANCE, H C Division of Project & Resident Programs 83/05/19, UHRIG, R E Florida Power & Light Co 2pp 18833 038 24X Fiche 50-335,83/05/19,8306140190
- --8306140196 IE Insp Rept 50-335/83-16 on 630426-29 No noncompliance noted Major areas inspected periodic integrated leak rate test & exam of test condition & test performance & results WHITENER, H L Region 2, Office of Director JAPE, F. Division of Engineering & Radiological Safety Programs 83/05/18. App 18833 040 24X Fiche. 30-335,83/05/19.8306140190
- 8306140302 Forwards IE Insp Repts 50-335/03-18 & 90-389/83-41 on B30504 No noncompliance noted DANCE:H C Division of Project & Resident Programs B3/05/23 UHRIG:R C Florida Power & Light Go 2pp 18832.098 24X Fichs 50-335,83/05/23.8306140302
- --B306140310 IE Insp Repts 50-335/83-18 % 50-389/83-41 on 830506 No noncompliance noted Major areas inspected amergancy preparedness accountability drill HUFFMAN. G N Region 2. Office of Director JENKINS, G R Division of Emergancy Preparedness & Materials Bafety B3/05/19. App. 18832 100 24X Fiche 50-335, B3/05/23, 8306140302
- 830 5110458 IE Info Notice 83-32. "Ruptured Am-241 Sources Contained in Well Logging Device" Svc list and I Info Market Programs (Post TAYLOR, J H Division of Safeguards & Inspection Programs (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc. 125pp 18831 043 24X Fiche 50-000,83/05/26,8305110458
- 8305110460 IE Info Notice 83-34. "Event Notification Info Worksheet"
 Svc list encl
 JORDAN, E. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/05/26 Consolidated Edison Co of New
 York, Inc. 115pp 18732,085 24X Fiche 50-000,83/05/26.8305110460
- 830.6140640 Documents concurrence w/util actions taken in response to B30411 Confirmation of Action Ltrs CAL-335/83-01 & 389/83-01 Insp during who of 830516 concluded that Unit 2 procedures adequate for startup & operation O'REILLY, J. P. Region 2, Office of Director 83/05/27 ADOMAT, E A Florida Power & Light Co 2pp 18841 161 24X Fiche 50-335,83/05/27,8306140640
- 8305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods Withdrawn at BWRs." Svc list encl. JORDAN:E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/31 Consolidated Edison Co. of New York, Inc. 116pp. 18732 208 24X Fiche 50-000,83/05/31,8305110461
- 8306290209 Forwards IE Insp Repts 50-335/03-17 & 50-369/03-39 on 830509-13 No noncompliance noted DANCE.H C Division of Project & Resident Programs 83/06/01 UHR19.R E Florids Power & Light Co. 2pp 19056 114. 24X Fiche 50-335.83/06/01.8306290209

- --8306290221 IE Insp Repts 50-335/83-17 & 50-389/83-39 on 830509-13 No moncompliance noted Major areas inspected enforcement responses, insp followup items containment cable tray covers & App R electrical cable rerouting HUNT, M D. COMLON, T E. Region 2, Office of Director. 83/05/26 App 19056 116 24X Fiche 50-335.83/06/01.8306290209
- 8306290398 Respands to IE Bulistin BD-00, "Check Valve Failures in Raw Mater Cooling Sys of Diesel Generators " Closed copling radiator sys contains no check valves Bulletin mot applicable
 UHRIGAR E Florida Power & Light Co 83/06/08 0'REILLY, J P
 Region 2, Office of Director 2pp 19052 183 24X
 Fiche 50-000.83/06/08.8306290398
- 8305110444 IE Info Notice 83-34. "Impact of Security Practices on Safe Operations "Syc list enc! JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83702/09 Consolidated Edison Co. of New York, Inc. 117pp 18830 280 24X Fiche 50-000,83/06/09,8305;10464
- 8305110470 IE Info Notice 83-38. "Defective Heat Sink Adhesive & Seismically Induced Chatter in Relays Within Printed Circuit Cards " Svc list entl JORDAN EL Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co of New York, Inc. 118pp 18720 225 24X Fichs 50-000,83/06/13.8305110470
- 8305090010 IE Info Notice 83-37, "Transformer Failure Resulting From Degraded Internal Connection Cables" Svs list encl JORDAN.E L Division of Emergency Preparedness & Engintering Response (Post 930103) 83706/13 Consolidated Edison Co of New York, Inc. 243pp 18921 001 24X Fiche 50-000.83/04/13.8306090010
- 8306270327 Ack receipt of 830420 ltr informing NRC of steps taken to correct violations noted in 16 Insp Rept 50-335/82-36 B3/06/17 URIO.R E Fiorida Power & Light Co 10 19050 194 24X Fichs: 50-335,83/06/17,8306290327
- --8306290338 Supple 830106 response to NRC 821207 ltr re violations noted in IE Insp Rept 90-335/82-36 Corrective actions employee responsibilities during procedure control & maint implementation emphasized URRIO.R E Florida Power & Light Co 83/04/20 O'REILLY, J.P., Ragion 2, Office of Director ip 19050 195 24X Fiche, 50-336,83/06/17,8306290327
- --8306270351 Responds to NRC 821207 ltr re violations noted in IE Insp Rept 50-335/82-36 Corrective actions caution tags bung & valves closed at time of notification on 821008 Responsible dept will be notified when restricted equipment installed UMRIG.R E Florida Power & Light Co 83/01/06 O'RESLLY, J P Region 2. Office of Director 2pp 19050 196. 24X Fiche 50-335, 83/06/17, 8306290327
- --8306270359 Forwards IE Insp Repts 50-335/82-36 & 50-389/82-55 on 821011-1110 & notice of violation DANCE.H C Division of Project & Resident Programs 82/12/07 UHRIO.R E Florida Power & Light Co 2pp 19050 198 24X Fichs 50-335,83/06/17.8306270327
- --8306290368 Notice of violation from insp on 821011-1110

 * Region 2, Office of Director 82/12/07 ip 19050.200 24X
 fichs 50-335,83/06/17,8306290327
- --8306290379 IE Insp Repts 50-335/82-36 & 50-369/82-55 on 821011-1111.
 Noncompliance noted use of unqualified math in emergency diesel gamerator lube oil sys EEROD, 8 A , BBS, HE Region 2, Office of Director JULIAN, C A Division of Project & Resident Programs 82/12/06 11pp 19050, 201 24X Fiche 50-335, 83/06/17, 8306290327
- 8305110475 IE Info Notice 83-40, "Need to Environmentally Qualify Epoxy Grouts & Sealers," Syc list encl.

 JURDAN, E. D. Division of Emergency Preparedness & Engineering Response (Post 830103), 83/06/22 Consolidated Edison Co. of New York, Inc. 115pp 19021.179 24X Fishe 50-000,83/06/22,8305110475
- 8305110477 IE Info Notice 83-41. "Actuation of Fire Suppression Sys-Causing Inoperability of Bafety-Related Equipment," Syc list and JORDAN, E. Division of Emergency Preparedness & Engineering Response (Fost 830103) 83/06/22 Consolidated Edison Co. of New York, Inc. 120pp. 18797.007. 24X Fiche-50-000,83/06/22.8305110477
- 8305110479 IE Info Notice 83-42, "Reactor Mode Switch Melfunctions "
 Svc list encl
 JORDAN, E.L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/06/23, Consolidated Edison Co. of New
 York, Inc. 114pp 18996-242 24X Fiche 50-000.83/06/23.8305110479

- 8305110483 IE Info Notice 83-43, "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints " Svc list enr l JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/24 Consolidated Edison Co. of New York, Inc. 116pp 19046-297 24X Fishe 50-000, 83/06/24, 83051(480)
- R Periodic operating reports & related correspondence
- 8304020216 Monthly operating repts for Mar 1983 W/830415 ltr PACE.P L . WILLIAMB.J W Tlorida Power & Light Co 83/04/15 Office of Resource Management, Darector 13pp 18670 256 (24) Fiche 50-000.883/04/15.8306020216
- 8306160638 Monthly operating repts for Apr 1983 W/830516 ltr PACE.P L . WILLIAMS.J W Florida Power & Light Co 83/05/16 Office of Resource Management. Director 17pp 18866 105 74 Fiche 50-000.83/05/16.8306160638
- S Reportable occurrences, LERs & related correspondence
- 8306140683 Part 21 rept supplementing 830506 notification of potential significant safety hazard re matl defects in staintess steel tubing pressure boundary component Ultrasonic exam shows assemblies acceptable per ABM. Godo. Section 111 SCHERER. A E Combustion Engineering. Inc 83/06/07 BEYBUNG. R C Director's Office. Office of Inspection and Enforcement 1p 18842 066 24% Fiche 50-335,83/06/07.8706140683
- V Operator Examinations
- 8304140745 Discusses shift staffing at facilities Util intends to initially operate Unit 2 & continue Unit 1 operations w/five full shifts of licensed operators on each unit Planned actions for filling vacant positions provided UHRIG.R E Florida Power & Light Co 83/06/03 EISENNUT.D Q Division of Licensing 3pp 18841 192 24X Fiche 50-335.83/06/03.8306140745
- 8306140572 Forwards revised Shift staffing chart based on 830606 notification that seven licenses candidates received reactor operator licenses UHRIG.R E Florida Power & Light Co 83/06/07 EISENBUT.B & Bivision of Licensing 2pp 18844 149 24X Fiche 50-335.83/06/07.8306140572
- DOCKET 50-336 MILLSTONE NUCLEAR POWER STATION, UNIT 2

 F. Sacurity, medical, emergency & fire protection plans
- 8306070136 Forwards Rev 16 to modified amended security plan Rev withheld (ref 10CFR2 790 & 10CFR73 21)
 COUNSIL W G Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL W G Northeast Utilities 03/05/12
 ALLANJ M Region i. Office of Director ip 18/39/215 24x
 Fichs.50-245,03/05/12,8304070134
- 8304040154 Provides add1 info re util request for exemption from 10CFR50. App R re control room fire per 030318 mosting Alternate operator actions can be completed to facilitate safe shutdown following fire in control boards COUNSIL.W O Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL.W O Northeast Utilities 63/05/25 EISEMPUT.D C Division of Licensing 31pp 18719 156 P4X Fiche 50-336,83/05/25,8306060154
- 8306090238 Forwards IE Insp Repts 50-245/83-11 & 50-336/83-13 on 830417-0507 No noncompliance noted STAROSIECKI, R Division of Project & Resident Programs 83/05/27, COUNSIL W 9 Northeast Nuclear Energy Co (subs of Northeast Ut(11ties) 2pp 18795 299 24X Fiche 50-245,83/05/27,8306070238
- --B306070241 IE Imap Repts 50-249/83-11 & 50-336/83-13 on 830417-0507 No noncompliance noted Major areas inspected evaluations of plant operations, startup testing, equipment alignments & readiness, radiation protection & physical security SHEDLOSKY, J T Region 1, Opfice of Director 83/05/20 17pp 18795 301. 24X Fiche 50-245,83/05/27,8306090238
- 8306200307 Ack receipt of 830225 & 0415 ltrs informing NRC of steps taken to correct violations noted in IE Insp Repts 30-245/83-01 & 50-336/83-01 Confirms understanding that uninterruptable power supply sys was operable by 830501 MARTIN, T T Division of Engineering & Technical Programs B3/06/15 COUNSIL.W @ Northeast Nuclear Energy Co (subs of Northeast Utilities). 2pp 18900 164 24X Fiche 50-245,83/06/15,8306200307

- ~~8306200313 Responds to NRC ltr re violations noted in HE Insp Repts 50-245/83-01 & 50-336/83-01 Forwards info requested during HE security insp Info withheld (ref 10CFR2 21 & 10CFR2 790) COUNSIL.W G Northeast Nuclear Energy Co (subs of Northeast Utilities) B3/02/25 HAYNES;R C Region 1, Diffice of Director 1p 18900 166 24X Fiche 50-245,83/06/15,8306200307
- --B306200322 Responds to NRC It; re violation noted in IE Insp Repts 50-245/83-01 & 50-336/83-01 Forwards info requested during IE security insp Info withhold (ref 10CFR73 21 & 10CFR2 /90) COUNSIL.H & Northeast Nuclear Energy Co (subs of Northeast Northeast Nuclear Energy Co (subs of Northeast 83/04/15 ALLAN, J M Region 1, Office of Director 167 24X Fiche 50-245,83/06/15,8306200307 Utilities) 0: Ip 19900 147

H General correspondence

- 8304060090 Requests rev to "cr" distribution list for NRR correspondence reflecting position & title changes within utils
 - utils
 COUNSIL,W G Connecticut Yankee Atomic Power Co COUNSIL,W G
 Northeast Utilities COUNSIL,W G Northeast Nuclear Energy Co
 (subs of Northeast Utilities) 83/05/31 CLARK,R A Operating
 Reactors Branch 3 CRUTCHFIELD,D D Operating Reactors Branch 5
 3pp 18/19 360 24X Fiche 50-000.83/05/31.8306040090
- P Operating license stage documents & correspondence
- 8306020642 Summary of 830504 meeting w/util & Westinghouse in Bathesda.MD re steam generator alsoving Request for Tech Spec changes expected by 830601 LEECH.P H Operating Reactors Branch 3 83/05/17 CLARK.R A Operating Reactors Branch 3 26pp 18716 278 24X Fiche 50-336.83/05/17.8306020642
- 830.6010340 Forwards Rev 13 to corporate organization for nuclear incidents procedures manual table of contents & Rev 3 to CONI 4 02, "On-Call Manager of Radiological Consequence Assessment, Responsibilities & General Guidelines "M/D encl CQUNSIL.W 9 SEARS.C F Connecticut Yankee Atomic Power Co CQUNSIL.W 9 Northeast Nuclear Energy Co (subs of Northeast Utilities) 83.705/18 EIBCNNUT.D 6 Division of Licensing 1p 18682 271 24% Fiche 50-000.83/05/18.8304010340
- 8304030012 Forwards SER re thermal shield & support sys Continued operation until 830528 scheduled shutdown justified Requests findings re 10-yr inservice insp of shield & barrel assembly
 - components
 CLARK,R A Operating Reactors Branch 3 83/05/18 COUNBI Northeast Nuclear Energy Co (subs of Northeast Utilities) 18733 141 24X Fiche 50-336,83/05/18,8306030012
- --8305030016 Safety evaluation supporting continued operation w/thermal shield & support sys
 * NRC No Detailed Affiliation Given 83/05/18 3pp
 18733 143 24% Fiche 50-836.83/05/18,8306030012
- 8306060098 "Environ Qualification of Safety-Related Electrical Equipment "
 COUNSIL.W 9 , SCARS.C F Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL.W 9. Northeast Utilities 82/05/20 EISENHUT, D 9 Division of Licensing 71pp 18723 001 24X Fiche 50-334,83/05/20.8304060098
- 8304060092 Advises that requirements of NURE9-0737, Item II. B 2 re plant shielding for vital areas will be mot when mods described in encl safety evaluation implemented Review of corrective actions completed CLARK, R A Operat actions completed CLARK,R A Operating Reactors Branch 3 83/05/24 COUNSIL, Northeast Nuclear Energy Co (subs of Northeast Utilities) 18751-253 24% Fiche 50-336,83/05/24,8306060092 COUNSIL, W C
- 8306130491 Ack receipt of 830503 ltr requesting Total Axial Shape Index utilized in safety analyses be withheld from public disclosure (ref 100FR2 790) Request approved CLARK,R A Operating Reactors Branch 3 83/06/01 COUNSIL,W O Northeast Nuclear Energy Co (subs. of Northeast Utilities) App 18830 140 24% Fiche 50-336,83/06/01.8306130491
- 8304080431 Notifies that util B30425 ltr informing NRC that technical evaluation rept re environ qualification of safety-related electrical equipment no longer proprietary.

 CLARK.R A Operating Reactors Branch 3 B3/06/03 BAILEY.I Division of Technical Information & Document Control ip 18792 188 24X Fiche 50-336,83/06/03.8306080431.

- 8306140352 Relgases, for public disclosure. 830406 technical evaluation rept re resolution of outstanding lisues from environ qualification SERs F-11 & B-60 for facility per 830425 util CLARK,R A Operating Reactors Branch 3 83/06/03 BAILEY,I Records Services & Facilities Branch 1p 18835 001 24X Fiche 50-336,83/06/03.8306140352
- --8306140361 Responds to B30406 SER re environ qualification of electrical equipment for facility Corresponding technical evaluation rept contains no proprietary info & can be retraced for public disclosure.per 1007R2 790
 CDUNSIL,W G Northeast Nuclear Energy Co (subs of Northeast Utilities) CDUNSIL.W O Northeast Utilities B3/04/25
 CLARK.R A Operating Reactors Dranch 3 2pp 18835 002 24X
 Fiche 50-336.83/06/03.8306140352
- --B3022503B1 "Review of Licensee Resolution of Outstanding Issues From NRC Equipment Environ Qualification SERs (F-11 & D-60)," nonproprietary technical evaluation rept TOMAN.O J Franklin Institute/Franklin Research Center NRC-03-79-11B TER-C8237-467 B3702/21 SHEMANSKI.P NRC No Detailed Affiliation Given 669pp 18936 001 24X Fiche 50-336.83/06/03.8306140352.
- 8306160283 Notice of consideration of issuance of amends to Licenses DPR-21 & DPR-65 & proposed no significant hazards consideration determination to apportunity for hearing CLARK, R A Operating Reactors Branch 3 83/06/03 10pp 18893 010 24X Piche 50-245,83/06/03,8306160283
- 8306270255 Application for amend to License DPR-65, revising Tech Specs re repair of defective steam generator tubes through plugging or sleeving COUNSILW 0 Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSILW 0 Northeast Utilities B3/06/03 CLARK, A Operating Reactors Eranch 3 4pp 18989 162 24X Fiche 50-336,83/06/03.8306270255
- --8306270258 Proposed Tech Spec rev re repair of defective steam generator tubes through plugging on sleeving * Northeast Utilities 83/06/30 268pp 18989,167. 24X Fiche 50-336-83/06/03.8306270255
- B306160412 Forwards draft Rev 5 to "GA Program Topical Rept "
 COUNSIL.H 0 Northeast Utilities Bervice Co. COUNSIL.H.O
 Northeast Utilities B3/06/09 MURLEY.T E Region 1. Office of
 Director App. 18899 090 24X Fiche 50-000.83/06/09.8304160412
- --8306160424 Draft Rev 5 to "GA Propram Topical Rept "
 * Northeast Utilities 83/06/09 135pp 18859,096 24X
 Fichs 50-000,83/06/09,8306160412
- 8306200278 Forwards request for add1 info on methodology of analyses re reload Cycle 6. to complete review of 830413 submitta) Response requested by 830701 CLARK.R A Operating Reactors Branch 3 83/06/10 COUNBIL, H. G Northeast Nuclear Energy Co (subs of Northeast Utilities) 4pp, 18909 389 24X Fiche 50-336,83/06/10,8306200278.
- 8304240200 Forwards listed revs to Corporate Organization for Nuclear Incidents procedure manual per Section V of App E to 10CFR50 W/o encl
 GOUNBIL, W Q Connecticut Yankes Atomic Power Co COUNBIL, W Q
 Northeast Nuclear Energy Co (subs of Northeast Utilities),
 GOUNBIL, W Q Northeast Utilities, 83/06/17 EISENHUT, D Q
 Division of Licensing 2pp 18980-263 24X Fiche, 50-000, 83/06/17,
 B306240200
- 8305290152 Requests FR notice of consideration of issuance of smend to SUBSTRICT REQUESTS P. NOTICE OF CONSIDERATION OF ISSUANCE OF SAME Licenss DPR-65 & proposed no significant hazards consideration & opportunity for hearing re insp of hydraulic snubbers Hazards determination available in Central Files. CLARK, R. A. Operating Reactors Branch 3. 83/06/22 KREUTZER, P. M. Operating Reactors Branch 3. 3pp 19046 266 24X Fiche 50-334, 83/06/22, 8308/290152
- 8306300140 Informs that addit nondegree personnel will be assigned to shift technical advisor position per NUREO-0737. Item
 I A. 1 i Info re experience, college aduc & current operator licenses encl.
 COUNBIL,W 0. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). COUNBIL,W 0. Northeast Utilities. 82/06/22
 CRUTCHFIELD, D. Operating Reactors Branch 5. CLARK.R.A. Operating Reactors Branch 3. 3pp 19122: 320. 24X Fiche: 50-245.83/06/22.8306300140

- O Inspection reports: IE Bulletins & correspondence
- B306030012 Forwards BER re thermal shield & support sys.Continued operation until B30528 scheduled shutdown justified Requests findings re 10-yr inservice insp of shield & barrel assembly
 - components
 CLARK,R A Operating Reactors Branch 3 83/05/18 CDUNSIL,W G
 Northeast Nuclear Energy Co (subs of Northeast Utilities) 2pp.
 18733 141 24 Fichs 50-336,83/05/18,8306030012.
- 8306060160 Forwards IE Inse Repts 50-245/83-06 & 50-336/83-08 on 830227-0416 & notice of violation STAROSTECKI.R Region 1. Office of Director. 83/05/83 COWRSTL.W 9 Northwast Nuclear Energy Co (subs of Northwast Utilities) 2pp 18719 205 24X Fiche 50-245,83/05/23,8306060160
- --8304040145 Notice of violation from insp on 830227-0414.

 # Region 1, Office of Director 83/05/23 ip 18719.207 24% Ficha 50-245,83/05/23,8304040140
- --8306060171 IE Insp Repts 50-245/83-06 & 50-336/83-08 on 830227-0416 Noncompliance noted failurs to maintain reactor power below 89% while monitoring core linear aret rate w/ex-core detector monitoring sys BHEDLOSKY, J T., LIPINSKI, D.R., ELSABSER, T C. Region i, Office of Director 83/05/21. 19pp. 18719 208. 24X Fiche 50-245.83/05/23, 830&040160.
- 8305110458 IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in Well Logging Device." Syc list encl TAYLOR.J M Division of Safeguards & Inspection Programs (Post 830103) 83005726. Consolidated Edison Co. of New York
- 8305110460 lE Info Notice 89-34, "Event Notification Info Horksheet " Byc list encl
 JORPAN,E L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) B3/05/26 Consolidated Edison Co of New
 York, Inc. 115p 18732'085 24% Fichs 50-000,83/05/26.8305110460
- 8306090238 Forwards IE Insp Repts 50-245/83-11 & 50-336/83-13 on 830417-0507. No noncompliance noted, 874RDSTECKIR Division of Project & Resident Programs 83/05/27 COUNBIL W G. Northeast Nuclear Energy Co. (subs of Northeast Utilities). 2pp. 18795 299, 24X Fiche 50-245,83/05/27,8306090238
- --8304090241 IE Imap Repts 50-245/83-11 & 50-334/83-13 on 830417-0507 No noncompliance noted Major areas inspected evaluations of plant operations startup testing equipment alignments & readiness radiation protection & physical security BHEDLOSKY, J. T., LIPINSKI, D. R., Region I., Office of Director, ELSABBER, T. C., Division of Project & Resident Programs 83, 17pp 18795, 301. 24x Fiche: 50-245, 83/05/27, 8306070238, 83/05/20.
- 8305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods Withdrawn at BWRs " Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/31. Consolidated Edison Co. of New York, Inc. 116pp. 18732 208 24X Fiche 50-000,83/05/31,8305110461.
- 8306170391 Responds to IE Bulletin 83-03, "Check Valve Failures in Raw Water Conling Sys of Diesel Generators " No check valves installed in loop of piping to diesel generators from svc installed in loop or paping to treet generally and for Northeast Mutlear Energy Co. (subs. of Northeast Utilities). COUNBIL.H.O. Connecticut Vanise Atomic Power Co. COUNBIL.W.O. Northeast Utilities 83/05/31 MURLEY, T. E. Region i, Office of Director. 3pp. 18880-240 24X Fichs. 50-000, 83/05/31,
- 8306140352 Ruleases, for public disclosure, 830406 technical evaluation rapt re resolution of outstanding issues from environ qualification SERs F-11 & 8-60 for Pacility per 830425 util ltr CLARK.R.A Operating Reactors Branch 3 93/06/03, BAILEY.I. Records Services & Facilities Branch 1p. 18835,001 24X Fiche 50-336,83/06/03.8306140352
- --8302280381 "Review of Licenses Resolution of Dutstanding Issues From NRC Equipment Environ Qualification SERs (F-11 & B-60)," nonproprietary technical evaluation rept.
 TOMAN.O.J Franklin Institute/Franklin Research Center NRC-03-79-118. TER-05257-467. 83/02/21. SHEMANSKIP NRC No Detailed Affiliation Given 649p. 18836-001. 24X Fiche. 50-336, 83/06/03, 8306140362
- 8305110464 IE Info Notice 83-36, "Impact of Security Practices on Safe Operations." Svc list encl.
 JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 930103). 83/06/09. Consolidated Edison Co of New York, Inc. 119pp. 16830.280. 24X Ficher 50-000,83/06/09.8305110464.

- 830.6230215 Forwards IE Insp Rept 50-336/83-14 on 830518-20 No nancompliance noted MARTIN, T.T. Division of Engineering & Technical Programs 83/06/16 COUNSIL, W.G. Northeast Nuclear Energy Co. (subs. of Northeast Utilities) 2pp 18945 255 24X Fiche 50-336.83/06/10.8306230215
- --8306230216 IE Insp Rept 50-336/83-14 on 830518-20 No noncompliance noted Major areas inspected licensee planning for outage review of selected areas of radiation protection program MINITY.R.L., SHANBARY.M M Region 1. Office of Director 83/06/08 7pp 18945 257 24X Fiche 50-336,83/06/10
- B305110470 IE Info Notice B3-38. "Defective Heat Sink Adhesive & Seismically Induced Chatter in Relays Within Printed Circuit Cards " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) 83/06/13 Consolidated Edison Co of New York: Inc 118pp. 18920 225 24% Fiche 50-000,83/06/13.8305110170
- 8304090010 IE Info Notice 83-37. "Transformer Failure Resulting From Degraded Internal Connection Cables" Syc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co. of New York, Inc. 243pp 18921 001 24X Fiche 50-000,83/06/13,8306090010
- 8304200307 Ack receipt of 830225 & 0415 ltrs informing NRC of steps taken to correct violations noted in IE Insp Repts 30-245/83-01 & 50-336/83-01 Confirms understanding that uninterruptable power supply eys was operable by 330501 MARTIN.T T. Division of Engineering & Technical Programs. 83/06/15 COUNSIL, W G Northeast Nuclear Energy Co (subs of Northeast Utilities) 2pp, 18900 164 24X Fiche 50-245,83/06/15,8306200307
- --8306200313 Responds to NRC ltr re violations noted in IC Insp Repts 50-245/83-01 & 50-336/83-01 Forwards info requested during IE security insp Info withheld (ref 10CFR73 21 & 10CFR2 790) COUNSIL, W.C. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). COUNSIL, W.C. Northeast Utilities 83/02/25 HAYNES, R.C. Region I. Office of Director ip 18900 166 24X Fiche. 50-245, 83/06/15, 8306200307
- --8306200322 Responds to NRC ltr re violation noted in IE Insp Repts 50-245/93-01 & 50-336/83-01 Forwards info requested during IE security insp Info withhold (ref 100FR73 21 & 100FR2.790).

 COUNSIL.W G. Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNBIL.W G. Northeast Utilities 83/04/15 ALLAN.J M. Region 1, Office of Director 1p 18700 167 24% Fichs 50-245,83/04/15,8306800307
- 8308110475 IE Info Notice 83-40, "Need to Environmentally Qualify Epoxy Grouts & Sealers " Byo list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/22 Consolidated Edison Co 19021 179 24X Fiche 50-000, 83/06/22, 8305110475
- 8305110477 IE Info Notice 83-41, "Actuation of Fire Suppression Sys-Causing Inoperability of Safety-Related Equipment " Syc list encl
 JORDAN, E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/06/22 Consolidated Edison Co of New
 York, Inc 120pp 18997 007 24X Fiche 50-000,83/06/22,830510477
- 830A280414 Notifies that entire core will be off-loaded during current refueling outage to affect 10-yr inservice insp program retailed fuel impact on Cycle & safety analyses Fuel sipping performed to detect defective cladding GDUNBIL,W G Northeast Nuclear Energy Co (subs of Northeast Vtilities) CDUNBIL,W G Northeast Utilities B3/06/22 CLARK,R A. Operating Reactors Branch 3 3pp 17020 273 24X Fiche 50-336,83/06/22,8306280414
- 830.6290152 Requests FR notice of consideration of issuance of amend to License DPR-65 & proposed no significant hazards consideration & opportunity for hearing re insp of hydraulic anubbers Hazards determination available in Central Files CLARKER A. Operating Reactors Branch 3 83/06/22 KREUTZER.P.M Operating Reactors Branch 3 89 17046 266 24X Fiche 50-336,83/06/22,8306290152
- 8305110479 IE Impo Notice 83-42, "Reactor Hode Switch Majfunctions" Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/23 Consolidated Edison Co of New York, Inc. 116pp. 18994-242, 24X Fiche: 50-000, 83/06/23, 8305110479
- B305110483 IE Info Notice B3-43, "Improper Bettings of Intermediate Range (IR) High Flux Trip Setpoints " Svc list encl. JORDAN,E. L. Division of Emergency Preparedness & Engineering Response (Post B30103). B3/06/24 Consolidated Edison Co of New York, Inc. 116pp. 19046 297. 24X Fiche 50-000,83/06/24,6305110483

- A Periodic operating reports & related correspondence
- 8306020077 Monthly operating rept for Mar 1983 W/830415 1tr 91880N.J., MROCZKA,E J. Northeast Nuclear Energy Co. (subs. of Northeast Utilities) MROCZKA,E J. Northeast Utilities 83/04/13 Office of Resource Management. Director 7pp 18691 203 24X Fiche 50-336.83/04/13.8306020077
- S Reportable occurrences, LERs & related correspondence
- 8306020397 RO 83 02 on 830223, excessive levels of activity observed in sample of mussels bose consequences evaluated for First Quarter 1983 by using effluent transport models No operational corrective actions necessary MROCZKA, L. J. HERBERT, R. J. Northeast Nuclear Energy Co. (subs. of Northeast Utilities) MRCZKA, L. J. Nurtheast Utilities 83/05/24 MURLEY, T. E. Region i. Office of Director. 3pp. 18695 100 24% Fiche 50-245,83/05/24,8306020397
- B3061700A2 LER B3-01B/03L-Q on B30506, reactor protection sys Channel A.

 low steam generator pressure bypass removal setpoints found
 out of spec Caused by instrument drift due to high
 sensitivity to changes in input resistance W/B30602 ltr
 DESLANDES, K D. MROCZKA, E J. Northeast Nuclear Energy Co (subs of
 Northeast Utilities) DESLANDES, K D. Northeast Utilities
 B3/06/02 MRRLEY, T E Region 1, Dffice of Director 2pp
 18882-223 24% Fiche 50-036, B3/06/02, B306170042
- B306200104 Advises of GA verification of 030413 ltr re reevaluation of steam generator tube rupture event in support of Cycle 6 ageration verification confirms conclusions COUNSIL.W G Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL.W G Northeast Utilities B3/06/03 CLARK.R A Operating Reactors Deanch 3 lp 18703 284 24X Fiche 50-336,83/06/03.8306200104
- B3Q6280231 LER B3-020 ongoing eddy current exams identified number of steam gamerator tubes w/defects which required both steam generators to be placed in C-3 insp category Frequency of occurrence primarily on cold leg side
 MROCZKA.E J Northeast Nuclear Energy Co (subs of Northeast Utilities) MROCZKA.E J Northeast Utilities 83/06/13
 MURLEY.I E Region i, Office of Director 1p 19015 040 24X
 Fiche 50-336,83/06/13,8306280231
- B306230001 PNS-I-83-015 on 830616 unannounced narcotics search of site initiated & one mariyuana cigarette found in pocketbook belonging to contract security watchperson Individuals employment terminated MADBEN, W., GODY, A., JOYNER, J. Region 1, Office of Director 83/06/17 p 18947 077 24X Fiche 50-245.83/06/17.8306230001
- 8306280383 Updated LER 82-037/03L-1 on 820702, blocking valve 2-RC-403 would not close Caused by Limitorque Type SMB000 torque switch out of adjustment Switch readjusted & tightened Stroke test completed in hot standby WH306417 Itr FOSTER, E.R., MROCZKA, E.J. Northeast Nuclear Energy Co (subs. of Northeast Utilities) MROCZKA, E.J. Northeast Utilities 83/06/17 MURLEY, T.E. Region i. Office of Director 2pp 17001 316 24% Fiche 50-336, 83/06/17, 8306280353
- B396280430 LER 83-019/03L-0 on 830528, following reactor trip from 40% power, surveillance testing indicated activity of greater than 1.0 uCi per gram dose equivalent I-131 in primary coolant Caused by degraded fuel pins W/830618 ltr BORCHERT,R, MROCZKA,E J. Northeast Nuclear Energy Co. (subs. of Northeast Utilities) MROCZKA,E J. Northeast Utilities B3/06/18 MRUCZKA,E J. Northeast Utilities B3/06/18 MRUCZKA,E J. Spp. 19018 337 24% Fiche 50-336,83/06/18,8306280430
- ♥ Operator Examinations
- 8306140231 Extends invitation to attend 830627 meeting in King of Prussia.PA to discuss transfer of reactor operator licensing function from Bethesda,MD to Region I ofc STAROSTECKI,R Division of Project & Resident Programs. 83/06/09 COUNSIL.W & Northeast Nuclear Energy Co (subs of Northeast Utilities) 2pp. 18832,351 24X Fiche 50-336.83/06/09,8306140231
- DOCKET 50-338 NORTH ANNA POWER STATION, UNIT 1

 F Security, medical, emergency & fire protection plans
- 8304080225 Application for amend to Licenses NPF-4 & NPF-7, chenging Tech Speck to revise audit frequencies for emergency & security plans to once every 12 months Rev consistent w/ Generic Ltr 82-23
 STEWART,W L. Virginia Electric & Power Co. 82/11/R2 DENTON,H R Office of Nuclear Reactor Regulation, Director. CLARK,R A Operating Reactors Branch 3 3pp 18771 094 24X
 Fiche 50-338,82/11/22,8304080225

- --8306080228 Proposed Tech Bper change revising audit frequencies for emorgency & security plans to once every 12 months * Virginia Electric & Power Co 62/11/22 4pp 18771 097 24X Fiche 30-336.82/11/22.8306080225
- 830&160399 Clarifies position on App R requirements re fixed fire suppression sys Installed standpipe, hose rack, portable equipment & Halon 1301 sys provide adequate fire protection STEMART,W L Virginia Electric & Power Co 83/06/13 DENTON, H R Office of Nuclear Reactor Regulation, Director CLARK, R A Operating Reactors Branch 3 lp 18859 311 24X Fiche 50-338,83/06/13.8306160399

O Adjudicatory correspondence

- 830.4150422 Memorandum discussing two issues briefed by applicant, for ABLB ABLB has jurisdiction to consider health & safety impacts & reasonably forsecable environ impacts of transshipment of spent fuel from Surry to North Anna WOLFE, S.J., KLINE, J.R. Atomic Bafety and Licensing Board Panel 83/06/10 9pp 18847 109 24% Fiche 50-338,83/06/10,8306150422
- P Operating license stage documents & correspondence
- 8306080225 Application for amend to Licenses NPF-4 & NPF-7, changing Tech Specs to revise audit frequencies for emergency & security plans to once every 12 months Rev consistent w/ Generic & RE-23
 STEWART, N L Virginia Electric & Power Co 82/11/22 DENTON, H R Office of Nuclear Reactor Regulation, Director CLARK, R A Operating Reactors Branch 3 3pp 19771 094 24X Fichs 50-338, 82/11/22, 8306080225
- --8306080828 Proposed Tech Spec change revising audit frequencies for emergency & security plans to once every 12 months * Virginia Electric & Power Co 82/11/22 4pp 18771 097 24X Fiche 50-338, 82/11/22, 8306080225
- B3D&O300&7 Forwards synopsis of issues to resolve conformance w/NVREO-0&12 re control of heavy loads (Phase I) & draft technical evaluation rept.
 CLARK,R A Operating Reactors Branch 3 B3/05/17 BTEWART,W.L Virginia Electric & Pawer Co 13pp 18733 211 24X Fiche 50-338, B3/05/17, B30&0300&7
- --8306030070 "Control of Heavy Loads (C-10), Virginia Electric Power Co, North Anna Power Station Units I & 2." draft technical evaluation rept BOMBERGER, CR. VOSBURY, FW. BARGENT, IH Franklin Institute/Franklin Research Conter NRC-03-81-130 TER-0506-372/973 DR 83/02/22 NRC NO Detailed Affiliation Given 25pp. 18703 224 24X Fiche 50-338, 83/05/17, 8306030067.
- B30&14020B Application for amend to Licenses NPF-4 & NPF-7, adding additional accident monitoring instrumentation & instrumentation for detection of inadequate core cooling per requirements of NUREQ-0737, Items II F 1 & II F 2
 STEWART.W L Virginia Electric & Power Co B3/06/03 DENTON.H R. Office of Nuclear Reactor Regulation, Director CLARK.R A Operating Reactors Branch 3 4pp 13B41 165 24X
 Fichs 50-338,83/06/03.8304140208
- --8306140222 Proposed changes to Tech Specs adding addl accident monitoring instrumentation & instrumentation for detection of inadequate core cooling per requirements of NUREG-0737.

 Items II F 1 & II F 2

 * Virginia Electric & Power Co 83/06/03 22pp 18841:169 24X Fichs 50-338.83/06/03.8306140208
- 8306190514 Advises of refund of fees re 821217 application to amend Licenses NPF-7 & NPF-4 proposing radiological effluent Tech Spec changes MILLER, W. O. License Fee Monagement Branch 83/04/07. STEWART, W. L. Virginia Electric & Power Co. 1p. 18854 359 24X Ficher 50-338, 83/06/07. 8306150516.
- 8306160405 Responds to 830111 ltr & safety evaluation re possible overvoltage on motor control ctr contactor coils & resolution of motor valve rerating Test results & schedule for overvoltage problem will be submitted by 840131 STEMART.W L. Virginia Electric & Power Co 83/06/07 DENTON.H.R. Office of Nuclear Reactor Regulation, Director CLARK.R A Operating Reactors Branch 3. 2pp. 18860 031 24X Fiche 50-338.83/06/07.830616040B
- 8306160249 Suppl to application for amend to Licenses NPF-4 & NPF-7, providing Tech Specs for NUREG-0737, Item II B i, "Reactor Vessel Head Vant," No addl license amend for required STEWART,W L. Virginia Electric & Power G 83/06/09 DENTON,H R Office of Nuclear Reactor Regulation, Director CLARK,R. A. Operating Reactors Branch S 2pp 18861 211. 24X Fiche 50-038,83/06/09,8306160249

- --8306160264 Tech Space re NUREG-0737. Itom II B 1. "Reactor Vessel Head Vent" Discussion of proposed Tech Spac change also encl * Virginia Electric & Power Co 83/06/09 11pp 19861 214 24X Fiche 50-338.83/06/09.8306160249
- B306270214 Forwards sdd1 info re 820820 application for amend to Licenses NPF-4 & NPF-7, allowing installation & use of neutron absorber spent fuel storage racks in pool, per NRC request
 STEMARTH L. Virginia Electric & Power Co. 83/06/16 DENTON, H.R. Office of Nuclear Reactor Regulation, Director. CLARK, R.A. Operating Reactors Branch J. Spp. 18988-036. 24X
 Fichs 50-338,03/06/16,8306270214
- 8304300240 Forwards revised environ qualification master list, originally submitted by 830520 response to 10CFR50. Paragraph 50 49(9) re environ qualification of safety-related blackrical equipment.

 STEKART, H. L. Virginia Electric & Power Co. 83/06/22 DENTON, H.R. Office of Nuclear Reactor Regulation, Director CLARK, R.A. Operating Reactors Branch 3 3pp 19122 295 24X Fichs 80-338.83/06/22.8306300240
- 8306300076 Advises of potential source of operator error resulting from Magan process controller mod. Design change will instituted to eliminate "inverse acting" feature of controller Mnd will be performed during refueling outage STEWART, W. L. Virginia Electric & Power Co. 83/06/27 DENTON, H. R. Office of Nuclear Reactor Regulation, Director CLARK, R. A. Operating Reactors Branch 3 4pp. 19121.036 24X Fiche 50-338,83/06/27,8306300076
- d Inspection reports, IE Bulletins & correspondence
- B306140556 Confirms mgt meeting on B30217 in Richmond, VA to review results of first phase of annual appraisal of regulatory performance Proposed meeting agenda encl LEMISTR C Division of Project & Resident Programs B3/02/08 BTEWART.W L Virginia Electric & Power Co 3pp. 18834:217 24X Fiche: 30-000, 83/02/08 B306140556.
- 8306140608 Forwards IE Insp Repts 50-338/83-08 & 50-339/83-08 on 830306-0405 No noncompliance noted DANCE, H C Division of Project & Resident Programs 83/05/17 STENARIU L Virginia Electric & Power Co 2pp 18834 341 24X Fiche, 50-338, 83/05/17, 8306440608
- ~-B306140647 IE Insp Repts 50~338/83~08 & 50~339/83~08 on B30306~0405 No honcompliance noted Major areas inspected surveillance & maint activities. LERs, followup of previously identified items: IE bulletin followup & plant operations
 BHYMLOCK.M.B. Region 2, Office of Director JULIAN.C. Division of Project & Resident Programs. B3/05/16 Bpp. 18834.343. 24X
 Fichs: 50~338,83/05/17,8306140608
- 8306140641 Forwards IE Insp Repts 50-338/83-10 & 50-339/83-10 on 830411-14 & 21-22 No noncompliance noted DANCE, H. C. Division of Project & Resident Programs 83/05/17 STEMART, W. L. Virginia Electric & Power Co. 2pp 1883
- --8306140652 IE Insp Repts 50-338/83-10 & 50-339/83-10 on 830411-14 & 21-22 No noncompliance noted Major areas inspected inservice insp data review & evaluation & observation of steam generator tube eddy current insp ECONOMOS, N. Region 2, Office of Director BLAKE. J. Division of Engineering & Radiological Safety Programs, 93/05/05 9pp. 18833:275 24X Fiche: 50-338, 83/05/17, 8306140641
- 8305110458 IE Info Notice 83-32, "Ruptured Am-241 Bources Contained in Hall Logging Device" Syc list encl
 TAYLON, J. H. Division of Safeguards & Inspection Programs (Post 830103), 83/05/26 Consolidated Edison Co. of New York, Inc 125pp 18631:043 24% Fiche 50-000,83/05/26,8305110458
- 9305110460 IE Info Notice 93-34. "Event Notification Info Worksheet."
 Svc list ent:
 JORDAN, E L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/05/26 Consolidated Edison Co of New
 York, Inc. 115pp. 18732.085. 24x Fiche: 50-000, 83/05/26, 8305110460
- 8305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods Withdrawn at BMRs." Svc list encl JORDAN.E.L Division of Emergency Preparadness & Engineering Response (Post 830103). 83/05/31. Consolidated Edison Co. of New York, Inc. 116pp. 18732:208 24X Fiche, 50-000, 83/05/31, 8305110461.

- 8306290331 Forwards response to IE Bulletin 83-08. "Check Valve Failures in Raw Water Cooling Sys of Diesel Generators."
 Surry has no valves in emergency diesel generator cooling sys Raw cooling water sys not used at North Anna STEWART. W L. Virginia Electric & Power Co. 83/06/08. D'REILLY, J.P. Region 2. Office of Director. Spp. 17055-303. JAX Fiche 50-000,83/06/08.8306290331
- 8305110444 IE Info Notice 83-36. "Impact of Security Practices on Safe Operations " Syc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/07 Consolidated Edison Co of New York, Inc 117pp 18830 200 24X Ficho 50-000.83/06/09,8385110464
- 9305110470 IE Info Notice 83-38, "Defective Heat Sink Adhesive & Seismically Induced Chatter in Relays Within Printed Circuit Cards "Syc list encl JORDAN, E L. Division of Emergency Proparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co of New York, Inc. 118pp 18920 225 24X Fiche 50-000,83/06/13.8305110476
- 8304090010 IE Info Notice 83-37, "Transformer Failure Resulting From Degraded Internal Connection Cables " Syc list oncl JURDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83706/13 Consolidated Edison Co of New York, Inc. 243pp 18921 001 24X Fiche 50-000,83706/13,8306090010
- 8306290383 Ack receipt of 830527 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-038/82-25 & 50-039/82-25 & 50-039/82-25 & LEWIS, R C Division of Project & Resident Programs 83/06/17 STEWART, W L Virginia Electric & Power Co Ip 19055 29/ 24X Fiche 50-038, 83/06/17, 8306290089
- --8306290397 Forwards response to NRC 890806 ltr re violations noted in IE Insp Repts 50-338/82-25 & 50-339/82-25 Corrective actions procedure w/valve lineup sheet & sys sketch provided Personnel surveyed to identify necessary controls STEMART.W L Virginia Electric & Power Co 83/05/27 O'REILLY, J.P. Region 2, Office of Director 5pp 19055 298 24% Fiche 50-338,83/06/17,8306290383
- 8305110475 IE Info Notice 83-40. "Need to Environmentally Qualify
 Epoxy Grauts & Sealers " Svc list one:
 JORDAN, E. L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/06/22 Consolidated Edison Co of New
 York, Inc. 115pp 17021 177 24X Fiche 50-000,83/06/22,8305110475
- 8305110477 IE Info Notice 83-41, "Actuation of Fire Suppression Sys-Causing Inoperability of Safety-Related Equipment " Syc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/22 Consolidated Edison Co. of New York, Inc. 120pp 18997 007 24% Fiche 50-000,63/06/22,6305110477
- 8305110479 IE Info Notice 83-42, "Reactor Mode Switch Malfunctions"

 Svc list encl

 JORDAN E L. Division of Emergency Preparadness & Engineering
 Response (Post 830103) 83/06/23 Consolidated Edison Co of New
 York, Inc 116pp 18976 242 24X Fiche 50-000,83/06/23,8305110479
- 8305110483 IE Info Notice 83-43, "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints " Svc list encl JORDAN E. L Division of Emergency Preparedness & Engineering Responso (Past 830103) 83/06/24 Consolidated Edison Co of New York, Inc. 116pp. 17046 277 24X Fiche 50-000.83/06/24,8305110483
- R Periodic operating reports & related correspondence
- 8306020092 Monthly operating repts for Mar 1983 W/830414 ltr STEWART, W L , SCHMITENDORF, 0 Virginia Electric & Power Co 83/04/05 10pp 18691 177 24X Fiche 50-338,83/04/05,8306020092
- B306160532 Monthly operating repts for Apr 1983 W/830513 ltr BCHMITENDORF, O. Virginia Electric & Power Co B3/05/02 HALLER, N M OPFice of Resource Management, Director 10pp 18864 034. 24% Fiche 50-338,83/05/02.8306160532
- S Reportable occurrences, LERs & related correspondence
- 8306070281 LER 83-028/03L-0. on 630507, inside containment recirculation spray pump I-R8-P-18 tripped during surveillance testing. Caused by feulty B phase overcurrent device in breaker Replacement breaker installed W/830525 ltr MARRELLE W Virginia Electric & Power Co 83/08/25 0'REILLY, J P. Region 2, Office of Director 4pp 18741 101 24X Fiche, 50-338, 63/05/25, 8306070281.

- 630.6070173 LER 83-029/03L-0 on 830509, following rapid rampdown from 100% to 4% power, I-131 does equivalent exceeded 1 0 uCi/g Caused by unidentified fuel element defect worsened by post-rampdown conditions Sampling increased W/830326 Itr MARRELL, E W. Virginia Electric & Power Co. 83/05/26 O'REILLY, J P. Region 2, Office of Director 4pp 18736 333 24% Fiche 50-338,83/05/26,8306070173
- 8306090137 LER 83-017/03L-0 on 830516, while in Mode 1, individual rod position indication for control bank B rod D-10 deviated from group demand position Caused by detector & signal conditioning card drift W/830601 ltr MARRELL,E W Virginia Electric & Power Co 83/06/01 D'REILLY, J P Region 2, Office of Director 2pp 18792 254 24X Fichs 50-338,83/06/01,8306090137
- 8304090158 LER 83-027/03t.-O an 830505, one header (42 bottles) of control room bottled air pressurtied sys found to have lower than required pressure (2,290 vs 2,300 ps;g) Probably caused by leakage when compressor malfunctioned W/830601 ltr HARRELL, E W Virginia Electric & Power Co 83/06/01 O'REILLY, J P Region 2, Office of Director 3pp 16809 199 24X Fiche 50-338,83/06/01,8306090158
- 830.6090318 LER 83-030/03L-0 on 830511, containment personnel hatch inner door failed leakage surveillance test Caused by dirt accumulating on inner door seal during containment entries prior to test HARRELL, E.W. Virginia Electric & Power Co. 83/06/01 O'REJLLY, J.P. Region 2. Office of Director 2pp 10795-175 24X Fiche 50-338.83/06/01.83060903J8
- 8304200232 LER 83-024/03L-0 on 830517, engineering review of steam driven auxiliary feedwater pump periodic tests revealed pump bearing temps not being measured in accordance w/ASME XI IMP requirements W/830409 ltr MARRELL, E W Virginia Electric & Power Co 83/06/09 O'REIILY, J P Region 2, Office of Director 4pp 10902 331 24% Fiche 50-338,83/04/09,8304200232
- B306270104 LER B3-040/03L-0 on B30603, w/unit at 100% power, Fire Door B71-19 would not close w/o assistance Caused by reclosure mechanism out of adjustment Mechanism readjusted Design mode to fire door being investigated W/B30615 ltr HARRELLE W Virginia Electric & Power Co B3/06/15 D'REILLY, J P Region 2, 0ffice of Director 2pp 10988 143 24X Fiche 50-338,83/06/15,8306270104
- 8306270366 LER 83-041/03L-0 on 830606, following reactor trip from 100% power, I-131 dose equivalent exceeded 10 mCi/g Caused by fuel element defect in reactor core Accelerated sampling frequency implemented W/830615 tor HARRELL, E W Virginia Electric & Power Co 83/06/15 O'REILLY, J P Region 2, Office of Director App 16993 199 24X Fiche 50-338,83/06/15,8306270366
- 8306270430 LER 83-032/03L-0 on 830521 during Mode 1 operation.
 containment tamp rose to greater than 105 F for 30 minutes
 Caused by malfunctioning mechanical chiller Steam jet
 chiller aligned to containment cooling coils W/830615 ltr
 HARRELL, E W Virginia Electric & Power Co 83/06/15 O'REILLY, J P
 Region 2. Office of Director 2pp 24X Fiche 50-338,83/06/15,
 8306270430
- 8306280568 LER 83-033/03L-0 on 830523, w/Unit 2 in Mode 5, pressurizer PDRV PCV-2455c lifted three times to mitigate RC8 pressure transient caused by inadventent 51 actuation Caused by inadequate instrumentation procedures W/830615 ltr HARRELL.F W Virginia Electric & Power Co 83/06/15 O'REILLY, J P Region 2, Office of Director 4pp 19017 314, 24X Fiche 50-338,83/06/15,8306280568
- 8306300020 LER 83-035/03L-0 on 830528, following rapid rampdown from 100% to 0% power, I-131 dose equivalent exceeded Tech Spec 1 init Level returned to limit within 12 h Caused by Fuel element defect in reactor core W/830621 ltr HARRELL, E W Virginia Electric & Power Co 83/06/21 O'REILLY, J P Region 2, Office of Director 4pp 19120 230 24% Fiche 50-338,83/06/21,8306300020

V Operator Examinations

8306240261 Advises that no reasonable basis exists to reverse denial of application for operator license Applicant for operator license entitled to request hearing on denial of license Reapplication permitted as of 830622 BURNS. 9 @ Regional Operations & Enforcement Division 83/06/08 TIBLIS, D 8 Virginia Electric & Power Co. 2pp 18980 144 24X Fiche 50-338,83/06/08,8306240261

- DOCKET 50-339 NORTH ANNA POWER STATION, UNIT 2

 F Security, medical, emergency & fire protection plans
- 8304080225 Application for amend to Licenses NPF-4 & NPF-7, changing Tech Spers to revise audit frequencies for emergency & security plans to once every 12 months Rev consistent w/ Generic Ltr 82~23
 STEWART, W L. Virginia Electric & Power Co. 82/11/22 DENTON, H F Office of Nuclear Reactor Regulation, Director 3pp. 18771:094
 24X Fiche 50-338,82/11/22,8306080225
- --8306080228 Proposed Tech Spec change revising audit frequencies for emergency & security plans to once every 12 months * Virginia Electric & Power (o. 82/11/22 4pp 1877) 097 24X Fiche: 50-338, 82/11/22,8306080225
- 8304140379 Clarifies position on App R requirements re fixed fire suppression sys Installed standpips hase rack portable equipment & Halon 1301 sys provide adequate fire protection STEWART.W L Virginia Electric & Power Co. 83/06/13 DENYON.H R Office of Nuclear Reactor Regulation. Director CLARK.R A Operating Reactors Branch 3 ip 18859.311 24X Fiche 50-338,83/06/13,8306160399

G Adjudicatory correspondence

- 8306150422 Memorandum discussing two issues briefed by applicant, for AGLE ASLE has jurisdiction to consider health & safety impacts & reasonably forseeable environ impacts of transshipment of spent fuel from Surry to North Anna MOLFE.S J. KLINE, JR. Atomic Safety and Licensing Board Panel. 83/06/10 9pp 18847 109 24X Fiche 30-338.83/06/10.8306150422
- P Operating license stage documents & correspondence
- 8306080225 Application for amend to Licenses NPF-4 & NPF-7, thanging Tech Specs to revise audit frequencies for emergency & security plans to once every 12 munths Rev consistent w/ General Ltr 82-23
 STEMART.W L. Virginia Electric & Power Co. 82/11/22 DENTON.H.R Office of Nuclear Reactor Regulation. Director. CLARK.R A. Operating Reactors Branch 3 3pp. 18771 094 24X
 Fiche 50-338.82/11/22.8306080225
- --B3060B022B Proposed Tech Spec change revising audit frequencies for emergency & security plans to once every 12 months * Virginia Electric & Power Co B2/11/22 App 18771 097 24X Fiche 50-33B, 82/11/22, 83060B0225
- 830.6030067 Forwards synopsis of issues to resolve conformance w/NURCG-0612 re control of heavy loads (Phase I) & draft technical availation rept CLARK.R A Operating Reactors Branch 3 83/05/17 9TEHART.W L. Virginia Electric & Power Co 13pp 18733 211 24X Fiche: 50-338, 83/05/17. 8306030067
- --8306030070 "Control of Heavy Loads (C-10), Virginia Electric Power Con Morth Anna Power Station Units 1 & 2," draft technical evaluation rept BUMBERGER, C R , VDBBURY,F W , SARGENT, I H Franklin Institute/Franklin Research Center NRC-03-B1-130. TER-05506-372/373 DR 63/02/22 NRC NO Detailed Affiliation Olven 25pp 18733 224 24X Fiche 50-338,83/05/17,8306030067
- 830.6140208 Application for amend to Licenses NPF-4 & NPF-7, adding add1 accident monitoring instrumentation & instrumentation for detection of inadequate core cooling per requirements of NUREO-0757, Items II.F.1 & II F 2 SIEWART.W L. Virginia Electric & Power Co. 83/06/03 DENTON.H R Office of Nurlear Reactor Regulation. Director CLARK.R A. Operating Reactors Branch 3 4pp 18841 165 24X Fiche.50-338.83/06/03.8306140208
- --8306140222 Proposed changes to Tech Boecs adding add1 accident monitoring instrumentation & instrumentation for detection of inadequate core cooling per requirements of NUREO-0737. Items II F 1 & II F 2
 * Virginia Electric & Power Co 83/06/03 R2pp 18841:169 24X Fiche:50-338,83/06/03,8306140208
- 8306:508:6 Advises of refund of fees re 82:217 application to amend Licenses NPF-7 & NPF-4 proposing radiological effluent Tech Spec changes MILLER, W O License Fee Management Dranch 83/06/07 STEWART, W. L. Virginia Electric & Pauur Co Ip 10854 359 24% Fiche 50-338,83/06/07,8306:508:6

- 8306160405 Responds to 830111 itr & safety evaluation re possible overvaltage on motor control ctr contactor coils & resolution of motor valve rerating Test results & schedule for overvaltage problem will be submitted by 840131 STEWART.W L. Virginia Electric & Power Co. 83/06/07 DENTON.H R. Office of Nuclear Reactor Regulation. Director CLARK.R A. Operating Reactors Branch 3. 2pp. 18860-031 24X Fiche.50-338.83/06/07.8306160405
- 8306160249 Suppl to application for amend to Licenses NPF-4 & NPF-7, providing Tech Specs for NUREO-0737, Item II B 1, "Reactor Vessel Head Vent " No addl license amend fee required STEWART.W L Virginia Electric & Power Co 83/06/09 DENIGN.H R Office of Nuclear Reactor Regulation, Director CLARK.R A Operating Reactors Branch 3 2pp 18861 211 24X Fiche 30-338,83/06/09,8306160249
- --8306160266 Tech Epecs re NUREO-0737. Item II B 1, "Reactor Vessel Head Vent " Discussion of proposed Tech Spec change also encl * Virginia Electric & Pouer Co. 83/06/07 | Ilpp | 18861 214 | 24X Fiche 50-338.83/06/09.8306160249
- 8306290876 Discusses status of License Condition 2 C(4)(c) ro replacement of wide & narrow range resistance temp detectors in RCS Status of vendor repair, redesign or provisions for obtaining resistance temp detectors requested. CLARK.R. A Operating Reactors Branch 3 83/06/15 STEHART, 4 L Virginia Electric & Power Co. 3pp 19046 122 24X Fiche. 50-337, 83/06/15, 8306290296
- 8306270302 Advises that stipulation & implementation as specified in License Condition 2 C(10) re containment backup overcurrent protection sys complete CLARK.R A. Operating Reactors Branch 3 83/06/15 STEMART.W L Virginia Electric & Power Co 2pp 17046 125 24X Fichs 50-337,83/06/15,8306270302
- 8306270214 Forwards add1 info re B20820 application for amend to Licenses NPF-4 & NPF-7.allouing installation & use of neutron absorber spent fuel storage racks in pool, per NRC request.

 STEMARTH L. Virginia Electric & Power Co. 83/06/16 DENJUN.H R. Office of Nuclear Reactor Regulation. Director CLARK,R A. Operating Reactors Branch 3 Spp. 18988-036 24X Fiche 80-336.83/06/16.8306270214
- 8306300240 Forwards revised environ qualification master list, originally submitted by 830820 response to 100FR50, Paragraph 50,49(g) re-environ qualification of safety-related electrical equipment.

 BIEWART, W.L. Virginia Electric & Power Co #3/06/22. DENYON, HR Office of Nuclear Reactor Regulation, Director CLARK, R A Operating Reactors Branch 3 3pp 19122 295 24X Fiche. 50-338,83/06/22.8306300240
- 8304300094 Advises of sotential source of operator error resulting from Hagan process controller mod Design change will instituted to climinate "inverse acting" feature of controller Mod will be performed during refusiting outage
 STEMART, W. L. Virginia Electric & Power Co. 83/06/27 DENTON, H.R. Office of Nuclear Reactor Regulation, Director CLARK, R.A. Operating Reactors Stanck 3 4pp. 14121-036 24X
 Fiche: 50-338,83/06/27,8306300096
- G. Inspection reports, IE Bulletins & correspondence
- 8306140556 Confirms mgt mesting on B30217 in Richmond, VA to review results of first phase of annual appraisal of regulatory performance Proposed mesting agenda encl.
 LEWIS, R.C. Division of Project & Resident Programs, 03/02/08
 STEMARI, W.L. Virginia Electric & Power Co. 3pp. 18834 217 24X
 Ficha 50-000, 83/02/08, 8306140556
- 8304140608 Forwards IE Insp Repts 50-338/83-08 & 50-339/83-08 on 830306-0405 No honcompliance noted DANCE, H C. Division of Project & Resident Programs 83/05/17 STEMART. W L. Virginis Electric & Power Co 2pp. 18834: 341. 24X Fichs: 50-338, 83/05/17: 8306140608.
- --8306140647 IE Insp Repts 50-338/83-08 & 50-339/83-08 on 830306-0405. No noncompliance noted Major areas inspected surveillance & maint activities. LERs. Pollowup of previously identified items. IE bulletin followup & plant operations. SHYMLOCK. M B Region 2. Office of Director. JULIAN. C Division of Project & Resident Progress 83/05/16. 8pp 18834-343 24X Fiche: 50-338,83/05/17.8306140608
- 8306140641 Forwards IE Insp Repts 50-338/83-10 t 50-339/83-10 on 830411-14 t 21-22. No honcompliance mated DANCE, H.C. Division of Project t Resident Programs 83/05/17, 83E4487, W.L. Virginia Electric t Power Co. 2pp 18833:273, 24X Fiche: 50-338, 83/05/17, 8306140641.

- --8306140652 JE Insp Repts 50-338/83-10 & 50-339/83-10 on 830411-14 % 21-22 No noncompliance noted Major areas inspected inservice insp data review & evaluation & observation of steam generator tube eddy current insp ECONOMOB, N Region 2, Office of Director BLAKE, J Division of Engineering & Radiological Safety Programs 83/05/05 9pp 18033 275 24% Fiche 50-338,83/05/17.8306140641
- 8305110458 IE Info Notice 83-32. "Ruptured Am-241 Bources Contained in Well Lugging Device " Svc list encl TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 125pp 18831 043 24X Fiche 50-000.83/05/26.8305110458
- 8305110460 IE Info Notice 83-34, "Event Notification Info Worksheet" Syc list encl
 JORDAN, E. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/05/26 Consolidated Edison Co of New
 York, Inc 115pp 18732 085 24X Fiche 50-000, 83/05/26, 8305110460
- 8305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods Withdrawm at BWRs " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) 83/05/31 Consolidated Edison Co of New York, Inc. 1146pt 18732 200 24X Fiche 50-000,83/05/31,830511046;
- 830.6290331 Forwards response to IE Bulletin 83-08, "Check Valve Failures in Raw Mater Cooling bys of Diesel Generaturs"
 Sorry has no valves in emergency diesel generator cooling sys Raw cooling water sys not used at North Anna STEWART, N. L. Virginia Electric & Power Co. 83/06/08 O'REIILY, J! Region 2, Office of Director 3pp 17055 303 24X
 Fiche 50-000, 83/06/08, 8306290031
- 8305110464 IE Info Notice 83-36, "Impact of Security Practices on Safe Operations " Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/09 Consolidated Edison Co. of New York. Inc. 119pp 18830 280 24X Fiche 50-000,83/06/09.8305110464
- 8305110470 IE Info Notice 83-38. "Defective Heat Sink Adhesive & Beismically Induced Chatter in Relays Within Printed Circuit Cards " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83706/13 Consolidated Edison Co of New York, Inc. 118pp 18920 225 24X Fishe 50-000, 83706/13, 8305110470
- G304090010 IE Info Notice 83-37, "Transformer Failure Resulting From Degraded Internal Connection Cables" Gvc list encl JURDAN, L Division of Emergency Preparedness & Engineering Response (Post 630103) 83/06/13 Consolidated Edison Cn of New York, Inc. 243pp 18921 001 24% Fiche 50-000,83/06/13,6304090010
- 8306290383 Ack receipt of 83052/lt; informing NRC of steps taken to correct violations noted in IC Insp Repts 50-338/82-25 & 50-339/82-25 & E418.R C Division of Project & Resident Programs 83/06/17 STEMART.H L Virginia Electric & Power Co ip 17055 297 P4X Fiche 50-338.03/06/17.8306290383
- ~-8306270387 Forwards response to NRC 820806 ltr re violations noted in IE Insp Repts 50-338/82-25 & 50-339/82-25 Carrective actions procedure w/valve lineup sheet & sys sketch provided Personnel surveyed to identify necessary controls STEMARI, W.L. Virginia Electric & Power Co 83/05/27 O'REILLY, J.P. Region 2, Office of Director 5pp 19055 290 24% Fiche 50-336,83/06/17,8306290383
- 8306290086 Advises that requirements of License Condition 2 C(17) re low pressure turbine inservice insp met Rept requested re identification of cause of low pressure turbine disc cracking CLARK.R A Operating Reactors Branch 3 83/06/20 STEMART.W L Virginia Electric & Power Co 3pp 19046 170 24X Fiche 50-339,83/06/20.8366290086
- 8305110475 lE Info Notice 83-40, "Need to Environmentally Gualify
 Epoxy Grauts & Sealers " Svc list encl
 JORDAN, E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83706/22 Consolidated Edison Co of New
 York, Inc. 115pp 19021 179 24X Fichs 50-000,83706/22,8305110475
- 8305110477 IE Info Notice 83-41, "Actuation of Fire Suppression Sys Causing Imperability of Safety-Related Equipment" Syc list encl. JCRDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/22 Consolidated Edison Co of New York, Inc. 120pp. 18997.007 24X Fichs 50-000,83/06/22,8305110477

- 8305110479 IE Info Notice 83-42, "Reartor Mode Switch Malfunctions " 3051104/Y IE THE MOST AND THE STATE OF THE S
- 8305110493 IE Info Notice 83-40, "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/24 Consolidated Edison Co of New York, Inc 116pp 19046 29/ 24X Fiche 50-000,83/06/24,8305110483
- R Feriodic operating reports & related correspondence
- 8304020092 Monthly operating repts for Mar 1983 W/830414 ltr STEWART.W L , SCHMITENDORF, G Virginia Electric & Power Co 83/04/05 10pp 18691 177 24X Fiche 50-338,83/04/05,8306020092
- 0306160532 Monthly operating rapts for Apr 1783 W/830513 ltr SCHMITENDORF, G Virginia Electric & Power Co 83/05/02 HALLER, N M Office of Resource Management, Director 10pp 18864 034 24X Fiche 50-338,83/05/02.8306160332
- S Reportable occurrences, LERs & related correspondence
- 8306090314 LER 83-039/03L-0 on 830513, train B solid-state protection sys undervoltage output board found failed during channel functional tast rendering trip function inoperable Cause not stated W/830601 ltr
 - NARRELL, E W Virginia Electric & Power Co 83/05/13 O'REILLY, J P Region 2, Office of Director 2pp 10795 228 24X Fiche 50-339,83/05/13,8306090314
- 8306070276 LER 83-037/03L-0 on 830502, containment particulate (RM-259) b gassous (RM-260) activity monitors found isolated w/containment purge & exhaust sys in operation Caused by failure to reopen manual isolation valve W/830525 ltr MARRELL,E W Virginia Electric & Power Co 83/05/25 G'REILLY, J P Region 2, Office of Director 4pp 18746 138 24X Fiche 50-339,83/05/25,83060702/6
- 8306070249 LER 83-038/03L-0 on 830503, suction to RHR pump B lost while JAGO/0249 LER B3-03B/03L-0 on B39003, suction to AMR pump is 1 transferring water from RCS to refueling water storage tank via refueling purification says Caused by pumping RCS below established operating limit RCS refilled W/B30526 thr HARRELL, E W Virginia Electric & Power Co B3/05/26 U'RI Region 2, Office of Director 3pp 16740 325 P4X Fiche 50-339,83/05/26.8304070P49 O'REILLY, J.P.
- 8306070148 Deficiency rept re narrow range resistance temp detectors installed to meet license condition failing to operate Cause under investigation Detectors replaced Testing modified until design revised Also reportable per Part 21
 STEWART, N. L. Virginia Electric & Power Co. 83/05/27 DENTON, H.R. Office of Nuclear Reactor Regulation, Director CLARK, R.A. Operating Reactors Branch 3 2pp. 18/36 266 24X
 Fiche 50-337.83/05/27,8306070148 DENTON, H R.
- 8306200114 LER 83-040/03L-O on 830518, during refueling outage, Type C tests revealed that 17 containment isolation valves exceeded total allowable leakage Caused by dirt or debric on seating surfaces Seats cleaned, inspected & repaired W/830609 ltr HARRELL, E W Virginia Electric & Power Co 83/06/09 O'REILLY, J P Region 2. Office of Director 3pp 10703 252 24X Fiche 50-339, 83/06/09, 8306200114
- 8306200207 LER 83-033/03L-0 on 830515.pressure in nitrogen supply tank B for pressurizer PORV (PCV-2435C) dropped below min pressure required Caused by downstream nitrogen supply to PORV relief valve lifting Regulaturs reset W/830609 ltr HARRELL, E W Virginia Electric & Power Co 83/06/09 O'REILLY, J. P Region 2. Office of Director 3pp 18902 215 P4X Fiche 50-339,83/06/09,8306200209
- 8304270142 LER 83-046/03L-0 on 830527-29.31 & 0614 & 22.individual rod position indicators deviated from group demand position Caused by instrument drift Indicator channels recalibr W/830615 ltr HARRELL.E W Virginia Electric & Power Co 83/06/15 C/REILLY, J. P. Region 2. Office of Director 2pp 18988 034 24X Fiche. 50-339, 83/06/15, 8306270142
- 8304270183 LER 83-041/03L-0 on 830917, two containment isolation trip valves failed Cause undetermined Broken plunger spring found on one valve. Stem assembly on TV-88-2064 & valve TV-88-203A replaced W/830615 ltr HARRELL, E W Virginia Electric & Power Co 83/06/15 O'REILLY, J P Region 2. Office of Director 3pp 18991:341 24X Fiche 50-339,83/06/15,8306270183

- 8306270316 LER 83-042/03L-0 on 830522.w/unit in Mode 4.RC9 unidentified 1052/0346 LER 83-042/03.-0 on M30522,0/unit im Mode 4.KC9 unidentified leakage exceeded Tech Spoc A A 2 limit Caused by shaft sloeve gasket failure on RHR pump A No cause determined Mechanical seal & gasket replaced M/830615 ltr.
 HARRELL.E W Virginia Electric & Pawer Co. 83/06/15. O'REILLY, J.P. Region 2. Office of Director 2pp. 18996-820. 24X
 Fiche 50-339.83/06/15.8308270316
- 830623024B PNO-II-83-049 on 830616, licensee shut reactor down in compliance w/plant operating requirements because one of two smergency power diesel genorators was inoperable Caused by cooling water leak into cylinders

 JULIAN, C A , VERRELLI, D M Region 2, Office of Director 83/06/17

 2pp 18945 228 24% Fiche 50-339,83/06/17,830623024B

V Operator Examinations

- 8306240261 Advises that no reasonable basis exists to reverse denial of application for operator license Applicant for operator license entitled to request hearing on denial of license Reapplication permitted as of 830622

 BURNS, S. O. Regional Operations & Enforcement Division 83/06/08 TIBLIS, D. B. Virginia Electric & Power Co. 2pp 18980 144, 24X Fiche 50-338,63/06/08.8306240261
- DOCKET 50-341 ENRICO FERMI ATOMIC POWER PLANT, UNIT 2
- A Application/construction stage documents & correspondence
- 8304200295 FOIA request for eight categories of documents re facility, JOHNSTON,M M. Affiliation Unknown, 83/04/11 Division of Rules and Records 2pp 18920 222 24X Fiche 50-341,83/04/11,8304200295
- 8306200279 Partial response to FDIA request for eight categories of documents re facility Copies of listed documents will be provided NUREO available from NTIS FELTON, J H Division of Rules and Records 83/05/06 JOHNSTON, M Affiliation Unknown ip. 18920 224 24X Fiche 50-341,83/05/06,8306200279 M.M.NOTENHOL
- 8306030171 Submits response to telcon request for add1 info re low-low set design & analysis Limiting operational transient for subsequent safety relief valve actuation is fast MBIV
- Detroit Edison Co. 83/05/26 YOUNGBLOOD.B.J Licensing 3pg 18703 324 24X Fiche: 50-341,83/05/26,8306030171 Branch 1
- 8306010168 Forwards Amend 48 to amended & substituted OL application. Consisting of Amend 48 to FSAR
 LANDGRAF.L C LeBoouf, Lamb, Leby & MacRae LANDGRAF,L C Detroit
 Edison Ca B3/05/27 DENTON.H Office of Nuclear Reactor
 Regulation, Director ip 18679 019 24% Fiche 50~341,83/05/27, 8304010168.
- --8306010174 Amend 48 to amended & substituted GL application, consisting of Amend 48 to FSAR
 HEIDEL, C M Detroit Edison Co 83/05/23 ip 19679 020 24X
 Ficha, 50-341, 83/05/27, 8306010168
- 8304080435 Notification of 830415 meeting w/util in Bethesda, MD to discuss independent design verification program LYNCH, M D Licensing Branch 1 83/05/27, YOUNOBLOOD, B J Licensing Branch 1 3pp 18792 194 24X Fiche, 50-341, 83/05/27, 8304080435
- 8304140614 Forwards Certificate of Svc for Amend 48 to amended & substituted application for licenses MATERS.B R Detroit Edison Co 83/06/07 Office of Nuclear Reactor Regulation, Director 3pp 18837 015 24X Fiche: 50-341.63/06/07.8306140614
- 830&i&0357 Forwards "Enrice Fermi Atomic Power Plant,Unit 2, Flant-Unique Analysis Rept for Torus Attached Piping & Suppression Chamber Penetrations "Bubmittal responds to 820526 ltr & SER (NUREO-0798) requirements TAUBER, H Detroit Edison Co 83/06/10, YOUNOBLOOD, B.J. Licens Branch I 2pp 18898 247 24X Fiche, 50-341,83/06/10,8306160357
- --8306160366 Rev D to "Enrico Fermi Atomic Power Plant.Unit P., Plant-Unique Analysis Rept for Torus Attached Piping & Suppression Chamber Penetrations"
 HIGGINDSTHAM, A., YOSHIDA, D.K. NUTECH Engineers, Inc. DET-19-0
 ROO 83/06/30 192pp 18898 249 24X Fichs.50-341,83/06/10,8306160357 DET-19-076-A
- 8304220106 Forwards request for info to complete review of Tech Spec applications re methodology for establishing setpoints for reactor protection & ESF instrumentation. Methodology should be submitted by 831230 YOUNGELOOD, B J. Licensing Branch 1. 83/04/14 TAUBER.H Detroit Edison Co 3pp 18777 340 24X Fiche 50-341,83/04/14.8306220106

- 8306280438 Confirms that scheduled fuel load date revised to 831230 Continued cooperation in resolving outstanding items requested TAUBER, H Detroit Edison Co 83/04/22 YOUNOBLOOD, B J Licen-Branch J. ip 19018 302 24X Fiche 50-341.83/05/22.8306280438 Licensino
- 0306290142 Requests rerouting of cables & analysis of installation of Class IE equipment to satisfy FBAR commitments re design criteria for standby liquid control sys YOUN981000, B J Licensing Branch 1 83/06/22 TAUBER, H Detroit Edison Co 3pp 19046 247 24% Fiche 50-341,83/06/22.8306290142
- E NRC Safety Evaluation Report (SER), supp)s & correspondence
- 8306160387 Forwards "Enrico Fermi Atomic Power Plant, Unit 2.
 Plant-Unique Analysis Rept for Torus Attached Piping &
 Suppression Chamber Penetrations "Submittal responds to
 820326 Itr & SER (NUREG-0798) requirements
 TAUSER, H. Detroit Edison Co 83/06/10 YOUNGBLOOD, B J Licens
 Branch i 2pp 18858 247 24X Fiche 50-341,83/06/10.8306160357
- --8306160366 Rev O to "Enrico Fermi Atomic Power Plant, Unit 2, Plant-Unique Analysis Rept for Torus Attached Piping & Buppression Chamber Penetrations " HOOLINBOYHAM, A. YOSHIDA, D.K. MUTECH Engineers, Inc. DET-19-0 ROO 83/06/30 192pp 18858 247 24X Fiche 50-341,83/06/10. DET-19-076-6 8306160357.
- F. Security, medical, emergency & fire protection plans
- 830.6240266 Responds to request for info re procedures for consideration of Monroe County, MI 2 206 patition re offsite emergency planning issues Relevant submittals will be considered in decisionmeking process
 CRY, N. D. Regional Operations & Enforcement Division #3/03/08
 MINOCK, J. R. Minock, J. Spp. 18980 103 24X Fiche 50-341,83/03/08,8306240266
- B306010321 Notification of location & date change for B30512 meeting w/util in Bethesda. ND to discuss fire protection of safety-related cables Date changed to 830614
 LYNCH H D Licensing Branch | 83/05/06 YOUNGBLOOD, B. J
 Licensing Branch | 3pp 18696 070 24% Fichs 50-341,83/05/06,8306010321
- 8306100210 Forwards IE Insp Rept 50-341/83-11 on 830506 No noncompliance noted Insp performed to determine util readiness for preoperational emergency preparedness readiness for preoperational emergency preparedness appraisal supposes and suppose of the suppos
- --8306100212 IE Insp Rept 50-341/83-11 on 830506 No noncompliance noted Major areas inspected emergency preparedness including implementing procedures procedures PATTERSON, J. P. PAPERIELLO, C. J., AXELSON, W. Region 3, Office of PATTERBON. J P. PAPERIELLO.C J. AXELSON. W. Region 3, Office of Director 83/05/19 4pp 18805/289 24X Fiche.50-341,83/05/20,8306100210
- 8306300053 Forwards IE Insp Rept 50-341/83-12 on 830318.21 & 0510-13 & Notice of Violation
 LITTLE.W 8 Region 3, Office of Director 83/06/16 WELLS.D A
 Detroit Edison Co 2pp 19120:292 24X Fishe 50-341.83/06/16,
- --8306300061 Notice of violation from insp on 830318.21 & 0510-13 LITTLE.W B Region 3. Office of Director 83/06/16 2pp. 19120 294 24% Fiche 50-341.83/06/16.8306300053
- -8306300067 IE Insp Rept 50-341/83-12 on #303[8,21 & 0510-13 Noncompliance noted failure to control procurement of matis-fire doors
 MANRAF.A. RAMSEY.C.B. ULIE, J.M. Region 3, Office of Director 83/06/16, 9pp. 19120 296 24X Fiche.50-341,83/06/16,8306500053
- 8306280385 Responds to Generic Ltr B2-33 (NUREQ-0737. Suppl 1) re requirements for emergency response capability Proposed completion dates enci TAUSER: H Detroit Edison Co. 83/06/23 YOUNOBLOOD, B J. Licensi Branch 1 2pp 19018 026. 24X Fiche 50-341.83/06/23.8306280585.
- O Adjudicatory correspondence
- 8305240266 Responds to request for info re procedures for consideration of Monroe County, MI 2.206 petition re offsite emergency planning issues. Relevant submittals will be considered in decisionmailing process
 CRY.K D. Regional Operations & Enforcement Division. 83/03/08,
 MINOCK, J. R. Minock, J. 5pp. 18980-103 24X Fiche, 50-341, 83/03/08,

- 8306060276 Decision ALAB-730.affirming ADIO 821029 Initial Decision LBP-82-96.authorizing OL issuances No substantial reason exists why asserted significance of facts long available should not have been raised earlier SHOEMAKER.C J Atomic Safety and Licensing Appeal Panel 25pp 18729 001 24% Fiche 50-341.83/06/02.8306060276 03/05/02
- 8306270218 Petition for review of ASLAP 830602 decision affirming ASLB 821029 decision authorizing insuance of full-power OL Monroe County does not have radiological energency response plan & will not implement draft Certificate of Syc encl MINOCK.J R Citizens for Energy & Employment MINOCK.J R Minock. MINOCK, J. R. Citizens for Energy & Employment N J. 83/06/22 Commissioners 8pp 18991 225 Fiche 50~341,83/06/22,8306270218
- K Utility Final Safety Analysis Report (FSAR) & amends
- 8306010168 Forwards Amend 48 to amended & substituted DL application, consisting of Amend 48 to FSAR LANDGRAF, L C Detroit Edison Co. B3705/27 DENTON, H Office of Nuclear Reactor Regulation. Director ip 18679 019 24X Fiche 50-241,83/05/27,8306010168
- --8306010174 Amend 48 to amended & substituted OL application, consisting of Amend 48 to FSAR HEIDEL, C M Detroit Editon Co 83/05/23 ip 18679 020 P4X Fiche 50-341.83/05/27.8306010168
- --8306010178 Amend 48 to FSAR * Detroit Edison Co 83/05/31 255pp 18679 021 P4X Fiche 50-341,83/05/27,8306010148
- Q inspection reports, IE Bulletins & correspondence
- 8304100210 Forwards IE Insp Rept 50-341/83-11 on 830504 No noncompliance noted Insp performed to determine util readiness for preoperational emergency preparedness appraisal HIND, J A Division of Radiological & Materials Safety Programs 83/05/20 WELLS, D A Detroit Edison Co 2pp 18805 288 P Fithe 50-341,83/05/20.8306100210
- ~-8306100R12 IE Insp Rept 50~341/83-11 on 830306 No noncompliance noted Major areas inspected emergency preparedness, including implementing procedures
 PATTERBON, J.P., PAPERIELLO, C.J., AXELSON, W. Region 3, Office of
 Director 83/05/19 4pp 18805 289 24X Fishe 50-341,83/05/20,
 8306100210
- 8306210291 Forwards IE Insp Rept 50-341/83-09 on 830303-06 No NOS/10891 PDIWARDS IN 1957 No. 1957 No.
- --8306210298 IE Insp Rept 50-341/83-07 on 830503-06 No noncompliance noted Major areas inspected followup on IE bulletins & circulars & 10CFR50 55(e) repts HEBCOTT.H M , PARKER,M E , KONKLIN.J E Region 3, Defice of Director 83/05/19 10pp 18915 129 24X Fiche 50-341.83/05/2J, 8306210291
- 8305110458 IE Info Notice 83-32, "Ruptured Am-241 Sources Contained In Hell Logging Device "Sur list encl TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103), 83/05/26 Consulidated Edison Co of New York, Inc 125pp 18831-043 24x Fiche 50-000,83/05/26,8305110458
- 8305110460 IE Info Notice 83-34, "Event Notification Info Worksheet " 305130460 IE Into Notice 30 2...

 Svc list encl
 JORDAN E L Division of Emergency Preparedness & Engineering
 Response (Post 630103) 83/05/26 Consolidated Edison Co of New
 York, Inc 115pp 18732 085 24% Fiche 50-000,83/05/24,8305110460
- 8306170049 Forwards IE Insp Rept 50-341/B3-10 on 830301-0430 No noncompliance hoted KNOP,R C Region 3, Office of Director B3/05/27 WELLS,D A Detroit Edison Co. 200 18982.213 24X Ficha 50-341,83/05/27.
- --8306170035 IE Insp Rept 50-341/83-10 on 830301-0430 No noncompliance noted Mayor areas inspected followup on previously identified items. followup on headquarters request & preoperational test program implementation.

 LITTLE: B H. BYRON, P M., KONKLIN, J E. Region 3, Office of Director 83/05/28 8pp 18882 215 24X Fishe 50-341,83/05/27. 8306170049.

- 8305110461 IE Info Notice 83-35. "Fuol Movement W/Control Rods Mithdrawn at BWRs " Svc list encl JORDAN,C L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/31 Consolidated Edison Co of New York, Inc 114pp 18732 208 24X Fiche 50-000,83/05/31.6305110461
- 8306070082 Ack receipt of 630525 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-341/83-05 NOREE, IUS. C E Division of Project & Resident Programs 83/06/03 NELLEN D A Detroit EUson Co ip 18739 142 24X Fiche 50-341,83/06/03,8306070002
- --8306070085 Responds to NRC 630411 ltr re violations noted in 1E Insp Rept 50-341/83-05 Corrective actions Nev 3 of Startup Instruction 4 5 1 01 issued on 830110 mandating use of test change notice for ink changes & page replacements WELLS.D A Detroit Edison (a 83/05/25 NORELIUS.C E Division of Project & Resident Programs 10pp 18737 143 24X Fiche 50-341,83/06/03,83060/0082
- 8305110464 IE Info Notice 83-36, "Impact of Security Practices on Safe Operations "Svc list encl JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Post 630103) 83/06/09 Consolidated Edison Co. of New York, Inc. 119pp 16830 280 24X Fiche 50-000, 83/06/09, 8305110464
- 830630289 Ack receipt of 830509 ltr informing NRC of steps taken to correct violations noted in 1F Insp Rept 50-341/82-21 Final terrestrial monitoring repts for 1979 & 80 close out Open Item 01 in IE Insp Rept 50-341/878-06 PAPERIELLO.C J. Region 3. Office of Director 83/06/10 WELLS.D / Detroit Edison Co ip 18823 303 24% Fiche 50-341/83/06/10. 8336430240
- --8306130292 Forwards final terrestrial monitoring repts for 1977 & 80 in response to open Item 01 in 1C Insp Rept 50-341/78 06 per violation in IC Insp Rept 50-341/82-21 M/a encl WELLS.D A Detroit Edison (a 83/05/09 HIND.) A Region 3, Dffice of Director 2pp 18023 304 24X Fiche 50-341,83/06/10, 8306130280
- 8305110470 IE Info Notice 83-30, "Defective Heat Sink Adhesiv: & Seismically Induced Chatter in Relays Within Printed Circust Cards " Gyc list entl JURDAN,E L Division of Emergency Preparedness & Engineering Response (Past 830103) 83/06/13 Consolidated Edison Co of New York, Inc. 118pp 18920 225 24X Fiche 50-000,83/06/13,838510470
- 9304070010 IE Info Notice 83-37. "Transformer Failure Resulting From Dograded Internal Connection Cables" Svc list encl JORDAN.F. L. Divinion of Emergency Proparodness & Engineering Response (Post 830103) 83/04/13 Consolidated Edison Co. of New York, Inc. 243pp 18921 001 PAX Fiths 50-000.83/04/13.8384090010
- 830.6220016 Ack receipt of 830527 & 0609 ltrs informing NRC of steps taken to correct noncompliance noted in IC Insp Rept 50-341/83-04 BPESBARD.R L Region 3, Office of Director 83/06/15 WELLS.D / Detroit Edison Co ip 18927 323 24X Fiche 50-341,83/06/15, 830.622016
- --0306220024 Responds to NRC B30427 itr re noncompliance noted in 1E Insp Rept 50-341/B3-04 Corrective actions all power cables now properly tagged & work per Nonconformance Rept 82-043 completed for cable identified on noncompliance WELLS,D A Detroit Edison Co 83/05/27 SPESSARD,R L Division of Engineering 11pp 1892/ 324 24% Ficher 80-341.83/06/15, B306220016
- --B306220030 Forwards two corrected pages to previous response to noncompliance noted in IE lnsp Rept 50-341/83-04 Responses to Items 83-04-04 & 83-04-07 correct, however, statements of noncompliance inadvortently interchanged WELLS, D A Detroit Edison Co 83/06/09 BPESBARD, R L Division of Engineering 3pp 18927-335 24X Fichs 50-341,83/06/15,8306320016
- 8304300053 Forwards 1E Insp Rept 50-341/83-12 on 830318,21 & 0510-13 & notice of violation
 LITTLE,W S Region 3, Office of Director 83/04/14 WELLS,D A Detroit Edison Co 2pp 19120 292 P4X Fiche 30-341,83/04/14, 8304300053
- --8306300061 Notice of violation from insp on 830318.21 & 0510-13 LITTLE, W 8 Region 3. Office of Director 83/06/16 Ppp 19120 294 24X Fithe 50-341.83/06/16.8306300053
- --8306300067 IE lnsp Rept 50-341/83-12 on 830318.21 & 0510-13 Noncompliance noted failure to control procurement of matls-fire doors MAURA:F A: RANSEY,C B , ULIE,J M Region 3, Office of Director. 83/06/16 7pp 19120 296 24X Fiche 50-341,83/06/16,8306300053

- 8305110475 IE Info Nutice 83-40. "Need to Environmentally Qualify
 Epoxy Grouts & Sealers " Swc list encl
 JORDAN, E. L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83706/22 Consolidated Edison Co. of New
 York, Inc. 113pp 19021 179 24X Fiche 50-000.83/06/22,8305110475
- 8305110477 IE Info Notice B3-41. "Actuation of Fire Suppression Bys Causing Inoperability of Safety-Related Equipment " Svc list enc! JORDAN.E L Division of Emergency Preparedness & Enginering Response (Post 830103) 83/06/22 Consolidated Edizon Cn of New York, Inc 120pp 18997 007 24X Fiche 50-000.83/06/22,8309110477
- 8305110479 IE Info Notice 83-42, "Reactor Mode Switch Malfunctions "
 Svc list encl
 JURDAN.E.L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/06/23 Consolidated Edison Co of New
 York, Inc. 116pp 18976 242 24X Fiche 50-000,83/06/23,8305110479
- 8305110483 IE Info Notice 83-43. "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/24 Consolidated Edison Co of New York, Inc 116pp 19046 297 24X Fiche 50-000,83/06/24,8305110483
- S Reportable occurrences, LERs & related correspondence
- B306060187 Deficiency Rept 94 re potential problem w/loose pole piece wedges on Four emergency diesel generators Initially reported on 830429 Util requested Beloit Power Bys to review & evaluate circumstances to determine cause WELLS,D A Detroit Edison Co. 83/05/27 KEPPLER,J G. Region 3, Office of Director 2pp 18728 271 24X Fiche 50-341,83/05/27, B306060187
- 8304040245 Final deficiency rept re overpressurizing primary containment pipe penetration beliou Initially reported on 821213 Test program & procedure developed Bellous meet or exceed acceptance criteria
 WELLS, D. A. Detroit Edison Co. 83/05/27 KEPPLER, J. O. Region 3, Office of Director 2pp. 18728 281 24X Fiche 50-341,83/05/27, 820404045
- 8306170233 Final Deficiency Rept 71 re improper assembly of core spray pump P16 E21-01-C001A Initially reported on 820615 Shaft repaired & impeller reinstalled in correct orientation per maint procedure rev HELLS,D A Detroit Edison Co. 83/05/27 KEPPLER,J O Region 3, Office of Director 2pp 18882 320 24X Fiche 50-341,83/05/27,8306170233
- 8306170419 Final Deficiency Rept 42 re spacing on concrete anchors Initially reported on 810326 Anchor bolts dispositioned Gateway inserts grouted Personnel attended anchor bolt installation training class WELLS.D A Detroit Edison Co 83/06/03 KEPPLER.J C. Region 3. Office of Director 2pp 18879 045 24X Fiche 50-341.83/06/03.8306170419

DOCKET 50-344 TROJAN NUCLEAR PLANT

- F Security, medical, emergency & fire protection plans
- 8306210314 F01A request for NRC records re security violations & safeguards events at nuclear Pacilities ODLDENBERS, 0 Scripps-Howard Newspapers 83/04/22 FELTON, J M Office of Administration 2pp 18925 178 24X Ficha 50-000,83/04/22,8306210314
- 8306210306 Partial response to FOIA request for NRC records re security violations & safeguards events at nuclear facilities Repts listed on App A available in PDR Search for addl documents aubj to request continuing FELTON. J M Division of Rules and Records 83/05/16 GOLDENBERG. @ Bcripps-Howard Newspapers 2pp 18925 196 24% Fiche 50-000,83/05/16,8306210306
- 830624030B Forwards "1982 Trojan Nuclear Power Plant Exercise" based on 821118 exercise State & local plans & preparedness adequate KRIMM.R W Federal Emergency Management Agency 83/05/18 JORDON,E L Division of Emergency Preparedness & Engineering Response (Post 830103) ip 18779 075 24X Ficher 50-344,83/05/18,8306240308
- --8306240310 "1982 Trojan Nuclear Power Plant Exercise "
 # Federal Emergency Management Agency 82/12/10 B0pi
 18979 074 24X Fiche 50-344,83/05/18.8306240308

- 8304070015 Forwards IE Insp Rept 50-344/83-11 on 830328-0429 No noncompliance noted STERNBERG D M Region 5. Office of Datector 83/05/23 MITHERS, B D Portland General Ejectrac Co 2pp 18737 339 24X Fiche 50-344,83/05/23,8304070015
- --8306070017 IE Insp Rept 50-344/83-11 on 830328-0429 No noncompliance moted Major areas inspected plant operations, surveillance testing, security, maint, refueling & followup on corrective action to NUREO-0737 items MALMROS.M H , DODDS.R, T Region 5, Office of Director 83/05/19 6pp. 18737 341. 24X Fiche 50-344,89/05/23,8304070015
- 8306280131 Forwards IE Insp Rept 50-344/83-09 on 830328-0401 No noncompliance noted NORDERHAUG, L. R. Region 5. Office of Director 83/06/03. WITHERS, B. D. Portland General Ejectric Co. 2pp. 19015-001 24X Fiche 50-344,83/06/03.8306280131
- --8306280136 TE Insp Rept 50-344/83-09 on 830328-0401 No noncompliance noted Major areas inspected emergency preparedness plan & implementing procedures
 ZURAKOMBKI.P.R., SCHUSTER.M D. Region 5, Office of Director 83/06/03 11pp 19015 003 24X Fishe 50-344.83/06/03,8306280131
- 8306100166 Forwards IE Safeguards Insp Rept 50-344/83-14 on 830523-26 No noncompliance noted Rept withheld (ref 10CFR2 790) NORDERHAUGL R Region 5. Office of Director 83/06/66 WITHERS, B. D. Portland General Electric Co 2pp. 18801 196 24X Fiche 30-344,83706/06,8306100166
- 8306130415 Requests exemption from 10CFR50 48(c) schedule requirements, per 10CFR50, 12, for completion of fire protection mode at fuel & auxiliary bldg 45-ft elevations Deferral requested due to const manpower commitment WITHERS, 8, D. Partised General Electric Co. 83/06/07 CLARK, R. A. Operating Reactors Branch 3. 2pp. 18823 136 24% Fiche 50-344,83/06/07,8306130415
- 8306170148 Ack receipt & provides evaluation of four sets of changes to listed emergency plan implementing procedures Changes do not decrease effectiveness of emergency response planning Review of Procedure EP-1. Rev 7 will be completed in near future NORDERHAUG.L R. Region 5, Defice of Director. 83/06/13 WITHERB.B Portland General Electric Co 2pp 18878 349 24X Fiche. 50-344.83/06/13.8306170148
- 8305200191 Forwards rev to Security Plan PGE-1017. Rev withheld WITMERS.B.D. Portland General Electric Co 83/05/14 Office of Nuclear Reactor Regulation, Director 2pp 18903.196 24X Fiche: 50-344. 83/05/14. 8305200191
- 8306240256 Requests reconsideration of denial of exemption request in SECY-83-199 re primary emergency operations facility (ROF) Current EOF location found acceptable by Region V.FEMA & state & local govts
 WITHERS.B D. Fortland General Electric Co. 83/06/17 DENTON,H R
 Office of Nuclear Reactor Regulation Director App 1898: 315
 24X Fiche 50-344,83/06/17,8306240256

H General correspondence

- B306270394 Requests NRC-specific style guide re util documents to promote consistency & cost effectiveness in producing documents ROUSE.E A. Portland General Electric Co. 83/06/20 NRC No Detailed Affiliation Given 2pp 18974:150 24X Fiche: 50-344.83/06/20.8306270374
- I. Financial information
- 9306200207 Forwards Annual Financial Repts 1982. WITHERS, B D Portland General Electric Co 83/06/07 CLARK, R A Operating Reactors Branch 3 ip 18902 154 24X Fiche: 50-344, 83/06/07, 8306200207.
- ~~8306200210 Annual Financia) Rept 1982. SHORT, R. H., LINDBLAD, W. J. Portland Gameral Electric Co. 83/06/07 38pp 18902:155 24X Fiche 50-344.83/06/07.8306200207.
- --8306200283 Annual Financial Rept 1982 FRISBEE: D Pacific Power & Light Co 83/06/07 46pp 18902,196 24% Fiche, 50-344,83/06/07,8306200207
- --8306200215 Annual Financial Rept 1982 TIFFANY, J.A. Eugene Water & Electricity Board 83/06/07, Sipp 18902-243, 24X Fiche 50-344,83/06/07,8306200207,

J Insurance & indemnity information

- B306030293 Forwards Endorsement 51 to NLIIA Policy NF-225 & MACIU Policy NF-26 JOHANSEN,E Portland General Cleatric Co 83/05/05 SALT/MAN,J Office of State Prugrams, Director 3pp 18703 334 24X Fiche 50-344,83/05/05,8306030293
- P Operating license stage documents & correspondence
- 8306070209 Forwards preliminary Cycle VI radial peaking factor rept as followup to util 830509 ltr No changes expected in final rept WITHERS, B.D. Portland General Electric Co. 83/05/23 MARTIN, J.B. Region 5, Office of Director. 20p 18747-051 24X Fiche 50-344.83/05/23-8306070209
- 8304010314 Advises that performance of load test in excess of 100% of max load unnecessary since crane operator training & safety programs ensure safest possible operations in response to 801222 ltr re control of heavy loads (NUREG-0612) MITHERS, B D Portland General Electric Co 83/05/24 EISENNAT, D & Division of Licensing 3pp 18682 138 24% Fiche 50-344, 83/05/24, 8306010316
- 8304040357 Notice of consideration of issuance of amend to License NPF-1 & proposed no significant hazards consideration determination & opportunity for hearing CLARK A Operating Reactors Branch 3 83/05/24 9pp 18751 273 24% Fiche 50-344.83/05/24.8306060357
- 830-6060377 Advisos that NUREG-0737. Items II F 1 4. "Containment Pressure Monitor, II F 1 5. "Containment Water Level Monitor" & II F 1 6. "Containment Hydrogen Monitor." resolved.per B21217 submittal Safety evaluation end CLARK, R A Operating Reactors Branch 3 83/05/24 WITHERH, B D Portland General Electric Co 9pp 18/50 938 24X Fiche 50-344,83/05/24.8306060377
- 8306030241 Advises that revised schedule for submittal of certain care physics data for Cycle 6 core acceptable Data will be available approx 30 days prior to scheduled criticality, CLARK.R A Operating Reactors Branch 3 83/05/25 WITHERS B D Portland General Electric Co 2pp 18/34 022 24X Fiche 50-344,83/05/25,8306030241
- 8304080332 Forwards request for addl info re potential modflows from postulated failure of Spirit Lake blockage Info required within 30 days of ltr receipt CLARK.R A Operating Reactors Branch 3 83/05/27 WITHERS, B D Portland Gengral Electric Co 2pp 18787 359 24% Fiche 50-344,83/05/27,8304080332
- 8306070207 Forwards License Change Application 93 requesting amend to License NPF-1 Amend modifies balanced flow criteria for HPBI & LPSI lines Amend needed to enter Mode 3 on 830707 Certificate of Svc and ROEML. D. J. Portland General Electric Co. 83/06/03 CLARK.R & Operating Reactors Branch 3 Spc 15/47 065 24% Fiche 50~344,83/06/03,8306070207
- --8306070211 Application for amend to License NPF-1.modifying balanted flow criteria for high & low pressure safety injection lines
 IRCEHL, D.J. Portland General Electric Co. 83/06/03 4pp 18747 068 24% Fichs 50-344.83/06/03,8304070207
- --8306070213 Proposed Tech Spec replacement pages re flow balance testing for ECCS # Portland General Electric Co 83/06/03 2pp 18747 072 24X Fichs: 50-344,83/06/03.8306070207
- 8306170303 Requests extension until 830729 for submittal of GA pregram Extension due to imminent organizational changes WITHERB, B D Portland General Electric Co 83/06/03 MARIIN. J B Region 5, Office of Director ip 18878 215 24X Fiche 50~344.83/06/03.8306170303
- B306160255 Notice of consideration of issuance of amend to Lirense NPF-1 & proposed no significant hazards consideration determination CLARK, R A Operating Reactors Branch 3 B3/06/10 App 18892 341 24X Fiche 50-344,63/06/10,8306160255
- B306160645 Requests notice of consideration of issuance of amend to License NPF-1 & proposed no significant hazards consideration determination & opportunity for hearing resumber testing be published in FR.
 CLARKER A Operating Reactors Branch 3 B3/06/10 KREUTZER,P.M Operating Reactors Branch 3 B9/06/10 KREUTZER,P.M Operating Reactors Branch 3 Spp 18804 328 24X Fiche: 50-344,83/06/10.8304160645

DOCKETED ITEMS

- 8306280613 Clarification to 830603 application to amend License NPF-1, modifying flow balance of cold leg high-pressure safety injection lines BROEHL, D. J. Portland General Electric Co. 83/06/21 CLARK, R. A. Operating Reactors Branch 3. App. 17016 003 24x Fiche 50-344,83/06/21,8306280613
- --8306280617 Proposed Tech Spec re flow balance of cold-leg,high-pressure safety injection lines

 Fortland General Electric Co 83/06/21 Jp 19016 007 24%
 Fiche 50-344.83/06/21.8306280613
- § Inspection reports, IE Bulletins & correspondence
- 8306100009 Addl response to FOIA request for documents dtd 820101 or after re SALP Forwards App A documents Documents also available in PDR FGLTON.J M Division of Rules and Records 83/04/11 CLARK.R Sat Francisco Examiner 3pp 18815 252 247 Fiche 50-000,83/04/11,
- ~~8305100014 Bubmits schedule for Region V SALP Board meetings for 820928-830323 ENGELKEN,R H Region 5, Office of Director 82/03/19 DENTON,H R Office of Nuclear Reactor Regulation, Director 1p 18815 285 24X Fiche 50-000.83/04/11.8305100009
- --8306100036 Discusses assignment of SALP coordinators for Reactor Operations Projects Branch facilities Coordinators will be responsible for preparing input data used by board members in analyzing functional areas Draft note from S Miner encl STERNBERG, D M Region 5, Office of Director 02/03/24 Region 5, Office 02/03/24 Region 5, Office 02/03/24 Region 5, Office 02/03/24
- 830&070075 Forwards 1E Insp Rept 50-344/83-10 on 830418-22 No noncompliance noted STERNBERG,D M Region 5, Office of Director 83/05/11 WITHERS,B D Portland General Electric Co 2pp 18737 274 24X Fiche 50-344.83/05/11.830&070075
- --8306070083 IE Insp Rept 50-344/83-10 on 830418-22 No noncompliance noted. Hajor areas inspected offsite support staff, GA/QC administration program, followup on previous insp findings & IE bulletin & independent insp MILLETT, D J, DGDDS, R T Region 5, Office of Director 83/05/11 640 18739 276 24% Fichs 50-344, 33/05/11, 8306070075
- 830AD70009 Forwards IE Insp Rept 50-344/83-13 on 830509-10 No noncompliance noted Insp conducted in Region V ofc BOOK, H E. Region 5, Office of Director 83/05/20 WITHERS, 8 O Portland Geneval Llectric Co 2pp 18737 333 24X Fiche 50-344,83/05/20,8306070009
- --B305070011 IE Insp Rept 50-344/83-13 on 830509-10 No noncompliance noted Major areas inspected results of split sample of liquid waste obtained during B30117-20 Insp Insp conducted in Region V ofc HAMADA: O H : WENSLAWSKI.F : BOOK.H E. Region 5, Office of Director 83/05/20 App 18737 335 24X Fiche 50-344.83/05/20.8306070009
- 8306070015 Forwards IE Insp Rept 50-344/83-11 on 830328-0429 No noncompliance noted STERNBERG, D M Region 5, Office of Director 83/05/23 MITHERS, B D Portland General Electric Co 2pp 18737 339 24X Fiche 50-344,83/05/23
- --8306070017 IE Insp Rept 50-344/83-11 on 830328-0429 No noncompliance noted Major areas inspected plant operations, surveillance testing, security, maint, refueling & followup on corrective action to NUREG-0737 items HALMROS, M H , DODDS, R T Region 5, Office of Director B3/05/17 dpp. 18737 341 24% Fiche 50-344,83/05/23,8306070015
- 8305110458 IE Info Notice 83-32. "Ruptured Am-241 Sources Contained in Hell Logging Device" Svc list encl
 TAYLOR, J. M. Division of Safeguards & Inspection Programs (Post B30103) 83/05/26 Consolidated Edison Co. of New York, Inc 125pp 18831 043 24X Fiche 50-000,83/05/26,8305110458.
- 8305110460 lE Info Notice 83-34, "Event Notification Info Worksheet "
 Byc list encl
 JORDANA,E.L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/05/26 Consolidated Edison Cp of New
 York, Inc. 115pp 18732-085 24X Fiche 50-000,83/05/26,8305110460
- 8305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods Withdrawn at BWRs " Bvc list encl.
 JORDANIE L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/31 Consolidated Edison Co of New York, Inc 116pp 18732, 208 24% Fithe 50-000, 83/05/31, 8305110461

- 8306280333 Forwards IE Insp Rept 50-344/83-15 on 830516-20 No noncompliance noted STERNBERG.D M Region 5, Office of Director. 83/06/02 WITHERS,B D Portland General Electric Co 2pp 19001 223 24X Fiche 50-344,83/06/02.8304280333
- --B306280337 IE Insp Rept 50-344/83-15 on 830516-20 No noncompliance noted Major areas inspected inservice inspectivities MAGNER, W J , ZWETZIG, 0 B Region 5, Dffice of Director, B3/06/01 4pp 19001 225, 24X Fiche 50-344.83/06/02,8306280333
- 8306280131 Forwards IE Insp Rept 50-344/83-09 on 830328-0401 No noncompilance noted NORDERHAUG,L R Region 5. Office of Director 83/06/03 HITHERS,B D Portland General Electric Co 2pp. 19015 001 24X Fiche 50-344,83/06/03,8306280131
- --8306280136 IE Insp Rept 50-344/83-09 on B30328-0401 No noncompliance noted Major areas inspected emergency preparedness plan & implementing procedures ZURAKOMSKIF R., SCHORTER, M D. Region 5, Office of Director 83/06/03
- 8306100166 Forwards 1E Safeguards Insp Rept 50-944/83-14 on B30523-26. No noncompliance noted Rept withheld (ref 10CFR2 790). NORDERHAUG, L. R. Region 5, Office of Director. B3/06/06 HITHERS, B.D. Portland General Electric Co. 2pp 18801, 196 24X Ficher 50-344, 83/06/06, 8306100166
- 8304170400 Updates status of plant mods to resolve in-plant communication sys deficiencies identified in response to IE Bulletin 79-18, "Audibility Problem Encountered on Evacuation of Personnel From High Noise Areas "
- 8305110464 IE info Notice 83-36, "Impact of Security Practices on Safe Operations " Svc list encl UDRDAN E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/09 Consolidated Edison Co of New York, Inc 119pp 18830 880 24X Fiche 50-000.83/06/09.8305110464.
- 8306280620 Forwards IE Insp Rept 50-344/83-12 on 830502-06 No noncompliance noted BOOK: HE Region 5, Office of Director 83/06/10 WITHERS, B D Portland Cameral Electric Co 2pp 19016-008, 24X Fichs: 50-344, 83/06/10, 8306280620
- --8306R80632 IE Insp Rept 50-344/83-i2 on B30B02-06 No noncompliance noted Major areas inspected radiation protection program, including procedures, surveys, general emplayee training, posting & labeling & internal & external exposure control CILLIS:M, WENSLAMSKI,FA, BDOK,H.C. Region 5, Office of Director B3/06/10 lipp 17016 010. Z4X Fiche 50-344,B3/06/10,8306280620
- 8305110470 IE Info Notice 83-38, "Defective Heat Sink Adhesive & Seismically Induced Chatter in Relays Within Printed Circuit Cards " Bvc list encl JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co. of New York, Inc 118pp 18920 225 24X Fiche 50-000,83/06/13,8305110470.
- 8304090010 IE Info Notice 83-37, "Transformer Failure Resulting From Degraded Internal Connection Cables " Svc list encl.
 JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consultidated Edison Co of New York, Inc. 243pp 18921:001, 24X Fiche, 50-000, 83/06/13, 8306090010.
- B306240316 Forwards invoice covering extraordinary expenses incurred during performance of 1983 LAEA spent fuel insp Transmittal of invoice to LAEA requested for reimbursement HITHERS.B.D. Portland General Electric Co. 83/06/17 DENTON.H.R Office of Nuclear Reactor Regulation, Director 3pp 18980 154 24X Fiche: 50-344.83/06/17.8306240316
- 8305110475 IE Info Notice 83-40. "Need to Environmentally Qualify
 Epoxy Grouts & Sealers " Svc list encl
 JORDAN, E. L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/06/22 Consolidated Edison Co of New
 York, Inc 115pp. 19021 177 24X Fiche 30-000,83/06/22,8305110475
- 8305110477 IE Info Notice 83-41, "Actuation of Fire Suppression Bys Causing Inoperability of Safety-Related Equipment." Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/22 Consolidated Edison Co. of New York, Inc. 120pp. 18997-007 24X Fithe 50-000, B3/06/22, B305110477

- 8305110479 IE Info Notice 83-42: "Reactor Mode Switch Malfunctions" Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83705/23 Consolidated Edison Co of New York, Inc 115pp 18996 242 24X Fiche 50-000,83705/23,8305110479
- 8305110483 IE Info Notice 83-43, "Improper Settings of Intermediate Range (IR) High Flux Trip Betpoints " Svc list enc! JURDAN E L Division of Emergency Preparedness & Engineering Response (Fost 830103) 83/06/24 Consolidate Edison Co of New York, Inc 116pp 19046 297 24X Fiche 50-000.83/06/24.8305110483
- R. Periodic operating reports & related correspondence
- 8306020119 Monthly operating rept for Mar 1983 W/830407 ltr KAMMEYER,D J , YUNDT,C P Portland General Electric Co 83/04/07 6pp 18691 227 24X Fiche 50-344,83/04/07.8306020119
- 8306160392 Monthly operating rept for Apr 1983 W/830506 ltr KAMMEYER.D J , YUNDT.C P. Portland General Electric Co 83/05/06 9pp 18861 143 24X Fiche 50-344,83/05/06,8306160392
- 8305200152 Monthly operating rept for May 1983 W/830513 ltr KENT.O.J. YUNDT.C P Postland General Electric Co 83/05/13 ADP Systems Development Branch 3pp 16903 113 24X Fichs: 50-344, 83/05/13, 8305200152
- 8 Reportable occurrences, LERs & related correspondence
- 8306010073 LER 83-002/03L-0 on 830122, after securing auxiliary feedwater pumps following auto-start two steam generator levels reached to-lo level causing reactor trip Caused by licensed operator error. W/830516 ltr BLAIR. 9.0. YUNDT. C.P. Portland Ceneral Electric Co. 83/05/16 HARTIN, J.B. Region 5. Office of Director. Spp. 18674-091-242 Fiche: 50-344, 83/05/16, 830601007.3
- 8306070071 LER 83-004/03L-0: on 830426, level transmitters LT-517 for steam generator A discovered out of calibr Caused by instrument drift Transmitter immediately recalibr & calibr date will be observed to detect degradation H/830525 ltr BAIR. @ 0 . YUNDT. C P. Portland Ceneral Electric Co 83/03/25. HARTIN. J B. Region 5. Office of Director 3pp 18740 087 24X Fiche. \$0-344,83/05/25,8306070071
- 8306070212 RO on B30525, during refueling outage, MSIVs did not shot as required per Tech Baccs & SAR Condition prevented restriction of single steam generator blowdown during certain steam line break accidents w/MSIV Failure YUNDT, C.P. Portland General Electric Co. 83/05/26 MARTIN, J.B. Region 5, Office of Director ip 18747.045 24X Fiche, 50-344,83/05/26,8306070212
- 8306170317 LER 83-005/03L-0 on 830504, pressurizer level transmitter LT-461 found out of calibr Caused by instrument drift Instrument recalibr W/830606 ltr BAIR. 0. 0 , YUNDT, C P Portland General Electric Co. 83/06/06 MARTIN. J B, Region 5. 04fice of Director 4pp 18877 064 24x Fiche 80-344,83/06/06.8306170317
- 8306170193 LER 83-006/03L-0 on 830317, four main steam nonreturn check valves found stuck open Analysis completed on 830524 showed possible insufficient torque to close valves, Caused by pacting induced friction, Packing adjusted W/8306081tr.

 BAIR: 0 0 . YUNDT, C. P. Portland General Electric Co. 83/06/08, MARTIN, J. B. Region 5. Office of Director. 4pp. 18882 281. 24X Fiche: 50-344, 83/06/08, 8306170193
- DOCKET 50-346 DAVIS-BESSE NUCLEAR POHER STATION, UNIT 1 F. Becurity, medical, emergency & fire protection plans
- 8306090057 Releases public version of Rev 178 to emergency plan supporting procedures rev index FELTON, J M Division of Rules and Records 83/06/01 Document Management Branch ip. 18797: 348. 24X Fiche: 50-346, 83/06/01, 8306090057.
- --8306090060 Public version of Rev 178 to emergency plan supporting procedures rev index. W/830913 ltr receipt form.
 * Toledo Edison Co. 83/05/13 2pp 18797 349 24X Fiche: 50-346.83/06/01.8306090057.
- 8304090281 Releases public version of revised emergency plan supporting procedure administrative memo & rev index FELTON, J. M. Division of Rules and Records. 83/04/01. Document Management Branch. ip. 18810; 035 24X Fiche. 50-346, 83/04/01, 8304090281.

- --8306070283 Public version of Rev 15 to Emergency Plan Supporting Procedure Administrative Memo 39, "Fire Brigade" & Rev 179 to rev index #/830519 1tr MURRAY.T D Toledo Edison Co 83/05/13 4pp 18810 026 24x Fiche 50-346.83/06/01.8306090281
- 8305150676 Releases public version of revised emergency plan administrative procedure FELTON. J M Division of Rules and Records 83/05/01 Document Management Branch ip 18876 300 24% Fiche 50-344.83/06/01. 8306160676
- --8306160679 Public version of Rev 13 to Emergency Plan Administrative Procedure AD 1827 10. "Emergency Offsite Dose Estimates" & Rev 177 to rev index W/830311 ltt & receipt form HURRAY, T D Toledo Edison Co 83/05/05 35pp 18876 301 241 Fiche 50-346.83/06/01/8306160676
- 8306090370 Releases public version of revised emergency plan implementing procedure FELTON. J M Division of Rules and Records 83/06/06 Document Management Branch 1p 18814-018 24X Fiche 50-346-83/06/06
- --9306090375 Public version of Rev 4 to Emergency Plan Implementing Procedure EI 1300 07 0, "Technical Support Ctr Activation" & rev index MURRAY.T D Toledo Edison Co 83/04/07 12pp 16014 019 24% Fiche 50-346, 83/06/06.8306090370
- 8304340696 Releases public version of temporary mod request FELTON. J M Division of Rules and Records 83/06/06 Document Management Branch 1p 18876 293 24% Fiche 50-346.83/06/06.
- --8306160690 Public version of Temporary Mod Request T-7111 to Emergency Plan Implementing Procedure AD 1827 10, "Offsite Dose Calculations " Rev 174 to rev index encl DONNING, G Toledo Edison Co 83/04/12 3pp 18876 294 24X Fiche 50-346,83/06/06,8306160686
- 8306170075 Forwards Temporary Mod T-7187 to Rev 19 to industrial security plan Mod withheld (ref 10CFR73 21) CROUSE, R. P. Toledo Edison Co. 83/06/07 Office of Nuclear Reactor Regulation, Director 1p. 19878 358 24X Fiche 50-346,83/06/07,8306170075
- B304220252 Releases public version of updated emergency plan & revised emergency plan implementing & station supporting procedures FELTON.J M Division of Rules and Records B3/06/07 Document Hanagement Branch 1p 18938 001 24X Fichs 50-344,83/06/07, 8306220252
- --8306220257 Forwards public version of updated emergency plan & revised emergency plan implementing & station supporting procedures Receipt form encl CROUSE, R P Toledo Edison Co 83/05/04 DENION, H R Office of Nuclear Reactor Regulation, Director 2pp 16938 002 24% Fiche 50-346,83/06/07,8306220252
- ~~9304820240 Public version of updated emergency plan MURRAY.T Totedo Edison Co 83/05/01 Office of Nuclear Reactor Regulation, Director 316pp 18938 004 24X Fiche 50~346.83/06/07.830620252
- --B306220263 Public version of revised emergency plan implementing & supporting procedures, including Procedures EI 1300 00 re station response, EI 1300 01 re emergency plan activation & EI 1300.02 re unusual events MURRAY, T Toledo Edison Co 83/05/01 Office of Nuclear Reactor Regulation, Director. 424pp 18938 320 24% Fiche. 50-346, 83/06/07, 8306220252
- 8306130298 Forwards IE Bafeguards Insp Rept 50-346/83-08 on 830502-06 b notice of violation.Notice of violation withhold (ref 100FR73, 21) HIND, J. A. Division of Radiological & Materials Safety Programs. 83/06/10. CROUSE, R. F. Tolede Edison Co. 2pp 18822 189 24X Fiche 50-346/83/06/10.8306130298
- --B306130319 IE Bafeguards Insp Rept 50-346/83-08 on 830502-06 Noncompliance noted security investigation results not properly documented Details withheld (ref 10CFR73 21). PIRTLE, 0 L , BELANGER, J.L., CREED, J R Region 3, Office of Director 83/06/09. 2pp 18828,191, 24% Fiche 50-346,83/06/10,8306130298
- 8306210161 Ack receipt of 830520 ltm informing NRC of steps taken to correct violations noted in IE Insp Rept 50-346/83-03. PAPERIELLO.C J Region 3, Office of Director. 83/06/15 CROUSE, R.P. Toledo Edison Co. ip. 18917, 003 24X Fichs: 50-346, 83/06/15, 8306210161

- --8306210170 Responds to NRC 830422 ltm re violations noted in IE Insp Rept 50-346/83-03 Corrective actions procedures revised to reemphasize methods available for contacting Ottawa County sheriff & shift supervisor provided with addl guidance CROUSE R P Toledo Edison Co 83/05/20 KEPPLER J & Region 3. Office of Director 7pp 18917 004 24X Fiche 50-346,83/06/15, 8306210161
- 8304270204 Ack receipt of 830516 ltr re emergency planning exercise for May 1983 per IE Insp Rept 50-346/83-07 No violations or deviations noted Response to weaknesses identified in observations over exercise period and CROUSE.R P Toledo Edison Co 83/06/21 KEPPLER, J G Region 3, Office of Director 6pp 18991 264 24X Fiche 50-346,83/06/21,8306270204
- P Operating license stage documents & correspondence
- 8306030503 Forwards safety evaluation supporting response to TMI Items I A 2 1.4 & II B 2 Requirements natisfied BEAQASIO, A Operating Reactors Branch 4 B3/08/13 CROUSE, R P Toledo Edison Co 4pp 18747 167 24X Fiche 50-346.83/09/13.
- --8209030325 "Improvements in Training & Requalification Programs As Required By TMI Action Items I A 2 i & II B 4 for Davis-Besse Nuclear Power Station," technical evaluation rept

 * Science Applications, Inc NRC-00-82-094 GAI-186-029-28
 B2/08/31 NRC No Detailed Affiliation Given 15pp
 18747 172 24X Fiche 50-346,83/05/13,8304030503
- 8306150508 Forwards BER supporting 830128 submittal re TMI Action Plan Itums II F.1 4. "Containment Pressure Monitor," II F.1 5. "Containment Water Level Monitor," & II F.1 6. "Containment Hydrogen Monitor," Requirements met BTOLZ,J F. Operating Reactors Branch 4 83/05/24 CRGUSE,R P. Toledo Edison Co. 2pp. 18866-313 24X Fichs 50-346.83/05/24. 8306150508
- --8306180515 Bafety evaluation supporting licenses 830128 submittal re NUREQ-0737, Items II F 1 4, "Containment Pressure Monitor," II F 1 5, "Containment Water Level Monitor: " & II F 1 6, "Containment Hydrogen Monitor " Requirements met. " Office of Nurlear Reactor Regulation, Director 83/05/24 5pp 18866 315 24X Fiche 50-346,83/05/24,8306150808
- B3060B0234 Forwards BER on 810313 revs to spismic reanalysis contained in Amend 30 to License NPF-3 Revs acceptable 810L7.J F Operating Reactors Branch 4 83/05/31 CRQUBE, R P Toledo Edison Co 2pp 18785 321 24X Fiche 50-346.83/05/31.83040B0234
- --8306080237 Safety evaluation supporting 810313 revs to Amend 30 to License NPF-3 re seismic reanalysis of piping sys & components
 * Office of Nuclear Reactor Regulation, Director 83/05/31. App 18785:323 24X Fichs 50-346
- 8304140703 Forwards request for add1 info re natural circulation condown.per Generic Ltr 81-21 Rev to 820127 response requested Demonstration of void formation necessary for demonstrating adequacy of procedures STOLZ. J F Operating Reactors Branch 4 83/06/01 CROUSE.R.P Toledo Edison Co. 4pp 18844.358 24X Fiche 50-346.83/06/01.8304140703
- B306220215 Designates O Lainas as licensing contact to coordinate staff interactions w/D&W Dumers Group subcommittees re generic regulatory issues.

 DENTON, H. R. Office of Nuclear Reactor Regulation. Director B3/O6/O1. CROUSE.R.P. Toledo Edison Co. CROUSE.R.P. Babcock & Wilcox Operating Plants Owners Group Spp. 18951.015 24X
 Fiche. 50-346.63/O6/O1.6306220215
- 8306140377 Forwards revised Table D-1, "Preliminary Stress Level Comparison," showing value of stress concentration factor & higher casculated peak stresses Higher peak stresses do not affect conclusions from 830506 meeting, Heeting summary encl TAYLOR. J. H. Rabcock & Wilcox Co. 83706707. MINER. S. NRC No Detailed Affiliation Given 2pp. 18844 001 24X Fiche. 50-000, 83/06/07, 8306140377.
- 8306140500 Forwards responses to 801222 Itr re NUREG-0612, "Control of Heavy Loads at Nuclear Power Plants," Info addresses overhead Anndling sys for fuel storage pool CHOUSE, R P Tolado Edison Co. 83706/10, 970LZ, J F Operating Reactors Branch 4 142pp 18843 096 24% Fiche 50-346,83/06/10, 830440500

- 8306170027 Advises that 830520 B&W Task Force rept, "Summary Rept of NRC/B&W Comers Group Meeting on Reactor Vessel Internals Bolting 830806.BAW-1784." constitutes basis for continued operation per 830506 presentation CROUSE,R P Toledo Edison Co 839/06/10 8YOLZ.J F Operating Reactors Branch 4 ip 18878 286 24X Fiche 50-346.83/06/10, 8304170027
- B30A200393 Application for amend to License NPF-3 revising Tech Spec surveillance test requirements to include flow test to verify mormal path availability of auxiliary feedwater to steam generator Class III amend fee encl
 GROUSE, R P Toledo Edison Co 83/04/15 970LZ, J F Operating Reactors Branch 4 4pp 18899 041 24X Fiche 50-346, 83/06/15, 830A200393
- ~-8306200394 Proposed Tech Specs revising surveillance test requirements to include flow test to verify normal path availability of auxiliary feedwater to steam generator

 * Toledo Edison Co. 83/06/15 2pp 18899 045 24X
 Fiche 50-346/83/06/15/8306200393
- 8306210026 Responds to 830314 ltr re-order requiring completion of TMI Item II F.1 5 on containment water level by 830615 Environ & seismic qualification repts received & under review.

 CROUSE.R P Toledo Edison Co 83/04/15 STOLZ, J F Operating Reactors Branch 4 ip. 18910 359 24X Fiche 50-346,83/04/15,8306210026
- 8306230259 Forwards Rev O to "Detailed Control Room Design Review (DCRDR) Program Plan for Davis Besse Nuclear Power Plant," in response to NRC 821217 ltr & commitments per util 830415 ltr CRRUSE.R P Toledo Edison Co 83/04/15 STOLZ, J F Operating Reactors Branch 4 lp. 18945 021 24X Fiche 50-346,63/06/15,8306230259.
- --8306230262 Rev O to "Detailed Control Room Design Review (DCRDR)
 Program Plan for Davis Besse Nuclear Power Plant "
 * Toledo Edison Co. 83/06/15 50pp 18945:022 24X
 Fiche 50-346:83/06/15.8306230259
- Q Inspection reports, IE Bulletins & correspondence
- 8306270379 Ack receipt of 830324 ltr summarizing IE Enforcement Conference Rept 30-346/83-06 on 830309 Util 830429 ltr formally submits maint & drawing control programs outlined at conference.

 CROUBER P Toledo Edison Co 83/03/20 NORELIUS, E Division of Project & Resident Programs ip 18994 154 24X Fiche: 50-346, 63/05/20, 8306270379
- 8305:10458 IE Info Notice 83-32. "Ruptured Am-241 Sources Contained in Well Logging Device " Eve list encl TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830:03) 83/05/26 Consolidated Edison Co of New York, Inc. 125pp 1883: 043 24X Fiche.50-000.83/05/26.8305:10458
- 8305110460 IE Info Notice 83-34, "Event Notification Info Worksheet" Byc list encl JURDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co. of New York, Inc 115pp 18732,085 24X Fiche. 50-000, 83/05/26, 8305110460.
- 8305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods Withdrawn at BWRs " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/31 Consolidated Edison Co of New York, Inc 116pp 18732 208 24% Fichs 50-000, 83/05/31, 8305110461.
- B304070155 Ack receipt of B30513 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-346/83-04.
 STREETER: J F Region 3, Office of Director 83/06/01. CROUSE: R P Toledo Edison Co 1p. 18736.237. R4X Fiche 50-346.83/06/01.
 B306070155
- --8306070166 Responds to NRC 830427 ltr re violations noted in IE Insp. Rept 50-346/83-04 Corrective actions policy of waiving radiological controls training for chemistry & health physics dept parsonnel rewritten CROUSE.R P Toledo Edison Co. 83/09/13 NORELIUS.C. E Region 3, Office of Director. 3pp 18796-238, 24X Fichs 50-346.83/06/01.8306070155
- 830&070397 Forwards rev to inservice insp pump & valve program submitted on 800515. Changes reflect results of 830525-2& telcons w/NRC Symposis of current program changes; relief requests & specific program changes encl
 CRCUSE, R. P. Tolado Edison Co 83/06/02 STOLZ, J. F. Operating Reactors Branch 4 13pp. 18742:003, 24X Fiche: 50-34& 83/06/02, 8306070397

- 830&i4044B Responds to IE Bullstin 83-03, "Check Valve Failures in Raw Mater Cooling Bus of Diesel Generators," Plasel generators cooled by water supplied from component cooling water sus. Three 14-inch Valan check valves used for testing CROUSE.R.F. Toledo Edison Co. 83/06/02 DEYDUNG.R.C. Office of International Programs, Director. 2pp. 18836-347 24X Fichs 50-346,83/06/02.830614044B
- 8305220037 Forwards IE Insp Rept 50-345/83-05 on 830201-0429 & notice of violation Causes of malfunctions should be determined, evaluated & documented prior to returning squipment to normal operating status.

 NORELIUS, C.E. Division of Project & Resident Programs. 83/05/07.

 CROUSE, R.P. Toledo Edison Co. 2pp. 18930 191 24X

 Fiche: 30-346.83/05/07.8306220037
- --8306220041 Notice of violation from insp on 830201-0427 NORELIUS.C E. Division of Project & Resident Programs. 83/06/07. 2pp. 18730.173. 24% Fiche 50-346.83/06/07.8306220037
- 8306220050 IE Insp Rept 50-346/83-05 on 830201-0429 Noncompliance noted administrative procedures & GA manual did not include controls to prevent procedures from becoming inadequate & follower LER not issued retrip breaker malfunction PEERLEST.A., ROGERS.H 0 . JACKIH.J.N Region 3. Office of Director. 83/06/06, 11pg. 18930, 195. 24X Fiche 50-346,83/06/07,8309R20037.
- 8308110464 IE Info Notice 83-36, "Impact of Security Practices on Safe Operations" Svc list encl URBOAN.E.L., Division of Emergency Preparedness & Engineering Response (Post 830103). 83706/09 Consolidated Edison Co of New York, Inc. 117pp. 18830 R80 24% Fiche 50-000, 83/06/09, 8305110464.
- 8304130298 Forwards 1E Safeguards Insp Rept 50-346/83-08 on 830502-06 & notice of violation Notice of violation withheld (ref 10CFR73 21).

 HIND, J. A. Division of Radiological & Materials Safety Programs, 83/06/10. CROUBE, R. P. Toledo Edison Co. 2pp. 18822, 189 24X Fiche: 50-346, 83/06/10, 8306130298
- --8306i303i9 IE Befeguards Inap Rapt 50-346/83-08 on 830502-06 Noncompliance noted security investigation results not properly documented Details withheld (ref 105R73 21). PIRTLE: 0. L.: BELANGER: J L. CREED. J R. Region 3. Office of Director 83/06/09. 2pp. 18822 191 24X Fichs 50-346,83/06/10,8306i30278.
- 8306230253 Forwards IE Insp Rept 50-346/83-10 on 830504-05 No noncompliance noted. LITTLE: M.B. Region 3. Office of Director 83/06/10. CROUSE, R.P. Toledo Edison Co. 2pp. 18945 219 24X Fiche: 50-346.83/06/10, 8306230253
- ~-8306230255 IE Insp Rept 50-346/83-10 on 830504-05. No nuncompliance noted Major areas inspected; followup of previously identified problem w/containment electrical penetrations HENDEZ, R. WILLIAMS, C. Region 3, Office of Director. 63/06/10, 5pp. 18945-221. 24X Ficher 50-346, 83/06/10, 8306230253,
- 8305110470 IE Info Notice 83-38, "Defective Heat Sink Adhesive & Seismically Induced Chatter in Relays Within Printed Circuit Cards " Svc list and UORDAN E.L. Division of Emergency Preparadness & Engineering Response (Post 830103). 83/06/13 Consolidated Edison Co. of New York, Inc. (18pp. 18720-225, 24% Fiche 50-000,83/06/13,8305110470
- 830&090010 IE Info Notice 83-37. "Transformer Failure Resulting From Degraded Internal Connection Cables." Bvc list encl. JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83706/13 Consolidated Edison Co. of New York, Inc. 243pp. 18921-001. 24X Fiche. 50-000, 83706/13, 8306090010
- 830.6300060 Forwards IE Insp Rept 50-346/83-13 on 830502-06 & 16-20 No noncompliance noted, BIREEYER, J.F. Region 3, Office of Director 83/06/14, CROUSE, R.P. Toledo Edison Co. 2pp. 19120:273. 24X Fiche: 50-346, 83/06/14, 830.6300060.
- --8306300063 IE Insp Rept 50-346/83-13 on 830502-06 & 16-20, No noncompliance noted Major areas inspected instrument calibr procedures & records test & measurement equipment procedures & records & nonroutine reporting procedures FARRELL.R. E., HAMKING.F. C. Region 3, Office of Director, 83/06/14, 4pp 19120:275, 24X Fichs:50-346,83/06/14,8306300060
- 8306210161 Ack receipt of 830520 ltr informing NRC of steps taken to confect violations noted in IE Imag Rept 50-346/83-03 PAPERIELIO, c.J. Region 3, Diffice of Director. 83/06/15. CROUBE, R. P. Toledo Edison Co. ip. 18917-003 24X Time: 50-346,83/06/15,8306210161.

- --8306210170 Responds to NRC 830422 ltr re violations noted in IE Insp. Rept 50-346/83-03 Corrective actions procedures revised to reemphasize methods available for contacting Ottawa County sheriff & shift supervisor provided with addl guidance CROUSE, R.P. Toledo Edison Co. 83/05/20 KEPPLER-J 0 Region 3. Office of Director 7pp. 18917-004 24X Fiche 50-346.83/06/15, 8306210141.
- 8306300022 Forwards IE Insp Rept 50-346/83-12 on 830527 No noncompliance noted LITTLE W S Region 3. Office of Director 83/06/17 CROUSE, R P Toledo Edison Co 2pp 19120 349, 24X Fiche 50-346,83/06/17, 8306300022
- --8306300029 IE Insp Rept 50-346/83-12 on 830527 No noncompliance noted Major areas inspected implementation of IE Bulletin 79-14 & followup on previously identified items YIN, I T., DANIELBUND H. Region 3, Dffice of Director 83/06/17 3pp 19120 351 24X Fiche 50-346,83/06/17,8306300022
- 8304300251 Forwards IE Insp Rept 50-346/83-14 on 830524-24 No noncompliance noted LITTLE, W B Region 3. Office of Director 83/06/17 CROUSE, R (Toledo Edison Co 2pp 19119 343 24X Fiche 50-346,83/06/17,8304300251
- --8306300282 IE Inap Rept 50-346/83-14 on 830524-26 No noncompliance noted Major areas inspected licensee action on previous inspetindings, MENDEZ, R., MILLIAMS, C.C. Region 3, Office of Director 83/06/17 5pp 19119 345, 24X Fiche 50-346,83/06/17,8306300251
- B306270204 Ack receipt of 830516 ltr re emergency planning exercise for May 1983.per IE Insp Rept 50-346/83-07 No violations or deviations noted. Response to weaknesses identified in observations over exercise period encl CROUSE.R P Toledo Edison Co B3/06/21 KEPPLER,J Ø Region 3-04fice of Director Opp 18991 244 24X Fiche 50-346.83/06/21, 830A272004
- 8305110475 IE Info Notice 83-40, "Need to Environmentally Qualify Epoxy Grouts & Bealers " Syc list encl JORDAN, E. L. Division of Chergency Preparedness & Engineering Response (Post 830103) 83706/22 Consolidated Edison Co of New York, Inc 115pp 19021 179 24X Fiche 50-000, 83/06/22, 8305110475
- 8305110477 IE Info Notice 83-41, "Actuation of Fire Suppression Sys-Causing Inoperability of Safety-Related Equipment " Syc list encl. JORDAN, E. L. Division of Emergency Preparedness & Enginearing Response (Post 830103) 83/06/22 Consolidated Edison Co of New York, Inc 120pp 18997,007 24X Fiche 50-000,83/06/22,8305110477
- 8305110479 IE Info Notice 83-42, "Reactor Mode Switch Malfunctions " Evc list encl. JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Pout 830103) 83/06/23 Consolidated Edison Co. of New York, Inc. 116pp 18996 242, 24x Fiche 50-000,83/06/23,8305110479
- 8305110483 IE Info Natice 83-43, "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints," Svc list ancl. JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Past 830103), 83706/24 Consolidated Edison Co. of New York, Inc. 116pp. 19046, 297 24X Fiche 50-000.83/06/24.6305110493
- 8306300044 Confirms arrangements for rescheduling 830627 meeting to discuss SALP, to 830712 at Region III ofc NORELIUS, C.E. Division of Project & Resident Programs. 83/06/24 CROUSE, R P Toledo Edison Co 1p. 19120, 222 24X Fiche: 50-346, 83/06/24, 8306300044
- R Periodic operating reports & related correspondence
- 8306020127 Monthly operating rept for Mar 1983 W/830408 1tr BARSOUR, B., MURRAY, T.D. Toledo Edison Co. 83/04/08 HALLER, N Office of Resource Management, Director 7pp 16691, 246 24X Fichs, 50-346, 83/04/08.8306020127
- 8306160540 Monthly operating rapt for Apr 1783 W/830507 ltr SAMSGUR. B. MURRAY. T. D. Toledo Edison Co. 83/05/09. HALLER, N. Office of Management and Program Analysis. 9pp 18865:051. 24X Fichs 50-346, 83/05/09, 8306160540
- B306170276 "May 1983 Wastewater rept" MURRAY, T D Toledo Edison Co. 83/06/14 Ohio, State of. 9pp 18878: 259 24X Fiche 50-346.83/06/14,8306170276.

- S Reportable occurrences. LERs & related correspondence
- 8306060137 LER 63-027/O3L-0 on 630428, valve RC2408 would not close w/o repeated signals from control room Caused by valve operator torquing out due to dirty & improperly lubricated atem Stem cleaned & torque switch reset W/830526 ltr W/8RRY, T D . LONG, J Toledo Edison Co 63/05/26 KEPPLER, J G Region J, Office of Director 3pp 18719 016 24X Fiche 50-346,63/05/26,8306060137
- 8306100124 LER 83-021/03L-0 on B30502, operator found Fuel Handling Access Corridor Door 406 ajar Caused by failure of closure mechanism Closure mechanism adjusted to force door closed HOLFE, R, MURRAY, J D Toledo Edison Go 83/05/31 KEPPLER, J Q Region 3, Office of Director App 18802 014 24% Fichs 50-346,83/05/31,8306100124
- 8306210262 LER 83-022/03L-0 on 830513, determined erratic generator output in response to speed change input on 830413 reported a caused by loose connection on electronic governor control box Terminal screw cross threaded W/830606 ltr UEBSINO, R. RICHTER, L., MURRAY, T. D. Toledo Edison Co. 83/06/06 KEPPLER, J. G. Region 3, Office of Director 4pp 18915 092 24; Fiche, 50-346, 83/06/06, 8306210262
- 8306170429 Revised LER 83-002/03X-2 on 830115,18,0409,10 & 0510,RCS dose equivalent I-131 exceeded Tech Spec limit Caused by stight fission product leakage through fuel cladding Level of I-131 monitored, W/830607 ltr RICHTER,L. NURRAY,T.D. Taledo Edison Co. 83/06/07 KEPPLER,J Q Region 3, Office of Director 10pp, 18879 050 24X Fiche 50-346,83/06/07,8306170429
- 8306;70414 LER 83-023/03L-0 on 830510, 120-volt ac essential bus Y4 lost-resulting in desnergizing reactor protection t safety features actuation sys Channel 4 Caused by blown fuse in inverter YV4 Power restored to bus, W/830608 ltr ROMLAND, M · HURRAY, T D Toledo Edison Co 83/06/08 KEPPLER, J D Region 3, Dffice of Director. 3pp 18879 001 24X Fiche 50-346,83/06/08,8306170414
- 8306170142 LER 83-024/03L-0 on 830511, while starting up from 830510 reactor trip, quadrant power tilt in quadrant YZ exceeded Tach Spec steady-state limit Caused by inherent design of B&N M888 & negative moderator temp coefficient W/820507 ltr O'CONNOR, B . MURRAY, T D Toledo Edison Co 83/06/09 KEPPLER, J. O Region 3, Office of Director 4pp, 18878, 307 24X Fichs 50-346,83/06/09,8306170142
- 8306210084 LER 83-025/03L-0 on 830429, Fire Detection Zone 410 on containment east passage alarmed & could not be reset Caused by faulty detector string Corrective action planned during next refusing outage W/830610 ltr.

 BORYSIAK, M. MURRAY, T. D. Toledo Edison Co. 83/06/10. KEPPLER, J. O Region 3, Office of Director. 3pp. 16911: 234 24X

 Fiche, 50-346, 83/06/10, 8304210084.
- 8306220007 Part 21 rept re adequacy of fittings supplied by Tube-Line Corp through Capital Pipe & Steel Products Co for use on new auxiliary feedwater headers of steam generators Flanges not heat-treated as required by matl specs
 TAYLOR, J. H. Babcock & Wilcox Co. 83/06/17 DEYOUNG R C. Birector's Office, Office of Inspection and Enforcement 4pp 18927-354. 24X Fiche: 80-000,83/06/17,8306220007.
- DOCKET 50-348 JOBEPH M FARLEY NUCLEAR PLANT, UNIT i F Security, medical, emergency & fire protection plans
- B306090319 Forwards IE Bafeguards Insp Repts 50-348/83-07 & 50-364/83-05 on 830227-0303 & notice of violation Rept details & notice of violation withheld (ref 100FR73 21) LEMISIR C Division of Project & Resident Programs. B3/03/23, MCDONALD.R.P Alabama Power Co 2pp. 18795 112 24X Fiche 50-348.83/03/23.8306090319.
- --8306070324 IE Safeguards Insp Repts 50-348/83-07 % 50-364/83-05 on 830227-0303 Moncompliance noted failure of vital area elarms in access mode to indicate tamper Details withheld (ref 10CFR79, 21).

 MOORE, D. E. Region 2, Office of Director MCGUIRE, D. R. Division of Emergency Preparedness & Materials Safety. 83/03/23. 1p 18795-114. 24X Fichs 50-348, 83/03/23, 8306070319.
- B306020570 Comments on NUREO-0737, Item III A.2 i, "Emergency Preparedness, Upgrade Emergency Plans to App E.10CFR50." Unsite & offsite emergency preparedness adequate, Item closed. VAROA, B.A. Operating Reactors Branch 1. B3/05/24 CLAYTON.F. L Alabams Power Co. 2pp 18715 066. 24X Fiche 50-348,83/05/24. B306020570.

- 8306010332 Forwards IE Safeguards Insp Repts 50-348/83-14 & 50-364/83-12 on 830509-13 No noncompliance noted. VERRELLI, D Division of Project & Resident Programs 83/05/26 MCD0NALD, R P Alabama Power Co 2pp 18682 150 24X Fiche 50-348, 63/05/26, 8306010332
- --8306010333 IE Bafeguards Insp Repts 50-348/83-14 & 50-364/83-12 on B30507-13 No noncompliance noted Major areas inspected site orientation, security organization-mgt, personnel & response. Details withheld (ref 10CFR/3 21)
 HALL.B L Region 2, Office of Director MCQUIRE.D R Division of Emergency Preparedness & Materials Safety 83/05/24 1p 18682, 192 24X Fichs 50-348,83/05/26.8306010332
- 8306140645 Forwards IE Insp Repts 50-348/83-11 & 50-364/83-09 on 830418-22 No noncompliance noted VERRELLI.D M Division of Project & Resident Programs 83/05/26 MCD0NALD.R P Alabama Power Co 2pp. 18841 242, 24X Fichs 50-348,83/05/26,8306140645
- --B306140655 IE Insp Repts 50-348/83-11 & 50-364/83-09 on B30418-22.No nancompliance noted Major areas inspected emergency preparedness MARBIDN.R.R. Region 2, Office of Director. JENKINB.G.R. Division of Emergency Preparedness & Materials Bafety. 63/05/24 App. 18841: 244 24X Ficher 50-348, B3/05/26, B306140645.
- 8306090204 Releases public version of emergency plan administrative procedures
 FELTON, J. M. Division of Rules and Records 83/06/01 Document Management Branch. 1p. 18809-229 24X Fiche: 50-348, 83/06/01, 8306090204
- --8306090208 Public version of Emergency Plan Administrative Procedure FNP-83-0497. "On-Call Schedule " Schedule will be filed w/Procedure FNP-0-EIP-8.4/830511 ltr HUDBFCH, J.B. Alabama Power Co. 83/05/11. 4pp 18809:230. 24X Fiche 50-348,63/05/01.8306090204
- 8306070329 Ack receipt of B30418 ltr informing NRC of steps taken to correct violations noted in IE Bafeguards Insp Repts 50-348/83-07 & 50-364/83-05 LEWIS,R.C. Division of Project & Resident Programs. 83/06/06 MCDONALD.R P. Alabame Power Co. 2pp 18795'070, 24% Fiche. 80-348, 83/06/06, 8306070329
- --8306090332 Responds to NRC 830323 ltr re violations noted in IE Bafeguards Insp Repts 50-348/83-07 & 50-344/83-05 Corrective actions withheld.

 CLAYTON,F L. Alabama Power Co. 83/04/18 LEMIS.R.C. Region 2, Office of Director ip 18795-072, 24X Ficher 50-348,83/04/06,8306090329.
- 830.616.0027 Releases public version of revised emergency plan implementing procedure.

 FELTON, J.M. Division of Rules and Records. 83/06/06 Document Management Branch. ip. 18872-295 24X Fiche.50-348.83/06/06.8306160027
- --8306160032 Public version of Rev 11 to Emergency Plan Implementing Procedure FNP-0-EIP-4, "Chemistry & Health Physics Support to Emergency Plan." W/830524 ltr.
 HUDSPETH, J. B. Alabama Power Cg. 83/05/19, 18pp 18872; 276 24x
 Fiche 50-348, 83/06/06, 8306160027
- 8306210363 Releases public version of revised emergency plan implementing procedure FELTON, J. M. Division of Rules and Records. 83/06/06. Document Management Branch ip 18937: 097. 24% Fiche 50-348,83/06/06, 8306210363
- --B306210365 Public version of Rev 12 to Emergency Plan Implementing Procedura FNP-D-EIP-9. "Radiation Exposure Estimation & Classification of Emergencies." Receipt form encl W/B30421 ltr.
 HUDBPETH,J B. Alabama Power Co. B3/04/14. Office of Nuclear Reactor Regulation, Director 138pp. 18937-098. 24X Fiche 50-340,83/06/8306210363.
- 8306290198 Ack receipt of 830608 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-348/83-09 & 50-344/83-07 LEHIS.R.C. Division of Project & Resident Programs. 83/06/16 MCDDNALD.R.P. Alabama Power Co. 2pp. 19056,095, 24X Fichs.50-348,83/06/16,8306290198

- --8306290222 IE Insp Repts 50-348/83-09 & 50-364/83-07 on 830306-0410 Moncompliance noted: failure to follow calibr & recycle procedures & Tech Baec requirements for fire doors & Procedure FNP-1-37P-256 15. Rev 3. inadequate BRADFORD, W H . RULAND, W H . Region 2. Office of Director CANTRELL,F S. Division of Project & Resident Programs 83/05/06 10pp 19056 104. 24% Fiche 50-348.83/06/16.8306290198
- P. Operating license stage documents & correspondence
- 8306010331 Submits list of post-trip review procedures to be modified following review of results of NURED-0977 (Salem event) & discussion w/NRC Mods will be made within 30 days CLAYTON,F.L. Alabama Power Co. 63/05/24. VAROA,8 A Office of Nuclear Reactor Regulation, Director 1p 18681 278 24% Fiche SO-348,83/05/24,8306010331.
- B306020036 Ack receipt of B30510 ltr informing NRC of commitment for resolution of reactor protection sys BS-816 breaker problem Program being reviewed Responsibility for review of conclusions transferred to Region II VARCA.B A Operating Reactors Branch 1 B3/05/25. CLAYTON.F L Alabama Power Co 2pp 18702-324. 24X Fiche 50-348,83/05/25,8306020036.
- 830.6030307 Suppl to S21116 application to amend OL adding snubbers attached to nonsafety-related giping assumed to be operable for safety-related selsmic attress analysis to Tech Spec snubber tables.

 CLAYTON-F.L. Alabama Power Co. S3/05/27 Office of Nuclear Regulation. Director 2pp 18708 280 24% Fiche 50-348,83/05/27,8306030307.
- --B306030311 Proposed Tech Spec changes adding snubbers attached to nonsefety-related piping assumed to be operable for sefety-related seismic stress analysis to snubber tables.
 Alabama Fouer Co. 83/05/27. 40pp. 18708-282 24X Fiche 50-349-83/05/27.8306030307
- 8306060201 Bubmits status & schedule re design changes, test procedures & confirmatory life program for DS-416 reactor trip breakers, per 830510 ltr & 830531 commitment. He int program will be modified upon completion of 6-month test program CLAYTON-F.L. Alabama Power Co 83/05/31. VAROA-S A Office of Nuclear Resultation, Director. 4pp 18727-324 24% Fiche: 50-348,83/05/31.8306060201
- 8306140610 Requests that util previous date of 830901 for approval of proposed amend to Tech Epec 3/4.1.3 re movable control assembles be advanced to 830715 due to increase in control rod sys events.

 CLAYTON.F.L. Alabama Power Co. 83/06/03 VARQA.8 A Office of Nuclear Reactor Regulation, Director. 2pp. 18842:077 24X Fiche 50-348,83/06/03.8306140610.
- 8306130427 Application for amend to Licenses NPF-2 & NPF-8, changing Tech Byecs re operating personnel, per NUREG-0737, Item I A. 1.3 & Opneric Ltrs 82-02 & 82-12, to incorporate current practices.

 CLAYTON, F L. Alabama Power Co. 83/04/06 VAROA, S A. Office of Nuclear Reactor Regulation, Director. 3pp. 18821 223 24x Fiche: 50-348, 83/04/04, 8306130429
- 9305140893 Commits to add1 action items associated w/Westinghouse reactor trip breakers. Model DS-416. based on B30502 telcon. Only replacement undervoltage trip attachments w/record of 25 cycles will be used. CLAYTON, F.L. Alabama Power Co. B3/06/06 VAR9A, S.A. Office of Nuclear Reactor Regulation. Director. Jpp. 18844:153 24% Fiche: 50-348.83/06/06.8306140593.
- 8306160278 Forwards status of all licensing items identified in util 830143 ltr. CLAYTON.F.L Alabama Power Co. 83/06/10 VARGA, S.A Office of Nuclear Reactor Regulation, Director 7pp 19860 177. 24X Fiche: 50-348,83/06/10,8306160278.
- 8306210193 Application for smend to License NPF-2 requesting one-time Change to Tech Spec permitting extension of subsequent visual inter of inaccessible hydraullic snubbers to fifth outage or next plant sutdown of sufficient duration. CLAYTON.F.L. Alabama Power Co. 83/06/17 VAROA.B.A. Office of Nuclear Reactor Regulation. Director. 2pp. 18914:152 24X Fiche: 50-348, 83/06/17, 8306210193.

- --8306210201 Proposed Tech Spec ra one-time change to inactessible hydraulic snubber visual insp # Alabama Power Co 83/06/17 1p 18914 154 24X Fiche 50-348.83/06/17,8306210193
- 8306230378 Application to amend Licenses NPF-2 & NPF-8, deleting Yeck Spec requirement for river water sys surveillance & svc water bldg battery sys discharge test during shutdown CLAYTON:F L Alabama Power Co 83/06/20 VARQA:B A Office of Nuclear Reactor Regulation. Director Spp 18943 247 24% Fiche 50-348.83/06/20.8306230378
- --8306230382 Proposed Tech Spec changes, deleting requirement for river water sys surveillance & svc water bldg battery sys discharge test during shutdown * Alabams Pauer Co. 83/06/20. 9pp 18743 249 24X Fiche 50-348,83/06/20. 8306230378
- 8306240040 Requests specific license amenda discussed during May 1963 telcons w/NRC be given priority to meet review schedules Evaluation will avoid need to resubmit changes as emergency Tech Spec changes
 CLAYTON.F L Alabama Power Co 83/06/20 VARQA.S A Office of Nuclear Reactor Regulation. Director App 16981 089 24X Fiche 50-348.83/06/20.8306240040
- G Inspection reports, IE Bulletins & correspondence
- 8306070319 Forwards IE Befeguards Insp Repts 50-348/83-07 & 50-344/83-05 on 830287-0303 & notice of violation Rept details & notice of violation withheld (ref 10CFR73 21) LENIS.R C Division of Project & Resident Programs 83/03/23 MCDDNALD.R P Alabama Power Co 2pp 18795 112 24% Fichs 50-348.83/03/23.8306090319
- --8305070324 IE Bafeguards Insp Repts 50-348/83-07 & 50-344/83-05 on 830227-0303 Noncompliance noted failure of vital area alarms in access mode to indicate tamper Details withheld (ref 10GrR73 21)
 HOORE, D E Region 2, Office of Director McGUIRE, D R Division of Emergency Preparedness & Materials Safety 83/03/23 ip 18795 114 24X Fiche 50-348,83/03/23,8306070319
- 8306140473 Forwards IE Insp Repts 50-348/89-12 & 50-364/83-10 on 830421-22 No noncompliance noted VERRELLI,D M Division of Project & Resident Programs 83/05/14 MCDONALD,R P Alabama Power Co 2pp 18834 326 24X Fiche 50-348
- --8306140477 IE Insp Repts 50-348/03-12 & 50-364/03-10 on 630421-22 No noncompliance noted Major areas inspected licensee program for keeping rediation exposures ALARA DEBS.B T. HOSEY.C M Region 2. Office of Director BARR.K P. Division of Engineering & Radiological Safety Programs 63/05/12 7pp 18634 328 24X Fichs 50-348,83/05/16,8306140473
- 8305110488 IE Info Notice 83-32, "Ruptured Am-241 Bources Contained in Well Logging Device" Svc list encl
 TAYLOR, J. M Division of Safeguards & Inspection Programs (Post
 830103) 83/05/26 Consolidated Edison Co of New York, Inc
 125pp 18831 043 24X Fiche 50-000,83/05/26,8305110458.
- 8305110460 IE Info Notice 83-34, "Event Notification Info Worksheet"
 Svc list encl
 JORDAN, E.L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/05/26 Consolidated Edison Co of New
 York, Inc. 115pp 18732.085 24X Fiche 50-000,83/05/26.8305110460
- 8304010332 Forwards IE Bafaguards Insp Repts 50~348/83~14 & 50~344/83~12 on 830509~13 No noncompliance noted VERRELLI.D. Division of Project & Resident Programs 83/05/26 MCDONALD.R P Alabame Power Co 2pp 18682.150 24X Fiche 50~348,83/05/26,8306010332
- --B306010333 IE Safeguards Insp Repts 50-348/83-14 & 50-364/83-12 on 830509-13 No noncompliance noted Major areas inspected site orientation, security organization-mgt, personnel & response Details withheld (ref 10CFR/3 21)
 HALL, B L. Region 2, Deflice of Director. MCGUIRE, D R. Division of Emergency Preparedness & Materials Safety 83/05/24 ip, 18682 152 24X Fiche 50-348,83/05/26,8306010332
- 8304140645 Forwards IE Insp Repts 80-348/83-11 & 50-364/83-09 on 830418-22. No noncompliance noted VERRELLI.D M Division of Project & Resident Programs 83/05/26. MCDONALD.R P Alabams Power Co 2pp. 18841-242 24X Fiche.50-348, 63/05/26. 8304140445

- --8306140655 IE Insp Repts 50-348/83-11 & 50-364/83-09 on 830418-22 No noncompliance noted Major areas inspected emergency preparedness MARSTON R R Region 2. Office of Director JENKINS G R Division of Emergency Preparedness & Materials Safety 83/05/24 App 18841 244 24X Fiche 50-348,83/05/26.8306140645
- 8305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods Withdrawn at BWRs" Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/31 Consolidated Edison Co of New York, Inc 116pp 18732 208 24X Fiche 50-000,83/05/31.8305110461
- 8304140071 Responds to IE Dulletin 82-02, "Degradation of Threaded Fasteners in RCPB of PWR Plants " Maint & QA measures implemented Listed closure connection threaded fasteners opened for component insp/maint CLAYTON.FL Alabama Power Co 83/05/31 O'REILLY.J P Region 2, Office of Director 3pp 1888 261 24X Fiche 50-348.83/05/31. 8306140071
- 8306090329 Ack receipt of 830418 ltr informing NRC of steps taken to correct violations noted in IE Bafeguards Insp Repts 50-384/83-07 & 50-364/83-05 teMIStR C Division of Project & Resident Programs 83/06/06 MCDONALD, R P Alabama Power Co 2pp 18795 070 24X Ficks 50-348,83/06/06.8306090329
- --8306090332 Responds to NRC 630323 ltr re violations noted in IE Sefeguards Insp Repts 50-348/83-07 & 50-364/83-05 Corrective actions withheld CLAYTON, F. L. Alabama Power Co. 63/04/18 LEWIB, R.C. Region 2: Office of Director ip 18795 072 24X Fiche 50-348.63/06/06, 830609393
- 8305i10464 IE Info Notice 83-36, "Impact of Security Practices on Sefe Operations" Svc list encl JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/09 Consolidated Edison Co. of New York, Inc. 119pp 18830 280 24X Fiche 50-000.83/06/09.8303110464
- 8306170357 Bubmits evaluation of plant design & initial description of planned actions in response to IE Bulletin 83-03 re diesel generator syc water sys Check valve design & matls superior Final evaluation forthcoming CLAYTON.F L. Alabama Power Co 83/06/10 O'REILLY, J.P. Region 2, Office of Director 3pp 18080 178 24X Fiche 90-348,83/06/10, 8304170357
- 8305110470 IE Info Notice 83-38. "Defective Heat Bink Adhesive & Beismically Induced Chatter in Relays Within Printed Circuit Cards " Svc list encl JURDAN.E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co of New York, Inc. 118pp 18920-225 24X Fiche 80-000,83/06/13,8305110470
- 8304090010 IE Info Notice 83-37. "Transformer Failure Resulting From Degraded Internal Connection Cables " Svc list encl JDRDAN E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co. of New York. Inc. 243pp 18921.001 24X Fichs 50-000.83/06/13.8306090010
- 8306290198 Ack receipt of 830608 ltr informing NRC of steps token to correct violations noted in 1E Insp Repts 50-348/83-09 & 50-344/83-07. LEMIS.R C. Division of Project & Resident Programs 83/06/16 MCDDNALD.R P. Alabama Power Co 2pp 19056:095 24X Fiche:50-348,83/06/16:8304290198
- --8306270207 Responds to NRC 830510 ltr re violations noted in IE Insp Repts 50-348/83-09 & 50-364/83-07 Corrective actions personnel instructed to close fire doors unless fire watch satablished & preventive maint program updated. CLAYTON,F L. Alabama Power Co 83/06/08 LEMIS,R C Region 2. Office of Director 4pp 19056 097. 24X Fiche 50-348,83/06/16, 8306270198.
- --8306290219 Forwards IE Insp Repts 30-348/83-09 & 50-344/83-07 on 830306-0410 & notice of violation. LEWIB.R C Division of Project & Resident Programs 83/05/10 MCDONALD,R P. Alabama Power Co 2pp 17056-101 24X Fiche 50-348,83/06/14,8306290198
- --8306270216 Notice of violation from insp on 830306-0410 * Region 2. Office of Director 83/05/10 ip 19056 103. 24% Fiche 30-348.83/06/16.8306270178

- --8306270222 IE Insp Repts 50-348/83-07 & 50-364/83-07 on 830306-0410 Noncompliance noted failure to follow calibr & recycle procedures & Tech Spec requirements for fire doors k Procedure FNP-1-57P-256 15, Rev 3, inadequate BRADFORD, H H . RULAND, H H . Region 2, Office of Director CANTRELL, F B Division of Project & Resident Programs 83/05/06 10pp 19056 104 24% Fiche 50-348,83/06/16,8306290198
- 830.6210193 Application for amend to License NPF-2 requesting one-time change to Tech Spec permitting extension of subsequent visual insp of inaccessible hydraulic snubbers to fifth outage or nest plant subdown of sufficient duration CLAYTON.F L Alabama Power Co 83/06/17 VARQA.S.A Office of Nuclear Reactor Regulation, Director Rpp 18914 152 24X Fiche 50-348.83/06/17.8306210193
- --8306210201 Proposed Tech Spac re one-time change to inaccessible hydraulic snubber visual inap * Alabama Power Co 83/06/17 ip 18914 154. 24X Fiche 50-348,83/06/17,8306210193
- 8305110475 IE Info Notice 83-40. "Need to Environmentally Qualify
 Epoxy Grouts & Sealers " Svc list encl
 JORDAN.E L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/06/22 Consolidated Edison Co. of New
 York. Inc. 115pp 19021 179 24X Fiche 50-000.83/06/22.8305110475
- 8305110477 IE Info Notice 83-41, "Actuation of Fire Suppression Sys Causing Inoperability of Bafety-Related Equipment " Syc list encl. JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/22 Consolidated Edison Co. of New York, Inc. 120pp 18997 007, 24X Fiche 50-000, 83/06/22, 8305110477.
- 9305110479 IE Info Notice 83-42. "Reactor Mode Switch Malfunctions." Bvc list encl JORDAN,C L. Divísion of Emergency Preparedness & Engineering Response (Post 930103) 83/06/23 Consolidated Edison Co of New York, Inc. 116pp 18796 242 24X Fichs 50-000,83/06/23.8305110479
- G3D5[10463 IE Info Notice 83-43, "Improper Bettings of Intermediate Range (IR) High Flux Trip Betpoints " Svc list encl JORDAN, EL Division of Emergency Preparedness & Engineering Response (Post 630103) 63/06/24 Consolidated Edison Co of New York, Inc 116pp 17046 277 24X Fiche 50-000, 63/06/24, 8305110483.
- R. Pariodic operating reports & related correspondence
- B306160327 Monthly operating rept for May 1983 W/B30610 ltm HARRSTON.W.O. c.CLAYTON.F.L. Alabama Power Co. B3706/02 9pp 18860 233 24% Fiche 50-348,03706/02,8306160327
- S Reportable occurrences. LERs & related correspondence
- 8306100270 LER 83-021/03L-0 on 830506 power supply breaker HBL7R opened Possibly caused by personnel inadvertently tripping breaker by closing locker Locker moved W/830606 ltr CLAYTON, F. L. HAIRBTON, W. G. Alabama Power Co. 83/06/06. Region 2, Office of Director 3pp. 18807, 001 24X Fiche 50-348, 83/06/06, 8306100270
- 830 6200 336 LER 83-022/09L-0 on 830 511, during monthly operability check, charging pump IC declared inoperable when breaker 8006 would not close Caused by broken follower-roller in breaker apring charging mechanism. Broken part replaced H/830608 ltr.
 HAIRBTON, H Q , CLAYTON, F. L. Alabama Power Co. 83/06/08 Region 2, Office of Director 2pp 18900 196 24X Fichs 50-348,83/06/08,8306200336
- 830.6200216 Forwards LERs 83-023/03L-0.83-023/03L-0 & 83-024/03L-0. CLAYTON,F L. Alabama Power Co 83/06/10 Region 2. Office of Director 1p 18902.279 24% Fichs 50-348.83/06/10.8306200216.
- --8306200220 LER 83-023/03L-0 on 830511,RCS controlled leatage determined to be 32 ppm.contrary to Tech Spec limit of 31 ppm Caused by increase in seal injection flow as result of manual throttle valve vibrating open slightly. Valves adjusted, HAIRSTON, W G Alabama Power Co B3/06/10, Region 2, Office of Director. 1p 18702,280, 24x Fichs 50-348,83/06/10,8306200216,
- --8306200227 LER 83-023/03L-0, on 830511, train B reactor trip breaker would not reclose Caused by design inadequecy Voltage available to undervoltage device coil marginally sufficient to allow undervoltage device to remain latched.

 HAIRSTON. H. 9. Alabams Power Co. 83/06/10 Region 2, Office of Director. 4pp 18702, 281 24X Fiche 50-348,83/06/10,8306200216.

- --8305200233 LER 83-024/03L-0 on 830512, rod control sys declared inoperable upon receipt of failure elerm on power cabinet 2AC Caused by failure of regulator circuitry card Card replaced HAIRBTON, H Q. Alabama Power Co 83/06/10 Region 2, Office of Director ip 16902 285 24X Fiche, 50-348, 83/06/10, 8305200216
- 8306270229 Forwreds LERS 83-085/03L-0 & 83-026/03L-0 CLAYTON: F. L. Alabama Power Co. 83/06/16 Region 2, Office of Director 1p 18993 320 24X Ficha 50-349,83/06/16,8306270229.
- --8306270R32 LEA 83-0R5/03L-0 on 830602, chlorine detector sys train A declared inoperable due to inoperable sensor Caused by broken wire in detector fiber optics Wire repaired Chlorine detector declared operable following FNP-0-8TP-318 I HAIRBYON: W O Alabama Power Co. 83/06/18 Region 2: Office of Director ip 1893 318 24X Fiche 50-348.83/06/16.8306270229
- --8306270369 LER 83-026/03L-0 on 830526, containment particulate activity monitor R-1. declared inoperable caused by vacuum pump failure Monitor declared operable following alignment to elternate pump Inoperable pump replaced.
 HAIRBTON, M. 9. Alabama Pumer Co. 83/06/16. Region 2, Office of Director 1p. 18993, 319 24X Fiche 50-348, 83/06/16, 8306270229
- DOCKET 50-352 LIMERICK GENERATING STATION. UNIT 1

 A Application/construction stage documents & correspondence
- B3Q4030086 Notification of B30525 meeting w/util in Bethesde, HD to resolve issues re accident evaluation identified in NRC B30311 ltr MARTIN R.E. Licensing Branch 2 83/05/20, BCHWENGER, A Licensi Branch 2, 4pp 18733 269 24x Fiche 50-352, 83/05/20, 8306030086
- 8305010292 Forwards draft changes to FBAR, design assessment rept & to previously provided responses in answer to Issues 5b, 5c, 5d, 3e & 20 discussed at 830407 meeting Rept on functionality of purg & vent valves will be submitted in June 1983 BRADLEY, E. J. Philadelphia Electric Co. 83/05/26 SCHMENCER, A Licensing Branch 2 75pp 18678 304 24X Fichs 50-352,83/05/26,8306010292
- 8306020649 Notification of 830608 meeting w/util & BMNL in Bethesda. HD to discuss severe accident risk assessment (BARA).
 MARTIN R. E. Licensing Branch 2 83/08/27 8CHMENCER. A Licensing Branch 2. 4pp 18716:271 24X Fiche 50-352. 83/08/27. 8306020649
- 830&010233 Forwards application for Amend 51 to DL application (filed in Category A) consisting of environ qualification rept, Rev 20 to FBAR (filed in Category K) & Rev 13 to environ rept (filed in Category C).

 BRADLEY, E. J. Philadelphia Electric Co. 83/05/31. DENTON, H R Office of Nuclear Reactor Regulation, Director Spp. 18675, 001, 24X Fiche: 50-352, 83/05/31, 8306010233.
- --8306010239 Application for Amend 51 to OL application.consisting of Rev 20 to FSAR.environ qualification rept k Rev 13 to environ rept BAUER.E. 9 Philadelphia Electric Co. 83/05/24 App. 18675-004, 24X Fichs 50-352,63/05/31,8306010233
- 8306090174 Notification of 830608 meeting w/util & Bechtel in San Francisco.CA to discuss outstanding items in structural engineering review area. MARTIM.R.E. Licensing Branch 2 83/06/02 SCHMENCER.A Licensing Branch 2 3pp. 18807.252 24X Fiche-50-352.83/06/02.8306090196.
- 8306070239 Forwards revised draft response to Question 410 17 re CP application compliance w/NUREO-0800 per 830330 meeting w/NRC. Changes will be incorporated in FSAR rev scheduled for June 1983.

 BRADLEY.E.U. Philadelphia Electric Co 83/06/03. SCHMENCER.A. Licensing Branch 2 3pp. 18747-048. 24X Fiche: 50-352.83/06/03, 8306070239.
- B306100109 Forwards revised draft response to Question 430.48 re level of training for operators, maint crew & QA personnel, Response will be incorporated into FBAR rev scheduled for Jul 1983 BRADLEY, E. J. Philadelphia Electric Co. 83/06/06 BCHMENCER, A Licensing Branch 2. 6pp. 18802; 205. 24X Ficher 50-352, 83/06/06, 8306100109.
- 3006100065 Forwards draft FBAR change re breed line depressurization branch per Accident Evaluation Branch request Change will be incorporated into Jul 1983 FBAR rev. BRADLEY, E. J. Philadelphia Electric Co. 83/06/07 BCHWENCER, A. Licensing Branch 2. Spg. 18803:067 24% Fiche 50-352,83/06/07,8306100065,

- 8305100241 Forwards revised draft response to FSAR mgt technology section re licensed operator courses & operating activities transmitted in 830505 treper 830527 request Changes will be incorporated into FSAR rev scheduled for Jul 1983 BRADLEY,E J Philadelphia Electric Co 83/05/07 9CHWENCER,A Licensing Branch 2 App 18807 053 24X Fiche 50-352,83/05/07,8306100241
- 8304150321 Forwards request for addl info re FSAR Design Criteria Summany, Item 260 56 reflecting requirements of NUREG-0737. "Clarification of TMI Action Plan Regularments " SCHWENCER, A Licensing Branch 2 B3/06/07, BAUER, E 9 Philadelphia Electric Co 7pp. 18870 010 24X Fiche 50-352,83/06/07,8306150321
- 8306160340 Responds to QA Branch 830527 telcon request re proposed organization change in Electric Production Dept reflecting change in QC Program for Operational Phase DALTROFF,8 L Philadelphia Electric Co 83/05/07 SCHWENCER,A Licensing Branch 2. Bpp 18859 082 24X Fiche 50-352.83/05/07.8306160340
- 8306160310 Forwards final response to NUREO-0612, "Control of Heavy Loads at Nuclear Power Plants-Resolution of TAP A-36" Response includes analyses for loads handled over reactor vessel KEMPER, J. 8 Philadelphia Electric Co 83/06/13 EISENHUT, D. 0 Division of Licensing 126pp 18860 243 24X Fiche 50-352, 83/06/13-8308160310
- 9306150377 Forwards rev to Page 1 2 of 830531 environ quelification rept. to be formally incorporated into Oct 1983 rept rev. BRADLEY, E. J. Philadelphia Electric Co 83/06/13 80HHENCER, A Licensing Branch 2, 3pp 18861 123 24X Fiche 50-332,83/06/13,8306160377
- 8305170210 Forwards draft responses to requests for add1 info Questions 252 1 through 252 7 & related draft FBAR text changes Draft changes will be incorporated in FBAR in rev acheduled for Jul 1983 BRADLEY, E. J. Philadelphia Electric Co. 63/05/14 BCHHENCER. A Licensing Branch 2 10000 18883 153 24X Fiche 50-352,83/05/14,8305170210
- 8306170309 Provides marked-up draft FBAR pages per QA Branch 830527 request for add1 info Page changes will be incorporated in FBAR rev echedulad for Jul 1993 BRADLEY,E J Philadelphia Electric Co 93/06/14 8CHHENCER, A Licensing Branch 2 16pp. 18877 113 24X Fiche 50-352,83/06/14.
- 830.6210.418 Notification of 830.615 meeting w/util.Bechtel & QE in Betheeda, MD to discuss high radiation isolation signals on containment purge/vent walves MARTIN.R E Licensing Branch 2 83/06/14 SCHWENCER, A Licensing Branch 2 App 18937, 065 24X Ficher 50-352, 83/06/14, 830.6210.418
- 8306200117 Forwards response to Matts Engineering Branch 830603 request for info re turbine missile issue RADLEY.E J Philadelphia Electric Co. 83/06/15 SCHWENCER.A Licensing Branch 2 See 18903-247 24X Fiche 50-352,83/06/15,8306200117
- 83062102RO Forwards mat1 presented at Anderson, Greenwood & Co (AGCo) vacuum breaker test program owners group 830607 meeting w/ NRC re dynamic testing & analysis of AGCo vacuum breaker valve assemblies.

 O'CONNOR, D. M. Bechtel Corp. 83/06/17, HOUSTON, R. W. Division of Systems Integration (post 811005), 91pp. 18919 038 24X
 Fiche 50-000, 63/06/17, 83062102RO
- 8306240412 Natification of 830621-24 meetings w/util.Bechtel & QE in Ban Jose & Ban Francisco.CA to discuss outstanding items in Matls Engineering Branch review of compliance w/ODC 51 MARTIN.R E Licensing Branch 2 83/06/17 894MENGER.A Licensing Branch 2 83/06/17 8958240412 Branch 2 App 18998 013, 24X Fiche 50-352.83/06/17.8306240412
- 830.6230276 Responds to NRC 830523 request for proposed resolution to TMI Item II K.3 18, "Mod of Automatic Depressurization Sys Logic " Justification for bysess timer setting will be provided prior to implementation of mod KEMPER.J S. Philadelphia Electric Co 83/06/20 SCHWENCER.A. Licensing Branch 2. 3pp 18745,135. 24X Fiche 50-352,83/06/20,8306230276
- 8304240138 Notification of 830423 meeting w/util & Bechtel in Bethesda. MB to discuss Auxiliary Sys Branch open issues ABELSON, H Licensing Branch 2. 83/04/20. SchuRKCER, A Licensing Branch 2 4pp 18987-213. 24X Fiche 50-352,83/04/20,8304240138

- 8306290595 Summarizes NRC Caseload Forecast Panel 830413-15 meetings w/util re-assessment of schedule for completing const & other activities necessary to support issuance of OL OL expected by Second Quarter 1985 NOVAK, T. M. Assistant Director for Licensing 83/06/20 BAUER, E @ Philadelphia Electric Co. 3pp. 19047 098 24X Fiche 50-352,83/06/20,8306290595
- 8306240367 Bummary of Caseload Forecast Panel 830413 meetings w/util, Bachtel & Conner & Wetterhahn in Valley Forge, PA re review of const progress & to collect data for estimating NRC resource needs for licensing activities Agenda encl HAVOHEY, M.F. Licensing Branch 2 83/06/21 Licensing Branch 2 16pp 18999 139 24X Fiche 50-352,83/06/21,8306240367
- 8306270212 Forwards revs to FBAR Bections 9 5 6 3.7 2.8 3 % 9 5-10 Info will be incorporated into rev to FBAR scheduled for Jul 1983 BRADLEY.E J Philadelphia Electric Co B3/06/21 SCHWENCER.A Licensing Branch 2 10pp 18990 252 24X Fiche 50-352.83/06/21, 8306270212
- B306270365 Forwards revised draft response to FBAR Question 410 70 re design temp for essential svc water & RHR svc water sys Draft change will be incorporated into FBAR rev scheduled for Jul 1983
 BRADLEY, E J Philadelphia Electric Co B3/06/21, BCHWENCER, A Licensing Branch 2 6pp. 18793 193 24X Fiche 50-352, B3/06/21, B306270365
- 8306270423 Forwards draft FBAR changes prepared in response to Containment Sys Branch Open Item 18 Changes state isolation valves will be sealed closed Info will be incorporated into FBAR rev scheduled for Jul 1983
 BRADLEY, E J Philadelphia Electric Co 83/06/23, 9CHWENCER, A Licensing Branch 2 7pp 18992 126 24X Fiche 50-352, 83/06/23, 8306270423
- 9306270459 Forwards draft revised responses to NRC Questions 410 05, 410 10, 410 37, 410 52, 410, 85 & 410, 89, per telcon w/Auxiliany Gys Branch Responses will be incorporated in FBAR scheduled for Jul 1983
 BRADLEY, E.J. Philadelphia Electric Co. 83/04/23 BCHWENCER, A Licensing Branch 2 20pp 18992, 075, 24X Fiche 50-352, 83/04/23, 8306270459
- 8304280589 Informs that Aug 1984 const completion date scheduled in last quarterly rept consistent w/ongoing const efforts, per NRC B10811 ltr BRADLEY, E. J. Philadelphia Electric Co. 83/06/23 E18ENHUT, D. Q Division of Licensing 2pp 19018 240 24X Fiche 50-332,83/06/23, 8306280589
- 8306300024 Responds to 830607 request for add1 info, forwarding documents used by Btructural Mechanics Assoc in seismic fragfility development RRADLEY,E J. Philadelphia Electric Co. 83/06/27, SCHWENCER,A Division of Licensing. 200pp 19114 250, 24X Fichs 50-352, 83/06/27, 830630024
- B306300221 Forwards draft FBAR changes re loose parts monitoring sysfor rev scheduled for Jul 1993. Detailed sys-description per Reg Quide i 133 submitted, pending receipt of BER, BRADLEY,E J Philadelphia Electric Co 83/06/27 BCHMEMCER,A. Licensing Branch 2 7pp 19120,001, 24X Fiche 50-352,83/06/27, 8306300221
- 8306300133 Forwards draft revised response to TMI Item I.Q i, "Training Buring Low-Power Testing," per 830627 conference call. Info contained in draft revised response will be incorporated into FBAR rev scheduled for Aug 1983.

 BRADLEY, E. J. Philadelphia Electric Co. 83/06/28 SCHWENCER, A. Licensing Branch 2 5pp. 19122.311 24X Fiche: 50-352,83/06/28,8306300133.
- C Utility Environmental Report (ER), amends & correspondence
- 8304010233 Forwards Rev i3 to environ rept BRADLEY,E J. Philadelphia Electric Co. 83/05/31. DENTON,H R. Office of Nuclear Reactor Regulation, Director 3pp 18675:001 24% Fiche: 50-382,83/05/31,8306010233.
- --8305010243 Rev 13 to environ rept.Environ qualification rept for safety-related equipment enc1
 + Philadelphia Electric Co 83/05/31, 837pp, 18675:010 24X
 Fiche: 50-352, 83/05/31, 8306010233.
- 8304210283 Forwards Affidavit of Svc re distribution of Rev 20 to FSAR, Rev 13 to environ rept & Rev 3 to fire protection evaluation rept.

 BRADLEY, E. J. Philadelphia Electric Co. 83/04/17 DENTON, H. R. Office of Nuclear Reactor Regulation, Director, 5pp. 18915; 022. 24X Fiche: 50-352, 83/04/17, 8304210283.

- E NRC Bafety Evaluation Report (SER), supple & correspondence
- 8304070330 Forwards responses to listed Procedures & Test Review Branch SER open items Draft response to TMI Item I C 1, "Openating & Maint Procedures & ATMB," incorporated in May FSAR rev BRADLEY, E J Philadelphia Electric Co 83/06/03 BCHMENCER, A Licensing Branch 2 4pp 18746 065 24X Fichs 50-352,83/06/03,8306070330
- 8306150579 Forwards request for addl info re SER open items Action plan & associated dates for response required within 7 working days of receipt of ltr SCHWENCER, A. Licensing Branch 2 83/06/03 BAUER, E Q Philadelphia Electric Co 24pp 18867 038 24X Fiche 50-382,83/06/03,8306150579
- 8306100110 Forwards final response to Reactor Sys Branch draft SER Item 3 re high/low pressure interlocks on ECCS injection valves, per discussion at 830517 meeting in Bethesda, MD BRADLEY, E J Philadelphia Electric Co B3/06/07 SCHWENCER, A. Licensing Branch 2. 4pp 18802 201. 24X Fiche 50-352,83/06/07,8306100110
- 8306140545 Responds to Geotechnical Engineering Branch draft SER open items transmitted via 830311 ltr. Properties of foundation bedrock.backfill, lateral loading & response of in-situ soil & backfill matis to dynamic loading discussed BRADLEY,E. J Philadelphia Electric Co 83/06/09. 8CHMENCER.A. Licensing Branch 2 25pp 18834 179 24X Fiche: 50-352.83/06/09.8306140545.
- 8306140606 Forwards response to Structural Engineering Branch draft BER Open Items 1, 4,8 & 9, All open items closed out, Items 1, 4 & 8 represent formal response while Item 9 indicates FBAR page changes.

 BAUER, E. 9 Philadelphia Electric Co. 83/06/10 BCHMENCER, A. Licensing Branch 2 38pp 18833 061 24X Fiche 50-352,83/06/10,8306140606
- 8306140624 Forwards draft responses to BER Open Items 2.7, 9, 11, 12, 16, 18, 19, 21, 27 & 34 re fire protection Fire protection evaluation rapt will be submitted in Aug 1983 BRADLEY, E. J. Philadelphia Electric Co. 83/06/10. SCHMENCER, A. Licensing Branch 2 33pp 18833:326 24X Fichs 50-352,83/06/10,8306140624
- 8306160001 Forwards draft FSAR page changes, in response to Reactor Sys Branch draft BER Itam 1, "UDYN Analysis of Pressurization Transients "Changes will be incorporated into FSAR rev scheduled for Jul 1983 BRADLEY, E. J. Philadelphia Electric Co. 83/06/13, BCHWENCER, A Licensing Branch 2 58pp 18862.025, 24X Fiche 50-352.83/06/13, 8306160001,
- 8306160371 Forwards draft responses & draft FBAR page changes in response to Meteorology & Effluent Treatment Branch draft SER Items 2.4.5 & Request for Addl Info RAI 451.14, BRADLEY.E.J. Philadelphia Electric Co 83/06/13, BCHMENCER.A Licensing Branch 2, 43pp. 18864:164 24X Fiche.50-352.83/06/13, B306160371
- 8306160527 Forwards response to Core Performance Branch draft BER. Draft page changes will be included in FBAR rev scheduled for Jul 1983 BRADLEY, E. J. Philadelphia Electric Co. B3/06/13, BCHMENCER, A. Licensing Branch 2. 71pp. 18863-140 24X Fiche: 50-352, 83/06/13, B306160527
- 8306160572 Forwards draft BER. Section II, "Test Review," Item 2, consisting of FBAR changes to be incorporated into FBAR review scheduled for Jul 1983

 BRADLEY,E. J. Philadalphia Electric Co. 83/06/13, 80HMENCER, A. Licensing Branch 2, 73pp. 18866:211, 24X Ficher 50-332, 83/06/13, 8306160572
- 8306170369 Forwards response to Accident Evaluation Branch draft SER, per 830528 meeting request Draft page changes will be included in FSAR rev scheduled for Jul 1983, BRADLEY.E. J. Philadelphia Electric Co 83/06/14, 8CHMENCER.A. Licensing Branch 2, 17pp 18880:193 24X Fiche 50-352,83/06/14,8306170369
- 8304200317 Forwards draft responses to NRC draft BER Guestions 250.1, 250 2,250,3,250,4 & 250.5 re preservice insp of reactor pressure vessels, pumps & valves, Responses will be incorporated in Jul 1983 FBAR rev.
 BRADLEY,E J. Philadelphia Electric Co. B3/06/14, BCHMENCER, A Licensing Branch 2, 31pp. 18899;212, 24X Fiche 50-352,83/06/14, B306200317.

- 8306240418 Notification of 830624 meeting w/util & OE in Bethesda, MD to discuse Effluent Treatment Sys Branch open SER items MARTIN:R E Licensing Branch 2 83/06/20 SCHMENCER.A Licensing Branch 2, 4pp 18798 009 24% Fiche 50-352,83/06/20,8306240418
- 8306270086 Forwards revised draft response to Question 480 7.including revised Section 6 2 6 5 1 % Table 14 2-4 in response to Containment Sys Branch draft SER Issue 1 & revised draft Section 6 2 3 2 % Table 6 2-15 BRADLEY, E J. Philadelphia Electric Go 93/06/21 BCHMENCER, A Licensing Branch 2 23pp. 19013:125 24X Fiche 50-352,83/06/21,830627086
- 8306270315 Provides response to structural angineering review draft SER open items discussed & resolved at 830603 meeting reresponse spectra reactor encl & control structure.

 KEMPERJ J B Philadelphia Electric Co. 83/06/21 SCHENCER.A Licensing Branch 2 19pp. 18994 010. 24X Fiche 80-352,83/06/21,8306270315
- 8306270340 Forwards revised Table 6 2-17. adding power sources in containment paretration, in response to Containment Sys Branch draft SER Issue 15 Info will be incorporated into FSAR schaduled for Jul 1983

 BRADLEY, E. J. Philadeighia Electric Co 83/06/23, SCHWENCER, A. Licensing Branch 2, Spp. 18991 210 24X Fichs, 50-352, 83/06/23, 8306270340
- 8306280381 Forwards calculate post-LOCA bounding drywell temp profile, per 830510 Rev 20 changes to FBAR Section 3.11, in response to Containment Bys Branch draft SER, Item 4
 KEMPER, J S Philadelphia Electric Co 83/06/24 SCHWENCER, A.
 Licensing Branch 2. 4pp 19014.063 24X Fiche. 50-352.83/06/24, 8306280381.
- B306300016 Forwards draft rev to response to Question 640.10 re low power & power ascension testing providing info necessary to close Item 5 of draft BER, Section II. "Test Review " Info will be included in FBAR rev scheduled for Jul 1982 BRADLEY.E. J Philadelphia Electric Co 83/05/27 SCHMENCER, A Licensing Branch 2 3pp. 19120-252 24X Fiche 50-352.83/06/27, 8306300016,
- 8306300200 Forwards list of Auxiliary Sys Branch open SER issues per 830620 meeting & merked-up draft FSAR pages responding to issues, SANDLEY, E. J. Philadelphia Electric Co. 83/06/28 SCHWENCER, A. Licensing Branch 2 Sipp. 19122: 126 24% Fiche 50-352, 83/06/28, 836300200

F Security, medical, emergency & fire protection plans

- 8306140396 Forwards draft change to FSAR re emergency ac lighting, per SIGNATURE PROMETER STATE CHANGE to FBAR TO SMETCHING, P. 830A07 telcon conmittenent Change will be formally incorporated into FBAR rev. acheduled for Jul 1983. BRANLEY, E. J. Philadelphia Electric Co. 83/06/10, BCHMENCER, A. Licansing Branch 2. 4pp. 18832.089 24X Fiche: 50-352,83/06/10,8306140395
- 8305140524 Forwards draft responses to SER Open Items 2,7,9,11,12,16, 18,19,21,27 % 34 re Fire protection. Fire protection evaluation rept will be submitted in Aug 1983 BRADLEY,E J. Philadelphia Electric Co. 83/06/10. SCHWENCER,A. Licensing Branch 2 93pp. 18833:326. 24% Fiche:50-332,83/06/10,8306140624
- 8305200183 Forwards draft changes to FBAR Bertion 9 5, 3, 2, 2 & Question 430. bl re outdoor security & roadway lighting. Changes will be incorporated into FSAR rev scheduled for Jul 1983 Out 1983. BRADLEY,E J. Philadelphia Electric Co. 83/06/j5 BCHWENCER,A. Licensing Branch 2. Spp. 18903.173. 24X Ficha 50-352.83/06/15. 8306200183
- 8306210283 Forwards Affidavit of Svc re distribution of Rev 20 to FSAR, Rev 13 to soviron rept & Rev 3 to fire protection evaluation rept.

 BRADLEY, E. J. Philadelphia Electric Co. 83/06/17, DENTON, H. R. BRADLEY.E. J. Philadelphia Electric Co. 83/06/17. DENTON.H.R. Office of Nuclear Reactor Regulation. Director. 5pp 18715-022. 24X Fiche: 50-352.83/06/17.8306210283.

O. Adjudicatory correspondence

830-6010464 Discusses IE Insp Rept 50-353/76-06 re inaccessible wolds. Melds capriciously & unilaterally declared acceptable following convenient & unaccentific decision that wolds cannot be inspected due to inaccessibility. ROMAND.F.R. Air and Water Pollution Patrol. 83/05/25. Atomic Bafety and Licensing Board Panel. 2pp 18679:319. 24X Fiche: 80-352,83/05/25,8306/10464

- 8305010372 Forwards motion for reconsideration of ASLB 830509-11 culing re-coordination of contention filing w/Limerick Ecology Action
 AU, T. Y. Pennsylvania. Commonwealth of. 83/05/26 BRENNER, L.,
 MDRRIB. P. A., COLE. R. F. Atomic Safety and Licensing Board Panel 19
 18682 091 24X Fiche 50-352.83/05/26.8306010372
- --B306010380 Motion for reconsideration of ASLB 830509-11 rulings re coordination of contention filling w/Limerick Ecology Action Ruling undermines role of state in presenting issues in neutral manner Certificate of Svc encl AU.T Y Pennsylvania, Commonwealth of 83/05/26 Atomic Safety and Licensing Board Panel [1pp 18682 092 24X Fiche 50-332.63/05/24.8304010372
- 8306010369 Petition to withdraw as intervenor representative in OL proceeding RJ Bugarman will continue to represent intervenor Draft order encl NEILL.J M Del-Aware Unlimited, Inc. 83/05/31 Atomic Rafety and Licensing Board Panel 2pp. 18682-105-24X Ficha 50-352,83/05/31.
- 8304030280 Response supporting NRC reply to ASLB 830514 order re use of PRA & subsequent risk-related documents Certificate of Svc & RK Weatherwax prof qualifications encl DORSEY, J A Limerick Ecology Action. DORSEY, J A Dorsey, J A 83/03/31 Atomic Sefety and Licensing Board Panel 27pp 18705, 187 24% Fiche 50-352, 83/05/31, 8304030280
- 8306020351 Memorandum & order danying Del-Awars 830308 motion to recent record & add proposed new Contention V-26 Contention is not significant & would not affect outcome of decision BRENNER, L Atomic Safety and Licensing Board Panel 83/06/01 Del-Awars Unlimited, Inc. 11pp 18694 247 24X Fichs 50-352.83/06/01.8306020351
- 8306030286 Order granting JM Neill petition to withdraw appearance request BRENNER.L Atomic Safety and Licensing Board Panel 83/06/01 is 18703 331 24X Fiche 50-352:83/06/01:8306030286
- 9304060322 Advises that Bucks County, PA citizens voted for County withdrawal from further participation in Point Pleasant Diversion Project intended to supply supplemental cooling water to plant Referendum does not affect contractor rights CONNER, T B Conner & Wetterhahn. CONNER, T B Philadelphia Electric Co 83/06/02 KONL, C N . EDLES. G J . QUTCHY, R. L. Atomic Selety and Licansing Appeal Panel 13pp 16729 172 24X Fiche 50-352, 83/06/02,8306060322
- 8306060330 Order scheduling resumed appellate process matters Exceptions to ABLB 830601 order denying Del-Awere 830308 motion due 830616 Brisés supporting all exceptions due BHOEMAKER, C. J. Atomic Safety and Licensing Appeal Panel 83/05/02 Pps. 18726-361 24X Fiche: 50-382, 83/06/02, 8306060330
- 8304070295 First set of interrogatories & request for production of accuments WETTERHAHM, M J Philadelphia Electric Co HETTERHAHM, M J Wetterhahn 83/06/03 Air and Water Pollution Patrol 18741 186. 24X Fiche 50-352,83/06/03,8306070295
- --B304070299 First set of interrogatories & request for production of MEDIANTY FIFE SECTION OF THE SECTION 10741 194
- --8304070301 First set of interrogatories & request for production of documents Certificate of Syc ancl.
 WETTERHAHN, M J. Philadelphia Ejectric Co WETTERHAHN, M J. Conner & Wetterhahn B3/04/03 LEWIB,M I Lewis, M 9pp 18741 203 24X Fiche 50-352,83/04/03,8306070295
- 8304090212 Forwards Attachments 2 & 3 to 830520 ltr Attachments may have been miscollated or incomplete WETTERHAHN, M J. Conner & Wetterhahn. WETTERHAHN, M J. Philadelphia Electric Co. 83/06/06. BRENNER, L. MORRIB, P. A. COLE, R F. Atosic Safety and Licensing Board Panel. Jipp 18796 103 24X Fiche 50-352,83/06/06,8306090212
- 8304090240 Motion for extension until 830410 to respond to NRC use of facility PRA Filing allowed per ASLB 830516 order confirming schedules. Ceptificate of Svc encl WETTERHAHN, M. J. Philadelphia Electric Co. WETTERHAHN, M. J. Conner Wetterhahn B3706/06 Atomic Bafety and Licensing Board Panel 4pp 18795 328 24X Fiche 50-352,83/06/06,8304090240. Conner &

- 8306080167 Order granting util 830606 motion for extension until 830610 to file response to NRC & Limerick Ecology Action Filings on PRA contentions Parties consent & good cause shown BRENNER, L. About Safety and Licensing Board Panel 83/06/07 Philadelphia Electric Co ip 18772 154 24X Fiche 50-352, and Color Content of Content o 83704707, B30A0B01A7
- review ALAB-726 CHILK: S.J. Office of the Secretary of the Commission to act Commissioners ip 18795 241 24X Fiche 50-352, 83/06/07, 8306090301 8306090301 Order extending time until 830627 for Commission to act to
- 8306100175 Order requiring NRC to update schedule estimate for issuance of DES All parties under duty to inform ASLS of any change in matl info BRENNER, L. Atomic Safety and Licensing Board Panel 83/06/ Commissionars 2pp 18806 017 24X Fiche 50-352,83/06/09,8306100195
- 8306130366 Advises that if Pennsylvania Emergency Mgt Agency draft smergency plans available by 831115,FEMA would complete review by mid Feb 1984 FEMA will expedite review & should be placed on svc list VOSLER.B H Hearing Branch 2 83/06/07 BRENNER, L MORRIS, P A . CDLE, R F Atomic 88fety and Licensing Board Fanel 2pp 18821 268 24X Fiche 50-352,83/06/07.8306130366
- 8306140676 Responds to request for definition of safety classification terms by transmitting relevant portions of ASLB 830526 Decision ALAB-729 HODODON, A.P. Hearing Oranch 2 83/06/10 LEWIS, M I Lewis, M 6pp 18842 069 24X Fiche 50-352.83/06/10.8306140676
- B306140715 Response to first set of interrogatories on pressurpred thermal shock. Contention 1-62 Centificate of Byc encl HOBOBON. A P Hearing Branch 2 83/06/10 Lewis, M 27pp 18841 276 24X Fichs 50-352, 83/06/10, 8306140715
- 8306140722 Responds to ASLB 830607 order requiring NRC to update schedule for DES issuance Schedule unchanged since dates set at 830509-11 second special preheating conference DES, scrept Chapter 7, to be published on 830613 HODODONA P Hearing Branch 2 83706/10 DRENNOR, L. HORRIS, P. A. COLE, R. F. Atomic Safety and Licensing Board Panel 2pp 18841 094 24X Fiche 50-352, 83706/10, 8306140722
- 8306150362 Discusses Contentions I-33B,D,E,K & I-45 re TM1 Action Plan Items I C 6,I G 1.1 D 1,II F 1.II D 3 & II D 2 Contentions denied w/o prejudice by ABLB 830516 memorandum & order, for tack of specificity DDRSEY,J A Dorsey, J A DDRSEY,J A Limerick Ecology Action 83/06/10 BRENNER,L , MORRIS,P A , COLE,R F, Atomic Safety and Licensing Board Panel 2pp 18847 145 24X Fiche: 50-352,83/06/10.8306150362.
- 8306150393 Response to NRC use of facility PRA & Limerick Ecology Action response to ASLB 830516 memorandum & order confirming schedules. Certificate of 8vc encl WETTERHAHN, M J Philadelphia Electric Co WETTERHAHN, M J Conni Hetterhahn 83/06/10 Atomic Bafety and Licensing Doard Panel 11pp 18847 139 24X Fiche 80-352,83/06/10,8306150393
- 8306160603 Forwards util answer to MI Lawis first set of interrogatories on presurized thermal shock contention METTERMAHN. M J Conner & Hetterhahn METTERMAHN. M J Philadelphia Electric Co 83/06/13 LENIS. M I Lewis, M Ip 18865 144. 24X Fiche 50~352,83/06/13,8306160603
- --8304160609 Answers to first set of interrogatories on pressurized thermal shock contention Certificate of Bvc encl BOYER. V 8 Philadelphia Electric Co 83/06/09 LEWIS. M. I Lewis. M. 16pp 16866-145 24% Fiche 50-392.B3/06/13.6306160603
- 8306220043 Answer to first set of interrogatories re-pressurized thermal shock in BMRs LEWIS.M.I Laws. M 83/06/15 Philadelphia Electric Co 2pp 18926 258 24X Fiche 50-352.83/06/15.8306220043
- 8306220051 Files add1 exceptions to ASLB 830601 order refusing to consider Interstate Delaware River Mgt 830517 recommendations & referendum Certificate of Syc encl SUGARMAN, R. J. Del-Aware Unlimited, Inc. SUGARMAN, R. J. Sugerman, R. J. 83706/16. Atomic Safety and Licensing Appeal Panel Spp 18926 198 24X Fiche 50-352,83/06/16.8306220051.
- 8306220103 Forwards Commonwealth of PA Bupreme Court decision.
 Unanimously reversing Commonwealth Court & holding that PUC
 of PA acted within power & acted property when ordering util
 to cancel or suspend const of Unit 2
 SUGARMAN.R.J Sugarman, R.J 83/06/16 BRENNER.L, COLE.R F,
 MORRES, PA Atomic Safety and Licensing Board Penel, lopp.
 18926.038 24X Fiche 50-352,83/06/16,8306220103

- 830.6270297 Forwards unsite emergency planning contentions, in response to ASLB 830516 memorandum of order DORSEY, J.A. Dorsey, J.A. 89706/17 BRENNER.L., CDLE, R.F., MORRIS, P.A. Atomic Safety and Licensing Board Panel 35pp 18995 170 24X Fiche 50-352,83/06/17.8306270297
- --8305270300 Onsite emergency planning contentions Certificate of Svc
- 830627003B Answer to first set of interrogatories Related correspondence ANTHONY.R C Friends of the Earth ANTHONY.R C Anthony.R L 83/06/20 Philadelphia Electric Co Rpp 18988 135 24X Fiche 50-352.83/06/20.8306270038
- 830.6290364 Discusses Air & Mater Pollution Patrol response to util B30.606 Interrogatories Related correspondence ROMAND, F.R. Air and Mater Pollution Patrol B3/0.6/21 BRENNER.L., COLE.R.F., MORRIB.P.A. Atomic Bafety and Licensing Board Panel ip 19055 226 24X Fiche 50-352.83/0.6/21.830.6290364
- 8306270807 Response to 830606 interrogatories Related correspondence ROMANG F R. Air and Water Pollution Patrol 83/06/21 Atomic Safety and Licensing Board Panel. 5pp 17052 207 24X Fiche 80-352.83/06/21,8306270507
- 8306270413 Advises that util does not object to Limerick Ecology Action position in 830610 ltr on contentions related to NUREO-0737 METTERHANN, M J Conner & Wetterhahn WETTERHANN, M J Philadelphia Electric Co 83/06/23 BRENNER, L , MORRIS, P A , COLE, R F Atomic Safety and Licensing Board Panel 2pp 1874/146 24X Fiche 50-352,83/06/23,8306270413,
- 8306280566 Responds to Del-Aware 830616 ltr ABLB requesting admittance of new contention Del-Aware failed to comply w/procedure re late-filed contentions MODODON, A P. Hearing Branch 2 83/06/27 BRENNER, L., MORRIE, P. A., COLE, R. F. Atomic Safety and Licensing Board Panel 2pp 19017, 330 24X Fiche 30-352, 83/06/27, 8306280566
- 8306300143 Advises that time for Commission to review ALAB-726 expired. Commission declined review Decision became final agency action on 830627 CHILK: 8 J Office of the Secretary of the Commission 83/06/29 Office of the Esecutive Legal Director 1p 19168 117 24X Fiche 50-352,83/06/29,8306300143

H General correspondence

- B3040203B0 Requests further discussion of 10CFR50 54(x) & (y) re single NEUZUGOV REQUESTS fUTTHET discussion of 190FR30 54(x) & (y) re single failure criterion Issue of common mode failure of all solenoids litigable
 LEWIS.M I Lewis. M 89/05/26 TRAMMELL.C M NRC - No Detailed Affiliation Given 2pp 18694.362 24X Fiche 50-352,89/05/26.
 8306020280
- 8306170387 Opposes CL issuance until local officials agree upon acceptable emergency plan providing adequate protection to affected population HORDIS, B A Affiliation Unknown 83/06/09 BRENNER, L. Atomic Safety and Licensing Board Panel. 1p 18880 070 24X Fiche 50-352,83/06/09,8306170387
- K Utility Final Bafety Analysis Report (FBAR) & amends
- 8306010233 Forwards Rev 20 to FBAR. BRADLEY,E J. Philadelphia Electric Co. 83/05/31. DENYON,H R. Office of Nuclear Reactor Regulation, Director 3pp. 18675, 00 24X Fiche 50-352,83/05/31,8306010233 18675, 001,
- --8304010240 Rev 20 to F8AR * Philadelphia Electric Cn 83, Fiche 50-352,83/05/31,8304010233 83/05/31, 10pp, 18675 247, 24%
- 8304210283 Forwards Affidavit of Svc re distribution of Rev 20 to FSAR.
 Rev 13 to environ rept & Rev 3 to fire protection evaluation rept.
 BRADLEY, E J. Philadelphia Electric Co 83/06/17, DENTON, H R.
 Defice of Nuclear Reactor Regulation, Director 5pp 18915 082
 24X Fiche 50-352,83/06/17,8306210283,
- O Inspection reports, IE Bulletins & correspondence
- 8305110458 IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in Well Logging Device" Svc list encl
 TAYLOR, J. M. Division of Safeguards & Inspection Programs (Post 830103) 83/05/26 Consolidated Edison Co. of New York, Inc.
 125pp. 16831 043 24X Fiche 50-000,83/05/26.8305110458

- 8305110460 IE Info Notice 83-34, "Event Notification Info Horksheet" 8vc list encl JORDAN:E L Division of Emergency Preparedness & Engineering Response (Post 830103) 63/05/26 Consolidated Edison Co of New York: Inc 115pp 18732 085 24% Fishe 50-000, 83/05/26, 8305110460
- 8305090140 Forwards IE Insp Repts 50-352/83-05 & 50-353/83-02 on 830319-0422 & notice of violation 8TAR09TECKI, R Division of Project & Resident Programs B3/05/26 KEMPER, J. 8 Philadelphia Electric Co 2pp 18792 259 24X Fichs 50-352,83/05/26.8306090140
- --8304090143 Notice of violation from insp on 830319-0482 * Division of Project & Resident Programs 83/05/26 18792-261 24% Fichs 50-352, 83/05/26, 8306090140
- --8306090151 IE Insp Repts 50-352/83-05 & 50-353/83-02 on 830319-0422 Noncompliance noted separation requirement for electrical raceway (cable trays) not verified & GC instruction did not include appropriate insp methods for conduit bends CHAUDHARY, 8, K., PAOLINO, R.J., NICHOLAS-H. H. Region 1. Office of Director, 83/05/26 7pp 18792 263 24% Fiche 50-352, 83/05/26, 8306090140.
- 8305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods Withdrawn at BWRs " Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/31. Consolidated Edison Co. of New York, Inc 116pp 18732:208 24X Fiche. 50-000.83/05/31.8305110461
- 8306150237 Forwards IE Insp Repts 50-352/83-07 & 50-353/83-04 on B30424-0528 No noncompliance noted.
 STAROSIECKI:R Division of Project & Resident Programs B3/06/02 KEMPER, J.S. Philadelphia Electric Co 2pp 18846 011 24X Fishe 50-352,83/06/02.8306150237.
- --8306150247 iE Insp Repts 50-352/83-07 t 50-353/83-04 on 830424-0528 No noncompliance noted Hajor areas inspected control red drive supports; following of Part 21 repts, design change control to parsonnel training CHAUDHARY.6.K. GRANT, J H : CONNER, E L Region 1, Office of Director. 83/06/02. 5pp 18846; 013 24X Fichs: 50-352, 83/06/02, 8306150237.
- 8306090212 Forwards Attachments 2 & 3 to 830520 ltr. Attachments may have been miscollated or incomplete WETTERHAMM. M. J. Conner & Wetterhahm WETTERHAMM. M. J. Philadelphia Electric Co 83/06/06. BRENNER.1. MORRIS, P.A., COLE, R.F., Atomic Bafaty and Licensing Board Panel. (ipp 1879-103 24X Fiche, 50-352,83/04/06,8306090212.
- 8305110464 IE Info Notice 83-36, "Impact of Security Practices on Bafe Operations." Syc list encl.
 JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/06/07 Consolidated Edison Co. of New York. Inc. 119p. 18830-280 24X Fiche-50-000.83/06/09.8305110464.
- 8305140470 IE Info Notice 83-38, "Defective Heat Bink Adhesive & Beismically Induced Chatter in Relays Within Printed Circuit Cards." Svc list encl.

 JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/06/13 Consul/dated Edison Co. of New York, Inc. 118pp 18920, 225 24% Fishe 50-000, 83/06/13, 8305110470
- B306090010 IE Info Notice 83-37, "Trensformer Failure Resulting From Degraded Internal Connection Cables" Svc list encl.
 JORDAN,E L. Division of Emergency Preparadness & Engineering Response (Post 830103), 83/06/13. Consolidated Edison Co. of New York, Inc. 243pp 18921-001, 24X Fichs. 50-000, 83/06/13, 8306090010
- 8306200317 Forwards draft responses to NRC draft SER Questions 250 1, 250, 2, 250, 3, 250, 4 & 250 5 re preservice insplict reactor pressure vessels, pumps & valves Responses will be incorporated in Jul 1903 FBAR rev BRADLEY, E. J. Philadelphia Electric Co. 83/06/14 SCHWENCER, A. Licensing Branch 2. Sipp. 18899 212 24X Fichs. 50-352, 83/06/14, 8306200317.
- B305110475 IE Info Notice B3-40. "Need to Environmentally Qualify Epoxy Grouts & Bealers." Eve list encl.
 JORDAN, E. L. Division of Emergency Preparadness & Engineering Response (Post B30103). B3706/22. Consolidated Edison Co. of New York. Inc. 115pp. 19021:179. 24X Fiche.50-000.83/06/22.8305110475.
- 8305110477 IE Info Notice 83-41, "Actuation of Fire Buppression Sys Causing Inoperability of Bafety-Related Equipment," Byo list encl. JORDAN,E L. Division of Emergency Preparadness & Engineering Response (Post 830103). 83/06/22 Consolidated Edison Co. of New York, Inc. 120pp. 18997-007. 24X Fiche: 50-000,83/06/22,8305110477.

- 8305110479 IE Info Notice 63-42, "Reactor Mode Switch Malfunctions "
 Svc list ancl
 JURDAN: E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/06/23 Consolidated Edison Co of New
 York: Inc 116pp 18996 242 24X Fiche 50-000.83/06/23.8305110479
- 8305110483 IE Info Notice 83-43, "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Fost 830103) 63/06/24 Consolidated Edison Co of New York, Inc 116pp 19046 297 24X Fiche 50-000,83/06/24,8305110483
- S Reportable occurrences, LERs & related correspondence
- 8306100092 Part 21 rept re potential incorrect interface w/reactor pressure vessel instrument piping Caused by error on four local instrument panel piping diagrams Field deviation disposition requests issued No operating plants affected SHERMODD.0 O General Electric Co 82/11/18 DEVOUNG.R C Director's Office, Office of Inspection and Enforcement 3pp 18802 226 24X Fichs 50-382,82/11/18,8306100092
- 830A280417 Part 21 Deficiency Rept 80 re damaged insulation on MCC Powers Co shielded multiconductor cable on HVAC control panels. Also reported by MCC Power KEMPER. J S Philadelphia Electric Co 83/06/01 MURLEY. T E Region 1. Office of Director 1p 17020 276 24X Fiche, 50-352, 83/06/01, 8306280417
- V Operator Examinations
- 8306140449 Requests attendance at 830627 meeting in King of Prussia.PA to discuss transfer of operating reactor licensing function from Bethesda. MD to Region I ofc STARDSTECKI.R Division of Project & Resident Programs 83/06/09 KEMPER.J B Philadelphia Electric Co 2pp 18836 345 24X Fiche 50-352.83/06/09.8306140449
- DOCKET 50-353 LIMERICK GENERATING STATION, UNIT 2

 A Application/construction stage documents & correspondence
- 8306030086 Notification of 830525 meeting w/util in Betheeda.MD to resolve issues re accident evaluation identified in NRC 830311 ltr MARTIN.R.E Licensing Branch 2 83/05/20 8CHWENCER.A Licensing Branch 2 4pp 18733 267 24% Fiche 50-352,83/05/20,8306030086
- 8306010272 Forwards draft changes to FSAR, design assessment rept & to greviously provided responses in answer to Issues 55, 5c, 5d, 5e & 20 discussed at 830407 meeting Rept on functionality of purge & vent valves will be submitted in June 1983 BRADLEY, E J Philadelphia Electric Co 83/05/26 SCHMENCER, A Licensing Branch 2 75pp 18678 304 24% Fiche 50-352, 83/05/26, 8306010292
- 8306020649 Notification of 830608 meeting w/util & BMNL in Bethasda.HD to discuss severe accident risk assessment (SARA) MARTIN.R E Licensing Branch 2 83/05/27 BCHWENCER.A Licensing Branch 2 4p 18716 271 24X Fiche 50-352,83/05/27,8306020649
- B306010293 Forwards application for Amend 51 to DL application (filed in Category A) consisting of environ qualification rept.Rev 20 to FBAR (filed in Category K) & Rev 13 to environ rept (filed in Category C)
 BRADLEY,E J Philadelphia Electric Co 83/05/31 DENTON.H R Office of Nuclear Reactor Regulation, Director. 3pp 18675 001 24X Fiche. 50-352, 83/05/31, 8304010233.
- --8306010237 Application for Amend 51 to OL application, consisting of Rev 20 to FBAR, environ qualification rept & Rev 13 to environ rept BAUER, E G Philadelphia Electric Co B3/05/24 App 18675 004 24X Fiche: 50-352, 83/05/31, 8304010233
- 8306090194 Notification of 830608 meeting w/util & Bechtel in Ban Francisco.CA to discuss outstanding items in structural engineering review area MARTIN.R E Licensing Branch 2 83/06/02 8CHWENCER.A. Licensing Branch 2. 3pp 18809 252 24X Fiche.50-352.83/06/02.8306090194
- B30&070239 Forwards revised draft response to Question 410 17 re CP application compliance w/NUREG-0800 per 830330 meeting w/NRC Changes will be incorporated in FSAR rev scheduled for June 1983,
 BRADLEY, E. J. Philadelphia Electric Co 83/06/03 SCHMENCER, A Licensing Branch 2 3pp. 18747 048 24X Ficher 50-252, 83/06/03, 830&070239,

- 8306100109 Forwards revised draft response to Question 430 4B re level of training for operators, maint crew & GA personnel Response will be incorporated into FBAR rev scheduled for Jul 1983
 BRADLEY,E J Philadelphia Electric Co 83/06/06 SCHMENCER, A Licensing Branch 2 opp 18802 205 24X Fiche 50-352,83/06/06, 8304100107
- 830&1000&6 Forwards draft FBAR change re breed line depressurization branch per Accident Evaluation Branch request Change will be incorporated into Jul 1983 FBAR rev BRADLEY.E J Philadelphia Electric Co 83/06/07 SCHWENCER, A Licensing Branch 2 3pp 18803 069 24X Fiche 50-352,83/06/07, B3061000&5
- 830.6100.241 Forwards revised draft response to FBAR mgt technology section re licensed operator courses & operating activities transmitted in 830506 ltr.per 830527 request Changes will be incorporated into FBAR rev acheduled for Jul 1983 BRADLEY, E. J. Philadelphia Electric Co. 83/06/07 SCHHENCER, A. Licensing Branch 2 App. 18807-053 24X Fiche 50-352, 83/06/07, 8306100241
- 830615032i Forwards request for add1 info re FSAR Dasign Criteria Bummary, Item 260 56 reflecting requirements of NUREO-0797, "Clarification of TMI Action Plan Requirements" SCHHENGER, A Licensing Branch 2 83/06/07 BAUER, E @ Philadelphia Electric Co 7pp 18870 010 24X Fiche 50-352,83/06/07,830615032i
- 8306160340 Responds to GA Branch 830527 telcon request re proposed organization change in Electric Production Dept reflecting change in GC Program for Operational Phase DALTROFF, S L Philadelphia Electric Co 83/06/07 8CHMENCER, A. Licensing Branch 2 8pp 18859 082 24% Fiche 50-352, 83/06/07, 8306160340
- 0306160310 Forwards final response to NUREO-0612, "Control of Heavy Loads at Nuclear Power Plants-Resolution of TAP A-36" Response includes analyses for loads handled over reactor vessel KEMPER, J 8 Philadelphia Electric Co 83/06/13 EISENHUT, D 0 Division of Licensing 126pp 18860 243 24% Fiche 50-352. 83/06/13,8306160310
- 830&1&0377 Forwards rev to Page 1 2 of 830531 environ qualification reptito be formally incorporated into Oct 1983 rept rev BRADLEY, E J Philadelphia Electric Co 83/06/13 8CHWENCER, A Licensing Branch 2 3pp 18861, 123. 24X Fiche 50-352, 83/06/13, 8306160377
- 8306170210 Forwards draft responses to requests for add1 info Questions 252 I through 252 7 & related draft FBAR text changes. Draft changes will be incorporated in FBAR in rev scheduled for Jul 1983

 BRADLEY, E J Philadelphia Electric Co 83/06/14 BCHWENCER, A Licensing Pranch 2 100pp 18883-153 24X Fichs 50-352,83/06/14,8306170210
- 8306170309 Provides marked-up draft FSAR pages per QA Branch 830527 request for add1 info Page changes will be incorporated in FSAR rev scheduled for Jul 1983 BRADLEY, E. J. Philadelphia Electric Co. 83/06/14 SCHNENCER, A. Licensing Branch 2 16pp 18877.113 24X Fiche 50-352,83/06/14,8306170309.
- 8306210418 Notification of 830615 meeting w/util, Bechtel & QE in Sethesda, MD to discuss high radiation isolation signals on containment purge/vent valves MARTIN, R. E. Licensing Branch 2 83/06/14 SCHWENCER, A. Licensing Branch 2. 4pp 18937 065 24X Fiche 50-352,83/06/14,8306210418
- 8384200117 Forwards response to Matls Engineering Branch 830603 request for Info re turbine missile issue.

 BRADLEV.E U. Philadelphia Electric Co 83/06/15, 8CHWENCER, A Licensing Branch 2. Spp 18903 247 24X Fiche 50-352
- B306210220 Forwards met1 presented at Anderson, Greenwood & Co (AGCo) vacuum breaker test program owners group B30607 meeting w/ NRC re dynamic testing & analysis of AGCo vacuum breaker valve assemblies 0 °CONNOR, D. M. Bechtel Corp 83/06/17 HOUSTON, R. W. Division of Systems Integration (post B11005). 91pp 18919 038. 24X Fichs. 50-000, 83/06/17, 8306210220
- 8306240412 Notification of 830621-24 meetings w/util, Bechtel & QE in Sen Jose & Ban Francisco. CA to discuss outstanding items in Matle Engineering Branch review of compliance w/ODC 51 MARTIN.R.E. Licensing Branch 2. 83/06/17. BCHMENCER.A. Licensing Branch 2. 4pp. 18978.013 24X Fiche: 50-352,83/06/17,8306240412

- 8306230276 Responds to NRC 830523 request for proposed resolution to TMI Item II K 3 i8. "Mod of Automatic Depressurization Sys Logic" Justification for bypass timer setting will be provided prior to implementation of mod KEMPER, J S Philadelphia Electric Co 83/06/20 SCHWENCER, A. Licensing Branch 2 3pp 18945 135 24X Ficha 50-352, 83/06/20, 8306230276
- 8306270212 Forwards revs to FBAR Sections 9 5 6 3.7.2.8 3 & 9 5-10. Info will be incorporated into rev to FSAR scheduled for Jul 1983 BRADLEY, E. J. Philadelphia Electric Co. 83/06/21 BCHHENCER, A. Licensing Branch 2 10pp 18990 282 24X Fiche 50-352.83/06/21, 8306270212
- 8306270365 Forwards revised draft response to FBAR Gusstion 410 70 re design temp for essential svc water & RHR svc water sys Draft change will be incorporated into FBAR rev scheduled for Jul 1983.

 BRADLEY, E. J. Philadelphia Electric Co. 83/06/21. SCHWENCER, A. Licensing Branch 2. 6pp. 18993 193. 24X Ficher 50-352, 83/06/21, 8306270365
- 8306270423 Forwards draft FSAR changes prepared in response to Containment Sys Branch Open Item 18 Changes state isolation valves will be sealed closed info will be incorporated into FSAR rev scheduled for Jul 1983 BRADLEY, E J Philadelphia Electric Co 83/06/23 BCHWENCER, A Licensing Branch 2 7pp 18992; 126 24X Fiche 50-352, 83/06/23, 8306270423
- 8306270459 Forwards draft revised responses to NRC Questions 410 05, 410 10, 410 37, 410, 52, 410, 85 k 410 89, per telicon w/Auxiliary 8ys Branch Responses will be incorporated in FBAR scheduled for Jul 1983
 BRADLEY,E J Philadelphia Electric Co 83/06/23 SCHWENCER, A Licensing Branch 2 20pp 18992-075 24% Fichs, 50-352,83/06/23, 83006/24, 60006
- 8306300024 Responds to 830607 request for add1 info, forwarding documents used by Btructural Mechanics Assoc in seismic fragility development BRADLEY,E J Philadelphia Electric Co 83/06/27 80HMENCER,A Division of Licensing
- 8306300221 Forwards draft FBAR changes re loose parts monitoring sys for rev scheduled for Jul 1983 Detailed sys description per Reg Quide I 133 submitted, pending receipt of 8ER. RRADLEY,E, J Philadelphia Electric Co. 83/06/27 SchWENCER,A. Licensing Branch 2. 7pp 19120 001 24X Fichs 50-352,83/06/27, 8306300221.
- 8306300133 Forwards draft revised response to TMI Item I 9.1: "Training During Low-Power Testing," per 830627 conference call Info contained in draft revised response will be incorporated into FBAR rev scheduled for Aug 1983
 BRADLEY,E J Philadelphia Electric Co. 83/06/28 BCHWENCER,A. Licensing Branch 2 5pp 19122 311. 24X Fiche. 50-352,83/06/28, 8306300133
- C Utility Environmental Report (ER), amends & correspondence
- 8306010233 Forwards Rev i3 to environ rept. BRADLEY,E J Philadelphia Electric Co 83/05/31 DENTON,H R. Office of Nuclear Reactor Regulation, Director. 3pp 18675:001. 24X Fiche 30-352,83/05/31,8306010233
- --8306010243 Rev 13 to environ rept. Environ qualification rept for safety-related equipment encl # Philadelphia Electric Co 83/05/31 237pp. 18675:010 24X Fiche. 50-332, 83/05/31. 8306010233
- B304210283 Forwards Affidavit of Bvc re distribution of Rev 20 to F8AR, Rev 13 to environ rept & Rev 3 to fire protection evaluation rept.

 BRADLEY, E J Philadelphia Electric Co. 83/06/17 DENTON, H. R.

 Defice of Nuclear Reactor Regulation, Director 5pp 18915, 022, 24X Fiche: 50-352, 83/06/17, 8308210283
- E NRC Safety Evaluation Report (SER), supply & correspondence
- B306070330 Forwards responses to listed Procedures & Test Review Branch SER open items Draft response to TMI Item I.C 1. "Operating & Maint Procedures & ATWS." incorporated in Hay FBAR rev. BRADLEY.E.J. Philadelphia Electric Co 83/06/03. BCHMcNCER.A. Licensing Branch 2. 4pp. 18746.065. 24X Fiche: 50-352.83/06/03. 8306070330.

- 8306150579 Forwards request for add1 info re SER open items Action plan & associated dates for response required within 7 working days of receipt of 1tr SCHWENCER. A Licensing Branch 2 83/06/03 BAUER. E 6 Philadelphia Electric Co 24pp. 18867 038. 24X Fiche. 80-352, 83/06/03, 8306150579.
- 8306100110 Forwards final response to Reactor Sys Branch draft SER Item 3 re high/low pressure interlocks on ECCS injection valves, per discussion at 830517 meeting in Betheade, MD BRACLEY, E. J. Philadelphia Electric Co 83/06/07 SCHWENCER, A Licensing Branch 2 App 18802:201 24X Fiche 50-352,83/06/07,8306100110
- 8306140545 Responds to Geotechnical Engineering Branch draft BER open itsms transmitted via 830311 ltr. Properties of foundation bedrock, backfill, lateral loading & response of in-situ soil & backfill matls to dynamic loading discussed BRADLEY, E. J. Philadelphia Electric Co., 83/06/09 BCHMENCER, A. Licensing Branch 2 25pp 18834 179 24X Fiche 50-352,83/06/09,8306140545
- 8306140606 Forwards response to Structural Engineering Branch draft SER Open Items 1, 4,8 & 9, All open items closed out Items 1, 4 & 8 regresent formal response while Item 9 indicates FBAR page changes BAUER, E 0. Philadelphia Electric Co 83/06/10 SCHWENCER, A Licensing Branch 2 38pp 18833 061. 24X Fiche: 50-352, 83/06/10, 8306140606.
- 8306140624 Forwards draft responses to SER Open Items 2,7,9,11,12,16, 18,17,21,27 & 34 re fire protection. Fire protection evaluation rept will be submitted in Aug 1983 BRADLEY. E J Philadelphia Electric Co 83/04/10 SCHWENCER, A Licensing Branch 2, 33pp. 18833 326 24X Fiche 50-352,83/04/10,8306140624.
- 8306160001 Forwards draft FSAR page changes, in response to Reactor Sys Branch fraft SER Item 1. "DDYN Analysis of Pressurization Transients." Changes will be incorporated into FBAR rev scheduled for Jul 1983
 BRADLEY.E J Philadelphia Electric Co 83/06/13 SCHWENCER, A Licensing Branch 2 58pp 18862,025 24X Fiche,50-352,83/06/13,8306160001
- 8306160371 Forwards draft responses & draft FSAR page changes in response to Meteorology & Effluent Treatment Branch draft SER Itsms 2,4:5 & Request for Add Info RAI 451 14
 BRADLEY.E. J Fhiladelphia Electric Co. 83/06/13 8CHHENCER, A Licansing Branch 2 43pp. 18864 164. 24% Fiche: 50-352,83/06/13,8306160371.
- 8306160527 Forwards response to Core Performance Branch draft SER Draft page changes will be included in FSAR rev scheduled for Jul 1983.

 BRADLEY, E J. Philadelphia Electric Co 83/06/13 SCHWENCER, A. Licensing Branch 2 91pp. 18863-140 24X Fiche 50-352, 83/06/13, 8306160527
- 8306160572 Forwards draft SER, Section II, "Test Review," Item 2, consisting of FBAR changes to be incorporated into FSAR revischeduled for Jul 1983

 BRADLEY, E. J. Philadelphia Electric Co 83/06/13 BCHMENCER, A. Licensing Branch 2. 73pp. 18866 211 24X Fiche, 50-352,83/06/13,8306160572
- 8306170369 Forwards response to Accident Evaluation Branch draft SER, per 830525 meeting request Draft page changes will be included in FSAR rev scheduled for Jul 1983 BRADLEY.E J Philadelphia Electric Co. 83/06/14. SCHHENCER.A. Licensing Branch 2 17pp. 18880-193. 24X Fiche. 50-352,83/06/14,8306170369
- 8306200317 Forwards draft responses to NRC draft SER Questions 250 1, 250, 2, 250, 3, 250, 4 & 250, 5 re preservice insp of reactor pressure vessels.pumps & valves. Responses will be incorporated in Jul 1983 FBAR rev.

 8RADLEY.E. J Philadelphis Electric Co 83/06/14 SCHMENCER, A Licensing Branch R. 31pp 18879: 212, 24% Fishs 50-352, 83/06/14, 8306200317.
- 830624041B Notification of 830624 meeting w/util t QE in Sethesda, MD to discuss Effluent Treatment Sys Branch open SER Itams MARTIN, R.E. Licensing Branch 2, 83/06/20 SCHWENCER, A Licensing Branch 2, 4pp. 18978:009. 24X Fiche: 50-352, 83/06/20, 836840418.
- 8306270086 Forwards revised draft response to Question 480 7, including revised Section 6, 2, 6, 5, 1 & Table 14, 2-4 in response to Containment Sys Branch draft SER Issue 1 & revised draft Section 6, 2, 3, 2, 5 k table 6, 2-15 SRADLEY, E. J. Philadelphia Electric Co. 93/06/21, SCHWENCER, A. Licensing Branch 2, 23pp. 19013:125, 24X Fiche; 50-352, 83/06/21, 8306270086.

- 8306270315 Provides response to structural engineering review draft SER open items discussed & resolved at 830603 meeting reresponse spectra, reactor encl & control structure KEMPER.J B Philadelphia Electric Co 83/06/21 SCHWENCER, A Licensing Branch 2 19pp 18994 010 24X Fiche 50-352,83/06/21,8306270315
- 8306280381 Forwards calculate post-LOCA bounding drywell temp profile, per 830510 Rev 20 changes to FSAR Soction 3 11 in response to Containment Bys Branch draft SER. Item 4
 KEMPER. J B Philadelphia Electric Co 83/06/24 SCHMENCER, A Licensing Branch 2 App 19014 063 24X Fiche 50-352, 83/06/24, 8306280381
- 8306300016 Forwards draft rev to response to Question 640 10 re low power & power ascension testing providing info necessary to close liem 5 of draft SER, Section II, "Test Review " Info will be included in FSAR rev scheduled for Jul 1983 BRADLEYLE J Philadelphia Electric Co 83/06/27 SCHWENCER, A Licensing Branch 2 3pp 19120 252 £4X Fiche 50-352,83/06/27,8306300016
- 8306300200 Forwards list of Auxiliary Sys Branch open SER issues per 830623 meeting & marked-up draft FSAR pages responding to 1ssues 8ABLEY,E J. Philadelphia Electric Co 83/06/28 SCHWENCER, A Licansing Branch 2 51pp 19122 126 24X Fiche 50-352,83/06/28. 8306300200
- F Security, medical, emergency & fire protection plans
- 8306140395 Forwards draft change to FSAR re emergency ac lighting.prr 830607 telcon commitment Change will be formally incorporated into FGAR rev. scheduled for Jul 1983 BRADLEY.E J Philadelphia Electric Co 83/06/10 SCHWENCER.A Licensing Branch 2 4pp 18832 089 24X Fiche 50-352.83/06/10. 8306140395
- 8306140624 Forwards draft responses to SER Open Items 2.7, 9, 11, 12, 16, 18, 19, 21, 27 & 34 re fire protection Fire protection evaluation rept will be submitted in Aug 1983 BRADLEY, E. J. Philadelphia Electric Co. 83/06/10 BCHWENCER, A. Licensing Dranch 2 33pp 18833 326 24X Fiche 50-352, 83/06/10, 8306140624
- 83062001B3 Forwards draft changes to FSAR Section 9 5 3 2 2 & Guestion 430 61 re outdoor security & roadway lighting Changes will be incorporated into FSAR rev scheduled for Jul 1983
 8RADLEY.E J Philadelphia Electric Co 83/06/15 SCHWENCER.A Licensing Branch 2 5pp 18903 173 24X Fiche 50-352.83/06/15.830A30A3R3
- B306210283 Forwards Affidavit of Svc re distribution of Rev 20 to FSAR. Rev 13 to environ rept & Rev 3 to fire protection evaluation rept BRADLEY.E J Philadelphia Electric Co 63/06/17 DENTON.H R Office of Nuclear Reactor Regulation. Director 5pp 18915.022 24X Piche 50-352, 83/06/17.8306210283

O Adjudicatory correspondence

- 8306010464 Discusses IE Insp Rept 50-353/76-06 re inaccessible welds Welds capriciously & unilaterally declared acceptable following convenient & unscientific decision that welds cannot be inspected due to inaccessibility ROMANO,FR Air and Water Pollution Patrol 83/05/25 Atomic Safety and Licensing Board Panel 2pp 18679 319, 24X Fichs. 50-352, 83/05/25, 8306010464
- 8304010372 Forwards motion for reconsideration of ASLE 830509-11 ruling re-coordination of contention filing w/Limerick Ecology Action.

 AU.T.Y. Pennsylvania. Commonwealth of. 83/05/26 BRENNER, L., MORRIS.P.A., COLE, R.F. Atomic Safety and Licensing Board Panel 19 18682, 091. 24X Fiche. 50-352, 83/05/26, 8306010372
- --8306010380 Motion for reconsideration of ASLB 830509-ii rulings recoordination of contention filing w/Limerick Ecology Action Ruling undermines role of state in presenting issues in neutral manner. Certificate of Syc encl AU, T, Y Penneylvania, Commonuealth of, 83/05/26 Atomic Safety and Licensing Board Panel 11pp. 18682.092. 24X Fichs 50-352,83/05/26,8306010372

- 8306010367 Petition to withdraw as intervenor representative in (IL proceeding RJ Suparman will continue to represent intervenor Draft order encl NEILL.J M Del-Aware Unlimited. Inc 83/05/31 Atomic Safety and Licensing Board Panel 2pp 18682 105 24X Fiche 50-352.83/05/31.8306010369
- 9305030280 Response supporting NRC reply to ASLB 930516 order re use of PRA & subsequent risk-related documents Certificate of Svc & RK Meatherwax prof qualifications encl DDREEY, J A Limerick Ecology Action DDRSEY, J A Dorsey, J A 83/05/31. Atomic Safety and Licensing Board Panel 27pp 18705 187 24X Fiche 50-352,83/05/31,8306030280
- B306020351 Memorandum & order denying Del-Aware 830308 motion to reopen record & add proposed new Contention V-26 Contention is not significant & would not affect outcome of decision BRENNER, L Atomic Safety and Licensing Board Panel 83/06/01 Del-Aware Unlimited. Inc. 11pp 18694 247 24X Fiche 50-352,83/06/01,8306020351
- 8306030286 Order granting JM Neill petition to withdraw appearance request.

 BRENNER,L Atomic Safety and Licensing Board Panel 83/06/01 ip 18703 331 24% Fiche 50-352,83/06/01,8306030286
- B306060322 Advises that Bucks County, PA citizens voted for County withdrawal from further participation in Point Pleasant Diversion Project intended to supply supplemental cooling water to plant Referendum does not affect contractor rights CONNER, T B Conner & Wetterhahn CONNER, T B Philadelphia Electric Co B3/06/02, KDHL, C N , EDLES, G J , GDTCHY, R L Atomic Safety and Licensing Appeal Panel 13pp 18729 172 24X Fiche 50-352, B3/06/02, B306060322
- 8306060330 Order scheduling resumed appellate process matters Exceptions to ABLB 830601 order denying Del-Aware 830308 mation, due 830616 Briefs supporting all exceptions due 830718 SHOEMAKER, C. J. Atomic Bafety and Licensing Appeal Panel 2pp 18726 361 24X Fiche 50-352.83/06/02.8306060330
- 8306070295 First set of interrogatories & request for production of documents
 METTERHAMN.M J Philadelphia Electric Co WETTERHAMN.M J Conner & Wetterhahn 83/06/03 Air and Water Pollution Patrol Bpp 18741 186 24X Fiche 50-352,83/06/03.8306070295
- --8306070279 First set of interrogatories & request for production of documents METTERHAHN,M,J Philadelphia Electric Co WETTERHAHN,M J Conner & Wetterhahn 83/06/03 Friends of the Earth 9pp 18741,194 24X Fiche 50-352,83/06/03,8306070295
- --B306070301 First set of interrogatories & request for production of documents Certificate of Byc ancl METTERHAHN, M J Philadelphia Electric Co WETTERHAHN, M J Conner & Wetterhahn, B3706/03. LEMIB, M I Lewis, M 9pp 18741 203, 24X Fiche, 50-352, 83/06/03, 8306070295
- 8306090212 Forwards Attachments 2 & 3 to 830520 ltr Attachments may have been miscollated or incomplete.

 METTERHAHN,M J Conner & Netterhahn WETTERHAHN,M J Philadelphia Electric Co 83/06/06 BRENNER,L , MORRIS,P A , COLE,R F Atomic Sefety and Licensing Board Panel 11pp, 18796 103 24X Fiche 50-352,83/06/06,8306090212
- 8306090240 Motion for extension until 830610 to respond to NRC use of facility PRA. Filing allowed per ABLB 830516 order confirming schedules Certificate of Byc encil HETTERHAHN, M. J. Philadelphia Electric Co. WETTERHAHN, M. J. Conner & Watterhahn B3/06/06 Atomic Safety and Licensing Roard Panel App. 18795 328 24X Fichs. 50-362, 63/06/06, 8306090240.
- 8306080167 Order granting util 830606 motion for extension until 830610 to file response to NRC & Limerick Ecology Action filings on PRA contentions. Parties consent & good cause shown.
 BRENNER-L Atomic Bafety and Licensing Board Panel. 83/06/07.
 Philadelphia Electric Co. ip 18772 154. 24X Fiche: 50-352, 83/06/07. 830600167
- 8306090301 Order extending time until 830627 for Commission to act to review ALAB-726.
 CHILK: S J Office of the Secretary of the Commission 83/06/07.
 Commissioners ip. 18795: 241. 24X Fiche 50-352, 83/06/07.
 8306090301
- 8306100195 Order requiring NRC to update schedule estimate for issuence of DEB. All parties under duty to inform ABLB of any change in met i info BRENNER.L. Atomic Bafety and Licensing Roard Panel B3/06/09 Cemmissioners 2pp. 18806:017. 24X Fiche: 50-352, 83/06/09, 8306100195.

- 8304130346 Advises that if Pennsylvania Emergency Mpt Agency draft emergency plans available by 831115, FEMA would complete review by mid Feb 1984 FEMA will expedite review & should be placed on svc list VOCLER, B H Hearing Branch 2 83/06/09 BRENNER, L, MORRIS, PA, COLER, F Atomic Bafetty and Licensing Board Panel 2pp 18821.268 24X Fiche 50-352,83/06/09,8304130346
- 8306140676 Responds to request for definition of safety classification terms by transmitting relevant portions of ASLB 830526 Decision ALAB-729 HODODON,A P Hearing Branch 2 83/06/10 LEWIS,M I Lewis, M 6pp 18842 069 24% Fiche 50-352,83/06/10,8306140676
- 8306140715 Response to first set of interrogatories on pressurized thermal shock. Contention I-62 Certificate of Svc encl HODODON.A P Hearing Branch 2 83/06/10 Lewis, N 27pp 18841 296 24% Fiche 50-352,83/06/10.8306140715
- 8306140722 Responds to ASLB B30609 order requiring NRC to update schedule for DES issuance Behadule unchanged since dates set at 830509-11 second spacial prehearing conference, DES, except Chapter 7. to be published on B30613 HODODON, AP Hearing Branch 2. B3/06/10 BRENNER, L., HORRIS, P. A., COLE, RF Atomic Safety and Licensing Board Panel 2pp 18841.094 24X Fiche: 50-352, 83/06/10, 8306140722
- 8306150362 Discusses Contentions I-33D, D, E, K & I-45 re TMI Action Plan Items I C 6, I 0 1, I D 1, II F 1, II, D 3 & II B, 2. Contentions denied w/o pregudice by ASLB 830516 memorandum & order, for lack of specificity
 DDRSEY, J A Dorsey, J A DDRSEY, J A Limerick Ecology Action
 B3/06/10 BRENNER, L , MORRIB, P A. , CDLE, R F. Atomic Safety and Licensing Board Panel 2pp. 18847 148 24X Fiche 50-352, 83/06/10, 8306150362
- 8306150393 Response to NRC use of facility PRA & Limerick Ecology Action response to ASLB 830516 memorandum & order confirming schedules Certificate of Syc enci HETTERHAHN, H. J. Philadelphia Electric Co HETTERHAHN, H. J. Conner & Wetterhahn 83/06/10 Atomic Bafety and Licensing Board Panel. 11pp. 18847 159, 24X Fichs 50-352,83/06/10.8306150393
- 8306160603 Forwards util answer to MI Lewis first set of interrogatories on pressurized thermal shock contention.
 HETTERHAHN, M. J. Conner & Wetterhahn HETTERHAHN, M. J. Philadelphia Electric Co. 83706/13 LEHIB, M. I. Lewis, M. ip. 18866-144. 24X Fiche 50-352, 83/06/13, 8306160603.
- --B306160609 Answers to first set of interrogetories on pressurized thermal shock contention. Certificate of Svc encl
 BOYER, V B Philadelphia Electric Co B3/06/09 LEWIS, M I
 Lewis, M 16pp 18866 145 24X Fiche 50-352,83/06/13,8306160603
- 8304220043 Answer to first set of interrogatories re pressurized thermal shock in BMRs. LEWIS, M I Lewis, M 83/06/15 Philadelphia Electric Co. 2pp 18922 255 24X Fiche. 50-352, 83/06/15, 8306220043
- 8304220051 Files add1 exceptions to ASLB 830401 order refusing to consider Interstate Delaware River Mgt 830517 recommendations to referendum. Certificate of 8vc encl BUGARMAN, R. J. Del-Aware Unlimited, Inc. BUGARMAN, R. J. Bugarman, R. J. 83704/16 Atomic Bafety and Licensing Appeal Panel, 5pp. 18726, 198 24X Ficher 50-352, 83/04/14, 8304220051.
- 8306220103 Forwards Commonwealth of PA Supreme Court decision, Unanimously reversing Commonwealth Court & holding that PUC of PA acted within power & acted properly when ordering util to cancel or suspend const of Unit 2.

 SUGARMAN, R J Sugarman, R J, 83/06/16 BRENNER, L., COLE, R F., MORRIS, P. A Atomic Seety and Licensing Board Panel. 16pp 18926 038 24X Fiche 50-352,83/06/16,8306220103.
- 8306270297 Forwards onsite swergency planning contentions in response to ASLB 830516 memorandum of order.
 DURGEY, J.A. Dorsey, J.A. 83/06/17, BRENNER.L., COLE,R.F.,
 MORRIB,P.A. Atomic Safety and Licensing Board Panel. 35pp.
 18995:170 24X Fichs.50-352,83/06/17,8306270297.
- --8306270300 Onsite emergency plenning contentions Certificate of 8vc enc1 * Limerick Ecology Action, 83/06/17 32pp 18995:172 24X Fiche:50-352:83/06/17,8306270297
- 8306270038 Answer to first set of interrogatories. Related correspondence.
 ANTHONY:R C. Friends of the Earth ANTHONY:R.C Anthony, R.L., 83706/20. Philadelphia Electric Co. 2pp. 18988: 135. 24X Fiche: 50-352, 83/06/20, 8306270038

- B306290364 Discusses Air & Water Pollution Patrol response to util B30606 interrogatories Related correspondence. ROMANO, F.R. Air and Mater Pollution Patrol 83/06/21 BRENNER, L., COLE, R.F., MORRIS, P.A. Atomic Bafety and Licensing Board Panel 19 19055. 826 24X Fiche 50-358, 83/06/21, 8306290364
- 8306290509 Response to 830606 interrogatories. Related correspondence ROMAND.F.R. Air and Water Pollution Patrol. 83/06/21 Atomic Bafety and Licensing Board Panel 5pp 19052-209. 24X Fiche-80-352.83/06/21.8306290509
- 8306270413 Advises that util does not object to Limerick Ecology Action position in 830610 ltr on contentions related to NUREO-0737. WETTERHAHMAN J Conner & Wetterhahm NETTERHAHMAN J Philadelphia Electric Co 83/06/23 BRENNER.L. MORRIG.P.A., COLE.R F Atomic Sefety and Licensing Board Panel. 2pp 18974 146 24X Fiche: 50-352.83/06/23.8306270413
- 8306280566 Responds to Del-Aware 830616 ltr ASLB requesting admittance of new contention Del-Aware failed to comply w/procedure re late-filed contentions.

 HODODON:A P Hearing Branch 2, 83/06/27 BRENNER,L, HORRIS,P A. COLE,R F. Atomic Bafety and Licensing Board Panel 2pp. 19017.330 24X Fiche 50-352,83/06/27,8306280566
- 8306300143 Advises that time for Commission to review ALAB-726 expired Commission feelined review Decision became final agency action on 930627.
 CHILK, S. J. Office of the Secretary of the Commission 63/06/29.
 Office of the Executive Legal Director 1p 19168 117 24X
 Fiche, 50-352, 83/06/29, 8306300143.

H Gameral correspondence

- G306020380 Requests further discussion of 10CFR50.54(x) & (y) re single failure criterion. Issue of common mode failure of all solemoids litigable
 LEWIS, M. I. Lewis, M. 63/05/26 TRANMELL, C. M. NRC No Detailed Affiliation Given. 2pp. 18694-362, 24% Fiche 50-352,83/05/26, 020400300
- 8306170387 Opposes OL issuance until local officials agree upon acceptable emergency plan providing adequate protection to affected population.
 HORDIS, B. A. Affiliation Unknown 83/06/07 BRENNER, L. Atomic Safety and Licensing Board Panel. 1p 18880-070 24% Fiche: 50-352, 83/06/07, 8306170387
- K Utility Final Bafety Analysis Report (FSAR) & amends
- 8304010233 Forwards Rev 20 to FBAR.
 BRADLEY,E.J. Philadelphia Electric Co. 83/05/31, DENTON.H R
 Office of Nuclear Reactor Regulation, Director, Spp. 18675, 001,
 24% Fichs. 50-352, 83/05/31, 8306010233
- --8306010240 Rev 20 to FBAR 4 Philadelphia Electric Co. 83/05/31. 10pp. 18675-247 24X Fiche:50-352.83/05/31.8306010233
- 8306210283 Forwards Affidavit of Bvc re distribution of Rev 20 to FSAR, Rev 13 to environ rept & Rev 3 to fire protection evaluation rept.

 BRADLEY.E.J. Philadelphia Electric Co. 83/06/17, DENTON, H R. Office of Nuclear Reactor Regulation, Director. 5pp. 18915 022 24X Fiche: 50-352, 83/06/17, 8306210283.
- O Inspection reports, IE Bulletins & correspondence
- 8303110458 IE Info Notice 83-32, "Ruptured Am-241 Spurces Contained in Well Logging Device" Syc list encl TAYLOR, J.M. Division of Safeguards & Inspection Programs (Post 830103). B3/05/26. Consolidated Edison Co. of New York, Inc. 125pp 18831.043 24X Fiche: 50-000, 83/05/26, 8305110458.
- 8305110460 IE Info Notice 83-34, "Event Notification Info Worksheet."

 8vc list encl.

 JORDAN,E.L. Division of Emergency Preparedness & Engineering
 Response (Post 830103), 83/05/26. Consolidated Edison Co. of New
 York, Inc. 115pp. 18732:085. 24X Fichs 50-000,83/05/26,8305110460.
- 8304090140 Forwards IE Insp Repts 50-352/83-05 & 50-353/83-02 on 830319-0422 & notice of violation. 81AR081E6K1R. Division of Project & Resident Programs. 83/05/26, KEMPER, U.S. Philadelphia Electric Co. 2pp. 18792: 259. 24X Fichs. 50-352, 83/05/26, 8306090140.

- --8306090151 IE Insp Repts 50-332/83-05 & 50-353/83-02 on 830319-0422 Noncompliance noted separation requirement for electrical raceway (cable trays) not verified & 6C instruction did not include appropriate insp methods for conduit bends CHAUDHARY, 8 K., PAOLINO, R.J., NICHOLAS, H. Region 1, Office of Director 83/05/26 7pp 18792 263 24X Fiche 50-352,83/05/26, 8306090140
- 83051104&1 IE info Notice 83-35, "Fuel Mavement W/Control Rods Withdrawm at BWRs " Syc list entl JORDAN, E. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/31 Consolidated Edison Co of New York, Inc. 116pp 18732 208 24X Fiche 50-000,83/05/31,83051104&1.
- 8306190237 Forwards IE Insp Repts 50-352/63-07 & 50-363/83-04 on 830424-0588 No noncompliance noted STAROSTECKI.R Division of Project & Resident Programs 83/06/02 KEMPER, J & Philadelphia Electric Co 2pp 18846 011 24X Fiche: 50-352, 83/06/02, 8306150237
- --8306150247 IE Insp Repts 50-352/83-07 & 50-353/83-04 on 830424-0528, No noncompliance noted Major areas inspected control rod drive supports, followup of Part 21 repts design change control & personnel training CHAUDHARY, S K , GRANT, J M , CONNER, E L Region 1, Office of Director 83/06/02 5pp 18846-013 24X Fiche 50-352,83/06/02,8306150237
- 8306090212 Forwards Attachments 2 & 3 to 830520 ltr Attachments may have been miscollated or incomplete WETTERHAHN, M. J. Conner & Wetterbahn 83/06/06 BRENNER, L. Atomic Safety and Licensing Board Panel 11pp 18794 103 24X Fichs 50-352,83/06/06,8306090212
- 8305110464 IE Info Notice 83-36. "Impact of Security Practices on Safe Operations " Syc list encl JORDAN:E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83706/09 Consolidated Edison Co of New York, Inc 119pp. 18830 280 24X Fiche 50-000.83/06/09,8305110464
- 8305110470 IE Info Nptice 83-38, "Defective Meat Sink Adhesive & Seismically Induced Chatter in Relays Within Printed Circuit Carda " Svc list enci. JURDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83706/13 Consolidated Edison Co. of New York. Inc 118pp 18980.225 RAX Fiche 50-000.83706/13.8305110470
- 8306090010 IE Info Notice 83-37, "Transformer Failure Resulting From Degraded Internal Connection Cables " Svc list enci JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co of New York, Inc. 243pp. 18921 001 24X Fiche 50-000,83/06/13,8306090010
- 8306200317 Forwards draft responses to NRC draft SER Questions 250 i, 250 2,250 3,250.4 & 250 5 re proservice insp of reactor pressure vessels, pumps & valves Responses will be incomporated in Jul 1968 FSBR rev RRADLEY, E J Philadelphia Electric Co 83/06/14, SCHWENCER, A Licensing Branch 2 31pp 18899 212 24X Fiche 50-352,83/06/14, 8306200317.
- 8305110475 IE Info Notice 83-40, "Need to Environmentally Gualify
 Epory Grouts & Sealers " Svc list encl
 JORDANIE L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/06/22. Consolidated Edison Co of New
 York, Inc 1155p 17021 179 24X Fiche 50-000,83/06/22.8305110475
- 8305110477 IE Info Notice 83-41, "Actuation of Fire Suppression Sys Causing Inoperability of Bafoty-Related Equipment." Svc list encl. JORDAN, E. Division of Emergency Preparadness & Engineering Response (Post 830103) 83/06/22 Consolidated Edison Co of New York, Inc. 120pp. 18997 007, 24X Fiche. 50-000, 83/06/22, 8305110477
- 8305110479 IE Info Notice 83-42, "Reactor Mode Switch Malfunctions "
 Svc list eacl.
 JORDAN, E.L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/06/23 Consolidated Edison Co. of New
 York, Inc. 116pp. 18996 R42 24X Fiche 50-000,83/06/23,8305110479
- 8305110483 IE Info Notice 83-43, "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints." Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/24 Consolidated Edison Co. of New York, Inc. 116pp 17046 297 24X Fiche, 50-000, 83/06/24, 8305110483

- S Reportable occurrences, LERs & related correspondence
- 8306100092 Part 21 rept re potential incorrect interface w/reactor pressure vessel instrument piping Caused by error on four local instrument panel piping diagrams Field deviation disposition requests issued No operating plants affected SHERNOOD, 0 General Electric Co 82/11/18 DEYQUNG.R C Director's Office. Office of Inspection and Enforcement Opp 18802 226 24X Fiche 50-352,82/11/18,8306100092
- 8306280417 Part 21 Deficiency Rept 80 re damaged insulation on MCC Powers Co shielded multiconductor cable on HVAC control panels Also reported by MCC Power, KEMPER, J S Philadelphia Electric Co 83/06/01 MURLEY, T E Region 1, Office of Director 1p 19020 296 24X Fiche 50-352,83/06/01.8306280417

V Operator Examinations

- E308140449 Requests attendance at B30827 meeting in King of Prussia.PA to discuss transfer of operating reactor licensing function from Bethesdan MD to Region I ofc STAROSIECKI.R Division of Project & Resident Programs 83/06/09 KEMPER.J B Philadelphia Electric Co 2pp 18836-345 24X Fiche 30-352.83/06/09.8308140449
- DOCKET 50-354 HOPE CREEK NUCLEAR STATION, UNIT 1
- A Application/construction stage documents & correspondence
- 8306270407 Forwards emended application for OL.for Hope Creek Generating Station.Unit 1 MITTL.R L Public Service Electric & Gas Co. of New Jersey 93/06/28 SCHMENCER.A Licensing Branch 2 2pp 19575 001 24X Fiche 50-354.83/06/28.8306290409
- --8306290432 Amended application for DL for Hope Creek Generating Bitation, Unit 1 # Public Bervice Electric & Gas Co of New Jersey. 83/06/28 19pp 19575-003 24X fiche 50-354.83/06/28,8306290409
- C Utility Environmental Report (ER), amends & correspondence
- --8306290435 Environ rept OL stage for Hope Creek Generating Station. Unit 1, Vols 1 & 2 * Public Service Electric & Gap Co of New Jersey 83/06/28 600pp 19543.001 24X Fiche 50-354,83/06/28,8306290409
- K Utility Final Bafety Analysis Report (FBAR) & amends
- B306290409 Forwards FBAR, amended application for DL (filed in PDR Category A) & environ rept (filed in PDR Category C), for Hope Creek Denerating Station, Unit I Sthedule of responses to NRC questions will be provided within 60 days MITTL. RL Public Service Electric & Gas Co of New Jersey B3706/28 SCHMENCER, A Licensing Branch 2 2pp 19575.001 24X Fiche, 50-334, 83/06/28, 8306270409
- --8306290431 Hope Creek Generating Station.Unit 1.FSAR, Vols 1-18 # Public Service Electric & Gas Co. of New Jersey 83/06/28 9.008pp 19575 022 24X Fichs 50-354.83/06/28,8306290409
- --8306270444 Chapter 1 to Hope Creek Generating Station, Unit 1.FSAR, "Introduction & General Description of Plant"
 + Public Service Electric & Gas Co. of New Jersey 83/06/28
 500pp 19575 028 24X Fiche 50-354.83/06/28,8306270409
- --8306270448 Chapter 2 to Hope Creek Generating Station, Unit 1, FSAR, "Site Characteristics "

 Public Bervice Electric & Gas Co of New Jersey 83/06/28 850pp 19576 165. 24X Fiche 50-354, 83/06/28, 8306270409
- --8306290449 Chapter 3 to Hope Creek Constating Station Unit 1, FSAR, "Design of Structures, Components, Equipment & Bys " Fublic Service Electric & Cas Co. of New Jersey 83/06/28 11/00pp. 19578:304 24X Fiche. 50-334, 83/06/28, 8306290409
- --8306270481 App 3A to Hope Creek Generating Station, Unit 1, FSAR, "Computer Programs Used in Structural Analysis & Design."

 Public Service Electric & Oas Co of New Jersey 83/06/28 17ps. 19582 075. 24X Fichs 50-354.83/06/28.8306290409
- --8306290454 App 3B to Hope Creek Generating Station, Unit 1,FSAR,
 "Mark I Long-Term Program Plant-Unique Analysis FSAR Summary
 Rept."

 Public Service Electric & Gas Co of New Jersey 83/06/28
 43pp 19382.092 24% Fiche 50-354,83/06/28,8306290409

- --8306290466 App 3C to Hope Crock Generating Station.Unit 1.FBAR.
 "Reactor Asymmetric Load Analysis "
 Public Service Electric & Gas Co of New Jersey 83/06/28
 4pp 19982 104 24% Fiche 50-354.83/06/28,8306290409.
- --8306290457 Chapter 4 to Hope Creek Generating Station,Unit 1.F8AR,
 "Reactor "

 * Public Service Electric & Gas Co of New Jersey B3/06/28
 155pp 1982 144 24X Fiche 50-354.83/06/28,8306290409
- --8306290458 Chapter 5 to Hope Creek Generating Station Unit 1.FBAR.

 "RCB & Connected Sys"

 * Public Service Electric & Qas Co of New Jersey B3/06/28
 200pp 19582.335 24% Fiche 50-354.83/06/28.8306290409.
- --8306290460 Chapter 6 to Hope Creek Generating Station.Unit 1.FSAR.
 "ESF"

 * Public Service Electric & Qas Co of New Jersey 83/06/28
 700pp. 19583 253 24X Fiche 50-354.83/06/28,8306290409
- --8306270465 App 6A to Hope Creek Generating Station Unit 1.F8AR.
 "Negative Pressure Design Evaluation"
 + Public Service Electric & Oas Co of New Jersey 83/06/28
 23pp 19885 111. 24X Fiche 50-354.83/06/28,8306270409
- --8306290468 App 68 to Hope Creek Generating Station.Unit 1.FBAR, "Subcompartment Differential Presure Considerations,"

 * Public Service Electric & Oas Co. of New Jersey 83/06/28
 63pp 19585 134 24X Fiche. 50-354.83/06/28
- --8306290469 Chapter 7 to Hope Creek Generating Station.Unit 1.FSAR.
 "Instrumentation & Controls "

 * Public Service Electric & Gas Cn of New Jersey 83/06/28
 1.500pp 17585 198 24% Fichs 50-354,83/06/28,8306290409
- --8306290471 Chapter 8 to Hope Creek Generating Station.Unit 1.FBAR.
 "Electric Power"

 * Public Service Electric & Gas Co. of New Jersey 83/06/28
 500pp 19587:247 24X Fiche.50-354.83/06/28,8306290409
- --8306290473 Chapter 9 to Hope Creek Generating Station.Unit 1.FBAR.
 "Auxiliary 8ys "

 * Public Service Electric & Gas Co of New Jersey 83/06/28 1.200pp 19388 130 24% Fiche 50-354.83/06/28.8306290409.
- --8306270474 Chapter 9A to Hope Creek Generating Station, Unit 1, FSAR, "App R Comparison"

 * Public Service Electric & Gas Co of New Jersey, 83/04/28
 113pp, 19590, 245 24X Fiche 50-354, 83/04/28, 8304290409.
- --8306270477 Chapter 10 to Hope Creek Generating Station, Unit 1, FBAR, "Steam & Power Conversion Sys."

 + Public Bervice Electric & Gas Co of New Jersey. 83/06/28 300pp 19591 016 24% Fithe 50-354, 83/06/28, 8306290409.
- --8306270478 Chapter 11 to Hope Creek Generating Station, Unit 1, FSAR, "Radwaste Mgt "

 * Public Service Electric & Gas Co. of New Jersey. 83/06/28 300pp. 19591.123 24X Fiche 50-354,83/06/28,8306290409
- --B306270479 Chapter 12 to Hope Creek Generating Station, Unit 1, FBAR, "Radiation Protection" Public Service Electric & Ges Co of New Jersey 83/06/28. 600pp. 19372: 003 24% Fiths 50-354,83/06/28,8306270409.
- --8306290482 Chapter 13 to Hope Creek Generating Station.Unit i.FSAR,
 "Conduct of Operations."

 # Public Bervice Electric & Gas Co of New Jersey 83/06/28,
 200p 1993:146 24X Fiche 80-354.83/06/28.8306290409
- --8306290484 Chapter 14 to Hope Creek Generating Station, Unit 1, FSAR,
 "Initial Test Program."

 * Public Service Electric & Qas Co of New Jersey. 83/06/28.
 150pp. 19593:337 24X Fiche 50-354,83/06/28,8306290409.
- --8306290487 Chapter 15 to Mope Creek Generating Station, Unit 1, FSAR, "Accident Analysis "
 * Public Bervice Electric & Gas Co of New Jersey, 83/06/28, 400pp. 19594: 121. 24X Fiche: 50-354, 83/06/28, 8306290409.
- --8306290489 App 15A to Hope Creek Generating Station, Unit 1.FSAR.

 * Public Service Electric & Gas Co. of New Jersey 83/06/28.
 22pp 19595 221 24X Fiche: 50-354.83/06/28.8306290409.
- --8306270491 Chapter 16 to Hope Creek Generating Station.Unit 1,FSAR,
 "Tech Specs."

 * Public Service Electric & Gas Co. of New Jarsey 83/06/28. 1p.
 19595,248 24X Fiche: 50-354.83/06/28,8306290409

- --8306290494 Chapter 17 to Hope Creek Generating Station. Unit 1.FSAR.
- --- 9306270497 Chapter 18 to Hope Creek Generating Station, Unit 1, FSAR. Human Factors Engineering "
 Human Factors Engineering "
 Fullic Bervice Electric & Oas Co of New Jersey 83.
 12pp 19895 305 24% Fiche 50-354.83/06/20.8306290409
- O Inspection reports, IE Bulletans & correspondence
- 8306060010 FOIA request for documents re investigation of L Berstler allegations concerning facility HODAS, D R. Potter & Carmine 83/03/18 Office of Administration ip. 18782 305 24X Fiche 50-354,83/03/18,8306060010
- 8304040013 Responds to FDIA request for documents re investigation of L Berstler allegations concerning facility Forwards listed documents.
 FELTON.J M Division of Rules and Records 83/04/15 HODAS,D R Potter & Carmins. 2pp 18752-306 24X Fichs. 50-354.83/04/15, 8306040013
- --8306040015 IE inquiry rept on 820819. Major area investigated L Berstler allegations re deficiencies in installation & testing of RVAC sys at Facility Inquiry closed SHEPHERD, R E., CHRISTOPHER, R. Region 1, Office of Director 82/11/22 14pp 18752:308 24X Fichs 50-354,83/04/15,8306660013
- --B906060018 Statement of LR Benstler alleging deficiencies in installation & testing of HVAC sys at facility Leak test rapt forms for nongas-tight ductwork & worksheet encl. BENBILER, L. R. Affiliation Unknown B2/04/13 App 18752 322. 24% Fiche: 50-354, 83/04/15, 8306060013
- --8306060021 Discusses L Berstler, former Hilliard & Hirsch, Arkin, Hershman (N-H) QC inspector, allegations re HVAC installation at facility, Bethtal preliminary review indicated minor hardware deficiencies & QC paperwork problem TRIPP, L. E Division of Project & Resident Programs 82/05/0 Division of Project & Resident Programs 2pp 18752-328 2- Fichs 50-354,83/04/15,8306060013 82/05/04
- ~-8306060023 Biscusses L Berstler, former Williard & Hirsch, Arkin, Hershman (N-H) OC Inspector, allegations re deficiencies in installation & testing of HVAC sys at facility, SHEPMERD, R E. Region 1, Office of Director, 82/12/16 Region 1, Office of Director, 82/12/16 Region 1, Office of Director 1p 18752-330 24X Fiche, 50-354, 83/04/15, 8306060013.
- 8304020375 Forwards IE Insp Rept 50-354/83-07 on 830418-22 No noncompliance noted
 HARTIN.T T. Division of Project & Resident Programs. 83/05/20
 HARTIN.T J. Public Bervice Electric & Que Co. of New Jersey |
 18675-113 24X Fiche 50-354,83/05/20,8304020375
- --8306020376 IE Insp Rept 50-354/83-07 on 830418-22 No moncompliance noted, Major areas inspected procurement, qualification, insp & installation of electrical raceways, cables, valves & Instrument lines PAOLINO.R., GREGO.H I. ANDERSON.C. Region 1, Office of Director. 83/05/14 7pp 18495;115 24X Fiche 50-354.83/05/20.8304020375.
- 8306280586 Ack receipt of 830601 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-354/83-05 STARDSTECKI,R. Division of Project & Resident Programs 83/06/20 MARTIN.T.J. Public Bervice Electric & Gas Co of New Jersey. 1P. 19017:325. 24X Fiche;50-354,83/06/20,8306280586
- --8306280570 Responds to NRC 830502 ltr re violations noted in IE Insp Rept 50-334/83-05 Corrective actions: GC & engineering personnel reinstructed on NVAC installation & acceptance criteria & Engineering Drawing C-0388-0 revised MARTIN: T J. Public Service Electric & Cas Co of New Jersey 83/06/01. ALAN: J M. Region 1. Office of Director. 2pp 19017: 326 24X Fiche: 50-354, 83/06/20. 8306280586

V. Operator Examinations

8304i40i48 Extends invitation to attend 830427 meeting in King of Prussia.PA to discuss transfer of reactor licensing function from BethesdayPD to Region I ofc.

8TAROSTECKI, Buyision of Project & Resident Programs 83/06/09.

MARTIN.T. J Public Service Electric & Cas Co of New Jersey 2pp 18839: 027 24X Fichs 50-354.83/06/09.8306140148

- DOCKET 50-355 HOPE CREEK NUCLEAR STATION, UNIT 2 V Operator Examinations
- 8306140148 Extends invitation to attend 830627 meeting in King of Prussis.PA to discuss transfer of reactor licensing function from Bethesda.MD to Region I ofc STAROSTECKI.R Division of Project & Resident Programs 83/06/09 MARTIN.T J Public Service Electric & Oas Co of New Jersey 2pp 18839 027 24% Fiche 50-354.83/06/09.8306140148
- DOCKET 50-356 UNIV OF ILLINOIS LOPRA RESEARCH REACTOR G Inspection reports: IE Bulletins & correspondence
- 8306100217 Forwards IE Insp Repts 50-151/83-01 & 50-366/83-01 on 830504-05 No noncompliance noted PAPERIELLO,C J Region 3, Office of Director 83/05/25 HILEV,O H Illinois, Univ of, Urbane-Champaign 2pp 18805 189 24X Fiche 50-151,83/05/25,8306100217
- --8305100220 IE Insp Repts 50-151/83-01 & 50-356/83-01 on 830504-05 No noncompliance noted Major areas inspected raduaste mgt & radiation protection program, audits, training, procedures & instruments & equipment GRANT, W II. ORRGEN.L R Region 3. Office of Director 83/05/23 6pp 18805 171 24X Fiche 50-151.83/05/25.8306100217
- 8306090023 Responds to violation noted in IE insp rept PROPOSED RESPONDE TO VIOLATION NOTED IN IE INSP TEPT Forwards data showing that calibr checks performed on dosimeters on 830616 BECK.G P Illinois. Univ of, Urbana-Champaign 83/05/31, GRANT.N B Region 3, Office of Director 2pp 18792 356, 24X Fichs 50-151,83/08/31,6306070023
- DOCKET 50-358 WILLIAM H. ZIMMER NUCLEAR STATION, UNIT 1 A Application/construction stage documents & correspondence
- 8306080307 FOIA request for info re safety & const violations at BADING, A. Affiliation Unknown 83/04/01 Division of Rules BADING, A. Affiliation Unknown 83/04/01 Division of Rules Records Ip 18792 217 24X Fiche 50-358,83/04/01.8306080307 Division of Rules and
- 8304080305 Responds to FOIA request for info re safety & const violations at facility Info available in LPDR.per 830407 VELCUN
 FELTON J M Division of Rules and Records 83/04/08 BADING.A
 Affiliation Unknown ip 18792 216 24X Fichs 50-358,83/04/08.
 8306080305
- 8305040156 Forwards summary of Ofc of Investigation rept re allegations concerning presence of Bechtel representatives at site prior to Nov 1982, potentially compromising objectivity of independent review Allegations not substantiated.
 FORTUNALE A Office of Investigation 83/04/26 SCOTT.S Division of Technical Information & Document Control 4pp 18541 131 24% Fiche 50-358,83/04/26.8305040156
- 8306010042 Forwards request for add1 info re diesel engine reliability to complete OL application review Amend to OL application should be amended to comple wheelve the enclose to enclose YOUNGBLOOD, B. J. Licensing Branch 1. 83/05/17 WILLIAMS, J. Cincinnati Gas & Electric Co. Spp. 18687 098 24X Fishe SD-338, 83/05/17, 83/05/01008 Fiche 50-358,83/05/17,8306010042
- 8306060347 Board Notification 83-67. forwards info re errors in computer analyses for Mark II containments Rept providing results of evaluations performed by S&W re Shoreham Mark II containment also encl NOVAK.T M Assistant Director for Licensing 83/05/19. A Safety and Licensing 804060347 Fiche 50-000.83/05/19.8306060349 Atomic
- 8306010151 Amend 149 to application for OL, consisting of Rev 95 to PBAR. WILLIAMB, J. Cincinnati Gas & Electric Co 83/05/31 DENTON.H R. Office of Nuclear Reactor Regulation, Director 2pp 18678 258 24X Fiche 50-358,83/05/31,8306010151.
- 8306060071 Ack receipt of 830513 ltr informing NRC of actions to expand quality confirmation program, Details will be reviewed during future insps
 HARNICK, R. F. Region 3, Office of Director 83/05/31 WILLIAMS, J. Cincinnati 9as & Electric Co. 2pp 18719 327 24X
 Fiche 50-358,83/05/31,8306060071

- ~-8306050074 Informs of intention to realign existing programs under quality confirmation program Details of addl expansions will be submitted WILLIAMS, J Cincinnati Gas & Electric Co B3/05/13 KEPPLER, J Q Region 3, Office of Director 2pp 18719 329 24% Fiche 50-358.83/05/31,8306060071
- 8305070357 Summarizes 830526 meeting to discuss planned changes to initial program plan Util interfaces w/Reactor Control, Inc should be added to program scope NEYLAN, A J Torrey Pines Technology 83/05/31 DICKHONER, W H Cincinnati Cas & Electric Co ip 18742 065 24X Fiche 50-359,83/05/31,8306070359
- 8306060254 Informs that definite fuel load date cannot be provided until 821112 Show Cause Order CLI-82-33 requirements met a safety-related const resumes Fuel load estimated for Fourth Quarter 1984
 - PAUFT duarter 1789 WILLIAMB, J. Cincinnati Gas & Electric Co. 83/06/01 Office of Nuclear Reactor Regulation, Director 2pp 24% Fiche 50-358,83/06/01,8306060284 DENTON: H
- 830A130381 Forwards Certificate of Svc for Amend 149, in form of Rev 95
 - JOBINION POWERS SALES TO SELECT TO B3/06/03 DENTIN, H R Office of Nuclear Reactor Regulation, Director 2pp 18822 347 24% Fiche 50-358,83/06/03,8306130381
- 830a220078 Submits 830606 request for documents re Kaisor Engineers.
 - Inc GA/GC personnel NEYLANLA J Torrey Pines Technology 83/06/09 H Cincinnati Gas & Electric Co ip 18927 182 24X Fiche 50-358.83/06/09.8306220078 HEDZICK, W
- B306270X32 Discusses effort to improve util organization Copy of ltr to editor which appeared in Cincinatti Enquirer & reply encl Expansion of GC program to cover bolting masonry walls &
 - rejentation of the program to cover soliting, massory wall seismic columns requested HILLIAMS, J. Cincinnati Gas & Electric Co. 83/06/16 Region 3, Office of Director. App. 18993 151, 24X Fiche 50-358,83/06/16.8306270332 KEPPLER, J 0
- B306280357 Forwards list of electronic communicating hardware installed in various depts at facility,per B30304 request H3LL1AMB.J Cincinnati Oas & Electric Co B3706/20 KEPPLER, J & Region 3, Office of Director 3pp 19014 092 24X Fiche 50-358.B3/06/20.B3062B0359
- B306270374 Ack receipt of B30601 ltr informing NRC of steps taken to provide current QA program in FBAR Util plans to submit rev to FBAR Chapter 17 I within 60 days of Region III approval
 - of Torrey Pines recommended plan
 HARNICKAR F Region 3, Office of Director 83/06/22
 Cincinnati Oas & Electric Co 2pp 18793 208 24X
 Fichu 50-358,83/06/22.8306270374. 83/06/25 MILLIAMS' 7
- --8306270378 Requests extension of 830610 deadling for submitting current GA program changes & rev to FBAR Chapter 17 1 until 60 days after Region III approval of plan resulting from Torrey Primes Technology mgt review
 HILLIAMS, J Cincinnati Oas & Electric Co 83/06/01 KEPPLER, J G
 Regian 3, Office of Director 2pp 18993 210 24X
 Fiche 50-358.83/06/22.8306270374
- B30628020B Responds to B30601 ltr requesting approval to continue activities re removal of wire ties at top of all previously installed Kellum Grips Request approved Initial installation of wire ties requires for ther detailed evaluation HARNICK.R F Region 3, Office of Director B3/06/24 WILLIAMS, J Cincinnati Gas & Electric Co 2pp 19015 05B 24X Fiche 50-358.83/06/24.8306280208
- --8306280213 Requests approval of encl Const Work Approval Request 98, Rev i re removal of wire ties at top of all previously installed Kellum Grips. WILLIAMS.J Cincinnati Gas & Electric Co 83/06/01 KEPPLER.J 0 Region 3. Office of Director 13pp 19015 060 24X Fiche 50-358.83/06/24,8306280208
- E NRC Safety Evaluation Report (SER), suppls & correspondence
- 8305060099 Forwards Rev 4 to "Transport of Toxic Chemicals & Control Room Habitability Study," in response to NRC request & in conjunction w/Suppl 3 to SER WILLIAMS. J Cincinnat: Gas & Electric Co 83/05/01 DENTON. H Office of Nuclear Reactor Regulation, Director ip 18731:301 Fiche 50~358,83/06/01.830606099
- --8306060101 Rev 4 to "Transport of Toxic Chemicals & Control Room Habitability Study " One oversize graph encl Aperture card is available in PDR BOOEN.P E Cincinnati Gas & Electric Co 83/05/18 114pp 18731,303 24X Fichs 50-358,83/06/01,8306060099

- 8306080137 Forwards "WH Zimmer Nuclear Power Station Unit 1. Heavy Loads Rept," in response to supplemental SER (NUREG-0528, Suppl 3) & NUREG-0612 re control of heavy loads WILLIAMS, J Cincinnati Gas & Electric Co 83/06/02 DENTON, H Office of Nuclear Reactor Regulation, Director 87pp 18768, 275 24X Fiche 50-358, 83/06/02, 8306080137
- --8306080140 "WH Zimmer Nuclear Power Station.Unit 1, Heavy Loads Rept." * Cincinnati 0ac & Electric Co 83/06/01 108pp 18768 277 24% Fishe 50-358, 83/06/02, 8306080137
- F Security, medical, emergency & fire protection plans
- 830.6030412 Forwards final schedule for satisfying requirements of Generic Ltr 82-33, Suppl 1 to NUREO-0737 "Requirements for Emergency Response Capability "YOUNGBLOOD, B J Licensing Branch 1 83/05/18 WILLIAMS, J. Cincinnati Oss & Electric Co App 18747 141 24X Fiche 50-358.83/05/18.8306030412
- 8304080213 Informs that station blackout procedure approved & available for NRC review.per NUREO-0528, Suppl 3. Subsection 8 1 2 WILLIAMS. J Cincinnati Gas & Electric Co 83/06/01 DENTON, H. R Office of Nuclear Reactor Regulation, Director ip 18771: 182 24X Fiche 50-358,83/06/01,8304080213
- G Adjudicatory correspondence
- 8304030321 Ack receipt of request to file amicus curise brief w/brief supporting Miami Valley Power Project motion for admission of eight GA contentions Request to file brief most Certificate of Svc and FRYE.J H. Atomic Bafety and Licensing Board Panel 83/06/DAVIS.M. Affiliation Unknown ip 1870B 349 24X Fiche 50-358.83/06/01.8306030321
- 830.606.075 Motion to reopen record for admission of eight contentions on GA & character & competence or, alternatively, for ASLB to exercise discretion to consider whether stds for 830715 demonstration of sua sponte authority met DEVINE, T Miami Valley Power Project 83/06/03 Atomic Safety and Licensing Board Powel 23pp 18723-023 24X Fiche 50-358,83/06/03.8306060075
- 8306070373 Requests Commission ignore Miami Valley Power Project 830525 ltr requesting Commission modify IE Director's Decision, DD-62-03,ruling on Project 820824 petition to suspend plant const const CONNER.T B Conner & Wetterhahn. CONNER.T B Cincinnati Gas & Electric Co 83/06/03 CHILK.B J Office of the Secretary of the Commission 3pp. 18741 355 24X Fiche 50-358,83/06/03.8306070373
- 8304080203 Request to file amicus curiae brief supporting Miami Valley
 Power Project efforts to obtain further public hearing
 SHEARER, V M , KRAUS-0 Affiliation Unknown. POWELL. T. Affiliation
 Unknown 83/06/06 Atomic 824
- ---8306080205 Brief supporting Miami Valley Power Project request to reapen licensing hearing re plant operation. Certificate of Syc encl Byc encl
 SHEARER V M , POWELL, T , KRAUB, G Affiliation Unknown. B3/06/06
 Atomic Safety and Licensing Board Panel. 4pp. 18770, 253, 24X
 Piche 50-358, 83/06/06, 8306080203
- 8304080215 Motion for leave to file amicus curiae brief supporting Miami Valley Power Project motion to reopen record to admit aight contentions on GA & character & competence AMADON, P. W. KRAUB, T., FREMONT, B. Affiliation Unknown 83/06/06 Atomic Safety and Licensing Board Panel 4pp. 18771 212 24X Fiche: 50-358,83/04/06,8304080215 83/06/06,
- 8306080162 Order delineating time for filing responses to requests to file amicus curiae briefs supporting Hiami Valley Power Project renewed attempt to obtain hearings on eight GA contentions FRYELJ H Atomic Safety and Licensing Board Panel 83/06/07 2pg, 18772.158 24X Fiche 50-358,83/06/07,8306080162

- 8306130483 Affirms Nuclear Study Committee, Southern Ohio District Church of Brethren 830603 amicus curiae brief Health, safety & well-being of Southern Ohio & Northern Kentucky communities must be assured Certificate of Svc encl DEARDORFF, D. MASON, J. M. Affiliation Unknown 83/6/07 Atomic Safety and Licensing Board Panel 3pp 18921 206 24% Fiche 50-358,83/06/07,8306130453
- 9306150384 Motion of Cumberland Chapter of Sierre Club for extension to file previously submitted amicus curies brief supporting Miami Valley Power Project renewed attempt to abtain bearings on eight 0A contentions

 # Bierre Club B3/06/10 Atomic Safety and Licensing Board Panel in 18847-231 24X Fiche 50-358.89/06/10,8306180384
- ~-B306iB0386 Motion of Appalachia-Science for extension to file previously submitted amicus curies brief supporting Miami Valley Power Project renewed attempt to obtain hearing on eight Oa contentions Certificate of Svc enc!
 * Affiliation Unknown 83/06/10 Atomic Bafety and Licensing Board Panel. 3pp 18847 202 24X Fiche 50-358,83/06/10,8306150384
- 8306160632 Order extending time until 830713 for Commission to act to review ALAB-727. CHILK:8 J Office of the Secretary of the Commission 83/06/13 Commissioners ip 18865:076 24X Ficha 50-358,83/06/13,
- 8306160581 Advises that Sierra Club.Cumberland Chapter.request to file amicus curiae brief or brief should not be refiled, Responses to request will be filed w/responses to Miami Valley Power Froject motion
 FRYE.J H Atomic Safety and Licensing Board Panel 83/06/14.
 BAVIS.M Bierra Club 1p. 18866-102 24X Fiche 50-358,83/06/14.
 8306160881
- 8306200333 Advises that NRC does not object to ASLB receipt of anicus curiae briefs re Miami Valley Power Project request for reconsideration of ASLB 820715 decision on eight GA/GC contentions
 BARTH, C. A. Hearing Branch 1 83/06/16 FRYE, J. H., LIVINGSTON, M.B., HODDER, F.F. Atomic Safety and Licensing Board Panel 1p 18900:195 24X Fiche 50-358, 83/06/16, 8306200333
- 8306200335 Petition for leave to file amitus curiae brief re Miami Valley Power Project motion to reopen record to admit eight contentions on OA & character & tompetence Requests extension of time, Certificate of Svc enci COOD.R. Sierra Club GOOD.R. Good, R.P. 83/06/16 Atomic Bafety and Licensing Board Panel Spp 18700-321 24X Fiche: 50-358, 83/06/16, 8306200335
- --8306200341 Ohio Sierra Club amicus curiae briaf supporting Miami Valley Powar Project motion to reopen record to admit sight contentions. Contentions provide evidence that GA problems exist Certificate of Svc encl.

 GOOD, R Sierra Club GOOD, R Affiliation Unknown 83/06/16
 Atomic Safety and Licensing Board Panel 6pp. 18700.327. 24X
 Fichs. 50-358, 83/06/16, 8306200335
- --8306200345 Forwards Appalachia-Science in the Public Interest request to file amicus curiae brief Amicus curiae brief not sent to NRC internal mail or docketing sections CLARK, L. Government Accountability Project 83/06/15 Docketing & Services Branch ip 18900-333 24X Fiche 50-358 83/06/16,8306200335.
- --8306200348 Appalachia-Science in the Public Interest request to file antous curies brief supporting Mami Valley Power Project attempt to obtain hearing on eight GA contentions * Affiliation Unknown. 83/05/20. Atomic Safety and Licensing Board Panel. 3pp 18900.334. 24X Fiche 50-358,83/06/16.8304.200335.
- --8306200351 Appalachia-Science in the Public Interest amicus curiae brief supporting Miami Valley Power Project renewed attempt to obtain hearings on sight OA contentions Certificate of Svc ancl DAVIS M Affiliation Unknown 83/05/17 Atomic Safety and Licensing Board Panel 5pp 18900 337 24% Fiche 50-358, 83/06/16,8306200335.
- --8306200389 Forwards Cumberland Chapter of Siarra Club request to file amicus curiae brief Amicus curiae brief not sent to NRC internal mail or docketing sections.

 GLARK, L. Gevernment Accountability Project 83/06/15

 Docketing & Services Branch 1p 18700;342. 24x

 Fiche, 30-338,83/06/16,8306200335

- --8306200372 Cumberland Chapter of Sierra Club request to file amicus curiae brief supporting Miami Valley Power Project renewed attempt to obtain hearing on eight GA contentions
 * Sierra Club S3/05/31 Atomic Safety and Licensing Doard Panel 3pp 18900 343 24X Fiche 50-358,83/04/16,8306200335
- 8306220031 Response opposing Mismi Valley Power Project 830603 matter to reopen record for admission of eight QA contentions Motion untimply HETTERHAHN, M. J. Cincinnati Qas & Electric Co. WETTERHAHN, M. J. Conner & Wetterhahn 83/06/20 Atomic Safety and Licensing Board Panel 48pp 18930-045 24X Fiche 50-358.83/06/20,8306220031
- --8306220036 Response opposing motions to file amicus curiae brief in support of Miami Valley Power Project motion to reopen record for admission of eight GA contentions Certificate of Svc encl
 HETTERHANN, M J Cincinnati Oas & Electric Co WETTERHANN M J Conner & Wetterhahn 83/06/20 Atomic Safety and Liconsing Board Panel 7pp 18930 093 24X Fiche 50-358, G3/06/20, 930A020031
- 8306240267 Brief opposing Miami Valley Power Project petition to adalt eight QA contentions Project failed to comply w/legal stds for reconsideration No program or policy supports reopening of record Certificate of Svc encl BARTH.C. A Hearing Branch 1 83/06/20 Atomic Safety and Licensing Board Panel 16pp 18980 110 24X Fiche, 50-35B, 83/06/20. 8306240267
- 8306270410 Memorandum supporting Miami Valley Power Project #30602 motion to reopen record to admit eight contentions on GA & lack of corporate character & competence Reopening necessary to foster public confidence in NRC M/Certificate of Svc WEBB.D F Mentor, KY. 83/06/22 Atomic Safety and Licensing Board Panel App 18994 140 24X Fiche 50-358.83/06/22.83062/0410

H General correspondence

- 8304210249 Informs that NRC correspondence should be directed to O C Ficke Revised address for svc list submitted FLYNN.J D Cincinnati Gas & Electric Co 83/06/16 pENTON,H Office of Nuclear Reactor Regulation, Director ip 18913-051 P4K Fiche 50-358,83/06/16,8305210249
- 8306230435 Notifies that effective immediately, all correspondence from NRC should be directed to 9C Ficke, Manager, Nuclear Licensing Dept at listed address FLYNN, J D Cincinnati Cas & Electric Co 83/06/16 KEPPLER, J Q Region 3, Office of Director ip 18942 077 24X Fiche: 50-358, 83/06/16, 8306230435
- K Utility Final Safety Analysis Report (FSAR) & amends
- 8306010151 Amend 149 to application for OL, consisting of Rev 99 to FSAR. WILLIAMB, J Cincinneti Gas & Electric Co. 83/05/31 DENTON, H R Defice of Nuclear Reactor Regulation, Director 2pp 186/8 958 24X Fichs. 30-389, 83/05/31, 8306010151
- --8306010154 Rev 95 to FSAR * Cincinnati Gas & Electric Co 63/05/31 44pp 18678 260 24x Fiche 90-358,63/05/31,8306010151
- 83061303B1 Forwards Certificate of Svc for Amend 149.in form of Rev 95 to FBAR.
 WILLIAMB, J. Cincinnati Gas & Electric Co. 83/06/03 DENTON, H. R. Diffice of Nuclear Reactor Regulation, Director 2pp 18882 347 24X Fiche 80-358,83/06/03,83061303B1
- G Inspection reports. IE Bulletins & correspondence
- B304040422 Forwards rept of investigation of allegations re presents of Bechtel representatives prior to Nov 1982 No evidence establishing Bechtel presence onsite prior to Nov 1982 H/o and.

 HAYES, B B Office of Investigation 83/03/16 KEPPLER, J D Region 9, Office of Director 2pp 18812 059 24X Fiche 50-358, B3/03/16, 8304040422.
- 8304040129 Forwards IE Insp Rept 50-358/82-13 on 830810-1104 & notice of violation No response required due to 821112 order suspending const KEPPLER. J G Region 3. Office of Director 83/05/23 WILLIAMS. J Cincinnati Gas & Electric Co 3pp. 18719.031 24X Fiche 50-358,83/05/23.8306060127.
- ---B306060132 Notice of violation from insp on 820810-1104. KEPPLER, J. G. Region 3. Office of Director B3/05/23 Epi 18719 034. 24X Fiche: 50-358,83/05/23,8306060129

DOCKETED ITEMS

- ~-8306060138 IE Insp Rept 50-358/82-13 on B20810-1104 Noncompliance noted GA manuals failed to provide adequate description of Catalytic. Inc purpose & function re site safety-related work activities to the safety-related YIN, 1 T. BARRET(,P A. MAUKA,F A. Region 3, Office of Director B3/04/21 33pp 18719 042 24X Fiche 50-358, B3/05/23, B306060129
- 8305110450 IE Info Natice 83-32, "Roptured Am-241 Sources Contained in Hell Logging Device" Svc list encl TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 125pp 18831 043 24X Fiche 50-000,83/05/26,8305110458
- 8305110460 IE Info Natice 83-34. "Event Natification Info Worksheet "
- 8305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods Hithdrawm at BWRs " 8vc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/31, Consolidated Edison Co of New York, Inc. 116pp 18732 208 24X Fiche 50-000,83/05/31,8305110461
- 8304070033 Forwards IE Mgt Meeting Rept 50-358/83-05 on 830425 KEPPLER.J G Region 3. Office of Director 83/06/01 WILLI Cincinnati Gas & Electric Co ip 18/40 005 24X Fiche 50-358.83/06/01.8308070033 LARMA LITH
- --9306070042 IE Mgt Meeting Rept 50-358/83-05 on 830425 Hajor areas discussed Torrey Pines Technology independent mgt review of util mgt MUNTER D.R., WARNICK.R.F. Region 3: Office of Director 83/05/
 - 10 R , WARNICK.R F Region 3, Office of Director 03/05/27 18740 006 24% Fiche 50-358,83/06/01,8306070033
- 8305110464 IE Info Notice 83-36, "Impact of Security Practices on Safe Operations " Syc list and Operations " Operations of Property Operations Operations of New York, Inc. 119pp 18830 280 24X Fiche 30-000.83/06/09.8305110464
- 8306230353 Forwards IE Insp Rept 50-358/82~17 on 821206-830218 & notice of violation

 WARNICK,R F Region 9, Office of Director 83/06/10 WILLIAM
 Cincinnati Cas & Electric Co 2pp 18943 288, 24X

 Fiche 50-358,83/06/10,8306230353 P'SWVITIIM 01/90/68
- --8306230357 Natice of violation from insp on 821206-830218 WARNICK,R F. Region 3. Office of Director. 83/06/10 18943,290 24X Fiche 50-358.83/06/10.8306230353
- --8306230359 IE Insp Rept 50-358/82-17 on 821206-830218 Noncompliance noted licensee corrective action statements re Final Deficiency Repts M-29 & M-30 concerning welder qualifications inappropriately dispositioned CHRISTIANSON.W., GHYNN.T.P., NICHTINGALE,E. Region 3, Office of Director 83/06/08 18pp 18943 291 24X Fiche 50-358,83/06/10,8306830333
- 8305110470 IE Info Notice 83-30, "Defective Heat Bink Adhesive & Beismically Induced Chatter in Relays Within Printed Circuit Cards " Byo list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co of New York, Inc 118pp. 18720.223 24X Fiche 50-000,83/06/13.0305110470
- B304090010 IE Info Notice B3-37, "Transformer Failure Resulting From Degraded Internal Connection Cables " Svc list encl JURDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post B30103) B3/06/13 Consolidated Edison Co. of New York, Inc. 243pp 18921-001 24X Fichs 50-000,83/06/13,8306090010
- 8304300212 Forwards IE Insp Rept 50-358/83-03 on 830419-21 No 306300212 Forwards It Insp Rept 50-358783-03 on 830419-21 No noncompliance noted LITILE.N 8 Region 3. Office of Director 83/06/15 HILLIAMS.J. Cipcinnati Gas & Electric Co 2pp 1912P 104 24X Fiche 30-358.83/06/15.8306300212
- --8306300218 IE Insp Rept 50-388/83-03 on 830419-21 No noncompliance noted Major areas inspected previous insp findings, IE bulletims & 100FR30 55(e) items MARD, X D. DANIELSON, D H. Region 3. Defice of Director 63/05/23 ilpp 19122 106 24X Fiche 50-356,03/06/15.8306300212.
- 8305110475 IE Info Notice 83-40, "Need to Environmentally Qualify
 Epoxy Grouts & Bealers " Svc list encl
 JORDAN, E.L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/06/22 Consolidated Edison Co. of New
 York, Inc. 115pp 19021-179 24X Fiche 80-000,83/06/22,8308110475

- 8305110477 IE Info Notice 83-41, "Actuation of fire Suppression Sys Causing Inoperability of Bafety-Related Equipment " Syc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/22 Consolidated Edison Co. of New York, Inc. 120pp 18997 007 24% Fiche 50-000,83/06/22.8305110477
- 8305110479 IE Info Notice 83-42. "Reactor Mode Switch Malfunctions "
 Svc list enc1
 JORDAN,E L Division of Emergency Preparedness & Engineering
 Response (Past 820103) 83/06/23 Consolidated Edison Co of New
 York, Inc 116pp 18996 242 24X Fich& 50-000,83/06/23,8305110479.
- 8305110483 IE Info Notice 83-43, "Improper Settings of Intermediate Range (1R) High Flux Trip Setpoints " Svc list encl JORDAN, E L Divasion of Emergency Preparadness & Engineering Response (Post 830103) 83/08/24 Consolidated Edison Co of New York, Inc 116pp 19046 297 24X Fiche 50-000,83/08/24,8305110483.
- R Periodic operating reports & related correspondence
- 8306070354 Forwards biweekly status rept on independent review of util project mpt covering period 830507-20.

 MEYLAN.A J Torrey Fines Technology 83/05/31. DICKHONER, W H. Cincinnati Que & Electric Co 3pp 18742 107 24X

 Fiche 50-358,83/05/31,8306070054
- 8304170321 Forwards quality confirmation program monthly status rapt & summary sheet for Apr 1983, in response to 821230 ltr WILLIAMB, J. Cincinnati Oas & Electric Co. 83706703 KEPPLER, J. G. Region 3, Opfice of Director 26pp 18878 217 24X Fiche 50-358, 83/06/03, 8306170321
- 8306230131 Forwards "Independent Review of Zimmer Project Mgt,"
 Biweekly Status Rept 3, for 930521-0603
 NEYLAN, A J Torrey Pines Technology 83/06/10 DICKHONER, H,
 Cincinnati Oas & Electric Co ip 18947 001 24X
 Fiche. 50-358, 83/06/10, 8306230131 DICKHONER, W. H.
- --8306230133 "Independent Review of Zimmer Project Mgt." Biweekly Status Rept 3. for 830521-0603 * Torrey Pines Tachnology. 83/06/10 46pp 18947 002 24X Fiche: 50-358.83/06/10,8306230131.
- S Reportable occurrences, LERs & related correspondence
- 8306060197 Interim deficiency rept to lack of procedural qualification for pipe bends Initially reported on 821109 Postqualification program for small bors pipe bending operations being conducted to date; 24 of 35 tests completed WILLIAMS; J Cincinnati Oas & Electric Co 83/05/25 KEPPLER; J. 9 Region 3. Office of Director 2pp 18727-322. 24X Fiche 50~358,83/05/25,8306060197
- 8304070135 Bupplemental final deficiency rept re inadequate RHR HX velves. Required mail expected within 1 month. Installation & testing to be scheduled efter mail received & Commission B21112 show cause order lifted.

 #ILLIAMS. J Cincinnati Gas & Electric Co. 83/05/27. KEPPLER, J C. Region 3. Office of Director 2pp 18739 262 24X
 Fiche 50-358,83/05/27.8306070125
- 8304070232 Interim deficiency rept re defective QE HMA relays Initially reported on 830225 NRC 82112 order to show cause & order immediately suspending const must be lifted to permit completion of corrective actions HILLIAMS, J. Cincinnati Cas & Electric Co. 83/05/27, KEPPLER, J.O. Region S. Office of Director. 2pp. 18746:103. 24X Fiche 50-358,83/05/27,8304070232
- 8304070267 Interim deficiency rept re failure of Brown Boveri wolid-state trip devices Initially reported on 830307 Order to show cause & order immediately suspending const dtd 82:112 must be lifted before work can be completed WILLIAMS, J. Cincinnati Gas & Electric Co. 83/05/27. KEPPLER, J. Q Region D. Office af Director 2pp 18747-074 24X Fiche 50-358,83/05/27,8306070267.
- 8304070267 Interim deficiency rept re failure of Brown Boveri solid-state trip devices Initially reported on 830307 Order to show cause & order immediately suspending const dtd 821112 must be lifted before work can be completed. WILLIAMS, J Cincinnati Oss & Electric Co 83/05/27 KEPPLER, J G. Region 3, Office of Director 2pp 18747,074 24X Fiche 50-058.63/05/27,8304070267 KEPPLER, J C.

- 8306070084 Deficiency rept re qualification of weld procedures consistent w/830207 response to 10CFRSD 58(e) Item M-29 (QA-2288) Activities in compliance w/821112 order to show cause & order immediately suspending const HILLIAMS, J Cincinnati Oas & Electric Co 83/06/01 KEPPLER, J O Region 3, Office of Director 2pp 18793 308 24X Fiche 50-358,63/06/01.8306090084
- 8306090127 Interim Deficiency Rept M-49 re radiographic & weld defects in sacrificial shields conteinment monorall & vent stack welds Analysis reviewed Corrective actions contingent upon lifting of NRC 821112 show cause order WILLIAMS. J. Cincinnati Gas & Electric Co. 83/06/01 KEPPLER. J. G. Region J. Office of Director 2pp 18792 252 24% Fiche 50-358.83/06/01.8306090127
- 8306210058 Interim deficiency rept for Item S-II re inadequacy of structural steel holting program to assure compliance w/design spec & FBAR criteria Initially reported on 830513 Followup rept expected by 830712.
 WILLIAMB-J Cincinnati Gas & Electric Co 83/06/10 KEPPLER, J G Region 3. Office of Director. Epp 18911 224 24X Fiche: 50-358, 83/06/10, 8306210058.
- 8304210054 Interim deficiency rept re Item 8-10 concerning masonry wall const not per design spec & FSAR criteria. Quality confirmation program will be expanded. Followup rept will be submitted by 830512
 HILLIAMB. J Cincinnati Qas & Electric Co 83/06/13 KEPPLER, J. 9 Region 3. Opfice of Director 2pp 18912-304 24X
 Fiche 80-358,83/06/13.8306210054
- 8306210274 Interim deficiency rept. Item S-7 re soil structure compaction outside power area not per design spec & FBAR criterie Initially reported on 830513. All eafety-related structures & sys will be identified WILLIAMS. J. Cincinnati Gas & Electric Co. 83/06/13 KEPPLER, J G Region 3. Office of Director Rop. 18915 147. 24X Fiche: 50-358,83/06/13,8306210274
- 8306230472 Interim deficiency rept on Item K-40 re indeterminate heat treatment for small hore pipe. Initially reported on 820422. Required corrective action contingent on NRC approval or release of 82112 order HILLIAMS, J Cincinnati Cas & Electric Co. 83/06/14 KEPPLER, J & Region 3, Office of Director 2pp. 18941: 323 24X Fiche, 50-358, 63/06/14, 8306230472
- 8306230081 Interim deficiency rept re Item M-56.inadequate installation of gamma plugs Requests due date of 830615 for next rept be extended to 830622 to allow coordination of status rept w/responsible dept managers
 MILLIAMS, J Cincinnati Gas & Electric Co. 83/06/15 KEPPLER, J G Region J, Office of Director Ip. 18947 076 24X
 Fiche 50-358.83/06/15.8306230081
- 8306230089 Interim deficiency rept re Item M-B7, inadequacy of design control process to assure design output documents contain adequate erection & into criteria. Initially reported on 830513 Item not reportable under 10CFR50 55(e) WILLIAMS.J Cincinnati Gas & Electric Co. 83/05/15 KEPPLER,J 0. Region G. Office of Director 20p 18747,074 24X Fiche 50-358,83/05/15.8306230089.
- 8306230268 Final deficiency rept on Item M-62 re fire damper failure. Initially reported on 821029 Orientation of "J" hooks on all seismic Air Balance. Inc fire dampers have been reversed so that open and is pointed away from blade MILLIAMB. J Cincinnati Gas & Electric Co. 83/06/15 KEPPLER, J 0 Region 3. Office of Director. 2pp 18945-102. 24X Fiche. 50-358. 83/06/15, 8306230268
- 8306230395 Interim deficiency rept re Item 8-5 on inadequate svc Level I coatings Initially reported on 830414 Extension to 830624 requested, for interim status rept submittal, WILLIAMS. J. Cincinnati Gas & Electric Co. 83/06/15 KEPPLER, J. Q. Region 3, Office of Director. ip. 18943.090 24X Fiche. 50-358, 83/06/15, 8306230395
- 8306230442 Interim deficiency rept re diesel generator control logic. Initially reported on 820913, Scheduling & completion of design change mod contingent on NRC release of 820912 order to show cause & order immediately suspending const WILLIAMS.J. Cincinnati Cas & Electric Co. 83/06/15. KEPPLER.J. 9. Region J. Office of Director. 2pp. 18942;081. 24X Fichs: 50-358, 83/06/15, 8306230442.
- 8306210123 Responds to 830519 deficiency rept re potentially reportable condition involving essential instruments attached to nonsemential/nonseismic piping Initially reported on 830420. Further avaluation required on design criteria MARNICK.R F. Region 3, Office of Director 83/06/16 WILLIAMS.J Cincinnati Gas & Electric Co. 2pp. 18918 134, 24% Fichs. 50-358.83/06/16.8306210123

- 8306230196 Interim deficiency rept. Item E-45 re failure of Stati;-C-Ring Model 5N pressure switch during environ qualification testing Engineering change request will be submitted to NRC to replace switches w/qualified pressure switches w/qualified pressure switches WILLIAMS; J Cincinnati Gas & Electric Co 83/06/16 KEPPLER, J & Region S, Office of Director 3pp 18746 349 24% Fiche 50-358, 83/06/16, 8306230176
- 8306270331 Interim deficiency rept re Item E-20, insp of inadequate cable tray hanger Initially reported on 820503 Insp criteria for weld quality acceptance will be established from analysis of Sargent & Lundy reinsp program Next rept 831010 WILLIAMS, J Cincinnati Gas & Electric Co 83/06/20 KEPPLER, J & Region 3, Office of Director 2pp 18793 119 24X Fiche 50-368, 83/06/20, 8306270331
- 8306270180 Interim deficiency rept re installation of gamma plugs Initially reported on 820804 Engineering evaluation & dispositioning of nonconformance repts will be completed by 830930 Next rept will be submitted by 831018 WILLIAMB. J Cincinnati Gas & Electric Co 83706/21 KEPPLER, J & Region 3. Office of Director 2pp 18791 345 24X Fiche 50-358, 83/06/21, 8306270180
- 8306300160 Interim deficiency rept re insdequate Svc Level I coatings (Item 8-5) Initially reported on 820928 Removal & replacement of coating necessary except where inaccessible Corrective action program being developed HILLIAMS.J Cincinnati Qas & Electric Co 83/06/23 KEPPLER.J 0 Region 3. Office of Director 20 pp 19119 306 24% Fiche 50-358,83/06/23,8306300160
- DOCKET 50-361 SAN QNOFRE NUCLEAR STATION, UNIT 2

 F Security, medical, emergency & fire protection plans
- 830&070251 Forwards IE Insp. Repts 50-206/83-10, 50-361/83-17 & 50-362/83-17 on 830411-27 & notice of violation BISHOP.T W Region 5. Office of Director 83/05/16 PAPAY.L T Southern California Edison Co. 2pp. 18746 088 24X Fichs 50-206.83/05/16,8306070251
- --8306070255 Notice of violation from insp on 830411-27 KIRBCH, D F Region 5, Office of Director 83/05/16 2pp 18746 090 24X Fiche 50-206,83/05/16,8306070251
- --8306070261 IE Insp Repts 50-206/83-10.50-361/83-19 & 50-362/83-17 en 830411-27. Noncompliance noted failure to install fully 6-h emergency lighting units in access/egress routes SCONN.K M Region 5, Office af Director 83/05/11 ijpp 18746 092 24X Fiche 50-206/83/05/16/8306070251
- 8306160011 Advises that 830323 Rev 9 to physical security plan consistent W/10CFR73 21 provisions & does not decrease plan effectiveness. Changes acceptable KNIGHYON, & H. Licensing Branch 3 83/06/06 DIETCH, R. Bouthern California Edison Co HOLCOMBE San Diego Gas & Electric Co Jap 18872 148 24X Fiche 50-206,83/06/06,8306160011
- G306220291 Responds to G30406 ltr re changes to physical security plan Changes consistent w/10CFR50 54(p) & do not decrease affectiveness of plan KNIGHTON,0 W Licensing Branch 3 G3/06/10 BIETCH,R Southern California Edison Co HOLCOMBE, J C San Diego Gas & Electric Co 3pp 18940 344 24X Fichs 50-206,83/06/10,8306220291
- 8306220274 Responds to 830323 ltr re Rev 2 to guard training & qualification plan Changes consistent w/10CFR50 54(p) provisions & do not decrease effectiveness of plan. KNIGHTGN.0 W Licensing Branch 3 83/06/10 DIETCH.R Southern California Edison Co HOLCOMBE.J. C San Diego Gas & Electric Co 3pp 18740 312 24X Ficha 50-206,83/06/10,8306220274
- 8306230520 Responds to 830427 ltr re temporary changes to physical security plan Changes consistent w/10CFR50 54(p) requirements & acceptable.
 KNIGHTON, O H Licensing Branch S 83/06/10 DIETCH, R Southern California Edison Co. HOLCOMBE, J C San Diego Gas & Electric Co 2pp 18954-361 24% Fiche 50-206,83/06/10.8306230520.
- 8304230455 Ack receipt & provides evaluation of changes to emergency plan implementing procedures submitted in 821029 & 831103 ltrs Changes do not decrease effectiveness of emergency response planning NORDERHAUO,L R Division of Radiological Safety & Safeguards Program 83/04/20 BASKIN,K.P Southern California Edison Co lf 18941 360 24X Fiche 50-204,83/04/20,8304230455

Q Adjudicatory correspondence

- \$306080195 Comments re offsite medical sycs, objections to applicant motion to augment record & request for hearing & proposed licensing condition Adequate arrangements for medical sycs not met Further hearings required MCCLUNG.C E Affiliation Unknown MCCLUNG.C E Flemming, Anderson, McCLUNG & Finch 83706/06 Atomic Safety and Licensing Board Panel 7pp 18772 251 24% Fiche 50-361,83/06/06,8306080195
- 8304080214 Response to util 830516 motion to augment record, position re Commission Memorandum & Order CLI-83-10 on offsite medical svcs & proposed findings of fact Supports motion & proposed findings VOOLER, B II Hearing Branch 2 83/06/06 Atomic Safety and Licensing Board Panel 7pp 18771 101 24X Fiche 50-361,83/06/06, B306080214
- --B3060B0216 Affidavit of DB Matthews that util ensured appropriate provisions for medical sycs to general public traumatically injured or contaminated during emergency Prof qualifications & Certificate of Syc encl
 MATTHEMS, D B Section B (Pre 820201) B3/04/06 7pp 18771 108 24% Fiche 90-361.83/06/06.8306080214
- 8306080157 Order extending time until 830614 for Commission to act to review ALAD-717 CHILK, B. J. Office of the Secretary of the Commission 93/06/07 Commissioners ip 18772 174 24X Fiche 50-361.83/06/07. B306080157
- 9306160635 Order extending time until 930621 for Commission to act to review ALAB-717 CHILK-S J Office of the Secretary of the Commission 93/06/14 Commissioners ip 18866-034 24X Fiche 50-361,83/06/14, 9306160635
- 8306210288 Response opposing GUARD & Carstens 830606 joint request for hearing on medical svcs issues Issue of sufficiency of medical resources atready litigated Heoring unnecessary to obtain authentication Certificate of Svc encl CHANDLER.L J Hearing Branch 2 83/06/17 Atomic Safety and Licensing Board Panel 8pp 18915 011 24X Fiche 50-361.83/06/17, 8306210208
- 8306220084 Reply to intervenor 830606 briefs on status of medical sycs issue Further hearings unjustified since Commission already ruled on adequacy of onsite medical sycs Declaration of Sycenci P1900TT. DR Gouthern California Edison Co P100TT. DR Orrick, Herrington & Suttliffe 83/06/17 Apr 18927 173 24X Fiche 50-361.83/06/17.8306220084
- 8306220127 Affidavit of FK Massey supporting util 830516 motion to augment record, authenticating documents as portions of Orange & San Diego County emergency plans MASSEY, F K Southern California Edison Co 83/06/17 5pp

J Insurance & indemnity information

- 8306270172 Forwards Endorsements 95,96 & 97 to NELIA Policy NF-146, & Endorsements 83,84 & 85 to MAELU Policy MF-38 & Endorsement 38 to NELIA Policy N8-282 ROCCO.J Southern California Edison Co. 83/06/13 DINITZ.I Antitrust & Economic analysis Branch (Utility Finance). 8pp 18971 349 24X Fichs 50-806.83/06/13.8306270172
- K Utility Final Safaty Analysis Report (FSAR) & amends
- B306150002 Amend 32 to FSAR W/B30606 ltr DIETCH: R Southern California Edison Co COTTON, 0 D San Diego Qus & Electric Co B3/05/31 DENTON, H R Office of Nuclear Reactor Regulation, Director 332pp 18854 001 24X Fiche B0-361, 83/05/31, B306150002
- 0306160275 Forwards Affidavit of 8vc for Amend 32 to FSAR MEDFORD.M.O. PEMBERTON.H R. Southern California Edison Co 83/06/14 KNIGHTUN.O W. Licensing Branch 3 App. 18860 173 24X Fiche: 50-361.83/06/14.8306160279
- P Operating license stage documents & correspondence
- 8304030062 Evaluation proposal to conduct xenon oscillation control test at 50% power vs 65% power spacified in FSAR Reduction acceptable XNIGHTON, 6 W Licensing Branch 3. 83/05/23 DIETCH, R Southern California Edison Co HOLCOMBE, J. C San Diego Qas & Electric Co 4pp 18733 204 24% Fiche 50-361,83/05/23.8306030062

- 8306070313 Discusses enhanced surveillance & maint activities of reactor trip breaters Tech Spec changes not appropriate at present time

 BASKIN, K P Southern California Edison Co 83/06/03 KNIGHTON, G W
 Licensing Branch 3 2pp 1874) 115 24X Fiche 50-361.83/06/03,
 8306070313
- B306080020 Forwards resolution of NRC comments on post-trip/restart review procedure.identifying procedure changes in response to NRC comments in Section III B 7 of SER BASKINIA P Southern California Edison Co B3/06/03 KNIGHTON, O W Licensing Branch 3 4pp 18773 001 24X Fiche 50-361.83/06/03.8306080020
- 8306090498 Requests remittance of Class III fees for 821119,1203 & 20 Tech Spec amend requests re shutdown cooling trains, turbine overspeed protection & component cooling water loop MILLER.W O License Fee Management Branch 83/06/06 DIETCH,R Southern California Edison Co 2pp 18812 062 24X Fiche 50-361.83/06/06.8306090498
- 8305090502 Ack receipt of 830128 partial payment for review of 820816 & 0930 amend applications re turbine overspeed protection sys inoperability Payment of remaining fee requested MILLER, W O License Fee Management Branch 83706/06 BASKIN, K P Southern California Edison Co (p. 18812-070-24X Fiche 50-361.83706/06.8306090502
- B306090156 Application to amend License NPF-10, extending Tech Spec surveillance interval to 18 months Approval requested by 830712
 BASKIM: K P Southern California Edison Co 83/06/07 KNIGHTON, O W Licensing Branch 3 ip 18792 316 24X Fiche 50-361, 83/06/07, B306090156
- ---B306090164 Proposed Tech Spec change extending 18-month surveillance regulrement to 831001 * Southern California Edison Co B3/06/07 2pp 18792 317 24X Fiche 50-361.83/06/07.8306090156
- 8306130386 Forwards Amend 6 to Topical Rept SCE-1-A, "GA Program," & miscellaneous documents per Final Rule 10CFR5D 54(a) Rept supercedes program described in FSAR, App D. BASKIN, K P. Southern California Edison Co. 83/06/09 MARTIN, J B Repion 5. Office of Director 3pp. 19821 271 24X Fiche 30-205;83/06/09,8306130386
- 8306140444 Confirms mods to high pressure governor valves 2 % 4 % to provide analyses of valve opening force & adequacy of mechanical clamps per 830208 commitment Analyses encl BASKIN.K P Southern California Edison Co 83706709 KNIGHTON.G W Licensing Branch 3 4pp 18838 019 24X Fiche 30-361,83706709,8306140444
- 8306140178 Revised application to amend License NPF-10 delaying until 831001 IB-month interval surveillance requirements which cannot be completed W/O extended outage MEDFORD. M D Southern California Edison Co 83/06/10 KNIGHTON. O W Licensing Branch 3 Bpc 18839 048 24X Fiche 50-361.83/06/10.8306140178
- B306140644 Submits post-accident sampling sys (PASS) progress rept as of B30601 PASS outage scheduled for B30617-0B10 Operator training course produced two qualified PASS operators License Conditions 2 C (17)1 i & (17)4 4 satisfied BASKIN.K P Southern California Edison Co 83/06/10 KNIGHTON, Q W Licensing Branch 3 3pp 18843 003 24X Fiche 30-361.83/06/10, 8306140644
- 8306240477 Forwards FR notice of consideration of issuance of amend to License NPF-7 & proposed no significant hazards consideration determination & opportunity for hearing renatural circulation tests to be conducted during startup RODD.H Licensing Branch 3 83/06/10 DIETCH-R Pacific Gas & Electric Co HOLCOMBE, J C San Diego Gas & Electric Co HOLCOMBE, J C San Diego Gas & Electric Co HOLCOMBE, J C San Diego Gas & Electric Co
- --8306240479 Notice of consideration of issuance of amend to License NPF-7 & proposed no significant hazards consideration detrmination & opportunity for hearing re natural circulation tests to be conducted during startup KNIGHTON.0 W Licensing Branch 3 83/05/31 9pp 18997 145 24X Fiche 50-361,83/06/10.8306240477

- 830.6230.478 Advises that NRR has reassessed Class III fee position on 820.514 application for amend to License NPF-10 re implementation of environ qualification program Addl fees not applicable per util 821203 ltr DIOGS.R M. License fee Hamagement Branch 83/06/16 BASKIN.R P. Bouthern California Edison Co. 1p. 18982.037 24X Fiche 50-361.83/06/16.8306230478.
- 9306300057 Forwards C-E repts, "Depressurization & DHR.Responses to NRC Guestions," Suppl 1 to "PRA of Effects of PORVs on Depressurization & DHR" & "Responses to Plant-Specific Guestions on Depressurization. ." per 820327 request BASKIN.K P Bouthern California Edison Co 83/06/22 KNIGHTON,6 W Licensing Branch 3 3pp 19117.062 24X Fiche 50-361.83/06/22, 8306300057
- --8306300125 "Degressurization & DHR.Responses to NRC Questions."
 # Combustion Engineering, Inc. CEN-239 83/06/30 390pp.
 19117-065 24X Ficks 50-361,83/06/22,8306300057
- --8306300136 Suppl 1 to CEN-239, "PRA of Effects of PDRVs on Depressurization & DHR. Ban Onofre Nuclear Generating Station, Units 2 & 3 " * Combustion Engineering, Inc. CEN-239 S01. 83/06/30 363pp. 19118 083 24X Fiche 50-361.83/06/22.8306300057
- --8306300144 "Responses to Plant-Specific Questions on Depressurization & DHR (Questions 6a.6b.12,17a.13c & 13d) "

 * Southern California Edison Co. 83/06/30 37pp 19119 088 24% Fichs 50-361,83/06/22,8306300057.
- 8306270362 Application for amend to License NPF-10, revising Tech Specs re radioactive gaseous effluent monitoring instrumentation to permit replacement of reactor coolant pump seals to maintain personnel exposure ALARA Change description and BABKIN, K.P. Bouthern California Edison Co 83/06/24 KNIGHTON, O H Licensing Branch 3 Spp 18973 188 24K Fiche 50-361,83/06/24, 8306270362.
- O Inspection reports: IE Bulletins & correspondence
- 8306160046 FOIA request, on behalf of EE Kent, for records prepared by US govt employees re Alliance for Survival T Carpenter %/or ongoing NRC investigation of facilities CARENTER.T. Orange County Alliance for Survival. 83/03/14 Office of Administration in 18893 031 24X Fiche 50-206. 83/03/14,8306160046
- 8306100009 Add1 response to FDIA request for documents dtd 820101 or sfter re BALP. Forwards App A documents Documents also available in PDR. FELTON.J H. Division of Rules and Records 83/04/11 CLARK.R. San Francisco Examiner. 3pp 19813 252 24X Fichs. 50-000, 83/04/11, 8306100009.
- --8306100014 Bubmits schedule for Region V SALP Brand meetings for 820928-830523 ENGELKEN, M. Region 5, Office of Director. 82/03/19 DENTON, H R Office of Nuclear Reactor Regulation, Director ip 18815:255 24X Fiche 50-000.83/04/11,8306100009.
- --B304100034 Discusses assignment of BALP coordinators for Reactor Operations Projects Branch facilities. Coordinators will be responsible for preparing input data used by board members in analyzing functional areas Draft note from B Miner encl STERNBERQ.D.M. Region 5. Office of Director. 82/03/24 Hegion 5. Office of Director. 11pp 16815:257 24X Fiche: 50-000.83/04/11,8304100009.
- 8306160032 Responds to FGIA request for records prepared by UB govt employees re Alliance for Survival.T Carpenter 4/or ongoing NRG investigation of facilities Forwards App A documents. Bearch for add documents in progress FELTON.J.M Division of Rules and Records 83/04/14, CARPENTER.T Orange County Alliance for Survival. 2pp. 18893.032 24X Fiche 50-206.83/04/14.8306160052
- 8306160197 Responds to FOIA request for documents re FOIA Request 82-618 Forwards App A documents. Documents 18 & 19(d) partially deleted (ref FOIA Exemption 6). FELTON.J. M Division of Rules and Records 83/04/25 GARDE, B.P. Government Accountability Project. 4pp 18893-125 24X Fiche: 50-206,83/04/25,8306160197.
- --8306160200 Forwards FOIA request Releasability determinations indicated in response litrs to requester. No action required. FELTON.J. M. Division of Rules and Records, 83/03/24. DIETCH.R. Bouthern California Edison Co. 1p 18893; 129, 24X Fichs 50-206,83/04/25,8306160197.

- ~-8306160209 Requests disclosure determination for listed documents subj to FOIA Request 82~618
 GRIMBLEY, D. H. Division of Rules and Records 83/02/07
 ALEXANDER, I. Region 5. Office of Director 2pp 18873 148 24x
 Fiche 50-206,83/04/25,8306160197
- --8306160218 Forwards documents re B Oarde FOIA request on behalf of EE Kent, for documents regarding 821120 IE rept "Special NRC Insp of San Onofre 1,2 & 3 (FOIA-82-618)" W/o ent I FORTUNA, R A Office of Investigation 83/01/24 CARR, J C Division of Rules and Records 3pp 18893 190 24X Fiche 50-206.83/04/25,8306160197
- --8306160223 Request disclosure determination for document originated by oft re FOIA Request 82-618 by noon on 830119
 CARR, J C Division of Rules and Records 83/01/12 WILSON, V Office of Nuclear Reactor Regulation, Director 2pp 18693 157 24% Fiche 50-206, 83/04/25,8306160197
- --8306160230 Submits list of Region V Ofc of Investigation File Serials 26-42. "EONOB-Allegations Re Welding of Piping by CE Kent." Case 5-82-021 Serials 1-25 previously provided in response to FOIA Request 82-528 SHACKLETON, O C Office of Investigation 89/01/03 FORTUNA.R A Office of Investigation 3pp 18893 159 24X Fiche 50-206.83/04/25.8306160197
- --8306160243 Forwards list of documents available at Region V re 8 Carde FOIA Request 82-618 on EE Kent behalf, for documents concerning 921130 IE rept "Special NRC Insp of San Onofre 1.2 & 3 "
 ALEXANDER, I Region 5, Office of Director 03/12/28 REED,C A Division of Rules and Records 3pp 18893 162 24X Fiche 50-206.83/04/25.8306160197
- --8306160253 Forwards OC Shackleton 821109 memo transmitting documents subj to FOIA Request 82-528 Review of Documents 1,2,10 & 19 by Region V recommended Confidentiality not sought by EE Kent
 FORTUNA.R A Office of Investigation 62/12/10 CARR.J C
 Division of Rules and Records 1p 18893 165 24X
 Fichs 50-206.83/04/25,8306160197
- --8306160263 Forwards list of documents responsive to FOIA Request 82-528 re EE Kent allegations concerning facilities from Oct 1980 to present. Region V not aware of allegation until Oct 1982
 SHACKLETON, O C Region 5, Office of Director, 82/11/09 FORTUNA: R.A. Office of Investigation 5pp 19893 166 24X Fiche 50-206.83/04/25.8306160197
- ~~8306160276 Requests info responsive to FOIA Request 82-528 for documents re EE Kent allegation concerning facilities from Oct 1980 to present be forwarded to Div of Rules & Records by 821116 GARR. J C Division of Rules and Records 82/11/04 KIME. C Director's Office. Office of Inspection and Enforcement ALEXANDER, I Region 5. Office of Director BOWERS: H Office of Inspector & Auditor 1p 18893 171 24X Fishe 50-206.83/04/25.8306160197
- --8306160281 Forwards list of documents responsive to FOIA Request 82-529 re EE Kent allegations concerning facilities from Oct 1980 to present, per 821104 memo Related info oncl ENGELKEN, R H Region 5, Office of Director 82/11/17. CARR.J C Division of Rules and Records 5pp 18893 174 24X Fiche 50-206.83/04/25.8306160197
- --8306160301 Forwards FOIA Request 82-618 for documents re 821130 IE ript
 "Special NRC Insp of San Onofre 1,2 & 3." Documents
 responsive to request should be forwarded to Div of Rules &
 Records by 830104
 CARR, J C Division of Rules and Records 82/12/22 FORTUNA;R
 Office of Inspector & Auditor ALEXANDER; I Region 5, Office of
 Director 1p 18893 195 24X Fiche 50-206,83/04/25,8306160197
- 8306160070 Add1 response to FUIA request for records prepared by US govt employees re Alliance for Surviva). T Carpenter %/or ongoing NRC investigation of facilities IE Insp Repts 50-206/82-31, 90-361/82-31 & 50-364/82-3 available in PDR FELTON, J M Division of Rules and Records 63/04/28 CARPENTER. T Orange County Alliance for Survival 2pp 18892 338 24X Fiche 50-206, 63/04/28, 6306160070
- 8306070240 Forwards IE Insp Repts 50-206/83-13,50-361/83-21 & 50-362/83-19 on 830401-29 No noncompliance noted, BIBNOP.I W Region 5, Offics of Director 83/05/13 PAPAY.L T Southern California Edison Co. 2pp. 18746 047 24X Fiche: 50-206, 83/05/13,8306070240

- --8304070244 IE Insp Repts 50-204/83-13,50-341/83-21 & 50-342/83-19 on B30401-29 No noncompliance noted Major areas inspected plant operations during long-term shutdown, monthly maint & surveillance activities & LERs MILLER, L , KIRSCH, D F Region 5, Office of Director 83/05/12 8pp 18746 049 24X Fiche 50-204,83/05/13,8304070240
- 8306070333 Forwards IE Insp Repts 50-206/83-08,50-361/83-17 & 50-362/83-20 on 830329-0406 No noncompliance noted 800K.H E Region 5. Office of Director 83/05/13 PAPAY, L T Bouthern California Edison Co. 2pp 18741 077 24X Fiche: 50-206, 83/05/13, 8306070333
- --8306070339 IE Insp Repts 50-206/83-08.50-361/83-17 & 50-362/83-20 on 830329-0406 No noncompliance noted Major areas inspected lab GA program, including independent confirmatory measurements re Region V mobile lab HAMDA. O H , TEMPLE. O M , CARCIA.E Region 5, Office of Director 83/05/12 10pp 18741 079 24% Fiche 50-206.83/05/13.8306070333
- 8306070361 Forwards IE Insp Repts 50-361/03-22 & 50-362/83-21 on 830326-0422 No noncompliance noted BISHOP, T W Region 5, Office of Director 83/05/13 PAPAY, L T Southern California Edison Co 2pp 18742 110 24X Fiche: 50-361, 83/05/13, 8306070361
- --8306070368 IE Insp Repts 50-361/83-22 & 50-362/83-21 on 830326-0422.No noncompliance noted Major areas inspected operational safety verification & LER review PATE.R.J. KRRSCH.DF Region 5. Office of Director 83/05/12 App 18742 112 24X Fiche 50-361,83/05/13.8306070361
- 8304220139 Ack receipt of 830502 ltr & full payment of civil penalty AXELRAD. J A Director's Office, Office of Inspection and Enforcement 83/05/13 PAPAY.L T Southern California Edison Co 2pp. 18737-350. 24X Fiche 80-361.83/05/13.8306220139.
- 8304070251 Forwards IE Insp Repts 50-204/83-10,50-361/83-19 & 50-362/83-17 on 830411-27 & notice of violation BISHOP.T M. Region 5, Office of Director 83/05/16 PAPAY, L T Southern California Edison Co. 2pp 18746 088 24X Fiche 50-206,83/05/16,8306070251
- --8304070255 Notice of violation from insp on B30411-27 KIRBCH, D F Region 5, Office of Director. B3/05/14 2pp 18744 090 24X Fiche 50-206,83/05/14,8306070251
- --8306070261 IE Insp Repts 50-206/83-10,50-361/83-19 & 50-362/83-17 on 830411-27 Noncompliance noted failure to install fully 8-h emergency lighting units in access/egress routes SCONN.K M. KIRSCH.D F Region 5. Office of Director. 63/05/11 11pp 18746-092 24X Fiche 50-206.83/05/16,8306070251
- 8304010157 Ack receipt of 830518 ltr informing NRC of steps taken to correct vialations noted in IE Inap Repts 50-361/83-14 & 50-362/83-14 RODK, HE Region 5. Office of Director. 83/05/25 PAPAY, L. T Southern California Edison Co. ip 18673, 046. 24X Fiche. 50-361, 83/05/25, 8306010159
- --8305010164 Responds to NRC 830418 ltr re violations noted in IE Insp Repts 50-361/83-14 & 50-362/83-14 Corrective actions release procedures revised, requiring observance of monitor response & dwaign change package ALARA review criteria strengthened, FOGARTY,D J Southern California Edison Co 83/05/18 MARTIN,J B Region 5, Office of Director 6pp 18673 047, 24X Fiche:50-361,83/05/25,8306010159.
- B305ii0458 IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in Well Logging Device" Svc list encl, TAYLOR.J.M Division of Bafeguards & Inspection Programs (Post 830103). 83/05/24 Consolidated Edison Co of New York, Inc. 125pp 18831 043 24% Fiche 50-000,83/05/26.8305110458
- 8305110460 IE Info Notice 83-34, "Event Notification Info Worksheet"
 Svc list encl
 JORDANIE L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/05/26 Consolidated Edison Co of New
 York, Inc. 115pp, 18732 085 24X Fiche 50-000, 83/05/26, 8305110460.
- 8305110461 IE Info Notice 83-35, "Fuel Mayement W/Control Rods Hithdrawn at BHRs " 8vc list encl.

 JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/31 Consolidated Edison Co. of New York, Inc 116pp 18732 208, 24X Fichs 50-000,83/05/31,8305110461

- 8304070D29 Responds to IE Builetin 83-03, "Check Valve Failures in Raw Water Cooling 8ys on Diesel Generator "Raw water cooling sys & check valves not utilized in diesel generator at facilities
 HAYNES, J 0 Southern California Edison Co 83/06/03 MARTIN, J B Region 5, Office of Director ip 18739 329 24X
 Fiche 50-361,83/06/03,8304070029
- 8305110464 IE Info Notice 83-36, "Impact of Security Practices on Bafe Operations" Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/07 Consolidated Edison Co of New York, Inc 119pp 18830 280 24X Fiche 50-000,83/06/09,8305110464.
- 8305110470 IE Info Notice 83-38, "Defective Heat Sink Adhesive & Seismically Induced Chatter in Relays Within Printed Circuit Cards "Syc list encl JORDAN,E. L. Division of Emergency Preparedness & Engineering Response (Post 830103), 83/04/13 Consolidated Edison Co. of New York Inc. 118pp. 18920 225 24X Fiche 50-000,83/04/13,8305110470.
- 8304070010 IE Info Notice 83-37. "Transformer Failure Resulting From Degraded Internal Connection Cables." Evo list encl.
 JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83706/13, Consolidated Edison Co. of New York, Inc 243pp 18921-001 24X Fichs 50-000,83706/13,8306070010
- B30428047B Forwards IE Insp Repts 50-341/83-24 & 50-342/83-23 on 830425-0402 No noncompliance noted BISHOP, T W Region 5. Office of Director. B3/04/15. PAPAY, L T. Southern California Edison Co 2pp 19017 295 24X Fiche: 50-341,83/04/15,8304280498
- --B3062B05ii IE Imsp Repts 50-961/83-24 & 50-362/83-23 on 830428-0602 No noncompliance noted Major areas inspected startup test programs, including operational safety verification, power ascension testing, plant trips & LER review PATE, R J. CHAFFEE, A E , STEMART, J P. Region 5, Office of Director 83/06/14 7pp 19017 297 24X Fiche 50-361,83/06/15,8306280498
- 8306200378 Ack receipt of 830516 ltr informing NRC of steps taken to correct violations noted in IE lnsp Repts 50-361/83-12 k 50-362/83-12. Undervoltage coil mechanism important Violation A cited properly MARTIN, J. B. Region 5, Office of Director 83/06/17, FOGARTY, D. J. Southern California Edison Co. 3pp 18899'087, 24X Fiche: 50-361, 83/06/17, 8306200378,
- --83062003B1 Responds to NRC 830414 ltr re violations noted in IE Insp Repts 80-361/83-13 & 50-362/83-12 ltem A in notice of violation re surveillance testing of reactor trip breaker unwarranted, FIOARTY.D J Southern California Edison Co 83/05/16 MARTIN.J B Region 5, Office of Director 7pp 18879 090 24X Fichs. 50-361, 83/06/17, 8306200378
- 830.6280546 Forwards IE Insp Repts 50-361/83-15 k 50-362/83-13 on 830323-0602 k notice of violation 818HOP.T.W Region 5. Office of Director 83/06/17. PAPAY, L.T. Southern California Edison Co Spp 19018 109 24X Fiche: 50-361.83/06/17.8306280546
- --8306280551 Notice of violation from insp on 830323-0602, KIRBCH,D,F. Region 5, Office of Director 83/06/17 7pp. 19018 112 24X Fiche 50-361,83/06/17,8304280546,
- --8306280561 IE Insp Repts 50-361/83-15 % 50-362/83-13 on 830323-0602. Noncompliance noted inadequate valve sys lineup procedures, failure to maintain certain fire protection valves locked open & alterations of official records. CHAFFEE.A. 8TEMART.P. KIRSCH.D F. Region 5. Office of Director. 83/06/16 lipp 19018:119. 24X Fichs: 50-361,83/06/17,8306280546.
- 8306230211 Responds to IE Bullatin 83-05, "ABME Nuclear Code Pumps & Bpare Parts Mfg by Hayward Tyler Pump Co " No subj pumps or spare parts in use or planned for use at facility HAYNES, J. G. Southern California Edison Co. 83/06/20 MARTIN, J. B. Region 5. Office of Director. ip 18746:348, 24% Fiche: 50-361,83/06/20,8306230211
- 8308110475 IE Info Notice 83-40, "Need to Environmentally Qualify Epoxy Grouts & Bealers." Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/22. Consolidated Edison Co. of New York, Inc. 115pp. 19021:179 24X Fiche: 50-000.83/06/22.8305110475.
- 8305110477 IE Info Notice 83-41, "Actuation of Fire Suppression Sys Causing Inoperability of Safety-Related Equipment," Syc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103), 83/06/22 Consolidated Edison Co. of New York, Inc. 120pp. 18997:007 24X Fithe:50-000.83/06/22,8305110477.

- B303110479 IE Infa Notice 83-42, "Reactor Mode Switch Malfunctions "
 Svc list and J
 JORDAN: EL Division of Emergency Preparedness & Engineering J
 Response (Post 830103) B3/06/23. Consolidated Edison Co of New York, Inc. 1169p 18996 242 24X Fiche 30-000,83/06/23,8305110479
- 8305110483 IE Info Notice 83-43, "Improper Sattings of Intermediate Renge (IR) High Flux Trip Setpoints " Svc list encl JORDAN: E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/24 Consolidated Edison Co of New York: Inc 116pp 19046 297 24X Fiche 50-000,83/06/24,8305110483
- R Periodic operating reports & related correspondence
- B306160489 Monthly operating repts for Apr 1983 M/B30513 ltr MAYMEATHER.L. RAY, H B Bouthern California Edison Co B3/05/13 Management Information Branch 12pp 18864 139 24X Fichs 50-361.83/05/13.8306160489
- 8 Reportable occurrences. LERs & related correspondence
- 830&100054 LER 83-030/03k-0 on 830406, CREACUB train B declared insparable for investigation of ground on fan motor HE-419 Limiting condition for operation invoked Caused by oily residue on windings Grease fittings removed M/830506 ltr RAY, H S Southern California Edison Co 83/05/06 MARTIN, J B Region 5, Office of Director 4pp 18802 119 24X Fiche 50-361, B3/05/06, 8306100054
- B30&10009B LER B3-040/01T-0 on B30507, containment isolation valve MU-099 (safety injection drain to refueling water storage tank) found open Caused by foreman initiating incomplete startup procedures W/830523 ltr
 RAY. H B Southern Cellifornia Edison Co 83/05/23 MARTIN, J B Region 5, Office of Director App 18802 262 24X
 Fiche 50-361,83/05/23.8306100098
- 8306100069 LER 83-048/03L-0 on 830424, pilot flames of trains A & B toric gas isolation sys butane/propane monitors experienced persistant flame-out Caused by high impurity level in replacement hydrogen gas Bottle replaced M/830524 ltr RAY.H B Southern California Edison Co 83/05/24 HARTIN.J B Region 5. Office of Director 3pp 18802 178 24X Fiche 50-361,83/05/24,8306100069
- 8306100072 RO on B30506.NFPA 72D std not mat, due to improper design change which eliminated ability to differentiate between trouble & alarm signals Design change package will be prepared by 830615 to modify circuitry.

 RAY. H S Southern California Edison Co 83/05/24 MARTIN. J B Region 5. Office of Director 2pp 18802 181 24X

 Ficha 50-361,83/05/24.8306100072
- 830&100115 LER 83-047/03L-0 on 830427, toxic gas isolation sys train A declared inoperable & subsequent insp revealed battery discharged & alarm function defeated Caused by discharged battery supply & missligned setpoint M/805027 ltr RAY.H B Southern California Edison Co 83/05/27 MARTIN, J. B Region 5. Office of Director App 18802 023 24X Fiche 50-361.83/05/27,8306100115
- B306140684 LER 83-041/07L-0 on 830429, documentation could not be located indicating operability testing, including testing required by inservice insp & testing gragmam, Caused by inservice insp & testing gragmam, Caused by inservice inspection #/#300529 itm RAY.H. B. Bouthern California Edison Co 83/05/29 MARTIN, J B Region 5. Office of Director 4pp 18842-062 24X
- 8306140039 LER 83-049/03L-0 on B30429, emergency chiller E-336 (Train A) failed to start following invalid TOTS Caused by sixalignment of supply breater Breaker aligned M/830601 ltr KAY.H B Southern California Edison Co B3/06/01 HARTIN, J B Region 5, Office of Director. App 18838 253 24X Fithe 50-361,83/06/01,8306140039.
- 8306440250 LER 83-051/03L-0 on B30501.w/Unit 2 in Mode 3 & Unit 3 in Mode 5, control room complex isolation damper 2/3HV9702 did not close as required Cause unknown Physical insp of relays, contacts & wiring will be conducted W/B30601 ltr RAY.H B Southern California Edison Co B3/06/01 MARTIN, J B Region 5 Office of Director 3pp 18833 014 24X
- 8306140007 LER 83-045/03L-0 on 830504, while working on plant protection ays Channel Areactor trip circuit breaker TCB-1 tripped open, rendering channel inoperable Caused by loose cable terminal block screws Screws tightened W/830603 ltr RAY.H. B. Southern California Edison Co. 83/06/03 MARYIN.J. 8 Region 5. Office of Director 7pp. 16838 244 24X

- 8306210113 LER 83-046/03L-0 on 830506, reactor coolent cold leg temp it found outside Limiting Condition for Operation 3.2 & Caused by personnel failure to properly monitor & control it it restored to limits W/830606 ltr RAY.H B Southern California Edison Co. 83/06/06 MARTIN.; D Region 5. Office of Director App. 18915-076 PAX Fiche 50-361,83/06/06.8306210113
- 8306210352 LER 83-060/01T-0 on 830529, hourly instead of continuous fire watch established & backup fire suppression equipment in place until Zone 5 deluge water spray ays returned to ave Caused by inadequate procedures W/830606 ltr RAY,H B Southern California Edison Co 83/06/06 MARTIN, J D Region 5, Office of Director 4pp 18914 018 24X Fiche 50-361,83/06/06,8306210352
- 8306230266 LER 83-051/03X-0 on 830501; contol room complex isolation dumper 2/3HV9702 did not close as required on spurious TGIU Caused by dirt on reset relay Relays cleaned M/830610 ltr RAY.H B Southern California Edison Co 83/06/10 MARTIN, J & Region 5, Office of Director 3pp 18945 083 2AX Ficha 50-361,83/06/10,8306230266
- 8304280267 LER 83-058/03L-O on B30514, failure of core protection calculator Channel B indicated by lights on DNDR trip & linear power density trip & alarm Caused by multi-purpose acquisition & control sys Error Code 10 W/B30613 ltr RAYH B, Bouthern California Edison Co. B3/06/13 MARTIN, J D Region 5, Office of Director, App 17014 102 24X Fichs 50-361, 63/06/13, 6306280267
- 8306280390 LER 83-052/03L-0 on 830524, purgs/vent stack radiation monitor 2RI-7865 failed Caused by failure of crystal oscillator & input/output board in microprocessor Crystal oscillator & board replaced W/830614 ltr.
 RAY.H B . RAY.H B Southern California Edison Co 83/06/14 MARTIN.J B . Region 5. Office of Director 3PP 19001 263 J4X Fichs 50-361.83/06/14.8306280350
- 8305280252 LER 83-056/03L-0 on 830516, w/plant in Mode I, core protection calculator (CPC) D failed & placed in bypass condition Caused by degraded power supply, probably due to CPC cabinet cooling fan bearing failure W/830615 ltr
 RAY.H B Bouthern California Edison Co 83/06/19, MARTIN, J H Region 5, Office of Director 4pp 17015-025 24X
 Fiche 50-361,83/06/15,8306280252
- 8306280273 LER 83-050/03L-0 on 830519, during surveillance testing, core protection calculator channel C declared inoperable due to automatic restarts exceeding number allowed for 12 h period Caused by interniteant losses of power. W/830615 ltr RAY.H B Southern California Edison Co 83/06/15 MARTIN, J B Region S, Office of Director 4pp. 19014 231 24X Fiche 50-361,83/06/15,8306280273
- 8306280410 LER 83-044/01T-0 on 830210, review of circuitry associated w/Kirk Key interlock operation of HPSI pumps 2P017 & 2P018 identified electrical continuity within breaker could result in simultaneous actuation of pumps W/830615 ltr RAY.H B Southern California Edison Co 83/06/15 MARTIN.J # Region 5, Office of Director 3pp 19001-332 24X Fichs 30-361,83/06/15,8306280410
- 8306230378 PND-V-83-024 on 830616, while increasing condenser vacuum & resetting trip setpoint, low vacuum tubine trip occurred followed by reactor trip from 100% power. Caused by low primary plant pressure for fine from 100% power. Caused by low ECKHARDT, J H. KIRSCH, D F. Region 5, Office of Director 03/06/16 ip 18943 075 24% Fichs. 30-361.83/06/16.8306230398.
- U. Congressional/Executive Correspondence
- 830&160052 Responds to FOIA request for records prepared by US govt amployees re Alliance for Survival T Carpenter &/or ongoing NRC investigation of facilities. Forwards App A documents Bearch for addl documents in progress FELTON.J M Division of Rules and Records 83/04/14 CARPENIER. To Orange County Alliance for Survival 2pp 18893 032 24% Fiche 50-206.83/04/14.8306160052.
- --82iii40565 Forwards Community Energy Action Natwork 021018 ltr & Los Angales Times article re potential problem w/welds at facilities (RANGTON.A Senate. 62/10/29 KRAMMERER, C. Office of Congressional Affairs 3pp. 18893, 056 24X Fiche: 50-206, 83/04/14,8304160052.

- DOCKET 50-362 SAN ONOFRE NUCLEAR STATION, UNIT 3

 F Security, medical, emergency & fire protection plans
- 8306070251 Forwards IE Insp Repts 50-206/B3-10.50-361/B3-19 & 50-362/B3-17 on 830411-27 & notice of violation BISHOP.T W Region 5. Office of Director 83/05/16 PAPAY.L.T Southern California Edison Co. 2pp 18746 088 24X Fichs 50-206.83/05/16.8306070251
- --B306070255 Notice of violation from insp on 830411-27 KIRBCH D F Region 5, Office of Director 83/05/16 2p 18746 090 24X Fiche 50-206,83/05/16,8306070251
- --8304070261 IE Insp Repts 50-206/83-10,50-341/83-19 & 50-362/83-17 on 830411-27 Noncompliance noted failure to install fully 8-6 margency lighting units in access/egress routes 8COBN.K M. Region 5, Office of Director 83/05/11 lipp 16746 092 24% Fichs 50-206/83/05/16,8306070251
- 8306160011 Advises that 830323 Rev 9 to physical security plan consistent H/10CFR73 21 provisions & does not decrease plan effectiveness Changes acceptable KFIGHTUN, C. H. Licensing Branch 3 83/06/06 DIETCH, R. Southern California Edison Co. HOLCOMBE San Diego Cas & Electric Co. 3pp 18872 148 24% Fiche 50-206, 83/06/06, 8306160011
- 6306220291 Responds to 830406 ltr re changes to physical security plan Changes consistent w/locr830 54(p) & do not decrease effectiveness of plan MNIGHTUN.G W. Licensing Branch 3 83/06/10 DIETCH.R. Southern California Edison Co. HOLCOMBE.J.C. San Diego Gas & Electric Co. 3pp 18740 344 24X Fiche 50-206.83/06/10.8306220291
- G306220294 Responds to 830323 ltr re Rev 2 to guard training & qualification plan Changes consistent w/10CFR50 54(p) provisions & do not decrease effectiveness of plan KNIGHTON, 9 H. Licensing Branch 3 83/06/10 DIETCH, R. Bouthern Callfornia Edison Co. HOLCOMBE, J. C. Ban Diego Qas & Electric Co. 3pp 18940 312 24X Fiche 50-206,83/06/10,8306220294
- GJ06230520 Responds to GJ0427 ltr re temporary changes to physical security plan Changes consistent w/10CFR50 54(p) requirements & acceptable MNIOHTON,0 W Licensing Branch 3 83/06/10 DIETCH,R Southern California Edison Co
- 8306230455 Ack receipt & provides evaluation of changes to emergency plan implementing procedures submitted in 821029 & 831103
 1 the Changes do not decrease effectiveness of emergency response planning.
 NORDERHAUO, L. R. Division of Radiological Bafety & Bafeguards
 Program 83/06/20 BABKIN, K.P. Bouthern California Edison Co. 1p. 18941 360 24X Fiche 50-206,83/06/20,8306230455

9 Adjudicatory correspondence

- B306080195 Comments re offeite medical avcs, objections to applicant motion to augment record & request for hearing & proposed licensing condition Adequate arrangements for medical avcs not met. Further hearings required MCCLUNG.C E Affiliation Unknown MCCLUNG.C E Flemming. Anderson, McClung & Finch. B3/06/04 Atomic Safety and Licensing Board Panel 7pg 18772 251 24% Fichs. 50-361,83/06/06,8306080195
- 8304080214 Response to util 830514 motion to augment record, position re Commission Memorandum & Order CLI-83-10 on offsite medical syrs & proposed findings of fact Supports motion & proposed findings.

 VOOLER, D. H. Hearing Branch 2 83/04/06 Atomic Safety and Licensing Board Panel 7pp 18771-101 24X Fiche 50-361,83/06/06,8304080214
- --6306080216 Affidavit of DB Matthews that util ensured appropriate provisions for medical sycs to general public traumatically injured or contaminated during emergency Prof qualifications & Certificate of Byc encl.
 NATTHEND, D B. Section B (Pre 820201) 83/06/06 7pp 18771 108.
 24X Fishe 50-361.83/06/06.8306080214
- B306080157 Order extending time until B30614 for Commission to act to review ALAB-717
 CHILK, B. J. Office of the Becretary of the Commission B3/06/07
 Commissioners. ip 18772:174. 24X Fiche 50-361,83/06/07,

- 8306160639 Order extending time until 830621 for Commission to act to review ALAB-717 CHILK: J Office of the Secretary of the Commission 83/06/14 Commissioners 1p 18866 034 24X Fiche 50-361,83/06/14, 8306160639
- 8306210288 Response opposing QUARD & Carstens 830606 joint request for hearing on medical sycs issues Issue of sufficiency of medical resources already litigated Hearing unnecessary to obtain authentication Centificate of Syc encl CHANDLER.L. J. Hearing Branch 2 83/06/17 Atomic Safety and Licensing Board Panel Spp 18915 011 24X Fiche 50-261.83/06/17, 8306210288
- 8306220084 Reply to intervenor 830604 briefs on status of medical sycs issue Further hearings unjustified since Commission already ruled on adequacy of ensite medical sycs Declaration of Syc encl
 PIGOTT, D R Southern California Edison Co PIGOTT, D R. Orrick,
 Herrington & Sutcliffe 83/06/17 Spp 18727 173 24X
 Fiche 50-361.83/06/17.8306220084
- 8305220127 Affidavit of FK Massey supporting util 830516 motion to augment record, authenticating documents as portions of Orange & San Diego County emergency plans.
 MASSEY, F.K. Bouthern California Edison Co. 83/06/17 5pp
- J Insurance & indemnity information
- B306270172 Forwards Endorsements 95,94 & 97 to NELIA Policy NF-146, & Endorsements 63,64 & 85 to MAELU Policy MF-38 & Endorsement 38 to NELIA Policy NB-882 ROCCO. J. Southern California Edison Co. B3/06/13 DINIT. I Antitrust & Economic enalysis Brench (Utility Finance) 8pp 18991 349. 24X Fichs. 50-204.83/06/13.8306270172
- K Utility Final Bafety Analysis Report (FSAR) & amends
- 8306150002 Amend 32 to FBAR W/830606 ltr
 DIETCH.R Bouthern California Edison Co COTTON, O.D. San Diego Pas
 & Electric Co 83/05/31 DENTON, HR Office of Nuclear Reactor
 Regulation, Director 332pp 18854 GO1 24X Fiche 80-361.83/05/31,
 8306150002
- 8306160275 Forwards Affidavit of Svc for Amend 32 to FBAR MEDFORD, N D , PEMBERTON, N R Southern California Edison Co 83/06/14 KNIGHTON, O W Licensing Branch 3 4pp 18860 173, 24X Fichs 50-361, 83/06/14, 8306160275
- P Operating license stage documents & correspondence
- 8306070313 Discusses enhanced surveillance & maint activities of reactor trip breakers Tech Spec changes not appropriate at present time

 BASKIN, K P Southern California Edison Co 83/06/03 KNIGHTON, G W, Licensing Branch 3 2pp 18741-115 24X Fiche 50-361,83/06/03, 8306070313
- 8304080020 Forwards resolution of NRC comments on post-trip/restart review procedure, identifying procedure changes in response to NRC comments in Bection III 8 7 of SER.

 BASKIN.K.P Southern California Edison Co 83/04/03. KNIGHTON.G.;
 Licensing Branch 3 App 18773 001 24X Fiche.50-361.83/04/03,
 8304080020
- 830.6090498 Requests remittance of Class III fees for 821119,1203 & 20 Tech Spec amend requests resistance cooling trains, turbine overspeed profesction & component cooling water loop MILLER, W. U. Litemse Fee Hanagement Branch. 83/06/06 DIETCH, R. Southern California Edison Co. 2pp. 19812-062 24X Fiche 50-361,83/06/06.8306090498
- B306i30386 Forwards Amend 6 to Topical Rept SCE-1-A, "GA Program," & miscellaneous documents per Final Rule 10CFR30 54(a) Rept supercedes program described in F8AR, App B. BABKIN, K.P. Southern California Edison Co. B3/06/09. MARTIN, J.B. Region 5. Office of Director 3pp 16921:271 24X Fiche 50-206,83/06/09.8308130386.
- --8306130392 Amend 6 to Topical Rept 80E-1-A, "GA Program." * Bouthern California Edison Co. 90E-1-A A06 83/04/30, 200pp. 16821:274 24X Fithe 50-206.83/06/09, 8306130386
- 8304140444 Submits post-accident sampling sys (PASS) progress rept as of 830401 PASS outage achaduled for 830417-0810. Operator training course produced two qualified PASS operators License Conditions 2 C. (1911. 1 & (17)d. 4 satisfied BASKIN. K P Southern California Edison Co. 83/06/10 KNIGHTON. C. W Licensing Branch 3 3pp. 18843-003. 24X Fiche 50-341.83/06/10, 8306140444.

- 8306300057 Forwards C-E repts: "Depressurization & DHR, Responses to NRC Obestions." Suppl I to "PRA of Effects of PORVs on Depressurization & DHR" & "Responses to Plant-Specific Questions on Depressurization." per 820327 request BASKIN, K P Southern California Edison Co. 83/06/22 KNIGHTON, G W Licensing Branch 3 3pp 19117-062 24X Fiche: 50-361, 83/06/22, 830630057
- --8306300136 Suppl 1 to CEN-239. "PRA of Effects of PDRVs on Depressurization & DHR: Ban Dooffe Nuclear Generating Station. Units 2 & 3."

 Combustion Engineering, Inc. CEN-239 S01. 83/06/30 363pp 19118.083 24X Fiche 50-361,63/06/22,8306300087
- --8306300144 "Responses to Plant-Specific Questions on Depressurization & DHR (Gyestions &s.cb.12, 12s, 12c & 13s) "
 * Southern California Edison Co 83/06/30 37pp 19119.088
 24x Picher 50-361, 83/06/22, 8306300057.
- G Inspection reports, IE Bulletins & correspondence
- 830&i60046 FOIA request on behalf of EE Kent for records prepared by US govt employees re Alliance for Survival T Carpenter t/or ongoing NRC investigation of facilities CARFENTER. T Orange County Alliance for Survival 82/03/14 Office of Administration ip 18873.03; 24x Fiche: 50-206.83/03/14.8306160046
- 8306100009 Add1 response to FOIA request for documents old 820101 or after re BALP Forwards App A documents Bocuments also evailable in FDR.
 FELTON, J M Division of Rules and Records 83/04/11 CLARK, R Sar Francisco Examiner. Spp. 18815-232 24X Fiche 50-000.83/04/11, 8306100009
- --830A100014 Bubmits schedule for Region V SALP Board meetings for 820728-830523. ENGELKEN, R H Region 5. Office of Director. 82/03/19 DENTON. H. R Office of Nuclear Reactor Regulation. Director ip 18815 255. 24X Fiche 50-000,83/04/11,8306100009.
- --B306100036 Discusses assignment of BALP coordinators for Reactor Operations Projects Branch facilities Coordinators will be responsible for preparing imput data used by board members in analyzing functional areas Draft note from B Miner encl STERNBERO, D.M. Region 5, Office of Director B2/03/24, Region 5, Office of Director B2/03/24, Fiche: 50-000, B3/04/11, B306100007
- 8306160197 Responds to FOIA request for documents re FOIA Request 82-618 Forwards App A documents. Documents 18 & 19(d) partially deleted (ref FOIA Exemption 6) FELTON, J. M. Division of Rules and Records 83/04/25 QARDE, B P Overnment Accountability Project App. 18873-125 24X Fichs 50-206,83/04/25,8306160197
- --B306160200 Forwards FOIA request Releasability determinations indicated in response ltrs to requester No action required FELTON, J M Division of Rules and Records 83/03/24 DIETCH, R. Southern California Edison Co. 1p. 18893 127 24X Fichs. 50-204, 83/04/25, 8306160197.
- ~-8306160207 Requests disclosure determination for listed documents subj to FOIA Request 82-618
 ORIMBLEV, D. H. Division of Rules and Records, 83/02/07
 ALEXANDER, I. Region 5, Office of Director 2pp. 18693-148, 24x
 Fiche, 50-206, 83/04/25, 8306160197,
- --8306160218 Forwards documents re B Garde FOIA request on behalf of EE Kentifor documents regarding 821120 IE rept "Bpecial NRC Insp of Ban Onofre 1:2 & 3 (FOIA-82-618)" M/o encl FORTUNA:R.A Office of Investigation, 83/01/24, CARR.J.C. Division of Rules and Records, 3pp. 18893 150 24% Fiche. 50-206,83/04/25,8306160197.
- --8306160223 Request disclosure determination for document originated by ofc re FOIA Request 82-618 by noon 830119.

 CARR.J.C Division of Mules and Records. 83/01/12 WILBON, V. Office of Nuclear Reactor Regulation, Director. 2pp 18893:157 24% Fiche: 50-206, 83/04/25, 8306160197
- --830A160230 Bubmits list of Region V Of: of Investigation File Serials 24-42. *80N0B-Allegations Re: Helding of Piping by EE Kent. *Case 5-82-021. Serials 1-25 previously provided in response to FDIA Request 82-528. SHACKLETON. O. C. Office of Investigation. 83/01/03. FORTUNA, R. A. Office of Investigation. 36p. 18993-189. 24X Fiche: 50-206, 83/04/25, 8304160197.

- --8306160243 Forwards list of documents available at Region V re B Cards
 FOIA Request 82-618 on EE Kent behalf, for documents
 concerning 821120 IE rept "Special NRC Insp of Ban Onefre
 1,2 & 3."
 ALEXANDER, I Region 5, Office of Director 83/12/28 REED.C A
 Division of Rules and Records 3pp 18893 162 24X
 Fishe 50-206.83/04/25,8306160197
- ~-8306160253 Forwards OC Shackleton 821109 memo transmitting documents subj to FOIA Request 82-528 Review of Documents 1.2.10 & 19 by Region V recommended Confidentiality not sought by EE Kent FORTUNA.R A Office of Investigation 82/12/10 CARR, J C Division of Rules and Records ip 18893 165 24X Fiche 50-206,83/04/25,8306160197
- --8306160263 Forwards list of documents responsive to FOIA Request 82-528 re EE Kent allegations concerning facilities from Oct 1980 to present Region V not aware of allegation until Oct 1982 SHACKLETON, O C Region 5, Office of Director 82/11/09 FORTUNA, R A Office of Investigation 5pp 19893, 166 24% Fiche 50-206,63/04/25,8306160197
- --8306160276 Requests info responsive to FDIA Request 82-538 for documents re EC Kent allegations concerning facilities from Oct 1980 to present be forwarded to Div of Rules Records by 821116

 CARR. J C Division of Rules and Records 82/11/04. KIME. C Director's Office. Office of Inspection and Enforcement. ip 18893 171 24X Fiche 50-206.83/04/25.8306160197
- --8306160281 Forwards list of documents responsive to FOIA Request 82-508 re EE Kent allegations concerning facilities from Oct 1980 to present, per B2/104 memo Related info encl ENGELKEN, R, H Region 5. Office of Director 82/11/17 CARR, J C Division of Rules and Records 5pp 18893 174 24X Fiche 50-206,83/04/25,8306160197
- --8306160301 Forwards FOIA Request 82-618 for documents re 821130 IE rept
 "Special NRC Insp of San Onofre 1,2 & 3 " Documents
 responsive to request should be forwarded to Div of Rules &
 Records by 830104.
 CARR.J.C. Division of Rules and Records 82/12/22 FORTUMA.R
 Office of Inspector & Auditor 1p. 18893 195, 24X
 Fiche 50-206.83/04/25.8306160197
- 830.6160070 Addl response to FOIA request for records prepared by US govt employees re Alliance for Survival, T Carpenter %/or ongoing NRC investigation of facilities. IE Insp Repts 50-206/82-31.50-361/82-31 & 50-362/82-27 available in PDR FELTON, J. M. Division of Rules and Records 63/04/28 CARPENTER.T. Orange County Alliance for Survival, 2pp 18892 338 24% Fiche. 50-206. 63/04/28, 8306160070
- 830A070240 Forwards IE Insp Repts 50-206/83-13,50-361/83-21 & 50-362/83-19 on 830401-29, No noncompliance noted BIBHOP, T W Region 5, Office of Director 83/05/13 PAPAY, L T Bouthern California Edison Co. 2pp. 18746 047 24X Fiche 50-206,83/05/13,8306070240
- --8306070244 IE Insp Repts 50-206/83-13,50-361/83-21 & 50-362/83-19 on 830401-29, No noncompliance noted Major areas inspected plant operations during long-term shutdown, monthly maint & surveillance activities & LERs.

 MILLER, L , KIRSCH, D F Region 5, Office of Director 83/05/12

 8pp 18746 049 24X Fiche 50-206,83/05/13,8306070240
- 8304070333 Forwards IE Insp Repts 50-206/83-08, 50-361/83-17 & 50-362/83-20 on 830327-0406 No noncompliance noted BOOK, H.E. Region 5, Office of Director 83/05/13 PAPAY, L T. Bouthern California Edison Co. 2pp 18741; 077 24X Fiche, 50-206, 83/05/13, 8306070333.
- --8306070339 IE Inmp Repts 50-206/83-08.50-361/83-17 & 50-362/83-20 on 8309329-0406 No noncompliance noted Major areas inspected lab GA program, including independent confirmatory measurements re Region V mobile lab. HAMDA.Q.H , TEMPLE.Q.H , OARCIA.E Region 5, Office of Director 83/05/12 10pp. 18741:079 24X Fiche:50-206.83/05/13.8306070333
- 8306070361 Forwards IE Insp Repts 50-361/83-22 & 50-362/83-21 on 830326-0422 No noncompliance noted, 818H0P.T W Region 5, Office of Director, 83/05/13, PAPAY.L T. 80uthern California Edison Co. 2pp. 18742-110, 24X Fiche 50-361,83/05/13,8306070361
- --8306070368 IE Insp Regts 50-361/83-22 & 50-362/83-21 on 830326-0422. No noncompliance noted Major areas inspected operational safety verification & LER review PATE, R. J. KIRSCH, D. F. Region 5, Office of Director. 83/05/12 4pp. 18742:112 24X Fiche. 50-361, 83/05/13, 8306070361.

- B306070251 Forwards IE Insp Repts 50~206/B3-10, 50~361/B3-19 & 50~362/B3-17 on 830411-27 & notice of violation BIBHOP, T W Region 5, Office of Director 83/05/16 PAPAY, L T Sauthern California Edison Co 2pp 18746 088 24X Fiche 50-206,83/05/16,8306070251
- --8306070255 Notice of violation from insp on 830411-27 KIRSCH F Rejon 5. Office of Director 83705/14 2pp 18746 090 24X Fiche 50-204.83/05/14.8304070251
- --8306070261 IE Insp Repts 50-206/83-10,50-361/83-17 & 50-362/83-17 on 830411-27 Noncompilance noted failure to install fully 8-h emergency lighting units in access/egress routes SCONN.K M . KIRBCH.D F Region 5, Office of Director 83/05/11 11pp 18746 092 24X Fiche 50-206.83/05/16,8306070251
- 830A010159 Ack receipt of 830518 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 30-361/83-14 & 50-362/83-14 BCOK.H.E Region 5, Office of Director 83/05/25 PAPAY,L T Bouthern California Edison Co. lp 18673 046 24X Fiche 50-361,83/05/25,8306010159
- --B304010144 Responds to NRC 830418 ltr re violations noted in IE Insp Repts 50-361/83-14 & 50-361/83-14 Corrective actions release grocedures revised, requiring observance of monitor response & design change package ALARA review criteria strengthened, FOGARTY, D J Southern California Edison Co 83/05/18 MARTIN.J B Region 5, Office of Director App 18673 047 24X Fichs 50-361,83/05/25,8304010159
- 8303110458 IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in Well Logging Device" Svc list encl
 TAYLOR. J. M Division of Safeguards & Inspection Programs (Post
 830103). 8306726. Consolidated Edison Co of New York, Inc
 125pp 18831-043 24X Fiche, 50-000, 83/05/26, 8308110458
- 8305110460 IE Info Notice 83-34, "Event Notification Info Worksheet" Svc list encl.
 JORDAN E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26. Consolidated Edison Co of New York, Inc 115pp 18732-085 24X Fiche 50-000,83/05/26,8305110460
- 8305110461 lE Info Notice 83-35, "Fuel Movement W/Control Rods Withdrawn at BWRs." Evc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/31. Consolidated Edison Co. of New York, Inc. 114pp 18732-208 24X Fiche 50-000,83/05/31,8305110461
- 8306070029 Responds to IE Bulletin 83-09, "Check Valve Failures in Raw Hater Cooling Bys on Diesel Generator," Raw water cooling sys & check valves not utilized in diesel generator at facilities HAYNES, J @ Bouthern California Edison Co 83/06/03 MARTIN, J B Region 5, Office of Director ip 18739, 329 24X Fiche 80-361,83/06/03,8306070029
- 8305110464 IE Info Notice 83-36, "Impact of Security Practices on Safe Operations " Syc list encl JURDAN, E. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/07 Consolidated Edison Co of New York, Inc. 119pp 18830 280 24X Fiche 80-000,83/06/09,8305110464.
- 8305110470 IE Info Notice 83-38, "Defective Heat Sink Adhesive & Seismically Induced Chatter in Relays Within Printed Circuit Cards," "Svc list encl JURDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co. of New York Inc. 118pp 18920 225 24X Fiche. 50-000,83/06/13,8305110470
- 8306070010 IE Info Notice 83-37, "Transformer Failure Resulting From Degraded Internal Connection Cables." Svc list encl JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/06/13 Consolidated Edison Co of New York, Inc 243pp. 18921.001 24X Fiche 50-000,83/06/13,8306090010
- 830628049B Forwards IE Insp Repts 50-361/83-24 & 50-362/83-23 on 830425-0802 No noncompliance noted.

 BISHOF, T W. Region 5, Office of Director. 83/06/15 PAPAY, L. T. Bouthern California Edison Co. 2pp. 19017 295, 24X Fiche: 50-361, 83/06/15, 8306280498.
- ---B306280511 IE Inap Rapts 50-361/83-24 & 50-362/83-23 on 830425-0602 No noncompliance noted Major areas inspected startup test programs, including operational safety verification, power accession testing, plant trips & LER review.

 PATE.R J., CHAFFEE.A.E., BTEWART.J.P. Region 5, Office of Director. 83/06/14 7pp. 19017:297 24X Fiche: 50-361.83/06/15, 8306280498.

- 830620037B Ack receipt of 830516 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-361/83-13 & 50-362/83-12 Undervoltage coil mechanism important Violation A cited properly,
 MARTIN.J B Region 5, Office of Director 83/06/17 FORARTY, D J,
 Southern California Edison Co 3pp 18899, 087 24X
 Fiche 50-361, 63/06/17, 8306200378
- --83062003B1 Responds to NRC 830414 ltr re violations noted in IE Insp Repts 50-361/83-13 & 50-362/83-12. Item A in notice of violation re surveillance testing of reactor trip breaker unwarranted FOGARTY.D J Bouthern Celifornia Edison Co 83/05/16 MARTIN.J B Region 5. Office of Director 7pp 18899.090 24X Fiche 50-361,83/06/17.8306200378
- 8306280546 Forwards IE Insp Repts 50-361/83-15 & 50-362/83-13 on 830323-0602 & notice of violation 818407. T. W. Region 5. Office of Director 83/06/17 PAPAY, L. T. Bouthern California Edison Co. Spp. 19018:109 24X Fichs 50-361,83/06/17,8306280546
- --8306280551 Natice of Violetion from insp on 830323-0602 KIRSCH, D. F. Region 5, Office of Director 83/06/17 7pp 19018: 112 24% Fiche 50-341,83/06/17,8306280546
- --8306280561 IE Insp Repts 50-361/83-15 t 50-362/83-13 on 830323-0602. Noncompliance noted inadquate valve sys lineup procedures, failure to maintain certain fire protection valves locked open & alterations of afficial records CHAFFEE.A , SIEMART,F , KIRSCH.D,F , Region 5, Office of Director. 83/06/14 1ipp. 17018.i19 24X Fiche: 50-361,83/06/17,8306280546.
- 8305230211 Responds to IE Bulletin 83-05, "ABME Nuclear Code Pumps & Spare Parts Mfg by Hayward Tyler Pump Co " No subj pumps or spare parts in use or planned for use at facility HAYNEB, J. 9 Southern California Edison Co 83/06/20 MARTIN, J B Region 5, Office of Director, ip. 18946-348 24X Fichs 50-361,83/06/20,8306230211.
- 8305110475 IE Info Notice 83-40, "Need to Environmentally Guelify
 Epoxy Grouts & Sealers." Svc list encl.
 JORDAN, E. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/06/22 Consolidated Edison Co. of New
 York, Inc. 1:5pp 19021.179 24X Fiche: 30-000, 83/06/22, 8305110475,
- 9305110477 IE Info Notice 83-41, "Actuation of Fire Buppression Bys Causing Inoperability of Safety-Related Equipment " Svc list encl. JORDAN, E. L. Division of Emergency Preparadness & Engineering Response (Post 830103) 83/06/22. Consolidated Edison Co. of New York Inc 120pp. 18997:007 24X Fiche: 30-000.83/06/22.8303110477.
- 8306240002 Application to amend License NPF-15, authorizing full-power operation on 830819.

 DIETCH, R. Southern California Edison Co. 83/06/22 DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 1p. 18981-309, 24) Fiche. 50-362, 83/06/22, 8306240002
- B305110479 IE Info Notice 83-42. "Reactor Mode Switch Malfunctions."
 Byc list encl.
 JURDAN, E. L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/06/23 Consolidated Edison Co. of New
 York, Inc. 116pp 18796-242 24X Fiche: 50-000, 83/06/23, 8305110479.
- 8305110483 IE Info Notice 83-43, "Improper Bettings of Intermediate Range (IR) High Flux Trip Satpoints " Svc list encl. JORDAN, E. L. Division of Emergency Preparedness & Enginsering Response (Post 830103) 83/06/24 Consolidated Edison Co of New York, Inc. 116pp. 19046:297. 24X Fiche: 50-000, 83/06/24, 8305110483
- R. Periodic operating reports & related correspondence
- B306160489 Monthly operating rapts for Apr 1983 W/830513 ltr. MAYWEATHERL , RAY, H. B Southern California Edison Co. B3/05/13 Management Information Branch, 12pp 18864 139, 24X Ficher 50-361183/05/13,8306160489.
- 8. Reportable occurrences. LERs & related correspondence
- 8306100072 RO on 830506. NFPA 72D std not met, due to improper design change which eliminated ability to differentiate between trouble & alarm signals. Design change package will be prepared by 830615 to modify circuitry RAY.H.B. Bouthern California Edison Co. 83/05/24 MARTIN.J B. Region 5. Office of Director. 2pp. 18802 181. 24X Fiche. 50-361, 83/05/24, 8306100072.

- B306140239 RO B3-034 on B30527, qualified safety parameter display sys failed to operate during completion & maint of inadequate core cooling instrumentation Caused by shorting of power cable due to abrasion RAY, H B Southern California Edison Co 83/05/31 MARTIN, J B Region 5, Diffice of Director 2pp 18833 001 24X Fiche 50-362,83/05/31,8306140239
- B306230467 LER 83-013/03L-0 on B30509, partial disengagement of rod-end burking on mechanical shock anubber identified Caused by bearing assembly not properly secured Snubber reworked H/830608 ltr
 RAY, H B Southern California Edison Co 83/06/08 MARTIN, J B Region 5, Office of Director 4pp 18941 336 R4X
 Fichs 50-362.83/06/08,8306230467
- 8306230367 LER 93-038/03L-0 on 830511. *pray sys protecting cable tunnel Brition 3 declared inoperable when internals to deluge panel 375H8951 found corroded Caused by water intrusion due to improper closure of panel W/830610 ltr RAY.H B Southern California Edison Co 83/06/10 MARTIN, J B Region 5 Office of Director 3pp 18944 132 24X Fiche 50-362.83/06/10.8306230369
- U. Congressional/Executive Correspondence
- 8211160365 Forwards Community Energy Action Network 821018 ltr & Los Angeles Times article re potential problem w/welds at facilities CRANSTON, A Senate 82/10/29 KRAMMERER, C Office of Congressional Affairs Spp 18893 036 24X Fiche 50-206,83/04/14,8306160052
- DOCKET 50-364 JOSEPH M FARLEY NUCLEAR PLANT, UNIT 2

 F Becurity, medical, emergency & fire protection plans
- B306090319 Forwards IE Safeguards Insp Repts 50-348/83-07 & 50-364/83-05 on 830227-0303 & notice of violation Rept data(1s & notice of violation withheld (ref 10CFR73 21). LEWIS.R C Division of Project & Resident Programs 83/03/23 HCDONALD.R P Alabama Power Co 2pp 18795 112 24X Fichs 50-348,83/03/23,8306090319
- --B30A090324 IE Bafeguards Insp Repts 50-348/83-07 & 50-344/83-05 on 830227-0303 Moncompliance noted failure of vital area alaras in access adde to indicate tamper Details withheld (ref 100FR73 21)

 MOCRE, D E Region 2, Office of Director 83/03/23 1p 18795 114 24X Fiche 50-348.83/03/23,8304090319
- 8306020570 Comments on NUREO-0737, Itam III A 2 1. "Emergency Preparedness, Upgrade Emergency Plans to App E, 10CFR50 "
 Unsite & offsite emergency preparedness adequate Item closed VARQA, B A Operating Reactors Branch 1 83/05/24 CLAYTON, F L Alabama Power Co 2pp 18715 066 24X Fiche 50-348, 83/05/24, 8306020570
- 830-8010332 Forwards IE Safeguards Insp Repts 50-348/83-14 & 50-364/83-12 on 830509-13 No noncompliance noted VERRELLI, D Division of Project & Resident Programs 83/05/26 MCD0MALD, R.P. Alabama Power Co. 2pp 18682 150 24X Fiche 50-348,83/05/26,8306010332
- --8306010333 IE Safeguards Insp Repts 50-348/83-14 & 50-364/83-12 on 830509-13 No noncompliance noted Major areas inspected site orientation.security organization-agt.personnel & response Details withheld fraf 100ERF3 211 HALLS L Region 2. Office of Director 83/05/24 ip 18682 152 24X Fiche 50-348.83/05/26.8306010332
- 8304140645 Forwards IE Insp Repts 50-348/83-11 & 50-344/83-09 on B30418-22 No concompliance noted VERRELLI, D M Division of Project & Resident Programs 83/03/26 MCDOMALD, R P Alabama Power Co 2pp 18841, 242 24X Fiche-50-348, 83/05/26, 8306140645
- ----8306140655 IE Insp Repts 50-348/83-11 & 50-364/83-07 on 830418-22 No noncompliance noted Major areas inspected emergency preparedness MARSION, R Region 2, Office of Director 83/05/24 App 18641 244 24X Fiche 50-348,83/05/26,8306140645
- B306090204 Releases public version of emergency plan administrative procedures FELTON.J M Division of Rules and Records 83/06/01 Document Management Branch ip 18809 229 24X Fiche 50-348,83/06/01.

- --B306090208 Public version of Emergency Plan Administrative Procedure FNP-83-0497, "On-Call Schedule "Schedule will be filed w/Procedure FNP-0-EIP-8 W/830511 ltr H/UDSPETH, J B Alabama Power Co 83/05/11 App 10009 P30 24% Fiche 50-348,83/06/01,8306090204
- 8306090329 Ack receipt of 830418 ltr informing NRC of steps taken to correct violations noted in II. Safeguarda lnsp Reptu 50-348/83-07 & 50-364/83-05 LEMIS.R C Division of Project & Resident Programs 83/06/06 HCDDNALD.R P Alabama Power Co 2pp 18795 070 P4X Fichs 50-348,83/06/06,8306090379
- --B306090332 Responds to NRC 830323 ltr re violations noted in ff Safeguards Insp Repts 50-348/83-07 & 50-364/83-05 Corrective actions withheld CLAYTON F L Alabama Power Co 83/04/18 LEWIS, R C Region 2. Defice of Director ip 18795 072 24X Ficha 50-348 B3V06/06. 8306090329
- 8306160027 Releases public version of rovised emergency plan implementing procedure FELTON, J M Division of Rules and Records 83/06/06 Document Management Branch Ip 18072 275 24X Fiche 50-348/03/06/06. 8306160027
- --8306160032 Public version of Rev II to Emergency Plan Implementing Procedure FNF-O-EIP-4, "Chemistry & Health Physics Bupport to Emergency Plan " W/830024 ltr HUDSPETH, J B Alabama Power Co P3/05/19 18pp 18072 24% 24: Fichs 50-348,83/06/06.8306160027
- 8306210363 Releases public version of revised emergency plan implementing procedure FELTON, J.M. Division of Rules and Records 93/06/06 Document Management Branch ip 18937 097 24% Fiche 50-349.83/06/06. 8306210363
- --B306210365 Public version of Rev 12 to Emergency Plan Implementing Procedure FNP-0-EIP-9. "Radiation Exposure Estimation & Classification of Emergencies" Receipt form encl H/B30421 ltr H/D59ETH.J B. Alabama Power Co. 83/04/14 Office of Nuclear Reactor Regulation, Director 130pp 18937 098 24X Fiche 50-348.83/06/06.8306210363
- 8306290198 Ack receipt of 830608 ltr informing NRC of atrps talen to correct violations noted in IE Insp Repts 50-348/83-07 & 50-354/83-07

 LEHIB.R C Division of Project & Resident Programs 03/06/16

 MCDDNALD.R P Ainbems Power Co 2pp 19056 075 24X

 Fiche 50-348.83706/16.8306290196
- --8306290207 Responds to NRC B30510 ltr re violations noted in IF Insp Repts 50-348/63-07 & 50-364/83-07 Corrective actions personnel instructed to close fire doors unless fire watch established & preventive maint program updated CLAYTON,F L. Alabama Power Co. B3/06/08 LEMIB.R C. Region 2. Office of Director App. 19056 097 24X Fiche 50-34B.B3/06/16. 8306290198
- --B306290222 IE Insp Repts 50-348/83-09 & 50-364/83-07 on 830306-0410
 Noncompliance noted failure to follow calibr & recycle
 procedures & Tech Spec requirements for fire doors &
 Procedure FNP-1-57P-256 15. Rev 3, inadequate
 BRADFORD, W H Region 2, Office of Director. 83/05/06 10pp
 19056 104 24X Fiche 50-348,83/04/16.8306290198.
- P Operating license stage documents & correspondence
- 8306010331 Submits list of post-trip review procedures to be modified following review of results of NUREQ-09/7 (Balem event) & discussion w/NRC Mode will be made within 30 days CLAYTON, FL Alabems Fouer Co. 83/05/24 VAROA. B A. Office of Nuclear Reactor Regulation, Director 1p 18681 270: 24X Fiche 50-348,83/05/24,8306010331.
- 8306020036 Ack receipt of 830510 ltr informing NRC of commitment for resolution of reactor protection sys BS-416 breaker problem. Program being reviewed Responsibility for review of conclusions transferred to Region II VAROA.S A Operating Reactors Branch I 83/05/25. CLAYTON.F L Alabama Power Co. 2pp 18702 324. 24X Fiche.50-349,83/05/25,8306020036
- 8304020030 Requests remittance of Class III fee for 82:119 application to amend License NFF-8 re safety-related masonry woll dasign.
 MILLER W D License Fee Management Branch 83/05/24. CLAYTON, F L. Alabama Pawer Co ip 18702, 332 24X Fichs 50-344, 83/05/26.

- 8304010426 Application for amend to OL, proposing one-time Tech Spec 4 3 4 2a & 2b change to waive turbing valve testing during remainder of current fuel cycle Approval of 821008 request to delete Tech Spec 3/4 3 4 negates one-time change request CLAYTON,F L Alabama Power Co 83/05/27 VAROA.S A Office of Nuclear Reactor Regulation. Director 3pp 18674 250 24X Fische 50-344.83/05/27.8306010426
- ~~8306010429 Proposed one-time change to Tech Spec 4 3 4 2a & 2b waiving turbine valve testing during remainder of current fuel
 - e Alabama Power Co 83/05/27 2pp 18674 253 24X Fishe 50-364,83/05/27,8306010426
- 8306060119 Appeals NRC 830427 decision that no basis exists for deleting turbine valve testing requirements NRC conclusion not factually based Interim relief from Tech Spec 3/4 3 4 requested Detailed commants submitted CLAYTON: F L Alabama Power Co 83/05/31 VAR9A. S A Office of Nuclisar Reactor Regulation, Director Spp 18719 077 24X fichs 50-364,83/05/31,8306060115
- B306060201 Submits status & schedule re design changes test procedures & confirmatory life program for DS-414 reactor trip breakers, per 830510 ltr & 830531 commitment Maint program will be modified upon completion of 6-month test program CLAYTON, F. L. Alabama Power Co. 83/05/31 VARGA, S. A. Office of Nuclear Reactor Regulation, Director 4pp 18727-324 24X Fishe 50-348,83/05/31.8304060201
- B306070326 Forwards RCS pressure isolation valve leakage results performed during first refueling outage, in response to 820810 & 1223 requests Valve disassembled & inspected Loose corroston products may have prevented closure CLAYTON:F L Alabama Power Co 83/06/03 VAROA:S A NRC No Detailed Affiliation Given Apr 18741 111 24X Fiche 50-264,83/06/03.8306070326
- 8304140610 Requests that util previous date of 830901 for approval of proposed amend to Tech Spec 3/4 1 3 re movable control assemblies be advanced to 830715 due to increase in control rod sys events CLAYTON.F.L. Alabama Power Co. 83/04/03 VARGA.8 A. Office of Nuclear Reactor Regulation, Director 2pp. 18842 077 24X Fiche 80-348,83/04/03,8306140610
- 830&130429 Application for amend to Licenses NPF-2 & NPF-8, changing Tech Specs re operating personnel.per NUREG-0737. Item I A 1 3 & Generic Ltrs 82-02 & 82-12, to incorporate current practices CLAYTON.F L Alabama Power Co 83/05/06 VARGA.S A Office of Nuclear Reactor Regulation. Director 3pp 18821 223 24X Fiche: 90-348.83/05/05.8305130429
- --9306130442 Proposed Tech Specs re use of overtime for operating personnel • Alabama Power Co 83/06/06 3pp 18821 226 24X Fiche 50-348,83/06/06,8306130429
- B306140593 Commits to add1 action items associated w/Westinghouse reactor trip breakers. Model DB-416, based on 830602 telcon Only replacement undervoltage trip attachments w/record of 25 cycles will be used.
 CLAYTON.F L Alabama Power Co 83/06/06 VARGA.8 A Office of Nuclear Reactor Regulation. Director 3pp 18844 183 24X
 Fiche: 50-348,83/06/06,8306140593
- 8305160278 Forwards status of all licensing items identified in util 830113 ltr CLAYTON.F.L. Alabama Power Co. 83/06/10 VAROA.8 A. Office of Nuclear Reactor Regulation, Director 7pp. 18860-177 24X Fichs. 50-348, 83/06/10. 8306160278
- 8306230378 Application to amend Licenses NPF-2 & NPF-9, deleting Tach Spac requirement for river water sys survoillance & svc water bidg battery sys discharge test during shutdown CLAYTON-F-L. Alabama Power Co. 83/06/20 VARQA-8.A. Office of Nuclear Reactor Regulation, Director. Jpp. 18743-247 24X Fiche 50-348,83/06/20,830378
- --6306230382 Proposed Tech Spac changes, deleting requirement for river water sys surveillance & svc water bldg battery sys discharge test during shutdown

 a Alabama Power Co. 83/06/20 9pp 18943 249 24X

 Fiche: 50-348:83/06/20:8308230378
- @306246040 Requests apecific license amends discussed during May 1983 telcons w/NRC be given priority to meet review schedules. Evaluation will avoid need to resubmit changes as emergency Tack Spec changes

 CLAYTON.F.L Alsbama Power Co 83/06/20 VARQA.S A Office of
 Nuclear Reactor Regulation, Director App 18981 089 24X

 Fiche 50-346,83/06/20.8306240040.

- O Inspection reports. IE Bulletins & correspondence
- B306090319 Forwards IE Sefeguards Into Repts 50-348/83-07 & 50-364/83-03 on 830227-0303 & notice of violation Rept details & notice of violation withheld (ref 10CFR73 21) LEWIS.R C Division of Project & Resident Programs 83/C MCDONALD.R P Alabama Power Co 2pp 18795 112 24X Fiche 50-348.83/03/23.8306090319 63/03/23
- --9306090324 IE Safeguards Insp Repts 50-348/83-07 & 50-364/83-05 on 830227-0303 Noncompliance noted failure of vital area alarms in access mode to indicate tamper Details withheld (ref 10CFR73-21)

 MODRE, D E Region 2, Office of Director MCOUIRE, D. R Division of Emergency Preparedness & Materials Safety 83/03/23 ip 18795-114 24X Fiche 50-348, 83/03/23, 8306090319
- 8304140473 Forwards IE Insp Repts 50-348/83-12 & 50-364/83-10 on B30421-22 No noncompliance noted VERRELLI.D M Division of Project & Resident Programs 83/05/16 MCDUNALD, R P Alabama Power Co 2pp, 18834 326 24X Fiche 50-348,83/05/16,8304140473
- --8304140477 IE Insp Repts 50-348/83-12 & 50-344/83-10 on 830421-22 No JOBIA04// IE Insp Repts 30-348/83-12 & 50-364/83-10 on 830421-2 noncompliance noted Major areas inspected licenses program for keeping radiation exposures ALARA DEBS, B T , NOSEY, C. M Region 2. Office of Director BARR, K P Division of Engineering & Radiological Safety Programs 83/05 7pp 18834 328 24X Fiche 50-348.83/05/16.8306140473
- 8305i1045B IE Info Notice 83-32, "Ruptured Am-241 Bources Contained in Well Logging Device " Svc list encl TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/05/26 Consolidated Edison Co. of New York, Inc. 125pp 18831 043 24% Fiche 50-000,83/05/26,830511045B
- 8304010332 Forwards IE Safeguards Insp Repts 50-348/83-14 k 50-344/83-12 on 830509-13 No noncompliance noted VERRELLI, D Division of Project & Resident Programs 83, MCDDNALD, R P Alabama Power Co 2pp 18682 150 24X Fiche 50-348,83/05/26,8304010332 83/05/26
- --8305010333 IE Bafeguards Insp Repts 50-348/83-14 & 50-344/83-12 on 830507-13 No noncompliance noted Major areas inspected site orientation, security organization-mgt.personnel & response. Details withheld (ref lOCFR3 21)
 HALL.B L Region 2. Office of Director MCOUIRE.D R Bivision of Emergency Preparedness & Materials Safety 83/05/24 ip 18682 152 24% Fiche 50-348,83/05/26.8306010332
- 8306140645 Forwards IE Insp Repts 50-348/83-11 & 50-364/83-09 on 830418-22 No noncompliance noted VERRELLI, D. M. Division of Project & Resident Programs 83/05/26, MCDONALD, R.P. Alabama Power Co. 2pp 18841 242 24X Fiche 50-348,83/05/26,8306140645,
- --8306140655 IE Insp Repts 50-348/83-11 & 50-364/83-09 on 830418-22 No noncompliance noted Major areas inspected emergency preparedness
 MARBION R R Region 2. Office of Director JENKINB, Q R Division
 of Emergency Preparedness & Materials Safety B3/05/24 App
 18841: 244 24X Fiche 50-348.83/05/26.8306140645
- B305ii0461 IE Info Notice B3-35, "Fuel Movement W/Control Rods Withdrawn at BWRs " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post B30i03) B3/05/31 Consolidated Edison Co. of New York Inc 116pp 18732 208 PAX Fichs 50-000,83/05/31,8305110461 11600
- 8306140071 Responds to IE Bulletin 82-02, "Degradation of Threaded Fasteners in RCPB of PMR Plants " Maint & GA measures implemented Listed closure connection threaded Pasteners opened for component insp/maint CLAYTON, F L Alabama Power Co 83/05/31 O'REILLY, J.P Region 2, Office of Director, 3pp 18838 241 R4X Fiche 50-348,83/05/31, 8206140071
- 8304090329 Ack receipt of 830418 ltr informing NRC of steps taken to correct violations noted in IE Bafeguards Insp Repts 50-348/83-07 & 50-344/83-05 LEMIS.R.C. Division of Project & Resident Programs 83/06/06, MCDONALD, R P Alabama Power Co. 2pp 10795 070 24X Fiche. 50-348, 83/06/06, 8306090329
- --8306090332 Responds to NRC 830323 ltr re violations noted in IE Safeguards Insp Repts 50-348/83-07 & 50-344/83-05, Corrective actions withheld CLAYTON.F L Alabama Power Co 83/04/18 LEWIS.R C. Region 2 Office of Director ip 18795.072 24X Fichs 50-348.83/04/06, 8304090329

- 8305110464 IE Info Notice 83-36, "Impact of Security Practices on Safe Operations." Sec list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83706/09. Consolidated Edison Co. of New York, Inc. 119pp 18830-280 24X Fiche 50-000,83706/09,8305110464
- 8306170357 Submits evaluation of plant design & initial description of planned actions in response to IE Bulletin 83-03 re diesel generator syc water sys Check valve design & matls superior. Final evaluation forthcoming CLAYTON.F L. Alabama Power Co. 83/06/10 O'REILLY, J. P. Region 2, Office of Director 3pp 18880 178. 24X Fiche: 50-348, 83/06/10, 8306170357
- 8305110470 IE Info Notice 83-38, "Defective Heat Sink Adhesive & Seismically Induced Chatter in Relays Within Printed Circuit Cards " Syc Tist encl.
 JORDAN-E, L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13. Consolidated Edison Co. of New York, Inc. 118pp 18920:225 24X Fishe 50-000.83/06/13.8305110470
- 8306090010 IE Info Notice 83-37, "Transformer Failure Resulting From Degraded Internal Connection Cables," Svc list encl JDROAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/06/13 Consolidated Edison Co. of New York, Inc. 243pp. 18921-001 24X Fichs 50-000, 83/06/13, 8306090010
- 8305290198 Ack receipt of 830508 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-348/83-09 & 50-364/83-07. LEWIS, R. C. Division of Project & Resident Programs E MCDDNALD, R. P. Alabama Power Co. 2pp. 19056-095. 24X Fiche: 50-348: 83/06/16: 8306290198
- --8306290207 Responds to NRC 830510 ltr re violations noted in IE Insp. Repts 50-348/83-09 & 50-364/83-07 Corrective actions personnel instructed to close fire doors unless fire watch established & preventive maint program updated CLAYTON.F.L. Alabama Power Co. 83/06/08 LEMIS.R C Region 2, Clayton of Director 4pp. 19056 097 24X Fiche: 50-348.83/06/16, 8306290198
- --8306290213 Forwards IE Insp Repts 50-348/83-09 & 50-364/83-07 on 830306-0410 & notice of violation LEMIB.R C Division of Project & Resident Programs. 83/05/10 MCDONALD.R P Alabama Power Co. 2pp 19056 101 24X Fiche: 50-348,83/06/16,8306290198
- --8306290216 Natice of violation from inse on 830306-0410. * Region 2: Office of Director. 83/05/10 lp. 19056 103. 24X Fiche 50-348.83/06/16:8306290198
- --B306290222 IE Insp Repts 50-348/83-09 & 50-364/83-07 on 830306-0410 Nancompliance noted: feilure to follow calibr & recycle procedures & Test Spec requirements for fire foors & Frocedure FNP-1-37P-256 15. Rev 3. inadequate.

 BRADFORD, W. H., RULAND, W. H. Repion 2. Office of Director. CANTRELLE, B. Division of Project & Resident Programs. 83/05/06.10pp. 19056:104. 24X Fiche: 50-348,83/06/16,8306270198.
- 8305i10475 IE Info Notice 83-40, "Need to Environmentally Qualify Epoxy Grouts & Saalers," Svc list encl.
 JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103), 83/06/22 Consolidated Edison Co. of New York, Inc. 115pp 19021 179 24X Fiche.50-000.83/06/22.8305110475
- 8305:10477 IE Info Motice 83-41, "Actuation of Fire Buppression Bys Causing Inoperability of Bafety-Related Equipment." Syc list enci. JORDAN, E. L. Divisson of Emergency Preparedness & Engineering Response (Post 830103), 83/06/22 Consolidated Esison Co. of New York, Inc. 120pp, 18997-007 24X Fiche: 50-000,83/06/22,8305110477.
- 8305110483 IE Info Watice 83-43, "Improper Settings of Intermediate Range (IR) High Flur Trip Betpoints." Svc list encl.
 JURDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/06/24. Consolidated Edison Co. of New York, Inc. 116pp. 17046.297. 24X Fiche: 50-000.83/06/24,8305110483
- R. Periodic operating reports & related correspondence
- 8306160119 Monthly operating rept for May 1983, W/830610 ltr CLAYTON.F.L., HAIRSTON.W.Q. Alabama Power Co. 83/06/02. of Resource Managament, Director. 9pp. 18861:273 24X Ficha: 50~364, 83/06/02, 8306160119. Detice
- 8 Reportable occurrences: LERs & related correspondence
- 8306200216 Forwards LERs 83-023/03L-0,83-023/03L-0 & 83-024/03L-0. CLAYTON.F.L. Alabama Power Co. 83/06/10. Region 2. Office of Director ip. 18902:279. 24X Fiche.50-348.83/06/10.8306200216

- --8306200227 LER 83-023/03L-0 on 830511, train B reactor trip breater would not reclose Caused by design inadequacy Voltage available to undervoltage device coil marginally sufficient to allow undervoltage device to remain latched HARRSTON.W G Alabama Power Co B3/06/10 Region 2, Office of Director 4pp 18902 281 24% Fiche 50-348,83/06/10,8306200216
- --8306200233 LER 83-024/03L-0 on 830512, red control sys declared inoperable upon receipt of failure alarm on power cabinet 2AC Caused by failure of regulator circuitry card Card HAIRSTON.W C Alabama Power Co 83/06/10 Region 2, Office of Director 1p 18902 285 24% Fiche 50-348,83/06/10.8306200216 Director
- DOCKET 50-366 EDWIN I HATCH NUCLEAR PLANT, UNIT R F Security, medical, emergency & fire protection plans
- 8304030233 Forwards revised response to 820701 requests for exemption from 10CFR50 48 & App R requirements.per 830330 request Rev reflects compliance w/10CFR50 48 & App R requirements & responds to 830120 draft SER concerns GUCMAL T Georgia Power Co 83/05/27 STGLZ, J F Operating Reactors Branch 4 144pp 18705 023 24X Fiche 50-321,83/05/27,830403023
- 8304140711 Approves issuance of SALP Repts 50-321/83-06, 50-366/83-06, 50-424/83-06 & 50-425/83-06 for Jul 1981 Oct 1982 LEWIS, R C Division of Project & Resident Programs 83/06/01 KELLY, R J Georgia Power Co 3pp 18841 196 24X Fichs 50-000, 83/06/01, 8304140711
- --8306140719 Advises of 830317 meeting in Atlanta, GA to discuss SALP Repts 50-321/83-04, 50-366/83-06, 50-424/83-06 & 50-425/83-06 for Jul 1781 Oct 1982 LEWIS.R C Division of Project & Resident Programs 83/03/09 KELLY.R J Georgia Power Co 2pp 18841 199 24X Fichs 50-000,83/06/01,8306140711
- --8306140730 SALP Repts 50-321/83-06,50-366/83-06,50-424/83-06 & 50-425/83-06 for Jul 1981 Oct 1982 No significant util weaknesses identified * Region 2, Office of Director 83/03/09 38pp 19841 201 24x Fiche 50-000,83/06/01.8306140711
- -8306140743 Ack receipt of BALP Ropts 50-321/83-06,50-366/83-06,50-424/83-06 & 50-425/83-06 for Jul 1981 Oct 1982 Survey of Sources (Sources) 23-06 for July 1981 - Oct 1982 Evaluation acceptable 6 BECKHARL J T Georgia Power Co 83/04/18 O'REILLY, J P Region 2, Office of Director ip 18841 239 24X Fiche 50-000, 83/06/01, 8306140711
- 8306150133 Releases public version of revised emergency plan implementing procedures FELTON, J M Division of Rules and Records 83/06/01 Bocum Management Branch 1p 18872 092 24X Fiche 50-321,83/06/01. Document. Management Branch 8306150133
- --8306150137 Forwards public version of revised emergency plan implementing procedures.including Procedures HNP-2-4219 re battery fire.HNP-4870 re exercises & drills & HNP-4621 re actions for personnel in site area emergency NIX.H C Georgia Power Co 83/05/18 Office of Nuclear Restor Regulation. Director ip 16872 093 24X Fiche 50-321.83/06/01.8306150133
- --8306150141 Public version of revised emergency plan implementing procedures, including Procedures HNP-2-4219 re battery fire, HNP-4890 re exercises & drills & HNP-4621 re actions for personnel in site area emergency BUNNER.L. Georgia Power Co. 83/05/06 26pp 16872-094 24X Fiche 50-321,83/06/01,8306150133.
- 8306140237 Releases public version of revised emergancy plan implementing procedures FELTON, JM Division of Rules and Records 83/06/06 Docum Management Branch ip 18844 258 24X Fichs 50-321, 83/06/06. - Editorio d' Division of Management Branch 1p 8306140237
- --8306140246 Forwards public version of revised emergency plan implementing procedures including Procedures HNP-8137 reportable ion chamber Model RO-2A. HNP-8143 re low vol air sampler Model H-809 VI & HNP-4200 re fire procedure.

 NIX.H C Quergia Power Co 83/05/24 Office of Nuclear Reactor Regulation, Director App 18844 259 24X Fiche 50-321,83/06/05.8306140237

- --8306i40254 Public version of revised emergency plan implementing procedures including Procedures HNP-8137 re portable ion chamber Model RO-2A, HNP-8143 re low vol air sampler Model H-809 VI & HNP-4200 re general fire procedure * Georgia Power Co 83/05/24 37pp 18844 263 24X Fiche 50-321,83/06/06,8306140237
- 8306150037 Reteases public version of revised emergency plan implementing procedures FELTON J M Division of Rules and Records 83/05/07 Document Management Branch ip 18071 182 24X Fiche 90-321,83/06/07, 8306150037
- --8306150041 Forwards public version of revised emergency plan implementing procedures, including Procedures HNP-8156 re Gamma-10 portal monitor operation HNP-4623 re site emergency shift supervisor & HNP-4626 re rally point leader NIX.H C Georgia Power Co 83/04/25 Office of Nuclear Reactor Regulation, Director ip 18871 183 24X Fiche 50-321,83/06/07,8306150037
- --B306150044 Public version of revised emergency plan implementing procedures including Procedures HNP-B156 rs gamma-10 portal monitor operation. HNP-6423 re site emergency-shift superviser & HNP-4626 re rally point leader NIX.H C Georgia Power Co B3/04/15 105pp 18871 184 24X Fiche 30-321.83/04/07,8306150037
- B306220307 Releases public version of revised emargency plan implementing procedures FELTON.J M Division of Rules and Records B3/06/07 Document Management Branch ip 18940 114 24X Fiche 50-321,83/06/07, B306220307
- --8304220313 Forwards public version of revised emergency plan implementing procedures, including Procedures HNP-B004 repersonnel dosimeter program HNP-B016 reshipment of radioactive metl & HNP-4622 recontrol room operators NIX.H C Georgia Power Co 83/05/04 Office of Nuclear Reactor Regulation, Director 1p 18740-115 24X Fiche 50-321,83/04/07,830420707
- --8306220310 Public version of revised emergency plan implementing procedures, including Procedures NNP-8004 re personnel dosimeter program, NNP-8016 re shipment of radioactive matl & NNP-4622 re control room operators
 ROCERS, W.H., NIX, H.C. Quergia Power Co. 83/04/26 Office of Nuclear Reactor Regulation, Director 181pp 18940 116 24X Ficha 50-321,83/06/07,8306220307
- 8306170202 Forwards addl info to justify 820701 10CFR50 48 & App R schedule examption requests discussed at 830330 meeting. Plan being developed to complete maint & design changes M/two oversite drawings Aperture cards available in PDR GUCHA.L T Georgia Power Co 83/06/14 STOL2.J F Operating Reactors Branch 4 4pp 18882:277 24X Fiche 50-321.83/06/14.8306170202
- 1 Financial information
- 8304070123 Forwards Annual Financial Repts.1982 OUCWA-L T Georgia Power Co. 83/04/02 DENTON.H R Office of Nuclear Reactor Regulation, Director ip 18739 038 24X Fiche.50-000.83/04/02.8304070123.
- --8306070127 Annual Financial Rept. 1982
 VGGTLE, A W The Bouthern Co 83/03/10 51pp 18739, 039 24X
 Fiche 50-000, 83/06/02, 8306070123
- --8306070130 Annual Financial Rept, 1982 SCHERER, R. W., MILLER, J. H., Georgia Power Co. 83/03/07 36pp 19739 091 24X Ficha 50-000, 83/06/02, 8306070123
- P Operating license stage documents & correspondence
- 8306010056 Advises that addi Tech Bpecs needed to assure that current Tech Epec limits for min critical power ratio are conservative Tech Bpec must assure operability of sys for inclusion in reload amend prior to restart STDLX.J F Operating Reactors Branch 4 83/05/12 BECKHAM.J T Georgia Power Co App 18687 071 24X Fiche 50-366.83/05/12, 8306010056
- 8306150478 Discusses 830223 application for amend to License NPF-5, modifying Tach Space to provide add1 & revised trip tetpoints reflecting design mode to reduce containment loads from transients FR notice of consideraton ancl.
 RIVENBARK, G W. Operating Reactors Branch 4 83/05/12 BECKHAM, J T. Georgia Power Co 2pp 18867.347 24X Fiche 50-366,83/05/12,8306150478.

- --B3061504B4 Natice of consideration of issuance of emend to License NPF-5 & proposed no significant hazards consideration determination & opportunity for bearing STOLZ.JF Operating Reactors Branch 4 B3/05/12 Bpp 18867 349 24% Fiche 50-366.83/05/12-8306150478
- 8306030239 Forwards request for add1 info re 830330 reload application for Cycle 4 operation Expedited response requested STOLZ, J.F. Operating Reactors Branch 4 83/05/19 BECKHAM, J.T. Georgia Power Co. 3pp. 18734-019 24X Fichs 50-366.83/05/19, 8306030239
- 8306070224 Forwards Rev O to "EI Hatch Nuclear Plant Units 1 & 2 Environ Qualification of Class IE Equipment," in response to IE Bulletin 79-018 & 10CFR50 49 requirements GUCHAL T Georgia Power Co 83/05/20 STOLZ, J F Operating Reactors Branch 4 219pp 18746 152. 24% Fithe 50-321,83/05/20,8306070224
- 8306010367 Application for amend to License NPF-5, proposing add Tech Spec surveillance requirements for high reactor water level trip function & main turbine bypass valves BECKHAM, JT Georgia Power to 83/05/26 8TGLZ, JF Operating Reactors Branch 4 3pp 18682 107 24% Fiche 50-366,83/05/26, 8306010367
- --8306010371 Proposed Tech Specs re add1 surveillance requirements for high reactor water level trip function & main turbine bypass valves

 * Georgia Power Co 83/05/26 7pp 18682.110 24X
 Fiche 50-366.83/05/26.8306010367
- 8304030082 Notification of 830801 meeting w/util in Bethesda, MD to discuss util evaluation & repair of cracks discovered in weld areas of recirculation & reactor heat removal syspiping RIVENBARK, G W Operating Reactors Branch 4 83/05/27 8TOLZ, J F Operating Reactors Branch 4 2pp 18733 264 24X Fiche 50-388, 83/05/27, 8308030082
- 8304070129 Requests withdrawal of 820430 proposed Tech Spec changes re safety-related snubber insp & surveillance requirements. Inoperable snubber conditions defined in proposed changes do not reflect actual operability concerns QUCHA: T. Quargia Power Co 83/05/31 STQLZ, J.F. Operating Reactors Branch 4 1p 18739 254. 24X Fichs 50-321.83/05/31. 8304070129
- 8304070351 Application for amend to Licenses DPR-57 & NPF-5, revising dose equivalent inding Tech Specs to reflect current requirements Info resolving outstanding purge & vent valve operability issues encl
 BECKHAM.JT Georgia Power Co 83/08/31 BTOLZ.JF Operating Reactors Branch 4. 34pp. 18742 071 24x Fiche: 50-321,83/05/31,8304070381
- --8306070387 Proposed Changes to dose equivalent indine Tech Specs & preliminary proposed Tech Specs for drywell & suppression chamber purge sys # Georgia Power Co 83/05/3i 5pp i8742.103 24X Fichs 50-321.83/05/31.8306070351.
- B304070125 Submits revs to B30525 augmented RCB leak detection submittal & inservice insp program commitment, incorporating surveillance frequencies per NUREQ-0313.Rev 1. Insp &/or mod plans for recirculation & RHR sys pipting forthcoming GUCHALL T Georgia Power Co 83/06/02 BTOL7.JF Operating Reactors Brench 4 2pp 18739 266 24X Fichs 50-366.83/06/02, 8306070125
- B306160397 Forwards revised pages to plant unique analysis rept re resolution of torus-attached piping pump & valve evaluation Pages reflect satisfactory results of evaluation of 14 valves & two pumps.

 GUCWA, L. T. Georgie Power Co. 83/06/02 STOLZ, J. F. Operating Reactors Branch 4. App. 18860 102 24% Fither 50-366, 83/06/02, 83/06/02, 83/06/02, 83/06/02, 83/06/0397
- 8304220217 Presents alternatives to automatic depressurization system to a siminate need for manual actuation for corecoverage per TMI Item II K 3 18 Implementation schedule & proposed Tech Specs requested within 45 days of itr receipt STOLZ, J F Operating Reactors Branch 4 83/04/03 BECKHAM, J T Georgia Power Co. 2pp. 18951:001. 24X Fichs 50-321.83/04/03, 8306220219
- 8306100132 Forwards Rev 0 to "Design Rept for Held Overlay Repairs & Flaw Evaluations in Recirculation & RHR Bys " Bensor check will be performed every 4 hours in addition to interval required by Tech Specs, effective at restart OUCHA, L. T. Georgia Power Co. 83/Q6/Q8. STOLZ, J. F. Operating Reactors Branch 4. 2pp. 18801-262, 24X Fichs. 50-366, 83/06/Q8, 83/06/D8, 83/06/D8,

- --8306100136 Rev O to "Design Rept for Weld Overlay Repairs & Flaw Evaluations in Recirculation & RHR Sys." GUSTIN.H L . CHARNLEY.J E . MCINNES.I D NUTECH Engineers, Inc GPC-07-102 ROO 63706407 104pp 18801 264 24X Fiche 50-366.83706708.8306100132
- 8306140075 Advises that SER & technical evaluation repts re environ qualification of safety-related electrical equipment do not contain proprietary info.Repts may be placed in PDR. QUCMAL T Georgia Power Co. 83/06/08 STCLZ.J F Operating Reactors Branch 4 jp 18839.114 24X Fiche:50-321.83/06/08, 820140075
- 8306150228 Forwards revised Page B 3/4 3-6 of proposed Tech Spec changes re reactor vessel water level submitted on 830526.in response to NRC 830512 request GUCWALL T Georgia Power Co 83/06/09 STGLZ.J F Operating Reactors Branch 4 1p 18846 287 24X Fiche 50-366.83/06/09, 8306150228
- --8306150232 Revised Page B 3/4 3-6 of 830526 proposed Tech Spec changes re reactor vessel water level.
 * Georgia Power Co 83/06/09 lp 18846 288, 24X
 Fiche 50-366 83/06/09 8306150228
- 8306160267 Forwards evaluation results demonstrating as-built acceptability of wetwell/drywell vacuum breakers on Mark I containments, in response to Generic Ltr 83-08 GUCHA/L.T Georgia Power Co. 83/06/09 STOL2.J.F. Operating Reactors Branch 4. 16pp 18859 329 24x Fiche.50-321,83/06/09,8306160267.
- 8306220002 Application for amend to Licenses DPR-57 & NPF-5 changing Tech Specs 3/4 6-2.8 3/4 6-6 & adding 3/4 6-46 for Unit 2 & 3 7-10a: 3 7-34: 3 7-34a & adding 3 7-10b & 3 7-34b for Unit 1 re purge & vent valve operability
 BECKHAM.J T Peorgia Power Co 83/06/15 STOLZ.J F. Operating Reactors Branch 4 5pp 18928:003. 24X Fiche 50-321:83/06/15, 3304-3003
- --8306220010 Proposed change: to Tech Specs 3/4 6-2,8 3/4 6-4 & added 3/4 6-46 for Unit 2 & 3,7-10a.3 7-34.3 7-34a & adding 3 7-10b & 3 7-34b for Unit I re purge & vent valve operability.

 Georgia Power Co 83/06/15. 55pp 18928 008 24X Fiche.50-321,83/06/15.8306220002
- 8306210335 Notification of 830623 meeting w/util in Atlanta. QA to discuss status of Region II review of inservice pump & valve test program & questions re program RIVENBARK. O Operating Reactors Branch 4 83/06/20 STULZ. J Operating Reactors Branch 4 2pp 18935-313 24% Fiche: 50-321. 83/06/20, 8306210335
- 8306270170 Application for amend to License NPF-5, revising Tach Spec Table 3 3 P-1 re isolation actuation instrumentation CAUSEY, J. C. Georgia Power Co 83/06/20 STOLZ, J. F. Operating Reactors Branch 4. 3pp 18992 003 24X Fiche. 50~366, 83/06/20, 8306270170
- --9306270175 Proposed Tech Spec Table 3 3 2-1 re isolation actuation instrumentation.
 # Gasrgia Power Co 83/06/20 4pp 18992 006 24X
 Fichs 50-366:83/06/20,8306270170.
- 8306270120 Bubmits add1 info re 830620 request for Tech Spec relief from requirement to have Group II isolation to occur on reactor water level low signal. BECKHAM. J T Georgia Power Co. 83/06/21, 870LZ, J.F. Operating Reactors Branch 4 2pp 18989, 110 24X Fiche 50-366,83/06/21, 8306270120
- G. Inspection reports, IE Bulletins & correspondence
- 8306140116 Forwards summary of IE mgt meetings on 830318 & 22 w/util to discuss condition of electrical cable trays & associated equipment & lack of mgt controls.

 U/REILLY,J,P. Region 2: Office of Director. 83/04/08 MELLY,R,J, Georgia Power Co 4pp 18839.092. 24X Fichs.50-321,83/04/08, 8306140116
- 8304070224 Forwards Rev O to "EI Hatchh Nuclear Plant Units 1 % 2 Environ Gualification of Class IE Equipment," in response to IE Bulletin 79-018 % 10CFR50.49 requirements. GUCHA, L. T. Georgia Power Co. 83/05/20 STGLZ, J. F. Operating Reactors Brench 4 10pp 18747.001 24X Fiche 50-381, 83/05/20, 8304070224

- 8304140515 Forwards IE Insp Repts 50-321/83-14 & 50-364/83-14 on 830426-29 & 0503-05 No noncompliance noted BANCE,H C Division of Project & Resident Programs B3/05/25 KELLY,R J Georgia Power Co 2pp 18843 238 24X Fiche 50-321,83/05/25,8306140515
- --B306140522 IE Insp Repts 50-321/83-14 & 50-366/83-14 on 830426-29 k 0503-05 No noncompliance noted Major areas inspected inservice inspigrevious enforcement matters & welding Heating head to discuss IE Bulletin 80 OZ inspirasults CROWLEY, B R Region 2, Office of Director BLAKE, J J Division of Engineering & Radiological Safety Programs 83/05/23 15pp 18843 240 24X Fiche 50-321,83/05/25,8306140515
- 8305110458 IE Info Nutice 83-32, "Ruptured Am-241 Sources Contained in Well Logging Device" Svc 1;st encl TAYLOR, J M Divirion of Safeguards & Inspection Programs {Post 830103) 63/05/26 Consolidated Edison Co of New York, Inc 125pp 18831 043 24X Fiche 50-000,83/05/26,8305110458
- 8305110460 IE Info Notice 83-34, "Event Notification Info Worksheet"
 Svc 11st enc!
 JORDANNEL Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/05/26 Consolidated Edison Co of New
 York, Inc 115pp 18732 085 24x Fiche 50-000,83/05/26,8305110460
- 8306140563 Corrected response to IE Bulletin B3-02 re inservice inspactivities concerning stress correction cracking in large diameter, stainless steel recirculation sys piping at BWR plants Weld exam list entl BECKHAM, J T Georgia Power Co 83/05/26 O'REILLY, J P Region 2, Office of Director 27pp 18834 239 24X Fiche 50-366.83/05/26, 8306140563
- 8305110461 IE Info Notice 83-35, "Fue; Movement W/Control Rods Withdrawn at BWRs " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) B3/05/31 Consolidated Edison Co of New York, Inc 114pp 18732 208 24X Fiche 50-000,89/05/31,8305110461
- 8306070129 Requests withdrawal of 820430 proposed Tech Spec changes resafety-related snubber insp & surveillance requirements
 Inoperable snubber conditions defined in proposed changes do not reflect actual operability concerns
 QUCNA, L T Georgia Power Co 83/05/31 STOLZ, J F Operating
 Reactors Branch 4 Ip 18739 254 24X Fiche 50-321,83/05/31,830670129
- 8306140711 Approves issuance of SALP Repts 50-321/83-06, 50-366/83-06, 50-424/83-06 & 50-425/83-06 for Jul 1981 Oct 1982
 LEWIS R C Division of Project & Resident Programs 83/06/01 KELLY, R J Georgia Power Co 3pp 18841 176 24X
 Fiche 50-000,83/06/01,8306140711
- --8306140719 Advises of 830317 meeting in Atlanta, GA to discuss SALP Repts 50-321/83-06, 50-366/83-06, 50-424/83-06 & 50-425/83-06 for Jul 1981 - Oct 1982 LEWIS,R C Division of Project & Resident Programs B3/03/09 KELLY,R J Georgia Power Co 2pp 18841 199 24X Fiche 50-000,83/06/01,8306140711
- --8306140730 BALP Repts 50-321/83-06, 50-366/83-06, 50-424/83-06 & 50-425/83-06 for Jul 1981 Oct 1982 No significant util weaknesses identified * Region 2, Office of Director 83/03/09 38pp 18841 201 24X Fiche 50-000, 83/06/01, 8306140711
- --8306140743 Ack raceipt of SALP Repts 50~321/83-06, 50~366/83-06, 50~424/83-06 for Jul 1981 Oct 1982 Evaluation acceptable BECKHAM, J T Georgia Power Co 83/04/18 D'REILLY, J P Region 2, Dffice of Director 1p 18841 237 24X Fichs 50-000.83/06/01, 23/44/74
- 8306070125 Submits revs to 830525 augmented RCS leak detection submittal & inservice insp program commitment incorporating surveillance frequencies per NUREG-0313. Rev i Insp &/or mod plans for recirculation & RHR sys piping forthcoming GUCMA, L.T. Georgia Fower Co. 83706/02 8701.7. J.F. Operating Reactors Branch 4 2pp 18739 266 24% Fiche 50-366,83/06/02,872407315
- B306240006 Discusses IE insp on 830227-0326 & forwards notice of violation & proposed imposition of civil penalty O'REILLY,J P Region 2. Office of Director, 83/06/02 KELLY,R J Georgia Power Co Spp 18987 341 24X Fiche 50-321.83/06/02.8306240006

- --8306240014 Notice of violation & proposed imposition of civil penalty in amount of \$40,000 Noncompliance noted failure to restore cable tray sys to quality conditions & lack of & planning for mods & maint re electrical cable tray installation O'REILLY, J P Region 2. Office of Director 83/06/02 4pp 18787 344 24X Fiche 50-321,83/06/02.8306240006
- 8308290455 Bubmits add1 response to IE Bulletin 81-03 Fire protection sys uses water from deep well Sys not susceptible to clam infiltration Mytilus ap not present in Altamaha River in vicinity of plant

 BECKHAM, J T Georgia Power Co 83/06/02 O'REILLY, J P Region P. Office of Director 2pp 19052 181 24X Fiche 50-321,83/06/02,8306290455
- B306140075 Advises that SER & technical evaluation repts re environ qualification of safety-related electrical equipment do not contain proprietary info Repts may be placed in PDR GUCMA, L. T. Georgia Power Co. B3/06/08 STOLZ, J. F. Operating Reactors Branch 4 ip 18839 114 24X Fiche 50-321,83/06/08, B306140075
- 8305290264 Responds to IE Bulletin 83-03 re check valve failures in raw water cooling sys of diesel generators No check valves installed in cooling water sys at facilities BECKHAH.J T Georgia Power Co 83/06/08 O'REILLY.J P Region 2. Office of Director 3pp 17056 075 24X Fiche 50-321.83/06/08. 8306270264
- B303110464 IE Info Notice B3-36. "Impact of Security Practices on Safe Operations " Syc list encl. JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post B30103) B3/06/09 Consolidated Edison Co. of New York: Inc. J19pp 18830 280 24% Fiche, 50-000, 83/06/09, 8305110464
- 8305110470 IE Info Notice 83-30, "Defective Heat Sink Adhesive & Seismically Induced Chatter in Relays Within Printed Circuit Cards." By: list encl JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co. of New York. Inc. 118pp 18920.225 24% Fiche 50-000,83/06/13.8305110470
- 8304090D10 IE Info Notice 83-97, "Transformer Failure Resulting From Degraded Internal Connection Cables " Svc list enc] JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/13 Consolidated Edison Co of New York, Inc 243pp 18921 001 24X Fiche 50-000,83/04/13,8304090010
- E306290254 Ack receipt of 830526 ltr informing NRC of steps taken to correct violations noted in IF Insp Repts 50-321/83-07 & 50-326/83-07 LEWIE.R C Division of Project & Resident Programs 83/06/16 MELLY, R J Georgia Power Co ip. 19056 058 24X Fiche 50-321,63/06/16.8306290254
- --9306290265 Responds to NRC 830421 ltr re violations noted in IE Insp Repts 50-321/83-07 & 50-346/83-07 Corrective actions valve handwheels being painted orange, adjustable wrenches removed & procedures for key lock switches revised BECKHAM, J T Georgia Power Co 83/05/26 O'REILLY, J P Region 2. Office of Director 4pp 19096 059 24X Fiche 50-321, 83/06/16,8306290254
- --8306290278 Forwards IE Insp Repts 50-321/83-07 & 50-366/83-07 on 830122-0226 & notice of violation LEWIS.R.C Division of Project & Resident Programs 83/04/21 KELLY.R J Georgia Pawer Co. 2pp. 19056 063 24X Fiche: 50-321
- --8306290293 IE Inap Repts 50-321/83-07 & 50-366/83-07 on 830122-0226 Noncompliance noted failure to implement procedures properly re-primary containment atmospheric control sys & operation of safety-related sys, CRLENJAK, R V : HOLMES-RAY, P. Region 2, Office of Director BROWNLEE, V L Division of Project & Resident Programs 83/04/12 opp 19056 067 24X Fiche 50-321,83/06/16,8306290254,
- B306270298 Ack receipt of B30523 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-321/83-08 & 30-366/83-08 LEWIS-R.C Division of Project & Resident Programs B3/06/16 KELLY-R J Georgia Pawer Co 1p. 19056 017 24X Fichs 50-321.83/06/16/8306290298
- ~-8306270303 Responds to NRC 830421 ltr re violations noted in IE Insp. Repts 50-321/83-08 & 50-366/83-08 Corrective actions. Procedure HNP-9 will be reviewed & revised to clarify requirements for revising procedures. GUCHA,L T. Georgia Power Co. 83/05/23 D'REILLY, J.P. Region 2, Office of Director. 2pp. 19056-018 24X Ficher50-321,83/06/16,8306290298.

- --8306290312 Forwards IE Insp Repts 50-321/83-08 & 50-366/83-08 on 830314-18 & 25 & notice of violation LEMISR C Division of Project & Resident Programs 83/04/21 KELLY.R J Georgia Power Co 2pp 19056 020 24X Fichs 50-321
- --8306290317 Notice of violation from insp on 830314-18 & 25 * Region 2. Office of Director 83/04/21. ip 19056 022 24X Fiche 50-321. 83/06/16, 8306370278
- --8306290332 IE Insp Repts 50-321/83-08 & 50-366/83-08 on 830314-18 & 25 Noncompliance noted failure to revise Procedure HNP-2-3801, Rev 17, per Procedure HNP-9 requirements CIRARD,E H , ROBS,W J , BLAKE,J J Region 2, Office of Director. 83/04/20 13pp 19056 023 24X Fiche 50-321,83/06/16,8306290298
- 8305110475 IE Info Notice 83-40. "Need to Environmentally Qualify
 Epary Orouts & Sealers " Byc list encl
 JURDAN, E.L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/06/22 Consolidated Edison Co of New
 York, Inc 115pp 19021 179 24X Fiche 50-000,83/06/22,8305110475
- B305110477 IE Info Notice B3-41, "Actuation of Fire Suppression Sqs Causing Inoperability of Safety-Related Equipment" Svc list encl JCRDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post B30103) B3/06/22 Consolidated Edison Co. of New York. Inc 120pp. 18979 007 24X Fichs 50-000.83/06/22.8305110477
- 8305110479 IE Info Notice 83-42, "Reactor Mode Switch Malfunctions "
 Svc list encl
 JURDONNE L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/06/23 Consolidated Edison Co of New
 York, Inc 1169p. 18996 242 24X Fiche 50-000,83/06/23,8305110479
- 8306300085 Responds to B30602 notice of violation & proposed imposition of civil penalties for violations noted in IE Inep Repts 50-321/83-09, 50-366/83-09 & 50-366/83-10. Corrective actions Procedure HNP-6921 revised BECKHAM.J T Georgia Power Co 63/06/23 Director's Office, Office of Inspection and Enforcement App 19048 254, 24X Fiche 50-321,83/06/29,8306300085
- 8305110483 IE Info Notice 83-43. "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints " Svc list onel JORDAN,E, L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/24 Consolidated Edison Co. of New York, Inc. 116pp 17046 297 24X Fiche 50-000.83/06/24,8305110483
- R Periodic operating reports & related correspondence
- 8306170382 Monthly operating rept for May 1983 W/830610 ltr. REDWANZ,F J , NIX,H C. Georgia Power Co. 83/06/10 Director's Office. Office of Inspection and Enforcement 23pp 18880 255. 24X Fiche 50-321,83/06/10,8306170382
- 8 Reportable occurrences, LERs & related correspondence
- 8304070259 LER 83-028/03L-0 on 830420.8 plant svc water isolation valve 2P41-F316B failed to auto-close upon loss-of-sys-pressure signal initiation Causa under investigation W/830601 ltr TIPP8:8 B., NIX.H.C. Georgia Power Co. 83/06/01 0'REILLY, J P Region 2, Office of Director 4pp 18746 084. 24X Fiche 50-366,83/06/01.8306070259
- 8306130264 Updated LER 81-098/03X-1 on 811007,RHR svc water pumps 8 k D found incapable of stablishing required flow.Caused 2004 and 2004
- 8306200004 LER 83-034/01T-0, on 830825, select isotopes identified but omitted from process computer E BAR library when program originally initiated Caused by incorrect computer program. Library will be corrected, W/630606 ltr. TIPPS, 8 B, NIX.H C Opengia Power Co. 83/06/06. O'REILLY, J. P. Region 2, Office of Director 4pp. 18903 256 24X Fiche 50-366,83/06/06,8306200004.
- B306200205 LER B3-035/03L-0: on B305ii, standby gas treatment (SB0T) humidity controllers 2T46-N015B & 2t46-N017B out of calibr & B80T train B inspensible. On B30525 8B0T train B carbon filter would not remove 99% test gas W/B30606 ltr.
 TIPPS, 8 B, NIX, H C. Georgia Fower Co. B3/06/06 O'REILLY, J. P. Region 2. Office of Director App. 18703; 208. 24% Fiche: 50-366, 83/06/06 B306200205.

- 8306270328 LER 83-031/017-0 on 830530, while performing fuel movement operation Procedure (HNP-2-9302), if fuel assemblies discovered loaded out of proper core orientation Caused by personnel error. Individual counseled W/830609 ltr TIPPS, 8 B , NIX.H C. Georgia Power Co. 63/06/09. 0'REILLY, J P Region 2, Office of Director App. 18993-047 24x Fiche. 50-366,83/06/09,8306270328.
- 8306280468 LER 83-021/03L-0 on B30516, during reactor coolant instrumentation line excess flow check valve operability Procedure (HNP-2-3760), five valves failed Caused by component failure. Valves freed or replaced M/830615 ltr TIPPS, 8 B. NIX,H C. Georgia Power Co. B3/06/15 D'REILLY,J P Region 2. Office of Director. 4pp 19020 129 24X Fiche: 50-366,83/06/15,8306280468

V Operator Examinations

- B306140486 Forwards summary of 830503 meeting re NRC policies on senior operator licensing exam Tach Spec memorization requirements Hritten exam requirements specified in draft Examiner Std EB-402 List of attendess encl DANCE, H.C. Division of Project & Resident Programs 83/05/24 BECKHAM, J.T. Qeorgis Power Co. 4pp. 18843.090 24X Fiche 50-000,83/05/24,8306140486
- --B306140493 Requests meeting to discuss NRC policies on senior operator licensing stam Tech Spac memorization requirements. Summary of Tech Spac sections covering required memorization entl. BECKHAH, J. T. Georgia Power Co. B3/03/11 WILSON, B. Region 2, Office of Director 2pp. ISB43.094 24X Fiche 50-000, 83/05/24, 8306140486.

DOCKET 50-367 BAILLY GENERATING STATION

Adjudicatory correspondence

- 8306230368 Responds to 830607 ltr re status of Business & Prof People for Public Interest application for fees under Equal Access to Justice Act Final Comptroller General opinion will not be issued for at least 1 month FIT20ERALD, J A Office of the General Counsel. 83/06/22 MHICHER, J M Businessen for the Public Interest 1: 18944 129 24X Fiche: 50-367,83/06/22,8306230368
- --8306230370 Requests status of Business & Prof People for Public Interest 820604 application for fees under Equal Access to Justice Act.
 WHICHER J M. Businessmen for the Public Interest 83/06/07 PLAINE, H H Office of the General Counsel. 2pp. 18744-130 24X Fiche: 50-367,83/06/22,8306230368

DOCKET 50-368 ARKANSAS NUCLEAR ONE, UNIT 2

F. Sacurity, medical, emergency & fire protection plans

- 8306070298 Submits supplemental response to IE Insp Repts 50-313/82-33 & 50-368/82-33 Completion date for revised procedures refire barriers changed to 830531 Addl time necessary to incorporate App R changes.

 MARSHALLJ R. Arkanses Power & Light Co 83/04/12 SEIDLE, H. C. Region 4, Office of Director in 18740-313, 24X Fichs: 50-313, 83/04/12, 8306070298
- 8306010101 Forwards IE Insp Repts 50-313/83-05 & 50-348/83-05 on 830314-17 No noncompliance noted, Open items will be examined during future insp.
 BEIDLE M. C. Region 4: Office of Director 83/05/12 ORIFFIN, J M Arkansas Power & Light Co. 2pp 18674.117. 24X Fichs. 50-313, 83/05/12, 8306010101
- --830&010107 IE Insp Repts 50-313/83-05 & 50-368/83-05 on 830314-17 No noncompliance noted. Major areas inspected. licensee parformance & capabilities during full-scale exercise of emergency plans & procedures.

 HACKNEY, C. A., MANN. J. BROWN.P. Region 1, Defice of Director 83/05/09, 28pp. 18674:119. 24X Fiche: 80-313, 83/05/12, 8306010101.
- 830603007B Forwards safety evaluation or safe shutdown capability in event of fire. Commitment requested for source range neutron flux monitoring capability & schedules for submittals by 83002B.

 STOLI, U.F. Operating Reactors Branch 4. CLARK, R.A. Operating Reactors Branch 3. 63/05/13 GRIFFIN, J.M Arkansas Power & Light Co. 2pp. 18733: 249. 24X Fiche: 50-313, 63/05/13, 8306030073.
- --8306030078 Bafety evaluation re 10CFR50 App R:Items III.0.3 & III L, re safe shutdown capability.Util design acceptable. " Office of Nuclear Reactor Regulation, Director. 83/05/13. 13pp. 18733.251. 24X Fiche:B0-313.83/05/13.8306030073

- 8304090313 Documents recent telcon re 830315 Tech Spec change request to increase emergency plan & contingency plan audit frequency Spec applies to both plans MARSHALL. JR Arkanses Power & Light Co 83/05/17 CULLING, JT Region A. Office of Director ip 18/95 227 24X Fiche 50-313,83/05/17,8304090313
- 8306090248 Provides status of transpent brochure distribution programme Purchase order for holders issued & delivery expected by 830606 MARSHALLJ R Arkansas Power & Light Co 83/05/23 COLLINS, J T Region 4. Optice of Director ip 18795 318 24X Fiche 50-313, 83/05/23, 8306090248
- 830.606.0063 Ack receipt of 830429 partial response to 8206.25 Emergenty Plan Evaluation Repts 50-313/81/22 & 50-368/81-21 Response addressing all outstanding deficiencies by revised plan or schedule for plan rev requested SEIDLE.W C. Region 4. Office of Director 83/05/31 GRIFFIN.J M Arkansas Power & Light Co 2pp 18723 271 24X Fiche 50-313,83/05/31.8306040063
- ~~8306060067 Responds to NRC 820625 evaluation of emergency plans Nuclear contingency plan a procedures & emergency plan being reviewed & revised Response to deficiencies identified by rays encl MARSHALLJR Arkansas Power & Light Co 83/04/29 COLLINS, JT Region 4, Office of Director 17pp 18723 273 244 Fiche 50~313,83/05/31,830606063
- 8306080012 Notifies of commitment to install source range monitoring capability on alternate shutdown sys, per 830313 lt; & 10CFR3D App R.
 MARSHALL, J R. Arkansas Power & Light Co. B3/06/03 STDLZ, J F.
 Operating Reactors Branch 4 CLARK, R.A. Operating Reactors Branch 3 2pp 18773 249 24X Fiche 50-313,83/06/03,8306080012
- 8306140155 Notifies that 1 h fire barriers installed by 830422,per 820327 request for schedular exemption from App R requirements for installation of barriers to 830501 MARSHALL, J R. Arkansas Power & Light Co B3/06/08 STDLZ, J,F Operating Reactors Dranch 4 CLARK, R A Operating Reactors Branch 3 Ip 18839 073 24X Ficho 50-313.83/06/08.8306140155
- 8306230474 Submits addl info re radiation filtration sys for emergency control ctr (ECC), per NUREO-0737, Suppl 1 on emergency response Radiation filtration sys designed to be manually activated Sketch of ECC filtration sys encl.

 MARBHALL.J R Ankaness Power & Light Co 83/06/17 STOLZ, J F Operating Reactors Branch 4 3pp 18741 307 24X

 Fiche 50-313,83/06/17,8306230474
- 8306240469 Requests exemption from 10CFR50 48(c) for all barriers, penetrations & fire suppression/detection sys be made more specific & detailed by identifying each area requiring exemption Schedule for submittal requested in 20 days STOLZ-JF Operating Reactors Branch 4 CLARK,R A Operating Reactors Branch 4 CLARK,R A Operating Costors Branch 3 83/06/17 @RIFFIIN.JM Arkansas Power & Ligh Co 2pp 18978 085 24X Fiche 50-313.83/06/17.8306240467

J Insurance & indemnity information

- 8306030274 Forwards certificate of insurance Policy X82-002 for CY83 MARSHALL JR Arkansas Power & Light Co 83/04/22 DINITZ, I Office of Resource Management, Director 2pp 18703 327 24X Fiche 50-313, 83/04/22, 8306030274
- P Operating license stage documents & correspondence
- 830.6010024 Forwards "Policy Statement re Alcohol/Drug Abuse & Theft;" issued as part of util policies & procedures manual, per 830309 commitment MARSHALL, J.R. Arkansas Power & Light Co. 83/05/12 COLLINS, J.T. Region 4. Office of Director ip 18674-070 24X Fiche 50-313, 83/05/12, 8306010024
- --8306010028 "Policy Statement re Alcohol/Drug Abuse & Theft" + Artansas Power & Light Co 83/05/03 2pp 18674 071 24X Fiche: 80-313, 83/05/12, 8306010024.
- 8306090313 Documents recent telcon re 830315 Tech Spec change request to increase emergency plan & contingency plan audit frequency. Spec applies to both plans MARSHALL.J.R. Arkanese Power & Light Co. 83/05/17, COLLINS.J.T. Region 4. Office of Director pp. 18795-227, 24X Fiche 50-313.83/05/17.8306090313

- B30&020135 Comments on App B Tech Spec revs.per B3031] Itr issuing Amends 72 & 40 to Licenses DPR-52 & NPF-6, respectively Util will routinely provide NRC w/changes to NPDES discharge permit MARSHALL,J R Arkansas Power & Light Co 83/05/20 STOLZ,J F Operating Reactors Branch 4 CLARK,R A Operating Reactors Branch 3 2pp 18691 244 24% Fiche 50-313.03/05/20.830&020135
- 8306020466 Submits supplementary info re unviron qualification of Category II b items, in response to NRC requests Rosemount transmitter satisfied all acceptance criteria MARSHALL, J.R. Arkansas Power & Light Co. 83/05/26 CLARK, R.A. Operating Reactors Branch 3 2pp. 10673 199 24X Fiche 50-368,83/05/26,8306020466
- 830.6070054 Provides results of technical evaluation of need to upgrade core protection calculator local power density penalty factor software & proposed implementation scheduls.per 830414 commitment MARSHALL.J.R Arkansas Power & Light Co 83/05/31 CLARK.R A Opprating Reactors Branch 3 2pp 18740 083 24X Fiche 50-360.83/05/31.8306070054
- 6306200059 Advises that NUREG-0737. Items II F 1 4.II F 1 5 & II F 1 6 requirements resolved per 801219. 820726 & 830408 submittals Environ qualification of equipment will be revisued separately SER encl STOLZ. J F Operating Reactors Branch 4 CLARK.R A Operating Reactors Branch 4 CLARK.R A Operating Co 7pp 18908 302 24X Fiche 50-313.83/06/06.8306200059
- 8306200055 Requests that submittal of justification for conclusion that shoulder gap clearance of 16x16 fuel will not be safety concern for Cycls 4 operations Preliminary results of Cycls 3 fuel insps also requested CLARK, R A Operating Reactors Branch 3 89/06/08 ORIFFIN, JARKANSA POWER & Light Co. 3pp 18908 R92 24X Fiche 50-368.89/06/08,8306200055
- 8306170275 Responds to NRC 830507 request for submittal of license amend applications incorporating snubber survaillance program into App A Tech Space Program autilined in 830228 11; will be followed pending NRC review of ANSI OH-4 Btd MARSHALL, JR Arkansas Power & Light Co 83/06/10 870LZ, JF Operating Reactors Branch 4 CLARK, R. A Operating Reactors Branch 3 2pp 18878 257 24X Fiche 50-313,83/06/10,8306170275
- 8306210229 Responds to 830411 ltr re steam generator reactor protection sys (RPS) bypass Boron dilution alarm installed & will be operational following operator training Need to bypass steam generator RPS low & high level inputs in Mode 5 negated MARSHALL, J.R. Arkansas Power & Light Co. 83/06/17 CLARK, R. A. Operating Reactors Branch 3 2pp. 18715 187 24X Fiche 50-368.63/06/17,6306210229,
- B306230487 Forwards justifications for continued operation for environ qualification deficiencies in NRC Categories I B.II.A & IV. in response to NRC B30415 BER & associated technical evaluation rept Flooding issue adequately addressed MARSHALL.J R Arkensas Power & Light Co 83/06/20 CLARK, R A Decating Rescotors Branch 3 ildept 18941 185 24X Fiche 50-368,83/06/20,8306230487
- @ Inspection reports. IE Bulletins & correspondence
- 830&080192 Forwards IE Insp Rept 50-313/8R-36 & 50-368/82-37 on 821213-16 & notice of violation 8E104E.W C Region 4. Office of Director 83/03/04. GRIFFIN, J M Arkansas Power & Light Co. 2pp 1877; 161 24X Fiche 50-313,83/03/04,830&080192
- --8304080197 Notice of violation from insp on 821213-16 * Region 4: Office of Director. 83/03/04 2pp 18771:163 24X Fichs.80-313.83/03/04.8304080192
- --8306080238 IE Insp Rept 50-313/82-36 & 50-368/82-37 on 801213-16
 Noncompliance noted update of Unit 1 FSAR showed radiation
 zones less than 100 m/h.when actual survey data indicated
 radiation levels exceeded 100 m/h
 CHANEY.H, D. WILBORN.L. MURRAY.B Region 4, Office of Director,
 83/02/28 17pp 18771 165 24X Fiche, 50-313, 83/03/04, 8306080192.
- B3Q6160537 Responds to 821025 IE Insp Repts 50-313/82-14 & 30-368/82-11. Item 8 re control room dose calculations Item re NUREO-0737. Item II 8 2, "Plant Shielding," closed, AARSHALL.J R Arkansas Power & Light Co. 83/03/24. COLLING.J T Region 4. Office of Director 2pp 18869 I15 24X Fiche. 50-313,83/03/24,8306160537

- 8306070278 Submits supplemental response to IE Insp Repts 50-313/82-33 & 50-348/82-33 Completion date for revised procedures refire barriers changed to 830521 Addition necessary to incorporate App R changes
 MARSHALL.JR Arkansas Fower & Light Co 83/04/12 SEIDLE, W C Region 4, Office of Director ip 18740 313 24X
 Fiche 50-313,83/04/12,8306070278
- #306010101 Forwards IE Insp Repts 50~313/#3-05 & 50~364/#3-05 on 830314-17 No noncompliance noted Open items will be examined during future insp SEIDLE.W C Region 4. Office of Director 83/05/12 GRIFFIN, J M. Arkansas Power & Light Co 2pp 18674 117. 24X Fiche 50-313.83/05/12.8306010101
- --8306010107 IE Insp Repts 50-313/83-05 & 50-368/83-05 on 830314-17, No noncompliance noted Major areas inspected licenses performance & capabilities during full-scale exercise of emergency plans & procedures HACKNEY, C A. BANGART, R L., HOLLEY, W. L. Region 1, Office of Director 83/05/09 28pp 18674 119, 24X Fiche 50-313,83/05/12,8306010101
- 8306140359 Forwards IE Insp Repts 50-313/83-09 & 50-368/83-09 on 830401-30 No noncompliance noted 8EIDLE, M. C. Region 4. Office of Director 83/05/18. QRIFFIN, J. M Arkansas Power & Light Co. 2pp 18832 143 24X Fichs 50-313, 83/05/18, 8306140359.
- --B306140363 IE Insp Repts 90-313/B3-09 & 50-368/B3-09 on B30401-30, No noncompliance noted Major areas inspected operational safety verification followup on reactor trip breaker failurs & plant startup after refueling.

 CALLAN.L J., CUMMINB.J E., JOHNSON.W.D. Region 4, Office of Director B3/05/16 opp IBB32-145 24X Fiche 50-313.83/05/18, B306140359
- 8306130222 Updates status of efforts & progress re drawing control. Progress made in program to update mylars transferred from corporate ofc. As of 830511, 2:714 drawings updated k reissued Info responds to IE Bulletin 80-06 MARSHALL. JR Arkansas Fower & Light Co. 83/05/23, 881DLE, W.C. Region 4. Office of Director. 3pp 18926-324, 24X Fiche 50-313,83/05/23,8306130222
- 8305110458 IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in Well Logging Device." Svc list encl. TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 63/05/26 Consolidated Edison Co. of New York, Inc. 125pp 18831:043, 24X Fiche 50-000,83/05/26.8305110458.
- 8305110460 IE Info Notice 83-94, "Event Notification Info Worksheet,"
 Svc list encl
 JORDAN,E L Division of Emergency Preparadness & Engineering
 Response (Post 830103). 83/05/26 Consolidated Edison Co. of New
 York Inc 115pp 18732,085, 24X Fiche 50-000,83/05/26,8305110460
- 8305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods Withdrawn at BWRs " Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/03/31 Consolidated Edison Co. of New York Inc (16pp 18732 208 24X Fiche 50-000,83/05/31,8305110461
- 830.6060063 Ack receipt of 830429 partial response to 820625 Emergency Plan Evaluation Repts 50-313/81-22 & 50-368/81-21 Response addressing all outstanding deficiencies by revised plan or schedule for plan rev requested BEIDLE.M. C. Region 4, Office of Director. 83/05/31. QRIFFIN.J.M. Arkansas Power & Light Co. 2pp. 18723:271. 24X Fiche.50-313,83/05/31,8306060063.
- --B306060067 Responds to NRC B206R5 evaluation of emergency plans. Nuclear contingency plan & procedures & emergency plan being revisued & revised. Response to deficiencies identified by revs encl.

 MAMBHALL, J. R. Arkansas Power & Light Co. B3/04/29. COLLINS, J. T. Region 4, Office of Director 17pp. 18723, 273 24X Fiche 50-313, 83/05/31,8306060063.
- 830&070380 Ack receipt of 830517 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 30-313/83-0& & 50-368/83-0&.

 SEIDLE-M.C. Region 4, Office of Director. 83/06/02. ORIFFIN.J.M. Arkansas Power & Light Co. 2pp. 18741-346. 24% Fichs.50-313,83/06/02,8306070380
- --B306070384 Responds to NRC 830418 ltr re violations noted in IE Insp. Repts 50-313/83-06 & 50-368/83-06 Corrective actions: procedures revised to define interface responsibilities & coordination required for radioactive shipments, MARSHALL, J.R. Arksnass Power & Light Co. 83/05/17. SEIDLE, W.C. Region 4. Defice of Director. 4pp 18741.348. 24X Fiche 50-313,63/06/02.6306070380

- --8306210097 "Summary Rept of Radiological Aspects of Mod of McGuire Nuclear Station.Unit 1 Steam Generator " * Duke Power Co : 83/06/15 19pp 18919 195 24X Fithe 50-349.83/06/18,8306210092
- 8306240205 Provides info re DS-416 Undervoltage trip attachments to be utilized in NRC evaluation of facility, per B Wright request RAME.E P Westinghouse Electric Corp 83/06/17 DENION.H Dffice of Nuclear Reactor Regulation, Director 4pp 18980 246 24X Fiche 50-369.83/06/17.8306240205
- 8306280027 Forwards notice of consideration of issuance of amend to OLs & proposed no significant hazards consideration determination & opportunity for hearing re 82:123 reactor coolant flow rate computation method submittal M/o encl ADENSAME Q Licensing Branch A 83/06/21 TUCKFR:H B Duke Power Co ip 19042.358 24X Fiche:50-369.83/06/21.8306280029
- 8306300002 Forwards responses to questions raised in 830617 telcom retesting of Type DB-416 circuit breaker undervoltage & shunt trip attachments for reactor trip switchgear Test description supplementing 830603 submittal encl TUCKER, H. B. Duke Power Co. 83706728 DENTON H. R. Bffice of NUCKER, H. B. Duke Power Co. 83706728 DENTON H. R. Bffice of Nucker Regulation, Director ADENSAN E. C. Licensing Branch 4 16pp. 19120:333 R4X Fiche 30-369, 63706728, 8306300002
- @ Inspection reports. IE Bulletins & correspondence
- 8306140530 Forwards IE Insp Repts 50-369/83-17 & 50-370/83-24 on 830411-19 No noncompliance noted. DANCE,H C Division of Project & Resident Programs 83/05/17 TUCKER,H B Duke Power Co 2pp 18840 258 24X Fiche 50-369,83/05/17,8306140530
- --8306140537 IE Inap Repts 50-369/83-17 & 50-370/83-24 on 830411-19 No noncompliance noted Major areas inspected review of outstanding insp items, snubber inservice inap & testing & witnessing Unit 1 integrated leak rate test WHITEMER, H. L. Region 2. Office of Director JAPE, F. Division of Engineering & Radiological Safety Programs 93/05/12 Upp 18843 260 24X Ficha 50-367,83/05/17.8306140530
- 8305110458 IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in Hell Logging Device." Svc list encl TAYLOR.J,N Division of Bafeguards & Inspection Programs (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 125pp. 18831:043. 24X Fiche:50-000,83/05/26,8305i10458
- 8305110460 IE Info Notice B3-34, "Event Notification Info Worksheet" Svc list encl JORDAN, EL Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 115pp. 18732:085 24x Fiche 50-000,83/05/26,8305110460
- 8305110461 IE Info Notice 83-95, "Fuel Movement W/Control Rods Hithdrawn at BMRs." Byo list encl, JORDAN,E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83705/31 Consolidated Edison Co of New York, Inc. 116pp 18732, 208 24X Fiche: 50-000, 83/05/31, 8305110461
- 8306290282 Forwards response to IE Bulletin 63-03, "Check Valve Failures in Raw Mater Cooling Sys of Diesel Generators." No check valves installed in cooling mater sys at facilities TUCKER, M.B. Duke Fower Co. 83/06/07 O'REILLY. J. P. Region P. Defice of Director 2pp. 19056 036. 24X Fiche 50-369,83/06/07,830620020
- 8306270517 Forwards IE Insp Repts 50-369/83-20 & 50-370/83-27 on 830502-12 No noncompliance noted. DANCE.H.C. Division of Project & Resident Programs 83/06/08 TUCKER.H B Duke Power Co. 2pp. 19052-186. 24% Fichs.50-367.83/06/08.8306270517.
- --8306290519 IE Insp Repts 50-369/83-20 & 50-370/83-27 on 830502-12 No noncompliance noted. Major areas inspected; preoperational test results, surveillance testing, post-mod startup of Unit 1 & instial criticality of Unit 2 Bushett, P T , THOMAS.M , JAPE.F. Region 2, Office of Director, 83/06/07 7pp. 19052-188. 24X Fiche 50-369,83/06/08,8306290517.
- 8305110464 IE Info Notice 83-36, "Impact of Security Practices on Safe Operations," Syc list encl. JORDAN.E.L. Bytsion of Emergency Praparedness & Engineering Response (Post 630103). 82/06/09. Consolidated Edison Co. of New York, Inc. 119pp 18630, 280, 24X Fiche, 50-000, 83/06/09, 8305110464.
- 8305110470 IE Info Notice 83-38. "Defective Heat Sink Adhesive & Beismically Induced Chatter in Relays Within Printed Circuit Cards " Byr list ench. JORDAN.E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/10. Consolidated Edison Co. of New York Inc (18pp. 18920, 225 24X Fiche: 50-000, 83/06/13, 8305110470

- 8306090010 IE Info Notice 83-37. "Transformer Failure Resulting from Degraded Internal Connection Cables " Svc list enc) JORDAN-E L Division of Emergency Properadness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co of New York Inc 243pp 18921 001 24X Fiche 50-000-83/06/13,030609080
- 8306170151 Forwards IE Safeguards Insp Ript 50-369/83-23 on 830524-26 No noncompliance noted DANCE,H C. Division of Project & Resident Programs 83/06/14 TUCRER,H B. Duke Power Co. 2pp. 18078-311 24X Fiche 50-369, 03/06/14,8306170151
- --8306170162 IE Safeguards Rupt 50-369/89-23 on 830524-26 No noncompliance noted Major area inspected review of licensee investigation of appeared willful manipulation of non-vital equipment Details withheld (ref 10CFR73 21) TOBIN.W J Region 2. Office of Director MCGUIRE.D R Division of Emergency Preparedness & Materials Bafety 83/06/14 Ip 18678 313 24X Fiche 50-369,83/06/14.8306170151
- 8305110475 IE Info Notice 83-40, "Need to Environmentally Gualify
 Epoxy Grouts & Bealers " Svc list encl
 JORDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/06/22 Consolidated Edison Co of New
 York, Inc 115pp 19021 179 24X Fiche 50-000,83/06/22,8305118475
- 8305110477 IE Info Notice 83-41, "Actuation of Fire Suppression Sys Causing Inoperability of Safety-Related Equipment " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/22 Consolidated Edison Co of New York, Inc 120pp 18997 007 24X Fiche 50-000,83/06/22,8305J164/7
- 8305110479 IE Info Notice 83-42. "Reactor Mode Switch Malfunctions Swc list encl JORDAN,E L Division of Emalgency Preparedness & Engineering Response (Post 830103) 83/06/23 Consolidated Edison Cn of New York, Inc 116pp 18996 242 PAX Fiche 50-000,03/06/23,8305110479
- 8305110483 IE Info Notice 83-43, "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/24 Consolidated Edison Co of New York, Inc 114pp 19046 297 24X Fiche 50-000,83/04/24,8305110403
- R Periodic operating reports & related correspondence
- B306170311 Monthly operating ropts for May 1983 W/800615 ltr REAVIS.J A. TUCKER.H 8 Duke Power Co B3/06/15 Director's Office. Office of Inspection and Enforcement Bpp 18877 105 04x Fiche 50-369.83/06/15.8306170311
- 8 Reportable occurrences, LERs & related correspondence
- B306010401 LER 83~020/017-0 on 830503, soap bubble test of 47 secondary containment bypass leakage paths not performed during initial integrated leak rate test Caused by procedural deficiency Procedures revised W/030817 ltr
 NARDOCI,P B , TUCKER H B Duke Power Co 83/05/17 O'REILLY, J P
 Region 2, 06761ce of Director 4pp 18682 245 24X
 Fiche 50~369,83/05/17.8306010401
- 8304010256 LER 83-021/03L-0 on 830419, while in Mode 5, nuclear svc water sys valve IRN 69 actuator w/mechanical latch replaced by actuator requiring electrical antihammer circuit Caused by deficient procedure W/830519 IT NARDOCI.P B . TUCKER.H B Duke Power Co 83/05/19 O'REILLY, J.P. Region 2, 04715cc of Director 2pp 18672 292 24X Fiche. 50-369, 83/05/19, 8306010266
- 8304010098 LER B3-023/01T-0 on B30504, discovered that RHR sys (ND) train A improperly declared operable on B30423 & subsequent change from Mode 5 to Mode 4 occurred on B30428 Caused by water hammer failures W/B30520 ltr NARDOCI,P B, TUCKER,H B Duke Power Co 83/05/20 O'REILLY,J P Region 2. Office of Director 4pp 18674 111 24X Fiche.50-349, B3/05/20, B304010090
- 8306010123 LER 83-022/03L-0 on 830421, bellows leak test not performed on penetration M354 after initial integrated leak rate test Caused by procedural deficiency since penetration not listed in initial procedures W/83050 ltr NARDGC1.P B , TUCKER.H B Duke Power Co. 83/05/20 O'REJLLY.J P Region 2. Office of Director. 2pp 18674 019 24X Fiche 50-369,83/05/20.8304010123

- 8306070143 LER 83-018/03L-0 on 83040/, following identification of inoperable RHR tys (ND) hange: & snubbers, sys welkdown revealed add1 hanger failure (aused by ND sys water hammer Hangers repaired & procedures revised W/030520 ltr NARDQC1,P B TUCKER,H B Duke Power Co 83/05/20 O'RE1(17,J P Region 2, Office of Director 5pp 18/39 228 24X Fiche 30-369,03/05/20.8306070143
- 830A090147 LER 83-024/03L-0 on 830424, Fire Door 1000B declared inoperable when damage, consisting of birt door, broken hinge, bent hinge, broken door lock & broken door closer discovered Cause unknown fire watch established W/G30524 ltr NARDGCI, P.B., TUCKER, H.B. Duke Power Co. 83/05/26 O'REHLLY, J.P. Region 2, Office of Director 2pp 16/92 303 24X Fiche 50-349,83/05/26.8304090147
- 8306130342 LER B3-025/03L-0 on B30508, while in Mode P, fire detection sys Zones 72 & 149 declared inoperable due to alarms remaining in alarm condition Fire watch patrols established Caused by control interface module failure W830527 ltr NARDOCI,P B , TUCKER.H B Duko Power (o. 83/05/2/ 0'REILLY, J P Region 2. Office of Director 28pp 18022 280 74X Fithe 50 369,83/05/27.8306130042
- 8306130448 LER 83-026/03L-0 on 830430 per formance of RCB leakage calculation determined unidentified leakage greater than 1 spec Caused by leakage past bornet seal ring on valves INC-18 to INC-237 Valves sealed W/030507 ltr MARBOCI.P B . TUCKER.H B Duke Power Co 83/05/27 O'REILLY, J P Region 2. Office of Director 2pp 16021 034 24X Fiche 50-369.83/05/27.8306130446
- 8306200212 LER 83-027/03L-0 on 830505, discovery of water in outside an pressure filter train 2 led to control area ventilation systrain B inoperability Caused by water backflow through drain lines into filter package Filter cloaned 4/830603 ltr NARDRCI,P B . TUCKER, B 0 Duke Power C 83/06/03 0'RELLLY, J P Region 2, Office of Director 2pp 10702,277 24X Fiche 50-369,83/06/03.8306200712
- 9304200245 LER 83-028/017-0 on 830525, impulse lines for two redundant steam generator ID level instruments came within 2 inches of each other at one point Caused by const/installation deficiency One line rerouted W/830408 ltr NARDACI, P B., TUCKER-H. B. Duke Power Co. 83/04/08 D'REILLY, J P. Region 2. Office of Director 4pp 18702 344 24X Fiche 50-349,84/04/08,8304200045
- B306200237 LER B3-029/03L-0 on G305i0 & 15.boron concentration dropped below 1,900 ppm in cold leg injection accumulator Caused by leakage into accumulator from RCB through check valves INI70 & iNI71 Valves repaired W/B30609 1tr NARDQCI.P B . TUCKER.H B. Duke Power Co 83/06/09 D'REILLY, J P Region 2, Office of Director 2pp 18902 342 24X Fiche 50-369,83/06/09,830620009J
- 8306270094 RO on 830527.containment pressure control sys monthly surveillance not performed at required interval & when performed.pressure found out of allowable limits Analysis incomplete Ropts will be submitted by 830624
 TUCKER. H. D. Duke Power Co. 83/06/07 O'REILLY. J.P. Region 2, Office of Director ip 18788 121 24X Fiche 50-369, 83/06/09, 8306270074
- 8306200264 LER 83-032/03L-0 on 830bi3: toutrol area ventilation systrain A failed to mest pressurisation criteria Caused by degradation of door seals & lack of trip interlocks Door seals taped & later replaced lest rerun W/8306i0 ltr MARDGCLP B . TUCKER/H B Duke Power Co 83/06/10 D'REILLY, J P Region 2. Office of Director App 18701 101 24X Fiche 50-369.83/06/10.8306200264
- B306270227 LER 83-031/03L-0:on B30812, reactor coolant gump taken out of type following sparadic low oil level alarms from pump motor 10 upper reservoir Level found slightly low. Cause not determined 011 added Pump restarted W/B30610 ltr.
 NARDQCI,P B., TUCKER.H B. Duke Power Co. 83/06/10 O'REILLY, J.P. Region 2. Office of Director 20p 18788 235 24X Fiche 50-369,83/06/10,8306270227
- 8306280427 LER 83-033/03L-0'on 830513, investigation of trouble alarm on fire detection sys received in control room that would not clear led to fire detection zone EFA 150 being declared inoperable Caused by spurious alarm. W/830610 ltr.
 NARDOCI.P B , TUCKER.H B Duke Power Co 83/06/10. O'REILLY, J P. Region 2, Office of Director 2pp 17018-348 24X Fiche, 50-369, 83/06/10, 8306280427
- 8306270124 RD 83-035, on 830515, Tech Spec 3 4 3 re pressurizer heaters each having capacity of at least 150 kW violated.
 Investigation continuing Next rept will be submitted by 830628
 TUCKEN, H B Duke Power Co 83/06/14 D'REILLY, J P Region 2, Office of Director 1p 18788 085, 24X Fiche 50-367, 83/06/14, 8306270124.

- 8306270301 LER 83-034/03L-0 on B30515, cold leg injection accumulator (CLA) "A" declared inoperable due to vol exceeding Tech Bprc limits Caused by leakage through valve seats of valves iNI-B5.1NI-B6 & INI-B7 Valves replaced W/B30614 ltr NARDOC1.P B , TUCKER.H B Duke Power Co 83/06/17 O'REILLY, J P. Region 2, Office of Director 2pp 18795 288 24x Fiche 50-369,83/06/14.8306270301
- 8306300191 Forwards LERs 83-036/03L-0 t 83-022/03L-0 TUCKER.H B Duke Power Co 83/06/23 O'REILLY, J P Region 2. Office of Director 3pp 19119 250 24% Fiche 50-369.83/06/23.8306300191
- --B306300198 LER B3-036/03L-0 on B30524 & 26.listed functional test procedures failed to satisfy monthly setpoint requirements Caused by failure to identify & incorporate changes into procedures Setpoints verified NARDOCI,P B Duke Power Co B3/06/23 ip 19119 253 24X Fiche 50-369, B3/06/23, B306300191
- --8306300204 LER 83-022/03L-0 on 830524 & 26. listed functional test procedures Pailed to satisfy monthly setpoint requirements Caused by failure to identify & incorporate changes into procedures Betpoints verified NARDOCI.P B Duke Fower Co. 83/06/23 ip 19119:254 24X Fiche 50-369.83/06/23.8306300191
- V Operator Examinations
- 830&i4034& Advises that based on results of oral exams administered to all personnel per 820825 request for waiver of exams, amended licenses will be forwarded for personnel w/appropriately submitted applications
 DANCE, H C Division of Project & Resident Programs 83/02/10 TUCKER, H B Duke Power Co ip 18832 175 24X
 Fiche 50-369,63/02/10,8306140346.
- DOCKET 50-370 WILLIAM B MCGUIRE NUCLEAR STATION, UNIT 2

 A Application/construction stage documents & correspondence
- 830&030299 Staff requirements memo re 830527 discussion/possible vote in Mashington, DC on full power OL authorization, License amend to be modified re maint of circuit breakers, Meating requested w/breaker mfg CHILK, SJ Office of the Secretary of the Commission 83/05/27. DIRCKS, M.J. Office of the Executive Director for Operations 1p. 18734-071 24% Fiche 50-370, 83/05/27, 8306030259
- E NRC Bafety Evaluation Report (SER), supple & correspondence
- B306020103 Proposes B30608 meeting in Bethesda, MD to discuss Suppl & to SER for McGuire & SER for standby shutdown facility for Ocones BTOLZ, J F Operating Reactors Branch 4 83/05/17 TUCKER, H. B. Duke Power Co 1p 18701 277 24% Fichs 50-000, 83/05/17, 8304020103.
- 8304020403 Forwards briefing package for forthcoming Commission meeting re full power operation Package includes briefing slides, BER Suppl 7.0L issued on 830303 & proposed amend.
 DIRCKS, M J. Office of the Executive Director for Operations 83/05/24 PALLADINO, N. GILINBKY, V., AMEARNE, J. Commissioners 147pp 18717 158, 24X Fiche 50-370,83/05/24,8304020403.
- 8304160665 BAFETY EVALUATION REPORT RELATED TO DEFRATION OF MCQUIRE NUCLEAR STATION, UNITS I AND 2. Docket Nos 50-369 And 50-370 (Dute Power Company)

 **Division of Licensing NUREO-0422 807 83/05/31, 100pp. 18876 164 24X Fiche 50-369,83/05/31,8306160665
- 8306230482 Forwards Suppl 7 to SER re application for OLs W/o encl. NOVAK,T M Assistant Director for Licensing. 83/06/16 TUCKER.H.B. Dute Power Co 2pp 18982 042. 24X Fiche 50-369.83/06/16, B306230682
- F Security, medical, emergency & fire protection plans
- 830.6070269 Forwards Class III & I fees for approval of use of public address sys for local fire elarms inside containment, per 830506 request TUCKER.H B Duke Power Co. 83/05/24 DENTON.H.R. Office of Nuclear Reactor Regulation, Director ADENSAM.E.G. Licensing Branch 4 ip 18740-350 24X Fiche 50-369, 83/05/24, 8306070269.
- 8306070433 Responds to 830206 ltr re physical security plan Rev 14.
 Changes consistent w/provisions of 100FR50 54(p) & acceptable
 ACCEPTABLE ADENSAM.E. O Licensing Branch 4 83/06/03 TUCKER.H B. Duke Power
 Co 2pp. 18776:347. 24% Fiche.50-369.83/06/03,8306070433

- 830609032B Ack receipt of 830506 request for approval of plans for local fire alarms inside containment Remittance of Class III fee requested DIGOS:R M Lacense Fee Management Branch B3/06/06 TUCKER,H B Duke Power Co ip 18797 110 24% Fiche 50-369.83/06/06.8306090328
- 8306270189 Forwards Rev 4 to training & qualification plan Rev withheld (ref 100FR73 21)
 TUCKER, H B Duke Power Co B3/06/14 O'REILLY, J P Region 2,
 Office of Director. 1p 18791 327 24X Fiche 50-369,83/06/14,
 B306270189

I. Financial information

- 8306200352 Forwards Annual Financial Rept 1782.
 TUCKERNH B Duke Power Co. 83706/15 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAM, E G Licensing Branch 2 2pp 18879 101 24x Fiche 50-000.83706/15.8306200352
- --8306200354 Annual Financial Rept 1782 * North Carolina Municipal Power Agencies 83/06/15 20pp. 18879 103 24% Fiche 50-000.83/06/15.8306200352

P Operating license stage documents & correspondence

- 8304020598 Forwards draft SER, NUREC-0422, Suppl 7 & "Evaluation of AcQuire Units 1 & 2 Undervoltage Trap Attachment Failures," interim technical evaluation rept & draft full power OL amend NOVAK. T K Assistant Director for Licensing 83/05/24 TUCKER
 - amend NGVAK.T H Assistant Director for Licensing 83/05/24 TUCKFR.H B Duke Power Co 44pp 18718 COI 24X Fiche 50-369.83/05/24, 8306020598
- 8306020603 Forwards briefing package for forthcoming Commission meeting re full power operation Pockage includes briefing slides. SER Suppl 7.0L issued on 830303 & proposed amend DIRCKS U J Office of the Executive Director for Operations 83/05/24 PALLADIND. N . OILINSKY. U . AHEARNEJ Commissioners 147pp. 18717 198 24X Fiche. SO-370, 83/05/24. 8306020603
- 8306030315 Forwards add) Class I fee for 830311 request for relief from ABME Code Bection XI requirement re hydrostatic testing on feedwater sqs to steam generators, in response to NRC 830511 request request
 TUCKER, H B Duke Fower Co 83/05/24, DENTON, H R Diffice of Nuclear Reactor Regulation, Director ADENSAM, E C Licensing Branch 4 ip. 18708 327, 24X Ficher 50-369, 83/05/24, 8306030315
- 8306070428 Forwards Amend 2 to License NPF-17 & notice of issuance & availability Amend requires testing of reactor trip breakers & changes license conditions for environ equipment & hydrogen control measures.

 ABENSAM.E O Licensing Branch 4 83/05/27 TUCKER.H D. Duke Power Co. 2pp 18776;338 24X Fiche 50-370.83/05/27.8306070428.
- --8306070431 Amend 2 to License NPF-17, modifying environ equipment the hydrogen control measures & requiring testing of reactor trip breakers EIBENHUT, D C Division of Licensing 83/05/27 App 19776;340 24% Fiche 50-370,83/05/27,8306070428.
- --B306070434 Notice of issuance & availability of Amend R to License NPF-17 ADENBAM, E. Q Licensing Branch 4 B3/05/27 3pp 18776 344 24X Fiche-50-370, B3/05/27, 8306070428.
- 8306070131 Forwards info supporting 821123 & B30427 applications for amend to Licenses NFF-9 & NPF-17, respectively, Bignificant hazards consideration analysis & info re penalty for undetected feedwater ventur; fouling encl.
 TUCKER, H B Duke Power Co B3706/02 DENTON, H, R Office of Nuclear Reactor Regulation, Director. ADENSAM, E Q Licensing Branch 4, App. 18739 243 24X Fiche: 50-369, 83/06/02,8306070131.
- --8306070134 Proposed Tech Specs re RCS flow rate & nuclear enthalpy ris hot channel factor measurement * Duke Power Co 83/06/02 7pp 18739 247 24X Fiche 50-369.83/06/02,8306070131
- B304070283 Forwards description of test program varifying reliability of undervoltage trip attachment on Westinghouse DS-416 breakers Submittal satisfies License Condition 2 C(12)a. NRC timely review requested TUCKER, H. B. Duke Power Co. 63/06/03 DENTON, H. R. Office of Nuclear Reactor Regulation. Director. ADENSAM, E. G. Licensing Branch 4. 3pp. 18741-214. 24X Fiche 50-369, 63/06/03, B306070283.

- 8306140680 Farwards Suppl I to "Reactor (ontainment Bidg Integrated Leak Rate Test (\$LRT)" Addendum to Section VI.Page 4 of ILRT test rept requested to close out Unit 2 ILRT outstanding items
 TUCKER. H B Duke Power Co B3/06/09 DLNTON. H R Office of Nuclear Reactor Regulation, Director ADENSAM, E G Licensing Branch 4 ip 18842 058 24X Fiche 50-370, B3/06/09, 8306140680
- ---8306140686 Suppl 1 to "Reactor Containment Bldg Integrated Lenk Rate Test (ILRT) " * Duke Power Co 83/06/07 3pp 16842 059 24X Fiche 50-370,83/06/07.8306140680
- 8306150177 Application for amend to Licenses NPF-9 & NPF-7, extending time limit for operation w/reactor coolant flow greater than 375,850 gpm & adding stricter limit for nuclear enthalpy rise hot channel factor during operation TMES, A C Duke Power Co B3/06/09 DENTON, H R Office of Nuclear Reactor Regulation. Director ADENSAN, C G Licensing Branch 4 Spp 16846 359 24X Fiche 50-369,83/06/09,830615017/
- 8306210406 Forwards notice of consideration of issuance of amend to Licenses NPF-9 & NPF-17 & proposed no significant harards determination & apportunity for hearing re setpoint tolerance for upper head injection accumulators ADENSAM.E 9 Licensing Branch 4 83/06/09 TUCKER, H B Nuke Power Co 2pp 18937 073 24X Fiche 50-369.83/06/09.8306210406
- --8306210427 Notice of consideration of issuance of amend to licenses NPF-9 & NPF-17 & proposed no significant hazards consideration determination & opportunity for hearing resetpoint tolerance for upper head injection accumulator JABBOUK, K N Licensing Branch 4 83/06/09 7pp 18937 075 241 Fichs 50-369,83/06/09,8306210406
- 8306160277 Forwards synopsis of issues & Franklin Research Ctr draft technical evaluation rept re NUREO-0612, "Control of Heavy Loads, Phase 1" W/o encis ADENSAM.E O Licensing Branch 4 83/06/10 TUCKER, H 0 Dute Pow Co 2pp 18872 170 24X Fiche 50-369, 83/06/10, 8306160277
- 8306160725 Bummary of 830324 meeting w/utils & Westinghouse in BethesdarMD re design review panel review of new Mestinghouse stress analysis on manifold fasteners for B2/D3 steam generator mod MOPKINSIJ B Licensing Branch 4 83/06/10 Licensing Branch 4 7pp 18874 277 24% Fiche 50-000,83/06/10.8306160725
- 830.6290573 Summary of Design Review Panel 630321 meeting w/utils & Westinghouse in Bethesda, MD re D2/D3 steam generator mod & Westinghouse Stress analysis of manifold fasteners HDPKINS. J. B. Licensing Branch 4 83/06/10 Licensing Branch 4 7pp 19047 085 24X Fiche 50-000,83/06/10,8306270573
- B306240205 Provides info re DB-416 undervoltage trip attachments to be utilized in NRC evaluation of facility, per B Wright request RAME, E P Westinghouse Electric Corp B3/06/17 DENTON: H Office of Nuclear Reactor Regulation, Director App 18980 246 24x Fiche 50-369,83/06/17.8306240205
- 9306280029 Forwards notice of consideration of issuance of amend to OLs & proposed no significant hazards consideration determination & opportunity for hearing re 821123 reactor coolant flow rate computation method submittal W/o encl ADENSAM, E. Q. Licensing Branch 4 83/06/21 TUCKER, H. B. Bute Power Co. 1p. 19042 358 24X Fichs 50-369, 83/06/21, 8306280029
- 830&300002 Forwards responses to questions raised in 830&17 telcon retesting of Type DB-41& circuit breaker undervoltage & shunt trip attachments for reactor trip switchgear Test description supplementing 830&03 submittal enci TUCKER, H B. Duke Power Co B3/06/28 DENTON, H R Office of Nuclear Reactor Regulation, Director ABENSAM, E G Licensing Branch 4 16pp 19120 333 24X Fiche 50-349, 83/06/28, 8306300002

Q. Inspection reports. IE Bulletins & correspondence

- 8306140830 Forwards IE Insp Repts 50-369/83-17 & 50-370/83-24 on B30411-19 No moncompliance noted BANCE: H C Division of Project & Resident Programs 83/09/17 TUCKER: H B Duke Power Co 2pp 18843 258 24X Fiche 50-369,83/05/17.8306140530
- --8306140537 IE Insp Repts 80-369/83-17 & 50-370/83-24 on B30411-19 No noncompliance noted Major areas inspected review of outstanding insp items, snubber inservice insp & testing & witnessing Unit i integrated leak rate test WHITENER, H.L. Region 2. Diffice of Director JAPE, F. Division of Engineering & Radiological Safety Programs B3/05/12. Gpp 18843 260 24X Fichs. 50-369, 83/05/17, 8306140530

- 8305110460 IE Info Notice BJ-34, "Event Notification Info Worksheet"

 Byt List encl
 JURDAN, E. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/05/26 Consolidated Edison Co. of New
 York, Inc. 115pp 18732 085 24X Fiche 50-000.83/05/26.8305110460
- 8305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods Withdrawn at BWRs " Svc list encl JDBDAN.C L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/31 Consolidated Edison Co. of New York, Inc. 11669 18732 208 24X Fiche 50-000,83/05/31.0305110461
- 8306270282 Forwards response to IE Bulletin 83-03, "Check Valve Failures in Raw Water Cooling Sys of Diesel Generators" No check valves installed in cooling water sys at facilities TUCKER. H B Duke Power Co B3/06/07 O'REILLY, J P Region P, Office of Director 2pp 17056-036 24X Fiche 90-369.83/06/07.830629282
- 8305290517 Forwards IE Insp Repts 50~369/83-20 & 50-370/83-27 on 830502-12 No noncompliance noted DAMCE, H C Division of Project & Resident Programs 83/06/08 TUCKER, H D Dake Power Co 2pp 19052 186 24X Fiche 50~369, 83/06/08, 8306290517
- --8305290519 IE Insp Repts 50-369/83-20 & 50-370/83-27 on 830507-12 No noncompliance noted Major areas inspected preoperational test results surveillance testing-post-mod startup of Unit 1 & initial criticality of Unit 2 BURNETI.P T . THOMAS, M . JAPE.F Region 2. Office of Director 83/06/07 7pp 19052 188 24X Fiche 50-369,83/06/08.8306270517
- 8305110464 IE Info Notice 83-36, "Import of Security Practices on Sofe Operations " Syc list encl JURDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/07 Consolidated Edison Co. of New York, Inc. 119pp 18830 280 24X Fiche 50-000,83/06/09,8305110464
- 8305110470 IE Info Notice 83-38. "Defective Heat Sink Adhesive & Seismically Induced Chatter in Rolays Within Printed Circuit Cards." Syc list end!

 JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co. of New York. Int. 118pp 18720-225 24X Fichs 50-000.83/06/13.8305110470
- 8306090010 IE Info Notice 83-3/. "Transformer Failure Resulting From Degraded Internal Connection Cables " Bvc list onc)
 JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co. of New York. Inc. 243pp 18921 001 24X Fiche 50-000.03/06/13.8306090010
- 8305110475 IE Info Notice 83-40, "Need to Environmentally Qualify
 Epoxy Grouts & Sealers " Svc list enc!
 JORDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/06/22 Compolidated Edison Co of New
 York, Inc 115pp 19021 177 24X Fiche 50-000,83/06/22,8205110475
- B305110477 lE Info Notice 83-41, "Actuation of Fire Buppression Bys Causing Imperability of Safety-Related Equipment " Svc list encl JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) B3/06/22 Consolidated Edison Co. of New York, Inc. 120pp 18997 007 24% Fiche 50-000.83/06/22,8305110477
- 8305110479 IE Info Notice 83-42, "Reactor Mode Switch Malfunctions " Byc 1ist encl JGRDANE L Division of Emergency Preparedness & Ingineering Response (Post 830103) 83/06/23 Consolidated Edison Co of New York, Inc 116pp 18996 242 24X Fiche 50-000.83/06/23,8305110479
- 8305110483 IE Info Notice 83-43, "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints "Svc list encl JORDAN, C L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/24 Consolidated Edison to of New York, Inc 116pp 19046 297 24X Fiche 50-000, 83/06/24, 8305110483.
- R. Periodic operating reports & related correspondence
- 8306170311 Monthly operating repts for May 1983 W/830615 ltr REAVIB.J A. TUCKER.H B. Duke Power Co. 83/06/15 Director's Office. Office of Inspection and Enforcement 8pp 18877 105 24X Fichs 50-369.83/06/15.8306170311

- S Reportable occurrences, LERs & related correspondence
- 8304010015 LER 83-007/01T-0 on B30503, during Tech Spec review, soep bubble test of 47 secondary containment bypass leakage paths discovered not performed Caused by procedural deficiency Temporary test procedure written W/830517 ltr NARDCC1.P B . BUCKER.H B Duke Power Co B3/05/17 O'REILLY, J P Region 2. Office of Director 4pp 18674 064 24X Fiche 50-370, B3/05/17, B306010015
- 830.6010104 LER 83-009/03L-0 on 830421.discovered that bellows leak test not performed on penetration fuel transfer canal tube after initial integrated leak rate test Caused by procedural deficiency Procedure changed W/830520 ltr NARDOC1.P B . TUCKER.H B Duke Power Co 83/05/20 D'REILLY.J P Region 2. Office of Director 2pp 18674 147 24X Fiche 50-370,83/05/20.8306010104
- 830.6090015 LER B3-012/03L-0 on B30427, investigation determined that main steam safety relief valve 2BV-20 lifted briefly while pressure below lift setpoint range Caused by setpoint drift Setpoint adjusted W/830527 ltr NARDOCI.P B . TUCKER.H B Duke Power Co B3/05/27 D'REILLY, J P Region P. Office of Director 2pp 18/92 346 24X Fiche 30-370, 63/05/27, 6306070015
- 8304090040 LER 83-010/03L-0 on 830427, data gathering panels 7 & 23 would not respond to fire detection sys processor Caused by water in bottom of panel 23 & HIOPOA encl Hater removed k boards in HIO2OA encl replaced W/B3052/ ltr NARDOCI.P B . TUCKER.H B Duke Power Co 83/05/27 D'REILLY, J P. Region 2. Office of Director 2pp 18793 278 24X Fiche 50-370,63/05/27,8304090040
- 9306100216 LER 83-011/OSL-0 on 930427.PDHV block valve 2NC-318 declared inoperable due to steam leaking past shaft to containment atmosphere Caused by Failure of packing gland eye bolts Valve closed & actuator devnergized W/830527 ltr NARDCI.P B., TUCKER.H B. Duke Power Co. 93/05/27 Region 2, Office of Director. 4pp. 18305-349, 24X Fiche 50-370,83/05/27,8306100216
- 8306130314 LER 83-013/03L-0 on 830430. Fire detection Zones 87.88 & 100 declared inoperable due to constant invalid alarms Fire watches & containment temp monitoring established Caused by dirt accumulation in amoka detectors W630527 1tr NARDOCI.P B . TUCKER.H B Duke Power Co 83/05/27 O'REILLY, J P Region 2. DPP1ce of Director 4pp 18822 233 24X Fiche 50-370, 83/05/27, 8306130316
- 8306100138 LER 83-014/03L-0 on 830501, refueling water storage tank boron concentration found low Caused by low reactor mekeup blender effluent concentration Boric acid added & procedures revised W/830531 ltr
 TUCKER.H B. NARDDCI.P B. Duke Power Co. 83/05/31 O'REILLY, J.P. Region 2, Office of Director 2pp. 18801 248 24X
 Fiche 50-370, 83/05/31, 8306100138
- 8306:Q0164 LER 83-015/03L-0 on 830501, while in Mode 3, radiation monitors REMF-38 & REMF-39 declared inoperable when low flow alarm could not be cleared Vacuum switch found stuck Switch exercised & returned to normal syc NARDOCI, P.B., TUCKER, H.B. Duke Power Co. Q3/05/31 O'REILLY, J.P., Region 2, Gffice of Director 2pg 18807 230 24X Fiche 50-370, 83/05/31, 8306100164
- 830&100185 LER 83-017/03L-0 on 830509, radiation monitor 2EMF-10 declared inoperable when monitor failed high Caused by RP23A power supply failing due to cabinet temp Power supply replaced W/830531 ltr
 TUCKER.H B , NARDOCI.P B Duke Power Co 83/05/31 G'REILLY, J P Region 2. Office of Director 2pp 18805 283 24X
 Fiche 50-370, 83/05/31. 8306100185
- 8306100243 LER 83-016/03L-0 on 830506, radiation monitor 2EMF-12 did not respond to check source Caused by water in detector canister & bad OH tube GAUSED by water in detector decontaminated H/830531 ltr NARDICLEP B., TUCKER, H.B. Duke Power Co. 83/05/31, O'REILLY, J.P. Region 2, Office of Director 2pp. 10807 137 24X Fiche 50-370, 83/05/31, 8306100243
- B306130312 Updated RO-370/83-07 re discrepancies in initial integrated leak rate test Soap bubble test of hot penetrations will be incorporated in periodic test procedure
 TVCKER.H B Duke Power Co 83/06/03 O'REILLY.J P. Region 2.
 Office of Director 1p 18823-329 24X Fiche 50-370.83/06/03.
 B306130312

- 8306200238 LER 83-008/03L-0 on 830418,upper & lower personnel airlocks declared inoperable when blown & ruptured inner seals, respectively, discovered on auxiliary kids door. Caused by design deficiency W/830603 ltr
 TUCKER, H B., NARDOCI, P B. Duke Power Co 83/06/03 O'REILLY, J P Region 2. Office of Director 4pp 18702 351 24X Fiche. 30-370, 83/06/03, 8306200238.
- 8306270094 RO on B30527, containment pressure control sys monthly surveillance not performed at required interval & when performed appressure found out of allowable limits Analysis incomplete Repts will be submitted by 830624 TUCKER, M.B. Duke Power Co. B3/06/09 O'REILLY, J.P. Region 2, Office of Director ip 1898B 121 24X Fichs 50~369, 83/06/09, 8306270094,
- 8306200321 RO 370/83-018 on 830513, radioactive liquid effluent monitoring instrumentation channels inoparable investigation incomplete Next rept will be submitted by 830620 TUCKER. H.B. Dute Power Co. 83/06/10 O'REILLY, J. P. Region 2, Office of Director ip 18899 011. 24% Fiche 50-370,83/06/10,8306200321.
- 8306300114 LER 83-020/03L-0 on 830519, shutdown not bank A Group I & control rod banks A & C Group I failed to move on command Caused by maifunction in input/output ac amplifier can ABO5 due to transistor failure Cent replaced W/830617 It NARDOCIP B, TUCKER, H B Duke Power Co 83/06/17 O'REILLY, J P Region R, Dffice of Director. 2pp 19121 067 24X Fiche, 50-370,83/06/17,8306300114
- 8305300171 RQ 370/83-18:on 830513, radioactive liquid effluent admitsring instrumentation channels failed Incident determined not reportable. No 30-day rept will be submitted TUCKER, H. B. Buke Power Co. 83/05/20 O'REILLY, J. P. Region 2, Office of Director ip. 19119 271 24X Piche 50-370, 83/05/20, 8306390171
- 8306300232 LER 83-021/03L-0 on B30521, while in Mode 2, control room steam generator D wide range level recorder indication incorrect. Caused by tube fitting leak on level transmitter high-pressure sensor line Fitting replaced W/630620 ltr. NARDGCI,P.B., TUCKER,H B Duke Power Co. 83/06/20 O'REILLY, J P. Region 2, Office of Director 2pp 19119 182 24X Fiche 50-370,83/06/20,8306300232
- 8306300187 LER 83-023/03L-0-on 830524, upper head injection surge tank low pressure alarm received Bult nitrogen not immediately available 4 pressure fell below limit Caused by leakage of gas relief valve on nitrogen accumulator W/830623 itr NARDOCI, P B., TUCKER, H B Duke Power Co 83/06/23 O'REILLY, J P. Region 2. Office of Director. 28p. 19122 193 24X Fiche, 50-370,83/06/23,8306300189
- B306300191 Forwards LERs B3-036/031-0 & B3-022/031-0 TUCKER, M.B Duke Power Co. B3/06/23 O'REILLY, J P Region 2, Diffice of Director. 3pp. 19119:230 24X Fichs. 50-369, B3/06/23, B306300191
- --8306300204 LER 83-022/03L-0: on 830524 & 26, listed functional test procedures failed to satisfy monthly setpoint requirements. Caused by failure to identify & incorporate changes into procedures, Setpoints verified NABOGI.P.B Duke Power Co. 83/06/23. ip 19119:254 24X Fiche: 50-369, 83/06/23, 8306300191
- T. Hearing transcripts on non-antitrust matters
- 8306020700 Transcript of Commission 830527 discussion & possible vote in Washington,DC on full power OL Pp 1-83, Supporting documentation and 1. **Commissioners. 83/05/27 112pp. 18717-046, 24% Fiche: 50-370, 83/05/27, 8306020700.
- V. Operator Examinations
- 830&140346 Advises that based on results of oral exams administered to all personnel per 820825 request for waiver of exams, amended literaces will be forwarded for personnel w/appropriately submitted applications.

 BANCE, H. C. Division of Project & Resident Programs 83/02/10, TUCKER, H. B. Duke Power Co. 1p. 18832:175. 24x

 Fiche: 50-369, 83/02/10, 8306140346.

- DOCKET 50-379 LASALLE COUNTY STATION, UNIT 1
- A Application/construction stage documents & correspondence
- B30.4230009 Addi response to FDIA request for all drafts, imap evaluation repts & comments on J Keppler B20719 rept re special safety imap during Hau-Jul 1982 of activities at Unit i Forwards documents listed in App B Addi records under review FELTON.J M Division of Rules and Records 83/03/25 GARDE.B Government Accountability Project 3pp 18952 001 24X Fiche 50-373,83/03/25.8308230005
- --8304230028 Forwards trip rept of 820525-26 visit to Region III & site re containment bolt installation problem Engineering discussion, recommendations & exam conclusion included HOUD, A C SPS Technologies 82/06/28 JACKIN, I N NRC No Detailed Affiliation 0/ym 16pp 18952 361 24X Fiche 50-373, 83/03/25,8306230005
- --8306230031 Comments on agenda items for 820625 site meeting retechnical aspects of torque whench calibr Motor aperator/ yoke connection tightness check, torque whench calibr accuracy & expansion anchor installation discussed RODABAUGH.E C E C Rodabaugh Associates, Inc. 82/06/26 TERAD.D Mechanical Engineering Branch App. 18983-015 24x Fiche 50-373,83/03/25.8306230005
- --8306230037 Forwards (A Manual 18-1 2 audit rept Plant const satisfactory. REED, C Commonwealth Edison Co 82/07/08 KEPPLER, J Q Region 3. Diffice of Director 1p 18953 021 24X Fiche 50-373,89/03/25, 8306230005
- --8306230039 GA Manual 18-1 2 audit rept Related correspondence encl MANSING-K J Commonwealth Edison Co 81/08/04 60pp 18953 022 24% Fiche 50-373,83/03/25,8306230005
- --8306230051 Discusses changes in Section X of util rept resulting from consultant concerns re bolting issue Rept revised to reflect verification of procedures & data NORELIUS.C C Division of Engineering 82/07/19 JOBLONSKI.F, KNICELEY.J. REIMANN.F Region 3, Office of Director 3pp 18953 085 24X Fiche: 50-373,83/03/25,8306230005
- 8306160031 Clarifies NRC final response to FOIA request for documents re Zack Co &/or work performed by Zack in const of facilities. App D Document 5 delated since document identical to App A Document 135
 FELTON, J. M. Division of Rules and Records 83/04/14
 PRENDERGAST, R. Prendergast, R. J. 1p. 18872 356 24X
 Fiche 50-000, 83/04/14, 8306160031
- F Security, medical, emergency & fire protection plans
- 8304070358 Forwards response to 830428 request for add1 info re Guestion 010 74 on fire protection for safe shutdown Add1 detectors to be installed prior to startup following refueling outage for Unit I SCHROEDER, C W Commonwealth Edison Co 83/05/31 SCHWENCER, A Licensing Branch 2 opp 18742 153 24X Fiche 50-373,83/05/31. 8306070335
- 8306130632 Releases public version of revised emergency plan implementing procedure FELTON.J M Division of Rules and Records 83/06/07 Document Management Brench 1p 18868 020, 24X Fiche 50-373,83/06/07, 8306150632
- --B306150636 Public version of Rev 2 to Emergency Plan Implementing Procedure L2P-1830-32. "Post-Accident Sampling of OA Wide-Range Oas Monitor " Offsite procedure mod forms & revised index encl * Commonwealth Edison Co 83/05/03 Office of Nuclear Reactor Regulation, Director 18pp 18868 021 24% Fiche 50-373, 83/06/07,8306150632
- 8306160391 Ack receipt of 830527 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-373/82-54 & 50-374/82-22 SPESBARD, R L Region 3. Office of Director 83/06/10 REED, C. Commonwealth Edison Co. 3pp 18860,037 24X Fichs 50-373,83/06/10,8306160391.
- --8306i60495 Responds to NRC 830428 ltr re violations noted in IE Insp Repts 50-373/82-54 & 50-374/82-22 Corrective actions, additinsp criteria utilized during reinsp of cable penetration firestops & during initial installation at Unit 2 FARRAR: D. L. Commonwealth Edison Co. 83/05/27 KEPPLER: J 9 Region 3. Opfice of Director 8pp 18860:040 24X Fiche: 50-373,83/06/10,8306160391

- 8304210205 Submits program for resolution of License Condition 2 C (25)(d) re unlabeled fire doors Bullet resistant assembly Door 299 will be removed & replaced w/smaller assembly door afg by Chicago Bullet Proof Co SCHROEDER, C W Commonwealth Edison Co 83/06/15 SCHMENCER, A Licensing Branch 2 3pp 18919 019 24X Fiche 50-373,83/06/15,8306210205
- 8306300117 Advises that DOE will respond to requests for emergency radiological assistance from licensees federal, state & local agencies private organizations or individuals involved in incident involving source byproduct or SNM BAUER, R H Energy, Dept of 83/06/23 DIEDERICH, 0 J Commonwealth Edison Co ip 19121 076 24X Fiche 50-373,83/06/23,
- J. Insurance & Indemnity information
- 8306020183 Forwards Certificate of Insurance N-83 to NCLIA Policy 1 & Certificate of Insurance M-83 to MAELU Policy 1 USTER: J Commonwealth Edison Co 83/05/24 SALT2MAN. J Assistant Director for State & Licensee Relations 13pp 18690 232 24X Fichs 50-373,83/05/24,8306020103
- 8305170283 Forwards Endorsements 25 & 10 to NELIA Policy NF-253 & MAELU Policy MF-104, respectively. OBTER, J. Commonwealth Edison Co. 83/06/13 SALTZMAN, J. Assistant Director for State & Licensee Relations 3pp 18877 017 24X Fiche 50-373,83/06/13.8306170283
- P. Operating license stage documents & correspondence
- 8305190370 Forwards computer listing of "Environ Qualification Status Rept IE Equipment (Harsh) " Unit 2 currently expected to begin fuel loading in Aug 1983 SCHADEDER.C W Commonwealth Edison Co 83/05/13 SCHMENCER.A Licensing Branch 2 2pp 18500 087 24X Fiche 50-373,83/05/13,8305190370
- --8305190373 "Environ Qualification Status Rept IE Equipment (Harsh) "
 * Sargent & Lundy: Inc 83/05/05 98pp 18500 089 24X
 Fiche 50-373,83/05/13,8305190370
- 8306040146 Forwards alternate & complete solution to resolve NRC concerns re detection of inadequate core cooling in reactor water level ref leg cooling sys W/one oversize drawing Aperture card is available in PDR SCHROEDER.C W Commonwealth Edison Co 83/05/31. 9CHWENCER.A Licensing Branch 2 9pp 18732 076 24X Fiche SO-373,83/05/31.8306060146
- 830406023B Responds to A Bournia request for rept of status of util negotiations w/Secretary of DDE re Nuclear Waste Policy Act of 1982 Agreement will be reached & contract executed within required 830630 time frame SCHROEDER, C W Commonwealth Edison Co 83/05/31 SCHHENCER, A. Licensing Branch 2 lp 18728 360 24% Fiche 50-373, 83/05/31, 8304040230
- 8306090194 Discusses util interpretation of 10CFRBO 49, "Environ Qualification of Electrical Equipment Important to Safety for Nuclear Power Plants " Intent of rulemaking is to require upgrade program for replacement equipment not parts FARRAR, D.L. Commonwealth Edison Co. 83/06/03 DENTON.H R. Deffice of Nuclear Reactor Regulation, Director. 3pp. 18796 690 24X Fiche 50-000,83/06/03,8306090194
- 830&1000&2 Bubmits clarification of multiple fuel lift values due to criteria differences used by GE Engineering & GE Generic Licensing Groups as result of continued refinaments to generic model SCHROEDER, C W Commonwealth Edison Co 83/06/03 SCHWENCER, H Licensing Branch 2 3pp 18802 235 24X Fiche 50-373,83/06/03,8306100062
- 8306150552 Forwards assessment of "Quick Look" rept in response to 830304 & 30 ltrs re submittal of initial evaluation of safety relief valve in-plant test results Addl info requested.

 SCHWENCER, A Licensing Branch 2 83/06/07 FARRAR, D L Commonwealth Edison Co 5pp 18867.029 24X Fiche 50-373,83/06/07,8306150552
- 8306280077 Ack receipt of 830302 ltr, providing reasons for not paying Class II fee for review of 821118 & 1207 applications for examption from primary containment inerting requirements Fee requested in 830128 ltr no longer required.

 DIGGS, R. M. License Fee Management Branch 83/06/17 FARRAR, D. L. Commonwealth Edison Co 1p. 17042 347 24X Fiche 50-373,83/06/17,83062800077

- B306240406 Notification of B30621 meeting w/util in Bethesda. MD to discuss & clarify responses re multiple control sys failures BDURNIA:A Licensing Branch 2 B3/06/20 SCHWENCER:A Licensing Branch 2 3pp 18998 017 24X Fiche 50-373.83/06/20.8306240406.
- 8306280323 Forwards table listing results of fuel lift max gap per License Condition 2 C (12) Results calculated per NEDE-21175-3-P 8CHRIEDER, C W Commonwealth Edison Co 83/06/20 SCHWENCER, A Licensing Branch 2 3pp 19001 213 24X Fiche 50-373, 83/06/20.
- 8306280502 Forwards supplemental response to EG&G.Phase I.Apr 1983 rept re NUREG-0612, "Control of Heavy Loads," reflecting areas of concern addressed during 830614 telcon SWARTZ.E D Commonwealth Edison Co 93/06/22 DENTON.H R Office of Nuclear Reactor Regulation, Director 26pp 19019-236 24X Fiche 50-373,83/06/22,8306280502
- Q Inspection reports, IE Dulletins & correspondence
- 830.6230.005 Add1 response to FDIA request for all drafts, insp evaluation repts & comments on J Keppler 820719 rept re special safety insp during May-Jul 1982 of activities at Unit 1. Forwards documents listed in App B Add1 recards under review FELTON, J.M. Division of Rules and Records 83/03/25 OARDE, B. Oovernment Accountability Project 3pp 18952, 001 24X Fichs 80-373, 63/03/25, 8306830005
- --8306230012 Insp Evaluation Rept 82-39 re allegations of drilling & const deficiences at sits Concerns resolved affectively by licenses & NRC Related draft info encl * NRC No Detailed Affiliation Given 83/03/25 265pp 18952 004 24X Fiche 50-373,83/03/25,8306230006
- --8306230015 Evaluation Rept on Atty Ornoral of IL allegations rediffiling & const deficiencies at site. Allegations w/o menit + Structural Engineering Branch 83/03/25 4pp, 18752 269, 24X Fichs 50-033 83/03/25,8306230005
- --8306230019 Summary of 820611 mgt meeting at site re ongoing investigation of Atty General of IL allegations concerning drilling & const problems.

 DAVIS.A.B. Region 3. Office of Director 82/06/17 Region 3. Office of Director 3pp 18952.280 24X Fiche 50-373.83/03/25.8306230005
- --B306230022 Discusses readiness of facility to receive OL.per request. Initial recommendation or issuance of OL withdrawn pending further quantification & clarification of const GC issues Insp evaluation & related info encl
 REIMANN.F W Region 3. Diffice of Director. 82/06/28.
 JACKIW.I N. WALKER.P. D Region 3. Diffice of Director 74pp.
 18952-283 24X Fiche 50-373, B3/03/29, B306230008
- --8306230043 Discusses 820630,0707 & 08 telcons re investigations of allegations concerning facilities Allegations not properly investigated & could result in "whitewash".

 CUMMINGS.J. J. Office of Inspector & Auditor 82/07/15 DIRCKS.W. Office of the Executive Director for Operations 2pp. 18953-083, 24% Fiche 50-373,83/03/25,8306230005
- --8306230056 Discusses results of insp of allegations considered to have potential effect on facility operation No reason evident to limit power operation at facility KEPPLER, J G Region 3, Office of Director, 82/07/19, DENTON, H. R. Office of Nuclear Reactor Regulation, Director ip 18953-088 24X Fiche 50-373, 63/03/25, 8306230005.
- --8304230061 Discusses concurrence w/Bection X of IE Insp Repts 50-373/82-35 & 50-374/82-06 or allegation that Morrison Co torque whench calibr records falsified Audit not sufficiently comprehensive to draw meaningful conclusions. REIMANN.F W Region 3, Office of Director. 82/07/21. Region 3, Office of Director. 82/07/21. Region 3, 8306230005
- --8306230065 Summarizes 820811 meeting w/N Jackiw.R Lipinski k representatives of public interest groups re affidavits submitted by bricklayers subsequent to completion of initial special insp of facility Insp evaluation repts encl NORELIUS.C.E. Region 3: Office of Director 82/08/18 Region 3: Office of Director 92/08/18 Region 5: Office of Director 15pp. 18953-090, 24X Fichs 50-373.83/03/25.8306230005.
- 8306100252 Porwards IE Insp Rept 50-373/63-18 on 630425-28 t notice of violation PAPERIELLO.C J Region 3, Office of Director 83/05/20 REED.C. Commonwealth Edison Co 2pp. 18807.042 24X Fiche 50-373,83/05/20,8336100252

- --8304100255 Notice violation from insp on 830425-28
 PAPERIELLO, C J Region 3, Office of Director 83/05/19 ip
 18807 044 24% fiche 50-373.83/05/20.8304100252
- --8306i00258 IE Insp Rept 50-373/83-18 on 830425-28 Noncompliance noted failure to follow applicable procedure when completing radiation work permit requirements MILLER, D E. OREGER, L. R. Region 3, Office of Director. B3/05/19 7pp 18807 045 24X Fiche:50-373,83/05/20,8306i00252
- 8306100172 Forwards IE Insp Repts 50-373/83-16 & 50-374/83-14 on 830411-0506 & notice of violation STREETER, J F Region 3. Office of Director 83/05/24 REED, C. Commonwealth Edison Co 2pp. 18805 265 24X Fiche 50-373,83/05/24,8304100172
- --B306100174 Notice of violation from insp on 830411-0506 BTREETER, J.F. Region 3. Diffice of Director 83/05/24 2pp 18805,267 24% Fiche 50-373,83/05/24,8306100172
- --8305100175 IE Insp Repts 50-373/83-16 & 50-374/83-14 on 830411-0506
 Noncompliance noted failure to have adequate table
 separation & failure to have adequate housekeeping practices
 in cable tray areas.
 LANKSBURY.R.D., DUPONT, 8 Q., REYES, L.A. Region 3, Office of
 Director 83/05/24 5pp. 18805 269 24X Fiche 50-373,83/05/24,
 2305/20173
- 8305110458 IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in Well Logging Device" Byo list entl
 TAYLOR, J. M. Division of Bafeguerés & Inspection Programs (Post
 830103) 83/05/26 Consolidated Edison Co of New York, Inc
 125pp. 18831 043. 24X Fiche 50-000,83/05/26,8305110458
- 8305110460 IE Info Notice 83-34, "Event Notification Info Worksheet"

 8vc list encl
 JURDAN, E L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/05/26 Consolidated Edison Co of New
 York, Inc. 115pp 18732 085 24X Fiche 50-000,83/05/26,8305110460.
- 8305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods Withdrawn at EWRs " Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/31 Consolidated Edison Co. of New York, Inc. 116pp 18732 208 24X Fichs 50-000,83/05/31,8305110441
- 8306100245 Ack receipt of 830526 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-373/83-11 & 50-374/83-06
 STRETIER, J F Region 3, Office of Director 83/06/06 REED, C Commonwealth Edison Co 1p 18807:061 24X Fiche 50-373, 83/06/06, 8306100245.
- --8306100250 Responds to NRC 830428 ltr re violations noted in IE Insp Repts 50-373/83-11 & 50-374/83-06 Corrective actions test engineers reinstructed re test procedures FARRAR,D L Commonwealth Edison Co 83/05/26 KEPPLER,J 9 Region 3, Office of Director 3pp. 18807 062 24X Fiche:50-373,83/06/06,8306100245.
- 8306100094 Forwards response to IE Bulletin 83-03 re diesel generator cooling water check valves. Plants utilize Mission Duo-Check valves employing hinge-to-pin design for protection against vibration-induced failure.

 BARNES, P. L. Commonwealth Edison Co. 83/06/07, KEFPLER, J. C. Regio. 3, Dffice of Director. 7pp. 18802 238. 24X Fiche: 50-000, 83/06/07, 8306100094.
- 8306170380 Forwards response to IE Bulletin 83-03 re diesel generator cooling water check valves Valves at Dresden & LaSalle acceptable w/a further insp Rept on valve failures at Quad Cities will be submitted within 70 days of insp completion. BARNES, P. L. Commonwealth Edison Co. 83/06/07 KEPPLER. J. G. Region 3, Office of Director 7pp. 18880 211. 24% Fiche 50-000.83/06/07.8306170380
- 8305110464 IE Info Notice 83-36, "Impact of Security Practices on Safe Operations," Svc list encl JORDAN-E, L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/09. Consolidated Edison Co. of New York: Inc. 119pp 18800.280, 24X Fichs-50-000,83/06/09.8305110464.
 - to notice of violation from IE Insp Rept | 630425-28. Corrective actions: all | permits will be reviewed for
 - ; Edison Co. 83/06/10. KEPPLER, J. G. Region 2pp. 18861:302 24X Fiche:50~373,83/06/10.

- B306160391 Ack receipt of B30527 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-373/82-54 & 50-374/82-82 BPESSARD,R L. Region 3. Office of Director B3/06/10 REED,C Commonwealth Edison Co 3pp 18860 G37 24X Fiche 50-373,83/06/10,8306160391
- --830Ai60A35 Responds to NRC 830A28 ltr re violations noted in IE Insp. Repts 50-373/82-54 & 50-374/82-22 Corrective actions additions criteria utilized during reinsp of cable penetration firesteps & during initial installation at Unit 2 FARRAR, D.L. Commonwealth Edison Co. 83/05/27 KEPPLER, J. G. Region 3. Office of Director Spp. 18860 040 24X Fiche 50-373,83/06/10,8306160391
- 8306300129 Forwards IE Insp Repts 50-373/83-12 & 50-374/83-10 on 830311-0410 & notice of violation 8HAFER.W D Region 3. Office of Director 83/06/11 REED.C Commonwealth Edison Co 2pp 17122 333 24X Fiche 50-373,83/06/11.
- --8306300135 Notice of violation from insp on 830311-0410 SHAFER, W D Region 3, Office of Director 83/06/11 lp 19122 335 24% Fiche 50-373,83/06/11,8306300129
- --8306300141 IE Insp Rept 50-373/83-12 & 50-374/83-10 on 830311-0410 Noncompliance noted HPC8 automatically initiated & no unusual event declared following reactor scram on 830322 GULDEMOND. W . MADISON, A . WALKER R D Region 3. Office of Director 83/04/08 ilpp 19122 336 24X Fiche 50-373,83/06/11,8306300129
- 8305110470 IE Info Notice 83-38, "Defective Heat Sink Adhesive & Seismically Induced Chatter in Relays Within Printed Circuit Cards " Syc list encl JORDAN, E. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co of New York, Inc. 118pp 18920 225 24X Fiche 50-000,83/06/13.8305110470
- B306070010 IE Info Natice 83-37, "Transformer Failure Resulting From Degraded Internal Connection Cables " Svc. list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 630103) 83706/13 Consolidated Edison Co of New York, Inc. 243pp 18921 001 24X Fiche 50-000.83706/13,8306090010
- 8305i10475 IE Info Notice 83-40, "Need to Environmentally Qualify
 Epozy Grouts & Sealers " Svc list encl
 JORDAN.E. L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83706/22 Consolidated Edison Co
- 8305i10477 IE Info Notice 83-41, "Actuation of Fire Suppression Sys Gausing Inoperability of Safety-Related Equipment" Syc list encl. JURDAN:E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/22 Consolidated Edison Co. of New York: Inc. 120pp 18797 007 24X Fiche 50-000.83/06/22.8305110477
- 8305110479 IE Info Notice 83-42, "Reactor Modo Switch Malfunctions" Svc list dell. JORDAN, E. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/23 Consolidated Edison Co of New York, Inc. 114pp 18996 242 24X Fiche 50-000,83/06/23,8305110479
- 8304270219 Forwards IE Insp Repts 50-379/83-17 & 50-374/83-16 on 830411-0517 & notice of violation SHAFER, W D Region 3, Office of Director 83/06/23 REED, C Commonwealth Edison Co. 2pp 18788 282 24X Fichs 50-373,83/06/23. 8306270215
- --8306270222 IE Insp Rept 50-373/83-17 & 50-374/83-16 on 830411-0517 Noncompliance noted inadequate procedure re traversing in-core probe sys MADIBON, A . OULDEMOND, W . WALKER, R D Region 3, Office of Director 83/06/22 Spp 18988 285 24X Fiche 50-373,83/06/23, 8306270215
- 8305110483 IE Info Notice 83-43; "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints " Svc list encl. JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/24 Consolidated Edison Co. of New York, Inc. 116pp 19046, 297 24X Fiche 50-000, 83/06/24, 8305110483
- 830630006B Ack receipt of 830610 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-373/83-18 PAPERIELLO, C.J. Region 3, Office of Director 83/06/27 REED, C Commonwealth Edison Co ip 19120 266. 24X Fichs 50-373, 83/06/27, 830630006B.

- --B306300073 Responds to NRC B30520 ltr re violations noted in IE Insp Rept 50-373/83-18 Corrective actions radiation protection foresen instructed to review each radiation work permit for completeness prior to signing by shift engineer FARRAR, D L Commonwealth Edison Co B3/06/10 KEPPLER, J Q Region 3. Dffice of Director 2pp 19120 267 24X Fiche 50-373,83/06/27,8306300068
- S Reportable occurrences. LERs & related correspondence
- #305050206 LER #3-043/03L-0 on #30427.while performing charger capacity test.Div I charger SCR output fuse F-1 blew & charger feed treater tripped shutting down charger Caused by problem w/battery capacity tester Fuse replaced W/#830326 try Capacity tester Fuse replaced W/#830326 CAPACITY COMMONWEALTH Edison Co #3/05/26 KEPPLER.J G #8egion 3, Office of Director 3pp 18732 346 24X Fiche #0-373.63/05/26.8306060206
- 9308210308 Special rept correcting 830517 rept re ECCS actuation & injection of water into RCS On 830529, HPCS & RCIC sysauto initiated due to low water level Caused by setpoints more conservative than Tech Spec DIEDERICH, 0 J Commonwealth Edison Co 83/05/26 KEPPLER, J @ Region 3, Dffice of Director ip 18914 004 24X Fichs 50-373, 83/05/26, 8306210308
- B305130349 LER 83-044/03L-0 on B30505, reactor water pH dropped below Tech Spec while in cold shutdown Suppression pool & ICYOIT contaminated w/arganics Caused by processing freen & organic solvents through radwaste into ICYOIT W/B30531 tr BHEARER, L N , DIEDERICH, Q J Commonwealth Edison Co B3/05/31 KEPFLER, J G Region 3, Office of Director Spp 18822 337 24X Fiche 50-373,83/05/31.8306130347
- 8306130352 LER 83-045/03L-0 on B30506, during reactor vessel high water level HPCS injection valve closure calibr & functional test. Isvel indicating switch 1821-N100A found out of tolerance Caused by instrument drift W/830601 ltr MASTERBON, V V, DIEDERICH, G J Commonwealth Edison Co 83/06/01 KEPFLERI, J G Region 3, Office of Director 3pp 18822 307 24X Ficha 50-373.83/06/01,8304130352
- B306210277 LER B3-046/03L-0 on B3050B, surveillance frequency for offsite to onsite breaker alignment, onsite breaker alignment & low pressure carbon dioxide sys exceeded spec Caused by shift supervisor error W/B30602 ltr CAMPSELL.L.D. DIEDERICH.9 J. Commonwealth Edison Co. 83/06/02 KEFFLER.J O. Region 3. Offsice of Director 4pp 18914 241 24X Fiche 50-373.83/06/02.8306210277
- 8308210045 LER 83-048/09L-0 on 830510 during visual insps:mechanical stubber NB13-10068 found locked between hot & cold settings Passibly caused by excessive snubber travel or defective snubber Shubber replaced W/830606 itp SPENGER: DA . DIEDERICH.9 J Commonwealth Edison Ca 83/06/06 KEPPLER: J G Region 3, Office of Director 3pp 18910 360 24X Fiche 50-373.83/06/06.8306210045
- 8305210339 Updated LER 83-033/03X-i on 830402, radwaste effluent munitor declared inaperable Caused by high fixed level of background radiation Inner chamber surface experimentally coated w/acresin W/830606 ltr
 ARAND.J. DIEDERICH.O J Commonwealth Edison Co 83/06/06
 MEPPLER.J G Region 3, Office of Director 3pp 18919 171 24X
 Fiche 50-373,83/06/06,8306210089
- 8305210263 LER 83-047/03L-0 on 830507.liquid radwaste effluent process radiation monitor declared inoperable Caused by alarm trip point exceeding Tech Spec limit Monitor decontaminated & investigation of geometry change continuing W/830606 ltr ARAND, J J. DIEDERICH.0 J Commonwealth Edison Co 83/06/06, KEPPLER.J G. Region 3, Office of Director 3pp 18915:047 24X Facher 50-373.83/06/06,8306210263
- 8306270302 LER 83-049/03L-0 on 830520, during evaluation of turbine bypass valve sys response time requirements, data from LIS-EH-03 improperly evaluated Caused by incorrect wiring of control circuitry for valves 2 & 5 W/830608 ltr XALKON, K. DIEDERICH. O J Commonwealth Edison Co 83/04/08 KEPPLER, J @ Region 3, Office of Director. 3pp 16995.205 24X Fiche 50-373.83/04/08,8304270302
- 8304220019 LER 83-050/03L-0 on 830519, administrative/clerical errors found in Table 3 7 9-2 Caused by personnel inability to transpose design info into Tech Spec table Discrepancies corrected. W/830609 ltr.

 SPENCER: D . DIEDERICH. 4, J Commonwealth Edison Co. B3/04/09.

 KEFPLER: J Q Region 3, Office of Director. 3pp 18930.212, 24X Fiche 50-373.83/04/09.836220019.

- 830&1&01&9 PNO-III-83-043 on 830&10, while removing filter from reactor water cleanup sample panel radiation protection technician received eye contamination from dry mat1 adhering to filter Eye flushing reduced contamination to 30,000 dpm HUETER.L. MILLER.J. Region 3, Office of Director 83/06/10. ip 18861 272 24X Fiche 50-373,83/06/10,830&1401&9
- 8306210192 LER 83-051/03L-0 on 830513.VC chloring detector B tripped & would not reset Caused by loose ground wire on circuit board Wire tightened H/830613 ltr
 ARAND, J J. DIEBERICH.0 J Commonwealth Edison Co 83/06/13
 KEPPLER.J Q Region 3. Office of Director 3pp 18914 116 24X
 Fiche 50-373,83/06/13.8306210192
- 8306220064 LER B3-051/03L-O on 830516, reactor protection sys trip channel H2 limit switch failed to operate properly Causa unknown Limit switch readjusted W/830614 ltr HOVSTON.R W. DIEDERICH, G.J. Commonwealth Edison Co. 83/06/14 KEPPLER.J.O. Region 3, Office of Director 3pp 18780 182 24X Fiche 50-373.83/06/14.8306220064
- 9304270002 LER 83-054/03L-0 on 830520, drywell air 4 suppression chamber air/water temp functional test discovered not performed since 820427 Caused by personnel failure to incorporate test in computerized surveillance program W/030616 ltr TRAINOR.A F. DIEDERICH.O. J Commonwellth Edison Co 83/06/16 KEPPLER.J O Region 3, Office of Director 3pp. 18989 107 24X Fiche 50-373.83/06/16,8306270002.
- 8306270282 Potential Part 21 rept re discrepancy in welding of turnbuckle assembly, turnbuckle-bolt interface & on top plate assembly variable springs 84307 Grade B bolts not ABME Section IX matl Investigation underwell KARADIANIS, J A Elren Metal Products Co B3/06/17 KEPPLER, J G. Region 3, Office of Director 2pp 18998 207 24X Fiche 50-000,83/06/17,8306270282
- 8306300026 PND-III-83-053, on 830621, one of two manual isolation valves for vacuum breakers D found closed, rendering vacuum breaker inoperable Cause being reviewed Appropriate enforcement action to be initiated JORGENSEN, B L., SHAFER, W D. Region 3, Office of Director 83/06/24, 2pp 19120 313 24% Fiche 50-373, 83/06/24, 83063000026.
- DOCKET 50-974 LABALLE COUNTY BTATION, UNIT 2

 A Application/construction stage documents & correspondence
- 8306230005 Add1 response to F01A request for all drafts, insp evaluation repts & comments on J Keppler B20719 rept re special safety insp during May-Jul 1982 of activities at Unit i Forwards documents listed in App B Add1 records under review FELTON, J M Division of Rules and Records B3/03/25, QARDE, D. Government Accountability Project 3pp 18952 001 24X Fiche 50-373, 83/03/25, 8306230005
- ~-8304230098 Forwards trip rept of B20425-26 visit to Region III & site re containment bolt installation problem Engineering discussion, recommendations & exam conclusion included HODD, A C SPS Technologies. 82/06/20 JACKIN, I N. NRC No Detailed Affiliation Given 16pp 10952 361 24X Fiche. 50-373.83/03/25,8306230005
- --8306230031 Comments on Agenda items for 820625 site meeting retechnical aspects of torque wrench calibr Motor operator/
 yoke Connection tightness check torque wrench calibr accuracy & expansion anchor installabition discussed.
 RODABAUOH, E.C. E.C. Rodabaugh Associates, Inc. 82/06/26, TERAU.D. Mechanical Engineering Branch App. 1893-015 24X Fiche 50-373.82/03/25,8306230005
- --8306230037 Forwards QA Manual 18-1 2 audit rept Plant comet satisfactory
 REED.C Commonwealth Edison Co 82/07/08 KEPPLER.J. Q Region
 3. Office of Director ip 18953 O21 24X Fiche: 50-373,83/03/28,8306230005
- --8306230039 GA Manual 18-1.2 audit rept.Related correspondence encl. HANBING,K J. Commonwealth Edison Co. 81/08/04. 60pp. 10753.022, 24X Fiche 50-373,83/03/25,8306230005
- ~-8304230051 Discusses changes in Section X of util rept resulting from consultant concerns re bolting issue Rept revised to reflect verification of procedures & data NORELIUS.C.E. Division of Engineering 82/07/19 UOBLONBKI.F., KNICELEY.J., REIMANN.F. Region 3, Office of Director. Spp. 18983 085, 24X Fiche 50-373,83/03/25,8306230008.

- 8306160031 Clarifies NRC final response to FGIA request for documents re Zact Cq 3/or work performed by Zack in const of facilities App D Document 5 deleted since document identical to App A Document 135 FELTON. J M Division of Rules and Records 83/04/14 PRENDERORAST.R Prendergast, R J 1p 18872 356 24X Fiche 50-000,83/04/14.8306160031
- 8305190370 Forwards computer listing of "Environ Qualification Status Rept IE Equipment (Harsh) " Unit 2 currently expected to begin fuel loading in Aug 1983 SCHROEDER. C W Commonwealth Edison Co 83/05/13 SCHWENCER. A Licensing Branch 2 2pp 18500 087 24x Fiche 50-373.83/05/13.8305190370
- ~-B305190373 "Environ Quelification Status Rept IE Equipment (Harsh) "
 * Gargent & Lundy, Inc 83/05/05, 98pp 18500 089 24X
 Fiche: 50-373,83/05/13,8305190370
- 8306060146 Forwards alternate & complete solution to resolve NRC concerns re detection of inadequate core coaling in reactor water level ref leg cooling sys M/one oversize drawing Aperture card is available in PDR SCHROEDER; C W Commonwealth Edison Co 83/05/31 SCHWENCER, A Licensing Branch 2 Ppp 18732, 076. 24x Fiche 50-373,83/05/31,8306060146
- 8304040238 Responds to A Bournia request for rept of status of util negotiations w/Secretary of DOE or Nuclear Haste Policy Act of 1982 Agreement will be reached to contract executed within required 830430 time frame.

 86HRGEOER, C H Commonwealth Edison Co 83/05/31 SCHHENCER, A Licensing Branch 2 ip 18728 360 24X Fiche 50-373,83/05/31,8306060288
- 8306070334 Confirms 830531 telcon correcting gap calculations of fuel lift results contained in Generic Rept NEDE-21175-3-P BCHDEDER, C.W. Commonwealth Edison Co. B3/06/01 SCHWENCER, A Licensing Branch 2. 2pp. 18746-063 24X Fiche 50-374, 83/06/01, 8306070334
- 8306090174 Discusses util interpretation of 10CFR30 47, "Environ Qualification of Electrical Equipment Important to Bafety for Nuclear Power Plants "Intent of rulemaking is to require upgrade program for replacement equipment not parts FARRAR.D L Commonwealth Edison Co 83/06/03 DENTON.H R Office of Nuclear Reactor Regulation. Director 3pp 18776 070 24X Fiche: 50-000.83/06/03.8306090194
- 8306280929 Forwards table listing results of fuel lift max gap per License Condition R.C (12) Results calculated per NEDE-21175-3-P 8CHROEDER.C W Commonwealth Edison Co 83/06/20 8CHWENCER, A Licensing Brench 2 3pp 19001 213 24X Fiche: 50-373, 83/06/20, 8306280323
- 8306240252 Revises estimated fuel load dates to Oct 1783 for LaSaile County & Dec 1783 & May 1785 for Byron Units i & 2, respectively STIEDE, W. L. Commonwealth Edison Co. 83/06/21 DENTON, H. R. Defice of Nuclear Reactor Regulation, Director ip 18781:323 24X Fiche: 80-000, 83/06/21, 8306240382.
- 8306300032 Revises estimated fuel load dates; based on const activity & preoperational testing budget review Fuel load scheduled for 831001; Dec 1983 & May 1985 for LaSaile County Unit 2 & Byron Units 1 & Prespectively STIEDE; W.L. Commonwealth Edison Co. 83/06/21 KEPPLER, J. 0 Region 3, Office of Director, ip. 19120, 311, 24X Fiche 50-000, 83/06/21, aggrdanoga
- 8306280502 Forwards supplemental response to EG&O, Phase I. Apr 1783 rept re NUREQ-0612. "Control of Heavy Loads." reflecting areas of concern addressed during 830614 telcon. 84ARTZ.E D. Commonwealth Edison Co. 83/06/22 DENTON: H R. Office of Nuclear Reactor Regulation. Director 26pp 17017 236 24X Fichs: 50-373, 83/06/22. 8306280502
- F Security, medical, emergency & fire protection plans
- 8306070355 Forwards response to 830428 request for add1 info re Question 010.74 on fire protection for safe shutdown.Add1 detectors to be installed prior to startup following refueling outage for Unit 1. 8CHROEDER,C W Commonwealth Edison Co. 83/05/31. 8CHMENGER,A Licensing Branch 2. 6pp. 18742.153. 24X Ficher 50-373,83/05/31, 8306070355.
- 830615063R Releases public version of revised emergency plan implementing procedure, FELTONIJ M. Division of Rules and Records, 83/06/07. Document Management Branch. ip. 18868-020, 24X Fiche: 50-373.83/06/07, 8306150632

- --8306150636 Public version of Rev 2 to Emergency Plan Implementing Procedure LZP-1330-32, "Post-Accident Sampling of GA Wide-Range Gas Monitor " Offsite procedure mod forms & revised index ancl # Commonwealth Edison Co 83/05/03 Office of Nuclear Reactor Regulation, Director 18pp 18868 021 24X Fiche 50-373, 83/06/07-8306150632
- 8306160391 Ack receipt of 830527 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-373/82-54 & 50-374/82-22

 RPESCARD.R L Region 3. Office of Director 83/06/10 REED.C Commonwealth Edison Co
- --B306i60433 Responds to NRC B3042B ltr re violations noted in IE Insp. Repts 50-373/B2-54 & 50-374/B2-22 Corrective actions add1 insp. criteria utilized during reinep of cable penetration firestops & during initial installation at Unit 2 FARRAR.D L. Commonwealth Edison Co. B3/05/27 KEPPLER.J Q Region 3, Office of Director Bpp. 18860 040 24% Fiche 50-373,83/06/10,8306160371
- B306210205 Bubmits program for resolution of License Condition 2 C (25)(d) re unlabeled fire doors Bullet resistant assembly Door 279 will be removed & replaced w/smaller assembly door meg by Chicago Bullet Proof Co SCHROEDER, C W Commonwealth Edison Co B3/06/15 BCHWENCER, A Licensing Branch 2 3pp. 18719 019, 24X Fiche 50-373,83/06/15,8306210205
- 8306300117 Advises that DDE will respond to requests for emergency radiological assistance from licensees, federal, state & local agencies, private organizations or individuals involved in incident involving source, byproduct or SNM BAUER, R H Energy, Dept of 83/06/23 DIEDERICH, Q, J Commonwealth Edison Co ip 19121 076 24X Fiche 50-373, 83/06/23, 8306300117
- P Operating license stage documents & correspondence
- B306100062 Bubmits clarification of multiple fuel lift values due to criteria differences used by GE Engineering & GE Generic Licensing Groups as result of continued refinements to generic model SCHROEDER, C W. Commonwealth Edison Co B3/06/03, SCHWENCER, H Licensing Branch & Spp 16802 235 24% Fiche 50-373,83/06/03,8306100062
- B306240406 Notification of B30621 meating w/util in Bethesda, HD to discuss & clarify responses re multiple control sys failures BOURNIA.A Licensing Branch 2 B3/06/20 BCHWENCER, A Licensing Branch 2 3pp 18978 017. 24X Fiche 50-373, B3/06/20, B306240406
- G Inspection reports, IE Bulletins & correspondence
- G30623000B Add1 response to FDIA request for all drafts, insp evaluation repts & comments on J Keppler B20717 rept re special safety insp during May-Jul 1982 of activities at Unit 1, Forwards documents listed in App B. Add1 records under review FELTON, J M Division of Rules and Records 83/03/25 CARDE, B, Oovernment Accountability Project 3pp 18952 001 24X Fiche 50-373, 83/03/25.8306230005
- --8306230012 Insp Evaluation Rept 82-35 re allegations of drilling & const deficiences at sits Concerns resolved effectively by licensee & NRC Related draft info encl * NRC No Detailed Affiliation Given 63/03/25 265pp 18952 004 24X Fiche 50-373,83/03/25,8306230005
- --8306230015 Evaluation Rept on Atty General of IL allegations rediffiling & const deficiencies at site Allegations w/o merit.

 # Etructural Engineering Branch 83/03/25 4pp 18952 269 24X Fiche, 50-370, 83/03/25, 8306230005
- --8306230019 Bummary of 820611 mgt meeting at site re angoing investigation of Atty General of IL allegations concerning drilling & const problems

 DAVIB: A.B. Region 3. Office of Director 82/06/17, Region 3. Office of Director 3pp 18752 280 24X Fiche: 50-373, 83/03/25, 8306230005
- ---B006230022 Discusses readiness of facility to receive OL, per request Initial recommendation or issuance of OL withdrawn pending further quantification & clarification of const GC issues Insp avaluation & related info encl REIMANN,F W. Region 3, Office of Director 82/06/20 JACKIN,I.N., WALKER,R.D. Region 3, Office of Director 74pp. 18952,283 24X Fiche; 50-373,83/03/25,8306230005

- --8306230043 Discusses 820630,0707 & 08 telcons re investigations of 306230043 Discusses 820630,0707 & O8 telcons re investigations of allegations concerning facilities Allegations not properly investigated & could result in "whitewash"

 CUMMINOS.J J Office of Inspector & Auditor 82/07/15 DIRCKS,W

 Office of the Elecutive Director for Operations 2pp 18953 083

 24X Fiche 50-373.83/03/25.8306230005
- --8306230061 Discusses concurrence w/Bection X of IE Insp Repts 50-373/82-35 & 50-374/82-06 re allegation that Morrison Co torque whench caller records falsified Audit not sufficiently comprehensive to draw meaningful conclusions REIMANN.F W Region 3, Office of Director 82/07/21 Region 3, Office of Director 82/07/21 Region 3, Office of Director 83/07/21 Region 3, R306230005
- 8304030209 Forwards IE Insp Rept 50-374/83-15 on 830412-15 & 19-21 No Commonwealth Edison Co 2pp 18703 290 24X Fiche 50-374, 83/05/19, B306030209
- --8306030213 IE Insp Ropt 50-374/83-15 on 830412-15 & 19-21 No noncompliance noted Major areas inspected exam of const & as-built drawings for incorporation of design changes review
- 8306100172 Forwards IE Insp Repts 50-373/83-16 & 90-374/83-14 on 830411-0506 & notice of violation STREETER.JF Region 3. Office of Director 83/05/24 REED.C. Commonwealth Edison Co 2pp 18805 265 24X Fiche 50-373,83/05/24.
- --8304100174 Notice of violation from insp on 830411-0504 STREETER, J.F. Region 3, Office of Director 83/05/2/ 18805 267 24x Fiche 30-373,83/05/24,8304100172 83/05/24 2pp.
- -- B306100175 IE Insp Repts 50-3/3/83-16 & 50-374/83-14 on B30411-0506 Noncompliance noted failure to have adequate cable separation & failure to have adequate housekeeping practices DUPO Differtor 83/05/24 9308100172
- 8305110458 IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in Hell Logging Device" Svc list enci TAYLOR, J M Division of Bafeguards & Inspection Programs (Post 830103) 83/05/26 Consolidated Edison Co. of New York, Inc 125pp 18831 043 24X Fiche 50-000,83/05/26,8305110458
- 8305110940 IE Info Natice 83-34, "Event Notification Info Worksheet"
- Seve list encl.

 DORDAN, E L Division of Emergency Preparedness & Engineering

 Response (Post 830103). 83/05/26 Consolidated Edison Co of New

 York. Inc. 115pp 18732 085 24X Fiche 50-000, 83/05/26, 8308110460
- 8306100263 Forwards 1E Insp Rept 50-374/83-17 on 830425-0904 No noncompliance noted
 LITTLE, W S Region 3. Office of Director 83/05/27 REED, C
 Commonwealth Edison Co 2pp 18807 005 24X Fiche 50-374,83/05/27,
- --8306:00266 IE Insp Rept 50-374/83-17 on 830425-0504 No noncompliance noted Major areas inspected 10CFR50 55(e) item re ECCS pumps. Instrument racks & installation records NAIBU, X R , AMMED, I , WILLIAMS, C C Region 3, Office of Director 83/05/26 6pp. 19807 007 24X Fiche 50-374,83/05/27,8306100263.
- 8305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods Mithdrawn at SWRs " Byc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/31 Consolidated Edison Co of New York, Inc. 116pp 18732 208 24X Fiche 50-000,83/05/31,8305110461
- 9306100245 Ack receipt of 830526 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-373/83-11 k 50-374/83-06 STREFTER, J F Repion 3, Office of Director 83/06/06 REED, C Commonwealth Edison Co
- --8306100250 Responds to NRC 830428 ltr re violations noted in IE Insp Repts 50-373/83-11 & 50-374/83-06 Corrective actions test engineers reinstructed re test procedures. FARRAR, D L Commonwealth Edison Co 83/05/26 KEPPLER, J Q Region 3, Office of Director 3pp 18807:062, 24X Fiche: 50-373,83/06/06,8306100245

- 8305110464 IE Info Notice 83-36, "Impact of Becurity Practices on Safe Operations " Svc list and JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/09 Consolidated Edison Co of New York, Inc 119pp 18830 280 24X Fiche 50-000,83/06/09.8305110464.
- 8306160391 Ack receipt of 830527 ltr informing NRC of steps taken to correct violations noted in IF Insp Repts 50-373/82-54 & 50-374/82-22 SPESSARD.R L Region 3, Office of Director 83/06/10 REED.C. Commonwealth Edison Co 3pp 18860 037 24X Fithe.50-373,83/06/10,8304160391 8304140391
- --8306160435 Responds to NRC 830428 ltr re violations noted in IE Insp Repts 50-373/82-54 & 50-374/82-22 Corrective actions add1 insp criteria utilized during reinsp of cable penetration firestops & during initial installation at Unit 2 FARRAR, D L Commonwealth Edison Co. 83/05/27 KEPPLER, J Q Region S, Office of Director Epp 18860 040. 24X Fiche 50-373,83/06/10,8304160391
- 8306230418 Forwards IE Insp Rept 50-374/83-12 on 830324-20 & 0505 No noncompliance noted

 STREETER, J F Region 3, Office of Director 83/06/10, REED, C.

 Commonwealth Edison Co 2pp 18942: 040 24% Fiche: 50-374, 83/06/10, 8306230418
- ~~8306230423 IE Insp Rept 50-374/83-12 on 830324-30 & 0505 No noncompliance noted Major areas inspected:mpt of GA program, auditing activities.control of design changes & nonconformance control
 VANDEL,T E., KISH,J N., HAWKINS,F.C. Region G, Office of Director,
 83/06/10 7pp 18942-050 24X Fiche 50-374.83/06/10.8306230418.
- 8306300129 Forwards lE Insp Repts 50-373/83-12 & 50-374/83-10 on 830311-0410 & notice of violation 84AFER,W D Region 3, Office of Director 83/06/11 REED,C Commonwealth Edison Co 2pp. 19122 333 24X Fiche 50-373,83/06/11,8306300129
- --8306300135 Notice of violation from insp on 830311-0410.

 8HAFER: N D Region 3, Office of Director. 83/06/11
 19122 335 24X Fichs 50-373,83/06/11,8306300129
- --8306300141 IE Insp Rept 50-373/83-12 & 50-374/83-10 on 830311-0410. 306300141 IE Insp Rept 50-373/83-12 & 50-374/83-10 on B30311-0410. Noncompliance noted HPCS automatically initiated & no unusual event declared, following reactor scram on B30322. OULDEMOND, W. MADISON, A. WALKER, R.D. Region 3, Office of Director 83/06/08 11pp 19122 336 24X Fich* 50-373, 83/06/11, 8306300129
- 8305110470 IE Info Notice 83-38, "Defective Heat Sink Adhesive & Seismically Induced Chatter in Relays Within Printed Circuit Cards" Svc list enci.
 JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13. Consolidated Edison Co. of New York, Inc. 118pp. 18720 225 24X Fichs. 50-000, 83/06/13, 8305110470.
- 8306090010 IE Info Notice 83-37, "Transformer Failure Resulting From Degraded Internal Connection Cables" Syc list encl JORDAN E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13. Consolidated Edison Co. of New York, Inc 243pp. 18921.001 24X Fiche. 50-000, 83/06/13. 8306090010
- 8305110475 IE Info Notice 83-40, "Need to Environmentally Qualify
 Epoxy Grouts & Bealers " Svc list and
 JORDAN, E. Division of Energency Preparedness & Engineering
 Response (Post 830103) 83/06/22 Consolidated Edison Co. of New
 York, Inc. 115pp 19021 179 24X Fiche, 50-000, 83/06/22, 8305110475,
- 8305110477 lE Info Notice 83-41, "Actuation of Fire Suppression Bys Causing Inoperability of Safety-Related Equipment " Byc list encl. JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/22 Consolidated Edison Co. of New York, Inc. 120pp 18997.007 24X Fiche 50-000,83/06/22.8305110477.
- 8305110479 IE Info Notice 83-42, "Reactor Mode Switch Melfunctions."

 8vc list encl.

 JORDAN, E.L. Division of Emergency Properedness & Engineering
 Response (Post 830109). 83/06/23. Consolidated Edison Co. of New
 York, Inc. 116pp 18996 242 24X Fiche: 50-000, 83/06/23, 8305110479.
- 8306270215 Forwards IE Insp Repts 50-373/83-17 & 50-374/83-16 on 830411-0517 & notice of violation SHAFER'S D. Region 3, Office of Director. 83/06/23, REED.C. Commonwealth Edison Co. 2pp. 18988 282, 24X Fichs 50-373,83/06/23, 8304270215

- --8306270222 IE Insp Rept 50-373/83-17 & 50-374/83-16 on 830411-0517 Noncompilance noted inadequate procedure re traversing in-core probe sys MADISON, A. GULDEMOND, W., WALKER, R. D. Region 3. Office of Birector 83/06/22 Bpp 18988 285 24X Fiche 50-373,83/06/23,8306270215
- 8305110483 IE Info Notice 83-43, "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints " Svc list encl JORDANIE L Division of Emergency Preparedness & Engineering Response (Post 830103) 83706/24 Consolidated Edison Co of New York, Inc 116pp 19046 297 24X Ficha 50-000,83/06/24,8305180483
- 8 Reportable occurrences, LERs & related correspondence
- 8306100234 Final deficiency rept re problems w/Riley temp switches Initially reported on 830316 Based on engineering evaluation by Riley, switches accurately perform intended function when calibr w/modified procedure SCHROEDER: C Commonwealth Edison Co 83/06/03 KEPPLER: J Q Repton 3. Office of Director 2pp 18805 321 24x Fiche: 50-374, 83/06/03, 8306100234
- 8306160169 PNG-III-83-043 on 830610, while removing filter from reactor water cleanup sample panel, radiation protection technician received eye contamination from dry matl adhering to filter Eye flushing reduced contamination to 30,000 dpm HUETER, L. HILLER, J. Region 3. Defice of Director 83/06/10 ip 18861 272 24% fichs 50-373,83/06/10.8306160169
- 8306270282 Potential Part 21 rept re discrepancy in welding of turnbucile assembly turnbucile-bolt interface & on top plate assembly variable springs 8A307 Grade B bolts not ASME Section IX matl Investigation underway KAR01ANIB, J A Elcen Metal Products Co 83/06/17 KEPPLER, J G Region 3, Office of Director 2pp 18796 207 24X Fiche: 50-000, 83/06/17,8306270282

DOCKET 50-382 WATERFORD GENERATING STATION, UNIT 3

- A Application/construction stage documents & correspondence
- 8306020687 Requests confirmation of NRC understanding that FSAR states that testing meets provisions of IEEE-338 & Reg Ouide I 22 re ESF actuation sys surveillance requirements KNIGHTON.O.W Licensing Branch 3 83/05/10 MAURIN.L V Louisiana Power & Light Co 4pp 18715 328 24X Fichs 50-382,83/05/10,8306020687
- 8306020641 Notification of 830609 meeting w/util & Torrey Pines in Bethesda,MD to discuss Torrey Pines independent design verification program for emergency feedwater sys WILSON, J.H. Licensing Dranch 3 83/05/16 KINOMTON, G.W. Licensing Branch 3 3pp 18716 331 24X Fiche 50-382,83/05/16,8306020641
- 8306070090 Advises of no adverse effect re-cultural resources described in protection plan on Areas 3 & 4 re-plantation overseers house & plantation workers quarters, respectively DEBIEUX, R B Louisians, State of 83/05/27 REGAN, H Biting Analysis Branch 1p 18739 206 24X Fichs 50-382,83/05/27,830A070090
- 8306130206 Forwards revised FSAR Chapter 17 re GA program, per 10CFR50 54 & 55 Rev constitutes complete rewrite of GA program description for operations phase & will be incorporated into next amend scheduled for Jul 1983 GERRETS, TF Louisians Power & Light Co 83/06/07, KNIGHTUN, 0 W Licensing Branch 3, 220pp 18826 054 24% Fiche 50-382,83/06/07,8306130206
- B30627020A Advises of planned use of respiratory protective equipment per 10CFR20 103. Use of equipment not anticipated prior to fuel load DRUHMOND, F. J. Louisiana Power & Light Co. B3/06/13 COLLING, J. T. Region 4, Office of Director 1p. 18991 263 24X Fiche 30-382,83/06/13,8306270206
- B306210124 Informs that CE Owners Group study on depressurization & DRR schedule will be accelerated to provide response to NRC questions by B30630 Response date orginally scheduled for B30815.

 DRUMMOND, FJ Louisians Power & Light Co B3/06/16 KNIGHTON, C W Licensing Branch 3. 1p 18914 205 24% Fiche 50-382,83/06/16,8306210124.
- 8306300166 Forwards supplemental description of CE Owners Group program & scheduls in response to Generic Ltr 83-10A re guidance for closing out NOREG-0737. Item II. K 3 5. "Automatic Trip of Reactor Coolant Pumps "
 DRUMMOND,F J. Louisiana Power & Light Co 83/06/27 KNIGHTON, G W. Licensing Branch 3 6pp 19119 273, 24X Fichs 50-382,83/06/27, 8306300166.

- E NRC Safety Evaluation Report (SER), supple & correspondence
- 8306130280 Submits results of preoperational piping thermat expansion testing per SER Confirmatory Issue 3 9 P Piping & component expansions acceptable, except for deviations noted Requirements satisfied RRMMOND, F J Louisiana Power & Light Co 83/06/08 KNIGHTON, Q W Licensing Branch 3 2pp 18824 140 24X Fiche 50-782,83/06/08,8306130280
- F Security, medical, emergency & fire protection plans
- 8306130118 Forwards IE lnsp Rept 50-382/83-15 on 830301-0430 No noncompliance noted MADBEN: O. L. Region 4. Office of Director 83/05/25 NAUKIN. (V Louisiana Power & Light Co. 2pp. 18824-284 24X Fiche 50-382.83/05/25.8306130118
- --8306130127 IE Insp Rept 50-382/83-15 on 830301-0430 No nuncompliance noted Hajor areas inspected organizational changes emergency & general plant operations procedure review, preoperational test witnessing & unusual event at Union Carbide CONSTABLE, G. L., FLIPPO T. A. CROSSHAN, W. A. Region 4. Defice of Director 83/05/23 9pp 18024 206 24X Fiche 50-382,87/03/25,8306130118
- 8306140631 Forwards IE Emergency Preparedness Appraisal Rept 50-382/83-08 on 830222-0304 No noncompliance noted Schedule for completing corrective actions for deficiency noted in App A requested within 30 days of receipt of ltr HADSEN, G. L. Region 4. Office of Director 83/05/27 MAURIN, I V Louisiana Power & Light Co. 1App. 186,37, 281 24X Fiche 50-302,83/05/27,8306140631
- --8306140634 IE Emergency Preparedness Appraisal Rept 50-382/U3 OH on 830222-0304 No noncompliance noted Major areas inspected administration.emergency organization training & retraining & emergency facilities

 MACKNEY.C A . PERROTTI.D J . WIENER.C E. Region 4. Office of Director 83/05/21 57pp 18837 297 24X Fiche 50-382,83/05/27.
- 8306090406 Releases public version of revised amargancy plan implementing procedures FELTON.J M Division of Rules and Records 83/06/06 Boroment Management Branch ip 18812 071 24X Fiche 50-382,03/06/06, 8306090406
- --83060904i1 Forwards public version of revised emergency glan implementing procedures including Procedures EP-1-010 reunusual event.EP-1-020 re alert & EP-1-030 re site emergency HAURIN.L V Louisiana Power & Light Co 83/05/12 (Iffice of Nuclear Reactor Regulation, Director ip 18812-072 P4K Fiche 50-382.83/06/0406
- --B305090416 Public version of revised emergency plan implementing procedures, including Procedures EP-1-010 re unusual event, EP-1-020 re alert & EP-1-030 re site emergency * Louisiana Power & Light Co 83/04/12 663pp 18812 073 24: Fiche 50-382,83/04/04,8306070406
- B306170266 Ack receipt of 830517 ltr informing NRC of steps taken to correct violations noted in IF Insp Rept 50-382/83-13 MAURIN.4 V Lauisians Power & Light Co. 1p. 18878 155 24X Fiche 50-382,83/06/15.8306170266
- --8304170268 Responds to NRC 830413 ltr re violations noted in If Insp Rept 50-582/83-13 Corrective actions walkdown of attachments to seismic supports for fire protection piping made ASP-IV-58-1 forms generated for existing attachments. DRUMMOND.F J Louisiana Power & Light Ca 83/05/17 MADSEN.O L Region 4. Office of Director 5pp 18878 156 24X Fiche 50-382.83/06/15,8306170266
- Q Adjudicatory correspondence
- 8306070417 Forwards util 830524 news release postponing 830525 emergency planning exercise State of LA requested postponement due to actual emergency conditions caused by flooding. Svc list encl CHURCHILL, B W. Shaw, Pittman, Potts & Trowbridge CHURCHILL, B W. Louisiana Power & Light Co. 83706703 ETLPERIN, S.F. Atomic Safety and Licensing Board Panel JOHNSON, W.R., KOHL, C.N. Atomic Safety and Licensing Appeal Panel 5pp 18742 243 24X Fiche: 50-382, 63/06/03, 8306070417

- 8305150368 Exceptions to ASLO 930576 partial initial decision Certificate of Syc encl CROSSING L. Joint Intervenors-Waterford 83/06/10 Atomic Safsty and Licensing Appeal Panel App 18847 302 24X Fiche 50-382,83/06/10.8306150368
- 8306280536 Forwards CH Burstein 830616 ltr to 80 Wolfe, not served on parties WOLFE:S J Atomic Safety and Licensing Board Panel 83/06/27 Office of the Executive Legal Director Ip 19020 000 24X Fichs 50-382,83/06/27.8306280536
- ~~9305280541 Advises that author appointed Joint Intervenors counsel fracedures accessary to reopen Contention 22 re cracked slab requested BURBTEIN, C. N. Burstein, C. N. BURSTEIN, C. N. Jaint Intervenors-Waterford 83/06/16 WOIFE, S. J. Atomic Safety and Licensing Board Panel 1p 19020 004 24% Fiche 50-382,83/06/27,8306280536
- I Financial information
- 8306060117 Forwards LA Power & Light Co & Niddle South Utils, Inc Annual Financial Repts 178J DRUMHOND-F J Louisiana Power & Light Co 83/05/30 Office of Nuclear Reactor Regulation, Director ip 18728 024 24X Fiche 50-38P, 83/05/30.8306060117
- --8306060120 Annual Financial Rept 1982 CAIN.J M , WYAIT.J M Louistana Power & Light Co 93/02/2-28pp 18/28 025 24X Fisher 50-382-83/05/30.8306060117
- ~-83060602P5 Annual Financia) Rept 1982 LERIS.F W Middle Bouth Utilities, Inc - Middle Bouth Energy, Inc 83/05/30 40pp 187P8 052 F/4X Fiche 50-382,83/05/30, 8308050117
- 9 Inspection reports, IE Bullotins & correspondence
- 9304080069 Forwards IE Insp Rept 50-382/83-04 on 830117-21 No noncompliance noted MADSEN.Q L. Region 4. Office of Director 83/04/04 MAURIN.L V Louisiann Power & Light Co. 2pp. 1877-2715 24X Fiche 50-382, 83/04/04,8306080069
- --8305080074 IE Imap Rept 50-382/83-04 on 830117-21 No noncompliance noted. Hayor areas inspected radiation program actions taken on 19 open items identified in IE Imap Rept 50-382/82-04 & imap of radiation protection controls for reactor fuel CHANEY.II D . MURRAY.B . CROSSMAN.W A Region 4. Office of Director 83/03/24 32pp 18773 217 24X Fichs 50-382.83/04/04.83C6080069
- 9304010223 Forwards summery rept for action plan for task force review of installed structures/components.per Enforcement Action 82-107 Structures acceptable HAURIN, L V Louisiana Powor & Light Co 83/04/08 COLLINS, J T Region 4, Office of Director 7pp 19672 342 24X Fichs 50-382, 63/04/08 8306010923
- 9305080078 Forwards IC Insp Rept 50-382/83-07 on 830124-28 No honcompliance moted MADSEN.G L. Region 4. Office of Director 93/04/20 MAURIN,L V Louisians Power & Light Co. 2pp 187/J 055 24x Fiche 50-382,83/04/20,8306080078
- --8305080077 IE Insp Rept 50-382/03-07 on 030124-28 No noncompliance noted Major areas inspected radwaste program, including organization, training, personnel qualifications, waste sys.effluent release controls & air cleaning sys BAER, R E . MURRAY, B . CROSBNAN, W A Region 4, Office of Director 83/04/12 2ipp 18773 057, 24X Fiche 50-382,83/04/20,8306080078
- 930A010152 Informs that IE Insp Rept 50-382/83-11 canceled MADSEN.Q L Region 4, Office of Director 83/05/25 MAURIN,L V Louisians Power & Light Co Jp 18674 049 24X Fiche 30-382, 83/05/25,8306010152
- 820&130118 Forwards IE Insp Rept 50-382/83-15 on 830301-0430 No noncompliance noted HADSEN.O.L., Region 4. Office of Director 83/05/25 MAURIN.L V Louisiana Power & Light Co Ppp 18824 284 24X Fiche 50-382,83/05/25,8306130118
- --BJOM30129 IE Insp Rept 50-382/83-15 on 830301-0430 No noncompliance noted Major areas inspected organizational changes emergency & general plant operations procedure review preoperational test witnessing & unusual event at Union Carbide CONSTABLE, O L , FLIPPO, T A , CROBENAN, W A Region 4, Office of Of

- 8305110458 IE Info Notice 83-32. "Ruptured Am-241 Sources Contained in Hell Logging Device " Svc list encl TAYLOR. J M Division of Safeguards & Inspection Programs (Post 630103) 83/05/26 Comsolidated Edison Co of New York, Inc 125pp 18831 043 24X Fiche 50-000.83/05/26.8305110458
- B303110460 IE Info Notice 83-34, "Event Nutification Info Worksheet" Svc list encl
 JURDAN.E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/05/26 Consolidated Edison Co of New
 York, Inc 115pp 18732-085 24X Fiche 50-000,83/05/26,8305110460
- 8306140631 Forwards IE Emproency Preparedness Appraisal Rept 50-382/83-08 on 830222-0304 No noncompliance noted Schedule for completing corrective actions for deficiency noted in App A requested within 30 days of receipt of itr MADSEN.G L. Region 4, Office of Director 83/05/27 MAURIN, L. V. Louisiana Power & Light Co. 16pp. 18837 281 24x Fiche 50-382,83/05/27.8306140631
- --8306140636 IE Emergency Preparedness Appraisal Rept 50-382/83-08 on 830222-0304 No noncompliance noted Major areas inspected administration, emergency organization, training & retraining & emergency facilities HACKNEY.C A , PERROTTI.D J , WISNER.C E Region 4, Office of Director 83/05/21 57pp 18837 297 24X Fiche 50-382,83/05/27,8306140631
- 8305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods Withdrawn at BWRs " Svc list encl JORDAN: E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/31 Consolidated Edison Co. of New York: Inc. 116pp 18732.208 24X Fiche 50-000.83/05/31,8305110461
- B306210061 Forwards IE Insp Rept 50-382/B3-17 on 83041B-21 & notice of violation MADSEN.Q L Region 4. Office of Director B3/06/06 MAURIN.L V Louisiana Pawer & Light Co 2pp 18712 31B 24X Fiche 50~3B2.83/06/06.8306210061
- --8306210064 Notice of violation from insp on 830418-21 * Region 4. Office of Director 83/06/06 3pp 18912 320 24x Fiche 50-382,83/06/06.8306210061
- --8306210070 IE Insp Rept 80-382/83-17 on 830418-21 Noncompliance noted failure to provide safety-related records in accordance w/ established procedures on emergency feedwater sys & failure to establish adequate document control OBERO, C R , JOHNSON, C E , ROBERDS, M J Region 4, Office of Director 83/05/27 13pp 18912 323 24X Fiche.50-382,83/06/06,8306210061
- 8305110464 IE Info Notice 83-36. "Impact of Security Practices on Safe Operations " Svc list encl JRDAN.E L. Division of Emergency Preparedness & Engineering Response (Post B30103) 83/06/09 Consolidated Edison Co. of New York. Inc 119pp 18830 280 24X Fiche 50-000,83/06/09.8305110464
- 8305110470 IE Info Notice 83-38. "Defective Heat Sink Adhesive & Seismically Induced Chatter in Relays Within Printed Circuit Cards "Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co of New York, Inc 118pp 18920 225 24X Fiche 50-000,83/06/13,8305110470
- B306090010 IE Info Notice 83-37. "Transformer Failure Resulting From Degraded Internal Connection Cables." Svc list encl JURDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) B3/06/13 Consolidated Edison Co of New York: Inc 243pp 18921:001 24X Fiche 50-000,83/06/13.8306090010
- 8306170266 Ack receipt of 830517 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-382/83-13 MADSEN.9 L Region 4. Office of Director 83/06/15 MAURIN.L V Louisiana Power & Light Co ip 18878 155 24X Fiche 50-382.83/06/15.8306170266
- --B30617026B Responds to NRC B30413 ltr re violations noted in IE Inap Rept 50-382/83-13 Corrective actions walkdown of attachments to seismic supports for fire protection piping made ABP-IV-58-1 forms generated for existing attachments DRUMMIND, F. J. Louisiana Power & Light Co B3/05/17 MADBEN, Q L Region 4. Office of Director 5pp 18878 156 24X Fiche 50-382,83/06/15,8306170266
- 8306170346 Ack receipt of 830429 ltr informing NRC of steps taken to correct violations noted in IA Insp Rept 50-382/83-09, MADSEN, G L. Region 4. Office of Director 83/06/15 MAURIN, L V Louisiana Power & Light Co. Jp. 18880 158 24X Fiche 50-382,83/06/15.8306170346

- --8306170349 Responds to NRC 83030] itr re violations noted in IE Insp. Rept 50-382/83-09 Corrective actions fan motor installation verified personnel trained in use of red-line drawing procedure & Ebasco force account GC group established MAURIN.L.V Louisiana Power & Light Co. 83/04/29 MADBEN. 0 L. Repion 4. Defice of Director. App. 18890-159 24X Fiche 50-382.83/06/15,8306170346
- 8305110475 IE Info Notice 83-40. "Need to Environmentally Qualify
 Epoxy Grouts & Sealers " Svc list encl
 JORDAN-E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/06/22 Consolidated Edison Co of New
 York, Inc. 115pg 19021 179. 24% Fiche 50-000,83/06/22,8305110475
- 8305110477 IE Info Notice 83-41, "Actuation of Fire Suppression Sys Causing Inoperability of Safety-Related Equipment " Syc list enc! JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/22 Consolidated Edison Co. of New York, Inc. 120pp 18797 007 24X Fichs 50-000,83/06/22,8305110477
- 8305110479 IE Info Notice 83-42, "Reactor Mode Switch Malfunctions," Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/P3 Consolidated Edison Co. of New York, Inc. 116pp. 18996 242 24X Fiche 50-000,83/06/23,8305110479
- 8305110483 IE Info Notice 63-43, "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints "Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/24 Consolidated Edison Co. of New York, Inc. 116pp 19046 297 24X Fiche 50-000,83/06/24,8305110483
- R Periodic operating reports & related correspondence
- 8306010297 Forwards monthly rept of recruiting & upgrading total corporate capability per 810806 meeting commitment. MAURIN, L. V. Louisians Power & Light Co. 83/05/16, WILSON, J. NRC ~ No Detailed Affiliation Given 3pp 18672.186 24X Fiche 50-382,83/05/16,8306010297
- 8304280342 Forwards 22nd monthly rept re recruiting & upgrading of total corporate capability MAURIN, L V Louisiana Power & Light Co 83/06/20 WILSON, J NRC ~ No Detailed Affiliation Given 3pp 19001 210 24X Fichs 30-382,83/06/20,8304280342
- 9 Reportable occurrences, LERs & related correspondence
- B306070307 First interim Significant Const Deficiency Rept B1 re shelf life exceeded on Okonite cable splice & termination tape.Engineering evaluation ongoing Next rept will be submitted by 830722 DRUMHOND, F. J. Louisians Power & Light Co. 83/05/24 COLLINS, J. T. Region 4, Office of Director. 3pp. 18740:359 24X Fiche:50-382,83/05/24,6306070307
- 8306070317 First interim Bignificent Const Deficiency 83 re heat tracing design electrical interference identified during hot functional testing Corrective action ongoing Completion expected by 830815 Next rept by 830826

 DRUMMOND.F.J Louisiana Power & Light Co 83/05/24 COLLINS.J T Region 4. Office of Director 3pp 18744.241 24X

 Fiche.50-382.83/05/24.8306070317
- B30A0100B4 Interim Bignificant Const Deficiency Rapt B2 re bent control element assembly rods. Initially reported on B30425 Control element assemblies LA-13 & LA-38 sent to vendor for evaluation Addl info expected by 830816
 DRUMMOND, F J Louisians flower & Light Co. B3/05/25 *COLLINB, J. T. Region 4, Office of Director 5pp 18674.098 24X
 Fiche 50-382,83/05/25,8306010084
- 8306070169 Sixth interim rept of Bignificant Const Deficiency 37 re failures of resistance temp detectors (RYD). Due to restrictions placed on entering RTD cabinets during testing, submittal of final rept delayed until 830612, DRUMMOND, F. J. Louisians Power & Light Co. 83/05/26 COLLINS, J. T. Region 4, Office of Director ip 18736, 280 24% Fiche 50-382,83/05/26,8306070169.
- 8306070274 Significant Const Deficiency 42 R-1 re HMA auxiliary relays, Initially reported on 830328 NCR W3-3361 redispositioned to use heat shrink tubing available onsite. Final rept delayed until 830717 DRUMHOND, F. J. Louisiane Power & Light Co. 83/05/26. COLLINB, J. T. Region 4. Office of Director. 19 18744 082. 24X Fiche 50-382,83/05/26,8306070274.

- 8304070133 Third interim rept re Significant Const Deficiency 48 concerning spurious ESF actuation sys acutation Initially reported on B30331 Corrective action completed Supporting info assembled for 94 review Final rept by 830624 DRUMMOND.F J Louisiana Power & Light Co 83/05/30 COLLING Region 4. Office of Director ip 18707 214 24X Fiche 50-382,83/05/30,8306070133
- 8306160002 Final rept of Significant Const Deficiency 31 re inco friction factor in pipe support hanger designed by Bergan-Paterson Nonconformance Rept W3-2732 identified, dispositioned & tracked all supports requiring rev & rework DRUMMOND, FJ Louisiana Power & Light Co 83/06/08 CDLLING Region 4, Office of Director. 3pp 18061 322 24X Fichs. 50-382, 83/06/08, 8306160002
- B304270052 Interim Bignificant Const Deficiency Rept 77 re unqua components in hydrogen analyzers Gwalified replacement pump maters not yet installed Final rept expected by B3D729 DRUMMOND.F. J. Louisiana Power & Light Co. B3/06/15 COLLINS Repion 4. Defice of Director ip 19013 359 24X Fiche 50-382.83/06/15.8306270052
- 8306270127 Interim Significant Const Deficiency Rept 84 rs tube welding not meeting AMS D 1 i requirements FCR-ICP-564 R-1 issued on 830511 by Ebasco Engineering to provide corrective action guidelines Final rept expected by 830831 DRUMMOND: F J Louisiana Power & Light Co 83/06/15 CCLLINS Region 4. Office of Director 3pp 18708 089 24X Fichs 50-382.83/06/15.8306270127
- 8306270213 Second interim deficiency rept re American Bridge rea auxiliary & fuel bandling bidg bolting & welding Significant Const Deficiency SCD 73 combined w/SCD 78. Reinap will be completed on 830815, w/sept by B30831 DRUMMOND, F. J. Louisiana Power & Light Co. 83/06/15 CDLLINS Region 4, Office of Director ip 18791 257 24X Fiche 50-382,83/06/15,8306270213
- 8306270310 Second interim Significant Const Deficiency Rept 74 r Undersize Schedule 80 socket welds All rework completed except for two flanges Final rept expected by 830729 DRUMMOND, F J Louisiana Power & Light Co 83/06/15 COLLINE Region 4, Office of Director 1p 10795 221 24X Fiche 50-382,83/06/15,8306270310
- 8306270330 Fourth interim rept re Significant Const Deficienty & concerning possible failure of GE Type HFA relays initially reported on B30429 Corrective action incomplete Final rept will be submitted by B30726
 DRUMHOND, F. J. Louisiana Fower & Light Co. 83/06/15 COLLING Region 4, Office of Director ip 18993-045 24X
 Fiche 50-382,83/06/15,8306270330
- B306300079 Third interim rept on Significant Const Deficiency 76 480-volt trip coil failure to drop out after tripping Corrective action complete & supporting documentation under review Final rept will be submitted by B30722 BRUMMOND, F J Louisiana Power & Light Co B3/06/22 COLLIN: Region 4. Office of Director 1p 19121 040 24X Fiche 50-382,83/06/22.8306300079
- 8306300188 Fourth interim rept on Significant Const Deficienty a sourious ESF actuation sys operation Required mode completed Testing still underway Final rept will be submitted by 830826 DRUMMOND, F. J. Louisiana Power & Light Co. 83/06/22 COLLING Region 4. Office of Director ip 19119 255 24X Fiche: 50-382, 83/06/22, 8306300188
- DOCKET 50-387 SUBQUEHANNA STEAM ELECTRIC STATION, UNIT 1 E NRC Bafety Evaluation Report (SER), supple & correspondence
- 8304140448 Forwards supplemental response to SER Open Item 3 10 Fatigue cycling affects on N888 aquipment due to safety relief loads (License Condition 23(a)) discussed CURTIE, N W Pennsylvania Power & Light Co 83/06/09 SCHMS Licensing Branch 2 83pp 18833 182 24X Fiche 50-387, 83/0 8306140648.
- 0306230430 Forwards listings of Reg Guide 1.97 Rev 2.instrument of equipment qualification for post-accident monitoring equipment in response to SER. Suppl 5 Qualification of equipment will be completed by 850331 for Unit 2 CURTIS. N. Pennsylvania Power & Light Co 83/06/20 SCIANE Licensing Branch 2 17pp 18943 215 24X Fiche, 50-387, 8306230430

- 8306230466 Responds to SER, Suppl 5, Item 3 1: 1(1)(a) re nonsafety-related electrical equipment Failure of nonsafety-related equipment unlikely due to classification under qualification program
 CURTIS, N W Pennsylvania Power & Light Co 83/06/20 BCHHENCER, A Licensing Branch 2 1p 18941 159 24X Fiche 50-387,83/06/20, 8306230466
- F Security, medical, emergency & fire protection plans
- 830&070Ri4 Forwards Change N to physical security plan Change withheld (ref 10CFR2 790) KENYON, B D Penney Ivania Power & Light Co 83/05/06 ALLAN, J M Region 1, Office of Director 1p 18/47 020 24X Fiche 50-38/, 83/05/06, 8306070714
- 8306010171 Ack receipt of 830428 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-387/83-04 MARTIN, T T Division of Engineering & Technical Programs 83/05/26 KENYON, B D Pennsylvania Power & Light Co ip 18673 034 24X Fiche 50-387,83/05/26,8306010171
- --930A010177 Responds to NRC 830331 ltr re violations noted in IE Insp Rept 50-387/83-04 Corrective actions separate security event log established per 10CFR73 71(c) MENYON. II D Pennsylvania Power & Light Co 83/04/28 MARTIN.T T Division of Engineering & Technical Programs 2pp 18673 035 24% Fiche 80-387, 83/05/26, 830A010171
- B30A090010 Releases public version of revised emergency plan implementing procedure & responses to request for addl info FELTON, J M Division of Rules and Records B3/06/06 Document Management Branch 1p 18798 178 24X Fiche 50-387,83/06/06, B30A090018
- --E306090021 Forwards public version of response to request for add1 info re emergency plan & Rev O to Emergency Plan Implementing Procedure EP-IP-iOI re inventory, insp. operational testing & calibr of emergency equipment & supplies CURTIS, N W. Pennsylvania Power & Light Co 83/05/26 SCHMENCER, A Licensing Branch 2 9pp 18798 179 24X Fiche 50-387,83/06/06,8306090018
- --830609002& Public Version of Rev O to Emergency Plan Implementing Procedure FP-IP-101 ro inventory, insp. operational testing & calibr of smargency equipment & supplies KEIBER, H Pennsylvania Power & Light Co 82/07/15 57pp 18798 188 24X Fiche 50-387,83/06/06,8306090018
- 830&210143 Forwards change to physical security plan Change withheld (ref 100FR2,770)
 KENYON, B. D. Pennsylvania Power & Light Co. 83/06/16. ALLAN, J. M. Region 1, Office of Director. 1p. 16919-037. 24X
 Fiche 50-387,83/06/16,8306210143
- B306280368 Provides Add1 justification for B30427 proposed Amend 23 to License NPF-14 Safety parameter display sys for emergency situation will be operational by B31230. fellowing completion of training & verification CURTIG.N W Pennsylvania Power & Light Co B3/06/23 SCHMENCER. A Licensing Branch 2 2pp 19001 276 24X Fiche 50-387, 83/06/23, B30620368
- 8306300092 Informs of emergency power supply addition to recirculation pump seals in cooling sys Action on License Condition 2 C 28(f) closed, CURTIS:N W Pennsylvania Power & Light Co 83/06/27 8CHWENCER.A Licensing Branch 2, ip 19121 041 24X Fiche 50-387,83/06/27, 8306300092
- P Operating license stage documents & correspondence
- B20B060366 Board Notification 82-70 notifies of differing prof opinion re sensitization of BWR stainless steel weldments.
 EISEMHUT, D Q Division of Licensing 82/07/20 PALLADING, N J , QILINBKY, V , AHEARNE, J Commissioners. App 17043 001 24X Fichs. 50-387, 82/07/20, 8208060366
- B306010330 Notifies that BWR Owners Group control room survey program not utilized at facilities, per Generic Ltr B3-18 Initial control room design review conducted prior to licensing, NRC evaluation of review contained in App F to BER.

 CURTIS, N W Pennsylvania Power & Light Co 83/05/26 BCHWENGER, A Licensing Branch 2 1p 19681.277 24X Fiche: 50-387, 83/05/26, 83/06/10330

- 8304020429 Forwards state historical preservation of response concurring w/util opinion that plant const will have no adverse effect on archaeological sites in area.per 830315 request CURTIS.N W Pennsylvania Power & Light Co 83/05/31 SCHWENCER.A Licensing Branch 2 4pp 18694 104 24X Fiche 50-387.83/05/31, 8306020429
- 8306150275 Submits daily highlight Util announced that plant began commercial operation on 830608
 PERCH,R L. Licensing Branch 2 83/06/08 DENTON,H R , CASE,E Q , CARTER, J. Diffice of Nuclear Reactor Regulation, Director ip 18869 360 24X Fichs 50-387,83/06/08,8306150275
- 8306170445 Notification of 830617 meeting w/util in Bethesda.MD to discuss ECCB activation instrumentation PERCH.R Licensing Branch 2 83/06/08 SCHWENCER.A Licensing Branch 2 3pp 18907 330 24X Fiche 50-387.83/06/08.8306170445
- 8306170188 Forwards "Susquehanna Steam Electric Station Unit 1 Startup Rept." per Tech Spec Section 6 9 i 1 Supplemental rept will be submitted within 90 days KENYON, B D Pennsylvania Power & Light Co 83/06/10 ALLAN, J N Region 1. Office of Director ip 18802 326 24% Fiche 50-387,83/06/10,8306170188
- --8306170191 "Susquehanna Steam Electric Station Unit 1 Startup Rept " KEISER: H W Pennsylvania Power & Light Co 83/06/09 172pp 18882 327 24X Fiche 50-387.83/06/10,8306170188
- B306230297 Forwards final response to Humphrey Issues 3 1 & 3 3 re hydrodynamic loads caused by actuation of RHR safety relief valve during steam condensing mode of RHR sys CURTIS.N W Pennsylvania Power & Light Co 83/06/15 9CHMENCER, A Licensing Branch 2 44pp 18945 169 24X Fiche 50-387, 83/06/15, 8306230297
- 8306210220 Forwards metl presented at Anderson, Greenwood & Co (AGCo) vacuum breaker test program owners group 830607 meeting w/ NRC re dynamic testing & analysis of AGCo vacuum breaker valve assemblies of CONNOR, D M Bechtel Corp 83/06/17 HOUSTON, R W Division of Systems Integration (post 811005) 91pp 18919 038 24X Fiche 50-000,83/06/17,8306210220
- 8306280368 Provides addl justification for 830427 proposed Amend 23 to License NPF-14 Safety parameter display sys for amergency situation will be operational by 831230, following completion of training & verification CURIIS.N W Pennsylvania Power & Light Co 83/06/23 8CHMENCER.A Licensing Branch 2 2pp 19001 276 24% Fiche 50-387,83/06/23, 83062038
- 8306300185 Advises that NRC concern re-primary containment vacuum breaker cyclic impact loading caused by pool swell phenomena during LUCA event should be considered resolved based on listed refs.per 830627 1tr CURTIS.N W Pennsylvania Power & Light Co 83/06/27 8CHMENCER.A Licensing Branch 2 10 19122 195 24X Fiche 50-387.83/06/27, 8306300185
- Q Inspection reports: IS Bulletins & correspondence
- B306220155 Discusses lE in*p on B30112-030B & forwards notice of violation & proposed imposition of civil penalty ALLAN,J M. Region i, Office of Director. B3/04/22 KENYON,B D Pennsylvania Power & Light Co 4pp 18937 330 24X Fiche 50-387,83/04/22,8306220155
- --B306220159 Notice of violation & proposed imposition of civil penalty in amount of \$60,000 Noncompliance noted inadequate review & approval of maint activity, which resulted in inoperability of both subsystems of standby gas treatment sys ALLAN, J M Region I. Office of Director 83/04/22 5pp 18937.334 24X Fiche 50-387,83/04/22,8306220155
- 8306010121 Forwards IE Insp Repts 50-387/83-11 & 50-388/83-04 on 830406-0503 & notice of violation of STARDETECKI, R Division of Project & Resident Programs 83/05/16 KENYON, D D Pennsylvania Power & Light Ca 2pp. 18674 001 24X Fiche, 50-387, 83/05/16, 8306010121
- --8306010124 Notice of violation from insp on 830406-0503 * Region 1. Office of Director 83/05/16 ip 18674 003 24X Fiche 50-387,83/05/16,8306010121

- --8304010134 IE Insp Repts 50-387/83-11 & 50-388/83-04 on 830406-0503
 Noncompliance noted numerous fuses had one terminal
 disconnected on temporary mod control panels 2C661 B2 & 3,
 opening circuit & no identification tags applied
 RHOADS, 9, MCCANN.J Region 1. Office of Director MCCABE, E C
 Division of Project & Resident Programs 83/05/13 15pp
 18674-004 24% Fiche 50-387,83/05/16.8306010121
- 83040R044R Ack receipt of 830328 ltr informing NRC of steps taken to correct violations noted in IE lnsp Rept 50-387/83-02 MARTIN, T Division of Engineering & Technical Programs 83/05/20 KENVON, B D Pennsylvania Power & Light Co 2pp 18694 088 24X Fiche 50-387.83/05/20.8304020442
- --8306020444 Responds to NRC 830224 ltr re violations noted in IE Insp Rept 50-387/83-02 Corrective actions memo sent to all members of chemistry group re changes to performance check procedures KENYON, B D Pennsylvania Power & Light Co 83/03/28 MARTIN, T T Division of Engineering & Technical Programs 9pp 18694 090 24X Fiche 50-387, 83/05/20, 8306020442.
- 8305110458 IE Info Notice 83-32. "Reptured Am-241 Sources Contained in Well Logging Device " Syr list encl TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 63/05/26 Consolidated Edison Co of New York, Inc 125pp 18831.043 24X Fiche 50-000,83/05/26.8305110458
- 8305110460 IE Info Notice 83-34, "Event Notification Info Worksheet,"

 Svc list encl

 JORDAN, E.L. Division of Emergenty Preparedness & Engineering

 Response (Post 830103) 83/05/26 Consolidated Edison Co. of New

 York, Inc. 115pp 18732-085 24X Fiche 50-000,83/05/26,83051j0460
- 8304010171 Ack receipt of 830428 ltm informing NRC of steps taken to correct violations noted in IE Insp Rept 50-387/83-04 MARTIN. T Division of Engineering & Technical Programs 83/05/26 KENYON, B D Pennsylvania Power & Light Co ip 18673 034 24X Fiche. 50-387,83/05/26,8306010171
- --8306010177 Responds to NRC 830331 ltr re violations noted in IE Insp Rept 50-387/83-04 Corrective actions separate security event log established per 10CFR73 71(c) KENYON, B D Pennsylvania Power & Light Co 83/04/28 MARTIN, T T Division of Engineering & Technical Programs 2pp 19673 035 24X Fiche 50-387, 83/05/26, 8306010171
- 8305110441 IE Info Notice 83-35, "Fuel Movement W/Control Rods Withdrawn at DWRs " Svc list encl JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103), 83/05/31. Consolidated Edison Co. of New York, Inc. 114pp 18732 208 24% Fiche 50-000.83/05/31,8305110461
- 8306150278 Ack receipt of 830520 ltr & Pull payment of proposed civil penalty Response to notice of violation to be evaluated during future insp.

 AXELRAD.J A Director's Office. Defice of Inspection and Enforcement 83/06/06 KEYON.B D Pennsylvania Power & Light Co 2pp. 18869, 320. 24X Fiche 80-387.83/06/06.8306150278
- 8306200135 Forwards IE Insp Rept 50-387/83-08 on 830310-0428 No noncompliance noted MARTIN, T T Division of Engineering & Technical Programs 83/06/06 KENYON, B.O. Pennsylvania Power & Light Co 2pp 18903 274 24X Fiche 50-387,837/06/06 8306200135
- --830A20013A IE Insp Rept 50-387/83-08 on 830310-0428 No noncompliance noted Major areas inspected startup test exceptions, power excelation testing Conditions 4 & 6 transient testing & warranty test.

 CHUNG. J W , BETTENHAUSEN. L Region 1. Office of Director 83/06/01 8pp. 18903 276 24% Fiche 50-387,83/04/06.8306200135
- 8305110464 IE Info Notice 83-36, "Impact of Security Practices on Safe Operations " Svc list encl.
 JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/09 Consolidated Edison Co. of New York, Inc. 119pp 18830.280 24X Fiche 50-000,83/06/09,8305110464
- 8306140482 Responds to IE Bulletin 83-03. "Check Valve Failures in Raw Hater Cooling Sys of Diesel Generators" Listed check valves in essential ave water flowpath will be included in Rev 2 to 830650 pump & valve inservice test program. KENYON. B D Pennsylvania Power & Light Co. 83/06/09 ALLAN, J, M Region 1. Office of Director 1pp 18834-173 24X Fiche 50-387, 93/06/09.8306140482
- 8305110470 IE Info Notice B9-38. "Defective Heat Bink Adhesive & Beismicelly Induced Chatter in Relays Within Printed Circuit Gards "Svc list encl.
 JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Past 630103) 83/06/13. Consolidated Edison Co. of New York, Inc. 118pp. 18920-225 24X Fiche 50-000.83/06/13.8305110470

- 8306090010 IE info Notice 83-37, "Transformer Failure Resulting From Degraded Internal Connection Cables" Svc list encl JORDAN, E. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consultated Edison Co. of New York, Inc. 243pp 18921 001 24X Fichs 50-000,83/06/13.8306090010
- B305110475 IE Info Notice 83-40, "Need to Environmentally Qualify
 Epoxy Grouts & Smalers " Sv. list encl
 JORDAN. E. Division of Emergency Preparedness & Engineering
 Response (Post B30103) B3/06/22 Consolidate Edison Co of Hr.
 York. Inc 115pp 19021 179 24X Fiche 50-000.83/06/22.0305110475
- 6305110477 IE Info Notice 83-41. "Actuation of Fire Suppression Sys Causing Inoperability of Safety-Related Equipment " Syc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/22 Consolidated Edison Co of New York, Inc 120pp 18997 007 24X Fishe 50-000.83/06/22.8305110477
- 8305110479 IE Info Notice 83-42, "Reactor Mode Switch Malfunctions " Bvc list encl JORDAN E L Division of Emergency Proparedness & Engineering Response (Post 830103) 83/06/23 Consolidated Edison Co of New York, Inc 114pp 18994 242 24X Fiche 50-000, 83/06/23, 8305110177
- 8305110483 IE Info Notice 83-43, "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints " Svc list encl JORDAN.E L Division of Emergency Proparedness & Engineering Response (Post 830103) 83/06/24 Consolidated Edison Co of New York, Inc 116pp 17046 297 24X Fiche 50-000,83/06/24.8305110483
- A Periodic operating reports & related correspondence
- 9306020223 Monthly operating rept for Mar 1983 W/830415 ltr KUCZYNSKIL A. KENYON B.D. Pennsylvania Power & Light C 93/04/08 BEEDE.M R. Management Information Branch 6p; 18691 129 24X Fiche 50-387,83/04/08,8306020223
- 8306270248 Forwards "Annual Environ Operating Rept (Nonradiological) 1982" & "Radjological Environ Monitoring Pregram 1982" KENYON, B.D. Pennsylvania Power & Light Co. 83/04/28 ALLAN, J. R Region 1, Office of Director 1p 18995 290 24X Fichs 50-387,83/04/28,8306270248
- --8306270251 "Radiological Environ Monitoring Program 1982" * Radiation Management Corp. RMC-TR-83-02 83/04/30 71pp 18995 291 24X Fiche 50-387,83/04/28.8306270248
- --8306270253 "Annual Environ Operating Rept (Nonradiological) 1982 '
 FIELDS.J S , SHANK.K E , MILLER,D W Pennsylvania Power & Light
 Co 83/04/27 135pp 18996 037 P4X Fiche, 50-387, 83/04/28
 8306270248
- 8306160472 Nonthly operating rept for Apr 1983 W/830510 ltr KUCZYNSKI, L A. KENYON, B D Pennsylvania Power & Light Co 83/05/06 BEEBE, M R Division of Data Automation & Management Information 5pp 18862 248 24X Fiche 50~387,83/05/06,830616472
- S Reportable accurrences, LERs & related correspondence
- 8306010070 LER 83-061/01P-0 on 830414, during loss of offsite power test; controller for heater element in standby gas treatment sys failed Caused by loss of power condition initiating low temp

 KEISER, H W Pennsylvania Power & Light Co 83/05/09 ALLAN, J M Ragion i, Office of Director ip 18673 362 24X

 Fiche 50-387,83/05/09,8306010070
- 9304010313 LER 83-065/01P-0 on 830511 & 12, reactor bldg, turbine bldg 4 standby gas treatment sys sample flow rate monitors out of avc Gaused by switch to alternate power supply in preparation for loss of offsite power test KEISER, H W Pennsylvania Power & Light Co 83/05/12 ALLAN, J K Region 1. Office of Director ip 18672 311 24X Fiche 50-387, 83/05/12, 8304010313
- 8306010323 LER 63-057/0IT-0 on 830428 bypass leakage calculations for feedwater ags found invalid Caused by assuming 30-day water seal during post-LOCA conditions Nonbypass leakage boundary valves reworked W/830512 ltr
 KEISER, H. W., PIEMONTESE, A.P. Pennsylvania Power & Light Co. 83/05/12. ALLAN, J. M. Region 1, Office of Director 3pp. 18682 272 24X Fiche 50-387,83/05/12,8304010323
- 8306010068 LER 83-064/03L-O on 830414, local leak rate test for main steam line C exceeded Tech Spec value Cause not stated inboard MBIV reworked & valve retested W/830513 ltr TODD, J T , KEISER, H W Pennsylvenia Power & Light Co 83/05/13 ALLAN, J M Region i. Office of Director 2pp 18674 087 24X Fiche: 50-387, 83/05/13, 8306010068

- 8304010097 LER B3-062/03L-0 on B30414.local leak rate test on main steam line A discovered leakage in excess of Tech Specs Cause not stated Inboard MSIV reworked Normal lapping performed on valve disc & seat W/B30513 ltr T0DD.J T . KEISER, H W Pennsylvania Power & Light Co 83/05/13 ALLAN.J M Region i. Office of Director 2pp 18674 115 24X Fiche 50-387.83/05/13.8306010097
- 8306010150 LER 83-066/03L-O on 830414.during removal of Pacific check valve internals valve disc found lodged in pipe & cotter pin & nut missing Cause not stated Insp will be performed to locate nut W/830513 ltr
 KUCZYMSKI.Ł A, KEISER.H W Pennsylvania Power & Light Ca 83/05/13 ALLAN.J M Region i, Office of Director 3pp 18674 Q57 24X Fiche 50-387.83/05/13.8306010150
- 8306010061 LER 83-067/01P-0 half scram received & MSIV B status light went out after reactor mode switch moved to startup position Neither switch would reset Addl info re cause & corrective action forthcoming KEISER.H W Pennsylvania Power & Light Co 83/05/17 ALLAN, J M Region 1. Office of Director ip 18674-086 24X Fiche 50-387,83/05/17,8306010061
- 830A010309 LER 83-070/01P-0 on 830518.control room emergency outside air sys declared inoperable Caused by discrepancies in 5.810 cfm flowrate specified Tech Spec requirements Sys inoperable until procedure changed KEISER.N W Pennsylvania Power & Light Co 83/05/18 ALLAN, J M Region 1. Office of Director 1p 18672 318 24X Fiche 50-387.83/05/18.8306010709
- 8306010278 LER 83-068/03L-0 on 830419, during surveillance testing to demonstrate diesel generator operability following maint, diesel generator A failed to start within required 10 s Caused by lines drained during maint W/830519 ltr KUCZYNSKI, L A, KEISER, H W Pennsylvania Power & Light Co 83/05/19 ALLAN, J M Region 1, Office of Director 2pp 18672.237 24X Fichs 50-387.83/05/19,8306010278
- 8306020369 LER 83-061/01T-0 on 830508, during performance of simulated loss of offsite power test to close startup test exception, standby gas treatment sys failed to develop 10 degree Delta T across heater within 200 s time delay W/930520 ltr PIEMONTERS A P. KEISER, H W Pennsylvania Power & Light Co 83/05/20 ALLANJ M Region 1, Office of Director 3pp 18695 103 24X Fiche 50-387,83/05/20.8906020369
- 830A0R0394 LER 83-069/03L-0 on 830424, during precommercial operation outage & removal of ECCS, leaking relief valve discovered in core spray keep-fill sys Caused by inadequate pressure control in sys W/830524 ltr KUCZYNBKI.L A. KEISER.H W Pennsylvania Power & Light Co 83/05/24 ALLAN.J M Region 1. Office of Director Spp 18695.006 24X Fiche 50-387.83/05/24.8306020394
- B306010218 Part 21 rept re screw-clamp type lugs which may not form adequate connection when used w/14 B1S stranded wire Defective lugs identified as ILSCO Corp SLUM-90 ILBCO lugs replaced w/proper sized crimped connection ring lugs KENYON, B D Pennsylvania Power & Light Co. B3/05/25 ALLAN, J M Region 1. Office of Director 2pp 18673 009 24X Fiche 50-387,83/05/25,8306010218
- 8308020382 LER 83-065/01T-O on 830511.while preparing for standby gas treatment sys testing, three vent monitor sample pumps lost for 5 h 4:15 minutes Gause unknown Procedural & stack monitoring sys reviews will be performed W/830525 ltr XUCZYNSKI.L.A., KEISER.H W Pennsylvania Power & Light Co 83/05/25 ALLAN.J M Region 1. Office of Director 5pp 18694 348 24X Fiche 50-387,83/05/25,8306020382
- 8306020401 Updated LER 83-059/03X-1 on 830404.plant placed in cold shutdown per planned outage/test schedules Analysis of test data on 830405 showed Level 1 test criteria not met for one valve Caused by leaking dashpot W/830525 ltr PIEMONTESE.A P. KEISER, H. W. Pennsylvania Power & Light Co 83/05/25 Region 1. Defice of Director 4pb 18695 158 24X Fiche 50-387,83/05/25,8306020401
- 8396170217 LER 83-071/03L-0 on 830426, overvoltage setting on one RPS alternate electrical protection assembly found greater than Tech Spec limit Caused by instrument drift Overvoltage setting calibr within limits W/830526 ltr XUCZYNBKI.L A . KEISER, H W Pennsylvania Power & Light Co 83/05/26. ALLAN, J M Region 1. Office of Director Ppp 18878 314 24X Fiche 50-387, 83/05/26, 8306170217
- 8305210212 Updated LER 83-043/01X-1: on 830322, reactor mode switch turned to shutdown position actuated half scram. Caused by two reactor mode switch contact failures Switch replaced Procedures revised W/undated forwarding ltr KEISER. H W . KUCZYNSKI. L A Pennsylvania Power & Light Co 83/03/26. ALLAN, J M Region i. Office of Director 3pp 18719.027. 24X Fiche 50-387,83/05/26.8306210212

- 8306280434 RD fire door found blocked open for period in excess of 7 days Caused by welding lead run through doorway during approved work activity Welding lead removed upon completion of job

 KEISER, H W Pennsylvania Power & Light Co 83/05/26 ALLAN, J M Region 1. Office of Director ip 19020 328 24% Fiche 50-387,83/05/26,8306280434
- 8306170015 LER 83-075/01T-0 on 830515, found chlorine detectors on control room emergency outside air supply may prevent operation in pressurization mode following loss of power Emergency operation procedures revised W/830527 Itr PIEMONTESE, A P. KEISER, H W Pennsylvania Power & Light Co. 83/05/27 ALLAN, J M Region i, Office of Director 3pp 18882 270 24X Fiche 50-387,83/05/27.8306170015
- 8304170037 LER 83-070/01T-0 on 830517. flow rates required to maintain gositive pressure in control structure appeared to exceed Tech Spec Ilmits Flow limit inadvertently omitted from procedure Forected W830527 INSOS27 P. FIEMONTERE, A P. KIEBER, H. W. Pennsylvania Power & Light Co. 8370527 ALLAN, J. M. Region I. Office of Director 3pp. 18882 229 24X Fiche 50-387,83/05/27.8306170037
- 830.6170413 LER 83-067/01T-0 on 830516 reactor mode switch placed in startup position & half scram developed Caused by improper functioning of reactor mode switch contacts Switch replaced. W/830527 ltr KUCZYNSKI, L A . KEISER, H W Pennsylvania Power & Light Co. 83705/27 ALLAN, J M Region 1, Office of Director 4pp 18879 329 24X Fiche 50-387,83/05/27,8306170413
- B306090246 LER B3-076/01P-0 on B30527, walkdown of control room emergency outside air supply systewealed cables run through open door Cables removed & door closed KEISER, H. W. Pennsylvania Power & Light Co. 83/05/31 ALLAN, J. M. Region 1. Office of Director ip 18795-320 24X Fiche 50-387, 83/05/31,8306090246
- 830.6280399 LER 83-082/01P-0 on B30607, main turbine trip function (high reactor vessel level) bypassed for post-mod testing on turbine control valves Trip function not returned to svc prior to Operational Condition 1
 KEISER, H W Pennsylvania Power & Light Co 83/06/08 ALLAN, J. M. Region 1. Office of Director ip 19001 358 24X
 Fiche 50-367, 83/06/08, 8306280399
- B30428051B LER 83-081/O3L-0 on B30511, in Operational Condition 4, shutdown cooling not promptly returned to svc following ABHE Class I boundary leak test Caused by amount of time required to fill vent sys following leak test H/B3060B ltr PIEMONTESE, A P., KEISER, H W Pennsylvenia Power & Light Co B3/06/06 ALLAN, J M Region 1, Office of Director 3pp 19017 209 24X Fichs 50-387, B3/06/08, B306280518
- 8306280348 LER 83-077/03L-0 on B30510, seven snubbers w/inadequate clearance identified indicating possible rear bracket interference Caused by lack of info from snubber vendor. Snubbers reworked W/830607 ltr KUCZYMSKI.L A. XETSER.H H Pennsylvania Power & Light Co 83/06/07 ALLAN.J M Region i, Office of Director 3pp 19001 260 24X Fiche 50-387,83/06/09,830689348
- 8306280140 LER 83-080/03L-0 on 830513, setpoint for PDIS-E-11-INQ198 (shutdown cooling high flow) found out of tolerance Caused by setpoint drift Switch recalibr & returned to svc W/830610 ltr.
 PIEMONTESE, A P., KEISER, H. W. Pannsylvania Power & Light Co. 83/06/10 ALLAN, J. M. Region 1, Office of Director Pap. 19014 327 24% Fiche 50-307,83/06/10,8306280140.
- 8306280310 LER 83-076/0iT-0 on 830527, w/control structure door blocked open to run electrical cables through for battary testing, control room emergency autside air supply sys unable to pressurize. Caused by personnel error. W/830610 Itr. EIBENHUTH, F. T., KEIBER, H. W. Pennsylvania Power & Light Co 83/06/10 ALLAN, J. M. Region I. Office of Director 3pp 19017 238 24% Fichs 50-387,83/06/10,8306280510
- 830628054B Requests that 830526 release date & Transmittel Number PLA-1670 be added to LER 83-043/01X-1 transmittel ltr KEISER, H W. Pennsylvania Power & Light Co. 83/06/10. ALLAN, J H Region 1. Office of Director 1p 17017, 304 24X Fiche. 50-387, 83/06/10, 830628054B
- 8306170343 PNO-I-83-060 on 830614, reactor tripped from 100% power due to high radiation signal sensed in main steam lines Caused by air pocket in steam lines Safety relief valve cycled & RGIC manually restarted RHOADS, 0, GRCENMAN, E. Region 1, Office of Director 83/06/14 1p 1880 083 24% Fiche \$0-387,83/06/14,8306170343

- 8306210050 LER 63-079/03L-0 on 830515 inboard & outboard dilution flou transmitters found valved out Caused by personnel error Event rept given to personnel & will be discussed at next meeting W/830614 ltr KUZCYNSKI.L A , KEISER, H W Pennsylvania Power & Light Co 83706/14 ALAN, J M Region 1. Office of Director 3pp 18911 352 24X Fiche.50-387.63/06/14.8306210050
- 8306280582 PNS-I-83-016; on 830622, bomb threat by unidentified male caller received at plant site & TV station Reactor & turbine bldge evacuated & search procedures initiated, per emergency & safeguands contingency plans Results negative MADDEN.H. 00DY.A Region I. Office of Director 63/06/23 2pp 19017.328 24% Fiche 50-887.83/06/23.8306280582
- 8306280006 NPDES noncompliance natification on 830619, total iron limit in Discharge O41A exceeded level Cause under investigation FIELDB.J. B Pennsylvania Power & Light Co 83/06/24 KOVAL, P. Pennsylvania, Commonwealth of. ip J7001 122 24X Fiche 50-387, 83/06/24, 8306280006

V Operator Examinations

- 8306140017 Extends invitation to attend 830627 meeting in King of Prussis, PA to discuss transfer of reactor operator licensing function from Bethesds, MD to Region 1 ofc 8TAROSTECKI. 8 Division of Project & Resident Programs 83/05/09 KENYON, 8 D Pennsylvania Power & Light Co 2pp 18838 235 24X Fichs: 50-387,83/06/09.8306140017
- DOCKET 50-388 SUSQUEHANNA STEAM ELECTRIC STATION, UNIT 2

 A Application/construction stage documents & correspondence
- 8208060366 Board Natification 82-70 notifies of differing prof opinion re sensitization of BWR stainless steel weldments EISENHUT, D © Division of Licensing 82/07/20 PALLADING, N J . QTLINSKY, V , AMERIKE J Commissioners 4pp 17043.001 24x Fiche 50-387,82/07/20,8208060366
- 8304010330 Notifies that BWR Owners Group control room survey program not utilized at facilities, per Generic Ltr 83-18. Initial control room design review conducted prior to licensing NRC avaluation of review contained in App f to SER CURTIS, N W Pennsylvania Power & Light Co 83/05/26 BCHMENCER, A Licensing Branch R. 1p. 18681-277 24X Fiche 50-397, 83/05/26, 8306010330.
- 8306020429 Forwards state historical preservation ofc response concurring w/util opinion that plant const will have no adverse effect on archaeological sites in area, per 830315 request.

 CURTIS, N. W. Pennsylvania Power & Light Co. 83/05/31 SCHWENCER, A. Licensing Branch 2 4pp 18694 104. 24X Fiche 50-987, 83/05/31, 8306020429
- 8304230277 Forwards final response to Humphrey Issues 3 1 & 3 3 re hydrodynamic loads caused by actuation of RHR safety relief valve during steam condensing mode of RHR sys. CURTIS.N W Pennsylvenia Power & Light Co 83/06/15 SCHWENCER.A Licensing Brench 2 44pp 18745:169 24X Fichs 50-087,83/06/15, 8306230277,
- 830A2i0220 Forwards mat1 presented at Anderson, Greenwood & Co (AGCo) vacuum breaker test program owners group B30A07 meeting w/ NRC re dynamic testing & analysis of AGCo vacuum breaker valve assemblies, O'CONNOR.D.M. Bechtel Corp. B3/OA/17 HOUSTON.R.H. Division of Systems Integration (post SiiOOB) 9ipp 18919 038, 24X Fiche: 50-000, 83/06/17, 8306210220.
- 8306300185 Advises that NRC concern re primary containment vacuum breaker cyclic impact loading caused by pool swell phenomena during LOCA event should be considered resolved based on listed refs.per 830627 ltr.
 CURTIS.N.W. Pennsylvania Power & Light Co 83/06/27 SCHMENCER, A Licensing Branch 2. Ip 19122-195 P4X Fiche. 50-387,83/06/27, 8306300185.
- E. NRC Safety Evaluation Report (SER), suppls & correspondence
- 8304140448 Forwards supplemental response to BER Open Item 3, 10, 1(3). Fatigus cycling effects on NSSS equipment due to safety relief loads (License Condition 23(a)) discussed. GURTIS, N W. Pennsylvenia Power & Light Co 83/06/09. SCHWENCER, A Licensing Branch 2. 83pp. 18833-182 24X Fiche, 50-387, 83/06/09, 8306140648.

- 8306230430 Forwards listings of Req Guide I 97 Rev 2. instrument status of equipment qualification for post-accident monitoring equipment in response to SER Suppl 5 Gwalification of equipment will be completed by 850331 for Unit 2 CURTIS, N W Pennsylvania Power & Light Co 83/06/20 SCHWENCER, A Licensing Branch 2 17pp 18943 215 24X Fiche 50-387, 83/06/20, 83/0620430
- 8306230466 Responds to SER, Suppl 5, Itum 3 11 i(1)(a) re nonsafety-related electrical equipment Failure of monsafety-related equipment unlikely due to classification under qualification program

 CURTIS.N W Pennsylvania Power & Light Co 83/06/20 SCHHENCER.A

 Licensing Branch 2 lp 18941 159 24X Fiche 50-387,83/06/20,8306230466
- F Security, medical, emergency & fire protection plans
- 8306090018 Releases public version of revised emergency plan implementing procedure & responses to request for addl into FELTON.J M Division of Rules and Records 83/06/06 Document Management Branch ip 18798 178 24% Fichs 50-387.83/06/06. 8306090018
- ~-8306070021 Forwards public version of response to request for addlined re emergency plan & Rev O to Emergency Plan Implementing Procedure EP-IP-101 re inventory, inspicoperational tenting & calibr of emergency equipment & supplies CURTIS, N W Pennsylvania Power & Light Co 83/05/26 SCHMENCER, A Licensing Branch 2 '/pp 18798 179 24X Fiche 50-387,83/06/06,8306090018
- --8306090026 Public version of Rev O to Emergency Plan Implementing Procedure EP-IP-IOI re inventory, insp. operational testing & calibr of emergency equipment & supplies KEISER.H Pennsylvania Power & Light Co 82/07/15 5/pp 18798 188 24X Fiche 50-387.83/06/06.8306090018
- G Inspection reports, IE Bulletins & correspondence
- 8306010121 Forwards IE Insp Repts 50-38/03-11 & 50-388/63-04 on 830406-0503 & notice of violation 8TAROBTECKI.R Division of Project & Resident Programs 83/05/16 KENYON, D D Pennsylvania Power & Light Co 2pp 18674 001 24X Fiche 50-387,83/05/16.8306010121
- --830&010124 Notice of violation from insp on 830404~0503 * Region L. Office of Director 83/05/16 ip 18674 003 24X Fiche 50-387,83/05/16,830&010121
- --8306010134 IE Inap Repts 50-387/83-11 & 50-388/83-04 on 830406-0503
 Noncompliance noted numerous fuses had one terminal
 disconnected on temporary mod control panels 20661 82 & 3,
 opening circuit & no identification tags applied
 RHOADS, G. MCCANN, J. Region 1, Office of Director MCCANE, E C
 Division of Project & Resident Programs 83/05/13 | 15pp
 18674 004 | 24X Fichs 50-387,83/05/16,8306010121
- 830511045B IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in Hell Logging Device" 8vc list encl TAYLOR. J M Division of Safeguards & Inspection Programs (Post 830103) 83/05/24 Consolidated Edison Co of New York. Inc 125pp 18831 043. 24% Fiche 50-000,83/05/26.830511045B
- 8305110460 IE Info Notice 83-34, "Event Notification Info Worksheet " Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Hasponse (fost 630103) 83/05/26 Consolidated Edison Co of New York, Inc 115pp 18732 085 24X Fiche 50-000, 83/05/26, 8305110460
- 8305110461 IE Info Notice 83-35. "Fuel Movement W/Control Rods Withdrawn at BWRs " Svc list encl JORDAN E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/31 Consolidated Edison Co of New York, Inc 1160p 18732 208 24X Fiche 50-000,83/05/31,8305110461
- 8305110464 IE Info Notice 83-36, "Impact of Security Practices on Safe Operations " Syc list encl JORDANIE L Division of Emergency Preparedness & Engineering Response (Fost 830103) 83/06/07 Consolidated Edison Co of New York, Inc 119pp. 18830,280 24X Fiche 50-000,83/06/09.8305110464
- 830.6140482 Responds to IE Bulletin B3-03, "Check Valve Failures in Raw Water Cooling Bys of Dissel Ownerstors "Listed check valves in essential svc water flowpath will be included in Rev 2 to B30.630 pump & valve inservice test program KENYON, B. D. Pennsylvania Power & Light Co. B3/06/09 ALLAN, J M Region 1. Office of Director 3pp 18034 173 24X Fiche, 50-387, 63/06/09, 8306140462.

- 8305110470 IE Info Notice 83-38, "Defective Heat Sink Adhesive & Seismically Induced Chatter in Relays Within Printed Circuit Cards" Svc list end JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co of New York, Inc. 118pp 18920 225 24X Fiche 50-000,83/06/13,8305110470
- 8306090010 IE Info Notice 83-37. "Transformer Feilure Resulting From Degraded Internal Connection Cables" Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co. of New York, Inc. 243pp 18921 001 24X Fiche 50-000.83/06/13.8306090010
- 8305110475 IE Info Notice 83-40, "Need to Environmentally Qualify Epoxy Grouts & Sealers " Svc list encl JORDÁN.E L. Division of Emergency Preparedness & Engineering Response (Post B30103) B3/06/22 Consolidated Edison Co. of New York, Inc. 115pp 19021 179 P4X Fiche D0-000.03/06/22,8305110475
- 8305110477 IE Info Notice 83-41, "Actuation of Fire Suppression Sys Causing Inoperability of Safety-Related Equipment " Svc list enc! JORDAN, E L Division of Emergency Preparadness & Engineering
- JORDAN, E L Division of Emergency Preparadness & Engineering Response (Post 830103) 83/06/22 Consolidated Edison Co. of New York, Inc. 120pp 18997 007 24X Fishe 50-000,83/06/22,8305110477
- 9305;10479 IE Info Notice 83-42, "Reactor Mode Switch Malfunctions "
 Svc list ent.]
 JORDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/06/23 Consolidated Edison Co of New York Inc 116pp 18996 242 24% Fithe 50-000,83/06/23,8305110475
- 8305110483 IE Info Notice 83-43, "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints "Svc list and JORDAN, E.L. Division of Emergency Proparedness & Engineering Response (Post 830103) 83/06/24 Consolidated Edison Co. of New York, Inc. 116pp 19046 297 24X Fiche 50-000,83/06/24,8305110483
- B Reportable occuprences, LERs & related correspondence
- 8306170250 Interim deficiency rept re potential excessive offsite dose concerning feedwater containment penetiations not maintaining water seal for 30 days post-LOCA Also reportable under Part 21 CURTIS.N W Pennsylvania Power & Light Co 83/05/31 ALLAN, J M Region 1. Office of Director App 18078 276 24% Fiche 50-388,83/05/31,8306170250
- 8306210079 Interim deficiency rept re lack of movement in ITT Grinnell snubber brackets Initially reported on D30429, All snubbers will be reinspected & design & installation processes under review Fanal rept due Dct 1983 Also reported per Part 21. CURTIS,N W. Pennsylvania Power & Light Co 83/05/31 ALLAN, J M Region 1. Office of Director 4pp 18911 241 24% Fiche 50-388,89/05/31,8306210079
- 8306280582 PN8-I-83-016 on B30622, bomb threat by unidentified male caller received at plant site & IV station Reactor & turbine bldgs evecuated & search procedures initiated, per emergency & safeguards contingency plans Results negative MADDEN, W. GDDY, A. Region i, Office of Director 83/06/23 2pp 19017 328. 24X Fiche 50-387,83/06/23,8306280582.
- 8306280006 NPDEB noncompliance notification; on 830619, total iron limit in Discharge O41A exceeded level Cause under investigation FIELDS, J. S. Penhsylvania Power & Light Co. 83/06/24 KOVAL, P. Pennsylvania, Commonwealth of, jp. 17001 122 24X Fiche 50-387,83/06/24,8306280006
- V Operator Examinations
- 8306140017 Extends invitation to attend 830627 meeting in King of Prussia-PA to discuss transfer of reactor operator licensing function from Bethesda. MD to Region I of: 6574R0STECKI.R Division of Project & Resident Programs. 83/06/09 KENYON.B. D Pennsylvania Power & Light Co. 2pp. 18808.235. 24X Ficher 50-387.83/06/09.8306140017
- DOCKET 50-369 ST LUCIE PLANT, UNIT 2
- A Application/construction stage documents & correspondence
- B306140366 Confirms IE mgt meeting on B30024 in Region III oft to discuss status of facility completion & readiness for license issuance. Proposed meeting agenda encl.

 O'REILLY, J. P. Region 2, Office of Director. 83/03/22 UHRIG, R. E Florida Power & Light Co 2pp 18832:139 24X

 Fiche 50-389,83/03/22,8306140366

- E NRC Safety Evaluation Report (SER), supple & correspondence
- 8306010057 SAFETY EVALUATION REPORT RELATED TO THE OPERATION OF 8T.
 LVCTE PLANT, UNIT NO 2 Docket No 50-589 (Floridæ Power And
 Light Company, And Orlando Utilities Commission Of The City
 Of Orlando, Florida)
 * Office of Nuclear Reactor Regulation, Director NUREG-0843 802
 82/09/30 99pp Available at NRC \$5 50 18684 321 24X
 Fiche 50-389,82/09/30.8306010057
- 8306240056 SAFETY EVALUATION REPORT RELATED TO THE OPERATION OF ST LUCIE PLANT, UNIT NO 2 Docket No 50-389 (Florida Power And Light Company And Orlando Utilities Commission Of The City Of Orlando, Florida) * Division of Licensing NUREO-0843 804 89/06/30 26pp 18986 245 24X Fiche 50-389,89/06/30,8306240036
- F Security, medical, emergency & fire protection plans
- B306i40272 Confirms B30203 mgt meeting in King of Prussia:PA.per B3020i telcon. Meeting requested to discuss recent insp concerns recivil turnovers; plans for fire protection equipment installation & status of operating procedure preparation LEWIG.R C Division of Project & Resident Programs 83/02/01 UHRIG.R F Florida Power & Light Co 3pp 18832, 222 24X Fiche 50-389, 83/02/01:8306i40272
- 8304140650 Summarizes 830203 mgt meeting at Region II oft re recent insp concerns about civil turnover packages, fire protection plans & operating & emergency procedures Meeting details & attender list encl
 LEWIS.R C Division of Project & Resident Programs 83/02/22,
 UHRIG.R E Florida Power & Light Co 5pp 18843,062, 24X
 Fiche 50-389,83/02/22,8306140650
- 8306140538 Forwards IE Insp Repts 50-335/83-06 % 50-389/83-20 on B30314-18 No noncompliance nated DANCE.H C Division of Project & Resident Programs 83/05/18 UHRIGR E Florida Power & Light Co. 2pp 18834 165 24X Fiche: 50-335, 83/05/18, 8306140538
- --8306140541 IE Insp Repts 50-335/83-06 & 50-389/83-20 on 830314-18 No noncompliance noted Major areas inspected emergency planning, HUFFMAN.G N. Region 2: Office of Director 83/05/17 App. 18834 167 24X Fichs 50-335/83/05/18,8306140538
- 8304140302 Forwards IE Insp Repts 50-335/83-18 & 50-389/83-41 on 830506 No noncompliance noted DANCE.H C Division of Project & Resident Programs 83/05/23 UNRIGR E Florida Power & Light Co 2pp 18832 098 24X Fiche 50-335,83/05/23,8306140302
- --8306140310 IE Insp Repts 50-335/83-18 & 50-389/83-41 on 830506 No noncompliance noted Major areas inspected emergency preparednoss accountability drill HUFFMAN.9 N Region 2, Office of Director 83/05/19 App 18832 100 24X Fichs 50-335.83/05/23,8306140302
- 8304290209 Forwards IE Insp Repts 50-335/83-17 & 50-389/83-39 on 830509-13 No noncompliance noted DANCE H C Division of Project & Resident Programs 83/06/01, UMRIO, R E Florida Power & Light Co 2pp 19056.114 24X Fiche: 50-335, 83/06/01, 8306290009
- --8306290221 IE Insp Repts 50-335/83-17 & 50-389/83-39 on 830509-13. No noncompliance noted Major areas inspected enforcement responses, insp followup items, containment cable tray covers & App R electrical cable rerouting HUNT, M.D. Region 2. Office of Director 83/05/26 App 19054:116 24X Fiche 50-335,83/06/01,8306290209.
- 8306140023 Releases public version of revised offnormal emergency plan implementing procedures FELTON.J M Division of Rules and Records 83/06/06 Document Management Branch, ip 18831.166 24X Fiche.50-335.83/06/06, 8306140
- ~-8306140033 Forwards public version of revised offnormal smergency plan implementing procedures, including Procedures 2-0030131 replant annunciator summary, 2-0030141 re control room inacessibility & 2-0440030 re 80c/LPSI offnormal operation, WETMY, C, M Florida Power & Light Co 83/05/17 Office of Nuclear Reactor Regulation, Director, 1p. 18831-167, 24X Fiche. SO-335,83/06/06,8306140023,
- --8306140038 Public version of revised offnormal emergency plan implementing procedures.including Procedures 2-0030131 replant annunciator summary, 2-0030141 recontrol room inacessibility & 2-0040030 re SBC/LP81 offnormal operation Fibrids Power & Light Co. 83/05/12, 263pp, 18831,168 Ficher 50-335,83/06/06,8306140023

- 8306160660 Releases public version of revised offnormal & emergency operating procedures
 FELTON, J.M. Division of Rules and Records 83/06/06 Document
 Management Branch 1p 19876 340 24X Fiche 50-339,83/06/06,8306160660
- --830&160662 Forwards public version of revised offnormal & emergency operating procedures, including Procedures 2-0120031 reexcessive RCS leakage & 2-0910031 re main transformer offnormal operation.

 METHY. C M Florida Power & Light Co 83/04/21 Director's Office, Office of Inspection and Enforcement ip 18876 341 24 Fiche 50-389,83/06/06.8306160660
- --8306160646 Public version of revised offnorms) & emergency operating procedures, including Procedures 2-0120031 re excessive RC5 leakage, 2-0910031 re main transformer offnormal operation & 2-0950030 re boric acid heat tracing sys HAND Florida Power & Light Co 83/04/20 21pp 18876 342 24x Fiche 50-389, 83/06/06, 8306160660
- 3306210382 Releases public version of revised offnormal & emergency operating procedures
 FELTON.J M Division of Rules and Records 83/06/06 Document
 Management Branch 1p 18936 001 24X Fiche 50-389,83/06/06.
 8306210382
- -830A21038B Forwards public version of revised offnormal & emergency operating procedures, including Procedures 2-0030140 re blackout operation;2-0030141 re control room inacessibility & 2-0910030 re start-up transformer HETHY, C. M. Florida Power & Light Co. 63/05/10, Director's Office, Office of Inspection and Enforcement. ip 18936 002 24X Fiche 50-389,83/06/06,8306210382
- -8308210392 Public version of revised offnormal & emergency operating procedures; including Procedures 2-0030140 rs blackout operation, 2-0030141 re control room inaccesibility & 2-0910030 re start-up transformer HALLEN Florida Power & Light Co 63/05/07 Director's Office, Office of Inspection and Enforcement 200pp 18936 003 24x Fichs, 50-389, 83/05/06, 8306210382
- 306220225 Releases public version of revised offnormal & emergency operating procedures FELTON.J H Division of Rules and Records 83/06/06 Document Management Branch ip 18977-167 24X Fiche 50-335,83/06/06,8306220225
- 8306220230 Forwards public version of revised offnormal & emergency operating procedures.including Procedures 2-0030140 reblactout operation.2-0030143 retotal loss of power & 2-0250030 remergency boration WETHY.C. M Floride Power & Light Co 83/04/27 Director's Office. Office of Inspection and Enforcement ip 18977 168 24X Fiche 50-035.83/06/06.8306220225
- 8306220236 Public version of revised offnormal & emergency operating procedures, including Procedures 2-0030140 re blackout operator, 2-0030143 re total loss of ac power & 2-0250030 re emergency boration * Florida Power & Light Co 83/04/26 Director's Office, Office of Inspection and Enforcement 87pp 16977 169 24X Fiche. 50-335, 83/06/06, 8306220225
- D4130154 Advises that sentence in util B10914 response to Human Engineering Discrepancy A. I 3 rs key storage stating. "Remote Bhutdown Panel SIS block keys will be maintained at 7AB control access point." should be deleted JHR10, R E. Florida Power & Light Co 93/06/08 EISENHUT, D 0 Vivision of Licensing 1p. 18824 244 24X Fiche 50-289,83/06/08. ISO8130156.

Insurance & indemnity information

Operating license stage documents & correspondence

6140784 Notifies of review of Rev I to B30308 process control regram Program contains necessary process parameters & oundary conditions to assure that dewatering of head resin ill be complete wino free liquid Pregram acceptable NIGHTON.0 H Licensing Branch 3 83/05/10 UHRIG.R E Florida ower & Light Co 2pp 18845 331 24X Fiche: 50-335.83/05/10, 306140784

- 830&020&16 Forwards @ McCorkle #30510 memo providing addl'info re results of vital area validation tevice #/o encl
 THOMAS.C O Standardization & Special Projects Branch 63/05/26
 PARR.O D Auxiliary Systems Wiench (LAYJON, B H Procedulet & Systems Review Branch 1p 18/15/044 24X Fiche 50-389,83/05/26,830&020&016
- 830A140111 Forwards list of equipment, justifications for interim operation & response to request for addlinfore IOCFR50 49 equipment qualification program UHRIO, R E Florida Power & Light Co 83/05/26 EISENRUT, D 0 Division of Licensing 8pp 18840 05/ 24% Fiche 50-389,83/05/26,8306140111
- --8306140115 "Florida Power & Light St Lucie, Unit 2, 100FN50 49 Equipment List" * Ebasco Services, Inc. (subs. of Enserch Corp.) 83/05/25 114pp 18840 066 24X Fiche 50-389, 03/05/26, 8306140111
- 8304030074 Fulfilts commitment made in 030331 ltr re investigating feasibility of performing demonstration test for loss of ac power Util dovaloped three addl preoperational tests to demonstrate ability to cross-connect diesol generators UHRIG, R C Florida Power & Light Co 82/05/27 FIGENKUT, D 0 Division of Licensing 3pp 18/03 359 24X Fichs 50-389,83/05/27.
- 8306060082 Forwards justification for interim operation requalification of CUNAX assembly used in inadequate core cooling instrumentation Test expasure to DBE/LOCA conditions successfully completed UHRIG.R F Florida Power & Light Co 83/05/31 EISENHUT, B & Division of Licenting 3pp 18719-33? 24X Fiche 50-389,83/05/31,8306060002
- 8306160630 Forwards draft "Control of Heavy Loads at Nuclear Power Plants, St Lucie Plant. Unit 2 (Phaso I)" & synopsis of NRC interpretation of guidelines of NUREG-0617 for use in resolving open items
 KNIGHTON, 0 W Licensing Branch 3 83/05/31 UHRIG, R E | 10116 Power & Light Co 14pp 18884 283 24X Fichs 50-387,83/05/31,8306140630
- ~~8306160641 Draft "Control of Heavy Loads at Nuclear Power Plants.St Lucis Plant.Unit 2 (Phase 1)," tachnical evaluation rept SKABER.C R EGEG. Inc FIN A-6457 EGG-HS-6263 DRFT B3/04/30 NRC ~ No Detailed Afrilation Given 16pp 18084 297 PAX Fiche 50-389.83/05/31.8306160630
- 8305100140 Application to amend License DPR-67, revising Tech Specs to extend testing cycle of valves utilized as part of turbine overspeed protection sys Change based on vendor recommendation

 URRIG, R E Florida Power & Light Co B3/06/06 EISENRUT, D @

 Division of Licensing 4pp 18801 250 24% Fiche 50-389, 83/06/06, 8306100140
- --8306100144 Proposed Tech Spec 3/4 3 4 re turbine overspeed protection * Florida Power & Light Co 83/06/06 1p 1880! 254 24X Fiche 50-389,83/06/06,8306100140
- 8306130268 Advises that license conditions for 5% power completed Power accension will be commenced upon completion of low power physics testing UHRIG.R E Florida Power & Light Co 83/06/06 EISENHUT, D 0 Division of Licensing Spp 18824 182 24% Fiche 50-389,83/06/06,8306130268
- 8306240466 Clarifies NRC position re ESF actuation sys surveillance testing required by Tech Specs & F9AR commitments Util required to test ESF actuation sys at power including complete operation of actuation devices NHG
- 8306170287 Forwards 2-0030133,Rev 4 to 2-0030140 & Rev 2 to 2-0120037, offnormal & emergency operating procedures
 WETHY, C M Florida Power & Light Co 83/06/08 Director's
 Office, Office of Inspection and Enforcement 1p 18877, 146, 24%
 Fiche. 50-389,83/06/08,8306170287
- --8306170292 Rev 4 to 2-0030140. "Blackout Operation." * Florida Power & Light Co 83/05/31 15pp 18877 147 24X Fiche: 50-389, 83/06/08, 8306170287
- --8306170299 Procedure 2-0030133. "Local Annunciator Summary "
 COUTURE,C Florida Power & Light Co 83/06/01 56pp 188/7 162
 24X Fiche 50-389,83/06/08,830617088/

- --8306170304 Rev 2 to 2-012003/, "Neactur Coolant Gas Vent Sys Off-Normal Operation "
- 8306130291 Application for mod to license Condition 2 C 7 for License NFF-16, changing requirement from "prior to exceeding 50% of rated thormal power" to "prior to completion of startup testing " Mod requested due to testing delays at San Onofre UHRIG.R E Florida Power & Light Cn 83/06/09 EISENHULD Q Division of Licensing 3pp 18824 12", 24% Fiche 50-389,83/06/09,8306130291
- 830&140009 Advises that post-reactor trip procedures will be modified to include add1 criteria for post-reactor trip review Procedures will be available onsite for NRC concurrence within 60 days following approval of full power OL UHAIG.R C. Florida Power & Light Co 63/06/09 EISENHUT.D @ Division of Licenting ip 1883B 240 24% Fiche 50-389,63/06/09,8306140009
- 9305200026 Staff requirements memo re 830610 discussion & passible vote in Mashington, DC on full power OL Commission voted 5 0 to authorize full power operation License amend to be modified re past—trip procedures
 CHILK.S J Office of the Serietary of the Commission 83/06/13
 DIRCKS M J Office of the Excutive Director for Operations ip 18708 355 24X Fiche 50-389,83/06/13.8306200026
- 83042003iO Application to amond License NFF-14.allowing use of alternate means of detecting PDRV position indication UNRIG.R E Florida Power & Fight Co 83/04/15 ETRENHUL, D & Division of Licensing 5pp 18900-150 24X Fiche 50-389, 83/04/15, 8304200310
- 8306200194 Forwards corrected lech Spec (able 3 3-10 re accident monitoring instrumentation submitted in 830615 application to amend license Superscript re min channel operability should have two astericks instead of three UHRIO,R F Florida Power & Light Co 83/06/16 EISENRUT,D 6 Division of Licensing ip 18902 355 24X Fiche 50-369,83/06/16,8306200194
- 8306210160 Application to amend License NPF-16 revising Tech Upec requirement for primary & secondary coolants in stram generator to be greater than 100 f when coolant pressure greater than 200 psig SER enc)

 UHRIGAR F Florida Power & Light Co 83/06/17 EISENHUT, D & Division of Licensing 4pp 18714 226 24X Fiche 50-387, 83/06/17, 873/8210160
- --B304210169 Proposed Tech Boecs revising requirement for primary & secondary coolants in steam generator to be greater than 100 F when coolant pressure greater than 200 psig # Florida Power & Light Co. 83/06/17 7pp 18914 230 24X Fiche 50-389.83/06/17.8306210160
- 6306210261 Forwards add1 info supporting proposed license amond request on PORV indication, per 830615 & 16 ltrs Chronology of PORV syents, current status & add1 info on significant hazards consideration enc!

 UMRIG.R.E Florida Power & Light Co #3706/17 FIBENHUT.D 0

 Division of Licensing Spp 18915 056 24X Fiche 50-389,83706/17, B306210261
- G. Inspection reports, 15 Bulletins & correspondence
- 830.6140272 Confirms 830203 mgt meeting in King of Pressie.PA.per B30201 telcon Meeting requested to discuss recent inspicularins receivil termovers.plans for fire protection equipment installation & status of operating procedure preparation LEMIS.R C Division of Project & Resident Programs B3/02/01 URRIG.R E Florido Power & Light Co 3pp 18832 222 24X Fiche 50-389.83/02/01.83061409/2
- 8304140450 Summarizes 830203 mgt meeting at Region II ofc me mecent insp concerns about civil turnover packages, fire protection plans & operating & emergency procedures Meeting details & attendee list encl,
 LEMISIR C Division of Project & Resident Programs 83/02/22
 UHRIOR E Florida Power & Light Co 5pp 18843 062 24X
 Fichs 50-389,83/02/22,8306140650

- 8306140011 Responds to IE Bulletin 83-04. "Failure of Under Voltage Trip Function of Reactor Trip Breakers " Representatives from util & GE are testing performance of breakers per electrical maint Procedure 0110060 UNRIGRE Florida Power & Light Co 63/03/31 D'REILLY, J P Region 2. Office of Director ip 18838 239 24% Fiche 50-369.63/03/31.6306140011
- 8306140174 Forwards 1E Insp Rept 50-389/83-36 on 830425-28 No noncompliance noted

 DANCE, H C Division of Project & Resident Programs 83/05/16

 URRIG, R E Florida Power & Light Co 2pp 18839 039 24X

 Fiche 50-369, 83/05/16, 8306140174
- --8306140180 IE Insp Rept 50-389/83-36 on 830425-28 No noncompliance noted Major areas inspected licensee action on previous insp findings, licensee identified item & previously identified inspector followup item tem temperator followup item temperator CONLON-T E Division of Engineering & Radiological Safety Programs 89/05/13 5pp 18839 041 24X Fiche 50-289,83/05/16,8306140174
- 8304140184 Forwards IE Insp Rept 50-389/83-34 on 830425-29 No noncompliance noted DANCE, H C Division of Project & Resident Programs 83/05/16 URRIG, R E Florida Power & Light Co 2pp 10837 058 24X Fiche 50-389,83/05/16,8306140186
- --8306140191 IE Insp Rept 50-389/83-34 on 830425-29. No noncompliance noted Major areas inspected preoperational procedure review & preoperational test results review KRUO.H E , TAYLOR,P A Region 2, Office of Director JAPE,F Division of Engineering & Radiological Safety Programs 83/05/12, 5pp 18839 060 24% Fiche 50-389,83/05/16,8306140386
- 8306140338 Forwards IE Insp Repts 50-335/83-06 & 50-389/83-20 on 830314-18 No noncompliance noted DANCE H C Division of Project & Resident Programs 83/05/18 UHRIG,R E Florida Power & Light Co 2pp 18834 165 24% Fiche 50-335,83/05/18,8306140538
- --B306140541 IE Insp Repts 50-335/83-06 & 50-389/83-20 on B30314-1B No noncompliance noted Major areas inspected emergency planning HUFFMAN, O N Region 2. Office of Director JENKING, O R. Division of Emergency Preparedness & Materials Safety. 93/05/17 App 18834 147 24X Fiche 50-335,83/05/18,8304140538
- 8306140302 Forwards IE Insp Repts 50-335/83-18 & 50-389/83-41 on B30506 No noncompliance noted DANCE-H C Division of Project & Resident Programs 83/05/23 UHRTO,R.C Florida Power & Light Co 2pp 18832 098 24X Fiche 50-335,83/05/23.8306140302
- --8305440310 IE Insp Repts 50-335/83-18 t 50-389/83-41 on 830504 No noncompliance noted Major areas inspected emergency preparedness accountability drill HUFFMAN-0 N Region 2. Office of Director JENKINS.0 R Division of Emergency Preparedness & Materials Safety 83/05/19 App. 18832 100 24X Fiche 50-335.83/05/23.8306140302
- 8306140633 Forwards summary of 830513 mgt meeting in Atlanta, 0A re util actions on 830411 confirmation of action ltr on plant operating & emergency procedures
 LEMIS, R.C. Division of Project & Resident Programs 83/05/23
 UHRIG, R.E. Florida Power & Light Co. 4pp. 18843-056-24X
 Fiche: 50-387, 83/05/23, 6306140633
- 830614063B Forwards schedule for completion of responses to IE Bulletin 80-11. "Hasonry Wall Design " Required mods to masonry walls will be completed prior to completion of first refueling outage Item closed UHRIG-R E Florida Power & Light Co 89/05/24 O'REILLY, J P Region 2. Office of Director 3pp 18043 043 24X Fiche 50-389, 83/05/24, 8306140638
- 8306140804 Ack receipt of 830509 ltr informing NRC of steps taken to correct violations noted in IF Imap Rept 50-389/83-16
 DANCE-H C. Division of Project & Resident Programs 83/05/25
 UHRIGA E. Florida Power & Light Co ip 18838 108, 24X
 Fiche 50-389,83/05/25,8306140504
- --8306140510 Responds to NRC 830325 ltm re violations noted in 18 Insp Rept 50-389/83-16 Corrective actions process sheets will include const hold points that will be signed off, providing ongoing status of required/completed insps. UHRIO.R E Florida Power & Light Co 83/05/09. O'REILLY, J. P Region 2, Office of Director. 3pp 1888 109 24X Fishe 50-389,83/05/25,8306140504

- --8306140514 Forwards IE Inso Rept 50-389/83-14 on 830222-25 & notice of 83/03/25
 - violation LEMIS.R C. Division of Project & Resident Programs 83 UMRIG.R E Florida Power & Light Co 2pp 18938 112 Fiche 50-389,83/05/25.8306140504
- --8306140516 Notice of violation from insp on 830222-25 * Division of Project & Resident Programs 83/03/25 ip 18838-114 24% Fiche 50-389,83/05/25,8306140504
- --8306140520 IE Insp Rept 50-389/83-16 on 830222-25 Noncompliance noted failure to execute & maintain status of structural steel insp program LENAHAN. J. J., CONLON, T. E. Region 2. Office of Director 83/03/16 5pp. 18838, 115. 24X Fiche 50-389.83/05/25,8306140504
- 8305110458 IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in Mell Logging Device." Svc list encl.
 TAYLOR, J.M. Division of Refequends & Inspection Programs (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 125pp. 18831 043 24X Fiche. 50-000, 83/05/26, 8305110458
- 8305110460 IE Info Notice 83-34, "Event Notification Info Worksheet." Byo list encl JORDAN,E L Division of Embrgency Preparedness & Engineering Rasponse (Post 830103) 83/05/26 Consolidated Edison Co. of New York, Inc 115pp 18732 085 24% Fiche 50-000,83/05/26,8305110460
- 8304140440 Documents concurrence w/util actions taken in response to B30411 Confirmation of Action Ltrs CAL-335/83-01 & 389/83-01 Insp during wk op 830516 concluded that Unit 2 procedures adequate for startup & operation O'RETELLY. J P Region 2. Office of Director B3/05/27 ADDMAT. E / Fiorida Power & Light Co. 2pp 18841 161 24X Fiche: 50-335, 83/05/27, 8306140640 89/05/27 ADDMAT.E A.
- 8305;10461 IE Info Notice 83-35, "Fuel Movement H/Control Rods Withdrawn at BHRs " Syc list encl JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/05/31 Consolidated Edison Co. of New York. Inc. 116pp. 18732-208 24X Fiche 50-000,83/05/31,8305110461
- 8306140097 Responds to IE Bulletin 79-14, "Seismic Analysis for As-Built Safety-Related Piging Bys " Program verifying piping geometry, including support/restraint/valve locations re piping sys trastraint function, complete URRIO, R E. Florida Power & Light Co 83/06/01 O'REILLY, J P Region 2, Offics of Director. 29p. 19039 109 24X Fiche 50-309, 63/06/01, 8306140097
- 8306140581 Submits final response to JE Bulletin 79-02 re safety-related concrete expansion anchors Stringent design criteria & systematic GA program inplemented to ensure proper installation & testing of anchors UHRIG.R E Florida Power & Light Co. 83/06/01. D'REILLY, J P. Region 2, Office of Director 2pp 18844-151 24X Fiche 50-389,83/06/01.8306140581
- 8304240209 Forwards IE Insp Repts 50-335/63-17 & 50-389/83-39 on 830509-13. No noncompliance noted DANCE H.C. Division of Project & Resident Programs 83/06/01 UHRIG.R.E. Florids Power & Light Co 2pp 19056:114. 24X Fichs: 50-335,83/06/01.8306290209
- --8306290221 IE Insp Repts 50-335/83-17 & 50-389/83-39 on 830509-13 No NOAMONAL IE INSP NEETS DO-335/83-17 & DO-339/83-39 ON 83050* noncompliance noked Major erees inspected enforcement responses, insp followup items, containment cable tray covers & App R electrical cable rerouting. HUNT; M D., CONLON, T.E. Region 2. Office of Director 83/0: App 19084, 114 24X Fiche: 50-335, 83/04/01, 8304290209
- 8306290421 Forwards IE Insp Rept 50-389/83-40 on 830509-12 No noncompliance noted
 DANCE M.C. Division of Project & Resident Programs, 83/06/4
 UHRIO.R E. Florida Power & Light Co 2pp 19053:174, 24X
 Fiche: 50-389,83/06/01.8306290421.
- --8306290424 IE Imap Rept 50-389/83-40 on 830509-12 No noncompliance NORTHER TO BE THE REPT SU-SHYPS-AD ON HIGGS 12 No noncomplinated Nejor areas inspected; seismic analysis for as-built sefety-related piping sys & pipe support beseplate design using concrete expansion anchor bolts (IE Bulletin 79-14) ANG. M.P. Region 2: Office of Director. BLAKE, J. J. Divisio Engineering & Radiological Safety Programs 83/05/27. Spp. 19053-176 24% Fiche 50-369.83/06/01.830629042) Division of
- 8306130268 Advises that license conditions for 5% power completed. SUBJECTION OF Licensing Spp. 18824:182 24X Fiche: 50-389,83/06/06, 8304130248

- 8306290217 Forwards IC Insp Rept 50-389/83-43 on 830516-20 Mp noncompliance noted

 DANCE N C Region 2, Office of Director B3/06/08 UMRIC.R C
 Florida Power & Light Co 2pp 19056 200 24X
 Fiche 50-389,03/06/08.830629021/
- --8306270225 IE Insp Rept 50-309/83-43 on 830514-20 No noncompliance noted Major areas inspected plant operating & surveillance
- B305110464 IE Info Notice 83-36. "Impact of Security Practices on Safe Operations " Svc list entl JORDAN,E L Division of Emergency Proparedness & Engineering Response (Post 830103) 63/06/09 Consolidated Edison Co. of New York, Inc. 119pp 18830 280 24X Fiche 50-000,83/06/09.8305110464
- 8305110470 IE Info Notice 83-38. "Defective Heat Sink Adhesive & Seismically Induced Chatter in Relays Within Printed Circuit Cards " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Cr of New York, Inc. 118pp 18920 225 24X Fishe 50-000,83/06/13,8305110470
- 8304090010 IE Info Notice 83-37. "Transformer Failure Resulting From Degraded Internal Connection Cables" Svc list and JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co. of New York, Inc. 243pp 18921 001 24X Fishe 50-000,83/06/13,8306090010
- 8306290327 Ack receipt of 830420 ltr informing NRC of steps taken to correct violations noted in 16 Insp Rept 50-335/62-36 DANCE,H C Division of Project & Resident Programs 83/06/17 UHRIG,R E Florida Power & Light Cu Ip 19050 194 24X Fiche 50-335,83/06/17,8306290327
- ~-8304290359 Forwards IE insp Repts 50-335/82-36 & 50-389/82-55 on 621011-1110 & notice of viglation DANCE.H C Division of Project & Resident Programs 82/12/07 UVRIO.R E Florida Power & Light Co 2pp 19050 198 24x Fiche 50-335.83/06/17.8306290327
- ~-8306290379 IE Insp Repts 50-335/82-36 & 50-389/82-55 on 821011-11[[Noncompliance noted use of unqualified mat] in emergency dissel generator lube oil sys ELROD, S A, BIBB, H E, Region 2, Office of Director JULIAN, C A Division of Project & Resident Programs 82/12/06 | 11pp 19050 201 | 24X Fichs 50-335,83/06/17,8306290327
- 8305110475 IE Info Notice 83-40, "Need to Environmentally Qualify Epoxy Grouts & Sealers " Byc list encl JOHDAN, EL Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/22 Consolidated Edison Co of New York, Inc. 115pp 19021 179 24X Fiche 50-000,83/06/22,8305110475
- 8308110477 IE Info Notice 63-41, "Actuation of Fire Suppression Sys Causing Inoperability of Safety-Related Equipment " Syc list encl. JORDAN,C L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/22 Consolidated Edison Co of New York, Inc 120pp. 18997 007 24X Fiche 50-000,83/06/22,830516477
- 8305110479 JE Info Notice 83-42, "Reactor Mode Switch Malfunctions "
 Svc list encl
 JORDAN, E. L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/06/23 Consolidated Edison Co. of New
 York, Inc. 116pp. 18996-242, 24X Fiche 50-000,83/06/23,8305110479
- 8305110483 IE Info Notice 83-43, "Impreper Settings of Intermediate Range (IR) High Flux Trip Setpoints " Svc list encl JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Fost 830103) 83/06/24 Consolidated Edison Co of New York, Inc 116pp. 19046-297 24X Fichs 50-000,83/06/24,8305110483
- R Periodic operating reports & related correspondence
- 8306160638 Monthly operating repts for Apr 1983 W/830516 itr PAGE/P L Florida Power & Light Co 83/05/16 Office of Resource Management, Director 17pp 18866 105 24X Fiche 50-000,83/05/16.
- 8 Reportable occurrences, LERs & related correspondence
- 6306300202 Part 2) rept re short-term reliability problem u/position AUSSOCIACY Part 2) rept re short-term reflability problem of indicating mechanism in solenoid valve used to control PORV 3750010 Magnet position indicating mechanism replaced on 830507 Corrective action in progress JOHNSON.V M Garrett Corp 83/05/09 Director's Office of Inspection and Enforcement 3pp 19122-123 24X Fiche, 50-389, 83/05/09, 8306300202 Director's Office, Office

- 8304010114 LER 83-002/OSL-0 on 830421, while in Mode 6, refueling bus tip breaker PA2 & PA3 opened, deenergizing bus 2A3 & causing loss of low pressure safety injection pump A Caused by shorted contact due to personnel error 80s PA3 restored BRANNIN, J P . WILLIAMS, J W Florida Power & Light Co 83/05/23 O'REILLY, J P Region 2, Office of Director 2pp 18473 356 24% Fiche 50-389, 03/05/23, 8306010116
- 8306010252 LER 83-005/017-0 on 830507, while reviewing plant status following mode change to hot shutdown, discovered safety injection tanks had remained isolated Caused by personnel error Operators counseled an procedures W/830523 ltr VALDES, S. A. WILLIAMS, J.W. Florida Power & Light Co. 83/05/23 G'RETLLY, J.P. Region 2, Office of Director 2pp 18672 294 24 Fiche 50-389, 03/05/23, 8306010252
- 830&010007 LER 83-004/03L-0 on 830424, during initial fill & vent, widerange pressure indicator discovered reading fero psig Caused by erroneously isolated pressure transmitter, rendering PORV indepenable Value lineup performed successfully WR30524 ltr VALDES, S.A. WILLIAMS, J.W. Florida Power & Light Co. 83/05/24 D'REILLY, J.P. Region 2. Office of Director 2pp 18674 149 24% Fiche 50-389, 83/05/24, 8306010007
- 9304070181 LER 83-006/01T-0 on 830511, loak of approx I quart per minuter developed in weld on 1-inch drain line for safety injection header 281 Cause unknown Gracked weld & associated piping replaced Weld undergoing exam W1930524 ltr BRANNIN-JP, WILLIAMS.JW Florida Power & Light Co 83/05/24 G'REILLY.JP Region 2. Office of Director 2pp 18736 325 24% Fiche 50-389,83/03/24.8306070181
- 8306070058 LER 83-007/03L-0 on 830428, during cold shutdown, PORV 1474 failed to open at required pressure Cause not determined Bys. pressure reduced & PORV tested satisfartorily W/800831 itr BRANNIN, J P., WILLIAMS, J W Finida Power & Light Co 83/05/31 0'REILLV, J P Region 2, Office of Director 2pp 18740 080 243 Fiche 50-389, 83/05/31, 8306070088
- 9306070191 FND-II-83-043 on B30602, initial criticality achieved w/actual parameters in close agreement w/predicted canditions Low power testing began immediately & scheduled to be completed within 5 days
 JULIAN, C A , DANCE, H C Region 2, Office of Director 83/06/02 ip 18736 298 24X Fiche 50-387,83/06/02,8306070191
- 830.6200146 Bubmits supplemental info to LER 83-06 re safety injection sys vent/drain vibration restraints Field insp program, field vent/drain insp plant change/mod procedure initiated info to be included in revised LER UNRIGER & Florida Power & Light Co 83/06/06 O'REILLY, J P Region 2. Office of Director 3pp 18703 121 24X Fiche. 50-389, 83/06/06, 8306200146
- 830.6200180 LER 83-011/03L-0 on 830b10, during precritical testing, initial performance of Tech Spec surveillance found three valve motor operators missing thermal overload bypass switches Caused by design error Design changed WA306.07 ltr WEST.D., WILLIAMS.J W Florida Power & Light Co 83/06/09 0'REILLY.J P Region 2. Office of Director 2pp 18903 178 24X Fiche 50-389,83/06/09.8306200180
- 9306200074 LER 87-010/03L-0 on 830911, power lost to side B vital & nonvital buses, Caused by opening incorrect breaker at distribution switchyard Personnel instructed on importance of proper switching VALDES, 9 A . WILLIAMS, J W Florida Power & Light Co 83/06/10 0'REILLY, J P. Region 2, Office of Director 2pp 18903 337 24X Floke 50-387,83/06/10,8306200074
- 8306210081 LER 83-008/03L-0 on 830514, while in Mode 3, operator observed all position indication lights on PORV 1475 were out Caused by loss of magnetic property to magnet on valve shaft due to high temps in onvirons Magnet replaced W/830613 ltm BRANNIN.J F. WILLIAMS.J W. Florida Power & Light Co. 83/06/13 O'REILLY, J.P. Region 2. Office of Director 2pp 18711 237 24% fichs 50-389,83/06/13,8306210001
- 8306220014 LER 83-009/03L-0 on 8305t4, while in Mode 3, hot standby, personnel airlock was in use & outer equalizing valve #id not shut Airlock declared inoperable Caused by broken equalizing valve Broken piece repaired W/H30613 lt; PRANNIN, JP, WILLIAMB, JW, Florida Power & Light Co. 83/06/13, 0'REILLY, JP, Region 2, Office of Director, 2pp. 18927-340 24; Fiche 30-389, 83/06/13, 8306220014
- 8306280474 LER 80-013/03L-0 on 830520, while leak testing escape airlock, excessive leak rate detected Caused by linkages for inner & outer door equalizing valves being elightly out of adjustment Linkages readjusted W/830620 ltr.
 PARKB, B., WILLIAMB, J.W. Florida Power & Light Co. 83/06/20.
 O'REILLY, J.P. Region 2, Office of Director 2pp 19018 289 24% Fiche 50-389, 83/06/20, 8306280476

- 8306300153 LER 83-014/03L-0 on 830522.main feed water isolation valve B drifted open twice Caused by thermal relief orifice installed in hydraulic line to top of actuator Thermal relief orifice in hydraulic sys plugged W/B30622 ltr WALLING.O E . WILLIAMS.J W Florida Power & Light Co 83/06/22 0'4ELLLY.J P Region 2. Office of Director Spp 19048 356 24X Fiche 50-389.83/06/22.8306300153
- 8306300025 LER 83-016/03L-0 on 830527, during preoperational testing, two of three charging pumps inoperable for approx 15 h, Caused by sealwater sys gasket leak & charging pump relief valve failure Pumps repaired & retested M/830624 ltr
 HEGT.D. . HILLIAMS.J W Florida Power & Light Co B3/06/24
 O'REILLY.J P Region 2. Office of Director 2pp 19120 356 24X
 Fiche 50-369.83/06/24.8306300025
- T Hearing transcripts on non-antitrust matters
- B306160673 Transcript of Commission B30610 meeting re discussion k possible vote on full-power QL in Washington DC.Pp 1-90 Supporting documentation encl + Commissioners B3706/10 150pp 18884.045 24X Fiche B0-389.83/06/10.8306160673
- V Operator Examinations
- 8306140745 Discusses shift staffing at facilities Util intends to initially operate Unit 2 & continue Unit 1 operations w/five full shifts of licensed operators on each unit.Planned actions for filling vacant positions provided URRIORR E Florida Power & Light Co. 83/06/03, EISENHUT, D & Division of Licensing 3pp 18841 192 24X Fiche: 50-335,83/06/03,8306140745
- 8304140572 Forwards revised shift staffing chart based on 830604 notification that seven licenses candidates received reactor operator licenses.

 UHRID, R E Florida Power & Light Co 83/06/07 E18ENHUT, D & Division of Licensing 2pp 18844 149 24X Fiche: 50-335,83/06/07,8306140572
- DOCKET 50-390 WATTS BAR NUCLEAR PLANT, UNIT 1
- A Application/construction stage documents & correspondence
- 8304080006 Forwards "TVA Watts Bar Nuclear Plant Auxiliary Feedwater Bys Independent Review Rept "Rept initially provided on 830418 MILLS, L.M. Tennessee Valley Authority 83/05/11 ADENBAM, E. Licensing Branch 4. Ip 18754 057 24X Fiche 50-390, 83/05/11, 8304080006
- --B3060B0009 "TVA Watts Bar Nuclear Plant Auxiliary Feedwater Bys Independent Review Rept " # Black & Veetch B3/04/12 A,800pp, 18754 058, 24X Fiche 50-390,83/05/11,83060B0006
- 8306020604 Notification of 830520 meeting w/util in Dethesda.

 MD to discuss measures to prevent liquefaction of soils beneath ERCM pipeline KENYON, T J. Licensing Branch 4 83/05/17. ADENSAM-E @ Licensing Branch 4 3pp 18715 053 24X Fiche 50-390,83/05/17,8306020604
- 830.6020606 Confirms NRC caseload forecast panel Findings resulting from 830302-04 site visit to assess const completion schedules. Issuance of suppl to SER (NUREO-0847) scheduled for Nov
 - 1983 NGVAK,T M. Assistant Director for Licensing. B3/05/24 PARRIS.H Q. Tennessee Valley Authority 3pp 18715.030 24X Fiche.50-390.83/05/24.8306020606
- 8306140287 Forwards request for add1 info re analysis of sheetpile walls & seismic analysis of buried pipes, based on review of util 821300 & 803025 submittals Response requested by 830630 to expedite facility review

 ADENSAME 0 Licensing Branch 4 B3/06/01 PARRIB.H 0 Tennessee
 Valley Authority 3pp 18844 310 24X Fiche, 50-390, 83/06/01, B306140807.
- 8304080071 Forwards responses to NRC concerns re 80RT issues for facility, per 830311 telcon Further audit of safety-related electrical & mechanical equipment not warrented. MILLS, L.M. Tennessee Valley Authority 83/06/03 ADENBAM, E. Licensing Branch 4 22pp 18773, 193 24K Fiche 50-090, 83/06/03.8304080071

- 8306160060 Summary of 830520 meeting w/util, Hoodward-Cycle consultants t NBB in Bethesda, MD re liquefaction of soils beneath ERCH pipeline Issue must be resolved to permit completion of remedial work by fuel load HILLER M A Licensing Branch 4 83/06/06 Licensing Branch 4 26pp 16872 323 24% Fiche 50-390.83/06/06,8306160060
- 8306130362 Forwards revised response to NUREO-0737. Item II F 1, committing to install GA Co Model RD-23 high-range gas monitors by fuel load MILLS,L M Tennessee Valley Authority 83/06/07 ADENSAM,E Licensing Brench 4 4pp 10822 157 24X Fiche 50-390,83/06/07,8306130362
- 8306160533 Forwards Page 11 inadvertently omitted from encl to 830603 responses to questions from SORT MILLS.L M Tennessee Valley Authority 83/06/10 ADENSAM, E Licensing Branch 4 22pp. 18863 117 24X Fichs 50-390, 83/06/10, 8306160593
- 8306160725 Summary of B30324 meeting w/utils & Westinghouse in Bethesda. MD re dosign review panel review of new Westinghouse stress analysis on manifold fasteners for D2/D3 steam generator mod HOPKINS. J. B. Licensing Branch 4 83/06/10 Licensing Branch 4 7pp 18876, 277. 24X Fiche 50-000, 83/06/10, 8306160725
- 8306170335 Forwards Rev A to "Thermal Capability Curves for CONAX Electric Penetration Assemblies & Electric Conductor Seal Assembles." inadvertently omitted Prom 8306697 1tr HILLS.L. M. Tennessee Valley Authority 83/06/10 ADENSAM.E Licensing Branch 4 4pp 18880.084 24X Fiche 50-390.83/06/10,8306170335
- --8306170336 Rev A to "Thermal Capability Curves for CONAX Electric Penetration Assemblies & Electric Conductor Seal Assemblies " FEDERICK, W C , RHODES, C M Conax Corp. IPS-701 81/07/16 70pp 18880 088 24% Fiche 50-390.83/06/10.8306170335
- 8306290573 Summary of Design Review Panel 830321 meeting w/utils & Westinghouse in Bethesda, MD re D2/D3 steam generator mod & Westinghouse stress analysis of manifold fasteners HOPKINBLJ B Licensing Branch 4 83706/10 Licensing Branch 4 7pp 19047 085 24X Fiche 50-000, 83/06/10, 8306290573
- 8306240366 Bummary of 830525 teleon w/util, NBS & Corps of Engineers re liquefaction Util proposal to construct underground barriers feasible Datailed plans requested for NRC review MILLER, M. Licensing Branch 4, 83/06/22 Licensing Branch 4, 5pp 18998 356 24% Fiche SD-390,83/06/22,8306240366
- 8306270163 Forwards evaluation re peak horizontal ground acceleration for use in soil liquefaction analyses Amplification factor of approx 2 appropriate Peak horizontal acceleration of 0 4 g should be used for analyses.

 NOVAK.T M Assistant Director for Licensing 83/06/22 PARRIE.H 0 Tennessee Valley Authority. 7pp 17046 280 24X

 Fiche 50-390.83/06/22.8306270163
- E NRC Safety Evaluation Report (SER), supple & correspondence
- 8306210217 Forwards responses to actions to resolve issues in Chapter B of SER & issues raised at 820701-04 site visit & drawing review KAMMER. D. B Tennessee Valley Authority 83/06/09 ADENSAM, E Licensing Branch 4 18pp 18918-076, 24X Fiche 50-390, 83/06/09, 8306210217
- 8306220011 Forwards updated listing showing status of each SER open & confirmatory item
 MILLS. Tennesses Valley Authority 83/66/16 ADEABAM.S
 Licensing Branch 4 lipp 18927 343 24% Fiche 50-390.83/06/16.
- F Security, medical, emergency & fire protection plans
- 8306210010 Forwards "Program Plan for Control Room Design Reviews for all TVA Nuclear Plants." in response to Generic Ltr 82-33 re upgrade of emergency plans KANMER, B. 8 Tennessee Valley Authority. 83/06/09. ADENSAM. E Licensing Branch 4. 3pp 18713-001 24X Fiche 50-000, 83/06/09, 8306210010
- --8306210016 Procedure B62209, 10, "Program Plan for Control Room Design Reviews for all TVA Nuclear Plants " * Tennesses Valle, Authority 83/06/09 200pp 18913 004 24X Fiche 50-000, 83/06/09, 8306210010.

- 8306200034 Responds to 83010/ & 10 requests for evaluation of three unresolved inspirems Chemical Engineering Branch/Fire Protection Section fire protection issues encl Interior fire hose sys conforms to guidelines EISENHUT. D @ Division of Licensing 83/06/13 OLGHINSKI, J A Division of Emergency Preparedness & Materials Safety App 18919 304 24% Fiche 50-390,83/06/13.8306200034
- 8306230178 Responds to NRC 830325 itr re need for add1 instrumentation in auxiliary control room for plant cooldown Instrumentation meets all App R requirements MILLS.L M Tennessee Valley Authority 83/06/17 ADENSAM, E Licensing Branch 4 3pp 16946 361 24X Fiche 50-390,83/06/17, 8306230178
- @ Inspection reports: IE Bulletins & correspondence
- 8304100239 Supple 821216 response to violations noted in IE Insp Repts 50-390/82-20 & 50-391/82-20 Vendor insp of dampers requested Three addl dampers replaced Corrective actions to be completed by 830331 MILLS.L M Tennessee Volley Authority 83/01/31 D'REILLY, J.P. Region 2. Office of Director ip 19007 052 24% Fiche 50-390,83/01/31.8306100239
- 8306140543 Confirms mgt meeting on 830421 in Chattanoga, TN to review results of first phase of annual appraisal of regulatory performance, per 830328 telcon
 LEWIS.R C Division of Project & Resident Programs 03/04/12
 PARRIS.H G Tonnesser Valley Authority Spp 18834 176 24X
 Fiche 50-000, 83/04/12,8306140543
- --8306140362 IE Insp Rept 50-390/03-13 on 830418-22 No noncompliance noted Major areas inspected prooperational test procedure review test witnessing test results review & followup on previous insp findings
 THOMAS, M. MATHIS, J. L., JAPE, F. Region 2, Office of Director 83/05/12 dep 18832 169 24X Fiche 50-390,83/05/13,8306140%5
- 8306140562 Forwards IE Insp Repts 50-390/83-15 & 50-391/83-11 on 830321-0422 No noncompliance noted VERRELLID M Division of Project & Resident Programs 83/05/20 PARRIS N G Tennessee Valley Authority 2pp 18844 129 24X Fiche 50-390,83/05/20,8306140562
- --8306140580 IE Insp Repts 50-390/83-15 % 50-391/83-11 an 830321 0422 No noncompliance noted Major areas inspected plant tour, operating maint & emergency procedure inspected plant tourcete test procedure review & observation of structural concrete HEATHERLY, T.L., SWAN, W. Region 2, Office of Director QUICK, D.R. Division of Project & Resident Programs 83/05/20 18pp 18044 131 24X Fiche 50-390,83/05/20,8306140562
- 830 9110 458 IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in Well Logging Device" Svc list encl
 TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc
 125pp 18831 043 24% Fire 50-000, 83/05/26, 8305110458.
- 830 5110460 IE Info Notice 83-34. "Event Notification Info Worksheet"

 Svc list encl

 JORDAN E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/05/26. Consolidated Edison Co of New
 York. Inc 115pp 18732 085 24X Fiche 50-000.83/05/26,8305110460
- 8304i404i5 Ack receipt of 8305i3 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-390/83-08 & 50-391/83-07

 LEWIS, R C Division of Project & Resident Programs 83/05/27

 PARTIB, H O Tennessee Valley Authority ip 18838 053 24X

 Fiche 50-390, 83/05/27,8306i40415
- --8306140420 Responds to NRC 830414 ltr re violations noted in IE Insp Repts 50-390/83-08 & 50-391/83-07 Corrective actions losse math removed from Unit i steam generators & Unit 2 generators will be inspected before secondary side closure KAMMER, D & Tonnessee Valley Authority 83/05/13 O'REILLY, J P Regton 2, Office of Director 4pp 18838 054 24X Fiche 50-390, 83/05/27, 8306140415
- --8306140425 Forwards IE Insp Repts 50-390/83-08 & 50-391/83-07 pn 830223-0320 & notice of violation LEMIB.R.C. Division of Project & Resident Programs 83/04/14 PARRIB.H O Tennessee Valley Authority 2pp 18838,058 24X Fiche 50-390,83/05/27,8308140415

- ~-8306140428 Notice of violation from insp on 830223-0320 # Region 2. Office of Director 83/04/14 ip 18038 060 24X Fiche 50-390.83/05/27,8306140415
- --B306440434 IE Insp Repts 50-390/83-08 & 50-391/83-07 on 830223-0320 Noncompliance noted unscheduled insps during B30302-14 identified foreign matl in secondary side of steam generators HEATHERLY, T. L. SMAN, W. Region 2. Office of Director QUICK, D.R. Division of Project & Resident Programs 83/04/13 Spp 18938 061 24X Fiche 50-390,83/05/27,8306440415
- 8305110461 IE Info Notice 83-35, "Fuel Novement W/Control Rods Hithdrawn at BWRs " 8vc list entl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/31 Consolidated Edison Co of New York, Inc 116pp 18732 208 24X Fiche 50-000,83/05/31.8305110461
- 0306290420 Forwards IE Insp Rept 50-390/83-20 on 830516-20 No noncompliance noted VERRELLI,D M Division of Project & Resident Programs 83/06/06 PARRIS,H G Tennessee Valley Authority 2pp 17050 187 24X Fiche 50-390.83/06/06.8306290420
- --B306290511 IE Insp Rept 50-390/83-20 on 830516-20 No nuncompliance noted Major areas inspected containment structural integrity testing containment integrated leakage rate testing & preoperational tast procedure review EROOKS, E. THOMAS, M. MATHIS, J. Region 2. Defice of Director 83/06/02 5pp 19050 189 24% Fiche 50-390,83/06/06.8306290428
- 8305110464 IE Info Notice 83-36, "Impact of Security Practices on Bafe Operations " Syc list encl JORDAN,E L Dyvision of Emergency Preparadness & Engineering Response (Post 830103) 83/06/09 Consolidated Edison Co of New York, Inc 119pp 18830 280 24X Fishe 50-000.83/06/09.8305110464
- 8305110470 IE Info Notice 83-38. "Defective Heat Sink Adhesive & Seismically Induced Chatter in Relays Within Printed Circuit Cards " Svc list encl JORDAN E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 (Onsolidated Edison Co of New York, Inc. 1189p 18920 225 24X Fiche 50-000.83/06/13.8305110470
- 830&090010 IE Info Notice 83-37, "Transformer Failure Resulting From Degraded Internal Connection Cables" Bvc list encl JURDAN, C. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co of New York, Inc. 243pp 18921 001 24X Fiche 50-000,83/06/13,8306090010.
- 8306290308 Ack receipt of 83060P ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-390/83-12 & 50-391/83-09
 VERRELLI,D M. Division of Project & Resident Programs 83/06/15
 PARRIB,H G Tennessee Valley Authority ip 19056 001 24X
 Fiche 50-390,83/06/15,8306290308
- --8306270316 Responds to NRC 830506 ltr re violations noted in IE Insp Repts 50-390/83-12 & 50-391/83-09 Corrective actions Nonconformance Rept 479R initiated on 830420 to document concrete test cylinder 5532 testing below design strength HILLS,L H Tennessee Valley Authority 83/06/02 O'REILLY,J P Region 2, Office of Director 3pp 19056 002 24X Fishe 50-390,83/06/15,8306290308
- --8304290318 Forwards IE Inap Repts 50-390/83-12 & 50-391/83-09 on 830418-20 & notice of violation VERRELLID M Division of Project & Resident Programs B3/05/06 PARRIB, M. @ Tonnessee Valley Authority 2pp 19056 004 24X Fichs 50-390,83/06/15,8306290308
- --8306290324 Notice of violation from insp on 830418-20 * Region 2, Office of Director 83/05/06 1p 19056 006 24X Fiche 50-390.83/06/15,8306290308
- --8308270328 IE Insp Repts 50-370/83-12 & 50-371/83-09 pm 830418-20
 Noncompliance noted nonconformance rept not issued for test
 cylinder 5532 testing below design strength Disputes Item
 I re failure to provide certified mall test rept
 HARRIS, J R . CONLON. T E Region 2. Office of Director 83/05/05
 4pp 19036 007 24X Fiche 30-390.83/06/15.8306290308
- B3062904B3 Approves issuance of SALP Repts 50-259/83 04,50-260/83-04, 50-296/83-04,50-327/83-04,50-328/83-04,50-391/83-04,50-391/83-06,

- --8306270470 Forwards BALP Repts 50-257/83-04, 50-260/83-04, 50-276/83-04, 50-327/83-04, 50-328/83-04, 50-390/83-07, 50-391/83-06, 50-439/83-06 for Jul 1981 Dec 1982
 LENIS, R C Division of Project & Resident Programs B3/04/13 PARRIS, H Q Tennessee Valley Authority 3pp 24% Fiche 50-000,83/04/17,8306270483
- --8306290503 SALP Repts 50-259/83-04,50-260/83-04,50-296/83-04, 50-327/83-04,50-328/83-04,50-390/83-07,50-391/83-06, 50-438/83-06 & 50-439/83-06 for Jul 1981 - Dec 1982 * Region 2, Office of Director 83/04/13 92pp 24X Fiche 50-000,83/06/17,8306290483
- --8306290510 Comments on BALP Repts 50-259/83-04, 50-240/83-04, 50-276/83-04, 50-227/83-04, 50-228/83-04, 50-390/83-07, 50-391/83-06, 50-438/83-06 & 50-439/83-06 for Jul 1781 Dec 1782

 MILLE, L. M. Tennessee Valley Authority 83/05/10 0'REILLY, J. P. Region 2, Office of Director. 2pp 24X Fiche 80-259, 83/06/17, 8306290483
- 8305110475 IE Info Natice 83-40, "Need to Environmentally Qualify
 Epoxy Grouts & Bealers " Svc list and I
 JORDAN,E L. Division of Emergency Proparedness & Engineering
 Response (Poxt B30103) B3/04/22 Consolidated Edison Co. of New
 York, Inc. 115pp 19021 179 24X Fiche 50-000.83/06/22.8305110475
- 8305110477 IE Info Notice 83-41, "Actuation of Fire Suppression Sys-Causing Inoperability of Safety-Related Equipment " Syc list encl JORDAN E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/22 Consolidated Edison Co of New York, Inc. 120pp 18997 007 24X Fiche 50-000.83/06/22,8305110477
- 8305110479 IE Info Notice 83-42, "Reactor Mode Switch Malfunctions," Byc list encl JORDAN,E L Division of Emergency Proparedness & Engineering Response (Post 830103) 83/06/23 Consolidated Edison Co of New York, Inc 116pp 18976 242 24X Fiche 50-000.83/06/23,8305110479.
- 83051104B3 IE Info Notice 83-43. "Improper Bettings of Intermediate Range (IR) High Flux Trip Betpoints " Svc list encl JORDAN.C L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/24 Consolidated Edison Co of New York, Inc 116pp 19046 297 24X Fiche 50-000.83/06/24,8305110483
- R Periodic operating reports & related correspondence
- 8306280612 "Environ Radioactivity Levels.Watts Bar Nuclear Plant," annual rept for 1982 W/830620 ltr MILLS.L M. Tennessee Valley Authority 63/05/31 DENTON.H R Office of Nuclear Reactor Repulation, Director 66pp 19016 023 24X Fiche 50-390,83/05/31.8306280612
- B Reportable occurrences, LERs & related correspondence
- 8304010113 First interim deficiency rept re nonconforming seismic analysis of steam valve rooms Initially reported on 830502 Reanalysis performed to correct all deficiencies in original analysis Next rept by 830923 MILBALM Tennessee Valley Authority 83/05/24 O'REJLLY, J P Region 2. Office of Director 2pp 18673 340 24X Fiche 50-390,83/05/24.8304010113
- B306010136 Fourth interim deficiency rept re failure to evaluate operator actions to realign ERCM Train A Initially reported on B20510 Analysis continuing Next rept will be submitted by B31003 MILLS.L If Tennessee Valley Authority B3/05/24 O'REILLY.J P Region 2. Office of Director ip 19674 041 24X Fiche 50-390.83/05/24.8306010136
- 0306010143 Supplemental info to deficiency rept re failure to inspect stud welds on flush-mounted embedded plates Initially reported on 820812 Completion date of 830513 for corrective actions not met Work will be completed by 830729 MILLS.L M Tennessee Valley Authority 83/05/24 O'REILLY, J P Region 2. Office of Director ip 18674.045 24X Fiche 50-390.83/05/24.8306010143.
- 8306010283 First interim deficiency rept re Hestinghouse pump motors supplied w/o seismic analysis or operability demonstrated Initially reported on 830928 Investigation continuing Next rept will be submitted by 830829 MILLS/L M Tennessee Valley Authority 83/05/24. O'REILLY, J P Region 2. Office of Director. 2pp 18472 340 24X Fiche 50-390,83/05/24.8306010283

- 8306070072 Fifth interim deficiency rept re engineering change notice review & handling Initially reported on 81215 Personnel retrained & corrective actions presented to 0/c of QA for approval Addi info will be submitted by 830722 MILLS.L M Tennessee Valley Authority 83/05/24. O'REILLY, J P Region 2, Office of Director 2pp 18740 095 24% Fichs 50-000,83/05/24.8306070072.
- 8306010274 Third interim deficiency rept re sheared motor pinion keys in Limitorque motor operators Initially reported on 820830 Field change notices issued to replace keys Next rept will be sent by 830722 Also reportable per Part 21 MILLS, L. H. Tennesses Valley Authority 83/05/25 O'REILLY, J. P. Region 2, Office of Director 2pp 18674 322 24X Fiche 50-000,83/05/258306010274
- 8306010431 Second interim deficiency rept re corrosion in high pressure fire protection sys Initially reported on 820903, Sys contains carbon steel piping Corrosion analyses in progress Next rept to be submitted by 821004 MILLS, L. M Tennessee Valley Authority 83/05/25 O'REILLY, J P Region 9, Office of Director 2pp 19674 255 24X Fiche: 50-000, 83/05/25, 8306010431
- 8306070064 Seventh interim deficiency rept re qualification of epoxy grout for safety-related applications Initially reported on Bi0827. Design Critaria BB-i 7.1, "General Anchorage to Concrete," & drawing for support mods being revised MILLS,L M Tennessee Valley Authority, 82/05/26, 0'REJLLY,J P Region 2, Office of Director, ip. 18740:099 24X Fiche 50-390,83/05/26.8306070064
- 8306070074 First interim deficiency rept re incorrect max pipe movements contained in TPIPE program Initially reported on 830804 W/o encl Next rept expected by 830922 MILLS.L M Tennessee Valley Authority 83/05/26 D'REILLY, J P Region 2. Office of Director ip. 18739.319. 24X Ficher 50-000.83/05/26.8306070074.
- 830607004B Final deficiency rept re potentially overstressed embedded plates Initially reported on 820412 Interim spacing requirements implemented to control spacing of Puture attachments to embedded plates
 HILLS: L. H. Tennessee Valley Authority 83/05/27. 0'REILLY, J. P. Region 2. Office of Director 2pp 18739 341 24X
 Fiche. 50-390, 83/05/27, 830607004B
- 830607013B Third interim deficiency rept re voiding of engineering change notices w/o groper review. Initially reported on 820816 Change notices being reviewed & unresolved andety question determination performed Next rept by 830923 MILLB:L M. Tennessee Valley Authority 83/05/31, 0'REILLY, J P Region 2. Office of Director 2pp 18739 264 24X Fiche. 50-000, 83/05/31, 8306070138.
- 8306090322 Final deficiency rept re faulty fillet welds. Initially reported on 800220. Listed ABME Code welds reinspected & marked for tracking. Clarified inspiciteria & acchanical aids (fillet gauges) used in routine visual insp. MILLS, L. H. Tennesse Valley Authority. 83/06/01 O'REILLY, J P Region 2. Office of Director. 4pp 18795 115 24X Fichs: 50-390,83/06/01.8306090322
- 8306090135 Second interim deficiency rept re Henry Pratt butterfly valve. Initially reported on 821109. Valve air-operator yoke mod kits delivered & mod in progress. Operators removed & returned to QH Sattis Co. Also reported per Part 21 MILLS, L. M Tennessee Valley Authority. 83/06/02. O'REILLY, J P. Region 2. Office of Director. Ip. 18795-297 24X Fichs. 50-000.83/06/02.8306090138
- 8306090142 Final deficiency rept re control bldg isolation dampers leaking. Initially reported on 830504. New leakight butterfly valves received & installed. Const drawings revised to indicate new valves
 MILLS.L.M Tennessee Valley Authority. 83/06/02 O'REILLY.J.P. Region 2. Office of Director 2pp 18795, 293 24X
 Ficher 50-370, 83/06/02, 8306090142
- 8306140466 Revised final deficiency rest re auxiliary power sys. Initially reported on 800925, ECN 2786 issued to modify transmission grid-auxiliary power sys interface to ensure adequate offsite power to safety-related buses HILLS.L.M. Tennessee Valley Authority 83/06/03 O'REILLY, J.P. Region P. Office of Director. Spp. 18054:313 24X Fiche. 50-390,83/06/03,8306140466
- 8306140427 Second interim deficiency rept re pipe supports not designed or modified per ECN 2576 Initially reported on 830118 Auxiliary feedwater sys review completed & drawings revised Generic implications reviewed Next rept by 830822 MILLS-L.M. Tennesse Velley Authority 83/06/06 O'REILLY, J.P. Region 2, Office of Director 2pp 18838,047, 24X Fichs: 50-390,83/06/06,8306140427

- 8306140435 First interim deficiency rept to DB-16 reactor trip breaker design error identified by Westinghouse Initially reported on 830505 Undervoltage attachments will be replaced Next rept by 830926 Also reported per Part 2! MILLS.L M Tennesse Valley Authority 83/06/06 O'REILLY, J P Region 2. Office of Director 2pp 18938 035 24X Fiche 50-370,83/06/06,8306140435
- 830&200169 Final deficiency rept re fire dampers improperly installed & damaged Initially reported on 830505 Damage caused by improper handling & installation by const craft due to inadequate GC New dampers purchased MILLS.L M Tennessee Valley Authority 83/06/07 O'REJLLY, J P Region 2. Office of Director 3pp 18702 360 24X Fiche: 50-390,83/06/07.8306200169
- 8306200145 First interim deficiency rept re Meriam Instrument failure to implement GA program Initially reported on 830910 Investigation underway Next rept to be submitted by 830922 MILLS.L.M. Tennessee Valley Authority 83/06/09 D'REILLY, J.P. Region 2. Office of Director. 2pp 10703-124 24X Fiche 50-370,83/06/09.8306200145
- 8306210031 Supplemental interim deficiency rept re potentially overstressed embedded plates Initially reported on 820412 Next submittal scheduled for 840217 instead of 830622 as originally stated MILLS.L M Tennesses Valley Authority 83/06/10 O'REJLLY, J P Region 2. Office of Director ip 18914 009 24X Fiche 50-000,83/06/10,8306210051
- 830.6210088 Final deficiency rept re failure to shut down redundant auxiliary bldg exhaust fans upon secondary containment isolation signal Initially reported on 830505 Engineering Change Notice ECN 3011 issued & logic drawings revised MILLS.1 M Tennessee Valley Authority 83/06/10 O'REILLY, J P Region 2, Office of Director 2pp 16/17 186 24X Fiche 50-290,63/06/10,8306210086
- 8306210150 Final deficiency rept for Unit i & sixth interim deficiency rept for Unit 2 re loading criteria for structural steel & supports Initially reported on Bill!7 Ongoing training programs in engineering procedures will resolve problems HILLS.L M Tennessee Valley Authority 83/06/13 0'REILLY, J P Region 2, Office of Director 3pp 18916 028 24X Fiche 50-390,83/06/13.8306210150
- 8306210039 First interim deficiency rept re lack of isolation capability for post-accident sampling facility air intakes Initially reported on 830517 Safety-grade redundant isolation valves to be installed Next rept by 830822 HILLS-L H Tennessee Valley Authority 83/06/15 0'REILLY, J P. Region 2, Office of Director 2pp 18912 337 24X Fiche: 50-390, 83/06/15, 8306210039
- 830A210087 First interim deficiency rept re containment isolation valves installed in chilled water sys not designed to be leaktight Initially reported on 83051/ Engineering Change Notices 3364 & 3684 initiated Next rept by 830913 MILLS.L M Tannessee Valley Authority, 83/06/15 O'REILLY, J P Region 2. Office of Director 2pp 18914 134 24X Fiche. 50-390,83/06/15,830A210087
- 8306210116 Final deficiency rept re solid state protection sys test procedures Initially reported on 82083! Procedural change initiating use of test probe w/indicator lamp connected to ground implemented Also reportable under Part 21.

 MILLSI.L.M Tennessee Valley Authority 83/06/15 D'REILLY, J P Region 2, Office of Director, 4pp 18714 098 24X

 Fiche 50-290,83/06/15,8306210116
- 8306270354 Fifth interim deficiency rept to frequency criteria for piping supports. Initially reported on 820713 Subsections 9.2.2 & 8 2 3 of WB-DC-40-31 9 revised to provide clarification Next rept by 830921
 MILLS.L. M Tennessee Valley Authority 83/06/16 D'REILLY, J P Region R. Office of Director 2pp 18796 226 24X
 Fiche 50-390,83/06/16.8306270354
- 8306270386 Second interim deficiency rept re flexible hoses not provided in drawings issued under ECN 2104 Engineering procedures checklist revised Next rept expected by 830706 MILLS, L.M. Tennessee Valley Authority 83/06/14 O'REILLY, J.P. Region 2. Diffice of Director 2pp 18793 166 24X Fiche 50-390,83/06/16,8306270386
- 8304280424 Supplemental deficiency rept re post-accident readings from containment sump level transmitters. Initially reported on 820708 Fuel load date rescheduled to Jan 1984 Also reportable per Part 21 MILLS, L.M Tennessee Valley Authority 83/06/17 0'REILLY, J P Region 2, Office of Director ip 19018 250 24% Fiche 50~390,83/06/17,8306280426.

- B30628057B Interim deficiency rept re resolution of listed items due for submittal in late June Corrective actions in progress List identifying each item, schedule for next submittal & level of interim rept encl HILLB, L N Tennessee Valley Authority B3/06/17 D'REILLY, J R Region 2, Office of Director Pyp 17018 193 24X Fiche 50-000,83/06/17,8306280578
- 830&280573 Second interim deficiency rept re Nestinghouse gate valve position indication problems Initially reported on 830203 Field change notices prepared to correct closure indication problems Next rept will be submitted by 830928 MILESL M Tennessee Valley Authority 8370&700 0'REILLY, J P Region 2. Office of Director 2pp 1'017 320 24X Fiche.50-370.8370&720.830&280573
- 830&300013 Supplemental final deficiency rept re containment penetration protection Initially reported on 811207 Deficiency expanded to cover Unit 2 on 020730 Correct completion date for Unit 2 is 840815 HILLS, M Tennessee Valley Authority 83/06/21 O'REILLY, J P Region 2. Office of Director 2pp 17120 354 24X Fichs: 50-390, 83/06/21, 8306300013
- 9306300038 Sixth interim deficiency rept re foam seals in mechanical pipe slerves Initially reported on 811604 Design std providing requirements & procedures to sleeve designers in final review Next rept by 830928 MILLSL M Tennessee Valley Authority 83/06/21 D'REILLY, J P Region 2, Office of Director 1p 1/120 305 24X Fiche. 50-390, 83/06/21, 8306300038
- 830.6300205 Final deficiency rept re rerouting high-pressure fire protection piping w/o proper analyses Initially reported on 830130 Based on head/flow tests on calculated worst case fire. condition determined not reportable per 10CFR50 55(e) MILLSL # Tennessee Valley Authority 83/06/21 O'REILLY, J P Region 2. Office of Director 2pp 17122 121 24% Fiche 50-390.63/06/21,8306300205
- 8306300051 Sixth interim deficiency rept re failure of Limitorque motor operators during valve closure Initially reported on 820126 Heatinghouse & Limitorque determining cause of failures Next rept aspected by 830928 Also reportable per Part 21 HILLS, L M Tennessee Valley Authority 83706/22 O'REILLY, J P Region 2. Office of Director 2pp 19120 193 24X Fiche 50-390,83706/22,6306300051
- 830.6300054 Final deficiency tept to piping sys analysis tracking Entitially reported on 820902 Engineering Procedures 3 03 & 4 25 revised to correct problem of tracking closure of engineering change notices prior to Class I analysis MILLGL M Tennesse Valley Authority, 83/06/22 0'RETILLY, J P Region 2, Office of Director 2pp 17120 290 24X Fiche 50-390.83/06/22,8306300054,
- 83063002i4 Second interim deficiency rept re tubeline matis supplied by Capitol Pipe & Steel not mfg under QA program Initially reported on 830329 Contractor will perform dimensional checks for pipes & fittings Next rept by 830922 HILLSL M Tennessee Valley Authority 83/06/23 O'REILLY, J P Region 2, Office of Director 5pp 19119 391 24X Fiche 50-000,83/06/23.8306300214
- 8306300228 Second interim deficiency rept re postulated accident blowdown of more than one stram generator Initially reported on 821122 Westinghouse analysis indicated no core damage will occur for postulated event Next rept by 830728 MILLS.L M Tennessee Velley Authority 83/06/23 0'REILLY, J P Region 2, Office of Director. 2pp 19119 180 24X Fiche 50-390.83/06/23,8306300228
- 8396300033 Becond interim deficiency rept re spacing & clearance in auxiliary bldg high-pressure fire protection sprinkler systematically reported on 83031 Review of installation configuration incomplete Next rept by 831005
 MILLS.L M Tennessee Valley Authority 83/06/24 0'RCILLY.J P Region R Office of Director 2pp 19120 308 24X
 Fiche 50-390.83/06/24.8306300033
- 8306300082 Fourth interim deficiency mept re concrete anchorage free edge violation initially reported on 820528 Redesign E/or rework will be required on 99 of 477 supports. Next mept by 830919
 HILLB.L M. Tennessee Valley Authority 83/06/24, D'REILLY, J.P. Region 2, Office of Director 3pp 17048 332 24X Fiche 50-390.83/06/24.8306300082

- DOCKET 50-391 WATTS BAR NUCLEAR PLANT, UNIT 2

 A Application/construction stage documents & correspondence
- B306080006 Forwards "TVA Watts Bar Nuclear Plant Auxiliary Feedwater Sys Independent Review Rept " Rept initially provided on 830418 MILLS.L M Tennessee Valley Authority 83/05/11 ADENSAM.E Licensing Branch 4 ip 18754 057 24X Fiche 50-390.83/05/11, 83060800006
- --8304080009 "TVA Watts Bar Nuclear Flant Auxiliary Feedwater Sys Independent Review Rept" * Black Weatch 83/04/12 4,800pp 18754 058 24X Fiche 50-390,83/05/11,8306080004
- 8306020604 Notification of B30520 meeting w/util in Bethesde, MD to discuss measures to prevent liquefection of soils beneath ERCW pipeline KENYON, T J Licensing Branch 4 83/05/17 ADENBAM, E Q Licensing Branch 4 3pp 18715
- 8306020606 Confirms NRC caseload forecast panel findings resulting from 830302-04 site visit to assess const completion schedules Issuance of suppl to SER (NUREO-0847) scheduled for Nov 1983 NOVAK, T.M. Assistant Director for Licensing. 83/05/24. PARRIS, H.O. Tennessee Valley Authority 3pp 19718-050 24X Fiche 50-390,83/05/24-8306020606
- B306140287 Forwards request for addi info re analysis of sheetpile walls & selsmic analysis of buried pipes, based on review of util B21130 & B30825 submittals Response requested by B30830 to expedite facility review ADENSAM.E. Q Licensing Branch 4 B3/06/01 PARRIS.H 0 Tennesse Valley Authority 3pp 18844 310 24% Fiche, 50-390, 83/06/01, B306140287
- 8306080071 Forwards responses to NRC concerns re 80RT issues for facility.per 830311 teleon Further audit of safety-related electrical & mechanical equipment not warranted.
 MILLB.L M Tennessee Valley Authority 83/06/03 ADENSAM.E Licensing Branch 4. 22pp 18773 173 24X Fichs. 30-390, 83/06/03.8306080071.
- 8304160060 Summary of 830520 meeting w/util.Woodward-Cycle consultants k NSB in Bethesda, HD re liquefaction of soils beneath ERCW pipeline Issue must be resolved to permit completion of remedial work by fuel load MILLER, M A. Licensing Branch 4. 83/06/06. Licensing Branch 4. 26pp 18872 323 24% Fiche 50~370.83/06/06.8306160060.
- 8306130362 Forwards revised response to NUREG-0737. Item II.F i, committing to install OA Co Model RD-23 high-range gas monitors by fuel load MILLS,L.M Tennesser Valley Authority 83/06/07. ADENSAM,E Licensing Branch 4 4pp 18822 157 24X Fiche 50-390.83/06/07, 8306130362
- 8306160533 Forwards Page 11 inadvertently omitted from encl to 830603 responses to questions from BGRT HILLS,L M. Tennessee Valley Authority 83/06/10, ADENSAM,E Licensing Branch 4 22pp 18863 117. 24X Fiche; 50-390,83/06/10,8306160833
- 8306160725 Summary of 830324 meeting w/utils & Westinghouse in Bethes6arMD re-design review panel review of new Hestinghouse stress analysis on manifold fasteners for D2/D3 steam generator mod HOPKINS.J B Licensing Branch 4 83/06/10 Licensing Branch 4 7pp. 18876 277 24X Ficher 50-000, 83/06/10, 8306160725
- 8306170335 Forwards Rev A to "Thermal Capability Curves for CDNAX Electric Penetration Assemblies & Electric Conductor Seal Assemblies." inadvertently omitted from 830609 ltr MILLE, L. M. Tennessee Valley Authority 83/06/10 ADENSAM, E. Licensing Spench 4 App. 18880-084 24% Fiche, 50-390, 83/06/10, 8306170335.
- 8304290573 Summary of Design Review Panel 830321 meeting w/utils & Westinghouse in Bethasda, MD re D2/D3 steam generator and & Westinghouse stress analysis of manifold fasteners.

 HOPKINS, J B. Licensing Branch 4 83/06/10 Licensing Branch 4 7pp. 19047:085 24X Fiche 50-000, 83/06/10, 8306290573.
- 8306240366 Summary of 830525 telcon w/util.NBS & Corps of Engineers re liquefaction Util proposal to construct underground barriers feasible Detailed plans requested for NRC review MILLER, M. Licensing Branch 4. 83/06/22 Licensing Branch 4. 5pp 18798 356 24X Fiche. 50-390, 83/06/22, 8306240366

- 8306290163 Forwards evaluation re peak horizontal ground acceleration for use in soil liquefaction analyses Amplification factor of approx 2 appropriate Peak horizontal acceleration of 0 4 g should be used for analyses
 NOVAK.T M Assistant Director for Licensing 83/06/22 PARRIB.H 9
 Tennessee Valley Authority 7pp 17046 280 24X
 Fiche 50-390,83/06/22,8306290163
- E NRC Safety Evaluation Report (SER), suppls & correspondence
- 8306210217 Forwards responses to actions to resolve assues an Chapter 8 of EER & issues raised at 820701-05 site visit & drawing review KAMMER, D 8 Tennessee Valley Authority 83/06/09 ADENSAM, E Licensing Branch 4 18pp 18918 076 24X Fache 50-390,83/06/09,8306210217
- 8306220011 Forwards updated listing showing status of each SER open & confirmatory item
 MILLS. Tennessee Valley Authority B3/04/16 ADENSAN.E
 Licensing Branch 4 lipp 18927 343 24% Fiche 50-390.83/04/16.
- F. Security, medical, emergency & fire protection plans
- 830&210010 Forwards "Program Plan for Control Room Design Reviews for all TVA Nuclear Plants." in response to Generic Ltr 02-33 re upgrade of emergency plans
 KAMMER.D B Tennessee Valley Authority 83/06/09 ADENSAM.E
 Licensing Branch 4 3pp 18913 001 24% Fiche 50-000, 83/06/09, 8306210010.
- --8306210016 Procedure B62207 10. "Program Plan for Control Room Design Reviews for all TVA Nuclear Plants " * Tennessee Valley Authority 83/06/09 200pp 18913 004 24x Fiche 50-000 83/06/09,8306210010
- 8306200034 Responds to 830107 & 10 requests for evaluation of three unresolved insplitems Chemical Engineering Branch/Fire Protection Section fire protection issues encl Interior fire hose systonforms to guidelines ETSENHUT, D © Division of Licensing B3/06/13 OLSHINSKI, J A Division of Emergency Preparedness & Materials Bafety App 18919 304 24X Fiche 50-390,83/06/13,8306200034
- 8306230178 Responds to NRC 830325 ltr re need for add1 instrumentation in auxiliary control room for plant cooldown Instrumentation meets all App R requirements
 HILLS, L. M. Tennessee Valley Authority 80/06/17 ABENBAM, E.
 Licensing Branch 4 3pp 18946 361 24X Fiche 50-390,83/06/17,830620178
- G Inspection reports. IE Bulletins & correspondence
- 8306100239 Buppls 821216 response to violations noted in IE lnsp Repts 50-390/82-20 & 50-391/82-20 Vendor insp of dampers requested Three additional dampers replaced Corrective actions to be completed by 830331 MILLS, L.M. Tannessee Valley Authority 83/01/31 O'REILLY, J.P. Region 2, Office of Director 1p. 18807 052 24X Fiche 50-390,83/01/31,8306100239
- 8306140543 Confirms mgt meeting on 830421 in Chattanoogs, TN to review results of first phase of annual appraisal of regulatory performance, per 830328 telcon LEMIS: R C Division of Project & Resident Programs 83/04/12 PARRIS: H Q Tennessee Valley Authority 3pp 18634 176 24X Fiche, 50-000, 83/04/12, 8306140543
- 8304140562 Forwards IE Insp Repts 50-370/83-15 & 50-371/83-11 on 830921-0422 No noncompliance noted. VERRELLI,D M Division of Project & Resident Programs 83/05/20 PARRIS.H Q Tennesse Valley Authority 2pp 18844 129 24X Fichs.50-370,83/05/20,8306140562
- --8306440580 IE Insp Repts 50-390/83-15 & 80-391/83-11 on 830321-0422
 No noncompliance noted Major areas inspected plant tour,
 operating maint & seergency procedure insps; preoperational
 test procedure review & observation of structural concrete
 HEATHERLY.T.L., SWAN.W. Region 2, Defice of Director GUICK, D.R.
 Division of Project & Resident Programs 63/05/20 18pp.
 18944 131. 24X Fiche-50-390,83/03/20,8306140562
- 8303110458 IE Info Notice 83-32, "Ruptured Am-241 Bources Contained in Well Logging Device" Svc list encl. TAYLON J.M. Division of Safeguards & Inspection Programs (Post 830103) B3/05/26. Consolidated Edison Co of New York, Inc. 125pp. 19831-043, 24X Fithe: 50-000,83/05/26,8305110458

- 8305110460 IE Info Notice 83-34, "Event Notification Info Worksheet" Svc list encl Jundah. E. Division of Emergency Proparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 115pp 18732 085 24% Fiche 50-000.83/05/26.8303110460
- 8306140415 Ack receipt of 830513 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-390/63-08 & 50-391/83-07
 LEWIS.R C Division of Project & Resident Programs 83/05/27
 PARRIB.H O Tennessee Valley Authority 1p 18030 053 24X
 Fiche 50-390,83/05/27,8306140415
- ~-8306140420 Responds to NRC 830414 ltr re violations noted in IE lnsp Repts 50-390/83-08 & 50-391/83-07 Corrective actions loose math removed from Unit 1 steam generators & Unit 2 generators will be inspected before secondary side closure KAMMER: D S Tennessee Valley Authority 83/05/13 D'REILLY, J.P. Region 2, Office of Director 4pp 18838 054 24X Fiche 50-390,83/05/27,8306140415
- --8306440425 Forwards IE Insp Repts 50-390/83-08 & 50-391/83-07 on 830223-0320 & notice of violation LEMIS.R C Division of Project & Resident Programs 83/04/14 PARRIS.H 9 Tennessee Valley Authority 2pp 18838 058 24X Fiche 50-390,83/05/27.8306140415
- --8306140428 Notice of violation from insp on 830223-0320 * Region 2, Office of Director 83/04/14 lp 18838 060 24x Fiche 50-390,83/05/27,8306140415
- ---B306140434 IE Insp Repts 50-390/83-08 & 50-391/83-07 on B30223-0320 Noncompliance noted unscheduled insps during 830302-14 identified foreign math in secondary side of steam generators HEATHERLY, T.L. SWAN, W. Region 2, Office of Director QUICK, D.R. Division of Project & Resident Programs 83/04/13 Bpp 18838 041 24X Fiche 50-390,83/05/27,8306140415
- 8305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods Withdrawn at BWRs " Svc list enc) JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/31 Consolidated Edison Co of New York, Inc 114pp 18732 208 24% Fishe 50-000,83/05/31.8305119461
- 8305;10464 IE Info Notice 83-36, "Impact of Security Practices on Safe Operations " Svc list encl JORDAN,E L. Division of Emergency Proparedness & Engineering Response (Post 830103) 83/06/09 Consolidated Edison Co. of New York, Inc. 117pp 18830 280 24% Fiche 50-000,83/06/09.8305110464
- 8305110470 IE Info Notico 83-98, "Defective Heat Bink Adhesive & Beismically Induced Chatter in Relays Within Printed Circuit Cards " Svc list enc!
 JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/12 Consolidated Edison Co of New York, Inc. 118pp 18920 225 24X Fiche 50-000,83/06/13,8305110470
- 830.6070010 IE Info Notice 63-37. "Transformer Failure Resulting From Degraded Internal Connection Cobles" Svr list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidate Edison Co. of New York, Inc. 243pp 18921 001 24X Fiche 50-000.83/06/13.8308090010
- 8306290308 Ack receipt of 830602 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-390/83-12 & 50-391/83-09
 VERRELLI.D M Division of Project & Resident Programs 63/06/15
 PARRIS.H G Tennesses Valley Authority 1p 19056 001 24X
 Fiche 50-390.63/06/15.8306290308
- --8306270316 Responds to NRC B30506 Itr re violations noted in IE Insp. Repts 50-390/83-12 & 50-391/83-07 Corrective actions Nonconformance Rept 4798R initiated on B30420 to document concrete test culinder 3532 testing below design strength MILLS, L M Tennessee Valley Authority 83/06/02 0'RETULY, J P Region 2. Office of Director 3pp 19056 002 24X Fiche: 50-390, 83/06/15, 8306290008
- --8306270318 Forwards IE Insp Repts 50-390/83-12 & 50-391/83-09 on B30418-20 & notice of violation VERRELLI,D M Division of Project & Resident Programs 83/05/06 PARTS,H G Tennessee Valley Authority, 2pp 19056-004 24X Fiche, 50-390, 83/06/15, 8306290308
- --8306270324 Notice of Violation from insp on 830418-20 * Region 2, Office of Director, 83/05/06 ip 19056 006 24% Fiche, 50-390-83/06/15,8306290308

- --8306290728 IE Insp Repts 50-390/83-12 & 50-391/83-09 on 830418-20 Noncompliance noted nonconformance rept not issued for test cylinder 5532 testing below design strength Disputes Item i re failure to provide certified mill test rept HARRIS, J R. CONLON, T E. Region 2. Office of Director 83/05/05 4pp 19056 007 24X Fiche 50-390,83/06/15,8306290308
- 8304270483 Approves issuance of SALP Repts 50-259/83-04.50-260/83-04. 50-276/83-04.50-328/83-04.50-328/83-04.50-328/83-04.50-328/83-04.50-328/83-04.50-328/83-06. 50-439/83-06. \$0-439/8
- --9306290490 Forwards SALP Repts 50-259/83-04, 50-260/83-04, 50-396/83-04, 50-396/83-04, 50-327/83-04, 50-328/83-04, 50-390/83-06, 50-391/83-06, 50-439/83-06 for Jul 1781 Dec 1982

 LEMIS.R C Division of Project & Resident Programs 83/04/13 PARRIS.H G Tennessee Valley Authority 3pp 24X Fichs 50-000, 83/06/17, 8306290483
- --8306290503 SALP Repts 50-259/83-04,50-260/83-04,50-296/83-04, 50-327/83-04,50-328/83-04,50-390/83-07,50-391/83-06, 50-438/83-06 & 50-439/83-06 for Jul 1981 - Dec 1982 8 Region 2, Office of Director 83/04/13 92pp 24X Fiche 50-000,83/06/17,8306290483
- ---8306270510 Comments on SALP Repts 50-257/83-04.50-260/83-04, 50-276/83-04.50-327/83-04.50-327/83-04.50-327/83-04.50-391/83-06.50-438/63-06.50-439/83-06 for Jul 1781 Dec 1782 HILLS, L M Tennessee Valley Authority 83/05/10 D'REILLY, J P Region 2, Office of Director 2pp 24X Fiche: 50-259.83/06/17.8306270483
- 8305110475 IE Info Notice 83-40, "Need to Environmentally Qualify
 Epoxy Grouts & Sealers " Svc list encl
 JORDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/06/22 Consolidated Edison Co of New
 York, Inc 115pp 19021 179 24X Fiche 50-000,83/06/22,8305110475
- 8305110477 IE Info Notice 83-41, "Actuation of Fire Suppression Sys Causing Inoperability of Safety-Related Equipment " Syc list encl JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/22 Consolidated Edison Co. of New York, Inc. 120pp 18997 007 24X Ficha 50-000,83/06/22,8305110477
- 8305110479 IE Info Notice 83-42, "Reactor Mode Switch Melfunctions."

 Evc list encl
 JORDAN,E L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/06/23 Consolidated Edison Co. of New
 York, Inc. 116pp 18976 242 24X Fiche 50-000.83/06/23.8305110479
- 8305(10483 IE Info Notice 83-43, "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints "Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/24 Consolidated Edison Co. of New York, Inc. 116pp 19046 297 24X Fiche 50-000,83/06/24,8305110483
- A Periodic operating reports & related correspondence
- 8306280612 "Environ Radioactivity Levels, Watts Bar Nuclear Plant," annual rept for 1982 W/830620 ltr MILLR.L M Tennessee Valley Authority 83/05/31 DENTON, H R Office of Nuclear Reactor Regulation, Director 66pp 19016:023 24X Fiche 50-390,83/05/31,8306280612
- 8 Reportable occurrences, LERs & related correspondence
- 8306010113 First interim deficiency rept re nonconforming seismic analysis of steam valve rooms initially reported on 830502 Reanalysis performed to correct all deficiencies in original analysis Next rept by 830923 MILLS.L M Tennessee Valley Authority 83/05/24 O'REILLY, J P Region 2, Office of Director 2pp 18673 340 24X Fiche 50-390,83/05/24.8306010113
- 8304010136 Fourth interim deficiency rept re failure to evaluate operator actions to realign ERCW Train A Initially reported on 820510 Analysis continuing Next rept will be submitted by B31003 MILLS.L. M Tennessee Valley Authority B3/05/24 O'REILLY. J P. Region 2, Office of Director ip 18674-041 24X Fiche 50-390,83/05/24,8304010134

- 830-6010143 Supplemental info to deficiency rept re failure to inspect stud welds on flush-mounted embedded plates Initially reported on 820812 Completion date of 830513 for corrective actions not met Work will be completed by 830729 MILLS.L M Tennessee Valley Authority 83/05/24 O'REILLY, J P Region 2. Office of Director ip 18674 045 24X Fiche 50-390,83/05/24,8306010143
- 830&010283 First interim deficiency rept re Wastinghouse pump motors supplied w/o seismic analysis or operability demonstrated initially reported on 830A28 Investigation continuing Next rept will be submitted by 830B29 MILLS.L.M. Tennessee Valley Authority 83/05/24 0'REILLY.J.P. Region 2. DEFice of Director 2pp 18672 340 24% Fiche 50-390.83/05/24.830&010P83
- 8306070072 Fifth interim deficiency rept re engineering change notice review & handling Initially reported on 811815 Personnel retrained & corrective actions presented to Dfc of GA for approval Addi info will be submitted by 830722 MILG.L M Tennessee Valley Authority 83/08/24 O'REILLY, J. P Region 2. Office of Director 2pp 18740 085 24% Fiche 50-000.83/05/24.8306070072
- 8306010274 Third interim Seficiency rept re sheared motor pinion keys in Limitorque motor operators Initially reported on 820830 Field change notices issued to replace keys Next rept will be sent by 830922 Also reportable per Part 21 MILLS, L N Tennessee Valley Authority. 83/05/25 O'REILLY, J P Region 2. Office of Director 2pp 18674 322 24X Fiche 50-000, 83/05/25, 8306010274
- 8306010431 Second interim deficiency rept re corrosion in high pressure fire protection sys Initially reported on 820903 Sys contains carbon steel piping Corrosion analyses in progress Next rept to be submitted by 821004. MILLS,L M Tennessee Valley Authority 83/05/25 O'REILLY, J P Region 2: Office of Director 2pp 18674 295 24X Fiche 50-000,83/05/25.8306010431
- 8306070064 Seventh interim deficiency rept re qualification of epoxy grout for safety-related applications Initially reported on 810627 Design Criteria DS-1 7 i. "General Anchorage to Concrete." & drawing for support mode being revised MILLS.L M Tennesse Valley Authority B3/05/26 0'REILLY, J P Region 2. Office of Director ip 18740 099 24X Fiche 50-390,03/05/26.8306070064
- 8306070074 First interim deficiency rept to incorrect max pipe movements contained in TPIPE program Initially reported on 830504 M/o encl Next rept expected by 830972 MILLS.L M Tennessee Valley Authority 83705/26 0'REILLY, J P Region 2, Office of Director Ip 18737 319 24X Fiche 50-000, 83705/26, 8306070074
- 830607004B Final deficiency rept re potentially overstressed embedded plates Initially reported on 820412 Interim spacing requirements implemented to control spacing of future attachments to embedded plates MILLS.L M Tennesses Valley Authority 83/05/27 O'REILLY, J. P. Region 2. Office of Director 2pp 18739 341 24X Fichs 50-370, 83/05/27, 0306070048
- 830&070138 Third interim deficiency rept re voiding of engineering change notices w/o proper review Initially reported on 82081& Change notices being reviewed & unresolved safety question determination performed Next rept by 830723 MILLS.L M Tennesse Valley Authority 83/05/31 D'REILLY, J P Region 2. Office of Director 2pp 18737 264 24X Fiche 50-000,63/03/31,830&070138
- 8306070322 Final deficiency rept re faulty fillet welds Initially reported on 800220 Listed ASME Code welds reinspected & marked for tracking Clarified insp criteria & mechanical aids (fillet gauges) used in routine visual insp MILLS, L M Tennesses Vallay Authority 83/06/01 O'REILLY, J P Rejion 2, Office of Director App 18795 115 24X Fiche 50-390, 83/06/01.8306090322
- 830A090135 Second interim deficiency rept re Henry Pratt butterfly valve Initially reported on 831109, Valve air-operator yoke mod kits delivered & mod in progress Operators removed & returned to GH Bettis Co Also reported per Part 21 HILLS, L. M. Tennesses Valley Authority 83/06/02 0'REILLY, J. P. Region 2. Defice of Director 1p 18795 297 24x Fiche 50-000, 83/06/02, 8304090135
- B30&070142 Final deficiency rept re control bidg isolation dampers leaking Initially reported on B30504 New leakingth butterfly valves received & installed Const drawings revised to indicate new valves.

 MILLB.L M Tennessee Valley Authority 83/06/02 O'REILLY, J P Region 2, Office of Director 2pp 18775 293 24X Fiche 50-370, B3706/02, B304090142

DOCKETED ITEMS

- 8386140466 Revised final deficiency rept re auxiliary power sys Initially reported on 800935 ECN 2786 issued to modify transmission grid-auxiliary power sys interface to ensure adequate offsite power to safety-related auses MILLS, L. H. Termessee Valley Authority 83/04/03 D'REILLY, J. Region 2, Office of Director Spp 18834 313 24% Fiche 50-390, 83/04/03, 8306140466
- 8306140435 First intorum deficiency rept re DB-14 reactor trip breaker design error identified by Westinghouse Initially reported on 830505 Undervoltage attachments will be replaced Next rept by 830926 Also reported per Part 31 Hills, L. H. Tennessee Valley Authority, 83/06/06 G'REILLY, J.P. Region 2, Office of Director, 2pp 18038-035 24X Fiche 90-390,03/06/06,8306140435
- 0306200169 Final deficiency rept re fire dampers improperly installed & damaged. Initially reported on 030505 Damage caused by improper handling & installation by const craft due to inadequate OC. New dampers purchased MILLB.L H Tennessee Valley Authority 03/06/07 0'REILLY, J P Region 2, 0ffice of Director. 3pp. 18702 360 24X fiche, 30-370, 83/06/07, 8306200169
- 8306200145 First interim deficiency ropt re Meriam Instrument failure to implement OA program Initially reported on 830510
 Investigation underway Next rept to be submitted by 830922
 MILLS.L.M. Tennessee Valley Authority 83/06/09 O'REILLY, J.P.
 Region R. Office of Director 2pp 18903-124 24X
 Fichs #0-390,83/06/09,8306200145
- 8304210051 Supplemental interim deficiency rept re potentially overstressed embedded plates initially reported on 820412 Next submittal scheduled for 840217 instead of 830622 as originally stated HILLS, L.H. Tennesses Valley Authority 83/06/10 G'REILLY, J.P. Region 2. Office of Director 1p. 18914 007. 24x Fiche: 50-000, 83/06/10, 8306210051
- 830 621008B Finel deficiency rept re failurs to shut down redundant auxiliary bldg exhaust fans upon secondary containment isotation signal Initially reported on 030505. Engineering Change Notice ECN 3011 issued & logic drawings revised MILLEL. H. Tennessee Valley Authority B3/06/10 0/REILLY. J P Region 2. Office of Director 2pp 18719/188 24x Fiche 50-390,83/06/10.830621008B
- 0306210150 Finel deficiency rept for Unit 1 % sixth interim deficiency rept for Unit 2 re loading criteria for structural steel & supports. Initially reported on Billi7 Ongoing training groognams in anginkering procedures will resolve problems HILLS.L.M. Tennessee Valley Authority 83/06/13 0'REILLY.J P Region 2. Office of Director Spp. 18916 028 24X Fiche: 80-370, 83/06/13, 83/06/10150.
- 0306210037 First interim deficiency rept re lack of isolation capability for post-accident sampling facility air intakes initially reported on 830317, Barbty-grade redundant itolation valves to be installed. Next rept by 830022. MILLGL H. Tennessee Valley Authority 83706/15 0'RCILLY. J.P. Region R. Office of Director 2pp 10712, 337 24X Fiche 50-370, 03/06/15, 8306210037
- R306210087 First Interim deficiency rept re containment isolation valves installed in chilled water sys not designed to be leaktight. Initially reported on 830517 Engineering Change Notices 3861 & 3866 initiated, Next rept by 830713 MILLS.L.M. Tennesses Valley Authority 83/06/15. 0'REILLY, J P Region 2, Uffices of Director 2pp 18914 (34, 24X Fiche: 50-390.83/06/15.8306210887
- 306210116 Final deficiency rept re solid state protection sys test procedures. Initially reported on H2083! Procedural change initiating was of test probe w/indicator lamp connected to ground implemented Also reportable under Part 2! MILLS.L. M Tennasce Velley Authority 83/06/15 O'REILLY, J P Region 2. Office of Director. App 10714 098 24X Fichs. 50-390.83/06/13.8306210116
- HOSE 70354 Fifth interim deficiency rept re frequency criteria for Riping supports initially reparted on 820713. Subsections B 2 2 & 8 2 3 of HS-DC-40-31. 9 revised to provide clarification. Next rept by 830321 HILLS.L.M. Tennessee Valley Authority. 83/06/16 D'REILLY. J P Region 2, Office of Director. 2pp. 18796. 226 24X Fiche: 80-390, 83/06/16, 8306870354.
- OARROARA Supplemental deficiency rapt repost-accident readings from containment sump level transmitters. Initially reported on 820708, Fuel load date rescheduled to Jan 1984 Also : reportable par Part RI.
 MILLS, L.M. Tennessee Valley Authority 83/05/17 O'REILLY, J.P. Region 2. Office of Director. 1p. 19018:350 24X
 Fiche: 80-390,83/06/17,8306280426

- 8306280578 Interim deficiency ript re recolution of listed stems due for submittal in late June Corrective actions in progress List identifying each item, schedule for next submittal & level of interim rept enc!
 MILLS, L. M. Tennessee Valley Authority 83/06/17 O'REILLY, J.R. Region 2, Office of Director 2pp 17018 193 24X
 Fiche 50-000.83/06/17.83062805/8
- 8306280573 Second interim deficiency rept re Westinghouse gate valve position indication problems initially reported on 830203 Field change notices prepared to correct closure indication problems Next rept will be submitted by 830928 MILLS, L M Temmeasee Valley Authority 83/06/20 O'REILLY, J P Region 2, Office of Director 2pp 19017 320 24% Fiche 50-390,83706/20,83062805/3
- 830 6300013 Supplemental final deficiency rept re containment penetration protection Initially reported on 81/207 Deficiency expanded to cover Unit 2 on 820/30 Correct completion date for Unit 2 is 840815 MILLR, L.M. Tennessee Valley Authority 83/06/21 O'REILLY, J.P. Region 2. Office of Director 2pp 17/20 354 24X Fiche 50-370,83/06/21,8306300013
- 8306300038 Sixth interim deficiency rept re foam seals in mechanical pipe sleeves Initially reported on BillOA Design std providing requirements & procedures to sleeve designers in final review Next rept by 830928 MILLS.L M Tennesse Valley Authority 83/06/21 O'REILLY, J P Regian 2. Office of Director in 19170 305 24% Fiche 50-370,83/06/21,8306300038
- 8306300205 Final deficiency rept re rerouting high-pressure fire protection piping w/o proper analyses Initially reported on 830130 Based on head/flow tests on calculated worst case fire, condition determined not reportable per 10CFR50 55(e) MILLS, L M Tennessee Valley Authority 83/06/21 O'REILLY, J P Region 2, Office of Director 2pp 19122 121 24% Fiche 50-370,83/06/21,8306300205
- 8306300051 Sixth interim deficiency rept re failure of Limitorque aptor operators during valve closure initially reported on 820126. Hestinghouse & Limitorque determining cause of failures Next rept expected by 830728 Also reportable per Part P1 MILLS, L M Tennessee Valley Authority 83/06/22 D'REILLY, J P Region 2. Office of Director 2. pp 19120 193 24% Fiche 50-370,83/06/22,8306300051
- 8306300054 Final deficiency rept re piping sys analysis tracking Initially reported on 820902 Engineering Procedures 3 03 % 4 25 revised to correct problem of tracking closure of engineering change notices prior to Class I analysis MILLS, L M Tennessee Valley Authority 83/06/22 O'REILLY, J P Region 2, Office of Director 2pp 19120 290 24x Fiche 50-390,03/06/22,6306300054
- 8306300214 Second interim deficiency rept re tubeline matls supplied by Capitol Pipe & Steel not mfg under GA program Initially reported on 830329 Contractor will perform dimensional checks for pipes & fittings Next rept by 830922 MILLS.L M Twomesses Valley Authority 83/06/23 O'REILLY.J P Region 2. Office of Director Spp 1919 351 24X Fiche 50-000.83/06/23.8306300214
- 8306300228 Second interim deficiency rept re postulated accident blowdown of more than one steam generator initially reported on 821122 Westinghouse analysis indicated no core damage will occur for postulated event Next rept by 830728 MILLS.L H lennessee Valley Authority 83/06/23 O'REILLY.J P Region 2. Office of Director 2pp 19119 180 24x Fiche 50-390.83/06/23.8306300228
- 8306300033 Second interim deficiency rept re spacing & clearance in auxiliary bldg high-pressure fire protection sprinkler sys Initially reported on 830331 Review of installation configuration incomplete Next rept by 831005 MILLELL M Tannessee Valley Authority 83/06/24 D'REJLLY, J P Region 2, Office of Director 2pp 19120 308 24X Fiche 50-390.83/06/24,8306300033
- 9306300082 Fourth interim deficiency rept re concrete anchorage free edge violation Initially reported on 820528 Redesign W/or rework will be required on 99 of 47/ supports Next rapt by 830919
 MILLS, L. M. Tennessee Valley Authority 83/06/24 0'REILLY, J. P. Region 2, Office of Director 3pp 19048 332, 24x
 Fiche 50-390,83706/24.8306300088

- DOCKET 50-394 CALIFORNIA STATE POLYTECH COLLEGE RES REACTOR a Enspection reports, IE Bulletins & correspondence
- 8305)10460 IE Info Notice 83-34, "Event Notification Info Worksheet" Syc list encl JORDAN,E L JORDAN,E L Division of Emergency Preparedness & Engineering Response (Past 830103) 83/05/26 Consolidated Edison Co of New York Inc 115pp 18732 085 24X Fichs 50-000.83/05/26.8305110460
- DOCKET 50-395 VIRGIL C SUMMER NUCLEAR STATION, UNIT 1 P Operating license stage documents & correspondence
- 8306010325 Forwards Rev 2 to "Inservice Insp Program.First Interval."
 Rev 3 to "General Test Procedure for Inservice Testing of Pumps" & Rev 5 to "General Test Procedure for Inservice Testing of Valve."
 DIXON.O W South Carolina Electric & Gus Co 83/05/23 DENTON.H |
 Diffice of Nuclear Reactor Regulation, Director 3pp 18681 053
 24x Fiche 50-395.83/05/23.8306010325
- --8306010366 Rev 5 to GTP-001, "General Test Procedure for Inservice Testing of Pumps " * South Carolina Electric & Gas Co 83/04/14 34pp. 18681 065 24% Fiche 50-375,83/05/23,8306010325
- --8306010374 Rev 5 to OTP-007, "General Test Procedure for Inservice Testing of Valves" TURKETT, J. South Carolina Electric & Qas Co. 83/04/28 177pp 18881 097 24X Fiche 50-37%, 83/05/23, 8306010325
- 830602066! Notification of 830526 meeting w/util in Betheada, MD to discuss reactor trip breakers HOPKINS.J D Licensing Branch 4 83/05/25 ADENSAM.E G Licen Branch 4 2pp 18716 256 24X Fiche 50-395,83/05/25,8306020661
- 8305020385 Forwards addl fee for 830413 Class III amend, in response to 1060203B5 ranwards add ree for 050-10 0105.

 MRC 830524 raquest

 DIXON 0 W Bouth Carolina Electric & Cas Co 83/05/31 DI869.R M

 License Fee Management Branch 1p 18694 360 24X

 Fiche 50-395.83/05/31.8306020385
- 8306070402 Withdraws requests for changes to Tech Spec Sections 3 4 9 3 3 2 3 & Table 3 3-3, requested in 821010 & 830215 ltrs DIXDN,O W South Carolina Electric & Cas Co 83/06/03 Office of Nuclear Reactor Regulation, Darector ip it 24% Fiche 50-395,83/06/03,8306070402 DENTON-H R 1874D 280
- 8306130417 Confirms agreements reached at 830526 meeting re issuance of 8ER for reactor trip breaker issue Maint procedures will include check of dimensional tolerance of pre- & post-travel of trip tabs DIXON.D W South Carolina Electric & Das Co 83/06/08 DENTON. Office of Nuclear Reactor Regulation, Director 4pp 18823 ISB 24% Fiche.50-395,83/06/08,8306130417 DENTON, N. R.
- 8304160279 Summary of 830428 meeting w/util.Dames & Moore, Ertec, USGS, Gilbert Assoc & URB/Blume in Bethesda, Mr re seismic irmatory program (INS.J B Licensing Branch 4 83/06/10 Licensing Branch 4 18893 026 24% Fiche 50-395,83/06/10,8306160299 HOPKINS, J B
- 8396160725 Bummary of 830324 meeting w/utils & Westinghouse in BetheedarMD re design review panel review of new Westinghouse stress analysis on manifold fasteners for B2/D3 steam generator mod. enerator mod. Licansing Branch 4 83/06/10 Licensing Branch 4 97 24X Fiche 50-000:83/06/10:8306160725 HOPKINS, J. D. 18876 277
- 8306270573 Bummary of Design Review Panel 830321 meeting w/utils & Westinghouse in Dethesda, MD re D2/D3 steam generator mod & Westinghouse stress analysis of manifold fasteners HOPKINB, J B Licansing Branch 4, 83/06/10 Licensing Branch 4, 7pp 19047 085 24X Fiche 50-000, 83/06/10, 8306290573
- 8306230521 Advises that mod of Model D2/D3 steem generators acceptable & modified steem generators can be operated at 1007 of design capacity w/mod in place
 DIRCKS.N J Office of the Executive Director for Operations,
 B3/06/14 PALLADIND.N J , 911 INSKY.V , AMEARNE.J Commissioners
 5pp 18951 357 24X Fiche D0-398,83/06/14,8306230521

- 8306230086 Requests written concurrence that load swing/load rejection tests intended for normal plant operations & that transient conditions initiated by util to complete Phase III test program do not violate License Condition 2 C(22)
 DIXON.O W South Carolina Electric & Gas Co 83/06/20 DENTON.H R
 Office of Nuclear Resctor Regulation, Director 2pp 18947 072.
 24X Fiche 50-395,83/06/20,8306230086
- B306240351 Summary of B30826 meeting w/util & Westinghouse in Bethesda, MD re Westinghouse Model D9-416 reactor trip breakers Tech Spec interpretation & meaning of preserving evidence of
- 8304270354 Forwards responses to NRC questions discussed at 830428 304270396 Forwards responses to NRC questions discussed at meeting re-seismic confirmatory program Equipment margin analysis for safe shuddown equipment for ACRS response spectrum scheduled after first refueling outage DIXON.O W Bouth Carolina Electric & Gas Co B3/06/22 Office of Nuclear Reactor Regulation, Director 123pp 24X Fiche 50-395,83/06/22,0306270356 DENTON, H R. 18994-155.
- @ Inspection reports, IE Bulletins & correspondence
- 8306140637 Confirms mgt meeting on 830527 at plant site to review results of annual appraisal of regulatory performance, per 830511 telcon B3/05/20 DIXIN. D W South Carolina Electric & Gas Co 2pp. 16843:040 Fiche 50-395,83/05/20.8306140637 24 X
- 8306010325 Forwards Rev 2 to "Inservice Insp Program, First Interval," Rev 5 to "General Test Procedure for Inservice Testing of Pumps" & Rev 5 to "General Test Procedure for Inservice Testing of Valvos "
 DIXON.O W South Carolina Electric & Gas Co 83/05/23 DENTON, H & Office of Nuclear Reactor Regulation, Director 3pp 18681 050 24X Ficher 50-375, 83/05/23, 8306010025
- --8306010357 Rev 2 to "Inservice Insp Program, First Interval "
 TURKETT, J., QUINTON, M. D., MODRE, D. R. South Carolina Electric & Gas
 Co. 63/05/19 9pp 18681 056 24X Fiche 50-395,83/05/23,
- --8306010366 Rev 5 to OTP-001, "General Test Procedure for Inservice Testing of Pumps "
 * South Carolina Electric & Gas Co 83/04/14 34pp 18681-065
 24% Fiche 50-395.83/05/23.8306010325
- --8306010374 Rev 5 to OTP-OD2, "General Test Procedure for Inservice Testing of Valves "

 Testing of Valves "

 Bouth Carolina Electric & Gas Co. 83/04/28 177pp. 18681-79 24X Fiche 50-395.83/05/23.8306010325
- 8306140492 Ack receipt of 830511 ltr informing NRC of steps taken to correct violations noted in 16 Insp Rept 50-395/83-08. LEWIS.R C Division of Project & Resident Programs. 83/05/25 DIXON.O W South Carolina Electric & Cas Co. 1p. 18834.267 24 Fiche 50-395/83/05/25,8306140482
- --8306140457 Responds to NRC 830413 ltr re violations noted in IE Insp Rept 50-395/83-08 Corrective actions meeting held w/GA staff to amphasize importance of timely issuance of audit repts & Procedure III A & amployee reading list revised. DIXON.O W South Carolina Electric & Gas Co 83/05/11 O'REILLY.J.P Region 2, Office of Director, 7pp 18834.268 PAX Fiche. 50-395.83/05/25.8306140452
- --8306140461 Forwards 1E Insp Rept 50-395/83-08 on 830307-11 & notice of violation

 LEHIS.R C Division of Project & Resident Progress. 83/04/13

 DIXON.O H South Carolina Electric & Qas Co 2pp. 18834.275.

 24X Ficha 50-095.83/05/25.8306140482
- --8306140465 Notice of violation from imap on 830307-11.
 * Region 2, Office of Director. 83/04/13 3pp 3 18894 277 241
- --8306140471 IE Insp Rept 50-395/83-08 on 830307-11 Noncompliance noted. failure to issue audits within Tech Spec time limits, to respond to audit findings to meet all operator training requirements of IOCFR55.App A to perfore required reading. BELISLE.O A. DEBBAGE, A O. FOSTER.L.E. Region 2. Office of Director. 83/04/06 31pp 18834-280 24X Fiche.50-395,83/05/25, Director. 83/04/06 8306140452
- 8305110458 IE Info Notice B3-32, "Ruptured Am-241 Sources Contained in Well Logging Device" "Svc list encl TAYLOR.J M Division of Bafeguerds & Inspection Programs (Post 830103). 83/05/26. Consolidated Edison Co of New York, Inc 125pp 18831.043. 24X Fiche.50-000,83/05/26,8305110458.

- 8305110460 IE Info Notice 83-34, "Event Notafication Info Worksheet "
- Svc list encl
 JORDAN, E.L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/05/26 Consolidated Edison Co of New
 York, Inc. 115pp 18732 085 24X Fiche.50-000,83/05/26,8305110460
- 8306140045 Confirms 830607 enforcement meeting at Region II ofc to discuss 830523 startup w/safety-related instrument tagged in isolated condition & other recent events. Agenda encl LEWIB, R C Division of Project & Resident Programs 83/05/27 DIXON, O W South Carolina Electric & Gas Co Jpp 18838 248 Fichs 50-395, 83/05/27, 8306140045 24 X
- 8305110461 IE Info Notice 83~35, "Fuel Movement W/Control Rods NOSTIONAL RE AIRS WOLL IST ENCI Hithdraum at BHRs "Svc list encl JORDAN: EL Division of Emergency Preparedness & Engineering Response (Post 830103) B3/05/31. Consolidated Edison Co of New York: Inc. 116pp 18732 208 24X Fiche 50-000, 83/05/31, 8305110461
- 8306140382 Ack receipt of 820520 ltr informing NRC of steps taken to correct violations noted in 1E Insp Rept 50-395/83-01
 LEWIS.R C Division of Project & Resident Programs 83/06/01
 DIXON.O W Bouth Carolina Electric & Gas Co. ip 18832 073 24X
 Fichs: 50-395, 83/06/01, 8306140382
- --8306140388 Suppls response to NRC 830301 ltr re violations noted in 1E Insg Rept 50-395/83-01 Corrective actions, training sessions in methods of tripping logic bistables in Westinghouse 7300 process cabinets held on 830317 & 0407
 PIXON.O W Bouth Carolina Electric & Oas Co 83/05/20
 O'REILLY, JP Region R, Office of Director 2pp 18832 074 24X
 Fiche 50-395,83/06/01,8306140382
- 8306220221 Denies B30127 request for exemption from ASMF Code Bertion XI, Subarticle IWA-1400(f), requirements for first interval of inservice insp program Facility personnel cannot provide same insp assurance as authorized insp agency NOVAK,T M Assistant Director for Licensing. B3/06/08 DIXON.O W South Carolina Electric & Oas Co Spp 18977 360 24X Fiche: 50-395, 83/06/08, 8306220221
- 830629008B Responds to IE Bulletin 83-03 re pump & valve inservice ensp program Two check valves applicable 8TP-123 003 will be revised to include reverse flow test by 830731 Refuzling outage presently scheduled for Oct 1984 DIXON.O N South Carolina Electric & Gas Co 83/06/08 0'REILLY.J P Region 2. Office of Director 2pp 17056 207 24X Fiche 50-395.83/06/08.8306290088
- B305i10464 IE Info Notice B3-36, "Impact of Security Practices on Safe Operations" Syc list encl
 JDRDAN, E.L. Division of Emergency Preparedness & Engineering
 Response (Post B30103) 83/66/09 Consolidated Edison Co. of New
 York, Inc. 119pp. 18830 280 24X Fiche. 50-000, 83/06/07, 8305i10464
- 83061404B7 Forwards IE Enforcement Conference Reat 50-395/83-21 on BOSAOV. Concerns to recent violations of regulatory requirements expressed
 O'REILLY. J P. Region 2. Office of Director 83/06/07
 South Carolina Electric & Gas Co 2pp 18843 069 24
 Fiche 50-395,83/06/09.8306140487 09 DIXON.O W 24X
- --9306140492 IE Enforcement Conference Rept 50-395/83-21 on 830607 Major areas discussed several recent violations of regulatory requirements, Licensee discussed root cause & corrective actions taken or planned to ensure proper plant operation VERRELLI, D.M. Division of Project & Rosident Programs app. 18843:071 24X Fiche 50-395,83/06/09,8304140487 83/06/09
- 8305110470 IE Info Notice 83-38, "Defective Heat Sink Adhesive & Seismically Induced Chatter in Releys Within Printed Circuit Cerds " Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co. of New York, Inc. 118pp 18920-228 24X Fiche 50-000,83/06/13,8305110470
- 8306090010 IE Info Notice 83-37, "Transformer Failure Resulting From Degraded Internal Connection Cables " Byo list encl AN.E. L. Division of Emergency Preparadness & Engineering onse (Fost 830103) 83/06/13 Consolidated Edison Co of New Inc. 243pp 18921 001. 24X Fithe 50-000,83/06/13,8306090010
 - lce 83-40, "Need to Environmentally Qualify
 's" Byc list encl.
) of Emergency Proparedness & Engineering
) 83/06/22. Consolidated Edison Co of New
 9021 179 24X Fiche 50-000,83/06/22,8305110475

- 8305110477 IE Info Notice 83-41. "Actuation of fire Suppression Sys Causing Inoperability of Safety-Related Equipment" Svc list Division of Emergency Proparedness & Engineering Post 8301031 83/06/22 Consolidated Edison Co. of New 120pp 18997 007 24% Fiche 50-000,83/06/22,8305110477 JORDAN, EL D Response (Post York, Inc. 12
- 8305110479 IE Info Notice 83-42. "Reactor Mode Switch Malfunctions " Svc list encl JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/23 Consplidated Edison to of New York, Inc. 116pp 18996 242 24X Fiche 50-000,83/06/23,83051104/9
- 8305110483 IE Info Notice 83-43, "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints "Sec list encl JORDAN, C. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/24 Consolidated Edison Co. of A 19046 297 24X Fiche 50-000,83/06/24,8305110483 York, Inc. 11600
- R Periodic operating reports & related correspondence
- 8306020142 Monthly operating rept for Mai 1983 W/830412 ltr TAYLOR, G J , DIXON.O W South Carolina Electric & Cas Co BARRY, L W Office of Resource Management, Director Sp; 18691 233 24X Fiche 50-395,83/04/11,8306020142 83/04/11
- 8306160570 Monthly operating rept for Apr 1983 W/830505 ltr TAYLOR, G J , DIXON O W South Carolina Electric & Gas Co BARRY, L W Office of Resource Management, Director Spp 18866 285 24X Fichs 50-395.83/05/09,0306160570 B3709702
- S Reportable occurrences. LERs & related correspondence
- B304140670 Final deficiency rept re frozen safety-related snubbers identified per IE Bulletin 81-01 insp Initially reported on B20622 Caused by improper installation, overloading & mishandling Handling procedures will be revised DIXON.O W South Carolina Electric & Gas Co B3/04/22 O'REILLY, J P Region 2. Office of Director 4pp 18842 079 Fiche 50-375, B3/04/22, B306140670
- 8306070202 LER 83-037/03L-0 on 830503, emergency feedwater valve IFV-3556-EF failed to remain closed for 3 h Caused by air leak around valve positioner gasket Positioner cover tightened down & valve tested satisfactorily W/830526 ltr 800MINIOHIR J. DIXON.O W South Carolina Electric & Gas Co 83/05/26 0'REJLLY, J P Region 2. Office of Director 3pp 19747 017 24X Fiche 50-395,83/05/26,8306070202
- 8306070128 Followup RO on 830307, plant outage initiated to perform required steam generator D-3 mods & mods requiring fire barrier removal One-hour fire watch established for affected areas during outage List of affected areas encl
 DIXON, D W South Carolina Electric & Gas Co 83/05/27
 O'REILLY, J P Region 2. Dfface of Director 3pp 18739 316 & Fiche 50-395,83/03/27,8306070128
- 8305100142 Updated LER 83-034/03L-1 on 830409.RHR pump B motor JOSEPH Condition for Cover found partially burned Caused by cable weight forcing B phase terminal lug against cover Termination retaped & procedures revised W/B30602 ltr MCKINNEY.C J. DIXON.O W South Carolina Electric & Gas Co B3/06/02 U/REILLY.J P Region 3, Office of Director 4pp 18801 205 24X Fichs 50-375.83/06/02.8J06100142
- 9306100213 LER 93-042/017-0 on 930519, steam leak activated smoke 306100213 Ltm 83-042/01(-0 on #30519, steam leak activated small detector, tripping open intermediate bldg preaction sprintlrr sys deluge valve. Caused by perconnel error & lack of sys knowledge Deluge valve reset #/830602 ltr MCKINNEY, C J , DIXON.O W South Carolina Electric & Gas Co B3/06/02 O'/REILLY, J P Region 2, Office of Director 5pp 18805 197 24X Fichs 50-395,83/06/02,8306100213
- 8306100163 LER B3-041/01T-0 on 830520, plant entered Mode 3 w/train B of heat tracing associated w/boron injection tank flow path deenergized Caused by personnel error & inadequate procedure Panel energized W/B30603 ltr BOUKNIGHT, R J, DIXON, O W South Carolina Electric & Gas Co B3/06/03 O'REILLY, JP Region 2, Office of Director 5pp. 18807 232 24X Fiche 50~395,83/06/03,8306100163
- B30610020B LER B3-043/03L-0 on B30506, while in Mode 5, operations personnel stepped through Maronite board fire barrier. Caused by personnel error Fire watch established Area posted Barrier repaired W/B30603 ltr FIELD. H C , DIXON. O W South Carolina Electric & Gas Co 83/0 O'REILLY. J P Region 2. Office of Director 2pp 18006 005 Fiche 50-375, 83/06/03, 8306100208 83706703

- 8306100261 LER 83-040/03L-0 on 830506, control room emergency ventilation sys trains A & B inoperable for 26 h Caused by failure in implementing procedural controls Personnel counseled H/830603 lt 900KMIGHT, R J . DIXON, O W South Carolina Electric & Oas Co 83/06/03 O'REILLY, J P Region 2, Office of Director 3pp 18807 035 24X Fiche 50-395,83/06/03,8306100261
- B306140088 LER 83-044/01T-0 on B30523.stram generator D ferdwater flow transmitter FT-486 did not respond to change in feedwater flow Caused by personnel error in not properly identifying transmitter on tayout sheet W/830606 it. MCKINNEY.C J. DIXON.O W South Carolina Electric & Gas Co B3/26706 0'REILLY.J P. Region 2. Dffice of Director App L8839 003 24X Fiche S0-395.01/06/06.8306140088
- B306210021 LER B3-046/03L-0 on B30520, sampling line from pressurizer valve XVX-9357-B8 indicated intermediate position Caused by out of adjustment limit switches on valve Switches adjusted M/B30610 ltr
 B0UKN16HT, R J, DIXON, O W South Carolina Electric & Oas Co B3/06/10 0'REILLY, J P Region 2, Office of Director 2pp 18910 357 24X Fiche 50-395, B3/06/10, B306210021
- 8304210209 LER 83-045/01T-0 on 830531, speed control (SC-2034A) for turbine driven emergency feedwater pump on main control board found in slow speed position (auted by operator error & procedure deficiencies W/8306i0 ltr

 BOUKN10HTR J. DIXON,O W Bouth Carolina Electric & Ges Co 83/06/10 078EILLY,J P Region 2. Office of Director 4pp 18918 127 24X Fiche 50-395.83/06/10.8306210209
- 8306280067 LER 83-047/O3L-O on 830517, w/plant in Mode 4, turbine bldg sump radiation manitor (RM-LB) removed from see because of inadequate sample pump flow Caused by sludge buildup Pump disassembled & cleaned W/B30615 ltr
 MCXINNEY, C J , DIXDN, D W South Carolina Electric & Gas Ca 83206/15 U/REILLY.J P Region P. Office of Director 3pp 19001 177 24X Fiche 50-395/83/06/15/8306280067
- 8306280504 LER 83-048/OSL-O on 830517.w/plant in Mode 4.2one 4 of fire svc sys locked in "trouble alarm" status Caused by water damage to two modules located in preaction sprinkler panel XPN-07! Engineering evaluation requested W/830615 ltr KOLB, L E . DIXON.O W South Carolina Electric & Oas Co 83/06/15 O'REILLY, J P. Rogion 2. Office of Director 3pp 17018 353 24X Fiche 50-395,83/06/15,8306280504
- B306270136 LER B3-050/03L-1 on B30520 & 22, sump pump XPP-138 lost prime & became incapable of pumping water, rendering reactor bldg sump lackage detection sys inoperable Caused by vapor lock Pump primed Air vent valve will be installed W/830616 ltr MCKINNEY; C J. DIXON, O W Bouth Carolina Electric & Oas Co B3/06/16 0'REILLY, J P. Region D, OBFice of Director 3pp 1998 149 24X Fiche 50-395.83/06/16.8306270136
- 8306270289 Part 21 rept re heat sink adhesive bond failures & NTC card relay problems within Westinghouse 7300 process sys Investigation underway to determine number of cards requiring heat sink replacement

 BIXON.O W South Carolina Electric & Gas Co B3/06/17
 O'REILLY, J P. Region 2, Défice of Director 4pp 18996 178 24X
 Fiche 50-395,83/06/17,8306270289
- 8304300122 RD on 830408 main plant vent radiation monitor RM-A13 declared inoperable when channel indicated high radiation Caused by loose cover on reed switch housing of preamplifier circuit board interfering w/electronic components DIXON,O W South Carolina Electric & Cas Co 83/06/20 O'RELLY, J P Region 2, Office of Director 3pp 19121 078 24X Fiche 50-395,83/06/20,8306300122
- 8306300156 LER 83-049/03L-O on 830606.svc water booster pump A discharge check valve, XVC-3135A-8W declared inoperable due to failure to close on reverse flow Caused by worn linkage Hinge & Key replaced & valve disk lapped W/830620 itr BOUKNIGHT: R J. DIXON.O W South Carolina Electric & Gas Co 83706/20 O/REILLY, J.P. Region 2, Office of Director 3pp L7048 393 24X Fiche 50-395, 83/06/20,8306300156
- B30630001B Final Part 21 evaluation rept re potential failure of Brown Bover! Model HPL-C speed switches for component conling pump & svc water pump motors initially reported on 830624. Failed motor replaced & defective motors repaired DIXON.D W South Carolina Electric & Oas Co 83/06/24 D'AELLY.J P Region 2. Dffice of Director 3pp 19120 234 24X Ficher 50-395,83/06/24.8306300018
- B306300049 LER 83-053/03L-0 on B30528, reactor vessel upper plenum level indicator ILI-1320 on main control board removed from svc due to high reading Caused by instrument drift Programmable function generator recalibr W/830624 ltr KGLB-L E. DIXON, O W South Carolina Electric & Gas Co. B3/06/24 O'REILLY-J P Region 2. Office of Director 3pp 19120, 195 24X Fiche 50-395, B3/06/24, 8306300049

- B306300196 LER 83-052/03L-0 on B3052B, main control board indication for steam generator B steam pressure failed high Caused by broken wires on transmitter PT-486 strain gags assembly Assembly replaced PT-486 calibr W/B30624 ltr MCKINNEY, C J. DIXON.O W Bouth Carolina Electric & Oas Co B3/06/24 O'REILLY.J P Region P. Office of Director 3pp. 19122 180 24% Fiche 50-399, B3/06/24, B306300196
- V Operator Examinations
- B306140135 Requests approved ref matl re operator exams by 830028 Missing deadline will result in delay in administering exams Applications should be submitted at least 60 days prior to first exam scheduled for wk of 830411 DANCE.H C Division of Project & Resident Programs 83/01/28 DIXON.O W South Carolina Electric & Gas Co 4pp 18839 131 24% Fiche 50-395.83/01/28.8306140135
- DOCKET 50-394 UNIV OF VIROINIA CAVALIER REACTOR

 F Security, medical, emergency & fire protection plans
- 830422022B Forwards request for addl info re Univ of VA research reactor 820827 emergency plan to continue review per 10CFR30. App E.Rag Quide 2 6.Rev 1 & ANSI/ANS-15 16-1982 requirements Info requested within 30 days of itr date THOMAS.C 0 Standardization & Special Projects Branch 83/06/10 BRENIZER.J S Virginia. Univ of. Charlottesville, VA 5pp. 18977 355 24X Fiche 50-062.83/06/10.8306220228
- DOCKET 50-397 WPPSS NUCLEAR PROJECT, UNIT 2
- A Application/construction stage documents & correspondence
- 8304010236 Clarifies responses to NUREO-0612. "Control of Heavy Loads " Turbine Crame MY-CRA-1 meets guidelines of NUREO BDUCHEY, 60 Washington Public Power Supply System 83/04/13 SCHMENCER,A Liconsing Branch 2 ip 18673 001 24X Fiche 50-397.83/04/13.8306010236
- 8304010413 Forwards descriptions of responsibilities of nuclear safety assurance group, in confirmation of B30209 meeting Encl provides revised response to TMI Items I B 1 2 & I C 5 B0UCHEY, 0 D Hashington Public Power Supply System 85/04/15 SCHWENCER, A Licensing Branch 2 opp 19674 244 24X Ficher 50-397, 83/04/15, 8304010413
- 830&010249 Advises that Tech Spoc 3/4 10 1, "Primary Containment Integriby." will be limiting condition for operation during primary containment integrated leak rate preoperational & startup testing program

 BDUCHEY, O D Washington Public Power Supply System 83/05/16
 BCHENCER, A Licensing Branch 2 2pp 18672 296 24X

 Fichs 50-397,83/05/16,830&010249
- 8304030020 Forwards "Control of Heavy Loads at Nuclear Power Plants, Washington Nuclear Project 2 (Phase II Interim), "technical evaluation rept BCHWENCER.A Licunsing Branch 2 83/05/24 FERQUSON,R L. Washington Public Power Supply System 2pp 18733 146 24X Fiche 50-397,83/05/24,8304030020.
- --8306030088 "Control of Heavy Loads at Nuclear Power Plants, Mashington Nuclear Project 2 (Phase II -- Interim), "draft technical evaluation rept. DIXON, B W , BTICKLEY, T H EQRO, Inc. FIN A-6457 B3/05/24 NRC -- No Detailed Affiliation Olyen 20pp 18733:148 24X Fichs 80-397,83/05/24,8306030020
- 8306070481 Notification of 830607 meeting w/util in Bethesda, MD to discuss radiological Tech Specs. AULUCK, R Licensing Branch 2 83/05/91 SCHWENCER, A Licensing Branch 2 3pp 18776 335. 24% Fiche 50~397,83/05/31,8306070481
- 830A080039 Forwards add1 info re containment out-of-roundness, per 830A19 telcon request, AE evaluation concluded that localized reductions in structural & shielding capacity of biological shield wall insignificant.
 BDUCHEY, @ D Washington Public Power Supply System 83/06/01.
 8CHUENCER, A Licensing Branch 2 5pp 18773:078. 24X
 Fichs 50-397,83/06/01,8306080039
- 8306070030 Notification of 830607 significant licensee meeting w/util at Region V ofc to review program status re engineering. licensing, constitest & startup program & quality verification Resting rescheduled from 830524.

 * Region 5. Office of Director. 83/06/02. Region 5. Office of Director 2pp. 18739 327 24% Ficher 50-397.83/06/02.8306070030

- 8306130004 Requests authorization to use encl ASME Code Case N-343, "Alternative Scope of Exam of Attachment Welds for Exam Categories B-H, B-K-1 & CC Section XI, Div 1 " Rev 2 to Reg Ouide 1 147 will include code case w/no add1 requirements BOUCHEY, O D Washington Public Power Supply System 83/06/02 BCMMENCER, A Licensing Brench 2 2pp 18824 248 24% Fiche 50-397, 83/06/02/8306130004
- 8306210120 Forwards partial response to TAA 830516 audit rept Findings 15 & 16 of independent verification program Response to Finding 14 forthcoming 800CHEY, Q D Hashington Public Power Supply System 63/06/08 80CHENCER, A Licensing Branch 2 App 18918 105 24X Fiche 50-397, 83/06/08, 8306210120
- 8306280596 Forwards responses to NRC telcon questions re H&R technical rept, "Effect of Hydrodynamic Loads on Safety-Related Equipment & Piping Outside Containment," transmitted by 830388 ltr BDUCHEY, 0 D Hashington Public Power Bupply System 83/06/16 SCHHENGER, A Licensing Branch 2 17pp 19018 17/ 24X Fiche. 50-397, 83/06/16.8306280596
- E NRC Safety Evaluation Report (SER), supply & correspondence
- 8306010043 SAFETY EVALUATION REPORT RELATED TO THE OPERATION OF MPPSB NUCLEAR PROJECT NO. 2 Docket No 50-39/ (Washington Public Power Supply System)

 * Division of Licensing NUREQ-0892 SO3 83/05/31 46pp Available 4t NRC \$4 75, 18684 082 24% Fiche, 50-397, 83/05/31, 8306010043
- 8306200243 Forwards three listed repts to expedite resolution of SER Outstanding Issue 13 re control sys failures, in response to NRC Questions 031.135,137 & 138 BOUCHEY, 0, D. Hashington Public Power Supply System 83/06/10 BCHMENCER, A. Licensing Branch 2. ip. 18901, 304 24X Fiche, 50-397, 83/06/10,8306200243
- --8306200247 "Cold Shutdown Power Bus Failure Analysis Rept "
 WORTHAM, T R . KINSTON, P B General Electric Co 83/02/28 130pp
 18901 305 24X Fiche 50-397.83/06/10.8306200243
- ~~8306200251 "Evaluation of High Energy Line Breaks & Consequential Control Sys Failures (IE Info Notice 79-22 Summary Rept) " PARKER, J. E. Hashington Public Power Supply System 83/02/28 Sopp. 18902 043 24% Fiche 50-397.83/06/10.8306200243
- --8306200253 "Common Sensor Failures Evaluation Rept." 8CHERER, P. R. General Electric Co. 83/04/30 48pp. 18902-082 24X Fichs. 50-397, 83/06/10, 8306200243
- 8306280453 Forwards "Control Sys Failures Evaluation Rept."
 inadvertently omitted from 830610 response to NRC request
 for info re SER 3 Outstanding Issue 13.
 80UCHEY, O D Washington Public Power Supply System 83/06/21
 80
- --8306280456 "Control Sys Failures Evaluation Rept"

 SCHERER, P. R., WORTHAM, T. R., ECKERT, E. C. General Electric Co.

 \$2/09/30 24pp 19020:142 24X Fiche 50-397.83/06/21,8306280453
- F Security, medical, emergency & fire protection plans
- 8306010400 Forwards proposed schedule re current status of emergency response capability ger Region V 830301 meeting (Generic Ltr 82-34 Euppl 1 to NNREO-0737) 80UCHEY, O D. Washington Public Power Bupply System 83704/15 80HWENGER, A Licensing Branch 2 4pp, 18682-241 24X Fiche: 50-397, 83704/15, 8306010400
- B304010241 Provides addl info re Yekima Indian Nation.per verbal request. State of MA utilizes law enforcement taletupe systo notify contiguous counties of event w/potential offsite consequences Yakima County would notify tribal police.

 DONOVAN.R W Federal Emergency Management Agency B3705/19
 AULUGK.R. Licensing Branch 2 lipp 18673-009 24X
 Fiche. 50-397, 83/05/19, 8304010241
- i. Utility Final Safety Analysis Report (FSAR) & amends
- 306160147 Amend 30 to FBAR W/830513 ltr * Washington Public Fower Supply System 83/06/30. 966pp, 18856:001. 24% Fiche.50-397,83/06/30,8306160147.

- Q Inspection reports, IE Bulletins & correspondence
- 8306170215 Forwards 12th progress rept re review of completed safety-related work.per 80071/ commitments & Enforcement Action 80-20 per indice of violation MATLOCK.R 9 Washington Public Power Supply System 82/10/19 ENGELKEN.R H Region 5. Office of Director 16pp 18883-137 24X Fiche 50 397.82/10/19.83061/0715
- 8306100009 Add1 response to FDIA request for documents dtd 020101 or after re SALP Forwards App A documents Documents also avaitable in PDR FELTON, J M Division of Rules and Records 83/04/11 CLARM, R San Francisco Examiner 3pp 18815 252 24X Fiche 50-000,83/04/11, 8306100009
- --8306100014 Submits schedule for Region V SALP Board meetings for 820928-830623 ENGELKEN, R H Region 5, Office of Director 82/03/19 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 18815-255 PAX Fishe 50-000,83/04/11,8306100009
- 8306010368 Forwards final response to IE Bulletin 79-02, Rev 2 re reliability of pipe support bose plates using concrete expansion anchor bolts in Seismic Category I piping sys Approx 10,000 Seismic Category I supports utilized CARLISLE:C S Washington Public Power Supply System 83/05/17 MARTIN J B Region 5, Office at Director Sipp 18682 001 24% Fiche 50-397,83/05/17,8306010368
- 8305110458 IE Info Notice 83-32. "Ruptured Am-241 Sources Contained in Well Logging Device " Svc list encl TAYLOR, J M Division of Safeguards & Inspection Programs (Post 820103) 83/05/26 Convolidated Edison Co of New York, Inc 125pp 18831.043 24% Fiche 50-000.83/05/26,8305110458
- 8305110440 IE Info Notice 83-34, "Event Notification Info Worksheet"
 Svc list entl
 JORDAN,E L Division of Emercency Preparedness & Engineering
 Response (Post 830103) 83/05/24 Consolidated Edison Co. of New
 York, Inc. 115pp 18732 085 24X Fiche 50-000,83/05/24,8305110460
- 8306020079 Ack receipt of 830505 amended response informing NRC of steps taken to correct violations noted in IE Insp Rept 50-397/82-27
 BTERNBERG,D M Region 5, Office of Director 83/05/27
 CARLISEE,C S Mashington Public Power Supply System 1p 18691 262 24X Fiche 50-397,83/05/27,8306020099
- --B306020104 Amended response to NRC 830104 ltr re violations noted in le Insp Rept 50-397/82-27 Corrective actions reinsp af all large & small bore-type bracket installations complete No addl rework or welding required CARLISLE.C 8 Washington Public Power Supply System 83/05/05 STERNBERG, D M Region 5, Optice of Director 3pp 18691 263 24X Fichs 50-397,83/05/27,8306020099
- 8306280503 Forwards IE Insp Rept 50-397/83-15 on 830503-05 No noncompliance noted 800%, H E Region 5, Office of Director, 83/05/27 CARLISLE.C 8 Washington Public Power Supply System 2pp 19018 356 24X Fiche 50-397,83/05/27,8306280503
- ~-8305280507 IE Insp Rept 50-397/83-15 on 830503-05 No noncompliance noted Major areas inspected lab capability for performing chemical & radiochemical assays & adequacy of lab GA program HAMADA. 0 H, TEMPLE. 0, HENSLAMSKI, F Region 5, Office of Director 83/05/27 5pp 19018 358 24X Fiche 50-397.83/05/27.8306280503
- 8305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods Withdrawn at BWRs * Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/31 Consolidated Edison Co of New York, Inc 116pp 18732 208 24% Fiche 50-000,83/05/31,8305110461
- 8306280209 Forwards IE Insp Rept 50-397/83-18 on 830328-0408 No noncompliance noted STERNBERG, D. A Region 5, Office of Director 83/06/02 CARLIESLE, C S Washington Public Power Supply System 2pp 19015 047 24X Fiche 50-397,83/06/02,8306280209
- --8306280215 IE Insp Rept 50-397/83-18 on 830328-0408 No nencompliance noted Major areas inspected previously identified followup items & const deficiencies in areas of concrete expansion anchor & safety-related slectrical sys installation. ELIN. J P. D0DBs.R.T Region 5. Office of Director. 83/05/25 9pp 19015 049 24X Fither 50-397.83/06/02.8306280209

- 8306280334 Forwards IE Insp Rept 50-397/83-14 on 830401-30 & notice of violation W/o notice of violation STERNBERG D M Region 5. Office of Director 89/06/03 CARLISLE.C S Washington Public Power Supply System 2pp 19001 283 24X Fiche 50-397.03/06/03.0306280334
- --B306280341 IE Insp Rept 50-397/B3-14 on B30401-30 Noncompliance noted failure to prevent damage to installed equipment & failure to assure adequate repairs & conformance to contamination & concrete cover requirements TOTH A D . FEIL, R A . DDDDG K T . Region 5. Office of Director B3/06/02 14pp 1900; 285 24X Fiche 50-397, B3/06/03, B306280334
- 8306280516 Forwards IE Insp Rept 50-397/80-17 on 830401-30 No SIDERUSIA FORWARDS IE INSP REPT 30-37/761-1/ ON 830/01-30 NONECOMPLIANCE NOTED STERNIERG.D M Region 5, Office of Director 83/06/06 CARLIBLE.C 8 Washington Public Power Supply System (19017 187 24X Fiche 50-377.83/06/06,8306280316
- --9306280921 IE Insp Rept 50-397/83-17 on 830401-30 No noncompliance noted Major areas inspected fuel receipt & storage, preoperational test program implementation & test witnessing & independent insp effort FEIL.R A , DODDS,R 1 Region 5, Diffice of Director 83/06/02 app 19017-191 24X Fiche 50-397.63/06/06.8306280516
- B305110464 IE Info Notice 83-36. "Impact of Security Practices on Safe Operations " Svc list encl JORDAN, EL Division of Emergency Preparedness & Engineering Response (Post B30103) B3/06/09 Consolidated Edison Co of New York, Inc 119pp 18830 280 24X Fiche 50-000, 83/06/09, 8305110464
- 8306200243 Forwards three listed repts to expedite resolution of SER Outstanding Issue 13 re control sys failures, in response to MRC Questions 021 135.137 & 138 BOUCHEY, 8 D Washington Public Power Supply System 83/06/10 SCHMENCCR. A Licensing Branch 2 ip 18701 304 24X Fiche 50-397, 83/06/10.8306200243
- --8306200247 "Cold Shutdown Power Bus Failure Analysis Rept " HORTHAM, T R . KINSTON.F B General Electric Co 83/02/28 130pp 18901 305 24x Fiche 50-397.83/06/10,8306200243
- --8306200R51 "Evaluation of High Energy Lina Dreaks & Consequential Control Bys Failures (IE Info Notice 79-22 Summary Rept)." PARKER.JE Washington Public Power Supply System 83/02/28 36pp 18902 043 24X Fiche 50-397.83/06/10.8306200243
- 8305110470 IE Info Notice 83-38, "Defective Heat Bink Adhesive & Seismically Induced Chatter in Relays Within Printed Circuit Cards " Bvc list encl JGRDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Concolidated Edison Co of New York, Inc. 118pp 16920 225 24X Fiche 50-000,83/06/13,8305110470
- B304090010 IE Info Notice 83-37, "Transformer Failure Resulting From Degraded Internal Connection Cables " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/13 Consolidated Edison Co of New York, Inc 243pp 18921 001 24X Fithe 50-000,83/04/13,8306090010
- £304280371 Forwards 1€ Insp Rept 50-397/84-20 on 830514-20 No noncompliance noted STERNBERG.D M Region 5. Office of Director 83/06/15 CARLISLE.C 8. Weshington Public Power Supply System 2pp 19001 323 24X Fiche 50-397.83/06/15.8306280371
- --8304280380 IE Insp Rept 50-397/83-20 on 830514-20 No noncompliance noted Major areas inspected GA program, TMI (NURE0-0737) activities, including Confirmatory Issue 22 & independent inse WILLETT, D. J. DODDS, R. T. Region 5, Office of Director 93/06/15 7pp. 19001:325 24X Fiche 50-397.83/06/15,8306280371
- 8304210240 Forwards IE Mgt Meeting Rept 50-397/83-25 on 830404 No oncompliance noted

 STERNBERG,D M Region 5. Office of Director 89/06/17
 CARLIBLE,C, S Washington Public Power Supply System ip
 18917:015 24X Fiche 50-397.03/06/17.8306210240
- --0306210245 IE Mgt Meeting Rept 50-397/83-25 on 830606 No noncompliance noted Major areas discussed sys completion engineering & licensing, quelity verification & test & startup programs & opertions & planning Viewgraphs encl BODDS.R.T Region 5, Office of Director 83/06/16 130pp 18917.016 24X Fiche 50-397.83/06/17,8306210240
- 8305110475 IE Info Notice 83-40, "Need to Environmentally Qualify
 Epoxy Grouts & Bealers " Svc list encl.
 JORDANNE L. Division of Emergency Preparedness & Engineering
 Response (Past 830103) 83/06/22 Consolidated Edison Co. of New
 York, Inc. 115pp 19021 179 24X Fiche 50-000,83/06/22,8305110475

- 8305110477 IE Info Notice 83-41. "Actuation of Fire Suppression Sys Causing Inoperability of Safety-Related Equipment " Syc list
 - encl JORDAN, E.L. Davision of Emergency Preparadness & Engineering Response (Post 830103) 83/06/22 Consolidated Edison Co. of New York, Inc. 120pp 18997 007 24% Fiche 50-000,83/06/22,8305110477
- 8305110479 IE Info Notice 83-42, "Reactor Mode Switch Malfunctions " Svc list enc)
 JORDAN, E L Division of Emergency Preparedness & Engineering
 JORDAN, E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/06/23 Consolidated Edison Co of New
 York, Inc. 116pp 18996 242 24X Fiche 30-000.83/05/23.8308110479
- 8305110483 IE 1nfo Notice 83-43, "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints " Svc list encl JORDAN E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/24 Consolidated Edison Co of New York, Inc 116pp 19046 297. 24X Fiche 50-000.83/06/24.8305110483.
- R Periodic operating reports & related correspondence
- 8 Reportable occurrences, LERs & related correspondence
- 8306100122 Part 21 Rept 82-10 re path of in-leakage in MSIV leakage control sys Path exists because valve not powered from critical bus to assure that MSIV-146 will be powered from critical bus to assure that MSIV-105 can perform intended function CONN, W G Burns & Ree Co 82/11/09 ENGELKEN, R H Region 5, Office of Director 4pp 18802 031 24X Fiche 50-397,82/11/09,8306100122
- 8306070095 Interim Deficiency Repts 216 & 223 re gaseous release from NOOVINGTO Internm Detriciency Repts 26.6 & 223 ms gaseous release (
 RHR relief valve vents & inadequate standby liquid control
 systrespectively Final Deficiency Rept 232 ms improper
 installation of RHR support pin receptacle also encl
 CARLIBLE, C.S. Washington Public Power Supply System 83/05/17
 MARTIN.J B. Region 5, Office of Director App. 18739 127
 Fiche 50-397,83/05/17.8304070095
- 8304010220 Final Deficiency Repts 227 & 254 re hangers not installed in turned over HPCS sys 7 i & improper installation of Lubrite assemblies, respectively Interim rept 25i re Limitorque motor operators e/motors supplied by Baldor encl.
 CARLISUS, C B Washington Public Power Supply System 83/05/23 MARTIN, J B Region 5, Office of Director 4pp 18673 005, 24X Fiche 50-397,83/05/23,8304010220
- 830.6240171 Part 21 Evaluation Rept B3-07 re improperly sized overcurrent fuses in dc motor feeders initially reported on 830.607 Fuses sized for 225% of full load current will be provided for logging pump VANDERBER; J Burns & Roe Co 83/06/06 COLLINS.J T. Region 4. Office of Director 16pp 18981 003 24% Fiche 50-397.83/06/06, 8306240171
- 8306270347 Recommends deletion of all refs to RHR steam condensing sys from sucl Interim Deficiency Rept 216 re RHR relief valve vents 8team condensing mode of RHR sys will be deactivated BOUCHEY, 0 D Washington Public Power Supply System 83/06/22 BCHHENGER, A Licensing Branch 2 2pp 18993:135 24X Fiche: 50-397,83/06/22,8306270347
- --B306270353 Interim Deficiency Rept 216 rs RHR relief valve vents.
 Initially reported on B21022. Relief valves will be removed,
 containment leakege path will be aliminated & steam
 condensing mode will be deactivated Next rept by B30817.
 CARLISLE, C 8 Washington Public Power Supply System B3/05/18
 HARTIN. J B Region 5. Office of Director App 18993:137. 24
 Fiche 50-397, 83/06/22, 8306270347
- DUCKET 50-400 SHEARON HARRIS NUCLEAR POWER PLANT, UNIT I A Application/construction stage documents & correspondence
- 830.6140.659 Summarizes 830128 meeting at plant site re results of self-evaluation programs & to tour plant. Heating beneficial, O'REILLY, J.P. Region 2, O'ffice of Director. 83/02/09 UTLEY, E. E. Carolina Power & Light Co. ip. 18833 360 24% Fiche: 50-400, 83/02/09, 8306140659

- B306160657 Forwards Mechanical Engineering Branch request for addition of criteria used for design & const of piping supports in FSAR Clarification of codes & stds used for design & const required to complete review KNIOHTON, 0 W Licensing Branch 3 B3/06/01 UTLEY, E E (arolina Power & Light Co | 3pp | 18884 353 | 24X Fiche SO-400, 63/06/01, 820416657
- 8306200017 Notification of 830615 meeting w/util in Bethesda. MD to discuss issues is structural analysis & consideration of soil structure interaction in analysis KADAMBI.N P Licensing Branch 3 83/06/03 KNIGHION. 0 W Licensing Branch 3 3pp 18707 118 24X Fichs 50-400,83/06/03.8306200017
- 8306270012 Notification of 830623 meeting w/util in Bethesda, MD to discuss applicant mgt organizational & operational structure RADAMBI.N P Licensing Branch 3 83/06/10 KNIGHTON.6 W Licensing Branch 3 3pp 18999 346 24X Fichs 50-400.83/06/10.8306270012
- 8306200019 Summary of 830331 meeting w/ut>is & Westinghouse in Bethesda: ND re Westinghouse analysis & evaluation of D4/D9/E steam generator mod MDPKINB; J B Licensing Branch 4 83/06/14 Licensing Branch 4 22pp 18908 327 24X Fiche 50-000.83/06/14, B306200019
- B306210002 Forwards addI info re FSAR Amend 5 per NRC request Info includes responses to safety review questions, revs to reg guide positions in FSAR Chapter 1 & revs to nuclear operations dept organization MCDUFFIE, M A Carolina Power & Light Co 83/06/17 DENTON, H R Office of Nuclear Reaction Regulation. Director IfOpp 18911 00. 24X Fiche 50-400.83/06/17.8306210002
- 8306270113 Responds to 830421 ltr & forwards design documents per 830201-03 meetings w/Mechanical Engineering Branch W/o encl MCDUFFIE.M A Carolina Power & Light Co 83/06/22 DENTON.H R Office of Nuclear Reactor Regulation. Director 3pp 18988 103 24X Fiche 50-400.83/06/22.8306270113
- D NRC Draft/Final Environmental Statements, suppls & correspondence
- 8306280269 Informs that review of DES complete Major factors of environ concern to Soil Conservation Svc adequately covered GARRETT.C A Agriculture, Dept of 83/06/22 Division of Licensing 2pp 19014 362 24X Fiche 50-400.83/06/22.8306280269
- E NRC Bafety Evaluation Report (SER), suppls & correspondence
- 8306080064 Forwards add1 input to draft SER & request for info returbine missiles Items should be added to list in Chapter 1 of draft SER as confirmatory items KNICHTON.0 W Licensing Granch 3 83/05/24 UTLEY,E E Carolina Power & Light Co 3pp 18787 300 R4X Fiche 30-400.83/05/24, 8306080064
- 8306160272 Forwards change pages to draft SER Changes cover turbine missiles, fuel design reactor matls, functional design of reactivity control sys & steam generator matls KNIGHTON, @ W. Licensing Branch 3 83/06/01 UTLEY, E.E. Caroline Power & Light Co. 45pp. 18872 172 24% Fiche 50-400,83/06/01,8306160272
- 8304040152 Forwards response to draft SER Open Itum 210 re results of evaluation of chemical & vol control sys malfunction event Transient scenario would not experience significant change except for delay of pressurizer low pressure trip MCDUFFIE.H A Carolina Power & Light Co 83/06/02 DENTON.H R Office of Nuclear Reactor Regulation, Director App 18728 097 24X Fiche 50-400,83/06/02,8304060152
- 8306060202 Forwards response to draft SER Open Item 306 re rated load test sequence for dissel generator load acceptance testing FSAR Section 8 3 J 1 2 14K will be revised as listed in future amend MCDUFFIE, M A Carolina Power & Light Co 83/06/02 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 18727: 293 24X Fiche: 50-400, 83/06/02, 8306060202
- 8306070122 Forwards response to draft SER Dpan Item 182 re process & effluent monitoring program
 HCDUFFIE, M A Carolina Power & Light Co 83/06/02 DENTON, H R,
 Dffire of Nuclear Reactor Regulation, Director 2pp 19739 210
 24% Fiche: 50-400, 83/06/02, 8306070122

- 8306080032 Forwards responses to draft SFR Open Items 156 & 157 remain condenser evacuation sys (MCEB) capacity & MCEG quality group correlation w/Reg Guide 1 26 Group D MCDUFFIE,M A Carolina Power & Light Co 63/06/02 DENION,H R Dffice of Nuclear Reactor Regulation. Director 3pp 102/3 005 24X Fiche 50-400,83/06/02,8306080032
- 8306070151 Forwards response to draft SER Open Itums 37 & 37 reitradiation strengthened Zircalog yield strengths & predicted cladding collapse time, respectively Response corrects 830518 submittal ZIMMERMAN, S.R. Carolina Power & Light Co. 83/06/03 DENION, H. R. Diffice of Nuclear Reactor Regulation, Director Spp. 18736-263 24X Fiche 50-400,83/06/03,8306070151
- 8306240463 Forwards results of NRC 830307-11 structural audit of plant at Ebasco in New York NY List of open items should be included in open items list of Chapter 1 of draft SER KNIGHTUN, 0 W Licensing Blanch 3 83/06/03 UTLEY, E E Carolina Power & Light Co 11pp 18997 244 24X Fithe 50-400, 83/06/07, 8306240463
- 8306100188 Forwards revised response to draft SER Open Itum (4.) e identification of SA-540, Class 1 & 2 matl used for clusure bolting in reactor coolant pumps MCDUFFIE, M A Carolina Power & Light Co 83/06/07 BENTON, 14 R Office of Nuclear Reactor Regulation, Director 2pp 18005, 281 24X Fiche 50-400,83/06/07,830610018B
- 8306240467 Forwards open items list of resolve questions to quality group classification to be included in draft SER as substant of Section 175
 KNICHTON.C W Licensing Branch 3 83/06/07 UTLEY.E E Carolina Power & Light Co. 4pp. 18978-096 24X Fiche 50-400,83/06/07,8306240467
- 830.624046B Forwards trip rept of geotechnical engineering 830412 IA site visit & audit List of open items in rept should be added to open items list in Chapter 1 of draft SER KNIGHTON.6 W Licensing Branch 3 83/06/10 UTLEY, E. & Carolina Power & Light Co. Spp. 18998-088 24X Fiche 50-400.03/06/10.
- 8306160116 Forwards responses to Power Sys Branch draft SER Upon Item 117 re cooling water leakage Impact of Flooding from postulated breaks in moderate energy fluid sys have no adverse effects on diesel generator areas MCDUFFIE,M A Carolina Power & Light Co B3/04/13 DENION,H R Office of Nuclear Reactor Regulation, Director 2pg 18861 202 24X Fiche 50-400,83/06/13.8306160116
- 8306170224 Forwards responses to draft SLR Open Items (37.39 % 43) refracture toughness exemption from testing four heats of manual metal and electrodes & compliance w/Charpy V-notch inpact orientation requirements, respectively MCDUFFIE.M A Canolina Power & Light Co 83/06/14 BENION. (f R Office of Nuclear Reactor Regulation, Director App 1882 IJS 24X Ficho 50-400,83/06/14,8306170224
- 83062000B3 Forwards response to Power Sys Branch draft SER Open Item 126 re crankcase vent line Rupture or breakage of crankcase vent line Rupture or breakage of crankcase vent line will not impede engine capability to start or operate as required MCDUFFIE,M A Carolina Power & Light Co 83/06/14 DENTON.If R Office of Nuclear Reactor Regulation, Director 2pp 18903-343 24X Fiche 50-400,83/06/14.8306200083
- 8306200307 Forwards responses to Containment Sys Branch draft () fit () pen Items 64 & 71 re containment pressure instrument lines & containment leakage testing program, respectively Responses to remaining open items forthcoming MCDUFFIE.M A Carolina Power & Light Co B3/06/14 DENTUN.M & Office of Nuclear Reactor Regulation. Director Spp 10500 155 24% Fiche 50-400,83/06/14,8306200307
- 8306210204 Forwards response to draft SER Open Item 145 re solid waste processing sys & Item 176 concerning process control program Absence of free water will be verified by use of process control program per Tech Spec 3/4 11 3 MCDUFFIE.M A Carolina Power & Light Co 83/06/17 DENTON, H R Office of Nucleur Reactor Regulation, Director 3pp 18718 811 24X Fiche 50-400, 83/06/17, 8306210204
- 8306270100 Forwards responses to draft SER Open Items 290 & 291 recombined seismic & dynamic lands to be used in qualification program & qualification of safety-related electrical equipment, respectively MCDUFFIE.M A Carolina Power & Light Co 83/06/22 DENTON. II A Office of Nuclear Reactor Regulation, Director 3pp. 18988. 118 24X Fiche 50-400.83/06/22.8306270100

- 8306270217 Forwards responses to Power Sys Branch draft SER Items 102, 114, 120, 122, 124, 125, 304, 305, 409 & 311 Direct generator training will be given to licensed operators & operations topervisory, maint & GA/GC personnel HCDUFFIE.M A Carolina Power & Light (a 83/04/2, DENTON, H R Office of Nuclear Reactor Regulation, Director 1',pp 10991 203 24X Fithe 50-400, 83/04/2, G306270217
- 8306270241 Forwards draft SER Upen Item 100, providing ref to correspondence & status info Addl open items include NRC 030411,0703 & 24 ltrs. & tolecopied 0 list items.audit items & evaluation of IM1 Item III D i 1 HCDUFFIE.M A Carolina Power & Light Co 83/06/22 DENTON.N R Office of Nuclear Reactor Regulation. Director 77pp 18789 085 24X Fische 50-400, GJ/06/22, 8306270241
- 8306270292 Forwards draft SER Open Item 2, responses for Structural & Gestechnical Engineering Branch
 HCDUFFIE.M A Carolina Fower & Light Cn 03/06/22 DENTON, H R
 Dffice of Nuclear Reactor Regulation. Director 44pp 18990 075
 24X Fiche 50-400,83/06/22.83062/0272
- 830A270448 Forwards response to Power Sys Branch draft SER Open Items 110 & 113 re growth of algae in diesel fuel oil storage tank & quality & reliability of fuel oil supply for emmyency diesel generator operation-respectively MCDUFFIE.M A Carolina Power & Light Co 83/06/22 DENTON.H R Office of Nuclear Reactor Requiation. Director 3pp 18972 063 24X Fiche 50-400.83/06/22.8700070448
- F Security, medical, emergency & fire protection plans
- 8306060112 Forwards supplemental into to detailed control room design review summary rept "Human Factors Design Evaluation Rept for Shearon Harris Unit I Control Room," per Generic Ltr 82-93 Evrata sheets to 821007 rept enci UTLEY, E C Carolina Power & Light Co 0,3/06/01 DENION, If R Office of Nuclear Reactor Regulation, Director 93pp 18722 178 24% Fiche 50-400,83/06/01,8306060112
- C Adjudicatory correspondence
- 8306010355 Advises that negotiations on first set of responses to interrogatories in progress Motion to compel will be issued if negotiations fail EDULEMAN.W Eddleman. W 83/05/26 KILLLY, J Atomic Safety and Licensing Board Panel ip 18681-347 24X Fiche 50 400,83/05/26,8306010355
- 8306010359 Advises that scheduling of negotiations re second set of responses to interpogatories in progress Motion to compet will be issued if negotiations fail EBDLEMAN, W Eddleman, W 87/05/26 KELLEY, J Atomic Safety and Licensing Board Panel ip 18481 348 24X Fiche 50-400,83/05/26,8306010357
- 8306010390 Response to W Eddleman request for production of documents contained in general interrogatories & interrogatories on Contentions 64(f) & 67 (second set)

 O'NEILL, J H Carolina Power & light (a O'NEILL, J H Bhaw, Pittman, Potts & Inobridge 03/05/2/ LIDLEMAN, W Eddlemon, W 2pp 18682 179 24% Fiche 50-400,83/05/27,8306010390
- --830&010375 Response to W Eddinman general interrogatories & interrugatories on Contentions 64(f) & 67 (second set) Affidavits, Certificate of Svc & certification of counsel encl
 O'NEILL, J H Garolina Power & Light Co O'NEILL, J H Shaw, Pittman, Potts & Trowbridge B3/05/27 EDDLEMAN, W Eddinman, W 32pp 18688 181 24X Fich. 50-400, 83/05/27, 830&010370
- B306010439 Memorandum & order, ruling on cost saving contentions, discovery disputes & scheduling matters Informal discussions on proposed contentions between NRC, applicants & intervenors prior to prehearing conference recommended BRIGHT.0 D. CARPENTER.J. H. KELLEY.J. L. Atomic Gafety and Licensing Board Panel B3/05/27. B3/05/27. B3/05/27. B3/05/27. B3/05/27. B3/05/27. B3/05/27. B3/05/27. B3/05/27. B3/05/27.
- 8306020175 Response to W Eddleman 830507 proposed Contention 161 repossible malfunctions of Westinghouse 19-416 circuit breakers Contention admissible per 10CFR2 /14(b) Certificate of Svr encl ROTHSCHILD, M U Hearing Branch 1 83/05/31 Atomic Safety and Licensing Spand Panel Spp 18691 084 24X Fiche 50-400,83/05/31,8306020175

- 8306030336 Response opposing W Eddleman proposed new Contention 161 re
 DS-416 circuit breakers Proposed contention should be
 rejected on alternatively deferred pendang W Eddleman review
 of proposed design change Certificate of Svc sncl
 O'NEILL, J H Carolina Power & Light Co O'NEILL, J H Shaw,
 Pittman, Potts & Froubridge 83/05/31 Atomic Safety and
 Licensing Board Ponel Spp 19706 165 P4X Fiche 50-400.83/05/31,
 220030374
- 8306030337 Confirms that J D'Neill oft contacted to open negotiations re applicant 830527 response to Eddleman Interrogatories 64F & 67 Applicant responses incomplete EDDLEMAN.W Eddleman.W 83/05/31 KELLY.J Atomic Bafety and intensing Board Panel 1p 18705 022 24X Fiche 50-400.83/05/31, 8306030337
- 8306070291 Responses to second set of interrogatories on Contention IVC Certificate of Svc encl O'NEILL.J H Carolina Power & Light Co O'NEILL.J H Shaw, Fittman, Potts & Trowbridge 83/06/02 WILBON,R Wilson, R 129 18741 282 24X Fiche 50~400,83/06/02.8306070291
- 8306070393 Memorandum & order memorializing 830602 telcons & granting intervenor request for extension until 830607 to file reply brief on proposed expert qualifications. KELLEV.J L. Atomic Safety and Licensing Board Panel 83/06/03 2pp 18742 016 24X Fiche 50-400.83/06/03.8306070393
- 8304080149 Response to request for production of documents on Contention 45 Certificate of Svc & Certification of counselenc!
 ELYNN-8 F Carolina Power & Light Co 83/04/03 EDDLEMAN.W
 Eddleman. W 4pp 18772 219 24x Fiche 50-400.83704/03.8304080149
- 8306080160 Answers to first set of general interrogatories & interrogatories on Contention 45 Certificate of Svc encl Related correspondence FLYNN.8 F Carolina Power & Light Co 93/06/03 EDBLEMAN.W Eddleman.W 15pp 18772 159 24X fiche 50-400.83/06/03.8306080160
- 8304090222 Advises that negotiations to discuss 830403 responses to interrugatories re Eddleman 45 (Water hammer) will begin 830423 Motion to compel will be issued if negotiations fail EDDLEPAN.W Eddleman.W 83/04/06 WELLEY.J Atomic Safety and Licensing Board Panel ip 18796 233 24X Fiche 50-400.83/04/06.8304090222
- 8306090225 Reply brief re qualification of intervenor security experts
 Plan review restrictions will not expedite matters Board
 requested to permit listed experts to review relevant
 gartions of plan Certificate of Svc encl
 GREENBLATT, D Affiliation Unknown GREENBLATT, D Greenblatt, D
 83/06/06 Atumic Bafety and Licensing Board Panel 14pp
 1875 348 24X Fichu 50-400.83/06/08.8306090225
- 8306100091 Requests clarification of "Joint Intervenors" in order to direct next round of discovery requests w/specificity & efficiency by 830630 Response requested within 10 days Related correspondence Svc list encl BAXTER.T A Show, Pittman. Potts & Trowbridge BAXTER.T A Carolina Power & Light Co 8306407 PAYNE.H T Edelstein & Payne App 18802 100 24X Fichs 50-400.83/06/07.8306100091
- 8306230345 Advises of util request for identification of author/authors of answers to util interrapatories Evc list encl
 HAXTER, T A Shaw, Pittman, Potts & Troubridge BAXTER, T A
 Carolina Power & Light Co. 03/04/4 CDULEMAN, W. Eddleman, W.
 5pp 18742 277 24X Fichs 50-400.83/06/16,8306230345
- 8304220090 Memorandum & order ruling on intervenor professed security expert qualifications BJ Tuggler. IR Maples. L Stevens & ER Blackher qualify as experts in respective fields. J Mackie disquelified as expert KELLEY, J L , DRJOTH. O O . CARPENTER, J H Atomic Safety and Licensing Board Panel 83/06/17 lipp 18926 211 24X Fiche. 50-400, 83/06/17.8306220090
- 8304220108 Response to second set of general interrogatories & interrogatories on Contentions 27 & 378 BAUSER, D B Carolina Power & Light Co DAUSER, D B, Shaw, Pittmen, Potts & Troubrige 83/06/17 & EDDLENAN, W Eddleman, W. 119pp 18926 257 24X Fiche 50-400, 03/06/17, 8306220108
- --83062201il Response to second request for production of documents on Contentions 29 & 378 Notice of appearance.Certificate of Svc & certification of counsel enc)
 BAUSER, D.B. Carolina Power & Light Co. BAUSER, D.B. Bhow,
 Pittman, Potts & Trowbridge B3/06/17 EDDLEMAN, W. Eddleman, W. 10pp 18927 006 24% Fiche 50-400,83/06/17,8306220108

- 8306220125 Forwards executed LI Loflin & LB Wilson affadavits.for inclusion in util 830510 response to R Wilson interrogatories on Contentions I(a) (d).l(e) (f) Svc list encl Related correspondence CARROW.H Carolina Power & Light Co 83/06/17 RCLLEY,J L , SRIGHT,O D , CARPENTER,J H Atomic Safety and Licensing Board Panel 4pp 18926 103 24% Fiche 50-400.83/06/17.8306220125
- 8306270307 Responses to NRC DES DES does not impact contentions on safety, mpt capability, security or emergency planning EDDLEMAN. W Eddleman. W 83/06/20 3-pp 18995 232 24X Fiche 50-400,83/06/20,8306270307
- --8306270313 Amended interrogatory responses Certificate of Svc encl EODLEMAN, W Eddleman. W 83/06/20 Carolina Power & Light Co 2pp 18995 264 24% Fiche 50-400,83/06/20,8306270307
- 8306270402 Advises of attempts to open negotiations re interrogatories on Contentions 29 & 378 Negotiations toll time for motion to compel, which will follow within 10 days of failure of negotiation EDDLEMAN, W Eddleman, W 83/06/22 KELLEY, J Atomic Safety and Licensing Board Panel 1p 18974 147 24% Fiche 50-400.83/06/22, 8306270402
- 8306280090 Response to W Eddleman & Joint Intervenors 830506 interrogatories Prof qualifications & Certificate of Svc encl BARTH. C A Hearing Branch 1 83/06/24 EDDLEMAN.W Eddleman. H 125pp 19000 288 24% Ficher 50-400.83/06/24.8306280090
- 8306270361 Responds to 830616 ltr re discovery issues Names of experts providing info to W Eddleman will not be provided since exceptional circumstances not demonstrated Cartificate of 8vc enc.1

 EDDLEMAN, W Eddleman, W 83/06/25 DAXTER, T Show, Pittman, Pottr & Troubridge 10pp 19055:22/ 24X Fiche 50-400.83/06/25, 8366290341
- 8306270381 Motion for extension until 830720 to file addl interrogatories on environ contentions & Eddleman Contentions 27 & 378 CONTENT 27 & 370 Eddleman W 83/06/26 Atomic Sofety and Licensing Board Panel App 19053 204 24% Fiche 50-400,83/06/26,8306270381
- 8306290395 Motion to establish schedule for responses to W Eddleman pleading on DES Requests deedline date of 630701 be extended to 630708 Certificate of Svc ent!

 BAXTER, T A Carolina Power & Light Co DAXTER, T A Shaw, Pittman, Potts & Trowbridge 83/06/27 Atomic Safety and Excensing Board Panel 5pp 19055 269 24X Fiche 50-400, 83/06/27, 8306290395
- O Inspection reports. IE Bulletins & correspondence
- 8306140399 Confirms 830510 mgt meeting in Releigh, NC to review BALP program (first phase) results, per 830412 telcon Proposed agenda encl
 LEMIS, R. C. Division of Project & Resident Programs 83/04/29
 UTLEY, E. Carolina Power & Light Co. 3pp 18832 093 24X
 Fiche 50-000, 83/04/29, 8306140399
- 830614036B Forwards IE Insp Repts 50-400/83-17 & 50-401/83-17 on 830803-06 No noncompliance noted VERRELLI,D M Division of Project & Resident Programs B3/05/24 UTLEY,E E Carolina Power & Light Co 2pp 18832 134 24X Fiche 50-400, 83/05/24, 8306140026B,
- --8306i40375 IE Insp Repts 50-400/83-17 & 50-401/83-17 on 830503-06 No noncompliance noted Major areas inspected independent inspeffort, electrical work (cable & terminations) & work activities & inspector followsp item 01880NB.7 D Region 2, Office of Director CONLON.T E Division of Engineering & Radiological Safety Programs 83/05/20 3pp 18832.136. 24% Fiche 50-400,83/05/24,8306i40368
- 8305i10458 IE Info Notice 83-32. "Ruptured Am-241 Sources Contained in Mell Logging Device" Svc list encl
 TAYLOR.J.M. Division of Bafeguards & Inspection Programs (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 125pp 1883i-043 24X Fiche 80-000.83/05/26,8305i10458.
- 8305110460 IE Info Notice 83-34, "Event Notification Info Worksheet"
 Svc list enc!
 JORRAN, E.L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 63/05/26. Consolidated Edison Co of New
 York, Inc. 115pp 18732 085, 24X Fiche 50-000, 83/05/26, 8303110460
- 8305ii0461 IE Info Notice 83-35, "Fuel Novement W/Control Rods Withdrawn at BWRs" Svc list encl. JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/31 Consolidated Edison to of New York Inc. 116pp 18732:208 24X Fiche. 50-000, 83/05/31, 8305110461

- 8306140483 Ack recopt of 830602 ltr informing NRC of strps taken to correct violations noted in II Insp Rept 50-400/83 07 VERRELLI.D M Division of Project & Resident Programs 83/06/02 UTLEY.E E Carolina Power & Light Co 1p 18833 IIB 24X Fiche 50-400,83/06/02.8306140483
- --830a140490 Responds to NRC BJ0412 ltm to violations noted in II lnsp Rept 50-400/B3 0/ Violation denied A'ME Section III.1971 Edition: Summer 1973 addendum requirer no specific documentations for upgrading components. PARSONS, R M Carolina Puwer & Light Co 83/05/12 0'RINLY, J P Region 2, Office of Directon 2pp 10833 119 24X Fishe 50-400,83/06/02,8304140483
- --8306140495 Forwards corrected Page 3 to II Insp Repts 50-400/83 0/ k 50-401/83 07 submitted w/830412 ltn LEMIS.R C Division of Praject & Resident Programs 83/04/18 UTLEY,E E Capulina Power & Light Co 2pp 18833 121 24Y Fiche 50-400,83/06/02,8306140483
- --8306140499 Corrected Page 3 to IE Insp Repts 50-400/03 07 to 50-401/03 07 to
- --8306140503 Forwards IE Insp Repts 50-400/83-07 & 50-401/83 0/ on B30308-11 & notice of violation LEMIS.R C Division of Project & Resident Programs 83/04/12 UTLEY.C f Carolina Power & Light (o 2pp 18637 123 24X Fichs 50-400,83/06/02,8306140483
- --8306140507 Notice of violation from this on 830308-11 * Region 2: Office of Director 83/04/12 ip 18833 125 24X Fiche 50-400.83/06/02.8306140483
- --B306140512 IE Insp Repts 50-400/03-07 % 50-401/83-07 on 83030H-11
 Noncompliance noted documentation not available to confirm
 that math had been upgraded to ment Class I requirements
 MCFARLAND, C R , JACKSON, L H Region 2, Office of Director
 UPRIGHT, C M Division of Engineering & Radiological Safety
 Programs 83/04/08 12pp 18833 126 24X Fiche 50-400,83/05/02.
 8306140403
- 8305110464 IE Info Notice 83-36, "Impact of Security Practices on Safe Operations " Syr Jist encl JORDAN E L Division of Emergency Preparadness & Engineering Response (Post 830103) 03/06/07 (consolidated Edison to of New York, Inc 119pp 18830 280 24X Fishe 50-000.83/06/09.8305110464
- 8305110470 IE info Notice 83-38, "Defective Heat Sink Adhesive & Seismkrally Induced Chatter in Relays Within Printed Circuit Cards " Gyc list one! JORDANIE L Division of Emergency Preparedness & Endineering Response (Post 830103) 83/06/13 Consolidated Edison Co of New York, Inc. 118pp 18920 225 24X Fichs 50-000.83/06/13.83051104/0
- 830.6090010 IE Info Notice 83-37, "Transformer Failure Resulting From Degraded Internal Connection (ables " Svc list enc) JORDAN E L Division of Emergency Preparedness & Engineering Response (Past 830102) 83706/13 Consolidated Edison Co of New York, Inc 243pp 18921 001 24X Fiche 50-000,83706/13,6306090010
- B304290924 Approves issuance of SALP rept Notes improvement in mafety-related activities, emergency preparedness & security & safeguards Meaknosses in GA program will be monitored O'REILLY, J.P. Region 2, Office of Director B3/06/14 UTLEY, E. Carolina Powor & Light Co. hpp. 24X Tiche 50-000, 83/06/14, B304290524
- ---B306270531 Forwards SALP Repts 50-325/83-09, 50-324/83-09, 50-261/83-0/.
 50-400/83-10 & 50-401/83-10 for Jan 1782 Jan 1783
 Evaluation will be discussed in Raleigh.NC on 830510
 LEWIS.R C Division of Project & Resident Programs 83/05/03
 UTLEY.E E Carelina Power & Light Co 2pp 24X
 Fiche 50-000.83/06/14.8306270574
- --8306290537 8ALP rept for Jan 1982 Jan 1983 * Region 2. Office of Director 83/05/03 64pp 24X Fiche 50-000.83/04/14.8306290524
- --8306290553 Responds to 830503 SALP rept for Jan 1982 Jan 1983 Reduced NRC attention may be appropriate for Category 1 re fite protection. NRC attention should be maintained at normal levels for emergency preparedness

 UTLEY.E E Caroline Power & Inght Co 83/05/20 O'REILLY.J P Region 2. Office of Director 16pp 24X Fiche 50-000.83/04/14.
 8306270524

- --8306290555 Forwards replacement Page 2 to Attachment 2 of 830520 lirwhich commented in SALP rept EURY. L W Carolina Fower & light Cn 83/05/27 D'REILLY, J P Region 2, Office of Directol 2pp 24X Fiche 50-000,83/06/14,8306290324
- 8305110475 IE Info Notice 83-40, "Need to Environmentally Qualify
 Epary Grants & Sealers " Svc)ist encl
 JORDAN, E. L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83704/22 Consolidated Edison Ca of New
 York, Inc. 115pp 19021 177 24X Fiche 50-000,83705/22,8305110475
- 8305110477 IE Info Notice 83-41, "Actuation of Fire Supplession Bys Causing Inoperability of Safety-Related Equipment" Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) | D3/06/22 | Consolidated Edison Co. of New York, Inc. 180pp 18997 00/ 24X Fiche 30-000.83/06/22, 8305110477
- 8305ii04/9 IC Info Notice 83-42, "Reactor Mode Switch Malfunctions" Svc list encl JORDAN, Et Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/23 Consolidated Edison Co of New York, Int. 116pp 18996-242 24X Fiche 50-000.83/06/23.8305110479
- 8305110483 IE Info Natice 83-42, "Improper Sattings of Intermediate Range (IR) High flux Trip Setpoints " Svc list encl JORDAN, E t Division of Emergency Preparedness & Engineering Response (Past 830102) 83/06/24 Consulidated Edison Co of New York, Inc. (16pp. 19046-29/ 24X Fiche 50-000.83/06/24.8305110483
- S Reportable occurrences. LLRs & related correspondence
- 830,6010128 Interim rept re-wolding deficiencies in Class IE abxiliary control panels Initially reported on (200401 Welds repaired Vendor comments & analysis for throming Final rept will be submitted by 8:0726 PAREONS.R M Carolina Power & Light Co 83/05/25 O'REJLLY, J P Region 2. Office of Director App 186/4 021 24% Ficha 50-400,83/05/25,8306010128
- 830.6010422 Interim deficiency rept re Gould. Inc Class IE 480 volt motor control ctr protective gromment Initially reported on 830425 Work underway to implement listed corrective actions Nest rept by 831216 Also reportable per Part 21 PARSONB. R M Carolino Power & Light Co. 83/05/25 0'REBLY, J.P. Region 2. Office of Director 4pp 106-79 324 24X Fiche 50-400.63/05/25,8306010402
- 8304070217 Interim rept re itom 105, world deficiencies in auxiliary relay cabinots initially reported on 829101 Apparent deficiencies evoluated by vendor Cabinets acceptable & seismically qualified Next rept will be submitted by 830727 PARSONS, R M Carolina Power & Light Co 83705/26 O'REILLY, J P Region 2. Office of Birector App 18747 041 24X Fichs 50-400.83/05/26.8306070217
- 839A070231 Interim deficiency rept re main leactor trip breakers design discrepancy Initially reported on 830427 Westinghouse will replace undervoltage attachments to accommodate new retaining ring Also reportable per Part 21 PARSONS.R M Carolina Power & Light Co 83/05/26 O'REHLY, J ₱ Region P. Office of Director App 18/46 105 24X Fiche 50-400.83/05/26.8304070% 4
- 8304070366 Interim deficiency rept on bolted structural connections (Item 112) Initially reported on 830426 Add1 training conducted for insp & craft personnel re insp & erection of structural steel linal rept by 840120
 PARSONS.R H Carolina Power & Light Co 83/05/26 D'REILLY, J P Region 2. Office of Director App 18741 308 24X
 Fiche 50 400,83/05/26.8306070766
- 8306070389 Interim deficiency rept.ltm.10% re grease in friction type structural connections Initially reported an 820915 Reimsp of turbine & containment bldgs completed Procedures revised Final rept by 840120
 PARSONS R M Carolina Power & Light Co 83/05/26 O'REILLY J P Region 2. Office of Director App 16/42 019 24X
 Fiche 50-400,83/05/26,8306070309
- 830&070400 Interim deficiency ript re Itim 92, bulted structural connections w/excessive gaps & ABIM A325 nuts on ABIM A490 bults initially reported on GCO702 Reinsp of turbine & containment bldgs completed Next rept by B40120 PARSONS.R M Carolina Power & Light Co B3/05/26 O'REILEY, J.P. Region 2. Office of Director App 18741 358 P4X Fiche 50-400,83/05/26.830&070400

- 8304090242 Second interim rept. Item 117, re welding deficiencies on Class It 6 9 kV circuit breakers Initially reported on 830211 All breakers returned to vendor for fabrication Also reportable under Part 21 PARSONS.R M Caralina Power & Light Co 83/05/31 0'REILLY, J. P Region 2. Office of Director 4pp 18795 332 24X Fiche 50 400,63/05/31.8304090242
- 830&09004& Interim doficiency rept re failure to perform verification of anchor bolt matl type when tags lost (Item 131) Initially reported on 830503 Evaluation of anchor balts continuing Submittal of rept on reportability extended until 830805 PARSONS:R M Carolina Power & Light Ce 83/06/01 O'REILLY, J P Region 2. Office of Director ip 19773 287 24X Fiche 50-400.83/06/01.8304090046
- 8306090180 Third interim deficiency rept to reactor protection sysfailure following secondary high energy line rupture initially reported on 800707 Insulation of steam generator ref leg underway Also reportable per Part 21 PARBONS: R M Caraline Fower & Light Co 83/06/01 U'REILLY, J P Region 2. Office of Director 4pp 18792 271 24X Fiche 50-400.03/06/01.8306090180
- 830&070191 Third interim deficiency rept re potential damage to safety injection charging pump following secondary side high energy line rupture (Item 38) Initially reported on 800707 Resolution under review Also repurtable per Part 21 PARSONSIR M Carolina Power & Light Co 83/06/01 D'REILLY, J P Region 2. Office of Director App 18776 086 P4X Fiche 50-400,83/06/01,830&070191
- B306090251 Final deficiency rept re Item 119, Beismic Class I slectrical, HVAC & conduit supports Initially reported on 830303 Item not reportable under loCFR50 55(e) CHIANGI, N. Carolina Power & Light Co. B3/06/01. D'REILLY, J. P. Region 2, Dffice of Director | p. 18745-292-24X Fiche 50-400, B3/06/01. B306090251
- 8306100238 Interim deficiency rept re ltum 127, shop weld defects in ITT Hammel Dahl chilled water valve ltum also reportable under Part 21 Valve returned to manufacturer Final rept expected by 830901 PAREONS.R M Carolina Power & Light Co 83/06/03 B'REILLY, J P Region 2, Office of Director 4pp 18907 154 24X Fiche 50-400,83/06/03,8306100P38
- 8306100254 Second interim rept on Item 104 re defective welds on 480-volt switchgear supplied by Brown-Hoveri Electric Co. Initially reported on 830304 Major defects repaired Minor defects to be modeled in upcoming seismic test PARSONS.R M Carolina Power & Light Co. 83/06/03 D'REILLY, J P Region 2. Defice of Director 4pp 1880/038 24X Fiche 50-400.83/06/03.8306100954
- 830A20011A Addendum : to final deficiency rept. Item 91:re welded studs on embedded strip plates Any tasting performed by site receipt insp unit is in excess of code requirements since same procedure revealed problem PARSONS.R M Caroline Power & Light Co 83/06/09. D'REILLY: J P Region 2. D'Fice of Director 2pp 18903 250 24X Fiche. 50-400,83/06/09.8306200116
- 8306200200 Addendum I to 800220 final definciency rapt re lamination in maint rail support plates (Item 28) Info provided to justify not conducting addl inap of similar matl PARSONS.R M Carolina Power & Light Co 83/06/09. B'REILLY, J P Region 2. Office of Director 2pp 18903 198 24X Fiche 50-400,83/06/09.8306200200
- 8306270223 Interim deficiency & Part 21 repts re boric acid transfer pumps. Westinghouse Shop Order 205, Item 113 Initially reported on 830113 Support bolting will be replaced & gusset stiffener spot welds supplemented by 930701 PARBONS.R M Carolina Power & Light Co 83/06/14 O'REILLY.J.P Region 2. Office of Director App 18970 227 24X Fichs: 80-400, 83/06/14, 8306270223
- 8306280088 Deficiency rept Item 128 re welding defects in emergency sychoter strainers supplied by RP Adams Initially reported on 830408 Condition not reportable per 10CFR50 55(e) or Part 21 CHIANGI, N J. Carolina Power & Light Co. 83/06/16 O'REILLY, J. P. Region 2, Office of Director 1p 17001, 156 24X Ficher 50-400, 83/06/16, 8306280088.
- 8306280463 Interim deficiency rept re Item 121.welding deficiencies in main steam/ferdwater support frames. Initially reported on 830318 Extension requested until 830715 to submit complete evaluation Also reportable per Part 21 PARSONS: R Carpline Power & Light Co. 83/06/17 O'REILLY: J P Region 2. Office of Director. 1p 19018 294 24X Fiche. 50-400:93/06/17:8306280463

8306300192 Final Part 21 rept on Item 133 re safety injection valves made of carbon steel instead of stainless steel Initially reported on 830524 Valves of correct mitl reordered & incorrect valves retaged PARSONS.R M Carolina Power & Light Co. 83/06/22 O'REILLY, J.P. Region 2, Office of Director. 4pp. 19122 187 24% Fiche 50-400,83/06/22.8306300192

V Operator Examinations

8306140132 Requests approved ref matl re operator exams by 830425 Missing deadline will result in delay in administering exams Applications should be submitted at least 60 days prior to first exam scheduled for 830613 VERRELLI, D M Division of Project & Resident Programs 63/04/0H FURR. B J Carolina Power & Light Co 3pp 18839 086 24% Fiche 50-400, 83/04/08.8306140132

DOCKET 50-401 SHEARON HARRIS NUCLEAR POWER PLANT, UNIT 2

A Application/construction stage documents & correspondence

8304140557 Summarises 83012B meeting at plant site or results of salf-evaluation programs & to tour plant Meeting beneficial O'REILLY, J.P. Region 2. Office of Director 83/02/09 UTLEY, E.F. Carolina Fouer & Light Co. Ip. 18833 340 24X Fiche 50-400,83/02/09.8304140459

8306160657 Forwards Mechanical Engineering Granch request for additing ore criteria used for design & const of piping supports in FSAR Clarification of codes & stds used for design & const required to complete review KNIGHTON. 0. W Licensing Dranch 3 B3/06/01 UTLEY. C E Careline Power & Light Co 3pp 18894 353 E4X Fiche 50-400.83/06/01.8306160657

B306200017 Notification of B30615 meeting w/util in Bethesda.MD to discuss issues re-structural analysis & consideration of soil structure interaction in analysis KADAMBI.N P Licensing Branch 3 B3/06/03. KNIGHTON, 6 W Licensing Branch 3 3pp 18909 IIB 24K Fiche 50-400.83/06/03. 8306200017

8306270012 Notification of 830623 meeting w/util in Bethesda.ND to discuss applicant mgt organizational & operational structure KADAMBI.N P Licensing Branch 3 83/06/10 KNIGHTON.O W Licensing Branch 3 3pp. 18797 346 24X Fiche 50-400.83/06/10. 8306270012

8306200017 Summary of B30331 meeting w/utils & Westinghouse in Bathesda, MD re Westinghouse analysis & evaluation of D4/05/E steam generator mod MDPXINB.J B Licensing Branch 4 83/06/14 Licensing Branch 4 22pp 18908 327 24X Fiche 50-000,83/06/14,8306200019

8306210002 Forwards add1 info re FBAR Amend 5 per NRC request Info includes responses to safety review questions revs to reg guide positions in FBAR Chapter 1 & revs to nuclear operations dept organization MCDUFFIE,M A Carolina Power & Light Co 83/06/17 DENTON,H R Office of Nuclear Reactor Regulation, Director 110pp 18V11 CO1 24X Fiche: 50-400, 83/06/17, 8306210002

830&270113 Responds to 830421 ltr & forwards design documents per 830201-03 meetings w/Mechanical Engangering Branch W/o encl MCDUFFIE.M A Catalina Power & Light Co 83/06/22 DENTON.H R Office of Nuclear Reactor Regulation. Director Spp 18798 103 24X Ficha 50-400, 83/06/22, 8306270113

D. NRC Draft/Final Environmental Statements, suppls & correspondence

8306280269 Informs that review of DEB complete Major factors of environ concern to Soil Conservation Syc adequately covered OARRETIC A Agriculture. Dryt of 83/06/22. Division of Licensing 2pp 19014 362 24% Fiche 50-400, 83/06/22, 8306280269

RC Safety Evaluation Report (SER), supple & correspondence

addl input to draft SFR & request for info re 'tems should be added to list in Chapter I 'irmatory items ing Branch 3. 83/05/24. UTLEY,E E Carolina p. 18/87 300 24% Fichs 50-460,83/05/24, 9306160272 Forwards change pages to draft SLK Changes cover turbine missiles. Fuel design reactor motts. Functional design of reactivity control sys steam generator matts
KNIGHTON.G W Licensing Branch 3 B3706/01 UTLLY, E.L. (aroline Power & Light to 45pp 18672 172 248 Fiche 50-400.83/06/01.
B306160272

8306060152 Forwards response to draft SLR Open Item 210 re results of evaluation of chemical & vol cuitiful rys malfunction event Transient scenario would not experience significant change except for delam of pressurize low picksure trip MCDUFFILN A Carolina Power & Light to 83706702 DENTON, H & Office of Noclear Reactor Regulation, Director 4pp 1879 077 24X Fiche 50-400,83706702,8306060152

8304040202 Forwards response to draft SLM Open Itom 304 re rated load test sequence for diesel generator load acceptance testing FSAR Section 8 3 1 1 2 14K will be revised as listed in future amend MCDUFFIE.N A Carolina Power & Light Co 83/05/02 DENTON, H H Office of Nuclear Reactor Regulation, Director Ppp 1877/ 793 24X Fische 50-400, 03/06/02, 030660202

8206070122 Forwards response to draft SLR Open Item 162 be process to effluent monitoring program MCDWFIL, M A Carolina Power & Light (b 83/06/02 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 18/29, 210 24X Fiche 30-400, 83/06/02, 83/06/070122

B306080032 Forwards responses to draft bin Upon Items 156 & 157 rp main condenser evacuation sys (MCES) capacity & MCES quality group correlation w/Neg Qualet 1 % Group i MCDUFFIE.M A Carolina Power & Light Co 83/06/52 DENION, 4 k Office of Nuclear Reactor Regulation, Director 3pp 18/73 005 24X Fiche 50-400, B3/06/02, B30608003P

B306070151 Forwards response to draft SLR Dpen Items SP & 3J to irradiation strengthened Zircalog yield strengths & predicted cladding collapse time, respectively Response corrects 830518 submittal ZIMMERMAN, SR Carolina Power & Light Co. 83/06/03 DENIGN, # k Office of Nuclear Reactor Regulation, Director 3pp. 18/36-264-24X Fiche 50-400,83/06/03,8306070151

8306240463 Forwards results of NRC 830307-11 structural audit of plant at Ebasco in New York.NY List of open items should be included in open items list of Open items should be included in open items list of Chapter I of draft SFR KNIGHTON.6 W Licensing Drawch 3 83/06/03 UTLEY.E Catalina Power & Light Co lipp 1899/ 244 24X Fiche 50-400.83/06/04.830620463

830610018B Forwards revised response to draft SER Open Item 34.re identification of SA-540.Class I & 2 mith used for closure bolting in reactor coolant pumps HCDUFFIE.8t A Carolina Power & Light Co 83/06/07 DENION,H & Defice of Nuclear Reactor Regulation, Director Ppp 1880; 741 24X Fiche 30-400.G3/06/07.830610018B

830624046/ Forwards open items list of resolve questions re quality group classification to be included in druft SER on subitems of Section 17 5
KNEGHTON.0 W Licensing Branch 3 63/06/07 UTLLY.E E (arelina Power & Light Co 4pp 18978-096 24X Fiche 50-400.83/06/07, 8306240467

830624046B Forwards trip rept of geotechnical engineering 830412-14 site visit & audit List of open items in rept should be added to open items list in Chapter 1 of draft SER KNIGHTON, 6 W Licensing Branch 3 83/06/10 UTLLY, C E tarolina Power & Light Co Gpp 18978 088 24X Fiche 50-400, 83/06/10.

8306160116 Forwards responses to Power Sys Branch draft SEK Open Item
117 re cooling water leakage Impact of flooding from
postulated breaks in moderate energy fluid sys have no
adverse effects on dissel generator areas
MCDUFFIE.M A Carolina Power & Light (b 83/06/13 DENTON.H &
Office of Nuclear Reactor Regulation, Director 2pp 18861 282
24% Fiche 50-400.83/06/13.8306160116

8306170224 Forwards responses to draft SER Upon Items 37.39 & 43 re fracture toughness, exemption from testing four heats of manual metal arc electrodes & compliance w/Charpy V-notch impact orientation requirements, respectively MCDUFFIE.M A Carolina Power & Light Co 83/06/14 DENTON, N R Office of Nuclear Resector Regulation, Director 4pp 18802 316 24X Fishe 50-400, 83/06/14, 8306170224

- 8306200083 Forwards response to Power Sys Branch draft SER Open Item 126 re crankcase vent line Rupture or breakage of crankcase vent line will not impede engine capability to stort or vent line will now ampeter operate as required
 ACDUFFIE.M A Carolina Power & Light (o 83/06/14 DENIGN, H R
 MCDUFFIE.M A Carolina Power & Light (o 83/06/14 DENIGN, H R
 - Office of Nuclear Reactor Regulation, Director 24% Fiche 50-400,83/06/14.8306200083
- 8306200309 Forwards responses to Containment Sys Branch draft SER Open 305200309 Forwards responses to Containment sys Branch draft SER (Items 64 & 71 re containment pressure instrument) incs & containment leakage testing program, respectively Responses to remaining open items forthcoming KCDUFFIE,N A Carolina Power & Light (a B3/06/14 DENTON, H R Office of Nuclear Reactor Requiation, Director Spp. 18700 155 24% Fiche S0-700,83/06/14,8304200309
- 930-5210204 Forwards response to draft BLR Open Item 165 re solid waste processing sys & Item 176 concerning pincess control program Absence of free water will be verified by use of process control program per lech Spec 3/4 11 3 MCBUFFIE, M A Carolina Power & Light (o. 83/06/17 DENION, N R Office of Nuclear Reactor Regulation, Director ... 3pp. 18718 111 24X Fiche 50-400.83/06/17.8306210204
- 8306270190 Forwards responses to draft LER Open Items 270 & 271 re combined seismic & dynamic loads to be used in qualification program & qualification of safety-related electrical program a quairfication of survey restricts continue agreement respectively HCDVFFLE, M A Carolina Power & Light Co 83/06/22 DENTON, H R Office of Nuclear Reactor Regulation, Director Spp 1898E 118 24X Fiche 50-400,83/06/22,8306270100
- 8306270217 Forwards responses to Power Sys Branch draft SkR Items 102, 114, 120, 122, 124, 125, 304, 305, 309 & 311 Diesel generator training will be given to licensed operators & operations supervisory, maint & 64/06 personnel MCDUFFIE, M A Carolina Power & Light (o 83/06/22 DENION, H R Office of Nuclear Reactor Regulation, Director 15pp 16791 233 24% Fiche 50-400.63/06/22 83062/0217
- 8305270241 Forwards draft SEK Open Item 100, providing ref to SOA2/0241 Forwards Draft Str. Upon Item 100, provining ret to correspondence & status info Add1 open items include NRC 8304]1,0503 & 24 ltrs, & telecopied 0 list items, audit items & evaluation of 7M1 Item III II I HCDUFFIE.M A Carolina Power & Light Co 63/06/22 DENTON, H R Office of Nuclear Reactor Regulation, Director 7/pp 18909 089 24% Fichs 50-400.83/06/22,8306270241
- 9306270292 Forwards draft SER Onen Item 22 responses for Structural & Geotechnical Engineering Branch
 MCDUFFIE,M A Carolina Power & Light Co 83/04/22 DENTON,N R
 Office of Nuclear Reactor Regulation, Director A4pp 18990 075 24X Fiche 50-400,83/06/22,83042/0272
- 830627044B Forwards response to Power Sys Branch draft SER Open Items 110 & 113 re growth of algae in diesel fuel dil storage tank & quality & reliability of fuel oil supply for emergency diesel generator operation respectively MCDUFFIE,M A Carolina Power & Light Co 03/06/22 DENION,H R Office of Nuclear Reactor Regulation, Director Upp 18972 063 24X Fiche 50-400,83/06/22,83062/044B

O Adjudicatory correspondence

- 8304010390 Response to W Eddleman request for production of documents contained in general interrogatories & interrogatories on Contentions 64(f) & 67 (second set)
 O'NEILL, J H Carolina Power & Light Co O'NEILL, J H Shaw,
 Pittman, Potts & Trowbridge 83/05/27 FDDLEMAN, W Eddleman, W 2pp 18482 179 24X Fiche 50-400, 83/05/27, 8306010390
- ~-8306010395 Response to W Eddleman general interrogatories & interrogatories on Contentions 64(f) & 67 (second set) Affidavits, Certificate of Evc & certification of counsel enci O'MEILL.J H Carolina Power & Light Co D'NEILL.J H Show, Pittman, Potts & Trowbridge 83/05/27 EDDLEMAN,W Edd]eman, W 32pp 18682 181 24X Fiche 50-400,83/05/27,8306010390
- 6306010437 Memorandum & order ruling on cost saving contentions.

 discovery disputes & acheduling matters Informal discussions on proposed contentions between NRC applicants & intervenors prior to prehearing conference recommended BRIGHT, G. D., CARPENTER, J. H., KELLEY, J. L. Atomic Safety and Licensing Board Panel 83/05/27 26pp 18679 2/6 24% Fiche 50-400. 83/05/27, 8306010439
- 830.6020175 Response to W Eddleman B3050/ proposed Contention 161 repossible malfunctions of Westinghouse Pb-416 circuit breakers Contention admissible per 10CfR2 714(b) Certificate of Svc snc! R0THSCHILD, M U Hearing Branch i B3/05/31 Atomic Bafety and Licensing Board Panel 8pp 18671 084 24X Fiche 50-400,83/05/31,8306020175

- 83060303026 Response upposing W Eddleman proposed new Contention 16f re DS-416 circuit breakers Proposed contention should be rejected or alternatively, deferred pending W Eddleman review of proposed design change Certificate of Svc sncl O'NEILL, J H Carolina Power & Light Co O'NEILL, J H Shaw, Pittman, Potts & Trowbridge 83/05/31 Atomic Safety and Licensing Roard Panel 8pp 18706/165 24X Fiche 50-400,83/05/31. 8304030334
- 8306030337 Confirms that J D'Neill ofc contacted to open negotiations re applicant 830827 response to Eddleman Interrogatories &4F & 67 Applicant responses incomplete EDDLEMAN, W Eddleman, W 83/05/31 KELLY, J Atomic Safety and Licensing Board Panel Ip 18705 022 24X Fishe 50-400,83/05/31,8306030337
- 8304070291 Responses to second set of interrogatories on Contention IVC Certificate of Svc encl O'NELL,JH Carolina Power & Light Co O'NELL,JH Pittman, Potts & Trowbridge 83/06/02 WILBON,R Wil 18741 282 P4X Fiche 50~400,83/06/02,8304070291 Shaw, Wilson, R. 12pp
- 8306070393 Memorandum & order memorializing 830602 telcons & granting intervenor request for extension until 830607 to file reply brief on proposed expert qualifications KELLEY, J L Atomic Safety and Licensing Board Panel 83/06/03 2pp 18742 016 24X Fiche 50-A00.83/06/03.8306070393
- 8306080149 Response to request for production of documents on Contention 45 Certificate of Svc & Certification of counsel FIVAN S F 83/06/03 FLYNN,8 F Carolina Power & Light Co. 83/06/03 EDDLEMAN,W. Eddleman, W 4pp 18772 219 24X Fiche 50-400,83/06/03,8306080149 4рр
- B3060B0160 Answers to first set of general interrogatories & interrogatories on Contention 45 Certificate of Svc encl. Related correspondence Related correspondence
 FLYNN.8 C Carolina Power & Light Co 83/06/03 EDDLEMAN
 Eddleman, W 15pp 18772 159 24X Fiche 50-400,83/06/03, 8304080140
- B306070222 Advises that negotiations to discuss 830603 responses to interrogatories re Eddleman 45 (water hammer) will begin 830623 hation to compel will be issued if negotiations fail EDDLEMAN.H Eddleman. H 83/06/06 KELLEY.J Atomic Bafety and Licensing Board Panel ip 18796 233 24% Fiche 50-400,83/06/06,8306070222
- 830&090225 Reply brief re qualification of intervenor security experts Plan review restrictions will not expedite matters Doard requested to permit listed experts to review relevant portions of plan Certificate of Svc encl QREENBLATY. D Affiliation Unknown QREENBLATY. D Greenblatt, D 8370&070& Atomic Safety and Licensing Board Panel. 14pp 18795 348 24X Fichs 50-400.83/06/06.8306090225
- 8306100071 Requests clarification of "Joint Intervenors" in order to direct next round of discovery requests w/specificity & efficiency by B30630 Response requested within 10 days Related correspondence Svc list encl.

 8AXTER.T A Shaw, Pittman, Potts & Trombridge BAXTER,T A Carolina Power & Light Co B3706/07. PAVNE, NT. Edelstein & Payr 4pp 18802 100 24X Fiche 50-400,83/06/07,8306100071 Edelstein & Paune.
- 8306230345 Advises of util request for identification of author/authors of answers to util interrogatories Svc list encl BAXTER.T A Shaw. Pittman. Potts & Trowbridge BAXTER.T A Carolina Power & Light Co 83/06/16 EDDLEMAN.W Eddleman, W 5pp 18942 279 24X Fiche 50-400.83/06/16.8306230345
- 830&220090 Memorandum & order ruling on intervenor proffered security expert qualifications BJ Tuggle, JR Maples, L Stevens & ER Bleacher qualify as experts in respective fields
 J Mackie disqualified as expert
 KELLEY. J L . BRIGHTH: 0 0 . CARPENTER, J M Atomic Safety and Licensing Board Papel. 83/06/17 lipp 18926 211 24X Fiche 50-400, 83/06/17.8906220090
- 830622010B Response to second set of general interrogatories & interrogatories on Contentions 29 & 378
 8AUSER, D B Carolina Power & Light Co BAUBER, D B Shew, Pittman, Potts & Troubridge 83/06/17 EDDLEMAN, W Eddleman, W. 119pp.
 18926 237 24X Fiche 50-400, 83/06/17, 830622010B.
- --8306220111 Response to second request for production of documents on Contentions 29 & 378 Notice of appearance, Certificate of Svc & certification of counsel encl BAUSER, D B Carolina Power & Light Co. BAUSER, D. B Shaw, Pittman, Potts & Troubridge 83/06/17. EDDLEMAN, W. Eddleman, W 10pp. 18927 004 24% Fiche 50-400,83/06/17.8306220108

- 8306220125 Forwards executed LI Loflin & LB Wilson affidavits, for inclusion in util 930510 response to R Wilson interragataries on Contentions (ia) (d).1(e) (f) Svc list enc! Related correspondence CARROW, H Carolina Power & Light Co. 83/06/17 KELLEY, J L . BRIGHT, G U . CARPENTER, J H Atomic Safety and Licensing Board Panel App 18726 103 24X Fiche 50-400,83/06/17,8306220125
- 8306270307 Responses to NRC DES DES does not impact contentions on safety, mpt capability, security or emergency planning EDDLEMAN, W Eddleman, W 83/06/20 32pp 18975-232 24X Fiche 50-400, 83/06/20, 8306270307
- --B306270313 Amended interrogetory responses Certificate of Svc encl EDDLEMAN, W Eddleman, W 83/06/20 Carolina Power & Light Co 2pp 18995 264 24X Fiche 50-400,83/06/20,8306270307
- 830A270402 Advises of attempts to open negotiations re interrogatories on Contentions 29 & 378 Negotiations toll time for motion to compel, which will follow within 10 days of failure of negotiation EDDLEMAN.W Eddleman, W 83/06/22 KELLEY, J Atomic Safety and Licensing Board Panel 1p 18994 149 24% Fiche 50-400,83/06/22,8306270402
- 8306280090 Response to W Eddleman & Joint Intervenors 830506 interrogatories Prof qualifications & Certificate of Svc encl BARTH, C A Hearing Branch 1 83/06/24 EDDLEMAN, W Eddleman. # 125p 19000 288 24X Fiche 50~400,83/06/24,83042800990
- 8306290361 Responds to 830616 ltr re discovery issues Names of experts providing info to H Eddleman will not be provided since exceptional circumstances not demonstrated Certificate of Svc entl EDDLEMAN, H Eddleman, N 83/06/25 BAXTER, T Shaw, Pittman, Potts & Troubridge 10pp 19055 227 24x Fiche 50-400, 83/06/25.
- 8306290381 Motion for extension until 830720 to file add1 interrogatories on environ contentions & Eddleman Contentions 27 & 378 EDDLEMAN.W Eddleman.W 83/06/26 Atomic Safety and Licensing Board Panel 4pp 19053 204 24X Fishe 50-400.83/06/26,8306290381
- 8306290395 Motion to establish schedule for responses to W Eddleman pleading on DEB. Requests deadline date of 830701 be extended to 830708 Certificate of Svc encl
 BAXTER, T A Carolina Power & Light Co BAXTER, T A Shaw, Pittman, Potts & Trowbridge 83706/27. Atomic Safety and Licensing Board Panel 5pp, 19055 269 24X Fiche 50-400, 83706/27, 8306290395
- G Inspection reports, IE Bulletine & correspondence
- 8306140397 Confirms 830510 mgt meeting in Ralsigh,NC to review SALP program (first phase) results,per 830412 telcon Proposed agenda entl
 LEWIS,R C Division of Project & Resident Programs 83/04/29 UTLEY,E E Carolina Power & Light Co 3pp 18832 093 24X Fishe 50-000,83/04/27,8306140399
- 8306140368 Forwards IE Insp Repts 50~400/83-17 & 50~401/83-17 on 830503-06 No noncompliance noted VERRELLI.D H Division of Project & Resident Programs 83/05/24 UTLEY, E Carolina Power & Light Co 2pp 18832 134 24X Fiche, 50~400, 83/05/24, 8306140368,
- ~-8306140375 IE Insp Repts 50-A0D/B3-17 & 50-401/83-17 on 830503-06 No nancompliance noted Major areas inspected independent insp effore, selectrical work (cable & terminations) & work activities & inspector followup item 01880NB, T D Region 2. Office of Director CONLON, T E Division of Engineering & Radiological Safety Programs 83/05/20 3pp 18832 136 24X Fiche 50-400,83/05/24,830614036B.
- 8305110458 IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in gging Device " Svc list encl J M Division of Safeguards & Inspection Programs (Post 83/05/26 Consolidated Edison Co of New York, Inc.
 - 3-34, "Event Notification Info Worksheet "
 - nergency Preparedness & Engineering 1/05/26 Consolidated Edison Co of New 185 24% Fichs 50-000, 83/05/26, 8305110460
 - -35, "Fuel Movement H/Control Rods st encl. mergency Preparedness & Engineering 3/05/31. Consolidated Edison Co of New 208. P4X [iche-50-000, 83/05/31, 8205110461.

- 8306140483 Ack receipt of 830602 itr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-400/83 07
 VERRELLI.D M Division of Project & Resident Programs 83/06/02
 VTLEY.E F Carolina Power & Light Ca ip 18833 116 24X
 Fiche 50-400,83/06/02.8306J40483
- --8306140495 Forwards corrected Page 3 to 1E Insp Repts 50-400/83-07 & 50-401/83 07 submitted w/830412 ltr
 LEWIS,R C Division of Project & Resident Programs 83/04/18
 UTLEY,C E Carolina Power & Light Co 2pp 18833 121 24X
 Fiche 50-400.83/04/02.8306140483
- --8306140499 Corrected Page 3 to IE Insp Repts 50~400/83-07 & \$0-401/83 07 * Division of Engineering & Radiological Safety Programs 83/04/18 ip 18833 122 24X Fichs 50-400.83/06/02,8306140483
- --8304140503 Forwards IE Insp Repts 50-400/83-07 & 50-401/83 07 on 830308-11 & notice of violation LEMIS.R C Division of Project & Resident Programs 83/04/12 UTLEY.E E Carolina Power & Light Co 2pp 18633 123 P4X Fiche 50-400.83/06/02.8304140483
- --8306140512 IE Insp Repts 50-400/83-07 & 50-401/83-07 on 830308-11 Nuncompliance noted documentation not available to confirm that math had been upgraded to meet Class I requirements MCFARLAND, C R. JACKSON, L H. Region 2, Office of Director UPRIGHT, C M. Division of Engineering & Radiological Safety Programs 83/04/08 12pp. 18833 126 24X Fiche 50-400, U9/06/02. 8306140483
- 8305110464 IE Info Notice 83-36, "Impact of Security Practices on Safe Operations " Svc list encl JORDAN.E L. Division of Emergency Preparadness & Engineering Response (Post 830103) 83/06/09, Consolidated Edison to of New York, Inc. 119pp 18830 280 24X Fiche 50-000.83/06/09.8305110464
- 8305110470 IE Info Notice 83-30. "Defective Heat Sink Adhesive & Seismically Induced Chatter in Relays Within Printed Circuit Cards " Syc list outl JORDAN, EL Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co of New York, Inc. 118pp 18920 225 24X Fiche 50-000,83/06/13.83051104/0
- 8306090010 IE Info Notice 83-37. "Transformer Failure Resulting From Degraded Internal Connection Cables " Svc list encl JORDAN, E. L. Division of Energency Properedness & Engineering Response (Post 830103) 83/06/12 Consolidated Edison Co of New York, Inc. 243pp 18921 001 24X Fiche 50-000.83/06/13.8306070010
- 8306290524 Approves issuance of GALP rept Notes improvement in safety-related activities, emergency preparedness & security & safeguards Weaknesses in GA program will be monitored O'REILLY, J.P. Region 2, Office of Director 83/06/14 UTLEY, F.C. Carolina Power & Light Co. 5pp. 24X Fiche 50-000,83/06/14, R306290524
- ~~8306270531 Forwards SALP Repts 50-325/83-07,50-324/83-07,50-261/83-07,50-400/83-10 & 50-401/83-10 for Jan 1782 Jan 1783 Evaluation will be discussed in Raleigh, NC on 830510 LEWIS.R C Division of Project & Resident Programs 83/05/03 UTLEY.E E Carolina Power & Light Co 2pp 24X Fiche: 50-000,83/06/14,8306270524
- --8306270537 9ALP rept for Jan 1982 Jan 1983 * Region 2, Office of Director 83/05/03 64pp 24X Fiche 50-000,83/06/14,8306290524
- --8306290553 Responds to 830503 SALP rept for Jan 1962 Jan 1963 Reduced NRC attention may be appropriate for Category I re fire protection NRC attention should be maintained at normal levels for emergency preparedness UTLEY.E E Carolina Power & Light Co 83/09/20 D'REILLY.J P Region 2, Office of Directo: 16pp 24X Fiche 50-000.83/06/14.8306290524
- --8306290535 Forwards replacement Page 2 to Attachment 2 of 830520 ltr which commented on SALP rept EURY.L W Carolina Power & Light Co 83/05/27 O'REILLY, J P Region 2, Office of Director 2pp 24X Fiche 50-000,83/06/14, 8306290524
- B305110475 IE Info Notice 83-40. "Need to Environmentally Qualify
 Epoxy Grouts & Sealers " Gyc list enci
 JURDAN,E L. Division of Emergency Preparedness & Engineering
 Response (Post B30103) B3706/22 Consolidated Edison Co

- 8305110477 IE lufo Notice 83-41, "Actuation of fire Suppression Sys Causing Inoperability of Safety Related Equipment " Svr list
 - encl
 JORDAN E L Division of Lawrigancy Preparedness & Engineering
 Response (Post 830103) D3/06/22 Consolidated Edison Co. of New
 York, Inc. 120pp 18997 007 24X Fiche 50-000.83/06/22.830511047/
- 8305110479 IE Info Notice 83 42, "Reactor Mode Switch Malfunctions"
- B305110483 IE Info Notice B3-43. "Improper Settings of Intermediate Range (IR) Migh Flux Trip Setpoints " Svc list encl JORDAN, C. L. Division of Lmergency Proparedness & Engineering Response (Post B30103) B3706/24 Cuncildated Edison Co. of New York, Inc. 1169p 19046-297 24X Fiche 59-000, B3706/24, B305110483 York, Inc
- 5 Reportable occurrences, LCRs & related correspondence
- 830.6070231 Interim deficiency rept re main reactor trip breakers design discrepancy Initially reported on 830.427 Wostinghouse will replace undervoltage attachments, to accommodate new retaining ring Also reportable per Part 21 PARSONS, R & Carolina Power & Light Co. 83/05/26 O'REILLY, J.P. Region 2. Defice of Birector. App. 16746-105 24X Fiche 50-400, 83/05/26, 83060702 H
- 830±090046 Interim deficiency rept re failure to perform verification of anchor bolt math type when tags lost (Item 131) Initially reported on 830503 Evaluation of anchor bolts continuing Submittal of rept on reportability extended until 830805 PARSONS.R M Cavolina Power & Light Cu 83/06/01 O'REILLY, J P Region 2. Defice of Director 1p 18/93 287 24X Fiche 50-400, 03/06/01.8306090046
- 8306090180 Third interim deficiency rept re reactor protection sysfations fullowing secondary high energy line repture initially reported on 800707 Insulation of steam generator ref leg underway Also reportable per Part 21 PARSONS,R M Carolina Power & Light Co 83/06/01 O'REILLY, J P Region 2, Office of Director App 18/92 271 24X Fiche 50-400, 83/06/01, 8304090180
- 8306070171 Third interim deficiency rept re-potential damage to safety injection charging pump following sccondary side high energy line rupture (Item 38) initially reported on 800707 Resolution under review Also reportable per Part 21 PARSONS,R M Carolina Power & Light Co 83/06/01 0'REILLY,J P Regison 2, Office of Director App 18/76-086 24% Fiche 50-400,83/06/01.8306090191
- 830&100254 Second interim rept on Item 104 re defective walds on 480-volt switchgear supplied by Brown-Broveri Electric Co Initially reported on 830304 Major defects repaired Minor defects to be modeled in upcoming seismic test PARSONS,R M Carolina Power & Light Co 83/06/03 O'REILLY, J P Region 2. Office of Director App 1800/038 24X Fiche 50-400,03/06/03,8306100254
- B306200116 Addendum i to final deficiency rept.ltem 91,re we)dod studs on embedded strip plates Any testing performed by site receipt insp unit is in excess of code requirements since same procedure revealed problem PARSONS.R M Carolina Power & Light Co. B3/06/09 D'REJILY.J P. Region 2. Office of Director 2pp 18703 250 24X Fiche 50-400.83/06/09.8306200116
- 8306270223 Interim deficiency & Part 21 repts re boric acid transfer pumps. Hestinghouse Shop Order 205, Item 113 Initially reported on 830113 Suppart bolting will be replaced & gusset stiffener spot welds supplemented by 830701 PARSONS.R M Carolina Power & Light Co 83/06/14 0'REILLY. J P Region 2, Office of Director App 18970 227 24X Fiche 50-400, 03/06/14, 0306270223
- 6306280463 Interim deficiency rept re Item 121, welding deficiencies in main steam/feedwater support frames Initially reported on 830318 Extension requested until 830715 to submit complete evaluation Also reportable per Part 21 PARSONS,R M Carolina Power & Light Co 83/06/17 O'REILLY, J P Region 2, Office of Director ip 17018 294 24X Fithe 50-400, 03/06/17, 8306280463

- V Operator Examinations
- 8306140132 Requests approved ref mati re operator exams by 830425 Missing deadline will result in delay in administering exams Applications should be submitted at least 60 days prior to first exam scheduled for 830613 VERRELLID M Division of Project & Resident Programs 63/04/0 FURR.B J Carolina Power & Light Co 3pp 18839 086 24X Fiche 50-400.83/04/08.8306140132 83/04/08
- DOCKET 50-404 NORTH ANNA POWER STATION: UNIT 3
- A Application/construction stage documents & correspondence
- 8306300036 Withdraws 820708 application to extend CP SPENCER.W C Virginia Electric & Power Co 83/06/22 Office of Nuclear Reactor Regulation. Director NOVAK DENTON, H. R. Hffice of Nuclear Reactor Regulation, Director NOVAN, TEN Ifficensing Epp 19120 306 24X Fiche 80-404,83/06/22, 1304390014
- DOCKET 50-407 UNIV OF UTAH RESEARCH REACTOR
- F Security, medical, emergency & fire protection plans
- 9304140189 Forwards IE Insp Rept 50-407/83-01 on 830418-20 No noncompliance noted e noted Regian 4, Office of Director 83/05/11 JACDH9 of 2pp 18833 046 24% Fiche 50-407,83/05/11, SEIDLE,W C Re Utah, Univ of 8306140180 JACOBS.H R.
- ---8306140197 IE Insp Rept 50-407/83-01 on 830418-20 No noncompliance noted Major areas inspected licensee organization, operations & maint logs & operating procedures, internal review program, requalification program & emergency program MARPHY-M E , JOHNSON-W D Region 4, Office of Director 03/05/15pp 19833 048 24X Fiche 50-407.83/05/11.8306140188 03/05/11
- 8306160189 Releases public version of emergency plan FELTON, J M Division of Rules and Records 83/06/06 Docum Management Branch 1p 18873 095 24% Fiche 50-072.83/06/06. 8306160189 Document
- --B306160194 Public version of "Emergency Plan for Training & Research Reactors " M/030512 ltr SANDQUIST.6 M , BROPHY.J J Uteh, Univ of UTEC ME 82-100-82/11/01 Defice of Nuclear Reactor Regulation, Director 27pp. 18693 096 24X Fiche 50-072.83/06/06.8306160189
- G Inspection reports. IE Bulletins & correspondence
- 8306140188 Forwards IE Insp Rept 50-407/83-01 on 830418-20 No noncompliance noted

 8EIDLE W C Region 4. Dffice of Director 83/09/11 JACOBE

 Vtab. Univ of 2pp 18833 046 24% Fiche 50-407,83/05/11,

 8306140188 JACOBE, H R.
- --8306140197 IE Insp Rept 50-407/93-01 on 830418-20 No moncompliance 306140197 IE Insp Rept 50-407/83-01 on 830416-20 No moncomplinated Major areas inspected licensee organization, operations & maint logs & operating procedures, internal review program, requalification program & emergency program MURPHY, ME. JOHNSON, W.D. Region 4, Office of Director 63 pp. 16833 048 24% Fichs. 50-407,83/05/11,8306140188 03/05/11
- DOCKET 50-409 LA CROSSE BOILING WATER REACTOR F Becurity, medical, emergency & fire protection plans
- 8306210314 FDIA request for NRC records re security violations & Suagrounds events at nuclear facilities
 COLDENBERG.O Scripps-Howard Newspapers E3/04/22 FELTON, J M.
 Diffice af Administration 2pp 18725 178 24X
 Fichs 20-000,83/04/22,8305210314
- 830A21030A Partial response to FOIA request for NRC records re security violations & safeguards events at nuclear facilities Repts listed on App A available in PDR Search for add1 documents subj to request continuing FELTON.J M Division of Rules and Records 83/05/16 GOLDENBERG, Q. Scripps-Housed Newspapers 2pp 18925 176 24% Fiche 50-000.83/05/16.8306210306
- 8306070311 Forwards revised emergency plan in partial response to NRC 830324 request for changes & clarifications to make plan more workable & readable W/o ench.

 LINDER, F Dairyland Power Cooperative 83/06/01 HIND.J.A Division of Radiological & Materials Safety Programs Spp 18741 089 24% Fiche 50-409, 83/06/01, 8306070311.

- 8306070332 Forwards nev to emergency plan to bring plan in conformance w/IE Emergency Preparedness Insp Rept 50-409/82-15 findings W/o encl LINDER, F. Dairyland Power Cooperative 83/06/01 KEPPLER, J. G. Region 3, Office of Director 2pp 18741-155 24X Fiche 50-409,83/06/01.8306070332
- 8306160269 Releases public version of Issue 9 to emergency plan implementing procedure
 FECTON J M Division of Rules and Records 83/06/06 Docum
 Hanagement Branch ip 18872 151 24% Fiche 30-409,83/06/06. Document 830A1A02A9
- --8306160279 Public version of Issue 9 to Emergency Flan Implementing Procedure EFF-2, "Organization & Operations During Emergencies" #//830523 ltr
 LINDER, F Dairyland Power Cooperative 83/05/10 (RUTCHFIFLD.D Operating Reactors Branch 5 17pp 16872 192 24X Fiche 50-409.83/06/06,8306160269
- 8306130311 Ack receipt of 830520 ltr informing NRC of steps taken to correct violations noted in IE insp PAPERIELLO,C J Region 3, Office of Director 83/06/10 LINDER,F W Dairyland Power Cooperative Ip 18823 299 24X Fiche 50-409,83/06/10,8306130311
- --9305130314 Responds to NRC B30324 ltr re violations noted in IE insp Corrective actions Lock & Dam 8 will be removed as backup meteorological site & revised joint frequency distribution resulting from meteorological data submitted LINDER: F Dairyland Power Cooperative 83/05/20 HIND. J A Division of Radiological & Materials Safety Programs Spp 18823 300 24% Fiche 50-409,83/06/10.8306130311
- 8306210292 Forwards exemption from 100FR50. App E.Section IV F 1 full-JUSQUENCE Permands exemption from Intersol App Election IV F.1 full scale emergency preparedness exercise requirements in response to 830408 request Next full-scale exercise scheduled for May or June 1984 CRUYCHFIELD, D. Operating Reactors Branch 5 83/06/20 LINDER.F. Dairyland Power Cooperative 3pp 18915 139 24X Fiche 50-409,83/06/20.8306210292
- --8306210299 Exemption from IOCFR50, App E. Section IV F 1 full-scale SUDELUNITY Exemption From 10CFR50, App E. Section IV F 1 full-s smergency preparedness exercise requirements One-time delay of dampgency exercises will not significantly affect state of emergency preparedness EIEENHUT, D O Division of Licensing 83/06/20 Dairyla Cooperative App 18915 142 24X Fache 50-409,83/06/20, 8306210292 Dairyland Power
- 9 Adjudicatory correspondence
- 8306060325 Notice of ASLB reconstitution C Bechhoefer, chairman & OC Anderson & HC Paxton, members COTTER, B P Atomic Safety and Licensing Board Panel 83/06/03 2pp 18727 001. 24% Fiche 50-409/83/06/03.8306060325
- 8306070356 Order undertaking sum sponte review of ASLB 830421 initial decision. Initial decision not to be treated as final agency action pending further order SHOEMAKER.C. J. Atomic Basety and Licensing Appeal Panel 83/06/03 2pp 18742 123 24X Fiche 50-409.83/06/03.8306070356
- 8306300134 Notice of ABLAB reconstitution AS Rosenthal, chairman & JH Buck & TS Moore, members. SHOEMAKER, U Atomic Safety and Licensing Appeal Panel 63/06/27 ip 19122 316 24% Fiche 80-409, 63/06/27, 8306300134.
- O Advisory Committee on Reactor Safaguards reports & correspondence
- B306010199 Bummarizes ACRB 277th meeting on B30512-14 re BEP review of plant Defers review of full-term QL application until NRC completes action on remaining BEP topics, unresolved safety issues & YMI action items
 EBERBOLE, J C ACRS Advisory Committee on Reactor Safeguards
 B3/05/17 PALLADING, J Commissioners 3pp 18496 197 24X
 Fichs. 50-409.83/05/17.8304010199
- 8306150330 Advises that NRC will revise draft integrated plant SAR reflecting addl info provided by licensee responding to recommendations & comments by NRC consultants & incorporating licensee schedular commitments
 DIRCKS.W J Dffice of the Executive Director for Sporations
 B3/06/08. EUERSOLE.J C ACRS Advisory Committee on Reactor
 Bafeguards 3pp 18870 001 24X Fiche 50-409.83/06/08.8306150330

- P Operating license stage documents & correspondence
- B306070079 Forwards schedule for completion of full-term license SIP commitments contained in NURLG-0827 Three items resolved after issuance of draft NURLG-0827 listed LINDER-F Dairyland Power Cooperative B3/06/02 CRUTCHFIELD, D Operating Reactors Branch 5 lopp 18/198 206 24X Fiche 50-409, 83/06/02, 8306070077
- 8306100184 Forwards comments on draft NUREC-0827. "Integrated Plant Safety Assessment, SEP," to help improve rept accuracy LIMDER F Dairyland Power Cooperative 83/06/02 CRUTCHFIELD, p Operating Reactors Branch 5 5pp 13006 024 24X Fiche 50-409, 83/06/02, 8306100184
- 8306140707 Forwards addl info re NUREO-0737, Items II F 1 4, II F 1 5 & 106140707 Forwards add1 info re NUMEO-0737, Items 11 | 1 4,11 F | 5 II F i 6 Due to small reactor size & low population density, existing equipment adequate for safe operation LINDER: F Dairyland Power Cooperative B3706/03 CRUTCHE-JE(D,D Operating Reactors Branch 5 9pp 13041 279 247 Fiche 50-409,83/06/03,8306140707
- B306190277 Application for amend to Liceuse DPR-45 adding Sections 4/5 3 & 4/5 4. "Radioactive Effluents" & "Radiological Environ Monitoring." respectively, to Tech Specs LINDER, F. Dairyland Power Cooperative 83/06/08 CRUTCHI-IELD, D. Operating Reactors Branch 5 5pp 18949 207 24X Fiche 50-409, 83/06/08, 8306150277
- --B3061902B3 Proposed revs to Tech Specs, adding Sections 4/5 % & 4/5 %, "Radioactive Effluents" & Radiological Environ Monitoring," respectively, incorporating IOCTR50, App. 1, requirements # Dairyland Power Cooperative 83/06/08 51pp 18849 212 24% Fiche 50-409,83/06/08,8306150277
- 8306170478 Notification of 830/07 meeting w/util & NPS in La(1055e.H) to discuss seitmic open items addressed in SEP Topic III-6 SER III-6 SER CHENG.T N Systematic Evaluation Program Branch 83/06/10 RUSSELL.W T Systematic Evaluation Program Branch 3pp 24% Fiche 50-409.83/06/10.8306170478 18094 300
- 8306210066 Forwards addl info re SEP Topic III~6. "Seismic Design Consideration." providing addl detail on LACBUR & Genoa J stacks seismic capability LINDER,F Dairyland Power Cooperative 83/06/13 CRUTCHFIELB,D Operating Reactors Branch 5 2pp 19715 080 24X Fiche 50-409,83/06/13.8306210066
- --8304290092 Forwards calculations of effect of flue openings at base of Genda III chimney stack using ACI 30/-79 criteria
 FINNAN.C F Nuclear Energy Service: Inc 83/04/15 CMING.T
 Systematic Evaluation Program Branch 10pp 18915 082 24X
 Fiche 50-409,83/06/13.8306210066
- ~~8308210122 Forwards stress calculations for LACBWR stack uning AUGENIALE Forwards stress calculations for LACHUR stack uni ACI 307-79 working stress method, per 030327 tolcon Calculations performed at weakest node of Nuclear Energy Sycs stack model LANGE, O Dairyland Power Cooperative 83/04/05 CHENG, T Systematic Cyaluation Program Branch 6pp 18715 113 2 Fishe 50-409, 03/06/13, 8306/10066
- B306210132 Responds to R Dudley B30607 tolcon request for util commitment to incorporate procedures in Vol I of operations manual re instructions to obtain addl fuel for emergency svc water supply sys pumps LINDER.F Dairyland Power Cooperative 83/06/14 CRUTCHFIELD.D Operating Reactors Branch 5 2pp 18718 120 24X Fiche 50-409.83/06/14.8306210132
- B3062B0197 Forwards safety evaluation of util draign review of TMI Action litem II B 2 2. "Plant Shielding " Plant shielding adequate to assure post-accident access to vital areas GRUTCHFICLD, D. Operating Reactors Branch 5 B3/06/27 LINDER, F Dairyland Power Cooperative Spp. 19015 074 24X Fiche 50-409, 83/06/27, 8306280197
- O Inspection reports, IE Bulletins & correspondence
- B305110458 IE Info Natice 83-30, "Ruptured Am-241 Sources Contained in Well Logging Davice " Svc list encl TAYLOR, J M Division of Safeguards & Inspection Programs (Post B30103) B3/05/24 Consolidated Edison Co ad New York, Inc 125pp 18831 043 24X Fithe 50-000, B3/05/24, B30511045B
- 8305110460 IE Info Notice 83-34, "Event Notification Info Worksheet " 305110460 IE INPA NOTICE BU-MA, "EXPEC NOTIFICATION INTO MONABLEY Byc list encl JORDAN E L Division of Emergency Preparedness & Engineering Response (Past 830103) 83/05/26 Consolidated Edison Co of New York, Inc. 115pp 18732-085 24X Fiche 50-000,83/05/26,8305110460

- B305110461 IE Info Notice B3-35, "Fuel Movement W/Control Rode Hithdraum at BWRs " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 8 30103) B3/05/31 Consolidated Edison Co of New York, Inc. 114pp 18732 208 24X Fiche 50-000.83/05/31.8305110461
- 830A078332 Forwards rev to emergency plan to bring plan in conformance w/IE Emergency Preparedness Insp Rept 50-409/82-15 findings
- N/o enci LINDER.F Dairyland Power Cooperative 83/06/01 Region 3. Office of Director 2pp 18741 155 2-Fiche 50-409, 83/06/01, 8306070332 KEPPLER, J G DAY
- 6306070094 Confirms B30609 meeting to discuss regulatory improvement program Meeting will provide NRC w/status & effectiveness of program XEPPLER. J Q Region 3, Office of Director 83/06/02 LINDER, F W Dairyland Power Cooperative 1p 18739 207 24X Fiche 50-409, B3/06/02, B306070094

- 8306100145 Confirms 830609 onsite enforcement conference to discuss discovery of containment bldg pressure transmitter capped sensing line NDRELIUS, C E Division of Project & Resident Programs 83/06/07 LINDEN, F W Dairyland Power Cooperative ip 1800: 211 24X fiche 50-409,83/06/07.8306100145
- 8306230411 Forwards IE Insp Rept 50-409/83-06 on 830509 No noncompliance noted LITTLE, N S Region 3, Office of Director 83/06/08 L. Dairyland Power Cooperative 2pp 18941 154 24% Fiche 50-409,83/06/08.8306230411 B3/06/0B LINDER, F W
- --8305230420 IE Inap Rept 50-409/83-04 on 830509 No noncompliance noted Major areas inspected licensee action re IE Bulletin 80-11, "Masonry Wall Design"
 NORTON-J F. WILLIAMS, C.C. Region 3, Office of Director 83/06/08 3pp 18941 156 24X Fiche 50-409,83/06/08,8306230411
- 9305110464 IE Info Notice 83-36, "Impact of Security Practices on Bafe
- Operations " Svc list encl
 Operations " Svc list encl
 JORDAN.E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/06/09 Consolidated Edison Co of New
 York, Inc. 119pp 18830-280 24X Fiche 50-000.83/06/09.8305110464
- 8306130311 Ack receipt of 830520 Itr informing NRC of steps taken to correct violations noted in IE insp PAPERIELLO,C J Region 3. Office of Director 83/06/10 LINDER,F W Dairyland Pawer Cooperative Ip 188P3 299 24X Fiche 50-409.83/06/10.8306130311
- --8306130314 Responds to NRC B30324 ltr re violations noted in 15 insp Corrective actions Lock & Dam B will be removed as backup meteorological site & revised joint frequency distribution resulting from meteorological data submitted £INDER.F Dairyland Power Cooperative B3705780 HIND, J A Division of Radiological & Materials Bafety Programs 3pp 18823 300 24% Fiche 50-409,83706/10,8306130311
- 3305110470 IE Info Notice 83-38, "Defective Heat Bink Adhesive & Seismically Induced Chatter in Relays Within Printed Circuit Cards " Syc list and JORDAN,E L Division of Emergency Proparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co of New York, Inc. 118pp 18920 225 24% Fiche 50-000,83/06/13.8305110470
- 3306070010 IE Info Notice B3-37, "Transformer Failure Resulting From Degraded Internal Connection Cables" Svc list encl.
 JORDAN, E. L. Division of Emergancy Preparedness & Engineering Response (Post 830103) B3704/13 Consolidated Edison Co of New York. Inc. 243pp 18921 001 24X Fiche 50-000,83/04/13,8306070010
- 306300226 Forwards IE Insp Rept 50-409/83-07 on 830516-18 No
- noncompliance noted

 PAPERIELLO:C J. Region 3, Office of Director 83/06/14

 LINDER: W. Dairyland Power Cooperative 2pp. 19119 173 24X

 Fiche 30-407,83/06/14:8306300226
- -8306300231 IE Insp Rept 50-409/83-07 on 830516-18 No noncompliance nated Major areas inspected status of post-TMI requirements
 - requirements PAUL,R A., QREGER,L R. Region 3, Office of Director B3/06/J4 5pp 19119 175 24% Fichs 50-409,83/06/14,8306300226
- 3306270382 Responds to IE Bujletin 83-05, "ASME Nuclear Code Pumps & Spare Parts Mfg by Hayward Tyler Pump Co " Subj pumps not in use or planned for use at facility LINDER.F Dairyland Power Cooperative 83/06/16 KEPPLER.J O Region 3. Office of Director 2pp 18794 152, 24X Fichs 50-409,83/06/16.8306270382

- 8306270381 Forwards IE Insp Rept 50-409/83-05 on 830301-0515 & notice BHAFER: W D Region 3: Office of Director 83/06/17
 Dairyland Power Cooperative 2pp 18993 241 24X
 Fiche 50-409.83/06/17:8306270381 83/06/17 LINDER: F W
- --8306270385 Notice of violation from insp on 830301-0515 8HAFER, W D Region 3. Office of Director 83/06/17 18993 243 24% Fiche 50-409.83/06/17.8306270381
- --8306270387 IE Insp Rept 50-409/83-05 on B30301-0515 Noncompliance noted emergency core spray pump IB failed to operate when challenged due to improper maint BRANCHIM U. DUDRY.N E. JACKIW.I N Region 3. Office of Director 83/06/17 8pp 18793 244 24X Fiche 50-409,83/06/17.8306270381
- 8305110475 IE Info Notice 83-40, "Need to Environmentally Qualify
 Epoxy Grouts & Sealers " Svc list enc!
 JORDAN, C L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/06/22 Consolidated Edison Co of New
 York, Inc 115pp 19021 179 24X Fiche 50-000,83/06/22,8305110475
- 8305110477 IE Info Notice 83-41, "Actuation of Fire Suppression Sys Causing Inoperability of Safety-Related Equipment," Svc list
 - ORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/22 Consolidated Edison Co. of New York, Inc. 120pp 18797 007 24X Fiche 50~000.83/06/22.8305110477
- 8305110479 IE Info Notice 83-42. "Reactor Mode Switch Mælfunctions " 3051104/Y LE ANGUERON CONTROL TO THE REPORT OF THE PROPERTY PROPERTY BY THE PR
- 8305110483 IE Info Notice 83-42, "Improper Bettings of Intermediate Range (IR) High Flux Trip Setpoints " Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/24 Consolidated Edison Co. of New York, Inc. 116pp 17046 277 24X Fiche 50-000,83/06/24,8305110483
- R Periodic operating reports & related correspondence
- 8304020291 Monthly operating rept for Mar 1983 W/83040B ltr 0000MAN.L S , LINDER, F Dairyland Power Cooperative 83. 9pp 18490-332 24X Fiche 50-409, 83/04/04.8304020291 B3/04/04
- 830&1&0378 Monthly operating rept for Apr 1983 W/830509 ltr ODDDMAN,L S., LINDER: F. Dairyland Power Cooperative. 83/ Office of Resource Management, Director 8pp 18859 345 Fishe 50-409, 83/05/04.8306160378 B3/05/04
- B Reportable occurrences, LERs & related correspondence
- 8306070040 RD 83-03 on 830827, one of two redundant containment bldg pressure sensing lines found capped Line capped on 830818 during verification of restoration following leakage tests Cap removed Followup rept will be submitted LINDER, F. Dairyland Power Cooperative 83/05/31 KEPPLER, J. O. Region J. Office of Director in 187.39 360 24X Fiche 50-409,83/05/31.8306070040.
- 8306170376 LER 83-003/017-0 on 830527, two containment \$10g pressure 306170376 LER 83-003/017-0 on B30527, two containment big gress sansing lines found capped Caused by personnel error. Cap removed Broken identification tag replaced. Line modified to prevent future capping H/830607 ltr G00DMAN.L B. LINDER, F. Dairyland Power Cooperative B3/06/0 KEPPLER.J O Region 3. Office of Director 4pp 18880.226 Fiche 50~409,83/06/09,8306170376 83/06/09
- 8306270337 LER 83-002/03L-0 on 830520, during leakage rate testing, electrical penetration unit 5 leakage found above Tech Spec limit Caused by cracked gland on individual penetration 283. Assembly replaced W/830616 ltr GODDMAN, L S . LINDER, F Dairyland Power Cooperative 83/06/16 KEPPLER, J G Region 3. Office of Director App 18793 121. 24X Fiche. 50-407, 83/06/16, 8306270337.
- 8306300006 Forwards Special Rept 83-01 re sampling analysis results k add1 info conterning occasions when reactor thermal power changed by more than 15% within 1 h while in Operational Condition 1 or 2 Constitut 1 of R LINDER, F Dairyland Power Cooperative 83/06/22 Kl Region 3, Office of Director, 12pp 19120 321 24X Fiche 50-409, 83/06/22, 8306300006

- DOCKET 50-410 NINE HILE POINT NUCLEAR STATION, UNIT 2
- A Application/construction stage documents & correspondence
- 8304010027 Notification of 830523 significant licensee meeting w/util in Xing of Prussia,PA to discuss current const problems LAZARUS.W J Region 1. Office of Director 83/05/19 Region 1. Office of Director 1p 18687 177 24X Fiche 50-410.83/05/19. 8304010027
- 8306090205 Notification of 830607 meeting w/otils & 88W in Cherry Hill, NJ to discuss GDC 51 compliance (fracture prevention of containment pressure boundary) HAUOHEY,M , WEINKAM,E Licensing Branch 2 83/06/02 NOVAK,T M Assistant Director for Licensing 4pp 18809 225 24X Fiche 50-000,83/06/02,8306090205
- 8304080273 Forwards repts re aquatic ecology of facility & "Nine Mile Point Aquatic Ecology Summary (1973-81)," in response to NRC Acceptance Review Requests E291 6(a) & E291 11(b) Bibliography of publications encl MANGAN, C V Niagara Mohawk Power Corp 83/06/06 EJSENHUT, D 9 Division of Licensing 3pp 18769 025 24X Fiche 50-410,83/06/06,8306080273
- --8306080274 "Nine Mile Point Aquatic Ecology Summary (1973-81) "

 * Lawler, Matusky & Skelly Engineers 83/05/31 258pp
 18769 028 24X Fiche 50-410,83/06/06,8306080273
- --B3060B0274 "Submerged Multiport Diffusor Thermal Discharges From Conceptual Design to Post-Operational Survey," presented at Proceedings of Conference on Waste Heat Mgt & Utilization on 770509-11. Hiami Beach. FL
 TBAI, Y J . BURRIS. B E Stone & Webster Engineering Corp 77/05/09 22pp 18769 341 24% Fiche 50-410, 83/06/06, 8304080273
- --8306080298 "Fish Return Sys." presented at Proceedings of 25th Annual Hydraulics Div Specialty Conference, ASCE at Texas A&M University, College Station, TX. Aug 1977 HUBBALLI.Y 9 . TAFT.E P. Stone & Nebster Engineering Corp 77/08/31 9pp 18770 001 24X Fiche 50-410,83/06/06,8306080273
- --8304080303 "Designing Offshore Intakes for Fish Protoction," presented at ASCE Natl Convention, Atlanta, CA in Oct 1979 MUSBALLI, Y G , TAFT, E P Stone & Webster Engineering Corp LARSEN, J Alden Research Laboratory 79/10/31 21pp 18770 010 24X Fiche 50-410.83/06/06.8306080273
- --8304080306 "Influence of Fish Protection Considerations on Design of Cooling Water Intakes." presented at Joint Intl Symposium on Design & Operation of Fluid Machinery at CO State Univ. Fort Collins.CO on 700612-14 MUSSALLIFY, Q., HOFMANN.P., TAFT.E.P. Stone & Webster Engineering Corp. 78/06/12 12pp 18770 031 24X Fiche 50-410,83/06/06, 83/06/062
- --8306080312 "Developing Adequate Hydrothermal Monitoring Program," presented at AIF Topical Conference on Water Quality Considerations for Siting & Operating Nuclear Power Plants on 721001-04 in Washington.DC BRODFELD.B Stone & Webster Engineering Corp 72/10/01 29pp. 18770 043 24X Fiche 50-410.03/04/05.8306080273
- --8306080328 "Engineering Implications of New Fish Screening Concepts." presented at Proceedings of Fourth Natl Workshop on Entreinment & Impingement on 771205-07 in Chicago IL MUSSALLI, Y Q . TAFT, E P., HOFNANN, P Stone & Webster Engineering Corp 77/12/05 16pp 18770 115 24X Fiche 50-410,83706/06, 8306080273
- --830608033B "Environ Engineering Studies for Thermal Discharges at Coastal Bites." presented at 1972 Joint Power Generation Conference on 72091i in Boston. MA MATCHETT, D. 1, TBAI.Y J. Stone & Webster Engineering Corp 72/09/11 34pp 18770 140 24X Fichs 50-410.83/06/06.8306080273
- --B3060B0343 "Lab Evaluation of Larval Fish Impingement & Diversion Bys," presented at Proceedings of Workshop of Advanced Intake Technology on B10422-24 in San Diego, CA TAFTE P, BERGEN, R H, LARSEN, J Stone & Webster Engineering Corp. B10404/22 22pp. 18770 174 24X Fiche 50-410.83/06/06, B304080273.
- --8304080351 "Experimental Approach to Design of Bys for Alleviating Fish Impingement at Existing & Proposed Power Plant Intake Structures," presented at Third Natl Workshop on Entrainment & Impingement in New York City, NY in Feb 1976
 TAFT, E P. HOFMANN, P. EISELE, P. J. Stone & Webster Engineering Corp. 76/02/29 13pp 18770 196 24X Fiche 50-410,83/06/06,8306080273

- --8306080360 "Biological Engineering Investigation of Angled Flush Fish Diversion Screens:" presented at 25th Annual Hydraulics Div Speciality Conference, ASCC at (exas A&M Univ. College Station, TX on 770810-12 TAFT.E P , MUSSALLI, V 0 Stone & Webster Engineering Corp 77708/10 10pp 18770 209 247 Fiche 50-410,83706/06,8306080273
- 8306140440 Responds to 830327 request for add1 info re application for OL Info addresses Encls 1-15 re distribution list for anytheon rept & FOAR, safety-related structure sys & components controlled by GA program MANOAN, C V Niagara Mohawk Power Corp 83/06/10 EISENHUT, D Q Division of Licensing 3pp 18838 029 24% Fiche 50-410,03/06/10,8306140440
- 8306280276 Advises that applicant proposed [ech Specs do not represent SRP difference since current generic STS used as bases MIRAGLIA,F J Assistant Director for Gaftty Assessment GA/06/21 NOVAK,T M Assistant Director for Licensing Ip P4X Fiche 50-410,83/06/21,8306280296
- C Utility Environmental Report (ER), amends & correspondence
- 8306220074 Forwards Suppl 2 to environ rept OL stage MANGAN, C V Niagara Mohawk Power Corp 83/06/06 EISENHUT, D 9 Division of Licensing ip 18932 275 24% Fithe 50-410,83/06/06,8306220076
- --8306220107 Suppl 2 to environ rept GL stage * Niagara Mohawk Power Corp 83/06/30 238pp 18933 321 24x Fiche 50-410,83/06/06,8306220096
- 8306200258 Forwards Affidavit of Svc indicating that Amend 3 & Suppl 2 to FBAR & environ rept OL stage have been provided to appropriate parties as requested in NRC 830329 ltr MANGAN, C V Niagara Mohawk Power Corp 83/06/14 EISENHUT, D @ Division of Licensing 2pp 18901 177 24X Fiche 50-410,83/06/14.8306200258
- F Security, medical, emergency & fire protection plans
- 8306130303 Forwards response to 830329 questions re physical security plan Response withheld (ref 1000R73 21)
 SURNER, J J Niagara Mohawk Fower Corp 83/06/08 CISENHUL, D Q
 Bivision of Licensing ip 18803 330 24X Fiche 50-410.03/06/08.
- G Adjudicatory correspondence
- 8306220123 Petition by New York State Energy Dfc to participate as interested State Certificate of Svc encl KLIMBERG. B in New York, State of, Energy Office 63/06/07 Commissioners 3pp 18926 100 24X Fiche 80-410.63/06/07, 8306220123
- B306160575 Forwards Multiple Intervenors petition to intervene WHITE.A F DeGraff. Foy. Commay & Holt-Harris B3/06/10 Docketing & Services Branch Ip 18365 206 24X Fiche 50-410,83/06/10.8306160575
- --8304160582 Petition to intervene & request for hearing Licensing decision will directly affect reliable supply & price of energy to member facilities Affidavit of Svc encl WHITE.A F Affiliation Unknown WHITE.A F DeGraff, Fay. Corway & Holt-Harris 83/06/10 Commissioners App 18866 207 24% Fiche 50-410,83/06/10,830616075
- 830A220070 Notice of ASLB constitution MB Margulies chairman & EE Hill & PW Purdom members COTTER. II P. Atomic Safety and Licensing Board Panel 93/06/1/ 2pp 18930 170. 24% Fiche 50~410.83/06/17.8304220070
- 8306270294 Answer to New York Btate Energy Ofc 830607 patition to participate as interested state Applicants raise objection to request if hearing held Notices of appearance & Gertificate of Syc encl GONNER. TB Niagara Mohawk Power Corp GONNER, TB Conner & Wetterhahn 83/06/22 Atomic Safety and Licensing Board Panel. Spp 18996 185 24% Fiche 50-410,83/06/22,8306270274
- 8306240273 Reponse supporting Naw York State Energy Ofc 83060/
 petition for leave to participate as interested state if
 hearing held as result of contested issue Certificate of Svc
 enc!
 BORDENICK, B. M. Hearing Bronch 3 83/06/23. Atomic Safuty and
 Licensing Board Panel 4pp 18980 094 24X Fiche 50-410.83/06/23.
 8306240273

- 830624027B Response opposing Multiple Intervenors 830610 petition for leave to intervene in OL proceeding Requisite interest & standing not exhabitshed Specific aspects to be litigated not identified Certificate of Svc end BORDENICK.B M Hearing Branch 3 D3706/23 Atomic Safety and Licensing Board Panel 12pp 18979 277 24X Fiche 50-410.83706/23.8306240278
- 8306240395 Notices of appearance in proceeding Certificate of Svc encl BORDENICK, B. M., PERLIS, R. G., Hearing Branch 3 83/06/23 3pp 18980-131 24X Fiche 50-410, B3/06/23, 8306240355
- 8306280550 Response re Multiple Intervenors 830610 petition for leave to intervene Multiple Intervenois counsel withdrawal of petition to intervene demonstrates that no basis exists for hearing Certificate of Svc encl CONNER, T B Niagara Mohawk Power Corp 83/06/23 Commissioners 2pp 17017 305 24X Fiche 50-410-83/06/23,8306280550
- K. Utility Final Safety Analysis Report (FSAR) & amends
- 8306220096 Forwards Amend 3 to ISAR & Suppl 2 to environ rept Ol stage (filed in PDR Category C) HANGAN,C V Niagara Mohawk Power Corp 83/06/06 EISENHUT.D Q Division of Licensing ip 18932 275 24X Ficho 50-410,83/06/06, 8306220096
- --8306220104 Amend 3 to FBAR
 # Niagara Mohawk Power Corp 83/06/30 405pp 18932 276 24X
 Fiche 50-410,83/06/06,8306220096
- B306200298 Forwards Affidavit of Ovc indicating that Amend 3 & Suppl ? to ESAR & environ rept UL stage have been provided to appropriate paities as requested in NRC 820329 18; HANGAN, C V Niagara Mohawk Power Coip 83/06/14 LIGENHUT, D Q Division of Lirensing 2pp 18701 1// 24X Fiche 50-410, 83/06/14, 8306200298
- O Inspection reports. IE Bulletins & correspondence
- 8306220149 Discusses IE insp on 820830-0750 & forwards notice of violation & proposed imposition of civil penalty ALANJ M Region i. Office of Director 83/04/26 RHODE, G K Niagara Mohawk Power Corp 3pp 1893/342 24X Fichs 50-410,83/04/26.8306220149
- ---830A220154 Notice of Violation & proposed imposition of cavil penalty in amount of \$100.000 Noncompliance noted improper implementation of GA program by S&H.principal contractor for util. & falsification of GC records
 ALLAN.J M Region 1. Office of Director 89/04/26 Spp 18937 345 24X Fiche 50-410.83/04/26.8306220149
- 8306210200 Responds to IE Bulletin 82-04 re deficient Bunker Ramo Coprimary containment electrical penetration assemblies as Assemblies not used at facility HANNO.8 F Niagara Mohawk Power Corp 83/05/25 ALLAN.J M Regio 1. Office of Director 2pp 18718 130 24X Fiche 50-410.83/05/25, 8306210200
- B305110460 IE Info Notice 83-34. "Event Notification Info Worksheet "
 Svc list enc!
 JORDAN, E L. Division of Emergency Proparedness & Engineering
 Response (Post 830103) 83/05/26 Consolidated Edison Co of New
 York, Inc. 115pp 18732 085 24X Fiche 50-000,83/05/26,8305110460
- 8305110461 IE Info Notice 83-35. "Fue] Movement W/Control Rods Withdrawn at BWRs " Ovc list encl UDBDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/31 Consolidated Edison Co of New York, Inc 114pp 18792 208 24x Fiche 50-000,83/05/31,8305110461
- B306140441 Ack receipt of B30406 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-410/83-01
 BTAROSTECKI.R Division of Project & Resident Programs B100E.G K Niagara Mohauk Power Corp 1p 1883B 025 24X
 Fiche 50-410-83/05/31-8306140441
- --8306140445 Responds to NRC 830228 ltr re violations noted in IE Insp. Rept 50-419/83-01 Corrective actions foremon trained in importance of making walding procedures available to welder & procedures available at weld rod issue stations MANOAN: C. V. Niagara Mohawk Power Corp. 83/04/06 STAROBTECKI.R. Division of Project & Resident Programs. 3pp. 18938-026 24X Fiche 50-410,83/05/31.8306140441
- B306140554 Ack receipt of B30525 ltr informing NRC of steps taken to correct violations noted in IC Insp Rept 50-410/82-14
 BTARDSTECKI: R Division of Project & Resident Programs
 RHODE: Q K Niagara Mehawk Power Corp ip 18834 208 24X
 Fiche 50-410:83/06/02:8306140554

- ~-8306140558 Provides add1 response to 1E Insp Rept 50-410/82-14,8MW field GC performing in-process insp of bulting crews to assure compliance w/installation section of RCRBB, spec MANND, 8 F Niegars Mohawk Power Corp 83/05/25 STAROSTECKI,R. Division of Project & Resident Programs is 18834 209 RAX Ficha 50-410.63/06/02.8306140554
- --B306i40564 Recponds to NRC B30ii0 itr re violations noted in IE Insp Rept 50-4i0/82-i4 Corrective actions S&W will perform additorque tests on 200 bolts installed by each contractor involved in sefety-related high strength bolting MANNO.8 F. DISE.D P. Nagara Mohauk Power Corp. B3/03/09 STARGSTECKI.R. Division of Project & Resident Programs. 7pp 18834 210 24X Fiche 50-410,83/06/02.8306i40554.
- 8305i10464 IE Info Notice 83-36. "Impact of Security Practices on Bafe Operations " Svc list ent! JORDAN,E L Division of Emergency Preparedness & Engineering Response (Fost 830103) 83/06/09 Consolidated Edison Co of New York, Inc 119pp 18830 280 P4X Fiche 50-000,83/06/09.8305110464,
- 8305110470 IE Info Notice 83-38, "Defective Heat Bink Adhesive & Seismically Induced Chatter in Relays Within Printed Circuit Cards " Syc list ench JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co. of New York, Inc. 118pp 18920-225 24X Fiche 50-000, 83/06/13,8305110470
- B306090010 IE Info Notice 83-37, "Transformer Failure Resulting From Degraded Internal Connection Cables" Byc list enc)
 JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post B30103) B3/06/13 Consolidated Edison Co. of New York, Inc. 243pp 18921-001 24X Fiche 50-000,83/06/13,8306090010
- B305110475 IE Info Notice 83-40. "Need to Environmentally Guality
 Epoxy Grouts & Sealers " Svc list enc!
 JORDAN.E L. Division of Emergency Preparedness & Engineering
 Response (Post B30103) 63/06/22 Consolidated Edison Co. of New
 York. Inc. 115pp 19021:179 24X Fiche 50-000.83/06/22.8305110475
- 8305110477 IE Info Notice 83-41, "Actuation of Fire Suppression Sys Causing Inoperability of Safety-Related Equipment" Syc list enci JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83706/22 Consolidated Edison Co of New York Inc 120pp 18997 007 24% Fiche-50-000,83/06/22,8305110477
- 8305110479 IE Info Notice 83-42, "Reactor Mode Bwitch Malfunctions "
 Bvc list encl
 JORDAN,E.L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/06/23 Consolidated Edison Co. of New
 York, Inc 116pp. 18796-242 24X Fiche: 50-000, 83/06/23, 8305110479.
- B306270122 Requests extension of time until & including B30705, to complete response to B30426 notice of violation & proposed imposition of civil penalty Addl time necessary to review & edit final response & to coordinate review WS&P.

 WETTERHAHN.H J Gonner & Hetterhahn HETTERHAHN.H J Niagara Hobawk Power Corp B3706/23 DEYOUNG.R Director's Office, Office of Inspection and Enforcement 2pp 18988 018. 24X Fiche 50-410.83/06/23.8306270122
- 8305110483 IE Info Notice 83-43, "Improper Bettings of Intermediate Range (IR) High Flux Trip Satpoints " Svc list encl JORDÁN E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/24 Consolidated Edison Co. of New York, Inc 116pp 19046 297 24X Fiche 50-000,83/06/24,8305110483.
- 8305110458 IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in Well Logging Device " Syc list encl. TAYLOR.J.H Division of Bafeguards & Inspection Programs (Post 830103). 83/05/26, Consolidated Edison Co. of New York, Inc. 125pp 18831 043 24X Fiche 50-000.83/05/26.8305110458
- R Periodic operating reports & related correspondence
- 8306080273 Forwards repts re equatic scology of facility & "Nins Mile Point Aquatic Ecology Summary (1973-81)." in response to NRC Acceptance Review Requests E291 6(a) & E291 11(b). Bibliography of publications encl MANDAN. C V Ningara Mohawk Power Corp 83/06/06. EISENHUT, D O Division of Licensing Spp 18769-025 24X Fichs 50-410,83/06/06,8306080273
- --8306080274 "Nine Mile Point Aquatic Ecology Summary (1973-81),"
 * Lawler, Metusky & Skelly Engineers 63/05/31, 258pp
 18769; 028 24X Fiche 50-410, 63/06/06, 8306080273

- 8 Reportable occurrences, LERs & related correspondence
- 8304010453 Final deficiency rept re undersized Power Generation control complex floor module welds Initially reported on 830207 Helds inspected & accepted Procedure revised to require weld leg length verification using fillet weld gauge HANNO.5 F Niagara Hohauk Power Corp 83/05/20 STAROSTECKI.R Officion of Project & Resident Programs 3pp. 18674.315 24x Fichs 50-410,83/05/20.8306010453
- 8306200262 Interim deficiency rept re nonconformance of pipe fittings mfg by Tube-Line Corp Intially reported on 830422 Final rept expected by 830919 MANNO.9 F. Niagara Mohawk Power Corp 83/05/25 STAROSTECKI.R Division of Project & Resident Programs 2pp 18901 105 24X Fiche 50-410,83/05/25.8306200262
- 8306210195 Interim deficiency rept re failure of main steam safety relief valve actuator during environ qualification testing Initially reported on 830505 Farlure due to seals in actuator assembly Investigation ongoing MANNO.8 F Niagara Mohawk Power Corp 83/06/01 STAROSTECKI.R. Division of Project & Resident Programs 2pp 18914 158 24X Fiche 50-410,83/06/01.8306210195
- 8304280605 Final deficiency rapt re faulty Clow Corp valves used in svc water. LPCS & RHR sys. Initially reported on 820923 Valves returned to manufacturer for heat treatment rework. Completion espected by 830831 MANNO. 8 F Niagara Mohawk Power Corp 83/06/02 STAROSTECKI, R Division of Project & Resident Programs 2pp 19016 021 24X Fiche. 50-410. 83/06/02. 8306280405
- 8306210182 Final deficiency rept re QA inspector certification Initially reported on 830429 Qualification/certification records reviewed & found complete Deficiency not reportable per IOCFRSO 55(e)
 DISE, D. P. Miagana Mohawi Power Corp. 83/06/03 STAROSTECKI, R. Division of Project & Resident Programs. 2pp. 18915.254 24X Fiche 50-410.63/06/03.6306210182
- 8304280597 Final deficiency rept re weld radiograph indications on Associated Piping & Engineering Corp recirculation piping appool piece Initially reported on 830113 Discontinuity accepted or establishment of the Property of the Property of the Property of Property of Property of Project & Resident Programs 2pp, 17018 195 24X Fiche 50-410,83/06/13,8306280597
- 8306280255 Final deficiency rept re failure to obtain ambient temp for HPCB diesel generator equipment qualification documentation. Initially reported on 820805 GE provided operating experience info to support qualification.

 DISE: 0 P Niagara Mohawk Fower Corp 83/06/20, STARDSTECKI.R Division of Project & Resident Programs 3pp 19015 022 24% Fiche: 50-440,83/06/20,8306280255

V. Operator Examinations

- 8306140322 Requests attendance at 830627 meeting in King of Prussia, PA to discuss transfer of reactor operator licensing function from Bethevda MD to Region I ofc STAROBTECKI, R Division of Project & Resident Programs 83/06/09 RHODE. 0. K. Niegara Mohawk Power Corp. 2pp 18832 210 24X Fiche: 50-410,83/06/09.8306140392.
- DOCKET 50-412 BEAVER VALLEY POWER STATION, UNIT 2
- A Application/construction stage documents & correspondence
- B304020013 Requests mgt meeting on 830407 to discuss licensing review of OL application. List of info to be highlighted included KNIQHTON, 0 W. Licensing Branch 3 83/05/13 HODLEVER, E J Duquesne Light Co. 3pp. 18702 344 24X Fiche 50-412,83/05/13,8306020013
- 8306020491 Notification of 830523 meeting w/util in Bethesda, MD to discuss fracture toughness of matls in containment pressure boundary LAZO, L. Licensing Branch 3 89/05/16 KNIGHTON, C W Licensing Branch 3 3pp. 18715, 197 24X Fiche 50-412, 83/05/16, 8306020491.
- B306150149 Forwards FR notice of receipt of application for OL, notice of availability of environ rept & notice of opportunity for hearing.

 KNIOHTON, O W. Licensing Branch 3 B3/05/19 WODLEVER, E J Duquesne Light Co 3pp 18870 079 P4X Fiche 50-412,83/05/19,8306180149

- --8306150190 Notice of receipt of application for UL notice of availability of environ rept.notice of consideration of issuance of OL & notice of opportunity for hearing KNIGHTON, GW | Licensing Rainch 3 69/05/19 'Vpp 180/0 GRU 24X Fiche 50-41P,89/05/19,8906150149
- 8306030034 Notification of 830607 meeting w/util in Bethesda. Mb to discuss plans for review of DL application LAZO.L Licensing Branch 3 63/05/24 KNICHTON.C W Licensing Branch 3 3pp 18733 176 24K Fiche 50 412.83/05/24,8306030031
- C. Utility Environmental Report (ER), amends & correspondence
- 8306090401 Advises that general info, filed in environ rept DL stage & FSAR, sufficiently complete for docketing application & instinction of safety & environ reviews Projected fuel date is 851231

 EISENHUT, D G Division of Licensing 83/05/04 WOOLFVER, C. J Duquesne Light Co 67pp 18615 070 PAY Fiche 50-412,03/05/04, 8306090401
- 8306150149 Forwards FR notice of receipt of application for UL notice of availability of environ rept & notice of opportunity for hearing KNIOHTON G W Licensing Branch 3 83/05/19 WDULEVER.E J Duquesine Light Co 3pp 18870 079 24X Fiche 50-412.83/01/19.
- --8306150150 Notice of receipt of application for OL notice of availability of environ reptinctice of consideration of issuance of OL & notice of apportunity for hearing KN10HTON, G W. Licensing Bianch 11 83/05/17 9pp 18870 088 24X Fiche 50-41P,83/05/19,8304150149
- 8306140365 Comments on environ rept OL stage Calculations utilizing recent data, scheduled shutdowns in summertime only & rev to support conclusion for downstream phytoplanikton sites recommended KULP.C J Interior. Dept of, Fish & Wildlife Service 83/06/09 MCINTIRE.W Duquesne Light Cn 2pp 18802 141 24X Fiche 50-412,63766/09.8306140365
- G Inspection reports. IE Bulletins & correspondence
- 8305110458 IE Info Notice 83-32. "Ruptured Am-241 Sources Contained in Well Lagging Device" Svc list encl TAYLOR, J M Division of Gafeguards & Inspection fragrams (Post 830103) 83/03/26 Consolidated Edison Co of New York, Inc 125pp 18831 043 24X Fiche 50-000, G3/05/26, 8305110458
- 8305110440 IE Info Notice 83-34, "Event Notification Info Worksheet"
 Svc list encl
 JORDAN, E. L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/05/26 Consolidated Edison Co. of New
 York, Inc. 115pp 18732 085 24X Fiche 50-000, 83/05/26, 8305110460
- 8306060289 Ack receipt of 830504 ltr Confirms understanding that CP halder has sole reporting obligations per 10CFR50 55(e) Part 21 reporting requirements excused if util awnie NRC adequately informed of defect or failures ALLAN, J M Region I, Office of Director 83/05/26 WOOLEVER, F J Duquesne Light Co ip 18727 039 24X Fiche 50 412,83/05/26,8306060289
- --8306040293 Discusses role & responsibility of lOCFR50 55(e) reporting Westinghouse directed to rept all future potential significant deficiency findings for facility only to util & util util rept to NRC HQDLEVER, E.J. Duquesne Light Co. B3/09/04 ALLAN, J. Region 1, Office of Director. 3pp. 18729 040 24X Fiche 50-412,87/05/26,8304060289
- B305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods Withdrawn at DWRs " Svc list onci JORDAN,E | Division of Emergency Preparedness & Engineering Response (Fost B30103) 83/05/31 Consolidated Edison Co. of New York, Inc. 116pp 18732 208 24X Fiche 50-000,83/05/31,8305110461
- 8306150349 Ack receipt of 830520 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-412/83-04
 STARBSTECKI: R Division of Project & Resident Programs 83/06/03
 WOOLEVER.E J Dequesse Light Ca Ip 18847 147 24X
 Fiche 50-412,83/06/03.8306150349
- --8306150355 Responds to NRC 830408 ltr re violations noted in IE lines Rept 50~412/83~04 Corrective actions engineering analysis completed for piping sys presently welded to containment penetration upheld by support further down pipe WOOLEVER: E J Duquesne Light Co 83/05/20 STAROSTECKI.R Division of Project & Resident Programs 3pp 18847 148 P4X Fiche 50-412.83/06/03.8306150347

DOCKETED ITEMS

- 8306440658 Summarires 830215 meeting re SALP conducted on B30124 SALP rept evaluation covers Dec 1981 Nov 1982 Overall performance in constructing famility alreptable ALLAN, J H Region 1. Office of Director 83/06/08 WDDLEVER, E J Duguesne Light Co 2pp 18942 005 .4X Fiche 50-412.83/06/08.8305140658
- --8306140663 Forwards SALP rept for Dec 1781 Nov 1782 Site meeting scheduled for 830215 to discuss assessment List of meeting attendees encl STAROSTECKI.R Division of Project & Resident Programs 83/01/3 MODLEVER.E J Duquesne Light Co App 18842 007 24X Fiche 50-412,83/06/08,8306140658
- --830614066/ SALP rept for Dec 1781 Nov 1782 (Const Phase) Performance Categories II & III assigned * Region 1, Office of Director 83/01/24 31pp 18842 010 24X Fiche 50-412,83/06/08,8306140658
- --8306140672 Forwards response to 830131 ltm forwarding SALP for Dec 1981 - Nov 1982 conducted on 830124 Response covers four areas assessed as Category II & one area assessed as Category III MODLEVER, E. J. Duquesne Light Co. 83/03/08 STAROSTECKI, R Bivision of Project & Resident Programs 7pp 18842 043 24X Fiche 50-412,83/06/08.8306140658
- B305;10464 IE Info Notice B3-36. "Impact of Becurity Practices on Safe Operations " Svc list encl JORDAN,E L. Division of Emorgency Preparedness & Engineering Response (Post B30103) B3/06/09 Consolidated Edison Co. of New York Inc. 119pp 18830 280 24X Fiche 50-000.B3/06/09.B305110464
- 8306230415 Forwards IE Insp Rept 50-412/00-07 on 830502-01 & notice of violation STARDSTECKI, R Division of Project & Resident Programs B0706/10 MD0LEVER, E. J. Duquesno Light to 2pp 18940-190 P4X Fiche 50-412, 83706/10, 8306230415
- --8306230417 Notice of violation from insp on 830502-31
 Region 1. Office of Director 83/06/10 1p 18943-192 24X
 Fiche 50-412,83/06/10,8306270415
- --8306230424 IE. Insp. Rept. 50-412/83-07 on 830502-31 Noncompliance noted failure of S&W to correctly consider "dead weight" when performing calculations for pipe supports MALTON, G.A. TRIPP. E. Region 1. Office of Director 83/06/08 10pp 18943 193 24X Fiche 50-412,83/06/10,8306230415
- 8305110470 IE info Notice 83-30, "Defective Heat Sink Adhesive & Seismically Induced Chatter in Relays Within Printed Circuit Cards" Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83706/13 Consolidated Edison Co of New York, Inc. 118pp 18920 225 24X Ficho 50-000,83/06/13.8305110470
- 830.6090010 IE Info Notice 83-37. "Transformer Failure Resulting From Degraded Internal Connection Cables" Svc list oncl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co of New York, Inc 243pp 18921 001 24X Fithe 50-000.83/06/13.8306090010
- B305;10475 IE Info Notice B3-40, "Need to Environmentally Qualify
 Epszy Grouts & Sealers " Svc list oncl
 JORDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post B30103) B3/06/22 Consolidated Edison Co of New
 York, Inc. 115pp 19021 179 E4X Fiche 50-000, B3/06/22, B305110475
- 8305110477 IE Info Notice 83-41, "Actuation of Fire Suppression Sys-Causing Inoperability of Safety-Related Equipment " Svc list encl JURDAN,E L. Division of Emergency Preparedness & Ingineering Response (Post 830103) 83/06/22 Consolidated Edison Co. of New York, Inc. 120pp 18997 007 24% Fiche 50-000,83/06/22.8305110477
- 8305110479 IE Info Notice 83-42, "Reactor Mode Switch Malfunctions " Svc list encl JURDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83706/23 Consolidated Edison Co of New York Inc 116pp 18796 242 24X Fiche 50-000,83706/23,8305110477
- B305110483 IE Info Notice 83-43. "Improprr Bettings of Intermediate Range (IR) High Flux Trip Betpoints " Svc list encl JDRDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) B3/06/24 Consolidated Edison Co of New York, Int 116pp 19046 29/ 24X Ficho 50-000,83/06/24,8305110483

- S Reportable occurrences. LERs & related correspondence
- 830&010092 Second Interim Significant Deficiency Rept 82-04 re potential problem in Westinghouse solid state protection sys Initially reported on 82080&0 Design changes being reviewed Next rept expected by 83073i WOOLEVER, E. J. Duquesne Light Co. 83/05/19 ALLAN, J. Region I. Office of Director. 3pp. 18673-246. 24X Fiche 50-412,83/05/19. 830&010092
- 8306020428 Final Significant Deficiency Rept 83-01 re Westinghouse gate valve position indication Initially reported on 830112 Inaccurate position indication; could result in improper systisolation Mod will be completed by June 1984 MODLEVER.E J. Dequesse Light Co. 83/05/23 ALLAN.J.H. Region 1, Office of Director 4pp 18693 191 24X Fiche 50-412,83/05/23. 8306020428
- 8306210141 Interim Significant Deficiency Rept 83-03 re misoperation of Westinghouse D3-416 reactor trip switchgear undervoltage attachments Initially reported on B30426 Util evaluating deficiency Next rept expected by 830901 HODLEVER.E J Duquesne Light Co 83/05/26 ALLAN.J Region 1. Office of Director Spp 18914 192 24X Fichs 50-412,83/05/26. 8306210141

V Operator Examinations

8306140044 Requests attendance at 830627 meeting w/Region I in King of Prussia.PA to discuss transfer of reactor operating licensing function from Bethesda.MD to Region I ofc STAROBIECKI.R Division of Project & Resident Programs MODLEVER.E J Duquesne Light Co 2pp 18838 311 24X Fiche 50-412,83706/09.8306140044

DOCKET 50-413 CATAMBA NUCLEAR STATION, UNIT 1

- A Application/construction stage documents & correspondence
- 8306030300 Forwards Vols 1 & 2 to Rev 1 to "Buke Power Co Response to Suppl 1 to NUREO-0737 for Catawba Nuclear Station "
 TUCKER, H B Dute Power Co 83/06/01 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAME 0 Licensing Branch 2 215pp 18/04 038 24X Fiche 50-413.03/06/01.0306030900
- 8306160725 Summary of 830324 meeting w/utils & Westinghouse in Dethesda. MD re design review panel review of new Westinghouse stress analysis on manifold fasteners for D2/D3 steam generator mod HOPKINS. J B Licensing Branch 4 83/06/10 Licensing Branch 4 7pp 18876 277 24% Fische 50-000.83/06/10.8306160725
- B306290573 Summary of Design Review Panel B30321 meeting w/utils & Westinghouse in Bethesda, MD re D2/D3 steam generator mod & Westinghouse stress analysis of manifold fasteners HOPKINS, J B. Licensing Branch 4 B3/06/10 Licensing Branch 4, 7pp 19047 085 24X Fiche 50-000, 63/06/10, 6306290573
- E NRC Safety Evaluation Report (SER), supple & correspondence
- 8306070206 Forwards "Overpressure Protection Rept for Catabba Nuclear Power Plant.Units 1 & 2 as Required by ASNE Boiler & Pressure Vessel Code. Section III, Article NB-7300" & response to SER Open Item 7 & Confirmatory Item 24

 TUCKER. H B Duke Power Co B3/05/27 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENBAM, E Q Licensing Branch 4 2pp 18747 076 24X Fiche 50-419,83/05/27,8306070206
- --8306070210 "Gverpressure Protection Rept for Catawba Nuclear Power Plant,Units 1 & 2 as Required by ASME Boiler & Pressure Vessel Code, Section III. Article NN-7300 " FORCHIX A. LANG. 9 E. HITSEMANN, R. A. Dute Power Co. 82/07/31, 14pp 18747 078 24X Fiche 50-413,83/05/27,8306070206
- 8306070314 Advises that internal corresion protection for fuel oil storage tanks in conformance w/ANBI N195 & that internal coating applied to fuel oil storage tank not necessary.per BER Section 9 5 4 2
 TUCKER.H B. Duke Fower Co 83/06/01 DENTON,H R. Office of Nuclear Reactor Regulation, Director ADENBAH.E @ Licensing Branch 4 14pp 18744 227 24X Fiche 50-413,83/06/01,8306070314.
- 830614001B Forwards six oversize electrical elementary diagrams in response to SER Confirmatory Item 34 Diagrams confirm removal of key-locked switches from control room HVAC circuits Aperture cards are available in PDR TUCKER.H B Duke Power Ca 63/06/07 DENTON.H R Office of Nuclear Reactor Regulation. Director ADENBANE 0 Licensing Branch 4 2pp 18832 071 24X Fichs 50-413.83/06/07.8306140018

- 8306170316 Forwards revised FSAR pages responding to SER Confirmatory
 Items 14,16 to 17 re containment isolation valve data to containment purge sys from 830525 meeting in BethesdauMD
 TUCKER, H B Duke Power Co 83/06/07 DENTON, HR Office of
 Nuclear Reactor Regulation, Director ADENBAM, E G Licensing Branch
 4 15pp 18877 027 24X Fithe 50-413,83/06/07,8306170316
- 8306240123 Forwards two oversize electrical elementary diagrams.in response to SER Confirmatory Item 30 TUCKER.H B Duke Power Co 83/06/20 DENTON.H R Office of Nuclear Reactor Regulation. Director ADENSAM.E G Licensing Branch 4. 2pp 18978 001 24X Fiche 50-413.83/06/20.8306240123
- 8306240183 Forwards revised FSAR pages re hydrologic engineering, in response to NRC 830506 ltr & SFR Confirmatory Item I Revised pages will be included in Rev B to FSAK W/three oversize figures Aperture cards are available in PDR TUCKER. H B Duke Power Co 83/06/21 DENTON. H R Office of Nuclear Reactor Regulation. Director ADENSAM.E G Licensing Branch 4 26pp 24X Fiche 50-413.83/06/21,0304240183
- 8306270384 Forwards brochure entitled, "Catawba Nuclear Station Emergency Plan," per SER, Suppl 1. Section 13 3 2 7 TUCKER. H B Duke Power Co 83/06/22 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAM, E G Licensing Branch 4 18pp 18972 134 24X Fiche 50-413,83/06/22,8306270384
- F Security, medical, emergency & fire protection plans
- 8306140664 Forwards IE Insp Repts 50~413/83-07 & 50~414/83-07 on B30426-29 No noncompliance noted DANCE,H C Division of Project & Regident Programs 83/05/24 TUCKER,H B Dute Power Co 2pp 18842 050 24X Fichs 50~413,83/05/24,8336140664
- --8306140671 IE Insp Repts⁴ 50-413/83-07 & 50-414/83-07 on 830426-29 No noncompliance noted Major areas inspected cable penetration firstops, installation of instrument sensing lines, electrical table terminations & review of OC records RVFF, A B Region 2, Diffice of Director CON,ON Division of Engineering & Radiological Safety Programs 83/05/20 &pp 18842 052 24X Fiche 50-413,83/05/24,8306140664
- 8304070349 Forwards "Study of Fire Resistive Performance of fire Div Walls Used in Power Plant Const." as partial response to Open Item 14 of fire protection program Three oversize drawlings encl Aperture cards are available in PDR TUCKER. H B Duke Power Co 83/05/31 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAM, E O Licensing Branch 4 2pp 18743 200 24% Fiche 50-443,83/05/31.8304070349
- --8306070352 "Study of Fire Resistive Performance of Fire Div Halls Used in Power Plant Const "
 BLETZACKER, R H Richard W Bletzacker & Associates, Inc B3/04/08 170pp 18743 202 24% Fiche 50-413.83/05/31, 8306070349
- 8306220287 Releases public version of emergency plans FELTON, J M Division of Rules and Records 63/06/17 Document Management Branch 1p 18748 089 24X Fiche 50-413.83/06/17.8306220287
- --8306220295 Forwards public version of State of SC operational radiological emergency response plan. State of NC emergency response plan & York County emergency operation plan TUCKER, H B Duke Power Co 83/06/06 DENTON, H R Offic of Nuclear Reactor Regulation, Director 4pp 18948 070 24X Fichs 50-413, 83/06/17, 8306220289
- --8306220279 Public version of State of SC operational radiological emergency response plan. State of NC emergency response plan & York County emergency operation plan * South Carolina. State of 83/05/31 938pp 18948 094 24X Fiche. 50-413, 83/06/17, 8306220289
- 83062703B4 Forwards brochure entitled, "Cotamba Nuclear Station Emargency Plan," per SER, Suppl 1, Section 13 3 2 7 TUCKER: H B Duke Power Co. B3/06/22 DENTINH R Office of Nuclear Reactor Regulation, Director. ADENBAM.E 9 Licensing Branch 4 18pp 18792:134 24X Fiche.50-413.63/06/22,8306270384.
- 9 Adjudicatory correspondence
- 8306060297 Further supplementary responses to util interrogatories re Contentions 6,7,8,16 & 44 & NRC interrogatories re Contention 7 & responses to util & NRC followup interrogatories. Certificate of Suc encl JOB, P.H. Palmetto Alliance 83/05/27, Duke Power Co 44pp 18729-325 24X Fiche 50-413,83/05/27,8304040297

- 8304040072 Response opposing Palmetto Alliance 830525 mation to establish discovery schedule on OA Contention 6 Alliance allotted reasonable opportunity to commit discovery Certificate of Svc end.

 JOHNSON, C. E. Healing Branch 4 83/06/02 Atomic Safety and Licensing Board Papel 17pp 18723 2°44 24% Fiche 50-413,83/06/02,8306060672
- 8306060301 Response opposing Palmetto Alliance motion to establish discovery schedule on RA Contention 6 Alliance afforded every opportunity to obtain info necessary to support contention Certificate of Soc (no.)

 MCGARRY, JM Duke Power Co MCGARRY, JM Debevoise & Liberman B3/06/02 Atomic Safety and Licensing Board Pancl 48pp 18729 049 24X Fiche 90-413.0 1/06/02, 8306060301
- B304070041 Motion for sanctions against Palmotto Alliance Alliance Contentions 7 & 44 should be dismissed for failure to meet discovery deadlines Certificate of Svc and JUHNSON. G E Hearing Branch 4 83/06/03 Atomic Safety and Licensing Board Panel 14pp 18737 344 24X Fiche 50-413.89/06/04, 8306070041
- 8306080170 Mobson for sanctions against Palmetto Alliance & (arelina Environ Study Group Number & scope of contentions should be limited for failure to respond to discovery requests Certificate of foc onl. MCGARRY, J M Duke Power Co MCCARRY, J M Debevoise & Liberman 83706/06 Atomic Safety and Licensing Board Panel 145pp 18771 346 24X Fiche 50-413,83/06/06,8306080170
- B30609030B Forwards Region II 830602 ltr transmitting notice of violation & proposed imposition of civil penalties in amount of \$180,000 for violations noted in IE Insp Repts 50-269783-11,50-270783-11 & '0-28798-3-11 UDHN90N,6 & Healing Branch 4 83706/06 KELLEY, J L , FUSIER.R / . CALLIFAN,D Atomic Safety and Licensing Board Panel Bpp 18795-179 24X Fiche 50-413,83706/06.6306090305
- ## B306/10197 Supplemental response to Interrogatory 17 on Contention 7 CARR, A V Buke Power Co CARR, A V Debevoise & Liberman ## B3766/08 2pp 18806 010 24% Fiche 50-413, 83706/08, 830501017/
- --B306100199 Motion for extension until B30/Ol to file motions for summary disposition Palmetto Alliance allowed to make discovery past scheduled time Certificate of Svc encl MCGARRY.J M Duke Power Co MCGARRY.J M Debevoise & Liberman B3/O6/OB Atomic Safety and Litersing Board Panel Spp 16806 012 24% Fiche 50-413,83/06/08.8306100197
- 8306130437 Notice of change of address PRESLER.H A Charlotte-Mecklimberg Environmental Coalitins 83/06/08 Docketing & Services Drauch ip 1887/1 194 24X Fiche.50-413, 83/06/08.8306130437
- B306150385 Response apposing applicant & NRC motions for sanctions re Contentions 6.7.8.16 & 44/18 & Contentions 7 & 44, respectively Applicant & NRC motions should be densed Discovery obligations fulfilled Certificate of Svc encl GUILD.R Palmetto Alliance GUILD.R Carolina Environmental Study Group GUILD.R Guild, R 83/06/10 Atomic Bafety and Licensing Board Panel 26pp 18847 170 24% Fishe 50-413.83/06/10.
- 8306160612 Memorandum & order ruling on Palmetto Atliance motion to establish discovery schedule on QA Contention & Denies portion of motion requesting extension for unrestricted discovery Add time allotted to take depositions or welding KELLEY, J. L. Atomic Safety and Licensing Board Panel 13706/13 Palmetto Alliance, 9pp 18866 131 24X Fiche 50-413.83/06/13.8306160612
- 8306170365 Response supporting util 830608 motion for extension until 830701 to file motions for summary disposition Palmetto filed discovery responses late Motions to dismiss for failure to make discovery pending H/Certificate of 8v. JOHNSON, Q E. Hearing Branch 4. 83/06/15. Atomic Bafety and Licensing Board Panel. 5pp. 18880 322/ 24X Fiche, 50-413,83/06/15,8306170365
- 8306220092 Submits position on conduct re dispositions of util amployees ordered by ASLB 830613 memorandum & order Related correspondence CARR.A V Duke Power Co 83/06/15 GUILD, R Guild, R 2pp 18927 171 24X Fiche 50-413,83/06/15.8306220092

- 8306210276 Forwards NRC 830602 response to Palmetto Alliance request to eitend discovery on Contention 6 re GA Filing inadvertently sent to wrong address W/o oncl
 JOHNSON G E Hearing Branch 4 83/05/17 FOSTER.R F Atomic
 Safety and Licensing Board Panel 1p 18914 024 24X
 Fiche 50-413.83/06/17.8306210296
- B306220059 Memorandum & order ruling on NRC B30603 motion for sanctions based on Palmetto Alliance (PA) failure to make discovery on Contentions / & 44 & util B30606 motion for sanctions requesting dismissal of PA Contentions 6.7.8.16 & 44 KELLEY, J. L. Atomic Bafety and Licensing Board Panel B3/06/20 19pp 1872B 185 24% Files 50-413,63/06/20,6306220059
- 8306270284 Response to interrogatories & requests to produce re-Carolina Environ Study Group Contention 13 Affirmation of Svc entl Related correspondence R[LEV.J L Carolina Environmental Study Group 63/06/20 Duke Power Co 8pp 18996 199 P4X Fiche 50-413,63/06/20,8306870284.
- D306290459 Forwards joint motion for approval of stipulation & stipulation re-sattlement of contentions CARR.A V Duke Power Co B3706723 KCLLEY.J L , CALLIHAN.A.D , FOSTER, R F Atomic Safety and Licensing Doard Panel 19
- ~-8306290461 Joint motion for approval of stipulation CARR.A V Duke Power Co PRESLER.H A Charlotte Mccklenberg Environmental Coslition 03/06/23 Atomic Safety and Licensing Board Panel 2pp 17052 176 24X Fiche 50-413.83/06/23, 8306270457
- --8306270464 Stipulation re settlement of contentions Charlotte-Mectlenburg Environ Coalition withdraws contentions from proceedings CARR, A V Duke Power Co * Charlotte-Mecklenberg Environmental Coalition 83/06/23 3pp 19052 178 24X Fiche 50-413,83/06/23, 8306290459
- 8306290540 Discusses Palmetto Alliance notices of depositions Some individuals unavailable on dates proposed Related correspondence GIBSON, R. L. Duke Power Co. 83/06/29 GUILD, R. Palmetto Alliance GUILD, R. Guild, R. 2pp. 17052-316 24X Fiche 50-413,83/06/23, 8306270540
- 8396280084 Comments on ASLB revised tentative prehearing schedule listed in ASLB 830620 memorandum & order Suggests revs if Charlotte-Macklenburg Environ Coalition Contentions 1-4 dismissed Certificate of Svc encl JGNRSON. O E Hearing Branch 4 83/06/24 7pp 19001 161 24X Fiche 50-413,83/06/24 8306280084
- I Financial information
- B306200352 Forwards Annual Financial Rept 1982 TUCKER: H B Duke Power Co B3/06/15 DENTON.H R Office of Nuclear Reactur Regulation, Director ADENSAM.E 0 Licensing Branch 4 2pg 18899 101 24% Ficha 50-000.83/06/15.8306200352
- --8306200356 Annual Financial Rept 1982 * North Carolina Municipal Power Agencies 83/06/15 20pp 18899 103 24X Fiche 50-000.83/06/15.8306200352
- O Advisory Committee on Reactor Safeguards reports & correspondence
- 830617043B Summary of ACRS Subcommittee on Catawba Nuclear Station 830304-05 meetings in Charlotte,NC re DL application review * ACRS - Advisory Committee on Reactor Safeguards 83/05/11 ACRS - Advisory Committee on Reactor Safeguards 39pp 18908 017. 24X Fichs 50-413,83/05/11,830617043B
- O Inspection reports, IE Bulletins & correspondence
- 8306140565 Confirms mgt meeting on 830301 at plant site to discuss self-initiated evaluation of project mgt, design & const of facility.

 D'REILLY, J.P. Region 2, Office of Director 83/02/10 OWEN, W H. Ouke Power Co. ip. 18834 266 24X Fishe 50-413,83/02/10, 8306140565
- B306140129 Ack receipt of IE Insp Repts 50-413/83-03 & 50-414/83-03 No proprietary info TUCKER, H B Duke Power Co 83/04/22 D'REILLY, J P. Region 2, Office of Director ip 18839 135 24X Fiche 80-413,83/04/22, B306140129

- 8306140119 Act receipt of IE Insp Repts 50-413/83-05 & 50-414/83-05 No proprietary info TUCKER:N B Duke Power Co 83/05/13 O'REILLY, J P Region 2, Office of Director ip 18039 161 24X Fiche 50-413,83/05/13, 8306140119
- 8306140123 Ack receipt of IE Insp Repts 50-413/83-06 & 50-414/83-06 No proprietary info TUCKER, H B Duke Power Co 83/05/19 D'REILLY, J. P Region 2. Office of Director ip 18839 162 24X Fiche 50-413,83/05/19,8306140123
- 8306140664 Forwards IE Insp Repts 50-413/83-07 & 50-414/83-07 on 830426-29 No noncompliance noted DANCE.H C Division of Project & Resident Programs 83/05/24 TUCKER,H B Duke Power Co 2pp 18842 090 24X Fiche 50-413,83/05/24,8306140664
- --8306140671 IE Insp Repts 50-413/83-07 & 50-414/83-07 on 830426-29 No noncompliance noted Major areas inspected cable penetration firestops, inetallation of instrument sensing lines, electrical cable terminations & review of GC rescribe RUFF, A B Region 2. Office of Director CONLON Division of Engineering & Radiological Safety Programs 83/05/20. App. 18042 052 24% Fiche 50-413,83/05/24,8306140664
- 8305i10458 IE Info Notice B3-32, "Ruptured Am-241 Sources Contained in Well Logging Device " Svc list encl. TAYLOR, J M Division of Safeguards & Inspection Programs (Post B30103) 8308726 Consolidated Edison Co. of New York, Inc. 125pp 18831 042 24X Fiche 50-000.83/05/26,8305i10458
- 8305:10460 IE Info Notice 83-34, "Event Notification Info Worksheet,"
 Svc list encl
 JORDAN, E. L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/05/26 Consolidated Edison Co. of New
 York, Inc. 115pp 18732 085 24% Fiche 50-000.83/05/26,8305110460.
- 8306140497 Ack receipt of 830512 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-419/83-04 & 50-414/83-04

 DANCE, H C Division of Project & Resident Programs 83/05/27
 TUCKER, H B Duke Power Co ip 18838 096 24X

 Fichs 50-413,83/05/27,8306140497
- --8306140502 Responds to NRC 830412 ltr re violations noted in IE Insp Repts 50-413/83-04 & 50-414/83-04 Corrective actions GA insp group inspected & accepted hanger I-R-NV-1385 w/location outside of tolerance required by drawing TUCKER,H B Duke Power Co 83/05/12 O'REILLY,J P Region 2, Office of Director 3pp 18838 097. 24X Fiche 50-413,83/05/27, 8336140497
- --8306140506 Forwards IE Insp Repts 50-413/83-04 & 50-414/83-04 on 830315-18 & notice of violation.

 DANCE:H C Division of Project & Resident Programs 83/04/12 TUCKER:H B Duke Power Co 2pp 18838 100 24X Fiche: 50-413.83/05/27.8306140497
- --8306140508 Notice of violation from insp on 830315-18
 * Region 2. Office of Director 83/05/12 lp 18838 102 24X
 Fiche: 50-413, 83/05/27, 8306140497
- --B306140511 IE Insp Repts 50-413/83-04 & 50-414/83-04 on 830315-18

 Noncompliance noted failure to follow procedure & drawings
 for Pabrication, erection of hangers, supports & seismic
 controls & component supports,
 YORK, J W Region 2, Office of Director, BLAME, J Division of
 Engineering & Radiotogical Bafety Programs 83/04/08 Opp
 18838-103 24X Fichs 50-419,83/08/87,8306140497
- 8305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods Withdrawn at BMRs " Svc list encl.
 JORDAN, E. L. Division of Emergenty Preparadness & Engineering Response (Post 830103) 83/05/31 Consolidated Edison Co. of New York Inc. 116pp 18732 208, 24X Fichs.50-000,83/05/31,8305110461.
- 8306290186 Forwards IE Insp Repts 50-413/83-10 & 50-414/83-10 on 830917-20 No noncompliance noted DANCE,H.C. Division of Project & Resident Programs 83/06/03 TUCKER,H B Duke Power Co 2pp 19056 211 24X Fiche 50-413,83/06/03,8306290186
- --8306290192 IE Insp Repts 50-413/83-10 & 50-414/83-10 on 830517-20 No noncompliance noted Major areas inspected RCPB piping, safety-related piping & structures & licensee identified iOCFR50 55e items.

 CROWLEY, B R., BLAKE, J J. Region 2, Office of Director 83/06/02, 8pp 19056, 213 24X Fiche 50-413, 83/06/03, 8306290186

- B306270376 Forwards IE Insp Repts 50-413/B3-07 & 50-414/B3-09 on B30516-20 No noncompliance noted DANCE,H C. Division of Project & Resident Programs 83/06/03 TUCKER,H B Duke Power Co 2pp 19055 263 24X TUCKER, H B Duke Power Co 2pp Fiche 50-413,83/04/03,8304290394
- --8306290404 IE Insp Repts 50-413/83-09 & 50-414/83-09 on 830516-20 No NOARY AND INSPIRED TO STATE OF THE STATE OF
- 8304090305 Forwards Region II 830402 ltr transmitting notice of Violation & proposed imposition of civil penalties in amount of \$180,000 for violations noted in IF Insp Repts 50-269/83-11,50-270/83-11 & 50-207/83-11
 JDHN8DN,0 E Hearing Branch 4 83/06/06 KELLEY, J L , FOSTER,R F , CALLIHAN,D Atomic Safety and Licensing Board, Panel 8pp 18795 179 24% Fiche 50-413,83/06/06,8306090305
- B306270300 Forwards IE Insp Repts 50-413/B3-08 & 50-414/B3-08 on B30326-0425 No noncompliance noted DANCE,H.C Division of Project & Resident Programs B3/06/07 TUCKER,H B Duke Power Co 2pp 19056 011 24X Fichs 50-413,83/06/07.83062707300
- -8306290305 IE Imap Repts 50-413/83-08 & 50-414/83-08 on 830326-0425 No JOAEVOADD LE INSP KERTS 30-413/83-08 & 30-414/83-08 on 8303s noncompliance noted Major areas inspected followup on NRC identified items.review of nonconforming items.observation of QA trasning & attendance at INPO mgt meeting VANDOORN.P K Region 2. Dffice of Director IRCUNLEE.V L Division of Project & Resident Programs 83/06/07 4pp 19056:012 24X Fichs 50-413,83/06/07.8306290300
- 8305110464 IE Info Notice B3-36. "Impact of Security Practices on Safe Operations " Syc list encl JORDAN.E.L. Division of Emergency Preparedness & Engineering Response (Post B30103) 83/06/09 Consolidated Edison Cn. of New 707 Consolidated Edison Cn of New 24X Fiche 50-000,83/06/09,8305110464 18830 280 119pp
- 8305110470 IE Info Notice 83-38. "Defective Heat Sink Adhesive & Seismically Induced Chatter in Relays Within Printed Circuit Cards." Syc list encl JORDAN, E. L. Bivisian of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co of New York, Inc. 118pp 18920 225 24X Fiche 50-000,83/06/13.8305110470
- 8304090010 IE Info Notice 83-37, "Transformer Failure Resulting From Degraded Internal Connection Cables " Svc list encl JORDAN,E.L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/13 Consolidated Edison Co of New York, Inc. 243pp 18921,001 24X Fishe 50-000,83/04/13.8304090010
- 8305110475 IE Info Notice 83-40, "Need to Environmentally Qualify
 Epoxy Grouts & Seaters " Svc list encl
 JORDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/06/22 Consolidated Edison Co of New
 York, Inc 115pp 19021 179 24X Fiche 50-000,83/06/22,8305110475
- 8305110477 IE Info Notice 83-41, "Actuation of Fire Suppression Sys Causing Inoperability of Safety-Related Equipment " Svc list
 - VORDAN.E.L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/22 Consolidated Edison Co. of New York, Inc. 120pp 18997 007 24X Fiche 50-000,83/06/22,8305110477
- 8305110479 IE Info Notice 83-42, "Reactor Mode Switch Malfunctions " 30510479 IE Inro Novier C. ... Byc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post B30103) B3706/23 Consolidated Edison Co of New York, Inc. 116pp, 18976:242, 24X Fiche 50-000,83/04/23,83051[0479
- 8305i10483 IE Info Natice 82-43, "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints " byc list encl JORDAN, E. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/24, Consolidated Edison Co. of New York, Inc. 116pp. 19046.297, 24X Fiche 50-000.83/06/24,8309110483
- 8 Reportable occurrences, LERs & related correspondence
- 8304070046 Informs of closeout of AITS F027002B5 re nonrelevant linear indications in 3/4-inch Kerotest check valve body w/o any branch action POTAPOS, U Division of Vendor & Technical Programs 63/05/02 LEWIS,R.C Division of Project & Resident Programs 1p 18740-098 24% Ficher 50-413,83/05/02,8305070055.

- 8306100176 PNO-II-83-045 on 830608 Cardox carbon dioxide fire protection sys in diesel room inadvertently activated Precautionary evacuation conducted No serious injuries
- 8306270118 Revised Significant Deficiency Rept SD 413/82-10 rc non-Class IE communication fire detection & lighting cables attached to essential cable tray side rails Initially reported on 820329 Cables qualified por IEEE 383-1974 test TUCKER.H II Duke Power Co. 83/06/15 0'REILLY, J.P. Region 2, Defice of Director 3pp 18988 107 24X Fiche 50-413,83/06/15, Office of Director
- DOCKET 50-414 CATAWRA NUCLEAR STATION, UNIT 2
- A Application/construction stage documents & correspondence
- 830A030300 Forwards Vols i & 2 to Rev i to "Duke Power Co Response to Suppl i to NUREG-0/37 for Catamba Nuclear Station " TUCKER: H B Duke Power Co 83/06/01 DENTON. H R Dffice of Nuclear Reactor Regulation. Director ADENSAM. E G Licensing Drane 4 215pp 18704 038 24% Fiche 50-413.83/06/01.8306030300 Licensing Branch
- B30.6200019 Bummary of B30331 meeting w/utils & Westinghouse in Bethesda.MD re Westinghouse analysis & evaluation of D4/D5/E steam generator mod HDPKINS.J B Licensing Branch 4 B3/06/14 Licensing Branch 4 R2Pp 1690B 327 24X Fiche 50-000, B3/06/14, B306200019
- E NRC Bafety Evaluation Report (SER), supple & correspondence
- B306070206 Forwards "Overpressure Protection Rept for Catawba Nuclear Power Plant, Units 1 & 2 as Required by ASMC Boiler & Pressure Vessel Code, Section III, Article NB-7300" & response to BER Dpen Item 7 & Confirmatory Item 24
 TUCKER, H B Dute Power Co 83/05/27 DENTON, H R Dffice of
 Nuclear Reactor Regulation, Director ADENSAM, E G Licensing
 4 2pp 18747 076 24X Fichs 50-413,83/05/27,8306070206 Licensino Branch
- --8306070210 "Overpressure Protection Rept for Catawba Nuclear Power Plant, Units 1 & 2 as Required by ASME Boiler & Pressure Vessel Code, Section III, Article NB-7300" FORCHI, K. A. LANGO, G. F. WIESENANN, R. A. Duke Power Co. 82/07/31 14pp 18/47-070 24X Fiche 50-413,83/05/27,8306070206
- B306070314 Advises that internal corrosion protection for fuel oil storage tanks in conformance w/ANSI N195 & that internal coating applied to fuel mil storage tank not necessary, per SER Section 9 5 4 2
 TUCKER: H B Duke Power Co B3/06/01 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAME Q Licensing D1 4 14pp 18744 227 24X Fiche 50-413.83/06/01.8306070314 Licensing Dranch
- 8306140018 Forwards six oversize electrical elementary diagrams, in response to SER Confirmatory Item 34 Diagrams confirm removal of key-locked switches from control room HVAC circuits Aperture cards are available in PDR TUCKER, H B Duke Power Co 83/06/07 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAM, E G Licensing Bt 4 2pp 16932 071 24X Fiche 50-413,03/06/07.8306140018 Licensing Branch
- B306170316 Forwards revised FBAR pages responding to BER Confirmatory Items 14, 16 & 17 re containment isolation valve data & containment purge sys from B20525 meeting in Bethasda. ND TUCKER. H B Duke Power Co B3/06/07 DENTON, H R Diffice of Nuclear Reactor Regulation. Director ADENSAM.E G Licensing Branch 4 15pp 18977 027 24X Fiche 50-413, B3/06/07, B306170316
- 8306240123 Forwards two oversize electrical elementary diagrams, in response to BER Confirmatory Item 30 TUCKER, H B Duke Power Co 83/06/20 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENBAN, E O Licensing Branch 4 2pp 18978 001 24X Fiche 80-413, 83/06/20, 8306240123
- 8306240183 Forwards revised FSAR pages re hydrologic engineering in response to NRC 830506 ltr & SFR Confirmatory Item I Revised pages will be included in Rev B to FSAR W/three eversize figures Aperture cands are available in PDR TUCKER, H B Duke Power Co 83/06/21 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAM, E O Licensing Bra 4 26pp 24% Fiche 50-443,03/06/21,0306240183 Licensing Branch
- 8306270384 Forwards brochure entitled, "Catawba Nuclear Station Emergency Plan," per SER, Suppl 1, Section 13 3 2 7 TUCKER, H B Duke Power Co 83/06/22 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAME Q Licensing 4 18pp 18992 134 24X Fiche 50-413, 83/06/22, 8306270384 Licensing Branch

- F Security, medical, emergency & fire protection plans
- 83D6140664 Forwards IE. Insp. Repts. 50-413/83-07 & 50-414/83-07 on B30426-29 No noncompliance noted DANCE,H.C. Division of Project & Resident Programs 83/05/24 TUCKER,H.B. Dake Power Co. 2pp. 18842-050 24X Fiche 50-413,830/5/24,8306140664
- --8306140671 IE Inap Repts 50-413/83-07 & 50-414/83-07 on 830426-29 No noncompliance noted Major areas inspected cable penetration firestops, installation of instrument sensing lines, electrical cable terminations & review of QC records RUFF, A B Region 2. Office of Director 83/05/20 6pp (8842-052 24X Fiche 50-413.83/05/24.8306140664
- B30A070°349 Forwards "Study of Fire Resistive Performance of Fire Div Walls Used in Power Plant Const." as partial response to Open Item 14 of fire protection program three oversize drawings encl Aperture cards are available in PDR TUCKER. H B Duke Power Co 83/05/31 DENTON, H R Office of Nuclear Reactor Regulation, Director ADENSAM, E G Licensing Branch 2pp 18743 200 24X Fiche 50-413.83/05/31.8304070349
- --8305070352 "Study of Fire Resistive Performance of Fire Div Walls Used in Power Plant Const " BLETZACKER: R W Richard W Bletzacker & Associates, Inc 8370470B 170pp 18743 202 24X Fiche 80-413,83705/31. 8306070349
- 8306220289 Releases public version of emergency plans FELTON, J M Division of Rules and Records 83/06/17 Document Management Branch Ip 18948 089 24X Fiche 50-413,83/06/17, 8306220289
- --8306220295 Forwards public version of State of SC operational radiological emergency response plan, State of NC emergency response plan tyork County emergency operation plan TUCKER, H II Duke Power Co 83/06/06 DENTON, H R Office of Nuclear Reactor Regulation, Director App 18748 090 24X Fiche 50-413,83/06/17,8306220289
- --8306220279 Public version of State of BC operational radiological emergency response plan. State of NC emergency response plan & York County emergency operation plan * South Carolina. State of 83/05/31 938pp 18946 094 24X Fiche 50-413,83/06/17.8306220289
- 8304270384 Forwards brochure entitled, "Catawba Nuclear Station Emergency Plan," per SER. Suppl 1. Section 13 3 2 7 TUCKER, H B Duke Power Co 83/6/22. DENTON, H R Office of Nuclear Reactor Regulation. Director 18pp 18792 134 24X Fiche 50-413.03/06/22.8306270384
- Q Adjudicatory correspondence
- 830.606.297 Further supplementary responses to util interrogatories re Contentions 6,7.0,16 & 44 & NRC interrogatories re Contention 7 & responses to util & NRC followup interrogatories Certificato of Svc encl JOB.P H Palmetto Alliance 83/05/27 Duke Power Co 46pp 18729 325 24X Fiche 50-413,83/09/27,8706060297
- 8304060072 Response opposing Palmetto Alliance 830825 motion to establish discovery schedule on QA Contention 6 Alliance allotted reasonable apportunity to conduct discovery Certificate of Buc enci JOHNEON, 0 E Hearing Branch 4 83/06/02 Atomic Bafety and Licensing Board Panel 17pp 18723 254 24X Ficher 90-413, 83/06/02, 8304060072
- 8304070041 Motion for sanctions against Palmetto Alliance Alliance Contentions 7 & 44 should be dismissed for failure to meet discovery deadlines Certificate of Svc encl JDHN9ON: 0 E Hearing Branch 4 83/04/03 Atomic Safety and Licensing Board Panel 14pp 18739,344 24X Fiche: 50-413,83/04/03, 8304070041
- B306080170 Motion for sanctions against Palmetto Alliance & Corolina Environ Btudy Group Number & scope of contentions should be limited for Failure to respond to discovery requests Certificate of Byc encl MCGARRY.JM Duke Power Co MCGARRY.JM Debevoise & Liberman B370406 Atomic Safety and Licensing Board Panel 144pp 18771 346 P4X Fiche 50-413,83/04/04,8304080170

- 8306090305 Forwards Region II 830602 ltr transmitting notice of violation & proposed imposition of civil penalties in amount of \$180,000 for violations noted in IE Insp Repts 50-269/83-II,50-270/83-II & 50-287/83-II JOHNSON, G E Hearing Branch 4 83/06/06 KELLEY, J L FOSTER, R F . CALLIAN, D Atomic Safety and Licensing Board Panel Bpp 18795 179 24% Fiche \$0-413.83/06/06.8306090305
- 8306100196 Responses to util 830523 followup interrogatories on DES Contentions 11:17 & 19 * Palmetto Alliance * Carolina Environmental Study Group 83/06/06 Duke Power Co 13pp 18805 354 24X Fiche 50-413.83/06/06.8306100196
- 8306100197 Supplemental response to Interrogatory 17 on Contention 7 CARR,A V Dute Power Co CARR,A V Debevoise & Liberman 83/06/08 2pp 18806 010 24% Fiche 50-413,83/06/08,8306100197
- --8304100199 Motion for extension until B30701 to file motions for summary disposition Palmetto Alliance allowed to make discovery past scheduled time Certificate of Svc enc! MCGARRY.J M Duke Power Co MCGARRY.J M Debevoise & Liberman 83/06/08 Atomic Sefety and Licensing Board Panel 5pp 18806 012 24X Fiche 50-413,83/06/08 8306100197
- 8306130437 Notice of change of address PRESLER.H.A. Charlotte-Mecklenberg Environmental Coalition 93/06/08 Docketing & Services Branch ip 19821 194 24X Fiche 50-413.83/06/08.8306130437.
- 8306180385 Response opposing applicant & NRC motions for sanctions re Contentions 6.7.B.16 & 44/18 & Contentions 7 & 44, respectively Applicant & NRC motions should be denied.
 Discovery obligations fulfilled Certificate of SVC encl.
 GUILD, R Palmetto Alliance GUILD, R. Carolina Environmental Study Group, GUILD, R. Guild, R. 83/06/10. Atomic Safety and Licensing Board Panel 26pp 18847.170 24% Fiche 50-413.83/06/10.
- 8306160612 Memorandum & order ruling on Palmetto Alliance motion to establish discovery schedule on GA Contention 6 Denies portion of motion requesting extension for unrestricted discovery Add time allotted to take depositions re welding KELLEY, J. L. Atomic Gafety and Licensing Board Panel B3/06/13 Palmetto Alliance 7pp 18866 131 24X Fiche 50-413, 83/06/13, 8306160612
- 8306170365 Response supporting util 830603 motion for extension until 830701 to file motions for summary disposition Palmetto filed discovery responses late flotions to dismiss for failure to make discovery pending W/Cortificate of Svc. JOHNSON. 0 E Hearing Branch 4 83/06/15 Atomic Safety and Licensing Board Panel 5pp 18880.322 24X Fiche 50-413,83/06/15,8306170365
- 8306220092 Submits position on conduct re dispositions of util employees ordered by ASLB 830613 memorandum & order Related correspondence.

 CARR, A.V. Buke Power Co. 83/06/15 GUILD, R. Guild, R. 2pp. 18927 171 24% Fiche 50-413,83/06/15,8306220092
- 8306B10276 Forwards NRC 830602 response to Palmetto Alliance request to extend discovery on Contention 6 re GA Filing inadvertently sent to wrong address W/o encl JOHNSON, 0 E Hearing Branch 4 83/06/17 F08TER, R F Atomic Safety and Licensing Board Panel. Ip. 18914 024, 24X Fiche: 50-413,83/06/17,8306210296
- 8306220039 Memorandum & order ruling on NRC 830603 motion for sanctions based on Palmetto Alliance (PA) failure to make discovery on Contentions 7 & 44 & util 830606 motion for sanctions requesting dismissal of PA Contentions 6,7,8,16 & 44 KELLEY, J. L. Atomic 8afety and Licensing Board Panel 83/06/20 19pp 18928 185 24X Fiche 50-41G,83/06/20,8304220039
- B306270284 Response to interrogatories & requests to produce re Carolina Environ Study Group Contention 13 Affirmation of Byc encl Related correspondence. RILEY, J. L. Carolina Environmental Study Group. 83/06/20. Duke Power Co. Bpp. 18994-199-24X Fiche 50-413,83/06/20,8306270284.
- 8306290459 Forwards joint motion for approval of stipulation & stipulation re settlement of contentions CARRA V buke Power Co 83/06/23 KELLEY, J.L., CALLIHAN, A B., FOBTER, R. F. Abomic Safety and Licensing Board Panel ip 19052:175 24X Fiche, 50-413, 83/06/23, 8306290459
- --8306290461 Joint motion for approval of stipulation.
 CARR.A V. Duke Power Co PRESLER, H.A. Charlotte-Mecklenberg
 Environmental Committee B2/06/23 Atomic Safety and Licensing
 Board Panel 2pp 17052 176 24X Fiche: 50-413, 83/06/23,
 8306290459

- --8305290464 Stipulation re-settlement of contentions Charlotte-Mcklenburg Environ Coalition withdraws contentions from proceedings CARR: A V Duke Power Co * Charlotte Mecklenberg Environmental Caalition 83/05/23 3pp 19052 170 24X Fiche 50-413,83/05/23, 8305290459
- B306290540 Discusses Palmetto Alliance notices of depositions Some individuals unavailable on dates proposed Related correspondence G1880N.R L Duke Power Co B3/06/23 GUILD.R Palmetto Alliance GUILD.R Guild. R 2pp 17052 316 24X Fiche 50-413,83/06/23,83/06/23
- 8306280084 Comments on ASLB revised tentative prehearing schedule listed in ASLB 830620 memorandum & order Buggests revs if Charlatte-Mecklenburg Environ Coalition Contentions 1-4 dismissed Certificate of Svc encl JOHNSON, C E Hearing Branch 4 83/06/24 7pp 19001 161 24X Fiche 50-413.83/06/24, 8306280084

I Financial information

- 8306200352 Forwards Annual Financial Rept 1982 TUCKER, H B Duke Fower Co B3/06/15 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 18899 101 24X Fithe 50-000.83/06/15.8306200352
- --8306200356 Annual Financial Rept 1982 * North Carolina Municipal Power Agencies 83/06/15 20pp 18899 103 24% Fiche 50-000,83/06/15,8306200352
- O Advisory Committee on Reactor Safeguards reports & correspondence
- 8306170438 Summary of ACRS Subcummittee on Catamba Nuclear Station 830304-05 meetings in Charlotte, NC re GL application review * ACRS - Advisory Committee on Reactor Safeguards 83/05/11 ACRS - Advisory Committee on Reactor Safeguards 39pp 18908 017 24X Ficher 50-413, 83/05/11, 8306170438
- Q Inspection reports. IE Bullotins & carrespondence
- 8306140865 Confirms mgt meeting on B30301 at plant site to discuss self-initiated evaluation of project mgt.design & const of facility

 O'REILLY, J P Region 2. Office of Director. B3/07/10 OMEN, W H

 Duke Power Co 1p 18834 266 24X Fiche 50-413,83/02/10.

 8306140565
- 8306140129 Ack receipt of IE lnsp Repts 50-419/83-03 & 50-414/83 03 No proprietary info TUCKER.H B Duke Power Co 83/04/22 D'REILLY, J.P. Region 2, Office of Director 1p 18839 135 24X Fiche 50-413,83/04/22. 830440129
- 8306140119 Ack receipt of IE Insp Repts 50-413/83-05 & 50-414/83-05 No proprietary info
 TUCKER H B Duke Power Co 63/05/13 D'REILLY, J P Region 2, Office of Director 1p 18839 161 P4X Fiche 50-413,83/05/13, 8306140119
- 8306140123 Ack receipt of IE Insp Repts 50-413/83-06 & 50-414/83-06 No proprietary info TUCKER, H B Duke Power Co 83/05/19 O'REILLY, J P Region 2, Office of Director 1p 18839 162 24X Fiche 50-413,83/05/19, 8306140123
- 8306140664 Forwards IE Insp Repts 50-413/03-07 & 80-414/83-07 on 830426-29 No noncompliance noted. DANCE,H.C Division of Project & Resident Programs 83/05/24 TUCKER,H B Duke Power Co 2pp 18842 050 24X Fiche 50-413,83/05/24,8306140664
- --8306140671 IE Insp Repts 50-413/83-07 & 50-414/83-07 on 830426-29 No noncompliance noted Major areas inspected cable penetration firestops, installation of instrument sensing lines, electrical cable terminations & review of GC records RWFF.A B Region 2. Office of Director CONLON Division of Engineering & Radiological Safety Programs 83/05/20 6pp 18842.052 BAX Fiche 50-413.83/05/24.8306140664
- 8305110458 IE Info Notice 83-32. "Ruptured Am-241 Sources Contained in Hell Logging Device." Svc list encl
 TAYLOR, J M Division of Bafeguards & Inspection Programs (Post 830103). 83/05/26. Consolidated Edison Co of New York, Inc 125pp. 18831.043 24X Fiche 50-000.83/05/26.8305110458

- 8305110460 IE Info Natice 83-34. "Event Notification Info Worksheet a Svc list encl JORDAN, Et Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison to of New York, Inc 115pp 18732 085 24X Fiche 50-000,83/05/26,8305110460
- --B306140502 Responds to NRC 830412 ltr ie violations noted in IE Insp.
 Repts 50-413/83-04 & 50-414/83-04 Corrective actions GA insp.
 group inspected & accepted hanger 1-R-NV-1385 w/location
 outside of tolerance required by drawing
 TUCKER: H B Duke Power Co 63/05/12 O'REILLY, J P Region 2,
 Office of Director 3pp 18836 097 24X Fiche 50-413,83/05/27,
 630614049/
- --8306140506 Forwards IE Insp Repts 50-413/83-04 & 50-414/83-04 on 830315-18 & notice of violation DANCE.H C Division of Project & Resident Programs 83/04/12 TUCKER.H B Duke Power Co 2pp 18038 100 24X Fiche 50-413.83/05/27.8306140497
- --B306140511 IF Insp Repts 50-413/83-04 & 50-414/83-04 on 830315~18
 Noncompliance noted failure to follow procedure & diawings
 for fabrication, erection of hangers, supports & seismic
 controls & component supports
 YORK, J W Region 2. Office of Director BLAKE, J Division of
 Engineering & Radiological Safety Programs 83/04/06 3pp
 18838 103 24X Fiche 50-413,83/05/27,8306140497
- 9305110461 IE Info Notice 63:35, "Fuel Movement W/Control Rods Withdrawn at BWRs " Svc list encl JORDAN,E L Division of Laeigency Preparedness & Engineering Response (Post 830103) 83/05/31 Consolidated Edison Co of New York, Inc 116pp 18732 208 24X Fiche 50-000,83/05/31,8305110461
- 8306290186 Forwards IE Insp Repts 50-413/83-10 & 50-414/83-10 on 830917-20 No noncompliance noted DANCE.H C Division of Project & Resident Programs 03/06/03 TUCKER,H B Dute Power Co 2pp 19056 211 24X Fiche 50-413, 83/06/03, 8306290186
- --8306290192 IE Insp Repts 50-413/83-10 & 50-414/83-10 on 8305:17-20 No noncompliance noted Major areas inspected RCPB piping, safety-related piping & structures & lirensee identified 10CFR50 55e items
 CROWLEY, B R . BLAKE, J J Region 2. Office of Director U3/06/02 8pp 19056 213 24X Fiche 50-413.83/06/03.8306890186
- 8306270376 Forwards IE Insp Repts 50~413/83-09 & 50~414/83-09 on B30516-20 No noncompliance noted DANCE.H C Division of Project & Resident Programs 83/06/03 TUCKER,H B Duke Power Co 2pp 19055 263 24X Fiche 50~413,83/06/03,8306290376
- --8306290404 IE Insp Repts 50-413/83-09 & 50-414/83-09 on 830516-20 No noncompliance noted Major areas inspected preoperational test program review & plant tour TAYLOR, P A Region 2. Office of Director JAPL, F Division of Engineering & Radiological Safety Programs 83/06/04 App 19055 265 24X Fiche 50-413,83/06/03.8306290396
- 830A090305 Forwards Region II 830A02 ltr transmitting notice of violation & proposed imposition of civil penalties in amount of #180.000 for violations noted in IE Insp Repts 50-269/83-11. 50-270/83-11 & 50-289/83-11 JOHNSON, 0 E. Hearing Branch 4 83/06/06 KELLEY, J L Atomic Safety and Licensing Board Panel Spp 18795 179 24X Fiche 50-413.83/06/06.8304090305
- 8304290300 Forwards IE Insp Repts 50-413/83-08 & 50-414/83-08 on 830324-0425 No noncompliance noted DANCE.H.C Division of Project & Resident Programs 83/04/07 TUCKER.H B Duke Power Co 2pp 19056 011 24X Fiche 50-413,83/04/07,8304290300
- --8306290305 IE Imsp Repts 50-413/83-08 & 50-414/83-08 on B30326-0425 No noncompliance noted Major areas inspected followup on NRC identified items: review of nonconforming items; observation of QA training & attendance at INPO mpt meeting VANDOGRN.P K Region 2. Defice of Director. BROWNLEE, V L Division of Project & Resident Programs B3/06/07 4pp 19056.013 24X Fiche, 50-413, 83/06/07, 8306290300

241

- 8305110464 IE Info Notice 83-36, "Impact of Security Practices on Safe
- 305110464 IE info Notice 83-30, Ample:
 Operations "Syc list encl
 JORDAN, E | Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/06/09 Consolidated Edison Co of New
 York, Inc. 119pp 18830 280 24% Fiche 50-000.83/06/09.8309110464
- B305110470 IE Info Notice B3-38, "Defective Heat Sink Adhesive & Seismica)ly Induced Chatter in Relays Within Printed Circuit Cords " Syc list encl JARRON.C L Divirion of Emergency Preparedness & Engineering Response (Post B30103) B3/06/13 Consolidated Edison Co of New York, Inc. 118pp 18920 225 24X Fiche 50-000.B3/06/13.B305110470
- 8306090010 IE Info Notice 83-3/, "Transformer Failure Resulting From Degraded Internal Connection Cobjes " Svc list encl JORDAN, E l Divirion of Emergency Preparedness & Engineering Response (Pust 830103) 83/06/13 Consolidated Raison Co of New York, Inc. 243pp 18921 001 24X Fiche 50-000,83/06/13,8306090010
- B305110475 IE Info Notice B3-40, "Need to Environmentally Qualify
 Epoxy Grouts & Soulers " Svc list encl
 JOBDAN, C L Division of Emergency Proparedness & Engineering
 Response (Post B30103) B3/06/22 Consolidated Edison Co
- 03051104// IE Info Notice 83-41, "Actuation of fire Suppression Sys Causing Inoperability of Safety-Related Equipment" Syc list
 - Division of Emergency Preparedness & Engineering ost 830103) 83/06/22 Consolidated Edison Co. of New 120pp 18997 007 PAX Fiche 50-000,83/06/22,8305110477 JORDAN, E. L. Assponse (York, Inc. (Post
- 8305116479 IE Imfo Notice 83-42, "Reactor Mode Switch Malfunctions " Set list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Past 830103) 83/06/23 Consolidated Edison Co. of New York. Inc. 114pp 18996 242 24X Ficha 50-000, 83/06/23, 8305110477
- DOCKET 50-414 GRAND GULF NUCLEAR STATION, UNIT 1
- A Application/construction stage documents & correspondence
- 0306060091 Add) response to FOIA request for three categories of documents re IMA of reactor safety study methodology application program repts & interim reliability evoluation program repts forwards App A documents bearch continuing FELTON, J M Division of Rules and Records 83/04/07 SHOLLY, Union of Concerned Scientists Opp 10752 001 24X Fiche 50-000, 03/04/07,8306060051 SHOLLY, 9 C
- --B2041204BD Discusses results of Bandia Natl Labs Study, "Reactor Safety Study Methodology Application Program Grand Gulf i BWR PPWTP Plant (NUKEC/CR-1659, Vol 4)" ERNSIAN L. Assistant Director for Technology Review B2/04/04 TEDESCOLR L. Assistant Director for Licensing Ppp 18752:067 24X Fiche 50-000:03/04/07.8506060051
- --830A0A005B Requests meeting w/NRC to discuss concerns to reactal safety study methodology application program Conservative rather than realistic assumptions & calculations used in analysis DALE.L F Mississippi Power & Light Co 81/07/23 DERNERO,R M Division of Rick Analysis 2pp 18/52 016 24X Fiche 50-000,83/04/07,8304040051
- 8306140666 Summarizes 830511 meeting at Region II ofc re changes to Tech Specs required prior to Unit 1 startup Meeting dotails & attended list entl LEMIS.R C Division of Project & Resident Programs 83/05/27 RICHARD.J B Mississippi Power & Light Co. 5pp 18842 089 P4) Fichs 50-416, 83/05/27,8306140666
- E MRC Bafrty Evaluation Report (SER), suppls & correspondence
- B3G6210331 BAFETY EVALUATION REPORT RELATED TO THE OPERATION OF GRAND GULF NUCLEAR STATION.UNITS | & 2 Dockst Nos 50-416 & 50-417 (Mississippi Power And Light Company) # Division of Licensing NUREG-0831 NO4 83/05/31 | 156pp Available at NRC \$5 90 | 18722 177 | 24X Fiche 50-416.83/05/31.8306210331
- 8306200429 Forwards Buppl 4 to SFR, NUREO-0831 W/o encl SCHMENCER, A Licensing Branch 2 83/06/13 MCGAUGHY, J P Mimsissing Power & Light Co. 4pp 18720 019 24X Fichs 50-416,83/06/13,8306200429

- --8306200430 Furwards Suppl 4 to SER W/o encl * Office of Nuclear Reactor Regulation, Director 63/06/13 SIMPSON: A Senate. Environment & Public Works ip 18920 (24% Fiche 50-416.63/06/13.8306200429
- --8306200431 Forwards Suppl 4 to SER H/o entl * Office of Nuclear Reactor Regulation, Director 83/06/13 WDALL H House of Rep . Interior & Insular Affairs ip 18920 024 24X Fiche 50-416.83/06/13.8306200429
- -8306200432 Forwards Suppl 4 to SER W/o enc) * Office of Nuclear Reactor Regulation, Director 83/06/13 OTTINGER.R House of Rep , Energy & Commerce ip 18920 02 24X Fiche 50-416, 83/06/13, 8306200429
- F Security, medical, emergency & fire protection plans
- 8306140519 Confirms 830511 enforcement conference at Region II oft to discuss security violations at facility & Tech Spec changes required prior to nuclear heatup, per 830505 telcon Proposed meeting agenda encl.

 O'REILLY, J. P. Region 2, Office of Director 83/05/06, RICHARD, J. Mississippi Power & Light Co. 2pp 18638 106 24X
 Fiche 50-416,83/05/06,8306140519 83/05/04, RICHARD, J B 04 24X
- 8306140235 Forwards IE Insp Rept 50-416/83-13 on 830329-0401 No noncompliance noted
 VERRELLI,D M Division of Project & Resident Programs
 RICHARD,J B Mississippi Power & Light Co 2pp 188:
 Fichs 50-414,83/05/17,8306140235 rams 83/05/17 18832 353 24
- --8306140244 IE Insp Rept 50-416/83-13 on 830329-0401. No noncompliance noted Major areas inspected exam of procedures & records, personnel interviews & observations re emergency prepareusess CLINE.WE Region 2. Office of Director. JENKINS.O R Division of Emergency Preparedness & Materials Bafety 83/05/13 9pp 18832.355 24X Fiche 50-416.83/05/17.8306140235
- 8306060079 Confirms 830602 telcon re submittal of implementation schedule for backup emergency operations facility by 830617 DALE, L.F. Mississippi Fower & Light Co. 83/06/02 DENTON, H.R. Office of Nuclear Reactor Regulation, Director 19 18719 331 Fiche: 50-414, 83/06/02, 8306060079
- 830A210234 Discusses IE insp on 830429 & 0503-04 & forwards notice of violation & proposed imposition of civil penalty as result of violations identified in IE Insp Rept 50-416/83-17 O'REILLY, J.P. Director's Office, Office of Inspection and Enforcement 83/06/13 RICHARD, J.B. Mississippi Power & Light Co. 2pp 18916 059 24% Fiche 50-416,83/06/13,8306210236
- --8306210243 Notice of violation & proposed imposition of civil penalty in amount of \$40,000 Noncompliance noted security force member-posted to control access to lower containment hatch, found asleep O'REILLV.J.P Director's Office, Office of Inspection and Enforcement 63/06/13 2pp 18916 061, 24X Fiche 50-416,83/06/13.8306210236
- 830.6.210140 Advises that Baxter Wilson plant selected for backup emergency operations facility Telephone capability will be expanded & antennae for offsite radiological monitoring radio will be installed Emergency plan revised DALE, L. F. Hississippi Power & Light Co. 83/06/17 DENTON, H. Office of Nuclear Reactor Regulation, Director 2pp 18914-2 18914-224
- K Utility Final Bafety Analysis Report (FSAR) & amends
- B3042001B4 Forwards Amend 54 to FBAR, updating sections dealing primarily wifire protection & incorporating minor editorial corrections & clarifications to other FSAR sections MCGAUGHY, JP Mississippi Power & Light Co 83/06/17. DENTON, H R. Office of Nuclear Reactor Regulation, Director 3pp 18905, 003 24% Fiche 50-416, 83/06/17. 8306800186
- --8306200189 Amend 56 to FSAR MCGAUGHY, J.P. Mississipp: Power & Light Co. 83, 18905-006 24% Fiche 50-416.83/06/17.8306200186 83/06/30 1,200pp
- P Operating license stage documents & correspondence
- B306060236 Forwards qualification status & compliance summary on environ qualification of electrical equipment important to safety, per 10CFR30 49
 DALE, L. F. Mississippi Power & Light Co. B3/05/20 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 62pp 18728 298, 24X Fiche 80-416, 83/05/20, 8306060236

- 8306010074 Forwards cumments re review of 830118 proposed changes to STB,per informal request Proposed change to Surveillance Requirement 4 & 4 3 re continuous operation of heaters thould not be implemented DALE,LF Mississippl Power & Light Co. 83/05/24 HOUSTON,M D. Division of Licensing 2pp 18673 272 24X Fiche 50-416,83/05/24.
- 8306020286 Application to amend License NFF-13, changing submittal dates for dynamic, inservice insplic communication systems.

 MCGAUGHY, J P Mississippi Power & Light Co 83/05/31 DENTON, H k
 Office of Nuclear Reactor Regulation, Director 5pp 18690 308
 24X Fiche 50~416.83/05/31.8306020286
- 8304140724 Application to amend License NPF-13, consisting of lech Spec Change PCOL-83/OB, per 821020 confirmation of action ltr Changes enhance clarity & provide consistency w/plant design & operation

 DALE: LF Mississippi Power & Light Co 83/06/09 DENTON, H & Office of Nuclear Reactor Regulation, Director 2pp 19841 017 24X Fiche 50-416, 83/06/09, 8306140724
- --8306140729 Proposed Tech Spec Change PCOL-83/08, enhancing charity & providing consistency w/plant design & operation, per 821020 confirmation of action ltr # Hississippi Power & Light Co #63/06/09 72pp 18841 019 24X Fiche: 50-416, 83/06/09, 8306140724
- 830622025B Notification of 830629 meeting w/BWR-Hydrogen Control Dwner: Group in Bethesda. HD to discuss hydrogen control program HOUSTON, D Licensing Branch 2 83/06/09 SCHHENCER, A Licensing Branch 2 7pp 18751 054 24X Fiche 50-416, 83/06/09, 8306220258
- 8306160271 Application to amend License NPF-13 clarifying & providing consistency w/plant design & operation BALE.L F. Mississippi Power & Light Co 83/06/14. DENTON,H R Office of Nuclear Reactor Regulation, Director 2pp 18860 125 24X Fiche 50-416,83/06/14,8306160271
- --8306140274 Proposed changes to Toch Specs re plant design & operation * Mississippi Power & Light Co 83/06/14 46pp 18860 127 24X Fiche 50-416,83/06/14,8306160271
- B306200204 Submits steps taken to satisfy Items 1 C & 3 of License NPF-13 re control room envelope leak tightness test Control room inleakage reduced Allowable inleakage increased & analysis performed verifying SRF (NUREO-0800) conformance DALE: L F Mississippi Power & Light Co 83/06/16 DENTON,H R Office of Nuclear Reactor Regulation, Director 7pp. 18903 236 24X Fiche 50-416,83/06/16.8306200204
- 8306230167 Forwards add1 info re Hydrogen Control Owners Group program, per NRC 830203 request Proprietary & nonproprietary versions of "Grand Gulf Drywell Break Sensitivity Summary" entl Proprietary rept withheld (ref 10CFR2 770)

 DALE: L. F. Mississippi Powor & Light Co. 83/06/16 DENTON, H, R. Office of Nuclear Reactor Regulation. Director. 1jpp 18745.297

 24X Fichs 50-416,83/06/16,8306230167
- --8306230169 Nonproprietary version of "Grand Gulf Drywell Break Sensitivity Summary" GUNTER, A D Offshore Power Systems (subs of Wastinghouse Electric Corp), DPS-39482 RA 83/05/11 397ap 18945 311, 24X Fiche 50-416.83/06/16.8306230167
- 8306290559 Provides list of proposed Tach Spec changes disapproved by NRC.in response to 830024.0407.25.0609 & 14 submittals List should be reviewed & revs submitted SCHWENCER.A Licensing Branch 2 b 83/06/21 MCGAUGHY.J P Mississippi Power & Light Co 3pp. 19046 137 24% Fiche 50-416.83/06/21.8306290559
- 8306270077 Application to amend License NFF-13, changing Tack Specs to enhance clarity or provide consistency w/plant design & operation in this setpoint & function in response to 821020 confirmation of action it:

 DALE: I. F. Mississippi Power & Light Co. 83/06/23 DENTON, H.R. Office of Nuclear Resctor Regulation, Director. 2pp. 19013 234 24X Fiche: 50-416, 83/06/23, 8306270077
- --8306270080 Proposed Tech Spec changes enhancing clarity or providing consistency w/plant design & operation re trip setpoint & function

 * Mississippi Power & Light Co 83/06/23 72pp. 19013 236 24X Fishe: 50-416,83/06/23
- 8306270285 Clarifies capabilities of hydrogen ignition sys under all circumstances.per Schwencer 811106 ltm & NUREO/CR-2486 Under worst case conditions.min voltage required would be 10 08 volts.

 DALC: LF Hississippi Power & Light Co 83/06/23 DENTON.H R. Dffice of Nuclear Reactor Regulation, Director 2pp 18996 196 24X Fiche. 50-416.83/06/23.8306276385

- 8306280505 Forwards affidavit requesting that final test rept, "Gafety Relief Valve In-Plant Discharge Test For Kunsheng Nuclear Power Station: " br withheld (ref JOURY 790 & IOCERS 6)
 DALE, L. F. Mississippi Power & Light Co. 83/06/24 DLNTON, H.k.
 Office of Nuclear Reactor Regulation. Director 2pp. 19019 001
 24% Fishe 30-416.83/06/24.8306280505
- Q Inspection reports, 1E Bulletins & correspondence
- 8306140561 Confirms mgt meeting on 830210 in Jackson, MB to discuss results of review of first phise of annual appraisal of regulatory performance Proposed meeting agenda encl LEWIS.R C. Division of Project & Resident Programs 83/01/26 STAMPLEY, N. L. Mississippi Power & Cight Co. 3pp. 18834 236 24% Fiche 50-416.83/01/28.8306140050
- B306140028 Confirms 630408 mgt meeting at Region II ofc.per 670363 telcon Utij will discuss "Grand Gulf Nuclear Station Operations Enhancement Program " Agenda encl O'REILLY, J.P. Region 2, Office of Director B3703/25 RICHMAD, J.J. Mississippi Power & Light Co. 2pp. 10838-229 249 Fichs 50-416, 83703/25, 8305140078
- 8306140602 Confirms 830420 enforcement conference at Region II off to discuss control of mods & maint & adequacy of corrective action in area of temporary alterations per 830400 & 11 telcons Agenda encl O'REILLY, J.P. Region 2, Office of Districtor 83/04/13 RICHARD, J.J. Mississippi Power & Light Co. 3pp 108/3 175 24X Fiche 30-416,83/04/13,83061404002
- 8306140634 Forwards summary of 830408 meeting in Atlanta GA result)
 B30311 rept, "Grand Gulf Nuclear Station Operations
 Enhancement Program "Implementation will be beneficial to
 plant operations Westendance list
 LEWIS.R C. Division of Project & Resident Programs 83/04/27
 RICHARD.J B Mississipp Power & Light Co. App. 18843-050 (24)
 Fiche 50-416.83/04/29.8306140674
- 830&140519 Confirms 630511 enforcement conference at Region 1) oft to discuss security violations at facility & Tech Spec changes required prior to nuclear heatup, per £J0505 telcon Proposed meeting agenda entl
 O'REMLLY, J P Region 2, Office of Director 83/05/06 RICHARD, J & Mississappi Power & Light Co 2pp 10838 106 24X
 Fiche 50-416,83/05/06,8306140519
- 830&140235 Forwards 1C Insp Rept 50-416/83-13 on 830329-0401 No noncompliance noted VERRELLI.D M Division of Project & Resident Programs, 83/05/17 RICHARD, J B Mississippi Power & Light Co 2pp 18832 359 PAX Fiche 50-416.83/05/17.8306140295
- --0306140244 [E Insp Rept 50-416/03-13 on 030327-0401 No noncompliance noted Major areas inspected exam of procedures & records, personnel interviews & observations to emergency preparedness
 CLINE.N E Region 2. Office of Director JENKINS, 6 R Division of Emergency Preparedness & Naterials Safety 03/05/13 7pp 18032 305 24X Fiche 50-416.03/05/17,0306140235
- 8305110458 IE Info Natice 83-32, "Ruptured Am-241 Sources Contained in Well Logging Device " Svc list enc! TAYLOR, J M Division of Bafeguards & Inspection Programs (Post 830103) 83/05/24 Consolidated Edison Co of New York, Int 125pp 18831 043 24X Fiche 50-000,83/05/24,8303110458
- 8305110460 IE Info Notice 83-54, "Event Notification Info Worksheet"

 8vc list encl
 JORDAN, E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 63/05/24 Consolidated Edison Co of New
 York, Inc 115pp 18732 085 24x Fiche 50-000,03/05/26,0305110460
- 8305110461 IE Info Notice 83-35, "Fue) Novement W/Control Rods Withdrawn at BWRs " Svc list cnc! JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/31 Consolidated Edison Co of New York, Inc 116pp 18732 208 24X Fiche 50-000,03/05/31,8305110461
- 8306020286 Application to amend License NPF-13, changing submittal dates for dynamic, inservice insp & communication sys tests MCGAUGHY, J.P. Mississippi Power & Light Co. 83/05/31 DENTON, H.R. Office of Nuclear Reactor Regulation, Director 5pp 18690 308 24X Fiche 50-416,83/05/31,8306020286
- 8306290236 Forwards IC Insp Rept 50-416/83-20 on 830609 13 No noncompliance noted VERRELLI,D M Division of Project & Resident Programs 83/06/03 RICHARD,J B Mississippi Power & Light Co 2pp 19076 236 24X Fiche 50-416,83/06/03,8306290236

- _#306290244 IE Insp Rept 50-416/83-20 on 830609-13 No noncompliance noted Major areas inspected radiation protection program. including liquid, solid & gaseous preoperational test program % previous inspector identified item. CCILLINS.T R. DARR.K.P. Region 2, Office of Director 03/06/02 opp 19096 238 24% Firhe 50-416,83/06/03,8306290236
- 1304290365 Forwards IC Insp Repts 50-416/83-16 & 50-417/83-05 on 830509-13 No noncompliance noted VERRELLI.D M Division of Project & Resident Programs 83/06/03 RICHARD.J & Mississippi Power & Light Co 2pp 19055 220 24; Fiche 50-416.83/06/03.8306290365
- -6306270371 IE Insp Repts 50-416/83-16 & 50-417/83 Of on 830509-13 No mancompliance noted Major aleas inspected licensee artion in previous enforcement matters, structural concrete, licensee identified items & followup stems

 HARRIS, J. R. Region 2, Office of Director CONLON, T.E. Division of Engineering & Radiological Safety Programs 83/05/31 App 19095 292 24X Fiche 50-416,83/06/03,8306290365
- 1306140450 Ack receipt of 830519 ltr informing NRC of steps taken to correct violations noted in 11 Insp Rept 50-416/83-12 VERRELLI.D M Division of Project & Recident Programs 83/06/07 RICHARD.J B Mississippi Power & Light Co. 1p 18840 187 24X Fiche 50-416.83/06/07.8306140450
- -8306140454 Responds to NRC 830419 ltr re violations noted in IE Insp. Rept 50-416/83-12 Corrective actions walkdown of rach concrete masonry wall w/structural ands performed by Bechtel Field Enganeering performed MCGAUGHY, J.P. Mississippi Power & Light Co. 83/05/19 O'REILLY, J.P. Region 2, Office of Director. 2pp. 18840 188 24X Ficht 50-416,03/06/07.8306140450
- -8305140463 Forwards IE Insp Repts 50-416/83-12 & 50-417/83 04 on 830322-25 & notice of violation VERRELLI, D M Division of Project & Resident Programs 83/04/19 RICHARD, J B Mississippi Power & Light Co 2pp 16840 190 24% Fiche 50-416.83/04/07.8306140450
- --830&1404&8 Notice of violation from insp on 830322-25 * Region 2. Office of Director 87/04/19 2pp 10840 192 24X Fiche 70-416.83/06/07.8306140450
- -8306140474 JE Insp Repts 50-416/03-12 & 50-417/83-04 on B30322-25 Noncomplance noted failure to complete control bldg masonry wall mods in accordance w/drawing repurements LENAHAN, J. J. Region 2, Office of Director CONION, T.E. Division of Engineering & Radiological Safety Programs 83/04/14 7pp 18840 194 24X Fichs 50-416.83/06/07.8306140450
- F306140559 Ack receipt of 830506 ltr informing NRC of steps taken to correct violation & deviation noted in IE Insp Repts 50-416/83-06 & 50-417/83-03 Nutrice of deviation retracted based on 820319 & 0421 ltrs referenced in suppl 2 to SER LEMIS-R C Division of Project & Resident Programs 83/06/07 RICHMRD. J W Mississippi Power & Light Co 1p 18424 220 24% Fichs 50-416,83/06/07.8306140559
- --E306140567 Responds to NRC B30329 ltm me violation & deviation hoted in IE Insp Rept 50-416/83-06 Corrective actions Rev 7 to Procedures 09-8-01-8 & 01-8 07-4 issued & preparation for training in progress MCGAUGHY, J.P. Mississippi Fower & Light Co. B3/05/06 O'REILLY, J.P. Region 2: Office of Director. 3pp. 18834-221, 247 Fichs 50-416,83/06/07,8306140559
- ~8306140569 Forwards IE Insp Repts 90-416/83-06 & 50-417/83 03 on 830215-17 & notices of violation & deviation LEMIS,R C Division of Project & Resident Programs 83/03/27 RICHARD,J B Mississippi Power & Light Co 2pp 18834 724 24X Fiche 50-416.83/06/07.8306140559
- --B3061405/1 Notice of violation from insp on 830215-17 * Region 2, Office of Director 83/03/29 ip 18834 206 24) Fiche 50-416,83/06/07,8306140559
- ~B306140574 Notice of deviation from insp on B30215-17 * Region 2, Office of Director 83/03/29 ip 18834 227 24X Fiche 50-414,83/06/07,8306140559
- ~8306140583 IE Insp Repts 50-416/83-06 & 50-417/83-03 on B30215-17 Noncompliance noted failure to conduct training in facility design changes Deviation from commitments contained in FOAR re shift technical advisor training also noted HERL, C W , NUNRO, J F , CASHATI, M E Region 2, Office of Director B3/03/10 Bp 18834 228 24X Firhe B0-416,83/06/07,8306140897

- 8306270211 Responds to IE Bulletin 83-03 re check valve failures in raw water cooling sys of diesel generators Three check valves in standby svc water sys meet applicable criteria Addl responso will be submitted when valve verification completed RICHARD, J B Mississippi Power & Light Co 83/06/07 O'REILLY, J P Region 2, Office of Director 4pp 19056 130 P4X Fiche 50-416.83/06/07.8306290211
- 8305110464 IE Info Notice 83-36, "Impact of Security Practices on Safe Operations" Svc list encl JDRDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/07 Consolidated Edison Co. of New York, Inc. 117pp 18830 280 24X Fiche 50-000.83/06/09,8305110464
- 9306140724 Application to amend License NPF-13, consisting of Tech Spec Change PCOL-83/08, per 921020 confirmation of action ltr Changes enhance clarity & provide consistency w/plant design & operation DALE.L F Mississippi Power & Light Co 83/06/09 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 18841 017 24X Fiche 50-416,83/06/09,8306140724
- --8306140729 Proposed Tech Basc Change PCGL-83/08, enhancing clatify & providing consistency w/plant design & operation.per 821020 confirmation of action 1tr # Mississipp Power & Light Co 83/06/09 72pg 18841 019 24% Fiche 50-416, 83/06/09, 8306140724
- 8305110470 IE info Notice 83-38, "Defective Heat Sink Adhesive & Seismically Induced Chatter in Relays Within Printed Circuit Cards " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co of New York, Inc 118pp 18920 225 24X Fiche 50-000,83/06/13,8305110470
- 8304070010 IE Info Notice 83-37. "Transformer Failure Resulting From Degraded Internal Connection Cables " Svc list enc] JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/13 Consolidated Edison Co. of New York, Inc. 243pp 18921 001 24X Fithe 50-000,83/04/13,8306090010
- 8306210236 Discusses IE insp on 830429 & 0503-04 & forwards notice of violation & proposed imposition of civil penalty as result of violations identified in 1E Insp Rept 50-416/83-17 (1/REILLY.J.P. Director's Office, Office of Inspection and Enforcement 83/06/13 RICHARD.J.B. Mississippi Power & Light Co 2pp 18916 059 24% Fiche 50-416.83/06/13.8306210236
- --8306210243 Notice of violation & proposed imposition of civil penalty in amount of \$40,000 Noncompliance noted security force member, posted to control access to lower containment hatch, found asleep O'REILLY, JP Director's DfPice, Office of Inspection and Enforcement 63/06/13 2pp 18915 06] 24X Fiche 50-416,83/06/13,8306210236
- 8305110475 IE Info Notice 83-40, "Need to Environmentally Qualify
 Epoxy Grouts & Sealers " Svc list encl
 JDRDAN,E L Division of Energency Preparedness & Engineering
 Response (Post 830103) 83/06/22 Consolidated Edison Co of New
 York, Inc 115pp 19021 179 24X Fithe 50-000.83/06/22.8305110475
- B305110477 IE Info Notice 83-41, "Actuation of Fire Suppression Sys Causing Inoperability of Safety-Related Equipment" Syc list encl JDRDAN, [L. Division of Emergency Preparedness & Engineering Response (Post 830103) B3706/82 Consolidated Edison Co. of New York, Inc. 120pp 18997 007 24X Fichs 50-000,83706/22,8305110477
- 8305110479 IE Info Notice 83-42. "Reactor Mode Switch Halfunctions " Svc list end JORDAN, E. Division of Emergency Preparedness & Engineering Response (Post 830103) 83706/23 Consolidated Edison Co. of New York, Inc. 116pp 18996 242 24X Fiche 50-000,83706/23,8305110479.
- 830A27011A Revises 800319 commitment in response to Question 8 in IE Bulletin 79-08 re maint & test procedures Operations section procedure will specify verification by test or insport of operability of redundant safety-related system. BALEIL F. Hississippi Power & Light Co. 83/04/23 DENTON.H R Office of Nuclear Reactor Regulation. Director 3pp 18988 020 24X Ficho 50-446.83/06/23.8306270116
- 8305110483 IE Info Notice 83-43, "Improper Settings of Intermediate Range (IR) High flux Trip Setpoints " Svc list encl JDRDAN, L L Division of Emergency Preparedness & Engineering Response (Post 820103) 83/06/24 Consolidated Edison Co of New York, Inc 116pp 19046 297 24% Fiche 50-000,83/06/24,8305110483

- R Periodic operating reports & related correspondence
- 8 Reportable occurrences. Ltks & related correspondence
- 9306070237 Updated LER 83-041/03X-1 on 830131, eight penetrations opened in control bidg to allow conduit routing Caused by glanned maint Hourly fire watch conducted for open penetrations Restoration scheduled for 030630 W/830507 ltm RDHRER:N V , NCGAUGHY-J P Nississipp: Power & Light Co B3/05/07 078ELLY, J P Region 2, Office of Director 3pg 18740 293 P4X Fiche 50-416.83/05/09.8304070237
- 8306140303 Summarizes 830420 meeting at Region II ofc reconst deficiency mept on plates embedded in reactor pressure vessel pedestal & newly formed Nuclear Eversight Committee of Middle South Utils Meeting details & attendee list encl LEMISE C Division of Project & Resident Programs 83/05/07 RICHARD, J B Mississippi Power & Light Co Spp 18832 104 24) Fiche 50-416,83/05/07,8306140303
- B306070089 Updated RO 83-001/1 on 830202 smoke detectors in LPUs pump room covered to perform planned activity Hourly fire watch established Work still in progress Rectoration date for smoke detectors estimated for 830615 MCGAUSHY.JP Mississipps Power & Light Co 83/05/17 0'REFLLY.JP Region 2. Office of Director 2pp 18739 153 24X Fiche 50-416.83/05/17.8306070089
- 8306010244 Updated LER 83-039/49X-1 on \$20112, Halon panel IHIJP911 detector A found centinuously alarming w/no fire or smoke & could not be reset Alarm prest Limiting condition of operation lifted on 830503 W/4305P0 ltr MCGAUGHY, J P , BYRD, R Mississippi Power & Light Co 83/05/20 G/REILLY, J P , Region 2, Office of Director 2pp 18672 P90 P4X Fiche 50-416,83/05/20,8304010244
- 9304010241 RD 83-035/0 on 830415, Fire Bour 14401 blocked open to prevent possibility of personnel injury due to high differential pressure across door as result of secondary containment boundary Door to be closed 030630 MC0AUGHY, J.P. Mississippi Power & Light Co. 83/05/20 O'REILLY, J.P. Region 2. Office of Director. 2pp. 18672 289 24% Ficht 50-416.83/05/20.8304010261
- 8306070142 RD 83-037/0 on B30421. Fire Doors 1AP14 & 1A210 opened to route air hoses into adjacent motor control ctr Div I switchgear rooms for planned maint during scheduled electrical outage Doors secured on B30707 MCGAUGHY, J P Mississippi Power & Light Co B3/05/P5 O'REILLY, J P Region 2, Office of Director 2pp 18739 255 24X Fiche: 80-416, 83/05/25, 8306070142
- 8306070230 RD 83-036/0 on 830418 fire-rated penetration DE-20A opened to route cable to supply temporary power to Biv I lighting transformer IXII3 during planned electrical outage Restoration scheduled for 830615 MCGAUCHY, J P Mississippi Power & Light Co 83/05/25 G'REILLY, J P Region 2. Office of Birector 2pp 18746 109 24X Fiche 50-416.83/05/25.8306070270
- 8306070228 RO 83-039/0 on 830414, fire detection rone 2-18 alarmed & would not reset Caused by dust particles on ionization detector. Detectors cleaned & restored to operability on 830505
 MCGAUGHLY, J.P. Mississippi Power & Light Co. 83/05/26
 0'AELLY, J.P. Region 2, Office of Director. 1p. 18744-216. 24: Fiche 50-416,83/05/26,8306070220
- 8366070410 RD 83-038/6 on 830426, control room ambient air temp siceeded area temp limit of lech Spec Table 3 7 8-1 Caused by lack of operating control room HVAC subsys Availability of operability of equipment not affected MCOAUGHY.JP Mississippi Pober & Light Co 83/05/26 O'REILLY.JP Region 2, Office of Director 2pp 18742 P73 PAX Fiche 50-416, 83/05/26, 8306070410
- 8304070004 Updated LER 83-058/01X-1 gn 83031; discovered that fire watches not conducted in two press of fire fatection Zone 2-19 Limiting conditions for operation entered on 830227 Caused by personnel oversight Zone re-tored W/830527 ltr BYRD R , MCGAUGHY, J P Mississippi Power & Light Ca 83/05/27 O'REILLY, J P. Region 2, Office of Director 3pp 18738 344 24 Fiche 50-416,83/05/27.8306070004

- 830,000134 RO 83 040/0 on 8304,24, listed fire nated prestrations :
 to implement design change packages Hourly fire watches
 established a will be meintained Work tasks expected to be
 completed by 630701
 RICHARD, J B. Phisissipp' Power & Fight Co. 83/05/51 B'HEAL
 Region B. Office of Director hop 16/72 256 (44)
 Fiche 50 414, 83/05/31.83(6090) 44
- 8306100251 final Deficiency Rept PRN 82/47 rc potential for pliff flooding based on PMP flood level Wateritight door reals, toe plate & curb to be installed & two penetrations raised Also reportable under Part 21 MCGAUCHY. J P. Nississippi Puwer & Light Co. 83/05/31 D'REILLY. J P. Region 2. Office of Director. Spp. 18907-217 Fiche 50-416.83/05/31.8306100251
- 8304100219 bixth Interim Deficiency Rept PRD-02/14 re sheared bolts diesel generater iser cranked-i cover Initially reported on 820322 Deficiency reportable under 1001kS0 55(e) & Part 21 for Unit i, his vil diesel generate only MCGAUCHY, J.P. Mississippi Fower & Light Co. 83/04/01 D'REILLY, J.P. Region 2, Office of Director App. 18805 18.3 x 14 Ficha 50-416, 63/04/01, 8304100219
- 8306140046 tER 83 021/017-0 on BJ0519, while in cold shutdown, tage gas broadment sys flow monitoring instrumentation found reading in error course by incorrect caliby range Correct caliby range Sisseed W830605 bt BYRD.R. SHINGLERON.B. NGGAUGHY.J P. Nisstasippi Power & 119°T BR30602 D'ARTILLY.J P. Region 2. Office of Director Syp 18638 300 247 fishs 50-416.83/06/02.8306140046
- 8306140084 Updated LER 82-190/99x-2 on 921122, limiting condition of operation entered when five fire rated floor penetrations in auxiliary bldg operad Caused by cable vouting Penetrations resealed W/830602 ltm
 DYRD.R , MCGAVGHY, J P Mississippi Power & Light Co 83/06/6 O'REILLY, J P Region 2, Office of Director 3pp 18838 75/ Fichs 50-416.83/06/02.8306140084
- 8306140384 Updated LER 83-010/97x-1 on B'00105 during insplof collection deficiencie, on redundant raceways similar deficiencies noted in auxiliary turbine & control bidgs Const completion expected by Jul 1983 M/830602 ltr BYRD-R, MCGAUGHY, J.P. Mississippi Pewer & Light Co. 83/66/02 O'REILLY, J.P. Region 2, Office of Director 4pp 18632 415 'Fiche 50-416, 83/66/02.8306140384
- 9306140667 Updated LER 83-052/03Y-1 on BM0411, vessel head & vessel flange thermocouples not physically mounted on respective surfaces Event incorrectly reported dut to inadequate procedures Procedures to be revised by 930701 W/830602 ltr ROMRER.M V. SHINGLEION.E B., NCGAUGHY.J.P. Mississippi Power & Light Co. 93/06/02 0/RCILLY.J.P. Wegion 2, Défice of Diject... 5pp. 16842-094 24X Fiche 50-416.R3/06/02,8306140669
- 8306100235 Final Deficiency Rept PRD-83/06 is failure to provide correction resistant matl in rarbon steel instrument air penetration Initially reported on 830315 Util preparing design change package Also reportable per Part 21 MCGAUGHY, J.P. Mississippi Power & Light Co. 83/06/06 C.RELLY, J.P. Region 2. Office of Director. 4pp. 18807 158: 44 Fiche 50-416, 83/06/06, 83061002/35
- 8306140259 Final Deficiency Rept PRD-83/05 re stress relieving of for sockets by vendor not appearing on AE producted supplier list Initially reported on 830308 Condition not reportable per 10CFR50 55(c) MCGAUGHY.JP Mississippi Power & Light (p. 83/06/06 O'REILLY.JP. Region 2, Office af Director 4pp. 1883 029 24; Fiche 50-416.83/06/06.8306140269
- 8306200121 LER 83-064/01T-0 on #30b24, inconsistencies & problems associated w/oneits chloring storage indentified during internal review of FSAR Caused by lack of administrative controls W/830607 its SHINGLETON, B. MCGAUGHY, J.P. Mississippi Power & Light Co. 83/06/07 0/RILLY, J.P. Region 2, 0493cc of Director Spy 18703 323 24X Fiche 50-416,83/06/07,4/06200121
- 8306200133 Interim Deficiency Rept 3 re Notron stud failures on type and embed places Initially reported on 821271 Unit 1 embed plates replaced wasurface mounted plates linal rept to be submitted by 630705 Also reported per Part 21 MCGAUCHY, J P Mississippi Power & Light Co 83/06/07 O'REILLY, J P Region 2 Deficie of Director 6pp 18903 265 74% Piche 50-416,83/06/07,8306200123

- 8306200250 RU B3 041/0 on 830424, make detectors in upper & lower cable spreading rooms of control bidg were rovered & deactivated to prevent inadvertent actuation from welding activities Detectors instruction overed within 14 days (CGAUGHY.4) P. Mississippi Power & Light Co. 83/06/07 (RERLEY.4) P. Kegion 2. Uffice of Director ip 18701 RRA 249 Fiche 50-416,83/06/07.8305/06.00
- B305140674 EN-B3 041 on B30513 natice of violation & proposed imposition of civil penalty in amount of \$40,000 will be issued Action based on util Paylure to control access to vital area licensee may respond unthin 30 days RDSANUR , AXELRAD, J. Director's Office of Phispection and Enforcement B3/05/08 Ip 18/41 345 24X fichs 50-416,83/06/08,8306140576
- 8306200142 LER 8.3-069/01F-0 on 830926, deficiencies in 18-month battery call & terminal runnection in intance readings identified Caused by personnal error & procedural inadequary Surveillance procedure will be revised WH30609 Iti 398B.R. MCGAUGHY, J.P. Mississippi Proof & Light Co. 03/06/09 0'REILLY, J.P. Reyion 2. Office of birector. 3pp. 18903-24X Fiche 50 416,63/06/09.830620014P
- 8305270439 Second Interim Part 21 Rept P4D-D3/08 re inability to maintain pressurized water supply to 48k pumps & discharge piping Initially reported on 830415 Final rept expected by 840201 RCSAUGHY, J.P. Mississippi Power & Light Co. 82706/13 O'REILLY, J.P. Region 2, Office of Director Spp. 18992 067 2 Fichs 50-416, 83706/13, 8306270439
- 8306280327 Updated RO 83-010/1 on 830209, smoke detectors covered to prevent continuous alarms during grinding & welding Hourly fire watch conducted Zones expected to be rentered by 830630 Add1 fire zone listed HCGAUGHY. J P. Mississippi Power & Light (n. 83/06/13 GTEILLY, J P. Region 2. Office of Director Spp. 19001 279 24) Fichs 50-416, 63/06/13, 6306280769
- 6306270.846 Final Deficiency Rept PRD-82/07 ie two Div 11 cables improperly routed outside scheduled conduit Initially reported on 830412 Design change package issued to rework cables Also reportable per Part 19 for Unit 1 MCGAUDRY, J P Mississippi Power & Light (a 83/04/14 O'ABELLY, J P Region 2, Office of Director 4pp 18796 1922 PAX Fiche 50-416,03/06/14,63062/0.846
- 9306270126 Updated RO 83-015/2 three open penetrations identified Caused by incomplete design drawings or constraint Mail nonconformance repts instituted to correct deficiencies Estimated restoration date is 8307/2; MCQAUGHY. J P Mississippi Power & Light Co 83/06/15 D'REILLY, J P. Region 2, Office of Director 2pp 18788 087 24X Fiche 50-416.05/06/15.0306/701/6
- 8306270132 RO 83-04P/O on 83050%, smoke detectors in certifor of control bldg covered to allow welding Hourly fire watch established Detectors will be restored by 8307P5 MCGAUGHY. J P Mississippi Power & Light Co 93/06/15 O'REILLY, J P Region 2. Office of Director 2pp 18788 147 24X Fiche 50-416,83/06/15,830627017P
- B3062B01BB RG 83 049/0 on 830500, smake detector N524E, in Zone 1 24 (control cabinet room), alarmed continueusly after being bumped by maint worker Fire detection zone declared ingerable Fire watch established No cruse found MCGAUGHY, J P Mississippi Power & Light to 83/06/15 D'RCILLY, J P Region R, Office of Director 1p 17015 003 24 Fiche 50-416, B3/06/13, B3068B0100
- B306280287 RO B3 044/0 on B30509, listed fire-related penetrations opened to implement design change packages Hourly fire watches established within 1 h & maintained for duration of planned maint activities

 MCGAUGHY, I P Mississippi Power & Light Co B3/06/15
 O'REILLY, J P Region 2, Office of Director 3pp 17014 2(6 24)
 Fiche 50-416,03/06/15,8306280/8/
- 8306280471 LER 83-066/OSL-O on 830517, while in cold shutdown, at & dc electrical power distribution weekly linear exceeded late date of B30516 Limiting conditions of aprrations entered Caused by improper scheduling W/830616 ltr

 9YRD,R MCGAUGHY,J P Mississippi Power & Light Co B3/06/16
 0'REILLY,J P Region 2, Office of Director 3pp 19018 191 PAX
 Fiche 50-416,83/06/16,8306280471
- B30A280555 LER B3-06B/01T-0 on 850603, discrepancy noted between Jerh Spec Table 3 & 6 E-1 & FSAR Section 15 7 4 5 2 isolation damper max closure time Tech Spec change requested Procedures revised W/830616 ltr
 BYRD.R. MCGAUCHY, JP Mississippi Power & Light Co 83/06/16, 0/REILLY, JP Region 2, 0ffice of Director 3pp 17017 30/ 24X Fichs 50-416, 83/06/16, 8306280555

- B306270165 RO B3 045/0 on B30515.Fire Doors 00901 & 00503 on east side of control room blocked upen to allow routing of hoses to seal fire-rated penetrations in control room Fire watch astablished Completion expected by B30725 MCGAUGHY.JP Mississippi Power & Light Co 83/06/17 0'REILLY.JP Region 2. Office of Director 2pp 18972 021 24X Fiche 50-416.03/06/17.8306270165
- 8306300175 RO B3 046/O on 830515 during surveillance testing. Fire Deor OC103 found damaged & in constant alarm Caused by damaged latch mechanism due to heavy use Repair work will be completed by 830630 Hourly fire watch established MCGAUGHY. JP Mississippi Power & Light Co 83/06/20 O'RETLLY. JP Region 2. Office of Director 2pp 17119 267 24X Fiche 50-416.83/06/20.8306300175
- 8306300163 RO 83-048/O on 83051/, reactor protection sys motor generator room Fire Door DC412 blocked open to support planned work activity Fire watch established until door restored on 830602 MCGAUGHY, JP Mississippi Power & Light Co 83/06/22 D'REILLY, JP Region 2, Office of Director 1p 19119 279 24% Fiche 50-416,83/06/22,8306300163
- V Operator Examinations
- 8306140102 Requests approved ref math re operator exams by 830531 Missing deadline will delay in administering exams All applications should be submitted at least 60 days prior to first exam scheduled for 830725 VERRELLI
- DOCKET 50-417 GRAND GULF NUCLEAR STATION, UNIT 2
- A Application/construction stage documents & correspondence
- 8306010074 Forwards comments re review of 830118 proposed changes to STS.per informal request Proposed change to Surveillance Requirement 4 & 3 re continuous operation of heaters should not be implemented DALE.L + Mississippi Power & Light Co 83/05/24 HOUSTON, M D Division of Licensing 2pp 18673 272 24X Fiche 50-416.83/05/24, 8306010074
- 8306140666 Summarizes 830511 meeting at Region II oft re changes to Tech Specs required prior to Unit 1 startup Meeting details & attendee list encl LEMIS.R C Division of Project & Resident Programs 83/05/27 RICHARD.J U Mississippi Power & Light Co 5pp 18842 089 24X Fiche 50-416.83/05/27.8306140666
- 8306230167 Forwards add1 info re Hydrogen Control Duners Group program, per NRC 830203 request Proprietary & nonproprietary versions of "Grand Gulf Drywell Break Brasitivity Summary" encl. Proprietary rept withheld tref 10CFR2 790)

 DALE, L. F. Mississippi Power & Light Co. 83/06/16 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 11pp. 18945 299. 24X Fiche 50-416.83/06/16.830623016/
- --8306230167 Nonproprietary version of "Grand Gulf Drywell Break Sensitivity Summary " GUNTER, A D Offshore Power Systems (subs. of Westinghouse Electric Corp.) UPS-39AB2 RA 63/05/11 397pp 18745 311 24X Fiche 50-416.83/06/16.8306230167
- 8306270285 Clarifies capabilities of hydrogen ignition sys under all circumstances.per Schwencer 811106 ltr & NUREQ/CR-2486 Under worst case conditions.mln voltage required would be 10 08 volts

 DALE.L F Mississippi Power & Light Co. 83/06/23 DENTON.H R Office of Nuclear Reactor Regulation, Director 2pp 18996 194 24X Fiche 50-416.83/06/23,8306270205
- E NRC Safety Evaluation Report (SFR), suppls & correspondence
- 8306210331 SAFETY EVALUATION REPORT RELATED TO THE OPERATION OF GRAND GULF NUCLFAR STATION, UNITS I & 2 Docket Nos 50-416 & 50-417 (Mississippi Pawer And Light Company) * Division of Licensing NURGO-0831 904 83/05/31. 156pp Available at NRC \$5 50 10922 197 24% Fiche 50-416.83/05/31, 8306210331
- 8306200429 Forwards Suppl 4 to SER, NUREC-0831 W/o encl SCHWENCER, A Licensing Branch 2 83/06/13 NCGAUGHY, J P Mississippi Pawer & Light Co 4ps 18920 019 24X Fiche 50-416,83/06/13,8306200429

- --8306200430 Forwards Suppl A to SER W/n end: * Office of Nuclear Reactor Regulation. Director 03/06/17 SIMPSON.A Senate, Environment & Public Works lp 18720 023 24X Fiche 50-116.83/06/13.8304200427
- --8306200431 Forwards Suppl 4 to SER W/o encl * Office of Nuclear Reactor Regulation, Director 83/06/1; UDALL.M House of Rep , Intersor & Insular Affairs | Ip 18920 024 24% Fiche 50-416.03/06/13.8306200429
- --B306200432 Forwards Suppl 4 to GLR W/o enci + Office of Nuclear Reactor Regulation. Director B3/06/13 OTTINGER, R House of Rep . Energy & Commerce ip 18920 00°, 24X Fiche 30-416.83/06/13.830620042°
- F Security, medical, emergency & fire protection plans
- 8305140519 Confirms 830511 enforcement conference at Region 11 ofc to discuss security violations at facility & Tech Spec change, required prior to nuclear heatup.per 830505 telcon Proposed meeting agenda encl
 D'REILLY, J P Region 2, Office of Director 83/05/06 RICHARD, J B Mississippi Power & Light Co 2pp 16838 106 24X
 Fiche 50-416.83/05/06.8306140/17
- 8306060079 Confirms 830602 telen re submittal of implementation schedule for backup emergency operations facility by 830617 DALE.L F Mississippi Power & Light Co 83706702 DENTON,H R Office of Nuclear Reactor Regulation. Director ip 18719 331 247 Fiche 50-416.83706702.8306060079
- 9306210140 Advises that Baxter Wilson plant selected for backup emergency operations facility Telephone capability will be expanded & antennae for offsite radiological monitoring radio will be installed Emergency plan revised DALE, L.F. Mississippi Power & Light Co. 83/06/17 DENTON, H. R. Office of Nuclear Reactor Regulation. Director . 2pp. 18914-224 24X Fiche 50-416.83/06/17.8306210140
- K Utility Final Safety Analysis Report (FBAR) & amends
- 8306200186 Forwards Amend 36 to FBAR, updating sections dealing primarily w/fire protection & incorporating minor editorial corrections & clarifications to other F6AR sections MCGAUGHY, J.P. Mississippi Power & Light Co. 83/06/17 DENTON, H.R. Office of Nuclear Reactor Regulation, Director. Sop. 18905.003 24X Fishs 50-416.83/06/17, 8306200186
- --8306200189 Amend 54 to FSAR MCGAUCHY.J P Mississippi Power & Light Co 83/06/30 1.200pp 18905-006 24X Fiche 50-416.83/06/17.8306200186
- Q Inspection reports: IE Bulletans & correspondence
- 8306140561 Confirms mgt meeting on 830210 in Jackson, MS to discuss results of review of first phase of annual appraisal of regulatory performance Proposed meeting agenda encl LEMIS.R C Division of Project & Resident Programs 83/01/28 STAMPLEY, N L Mississippi Power & Light Co 3pp 18834 236 24x Fiche, 50-416, 83/01/28, 8306140561
- 8306140028 Confirms 830408 mgt meeting at Region II afc.por 830323 teleon Util will discuss "Grand Culf Nuclear Station Operations Enhancement Program " Agenda oucl O'REILLY, J.P. Region 2. Office of Director 83/03/25 RICHARD, J.B. Mississippi Power & Light Co. 2pp. 18838 229 PAX Fiche 50-416,83/03/25.8306140020
- 8306140602 Confirms B30420 enforcement conference at Region II ofc to discuss control of mods & maint & adequacy of corrective action in area of temporary alterations, per B30408 & II telcons Agenda encl
 O'REILLY, J.P. Region 2. Office of Director 93/04/13 RICHARD, J.M. Mississippi Power & Light Co. 3pp. 18833 175 24X
 Fiche 50-416.83704/13.8306140602
- 8306140634 Forwards summary of 830408 meeting in Atlants, GA to util 830311 rept, "Grand Gulf Nuclear Station Operations Enhancement Program "Implementation will be beneficial to plant operations W/attendance list LEMIS, R C Division of Project & Resident Programs 83/04/27 RICHARD, U Nississippi Power & Light Co opp 18843 050 RAX Fichs 50-416,83/04/29,8306140634
- B305140519 Confirms B30511 enforcement conforence at Region II of: to discuss security violations at facility & Tech Spec changes required prior to nuclear heatup.per B30505 telcon Proposed meeting agenda encl
 O'REILLY.J P Region 2. Office of Director B3/05/06 RICHARD.J B
 Hissistppi Power & Light Co 2pp 18838 106 24X
 Fiche.50-414.83/05/06.8304140b17

- 8305110458 IE Info Natice 83-J2, "Ruptured Am-241 Sources Contained in Well Logging Device" Svc list on 1 TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 09/05/26 Consolidated Edison Co. of New York, Inc 125pp 18831 040 24% Fishe 50 000, 83/05/26, 8305110458
- #305110460 IE Info Notice #3 34. "Event Nutification Info Worksheet"

 Syc list end!

 JORDAN, L. Division of Emergency Proparedness & Engineering

 Response (Past #30103) #63/09/26 Consolidated Litison Co. of New

 York: Inc. 119pp 18732 085 #24X Fiche 50-000.03/35/26.0405110460
- 8305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rod Withdrawn at BWRs " Svc list encl JORDAN, E L Division of Emergency Properations & Engineering Response (Post 830103) B3/07/31 (Bibolidated Editon Co. of New York, Int. 1166p 18732 200 247 Fiche 50-000.83/05/31.8305110461
- 8306290365 Forwards IE Insp Repts 50-416/83-16 & 50-417/83-05 on 830509-13 No noncompliance noted VERRELLI,D M Division of Project & Resident Programs 83/06/03 RICHARD./ B Mississippi Power & Light (n 2pp 17055-220 24x Fiche 50 416.83/06/03.8306290345
- --83062903/1 IE Imsp Repts 50-416/83-16 & 50-417/83 O5 on 830509 13 No noncompliance noted Major areas inspected licensee action in previous enforcement matters, structural concrete, licensee identified items & followup items HARRIS, J R Region 2, Office of Director CONLON-T C. Division of Engineering & Radiological Safety Programs (63/05/3) 4pp 19055 222 24X Fithe 50 416,03/06/9,3,0306290365
- 8306140450 Ack receipt of 830519 ltr informing NRC of steps taken to correct violations noted in II lusp Ropt 50-416/83 12 VERRELLIB M Division of Project & Resident Programs 83/06/0/ RICHARD, J B Mississappi Power & Light Co ip 18840 18/ 24X Fiche 50-416,83/06/07,8306140450
- --8306140463 Forwards 1E Insp Ripts 50 416/83-12 & 50-417/83-04 on 830322-25 & notice of violation VERRELLI,D N Division of Project & Resident Programs 83/04/19 RICHARD,J B Mississippi Power & Light Co 2pp 18840 190 24) Ficha 50-416,83/06/07,8306140450
- --83064404/4 IE imsp. Repts 50-416/83-12 & 50-417/83 04 on 830322-25 Noncompliance noted failure to complete control bldg masoury wall mods in accordance w/drawing requirements LENAHAN, J. Region 2, Office of Director CONIGN.T.F. Division of Engineering & Radiological Safety Prugrams 83/04/14 7pp 18840 194 24X Fiche 50-416.83/06/07.8306140450
- 8306140557 Ack receipt of 830506 ltr informing NRC of steps taken to correct violation & deviation nated in IE Insp Repts 50-416/83-06 & 50-417/83-03 Nutice of deviation retracted based on 820317 & 0421 ltrs referenced in suppl 2 to SER LEMIS, R.C. Division of Project & Resident Programs 63706/07 RICHARD. J B Mississippi Power & Light Co. 1p 10834 220 24% Fiche 50-416,83/06/07,8306140557
- --8306140569 Forwards 1E Insp Repts 50-416/83-06 & 50-417/83-02 on 830215-17 & notices of violation & deviation LEMIS, R C Division of Project & Resident Proprams 83/03/29 RICHARD, J B Mississipp: Power & Light Co 2pp 18834 224 24X Fiche 50-416,83/06/07,8306140559
- --8306140583 IE Insp Repts 50-416/83 06 % 50-417/83 03 on 830215-17 Noncompliance noted failure to conduct training in facility design changes Deviation from commitments contained in FBAR re shift technical advisor training also noted HEMLO W. NUNRO JF. (ASHATIM L. Region 2, Office of Director 83/03/10 Upp 18834 2/8 24X Fiche 50-416.83/06/07.830614057
- 8306290211 Responds to IE Bulletin 83-03 re check valve failures in raw water cooling sys of diesel generators. Three check valves in standby svc water sys meet applicable criteria Addl responds will be submitted when valve verification completed RICHARD. J B. Mississippi Power & Light Co. 83/06/07 G/HLILLY, J P. Region 2. Office of Director. 4pp. 19096-130. 24X Fiche 50-416.83/06/07.8306290211
- 8305110464 IE Info Notice 83-36, "Impact of Security Practices on Safe Operations " Syc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/09 Consulidated Edison Co of New York, Inc 119pp 18830 280 24% Fiche 50-000,83/06/09,8305110464
- 8305110470 IE Info Notice 83-30, "Defective Heat Sink Adhesive & Seismically Induced Chatter in Relays Within Printed Circuit Cards" "Svc list enc!

 JORDANIE L. Division of Emergency Preparedness & Engineering Response (Pust 830103) 83/06/13 Consolidated Edison Co of New York, Inc. 118pp. 18920 225 24X Fiche 50-000,83/06/13,8305110470

- 830A090010 IE Info Notice 83-37, "Transformer Failure Resulting from Degraded Internal Connection Cables" Svc list encl JORBAN.E | Division of Emergency Preparedness & Engineering Response (Post 630103) 8370A/1J Consolidated Edison Co of New York, Inc. 243pp 18921 001 24X Fiche 50-000.83/0A/13,830A090010
- 830B110475 IC Info Notice 83-40, "Need to Environmentally Qualify
 Epcry Grouts & Sealers " Svc list encl
 JERDAN, E. L. Division of Lamigency Preparadness & Engineering
 Response (Post 830103) 83706/22 Consolidated Edison Co. of New
 York, Inc. 115pp 19021 179 24X Fiche 50-000.83706/22.8305110475
- 8305110477 IE Info Notice 83-41, "Actuation of Fire Suppression Bys Causing Inoperability of Safety-Related Equipment " Syc list encl
- ADROAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 930103) 83/04/22 Consolidated Edison Co. of New York, Inc. 120pp 18997 007 24X Fiche 50-000,83/04/22,8305110477
- 8:05110479 IE Info Notice 83-42, "Reactor Mode Switth Malfunctions " Svc list encl JORDAN.E L Division of Emergoncy Preparedness & Engineering Response (Post 830103) 83706/23 Consolidated Edison Co of New York, Inc. 114pp 18996 242 24X Fiche 50-000,83706/23,8305110479
- 5 Reportable occurrences, LERs & related correspondence
- 830&140303 Summarizes 830420 morting at Region II oft re const deficiency rept on plates embedded in reactor pressure yestel pedestal & newly formed Nuclear Oversight Committee of Middle South Utils Neeting dotails & attendee list encl LEWIS.8 C Division of Project & Resident Programs 83/05/07 RICHARD.J II Mississipp! Power & Light Co 5pp 18832 104 24X Fiche 50-416.83/05/09.8306140303
- 8306100251 Final Deficiency Rept PRD-82/P7 re potential for plant flooding based on PMP flood level Watertight door seals, toe plate & curb to be installed & two penetrations raised Also reportable under Part 21 MCGAUGHY., P Mississippi Power & Light Co. 83/05/31 078EILLY., J P. Region 2, Office of Director Spp. 18807 149 P4X Fiche 50-416,83/05/31,8306100251
- 8306100219 Bixth Interim Deficiency Rept PRD-82/14 re sheared bolts on diesel generator rear crankcase cover Initially reported on 820322 Deficiency reportable under 10C(RSO 55(e) & Part 21 for Unit 1.Div II diesel generator only MCGAUGHY, J P Mississippi Power & Light (o 83/06/01 O'MEILLY, J P Region 2. Office of Director 6pp 18805 183 24X Fiche 50-416,83/06/01,8306100217
- 0306100235 Final Deficiency Rept PRO-83/06 to failure to provide corroston-resistant matt in carbon steel instrument air penetration Initially reported on 830315 Util preparing design change package Also reportable per Part 21 MCGAUGHY, J.P. Mississippi Pawer & Light Co. 83/06/06 07/REILLY, J.P. Region 2, Office of Director. App. 18807 158 P4X Fiche 50-416,83/06/06,8306100235
- 8306140297 Final Deficiency Rept PRD-83/05 re stress relieving of REOB sockets by wender not appearing on AE evaluated supplier list Initially reported on 830308 Condition not reportable per 10CFRDO 55(e)
 MCGAUDHY, J. P. Mississippi Power & Light Co. 83/06/06
 07REILY, J. P. Region 2, Office of Director. 4pp. 1803-073 P4X
 Fiche 50-416,83/06/06,8306140859
- 8306200133 Inturim Deficiency Rept 3 re Nelson stud failures un Type 86 embed plates Initially reported on 821221 Unit 1 embed plates Initially reported on 821221 Unit 1 embed plates Final rept to be submitted by 830705 Also reparted per Part 21 MCGAUGHY, J P Mississippi Power & Light Co 83/06/07 D'AELILY, J P Region 2, Office of Director 5pp 18703 285 24X Ficher 80-416, 83/06/07, 8306200133
- 8306270439 Second Interim Part 21 Rept PRD-83/08 re inability to maintain pressurized water supply to kilk pumps & discharge piping Initially reported on 830415 Final rept expected by 840201 MCGAUSHY, J. P. Hississippi Pawer & Light Co. 83/04/18 D'HEILLY, J. P. Region 2, Office of Director. 5pp. 18992 067 24) Fiche 50-416, 83/04/18 8308270439
- 8306270346 Final Deficiency Rept PRD-83/07 re two Div II cables improperly routed outside scheduled conduit Initially reported on 830412 Design change package issued to rework cables Also reportable per Part 2! for Unit 1 MCOAUGHY. J.P. Mississippi Power & Light Co. 83/06/14 O'REILLY. J.P. Region 2, Office of Director App. 18796-222 P4X Fiche 50-416,83/06/14,8306270346

V Operator Examinations

8306140102 Requests approved ref math re operator exams by 830531 Missing deadline will delay in administering exams All applications should be submitted at least 60 days prior to first exam scheduled for G30725 VERRELLI

DOCKET 50-423 HILLSTONE NUCLEAR POWER STATION, UNIT 3

Application/construction stage documents & correspondence

8306020069 Notification of 830601-02 meetings w/util & 8&W in Bethesda. MD to discuss safety review questions reportions of FSAR DOULITTLE-E L Licensing Branch i 83/05/24 Licensing Branch 1 4pp 18701-338 24X Fichs 50-423.83/05/24.8306020067

8304060143 Submits revised list of joint facility owners All other names should be deleted from svc list COUNSILL W G Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL W G Northeast Utilities 83/05/31 YOUNOBLOOD, B J Licensing Branch I 2pp 18719 022 24X Fiche 50-423.83/05/31.8306060143

8306070459 Forwards request for additinfo re application for OL Requests are result of Instrumention & Control Sys, Reactor Sys, Rectagent Evaluation, Core Performance & Power Sys Branch review of FBAR YOUNGBLOOD, D. J. Licensing Branch 1 83/05/31 CDUNSIL, W.G. Northeast Nuclear Energy Co. (subs. of Northeast Utilities) 7ipp 18780 240 24X Fiche 50-423, 83/05/31, 8306070459

8304080433 Notification of 830602 & 07 meetings w/util in Bethesda, MD to discuss NRC safety review questions reportions of FSAR Meeting originally scheduled for 630601 DODLITTLE, E L Licensing Branch | 83/06/01 YOUNGBLOOD, B J Licensing Branch | 4pp 18/72 189 24X Fiche 50-423, 83/06/01, 83/0680433

8306160412 Forwards draft Rev 5 to "QA Program Topical Rept "
COUNBIL W G Northeast Utilities Service Co 83/06/07 MURLEY, T E
Regian 1. Office of Director App 18859 090 24X
Fiche 50-000,03/06/09,8306160412

--8306160424 Draft Rev 5 to "GA Program Topical Rept " * Northeast Utilities 83/06/09 135pp 18859 096 24X Fiche 50-000,83/06/09,8306160412

8306220167 Notification of 830707 meeting w/util in Waterford & Berlin. CT to discuss applicants responses to GA Branch safety review questions
DODLITTLE, E L Licensing Branch | 83/06/10 YOUNGBLOOD. B J Licensing Branch | 3pp 18737 317 24X Fiche 50-423, B3/06/10, 8306220167

8306230141 Notification of 830629 meeting w/util in Bethesda.MD to discuss specific design info needed by NRC to complete review of RCPB matls Meeting originally scheduled on 830416

DOOLITILE.E L Licensing Branch 1 83/06/21 YOUNGBLOOD.B J Licensing Branch 1 3pp 18954 349 24% Fiche 50-423.83/06/21.830620141

8306230145 Notification of 830726-28 meetings w/util & SkW in Boston, MA to discuss Instrumentation & Control Sys Branch safety review meeting agenda items DODLITTLE.E L. Licensing Branch 1 93/06/21 YBUNGBLOOD.B J Licensing Branch 1 3pp 18954 352 24X Fiche 50-423,83/06/21,8306230145

C Utility Environmental Report (ER), amends & correspondence

8306020045 Notifies of changes in schedule for review of environ rept.
Adjustments will result in Nov 1984 issuance date Bafety
review schedule unchanged Overall licensing schedule not
expected to be affected
NOVAK, T M Division of Licensing 83/05/27 KNICHT, J P Assistant
Director for Comp & Structures Engineering (Pre 830201)
JOHNSTON, W V Assistant Director for Matis & Qualif Engineering
(Pre 830201) MULLER, D R Assistant Director for Radiation
Protection 4pp 18701 358 24X Fiche 50-423,83/05/27,8306020045.

- D NRC Draft/Final Environmental Statements, suppls & correspondence
- B306240077 Notifies of B30720-21 site visit as part of review process for EIS associated w/application for OL Duen public meeting planned on B30721 Agenda encl NOVAK, I M Assistant Director for Licensing B3/06/20 BETTENCOURT, L Materford, CT 3pp 18787 136 24X Fiche. 50-423, B3/06/20, B306240077
- Q Inspection reports, IE Bulletins & correspondence
- 8306060R05 Forwards IE Insp Rept 50-423/83-06 on 830328-0501 No noncompliance noted STAROSTECKI, R Division of Project & Resident Programs 83/05/23 COUNSIL.W O Northeast Nuclear Energy Co (subs of Northeast Utilities) 2pp 18727 339 24X Fiche 50-423,83/05/23,8306060205
- --8306060211 IE Insp Rept 50-423/83-06 on 830328-0501 No noncompliance noted Major areas inspected environ protection commitments, welds in main control room panels, baseline inservice insp of reactor vessel head & licensee reportable items REBELMHSRIT, GRANT, J. ELSASSER, T.C. Region 1, Office of Director 83/05/18 7pp 18727 341 24X Fiche 50-423,83/05/23,8306060205
- 830511049B IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in Hell Logging Device " Svc list encl TAYLOR. J M Division of Safeguards & Inspection Programs (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 125pp 18831 043 24X Fiche 50-000.83/05/26.830511045B
- B305110460 IE Info Notice 83-34, "Event Nutification Info Worksheet"
 Svc list encl
 JURBAN.E L Division of Emergency Preparedness & Engineering
 Response (Post B30103) B3/05/26 Consolidated Edison Co of New
 York, Inc 115pp 18732 0B5 24X Fiche 50-000, B3/05/26, B305110460
- 8305110461 IE Info Notice 83-35, "Fuel Hovement W/Control Rods Withdrawn at BWRs " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/31 Consolidated Edison Co of New York, Inc 116pp 18732 208 24% Fiche 50-000, B3/05/31, B305110461
- 8306200092 Forwards 1E Insp Rept 50-423/83-09 on 8305i0-12 No noncompliance noted
 MARTIN.T T Division of Engineering & Technical Programs 83/06/06 COUNSIL.N G Northeast Nuclear Energy Co (subs of Northeast Utilities) 2pp 18903 345 24% Fiche 50-423/83/06/06/8306200082
- --B306200086 IE Insp Rept 50-423/B3-09 on B30510-12 No noncompliance noted Major areas inspected installation of electrical safety-related equipment FINKEL, A E. ANDERSON. C. Region 1, Office of Director B3/06/01 App. 18903 347 24X Fiche 50-423.83/06/06.8306200082
- 8305110464 IE Info Notice 83-36, "Impact of Security Practices on Safe Operations" Syc list entl JORDAN, EL Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/09 Consolidated Edison Co. of New York, Inc. 119pp 18830 280 24X Fichs 50-000, 83/06/09, 8305110464
- 8305110470 IE Info Notice 83-38, "Defective Heat Sink Adhesive & Seismically Induced Chatter in Relays Within Printed Circuit Cards " Svc list enci JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co of New York, Inc. 118pp 18920 225 24X Fiche 50-000,83/06/13,8305110470
- 9304090010 IE Info Notice 83-37, "Transformer Failure Resulting From Degraded Internal Connection Cables" Svc list encl.

 JURDAN.E I. Division of Emergency Preparedness & Empineering Response (Post 930103) B3706/13 Consolidated Edison Co of New York, Inc. 243pp 18921 001 24% Fiche: 50-000, 83/06/13, 8306090010
- 8305110475 IE Info Notice 83-40. "Need to Environmentally Qualify
 Epoxy Grouts & Sealers " Svc list encl
 JORDAN, E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/06/22 Consolidated Edison Co of New
 York, Inc 115pp 19021 179 24X Fishe, 50-000, 83/06/22, 8305110475
- 8305110477 IE Info Notice 83-41, "Actuation of Fire Suppression Sys Causing Inoperability of Safety-Related Equipment " Syc lint encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/22 Consolidated Edison Co. of New York, Inc. 120pp 18997 007 24% Fiche. 50-000, 83/06/22,8305110477

- 8305110479 IE Info Notice 83-42, "Reactor Mode Bwitch Molfunctions" Syc list encl JORDAN, E.L. Division of Emergency Preparedness & Empinoering Response (Past 830103) 83704723 Consolidated Edison (c. of Kru York, Inc. 116pp 18976-242 24X Fiche 50-000,83706721.8305110477
- 8305110483 IE Info Notice 83-43, "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints " Ove list unell JORDAN,EL Division of Emergency Preparedness & Engineering Response (Post B30103) B3706/24 Consolidated Edison (u of New York, Inc. 116pp 19046 297 24X Fichs 50-000, 83/06/24, 8 0%,11048)
- S Reportable occurrences, LERs & related correspondence
- 8306280346 Interim Bignificant Deficiency Rept 9D-33 re ever water preparation water strainer clogging Initially reparted on 830331 New strainers of increased mesh size will be installed & shaft sleeves replaced by late Fall 1983 COUNSIL.W G Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL.W G Northeast Utilities 83/06/13 MURLEY, TE Region 1. Office of Director 1p 17001 P66 P1X Fiche 50-423,83/06/13,8306280846
- 8304280482 Final Deficiency Rept SD-33 or clogged svc water pump lubricating water strainer Instally reported on 830391 New strainers of increased mesh size & new shaft sleeves wharder sleeve matt will be installed by fall 1993 COUNSIL.W G Northeast Nuclear Energy Co (subs of Northeast Utilities) ODUNBIL.W G Northeast Clubs of Northeast Nuclear Energy Co (subs of Northeast Nuclear Energy Co (subs of Northeast Nuclear Energy Co (subs of Northeast Utilities) B3/06/13 B3/06/18 B
- V Operator Examinations
- 8306140673 Extends invitation to attend 830627 meeting in King of Prossis.PA to discuss transfer of reactor operator licensing function from Bethesda.MD to Region I ofc STAROBTECKI.R Division of Project & Resident Programs (RY/DA/A/V COUNSIL & Q Northeast Nuclear Energy to (subs of Northrist Utilities) 2pp 18842-075 24X Fiche 80-423-83/06/09-81061407/J
- DOCKET 50-424 ALVIN W VOGTLF NUCLEAR PLANT, UNIT 1
- A Application/construction stage documents & correspondence
- 8306140159 Confirms 830302 meeting at Region II oft to discuss field change control for project per 830222 teleon Proposed meeting agenda enci LEMIS.R C Division of Project & Resident Programs 03/02/24 KELLY.R J Georgia Power Co 2pp 10039 034 24X Fithe 50-424.83/02/24.8306140159
- 8306140721 Forwards summary of B30302 mgt meeting in Atlanta.(A le tentative proposals to improve staffing & handling of changes at const site Attendance list encl
 LEWIS.R C Division of Project & Rosident Programs (D)/07/27,
 KELLY.R J Georgia Power Co App 18041 332 24X
 Fiche 50-424.83/03/25,8306140721
- 8906100264 Forwards application for DL. consisting of Suppl 9 to PSAN Chapter 17 re GA Basic GA program not changed significantly Proposed mods to field change request program transmitted on 830504 FOSTER.D Q Georgia Power Co. 83/06/10 O'REILLY.JP Argies J Office of Director 2pp 18804 292 24X Fiche 50-424.01/06/16. 8306100264
- --8306100265 Application for OL.consisting of suppl 9 to PBAR Chapter 17 mg GA FOSTER,D O Georgia Power Co 83/06/10 tp t6504 294 2/4x Fiche 50-424,83/06/10,8306100264
- --8306100267 Suppl 9 to PSAR Chapter 17 re GA * Georgia Power Co 83/06/10 178pp 19804 295 24X Ficha 50-424,83/06/10.8306100264
- 8306240274 Forwards response to criteria for resolution of NUREC GALL, Item II K 3 5, "Automatic Trip of Reactor Coclant Pumps," stated in NRC 830208 Generic Ltr 83-10C Westinghouse Comerc Group program addressing criteria will be evaluated. FOBTER, D 0 Georgia Power Co FOBIER, D 0 Southern Co Hervicet. Inc. 83/06/16 ADENSAM, E G Licensing Branch 4 5pp 18900 1J& 24X Fiche 50-424,83/06/16,8306240274

- B Utility Preliminary Safety Analysis Report, amends
- 8306100264 Forwards application for OL, consisting of Suppl 9 to PSAR Chapter 17 re QA Basic QA program not changed significantly Proposed mods to field change request program transmitted on 830504
 - 830504 FOSTER B D Georgia Power Co 83/06/10 D'REILLY, J P Region 2, Deffice of Director 2pp 18804 292 24X Fiche 50-424, 83/06/10, 8306/100264
- --8306100967 Supp) 7 to PSAR Chapter 17 re GA + Georgia Power Co 83/06/10 173pp 18804 275 24X Fiche 50-424, 83/06/10, 8306100264
- F Security, medical, emergency & fire protection plans
- B30Ai40711 Approves issuance of SALP Repts 50-321/80-06, 50-366/83-06, 50-424/83-06 & 50-425/83-06 for Jul 1781 Oct 1782 LEMIS, R C Division of Project & Resident Programs B3/06/01 MELLY, R J Georgia Power Co 3pp 10341 176 24X Fishe 50-000, 93/06/01, 8306140/11
- ~-8306140717 Advises of 830317 meeting in Atlanta.0A to discuss SALP Repts 50-321/83-06.50-366/83-06.50-424/83-06 & 50-425/83-06 for Jul 1981 - Oct 1982 LEMIS.R C Division of Project & Resident Programs 83/03/09 KELLY.R J Overgia Power Ce Rep 18841 199 24X Fiche 50-000.83/06/01.8306140711
- --8306140730 SALP Repts 50-321/83-06,50-366/83-06,50-424/83-06 & 50-425/83-06 for Jul 1981 Oct 198P No significant util weaknesses identified * Repion 2. Office of Director 83/03/09 38pp 18841 201 24X Fiche 50-000,83/06/01,8306140711
- --8306140743 Ack receipt of SALP Repts 50-321/83-06,50-366/83-06, 50-426/83-06 & 50-425/83-06 for Jul 1781 - Oct 1782 Evaluation acceptable BECKHAM.J T Georgia Power Co 83/04/18 O'REILLY.J P Region 2. Office of Director ip 18841 237 RAX Fiche 50-000,83/06/01, 8306140711
- [Financial information
- 9304070123 Forwards Annual Financial Repts, 1982 QUCHALL T Georgia Power Co 83/06/02 DENTON, H R Office of Nuclear Reactor Regulation, Director ip 18737-038 24X Fiche 50-000, 83/06/02, 8306070123
- --8306070127 Annual Financial Rept, 1982 V007LC, A W The Southern Co B3/03/10 51pp 18739 037 24X Fithe 50-000, 83/06/02, 8306070123
- --8306070130 Annual Finencial Rept.1982 8CHERER, R W., MILLER, J H. Georgia Power Co. 83/03/07 36pp 18739 091 24% Fiche 50-000, 83/06/02, 8306070123
- 4 Inspection reports: IE Bulletins & correspondence
- 8306140432 Forwards IE Insp Repts 50-424/83-07 & 50-425/83-09 on B30425-29 No noncompliance noted DANCE.H.C. Division of Project & Resident Programs B3/05/19 KELEYR J Georgia Power Co 2pp 18838 037 24X Fiche:50-424,83/05/19,8306140432
- --8306140439 IE Insp Repts 50-424/83-09 & 50-425/83 09 on 830425-29 No noncompliance noted Major areas inspected independent insp, containment steel weld heat treatment of structures & supports & visual axem of welds for structures & supports & visual axem of welds for structures & supports YORK, J W. Region 2, Office of Director BLAKE, J J Division of Engineering & Rediological Safety Programs 63/05/18 App 16838 039 24X Fichs 50-424,83/05/19,8306140432
- 830511045B IE Info Notice 83-32. "Ruptured Am-241 Sources Contained in Well Logging Device " Svc list enr! TAYLOR, J M Division of Bafeguards & Inspection Programs (Post B30103) 83/05/26 Consolidated Edison Co of New York, Inc 125pp. 18831:040 24x Fiche, 50-000, 83/05/26, 8305110458
- 8305110460 IE Info Notice 83-34, "Event Notification Info Worksheet" Svc list encl JCRDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 115pp, 18732:085 24X Fiche 50-000,83/05/26,8305110460

- 8306140711 Approves issuance of BALP Repts 50-321/83-06, 50-366/83-06, 50-424/83-06 & 50-425/83-06 for Jul 1981 Oct 1982 LEWIS.R C Division of Project & Resident Programs 83/06/01 KELLY.R J Georgia Power Co Jop 18841 196, 24X Fiche 50-000, 83/06/01, 8306140711
- --8306140719 Advises of 830317 meeting in Atlanta, 0A to discuss BALP Repts 50-321/83-06, 50-366/83-06, 50-424/83-06 & 50-425/83-06 for Jul 1981 Oct 1982 LEMIB, R C Division of Project & Resident Programs. 83/03/09 KELLY, R J Georgia Power Co 2pp 18841 199. 24X Fiche 50-000, 83/04/01, 8306140711.
- --8306140730 SALP Repts 50-321/83-06,50-366/83-06,50-424/83-06 & 50-425/83-06 for Jul 1981 Oct 1982 No significant util weaknesses identified * Region 2, Office of Director 83/03/09 38pp 18841 201 24X Fichs 50-000,83/06/01,8306140711
- --8306140743 Ack receipt of BALF Repts 50-321/83-06, 50-366/83-06, 50-424/83-06 & 50-425/83-06 for Jul 1781 Oct 1782. Evaluation acceptable BECKHAM.J T Georgia Power Co 83/04/18 O'REILLY, J.P. Region 2, Office of Director Ip 18841 237 24X Fiche 50-000,83/06/01,8306140711
- 8305i10464 IE Info Notice 83-36. "Impact of Security Practices on Safe Operations." Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/09 Cansolidated Edison Co. of New York, Inc. 119pp 18830 280 24X Fiche 50-000.83/06/09.8305i10444
- 8305110470 IE Info Notice 83-38. "Defective Heat Sink Adhesive & Salsmically Induced Chatter in Relays Within Printed Circuit Cards" Svc list encl
 JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83706/13 Consolidated Edison Co of New York, Inc 118pp. 18920 225. 24X Fiche 50-000,83/06/13.830510470
- 8304090010 IE Info Notice 83-37, "Transformer Failure Resulting From Degraded Internal Connection Cables " Svc list and JORDAN E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13. Consolidated Edison Co. of New York. Inc. 243pp 18921 001 24X Fichs 50-000.83/06/13.8306090010
- B305110475 IE Info Notice B3-40, "Need to Environmentally Gualify
 Epoxy Grouts & Sealers " Svc list encl.
 JORDAN, E.L. Division of Emergency Preparedness & Engineering
 Response (Post B30103) B3/06/22 Consolidated Edison Co of New
 York, Inc 118pp 17021.179. 24X Fiche 50-000.83/06/22.8305110475
- 8305110477 IE Info Notice 83-41, "Actuation of Fire Suppression Sys Causing Inoperability of Safety-Related Equipment " Syc list encl JORDAN, E.L. Division of Emergency Preparadness & Engineering Response (Post B30103) 83/06/22. Consolidated Edison Co. of New York, Inc 120pp 18997 007 24% Fichs 50-000.83/06/22, 8305110477.
- 8305110479 IE Info Notice 83-42, "Reactor Mode Switch Malfunctions "
 Svc list encl
 JORDAN, E L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/06/23. Consolidated Edison Co. of New
 York, Inc 116pp 18996 242 24X Fishe 50-000.83/06/23.8305110479
- 8305110483 IE Info Notice 83-43, "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints," Byc list and JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/24 Consolidated Edison Co. of New York, Inc. 114pp 17044 297, 24X Fiche 50-000, 83/06/24, 8305110483
- S Reportable occurrences, LERs & related correspondence
- 8306100221 Interim deficiency rapt to embeds 1982 Add1 info required before evaluation can be completed. Info expected by 830610, Final rept will be submitted by 830624. FOSTER, b. O. Georgia Power Co. 83706/01 O'REILLY, J. P. Region 2, Office of Director ip 18805, 353, PAX Ficha: 50-424, 83/06/01, 200180331
- 8306100231 Interim deficiency rept re use of defective math for pinion keys in Limitorque motor operators Initially reported on 820827. Also reportable per Part RI. Rept contains no proprietary info FOSTER. D.O. Georgia Power Co. 83/06/01 O'REILLY. J.P. Region 2. Office of Director Spp. 18807: 189 24X Fiche, 50-424, 83/06/01, 8306100231.
- 8306100257 Interim deficiency rept re Pullman Power Products weld radiograph quality Final rept to be submitted by 830624 FOSTER. D O Georgia Power Co 83/06/01 D'REILLY. J P Region 2, Office of Director 1p 18807 004 24X Fiche: 50-424.83/06/01, 8306100257

- 8306100274 Interim deficiency rept re use of cadwelds as end anchorages Info from AC expected within next month Final rept will be submitted 830729
 FORTER D D Georgia Power Co 83/06/01 O'REILLY, J P Region 2, Office of Director ip 18806 258 24X Fiche 50-424,83/06/01,8306100274
- 8306270166 Interim deficiency rept re Westinghouse DS-416 reactor trip breakers Initially reported on 830505 Util review in grogress Final rept will be submitted by 830909 FOSTER, D.O. Georgia Power Co. FDSTER, D.O. Bouthern Co. Services, Inc. 83/06/13. 0'REILLY, J.P. Region 2. Office of Director ip 18992 020 24X Fiche 50-424, 83/06/13, 8306270166

V Operator Examinations

- 8306140486 Forwards summary of B30503 meeting re NRC policies on senior operator licensing exam Tech Spec memorization requirements Written exam requirements specified in draft Examiner Std EB-402 List of attendess encl DANCE.H C Division of Project & Resident Programs 83/05/24 BECKHAMJ T Georgia Power Co 4pp 18843 090 24X Fiche 50-000.83/05/24.8306140486
- --8306140493 Requests meeting to discuss NRC policies on senior operator licensing exam Tech Spec memoritation requirements Bummary of Tech Spec sections covering required memoritation end!

 BECKHAM, J T Georgia Power Co 83/03/11 HILSDN.B Region 2.

 Defice of Director 2pp. 18843 094 24% Fiche 80-000,83/05/24,8306140486

DOCKET BO-425 ALVIN W VOOTLE NUCLEAR PLANT, UNIT 2

A Application/construction stage documents & correspondence

- 8306140159 Confirms 830302 meeting at Region II ofc to discuss field change control for project per 830222 telcon Proposed meeting agenda encl
 LEMIB:R C Division of Project & Resident Programs 83/02/24
 KELLY:R J Georgia Power Co 2pp 18939 034 24X
 Fiche 50~424.83/02/24.8306140159.
- 8306440721 Forwards summary of B30302 mgt meeting in Atlanta, GA re tentative proposals to improve staffing & handling of changes at const site Attendance list encl LEHIS,R C Division of Project & Resident Programs 83/03/25 KELLY,R J Georgia Power Co 4pp 18841 332 24% Ficha 50-424,63/03/25,8306140721
- 8306100264 Forwards application for OL.consisting of Suppl 7 to PSAR Chapter 17 re GA Basic GA program not changed significantly Proposed mode to field change request program transmitted on 830504 FOSTER, D.O. Georgia Power Co. 83/06/10 O'REJLLY, J.P. Repion 2, Office of Director 2pp 18004 292 24X Fiche 50-424, 83/06/10, 8306100264
- --8306100265 Application for OL. consisting of suppl 9 to PEAR Chapter 17 re GA FOSTER.D O. Georgia Power Co B3/06/10 ip 18804 294 24X Fiche 50-424 03/06/10.0306100264
- 8306240274 Forwards response to criteria for resolution of NUREG-0737, Item II K 3 5. "Automatic Trip of Reactor Cootant Pumps," stated in NRC 830208 Generic Ltr 83-10C Westinghouse Dwners Oroup program addressing criteria will be evaluated FOSTER.D 0 Georgia Power Co FOSTER.D 0 Southern Co Bervices, Inc 83/06/16 ADENBAME G Licensing Branch 4 Spg 18980 126 24X Fiche. 50-424, 83/06/16, 8306240274

B Utility Preliminary Safety Analysis Report, emends

- 8306100264 Forwards application for OL.consisting of Suppl 9 to PBAR Chapter 17 re QA Basic QA program not changed significantly Proposed mode to field change request program transmitted on B30504.
 FOSTER.D D Georgia Power Co 83/06/10. O'REILLY, J P Region 2, Office of Director 2pp 18804 292 24X Fichs 50-424,83/06/10, 8306100264
- --8306100267 Suppl 9 to PBAR Chapter 17 re QA * Georgia Power Co 83/06/10 178pp 18804 295 24X Fiche: 50-424, 83/06/10, 8306100264

F Security, medical, emergency & fire protection plans

- B306140711 Approves issuance of SALP Repts 50-321/B3-06,50-366/B3-06, 50-424/B3-06 & 50-425/B3-06 for Jul 17B1 Oct 17B2, LEWIS.R C Division of Project & Hesident Programs B3/06/01 KELLY.R J Georgia Power to Jpp 18U41 174 24X Fiche 50-000,B3/06/01,8306140711
- --B306140719 Advises of 830317 meeting in Atlanta,0A to discuss SALP Repts 50-321/83-06,50-366/83-06,50-424/83-06 & 50-425/83-06 for Jul 1981 Oct 1982 LEWIS,R C Division of Project & Resident Programs 83/03/07 KECLY,R J Georgia Power Co 2pp 18841 199 24X Fichs 50-000,83/06/01.8306140711
- ---8306140730 SALP Repts 50-321/83-06.50-366/83-06.50-424/83-06.% 50-425/83-06 for Jul 1981 Oct 1982 No significant util weaknesses identified ** Region 2. Office of Director 83/03/09 38pp 18841 201 24k Fiche 50-000.83/06/01.8306140711
- --8306140743 Ack receipt of BALP Repts 50-321/83-06,50-366/83 OA, 50-424/83-06 & 50-425/83 06 for Jul 1781 Oct 1782 Evaluation acceptable BECKHAM, J T Georgia Power Co 83/04/18 O'REILLY, J P Region 2, Office of Director 1p 18841 277 24X Fiche 50-900,87/06/01, 8306140711

I Financial information

- 830&070123 Forwards Annual Financial Repts.1982 QUCMAL T Georgia Pawer Co 8370&702 DENTON.H R Office of Nuclear Reactor Regulation, Director Ip 18739 038 24x Fiche 50-000.8370&702.830&070123
- ---8306070127 Annual Financial Rept.1782 V007LE.A W The Southern Co 83/03/10 51pp 18739 039 24x Fiche 50-000.83/05/02.8306070123
- --8306070130 Annual Financial Rept.1982 SCHERER.R W Georgia Power Co 83/03/07 36pp 18739 091 34x Fiche 50-000.63/06/02.8306070123
- G Inspection reports, 1E Bulletins & correspondence
- 8304140432 Forwards IE Insp Repts 50-424/83 07 & 50-425/83-09 on B30425-29 No noncompliance noted DANCE.H C Division of Project & Resident Programs 83/09/17 KELLY.R J Georgia Power Co Ppp 18038 037 24X Fiche 50-424,83/05/19.8306140432
- --8306140437 IE Insp Repts 90-424/83-09 & 50-425/83-09 on 830425-27 No nancompliance noted Major areas inspected independent insp. containment steel-weld heat treatment of structures & supports & visual exam of welds for structures & supports YORK.J W Region 2. Office of Director BLAKE.J J Division of Engineering & Radiological Safety Programs 83/05/18 App 18838 037 24X Fiche 50-424.83/05/19.8306140432
- 8305110498 IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in Well Lagging Device " Syc list encl TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 125pp 18831 043 24X Fiche 50-000, 83/05/26, 8305110458
- 8305110460 IE Info Notice 83-34, "Event Notification Info Worksheet" Svc list encl Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Pout 830103) 83/05/26 Consolidated Edison Co of New York, Inc 115pp 18732 085 24X Fiche 50~000,83/05/26,8395110460
- 8305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods Withdrawn at BWRs " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Past 830103) 83/05/31 Consolidated Edison Co of New York, Inc 116pp 18732 208 24% Fiche 50-000,83/05/31,8305110461
- 8306140711 Approves issuance of SALP Repts 50-321/83-06, 50-366/83-06. 50-424/83-06 & 50-425/83-06 for Jul 1981 Oct 1982 LEWISLR C Division of Project & Resident Programs 83/06/01 KELLY, R J Georgia Power Co 309 18041 176 24X Fiche 50-000, 83/06/01.8306140711
- --8306140719 Advises of 830317 meeting in Atlanta, GA to discuss SAIP Repts 80-321/83-06.50-366/83-06.50-424/88-06 & 50-425/83-06 for Jul 1981 - Oct 1982 LEWIB, R C Division of Project & Resident Programs 83/03/09 KELLY, R J Georgia Power Co 2pp 18841.199 24X

- --8306140730 SALP Repts 50-321/83-06,50-366/83-06,50-424/83-06 & 50-425/83-06 for Jul 1981 Oct 1982 No significant util weaknesses identified * Region 2, Office of Director 83/03/09 38pp 18841 201 24 Fiche 50-000,83/06/01,8306140711
- --8306140743 Ack receipt of SALP Repts 50-321/83-06, 50-365/83-06, 50-424/83-06 & 50-425/83 06 for Jul 1981 Dct 1982 Evaluation acceptable DECKMAMJ T Georgia Power Co 83/04/18 D'REILLY, J P Region 2, Bffice of Director 1p 18841 219 24X Fiche 50-000, 83/06/01. 83061407/11
- 6305110464 IE Info Notice 63-36, "Impact of Becurity Practices on Safe Operations " Syc list encl JORDAN II t Division of Emergency Preparedness & Engineering Response (Post 630103) 63/06/09 Consolidated Edison Co of New York, Inc. 119pp 16830 280 24X Fichs 50-000,03/06/09.6305110464
- 8305110470 IE info Notice 83-36, "Defective Heat Sink Adhesive & Seismically Induced Chatter is, Relays Within Printed Gircuit Cards " Svc list encl JORDAN, C L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/19 Consolidated Edison Co of New York, Inc. 118pp 18920 225 24X Fishe 50-000, 03/06/13, 8305110470
- 8306090010 IE Info Notice 83-37, "Transformer Failure Acsulting from Degraded Internal Connection Cables " Syc list encl JURDAN E L. Division of Lawrency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co. of New York, Inc. 243pp 18921 001 24X Fiche 50-000,83/06/13,8306090010
- 8305110479 IE Info Notice 83-40, "Need to Environmentally Qualify
 Epoxy Grouts & Scalers " Svc list encl
 JURDANIE L Division of Emergency Proparedness & Engineering
 Response (Post 830103) 83/06/22 Consolidated Edison Co of New
 York Inc 115pp 19021 179 24X Fiche 50-000,83/06/22,8305110475
- 8305110477 IE Info Notice 83-41, "Actuation of Fire Suppression Sys Causing Inoperability of Sofoty-Related Equipment " Svc list and! JORDAN.C L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/22 Consolidated Edison to of New York: Inc 120pp 18977 007 24X Fiche 50-000.83/06/22.8305110477
- E305;10479 IC Info Notice 83-42, "Reactor Mode Switch Malfunctions " Svc list encl JORDAN, EL Division of Emergency Preparedness & Engineering Response (Post 830103) B3/06/23 Consolidated Edison Co of New York, Inc. 116pp 18996-242 P4X Fiche 50-000,83/06/23,8305110479
- 8305110483 IE Info Notice 83-43, "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints "Syr list enc) JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/24 Consolidated Edison Co. of New York, Inc. 116pp 19046-297 24X Fiche 50-000,83/06/24,8305110483
- 8 Reportable occurrences, LERs & related correspondence
- 8304100221 Interim deficiency rept re embeds 1982 Addl anfo required before evaluation can be completed into expected by 830410 Final rept will be submitted by 830424 FOSTER, D Georgia Power Co 83/04/01 O'REILLY, J P Region 2, Office of Director 1p 18805 353 PAX Fiche 50 424,83/04/01, 8304100P21
- 830&100231 Interim deficiency rept re use of defective math for pinion keys in Limitorque mator operators initially reported on 820827 Also reportable per Part 21 Rept contains no proprietary info FOSTER.D.O Georgia Power Co 83/06/01 O'REILLY, J.P. Region 2. Office of Director Spp 19807 189 24X Fiche 50-424.83/06/01, 830&100231
- G306100259 Interim deficiency rept re Pullman Power Products weld radiograph quality Final rept to be submitted by B30624 F09TER, D O Georgia Power Co 83/06/01 O'REILLY, J P Region 2. Office of Director ip 18807 004 24X Fiche 50-424,83/06/01,8306100259
- 8306100274 Interim deficiency rept re use of cadwelds as end anchorages Info from AE expected within next month Final rept will be submitted 830727 FOSTER, D. D. Georgia Power Co. 83/06/01 O'REILLY, J.P. Region 2 Office of Director ip 18806-258 24X Fiche 50-424,83/06/01, 83061002/4

8306270166 Interim deficiency rept re Westinghouse DS-416 reactor trip breakers Initially reported on 830505 Util review in progress Final rept will be submitted by 830909 FOSTER, D.O. Georgia Power Co. FOSTER, D.O. Southern Co. Services, Inc. 83/06/13 D'REILLY, J.P. Region 2, Office of Director ip 18992 020 24% Fiche 50-424.83/06/13.8306270166

V Operator Examinations

- 8306140486 Forwards summary of 830503 meeting re NRC policies on senior operator licensing exam Tech Spec memorization requirements Written exam requirements specified in draft Examiner 3td ES-402 List of attendees enti
- --8306140493 Requests meeting to discuss NRC policies on senior operator literasing exam Tech Spec memorization requirements Summary of Tech Spec sections covering required memorization encl SECKHAM.J T Georgia Power to 83/03/11 WILSON, Bregion 2. Office of Director 2pp 18843 094 24% Fiche 50-000.83/05/24. RS0048040886

DOCKET 50-438 BELLEFONTE NUCLEAR PLANT, UNIT 1

- A Application/construction stage documents & correspondence
- 8304100123 Advises of withholding of certain matl contained in util 830428 transmittal of documentation demonstrating compliance u/Code Case N-192 for use of flexible metal instrumentation home assemblies, per 1005R2 790 Listing of matl encl HILLSIL M Tennessee Valley Authority 83/06/06 ADENSAM.E Licensing Branch 4 2pp 18802 808 24% Fiche 50-438,83/06/06,8306100123
- 8304130340 Informs of suspension of preoperational radiological monitoring activities until 1 yr before plant operation Reimplemented program will reflect appropriate changes in regulatory requirements on monitoring philosophy MILLBL H Tennessee Valley Authority 83/06/07 ADENSAM, E Licensing Branch 4 2pp 18822 210 24X Fiche 50-438,83/06/07,8306130340
- F Security, medical, emergency & fire protection plans
- 8308210010 Forwards "Program Plan for Control Room Design Reviews for all TVA Nuclear Plants." in response to Generic Ltr 82-33 re upgrade of emergency plans KAMMER.D S Tennessee Valley Authority 83/06/09 ADENSAM.E Licensing Branch 4 3pp 18913 001 24X Fiche 50-000.83/06/09, 8306210010
- --8306210016 Procedure B42209 10. "Program Plan for Control Room Design Reviews for all TVA Nuclear Plants " * Tennessee Valley Authorsty 83/06/09 200pp 18913 004 24X Fiche 50-000,83/06/09.8306210010
- 8305290309 Ack receipt of 830524 ltr advising NRC that IE Insp Regts 50-438/83-13 & 50-439/83-13.contain safeguards-related matl Rept will be withheld (ref locrita 21) VERRELL,D M Division of Project & Resident Programs 83/06/15 PARRIE, H 0 Tennessee Valley Authority. 1p 19055:351 24X Fiche 50-438,83/06/15,8306290309
- --8306270319 Responds to NRC 830519 ltr re violations noted in IE Insp Repts 50-438/83-13 & 50-439/83-13 Bafeguards info should be withheld (ref 10CFR73 21) MILLS,L H Tennessee Valley Authoraty 83/05/24 O'REILLY, J P Region 2. Office of Director 1p 17055 352 24X Fiche 50-438,83/04/15,8306270307
- --B306290334 IE Insp Repts 50-438/B3-13 & 50-439/B3-13 on 830301-0430. No noncompliance noted. Major areas inspected const surveillance & licensee action on previous enforcement matters Safeguards info deleted (ref 10CFR73 21) WILCOX,J D Region 2. Office of Director. GUICK, D R Division of Project & Resident Programs 83/05/19 Bpp 19055 395 24X Fiche 50-438, 83/04/15, 8306290309
- O Inspection reports, IE Bulletins & correspondence
- 8306140570 Confirms mpt meeting on B30216 at Region II ofc to discuss results of self-initiated evaluation of activities at facility conducted under INPO guidelines Proposed meeting agenda encl.

 O'REILLY, J. P. Region 2. Office of Director 93/02/09 PARRIS, H 9
 Tennesses Valley Authority Dpp 18844 162 24X
 Ficher 50-438, B3/02/09, B306140570

- 8306140618 Forwards summary of 830216 meeting re licensee-initiated evaluation of const activities, per INPO guidelines (LEMIS.R C Division of Project & Resident Programs 83/02/22 PARRIS.H G Tennessee Valley Authority 4pp 18834 017 24X Fiche 50-438,83/02/22.8306140618
- 8306140543 Confirms mpt meeting on 830421 in Chattanooga. Th to review results of first phase of annual appraisal of regulatory performance, per 830328 telcon LEWIS.R C Division of Project & Resident Programs 83/04/12 PARRIS.H C Tennesses Valley Authority 3pp 18834 176 24X Fiche 50-000,83/04/12.8306140543
- B305i1045B IE Info Notice B3-32, "Ruptured Am-241 Sources Contained in Well Logging Device " Svc list enc! TAYLOR, J M Division of Bafeguards & Inspection Programs (Post B30103) B3/05/26 Consolidated Edison Co of New York, Inc 125pp 18831 043 24% Fiche 50-000.83/05/26.8305110458
- 8305110460 IE Info Notice 83-34, "Event Notification Info Worksheet" Svc list encl
 JORDAN, E L Division of Emergency Preparedness & Engineering
 Response (Past 830103) 83/05/26 Consolidated Edison Co of New
 York, Inc. 115pp 18732 085 24X Fiche 50-000,83/05/26.8305110460
- 8306140143 Ack receipt of 830516 ltr informing NRC of steps taken to correct violations noted in IE Insp Ropts 50-438/83-07 & 50-439/83-07. VERRELLI,D M Division of Project & Resident Programs 83/05/26 PARRIE,H O Tennessee Valley Authority ip 18839 007 24X Fiche 50-438,83/05/26.8306140143
- --8306140150 Responds to NRC 830414 ltr re violations noted in IE Insp Repts 50-436/83-07 & 50-439/83-07 Corrective actions equipment named in violation tagged or returned to instrument test lab for repair or callibr MILLS:L N Tennessee Valley Authority 83/05/16 O'REILLY, J.P. Region 2, Office of Director 7pp 18839 008 24X Fiche 50-438.83/05/26.8306140143
- --8306140157 Forwards IE Insp Repts 50-438/83-07 & 50-439/83-07 on 830307-11 & notice of violation VERRELLI, D M Division of Project & Resident Programs 83/04/14 PARTS, H G Tennessee Valley Authority ip 18839-015 24X Fichs 50-438.83/05/24.8306140143
- --8306140164 Notice of violation from insp on 830307-11 * Region 2, Office of Director 83/04/14 2pp 18839 017 24X Fiche 50-438 83/05/26,8306140143,
- --B306140172 IE Insp Repts 50-438/83-07 & 50-439/83-07 on B30307-ii
 Noncompliance noted failure to control & calibr measuring &
 test equipment & failure to audit several site const
 activities on annual basis
 WRIGHT, R W , UPRIGHT, C M Region 2. Defice of Director 83/04/13
 Epp 18839 019 24X Fiche 50-438.83/05/26.8306140143
- 8306140114 Ack receipt of 830512 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-438/83-05 & 50-439/83-05 VERRELLI.D M Division of Project & Resident Programs 83/05/27 PARRIS.H Q Tennessee Valley Authority Ip 19839 138 24X Fiche.50-438.83/05/27.8306140114
- --8306140125 Responds to NRC 830412 ltr re violations noted in 1E Insp Repts 50-483/83-05 & 50-439/83-05 Corrective actions checklist prepared & issued to unit training afficer delineating documentation requirements for NDE personnel MILLS:L.M Tennessee Valley Authority 83/05/12 0'REILLY, J.P. Region 2, Defice of Director 5pp 18839 139. 24X Fiche 50-436:83/05/27,8306140114
- --8306140131 Forwards IE Insp Repts 50-438/83-05 & 50-439/83-05 on 830214-0304 & notice of violation VERRELLI, D H Division of Project & Resident Programs 83/04/12. PARTS-H O Tennessee Valley Authority 2pp 18839 144 24X Ficher 50-438,83/05/27,8306140114.
- --8306140134 Notice of violation from insp on 830214-0304 * Region 2. Office of Director. 83/04/12 2pp 18839-146, 24% Fiche: 50-438.83/05/27,8306140114
- --8306440139 IE imsp Repts 50-438/83-05 & 50-439/83-05 on 830214-0304 Noncompliance noted sufficient records affecting quality such as qualification of GC personnel not maintained, YORK, J W., LIU, H. C., BLAKE, J Region 2, Office of Director. 83/04/06 13pp. 18839 148. 24X Fiche 50-438,83/05/27,8306140114

- 8304140757 Concurs w/util position contained in 821109 ltr supporting denial of violation identified in IE Insp Repts 50-438/82-24 & 50-439/82-24 Violation will be deleted from NRC records VERRELLI, D.M. Division of Project & Resident Programs 83/05/27 PARRIS, N.G. Tennessee Valley Authority in 18841 195 24X Fiche 50-438, 83/05/27, 8304140757
- 8309110461 IE Info Notice B3-35, "Fuel Movement W/Control Rods Withdrawn at BWRs " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/31 Consolidated Edison Co of New York, Inc. 116pp 18732 208 24X Fiche 50-000.83/05/31.8305110461
- 8305110464 IE Info Notice 83-36, "Impact of Security Practices on Safe Operations " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/07 Consolidated Edison Co of New York, Inc 117pp 18830 280 24X Fiche 50-000.83/06/09.8309110464
- 8306290231 Forwards 1E Insp Repts 50-438/03-12 & 50-439/03-12 on 830516-20 No noncompliance noted VERRELLI:D M Division of Project & Resident Programs 83/06/09 PARRIS,N 6 Tennessee Valley Authority 2pp 19056 087 24X Fichs 50-438,83/06/09,8306290231
- --B306290235 IE Insp Repts 50-438/83-12 & 50-439/83-12 on 830516-20 Na noncompliance noted Major areas inspected previous enforcement matters, safety-related pipe support & restraint sys & licensee action on previously identified insp items YORK, J W , BLAKE, J J Region 2, Dffice of Director 83/06/06 5pp 19056 089 24X Fiche 50-438.63/06/09.8306290231
- 8305110470 IE Info Notice 83-38, "Defective Heat Sink Adhesive & Beismically Induced Chatter in Relays Within Printed Circuit Cards " Svc list encl JORDAN, E L Division of Emergency Preparadness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co of New York, Inc 118pp 18920 225 24X Fiche 50-000,83/06/13,8305110470
- 8306090010 IE Info Notice 83-37, "Transformer Failure Resulting From Degraded Internal Connection Cables " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83706/13 Consolidated Edison Co of New York, Inc 243pp 18921 001 24X Fiche 50-000.83706/13.8306090010
- 8306290309 Ack receipt of 830524 ltr advising NRC that IE Insp Repts 30-438/83-13 & 50-439/83-13 contain safeguards-related math Rapt will be withheld (ref 10CFR73 21)

 VERRELLI, D M Division of Project & Resident Programs 83/06/15 PARRIS, H 0 Tennessee Valley Authority 1p 19055 391 24X Fiche 50-438, 83/06/15,8306290309
- ---8306270319 Responds to NRC 830519 ltr re violations noted in If Imp Repts 50-438/83-13 & 50-439/83-13 Safeguards info should be withheld (ref 10CFR73 21) MILLB, L M Tennessee Valley Authority. 83/05/24 D'REILLY, J P Region 2. Office of Director ip 19055 352 24X Fiche 50-438.83/06/15.8306290309
- --8306290365 Forwards IE Insp Repts 50-438/83-13 & 50-439/83-13 on 830301-0430 No noncompliance noted VERRELLI, D N Division of Project & Resident Programs D3/05/19 PARRIS, H G Tennessee Valley Authority 2pp 17055 353 P4X Fichs 50-438,83/06/15,8306290309
- --8306290334 IE Insp Repts 50-438/83-13 & 50-439/83-13 on 830301-0430 No noncompliance noted Major areas inspected const surveillance & licensee action on previous enforcement matters Safaguards info deleted (rep locf873 21) WILCOX, U D Region 2. Office of Director GUICK, D R Division of Project & Resident Programs 83/05/19 Spp 19055 355 24X Fiche 50-438,83/06/15,8306290309
- 8306290483 Approves issuance of BALP Repts 50-259/83-04,50-260/83-04, 50-296/83-04,50-326/83-04,50-326/83-04,50-396/83-07,50-391/83-04,50-438/83-06 & 50-439/83-06 for Jul 1981 Dec 1982 No reply required O'REILLY,JP. Region 2, Office of Director 83/04/17 PARRIE,H 9 Tennesse Valley Authority 3pp 24X Fiche 50-000,83/06/17,8306290483
- --8306290490 Forwards SALP Repts 50-259/83-04, 50-260/83-04, 50-295/83-04, 50-327/83-04, 50-328/83-04, 50-390/83-07, 50-391/83-06, 50-438/83-06 & 50-439/83-06 For Jul 1981 Dec 1982 LEWIS, R C Division of Project & Resident Programs 83/04/13. PARRIS, H, G Tannessee Valley Authority 3pp PAX Fiche 50-000, 83/06/17, 8306270483

DOCKETED ITEMS

- --8306290503 SALP Repts 50-259/83-04.50-260/83-04.50-296/83-04. 50-327/83-04.50-328/83-04.50-390/83 07.50-391/83-06. 50-438/83-06 & 50-439/83-06 for Jol 1781 - Dec 1782 * Region 2. Office of Director B'1/04/13 72pp 24X Fiche 50-000.83/06/17.8306290483
- --8306290510 Comments on SALP Repts 50-257/83-04, 50-260/83-04, 50-294/83-04, 50-294/83-04, 50-329/83-04, 50-391/83-06, 50-438/83-06 & 50-439/83-06 for Jul 1981 Dec 1982

 MILLS.L M Tennessee Valley Authority 83/05/10 O'REILLY, J. P. Region 2. Office of Director 2pp 24X Fiche 50-259, 83/06/17, 8308290483
- 8306290239 Ack receipt of 830610 ltm informing NRC of steps taken to correct violations noted in II Insp Repts 50-438/81-27 & 50-439/81-29 VERRELLI.D M Division of Project & Resident Programs 83/06/20 PARRIS.H O Tennessee Valley Authority ip 19036-244 D4X Fiche 50-438, 83/06/20.8306290239
- --8306290246 Submits supplemental response to NRC 811208 ltr re violations noted in IE Insp Repts 50-438/81-29 & 50-439/81-29 Corrective actions letdown coalers to be installed upon receipt of IRW info re support deficiencies MICLS.L M Tennessee Valley Authority 83/06/10 O'REILLY, J P Region 2, Office of Director 2pp 19056 245 24X Fiche 50-438,83/06/20,8306270239
- 8305110475 IE Info Notice 83-40, "Need to Environmentally Qualify
 Epozy Growts & Sealers " Svc list encl
 JORDAN.E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/06/22 Consolidated Edison Co of New
 York Inc 1155p 19021 179 24X Fiche 50-000.83/06/22.8305110475
- 8305110477 IE Info Notice 83-41, "Actuation of Fire Suppression Sys Causing Inoperability of Safety-Related Equipment" Syc list enc1 JORDAN: C L Division of Emergency Preparedness & Engineering Response (Pust 830103) 83/06/22 Consolidated Edison Co of New York: Inc 120pp 18997 007 24X Fiche 50-000.83/06/22,8305110477
- 8305110479 lE Info Notice 83-42, "Reactor Mode Buitch Malfunctions " Svc list entl JORDAN.E. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/23 Consolidated Edison Co of New York, Inc. 114pp 18996 242 24X Fiche 50-000,83/06/23,8305110479
- G3051104B3 IE Info Notice 83-43, "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints "Syc list encl JURDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) B3/06/24 Consolidated Edison Co. of New York, Inc. 1146pp 17046 297 24X Fiche 50-000.83/06/24.8305110483
- S Reportable occurrences, LERs & related correspondence
- B30A070072 Fifth interim deficitncy rept re engineering change notice review & handling Initially reported on B11215 Personnel retrained & corrective actions presented to Offc of GA for approval Addl info will be submitted by 830722 MILLS.L M Tennesses Valley Authority 83/05/24 O'REILLY, J P Region 2. Defice of Director 2pp 161/40 085 24X Fiche 50-000,03/05/24,8306070072
- 8306010251 Third interim deficiency rept re underdesigned snubber on main feedwater piping in Valve Room B Initially reported on 821013 Process of documenting completed, Analysis & review underway, Next rept by 840118
 HILLS.L M Tennesse Valley Authority 83/05/25 G'REJLLY, J. P. Region 2. Office of Director ip 18673 033 24X
 Fiche 50-438,83/05/25,8306010251
- 830&010274 Third interim deficiency ropt re sheared motor pinion keys in Limitorque motor operators Initially reported on 820830 Field change notices issued to replace keys Next rept will be sent by 830922 Also reportable per Part 21 MILLS.L M Tennessee Valley Authority 83/05/25 D'REILLY, J P Region 2, Office of Director 2pp 18674:322 24X Fiche 50-000, 93/05/25, 8306010274
- 8306010405 Fourth interim deficiency rept re failure of BIF butterfly valve seats Initially reported on 820511 Valves returned to BIF & tested satisfactorily Final rept by 830801 Also reportable per Part 2] MILLS.L M Tennessee Valley Authority 83/05/25 D'REILLY, J P Region 2, Office of Director. 2pp 18679 328 24X Fiche 50-438.83/05/25.8306010405

- 8304010431 Second interim deficiency rept re corrosion in high pressure fire protection sys Initially reported on 820903 Sys contains carbon steel piping Corrosion analyses in progress. Next rept to be submitted by 821004 MILLS.L M Tempessee Valley Authority 83/05/25 O'REILLY.J P Region 2. Office of Director 2pp 18674 255 24X Fiche 50-000.83/05/25,8304010431
- 8306070074 First interim deficiency rept to incorrect max pipe movements contained in TPIPE gragram Initially reported on 830504 M/o encl Next rept expected by 830922 MILLS,L M Tennessee Valley Authority 83/05/26 O'REILLY, J P Region 2, Office of Director ip 18739 319 24X Fiche 50-000.83/05/26.8306070074
- 8306070121 Second interim deficiency rept re failure of Ingersoll Rand air compressor motor Initially reported on 821209 Replacement of stators w/Class IE motors initiated & cause & corrective actions investigated Next rept by 840109 MILLS, L. N. Tennessee Valley Authority 83/05/26 O'REILLY, J.P. Region 2. Office of Director 2pp 18739 314 24X Fiche 50-438.83/05/26.8306070121
- 8306070160 Fifth interim deficiency rept re defects in reactor protection & ESF actuation sys modules supplied by Bailey Meter Co Initially reported on 820414 B&W investigating use of yellowish bonding agent Also reportable per Part 21 MILLS, L M Tennessee Valley Authority 83/05/26 O'REILLY, J P Region 2. 04fice of Director 3pp 18706 288 24X Fiche 50-438,83/05/26,8306070160
- 830607018B Final rept re deficient weldolets on NAVCO spool pieces Initially reported on 820224 Five weldolets on spool pieces IND-196,178,200,202 & INV-242 do not conform to A9ME Bection III Not reportable per 100FRSO 85(e) MILLS, L M Tennessee Valley Authority 83/05/27 O'RCILLY, J, P. Region 2. 0ffice of Director 2pp. 18736 279 24X Fiche 50-438,83/05/27,8306070188
- 8304070138 Third interim deficiency rept re voiding of engineering change notices \(\omega / \omega \) proper review Initially reported on 820816 Change notices being reviewed & unresolved safety question determination performed Next rept by 830923 MILS.L M Tennessee Valley Authority 83/05/31 O'REILLY, J P Region 2. Office of Director 2pp 187/39 264 24X Fiche 50-000,83/05/31,8304070138
- 8306090310 Second interim deficiency rept re tube leaks in component cooling water HKs Initially reported on 830218 Corrosion pitting revealed by metallurgical exam Alloys investigated for replacement MILLS.L M Tennesse Valley Authority 83/06/03 O'REILLY, J P Region 2. OFFice of Director 3pp. 18779 193 24X Fiche 50-438,83/06/03.8306090310
- 830.6200141 Sixth interim deficiency rept to Viking flow control valves in fire protection sys Initially reported on Bili24 Drawing rev review continuing Next rept to be submitted by 830809 Also reportable per Part 21 MILLS, L.M. Tennesse Valley Authority 83/06/07. O'REILLY, J.P. Region 2. Office of Director 1p 18903 264. 24% Fiche 50-438,83/06/07,6306200141
- 8306200143 First interim deficiency rept me failure to specify IEEE class of safety-melated sys components on procurement specs. Initially reported on 830509 Suppliers being contacted Next rept to be submitted 831119
 MILES.L M Tennessee Valley Authority 83/06/09. O'REILLY, J. P. Region 2, Dfrice of Director 2pp 18703 289 24X
 Fiche 50-438,83/06/09.8306200143
- 8306210051 Supplemental interim deficienty rept re potentially overstressed embedded plates Initially reported on 820412
 Next submittal scheduled for 840217 instead of 830622 as originally stated
 MILES.L.M. Tennesses Valley Authority. 83/06/10. D'REILLY.J.P. Region 2. Office of Director. ip. 18714 009 24X
 Fiche 50-000,83/06/10,8306210051
- 8304210005 First interim deficiency rept re max temp inside containment Initially reported on 830513. Util requested B&W to respond to nonconformance rept by 830715. Next rept to be submitted by 830925 Also reported per Part R1, MILLS.L M Tennessee Vallay Authority. 83/05/13, 0'REILLY, J. P. Region 2. Office of Director. Rpp. 18912-283 24X Fiche 50-438,83/06/13,8304210005.
- 8306210018 First interim deficiency rept re B&W plant internal bolt failures Initially reported on 830513.8&W & B&W Damers Group assessing situation to determine scope of problem & corrective actions. Next rept to be submitted by 831206 MILES.L M Tennessee Valley Authority 83/06/13 0'REILLY, J. P Region 2. Office of Director. 2pp 18714-237. PAX Fiche: 50-438, 83/06/13, 8306210018

- 8306210252 Second interim deficiency rept re failure to identify grade of nots due to orientation w/grade maikings facing against structural member Initially reported on 830126 Testing in progress Next rept by 830930 MILLS.L M Tennessee Valley Authority 83/06/14 U/REILLY.J P Region 2. Office of Director 2pp 10718 099 24X Fiche 50-438.83/06/14.8306210252
- 8306210004 First interim deficiency rept re in-core monitoring sys Dutchman pipes offset from longitudinal axis of pipe runs Initially reported on B30516 Util requested B&H to advise of corrective action Next rept to be submitted on B30024 MILLS.L M Tennessee Valley Authority B3/06/15 0'REILLY, J P Region 2. Office of Director 2pp 18911 340 PAX Fiche 50-438.83/06/15.8306210004
- 8306210042 Fifth interim deficiency rept re seismic analysis of auxiliary control bldg Initially reported on 820226 Beismic analysis rept revised & two new walls will be constructed Next rept to be submitted by 840622 MILLS.L. N. Tennessee Valley Authority 83/06/15 O'REILLY, J.P. Region 2. Office of Director 2pp 10912 299 24X Fiche 50-438,83/06/15.8306210042
- 8306280479 Final deficiency rept re improperly welded chiller unit piping components Initially reported on 820111 Radiographic exam to be performed on all safety-related chiller piping Also reportable per Part 21 MILLS.L M Tennessee Valley Authority 83/06/17 0'REILLY, J P Region 2. Office of Director 3pp 19020 116 24X Fiche 50-438,83/06/17,8306280479
- 8306280578 Interim deficiency rept re resolution of listed items dur for submittal in late June Corrective actions in plugress List identifying each item, schedule for next submittal & level of interim rept encl MILLS.L M Tennessee Vailey Authority 83/06/17 O'REILLY, J R Region 2, Office of Director 2pp 19018 193 24X Fiche 50-000,83/06/17,8306280578
- 8306280619 Fourth interim deficiency rept re incorrect installation of pressure relief & safety valves Initially reported on 830305 Two 3-inch relief valves.exhausting into waste disposal header.added Next rept to be submitted by 840718 MTLLS.L M Tennessee Valley Authority 83/06/17 0'REILLY, J P Region 2. Office of Director 2pp 17016 001 24X Fiche.50-438.83/06/17.8306280619
- 8306280092 Second interim deficiency rept re disruption & collapse of sodium hydroxide storage tank Initially reported on 82:124, Const Test Procedure DNP-CTP-6 I revised to include positive measures for monitoring tank levels Next rept by 83:1216 MILLS,L M Tennessee Valley Authority 83/06/20 D'(REILLY, J P Region 2, Office of Director 25pp 19001 131 24X Fiche: 50-438.63/06/20,8306280092
- 8306280367 Second interim deficiency rept re incorrect seismic pipe support insps Approx 3.600 completed insp records for rigorously analyzed supports identified Support location will be shown on detail drawings Next rept by 631213 MILLS.L M Tonnessee Valley Authority 83/06/20 0'REILLY, J P Region 2.0ffice of Director 2pp 17014.083 24X Fiche 50-438.83/06/20.8306280369
- 8306280425 Fourth interim deficiency rept re B&W design of RCS supports & restraints Initially reported on 820601 Majority of alocks installed Shear bar evaluation expected by 830801. Also reported per Part 21 MILLS.L M Tennesse Valley Authority 83/06/20 0'REILLY, J P Region 2, Office of Director 2pp 17020 300 24X Fiche 50-438,83/06/20,8306280425
- 8304300254 Final deficiency rept re overpressurized sys during flushing Initially reported on 821130 Drawings of affected pipes & valves revisued & evaluated Item determined not reportable per 10CFRSO 35(e)
 MILLS.L M Tennessee Valleg Authority 83/06/21 0'REILLY, J P Region 2, Office of Director 2pp 19119 208 24X Fiche 50-438,83/06/21,8306300254
- 8306300157 Part 21 rept re spot welds in Bailey Controls Co cabinets w/smaller diameter than specified Cabinets strengthened by seam & edge welding or builting TAYLOR. J H Babcotk & Hilcox Co 83/06/23 DEYOUNG. R C Director's Office. Office of Inspection and Enforcement 2pp 19119 308 24X Fiche 50-000.83/06/23.8306300159
- 8304500214 Second interim deficiency rept re tubeline maths supplied by Capitol Pipe & Steel not mfg under GA program Initially reported on 830329 Contractor will perform dimensional checks for pipes & Pittings Next rept by 830922 MILLS, L.M Tennessee Valley Authority 83/06/23 D'REJLLY, J. P. Region 2, Office of Director Spp 19119 351 24% Fiche 50-000,83/06/23,8306300214

- 8306300008 Fourth interim deficiency rept re possibility of exceeding turbine driven auxiliary feedwater pump room temp Initially reported on 811006 Fan motors will be replaced Next rept by 840430 MTLLS.L M Tennessee Valley Authority 83/06/24 O'REILLY, J P Region 2. Office of Director 2pp 19120 317 24X Fiche 50-438.83/06/24.8306300008
- 630.6300.245 Final deficiency rept re analysis for loss of feedwater event Initially reported on BIO316 Util does not consider subj monconforming condition adverse to safe operation of plant Condition not reportable per IOCFR50 55(e) MILLS.L.M. Tennesse Valley Authority 63/06/24 O'REILLY, J.P. Region 2. Office of Director 2pp 19119 341 24X Fiche 50-438,83/06/24,8306300745
- DOCKET 50-439 BELLEFONTE NUCLEAR PLANT, UNIT 2
- A Application/construction stage documents & correspondence
- 8304100123 Advises of withholding of certain math contained in util 830428 transmittal of documentation demonstrating compliance w/Code Case N-192 for use of flexible metal instrumentation hose assemblies.per 100FR2 770 Listing of math encl MILLSL M Tennessee Valley Authority 83/06/06 ADENSAN,E Licensing Branch 4 2pp 18802 008 24X Fiche 50-438,83/06/06,8306100123
- B304130340 Informs of suspension of preoperational radiological monitoring activities until 1 yr before plant operation Reimplemonted program will reflect appropriate changes in regulatory requirements on monitoring philosophy MILLS, L N Tennessee Valley Authority 63/04/07 ADENBAN, E Licensing Branch 4 2pp 18022 210 247 Fiche 50-438,83704/07,83061303040
- F Security, medical, emergency & fire protection plans
- B304210010 Forwards "Program Plan for Control Room Design Reviews for all TVA Nuclear Plants," in response to Generic Ltr 92 33 re upgrade of emergency plans KAMMER. D S Tennessee Valley Authority 83/06/09 ADENGAH, Licensing Brench 4 3pp 18913 001 24X Fiche 50-000.83/06/09, 8306210010
- --8306210016 Procedure 862209 10, "Program Plan for Control Runm Design Reviews for all TVA Nuclear Plants " * Tennessee Valley Authority 83/06/09 200pp 18913 004 P4X Fiche 50-000.83/06/09,8306210010
- 8306290309 Ack receipt of 830524 ltr advising NRC that IF Insp Repts 50-438/83-13 & 50-439/83-13, contain safeguards-related matl Rept will be withhold (ref 10CFR3 21)
 VERRELLI, D M Division of Project & Resident Programs 83/06/15 PARRIS, H 0 Tennessee Valley Authority 1p 19055-351 /4X Fiche 50-438, 83/06/15, 8306290309
- --8306290319 Responds to NRC 830519 ltr re violations noted in IF Insp Repts 50-438/83-13 & 50-439/83-13 Safequards info should be withheld (ref 10CFR73 21) MILLS:I. M. Tennessee Valley Authority 83/09/24 O'REINLY,J' Region 2, Office of Directo: ip 19055 352 24X Ficho 50-438.03/06/15.8306290309
- --8306290334 IE Insp Repts 50-438/83-13 & 50-439/83-13 on 830301-0400 Mononcompliance noted Major areas inspected const surveillance Relicensee action on previous enforcement matters Safeguards info deleted (ref 1006R73 21) HLCDX.J D Region 2. Office of Director 83/05/19 Bpp 19058 355 24% Fichs 50-438.83/06/15.8306290309
- a Inspection reports, IE Bulletins & correspondence
- 8304i40570 Confirms mgt meeting on 8302i6 at Region II oft to discuss results of self-initiated evaluation of activities at facility conducted under INPO guidelines Proposed meeting agenda entl
 O'REILLY, J P Region 2, Office of Director 83/02/07 PARRIS. B O Tennessee Valley Authority 2pp 18844 162 24X
 Fiche 50-438,83/02/07,8306i40b/0
- 8306140618 Forwards summary of 830216 meeting rellicensee-initiated avaluation of constluctivities, per INFO guidelines LEMIS.R C Division of Project & Resident Programs 83/02/22 PARRIS.H G Tonnessee Valley Authority 4pp 18834 017 24X Fiche 50-438,83/02/22,8306140618

- 8306140543 Confirms mgt meeting on 830421 in Chattanooga/TN to review results of first phase of answal appraisal of regulatory performance, per 630528 teleon
 LEWIS, R. C. Division of Project & Resident Programs 83/04/12
 PARRIS, H. G. Tunnessee Valley Authority Jap 18634 176 24X
 Fiche 50-000,83/04/12,8306140°43
- 830511045B IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in Well Logging Device" Svc list enct TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/05/26 Consolidated Edicon Co of New York, Inc 125pp 18831 043 24X Fiche 50 000.83/05/26.8305110458
- B305110460 IE Info Notice 83-34, "Event Notification Info Worksheet" Syc list encl
 JORDAN, E. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/05/26 Consolidated Edison Co of New
 York, Inc. 115pp 18732 085 24X Fisho 50-000,83/05/26,8305110460
- 8306140143 Ack receipt of 830516 ltr informing NRC of steps taken to correct violations noted in IL lusp Repts 50-439/83-07 & 50-439/83-07 WERELLI, D M Division of Project & Resident Programs 83/05/26 PARRIS, H 9 Tennessee Valley Authority to 18039 007 24X Fiche 50-438,83/05/26,8306140143
- --8305140150 Responds to NRC 830414 ltm re violations noted in IE Insp Repts 50-438/83-07 & 50-439/83-07 Corrective actions equipment named in violation taggod or returned to instrument test lab for repair or callbr KILLB.L M Tennessee Valley Authority 83/05/16 D'REILLY, J P Region 2, Office of Director 7pp 18839 008 24X Fiche 50-438,83/05/25,8306140143
- --8306140157 Forwards IE Insp Repts 50-438/83-07 & 50-439/83 07 on 830307-11 & notice of violation VERRELLI, D M Division of Project & Resident Programs 83/04/14 PARRIS, H G Teinnessee Valley Authority 1p 18839 015 P4X Fiche 50 438,83/05/26,8306140143
- --8306140164 Notice of violation from insp on 830307-11 * Region 2, Office of Director 83/04/14 2pp 18839 017 24X Fiche 50-438,83/05/26,8306140143
- --8306440172 IE Insp Repts 50-438/83 07 & 50-439/83-07 on 830307-11
 Noncompliance noted failure to control & calibr measuring &
 test equipment & failure to audit several site const
 activities on annual basis
 WRIGHT.R W. UPRIGHT.C M. Region 2. Office of Director
 Bpp 18837 019 24X Fiche 50-438,83/05/26,8306140143
- B306140114 Ack receipt of 830512 ltr informing NRC of steps taken to correct violations noted in IL Insp Repts 50-439/83-05 & 50-439/03-0', VERRELLI,D M Division of Project & Resident Programs 83/05/27 PARRIS,H O Tennessee Valley Authority 1p 18039-138 24X Fiche 50-438.83/05/27.8306140114
- --8306140125 Responds to NRC 830412 ltr re violations noted in IC Insp Repts 50-483/83 05 & 50-4839/83-05 Corrective actions checklist prepared & issued to unit braining officer delineating documentation requirements for NDE personnel MILLS.L M (enuessee Valley Authority 83/05/12 0'REILLY, J P Region 2, Office of Director 5pp 18839 139 24X Fiche 50-438,83/05/27,8306140114
- --8306140131 Forwards IE Inop Repts 50-438/83-05 & 50-439/83-05 on 830214-0304 & notice of violation VERRELLI, D M Division of Project & Resident Programs 83/04/12 PARRIS. N 9 Tennessee Valley Authority 2pp 18839 144 24X Fiche 50-438.83/05/27,8306140114
- --8306140134 Notice of violation from insp on 830214-0304 4 Region 2, Office of Director 83/04/12 2pp 18839 146 24x Fiche 50-438,83/05/27,8306140114
- --B306140139 IC Insp Repts 50-438/83-05 & 50-439/83-05 on B30214-0304 Noncompliance noted sufficient records affecting quality such as qualification of GC personnel not maintained YORK, J W. LIU, W.C. BLAKE, J.J. Region 2, Office of Director. 83/04/06 13pp 18839 148 24X Fiche 50-438,83/05/27,8306140114.
- 8306:40757 Concurs w/util position contained in 82:109 ltr supporting denial of violation identified in IE lnsp Repts 50-438/82-24 the So-439/82-24 Violation will be deleted from NRC records VERRELLI.D M. Division of Project & Resident Programs 83/05/27 PARRIS.H @ Tennessee Valley Authority ip 18841 195 24X Fiche 50-438.83/05/27.8306140/87

- B305110461 IE Info Notice B3-35, "Fuel Movement W/Control Rods Withdrawn at INRs " Svc list encl JORDAN Et Division of Emergency Preparedness & Engineering Response (Post B30103) B3/05/31 Consolidated Edison Co of New York, Inc 116pp 18732 208 24% Fiche 50-000,83/05/31,8305110461
- 8305110464 IE Info Notice 83-36. "Impact of Security Practices on Bafe Operations" Syc list enci JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/09 Consolidated Edison Co. of New York, Inc. 119pp 18830 280 24% Fiche 50-000,83/06/09,8305110464
- 8306290231 Forwards IE Insp Repts 50-438/89-12 & 50-439/83-12 on 830516-20 No moncompliance noted VERRCLLI.D M Division of Project & Resident Programs 83/06/09 PARRISH O Tonnessee Valley Authority 2pp 19056 087 24X Fiche 50-438.83/06/09.8306290231
- --8306290235 IE Insp Repts 50-438/83-12 & 50-439/83-12 on 830516-20 No noncompliance noted Major areas inspected previous enforcement matters, safety-related pipe support & restraint sys & licensee action on previously identified insp items YORK, J W. BLAKE, J J. Region 2. Defice of Director 83/06/06 5pp 19056 089 24X Fiche 50-438,83/06/09,8306290231
- 0305110470 lE Info Notice 83-38. "Defective Heat Sink Adhesive & Seismically Induced Chatter in Relays Within Printed Circust Cards" Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co of New York, Inc. 118pp 18920-225 24% Fiche 50-000,83/06/13,8305110470
- 8306070010 IE Info Notice 83-37. "Transformer Failure Resulting From Degraded Internal Connection Cables " Svc list and JURDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83706/13 Consolidated Edison Co. of New York, Inc. 243pp 18921 001 24% Fiche 50-000.83/06/13,8306090010
- 8306270307 Ack receipt of 830524 ltr advising NRC that IE Insp Repts 50-438/83-13 & 50-439/83-13, contain safeguards-related matl Rept will be withheld (ref 10CFR/3 21) VERRELLI,D M Division of Project & Resident Programs 83/06/15 PARRIS,H G Tennessee Valley Authority 1p 17095 351 24X Fiche 50-438,83/06/15.8306290307
- --8306290319 Responds to NRC 830519 itr re violations noted in IE Insp Repts 50-438/83-13 & 50-439/83-13 Safeguards info should be withheld (ref 10CFR73 21) MILLS.L M Tennessee Valley Authority, 83/05/24 G'REILLY, J.P. Region 2. Office of Director ip 19055 332 24% Fichs 50-438.83/06/15.8306290309
- --8306290375 Forwards IE Insp Repts 50-438/83-13 & 50-439/83-13 on 830301-0430 No noncomplisher nated VERRELLI,D M Division of Project & Resident Programs 83/05/19 PARTS.H O Tennessee Valley Authority 2pp 19055 353 24X Fichs 50-438.83/06/19,8306290307
- --8306290334 IE Insa Repts 50-438/83-13 & 50-439/83-13 on 930301-0430 No noncompliance noted Major areas inspected const surveillance & licensee action on previous enforcement matters Bafeguards info deloted (ref 10CFR73 21) WILCOX.J D Region 2: Office of Director QUICK, D R Division of Project & Resident Programs 87/05/17 Bpp 19055 385 24X Fiche 50-438,83/06/15,8306290309
- 8306270483 Approves issuance of SALP Repts 50-289/83-04,50-260/83-04, 50-296/83-04, 50-327/83-04,50-328/83-04,50-390/83-07, 50-391/83-06,50-438/83-06,50-439/83-06 for Jul 1981 Dec 1982 No reply required O'REILLY,JP Region 2, Office of Director 83/06/17 PARRIS:H 0 Tennessee Valley Authority Spg 24% Fiche 50-000,83/06/17, 200/200488
- --B306290490 Forwards BALP Repts 50-259/83-04.50-260/83-04. 50-296/83-04.50-327/83-04.50-328/83-04.50-390/83-07. 50-391/83-06.50-438/83-06 & 50-439/83-06 for Jul 1981 - Dec 1982 LEHTBLR C Division of Project & Resident Programs 83/04/13 PARRISH G Tennessee Valley Authority 3pp 24X Fiche 50-000, B3/06/17, 8306290483
- --8306290508 SALP Repte 50-259/83-04, 50-260/83-04, 50-296/83-04, 50-327/83-04, 50-327/83-04, 50-327/83-04, 50-327/83-06, 50-438/83-06, 50-438/83-06, 50-438/83-06, for Jul 1981 Dec 1982 * Region 2, Office of Director 89/04/13 92pp 24X Fich* 50-000, 83/06/17, 8306290483

- --8306290510 Comments on SALP Repts 50-259/83-04,50-260/83-04, 50-294/83-04,50-327/83-04,50-328/83-04,50-390/83-07, 50-391/83-06,50-438/83-06 & 50-439/83-06 for Jul 1981 - Dec 1982 MILLS,L M Tennessee Valley Authority 83/05/10 O'REILLY,J P Region 2, Office of Director 2pp 24X Fiche 50-259,83/06/17, 8306290483
- 8306290237 Ack receipt of 830610 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-438/81-29 & 50-439/81-29 VERRELLI, DM Division of Project & Resident Programs 83/06/20 PARRIS.H 0 Tennessee Valley Authority 1g. 19056-244 24x Fiche 50-438.63/06/20.8306290239
- --B306290246 Submits supplemental response to NRC Bil208 ltr reviolations noted in IE Insp Repts 50-438/81-29 & 50-439/81-29 Corrective actions letdown coolers to be installed upon receipt of B&W info re support deficiencies MILLS.L M Tennessee Valley Authority B3/06/10 O'REILLY, J P Region 2. Office of Director 2pp 17056 245 24X Fiche 50-438.83/06/20,8306290239
- 8305110475 IE Info Notice 83-40, "Need to Environmentally Qualify
 Epoxy Grouts & Sealers " Svc list encl.

 JORDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83706/22 Consolidated Edison Co of New
 York, Inc. 115pp. 19021 179 24X Fishe 50-000,83706/22,8305110475
- 8305110477 IE Info Notice 83-41. "Actuation of Fire Suppression Bys Causing Inoperability of Bafety-Related Equipment." Bvc list encl JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83706/22 Consolidated Edison Co. of New York, Inc. 120pp. 18997 007 24X Fiche 50-000, 83706/22, 8305110477
- 8305110479 IE Info Notice 83-42. "Reactor Mode Switch Malfunctions "
 Svc list encl
 JORDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/06/23 Consolidated Edison Co of New
 York, Inc. 116pp 18996-242 24X Fiche 50-000,83/06/23.8305110479
- 8305110483 IE Info Notice 83-43, "Improper Settings of Intermediate Range (IR) High Flux Trip Betpoints " Svc list encl JORDAN: E.L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/06/24 Consolidated Edison Co. of New York, Inc. 116pp 19046 297 24X Fiche: 50-000.83/06/24.8305110483

8 Reportable occurrences, LERs & related correspondence

- 8306070072 Fifth interim deficiency rept re engineering change notice review & handling Initially reported on 811215 Personnel retrained & corrective actions presented to Ofc of GA for approval Addl into will be submitted by 830722 MILLS.L M. Tennessee Valley Authority 83705/24 D'REILLY, J.P. Region 2. Office of Director 2pp 18740:085 24X Fiche 50-000,83/05/24,8306070072
- 8306010251 Third interim deficiency rept re underdesigned snubber on main feedwater piping in Valve Room B Initially reported on 821013 Process of documenting completed Analysis & review underway Nest rept by 840118.

 MILLS:L.M Tennessee Valley Authority 83/05/25 D'REILLY, J.P. Region 2, Office of Director ip 19673 033 24% Fiche 50-438,83/05/25,8306010251
- 8306010274 Third interim deficiency rept re sheared motor pinion keys in Limitorque motor operators Initially reported on 820830 Field change notices issued to replace keys. Next rept will be sent by 830922, Also reportable per Part 21. MILLB.L M. Tennessee Valley Authority 83/05/25 O'REILLY.J P Region 2, Office of Director 2pp. 18674 322, 24X Fiche 50-000, 83/05/25, 8306010274
- 8306010431 Second interim deficiency rept re corrosion in high pressurc fire protection sys. Initially reported on 820903, Sys contains carbon steel piping Corrosion analyses in progress Nect rept to be submitted by 821004.

 MILLS:L M Tennessee Valley Authority 83/03/25. 0'RETLLY, J. P Region R. Office of Director. 2pp. 18674 255 24X

 Fiche: 50-000, 83/05/25, 8306010431
- 8306070074 First interim deficiency mept re incorrect max pipe movements contained in TPIPE program. Initially reported on 830804. W/a encl. Next mept expected by 830922 MILLS.L.M. Tennessee Velley Authority. 83/05/26. D'REILLY, J P. Region 2. Office of Director ip 18739 319. 24X Fiche 50-000, 83/05/26, 8306070074

- 830.6070160 Fifth interim deficiency rept re defects in reactor protection & LSF actuation sys modules supplied by Bailey Meter Co Initially reported on 820414 l&W investigating use of yellowish bonding agent Also reportable per Part 21 MILLS.L M Tennessee Valley Authority 83/05/26 O'RETLLY, J P. Region 2, Office of Director 3pp 18/36 288 24X Fiche 50-438,83/05/26.8306070160
- 830607013B Third interim deficiency rept re voiding of enginerring change notices w/o proper review Initially reported on 820816 Change notices being reviewed & unresolved safety question determination performed Next rept by 830923 MILLS.L M Tennessee Valley Authority 83/05/31 0'REILLY, J P Region 2. Office of Director 2pp 18/39 264 24X Fishe 50-000,83/05/31.8306070138
- 8306090310 Second interim deficiency rept re tube leaks in component cooling water HXs Initially reported on 830218 Corresion pitting revealed by metallurgical exam Alloys investigated for replacement HILLS,L M Tennessee Valley Authority 83/06/03 O'REILLY, J P Region 2. Office of Director 3pp 18/75 193 24X Fiche 50-438,83/06/03.8306090310
- 8304200141 Sixth interim deficiency rept re Viking flow control valves in fire protection sys Initially reported on Bill24 Drawing rev review continuing Next rept to be submitted by B30809 Also reportable per Part 21 HILLSL M Tennessee Valley Authority B3/06/07 O'REILLY, J.P. Region 2. Office of Director ip 18903 264 249 Fichs 50-438,83/06/07,8306200141
- 8306200143 First interim deficiency rept to failure to specify IFEE class of safety-related sys components on procurement specs Initially reported on 830509 Suppliers being contacted Next rept to be submitted 831119 MILLS.L M Tennessee Valley Authority 83/06/09 O'REILLY.J P Region 2. Office of Director 2pp 10:03 259 24X Fiche 50-438.83/06/09.8306200143
- 8304210051 Supplemental interim deficiency rept re potentially overstressed embedded plates Initially reported on 820412 Next submittal scheduled for 840217 instead of 830422 as originally stated MILLS.L M Tennessee Valley Authority 83/06/10 0'REILLY, J P Region 2. Defice of Director lp 18914 009 24x Fiche 50-000,83/06/10,8308210051
- 8306210005 First interim deficiency rept re max temp inside containment Initially reported on 830513 Util requested BMH to respond to nonconformance rept by 930715 Next rept to be submitted by 830826 Also reported per Part 21 MILLS.L M Tennessee Valley Authority 83/06/13 G'REILLY.J P Region 2, Defice of Director 2pp 18912 283 P4X Fiche 50-438.83/06/13.8306210005
- 830A21001B First interim deficiency rept re B&W plant internal holt failures Initially reported on 830513 B&W & B&W Duners Group assessing situation to determine scope of problem & corrective actions Next rept to be submitted by 831206 MILLB, L M Tennessee Valley Authority 83706/13 0'REILLY, J P Region 2, Office of Director 2pp 10914 239 24X Fichs 50-438,83/06/13,8306210018
- 8306210252 Second interim deficiency rept re failure to identify grade of nuts due to orientation w/grade markings facing against structural member Initially reported on 830126 Testing in progress Next rept by 830930 MILLS,L M Tannesse Valley Authority 83/06/14 O'REJLLY, J P Region 2. Office of Director 2pp 18718 099 24X Fiche 50-438,83/06/14.8306210252
- 8306210042 Fifth interim deficiency rept re seismic analysis of auxiliary control bldg Initially reported on 820226 Seismic analysis rept revised & two new walls will be constructed Next rept to be submitted by 840622 MILLS.L.M Tennessee Valley Authority 83/06/15 O'REILLY.J.P. Region R. Office of Director 2pp 18712 299 24% Fiche 50-438,83/06/15,8306210042
- 8306280479 Final deficiency rept re improperly welded chiller unit piping components Initially reported on 820111 Radiographic exam to be performed on all safety-related chiller piping Also reportable per Part 21 MILLS, L M Tennessee Valley Authority 83/06/17 O'REILLY, J P Region 2. Office of Director 3pp 17020 116 24X Fiche 80-438,83/06/17,8306280479
- 8306280878 Interim deficiency rept re resolution of listed items due for submittal in late June Corrective actions in progress List identifying each item, schedule for next submittal & level of interim rept encl
 MILLS, L.M Tennesses Valley Authority 83/06/17 O'REILLY, J R
 Region 2. Office of Director 2pp 19018 193 24X
 Fiche 50-000, 83/06/17, 83062805/8

- 8306280619 Fourth interim deficiency rept re incorrect installation of pressure relief & safety valves Initially reported on 830305 Two 3-inch relief valves, exhausting into waste disposal header, added Next rept to be submitted by 840718 MILLS-L M Tennessee Valley Authority 83/06/17 0'REILLY, J P Region 2. Office of Director 2pp 17016 001 24X Fiche 50-438,83/06/17.8306280617
- 8306280222 Revised final deficiting reptite DHR valve Initially reported on 820212 Lower stem valve plug & lock pin replaced Control valve design sold to company not qualified as nuclear industry supplier Also reportable per Part 21 MILLS.L M Tennessee Valley Authority 83/06/20 O'REILLY, J P. Region P. Office of Director 2pp 19014 185 24x Fishe 50-439.03/06/20.0306800222
- 830.6280369 Second interim deficiency rept re incorrect seismic pipe support insps Approx 3.800 completed insp records for rigorously analyzed supports identified Support location will be shown on detail drawings Next rept by 831213 MILLS, L.M. Tennessee Valley Authority 83706720 07REJLLY, J.P. Region 2. Office of Director 2pp 19014 083 24X Fiche 50-438.83/06/20.8306280369
- 830.6280425 Fourth interim deficiency rept re B&W design of RCS supports & restraints Initially reported on 820.601 Majority of blocks installed Shear bor evaluation expected by 830801 Also reported per Port Pl MELLS, L. M. Tennessee Valley Authority 83/06/20 D'REILLY, J. P. Region 2. Defice of Director 2pp 17020 300 24X Fiche 50-438.63/06/20,6306280429
- 8306300159 Part 21 rept re spot welds in Bailey Controls Co cabinets w/smaller diameter than specified Cabinets strengthened by seam & edge welding or bolting TAYLON.J II Bobcock & Wilcox Co 83/06/23 DEY8UNO.R C Director's Dffice, Office of Inspection and Enforcement 2pp 1919 308 24X Fishs 50-000,83/06/2J.8306300199
- 8306300214 Second interim deficiency rept re tubeline matls supplied by Capitol Pipe & Steel not mfg under GA program Initially reported on 830329 Contractor will perform dimensional chects for pipes & fittings Next rept by 830922 MILLS.L M Tennossee Valley Authority 83/06/23 O'REILLY.J P Region 2. Office of Director 5pp 19119 351 24% Fiche 50-000.83/06/23.8306300214
- 970430000B Fourth interim deficiency rept re possibility of exceeding turbine driven auxiliary feedwater pump room temp Initially reported on 911006 Fan motors will be replaced Next rept by 940430 MILLS.L M Tennessee Valley Authority 83/06/24 O'RCILLY.J P Region 2, Office of Director 2pp 19120 317 24X Fiche 80-430.03/06/24.8306380008
- 8306300245 Final deficiency rept re analysis for loss of feedwater event Initially reported on 830316 Util does not consider subj nonconforming condition adverse to safe operation of plant Confistion not reportable per 100FRSD 55(e) MILS.L M Tennessee Valley Authority 83706/24 0'REILLY.J P Region 2. Office of Director Ppp 19119 341 24X Fiche 50-438.83/06/24.8306300245
- DOCKET 50-440 PERRY NUCLEAR POWER PLANT, UNIT 1
- A Application/construction stage documents & correspondence
- B3060603B1 Appeals denial of FDIA request for documents re risk to facilities from low trajectory turbine missiles HIATT. B. Dhio Citizens for Responsible Energy B3/03/03 DIRCKG.N J Office of the Executive Director for Operations Dap 18750-387 24X Fiche 50-440.83/03/03.83060603B1
- B304060384 Responds to appeal re partial denial of FDIA request for documents concerning risks to facilities from low trajectory turbine missiles Appeal denied Documents withheld (ref FDIA Exemption 5)
 DIRCKS-W J Office of the Executive Director for Operations B3/04/06 HIATTS L Ohio Citizens for Responsible Energy 1p. 18780 332 24X Fiche 50-440,03/04/06,6306060384
- 8304030509 Informs that each LNG-II member must submit numerical value determined by GE for respective plants on fuel assembly lift off displacement, due to error in fuel assembly topical rept re LRG-II Generic Issue P-CPB NOVAK, T M Assistant Director for Licensing 83/05/23 HDLTZSCHER, DL Licensing Review Group II 3pp 18735 051 24X Fiche 50-000,83/05/23,8306030509

- 8306060373 Responds to 820903 ltr submitting position pagers which included Licensing Review Oroup II proposed solution for Issue 4-MEB, intended to protect in-core instrument tubes from flow-induced vibration Issue unresolved YOUNGOLOOD, B J Licensing Revent I 93/05/26 HOLTZSCHER, D L. Licensing Review Oroup II HOLTZSCHER, D L. Illinois Power Co. 4pg 18751 287 24X Fiche 50-000, 83/05/26, 8306060373
- 8306080044 Forwards "Analysis of Inaccessible & Potentially Rejectable Defects in Perry Nuclear Power Plant," per 830426 meeting commitment EDELMAN.M R Cleveland Electric Illuminating Co 83/05/31 YOUNGBLOOD, B J Licensing Branth 1 1p 18774 115 24X Fiche 50-440, 83/05/31.8306080044
- ---B30A0B004B "Analysis of Inaccessible & Potentially Rejectable Defects in Perry Nuclear Power Plant"

 MCNAUGHTON, W.P., EGAN, O.R., BYRON, J.D. Aptech Engineering Services B3/05/31 117pp 187/4 116 24X Fiche 50-440, 83/05/31,8304080044
- B306140661 Forwards response to R Dimber ltr re salt cavity storage area Encl FSAR changes will be incorporated into future FBAR amend EDLEMAN.M R Cleveland Electric Illuminating Co B3/06/01 YOUNGBLOOD, B J Licensing Brench 1 4pp iBB34·001 24X Fiche-50-440, 83/06/01.8306140661
- B306100180 Forwards current description of GA program for design & const of facilities Program acceptable, per 10CFR50, App B EDELMAN, M R Cleveland Electric Illuminating Co. B3706/02 KEPPLER, J G Region J. Office of Director 3pp 18806 029 24X Fiche. 50-440, 83/06/02, 8306100180
- 8306240186 Forwards add1 info on safety relief valve piping & quencher device & safety-related giping supports in response to Questions 210 7, 210 10 & 210 11 in NRC 821214 & 830401 ltrs Lateral instability will not occur EDELMAN.M R Cleveland Electric Illuminating Co 83/04/21 YOUNDELOOD, J Licensing Branch 1 9pp 18981 021 24X Fiche 50-440,83/06/21,8306240186
- 8306240390 Requests submittal of proof & review Tech Specs accompanied by detailed discussion of methodology used in establishing setpoint values Par reactor protection mys & ESF instrumentation & months prior to Unit 1 licensing YOUNGBLOOD, B.J. Licensing Branch 1 83706/21 EDLEMAN.M R. Cleveland Electric [1]uminating Co. 3pp 18987-350 24% Fiche 50-440.83706/21,8306240390
- 8306280161 Responds to Generic Ltr B3-10, "NRC Review of BWR Owners Group Control Room Burvey Program " Plant-specific info to be addressed listed EDELMAN,M R Cleveland Electric Thluminating Co B3/06/21 YDUNGHLOUD, D J Licensing Branch 1 2pp 19015 100 24X Fiche 50-440,83/06/21.8306280161
- E NRC Safety Evaluation Report (SER), suppls & correspondence
- B306020694 Submits rept re turbine missile issue Rept completes MRR action requested in ACRS 820713 ltr Results documented in Suppl 3 to SER (NUREO-0887).
 NUVAK: I M Assistant Director for Licensing. B3/05/23 RAY, J J.
 ACRS Advisory Committee on Reactor Sefeguerds. 10pp 18716-237.
 24x Fiche 50-440, B3/05/23, B304020694
- 830401005B Responds to B30506 ltr on procedures generation package per SER Outstanding Issue 21 Dec 1983 scheduled completion date provided in B30415 suppl to Generic Ltr 82-33 EDELMAN, M R Cleveland Electric Illuminating Co. 83/05/27 YOUNGBLODD, B J Licensing Branch I ip 18674,073. 24X Fiche 50-440,83/05/27,8304010058
- 8306080437 Summary of 830526 meeting w/util in Bethesda, MD re present containment purge sys design, Outstanding Issue 10 in SER (NUREO-0887) STEFANG.J J Licensing Branch 1 83/06/03 YOUNOBLOOD, B J. Licensing Branch 1 12pp 18792 197 24% Fiche 50-440,83/06/03,8304080437
- 8306200085 Clarifies commitment to perform addl start & load qualification testing on standby diesel generators, as outlined in SER Section 8 3 1 Total of 20 addl tests will be conducted EDELMAN.M R Cleveland Electric Illuminating Co. 83/06/15 YOUNGBLOOD B J Licensing Branch 1 2pp 18903 353 24X Fiche 50-440,83/06/15,8306200085

- 8306240269 Forwards study results of effects of grating on drywell & containment response per SER Outstanding Issue 9 re pool dynamic loads App 30 incorporated in Amend 11 to FEAR providing description of hydrodynamic loads EDELMAN.H R Cleveland Electric Illuminating Co 83/06/20 YOUNDELDOB J Licensing Branch 1 5pp 18980-098 24X Fiche 50-440.83/06/20.8306240269
- 8306240064 Notifies that add1 info re list of safety-related items in FSAR Table 3 2-1 (0A-list) acceptable Dutstanding Issue 23 in Suppl 3 to BER (NUREO-00B7) will be changed to confirmatory issue per FSAR Amend 12 review YOUNGBLOODE J Licensing Branch 1 83/06/21 EDELMAN M R Cleveland Electric Illuminating Co 2pp 18987 134 24X Fiche 50~440,83/06/21,8306240064
- 8306240288 Requests addl info to resolve SEK Confirmatory Issue 10 rc Fast scram hydrodynamic loads on control rod drive sys Response within 7 days of ltr receipt requested YOUNGBLODD, B J Licensing Branch : 83/06/21 EDELMAN, M R Cleveland Electric Illuminating Co 3pp 18979 167 24% Fichs 50-440,83/06/21,8306240288
- 8306290137 Submits evaluation findings on outstanding & confirmatory instrumentation & control sys issues documented in SER Addl info requested. Response requested within 7 days YQUNOBLOD, B J Licensing Branch i 83/06/22 EDELMAN, M R Cleveland Electric Illuminating Co 25pp 19046-222 24X Fiche 50-440,83/06/22,8306290137
- F Security, medical, emergency & fire protection plans
- 8304010058 Responds to 830506 ltr on procedures generation package per SER Outstanding Issue 21 Dec 1983 acheduled completion date provided in 830415 suppl to Generic Ltr 82-33 EDELMAN, M.R. Cleveland Electric Illuminating Co. 83/05/27 YOUNGELOOD, B.J. Licensing Branch I lp 18674 073 24X Fiche 50-440, 83/05/27, 8304010058

G Adjudicatory correspondence

- 8306010433 Motion for summary disposition of Issue 13 No genuine issue of math fact exists & NRC entitled to fovorable decision Affidavit Centificate of Svc & prof qualifications encl CUTCHIN.J Hearing Branch 4 83/05/31 Atomic Safety and Licensing Board Panel 11pp 18674 25/ 24X Fiche 50-440.83/05/31.8306010433
- B306090345 Notice of Dhio Citizens for Responsible Energy 10CFR2 206 petition alleging false util statements in application re use of herbicides to control vegetation along transmission lines
 DEYGUNO.R C Director's Office. Office of Inspection and Enforcement B3060406 Ip 18794 335 24X Fiche 50-440, B3/06/06.
- 830&14070& Forwards NRC answers to two ABLB questions posed during B30509 telephone conference re declaration of sua sponta issue Operators will be trained to differentiate between instrument failures & transients & accidents CUTCHIN.J M Hearing Branch 4 83/06/13 DLOCH,P B. HRIGHT,Q D. KLINE.J.R Atomic Safety and Licensing Board Panel Spp 18841-274 24X Fichs 50-440.83/06/13.8306140706
- 8306160596 Answer opposing Chia Citizens for Responsible Energy B30510 motion to admit five new contentions on SNM license application Contentions unjustifiably late, outside ASIB Jurisdiction or moot Certificate of Svc encl BILBERG, J E Commonwealth Edison Co STLBERG, J E Shaw, Pittman, Potts & Troubridge B3706/13 Atomic Sefety and Licensing Board Panel 23pp 18892 286 24X Fishe 50-440, 83/06/13, 8306160596
- 8306160611 Provides estimate of hearing dates In-core thermocouples & steam proston issue will be disposed of by summary disposition Standby liquid control sys initiation & hydrogen control issues should be resolved by rulemaking SILBERG. J E Shaw, Pittman, Potts & Troubridge SILBERG, J E Cleveland Electric Illuminating Co 83/06/14 DLOCH, PB. KLINE. J, R., BRIGHT, G D Atomic Safety and Licensing Board Panel 3pp 18866 097 24X Ficher 50-440,83/06/14,8306160611
- 8306220080 Answer opposing NRC 830531 motion for summary disposition of Issue 13 re adequacy of proposed tubine maint program w/turbine missile probability Statement of mat1 fact & Certificate of Svc encl Related correspondence
 LODGE.T.J Bunflower Alliance 83/06/15 Atomic Safety and Licensing Board Panel 5pp 18730 157 24X Fiche 50-440.83/06/15, 8306220080.

- 8306170399 Advises of incorrect cite in NRC 930713 answer opposing this citizens for Responsible Enlargy motion to file contentions on SNM license application CUTCHIM.J M Hearing Branch 4 83/06/16 BLOCK, P B BRIGHT 6 (L. KLINE, J R Atomic Safety and Licensing Board Panel ip 18880 01/24X Fiche 50-440.83/06/16.830/170399
- B304270014 Responses to fourth set of interrogatories & request for production of documents Related correspondence HIATT. S.L. Ohio Citizens for Responsible Energy B3/06/21 Cleveland Electric Illuminating Co. Sup. 18988 050 24x Fiche 50-440.83/06/21.8306270014
- --8306270017 Supplemental response to third set of interrogatories Certificate of Svc encl HIATTS (Ohio Citizens for Responsible Energy 83/06/21 Cleveland Electric Illuminating Co 3pp 18988 055 24y Fiche 50-440.83/06/21.8306270014
- 8306290536 Response opposing NRC 830531 motion for summary disposition of Issue 13 re turbine missile hazards Motion premature Valuable evidence would be excluded if motion granted Statement of moti facts encl Related correspondence HIATT.S L Ohio Citizens for Responsible Energy 83/06/23 Atomic Bafety and Licensing Board Panel 7pp 17082 29:2 24X Fiche 50-440.83/06/23.8306290536
- --8306290549 Affidavit of SL Hight that Unio Citizens for Responsible Energy cannot currently present Farts to justify apposition to NRC motion for summary disposition of Issue 3 since info still being reviewed Certificate of Syc encl HiATTS L Dhio Citizens for Responsible Energy 83/06/23 1app 19052 299 24X Fiche 50-440.83/06/23,8306290536
- 8306290214 Answer supporting NRC 830531 motion for summary disposition of Issue 13 No genuine issue of math fact exists & no good cause provided Certificate of Svc entl Related correspondence SILBERG, J E Cleveland Electric Illuminating Co SILBERG, J E Shaw, Pittman, Potts & Troubridge 83/06/27 Atomic Safrty and Licensing Board Panel 12pp 19056 140 24X Fiche 90-440,63/06/2/,8306290214
- --8306270220 Affidavit of DP Timo & LH Johnson, supporting NRC 830531 motion for summary disposition of Issue 13 Prof qualifications oncl TIMO. DP , JOHNSON, LH NRC No Detailed Affiliation Given TIMO, DP General Electric Co 83/06/24 35pp 19056 1&0 24: Fiche 50-440,83/06/27,8306290214
- --8306290240 Affidavit of EJ Turk, supporting NRC 830531 motion for summary disposition Util will follow &E recommendations rotesting of overspeed protection sys Prof qualifications enc.

 TURK, E J NRC No Detailed Affiliation Given * Clevelund Electric Illuminating Co 83/06/24 Bpp 19056 195 24X Fichs 50-440,83/06/27,8306290214

H General correspondence

- B306030288 Notice of change of counsel address Certificate of Evc oncl LODGE, T. J. Lodge, T. J. 83/05/31 1p 18703 357 24X Fiche 50-440, 83/05/31,8306030288
- 830.6270.144 Ack receipt of 830516 ltm forwarding council Resolution 1443-83 re quality of containment vessel welds Summary rept of 830504 site visit encl Completed rept of review of util commitments expected in Jul 1783 DENTON. If R Office of Nuclear Gractor Regulation, Director 83706/22 EULERI, G A Perry, DH App 17046 250 PAX Fiche 50-440,8306/22,83062790144
- @ Inspection reports: IE Bulletins & correspondence
- 8306270112 Ack receipt of 830410 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-440/83-06 & 50-441/83-06 SPESSARD, R L Division of Engineering 83/04/22 EDCLMAN, M R Claveland Electric Illuminating Co 1p 18788 09/ 24X Fithe 50-440,83704/22. 8306270112
- --8306270115 Responds to NRC 930316 ltr re violations noted in JE Insp Repts 50-440/83-06 & 50-441/83-06 Corrective actions GC insp rept written for each concern identified during LK Comstock Task Force document review EDELMAN, M, R Cleveland Electric Illuminating Ca 83/04/15 SPESBARD, R L Division of Engineering 5pp 18788 098 24X Fiche 50-440,83/04/22,8306270112

- 8304030149 Forwards IE Insp Repts 50-440/83-08 & 50-441/83-07 on 830301-03 & 11 No noncompliance noted LITLE, W.S. Region 3, Office of Director 83/05/16 EDELMAN, M.R. Cleveland Electric Illuminating Co. 2pp 18704-293 24X Fiche 50-440,83/05/14,8304030149
- --8306030151 IE Insp Repts 50-440/83-08 & 50-441/83-07 on 830301-03 & 11 No noncompliance noted Major areas inspected LK Constock personnel qualifications @A/QC & craft personnel & licensue actions on previously identified items
 BARRETT, P A , NAIDU. K R , PLIKE, P R Region 3, Office of Director 83/05/12 | 13pp 18704 255 | 24X Fische 50-440,83/05/16,8306030147
- 8305110458 IE Info Notice 83-32. "Ruptured Am-241 Sources Contained in Hell Logging Device" Svc list encl
 TAYLOR, J H Division of Safeguards & Inspection Programs (Pust 830103) 83/05/24 Consolidated Edison Co of New York, Inc 125pp 18831 043 24% Fiche 50-000,83/05/26,8305110458
- B305110460 LC Info Notice B3-34, "Event Notification Info Workshept"
 Svc list encl
 JORDAN, E. Division of Emergency Preparedness & Engineering
 Response (Post B30103) 83/05/26 Consolidated Edison Co of New
 York, Inc 115pp 18732 085 24X Fiche 50-000,83/05/26,8305110460
- 8305110461 IE Info Notice 83:35, "Fuel Movement W/Control Rods Withdrawn at BWRs " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/31 Consolidated Edison Co of New York, Inc 116pp 18732 208 24X Fiche 50-000.83/05/31.8305)10461
- 8306160242 Forwards IE Insp Rupts 50-440/83-12 & 50-441/83-11 on B30418-22 & notice of violation LITTLE W B Region 3, Office of Director 83/06/03 EDELMAN, M R Cleveland Electric Illuminating Co 2pp 18861 226 24X Fache 50-440, 83/06/03, 8306160242
- ~-8306160247 Notice of violation from 105p on 830418-22 L[TTLE,W S Region 3, Office of Director 83/06/03 ip 18861 228 24X Fiche 50-440,63/06/03,8306160242
- --B306160254 IE Insp Repts 50-440/83-12 & 50-441/83 11 on 820418-22 Noncompliance nated failure to perform routine manthly insp on stored items HUNT, M D . MERRIWEATHER, N Region 2. Office of Director CONLON. T E Division of Engineering & Radiological Bafety Programs B3/05/11 App 18861 227 24X Fiche 50-440.83/06/03, B306160242
- 830&130299 Ack receipt of 830531 ltr informing NRC of steps taken to correct violations noted in II lnsp Repts 50-440/83-09 & 50-441/83-08
 LITTLE W S Region 3. Office of Director 83/06/08 EDELMAN. M R Cleveland Electric Illuminating Co. Ip. 18823-320 P4X
 Fiche 50-440,83/06/08.8306130299
- --8306130305 Responds to NRC 830401 ltr se violations noted in IE Insp Repts 50-440/83 09 & 50-441/83 08 Corrective actions monitoring program consisting of periodic visual eram of suppression pool welds performed from plotform EDELMAN.M R Cleveland Liectric Illuminating Co B3/05/31 KEPPLER.J 0 Region 3, Dffice of Director 2pp 18823 321 24X Fichs 50-440.83/06/08.8306130299
- 8306230267 Forwards IE Insp Repts 50-440/03-14 & 50-441/89-13 on 830425-28 No noncompliance noted LITALE.W B Region 3. Office of Director 83/06/08 CDELMAN.M R Cleveland Electric Illuminating Co 2pp 18745-086 24X Fache 50-440.03/06/08.830623026/
- --8306230271 lE Insp Repts 50-440/83-14 & 50-441/83-13 on 830426-28 No moncompliance noted Major areas inspected license action on deficiency item re RCPB piping work activities & review of quality records
 WARD.K D . KEATING.D E , DANICLSON.D H Region 3, Dffice of Birector 83/06/07 14pp 18945 080 24X Fichs 50-440,83/06/08, 8306230267
- 8305110464 IE Info Notice 83-36. "Impact of Security Practices on Safe Operations " Six: list encl JORDAN, E. L. Division of Lawrgency Preparedness & Engineering Response (Post 830103) 83/06/09 Consolidated Edison Co. of New York, Inc. 119pp 18830 280 24X Fiche 50-000, 83/06/09, 8305110464.
- 8305i10470 IE Info Notice 83-38, "Defective Heat Sink Adhesive & Bersmically Induced Chatter in Relays Within Printed Circuit Cands "Bvc list encl JGRDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Eduson Co of New York, Inc 189p 18920 295 24X Fichs 50-000.83/06/13.8305i10470

- 8304090010 IE Info Notice 83-37. "Transformer Failure Resulting From Degraded Internal Connection Cables" Svc list and JURDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/13 Consolidated Edison Co. of New York, Inc. 243pp 18721 001 24X Fithe 50-000.83/04/13,8304090010
- 8304300201 Forwards IE Insp Repts 50-440/83-17 & 50-441/83-16 on 830301-0430 No noncompliance noted KNDP.R C Region 3. Defice of Director 83/06/14 EDELMAN.M R Cleveland Electric Illuminating Co 2pp 19119 359 24X Fiche 50-440,83/06/14.8306300201
- --8306300207 IE Inap Repts 50-440/83-17 & 50-441/83-16 on 830301-0430, No noncompliance noted Major areas inspected safety-related const activities, including (OCFRSO 55(e) reportable item followup, housekeeping & preparation for ASLB hearings, GILDNER,H L , KONKLIN, J E Region 3, Office of Director 83/04/14 Spp 1919 361 24% Fiche 50-440,83/04/14.8306300201
- 8304300179 Forwards IE Insp Repts 50-440/83-16 & 50-441/83-15 on 830518-19 No noncompliance noted KNOP.R C Region 3. Office of Director 83/06/15 EDELMAN, M R Clevel and Electric Illuminating Co 2pp 19119 R63 R4X Fiche 50-440,83/06/15,8306300179
- --B3063001B3 IE Insp Repts 50-440/B3-16 & 50-441/B3-15 on B30518-19. No noncompliance noted Major areas inspected licensee actions on previous insp findings, IOCFR50 55(e) reportable items & IE bulletins
 PELKE.P R . KONKLIN.J E Region 3, Diffice of Director B3/06/15
 4pp 1919 265 24X Fiche 50-440, 63/06/15, 6306300179
- 8306300126 Forwards IE Insp Rapts 50-440/83-15 % 50-441/83-14 on B30509-13 No noncompliance noted LITTLE.W S Region 3. Office of Director 83/06/17 EDELMAN,M R Cleveland Electric Illuminating Co 2pp 19122-323 24X Ficha 50-440.83/06/17.8306300126
- --8306300132 IE Imap Repts 50-440/83-15 & 50-441/83-14 on 830509-13 No noncompliance noted Major areas inspected safety-related cable tray installation, electrical cables & terminations & equipment installation
 MERRIMEATHER, N. CONLOW, T. E. Region 2, Office of Director 83/06/02 4pp, 19122 325 24% Fiche 50-440,83/06/17,8306300126,
- 8305110475 IE Info Notice 83-40, "Need to Environmentally Gualify
 Epoxy Grouts & Bealers " Syc list encl
 JORDAN,E L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/06/22 Consolidated Edison Co. of New
 York, Inc. 113pp 19021 179 24X Fiche 50-000,83/06/22,8305110475.
- 8305110477 IE Info Notice 83-41, "Actuation of fire Suppression Sys Causing Inoperability of Safety-Related Equipment " Syc list encl JORDAN, Et Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/22 Consolidated Edison Co of New York, Inc 120pp 18997 007 24X Fiche 50-000,83/06/22,8305110477
- 8305110479 IE Info Notice 83-42, "Reactor Mode Switch Malfunctions "

 8vc list encl
 JORDAN, El Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/06/23 Consolidated Edison Co of New
 York, Inc 116pp 18996 242 24X Fiche 50-000,83/06/23,8305110479
- B306270283 Ack receipt of 830609 ltr informing NRC of steps taken to correct violations noted in IE Imap Repts 50-440/83-11 & 50-441/83-10 LITTLE.W S Region 3, Office of Director, 83/06/23, EDELMAN.W R. Cleveland Electric Illuminating Co ip 18996 173 24X Fiche 50-440,83/06/23,8306270283
- --B305270287 Responds to NRC B30509 ltr re violations noted in IE Insp. Repts D0-440/B3-11 & 50-441/B3-10 Corrective actions Johnson Controls Procedure 0A8-1802-PNPP, "Review & Turnover of Records," revised to reflect present document review EDELMAN.M R. Cleveland Electric Illuminating Co. 83/06/09 KEPPLER, J. Q. Region 3, Dffice of Director 2pp 18996 174 24X Fiche 50-440.83/06/23.8306270283
- 8305i10483 IE Info Notice 93-43, "Improper Bettings of Intermediate Range (IR) High Flux Trip Setpoints " Svc list encl JORBAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/24 Consolidated Edison Co of New York, Inc 116pp 19046 297 24X Fiche.50-000,83/06/24,8305110483

8 Reportable occurrences, LERs & related correspondence

- 8306:100:19 Fifth interim deficiency rept to rejection of previously accepted containment vessel radiographs Review of Tadiographs utilizing film overlay techniques being performed Next rept will be submitted by 830930 EDELMAN, R Cleveland Electric Illuminating Co 83/05/31 KEPPLER, J Q Region 3, Office of Director ip 18802 029 24X Fiche 50-440,83/05/31.8306100119
- 8306220015 Interim deficiency rept re sensitivity & density voriations in Borg-Harner valve radiographs Initially reported on 830411 Sampling plan to determine valve acceptability established Final rept by 830710 Also reported per Part 21 EDELMAN.H R Cleveland Electric Illuminating Co 83/06/10 KEPPLER, J Q Region 3, Office of Director 2pp 18727 338 24X Fiche. 50-440, 83/06/10, 8306220015
- 830622005B Final deficiency rept re potentially inadequate cooling of RCIC room during LUCA Initially reported on 830513 AE reviewing RCIC pump/turbine automatic start Heview will be completed by 83072P Also reported per Part 21 EDELMAN, M R Cleveland Electric Illuminating Co 83/06/10 KEPPLERJ G Region 3, Defice of Director 2pp 18930 034 24X Fiche 50-440, 83/06/10, 830622005B
- 8304200120 Notifies that rework associated w/potentially signaficant deficiency ra governor drive coupling mfg by Transamerica Delaval in standby diesel generators.scheduled to be completed by 831031 for Unit 1 & 83123 for Unit 2 EDELMAN.M R Cleveland Electric Illuminating Co 83/06/14 KEFPLER.J G Region 3. Office of Director 1p 18903 329 24X Fiche.50-440,83/06/14,8304200120
- 8306220039 Supple finel deficiency mept me math used in Transamerica Delaval. Inc. governor drive coupling in standby diesel generators Due to long storage time.governors will be returned to manufacturers for overhauling & recalibr EDELMAN.H R Cleveland Electric Illuminating Co 83/06/14 KEPPLER.J G Region 3. Office of Director ip 18930 179 24X Fiche: 50-440.83/06/14.8306220039
- 8306300167 Suppl to B10B03 final deficiency rept re Mono-Bol Brand
 7-0015-3 COS polyvinyl alcohol film, water solvole purge dam
 matl mfg by Chris Craft Industries Portions of sys will be
 flushed prior to fuel loading
 EDELMAN, M R Cleveland Electric Illuminating Co 83/06/27
 KEPPLER, J G Region 3, OPfice of Director 3pp 17121 360 24X
 Fiche 80-440, 83/06/27, 8306300167
- T Hearing transcripts on non-antitrust matters
- 8306010006 Transcript of 830525 hearing in Painesville, BH Pp 1,227-1,436

 * Atomic Safety and Licensing Board Panel 83/05/25 211pp 18673 053 24X Fiche 50-440,83/05/25,8306010006
- 830&010010 Transcript of 83052& hearing in Pain*svi)]p. DH Pp 1, 437-1.70& Supporting documentation encl * Atomic Safety and Licensing Board Panel 83/05/2& 314pp 18671.224 24X Fiche 50-440.83/05/2& 830&010010
- 830&010004 Transcript of 83052/ hearing in Painesville, OH Pp 1,707-1,877 Supporting documentation encl. * Atomic Bafety and Licensing Board Panel 83/05/27 174pp 18665 200 24X Fiche 50-440,83/05/27,830&010004
- 8304070149 Transcript of 830531 hearing in Painesville, OH Pp 1,879-1,980 Supporting documentation encl * Atomic Safety and Licensing Board Panel 83/05/31 127pp 18737.001 24% Fiche 50-440,83/05/31,8306070149
- DOCKET 50-441 PERRY NUCLEAR POWER PLANT, UNIT 2
- A Application/construction stage documents & correspondence
- 8306060381 Appeals denial of FOIA request for documents on risk to facilities from low trajectory turbine missiles
 HIATT, S.L. Dhin citizens for Responsible Energy 83/03/03
 DIRCKB, H.J. Office of the Executive Director for Operations Spp. 18750 329. 24X Fiche 50-440,83/03/03,8306060381
- 8306060384 Responds to appeal repartial denial of FDIA request for documents concerning risks to facilities from low trajectory turbine atssiles Appeal denied Documents withheld (ref FDIA Exemption 5) DIRCKS, W.J. Office of the Executive Director for Operations 83/04/06, HIATT, B. L. Ohio Citizens for Responsible Energy 19 18750 332. 24X Fiche 50-440,83/04/06,8306060384

- 8306030507 Informs that each LRR-II member must submit numerical value determined by GF for respective plants on fuel assembly lift off displacement due to error in fuel assembly topical rept re LRG-II Generic Issue 2-CPB NOVAN, T.M. Assistant Director for Licensing 83/05/27 HOLTZSCHER, D.L. Licensing Review Group II 3pp 18735-051 P4x Fiche 50-000,83/05/23.8306030509
- 8306060373 Responds to 820903 ltr submitting position papers which included Licensing Review Group II proposed solution for Issue 4-MEB. Intended to protect in-core instrument tubes from flow-induced vibration issue unresolved YOUNOBLODD, B J Licensing Branch 1 83705726 IMPLIFACHUR, D t Licensing Review Group II HOLITZSCHER, D t Illistofs Power Co 4pp 18751 RB7 24X Fiche 50-000, 83/05/26. 8306060373
- 8306080044 Forwards "Analysis of Inaccessible & Potentially Rejectable Defects in Perry Nuclear Power Plant: "per B304,76 meeting commitment EDELMAN.M R Cleveland Electric Illuminating Co 878/05/3t YOUNGBLOOD, B J Licensing Branch I Ip 18774 115 24X Fiche 50-440,83/09/31.8304080044
- --83060B0048 "Analysis of Inaccessible & Potentially Rejectable Defocts in Perry Nuclear Power Plant"
 MCNAUCHTON, W.P., EGAN, G.R., BYRON, J.D. Aptech Engineering Services 83/05/31 11/pp 18774 116 24X Fiche 30-440, 63/05/31,83060B0044
- 8304140461 Forwards response to R Bimber ltr re-salt cavity storage area Encl FSAR changes will be incorporated into future FSAR amend EDLEMAN, M R Cleveland Electric Illuminating Co 83/04/04 YOUNGBLOOD B J Licensing Granch I App 18834 COJ 24X Fiche 50-440,83/04/04/05
- 8306100180 Forwards current description of GA program for denign he const of facilities Program acceptable, per 1001890, App B EDELMAN, M.R. Cleveland Electric Illuminating Co. 8370670, KEPPLER, J. G. Region 3. Office of Director. 3pp. 18806-039 44 Fiche 50-440,83706702,8306100180
- 8306240196 Forwards addl info on safety relief valve piping & quenther device & safety-related piping supports in response to Questions 210 9, 210 10 & 210 11 in NRC 021714 & 630401 itrs Lateral instability will not occur EDEMAN. M R Cleveland Electric Illuminating Co 63/06/21 VQUNGBLUGD, B, J Licensing Brench I 9pp 18961 021 24X Fiche 50-440,63/06/21,8306240186
- 8306240390 Requests submittal of proof & review Tech Specs accompanied by detailed discussion of methodology used in establishing setpoint values for reactor protection sys & ESF instrumentation & months prior to Unit 1 licensing, YOUNOBLOOD, B J Licensing Branch [83/06/21 EDLEMAN, M R Claveland Clectric Illuminating Co Jup 18987 350 24% Fiche. 50-440, 83/06/21, 8306240390
- 8304280141 Responds to Generic Ltv 83-18, "NNC Review of GMM Gwnera Group Control Room Survey Program " Plant-specific info to be addressed listed EDELMAN, M.R. Cleveland Electric Illuminating Co. 87/04/21 YOUNGBLOOD, B.J. Licensing Branch I. 2pp. 19015 100 24X Fichs 50-440, 83/04/21, 8304080161
- E NRC Safety Evaluation Report (SER), tuppis & correspondence
- 8304020494 Submits rept to turbine missile issue Rept completes RRM action requested in ACRS 0.20713 ltr Results documented in Suppl 3 to SER (NUREO-0887) NOVAK, T M Assistant Director for Licensing 03/05/23 RAY, F, I ACRS Advisory Committee on Reactor Safeguards 10pp 10/14 Pi/ 24X Fichs 50-440.83/05/23,8304080694
- 8304010058 Responds to 830804 ltr on procedures generation package per SER Dutstanding Issue 21. Dec 1983 scheduled completion date provided in 830415 suppl to Genoric Ltr 82-33 EDELMAN, M R Cleveland Electric Illuminating Co E0/05/2/YOUNDECOUD, B J Licensing Branch 1 ip 18674 079, 24X Fichs; 50-440,83/05/27,8304010058
- B306080437 Summary of B30526 merting w/util in Betherda.HD re present containment purge sys design.Gutstanding Issue 10 in BCR (NUREO-OGB7)
 BTEFAND.J J Licensing Branch I 83/06/03 YDUNGBLOOD.8 J Licensing Branch I 12pp 18792 197 24X Fiche 50-440.83/06/04 8306080437

- 8306200095 Clarifies commitment to perform add1 start & load qualification testing on standby dissel generators as outlined in SER Section 8 3 1 lotal of 20 add1 tests will be conducted EDELMAN.N R Cleveland Electric Illuminating Co 83/06/15 YOUNGBLOOD, B J Licensing Branch 1 2pp 18903 353 24% Ficha 50-440, 83/06/15, 8306200005
- 8304240249 Forwards study results of effects of grating on drywell & containment response, per SER Dutstanding Issue 9 re pool dynamic loads App 30 incorporated in Amend il to EBAR providing descripts on of hydrodynamic loads EBELMANIN R Cleveland Electric Illuminating Co 83/06/20 YOUNGELOOD, B J Licensing Brunch I hpp 18980 078 24X Fiche 50-440.83/06/20.8306240269
- 8306240064 Notifies that addl 10F0 re lift of safety-related items in FBAR Table 3 2-1 (GA-list) acceptable Outstanding Issue 23 in Suppl 3 to 5ER (NUREG-08B) will be changed to confirmatory issue per FBAR. Amend 12 review YOUNGBLOOD, B J Licensing Branch 1 83706/21 EDELMAN, M R Cleveland Electric Illuminating Co 2pp 18787 134 24X Fichs 50-440.83706/21.8306240064
- 830624028B Requests add1 info to resolve SER Confirmatory Issue 10 re fast scram hydrodynamic leads on control rod drive sys Response within 7 days of 1tr receipt requested YOUNGBLOOD, B J Licensing Branch 1 83/06/21 EDELMAN, M R Cleveland Electric Illuminating Co 3pp 18999 167 24X Fiche 50-440,83/06/21,830624028B
- 8306290137 Submits evaluation findings on outstanding & confirmatory instrumentation & control sys issues documented in SER Addinfo requested Response requested within / days YOUNOBLOOD, II J Licensing Branch 1 83/06/22 EDELMAN, M R Cleveland Electric Illuminating Co 25pp 19046 222 24X Fiche 50-440,83/06/22,8306290137
- F Security, medical, emergency & fire protection plans
- 8306010058 Responds to 830506 itr on procedures generation package per SER Outstanding Issue 21 Dec 1983 scheduled completion date provided in 830415 suppl to General Ltr 82-33 EDELMAN,M R Cleveland Electric Illuminating Co 83/05/27 YOUNGBLOOD, B J Licensing Branch 1 Ip 18674 073 24X Fiche 50-440,83/05/27,8306010058
- G Adjudicatory correspondence
- 830&010433 Motion for summary disposition of Issue 13 No genuine issue of math fact exists & NRC entitled to favorable decision Affidavit. Certificate of Svc & prof qualifications encl CUTCHIN. J. Hearing Branch 4 83/05/31 Atomic Safety and Licensing Board Panel 11pp 18674-257 24X Fiche 50-440.83/05/31, 830&010433
- 830.6090345 Notice of Ghio Citizens for Responsible Energy 1001R7 206 petition alleging false util statements in application reuse of herbicides to control vegetation along transmission lines
 DEYOUNG.R C Director's Office, Office of Inspection and
 - Times

 DEYOUNG, R C Birector's Office, Office of Inspection and

 Enforcement 83/06/06 1p 18794 335 24X Fiche 50-440,83/06/06,

 8306090345
- B306140706 Forwards NRC answers to two ACLB questions posed during B30509 telephone conference re declaration of sua sponte issue Operators will be trained to differentiate between instrument failures & transfents & accidents CUTCHIN.J M Hearing Branch A B3706/13 BLOCH.P B , DRIGHT. C D , MLINE.J R , Atomic Bafety and Liconsing Board Panel 5pp 18841 274 24X Fiche 50-440.83/06/13.8006140706
- 8306160896 Answer opposing Ohio Citizens for Responsible Energy 830510 motion to admit five new contentions on 6NM license application Contentions unjustifiably lateroutside ASLB jurisdiction or moot Certificate of Svc encl SILBERG. J E Commonwealth Edison Co SILBERG. J E Shaw, Pittman, Potts & Trowbridge 83706/13 Atomic Safety and Licensing Board Panel 23pp 18892 286 24X fishe 50-440,83/06/13,8306160596
- 8306160611 Provides estimate of hearing dates In-core thermocouples & steam erosion issue will be disposed of by summary disposition Standby liquid control sys initiation & bydrogen control issues should be resolved by rulemaking Silberg. J E. Shaw, Pittman, Potts & Treubridge Silberg. J E. Cleveland Electric Illuminating Co. 83/06/14 | ILCRO. J E. KLINE, J R. ; BRIGHT, D. D. Atomic Safety and Licensing Board Panel Spp. 168646 097 | 24X Fiche 50-440,63/06/14,8306160611

- 8306220080 Answer apposing NRC 830831 motion for summary disposition of Issue 13 re adequacy of proposed tubine maint program w/turbine missile probability Statement of matl fact & Certificate of Svc enci Related correspondence LOBGE.T J Sunflower Alliance B3/06/15 Atomic Safety and Licensing Board Panel Spp 18930 197 24X Fiche 50-440,83/06/15,8306220080
- B306170399 Advises of incorrect cite in NRC B30713 answer opposing Ohio Citizens for Responsible Energy motion to file contentions on SAN license application CUTCHIN, J M Hearing Branch 4 83/06/16 B10CH, P D, BRIGHT, O D, KLINE, J R Atomic Safety and Licensing Board Panel ip 18880 017 24X Fiche 50-440,83/06/16,8306170399
- 8306270014 Responses to fourth set of interrogatories & request for production of documents Related correspondence HIAFT, S.L. Ohio Citizens for Responsible Energy 83/06/21 Cleveland Electric Illuminating Co. 5pp 18788 050 24X Fiche 50-440,83/06/21,8306270014
- --8306270017 Supplemental response to third set of interrogatories Certificate of Svc encl HIATT,S L Obio Citizens for Responsible Energy 83/06/R1, Cleveland Electric Illuminating Co 3pp 18988 055 24X Fiche 50-440.83/06/R1.8306870014
- 830.2290536 Response opposing NRC 830531 motion for summary disposition of Issue 13 re turbine missile hazards. Motion premature Valuable evidence would be excluded if motion granted Statement of mat1 facts encl Related correspondence HIATT, S.L. Chio Citizens for Responsible Energy 83/06/23 Atomic Safety and Licensing Board Panel 7pp 17052 292 24X Fiche 50-440,83/06/23,8306290536
- --8306290549 Affidavit of BL Hight that Ohio Citizens for Responsible Energy cannot currently present facts to Justify opposition to NRC motion for summary disposition of Issue 13 since info still being reviewed Certificate of Svc encl HIATT, BL Dhio Citizens for Responsible Energy 83/06/23 1App. 19052 297 24X Fichs 50-440,83/06/23,8306290536
- 8306270214 Answer supporting NRC 830531 motion for summary disposition of Issue 13 No genuine issue of matl fact exists & no good cause provided Certificate of Svc enci Related correspondence SILDERO, J E. Cloveland Electric Illuminating Co. BILDERO, J E. Shaw. Pittann. Potts & Troubridge 83/06/87 Atomic Bafety and Licensing Board Panel 12pp. 17054 148 24X Fichs 50-440,83/06/27,8306270214
- --8306270220 Affidavit of DP Timm & LH Johnson, supporting NRC 830531 motion for summary disposition of Issue 13 Prof qualifications enci TIMO, D P. JUBNSON. L. H. NRC - No Detailed Affiliation Given. TIMO, D P. General Electric Co. 83/06/24 35pp 19056:160 24X Fiche 50-440,63/06/27,8306290214
- --8306270240 Affidavit of EJ Turk, supporting NRC 830831 motion for summary disposition Util will follow 9E recommendations retesting of overspeed protection sys Prof qualifications encl TURK, E J NRC No Detailed Affiliation Given * Cleveland Electric Illuminating Co 83/06/24 Spp 19086 195 24X Fiche 50-440.83/06/27.8306270214
- H Ceneral correspondence
- 8304030288 Notice of change of counsel address Certificate of Evc encl LONGE, T J B3705/31 lp 18703,357 24X Fiche 50-440,83/05/31,8304030208
- 8306290144 Ack receipt of 830516 ltr forwarding council Resolution 1443-83 re quality of containment vessal welds Summany rept of 830504 site visit encl Completed rept of review of util commitments expected in Jul 1983 DENTON, HR Office of Nuclear Reactor Regulation, Director 83706/22 EULERT, O A Perry, CH 4pp 19046 250, 24X Fiche 50-440,83706/22.8306290144
- Q Inspection reports: IE Bulletins & correspondence
- 8306270112 Ack receipt of 830415 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-440/83-06 & 50-441/83-06 SPESSARD.R L. Division of Engineering 83/04/22 EDELMAN.M R Cleveland Electric Illuminating Co ip 18788.097 24X Fiche 50-440.83/04/22.8306270112

- --8306270115 Responds to NRC 830316 ltr re violations noted in If Insp Repts 50-440/83-06 & 50-441/83-06 Corrective actions QC insp rept written for each concern identified during LK Comstock Task Force document review EDELMAN.M R Cleveland Electric Illuminating Co 83/04/15 SPESSARD, R.L. Division of Engineering Spp 18788 078 24X Fiche 50-440,83/04/22,8306270112
- 8308030149 Forwards IE Insp Repts 50-440/83-08 & 50-441/83-07 on 830301-03 & 11 No noncompliance noted LITTLE.W 9 Region 3. Office of Director 83/05/16 EDELMAN, N & Cleveland Electric Illuminating Co 2pp 18704 253 24X Fiche 50-440,83/05/16 8308030149
- --8306030151 IE Insp Repts 50-440/83-08 & 50-441/83-07 on 830301 03 & 11 No noncompliance noted Major areas inspected LK Comstnck personnel qualifications (6A/00 & craft personnel & licensee actions on previously identified items BARRETT.P A , NAIBU.K R , PELKE.P R Region 3, Office of Director 63/05/12 | 13pp 18704 255 24X Fiche 50-440,83/05/16,8306030149
- 8305110458 IE Info Notice 83-32. "Ruptured Am-241 Sources Contained in Wall Logging Device " Syc list encl TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103). 83/05/24 Consolidated Edison Co of New York, Inc 125pp 18831 043 24X Fiche 50-000.83/05/26.8305110458
- 8308110460 IE Info Notice 83-34, "Event Natification Info Worksheet" Svc list encl.
 JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc. 115pp 18732 085 24X Fithe 50-000,83/05/26,8305110460
- 8305110441 IE Info Notice 83-35, "Fuel Novement W/Control Rods Withdrawn at BWRs " Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/31. Consolidated Edison Co. of New York, Inc. 116pp 18732 208 24X Fischs 50-000, 03/05/31.8305110461
- 8306160242 Forwards IE Insp Repts 50-440/83-12 & 50-441/83-11 on 830418-22 & notice of violation LITTLE.N S Region 3. Office of Director 83/06/03. EDELNAN.N R Cleveland Electric Illuminating Co 2pp 18861 226 24X Fiche. 50-440, 83/06/03. 8306160242
- --8306160254 IE Insp Repts 50-440/83-12 & 50-441/83-11 on 830418-22 Noncompliance noted failure to perform routine monthly intp on stored items HUNT, M D . MERRIHEATHER, N Region 2, Office of Director CONLON, Y. E. Division of Engineering & Radiological Safety Programs. 93/05/11 &pp 18061-229, 24X Fiche 80-440,83/06/03, 8304160242
- 8306130299 Ack receipt of 830531 ltr informing NRC of steps taken to correct violations noted in 1E Insp Repts 50-440/83-09 & 50-441/83-08 LITTLE W S Region 3. Office of Director 83/06/08 EDELMAN W R Cleveland Electric Illuminating Co ip 18823 320 24X Fiche: 50-440/83/06/08.8306130299
- --B306130308 Responds to NRC 830401 ltr re violations noted in IF Insp Repts 50-440/83-09 & 50-441/83-08. Corrective actions manitoring program consisting of periodic visual exam of suppression pool welds performed from platform EDELMAN.M R. Cleveland Electric Illuminating Co 83/08/31 KEPPLER, J G Region 3. Office of Director 2pp 18823 32: 24X Fiche: 50-440, 83/06/08, 8306130299
- 8306230267 Forwards IE Insp Repts 50-440/83-14 & 50-441/83-13 on 830425-28 No noncompliance noted LITLE.W B Region 3. Office of Director 83/06/08 EUCLMAN, M R Cleveland Electric Illuminating Co 2pp 18945 086 24X Fichs 50-440,83/06/08.8306230267.
- 8305110464 IE Info Notice 83-36. "Impact of Security Practices on Sofe Operations " Syc list encl JORBAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103). 83/06/09 Consolidated Edison Co of New York, Inc. 117pp 18830 280 24X Fiche 50-000,83/06/09,8305110464

- 8305110470 JE Info Notice 83 38, "Defective Heat Sink Adhesive & Seismically Induced Chatter in Briags Within Brinted Circust Cards" See list end JORDAN E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 33706/13 Consolidated Edison Co. of New York, Inc. 118pp 18920 P2°5 24X Fishe 50-000, BS/06/13, 8305110470
- B306090010 IE Info Notice 83-3/. "Inausformer failure Resulting From Degraded Internal Connection (ables "Evol list encl JORDAN, E. L. Division of Imergebry Preparedness & Engineering Response (Post B30103) B3/00/13 (Obsolidated Edison Co. of New York, Inc. 243pp 18921 001 24X Fishe 50-000 B3/06/13, 0306090010
- 8306300201 Forwards IE Inspikepts 50-440/u3 17 % 50-441/83-16 un 830301-0430 No noncompliance noted RNDP.R C Region 3. Office of Director 03/06/14 EDELMAN, H R Cleveland Electric Illuminating Co 2pp 1919-359 24X Fiche 50-440.83/06/14.8306300201
- --8306300207 IE Insp Repts 50-440/83-17 % 50-441/80 16 on 830301 04%0 No noncompliance moted Major areas inspected safety-related const activities, including 1008/850 55(e) reportable item followup, housekoeping & preparation for ASLD hearings OILDNER, M.L., KORKLIN, J.L., Region 'D. Office of Director 83/06/14 Jpp 19119 J51 24X Fiche 50-440,83/06/14.8J06/90001
- 8306300179 Forwards IE Insp Rept. 50-440/U3 16 & 50-441/83 15 nn 830518-19 No noncompliance nated KMOP.R C Region 3. Office of Director 89/06/15 EBELMAN, M H Cleveland Cletchric Illuminating Co. 2pp 19119 263 24X Fiche 50-440,83/06/15 8306300179
- --83063001BJ IE Insp Repts 50-440/83-16 & 50-441/83-15 on 830518-19 No noncompliance noted Major areas inspected licensen actions on previous insp findings IOC(R50 55(c) reportable items & IE bulletins
 PELKE.P R . KONKLIN.J E Region 3. Office of Director DY/08/15
 4pp 19119 265 24X Fiche 50-440.0/1/06/15.8306/300179
- 8306300126 Forwards IE Insp Repts 50-440/03-15 t 50 441/43-14 on 830509-13 No mencompliance noted LITTLE.N S Region 3. Office of Directos 83/06/17 CDELMAN,N R Cleveland Electric 1110minating Co 2pp 19122 323 24X Fiche 50-440,03/06/17.8306300126
- --B306300172 IE Insp Repts 50-440/83-15 & 50-441/83-14 on 830/07-17 No noncompliance noted Major areas inspected safety-related cable tray installation, electrical cubies & terminations & equipment installation MERRIVEATHER, N . CONLON.T I Region 2. Office of Director 83/06/02 4pp 19122 325 24X Fiche 50-440,83/06/17,8306300126
- 8305110475 IC Info Notice B3-40. "Need to Environmentally Guality
 Epoxy Grouts & Sealers " Svc list out!
 JORDANIE L Division of Energency Preparedness & Engineering
 Response (Post 830103) B3/06/22 (consolidated Edison Co
- 8305110477 IC Info Notice 83-41. "Actuation of fire Suppression Bys-Causing Inoperability of Safety-Related Equipment." Svc. list. encl. JORDAN, E. Division of Lawryency Preparadness & Engineering Response (Post 830103) 83/04/22 Consolidated Edition Co. of New York, Inc. 120pp 18997 007 247 Fiche 50-000, 83704/22, 83051104/7
- 8305110477 IE Info Notice 83-42. "Reactor Mode Switch Mulfonctions " Svc list encl JORDAN, Et Division of Emergency Preparadness & Engineering Response (Post 830103) 83/06/23 Consolidated Edison Co of New York, Inc 114pp 18996 242 247 Fiche 50-000,83/06/23,83051104/9
- 8306270283 Ack receipt of 830607 ltr informing NRC of steps taken to correct violations noted in II lisp Repts 50-440/87-11 & 50-441/83-10 LTTLE, W S Region 3, Office of Director 83/06/23 CDELMAN, H R
 - 90-441/M3-10 LITTLE W S Region 3, Office of Director 83/06/23 CDELMAN, H R Cleveland Electric Illuminating Co ip 18996 173 24X Fiche 50-440, 83/06/29, 8306270203
- --8306270287 Responds to NRC 830509 ltr re violations noted in IC Insp Repts 50-440/B3-11 & 50-441/B3-10 Corrective actions Johnson Controls Procedure 0AS-1802 PAPP, "Review & Turnavir of Records: "revised to reflect present document review EDELMAN, H.R. Cleveland Liectric Illuminating Co. 83/06/09 KEPPLER, J.O. Argion 3, Office of Director 2pp. 18996-174, 24K Fishe 50-440,03/06/23,83062/02/83
- B3051104B3 IE Info Notice B3-43, "Improper Settings of Intermediate Range (IR) High Flux Trip Betpoints "Syc list encl JORDAN, C t Division of Lawrgency Preparedness & Engineering Response (Post B30103) B3/06/24 Consolidated Edison Co of New York, Inc 116pp 19046 297 P4X Fiche 50-000, B3/06/24, B3051104BJ

- S Reportable occurrences, LLRs & related correspondence
- 8304100119 Fifth interim deficiency rept re rejection of previously 304100119 Fifth interim deficiency ript re rejection of previously accepted containment vessel radiographs Review of radiographs utilizing film overlay techniques being performed Next ropt will be submitted by 830930 EDELMAN. Hr Cleveland Electric Illuminating Co 83/05/31 KEPPLER, J G Region 3, Office of Unjector in 16802 02% 24X Fiche 50-440,83/05/31,8304100119
- 8306220015 Interim deficiency ript re sensitivity & density variations in Borg-Wainer valve radiographs Initially reported on 830411 Sampling plan to determine valve acceptability established final rept by 830/10 Also reported per Port 21 EBELMAN.M R Cleveland Electric Illuminating Co 83/06/10 KEPPLER, J G Region 3, Office of Director 2pp 18927 330 P4X Fiche 50-440,83/06/10,8306220015
- 8306220058 Famal deficiency rept re-patentially inadequate cooling of RCIC roum during LOCA Initially reported on 830513 AE reviewing RCIC pump/turbing nathmatic start Review will be completed by B30729 Also reported per Part 21 EDELMAN.N R Cleveland Electric Illuminating Co 83/06/10 KEPPLER.J G Region 3. Office of Directol 2pp 18930 034 24X Fiche 50-A40,83/06/10,8306220050
- 9306200120 Notifies that rework associated w/potentially significant deficients to governor drive coupling mfg by Transamorica Delaval in standby diesel generators, schoduled to he completed by 831031 for Unit 18, 831231 for Unit 2 EDELMAN, N R Cleveland Electric Illuminating Co. 83/06/14 KEPPLER. V G. Region 3, Office of Director ip 18903 329 Fichs 50-440, 83/06/14, 8306200120
- 9305220039 Supple final deficiency rept re matl used in Transamerice Delaval, Inc governor drive coupling in standby diesel generator: Due to long storage time, governors will be returned to manufacturers for overhauling & recalls:
 EDELMAN, M R Cleveland Electric Illuminating Co 83/06/14
 KEPPLER, J G Region 3. Office of Director lp 18930 179 24X
 Fiche 50-440.83/06/14.8306220039
- 8306300169 Suppl to 810803 final deficiency rept re Mone-Sol In and 7-0019-3 CO5 polyvinyl alcohol film, water soluble purge dam matt mfg by Chiis Craft Industries Politions of sys will be flushed prior to fuel loading EDECMAN. M R Cleveland Electric Illuminating Co B3/06/27 KEPPLER. J G Region 3. Office of Director 3pp 19121 360 P4X Fiche 50-440, 03/06/27, 9306300169
- T Hearing transcripts on non-antitrust matters
- 8304010004 Transcript of 830525 hearing in Painesville, OH Pp 1,227-
 - 1.434 Atomic Bafety and Licensing Woard Panel 83/673 053 24X Fiche 50-440,83/05/25,8306010006 83/05/25 Riter
- 8308010010 (ranscript of 830526 hearing in Painesville, OH Pp 1,437.
- 1.706 Supporting documentation encl
 * Atomic Safety and Licensing Board Penel 83/05/26 314pp
 18671 224 24X Fiche 50-440.83/05/26.8306010010
- 830&010004 Transcript of 83052/ hearing in Painesville, CH Pp 1.707-1.87/ Supporting documentation encl
 Atomic Safety and Licensing Board Panel 83/05/27 174pp
 18665 200 26% Firhe 50-440,83/05/27,839&010004
- 8306070149 Transcript of 830531 hearing in Painesville.OH Pp 1:879-1,780 Supporting documentation earl * Atomic Safety and Licensing Board Panel 83/05/31 127pp 18737 OOI 24X Fiche 50-440,83/05/31:6506070149
- DOCKET 50-449 SEABROOK NUCLEAR STATION, UNIT 1
- A Application/construction stage documents & correspondence
- 8306020039 Notification of 830607 significant licenses meeting w/otil & Pullman Higgins in King of Prussia, PA to discuss performance of site contractor HOLDEN, C. Region 1, Office of Director 83/05/25 Region 1, Office of Director 83/05/25 Region 1, Office of Director 1p 18702 323 P4X Fiche 50 443,83/05/25, 8304020039
- 830&010448 Application to amend & renew (PPR-135 & CPPR-136, extending const completion dates to 841031 & 881v51, respectively Factors delaying const listed JOHNSON, W.P. Yankee Atomic Electric Co. JOHNSON, W.P. Public Service Co. of New Hampshile 83/05/26 DENTON, H.R. Office of Nuclear Reactor Regulation, Disector. Upp. 18674-309 24X Fiche 50-443.0J/05/26.830&010440

- 8306240462 Summary of 830511 morting w/util re basis for projecting fuel load date of Sept 1984 for Unit 1
 WHEELEK,L Licensing Branch 3 83/06/10 Licensing Branch 3
 4pp 1898 805 24X Ficho 50-443, 83/06/10, 8306240462
- 8306230452 Forwards revised response to NUREG-0612, "Control of Heavy Loads " Rev addresses NRC comments contained in draft technical evaluation rept dtd 821123 & supplemented by NRC 921229 1ts B2128 Ith DEVINCENTIS.J Yankee Atomic Flectric Co DEVINCENTIS.J Public Service Co of New Hampshire 83/06/20 KNIGHTON 6 W Licensing Branch 3 2pp 18941 001 24X Fiche 50-443,83/06/20,8306230452
- --8306230458 "Response to NRC Generic Request for Addl Info Re NUREG-0612.Control of Heavy Loads " + United Engineers & Constructors. Inc. (subs. of Raytheon Co.) 7743 006-8-N-5 83/05/31 147pp 18941 004 24% 9743 004-8-N-5 B3/05/31 147pp Fiche 50-443,83/04/20,8304230452
- E NRC Safety Evaluation Report (SFR), supple & correspondence
- B306030177 Forwards response to request for add1 info re open item in SER, Section 7 J 2 B concerning effects of high temps on reflegs of steam generator & pressurized water level measuring instruments after high energy line breaks DEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J Public Bervice Co of New Hampshire 8 23/05/31 KNIGHTON, 0 W Licensing Branch 3 11pp 18703 313 24X Fiche 50-443, 83/05/31, 8306030177
- 8306080125 Forwards SER open item response to Chemical Engineering Granch request for add1 info re NUREG-0737, Item II B 3, "Post-Accident Sampling Capability "Info supple 82120! response & OL application Amend 4B DEVINCENTIS, J Yankee Atomic Flectric Co DEVINCENTIS, J Public Service Co of New Hampshire 83/05/31 KNIGHTON, G W Licensing Branch 3 21pp 18772 333 24X Fiche 50-443,83/05/31,8306080125
- 8306200236 Forwards "Containment Ultimate Capacity of Beabrook Station Units I & 2 for Internal Pleasure Loads." in response to Request for Add) Info RAI 220 37 & BER Section 3 8 1 Rept will be referenced in OL application Amend 49
 DEVINCENTIS. J Yankee Atomic Flectric Co DEVINCENTIS. J Public Service Co of New Hampshire 83/06/07 KNIGHTON. 6 W Licensing Branch 3 2pp 18903 001 24X Fiche 50-443.83/06/07.8306200236
- --8306200242 "Containment Ultimate Capacity of Seabrook Station Units 1 & 2 for Internal Pressure Loads " W/eight oversite figures Aperture cards are available in PDR * United Engineers & Constructors, Inc. (subs. of Raytheon Co.) 83/02/28 75pp 18703 003 P4X Fiche 50-443,83/06/07.8306200236
- 8306200930 Forwards response to Meteorological & Effluent Treatment Sys Branch draft SER open items per 830518 meeting request Response will be incorporated in Amend 50 to OL application & FBAK DEVINCENTIS, J. Yankee Atomic Electric Co. DEVINCENTIB, J. Publi Service Co. of Now Hampshire 93/06/15 KNIGHTON, G.W. Licensin Branch 3 3pp 18900 350 £4% Fiche 50-443.83/06/15,830&200330 DEVINCENTIBAJ Public
- 830620039/ Forwards supplemental response to SER Section ii 5.2 re need for gross radioactivity monitor in svc water sys Response will be incorporated in Amend 50 to OL application & FSAR DEVINCENTIS, J. Yankee Atomic Electric Co. DEVINCENTIS, J. Public Service Co. of New Hampshire 83/06/15 KNIGHTON, 6 W. Licensing Branch 3. 4pp. 18899-037 (20% Fiche 50-443,83/06/15,8306200397.
- G Adjudicatory correspondence
- 9306150256 Forwards Suppl 1 to SER (NUREG-0896), addressing two 304150256 Forwards SUppl 1 to SLH (NUREG-0876), addressing two outstanding issues re emergency preparedness & secondary water chemistry Corrected page to NRC B20420 joint affidavit & WT LeFave B30511 affidavit encl W/o BER, LEBSY,R P, PATTERBON.W F Hearing Branch 3 83/05/11 HOYT.H, LUEDKE,E A, HARDOUR,J Atomic Safety and Licensing Board Panel, 2pp 18849 191 24X Fiche 80-443.83/05/11,8306150256
- --8306150259 Affidavit of WT LeFave, detailing corrections to NRC joint affidavit of C Liang, WT LeFave & 58 Kirslis, Paragraphs 9 & 10 re environ qualification of nonsafety-related valves valves not needed for safe shutdown under LOCA conditions LEFAVE, WY Auxiliary Systems Branch 83/05/11 2pp 18849-193. 24X Fiche 50-440,83/05/11 (8306180254
- --8306150262 Corrected Paragraphs 9 & 10 to joint affidavit of C Liang, WT LeFave & SS Kirslis re environ qualification of nonsafety-related valves, filed on 830420 LIANG.C. LEFAVE, W T. KIRSLIS, S S. NRC No Detailed Affiliation Given 83/05/11 lp 18049 195 PAX Fichs 50-443,83/05/11, P204150254 Given 83, 8306150256

- 8306150238 Response opposing New England Coalition on Nuclear Pollution 830512 motion to file out-of-time answer to NRC affidaviting environ qualification of electric valve operators. Unavailability of consultant does not justify late response PATTERSON W.F., LESSY, R.P. Heaving Branch 3 83/05/24 Atomic Safety and Licensing Board Panel 5pp 18847 263 24%. Fiche 50-443,83/05/24,8306150238
- --8306150431 Affidavit of C Liang re environ qualification of electric valve operators C8-HCV-189, C8-HCV-190 & RC-VB1 Valves not required to be environmentally qualified since letdown ty; not in use during post-accident operations LIANG, C. Reactor 9ystems Branch 93/05/24 5pp 18847 273 24x Fiche 50-443,83/05/24,8306150238
- --8306130437 Affidavit of WT Lefave re electric valve operators
 8A-8V-4A/4D Operators not amportant to safety & do not need
 to be environmentally qualified No fallure mode of valves
 exists due to harsh environ that could affect safe shutdown
 LEFAVE.W T Division of Systems Integration (post 811005)
 83/05/24 3pp 18847 278 24% Fiche 50-443,83/05/24,8306150238
- 8304010342 Objection to ASLB 830511 memorandum & order re Contentions NH-9 & NH-13 & to rationale for granting of summary disposition on contentions Order should be reconsidered & contentions readmitted Cortificate of Svc encl BISBEE. O D New Hampshire. State of 83/05/24 Atomic Sufety and Licensing Board Panel 7pp 18690 084 24X Fiche 50-443.83/05/26.8306010342
- 8306010382 Petition for directed certification of ASIB summary disposition dismissing Contention II K 4 on GA for replacement parts ASLB ruling flagrantly illegal & sets dangerous precedent CURRAN,D., JORDAN,W 9 New England Coalition on Nuclear Pollution CURRAN,D Harmon & Weiss GS/05/R6 Atomic Bafety and Licensing Appeal Panel 10pp 18682 160 24X Fishe 50-443,83/05/26.
- 8304010384 Motion for 3-day extension to 030523 for filing objection to ASLO 830511 memorandum & order Delay due to unexpected involvement in federal court litigation BISBEE 0 D New Hampshire, State of 03/05/26 Atomic Safety and Licensing Board Panel ip 18682 170 24X Fiche 50-443,83/05/26,8304010384.
- 830A010444 Appeal of dismissal of Class 9 accident Contention 3 pi, in alternative, request for certification per 10CFR2 718(i). Issue central to determining whether OL should provide for mitigating features Certificate of Svc encl. BACKUS, R. A. Seacoast Anti-Pollution League 63/05/26 Atomic Safety and Licensing Appeal Panel 9pp 18074-354 24X Fichs: 50-443, 83/05/26, 8306010444
- B306010437 Forwards LL Bishop notice of withdrawal as counsel for New England Conlition on Nuclear Pollution CURRAN. D. Hunton & Milliams B3/05/2/ HOYT, H F Atomic Safety and Licensing Board Panel 1p 18679 302 24X Fichs 50-443,83/05/27.8306010437
- --8306010443 Notice of withorawal as counsel for New England Coalition on Nuclear Pollution Certificate of Svc encl BIGHOP.L L. Hunton & Williams 83/05/26 3pp 18679 303 24x Fichs 50-443.83/05/27.8306010437
- 8306010446 Forwards, under separate cover, exhibit to New England Coalition on Nuclear Pollution 830526 petition for directed certification CURRAN, D. Harmon & Weiss. B3/05/27 ROSENTHAL, A.S. Atomic Bafety and Licensing Appeal Panel. Ip. 18674-326. 24X Fiche 50-443,83/05/27,8306010446
- 8306020169 Requests deferral of responses to applicants motion for summary disposition of New England Coalition on Nuclear Pollution Contention I D 2 re reactor trip sys until 20 days after svc of NUREO-1000. Vol 2
 PERLIB.R O Hearing Branch 3 83/05/31 HOYT.H. LUEBKE, E A . HARBOUR.J Atomic Safety and Licensing Board Panel 2pp 18690; 361 24X Fiche 50-443,83/05/31,8306020169
- B306020361 Notice of ASLAB constitution AS Rosenthal, chairman, OJ Ldles & HA Wilber, members BHOEMAKER, C J. Atomic Safety and Licensing Appeal Panel 83/05/31 pp. 18474 330 24x Fiche: 50-443; 83/05/31; 8306020361
- 830&030355 Forwards New England Coalition on Nuclear Pollution 830&01 objection to applicant twenty-first motion for summary disposition of Contentions III 2 & III 15. Renotarized affidavit of PB Herr available upon request CURRAN.D Hunton & Williams. CURRAN.D New England Coalition on Nuclear Pollution 830&001 HOYT.H.F. Atomic Safety and Licensing Board Panel 1p 18705 215 24X Fiche 50-443,83/06/01.830&03055

- --8306030357 Objection to applicant twenty-first motion for runmary disposition of Contentions III 2 & III I3 Affidavit of JA MacDonald insufficient or matter of law to support grant of summary disposition Statement of mill facts each CURRAN, D. New England Chalition on Nuclear Pollution (URRAN, D. Hunton & Williams 83/04/01 Atomic Safety and Liconaine Beard Panel 2pg 18705-216 24X Fiche 50-443, 83/04/01, 83040 10355
- --8306030363 Affidavit of PB Heir on (antentions II) 12 & 13 to documentation in support of applicant 8.0214 twenty-first motion for support of applicant 8.0214 twenty-first motion for support dispersion Coefficient of Svc encl HERR. F B New England Coalition on Nuclear Pollution MCM's, P & Massachusetts Institute of Technology 83/05/22 287pp 18705 218 247 Fichs 50-44% 83/06/01.830603055
- 8306070411 Advises that Commonwealth of MA Civil Defense Agenty whatle to meet 830601 target date for submission of state area plan to FEMA New target date is 830815 BHOTWELL, J.A. Massachusetts, Commonwealth of, 83/06/01 NUMLH, PARIS, D.H., LUEBKE, E.A. Atomic Safety and Licensing Board Famil 2pp 18/42 271 24% Fiche 50-443,83/06/01,8306070411
- B304080053 Response supporting util motion for summary disposition of New England Coalition on Nuclear Pollution Contentions
 III 12 & III 13 & opposing util motion for summary disposition of State of NH Contention 21
 PERLIB.R C , LESSY, R P Hearing Branch 3 83/06/06 Atumit
 Safety and Licensing Board Paniel 8pp 187/3 176 24X
 Fichs 50-443,83/06/06,8304080053
- --8305080057 Affidavit of JR Seers Util has not provided info necretary to comply w/onsite protective measure requirements. Evacuation time estimates accurate & useful Certificate of Svc encl
 SEARS.J R EP Licensing Branch 83/04/03 7pp 18/73 184 74x Fiche 50-443.63/04/06.8304080083
- 830408008B Response apposing Seacoast Anti-Pollution League (19514 motion to amend intervention petition by adding new contention re instrumentation for detection of inadequate core cooling Motion untimely Certificate of Svc encl PATTERSON.W F. LESSY:R F. Hearing Breuch 3 83/04/04 Alumit Safety and Licensing Board Panel Opp 18773 255 P4X Fiche 50-443,03/04/04.8304080080
- 8304080144 Order advising that supplemental answers to util motion for summary disposition of New England Condition on Norlear Pollution Contention I D 2 due 20 days after see of Vol 2 of NRC rept on implications of ATMS incident at Balem HOYT.M.F. Atomic Safety and Licensing Board Panel 83/04/06 (7) 18772 155 24% Fiche 50-443,83/04/06,8384080166
- 830608D176 Order denying New England Coalition on Nuclear Pollution B30912 mution to file out-of-time answer to NRC affidavit reserving qualification of electric valve operators Issue decided twice & will not be considered again HOYT.H F Atomic Bafety and Licensing Board Panel 83/Q6/U6 England Coalition on Nuclear Pollution 2pp 18772 276 1988 Fithe 50-443,63/06/06.83060001/6
- 83060B0186 Memorandum advising that State of NH 830526 objections to ASLB 830511 order not filed late Objections will be considered HOYT.H F Atomic Safety and Licensing Board Panel 87/06/06 [19] 18772 PSB 24X Fiche 50-443.83/06/06.83060B0186
- 8306150387 Response opposing New England Coalition on Nuclear Pollutapetition to ASLAB for directed certification of ASLB 830011
 memorandum & order dismissing Contention II B 4 Petition
 should be dismissed Certificate of Sec engl
 DIONAN.T G, GAB.R K, Public Service Co of New Hampshire
 DIONAN.T G Ropes & Gray 83/06/08 Atomic Safety and Licenses
 Appeal Penel 9pp 16847 239 24X Fiche 50-443.83/06/08.
- 8306150388 Response opposing Seacoast Anti-Pollution League appeal of dismissal of Class 9 accident contention or, alternatively.

 request for certification Appeal should be dismissed & i directed certification desired Certificate of Svc encl
 DIONAN. T 0 , OAD, R K Public Service Co of New Hampshire
 DIONAN. T 0 , Ropes & Gray B3/06/08 Atomic Safety and Isently appeal Panel Spp 18847 196 24X Ficher 50-443,83/06/08, B306150388
- B306150357 Ack receipt of B3060B ltr & entls HA Wilber, not Qatchy, assigned to ASLAB
 TOMPKING, B A Atomic Bafety and Licensing Appeal Panel (37/06/13)
 OAD, R.K. Ropes & Gray ip 18847 267 24X Fiche 50-443,03/06/13 ;
 B306150357

- 8306200173 Response opposing New England Coalition on Nuclear Pollution & Seacoast Anti-Pollution League petitions for directed certification of ASLB 830511 order Petitions do not meet requirements for discretionary review W/Certifiate of Svr LESSY.R P. PATTERSON.W F. PURLIS.R C. Hearing Branch 3 83/06/15 Atomic Safety and Licensing Appeal Panel 28pp 18903 145 24X Fiche 50-443.87/06/15.8306200173
- B306270256 Expresses concern re draft emergency resource plan Draft does not accurately reflect or address emergency response plan for Mest Newbury Related correspondence CMUTE/M "Jest Newbury, DA 87/06/15 LOMASNEY,M Costello. Lumasney & deNapoli. Inc. Sup. 10990 21." 24X Fiche 50-443.83706/15.8306270766
- 830622007/ Requests OJ Humphrey be added to svc list LEMIS D R Atomic Safety and Licensing Board Panel 63/06/16 Office of the Executive Logal Director ip 18930-161 P4X Fiche 50-445, B3/06/16, 8306/2007/
- 8306220085 Deletes R Cashman & adds M Pranson to syc list as lown of Amesbury, NR representative LEWIS.D R Atomic Safety and Licensing Board Panel 83/06/16 Office of the Executive Legal Director 1p 1892/181 24X Fiche 50-443,83/06/16-8306220005
- 8306220100 Requests RC Miller be deleted & DR Lewis added to sec list COFELAND, J. F. Atomic Safety and Licensing Board Panel 83/06/16 Office of the Executive Legal Director (p. 1892/ 1/0 74X Fiche 50-443, 83/06/16, 8306220100
- B306220079 Memorandum & order denying Beacoast Anti-Pollution League B30516 motion to amend petition to intervene No good cause shawn for late filing Admission of Contention Sppl / would not assist in developing sound record MOYT.H F Atomic Safety and incensing Board Panel 83/06/20 Seacoast Anti-Pollution League App 18927 189 24X Fiche 50-443,83/06/20,83042200/9
- 8306220077 Memorandum & Order Al AB-/31 dismissing Beacoast AutiPollution Leaque (SAPL) appeal of & denying request for
 certification of portion of ASLB 830511 order growting
 summary disposition of SAPL Supplemental Contention 3
 FOMPKING.B A Atomic Safety and Licensing Appeal Panel
 Seatoast Anti-Pollution League 3pp 18927-016 24X
 Fiche 50-443,83/06/20,8306200097
- B306220099 Memorandum & order schoduling B30/13 oral argument in Bethesda, MD ro Now England Coalition on Nuclear Pollution petition for directed certification of ASI B 830511 order granting summary disposition on Contention II B 4 TOMPRING, B A Atomic Safety and Licensing Appeal Panel B*/06/20 7pp 18926 174 24X Fiche 50-443,83/06/20,8306220099
- B306270249 Memorandum providing schedule of locations & ASI II anticipated hearing & limited appearance session dates HDYT.H F Atomic Safety and Licensing Board Panel B3/06/22 2pp 18990 217 24X Fishe 50-443, U3/06/22, U306270249
- 8306270306 Response opposing State of NH 030526 objections to ASLB 030511 momorandum & order ruling on motions for summary disposition No mods to ASLB conclusions warranted Certificate of Svc encl LESSY.R P. PATIERBON.W F. Hyaring Branch 3 83/06/22 Atomic Gafety and Licensing Board Panel 11pp 18975 208 24X Fichs 50-443,63/06/22.83067/0306
- 030A280512 Informs that add1 work needed in listed areas of draft emergency plan Traffic & areass control point section of plan must be completed so entire draft can be analyzed Related correspondence RIEL. & L. Ngwbury, MA 03/06/22 LOMAGNEY, M. Castello, Lomasney & deNapola, Inc. 2pp 19016 191 24X Fiche 50-443.03/06/22, 8306200512
- B308290521 Contentions on State of NH radiological emergency response plan Certificate of Svc encl BACKUS: R A Seaconst Anti-Pollution League BACKUS: R A Notkus, Shea & Meyer B3/06/22 Atomic Safety and Licensing Board Panel Bpp 19059 195 24X Fiche 50-443, B3/06/22, B306270521
- 8306280553 Contentions re emergency planning for State of NH Certificate of Byc entl BELLOTTI:F X Texas, State of 83/06/23 Atomic Safety and Licensing Board Panel 36pp 19018 066 24X Fiche 50-443,83/06/24, 8306280553

- 8306280543 Response opposing State of NH B30511 filing Request for reconsideration of ASLB B30511 memorandum & order should be denied Issue in Contention NH-9 not ripe for litigation Certificate of Svc encl D10NAN.TO. OADLR K. Public Service Co. of New Hampshire D10NAN.TO. Ropes & Oray. 63/06/24 Abomic Safety and Licensing Board Panel. 16pp. 19019-32/ 24X Fiche 50-443.83/06/24.
- B306290532 Errata to Seacoast Anti-Pollution League contentions on State of NH radiological emergency response plan Certificate of Svc encl
 BACKUB, R A Seacoast Anti-Pollution League BACKUB, R A Backus,
 Bhea & Meyer B3/06/24 Atomic Bafety and Licensing Board Panel
 Tpp 19052 324 24X Fiche 50-443, 83/06/24, 8306290532
- 8306270556 Contentions on State of NH radiological emergency response plan. Vol 1 Certificate of Bvc encl CURRAN. D . JOHDAN. H S New England Conlitton on Nuclear Pollution CURRAN. D . Harmon & Weiss 83/06/27 Atomic Bafety and Licensing Board Panel 24pp 17052 217 24X Fiche 50-443.83/06/27.
- O Inspection reports, IE Bulletins & correspondence
- 8306080259 Addl response to FDIA request for nine separate categories of documents re facilities Forwards documents listed in App A App B documents completely & partially withheld (ref FDIA Exemptions (& 7) FELTON, J M Division of Rules and Records 83/04/06 KINDER, E. T. New Hampshire, State of App 18790 315 24X Fiche 50-443, 83/04/06,8306080259
- --8306080263 Forwards results of licenser investigation of Pullman-Higgins GC inspector altagations re perceived harassment of GC inspectors from within organization & documentation of organization changes

 CERNELA C Region 1, Office of Director 82/07/16 Region 1, Office of Director 7pp 18790 319 24X Fiche 50-443,83/04/06,8304080259
- --8306080264 Discusses GC Inspertor conterns within Pullman-Higgins arganization (facility piping contractor) re-perceived harassment of GC inspectors by P-H const personnel Closure of case recommended CERNE.A C Region 1. Office of Director 82/10/13 Region 1. Office of Director 2pp 18770-326 24X Fichs 50-443.83/04/06,830600259
- --8306080266 Discusses Pullman Higgins (P-H) QC inspector conterns re allegations of harassment of QC inspectors by P-H const personnel Personally identifiable info deleted CERNE. A C Region 1. Office of Director 82/06/09 Region 1. Office of Birector 2pp 18790 328 24X Fiche 50-443.83/04/06, 8306080257
- --8306080269 Discusses nonspecific allegations re Pullman-Higgins GA/GC inspectors at facilities Personally identifiable into deleted
 MATAKASIR A Region 1, Office of Director 82/09/27 OALLO,R N
 Division of Project & Resident Programs 2pp 18790 336 P4X
 Fiche 50-4443 83/04/96,830608259
- 8306010442 Ack receipt of 830502 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-443/83-02 & 50-444/83-02 STARDSTECKI.R Division of Project & Resident Programs 83/05/28 HARRISON.R J Public Service Co of New Hampshire in 18474 302 24X Fichs 30-443,83/05/25.8306010442
- --8306010449 Responds to NRC 830404 ltr re violations noted in 1E Insp Repts 50-443/83-02 & 50-444/83 02 Corrective actions craft personnel reindactrinated. GC personnel will monitor safetyrelated supports & site contractor GA audited DEVINCENTIS, J Yankee Atomic Clectric Ca DEVINCENTIS, J Public Service Co of New Hampshire B3/05/02 BTAROSTECKI.R Division of Project & Resident Programs App 18674 303 24X Fiche 50-443, 83/05/25, 8304010442
- 8305;10458 IE Info Notice 83-32. "Ruptured Am-241 Sources Contained in Well Logging Device " Svc list encl TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 125pp 16831 043 24% Fiche 50-000, 83/05/26, 8305110458
- 8305110460 IC Info Natice 83-34. "Event Notification Info Worksheet"
 8vc list enc)
 JORDAN.E L Division of Emergency Preparedness & Engineering
 Response (Post \$30103) B3/05/26 Consolidated Edison Co of New
 York, Inc 115pp 18732 085 24% Fiche 50-000,83/05/26,8305110460

- 8305110461 IE Info Notice 83-35. "Fuel Movement W/Control Rods Withdrawn at DWRs " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/31 Consolidated Edison Co of New York, Inc 116pp 18732 208 24X Fiche 50-000.83/05/31,8305110461
- 8306230379 Forwards IE Insp Repts 50-443/83-06 & 50-444/83-06 on 830411-0523 No noncompliance noted 8TAROSTECKI.R Division of Project & Resident Programs 83/06/08 HARRIEDON,R J. Public Service Co of New Hampshire 2pp 18/43-07/024X Fichs 50-443/83/06/08/8306230399
- --8306230405 IE Insp Repts 50-443/83-06 & 50-444/83-06 on 830411-0523 No noncompliance noted Major areas inspected licensee action on previously identified insplices & work activities, procedures & records re piping & racumay installation CERNE.A C. GRAMM.R A Region I. Office of Director GALLO.R M Division of Project & Resident Programs 83/06/07 12pp 18943.078 24X Fiche 50-443-83/06/08.8306230399
- 8305110464 IE Info Notice 83-36. "Impact of Security Practices on Safe Operations" Svc list encl JORDAN.E L Division of Emergency Preparedness & Ingineering Response (Post 830103) 83/06/09 Lonsolidated Edison Co of New York, Inc 117pp 18830 280 24X Fishe 50-000,83/06/09,8305110464
- 8305110470 IE Info Notice 83-38, "Defective Heat Sink Adhesive & Seismically Induced Chatter in Relays Within Printed Circuit Cards " Syc list encl JORDAN, EL Division of Emergency Preparedness & Engineering Response (Post 830)03) 83/06/13 Consolidated Edison Co of New York, Inc. 118pp. 18920 225 24% Fiche 50-000, 83/06/13, 8305110470
- 8306090010 IE Info Natice 83-87, "Transfermer Failure Resulting From Degraded Internal Connection Cables " Svc list enc! JORDAN E L Division of Emergency Preparedness & Logineering Response (Post 830103) 83/04/13 Consolidated Edison Co of New York, Inc 243pp 18921 001 24X Fiche 50-000.83/04/13.8306090010
- 8305110475 IE Info Notice 83-40, "Need to Environmentally Qualify
 Epoxy Grouts & Sealers " Svc list encl
 JORDAN E L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 63/06/22 Consolidated Edison (n of New
 York, Inc. 115pp. 19021 177 24X Fiche 50-000.83/06/22.8305110475
- 8305110477 IE Info Notice 83-41, "Actuation of Fire Suppression Sys-Causing Inoperability of Safety-Related Equipment " Svc list enc! JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/22 Cynsolidated Edison Co of New York, Inc 120pp 18997 007 24X Fiche 50-000,83/06/22,8205110477
- 8305110479 IE Info Notice 83-42, "Reactor Mode Switch Malfunctions "
 Svc list encl
 JORDAN, EL Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/06/23 Consolidated Edison Co of New
 York, Inc. 116pp 18996 242 24X Fiche 50-000, 83/06/23, 83051104/9
- 8305110483 IE Info Notice 83-48, "Impraper Settings of Intermediate Range (IR) High Flux Trip Setpoints " Svc list enel JORAN, EL Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/24 Consolidated Edison Co. of New York, Inc. 116pp 19045 297, 24% Fichs 50-000, 83/06/24, 8305110483

8 Reportable accurrences, LERs & related correspondence

- 8306170169 Interim deficiency rept re suspected quality of NDFperformed at facilities Initially reported an 830504 flan
 established to reexamine 100% of all readily accessible
 affected work Noxt rept by 830831
 DEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J Public
 Service Co of New Hampshire 83706/03 STAROSTECKI, R Division of
 Project & Resident Programs 3pp 18878 329 24X
 Fiche 50-443,83706/03.8306170169
- 8304280545 Final deficiency rept re potential for certain Westinghouse gate valves to provide closed indication prior to valve disc fully isolating flow Field change notice issued modifying generic wiring specs

 DEVINCENTIS, J. Yankse Atomic Electric Co DEVINCENTIS, J. Public Stryice Co. of New Hampshire 837/06/10. 874R0STECKI, R. Division of Project & Resident Programs Epp. 19019 325 24X

 Fiche. 50-443, G3/06/10, 8306280945
- 8306210112 Interim Part 21 rept re adequacy of circulating water pump house structure Analysis & design of needed structural mods for ave water pump house being performed & will be completed by 830819

 SARSTEN.0 E United Engineers & Constructors, Inc. (subs. of Raytheon Co.) 83/06/17 Director's Office, Office of Inspection and Enforcement 3pp 18914 108 24X Fiche 80-443.83/06/17, 8306210112

V Operator Examinations

8306140518 Extends invitation to attend 830627 meeting in King of Prussia, PA to discuss transfer of reactor operator licensing function from Bethesda. MD to Request I of STAROSTECKI, R. Division of Project & Resident Programs D3/06/09 HARRISON, R. J. Public Service Co. of New Humpshire 2pp 18908 120 24X Fiche 50-443, 83/06/09, 8786140518

DOCKET 50 444 SEABROOK NUCLEAR STATION, UNII 2

- A Application/construction stage documents & correspondence
- B304020039 Notification of B30407 significant licenses meeting w/otif & Pullman-Higgins in King of Pressa.PA to discuss performance of site contractor
 ACU_BEN_C Region 1. Office of Director 83/05/25 Region 1.
 Office of Director 1p 18/02 323 24X Fiche 50-443,83/05/25.
- 830401044B Application to amond & renew CPPR-135 & CPPR-136, extending const completion dates to B41031 & B81031, respectively Factors delaying const listed JOHNSON, W.P. Yankee Atomic Electric Co. JOHNSON, W.P. Public Service Co. of New Hampshire. 83705726 UENTON, H.R. Office of Noviear Reactor Regulation. Director. 3pp. 18674-309. 24X Fiche 50-443,83705726,8304010448
- 8306240462 Summary of 830513 meeting w/util re hasts for projecting fuel load date of Sept 1984 for Unit 1 WHEELER, L Licensing Branch 3 83/06/10 Licensing Branch 7 4pp 18798-005 24% Fiche ho-443.83/06/10.8306240462
- 8306230452 Forwards revised response to NURFG-0612. "Control of Heavy Loads " Rev addresses NRC comments contained in draft technical evaluation rept dtd 821125 % supplemented by NRC 821228 ltr
 DEVINCENTIS.J Yankee Atomic Clectric Co DEVINCINTIS.J Public Service Co of New Hampshire 83706720 KNIGHION, G H Licensing Branch 3 2pp 18941 001 24X fiche 50-443,83706720,8306730452
- --8306230458 "Response to NRC Generic Request for Addl Info Re-NUREO-0412, Control of Heavy Loads" * United Engineers & Constructors, Inc. (subs. of Regtheon Co.) 9763-006-9-M-5 83/05/31 147pp 10941-004 PAX Fiche 50-443,83/06/20,8306230452
- E NRC Safety Evaluation Report (SER), suppls & correspondence
- 630 & 0.30177 Forwards response to request for add1 info re open item in SER. Section 7 3 2 8 concerning effects of high temps on reflegs of steam generator & pressuring water level measuring instruments after high energy line breaks

 DEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J Public Service Co of New Hampshire 83/05/31 KNTGHTON, 8 W Litering Branch 3 11pp 18703 313 24X Fiche 50-443,83/05/31.83060301//
- 8304080125 Forwards SER open item response to Chemical Enginerating Branch request for additinfore NUREO-0737, Item II B 3, "Post-Accident Sampling Capability "Info suppls 821201 response & OL application Amend 48
 DEVINCENTIS.J Vankee Atomic Electric Co DEVINCENTIS.J Public Bervice Co of New Mampshire 82/05/31 KNIGHTON, O W Licensing Branch 3 21pp 18772 333 24X Fichs 50-443,83/05/31,8304080125
- 8306200236 Forwards "Containment Ultimate Capacity of Genbrook Station Units I & 2 for Internal Pressure Loads: "in response to Request for Add Info RAI 220 37 & SER Section 3 8 I Rept will be referenced in OL application Amend 49 DEVINCENTIS, J. Yankee Atomic Electric Co. DEVINCENTIS, J. Yankee Atomic Electric Co. DEVINCENTIS, J. Public Service Co. of New Hampshire 8/3/06/07 XNIGHTON.6 W. Licensing Branch 3 2pp 18903 001 24% Ficha 50-443,83/06/07,8306200276
- --8306200242 "Containment Ultimate Capacity of Scabrook Station Units 1 & 2 for Internal Pressure Loads " W/eight oversize figures Aperture cards are available in PDR * United Engineers & Constituctors, Inc. (subs. of Raytheun Co.) 83/02/28 75pp 18903 003 24X Fiche 50-443,83/06/07,8306200236
- 8306200330 Forwards response to Meteorological & Effluent Treatment Sys-Branch draft SER open items.per 830518 meeting request Response will be incorporated in Amend 50 to OL application & FSAR DEVINCENTIS, J. Yankee Atomic Flectric Co. DEVINCENTIS, J. Public Service Co. of New Hampshire 83/06/15 KNIGHTON, G.W. Licensing Branch 3 3pp 18900-350 24X Fichs 50-443.83/06/15.8306200330

- 8306200397 Forwards supplemental response to SER Section 11 5 2 re need for gross radioartivity monitor in svc water sys Response will be incorpurated in Amend 50 to OL application & FBAR DEVINCENTIS, J Yankee Atomic Flectric Co DEVINCENTIB, J Public Service Co of New Hampshire 83/06/15 KNIGHTON, 6 W Licensing Branch 3 4pp 18897 037 24% Fichs 50-443,83/06/16,8306200397
- G Adjudicatory correspondence
- 8306150256 Forwards Suppl 1 to SER (NUREG-0896), addressing two outstanding issues re emergency preparedness & secondary water chemistry Corrected page to NRC BF0420 Joint affidavit & WT LeFave 830511 affidavit encl M/o SER LESSY, RP. PATTERSON, W.F. Hearing Branch 3 83/05/11 HDYT, H. LUEBKE, E.A. HARRDUR, J. Atomic Safetu and Licensing Board Panel 2pp 13849 171 24X Fiche 50-443,83/05/11,8306150256
- --8306150259 Affidavit of MT LeFave, detailing corrections to NRC joint affidavit of C Liang. WT LeFave & 88 Kirslis, Paragraphs 9 & 10 re environ qualification of nonsafety-related valves Valves not needed for safe shutdown under LOCA conditions LEFAVE, W T Auxiliary Systems Branch 83/05/11 2pp 18849 193 24X Fiche 50-443,63/05/11,8306150256
- --8306150262 Corrected Paragraphs 9 & 10 to joint affidavit of C Liang, NT Lefave & 98 Kirslis re environ qualification of nonsafety-related valves, filed on 850420 LIANG.C., LEFAVE, NT. KIRSLIB, S. S. NRC. No Detailed Affiliation Given 83/05/11 ip 18849 195 24x Fiche 50-443,83/05/11, 8306150236
- 6306150238 Response opposing New England Coalition on Nuclear Pollution 630512 motion to file out-of-time answer to NRC affidavit reservinon qualification of electric valve operators Unavailability of consultant does not justify late response PATIERSON.W F. LEBSY.R P. Hearing Branch 3 83/05/24 Atomic Safety and Licensing Board Panel 5pp 18847 268 24X Fiche 50-443.63/05/24.8306150238
- --8306180431 Affidavit of C Liang re environ qualification of electric valve operators CS-HCV-189, CS-HCV-170 & RC-VB1 Valves not required to be environmentally qualified since letdown sys not in use during post-accident operations
 LIANG-C Reactor Systems Branch 83/05/24 Spp 18847 27.3 24X Fiche 50-443,83/05/24,8306150238
- --B306150437 Affidavit of WF Lefave re electric valve operators BA-BV-4A/4B Operators not important to safety & do not need to be environmentally qualified No failure mode of valves exists due to harsh environ that could affect safe shutdown LEFAVE.W T Division of Systems Integration (post 811005) 83/05/24 3pp 18847 278 24X Fiche 50-443,83/05/24,8306150238
- 830A010342 Objection to ASLB 830511 memorandum & order re Contentions NH-9 & NN-13 & to rationale for granting of summary disposition on contentions Order should be reconsidered & contentions readmitted Certificate of Syc entl BISBEE.0 D New Hampshire, State of 83/05/26 Atomic Bafety and Licansing Board Panel 7pp 18680 084 24% Fiche 50-443,83/05/26.
- 8304010382 Patition for directed certification of ASLB tummary disposition dismissing Contention II B 4 on GA for replacement parts ASLB ruling flagrantly illegal & sets dangerous precedent CYBRAN.D , JORDAN.W 8 New England Conlition on Nuclear Pollution CYBRAN.D , Harmon & Weiss 83/05/26 Atomic Bafety and Licensing Appeal Panul 10pp 18682 140 24X Fichs 50-443,83/05/26.
- 8304010384 Motion for 3-day extension to 830523 for filing objection to ASLB 830511 memorandum & order Delay due to unexpected involvement in federal court litigation BISBEE C D New Hampshire, State of, 83/05/26 Atomic Safety and Licensing Board Panel 1p 19682 170 24X Fiche 50-443,83/05/26, 8306010384
- 8306010444 Appeal of dismissal of Class 9 accident Contention 3 or, in alternative, request for certification per 100FR2.718(i)
 Issue central to determining whether OL should provide for mitigating features Certificate of Svc encl
 BACKUS, R A Seacoast Anti-Pollution League 83/05/24 Atomic Safety and Licensing Appeal Panel 9pp 18674 354 24%
 Fiche 50~443,83/05/26.8306010444
- 8306010437 Forwards LL Bishop notice of withdrawal as counsel for New England Comittion on Nuclear Pollution CURRAN.D Hunton & Williams 83/05/27 HOYT, H. F. Atomic Bafety and Licensing Board Panel Ip 10677 302 24X Fiche 50~443,83/05/27,8306010437

- --8306010443 Notice of Withdrawal as counsel for New England Coalition on Nuclear Pollution Certificate of Svc encl BISHOP.L L Hunton & Williams 03/05/26 3pp 18679 303. 24X Fiche 50-444,83/05/27,8306010437
- B306010446 Forwards, under separate cover, exhibit to New England Coalition on Nuclear Pollution B30526 petition for directed certification
 CURRAN.D Harmon & Weiss B3/05/27 ROSENTHAL.A S Atomic Safety and Licensing Appeal Panel 1p 18674 326 24X
 Fiche 50-443.B3/05/27.B306010446
- 8306020169 Requests deferral of responses to applicants motion for summary disposition of New England Coslition on Nuclear Pollution Contention I D 2 re reactor trip sys until 20 days after svc of NUREO-1000, Vol 2
 PERLIB,R 0 Heaving Branch 3 B3/05/31, HCYT,H, LUEBKE,E A, HARBOUR,J Atomic Safety and Licensing Board Panel 2pp 18690 361 24X Fiche 50-443,83/05/31,8306020167
- 8306020361 Notice of ASLAB constitution AB Rosenthal, chairman, GJ Edles & HA Wilber, members SHOEMAKER, CJ Atomic Safety and Licensing Appeal Panel B3/05/31 ip 18674 330 24X Fiche 50-443,83/05/31.8306020361
- 8306030355 Forwards New England Coalition on Nuclear Pollution 630601 objection to applicant twenty-first motion for summary disposition of Contentions III 2 & III 13 Renotarised affidavit of PB Herr available upon request.

 CURRAN, D Hunton & Williams CURRAN, D New England Coalition on Nuclear Pollution 83066/01 HOYT, R F Atomic Rafety and Licensing Board Panel 1p 18705 215 24X Fiche 50-443.83/06/01.8306030355
- ~-B306030359 Objection to applicant twenty-first motion for summary disposition of Contentions III 2 & III 13 Affidavit of JA MacDonald insufficient as matter of law to support grant of summary disposition Statement of matl facts encl CURRAN.D New England Coalition on Nuclear Pollution CURRAN.D Hunton & Williams 83/06/01 Akomic Bafety and Licensing Board Panel 2pp 18705 216 24X Fiche 50-443,83/06/01.6306030355
- --8306D30363 Affidavit of PB Herr on Contentions III i2 & 13 re documentation in support of applicant 830214 twenty-first motion for summary disposition Centrificate of Byc encl HERR:PB New England Coalition on Nuclear Pollution HERR:PB Massachusetts Institute of Technology 83/05/27 289pp 18709 218 24X Fichs 50-443,03/06/01.8304030355
- B304070411 Advises that Commonwealth of MA Civil Defense Agency unable to meet 830401 target date for submission of state area plan to FEMA New target date is 830815 SHOTWELL, J.A. Massachusetts, Commonwealth of. 830601 MOYT.H., PARIB, O.H., LUEBKE, E.A. Atomic Safety and Licensing Board Panel 2pp 18742:271 24X Fiche 50-443,83/06/01,8306070411
- 8306080053 Response supporting util motion for summary disposition of New Empland Coalition on Nuclear Poliution Contentions III. 12 & III. 13 & apposing util motion for summary disposition of Stats of NH Contention 21 PERLIS.R 0 . LEBSY.R P Hearing Branch 3 83/06/06 Atomic Safety and Licensing Board Panel 8pp 18773 176 24X Ficher 50-443.83/06/06.8306080053
- --8306080087 Affidavit of JR Sears Util has not provided info necessary to comply w/onsite protective measure requirements Evacuation time estimates accurate & usoful Certificate of Svc encl.
 SEARB.J R EF Licensing Branch 83/06/03 7pp 18773 184 24X Fiche 50-443.83/06/06.8306080033
- 83060808B Response apposing Beacoast Anti-Pollution League 630516 motion to amend intervention petition by adding new contention re instrumentation for detection of inadequate care cooling Motion untimely Certificate of Syc ancl PATTERSON.W F. LEBSY.R P Hearing Branch 3 83/06/06 Atomic Sefety and Licensing Board Panel Spp 18773 255 24X Fiche 50-443.83/06/06.830408008B.
- 8304080166 Order advising that supplemental answers to util motion for summary disposition of New England Coalition on Nuclear Pollution Contention I D 2 due 20 days after svc of Vol 2 of NRC rept on implications of ATHB incident at Salam HOYT.H.F. Atomic Bafety and Licensing Board Panel 83/06/06 2pp 18772.155 24X Fishe 50-443.83/06/06.8304080166
- B306080174 Order denying New England Coalition on Nuclear Pollution B30512 motion to file out-of-time answer to NRC affidavit reserviron qualification of electric valve operators. Issue decided twice & will not be considered again.

 NOYTHIF Atomic Bafety and Licensing Board Panel B3/06/06 New England Coalition on Nuclear Pollution 2pp 18772 276, 24% Fiche, 50-443, 63/06/06, 8306080176

- 8306080186 Memorandum advising that State of NH 630526 objections to ASLB 830511 order not filed late Objections will be considered MOYTH F Atomic Safety and Discussing Board Page 1 83/06/06 2nd
 - HOVT, H F Atomic Safety and Licensing Board Panel B3/06/06 2pp 18772 258 24% Fiche 50-443,83/06/06,8306080186
- 8306190397 Response opposing New England Coalition on Nuclear Pullution petition to ASLAB for directed certification of ASLAB 830511 memorandum & order dismissing Contention II B 4 Petition should be dismissed Certificate of Svc encl DIGHAN.T G, GAD,R K Public Service Co of New Hampshire DIGHAN.T G Ropes & Gray 83/06/08 Atomic Safety and Licensing Appeal Panel 9pp 18847 239 24% Fiche 50-443,83/06/08,8306150387
- 8306190388 Response apposing Seacoast Anti-Pollution League appeal of dismissel of Class 9 accident contention or alternatively, request for certification Appeal should be dismissed & directed certification denied Certificate of Svc encl DIONAN.T 0 , GAD.R K Public Service Co of New Hampshire DIONAN.T 0 Ropes & Gray B3/06/08 Atomic Safety and Licensing Appeal Panel Bpp 18847 196 24X Fiche 50-443,83/06/08,8306150388
- 8306150357 Ack receipt of 830608 ltr & encls HA Wilber, not Gotchy, assigned to ASLAB
 TOMPKINS.B A Atomic Safety and Licensing Appeal Panel 83/06/13
 GAD.R K Ropes & Gray 1p 18847 267 24X Fiche 50-443,83/06/13,8306150357.
- 8306200173 Response opposing New England Combition on Nuclear Pollution & Seacoast Anti-Pollution images patitions for directed certification of ASLB 830911 order Petitions do not meet requirements for discretionary review #//Cortifiate of Svc LESSY.R P. PATTERSON.W F. PERLIS.R O Hearing Branch 3 83/06/15 Atomic Bafety and Licensing Appeal Panel 28pp 16903 145 P4X Fiche 50-443,83/06/15.8306200173
- 8306270296 Expresses concern re draft emergency response plan Draft does not accurately reflect or address emergency response plan for West Newbury Related correspondence CHUTE.# West Newbury, MA 83/06/15 LDMABNEY, M Costello, Lomasney & deNapoll, Inc 5pp 18990 212 24X Fiche: 50-443,83/06/15:8306270256
- 8306220077 Requests 0J Humphrey be added to svc list LEMIS:DR Atomic Safety and Licensing Doard Panel 83/06/16 Office of the Escettive Legal Director 1p 18730 163 24X Fiche 50-443.83/06/16.8306220077
- 8306220085 Deletes R Cashman & adds M Pearson to svc list as Town of Amesbury, NH representative LEMIS D R Atomic Safety and Licensing Board Panel 83/06/16 Office of the Executive Legal Director 1p 18927 181 24X Ficha 50-443,83/06/16,8306220085
- B306220100 Requests R0 Miller be deleted & DR Lewis added to svc list COPELAND, J E. Atomic Safety and Licensing Board Panel 83/06/16 Office of the Executive Legal Director ip 18927 170 24X Fichs 50-443,83/06/16,8306220100
- 8305220079 Memorandum & order denying Beacoast Anti-Pollution League 830516 motion to amend petition to intervene No good cause shown for late filing Admission of Contention Suppl 7 would not assist in developing sound record HOYT.H F Atomic Eafety and Licensing Board Panel B3/06/20 Seacoast Anti-Pollution League 4pp 18727 183 24X Fichs 50-443.83/06/20.8306220079
- B306220097 Memorandum & Order ALAB-731 dismissing Seatoest Anti-Pollution League (SAPL) appeal of & denying request for certification of portion of ABLB B30511 order granting summary disposition of BAPL Supplemental Contention 3 TOMPKINSD B. A. Atomic Safety and Licensing Appeal Panel Seatoest Anti-Pollution League 3pp 1B927 016 24X Fithe 50-443, 83/06/20, 8306220097
- B306220099 Memorandum & order scheduling B30713 oral argument in Bathesda. MD re New England Coalition on Nuclear Pollution patition for directed certification of ABLB B30511 order granting summary disposition on Contention II B 4 TOMPKINS, B A Atomic Safety and Licensing Appeal Panel. B3/06/20 7pp 18926, 174 24X Ficha 50-443, 83/06/20, 8306220099
- 8306270249 Memorandum providing schedule of locations & ASLB anticipated hearing & limited appearance session dates HOYT, H F. Atomic Bafety and Licensing Board Panel 83/06/22 2pg 18990, 217. 24X Fiche 50-443, 83/06/22, 8306270249

15.5

- 8306270306 Response apposing State of NH 830526 objections to AGLD 830511 memorandum & order juling on motions for summery disposition No mods to ASLB conclusions warranted Cortificate of Svc encl LESSY.R P. PATTERSON.W F. Hearing Branch 3 03/06/22 Atomic Safety and Licensing Board Panel 11pp 18995 200 24x Fiche 50-443.03/06/22.8306270306
- 8306280512 Informs that add1 work needed in listed areas of diaFt emergency plan Traffic & access control point section of plan must be completed so entire draft can be analyzed Related correspondence RIEL.9 L. Nowbury, MA 63/06/22 LOMASNLY, M. Contello, Lomasney & deNapoli, Inc. 2pp. 17018-191 24X Fiche 50-443, 63/06/32, 8306280515
- 8306290521 Contentions on State of NH radiological emergency response plan Certificate of Svc encl
 BACKUS, R A Seacoast Anti-Pollution League BACKUD, R A Bactus.
 Shee & Meyer B9/06/22 Atomic Safety and Licensing Board Panel
 Bpp 17052 195 24X Fiche 50-443,83/06/23.8306290521
- 8306280553 Contentions re emergency planning for State of NH Certificate of Svc encl BELLOTTI.F X Texas, State of 83/06/23 Atomic Safety and Licensing Board Panel 36pp 19018 066 24X Fiche 80 443.01/06/21 8306280553
- 8306280543 Response opposing State of NH 830511 filling Request for reconsideration of ASLB 830511 memorandum & order should be denied issue in Contention NH-9 not ripe for litigation Certificate of Svc enci DIONAN, T. O., GADLR K. Public Service Co. of New Hampshire DIONAN, T. G. Ropes & Oray B3/06/24 Atomic Safety and Licensing Board Panel 16pp 17017 3P/ 84X Fichr 50-443,83/06/14,
- 8306290532 Errata to Seacoast Anti-Pollution League contentions on State of NH radiological emergency response plan Certificate of Svc encl BACKUS.R A Seacoast Anti-Pollution League BACKUS.R A Hackus. Shea & Meyer 63/06/24 Atomic Safety and Liconsing Board Poll 5pp 19082 324 24X Fiche 50-443,83/06/24.8306270532
- B306290556 Contentions on State of NH radiological Emergency response plan, Vol 1 Certificate of Svc out 1 CURRAN, D . JURDAN, N S New England Condition on Nuclear Pollution CURRAN, D Harmon & Weiss B3/06/27 Atomic Bafety and Intensing Board Panel 24pp 19052 217 24y Fiche 50-443, B3/06/27.
- O Inspection reports, IE Bulletine & correspondence
- 8304080259 Add1 response to FDIA request for nine separate categories of documents refacilities Forwards documents listed in App A App B documents completely & partially withheld (ref (DIA Exemptions & & 7)
 FELTON J M Division of Rules and Records B3/04/04 KINDIR.1 I New Hampshire. State of 4pp 18790 315 24X Fiche 50 44.1. B3/04/04, B304080259
- ***-B3040B0253 Forwards results of licenser investigation of l'ullant Higgins QC inspector allegations re perceived haracoment of QC inspectors from within organization & documentation of organization changes CERNE.A C. Region 1. Office of Director B2/07/14 Region 1. Office of Director 7pp 18790 319 24X Fiche 50-443. U.4/04/Uh. B3040B0259.
- --B3060B0264 Discusses GC inspector concerns within Pullman Higgins organization (facility piping contractor) re-perceived harassment of GC inspectors by P H const personnel Glosure of case recommended CERNEJA C Region 1. Office of Director 82/10/13 Hugiun E. Office of Director 2pp 18/90-526 24X Fiche: 50-443. 03/04/105. B3060B0259
- --B306080266 Discusses Pullman-Higgins (P-H) OC inspector conterns to allegations of harassment of QC inspectors by P-H const personnel Personally identifiable info deleted CERNE, A C Region 1, Office of Director B2/04/09 Region 1, Office of Director B2/04/09 Region 1, Office of Director 2pp 18790 328 24X Fiche 50-443, 03/04/04.
- --8306080269 Discusses nonspecific allegations re Pullman-Higgins GA/GC inspectors at facilities Personally identifiable info deleted MATAKAS,R A Region 1. Office of Director 82/09/27 CALLO,R N Division of Project & Resident Programs 2pp 18770 336 PAX Fiche. 50-443,83/04/06,8306080259.

- 8304010442 Ack receipt of 830502 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-443/83-02 & 50-444/83-02 STAROSTECKI.R Division of Project & Resident Programs B3/05/25 HARRISON.R J Public Service Co of Nrw Hampshire ip 18474 302 24X Fiche 50-443.83/05/25.8306010442 18674 302
- --830&010447 Responds to NRC 830404 ltr re violations noted in IE lnsp Repts 50-443/83-02 & 50-444/83-02 Corrective actions craft Repts 30-443/83-02 & 50-444/83-02 Corrective actions cratt personnel will monitor safety-related supports & site contractor GA audited DEVINGENTIS, J Yankee Atomic Elertiic Co DEVINGENTIS, J Service Co of New Hampshire 83/05/02 STAROSIECKI, R b of Project & Resident Programs App 18674 303 24X Fishe 50-443.83/05/25,8306010442 Public Division
- B30511045B IE Info Notice B3-32, "Ruptured Am-241 Sources Contained in Well Logging Dovice" Syc list encl TAYLOR.J M Division of Safeguards & Inspection Programs (Post B30103) B3/05/26 Consolidated Edison Co of New York. Inc 125pp 18831 043 24X Fiche 50-000.83/05/26.830511045B
- 0305110460 IE Info Notice 83-34. "Event Notification Info Worksheet " HOSTIDADO II. AND MANAGEMENT OF Emergency Preparedness & Engineering JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co. of New York, Inc. 115pp 18732 085 24X Fiche 50-000, 83/05/26, 8305110460
- B305110461 lE Info Notice 83-35, "Fue) Movement W/Control Rods Withdrawn at UWRs " Svc list encl JSRDAN,E L Division of Emergency Preparedness & Engineering Response (Post B30103) B3/05/31 Consolidated Edison Co of New York Inc 116pp 18732 208 24X Fiche 50-000.83/05/31.8305110461
- 9305230399 Forwards IE Insp Repts 50-443/83-06 & 50-444/83-06 on B30411-0523 No noncompliance noted STARDSTECKI,R Division of Project & Resident Programs B3/06/0B HARRISON.R J Public Service Co of New Hampshire 2pp 18743.07 24X Fiche 50-443.83/06/08.8306230397
- --8306230A05 IE Insa Reats 50-443/83-06 % 50-444/83-06 on 830411-0523 No SUCKINGUOUS IE Insp Nepts 50-443/83-06 & 50-444/83-06 on 830411 noncompliance noted Major areas inspected licensee action on previously identified insp jtems & work activities, procedures & records re piping & raceway installation CERNE, A C, GRAMM, A Region I. Office of Director. GALLO Division of Project & Resident Programs 83/06/07 12pp GALLO, R M 24X Fiche 50-443, 83/06/08, 8306230399
- 8305110464 IE Info Notice 83-36, "Impact of Security Practices on Safe Operations " Svc list encl JORDAM, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/09 Consolidated Edison Co. of New York, Inc. 119p 18830 280 24X Fiche 50-000,83/06/09,8305110464
- 8305110470 IE Info Notice 83-38, "Defective Heat Sink Adhesive & JUSTICATO IE Info Notice B3-3B, "Defective Heat Sink Admestive & Seismically Induced Chatter in Relays Within Printed Circuit Cards " Syc list encl JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Post B30103) B3/06/13 Consolidated Edison to of New York, Inc. 1189p 18920 225 24X Fiche 50-000.83/06/13.8305110470
- 8306090010 IE Info Notice 83-37. "Transformor Failure Resulting From Degraded Internal Connection Cables " Svc list enc.]
 JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co of New York, Inc. 243pp 18921 001 24X Ficha 80-000,83/06/13,8306090010
- B305110475 IE Info Notice B3-40, "Need to Environmentally Qualify
 Epoxy Grouts & Sealers " Svc list encl
 JORDAN E L Division of Emergency Preparedness & Engineering
 Response (Post B30102) 83/06/22 Consolidated Edison Co of Net
 York, Inc 115pp 19021 177 24X Fiche 50-000,83/06/22,630511047
- 0305119477 IE Info Notice 63-41, "Actuation of Fire Suppression Bys Causing Inoperability of Safety-Related Equipment" Svc list enci JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/22 Consolidated Edison Co of New York, Inc 120pp 18997.007 24% Ficher 30-000, 83/06/22, 8305110477
- 8305110479 IE Info Notice 83-42, "Reactor Mode Switch Malfunctions " 305110479 LE Into Notice do 12. Svc list encl JDRDAN: EL Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/23 Consolidated Edison Co of New York, Inc 116pp 18996 242 24X Fiche 50-000,83/06/23,8305110479
- 8305110483 IE Info Notice 83-43, "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints " Svc list encl.
 JORDAN, EL Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/06/24 Consolidated Edison Co of New
 York, Inc 114pp 19046 297 24X Fiche 50-000,63/06/24.6305110483.

- S Reportable occurrences. LERs & related correspondence
- 8306170169 Interim deficiency rept re suspected quality of NDE performed at facilities Initially reported on 830504 Plan established to reexamine 100% of all readily accessible affected work Noxt rept by 830831 DEVINCENTIS, J. Vanker Atomic Electric Co. DEVINCENTIS, J. Service Co. of New Hampshire 83/04/03 83AR0STECK1.R DirProject & Resident Programs 3pp 18878 329 24X Fiche 50-443,83/06/03.8306170169 Public Division of
- B3062B0545 Final deficiency rept re potential for certain Westinghouse gate valves to provide closed indication prior to valve disc fully isolating flow Field change notice issued modifying generic waring specs
 DEVINCENTIB, J Yankse Atomic Electric Co DEVINCENTIB, J Public
 Service Co of New Hampshire 83/06/10 STAROSTECKIR. Division of
 Project & Resident Programs 2pp 19019 325 24X
 Fiche 50-443,83/06/10,8306280545
- 8304210112 Interim Part 21 rept re adequacy of circulating water pump house structure. Analysis & design of needed structurel mods for svc water pump house being performed & will be completed by 830819. completed by B30B19
 SARSTEN.0 E United Engineers & Constructors, Inc. (subs of Rautheon Co.) B3/06/17 Director's Defice, Office of Inspection and Enforcement 3pp 18914 108 24X Fiche. 50-443, B3/06/17,

V Operator Examinations

- 8306140518 Extends invitation to attend 830627 meeting in King of Prussia:PA to discuss transfer of reactor operator licensing function from Bethesda.MD to Region I of: STAROSTECKI, R Division of Project & Resident Programs 83/06/09 HARRISON,R J Public Service Co of New Hampshire 2pp 18838 II 24X Fiche 50-443,83/06/09.8306140518
- DOCKET 50-445 COMANCHE PEAK STEAM ELECTRIC STA , UNIT 1 A Application/construction stage documents & correspondence
- 830A090162 Forwards table providing description of 830810 Amend 40 to FSAR re administrative controls, environ qualification tables & ESF components MARSHALL, J.S. Texas Utilities Services, Inc. 83/05/11 BURHELL, S.B. Division of Liconsing 7pp 18792 308 24X Fiche 50-449,83/05/11,8304090142
- 8306010392 Forwards, for review, revised page from Chapter 17 1 of FBAR. Change (Amend 40) adds more specific commitment re 0A program, per encl NRC 830307 request OARY, R J Texas Utilities Conprating Co 83/05/23 COLLING, J T Region 4, Office of Director. App 18682, 227, 24X Fiche 50-445, 83/05/23, 8306010392
- 8306210403 Advises that Benjamin May House not sligible for inclusion in Natl Register of Historic Places Determination of sligibility notification and YOUNORLOOD, B. J. Licensing Branch 1 83/06/03 GARY, R. J. Texas Utilities Generating Co. Spp. 18936 293 24% Fiche 50-445, 83/06/03,8306210403
- 8306100153 Forwards add1 info re environ qualification of safety-related mechanical equipment, in response to Equipment Qualification Branch 830426 request W/six oversize drawings. Aperture cards are available in PDR MARSHALL, J B Texas Utilities Services, Inc 83/06/07 YOUNGELOOD, B J Licensing Branch I 12pp 18801:164 24X Fiche 50-445,83/06/07,8306100153
- 8306130193 Forwards audit rept re environ qualification verification of installed aquipment per request. No model indentification indicated on recombiner, however, ratings info on nameplate sufficient to establish model identify MARSHALL, J S. Texas Utilities Services, Inc. 83/06/07. YOUNGBLOOD, B J Licensing Branch I. 5pp 18826-298 24X Fiche 50-445,83/06/07.8306130193
- 8306130176 Forwards final response to NUREQ-0612, "Control of Heavy Loads at Nuclear Power Plants." 8CHMIDT.H C Texas Utilities Services, Inc 83/06/08 YOUNGBLOOD, B. J Licensing Branch 1 183pp 18828; 031 24X Fiche 50-445,83/06/08.8306130176
- 830&130279 Bubmits results of testing program re tube vibration in Hestinghouse Model D-4 & D-5 steam generators. Mode to steam generators & foredwater sys required to germit unrestricted operation Mode to begin 830615 SCHMIDTH C Texas Utilities Bervices: Inc. 83/06/09. YOUNGBLOOD, B. J Office of Nuclear Reactor Regulation, Director, 37pp. 18824 142 24X Fiche 50-445,83/06/09.8306130279

- 8306130293 Forwards proprietary "Counterflow Preheat Steam Generator Tube Vibration Summary Repts" & "Counterflow Preheat Steam Tube Expansion Rept " Repts withheld (ref 10CFR2 774) SCHMIDT.H C Teras Utilities Services, Int 83706/09 EISENHUT,D G Division of Licensing 2pp 18823 275 24X Fiche 50-445, 89706/079 8006130293
- 8306220170 Notification of 830615 meeting w/util in Bethesda, MD to discuss applicant plans for tube expansion in Model D-4 steam generator Meeting will be closed one to proprietary nature of info to be discussed BURNELLS B Licensing Branch 1 83/06/13 YOUNGBLOOD, B J Licensing Branch 1 3pp 18937 289 24% Ficha 50-445,83/06/13,8306220170
- 8306200019 Summary of 830331 meeting w/utils & Westinghouse in Bethesda.HD re Westinghouse analysis & evaluation of D4/05/E steam generator mod HOPKING.J D Licensing Branch 4 83/06/14 Licensing Branch 4 22pp 18908 327 24X Fiche 50-000.83/06/14.8306200019
- 8306220177 Summary of 830615 meeting w/util & Westinghouse in Bethesda. MD re applicant plans for tube expansion in Model D-4 steam generators HDPKING.J B Licensing Branch 4 83/06/16 Licensing Branch 4 4pp 18937 275 24X Fiche 30-445,83/06/16,8306220177
- 8306280392 Advises that info submitted by util on 830610 re response to open items from Equipment Qualification Branch SQR(is nonproprietary RAMELE P Westinghouse Electric Corp 83/06/21 YOUNGELOOD, D Jifensing Branch 1 lp 19019 008 24X Fiche 50-445,83/06/21,83/06/20
- --8306280400 Forwards addl info re unresolved concerns from seismic & dynamic qualification review of safety-related electrical & mechanical equipment SCHMIDT.H C Texas Utilities Services, Inc 83/06/10 YOUNGBLOOD, B J Licensing Branch 1 164pp 19019 009 24X Fichs 50-445.83/06/21.8306280392
- 8306300120 Advises that info provided in Texas Utils 830610 ltr re open items from NRC Equipment Qualification Branch SQRT audit of site not Hestinghouse proprietary as originally marked RAME, E P Westinghouse Electric Corp 83/06/21 YOUNGBLQUD, B J Licensing Branch I ip 19121 077 1/4X Fiche 50-445.83/06/21, 0306300120
- F Security, medical, emergency & fire protection plans
- 8304010279 Forwards Rev 4 to physical security plan Rev withheld (ref 10CFR73 21) CLEMENTO B R Teres Utilities Generating Co 83/05/26 DLNTUN.H R Office of Nuclear Reactor Regulation, Director 1p 18672 236 24% Fiche 50-445,83/05/26,8306010279
- 830615010: Releases public version of revised emergency plan implementing procedures FELTON.J M Division of Rules and Records 83/06/06 Document Management Branch 1p 18872 121 24X Fichs 50-445.83/06/06, 8306150101
- --8305150102 Forwards public version of revised emergency plan implementing procedures, including Procedures EPP-101 repreparation of emergency plan procedures, EPP-208 recontrol of site access & EPP-210 re evacuation W/o encl BCHMIDT.H C Texas Utilities Services. Inc 83/05/10 COLLINS.J T Region 4. Office of Director ip 18872 122 24) Fichs 50-445,83/06/96,8306150101
- Q Adjudicatory correspondence
- 830.6030330 Forwards proposed order reflecting ABLB 830516 ruling reconsideration of thermal stresses under ABME Code Order incorporates subsequent ruling reinclusion of support frames in ABME Code defanition of supports
 REYNOLDS,N S Debavoise & Liberman REYNOLDS,N S Texas Utilities
 Oenerating Co 83706/01 BLOCH.PB. JORDAN,W H , MCCOLLON.K A Atomic Bafety and Licensing Board Panel 7pp 18708 349 24X
 Fiche: 50-445,83/06/01,8306030330
- 8304070304 Fifteenth set of interrogatories & requests to produce ELLIS.J Citizens Association for Sound Energy 83/06/04 Texas Utilities Cenerating Co 3pp 18740 351 24% Fiche. 50-445, 83/06/04,8306070304
- --B306070306 Fifth set of interrogetories & requests to produce Certificate of Svc encl ELLIB.J Citizens Association for Sound Energy B3/06/04 Office of the Executive Legal Director Spp 18740 354. P4X Fiche 50-445,83/06/04,8306070304

- 8306070382 Forwards motion to reopen record re steam generator upper lateral restraint & J Doyle unexecuted affidavit ELLIS.J Citizens Association for Bound Energy 83/06/04 BLOCH.P B. JIRDAN.W H. NICOLLON.K A. Atomic Safety and Licensing Board Panel Ip 18741-312 24X Fiche 50-445/83/06/04/8306070702
- --8306070374 Motion to reopen record re steam generator upper lateral restraint Util should be ordered to supply Citizens Assoc for Sound Energy w/info necessary to determine if problem exists Certificate of Svc encl
 ELLIS.J. Citizens Association for Sound Energy 83/06/04
 Atomic Safety and Licensing Board Panel 8pp 18741 313 24x
 Fithe 50-445,83/06/04,83060/0382
- 8306070350 Order extending time until 830706 for Commission to act to review ALAB-714
 CNILK 5 J Office of the Secretary of the Commission 83/06/06
 Commissioners 1p 18742 066 24X Fiche 50-445,83/06/05,8306070350
- B3060B021B Forwards testimony of 1E Const Appraisol Team Insp Ropts 50-445/83-18 & 50-446/83-12 TREBY, S A Hearing Branch ! B3/06/06 BLOCH P B , JORDAN H H . MCCOLLON, K A Atomic Safety and Licensing Board Panel 2pp 18771 004 24X Fiche 50-445,83/06/06,8306080218
- --8306080222 Answer to ASLB inquiry re iterative sys for pipe design ASLB need not inquire into subj since iterative sys not issue in controversy Evidence in record sufficient to conclude process & piping adequate MIZUNO. G S. Hearing Branch 1 83/06/06 7gp 18771 006 24% Fiche 30~445,83/06/06,83060H0210
- --8306080224 Testimony of AB Beach, DC Ford, RM Compton & WA Hapsen to IL Const Appraisal leam Insp Repts 50-445/83-18 & 50-446/83-12 Changes & corrections to repts listed Prof qualifications entl
 BEACH, AB, FDRD, DC, COMPTON, RM Director's Office, Office of Inspection and Enforcement 83/06/06 10pp 18771 013 24X Fiche 50-445,83/06/06,8306080218
- --8306080227 Supplemental affidavit of TG Dunning re NRC consideration of voltage spike or pressure surge in piping sys Adequate analysis of control sys failure safety significance conducted w/o considering voltage spikes or pressure surges.

 DUNNING:T G Instrumentation & Control Systems Branch 83/06/06 6pp 18771 023 24% Fiche 50-445,83/06/06,8306080218
- 8306080239 Forwards testimony & miscellaneous documents on NRC constappraisal team rept
 REYNOLDS, N J Debevoise & Liberman REYNOLDS, N J Texas (Rilities
 Generating Co 83/06/06 BLCCH.P B MCCCLLOM.K A JORDAN, W H
 Atomic Sefety and Licensing Board Panel 2pp 18771 115 24X
 Fiche 50-445,83/06/06.8306080239
- --8306080241 Testimony of CT Brandt.RO Tolson & A Vega re NRC const appraisal team rept BRANDT.C T , TOLSON.R O , VEGA.A Texas Utilities Generating Co 83/06/06 25pp 18771 117 24X Fiche 50-445.83/06/06.8306080237
- --8306080243 Response to ASLB inquiry re iterative piping design process
 ABLB should not inquire sun sponte into process since record
 evidence sufficient No basis exists for further inquiry into
 as-built verification program
 REVNOLDE, N S . HORIN, H A Texas Utilities Generating Co
 REYNOLDE, N S . Debevoise & Liberman 83/06/06 9pp 18771 135
 24X Fiche 50-445,83/06/06,8306080237
- --830&080248 Affidavit of JC Finneran re ABLB inquiries on status of pips support design verification & unstable support design Approx 8&% of pipe supports vendor certified Approx 50% of review process for remaining supports complete FINNERAN, J C Texas Utilities Generating Co 83/04/03 5pp 18771 151 24% Fiche 50-445,83/06/06,8306080239
- B3061002R3 Motion for stay of ABLB order re LDCA Record on ishue should remain open until ABME Code interpretation received & analyzed ELL18.J Citizens Association for Sound Energy B3/06/06 Atomic Bafety and Licensing Board Panel App 18807 143 24X Fiche 50~445,83/06/06.83061002R3
- --8306100230 Affidavit of DH Boltz re interpretation of ABME Code Bubsoction NF-1121(a) Linguistic analysis presented BOLTZ.D M. Citizens Association for Sound Energy 83/06/05 17pp 18807 167 24X Fichs 50-445.83/06/06.8306100223
- --8306100227 Forwards DH Goltz original signed affidavit W/o encl Centificate of Svc encl ELLIS.J Citizens Association for Sound Energy 83/06/06 Docketing & Services Branch Spp 18807 186 P4X Fiche 50-445,83/06/06,8306100223

- 8306080230 Forwards Region IV 83053) it & notice of violation re IE Const Appraisal Team Insp Repts 50-445/83-18 & 50-446/83-12 Ltr omitted from 830606 submittal to ASLB TREBY, S.A. Hearing Branch i 83/06/07 BLOCK, P.B., JORDAN, W.W., MCCOLLOM, K.A. Atomic Safety and Licensing Board Panel 6pp 18771 089 24% Fiche 50-445,83/06/07.8306080230
- 830610011B Confirms 830526 teleon discussing tonversation between K Ennis & M Walsh re thermal expansion in piping or pipe supports under accident conditions TREBY.S A., MIZUND, G.S. Hearing Branch i B3/06/00 ENNIS.K. American Society of Mechanical Engineers 2pp 18802 027 24X Fiche 50-445.83/06/08.8306100118
- 8306150310 Notice of DR Boltz appearance in proceeding Certificate of Sec encl ELLIS.J Citizens Association for Sound Energy 83/06/08 App 18849 129 24X Fiche 50-445.83/06/08.8306190310
- 8306150380 Forwards miscellaneous ltrs.exhibits & stipulations re IE
 Insp Repts 50-445/82-26 & 90-446/82-14 W/n encls
 ELLIS.J Catizens Association for Sound Energy 83/06/08 HDRIN.W
 Debevoise & Liberman 1p 18847 257 24X Fiche 50-445.83/06/08,
 8306150380
- 8306150307 Nation for admission of new contention re adequacy of emergency planning Somervell County & Hood County commitment expertise & resources inadequate to adopt & implement emergency plans Certificate of Bvc encl HATHCHS.J Texas, State of B3/06/07, Commissioners 9pp (8849 137 24X Fiche 50-445, 83/06/09, 8306150307
- 8306150406 Forwards cross-examination documents to assist util & NRC in preparing witnesses for questioning ELL(8), J. Citizens Association for Sound Energy 83/06/09 ROTHSCHILD, M. U. Hearing Branch 1. REYNOLDS, N.S. Debevoise & Liberman REVNOLDS:N.S. Texas Utilities Generating Co. 2pp 16847-126 24% Fiche 50-445,83/06/09.8306150406
- 8306150414 Forwards executed J Doyle 830608 affidavit Unexecuted version encl w/Citizens Assoc for Sound Liergy 830604 motion to reopen record re steam generator upper lateral restraint issue ELLIS. J Citizens Association for Sound Energy 63/06/09 Docteting & Services Branch | p 18947 091 24X Fisher 50-445,83/06/09,8306150414
- --8306150415 Affidavit of J Doyle re need to reopen record on steam generator upper lateral restraint issue DOYLE.J Citizens Association for Sound Energy 83/06/08 3pp 18847 092 24% Fiche 50-445,83/06/09.8306150414
- 830.6150425 Forwards updated Somervell County emergency plan w/
 Attachment S & Attachment S to Hood County emergency plan
 W/o encl
 REVNOLDS.N 8 Debevoise & Liberman REVNULDS.N S Texas Utilities
 Generating Co 03/06/09 BLNCH.P B , JORDAN.W H , NCCOLLUH.K A
 Atomic Safety and Licensing Board Panel ip 18847 090 24X
 Fiche 50-445, 83/06/09. 8306150425
- 8306150366 Response opposing Citizens Assoc for Sound Energy (CASE)
 830604 motion to reopen record re upper lateral steam
 generator support CASE should be admonished for raising new
 issues gremised on speculation Certificate of Svc encl
 REYMOLDS,N S HORIN,W A Texas Utilities Generating Co HORIN,W A
 Debavoice & Liberman B3/06/10 Atomic Safety and Licensing
 Board Panel 7pp 18847 306 24X Fiche 50-445,83/06/10.8306150366
- 8306150390 Forwards documents to assist NRC in cross-examining util panel consisting of CT Brandt.RO Tolson & A Vega
 TREBY, S A Hearing Branch 1 92/06/10 ELLIS.J Citizens
 Association for Sound Energy REYNOLDS, N S Debevoise & Liberman
 ip 18847 029 24X Fiche 50-445,83/06/10,8306150390
- 8306150396 Forwards WP Heass supplemental affidavit re ASLB question on NRC position re application of GA/GC to sys important to safety & response to Citizens Assoc for Sound Energy motion to reopen record on upper lateral restaint issue ROTHECHILD. M U. Hearing Branch I 83/06/10 BLDCH/P B JGRDAN, W H MCCOLLOM, K A Atomic Safety and Licensing Board Panel, in 18847 075 24X Fiche 50-445,83/06/10,8304150396
- ~~8306150400 Affidavit of MP Hanss responding to ABLB 830510 question re NRC position on application of GA/GC to sys important to safety NRC position on Comanche Peak consistent w/NRC position on Shoreham HAMSS, W P GA Branch 83/06/10 3pp 18847 0/6 24X Fiche 80-445,63/06/10,8306150396

- --8306150403 Response opposing Citytens Assoc for Sound Energy 830604 motion to reopen record re-steam generator upper lateral support issue Assertsons re-placement of snubbers incorrect Certificate of Svc encl MIZUNG.0 8 Hearing Branch 1 83/06/10 Atomic Safety and Licensing Board Panel App 18847-079 24X Fiche 50-445, 83/06/10,8306150376
- 8306170406 Answer opposing State of TX 830609 motion for admission of new contention re adequacy of emergency planning Proposed contention lacks requisite specificity & bases for late-filed contentions Certificate of Svc encl REYNOLDS:N S Texas Utilities Generating Co REYNOLDS:N S Texas Utilities Generating Co REYNOLDS:N S Debevoise & Liferman 83706/12 Atomic Safety and Licensing Board Panel 26pp 18880 018 24X Fishe 50-445,83/06/12,8306170406
- 8306150313 Forwards Secretary of Labor 830610 decision & finel order in CA Atchison vs Brown & Root, Inc Certificate of Svc encl ROTHSCHILD, M U Hearing Branch 1 83/06/13 BLOCH, P B , JORDAN, W M , MCCOLLON, A Atomic Sefety and Licensing Board Panel 27pp 18849 099 24X Fiche 50-445,83/06/13 B306150313
- 8306150376 Summary of 830609 telcon w/ASLB & parties re util draft order on thermal stress issue REYNOLDS.N S Texas Utilities Generating Co REYNOLDS.N S Debevoiss & Liberman 83706/13 6pp 18847 282 24X Fighs 50-445,83706/13.8306150376
- 83062303B1 Forwards Secretary of Labor decision & final order re CA Atchison vs Brown & Root. Inc Decision relevant to pending NRC 830311 pattition for Commission review of ALAB-714 W/o encl ROTHSCHILD, M U Mearing Bronch 1 83/06/20 CHILK, 8 J Office of the Secretary of the Commission 1p 18943 243 24X Fiche, 50-445, 83/06/20, 8306230381
- B306280556 Memorandum & order denying State of TX 930609 motion for admission of new contention re adequacy of emergency planning Late filing criteria not met BLOCH.P B. JERDAN.H H. MCCOLLON.K A. Atomic Safety and Licensing Board Panel B3/06/27 Teras. State of 7pp 19018-016-24X Fiche 50-445.83/06/27.8306280556
- B306300056 Forwards util B11218 ltm to NRC.responding to ACRB B11117 comments re reactor protection sys.util mgt & organizational capabilities & station operations review committee TREBY.S A Hearing Branch I 83/06/28 JORDAN.W H Atomic Safety and Licensing Board Panel ip 19121 012 24X Fichs 30-445.83/06/28.8306300056
- M Antitrust correspondence
- B306230127 Advises that documents produced by Gulf States Utils Co.in response to NRC subpoena.destroyed VOQLER.B H Hearing Branch 2 83/06/21 CLEMENTS.D M. Gulf States Utilities Co. ip 19947 O4B 24X Fiche 50-000.83/06/21.8306230127
- O Inspection reports. IE Bulletins & correspondence
- 8306080220 Forwards IE Insp Repts 50-445/83-06 & 50-446/89-03 on 830131-0204 No noncompliance noted MADSEN 9 L Region 4. Office of Director. 83/04/14 GARY, R J. Teras Utilities Generating Co Ppp 18771 189 24% Fiche 50-445,83/04/14.8306080220
- --8306080221 IE Insp Repts 50-445/83-06 & 50-446/83-03 on 830131-0204 No noncompliance noted Major areas inspected preoperational environ protection programs organization & administration, audito, training, procedures & site tour HOLLEY, W L , MURRAY, B , WESTERMAN, T F, Region 4, Office of Director 83/04/12 2ippp 1877; 171 24X Fithe, 50-445, 83/04/14, 8306080220
- B306130255 Forwards IE Insp Rept 50-445/83-22 on 830401-30 No noncompliance noted MADSEN.9 L Region 4. Diffice of Director B3/05/25 GARY, R J Texas Utilities Comerating Co 2pp 18824 234 24X Fiche. 50-445, 83/05/25, 8306130255
- --8306130261 IE Insp Rept 50-445/83-22 on 830401-30 No noncompliance noted Major areas inspected.preoperational test results evaluation, fuel receipt preparation, hot functional test, plant tours & plant status

 KELLEY,D L , MCCRORY,S L , WESTERMAN,T F Region 4, Office of Director. 83/05/24 Bpp 18824 236 24% Fiche.50-445,83/05/25,8306130255
- B305110458 IE Info Notice 83-32. "Ruptured Am-241 Sources Contained in Well Logging Device " Svc list encl
 TAYLOR, J M Division of Safeguards & Inspection Programs (Post B30103) 83/05/26 Consolidated Edison Co. of New York, Inc
 125pp 1883) 043 24X Fiche 50-000, 83/05/26, 8305110458

- 8305110460 IE Info Notice 83-34, "Event Notification Info Worksheet " ROSIDAGO IE amo novilo --Byc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc. 115pp. 18732-085 24X Fishe 50-000,83/05/26,8305110460
- 8306140370 Forwards IE Insp Repts 50-445/83-19 & 50-446/83-13 on 830420-22,25,27 & 0503-05 No noncompliance noted MADSEN.6 L Region 4. Office of Director 83/05/27 GARY.R J Teras Utilities Gonerating Co. 2pp 18832 123 24X Fiche 50-445,83/05/27,8304140370
- --8306140374 IE Insp Repts 50-445/83-17 & 50-446/83-13 on 830420-22.25,27 & 0503-05 No noncompliance noted Major areas inspected followup of allegations on protective coatings & review of records for safety-related pige supports of DIBERT.L D. JOHNSON, C.E. BESS, J.E. Region 4, Office of Director 83/05/24 9pp 18832-125 24X Fiche 50-445,83/05/27, page 148032-125 24X Fiche 50-445/125 24X Fiche 50-445/125 24X Fiche 50-445/125 24X Fiche 50-445/125 24X Fic P206140370
- 8305110461 IE Info Notice 89-95. "Fwel Movement W/Control Rods Withdrawn at BWRs " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/31 Consolidated Edison Co of New York, Inc 116pp 18732 208 24X Fiche 50-000,83/05/31.8305110461
- 8306210105 Discusses Const Appraisal Insp Repts 50-445/83-18 & 50-446/83-12 on 830124-0204 & forwards notice of violation

 HADSEN, C L Region 4. Office of Director 83/0

 Texas Utilities Generating Co 2pp 18914 206

 Fiche 50-445,83/05/31.8306210105 83/05/31
- --8306210110 Notice of violation from insp on 830214-0303 Noncompliance noted failure to provide adequate procedures, instructions or drawing for installation of major items of aquipment * Region 4. Office of Director 83/05/31 3pp 18914 208 24X Fiche 50-445,83/05/31.8306210105
- 8306080230 Forwards Region IV 830531 ltr & notice of violation re IE Const Appraisal Yeam Insp Repts 50-445/83-18 & 50-446/83-12 Ltr unitted from 830606 submittal to AFLB TREBY.9 A Hearing Branch 1 83/06/07, DLOCH,P R , JDRDAN,W H , HCCOLLON.K A Atomic Safety and Licensing Board Panel 6pp 18771 088 24X Fichs 30-445,83/06/07,8306080230
- 8305110464 IE Info Notice 83-36. "Impact of Security Practices on Safe Operations " Syc list encl JURDAN E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/09 Consolidated Edison Co of New York, Inc 119pp 18830 280 24% Fiche 50-000, 83/06/09, 8305110464
- 8305110470 IE Info Notice 83-38, "Defective Heat Sink Adhesive & Selimically Induced Chatter in Relays Within Printed
 Circuit Cards." Svc list encl
 JORDAN, E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/06/13 Consolidated Edison Co of New
 York, Inc 118pp 18920 225 24X Fiche 50-000,83/06/13,8305110470
- 8304090010 IE Info Notice B9-37. "Transformer Failure Resulting From Degraded Internal Connection Cables " Svc list encl JURDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83706/13 Consolidated Edison Co of New York, Inc. 243pp 18921 003 24X Fiche.50-000.03/06/13.8304090010
- 8306160503 Forwards Westinghouse Procedure 151-154, "Preservice & Inservice Insp of Reactor Vessels" & plant-specific reactor Inservice insp or reactor vesses a plant system vessel insp program
 MARSHALL, J. B. Texas Utilities Services, Inc. 85/06/13
 BURNELL, B. B. Division of Lirensing ip 16862, 104
 Fiche 50-445, 83/06/13, 8306140503
- --8306160506 "Reactor Vessel Exam Program "
 ADAMONIS, D.C. EFTHYMEOU, G.C. JOHNSON, R.M. Texas Utilities
 Services: Inc. 83/05/07 52pp 19862 105 24x
 Fichs: 50-445,83/06/13.8306160503
- 8305110475 IE Info Notice 83-40. "Need to Environmentally Qualify Epoxy Grouts & Sealers " Svc list ent! JORDAN.E L Division of Emergency Preparedness & Engineering 187064/22 Consolidated Edison Co of New 11 (post 830103) 83706/22 Consolidated Edison Co of New 11 (post 830103) 24X Fiche 50-000, 83/06/22,8305110475
 - 41, "Actuation of Fire Suppression Sys ated Equipment " Svc list
 - paredness & Engineering Consolidated Edison Co. of New <ahe. 90-000, 83/06/22,8309110477

- 8305110477 IE Info Notice 83-42, "Reactor Mode Switch Malfunctions " Svc list encl JURDAN: C L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/23 Consolidated Edison Co of New York, Inc 116pp 18996 242 24X Fichs 50-000.83/06/23,8105110479
- 8305110483 IE Info Notice 83-43. "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints "Sec list encl JURDANIE L Division of Emergelicy Preparedness & Engineering Response (Post 830103) 63/06/24 Consolidated Edison Co. of New York, Inc. 116pp 19046 297 24X Fiche 50-000,83/06/24,8705110483
- S Reportable occurrences, LLRs & related correspondence
- 8304090043 Interim deficiency rept re new fuel storage fack support anchors installed w/o proper authorization Initially reported on 830407 Approved anchoring design implemented No evidence that deficiency is generic GARY, R J Texas Utilities Generating Co 83/05/21 MADSEN, G t Region 4. Office of Director 2007 18/9J 285 24X Fiche 50-445,83/05/31,8306090043
- 8306130440 Interim deficiency rept re leidown HX anchors Initially reported on 830709 Evaluation continuing Investigation will be completed by 830708 GARY.R J laxes Utilities Generating to 83706/02 MADS!N.G L Region 4, Office of Director Ip 19821 211 24X Fiche 50-445.83706/02.8306130440
- 8306300055 Final deficiency rept re adhesive bond on Westinghouse NIP (loop power supply) printed cilcuit cards initially reported on 830601 Condition not reportable under LOCFRED 55(e)

 9ARY, R J Texas Utilities Generating Co 83/06/21 MADSLN.G L Region 4. Office of Director ip 171P1 018 24X

 Fiche 50-445,83/06/21.8306300055
- 8304300074 Final deficiency rept re Class I support math w/o complete NDE required for NF2500 Initially reported on 830525 Item nat reportable under (OCFR50 55(e) GARY, R J Texas Utilities Generating Co 83/06/21 MADSEN.O L Region 4, Office of Director ip 19121 002 24X Fichs 50-445,83/06/21,83063000/4
- 8304300088 Final deficiency rept re jam nots on riqid struts not adequately installed to prevent rotation of strut bariel Initially reported on 830826 Item not reportable under 10CFR50 55(e) OARY, R. J. Toxas Utilities Generating Co. 83/ Region 4. Office of Director. Ip. 17048-345 Fiche 50-445, 83/06/21, 8306300088 83/06/21 MADSEN, & L 345 24X
- 8306300167 Deficiency rept re nonsafety-related components in couling water Class V piping Controls will be added to existing level transmitters by 830801 to sense depletion of surge tank VARY, R J Texas Utilities Generating (o 83/06/P) Region 4, Office of Director 2pp 1712P 065 24X Fiche. 50-445, 83/06/21, 8306300167 83/06/PI MADSLN. 6 L
- T Hearing transcripts on non-antitrust matters
- 830408021B Forwards testimony of 1E Const Appraisal Team Insp Repts 50-445/83-18 & 50-446/83-12 TREBY. S A Hearing Branch I 83/04/04 BLOCH, P B , JORDAN, W II , MCCOLLUM, K A Atomic Safety and Licensing Board Panel 2pp 18771 004 24X Fichs 50-445,83/04/06,8304080218
- ~~8306080224 Testimony of AB Beach.DC Ford.RM Compton & WA Hansen re IE. Comst Appraisal Team Insp Repts 50-445/83-18 & 50-446/83-12 Changes & corrections to repts listed Prof qualifications enci BEACH, A B , FURD, D C , COMPTON.R M Director's Office, Office of Inspection and Enforcement 83/06/06 10pp 18771;013 D4X Inspection and Enforcement 83/0 Fiche 50-445, 83/06/06, 8306080218
- 8304080239 Forwards testimony & miscellaneous documents on NRC const appraise team rept

 REYNOLDS,N J Debevoise & Liberman REYNOLDS,N J Texas Utilities

 Generating Co 83/06/06 BLNCH,P B, NCCOLLOM,K,A, JURDAN,H H

 Atomic Safety and Litensing Board Panel Rep 18/71 | 15 24X

 Fichs. 50-445,83/06/06,8304080279
- --9306080241 Testimony of CT Brondt,RO Tolson & A Vega re NRC const appraisal team rept BRANDT,C T , TOLSON,R G , VEGA.A Texas Utilities Generating Co 83/06/06 25pp 1871 117 24X Fiche %0-445,83/06/06,8306080207
- 8304090013 Transcript of 830407 telephone conference in Bethesda. HD Pp 7.486-7.535 * Atomic Bafety and Licensing Board Panel 83/06/07 Sipp 1879 117 24X Fiche 50-445.83/06/07.8306090013

DOCKETED ITEMS

- B306170286 Transcript of 830613 hearing in Ft Worth, TX Pp 7,536-7,809 Supporting documentation entl Atomic Safety and Licensing Board Panel 83/06/13 273pp 18881 272 24X Fiche 50-445,83/06/13,8306170286
- 6306218059 Transcript of 830614 hearing in Fort Worth.TX Pp 7.810-Commissioners 83/06/14 269pp 10912 001 24X
- 8306210117 Transcript of 830615 hearing in Ft Worth, TX Pp 8,08-8,345 Supporting documentation encl * Atomic Safety and Licensing Board Punel 83/06/15 280pp 18917 146 24X Fichs 50-445,83/06/15,8306210119
- 8306210222 Transcript of 830616 hearing in Ft Worth, TX Pp 8,346-8,619 Supporting documentation encl * Atomic Safety and Licensing Board Panel 83/06/16 282pp 18916 063 24X Fithe 50-445,83/06/16,8306210222

♥ Operator Examinations

Fishe 50-445, 03/06/14, 8306210059

- 8304090312 Forwards Rev 1 to Training Manual Procedure TRA-204.
 "Licensed Operator Requalification Training Program"
 CLEMENTS, B R Texas Utilities Generating Co 83/06/04 DENTON:H R
 Office of Nuclear Reactor Regulation, Director 1p 18795 199
 24% Fiche 50-445.83/06/06.8306090312
- --8306090315 Rev I to Training Manual Procedure TRA-204, "Liconsed Operator Requalification Training Program "
 JONES.R A Texas Utilities Generating Co 83/05/13 27pp
 18795 200 24X Fiche 50-445.83/06/06.8304090312
- DOCKET SO-446 COMANCHE PEAK STLAM ELECTRIC STA JUNIT 2
- A Application/construction stage documents & correspondence
- 8304090162 Forwards table providing description of 830510 Amend 40 to FSAR re administrative controls, environ qualification tables & ESF components MARSHALL, J B Texas Utilities Services, Inc 83/05/11 JURKELL, 8 B Division of Licensing /pp 18792 308 24% Fiche 50-445,83/05/11,8306090162
- 8306010392 Forwards, for review, revised page from Chapter 17 1 of FSAR Change (Amend 40) adds more specific commitment re 8A erogram, per encl NRC 830307 request GARY, R J Texas Utilities Generating Co 83/05/23 COLLINS, J T Region 4, Defice of Director 4pp 18682 227 24X Fiche 50-445, 83/05/23, 8306010392
- 8306210403 Advises that Benjamin May House not eligible for inclusion in Natl Register of Historic Places Determination of eligibility notification encl YOUNGILOOD. B J Licensing Branch I 83/06/03 GARY:R J Texas Utilities Generating Co 5pp 18936 233 24% Fiche 50-445. 83/06/03.8306210403
- 8306100153 Forwards addl info re environ qualification of safety-related mechanical equipment, in response to Equipment Qualification Branch 830426 request W/six oversize drawings Aperture cards are available in PBR MARSHALL, J S Texas Utilities Services, Inc 83/06/07 YOUNGBLOOD, B J Licensing Branch | 12pp 18801 164 24X Fiche 50-445,83/06/07,8306100153
- 8306130193 Forwards audit rept re environ qualification verification of installed equipment per request No model indentification indicated on recombinen, however, natings into on nameplate sufficient to establish model identify MARSMALL, J S Texas Utilities Services, Inc. 83/06/07 YOUNGBLOOD, B J Licensing Branch I Spp 18826-278 24X Fiche 50-445-83/06/07.8306130173
- 8306130176 Forwards final response to NUREO-0612, "Control of Heavy Loads at Nuclear Power Plants" SCHNIDT.H C lexas Utilities Services, Inc 83/06/08 YOUNGBLOOD,B J Licensing Branch 1 153pp 18828 031 24X Fiche 50-445,63/06/08,8306130176
- B306130279 Submits results of testing program re tube vibration in Heatinghouse Model D-4 & D-5 steam generators Mods to steam generators & feedwater sys required to permit unrestricted operation Mods to begin B30615 SCHMIDT, H C Texas Utilities Services, Inc. B3/06/09 YDUNGBLORD, D J Office of Nuclear Reactor Regulation, Director, 37pp 18824 142 24X Fiche 50-445,83/06/09,8306130279

- 8306130293 Forwards proprietary "Counterflow Preheat Steam Generator Tube Vibration Summary Repts" & "Counterflow Preheat Steam Tube Expansion Rept " Repts withheld (ref 100FR2 790) SCHMIDT,H C Texas Utilities Servites, Inc 83/06/09 EISENHUT.D Q Division of Licensing 2pp 18823 275 24X Fithe 50-445,83/06/09,8306130293
- B304200019 Summary of B30331 meeting w/utils & Westinghouse in Bethesde, MD re Westinghouse analysis & evaluation of D4/D3/E steam generator mod HOPKINS, J B Licensing Branch 4 B3/06/14 Licensing Branch 4 22pp 18908 327 24% Fishe 50-000, B3/06/14 8306200019
- 9306280392 Advises that info submitted by util on 930610 re response to apen items from Equipment Qualification Branch SQRT is nonproprietary RAHE.E P Westinghouse Electric Corp 93/06/21 YOUNGBLOOD, B J Licensing Branch 1 lp 19019 008 24% Fiche 50-445, 83/06/21, 8306280392
- --8306280400 Forwards addl info re unresolved concerns from swismic & synamic qualification review of safety-related electrical & mechanical equipment.

 8CMMIDT.H C Texas Utilities Bervices, Inc 83/06/10 YDUNGBLOOD, B J Licensing Branch 1 164pp 19019 009 24X Fiche-50-445, 83/05/21, 8305280392
- 8306300120 Advises that info provided in Texas Utils 830610 ltr re open items from NRC Equipment Qualification Branch SQRT audit of site not Westinghouse proprietary as originally marked. RAHELE P Westinghouse Electric Corp 83706/21 YQUMOBLOOD, B J Licensing Branch 1 19 1910 077 24X Fiche: 50-445, 83/06/21. 830A300120
- F Security, medical, emergency & fire protection plans
- 8306010279 Forwards Rev 4 to physical security plan Rev withheld 305010279 Forwards Rev a to physical security plan new withher (ref 1056RF3 21)
 CLEMENTS.B R Texas Utilities Generating Co. B3/05/26 DENTON. Office of Nuclear Reactor Regulation, Director ip 18672: 236
 24% Fische 50-445, B3/05/26, B306010279 DENTON, H. R.
- 8306150101 Releases public version of revised emergency plan implementing procedures FELTON, J M Division of Rules and Records 83/06/06 Docum Management Branch ip 18872 121 24X Fiche 80-445,83/06/06, 8306150101 Document
- --8306150102 Forwards public version of revised emergency plan implementing procedures including Procedures EPP-101 repreparation of emergency plan procedures EPP-208 recontrol of site access & EPP-210 reevacuation W/o encl.

 8CHMIDT.R C Texas Utilities Services. Inc. 83/05/10

 COLLINS.J T. Rogion 4. Office of Director. 1p 18872 122.

 Fishe 80-445.83/06/06.8306150101
- Q Adjudicatory correspondence
- B3040303330 Forwards proposed order reflecting ASLB B30514 ruling reconsideration of thermal strasses under ASME Code Order incorporates subsequent ruling reinclusion of support frames in ASME Code definition of supports.

 REYNOLDS,N B Debevoise & Liberman REYNOLDS,N B Texas Utilities Generating Co B3/06/01 BLOCH,P B, JORDAN,W H, MCCGLLON,K A, Atomic Safety and Licensing Board Panel 7pp 18708-349, 24X Fiche 50-445,83/06/01,8306030330
- 8304070304 Fifteenth set of interrogatories & requests to groduce ELLIB, J Citizens Association for Sound Energy 83/06/04 Utilities Generating Co 3pp 18740-391. 24X Fiche-80-44B, pp. 104-48-70-107-204 83/06/04/8306070304
- --8306070306 Fifth set of interrogetories & requests to produce Certificate of Svc encl ELLIS,J Citizens Association for Sound Energy 83/06/04 Office of the Executive Legal Director 5pp. 18740.354, 24x Fiche 50-445,83/06/04,8306070304.
- 83060703B2 Forwards motion to reapen record re steam generator upper lateral restraint & J Doyle unexecuted affidavit ELLIB, J Citizens Association for Sound Energy. B3/06/04. BLOCH, F B . JORDAN, M. H . MCCOLLOM, K A. Atomic Bafety and Licensing Board Panel ip. 18741 312 24% Fiche 50-445.83/06/04.8306070382.
- --8306070394 Notion to respen record re-steam generator upper lateral restraint Util should be ordered to supply Citizens Assoc For Sound Energy winfo necessary to determine if problem exists Certificate of Svc encl.

 ELL19.7 Citizens Association for Bound Energy 83/06/04 Atomic Safety and Licensing Board Panel 8pp 18741 313 24X Fiche 50-445,83/06/04,8305070382

- 8304070350 Order extending time until 830706 for Commission to act to review ALAB-714
 CHILM.B J Dffice of the Becretary of the Commission 83/06/06
 Commissioners ip 18742 066 24X Fiche 50-445.83/06/06.
- B3060B021B Forwards testimony of IE Const Appraisa) Team insp Repts 50-445/83-18 & 50-446/83-12
 TREBY.E.A. Hearing Branch I B3/06/06 BLOCK, P B , JORDAN, W H , MCCOLLON, K A Atomic Safety and Licensing Board Panel 2pp 1871 004 24X Fiche 50-445, B3/06/06, B3060B021B
- --8306080222 Answer to ASLB inquiry reliterative sys for pipe design ASLB need not inquire into subj since iterative sys not issue in controversy Evidence in record sufficient to conclude process & piping adequate MIZUND
- --8306080227 Supplemental affidavit of TO Dunning re NRC consideration of voltage spike or pressure surge in piping sys Adequate analysis of control sys failure safety significance conducted w/o considering voltage spikes or pressure surges DUNTING.T O Instrumentation & Control Systems Branch 83/06/06 6pp 18771.023 24X fiche 50-445.83/06/06.8306080218
- 8304080239 Forwards testimony & miscellaneous decuments on NRC const appraisal team rept REYNOLDS.N J Debevoise & Liberman REYNOLDS.N J Texas Utilities Generating Co 83/06/06 BLOCH.P B , MCCOLLOM.K A , JORDAN.W H Atomic Safety and Licensing Board Panel 2pp 1877/ 115 24X Fiche 30-445,83/06/06.8304080239
- --B306080243 Response to ASLB inquiry re iterative siping design process ASLB should not inquire sum sponte into process since record evidence sufficient No basis exists for further inquiry into as-built verification program REVNOLDS, N 9 . KORIN, W A Teles Utilities Generating Co REVNOLDS, N 9 Debevoise & Liberman 63/06/06 9pp 18771 135 24X Fiche: 50-445, 83/06/06, 8306080237
- --8306080248 Affidavit of JC Finneran re ASLB inquiries on status of pipe support design verification & unstable support design Approx 86% of pipe supports vendor certified Approx 90% of review process for remaining supports complete FINNERANJ C Texas Willities Generating CO 83/06/03 5pp 1871 151 24% Fiche 50-445, 89/06/08/239
- 8305100223 Motion for stay of ASLB order re LOCA Record on issue should remain open until ASME Code interpretation received & analyzed, ELLIS, J. Citizens Association for Sound Energy. 83705/06 Atomic Safety and Licensing Board Panel. 4pp 18807 163 24X Fiche 50-445,83706/06,8306100223
- --6306100230 Affidavit of DH Boltz re interpretation of ASME Code Bubsection NF-1121(a) Linguistic analysis presented BOLTZ, D H Citizens Association for Sound Energy 83/06/05 17pp 18807 169 24X Fiche 50-445,83/06/06,8306100223
- ---8306100227 Forwards DH Goltz original signed affidavit H/o enc)
 Certificate of Svc enc1
 ELLIS.J Citizens Association for Bound Energy B3/06/06
 Docketing & Services Branch. 3pp 16807 186 24X
 Fiche 50-445,83/06/06,8306100223
- 8304080230 Forwards Region IV 930531 ltr & notice of violation to IE Const Appraisal Team Insp Repts 50-445/83-18 & 50-446/83-12 Ltr omitted from 83060& submittal to ASIB TREBY, 8 A Hearing Branch 1 83/04/07 BLOCH, P.B., JORDAN, W.M., MCCOLLOM, K.A. Atomic Safety and Licensing Board Panel Spp 18771 088 24X Fichs 50-445,83/06/07,8306080230
- 8306100118 Confirms 830526 telcon discussing conversation between & M Walsh re thermal expansion in piping or pape under accident conditions . MIZUNO, 0 8 Hearing Branch 1 83/06/08 ENNIS, K locitety of Mechanical Engineers 2pp 18602 027 24X 45,83/06/08,8306100118
 - ptice of DH Boltz appearance in proceeding Certificate of
 - Citizens Association for Sound Energy 83/06/08 3pp 24% Fichs.50-445,83/06/08,8306/50310.
 - Drwards miscellaneous ltrs.exhibits & stipulations re IE 50-445/82-26 & 50-446/82-14.W/o encis. Citizene Association for Bound Energy 83/06/08 FMRIN, W & Liberman 1p 19847 257 24X Fiche 50-445, 83/06/08.

- 8306150307 Motion for admission of new contention re adequacy of emergency planning Somervell County & Hood County Commitment expertise & resources inadequate to adopt & implement emergency plans Certificate of Svc encl MATHEMS. J. Teles, State of 83/06/09 Commissioners 9pp 19849 137 24X Fichs 50-445.83/06/09.8706150307
- 8306150406 Forwards cross-examination documents to assist util & MMC in preparing witnesses for questioning ELLIS.J Citizens Association for Sound Energy 83/06/09 ROTHSCHILD, M U Hearing Branch I REYNOLDS:N S Debevoise & Liberman REYNOLDS:N S Perss Utilities Concrating Co 2pp 18847-126 24X Fiche 50-445:83/06/09:8J06150406
- B30A150414 Forwards executed J Doyle 830A08 affidavit Unexecuted version encl w/Citizens Assoc for Sound Energy 830A04 motion to reopen record re steam generator upper lateral restraint 1850e
 ELLIG.J Citizens Association for Sound Energy 83/06/09 Docketing & Services Branch 1p 1884/ 091 24X Fichs 50-445.83/06/09.8306150414
- --8306150415 Affidavit of J Doyle is need to reopen record on stiem generator upper lateral restraint listue DDYE.J Citizens Association for Sound Energy 83/06/08 Opp 18847 092 24% Fiche 50-445,83/06/09,8306150414
- 8304150425 Forwards updated Somervell County emergency plan w/ Attachment S & Attachment S to Hood County emergency plan W/o encl REYNOLDS,N S Debevoise & Liberman REYNOLDS,N S Fexas Utilities Generating Co 87/06/09 BLOCH,P B JORDAN,W H , MCCOLLOH,R A Atomic Bafety and Licensing Banet Panel 1p 18847 090 24X Fishe 50-445,83/06/09.8306/50425
- B306150366 Response opposing Citizens Assoc for Sound Energy (CASE)
 B30604 motion to reopen record re upper lateral steam
 generator support CASE should be admonsted for raising new
 issues premised on speculation Certificate of Sec entl
 REYNOLDS:N S : HORIN.W A Texas Utilities Generating Co HORIN.W A
 Debevoise & Liberman 82/04/10 Atomic Safety and Licensing
 Board Panel 7pp 18847 304 24X Fishe 50-445,83/06/10.8306150364
- 8306150370 Forwards documents to assist NRC in cross-examining util panel consisting of CT Brandt, RG Tolson & A Vega TREBY, S A. Hearing Branch I. 82/06/10 ELLIS, J. Citizens Association for Sound Energy REYMOLDS.N. S. Debevoise & Liberman Ip. 18847-027 24X Fichs 50 445,83/06/10,8306150370
- B306150376 Forwards WP Haess supplemental affidavit re ASLB question on NRC position re application of GA/GC to sys important to safety & response to Citizens Assoc for Sound Energy motion to reopen record on upper lateral restreint issue ROTHSCHIED, M U Hearing Branch 1 83/06/10 BLOCH, P B . JORDAN, W H . MCCGLLOM, K A . Atomic Safety and Licensing Board Panel 1p 18847 075 24X Fire 50-445.83/06/10.8306150396
- --8306150400 Affidavit of WP Haass responding to AGLB 830510 question ie NRC position on application of QA/AC to sys important to safety NRC position on Commiche Peak consistent w/NRC position on Shoreham HAASS,W P GA Branch 83/06/10 3up 18847 076 24X Fichs 50-445.83/06/10.8306150376
- --8306150403 Response opposing Citizens Assoc for Bound Energy 830404 motion to reopen record re steam generator upper lateral support issue Assertions re placement of snubbers incorrect Certificate of Svc encl MIZUNO.0,9 Hearing Branch 1 83/06/10 Atomic Safety and Licensing Board Panel 6pp 18847 079 24X Fiche 50-445, 83/06/10, 8306150376
- 8306170406 Answer opposing State of IX 830607 motion for admission of new contention re adequacy of emergency planning Propused contention lacks requisite specificity & bases for late-filed contentions Certificate of Svc encl REYNDLDS, N S Texas Utilities Generating Co REYNDLD9, N S Debevoise & Liberman 83/06/12 Atomic Safety and Licensing Board Panel 26pp 18880 018 24X Fiche 50-445,83/06/12,8306170406
- 8306(50313 Forwards Secretary of Labor 6306(0 decision & final order in CA Atthison vs Brown & Root, Inc Certificate of Svc encl ROTHSCHILD, M U Hearing Branch 1 83/06/13 BLOCH, P B , URRDAN, W H , MCCULLDM. K A Atomic Safety and Licensing Board Panel 29pp 18849 099 24X Fiche 50-445,83/06/13.8306150313
- 8306150376 Summary of 830609 telton w/A6LB & parties re util draft order on thermal stress issue REYNGLDB,N B Texas Utilities Generating Co REYNOLDS,N S Debavoise & Liberman 83/06/13 6pp 18847 292 24X Fiche 50-445,83/06/13,8306150376

- 8306230381 Forwards Secretary of Labor decision & final order re CA Atchison vs Brown & Root, Inc Decision relevant to pending NRC 830311 petition for Commission review of ALAN-714 W/a encl ROTHSCHILD, M U Hearing Brouch 1 83/06/20 CHILK, S J Office of the Secretary of the Commission 1p 18943 243 24X Fichs 50-445, 83/06/20, 8306230501
- B306280556 Memorandum & order denying State of TX 830609 motion for admission of new contention or adequacy of emergency planning Late filing criteria not met BLOCH.P B. JORDAN, W H., MCCOLLOM.K A. Atomic Safety and Licensing Soard Panel B3/06/27 Texas, State of 7pp 19018-014 24X Fiche 50-445,83/06/27,8306280556
- 6306300056 Forwards util 811218 ltr to NRC, responding to ACRS 811117 comments re reactor protection sys, util mgt & drganizational capabilities & station operations review committee TREBY. S A Hearing Branch 1 83/06/28 JORDAN, W.H. Atomic Safety and Licensing Board Panel 1, 19121 012 24X Fiche 50-445, 83/06/28, 8306300056
- M Antitrust correspondence
- 8306230127 Advises that documents produced by Gulf States Utils Co.in response to NRC subpoens destroyed VOLER.B H Hearing Branch 2 83/06/21 CLEMENTS.D M Gulf States Utilities Co. 1p 18947 048 24% Fishe 50-000, 03/06/21
- Q Inspection reports, IE Bulletins & correspondence
- 8304080220 Forwards IE Insp Repts 50-445/83-06 & 50-446/83-03 on 830131-0204 No noncompliance noted MADECN G L. Region 4. Office of Director 83/04/14 GARY R J Teras Utilities Generating Co. 2pp 1877J 189 24X Fiche 50-445
- ---0306080221 IE Insp Repts 50-445/83-06 & 50-446/83-03 on 830131-0204 No noncompliance noted Major areas inspected preoperational environ protection programs, organization administration, audits, training, procedures & site tour HOLLEY, W. L., MURRAY, B., WESTERMAN, T. I. Region 4, Office of Director 83/04/12 21ppp 18771 191 24% Fiche 50-445, 83/04/14, 8306080220
- B305110458 IE Info Notice 83-32. "Ruptured Am-241 Sources Contained in Well Logging Device" Svc list encl TAYLOR.J M Division of Safeguards & Inspection Programs (Post B30163) C37.05724 Consolidated Edison Co of New York, Inc 125pp 18831 043 24X Fiche 50-000, 83/05/26, 8305)10458
- 8305110440 IE Info Notice 83-34. "Event Notification Info Worksheet" Svc list encl
 JURDAN.C L Division of Emergency Proparedness & Engineering
 Response (Fost 830103) 83/08/26 Consolidated Edison Co of New
 York, Inc 115pp 18732 085 24X Fiche 50-000,83/08/26.8305110460
- #306140370 Forwards IE Insp Repts 50-445/83-19 & 80-446/83-13 on 830420-22, 25, 27 & 0503-05 No noncompliance noted MADSEN. 6 L Region 4, Office of Director 83/05/27 GARY, R J Teras Utilistus Generating Co. 2pp 18832 123 24X Fiche 50-445, 83/05/27, 8306140370
- --8305140374 1E Insp Repts 50-445/83-17 & 50-446/83-13 on 830420-22,25,27 & 0503-05 No noncompliance noted Major areas inspected followup of allegations on protective contings & review of records for safety-related pipe supports GILBERT, L. D., JOHNSON, C. E., BESS, J. E., Region 4, Office of Director 83/05/24 9pp 18832 125 24X Fiche 50-445,83/05/27, 8305140370
- 8305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods Withdrawn at GWRs " Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/31 Consolidated Edison Co. of New York, Inc. 116pp 18732 208 24% Fiche 50-000, 03/05/31, 8305110461
- ---8306210110 Notice of violation from insp on 830214-0303 Noncompliance noted failure to provide adequate procedures instructions or drawing for installation of major items of equipment * Region 4, Office of Director 83/05/31 3pp 18914 208. 24X Fiche 50-445,83/05/31.8306210105

- 8306080230 Forwards Region IV B30531 ltr & notice of violation re IE Const Appraisal Team Insp Repts 50-445/83-18 t 50-446/83-12 Ltr omitted from 830606 submittal to ASLB TREBY, S A Hearing Branch 1. 83/06/07 BLOCH, P B Atomic Safety and Licensing Board Panel App 18771 OBB 24X Fiche 50-445,83/06/07,8306080230
- 8305110444 IE Info Notice 83-34, "Impact of Security Practices on Safe Operations" Svc list and I JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 93/06/09. Consolidated Edison Co. of New York, Inc. 119pp 15830 280 24X Fiche 50-000,83/06/09,8305110464
- 8305110470 IE Info Notice 83-38, "Defective Heat Sink Adhesive & Seismically Induced Châtter in Relays Within Printed Circuit Cards "Svc list encl JORDAN-E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co. of New York: Inc. 118pp 18920 225 24X Fiche 50-000.83/06/13.8305110470
- 8304090010 IE Info Notice 83-37, "Transformer Failure Resulting From Degraded Internal Connection Cables" Svc list and JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83706/13 Consolidated Edison Co of New York, Inc 243pp 18921 001 24% Fithe 50-000, 83/06/13, 8306090010.
- 8306160503 Forwards Westinghouse Procedure ISI-154, "Preservice & Inservice Insp of Reactor Vessels" & plant-specific reactor vessel insp program
 MARSHALL.JS Texas Utilities Services, Inc. 83/06/13
 BURHELL,8 D Division of Licensing Jp 18862-104 24X
 Fiche 50-445,83/06/13.8306160503
- 8305110475 IE Info Notice 83-40, "Need to Environmentally Qualify
 Epoxy Grouts & Sealers " Syc list encl
 JORDÁN.C i Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/06/22 Consolidated Edison Co of New
 York, Inc 115pp. 17021 177 24X Fichs 50-000,83/06/22.8305110475
- 8305110477 IE Info Notice 83-41, "Actuation of Fire Suppression Sys Causing Inoperability of Safety-Related Equipment " Syc list and! JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/22 Consolidated Edison Co. of New York, Inc 120pp 18997.007 24X Fiche 50-000,83/06/22,8305110477.
- 8305110479 IE Info Notice 83-42, "Reactor Mode Switch Malfunctions "
 Svc list encl
 JGRDAN.E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83706/23 Consolidated Edison Co of New
 York, Inc 116pp 18976 242 24X Fiche: 50-000, 83/06/23, 8305110479
- B30511Q483 IE Info Notice 83-43, "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints " Svc list encl JORDAN, E. L Division of Emergency Preparedness & Engineering Response (Post 830103) B3706/24 Consolidated Edison Co. of New York, Inc. 116pp 19046 277 24X Fiche 50-000, B3/06/24, B305110483
- S Reportable occurrences, LERs & related correspondence
- B304090043 Interim deficiency rept re new fuel storage rack support anchors installed w/o proper authorization initially reported on B30407 Approved anchoring design implemented. No evidence that deficiency is generic OARY.R J Texas Utilities Conserating Co. 83/05/31. MADSEN.Q.L Region 4. Office of Director 2pp 18793 285. 24X Fiche 50-445.83/05/31.8304090043
- 9306:30440 interim deficiency rept re latdown HX anchors Initially reported on 630709 Evaluation continuing Investigation will be completed by 830708
 ORY, R J Texas Utilities Generating Co 83/06/02 MADSEN. Q L. Region 4. Office of Director ip 19821 211 24X
 Ficha 50-445,83/06/02,8306130440
- 8306300055 Final deficiency rept re adhesive bond on Westinghouse NLP (loop power supply) printed circuit cards Initially reported on 830601 Condition not reportable under 10CFR90 55(e)
 ORRY.R J Texas Utilities Generating Co. 83/06/21 MADSEN, O, L Region 4, Office of Director ip 19121, OIB 24X Fiche 50-445, 83/06/21, 8306300055
- 8306300074 Final deficiency mept me Class i support math w/o complete NDE required for NF2500 Initially reported on 830525 Item not reportable under 10CFR50 55(e).

 9ARY: R. J. Texas Utilities Generating Co. 83/06/21 MADSEN, Q. L.,
 Region 4, Office of Director ip. 1932; 002 24X

 Ficho 50-445,83/06/21,8306300074

- 8306300088 Final deficiency rept re jam nots on rigid struts not adequately installed to prevent rotation of strut barrel Initially reported on 830526 Item not reportable under 10CFR50 55(e).

 OARY.R J Texas Utilities Generating Co 83/06/21 MADSEN, G L Region 4, Office of Director Ip 17048 345 24X Fiche 50-445,83706/21,8306300088
- 8306300167 Deficiency rept re nonsefety-related components in cooling water Class V piping Controls will be added to existing level transmitters by 830801 to sense depletion of surge tank QARY.R J Texas Utilities Generating Co 83/06/21 MADSEN.G L Region 4, Office of Director 2pp 19122 065 24X Fichs.50-445.83/06/21.8306300167
- T Hearing transcripts on non-antitrust matters
- 8306080218 Forwards testimony of IE Const Appraisal Team Insp Repts 50-445/83-18 & 50-446/83-12 TREBY.8 A Hearing Branch 1 83/06/06 BLOCH.P B Atomic Safety and Licensing Board Panel 2pp 18771 004. 24X Fiche 50-445,83/06/06.8306080218
- --8306080224 Testimony of A9 Beach, DC Ford, RM Compton & WA Hausen re It Const Appraisal Team Insp. Repts 50-445/83-18 & 50-446/83-12 Changes & corrections to repts listed, Prof qualifications encl.

 BEACH, A B , FORD, D C , COMPTON, R. M Director's Office Office of Inspection and Enforcement 83/06/06 10pp 18771 013 24X Fiche 50-445,83/06/06.8306080218
- 8306080239 Forwards testimony & miscellaneous documents on NAC const appraisal team rept REYNOLDS,N J Dabevoise & Liberman. 83/06/06 BLOCH.P B Atomic Safety and Licensing Board Panel 2pp 18771 115 PAX Fiche 50-445,83/06/06.8304080239
- --8306080241 Testimony of CT Brandt R9 Tolson & A Vegs re NRC const appraisal team rept BRANDT,C T. TOLSON.R G. VEGA.A. Tries Utilities Generating Co 83/06/06 25pp 18771 117 24X Fiche 50-445,83/06/06.0306080239
- 8304090013 Transcript of 830607 telephone conference in Bethesda, MD Pp 7,486-7,535.

 * Atomic Safety and Licensing Board Panel 83/04/07 5ipp 18793 117. 24X Fiche 30-445,83/06/07,8306090013
- 8306170284 Transcript of 830613 hearing in Ft Worth, TX Pp 7,536-7,807 Supporting documentation encl. * Atomic Safety and Licensing Board Panel 83/06/13 273pp 18881 272. 24X Fiche 50-445,83/06/13.8306170286
- 8306210059 Transcript of 830614 hearing in Fort Worth, TX Pp 7,810-8,079 * Commissioners 83/06/14 269pp 18912.001 24X Fiche. 30-445.83/06/14.8306210059
- 8306210117 Transcript of 830615 hearing in Ft Worth.Tx Pp 8.08-8.345 Supporting documentation enel * Atomic Safety and Licensing Soard Patel. 83/06/15 280pp 18917.146 24X Fiche 50-445.83/06/15.8306210119.
- 8306210222 Transcript of 830616 hearing in Ft Worth, TX. Pp 8, 346-8, 619 8upporting documentation encl * Atomic Bafety and Licensing Board Panel 83/06/16 282pp. 18916.063, 24% Fiche 50-445.83/06/16.8306210222
- V Operator Examinations
- 8306090312 Forwards Rev 1 to Training Manual Procedure TRA-204,
 "Licensed Operator Requalification Training Program"

 CLEMENTS, B R Texas Utilities Generating Co 83/06/06 DENTON, H R
 Office of Nuclear Reactor Regulation. Director 1p 18795 199
 24X Fichs 50-445,83/06/06.8306090312.
 - 15 Rev i to Training Manual Procedure TRA-204, "Licensed Requaliffication Training Program." Texas Utilities Generating Co. B3/05/13 27pp 24X Fiche 50-445, B3/06/06. B306070312

- DOCKET STN-50-447 GESSAR-238
- A Application/construction stage documents & correspondence
- 8306080434 Discusses potential for delays in GESSAR-11 severe accident review atchedule Mases for delay was development of source term which would not be completed until Feb 1984 Schedule impacts of up to 8 months could be encountered SCALETTI.D C Standardiration & Special Projects Branch MIRAGLIA.F J Assistant Director for Safety Assessment 1p 18792 193 24% Fishe 50-447.83/06/02.8306080434
- B306090236 Forwards draft Amend 17 to GESbAR-II re CP/multi-plant licensing % SRP rules SHERMODD.0 G General Electric Cu G3/06/07 EISENHUT.D Q Division of Licensing 125pp 18796 239 24X Fiche 50-447, B3/06/07,B306090236
- 8306170214 Forwards supplemental response to Question 410 24 of NMC 820825 response & summary of measures taken in GESSAR-II design to avoid intergranular stress corrosion cracking Info will be included in Amend IB scheduled for Jul 1983 SHERMODD, 9 Q General Electric Co 83/06/15 FISENNUT, D Q Division of Licensing 8pp 18882 306 24X Fiche 50-447,83/06/15,8306170214
- K Utility Final Safety Analysis Report (FSAR) & amends
- 8306070105 Forwards Amend 15 to application for review of Amend 15 to OESSAR-11, consisting of proprietary & nonproprietary portions Proprietary portion withhold (ref 10CFR2 790) & submitted under separate cove: 8HERNDOD, 0 @ General Electric Co 03/05/24 EISENHUT, D @ Division of Licensing 2pp 18/44 246 24X Fiche 50-447,83/05/24, 8306070105
- --8306070111 Amend 15 to application for review of Amend 15 to GLbSAR 11 SHERWOOD, G G General Electric Co D3/05/24 1p 18744 240 24% Fiche 50-447.83/05/24,8306070105
- --8306070114 Amend 15 to GESSAR 11 * General Electric Co 22A7007 83/05/24 515pp 18/44 247 24% Ficho 50-447,83/05/24,8306070105
- 8306070201 Forwards proprietary portion Amend 15 to GESSAR-II re human factors sys analysis emergency procedures Info withheld (ref 10CFR2 77)
 SHERMOOD, G G General Electric Co 83/05/24 EISENHUT, D G Division of Licensing Spp 18747 011 24X Fiche 50-447, 83/05/24, 8306070201
- 8306270481 Forwards proprietary Amend 16 to GESSAR-II.describing design considerations to reduce sabotage risk Amend withheld (ref 10CR2 790)
 SHERMODD 0 0 General Electric Co 83/06/15 EISENRUT.D 0
 Division of Licensing 2pp 19049 277 24X Fiche 50-447,83/06/15,836270481
- 8306290495 Forwards nonproprietary Amend 16 to OESSAR-II.providing assessment of design features which reduce sabotage risk SHERWOOD, G G General Electric Co &3/06/15 ElSCANUT, D & Division of Licensing ip 19052 335 24X Fiche 50-447,83/06/15, 8306290495
- --8306290500 Nonproprietary Amend 16 to Application for review of GESSAR-II Amend provides assessment of design features which reduce salotage risk GUIRK.J F. Ceneral Electric Co. 83/06/15 Division of Licensing Jp. 19052
- --8306270504 Nonproprietary Amend 16 to GESSAR-11, providing assessment of design features which reduce sabotage risk

 * General Electric Co 83/06/15 2/pp 19082 337 24X
 Fiche 50-447,83/06/15,8306290495
- 8306290507 Forwards Amend 17 to GESSAR-II, furnishing new App 10 & revised Section 1 8 & clarifying discrepancies in text SHERHOOD, 0 G. General Electric Co. 03/06/15 EISENHUT, D. 0 Division of Licensing ip 19050 011 24X Fiche 50-447.03/06/15.8306290507
- --8306290512 Amend 17 to GESSAR-II, furnishing new App 10 & revised Section 1 8 & clarifying discrepancies in text GUIRK, J F General Electric Co. B3/06/15 Division of Licensing 1p 19050 012 24% Fiche 50-447, B3/06/15, B306290507
- --8306290515 Amend 17 to GESSAR-II, furnishing new App 10 & revised Section 1 B & clarifying discrepancies in text * General Electric Co 83/06/15 174pp 17050 013 24X Fichs 50-447,83/06/15,8306270507

- O Advisory Committee on Reactor Safeguards reports & correspondence
- B306270097 Forwards, for info, ACRS B30615 comments on application for final design approval of GESSAR-II
 THOMAS: C D Standardization & Special Projects Branch B3/06/23
 SHERHOOD, C G Ceneral Electric Co 2pp 19046-173 24X
 F1che 50 447, 83/06/23, 8306290089
- --SJ06290122 Summarizes ACRS 278th meeting on BJ0609-11 re limited review of final design approval of GLSSAR-II BWR/6 nuclear island design GBSAR-II design can be incorporated in plants w/walld OP that references PDA in CP application RAY, J J ACRS Advisory Committee on Reactor Safeguards BJ706/15 PALLADINO, N J Commissioners 3pp 19046 175 PAX Fiche 50-447, 83706/20,8306290089
- DOCKET STN-50-454 BYRON STATION, UNIT 1
- A Application/construction stage documents & correspondence
- 8306030417 Requests info re identification of safety-related mechanica) equipment located in harch environ areas including required operating times & plant location Info requested within 30 days of receipt of itr YDUNOBLOOD, B. J. Licensing Branch 1 83/05/20 [ARRAR, D.f. Commonwealth Edison Co. 3pp. 18735-359 24X Fiche, 50-000, 83/05/20, 83/030417
- 830&010019 Summary of 830504 meeting w/util.Westinghouse.Sargent & Lundy & Energy.Inc in Bethesda,MD re design verification programs
 OLSHANL N Licensing Branch I 83/05/23 Licensing Branch I 4pp 18487 171 24X Fiche 80-484,83/05/23.8304010019
- 830.6010031 Bummary of 830513 meeting w/util.Westinghouse & Sargent & Lundy in Bethesda, MD re review of seismic qualification & gump & valve operability OLBHAN.L N Licensing Branch 1 83/05/23 Licensing Branch 1 4pp 18687
- 8306030517 Board Notification 83-74 submits info re work stoppage on installation of new pipe whip restraints Stop work action related to deficiencies in applicant QA program Hork will resume when upgraded program in place NOVAK.T M. Assistant Director for Licensing 83/05/23 Atomic Safety and Licensing Board Panel 6pp 18735 054 24X Fiche 50-454, 83/05/23, 8306030517
- 8396090194 Discusses util interpretation of 10CFR50 49. "Environ Qualification of Electrical Equipment Important to Safety for Nuclear Power Plants "Intent of rulemaking is to require upgrade program for replacement equipment not parts FARRAR.D L Commonwealth Edison Co 83/06/03. DENTIN.H R Office of Nuclear Reactor Regulation. Director 3pp 18/76 090 24X Fichs 50-000, 83/06/03,8306090194
- 8304200019 Summary of 830331 meeting w/utils & Westinghouse in Dethesda, MD re Westinghouse analysis & evaluation of D4/D5/E steam generator mod MOPKINS, J B Licensing Branch 4 83/06/14 Licensing Branch 4 22pp 18708 327 24X Fiche 50-000,83/06/14,8306200019
- 830623023/ Forwards add1 info re use of PORVa for venting & depressurizing RCS at facilities & response to FBAR Objection 212 159, to be incorporated into future FBAR amend TRAPMLT R Commonwealth Edison Co. 83/06/16 DENION H R Office of Nuclear Reactor Regulation, Director 18pp 18948-235 R4X Fiche 50-000.83/06/16.8306230237
- B304240377 Summary of Caseload Forecast Panel B30324-25 meetings w/uti) in Ogle County. It re independent assessment of applicant fuel load date of B30931 Fuel load will not occur earlier than Nov 1793

 OLBHAN. L. N. Licensing Branch 1 B3/06/17 Licensing Branch I 75pp 18987 057 24X Fiche 50-454, 83/06/17. 8306240379
- 9306270322 Provides addl details re control of heavy loads during const when new fuel essemblies being stored in spent fuel pit Duo to failure of reactor coolant pump at Dyron I, fuel handling bldg crane will be installed TRAHH, TR Commonwealth Edison Co 83/06/17 DENTON, HR Office of Nuclear Reactor Repulation, Director, Jp 18794 073 24X Fichs. 50-000, 83/06/17,8306270372
- 9306240252 Revises estimated fuel load dates to Oct 1980 for LaSalle County & Dec 1983 & May 1985 for Byron Units 1 & 2. respectively STIEDE. H L Commonwealth Edison Co 83/06/21 'DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 18981 323 24X Fiche 50-000, 83/06/21, 8306240252

- 8306270373 Notifies of change in FSAR distribution All nuclear power plant activities transferred to new IL Dept of Nuclear Safety State copy of FSAR amend should be sent to listed address
 TRANH, T R Cummonwealth Edison Co 83/06/21 DENTON, H R Dff(coof) Of Nuclear Reactor Regulation, Director ip 18793-313 24X
 Fiche 50-000,83/06/21.8306270373
- 8306300032 Revises estimated fuel load dates, based on const activity & presperational testing budget review Fuel load scheduled for 831001, Dec 1983 & May 1985 for LeSalla County Unit 2 & Byron Units i & 2, respectively 8TIEDE, W L Commonwealth Edison Co 83/06/21 KEPFLER, J @ Region 3, Office of Director ip. 19120 311 24X Fiche: 50-000, 83/06/21, 8306300032
- E NRC Safety Evaluation Report (SER), suppls & correspondence
- 8306220001 Forwards add1 info re seismic design basis for river screenhouse Review of info should help close Confirmatory Issue I of BER Values presented in FBAR are reasonable for matls underlying river screenhouse TRAMM. T R Commonwealth Edison Co 83/06/15 DENTON, H R Office of Nuclear Reactor Regulation, Director 15pp 18928 063 24X Fiche 50-454,83/06/15,8306220001.
- 8306270431 Forwards advance copy of rev to Section E 17 of App E to FBAR Section describes sefety parameter display sys. Info should close BER Outstanding Item 16.

 TRAMM.T R Commonwealth Edison Co 83/06/17 DENTON, H R Office of Nuclear Reactor Regulation. Director 13pp 19345:353 24X Fiche 50-000.83/06/17.8306270401
- 8306240070 Requests add1 info re moisture separators of heaters in filter sys serving nonaccessible area & fuel handling bldg for SER review Info requested within 30 days to maintain review schedule YGUNOBLOOD, B J Licensing Branch 1 83/06/21 FARRAR, D.L. Commonwealth Edison Co 3pp 18985 020 24X Fiche 50-000,83/06/21,8306240070
- F Security, medical, emergency & fire protection plans
- 8304090247 Confirms B30401 telcon re changes to exercise windows for Dresden & Byron Nuclear Power Stations Dresden partial exercise will be conducted during wk of B30912 w/Byron full-scale exercise beginning wk of B31114
 JONES-E E Illinois, State of, 83/06/01 KEPPLER, J. Region 3, Office of Director Jp JB795:319 24X Fiche. 50-000, 83/06/01. B306090247
- 8306090221 Forwards current versions of all prefire plans, per requirements of 10CFR50.App R, Paragraph 3 K i2 Plans will be continually revised & future revs will not be formally subsitted unless specifically requested TRAPM.T R Commonwealth Edison Co 83/06/02 DENTON, H R. Office of Nuclear Reactor Regulation. Director ip 18795 119 24X Fiche 50-454,83/06/02,8396090221
- --8306090R23 Prefire plans * Commonwealth Edison Co 83/05/19 113pp 18796·120 24X Fiche 50-454,83/06/02,8304090R21
- 8306160214 Submits correction to 830601 ltr Date of reassessment will be made prior to 830801, not 831001 JONES, E. E. Illinois, State of 83/06/09 KEPPLER, J. Region 3, Office of Director 1p 18861, 358 24% Fiche 50-000, 83/06/09, 8306160214
- 8306230257 Forwards addl info on communications & cable spreading room suppression sys re fire protection program Third radio communication channel being installed. Repeater will be located in turbine bldg.

 TRAMM.T.R. Commonwealth Edison Co. 83/06/17, DENTON.H.R. Office of Nuclear Reactor Regulation, Director 5pp 18745:016 24X Fichs 50-000.83/06/17,8306230257.
- 8306230412 Provides additings requested in NRC 830411 ltr reinstrumentation used to assure safe shutdown in event of fire Info will be incorporated into FBAR & fire protection rept in future amends
 TRAMM.TR Commonwealth Edison Co 83/06/17 DENTON, HR. Office of Nuclear Reactor Regulation, Director 52pp 18943, 136 24X Fiche 80-000,83/06/17,8306230412

Q Adjudicatory correspondence

- 8306010497 Forwards marked-up Joint Intervenor Exhibit 14 re radiological emergency response survey Ambulance medical syes, indicating stricken portions per ASLB 830426 ruling encl Certificate of Svc encl COPELAND, V G Isham, Lincoln & Beale COPELAND, V G Commonwealth Edison Co 83/05/05 SMITH. I W . COLE.R F . CALLIHAN, A D . Atomic Safety and Licensing Board Panel 24pp 18674 328 24% Fiche 50-454,63/05/26,8306010457
- 8306020437 Forwards Roctford League of Women Voters proposed findings of fact & conclusions of law re Contention 106 on seismology, per 820818 stipulation THOMAS, D.C. Illinois Institute of Technology, 83/05/31 SHITM, I.W., COLE, R.F., CALLIIAN, D. Atomic Safety and Licensing Board Panel 12pp 18493 228 24X Fiche 50-454,83/05/31,8306020437
- 8306060193 Forwards proposed findings of fact & conclusions of law re seismology, water hammer & ALARA Final agreement not reached re procedural history COPELAND, V O Isham, Lincoln & Beale COPELAND, V O Commonwealth Edison Co 63/05/31 SMITH. I V. COLE. R F. CALLIHAN, A D Atomic Bafety and Licensing Board Panel 2pp 18718 261 24X Fiche 50-454,83/05/31.8306060193
- --8306060196 Proposed findings of fact & conclusions of law resistance, water hammer & ALARA
 MILLERIM I BIELAHSKI.A P , COPELAND, V 0 Commonwealth Edison Co
 83/05/31. 104pp 18718 263 24% Fiche 50-454,83/05/31.
 8306060193
- 8304080143 Forwards proposed findings of fact & conclusions of law on Contention 9a re water hammer for the Environment (BAFE) CHAVEZ, D. Sinnissippi Alliance for the Environment (BAFE) CHAVEZ, D. DeKelb Area Alliance for Responsible Energy 83/05/31 Atomic Safety and Licensing Board Panel 19 18772 290 24X Fiche. 50-454.83/05/31,8306080143.
- --8306080145 Proposed findings of fact & conclusions of law on Contention 9a re water hammer.

 * Simissippi Alliance for the Environment (SAFE) * DeKalb Area Alliance for Responsible Energy 83/05/31 19pp 18772 291 24X Fiche 50-454.83/05/31,8306080143
- 8306060286 Requests delay of plant licensing & operation until design, OA.waste disposal & emergency procedure problems resolved PULIDD.N Affiliation Unknown B3/06/03 SMTTH.I W Atomic Safety and Licensing Board Panel ip 18729 CGS 24X Fiche 50-454.83/06/03.8306060286
- 8306060302 Complaint filed in Circuit Court of Seventeenth Judicial Circuit, Hinnebage County, IL requesting imposition of punitive damages for wrongful diversion of waste water onto plaintiff property
 FEARER. W P Motor Oils Refining Co FEARER. W P Fearer & Nye 83/06/03 Illinois, State of 5pp. 18727 097 24X
 Fiche 50-454, 83/06/03.8306060302
- 8306070342 Supplementary memorandum opposing intervenor motion to reopen record Neither triable issue nor significant safety issue exists re Hughes allegations Centificate of Svc enci BECKER.B D Commonwealth Edison Co 83/06/07 Atomic Sofety and Licensing Board Panel 12pp. 18794 322 24X Fiche 50-454.83/06/07, 8306070342
- 8304100201 Brief supporting motion to admit J Hughes testimony Intervenors have raised serious & significant safety issues re quality of work at plant Hughes testimony should be considered in ruling on Contention IA W/Certificate of Svc WHICHER, J M League of Women Voters of Rockford, IL. WHICHER, J M DeKalb Area Alliance for Responsible Energy. WHICHER, J M Sinnissippi Alliance for the Environment (SAFE) 83/06/07. Atoms Safety and Licensing Board Panel 21pp 18805, 230 24X Fiche 50-454, 83/06/07, 8306100201
- 8306130445 Forwards proposed findings of fact & conclusions of law re steam generator tube integrity Document should be filed w/830531 proposed findings re-seismology, water hammer & ALARA GOLDFEIN.H R Lincoln & Beels GOLDFEIN.H R Commonwealth Edison Co. 83/06/07. BMITH.I.W., COLE, R F, CALLIHAN.A.D Atomic Safety and Licensing Board Panel 2pp 18820 319. 24% Fiche 50-454,83/06/07.8306130445
- --B306i30452 Proposed findings of fact & conclusions of law re steam generator tube integrity Certificate of Bvc encl
 QALLO, J. COLDFEIN, H. R. Commonwealth Edison Co. QALLO, J. Isham,
 Lincoln & Beals., 83/06/07 64pp 18820 321 24X
 Fiche, 50-454, 83/06/07, 8306i30445

- B306150402 Informs that radiological emergency exercise moved to wk of 831114, to accommodate illinois Emergency Sycs & Disaster Agency Syc list encl BIELAWSKI, A P I ham, Lincoln & Beale BIELAWSKI, A P Commonwealth Edison Co 83/06/07 SMITH. I W. COLF. R F. CALLIHAN, A D Atomic Safety and Licensing Board Panel 3pp 18847 129 74X Fiche 50-454. B3/06/07, B306150402
- 8306150420 Forwards motion for & amend to consolidate Dekalb Area Alliance for Responsible Energy/Sinnissippi Alliance for Environ Contention 3 w/Rockford League of Vomen Voters Contentions 19 & 108
 BIELAWSKI, A P Isham, Lincoln & Beale BIELAWSKI, A P Commonweal Edison Co 83/06/07 Office of the Secretary of the Commission 2pp 18847 095 24X Fiche 50-454,83/06/07,8306150420
- ~~8306150436 Motion to amend & consolidate Dekalb Area Allianto for Responsible Energy/Sinnissippi Alliance for Environ Contention 3 w/Rockford League of Women Voters Contentions 69 & 108 CHAVEZ, D Dekalb Area Alliance for Responsible Energy (HAVIZ, D Sinnissippi Alliance for the Environment (BAFE) MORRISIN.P League of Women Voters of Rockford, IL 83/02/21 Atomic Bafety and Licensing Board Panel 4pp 18847 097 24% Fiche 50-454,83/04/07,8304150420
- --8306150442 Amend & consolidation of Dekalb Area Alliance for Responsible Energy/Sinnissippi Alliance for Environ Contention 3 & Rockford Leaque of Womrn Voters Contention: 19 & 108
 CHAVEZ, D. DeKalb Area Alliance for Responsible Energy (MAVEZ, D. Sinnissippi Alliance for the Environment (SAFE) MORRISON. P. League of Women Voters of Rockford, 1L. 83/02/21 Atomic Safety and Licensing Board Panel 8pp 10H47 101 249
 Fiche 50-454.83/06/07.8306150420
- 830&150&00 Notifies that pending review of NRC-commissioned study of current sabotage problems at nuclear power plants, intervence may move to reopen evidentiary record to consider ramifications of study Svc list end.

 THOMAS, D.C. Illinois Institute of Technology THOMAS, D.C. Affiliation Unknown 83/06/09 SMITH, J.W. COLE. R. (... CALLINA, D. Atomic Safety and Licensing Board Panel 3pp 19847-118 24X Fiche 50-454,83/06/09,830&150408
- 8306200300 Reply opposing Rockford League of Women Voters proposed findings of fact & conclusions of law re seismology Certificate of Svc encl ObloPEIN.M R Commonwealth Edison Co GO: DFEIN.M R Isham. Lincoln & Beals 83/06/09 10pp 18700 176 24X Fiche 50-454.63/06/09.
- B306200304 forwards util reply to Rockford League of Women Voters proposed findings of fact & conclusions of law re seismology Related correspondence W/o enci.
 COPELAND.V G Isham. Lincoln & Beale COPELAND.V G Commonwealth Edison Co B3/06/09 SMITH.I W COLC.R F . CALLIHAN.A D Alomic Safety and Licensing Board Panel 2pp 18900 170 24X Fiche 50-454.83/06/09.8306200304
- 8306130361 Proposed findings of fact & conclusions of law in form of partial initial decision on seismology & water hammer issues Certificate of Svc encl GOLDBERG, & C Hearing Branch 4 83/06/10 39pp 18822 [14 24X Fichs 50-454,83/06/10,830613036]
- 8306170371 Forwards NRC 830531 ltr transmitting IE lnsp Rept 50-454/83-16 & notice of violation Rept supports intervenor position that util unwilling or unable to maintain effective GA/GC program Svc list encl HHICHER, J M Businessmen for the Public Interest WHICHER, J M League of Women Voters of Rockford, IL WHICHER, J M Sinnissippi Alliance for the Environment (SAFC) B3/06/16 SHITH, I W, CALLAHAN, A D. COLE, R F. Atomic Safety and Licensing Roard Panel 17pp 18880 294 24% Fiche 50-454,83/06/13,83061/03/1
- 8306150318 Proposed findings of fact & conclusions of law in form of supplemental partial initial decision on occupational radiation safety & steam generator issues Certificate of Sv. encl.
 GCLDBERG, & C Hearing Branch 4 RAWSON, R J Hearing Branch 3 83/06/14 120pp 18948 328 24X Fiche 50~454,83/06/14,8306150318
- 8306170378 Advises that NRC will not reply to party 830607 supplemental briefs re intervenor 830427 motion to reopen record NRC position already matter of record GDLDBERQ, 8 C Hearing Branch 4 83/06/14 SMITH, I W , CDLE, R F , CALLIHAN, A D Atomic 8afety and Licensing Board Panel 2pp 18880 248 24% Fiche 50-454,85/06/14,8306170378

DOCKETED ITEMS

- --8306170JB4 Confirms that JM Whicher will represent J Hughes, former employee of Pittsburgh Testing Labs, per B30427 tolcon NRC should not contact Hughes directly Hoghes Statement, prepared by Region III. requested HHCCHER. J M. Businessmen for the Public Interest B3/04/20 LEMIS. S H. Region 3.0ffire of Director 2pp 18380-250-24X Fiche 50-454.8J/06/14.83061/03/8
- --8306170389 Advises that author will represent J Hughes, former employee of Pittsburgh Testing Labs & requests Hughes Jan 1983 statements to NRC & documents provided to NRC HITCHER. J M Businessmen for the Public Interest 83/04/28 PAWLICK. E Region 3, Office of Director 2pp 18880 252 24X Fithe 50-434.83706/14.8304170378
- --8306170392 Responds to 830420 ltr & transmits JH Hughes 830119 statements Other mati/documents being used in angoing investigation & cannot be provided PAMLIN-C T Region 3. Office of Director 83/05/13 WHICHER.J Businessmen for the Public Interest ip 18880 254 247 Fichs 50-454,83/06/14-83061703/8
- 8306200320 Proposed findings of fact & conclusions of law re ALARA & steam generator tube integrity— THOMAS, D.C. League of Women Voters of Rockford, IL. THOMAS, D.C. Thomas, D.C. 83/06/14 32pp 18899 173 24X Fiche 50-454, 83/06/14, 8306200320
- --8306200327 Motion for extension until 830628 to file proposed findings of fact & conclusions of law re Contintions 22 & 9(c)
 THOMAS.D C League of Women Voters of Rockford, IL THOMAS.D C
 DeMaib Area Alizance for Responsible Energy THOMAS.D C
 Sinnissippi Allizance for the Cuvironment (SAFE) 83/06/14
 Atomic Safety and Licensing Board Panel Ip 18699 205 P4X
 Fiche 50-454.83/06/14,8306200320
- --8306200331 Affidavit of DC Thomas supporting extension until 800628 to file proposed findings of fact & conclusions of law re Contentions 22 & 9(c) Time needed due to heavy tital & teaching schedule Certificate of 5vc oncl
 THOMAS.D C League of Women Votors of Rockford, IL THOMAS.D C. DeKalb Area Alliance for Responsible Energy THOMAS.D C Sinnissippi Alliance for the Environment (SAFE) 83/06/14 3pp 18079 204 24X Fishe 50-454.83/06/14,8306200320
- 8304200350 Forwards 830406 memorandum & unexecuted stipulations re emergency planning contentions COPELAND.V 0 Isham, Lincoln & Beale COPELAND.V 0 Communicalth Edison Co 83/06/14 Docketing & Terrices Branch 47pp 18900 274 24X Fiche 50-454,83/06/14,8006200350
- 8306200274 Certification to Commission of ASLB recommendation that Commission confer continuing jurisdiction to ASLB or clarify ASLB has jurisdiction to resolve specified emergency planning disputes after decision authorizing operation CALLIHAN.D. COLE, R.F., SMITH.I W. Atomic Bafety and Licensing Board Panel 83/06/17 21pp 18948 008 PAX Fiche 50-454.83/06/17, 8306200294
- 8306210281 Proposed findings of fact & conclusions of law in form of supplemental partial initial decision on emergency planning I saves Certificate of Svc encl GOLDBERG, S C Hearing Branch 4 83/06/20 43pp 18714 310 24X Fiche 50-454,83/06/20,8306210281
- 8306270022 Findings of fact & conclusions of law re emergency planning * DeKalb Area Alliance for Responsible Energy * Sinnissippi Alliance for the Environment (SAFE) * League of Women Voters of Rockford, IL 83/06/20 67pp 19018 259 24X Fiche 50-454,83/06/20,8306270022
- B306270041 Proposed findings of fact & conclusions of law re umergency planning Certificate of Svc encl Miller, M I - BICLAWSKI, A P , COPELAND, V Q Commonwealth Edison Co B3706/20 53pp 17012 326 24X Fiche 50-454, B3/06/20, 8306270041
- B306270383 Forwards will proposed findings of fact & conclusions of law re emergency planning to be incorporated w/830531 & 0607 submittals W/o encl COPELAND, V g Osmannucalth COPELAND, V g Osmannucalth Edison Co 83/06/20 SMITH, I W, COLE, R F., CALLIMAN, A D Atomic Safety and Licensing Board Panel ip 18993 165 24X Fiche 50~494,83/06/20,8306270383
- 8306230352 Requests cooperation of Ofc of Investigations in response hearing, in particular by releasing perticent Ofc of Investigations documents, insp. repts & hearing testimony SMITH, I.W. Atomic Safety and Licensing Board Panel 83/04/21 PAMLIK, E.T. Region 3, Office of Director 1p 18743 287 24X Fiche 30-454,83/06/21.8306230352

- 8306230355 Memorandum & order reopening recurd re alleged falsification of GA inspector records by Hatfield Electric Co Evidence should be presented on all pertinent investigations SHITH.I W Atomic Safety and Licensing Board Panel 83/06/21 5pp 18943 309 24% Fiche 50-454.83/06/21,8306230355
- 8304230362 Memorandum & order ruling on Joint Intervenors 830427 motion to allow J Hughes testimony on GA/GC issue Motion granted in part & denied in part Intervenors to present proposed statement of Hughes testimony by 830701.

 COLE.R F. SMITH, I W Atomic Safety and Licensing Board Panel.
 83/06/21 17pp 18744 100 24X Fiche 50-454.83/06/21.8306230362
- 8306270016 Reply to Dekalb Area Alliance for Responsible Energy/
 Sinnissippi Alliance for Environ proposed findings of fact & conclusions of law re water hammer Certificate of Svc encl
 QALLO, J. COPELAND, V O. Commonwealth Edison Co. QALLO, J. Isbam,
 Lincoln & Beale 83/06/21 lipp 19012 846 24X
 Fiche 50-454.83/06/21,8306270016
- --8306270020 Motion for leave to file out-of-time reply to proposed findings of fact & conclusions of law on weterhammer. Addl time needed due to demands imposed by preparation of other documents
 COPELAND.V G Commonwealth Edison Co COPELAND.V G Isham,
 Lincoln & Beale 83/06/21 Atomic Safety and Licensing Board
 Panel 2pp 17012 257 24X Fiche 50-454:83/06/21.8306270016
- 8306270032 Errata to ASLB 830621 memorandum & order ruling on intervenor motion to admit J Hughes testimony Date for intervenor to submit matter for ASLB consideration is 830707, not 830701 MDRAN, D M Atomic Safety and Licensing Board Panel 83/06/22, ip 18989 044 244 Fiche 50-454.83/06/22, 8306270032
- 8306270393 Advises that Dec 1783 current fuel load date for Unit I MILLER, M I Isham. Lincoln & Beale MILLER, M I Commonwealth Edison Co 83/06/22 BMITH, I W Atomic Safety and Licensing Board Panel Ip 18974 137 24X Fiche 50-454,83/06/22,8306270393
- 8306280528 Motion for extension until 830715 to reply to Dekalb Area Alliance for Responsible Energy/Simmissippi Alliance for Environ & Rockford League of Momen Voters proposed findings of fact & conclusions of law Certsficate of Svc encl COPELAND, V O Commonwealth Edison Co COPELAND, V O Isham, Lincoln & Beals 83/06/23 Atomic Safety and Licensing Board Panel App. 19019 262 24X Fiche 50-454.63/06/23.83(66280528
- 8306280535 Proposed findings of fact & conclusions of law re liquid pathway Certificate of Svc encl
 GALLO, J. FURSE.N C. Commonwealth Edison Co. GALLO, J. Isham,
 Lincoln & Beale 83/06/24, 39pp 17020 005 24X
 Fither 50-454, 83/06/24, 8306280535
- 8306290508 Informs of correct mobiling address for ASLB chairman MDRAN,D N Atomic Safety and Licensing Board Panel 83/06/27 J ,19052 195 24% Fithe S0-454,83/06/27,8306290508
- 8306300215 Motion for extension until 830701 to file remaining proposed findings of fact & conclusions of law for parties.
 THOMAS, D.C. League of Women Voters of Rackford, IL. THOMAB, D.C. Thomas, D.C. B3/06/29 Atomic 8afety and Licensing Board Panel 2pp 19122 099 24X Fichs 50-454,83/06/29.8306300215.
- J Insurance & indemnity information
- 8306130231 Forwards NELIA & MARLU Certificates N-93 & M-93, respectively, evidencing secondary financial protection for plant OSTEM. J. Commonwealth Edison Co. 83/06/03 SALTZMAN. J. Assistant Director for State & Licensee Relations 13pp 18826-311, 24X Fiche 50-454.83/06/03.8306130231
- 8306270345 Forwards Endorsement 7 to NELIA Policy NF-277
 OBTER.J Communucalth Edison Co 83/06/16 SALTZKAN.J Assistant
 Director for State & Licensee Relations 2pp 18993 133 24X
 Fiche 50-454.83706/16.8306270345
- K Utility Final Safety Analysis Report (FBAR) & amends
- 8306030272 Forwards Amend 42 to FBAR TRAHM.T R Commonwealth Edison Co 83/05/31 DENTON.H.R Office of Nuclear Reactor Regulation, Director App 18713 001 24X Fiche 50-000,83/05/31.8306030272
- --83060302B1 Amend 42 to FSAR * Commonwealth Edison Cp 83/05/31 583pp 18713:005, 24X Fiche 50-000,83/05/31,8306030272

- 8306210211 Forwards affidavit of distribution for FSAR. Amend 42 TRANH, T R Commonwealth Edison Co 83/06/14 DENTEN H R Office of Nuclear Reactor Regulation, Director 2pp 18918 117 24X Fiche 50-000,83/06/14,8306210211
- O Inspection reports, IE Bulletins & correspondence
- 8306100244 Forwards IE Insp Rept 50-454/83-17 & 50-455/83-14 on 830330-0504 & notice of violation. STREETER.J F Region 3, Office of Director 83/05/24 REED.C Commonwealth Edison Co 2pp 18807 139 24% Fiche 50-454,83/05/24,
- --8306100247 Notice of violation from inco on 830330-0504 BTREETER.JF Region 3. Office of Director 8305/24 2pp 18807 141 24X Fiche 50-454.83/05/24.8306100244
- --8306100249 IE Insp Repts 50-454/83-17 & 50-455/83-14 on 830330 0504 Noncompliance noted failure to perform adequate test procedure review & approval & failure to adequately implement program for maintaining cleanliness RINO.M A. REVES.L A. Region 3. Office of Director. 83/05/24 6pp 18807.143 24X Fiche 50-454.83/05/24.8306100244
- 8305110458 IE Info Natice 83-32, "Ruptured Am-241 Sources Contained in Well Logging Device" Svc list encl.
 TAYLOR, J M Division of Bafaguards & Inspection Programs (Post 830103), 83/05/26 Consolidated Edison Co of New York, Inc 125pp 18831 043 24x Fiche 50-000,83/05/26,8305110458
- 8305110460 IE Info Notice 83-34, "Event Notification Info Workshoot" 8vc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/05/26 Consolidated Edison Co. of New York, Inc. 115pp. 18732-085, 24X Fiche: 50-000, 83/05/26,8305110460
- 8306170359 Forwards IE Insp Repts 50-454/83-18 & 50-455/83-15 on B30301-0430 & notice of violation NORELIUS,C E Division of Project & Resident Programs 83/05/26 REED.C Commonwealth Edison Co 3pp 18680 071 24X Fichs, 50-454,83/05/26,8306170359.
- --8306170361 Notice of violation from insp on 830301-0430 NORELIUS.C C Division of Project & Resident Programs 83/05/26 2pp. 18880 074 24X Fiche 80-454,83/05/26,8306170359
- --8306170364 IE Insp Repts 50-454/83-18 & 50-455/83-15 on 830301-0430 Noncompliance noted operating personnel failed to observe control bands for RCS pressure & temp during preoperational testing & precaution re loose parts indication posted FORNEY, W., CONNAUGHTON, K., HAYES, D. W., Region 3. Office of Director 83/05/25 7pp 18880-076 24% Fiche 50-454,83/05/26,8306170357
- 8306170020 Forwards IE Insp Rept 50-454/83-17 on 830427-29 No noncompliance noted NORELIUB,C E Division of Project & Resident Programs 83/05/27 REED.C. Commonwealth Edison Co 2pp 18892 232 24X Fiche. 50-454,83/05/27,8306170020
- --8306170023 IE Insp Rept 50-454/83-19 on 830427-29 No noncompliance noted. Major areas inspected testing of pipe support & restraint sys

 ANO.N.P. JAPE.F. Region 2. Diffice of Director 63/05/16 5pp 18882.254. 24X Fiche 50-454.83/05/2/.8306170020
- B305110461 IE Info Natice B3-35, "Fuel Movement W/Control Rods Withdrawn at DWRs " Byo list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post B30103) B3/05/31 Consolidated Edison Co. of New York, Inc. 116pp 18732 208 24% Fiche 50-000, 83/05/31,8805110461
- 8306130341 Forwards IE Insp. Rept 50-454/83-16 on 830321-25 & 0404-08 & notice of violation.

 LITTLE, H. B. Region 3, Office of Director 83/05/31 REED, C.

 Commonwealth Edison Co. 2pp. 18822, 282 24X Fiche 50-454, 83/05/31, 8306130341
- --8308180343 Notice of violation from insp on 830321-25 & 0404-08 LITTLE, W. 8. Region 3, Office of Director, 83/05/27 ip 18822; 284 24X Fiche: 50-454, 83/05/31, 8306130341
- --8306130345 IE Insp Rept 50-454/83-16 on 830321-25 & 0404-08
 Noncompliance noted failure to assure that lead auditors
 performing Power-AZOO-Pope properly qualified & certified
 LOVE.R.S. WILLIAMS.C.C. Region 3. Office of Director 83/05/27
 11pp. 18822-285 24X Fiche 50-454.83/05/31,8306130341

- 8306070388 Ack receipt of 830516 ltr informing NRC of steps taken to correct violations noted in II Insp Repts 50-454/83 12 t 50-455/83 10 SPE65ARD.R L Region 3. Office of Director 83/06/01 RLFD,C Commonwealth Edison Co Ip 18/42 023 24X Fiche 50-454,83/06/01,8306070388
- --8306070392 Responds to NRC 830413 ltr re violations noted in il John Repts 50-484/83-12 & 50 455/83-10 Corrective actions FSAR to be changed to represent accurate design philosophy for RCS leak detection FARRAR.D L. Commonwealth Edison Co. 63/05/16 KEPPLER, J & Region 3, Office of Director 7pp. 18/42 024 24X Fiche 50-454.83/06/01.83060/0388
- 830.6230.385 Advises that requested cable tray stiffener weld suspensive criteria available in Amend 41 to FGAR.revised Page 3 10-6
 TRAMM.T R Commonwealth Edison Co. 33/06/02 KEPPLER.J Q Region,
 3. Office of Director 1p 18943 058 24X Fiche 50-454, G3/06/02, B306230385
- 9305110464 IE Info Notice 93-36, "Impact of Security Practices on 9sfe Operations " Syc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/09 Concolidated Edison Co. of New York, Inc. 119pp 18830 280 (44X Fiche 50-000,83/06/09.03001)0464
- 8306230285 Forwards IE Enforcement Conference Rept 50-454/83 23 on 830523 SPESSARD, R. L. Region 3, Office of Director 83/06/10 Rf.I-D. C Commonwealth Edison Co 2pp 18945 150 24X Fiche 50-454,83/06/10, 8306230285
- --8306230290 IE Enforcement Conference Rept 50-454/83-23 on 860523 Major areas discussed deficiencies identified in preoperational test program SPESSARD, R. L. Division of Engineering REYES, L. A., FORNEY, W. L. Region 3, Office of Director D3/06/09 App 18945 160 24x Fiche 50-454,83/06/10.83062/0285
- 8305110470 IE Info Notice 83-38, "Defective Heat Sink Adhesiv; & Seismically Induced Chatter in Relays Within Printed Circuit Cards " Svc list enc)
 JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co of New York, Inc 118pp 18920 225 24% Ficho 50-000,83/06/13,07051104/0
- 8304090010 IE Info Notice 83-3/. "Transformer Failure Resulting From Degraded Internal Connection Cables " Svc list and JURDAN E L Division of Language Preparedness & Engineering Response (Post 830103) 83/06/19 Consultated Edison Co of New York, Inc 243pp 18921 001 P4X Fiche 50-000,83/06/13,8306099010
- 830.6170.371 Forwards NRC 830531 ltr transmitting IE Insp Rept 30-454/83 i6 & notice of violation Rept supports intervenor position that util anuilling or unable to maintain offective QA/QC program Svc list enc!

 WHICHER.J M Businessmen for the Public Interest WHICHER.J M League of Women Voters of Rockford, IL WHICHER.J M Sinnissippi Alliance for the Environment (SAFE) 83/06/16 SMITH.I W .

 CALLAMAN.A D . COLE.R F Atomic Safety and Licensing Board Panyl 17pp 18880 294 24X Fiche b0-454.83/06/13.83061703/1
- 8306300178 Forwards 16 Insp Repts 50-454/83-21 & 50-455/83-16 on 830427 & 0502-03 & 10 No noncompliance noted KNOP.R C Region 3. Office of Director 83/06/16 REED.C Commonwealth Edison Co 2pp 19120 028 24X Fiche 50-454,83/06/16.8304300178
- --8306300184 IE Insp Repts 50-454/83-21 & 50-455/83 16 on 83042/ & 0502-03 & 10 No noncompliance noted Nojor areas inspected allegations re safety-related insp activities & electrical work HINDS, J M , HAYES, D W , KNOP, R C Region 3, Office of Director 83/06/16 12pp 19120 030 24X Fichs 50-454,83/06/16.0306300170
- B305110475 IE Info Notice B3-40, "Need to Environmentally Qualify
 Epoxy Grouts & Sealers " Svc list entl
 JDRDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post B30103) 83/06/22 Consolidated Edition Co
- 8305110477 IE Info Notice 83-41, "Actuation of Fire Suppression Sys-Causing Inoperability of Safety-Related Equipment "Syc list enc! JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/22 Consolidated Edison Co. of New York, Inc. 120pp 18997 007 24X Fishe 50-000,83/06/22.03051104/7

- 8305110477 IE Info Notice 83-42, "Reactor Mode Bortch MalAunctions"
 - 305110479 IE INTO MOCICE CE Byo list enil JORDAN,E L Division of Labruchcy Preparadness & Engineering Response (Post 830103) BJ/06/73 (Unsolidated Edison Co of New York, Inc. 116pp 18996 247 P4X Fiche 50-000,89/06/23,8305110479
- 83051:0483 IE Info Notice 83-43, "Improper Settings of Intermediate Range (IR) High flux Trip Setpoints "'Ave list end John St. Trip Setpoints "'Ave list end John St. Trip Setpoints "'Ave list end John St. Trip Setpoints "'Ave list end John Co. Bridgingering Response (Post B20103) BJ/06/24 Consolidated Edison Co. of New York. Int. 116pp 17046-29/ 24X Fisho 70-000.03706/24,8305110483
- S Reportable occumences. LLRs & related correspondence
- 8306030225 Interim Deficiency Rept 83-05 to preservice insp weld indications Initially reported on 830427 Disposition of weld indications to be finalized within 90 days of completion of hot functional testing scheduled for 33090 of completion of SHARTZ. E.D. Commonwealth Edison Co. 83/05/26 MEPPLER, J. G. Regio 3. Office of Director. 3pp. 18/03-280. 24X Fiche 50-454,83/05/26,8304030225
- 8306030229 Final Deficiency Rept 83.04 or structural steel connection rework design inadequacy initially reported on 830429 Jam nuts to be installed on sliding connections by 830803 & 840101 for Byron & 830725 & 1125 for Binaldwood SWARTZ, & D. Commingweith Editon Co. 93/05/26 REPPER, J. 9. Regio 3. Office of Director 2pp. 18/03-341 24X Fiche 50-000,83/05/26,8306030229
- 8306100178 Informs that final response to 881206 interim deficiency rept re failure of several 4c cables in underground duct, will be submitted in Sept 1903 instead of Apr 1983 TRAMM. TR Commanwealth Edison Co 03/06/01 KEPPLFR. J G Regio 3. Office of Director 1p 18806 019 24X Fiche 50-434.03/06/01, 8306100178
- 830&10023& Ihard Interim Deficiency Ropts 82-11 & 82-12 re accuracy of Barton electronic instrument transmitters Changes in allowable accuracy of transmitters being evaluated Final rept will be sent by 830831 TRAMM, T.R. Commonwealth Ldison (o. 33/06/01 KEPPLIR, J.G. Region 3, Office of Director ip 18805 311 24X Fiche 50 000.03/06/01. 3. Office of Director ip 8305100236
- B30610020/ Final Deficiency Rept 82-09 or mechanical slubber bracket interference No inspected annihors require redesign or repair lines & changes will be completed prior to fuel load TRAHM. T. K. Commonwealth Edison Co. 8:/06/02 KLPPLER. J. 6 Regio 3. Office of Director ip 18805-294 24% Fiche 50-000.03/06/02. 8306100207 Region
- 8306100246 Final deficiency rept re Westinghouse DB-416 reactor trip switchpaar design discrepancy Instally reported on 030504 Replacement undervoltage attachments will have modified, widened grooves to accompdate new retaining rings SWARTZ, C D Commonwealth Edwon Co B3/06/03 KEPPICR, J G Regio 3. Office of Director 3pp 10807 Obs 24X Fiche 50-000,03/06/03. B306100246
- 8306170045 Interim Deficiency Ript 83-0/ re reactor coolant pump IA Searing failure Instally reported on 0'30503 Defective pump IA bearing failure Instally reported on 0'30503 Defective pump internals returned to Westinghouse to determine cause of failure Damaged internals is placed final rept in 70 days SWARTZ.E D Commonwealth Edison Co 83/06/09 KFPPLER, J & Regio 3. Office of Director 3pp 10878 357 24X Fiche 50-454,83/06/09,8306170045
- B306270282 Potential Part 21 rept re discrepancy in welding of turnbuckle assembly, turnbuckle bolt interface & on top plate assembly variable springs SA(80) Grade B bolts not ABM.

 Bection 1X matl Investigation underway KARAGIANIS, J. A. Licen Metal Products Co. 83/06/17 KEPPLER, J. 0 Region 3. Office of Director 2pp. 18796-207 P4X

 Fiche 50 000, 83/06/17, 83062/0782
- T Hearing transcripts on non-antitrust matters
- B306010023 Transcript of B30526 hearing in Rockford. IL Pp 7.102-7.231 Supporting documentation encl.
 * Atomic Safety and Licensing Board Panel 83/05/26, 287pp 18668 P20 24X Ficho 50-454, 83/05/26, 8306010023.

- DOCKET BIN 50-455 BYRON STATION, UNIT 2
- A Application/construction stage documents & correspondence
- B306030417 Requests info re identification of safety-related mechanical equipment located in harsh environ areas including required operating times & plant location Info requested within 30 days of receipt of 1tr YOUNGILOOD B J Licemsing Bioneh 1 85/05/20 FARRAR, D L Commonwealth Edison Co 3pp 18/35 357 24% Fiche 50-000,83/05/20,
- B304010019 Summary of B30904 meeting w/util, Westinghouse, Bargent & Lundy & Energy, Inc. in Detherda, MD re design verification programs programs OLSHAN, L.N. Licembing Branch 1 83/05/23 Licensing Branch 1 4pp 18687 171 24% Fiche 50-454.83/05/23,8306010019
- 8306010031 Summary of 830913 meeting w/util, Westinghouse & Sargent & Lundy in Bethebda, MD re review of spismic qualification & yump & valve operability OLSMAN, L N Licensing Branch 1 03/05/23 Licensing Branch I 4pp 18687 170 24X Fiche 50-454, 89/05/23, 8306010031
- 8306030517 Board Notification 83-74 submits info re work stoppage on installation of new pipe whip restraints Stop work action related to deficiencies in applicant (AA program Work will resume when upgraded program in place NOVAK.TM Assistant Director for Licensing 83/05/23 Safety and Licensing Board Ponel App 18735 054 24X Fiche 50-454,63/05/23.8304030517 Atomic
- 8306090194 Discusses util interpretation of 10CFR30 49, "Environ Qualification of Electrical Equipment Important to Bafety for Nuclear Power Plants " Intent of rulemaking is to require upgrade program for replacement equipment not parts FARRAR,D.L. Commonwealth Edison Co. 80706/03 DENION,H R. D. of Nuclear Reactor Regulation, Director Dpp. 18796 090 24X Fichs 50-000,83/06/03.8306090194
- 8306200019 Summary of 830331 meeting w/utils & Westinghouse in Bethesda,ND re Wentinghouse analysis & evaluation of D4/D5/E steam generator mod HOPKINS.J B Licensing Brunch 4 83/06/14 Licensing Bra 22pp 18408 327 24X Fiche 50 000,83/06/14,8306200019 Licensina Branch 4
- 8306230237 Forwards add1 info re use of PORVs for venting & depressurizing RCB at facilities & response to FBAR Guestion 212 159, to be incorporated into future FSAR amend TRAMM T R Commonwealth Edison Co 83/06/16 DENTON, H R of Nuclear Reactor Regulation, Director 189p 18945 235 Fichs 50-000,84/06/16/8306230277
- 8306240379 Summary of Caseload Torecast Panel 830324-25 meetings w/util in Ogle County, II, re independent assessment of applicant fuel load date of 830831 Fuel load will not occur earlier than Nov 1983 ov 1783 ;L N Licensing Branch I 83/06/17 Licensing Branch I 18987 05:9 24% Fiche 50-454,83/06/17,8306240379
- 8305270322 Provides addl details re control of heavy loads during const when new fuel assemblies being stored in spent fuel pit Due to failure of reactor coolant pump at Byron I, fuel handling bldg crane will be installed

 TRAMM,T R Commonwealth Edison Co 83/06/17 DENTON,H R Office of Nuclear Reactor Repulation, Director ip 18994.073 24X

 Fichs 50-000,83/06/17,8306270322
- B306240252 Revises estimated fuel load dutes to Oct 1983 for LeBalle County & Dec 1983 & May 1988 for Hyron Units 1 k 2, respectively
 BTIEDE, H I Commonwealth Edison Co. BD/06/RI. DENTON, H R Offic of Nuclear Reactor Repulation, Director 1p 18781 323 24% Fichs 50 000,85/06/21.8306240252
- B306270373 Notifies of change in FSAR distribution All nuclear power plant activities transferred to new IL Dept of Nuclear Safety, State copy of FSAR amond should be sent to listed DENTON, H. R. D address Tramm, T R TRANM, T.R. Commonwealth Edison Co. 83/06/21. DENTON, H. of Nuclear Reactor Regulation, Director. 1p. 18993:313 Fiche 50-000, 83/06/21, 8306270373 Office
- 8306300032 Revises estimated fuel load dates, based on constractivity & preoperational testing budget review Fuel load scheduled for 831001, Dec 1983 & May 1985 for LaBalle County Unit 2 & Byron Units 1 & 2 respectively 871EDE.W L Commonwealth Edison Co 89/06/21 KEPPLER, J Q Region 3, Oppice of Director 1p 19120 311. 24X Fiche 50-000.83/06/21, 8306300032 Region

- E NRC Safety Evaluation Report (SFR), supple & correspondence
- 8306220001 Forwards addl info to seismit design basis for river screenhouse Review of info should help close Confirmatory Issue 1 of SER Values presented in FSAR are reasonable for matts underlying river screenhouse
 TRAMM, TR. Commonwealth Edison Co. 63/06/15 DENTON. H.R. Office of Nuclear Reactor Regulation, Director 15pp 18928-063 24X
 Fiche 50-454.83/06/15.8306/20001
- 8306270431 Forwards advance cupy of rev to Section E 17 of App E to FBAR Section describes safety parameter display sys Info should close SER Outstanding Item 16
 TRAMM, T R Commonwealth Edison Co 83/06/17 DENIGN, H R Office of Nuclear Reactor Regulation, Director 13pp 4/345 353 24X
 Fiche 50-000.83/06/17.8306270433
- 8306240070 Requests add1 info re moisture separators of heators in filter sys serving nonaccessible area & fuel handling bldg for SER review Info requested within 30 days to maintain review schedule
 YOUNGELOOD, B J Licensing Biench 1 63/06/21 FARRAR, D L
 Commonwealth Edison Co 3pp 18785 026 24X Fiche 50-000.83/06/21, 8306240070
- F Security, medical, emergency & fire protection plans
- B30A090247 Confirms B30A01 telron to changes to exercise windows for Dresden & Byron Nuclear Power Stations Dresden partial exercise will be conducted during wk of B30912 w/Byron full-scale exercise beginning wk of B31144

 JONES, E C Illinois, State of B3/06/01 KEPPLER, J Region 3, Office of Director ip 18/95 319 24X Fiche 50-000, B3/06/01, B30A09047
- 8304090221 Forwards current versions of all prefire plans, per requirements of 10CFR50.App N.Paragraph 3 K 12 Plans will be continually revised & future revs will not be formally submitted unless specifically requested TRAMM.7 R Commonwealth Edison Co DX/06/02 DENION, H R Office of Nuclear Reactor Regulation. Director 1p 18794-119 24X Ficha 50-494,83/06/02.8304090221
- ~~8306090223 Prefire plans * Commonwealth Edison Co 83/05/18 113pp 18796 120 24X Fiche 50~454,83/06/02,8306090281
- 8306160214 Submits correction to B30601 ltr Date of reassessment will be made prior to B30801 not 031001

 JONES, E E 11linois, State of B3/06/09 KEPPLEK, J. Region S. Office of Birector 1p 18861 358 24X Fiche 50-000, B3/06/09. 8306160214
- 8306230287 Forwards add1 info on communications & cable spreading room suppression sys to fire protection program Third radio communication channel being installed Reprater will be located in turbine bldg
 TRAMM.T R Commonwealth Edison Co. 33/06/17. DENTON.H R. Office of Nuclear Reactor Regulation. Director 5pp. 18745-016 24X
 Fiche 50-000.63/06/17.8306230257
- 8306230412 Provides add1 info requested in NRC 830411 ltr reinstrumentation used to assure safe shutdown in event of fire Info will be incorporated into FSAR & fire protection rept in future amends
 TRAMM.TR Commonwealth Edison to 83/06/1/ DENTON.HR Office of Nuclear Reactor Regulation, Director 52pp 18943 136 24X
 Fiche 50-000,83/06/17/8306230412

O Adjudicatory correspondence

- G304010457 Forwards marked-up Joint Intervenor Exhibit 14 re
 radiological smergency response survey Ambulance medical
 svcs.indicating stricken portions per ASLD G30426 ruling
 encl Certificate of Svc encl.
 GOFELAND, V G. Lisham, Lincoln & Beale COPELAND, V G. Commonwealth
 Edison Co. G3/05/26, SMITH.I W. COLE, R F., CALLIHAN, A D. Atomic
 Gafety and Licensing Board Panel R4pp 18674-328 24X
 Fiche: 50-454, 83/05/26, 8306010457
- B306020437 Forwards Rockford League of Homen Voters proposed findings of fact & conclusions of law re Contention 104 on seismalogy, per B20818 stipulation THOMAD.D.C Illinois Institute of Technology B3/05/31 SHITH.I W. COLE.R F. CALLIHAN.D Atomic Safety and Licensing Board Panel. 12pp 18693 228 24X Fiche 50-454.83/05/31.8306020437.

- 8306060193 Forwards proposed findings of fact & continsions of low research of the seismology, water hammer & ALARA Final agreement not reached re-procedural history COPELAND, V @ Isham, Lincoln & Beale COPELAND, V @ Commonwealth Edison Co 83/05/31 SMITH, I W . COLC.R F . CALLIHAN.A D Atomic 84fety and Licensing Board Panel 2pp 18718 261 24x Fiche 50-454, 83/05/31, 8304060193
- --8306060196 Proposed findings of fact & conclusions of law ro seismology, water hammer & ALARA MILLER, M I , BIELAWSKI, A P , COPELAND, V & Commonwealth & dison Co 83/05/31 104pp 18718 PA3 24X Fiche 50-454,83/05/31, 8306060193
- B3060B0143 Forwards proposed findings of fact & conclusions of lew on Contention 9a re water hammer CHAVEZ.D Einnissippi Alliance for the Environment (BAPE) CHAVEZ.D DeKalb Area Alliance for Responsible Energy B3/05/M Atomic Safety and Licensing Board Panel lp 18772 290 P4X Fiche 50-454.B3/05/31.B3040B0143
- --8306080145 Proposed findings of fact % conclusions of law on Contention % re water hammer * Simmissippi Alliance for the Environment (SAFE) * DPKulb Arta Alliance for Responsible Energy 83/05/31 19pp 18772 291 24t Fiche 50-454,83/05/31,8306080143
- 8306060286 Requests delay of plant licensing & operation until design.

 GA. waste disposal & emergency procedure problems resolved

 PULIDD. M Affiliation Unknown 83/06/03 SMITH, I W Atomic Safet,
 and Licensing Board Panel 1p 18/27 C38 24X

 Fiche 50-454, 83/06/03.830606286
- 8306060302 Complaint filed in Circuit Court of Beventeenth Judicial Circuit, Winnebago County, IL requesting imposition of punitive damages for wrongful diversion of waste water ento plaintiff property
 FEARER, W P Motor Oils Refining Co FEARER, W P Fearer & Nye 837066/03 Illinois, State of Spp 18729 097 24X
 Fiche 50-454,83/06/03,8306060302
- B306090342 Supplementary memorandum opposing intervenor motion to reopen record Neither triable issue nor significant safety issue exists re Huphes allogations Contificate of Svc encl BECKER, B D Commonwealth Edison Co B3/06/07 Atomic Befety and Licensing Board Panel 12pp 18794 322 24X Fiche 50-454,83/06/07,8306990342
- B306100201 Brief supporting motion to admit J Hughes testimony Intervenors have raised serious & significant safety issues re quality of work at plant Hughes testimony should be considered in ruling on Contention iA W/Certificate of Bvc WHICHER.J M League of Women Voters of Rockford, IL WHICHER.J M DeMalb Area Alliance for Responsible Energy WHICHER.J.M Sinnissippi Alliance for the Environment (BAFE) 83/06/07 Atomic Safety and Licensing Board Panel 21pp 18805 230, 24% Fiche 50-454,83/06/07,8306100201
- B306130445 Forwards proposed findings of fact & conclusions of law resteam generator tube integrity Document should be filed w/B3031 proposed findings resembling, water hammer & ALARA OCLDFEIN. MR Isham, Lincoln & Beale GDLDFEIN. MR Commonwealth Edison Co B3/06/07 SMITH. I W. COLE. RF. CALLINAN. A D Atomic Bafety and Licensing Board Panel 2pp 18820 319 24X Fiche 50-494, 83/06/20. 8306130445
- --8306130452 Proposed findings of fact & conclusions of law re stram generator tube integrity Cortificate of Svc encl
- GALCOLOGUE PROPOSED FINGINGS OF Pact & Conclusions of law re stram generator tube integrity Corntificate of Svc oncl GALLOLJ, GOLDFEIN M R. Commonwealth Edison Co., GALLOLJ, Isham. Lincoln & Beale 83/06/07 64pp 18820 321 24X Fiche 50-454.63/06/07,8306130445

 GSO6130402 Informs that radiological emergency exercise moved to what SE Hisham Commonwealth in the common of the second of the second
- 8306i30402 Informs that radiological emergency exercise moved to we of 831i14 to accompdate Illinois Emergency Sycs & Disaster Agency Syv list encl BIELAMBKI.A P Isham. Lincoln & Beale BIELAMBKI.A P Commonwealth Edison Co 83/06/07 SMITH.I W . COLT.R F . CALLIHAN.A B Atomic Safety and Licensing Board Panel Spp. 18847 129 24X Fiche 50-454,83/06/07.8306150402
- 8304i30420 Forwards motion for & amend to consolidate Details Area Alliance for Responsible Energy/Binnissippi Alliance for Environ Contention 3 w/Rockford League of Women Voters Contentions 19 & 109
 BIELAMBKI.A P Isham, Lincoln & Beale, BIELAWSKI.A P Commonwealth
 Edison Co 83/06/07 Office of the Secretary of the Commission
 2pp 18847 095 24X Fiche 50-404,83/06/07,8306150420.

- --8304150406 Notion to amend % consolidate behalb Area Alliance for Responsible Livergy/Sinnissippi Alliance for Environ Contention 3 w/Rockford Leanue of Hemin Vaters Contentions 19 & 108
 CMAYEZ, D. DeKalb Area Alliance for Responsible Energy (HAVEZ, D. Sinnissippi Alliance for the Environment (SAFE) MORRISON, P. League of Conen Vaters of Rockford, 11 83/02/21 Atomic Safet and Licensing Board Panel App. 1/847-097 24X
 Fiche 50-454-83/06/07,8306150420
- --8304150442 Amend & consolidation of Dekalb Area Alliance for Responsible Intergy/Sinniverpsi Alliance for Environ Contention 3 & Rockford League of Women Voters Contentions 19 & 108 CNAVEZ, D. DeKalb Area Alliance for Responsible Energy CHAVEZ, D. Sinnissippi Alliance for the Environment (SAFE). MORRISON, 3. League of Women Voters of Rockford, 11 83/02/21 Atomic Gafety and Licensing Board Panel. Opp. 13047 101 249 Fiche 50 454,03/06/07,830619420
- 8306150408 Notifies that pending review of NRC-commissioned study of corrent sabotage problems at nuclear gover plants. Intervenor may move to reopen evidentiary second to consider rangifications of study Svc list cm.)

 THOMAS. D. (Illinois Institute of Technology THOMAS. D.C. Affiliation Unknown 83/06/07 SMITH. J.W., COLE, R.F., CALLHAN, D. Atomic Bafety and Licensing Buard Panel Jap. 18847-118 PAX Ficho 50-454,83/06/09.8304150408
- 8306200300 Reply apposing Rockford Leagur of Wamen Voters proposed findings of fact & conclusions of law 10 sersmalogy Certificate of Svc encl OCLDFEIN.M R Commonwealth I dison Co GCLDFEIN.M R Isham, Lincol & Beale 83/06/09 10pp 18900 176 24X Fiche 50-454.83/06/09, 8706200300
- 8306200304 Forwards util reply to Rockford League of Momen Voters proposed findings of fact & conclusions of law re solsmology Rolated correspondence W/o (nc) COPELAND.V C Commonwealth COPELAND.V C Islam, Lincoln & Beale COPELAND.V C Commonwealth Edison Co 83/06/07 SMITH. W. (OLL K.F. CALL)HAN.A D Atomic Safety and Licensing Board Panel 2pp 18700-170 24X Fiche 50-454,83/06/07.8306/00X04
- 8304(3036) Proposed findings of fact & conclusions of law in form of partial initial docusion on seismologu & water hammer issues Cortificate of Svc ent. |
 GULDBERG, S.C. Hearing Branch 4 BY/06/10 39pp 18822 114 24X
 Fiche 50-454.8 //06/10, 8306130361
- 83061703/1 forwards NRC 830501 ltr transmitting IE lusp Rept 50-454/83-16 & notice of violation Rept supports intervenol position that util unwilling or unable to maintain effective 84/8C program Svc list onel WHICHER.J M Lusinessmen for the Public Interest WHICHER.J M Lusque of Women Voters of Rockford, II WHICHER.J M Sinnissippi Alliance for the Environment (BACE) 83/06/16 SMITH.I W. CALLAHAN.A D. COLE.R F. Atomic Safety and Licensing Board Penel 17pp 18880 244 24% Fiche 10 454,81/06/13,83041/9771
- 0304150310 Proposed findings of fart & conclusions of law in form of supplemental partial initial decision on occupational radiation safety & steam generator issues Certificate of Svc encl 00LDBERG, 9 C Hearing Branch 4 RAWSUN, R J Hearing Branch 3 03704714 120pp 18848 328 247 Fichs 50-454,8370474,8306150318
- G304170378 Advises that NRC will not reply to party B30607 supplemental brings re intervenor B30427 mution to reopen record NRC position already matter of record OCLBBERG.S C Hearing Branch 4 83/06/14 SHITH.I W. COLF.R F. CALLIMAN,A D. Atomic Bafety and Licensing Board Panel 2pp 18880 248 24X Fiche 50-454,83/06/14.8306170378
- B306200320 Proposed findings of fact & conclusions of law re ALARA & steam generator tube integraty
 THOMAS, D.C. League of Women Voters of Rockford, IL. THOMAS, D.C. Thomas, D.C. 63/06/14 3Ppp 18099 173 24X Fiche 50-454, 83/06/14,8306200370
- --8306200327 Mation for extension until 800628 to file proposed findings of fact & conclusions of law re Contentions 22 & 9(c)
 THOMAS.D C League of Women Voters of Rockford, IL. THOMAS.D C
 DeKalb Area Alliance for Responsible Energy THOMAS.D C
 Simulssippi Alliance for the Environment (SATE) 83/06/14
 Atomic Safety and Licensing Board Panel ip 18897 205 24X
 Fiche 50-454,03/06/14.8306200370

- --830A2003'll Affidavit of DC Thomas supporting extension until 830A28 to file proposed findings of Pact & conclusions of law re Contentions 22 & 9(c) Time needed due to heavy trial & teaching schedule Certificate of Svc ent)
 THOMAS.D C League of Women Voters of Rockford, IL THOMAS.D C Dekalb Area Alliance for Responsible Energy THOMAS.D C Simissippi Alliance for the Environment (SAFE) 83/06/14 3pp 1899 206 24X Fiche 50-454.83/06/14.830A200320
- 8306200350 Forwards 830406 memorandum & unexecuted stipulations re emergency planning contentions CDPELAND.V 9 Isham Lincoln & Beale COPELAND.V 9 Commonwealth Edison Co 83706/14 Docketing & Services Branch 47pp 18900 274 24X Fiche SO-454.83/06/14.8306200350
- 8304200294 Certification to Commission of ASLB recommendation that Commission confer continuing jurisdiction to ASLB or clarify ASLB has jurisdiction to resolve specified emergency planning disputes after decision authorizing operation CALLIHAN.D. COLE.R F. SMITH.I W. Atomic Safety and Licensing Board Panel 83/06/17 21pp 18948 008 24X Fiche 50-454,83/06/17.
- 8306210281 Proposed findings of fact & conclusions of law in form of supplemental partial initial decision on emergency planning issues Certificate of Svc encl OCLDBERG.S C. Hearing Branch 4 63/06/20 63pp 18714 310 24X Fiche 50-454,83/06/20,8306210281
- 8306270022 Findings of fact & conclusions of law re emergency planning * DeKaib Area Alliance for Responsible Energy * Sinnissippi Alliance for the Environment (SAFE) * League of Women Voters of Rockford, IL 83706/20 67pp 19012 259 24X Fiche 50-454,83706/20,8306270022
- 8306270041 Proposed findings of fact & conclusions of law re emergency planning Certificate of Svc and HILLER.M I. BIELAWSKI, A.P. COPELAND.V Q Commonwealth Edison Co 83/06/20 53pp 19012 326 24X Fiche 50-454.83/06/20.8306270041
- 8306270383 Forwards util proposed findings of fact & conclusions of law re emergency planning, to be incorporated w/830531 & 0607 submittals W/o encl
 COPELAND.V G Isban. Lincoln & Beale COPELAND.V G Communuealth Edison Co 83/06/20 SMITH, I W. COLL.R F. CALLIHAN.A D Atomic Safety and Licensing Board Panel 1p 18973 165 24X Fiche 50-454,83/06/20.8306270383
- 6305230352 Requests cooperation of Oft of Investigations in reopened hearing, in particular, by releasing pertinent Oft of Investigations documents, insprepts & hearing testimony SMITH, I H Atomic Safety and Licensing Board Panel E3/05/21 PANLIK, ET Region 3, Office of Director ip 18943 287 24X Fiche 50-434,83/05/21,8306230352
- 8306230355 Memorandum & order reopening record re alleged falsification of QA inspector records by Matfield Electric Co Evidence should be presented on all pertinent investigations SMITH, I W Atomic Safety and Licensing Board Panel 83/06/21 5pp 18943 309 24X Fiche SO-454.83/06/21.8306230355
- 8306230362 Memorandum & order ruling on Joint Intervenors 830427 motion to allow J Hughes testimony on GA/QC issue Mation granted in part & denied in part Intervenors to present proposed statement of Hughes testimony by 830701 COLE, R F , SMITH. I W Atomic Safety and Cicensing Board Ponel 83/06/21 19pp. 18944 100 24X Ficho 50-454,83/06/21.8306230362
- 8306270016 Reply to Dekalb Area Alliance for Responsible Energy/ Sinnissippi Alliance for Environ proposed findings of fact & conclusions of law re water hammer Certificate of Svc encl. QALLO, J. COPELAND, V © Commonwealth Edison Co GALLO, J Isham Lincoln & Beale 83/06/21 lipp 17012 246 24% Fiche 50-454,83/06/21.8306270016
- --8306270020 Notion for leave to file out-of-time reply to proposed findings of fact & conclusions of law on waterhammer Addl time needed due to demands imposed by preparation of other documents COPELAND, V O Communusalth Edison Co COPELAND, V O Isham, Lincoln & Boale 83/06/21 Atomic Safety and Licensing Board Panel 2pp 17012 257 24X Fiche 50-454,83/06/21,8306270016
- 8304270032 Errate to ASLB 830421 memorandum & order ruling on intervenor motion to admit J Hughes testimony Date for intervenor to submit matter for ASLB consideration is 830707, not 830701 MORAN, D.M. Atomic Safety and Licensing Board Panel. 83/06/22 1: 18788-064 24X Fiche 50-454,83/06/22,8306270032

- 8306270393 Advises that Dec 1900 current fuel load date for Unit I MILLER, M l Isham, Lincoln & Beale MilleR, M I Commonwealth Edison Co 83/06/22 SMITH, I M Atomic Safety and Licensing Board Panel 1p 18994 137 24% Fische 50-454,83/06/22,83062/0393
- 8306280528 Motion for extension until BD0/15 to ruply to Dekolb Area Alliance for Responsible Energy/Simmissippi Alliance for Environ & Rockford League of Homen Voters proposed findings of fact & conclusions of law Certificate of Bvc enc) COPELAND, V G Commonwealth Edison Co COPELAND, V G Isham, Lincoln & Beale 83/06/23 Atomic Safety and Licensing Beard Panel 4pp 19019 262 24X Fiche 50-454,83/06/23,0306280528
- 8304280535 Proposed findings of fact & conclusions of law re liquid pathway Certificate of Svc encl
 OALLO.J., FURSE.M C Commonwealth Edison Co GALLN.J Isham,
 Lincoln & Beale 83/04/24 37pp 17020 005 24X
 Fiche 50-454.83/04/24.8306280535
- #30629050B Informs of correct mailing address for AGLB chairman MORAN,D N Atomic Safety and Licensing Board Panel #3/06/27 ip 19052 185 24% Fiche 50-454,83/06/27,830629050B
- 8306300215 Motion for extension until 830701 to file remaining proposed findings of fact & conclusions of law for parties THOMAB.D C League of Women Voters of Rockford. It THOMAB.D C Thomas.D C 8306629 Atomic Safety and Licensing Board Panel 2pp 19122 099 24X Ficher 50~484.83/06/29,8306300215
- J Insurance & indemnity information
- 8306270345 Forwards Endorsement 7 to NELIA Policy NF-277 OSTER.J Commonwealth Edison Co 83/06/16 SALTZMAN.J Assistant Director for State & Licenses Relations 2pp 10993 133 14X Fiche 50-454.83/06/16.8306270345
- K Utility Final Bafety Analysis Report (FBAR) & amends
- 8306030272 Forwards Amend 42 to FSAR
 TRAMM.T R Commonwealth Edison Co 83/05/31 DENTON.H R Office
 of Nuclear Reactor Regulation, Director App 18/13 001 P4X
 Fiche 50-000,03/05/31,830603027/2
- --83060302B1 Amend 42 to FBAR * Commonwealth Edison Co 83/05/31 583pp 18713 005 24X Fiche 50-000, 83/05/31, 83366/302/72
- 8306210211 Forwards affidavit of distribution for FGAR.Amend 42 TRAMM.T.R. Commonwealth Edison Co. 83/06/14 DENTON, H.R. Defice of Nuclear Reactor Regulation, Director 2pp 18918-117 24y Fiche 50-000.83/06/14.8306210211
- G Inspection reports, IE Bulletins & correspondence
- 8306100244 Forwards IE Insp Rept 50-454/D3-17 & 50-455/B3-14 on 830330-0504 & notice of violation STRETER, J F Region 3, Office of Director 83/05/24 RCED, C Commonwealth Edison Co 2pp 18807 139 24X Fiche 50-454, 83/05/24, 8306100244
- --8306100247 Notice of Violation from insp on 830330-0504 BTREETER, J.F. Region 3. Office of Director 83/05/24 Ppp 18807 141 24X Fichs 50-484,83/05/24,8306100244
- --8306100249 IE Insp Repts 80-454/83-17 & 50-455/83-14 on 830030-0504 Noncompliance noted failure to perform adequate test procedure review & approval & failure to adequately implement program for maintaining cleanliness RING.M A , REYES.L A Region 3, Office of Director 83/05/24 6pp 18807:143. 24% Fiche 50-454.83/05/24,8306100244
- 8305110488 IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in Well Logging Device" Syr list encl TAYLOR: JM, Division of Safeguards & Inspection Programs (Post 830103), 83/05/26 Consolidated Edison Co of New York, Inc 125pp 18831 043. 24X Fichs:50-000,83/05/26,8305110450
- 8305110460 IE Info Notice 83-34, "Event Notification Info Worksheet"
 Syc list encl
 JORDAN, EL Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/05/26 Consolidated Edison Co. of New
 York, Inc. 115pp 18732 085, 24% Fiche 50-000,83/05/26,8305110460
- 8306170359 Forwards IE Insp. Rept. 50-454/83-18 & 50-455/83-15 on 830301-0430 & notice of violation. MORELIUS, C. E. Division of Project & Resident Programs 83/05/86 REED. Commonwealth Edison Co. 3pp. 18980 071. P4X Fiche 50-454,83/05/26.8306170359

- --8306170361 Notice of violation from insp an 830301-0430 NORECIUS, C.C. Division of Project & Resident Programs 03/05/26 22p 16880 074 24x Fiche 50-454, 83/05/26 8306170.59
- --8305170364 1E Insp Repts 30-454/83-18 & 50-455/83-15 on 830501-04'10 Noncompliance noted operating personnel failed to observe control bands for RCS pressure & temp during preoperational testing & precaution re loose parts indication posted FORNEY, B. CONNAUGHTON, K., HAYEG, D. W. Region 3, Office of Director 83/05/25 7pp 18800 076 24X Fiche 50-454.63/05//6, 8306170399
- 8305110461 1E Info Notice 83-35, "Fuel Movement W/Control Rods, Withdrawn at BWRs " Svc list cncl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/31 Consolidated Edison Co. of New York, Inc. 116pp 18732 200 24X Fiche 50-000.83/05/31.8309310451
- 8306070388 Ack receipt of 830516 ltr informing NRC of steps taken to correct violations noted in IC Insp Repts 50-454/83-12 & 30-455/89-10.

 SPESSARD, R L Region 3, Office of Director 83/06/01 RCED, Commonwealth Edison Co ip 10/42 023 24X Fiche 50-454,83/06/01.
- --8306070392 Responds to NRC 830413 ltr re violations noted in II lusp Repts 50-454/83 12 & 50-455/83-10 Corrective actions F5AR to be changed to represent accurate design philosophy for R(R lesk detection FARRAR, D L Commonwealth Edison Co 83/05/16 KEPPLER, J & Region 3, Dffice of Director 7pp 18742 024 24X Fichs 50-454,83706/01.8306070388
- 8306230385 Advises that requested cable tray stiffener weld insperitoria available in Amend 41 to FSAR, revised Page 3 10-6
 TRAMM T R Commonwealth Edison Co. 83/06/02 KEPPLER, J G Region
 3. Office of Director ip 18743 058 24X Fiche 50-454,83/06/02,
 8306230385
- 8305110464 IE Info Notice 83-36, "Impact of Security Practices on Safe Operations " Svt list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) B3/06/09 Consolidated Edison Co. of New York, Inc. 119pp 18830 280 24X Fiche 50-000,83/06/09,8305110464
- B305110470 IE Imfo Notice B3-38, "Defective Heat Bink Adhesive & Seismically Induced Chatter in Relays Within Printed Circuit Cards "Syc list one!

 JORDANIE L Division of Emergency Preparedness & Engineering Response (Post 830103) B3706/13 (onsolidated Edison Co of New York, Inc. 118pp 18920 225 24X Fiche 50-000,83706/13,0305110470
- 8306170371 Forwards NRC 830531 ltr transmitting IE lnsp Rept 50-454/83-16 % notice of violation Rept supports intervenor position that util unwilling or unable to maintain effective GA/QC program Svc list encl HHICHER.JM Businessmen for the Public Interest HHICHER.JM DeKalb Area Alliance for Responsible Energy 83/06/16 9MI1H.IH Atomic Safety and Licensing Board Panel 17pp 18890 274 24X Fiche 50-454,83/06/13,8306170371
- 8306300178 Forwards IE Insp Repts 50-454/83-21 & 50-455/83-16 on 830427 & 0502-03 & 10 No noncompliance noted KNOP, R C Region 3. Office of Directon 83/06/16 REED. C Commonwealth Edison Co 2pp 19120/026 24X Fiche 50-454,83/06/16-8306300178
- --8306300184 IE Insp Repts 50-454/83-21 & 50-455/83-16 on 830427 & 0502-03 & 10 No noncompliance noted Major areas inspected. allegations re-safety-related inspectivities & electrical work
 HINDS.J M. HAYES.D W. KNOP.R C. Region 3, Office of Director 83/06/16 12pp 19120 030 24X firhs.50-434,83/06/16,8306300170
- 8304090010 IE Info Notice 83-37. "Transformer Failure Resulting from Degraded Internal Connection Cables " Svc list and JORDAN,E L. Davision of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co. of New York, Inc. 243pp 18921 001 24X Fiche 50-000,83/04/19,8306090010
- 8305110475 IE Info Notice 83-40, "Need to Environmentally Gualify
 Epoxy Grouts & Sealers " Gvc list encl
 JORDAN, E. L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/06/22 Consolidated Edison Co. of New
 York, Inc. 115pp 19021 179 24X Fiche 50-000,83/06/22,83051104/5
- 8305110477 IE Info Notice 83-41. "Actuation of Fire Suppression Sys Causing Imperability of Bafety-Related Equipment " Syc list and! JURDAN, E. L. Division of Emergency Prevaredness & Engineering Response (Post 830103) 83/06/22 Consolidated Edison Co. of New York, Inc. 120pp 18997 007 24X Fichs 50-000,83/06/22,8308110477

- 9305110479 IE Info Notice 83-42, "Reactor Mode Switch Malfunctions " Svc list encl JORDAN, E. Division of Emergency Preparadness & Engineering Response (Post 830103) 83/06/23 Consolidated Edison Co. of New York, Inc. 114
- 8305110483 IE Info Notice 83-43, "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints " Svc list onel JORBAN.E L. Division of Emergency Preparadness & Engineering Response (Post 830103) 83/06/24 Consolidated Edison Co. of New York, Inc. 114pp 19046 297 24X Fishe 50-000,83/06/24,8305110483
- S Reportable occurrences. LLRs & related correspondence
- 9306030229 Final Deficiency Rept 83-04 re structural steel connection rework design inadequacy Initially reported on 830429 Jam nuts to be installed on sliding connections by 830801 & 840101 for Byron & 830725 & 1125 for Braidwood SWART/LE D Commonwealth Edison Co 83/05/26 KEPPLER, J & Region 3, Office of Director 2pp 18703 341 24% Fiche 50-000.83/05/26.8306030229
- P30610017B Informs that final response to BP1206 interim deficiency rept re failuse of several dc cables in underground duct, will be submitted in Sept 1980 instead of Apr 1980 TRANN.T R Commonwealth Edison Co B3/06/01 KEPPLER.J G Region 3. Office of Director 1p 18806 017 24X Fiche 50 494,83/06/01.
- 8304100236 Third Interim Deficiency Repts 82-11 & 82-12 re accuracy of Darton electronic instrument transmitters Changes in allowable accuracy of transmitters being evaluated Final rept will be sent by 830831 TRAMM.T R Commonwealth Edison Co 83/06/01 KEPPLER.J G Region 3. Office of Director 1p 16905 311 24X Fichs 50-000.83/06/01.
- 8306100207 Final Deficiency Rept 82-09 re mechanical snubber bracket interference. No inspected snubbers require redesign or repair Insps & thanges will be completed prior to fuel load TRAMF, T R Commonwealth Edison Co 03/06/02 KEPPLER, J & Region 3, Office of Director 1p 18805 294 24X Ficho 50 000,83/06/02,8306100207
- 8308100246 final deficiency rept re Westinghouse DS-416 reactor trip switchgear design discrepancy Initially reported on 830504 Replacement undervoltage attachments will have modified, widened grooves to accomplate new retaining rings SWARTZ, C.D. Commonwealth Edison Co. 03/08/03 KEPPLER, J.G. Region 3, Office of Director 3pp. 18807-088 PAX Fiche 50-000,83/08/03/6308
- 8306170045 Interim Deficiency Rept 83-07 re reactor coolant pump iA bearing fatiure Instially reported on 830503 Defective pump internals returned to Westinghouse to determine cause of failure Damaged Internals replaced Final rept in 90 days SMARTZ.E D Commonwealth Edison Co 83/06/09 KEPPLER.J & Region 3, OPFice of Director 3pp 10878 359 24X Fiche 80-454.83/06/09, 8306170045
- 8306270282 Potential Part 21 rept re discrepancy in welding of turnbuckle assembly, turnbuckle-bolt interface & on top plate assembly variable springs SA307 Grade B bolts not ASME Section JX math Investigation underway KARADIANIS.J A Eleen Metal Products Co 83/06/17 KEPPLER.J G Region 3. Office of Director 2pp 10976 207 24X Fiche 50-000.83/06/17.8306270082
- T Hearing transcripts on non-antitrust matters
- 8306010023 Transcript of 830526 hearing in Rockford, IL Pp 7,102-7,231 Supporting documentation encl * Atomic Safety and Licensing Board Panel 83/05/26 287pp 18668; 220 24% Fiche 50-454,83/05/26,8306010023
- DOCKET STN-50-456 BRAIDWOOD STATION, UNIT 1
- A Application/construction stage documents & correspondence
- 8304030417 Requests info re identification of safety-related mechanical equipment located in harsh environ areas, including required operating times & plant location info requested within 30 days of receipt of itr YOUNGBLOOD, B. J. Licensing Branch 1 83/05/20 FARRAR, D. L. Commonwealth Edison Co. 3pp 18735-357 24% Fiche 50-000, 83/05/20, 8306030417.

- 8306030066 Ack participation in B30503-05 environ site visit Expertise on aquatic biological resources will be particularly valuable as input to environ review youNODLOOD, B. J. Licensing Branch I B3/05/23 BERTRAND, B.A. YOUNOBLOOD, B.J. Licensing Branch I B3/05/23 BERTRAND, B.A. B306030066
- 8306030237 Forwards request for add1 info re application for BL covering pipe line locations & frequency of munitions shipments FEAR should be amended to include requested info Response required by 830715 YOUNGDLOOD, B J Licensing Branch 1 83/05/24 FARRAR, D L. Commonwealth Edison Co Spp 18734 016 24X Fiche 50-456, 83/05/24, 8306030237
- 8306090194 Discusses util interpretation of MCFRSO 49. "Environ Qualification of Electrical Equipment Important to Bafety for Nuclear Power Plants" intent of rulemaking is required program for replacement equipment not parts FARRAR, D.L. Commonwealth Edison Co. 83/06/03 DENTON, H.R. Office of Nuclear Reactor Regulation, Director 3pp 18/96 090 24X Fiche 50-000,83/06/03.8306090194
- 830&140161 Submits list of endangered species present in proposed const site, in response to B30503 ltr Indiana bat utilizes steam corridors for foraging in summer Bald eagle found in Mill County furing winter No critical habitat designated OROUTAGE,T M Interior, Dept of Fish & Wildlife Service 83/06/09 YOUNGILCODD BJ Division of Licensing. 2pp 18839-071 24X Fiche 50-456,83/06/09,8306140161
- 8306200019 Summary of 830331 meeting w/utils & Westinghouse in Bethesda.MD re Westinghouse analysis & evaluation of D4/D5/E steam generator mod HOPKINS, J B Licensing Branch 4 B3/06/14 Licensing Branch 4 22pp 18908 327 24X Ficher50-000,83/06/14,8306200019
- 8306200069 Responds to 830414 memo requesting decision under NRC standardization policy re need to perform review of operation QA program Review of plant should be consistent w/stanfardized review
 THOMAS, C O Standardization & Special Projects Branch 83/06/14
 HAASS, W P Quality Assurance 1p 18908 173, 24X
 Fiche 50-456,03/06/14,8306200069
- 8306230237 Forwards add1 info re use of PDRVs for venting & depressuriting RCB at facilities & response to FBAR Question 212 159, to be incorporated into future FSAR smend TRAMM, TR Commonwealth Edison Co. 83/06/16. DENTON, H R. of Nuclear Reactor Regulation, Director 18pp 18945 235 24X Fiche 50-000,83/06/16.8306230237
- 8306230294 Forwards addI FSAR info re Question 423 40 concerning suction conditions for essential svc water pumps FSAR will be amended to include info contained in encl.

 BWARTZ, E D Commonwealth Edison Co 83/06/17 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp. 18945 167 24X Fiche 50-456,83/06/17,8306230294
- 8306270322 Provides additetails recontrol of heavy loads during const when new fuel assemblies being stored in spent fuel pit. Due to failure of reactor coolant pump at Byron 1, fuel hendling bidg crane will be installed TRAHM.TR. Commonwealth Edison Co. 83/06/17 DENTON.H.R. Office of Nuclear Reactor Regulation. Director. 1p. 18994-073 24X Fiche 50-000.83/06/17.8306270322
- 8306270373 Notifies of change in FSAR distribution All nuclear power plant activities transferred to new IL Dept of Nuclear Safety State copy of FSAR amend should be sent to listed address
 TRAMM.T R Commonwealth Edison Co. 93/06/21 DENTON.H R. Office of Nuclear Reactor Regulation, Director, ip 18993,313 24X Fiche 50-000,83/06/21.8306270373
- C Utility Environmental Report (ER), amends & correspondence
- 8304030R32 Forwards request for add1 info re environ rept OL stags. Response required by 830715
 YOUNGBLODD, B. J. Licensing Branch 1. 83/05/24 FARRAR, D. L. Commonwealth Edison Co. 26pp. 18733-352. 24X Fiche: 50-456, 83/05/24, 8304030232
- E NRC Safety Evaluation Report (SER), supply & correspondence
- 8306270431 Forwards advance copy of rev to Section E 17 of App E to FBAR Section describes safety parameter display sys. Info should close SER Dutstanding Item 16 TRAMM, T R. Commonwealth Edixon Co D3/06/17 DENTON, H R Office of Nuclear Reactor Regulation, Director, 13pp 19345-353, 24X Fiche 50-000, 83/06/17, 8306270431

- 8306240070 Requests add1 info re moisture separators of heaters in filter sys serving nonaccessible area & fuel handling bldg for SER review Info requested within 30 days to maintain review schedule
 YOUNGILCOD.B J Licensing Branch t 83/06/21 FARRAR, D 1
 Commonwealth Edison Co. 3pp. 18985 020 24X Fiche 50-000,83/06/21,83/06/21
- F Security, medical, emergency & fire protection plans
- 830&230257 Forwards add1 info on communications & cable spreading room suppression sys re fire protection program Third radio communication channel being installed Repeater will be located in turbine bidg.

 TRAMM.TR Commonwealth Edison Co. 83/06/17 DENTON.HR. Office of Nuclear Reactor Regulation. Director. 5pp. 19945-016 24X Fiche 50-000.83/06/17.8306230257
- 8306230412 Provides add1 info requested in NRC 830411 ltr reinstrumentation used to assure safe shutdown in event of fire Info will be incorporated into FSAR & fire protection rept in future amends
 TRAMM.T R Commonwealth Edison Co 83/06/17 DENTON.H R Office of Nuclear Reactor Regulation, Director 52pp 18743 136 PAX Fiche 50-000,83/06/17.8306230412
- K Utility Final Safety Analysis Report (FSAR) & amends
- B304030272 Forwards Amend 42 to FSAR
 TRAMBIT R Commonwealth Edison Co B3/05/31 DENTON, H R Office
 of Nuclear Reactor Regulation, Director 4pp 18/13 001 24X
 Fiche 50-800, B3/05/31, B304030272
- --8306030281 Amend 42 to FSAR * Commonwealth Edison Cp 83/05/31 583pp 18713 005 24X Fiche 50-000,83/05/31,8306030272
- 8306210211 Forwards affidavit of distribution for FSAR, Amend 42 TRAMM, TR Commonwealth Edison Co 83/06/14 DENION, HR Office of Nuclear Reactor Regulation, Director 2pp 18918 117 24X Fiche 50-000, 83/06/14, 8306210211
- Q Inspection reports: IE Bulletins & correspondence
- 8305110458 IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in Well Logging Device" Svc list encl TAYLOR.J M Division of Safeguards & Inspection Programs (Post 830103) 83/05/26 Consol)dated Edison Co of New York, Inc 125pp 18831 043 24X Fiche 50-000,83/05/26,8305110458
- 8305110460 IE Info Notice 83-34, "Event Notification Info Worksheet " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 115pp 18732 085 24x Fiche 50-000,83/05/24,8305110460
- 8305110461 IE Info Notice 83-35. "Fuel Movement W/Control Rods Hithdrawn at BHRs " 8vc list encl JORDAN E L Division of Emergency Proparedness & Engineering Response (Post 830103) 83/05/31 Consolidated Edison Co of New York, Inc 116pp 18732 208 24X Fiche 50-000,83/05/31,8305110461
- 8305110464 IE Info Notice 83-36. "Impact of Security Practices on Safe Operations" Svc list encl JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/07 Consolidated Edison Co. of New York, Inc. 119pp 18830 280 24X Fiche 50-000,83/06/07.8305110464
- 8305110470 IE Info Notice 83-38, "Defective Heat Sink Adhesive & Seismically Induced Chatter in Relays Within Printed Circuit Cards "Syc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co of New York, Inc. 118pp 18920 225 24X Fiche 50-000,03/06/13,8305110470
- 8306090010 IE Info Notice B3-37, "Transformer Failure Resulting From Degraded Internal Connection Cables" Svc list encl JURDAN, EL Division of Emergency Preparedness & Engineering Response (Post B30103) B3/06/13 Constit
- 8306270066 Ack receipt of 830524 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-456/82-08 & 50-457/82-08 NRELIUS, C. E. Division of Project & Resident Programs REED, C. Commonwealth Edison Co. 1p 18988 131, 24X Fiche' 50-456/83/06/20,8306270066

- --8306270071 Supple response to NRC 830234 ltr re violations noted in IE Insp Repts 50-456/82-08 & 50-457/32-08 Corrective action date of issuance for FCR L 8344 on diaming M337 located in Area III of auxiliary bldg corrected FARRAR, D L Commonwealth Edison Co 83/05/24 KEPPLFR, J & Region 3, Office of Director Jap 18488 132 24X Fiche 50-456-83/06/20,83062/0066
- 8309110475 IE Info Notice 83-40, "Need to Environmentally Qualify
 Epoxy Grouts & Sealers " Svc list enil
 JORDAN, E L Division of Energency Proporedness & Ingineering
 Response (Post 830103) 83/06/22 (onsolidated Edison to of New
 York, Inc 1155p 17021 177 24X Fiche 50-000.83/06/22.83051104/5
- B305110477 IE Info Notice B3-41, "Actuation of Fire Supplession Sys Causing Inoperablity of Safety Related Equipment" Syr list enc! JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) BJ/06/22 Consolidated Ldison Co of New York, Inc. 120pp 1897 007 24X Fires 50-000,63708/22,63051104/
- 8305110479 IE Info Notice 83-42, "Reactor Mode Switch Malfonctions " Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/23 (uncolidated Edison Co. of Meu York, Inc. 116pp 18996 242 24X Fichs 50-000,83/06/23,83051101/2
- 83051104B3 IE Info Notice 83-43. "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints "(vc list enc) JORDAN E L Division of Labergency Preparedness & Engineering Response (Post 830103) 83/06/24 Consolidated Edison Co of Mr., York, Inc 116pp 19046-297 24X Fichs 50-000,83/06/24,8,0051[018]
- 5 Reportable occurrences, LERs & related correspondence
- 8306030229 Final Deficiency Rept 63-04 re structural steel connection rework design inadequacy Initially reported on 830429 Jam nuts to be installed on sliding connections by 830601 & 840101 for Byron & 830725 & 1125 for Braidwood SMARTZ, ED Commonwealth Edison Co 83/05/26 KEPPLER, J O Regic 3. Office of Director 2pp 18/03 341 24X Fiche 50-000,83/05/26,8306030229
- 8306100234 Third Interim Deficiency Repts 82-11 & 82-12 re accuracy of Barton electronic instrument transmitters Changes in allowable accuracy of transmitters being evaluated Final rept will be sent by 830831
 TRAMM. TR Commonwealth Edison Co 03/06/01 KEPPLER, J 0 Region 3, Office of Director ip 1805-311 24X Fiche 50-000,03/06/01, 8306100236
- 8304100207 Final Deficiency Rept 82-09 re mechanical snubber bracket interference No inspected snubbers require redesign or repair Inspected suil be completed prior to fuel load FRAMMLT R. Commonwealth Edison Co. 33/06/02 KCPPLER.J G. Region 3. Office of Director ip 18805-294 24% Fiche 50-000. B3/06/02. B306100207
- 8306100246 Final deficiency rept re Westinghouse D8-416 reactor trip switchgear design discrepancy Initially reported on 830404 Replacement undervoltage attachments will have modified, widened proves to accommodate now retaining rings 8WARTZ. E. D. Commonwealth Edison Co. 83/06/03 KEPPLER. J (* Reps. 3, Office of Director 3pp. 18807-058 247 Fiche 50-000.83/06/63.8306100246
- 8306270282 Potential Part 21 tept re discrepancy in welding of turnbuckle assembly, turnbuckle-bolt interface & on top plate assembly variable springs SA307 Grade II bolts not AGN Section IX matl investigation underway KARAGIANIS.J A Elcen Metal Products Co 83/06/17 KEPPLIR,J 0 Region 3. Office of Director 2pp 18976 207 24X Fiche 50-000,83/06/17,8306270282
- DOCKET BTN-50-457 BRAIDWOOD STATION, UNIT 2
- A Application/construction stage documents & correspondence
- 8306030417 Requests info re identification of safety-related mechanical accipment located in harsh environ areas, including required operating times & plant location Info requested within 30 days of receipt of ltr
 YOUNGBLODD, B. J. Licensing Branch I 83/05/20 FARRAR, D. t. Commonwealth Edison Co. 3pp. 18735-359 24X Fiche 50-000.83/05/20 8306030417
- 8306030066 Ack participation in 830503-05 environ site visit [rpertise on aquatic biological resources will be particularly valuable as input to environ review YOUNOBLOOD, B J Licensing Branch i 80/05/23 BERTRAND, B A Illinois, State of Ip 18733-210 24X Ficho 50-456, 83/05/23, 8306030066

- 8306030237 Forwards request for addl info re application for GL covering pipe line locations & frequency of munitions shipments FSAR should be amended to include requested info Response required by 830715
 YOUNGBLOOD.B J Licensing Branch 1 83/05/24 FARRAR, D L Commonwealth Edison Co 3pp 18734 014 24% Fiche 50-456,83/05/24,8304030237
- 8306090194 Discusses util interpretation of 10CFR50 49, "Environ Qualification of Electrical Equipment Important to Safety for Nuclear Power Plants "Intent of Full Intent of Safety require Upgrade program for replacement equipment not parts FARRAR, D.L. Commonwealth Edison Co. 83/06/03 DENTON.H & Office of Nuclear Reactor Regulation, Director 3pp 18796 090 24% Fiche 50-000, 03/06/03, 8306090174
- B305140161 Submits list of endangered species present in proposed const site in response to B30503 ltr Indiana bat utilizes steam corridors for foraging in summer Bald eagle found in Will County during winter No critical habitat designated GB0UTAGE. I M. Interior, Dept. of. Fish & Wildlife Service B3705/07 YDUNBOLOOL B. J. Division of Licensing 2pp. 18839-071 24X Fiche 50-456,83/06/09,8306140161
- 8306200019 Summary of 830331 meeting w/utils & Westinghouse in Bethesda.MD re Westinghouse analysis & evaluation of D4/D5/E steam generator mod MDPKINS.J B Licensing Branch 4 83/06/14 Licensing Branch 4 22pp 18908 327 24X Fiche 50-000.83/06/14 8306200019
- 8306200069 Responds to 830414 momo requesting decision under NRC standardization policy re need to perform review of operation GA program Review of plant should be consistent w/standardized review
 THOMAS.C O Standardization & Special Projects Branch 83/06/14
 HAAES, W P Quality Assurance ip 18708 173 24X
 Fiche 50-456,83/06/14,8306200069
- B306230237 Forwards add1 info re use of PURVs for venting & depressurizing RCS at facilities & response to FBAR Guestion 212 159, to be incorporated into future FSAR amend TRAMM, I R. Commenwealth Edison Co. 97/06/16 DENION H R. Office of Nuclear Reactor Regulation, Director 18pp 18745-235 24X Fiche 50-000,83/06/16,8306230237
- 8306230294 Forwards addl FSAR info to Question 423 40 concerning suction conditions for essential see water pumps FSAR will be amended to include info contained in encl
 SHARTZ.C D Commonwealth Edison Co 83/06/17 DENTON.H R Office of Nuclear Reactor Regulation. Director 2pp 18945 167 24X Fiche 50-456.83706/17.8306230294
- 8305270322 Provides add1 details re control of heavy loads during const when new fuel assemblies being stored in spent fuel pit Durto failure of reactor coolant pump at Byron 1 fuel handling bldg crane unli be installed TRAMM T R Commonwealth Edison Co 03/06/17 DENTON, H R Office of Nuclear Reactor Regulation, Directur 1p 18794 073 2/4X Fiche 50-000, 83/06/17,8306270322
- 8306270373 Notifies of change in FBAR distribution All nuclear power plant activities transferred to new IL Nept of Nuclear Safety State copy of FBAR amend should be sent to listed address
 TRAPM.T R Commonwealth Edison Co 83/06/21 DENTON.H R Office of Nuclear Reactor Regulation. Director ip 18993 313 24X
 Fiche 50-000,83/06/21,8306270373
- C Utility Environmental Report (ER), amends & correspondence
- 8304030232 Forwards request for addl info to environ rept GL stage Response required by 830715 YOUNOBLOOD, B. J. Licensing Branch i 83/05/24 FARRAR, D. L. Commonwealth Edison Co. 26pp 18733 J62 24x Fiche 50-456, 83/05/24:8304030232
- E NRC Safety Evaluation Report (SCR), suppls & correspondence
- 8304270431 Forwards advance copy of rev to Section E 17 of App E to FBAR Bection describes safety parameter display sys Info should close SER Outstanding Item 16
 TRAMM.T.R. Commonwealth Eduson Co. 83/06/17. DENTON.H.R. Office of Nuclear Reactor Regulation. Director 13pp 19345-352 24X
 Fiche 50-000.83/06/17:8306270431
- 8304240070 Requests addl info re moisture separators of heaters in filter sys serving nonaccessible area & fuel handling bldg for SER review Info requested within 30 days to maintain review scheduls
 YOUNOBLOOD, B J Licensing Dianch 1 G3/06/21 FARRAR, D L.
 Commonwealth Edison Co 3pp 10980 029 84X Fiche 50-000,83/06/Pi,8304240070

- F Security, medical, emergency & fire protection plans
- 8306230257 Forwards add1 info on communications & cable spreading room suppression sys re fire protection program Third radio communication channel being installed Repeater will be located in turbine bldg
 TRAMM.T R Commonwealth Edison Co 83/06/17 DENTON, H R Office of Nuclear Reactor Regulation, Director 5pp 18945 016 24X
 Fiche 50-000, 83/06/17, 8306230257
- 8306230412 Provides add1 info requested in NRC 630411 ltr reinstrumentation used to assure safe shutdown in event of fire Info will be incorporated into 15AR & fire protection rept in future amends
 IRAMM.T R Commonwealth Edison Co. 63/06/17 DENTON.H R Office of Nuclear Reactor Regulation, Director 52pp 16943 136 24X Fiche 50-000.83/06/17.8306230412
- K Utility Final Safety Analysis Report (FSAR) & amends
- 8304030272 Forwards Amend 42 to FSAR TRAMMLT R Commonwealth Edison Co 83/05/31 DENTON,H R Office of Nuclear Reactor Regulation, Director 4pp 18713 001 24X Fiche 50-000,83/05/31,8304030272
- --8304030881 Amend 42 to F8AR * Commonwealth Edison Co 83/05/31 357pp 18713 005 24X Fiche 50-000.83/05/31.8304030272
- B306210211 Forwards affidavit of distribution for FSAR, Amend 42 TRAMM.T R Commonwealth Edison Co B3706/14 DENTON.H R Office of Nuclear Reactor Regulation, Director 2pp 18918 117 R4X Fiche 50-000.B3706/14.B306210211
- G Inspection reports, IE Bulletins & correspondence
- 8305110458 lE Info Notice 93-52, "Ruptured Am-241 Bources Contained in Hell Logging Device " Svc list enc! TAYLOR, J M Division of Safeguards & Inspection Programs (Post 833103) B3/05/26, Consulidate Edison Co of New York, Inc 125pp 18831 043 24X Fiche 50-000.83/05/26,8305110458
- 8305110460 IE Info Notice 83-34, "Event Notification Info Workshoot" Byc list encl JORDAN E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 115pp 18732 085 24X Fiche 50-000.83/05/26,8305110460
- 8305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods Withdrawn at BWRs." Svr list encl JORDAN:C L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/31 Consolidated Edison Co of New York, Inc 116pp 18732 208 24X Fiche 50-000,83/05/31,8308110461
- 8305110464 FE Info Notice 83-36, "Impact of Becurity Practices on Bafe Operations" Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) B3706/07 Consolidated Edison Co. of New York, Inc. 119pp 18890 280 24X Fiche 50-000,83/06/09,8305110464.
- 8305110470 IE Info Notice 83-39, "Defective Heat Bink Adhesive & Seismically Induced Chatter in Relays Within Printed Circuit Cards "Syc list entl.

 JORDAN.C L Divixion of Emergency Preparedness & Engineering Response (Post 830403) 83706/13 Consolidated Edison Co of New York, Inc. 11689, 18920-225 24X Fiche 50-00083706/13.8305110470.
- 8304090010 IE Info Notice 83-37. "Transformer Failure Resulting From Degraded Internal Connection Cables" Svc list encl JORDAN, E. L. Division of Energency Preparedness & Engineering Response (Post 830103) 83706/13 Consolidated Edison Co. of New York, Inc. 243pp 18921 001 24X Fithe 50-000.83/06/13.8304090010
- 8304270046 Ack receipt of 830524 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-456/82-08 & 30-457/82-08 MRELIUS, C E Division of Project & Resident Programs 83/06/20 REED. C Commonwealth Edison Co ip 18988 131 24X Fiche: 50-456, 83/06/20, 8306270066
- --8306270071 Supple response to NRC 830214 ltr re violations noted in IE Insp Repts 50-456/82-08 & 50-457/82-08 Corrective action, date of issuance for FCR L-8344 on drawing M537 located in Area III of auxiliary bldg corrected FARRAR, D L Commonwealth Edison Co 83/05/24 KEPPLER, J. G Region 3, Office of Director 3pp 1898 132 24X Fichs, 50-456, 83/06/20, 8306270066

- 8305110475 IE Info Notice 83-40, "Need to Environmentally Gualify
 Epary Grouts & Sealers " Svc list encl
 JORDAN, E. L. Division of Emergency Preparedness & Engineering
 Response (Post 830102) 83/06/22 Consolidated Edison Co. of New
 York, Inc. 115pp 17021 177 24X Fiche 50-000.83/06/22.8305110475
- 8305110477 IE Info Notice 83-41. "Actuation of Fire Suppression Bys Causing Inoperability of Safety-Related Equipment " Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 630103) 83/06/22 Consolidated Edison Co. of New York, Inc. 120pp 18997 007 24X Fishe 50-000.83/06/22.8305110477
- 8305110479 IE Info Notice 83-42 "Reactor Mode Switch Malfunctions" Byo list encl JORDAN, E. Division of Emergency Preparedness & Engineering Response (Post 830103) 83706/23 Consolidated Edison Co. of New York, Inc. 116pp 18996 242 24X Fiche 50-000,83706/23,8305110479
- 8305110483 IE Info Notice 83-43, "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints "Svc list encl JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/24 Consolidated Edison Cn of New York, Inc. 116pp 19046 297 24X Fiche 50-000,83/06/24,8305110483
- S Reportable occurrences, LERs & related correspondence
- 8304030229 Final Daficiency Rapt 83-04 re structural steel connection rework design inadequacy Initially reported an 830429 Jam nuts to be installed on sliding connections by 830801 & 840101 for Byron & 830725 & 1125 for Braidwood SKARTZ.E D Commonwealth Edison Co 83/05/24 KEPPLER.J & Region 3, Office of Director 2pp 18703 341 24% Fiche 50-000.83/05/26.
- 8306100236 Third Interim Deficiency Repts 82-11 & 82-12 re accuracy of Barton electronic instrument transmitters Changes in allowable accuracy of transmitters being evaluated Final rept will be sent by 830831 TRANM, Y R. Commonwealth Edison Co 83/06/01 KEPPLER, J G Region 3, Office of Director 1p 18805-311 24X Fiche 50-000,83/06/01,8306100236
- 8306100207 Final Deficiency Rept 82-09 re mechanical snubber bracket interference Na inspected snubbers require redesign or repair insps & changes will be completed prior to fuel load TRAMMIR Commonwealth Edison Co 93/06/02 KEPPLER, J 9 Region 3, Office of Director ip 18805 294 24% Ficha 50-000,83/06/02.8306100207
- 8306100246 Final deficiency rept re Wastinghouse DB-416 reactor trip switchgear design discrepancy Initially reported on 830504 Replacement undervoitage attachments will have modified, widered grouves to accomplate new retaining rings BHARTZE D. Commonwealth Edison Co 83706703 KEPPLER.J © Region 3, Office of Director 3pp 18807 058 24% Fiche, 50-000, 83706/03, 8306100246
- 8306270282 Potential Part 21 rept re discrepancy in welding of turnbuckle assembly, turnbuckle-bolt interface & on top plate assembly variable springs. 9A307 Grade B bolts not ABME Bection IX matl. Investigation underway KARAGIANIB. J A. Elten Metal Products Co. 83/06/17. KEPPLER. J G Region 3. Office of Director 2pp 18796 207 24X Fichs 50-000.83/06/17.8306270282

DOCKET 50-458 RIVER BEND STATION, UNIT 1

- A Application/construction stage documents & correspondence
- 8306030509 Informs that each LRG-II member must submit numerical value determined by GE for respective plants on fuel assembly lift off displacement, due to error in fuel assembly topical rept re LRG-II Generic Issue 2-CPB NDVAK.T M. Assistant Director for Licensing 63/05/23 NOLTISCHER, D. L. Licensing Review Group II 3pp 18735-051 24% Fiche: 50-000.83/05/23,8306030509
- 8304040373 Responds to 820903 ltr submitting position papers which included Licensing Review Group II proposed solution for Issue 4-MEB, intended to protect incrore instrument tubes from Flow-induced vibration Issue unresolved VOUNGELODD, B J Licensing Branch 1 83/05/26 HOLTSCHER, D L Licensing Review Group II HOLTSCHER, D L 111npis Power Co 4pp 18751-287. 24X Fichs. 50-000, 83/05/24, 8304040073
- 8306070205 Notification of B30607 meeting w/utils & S&W in Cherry Hill. NJ to discuss QDC 51 compliance (fracture prevention of containment pressure boundary) HAUOHEV, H. HEINKAM. E. Licensing Branch 2 83/06/02, NDVAK, T M Assistant Diractor for Licensing. 4pp 18809 225 24X Fiche 50-000, 83/06/02, 8306070205

- B306140417 Notification of B306d) meeting w/util & GE in Ban Jose, CA to discuss OBC B1 compliance MEINKAM.E. J. Licensing Branch 2 B3/06/02 SCHWFNCER.A. Licensing Branch 2 3pp. 18854 C69 P47 Fische 50-458, B3/06/02 B306140417
- 8306150227 Supple 830523 request for addlinfo repersonnel simulator training to complete review of DI application Response schedule requested SCHNENCFR.A Licensing Branch 2 83/06/02 CAHILL, W J Gulf Status Utilities Co 3pp 18870 063 24X Fiche 70-458.83/06/02, 8306150-27
- 8306130462 Notification of 830616 meeting w/util in St Francisville.LA to discuss various environ fractures prior to site tour HEINKAM.E. J. Licensing Branch 2 83/06/06 96H#FNCER.A Licensing Branch 2 3pp 18830 171 24X Fiche 50-458.83/06/06.8306130462
- 8306220254 Notification of 830621 meeting w/util & S&W in Bethesda.MD to discuss geosciences open items WEINKAM.E.J. Licensing Branch 2 83/06/09 BCHWENCER.A Licensing Branch 2 3pp 18951 063 P4X Fiche 50~458.83/06/09.8306220254
- 8306280328 Responds partially to NRC 816930 ltr re ultimate capacity analysis of Mark III containments Rept showing calculated general yielding value for steel containment of 56 psi encl Final results for remaining issues provided by 830430 BOOMER, JE Gulf States Utilities Co. 83766/22 TEDESCO,R I Assistant Director for Licensing App. 19001-216 EAX Fiche 50-458,83/06/22,8306280328
- F Security, medical, emergency & fire protection plans
- 830&150221 Responds to util B30307 & AlW ltrs re emergency operations facility (EGF) & backup EOF Pruposed LOF & backup EUF sites acceptable Addl LOF features & emergency response facilities to be evaluated during post-implementation review EIEENHUT,D @ Division of Licensing 83/06/01 CAHILL,W J Gulf States Utilities Co 2pp 18870 061 24X Fiche 50-458,83/06/01,8306150221
- 8306220250 Responds to 830307 ltr submitting Rev 3 to guard training & qualification plan Rev 3 satisfies 10CFR73 & 10CFR73. App B requirements License condition will incorporate 810825 ltr & approved revs SCHMENGER. A Licensing Branch 2 63/06/09 CAHILL. H.J. Gulf States Utilities Co. 2pp 18751-069 24X Fiche 50-458-83/06/09. 8306220250
- 8306220234 Summarizes telephone survey of agencies cited in k Littell B30603 ltr re whether govt agencies advise witnesses of right to coursel per Advisory Committee on Rights of Licensee Employees Under Investigation
 LEVI.R P Office of the General Counsel 83/06/10 Rights of Licensee Employees Under Investigation 4pp 18977 348 P4X Fiche: 50-458.83/06/10.8306220234

G Adjudicatory correspondence

- 8306100206 Answer opposing Joint Intervanors 830531 first amended & supplemented contentions Unauthorized filing seeks to add new contentions beyond time prescribed by ASLD Contentions w/o merit Certificate of Svc encl
 CONNER. T B Guif States Utilities Co CONNER. T B Conner & Wetterhahn 83/06/07 Atomic Safety and Licensing Board Panel lipp 18805 295 24% Fiche 50-458.83/06/07.8306100206
- 8306100041 Response opposing Joint Intervenors B30631 first amended & supplemented contentions Bubmittal procedurally improper Amends fail to remedy original contention defects Bupplemental contentions inadmissible W/Certificate of Bvc REPKA, D. A. Hearing Branch 3 B3/06/09 Atomic Safety and Licensing Board Panel 11pp 18805 117 24X Fiche 50-458,83/06/09,8306100041
- 8306220117 Response to NRC & util ensuers to first amended & supplemental contentions Contentions Piled in timely manner Certificate of Svc encl
 PALKENHEINER, D. IRVINO, S. M. Louislana Consumer's League, Inc., WATKINS, L. B. Rothschild, O. C. 83/06/13 Atomic Bafety and Licensing Board Panel App. 18926-096 24X Fiche 50-458,83/06/13,8306920117
- B306230003 Forwards NRC 830601 Wroft SER W/o encl REPKA,D A Hearing Branch 3 83706/21 COLE,R F., LINENBERGER,O., COTTER, U.P. Atomic Safety and Licensing Board Panel 1p 18747-079 24X Fiche 50-458,82706/21,8205230003,

- @ Inspection reports, IE Bulletins & correspondence
- B304060069 Forwards IE Insp Rept 50-458/b3-10 on B30407-30 No noncompliance noted MADSEN.O L. Region 4. Office of Director 83/05/17 CAHILL, W. J. Quif States Utilities Co. 2pp. 18719 J19 24X Fiche 50-458, B3/05/17, B304040067
- --8306060073 IE Insp Rept 50-458/83-10 on 030407-30 No noncompliance noted Major areas inspected licensee identified const deficiencies, safety-related pape welding, pape supports & restraints & electrical sys installation BROWN, R. L., CROSSMAN, W. A. Kegion 4. Office of Director 83/05/15/6pp 18719 321 24% Fiche 90-458,83/05/17,8306060069
- 830511049B IE Info Notice B3-32, "Ruptured Am-241 Sources Contained in Well Lugging Device" Svc list encl FAYLOR, JM Division of Safeguards & Inspection Programs (Post B30103) B3/05/24 Consolidated Edison Co of New York Inc 125pp 18831 043 24% Fiche 50-000,03/05/26,830511045B
- 8305110460 IE Info Notice 83-34. "Event Notification Info Worksheet" Svc list encl
 JORDAN, Et Division of Laergency Preparedness & Engineering
 Response (Post 830103) 83/05/26 Consolidated Edison Co of New
 York Inc 115pp 18732 085 24X Fiche 50-000, 83/05/26, 8305110460
- 8305;10461 IE Info Notice B3-35, "Fuel Movement W/Control Rods Withdrawn at BWRs " Svc list enc.]
 JORDAN: E.L. Division of Emergency Proparedness & Engineering Response (Past 830103) B3/05/31 Consolidated Edison to of New York Inc. 116pp 18732 200 24X Fiche 50-000, 83/05/31, 8300110461
- B305110464 IE Info Notice B3-36, "Impact of Security Practices on Safe Operations " Syr list enc! JDRDAN.E L Division of Emergency Proporedness & Engineering Response (Post 830103) 83/06/09 Consolidated Edison Co of New York, Inc 119pp 18830 280 24% Fiche 50-000,83/06/09,8305110464
- 8305110470 L. Info Notice 83-38. "Defective Heat Sink Adhesive & Seismically Induced Chatter in Relays Within Printed Circuit Cards " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Past 830103) 83/06/13 Consolidated Edison Co of New York, Inc. 118pp 18920 225 24X Ficho 50-000,83/06/13,8305110470
- 8306090010 IE Info Notice 83-37, "transformer Failure Resulting From Degraded Internal Connection Cables " Svc list and JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co of New York, Inc 243pp 18921 001 24X Fichs 50-000,83/06/13,8306090010
- 8305110475 IE Info Notice 83-40. "Need to Environmentally Qualify
 Epoxy Grouts & Sealers " Svc list encl
 JORDANIE L Division of Emergency Proparedness & Engineering
 Response (Post 830103) 83/06/22 Consolidated Edison Co of New
 York Inc 115pp. 19021 179 24X Fiche 50-000.83/06/22.8305110475
- 8305110477 IE Info Notice 83-41. "Actuation of Fire Suppression Bys Causing Inoperability of Safety-Related Equipment " Byc list enc! JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/22 Consolidated Edison Co. of New York Inc. 120pp 18997 007 24X Fiche 50-000,83/06/22,8308110477
- 8305110479 IE Info Notice 83-42. "Reactor Mode Switch Melfunctions " Exc list enc) JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/23 Consolidated Edison Co of New York, Inc. 114pp 18996 242 24X Fiche 50-000,83/06/23,8305110479
- 8305110483 IE Info Notice 83-43, "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints "Svc list enc), JORDAN, E. Davision of Emergency Properedness & Engineering Response (Post 630103) 63/06/24 Consolidated Edison to of New York, Inc. 116pp 19046 297 24X Fiche 50-000,83/06/24,8305110483
- S Reportable occurrences, LERs & related correspondence
- B305010394 Interim Deficiency Rept DR-73 re improperly installed apring buts in GE power generation control complex termination cabinets Initially reported on 820902 GE evaluation awaited Next rept due by 83(ROS BOOKER, J E Guif States Utilities Co 83/05/24 COLLINS, J T. Region 4. Office of Director ip 10402 234 24X Fiche 80-450,83/05/24,8304010394

- 8306010423 Interim Deficiency Rept DR-101 re undersized fillot welds on NF gips supports Initially reported on 830223 Addl info from util AE awaited Next rept will be submitted by 830808 BOOKER. J E Gulf States Utilities Co 83/05/24 COLLINS, J T Region 4. Office of Director ip 18679 311 24X Fichs 50-458.83/05/24.8306010423
- 8306070265 Interim Deficiency Rept DR-93 re documentation & code stamping of interconnecting piping between reactor water cleanup HXS Util awaiting info from supplier Atlas Industrial Mfg Co Next rept will be submitted by 830708 BCOKER, J E Gulf States Utilities Co 83/05/25 COLLINS, J T Region 4, Office of Director ip 18/40 336 24X Fiche 50-458,63/05/25,9306070265
- 8304070195 Interim Deficiency Rept 80 re defective piston skirt castings installed in emergency diesel generator engines supplied by Transamerica Delavel. Inc Initially reported on 821124 Insp of diesel generators underway BOOKER. J E 901f States Utilities Co 83/05/27 COLLINS, J T. Region 4, Office of Director ip 18736 294. 24X Fiche 50-458,83/05/27,8306070195
- 8306070176 Interim Deficiency Rept 89 re malfunction of primary knifetype disconnect mfg by RTE Delta Corp & used in dissel generators Initially reported on 830317 Util swalting addlinfo from Transamerica Delaval Next rept expected by 830706 BOOKER. J E Quif States Utilities Co 83/05/27 COLLINS. J T. Region 4. Office of Director 1p 18736 293 24X Fichs 50-458.83/05/27.8306070196
- 8306090038 Final Deficiency Rept DR-60 re design of nonseismic pipe sys over Category i components in control bldg. Initially reported on 820615 S&W improved basic program for sesting requirements of Reg Guide i 29 BOCKER. J. E. Guife i 29 BOCKER. J. E. Guif States Utilities Co. B3/05/31 COLLING, J. T. Region 4. Office of Director ip 18793 310 24X Fiche 50-458,83/05/31,8306070038
- 8306090365 Interim Deficiency Ropt DR-74 re incorrect installation of 1/4-inch drilled-in-expension-type anchor bolts, used to support emergency lighting bettery units Add1 AE info expected by 830729 Nost rept scheduled for 830818 BOOKER.J E Gulf States Utilities Co 83705/31 COLLINS, J T. Region 4. Defice of Director ip. 18795 068 24X Fiche 80-458,83705/31,8306090365
- 8306130317 Final Deficiency Rept DR-71 re inconsistencies in OA program at NJ Moolley Co.manufacturer of personnel air locks Initially reported on 820827. No physical hardware changes necessary Item not reportable per 100FR50 55(e) BOOKER, J E Quif States Utilities Co 83/06/03 COLLINS, J, T Region 4. Office of Director ip 18821 033. 24% Fichs 50-458, 83/06/03.8306130317
- 8306130376 Interim Part 21 Rept DR-95 re possible defect in plate & face plate gaskets for Morrison-Knudsen Co hydrogen ignitor, Model 6043 Initially reported on 830204 Evaluation not completed Not rept to be submitted by 830711 BOOKER, J E Gulf States Utilities Co. 83706/06, CDLLING, J T. Region 4. Office of Director ip 18822 346 24X Fiche 50-458.83/06/06.8306130376
- 8306160353 Interim Deficiency Rept DR-61 re length of capscrew which holds starting air valve assembly in cylinder head of standby emergency diesel generators supplied by Transamerica Delaval Initially reported on 830406 Next rapt by 830725 BOOKER, J E Gulf States Utilities Co 83706/07 COLLINS, J T Region 4, Office of Director ip 19060 123 24X Fiche, 50-458,83/06/07,8306160353
- 8306160320 Interim Deficiency Rept DR-111 re dimensional discrepancy on two small bore pipe support design drawings Initially reported on 830412 Evaluation continuing Next rapt will be submitted by 830714

 BODKER, J E Gulf States Utilities Co 83/06/08. CDLLING, J T Region 4. Office of Director ip 18863 233 24X

 Fich 50-458,83/06/08.8306160520
- 830&160439 Interim Deficiency Rept DR-115 we tactualding of heavy hex nuts Initially reported on 830510 Current station design specifies use of locknuts wheavy hex nuts in lieu of tackwelding Interim or final status rept expected by 83071B BOOKER.J E Gulf States Utilities Co 83706/09 COLLINS.J T Region 4. Defice of Director ip 18860 206 24X Fiche 50-458.83706/09.8306160439.
- 8306160521 Interim Deficiency Rept DR-72 re improper installation, teating & insp of concrete drilled-in-expansion-type anchors Initially reported on 830425 Add) AE info awaited. Next rept due by 830831 BODKER, J E Oulf States Utilities Co 83/06/10 COLLINS, J, T. Region 4, Dffice of Director ip 18864 033 24X Fiche 50-458,83/06/10,8306160521

- 8306160531 Interim Deficiency Rept DR-116 re larger-than-specified gaps in joints connecting RHR HX supports to embedment plates Initially reported on 830511 Nort rept to be provided by 830715 BOOKER, J. E. Gulf States Utilities Co. 83/06/10 COLLINS, J. T.
 - BOOKER, J E Gulf States Util)ties Co B3/06/10 COLLING, J T Region 4, Office of Director ip 13863 137 24X Fiche 50~458,83/06/10.8306160531
- 8306170395 Interim Deficiency Rept DR-109 re Velam 3/4-inch socket welded globe valves w/counterbores not concentric to ctr of valves Initially reported on 830408 AE evaluation awaited Next rept will be submitted by 830804 BDDKER, J E Gulf States Utilities Co 83/06/13 CGLLINS, J T Region 4. Defice of Director 1p 18800 237 24X Fiche 50~458,83/06/13.8306170395
- 830630014B Interim Deficiency Rept DR-107 re Category I air circuit breaters w/trip coils of higher range than shown on Dill of Matta Initially reported on 830404 Util awaiting addinfo from AE Next rept by 830719 to 800KER, J E General Public Utilities QPU Service Corp 83/06/14 COLLING.J T Region 4, Office of Director 1p 19119 320 P4X Fiche 50-458.63/06/14.6306300148
- 830A280355 Interim Deficiency Rept DR-#10 re contamination of stainless item woultrasonic couplant not meeting chemical analysis requirements Initially reported on B30408 Addl info from AE spected, Next rept will be provided by 830727 BOOKER, J E Gulf States Utilities Co 83/06/15 COLLINS, J T Region 4, Dffice of Director 1p 19014 OB2 24X Fiche 80-458,83/06/15,83063800555
- 830&270095 Interim Deficiency Rept DR-118 re insufficient penetration of welds for platform channels on primary shield well initially reported on 830917 investigation incomplete interim or final rept will be submitted by 830728 800KER, J E Gulf States Utilities Co 83706/16 COLLINS, J T Region 4, Office of Director ip 13488 138 24X Fiche 50-458,83704/16.8306270095
- 8306270130 Interim Deficiency Rept DR-119 re failure of threaded weld study during const of cable tray supports initially reported on 630517 Investigation incomplete Interim or final rept espected by 830502 BOOKER, J E Gulf States Utilities to 63/06/16 COLLINS, J 7 Region 4, Office of Director ip 18908 093 24X Fiche 50-458,83/06/16,8306270130
- 8306270391 Interim Deficiency Rept DR-117 we previously unanalyzed scenario which could result in containment negative pressure less than containment design negative pressure Initially reported on 830517 Next rept by 830807 BOOKER, J. E. Guif States Utilities Co. 83/06/16 COLLINS, J. T. Region 4. Office of Director ip 13974 151 24% Fiche 50-458,83/06/16,8306270391
- 8306270156 Interim Deficiency Rept DR-103 re linear indications found in lifting lugs on containment dome Initially reported on 830325 Util awaiting addl info from AE. Next rept expected by 830811
 BODKER, J. E. Gulf States Utilities Co. 83/06/17 COLLINS, J T Region 4, Defice of Director ip 17012 147 24% Fiche 50-458,83/06/17,8306270156
- 6306300121 Interim Deficiency Rept DR-10B re pipe support std components, supplied by Bergen-Paterson Pipe Support Corp not conforming to components referenced in design drawings Util awaiting info from AE Interim of final rept by 830910 BODKER. J E Gulf States Utilities Co 83/06/21 COLLINS, J T Region 4, Office of Director ip 19121 074 24X Fiche. 50-458, 83/06/21, 8306300121

T Hearing transcripts on non-antitrust matters

8306170289 Transcript of 830614 prehearing conference in Baton Rouge. LA Pp 1-132 * Atomic Bafety and Licensing Board Ponel 83/06/14 193pp 18881.139 24X Fiche.50-458.83/06/14,8306170289

RIVER BEND STATION, UNIT 2

'construction stage documents & correspondence

as that each LRG-II member must submit numerical value IE por respective plants on Puel assembly idement, due to error in fuel assembly topical deneric Issue 2-CPB istant Director for Licensing 83/05/23, Licensing Review Group II 3pp 18735 051 24X 1/05/23, 830&030509

- 8306060373 Responds to 820903 ltr submitting position papers which included Licensing Review Group II proposed solution for Issue 4-MEB, intended to protect in-tore instrument tubes from flow-induced vibration Issue unresolved YOUNGBLOOD, B.J. Licensing Rionch 1 83/05/26 HOLT/SCHER, D.C. Licensing Review Group II 4pp 18/51 28/ 24X Fiche 50-000,83/05/26.83060603/3
- 8306070205 Notification of 830607 meeting w/utils & SAW in Cherry Hill, NJ to discuss GDC 51 compliance (fracture prevention of containment pressure boundary)
 HAUGHEY.M., WEINKAM.E. Licouring Branch 2 83/06/02 NOVAK.] M. Assistant Director for Licenting App. 18809-225 24X
 Fishe 50 000,83/06/02.8306070205
- 8306140417 Notification of 830621 meeting w/util & GF in San Jose CA to discuss GDC 51 compliance WEINKAM E J Licensing Branch 2 83/06/02 SCHWENCER A Licensing Branch 2 3pp 18854 069 24X Fiche 50-458/83/06/02/8306140417
- 8306150227 Suppls 030523 request for add1 info re personnel simulator training, to complete review of OL application Response schedule requested SCHMENCER, A Licensing Granch 2 83/06/02 CAHILL, W.J. Culf States Utilities Co. 3pp. 18870-063 24X Fiche 50-458,83/06/02,8306150227
- 8306130462 Notification of 830616 meeting w/util in St Francisvills.LA to discuss various environ features prior to site tour MEINKAM, E. J. Licensing Branch 2. 83/06/06. SCHWENGER, A. Licensing Branch 2. 3pp. 18830-171. 24% Fiche 50-458, 83/06/06, 8306130469
- 830628032B Responds partially to NRC 810300 ltr re ultimate capacity analysis of Mark III containments Rept showing calculated general yielding value for steel containment of 54 ps: encl Final results for remaining issues provided by 8309400 BOOKER, J E Gulf States Utilities Co 83706/22 TEDESCO,R L Assistant Director for Licensing App 17001 215 24X Fiche 50-458,8306/22.830628032B
- F Security, medical, emergency & fire protection plans
- 8306150221 Responds to util 830307 & 410 ltrs re emergency operations facility (EDF) & backup EQF Proposed Eur & backup EQF sites acceptable Addl EUF features & emergency response facilities to be evaluated during post-implementation review EISENHUT, D 0 Division of Lirensing 83/06/01 CAHILL.W J Gulf States Utilities Co 2pp 18070 061 24X Fiche 50-458,83/06/01.
- 8306220250 Responds to 830307 ltr submitting Rev 3 to guard training & qualification plan Rev 3 satisfies 10CFR73 & 10CFR73.App B requirements License condition will incorporate 810025 ltr & approved revs SCHMENCER, A Licensing Branch 2 83/06/09 CAHILL.W J Gulf States Utilities Co 2pp 18751 069 24X Fiche 50-458.83/06/09, 8306220270
- 8304220234 Summarizes telephone survey of agencies cited in R littoll 830603 ltr re whether govt agencies advise witnesses of right to counsel per Advisory Committee on Rights of Licenser Employees Under Investigation LEVI.R P Office of the General Counsel 83/06/10 Rights of Licensee Employees Under Investigation 4pp 18777 348 24X Fiche 50-458,83/06/10,8306220234

G Adjudicatory correspondence

- 9306100206 Answer appasing Joint Intervenors 830531 first amended & supplemented contentions Unauthorized filing seeks to add new contentions begoing time prescribed by ASLB Contentions w/o merit Certificate of Byc ricl
 CONNER, T B Gulf Btates Utilities Co CONNER, T B Conner & Wetterhahn 83/06/07 Atomic Safety and Licensing Board Facel lipp 18805 295 24X Fiche 50-458,83/06/07,8306100206
- 8306100041 Response opposing Joint Intervenors 830531 first amended k supplemented contentions Bubmittel procedurally improper Amends fail to remedy original contention defects Supplemental contentions inadmissible W/Certificate of Svc. REPKA, D A Hearing Branch 3 83/08/09. Atomic Safety and Licensing Board Panel 11pp 18805 117 24X Fiche 50-458,83/08/09, 8306100041
- 8306220117 Response to NRC & util answers to first amended & supplemental contentions Contentions filed in timely manner Certificats of Svc encl FALKENHEINER, D. IRVING, S.M. Louisiana Consumer's League, Inc. WATKINS, L.D. Rothschild, G.(193/06/13) Atomic Safety and Licensing Board Panel App. 18926-094 24X Fiche 50-458,83/06/13,8306220117

- 8306230003 Forwards NRC 830601 draft SER W/o entl REPKA,D A Hearing Branch 3 B3/06/21 COLE.R F , LINENBERGER,G , COTTER,B P Atomic Safety and Licensing Board Pane) 1p 18947-079 24X Fiche 50-458,83/06/21.8306230003
- Q inspection reports, IE Bulletins & correspondence
- 8305110458 IE Info Notice 83-32, "Reptured Am-241 Sources Contained in Well Logging Device" Sec list encl
 FAYLOR, J M Division of Safequards & Inspection Progrems (Post 830603) 83/05/26 Consolidated Edison Co of New York, Inc 125p 18831 043 24% Fiche 70-000,83/05/26,8305110458
- B305110460 IE Info Notice B3-34, "Event Notification Info Worksheet" Swc list encl JORDAN E L Division of Emergency Preparedness & Engineering Response (Post B30103) 83/05/26 Consolidated Edison Co of New York, Inc 1159p 18732 085 24X Fiche 50-000, 83/05/26, 8305110460
- 8305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods Withdrawn at BWRs " Svc list (ncl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/31 Consolidated Edison Co. of New York, Inc. | 116pp 18732 208 24X Fiche 50-000,83/05/31,8305110461
- 8305110464 IE Info Notice 83-36, "Impact of Security Prectices on Safe Operations" Svc list encl JURDAN, E. L. Divicion of Emergency Preparedness & Engineering Response (Post 830103) 83/06/07 Consolidated Edison Co. of New York, Inc. 119pp 18830 280 24X Fiche 50-000, 83/06/09, 8305110464
- 8305110470 IE Info Notice 83-38, "Defective Heat Sink Adhesive & Seismically Induced Chatter in Relays Within Printed Circuit Cards." Svc list encl.

 JRROAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/04/13 Consolidated Edison Co. of New York, Inc. 1189p 18920 295 24X Fiche 50-000.83/04/13.8305110470
- 8306090010 IE Info Notice 83-37, "Fransformer Failure Resulting From Degraded Internal Connection Cables " Gvc list encl JURDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co of New York, Inc. 243pp 18921 001 24X Fiche 50-000,83/06/13,8306090010
- 8305110475 IE Info Notice 83-40, "Need to Environmentally Qualify
 Epoxy Grouts & Bealers " Svc list encl
 JORDAN E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/06/22 Goncolidated Edison Co of New
 York Inc 115pp 19021 179 24X Fiche 50-000,83/06/22,8705110475
- B305110477 IE Info Notice B3-41, "Actuation of Fire Suppression Sys Causing Inoperability of Safety-Related Equipment " Svc list encl JORDAN, C. L. Division of Emergency Preparedness & Engineering Response (Post B30103) B3/06/22 Consolidated Edison Co. of New York, Inc. 120pp 1897 007 24X Fire 50-000, B3/06/22, B305110477
- B305i10479 IE Info Notice B3-42. "Reactor Mode Switch Malfunctions " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) B3/06/23 Consolidated Edison Co of New York, Inc 116pp 18796 242 24X Fiche 50-000, 83/06/23, 8305110479
- 8308110493 IE Info Notice 83-43. "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Past 830103) B3/06/24 Consolidated Edison Co of New York. Inc 116pp 19046 297 PAX Fiche 50-000,83/06/24,8305110483
- T Hearing transcripts on non-antitrust matters
- 8304170289 Transcript of 830614 prohearing conference in Baton Rouge: LA Pp 1-132. * Atomic Safety and Licensing Board Panel 83/06/14 133pp 18881 139. 24X Fiche 30-458,83/06/14,8306170289.
- DOCKET 50-460 MPP68 NUCLEAR PROJECT: UNIT 1
- A Application/construction stage documents & correspondence
- B306080062 Notification of 830608 meeting w/util & United Engineers & Constructors in Opthesda, MU to discuss ABME Section III, Div 2 addends articles & code case review THADANI.M Licensing Branch 4 83/05/06 ADENBAM, E Q Licensing Branch 4, 3pp. 18787-303 24X Fiche 50-460,83/06/06.8306080062

- 8306090262 Forwards discussion of remaining ASME approved code cases & ABME Code addenda articles utilized during containment design & const for NRC approved Text of each code case, as approved by ASME, also encl Repty requested by 830617 BDUCHEY, 0 D Washington Public Power Supply System 83/06/06 ADENSAM.E Q Licensing Branch 4 22pp 18795 257 24% Fiche 50-460,83/06/06,8306090262
- 8306140612 Forwards add1 info requested at 830608 meeting re approval of ASME Section III, Div 2 Code Cases for containment In-place concrets strength is greater than design strength 80UCHEY, G D Washington Public Power Supply System 83/06/10 ADENSAM, E G Licensing Branch 4 App 18841 264 24X Fiche 50~460,83/06/10.8306140612
- B306240017 Forwards order extending const completion date of CPPR-134 to 910601 Safety evaluation supporting order encl ABENDAM.E G Licensing Branch 4 83/06/16 FERQUSON.R L Washington Public Power Supply System 2pp 18987 283 24X Fiche 50-440,83/06/16.8306240017
- --8306240025 SER supporting extension of CPPR-134 const completion date to 910601 * Licensing Branch 4 83/06/16 4pp, 18987 285 24X Fiche 50-460 83/06/16,8306240017
- ---8306240027 Order extending CPPR-134 const completion date to 910401 EIBENHUT.D 9 Division of Licensing 83/06/16 Washington Public Power Bupply System 3pp 18787 287 24X Fiche 50-460.83/06/16.8306240017
- 8306210301 Advises that NRC issued order extending CP per Commission Order CLI-82-29 YOUNG,M A Hearing Branch 4 B3/06/17 CROSSMAN,H, HARBOUR,J, BRIGHT,G O Atomic Safety and Licensing Board Panel 9pp 18914-025 24X Fiche 50-460.83/06/17.8306210304
- 9 Adjudicatory correspondence
- 8306010364 Responses to NRC first set of interrogatories Certificate of Syc encl, Related correspondence BELL.N Coalition for Safe Power 83/05/24 Office of the Executive Legal Director 7pp 18681 350 24X Fiche 50-460.83/05/24.8306010364
- 8306020365 Response supporting State of MA 830523 motion to be admitted as interested state in OL & CP proceedings Certificate of Svc encl REYNOLDS, N S Machington Public Power Supply System REYNOLDS, N S Debevolse & Liberman 83/05/31 Atomic Safety and Licensing Board Panel 3pp 18694 262 24% Fiche 50~460,83/05/31,8306020365
- 8306020412 Submits status rept re proposed schedules for remaining discovery, summary disposition memorando filing & hearing commencement Hearing tentatively scheduled for 831104.
 WAGNER.M E Hoaring Branch 4 83/06/01 GROBSHAN,H., HARBOUR.J, BRICHT, 9 D Atomic Safety and Licensing Board Panel 3pp 18695 030 24X Fiche 50-460,83/06/01.8306020412
- B30.6030347 Status rept & recommendations refuture course of proceeding.per ASLB B30325 memorandum & order Recommended schedule provided Hearings should not be prolonged unnecessarily Certificate of Svc encl REYNOLDS.N 9 Washington Public Power Supply System REYNOLDB.N 8 Debsvoise & Liberman 83/06/01 Atomic Safety and Licensing Roard Panel App 18705 001 24X Fiche 50-460.83/06/01.8306030347
- 830.6030353 Response in opposition to Coalition for Safe Power 830518 motion to compel licenses to respond to Interrogatories 6.7.
 8 % 9 Intervenor fundamentally misunderstand 830503 objections to interrogatories Certificate of 8vc encl REYNOLDS:N 9 Washington Public Power Supply System REYNOLDS:N S Delevoire & Liberman 83/06/01 Atomic Safety and Licensing Board Panel 9pp 18706 117 24X Fiche 50-460.83/06/01.8306030353.
- 830406030B Discovery status rept & proposed schedule for proceeding Certificate of Svc encl Related correspondence. BELL.N Coalition for Safe Power 83/06/01 4pp 18729.134 24X Fiche 50-460,83/06/01.8306060308
- B306090337 Motion to compel intervenor answers to licensee first set of interrogatories & requests to produce Responses avasive & incomplete Certificate of Svc encl REYNOLDS,N S Washington Public Power Supply System REYNOLDS,N S Debevoise & Liberman, B3706/07 Atomic Safety and Licensing Board Panel JSpp 18799 081 24X Fiche: 50~460,83/06/07,8306090337

- 8306100190 Second memorandum re petitioner standing to intervene Requisite interest to support representational standing established One litigable contention requirement not met Certificate of Svc encl REYNOLDS, N S Hashington Public Power Supply System * Debevoise & Liberman 83/06/08 Atomic Safety and Licensing Board Panel 7pp 18805 274 24X Fiche 50-460,83/06/08.8306100190
- 8306150302 First set of interrogatories Related correspondence ROSCLIE.E Coalition for Safe Power 83/06/09 Office of the Executive Legal Director Spp 18849 162 24X Fiche.50-460.83/06/09.8306150702
- 8306150306 Second set of interrogatories Certificate of Svc encl Related correspondence ROSOLIE.E Coalition for Safe Power 83/06/09 Hashington Public Power Supply System App 18249.146 24X Fiche 50-460.83/06/09, 8306150306
- 8306170411 Position re Combition for Safe Power standing to intervene Combition has met interest requirement & should be admitted as party if at least one litigable contention submitted Certificate of Svc encl WARNER.M E Hearing Branch 4 83/06/16 Atomic Safety and Licensing Board Panel 5pp 18880 044 24X Fiche 50-460.83/06/16,8306170411
- 8306210276 Response supporting State of WA 830509 request to participate as interested state in CP extension proceeding Certificate of Svc encl YOUNGM A. Hearing Branch 4. 83/06/16 Atomic Safety and Licensing Board Panel 2pp 18715 123 24X Fiche 50-460.83/06/16.8306210276
- 8306210347 Response supporting State of WA 830609 request to participate as interested state in QL proceeding, if Coalition for Safe Power petition to intervene granted Certificate of Svc encl YOUNG.N A Hearing Branch 4 83/06/16 Atomic Safety and Licensing Board Panel 2pp 18714 036 24X Fithe 50-460,83/06/16,8308210347
- 8306210301 Advises that NRC issued order extending CP per Commission Order CLI-82-29 YOUNG, M. Heering Branch 4 83/06/17 GROSSMAN, H., HARBDUR, J., BRIGHT, G.O. Atomic Safety and Licensing Board Penel 9pp 18914 025 24X Fiche 50-460,83/06/17,8306210301
- 8306230364 Forwards NRC 830616 order & safety evaluation extending const completion date from 820101 to 910101
 REYMOLDS,N S Debryoise & Liberman REYMOLDS,N S Washington Public Power Supply System. B3/06/21 GROSSMAN.H , BRIGHT,G O. HARROUR,J Atomic Safety and Licensing Board Panel 7pp 18944 119 24X Fiche 50-460,83/06/21,8306230364
- 8306240286 Advises that NRC will not respond to licensee 830607 motion to compal, girected to Coalition for Safe Power, Discovery dispute between licensee & intervenor MAGNER, M.E. Hearing Branch 4 83/06/22 QRDSSMAN, H., BRIGHT, Q.O., HARBDUR, J. Atomic Safety and Licensing Board Panel 1p 18780.157 24% Fiche: 50~460, 83/06/22, 8306240286
- 8306270370 Response to licensee 830607 motion to compel to first set of interrogatories Updated responses addressed licensee concerns thus negating necessity of ASLB ruling Related correspondence.

 ROSBLIE.E Coalition for Bafe Power 83/06/22 Atomic Safety and Licensing Board Panel ip. 19055 214 24% Fiche 50-460,83/06/22, 8306270370
- --8306290375 Updated response to first set of interrogatories Discusses decision to defer const & to extend CP Certificate of Svc encl. Related correspondence.

 ROSOLIE, E. Coalition for Spie Power 83/06/22 Washington Public Power Supply System 5pp 19055 215 24% Ficha 50-460,83/06/22,8306290370
- 8306270254 Memorandum holding Coalition for Safe Power meets interest requirements for intervenor status ABLB will not rule on contentions until State of WA responds to contentions GROSSMAN.H Atomic Safety and Licensing Board Papel 83/06/23 2pp 18990 223 24X Fiche 50-460.83/06/23,8306270254
- 8306270333 Memorandum & order admitting State of WA as interested state, to be represented by Energy Facility Bite Evaluation Council
 OROBSMAN.H. Atomic Safety and Licensing Hoard Panel 83/06/23
 Washington, State of 2pp. 18993 155 24X Fiche 50-460,83/06/23,8306270333,

- 8306270348 Memorandum & order admitting State of WA as interested state, to be represented by Energy Facility Site Evaluation Council State response to petitioner contentions due by 830712 GROSSMAN, H. Atomic Safety and Licensing Board Panel 83/04/27 Washington, State of 2pp 18993 141 24X Fiche 50-460.83/06/23, 8306270348
- 8306300047 Response to 830609 second set of interrogatories Certificat, of Svc encl
 REYNOLDS,N S Washington Public Power Supply System REYNOLDS,N S
 Debevoise & Liberman 83/06/28 Coalition for Safe Power 24pp
 19120 198 24X Fiche 50-460,83/06/28,8306300047
- B306300127 Memorandum & order granting Coalition for Safe Power B3052's motion to compel answers to Interrogatories 6.7.8 & 9 Info sought reasonably calculated to lead to discovery of admissable evidence OROSSMAN.H Atomic Safety and Licensing Board Panel 83/06/28 Coalition for Safe Power 4pp 19122 095 24X Fichs 50-460.03/06/28.8306300127
- @ Inspection reports, IE Bulletins & correspondence
- 8306100009 Addl response to FDIA request for documents dtd 820101 or after re SALP Forwards App A documents Documents also available in PDR FELTON.J M Division of Rules and Records 83/04/11 CLARK.R San Francisco Examiner 3pp 10815 252 24X Fiche 50-000,83/04/11,8306100009
- --8306100014 Submits schedule for Region V SALP Board meetings for 820928-830523 ENGELKEN,R H Region 5, Office of Director 82/03/19 DENTON.H R Office of Nuclear Reactor Regulation, Director 1p 18815 253 24X Fiche 50-000.83/04/11.8306100009
- B305110458 IE Info Notice B3-32, "Ruptured Am-241 Sources Contained in Well Logging Device" Syc list entl TAYLOR, J K Division of Safeguards & Inspection Programs (Post 830103) B3/05/26 Consolidated Edison Co of New York, Inc 125pp 18831 043 24X Fiche D0-000, 0:/05/26, 8305110458
- 8305110460 IE Info Notice 83-94, "Event Notification Info Worksheet"
 8vc list encl
 JORDAN. EL Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/05/26 Consolidated Edison to of New
 York, Inc. 115pp 18732 085 24X Fiche 50-000, 83/05/26, 8305110460
- 8305110461 IE lnfo Notice 83-35. "Fuel Movement W/Control Rodo. Withdrawn at BMRs " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/31 Consolidated Edison Co of New York, Inc 116pp 18732 208 24X Fiche 50-000,83/05/31,8305110461
- 8305110464 IE Info Notice 83-36, "Impact of Security Practice, on Safe Operations" Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post B30103) 83/06/09 Consolidated Edison Co. of New York, Inc. 117pp 18830 280 24X Fiche 50-000,83/06/09,8305110464
- 8305110470 IE Info Notice 83-30, "Defective Heat Sink Adhesive & Seismically Induced Chatter in Relays Within Printed Circuit Cards " 3ve list encl URDAN.C L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Cp of New York, Inc 118pp 18920 225 24X Fiche 50-000.83/06/13.0305110470
- 8306090010 IE Info Notice B3-97, "Transformer Failure Resulting From Degraded Internal Connection Cables " Svc list encl JURDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83706/13 Consolidated Edison Co. of New York, Inc. 243pp 18921 001 24X Fishe 50-000,83/06/13,8306090010
- 8305110475 IE Info Notice 83-40, "Need to Environmentally Qualify
 Epoxy Grouts & Sealers " Svc list encl
 JORDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/06/22 Consolidated Edison Co of New
 York, Inc 115pp 17021 177 24X Fiche 50-000,83/06/22,8305110475
- 8305110477 IE Info Notice 83-41, "Actuation of Fire Suppression Gys Causing Inoperability of Safety Related Equipment " Svc list encl. JORDAN, E.L. Division of Emergency Proparedness & Engineering Response (Post 830103) 83/06/22 Consolidated Edison Co. of New York, Inc. 120pp 18997 007 24X Fiche 50-000,83/06/22,8305/10477
- 8305110479 IE Info Notice 83-40, "Reactor Mode Switch Malfunctions " 8vc list encl. JORDAN,E I. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/23 Consolidated Edison Co. of New York, Inc. 116pp. 18996 242 24X Fiche 80-000,83/06/23,8305110479

- 8305110483 IE Info Notice 83-43, "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints " Svc list encl JORDAN E E Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/24 Consolidated Edison Co of New York, Inc 114pp 17046 277 24X Fiche 50-000,83/06/24,8305110483
- S Reportable occurrences, LERs & related correspondence
- 830A070113 Interim deficiency rept re potential failure of reactor vessel internals bolts Initially reported on 830502 B&W participating in insp program on operating plants Status rapt will be provided upon const rectart DE LORENZO.R A Washington Public Power Supply Bystem 83/05/25 STERNIERO.D M Region 5. Office of Director 2pp 18739 212 243 Fithe 50-440.83/05/25.8304070113
- B306300157 Part 21 rept re spot welds in Bailey Controls Co cabinets w/smaller diameter than specified Cabinets strengthened by stam & edge welding or bolting TAYLOR, J H Babcock & Wilcox Co B3/06/23 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 2pp 1919 308 24X Fichs 50-000, 83/06/23, 8306300159

DOCKET 50-461 CLINTON POWER STATION, UNIT 1

- A Application/construction stage documents & correspondence
- B306160031 Clarifies NRC final response to FDIA request for documents re Zack Co &/or work performed by Zack in const of facilities App D Document 5 deleted since document identical to App A Document 135
 FELTON.J M Division of Rules and Records 83/04/14
 PRENDEROAST, R Prendergast, R J 1p 18872 356 24X
 Fichs 50-000.83/04/14,8306160031
- 8306030509 Informs that each LRO-II member must submit numerical value determined by QE for respective plants on fuel assembly lift aff displacement due to error in fuel assembly topical rept re LRO-II Generic Issue 2-CPB NOVAN, T M Assistant Director for Licensing 83/05/23 MOUAN, T M Assistant Director for Licensing 83/05/23 Fiche 50-000, 83/05/23, 8306030509
- 830&060373 Responds to 820903 ltr submitting position papers which included Licensing Review Group II proposed solution for Issue 4-MEB, intended to protect in-core instrument tubes from flow-induced vibration Issue unresolved YOUNOOLOOD, B J Licensing Branch 1 83705/26 HOLTZSCHER, D L Licensing Review Group II 4pp 18791 247 24X Fiche 50-000, 83/05/26, 8306060373
- B306020620 Informs that fuel load date revised from Jan 1984 to Jan 1984 Press release encl AEEL80N.H Licensing Branch 2 83/05/27 DENTON.H R . CASC.E 0 . CARTER.J Office of Nuclear Reactor Regulation, Director 2pp 18702 357 24X Fiche 50-461.83/05/27.8306020620
- 8306210231 Forwards Action Plans 1.2,3.4 & 33, in response to Humphrey concerns for NRC review Action 33 re suppression pool temp sensors emergency procedures closed NULLER, G E Illinois Power Co 83/06/17 SCHWENCER, A Licensing Branch 2 16pp 18916 043 24X Fiche 50-461,83/06/17.8306210231.
- E NRC Safety Evaluation Report (SER), suppls & correspondence
- 930404012 SAFETY EVALUATION REPORT RELATED TO THE OPERATION OF CLINTON POWER STATION. UNIT NO 1 Docket No 50-461 (Tilinois Power Company. et al) # Division of Licensing NUREO-0853 SOR 83/05/31 72pp Available at NRC 44 50 18747 321 24X Fiche. 50-461, 83/05/31, 8306360412
- 8306070444 Forwards Suppl 2 to SER (NURLG-0853) W/o encl 9CHHENCER, A Licensing Branch 2 83/05/31 WULLER, 0 Illinois Power Co 1p 18780 351 24X Fishe 50-461,83/05/31,8306070444
- --8306070446 Forwards Suppl 2 to May 1783 SER (NUREG-0853) W/a encl. * Office of Nuclear Reactor Regulation, Director 83/08/26. OTTINGER.R. House of Rep , Energy & Commerce ip 18780 352 24% Fiche. 50-461.83/05/31.8306070444
- --8306070447 Forwards Suppl 2 to May 1983 GER (NUREQ-0853) W/o encl. * Office of Nuclear Reactor Regulation, Director 83/05/26 SIMPSON, A Benate, Environment & Public Works. 1p. 18780: 353 24X Fiche 50-461, 83/05/31, 8306070444
- --9306070451 Forwards Suppl 2 to May 1983 SER (NUREG-0853) W/o encl * Office of Nuclear Reactor Regulation, Director 83/05/26. UDALL, M. House of Rep. Interior & Insular Affairs 1p 18780-354. E4X Fiche 50-461.83/05/31.8306070444

- F Security, medical, emergency & fire protection plans
- 8304150285 Responds to util B21203 ltr & May 1982 Amend 14 to FSAR responds of second site acceptable Addl EGF features & emergency response facilities to be reviewed during post-implementation review EISENHUT, D O Division of Licensing. B3/06/01 WULLER, 0 E Illinois Power Co. 2pp 18869 318 24X Fiche 50-461,83/06/01,8304150285
- 8306100077 Forwards schedule implementation plan for emergency response capability & list of submittals required by NUREG-0737.
 Suppl i.per Generic Ltr 82-33 Procedures generation package will be submitted by B40501
 MULLER.G E Illinois Power Co 83/06/06. SCHNENCER, A Licensing Branch 2 5pp 18804 043 24X Fiche 50-461.83/06/06.9306100077
- 8306200407 Forwards "Emergancy Response Facilities Design Rept." per NUREO-0737. Suppl 1. in response to Generic Ltr 82-33 WULLER. & Illinois Fower Co 83/06/16 SCHHENCER. A Licensing Branch 2 ip 18704 325. 24X Fiche 50-461. 83/06/16 8306200409.
- --8306200414 "Emergency Response Facilities Design Rept " * Illinois Power Co 83/06/16 38pp. 18904-326 24X Fiche 50-461.83/06/16,8306200409
- Adjubicatory correspondence
- 8306150226 Response to 830419 questions & document request re Contentions III & IV. PATTERSON,W F Hearing Branch 3 83/05/23, WILLIAM,P L Illinois, State of 22pp 18846, 289, 24X Fiche 50-461, 83/05/23, 8306150226
- 8306080169 Forwards Suppl 2 to BER H/o encl.
 ODDDARD.R J. Hearing Branch 3 B3/06/06 CLARK.H K , PARIB.D H ,
 FEROUSON.O A Atomic Safety and Licensing Board Panel ip
 18772 157 24X Fichs 50-461, B3/06/06. B306080163
- K Utility Final Safety Analysis Report (FBAR) & amends
- B306070396 Forwards Amend 25 to FSAR; containing rev to Chapter 17 to resolve BER Outstanding Issue 20 re QA program & SER Confirmatory Issue 5 re containment ultimate strength HALL, D. P. Illinois Power Co. B3/05/31 DENTON, H. R. Office of Nuclear Reactor Regulation, Director 1g 18742 284 24X Fiche 50-461, B3/05/31, B306070396
- --8306070401 Amend 25 to FSAR. * Illinois Fower Co 83/05/31 137pp 18742,285 24% Fiche 50-461,83/05/31,8306070396.
- Q Inspection reports. IE Bulletins & correspondence
- 8306030142 Forwards IE Insp Rept 50-461/83-02 on 830117-21 & 0308-11 & notice of violation LITTLE.W. 8 Region 3. Office of Director 83/05/16 GERSTNER.W (Illinois Power Co 2pp 18704.268. 24X Fiche 50-461.83/05/16.8306030142
- --8306030144 Notice of violation from insp on 830117-21 t 0308-11 LITTLE,W. 8 Region 3, Office of Director 83/05/16 2pp 18704 270 24X Fiche, 50-461, 83/05/16, 8304030142
- --8306030147 IE Insp Rept 50-461/83-02 on 830117-21 & 0308-11.

 Noncompliance noted failure to accomplish activities affecting quality in accordance w/instructions, procedures & drawings

 LOVE, R S., WILLIAMS, C C. Region 3, Office of Director 83/05/12
 11pp 18704 272, 24X Fiche: 50-461, 83/05/16, 8306030142
- 8306220066 Forwards IE Insp Rept 50~461/83-05 on 830318-0515. No noncompliance noted.

 KNOP,R C Region 3. Office of Director 83/06/06. GERSTNER.W C. Illinois Power Co 2pp 18728-171. 24% Fichs, 50~461,83/06/06. 830620066
- --BD06220076 IE Insp Rapt 50-461/83-05 on B30318-0515 No noncompliance moted, Major areas inspected mat I laydoum & storage areas, progress control; licensee action on previous insps, walding, heat treat & NDE & stop work recovery activities.
 LIVERMORE, H. H., HAYES, D. H. Region: 3, Office of Director, 83/06/03, 7pp 18928.173 24X Fiche: 50-461,83/06/06,8306220066.

- 8306270117 Requests review of util recovery plan to correct deficiencies associated w/NRC 820623 stop work order Appropriate procedures & instructions revised & training accomplished & documented HALL.D F Illinois Power Co 63/06/15 KEPPLER.J O Region 3, Defice of Director 1p 1878B 106 24X Fiche. 50~461.83/06/15, ago.27047017
- 8306270311 Forwards SALP Rept 50-461/82-21 for Oct 1981 Bept 1982 KEPPLER, J G Region 3, Office of Director 83/06/22 GERSINER, W C Illinois Power Co 2pp 18993 321 24X Fiche 50-461,83/06/22,
- --8306270314 SALP Rept 50-461/82-21 for Oct 1981 Sept 1982 Significant progress in upgrading regulatory performance evident Region 3. Office of Director 83/06/22 27pp 18993 323 24X Fiche 50-461.83/06/22.830627031
- --8306270321 Responds to BALP Rept 50-461/82-21 for Oct 1981 Sept 1962 SM retained as mgt support involved w/const of Facility & increased emphasis placed on hiring & retention of qualified personnel GERSTNER, W C Illinois Power Co 83/04/12 KEPPLER, J 0 Region 3, Office of Director 3pp 18993 350 24X Fiche 50-461, 83/06/22,8306270311
- S Reportable occurrences, LERs & related correspondence
- 830&070289 Interim Deficiency Rept B2-12 re bound sway strut/snubber piping component supports Initially reported on 821021 Field insp of Basic Engineers sway struts & snubbers underway Next rept expected in 90 days HALL,D P Illinois Power Co 83/05/31 KEPPLER,J 0 Region 3, Office of Director. 4pp 18776 178 24X Fiche 50-461,83/05/31,830&073289
- 830A070338 Interim rept of Potential Deficiency 83-02 re procedural controls for insp of field counterboring of safety-related pipe Initially reported on 8301i3 Applicable procedures & instructions revised HALL,D P Illinois Power Co 83/05/31 KEPPLER, J 0 Region 3, Office of Director 5pp 18742 125 24X Fiche 50-461, 83/05/31, 830A07033R
- 8306100060 Interim rept re vendor shop welding deficiencies on structural steel walds supplied by Rockwell Engineering Initially reported on 830427 Investigation continuing Final rept will be submitted in 90 days HALL, D P Illinois Power Co 83/05/31 KEPPLER, J Q Region 3, Office of Director 3pp 18802 172 24X Fiche, 50-461, 83/05/31, 8306100660
- B306100141 Interim Deficiency Rept B3-01 re qualification of suppliers for measuring & test equipment calibr svcs Initially reported on B30113 QA instruction for procurement document reviews revised & training provided to QA personnel. HALL.D. P Illinais Power Co. B3/05/31 KEPPLER.J. O Region 3. Office of Director 4pp 1B801 295 24X Fiche 50-461.B3/05/31.B306100141
- 8306170370 Final Deficiency Rept 82-08 re lack of distribution control for instrument data sheets Initially reported on 820902 Instrument data sheet books reissued as controlled copies & computer info sys established by Baldwin Assuc HALL.D F Illinois Power Co 83/06/06 KEPPLER.J. 9 Region 3, Office of Director 7pp 18880.312 24X Fiche 50-461.83/06/06.8306170370
- 8306170383 Final Deficiency Rept 82-07 re breakdown in OA program Initially reported on 820708 Actions to be taken to ensure timely insps listed HALL.D. P. Illinois Power Co. 83/06/06 KEPPLER, J. 9. Region 3, Office of Director 7pp 18880 230 24X Fichs 50-461,83/06/06, 8206170882
- 8306270334 Interim Deficiency Rept 82-10 re violation of min wall thickness for safety-related piping Initially reported on 821007 Sargent & Lundy reviewing piping design Piping lines 1LP2164 & 1LP2184 modified Next rept within 90 days HALL,D P Illinois Power Co 83/06/17, KEPPLCR.J Q Region 3, Office of Director 4pp 18993:137 24X Ficher 50-461, 83/06/17, 8306270334
- T Hearing transcripts on non-antitrust matters
- B306070183 Transcript of B30602 prehearing conference in Urbana.IL Pp 372-437. • Atomic Bafety and Licensing Board Panel 83/06/02. 66pp 18738.216 24X Fiche 50-461.83/06/02.8306070183

- DOCKET 50-462 CLINTON POWER STATION, UNIT 2
- A Application/construction stage documents & correspondence
- 8306160031 Clarifies NRC final response to FDIA request for documents re Zack Co &/or work performed by Zack in const of facilities App D Document 5 deleted since document identical to App A Document 135 FELTON, J M Division of Rules and Records 83/04/14 PRENDERGASTA Prendergast R J ip 18872 356 24X Fiche 50-000,83/04/14,8306160031
- DOCKET STN-50-470 CESSAR SYSTEM SO
- A Application/construction stage documents & correspondence
- 8304070170 Forwards review of CESBAR-F against requirements of CP/ML rule 10CFR50 34(f) & selective sections of App B & Chapter 3 of CESBAR-F Only fraction of rule requirements within scape of CESBAR-F CESBAR-F complies w/rule SCHERER, A E Combustion Engineering, Inc. 83/05/25 EISEMIUT, D & Division of Licensing 103pp 18794 010 24X Fiche 50-470, 83/05/25,8304090170
- B30613042B Summarizes 830425 meeting w/NRC re natural circulation cooldown analysis for CESSAR-F Reanalysis to be submitted by B30729
 SCHERER, A E Combustion Engineering, Inc. B3/06/07 EISENHULD O Division of Licensing ip IBB21 229 24X Fiche 50-470.83/66/0/, 830613042B
- 8304200254 Forwards "Basis for Design of Plant W/o Pipe Whip Restraints for RCS Main Loop Piping," to demonstrate that guillutine-type failure of RCS main loop piping need not be considered in design basis for Sys 80 SCHERER, A E Combustion Enganeering, Inc. 83/06/14 EIGENHUI, D Q Division of Licensing 121pp 18701 FO2 24X Fiche 50-470. 83/06/14,8306200254
- E NRC Safety Evaluation Report (SER), supple & correspondence
- B305200070 Approves request for withholding, per 10CFR2 770, inPotransmitted by B30228, 0304 & 0503 ltrs re SER Confirmatory Item 7
 THOMAS.C O Standardization & Special Projects Branch B3705/13) SCHERER, A E Combustion Engineering, Inc. Spp. 18708 174 24X Fiche 50-470, 83/05/13, 8305200070
- 8304200392 Clarifies plant-specific info needed to CESBAR-F supplemental SER, Section 4 4.6, "Statistical Combination of Uncertainties" No plant-specific submittal planned since verification of values to be documented internally SCHERER. A C Combustion Engineering, Inc 83/06/15 EIBLNBULD O Division of Licensing ip 18919 219 24X Fiche 50-470.83/06/15, 8304200392

DDCKET BTN-50-482 WOLF CREEK GENERATING STATION

- A Application/construction stage documents & correspondence
- B3060603B3 Responds to B30509 request for permission to use Foragraph NX-4427 of Winter 1982 Addenda to Section III of ABMC Boiler & Pressure Vessel Code refillet wold requirements Request acceptable YOUNOBLOOD, B J. Licensing Branch 1 B3/05/26 KDESTER, G I Mansa Gas & Electric Co. SCHNELL, D F. Union Electric Co. 3pp 18748 359 24X Fiche 50-000, 83/05/26, 83060383
- 8304080051 Forwards request for add1 info re environ qualification plan Info requested within 2 wks of receipt of 1tr YOUNGBLOOD, B J Licensing Branch 1 BD/05/31. BCINELL, D, F Union Electric Co. KOESTER, O L Kaness Gas & Electric Co. 4pp 18787 308 24X Fiche 50-000, 83/05/31, 8304080051
- 8306080321 Notification of 830620 & 24 meetings w/utils & SNUPPG in Highway, MO & Burlington, KG, respectively, to discuss environ qualification of equipment EDISON, G E Licensing Branch i 83/06/02 YOUNGBLOOD, B J Licensing Branch i 5pp 18/89 350 24X Fiche 50-000,83/06/02,830680321
- 8306080175 Forwards changes to FBAR addendum.Rev 10 re operating QA program (Section 17 2) Updated Table 17 2-1 will be formally incorporated in Rev II to FSAR.

 KOESTER.G L Kansas Gas & Electric Co 83/06/06 DENTON,N R Office of Nuclear Reactor Regulation, Director Spp. 19771,301 24X Fiche 50-482,83/06/06,8306080175

- --830&080178 Changes to FSAR addendum, Rev 10 re operating GA program (Section 17 2) ** Kansas Gas & Electric Co 83/04/30 27pp 18771 304 24X **Fight 50-482, 83/04/04, 830&080175
- 8306140230 Forwards revised pages to design & const GA program & revised Page 17 1-15 to SNUPPS Design & Const GA Program Pages will be formally incorporated into next rev of SNUPPS Design & Const GA Program XDESTER.0 L. Kansas Gas & Electric Co. 83/06/10 DENTON.H R Office of Nuclear Reactor Regulation, Director COLLINS, J.T. Region 4. Office of Director Spp. 18832-296 24X Fiche 50-482,83/06/10.8306140230
- --B306140234 Revised pages to design & const QA program # Kansas Cas & Electric Co B3/06/10 49pp 18832 299 24X Fiche 50-482,83/06/10,8306140230
- --8306140240 Revised Page 17 i-15 to SNUPPS design & const GA program

 * Standardized Nuclear Unit Power Plant System 83/06/10 3pp
 16832 348 24% Fiche 50-482,83/06/10,8304140230
- B30&220018 Forwards addl info re environ qualification of safety-related electrical equipment, in response to NRC B30531 ltr
 FBAR will be updated in next rev to include questions & responses
 PETRICK,N A Standardized Nuclear Unit Power Plant System
 B3/06/10 DENTON, HR Office of Nuclear Reactor Regulation,
 Director 4pp 18927 318 24X Fiche 50-000.83/06/10.8306220018
- 8306160539 Informs of change in plans for completion of local containment leak rate testing Encl info re testing will be incorporated into Rev II of Wolf Creek FSAR & Rev I2 of SNUPES FSAR KOESTER. C L Kansas Gas & Electric Co 83/06/13 DENTON, H R Office of Nuclear Reactor Regulation, Director Opp 18865 043 24X Fiche 30-482.83/06/13.8306160539
- 8306200312 Forwards util 830523 ltr informing NRC of revised schedule for fuel load & commercial operation Fuel load scheduled for 840815 Commercial operation planned for 850215 Svc list encl RIDGHAY, D. A. Shaw, Pittman, Potts & Troubridge RIDGHAY, D. A. Kansas Gas & Electric Co. 83/06/15 LAURENSON, J. A. ANDERSON, O. C. FAXTCH, H. C. Atomic Safety and Licensing Board Panel App. 18897, 300 24X Fiche 80-482, 83/06/15, 8306200312
- F Security, medical, emergency & fire protection plans
- B306060191 Forwards Rev 10 to radiological emergency response plan (filed in PDR Category F) KDESTER,0 L Kentas Gas & Electric Co 83/05/31 DENTON, H R Office of Nuclear Reactor Regulation, Director 10pp 18720 001 24X Fiche 50-482,83/05/31,8306060191
- --8306060195 Rev 10 to radiological emergency response plan * Kansas Gas & Clectric Co 83/04/30 205pp 18721 333 24X Fiche 50-482,83/05/31,8306060191
- B306.150482 Releases public version of revised radiological emergency response plan.
 FELTON, J H Division of Rules and Records 83/06/06 Document Management Branch ip 18868 039 24% Fiche 50-482,83/06/06,8306.150482
- --8306150487 Public version of Rev 10 to radiological emergency response plan Revised plan will be included in FSAR.Rev 10 W/830429 ltr s. KOESTER. © L. Konsas Gas & Electric Co 83/04/30 DENTON.H R Office of Nuclear Reactor Regulation. Director 128pp 18868 040 24X Fiche 80-482,832/06/06.8306150482
- 8306220078 Forwards Suppl 2 to SER (NUREO-0881) W/o encl YQUNGBLOOD, D.J. Licensing Branch 1 83/06/16 KDESTER, C.L. Kanson Gas & Electric Co. 2pp 18977-346 24X Fiche 50-482.83/06/16. 8306220098
- Q. Adjudicatory correspondence
- 8306160393 Forwards collation of intervenor interrogatory responses identified in Paragraphs 6(a)-(h) of intervenor 830512 response to util dejections Svc list encl
 Silberg, J E Shaw, Pittman, Potts & Troubridge Bilberg, J E Kansas Gas & Electric Co 83/06/13 LAURENSON, J. A. ANDERSON, G C. . PAXTON, H C Atomic Safety and Licensing Board Panel 47pp 18966 048 24X Fichs 50-482, 83/06/13, 8306160593

- 8306200318 Forwards "Hyle Research Rept (MR B2-36).Final Design of Alert & Notification Sys for Wolf Creek Generating Station "
 Svc list encl Related correspondence M/o rept
 SILBERG.J E Shaw, Pittman, Potts & Trowbridge SILBERG.J.E.
 Kansas Gas & Electric Co 83/06/13 LAURCHSON.J A , ANDERSON. Q C ,
 PAXTON.H C Atomic Safety and Licensing Board Panel 3pp
 18899 209 24X Fiche 50-482.83/06/13.8306200318
- 8306200312 Forwards util 830523 ltr informing NRC of revised schedule for fuel load & commercial operation fuel load scheduled for 840815 Commercial operation planned for 850215 Svc list ench RIDGMAY, D.A. Shaw, Pittman, Potts & Trowbridge RIDGMAY, D.A. Kansas Gas & Electric Co. 83/06/15 LAURENSON, J.A., ANDERSON, O.C., PAXTON, H.C. Atomic Safety and Licensing Board Panel App. 18899 300 24X Fiche 50-482, 83/06/15, 8306200312
- 8306220082 Forwards map depitting location & range of warning sirens recommended for alert & notification sys.as part of rept served on 830613 Bvc list encl W/o map RIDGHAY.D A Shaw. Pittman, Potts & Trowbridge RIDGHAY,D.A Kansas Gas & Electric Co 83/06/15 LAVRENSON.J.A. PAKTON.H C. ANDERSON.D C. Atomic Safety and Licensing Board Panel. 3pp 18930 154. 24% Fichs 50-482.83/06/15.8306220082
- B306230358 Forwards revised pages modifying compilation of intervenor interrogatory responses Certificate of Svc and Related correspondence RIDGMAY, D. A. Shaw, Pittman, Potts & Trowbridge RIDGMAY, D. A. Kansas Gas & Electric Co B3/06/21 LAURENSON, J. A. ANDERBON, Q.C., PAXTON, H.C. Atomic Safety and Licensing Board Panel 12pp 18943-319 24X Fiche 50-482, B3/06/21, B306230358
- 8306290522 Responds to applicant collation of intervenor interrogatory responses, submitted in 830643 ltr Bome responses will be amended Listed amends not agreed upon Svc list and Related correspondence SIMPSON, J M 81mpson, J M 81MPSON, J M Affiliation Unknown 83/06/22 LAURENSON, J A , ANDERSON, C C., PAXTON, H C Atomic Safety and Licensing Deard Panel App 19052-203 24X Fiche 50-402,83/06/22,8306290522
- 8306280514 Forwards Change Page 7, for insertion into 830613 compilation Svc list encl RIDGMAY,D A Shaw, Pittman, Potts & Trowbridge 83/06/24, LAURENSON,J A, ANDERSON,G C, PAXTON,H C Atomic Safety and Licensing Board Panel 4pp 19017 234 24X Fiche 50-482,83/06/24,8306280514
- B306300138 Forwards SER Suppl 2.(NUREO-0881) W/o enc)
 KARMAN.M Hearing Iranch 1 83/06/28 LAURENSON.J A. PAXTON.H C.
 ANDERSON, C Atomic Safety and Licensing Board Panul 1p
 19168 118 24X Fiche.50-482.83/06/28.8306300138
- K Utility Final Bafety Analysis Report (FBAR) & amends
- B306060191 Forwards Rev 10 to FSAR (filed in PDR Category K) & Rev 10 to radiological emergency response plan (filed in PDR Category F) Certificate of Bvc encl KdESTER.0 L Kansas Gas & Electric Co B3/05/31 DENTON, H R. Office of Nuclear Reactor Regulation. Director 10pp. 18720:001 24X Fichs 50-482, B3/05/31, B306060191
- --8306060194 Rev 10 to FSAR * Kansas Gas & Electric Co 83/04/30 483pp. 18720:010, 24X Fichs 50-482.83/05/31.8306060191
- Q Inspection reports, IE Bulletins & correspondence
- 8306140354 Confirms Region IV plan to perform independent NDE verification insp on 830606-17 Addl info on documentation selected for insp encl GAGLIARDD, J E Division of Resident, Reactor Project & Engineering Programs 83/05/11 KDEBTER, G L. Kansas Gas & Electric Ca 6pp 18832 186 24% Fiche 50-482,83/05/11,8306140354
- 8306140245 Forwards IE Insp Rept 50-482/83-08 on 830418-22 No noncompliance noted 8EIDLE, W C Region 4, Office of Director 83/05/13 KOESTER, Q L. Kansas Gas & Electric Co 2pp 18833 005 24X Fiche 50-482,83/05/13,8304140245
- --8306140249 IE Insp Rept 50-482/83-08 on 830418-22 No noncempliance noted Major areas inspected safety-related piping sys for selection of welds for NRC independent insp program GILBERTLL D., JOHNSON, W. D., HUNNICUTT, D. M. Region 4, Office of Director 83/05/13 4pp 18833:007 24X Fiche 50-482,83/05/13,8306140245

- 8306130393 Responds to NRC 630422 ltr re violations noted in IE Insp Rept 50-482/83-07 Corrective actions listed Daniel Const Cn procedures/activities revised to include definite test control criteria per Corrective Action Rept 1-0-0024 KOESTER, 0 L Kansas Gas & Electric Co 83/05/20 SEIDLE, W C Region 4, Office of Director Jpp 18922 216 24X Fichs 50-482,83/05/20.8306130393
- 8306140207 Forwards IE Insp Rept 50-482/83-11 on 830401-30 & notice of violation SEIDLE, W C Region 4. Office of Director 83/05/20 KOESTER, & L Kansas 9ps & Electric Co 2pp 18832 264 24X Fichs 50-482, 83/05/20, 8306140207
- --8306140212 Notice of Violation from insp on 830401-30, # Region 4, Office of Director 83/05/20 ip 18832 266 24X Fiche 50-482,83/05/20,8306140207
- --8306140220 IE Insp Rept 50-482/83-11 on 830401-30. Noncompliance noted failure to follow procedures re QC insp checklist for two auxiliary feedwater sys spring hangers ECHUM, M 8 . JOHNSON, M D Region 4, Office of Director 83/05/19 Spp 18832 247 24% Fiche 50-482, 83/05/20, 8306140207
- 8305110458 IE Info Notice 83-32. "Ruptured Am-241 Sources Contained in Well Logging Device" Svc list encl
 TAYLOR, J M Division of Safeguards & Inspection Programs (Post
 830103) 83/05/24 Consolidated Edison Co of New York, Inc
 125pp 18831 043 24X Fiche 50-000, 83/05/26, 8305110458
- 8305110460 IE Info Notice 83-34, "Event Notification Info Worksheet" 8vc list and JORPAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc. 115pp 18732-085 24X Fiche 50-000,83/05/26,8305110460
- 8305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods Withdrawn at BWRs " Svc list encl JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/31 Consolidated Edison Co of New York, Inc. 116pp 18732 208 24X Fichs 50-000, 83/05/31, 8305110461
- 8306270088 Informs that response to notice of violation contained in IE Insp Rept 50-482/83-10 will be submitted by 830684 KOESTER.9 L Kensas Gas & Electric Co 83/06/03 SEIDLE,W C Region 4, Office of Director 1p 18793-042 24X Fichs 50-482,83/06/03.8306270088
- B3060B01B4 Ack receipt of B30520 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-482/83-07 Program to control all aspects of contractor testing should be developed at earliest practicable time SEIDLE:W C. Region 4. Office of Director B3/06/06 K0EBTER:G L Kansas Gas & Clectric Co ip 18770 359 24X Fiche 50-482; 83/06/06.83060B0184
- c-8306080188 Responds to NRC 830422 lth re violations noted in 1E Insp Rept 50-482/83-07 Corrective actions procedures/activities identified will be revised to include definitive test control criteria KOE8TER.@ L. Kansas Gas & Electric Co. 83/05/20 SEIDLE, W. C Region 4, Office of Director 3pp. 18770 360 24X Fiche 50-482,83/06/06.8306080184
- 8305110464 IE Info Notice 83-36, "Impact of Security Practices on Safe Operations " Svc list encl JORDAN E.L Division of Emergency Preparedness & Engineering Response (Post 830103). B3/06/07 Consolidated Edison Co. of New York, Inc. 119pp. 16830 280 24X Fichs. 50-000, 83/06/09, 8305110464
- 8305110470 IE Info Notice 83-38, "Defective Hest Sink Adhesive & Seismically Induced Chatter in Releys Within Printed Circuit Cards " Svc list enc! JGRDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/12. Consolidated Edison Co. of New York, Inc. 118pp. 18920, 225 24X Fiche 50-000, 83/06/13,8305110470
 - 100 IE Info Notice 83-97, "Transformer Failure Resulting From ad Internal Connection Cables." Svc list enc!
 .E.L. Division of Emergency Preparadness & Engineering 83/06/13 Consolidated Edison Co. of New 24X Fiche 50-000, 83/06/13, 8306090010

'nvironmentalle Qualife

Iness & Engineering Hidated Edison Co. of New 10-000,83/06/22,8305110478

- 8305110477 IE Info Notice 83-41, "Actuation of Fire Suppression type Causing Inoperability of Safety-Related Equipment" See list and JORDAN, E. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/22 Consolidated Edison Co. of New York. Inc. 120pp 18997 007 24X fichs 50-000,03/06/22,838911047
- 8305110479 IE Info Notice 83-42, "Reactor Mode Switch Malfunctions "
 Svc list encl
 JDRDAN,E L Division of Emergency Preparedness & Engineering
 Response (Past 830103) 83/06/23 Consolidated Edison Co of New York, Inc 116pp 18996 242 24X Fiche 50-000.83/06/23.0]05110479
- 8305110483 IE Info Notice 83-49. "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints " Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/24 Consolidated Edison Co. of New York, Inc. 114pp 19046-29/ 24X Fichs 50-000.83/06/24,8805110401
- S Reportable occurrences, LERs & related correspondence
- 8306230277 Part 21 rept re defect in hose assembly 7/379 Assumbly welded w/60-degree rather 30-degree elbow installed Condition reported to Rechtel BHAFER, J C Metal Bellows Corp 83/05/09 COLLINS, J T Region 4, Office of Director 4pp 18945 138 24X Fiche 50-000, 83/05/09, 8306230277
- 8306030220 Final Part 21 rept re deficiency in DS-416 reactor trip switchgear undervoltage attachment (SDR-83-07) Initially reported on 830421 Attachments to be replaced Also reported by Westinghouse per Part 21 SEIKEN, S J Standardized Nuclear Unit Power Plant System 83/03/23 KEPPLER, J 9 Region 3, Office of Director COLLINS, J T. Region 4, Office of Director 3pp 18/03/28/24X Fiche 50-000,83/05/24, 8306030220
- 8306070194 Interim deficiency rept re welds on Bergen Paterson sway struck Initially reported on 830224 Majority of welds evaluated No adverse safety concerns identified Next rept will be submitted by 830718 KOESTER.0 L. Kansas Gas & Electric Co. 83/05/26 SEIDLE.W C. Region 4, Office of Director 1p. 18/56 298 24X Fiche 80-482,83/05/26,8306070194
- 8304070262 Interim deficiency rept re loose parts in steam generators Initially reported on 830426 Mestinghouse evaluation of safety implications underway Status rept will be submitted by 830815 KGESTER, O. L. Kansas Gas & Electric Co. 83/05/26 SCIDLE, W. C. Region 4, Office of Director 2pp. 18/40-337 PAX fiche.50-482,83/05/26.8306070242
- 8306070345 Final significant deficiency rept re lockup of RM-P3 display in radiation monitoring sys Initially reported on 830223 Circuit boards returned to vendor for mod & testing Modified boards will be installed prior to fuel load. SEIXEN 8 J Standardized Nuclear Unit Power Plant Bystem 83/05/2/KEPPLER, J G Region 3, Office of Director COLLINS, J T Region 4. Office of Director 7pp 18/42 145 24X Fiche 50-482,63/05/27.
- 8306100183 final Deficiency Rept 83-01 re faulty Westinghouse EMD gate valve position indication Initially reported on 830121 Valve mads & adjustments to be performed per Westinghouse Field Change Notices SAPM-10605 & SCPM-10602 PERRICK, N.A. Standardized Nuclear Unit Power Plant System 83/05/31 COLLINS, J.T. Region 4. Office of Director KEPPLFR, J.O. Region 3. Office of Director Spp. 18005 285 24X Fiche. 50-000, 83/05/31.8306100183
- 8306090231 Interim deficiency rept re inadequate matl control for special scope items Results of numerous insps. tests & document reviews tabulated & will be sprt to AE within 2 wks for final evaluation Next rept expected by 830901 KOESTER, O L Kansas Gas & Electric Co 83/06/01 SEIDLE, W. C Region 4. Office of Director 1p 18/96 238 24X Fiche. 50-482,83/06/01.8306090231
- 8306130138 Interim deficiency rept re workmanship on Swagelok fittings Initially reported on 830215 Info obtained from insps & testing of various tubing installations transmitted to AE for evaluation Next rept will be submitted by 830808 KOESTER. Q L. Kansas Gas & Electric Co. 83/06/03 SEIDLE. W C. Region 4, Office of Director. ip 18024-281 24X Ficher 50-482,83/06/03,8306130138
- 8306160865 Final deficiency rept re use of Teflon tape in instrument lines Initially reported on 830504 List of sys where use of Teflon tape or compound could have potentially adverse implications being developed KOESTER, O. L. Kansas Gas & Electric Co. 83/06/03 SEIDLE, W.C. Region 4. Office of Director. 2pp 18866:103 24X Ficha 50-482.83/06/03.8306160565

- @306100125 Past 21 rept re incorrect assembly of Vitro Labs 125-velt battery monitor used at site Faulty Jener diode will cause emotion to issue battery failure indication DIXON.D J General Electric Co 83/06/06 DEYOUNG.R C Director's Office. Office of Inspection and Enforcement ip 18802 010 24X Fiche 50-482,83/06/06.8306100125
- 8306130043 Fourth interim deficiency rept re diesel generator bolt torque Initially reported on 820614 Retorquing of diesel stud/nut combinations completed Results forwarded to manufacturor for evaluation Next rept expected by 830801 KOESTER, O L. Kansas Gas & Electric Co. 83/06/06 SEIDLE, W.C. Region 4. Uffice of Director 1p. 188-4 247 24% Fiche 50-482,83/06/06.8306130043
- 8306160415 Final deficiency rept re containment spray/RHR motor oil feaming Foaming observed in ail sight gauges determined to be normal Condition not reportable per 10CFRSO 55(e) KOESTER. & L. Kansas Gas & Electric Co. 83/06/10 SEIDLE. W C. Region 4, Office of Director ip 18859-309 24% Fiche 50-402,83/06/10.8306160415
- \$306170386 Final deficiency rept or diesel generator thermostatic valves Initially reported on 820622 Valves reworked & found free of potential defect Valves replaced w/unit containing overeum assembly utilizing cotter pin KOESTER. © L. Kensas Gas & Electric Co. 83/06/13 SLIDLE. W.C. Region 4, Office of Director 1p. 18800 053 24% Fiche 50-482.83/06/13,8306170386
- 8306270352 Final deficiency rept re component testing OA program Initially reported on 830209 Revised procedures reviewed No descrepancies identified Component test program resumed Condition withdrawn as potential 100FR60 55(e) item MOESTER. & L. Kansas Oas & Electric Co. 83/06/17 SEIDLE, W.C. Region 4. Office of Director ... Pp. 18793 149 24% Fiche 50-492,83/06/17,83062/0352
- 9306280335 Interim deficiency rept re insufficient torque on structural steel bolted connections Initially reported on 830204 Corrective Action Rept 1-C-0026 initiated to tract evaluation & resolution of problem Next rept by 830909 MOESTER.6 L Kansas Cas & Electric Co 83/06/20 961DLE.W C Region 4, Office of Director 2pp 19001 310 24X Fiche 50-482,83/06/20,8306280335
- DOCKET STN-50-483 CALLAWAY PLANT, UNIT I
- A Application/construction stage documents & correspondence
- 93D6060393 Responds to 830509 request for permission to use Peragraph NX-4427 of Winter 1982 Addenda to Section III of ASME Boiler & Pressure Vossel Code re fillet weld requirements Request acceptable
- YOUNDBLOOD, B J Licensing Branch 1 83/05/26 KDESTER, G L Kansar Pas & Electric Co SCHNELL, D T Union Electric Co Jpp. 18748 359 24X Fiche 50-000.83/05/26.8306060383
- 3304080051 Forwards request for addl info re environ qualification plan Info requested within 2 wks of receipt of ltr YOUNOBLOOD, D. J. Licensing Branch i 83705731 BCHNELL, D.F. Unson Electric Co. KOESTER, C.L. Kansas Gas & Electric Co. App 18787-308 24X Fiche 50-000,83705731,8306080051
- B306080438 Notification of 830617 meeting w/util in Bethesda.MD to discuse clarifications to GA program EDISON,O E Licensing Branch I 83/06/01 YOUNGBLOOD, B. J Licensing Branch I 4pp 18/92 209 E4X Fiche 50-48J,83/06/01, 8306080438
- COCCEORCE Notification of B30620 & 24 mostings w/utils & BNUPPS in Highway, MO & Burlington, KB, respectively, to discuss environ qualification of equipment ED180N, G E Licensing Branch 1 B3/06/02 YdUNGBLOOD, B J. Licensing Branch 1 5pp 18789 350 24X Fiche 50-000, 63/06/02, B306080321
- COUNTY Forwards revised draft versions of, "Cultural Resources Mgt Plan for Residual Lands" & "Phase i Cultural Resources Survey & Assessment to Residual Lands" & responses to SHPO comments
 SCHNELL, D. F. Union Electric Co. 83/04/03 DENTON, H. R. Office of Nuclear Reactor Regulation. Director 44pp 18607-237. 24X
 Fiche 50-483,83/04/03,8304100147
- -830610014B Revised draft of, "Cultural Resources Mgt Plan for Residual Lands at union Electric Co " * Union Electric Co 83/06/03 49pp 18807 281 24X Fiche 50-483.83/06/03.8306100147

- --8306100152 Revised draft of, "Phase i Cultural Resources Survey & Assessment to Residual Londs at Union Electric Co Callaway Nuclear Power Plant" RAY, J H., MORLIN, E M., MCNERNEY, M J American Resources Group, Ltd 83/04/03 495pp 18807 332 P4X Fiche 50-483,83/06/03,8306100147
- 8306220018 Forwards add1 info re environ qualification of safety-related electrical equipment, in response to NRC 830531 ltr
 FSAR will be updated in next rev to include questions & responses
 PETRICK, N A Standardized Nuclear Unit Power Plant System 83/06/10 DENTON, H R Office of Nuclear Reactor Regulation, Director 4pp 18927 318 24X Fiche 50-000:83/06/10.8306220018
- F Security, medical, emergency & fire protection plans
- 8306150454 Releases public version of revised emergency plan administrative procedure FELTON, JM Division of Rules and Records, 83/06/06 Document Management Branch 1p 18869 148 24% Fiche 50-483, 83/06/06.
- --8306150455 Public version of Rev O to Emergency Plan Administrative Procedure APA-ZZ-00102. "Emergency Operating Procedures Writers Guide." Item numbers on encl correspond to numbers used in Generic Ltr 82-33 W/93051i ltr 8COTT,W G : SCHNELL,D F Union Clectric Co 83/04/07. DENTON,H R Office of Nuclear Reactor Regulation, Director 49pp. 18869 149 24X Fiche 50-483,83/06/06,8306150454.
- 8306170473 Responds to SNUPPS 810601 & util 821203 ltr re primary & backup emergency operations facilities (EDF) Location of primary & backup EDF approved. Approval of addl features to be determined during post-implementation apprecial EISENHUT.D © Division of Licensing 83706/06 BCHNELL.D F Union Electric Co 3pp 18874 335 24X Fiche 50-483.83/06/06.8306170473
- 8306230474 Forwards SALP Rept 50-483/83-09 for Oct 1981 Sept 1982 Overall performance satisfactory Tissue re emergency planning ione resolved. KEPPLER, J G Region 3, Office of Director 83/06/20 SCHNELL, D.F. Union Electric Co 2pp 18941 160 24X Fiche 50-483, 83/06/20, 8306230476
- --8306230481 Clarifies Page 9 of SALP Rept 50-483/83-09 transmitted by NRC 830126 ltr re licensing activities to reduce size of emergency planning zone (EPZ) excluding two eastern most countries Reduction of EPZ not formally requested SCHMELL-D F Union Electric Co 83/02/23 HIND. J. A Division of Emergency Preparedness & Operational Support 1p. 18941, 184, 24X Fiche 50-483.83/06/20.8306230476.
- O Adjudicatory correspondence
- 8304010146 Informs that author will represent NRC in 830622 oral argument in response to ASLAB 830429 order PERLIS.R.O Hearing Branch 3 83/05/27 SHDEMAKER.C J Atomic Safety and Licensing Appeal Panel. 1p 18674 050 24% Fiche 50-483.83/05/27.8304010146
- 8306030331 Motion & response to applicant 830520 motion for summary disposition of JQ Reed Contentions 1 through 11 & 13 through 20 Applicant motion should be denied since matl facts should be heard W/Certificate of Svc.

 REED, J G. Reed, J G 83/05/31 Atomic Safety and Licensing Board Panel 17pp 18707 001 24X Fiche 50-483,83/05/31.8306030331.
- 8306100045 Motion for extension until 830617 to respond to util 830520 20 motions for summary disposition Large number of filings creates undue burden Negotiations initiated to dispose of contentions Certificate of Syc sncl.

 ODDDARD, R. J. Hearing Branch 3 83706/08 Atomic Safety and Licensing Board Panel 4pp 18802 115 24X Fiche: 50-483,83706/08,8306100045
- 8306150287 Order granting NRC request for extension until 830617 to file responses to pending motions for summary disposition. QLEASON, J.P. Atomic Safety and Licensing Board Panel 83/06/10 Office of the Executive Legal Director ip. 18849:173, 24X Fiche 50-483,83/06/10,8306150287
- 8306160314 Answer to JO Reed 830531 motion & response to applicant motion for summary disposition of JO Reed contentions. Temporary funding of GM Stanfill position irrelevant & accusation of blus w/o foundation. Certificate of Svc sncl. BAXTER. T.A. Union Electric Co BAXTER. T.A. Shaw. Fittmen. Potts & Troubridge 83/06/13. Atomic Safety and Licensing Soard Panel. 4pp 18860 048. 24X Fiche: 50-483,83/06/13,8304160314.

- --8306160322 Affidavit of WR Bebtty informing of erroneous statements in JG Reed 830531 filing on status of GW Stanfill Stanfill is not util employee Util temporarily funds position but giercises no control over position BEATY,WR Union Electric Co BEATY,WR Missouri, State of 83/06/10 App 18860 052 24X Fiche 50-483,83/06/13,8306160314
- 8306210266 Advises of partial settlement re Reed contentions on emergency planning Sattlement discussions will be held on Contentions 4 II & 15 Hearings will be held on Contentions 6 to Remaining contentions will be withdrawn PERLISIR Q Hearing Branch 3 83/06/17 QLEASON, J P , KLINE, J R , 88/04/17, 0 D Atomic Safety and Licensing Board Panel 2pp 18919 031 24X Fiche 50~483,83/06/17.8306210266
- --8306210271 Sattlement agreement re disposition of Reed contentions & util motions for summary disposition Util agrees to withdraw motions re Contentions & & 16 Neeting scheduled for 830623 or 24 to settle Contentions 4,11 & 15 Draft order encl PERLIS.R 9 Hearing Branch 3 83/06/16 4pp 18715 033 24X Fiche 50-483,83/06/17,8306210266
- 8306220132 Forwards settlement agreement executed by util
 BAXTER.T A Shaw, Pittman, Potts & Trowbridge BAXTER.T A Union
 Electric Co 83/06/20 GLEASON, J.P., BRIGHT, G.O., KLINE, J.R.
 Atomic Bafety and Licensing Board Panel 1p 18924 152 24X
 Fiths 50-483,63/06/20,8306220132
- --8306220137 Sattlement agraement executed by util re disposition of J Reed contentions Util will withdraw motion for summary disposition of Reed Contentions 6 & 16 Parties will attempt to settle Contentions 4,11 & 15 Syc list encl BAYTER, 7 A Union Electric Co 83/06/20 3pp 18726 153 24X Fiche 50-483,83/06/20.8306220132
- B306230344 Bettlement agreement re disposition of J Reed contentions & util motions for summary disposition Util will withdraw motions for summary disposition of Contentions & 16 Gertificate of Svr encl REED, J O Reed, J O B3/06/20 3pp 18942,276 24X Fiche 50-483,83/06/20,8306230344
- 8306270137 Order ratifying settlement agreement of parties Util motion for summary disposition of Reed Contentions 6 & 16 dismissed Reed Contentions 1, 2, 3, 5, 7, 8, 7, 10, 13, 14, 17, 18, 19 & 20 dismissed NRC responses to motions due 833701 QLEASON, J P Atomic Bafety and Licensing Board Panel 83706/23 Union Electric Co ip 18988, 152 24X Fiche 50-483, 83/06/23, 8306270157
- G Inspection reports: IE Bulletins & correspondence
- 8306030180 Forwards IE Insp Rept 50~483/83~06 on 830411-14 No noncompliance noted. LITTLE W 8, Region 3, Office of Director 83/05/20 SCHNELL, D F Union Electric Co 2pp 18704 607 D4X Fiche 50~483,83/05/20, 8306030180
- --8306030185 IE insp Rept 50-483/83-06 on 830411-14 Na noncompliance noted Major areas inspected 100FR50 95(e) items. IE bulletins. 100FR21 item. circulars. RCPB piping, review of quality records & work activities WARD, K D , DANIELSON, D H Region 3, Defice of Director 83/05/20 12pp 18704 009 24X Fishs. 50-483, 83/05/20, 8306030180
- 8304040241 Forwards IE Inap Rept 50-483/83-05 on 830301-0415 & notice of violation
 KNOP,R C Region 3, Office of Director 83/05/20 SCHNELL, D.F Union Electric Co 2pp 18727 281, 24X Fiche, 50-483,83/05/20,83060241
- --8304040242 Notice of viglation from insp on 830301-0415 MNOP, R C Region 3, Office of Director 83/05/20 2pp 18727-283 24% Fiche 50~483,83/05/20,8304040241.
- ~-8306060244 IE Insp Rept 50-483/83-05 on 830301-0418 Noncompliance noted untimely audit response, inadequate procedures & inadequate delineation of authorities & responsibilities NEISLER, J H. KONKLIN, J E. Regies 3, Office of Director 63/05/20 6pp. 18727 285 24X Fiche 50-483,83/05/20 8306060241
- 8306100162 Forwards IE Insp Rept 50-483/83-08 pn 830426-28 No noncompliance noted STREETER J F Region 3, Office of Director 83/05/23 SCHNELL D I Union Electric Co 2pp. 18805-128 24X Fiche 50-483,83/05/23, 8306100162
- ~~8306100169 IE Insp Rept 50-483/83~08 on 830426~28 No noncompliance noted, Major areas inspected preparation & implementation status of licensee operational GA program.

 HABBE, R A , HAMKINB, F C Region 3, Office of Director 83/05/23 3pp. 18805 130 24% Fiche 50-483,83/05/23,8306100162

- 9306100165 Forwards IE Insp Rept 50-493/87-0/ on 830426-28 No noncompliance mated PAPERIECLOUC J. Region 3. Office of Director 83/05/25 SCHWELL, D.F. Union Electric (o. 2pp. 18001 198 24% Fiche 50-483,83/05/25.8306100165
- --8306100167 IE Insp Rept 50-481/83-07 on 830426-28 No nuncompliante noted Major areas inspected preoperational radiological environ monitoring program, including mgt controls, QA & siti tour ROZAM, S. OESTMANN, M. J. SCHUMACHER, M. C. Region D. Office of Director 83/05/25 Spp 18801 200 24X Fishu 50-483,83/05/25,8306100165
- 8305110458 IE Info Notice 83-32. "Ruptured Am-241 Sources Contained in Well Lagging Dovice" Svc list encl TAYLOR, J M Division of Safeguards & Inspection Programs (Post B30103) B3705726 Consolidated Edison Co of New York, Inc 125pp 18831 043 24X Fiche 50 000 84/05/26,8305110458
- 8305110460 IE Info Notice 83-34, "Event Notification Info Workshret"
 Syc list encl
 JORDAN, E. L. Division of Emergency Preparedness & Engineering
 Response (Past 830103) 83/05/24 (Ansolidated Edison Co. of New
 York, Inc. 11988 18732-085 P4X Fiche 50-000,83/05/26,8305110460
- 8305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods Withdrawn at BWRs " Svc list (nc) JORDAN,C L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/31 Consolidated Edison Co of New York, Inc 116pp 18732 208 24X Fiche 50-000,83/05/31,8305:10461
- 8304070137 Ack receipt of 830518 ltr informing NRC of steps taken to correct violations noted in 1E Insp Rept 50-483/83-08 Submittal of test procedures per FSAR (hapter 14 required 60 days prior to test performance SPESSARD.R L. Division of Engineering 83/06/01 SCINELL.D F Union Electric Co. 10 18709-216 24X Fiche 50-483,83/06/61. 8306070137
- --8306070145 Responds to NRC 830418 ltr re violations noted in IF lesp Rept 50-483/83 02 Corrective actions minor change notice added to CS-03EPOI to ensure recording of accumulator temps in text log prior to repressure recording of SCHNELL, DF Union Electric Co 83/05/18 SPESSARD, R L Division of Engineering 2pp 18739 217 24X Fiche 50-483/83/06/01.8306070137
- 8305i10464 IE Info Notice 83-36, "Impact of Security Practices on Safe Operations " Syc list encl JORDAN, E.L. Division of Emergency Proparadness & Engineering Response (Post 830103) 83/06/09 Consolidated Edison Co. of New York, Inc. 119pp 18830 280 24X Fiche 50-000,83/06/09.8305i10464
- 9305110470 IE Info Notice 93-38, "Defective Heat Sink Adhesive & Seismically Induced Chatter in Relays Within Printed Circuit Cards " Sve list ent JORDAN, E.L. Division of Emergency Proparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co of New York, Inc. 118pp 18920 225 24% Fiche 50-000, 93/06/13.03061104/0
- 8304090010 IE Info Notice 83-37, "Transformer Failure Resulting From Degraded Internal Connection Cables" Svc list encl JORDAN, C. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83706/13 Consolidated Edison Co. of New York, Inc. 243pp 18721 001 24X Fiche 50-000,83706/13,8306090010
- 8306210187 Ack receipt of 830603 ltr informing NRC of steps taken to correct violations noted in IL Insp Rept 50-483/82-20 SPESSARD, R L Division of Engineering 83/06/14 SCHNELL, D f Union Electric Co ip 18914 172 /4X Fiche 50-483,83/06/14.8306210187
- --8306210198 Responds to NRC 830315 ltr re violations noted in IF Ensp Rept 50-483/82-20 Corrective actions piping seismic analyses performed on snubbers to identify ineffective areas & overstressed piping Equipment notices acceptable SCHNELL.D F Union Electric Co 83/06/03 LITTLE, W. A Region 3. Office of Director 7pp 18914 123 24X Fichs 50-483,83/06/14, 8306210187
- 8306230476 Forwards BALP Rept 50-483/83-09 for Oct 1981 Sept 1982
 Overall performance satisfactory Issue re emergency planning
 zone resulved
 KEPPLER, J G Region 3, Office of Director 83/06/20 SCHNELL D F
 Union Electric Co 2pp 18741 160 24X Fiche 50-483,83/06/20.
- --8306230477 SALP Rept 50-483/83-09 for Oct 1981 Bept 1982. * Region 3, Office of Director 83/06/20 19pp 18941 168 F4X Fiche 50-483/83/06/20,8306230476

- --B30A230481 Clarifies Page 9 of SALP Rept 50-483/83-09 transmitted by NRC B30126 ltm me licensing activities to reduce size of emergency planning zone (EPZ) excluding two eastern most countres Reduction of EPZ not formally requested SCHNELL DF Union Electric Co. B3/02/23 HIND, J A. Division of Emergency Preparedness & Operational Support 1p 18941-184 24X Fiche 50-483, 83/06/20, 8306230476
- B306300170 Forwards 1E Insp Rept 50-483/83-11 on 830416-0531 & notice of violation
 KNOP, R C Region 3. Office of Birectol 83/06/20 SCHNELL, D F Union Electric Co 2pp 1912P 056 P4X Fiche 50-483, 83/06/20, 8306300170
- --9306300182 Notice of violation from insp on 830416-0531 KNDC,R C Region 3. Office of Director 83/06/17 1 19122 058 24X Fiche 50-483,83/06/20,8306300170
- --B3G6300186 IE Insp Rept 50-483/83-11 on 830416-0531 Noncomplicance noted failure of insp program to adequately identify broken & missing parts on safety-related pipe supports NEISLER, J H , KONXLIN, J E Region 3, Office of Director. 833/06/17 6pp 19122 059 24% fiche 50-483,83/06/20.8306300170
- e305110475 IC Info Notice 83-40, "Need to Environmentally Qualify Epoxy Grouts & Sealers " Svc list enc! JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/22 Consolidated Edison Co of New York, Inc 115pp 19021 179 24X Fiche 50-000, 83/06/22, 8305110475
- O30 5110477 IE Info Notice 83-41. "Actuation of Fire Suppression Sys Causing Inoperability of Safety-Related Equipment " Syc list encl.

 JGRDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/22 Consolidated Edison Co. of New York, Inc. 120pp 18997 007 24X Fiche 50-000, 83/06/22, 8305110477
- B305110479 IE Info Notice B3-42, "Reactor Made Switch Malfunctions" Svc list encl.
 JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post B30103) 83/06/23 Consolidated Edison Co. of New York, Inc. 114pp 18996 242 24X Fiche 50-000, 83/06/23, 8305110479
- 8305110483 IE Info Notice 83-43, "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints "Svc list encl JGRDAN, E.L Division of theorency Proparedness & Engineering Response (Post 830103) 83/06/24 Consolidated Edison Co of New York, Inc 116pp 19046 297 24X Fiche 50-000,83/06/24,8305110483
- OBOAGODOBA Ack receipt of 830615 ltr informing NRC of steps taken to correct violations noted in 1E Insp Rept 50-489/83-05
 KNOP, R. C. Region 3, Office of Director 83/06/27 SCHNELL, D.F.
 Union Electric Co. 1p 19048 249 24X Fichs 50-483, 83/06/27,
 B306300084
- --8306300090 Responds to NRC 830520 ltr re violations noted in IE Insp Rept 50-483/83-03 Corrective actions test program surveillance group program being revised to upgrade & establish requirements for witnessing test activities SCHNELL,D F Union Electric Co 83/06/15 KNOP,R C. Region 3, Office of Director 4pp 19048 250 24X Fiche 50-483.83/06/27, 8306300084.
- 8 Reportable occurrences, LFRs & related correspondence
- 8306230277 Part 21 rept re defect in hose assembly 77379 Assembly welded w/60-dagree rather 30-degree allow installed Condition reported to Bechtel SHAFER, J C Metal Bellows Corp 83/05/09 COLLINS, J T Region 4. Office of Director. App 18745 138 24x Fiche 50-000,83/05/09, 8306230277.
- 8304030220 Final Part 21 rept re deficiency in DS-416 reactor trip switchgear undervoltage attachment (SDR-83-07) Initially reported on B30421 Attachments to be replaced Also reported by Westinghouse per Part 21
 SEIKEN, 9 J. Standardized Nuclear Unit Power Plant Bystem 83/05/23 KEPPLER, J G Region 3, Office of Director COLLINS, J T Region 4, Office of Director 3pp 18/03 287 24% Fiche 50-000, 83/05/23, 83006030220

- 8306070345 Final significant deficiency rept re lockup of RM-23 display in radiation monitoring sys Initially reported on 830223 Circuit boards returned to vendor for mod & testing Modified boards will be installed prior to fuel load SEIKEN.S J Standardized Nuclear Unit Power Plant System 83/05/27 KEPPLER.J G Region 3, Office of Director COLLING.J T Region 4, Office of Director 7pp 18/42 145 24% Fishe 50-482.83/05/27, 8201037045
- 8306100183 Final Deficiency Rept 83-01 re faulty Hestinghouse EMD gate valve position indication Initially reported on 830121. Valve mods & adjustments to be performed per Hestinghouse Field Change Notices SAPM-10400 & SCPM-10602 PETRICK, N.A. Standardized Nuclear Unit Power Plant System 83/05/31 COLLINS.J.T. Region 4, Office of Director. KEPPLER, J.G. Region 3. Office of Director. 3pp. 18005.285 24X Fiche 50-000.83/05/31,8306100183
- 8304170279 Final deficiency & Part 21 Repts U-53 re defective plastic molding utilized in circuit boards supplied by Foxboro Co Initially reported on 830511 Components returned to vendor for rework/replacement SCHNELL.D F Union Electric Co 83/04/01 KEPPLER.J 0 Region 3. Office of Director Ip 18877 024 24% Fiche 50-483.83/04/01.
- 8306270235 Final Deficiency Rept U-54 & Pert 21 rept re failure of closed limit switches to reset on containment isolation valves HV-7126 & HV-7180 Initially reported on 830514 Compensating spring installed on actuating arm SCHNELL, D F Union Electric Co B3/06/14 KEPPLER, J 0 Region 3, Defice of Director 1p 18788 250 24X Fiche 30-483.83/06/16.
- T Hearing transcripts on non-antitrust matters
- 8306270074 Transcript of 830622 oral argument in Bethesda.MD Pp 1-83 * Atomic Safety and Licensing Appeal Panel 83/06/22 85pp. 19013 148 24% Fiche 50-483,83/06/22,8306270074
- DOCKET SO-494 MENTAGUE NUCLEAR POWER STATION, UNIT 1

 G Inspection reports, IE Bulletine & correspondence
- 8305110458 IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in Well Logging Device " Svc list encl. TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 125pp 18831 043 24x Fichs 50-000,83/05/26,8305110458
- 8305110460 IE Info Notice 83-34, "Event Notification Info Worksheet "
 Svc list encl
 JORDAN.E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/05/26 Consolidated Edison Co. of Now
 York, Inc 115pp 18732 085 24X Fiche 50-000,83/08/26.8305110460
- 8305110461 IE Info Notice 83-35, "Fuel Movement W/Control Reds Withdrawn at BWRs " Svc list encl JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/31 Consolidated Edison Co of New York, Inc 116pp 18732 208 24X Fiche 50-000,83/05/31.8305110461.
- 8305110464 IE Info Notice 83-36, "Impact of Security Practices on Safe Operations" Svc list enc!
 JURDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83706/09 Consolidated Edison Co of New York, Inc 119pp 18830 280. 24% Fiche 50-000.83/06/09.8305110464
- 8305i10470 IE Info Notice 83-38, "Defective Heat Sink Adhesive & Seismically Induced Chatter in Relays Within Printed Circuit Cards " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103). 83/06/13 Consolidated Edison Co of New York, Inc 118pp 18920 225 24X Fiche 50-000,83/06/13,8305110470
- 830 4070010 IE Info Notice 83-37, "Transformer Failure Resulting From Degraded Internal Connection Cables" Syr list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co. of New York, Int. 243pp 18721-001 24X Fiche 50-000, 63/06/13, 8306090010
- B309110475 IE Info Notice 83-40, "Need to Environmentally Qualify
 Epoxy Grouts & Sealers " Syt list and
 JORDAN, E L Division of Emergency Preparedness & Engineering
 Response (Post B30103) B3/06/22 Consolidated Edison Co

- 8305110477 IE Info Notice 83-41. "Actuation of Fire Suppression Sys-Causing Inoperability of Safety-Related Equipment " Syc list encl
 - entl JORDAN, E.L. Division of Loergency Preparedness & Engineering Response (Post 830103) 83/06/22 Consolidated Edison to of New York, Inc. 120pp 18997 007 24X Ficho 50-000,83/06/22,8305110477
- 8305110479 IE Info Notice 83-42, "Reactor Mode Switch Molfunctions " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/23 Consolidated Edison Co of Net York Inc 114pp 18996 242 24X Fishe 50-000,83/06/23,83051104/
- 8305110483 IE Info Notice 83-43, "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints " Svc list and JURDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83706/24 Consolidated Edison Co. of New York, Inc. 116pp 19046-297 24X Fiche 50-000, 03/04/24, 8305110483
- DOCKET SO-497 MONTAGUE NUCLEAR POWER STATION, UNIT 2 G Inspection reports. IE Bulletons & correspondence
- 8305110458 IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in Well Logging Device." Svc list encl TAYLOR. J.M Division of Safeguards & Inspection Programs (Post 830103) 83/05/26 Consolidated Edison Co. of New York. Inc 125pp 18831.043 24X Fiche 50-000,63/05/26.8305110458
- 8305110460 IE Info Notice 83-34, "Event Notification Info Worksheet " Notification at an annual state of Emergency Preparations & Engineering NoRDAN, E L Division of Emergency Preparations & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 118pp. 18732 085 24% Fiche 50-000, 83/05/26, 8305)10460
- 8305110461 IE Info Notice 83-35, "Fuel Novement W/Control Rads Withdrawn at DWRs " Svc list encl JORBAN E L Division of Emergency Preperedness & Engineering Response (Post 830103) 83/05/31 Consolidated Edison Co of New York, Inc 116pp 18732 200 24% Fiche 50-000.83/05/31.8308110461
- 8305|10464 IE Info Notice 83-36. "Impact of Security Practices on Safe Opprations "Svc list end of Company Propagations & Engineering Response (Post 830103) 83/06/09 Consolidated Edison Co. of New York, Inc. 119p 18830:280 24X Fichs 50-000 83/06/09,8306110464
- 8305110470 IE Info Notice 83-38, "Defective Heat Sink Adhesive & NOTION/O IL INFO NOTICE 83-38. "Defective Heat Sink Adhesiye & Seismically Induced Chatter in Relays Within Printed Circuit Cards " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co of New York, Inc. 118pp 18920 225 24X Fiche 50-000,83/06/13,8305110470
- 8306090010 IE Info Notice 83-37, "Transformer Failure Resulting From Degraded Internal Connection Cables" Svc list encl.
 JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83706/13 Consolidated Edison Co. of New York: Inc. 243pp. 18921-001 24X Fiche 50-000,83706/13,8306090010
- 8305110475 IE Info Notice 83-40, "Need to Environmentally Qualify Epoxy Grouts & Sealers." Syc list encl JORDAN, E.L. Division of Embigency Preparedness & Engineering Response (Post 800103) 83/06/22 Consolidated Edison Co of New York: Inc. 115pp. 19021 179. 24X Fishe 50-000,83/06/22,8305110475
- 8305110477 IE Info Notice 83-41, "Actuation of Fire Suppression Sys Causing Inoperability of Safety-Related Equipment" Svc list enci. JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/22 Consolidated Edison Co York, Inc. 120pp. 18997-007 24X Fiche: 50-000.83/06/22.8303 24X Fiche: 50-000, 83/06/28, 0305110477
- 8305110479 IE Info Notice 83-42, "Reactor Mode Switch Malfunctions "
- 8305110483 IE Info Notice 83-43, "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints "Eve list enel JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/24 Consolidated Edison Co. of New York, Inc. 116pp 19046-297 24X Fiche. 50-000, 83/06/24, 8305110483.

- DOCKET STN-50-498 SOUTH TEXAS PROJECT, UNIT I A Application/construction stage documents & correspondence
- 8306240059 Requests participation in pilot program concept contained in Public Law 87 415 Section 13 is QA lists bases to be used
- for planning purposet
 TAYLOR, J M Division of Safeguards & Inspection Programs (Post
 830103) 83/05/03 OPREA, G A Houston Lighting & Power Co 2pp
 18987 057 24% Fiche 30-498.03/05/03.0306240059
- 8306020024 farwards request for add) info re proposed deletion of emergency boration sys Response should be provided in amend form KNIGHTON, G W. Licensing Branch, B. 82/09/12 OPREA, G W. Houston Lighting & Power Co. Spp. 18/15 245 24X Fiche 50-498, 83/05/12, 8306020054
- --8112030545 Forwards Div of Sys. Integration safety evaluation of Westinghouse 1981 version of large break ECCS evaluation model, per NURES 0630 Revisions, per 100FR50. App K requested SPEIS, T P Assistant Director for Reactor Safety 81/11/02 TEDESCO. R L Division of Lirensing 1p 18715-250 24X Fiche 50-498.83/05/12,8306020024
- 8306200122 Forwards Rev 4 to GA program for design & const phase Nev does not reduce commitments contained in Rev 3 submitted on 820309 Affidayst encl OPREA, GW Hourton Lighting & Power Co 83/05/18 COLLING, J T Region 4
- --8306200126 Rev 4 to GA program for design % const phase * Houston Lighting & Power Co 83/05/18 300pp 18904 029 24t fiche 50-496.83/05/18.8306200122
- 8306140052 Advises that responses to FSAR Questions 32 42, "Less of Non-Class IE Instrument & Control Power Sys Bus During Operation" & 32 44, "Qualification of Control Sys" will be provided by May 1984 Delay due to extensive redesign effort GCLDDERG.J H Houston Lighting & Power Co 83/06/07 NOVAK, TH Assistant Director for Licensing 2pp 18838 286 24% Fiche 50-498,83/06/07,8306140052
- 8306200019 Summary of 830331 mosting w/utils & Westinghouse in Bethesda, MD re Westinghouse analysis & evaluation of D4/D5/E steam generator mod HOPKINS, J B Licensing Branch 4 83/06/14 Licensing Branch 4 22pp 18708 307 24% Fiche 50-000,83/06/14,8306200019
- 8306230440 Comments on NRC activities re load combinations & pipe break design Quidance on elimination of double-ended breaks & intermediate break postulations requested Meeting recommended
 ODLDBERG, J.H. Houston Lighting & Power Co. 83/06/17 DENTUN.H.
 OPfice of Nuclear Reactor Regulation, Director. 3pp. 18941 3/5
 24X Fiche 50-498,83/06/17,8306/30460 DENTUN-U R
- F Beturity, medical, emergency & fire protection plans
- 8306010350 Forwards IE Mgt Meeting Repts 50-498/83-05 & 50-499/83 05 on B30217-10 MADSEN, G L Region 4. Office of Director 85 Houston Lighting & Power Co 2pp 19502 145 Fiche 50-498, 03/05/25, 8304010350 83/05/95 OPREA. @ VI
- -8304010354 IE Mgt Meeting Repts 50-498/83-05 & 50-499/83-05 on 83021/-IB Hajor areas discussed emergency preparadness & tentative date for emergency preparadness & tentative fallowed meeting (ROSBMAN, W.A. Rugion 4, Office of Director BANGART, R. Division of Vendor & Terknical Programs 83/05/25 Jap 18682 147 24% Fiche 50-476,83/05/25,8306010350
- 8306070204 Forwards Amend 3 to security plan Amend withheld (ref 10CFR73 21) Rev 2 to security plan should be disposed of per appropriate safeguands procedurity of the procedurity of the security of the sec DENTON, N. N.
- Q Adjudicatory correspondence
- 8306080150 Forwards suppl to motion for new contention on processive recoveres supply to metion for new contention on stall financial qualifications & response to seventh set of util interrugatories Helated correspondence SINKIN.L. Citizens Concerned About Nuclear Power, Inc. 8J/06/02 BECHMORFER,C., LANBLJ,C., HILL, E. Atomic Safety and Licensing Board Panel, ip 18772 192 24X Fichs 50-498,83/06/02,8306080150

- --8304080155 Suppl to 830318 mution to admit new contention on util financial qualifications Adregate grounds for waiver of rule of financial qualifications review ortablished & good caure shown for late filing SINKIN.L A Citizens Concerned About Nuclear Power, Inc 83705/30 Atomic Safety and Licenting Board Panel 1Ppp 18772 193 PAX Fiche 50-476.83/04/04.8306080150
- --8306080159 Response to motion to compe) answers to seventh set of interrogatories, consisting of answers to interrogatories Centificate of Svc encl Related correspondence SINKIN, L A Citizens Concerned About Nuclear Power, Inc. 83706/02 Houston Lighting & Power Co. 14pp. 18772-205 24X Fiche 50-498.83/06/02.83060000100
- G306100200 Comments on Citizons Concerned About Nuclear Power 800602 itr & pleadings Certificate of Svc pncl NEWMAN,JR Lowenstein, Newman, Reis, Axelrad & Tall NEWMAN,JR Houston Lighting & Power Co. 83/06/08 DECHROEFER,C., LANN,JC., HILL.E E. Atomic Safety and Licensing Board Panel 5pp. 18305-306 24X Fiche 50-478,83/06/08,8304100200
- B306130427 Advises that time for Commission to review Director's Decision DD-83 05 expired Commission declined review Decision became Final agency action on 030606 CHILK, B J Office of the Secretary of the Commission B3/06/10 SINKIN:L Affiliation Unknown ip 10821 1/8 P4X Fiche 50-498,83/06/10,8306130427
- B306220057 Supplemental answer to seventh set of interrogatories & requests for production of documents are site location acceptability W/Cortificate of Syc Related correspondence SINKIN.L A Citizens Concerned About Nuclear Power, Inc. B3/06/13 Houston Lighting & Power Co. Spp. 10930-029 24X Fiche 30-498.83/06/13.8306280057
- 830620030B Advises that applicant does not intend to file motion to compel detailed answers from Citizens Concerned About Nuclear Power to applicant seventh set of interroquetorjes & requests to produce Effort would be fruitless, REMMAN, JR Lowenstein, Nowman, Reis, Axelrad & Toll NEWAN, JR Joint Applicants-Bouth Texas Project 83/06/15 DECHMOEFCR, C. LAHB, J C. HILL, E E. Atomic Safety and Licensing Monif Pancl. 4pp 18900 160 24X Fiche 50-499,83/06/15,8'06/20030B
- B30&270148 Memos andum & order granting util 830418 motion to compel Citizens Concerned About Nuclear Power answers to B30310 sixth set of interrogatories & requests for documents NRC directed to brief issues at earliest convenience BECH-NDETER, C Atomic Safety and Licensing Board Panel 83/06/22 Houston Lighting & Power Co Bpp 18908 041 24X Fiche 50-498,63/06/22.83062/0140
- 8306280583 Forwards.per request.Reg Quide 1 70 & NURFO-0800.Sections 2 3 1 W/o enris
 PERLISR 0 Hearing Branch 3 83/06/P7 DERWICK,B Texas, State of 1p 19017 324 24X Fiche 50-498.B3/06/27.8306280383
- K Utility Final Safety Analysis Report (FSAR) & amends
- 8306300077 Forwards effective page listing through Amend 31 for FBAR Listing to be considered formal addition to FBAR HIBENBURGIN R Houston Lighting & Power Co 83/06/22 NDVAK.T M Assistant Director for Licensing /Opp 19048 260 24X Fiche 50-498.83/06/22.8306300077
- M Antitrust correspondence
- 8308230127 Advises that documents produced by Qulf States Utils Co.in response to NRC subpoens.dostroyed VOOLER.B H Hearing Branch 2 83/06/P1 CLEMENTS.D N Gulf States Utilities Co Ip 18947 040 24% Firhe 50-000.83/06/21.0306230127
- @ Inspection reports. IE Bulletina & correspondence
- 8304080128 Forwards IE Insp Repts 50-498/83-04 & 50-499/83-04 on 830207-11 No noncompliance noted MADSEN, 6 L. Region 4. Office of Director 83/04/04 DPRCA, 6 W Houseon Lighting & Power Co. 2pp. 18/72 318 24X Fiche 50-498,83/04/04.8304080128
- --B3060B0133 IE Insp Repts 50-478/83-04 & 50-499/83-04 on 830807-11 No noncompliance noted Major areas inspected environ protection program during const.including organization & administration audits & compliance w/CP & FFS CHANEY, N D. MURRAY, B , CROSSMAN, W A Region 4, Office of Director 83/03/29 13pp 18772 3C0 24X Fiche 50-498,83/04/04,8306080128

- 8306080277 Add1 response to FOIA request for seven categories of records re Brown & Root. Inc & facilities App C Document 1 partially withheld (ref FOIA Exemption 7) App D documents withheld entirely (ref FOIA Exemption 5) FELTON, J M Division of Rules and Records 83/04/12 LINDEMAN, H N Commenstein, Nowman, Reis, Axelrad & Toll 4pp 18792 156 24X Fiche 50-498,83/04/12,8306080277
- --83060B0304 "Request for Investigation Concerning Alleged Advanced Notification," (nvestigation rept Info partially deleted SINCLAIR.J R Office of Inspector & Auditor 80/10/23 9pp 18792 160 24X Fiche 50-498.83/04/12/8306080277
- --B306080308 Forwards rept re alleged advanced notification to util or Brown & Root. Inc of Forthcoming Region IV investigation &/or alleger identities No further investigation contemplated W/o encl CUMMINGB. J. Office of Inspector & Auditor B0/10/24 AHEARNE. J.F. OILINEXY. V. HENDRIE. J. H. Commissioners ip 18792 169 24X Fiche 50-498.83/04/12.8306080277
- --8306080310 Forwards "Request for Investigation Concerning Alleged Advanced Notification" (ref 801024 memo) W/o ancl CUMMINGS, J J Diffice of Inspector & Auditor, 80/11/10 STELLO, V J Director's Office, Office of Inspection and Enforcement 1p 18772 170 24X Fiche 50-479,83/04/12,8306080277.
- 8306060056 Forwards IE insp Repts 50-498/83-08 & 50-499/83-08 on 830411-15 No noncompliance noted MADSEN, G.L. Region 4: Office of Director 83/05/18, OFREA, Q. W. Houston Lighting & Power Co. 2pp. 18717 258 24X Fiche 50-498/83/05/18/8306060056
- --8306060060 1E Insp Repts 50-498/83-08 & 50-499/83-08 on 830411-15. No noncompliance noted Major areas inspected const activities including deficient threads on site-fabricated anchor bolts, improper bolt matl & training records BOARDMAN, U.R., CROSSMAN, W.A. Region 4, Office of Director, 83/05/13 11pp 18719 260 24X Fiche 50-498.83/05/18.8306060056
- 8304060111 Forwards IE Insp Repts 50-498/83-02 & 50-499/83-02 on 830201-28 & notice of violation MADSEN. C L. Region 4. Office of Director 83/05/18 OPRCA. G W. Houston Lighting & Power Co. 2pp 18719 082 24X Fichs 50-498.83/05/18.8306060111
- --8306060116 Notice of violation from insp on 830201-28.

 * Region 4. Office of Director 83/05/18 2pp. 18719-084 24X
 Fichs 50-498.83/05/18.8306060111
- --B304040122 IE Insp Repts 50-498/B3-02 & 50-499/B3-02 on B30201-28
 Noncompliance noted.licensee unable to retrieve 9A records
 re site fabricated anchor bolts
 HILL, W H , BOARDHAN, J R , TOMLINSON, D P Region 4, Office of
 Director 83/05/13 40pp 18717-086 24X Fiche 50-498, B3/05/18,
 8304040111
- 8306010350 Forwards IE Mgt Meeting Repts 50~498/83~05 & 50~499/83~05 on 830217~18 MADSEN, G L Region 4. Office of Director 83/05/25 OFREA, G W Houston Lighting & Power Co 2pp 18602,145 24X Fichs 50~498,83/05/25,8306010350
- --B306010356 IE Mgt Meeting Repts 50-498/83-05 & 50-499/83-05 on 830217-18 Major areas discussed emergency preparedness & tentative date for emergency preparedness appraisal Tour of facilities followed meeting CROSEMAN W A Region 4. Office of Director. BANGART.R.L. Division of Vendor & Technical Programs 83/05/25. 3pp 12682 147. 24X Fichs 50-478,83/05/25,8306010350
- 8305110458 IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in Well Logging Device " Byc list encl TAYLOR, J M. Division of Bafeguards & Inspection Programs (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc. 125pp 18831 043 24X Fiche 50-000,83/05/28.8305110458.
- 8305110460 IE Info Notice 83-34, "Event Notification Info Worksheet," Byc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co. of New York, Inc. 115pp 18732 085 24X Fiche 50-000,83/05/26,8305110460
- 8305110461 16 Info Notice 83~35, "Fuel Movement W/Control Rods Withdrawn at BWRs " Bvc list encl.
 JORDAN, Et. Division of Emergency Preparedness & Engineering Response (Fost 830103) 83/05/31 Consolidated Edison Co of New York, Inc. 116pp 18732 208, 24X Fiche: 50-000, 83/05/31, 8305110441

- 8305110464 IE Info Notice 83-36. "Impact of Security Practices on Safe
- Operations "Svc list encl
 JORDAN,E L Division of Emergency Precaredness & Engineering
 Response (Post 839103) 83/06/09 Consolidated Edison Co of New
 York, Inc 119p 18830 280 24X Fishe 50-000,83/06/09.8305110464
- 8305110470 IE Info Notice 83-30, "Defective Heat Sink Adhesivo &
- JOSI 10470 IE 1860 NOTICE 83-33, "Defective Heat Sink Admessive & Seismically Induced Chatter in Relays Within Printed Circuit Cards " Svc list encl URDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co of New York, Inc 118pp 18920 225 24X Fishe 50-000,83/06/13,8305110470
- 8306090010 IE Info Notice 83-37. "Transformer Failure Resulting Frum Begraded Internal Connection Cables " Svc list encl JGRDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83706/13 Consolidated Edison Co of New York, Inc 243pp 18921 001 24X Fiche 50-000, B3/06/13, 8306090010
- 8305110475 IE Info Notice 83-40, "Need to Environmentally Qualify
 Epoxy Grouts & Sealers " Svc list enc!
 JCROAN.E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/06/22 Consolidated Edison Co of New
 York, Inc 115pp 19021 179 24X Fishe 50-000,83/06/22,8305110475
- 8305110477 IE Info Notice 83-44. "Actuation of Fire Suppression Sys Causing Inoperability of Safety-Related Equipment " Syt list
- enci JORDAN, E.L. Division of Emergency Preperedness & Engineering Response (Post 830103) 83706/22 Consolidated Edison Co. of New York, Inc. 120pp 18997-007 24X Fiche 50-000,83706/22,8305110477 120pp
- 8305110479 IE Info Notice 83-42, "Reactor Mode Switch Malfunctions "
- Byc list encl
 JORDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/06/23 Consolidated Edison Co of New
 York, Inc. 116pp 18996-242 24X Fiche 50-000,83/06/23,8305110479
- 8305110483 IE Info Notice 83-43. "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints "Syc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830(03) 83/06/24 Consolidated Edison Co of New York Inc 116pp 19046 29) 24X Fiche 50-000.83/06/24.8305110483
- 8 Reportable occurrences, LERs & related correspondence
- 8306070112 Final deficiency rept re inadequate duct layout of reactor containment fan cooler sys Instally reported on 930429 Design of discharge ducts will be modified to prevent water spray into ducks graph and spray into ducks graph into ducks of the spray into
- 8304130350 Final deficiency rept re breakdown in Brown & Root quality program for procurement cycle of purchased matte Initially reported on 800615 Item not reportable per 10CFR30 55(e) or OPREA, O W OFREA: 0 W Houston Lighting & Power Co 83/06/03 CDLLING, J T Region 4, Office of Director, lips 18822-326 24X Fichs 50-478,83/06/03.8306130350
- 830&1703BB Seventh interim deficiency rept re lack of visability on Brown & Root computer program methods Initially reported on BioSoB Further action re codes used by civil disciplines & pipe stress group required Next rept expected by 831014 OPREA.G.W Houston Lighting & Power Co 83/06/13 CDLLINS, J T Region 4. Office of Director 5pp 18880*243 24% Fiche 50-478.83/06/13.830617038B
- DOCKET STN-50-499 SOUTH TEXAS PROJECT, UNIT 2
- A Application/construction stage documents & correspondence
- B306240059 Requests participation in pilot program concept contained in Public Law B7-415 Section 13 re GA lists bases to be used for glanning purposes TAYLOR, J M Division of Safeguards & Inspection Programs (Post B30103) B3/05/03 DPREA: 6 A Houston Lighting & Power Co 2pp 18987.057 24X Fiche 50-498,83/05/03.8306240059
- 8306020024 Forwards request for addl info re proposed deletion of emergency paration sys Response should be provided in amend rorm. KNIQHTON, Q, W. Licensing Branch 3 83/05/12 OPREA: Q W. Houston Lighting & Power Co. 5pg. 18715 245 24% Fiche. 50-498, 83/05/12, 8306020024 Houston

- 8304200122 Forwards Rev 4 to GA program for design & const phase Rev does not reduce commitments contained in Rev 3 submitted on 020309 Affidavit encl
- VENDER APPROVATE ENCI OPREAS G W Houston Lighting & Power to 83/05/18 COLLING, J 7 Region 4, Office of Director App 10/04 025 24X Fiche 50-478,83/05/18,8306200122
- --8306200126 Rev 4 to GA program for design & const phase * Houston Lighting & Power Co 83/05/18 300pp 18 Fiche 50-498,83/05/18.8306200122 18704 029 248
- 8306140052 Advises that responses to FSAR Questions 32 42, "Loss of Non-Class IE Instrument & Control Power Sys Rus During Operation" & 32 44, "Quelification of Control Sys" will be provided by May 1984 Delay due to extensive redesign effort QDLDBERG, J H Houston Lighting & Power Co 83/06/07 NOVAK, 1 M Assistant Director for Licensing 2pp 18838 286 24X Fiche 50-498,83/06/07,8306140032
- 8306200017 Summary of 83033) meeting w/utils & Westingbouse in Bethesda,MD re Westingbouse analysis & evaluation of D4/D5/E steam generator mod HOPKINS,J B Licensing Branch 4 83/06/14 Licensing Branch 4 22pp 18908 327 24% Fiche 50 000,83/06/14,8306200019
- 8304230460 Comments on NRC activities re load combinations & pipe break design Guidence on elimination of double-ended breaks & intermediate break postulations requested Meeting 83/06/17 DENTUN: 0 200 18941 325 recommended recommended GOLDBERG, J H Houston Lighting & Power Co 83. Office of Nuclear Reactor Regulation, Director 24X Fiche 50-498,83/06/17,8306230460 DENTON, N. R.
- F Security, medical, emergency & fire protection plans
- 8306010350 Forwards 1E Mgt Meeting Repts 50-498/83-05 & 50-499/83 05 on 839217-18 MADSEN. 9 L. Region 4. Office of Director 83/05/25 OPREA. 9 W Houston Lighting & Power Co. 2pp. 18682 145 24X Fiche 50-498.83/05/25.8304010390
- --8304010356 IE Mgt Meeting Repts 50-498/83-05 & 50-499/83-05 on 63021/18 Major areas discussed emergency preparedness & tentative date for emergency preparedness appraisal Tour of facilities CROSSMAN, W A Region 4, Office of Director 83/05/25 3pp 18682 147 24% Fiche 50-494,83/05/25,8306010350
- B306070204 Forwards Amend 3 to security plan Amend withheld (ref 10CFR73 21) Rev 2 to security plan should be disposed of per appropriate safeguards procedures 90LDBERG.J H Houston Lighting & Power Co 83/05/27 DENTON.H & Office of Nuclear Reactor Regulation, Director 3pp 18/47 092 24X Fiche 50-498,83/05/27,8306070204
- G Adjudicatory correspondence
- 8306080150 Forwards suppl to motion for new contention on util financial qualifications & response to seventh set of util interrogatories Related correspondence SINKIN, L. Citizens Concerned About Nuclear Power, Inc. 83/04/02 BECHHOEFER.C., LAMB.J.C., HILL.C.E. Atomic Safety and Licensing Board Panel 1p. 18772 192 24X Fiche 50-498,83/04/02,8304080150
- --8304080155 Suppl to 830318 motion to admit new contention on util financial qualifications Adequate grounds for waiver of rele of financial qualifications review established & good cause shown for late filing SINKIN.L A Citizens Concerned About Nuclear Pawer, Inc 83/05/30 Abomic Safety and Licensing Board Panel 12pp 18772 193 24X Fiche 50-498,83/06/02.8306080150
- --8306080159 Response to motion to compel answers to seventh set of interrogatories, consisting of answers to interrogatories.

 Certificate of 8vc encl Related correspondence
 SINKIN,L A Citzzens Concerned About Nuclear Power, Inc
 83/06/02 Houston Lighting & Power Co 14pp 18772 205 24
 Fiche 50-498,83/06/02,8306080150 18772 205 24X
- 8306100200 Comments on Citizens Concerned About Nuclear Power 830602

 1tr & pleadings Certificate of Svc uncl
 NEWMAN, J.R. Lowenstein, Newman, Reis, Axelrad & Toll NEWHAN, J.R.
 Houston Lighting & Power Co. 83/06/08

 BECHHOEFER, C., LAMB, J.C.
 HILL, E.E., Atomic Safety and Licensing Board Panel 5pp 18805 306

 24X Fiche 50-498,83/06/08,8306100200
- 8306130427 Advises that time for Commission to review Director's Decision DD-83-05 expired Commission declined review Decision became final agency action on 030606 CHILK.S J. Office of the Secretary of the Commission 83/05/BINKIN, L. Affiliation Unknown jp 10821 178 24X Fiche 50-478,83/06/10.8306130427

- 8306220057 Supplemental answer to seventh set of interrogatories & requests for production of documents re site location acceptability W/Certificate of Svc Related correspondence SINKIN-L A Citizens Concerned About Nuclear Power, Inc. 83/06/13 Houston Lighting & Power Co. 5pp. 16930-029 24X
 Fiche 50-498.83/06/13.830622005/
- 830620030B Advises that applicant does not intend to file motion to compel detailed answers from (itizens Concerned About Nuclear Power to applicant seventh set of interrogatories & requests to produce Effort would be fruitless MEWHAN, J R Lowenstein, Neuman, Reis, Axelrad & Toll NEHMAN, J R Joint Applicants-Bouth Texas Project 83/06/15 BECHHOEFER, C, LAMB, J C, HILL, E & Atomic Safety and Licensing Board Panil Appli8900 160 24X Fiche 50-498,83/06/15,8306200308
- 8304270148 Memorandum & order granting util 830418 motion to compel Citizens Concerned About Nuclear Power answers to 830310 sixth set of interrogatoriles & requests for documents NRC directed to brief issues at earliest convenience BECHMOETER, C. Atomic Safety and Licensing Board Panel B3/06/22 Houston Lighting & Power Co. Bpp. 18768-041 24X Fiche 50-498,63/06/22,6304270148
- 8306280583 Forwards, por request, Reg Quide 1 70 & NUREG-0800, Sections 2 3 | W/a encis PERLIS, R G Hearing Branch 3 83/06/27 BERWICK, B Texas, State of 1p 19017 324 24% Fiche 50-498, 83/06/27, 8306280583
- K Utility Final Safety Analysis Report (FBAR) & amends
- B306300077 Forwards effective page listing through Amend 31 for FBAR Listing to be considered formal addition to FBAR WISEMBURG.M R Houston Lighting & Power Co B3/06/22 NOVAK.T M Assistant Director for Licensing 70pp 19048 260 24X Fiche 50-498,83/06/22,8306300077
- M Antitrust correspondence
- 8306230127 Advises that documents produced by Gulf States Utils Co.in response to NRC subpoema destroyed VOGLER. B H Hearing Branch 2 83/06/21 CLEMENTS, D M Gulf States Utilities Co. 1p 18947 048 24% Firms 50-000, 82/06/21, 8306230127
- Q Inspection reports, IE Bulletins & correspondence
- B3060B012B Forwards IE lnsp Repts 50-499/83 04 & 50-499/83-04 on B30207-11 No noncompliance nated MADSEN.G L Region 4. Office of Director B3/04/04 OPREA.G W Houston Lighting & Power Co 2pp 18772 318 24X Fichs 50-498,83/04/04.8306080128
- --8306080133 IE Insp Repts 50-498/63-04 & 50-499/83 04 on 830207-11 No noncompliance noted Major areas inspected environ protection program during const, including organization & administration audits & compliance w/CP & (ES CHANEY, H D , MURRAY, D , CROBSMAN, W A Region 4, Office of Director 83/03/29 13pp 18772 320 24X Fiche 50-498,83/04/04,8306060128
- B30&0B0277 Add1 response to F01A request for seven categories of records re Brown & Root. Int & facilities App C Document 1 partially withheld (ref F01A Exemption 7) App D documents withheld entirely (ref F01A Exemption 5) FELTON. J M Division of Rules and Records 83/04/12 LINDEMAN. H. N Lowenstein, Newman. Refs. Axerlad & Toll 4pp 18792 156 24X Fiche 50-478, 83/04/12, 830&080P/7
- --8306080304 "Request for Investigation Concerning Alleged Advanced Notification," investigation rept Info partially deleted BINCLAIR.J R Office of Inspector & Auditor 80/10/23 9pp. 18792 160 24X Fiche 50-498.83/04/12-8306080277
- --8306080308 Forwards rept re alleged advanced notification to util or Brown & Root.inc of forthcoming Region IV investigation &/or alleger identities No further invostigation contemplated W/o encl CUMMINGS.J J Office of Inspector & Auditor BO/10/24 AHEARNE, J F . GILINSKY.V , HENDRIE.J M Commissioners ip. 18792 169 24% Fiche 50-498,83/04/12.0306080277
- --8306080310 Forwards "Request for Invastigation Concerning Alleged Advanced Notification" (ref 801024 memo) W/o encl CUMMINOS, J Diffice of Inspector & Auditor 80/11/10, STELLO, V J. Director's Office, Office of Inspection and Enforcement ip 18792.170 24X Fishe 50-498,83/04/12,8304080277

- 8304060054 Forwards IE Insp Repts 50-498/83-08 & 50-499/83-08 on 830411-15 No noncompliance noted MADSEN. G L. Region 4. Office of Director 83/05/18 DPREA. G W Houston Lighting & Power Co. 2pp 18719 258 24X Fiche 50-498,83/05/18.83040400056
- --830606060 IE Insp Repts 50-498/83-08 & 50-499/83-08 on 830411-15 No noncompliance moted Major areas inspected const activities including deficient threads on site-fabricated anchor bolts, improper bolt matl & training records BOAHDMAN, JR. CROSEMAN, W. A. Region 4, Office of Director 86/05/13 Ilpp 18719 260 24X Fiche 50-498.83/05/18,8306060056
- 8306060111 Forwards IE Insp Repts 50-498/83-02 & 50-499/83-02 on 830201-28 & notice of violation MADBEN, G L Region 4. Office of Director 83/05/18 DPREA, O W Houston Lighting & Power Co 2pp 18719 082 24X Fichs 50-498,83/05/18,8306060111
- --8306040116 Natice of violation from insp on 830201-28 * Region 4, Office of Director 83/05/18 2pp 18719 084 24X Ficho 50-498.83/05/18.8306060111
- --8306060122 IE Imsp Repts 50-498/83-02 to 50-499/83-02 on 830201-28 Noncompliance noted licensee unable to retrieve GA records re site fabricated anchor holts HILLIW M, BDARDMAN, J R, TOMLINSON, D P Region 4, Office of Director 83/05/13 40pp 18719 086 24X Fiche 50-498, 83/05/18, 8306060111
- 8304010350 Forwards IE Mgt Meeting Repts 50-498/83-05 & 50-499/83-05 on 830217-18. MADSEN, G L Region 4. Office of Director 83/05/25 OPREA, G W Houston Lighting & Power Co 2pp 18602 145 24X Fiche 50-498,83705/25,8304010350
- --8306010356 IE Mgt Meeting Repts 50-498/83-05 & 50-499/83-05 on 830217-18 Major areas discussed.emergency preparedness & tentative date for emergency preparedness appraisal Tour of facilities followed meeting CROSSMAN.W A Region 4. Office of Director BANGARY.R L Division of Vendor & Technical Programs 83/05/25 3pp 18682 147 24X Fiche 50-498,83/05/25,8306010350
- 830511045B IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in Well Logging Device" Svc list encl TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 125pp 18831 043 24% Fiche 50-000,83/05/26,8305110458
- 8305;10460 IE Info Notice 83-34, "Event Notification Info Worksheet" 8vc list encl. JORDAN,C L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc. 115pp. 18732 089 24X Fichs 30-000,83/05/26,8305110460.
- 8305110461 IE Info Notice B3-35, "Fuel Movement W/Control Rods Withdrawn at JMRs." Svc list encl JORDAN,E L. Division of Emergency Preparadness & Engineering Response (Post 830103) 83/05/31 Consolidated Edison Co of New York, Int. 116pp 18732 208 24X Fiche 50-000,83/05/31,8305110461
- 8305110464 IE Info Notice 83-36. "Impact of Security Practices on Safe Operations " Syc list encl.
 JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/09 Consolidated Edison Co of New York. Inc 119pp 18830 280 24X Fithe 50-000,83/06/09.8305110464.
- 8305110470 IE Info Notice B3-38, "Defective Heat Bink Adhesive & Seismicelly Induced Chatter in Relays Within Printed Circuit Cards " Svc list encl.
 JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Post B30103) B3/06/13 Consolidated Edison Co of New York: Inc 118pp. 18920.225, 24X Fiche 50-000,83/06/13.8305110470.
- 8304090010 IE Info Notice 83-37. "Transformer Failure Resulting From Degraded Internal Connection Cables " Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co of New York Int 243pp 18921 001 24X Fiche 50-000,83/06/13,8304090010.
- 8305110475 IE Info Notice 83-40. "Need to Environmentally Qualify
 Epoxy Grouts & Bealers " Svc list encl
 JORDAN,E L Division of Energency Proparedness & Engineering
 Response (Post 830103) 83/06/22 Consolidated Edison Co. of New
 York, Inc. 115pp 19021.179 24% Fiche 50-000,83/06/22,8305110475

1

- 8305110477 IE Info Notice 83-41: "Actuation of Fire Suppression Sys Causing Inoperability of Safety-Related Equipment" Syc list encl
- anci JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/22 Consolidated Edison to of New York, Inc. 120pp 18997 007 24X Fiche, 50-000, 83/06/22, 83051104/7
- 8305110477 IE Info Notice 83-42, "Reactor Mode Switch Malfunctions" Byc list encl JORDAN, EL Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/23 Consolidated Edison Co of New York: Inc 116pp 18776 242 24X Fiche 50-000,83/06/23,8305110477
- B305110483 IE Info Notice 83-43, "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints " Syc list encl.
 JORDAN E L Division of Emergency Proparedness & Engineering Response (Post 830103) 83/06/24 Consolidated Edison Co. of New York, Inc. 116pp 19046 297 24X Firhe 50-000,83/06/24,8305110483

8 Reportable occurrences. LERs & related correspondence

- 8306070112 Final deficiency rept re inadequate duct layout of reactor containment fan cooler sys Initially reported on 830427
 Design of discharge ducts will be modified to prevent water spray into ducts
 EPREA:0 W Houston Lighting & Power Co 63/05/25 COLLING, J T Region 4, Defice of Director 4pp. 18239 168 24X
 Fichs 50-498,83/05/25,8306070612
- 8306;30350 Final deficiency rept re breakdown im Brown & Root quality program for procurement cycle of purchased matis Initially reported on 800615 Item not reportable per 10CFR50 55(e) or Part 21.

 OPREA G.H Houston Lighting & Power Co 83/06/03 CDLLING, J T Region 4, Office of Director 11pp 18822 326, 24X Fiche. 80-478, 83/06/03, 8306130350
- 8306170388 Seventh interim deficiency rept re lack of visability on Brown & Root computer program methods Initially reported on B10308 Further action re-codes used by civil disciplines & pipe stress group required Next rept expected by 831014 OPREA.0. W Houston Lighting & Power Co 83/06/13 COLLINS, J T Region 4, Office of Director 5pp 18880 243 24X Fiche 50-498,83/06/13,8306170388

DOCKET STN-50-508 WPPSS NUCLEAR PROJECT, UNIT 3

- A Application/construction stage documents & correspondence
- B306080378 Summarizes 830112 meeting w/C-E Owners Group in Bethesda, MD re depressurization & DHR capability w/o PDRVs Scenarios should reflect current emergency response guidelines rather than take credit for depressurization w/RCB couldown NDVAK-T N Assistant Director for Licensing 83/05/24 FERGUSON,R L. Weshington Public Power Supply Bystem. 4pp 18769-336. 24% Fiche 50-508,83/05/24.8306080378
- 8306080388 Forwards C-E ltr requesting addl info re rapid depressurization & DHR Responses provided by C-E will be directly applicable to facility NDVAK.I M Assistant Director for Licensing. 83/05/24 FEROUSON.R L Washington Public Power Supply System 2p; 18792.218. 24X Fiche 50-508.83/05/24.6306080388
- --8204090019 Forwards request for add1 info re depressurization & decay heat removal capability of CESBAR design TEDESCOR L Assistant Director for Licensing. 82/03/26 SCHERER:A E Combustion Engineering, Inc. 7pp 18792 220 24X Fiche 50-508,83/05/24,8306080388
- 8306170184 Advises that on 830527.util executive board directed immediate slowdown of const.not to streed 30 days.due to nearly exhausted funds & inability to secure conventional financing. No change to current licensing schedule requested LEDDICK.R. B Washington Public Power Supply System 83/06/01 STERNBERGOJM Region 5. Defice of Director. 2pp. 18882.300 24X Fichs: 50-508.83/06/01.8306170184
- 8304100117 Notifies that on 830527, util implemented slowdown of const for period of 30 days Decision based on reduction of funds. Plans being developed for possible 3-yr extension of completion date in case financing cannot be secured BOUCHEY, 0, D. Mashington Public Power Supply System 83/04/03, DENTON, H.R. Office of Nuclear Reactor Regulation, Director ip 18801:195, 24X Fiche: 50-508,83/04/03,8306100117.

- 8308230373 Forwards changes to QA program description, re organizational structure per 830110 notice of final rulemaking Program description will be incorporated into FSAR Chapter 17 by future FSAR amend BOUCHEY. O D Washington Public Power Supply System 83/06/13 MARTIN, J L Region 5, Office of Director 42pp 18742 304 24x Fiche 50-508,03706/13,8306230373
- 8306210154 Forwards responsed to Apr & May 1983 acceptance review questions Info covers fire hazard analyses & RHK sys BOUCHEY. © D Washington Public Power Supply System 83/06/14 KNIGHTON, G W. Licensing Branch 3 Spp 18916-013 24X Fiche 50-508.83/06/16.8306210154
- C Utility Environmental Report (ER), amends & correspondence
- 8304090207 Forwards response to 830406 request for 1940 re environ rept OL stage Site certification agreement w/Energy Facility Site Evaluation Council requires replacement &/or compensation for wildlife lostes BOUCHEY. 8 D Washington Public Power Supply System 83/06/07 KNIOHTON. 0 W Licensing Branch 3 10pp 18796 093 24X Fiche 50-508,83/06/02,8306070207
- E NRC Bafety Evaluation Report (SER), suppls & correspondence
- 8306170079 Forwards request for add1 into re FSAR review Response requested by 830712 Draft SER will be prepared following review of response KNIGHTON 6 W Licensing Branch 3 83/06/01 FERGUSON R L Hashington Public Power Supply System 13pp 18708 001 ;/4X Fiche 80-808,03/06/01,8306170077
- F Security, medical, emergency & fire protection plans
- 8306210154 Forwards responses to Apr & May 1983 acceptance review questions Info covers fire hazard analyses & RHK syk BOUCHEY. 8 D Washington Public Power Supply System 83/06/15 KNIGHTON. 6 W. Licensing Branch 3 5pp 18916 013 24X Fiche 50-508,83/06/16.8306210154
- O Adjudicatory correspondence
- 830.6020431 Requests special prehearing conference be rescheduled for B30817-18
 REYNOLDS,N 8 Dehevoise & Liberman 83/06/01 MAROULIES,N B Atomic Bafety and Licensing Board Panel 1p 18694 112 24X Fishe 50-508, 83/06/01.8306020431
- 8306150354 Forwards util 830603 ltr re 30~day const slowdown & possible addl const delays
 REYNOLDS,N B Debevoise & Liberman REYNOLDS,N G Hasbington Public Power Supply System 83/06/10 MARGULIES,M, CARPENTER,J H. SHON,F J Atomic Safety and Licensing Board Panel 1p 18847 265 24X Fiche 50-508.63/06/10.8306150354
- 8306220129 Suppl to 830218 petition to intervene, consisting of proposed contentions Certificate of Svc encl
 BELL.N Coalition for Safe Power 83/06/15 Atomic Safety and Licensing Board Panel 41pp 18926 112 24X Fiche 50-500.83/06/15.8306220129
- Q Inspection reports, IE Bulletins & correspondence
- B306100009 Add1 response to FDIA request for documents Atd B2010) or after re BALP Forwards App A documents Documents also available in PDR FELTON, J M Division of Rules and Records B3/04/11 CLASK. R Camerancisco Examiner 3pp 16815 252 24X Fiche 50-000,83/04/11,8306100009
- --8306100014 Bubmits schedule for Region V SALP Board meetings for 820928-830523 ENGELKEN,R H. Region 5, Office of Director 82/03/19 DENTON,H R Office of Nuclear Reactor Regulation, Director 1p 18815 255 24X Fiche 50-000.83/04/11,8306100009
- 8304010376 Advises that response to deviation identified in IE Insp Repts 50-508/83-03 & 50-508/83-01 re failure to meet AW8 DI 1 weld joint requirements will be submitted by 830715 LEDDICK.R B Washington Public Power Supply System 83/05/10 STERNBERGID M Region 5. Office of Director 2pp 18482 103 24X Fiche, 50-508, 83/05/10, 8304010374
- B305110458 IE Info Notice B3-32. "Ruptured Am-241 Bources Contained in Well Logging Device" Svc list entl
 TAYLUR, J M Division of Bafeguards & Inspection Programs (Post
 B33103) B3/05/26 Consolidated Edison Co. of New York, Inc
 125pp 18831 043 24X Fiche 50-000.83/05/26.8305110438

- 8305110460 IC Info Notice 83-34, "Event Notification Info Worksheet"
 Svc list encl
 JORDAN, El Division of Emergency Preparedness & Engineering
 Respanse (Post 830103) 83/05/24 Consolidated Edison Co of New
 York, Inc. 115pp 18732 085 24X Fiche 50-000, 83/05/26, 8305110460
- 830510461 IE Info Notice 83-35, "Fuel Movement W/Control Rods Withdrawn at DWRs " Svc list encl JORDAN,C | Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/31 Consolidated Edison Co of New York, Inc 116pp 18732 208 24X Fiche 50-000,83/05/31,8305110461
- 8305110464 IE Info Notice 83-36. "Impact of Security Practices on Safe Operations "Svc list encl JORDANIC L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/09 Consolidated Edison Co. of New York, Inc. 119pp 18830 280 24X Fiche 50-000.83/06/09.8305110464
- 8305110470 IE Info Notice 83-38, "Defective Heat Sink Adhesive & Seismically Induced Chatter in Relays Within Printed Circuit Cards "Syc list encl JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83706/13 Consolidated Edison Co. of New York, Inc. 1108pp 18920 225 24X Fiche 50-000.83/06/13.8305110470
- 8306090010 IE Info Notice 83-37, "Transformer Failure Resulting From Degraded Internal Connection Cables" Byo list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83706/13 Consolidated Edison Co of New York Inc 243pp 18921 001 24X Fiche 50-000,83/06/13.8306090010
- 8306170216 Ack receipt of 830216 ltr informing NRC of steps taken to correct violations noted in 1E Insp Rept 50-508/82-25 STERNBERG.D M Region 5. Office of Director 83/06/13 LEDDICK,R S Washington Public Power Supply System 1p 18882 285 24% Fiche 50-508,83/06/13,8306170216
- --8304170222 Responds to NRC 830117 ltm re violations noted in IC Insp. Rept 50-502/82-25 Util does not concur that activities described in item of noncompliance are in violation of 10CFR90-App B requirements Discussion requested LEDDICK-R 9 Weshington Public Power Bupply System 83/02/14 SICRNBERO, DM Region 5, Office of Director 3pp 18882 204 24X Fiche 50-508, 83/06/13, 6304170214
- 8304170425 Ack receipt of 830401 ltr informing NRC of steps taken to correct violations noted in IL Insp Rept 50-508/82-14 STERNBERO:D M Region 5. Office of Director 83/04/13 LEBOICK, R 8 Washington Public Power Supply System Ip 18879.019 24X Fiche 50-508.83/04/13.8304170425
- --8306170428 Buppls 821124 response to NRC 821227 ltr re violations noted in IE insp Rept 50-508/82-16 Corrective actions code/code case addenda requested to allow full penetration welds in lieu of double butt welds
 LEDBIGK.R.S Washington Public Power Supply System 83/06/01
 STERNBERG, D M Region 5. Office of Director 3pp 19879 014
 24X Fiche 50-508,83/06/13,8306170425
- B306280405 Forwards IE Insp Rept 50-508/83-04 on B30411-15 & 25-29 No concompliance noted STERNBERG D M Region 5, Office of Director B3/06/13 LEDDICK,R 8 Hashington Public Power Supply Bystem 2pp 19001 337 24X Fiche 50-508, B3/06/13, B306280405
- --8304280409 IE Insp Rept 50-508/63-04 on B30411-15 & 25-29 No noncompliance noted Major areas inspected const activities, including installation of pipe support & restraint sys & preservice insp of RCPB HARST, D. P. DODDS. R T Region 5, Office of Director B3/06/09. 12pp 19001 339 24X Fiche, 50-508, 63/06/13, 8306280405
- 8305110475 IE Info Notice 83-40. "Need to Environmentally Gualify
 Epoxy Grouts & Sealers " Svc list enc).
 JORDAN, E. L. Division of Emergency Preparedness & Engineering
 Response (Post 83010-3) 83706/22 Consolidated Edison Co. of New
 York, Inc. 115pp 17021 179 24X Fiche 50-000,83706/22,8305110475
- 8305110477 IE Info Notice 83-41, "Actuation of Fire Suppression Sys Causing Inoperability of Safety-Related Equipment " 8vc list encl JORBAN, E. Division of Emergency Preparedness & Engineering Response (Post 830103) 83706722 Consolidated Edison Co of New York, Inc. 120pp 18997,007. 24X Fiche. 50-000,83706722,8305110477
- 8305110479 IE Info Notice 83-42, "Reactor Mode Switch Melfunctions." Svc list encl JORDAN, E. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/06/23 Consolidated Edison Co of New York, Inc. 116pp. 18996 242 24X Fiche 30-000, 83/06/23, 8305110477

- 8305110483 IE Info Notice 83-43, "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints " Bvc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post B30103) B3/06/24 Consolidated Edison Co. of New York, Inc. 116pp 19046 297 24X Fiche 50-000,83/06/24,8305110483
- 8 Reportable occurrences, LERs & related correspondence
- 8306070254 PND-V-83-023 on 830527, executive board of util passed resolution delaying completion of Project 3 for 3 yrs if addl financing not obtained within 30 days Present employment at project is approx 3,000 BTERNBERG,D M. HAIST,D P. Region 5, Office of Director 83/05/27 ip 18740 335 24% Fichs 50-506.83/05/27,8306070254
- 8306170296 Interim Deficiency Rept NY-GA-5 re main steam & feedwater penetration anchor stress analyses Initially reported on 830426 Engineering procedure revised & analyses performed Final rept expected by 830729 LEDDICK, R 8 Washington Public Power Supply System 83/06/09 STERNERG, D M Region 5. Office of Director Spp 10878 174 24X Fiche 50-508.83/06/09.8306170296
- DOCKET BIN-50-509 WPPSS NUCLEAR PROJECT, UNIT 5
- Q Inspection reports: IE Bulletins & correspondence
- B306:00009 Add1 response to FOIA request for documents dtd 820101 or after re SALP Forwards App A documents Documents also available in PDR.
 FELTON.J M Division of Rules and Records 83/04/11 CLARK.R Ban Francisco Examiner 3pp 18815 252 24X Fiche.50-000.83/04/11.8306:100009
- --B306100014 Bubmits schedule for Region V SALP Board meetings for B20928-B30523 ENGELKEN,R H Region 5, Office of Director. 82/03/19 DENTON,H R Office of Nuclear Reactor Regulation, Director 1p 18815 255 24x Fiche 50-000,83/04/11,8306100009.
- DOCKET 50-513 WPPBS NUCLEAR PROJECT, UNIT 4
- Q. Inspection reports. IE Bulletins & correspondence
- 8306100007 Addl response to FOIA request for documents dtd 820101 or after re BALP. Forwards App A documents Documents also available in PDR FELTON, J. M. Division of Rules and Records. 82/04/11 CLARK.R. San Francisco Examiner 3pp 18815 252. 24X Fichs 50-000,83/04/11, 8306100007
- --B306100014 Submits schedule for Region V SALP Board meetings for B20928-B30523
 ENGELKEN,R H Region 5, Office of Director 82/03/19, DENTON-H R Office of Nuclear Reactor Regulation, Director, 1p 18815 255 24% Fiche: 50-000, 83/04/11, 8306100009
- 8 Reportable occurrences, LERs & related correspondence
- 8304010106 Final deficiency mept me stuck meactor vensel flange stud/hole-stuck stud initially reported on 871115 Vendom determined that structural & functional integrity of stud hole acceptable Condition not reportable per 100FRSD. 53(e) DE LORENZD.R A Mathington Public Powrr Supply System 83/05/17 87ERNBERG.D R Region 5. Office of Director 2pp. 18674 062. 24X Fiche 50-513,83/05/17,8306010106
- 830.6070113 Interim deficiency rept re potential failure of reactor vessel internals bolts Initially reported on 830502 B&W participating in insp program on operating plants Status rept will be provided upon const restart DE LORENZO,R A. Mashington Public Power Supply System 83/05/25. STERNBERG,D M Region 5. Office of Director 2pp 18739-212 24X Fiche 50-460.63/05/25.8306070113
- DOCKET 50-614 PEBBLE BPRINGS NUCLEAR PLANT, UNIT 1

 Q. Inspection reports. IE Bulletins & correspondence
- 8305110458 IE Info Notice 83-32. "Ruptured Am-241 Bources Contained in Hell Logging Device." Syr list encl TAYLOR.J.M. Division of Safeguards & Inspection Programs (Post 830103) 83/05/26 Consolidated Edison Co. of New York, Inc 125pp. 16831 043. R4X Fiche; 50-000, 83/05/26, 8305110458.

- 8305110460 lE Info Notice 83-34, "Event Natification Info Worksheet "
- Svc list ent:
 JORANN.E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/05/26 Consolidated Edison Co of Νεω
 York, Inc 115pp 18732 083 24X Fiche 50-000,83/05/26,8305110460
- 8305110461 IE Info Notice B3-35, "Fuel Movement W/Control Rods Withdrawn at BWRs " Svc list encl JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post B30103) 83/05/31 Consolidated Edison (n of New York, Inc. 116pg 18732 200 24X Fishs 50-000,83/05/31,8305110461
- 8305110464 IE Info Notice 83-36, "Impact of Security Practices on Safe
- Operations "Svc list enci JORDAN E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/09 Consolidated Edison Co of New York, Inc. 119pp 18830 280 24% Fichs 50-000.83/06/09.8305110464
- 8305110470 IE Info Notice 83-38. "Defective Heat Bink Adhesive & Seismically Induced Chatter in Relays Within Printed Circuit Cards " Svc list encl JORDAN, EL Division of Emergency Preparedness & Engineering Response (Post 830103) 83704/13 Consolidated Edison Co of New York Inc 118pp 18920 225 24x Fichs 50-000,83704/13,8305110470
- 8306090010 IE Info Notice 83-37. "Transformer Failure Resulting From Degraded Internal Connection Cables " Svc list encl JORDAN: E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consultdated Edison Cr of New York, Inc 243pp 18921 001 24X Fiche 50-000,83/06/13.0304090010
- 8305110475 IE Info Notice 83-40, "Need to Environmentally Qualify
 Epary Grouts & Sealers " Svc list encl
 JORDANIE L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 89/04/22 Consolidated Edison Co of New
 York, Inc. 115pp 19021 179 24X Fishe 50-000,83/04/22,8305110475
- 8305110477 IE Info Notice 83-41, "Actuation of Fire Suppression Sys Causing Inoperability of Safety-Related Equipment" Svc list
- encl JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/22 Consolidated Edison Co. of New York, Inc. 120pp 18997 007 24% Fithe 50~000,83/06/22,8305110477
- 9305110479 IE Info Notice 83-42, "Reactor Hode Switch Malfunctions"
- 8308110483 IE Info Notice 83-43, "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints "Svc list encl JORDAN E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/24 Consolidated Edison Co of New York, Inc 116pp. 19046 297 24X Fiche 50-000,83/06/24,8305110483
- DOCKET 50-515 PERBLE SPRINGE NUCLEAR PLANT, UNIT 2
- Q Inspection reports: IE Bulletins & correspondence
- 8305110498 IE Info Notice 83-32. "Ruptured Am-241 Sources Contained in Well Logging Device" Svc list encl
 TAYLOR J M Division of Safeguards & Inspection Programs (Post 830103) 83/08/26. Consolidated Edison Co of New York, Inc
 125pp 18831 043 24x Fiche 50-000.83/05/26.8305110458
- 8305110460 IE Info Notice 83-34, "Event Notification Info Worksheet "
- Svc list encl JORDAN, E.L. E Bvc list encl
 JORDAN, E.L. Division of Emergency Preparedness & Engineering
 Response (Post B30103) 83/05/26 Consolidated Edison Co of New
 York, Inc. 115pp 18732 085 24X Fiche 50-000.83/05/26,8305110460
- 8305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods Withdrawn at BMRs " Syc list encl. JBRDAN.E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/31 Consolidated Edison Cn. of New York, Inc. 116pp 18732 208 24X Fiche 50-000, 83/05/31,8305110461
- 8305110464 IE Info Notice 83-36, "Impact of Security Practices on Safe
- 30510464 IE Info Notice Bullaco, Ampliana (Operations, "Byo list entl Upprations," Byo list entl Upprations, "Byo list entl Upprations," Byo Emergency Preparedness & Engineering Response (Post 830103) 83/06/09 Consolidated Edison Co. of New York, Inc. 119pp 18830 280 24X Fiche 50-000, 83/06/09, 8305110464
- 8305110470 IE Info Notice 83-38, "Defective Heat Bink Adhesive &
- Seismically Induced Chatter in Relags Within Printed Circuit Cards "Byc list encl JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Commolidated Edison Co of New York, Inc 118pp. 18920 225, 24X Fiche 50-000, 83/04/13,8308110470

- 8306090010 IE Info Notice 83-37. "Transformer Failure Resulting From Degraded Internal Connection Cables " Svc list encl JORDAN.C L Division of Emergency Properedness & Engineering Response (Post 830103) 83706/13 Consolidated Edison Co of New York, Inc 243pp 18921 001 24X Fiche 50-000.83/06/13.8304090010
- 8305110475 IE Info Notice 83-40, "Need to Environmentally Qualify Spany Grouts & Sealers "Svo last encl
 JORDAN, E L Division of Emergency Preparedness & Engineering
 Response (Post 80103) 83/06/22 Consolidated Edison Co of Neu
 York, Inc. 115pp 19021 177 24X Fiche 50-000,83/06/22,6305110475
- 8305ii0477 IE Info Notice 83-41, "Actuation of Fire Suppression Sys-Causing Inoperability of Sofety-Related Equipment" Syc list URDAN, C.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/22 Consolidated Edison Co. of New York, Inc. 120pp 18997 007 24% Fiche 50-000.83/06/22,83051[0477
- 8305110479 IE Info Notice 83-42, "Reactor Mode Switch Malfunctions "
- 8305110483 IE Info Notice 83-43, "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints "Sve list encladered by Jordan, EL Division of Emergency Proparedness & Engineering Response (Post 830103) 83/06/24 (onsolidated Edison to of Jordan) York, Inc. 116pp 19046 297 247 Fiche 50-000, 83/06/24, 8305110483
- DOCKET STN-50-517 JAMESPORT NUCLEAR STATION, UNIT 2
- O Inspection reports: IE Bulletins & correspondence
- 8305110483 IE Info Notice 83-43, "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints " Ove list one; I address & Engineering Adraba, C L. Division of Emergency Preparedness & Engineering Response (Post 80103) 83/06/24 Consolidated Edison Co of New York, Inc. 114pp 19046 29/ 24X Fiche 50-000,83/06/24,8305110483
- DOCKET STN-50-518 HARTSVILLE NUCLEAR PLANT, UNIT 1
- S Reportable occurrences, LERs & related correspondence
- 4306160494 Pt 21 rept repotential defect in transmitter mfg by 30&160494 Pt 21 rept re potential defect in transmitter mfg by
 Rosemount, Inc used in control sys components furnished to
 listed plants All components involved retrofitted w/new
 circuit boards Matter closed
 GIRGUX,E J Carrier Corp 83/05/23 STELLO, V Director's Dffice.
 Office of Inspection and Enforcement ip 18863 094 24X
 Fiche 50-518,83/05/23.8306160454
- 8304090135 Second interim deficiency rept re Henry Prett butterfly valve Initially reported on 821109 Valve air-operator yeke mod kits delivered & mod in progress Operators removed & returned to GH Bettis Co Also reported per Part 21 HILLS.L. M. Tennessee Valley Authority 83/06/02 O'REILLY, J.P. Region P. Office of Director ip 18/95 297 24X Fiche 50-000,83/06/02,8306090135
- DOCKET STN-50-519 HARTSVILLE NUCLEAR PLANT, UNIT 2
- 8 Reportable occurrences, LERs & related correspondence
- B306160454 Pt 21 rept re potential defect in transmitter mfg by Rosemount Inc used in control sys components furnished to listed plants All components involved retrofitted w/new circuit boards Matter closed GIRDUX, E. J. Carrier Corp. B3/05/23 STELLD, V. Director's Office. Defice of Inspection and Enforcement ip 18863 074 24X Fiche 50-518, 83/05/23, 8306160454
- DOCKET STN-50-520 HARTSVILLE NUCLEAR PLANT, UNIT 3
- S Reportable occurrences, LERs & related correspondence
- 8306160454 Pt 21 rept re potential defect in transmitter mfg by 303160454 FT 21 rept re potential derect in transmitter and by Rosemount. Inc used in control sys camponents furnished to listed plants All components involved retrofitted w/new circuit beards Matter closed GIRQUX, E. J. Carrier Corp. 83/05/23 STELLD, V. Director's Office. Office of Inspection and Enforcement ip 18863 094 24X Fichs 50-918, 83/05/23, 8306160454

830.6090135 Second interim deficiency rept re Henry Pratt butterfly valve Initially reported on 8.11699 Volve air-operator yoke mod kits delivered & mod in progress Operators removed & returned to 691 Rettis Co Also reported per Part 21 HILLS, L.M. Tennessee Valley Authority 83/06/02 0'REILLY, J.P. Regian 2, Offsee of Director in 1917/5-297 24X Fiche 50-000, 83/06/02, 8306070135

DOCKET STN-50-591 HARTSVILLE NUCLEAR PLANT, UNIT 4

S. Reportable occurrences, LERs & related correspondence

830.6160454 Pt 21 rept re potential defect in transmitter mfg by Rossmount. For used in control sys of components furnished to listed plants All components involved retrofitted w/new circuit boards Matter closed GIROUX.E. J. Carrier Corp. 83/05/23 STELLO.V. Director's Office. Office of Inspection and Enforcement ip 18863-094 24X Fiche 50 518.03/05/23.8306160454

DOCKET 50 522 SKA011 NUCLEAR POWER PROJECT, UNIT 1

Q Adjudicatory correspondence

B306060285 Momorandum & order extending time until 830930 for parties to answer intervenor 830912 motion for summary disposition of Contention i Util considering alternative to terminating licensing efforts

HDLF.J f Atomic Safety and Licensing Board Panel B3/06/02

Puget Sound Power & Light to 7pp 18/28 361 24X

Fiche 50-527,03/06/02.8306060285

830&070234 Response opposing applicant 8'30525 request for extrasion until 830930 to answer motion for summary disposition of Contention 1 No good cause demonstrated Certificate of Svc sncl
CAVANAON, R. Natural Resources Defense (ouncil 83/06/03 Atomi Safety and Licensing Board Pauel App. 18795-336, 24X
Fiche 50-522,83/06/03,8306090234

- O Inspection reports, IE Bulletins & correspondence
- 8305110458 IE Info Notice 83-32. "Roptured Am-241 Sources Contained in Meth Logging Device" Svc list onth TAYLOR, J M Division of Safequards & Inspection Programs (Post 830103) 83/05/26. Consolidated Edison Co of New York, Inc 125pp 18831 043 24X Fiche 50 000.03/05/26.830510458
- 8305110460 IE Info Notice 83-34. "Event Notification Info Worksheet" Eve list enri JORDAN,E L. Division of Lmergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Eduson Co. of New York, Inc. 115pp 18732 085 P4X Fiche 50-000,83/05/26,8305110460
- 8305110461 IE Info Notice 83-35, "Fuel Novement W/Control Rods Withdrawn at BWKs " Byo list end JORDAN, El Division of Emergency Proparedness & Engineering Response (Post 830103) 83/05/31 Consolidated Edison Co. of New York Inc. 116pp 18732 208 24% Ficbs 50-000.83/05/31.8305110461
- 8305110464 IE Info Natice 83-34, "Impact of Security Practices on Safe Operations " Syc list encl JORDANIE L Division of Emergency Preparedness & Engineering Response (Past 830103) 83/06/07 Consolidated Edison Ca of New York, Inc 117pp 18830 280 24X Fichs 50-000,03/06/09.0705110464
- 8305110470 IC Info Notice 83-38, "Defective Heat Sink Adbasive & Seismically Induced Chatter in Relays Within Printed Circuit Cards " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co of New York, Inc 118pp 18920 225 24X Fichs 50-000.83/06/13.8305110470
- 8304090010 LE Info Notice 83-37, "Transformer Failure Resulting From Degraded Internal Connection Cables " Svc list encl JURDAN,E L Division of Emergency Preparedness & Engineering Response (Post 930103) 83/04/13 Consolidated Edison Co of New York, Inc 243pp 18921 001 24% Fiche 50-000.83/05/13.8306090010
- 8305110475 IE Info Notice 83-40, "Need to Environmentally Qualify
 Epoxy Grouts & Sealers " Syc list encl
 JCRDANGE L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/06/22 Consolidated Edison Co. of New
 York, Inc. 115pp 19021 177 24X Fiche 50-000,83/06/22,8305110475

- B305i10477 IE Info Notice 83-41, "Actuation of Fire Suppression Sys Causing Inoperability of Safety-Related Equipment " Svc list enc! JGRDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post B30103) B3/04/22 Consolidated Edison Co. of New York, Inc. 120pp 18997 007 24X Fiche 50-000,83/04/22,8305i10477
- B305110479 IE Info Notice B3-42, "Reactor Mode Switch Malfunctions "
 Svc list enc!
 JDRDAN, E. L. Division of Emergency Preparedness & Engineering
 Response (Post B30103) B3/06/23 Consolidated Edison Co. of New
 York, Inc. 116pp 18996 242 24X Fiche 50-000.03/06/23.8305110479
- 8305;10483 IE Info Notice 83-43, "Improper Bettings of Intermediate Range (IR) High Flux Trip Setpoints " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/24 Consolidated Edison Co of New York, Inc 116pp 19046 297 24X Fiche 50-000.83/06/24.8305110483

DOCKET 50-523 SKAGIT NUCLEAR POWER PROJECT, UNIT 2

8304060285 Memorandum & order extending time until 830930 for parties to answer intervenor 830512 motion for summary disposition of Contention I Util considering alternative to terminating licensing effort:
WOLF, J.F. Atomic 84Pety and Licensing Board Panel 83/06/02
Puget 80ound Power & Light Co. 2pp. 18728-361 24X
Fiche 50-522,83/06/02,8304060285

8306070234 Response opposing applicant 830525 request for extension until 830930 to answer motion for summary disposition of Contention I No good cause demonstrated Certificate of Sycenci CAVANAGH.R Natural Resources Defense Council 83/06/03 Atomic Safety and Licensing Board Panel App 18795 336 24X Fiche 50-522.83/06/03.8306090234

- G Inspection reports. IE Bullstins & correspondence
- 8305110458 IE Info Notice 83-32. "Ruptured Am-241 Sources Contained in Well Logging Device" Svc list encl TAYLOR, J M Division of Bafeguards & Inspection Programs (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 125pp 18831 043 24X Fiche 50-000.83/05/26.8305110458
- 8305110460 IE Info Notice 83-34, "Event Notification Info Horksheet" Bvc list encl JORDAN, C. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc. 115pp. 18732 085 24% Fiche, 50-000,83/05/26,8305110460
- 8303110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods Hithdrawn at BWRs " Syc list encl JORDAN,C L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/31 Consolidated Edison Co of New York, Inc 116pp 18732 208 24% Fiche 50-000,83/05/31,8305110461
- 8305110464 IE Info Notice 83-36, "Impact of Becurity Practices on Safe Operations "Syc list encl URDAN,E L Division of Emergency Proparedness & Engineering Response (Post 830103) 83706/09 Consolidated Edison Co of New York, Inc 119pp 18830 280 24X Fiche 50-000,83706/09,8305110464.
- 8305110470 IE Info Notice 83-39, "Defective Heat Sink Adhesive & Seismicelly Induced Chatter in Relays Within Printed Circuit Cards" Svc list encl JURDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co of New York, Inc. 118pp 18720 225 24X Fiche 50-000,83/06/13,8305110470
- 8306070010 IE Info Notice 80-97, "Transformer Failure Resulting From Degraded Internal Connection Cables" Over list encl JURDAN, E. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Contolidated Edison Co of New York, Inc 243pp 18921 001 24X Fiche 50-000,83/06/13,8306070010
- 8305110475 IE Info Notice 83-40. "Need to Environmentally Gualify
 Epoxy Grouts & Sealers " Svc list encl
 JORDAN, E L Division of Emergency Proparedness & Engineering
 Response (Post 830103) B3/06/22 Consolidated Edison Co. of New
 York, Inc 113pp 17021 177 24X Fiche 50-000.83/06/22.8305110475.
- 8305110477 IE Info Notice 83-41, "Actuation of fire Suppression Sys-Causing Inoperability of Safety-Related Equipment " Syc list encl JORDAN,E L Division of Largency Preparedness & Engineering Response (Post 830103) 83706722 Consolidated Edison Co. of New-York, Inc. 120pp. 18997 007 24X Fiche 50-000.83706722.8305110477

- 8305110479 IE Info Notice 83-42, "Reactor Mode Switch Malfonctions "
 - Socilist encl
 JORDAN, E.L. Division of Emergency Proparedness & Engineering
 Response (Post 830103) 83/06/23 Consolidated Edison Co. of New
 York, Inc. 116pp 18996 242 24X Fiche 50-000,83/06/23,8305110477
- 8305110483 IE Info Notice 83-43, "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints" Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83706724 Consolidated Edison Co of New York, Inc 116pp 19046 297 24X Fiche 50-000,83706724,8305110483
- DOCKET STN-50-528 PALO VERDE NUCLEAR STATION, UNIT 1
- A Application/construction stage documents & correspondence
- 8304080284 FOIA request for documents re R Gunderson & Bechtel senior 304080284 FulA request for documents re R Gunderson & Becht manager allegations concerning electrical problems & deficiencies at Pacilities Haiver of fees requested YQUNO.M.C., EERNABEIL Government Accountability Project 83/03/29 Office of Administration 2pp 18790 757 . Fiche 50-528,83/03/29,8304080284
- 8306140225 Forwards Conference Notes CN-E-1285 from 830323 meeting w/util.counsel.Bechtel.NRC & C-E in Washington.BC repost-LOCA containment sump WILEON.W H Bechtel Corp 83/04/14 VAN BRUNT.E E Arizona Publ Bervice Co 3pp 18844 322 24X Fiche 50-528.83/04/14.8306140225 Arizona Public
- 8306080281 Partial response to FUIA request for documents re
 R Gunderson & Bechtel allegations concerning electrical
 problems at facilities App A Documents I & 2 available in
 PDR Documents 3.4 & 5 withheld (ref FUIA Exemption 5)
 FELTON.J M Division of Rules and Records 83/04/28 YOUNG M C,
 BERNABELL Government Accountability Project 3pp 18790 354
 24X Ficher 50-528, 83/04/28, 8306080201
- 8306020627 Notification of 830622-23 & 24 meetings w/util in Maricopa & Phoenix. AZ: respectively, to assess current status of const LECTRALE A Licensing Branch 3 82/05/24 KNIGHTON.6 H Licensing Branch 3 6pp 18716 339 24X Fiche 50-528.03/05/24. 8306020627
- 8306070091 Advises that schedule for responding to five confirmatory items & completion of qualification program for safety—related pumps & valves will be submitted by 830630 VAN BRUNT. E E Artrona Public Service Co 83/05/31 KNIGHTON. 0 W Licensing Branch 3 ip 18739 141 24X Fiche 50-528.83/05/31.
- 8304080077 Summary of 830517 meeting w/otil.C-E & Bechtel in Bethesda. HD re NRC 830314 requested info on environ qualifications Environ qualification audit scheduled during wk of 830627 LICITRA.E A Licensing Branch 3 83/06/01 Licensing Branch 3 4pp 18787 327. 24X Fiche 50-528.83/06/01.8306080097
- 8306200051 Notification of 830608 meeting w/util in Bethesda, MD to discuss control room design review LICITRA; E. A. Licensing Branch 3. 83/06/03 KNIGHTON, C W Licensing Branch 3 3pp 18708 286 24X Fiche, 50-528, 83/06/03, 8306200051.
- 830A200053 Notification of 830A28-30 & 0701 meetings w/util, Brchtel. C-E & EGRO in Phoenix & Maricopa County, AZ to conduct audit of equipment environ qualification documentation LICITRA, E A Licensing Branch 3 83/06/03 KNIGHTON, G W Licensing Branch 3 3pp 18708 289 24X Fiche 50-528, 83/06/03, 8306200053.
- 8306170265 Forwards marked-up Amend 12 to FBAR Section 17 1 re GA program for engineering design procurement & const of facility, per 10CFR50.55(#)

 WAN BRUNT, E E Arizona Public Service Ca 63/06/10 STERNBERG, D M Region 5, Diffice of Director 52pp 18877, 274 24X Fiche, 50-528, 83/06/10, 8306170265
 - orwards App J to, "Evaluation of Pressurized Thermal Bhock to Small Break LOCAs W/Loss of Feedwater for 7.2 & 3 Reactor Vessels " Rept applies to
 - rizona Public Garvice Co. 83/06/14 KNIGHTON, G 3 3pp 18878 197. 24X Fiche. 50-528, 83/06/14,

- 830624045B Summary of B30608 meeting w/util in Bethesda. MD re-detailed 306240438 Summary or Budgo marring and Control room design review LICITRA.E A Licensing Branch 3 83/06/14 Licensing Branch 3 4pp 18978 001 24% Fiche 50-528,83/06/14,8306240458
- 8306270143 Forwards schedule for submittal of info required for NRC review of FSAR Schedule covers submittal of revised security plan & addl CCSSAR interface requirements VAN SRUNTLE E Arizona Public Service Co 83/06/20 KNIGHTON, Q Licensing Branch 3 8pp 18908 001 24X Firhe 50-529, 83/06/20, 8306270143
- 8306280436 Forwards Amend 1 to environ qualification rept,per 8,30314 request & NUREO-0588 requirements

 VAN BRUNT,E E Alizona Public Service Co 83/06/24 KNIGHTGN,Q Litensing Branch 3 228pp 17016 27/ 24X Ficke 50-528,83/06/24, 8306280436
- E NRC Safety Evaluation Report (SFR), supple & correspondence
- 8306130432 Responds to 830328 request for add1 info re adequacy of electric distribution sys voltages per SFR (NUREG-0857) Response re adequacy of util info requested mithin 2 wks VAN BRUNT, E E Arizona Public Service Co 83/06/07 KNIOHTMLO Licensing Branch 3 App 18821 195 24X Fiche 50-528,83/06/07,8306130432
- 8306160500 Advises that procedures indicating shutdown cooling relief valves armed by manually opening shutdown cooling systematical valves will be utilized until operable low temp overpressure alarm available.per NUREO-0857, Suppl I VAN BRUNT, E. Arizona Public Service Co. 83/06/13 KNIGHION, O Arizona Public Service Co 83/04/13 KNIGHION, h J 1p 18044 156 P4X Fiche 50-520, 83/04/13, Licensing Dranch J B306140500
- 8306170326 Forwards proposed amend to FbMt re CESSAR ladine removal sys & responses to NRC 830422 ltr Proposed FBAR amend combined w/responses clases out sump ph issue in SER Sections 6.4 & 15.4 8 tml Item III D.3.4

 VAN BRUNTLE E Arizona Public Service Co. 83/06/13 KNIGHTON.6 Licensing Branch 3. 8pp. 188/9.040 24X Fiche 50-528.83/06/13.8306170326
- 8306270368 Forwards responses to SER, Suppl 4. Sections 13 3 2 2 & 13 3 2 3 (NUREG-0857), re courses of action necessary in unlikely event of emergency at facilities info will be included in Rev 3 to emergency plan
 VAN BRUNT, E E Arizona Public Service Co 83/06/15 KNIGHTON, Q Licensing Branch 3 26pp 18993 214 24X Fiche 50-528, 83/06/15.
- Licensing Branch 3 8304210287
- 8306280317 Submits required data to demonstrate that line voltage BONDHOINN CS/40/EB
- F Swcurity, medical, emergency & fire protection plans
- 8305170356 Forwards description & list of objectives for 830519 emergency preparedness exercise Scenario will be provided within 30 days Comments requested within 15 days of ltr mate ANDOGNINI,G C. Arizona Public Service Co. 83/03/02 GRIMES,B K Division of Emergency Preparedness (Pre 830103) 19pp. 18880 33 24X Fiche 50-520,83/03/02,8306170356
- --8306170360 Forwards description & list of objectives for 830511 emergency preparadness exercise Scenario will be provided within 30 days Comments requested within 15 days of ltr within 30 days comment. And the service Co 83/03/02 MARTIN.R ANDBONINI.C C Arizona Public Service Co 83/03/02 MARTIN.R Region 5, Office of Director 10pp 18880 352 24X Ficker 50-528,63/03/02,8304170354
- 8304020056 Responds to B30414 ltr re Generic Ltr 82-33 requirements concerning Suppl 1 to NUREG-0737 Portion of response addressing detailed control room design review does not provide all info requested Response requested by 630531 KNIGHTON, C W. Licensing Branch 3 83/05/10 VAN BRUNT, E E Anizone Publis Gervice Co App 18701 349 24% Fiche 50-528,83/05/10,8306020056

- 830A030357 Advises that add1 info re detailed control room design review per Generic Ltr 82-33 re emergency response capabilities will be submitted by 830617 VAN BRUNT.E E Arizona Public Spivice Co 83/04/01 KNIGHTON. 0 Licensing Branch 3 lp 18/05-214 247 Fiche 50-528.83/04/01.830600357
- B306090273 Releases public version of revised emergency plan implementing procedures FELTON, J M Division of Rules and Records 83/06/03 Document Management Branch ip 18810 067 24% Fiche 50-528,83/06/03, B306070273
- --8306090275 Forwards public version of revised emergency plan implementing procedures, including Procedures EPIP-01 resemency organization. EPIP-02 resemergency classification & EPIP-04 resulted alors implementing actions
 VAN BRUNT.E E Arizona Public Service Co. 83/05/23 KNIGHTON.Q Licensing Branch 3 3pp. 18810-068 24X Fiche 50-528.83/06/03.8306090273
- --830&07027& Public version of revised emergency plan implementing procedures, including Procedures EPIP-O1 re emergency organization, EPIP-O2 re emergency classification & EPIP-O4 re alert implementing actions LUCIA, B Arizona Public Service Co 83/03/30 709pp 18810 071 24% Ficha 50-528,83/06/03,830&070273
- 830616005B Releases public version of revised emergency plan FELTON.J M Division of Rules and Records 83/06/06 Document Management Branch 1p 18872 316 24% Fiche 50-528.83/06/06,
- --8306160064 Public version of Rev 3 to Emergency plan, changing overal) organizing task force & organizational option of corporate emergency planning & preparedness group W/830510 1tr ANDOONINI, G C Ariiona Public Service Co B3/03/28 KERRIGAN, J Operating Reactors Branch 3 App 180/2 317 24X Fiche 50-528,63/04/06,8306160058
- 8306280515 Forwards IE Insp Rept 50-528/83-21 on 830523-27 Nu noncompliance noted STERNBERG.D M Region 5, Office of Director 83/06/14 AMBOGNINI, 6 C Amirona Public Service Co 2pp 19017 197 24X Fiche 50-528,83/06/14,8306280015
- --8306280519 IE Insp Rept 50-528/83-21 on 830523-27 No noncompliance noted Major areas inspected fire protection/prevention program & program implementation SCGMN.K., YOUNG, T. Region 5, Office of Director 83/06/14 App 19017 201 24X Fiche 50-528,83/06/14,8306280515
- B306200371 Forwards responses to open items from NRC 830201-03 fire protection audit
 VAN ERUNT.E E Arizona Public Bervice Co B3/06/15 KNIGHTON.G
 Licensing Branck 3 Sipp 18899 056 24X Fiche 50-528.B3/06/15.
 B306200371
- 830627036B Forwards responses to Ser, Suppl 4, Sections 13 3 2 2 & 13 3 2 3 (NUREQ-0857) are courses of action necessary in unlikely event of emergency at Pacilities Info will be included in Rev 3 to emergency plan
 VAN BRUNTLE E Arizona Public Service Co 83/06/15 KNIOHTON, Q Licensing Brench 3 26pp 18993 214 24X Fiche 50~528, 83/06/15, 830627036B
- B306270447 Responds to Generic Ltr B2-33 re Suppl 1 to NUREO-0737 concerning requirements for emergency response capability Unit 1 selected as backup smargency operations facility Exemptions from 10-mile criteria requested VAN BRUNILE E Arizona Public Service Co B3/06/16 KNIGHTON, Q Licensing Branch 3 Spp 18992 096 24X Fiche 50-528.83/06/16, B306270447.
- 8306210287 Forwards program plan issues & areas for outstanding items re NURE9-0737. Item I D i re detailed control room design review per NURE9-0700 requirements & SIR, NURE9-085/ Generic E.tr B2-33 issues addressed.

 VAN BRUNT, E.E. Arizona Public Service Co 83/06/17 KNIGHTON, G Licensing Branch 3 36pp 18914 038 24X Fiche 50-528, 83/06/17, 8306210287
- 8306270143 Forwards schedule for submittal of info required for NRC review of FSAR Schedule covers submittal of revised security plan & addl CES6AR interface requirements VAN BRUNT. E Arizona Public Bervice Co 83/06/20 KNIGHTON. © Licensing Branch 3 8pp 10788 001 24x Fiche, 50-528, 83/06/20, 8306270143

Q Adjudicatory correspondence

- 8306140427 Requests info needed to complete review of util proposed salt deposition & impact monitoring plan DEWEY.L S Hearing Branch 3 83/06/10 PLATT.W E Shell & Wilmer PLATT.W E Arizona Public Service Co 2pp 18838:045 24X Fiche 50-528.03/06/10.8306140429
- @ Inspection reports. IE Bulletins & correspondence
- 8306100009 Add) response to FOIA request for documents dtd 820101 or after re SALP Forwards App A documents Documents also available in PDR FELTON.J M Division of Rules and Records 83/04/11 CLARK.R. San Francisco Etaminer 3pp 18815 252 24X Fiche 50-000,83/04/11, 8306100009
- ---8306100014 Submits schedule for Region V SALP Board meetings for 820928-830523 ENGELKEN, R H Region 5, Office of Director 82/03/19 DENTON, H R Office of Nuclear Reactor Regulation, Director, 1p. 18815,255 24% Fiche 50-000,83/04/11,8306100009
- 8304010343 Requests extension until B30415 to determine suitable time for QA program implementation insp prior to QL issuance, per IE Insp Rept 50-528/83-04 ANDOONINI, Q C Arizona Public Service Co 83/05/13 STERNBERG, D M Region 5, Opfice of Director ip 18481 349 24X Fiche. 50-528, 83/05/13, 8304010343
- 8306070005 Forwards IE Insp Rept 50-528/83-17 on 830502-06 No nencompliance noted STERNBERG,D M Region 5. Office of Director 83/05/24 VAN BRUNT,E E Arizona Public Service Co 2pp. 18736:337 24X Fiche 50-528,83/05/24,8306070005.
- --B306070007 IE insp Rept 50-528/83-17 on B30502-06 No noncompliance noted Major areas inspected allegations associated w/ electrical & coating activities & licensee action on previous insp findings NARDUT, P. P. BURDOIN J. F., YOUNG, T. Region 5, Office of Director 83/05/23 14pp 18736-339 24X Fiche 50-528,83/05/24,8304070005
- 830.6070252 Forwards IE Insp Repts 50-528/83-18, 50-529/83-10 & 50-530/83-08 on 830301-0430 & notice of violation.
 STERNBERG, D M Region 5, Diffice of Director 83/05/25 VAN BRUNT. E E Arizona Public Service Co 2pp 18740: 340 24% Fiche: 50-528, 83/05/25, 8306070252
- --8306070253 Notice of Violation from insp on B30301-0430 VDRDERBRUEGGEN Region 5, Office of Director B3/05/25, 2pp 18740 342, 24X Fiche 50-528,83/05/25,8306070252,
- --8306070286 1E Insp Repts 50-528/83-18,50-529/83-10 & 50-930/83-08 on 830301-0430 Noncompilance noted:power cables for containment spray pump drive motors w/unsupported lengths longer than 24 inches & cables trays not grounded at both ends. VORDERRRUEGOEN, YOUNG, T. Region 5, Office of Director 83/05/24 App. 18740 244, 24x Fiche 50-528,83/05/25,8306070252.
- 8305110458 IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in Well Logging Device " Svc list encl TAYLOR, J M Division of Bafeguards & Inspection Programs (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc. 125pp 18831-043 24X Fiche 50-000.83/05/26,8305110458
- 8305110460 IE Info Notice 83-34, "Event Notification Info Worksheet." 8vc list encl JORDAN, C. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co. of New York, Inc. 115pp 18732-085 24X Fiche 50-000, 83/05/26, 8305110460
- 8305110461 IE Info Notice 83-35. "Fuel Novement W/Control Rods Withdrawn at BWRs " Byo list encl. JORDAN.E.L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/31. Consolidated Edison Co. of New York Inc. 116pp 18732 208 24X Fiche.50-000.83/05/31.8305110461
- 8304280137 Forwards IE Insp Rept 50-528/83-12 on 830424-29 & 0512 No noncompliance noted.
 800K; HE Region 5: Office of Director. 83/06/03 ANDOGNINI.Q.C. Arizona Public Service Co 2pp 19014; 333 24X Fiche. 50-528: 63/06/03
- --8306280145 IE Insp Rept 50-528/83-12 on 830424-29 & 0512. No noncompliance noted Major areas inspected. Pollowup on IE into notices, organization & staffing, environ protection, resolution 10CFR80 55(e) & NUREO-0737. Items II F. 1 & II.B.3. SHERMAN.C , NORTH.H S , HENSLAHSKI.F.A. Region 5. Office of Director 83/06/03. 16pp. 19014:335. 24X Fiche.50-528.83/06/03.8306280137

- 8305110464 IE Info Notice 83-36, "Impact of Security Practices on Safe Operations" Syc list encl JORDAN E L Division of Emergency Preparedness & Ingineering Response (Post 830103) 83/06/09 Consolidated Edison to of New York Inc 119pp 18830 280 24% Fishe 50-000,83/06/09.8305110464
- 8306280450 Forwards IE Insp Repts 50-528/83-19 & 50-529/83-11 on 830502-31 No noncompliance nated STERNBERO, D M Region 5, Office of Director 83/06/09 ANDOONINJ.0 C Arizona Public Service Co 2pp 19020 168 24X Fiche 50-528
- --8306280452 IE Insp Repts 50-528/83-19 & 50-527/83-11 on 830502-31 Nn noncompliance noted Major areas inspected startup testing procedures: plant cleanliness, control room cooler line rupture & allegation re lifting of leads FIORELLI,0: JOHNSTON.0:, YOUNG.T Region 5, Office of Director 83/06/03 6pp 19020 170 24X Fiche 50-528,83/06/09,8306280450
- 8305110470 IE Info Notice B3-38. "Defective Heat Sink Adhesive & Seismically Induced Chatter in Relays Within Printed Circuit Cards" Svc list encl.
 JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post B30103) 83706/13 Consolidated Edison Co of New York, Inc. 118pp 18920 225 24X Fishe 50-000, 83/06/13, 8305110470
- 8306090010 IE Info Notice 83-37. "Transformer Failure Resulting From Degraded Internal Connection Cables " Svc list encl JORDAN E. L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co of New York, Inc. 243pp 18921 001. 24X Fiche 50-000.63/06/13.8306090010
- 8306230252 Responds to IE Insp Rept 50-528/83-06 & requests proposed & alternate dates for insp of QA program Suggests 830822-26 as insp date & 830827-0902 as alternate date ANDOGNINI.0 C Arizona Public Service Co B3/06/14 STERNBERG, D M Region 5, Office of Director ip 18745 226 24X Fiche.50-528,83/06/14,8306230252
- 8306280515 Forwards IE Insp Rept 50-528/83-21 on 830523-27 No noncompliance noted STERNBERG.D H Region 5. Office of Director 83/06/14 ANDOGNINI.G C Arizona Public Service Co 2pp 19017 199 24X Fiche 50-528,83/06/14,8306280515
- --B306280519 IE Insp Rept 50-528/83-21 on 830823-27 No noncompliance noted Major areas inspected fire protection/prevention program implementation SCOMN.K. YOUNG.T Region B. Office of Director 83/06/14 Bpp 19017-201 24X Fiche 50-528.83/06/14.8306280515
- 8306280303 Forwards IE Insp Rept 50-528/83-20 on 830524-25 No noncompliance noted BOOK.H Region 5, Office of Director 83/06/16 VAN BRUNT, E Arizona Public Service Co. 2pp 19014 097 24X Fiche: 50-528,83/06/14,8306280303
- --8306280310 IE Insp Rept 50-528/83-20 on 830524-25 No noncompliance noted Major areas inspected lab capability to perform chemical & radiochemical analyses HAMADA, O, MENSCAMBKI, F. BODN, H E Region 5, Optice of Director 83/06/16 3pp 17014 099 24X Fiche 50-528,83/06/16,8306280303
- 8305110475 lE Info Notice 83-40, "Need to Environmentally Qualify Epoxy Grouts & Bealers " Syc list encl JURDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/06/22 Consolidated Edison Co. of New York, Inc. 115pp. 17021 179 24X Fishe 50-000,83/06/22,8305110475
- 8305110477 IE Info Notice 83-41, "Actuation of Fire Buppression Sys Causing Inoperability of Safety-Related Equipment " Svc list encl JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/22 Consolidated Edison Co of New York, Inc. 120pp 18997 007 24X Fiche 50-000,83/06/22.8305110477
- 8305i10477 IE Info Notice 83-42, "Reactor Mode Switch Malfunctions of Syc list encl Syc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) B3/06/23 Consolidated Edison Co of New York, Inc. 116pp. 18996-242, 24X Fiche 50-000,83/06/23,0305110477
- 8305110483 IE Info Notice 83-43, "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints "Svc list encl. JORDAN.E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 89/06/24. Consolidated Efison Co of New York, Inc. 116pp. 19046:297 24X Fiche 50-000,83/06/24.8305110483

- S Reportable occurrences, LERs & related correspondence
- 8304010137 Interim Deficiency Rept DER BU-9 re low pressure safety injection pump A suction strainer containing foreign matl & pump B w/torn strainer Initially reported on 830216 Due to extensive evaluation, final rept will be submitted by 830715 VAN DRUNT, E E Arizona Public Service Co 83/05/11 STERNBERC.D M Region 5. Office of Director 2pp 18474 042 24X Fiche 50-528,83/05/11,830401013/
- 8306010289 Interim Deficiency Rupt DER 83-22 re failure of ITE Obulé circuit breaker for hydrogen recombiner to function properly Initially reported on 830413 Dechtel & Rockwell Intl working on circuit breaker Next root by 83108 VAN BRUNT, E.E. Axizona Public Service Co. 83/05/11 STERNBERG, D. H. Region 5, Office of Director .3pp. 106/2 195 .24X Fiche 50-528,63/05/11.8306010289
- 830&01007& Interim Deficiency Rept DEM 80-10 re main steam relief valve tests exceeding 5% blowdown limit Initially reported on 830&28 Submittal of final rept extended to 830&30 VAN DRUNT,E E Arizona Public Service Co 83/05/16 STERNBERG,D M Region 5, Office of Director 2pp 186/4 096 24% Fiche 50-528,83/05/16,830&010076
- 8306010119 Interim deficiency rept re underground cables to startup transformers unable to carry full-load current at mai site soil temp Initially reported on 821126 Final rept submittal extended to 830729 due to extensive investigation VAN DRUNTLE E Alizona Public Service Co. 83/05/16 STERNBERGID M. Region 5. Office of Director 2pp 18673 360 24X Fiche 50-528,83/05/16.8306010119
- 8304010272 Rev 2 to Final Deficiency Rept DER 92-78 re improperly crimped termination lugs in control panels for water chillers supplied by Carrier; revising panel numbers initially reported on 821217 Also reportable under Part 21 VAN BRUNT, E E Arizona Public Service to 83/05/14 STERNDLRO, D M Region 5, Office of Director 3pp 18672 246 24% Fiche 50-528,83/05/16,83060102/2
- 8306010375 Final Deficiency Rept DER 82-39 re C-E valve limit switches (Class IE) below max LOCA flood level in containment Initially reported on 820730 Bechtel review complete Condition determined not reportable por 10CFR50 55(e) VAN BRUNT, E E Arizona Public Service Co 83/05/16 23pp 18682 080, 24X Fiche 50-528,83/05/16,8306010375
- 8306010055 Final Deficiency Rept 83-24 re diesel generator lube oil & jacket water heaters not maintaining required temp Initially reported on 830421 Design Change Packages 25M-DQ-029 & 36M-DQ-029 issued to install new heaters VAN BRUNI.E E Ari ona Public Service Co 83/05/18 STERNDERG, DR Region 5. Office of Director 3pp 10573 330 24X Fiche 50-528,83/05/18.8305010055
- 8304010072 Rev 1 to Interim Deficiency Rept DER 82-61 re potential for reactor coolant pump diffusor ring cap screws to fail & damage pump Initially reported on 821021 C-E reviewed potential failure mechanisms final rept by 830725 VAN BRUNT, E E Arizona Public Service (o 83/05/18 STERNDFR0.D H Region 5. Office of Director 4pp 10473 274 24X Fiche 50-528.83/05/18.8304010072
- --0304010078 "Reactor Coolant Pump Diffuser Bolt Failure Summary "
 COLON,F P Combustion Engineering, Inc 03-0002 03/04/04 0pp
 18673 278 24X Fiche 50-328,83/05/10.83060100/2
- --8306010083 App 1 to. "Metallurgical Investigation of Diffuser/Rearton Communication Bolt Failures (791350) " BOLLANSKY, K W Combustion Engineering, Inc. TR-MCM-112 82/11/24 30pp 18673 286 24X Fiche 30-528,83/05/18.8306010072
- --83060100B7 App 2 to. "Metallurgical Exam of Diffuser/Reactor Coolant Pump Casing Bolts Returned From AZ Unit 2 (791350) " DDLLAMSKY, K W Combustion Engineering, Inc TR-V-MCM-003 83/01/25 14pp 18673 316 24X Fiche 50-528,83/05/18,830601072
- B30-6070225 Final Deficiency Rept DER 83-23 re failure of M81V bypass valves to close in required time Instially reported on B30419 Solenaid valve replaced Problem investigation request issued by Bechtel Also reported per Part 21 VAN BRUNT, E E Arizona Public Service Ca 83/05/19, STERNDERG, D H Region 5, Office of Director, Spp 16744 217 24% Fiche 50-528,83/05/19,8306070225
- 8306100203 Part 21 rept re deficiency in aix emergency standby diesel generator sets mfg by Cooper Energy Svcs Jacket water heater & lube oil heater will be replaced w/40 kW & 19 kH versions, respectively, to maintain 120 F standby temp STOLBA.F B Cooper Industries, Inc 83/05/20 Director's Dffice. Office of Inspection and Enforcement 2pp 18806 007 24X Fiche 50-528,83/05/20,8306100203

- 8306070078 Interim Deficioncy Rept DER 82-63 re design calculation error in refueling water tank seismic response Initially reported on 821026 Time extension requested until 830624 to submit final rept VAN BRUNT.E E Alizona Public Service Co 83/05/24 STERNBERG, D M Region 5. Office of Director 2pp 18739 272 24X Fiche 50-528, 83/05/24, 8306070078
- 830&070221 Interim Deficiency Rept DER 82-56 re condensate storage tank design scaled down w/o new calculations for selsmit response Initially reported on 821015 final rept delayed until 830&24 due to extensive investigation & evaluation VAN BRUNT. E Anizona Public Service Co 83/05/24 STERNBERG, D M Region 5. Office of Director 2pp 10746 136 24X Fiche 50-528,83/05/24,830&070221
- 8306070178 Interim Deficiency Rept DER 82-46 re failure of ITI-Barton pressure transmitters supplied by GE to meet overpressure requirements Initially reported on 820824 Submittal of final rept delayed until 830830 due to extensive investigation VAN GRUNT.E E Arizona Public Service Co 83/05/25 STERNBERG.D M Region 5, Uffice of Director 2pp 18736 327 24X Fiche 50-528,83/05/25,8306070178
- 8306170240 Interim Deficiency Rept DEN 83-26 re balance of ESF actuation sys electronic module failure in preoperational testing due to overheating Initially reported on 830427 Final evaluation expected by 830825 VAN ERUNI, C E Ariona Public Service Co 83/05/25 STERNBERG, D M Region 5, Office of Director 3pp 18882 322 24X Fiche 50-538, 83/05/25, 8306170240
- 8306170180 Interim Deficiency Rept DER 80-25 rellack of instrumentation tubing boundary class break requirements Initially reported on 830421 Evaluation & final rept will be submitted by 830630
 - WAN ERUNT, E. E. Arizona Public Service Co. 83/05/26 STERNBERG, D. M. Region 5, Office of Director 5pp. 18883, 258 24X
 Fiche 50-528, 83/05/26, 8306170180
- 8306170246 Final Deficiency Rept DER 83-28 re Pacific Scientific snubbers installed in violation of reserve range requirements Initially reported on 830427 8pec Change Notice 3390 issued to clarify intent of Spec 13-PH-204 VAN BRUNT, E E Arizona Public Scrvice Co 83/06/01 STERNBERG, D M Region 5, Office of Director Spp 18883 274 24X Fiche 50-528,83/06/01,8306170246
- 8306170342 Interim Deficiency Rept 82-51 re Pullman-Kellogg essential cooling water sys pipeline failure Completion date for final rept extended to 830706 VAN BRUNT, E E Arizona Public Service Co 83/06/01 STERNDERG, D M Region 5. Office of Director 2pp 18880 289 24% Fiche 50-528,83/06/01.8306170342
- 8306170373 Interim Deficiency Rept DER 82-50 re possibility of damage to flexible conduit couplings between auxiliary & control bldgs if seismic event exceeds 3/4-inch movement Initially reported on 820710 Final rept will be available by 830706 VAN BRUNT.E E Alitona Public Service Co 83/06/01 STERNBERG, D M Region 5, Office of Director 2pp 18080 238 24X Fiche 50-528.83/06/01,8306170393
- B306170366 Interim Deficiency Ropt DER 83-31 re temp rise in diesel generator control cabinet potentially exceeding design requirements Initially reported on 830505 Bechtel & Cooper Energy Sycs evaluating condition Final rept by B30906 VAN BRUNT, E E Arizona Public Service Co 83/06/06 STERNDERO, D N Region 5. Office of Director 3pp 10880 319 24X Fiche 50-528.83/06/06.8306170366
- 8306170367 Final Deficiency Rept DER-29 re two pipe hangers in safety injection sys not installed as designed Supports 1-81-100-H-005 & 1-81-106-H-007 repaired per design drawings & drawings revised to clarify bar locations
 VAN BRUNT: E E Arizona Public Service Co 83/06/06 STERNBERG, D M Region 5. Office of Director App 10880 220 24X
 Fiche 50-528,83/06/06.8306170367
- 8306:30:50 Part 21 rept re solenoid activated valves, Models 770-001 & 770-003 Defects include incorrect valve assembly, significant missing parts, limited switch valve position indication failures & failure of valve to open & close PUTTARINI,D M Tunget Rock Gorp 83/06/07 DEYDUNG, R C Director's Office, Office of Inspection and Enforcement 7pp. 18824 267 24X Fiche 50-528,83/06/07.8306:30:150
- 8306230270 Final Deficiency Rept DER 83-28 me Pacific Scientific anubbers installed in violation of reserve range requirements. Deficiency determined not reportable per 100FR80 55(e).

 VAN BRUNT, E.C. Arizona Public Service Co. 83/06/08 STERNBERG, D. M. Region 5. Office of Director. 4pp. 10745 108 24X Fiche 50-528, 83/06/08, 8306230270

- 8306230318 Advises that final Deficiency Rept DER 83-14 re Wastinghouse diesel generator protective relay failures due to leaking capacitors will be submitted by 830831 Delay due to extensive investigation & evaluation

 VAN BRUNT, E E Arizona Public Service Co 63/06/08 STERNBERG, D M. Region 5. Office of Director 2pp 16744 164 24X

 Fiche 50-528,83/06/08,8306230318
- 8306230408 Interim Deficiency Rept DER 83-10 re main steam relief valve test exceeding specified 5% aloudown limit Initially reported on 830228 Submittal of final rept delayed until 830818 due to extensive investigation & evaluation required VAN DRUNT.E E Arizona Public Service Co 83/06/08 STERNBERO, D. M. Region 5. Office of Director 2pp 18943: 132 24X Fiche 50-528,83/06/08,8306230408
- 8306230245 Requests extension until 830714 to submit final deficiency rept re requirements on tagged-out cable terminations, due to extensive investigation & evaluation required VAN BRUNT, E E Arizona Public Service Co 83/06/15. STERNBERG, D. M Region 5, Office of Director 2pp 18945, 231 24X Fiche 50-528, 83/06/15, 8306230245
- DOCKET STN-50-529 PALO VERDE NUCLEAR STATION, UNIT 2
- A Application/construction stage documents & correspondence
- 8304080284 FOIA request for documents re R Ounderson & Bechtel senior manager allogations concerning electrical problems & deficiencies at facilities Haiver of fres requested. YOUNO, M C Government Accountability Project 83/03/29, Office of Administration. 2pp 18790.357. 24X Fiche 50-528,83/03/29, 8304080284
- 8306140225 Forwards Conference Notes CN-E-1255 from B30323 meeting w/util.counsel.Bechtel.NRC & C-E in Washington.DC repost-LDCA containment sump HILSON.W H Bechtel Corp B3/04/14. VAN BRUNT.E.E Arizona Public Service Co 3pp 18844 322. 24X Fiche.50-528.83/04/14.8306140225
- 8304080281 Partial response to FDIA request for documents re R Gunderson & Bechtel allegations concerning electrical problems at facilities App A Documents 1 & 2 available in PDR Documents 3,4 & 5 withheld (ref FOIA Exemption 5), FELTON, J M Division of Rules and Records 83/04/28, YOUNG, M C. Government Accountability Project 3pp. 18790-354 24X Fiche 50-528,83/04/28,8304080281.
- 8304020627 Notification of 830422-23 & 24 meetings w/util in Maricopa & Phoenix.AZ, respectively, to assess current status of const LICITRALE A Licensing Branch 3 83/05/24 KNIGHTON.O W. Licensing Branch 3 6pp 18716 339. 24X Fiche 50-528,83/05/24,8306020627
- 8306070091 Advises that schedule for responding to five confirmatory items & completion of qualification program for safety-related pumps & valves will be submitted by 830630 VAN BRUNT, E.E. Arizona Public Service Co. 83/05/31 KNIOHTON, Q. W. Licensing Branch 3 ip 18739 141. 24X Fiche, 50-528, 83/05/31, 8306070091
- 9304080097 Summary of B30317 meeting w/util, C-E & Bechtel in Bethesda, MD re NRC 830314 requested info on environ qualifications Environ qualification audit scheduled during wk of 830627 LICITRA, E A Licensing Branch 3 93706/01 Licensing Branch 3 4pp 18787 327, 24% Fiche 50-528.83/06/01.8306080097
- 8306200051 Notification of 830608 meeting w/util in Bethesds, ND to discuss control room design review, LICITRALE A Licensing Branch 3 83/06/03 KNIGHTON, 9 W Licensing Branch 3 3pp. 18908 286 24X Fichs, 50-528, 83/06/03, 8306200051
- 8306200053 Notification of B30628-30 & 0701 meetings w/util, Bechtel, C-E & E6&G in Phoenix & Maricopa County, AZ to conduct audit of equipment environ qualification documentation.

 LICITRA: E.A. Licensing Branch 3 83/06/03 KNIGHTON, G. W. Licensing Branch 3 3pp. 18908 289 24X Fiche 50-528, 83/06/03, 8306200053,
- B306170265 Forwards marked-up Amend 12 to FSAR Section 17.1 re QA program for engineering, design procurement & const of facility, per 100F850 55(f).

 VAN BRUNT,E E Arizona Public Service Co. 83/06/10 STERNBERG, D M Region 5, Office of Director 82pp 18877.274 24X Fiche 50-528,83/06/10.8306170265

- 8306170302 Forwards App J to, "Evaluation of Pressursied Thermal Shock Effects Due to Small Break LOCAs W/Loss of Feedwater for Palo Verde : & 2,2 & 3 Reactor Vessels "Rept applies to only Unit 1
 VAN BRUNT.E E. Arizona Public Service Co 83/06/14 KNIGHTON, G Licensing Branch 3 3pp 18878 197 24X Fiche 50-528,83/06/14, 8306170302
- 8306170351 Forwards response to 830503 request for info supplementing 830322 info on FBAR Table 3 2-1 re quality classification of structures sys & components VAN BRUNTLE E Arizona Public Service Co 83/06/14 KNIGHTON. G Licensing Branch 3 14pp 18881-005 24X Fiche 50-528,83/06/14, 8306170351
- 8306240458 Summary of B30608 meeting w/util in Bethesda.MD re detailed control room design review LICITRA.E A Licensing Branch 3 B3/06/14 Licensing Branch 3 4pp 18998 001 24X Fiche 50~528.83/06/14.8306240458
- 8306280436 Forwards Amend 1 to environ qualification rept.psr 830314 request & NUREQ-0588 requirements VAN BRUNT,E E Arizone Public Service Co 83/06/24 KNIGHTON,G Licensing Branch 3 228pp. 19016 297 24X Fiche 50-528,83/06/24,8306280436
- E NRC Safety Evaluation Report (SER), supple & correspondence
- 8306190492 Responds to 830328 request for add1 info re adequacy of electric distribution sys voltages per SER (NUREO-0857) Response re adequacy of util info requested within 2 wks VAN SRUNT, E.E. Arizona Public Service Co. 83/06/07. KNIGHTON, O. Licensing Branch 3. App. 18821: 195 24X Fichs. 50-528, 83/06/07, 8306130432
- 8306160500 Advises that procedures indicating shutdown cooling relief valves armed by manually opening shutdown cooling sys isolation valves will be utilized until operable low temp overpressure alarm available, per NUREO-0857, 80pp; 1

 VAN BRUNT, E.E. Arizona Public Service Co. 83/06/13 KNIGHTON, G. Licensing Branch 3 ip 18864 156 24X Fiche 50-528, 83/06/13, 8306160500
- B306170326 Forwards proposed amend to FSAR re CESSAR iodine removal sys & responses to NRC 830422 ltr Proposed FSAR amend combined w/responses closes out sump ph issue in SER Sections 6 4 & 15.4 8 & TMI Item III D 3.4

 VAN BRUNT,E.E. Arizona Public Service CD 83/06/13 KNIGHTON,G Licensing Branch 3 8pp 18879 040 24X Fiche 50-528.83/06/13,8306170326
- 830A270368 Forwards responses to SER, Suppl 4. Sections 13 3 2 2 & 13 3.2 3 (NUREG-0857).re courses of action necessary in unlikely event of emergency at facilities info will be included in Rev 3 to emergency plan
 VAN BRUNT.E E. Arizons Public Service Co. 83/06/15. KNIGHTON, O Licensing Branch 3 26pp 18993 214 24X Fiche 50-526.83/06/15. 8306270368
- B306210287 Forwards program plan issues & areas for outstanding items re NUREO-0737. Item I D i re detailed control room design review per NUREO-0700 requirements & BER, NUREO-0857 Generic Ltr 82-33 issues addressed VAN BRUNTLE E Arizona Public Service Co B3/06/17 KNIGHTON, O Licensing Branch 3 36pp 18914 038 24X Fiche 50-528,83/06/17, B306210287
- B306280317 Submits required data to demonstrate that line voltage regulators perform as acceptable isolation device by limiting primary current under short circuit conditions to full-load primary currentsper SER (NUREQ-0857)

 VAN BRUNTLE E Arizona Public Service Co 83/06/23 KNIGHTON G Licensing Branch 3. ip 19001,282 24% Fiche 50-528,83/06/23,8306280317.
- F. Security, medical, emergency & fire protection plans
- 8306170356 Forwards description & list of objectives for 8305)1 emergency preparedness exercise Scenario will be provided within 30 days. Comments requested within 15 days of ltr dets.

 ANDONINI. C. Arizona Public Service Co 83/03/02 GRIMPS, B K Division of Emergency Preparedness (Pre 830103) 17pp. 18880 333 24X Fiche: 50-528, 83/03/02, 8306170356
- --8306170360 Forwards description & list of objectives for 830511 energency preparedness exercise. Scenario will be provided within 30 days. Cumments requested within 15 days of ltr dats.

 AMDOSNINI. Q. C. Arizona Public Service Co 83/03/02 MARTIN.R. Region 5, Dffice of Director. 10pp 18880.352, 24x Fiche. 50-528.83/03/02,8306170356

- 8306020056 Responds to 830414 ltr re Generic Ltr 82-33 requirements concerning Suppl I to NUREG-0/37 Portion of response addressing detailed control room design review does not provide all info requested Response requested by 830531 KNIGHTON.C W Licensing Branch 3 83/05/10 VAN BRUNT.E E Arizona Public Service Co App 18701 349 24X Fiche 50-528,83/05/10.8306020056
- 8304030357 Advises that addl info re detailed control room design review per Generic Ltr 82-33 re emergency response capabilities will be submitted by 830417 VAN BRUNT, E Arizona Public Service Co 83/04/01 KN10+110N, G Licensing Branch 3 lp 18705 214 24X Fiche 50-528,83/04/01,8304030357
- 8306090273 Releases public version of revised emergency plan implementing procedures FELTON, J M Division of Rules and Records 83/06/03 Document Management Branch ip 18810 067 24% Fiche 50-528,83/06/07, 8306090273
- --8306090275 Forwards public version of revised emergency plan implementing procedures, including Procedures EPIP-01 re emergency organization, EPIP-02 re emergency classification & EPIP-04 re alert implementing actions.

 VAN BRUNT, E E Arizona Public Service Co 83/05/23 KNICHION, 6 Licensing Branch 3 3pp 18810 060 24% Fiche 50-528, 03/06/03, 8306090273
- --8304090276 Public version of revised emergency plan implementing procedures, including Procedures EPIP-01 re emergency organization, EPIP-02 re emergency classification & EPIP-04 re alert implementing actions LUCIA: S Arizona Public Service Co 83/03/30 708pp 18810 071 24X Fiche 50-528,83/06/03,83040902/J
- 8306200371 Forwards responses to open items from NRC 830201-03 fire protection audit.

 VAN BRUNT, E E Arizona Public Service Co \$3706/15 KNIGHTDM. 0 Licensing Branch 3 31pp 18899 056 24X Fiche 50-528,83706/15. 8306200371
- 8306270368 Forwards responses to Ser, Suppl 4, Sections 13 3 2 2 & 13 3 2 3 (NUREG-0857), re courses of action necessary in unlikely event of emergency at facilities Info will be included in Rev 3 to emergency plan

 VAN BRUNT, E E Arizona Public Service Co 83/06/15 KNIGHTON, 9 Licensing Branch 3 26pp 18993 214 24X Fiche 50-528, 83/06/15, 8306270368
- 8306270447 Responds to Generic Ltr 82-33 re Suppl 1 to NUREG-073/concerning requirements for emergency response capability Unit 1 selected as backup emergency operations facility Exemptions from 10-mile criteria requested VAN BRUNT.E E Arizona Public Service Co 83/06/16 KN19HTON.G Licensing Branch 3 3pp 10992 095 24X Fiche 50-528.83/06/16, 8306270447
- 8306210287 Forwards program plan issues & areas for outstanding items re NUREO-0737. Item I D 1 re detailed control room design review per NUREO-0700 requirements & SER, NUREO-0857 Generic Ltr 82-33 issues addressed VAN BRUNT, E E Arizona Public Service Co 83/06/17 KNIGHTON, 0 Licensing Branch 3 36pp 18914 038 24X Fiche 50-528, 83/06/17. 8306210287
- @ Adjudicatory correspondence
- 8306030333 Response to second set of interrogatories Certificate of Svc entl BERLIN.K West Valley Agricultural Protection Council, Inc 83/06/01 Office of the Executive Legal Director 10pp 18709 018 24X Fiche 50~529.83/06/01.8306030333
- --8306030334 Request for production of documents identified in response to first & second set of interrogatories & documents requested in interrogatories Certificate of Svc encl BERLIN.K West Vailey Agricultural Protection Cauncil, Inc 83/06/01 Arizona Public Service Ca App. 18709 028 24X Fiche 50-529,83/06/01.8306030333
- --8306030335 Response to second set of interrogatories Certificate of Svc entl. BERLINK West Valley Agricultural Protection Council, Inc. 83/06/01 Arizona Public Service Co. 42pp 18709 034. 24X Fiche 50-589,83/06/01,8306030333

- 830&150398 Stipulation agreeing that motions to compel interrogatory answers due 830715 & supplemental info responding to interrogatories due 830701 Proposed order & Certificate of Svc encl
 - Svc encl
 DEHEY, L S Hearing Branch 3 DERLIN, K West Valley Agricultural
 Protection Council, Inc PLATT, W Joint Applicants-Palo Verde
 83/06/01 5pp 18847 140 24% Fiche 50-527,83/06/01,8306150398
- 830&090311 Withdrawal of 830526 request to extend time to respond to revised discovery schedule No addl time needed to review schedule Schedule acceptable Certificate of Svc encl DRHEY.L B Hearing Branch 3 83/06/08 Atomic Safety and Licensing Board Panel 3pp 18795 196 24X Fiche 50~529,83/06/08.
- 8306100075 Forwards Hest Valley Agricultural Protection Council, Inc & Jaint Applicants stipulation re discovery schedule mod ENG, H B West Valley Agricultural Protection Council, Inc 83706/09 LAZOLR M Atomic Safety and Licensing Board Panel ip 18803 164 24X Fichs 50-529,83/06/09,8306100075
- --8306100078 Stipulation agreeing to comply w/provisions of proposed order, unless & until further mod requested by parties ASLB should enter encl order re discovery schedule mod BERLIN.X Host Valley Agricultural Protection Council, Inc PLATT.W E Joint Applicants Palo Verde PLATT.W E Bnoll & Wilmer 83/06/09 6pp 18803 165 24X Fiche 50-529.83/06/09, 8306100075
- B306140429 Requests info needed to complete review of util proposed salt deposition & impact monitoring plan DEWEY,L S. Hearing Branch 3 B3/06/10 PLATT,WE Snell & Wilmer FLATT,WE Arizona Public Service Co 2pp 18838 045 24X Fiche 50-528,83/06/10.8306140429
- B306150304 Request for production of documents Certificate of Byc encl CRAMFORD.VA Joint Applicants Palo Verde CRAMFORD.VA Bhell & Wilmer B3/06/10 West Valley Agricultural Protection Council, Inc 10pp 18849 152 24X Fiche 50-529,83/06/10,8306150304.
- B306160622 Order directing motions to compel re interrogatory answers be filed by 830715 Supplemental responses to interrogatories to be filed by B30701
 LAZO,R M Atomic Safety and Licensing Board Panel 83/06/14 Ip. 18865
- B306160629 Order delineating schedules for depositions discovery on crop study & pretrial preparation
 LAZO,R.M. Atomic Safety and Licensing Board Panel 83/06/14. App 18866 122 24X Fichs 50-529.83/06/14.8306160629
- 8306210264 Request for production of documents Certificate of Byc and DEMEY, L B Hearing Branch 3 83/06/17. West Valley Agricultural Protection Council, Inc. 4pp 18915 027 24X Fiche 50-529, 83/06/17.8306210264
- 830621026B Request for production of documents Certificate of Svc encl DEWEY,L.8 Hearing Branch 3 83/06/17 Arizona Public Service Co App 18914 005 24X Fiche 50-529,83/06/17,8306210268
- BGO6240284 Forwards util 830426 application for SNM license DEMEY, L S Hearing Branch S BG/06/21 LAZD, R M , CALLIHAN, D . COLE, R F. Atomic Bafaty and Licensing Board Panel, 149pp. 18979 291 24X Fiche 50-827,83706/21,8306240284
- G Inspection reports, IE Bulletins & correspondence
- 830&100009 Add1 response to FDIA request for documents dtd 820101 or after re BALP Forwards App A documents Documents also available in PDR FELTON.J M Division of Rules and Records 83/04/11 CLARK.R. San Francisco Examiner 3pp. 18815 252 24X Fiche.50-000/83/04/11. 830&100009
- --8306100014 Submits schedule for Region V SALP Board meetings for 820728-830823 ENGELKEN, R H. Region 5, Office of Director 82/03/19. BENTON, H R. Defice of Nuclear Reactor Regulation. Director 1p. 18815-255 24X Fiche: 50-000, 83/04/11, 8306100009
- B306070252 Forwards IE Insp Repts 50-528/83-18, 50-529/83-10 & 50-930/83-08 on 830301-0430 & notice of violation STERNBERO, D. M. Region 5, Office of Director. 83/05/25 VAN BRUNT, E E Arizona Public Service Co 2pp. 18740-340. 24% Fiche, 50-528, 83/05/25, 8306070252
- --8306070253 Notice of violation from insp on 830301-0430. VORDERBRUEGGEN Region 5, Office of Director, 83/05/25, 2pp. 18740 342 24X Fiche 50-528,83/05/25,8304070252

- --8304070254 1E Insp Repts 50-528/83-18.50-529/83-10 & 50-530/83-08 on 830301-0430 Noncompliance noted power cables for containment spray pump drive motors w/unsupported lengths longer than 24 inches & cables trays not grounded at both ends VORDERBRUEGGEN, YOUNG, T Region 5. Office of Director 83/05/24. 6pp 18740 344. 24X Fiche 50-528.83/05/25,8306070252
- 830511045B IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in Well Logging Device" Syc list encl. TAYLOR, J M. Division of Safeguards & Inspection Programs (Post 830103) B3/05/26 Consolidated Edison Co. of New York, Inc 125pp 18831 043. 24% Fichs 50-000,83/05/26,8305110458
- 8305110460 IE Info Notice 83-34, "Event Notification Info Worksheet "
 8vc list encl
 VGRDAN.E L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/05/26, Consolidated Edison Co. of New
 York, Inc. 115pp 18732.085 24x Fiche.50-000,83/05/26,8305110460.
- 8305;10461 IE Info Notice 83-35, "Fuel Hovement W/Control Rods Withdrawn at BMRs." Evc list encl JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830t03) 83705/31 Consolidated Edison Co. of New York, Inc. 116pp 18732 208 PAX Fiche 50-000,83705/31,8305110461.
- 8305110464 IE Info Notice 83-36, "Impact of Security Practices on Safe Operations," Svc list encl. JORDAN E L. Division of Emergency Preparadness & Engineering Response (Past 830103). 83706/09 Consolidated Edison Cs. of New York: Inc. 119pp. 18830 280. 24X Fichs 50-000,83706/09,8305110464
- 8306280490 Forwards IE Insp Repts 50-528/83-19 & 50-529/83-11 on 830502-31 No noncompliance noted. STERNBERG.D M. Region 5. Dffice of Director. 83/06/09. ANDOOMINI,0 C. Arizona Public Service Co. 2pp 19020 168 24X Fiche 50-528,83/06/09.8306280450
- --8306280452 IE Insp Repts 50-528/83-19 k 30-329/83-11 on 830502-31 No noncompliance noted Major areas inspected startup testing procedures, plant cleanliness, control room cooler line rupture & allegation re lifting of leads.
 FIRELLI,0, JOHNSTON.0, YOUNG.T Region 5, Office of Director. 83/06/03 App. 19020 170 R4X Fiche 50-528/83/06/09,8306280450.
- B305110470 IE Info Notice 83-38, "Defective Heat Sink Adhesive & Seismicelly Induced Chatter in Relays Within Printed Circuit Cards "Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13, Consolidated Edison Co of New York, Inc. 118pp 18720:225 24x Fiche: 50-000.83/06/13,8305110470
- 8306090010 IE Info Notice 83-37, "Transformer Failure Resulting From Degraded Internal Connection Cables " Svc list encl. JORDAN E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co. of New York, Inc. 243pp 18921.001. 24X Fiche, 50-000, 83/06/13, 8306090010.
- 8308110475 IE Info Notice 83-40, "Need to Environmentally Qualify Epoxy Grouts & Smalers." Swc list encl.
 JORDAN E L. Division of Emergency Preparedness & Engineering Response (Fost 830103). 83/06/22. Consolidated Edison Co. of New York, Inc. 115pp 17021 179 24X Fiche: 50-000,83/06/22,8305110475
- 8305110477 IE Info Notice 83-41: "Actuation of Fire Suppression Sys Causing Inoperability of Safety-Related Equipment " Syc list encl JCRDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103). 83/06/22 Consolidated Edison Co. of New York, Inc. 120pp. 18997.007 24X Fiche: 50-000,83/06/22,8305110477.
- 8305)10479 IE Info Notice 83-42, "Reactor Mode Switch Melfunctions." Svc list encl. JORDAN:E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/23 Consolidated Edison Co. of New York, Inc. 116pp. 18996-242 24X Fiche. 50-000, 83/06/23, 8305110479.
- 8305110483 IE Info Notice 83-43, "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints," Svc list encl. JORDAN-E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/24 Consolidated Edison Co of New York, Inc. 116pp. 19046-297. 24X Fiche 50-000.83/06/24.8305110483.
- 8 Reportable occurrences, LERs & related correspondence
- 830&010289 Interim Deficiency Rept DER 83-22 re failure of ITE Gould circuit breaker for hydrogen recombiner to function properly Initially reported on 803413. Becktel & Rockwell Intl working on circuit breaker Next rept by 831108 VAN BRUNT.E.E. Arizona Public Service Co. 83/05/11. STERNBERG.D.M. Region 5. Office of Director. 3pp. 18672:195. 24X Fiche 50-528,83/05/11.830&010289

- 8304010341 Rev I to final Deficiency Rept DER 81-29 re failure of ASTN A490 bolts Initially reported on B10521 Detective bolts replaced Insp program implemented to verify bolt tension Also reportable per Part 21 VAN BRUNTLE E Arisona Public Service Co 83/05/11 STERNBERG, D M Region 5, Office of Director App. 18481:289 24X Fiche: 50-529, 83/05/11.8304010341
- 8304010074 Interim Deficiency Rept DER 83-10 re main steam relief valve tests exceeding 5% blowdown limit Initially reported on 830228 Submittal of final rept extended to 830630 VAN BRUNT, E E Arizona Public Service Co 83/05/16 STERNBERG, D M Region 5, Office of Director 2pp 18674 096 24% Fiche 50-528,83/05/16,8306010074
- 8304010119 Interim deficiency rept re underground cables to startup transformers unable to carry full-load current at max sits soil temp Initially reported on 82:124 Final rept submittal extended to 830729 due to extensive investigation VAN BRUNT, E E Arisona Public Service Co 83/05/14 STERNBERO, D M Regian 5, Office of Director 2pp 18473 360, 24% Fiche 50-528,83/05/16.8306010119.
- 8306010272 Rev 2 to Final Deficiency Rept DER 82-78 re improperly crimped termination lugs in control panels for water chillers supplied by Carrier revising panel numbers Initially reported on 821217 Also reportable under Part 21 VAN BRUNT.E E Arizona Public Service Co 83/05/16. STERNUERO, D M Region 5, OPfice of Director 3pp 18672-246 24X Fiche: \$0-528,83/05/16.8306/010272
- 8306010072 Rev 1 to Interim Deficiency Rept DER 82-41 re patential for reactor coolant pump diffusor ring cap screws to fast & damage pump Initially reported on 821021. C-E reviewed potential failure mechanisms Final rept by 830725
 VAN BRUNTIE.E. Arizona Public Service Co. 83/05/18 STERNBERO, D M Region 5. Office of Director 4pp. 18673 274 24X
 Ficha 50-528,83/05/18,8306010072
- --8306010087 App 2 to, "Metallurgical Exam of Diffuser/Reactor Coolant Pump Casing Bolts Returned From AZ Unit 2 (791350) " DOLLANSKY, K W Combustion Engineering. Inc TR-V-MCM-003 83/01/25 14pp 18673 316 24X Fiche 50-528,83/05/18.8306010072
- 8306070225 Final Deficiency Rept DER 83-23 re failure of MSIV bypass valves to close in required time. Initially reported on 830419 Solenoid valve replaced Problem investigation request issued by Bechtel Also reported per Part 21 VAN BRUNTLE E Arizona Public Service Co. 83/05/19 STERNBERO, D M Region 5, Office of Director Spp 18744, 217 24X Fiche: 50-528, 83/05/19, 8306070225
- 8306100203 Part 21 rept re deficiency in bix emergency standby diesel generator sets mfg by Cooper Energy Byca Jacket water heater & lube oil heater will be replaced w/40 kM & 19 kM versions, respectively, to maintain 120 F standby temp STOLBA-F B Cooper Industries, Inc 83/05/20 Director's Office, Office of Inspection and Enforcement 2pp 18806 007. 24X Ficher 50-828,83/05/20,8306100203
- 830607007B Interim Deficiency Rept DER 82-63 re design calculation error in refueling water tank seismic response. Initially reported on B21026 Time extension requested until B30624 to submit final rept
 VAN SRUNT, E E Arizona Public Service Co 83/05/24 STERNBERG, D. M Region 5. Office of Director 2pp. 18737-272 24X Fiche 30-528,83/05/24,8306070078.
- 830A070104 Interim Deficiency Rept DER 83-15 re ASTM A354 anchor bolt supplied by Marethon Steel breaking under installation torque after test acceptance Initially reported on 830318 Alternate column base anchoring detail usil be installed. VAN BRUNTLE E Arizona Public Service Co 83/05/24 STERNBERG.D'M Region 5. Office of Director. Spp 18739.172 24X Fiche. 80-529, 83/05/24, 8306070104.
- --B306070107 "Failure Analysis of 48TM A-354 Bolt for Palo Verde Nucleor Generating Station "BINOHAM W.O. GONZALES, J. C., SCHMIDT, C. R. Bechtel Corp. 0383-03 FA 83/02/01 5000 1177. 24X Ficher 50-529, B3/05/24,
 - t DER 93-25 re lack of instrumentation uirements. Initially reported pt will be submitted by
 - Service Co. 83/05/26 STERNBERG, D M. 5pp. 18883, 258. 24%

- 8306170341 Interim Deficiency Rept DER 83-30 re broken anchor bolt A354 on feedwater pump during torquing Initially reported on 830505 Test program developed & conducted to assess torque values Final rept expected by 830817

 VAN BRUNT. E E Arizona Public Service Co 83/06/06 STERNBERD, D H Region 5, Office of Director 3pp 18880 286 24X

 Fiche 50-529,83/06/06,8306170341
- 9306170366 Interim Deficiency Rept DER 83-31 re temp rise in diete)
 generator control cabinet potentially exceeding design
 requirements Initially reported on 830505 Bechtel & Cooper
 Energy Svcs evaluating condition Final rept by 830906
 VAN BRUNT, E Arizona Public Service Co 83706/06 STERNBERG, D H
 Region 5, Office of Director 3pp 19880 319 24X
 Fiche 50-528,83706/06.8306170366
- B306130150 Part 21 rept re solenoid activated valves, Models /7C-001 k 77C-003 Defects include incorrect valve assembly, significant missing parts, limited switch valve position indication failures & failure of valve to open & close PUTTARINI, D M Target Rock Corp 83/06/07 DEYOUNG, R C Director's Office, Office of Inspection and Enforcement 7pp 18024 267 24X Fiche 50-528,83/06/07,8306130150
- 8306230318 Advises that final Deficiency Ropt DER 83-14 re Westinghouss diesel generator protective relay failures due to leaking capacitors will be submitted by 830831 Delay due to extensive investigation & evaluation VAN BRUNT.E E Arizona Public Service Co 83/06/08 STERNBERG.D M Region 5. Office of Director 2pp 18944 164 24X Fiche 50-528.83/06/08.8306230318
- 830.6230379 Rev I to Interim Deficiency Rept DER 82-73 re excessive gap between pipo & pipe clamp across ITT Grinnell pipe support clamps Initially reported on 821124 Clamps acceptable w/twn or four-area contact Final rept to be submitted by 830901 VAN BRUNT, E E Arizona Public Service Co 83/06/08 STERNBERG, D M Region 5, 0 Ffice of Director 3pp 10943 244 24X Fiche 50-529, 83/06/08,8306230379
- DOCKET STN-50-530 PALO VERDE NUCLEAR STATION, UNIT 3
- A Application/construction stage documents & correspondence
- 8304140225 Forwards Conference Notes CN-E-1255 from 830323 meeting w/util, counsel, Bechtel, NRC & C-E in Washington, DC repost-LOCA containment sump Wilson, W Bechtel Corp 03/04/14 VAN BRUNT, E E Arizona Publit Service Co 3pp 18844 322 24X Fiche 50-528, 83/04/14, 8306140225
- 8304080281 Partial response to FOIA request for documents re R Gunderson & Bechtel allegations concerning electrical problems at facilities App A Documents I & 2 available in FDR Documents 3.4 & 5 withheld (ref FDIA Exemption 5) FELTON, J M Division of Rules and Records 83/04/28 YOUNG, M C Government Accountability Project 3pp 18770 354 24X Fiche 50-528, 83/04/28, 8306080281
- B306020627 Notification of B30622-23 & 24 meetings w/util in Markcops & Phoenix.AZ, respectively, to assess current status of const LIGITRA.E A Licensing Branch 3 83/05/24 KNIGHTON.G W Licensing Branch 3 6pp 18716 339 24% Fiche 50-526.83/05/24, B306020627
- 8304070091 Advises that schedule for responding to five confirmatory items & completion of qualification program for safety-related pumps & volves will be submitted by 830630 VAN BRUNTLE E. Arizona Public Service Co 83/05/31 KNIGHION.Q W Licensing Branch 3 to 18739 141, 24% Ficha 50-528,83/05/31,8306070091
- 8306080097 Bummary of 830517 meeting w/util, C-E & Bechtel in Dethesda. MD ro NRC 830314 requested info on environ qualifications Environ qualification audit scheduled during wk of 830627 LICITRA,E A Licensing Branch 3 83/06/01 Licensing Branch 3 4pp. 18787 327 24X Fiche 50-528,83/06/01,8306080097
- 8306200051 Notification of 830608 meeting w/util in Bethosda, MD to discuss control room design review LICITRA, E A Licensing Brench 3 83/06/03 KNIGHTON, 8 W Licensing Brench 3 3pp 18908 286 24X Fiche 50-528, 83/06/03, 8306200051
- 8304200053 Notification of 830428-30 & 0701 meetings w/util, Bechtel. C-E & EG&O in Phoenix & Maricopa County, AZ to conduct audit of equipment environ qualification documentation LICITRA, E A Licensing Branch 3 83/04/03 KNIQHION, 9 W Licensing Branch 3 3pp 18708-287 24X Fiche 50-528,83/04/03, 830420053

- 8306170265 Forwards marked-up Amend 12 to FSAR Section 17 1 re QA program for engineering, design procurement & const of facility, per 16CFR50 55(f)

 VAN BRUNT, E E Ariona Public Service Co 83/06/10 STERNBERG, D M Region 5, Dffice of Director 82pp 18877 274 24X
 Fiche 50-528, 83/06/10, 8306170265
- 830.170302 Forwards App J to. "Evaluation of Pressuilled Thermal Shock Effects Due to Small Break LDCAs MYLoss of Feedwater for Palo Verde 1 & 2.7 & 3 Reactol Vessels " Rept applies to only Uhit 1
 VAN BRUNT.E E Arizona Public Service Co 83/06/14 KNIGHTDN.6
 Licensing Branch 3 3pp 18878 197 24X Fiche 50-528.83/06/14.
 8306/70302
- 8306170351 Forwards response to 830503 request for info supplementing 830322 info on FSAR Table 3 2-1 re quality classification of structures, sys & components WAN ERUNT, E E Arizona Public Service Co 83/06/14 KNIGHTON, O Licensing Branch 3 14pp 18881 005 24X Fiche 50-528,83/06/14,8306170351
- B30624045B Summary of B3060B meeting w/util in Bethesda,MD re detailed control room design review CICITRA, b. A. Licensing Branch 3 83/06/14 Licensing Branch 3 4pp 1897B 001 24X Ficho 50-52B, 83/06/14, B30624045B
- request & NUREG-OSBB requirements
 VAN BRUNTLE E Arizona Public Service Co 83/06/24 KNIGHTDN, Q
 Litensing Branch 3 228pp 19016-297 24% Fiche 50-528, 83/06/24,
 8306280436 6306280436 Forwards Amend 1 to environ qualification reptiper 830314
- E NRC Safety Evaluation Report (SER), supple & correspondence
- 8306130432 Responds to 830328 request for add1 info re adequacy of electric distribution sys voltages per SER (NUREG-0857)
 Response re adequacy of util info requested within 2 wks
 VAN BRUNT, E E Arizona Public Service Co 83/06/07 KNIGHTON, G
 Licensing Branch 3 bpp 18821 195 24X Fiche 50-528,83/06/07.
 83061300432
- e306160900 Advises that procedures indicating shutdown cooling relief valves armed by menually opening shutdown cooling system isolation valves will be utilized until operable low temp overpressure alarm available, per NUHEG-0857. Suppl 1 VAN BRUNT, E. E. Arizona Public Service Co. 83/05/13 KNICHTON, G. Licensing Branch 3 lp. 18864-156 24% Ficha 50-528-83/06/13. 8306160500
- 8306170326 Forwards proposed amend to FSAR re CESSAR indine removal sys & responses to NRC 830422 ltr Proposed FSAR amend combined w/responses closes out sump ph issue in SER Sections 6.4 & 15.4 B & TMI Item III D 3.4

 VAN BRUNTLE F Arizona Public Service Co. 83/06/13 KNIGHTON, 0 Licensing Branch 3. Bpp. 18879 040 24X Fiche 50-528, 83/06/13. B306170326
- 8306270368 Forwards responses to SER, Suppl 4, Sections 13 3 2 2 & 13 3 2 3 (NUREO-0857), re courses of action necessary in unlikely event of emergency at facilities Info will be included in Rev 3 to unerpancy plan
 VAN BRUNT, E. E. Arizona Public Service Co. 83/06/15 KNIGHTON, & Licensting Branch 3 26pp 18773 214 24X Fiche 50-528, 83/06/15, 8306270368
- B306210287 Forwards program plan issues & areas for outstanding items rs NUREQ-0737. Item I D i re detailed control room design raview per NUREQ-0700 requirements & SFR, NUREQ-0857 Generic Ltr 82-33 issues addressed VAN BRUNT, E E Arizona Public Service Co 83/06/17 KNIGHTON, O Licensing Branch 3 36pp 18914 038 24X Fiche, 50-528, 83/06/17, 8306210287
- 8306280317 Submits required data to demonstrate that line voltage regulators perform as acceptable isolation device by limiting primary current under short circuit conditions to full-load primary current.per SER (NURE-0057)
 VAN BRUNTLE E Arizona Public Service Co 83/06/23 KNIGHTON.O Licensing Branch 3 ip 19001 262 24X Fichs 50-528.83/06/23.83/06/23.83/06/23.
- F Security, medical, emergency & fire protection plans
- 8306170356 Forwards description & list of objectives for 830511 emergency preparedness exercise Scenario will be provided within 30 days Comments requested within 15 days of ltr date.
 ANDOGNINI: G C Arizona Public Service Co. 83/03/02 GRIMEB. B. K
 Division of Emergency Preparedness (Pre 830103) 17pp 18880; 33:
 24X Fichs: 50-528, 83/03/02, 8306170356

- --8306170360 Forwards description & list of objectives for 830511 emergency preparedness exercise Scenario will be provided within 30 days Comments requested within 15 days of 1tr date ANDORNINI.G C Arizona Public Service Co 83/03/02 Region 5. Office of Director 10pp 18880 352, 24X Fiche 50-528,83/03/02,8306170356
- 8304020054 Responds to 830414 ltr re Generic Ltr 82-33 requirements concerning Suppl I to NUREQ-0757 Portion of response addressing detailed control room design review does not provide all info requested Response requested by 830531 KHIGHTON G W Licensing Branch 3 83705710 VAN BRUNT, E. E. Artzona Public Service Ca 6pp 18701 349 24X Ficha 50-528,83705710,8304020055
- B3D6030357 Advises that add1 info re detailed control room design review per Generic Ltr B2-33 re emergency response capabilities will be submitted by B3D647 VAN BRUNT.E E Arizona Public Service Co B3/06/01 KNIGHTON.O Licensing Branch 3 ip 18705.214 24X Fiche 50-528, B3/06/01, B30603057
- 8306090273 Releases public version of revised emergency plan implementing procedures FELTON, J M Division of Rules and Records 83/06/03 Docum Management Branch 1p 18810 067 24% Fiche: 50-528, 83/06/03, names represented to the state of the FELTON, J M Divis Management Branch 8306090273
- --8306090875 Forwards public version of revised emergency plan implementing procedures including Procedures EPIP-01 regenergy organization. EPIP-02 regenergency classification & EPIP-04 regalert implementing actions
 VAN BRUNT, E.E. Arizona Public Service Co. 83/05/23 KNIGHTON, Q. Licensing Branch 3. 3pp. 18810-068 24X Fiche: 50-528, 83/06/03, 8306090273
- --8306090276 Public version of revised emergency plan implementing procedures, including Procedures EPIP-01 re emergency organization, EPIP-02 re emergency classification & EPIP-04 re alert implementing actions LUCIA.8 Arizona Public Service Co 83/03/30 708pp 18910.071 24X Fiche \$0-528.83/06/03,8306090273
- 830620037) Forwards responses to open items from NRC 830201-03 fire VAN BRUNT, E E Arizona Public Service Co B3/04/15, KNIGHTON, O Licensing Branch 3 Sipp 18899 034 24X Fiche 50-528, B3/04/15, 8304200371
- 8306270368 Forwards responses to BER. suppl 4. Bections 13 3 2.2 & 13 3 2 3 (NURE9-0857), re courses of action necessary in unlikely event of emergency at facilities info will be included in Rev 3 to smergency plan
 VAN BRUNT, E E Arizona Public Bervica Co 83/04/15 KNIGHTON, 0 Licensing Branch 3 26pp 18793-214 24X Fiche 50-528,83/04/15,8306270368
- 8306270447 Responds to Generic Ltr 82-33 re Suppl 1 to NUREG-0737 406270447 Responds to deneric Ltr B2-3 re supplies marke-0/3/ concerning requirements for emergency operations facility Unit i selected as backup emergency operations facility Exemptions from 10-mile criteria requested VAN BRUNT.E E Arizona Public Bervice Co 83/06/16 KNIOHTON.C Licensing Dranch 3 3pp 18792 095. 24X Fiche 50-528,83/06/16. 8306270447
- 8306210287 Forwards program plan issues & areas for outstanding items re NUREO-0737, item I.D i re detailed control room design review per NUREO-0700 requirements & SFR, NUREO-0857 Generic Ltr 82-33 issues addressed VAN BRUNT, E E Arizona Public Service Co 83/06/17 KNIGHTON, C. Cicensing Branch 3 36pp. 18914-038. 24X Fiche. 50-528, 83/06/17, 8306210287.

G Adjudicatory correspondence

- B304030333 Response to second set of interrogatories Certificate of BERLIN, K BERLIN,K Hest Velley Agricultural Protection Council, Inc 83/06/01 Office of the Executive Legal Director, 10pp 18707 018, 24X Fiche 50-529,83/06/01,8306030333
- --8306030334 Request for production of documents identified in response to first & second set of interrogatories & documents requested in interrogatories, Certificate of Bvc encl.
 BERINK Hest Valley Agricultural Protection Council Inc.
 83/06/01 Arizona Public Service Co 6pp 18709:028 P4X Fiche 50-529,83/06/01,8306030333

- --8306030335 Response to second set of interrogatories Certificate of 8vc encl BERLIN.K West Valley Agricultural Protection Council. Inc 83/06/01 Arizona Public Service Co 42pp 18709 034 P4X Fiche 50-529, 83/06/01, 8306030333
- 8306150398 Stipulation agreeing that motions to compel interrogatory answers due 830715 & supplemental info responding to interrogatories due 830701 Proposed order & Cartificate of Svc encl
 EMEYS. S. Hearing Branch 3. BERLIN.K. West Valley Agricultural Protection Council. Inc. PLATT.W. Joint Applicants-Palo Vorde 83706701 Spp. 18847 140. PAX Ficher 50-529.83706701.8306150398
- 8306090311 Withdrawel of 830526 request to extend time to respond to revised discovery schedule. No addl time needed to revised schedule Schedule acceptable Certificate of Svc encl. DEWEY, L. S. Hearing Branch 3 83/06/08 Atomic Safety and Licensing Board Fanel. 3pp 18795-196 24X Fiche 50-529.83/06/08.
- 8306100075 Forwards West Valley Agricultural Protection Council, Inc & Joint Applicants stipulation re discovery schedule mod END, M B West Valley Agricultural Protection Council, Inc 83706/09. LAZO,R M Atomic Safety and Licensing Board Panel Ip 18803 164. 24X Fiche 50-529.83706/09.8306100075
- --8306100078 Stipulation agreeing to comply w/provisions of proposed order, unless & until further mod requested by parties ASLB should enter encl order re discovery schedule mod BERLINK Wost Valley Agricultural Protection Council, Inc PLATT, W E Joint Applicants-Palo Verde PLATT, W E. Snell & Wilmer 83/06/09 App 18803 165 24X Fiche; 50-529, 83/06/09, 8306100075
- 8306140429 Requests info needed to complete review of util proposed salt deposition & impact monitoring plan
 DEWEY, L B Hearing Branch 3 83/06/10 PLATT, W. E Snell & Wilmer PLATT, W. E. Arizona Public Service Co Rpp 18638 045 24X
 Fiche 50-528,83/06/10,8306140429
- B306150304 Request for production of documents. Certificate of Byr encl. GRAWFORD, V A Joint Applicants-Palo Verde CRAWFORD, V.A Bnell & Wilmer, B3/06/f0. West Valley Agricultural Protection Council, Inc. 10pp 18847 152 24X Fiche 50-529, 83/06/f0.8306150304
- 8306160622 Order directing motions to compel re interrogatory answers be filed by 830715 Supplemental responses to interrogatories to be filed by 830701
 - LAZO,R.M. Atomic Safety and Licensing Board Panel 83/06/14 lp 18865 073. 24% Fiche 50-529,83/06/14,8306160622
- 8304i40629 Order delineating schedules for depositions, discovery on crop study & pretrial preparation.
 LAZO.R M Atomic Safety and Licensing Board Panel 83/06/14 App 18866, 122 24X Fiche 50-529, 83/06/14,8306140629
- B306210264 Request for production of documents. Certificate of Suc encl DEMEY.L.S. Hearing Branch 3 83/06/17 West Valley Agricultural Protection Council Inc. 4pp, 18915-027, 24X Fiche: 30-529, 83/06/17, 8306210264.
- 8306210268 Request for production of documents Certificate of Svc encl DEWEY,L B Hearing Brench 3 83/06/17 Arizona Public Service Co. 4pp. 18914-005. 24X Fiche 50-529,83/06/17,8306210268.
- 8306240284 Forwards util 830426 application for SNM license, DEMEY, L 8 Hearing Branch 3 83/06/21 LAZD,R M, CALLIHAN,D., COLE.R.F. Atomic 88fety and Licensing Board Panel 149pp 18779,291, 24X Fichs: 50-529,83/06/21,8306240284
- G Inspection reports, IE Bulletins & correspondence
 - VOP Add1 response to FDIA request for documents dtd 820101 or ve BALP Forwards App A documents Documents also in PDR. Division of Rules and Records. 83/04/11. CLARK.R S v=miner. 3pp. 18815:252. 24X Fichs.50-000.83/04/11.
 - or Region V SALP Board meetings for
 - fice of Director, 82/03/19
 sar Reactor Regulation, Director 1p.
 0.83/04/11.8306100009

- 8304070252 Forwards IE Insp Repts 50-528/83-18,50-529/83-10 & 50-530/83-08 on 830301-0430 & notice of violation STERNBERG, D M Region 5. Office of Director 83/05/25 VAN BRUNT,E E Arizona Public Service Co 2pp 18740 340 24X Fiche 50-528.83/05/25.8304070:52
- --8306070286 IE Insp Repts 50-528/83-18.50-529/83-10 & 50-530/83-08 on 830301-0430 Noncompliance nuted power cables for containment spray pump drive motors w/unsupported lengths longer than 24 inches & cables trays not grounded at both ends vORDERGRUEGOEN, VOUNS, T Region 5, Office of Director 83/05/24 6pp 18740 344 24% Fiche 50-528,83/05/25.8306070252
- 9305110458 IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in Well Logging Device" Svc list encl
 TAYLOR, J M Division of Safeguards & Inspection Programs (Post B30103) 83/05/26 Consolidated Edison Co of New York, Inc
 125pp. 1883) 043 24X Fiche 50-000, 83/05/26, 8305110458
- 8305110460 IE Info Notice 83-34, "Event Notification Info Worksheet "
 5vc list encl
 JORDAN-C I Division of Emergency Preparodness & Engineering
 Response (Post 830103) 83/05/26 Consolidated Edison Co of New
 York, Inc. 115pp 18732 085 24X Fiche 50-000.83/05/26.0305110460
- 8305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods Withdrawn at BWRs" Eve list encl JORPAN.C L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/31 Consolidated Edison Co of New York. Inc 116pp 18732 208 24X Fiche 50-000.83/05/31.8305110461
- 8305110464 IE Info Notice 83-36, "Impact of Security Practices on Bafe Operations " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/09 Consolidated Edison Co of New York, Inc 119pp 18830 280 24X Fiche 50-000,83/06/09,0305110464
- 8305110470 IE Info Notice 83-38. "Defective Heat Sink Adhesive & Seismically Induced Chatter in Relays Within Printed Circuit Cards " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co of New York, Inc 118pp 18920 225, 24X Fiche 50-000,83/06/13,0305110470
- 8304090010 IE info Notice 83-37. "Transformer Failure Resulting From Degraded Internal Connection Cables" Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co of New York. Inc 243pp 18921 001 24X Fiche 50-000,83/06/13.8306090010
- 8305110475 IC Info Notice 83-40, "Mend to Environmentally Qualify
 Epoxy Grouts & Sealers." Evc list enc1
 JORDAN, E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/06/22 Consolidated Edison Co of New
 York, Inc 115pp 19021 179 24X Fiche 50-000,83/06/22,830510475
- 8305110477 IE Info Notice 83-41, "Actuation of Fire Suppression Bys Causing Inoperability of Safety-Related Equipment "Syx list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/22 Consolidated Edison Co. of New York, Inc. 120pp 18997 007 24X Fiche 50-000,83/06/22,8305110477
- 8305110479 IE Info Notice 83-42, "Reactor Mode Switch Malfunctions a Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/23 Consolidated Edison Co of New York, Inc 114pp 18996 242 24X Fiche 50-000,83/06/23,8305110479
- 8305[1048] IE Info Notice 83-43. "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints " Svc list enc] JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/24 Consolidated Edison Co of New York, Inc 116pp 19046:297 24X Fiche 50-000.83/06/24.8305[1048]
- S Reportable occurrences, LERs & related correspondence
- 8304010289 Interim Deficiency Rept DER 83-22 re failure of ITE Boold circuit breaker for hydrogen recombiner to function properly Initially reported on 830413, Bechtel & Rockwell Intl working on circuit breaker Next rept by 831108 VAN BRUNT, E. E. Arizona Public Bervice Co. 83/05/11, STERNBERG, D. N. Region 5, Office of Director 3pp. 18472 195 24X Fichs. 50-528, 83/05/11, 8304010209.
- 8304010341 Rev 1 to final Deficiency Rept DER 81-29 re failure of ASTM A490 bolts Initially reported on 810521 Detective bolts replaced. Insp program implemented to verify bolt tension Also reportable per Part 21 VAN BRUNTLE E Arisona Public Service Co 83/05/11 STERNBERG. D H Region 5. Defice of Director. App. 18681 289 24X Fiche 50-529,83/05/11,8306010341

- 8304010076 Interim Deficiency Rept DER 80-10 re main steam relief valve tests exceeding 5% blowdown limit Initially reported on 830228 Submittal of final rept extended to 830630 VAN BRUNT, E E Arizona Public Service Co 83/05/16 STERNBERG, I) M Region 5. Defice of Director 2pp 18674 076 24X Fiche 30-528, 83/05/16, 8306010076
- 830&010119 Interim deficiency rept re underground cables to startup transformers unable to carry full-load current at max site soil temp initially reported on 821126 Final rept submittal extended to 830729 due to extensive investigation WAN BRUNTLE E Arizona Public Service Co 83/05/16 STERNBERO, D M Region 5. Office of Director 2pp 18673 340 24% Fiche 50-528.83/05/16.830&010119
- 8306010272 Rev 2 to Final Deficiency Rept DFR 82-78 re improperly crimped termination lugs in control panels for water chillers supplied by Carrier, revising panel numbers initially reported on 821217 Also reportable under Part 21 YAN BRUNT.E E Arizona Public Service Ca 83/05/16 STERNUERG, D N Region 5. Office of Director 3pp 10672 246 24X Fiche 50-528.83/05/16.8306010272
- 930&010072 Rev 1 to Interim Deficiency Rept DER 82-61 re potential for reactor coolant pump diffusor ring cap screws to fail & damage pump Initially reported on 821021 C-E reviewed potential failure mechanisms Final rept by 930725

 VAN BRUNT, E E Arizona Public Service Co 83/05/10 STERNDERG, D M Region 5, Office of Director 4pp 18673 274 24X

 Fiche 50-528.83/05/18.8306010072
- 8306070225 Final Deficiency Rept DER B3-23 re failure of MSIV bypass valves to close in required time Initially reported on 830419 Solenoid valve replaced Problem investigation request issued by Bechtel Also reported per Part 21 VAN BRUNT, E E Arizona Public Service Co 83/05/19 STERNBERG, D PRegion 5, Office of Director Spp 10744 217 P4X Fiche 50-528,83/05/19.8306070PP5
- 8306100203 Part 21 rept re deficiency in six emergency standby diesel generator sets mfq by Cooper Energy Svcs Jacket water heater & lube oil heater will be replaced w/40 kW & 19 kW versions respectively to maintain 120 F standby temp STOLBA.F B Cooper Industries, Inc 83/05/20 Director's Office. Office of Inspection and Enforcement 2pp 18804 007 24X Fiche 50-528.83/05/20.8306100203
- 8304070078 Interim Deficiency Rept DER 82-63 re dasign calculation error in refueling water tank seismic response Initially reported on 821026 Time extension requested until 830624 to submit final rept
 VAN BRUNT.E E Ariona Public Service Co 83/05/24 STERNBERO.D M Region 5. Office of Director 2pp 18739 272 24X Fiche 50-528.83/05/24.8306070078
- 8306170180 Interim Deficiency Rept DER 83-25 re lack of instrumentation tubing boundary class break requirements Initially reported on 830421 Evaluation & final rept will be submitted by 830630 VAN BRUNT, E. E. Apizona Public Service Co. 83/05/26 STERNDERO, D. M. Region 5, Office of Director Spp. 16883 258 24X Fiche 50-528, 83/05/26, 8306170180
- 8396170366 Interim Deficiency Rept DER 83-31 re temp rise in diesel generator control cabinet potentially exceeding design requirements Initially reported on 830505 Bechtel & Cooper Emergy Sycs evaluating condition Final rept by 830906 VAN BRUNT, E E Arizona Public Bervice Co E3/06/06 STERNBERG, D M Region 5, Office of Director 3pp 10880 319 24% Fiche 50-528,83/06/06,8306170366
- 8304130150 Part 21 rept re solenoid activated valves, Models 77C-001 k 77C-003 Defects include incorrect valve assembly, significant missing parts, limited switch valve position indication failures & failure of valve to neem & close PUTTARINI, D. M. Target Rock Corp. 83/06/07 DEYOUNG, R C Director's Defice, Office of Inspection and Enforcement 9pp 18824 247 24X Fiche 50-528, 83/06/07, 8306130150
- DOCKET 50-507 CLINCH RIVER BREEDER REACTOR
- A Application/construction stage documents & correspondence
- 0305050203 Submits agreements reached at 030524 meeting w/CRBR project re PRA Description of additasks needed to integrate Plan I & II efforts encl.
 LONGENECKER, J Energy, Dept of 83/05/27 GRACE, J N Clinch River Breeder Reactor Program Office 11pp 18727, 328, 24X
 Fiche 50-537, 83/05/27, 8306060203

- 8304070436 Notification of 830406 meeting w/DDE, Project Mgt Corp & TVA in Bethesda, MD to discuss schedule for completion of confirmatory items
 STARK, R M Clinch River Breeder Reactor Program Office 83/05/27.
 ORACE, J N Clinch River Breeder Reactor Program Office 3pp. 1876-354 24% Fiche SO-537,83/05/27.8306070436
- 8306130403 Forwards "CRBR Erosion & Sediment Control Plan Rept," providing implementation status of control plan measures currently utilized GROSSP J Energy, Dept of 83/05/27 JOHNSTON.W Assistant Director for Matls. Chem & Environ Technology (Post 830201). MCKINNEY.A D Tennesses: State of TRAINA.P J Environmental Protection Agency 2sp 18823 047 24X Fiche 50-537,83/05/27,830430403
- --8306130407 "CRBR Erosion & Sediment Control Plan Rept "
 * Energy, Dept of. 83/05/27 15pp 18823 049. 24X
 Fiche 50-537,83/05/27,8306130403
- B306070462 Notification of B30610 meeting w/DGE & Project Mgt Corp in Bethesde,MD to discuss CRBR programmatic objectives. STARK,R M Clinck River Breeder Reactor Program Office G3/06/01 ORACE,J N Clinck River Breeder Reactor Program Office Spp. 18780 315 P4X Fiche S0-537,83/06/01,B306070462
- 830622004B Informs of planned optional use of mechanical couplers for reinforcing bar splice sys in nuclear island mat QA program will be astablished. Exception to ARME Code: Bection III & Reg Ouide i 136 requirements encl
 LCMCENECKER. J. Energy. Dept. of 83/06/20 GRACE. J. N. Clinch River Breeder Reactor Program Office Opp. 18930,020 24X
 Fiche 50-537.83/06/20.830622004B
- B306290570 Notification of B30628 meeting w/DDE, Project Mgt Corp & util in Bethesda, MD to discuss applicant radiological calculations
 STARK.R M Clinch River Breeder Reactor Program Office B3/06/21.
 GRACE.J N Clinch River Breeder Reactor Program Office, 3pp 17047 170 24X Fiche 30-537, 03/06/21, 0306290570
- 8306240233 Summarizes 830606 meeting w/CRUR project personnel reschedule for resolution of confirmatory items All identified items & preliminary schedule info discussed List of attendees encl LONGENECKER, J. Energy. Dept. of, Clinch River Breeder Reactor Plant 83/06/23 QRACE, J. N. Clinch River Breeder Reactor Program Office. 2pp 18980 185 24X Fiche 50-537.83/06/23,8306240233
- E NRC Safety Evaluation Report (SER), supple & correspondence
- B306150616 SAFETY EVALUATION REPORT RELATED TO THE CONSTRUCTION OF THE CLINCH RIVER BREEDER REACTOR PLANT Docket No. 50-537.
 (U.S. Department of Energy, Tennessee Valley Authority And Project Hanagement Corporation)

 ** Clinch River Breeder Reactor Program Office NUREO-0968 802
 83/05/31 199p Available at NRC. \$3.00 18854,231 24X
 Fiche 50-537,83/05/31,8306150616
- 8306170452 Forwards Buppl 2 to GFR (NUREC-0768) re const of facility.
 Suppl provides evaluation of add1 info received on
 previously identified outstanding review items M/o encl
 gRACE.J N Clinch River Breeder Reactor Program Office G3/06/13
 LONGENECKER.J Energy, Dept. of, Clinch River Breeder Reactor Plant.
 2pp. 18894 303 24X Fiche 50-537.83/06/13.8306170452
- 8306200325 Summarizes programmatic objectives B30610 meeting refallbacks identified in Chapter 4 of SER & Impact on CRBR project Vieugraphs & supporting documentation and L. LONGENECKER, J. Energy, Dapt of B3/06/17 GRACE, J. N. Clinch River Breeder Reactor Program Office 17pp 18901:001 24X Fiche 50-537,83/06/17,83062003P5
- Q Adjudicatory correspondence
- B306070037 Forwards util analysis re seismic qualification of small diameter piping.in response to ABLB B30513 inquiry.NRC analysis forthcoming.

 TURK.BE Hearing Branch 1. B3706/03. MILLER,M., LINENBERGER, 0., HAND.C.H. Atomic Bafety and Licensing Board Panel ip. 18739:334. 24X Fichs 30-537.83706/03,8306070037
- 8306100043 Answer supporting util 830517 motion for summary disposition of intervenor Contention 9(g). Contention 9(g) fails to raise litigable issue of fact that will not be litigated under other subparts of Contention 9 Certificate of Syz encl.

 TURK.8 E Hearing Branch | 83/06/08, Atomic Bafety and Licensing Board Panel 4pp | 18802 111, 24X Fiche: 50-537.83/06/08, 8306100043

- 8306150311 Confirms understanding re NRC production of documents identified in NRC 830520 response to CP interrogatories (third set) Documents will be available in Dethesda, MD on 830616
 TURK, 8 E Hearing Branch | 83/06/10 FINAMORE, 8 A Natural Resources Defense Council ip 18849-128 24X
 Ficher 50-837, 83/06/10, 8306150311
- 8306150917 Confirms 830610 telcon rs NRC deposition of T Cochran Deposition continued on 830512 NRC will adjourn deposition, subj to listed conditions TURK,8 E Hearing Branch 1 83/06/10 FINAMORE,B A Natural Resources Defense Council 2pp 18849 088 24X Fichs 30-837.83/06/10.8306150317
- 8306150315 Answer supporting util 830523 motion for partial summary disposition of intervenor Contentions 9(c) & 9(f) Intervenor fails to provide any factual basis that 10-mile emergency planning tone inappropriate Certificate of 8vc encl TURK,8 E Hearing Branch 1 B3/06/13 Atomic Safety and Licensing Board Panel 9pp 18849 090 24X Fiche 50-337,83/06/13,8306150315
- B306200302 Advises that DOE addressess include TJ Garrish.1 Silverstrom & WD Luck RT Johnson & WE Bergholz should be deleted from syc list Cartificate of Syc encl
 LUCK.W B Energy, Dept of 83/06/16 MILLER.M E. MAND.C H.
 LINENDERGER.G Atomic Safety and Licensing Board Panel 4pp
 18700 172 24X Fiche 50~537,83/06/16,8306200302
- 8306220146 Motion to withdraw Contentions 1.3.9(c),9(g) From consideration at Jul 1983 CP hearings & request for leave to submit written statement on issues raised Limited resources prohibit continued full participation FINAMORE,8 A. MEJ88.E R. OREENDERG.E V Natural Resources Defense Council. 83/06/21 Atomic Safety and Licensing Board Panel Spp. 18926 181 24% Fiche 50-53/.83/06/21.8306220146
- --8305220153 Response apposing applicant 830519 & 23 motions for summary disposition of Contentions 9(g),9(c) & 9(f) Motions mont since intervenors moved to withdraw contentions from consideration
 FINAMORE, B A. WEISS, E R. Natural Resources Defense Council
 WEISS, E Bierra Club 83/06/21 Atomic Safety and Licensing
 Board Panel 2pp. 18726 184 24X Fishe 50-537.83/06/21, 8304220144
- --8306220157 Lists typographical & transcription errors in 830512 deposition Certificate of Svc encl COCHRAN.T B Natural Resources Defense Council 83/06/21 TURN.B E Hearing Branch 1 4pp 18926 186 24X Fiche 50-537.83/06/21,8306220146
- 8306270317 Response to intervenur B30621 motion to withdraw Cantentians 1.3,9(c),9(f) & 9(g) from consideration at Jul 1983 CP hearings Intervenors should be dismissed as parties Certificate of Svc encil EDOAR.O.t. Project Management Corp LUCK.W D Energy. Dept of 83/06/22. Atomic Safety and Licensing Board Panel 9pp 18994.030 24X Fishe 50-537,83/06/22.8306270317
- @ Inspection reports: IE Bulletins & correspondence
- 8305110458 IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in Wall Logging Device" See list encl IAYLOR, J. M. Division of Safeguards & Inspection Programs (Post 830103). 83/05/25 Consolidated Edison Co. of New York, Inc 125pp 18831:043 24X Fiche. 50-000, 83/05/26, 8305110458
- 8305110460 IE Info Notice 83-34, "Event Notification Info Worksheet " Byo list encl.
 JORDAN, E. L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/05/26 Consolidated Edison Co. of New
 York, Inc. 115pp 18732 085 24X Fishe 50-000,83/05/26,8305110460
- 8305110461 IE Info Notice 83-36, "Fuel Movement W/Control Rods Withdrawn at BWRs " Evc list entl JORDAN,E.L Division of Emergency Preparedness & Engineering Response (Post 830103) B3/05/31 Consolidated Edison Co York, Inc 116pp 18732-208 24X Fiche 50-000,83/05/31,8305 116pp 18732-208 24X Fiche 50-000.83/05/31.8305110461
 - =" \$37/83-06 on 830502-05 No esident Programs 83/06/07 harity 2pp 19054 123 24 X
 - n 930502-05 No noncompliance t surveillance of
 - . Office of Director he 50-537,83/06/07,8306270227

- 8305110464 lE Info Notice 83 36, "Impact of Security Practices on Gafe Operations" Svc list encl JORDAN, L. Division of Lucisency Preparedness & Engineering Response (Post 830103) B3/06/07 Consolidated Edison to of New York, Inc. 119pp 16830 280 (4X Fiche 50-000,83/06/09,8305110464
- 8305110470 IE Info Notice 83 36, "Defective Heat Sink Adhesive & Seismically Induced Chatter in Relays Within Printed Circuit Caids " Svc list end JORDAN, EL Division of Lampency Proparedness & Engineering Response (Post 830103) 83/06/11 (onsalidated Edison Co. (03) | 83/06/13 | Consolidated Edison Co. of New 18920 | 225 | 24% Fiche 50-000 | 83/06/13 | 8305110470
- 8306090010 IE Info Notice 83-37, "Transformer Failure Resulting From Degraded Internat Connection Cables " Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83706/13 Convolidated Edison (p. of New York, Inc. 243pp. 18921-001 24X Fiche 50-000.83706/13,8306090010
- 8305110475 IE Info Notice 83-40. "Noed to Environmentally Gualify Epoly Grouts & Sealers " Svc list encl JORDAN, L. L. Division of Emergency Preparedness & Engineering Response (Post 830103) B3706/2P Consolidated Edison to of New York, Inc. 115pp 19021 177 24X Fishe 50-000.83706/22.8305110475
- 8305110477 IE Info Notice 83-41, "Actuation of Fire Suppression Sys Causing Imoperobility of Sofoty Related Equipment " Svc list and anci JARBAN, E.L. Division of Emergency Proparedness & Engineering Response (Post 830103) 83/06/22 Consolidated Edison Co. of New York, Inc. 120pp 18997-007 24x Fiche 50-000,83/06/22,8305f104/7
- 8305110479 IE Imfo Notice 83~42, "Reactor Mode Switch Malfunctions " Svc list enc]
 JORDAN, E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/06/23 Consolidated Edison Co. of New
 York, Inc. 114pp 18996 242 24X Ficho 50-000,83/06/23,8305110477
- 8305110483 IE Info Nutice 83-43, "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints" Svc list encl JORDAN, E. E. Division of Emergency Preparedness & Engineering Response (Fost 830103) 83/06/24 (cnsolidated Edison Co. of New York, Inc. 116pp 19046-29/ PAX Fiche 50-000,83/06/24,8305110403
- DOCKET STN-50-546 MARBLE HILL NUCLIAR STATION, UNIT 1
- A Application/construction stage documents & correspondence
- 8306060039 Forwards "Audit of Jul 198; Cost Estimate for Marble Hill Nuclear Project," in support of util potition to increase existing rates & changes for retail electric svc & for approval of new rate schedulos, rules & regulations SHIELDS, 8 W Public Service (o of Indiana, Inc 83/05/31 DENTON, HR Office of Nuclear Reactor Regulation, Director 2pp 18723 300 24% Fiche 50-546,63/05/31,8706060039
- --8306060043 "Audit of Jul 1982 Cost Estimate for Marble Hill Nuclear # U'Hrien-Kreitiberg & Associates, Inc. 83/05/20 1107pp 18723 302 24X Fiche 50-544,83/05/31,8306060039
- 8306140576 Forwards schedular commitments for submittal of environ Qualification program in response to Questions M270 2 & M270 3.por H30510 request for add1 info re environ qualification program in response to Questions M770 2 & M270 3.por H30510 request for add1 info re environ qualification of otectrical & mechanical equipment SHIELDS. S W Public Service (n of Indiana, Inc H3/06/09 DENTON. H R Office of Nucleor Reactor Regulation, Director IBBS3 138 24% Fiche 50-546 B3/06/09.8306140394
- 8306200019 Summary of 830331 meeting w/utils & Westinghouse in Bethesda: MD re Westinghouse analysis & evaluation of D4/D5/E steam generator mod HDPKINS: J D Licensing Branch 4 83/06/14 Licensing Branch 4 22pp 16908 327 24X Fishe 50 000.83/06/14.8306200019
- 8306200097 Informs that area proposed by util for const of transmission lines within range of state endangered bobcat, badger. Indianabat & within seasonal migration routs of bald eagle TURNER, D Indiana, State of 83/06/14 YOUNDBLOOD, B J Licensing Branch 1 1p 18903 339 224X Fiche 50-546,83/06/14,8306200097
- 830622010: Forwards notice of 0307!2 public meeting in Madison, IN to discuss recent application submitted by util & Wabash Valley Power Assoc.Inc for OLs to be published in local newspapers YOUNGELOOD, B J Licensing Branch 1 83/06/14 SHI Bervice Co of Indiana, Inc. 3pp 19977 343 24X Picke 50-546, 83/06/14: 8306220101 SHIELDS, S. W Public

- 8304210127 Informs that site or as occated transmission line impact on natl forest lands & program discribed in 830408 ltm will be forwarded to forest supervisor H Godlevske for response SHUTLEMORTH. M Agriculture, Dept of 83/05/15 YDUNGOLOUB, B J Licensing Branch 1 ip 18918 131 24X Fiche 50-546,83/06/15,8306210127
- 8306270219 Amend 26 to CP & UL applications, consisting of Byton Amend
 41 to FSAR, Suppl & to environ rept & rest to training &
 qualification plan sertion of safequards vol Revs withheld
 (ref 10CFR2 770) W/a encis
 SHIELDSS W Public Service (n of Indiana, Inc B3/06/24
 DENTON, H R Office of Nuclear Reactor Regulation, Director App
 18991 219 24X Fishe 50-548, 03/06/24, 8306270219
- C Utility Environmental Report (ER), amends & correspondence
- 8306270138 forwards Suppl 2 to environ tept UL stage SHELDS.S W Public Service (o of Indiana, Inc 83/06/24 DENTON IR Office of Nuclean Reactor Regulation, Director 6pp 18970 262 24X Fichs 50-546,83/06/24,8306/70138
- --8306270149 Suppl 2 to environ tept (A stage * Public Service Co of Indiana, Inc. 83/06/30 48pp 18990 PAB PAX Fiche 50 544.03/06/24,8306270138
- D MRC Draft/Final Environmental Statements, suppls & correspondence
- 9306170470 Requests info re environ impact of station operation to assist in EIS preparation Notification re participation in 030711-15 site virit due by 0.00630 YOUNGBLOOD, D. J. Licensing Branch J. 63706708 SMITH P.H. Advisory Council on Historic Preservation 9pp 18094-347 24X Fiche 50-546.03706708-8306170470
- 8306280382 Communits on EIS re water quality, in response to 830600 request CP re construm off & sedimentation pond issued on 760209 80NER, E A Indiana, State of 83/06/24 YOUNOBLOOD, B J Licensing Branch I ip 19001 PBI P4X Fiche 50-546,83/06/24,8306280382
- F Security, medical, Pmergency & fire protection plans
- 8306270P19 Amend 26 to CP & UL applications, consisting of Byron Amend 41 to 19AR Suppl 2 to environ rept & revs to training & qualification plan section of cafeguards vol Revs withheld (ref 10CFR2 770) W/o encls
 SHIELDS.S W Public Service (n of Ludiana, Inc 03/06/24 OCNTON, H R 0ffice of Nuclear Reactor Regulation, Director App 18991 219 24X Fishe 50-946,83/06/24,0306270219
- K. Utility Final Sairty Analysis Report (FSAR) & amends
- 930527013B Application for amend to CPPR 170 & CPPR-171, including Amend 26 to F8AR, rev to training & qualification plan section of safeguards vol & Suppl 2 to environ rept Ol stage (filed in PDR Category C) Safeguards vol withheld (ref 10CFR2 790) SHELDS, 8 W Public Service Co of Indiana, Inc 83/06/24 DENION.N R Uffice of Nuclear Reactor Regulation, Director Appl 18990 242 24X Fiche S0-346,83/06/24,840627013B
- --8305270152 Amend 25 to FSAR * Public Service Co of Indiana, Int 83/05/30 254pp 18790 315 24% Fiche 50-546,83/05/24,8306270136
- G Inspection reports: IE Bulletins & correspondence
- B305030144 Forwards IE Insp Repts 50-546/B3 05 & 50-547/B3-05 on B30330-0401 No noncompliance noted LITILE, W S Region 3, Office of Director 83/05/17 SHIELDS, S y Public Service Co of Indiana, Inc. 2 pp 18704 028 24X Fiche 50-046, 03/05/17, 8306030146
- --830603014B IC Insp Repts 50-546/83-05 & 50-547/83-05 on 830330-0401 Np noncompliance noted Major areas inspected follows on allegations/concerns re const deficiencies in 8vc Level I protective coatings area Rept addresses technical aspects NOMTON, J F , WILLIAMS, C C Region 3, Defice of Director 83/05/16 App 18704 030 24X Fiche 50-546,83/05/17,8306030146
- 8306030178 Forwards IE Insp Repts 50-546/83-03 & 50-547/83-03 on 830411-15 No Mencompliance noted LITTLE, W S Region 3. Office of Director 83/05/10 SHIELDS S W. Public Service Co of Indiana. Inc 2pp 18703-302 24X Fiche 50-546,83/05/18,8306030178

- ---8306030202 IE Insp Repts 50-846/83-03 & 50-547/83-03 on 830411-15 Np noncompliance noted Major areas inspected licensee progress on recovery progress in electrical arts LOVE, R S. WILLIAMS, C C. Region 3, Office of Director, 83/05/16 5pp 18703 304 24X Fiche 50-546,83/05/18,8306030198
- 8305110458 IE Info Notice B3-32, "Ruptured Am-241 Sources Contained in Hell Logging Device " Svc list encl TAYLOR, J M Division of Safeguards & Inspection Programs (Post 8301031) 63705726 Consolidated Edison Co of New York, Inc 125pp 18831 043 24X Fiche 50-000,83705726,8305110458
- 8305110460 IE Info Notice 83-34, "Event Nutification Info Worksheet"
 Svc list ent]
 JORDAN, CL Division of Chargency Preparedness & Engineering
 Response (Post 830103) 83/05/26 Consolidated Edison Co of New
 York, Inc 115pp 18732 085 24X Firks 30-000,83/05/26,8305110460
- 8305110461 IE Info Notice 83-35, "Fuel Movement H/Control Rods Withdrawn at BNRs " Svc limt encl JORDAN: EL Division of Emergency Preparedness & Engineering Response (Post 830103) 83705/31 Consolidated Edison Co. of New York, Inc 116pp 18732 208 24X Fiche 50-000.83705/31.8305110461
- 8306070137 Ack receipt of 830527 ltr informing NRC of steps taken to correct violations noted in IC Insp Repts 50-546/83-01 & 50-547/93-01 SPESSARD.R L Division of Engineering 83/06/01 SHIELDS.9 W Public Service Co of Indiana, Inc Ip 18739 219 24X Fiche 50-546/83/06/01.8306070137
- --8306070144 Responds to NRC 830425 ltr re violations noted in IE Insp Repts 50-946/83-01 & 50-94/83-01 Corrective actions cable tray to hanger ottachments & cable tray splice plate bolting identified at safety-related on design drawings SHIELDS, S W Public Service Co of Indiana. Inc 83/05/24 KEPPLERL J G Region 3. Defice of Director 6pp 18739 220 24X Ficha 50-546.83/06/01.83060/0139
- --B306070147 Requests inspector verification that program for improved control over electrical const adequate per B30202 confirmatory action ltr. Items 2-6 re electrical cable tray hanger installation
 BHIELDS.5 W Public Service Co of Indiana, Inc 83/04/08
 KEPPLER.J G Region 3. Office of Director ip 18739 226 24X
 Fichs 50-546,83/06/01.83060/0137
- 830.6270201 Forwards IE Insp Repts 50-946/83-06 ts 50-947/83-06 on 830401-0511 No noncompliance noted KNDP.R C Region 3. Office of Director 63/06/08 SHIELDS, S W Public Service Co of Indiana, Inc. 2pp 18991 270, 24X Fiche 50-546,83/06/08.8306270201
- --8306270205 IE Insp Repts 50-546/83-06 & 50-547/83-06 on 830401-0511 No noncompliance noted Major areas inspected allegations of cracked welds in electrical cable tray & conduit support hangers & review of training activities SCHAPKER.JF , KONKLIN.JF Region 3. Office of Director 83/06/08 Upp 18991 272 24X Fishe 50-546.83/06/08.8306270201
- 8305110464 IE Info Notice 83-36, "Impact of Security Practices on Safe Operations" Syc list encl JORDAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/09 Consolidated Edison Co. of New York, Inc. 119pp 18830 280 24X Fiche 50-000,83/06/09,8305110464
- 8305ii0470 IE Info Notice 83-39, "Defective Heat Sink Adhesive & Seismirally Induced Chatter in Relays Within Printed Circuit Cards" (Not list one)
 JURDAN, E.L. Division of Lawrgency Preparedness & Engineering Responso (Post 830103) 83/06/13 Consolidated Edison Co of New York, Inc. 118pp 18720 225 24X fiche 50-000,83/06/13,8305i10470
- B30A090010 IE Info Notice B3-37, "Transformer Failure Resulting From Degraded Internal Connection Cables." Svc list encl JURDAN,E L. Division of Emergency Preparedness & Engineering Response (Post B30103) 83706/13 Consolidated Edison Co. of New York, Inc. 243pp 18921 001 24X Fiche 50-000,83/04/13,8306090010
- 830.6210006 Responds to util request for partial release of electrical conduit & conduit hanger installation activities. Util program addressing confirmatory action ltr. Items 2-4 adequate for resumption of electrical work activities. KEPPLER, J G Region 3, Office of Director 83/06/15. SHIELD8, S W Public Service Co of Indiana, Inc. 2pp 18911.355 24X Fiche 30-546.83/06/15.8306210006
- B305110475 IE Info Notice B3-40, "Need to Environmentally Qualify Epoxy Grouts & Sealers " Byc list enc! JORDAN, C L Division of Emergency Preparedness & Engineering Response (Post 830103) B3704/22 Consolidated Edison Co of New York, Inc 115pp 19021 179 24X Fiche 50-000.83/04/22.8305110475

- 8305110477 IE Info Notice 83-41. "Actuation of fire Suppression Sys-Causing Inoperability of Safety-Related Equipment " Syc list enc! JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83206/22 Consolidated Edison (u. of New York: Inc. 120pp 18997 007 24X Fire 50-000.03705/22.030831047/
- 8305110479 IE Info Notice 83-42, "Reactor Mode Switch Malfunctions"

 8vc list encl

 JORDAN, E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/04/23 Consolidated Edison Co of New
 York, Inc 116pp 18996 242 24X Fishe 50-000,83/04/23,8305110479
- 8305110483 IE Info Notice 83-43, "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints "Svc list encl JORDANIE L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/24 Consolidated Edison Co of New York, Inc 116pp 19046 297 24X Fiche 50-000,63/06/24.0305110483
- 8 Reportable occurrences, LERs & related correspondence
- 8306070377 Final deficiency rept re mechanically cracked embedded box beam plate initially reported on 830503 Alternative welding methods investigated Similar embedded plate welds SHIELDS,S H Public Service Co of Indiana, Inc 83/05/31 KEPPLER,J Q Region 3, Office of Obsector 2pp 18741 344 24X Fiche.50-546,83/05/31,8304070J77
- 8306170182 Interim deficiency rept re separation of deformed will enchars from embedded plate in containment Initially reported on 821020 Investigation re source of sxial tensile stress applied to welds underway Next rept due 830702 SHIELDS, S W Public Servare Co of Indiana, Inc 83/06/07 KEPPLER, J O Region 3, Defice of Director 2pp 18883 254 24X Fiche 50-546, 83/06/07, 8306170182
- 8306270375 Interim deficiency rept re design changes not shown on detail drawings used by primary civil contractor (Newberg-Marble Hill) Initially reported on 830622 Drawing review continuing Next rept by 830826 BHECDS.S W Public Service Co of Indiana. Inc 83/06/16 KEPPLER.J Q Region 3. Diffice of Director 2pp 18993 212 24% Fichs 50-546.83/06/16.8306270375
- DOCKET STN-50-547 MARBLE HILL NUCLEAR STATION, UNIT 2

 A Application/construction stage documents & correspondence
- 8306060039 Forwards "Audit of Jul 1982 Cost Estimate for Marble Hill Nuclear Project," in support of util petition to increase #xisting rates & changes for retail electric syc & for approval of new rate schedules, rules & regulations SHIELD8.8 W Public Service Co of Indiana, Inc 83/05/31 DENTON, H.R. Office of Nuclear Reactor Regulation, Director Pap 18723-300 24X Fiche 50-544,83/05/31.8706060037
- --8306060043 "Audit of Jul 1982 Cost Estimate for Marble Hill Nuclear Project " Apps 1-5 encl + 0 "Prien-Kreitzberg & Associates, Inc 83/05/20 1107pp 18723 302 24X Fiche 50-546,03/05/31.830606003?
- B306140596 Forwards schedular commitments for submittal of environ qualification program in response to Questions M270 P & M270 3, per 830510 request for addl info re environ qualification of electrical & machanical equipment SHIELDS: 8 W Public Service Co of Indiana Inc 83/06/09 DENTON, HR Office of Nuclear Reactor Regulation, Director 3pp 18833, 138 24% Fiche 50-546, 83/06/09, 8306140596
- 8304200019 Summary of 830331 meeting w/utils & Mastinghouse in Bethasda.MD re Mestinghouse analysis & evaluation of D4/D5/E steam generator mod. MCPKINS.J B Licensing Branch 4 83/04/14. Licensing Branch 4 22pp 18908 327 24X Fiche 50~000,83/04/14,83068000019
- 8306200097 Informs that area proposed by util for const of transmission lines within range of state endangered bobcat, badger, Indianabat & within seasonal migration route of bald eagle, TURNER, D Indiana, State of 83706/14 YDUNGLOOD, B J, Licensing Branch I ip 18903.339 24X Fiche 50-346,83/06/14,8306200097.
- 8306220101 Forwards notice of G30712 public meeting in Madison, IN to discuss recent application submitted by util & Mabash Vallay Power Assoc. Inc for OLs to be published in local newspapers
 YOUNOBLOOD, B J. Licensing Branch 1 83/06/14 SHIELDB, 8 W Public Bervice Co. of Indiana, Inc. 3pp 15977: 343 24X
 Fiche: 50-546, 83/06/14, 8306220101

- 8306210127 Informs that site or associated transmission line impact on natl forest lands & program described in 830608 ltm will be forwarded to forest supervision H Godlevske for response SHUTTLEWORTH. W Agriculture. Dept of 83/06/15 YOUNGE GUD, B J Licensing Branch I ip 189/8 131 298 Fische 50-546.83/06/15, 8306210127
- 8306270219 Amend 26 to CP & UL applications consisting of Byton Amend 41 to FBAR. Suppl 2 to environ rept & ic,s to training & qualification plan section of safeguard vol Revs withhold (ref 100FR2 770) W/p encis
 SHIELDS.S W Public Service Co of Indiana, Inc. G.3/06/24
 DENTIN, HR Office of Nuclear Reactor Regulation, Director 6pp 18791 219 24X Fiche 50-546. B.3/06/24, B.06270219
- C Utility Environmental Report (CR), amends & correspondence
- 8306270138 Forwards Suppl 2 to environ tept OL stage
 SHICLDS, 8 W Public Service Co of Indiana, Inc. 83/06/24
 DENION, H R Office of Nuclear Reactor Regulation, Director Appl 18990 262 24X Fiche 50-546.83/06/24.8306270138
- --8306270149 Suppl 2 to environ rept Ut stage * Public Service Co of Indiana, Inc 83/06/30 46pp 18990 268 24% Fiche 50-546, 83/06/24, 8306270138
- D NRC Draft/Final Environmental Statements, supple & correspondence
- 9306170470 Requests info re environ impact of station operation to assist in EIS preparation Notification re participation in 830711-13 site visit due by 930630 YOUNOBLOOD, B J Licensing Branch 1 83/06/08 SM17H-P M Advisor Council on Historic Preservation 9pp 18894 347 24X Fiths 50-546,83/06/08,8306170470
- 8306280382 Comments on EIS re water quality, in response to 830608 request CP re const run off & sedimentation pend issued on 760209 BDHNER, E A Indiana, State of 63/06/24 YOUNGBLOOD, B J Licensing Branch | ip 19001 281 24X Fiche 50-546,83/06/24,8306800382
- F Security, medical, emergency & fire protection plans
- B306270219 Amend 26 to CP & OL applications, consisting of Byron Amend 41 to F6AR, Suppl 2 to environ rept & revs to training & qualification plan section of safeguards vol Revs withheld (ref 10CTR2 790) W/o encls
 SHIELDB.S W Public Service (o of Indiana, Inc. 83/06/24
 DENIGN, HR Office of Nuclear Reactor Regulation, Director App. 18791 219 24X Fichs 50-546,83/06/24,8306270219
- K. Utility Final Safety Analysis Report (FSAR) & amends
- 8306270138 Application for amend to CPPR-170 & CPPR-171.including Amend 26 to FSAR.rev to training & qualification plan section of safeguards vol & Suppl 2 to environ rept OL stage (filed in PDR Category C) Safeguards vol withheld (ref 10CFRR 770) SHIELDS, S W Public Service Co of Indiana. Inc 83/06/24 DENTON, HR Diffice of Nuclear Reactor Regulation, Director 6pp 18770 262 24X Fiche 50-546.83/06/24.6306270138
- --B306270152 Amend 26 to FSAR * Public Service Co of Indiana, Inc B3/06/30 254pp 18990 316 24X Fiche 50-546,83/06/24,830627013B
- O Inspection reports. IE Bulletins & correspondence
- 8304030144 Forwards IE Insp Repts 50-544/83-05 & 50-547/83-05 on 830330-0401 No noncompliance noted LITYLE, W S Region 3. Office of Director 83/05/17 SHIELDS, S W Public Service Co of Indiana, Inc. 2pp 18704-028 24X Fighe 50-544, 83/05/17, 8306030144
- --8304030148 IE Insp Repts 50-846/B3-05 & 50-547/B3-05 on B30330 0401 No noncompliance noted Major aleas inspected followup on allegations/concerns re const deficiencies in Byc Level I protective coatings area. Rept addresses technical aspects NERTON, J. F. WILLIAMS, C. C. Region 3, Office of Director B3/05/16 App. 18704 030 24X Fiche 50-546,83/05/17.8304000146
- 8306030198 Forwards IE Insp Repts 50-546/89-09 & 50-547/83-03 on 830411-15 No moncompliance noted LITTLE, W. 8 Region 3, Office of Director 83/05/10 SHIELDS, S W Public Service Co of Indiana, Inc. 2pp 18703 302 24X Fiche 50-546, 83/05/18, 8306030198

- --836630202 IE Insp Repts 50-546/83-03 & 50-547/83-03 on 830411-15 No noncompliance noted Major areas inspected licenses progress on recovery program in ejectrical area LOVE, R S . WILLIAMS.C C Region 3, Office of Director 83/05/14 5pp 18703-304 24X Fiche 50-546.83/05/18.8306030198
- 8305110458 IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in Well Logging Device" Svc list encl TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 125pp 18831 043 24% Fiche 50-000,83/05/26,8305110458
- 8305110460 IE Info Notice 83-34, "Event Notification Info Workshoet"
 Svc list encl
 JORDAN, C.L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/05/26 Consolidated Edison Co. of New
 York, Inc. 115pp 18732 085 24X Fiche 50-000, 83/05/26,8305110460
- 8305110461 IE Info Notice 83-35, "Fuel Movement W/Control Rods Withdrawn at BWKs " Svc list encl JORDAN, E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/31 Consolidated Edison Co. of New York, Inc. 116pp 18732 208 24X Fichs 30-000,83/05/31,8305110461
- B306070139 Ack receipt of B3052/ ltr informing NRC of steps taken to correct violations noted in IL Insp Repts 50-546/03-01 & 50-547/83-01 SPESSARD.R L Division of Engineering B3/06/01 SHIELDS.5 W Public Service Co of Indiana, Inc. 1p. 18739 219 24X Fiche 50-546.83/06/01.8306070179
- --B306070144 Responds to NRC 830425 ltr re violations moted in II. Insp Repts 50-546/83-01 & 50-547/83-01 Corrective actions cable tray to hanger attachments & cable tray splice plate bolting identified as safety-related on desion drawings SHIELDS, 8 W Public Service Co of Indiana. Inc. 83/05/24 KEPPLER. J G. Region 3. Office of Director. App. 18739 220 24% Fichs 50-546,83/06/01,8306070137
- --B306070147 Requests inspector verification that program for improved control over electrical const adequate per 830202 confirmatory action ltr. Items 2-6 re electrical cable trny hanger installation
 SHIELDS.S W Public Service Co of Indiana, Inc 83/04/08 KEPPLER.J O. Region 3. Office of Director 1p 18739 276 24% Fiche 50-546.83/06/01.8306070137
- 8306270201 Forwards IE Insp Repts 50-546/83-06 & 50-547/83-06 on 830401-0511 No noncompliance noted KNOP.R C Region 3. Office of Director 83/06/09 SHIELDS, 9 W Public Service Co of Indiana, Inc. 2pp 18991 270 24X Fiche 50-546.03/06/08.8306270201
- --9306270205 lE Insp Repts 50-546/83-06 & 50-547/83-06 on 830401-0511 No noncompliance noted Major areas inspected allegations of cracked we'ds in electrical cable trap & conduit support hangers & review of training activities
 SCHAPMER.JF, KDNKLIN,JE Region 3, Office of Director 83706/08 89p 18791 2/2 24% Fichs 50-546.83/06/08.8306270201
- B305110464 IE Info Natice 83-36, "Impact of Security Practices on Safe Operations " Svc list encl JORDANNE L Division of Emergency Preparedness & Engineering Response (Post 830103) B3706/07 Consolidated Edison Co of New York, Inc 117pp 18830 280 24X Fiche 50-000,83706/09,8305110464
- 9305110470 IE Info Notice 83-38, "Defective Heat Sink Adhesive & Boismically Induced Chatter in Relays Within Printed Circuit Cards " Syc list enc)
 JORDAN, E. L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/06/19 Consolidated Edison Co. of New York, Inc. 118pp 18720 225 24X Fiche 50-000,83/06/13,8305110470
- 8396090010 IE Info Notice 83-37, "Transformer Failure Resulting From Degraded Internal Connection Cables" Svo list encl JORDAN, E. L. Division of Emergency Proparadoess & Engineering Response (Post 830103) 83706/13 Contolidated Edison Co. of New York, Inc. 243pp 18921 001 24X Fiche 80-000,83706/13,8304090010
- 8306210006 Responds to util request for partial release of electrical conduit & conduit hanger installation activities Util program addressing confirmatory action ltr. Items 2-6 adequate for resumption of electrical work activities KEPPLER. J 0 Region 3. Office of Director 89706/15 BHIELDB, 8 W Public Service Co of Indiana, Inc. 2pp 18911 355 24X Fiche 50-546,83/06/15,8306210006
- 8305110475 IE Info Notice 83-40. "Need to Environmentally Qualify
 Epoxy Grouts & Sealers " Svc list encl
 JORPAN.E L Division of Emergency Preparadness & Engineering
 Response (Post 830103) 83706/22 Consolidated Edison Co of New
 York, Inc 115pp 17021 179 24X Fichs.50-000.83/96/22.0305110475

- B30B110477 IE Info Notice 83-41, "Actuation of Fire Suppression Sys Causing Inoperability of Safety-Related Equipment " Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post B30103) B3/06/22 Consolidated Edison Co of New York, Inc 120pp 18997 007 24X Fiche 50-000/B3/06/22, B309110477
- B305110479 IE Info Notice B3-42, "Reactor Mode Switch Malfunctions "
 Svc list encl
 JORDAN,E L Division of Emergency Preparedness & Engineering
 Response (Post B30103) B3/06/23 Consolidated Edison Co of New
 York Inc 116pp 18996 242 24X Fiche 50-000.B3/06/23,B305110479
- 8305110483 IE Info Notice B3-43. "Improper Battings of Intermediate Range (IR) High Flux Trip Setpoints " Svc list encl JORDAN, EL Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/24 Consolidated Edison Co of New York, Int 116pp 19046 297 24X Fiche 50-000,83/06/24.8305110483
- S Reportable occurrences, LERs & related correspondence
- 8306270375 Interim deficiency rept re design changes not shown on detail drawings used by primary civil contractor (Newberg-Harble Hill) Initially reported on 830622 Drawing review continuing Next rept by 830826 SHIELDS.8 W Public Service Co of Indiana, Inc 63/06/16 KEPPLER.J O Region 3, Office of Director 2pp 18993 212 24X Fiche 50-546, 83/06/16. 8306270375
- DOCKET STN-50-553 PHIPPS GEND NUCLEAR STATION, UNIT 1

 8 Reportable occurrences. LERs & related correspondence
- 8306160454 Pt 21 rept re potential defect in transmitter mfg by Rosemount. Inc used in control sys of components furnished to listed plants All components involved retrofitted w/new circuit boards Matter closed OIROUX,E J Carrier Corp 83/05/23 STELLO,V Director's Office. Office of Inspection and Enforcement ip 18863 694 24X Fichs 50-518, 63/05/23, 8304140454
- DOCKET 81N-50-554 PHIPPB BEND NUCLEAR STATION, UNIT 2 S Reportable occurrences, LERs & related correspondence
- 8306160454 Pt 21 rept re potential defect in transmitter mfg by
 Rosemount.inc used in control sys of components furnished
 to listed plants All components involved retrofitted w/new
 circuit boards Matter closed
 QIRQUX.E J Carrier Corp 83/05/23 STELLO, V Director's Office.
 Office of Inspection and Enforcement ip 18863 094 24X
 Fiche 50-518.83/05/23,8306160454
- DOCKET STN-50-556 BLACK FOX STATION, UNIT 1
- A Application/construction stage documents & correspondence
- 8304290128 Forwards FR notice of withdrawal of application for CPs & revocation of LWA & AGLB 830707 order & ABLAB 830414 order re termination of appellate jurisdiction retained in ALAB-573 re radon issue DENTON.H R Office of Nuclear Reactor Regulation, Director 83706722 HESTLJ B Public Service Co of Oklahoma 3pp. 19046 180 24X Fiche 50-556.83706722.8306290128
- --8306290135 Notice of withdrawal of application for CPs & revocation of LWA ADENSAME Q Licensing Branch 4 63/06/22 Spp 19044,163 24% Fiths: 30-554.83/06/22,8306290128
- @ Inspection reports: IE Bulletins & correspondence
- 8305110458 IE Info Notice 83-32. "Ruptured Am-241 Sources Contained in Well Logging Device " Svc list encl. TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 63/05/24 Consolidated Edison Co of New York, Inc 125pp 18831 043 24X Fiche 50-000,83/05/25,8305110458
- 8305110460 IE Info Notice 83-34, "Event Notification Info Worksheet"
 8vc list encl
 JORDAN, E. L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/05/26 Consolidated Edison Co. of New
 York, Inc. 115pp 18732 085. 24X Fiche: 50-000, 83/05/26, 8305110440

- 8305110461 IE Info Notice 83-35, "Fuel Mavement W/Control Rods Withdrawn at BMRs " Syc list encl JORDAN E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/31 Consolidated Edison Co of New York, Inc 116pp 18732 208 24X Fiche 50-000.83/05/31,8305110461
- 8305110464 IE Info Notice 83-36, "Impact of Security Practices on Safe Operations " Svc list encl JORDAN, E. L. Division of Emergency Proparedness & Engineering Response (Post 830103) 83706/09 Consolidated Edison Co. of New York, Inc. 119pp 18830 280 24X Fiche 50-000,83/06/09,8305110464
- 8305110470 IE Info Notice 83-38. "Defective Heat Sink Adhesive & Seismically Induced Chatter in Relays Within Printed Circuit Cards " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co of New York, Inc. 118pp 18920 225 24X Fiche 50-000.83/06/13.8305110470
- B306090010 IE Info Notice 83-37. "Transformer Failure Resulting From Degraded Internal Connection Cables " Svc list encl JORDAN.E L. Division of Emergency Preparedness & Engineering Response (Post 830103) B3706/13 Consolidated Edison Co of New York, Int 243pp 18921 001 24X Fiche 50-000.83/06/13.8306090010
- 8305110475 IE Info Notice 83-40, "Need to Environmentally Qualify Epoxy Grouts & Sealers " Syc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/22 Consolidated Edison Co of New York, Int 115pp 17021 179 24X Fiche 50-000.83/06/22,8305110475
- 8305110477 IE Info Notice 83-41, "Actuation of Fire Suppression Sys Causing Inoperability of Safety-Related Equipment" Svc list encl JORDAN, E. Division of Emergency Preparedness & Engineering Response (Post 830103). 83/06/22 Consolidated Edison Co of New York, Inc. 120pp 18797-007 24X Fishe 50-000.83/06/22,8305110477.
- 8305110483 IE Info Notice 83-43, "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints " Svc list encl JORDAN, E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/24 Consolidated Edison Co of New York, Inc 116pp 19046 297 24X Facha 50-000,83/06/24,8305110483

DOCKET STN-50-557 BLACK FOX STATION, UNIT 2

A Application/construction stage documents & correspondence

- 830629012B Forwards FR notice of withdrawal of application for CPs & revocation of LMA & ASLB B30307 order & ASLAB B30414 order restarmination of appellate jurisdiction retained in ALAR-573 re radon issue DENTON.H R Office of Nuclear Reactor Regulation: Director 83/06/22 MESTJ.B. Public Service Co of Oklahoms Opp 19046 180 24X Fichs.50-556.83/06/22.8306290128
- --8306290135 Notice of withdrawal of application for CPs & revocation (if LMA ADENBAM, E. Q. Licensing Branch 4 83/06/22, 3pp 19046, 183 24X Fiche 50-556, 83/06/22, 8306290128,

O Inspection reports, IE Bulletins & correspondence

- 8305ii0458 IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in Well Logging Device" Svc list ent!
 TAYLOR, J. M. Division of Safeguards & Inspection Programs (Post 930i03) 83/05/26 Consolidated Edison Co of New York, Inc 125pp 18831 043 24X Fiche:80-000,83/05/26,8305i10458.
 - Event Notification Info Worksheet "

Preparedness & Engineering Consolidated Edison Co of New X Fiche, 50-000, 83/05/26, 8305110460

ovement W/Control Rods

aredness & Engineering on New --he 50-000,83/05/31,8305110461.

- 8305110464 IE Info Notice 83-36, "Impact of Security Practices on Hofe Operations "Svc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83706/09 (onsolidated Edison Co of New York, Inc 119pp 18830 280 24X Fische 50-000,83706/09,8305110464
- 8305110470 IE Info Notice 83-38, "Defective Heat bink Adhesive & Beismically Induced Chatter in Relays Within Printed Circuit Cards " Svc list oncl JORDAN,C L Division of Emergency Properedness & Engannering Response (Post 830103) 83706/13 Consolidated Edison Co of New York, Inc. 118pp. 18920-225 24X Fiche 50-000,83706/13,8305/1101/0
- 8306070010 IE Info Notice 83-37: "Transformer Failure Resulting | Fun Degraded Internal Connection Cables " Evo list and JURDAN, E | Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/13 Consolidated Edison Co of New York Inc 243pp 18721 001 24X Fichu 50-000 83/06/13, 8380/070010
- 8305110475 IE Info Notice 83-40, "Need to Environmentally Qualify
 Epory Grouts & Sealers " Byo list encl
 JORDAN E L Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/06/22 Consolidated Edison Co of New
 York, Inc 115pp 17021 179 24X Fiche 50-000,83/06/22,03051104/5
- 8305i10477 IE Info Notice 83-41, "Actuation of Fire Suppression Sys Causing Inegerability of Bafety-Related Equipment" Syr list enc! JORDAN,E L. Division of Emergency Preparedness & Ingineering Response (Post 830103) 83/06/22 Consolidated Edison Co. of New York, Inc. 120pp 18997 007 24X Fisho 30-000.83/06/22,03051104//
- 9305110477 IC Info Notice 93-42, "Reactor Mode Switch Molfonctions " Svc list encl JORDAN,EL Division of Emergency Proparedness & Engineering Response (Post 830103) 83/06/23 Consolidated Edison to at New York, Inc. 116pp 18996-242 24X Fiche 50-000,83/06/23.8305/194//
- B305110483 IE Info Notice 83-43, "Improper Bettings of Intormodiate Range (IR) High Flux Trip Setpoints " Svc list and JDRDAN-E L Division of Emorgency Proparedness & Enganeering Response (Post 830103) 83/06/24 Consulidated Edison on New York, Inc 116pp 19046 297 24X Fiche 50-000,83/06/24.630511016J

DOMESTIC LICENSING OF SPECIAL NUCLEAR MATERIAL

DOCKET 70-000B BATTELLE MEMORIAL INSTITUTE, COLUMBUS, OH

- 8306230127 Responds to FOIA request for five categories of documents respond to spent fuel at facilities App A & B documents respond to Items 1,2,4 & 5 Forwards App B Documents 1 & 5-11 No documents located for Item 3 FELTON, J M Division of Rules and Records 83/04/13 AUDIN,1 Affiliation Unknown 3pp 18982 047 24% Fiche 50 014,8,1/04/1,1,8306230129
- ---8306230137 Part 21 rept re employee recriving dose of 30 /10 rems to right hand on 800720 while removing particulate cartridge from water filter subsequent to cask flushing operation TOY.H L Battelle Memorial Institute Pacific Northwest Laboratory 80/08/19 KEPPLER, J G Region 3, Chicago, Office of the Director App 18782-060
- --B306230139 Forwards data sheet for Part 21 Rept 80-296-000 to defert to spent fuel cask unloading procedures.per TI1109/P(Rev 1) F19HER.W L Region 3. Chicago, Office of the Director HU/16/21 HIGGINNOTHANL Region 3. Chicago, Fuel Facility & Materials Safety Branch ip 18982-066
- --8306230144 Forwards data sheet for Part 21 Rept B0-256-000 pe defect in spont fuel unloading procedures Completed data sheet should be returned by B01001 Comments on Part 21 rept encl HIGGINBOTHAM. L. Region 3, Chicago, Fuel Facility & Materials Safety Branch ,80/08/27 DAVIS.A B Region 3, Chicago, Furl Facility & Materials Safety Branch 4pp 18982-067
- --8306230149 Forwards request for addl info re IE Insp Repts /O DGKI/ 82-02,30-05728/80-02 & 50-006/80-01 concerning problems w/NF8-4 (NAC-IE) cask.per 810226 telcon CARLEDN.R T Region 1, Philadelphia, Dffice of the Director, 81/02/27 FISCHER.W L Region 3, Chicago, Office of the Director 4pp 18982 071 24X Fiche 50-004,83/04/13,8306230189
- --8306230153 Forwards add1 info re IE Insp Rept 70-0008/80-02 re over#ir# through vent tubing, means of floor surfaces & radiation levels w/portable instrument & removal of fuel assembly FISCHER, M. L. Technical Inspection Branch 81/03/25 CANLOW, R 1 Director's Office, Office of Inspection and Enforcement Spp 18982-075

- DOCKET 70-0025 ROCKWELL INTERNATIONAL CORP , CANOGA PARK, CA
- 8306060274 Order CLI-83-15, requesting potential intervenors to file statement setting forth certain facts, within 45 days of order Parties to informal adjudication are licensee & persons filing intervention statement Addl views encl CHICA. B J Office of the Secretary of the Commission 83/06/02 Spp 18730 027
- 830&060307 Forwards Commission order re request for hearing on license renewal Addresses of signatories to 821124 ltr requested STUCKY.S W Docketing & Services Branch 83/06/03 MICHAFLS.A Affiliation Unknown 1p 18/27 130
- ~-8306060309 Request for public hearing on license renewal WILLIANS.R K , WOLLIN.J , ZEIDLER.Z Affiliation Unknown 82/11/24 PAGE NRC ~ No Detailed Affiliation Given 3pp 18729 131
- 8306080185 Notice of appointment of RM Lazo as presiding officer to conduct informal proceeding re Rockwell Intl Energy Sys Group application to renew License SNM-21 COTTER. B P Atomic Safety and Licensing Board Panel 83/06/06 lp 18772 260
- 8304290343 Demands public hearing on license renewal & opposes response to ASLB questions on financia) interests of individuals requesting hearings COCKL Affilation Unknown 83/04/21 PALLADING N J NRC No Detailed Affiliation Given 2pp 19055 243
- DOCKET 70-0084 IDWA STATE UNIV . AMES. IA
- 8306100275 Submits corrected date for application to renew License R-59 & advises that computer printout records summarizing SNM inventory results for 1981 to 1982 corrected in response to IE Insp Repts 50-116/83-01 & 70-0084/83-01 HENDRICKSON, R lowa State Univ 83/05/19 PIRTLE, 0 L Region 3, Office of Director 2pp 18805 142 24% Fiche 50-116.83/05/19, 8306100275
- DOCKET 70-0115 WASHINGTON, UNIV OF, BEATTLE, WA
- 8306280455 Discusses IE insp of License CNM-108 on 630517 & forwards notice of violation
 SCARAND,R A Division of Radiological Safety & Safeguards Program 83/06/07 CHALK,W S Washington, Univ of, Seattle, WA 2pp 19020 13b
- --8306280458 Notice of violation from insp on 830517 Noncompliance noted five fu/De sources not leak tested within required 6-month interval THOMAS, R D Region 5. Office of Director 83/06/07 ip 19020 137
- DOCKET 70-0121 INTERIOR, DEPT OF, DENVER, CD
- 8304240140 Forwards IE Safeguards Insp Repts 50-274/83-02 & 70-0121/83-02 on 830418-20 No noncompliance noted MADSEN, 8 L Region 4. Office of Director 83/06/20 NILLARD. II Interior. Dept of. Geological Survey 2pp 18980 162 24X Fiche 50-274, 83/06/20, 8306240140
- --8306240148 IE Bafeguards Inap Repts 50-274/83-02 & 70-0121/83-02 on 830418-20 No noncompliance noted Najor areas inspected nuclear matl control & accountability, including facility organization & operations Details withheld (ref 100FR2 770). CALDHELLR A . KELLY, J A F . WESTERMAN, T F Region 4. Office of Director 83/06/15 ip 18980-164 24% Fichs 50-274, 83/06/70, 8306240140
- DOCKET 70-0124 TELEDYNE ISOTOPES, INC . WESTWOOD, NJ
- 830&020019 Application to amend License SNM-107, reducing possession limit of U-235 from 235 to 225 g BLACK, S A Teledyne Isotopes 83/03/24 PAGE, R, G Uranium Fuel Licensing Branch ip 18702 343

- DOCKET 70 -0134 WISCONSIN, UNIV OF, MADISON, WI
- 8306270162 Forwards IE Insp Repts 50-154/83-03 & 70-0134/83-01 on B30519-20 No nuncompliance noted PAFERIELLD, C J Region 3. Office of Director B3/06/08 CASHAELL, R J Wisconsin, Univ of Madison 2pp. 18972 026 24X Fichs 90-156, 83/06/08, 8306270162
- --B306270167 IE Insp Repts 50-154/B3-03 & 70-0134/B3-01 on B30519-20 No noncompliance noted Major areas inspected radiation protection & raduaste mgt program.including organization & qualifications & logs & records
 PAUL, R A . GREGER, L R . Region 3, Dffice of Director B3/06/08 dpp 18992 028 24X Fiche 50-156.83/06/08,8306270162
- DOCKET 70-0135 BABCOCK & WILCOX CO , APOLLO, PA
- 8306200020 Notifies of B30423 accident Truck carrying 45 packages containing low enriched U dioxide powder.36 empty 55 gallon drums & two boxes of low enriched U lab samples overturned in Lynchburg, VA No radioactive mati released AUSTIN.M A Dabcock & Wilcox Co 83/05/19 Office of Nuclear Material Safety & Safeguards, Director ip 18708 350
- DOCKET 70-0143 NUCLEAR FUEL SERVICES, INC. , ERWIN, TN
- 8306030283 Repts on airborne radioactivity concentrations released from plant stacks for Apr 1783 GUINN:F K Nuclear Fuel Services, Inc (subs of Getty Oil Co). 83/08/13 O'REILLY.J.P. Region 2. Office of Director 6pp 18734
- B30&080381 Act receipt of IE Insp Rept 70-0143/83-15 No proprietary info QUINN.F K Nuclear Fuel Bervices, Inc. (subs. of Getty Dil Co.) 83/05/23 BTDNR,J P Division of Project & Resident Programs 1 18789 3&0
- 8304030175 Trip rept of 830418-22 meetings w/Nuclear Fuel Svcs in Erwin.TN re health-physics insp of facility 800N0.A L Uranium Fuel Licensing Branch 83/05/26 Uranium Fuel Licensing Branch. 2pp 18733 318
- 8304140700 Forwards IE Safeguards Insp Rept 70-0143/83-18 on 830411-15 No noncompliance noted 8TDHR,JP Division of Emergency Preparedness & Materials Safety, 83/06/02 MANSER,W.C. Nuclear Fuel Services, Inc. (subs. of Cetty 011 Co.) 2pp 18840 207
- --8306140713 IE Safaguards Insp Rept 70-0143/83-18 on 830411-15 No noncompliance noted Major areas inspected MC-852068 measurement & statistical controls MC-852138 & inventory verification Details withheld (ref 100FR2 790) SADADDS J W Region 2. Office of Director MCALPINE, E J. Division of Emergency Preparedness & Materials Safety 83/06/02 ip 18840 209
- 8306150264 Ack receipt of 830407 ltr informing NRC of steps taken to correct violation noted in IE Safeguards Insp Rept 70-0143/83-08 STOHR. J P Division of Emergency Preparedness & Materials Safety 83/06/02 MANSER, W C Nuclear Fuel Services, Inc (subs of Getty Uil Co.) ip 18848-326
- --8306150269 Responds to NRC B30310 ltr re violation noted in IE Safeguards Insp Rept 70-01437B3-0B Corrective actions withheld (ref 100FR2 790) MANBER, W C Nuclear Fuel Services, Inc (subs of Cetty Dil Co) B3/04/07 STDHR.P Division of Emergency Preparedness & Materials Bafety ip 18848 327
- 830616065B Responds to B30407 questions re proposed groundwater monitoring program. Depth of proposed wells expected to be similiar to existing wells or approx 20 ft Agrees to comply w/lower limits of detection specified QUINN.F.K. Nucleor Fuel Bervices, Inc. (subs. of Getty Dil Co.) 83/06/03 CROWN,W.T. Uranium Fuel Licensing Branch ... 6pp. 18884-346
- 830A210436 Issues Amend 20 to License BNM-124.authorizing installation of nonfavorable geometry pits in Bldgs 302 & 303.8ER supporting licensing action & review of license amend application encl.
 PAGE: R 0 Uranium Fuel Licensing Branch 83/06/10. IDEKER, R. Nuclear Fuel Services. Inc. (subs. of Getty Oil Co). App. 18936-270

- --B306210440 SER supporting Amend 20 to License SNM-124, author; ring installation of nonfavorable grometry pits in floor beneath furnaces in Bldgs 302 & 303 Pits in floor needed for installation & maint of equipment for improved operation BIDINGER, 6 H. CROW, W.T. Uranium Fuel Licensing Branch 83/06/10 2pp 18936 273
- 8306170345 PNO-II-83-046 on 830613, fire identified in high-enriched U incinerator ventilation duct Cause not determined No indications of personnel exposure or contamination noted Downwind radiation monitoring devices being analyzed WRAY, J R. BARR, K. Region 2. Office of Director 83/06/14 1p 18880.293
- 8306270572 Ack receipt of IE Insp Rept 70-0143/83-20 No proprietary
- 8306270240 PNO-II-B3-050 on 830620, bimonthly inventory difference resulting from 830420 physical inventory reported inventory difference was accounting gain greater than calculated error limit. Investigation initiated by licensee MCALPINE, E. J. Region 2, Office of Director 83/06/21 ip MCALPINE, E J 10788, 267

DOCKET 70-0258 ILLINDIS, UNIV OF, URBANA, IL

- 8306090023 Responds to violation noted in IE insp rept Forwards data showing that calibr checks performed on docimenters on 830616 BECK. O.P. Illinois. Univ. of. Urbana-Champaign 83/1 GRANT, N.B. Region 3. Office of Director 2pp 1879 Fichs 50-151, 83/05/21, 8306090023 84/05/31 2pp 18/92-356 24X
- DOCKET 70-0267 NEW YORK, STATE UNIV OF, BUFFALO, NY
- 8306170050 Ack receipt of 830511 ltr informing NRC of steps taken to correct violations noted in IE Imap Repts 50-057/82-01 & 70-0267/82-01 MARTIN.T T Division of Engineering & Technical Programs HENRY, L G. New York, State Univ of Buffalo, 2pp 188 24X Fiche 50-057,83/06/01,8306170050 89/06/01 18682 210
- --8306170052 Responds to NRC 930427 ltr re violations noted in IF Insp. Repts 50-057/82-01 & 70-0267/82-01 Corrective actions new reactor engineer added to assume responsibility for accountability actions & records Fuel burnup code modified HENRY.L Q. New York, State Univ of, Buffelo 83/05/11. HARTIN.T T. Division of Engineering & Technical Programs ip 19982 212. 24% Fiche 50-057,83/06/01.8306170050

DOCKET 70-0364 BABCOCK & WILCOX CO , APOLLO, PA

- 8306060163 Forwards IE Insp Rept 70-0364/83-02 on 830321-23 & notice of Violation STAROSTECKI,R. Division of Project & Resident Programs B3/05/23 COLEMAN.W L Babcock & Wilcox Co 2pp 18728 105
- --8304040173 Notice of Violation from insp on 820321-23 * Region i, Office of Director 83/05/23 2pp
- --8306060176 IE Insp Rept 70-0364/83-02 on 830321-23 Noncompliance noted JUDIODIZE LE Insp Mept 70-0364/63-02 on 630321-23 Noncompliance refailure to maintain air flow from areas of low contamination potential to high contamination & failure to take corrective actions when smear survey exceeded 100 dpm/100cm RDTH, J. ELSASEER.T C Region 1. Office of Director 63/05/18 9pp 18728 109.
- 8306280473 Responds to 830310 ltr re cancellation of Pu decommissioning fundamental nuclear math control plan for License SNM-414 & submitted of control plan for low enriched U decontamination activities under License SNM-145 ALLAN, J M Region 1. Office of Director 83/06/16 COLENAN, H L Bahenek & Wilcox Co. 200 (2007) 127.

10 . UNCABVILLE, CT

to Page 10,0-70 re wet & dry 5/12 BIDINOTR.G. Fuel 1p 18734 362

- 8306010148 Forwards IE Safequards Insp Rept 70-0371/83-03 on 830321-25 MARTIN. T 7 Division of Engineering & Technical Pingrams 83/05/17
 AMY. & D United Nuclear Coip 2pp 18674 051
- ~~B3DAD10153 IE Safeguards Insp Rept 70 *0371/83-03 on B30321-25 No noncompliance noted Major areas inspected measurement control program, shipper-receiver verification, inventory difference & associated limit of error verification ZIBULSKY, H., KENT, J., GODY, A.T., Region 1, Office of Director B3/05/13 4pp 18474-053
- 8304030238 Fawards IE Safeguards Insp Rept 70-0371/83-05 on 830411 15 No noncompliance noted

 No noncompliance noted

 MARTIN. T V Division of Engineering & Technical Programs U3/05/20

 AMY, C U United Nuclear Corp 2pp 18/08 271
- --8306030324 IE Safeguards Insp Rept 70-0371/83-05 on 830411-15 No
 - noncompliance noted Major areas inspected inventory verification ZIBULSKY, N . DELLA RATTA.A . GODY, A T Region 1. Office of Director G3/05/18 2pp 18708 27.
- 9304030314 Forwards IE Safeguards Insp Rept 70~0371/83-06 on 830503-05 MARTIN.T T Division of Engineering & Technical Programs U3/05/20 AMY, Q O United Nuclear Corp 2pp 18/08/275
- --8306030317 IE Safequards Insp Rept 70-6371/83-06 on 830503 06 No noncompliance noted Major areas inspected security program audit testing & maint, locks, keys & combinations & security sys power supply SMITH, G C , DUNLAP, J M , GUNY, A f Region 1, Office of Director 83/05/18 3pp 18708 277
- 8306170241 Forwards IE Safequards Insp Rept 70-0371/83-07 on 830509-14 No noncompliance noted

 No noncompliance noted

 MARTINITY Division of Engineering & Technical Programs 83/06/01

 ARY, 0 O United Nuclear Corp Ppp 18878-280
- --8304170245 IE Safequards Insp Rept 70-0371/83-07 on 830509 I3 No noncompliance noted Major areas inspected physical inventory reconciliation & records & repts RATTA. A D., WOLTNER, E., GODY. A T. Region 1, Office of Director 82/05/31 2pp 18878 282
- 8306210449 Forwards request for addl info in order to proceed w/ilh associated w/renewal of License SUB-1010, during 830518 RHODES, M J Utanium Fuel Licensing Branch 83/06/10. Nuclear Corp 6pp 18935 345
- 8306280095 Trip rept of 830517-18 meetings & site tour w/ORNL & State of CT in Uncasyille.CT re environ review for United Nuclear Corp Naval Products license renewal application RHODES, M J Uranium Fuel Licensing Branch 83/06/16 Unanium Fuel Licensing Branch 2pp 19042 361 Fuel Licensing Branch 2րթ
- DOCKET 70-0498 EASTERN MICHIGAN UNIV , YPSILANTI, MI
- B306170077 GA program W/830531 ltr KOEHLKK N Gearheart-Owen Industries, Inc 83/06/31 MACDONALD.C E Transportation Branch 4pp 18907 3 18907 359
- DOCKET 70-0667 UNION CARBIDE CORP . TUXEDO, NY
- 8306030064 Describes present monitoring sys to replace old sys detailed on Page 33 of rept discussed on 830510 VOTH, M II Union Carbide Corp 83/05/11 CLARK, 1 NRC No Detailed Affiliation Given ip 18733 208
- 8304010338 Forwards IE Safeguards Insp Repts 70-0687/83 01 on 830428-29 No noncompliance noted HARTIN:T T Division of Engineering & Technical Programs 83/05/1/ MCGOVERN:J J Union Carbide Corp 2pp 18680 079
- --8304010339 IE Safeguards Insp Rept 70-0697/83-01 on 830425-29, No JOAN 10339 It Bareguards inspected nuclear motil control & accounting including shipper/receiver verification physical inventory & verification DELLA RATTA.A. ZIBULSKY.H., CODY.A T Region 1, Offic Director 83/05/13 3pp 18680 OC1 Region 1. Office of

- DOCKET 70-0698 WESTINGHOUSE ELECTRIC CORP , PITTSBURGH, PA
- 8306020387 Forwards IE Insp Rept 70-0698/63-01 on 830308 & 10 & natice of violation
 MARTIN.T F Division of Engineering & Technical Programs 83/05/20
 NARDI.A J Westinghouse Electric Corp 2pp 18695 001
- --8306020391 Notice of violation from into on 830308 & 10 * Region 1, Office of Director 83/05/20 ip 18695 003
- --8306020392 IE Insp Rept 70-0698/83-01 on 830308 & 10 Noncompliance noted licensee transferred licensed matl in form which recipient not authorized to receive NICOLOSI.J. KINNEMAN.J. Region 1. Office of Director 83/05/20

DOCKET 70-0734 GA TECHNOLOGIFS, INC . SAN DIEGO, CA

- 830&100005 Forwards requested info re 1963 shipping plan for HTGR fuel algments Tri-State escorts will assume responsibility at GA Co protected area & relinquish responsibility at plant site MOMRY. W GA Technologies, Inc. Copeneral Atomic Co. 83/05/19 HILLMAN, C Division of Safequards 4pp 18815 317
- G306200379 Forwards IE Safeguards Inap Rept 70-0734/83-07 on 830410-0513 No noncompliance noted NGNDERHAMO, L. R. Region 5, Office of Director 83/06/15 PARKER, J. W. GA Technologies, Inc. / General Atomic Co. 2pp 1889
- --8306200383 IE Safeguards Insp Rept 70-0734/83-07 on 830418-0513 No noncompliance noted Major areas inspected independent safeguards efforts measurement controls & physical inventory Details withheld (ref 10CFR2 790) NELSON, 9 B, WIEDER, A V, NORDERHAUS, L\R Region b, Office of Director 83/06/15 ip 18879 003
- B306290082 Forwards negative declaration & EIA (NUREG-0994) re renewal of License BNM-696 W/o EIA PAGE.R Q Uranium Fuel Licensing Branch B3/06/21 MOWRY.W R GA Technologies, Inc /General Atomic Co ip 19046.167
- --8304290083 Negative declaration supporting renewal of License SNM-676 PAGE.R 9 Uranium Fuel Licensing Branch 83/06/21 2pp 19046 168
- DOCKET 70-0754 GENERAL ELECTRIC CO . PLEASANTON, CA
- B306020234 Advises of shipment of 12 irradiated fuel rods from Monticello, NN to BMI Schedule withhold (rpf 10CFR73, 21) KIRKLAND,M W General Electric Co B3/04/26, Region 3, Office of Director 3pp 18700 352
- DOCKET 70-0820 UNITED NUCLEAR CORP . WOOD RIVER JCT . RI
- 8306080098 Discusses 830502-04 & 06 meetings w/United Nuclear, Naval Freducts Div & C-E in Montville.CT & Windsor.CT, respectively, re-safeguards program & other safeguards, classified & licensee proprietary linfo JACK90N.R L Material Control Licensing Branch 63/05/19 BROWN.R B Fuel Facility Safeguards Licensing Branch 1p 10789 362
- 8305130450 Forwards list of rejected concrete grid blocks replaced per Oak Ridge Assoc Univs Apr 1903 contamination level survey HELOESON.K A United Nuclear Corp 83/05/31. CROW.W T. Office of Nuclear Material Bafety & Bafeguards, Director 5pp 18830 179.
- 9304170435 Summary of 930425-27 meetings w/licensee & ORNL in Wood fliver Junction RI to observe ORNL performance of main process bldg radiological survey \$6000.A L. Uranium Fuel Licensing Branch 83/06/09 Uranium Fuel Licensing Branch 2pp 18907 333
- B306230114 Forwards IE Insp Rept 70-0820/83-03 on B30418-0506 No noncompliance noted STAROSTECKIR. Division of Project & Resident Programs B3/06/09. AMY-0 O United Nuclear Corp 2pp 10747 057
- --8306230118 IE Insp Rept 70-0820/83-03 on 830418-0506 No noncompliance noted Hajor areas inspected decommissioned processing areas ROTH.J. CLEMONS.P., ELSASSER.T.C. Region 1, Office of Director. 63/06/07 13pp 18947 057

- B306290877 Forwards revised Bubsection 2 to Section 1 of final survey rept re description of methodology HELGESON, K A United Nuclear Corp B3/06/16 GROW, W T. Office of Nuclear Material Safety & Safeguards, Director 2pp. 19047 195
- DOCKET 70-0824 BABCOCK & WILCOX CO , LYNCHBURG, VA
- 8306140609 Forwards IE Insp Ropt 70-0824/83-03 on 830427-29. No moncompliance noted
 BTCHR.J P Division of Emergency Preparedness & Materials Safety
 83/05/18 ENGELDER.T C Babcock & Wilcox Co 2pp 18834 351.
- ---B306140617 IE Insp Rept 70-0824/83-03 on B30427-29 No noncompliance noted Major areas inspected organization, facility changes & mods, internal review, safety committee operations & criticality safety
 CORYELL, 0 P. Region 2. Office of Director MCALPINE, E. J
 Division of Emergency Preparedness & Materials Safety 83/05/17.
 4pp 18834 353
- 8304220131 Submits info re planned shipments of SNM of moderate strategic significance REGAN,N A Babcock Wilcox Co 83/05/30 O'REILLY,J P. Region 2. Office of Director 2pp. 18937 357
- DOCKET 70-1113 GENERAL ELECTRIC CO. . WILMINGTON, NO
- 8306140122 Ack receipt of IE Insp Rept 70-1113/83-08 on 830307-11 No proprietary info VAUCHAN, C.M. Opneral Electric Co. 83/04/15 STOHR, J.P. Division of Emergency Preparedness & Materials Safety. ip. 18839:100.
- 8306140072 Confirms 830518 enforcement conference at facility to discuss improper shipments of radioactive matl to Cham-Nuclear site at Dernuell, 8C, per 830511 telcon O'REILLYJ P. Region 2. Diffice of Director 83/05/13 LONG, J A General Electric Co. Ip. 18838:341
- 8306140317 Ack receipt of 830507 ltr informing NRC of steps taken to correct violation noted in IE Insp Rept 70-1113/83-04
 8TOHR, J P Division of Emergency Preparedness & Materials Safety, 83/05/26 LONG, J A. General Electric Co ip. 18832,172.
- ---8306140338 Responds to NRC 830411 ltr re violation noted in IE lnsp Rept 70-1113/83-06 Corrective actions internal HMD procedures modified to require surveys during roof scrubber filter changes following unusual incidents VAUGHAN, C M General Electric Co 83/05/09 BTDHR, J. P Division of Emergency Preparedness & Materials Safety 3pp 18832 193
- --8306140342 Forwards IE Insp Rept 70-1113/83-06 on 830307-11 & notice of violation STOHR.J P Division of Emergency Preparedness & Materials Bafety. 83/04/11 LONG,J A General Electric Co. 2pp. 18832:176.
- --8306140348 Natice of violation from insp on 830307-11 * Region 2, Office of Director. 83/04/11 1p 18832:178.
- --B306i403B7 IE Insp Rept 70-ili3/83-06 on 830307-ii Noncompliance noted: failure to perform airborne radioactivity surveys during removal of contaminated high efficiency particulate air filters on 830204
 HOSEY, C M Region 2, Office of Director. BARR.K P Division of Engineering & Radiological Safety Programs 83/04/07. 3pp. 18832 199
- 8305140576 Forwards IE Safeguards Insp Rept 70-1113/83-14 on 830502-06. No noncompliance noted. 8TOHRJ P Division of Emergency Preparedness & Materials Safety. 83/06/01 LONGJJ A General Electric Co 2pp. 18834-357.
- --8306140582 IE Safeguards Insp Rept 70-1113/83-14 on 830502-06 No noncompliance noted Major areas inspected; physical inventory on previous insp findings (MC-85213) Details withheld (ref 100FRZ. 770)
 8ABADOS, J W. Region 2, Office of Director, MCALPINE,E J.
 Division of Emergency Preparedness & Materials Safety. 83/06/01, 1p 18834-359
- 8306i40568 Forwards IE Safeguards Insp Rept 70-1113/83-13 on 830425-29, No noncompilance noted 8TDHR.J P Division of Emergency Preparedness & Materials Safety. 83/06/02 LONG.J A General Electric Co. 2pp. 18834:338

- --8306140575 IE Insp Rept 70-1113/83-13 on 830425-29 No noncompliance noted Major areas inspected verification of export shipment & mpasurement control program Rept details withheld (ref 10CFR2 790)

 BATES: J W Region 2. Defice of Director MCALPINE: E J Division of Emergency Preparedness & Materials Safety 83/06/02 ip 18834 340
- 830.6210444 Submits items of interest re 830.603 meeting w/OE to discuss supplemental info needed for license renewal application & notice of availability of Kerr-McGes /E9 NMSS div meeting notices & info on Canonsburg.PA site enc!
 PAGE.R 0 Uranium Fuel Licensing Branch 83/06/08 DAVIS.J 6
 Office of Nuclear Maturial Safety & Safeguards.Director 3pp 18935-356

DOCKET 70-1143 WESTINGHOUSE ELECTRIC CORP , PITTSBURGH, PA

- B306200221 Forwards IE Insp Rept 70-1143/83-01 on 830325-28 & notice of violation
 STAROBTECKI.R Division of Project & Resident Programs 83/06/06
 JACOBI.W.M Westinghouse Electric Corp 2pp 18702 288
- --8306200222 Notice of violation from insp on 830323-25
 * Region 1, Office of Director 83/06/06 1p 18702 290
- --8306200225 IE Insp Rept 70-1143/83-01 on 830323-25 Noncompliance noted failure to initiate special air investigation repts when three stack air samples exceeded action level ROTH, J. ELSASSER.T C Region 1. Office of Director 83/05/20 Spp. 18902 291
- B306180001 Notification of B30629 significant licenses meeting w/vendor in King of Prosis.PA to discuss status of plant decommissioning activities
 ROTH.J. Region 1, Office of Director 83/06/10 Region 1, Office of Director 10 18845 318

DOCKET 70-1151 WESTINGHOUSE ELECTRIC CORP . PITTSBURGH, PA

- B304040114 Act receipt of 830228 ltr informing NRC of steps taken to correct violations noted in IC Safeguards Insp Rept 70-1151/83-02 STOHR.J P Division of Emergency Preparodness & Materials Bafety B3/04/06 D'AMORE, M Hestinghouse Clectric Corp ip 18728 092
- --8304040118 Responds to NRC 830215 lt; re violation noted in IE Safeguards Insp Rept 70-1151/83-02 Corrective actions withheld (ref FOCFR2 790), D'AMDRE,M Westinghouse Electric Corp 83/02/28 O'RCILLY,J P Region 2, Office of Director 3pp 18728 093
- --8305050124 Forwards IE Safeguards Insp Rept 70-1151/93-02 on 830125-28 & notice of violation Encls withheld (ref 10CFR2 790)
 STOHR, JP Division of Emergency Preparadness & Materials Safety 83/02/15 D'AMORE, M Westinghouse Electric Corp 2pp 19728:095
- 8304080021 Forwards application for renewal of License SNM-1107, for 20-Ur period-authorizing use of SNM at Columbia, SC site NARDI, A. J. Westinghouse Electric Corp. 63/04/29 PAGE, R c Uranium Fuel Licensing Branch 2pp. 18786-001
- ---9306080033 Application for renewal of License SNK-1107, authorizing use of SNM at Columbia. SC site
 * Westinghouse Electric Corp 93/04/30 496pp 18786 003.
- 8306140179 Ack receipt of 830429 application for renowal of License SMM-1107 Existing license will not expire until application for renewal has been determined by Commission PAGE.R.O Uranium Fuel Licensing Branch 83/06/06 NARDI.A J Westinghouse Electric Corp. 1p. 18844-186.
- 8306290433 Forwards IE Safeguards Insp Rept 70-1151/63-10 on 830606-08 No noncompliance noted BTOMR, J. Division of Emergency Preparadness & Materials Bafety 83/04/22 BRITTON, W H Westinghouse Electric Corp 2pp 19049 279
- --B306290436 IE Safaguards Insp Rept 70-1151/B3-10 on 830406-08 No noncompliance noted Hajor areas inspected physical protection of SNM of low strategic significance at fixed site Details withheld (ref IOCFR2 770).

 HALL, B L. Region R, Office of Director HCQUIRE, D R Division of Emergency Preparadness & Materials Safety 83/06/20 [p

DOCKET 70-1201 BABCOCK & WILCOX CO , LYNCHBURG, VA

- 8306140674 Rev I to application for Amend 83-1 to License SNM 1168, allowing receipt of reactor insp equipment for storage & maint Revised & addl pages of license & check for minor amend fee encl
 FORD, JT Babcock & Wilcox Co 83/03/09 PAGE, R G Uranium Fuel Licensing Branch 11pp 18854 004
- 8306200020 Notifies of B3042J accident Truck carrying 45 packages containing law emitched U dioxide powder, 36 empty 55 pallon drums & two boxes of low enriched U lab samples overturned in Lynchburg, VA No radioactive moti released AUSTIN, M A Babcock & Wilcox Co B3/05/19 Office of Nuclear Material Safety & Safeguards, Director Ip 18908 350
- 8306270121 Forwards revised pages to fundamental nuclear matts control plans incorporating personnel reorganization, revised facility layout & Part 4 | 2 clarification Pages withheld (ref 10CFR2 770)
 FORD, J T Babcock Wilcox Co 83/05/23 D'REILLY, J P Region 2, Office of Director ip 18788 063
- 9306140527 Forwards IE Insp Rept 70-1201/83-06 on 930426 No noncompliance noted STOHR.J P Division of Emergency Preparedness & Materials Safrty 83/05/25 ALTD.R A Babcock & Wilcox Co 2pp 18940 190
- --8306140529 IE Insp Rept 70-1201/83-06 on 830426 & 27 No noncompliants noted Major areas inspected organization, facility mods, internal review & audit safety committees & nuclear criticality safety & operations CORVELL. O P Region 2, Office of Director MCALPINE, E J Division of Emergancy Preparedness & Moterials Safety 67/05/24 4pp 18840 182
- 8306030152 Forwards negative declaration & EIA re renewal of license SNM-1168 for continued operation of plant W/o supporting EIA PAGE.R G Uranium Fuel Licensing Branch 83/05/2/ FDRD, J 7 Babcock & Wilcox Co ip 18/33 310
- --8306030179 Negative declaration re renewal of License SNM-1140 for continued operation of plant PAGE.R Q Uranium Fuel Licensing Branch 83/05/25 2pp 18733-311
- 8306020112 ENVIRONMENTAL IMPACT APPRAISAL FOR RENEWAL OF SPECIAL NUCLEAR MATERIAL LICENSE NO SNM-1168 Docket No 70-1201 (Babcock & Wilcox Company Commercial Nuclear Fuel Plant) # Office of Nuclear Material Safety & Safeguards, Director NUREG-0987 83/05/31 141pp Available at NRC \$6.50 18698 271
- BOCKET 70-1207 NAVY, DEPT OF, BILVER SPRING, MD
- 8306160313 Discusses IE Insp Repts 70-1207/83-01.30-08422/83-01 & 30-10712/83-01 on 830412-14 & forwards notice of violation MARTIN.T T Division of Engineering & Technical Programs 83/06/01 FERNANDES, J E Navy. Dept of 3pp 18860 184
- --8306160321 Notice of violation from insp on 830412-14 Noncompliance noted survey meters not calibr at 6-month intervals & refresher training not provided to individuals using licensed matl during CYG1-G3 + Region 1. Office of Director 83/06/01 2pp 18860.187
- DOCKET 70-1224 TELEFLEX, INC , NORTH WALES, PA
- B30602040B Ack request of 830517 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 70-1224/83-01
 MARTIN,T T Division of Engineering & Technical Programs 93/05/31
 ALBDM, I Teleflex, Inc. 1p 18693
- --8304020415 Responds to NRC 830421 ltr re violation noted in If Insp Rept 70-1224/83-01 Corrective actions separate inventory listings will be maintained, plant engineer will post new deliveries & quarterly inventory count will be varified DEAN, J.P. Teleflex, Inc. 83/05/17 MARTIN.T.T. Region 1, Office of Director 2pp 18493 F04

DOCKET 70-1257 EXXON NUCLEAR CO : INC : RICHLAND, WA

- 8306130493 Advises that fee not received for 830103 application to amend License SNM-1227 for const & operation of chemical process waste treatment facilities
 WEISS, D. License Fee Management Branch 83/02/28 MALODY, C. W. Eison Nuclear Co., Inc. (subs. of Exxon Corp.) jp 18830-271
- ~-8306130500 Application to amend License SNM-1227 providing for const & operation of chemical process waste treatment facilities Hinor amend fee encl
 MALODY.C W Exxon Nuclear Co , Inc (subs of Exxon Corp)
 83701703 CROW.W T Uranium Fuel Licensing Branch 6pp
 180730 272
- 8306240396 Application to amend License ENM-1227, allowing const & operation of solids holding & leaching basin & permitting cleanout of solids from lagoons MALODY, C W Exxon Nuclear Co . Inc (subs of Exxon Corp) 83/05/04 CROW, W T Division of Fuel Cyclo & Material Safety Bpp
- 8306190332 Issues Amend 10 to Exxon Nuclear Co.Inc license.authorizing const & operation of solids bacin SER enc.) PAGE.R 0 Uranium Fuel Licensing Branch 83/06/07 MALODY,C W Esxon Nuclear Co., Inc. (subs. of Exxon Corp.) ip 18870 007
- 10870 008
- 8304200404 Forwards IE Safeguards Insp Rept 70-1257/83-03 on 830523-27 No mancompliance noted NGNDERHAUG,L R Region 5, Office of Director 83/06/15 Esson Nuclear Co , Inc (subs of Exxon Corp) 2pp 18 18719 220
- --830&200410 IE Safeguards Insp Rept 70-1257/83-03 on 630523-27 No noncompliance noted Major areas inspected facility organization & operations & shipper-receiver verification Details withheld (ref 10CFRP 790)
 NELSON.0 B , WIEBER.A V , NDRDERHAUO, L R Region 5, Office of Director 83/06/15 ip 18919 222

DOCKET 70 130B GENERAL ELECTRIC CO., SAN JOSE, CA.

- 83/05/13
- 8305240484 Supposts withdrawal of rev to 9A Plan NEDO-20776, for further editing before resubmission Response by 830708 requested ROBERTS, J.P. Advanced Fuel & Spent Fuel Licensing Branch 8: Advanced Fuel & Spent Fuel Licensing Branch 83/04/20 General Electric Co 1p 18978 047

DECKET 70-1402 ABINGTON MEMORIAL HOSP. , ABINGTON, PA

DAMSON, D.M.

- B304280429 Ack receipt of 830517 ltr informing NRC of steps taken to correct violations noted in IC Insp Repts 30-02948/83-01, 30-06453/83-01 & 70-1402/83-01 on 830315 HARTIN I T Division of Engineering & Tochnical Programs 83/06/16 CANDIA. 6 Abington Memorial Hosp Abington, PA ip 19020 324
- --- 8306280433 Responds to NRC 830421 ltr re violations noted in IE Insp Repta 30-02948/83-01,30-00459/83-01 & 70-1402/83-01 on 830315 Corrective actions 3-month interval calibr check of survey meters reinitiated CANDIA.C R. Abington Momorial Hosp Abington.PA 83/05/1 MARTIM.T.T. Division of Engineering & Technical Programs

DOCKET 70-1549 NUCLEAR FUEL SERVICES, INC. , ERWIN, TN

8306170024 Notifies of 830517-20 meetings w/vendor at Erwin, TN re NOBITION OF COURSE BY BOOK TO BE STORE WITH THE COURSE WITH THE COURSE BY THE BY THE COURSE BY THE B 83/05/24 10

DOCKET 70-1739 TRI-STATE MOTOR TRANSIT CO . JOPLIN, MO

- 8306200115 Forwards route overview depicting planned check call frequency for forthcoming shipment. W/o encl RUTENKROGER.E Tri-Beate Motor Transit Co NRC No Detailed Affiliation Given 2pp 18908 236
- DOCKET 70-1764 NUCLEAR FUEL SERVICES, INC , ERWIN, TN
- 8306170024 Notifies of 830517-20 meetings w/vendor at Erwin, TN re safeguards program & other classified, proprietary & safeguards info GUNDERSEN, G Fue) Facility Safeguards Licensing Branch BRGUN, W B Fuel Facility Safeguards Licensing Branch
- DOCKET 70-2075 PACIFIC QAS & ELECTRIC CD . SAN FRANCISCO, CA
- 830424039B Application to renew License SNM-1667, extending expiration data to 840630 SCH-VYLER, J O Pacific Gas & Electric Co 83/05/11 PAGE, R. Q Uranium Fuel Licensing Branch ip 18997 354
- 8306290682 Amend 9 to License SNM-1667, extending expiration data to 840630 or upon conversion of CPPR-69 to 0L PAGE.R 9 Uranium Fuel Licensing Branch 83/06/16 SCHIYLER, J 0 Pacific Gas & Electric Co 1p 19047 102
- --8306270687 SER supporting Amend 9 to License SMM-1667 BIDINDER.C H . CROW.W T Uranium Fuel Licensing Branch 83/06/16 ip 19047 103

DOCKET 70-2548 DOVER GENERAL HOSP , DOVER, NJ

- 8304020399 Ack receipt of 830830 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 70-2548/82-01, 30-00374/82-01 & 30-02574/82-01.

 MARTIN.T T Division of Engineering & Technical Programs 83/05/3 LGYELL.R Dover General Hosp Dover.NJ ip 18695-013 83/05/31,
- --8306020405 Responds to NRC 830324 ltr re violations noted in IE Insp Repts 70-2548/82-01.30-00374/82-01 & 30-02576/82-01 Exhibits A.B.C & D re Co-60 teletherapy forwarded LOVELLAR M Dover General Hosp DoverNJ 83/03/30 MARTIN.T T. Division of Engineering & Technical Programs 16pp 18675 014

DOCKET 70-2669 ROBERT PACKER HOSP , BAYRE, PA

- 8306150156 Ack receipt of 830418 ltr informing NRC of steps taken to correct violations noted in 16 insp of License SNM-1758 License should be retired MARTIN.T T Division of Engineering & Technical Programs 83/06/0 MORRISON.G B Robert Packer Hosp Sayre.PA ip 18846 001. 83/06/09.
- --8306150163 Informs that License SNM-1758 expired on 820831 No renewal application received Licensee never received or possessed licensed mati Termination requested per 830418 ltm KINNEMAN.J D. Region j. Office of Director 83/06/08, WALKER.L E. Material Control Licensing Branch. ip. 18846:002
- ---8306150166 Responds to NRC 830331 ltr re License SNM-1758 No matis procured or expected under license. Cancellation of license hetzennes requested MORRIGON,0 B Robert Packer Hosp Bayre,PA 83/04/18 1, Offlice of Director 1p 18846 003
- --8306150169 Certificate of disposition of matts:no matts procured by licenses under License BNM-1758 MORRISON, G. B. Robert Packet Hosp Soure, PA 83/04/18 ip. 18846 604
- DUCKET 70-2038 CINCINNATI GAS & ELECTRIC CO . CINCINNATI, OH
- 8306080393 Issues Amend 8 to License SNM-1823.extending expiration Association of the Literner SNN-1823 extending expiration date to 850731 or upon conversion of CPPR-88 to OL PAGE.R G Uranium Fuel Licensing Branch 83/05/31. FLYNN, J D Cincinnati Gas & Electric Co Ip. 18792 174
- --8306080396 Safety evaluation supporting Amend 8 to License SNM-1823 81DINGER, G H , CROW, W T Uranium Fuel Licensing Branch 83/05/3 1p. 18792 175.

DOCKET 70-2850 WEBER STATE COLLEGE, OGDEN, UT

8306090065 Submits notice of violation re expiration of License SNM-IB19 Discusses actions to be taken by licensee Radioactive matl must be placed in secure storage until valid license issued BROWN,0 D Region 4. Office of Director 83/06/03 TRIPP,D Weber State College 2pp 18793 208

DOCKET 70-2892 AUXILID MUTD HOSP . HATO REY, PR

830.6020312 Application for renewal of License SNM-1820, revising expiration date to 830731 or upon conversion of CPPR-88 to OL...... CLYNN.J D Cincinnati Gas & Electric Co 83/02/12 PAGE, R O Division of Fuel Cycle & Material Safoty 1p. 18715 280

DOCKET 70-2910 TENNESSEE VALLEY AUTHORITY, CHATTANODGA, TN

8306030504 Application for extension of License SNM-1841 to 840331 due to const delays
MILLS.L M Tennessee Valley Authority 83/05/02 CROW.W T MILLS.L M. Tempessee Valley Authority 83/05/02 CROW. Division of Fuel Cycle & Material Safety 1p. 18735 002 CROW, W T

8306080032 Informs that License SNM-1861 has been amended, extending expiration date to 840331 or upon conversion of CPPR-91 to OL SER encl
PAGE.R G Uranium Fuel Licensing Branch 83/06/01. MILLS.L M

. Uranium Fuel Licensing Branch /alley Authority | Jp 10797 305 PAGEIR & Oranium Foot Electron Tennessee Valley Authority Ip

--8306080086 Recommends approval of 830502 application to amond License SNM-1861 extending expiration until 840331 or upon conversion of CPPR-91 to OL.
BIDINOER, O H. CROW, P. T. Uranium Fuel Licensing Branch 83/06/01
Uranium Fuel Licensing Branch 1p 18/97 307.

8306090255 Issues Amend 5 to License SNM-186), changing expiration date to 840331 or upon conversion of CPPR-91 to OL PAGE.R G Uranium Fuel Licensing Branch 83/06/01. MILLS, L N Tennessee Valley Authority ip 18797 043

--8306090259 Bafety evaluation supporting 830502 amend application to extend license expiration data to 840331 due to const delaus PAGE R G Uranium Fuel Licensing Branch 83/06/01 ip 18797:044

DOCKEY 70-2924 DETROIT EDISON CO , DETROIT, MI

8305090022 Unexecuted Amend 25 to Indemnity Agreement B-20.deleting Items 3 & 4 re license numbers & location.respectively BALTIMAN.J. Assistant Director for State & Licensee Relations 83/05/31 ip 18797.351 24X Fiche 50-016.83/05/31.8306090022

8306070039 Unexecuted Amend 24 to Indemnity Agreement B-20, adding Wolverine Power Bupaly Cooperative as licensee BALTEMAN J Assistant Director for State & Licensee Relations 83/05/31. ip 18797 360 24X Fiche. 50-016, 83/05/31, 8306070039

8306090265 Forwards Matls License BNM-1915 authorizing receipt, possession, insp & storage of enriched U-225, contained in fuel assemblies, for eventual use at Enrice Fermi, Unit 2 Indemnity Agreement B-20 & SER also encl. PAGE.R O. Uranium Fuel Licensing Branch. 83/05/31 TAUDER, H Detroit Edison Ca 2pp 18810 049

~~8306090269 Matls License SNM-1915 authorizing receipt, possession, insp & storage of enriched U-235 contained in fuel assemblies for use at Enrico Fermi, Unit 2 PAGE.R.O Uranium Fuel Licensing Branch. 83/05/31 3pp 18810:051

--8304090274 Befety evaluation supporting issuance of Matls Licenso SNM-1915 re 821109 application for storage of enriched fuel assumbles at Enrico Fermi.Unit 2 SERINI.B L Uranium Fuel Licensing Branch. 83/05/31. 13pp. 18810:054

929 ARMY, DEPT. OF, FT MCCLELLAN, AL

R Insp Findings & Licensee Ack dtd 830407 of License nsp findings no violations observed 2, Office of Director. 83/04/07, ip 18839.070

DOCKET 70-2945 UNION ELECTRIC CO . ST 10018, MG

8306010110 Application to amend License SNM-1901 permitting restricted use of cranes in proximity of fuel hidg Cranes, when not in use will be placed in safe configuration SCHNECL, D. F. Union Electric Co. 83/05/16 KEPPLER, J. G. Region 3, 83/05/16 KEPPLER. J O Region 3. Office of Director 5 թ թ 10606 343

B304290585 Notifies that either operating supervisor or shift supervisor will verify trolley placement & replacement of crane stops during & after use of cask handling crane over spent fuel pooliper B30516 ltr
SCHNELL, D.F. Union Electric Co. 83/06/17 DAVIS, J.G. Office of MacLand Material Safety & Safenuards, Director. 200 197822 021 Nuclear Material Safety & Safeguards, Director 2pp 19222 021

DOCKET 70-2947 ILL INDIS POWER & LIGHT CO , DECATOR, IL

6304020203 Application to renew License CNM-1886, extending license to 840831 or upon conversion of CPPR-137 to OL Amend authorizing prossession of two neutron callor stds consisting of may of 20 Ci Pu-238 requested WULLER, G E Illinois Power Co 83/04/25 CUNNINGHAM, R E Division of Fuel Cycle & Material Safety 2pp 18701 042

DOCKET 70-2950 WASHINGTON PUBLIC POWER SUPPLY SYSTEM, RICHLAND, WA

8306080026 Application to amend License CNM-1890, changing present curis limit from 1,200 C1/source to 3,000 C1/source BDUCHEY, O D Washington Public Power Supply System 83/04/15 Office of Nuclear Material Safety & Safequards, Director 1p 18787 312

8306240337 Application for amend to License SNM-1870 increasing possession limit to 3,000 Ci/source BUCHEY,0 D Mashington Public Power Bupply System 83/04/15 Office of Nuclear Material Safety & Safeguards Director Spp

8306240460 Application for smend to License SNM-1890, deleting ref to warehouse storage BOUCHEY, O D Washington Public Power Supply System 03/0 Office of Nuclear Material Safety & Safeguards, Director 18998 108

DOCKET 70-2953 CONNECTICUT, UNIV OF, STORRS, CT

8304020025 Ack reteipt of 830503 ltr informing NRC of steps taken to correct violations noted in IF Insp Repts 30-10576/83-01, 30-11727/83-01 & 70-2959/83-01

HARTIN, T T Division of Engineering & Technical Programs 83/05/18 VAN GELDER, A Connecticut, Univ of 1p 18702 333

--8306020032 Responds to NRC 830411 ltr re violations noted in IF Insp Repts 30-10576/83-01,30-11727/83-01 & 70-2953/83-01 Corrective actions room locked, proper posting maintained & updated Form NRC-3 posted HARBHAM.F. Connecticut, Univ of 83/05/03 MARTIN.T F Division of Engineering & Jechnical Programs 2pp 18702-334

DOCKET 70-2968 CLEVELAND ELECTRIC ILLUMINATING CO , CLEVELAND, (M

8306240344 Amend 2 to application for SNM license, changing requested effective date of license to 840810 EDELMAN.M R Cleveland Electric Illuminating Co. 83/05/27 DAVIS.J Q Office of Nuclear Material Safety & Safeguards, Director 18999 171

DOCKET 70-2982 ROCHESTER, UNIV OF, ROCHESTER, NY

8304030494 Application for license authorizing possession only of 455 \$ U hexafluoride stored in metal cylinder for use in animal inhalation experiments OREGORY.W D. Rochester, Univ of 83/04/28 COUL.D. A Office of Nuclear Material Bafety & Safeguards, Director 2pp 18735 275

DOCKET 70-2984 ARIZONA PUBLIC SERVICE CO . PHOENIX, AZ

8306070432 Application for SNM license, authorizing storage of unirradiated reactor fuel & associated radioactive mat) Supporting documentation encl ANDOOMINI, G C Arizona Public Service Co 83/04/26 Off Nuclear Material Bafety & Safeguards, Director 15ipp 187 Office of 19775 192

DOCKET 70~2985 DUKE POWER CO , CHARLOTTE, NC

B30602063B Forwards application for SNM license
TUCKER: H D Duke Power Co B3/05/17 DAVIS, J G Office of N
Material Safety & Safeguards, Director PAGE, R G Uranium Fuel
Licensing Branch 2pp 18716 304 Office of Nuclear

--8306020646 Application for SNN license, authorizing receipt, possession, insp. use & storage of U enriched in U-23b isotope, contained in fuel assemblies & in fission chambers. Pu-23B contained in Pc/Be neutron source & Pc/23P alpha source * Duke Power Co 83/05/17 24pp 18714 306

PACKAGING OF RADIOACTIVE MATERIAL FOR TRANSPORT AND TRANSPORTATION OF RADIOACTIVE MATERIAL UNDER CERTAIN CONDITIONS

DOCKET 71-0002 ATOOR ENGINEERED SYSTEMS, INC

8304070030 Forwards IE Insp Rept 71-0002/63-61 on 830427 of activities associated u/periodic maint of transport packages No distolates by provided an arcompliance noted an arcompliance noted HARTIN.1 T Division of Engineering & Technical Programs 63/08/25 BROWNSTEIN.M AICOR 2pp 18792 350

--830409D034 IE Insp Rept 71-0002/83-41 on 830427 No noncompliance noted Hajor areas inspected periodic maint of transport patkages, including QA manual & interviews w/personnel CLCMDNS, P., SHANBAKY,M. Region 1. Office of Director 83/05/24 Rep. 18/92 360

830&230473 Clarifies IE Insp Rept 71-0002/83-61 transmitted by 830525 Itr re maint activities for transport packages at alternate facility MARTIN T 1 Division of Engineering & Technical Programs 83/06/20 BROWNSTEIN.M ATCOR 1p 18941 301

DOCKET 71-0084 ALPHA-OMEGA SERVICES, INC.

B306160649 Forwards "QA Plan for Shipping Parkages," for approval Plan is not rev SOUTHERN,R L. Alpha-Omega Services, Inc. 83/05/25 GORDON,L Transportation Dranch 2pp 18884 250

~~8365160652 "GA Plan for Shipping Packages" * Alpha-Omega Services, Inc. 63/05/25 30pp 18884 252

9306240400 Forwards GA program approval for Radioactive Matl Package DOBA, Rev. I OCHA, Rev 1 HACDENALD, C E Transportation Branch 83 Alpha-Omega Services, Inc. 16 18997 361 83706716 SOUTHERN, R L

--8306240469 @A Program approval for Radioactive Matl Package 0086.Rev 1 MACDUNALD.C & Transportation Branch 83/06/16 lp 18997.362

DOCKET 71-0210 QUIF NUCLEAR, INC.

8306060394 GA program for Gulf Nuclear. Inc W/830504 ltr HCPCRAFT.C P Gulf Nuclear, Inc 83/03/01 MACDONAL Transportation Branch 36pp 18750 216 MACDONALD, C E

8306220203 Requests addl info re 830504 application for approval of 10820203 Requests and into re 33304 application for approved revised QA program applicable to design, fabrication & use of packaging containing special form radioactive math W/o encl Reg Guide 7 10
MACDONALD.C E Transportation Branch 83/06/13 HOPCRAFT.C P Guif Nuclear, Inc. 2pp 18751 034

DOCKET 71 0250 TRANSNUCLEAR, INC.

B304020258 Forwards IE Insp Repts 71-0250/83-61 on 830426 No noncompliance noted MARTIN, T Division of Engineering & Technical Programs 83/05/20 MACKLIN, L Transnuclear, Inc. 2pp 18690-275

--8306020364 IE Insp Rept 71-0250/83-61 on 830426 No noncompliance noted Major areas inspected periodic maint of transport packages, including GA manual.procedures & personnel interviews CLEMONS.P., SHANBAKY.M Region 1. Office of Director 83/05/18 2pp 18690 277

DOCKET 71-0302 ASSOCIATED PIPING & ENGINEERING CORP.

8306020585 Forwards.for approval.GA for Radioactive Matl Package 0302 Rev O Requests registration as user of Model 6717-8 M/o 20025,K C Associated Piping & Engineering Corp (subs of Johnson Controls, Inc.) 83/05/19 MACDONALD,C E Transportation Branch 1p 18715-061

DOCKET 71-0367 NAVY, DEPT OF

B306220231 Responds to B30503 request for rev to GA Program approval for Certificate of Compliance O367 to include SNAP-23A radioisotope thermoelectric generator (RTO) GA program administrative & mgt controls applicable to all RTGs MACDONALD.C E. Transportation Branch B3/06/13 SHDEMAKER.B Navy. Dept of 1p 18977 352

DOCKET 71-0498 GEARHART-OWEN INDUSTRIES

6306220172 Forwards GA program approval for Radioactive Matl Package 0498, Rev O 0448.Rev U MACDONALD.C E Transportation Branch 83/06/1: Gearheart-Owen Industries, Inc. 1p. 18937-279 63/04/13 KOEHLIK M

--8306220178 GA program approval for Radioactive Matl Package 0498. MACDONALD.C E Transportation Branch 83/04/13 ip 18937 280

DOCKET 71-4909 MODEL GE 21PF-1, GENERAL ELECTRIC CO

8304080341 Discusses proposed design fixes for U hexafluoride 30-inch diameter overpacks to correct water leakage problem Fixes include mods to existing overpacks & to current DDT Spec 21FF-1 M/three oversize drawings Aperture cards are in PDR PRICHARD.R P Transportation, Dept of 83/05/12 ROBERTS, A I Transportation, Dept of 15pp 18770 250

--8306080948 "U Hexafluoride Product Cylinder - Overpack Insulation FRAZIER, J L Union Carbide Corp M-7405 K/TL/88-88 83/02/2 FRAZIER, J L Union Carbide Corp 11pp 18790 266

--8306080358 Rev 1 to "BAR for Modified U Hexafluoride Cylinder Shipping Package.DDT Spec 21 PF-1 " * Union Carbide Corp K/D-5400 RO1 83/03/30 17pp 18790 277

8306020473 Notification of registration as user of Model GE-2JPF-1 in rasponse to 830310 request MACDONALD, C.E. Transportation Branch. 83/05/25 TAYLOR, J.C. Union Carbide Corp. Ip 18715-194

830 6080327 Forwards three oversize revised drawings, including one proprietary, in response to NRC 830224 request for add1 info re 830117 request for amend to Cortificate of Compliance 4909. Aperture cards in PDR & Central Files NARDIA J Westinghouse Electric Corp 83/05/31, NACDONALD.C.E Transportation Branch 1p. 18791 217

8304220195 Forwards request for add) info re 830117 & 0531 application & suppl for approval of Model W-21PF-1 packaging Info should be submitted as revised pages MACDONALD, CE Transportation Branch 83/04/14 NARDI, A J Westinghouse Electric Corp. 2pp 18951 043

DOCKET 71-49A0 NODEL LLD-1, ENERGY, DEPT. OF

830.6200.022 Bubmits lists of BAR packages for which DDE no longer intends to pursue certificates of compliance Also lists BARPs for which DDE intends to pursue issuance of certificates of compliance PRICHARD: R.P. Energy, Dept. of. 83/05/31 MACDDNALD: C Diviof Fuel Cycle & Material Safety. 2pp 18908 352 /31 MACDDNALD,C Division 18908 352

DOCKET 71-5026 MODEL: CNS 14-190, CHEM-NUCLEAR SYSTEMS, INC.

8305090014 Forwards Rev 7 to Certificate of Compliance 5025 for Model CNS 14-190 CMB 14-170 MACDONALD,C E. Transportation Branch. 83/ Chem-Nuclear Bystems: Inc. 3pp 18798:001 83/05/31 DEAL, R

---8304090017 Certificate of Compliance 5026.Rev 7.for Model CNB 14-190 MACDDNALD.C.E Transportation Branch 63/05/31 4pp 18798 004.

DOCKET 71-5097 MODEL 44. ENERGY, DEPT OF

8306200022 Submits lists of SAR packages for which DDE no longer intends to pursue certificates of compliance Also lists SARPs for which DDE intends to pursue issuance of certificates of compliance PRICHARD, R P Energy, Dept of 93/05/31 MACDDNALD, C Division of Fuel Cycle & Material Safety 2pp 18708-352

DOCKET 71-5170 MODEL STEEL INGOT SKID & BOX 37, ENERGY, DEPT OF

8306200022 Submits lists of SAR packages for which DOE no longer intends to pursue certificates of compliance Also lists SARPs for which DOE intends to pursue issuance of certificates of compliance PRICHARD, R P Energy, Dept of 83/05/31 MACDONALD, C Division of Fuel Cycle & Material Safety 2pp 18908 352

DOCKET 71-5364 MODEL WPI-67-0442, NEUTRON PRODUCTS, INC.

8304020488 Notification of registration as user of Models DT-148 & NPI-67-0442 in response to 830218 & 0322 requests MACDONALD, C E Transportation Branch. 83/05/25 ANSELMO, A A EQ&6, Inc. 1p 18715-200

8306240341 Informs of inadvertent overloading of shipping cask under Certificate of Compliance 5364 On 830222,407,300 Ci shipped in container licensed for 400,000 Ci Caused by miscalculations of generation rate of first Co-60 targets 8MEDIRA: C Neutron Products. Inc 83/06/03 MACDONALD.C E Transportation Branch 2pp 18999:233

DOCKET 71-5450 MODEL RCC. -1. -2. -3. -4. WESTINGHOUSE ELECTRIC CORP

8308290861 Forwards listing of applicable shipping packages for continued registration as user Encl also identifies packages to be removed from user list STEMART. W.L. Virginia Electric & Power Co. 83/06/06 MACDONALD.C E. Transportation Branch. App. 19047 181

DOCKET 71-5467 MODEL MARK VR. VE & MARK 15, ENERGY, DEPT OF

8306200022 Submits lists of SAR packages for which DDE no longer intends to pursue certificates of compliance. Also lists SARPs for which DDE intends to pursue issuance of cartificates of compliance PRICHARD.R P Energy, Dept of 83/05/31 MACDONALD.C Division of Fuel Cycle & Material Safety 2pp 16908 352

DOCKET 71-5449 MODEL HNPF SPENT FUEL SHIPPING CASK, ENERGY, MEPT OF

8306200022 Bubmits lists of SAR packages for which DDE no longer intends to pursue certificates of campliance Also lists SARPs for which DDE intends to pursue issuance of certificates of compliance priceducing the property of B3/05/31 MACDONALD.C Division of Fuel Cycle & Material Safety 2pp 18908 352.

DOCKET 71-5507 MODEL HEIR SPENT FUEL ELEMENT SHIPPING CASK, ENERGY,

8306200022 Submits lists of SAR packages for which DDE no longer intends to pursue certificates of compliance Also lists SARPs for which DDE intends to pursue issuance of certificates of compliance PRICHARD.R.P Energy. Dept of 83/05/31 MACDONALD.C Division of Fuel Cycle & Material Safety 2pp 18708:352

DOCKET 71-5552 MODEL GAS CYLINDER FIRE IMPACT SHIELD, ENERGY, DEPT.

830&200022 Bubmits lists of SAR packages for which DDE no longer intends to pursue certificates of compliance Also lists 8APPs for which DDE intends to pursue issuance of certificates of compliance.
PRICHARD,R.P Energy, Dept of. 83/05/31 MACDONALD,C Division & Material Safety. 2pp 18708 352

DOCKET 71-5595 MODEL L&M ORNL URANIUM SHIELDED CASK, ENERGY, DEPT OF

8306200022 Submits lists of BAK packages for which DUE no longer intends to pursue certificates of compliance Also lists SARPs for which DUE intends to pursue issuance of certificates of compliance prickarBi.RP Energy, Dept of 83/05/31 MACDONALD.C Division of Fuel Cycle & Material Safety 2pp 18908 352

8306240033 Advises that questions re structural integrity of Model L casks resolved by replacing stainless steel closure bolts w/ASIC 4340 quenched & tempored steel bolts Questions re containment & testing resolved w/issuance of revised SARP TRAVIS.W H Energy, Dept of 83/06/10 MACDONALD.C E Transportation Branch 2pp (8987-23)

--8306240044 Certificate of Compliance 5575, Rev 4, for Models L & M TRAVIS, W H Energy, Dept of 83796/10 46pp 18987 239

DOCKET 71-5597 MODEL TUNGSTEN SHIELDED CASK, ENERGY, DEPT OF

8306200022 Submits lists of SAR packages for which DOF no longer intends to pursue certificates of compliance Also lists SARPs for which DOF intends to pursue issuance of certificates of compliance PRICHARD, R P Energy, Dept of 83/05/31 MACDONALD, C Division of Fuel Cycle & Material Safety 2pp 18708 352

DOCKET 71-5607 MODEL T-2, ENERGY, DEPT OF

8306290610 Notifies that registration for Model GE T-2 still valid in response to 830902 ltr Registration for Model HFIR not get issued by NRC MACDONALD.C E Transportation Branch 83/06/21 DEIGL, H J Teras A&M Univ , College Station, 1X Ip 17047 082

DOCKET 71-5608 MODEL BR 63 0101, ENERGY, DEPT OF

B304200022 Submits lists of BAR packages for which DDE no longer intends to pursue certificates of compliance Also lists SARPs for which DDE intends to pursue issuance of certificates of compliance PRICHARD, R P Energy, Dept of 83/05/31 MACDONALD, C Division of Feel Cycle & Material Safety 2pp 18908 352

DOCKET 71-5641 MODEL UNC-2500, UNITED NUCLEAR CORP

8306080022 Application to amend Certificate of Compliance 5641 incorporating listed changes re stated dry & wet safe quantities per Amend 19 KIRK.W F United Nuclear Corp 83/04/25 MACDONALD.C E Transportation Branch 2pp 18787 317

B306140790 Forwards request for addl info re B30425 application for amend to Model UNC-2500 packaging contents Response schedule requested within 30 days MACDDNALD.C E Transportation Branch 83/05/31 KJRK,WF United Nuclear Corp 2pp 18845 325

8306170447 Forwards request for add1 info re 830425 supplemented application for amend to Model UNC-2500 Response schedule requested within 30 days MACDONALD.C E Transportation Branch 83/06/08 KIRK.W f United Nuclear Corp 2pp 18907 326

DOCKET 71-5645 MODEL AL-L 8, ENERGY, DEPT DF

830A200022 Submits lists of SAR packages for which DDE no longer intends to pursue certificates of compliance Also lists SARPs for which DDE intends to pursue issuance of certificates of compliance PRICHARD.R P Energy, Dept of 83/05/31 MACDONALD.C Division of Fuel Cycle & Material Safety 2pp 18908 352

DOCKET 71-5753 MODEL ORNL LOOP TRANSPORT CASK, ENERGY, DEPT OF

8306200022 Submits lists of SAR packages for which DOE no longer intends to pursue certificates of compliance Also lists SARPs for which DOE intends to pursue issuance of certificates of compliance PRICHARD, R P Energy, Dept of 83/05/31 MACDONALD, C Division of Fuel Cycle & Material Safety 2pp 16908 352

DOCKET 71-5795 NODEL NONE, ENERGY, DEPT OF

830.6200022 Submits lists of BAR packages for which DDE no longer Intends to pursue certificates of compliance Also lists SARPs for which DDE intends to pursue issuance of certificates of compliance PRICHARD, R P Energy, Dept of 83/05/31 MACDONALD, C Division of Fuel Cycle & Material Safety 2pp 18908-352

DOCKET 71-5796 MDDEL 181375, 181361, ADVANCED MEDICAL SYSTEMS, INC.

839602046B Forwards Change 3, consisting of revised pages & drawings, to Certificate of Compliance 57% showing four bolts on each side of tie down assembly bolt into machine irradiator head, in response to 821229 & B30225 ltrs
[RMIN.H R ATC Medical Technology, Inc B3/05/03 MACDONALD.C C Transportation Branch 24pp 18715 210

8306210445 Requests revised analysis showing internal support sys capable of withstanding 30 ft corner drop per 821101 application for amend to Model 181375 packaging MACLOMALD.C E Transportation Branch 83/06/15 IRWIN.H R Advanced Medical Systems. Inc. ip 18735-355

DOCKET 71-5020 MODEL TREAT, ENTROY, DEPT OF

8304220184 Forwards Rev 2 to Certificate of Compliance 5828 Ppr Model TREAT MACDONALD, C E Transportation Branch 83/06/09 BARRACLAUGH, E Energy, Dept of ip 18977 334

--8306820190 Certificate of Compliance 5828, Rev 2, for Model TREAT Approval record encl MACDONALD. C E Transportation Branch 83/06/09 3pp 18977-335

DOCKET 71-5885 MODEL AL-L 11, ENERGY, DEPT OF

8306200022 Submits lists of BAR packages for which DGE no longer intends to pursue certificates of compliance Also lists SARPs for which DGE intends to pursue issuance of cartificates of compliance PRICHARD, R P Energy, Dept of 83/05/31 MACDONALD, C Division of Fuel Cycle & Material Safety 2pp 18908 352

DOCKET 71-5907 MODEL ORNL IN PILE CAPBULE, ENERGY, DEPT OF

8306200022 Submits lists of SAR packages for which DOE no longer intends to pursue certificates of compliance Also lists SARPs for which DOE intends to pursue issuance of certificates of compliance FRICHARD.R P Energy, Dept of 83/05/31 MACDONALD.C Division of fuel Cycle & Material Bafety 2pp 18708 352

DOCKET 71-5957 MODEL BMI-1, BATTELLE COLUMBUS LABORATORY

B30403045 Requests registration as user of Model BHI DEIGL.H J Texas AMM Univ. College Station. TX B3/05/13 HACDDMALD.C E Transportation Branch ip 18733 190

DOCKET 71-5971 MODEL 0E-200, CENERAL ELECTRIC CO

830603029 Requests registration as user of Model OC-200 MILLER, R I Sacramento Municipal Utility District 83/05/08 MACDONALD, C E Transportation Branch ip 19733 172

DOCKET 71-6003 NODEL M-130, ENERGY, DEPT OF

E30&03087 Forwards Rev 4 to Certificate of Compliance 6003 for Model M-130 MACDONALD.C.E Transportation Branch 83/05/25 ENGEL.W.P Energy. Dept of 1p 18/33 273

--8305030090 Certificate of Compliance 5003, Rev 4, for Model M-130. MACDDNALD,C E Transportation Branch 83/05/25 App 18733 274. 8305140787 Forwards request for add1 info re 810911 application for amend to Cortificate of Compliance 6003 to include light water breeder reactor seed modules in Model M-130 Add1 info should be submitted in form of revised pages MACDDNALD, C E Transportation Branch 83/05/27. ENGEL, W P Energy, Dept of 209 18845 329

DOCKET 71-6088 MODEL D-38, DAK RIDGE NATIONAL LAB

8306200022 Submits lists of SAR packages for which DOE no longer intends to pursue certificates of compliance Also lists SARPs for which DDE intends to pursue issuance of certificates of compliance PRICHARD, R P Energy, Dept of 83/05/31 MACDONALD, C Division of Fuel Cycle & Material Bafety 2pp 18708 352

DOCKET 71-6104 MODEL: ANL-390-SPM: ENERGY: DEPT OF

B306200022 Submits lists of SAR packages for which DUE no longer intends to pursue certificates of compliance Also lists SARPs for which DUE intends to pursue issuance of certificates of compliance PRICHARD, R P Energy, Dept of 83/05/31. MACDONALD, C. Division of Fuel Cycle & Material Safety 2pp 18908 352

DOCKET 71-6115 MODEL R1010-0032, ENERGY, DEPT OF

8306200022 Bubmits lists of BAR packages for which DDE no longer intends to pursue certificates of compliance Also lists SARPs for which DDE intends to pursue issuance of certificates of compliance.

PRICHARD, R P Energy. Dept of B3/05/31 MACDONALD, C Division of Fuel Cycle & Material Safety 2pp 18708 352

DOCKET 71-8142 MODEL BETTIS WASTE, ENERGY, DEPT. OF

B306030022 Forwards Rev 1 to Certificate of Compliance 6142 for Model B-2 MACDDNALD, C E Transportation Branch 83/05/25 ENGEL, H F Energy, Dept of ip 18733 168

--8306030027 Certificate of Compliance 6142.Rev 1.for Model Dettis Disposable Waste MACDONALD.C C Transportation Branch 63/05/25 3pp. 18733 169

DOCKET 71-6944 MODEL 6844, CHEM-NACLEAR BYBTEMS, INC

8306090070 Forwards Rev 4 to Certificate of Compliance 6244 for Model 6244 MACDONALD.C E Transportation Branch 83/05/31. DEAL.R Chem-Nuclear Systems, Inc. 3pp 18797 351

--8306090074 Certificate of Compliance 6244, Rev 4 for Model 6244 MACDONALD, C E Transportation Branch 83/05/31. 4pp 18797 354

DOCKET 71-6272 MODEL 6272, U 8 ECOLOGY

8306200022 Submits lists of SAR packages for which DDE no langer intends to pursue certificates of compliance Also lists SARPs for which DDE intends to pursue issuance at certificates of compliance PRICHARD, RP Energy, Dept of 83/05/31 MACDDNALD.C Division of Fuel Cycle & Material Safety. 2pp 18708 352

DOCKET 71-6345 MODEL ANL-402-BPM & 403-BPM, E I DU PONT DE NEMOURB

8306@00022 Submits lists of BAR packages for which DDE no longer intends to pursue certificates of compliance. Also lists SARPs for which DDE intends to pursue issuance of certificates of compliance PRICHARD, R P Energy, Dept of 83/05/31 MACDONALD, C Division of Fuel Cycle & Material Safety 2pp 18708:352

DOCKET 71-6346 MODEL FSV-1. GENERAL ATOMIC CO

- 8306210408 Application for amend to Certificate of Compliance 6546 to allow use of lead shielded pig within generic burinl liners used w/FSV-i cask,per IOCFR7: & IE Notice 83-10 GADR 55 safety analysis suppl.Addendum III & fee encl MCHRY.W R GA Technologies. Inc /General Atomic Co 83/05/18 MACDENALD.C E Division of Fuel Cycle & Material Safety 4pp
- ~~8306210415 "Consolidated Design Rept for Fort St Vrain Fuel Shipping Cask," GABR-55 Addendum III for May 1983 MOGRE, R L , LABAR, M P , MOURY, W R GA Technologies, Inc /General Atomic Co B3/05/31 72pp 18748 029
- 8306210447 Forwards request for add1 info re 830518 application requesting amend to Model FSV-1 packaging Response within 30 days requested MACDOMALD,C E Transportation Branch 83/06/16 MGHRY,W R GA Tachnologies, Inc /General Atomic Co 3pp 18935 351

DOCKET 71-8357 MODEL NNFD-10, DABCOCK & WILCOX CO

8306290588 Requests registration as user of Model NNFD-10. IDEMER.R L Nuclear Fuel Services. Inc (subs of Getty Gil Co 83/06/15 HACDONALD.C E Transportation Branch 1p 19047 15 19047 198

DOCKET 71-6400 MODEL 6400, WESTINGHOUSE ELECTRIC CORP

- 8305010001 Fowards Rev 3 to BAR for packaging Super Tiger shipping container as adapted for light-water breader reactor-type fuel rods Concurrence requested by 830704
 ENGEL W P Energy, Dept of 83704/22 MACCONALD.C E
 Transportation Branch 2pp 18687 192
- --8306010085 Rev 3 to SAR for peckaging Super Tiger shipping container as adapted for light-water breeder reactor-type fuel rods PLUMMER, D E , ZUCKER, C E Energy, Dept of WAPD-LP(FE)-220 ROS 63/02/20 120pp 18687 184
- 8306R0002R Submits lists of SAR packages for which DDE no longer intends to pursue certificates of compliance Also lists SARPs for which DDE intends to pursue issuance of certificates of compliance PRICHARD, R P Energy, Dept of 83/05/31. MACDONALD, C Diviof Fuel Cycle & Material Safety 2pp 18908 352 MACDONALD, C Division

DOCKET 71-4421 MODEL: CBE-14, ENFRGY, DEPT OF

8306200022 Submits lists of SAR packages for which DOE no longer intends to pursua certificates of compliance Also lists SARPs for which DOE intends to pursue issuance of certificates of compliance PRICHARD, R P Energy, Dept of 83/03/31 MACDONALD, C Diviof Fuel Cycle & Material Safety 2pp 18908 352 MACDONALD, C Division

DOCKET 71-6550 MODEL: 6-08-1, ENERGY, DEPT OF

930&1704&5 Requests for Model &-6-5-1, documents referenced by Gertificate of Compliance 6550 within 45 days of ltr date, to complete review of LBL 830503 renewal application MACEDONALD, C E. Transportation Irranch 83/06/08 JACKSON, C D Energy, Dept of 1p 18874 362

DOCKET 71-6553 MODEL: PADUCAN TIGER, ENERGY, DEPT OF

- 8306140744 Forwards Rev 1 to Certificate of Compliance 6553 For Model Puducah Tiger.

 MACDUNALD.C E Transportation Branch 83/06/03 BLALUCK.L
 Ensigy Dept of 2pp 18845 345
- --8306140750 Certificate of Compliance 4553. Rev 1, for Model Paducah Tiger HACDUNALD,C E Transportation Branch. 63/06/03 4pp 18845 347.

- DOCKET 71-6574 HODEL HN-200, HITIMAN NUCLEAR & DEVELOPMENT CORP
- 6306020626 Notification of registration as user of Models HR-1008, HR-100, Series 1, HN-100, Series 3 & HN-700 in response to MACDONALD, C E Transportation Dranch Wisconsin Electric Power Co ip 18 anch 83/05/23 FAY,C W 18716 345

DOCKET 71-6601 MODEL CNS 8-120. CHEM-NUCLEAR SYSTEMS, INC

- 8306240372 Corrects util name & address on list of registered i Rev 10 to Certificate of Compliance 6401 for Model CNS 8-120 stered users of packaging QAUNY.R D Consolidated Edison Co of New York, Inc. | MACDONALD.C E Transportation Branch 3pp 18907 359 B3/05/24
- 8306090004 Forwards Rev 11 to Certificate of Compliance 6601 for Hodel
- CNS 8-120 MACDONALD.C E Transportation Branch 83/05/31 DEAL.R Chem-Nuclear Systems. Inc. 4pp. 18798 245
- --9306090006 Certificate of Compliance 6601.Rev ii for Model (NS 8-120 MACBONALD, C E Transportation Branch 83/05/31 3pp 18798 249

DOCKET 71-4613 MODEL 702, TECHNICAL OPERATIONS, INC.

8306240440 Requests issuance of IAEA certificate of competent authority for Certificate of Compliance 6613 for Type 8(u) packaging, Model 702, for use in conjunction w/Model 849 special form source assembly Technical Operations, Inc. 83/05/16 RAWL.R. Low, Dept. of in 18997-273 Transportation, Dept of

DOCKET 71-6639 MODEL MH-1A, ENTROY, DEPT OF

8306200022 Submits lists of SAR packages for which DDE no longer intends to pursue certificates of compliance Also lists SARPs for which DDE intends to pursue issuance of certificates of compliance PRICHARD, R P Energy, Dept of 83/05/31 MACDONALD, C Division of Fuel Cycle & Material Safety 2pp 18708 332.

DOCKET 71-6679 MODEL 6679, U.S. ECOLOGY

8305030105 Requests extension until 830701 to submit add1 info re consplidated application for Certificate of Compliance . US Ecology, Inc. (formerly Nuclear Engineering) MACDONALD,C E Transportation Branch | p 1873 WALLER, N K 63/05/18 Ip 18733 296

DOCKET 71-6598 MODEL NFS-4, NUCLEAR FUEL SERVICES, INC.

- 8306230123 FOIA request for five categories of documents re spent fuel at facilities er racisivies AUDIN, L Affiliation Unknown 83/03/05 Office of Administration 2pp 18982 045 24% Fiche 50-014,89/03/05, Benedalistration 8304230123
- 8306230129 Responds to FOIA request for five categories of documents respond to spent fue) at facilities App A & B documents respond to Items 1.2.4 & b forwards App B Documents 1 & 5-11. No documents located for Item 3
 FELTON.J M Division of Rules and Records 83/04/13 AUDIN.L Affiliation Unknown 3pp 18982 047 24X Fichs. 50-014.83/04/13. 8306230127

DOCKET 71-6717 HODEL 6717-B, GAMMA INDUSTRIES

- 8304020585 Forwards, for approval, GA for Radioactive Matl Package 0302 Rev O Requests registration as user of Model 6717-B W/o encl JONES.K C Associated Piping & Engineering Corp (subs. of Johnson Controls, Inc.) B3/05/19 MACDONALD.C E. Transportation Branch
 - Controls, Inc)
 19 18715 061.

- DOCMET 71 9006 MODEL 500-SU, AUTOMATION INDUSTRIES, INC.
- 8305240438 Ack receipt of 830517 ltm requesting amend to Certificate of Compliance 9006 Minor amend for required JACKSON, 6 License Fee Management Brain 83/06/07 SANTORO, M.P. Automation Industries, Inc. .7pp 1897/174
- --8305240441 Forwards amend fee per 830517 request for addition of shielding plates to Model 500-80. Ir-172 source changer, under Cestificate of Compliance 9006
 MAYDERRY, O B. Automation Industries. [in: 83/06/02
 MACDONALD, C C. Transportation Branch 2pp (8797-176
- --8306240445 Application for amond to Certificate of Compliance 9006, adding shielding plates to Model 500-50, hr-192 source changer W/two oversize drawings Aperture cards are available in PDR SANTORD, M P Automation Industries, Inc. 83/05/19 MACDUMALD, C C frensportation Branch 2pp 18997-178
- DOCKET 71-9010 MODEL NC1-1/2: NE INDUSTRIES, INC.
- 830624045/ Application for amend to Rev 9 to Certificate of Compliance 9010 to allow transport of PBR fuel assembly w/max average burnup of 96,000 NBD/MTU & min cooling time of 450 days pract to shipment JOHNSON,C R Nuclear Assurance Corp 42/05/24 MACDONALD,(E Fransportation Branch &pp 18798 114
- 8306090034 Forwards Rev 10 to Certificate of Compliance 9010 for Model NLI-1/2 MACDONALD, C.E. Transportation Branch 83/05/27 JUHNSON, C.R. Nuclear Assurance Corp. 3pp. 18/98 011
- ~8306090037 Contificate of Compliance 4010, Rev 10, for Model NLJ-1/2 MACDGNALD, C. F. Transportation Branch 83/05/27 6pp 18798 014
- DOCKET 71-9015 MODEL IN B. BL. NO USERS
- 8306240375 Requests rev to Cortificates of Compliance 7015 & 7016 to allow use of component spacers to properly position fuel unthin fuel compartments of IN 0.7N-01 & IN-7 packagings ODLSHANN.K Transported In 63703727 MCDONALD.C C Transportation Broach 3pp 10987-3%
- 8306090278 Forwards Rev 5 to Certificate of Compliance 9015 for Models IN 8 & IN 61 MACDONALD, C E Transportation Branch 81/06/03 GOLDMANN, K Transmucles: Inc. Ip. 18810-040
- --8306090277 Certificate of Compliance (U15, Nev 5, For Mudels TN 8 & TN -8L TN -8L MACCONALD, C. L. Transportation Branch 83/06/03 6pp 18810 041
- DOCKET 71-9016 NODEL TN-9, NO USERS
- 8306240375 Requests rev to Contificates of Compliance 9015 & 9016 to allow use of component spacers to properly position fuel within Fuel compartments of TN-0, TN-81 & TN-9 packagings GOLDMANN.K. Transnuclear, Inc. 83705767 MACDONALD, C.E. Transportation Branch. 3pp. 18787-355
- 6306080408 Forwards Rev 3 to Certificate of Compliance 9016 for Model TN-9 MACDONALD,C E Transportation Branch 63/06/03 GULDMAN.K Transmuclear, Inc. ip 18/72 1/6
- --8305080411 Certificate of Compliance 9015.Rev 3.for Hodel IN-9 MACDONALD.C L Transportation Branch 83705703 5pp 18792 177
- DOCKET 71-9017 MODEL SNAP-23A 1000, NAVY, DEPT OF
- 83040B0326 Requests renewal of Certificate of Compliance 9017 for SNAP-23A Model 1000 shipping package w/expiration date of B80331 Amend to QA program to include Certificate of Compliance 9017 for SNAP-23A also requested BHOEMAKER, B Navy, Dept of 83705703 ODEGAARDEN, R Franceportation Branch 2pp 18791 001
- --8306680334 Forwards Certificate of Compliance 9017.Rev 1.for SNAP-23A Model 1000 shipping package MACDUNALD.C.E Transportation Branch 77/03/29 HENDRIX.G W Navy, Dept of 2pp 1879] 004

- --9306080336 Certificate of Compliance 9017.Rev 1.for 9NAP-23A Model 1000 shipping package MACDONALD.C L Transportation Branch 77/03/29 3pp 18791 006
- ~~8306080339 SER supporting use of SNAP-23A Model 1000 shipping package by Dept of Navy Supporting documentation encl W/15 oversize drawings Aperture cards are available in PDR MACDUNALD.C L. Atomic Emergy Commission. Directorate of Licensing 74/09/30 4pp 18791 009
- --8306080340 Application for Certificate of Compliance 9017 for BNAP-23A, Model 1000
 * Hittman Nuclear & Development Corp (subs Hittman Corp), 74/04/19 190pp 18791 013
- ---8306080342 Supplemental appliration for Certificate of Compliance 9017 for SNAP-22A. Nodel 1000 + Hittman Nuclear & Development Corp (aubs. Hittman Corp) 74/08/28 76pp 18791 141
- 9306150239 Forwards Rev 2 to Certificate of Compliance 9017 Por Model BNAP-23A MACDONALD.C E Transportation Branch 83/06/03 Navy, Dept of Ip 18970 050
- ---8306150240 Certificate of Compliance 9017.Rev 2.Por Model SNAP-23A MACDDNALD,C C Transportation Branch 83/06/03 4pp 18870 051.
- DOCKET 71-9029 MODEL 676 & 676E, TECHNICAL OPERATIONS, INC
- 8306030041 Notification of registration as user of Models 676,676E,650,660,660E,680,715,920,850 & MRC-20WC in response to 830412 request
 MACDUNALD,C E Transportation Branch 83/05/23 KRUZIC,R W
 Chicago Bridge & Iron Co ip 18733 187
- DOCKET 71-9032 MODEL 650, TECHNICAL OPERATIONS, INC.
- 8304030041 Natification of registration as user of Models 676,676E,650. 640.660E.690,715,920.850 & MRC-20MC in response to 830412 request MACDONALD,C E Transportation Branch. 83/05/23 KRUZIC,R W Chicago Bridge & Iron Co Ip 18/33 187
- DOCKET 71-9033 MOUEL 660 & 660L, TECHNICAL DPERATIONS, INC
- 8306240401 Requests repistration as user of Model 660 NEAL-T F Consumors Fower Co. 83765726 MACDONALB.C E Transportation Branch p 18997 353
- DOCKET 71-9035 MODEL 480 & 680E, TECHNICAL OPERATIONS, INC
- 8304030041 Notification of registration as user of Models 474,676E,450,660,460E,680,715,920,850 & MRC-ROMC in response to 830412 request MACDONALD,C E Transportation Branch 83/05/23 KRUZIC,R W Chicago Bridge & Iron Co Ip. 18733 187
- DOCKET 71 9039 MODEL 715, TECHNICAL OPERATIONS, INC.
- 8304030041 Notification of registration as user of Models 676,676E,650, 660,660E,690,715,720,850 & MRC-20HC in response to 830412 request MACDONALD, C.F. Transportation Branch 83/05/23 KRUZIC, R. H. Chicago Bridge & Iron Co. 1p. 18733 107
- DOCKET 71-9056 MODEL SPEC 2-T. SOURCE PRODUCTION & EQUIPMENT CD
- 8306030053 Informs that 830419 application for amend to Certificate of Compliance 9056 requires for Request classified as minor amend JACKBON 0 License Fee Management Branch 83/05/05 DICHARRY, R.F. Bource Production & Equipment Co., Inc. 2pp 18733 199
- --B304030087 Requests amend to Certificate of Compliance 9056, requiring use of overpack, consisting of 12 gallon, 24 gauge drum fitted w/lock ring top DICHARRY, R F Source Production & Equipment Co , Inc B3/04/19 MACDONALD, C. Transportation Granch. 1p 18733 201

- B306170464 Requests add1 info re 930419 application for amend to Modrl SPEC 2-T Unique model number should be designated for overpact & contents Response schedule requested within 30 days of itr date

 MACDONALD, C E Transportation Branch B3/06/08 DICHARRY, R f
 Source Production & Equipment Co , Inc 1p 18906 348
- DOCKET 71-9070 MODEL N-55. ENERGY, DEPT OF
- 830&080382 Issues amend to Certificate of Compliance 9070 for Model N-55, authorizing one-time shipment of Pu fluoride neutron source containing 35 Ci Pu-238 MACDONALD, CE Transportation Branch 83/06/03 NARDI, A J Westinghouse Electric Corp 2pp 18785 360
- DOCKET 71-9080 MODEL 9080. HITTMAN NUCLEAR & DEVELOPMENT CORP
- 8306020828 Advises that encl Hittman Nuclear & Development Corp 830422 application for renewal of Certificate of Compliance 9080 & associated proprietary SARs & drawings should be placed in FDR MACDUNALD, C.E. Transportation Branch 83/05/13 SCOTT, S. Document Management Branch ip 18702 001
- --8306020533 Forwards application for renewal of Certificate of Compliance 7080, authorizing use of HN-600 & NUPAC 7-100 casks.

 MALLORY, C. W. Hittman Nuclear & Development Corp. (subs. Hittman Corp.), 83/04/22. MACDONALD, C. Transportation Branch. 2pp. 18702-002
- --8306020540 Application for renewal of Certificate of Compliance 9180, authorizing use of HN-600 & NUPAC 7-100 casks W/seven oversize drawings Aperture cards are available in PDR × Hittman Nuclear & Development Corp (subs Hittman Corp) 83/04/22 App 18702-004
- --8306020592 Rev O to "SAR for 9080 Radwaste Shipping Cask "
 PETTIGREH,M Hittman Nuclear & Development Corp (subs Hittman Corp). STD-R-02-011 ROO 83/04/22 /6pp 18702 012
- 8306020635 Informs that Rev & to Certificate of Compliance 9080 for Model 9080 will not expire until determination made by Commission Application for renewal should be submitted in timely manner.

 MACDONALD.C.E. Transportation Branch 83/05/23 ROME, 8 9 Hittman Nuclear & Development Corp (subs. Hittman Corp.) App. 18716-334
- 8304290601 Forwards request for addl info in response to 830422 application for renewal of Certificate of Compliance 9080 for Model 9080. Info should be submitted within 60 days MACDONALD, C. E. Transportation Branch 8370470 MALLORY, C. W. Hittman Nuclear & Davelopment Corp. (subs. Hittman Corp.) 3pp. 19047-090
- DOCKET 71-9086 MODEL, HN-100, SERIES 1, HITTMAN NUCLEAR & DEV CORP.
- 8304020424 Notification of registration as user of Models HN-1008, HN-100, Beries 1, HN-100, Series 3 & HN-200 in response to 830330 request.
 MACDUNALD.C.E. Transportation Branch 83/05/23 FAY, C W Wisconsin Electric Power Co. ip 18714, 345
- DOCKET 71-9089 MODEL HN-1008, HITTMAN NUCLEAR & DEVELOP CORP
- 830.6020.626 Notification of registration as user of Models HN-1008, HN-100, Beries 1, HN-100, Beries 3 & HN-200 in response to 830330 request
 MACDONALD.C. E Transportation Branch 83/05/23 FAY, C W Wisconsin Electric Power Co 1p. 18716 345.
- 8305130177 Advises that encl Hittman Nuclear & Development Corp 830515 application for renewal of Certificate of Compliance 9089 & associated proprietary SARs & drawings should be placed in PDR HACDONALD.C.E Transportation Branch 83/06/03 SCOTT.8 Document Management Branch in 18830 184.
- --8306130185 Forwards application for renewal of Certificate of Compliance 9089, authorizing use of Model HN-1008 MALLORY, C. V. Hittman Nuclear & Davelopment Corp (subs Hittman Corp.). 83/05/16 MACDONALD, C. Transportation Branch. Ip 18830-185

- --8306130198 Application for renewal of Certificate of Compliance Maly, authorizing use of Model HN 1005 W/Nev 0 to "SAR for HN-1005 Radwaste Shipping Cask" & two oversize diawings Aperture cards are available in PDR # Hittman Nuclear & Development Cosp (5465 Hittman Cosp) 83/05/16 | 4pp | 18830 186
- --B306130212 Rev O to "SAR for NN 1005 Radwarte Shipping Cask"
 PETTIGREW, M. Hittman Nuclear & Development Corp. (subs. Hittman Corp.) STD R-02-012 ROO. 63/05/1,1 /8pp. 10HJO 192
- DOCKET 71-9096 MODEL CNS 21-300. (HEM-NUCLEAR SYSTEMS, INC
- B306090202 Advises that response to B30505 request For add1 info re Model CNS-21-300 amend request will be submitted by B30701 POPPEL K Chem-Nuclear Systems Inc B3/05/27 MACDONALD, C F Transportation Branch ip 16809 204
- 8306280101 Summary of 830614 meeting w/Chem-Nuclear.Inc in Silver Spring.MD re proposed use of temporary shielding in Model CNS 21-300 DDEGARDEN.R H Transportation Branch 83/06/20 Transportation Branch 2pp 17042 300
- DOCKET 71-9100 MDDLL KKP-20-4950, KERR NK GEL NUCLEAR CORP
- B308240459 Notification of registration as user of Model KKP (*) 4950. in response to 830414 request MACDONALD, C E Transportation Branch 83/06/20 0'HEA, P B Rhome-Poulene, Inc. (p. 1894) 255
- DOCKET 71 -9108 MODEL CNS 6-75, CHEM-NUCLIAR SYSTEMS, INC
- 8306210290 Application for renewal of Certificate of Compliance 9100, authorizing use of CNB 6-75 cask for shipment of indwaste Rev I to "GAR for Chem-Nuclear Sys, Inc Model CNS 6-75 Type A Radwaste Shipping Cask" encl POPPE, L K Chem-Nuclear Systems, Inc 89/03/31 MACDONALD, CE Transportation Branch ip 18921 244
- --8306210256 Rev I to "BAR for Chem-Nuclear Sys. Inc Model CNS 6-/5 type A Radwasts Shipping Cask" * Chem-Nuclear Systems, Inc. 83/05/20 53pp 18921 245
- DOCKET 71-9110 MUDEL MX-IC-100, MAGNAFILUX CORP
- B306240342 Application for renewal of Certificate of Compliance 7110. Rev 0.for Model MX-KC-100 ROSAUER,P J Affiliation Unknown B3/06/02 MACDONALD.C F Transportation Branch 2pp 18999 184
- 8306170455 Forwards Rev I to Certificate of Compliance 9110 for Model MX-IC-100 MACDDNALD, C F Transportation Branch 83/06/09 ROBAUER, P J Magnaflux Corp (subs of Peabody Galion Corp) 2pp 1890/31/
- --8306170456 Certificate of Compliance 9110, Rev 1, for Model MX-1C 100 Approval record encl MACDONNLD.C E Transportation Branch 83/06/09 3pp 141907 3J9
- DOCKET 71-9111 MODEL CNS 6-80-2, CHEM-NUCLEAR SYSTEMS, INC
- 8304020040 Requests add1 info ie 830303 amend application for Modrl CN86-80-2 Response requested in 30 days of receipt of ltr MACDONALD.C E Transportation Branch 82/05/25 DEAL.R Ghem-Nuclear Systems. Inc 2pp 18702 321
- 8306090001 Forwards Rev 6 to Certificate of Compliance 9111 for Model CNS 6-80-2 MACDONALD, C E Transportation Branch 83/05/31 SIMCHUK, J D Nuclear Packaging, Inc. 3pp 18798 (**);
- ---B306090002 Certificate of Compliance VIII.Rev 6.for Nodel CNS 6-80-9 MACDONALD.C E Transportation Branch 93/05/31 4pp 141798 259
- 8306170458 Requests consolidated application w/drawings, incorporating previous submittals, within 30 days of expiration date of Certificate of Compliance 9111 for Model CNB 6-80-2 MACDONALD.C E Transportation Branch 83/06/08 SIMCHUK, J D Nuclear Packaging, Inc. ip 18906-359

DOCKET 71-9132 MODEL T-3, ENFRGY, DEPT OF

- 8306170462 Requests registration as user of Model T-9 PRICHARD.N P Energy, Dept of 83/06/02 MACDONALD.C & Transportation Branch 1p 18906-351
- 0306240455 Natification of registration as user of Model 1-3.in response to 830602 request MACDONALD.C E Transportation Branch 83/04/20 Energy, Dept of jp 1879/ 257
- 8306240485 Natification of registration as user of Model T-3.in response to 830602 request MACDOMALD.C E Transportation Branch 83/06/20 TERRY,W E Union Carbide Corp 1p 18998 060

DOCKET 71-9133 MODEL C-10, GARMA INDUSTRIES

8304030038 Requests registration as user of Model C-10 EVANS.W A Capitol Steel Corp 83/05/05 MACDONALD.C E Transportation Dranch 1p 18733 179

DOCKET 71-9134 MODEL ETR. EXXON NUCLEAR IDARO CO

- 8306160864 Requests Certificate of Compliance 9134 by revised to permit shipment of unirradiated reactor fuel other than ETR & GTR fuel elements Technical evaluation encl PRICHARD.R P Energy, Dept of 83/06/02 MACDONALD.C E Transportation Branch 5pp 1889 003
- --8306160667 Certificate of Compliance 5/05, Rev 2, for Models ATR & ETR fuel element shipping containers
 WILLIAMS, C. E. C. Energy, Dept of 82/10/25 App 18892 007
- --8306180670 "RTR Fuel Element Shipping Container Addendum to PR-T-/9-011 (TR-466)." internal tachnical rept SMITH.M L EC&G. Inc PR-T-79-012 ROI 82/12/02 USpp 18884 217

DOCKET 71-9135 MODEL CENTURY 6 & BA, CEN UNIV 8 & BA, QAMMMA IND

0306240301 Requests registration as user of Models Century SA, IR-50 & IR-100 IR-100 CORDESIA.D M Cherno Contracting Corp 83/06/06 NACOUNALD, C L Transportation Branch 1p 18987 354

DOCKET 71-9141 MODEL 900, TECHNICAL OPERATIONS, INC.

- 8306160639 Informs that Model NRC-20WC vs Package Number V8A/9141/N in error Model number should be 900 Requests issuance of confirmation itr covering model number KRVIICR W Chicage Bridge & Iron Co 83/06/02 MACDONALD, C & Transportation Branch 2pp 16884 342
- 8306240456 Notification of registration as user of Model 900.in response to 830502 request
 HACDONALD.C E Transportation Branch 83/06/20 KRUZIC.R W Chicago Bridge & Iron Co. ip 18997 256
- DOCKET 71-9142 NODEL MRC-20WC, MONSANTO RESEARCH CORP
- E304030041 Notification of registration as user of Models 674.478E.650. 640.660E.680.715,920.850 & MRC-20WC in response to 890412 request MACDOMALD.C E Transportation Branch 89/05/29 KRUZIC.R W Chicago Bridge & Iron Co ip 18793 187

DOCKET 71-9143 MODEL 920, TECHNICAL OPERATIONS, INC.

8304030041 Notification of registration as user of Models 676,676E,650, 660,660E,680,715,920,850 & MRC-20WC in response to 830412 request. MACDONALD,C E Transportation Branch B3/05/23 KRUZIC,R W Chicapo Bridge & Iron Co ip 18733 107

- DOCKET 71-9147 MODEL 850, TECHNICAL OPERATIONS, INC.
- B306030041 Notification of registration as user of Models 676,676E.650,660.660.715,920.850 & MRC-20WC in response to 830412 request MACDONALD.C E Transportation Branch B3/05/23 KRUZIC.R W Chicago Bridge & Iron Co lp 19733
- DOCKET 71-9151 MODEL HN-100, SERIES 3: HITTMAN NUCLEAR & DEV CORP
- 8306020626 Notification of registration as user of Models HN-100B, HN-100 Series 1.4N-100 Series 3 & HN-200 in response to 830330 request MACDUNALD, C E Transportation Branch 83/05/23 FAY, C W Wisconsin Electric Power Co 1p 18716 345
- 8306150143 Notification of registration as user of Models HN-100 Beries 3 & CNS 14-170 Series III in response to 830228 request MACDONALD, C.C. Transportation Branch 83/06/09 MUSOLF, D Northern States Power Co. ip. 18872
- DOCKET 71-9152 MODEL CNS 1-13C11. CHEM-NUCLEAR SYSTEMS, INC
- 8306020711 Notification of registration as user of Model CNS 1-13C 11 in response to 830309 request MACDDNALD,C E Transportation Branch 83/05/23, BRACKEN.K W Energy, Dept of 1p 18715 319
- DOCKET 71-9156 MODEL IR-50, INDUSTRIAL NUCLEAR CO
- 8306170461 Forwards info on IAEA B(U) certification of devices, per request.Requirements listed in IAEA Safety Std 6 adequately addressed in application GAINES, T M Industrial Nuclear Co 83/05/31 RAWL.R Transportation. Dept of 2pp 18906-352
- 8306240381 Requests registration as user of Models Century BA, IR-50 & IR-100 CORRESIA.D M Charne Contracting Corp 83/06/06 MACDONALD, C E Transportation Branch 1p 18987 354

DOCKET 71-9157 MODEL IR-100, INDUSTRIAL NUCLEAR CO

- 8306170461 Forwards info on IAEA B(U) cortification of devices, per request Requirements listed in IAEA Safety Std 6 adequately addressed in application GAINES, T M Industrial Nuclear Co 83/05/31 RAML, R Transportation, Dept of 2pp 18905-352
- 8306240381 Requests registration as user of Models Century 8A, IR-50 & IR-100 CORRESIA.D M Cherne Contracting Corp 83/06/06 MACDONALD, C. E Transportation Branch ip 18987-354
- DOCKET 71-9159 MODEL; NUPAC BERIES A. NUCLEAR PACKING. INC.
- B306030135 Expresses appreciation to Transporation Certification Branch for cooperation 2 assistance during licensing process SINCHUK, JD Nuclear Packaging, Inc. B3/05/04 MACDONALD, C E Transportation Branch ip. 18733 308
- DOCKET 71-9163 MODEL GNG-20, GULF NUCLEAR, INC
- 8306210305 Forwards pertinent drawings of shipping shield, insert & plug HOPCRAFT, C.P. - Quif Nuclear, Inc. - 83/06/03 MACDONALD, C.E. Division of Fuel Cycle & Material Safety, 12pp 18920; 351
- DOCKET 71-9165 MODEL 855, TECHNICAL OPERATIONS, INC.
- 8304030489 Forwards add1 info on Model 855 Type B package in response to 820727 request MUNRO.J J Technical Operations. Inc 83/05/12 MACDDNALD.C.E Transportation Branch. 13pp 18735 230

- --8306030492 Forward request for addl info re 820521 application for Certificate of Compliance 9165 for Model 855 packaging Addl Info should be submitted in form of revised pages HACDDNALD, C.E. Transportation Dranch 82/07/29 NUNRO, J.J. Technical Operations, Inc. 2pp. 18/15 244
- 8306220199 Forwards request for addl info re 820521 application & 830512 supp) for approval of Model 855 packaging Submittal schedule requested in 30 days
 MACDONALD, C E Transportation Branch 83/06/16 MUNRO, J J Technical Operations, Inc. 2pp 18951 038
- DOCKET 71-9174 MODEL F-147, ATOMIC ENERGY OF CANADA, LID
- B30A220185 Forwards request for add1 info re 830224 application for approval of Model F-147 packaging Submittol schedule requested within 30 days MACDDNALD.C E. Transportation Branch B3/06/15 RIDOUT.E F Canada. Atomic Energy Control Board 2pp 18977 332
- DOCKET 71-9174 MODEL NUPAC 14/210L & 14/210H, NUCLEAR PACKAGING, INC
- 8304030135 Expresses appreciation to Transporation Certification Branch for cooperation & assistance during licensing process SIMCNUK, J.D. Nuclear Packaging, Inc. 83/05/04 MACDDNALD, C.E. Transportation Branch Ip 18733
- 8306030042 Requests registration as user of Model NUPAC 14/210K NIX.H C Georgia Power Co B3/05/13 MACDONALD.C E Transportation Branch. 1p 18733 188
- 8306080345 Requests registration as user of Model 14-210H EBENHACK.D.G Chem-Nuclear Systems, Inc. 83/05/26 MACDONALD.C Transportation Branch 1p. 18787 362
- DOCKET 71-9178 MODEL NUPAC 7/100. NUCLEAR PACKAGING. INC
- B306030135 Expresses appreciation to Transporation Certification Branch for cooperation & assistance during licensing process SIMCHUK, J D. Nuclear Packaging, Inc. 83/05/04 MACDONALD, C.E. Transportation Branch ip 18733
- DOCKET 71-9179 MODEL NUPAC 6/100L & 6/100 H, NUCLEAR PACKAGING, INC.
- 830&030135 Expresses appreciation to Transporation Certification Branch for cooperation t assistance during licensing process SIMCHOK, J.D. Nuclear Packaging, Inc. 83/05/04 MACDONALD, C. F. Transportation Branch Ip. 18733
- DOCKET 71-9102 MODEL HUSMAN IRRADITOR, AGRICULTURE, DEPT OF
- 8306070453 Forwards "8AR for Husman Irradiator to 10CFR71 Type B Packaging Requirements "Packaging to be used by USDA BTREUTRER.6 R Nuclear Packaging, Inc 83/05/16 MACDONALD,C E Transportation Branch ip 82781 CO1
- --8306070455 "SAR For Husman Irradiator to 10CFR71 Type B Patkaging Requirements" * Nuclear Packaging, Inc. 83/05/15 12700 18781 002

- ---830c070458 Advises that Nuclear Packaging, Inc will be forwarding, under separate cove, SAR for new Husman irradiator Requests issuance of license & IAEA Certificate of Competent Authority for shipment of yadioactive matl
 JARRETIAR D Agriculture, lept of 81/04/27 WCISS, D licens, Fee Management Branch 3pp 18781 131
- DOCKET 71-950B MODEL DOT SPEC AM. EMERGY, DEPT OF
- 8306150326 Forwards list of addl info required re 800005 application requesting Certificate of Compliance authorizing shipment of polystyrene Pu compacts in Model 6M packaging MACDONALD.C E. Transportation Branch 83/06/06 PRICHARD.R P Energy. Dept of 2pp 18867 357
- DOCKET 71-9510 MODEL OPHS, ENERGY, DEPT OF
- 8304200022 Submits lists of SAR packages for which DDE no longer intends to pursue certificates of compliance Also lists SARPs for which DDE intends to pursue issuance of certificates of compliance PRICHARD, R P Energy, Dept of 83/05/31 MACDONALD, C Division of Fuel Cycle & Material Safety 2pp 18908 352
- DOCKET 71-9851 MODEL LITHIUM HYDROXIDE FIRE/IMPACT SHIFED. ENERGY,
- B306200022 Submits lists of SAN packages for which DDF no longer intends to pursue certificates of compliance Also lists SARPs for which DDE intends to pursue issuance of certificates of compliance PRICHARD, R P Energy, Dept of B3/05/31 MACDUNALD, C Unvision of Fuel Cycle & Material Sofety 2pp 18908 352
- DOCKET 71-9852 HODEL D7-14, ENERGY, DEPT OF
- 8304020488 Notification of registration as User of Models DT-148 & NFI-67-0442 in response to B30218 & 05% requests MACDONALD, C E Transportation Branch B3/05/25 ANSELNO, A A E000, Inc. ip 19715-200

LICENSING OF INDEPENDENT SPENT FUEL STORAGE

DOCKET 72-0001 MORRIS OPERATIONS, GENERAL ELECTRIC CO

- 8306030426 Submits annual concollidated SAR update
 DAMSON.D M. General Electric Uranium Management Corp. 83/05/1:
 CUNNINGHAM, R. Division of fuel Cycle & Material Safety 2pp
 18735-346
- 8306240484 Suggests withdrawal of rev to GA Plan NEDD-20774, Pot further editing before resubmission Response by 030708 requested ROBERTS, J P Advanced Fuel & Spent Fuel Licensing Branch B3/06/20 DANSON, D M General Electric Co ip 18778 067

LOCER COMMISSION MEETING RECORDS 8303110499 Board Notification 83-87 forwards info item re design verification program
EIEENHUT.D 0 Division of Licensing 83/06/27 PALLADINO,N.Q
EILINSKY,V. ROBERTS,TM Commissioners 2pp 19053 035 2/ --8306290470 Transcript of 830617 public meeting in Bethesda, MD re design 8306020371 Transcript of Commission 830527 public briefing in Hashington, DC re plant reliability data sys Pp 1-60 Supporting documentation and Commissioners 83/05/27 116pp 18714 247 8304020700 Transcript of Commission 830527 discussion & possible vote in Mashington, DC on full power GL Pp 1-83 Supporting documentation ent!

Commissioners B3/05/27 112pp 18717 046 24X
Fiche 50-370, 83/05/27, 8304020700 8306020709 Transcript of Commission 830526 meeting in Washington. DC, re emergency planning & preparedness Pp 1-117 Supporting documentation encl # Commissioners 83/05/26 236pp 18716 001 24X * Commissioners 83/05/26 23 Fiche 50-247,83/05/26,8306020709 9306030157 Staff requirements memo informing of Commission 830513 briefing in Washington.DC on NUREG-1900, "Generic Implications of ATWS Events at Salem Nuclear Power Plant"
Departing criteria requested CHILK.B J Office of the Secretary of the Commission M830518 83/05/27 DIRCKB,W J Office of the Executive Director for Operations ip 18733 313 24X Fiche 50-272,83/05/27,8306030157 B306030259 Staff requirements memo re B30527 discussion/possible vote in Washington, DC on full power OL authorization License amend to be modified re maint of circuit breakers Meeting requested w/breaker mfg CHILK.S J Office of the Secretary of the Commission M830527A 83/05/27 DIRCKS.W J Defice of the Executive Director for Operations 1p 18734 071 24X Fiche 50-370, 83/05/27, 8306030259 8306030499 Staff requirements memo re Commission 830527 briefing in Washington.DC on status of nuclear plant reliability data sys Staff responded to questions on status rept.per SECY-83-4 CHILK: 8 J 83/05/27 Office of the Secretary of the Commission M8305279
Office of the Secretary of the Commission ip. 18735 246 8304030501 Staff requirements memo re Commission 830523 briefing in Hashington.DC on SECY-83-195, "Staff Comments on EPA Proposed Stds for U & Thorium Mill Tailings at Licensed Commencial Processing Site " Comment deadline is 830614 CHILK.S J Office of the Secretary of the Commission M8305238 83705727 Office of the Secretary of the Commission ip.

8306060369 Transcript of Commission 830531 affirmation/discussion & vota in Washington, DC re SECY-83-128 on renewal of Rockwell Entit Energy Sys Oroup SNM license Pp 1-2 Commissioners. 83/05/31 Spp 18748 349.

8306060389 Staff requirements memo re 830523 affirmation/discussion & vote in Washington,DC on 8ECY-83-117 review of ALAB-701 & 10CFR60, "Disposal of High Level Wastes in Geologic

9304080331 Staff requirements memo re Commission 930524 briefing on NRC revalidation of mgt competence identified in insps on 930518 t 19 830518 t 19
CHILK, S J Office of the Secretary of the Commission M830524A
83/06/02 DIRCKS, H J Office of the Executive Director for
Operations 1p 18789 355 24X Fiche 50-320,83/06/02,8306080331 8304080439 Forwards Commission determination statement withholding transcript of 830224 meeting from public disclosure CHILKS J. Defice of the Secretary of the Commission 83/05/18 Public Document Branch 1p 18792 213 24X Fiche 50-322,83/05/18. --8304080442 Commission determination statement withholding transcript of 830224 meeting from public disclosure CHILK: 8 J Office of the Secretary of the Commission 83/05/18 Office of the Secretary of the Commission 1p 18792 214 24X Fiche 50-322,83/05/18,8304080439. 8304i305i6 Staff requirements memo re 83033i affirmation/discussion & vote in Hashington, DC re concerning renewal of Ruckwell Intl SNN license CHILLERS CHILLE Of the Secretary of the Commission. MR30531C 83/06/03 PLAINE.H E Office of the General Counsel. 1p 18830 270 8306150206 Staff requirements memo re 830526 oral presentations in Bethesda, ND re emergency planning & preparedness at Indian Point List of participants encl CHILK, 8 J Office of the Secretary of the Commission 83/06/07 Office of the Becretary of the Commission. 2pp. 18870 045 24X Ficher 50-247, 83/06/07, 8306150206 B306150500 Transcript of B30607 Commission discussion & vote on swergency planning deficiencies at Indian Point in Washington, DC Pp 1-24 # Commissioners B3/06/07 30pp 18868:249 24X Fiche 30-247, 83/06/09, 8306150500 B304i40093 Addl response to FOIA request for documents re IAEA nuclear matl safeguards program. Forwards App A documents App B Documents 1-8 entirely withheld & Documents 9-16 partially withheld to Documents 9-16 partially withheld (ref FOIA Exemptions 1.3 & 5).
FELTON.J M Division of Rules and Records, 83/04/01.
OREENBERO, E V Tuttle & Taylor 5pp. 18892 011 --8306160211 Forwards partially released transcript of 820602 briefing on efforts to improve IAEA safeguards in Washington, DC. Withheld portions per iOCFR9, IO4(a)(i) listed CHILKS J. Office of the Secretary of the Commission 82/08/03, Office of the Secretary of the Commission 2pp 18892-187 B3D4i40673 Transcript of Commission B30610 meeting re discussion & possible vote on full-power DL in Washington, DC. Pp 1-90 Supporting documentation encl # Commissioners B3/06/10 150pp 18884 045. 24X Fiche: 50-389, B3/06/10, B306i60673 8304170450 Transcript of Commission 830415 briefing in Hashington,DC re-status of certification in TMI-1 restart proceeding Pp 1-36 Supporting documentation encl * Commissioners 83/06/15. 80pp 18706:234 24X Fiche:50-289,83/06/15,8306170450 8306200016 Transcript of Commission 830615 briefing in Washington, DC restatus of GA & soil settlement at facility Pp 1-64
Supporting documentation encl.
Commissioners. 83/06/15, 76pp 18909:238, 24X
Fiche, 30-329, 83/06/15, 8306200016

- B306200026 Staff requirements memo re 830610 discussion & possible vote AURITORIA STATE TEQUITEMENTS memo TE 330010 4136.093101 0 possible vi in Mashington, BC on full power OL Commission voted 5-0 to authorize full power operation License amend to be modified re post-trip procedures CHILK. S. J. Office of the Secretary of the Commission M830610A 83/06/13 DIRCKS, W. J. Office of the Executive Director for Operations ip 18908 355 24X Fiche 50-389.83/06/13.8306200026
- 8306200030 Staff requirements memo re 830609 discussion & vote in Washington.DC on continued operation of Indian Point Commission agreed by vote of 3-2 to allow continued operation CHILK.S J CHILK'S J Office of the Secretary of the Commission 83/06/14 Office of the Secretary of the Commission 18908 356 24X Fiche 30-247,83/06/14,8306200030 M830609B 83/06/14
- B306240018 Transcript of Commission B30617 briefing on Indian Point labor issues in Hashington.DC Pp 1-44 + Commissioners B3/06/17 47pp 18907 293 24X Fiche 30-247.83/06/17,8306240018
- 8304290562 Transcript of Commission 830417 public meeting in Washington. DC re addi budgetary needs to fulfill requirements of Nuclear Waste Policy Act Pp 1-72 * Commissioners 83/04/17 76pp 19047 103

ACRS ADVISORY COMMITTEE ON REACTOR SAFEGUARDS

- 8305010002 Transcript of ACRS Subcommittee on Electrical Sys 830526 masting in Washington, DC Pp 1-177 Supporting documentation encl
 - AGRS Advisory Committee on Reactor Safeguards 83/05/26 Opp 18664 001 190pp
- B304010064 Transcript of ACRS Subcommittee on ECCS B30524 meeting in Denver CD Pp 1-338 # ACRS - Advisory Committee on Reactor Safeguards 83/05/24 597pp 18666 167
- 8306010075 Transcript of ACRS Subcommittee on ATHS 830527 meeting in Mashington, DC Pp 1-173 * ACRS Advisory Committee on Reactor Safeguards 83/05/27 175pp 18668 044
- 8306010082 Transcript of ACRS Joint Subcommittee on Metal Components/ Reactor Fuels 830527 meeting in Washington DC Pp 219-366 a ACRS Advisory Committee on Reactor Safeguards 83/05/27 151pp 18666-016
- B306010179 Summarizes ACRS 277th meeting on B30512-14 re GEP review of plant Defers review of full-term GL application until NRC completes action on remaining SEP topics, unresolved safety issues & TM1 action items
 EBERSOLE, J. C. ACRS Advisory Committee on Reactor Safeguards
 B3/05/17 PALLADING, J. Commissioners Spp (8696 197 24X)
 Fiche-30-409, B3/03/17, B306010199
- 8304020075 Discusses ACRE 277th meeting on 830512-14 re-results of Phase II of BEP as applied to facility Issue re-protection against extreme external events requires resolution EBERSOLE. J C ACRE Advisory Committee on Reactor Safeguards 83/05/17 PALLADINO, N J Commissioners 3pp 18701 283 24X Fiche. 50-213.89/05/17, R3060200096 Fiche. 50-213, 63/05/17, 8304020095
- 8305020098 Discusses ACRS 277th meeting on 830512-14 re proposed final rules on immediate notification requirements (100FR50 72) & LER sys (100FR50 73) Implementation of rules would greatly improve current reporting requirements EBERSCLE, J. C. ACRS Advisory Committee on Reactor Safeguards 83705/16 PALLADINO, N. J. Commissioners 2pp 18701 281
- 8306020386 Transcript of ACRS Subcommittee on ECCS 830525 meeting in Denver.CD Pp 339-600 Supporting documentation encl # ACRS Advisory Committee on Reactor Safeguards 83/05/25 422pp 18689.168
- 8306090003 Transcript of ACRS Subcommittee on Advanced Reactors 830607 'n Washington, DC. Pp 1-101 Supporting documentation
 - Advisory Committee on Reactor Safeguards 83/06/07
 - ript of ACRS Subcommittee on Qualification Program for Equipment 830607 meeting in Washington,DC ting decumentation enci ory Committee on Reactor Safeguards 83/06/07

- 8304090011 Transcript of ACRS Subcommittee on Plant Features Important to Bafety 830407 meeting in Washington, DC Pp 1-80 Supporting documentation encl

 * ACRS Advisory Committee on Reactor Safeguards 83/06/07 116pp 18793 001
- B306:00073 Transcript of ACRS Subcommittee on Regulatory Policy & Procedures 830608 meeting in Washington, DC Pp 1-81 Supporting documentation encl # ACRS Advisory Committee on Reactor Safeguards 83/06/08 89pp 18803 075
- B304100076 Transcript of ACRS Subcommittee on Safety Research Program B3060B meeting in Washington, DC Pp 1-214 Supporting documentation encl a ACRS Advisory Committee on Reactor Safeguards 83/06/08 232pp 18803 171
- 8306130208 Transcript of ACRS 278th meeting on 830609 in Washington.00 Pp 1-255 Supporting documentation encl * ACRS Advisory Committee on Reactor Safeguards 83/06/09 46bpp 18827 001
- B306170322 Transcript of ACRS 278th general meeting on 830610 in Washington, BC Pp 256-349 * ACRS Advisory Committee on Reactor Safeguards 83/06/10 73pp 18578 058
- 8306170438 Summary of ACRS Subcommittee on Catauba Nuclear Station 830304-05 meetings in Charlotte,NC re OL application review # ACRS Advisory Committee on Reactor Safeguards 83/05/11 ACRS Advisory Committee on Reactor Safeguards 39pp 18908 0 24% Fichs 50-413,83/05/11,8306170438
- B30A200075 Minutes of ACRS Waste Mgt Subcommittee 830318 meeting in Washington.DC re DDE proposed general guidelines for recommendation of nuclear waste repository sites 10CFR60 Proposed agenda.summary comments & attendance list encl
 # ACRB Advisory Committee on Reactor Safeguards 83/05/02 ACRS Advisory Committee on Reactor Safeguards 25pp 18708 206 18708 204
- 830A200096 Submits corrections to Low Level Waste Licensing Branch technical position paper re raduaste classification, to maintain scientific accuracy ORTM, D A ACRS -- Advisory Committee on Reactor Safeguards 83/05/18 TANG, R C ACRS -- Advisory Committee on Reactor Safeguards 1p 18908 231
- 830.6200119 Minutes of ACRS ECCS Subcommittee 830512 meeting in Washington.DC re proposed GE SAFER/GESTR ECCS licensing codes & status of other NRR licensing actions Schedules for completing Unresolved Safety Issues A-43 & A-1 encl # ACRS Advisory Committee on Reactor Safeguards 83/05/12 ACRB Advisory Committee on Reactor Safeguards 29pp 18908
- 8306200153 Minutes of ACRS Subcommittee on SEP on Haddam Neck Nuclear Plant 830407 meeting in Washington DC re integrated plant safety assessment Proposed agenda & attendance list enci # ACRS Advisory Committee on Reactor Safeguards 83/05/14 ACRS Advisory Committee on Reactor Safeguards 14pp 18709 190 24X Fiche 50-213-83/05/14,8306200153
- 8306290163 Minutes of ACRS Joint Class 9 Accidents & Reactor Radiological Effects Subcommittee 830222 meeting in Washington.DC re severe accident source term program Attendance list & agenda encl # ACRS Advisory Committee on Reactor Safeguards 83/05/10 ACRS Advisory Committee on Reactor Safeguards 22ep 18905
- 8306200168 Comments on NUREO-0963 Items 10 6 2 c & 10 6 2 d re waste mgt research program, in view of NRC request for clarification of ACRS recommendations per 830429 meeting Recommendations
- 8305200440 Comments on Reliability & Probabilistic Assessment & Extreme External Phenomena Subcommittees 830413 meeting re Charleston earthquake & licensing implications POMEROY.P W ACRS Advisory Committee on Reactor Safeguards 83/04/25 OKRENT,D ACRS Advisory Committee on Reactor Safeguards 2pp 18920 012
- 8306200444 Responds to P Shewmon questions re cracks in BMR primary piping Meaningful NDE can be conducted if Weldcap designed Correctly

 BUSH.S H

 BuSH.S H

 BUSH.S H

 BUSH.S H

 CRS - Advisory Committee on Reactor Safeguards

 BJ704/29

 IONE, E 0 ACRS - Advisory Committee on Reactor

 Safeguards

 Spp 18920 008

- B304200443 Comments on IDCOR & NRC severe accident research program FDCOR is worthwhile endeavor which should have positive & Long lasting results NRC programs lack strong centralized angt & prioritiration structure DAVIS.P R AFFILIATION STRUCTURE DAVIS.P R AFFILIATION Unknown DAVIS.P R ACRS Advisory Committee on Reactor Safeguards B3/05/02 KERR, W ACRS Advisory Committee on Reactor Safeguards 3pp 18920 005
- B306210007 Transcript of ACRS Metal Components Subcommittee on Pressurized Thermal Shock Research Program B30615 meeting in Oak Ridge. TN Pp 1-199 Supporting documentation encl

 * ACRS Advisory Committee on Reactor Safeguards B3/06/15
 300pn 18910 001
- 8304210378 Comments on Class 9 Subcommittee 830425-26 meetings Severe accident research plan could be more useful to NRR if plan facused on prioritization of research results already gathered CORRADINI.M Misconsin, Univ of Madison CORRADINI.M ACRS Advisory Committee on Reactor Safeguards 83/05/04 MANG.A ACRS Advisory Committee on Reactor Safeguards 4pp 18935 285
- 8306210410 Comments on ACRS Subcommittee on Human Factors 830519
 meeting Add1 funds should be added to human factors research
 budget for FY83
 PZARSON,D North Carolina State Univ PEARSON,D ACRS Advisory
 Committee on Reactor Safeguards 83/05/20 WARD,D ACRS Advisory
 Committee on Reactor Safeguards 2pp 18937 070
- B306210422 Comments on ACR8 ECCS Subcommittee 830510 meeting in Mashington DC Planned B&W intergral sys may be inadequate to achieve stated goals CATTON. I ACR8 Advisory Committee on Reactor Safeguards 83/05/23 BOEHNERT. P ACR8 Advisory Committee on Reactor Safeguards 3pp 18937 045
- B308210442 Summary of joint ACRS Subcommittees on Metal Components & Combination of Dynamic Leads 830327 meeting in Washington DC Te revaluation of double-ended guillotine pipe leak break for Mestinghouse PMR plants ACRS Advisory Committee on Reactor Safeguards 83/05/18 ACRS Advisory Committee on Reactor Safeguards 23pp 18736 237
- 8304210444 Expresses concern re combined legal & best estimate approaches to SAFER/OESTER ECCS methodology Add1 statistical analysis required to justify calculated App K value ZUDANS, Z Franklin Institute/Franklin Research Center ZUDANS, Z ACR8 Advisory Committee on Reactor Safeguards 83/05/13 BOEHNERT, P A ACR8 Advisory Committee on Reactor Safeguards 19 189:33 384
- B305210433 Comments on Class 9 Accidents Subcommittee 830425 & 26 meetings NUREG-0900 fails to answer how regulatory needs for degraded core accidents could be met by severe accident research plan tee.J C Michigan, Univ of LEE.J C ACRS Advisory Committee on Reactor Safeguards 83/05/05 WANG,A ACRS Advisory Committee on Reactor Safeguards 2pp 18935 338
- 8306220290 Comments on GE SAFER/GESTER evaluation model & NRC & GE presentation at 830217-18 & O510 subcommittee meetings ACRS andorsement of evaluation model recommended SCHROCK, V E California, Univ of Berkolog SCHROCK, V E ACRS Advisory Committee on Reactor Safeguards 83/05/17 WARD, D, 80EHNERT, P ACRS Advisory Committee on Reactor Safeguards 3pp 18940 347

ADVCH NRC ADVISORY COMMITTEE

- 8306060331 Transcript of Advisory Committee on Rights of Licensee Employees Under Investigation 830526 hearing in Hashington.DC Pp 1-206 > Rights of Licensea Employees Under Investigation 83/05/26 207pp 18751-046
- B306GB0092 Fowards charter for Advisory Committee for Review of Ofc of Investigation Policy on Rights of Licensee Employees Under Investigation HGVL5.J C Office of the Secretary of the Commission 83/02/23 HOMTON.C National Archives & Records Service 3pp 18787 356
- 8305080093 Meeting agenda for Advisory Committee on Ofc of Invastigation Policy on Rights of Licensee Employees Under Invastigation 830526 meeting a Rights of Licensee Employees Under Invastigation 83/05/26 Rights of Licensee Employees Under Invastigation ip 18787-353

- 8306080095 Statement of P Shoop re grievance/arbitration procedures, presented before Advisory Committee for Review of Ofc of Investigation Policy on Rights of Employees Under Investigation
 SHOOP, P International Brotherhood of Electrical Workers 83/05/26
- 8305080096 Charter for Advisory Committee for Review of Ofc of Investigation Policy on Rights of Licensee Employees Under Investigation HOYLE J C Rights of Licensee Employees Under Investigation 83/02/23 2pp 18787 337
- 8306080101 Ack receipt of 830217 ltr expressing interest in Advisory Committee for Review of Dfc of Investigation Policy on Rights of Licensee Employees under Investigation Press release naming members & charter encl
 HCYLE.J C Office of the Secretary of the Commission 83/03/01
 METTERHAHNIM J Conner & Wetterhahn 4pp 18787 320
- --B306080107 Expresses interest in now Advisory Committee for Review of Ofc of Investigation Policy on Rights of Licensee Employees Under Investigation Requests info re meetings & other activities & membership WETTERMANN M J Conner & Wetterhahn 83/02/17 HDYLE, J C Rights of Licensee Employees Under Investigation 3pp 19787 324
- 8304080337 Forwards transcript of statement before Advisory Committee on Ofc of Investigation Policy on Rights of Licensee Employees Under Investigation on 830526 W/a enc.). LEVI.R P. Rights of Licensee Employees Under Investigation 83/03/04 SHOUP.P Affiliation Unknown ip 18787-361
- 8306080385 Submits comments responding to Commissioner Palladino 830411
 Itr re Advisory Committee on Dfc of Investigation Policy on
 Rights of Licensee Employees Under Investigation Grants of
 confidentiality should be used sparingly
 BURNS, J B Isham, Lincoln & Beale 83/06/03 SILBERT, E J
 Schwalb, Donnenfeld, Bray & Silbert 7pp 18790-276
- B306080429 Delegates authority as acting director of IE to JA Fittgerald PALLADINO,N J Commissioners B2/07/16 FITZGERALD,J A Director's Office, Office of Inspection and Enforcement 2pp 18709-18A
- 8306070450 Requests clarification of 830511 FR notice re text of "Ofc of Investigation Policy on Rights of Licensee Employees Under Investigation" & statutory authority of policy HOGANJ JP 0A Technologies. Inc /Oeneral Atomic Co 83/05/20 LEVI.R P Office of the General Counsel 1p 18812 061
- 8306090801 Responds to 830501 ltr re establishment of advisory committee on investigative procedures DOJ & NRC should jointly review violations prior to adoption of mods to investigative procedures OLSEN.R M Justice. Dept of, Attorney General. Office of 83/05/20 BILBERT.E J Schwalb, Donnemfeld, Bray & Silbert ip 18812 047
- 8306100006 Submits response to N Palladino 830411 ltr re rights of amglayers under investigation Comments will be discussed at 830526 meeting NRC should recognize that public policy favors liberal right to counsel for all interviewers LITTELL.R Debevoise & Liberman 83/05/25 SILBERT.E J Schwalb, Donnenfeld, Bray & Silbert 5pp 18815-314
- 8306i3050i Responds to Advisory Committee on Ofc of Investigation Policy on Rights of Licensee Employees Under Investigation question re govt agencies advising witnesses about right to counsel during informal interviews LITTELL.R Debevoise & Liberman 83/06/03 SILBERT.E J Schwalb. Donnenfeld. Bray & Silbert 2pp 18630 278
- 830&140227 Forwards transcript of Advisory Committee on Ofc of Investigation Policy on Rights of Licensee Employees Under Investigation 830413 meeting. Committee charter & questions for 830422 meeting LEVI.R P Office of the General Counsel 83/04/27 DEVINE.T Government Accountability Project 1p 19844 331
- 8306140270 Confirms commitment to appear at Advisory Committee on Ofc of Investigation Policy on Rights of Licensee Employees under Investigation 830526 meeting W/o encis LEVI,R P NRC - No Detailed Affiliation Given. 83/05/04 8H00P,P Affiliation Unknown ip 18844 208
- 8306140329 Forwards corrected Page 143 to transcript of Advisory Committee on Office of Investigation Policy on Rights of Licansee Employees Under Investigation 830826 meeting LEVI.R. NRC - No Detailed Affiliation Given 83/06/07 MCKNIOHT.J. Document Management Branch ip 19834 118

- --8306440337 Corrected Pages 143-144 to transcript of 830526 meeting of Advisory Committee on Ofc of Investigation Policy on Rights of Licensee Employees Under Investigation # Rights of Licensee Employees Under Investigation 83/06/07 2no 18854 19
- 8306140509 Submits info on effective establishment date & background info on Advisory Committee on Ofc of Investigation Policy on Rights of Licensee Employees Under Investigation LEVI.R P Office of the General Counsel 83/02/28 SILBERT. E Schwalb. Donnenfeld, Bray & Silbert 9pp 18854-015
- --8306140513 Submits info re creation of NRC advisory committee to obtain expert advice on rights of licensee employees under investigation Prompt reply assessing merit of committee requested PALLADINO.N J Commissioners 83/01/10 CARMEN.O P General Services Administration 4pp 18854-024
- --8306140517 Advises that QSA concurred in establishment of Advisory Committee for Review of Ofc of Investigation Policy on Rights of Licensee Employees Under Investigation ROYLE.J C Rights of Licensee Employees Under Investigation 83/02/03 Rights of Licensee Employees Under Investigation 3pp 18854 028
- --8306140521 Forwards charter for Advisory Committee for Review of Ofc of Investigation Policy on Rights of Licensee Employees Under Investigation KAMMERER.C Office of Congressional Affairs 83/02/24. OTTINGER.R L House of Rep., Energy & Commerce 3pp 18854 031
- 8306140681 Requests Commission directly consult DOJ re mads to investigative & insp procedures Consultant svcs to E Silbert withdrawn Procedures inconsistent w/judicial authority JENES, D. Justice, Dept of, Attorney General, Office of 83/05/02 PALLADINO, N. J. Commissioners 2pp 18845-354
- 8306140726 Forwards MJ Wetterhahn 830217 ltr re Advisory Committee for Review of Ofc of Investigation Policy on Rights of Licensee Employees Under Investigation LEVI, R Defice of the General Coursel 83/03/03 SILBERT, E J Schwalb, Donnenfeld, Sray & Silbert 1p 18845-351
- --8306140734 Ack receipt of B30217 ltr expressing interest in Advisory Committee for Review of Ofc of Investigation Policy on Aights of Licensee Employees under Investigation Ltr formanded to EJ Bilbert Press release naming members encl HOYLE.J C Rights of Licensee Employees Under Investigation B3/03/01 WETTERHAHN.M J Conner & Wetterhahn ip 18845 352
- --8306140740 Expresses interest re nomination & selection procedure & matters associated w/formation & operation of Advisory Committee for Review of Ofc of Investigation Policy on Rights of Licensee Employees Under Investigation WETTERHARM. M J Conner & Wetterhahn 83/02/17 HOYLE, J C Rights of Licensee Employees Under Investigation ip 18945-353
- B306140756 Forwards response to B20520 request re Advisory Committee for Review of Ofc of Investigation Palicy on Rights of Licensee Employees Under Investigation & statutory authority for Adoption of propositions before Committee W/o encl LEVI,R P NRC No Detailed Affiliation Given 83/06/03 HOGAN.J P GA Technologies, Inc /General Atomic Co 1p 18845 238
- 8305140789 Notifies of B30526 meeting of Advisory Committee on Ofc of Investigation Policy on Rights of Licensee Employees Under Investigation Recommendations of individuals to contact to appear before committee or submitting views requested SILBERT.E. J Schwalb. Donnenfeld, Bray & Silbert B3/05/03. FITZOERALD, J A Office of Investigation REABHAUSEN.O Debevoise & Plimpton SPRITZER.R B Pennsylvania, Univ of 2pp (8845-327
- 8306170310 Informs that Federal Aviation Administration does not generally advise witnesses of right to counsel.per 830526 meeting of Advisory Committee on Dfc of Investigation Policy on Rights of Licensee Employees Under Investigation LEVI,R P. Rights of Licensee Employees Under Investigation 18706703 Rights of Licensee Employees Under Investigation ip 18908:016
- 8306170476 Forwards proposed form of "Advice to Interviewess" for use by NRC investigators, per Advisory Committee on Ofc of Investigation Policy On Rights of Licensee Employees Under Investigation CHARNOFF, 0. Charnoff, 0. 83/06/03. SILBERT, E. J. Schwalb, Donnenfeld, Bray & Silbert Spp. 18874.327

- 830&200045 Forwards packet of matis describing reasons for creation of Advisory Committee on Ofc of Investigation Policy on Rights of Licensee Employees Under Investigation & formal charter Meeting on 830412 or 13 requested SILBERT. E. J. Schwalb, Donnenfeld, Bray & Silbert 83/03/07 FITZOERALD. J. A. Office of Investigation RUEBHAUSEN, O. Debevoise & Plimpton SCOTT. J. B. Kator, Scott & Heller 3pp. 18909-066
- --8212020236 "IWE Conflict or Cooperation," presented to 1982 AIF annual conference
 CHARNOFF, 0 Affiliation Unknown 82/11/17 18pp 18909 069
- --8306200048 Submits discussion items for Subcommittee on NRC Investigations 821020 meeting in Washington, DC Items include initiation of investigation, availability of counsel & debriefing employees post-NRC interview CHARNOFF: O Charnoff, G 82/10/20 Office of Inspector & Auditor 3pp 18909 087

COMMISSION NRC COMMISSIONERS

- 8305240605 Responds to 830324 & 0411 ltrs re next generation of LWRs NRC has on going program w/EPRI in identifying unresolved generic safety issues which impact design of plant & could affect cost & const time PALLADING.N J Commissioners 83/05/09 AMOROSI.A Argonne National Laboratory ip 18716-356
- --9305240612 Requests that 830324 ltr be made available to all Commissioners re study of LNRs Study would take advantage of worldwide experience w/LNRs, including EPRI evaluation, emphasizing basic changes in design AMDROSI. A Argonne National Laboratory 83/04/11 PALLADING, & J Commissioners to 18716-357
- --8309240624 Comments on development of next generation of LWRs for US & foreign use NRC & nuclear industry collaboration in defining safety criteria & evaluating safety improvements recommended AMOROSI. A Argonne National Laboratory 83/03/24 PALLADINO: N J Commissioners 3pp 18716-398
- 8306020229 Forwards answer to Subcommittee on Nuclear Regulation Question 7. in response to 830411 ltr on FY82-83 Authorization Act. Section 5 re current offsito emergency planning controversy PALLADINO, N J Commissioners 83/05/09 OTTINGER.R L House of Reg 1p 18701 001 24X Fiche 50-322.83/05/09.8306020229
- --8304020242 Forwards answer to Bubcommittee on Nuclear Regulation Question 7, in response to 830411 ltr on FY82-83 Authorization Act, Section 5 re current diffsite emergency planning controversy PALLADINO, N J Commissioners 83/05/07 DUWNFY, T J House of Rep App 18701 002 24X Fiche 50-322,83/05/09,8304020229
- --B306020248 Emphasizes that NRC must not lake undue liberties w//982 Authorization Act. Section 5 re offsite emergency preparedness NRC cannot consider local govt plan developed by util if plan officially approved by iccal govt DOKNEY. T J , OTTINGER.R L House of Rep 83/04/11 PALLADING.N J Commissioners 3pp 18701 008 24X Fiche 50-322,83/05/09.8306020229
- 8304020710 Heekly info rept for wk ending 830520 REHM.T A Office of the Executive Director for Operations 83/05/25 45pp 18717 001
- 8304030156 Responds to 830504 request for clarification of 830505 order to consideration of views of public & parties to special graceoding in 830409 decision Comments from licensees govt agencies & public invited PALLADIND.N J Commissioners 83/05/12 OTTINGER.R L House of Rep. Energy & Commerce 2pp 18733 326 24% Fiche 50-247, 83/05/12, 8304030156
- --83060301DB Requests Commission 830505 order be revised to stress need for parties to safety investigation views on shutdown Rev requested by 830511 OTTINGER,R L. House of Rep., Energy & Commerce 83/05/06 PALLADIND.N. Commissioners 2pp 18733 328 24X Fiche 50-247,83/05/12,8306030136
- 8304030157 Discusses efforts to consolidate NRC activities in one location since THI-2 accident PALLADINO, N J. Commissioners 83/05/10 HATFIELD, H O Senate Appropriations, 2pp 18733, 330.

- B308030164 Submits status rept re Commission activities concerning allegations raised by GPU employees & former employees on mods to plant sys & components w/o proper review tests & approval PALLADINO.N J Commissioners 83/05/12 MINNICH. J Advisory Council for Decontamination of TMI Unit 2 ip 18733 332 24X Fiche 50-320.83/05/12.8306030164
- B306030170 Designates WJ Pircks, Executive Director for Operations, as representative to fact finding panel on facility per 830422 request PALLADIND,N J Commissioners 83/05/10 CUBMB,M M New York, State of 2pp 18733 333 24% Fiche 50-322,83/05/10,8306030170
- --8306030\$76 Requests assistance & participation in fact finding panel re scientific & economic issues surrounding debate on proposed nuclear power plant CUONO.M M New York. State of 83/04/22 Commissioners ip £8733 334 24X Fiche 50-322,83/05/10,8306030170
- 8304D30369 Forwards "NRC Eighth Annual Rept on Domestic Safeguards (U), for Oct 1981 Sept 1982," in response to 740427 NSDM-854, "Domestic Safeguards" re safeguards sys established under
- -womestic mareguards" re safeguards sys esta NRC porview PALLADINO.N J Commissioners 83/05/11 Executive Offices 1p 18734-353 President of US &
- --8306930371 "ARC Eighth Annual Rept on Domestic Safeguards (U), for Oct 1981 Bept 1982 " * Commissioners 83/05/11 App 18714 247
- --8304030975 Advises that "NRC Eighth Annual Rept on Domestic Safeguards (U), for Oct 1981 Sept 1982" submitted to President Reagan Approval to discontinue annual safeguards rept submission requested since info duplicates annual rept PALLAPINO. N J Commissioners 83/05/11 CLARK.W P President of US & Executive Offices 1p 18734 360
- 8306060369 Responds to 830511 ltr.inviting Commission testimony at joint hearing on proposed amends to 10CFR110 re licensing of nuclear exports Commission testimony should be delayed until proposed mods reviewed & reexamined PALLADIND.N J Commissioners 83/05/16 DTTINGER,R L House of Rep., Energy & Commerce 1p 18750-347 83/05/16 OTTINGER,R L House of
- --8306060374 Responds to RL Ottinger 830511 ltr, invating Commission testimony at joint hearing on proposed amends to 10CFR110 re licensing of nuclear exports Commission testimony should be delayed until proposed mods reviewed & reexamined PALLADING.N J Commissioners 83/05/16 DONKER.D House of Rep . Foreign Affairs 1p 18750 348
- -BJOSOGOSO Notifies of BJOS25 joint hearing on prospective amends to COCFRIO relicensing of nuclear exports Present status of proposed amends requested Commission invited to appear & testify at hearing Summary statements requested by BJOS20.
 DTIINGER,R L House of Rep , Energy & Commerce BJ/05/11
 PALLADING,N J Commissioners Jpp 18750 J49
- 830&0&0388 Responds to 830407 ltr re ATMS events & reactor trip breaker malfunctions Language used in IE bulletins revised to ensure specific & general responses
 PALLADINO, N. J. Commissioners 83/05/16 MARKEY, E. J. House of Rep. : Interior & Insular Affairs 24pp 18752 349 24X
 Fiche 50~272,83/05/16,8306060388
- --8306060392 Requests info re unreported breaker failures, reporting requirements & reliability of 25 cycle pre-startup testing to better Understand LER sys MARKEY,E J House of Rep . Interior & Insular Affairs 83/04/07 PALLABINO,N J Commissioners 2pp 18753 018 24X fiche 50-272,83/05/16,8306060388
- 8306070426 Heekly info rept for wk ending 830527 REHM.T A Office of the Executive Director for Operations 83706703 43pp 18782 313
- 8305140801 Forwards response to 830425 request for clarification of allegations re illegal procedures & faulty welds at nuclear power plants.
 DIRGKS,M / Office of the Executive Director for Operations 83/03/18 HATCH,O Q Senate, Labor & Human Resources App 18854 049
- --830&140505 Requests clarification of procedures responding to G Boring allegations re illegal procedures & faulty welds at nuclear power plants, NEHMAN, B Senate, Labor & Human Resources 83/04/25 KAMMERER, C Office of Congressional Affairs 2pp 18834 035

- 8306130146 Weekly info rept for wk ending 830603 REHM.T A Office of the Executive Director for Operations 83/06/09 43pp 18872.048
- 8306130533 Responds to 830304 ltr requesting info 5 responses to questions re 830222 & 25 events Failures of safety sys & broader implications for nuclear power industry discussed PALLADINO, N J Commissioners 83/06/02 81DBN,J R Senate. 27pp 18866 334 24X Fiche 50~272,83/06/02.8306130533
- --8306150343 Expresses concern re 830222 & 25 events when manual shutdown of reactor required following failures of automatic safety sys Investigation by NRC requested prior to restart Questions encl for NRC response.

 BIDEN.J.R. Senate 83/03/04 PALLADING,N.J. Commissioners
 3pp 18867 023 24X Fiche 50-272,83/06/02.8306150533
- 8306160093 Addl response to FOIA request for documents re IAEA nuclear matl safeguards program Forwards App A documents App B Documents 1-8 entirely withheld & Documents 9-16 partially withheld (ref FOIA Exemptions 1.3 & 5) FELTON, J M Division of Rules and Records 83/04/01. GREENBERG, E V Tuttle & Taylor Spp 18892-011.
- --8306160118 Forwards undisputed portion of response to 811125 ltr re IAEA safeguards sys, supplementing Commission 820302 ltr BRADFORD.P A Commissioners. 82/03/04 QTTINGER.R.L House of Rep. Energy & Commerce HART.G Senate DINGELL.J D House o Rep. 2pp 18892 042
- 8306170449 Forwards NRC rept on ADs at licensed nuclear facilities (NUREG-0090,Vol 5,Number 4),for Fourth Quarter CYB2 W/o AMEARNE J F Commissioners 83/06, 83/06/02 O'NEILL, T.P House of Rep BUSH, C H Benate 3pp
- --B306170451 Forwards FR notice & ltr forwarding AO rept to Congress (NUREO-0090, Vol 5, Number 4). Medical misadministration events discussed in SECY-B3-92, upgraded to App C item W/o encla W/o encls
 DIRCKS.W.J. Office of the Executive Director for Operations,
 83/06/02 CHILK.B.J. Office of the Secretary of the Commission
 ip 18907-325
- 8306220198 Forwards Vol 5, Number 4 to NUREG-0090, "Rept to Congress on AOs," for Fourth Quarter CY82 One AO reported at NRC licensees re inoperability of containment spray sys Agreement states reported no AOs AHEARNE J F Commissioners. 83/06/02 D'NEILL,T P, House of Rep BUSH G H W Benate 2pp 18740.024 24X Fiche 50-000,83/06/02, NG00620689 B9105250ER
- --8306220264 Agrees w/830225 view that B&W/util litigation should be carefully reviewed Responses to Questions 2 through 5 raised in 830225 ltr encl
 AHEARNE.JF Commissioners 83/06/01 UDALL,M,K House of Rep.,
 Interior & Insular Affairs 5pp 18940 107, 24X
 Fichs 50-000.83/06/02.8306220378
- --8306220268 Discusses importance of carefully analysing B30222 record of hearing on util/BBW litigation to determine whether record contains info bearing on questions of competence & character requirements of OL holder Questions per TMI-2 accident encl UDALL, M K House of Rep , Interior & Insular Affairs B3/02/25 PALLAPING,N Commissioners 2pp 18940.112 24X Fiche 50-000,83/06/02,8306220198
- 8306230221 Weskly info rept for wk ending 830610. REHM.T.A Office of the Executive Director for Operations 83/06/15 41pp. 18931 315
- 8306240328 Requests encl 830105 memo re IE investigation of Automation NOSACOSES requests spic books members to the spice of the Industries be placed in PDR HANNING,W J Commissioners 83/06/13 CHILK,8 J Office of the Secretary of the Commission ip 18777 171
- --8306240300 Express outrage re IE investigation of Automation Industries Employees received overdose of thousands of rade, suffered extensive visible damage & reported injuries, GILINEKY Commissioners 83/01/05 Commissioners 3p Commissioners 3pp.
- --8306240331 Discusses investigation of AO at Automation Industries. Serious violations & attempted coverups must be penalized swiftly & severely if NRC regulatory policies are to be

- 40333 Requests restoration of \$14,000,000 cut from NRC budget uests Deferral of work from FYB3 plus FYB4 cuts would stantially delay programs scheduled to resolve many nificant issues ERTS.T.M. Commissioners 83/06/13 HATFIELD.M.O. Senate. ERTS, T M Commissioners 83/06/13 HATFIELD, M O Senate, repriations 2pp 18999 207
- 40335 Forwards "Annual Rept for 1982 on Administration of Govt in shine Act of 1976" W/o encl ERTS: T N Commissioners 83/06/13 BUSH: G N Senate 1p 77 207
- 6240336 Forwards "Annual Rept for 1982 on Administration of Govt in unshine Act of 1976"

 DBERTS.T M Commissioners 83/06/13 O'NEILL.T P House of 18999 210
- 4240337 "Annual Rept for 1782 on Administration of Govt in Sunshine ct of 1976 " Commissioners 82/12/31 20pp 18999 211
- 30008 Submits monthly rept on status of offsite emergency paredness for OL reviews for May 1983 CKS.H J Office of the Executive Director for Operations 36/14 PALLADIND.N J Commissioners 69 19046 098

ACT NRC CONTRACTS AND MODIFICATIONS

- 40557 Notification of contract execution "EIIS Sys Drawings," rded to TVA EBJE B - Adm roed to IVA ES.E B Administrative Contracts Branch FIN B-8841 83/ HELSON,C Director's Office HEDDON,F NRC - No Detailed Iliation Given 1p 18327 197 FIN B-8841 83/04/28
- 1190510 Executed Interagency Agreement NRC-ADM-83-441, "EliS Sys vaulogs "
 ATTIANM J NRC - No Detailed Affiliation Given FIN B-8841
 RC-26-83-441 B3/04/13 App 18327 198
- 10708 Notification of contract execution, Mod 2 to "Radionuclide NOTIFICATION of contract execution.Mod 2 to "Radionuclide ation Around U Gre Bodies - Analogue of Radwaste sitories " Contractor Australian AEC .ETT-8 Research Contracts Branch FIN B-6661 NRC-04-B1-172 14/20 BATEON.W Office of Nuclear Regulatory Research sector BIRCHARD.@ NRC - No Detailed Affiliation Given ip 31.311
- i040713 Mod 2, incrementing funds, to "Radionuclide Migration Around Dre Bodiss Analogue of Radwaste Repositories " TCLIFF, W H Australia GUSTAVE, R P. Research Contracts Branch "IN 8-6661 NRC-04-81-172 83/04/20 1p 18351
- OOR2 Notification of contract execution.Mod 3 to "Task Analysis luclear Power Plant Control Room Creus " Contractor ral Physics Corp Natch: V Technical Assistance Contracts Branch FIN 8-7491 O4-82-005 83/05/09. FOREHAND.# Office of Nuclear Regulatory arch. Director JENKINS.J NRC No Detailed Affiliation Given 18687 175
- O10077 Mod 3.extending period of performance to 830609.to "Task alysis of Nuclear Power Plant Control Room Crees" "ITNEY, J W General Physics Corp GUSTAVE, R P Division of stracts FIN 8-7491. NRC-04-82-005 83/03/09 ip 18687 174 1p 18687 176
- 0117 Notification of contract execution, Mod 7 to "Fission Product sport Analysis" Contractor Battelle Columbus Labs ETT.8 Technical Assistance Contracts Branch FIN 8-8992 04-80-177 83/05/11 84180N.W Office of Nuclear Regulatory arch. Director WALKER, T NRC No Detailed Affiliation Given 18486. 338
- 010129 Mod 7, adding Task 8 & providing funding, to "Fission Product Antiport Analysis "
 KZ.F J Battelle Memorial Institute, Columbus Laboratories
 RTGN.K.V Division of Contracts FIN 8-8992 NRC-04-80-1
 /05/11. 4pp 18686 339
- 0327 Notification of contract execution, Mod 2 to "Technical & meering Support Svcs for Radio Communications" ractor DOI ractor DUI AREN.T. Administrative Contracts Branch NRC-10-83-352 5/26 CORLEY.J Division of Facilities & Operations COHEN ILLE.T NRC - No Detailed Affiliation Given 1p 18715-310 COHEN S
- 020327 Mod 2, increasing ceiling amount for FY83 & total amount ligated, to "Technical & Engineering Support Svcs for Radio mmunications " RCIVAL.R M Interior, Dept of HAGAN,T F Division of ntracts NRC-10-83-352 83/05/26 ip 18715 311

- B306020333 Notification of contract execution. Mod 1 to "Technical 1 Engineering Support Sycs for Radio Communications" Contractor DOI MCLEAREN. T Administrative Contracts Branch NRC-10-83-352 B3/05/26 CORLEY. J Division of Facilities & Operations MELVILLE, T , COMEN, S NRC ~ No Detailed Affiliation Given in 18714 312
- --8306020336 Mod 1. defining statement of work deliverables required peliminating requirement for issuance of task orders under agreement to "Technical & Engineering Support Sycs for Radio Communications" WILSON.JF Interior, Dept of HAGAN,TF Division of Contracts NRC-10-83-352 83/05/26 3pp 18719 313
- 8306020459 Notification of contract execution to "Radiation Monitoring Program Requirements " Contractor State of NE MCDERMOTT, D Technical Assistance Contracts Branch FIN 8-8508 NRC-31-83-670 83/05/16 MEVERS.D M Region 4. Office of Director NRC-31-83-670 B3/05/16 MEVERS.D M Region 4. Office of Director NICHOLAS.J B NRC No Detailed Affiliation Given 1p 18715 234
- --8306020463 Contract "Radiation Honitoring Program Requirements," awarded to State of NE SMITH.H D Nebraska, State of MORTON,K V Division of Contracts FIN B-8508 NRC-31-83-670 83/05/14 10pp
- 8906020480 Notification of contract execution, Mod 21 to "Local ECCS Support Studies" Contractor MPR Assoc. Inc WDLLETT. Technical Assistance Contracts Branch FIN 3-5537 NRC-04-75-183 83/05/20 BATSON, W Office of Nuclear Regulatory Research, Director RHEE, O NRC No Detailed Affiliation Given 18715 201
- --B304020482 Mod 21, extending period of performance to 851105 to increasing funding to "Local ECCS Support Sys" MANDIL.1 H MPR Associates, Inc MORTON, K V Division of Contracts FIN 8-5537 NRC-04-75-183 83/05/20 3pp
- 8306020806 Notification of contract execution, Mod 1 to "Licensing Assistance/Geotechnical & Hydrological Evaluation" Contractor EBASCO Svcs, Inc FIELDS, J.A. Technical Assistance Contracts Branch NRC-02-80-033-08 83/05/20 DAVIS, J. Division of Safeguards GARCIA, P. NRC No Detailed Affiliation Given ip 18718 146
- ~8306020513 Mod 1, extending period of performance to 830930, to "Licensing Assistance/Geotechnical & Hydrological Evaluation"
 RASILE, J A Ebasco Services, Inc (subs of Enserch Corp)
 GUSTAVE, R P Division of Contracts NRC-02-80~033-08 83,
 1p 18715 147 83/05/20
- B30603004B Notification of contract execution "Oriovance Review Examiner," awarded to BA Theeman HOYLE, A Administrative Contracts Branch NRC-10-83-360 83/05/17 BIRD, PE Division of Organization and Personnel EDWARDS, R MRC No Detailed Affiliation Given ip 18733 171
- --8306030054 Contract "Grievance Review Examiner" awarded to BA Theemal THEEMAN, B. A. Theeman, B. A. REDELLO, J. E. Division of Contracts NRC-10-83-340. 83/05/17 5pp 18733 192
- 8306030252 Notification of contract execution Mod 16 to "Performance Testing for Personnel Dosimetry" Contractor Univ of Nesting for Personnel Dosimetry "Contractor Univ of Michigan WDLLETT.6 Technical Assistance Contracts Branch FIN B-1049 NRC-01-77-180 83/04/06 FOREHAND,W Office of Nuclear Regulatory Research, Director ROECKLEIN,R NRC - No Detailed Affiliation Given ip 18734 O65
- --8306030256 Mod 16.extending period of performance through 830427. to "Performance Testing for Personnel Dostmetry "
 STEMPLE, P J Michigan, Univ of GUSTAVE, R P Division of Contracts FIN B-1049 NRC-01-77-180 83/04/06 ip 18734
- 8306030254 Corrected notification of contract execution. Mod 6 to "Canadian Beismic Agreement" Contractor Canadian Commercial Corp. Commercial Corp.

 WOLLETT, S. Technical Assistance Contracts Branch FIN 8-6275
 NRG-04-79-180 83705/26 BATBON.W Office of Nuclear Regulator®
 Research Director MURPHY NRC - No Detailed Affiliation Given
 1p 18734 070
- 8304030263 Notification of contract execution, Mod 2 to "Multiple Averd Task Order Contract for ADP Development" Contractor Boeing Computer Sycs Co Compover Syck Co PERLMAN, J Administrative Contracts Branch FIN B-8166 NRC-33-83-452 83/05/25 BASSETT.H S . HARVES.J Office of Resource Management, Director ip 18734 072

- --8306030266 Mod 2, correcting subcontractor wage rate, to "Multiple Award Task Order Contract for ADP Development" HOPKINS, H R Boeing Computer Services, Inc (subs of Boeing Co) SMITH.P A Division of Contracts FIN B-8166 NRC-33-83-452 B3/05/25 ip 18734 073
- 8306030258 Notification of contract execution, Mod 1 to "Electrostatic Copying & Related Svcs " Contractor Literature Research CopERLMAN.J Administrative Contracts Branch NRC-10-83-318 83/05/19 BESAN, W J. BAGGETT, M Division of Technical Information & Document Control 1p 18734 074
- --8306030271 Mod 1.adding funds.to "Electrostatic Copying & Related Svcs " • Literature Research Corp SMITH,P A Division of Contracts NRC-10-83-318 83/05/19 ip 18734-075
- 8304030277 Notification of contract execution. Med 1 to "Radiation Monitoring Program Requirements" Contractor State of AR MCDERMOTT.D Technical Assistance Contracts Branch FIN D-8500 NRC-31-93-467 83/05/20 MEYERS.D M Region 4. Office of Director NICHOLAS.J B NRC - No Detailed Affiliation Given ip 18733 324
- --8306030284 Mod 1.increasing funding to FYB3 levels.to "Radiation Monitoring Program Requirements" * Arkansas. State of MORTON,K V Division of Contracts FIN B-8500 NRC-31-83-667 83/05/20 ip 18733 325
- 8305030400 Notification of contract execution "Hypocenter
 Determination of Regional Earthquakes" awarded to Univ of
 KY
 MURPHY,L Q Purchasing Section FIN B-9000 NRC-04-83-024
 83/03/27 ARSENAULT,F J Division of Health, Siting & Waste
 Management MURPHY,A J NRC No Detailed Affiliation Given 1
 18747 117
- --8306030402 Contract "Hypocenter Determination of Regional Earthquakes," awanded to Univ of KY MCDONALD.J Y Kentucky, Univ of * Division of Contracts FIN 8-9000 NRC-04-83-024 83/05/27 6pp 18747 118
- B306060391 Notification of contract execution "lith Water Reactor Safety Research Info Meeting," awarded to SA Stawlewict (CDERMOTT.D Technical Assistance Contracts Branch FIN 8-8943 NRC-04-83-005 83/04/28 BASSETT.D E Division of Accident Evaluation SULLIVAN.H NRC No Detailed Affiliation Given 1p 18730 233
- --8304040375 Contract "lith Water Reactor Safety Research Info Meeting," awarded to SA Szawlewicz, S A MORTON, K V Division of Contracts FIN 8-8943 NRC-04-83-005 83/04/28 3pp 18750 254
- --8306060397 Solicits proposals for lith water reactor research meeting Summary, instructions & solicitation package encl MORTON.K V Technical Assistance Contracts Branch R8-RE8-83-005 83/02/16 Affiliation Unknown 77pp 18750 257
- 8305070464 Notification of contract execution, Mod 4 to "Definition of Bounding Physical Tests Representative of Transport Accidents Air & Marine " Contractor IIT Research Inst MCLETT.8 Technical Assistance Contracts Branch FIN 8-7570 NRC-04-81-203 83/05/18 FOREHAND.8, Office of Nuclear Regulatory Research, Director LAHS.W NRC No Detailed Affiliation Given 19 18780 333
- ---B305070455 Mod 4, extending period of performance to 830921, to "Definition of Bounding Physical Tests Representative of Transport Accidents Air & Marine" PLONIS, T R IIT Research Inst OUSTAVE, R P Division of Contracts FIN B-7870 NRC-04-81-203 83/05/18 ip 18780 334
- 8304080067 Notification of contract execution, Mod 2 to "Audit of NRC Eupergrade Positions" Contractor Damans & Assocs SHITH,P A Division of Contracts NRC-10-77-140 83/06/02 BIRD.P E Division of Organization and Personnel 1p 18787 295
- --8306080072 Mod 2, finalizing final indirect rates & incorporating rates into contract per General Provisions Clause 34 % deobligating unliquidated balance, to "Audit of NRC Supergrade Positions."

 CASANAVE.N Damans & Associates SMITH.P.A Division of Contracts NRC-10-77-140 83/06/02 2pp, 18787 296
- 830&080413 Notification of contract execution, Mod 2 to "Word Processing Bycs " Contractor Keyboard Communications, Inc MCLEAREN, T Administrative Contracts Branch NRC-10-83-296 83/06/01 STECLE, M Division of Technical Information & Document Control JOHANSEN, J Cress Branch 1p 18792, 182

- --8306080417 Mod 2,increasing funding ceiling to "Hord Processing Svcs "
 * Keyboard Communications, Inc. SMITH.P A. Division of
 Contracts NRC-10-83-296 83/06/01 1p 18792 183
- 8306080419 Notification of contract execution. Mod 20, to "FLECHT-SEASET" Contractor Westinghouse/EPRI MOLLETT.S Technical Assistance Contracts Branch FIN 8-6204. NRC-04-77-127 83/05/24 BATSON.W Office of Nuclear Regulatory Research, Director LEE,R NRC No Detailed Affiliation Given 1p 18792 184
- --8306080427 Ltr contract, Mod 20, changing ceiling amounts, to "FLECHT-BEASET"

 GUSTAVE, R P Technical Assistance Contracts Branch. FIN 8-6204 NRC-04-77-127 83/05/19 ROSENBLATT, H Wastinghouse Electric Corp ip 18792 185
- B304090277 Notification of contract execution, Mod 1 to "Gregg Shorthand Theory Review" Contractor Montgomery County, MD Public Schoola SMITH, P A Division of Contracts NRC-10-79-665 B3/03/09 DDRIE, W M Office of Administration VAN SANTEN, L NRC Na Detailed Affiliation Olven ip 18810,047
- --8306090280 Mod 1.deobligating funds to enable final contract closeout, to "Gregg Shorthand Theory Review"
 PASCOE, 8 Maryland, State of SMITH,P A Division of Contracts NRC-10-79-665 83/05/09 1p 18860:048
- 8306090282 Notification of contract execution, Mod 2 to "Records Holding Area Support Sves." Contractor SBA Subcontractor Maxima Corp MCLEAREN, T Administrative Contracts Branch NRC-10-82-396 83/06/02 BESAH, W J Division of Technical Information & Document Control SCOTT, R S NRC No Detailed Affiliation Given 1p 18810 032
- --8306090284 Mod 2, extending period of performance to 840613 & increasing funding to "Records Holding Area Support Sycs"

 * Small Business Administration * Maxima Corp SMITH,P. A Division of Contracts NRC-10-82-376 83/06/02 2pp 18810-033.
- 8306070447 Natification of contract execution. Med 1 to "Licensing Technical Assistance" Contractor Science Applications. Inc FLYNN.M J Technical Assistance Contracts Branch FIN B-7337-3. NRC-02-B3-035 83/05/27 DAVIS.J Defice of Nuclear Material Safety & Safeguards. Director LOYSEN.P. NRC No Detailed Affiliation Given 1p 18815-145
- --8306070452 Mod f.issuing fully definitized Task Order 004 & increasing funding to "Licensing Technical Assistance,"
 FINDLEY.D E Science Applications, Inc. QUSTAVE.R P. Division of Contracts FIN 8-7339-3. NRC-02-83-035 83/05/27 App
- 8304070447 Notification of contract execution, Mod 14 to "Improved Ultrasonic NDT of Pressure Vessels" Contractor Univ of MI FLYNN, M J Technical Assistance Contracts Branch NRC-04-75-182 83/05/25 FOREHAND, W Office of Nuclear Regulatory Research, Director MUSCARA, J NRC No Detailed Affiliation Given 1p 18815 154
- --8306090470 Mod id, changing period of performance to 830228 & adding paragraph to Article IV, to "Improved Ultrasonic NDT of Pressure Vessels"

 DALRYMPLE, J T Michigan, Univ of, GUSTAVE, R P. Technical Assistance Contracts Branch NRC-04-75-182 83/05/25 2pp, 4885-158
- 8306090484 Notification of contract execution Mod 5 to "Benchmarking of Computer Codes & Licensing Assistance" Contractor, Teknekron Research Inc.
 FLYNN-M J Technical Assistance Contracts Branch FIN 8-6985, NRC-02-81-026 83/05/25 DAVIS, J Office of Nuclear Material Bafety & Safeguards, Director. FEMRINGER, D J NRC No Detailed Affiliation Given. 1p. 18815-159
- --8306090488 Mod 5, exercising option for performance of Tasks 4 & 5, providing incremental funding & substituting key personnel, to "Benchmarking of Computer Codes & Licensing Assistance." VQQT,D.K Tekneiron Research, Inc QUSTAVE,R P. Technical Assistance Contracts Branch FIN B-4985 NRC-02-81-026. B3/05/25 4pp 18815 160
- B306140228 Notification of contract execution. "BWR Nuclear Engineering Courses." awarded to QE. HCDERMOTT.D Technical Assistance Contracts Branch FIN B-8710. NRC-05-B3-219. B3/05/18 BLAHA.J L Program Support Branch. HAVENS.D H NRC - No Detailed Affiliation Given 1p. 18844 325

- --8306140238 Contract "BMR Nuclear Engineering Courses."

 awarded to GE
 PIERCE.R C Deneral Electric Co MORTON.K V Division of
 Contracts FIN 8-8710. NRC-05-83-219 B3/05/18 5pp
 18844 326
- 8306140421 Notification of contract execution, Mod 9 to "Study of Chemical Toxicity of Low Level Waste" Contractor General Research Corp SILVIBAR M Technical Assistance Contracts Branch FIN 8-6127 MRC-02-77-183 83/06/03 DAVIS.J @ Office of Nuclear Material Safety & Safety
- --8306140426 Mod 9, deobligating unliquidated balance, to "Study of Chemical Toxicity of Low Level Hasts"

 ANDERSON, D J General Research Corp GUSTAVE, R P Division of Contracts FIN 8-6127 NRC-02-77-183 83/06/03 1p 18834 063
- 8306140433 Notification of contract execution Mod 2 to "Reviewing Hydrogeologic Investigations of Nevada Tast Site Project C " Contractor Williams-Robinette & Assoc. Inc SILVIS.R M. Technical Assistance Contracts Branch FIN 8-7377-2 NRC-02-82-446 83706/03 DAVIS.J 9 Office of Nuclear Material Bafety & Safegyards. Director. POHLE.J A NRC No Detailed Affiliation Given 1p 18854 064
- --8306140438 Mod 2, adjusting consulting hours of svc. to "Reviewing Hydrogeologic Investigations of Nevada Test Site Project C."

 HILLIAMS.R E. Williams-Robinotte & Associates, Inc GUSTAVE.R P Division of Contracts. FIN 8-7377-2 NRC-02-82-046 83/06/03 ip 18854 045
- 8306130246 Notification of grant execution "Criteria & Procedures for Low Level Radwaste Mgt." awarded to Conference of Radiation Control Program Directors.Inc.

 MCDERMOTT.D. Technical Assistance Contracts Branch FIN 0-1049-NRC-0-04-83-003 83/06/07 BATSON,W Office of Nuclear Regulatory Research, Director, KIM.K NRC No Detailed Affiliation Given ip 18870 047
- --8306150251 Grant "Criteria & Procedures for Low Level Radwasts Mgt,"
 awarded to Conference of Radiation Control Program
 Directors, Inc."
 SHEALY,M. Q. Conference of Radiation Control Program Directors,
 Inc. MCRTON,K V. Technical Assistance Contracts Branch FIN
 Q-1049 NRC-Q-04-83-005 83/06/07 2pp. 18870 048.
- 8306130485 Notification of contract execution "Radiation Monitoring Progres Requirements," awarded to State of LA MCDERMOTT, D. Technical Assistance Contracts Branch FIN 8-8502 NRC-31-83-667 83706/01. MEYERS, D M Region 4, Office of Director NICHOLAS, J. B NRC No Detailed Affiliation Given 1p 18869 001
- --83061504BB Contract: "Radiation Monitoring Program Requirements," awarded to State of LA SIMOMEAUX.F P. Louislana, State of MORTON, K V Administrative Contracts Branch FIN B-8502 NRC-31-83-669. 83/06/01 18pp 18868 002
- 8306150906 Notification of contract execution: "Investigation of Alternative Means to Accomplish Goals of Biennial Calibr of Ionization Chambers," awarded to Univ of WI MCDERHOTT, D.K. Technical Assistance Contracts Branch FIN B-8906 NRC-04-83-002 83/06/01. BATSON, W Diffice of Nuclear Regulatory Research, Director. RODENBECK, E. NRC No Detailed Affiliation Olven. 1p. 18866, 298.
- --8306150521 Contract "Investigation of Alternative Means to Accomplish Gasis of Biennial Calibr of Ionization Chambers," awarded to Univ of HI ERICKBOM:R H Wisconsin, Univ. op, Madison MORTON, K V. Division of Contracts FIN 8-8906 NRC-04-83-002 83/06/01 17pp 18866.276
- 8306130360 Notification of contract execution, Mod 10 to "Site Suitability Assessments Based on Sepage & Groundwater Conditions Associated WV Necovery Operations "Contractor Hilliams Robinstee & Assoc.

 DELDATCH.Y. Technical Assistance Contracts Brench, NRC-02-81-039 B3/06/03. DAVIS.J. G. Office of Nuclear Material Safety & Safeguards, Director SIEFMEN NRC No Detailed Affiliation Given ip. 18834, 360.
- --8306180870 Hod 10.modifying period of performance, to "Bite Switability Assessments Based on Beepage & Groundwater Conditions Associated W/U Recovery Operations "
 HILLIAMS.R E. Williams-Robinette & Associates, Inc GUBTAVE, R P
 Administrative Contracts Branch. NRC-02-81-039 83/06/03 1p
 18654:361

- B306160040 Notification of contract execution.Mod 4 to "Followon Earthquake Ground Motion" Contractor Univ of Californía at San Diego MURPHY.L G Administrative Contracts Branch FIN B-6898 NRC-03-80-143 83/06/06 VOLLMER.R Division of Engineering JACKSON.R NRC No Detailed Affiliation Civen ip 18392 336
- --8306160045 Mod 4, deleting reporting requirements, to "Followon Earthquake Ground Motion"

 California, Univ of San Diego REBELLO, J Division of Contracts FIN 8-6898 NRC-03-80-143 83/06/06 ip [6892 337
- 8306i60259 Notification of contract execution, Mod 9 to "Memphis Area Regional Seismic Network" Contractor Memphis State Univ. FIELDS. JA Technical Assistance Contracts Branch NRC-04-78-200 83/05/27 BATSON.W Office of Nuclear Regulatory Research. Director JOHNSON.A c NRC - No Detailed Affiliation Given 1p 18893 020
- --8306160273 Mod 9: incorporating App A to modify govt property, to "Mamphis Area Regional Selamic Network"

 CARPENIER, T O Memphis State Univ GUSTAVE, R P Division of Contracts. NRC-04-78-200 83/05/27 4pp 18893 021
- 8306170026 Notification of contract execution "A/E Design Svcs for Installation of Shielded Encl." awarded to EK Fox & Assoc.

 Ltd.

 8AZIN.JP Administrative Contracts Branch NRC-10-B3-334

 83/04/08 CORLEV.J H Division of Facilities & Operations
 FISHER.L NRC No Detailed Affiliation Given 1p 18907 349
- --830&170029 Contract "A/E Design Svcs for Installation of Shielded Encl." awarded to EK Fox & Assoc.Ltd FOX.E K E K Fox & Associates, Ltd MATTIA.M J Division of Contracts NRC-10-83-334 B3/04/08 7pp 18907 350
- B306170253 Notification of contract execution, Mod 5 to "Licensing Assistance/Tailings Mgt Program Technical Evaluation "Contractor Geotechnical Engineers. Inc FIELDS. J A Research Contracts Branch NRC-02-79-031-01 B3/05/27 DAVIS, J Office of Nuclear Material Safety & Safeguards. Director ROSSBACH.L NRC No Detailed Affiliation Given 1p 18908 014
- --8306170289 Mod 5.extending period of performance to 830930 at no addl cost, to "Licensing Assistance/Tailings Mgt Program Technical Evaluation"

 CABTRO. G Geotechnical Engineers, Inc GUBTAVE Administrative Contracts Branch NRC-02-79-031-01 83/05/27 1p 18908 015
- B306i70463 Notification of contract execution, Mod 6 to "Career Counseling" Contractor Binder, Elster, Mendelson & Wheeler PERLMAN, J Administrative Contracts Branch NRC-10-92-338 B3/06/15 DURIE: W Office of Administration VAN SANTEN, L W NRC No Detailed Affiliation Given ip 18706-349
- --8306170466 Mod 6. allowing for quarterly payments for regional liaison svcs. to "Career Counseling " MENDELSON.I N Binder Elster, Mendelson & Wheeler, Inc SMITH, P A Administrative Contracts Branch NRC-10-82-358 83/06/15 1p 18906 350
- B3G61704B0 Notification of contract execution Mod I to "Environ Assessments & Impact Statements for Low Level Waste Disposal Facilities " Contractor Battelle Columbus Labs FLEENOR.C Technical Assistance Contracts Branch NRC-02-B2-026-10 B3/05/27 DAVIS.J Office of Nuclear Material Safety & Bafaguards, Director. NEUDER.S M NRC - No Detailed Affiliation Qivan ip 18874 3:17
- ~-8306170482 Mod 1.extending period of agreement to 850930.incorporating microfiche requirements & project officer.to "Environ Assessment & Impact Statements for Low Level Waste Disposal Facilities"
 LUKZ.F.J. Battelle Memorial Institute, Columbus Laboratories GUSTAYE, R.P. Administrative Contracts Branch NRC-02-82-026-10 83/05/27 3pp 18894 318
- 8306170484 Notification of contract execution.Mod 3 to "Environ Assessments & Impact Statements for Low Level Waste Disposal Facilities." Contractor Versar.Inc FLEENDR.C. Technical Assistance Contracts Branch NRC-02-82-026-04 83/06/03 DAVIS.J Office of Nuclear Material Safety & Safegwards.Director. NEUDER.S M NRC No Detailed Affiliation Oiven 2pp. 18894 305
- ~-8306170483 Mad 3, extending period of agreement to 830930 & incorporating project officer, to "Environ Assessments & Impact Statements for Low Level Maste Disposal Facilities," ROGERS: W H Versar, Inc GUSTAVE, R P Administrative Contracts Branch NRC-02-82-026-04 83/06/03 1p 18894-306

- 830520012B Notification of contract execution, Mod 2 to "Audiovisual Consultant 8vcs" Contractor N Hall
 PERLMAN, J Administrative Contracts Branch FIN 8-8181
 NRC-17-83-398 83/05/07 CHILK, S . MAGRE, W Office of the
 Secretary of the Commission ip 18908 268
- --8306200634 Mod 2.extending period of performance to 830730,to "Audiovisual Consultant 8vcs"
 HALL.N M Hall, N SMITH,P A Division of Contracts FIN 8-8181 NRC-17-83-378 83/06/07 1p 18708 269
- 8306200224 Natification of contract execution, Mod & to "Statistical Analysis Study " Contractor & Wolfbein GILDENMURN, A Administrative Contracts Branch BY06/06 DORIE, W Office of Administration DAMBLEY, D Office of the Executive Legal Director ip 18909 355
- --8306200287 Mod 6.extending period of performance to 840601 at no addl cost.to "Statistical Analysis Study " WDLFBEIN,8 L Wolfsbein,S L SMITH.P A Division of Contracts NRC-10-80-694 83/06/06 1p 18909 356
- 8306210339 Notification of contract execution Mod 11 to "Evaluation of Mat1 Accounting Performance at Nuclear Fuel Cycle Facilities " Contractor NUSAC, Inc FIELDS, J. A. Technical Assistance Contracts Branch NRC-02-81-028 83/06/03 DAVIS, J. Office of Nuclear Material Safety & Safeguards, Director MILLER, M. NRC No Detailed Affiliation Given 16, 18921-332
- --B306210344 Hod II.correcting Mod 8 numbering to Mod 10.to "Evaluation of Matl Accounting Performance at Nuclear Fuel Cycle Facilities"

 * NUSAC, Inc GUSTAVE,R P Division of Contracts, NRC-02-B1-028 83/06/03 ip 18721 333
- 8306210364 Notification of contract execution, Mod 5 to "Personnel Neutron Dosimetry for Nuclear Power Plants " Contractor Assistance Polytechnic Inst SttV18,R M Technical Assistance Contracts Branch FIN 9-6651 MRC-04-78-263 83/09/31. FOREHAND W Office of Nuclear Regulatory Research, Director FOULKE, J NRC No Detailed Affiliation Given ip 18937 094
- --8305210371 Mod 5, extending period of performance to 830228, to "Personnel Dosimetry for Nuclear Power Plants" LOGIUDICE, J M Rensselver Polytechnic Inst GUSTAVE, R P Division of Contracts FIN 0-6651 NRC-04-78-263 83/05/31 2pp 18937 095
- 8306210370 Notification of contract execution, Mod 4 to "Licensing Assistance/Geotechnical & Hydrological Evaluations "Contractor Intl Engineering Co FIELDS, J A Technical Assistance Contracts Branch NRC-02-80-033-04 83706/03 DAVIS, J Défice of Nuclear Material Bafety & Safeguards, Director GARCIA, P NRC No Detailed Affiliation Given ip 18937-086
- --3306210373 Mod 4.extending period of performance to 830930.to
 "Licensing Assistance/Geotechnical & Hydrological
 Evaluations"
 CHRISTEMBEN, R International Generation & Transmission Co , Inc
 GUSTAVE, R P Division of Contracts NRC-02-80-033-04 83/06/03
 1p 18937 087
- B306210376 Notification of contract execution:Mod 1 to "Advisory Committee for Const During Adjudication " Contractor Berle: Butzel Kass & Case
 SMITH-P A Division of Contracts FIN B-1560 NRC-17-79-701
 B3706/16 HQLE.J C Office of the Secretary of the Commission BERSON:B NRC No Detailed Affiliation Qiven 1p 18937:088
- --8306210384 Mod 1.deobligating funds for closeout, to "Advisory Committee for Const During Adjudication" 8 Berle, Buttel, Kass & Case SMITH, P A Division of Contracts FIN 8-1540 NRC-17-79-701 83/06/16 ip 18937 089
- 8306210381 Notification of contract execution. Mod 2 to "Licensing Assistance/Tailings Mgt Program Technical Evaluation" Contractor Simons. Li & Assoc. Inc. FIELDS. J. A Fechnical Assistance Contracts Branch NRC-02-79-031-06 83/05/27 DAVIS. J. Office of Nuclear Material Safety & Safeguards, Director CILLEN, D. NRC No Datailed Affiliation Given 1p. 18937 082
- ---8304210384 Mod 2:extending period of performance to 830930,to
 "Licensing Assistance/Tailings Mgt Program Technical
 Evaluation"
 SIMONS, D B Simons, Li & Associates, Inc. QUSTAVE.R.P. Division
 of Contracts NRC-02-79-031-06, 83/03/27 ip 18937-083.

- 8304210391 Natification of contract execution Mod 1 to "Lab Studies Dynamic Response of Prototypical Piping Bys " Contractor Anco Engineers, Inc & EPRI BAISDEN,L Technical Assistance Contracts Branch FIN B-B907 NRC-04-82-025 83/06/10 FOREHAND.W Office of Nuclear Regulatory Research Director D'BRIEN,J NRC No Detailed Affiliation Given 10 18935-289
- --8306210397 Ltr Contract Mod 1 to NRC-04-B2-025, increasing funds, to "Lab Studies Dynamic Response of Prototypical Piping Sys " MORTON.K V Technical Assistance Contracts Branch Fin B-8907 NRC-04-B2-025 83/06/10 HOHARD.G E ANCO Engineers, Inc 1p. 18935 290
- 8306210421 Notification of contract execution "Radiation Monitoring Program Requirements," awarded to Environ Surveillance Lab MCDERMOTT.D Technical Assistance Contracts Branch FIN B-8550 NRC-32-83-681 83/06/16 ALEXANDER.I Division of Resourca Management & Administration. HAHADA.G NRC No Detailed Affiliation Civen Ip. 18937 048
- ---B306210432 Contract "Radiation Monitoring Program Requirements,"
 awarded to Environ Burveillance Lab
 TEDFORD, C F Environmental Surveillance Laboratory, MORTON, K V.
 Division of Contracts, FIN 9-8850 NRC-32-83-681 83/06/16
 1699 18937-049
- 8306220073 Notification of contract execution "Autoprint F Microfiche Printer," awarded to Bubell/Ware & Assoc. Inc COLEMAN: R Amministrative Contracts Branch NRC-10-83-340 83/06/02 BESAW,W Division of Technical Information & Document Control SKOCZLAS.J NRC No Detailed Affiliation Given Ip 18947 311
- --8306220091 80]icitation, offer & award of "Autoprint F Microfiche Printer" to Bybell/Mare & Assoc, Inc WARE, J T Bybell/Mare & Associates, Inc MATTIA, M J Division of Accounting & Finance NRC-10-83-340 83/06/02 59pp 18747 312
- 8304220133 Notification of contract execution, Mod 7 to "Computer Time-Sharing & Related Bycs," Contractor NIH.
 PERLMAN, J Administrative Contracts Branch FIN B-1666.
 NRC-23-82-312 83/06/06 BASBETT, H 8 KIRK, I., BANDINI, B, Office of Resource Management, Director ip 19748,087
- --8306220138 Mod 7,designating JA Shields as project officer, to "Computer Time-Sharing & Related Sycs"

 * HHS, Dept, of, US Public Health Service SMITH,P A Division of Contracts, FIN 8-1646 NRC-25-82-312 63/06/06. 1p.
- 8306220151 Notification of contract execution Mod 7 to "Licensing Review of OL Applications." Contractor Naval Surface Heapons Ctr SILVI8.R M Technical Assistance Contracts Branch. FIN 8-6878 NRC-03-80-107. 83/06/10. VOLLMER.R Division of Engineering RINALDI.F NRC No Detailed Affiliation Given 1p 18737-337.
- --8304220158 Mod 7.extending period of performance to 830930, modifying statement of work & obligating addl funds to "Licensing Review of DL Applications"
 ROBERTS.E.S. Navy. Papt of. GUBTAVE.R P. Technical Assistance Contracts Branch FIN 8-4878 NRC-03-80-109. 83/06/10 2pp.
- 8304220146 Notification of contract execution "Radiation Monitoring Program Requirements," awarded to State of HD MCDERMOTT, D. Technical Assistance Contracts Branch FIN 8-8353. NRC-28-89-608 83/06/16 MCG8CAR, J. Region 1. Office of Director COSTELLO, F. NRC No Detailed Affiliation Given ip 18937;305.
- --8306220168 Contract. "Radiation Monitoring Program Requirements," awarded to State of MD.
 RESH.D L Maryland. State of * NRC No Detailed Affiliation Given FIN 8-8333. NRC-28-83-408 83/06/16. 13pp. 18937:306.
- B306220186 Notification of contract execution. Mod 26 to "Review & Evaluation of Approx 500 Pending Operating Reactors Licensing Actions" Contractor. Franklin Inst. FLYNN.M Technical Assistance Contracts Branch. FIN 8-6370. NRC-03-79-118 B3/06/15. EISENHUT.D G. BAJWA.S. Division of Licensing 1p 19751.045.
- --8306220192 Mod 26.extending period of performance for GO days at no addl cost & deobligating funds from residual fee, to "Review & Evaluation of Approx 500 Pending Operating Reactors Licensing Actions"

 ASHTON.A.M. Franklin Institute/Franklin Research Center QUSTAVE.R.P Division of Contracts. FIN B-6590. NRC-03-79-118 B3/06/15. 3pp. 18951-046

- B306220217 Notification of contract execution, Mad 6 to "Eastern Tannesser/Hestern North Carolina Regional Seismic Notwork "Contractor Memphis State Univ SILVIS:R K Technical Assistance Contracts Branch FIN 8-6675 NRC-04-779-214 B3/09/31 BATSON,W Office of Nuclear Regulatory Research, Director MURPHY, A NRC No Detailed Affiliation Given in 1898
- --8306220222 Mod 6, vesting title to property in NRC, to "Eastern Tennessee/Hestern North Carolina Regional Seismic Network" * Tennessee, State of GUSTAVE, R P Technical Assistance Contracts Branch FIN 8-6675 NRC-04-79-214 83/05/31 2pp 18980 360
- 8305220220 Notification of contract execution.Mod 3 to "Environ Assessments & EIS for Low Level Waste Disposal Facilities"

 Contractor Engineering-Science, Inc
 FLEENOR.C Technical Assistance Contracts Branch NRC-02-82-026-08

 83/06/10 DAVIS.J. Office of Nuclear Material Safety & Safeguards. Director. NEUDER.S NRC No Detailed Affiliation Given ip 18750-355
- --8306220227 Mod 3.extending period of performance to 890930 & incorporating new project officer, to "Environ Assessments & E18 for Low Level Waste Disposal Facilities "TISCHLER,L F Engineering Science GUSTAVE,R P Division of Contracts NRC-02-82-026-08 83/06/10 1p 18950 356
- B30622029 Notification of contract execution, Mod 8 to "Fuel Cycle Project Review " Contractor Science Applications Inc WOLLETT, 8 Technical Assistance Contracts Branch FIN 8-6694 NRC-04-80-178 83/06/10 FOREHAND, W Office of Nuclear Regulatory Research, Director ENG, C NRC - No Detailed Affiliation Given 10. 18977 353
- --8306220233 Mod 8.extending period of performance to 830530, to "Fuel Cycle Project Review" FELDMAN.S A Science Applications. Inc GUSTAVE.R P Division of Contracts FIN 8-6694 NRC-04-80-178 83/06/10 ip 18977 354
- 8306220238 Notification of contract execution. Mod 2 to "Licensing Assistance/Tailings Mgt Program Technical Evaluation "Contractor Energy Resources Co FIELDS.) A Technical Assistance Contracts Branch NRC-02-79-031-07 83/06/15 DAVIS.J Office of Nuclear Material Safety & Safeguards. Director GILLEN, D NRC No Detailed Affiliation Given 1p 18777 032
- --8306220241 Mod 2.extending period of performance to 830930 to "Licensing Assistance/Tailings Mgt Program Technical Evaluation "
 - **Energy Resources Co., Inc. GUSTAVE.R P Division of Contracts NRC-02-79-03:-07 B3/06/15 ip 18977 033
- B308220244 Notification of contract execution, Mod i to "California Offshore Radiological Licenses Survey " Contractor State of CA HOYLE, A Administrative Contracts Branch FIN B-8705 NRC-03-82-254 B3/06/10 BLAHA, J L Program Support Branch YACZKO, C T NRC - No Detailed Affiliation Given Ip 18951 114
- ~-8306220246 Mod 1.extanding period of performance to 830630 to
 "California Diffshore Radiological Licensee Survey"

 California State of REBELLO, J E Division of Contracts FIN
 8-8705 NRC-05-82-254 83/06/10 ip 18951 115
- 8306220247 Notification of contract execution. Mod 3 to "Environ Assessments & E18 for Low Level Waste Disposal Facilities." Contractor Kaman Tempo FLEENGR.C Technical Assistance Contracts Branch NRC-02-82-026-05 83/06/10 DAVIS.J Office of Nuclear Material Safety & Safeguards. Director NEUDER.S NRC No Detailed Affiliation Given to 18951.071
- --8306220255 Mod 3.extending period of performance to 850930 & incorporating new project officer, to "Environ Assessments & E18 for Low Level Waste Disposal Facilities "FOXMELLD O Kamen Tempo GUSTAVE.R P Division of Contracts NRC-02-82-026-05 83/06/10 IP 18751 072
- 8306220253 Notification of contract execution, Mod 2 to "Reviewing Hydrologic Investigations of Basalt Maste Isolation "Contractor Williams-Robinette & Assoc FLEENORIC Tachnical Assistance Contracts Branch NRC-02-82-044 83706/03 DAVIS, J Office of Nuclear Material Bafety & Safguards, Director LOOSDDN, M NRC No Detailed Apfiliation Given ip 18951-066
- --8306220257 Mod 2, revising indirect rates & designating new project officer, to "Reviewing Hydrologic Investigations of Basalt Hasta Isolation"

 WILLIAMS.R. Williams-Robinstte & Associates, Inc. GUSTAVE.R.P., Division of Contracts NRC-02-82-044, 83/06/03, 2pp 18751-067

- B306220262 Notification of contract execution.Mod 3 to "Environ Assessments & EIS for Low Level Waste Disposal Facilities" Contractor Envirosphere Co FLEENOR.C Technical Assistance Contracts Branch NRC-02-82-026-09 B3/06/10 DAVIS.J Office of Nuclear Material Safety & Safeguards, Director NEUDER, S NRC No Detailed Application Given ip 18951 052
- --8306220266 Mod 3. extending period of performance to 850930 & incorporating new project officer to "Environ Assessments & E18 for Low Level Wasto Disposal Facilities"

 0. ODNNELL, E P Envirosphere Co GUSTAVE, R P Division of Contracts NRC-02-82-026-09 83/06/10 1p 18951 053
- 8306220267 Notification of contract execution, Mod 13 to "Transport/Fixed Site Vulnerability Analysis" Contractor US Army JF Kennedy Ctr FIELDS, J A Technical Assistance Contracts Branch NRC-02-76-311 83/06/03 DAVIS, J Office of Nuclear Material Safety & Safeguards, Director CAWLEY, J NRC - No Detailed Affiliation Given ip 18751 050
- --8304220272 Mod i3, extending period of performance to 831231, to "Transport/Fixed Site Vulnerability Analysis " WEBB,D Army, Dept of GUSTAVE,RP Division of Contracts NRC-02-74-311 83/06/03 ip 18951 081
- 8304220269 Notification of contract execution Mod 3 to "Environ Assessment & EIS for Low Level Waste Disposal Facilities" Contractor Science Applications. Inc FLEENOR.C Technical Assistance Contracts Branch NRC-02-82-026-07 83/06/10 DAVIS.J Office of Nuclear Material Safety & Safeguards. Director NEUDER.S NRC No Detailed Affiliation Given 1p 16977 165
- --8306220276 Mod 3, extending period of performance to 830930 & incorporating new project officer, to "Environ Assessments & EIS for Low Level Waste Disposal Facilities "PASQUAM P Science Applications, Inc GUSTAVE, R P Division of Contracts NRC-02-82-026-07 83/06/10 ip 18977 166
- 8304220277 Notification of contract execution, Mod 4 to "Demographic Projections & Regional Economic Impacts of Accidents "Contractor Dept of Commerce FIELDS, J A Technical Assistance Contracts Branch FIN B-8044 NRC-03-82
- --8306220282 Mad 4, revising reporting requirements, extending period of performance to 830930 & modifying funding to "Demographic Projections & Regional Economic Impacts of Accidents"
 Draft monthly business ltr rept encl
 TROTTLE Commerce, Dept of, QUSTAVE, R P Division of Contracts FIN 8-8044 NRC-03-82-112 83/06/06 4pp
- 830622028A Notification of contract execution, Mod 3 to "Maint of Data General Computers & Peripheral Equipment" Contractor Data Consultants. Inc
 PERLMAN. J Administrative Contracts Dranch FIN D-1663
 NRC-25-82-311 83/05/31 BASSETT. H Office of Resource
 Management, Director JOHNSON, CR NRC No Detailed Affiliation Given Ip 18940 353
- --8306220289 Mod 3, adding funds, to "Maint of Data General Computers & Peripheral Equipment"

 * Data Consultants, Inc SMITH, P A Division of Contracts FIN B-1663 NRC-28-82-311 83/09/31 1p 18940 354
- 8306220302 Nutification of contract execution, Mod 4 to "Licensing Assistance/Geotechnical & Hydrological Evaluations" Contractor Geotechnical Engineers, Inc FIELDB, J A Technical Assistance Contracts Branch NRC-02-80-023-01. 83/06/03 DAVIS, J Office of Nuclear Material Safety & Safeguards, Director GARCIA, P NRC No Detailed Affiliation Given. Ip 18740 277
- --8306220305 Mod 4, extending period of performance to 830930, to "Licensing Assistance/Gentechnical & Hydrological Evaluations" CASTRU, G. Geotechnical Engineers, Inc. QUSTAVE, R.P. Division of Contracts NRC-02-80-033-01
- 8306220316 Notification of contract execution. Mod 3 to "Environ Assessments & Impact Statements for Low Level Waste Disposal Facilities " Contractor H & R Technical Assoc, Inc PLEEMOR, C Technical Assistance Contracts Branch NRC-02-82-026-01 83/06/03 DAVIS, J Office of Nuclear Material Safety & Safeguards, Director NEUDER, S M NRC No Detailed Affiliation Given 1p. 18740 297

- --8306220320 Mod 3 extending period of performance to 850930 & designating project officer, to "Environ Assessments & Impact Statements for Low Level Waste Disposal Failities RHYME, W R H&R Technical Associates, Inc. GUSTAVE, R P. Division of Contracts. NRC-02-82-026-01 83/06/03 1p 18940 298
- 8306220324 Notification of contract execution.Mod 18 to "Reactor Effluent & Environ Radioactivity Stds " Contractor NBS WDLLETT.S A Technical Assistance Contracts Branch FIN 8-5118 NRC-05-72-100 83/05/27 BLAHA.J L Director's Office, Office of Inspection and Enforcement COHEN.L NRC - No Detailed Affiliation Given ip 18977 147
- --8306220327 Mod 18, providing scope of work for FY83, extending period of performance to 830930 % increasing Commission support, to "Reactor Effluent & Environ Radioactivity Stds "
 SHREVE, D B Commerce, Dept of, National Bureau of Standards GUSTAVE, R P Division of Contracts FIN 8-5118 NRC-05-72-100 83/05/27 2pp 18977 148
- B306230041 Notification of contract execution "Technical Assistance in Defense of Appeal of TERA Advanced Svcs Corp (TABC)
 Before GSA Board of Contract Appeals Analyse Technical Aspects of TABC Case ," awarded to Dataflow Sys,inc TOWNSEND.B L Administrative Contracts Branch NRC-10-83-96B S3/06/07 NORTY,P Q Office of Administration AVERY,R E NRC No Detailed Affiliation Given 1p 18954 344
- --8306230048 Contract "Technical Assistance in Defense of Appeal of TERA Advanced Svcs Corp (TASC) Defore QSA Board of Contract Appeals Analyse Technical Aspects of TASC Case , awarded to Dataflow Sys.Inc Statement of work encil BQUBNIKQFF.B Dataflow Systems. Inc REBELLO, J E Division of Contracts NRC-10-83-368 83/06/07 4pp 18954 345
- 8306230054 Notification of contract execution Mod 3 to "Licensing Assistance/Geotechnical & Hydrological Evaluations" Contractor Converse Ward Davis Dixon. Inc PIELOS. J Technical Assistance Contracts Branch NRC-02-80-033-07 83/05/27 DAVIS. J Office of Nuclear Material Safety & Safeguards. Director GARCIA.P NRC No Detailed Affiliation Given ip 18982 184
- --8306830039 Med 3.extending period of performance to 830930.to
 "Licensing Assistance/Geotechnical & Hydrological
 Evaluations "
 LEBKYB.A 9 Converse, Ward, Davis, Dixon, Inc. 9USTAVE.R.P
 Division of Contracts NRC-02-80-033-07 83/05/27 1p
 18982 185
- B305230192 Nutification of contract execution.Mod 4 to "Licensing Assistance/Geotechnical & Hydrological Evaluations "Contractor Leeds.Hill & Jewett.Inc FIELDS.J A Technical Assistance Contracts Branch NRC-02-80-033-02 83/06/14 DAVIS.J Office of Nuclear Material Safety & Safeguards.Director OARCIA.P NRC No Detailed Affiliation Given 1p 18954 355
- --B306230198 Mod 4, extending period of performance to 830930, to "Licensing Assistance/Geotechnical & Hydrological Evaluations"

 * Leeds, Hill & Jewett, Inc. GUSTAVE, R P. Division of Contracts NRC-02-80-033-02 83/06/14 1p 18954 356
- B304230218 Notification of contract execution "Foreign Fuel Cycle Data," awarded to Nuclear Assurance Corp Hi001Nauarded to Nuclear Assurance Corp Hi001Nauarded Sala Division of Contracts FIN 8-7382-3 NRC-02-83-036 83/03/31 DAVIS.J Office of Nuclear Material Safety & Safeguards, Director THOMAS, B NRC No Detailed Affiliation Given | Ip 18981 324
- --B306230220 Contract "Foreign Fuel Cycle Data:" awarded to Nuclear Assurance Corp DDIRON:D 9 Nuclear Assurance Corp MDRTON:K V Division of Contracts FIN B-7382-3 NRC-02-83-036 83/03/31 65pp 18981 325
- 8304230485 Notification of contract execution. Mod i to "Radiation Monitoring Program Requirements" Contractor State of TX SILVIS.R M Technical Assistance Contracts Branch FIN B-8504 NRC-31-83-671 83/06/14 MEYERS.D M Region 4. Office of Director NICOHOLAS.J B NRC No Detailed Affiliation Given ip 18982 040
- --8306230491 Mod 1, providing CY83 funding & changing B&R number to 94-19-30-02, to "Radiation Monitoring Program Requirements" MACLEAN, R Texas, State of GUSTAVE, R P Technical Assistance Contracts Branch FIN 8-8504 NRC-31-83-671 83/06/14 1p

- 8306230494 Notification of contract execution. Mod 2 to "Radiation Munitoring Program Requirements" Contractor State of NE SILVIS,R M Technical Assistance Contracts Branch FIN 8-8503 NRC-31-83-670 83706/15 MEYERS.D M Region 4. Office of Director NICHOLAS.J B NRC No Detailed Affiliation Diven to 18982 038
- ---8306230496 Mpd 2.providing CY93 funds, to "Radiation Manitoring Program Requirements" BECK.R H Nebraska, State of GUSTAVE.R P Technical Assistance Contracts Branch. FIN B-8503. NRC-31-83-670 83/06/15, 1p 18982 039
- 8306230497 Notification of contract execution, Mod 1 to "Provision of Technical Assistance to Assass Psychological Stress Related to Decontamination & Disposal of Radwaste at TMI-2" Contractor Human Design Group SMITH, P A Administrative Contracts Branch FIN 8-7538 NRC-03-81-097 83/05/13 DENTON, H R. Office of Noclear Reactor Regulation, Director CLEARY, D P NRC No Detailed Affiliation Given 1p 18782 035 24X Fiche 50-320.89/05/13.8306230497
- --8306230301 Mod 1.deobligating balance of funds, to "Provision of Technical Assistance to Assess Psychological Stress Related to Decontamination & Disposal of Radwaste at TMI Unit 2."

 BAUM.A S Human Design Group SMITH.P A Administrative Contracts Branch FIN B-7538 NRC-03-81-097. 83/05/13. 1p 18982 036. 24X Fiche.50-320.83/05/13.8306230497
- B306230503 Notification of contract execution, Mod 20 to "Steam-Hater Mixing & Steam Hydrodynamics "Contractor BMI. SILVIB.R M Technical Assistance Contracts Branch FIN A-4048 NRC-04-76-293 B3/06/15 BATSUN.W Office of Nuclear Regulatory Research Director REYES, J NRC - No Detailed Affiliation Given ip 18982 031
- ---8306230505 Mod 20.providing add1 work scope & FY83 funding to
 "Bteam-Water Mixing & Steam Hudrodynamics."

 LUKZ,F J Battelle Memorial Institute, Columbus Laboratories
 MORTON.K V Division of Contracts FIN A-4048 NRC-04-76-293
 83/06/15 3pp 18782 032.
- 8306230507 Notification of contract execution, Mod I to "Radiation Monitoring Program Requirements" Contractor State of OR SILVIB, R M Technical Assistance Contracts Branch FIN B-B554 NRC-92-83-685. 83/06/15 ALEXANDER, I Office of Resource Management, Director HAMADA, 9 NRC No patalled Affiliation Given in 18982 029
- ---8306230509 Mod i,providing funds for CY83, to "Radiation Monitoring Program Requirements "

 * Oregon, State of QUSTAVE, R P Division of Contracts FIN B-8554 NRC-32-83-685 B3/06/15 ip 18782-030.
- 8304240031 Notification of contract execution. Mod 6 to "Qaotechnical Assistance" Contractor Dept of Army, Corps of Engineers.
 FLEENOR, C Division of Contracts. NRC-02-81-036 83/06/15
 DAVIS, J Office of Nuclear Material Bafety & Bafeguards, Director PRESTHOLT, P NRC No Detailed Affiliation Given ip 18987: 280.
- --8306240034 Mod 6,6sobligating unexpended travel funds for FY82, obligating travel funds for FY83 & extending period of performance to 840730. to "Geotechnical Assistance" RYAN, R H Army, Dept of, Corps of Engineers GUSTAVE, R P Division of Contracts. NRC-02-81-036 83/06/15 2pp 18787 281.
- B306240055 Notification of contract execution.Mod 2 to "Licensing Assistance/Tailings Mgt Program Technical Evaluation" Contractor:Weston Designers Consultants. FIELDS, JA Technical Assistance Contracts Branch NRC-02-79-031-08 B3/06/15 DAVIB.J Diffice of Nuclear Material Safety & Safeguards, Director RUSSBACH.L NRC No Detailed Affiliation Given 1p. 18999 188
- --8306240057 Med 2.extending period of performance to 830930, to "Licensing Assistance/Tailings Mgt Program Technical Evaluation"
 THOMPSON, A.F., Roy F., Weston, Inc., QUBTAVE, R.P. Division of Contracts, NRC-02-79-031-08
- 8306240353 Notification of contract execution. Mod 1 to "Field Experiment Determinations of Distribution Goefficients of Actinide Elements in Aquetic Environs." Contractor. Golumbia Univ.
 FIELDB. J A Fechnical Assistance Contracts Branch NRC-04-81-21783/06/15. BATSON. W Office of Nuclear Regulatory Research.
 Director BIRCHARD, O. NRC No Detailed Affiliation Olven 19.

- --8306240338 Mod 1.madifying gavt property & definition of purchased aquigment to "Fleld Experiment Determinations of Distribution Coefficients of Actinide Elements in Aquatic Environs " ISRAEL B H Columbia Univ GUSTAVE. R P Division of Contracts MRC-04-81-217 83/96/13 2pp 18999 161
- B306270441 Notification of contract execution "Maint for IBM Mag Cards & Memory Typeuriters," awarded to Technical Specialties, Inc COLEMAN, R Administrative Contracts Branch NRC-33-B3-459 B4306409 BASETI-H Office of Resource Management, Director JOHNSON, C NRC No Detailed Affiliation Office ip 18999 350
- --8306270446 Contract "Maint for IBM Mag Cards & Memory Typewriters." #warded to Technical Specialties. Inc * Technical Specialties. Inc MATTIA.M J Division of Contracts NRC-33-83-459. 83/06/03 18pp 18997 351
- 8306280050 Notification of contract execution. Mod 2 to "Licensing Technical Assistance" Contractor Science Application. Inc FLYNN.M Technical Assistance Contracts Branch FIN 8-7391-3 NRC-02-83-035 83/05/27 DAVIS.J 0 Office of Nuclear Material Safety & Safeguards. Director LOYSEN.P NRC No Detailed Affiliation Given 1p 19042 303
- --8306280057 Mod 2, increasing funds & definitizing Task Order 2, to
 "Licensing Technical Assistance"
 FINDLEY, D E Science Applications, Inc. GUSTAVE, R P. Division of
 Contracts FIN B-7391-3 NRC-02-83-035 83/05/27 6pp
 19042 304
- 8306280113 Notification of contract execution, Mod 3 to "Licensing Technical Assistance" Contractor Science Application, Inc. FLYNN.H Technical Assistance Contracts Branch FIN 8-7392-3 NRC-02-83-035 83/06/03 DAVIS, J O Office of Nuclear Material Safety & Safeguards, Director LOYSEN.P NRC No Detailed Affiliation Oliven 1p 19056 239
- --8306280118 Mod 3, increasing funds & definitizing Task Order 2, to
 "Licensing Technical Assistance"
 FINDLEY, D E Science Applications, Inc GUSTAVE, R P Division of
 Contracts FIN 8-7392-3 83/06/03 5pp 19056 260
- B306280115 Notification of contract erecution "FSARe," awarded to Info Handling Svcs COLEMAN R Administrative Contracts Branch NRC-10-83-341 83/06/13 BESAM, W Division of Technical Information & Document Control BKOCZLAS, J NRC - No Detailed Affiliation Given 1p 19056 265
- --8306280122 Contract "FBARs." awarded to Info Handling Svcs * Information Handling Services. MATTIA, M J Division of Contracts NRC-10-83-341 83/06/13 23pp 19056 266
- 8306280127 Notification of contract execution, Mod 10 to "Word Processing Sycs " Contractor Automated Correspondence Sys DORBEY, M. SMITH, P. A. Administrative Contracts Branch NRC-10-80-702 B3703706 SPRINGER, M. L. Office of Administration JOHANSEN, J. NRC No Detailed Affiliation Given 1p 19036, 289
- 8306280141 Notification of contract execution. Mod 4 to "Licensing Technical Assistance" Contractor Science Application. Inc. FLYNN:N Technical Assistance Contracts Branch FIN B-7393-3 NRC-02-83-035 B3/06/03 DAVIS.J Q Office of Nuclear Material Safety & Safeguards. Director LOYSEN, P NRC No Detailed Affiliation Given ip 19043 353
- --8306280147 Mod 4, increasing funds & definitizing Task Order 3, to
 "Licensing Technical Assistance"
 FINDLEY, D E Science Applications, Inc. GUSTAVE, R P Division of
 Contracts FIN 8-7393-3 NRC-02-83-035 83/06/03 5pp
- 8306280152 Notification of contract execution, Mod 5 to "Beismicity & Earthquake Hazard Research in Northern AL " Contractor Geological Survey of AL MCLETT: 8 Technical Assistance Contracts Branch FIN 8-6674 NRC-04-80-220 83/05/16 BATSDN:W Office of Nuclear Regulatory Research, Director MURPHY:A NRC No Detailed Affiliation Given 19. 17069 359
- --8306280159 Mod 5, extending period of performance to 840516 & increasing funds, to "Beismicity & Earthquake Hazard Research in Northern AL "

 MANCINI,E A Alabama, State of GUSTAVE,R P Administrative Contracts Branch FIN 8-6674 NRC-04-80-220 83/03/16 2pp 19069 360

- 830629026B Notification of contract execution "Provide Necessary Bupport for Brown to Present Paper Entitled 'Biaxial Loading Effects on Growth of Cracks' at Seventh Intl Conference ", awarded to Sheffield Univ TOHNSEND, B L Administrative Contracts Branch FIN 8-8993 NRC-04-83-166 83/06/20 BASSETT, O Division of Accident Evaluation WALKER, J NRC No Detailed Affiliation Given)p
- --83062902Bi Contract "Provide Necessary Support for Brown to Freesame Paper Entitled 'Biaxial Loading Effects on Growth of Cracks' at Seventh Inti Conference on Structural Mechanics "awarded to Sheffield Univ BROWN W Sheffield, Univ of RCDELLO, J E Division of Contracts FIN D-8975 NRC-04-83-166 83/06/20 4pp 19046 128
- 8306290385 Notification of contract execution. Mod 4 to "Task Analysis of Nuclear Power Plant Control Room Crews" Contractor General Physics Corp DELOATCH, V Technical Assistance Contracts Branch FIN 8-7491 NRC-04-82-005 83/06/15 FOREHAND, W Office of Nuclear Regulatory Research, Director JENKINS, J NRC No Detailed Affiliation Given
- --8306290633 Mod 4.extending period of performance to 830709. to 'lass Analysis of Nuclear Plant Control Room Crews " WHITNEY, J H General Physics Corp OUSTAVE.R P Division of Contracts FIN 8-7491 NRC-04-82-005 83706/15 ip 1904A ##1
- B306290597 Notification of contract execution revised Mod 4. to "Presentation of GE BWR/6 Design & Operation Courses"
 Contractor GE WCLETT, S Technical Assistance Contracts Branch FIN B-1224
 NRC-05-80-R32 83/06/15 BLAHA, J Program Support Branch
 HAVEN, O NRC No Detailed Affiliation Given 1p 19047 095
- --8306290629 Revised Mod 4.canceling Mods 4 & 5 % setting new course schedule to "Presentation of OE BWR/6 Design & Operation Courses "
 DUNN,M 9 General Electric Co GUSTAVE,R P Division of Contracts FIN B-1224 NRC-05-80-282 83/06/15 2pp
- 8306280133 Mod 10, deobligating balance of funds remaining to "Herd Processing Sycs" SPAISMAN, B.H. Automated Correspondence Systems, Inc. SKITH, P. A Division of Contracts NRC-10-80-702 83/05/06 ip 17056, 240
- FOIA FREEDOM OF INFORMATION ACT REQUESTS AND RELEASES
- 8304030007 FOIA request for rept or memo to Commissioners reviewing evidence in recently-terminated lawsuit between OPU & IBAH in federal court Southern District of NY MEISS, E R Union of Concerned Scientists 83/02/23 FELTON. J Division of Rules and Records 1p 18733 043 24X Fiche 50~320,83/02/23,8304030007
- 8306030010 Responds to FOIA request for rept or memo to Commissioners reviewing evidence in recently-terminated lawsuit between OPU & BBW in federal court. Southern District of NY Rept available in PPR FELTON, J M Division of Rules and Records 83/04/01, WEISS, K R Union of Concerned Scientists in 18733-044 24X Fiche 50-320,83/04/01,8306030010
- 8306030039 Appeals denial of FOIA request for NRC General Counset B10923 memo re interim 11censing legislation HAFNER, B Affiliation Unknown 83/02/28 Office of the Secretary of the Commission 2pp 18733 181
- 8306030046 Responds to appeal of denial of FOIA request for NRC Ceneral Counsel 810923 memo re interim licensing legislation Requested document not incorporated into final decision & remains predecisional & withholdable (ref FOIA Exemption 3) CHILK/S J Office of the Secretary of the Commission 83/04/OR NAFNER, B Affiliation Unknown 1p 18733 183
- 8304030366 Add1 response to FOIA request for SECY-82-368.SECY-82-475 & SECY-82-509.SECY-82-475 available in PDR SECY-82-368 withheld entirely (ref FOIA exemption 5) FELTON.J M Division of Rules and Records 83/04/01 SUCKLES.R Affiliation Unknown 2pp 18734 290
- --8306030370 SECY-82-475
 Informs of resolution of reactor coolent pump trip issue
 (TMI Action Plan Item II.K 3 5)
 DIRCKS.W J Office of the Executive Director for Operations
 82/11/30 55pp 18734 292

- 8306030373 FDIA request for two categories of address labels for listed NBOJOSTA FORMER TO COME CONTROL OF THE CONTROL OF T
- 8306030376 Responds to FOIA request for two categories of address Labels Forwards labels W/o encl FELTONJM Division of Rules and Records 83/04/01 AGNIHOTRI.N K Nuclear Plant 8afety 1p 18734 332
- 8304030379 FOIA request for NUREG-0945, "Final EIS on 10CFR41 "Licensing Requirements for Land Disposal of Radwaste JOHNBON B J Minnesota Project 83/03/22 Division Records 19 18734 348 Division of Rules and
- 8304030382 Responds to FOIA request for NUREG-0945, "Final EIS on IGCFR61 'Licensing Requirements for Land Disposal of Radwasts '" Forwards NUREG-0945, Vols 1-3 M/o encls FELTON, J Division of Rules and Records 83/04/01 JOHNSON, B J Minnespta Project ip 18734 349
- B306030303 Responds to FDIA request for documents re exploration, mining or milling of U in specific areas in State of NE Forwards documents listed in app FELTON, JM Division of Rules and Records 83/04/01 REID, A B Broken Plow Law Office 2pp 18747 149
- --8204070018 SECY-82-127 EUROPHOTE BECY-82-127
 Recommends Commission reassert regulatory authority over
 Stats of NE U mining & milling activities to protect public
 health & safety, per Governor Thone request
 DIRCKEN U Office of the Executive Director for Operations
 62/03/23 2pp 18747 153
- --8306030388 Approves encl draft FR notice re reassertion of certain regulatory authority in State of NE (SECY-82-127) CHILK 8 J Office of the Secretary of the Commission 82/04/20. DIRCKS W J Office of the Executive Director for Operations 4p 18747 157
- --8306030399 Forwards notice of issuance & availability of reassertion of certain regulatory authority in State of NE KERR.O W Office of State Programs, Director 82/04/26 COMBS.T R Correspondence & Records Branch 1p 18747
- --8306030395 Notice of issuance & availability of reassertion of certain regulatory authority in State of NE KERR, G W Office of State Programs, Director 82/04/26 3pp. 18747, 164
- 8306030448 Addl response to FOIA request for three documents re Univ of XB Research Reactor (License R-78) Forwards GL Madeen 830324 itr transmitting notice of viciation & IE Insp Rept 30-148/83-01 UU-148/83-01
 FECTON.J M Division of Rules and Records, 83/04/19 BARNES.C Affiliation Unknown ip 18735-329 24X Fiche 50-148/83/04/19,8306030448
- 830603044? FDIA request for results of insp & investigation performed by R Brown & D Murphy on 821130-31 RAE.R K Laboratory of Clinical Medicine, Sioux Falls, SD. 83703/18 Division of Rules and Records ip 18735-344.
- 8304030450 Responds to FOIA request for results of insp & investigation performed by R Brown & D Murphy on 821130-31 Requested rept will not be completed until end of Jul 1983 FELTON, J M Division of Rules and Records 83004/19 RAE.R M Laboratory of Clinical Medicine, Stoux Falls, 8D
- B306030451 FOIA request for Matl/Byproduct License 37-21226-01 granted to Swank-Metacon Sys Co ROBBINS,M C Republic Steel Corp 83/03/30. GRIMBLEY, D. H. Division of Rules and Records ip 18735:270
- 830.6030454 Responds to FDIA request for Matl/Byproduct License 37-21226-01 granted to Swank-Metacon Sys Co Forwards requested license FEL-TDN.J M Division of Rules and Records 83/04/19 ROBBINS,M C Republic Steel Corp. 1p 18735-271
- ~-8306030455 Matl/Byproduct License 37-21226-01 for Swank-Metacon Sys Co, authorizing Co-60 & Cs-137 smalled sources for use in installation, relocation, repair & servicing of Berthold devices GUINN P R Division of Fuel Cycle & Material Safety, 83/01/31. 3pp 18735 272

- 8304030459 FDIA request for study & recommendation paper by Commission Ofc of Policy Evaluation re-replacement of highly enriched U w/low enriched U in research reactors Paper referred to in encl CP Woodland 830215 ltr
 AFTEROCOD, 9 Committee to Bridge the Gap 83/03/18 Office of Administration Ip 18747 124
- 8306030461 Responds to FOIA request for study & recommendation paper by Commission Ofc of Policy Evaluation re replacement of highly enriched U in research reactors Forwards
 JE Zerbs 830301 meno to Commission Ahearne
 FELTON, J M Division of Rules and Records 83/04/19 AFTERGOOD, 8
 Committee to Bridge the Cap Ip 18747-126
- 8304040002 FOIA request for info re four listed corporations & individuals & all info concerning facilities licensed for use of 2 to 3 million curies near residential area. CLARK, R I Dolan & Dolan 83/02/09 Office of Administration. 2pp 18752 212.
- 8306060003 Responds to FDIA request for info re four listed corporations & individuals & all info concerning facilities licensed for use of 2 to 3 million curies near residential areas Forwards documents listed in App A FELTON.J M Division of Rules and Records 83/03/21 CLARK.R I Dolan & Bolan App 18752.114.
- --8006200486 Mati/Byproduct License 27-02786-03 for Ethicon: Inc. is amended in its entirety per 790426 application Amend 23 authorizes use of Co-60 in sealed sources for sterilization of medical & pharmacouticals products BROWN.J M Licensing Management Branch. 80/03/27. 3pp 18782 302
- --8007i60084 Matl/Buproduct License 29-i5364-01 for Isomedix, Inc.is amended per 790629 application. Amend 19 authorizes use of Co-60 & Cs-i37 in sealed sources for irradiating matls GUINN.P R Licensing Management Branch 80/06/17. 3pp
- --8304040004 Notifies that source discovered leaking on 7404i1-14 during transfer of Co-40 from old to new source holder Insp field notes for Insp Rept 7401 encl.

 O'BULLIVANE T RBA Corp 74/07/03 Atomic Energy Commission.

 17pp 18752 218
- --8304060005 Responds to NRC 740711 ltr re violations noted in insprept. Corrective actions separate log book established to record all routine & noncutine surveys Proper notices posted stating where license document posted.

 STEIN.M H R8A Corp 74/07/29 Region i, Philadelphia, Office of the Director ip. 18752 235
- --8306060006 Ack receipt of 740729 itr informing AEC of steps taken to correct violations noted in inep rept Related info encl.
 NELSON.P.R. Region 1. Philadelphia. Office of the Director 74/08/02 STEIN.M RSA Corp Spp 18752: 236
- -8306060007 Discusses Insp Rept 30-07026/79-01 on 751023 & forwards notice of violation Corrective actions re radiation surveys per 740711 itr verified NELSON.P R Region J. Philadelphia, Office of the Director 75/11/06 STEIN.H H RSA Corp. 2pp 18752.244.
- --8304060009 Nutice of violation from insp un 751023. Noncompliance noted failure to submit annual rept of radiation exposure incurred by parsonnel & to submit required repts re radiation exposure of terminated employees # Region 1: Philadelphia, Office of the Director 75/11/06 8pp. 18752 246.
- --8306060012 Responds to AEC 751106 ltr re violations noted in imap rept. Corrective actions: ltr reporting annual exposures sent to emonovors responds to AEU 701106 it re violations noted in in Corrective actions: itr reporting annual exposures sent to Executive Director of Regulations on 751027. Ltrs to terminated employees sent on 751113 O'SULLIVAN,E.T. RBA Corp 75/11/14. NELBON.P.R. Region 1, Philadelphia, Fuel Facility & Materials Safety Branch. ip 18752: 254.
- --8306060015 Ack receipt of 751114 ltr informing AEC of staps taken to correct violations noted in Insp Rept 30-07026/78-01. Insp field notes encl
 NELSON.P R Region 1. Philadelphia. Fuel Facility & Materials
 Bafety Branch 75/11/21 STEIN.H RSA Corp. 11pp. 18732 205.
- --830A060017 Notification of 761202 significant licenses meeting w/ Radiation Svc Assoc Corp in King of Prussia, PA to discuss results of 761116 & 23 insps & inadequacies observed in licenses mpt control Sys GLENNJ Region i, Philadelphia, Office of the Director. 76/11/30 Region i: Philadelphia, Office of the Director. ip. 18752 244

- --830A060019 Discusses agenda for mgt meeting w/Radiation Svc Assoc Corp on 761202 Commitments needed from licenses include health physics audits, survey program & method & date of leaking source disposal MCCLINTOCK, R O Region 1. Philadelphia, Office of the Director 76/11/30 O'REILLY, J P Region 1. Philadelphia, Office of the Director 3pp 18752 267
- --8306060020 Confirms 761202 meeting at Region t ofc to discuss results of 761116 & 23 insps & items of noncompliance Outline of corrective actions & improvements in mgt control sys requested 0'REILLY, J P 76/11/30 S P Region 1. Philadelphia. Office of the Director STEIN, M RSA Corp 1p 18752 270
- --8306060022 Submits agenda for 761207 mgt meeting w/Radiation Svc Assoc Carp to discuss detailed plan & time table for achieving compliance w/NRC rules & regulations per 761202 mgt meeting NELSON,P R Region i, Philadelphia, Fuel Facility & Materials Safety Branch 76/12/03 O'REILLY,J P Region i, Philadelphia, Office of the Director 2pp 19752 271
- --8306060024 Confirms 761207 meeting at Region I ofc to discuss dotailed plans resulting from 761202 meeting re assurance of future compliance w/NRC regulations & conditions of license O'REILLY, JP Region 1, Philadelphia, Office of the Director 76/12/06 STEIN, M RBA Corp ip 18732 273
- --8306060025 Commits to comply w/NRC rules & regulations re upgrade of radiological health & control stdw.in response to noncompliance noted during insp STEIN.M H RSA Corp. 76/12/09 O'REILLY, J.P. Region i. Philadelphia, Office of the Director ip 18752 274
- --8306060026 Discusses implementation of radiation protection program per 761214 meeting re control of radioactive metls D'REILLY,J P Region I, Philadelphia, Office of the Director IAL 76/12/16 BIEIN.M RSA Corp 2pp 19752 275
- ---8306060028 Discusses 761123 insp of Radiation Svc Assoc Corp Smear for removable radiation contemination revealed higher than reported concentration in samples drawn during 761116 insp GLENN.J E Region I, Philadelphia, Office of the Director 77/01/03 Region I, Philadelphia, Office of the Director 2pp 18752 277
- --8306060030 Discusses insp of Licenses 29-13848-01 & 29-13848-02 on 761116 & 23 & 1213 & 14 & 761202.09 & 14 meetings & forwards notice of violation THOMPSON, D Office of Inspection & Enforcement, Office of the Director 77/01/31 STEIN, M H RSA Corp 3pp 18752 279
- --8304040031 Notice of violation from insp on 741116 Noncompliance noted radiation levels in unrestricted ofc bldg exceeded allowable limit & contaminated underwater light stored in unrestricted machine shop * Office of Inspection & Enforcement, Office of the Director 77/01/31 5pp 19752 282
- ~8306060033 Responds to NRC 770131 ltr re viglations noted in IE insp spokedu33 Respones to Mic //Ulal itr re vigiations notes rept Corrective actions leaking broken source storage container removed from pool & placed in shielded storage cask for disposal.
 O'SULLIVANE T RBA Corp 77/02/17 THOMPSQN, D Offic Inspection & Enforcement, Office of the Director 4pp 18752 287
- --8306060035 Ack receipt of 770217 ltr informing NRC of steps taken to correct violations noted in IE Insp Ropt 30-07026/75-01 VULCENAU, E Defice of Inspection & Enforcement, Office of the Director 77/02/17 STEIN.M H RSA Corp 1p 18732:291
- --8306060039 Forwards proposed enforcement ltr in response to Radiation 8vc Assoc Corp 770217 its Corrective actions adequate. 0'REILLY, J. P. Region i. Philadelphia, Office of the Director 77/03/04 THOMPSON, D. Office of Inspection & Enforcement, Office of the Director ip 18752 292
- --8306060041 Amend 12 to Matl Bygroduct License 20~00315~03 for Dept of Army, authorizing use of Co-60 sealed source in irradiation of monexplosive matl COMBB, F Division of Fuel Cycle & Material Safety 78/11/15 2pp 18752
- --8304060083 Amend 16 to Matl/Byproduct License 29-13613-02, authorizing use of Co-60 sealed sources for Radiation Technology Model 2102 irradiator for surface irradiation, R&O & storage in receiving pool QUINN.P R Division of Fuel Cycle & Material Safety Bi/08/17 App. 19752 298.

- 830606000B FOIA request for list of 1982 & 83 SECY papers BROLINIM A KLM Engineering, Inc. 83/04/05 Division of Rules and Records 1p. 18751-258
- 8306060010 FOIA request for documents re investigation of L Berstler allegations concerning facility HGDAS: D R Potter & Carmine 83/03/18 Office of Administration ip 18792 305 24X Fiche 50-334,83/03/18,8306060010
- 8306060011 Responds to FOIA request for list of 1982 % 83 SECY papers Forwards requested list SECYs available in PDR FELTON.J M Division of Rules and Records 83/04/19 BROLIN.M A KLM Engineering, Inc 1p 18751 259
- ~~8306060014 Publicly available 1982 & 83 SECY papers * NRC No Detailed Affiliation Given 83/04/19 8pp 18751 260
- 8306060013 Responds to FOIA request for documents re investigation of L Berstler allegations concerning facility Forwards listed documents FELTCH.J M Division of Rules and Records 83/04/15 HODAS.p Potter & Carminø 2pp 18752 306 24% Fiche 50-354.83/04/15. 8306060013
- --8306060016 IE inquiry rept on 820819 Major area investigated L Derstire allegations re deficiencies in installation & testing of HVAC sys at facility Inquiry closed SHEPHERD, R E . CHRISTOPHER, R Region 1, Office of Director 62/11/22 14pp 18792 308 24X Fiche 50~394,83/04/15,8306060013
- --8306060018 Statement of LR Berstler alleging deficiencies in installation & testing of HVAC sys at facility Leak test rept forms for nongas-tight ductwork & worksheet encl BERSTLER.L R Affiliation Unknown 82/04/13 App 1875 24x Fiche 50-354.83/04/15.8306060013 18752 322
- --B30A060021 Discusses L Berstler, former Williard & Hirsch, Arkin, Hershman (W-H) QC inspector, allegations re HVAC installation at facility Bechtel preliminary review indicated minor hardware deficiencies & QC paperwork problem TRIPP, L E Division of Project & Resident Programs 82/03/0 Division of Project & Resident Programs 82/03/0 Fiche 50-354, 83/04/15, 8306060013
- --8306060023 Discusses L Barstler, former Williard & Hirsch, Arkin, Hershman (W-H) QC inspector, allegations re deficiencies in installation & testing of HVAC sys at facility SHEPHERD, R E Region 1, Office of Director 82/12/16 Region 1, Office of Director 82/12/16 Region 1, Office of Director 1p 18752 330 24% Fiche 50-354, 83/04/15, 8306060013
- --8306060027 Forwards matl discussed on 820819, per request Further discussion of matl will be arranged W/o encl SHEPHERD, R E. Region I. Office of Director 83/08/23 BERSTLER, L Affiliation Unknown 1p 18752 333
- 8306060032 Partial response to FOIA request for two categories of labels Forwards labels responsive to first category Second category labels will be forwarded when available W/o encl FELTON.J M Division of Rules and Records 83/04/01 AGNIHOTRI.N K Nuclear Plant Safety 1p 18751 270
- 8306060034 FOIA request for documents re US approvals of reprocessing of US-supplied nuclear fuel abroad & transfer & use of Pu derived from fuel LEVENTHAL.P Nuclear Club, Inc., The 83/06/10 MACHAK,F, State-Dept of 1p 18751 268
- 8304040037 Responds to FOIA request for documents re US approvals of reprocessing of US-supplied nuclear fuel abroad & transfer & use of Pu derived from fuel Documents withheld (ref FOIA Exemption 1), FELTON.J M Division of Rules and Records 83/04/08 LEVENTHAL.P Nuclear Club, Inc., The ip 18791 269
- 8306060051 Addi response to FDIA request for three categories of documents re PRA of reactor safety study methodology application program repts & interim reliability evaluation program repts Forwards App A documents, Search continuing FELTON, J M Division of Rules and Records 83/04/07 8HQLLY, 8 C Union of Concerned Scientists 3pp 10752 001 24X Fichs 50-000, 83/04/07, 8306060051
- ---Bi09210310 Responds to Bi0B20 memo re transmittal of NUREG/CR-1659, Vol 2, to licenses for comments Util comments on rept already vol 2.75 licensee for comments vol comments on rept already requested BERNERO.R M Division of Risk Analysis B1/08/28 NOVAK.T M Assistant Director for Operating Reactors, 2pp 18752 018 24X Fichs. 50-000.83/04/07.8306060051

- --R204120488 Discusses results of Sandia Nati Labs Study, "Reactor Safety Study Methodology Application Program Grand Gulf 1 BMR Power Plant (NUREG/CR-1659, Vol 4)" ERNST, M L Assistant Director for Technology Review 82/04/06 TEDESCO, R L Assistant Director for Licensing 2pp 18732 067 24% Fiche 80-000,83/04/07.8306060051
- ---B207280024 Discusses NUREO/CR-2787. "Interim Reliability Evaluation Program Analysis of AR Nuclear One-Unit i Nuclear Power Plant," first final rept on four integrated reliability avaluation program Phase II studies
 BERNERO, R M Division of Risk Analysis B2/06/24 HANAUER, S H
 Division of Human Factors Safety Spp 18752 074 24X
 Fiche 50-000, 83/04/07, 8306060051
- --8211220332 Forwards "Effect of Resolution of Millstone Unit 1 SEP Issues on Probabilistic Calculations of Risk" & risk-based perspective of selected SEP issues
 ERNST.M L Assistant Director for Technology Review 82/11/15
 MRRACLIA:F Assistant Director for Safety Assessment 12pp 18752 077 24X Fiche 50-000.83/04/07.8306060051
- -- 8211220337 SAND82-2429 Zli220337 SAND82-2429
 "Effect of Resolution of Millstone Unit 1 SEP Issues on
 Probabilistic Calculations of Risk "
 SPULAK,R O , STACK,D , AMICO,P Science Applications, Inc
 82/11/19 NRC - No Detailed Affiliation Given 108pp
 18752 091. 24X Fiche 50-000,83/04/07,8306060051
- --B306060058 Requests meeting w/NRC to discuss concerns re reactor safety study methodology application program Conservative rather than realistic assumptions & calculations used in analysis DALE.L F Mississippi Power & Light Co AECM-81/18A 81/07/23 BERNERD,R M Division of Risk Analysis 2pp 18752 016 24X Fiche 50-000,83/04/07,8306060051
- --8306060061 Statement on background, issues, current status & future action re interim & natl reliability evaluation programs * NRC No Detailed Affiliation Given 82/12/31 2pp 18752 059 24X Fiche 50-000.63/04/07.8306060051
- --8306060066 Requests review of listing of all PRA-type studies performed on plants (both operating & under const) Listing does not include SEP Phase III/natl reliability evaluation program EIGENHUT, D & Division of Licensing 82/06/01 HANAUER, S H Division of Safety Technology 2pp 18752 069
- --8306060076 Discusses interim actions taken to reduce impact of turbine ASSOCIOUS DISCUSSES INTERIM ACTIONS taken to reduce impact of turb hidg flooding Doors between turbine & auxiliary bidgs at basement level smaled shut.component cooling water crossover valves closed & condensate cooler isolated TUCKER.H B Duke Power Co 82/12/01 O'REILLV.J P Region 2. Office of Director 2pp 18752 198 24X Fiche 50-000.83/04/07.8306060031
- --8306060080 Forwards background info re PRA studies Review of Sandia Natl Labs interim reliability evaluation program studies discussed W/o encl BISCLZ.J Uperating Reactors Branch 4 TAC 47471 83/01/19 LAINAB.9 C Assistant Director for Operating Reactors 2pp 18752 200 24X Fiche 50-000.83/04/07.8306060051
- --830A0A0D89 Provides info on boron precipitation clogging HPI lines & failure of operator to switch to hot leg injection in order to flush out boron residue from core during recirculation lines obtained from PRAs
 DAVIB. S NRC No Detailed Affiliation Given 83/02/24
 THADANI, A NRC No Detailed Affiliation Given App 18752 206
 24X Fiche DD-000.83/04/07.830A0A0051
- 8306060096 FOIA request for SECY-81-645 SECY-81-654 & SECY-82-162A QRABER.L. Affillation Unknown 83/01/31 Division of Rules a Records ip 18750 352
- 8305050104 Responds to FDIA request for SECY-81-449.6CCY-81-554 & BECY-82-152A BECY-81-645 & BECY-81-554 pertain to AOs noticed in 46FR51020 Forwards BECY-82-152A FELTON.J M Division of Rules and Records B3/03/29 GRABER.L Affiliation Unknown 1p 18750 353
- --830606010B BECY-82-162A Forwards integrated plan for development of rule for shift crew qualifications.

 DIRCKS, W J Office of the Executive Director for Operations
 82/08/26 9pp 18750 354
- 830606038i Appeals denial of FOIA request for documents re risk to facilities from low trajectory turbine missiles HIATT.8.L Ohio Citizens for Responsible Energy 83/03/03 BIRCKS, W J Office of the Executive Director for Operations. 3pp 18750 329 24X Fiche, 50-440, 83/03/03, 8306060381

- 830.6040384 Responds to appeal re partial denial of FOIA request for documents concerning risks to facilities from low trajectory turbine missiles Appeal denied Documents withheld (ref FOIA Exemption 5)
 DIRCKS.W J Office of the Executive Director for Operations 83/04/06 HIATTS L Ohio Citizens for Responsible Energy ip 18750 332 24X Fiche 50-440.83/04/06.8306060384
- 8306060393 Final response to FDIA request for five listed documents reguide tube support pin failures Forwards Documents 2 & 5 & related meeting minutes Document 5 incorrectly identified as 820520 ltr Ltr coded NS-EPR-2551 actually dtd 820128 FELTON,J M Division of Rules and Records 83/04/05 MDNAMAN,J. Francis & McGinnis Associates ip 18753 021
- --8306060396 Summary of 820602 meeting w/Westinghouse re control rod drive guide tube support pin failures List of attenders & viewgraphs encl KOLLAND, R A Director's Office, Office of Inspection and Enforcement 82/06/02 MILLS, W R Events Analysis Branch 49pp 18753 029
- 830606039B FOIA request for lists of geople in emergency planning dept & instrumentation & control dept of nuclear plants & in state depts of health physics/radiology WEST-D K Affiliation Unknown 83/02/28 Division of Rules and Records ip 18751 291
- 8306060400 Responds to FOIA request for lists of personnel in specified depts of nuclear plants & in state depts of health physics/radiology Forwards listed documents. Document partially withheld (ref FOIA Exemption 6)
 FELTON-J M Division of Rules and Records 83/04/06 WEST.D K Affiliation Unknown 2pp 18751 292 24X Fiche 50-312.83/04/06, 8306060400
- --8306060402 "Directory of Personnel Responsible for Radiological Health Programs " Organization charts of NC, FL, AL, QA, KY, MB, SC & TN & list of state contacts for emergency preparedness w/ info partially deleted encl. # HHS, Dept of, US Public Health Service 82/10/08 56p 18751 274
- B30.6070018 FOIA request for inspisurveillance & radiological monitoring repts re Restinghouse Cheswick Divilicense 37-05809-01
 37-05809-01
 JOHNBON.C Behrand, Aramson & Morraus 83/05/03 ALLAN, Region 1, Office of Director 2pp. 18780-360 M L WALLA CONTONER
- B306070019 Final response to FDIA request for documents re current efforts by NRC to upgrade earthquake resistance at facility Forwards documents listed in app. Handwritten document withheld (ref FDIA Exemption 5)
 FELTON, J M Division of Rules and Records B3/04/05 HHARTON, F Ban Diego, Univ of, San Diego, CA 2pp 18781 343 24X
 Fiche 50-206,83/04/05,8306070019 93/04/03 WHARTON R. J 8781 343 24X
- ---8205170474 Forwards 820505 memo w/Systematic Evaluation Program Branch recommendations re seismic reanalysis program
 DIRCKG,W J. Office of the Executive Director for Operations
 82/05/07 PALLADINGIN J. OILINBKY.V. AHEANNE, J. F.
 Commissioners 2pp 18781 352 24X Fiche 50-206,83/04/05, 8306070019
- --B208050024 Forwards response to B20618 request for comments on Director's Decision B1-19 denying 100FR2 206 relief re DIRCKS,W J. Dffice of the Executive Director for Operations. DD-91-19 82/07/22 ANEARNE, J Commissioners App. 18781 354 24% Fiche 50-206.89/04/05.89366070019
- --8304070021 Requests meeting to discuss encl questions on SECY-82-63 re Director's Decision denying 10CFR2, 206 relief concerning interim seismic adequacy AKEARNE, J Commissioners 82/04/20. Office of Policy Evaluations. 3pp. 18781-347 24X Fiche: 50-206, 83/04/05, 8304070019
- --8306070028 Approves SECY-82-63 re Director's Decisions 81-19 & 81-20 denying request for 10CFR2 206 relief, Comments on SECY-82-63 re misclassification of turbine bldg complex enti AHEARNE, J. F. Commissioners, DD-81-19 82/05/03 CHILK, 8 J. Office of the Secretary of the Commission 2pp 18782 008 24% Fiche, 50-206, 83/04/05, 8306070019
- 8304070020 Responds to FDIA request for insp.surveillance & radiological monitoring repts re Westinghouse Cheswick Div. License 37-05809-01 Forwards App A documents Search for addl documents continuing. W/o encls FELTON, J M Division of Rules and Records 83/05/16 JOHNBON, C. Behrand, Aramson & Morraus 2pp. 18780-362

- 8306070023 FGIA request for documents re proposals submitted under RFP R8-BECY-82-473.including proposal revs & review of proposals & negotiations between NRC & any entity submitting proposals SHARP.I H Alderson Reporting 83/03/21 FELTON.J M Division of Rules and Records 1p. 18782 270
- 8306070023 Add1 response to FOIA request for proposals submitted under RFP RB-SECY-B2-473, including proposal revs, review of proposals & negotiations between NRC & any entity submitting proposals Nonproprietary portions of proposals encl FELTON.J H Division of Rules and Records 83/05/03 SHARP, I H Alderson Reporting. (p 18782-271
- --B306070026 Solicitation offer & award to Mohick Reporting Co. MEHOLICK, J J. Monick Reporting Co. FLYNN-M Division of Contracts RS-SECY-82-473 82/09/13. 3pp 18782 272
- --8306070027 Requests that encl response to RFP RS-SECY-82-473 be withheld. Info partially deleted HEMOLICK. J J Monick Reporting Co 82/09/13 Division of Contracts 25pp 18782-277.
- 8306070439 Responds to FOIA request for 790329 original petition for rulemaking filed by 0 Taplin Forwards document W/o encl FELTON.J.M Division of Rules and Records 83/04/05 KRONZEK.A L FOI Services 1p. 18776 357
- 8306070441 FOIA request for 79032B original petition for rulemaking filed by 9 Taplin.

 KRONZEK.A L. FOI Services 2724. 83/03/29 FELTON: J M Division of Rules and Records kip 18776 358
- 8306080028 FOIA request for ORNL/TM-8275, "Technical Considerations re Interim Source Term Assumption for Equipment Qualification & Emergency Planning."

 BHOLLY: C Union of Concerned Belentists B3/03/14 FELYON, J M Division of Rules and Records 1p 18784 148.
- 8306080031 Responds to FDIA request for ORNL/TM-8275, "Technical Considerations re Interim Source Term Assumptions for Equipment Qualification & Emergency Planning," ORNL/TM-8275 enci PELTON.J M. Division of Rules and Records 83/03/25 SMOLLY, 8 C Union of Concerned Scientists ip 18784 049
- --8306080041 GRNL/TM-8275

 "Technical Considerations re Interim Source Term Assumptions for Emergency Planning & Equipment Gualification "
 NIEMCZYK, 8 J., MCDOWELL-BDYER Dak Ridge National Laboratory 82/09/30 NRC No Detailed Affiliation Given 312pp 18784 150.
- 8306080066 Responds to FOIA request for current roster of utils list Ducument available in PDR FELTON.J M. Division of Rules and Records 83/04/04 SANDRY.W A Professional Reactor Operator Society ip 18787 298
- B306080070 FOIA request for current roster of utils list BANDRY, W. A. Professional Reactor Operator Society, B3/03/R8 CARR, J. Division of Rules and Records 1p 18787, 299.
- 8306080255 Responds to FDIA request for names, addresses, license numbers & insp priorities & subpriorities for licenses in nine states Forwards computer printout W/o encl FELTON.J.M Division of Rules and Records 83/04/11 TEKIN,J V Radiac Research ip 18785-349
- 8305080255 FOIA request for names, addresses, license numbers & insperiorities & subpriorities for licenses in nine listed states

 TEKIN.J V. Radiac Research. 83/03/23 Office of Administration ip. 18785-350
- 8306080257 Responds to FDIA request for info on fraudulent practices of Ray Miller. Inc. App A documents available in PDR FELTON.J.M Division of Rules and Records 83/04/11. STECKEL.A Union of Concerned Scientists. 4pp. 18785:351.

fraudulent
715. FELTON,J M

te categories n App FOIA

... KINDER, E. T.

- --8306080263 Forwards results of licensee investigation of Pullman-Higgins QC inspector allegations reperceived harassment of QC inspectors from within Organization & documentation of organization changes

 CERNE.A C Region 1. Office of Director 82/07/16 Region 1. Office of Director 7pp 18790 319 24X Fiche 50-443.83/04/06.8306080259
- ~-8306080264 Discusses GC inspector concerns within Pullman~Higgins organization (facility piping contractor) re-perceived harasament of GC inspectors by P~H const personnel Closure of case recommended GERNE.A C Region i. Office of Director 82/10/13 Region i. Office 92/10/13 Region i. Office 92/10/10/13 Region i. Office 92/10/13 Region i. Office 92/10/10/13 Region i. Office 92/10/10/13 Region i. Office 92/10/10/10/10/10/
- --8304080266 Discusses Pullman-Higgins (P-H) GC inspector concerns re allegations of harassment of GC inspectors by P-H const personnel Personally Identifiable info deleted CERNE A C Region i, Office of Director 82/06/09 Region I, Office of Director 2pp 18790 328 24X Fiche 50-443,83/04/06, 8394080229
- --8306080267 Discusses QC inspector concerns.per AC Cerne 820609 mena Handwritten notes encl Memo contents deleted SHEPHERD.R E Region 1. Office of Director 82/06/17 BRUNHNER,E J Division of Project & Resident Programs App 18790 330
- --8306080269 Discusses nonspecific allegations re Pullman-Higgins GA/GC inspectors at facilities Personally identifiable info deleted MATAKAS.R A Region i. Office of Director 82/09/27 OALLO,R N Division of Project & Resident Programs 2pp 18790 336 24X Fiche 30-443.83/04/06.8306080259
- 830608026) FOIA request for R Parks 56-page affidavit sent to US Dept of Labor ROMANO,F R Air and Water Pollution Patrol 83/03/31 Division of Rules and Records ip 18787 177 24% Fiche 50-320,83/03/31, 8306080261
- 8304080262 Responds to FOIA request for R Parks 56-page affidavit sent to US Dept of Labor Forwards T Devine 830323 ltr transmitting RD Parks 830321 affidavit & RD Parks 830316 ltr to Bechtel FELTON, J M Division of Rules and Records 83/04/12 ROMANO, F R Air and Water Pollution Patrol 1p 18787 178 24X Fiche 50-320, 83/04/12, 8306080262
- 8306080265 FOIA request for SECY-83-22 KNIGHT,N L General Physics Corp 83/03/18 Division of Rules and Records 1p 18787 239
- 8304080268 Responds to FDIA request for SECY-83-22 Forwards publicly available portions of paper per telcon w/N Toms FELTON, J M Division of Rules and Records 83/04/11 KNIGHT.N L General Physics Corp 1p 18767 240
- --8306080270 "Statement of policy Further Commission Guidance on Emergency Response Capability," draft 10CFR30 effective rule Buppl (ssued to NUREO-0737, "Clarification of TMI Action Plan Requirements" CHILK, B. J. Office of the Secretary of the Commission 83/04/11 Spp. 18787 241
- 8306080272 Add1 response to FOIA request for documents re meeting between ABEA-ATOM (Sweden) & NRC concerning PIUS reactor & documents regarding PIUS reactor No add1 documents available FELTON, J M. Division of Rules and Records 83/05/03 SHOLLY, S C Union of Concerned Scientists ip 18790-350
- 8306080275 Responds to FDIA request for lists of people in nuclear industry Forwards requested lists except for list of expired reactor operator licenses List of reactor & senior reactor operators also encl W/o encls FELTON.J M Division of Rules and Records 83/04/25, BCUDDER, J Affiliation Unknown ip. 18790 352
- 8306080276 FOIA request for lists of people in nuclear industry 8CUDDER, J. Affiliation Unknown 83/04/15 FELTON, J. Division of Rules and Records, 1p. 18790-353
- 8306080277 Add1 response to FOIA request for seven categories of records re Brown & Root, Inc & facilities App C Document i partially withheld (ref FOIA Exemption 7) App D documents withheld entirely (ref FOIA Exemption 3) FELTON, J M. Division of Rules and Records B3/04/12 LINDEMAN, H N Lowenetsin, Newman, Reis, Axel Frad & Toll 4pp 18792.156 24X Fiche. 50-498, 83/04/12, 8306080277

- --8306080304 "Request for investigation Concerning Alleged Advanced Notification," investigation rept Info partially deleted SINCLAIR.JR Office of Inspector & Auditor 80/10/23 9pp 18772 160 24X Fichs 50-498.83/04/12.8306080277
- --8306080308 Forwards rept re alleged advanced notification to util or Brown & Root, Inc of forthcoming Region IV investigation L/or alleger identities No further investigation contemplated N/o enci
 CUMMINOS. J J Office of Inspector & Auditor B0/10/24
 AHEARNE. J F , OILINGKY, V , HENDRIE, J M Commissioners 19
 18792 169 24X Fichs 30-498.03/04/12.8306080277
- --8306080310 Forwards "Request for Investigation Concerning Alleged Advanced Notification" (ref 801024 memo) W/o encl CUMMINGS.J J Office of Inspector & Auditor 80/11/10 STELLD.Y J Director's Office, Office of Inspection and Enforcement 1p 18792 170 24X Fiche 50-498.83/04/12, 8306080277
- 830.6080281 Partial response to FOIA request for documents re
 R Conderson & Bechtel allegations concerning electrical
 problems at facilities App A Documents 1 & 2 available in
 PDR Documents 3,4 & 5 withheld (ref FOIA Exemption 3)
 FELTON,J K Division of Rules and Records 83/04/28 YOUNG,M C
 BERNABELL Government Accountability Project 3pp 18790 354
 24x Fiche 50-528,83/04/28,8304080281
- 8306090284 FOIA request for documents re R Ounderson & Bechtel senior manager allegations concerning electrical problems & deficiencies at facilities Waiver of fees requested YOUNG, M.C. BERNABELL. Qovernment Accountability Project 83/03/29 Office of Administration 2pp 18790-357 24% Fichs 50-528.83/03/27,8306080284
- 8304080288 FOIA request for list of NRC licensed contractors &/or subcontractors performing HVAC sheet metal work at nuclear plants currently operating b under const in US WEGT.D K Affiliation Unknown 83/02/28 Office of Administration Ip 18790 360
- 8306080291 Responds to FOIA request for list of NRC licensed contractors &/or subcontractors performing KVAC sheet metal work at nuclear plants currently operating & under const in US.
 FELTON.J M Division of Rules and Records 83/03/23 WEST.D K
 Affiliation Unknown Ip 18790 359
- 8306080293 FDIA request for list of addresses receiving DEB redecommissioning of Rare Earths Facility, West Chicago, IL subsequent to May 1982 SPELMAN, H.J. Harold J. Bpelman & Associates 83/03/23 Division of Rules and Records 2pp 18792 145
- 8306080276 Responds to FDIA request for documents re licensee (Radiation Technology, Inc) & other licenses dealing w/ MA Helt Prior insp repts & transcript of hearing involving licensee will be provided, per 830425 conference call FELICN, J M Division of Rules and Records 83/04/27 HILL, R Riverside County, CA 1p 18790 361
- 8.306080297 Responds to FOIA request for list of addressees receiving DES re decommissioning of Rare Earths Facility. West Chicago.

 18. subsequent to May 1982 Forwards molling list for DES Addressees receiving DES after May 1982 not identified FELION. J M Division of Rules and Records 83/04/06 SPELMAN. M J Harold J Spelman & Associates ip 18792 147
- --8306080302 "Distribution List.Kerr-McGee West Chicago DES " * NRC - No Detailed Affiliation Given 83/04/06 8pp 18792 148
- B30A0B0301 F0IA request for documents re licensee (Radiation Technology,Inc) & other licenses dealing w/MA Welt HILL,B. Riverside County, GA B3/03/31 Office of Administration ip 18790 362
- 8306080305 Responds to FOIA request for info re safety & const violations at facility Info available in LPDR.per 830407 teleon FELTON.J M Division of Rules and Records 83/04/08 BADING.A Affiliation Unknown ip 18792 216 24% Fiche 50-358.83/04/08,8306080305
- B3060B0307 F0IA request for info re safety & const violations at facility BADING.A Affiliation Unknown B3/04/01 Division of Rules and Records 1p 18792 217 24X Fiche 50-358.83/04/01.8306080307

- 8306080309 FDIA request for three documents re Univ of KS Research Reactor BARNES.C Affiliation Unknown 83/03/08 FELTON,J M Division of Rules and Records 1p 18790 303 24X Fiche 50-148,83/03/08, 8304080309
- B3060B0313 Responds to FDIA request for three documents re Univ of KB Research Reactor Forwards documents responsive to Items 1 & 2 of request Releasability determination for Item 3 re insprept under review FELTON, J M Division of Rules and Records B3/04/06 BARNES, C Affiliation Unknown ip 18790 304 24X Fiche 50-148,83/04/06,8306080313
- --B3060B0316 Forwards responses to 731106 questions, indicating specified locations on floor plan SMITH.WP Kansas, Univ of 8759 73/12/06 ZIEMANN,D L Atomic Energy Commission, Directorate of Licensing Spp. 18790 305 24X Fiche 50-148, 83704/06, 83060B0313
- 8306080320 FOIA request for info re safety requirements of nuclear power plants MARTIN.C Affiliation Unknown 83/04/25 NRC - No Detailed Affiliation Given 1p. 18789 336
- B306080322 Responds to FDIA request for info re safety requirements of nuclear power plants Forwards App A documents W/o enci FELTON. J K Division of Rules and Records 83/05/03 MARTIN.G Affiliation Unknown 2pp 18789-337
- 8304090373 FOIA request for winning technical proposal & any mgt proposals submitted by Computer Data Sys. Inc. to provide publication distribution & inventory sycs.

 SEMINARA C Science Management Corp 63/02/09 Division of Contracts ip 18815 171
- B306090374 Responds to FOIA request for winning technical proposal & any mgt proposals submitted by Computer Data Sys. Inc to provide publication distribution & inventory svcs Forwards nonproprietary version of requested proposal FELTON, J M Division of Rules and Records B3/04/13 SEMINARA.C. Bcience Management Corp ip 18815 172
- --8306090379 Nonpreprietary version of "Proposal to Provide Publication Distribution & Inventory Sys for NRC " + Computer Data Systems, Inc. 82/08/20 44pp. 18815-173
- 83060903B1 Responds to FOIA request for documents released under Request FOIA Request 82-315 & NRC repsonse & all encls Documents available in PDR Status of administration of FOIA for wk ending 82:105 encl FELTON.J H Division of Rules and Records 89/04/13 KRONZEK.A L FOI Services 2pp 18815 168
- 8306100009 Add) response to FOTA request for documents dtd 820101 or after re SALP forwards App A documents Documents also available in PDR FELTON.J M Division of Rules and Records 83/04/11 CLARK.R San Francisco Examiner 3pp 18815 252 24X Fiche 50-000.83/04/11, 8206100009
- --B306100014 Submits schedule for Region V SALP Board meetings for 820728-830523
 ENGELKEN R H Region 5. Office of Director 82/03/19.
 DENTON H R Office of Nuclear Reactor Regulation, Director DAVIS. J Q Office of Nuclear Material Safety & Bafeguards, Director MiCHELSON. C Director's Office ip, 18815 255 24X Fiche 50-000,83/04/11.B306100009.
- --8306100032 Requests brief performance analysis & recommended conclusion for each functional area inspected/based on review of summary of inspected/based on review of summary of inspected ties & analyses of LERS & noncompliance items issued from Jul 1981 Sept 1982, STERNBERG, D.M. Region 5. Office of Director, 82/03/23 YOUNG, T., CANTER, H. D'BRIEN, J. Region 5. Office of Director 1p. 18815 256 24X Ficher 50-000, 83/04/11, 8306100009
- --B306100036 Discusses assignment of BALP coordinators for Reactor Operations Projects Branch facilities Coordinators will be responsible for preparing input data used by board members in analyzing functional areas Draft note from 8 Hiner entl. STERNBEROLD M Region 3. Diffice of Director. B2/03/24 Region 3. Office of Director 11pp 18815 257 24X Fiche 50-000,83/04/11.8304100009.
- --8306100038 Forwards input to SALP rept CHOKREFI.N. Structural Engineering Branch NRC -- No Detailed Aptiliation Olven 5pp 18815 271. 24X Ficha 50-000, 83/04/11, 8306100009

- --8306100039 Forwards evaluation of licensee performance for safeguards licensing portion of SALP review per Sternberg 821014 memo Util has responded quickly & accurately to NRC-initiated comments & suggestions HCCORKLE, O W Power Reactor Safeguards Licensing Branch comments & suggestions
 MCCORKLE, O W Power Reactor Safeguards Licensing Branch
 82/11/04 NORDERHAUO, L Region 5, Office of Director
 19815 288 24X Fiche 50-000.83/04/11,6306100009
- --B306100040 Forwards brief description of investigative activities of seven cases re SALP during Jul 1981 Sept 1982 Allegation against contract personnel using controlled drugs during outages still pending BHACKLETON.O C Region 5. Office of Director 82/11/10 WILLETT.D Region 3. Office of Director 2pp 18813 291 24X Fiche 50-000.83/04/11.8306100009
- ~-8306100044 Comments on 821014 memo re SALP Board review of facility NORTH,H Region 5, Office of Director 82/11/10 WILLETT,D Region 5, Office of Director 2pp 18815 293 24X Fiche 50-000,83/04/11,8306100009
- --8306100047 Forwards SALP rept inadvertently omitted from 821202 ltr & revised agenda for SALP 830105 meeting STERNBERG, D M Region 5. Office of Director 82/12/15 MATTIMOS, J. J Sacramento Municipal Utility District ip 18815 304 24X Ficher 50-000,83/04/11,8306100009
- 8306160013 Responds to FOIA request for grant applications, grant awards, contracts & cooperative agreements to League of Cities & Conference of Mayors over last 10 yrs Div of Contracts has no records subj to request FELTON, J H Division of Rules and Records 83/04/14. HOUSTON, Fairness Committee Against Tax Funded Politics 1p 18872, 217
- 8306660015 FOIA request for grant applications, grant awards, contracts & cooperative agreements to League of Cities & Conference of Mayors over last 10 yrs
 HOUSTON, J. C. Fairness Committee Against Tax Funded Politics
 83/04/04 PALLADING, N. J. Commissioners ip 18872.218
- 8306160019 Responds to FOIA request for four categories of documents re suspected teratogens & birth defects as result of nuclear yower plant operation NRC has no records subj to request FELTON.J K Division of Rules and Records 83/04/15 MARSHALL,C Foundation for National Progress ip 18972 291
- 8306160024 FOIA request for four categories of documents re suspected teratogens & birth defects as result of nuclear power plant operation
 MARSHALL,C Foundation for National Progress 83/03,
 NRC - No Detailed Affiliation Given Spp 19872 292 83/03/16 CARRIJ C
- 8306160026 Responds to FOIA request for four documents re Saxton Test Reactor Requested Itrs available in PDR Saxton 741124 ltr to NRC not located FELTONJ K Division of Rules and Records 83/04/20 GRABER.L D NUB Corp 1p. 18872 314 24X Fiche 50~146,83/04/20,8306160026
- 8306160030 FOIA request for four documents re Saxton Test Reactor QRABERIL D. NUS Corp CP-LIS-9104 83/04/12 Division of Rules and Records ip 18872-315 24X Fiche 50-146.83/04/12,8306160030
- 8306160031 Clarifies NRC final response to FOIA request for documents re Zack Co W/or work performed by Zack in const of facilities App D Document 5 delated since document identical to App A Document 135.
 FELTON-J M Division of Rules and Records 83/04/14
 PRENDERORAST-R. Prendergast-R J 1p 18872 336 24X
 Fiche 50-000-83/04/14.8306160031
- 8306160033 Responds to FOIA request for documents re Jul 1782 stop work order issued to util Request withdrawn.per 830414 telcon between requester & N Toms Case closed. FELTON.J M Division of Rules and Records 83/04/14 GARDE.B Government Accountability Project ip 18892:333 24X Fiche, 50-329, 83/04/14, 8306160033
- 8304140035 FDIA request, on behalf of EE Kent, for documents re Jul 1982 stop work order issued to util 9ARDE.B Government Accountability Project 83702/16 Office of Administration ip 18892 334. 24X Fiche 50-329, 83/02/16,
- 8306160041 FDIA request for AEOD Engineering Evaluation Rept AEOD/N301 re 1-125/1-131 effluent releases by licensees & documents re Ray Hiller; Inc KRANIENIA Trends Publishing, Inc 83/04/06 Division of Rules and Records. ip 18892 328

- 8306160046 FDIA request, on behalf of EE Kent, for records prepared by US govt employees re Alliance for Survival, Y Cargenter 1/or ongoing NRC investigation of facilities CARENTER, T Drange County Alliance for Survival 83/03/14 Office of Administration 1p 18893 031 24% Fiche 50-206, 83/03/14,8306160046
- 8306160050 Responds to FOIA request for AEOD Engineering Evaluation Rept AEOD/N301 re I-125/I-131 effluent releases by licensees & documents re Ray Miller. Inc Forwards AEOD roet Ltr sont to UCS re Ray Miller, Inc practices will be provided FELTON, J M Division of Rules and Records 83/04/21 KRANISH, A Trends Publishing, Inc. 1p 18892 329
- --8306160057 AE0D/N301 SOLEOUST ACLOVAGO
 ACCO Engineering avaluation rept re I-129/I-131 officent releases by licensees Issuance of IE info notice recommended to clarify 100FR20 201(b) requirement that licensees make physical measurements to verify compliance w/100FR20 106(a) * Director's Office 83/03/18 3pp 18892 330
- 8306160052 Responds to FDIA request for records prepared by US govt employees re Alliance for Survival T Carpenter 3/or ongoing NRC investigation of facilities Forwards App A documents Search for add! documents in progress FELTON.J M Division of Rules and Records 83/04/14 CARPENTER. Orange County Alliance for Survival 2pp 18893 032 24X Fiche 50-206.83/04/14.8306160052 CARPENTER. I
- --8211160565 Forwards Community Energy Action Network 821018 htr //
 Los Angeles Times article re potential problem w/weids at facilities CRANSTON: A Senate 82/10/29 KRAMMERER, C Office of Congressional Affairs 3pp 18873 056 24X Fiche 50-206, 83/04/14,8306160052
- B306160069 FOIA request for Chairman Palladino 810930 memo referenced in 821210 FR notice of proposed rulemaking 47FR2874 & 2877, "Environ Qualification of Electrical Equipment for Nuclear Power Plants " NEWMAN, K.A. Debevoise & Liberman E of Rules and Records 1p 18872 359 83/03/28 FELTON, J M Division
- 8306160070 Add1 response to FOIA request for records propared by Us gott employees re Alliance for Survival, T Carpenter E/or ongoing NRC investigation of facilities IE Insp Repts 50-206/82-31.80-361/82-31 & 50-362/82-27 available in PDR FELTON, J M Division of Rules and Records 83/04/28 CARPENIER, T Grange County Alliance for Survival 2pp 18892 338 24X Fiche 30-206,83/04/28,8306160070
- B306160073 Responds to FDIA request for Chairman Palladino 810930 mena referenced in B21210 FR notice of proposed rulemaking 47FR2B76 & 2877, "Environ Gualification of Electrical Equipment for Nuclear Power Plants "Forwards memo FELTON, U H Division of Rules and Records 83/04/25 NEWHAN.K A Debevoise & Liberman Ip 18872 360
- 8306160078 FOIA request for eight categories of records re certain sys in C-E designed huclear power plants BELL.N. Committee for Safe Power 83/03/31 Office of Administration 4pp 18893 203
- 8306160081 Responds to FOIA request for eight categories of records receptain sys in C-E designed nuclear power plants forwards
 App A documents identified in Categories 5 & 6 Category 8
 document not located Remaining documents filed in NRR
 FELTON, J M Division of Rules and Records 83/04/19 BELL, N
 Coalition for 8afe Power 4pp 18873 204 24X
 Fiche 50-317,83/04/19,8306160081
- --8203090638 Advises that three listed accident classes may each be more frequent than Commission safety goal in C-E designs that lack capability for core cooling via HPI injection & venting of RGS absence of feedwater replenishment PRIVIDED ACT ROUSDING. F. Division of Risk Analysis MURPHY, J. A. Reactor Risk Branch 82/01/27 TEDESCOR. Assistant Director for Licensing GPEIS.T. Assistant Director for Reactor Safety 23pp 18894 200
- --83061600B3 Submits daily highlight re diesel generator failures at facility on 820603 Incident caused by paralleling of diesel generators w/buses powered from offsite source licenses investigating incident.

 JAFFE. D. H. Operating Reactors Branch 3 82/06/04 DENTON.H F. CARTER. J. FISENNUT. D. O. NRC No Detailed Affiliation Given 18894 227 24X Fiche 50-317,83/04/17,830616008;
- B306160093 Addl response to FDIA request for documents re IAEA nuclear metl safeguards program Forwards App A documents App B Documents 1-B entirely withheld & Documents 9-16 partially withheld (ref FDIA Exemptions 1,3 & 3) FELTON, J M Division of Rules and Records B3/04/01 GREENBERG, E V Tuttle & Taylor 5pp 18892 011

- --8306160107 Forwards suggested questions & answers for 811202 hearing re [AEA safeguards, per request SHEA, J R Office of International Programs, Director 81/12/01 GLLINSKY, V Commissioners 7pp 18892 018
- --8306160112 Advises that Congressmen Dingell Ottinger & Hart 81(125 ltr classified as "SECRET-NSI" & Blil30 ltm unclassified.per Blil30 request Draft response to Blil25 ltr will be forwarded separately W/o encl marked-up 81(125 ltr REMMIT A NRC - No Detailed Affiliation Given 81/12/08 REAMER.C W NRC - No Detailed Affiliation Given 1p 18892 025
- --8306160115 Draft Commission paper proposing 1tr from Chairman thanking TE Shea for suggestions on improving IAEA safeguards & informing Commission that TE Shea Itr sent to State Dept DIRCKS.W J Office of the Executive Director for Operations 82/01/27 16pp 18892 026
- --8306160118 Forwards undisputed portion of response to 811125 ltr re IAEA safeguards sys, supplementing Commission 820302 ltr BRADFORD.P A Commissioners 82/03/04 OTTINGER,R L House of Rep. Energy & Commerce HART.G Senate DINGELL,J D House of Rep. 2pp 18892 042
- --8306160125 Forwards O Hart, MB Kratzer, L Scheinman, P Leventhal & HD Scholski testimonies & prepared statements at 830303 Joint hearing of Committee on Foreign Affairs in IAEA safeguards
 KAMMERER, C Office of Congressional Affairs 82/03/05 FALLADINOLN J , GILINSKY, V , BRADFORD, P A Commissioners 4pp 1692 044
- --8306160131 Testimony of G Hart before Subcommittee on Intl Economic Policy & Trade, Committee on Foreign Affairs, US House of Representatives re IAEA safeguards Committee 820301 revised meeting nutice encl HART, G Senate 82/03/03 4pp 18892 048
- --9305150134 Statement of MB Kratzer before Subcommittees on Intl Becurity & Scientific Affairs & Intl Economic Policy & Trade.Committee on Foreign Affairs, US House of Representatives re IAEA safeguards KRATZER.M B International Energy Associates, Ltd 82/03/03 35ec 18892 052
- --8306160138 Prepared statement of L Scheinman before Subcommittee on Intl Economic Policy & Trade Committee on Foreign Affairs, US House of Representatives re IAEA safeguards SCHEINMAN.L. Cornell Univ 92/03/03 17pp 18872 087
- --830&160143 Testimony of P Leventhal before Committee on Foreign Relations.US House of Representatives re IAEA safeguards LEVENTHAL.P Nuclear Club. Inc., The 82/03/03 10pp
- --8306160148 Prepared Statement of HD Sokolski before Subcommittee on Intl Security & Scientific Affairs & Subcommittee on Intl Economic Policy & Trade.Committee on Foreign Affairs.US House of Representatives re IAEA safeguards SCHOLSKI.H D Heritage Foundation 82/03/03 10pp 18892 120
- --B306160153 Responds to 820420 ltr re JACA safeguards NRC actively examining effective ways & means to continue support for IAEA safeguards
 PALLADINO.N J Commissioners 82/06/10 BLIX-H International Atomic Energy Agency (Austria), 1p 18892 130
- ~-B306160156 Forwards summary of IAEA safeguards sys U8 support for IAEA safeguards crucially important BLIX.H International Atomic Energy Agency (Austria) 82/04/20 PALLADING.N J Commissioners 4pp 18892.131
- --8306160162 Comments on proposed Commission paper & 1tr to Dept of State re classification of Morgan rept Proposed Commission paper unnecessary Proposed Itr to Dept of State should be modified H/o encl redraft Itr BRADY, R J Division of Security 82/04/26 BHEA, J R Office of International Programs, Director ip 18892 135
- --B306160165 Forwards draft Romania safeguards analysis for review & comment Response requested by B20524 W/o enc!
 SHERR.T S Material Transfer Safeguards Licensing Branch
 B2705/19 ZIMMERMAN, J Office of International Programs,
 Director BURNETY, B., MCCORKLE, O Division of Safeguards. 1p

- --8304160175 Forwards draft safeguards country analysis for Pakistan Analysis based on unclassified & foreign intelligence info provided by State Dept CIA or DDE repts not included W/o encl
 DAVIS-JO Office of Nuclear Material Safety & Safeguards, Director 82/05/24 PALLADIND, N J, OILINSKY, V, AHEARNE, JF Commissioners Ip 18892 137
- --B306160178 Forwards revised safeguards country analysis for Romania, including changes to reflect JQ Davis comments Section 3 3 on nuclear trade w/other countries changed in response to comments from Dfc of Inti Programs W/o encl BURNETT, R F Division of Safeguards B2/06/16 DAVIS, J Q Office of Nuclear Material Safety & Safeguards, Director Ip, 18872 138
- --9306160182 Forwards draft safeguards analysis for Romania, incorporating comments from Ofc of Intl Programs Updated analysis will be provided after receipt of comments from State Dept W/o encl DAVIS.J O Office of Nuclear Material Safety & Safeguards, Director 82/06/30 DIRCKS, W J Office of the Executive Director for Operations in 18892 139
- ---8305i50i85 Forwards draft safeguards analysis for Romania, incorporating comments from Ofc of Intl Programs Analysis based on unclassified info & classified foreign intelligence info provided by State Dept W/o encl DIRCKS.W J Office of the Executive Director for Operations 82/07/12 PALLADIND.N J, OILINSKY.V, AMEARNE, JF. Commissioners ip 18892 140
- --8306160190 Forwards revised draft safeguards analysis for Romania for transmission to State Dept No sensitive foreign intelligence into employed W/o encl Partially deleted answers & questions re IAEA safeguards encl BURNETT, R F Division of Safeguards 82/07/15 SHEA, J. R Office of International Programs, Director Spp 18892 141
- --8306160193 SECY-82-025
 Forwards H Gruem preliminary comments on Morgan memo re
 IAEA safeguards for Billi9 press conference SECY title &
 other safeguards info deleted
 DIRCKSHW J Office of the Executive Director for Operations
 82/01/19 Bpp 18892:146
- --0306160198 BECY-02-046
 Informs Commission of existing interagency groups involved in US efforts to upgrade IAEA safeguards & provides brief rept on status of activities W/e encl outline & status of action plan
 DIRCKB,N J Office of the Executive Director for Operations
 82/02/02 13pp 18892 154
- --8306160203 Discusses implications of R Richter testimony before Senate Foreign Relations Committee & House Foreign Affairs Committee re Iraqi nuclear program & weaknesses in IAEA safeguards Safeguards info deleted DIRCKS.W J Office of the Executive Director for Operations 82/03/09 BRADFORD.P.A Commissioners 3pp 18872 167
- --8306460208 SECY-82-210
 Forwards summary of significant NRC & Executive Branch seferts to improve IAEA safeguards & estimate of expended resources Safeguards info deleted W/o encl rept on US assistance to IAEA & outline of areas needing improvements DIRCKS: W J Office of the Executive Director for Operations 82/05/26, 17pp 18892.170
- --8306160211 Forwards partially released transcript of 820602 briefing on efforts to improve IAEA safeguards in Washington, DC Withheld portions per 100FR9 104(a)(i) listed CHILKS J Office of the Secretary of the Commission. 82/08/03 Office of the Secretary of the Commission 2pp 18892:187
- --B306160R16 SECY-B2-313
 Informs Commission of receipt of Dept of State B20702 ltr
 re classification of Morgan rept. State agrees that rept
 should be classified "ascret" Safeguards info deleted W/o
 listed encls
 DIRKS.W J. Office of the Executive Director for Operations
 B2/07/26 2pp 18892 282
- --8306160222 Draft Commission paper recommending Commission approval of proposed responses to Benator Hart & Representatives Dingell & Ottinger 821123 & 30 Itrs re IAEA safeguards Safeguards info deleted M/o encl proposed Itrs DIRCKS: W J Office of the Executive Director for Operations 81/12/31, ip 18892: 284
- B30616009B FDIA request for insp repts & responses to insp repts for all Pharmatopes, inc nuclear pharmacies licensed by NRC. MCDUNALD,D D Nuclear Pharmacy, inc DDM 383-12 83/03/16 FELTON,J M Division of Rules and Records 1p 18891.244

- 8304160110 Partial response to FOIA request for inspirepts & responses to inspirepts for all Pharmatopes, Inc. nuclear pharmacies licensed by NRC Forwards App A documents Search for other related documents continuing FELTON-J M Division of Rules and Records 83/04/14 DESSEL.6 Nuclear Pharmacy, Inc. 4pp 18891 245
- --8306160124 IE Insp Rept 30-18718/81-01 on 810720 Noncompliance noted possession of Xe-133 not authorized by Doctors Hosp license, CRM signs not posted on premises & survey matls disposal not recorded CAIN.C L Region 4, Dallas, Office of the Director (81/03/01) 81/07/01 9pp 18871/249
- --8306160132 Forwards IE Insp Findings & Licensee Ack of License 35-19383-01MD Signature required agreeing to correction of violations within 30 days Mo encl CAIN.C L Technical Inspection Branch 81/07/30 LAHN.J M Pharmatopes, Inc. ip 18891 258
- --8306160137 Responds to NRC 801215 ltr re violations noted in IE Insp Rept 30-14826/80-01 Corrective actions individual receiving overexposure to hands terminated & overexposure rept submitted Protests imposition of civil penalties HEBNER.M T . IRMIN.R Pharmatopes. Inc 81/01/06 Region i, Philadelphia. Office of the Director 33pp 18891 281
- B306160149 F01A request for SECY-82-499 COMER.E Edison Electric institute. B3/04/04 FELTON, J H Division of Rules and Records 1p 18893 198
- 8306160151 Responds to FOIA request for SECY-82-479 Forwards transmittal memo attached to SECY paper Requested document available in PDR W/o encl FELTON.J M. Division of Rules and Records 83/04/28 COMER.E Edison Electric Institute ip. 18893-199
- 8304160155 FOIA request for four categories of documents re McGraw-Edison Co. Horthington Compressors, Inc. Worthington Svc Corp & Edison Inti ADRAPNA, J M Spiegel & McDiarmid 83/04/04 FELTON, J M Division of Rules and Records 2pp 18873 200
- 8306160160 Responds to FOIA request for four categories of documents re McGraw-Edison Co.Worthington Compressors, Inc. Worthington Svc Corp & Edison Intl. Inc NRC has no documents subj to request FELTONJY M Division of Rules and Records 83/04/27, ADRAGNA, J M Spisgel & McDiarmid ip. 18893 202
- 8306160171 Finel response to FOIA request for documents concerning NRC policy re issuances of press releases in connection w/ enforcement & licensing activities Forwards partial Document 2 listed in app Document I available in PDR FELTON.J M Division of Rules and Records 83/04/27 HARTMAN.S Debevoise & Libermen. 2pp 18892 347
- --8306160173 Discusses specific guidelines for release of info to news media by Ofc of Investigation personnel. Instructions should not be construed as contradicting any other stated NRC policy Info partially deleted a Diffice of Investigation 2pp 18892 350
- 8306160174 FDIA request for all correspondence from RO McClintock to NRC since 830314. MCDDNALD.D D Nuclear Pharmacy, Inc. DDM 483-8 83/04/06 FELTON.J M Division of Rules and Records 1p, 18872 352
- 8306160177 Responds to FOIA request for all correspondence from RO McClintock to NRC since 830314 Forwards RO McClintock 830411 ltr FELTONJM Division of Rules and Records 83/04/25 MCDONALD, D D Nuclear Pharmacy, Inc. ip 18892 353
- ~-8306160179 Advises that author no longer responsible for radiation safety & regulatory affairs program for Nuclear Pharmacy: Incres of 830317.
 HOULINTOCK.R.D. Affiliation Unknown 83/04/11 DELMEDICO.J. '''nn of Fwel Cycle & Material Safety 1p 18892:334

rr SECY-82-306 & SECY-82-499 b, Leiby & MacRae 83/03/24 FELTON, J M 's ip 18876, 297.

Tuest for SECY-82-306 & Y-82-497 published on illable in PDR Forwards ords 83/04/28 DIBBLE/C 8 8876-298

- --8209210553 Requests proposed reg guide re nuclear energy liability policy & related rule mod be prepared in final form pointing out potential for protracted licensing hearings resulting from deletion of IOCFR140. App A
 DIRCKS, W J Office of the Executive Director for Operations 82/09/15 MERR, W Q Office of State Programs, Director lp 18876 299
- 8306160192 FOIA request for documents re FOIA Request 82-6189 Requests fees be walved GARDE.B P Government Accountability Project 83/03/24 Office of Administration 2pp 18893 123
- 8306160197 Responds to FOIA request for documents re FOIA Request 82-618 Forwards App A documents Documents 18 & 19(d) partially deleted (ref FOIA Exemption 6) FELTON, J M Division of Rules and Records 83/04/25 OARDE, B p Government Accountability Project 4pp 18893 125 24X Fiche 50-206,83/04/25,8306160197
- --8306160200 Forwards FOIA request Releasability determinations indicate; in response ltrs to requester No action required FELTON.1 M Division of Rules and Records 83/03/24 DIETCH.R Sauthern California Edison Co Ip 18893
- --8306160200 Forwards FOIA request Releasability determinations indicated in response ltrs to requester No action required FELTON, J M Division of Rules and Records 83/03/24 DIETCH, R Southern California Edison Co ip 18893
- --8306160204 Requests disclosure determination for listed document subj to FOIA Request 82-618 by nown on 830314 GRIMBLEY,D H Division of Rules and Records 83/03/11 ALEXANDER,I Region 5, Office of Director 1p 19893 140
- --B306160207 Requests disclosure determination for listed Sociments subj to FOIA Request 82-618
 GRIMSLEY, D. H. Division of Rules and Records 83/02/07
 ALEXANDER, I. Region 5, Office of Director 2pp 18893 148 24x
 Fiche 50-206.63/04/25.8306160197
- --8306160218 Forwards documents re B Garde (OIA requestion behalf of EE Kentifor documents regarding 821120 JE rept "Special NRC Insp of San Onofre 1,2 & 3 (FOIA-82-618)" W/o encl FORTUMA.R A Office of Investigation 83/01/24 CARR.J C Division of Rules and Records 3pp 18893 150 24X Fiche 50-206,83/04/25,8306160197
- --8306160223 Request disclosure determination for document originated by ofc re FOIA Request 82-618 by noon on 830119
 GARR.J.C Division of Rules and Records 83/01/12 WILEON, V
 Office of Nuclear Reactor Regulation, Director 2pp 18893 157
 24% Fichs 50-206.83/04/23.8306160197
- --8306160230 Submits list of Region V Ofc of Investigation File Serials 26-42. "BONOS-Allegations Re Welding of Piping by EE Kent," Case 3-82-021 Serials 1-25 previously provided in response to FDIA Request 82-528 SHACKLETON, O C Office of Investigation 83/01/03 FORTUNA, R A Office of Investigation 3pp 18893 159 24% Fiche 50-206,83/04/25,8306160197
- --8306160243 Forwards list of documents available at Region V re 8 Carde FOIA Request 82-618 on EE Kent behalf, for documents concerning 821130 IE rept "Special NRC Insp of San Onofre 1,2 & 3" ALEXANDER, I Region 5, Office of Director 83/12/28 REED, C A Division of Rules and Records 3pp 18893 162 24X Fiche 50-206,83/04/25,8306160197
- ---8306160253 Forwards DC Shackleton 821109 memo transmitting documents subj to FDIA Request 82-528 Review of Documents 1,2,10 & 19 by Region V recommended Confidentiality not sought by EE Kent
 FORTUNA, R A Office of Investigation 82/12/10 CARR, J C DIVISION of Rules and Records 1p 18893 165 24X
 Fiche 50-206,83/04/25,8306160197
- --8306160263 Forwards list of documents responsive to FOIA Request 82-528 re EE Kent allegations concerning facilities from Oct 1980 to present Region V not awars of allegation until Oct 1982 SHACKLETON O C Region 5. Office of Director 82/11/09 FORTUNA, R A Office of Investigation 5pp 18893 166 247 Fiche 50-206, 83/04/25, 8306160197

- -8306160276 Requests info responsive to FOIA Request 92-528 for documents re CE Kent allegation concerning facilities from Oct 1980 to present be forwarded to Div of Rules & Records
 - Oct 1980 to present be forwarded to Div of Rules & Records by 921116
 CARR.J C Division of Rules and Records 82/11/04 KIME.C Director's Office Office of Inspection and Enforcement ALEXANDER.I Region 5, Office of Director BOWERS, H Office of Inspector & Auditor 1p 18873 171 24X Fiche 50-206, 83/04/25, 8306160197
- 8306/60281 Forwards list of documents responsive to FOIA Request 82-528 re EE Kent allegations concerning facilities from Oct 1980 to present per 82/104 memo Related into encl ENGELKEN,R H. Region 3. Office of Director 82/11/17 CARR,J C Division of Rules and Records 5pp 18893 174 24X Fiche 50-206,83/04/25,8306160197
- 8306160272 FOIA request for tape recolding & NRC transcript of meeting w/D Kirsch. O Shackleton & P Joukoff at Dana Point. CA KENT.E E Affiliation Unknown 82/11/08 Office of Administration 8pp 1887J 187
- 3306160301 Forwards FOIA Request 82-618 for documents re 821130 IE rept
 "Special NRC Insp of San Onofre 1.2 % 3 " Documents
 responsive to request should be forwarded to Div of Rules &
 Records by 830104
 CARR.J C Division of Rules and Records 82/12/22 FORTUNA.R
 Office of Inspector & Auditor ALEYANDER, I Region 5, Office of
 Director ip 16873 193 24X Fiche 50-206.83/04/25.8306160197
- 16170084 FOIA request for five categories of documents re Matl/ hyproduct License 20-00297-93 Fee waiver requested MICE, J.C. Affiliation Unknown 83/03/18 Office of udministration 2pp 18708 056
- 16170089 Responds to FOIA request for five categories of documents re lati/Byproduct License 20-00277-53 Forwards listed ocuments License Amend 18 % documents identified by Items & 5 cannot be located ELTON.J M Division of Rules and Records 83/04/14 GRICE.J C ffiliation Unknown ip 18908-058
- 009030104 Application for amend of Matl/Byproduct License 20-00297-53 Amend authorizes individuals approved by radiation safety committee to use or supervise use of Cm-244 in sealed sources for surface analysis & calibr SHAPIRO.J Harvard Univ 80/07/10 Jpp 18908 115
- 010070140 Mat1/Byproduct License 20-00297-53 for President & Fellows of Harvard College is amended per 800710 application Amend 32 adds 50 mCi of Cu-244 sealed sources for 820 defined in EOCFR30 4(g)

 LAMASTRANIA Licensing Management Branch 80/09/04 ip 16908 062
- 10&170097 Amend 34 to Matl/Byproduct License 20-00297-53, changing license name & address.per 821119 ltm CLENN.JE Region 1. Office of Director 82/11/30 lp 18408 009
- 06170079 Amend 33 to Matl/Byproduct License 20-0027/-53.changing Items 6.7 & 8.authorizing use of listed matl & revising Condition 19 re possession & use of licensed matl.per 810710
- ltr Division of Fuel Cycle & Material Safety 81/09/04, 2pp 1890F 040
- 06170192 Amend 31 to Mati/Byproduct License 20-00297-53, changing Condition 20.authorizing use of 15 mCi Ni-63 at research lab at Harvard Forest.per 7/1118 1tr MADE, Radioisotopes Licensing Branch (Pre 790501) 77/12/01 18908 043
- 75170155 Amend 30 to Mati/Byproduct License 20-00297-53, changing Condition 10 re use of licensed mati.por 770614 ltr 304YER.JE Radioisotopes Licensing Branch (Pre 790501) 77/06/30 ip 18908 064
-)&170157 Amend 29 to Matl/Byproduct License 20-00297-53.changing Condition to re use of licensed matl.per 751107 ltr PAVIS.F C Division of Fuel Cycle & Material Safety 75/12/22 18908.045
- 16170160 Amend 28 to Matl/Byproduct License 20-00297-53; adding Cm-244 lated sources for R&D use, per 750110 application NRC No Detailed Affiliation Given 75/03/26 1p 870B 066

- --8306170167 Amend 27 to Matl/Byproduct License 20-00297-53.changing license in entirety.per 740222 ltr & 740409 application Amend authorizes use of any byproduct matl between Atomic Numbers 3-83.tritium.Po-210, Th-228.Am-241 & Cf-252 Numbers 3 L BOWYER, J E At 198702 5pp Atomic Energy Commission, Directorate of Licensing 1500 16908 067
- --8306170170 Amend 26 to Matt/Byproduct License 20-00297-53, changing Condition 10 re use of byproduct matl, per 720707 ltr BOLYER, J E Atomic Energy Commission, Directorate of Licensing 73/03/13 ip 18908-072
- --8306170174 Amend 25 to Matl/Byproduct License 20-00297-53, changing Subitems 7 F & 8 F, authorizing use of 5 6 mCi sealed sources (ORNL platinum foil & ERO type ALC or SALC), per 710427 ltr BOWYER, JE Atomic Energy Commission 71/05/21 1p
- --8306170178 Amend 24 to Mati/Byproduct License 20-00297-53, adding Condition 23 authorizing use of C-14 at Lynn Harbor, MA, per 701022 & 1103 ltrs Atomic Energy Commission 70/11/27 1p 18908 074
- --8306170185 Amend 23 to Hatl/Byproduct License 20-00297-53, changing Condition 20 re possession & use of byproduct matl & adding Condition 22, authorizing burial of byproduct matl at Primate Ctr in Southboro, MA, per 690005 ltr BDWYER, J E Atomic Energy Commission 69/07/08 1p 18908 075
- --8306170190 Amend 22 to Matl/Bygroduct License 20-00297-53, changing license in entirety.per 690130 application Amend authorizes any byproduct matl between Atomic Numbers 3-83, tritium. Po-210, Th-228, Am-241 & Cf-232 for R80 BGWYER.J E Atomic Energy Commission 69/03/24 App 18908 O
- --8306170194 Amend 21 to Mat1/Byproduct License 20-000297-53 changing Subitem B F to read 55 9 uCi BUCHANAN, C R Atomic Energy Commission 68/07/18 1p. 18708-082
- --8306170198 Amend 20 to Matl/Byproduct License 20-00297-53, adding Cf-252 platinum foil for RMD,per 680701 telegram BQWYER.J E Atomic Energy Commission 68/07/05 ip 18908 083
- --8306170203 Amené 19 to Matl/Byproduct License 20-00297-53, changing Condition 18, authorizing disposal of licensed matl w/listed exception & revising Condition 20 re possession & use of byproduct matl, per 60506 & 15 ltps
 BOWYER, J E Atomic Energy Commission 68/06/27 2pp 18908 08
- ---8306170208 Amend 17 to Mati/Byproduct License 20-00297-\$3, changing license in entirety, per 670223 application Amend authorizes any byproduct mati between Atomic Numbers 3-83 inclusive: tritium; Po-210, Th-228 & Am-241 for R&D use DOWYER, J E Atomic Energy Commission 67/03/30 5pp 18708 0
- --8306170212 Amend 16 to Mat1/Byproduct License 20-00277-53, adding Condition 23 authorizing use of 1 mCi C-14 source at Youngstown Sheet & Tube Co. Campbell Works in Youngstown. ON. per 470216 ltr
 BOWYER. J E Atomic Energy Commission 47/03/03 ip 18908 6 Atomic Energy Commission 67/03/03 ip 18908 091
- --8306170220 Amend 15 to Matl/Byproduct License 20-00297-53 changing Condition il. authorizing use of byproduct matl at specified locations, per 660606 ltr BOWYER. J E Atomic Energy Commission 66/07/11 lp 18708 092
- --8304170225 Amend 14 to Matl/Byproduct License 20-00297-53 thanging Condition 21 E re transportation vehicle of licensed matl, per 660415 ltr BOWYER, J.E. Atomic Energy Commission 66/05/16 ip 18908 093
- --8306170229 Amend 13 to Mati/Byproduct License 20-00297-54, adding Am-241 in any form for R&D, per 651130 ltr BUCHANAN, C R. Atomic Energy Commission 65/12/08 ip.
- --8306170235 Amend 12 to Matl/Hyproduct License 20-00297-53, adding Condition 22, authorizing use of 1 mCi C-14 source at Pittsburgh Steel Co.Monessen Works in Monessen.PA.per BOWYER, J E Atomic Energy Commission 65/11/08 ip 18908 093
- --8306170238 Amend 11 to Matl/Byproduct License 20-00297-53, changing license in entirety, per 650730 ltr Amend authorizes any byproduct matl between Atamic Numbers 3-83 inclusive, tritium, Po-210 t Th-228 for R&D BUNYER. J E Atamic Energy Commission 65/09/17 App. 18908 096

- --8306170242 Amend 10 to Matl/Byproduct License 20-00297-59, adding Condition 24, authorizing use of I mCi C-14 source at Jones Laughlin Steel Carp, South Works in Pittsburgh, PA, per 450709 & 21 ltrs
 - BOWYER, J E Atomic Energy Commission 65/07/28 1p 18908 102
- --8306170244 Amend 9 to Matl/Byproduct License 20-00297-53 changing Condition 17, authorizing disposal of licensed matl w/listed exception.per 650925 ltr 80WYERJE Atomic Energy Commission 65/05/07 lp 18908 103
- ---8306170248 Amend B to Matl/Byproduct License 20-00277-53, changing symbol below license number to C67, extending expiration date to 670331 & revising Item 9 A-9 D.per 650217 itr & application BGMYER.J E Atomic Energy Commission 65/03/31 1p 18908 104
- --8306170252 Amend 7 to Matl/Byproduct License 20-00297-53, changing Condition 11. authorizing use of byproduct matl at specified locations.per 650125 application & ltr BOWYERJ E Atomic Energy Commission 65/03/07 1p 18908 105
- --8306170258 Amend 6 to Matl/Byproduct ticense 20-00297-53 changing Item 8 A re possession limit of byproduct matl, per 641106 Itr BOHYER, J. E. Atomic Energy Commission 64/12/01 Ip 19908 106
- --8306170262 Amend 5 to Matl/Byproduct License 20-00297-53, changing Condition 11, authorizing use of byproduct matl at specified locations, per 641015 ltr BOWERJUE Atomic Energy Commission 64/11/04 lp 18908 107
- --8306170267 Amend 4 to Matl/Byproduct License 20-00297-53, changing Condition 21 re possession & use of byproduct matl, per 640901 ltr BOWYER.JE Atomic Energy Commission 64/09/30 ip 18908 108
- ---8306170269 Amend 3 to Matl/Byproduct License 20-00297-83, adding Condition 23, authorizing use of P-32 at Drumlin Farm in Lincoln.MA to study habitat selection of queen ant & foreging patterns of worker ants.per 640624 & 0803 [trs BUHYER.J E. Atomic Energy Commission 64/08/25 1p 18908 109
- --8306170272 Amend 2 to Matl/Byproduct License 20-00297-53, adding Condition 22 re transportation of byproduct matl/per 640326.
 O611 & 16 litts
 BDWYER-J E Atomic Energy Commission 64/08/04 ip 18908 110
- --8306170274 Amend I to Matl/Byproduct License 20-00297-53, adding Condition II.authorizing use of byproduct matl at specified locations, changing Condition 17 re disposal of radwastes & deleting Conditions 18 & 19. per 631108 ltr BOWYER, J E Atomic Energy Commission 63/12/06 ip 18908 111
- --8306170280 Matl/Byproduct License 20-00297-53 for President & Fellows of Harvard College, authorizing any byproduct matl between Atomic Numbers 3-83, inclusive in any form for R&D BOWYER.J E Atomic Energy Commission 63/06/19 3pp 18908 112
- --8306170284 Returns application for renewal of Matl/Byproduct License 20-00297-33 for signature BONYER.J E Atomic Energy Commission, Directorate of Licensing 45606 74/04/02 SHAPIRO.J Harvard Univ ip 18908-118
- --8306170288 Ack receipt of application for renewal of Mat1/Byproduct License 20-00297-53 License will not expire until final action taken by AEC 80MYER.J E. Atomic Energy Commission. Directorate of Licensing 74/03/21. JDHNSON:R U Harvard Univ Ip 19908 119
- --B306i70291 Forwards application for renewal of Matl/Byproduct License 20-00297-53 for use of radioisotopes JOHNSON,R U Harvard Univ 45605 74/02/22 BOWYER, J E Atomic Energy Commission ip 18908 120.
- --830&170295 Application for renewal of Hatl/Byproduct License 20-00297-53, authorizing individuals approved by radioisotope committee to use any Syproduct math between Atomic Numbers 3-83, tritium, Po-210, Am-241, Th-228, Cf-225 for RED SHAPIRO, J Harvard Univ 45605 74/04/09 22ep 18908 121
- --8306170298 "Regulations for Use of Radioisotopes at Harvard Univ "
 Related info encl.
 * Harvard Univ 43606 74/04/09 28pp 18908 143
- 8306200035 FOIA request for blueprints & explanations of assorted power plants SPECTOR, B. Affiliation Unknown, B3/05/08 NRC - No Detailed Affiliation Given ip 18717 317

- B30620003/ Responds to FOIA request for blueplints / explanations of assorted power plants Forwards documents describing safety & NRC licensing process for reactors Drawings & design details available in listed LPDRs in Nr FELTON J M Division of Rules and Records 83/05/18 SPECTUR RAFFILIATION Unknown 2pp 18919-320
- --8306200040 WASH-1250
 Excerpt from MABH-1250. "Safety of Nuclear Power Reactors (Light Water-Cooled) & Related Facilities "
 ** NPC ~ No Detailed Affiliation Given 83/05/18 39pp 18917 322
- 8306200273 FOIA request for records to Book Mart Intl.Inc & DL Hall TRUITT,M O . DANA.J T Wilner, Cutler % Pickering 87/04/13 Office of Administration 3pp 18919 223
- 8306200277 Responds to FOIA request for records to Book Mart Intl.in. & DL Hall Forwards documents listed in app Documents also available in PDR FELTON.J.M Division of Rules and Records 83/04/28 TRULT IS () DANA.J T Wilner, Cutler & Pickering Ppp 18719-220
- --8306200280 Discusses corporate structure & svcs provided by Dank Harl Intl. (no Related info encl HALL, D.L. Book Mart International, Inc. 83/04/28 NRC No Detailed Affiliation Given 9pp 18919 228
- --8306200282 Ack NRC interest in Book Mort Intl. Inc Brochures & newsletter encl HALL.D L Book Mart International, Inc 83/04/28 NRC W Detailed Affiliation Given 4pp 18719 237
- --8306200284 Requests execution of blanket purchase order w/Book Hait Entl. Inc for scientific texts & medical books HAMILTON.M . DEVINE. 8 NRC - No Detailed Affiliation Given 80/09/01 1p 18919 241
- --B306200286 Requests availability of funds for library book acquisitions from Book Mart Intl.Inc Related info encl MURPHY.L G Administrative Contracts Branch 80/10/30 CDDPER.L P Administrative Contracts Branch 16pp 10919
- --8306200287 Requests cancelation of Blanket Purchase Agreement
 DR-Bi-0181 w/Book Mart Intl Company apparently out of
 business Related info encl
 DEVINC,R C NRC No Detailed Affiliation Given 81/04/20 "pp
 18917 258
- --8306200280 Discusses corporate structure 5 svcs provided by Dook Mart Intl.Inc Related info encl HALLO L Book Mart International. Inc 83/04/28 NRC Mo Detailed Affiliation Given 9pp 18919 228
- --8306290287 Ack NRC interest in Book Mart Intl.Inc Brochures & newsletter and I HALL.D i. Book Mart International, Inc 83/04/28 NRC | Detailed Affiliation Given App 18919-237
- --8306200284 Requests execution of blanket purchase order w/Dook Hart Intl. In. for scientific texts & modical books HAMILTON.H , DEVINE.B NRC - No Detailed Affiliation Given BO/209/01 1p 18919 241
- --8306200286 Requests availability of funds for library book acquisitions from Book Mart Intl. Inc. Related info enci MURPHY.L. 9 Administrative Contracts Branch 60/10/30 COOPER.L.P. Administrative Contracts Branch 16pp 18919 24a
- --8306200287 Requests cancelation of Blanket Purchase Agreement DR-81-0181 w/Book Mart Intl Company apparently out of business Related info encl DEVINE.R & NRC No Detailed Affiliation Given 81/04/28 3pp 18919 298
- B306200291 Informs that response to Seacoast Anti-Pollution League B30328 FOIA request has not been received Statute requires response within 10 working days Prompt attention appreciated BACKUS,R A Backus, Shea > Meyer 83/05/06 Division of Rules and Records 19 18720 027
- ~~8306200293 FOIA request on behalf of Seacoast Anti-Pollution League. G Speth ltr to Commissioner Absarne on or about 800320 concerning NRC treatment of Class 9 accidents in EIS BACKUS.R A Dackus. Shea & Meyer 83/03/28 Division of Rults and Records 3pp 18920 028

- 8306200295 FOIA request for eight categories of documents re facility JOHNSTON, M M Affiliation Unknown 83/04/11 Division of Rules and Records 2pp 18920 222 24% Fiche 50-341,83/04/11,8306200295
- 8305200276 Partial response to FOIA request for ltr from G Speth to Commissioner Ahearne on or about 800320 concerning NRC streatment of Class 9 accidents in EIS Forwards documents listed in app Review continuing FFLTON.J M Division of Rules and Records 83/05/16 BACKUS.R A Bactus. Shea & Moyer 2pp 18920 031
- 8306200299 Partial response to FOIA request for eight categories of documents re facility Copies of listed documents will be provided NUREG available from NTIS FELTON.J M Division of Rules and Records 83/05/06 JOHNSTON.M M Affiliation Unknown Ip 18920 224 24X Fiche 50-341,83/05/06.
- 8306200434 Responds to FDIA request for NRC Investigation Rept 1-83-003 re fac(lities Rept withheld (ref FDIA Exemptions 5 % 7) FELTCHLJM Division of Rules and Records 83/05/02 KILCOYNE, J Kilcoyne, J J 1p 18920 017 24% Fiche 50-289, 83/05/02, 8306200434
- 8306200438 F01A request for NRC Investigation Rept 1-83-803 re facilities KILCOVINE-J J Kilcovne, J 83/03/28 FELTON, J Division of Rules and Records 1p 18920 018 24X Fiche 50 289,83/03/28, #30x200438
- B305210289 Responds to FOIA request for documents re NRC current, potential or future use of line of business data published by Federal Trade Commission No records subj to request available FELTON-J M Division of Rules and Records 83/04/05 BILEK, M Paut, Wess, Rifkind, Wharton & Garrison 1p 18925 326
- B306210293 F01A request for documents re NRC current potential or future use of line of business data published by Federal trade Commission B1LEK,M L Paul, Weiss, Rifkind, Wharton & Garrison B3/03/29 Office of Administration 2pp 18925-327
- B308210297 FOIA request for part number & pricing on recent order avarded to Federal Sales Svc for 67 HELKO work stations MEATH.R C Dota Stor. Inc 83/03/21 MCNULTY.A Division of Contracts 1p 18925 323
- B306210300 Responds to FDIA request for part number & pricing on recent order awarded to Federal Sales 5vc for 67 HFLKO work stations Forwards NRC Purchase Order DR-83-0727 FELTON.J M Division of Rules and Records 83/04/11 HEATH,R C Data Stor, Inc. 1p 18925-324
- --8306210303 Purchase Order DR-83-0727 awarded to Federal Sales Svc for A7 HELKO work stations REBEILO, J. E. Administrative Contracts Branch 83/02/25 lp 18925-325
- 8306210306 Partial response to FOIA request for NRC records or security violations & safeguards events at nuclear facilities Repts listed on App A available in PDR Search for add1 documents tub; to request continuing FELTON, JM Division of Rules and Records 83/05/16 GOLDENBERG, G Scripps-Howard Newspapers 2pp 18925 176 24X Fiche 90-000,83/05/16,8306210306
- 8386210312 Responds to FOIA request for info re NRC involvement in activities occurring at US Army Mall Command firing range MRC has no documents subj to request Request referred to DOD for direct response FELTON.J M Division of Rules and Records 83/05/16 MARVEY.P W Underhill Range Committee ip 18922 338
- 8306210313 FOIA request for info re NRC involvement w/activities within confines of UB Matl Command firing range HARVEY.P. W. Underhill Range Committee 83/04/27 Office of Administration Ip 19722-339
- 8308210314 FDIA request for NRC records re security violations & safeguards events at nuclear facilities COLDENGERG.O Scripps-Howard Newspapers 83/04/22 FELTON, J M Office of Administration 2pp 18925 198 24X Fichs 50 000, 83/04/22, 8308210314
- 8306210318 FDIA request for all documents re proposals & revs to proposals submitted under RFP RS-SECY-82-473 BMARP.(H Alderson Reporting 83/03/21 FELTON, J M Division of Rules and Records ip 18921 301

- 8306210320 Responds to FOIA request for all documents re proposals & revs to proposals submitted under RFP RS-SECY-82-473
 Forwards nonproprietary version of technical proposal & certain RFP pages
 FELTON.J M Division of Rules and Records 83/04/07 SHARP, I H
 Alderson Reporting 1p 18921 302
- --8306210323 Nonproprietary version of Proposal RS-SECY-02-473,
 "Stenographic Reporting Syts"
 4 Interstate Court Reporters, Inc. 83/04/07 22pp 18921 303
- ---8306210326 Splicitation, offer & award of "Stenographics Reporting Sycs," to Interstate Court Reporters. Inc JACKBON, B M Interstate Court Reporters, Inc 82/08/06 5pp. 18721-325
- 8306210322 FOIA request for final rept on probability & consequences of highway & rail hazardous math accidents published Dec 1982 RESNIKOFF.M Council on Economic Priorities 83/02/21 Division of Rules and Records 1p 18923
- 8306210327 Responds to 830221 FOLA request for final rept, "Definition of Bounding Physical Test Representative of Transport Accidents Rail & Truck," & 830406 appeal re NRC lack of response to initial request Forwards requested rept FELTON.J M Division of Rules and Records 83/04/22 REBNIXOFF.M Council on Economic Priorities (p. 18923-002
- --8304210332 Draft Vol I to "Final Rept on Severe Reil & Truck Accidents Toward Definition of Bounding Environs for Transportation Packages " * Ridihalgh, Eggers & Associates NRC-04-80~182 82/12/31 NRC - No Detailed Affiliation Given 250pp 18923 004
- --B306210336 PLG-0207 DRFY
 Draft "Analysis of Severe Transportation Accident Environ
 Frequencies "
 SIU.N D. GARRICK, B.J. Pickard, Lowe & Garrick, Inc. B1/09/30
 8100 18723 280
- --8306210332 Draft Vol I to "Final Rept on Severe Rail & Truck Accidents Toward Definition of Bounding Environs for Transportation Packages " + Ridihalph, Eggers & Associates NRC-04-80-182 82/12/31 NRC -- No Detailed Affiliation Given 250pp 18723 004
- --8306210336 PLG-0207 DRFT
 Draft "Analysis of Beyere Transportation Accident Environ
 Frequencies"
 SIU.N O . GARRICK, B J Pickard, Lowe & Garrick, Inc. 81/09/30
 81pp 18923 280
- 8306210330 Appeals NRC lack of response to 8 denial of FOIA request for final rept. "Definition of Bounding Physical Yest Representative of Transport Accidents Rail & Truck "RESNIKOFF,M Council on Economic Priorities 83/04/06 Office of the Executive Director for Operations 1p 18923 003
- 8306210340 Responds to FOIA request for names & locations of various nuclear facilities licensed by NRC Forwards NUREO-0871.
 "Bummary Info Rept" W/o encl
 FELTON.J M Division of Rules and Records 83/04/08 THOMAS.D M
 Overseas Packing. Inc. Lp. 18921 330
- 8306210342 FDIA request for names \$ locations of various nuclear facilities licensed by NRC THOMAS.D M. Gyerseas Packing. Inc. 83/03/15 NRC No Detailed Affiliation Given. Ip. 18921.331
- 8306230005 Add1 response to FDIA request for all drafts, insplevaluation repts & comments on J Keppier 820719 reptire special safety insplements on J Keppier 820719 reptire special safety insplements listed in App 8, Add1 records under review FELTON, J M Division of Rules and Records 83/03/25 GARDE, 8 Government Accountability Project 3pp 18952 001 24X Fichs 50-373, 83/03/25, 8306230005
- --8306230012 Insp Evaluation Rapt 82-35 re allegations of drilling & const deficiences at site Concerns resolved effectively by licensee & NRC Related draff info encl * NRC No Detailed Affiliation Given RF 1206 83/03/25 265pp 18782 004. 24X Fiche 50-373,83/03/25,8306230005
- --8306230015 Evaluation Rept on Atty General of IL allegations redrilling & const deficiencies at site Allegations w/o merit > Structural Engineering Branch 83/03/25 4pp 18952 269 24X Fiche 50-373.83/03/25.8306230005.

- --8306230019 Summary of B20611 mgt meeting at site re ongoing investigation of Atty General of IL allegations concerning drilling & const problems
 DAVISA B Region 3, Office of Director B2/06/17 Region 3, Office of Director 3pp 18952 280 24X Fiche 50-373,83/03/25,8306230005
- --8306230022 Discusses readiness of facility to receive DL.per request Initial recommendation or issuance of DL withdrawn pending further quantification & clarification of const GC issues Insp evaluation & related info enc!
 REIMANN.F W Region 3. Office of Director 62/05/28
 VACKIN.I N. WALKER.R D Region 3. Office of Director 74pp 19752 283 24X Fiche 50-373,83/09/25.8306230005
- --8306230024 "Assessment of Effects of Nicked Reinforcing Steel," technical rept evaluation CHAN.8 P Systematic Evaluation Program Branch 82/06/15 4pp 18932 357
- --8306230028 Forwards trip rept of 820629-26 visit to Region III & site re containment bolt installation problem Engineering discussion recommendations & exam conclusion included HOOD, A C SPS Technologies 82/06/28 JACKIN, I N NRC No Betailed Affiliation Given 16pp 18952 361 24X Fiche 50-373,83/03/25,8306230005
- --830623003; Comments on agenda items for 820625 site meeting retechnical aspects of torque wrench calibr Motor operator/ yote connection tightness check-torque wrench calibr accuracy & expansion anchor installation discussed RODABAUGH, EC E C Rodabaugh Associates, Inc 82/06/26 TERAD, D Mechanical Engineering Branch App 18953,015 24X Fiche 50-373,83/03/25.8306230003
- --8306230037 Forwards OA Manual 18-1 2 audit rept Plant const satisfactory REED.C Commonwealth Edison Co 82/07/08 KEPPLER.J G Region 3, Office of Director 1p 18753 021 24X Fiche 50-373,83/03/25, 8306230005
- --8306230039 GA Manual 18-1 2 audit rept Related correspondence encl MANBINO, N. J. Commonwealth Edison Co. B1/08/04 60pp 18993 022 24X Fiche 50-373, B3/03/25, B306230005
- --8306230043 Discusses 820630,0707 & DB telcons re investigations of allegations concerning facilities Allegations not properly investigated & could result in "whitewash", CUMMINOS, J Office of Inspector & Auditor 82/07/15 DIRCKS, W Office of the Executive Director for Operations 2pp 16993 093 24% Fichs 50-373.83/03/25.8306230005
- --8306230051 Discusses changes in Section X of util rept resulting from consultant concerns re bolting issue Rept revised to reflect verification of procedures & data NORELIUS, C E Division of Engineering 82/07/19 JOBLONSKI, F. KNICELEY, J., REIMANN, F. Region 3, Office of Director 3pp 1893 085 24X Fiche 50-373,83/03/25,8306230005
- --8306230056 Discusses results of insp of allegations considered to have potential effect on facility operation No reason evident to limit power operation at facility KEPPLER, J. © Region 3. Office of Director 82/07/19 DENTON, H R Office of Nuclear Reactor Regulation, Director 1p 18753 088 24% Fiche 50-373,83/03/25,8306230005
- --8306230061 Discusses concurrence w/Section X of IE Inap Repts 50-373/82-35 & 50-374/82-06 re allegation that Morrison Co torque wrench calibr records falsified Audit not sufficiently comprehensive to draw meaningful conclusions REIMANN.F H Region 3. Office of Director 82/07/21. Region 3 Office of Director 1p 18753 087 24X Fiche 50-373,83/03/25,836230005.
- --8306230045 Summerizes B20B11 meeting w/N Jackiw.R Lipinski & representatives of public interest groups ne affidavits submitted by bricklayers subsequent to completion of initial special insp of facility insp evaluation repts ent NORELIUS.C E. Region 3. Office of Director 82/08/18 Region 3. Office of Director 82/08/18 Region 5.0 Office of Director 82/08/18 Region 5.0 Office 90 Oracle 92/08/18 Region 5.0 Office 90 Oracle 92/08/18 Region 5.0 Office 90 Oracle 92/08/18 Region 6.0 Oracle 92/08/18 Region 6.
- 8306230006 FOIA request for 28 administration tort claims for damage filed w/NRC by residents of Canonsburg.PA area MONTANGER.C.H. Covington & Burling 83/04/29 FELTON.U. Division of Rules and Records. 2pp 18982:279
- 8306230009 Responds to FOIA request for 28 administrative tort claims for damage filed w/NRC by residents of Canonsburg.PA area Forwards requested claims & physician affidavit Documents also evaluable in PDR FELTON.J M Division of Rules and Records 83/05/06 MONTANGE, C M Covington & Burling 19. 18782 281

- --8306230016 Claim for damage injury or death as result of radiation emanating from Canonsburg Industrial Park site causing loss of real property w/improvements JW Gofman affidavit encl AMORDSE.M L Affiliation Unknown 83/02/20 3pp 18982 282
- --8306230018 Claim for damage, injury or death as result of radiation emanating from Canonsburg Industrial Park site causing loss of real property w/improvements JW Gofman affidavit encl AMOROSE, A Affiliation Unknown 83/02/20 3pp 18982 284
- --8306230020 Claim for damage.injury or death as result of radiation emanating from Canonsburg Industrial Park site causing loss of real property w/improvements JW Gofman affidavit encl BADIA.A Affiliation Unknown 83/03/14 3pp 18982 287
- --8306230025 Claim for damage injury or death as result of radiation emanating from Canonsburg Industrial Park site causing loss of real property w/improvements JW Gefman affidavit encl.

 2ADIA:A Affiliation Unknown 83/03/14 3pp 18982 289
- ---8306230035 Claim for damage, injury or death as result of radiation emanating from Canonsburg Industrial Park site causing loss of real property w/improvements JH Gofman affidavit enc! BROWN. E Affiliation Unknown 83/02/21 3pp 18982 291
- --8306230038 Claim for damage, injury or death as result of radiation gmanating from Canonsburg Industrial Park site causing loss of real property w/improvements JW Ogman affidavit encl BROWN, S W Affiliation Unknown 83/02/21 3pp 1892 294
- --8306230042 Claim for damage, injury or death as result of radiation emanating from Canonsburg Industrial Park site causing loss of real property w/improvements JW Gofman affidavit encl DAVIS, H H Affiliation Unknown 83/02/22 3pp 18982 297
- ~-8306230053 Claim for damage, injury or death as result of radiation emanating from Canonsburg Industrial Park site causing loss of real property w/improvements JW Gofman affidavít ent DAVIS,L K Affiziation Unknown 83/02/22 3pp 18982 300
- --8306230058 Claim for damage, injury or death as result of radiation emanating from Canonsburg Industrial Park site causing loss of real property w/improvements JW Gofman affidavit end DELOST, J Affiliation Unknown 83/02/21 3pp 18982 303
- --8304230060 Claim for damage injury or death as result of radiation emanating from Canonsburg Industrial Park site causing loss of real property w/improvements JW Gafman affidavit end DCLOST.T Affiliation Unknown 83/02/21 3pp 18982 306
- ---8306230063 Claim for damage injury or death as result of radiation emanating from Canonsburg Industrial Park site causing loss of real property w/improvements JW Gofman affidavit encl
 DUNN.D C Affiliation Unknown 83/02/21 3pp 18982 309
- --B306230064 Claim for damage injury or death as result of radiation emanating from Canonsburg Industrial Park site causing loss of real property w/improvements JW Gofman affidavit end.
 DUNN.D C Affiliation Unknown 83/02/23 3pp 18982 312
- --8306230066 Claim for damage injury or death as result of radiation emanating from Camonsburg Industrial Park site causing loss of real property w/improvements JW Gofman affidavit and DUNN.K Affiliation Unknown 83/02/20 3pp 18982 315
- ---8306230067 Claim for damage, injury or death as result of radiation emanating from Canonsburg Industrial Park site causing loss of real property w/improvements JW Ogfman affidavit end DUNN.R E Affiliation Unknown 83/02/21 Jpp 18982 318
- --8304230069 Claim for damage injury or death as result of radiation emanating from Canonsburg Industrial Park site cousing lost of real property w/improvements JW Gofman affidavit end DUNN.R W Affiliation Unknown 83/02/20 3pp 18982 321
- --8306230071 Claim for damage injury or death as result of radiation emanating from Canonsburg Industrial Park site causing loss of real property w/improvements JW Oofman affidavit encl DUNN.W J Affiliation Unknown 83/02/23 3pp 18982:324
- --8306230072 Claim for damage injury or death as result of radiation emanating from Camponaburg Industrial Park site causing loss of real property w/improvements JW Gofman affidavit ent. HERRON.M M Affiliation Unknown 83/02/22 3pp 18982 327
- --B306230076 Claim for damage injury or death as result of radiation emanating from Canonsburg Industrial Park site causing loss of real property w/improvements JW Gofman affidavit enci MALARDIE,P J Affiliation Unknown 83/02/21 3pp 18982 330

- ---B3062300/7 Claim for damage, injury or death as result of radiation emanating from Canonsburg Industrial Park site causing loss of real property w/improvements JW Offman affidavit encl MARTON.E J Affiliation Unknown 83/02/26 3pp 1898 333
- --8306230078 Claim for damage, injury or death as result of radiation amanating from Canonsburg Industrial Park site causing loss of real property w/improvements JW Offman affidavit encl MARTON, J Affiliation Unknown 83/02/16 3pp 18982 336
- --8306230080 Claim for damage, injury or death as result of radiation emanating from Canonsburg Industrial Park site causing loss of real property w/improvements JW Gofman affidavit encl PROMITTION Affiliation Unknown 83/02/22 3pp 18782 337
- --8306230084 Claim for damage injury or death as result of radiation emanating from Canonsburg Industrial Park site causing loss of real property w/mprovements JW Odman affidavit encl SPIMOSA E Affiliation Unknown 83/02/28 3pp 18982 342
- --8306230085 Claim for damage injury or death as result of radiation emanating from Canonsburg Industrial Park site causing loss of real property w/improvements JW Ochman affidavit encl pp[NOSA:1 Affiliation Unknown 83/02/28 3pp 18982 345
- --8306230091 Claim for damage injury or death as result of radiation enamating from Canonsburg Industrial Park site causing loss of real property w/improvements JW Cofman affidavit encl
 TOMECSKO.M Affiliation Unknown 83/02/23 3pp 18982 348
- --8304230074 Claim for damage injury or death as result of radiation manating from Canonsburg Industrial Park site causing loss of real property w/improvements JW Offman affidavit encl
 TOMECONO.P Affiliation Unknown 83/02/23 3pp 1892-351
- --8306230098 Claim for damage, injury or death as result of radiation emanating from Canonsburg Industrial Park site causing loss of real property Wimprovements JW Gofman affidavit encl WAGNER, G H Affillation Unknown 83/02/21 3pp 1892 354
- --8306230105 Claim for damage, injury or death as result of radiation emanating from Canonsburg Industrial Park site causing loss of real property w/improvements JN Cofman affidavit encl MACNER, R M Affiliation Unknown 83/02/21 3pp 18982 357
- --8306230109 Claim for damage, injury or death as result of radiation emanating from Canonsburg Industrial Park site causing loss of real property w/mprovements JW Oofman affidavit encl WINSECK, S Affiliation Unknown 83/07/22 3pp 18982 360
- O305230123 FOIA request for five categories of documents re spent fuel at facilities
 AUDING Affiliation Unknown 83/03/05 Office of
 Administration 2pp 18982 045 24% Fiche 50-014,83/03/05,
 8308230123
- B305230127 Responds to FOIA request for five categories of documents respont fuel at facilities App A & B documents respond to Items 1:2.4 & 5 Forwards App B Documents 1 & 5-11 No documents located for Item 3 FELTON-J M Division of Rules and Records 83/04/13 AUDIN.L Affiliation Unknown 3pp 18782 047 24X Fiche 50-014.83/04/13, 6304270129
- --8306230137 Part 21 rept re employee receiving dose of 30 710 rems to right hand on 800720 while removing particulate cartridge from water filter subsequent to cask flushing operation TGY.H L Battelle Memorial Institute, Pacific Northwest Laboratory 80708/19 KEPPLER.J G Region 3. Chicago, Office of the Director 4pp. 18782 060
- --8306230139 Forwards data sheet for Part 21 Rept 80-286-000 re defect in spent fuel cask unloading procedures.per TI1105/2(Rev 1) FIGHER.H L. Region 3. Chicago, Office of the Director, 80/10/21 HIGOINBOTHAMPL. Region 3. Chicago, Fuel Facility & Materials Safety Branch ip 18982 066
- --8306230144 Forwards data sheet for Part 21 Rept 80-256-000 re defect in spant fuel unloading procedures Completed data sheet should be returned by 801001 Comments on Part 21 rept encl HI001NB0THAM.L Region 3, Chicago, Fuel Facility & Materials Safaty Branch 80/08/27, DAVIS, A Region 3, Chicago, Fuel Facility & Materials Safaty Branch 90/08/27, Branch 4pp 18982 067
- --B30A230149 Forwards request for add1 info re IE Insp Repts 70-0008/82-02.30-0572B/B0-02 & 50-006/80-01 concerning problems w/NFB-4 (NAC-1E) cask.per B10226 telcon CARLBON.R T Region 1. Philadelphia. Office of the Director B1/02/27 FISCHER.W L. Region 3. Chicago. Office of the Director. 4pp 18982 071 24X Fiche 50-006.83/04/13.8306230129.

- --B306230153 Forwards add1 info re 1E Insp Rept 70-0008/80-02 re overflow through vert tubing smears of floor surfaces & radiation fevels w/portable instrument & removal of fuel assembly FISCHER, W L Technical Inspection Branch 81/03/23 CARLBON, R T Director's Office, Office of Inspection and Enforcement, 5pp 18982 075
- --8306230137 Forwards ANI complaint against BMI.Northeast Utils Svc Co & Connecticut Yankee Atomic Power Co re damage to shipping cask due to contamination during spent fuel shipment GALTZMAN.J Assistant Director for State & Licensee Relations 62/03/04 CUNNINGHAM.O Office of the Executive Legal Director ip 18982 086
- --8306230161 Discusses Nuclear Assurance Corp suit against Connecticut Yankee Atomic Power Co.Northeast Utils Svc Co & BMI redamage to shipping cask due to contamination during spent fuel shipment HARWARD. J E American Nuclear Insurers 82/02/10 SALTZMAN. J Assistant Director for State & Licensee Relations 2pp.
- --8306£30166 Compliant against BMT. Connecticut Yankes Atomic Power Co & Northeast Utils Svc Co re damage to shipping cask due to contamination during spent fuel shipment CROFT.TL. ANDERSON.A S Nuclear Assurance Corp CROFT.TL Affiliation Unknown CS2-53 A S2/01/15 Unknown Affiliation 20pp 18982 089
- 8306240003 FDIA request for all NRC draft & final comments or memoranda re DOE proposed general guidelines for recommendation of sites for nuclear waste repositories (48FR5670) TOUSLEYID R Harmon & Weiss 83/04/05 FELTON.J M Division of Rules and Records ip 18984 050
- 8306240007 Responds to FDIA request for all NRC draft & final comments or memoranda on DDE proposed general guidelines for recommendation of sites for nuclear waste repositories (48FR3670) Forwards documents listed in App A. FELTON.J M Division of Rules and Records 83/04/25 TOUBLEY, P.R. Harmon & Weiss 3pp. 18984-051
- --B306240011 Forwards DDE draft "Nuclear Waste Policy Act of 1982, Proposed General Guidelines for Recommendation of Sites for Nuclear Waste Repositories " Technical review initiated to provide basis for NRC concurrence/nonconcurrence BELL: M J High Level Waste Licensing Management Branch 83/01/27 KERR, G W Office of State Programs: Director. 66pp 18984-054
- ---B306240016 Forwards proposed DDE Regulation 100FR960. "Proposed General Guidelines for Recommendation of Sites for Nuclear Waste Repositories." & briefing package Comments requested by B3022 W/o encis
 BELL,N J High Level Waste Licensing Management Branch B3/02/14 GDMGLAP,A Division of Health, Siting & Waste Management 2pp 18984 120
- ---B306240020 Forwards briefing re proposed DDE Regulation 10CFR960,
 "Proposed General Guidelines for Recommendation of Sites for
 Nuclear Waste Repositories." DDE requests concurrence w/
 guidelines by 830603 Comments required by 830222
 BELL.M.J. High Leval Waste Licensing Management Branch 83/02/14
 BUNTINGJ O Licensing Process & Integration Branch 16pp
 18984 122
- --8306240024 Forwards draft DdE Regulation 10CFR960, "Proposed General Guidelines for Recommendation of Sites for Nuclear Weste Repositories" W/a encl State Working Group on High Level Radwaste High recommendations to DdE encl BELL.M J High Level Waste Licensing Management Branch. 83/02/14 HILLER:H J High Level Waste Technical Development Branch. 10pp 18984 138
- --8306240028 Forwards general comments re proposed DDE Regulation 100FR960, "Proposed General Guidelines for Recommendation of Sites for Nuclear Waste Repositories," per 830214 memo MILLER, H J High Level Waste Technical Development Branch, 83/02/24 BELLM J High Level Waste Licensing Management Branch, 4pp 18984-150
- --B306240036 Bummery of 830209 meeting w/Natl Governors Assoc State
 Working Group Te DQE proposed guidelines for siting of high
 level waste repositories Quidelines technically deficient.
 MACDOWALL, R. D. Licensing Process & Integration Branch. 83/03/02.
 BUNTING, J. O. Licensing Process & Integration Branch. 5pp
 18984.154
- --B306240039 Comments on DDE draft siting guidelines re nomination of sites for site characterization Pending legal determination, guidelines do not Pulfill requirements of Nuclear Waste Policy Act. W/stated encis.
 BUNTING.U O Licensing Process & Integration Branch. B3/03/03
 BELL.M J. High Level Waste Licensing Management Branch. 10pp 18984-159

- --8308240043 Trip rept of 830304 visit to Chicago, IL for DDE public hearing on proposed general guidelines for siting high level waste repository List of speakers & statements of chaleperson & DDE representative encl REHFELDT, W.R. High Level Waste Licensing Management Branch 83/03/II BOYLE, R.R. High Level Haste Licensing Management Branch 15pp 18984 169
- --8306240047 Submits add1 proposed guidelines to be added to DDE draft site selection guidelines w/emphasis on disqualifying factors.per B30309 telcon Backup point paper for discussion encl
 BUNTING.J O Licensing Process & Integration Branch B3/03/15
 BELL.H J High Level Waste Licensing Management Branch 5pp 18784 184
- ---8306240051 Comments on DDE proposed general guidelines for recommendation of sites for nuclear waste repositories, per 830214 memo Guidelines generally acceptable Specific comments encl
 COMELLA,P A Division of Health, Siting & Waste Management 83/03/15 BELL,M J High Level Waste Licensing Management Branch 4pp 18784 187
- ---8306240053 Discusses review of tectonic environ technical guidelines in draft DDE proposed general guidelines for recommendation of sites for nuclear waste repositories Guidelines would be difficult to apply rigorously in licensing action SCHMITT.T J Earth Sciences Branch 83/03/11 COMELLA, P Division of Health, Siting & Waste Management 2pp 18984 193
- --8306240084 Summarizes DDE 830310 public hearing on proposed general guidelines for siting high level waste repository in Mashington DC Draft briefing & prepared statements encl FFLUM.C O. High Level Waste Licensing Management Branch 83703/16 BOYLE.R R. High Level Waste Licensing Management Branch 18pp 18984 195
- --8306240094 Trip rept of 830307 visit to New Orleans,LA for DOE public hearing on proposed general guidelines for siting high level waste repositories Prepared statements ent!
 PFLUM.C Q High Level Waste Licensing Management Branch 83/03/23 80YLE.R R. High Level Waste Licensing Management Branch 13pp 18984 229
- --8306240096 Forwards "Comments on Proposed General Quidelines for Recommendation of Sites for Nuclear Waste Repositories per Nuclear Waste Policy Act of 1982 before DDE," presented on 830321 SAMPSON.M R Yakima Indian Nation 83/03/24 HTLLER.H J High Level Maste Technical Development Branch ip 18984 244
- --8306240101 "Comments on Proposed General Guidelines for Recommendation of Sites for Nuclear Waste Regositories per Nuclear Waste Policy Act of 1982 before OGE "
 SAMPSONM Yakima Indian Nation 83/03/21 lipp 18984 245
- --8306240106 Trip rept of 830321 visit to Seattle, MA for DOE public hearing on proposed general guidelines for siting high level waste repository. List of scheduled speakers encl REMFELDI. H R High Level Waste Licensing Management Branch 83/03/30 BOYLE, R R High Level Waste Licensing Management Branch 8pp 18784-256
- --8306240109 Forwards AGRS Waste Mgt Subcommittee 830318 comments on DDE proposed guidelines for recommendation of sites for nuclear waste repositories (10CFR960) & Philbrick 830316 comments on NRC proposed rule 10CFR60 TANO, R C ACRS Advisory Committee on Reactor Safeguards 83/04/01 BELL, M J High Level Waste Licensing Management Branch Opp 18984 264
- --8306240112 Comments on NRC proposed rule 10CFR60 re high level waste disposal Listed mods should be incorporated PHILBRICK, 8 8 Philbrick, 8 8 83/03/16 MOELLER, D ACR8 Advisory Committee on Reactor Sefeguards 2pp 18984 272
- --B306240il6 Summarires DDE B30314 public hearing on proposed general guidelines for siting high level waste repusitory in Salt Lake City. UT. List of panel members, statements of chairperson & DDE representative & list of speakers encl B0YLERR High Level Waste Licensing Management Branch, B3704703 BELL, M J. High Level Waste Licensing Management Branch 18pp 18984,274.
- ---B306240119 Summary of B30220 meeting w/DDE in Germantown, HD re 10CFR760. "Proposed General Guidelines for Recommendation of Bites for Nuclear Waste Repositories." List of attendees encl PFLUM, C 9. High Level Waste Licensing Management Branch. B3/04/05 B0YLE, R High Level Waste Licensing Management Branch 6pp. 18984 292

- --8306240128 Forwards Yakima Indian Nation comments on DDE proposed guidelines for recommendation of sites for repositories & requests Reg Guide 4 17. "Bid Form & Content of Site Characterization for High Level Waste Geologic " HGVIS.J B Hovis. Cockrill, Woaver & Bjur 83/04/06 RRIGHT.R J Basalt Waste Isolation Project 2pp 18784 278
- ---8306240131 "Written Comments on Proposed General Guidelines for Recommendation of Sites for Nuclear Waste Repositories,per Nuclear Waste Policy Act of 192 Before DDE " * Yakima Indian Nation 83/04/07 19pp 18984 300
- ~~8306240151 Summary of 830404 meeting w/DDE in Germantown, MD re staff comments on 10CFR960 concerning DDE proposed guidelines for recommendation of sites for nuclear waste repositories PFLUM, C G High Level Waste Licensing Management Branch 83704706 BOYLE, R R High Level Waste Licensing Management Branch 2pp 18984 319
- ---8306240155 Forwards comments on 10CFR960 re DDE proposed general guidelines for recommendations of sites for nuclear waste repositories, in response to 830207 FR notice BROWNING-R E Division of Waste Management 83/04/07 MORGAN,R L Energy, Dept of 12pp 18984 321
- --8306240159 Forwards comments re transportation aspects of DDE proposed general guidelines for recommendation of sites for nuclear waste repositories
 TROSTEN.L M LeBoouf, Lamb, Lefby & MacRap 83/04/07 DAVIS.J O
 Office of Nuclear Material Safety & Safeguards.Director 12pp
 18984 333
- --8304240160 Summary of 830120 meeting u/OMB & DOE re proposed BOE guidelines for siting repositories required by Nuclear Waste Policy Act of 1782
 BELL.M J High Level Waste Licensing Management Branch 83/04/07
 High Level Waste Licensing Management Branch 2pp 18984 345
- --8305240163 Forwards comments on draft DDE guidelines for recommendation of sites for repositories (10CFR960), in response to Request 2 of 830324 telcon BROWNING, R E Division of Waste Management 83/04/11 KAMMERER: C C Office of Congressional Affairs 1p 18984 347
- --8306240168 Forwards visugraphs used in ACRS presentation on DDE sitirg guidelines & comments sent to DDE, per 830407 request BELLIM J High Level Waste Licensing Management Branch 83/04/11 BUDNITZ,R Affiliation Unknown ip 18784-361
- 8306240349 FOIA request for winning technical proposal under NRC-03-83-107 THURMOND,P NUB Corp SE-3006 83/04/18 CARR.J 0 Office of Administration ip. 18997 180
- 8306240352 Responds to FOIA request for winning technical proposal under NRC-03-83-107 Forwards nonproprietary version of proposal Document also available in FDR FELTON.J M Division of Rules and Records 83/05/06 THURMOND.P NUS Corp ip 18977 181
- --8306240356 "Technical Proposal for Development of Reg Guide & Regulatory Analyses"

 * Analysis & Technology, Inc NRC-03-83-107 RS-NRR-83-107 83/03/07 535p 18777 182
- 8304280182 Partial response to FQIA request for all documents made available per FQIA Request 83-153 re consultations w/EPA concerning development of stds for remedial actions at inactive U processing sites Documents available in PDR FELTON, J M Division of Rules and Records 83/05/11 KAPPEL, B Hamel, Park, McCabe & Saunders Ip 19043 210
- 8306280186 FOIA request for all documents made available per FOIA Request 83-153 re consultations w/EPA concerning development of stds for remedial actions at inactive U processing sites KAPPEL, B. Hamel, Park, McCabe & Saunders 83/04/12 NORNAY.F 8 Office of Administration Ip 19043 211
- 8306280193 FDIA request for DDE/NRC Forms 74; filed since Jan 1982 removement of South African origin matl from DDE U enrichment facilities to any US fuel fabricator KMAPIK, M McGraw-Hill Publications CO 82/12/21 CARR, J Division of Rules and Records in 19043 212
- B304280198 Responds to FOIA request for DOE/NRC Forms 741 filed since Jan 1982 re movement of South African origin matl from DOE U enrichment facilities to any US fuel fabricator Forms withheld (ref FOIA Exemption 4) FELTON, J M Division of Rules and Records B3/05/12 KNAPIK, M McGraw-Hill Fublications Co 1p 19043 R13,

- 8306280202 FOIA request for copies of all permits allowing radioactive matis in sewage or sewage sludge from plants or sanitary landfills since 820101 or any repts from TMI concerning levels of radiation or radionuclide contamination +UNT.B D Three Mile Island Alert 83/04/07 Office of Administration ip 17043 214 24X Fiche 50-320.83/04/07.8306280202
- 8306280206 Partial response to FDIA request for copies of permits allowing radioactive matls in sewage or sewage sludge from TMI plant transported to area sewage treatment plants or landfills Forwards App A documents Search continuing FELTON.J M Division of Rules and Records 83/05/06 HUNT, B D Three Mile Island Alert 2pp 19043 215 24% Fiche 50-320. 83/05/06.8306280206
- --B306280211 Submits evaluation results of contaminated sewage in Gate 7 sewage holding tank Concentrations of radionuclides in sewage in accordance w/10CFR20 303 Cs-137 & tritium concentrations 0.023% mpc & 0.0057% mpc.respectively LAZAREKI.R F Region i. Office of Director 83/01/27 BARRETT.L H TMI Program Office 4pp 19043 261 24% Fiche 50-320.83/05/04.8306280206
- --8306280216 Forwards info re Gate 7 sewage holding tank, located outside west entrance to turbine bldg Info consists of effluent & waste disposal & liquid effluent to summation of all releases

 BYRNE, J J Region 1, Office of Director 4410-83-M-0134

 83/02/04 BARRETT, H TMI Program Office 33pp 19043.265

 24X Fiche 50-320,83/05/06.8306280206
- --8306280220 Forwards GPU 830331 memo & related info re contamination in Gate 7 sewage holding tanks Info results of King NY Times article & Gischel affidavit BARRETT.L H TMI Program Office 83/04/06 WARD.B Region 1. Office of Director 49pp 19043 299 24X Fiche 50-320.83/05/06. 8306280200
- 8306280224 Addl response to FOIA request for insp.surveillance & radiological monitoring repts re Westinghouse Cheswick
 Div from 1963-1970 Addl documents not located
 FELTON.J M Division of Rules and Records 83/06/02 JOHNSON.C
 obsolete code ip 19043 350
- B306280230 F0IA request for insp. surveillance & radiological monitoring repts re Hestinghouse Cheswick Div from 1963-1970 JOHNBON.C Behrand, Aramson & Morraus 83/05/03 ALLAN.J N Region 1. Defice of Director 2pp 19043 331

GEN TEC IS GENERIC TECHNICAL ISSUES

- B305010052 NUREG/CR-3226 BTATION BLACKOUT ACCIDENT ANALYSES (PART OF NRC TASK ACTION PLAN A-44) KOLACZKONSKI.A , PAYNE,A C Sandia Laboratoriss FIN A-1302 BANDH2-2450 B3/05/31 Division of Safety Technology 279pp A-vallable at NRC 48 00 18685 252
- B306010065 Forwards "Control of Heavy Loads (C-10). Kewaunee Nuclear Power Plant," draft technical evaluation rept for review & comment Conference call to discuss rept scheduled for wk of B30610 VARGA.S A Operating Reactors Branch | B3/05/16 GIEGLER.C W Wisconsin Public Service Corp 2pp 18695 332 24X Fichs 50-305.83/05/16.8306010065.
- --8305200714 TER-C5506-363 DRFT
 "Control of Heavy Loads (C-10), Kewaunes Nuclear Power
 Plants," draft technical evaluation rept.
 VD38URY,F W, BUMBERGER, C Franklin Institute/Franklin Research
 Center NRC-03-81-130 TAC 46747 83/04/29 SARGENT,I H NRC Na Detailed Affiliation given 38pp 18696 001 24X
 Fiche 50-305,83/05/16,8306010065
- 8306010164 NUREQ-0869 FC ERR
 USI A-43 RESOLUTION POBITIONS
 SPEIB, T P Division of Safety Technology 83/05/12 5pp
 18686 322.
- 8306060236 Clarifies responses to NUREG-0612, "Control of Heavy Loads"
 Turbine Crane MT-CRA-1 mests guidelines of NUREG
 BDUCHEY: 0 D Washington Public Power Bupply System GD2-83-337,
 B3/04/13 SCHWENCER: A Licensing Branch 2 ip 18673 001 24X
 Fiche 50-397,83/04/13,8306010236

- B306010316 Advises that performance of load test in excess of 100% of max load unnecessary since crane operator training & safety programs ensure safest possible operations, in response to B01222 ltr re control of heavy loads (NUREO-0612) WITHERS.B D Portland General Electric Co B3/05/24 EISENHUY.D & Division of Licensing 3pp 18682 138 24% Fichs 50-344,83/05/24,83/05/0316
- B306020015 Requests performance or documentation of completion of load test of reactor vessel head lifting fixture for control of heavy loads. Phase I within 120 days Quidelines for response 5 complete draft technical evaluation rept encl CLARK.R A Operating Reactors Branch 3 83/05/24. QARRITY.J H Maine Yankee Atomic Power Co 16pp 18701 146 24X Fiche 50-309,83/05/24,8306020015
- --8306020037 TER-C5506-365 BRFT
 "Control of Heavy Loads (C-10), Maine Yankse Atomic Power
 Co, Main Yankse Nuclear Power Station," draft technical
 evaluation rept
 VITO, D J, BOMBERGER, C, BARGENT, I H Franklin Institute/Franklin
 Research Center NRC-03-Bi-130 TAC-08059, 82/12/30,
 CLEMENSON, F NRC No Detailed Affiliation Civen 26pp
 18701 162, 24X Fiche 50-309,83/05/24-8306020015
- 8306020194 NNREO/CR-2837 BO1
 PNL TECHNICAL REVIEW OF PRESBURIZED THERMAL BHOCK ISBUEB.
 Technical Critique Of The NRC Near-Term Screening Criteria.
 PEDERSON.L T . APLEY.H J . BIAN.B H Battelle Mamorial Institute,
 Pacific Northwest Laboratory FIN B-2310 PNL-4327 B3/05/31
 Division of Safety Technology 56pp Available at NRC 44 75
 IBASR LG
- B30602018B Forwards Franklin Research Ctr draft technical evaluation rapt. "Control of Heavy Loads (C-10). Florida Power Co. Crystal River Unit 3 " Guidance document. "Synopsis of Issues Associated w/NURGE-00612." also encl
 9TOLZ.J F Operating Reactors Branch 4 83/05/19. WILGUS. W S Florida Power Corp 2pp. 18701 072 24X Fiche 50-302.83/05/19.
- --8304020196 TER-C5504-347 DRFT
 "Control of Heavy Loads (C-10).Florida Power Co.Crystal
 River Unit 3." draft technical evaluation rept.
 DOMBERGER.C., VOSBURY.F W Franklin Institute/Franklin Research
 Center NRC-03-B1-130 83/01/28 CLCMENSON.F NRC No Details:
 Affiliation Given. 39pp 18701.074 24X Fiche: 50-302.83/05/19.
 8304020188
- 8306020524 Discusses status of 820827 commitment to perform comprehensive stress analyses of reactor vessel closure head & internals lifting rigs to provide scope & schedule of effort Results scheduled for submittal by 830837. GARRITY, J H Maine Yankee Atomic Power Co MN-83-115 83/05/27 CLARK R A Operating Reactors Branch 3. 2pp. 18693 241 24K Fiche. 50-309, 83/05/27, 8306020524
- 8306030020 Forwards "Control of Heavy Loads at Nuclear Power Plants, Hashington Nuclear Project 2 (Phase II - Interim): " technical evaluation rept SCHHENCER:A Licensing Branch 2 83/05/24 FERGUBON, R. L. Hashington Public Power Supply System, 2pp 18733:146 24X Fiche, 50-397, 83/05/24, 8306030020.
- --8306030088 "Control of Heavy Loads at Nuclear Power Plents. Washington Nuclear Project 2 (Phase II Interim), " draft technical evaluation rept.

 DIXON B W , STICKLEY, T. H E0&Q. Inc FIN A-6457 83/05/24 NRC No Detailed Affiliation Given 20pp 18793, 148 24X Fiche-50-397, 83/05/24, 8306030020
- 8306030067 Forwards synopsis of issues to resolve conformance w/NUREQ-0612 re control of heavy loads (Phase I) & draft technical evaluation rept.

 CLARK. A Operating Reactors Branch 3 83/05/17. STEWART: W. L. Virginia Electric & Power Co 13pp. 18733-211 24X

 Fiche 50-338.83/05/17.8306030067
- --B304030070 TER-C5504-372/373 DR
 "Control of Heavy Loads (C-10), Virginia Electric Power Co.
 North Anna Power Station Units 1 & 2," draft technical
 evaluation rept
 B0HBERGER, C. R. Franklin Institute/Franklin Research Canter
 NRC-D3-B1-130 TAC 47112 B3/02/22 NRC No Detailed
 Affiliation Given. 25pp 18703 224. 24X Fiche 50-338,83/05/17,
 83040300467
- B306030290 Forwards add1 guidance on acceptable solutions to open items re control of heavy loads in compliance w/NUREG-0612 & draft "Control of Heavy Loads (C-10). Donald C Cook Nuclear Plant Units 1 & 2." technical evaluation rept. VAROA: 8 A Operating Reactors Branch i 83/05/16 DOLAN, J Indiana & Michigan Electric Co 14pp 18734 086 24X Fiche. 50-315, 83/05/16, 8306030290

- --8306030299 TER-C5806-344/345 DR

 Draft "Control of Heavy Loads (C-10), Donald C Cook Nuclear Power Plant Units 1 & 2," technical evaluation rept VOSBURY: F W Franklin Institute/Franklin Research Center NRC-03-81-130 TAC 07981 83/02/24 CLEMENSON, F NRC No Detailed Affiliation Given 33pp 18734 100 24x Fichs 50-315,83/05/16.8306030290
- 8306030441 Forwards "Control of Heavy Loads (C-10), Surry Power Station Units 1 & 2," draft technical evaluation rept & summary of addl info required to complete review Response requested within 60 days VAROA.8 A Operating Reactors Branch 1 83/05/16 STEWART, W L Virginia Electric & Power Co 2pp 18735 287 24X Fiche 50-280,83/05/16,8306030441
- --8306030446 TER-C5506-395/396 DR
 "Control of Heavy Loads (C-10), Surry Power Station Units 1 & 2:" draft technical evaluation rept VOSBURY: F W. SARCENT, I H. Franklin Institute/Franklin Research Center NRC-03-81-i30. TAC 08084 83/01/14 NRC No Details Affiliation Olyan 40pp 18735, 289 24X Fiche 50-280, 83/05/16, 83/05/0441
- 8304030508 Forwards draft "Centrel of Heavy Loads (C-10), Zion Station Units 1 & 2," per responses to NRC 800731 request for review of provisions for headling & control of heavy loads in conformance w/NURE9-0612 Addi guidance encl.

 VAR9A:S A Derating Reactors Branch 1 83/05/19 FARRAR, D L Commonwealth Edison Co 15pp 18735-006 24X Fiche. 50-275, 83/05/19,8306030508
- --B306030512 TER-C5506-403/404 DR
 Draft "Control of Heavy Loads (C-10), Zion Station Units 1 & 2; * technical evaluation rept
 BARGENT I H Franklin Institute/Franklin Research Center.
 NRC-03-B1-130 TAC 08093 82/11/30 CLEMENSON,F NRC No
 Detailed Affiliation Given 30pp. 18735 021 24X
 Fiche, 50-275, 83/05/19, 8306030508
- 8306060121 Forwards evaluations submitted to NUREG-0612, "Control of Heavy Loads at Nuclear Power Plants " Handling shielded shipping casks over sport fuel pool will be prohibited until measures taken to reduce probability of cask drop SAYNE, J P Power Authority of the State of New York JPN-83-49 83/06/02 VASSALLO, D.B Operating Reactors Branch 2 14pp 18722 275 24X Fichs. 50-333, 83/06/02, 8306060121.
- 8306060413 NUREG-0927 FC
 EVALUATION OF HATER HAMMER EXPERIENCE IN NUCLEAR POWER
 PLANTS Technical Findings Relevant To Unresolved Safety
 Issue A-1
 BERKIZ:A W Division of Bafety Technology B3/05/31 78pp
 18748-076
- 9306060418 NUREG-0993 FC VALUE-IMPACT ANALYSIS FOR USI A-1: "WATER HAMMER" SERVIL:A W. Division of Safety Technology 83/95/31 29pp. 18747.293
- 8304070427 Notification of B30401 meeting w/util/E0kg.DRNL & C-E in Betheada,MD to review control sys on plant design for resolution of Unresolved Safety Issue A-47. "Bafety Isplications of Control Sys."

 82UKIENICZ-A-J Generic Issues Branch B3/05/26, KNIEL,K. Generic Issues Branch B3/05/26, S304070427.
- 8306070449 Summary of 830322 meeting w/util & consultants in Sethesda.

 MD re reactor vessel beltline weld (MF-70) anomaly
 (Unresolved Safety Issus A-1)) Attendance list and
 HERNAN, R. H. Licensing Branch 4, 83/05/25, Licensing Branch 4,
 4pp. 18780.355 24X Fichs 50-329,83/05/25,8306070449
- 8306070460 Requests concurrence w/encl package & comments re resolution of Qeneric Issue B-10. "Behavior of BHR Mark III Containment "
 MOVAN.T. H. Assistant Director for Operating Reactors 83/05/27 EISENHUT.D. G. Division of Licensing. 3pp. 18780 312
- 8306080102 Forwards response to questions asked at mid-ur program review.per 830806 memo.
 REHM.T.A. Diffice of the Executive Director for Operations.
 83/09/31. CHILK.S. J. Office of the Sacretary of the Commission Sac. 18797:331.
- B306080137 Forwards "MH Zimmer Nuclear Power Station.Unit 1. Heavy Loads Rept," in response to supplemental SER (MUREO-0328, Buppl 3) & NUREO-0612 re control of heavy loads, MILLAMS, J. Cincinneti Gas & Electric Co. B3/Q6/O2 DENTON, H Office of Nuclear Reactor Regulation, Director. B7pp 18768; 275, 24X Fiche; 50-358, B3/06/O2, 8306080137.

- --8306080140 "WH Zimmer Nuclear Power Station.Unit 1. Heavy Loads Rept *

 * Cincinnati Gas & Electric Cd 83/06/01 108pp 18768 2/7
 24% Fiche 50-358.83/06/02.8306080137
- B304080143 Forwards proposed findings of fact & conclusions of law on Contention 9a me water hammer CHAVEZ.D Simissippi Alliance for the Environment (SAFE) CHAVEZ.D Dekalb Area Alliance for Responsible Energy (BSUANCES QL B3/05/31 Atomic Safety and Licensing Board Panel to 18772 290 24X Fiche 50-454.83/05/31.8304080143
- ~-830A080145 Proposed findings of fact & conclusions of law on Contention 9s re water hammer * Sinnissippi Alliance for the Environment (SAFE) * DeKalb Area Alliance for Responsible Energy 83/05/31 19pp 18772 291 24x Fiche 50~454,83/05/31,8306080143
- 8306080207 Summary of CROR Maeting 38 on 830518 to presentation of proposed rule on pressurized thermal shock of reactor pressure vessels Committee supports proposed rule STELLO.V Regional Operations & Generic Requirements 83/05/31 DIRCKS.W J Office of the Executive Director for Operations 39 18771 267
- B306080213 Informs that station blackout procedure approved & 4valleble for NRC review.per NUREO-0528.Suppl 3. Subsection 8 1 2 WILLIAMS. J Cincinnati Gas & Electric Co B3/06/01 DENTON.N B Office of Nuclear Reactor Regulation. Director 1p 18771 102 24z Fiche 50-358.83/06/01.8306080213
- 8306080218 Forwards testimony of IE Const Appraisal Team Insp Repts 50-445/83-18 & 50-446/83-12 TREBY.5 A Hearing Branch 1 83/06/06 BLOCH.P B Atomic Gafety and Licensing Board Panel 2pp 18771 004 24X Fiche: 50-445, 83/06/06, 8306080216
- 8306080251 Forwards "Control of Heavy Loads (C-10) St Lucie Unit |,"
 draft technical rept,per util response to Section 2 I of
 801222 generic ltr re NUREO-0612 Completion of review by
 830617 requested
 CLARK.R A Operating Reactors Brack 2 83/05/24 UHRIO,R L
 Florida Power & Light Co 2pp 18787 139 24X
 Fiche 50-335,83/05/24,8306080251
- --B30A0B0252 TER-C550A-374 DRFT

 "Control of Heavy Loads (C-10) St Lucie Unit 1." draft technical evaluation rept SDMBERGER: C., AHMED.N. Franklin Institute/Franklin Research Center NRC-03-B1-130 TAC 080B3 83/04/29 CLEMENBON.F MG No Detailed Affiliation Given 3App 18787 141 24X Fiche 50-335.83/05/24.830A080251
- 8306090386 Forwards request for addl info re response to encl "Control of Heavy Loads at Nuclear Power Plants. Phass I, Nebraska Public Power District. Cooper Nuclear Station " Draft technical evaluation rept encl Info requested in 60 days. VASSALLO, D B Operating Reactors Branch 2 83/05/26 PILANT, J H Nebraska Public Power District 13pp 18914 042 24X Fiche 50-298, 83/05/26, 8306090386
- --8306090388 TER-C5506-346 DRFT
 "Control of Heavy Loads (C-10), Nebreska Public Power
 District. Cooper Nuclear Station," draft technical evaluation
 rept
 VOBBURY, F. VITO, D., SARGENT, I.H. Franklin Institute/Franklin
 Research Center NRC-03-81-130 TAC 07982 82/12/30.
 CLEMENSON, F. NRC No Detailed Affiliation Given 29pp
 18814 033 24X Fiche 50-298,83/05/26,8306090386
- 8306090393 Forwards request for add1 info re three open items concerning controls for handling heavy loads Franklin Research Ctr draft technical evaluation and Response requested within 60 days of receipt of ltr BTOLZ, J. F. Operating Reactors Branch 4 83/05/31 RODRIGUEZ, R. J. Sacramento Municipal Utility District 13pp. 18815 037. 24X Fiche 50-312,83/05/31,8306090393
- --8306090397 TER-C5287-388 DRFT
 "Control of Heavy Loads, Sacramento Municipal Util District,
 Rancho Seco Nuclear Generating Station," draft technical
 avaluation rept
 VOSBURY, F. H., VITO, D. J., SARGENY, I. H. Franklin Institute/Franklin
 Research Center NRC-03-91-130 TAC 08079 83/01/13
 CLEMENBON, F. NRC NO. Detailed Affiliation Qiven 28pp.
 18815 050 24X Ficha 50-312,83/05/31,8306090393
- B306090426 Forwards safety evaluation & technical evaluation rept.
 "Control of Heavy Loads " Guidelines of NUREG-0612
 satisfied
 CLARK,R A Operating Reactors Branch 3 B3/05/27 LUNDVALL,A €
 Baltimore Qas & Electric Co 2pp 18809 107 24x
 Fichs 30-317.83/05/27.8306090426

- --8306090492 Safety evaluation accepting util response to "Control of Hravy Londs Phase I" Item resolved a NRC No Detailed Affiliation Given B3/05/27 2pp 18809 109 24X Fiche 50-317,83/05/27,8306090426
- --830&030310 TER-C5906-342

 "Control of Heavy Loads (C-10) Calvert Cliffs Nuclear Power

 Plants Units 1 & 2." technical evaluation rept

 BDMSERGER.C Franklin Institute/Franklin Research Center

 NRC-03-81-130 TAC 07978 83/05/31 CLEMENSON,F NRC No
 Detailed Affiliation Given 28pp 19809 111 24X

 Fiche 50-317.83/05/27.830&09042&
- 8306130176 Forwards final response to NUREG-0612, "Control of Heavy Loads at Nuclear Power Plants" SCHMIDT-H C Texas Utilities Services, Inc TXX-3659 83/06/08 YDWNDBLOOD, B J Licensing Branch i 153pp 18828 031 24X Fiche 50-445.83/06/08.8306130176
- 8306130356 Forwards safety evaluation supporting util decision not to remote reactor water cleanup sys return line per NUREO-0619 Decision based on value-impact analysis & sleeve leakage measurements

 SHEA.J.J. Operating Reactors Branch 5 L805-83-06-024 83/06/09

 COUNSIL.H O Northeast Nuclear Energy Co (subs of Northeast Utilities) 2pp 18822 153 24% Fiche 50-245.83/06/09.8306130356
- --8306130358 Bafety evaluation supporting util decision not to reroute reactor water cleanup sys return line per NUREQ-0619 Decision based on value-impact analysis & sleeve leakage measurements a Office of Nuclear Reactor Regulation, Director TAC 08412 83/06/09 2pp 18822 155 24X Fiche 50-245,83/06/09,8306130356
- 8306130495 Forwards synopsis of resolutions to open items re control of heavy loads at nuclear power plants, per NUREO-0612 guidelines Draft final technical evaluation rept & request for addi info encl VASSALLO, D B Operating Reactors Branch 2 83/05/26 SINGLAIR, J B Vermont Yankee Nuclear Power Corp 13pp 18830 107 24X Fiche 50-271,83/05/26,8306130495
- B306140198 Notification of B30601-02 meetings w/Bandia.Aldem Research Labt. Burns & Roe. Creare.Alf. S&M. Duens Corning & EPRI in Bethesda.MD to discuss proposed resolution of Unresolved Bafety Issue A-45, "Containment Emergency Sump Performance" BERKIZ.A W Generic Issues Branch B3/05/31 KNIEL.K Generic Issues Branch 3pp 18844 209
- 8306140305 Forwards draft task action plan.Rev 2 under Task A-45 re shutdown DHR requirements & A Marchese paper, presented before Swiss Federal Inst for Reactor Research in Switterland in late Apr 1983 W/o encis MGRAN.D H Standardization & Special Projects Branch 83/05/25 NELLS 0 H Public Service Electric & Oas Co of New Jersey ip. 18844 348
- B3G&140500 Forwards responses to 801222 ltr re NUREC-0612, "Control of Meavy Loads at Nuclear Power Plants" Info addresses overhead handling sys for fuel storage pool CRDUSE.R P Toledo Edison Co 952 83/06/10 876LI.J F Operating Reactors Branch 4 142pp 18843 096 24X Fiche 50-346.83/06/10.8306140500
- 8306140715 Response to first set of interrogatories on pressurized thermal shock, Contention I-62 Certificate of Svc encl HODODON.A P Hearing Branch 2 83/06/10 Lewis, M 27pp 18841 276 24X Fiche, 50-352, 83/06/10, 8306140715
- 830-6140792 Forwards draft task action plantRev 2 for Task A-45 re shutdown DHR requirements & A Marchese paper on same subj. presented before Swiss Federal Inst for Reactor Research in late Apr 1983, W/o encls MORAN, D H Standardization & Special Projects Branch 83/05/25, SERGA, J O Electric Power Research Institute ip 18854.078
- 830614077 Forwards draft task action plan.Rev 2 for Yask A-45 resolution DHR requirements & A Marchese paper on same subj. presented before Swiss Federal Inst for Reactor Research in late Apr 1983 W/o entits MORANAD H Standardization & Special Projects Branch 83/05/25 MITTLER Public Service Electric & Gas Co of New Jersey 19. 18845 324
- 8305140814 Forwards draft task action plan.Rev 2 for Task A-45 re shutdown DHR requirements & A Marchese paper on same subj. presented before Swiss Federal Inst for Reactor Research in late Apr 1983 W/o encls. MORAN.D H Standardization & Special Projects Branch 83/05/25 NICKELL.R E. Electric Power Research Institute 1p 18845 323

- B306150019 Forwards draft task action plan.Rev 2 Under Yask A-45 re shutdown DHR requirements & A Marchese paper on same subj. presented before Suiss Federal Inst for Reactor Research in late Apr 1983 M/a encls
 MCRAN.D H Btandardization & Special Projects Branch 83/05/25
 MATTIMOS.J J Sacramento Municipal Ubility District ip.
- 8306150022 Forwards draft task action plan.Rev 2 for Task A-45 ra shutdown DKR requirements & A Marchese paper on same subj. presented before Swiss Federal Inst for Reactor Research in late Apr 1983 W/o encis MORAN, D H Standardization & Special Projects Branch 83/05/25. PATTERSON.D R Tennessee Valley Authority ip 18872 046
- 8306150112 Forwards draft tast action plan. Rev 2 for Task A-45 re shutdown DHR requirements & A Marchese paper on same subj. presented before Swiss Federal Inst for Reactor Research in late Apr 1983 M/o encls. MCRAND H Standardization & Special Projects Branch. 83/05/25 BURSTEIN.S Wisconsin Electric Power Co ip 18872 120
- 8306150260 Forwards "Control of Heavy Loads (C-10). TVA. Browns Ferry Nuclear Power Station. Units 1, 2 & 3, " draft technical evaluation rept Conference call requested within 4 to 5 wks to discuss review results VA88ALLO.D B Decrating Reactors Branch 2 B3/05/26 PARRIS. H O Tennessee Valley Authority 2pp 18869-322 24X Fichs 50-259, 83/05/26, 8306150260
- --B306150266 TER-C5506-G37/338/33
 "Control of Heavy Loads (C-10), TVA, Browns Ferry Nuclear Power Station Units 1,2 & 3," draft technical evaluation rept B0MBERGER, C Franklin Institute/Franklin Research Centar NRC-03-B1-130 TAC 07975, 83/04/05 CLEMENSON, F. NRC No Detailed Affiliation Given 25pp 18869:324 24X Fiche 50-259, 83/03/26, 8306130260.
- --8306150272 "Bynopsis of Issues Associated w/NUREO-0612 "

 * Operating Reactors Branch 2 83/05/26 11pp 18869 349. 24X
 Fiche 50-259,83/05/26,8306150260
- 8306160034 Forwards draft task action plantRev 2 for Task A-45 rs shutdown DHR requirements & A Marchese paper same subj. presented before Swiss Federal Inst for Reactor Research in late Apr 1983, M/o encis.

 MORAN, D.H. Standardisation & Special Projects Branch. 83/05/23 TAYLOR.J.J. Electric Power Research Institute ip 18892-335.
- 8306160277 Forwards synopsis of issues & Franklin Research Ctr draft technical evaluation rept re NUREO-0612, "Control of Heavy Loads: Phase I," W/o encis ADENSAME G. Licensing Branch 4. 83/06/10 TUCKER, H.B. Duke Power Go 2pp 18872 170 24% Fiche: 56-369, 83/06/10, 8306160277.
- 83Q6160310 Forwards final response to NUREQ-0612. "Control of Heavy Loads at Nuclear Power Plants-Resolution of TAP A-36" Response includes analyses for loads handled over reactor vessel KEMPER.J B Philadelphia Electric Co 83/06/13. EISENHUT.D O Division of Licensing. 126pp 18860,243 24X Fiche-30-352, 83/06/13.8306160310
- B306160603 Forwards util enswer to MI Lewis first set of interrogatories on pressurfied thermal shock contention.
 WETTERHANN, M J. Conner & Wetterhahn WETTERHANN, M J. Philadelphia Electric Co. 83/06/13 LENIS, M I. Lewis, M, ip. 18866;144. 24X Fiche 50-352,83/06/13,8306180603
- --8306160609 Answers to first set of interrogatories on pressurized thermal shock contention Certificate of Bvc encl.

 80YER, V B Philadelphia Electric Co. B3/06/09. LEWIS, M I
 Lewis, M. 16pp 18866 145 24X Fichs 30-352,83/06/13,8306160603.
- 8306160630 Forwards draft "Control of Heavy Loads at Nuclear Fower Plants St Lucie Plant, Unit 2 (Phase I)" & synopsis of NRC interpretation of guidelines of NUREO-0612 for use in resolving open items.

 KNIGHTON, 6 W. Licensing Branch 3 TAC 47015. 83/05/31. UHRIO, R.E. Florida Power & Light Co. 14pp. 18884 283 24X

 Fichs 30-387, 83/05/31, 8306160630
- --B306i60441 E00-H8-6263 DRFT
 Draft "Control of Heavy Loads at Nuclear Power Plents: 8t
 Lucie Plant; Unit 2 (Phase I); " technical evaluation rept.
 SHABER: C. R. E0&9, Inc. FIN A-6457 TAC 47015. 83/04/30. NRC
 No Detailed Affiliation Given. 16pp. 18884: 297 24X
 Fiche 50-389, 83/05/31: 8306160430

- 8306170053 Concurs w/findings contained in technical evaluation rept.
 "Control of Heavy Loads" Guidelines in NUREG-0612. Section
 5 I 1 satisfied, per util 810402. 0715. 0831 & 1209.820203 &
 1108 & 830408 submittals.
 CLARK.R A Operating Reactors Branch 3 83/06/06 MUSQLF.D M
 Northern States Power Co 2pp 18906 314 24X
 Fichs 50-282.83/06/06.8306170053
- --830617005B Safety evaluation supporting util Phase 1 actions re control of heavy loads NUREG-0612. Section 5.1 1 guidelines attisfied

 * Office of Nuclear Reactor Regulation, Director 18706 316 24% Fiche 50-282. 83/06/06. 8306170053
- --8303230021 TER-C5506-384/385
 "Control of Heavy Loads (C-10), Prairie Island Nuclear
 Generating Plant. Units 1 & 2." technical evaluation rept
 VOSBURY, F W. Franklin Institute/Franklin Research Center
 NRC-03-81-130 TAC 08075 83/05/17 NRC No Detailed
 Affiliation Given Sipp 66794 188 24X Fiche 50-282,83/06/06,8306/70053
- 8306170302 Forwards App J to, "Evaluation of Pressurized Thermal Shock Effects Due to Small Broak LOCAs W/Loss of Feedwater for Palo Verde i & 2,2 & 3 Reactor Vessels "Rept applies to only Unit 1 VAN BRUNT, E E Arizona Public Service Co ANPP-24608-WFG/83/06/14 KNICHTON, C. Licensing Branch 3, 3pp 18878-197 24X Fiche 50-528,83/06/14,8306170302
- 8306170453 Forwards draft task action plan. Rev 2. for Task A-45.
 "Shutdown DHR Requirements" & A Marchese paper presented before Swiss Federal Inst for Reactor Research, during Apr 1983. W/o encis MCRAN, D H Standardization & Special Projects Branch 83/05/31 BTAHLKOPF, K Electric Power Research Institute 1p 18906-360
- B306200119 Minutes of ACRS ECCS Subcommittee B30512 meeting in Washington, DC re-proposed GE BAFER/GESTR ECCS licensing codes & status of other NRR licensing actions Schedules for completing Unresolved Bafety Issues A-43 & A-1 encl # ACRS Advisory Committee on Reactor Bafeguards 83/05/12 ACRS Advisory Committee on Reactor Bafeguards 27pp 18908 239
- 8306210007 Transcript of ACRS Metal Components Subcommittee on Pressurized Thermal Shock Research Program 830615 meeting in Oak Ridge: TN. Pp. 1-197 Supporting documentation encl a ACRS Advisory Committee on Reactor Safeguards 83/06/15 300pp 18910 OQ1
- 8306220043 Answer to first set of interrogatories re-pressurized thermal shock in BRRs LEMIS.M I Lewis. M 83/06/15. Philadelphia Electric Co 2pp 18926-255 24X Fichs 50-352.83/06/15.8306220043
- B306220074 Forwards safety evaluation & technical evaluation rept re util response to B01222 generic ltr. "Control of Meavy Loads" Quidelines in NUREQ-0612 satisfied & Phase acceptable CRUTCHFIELD, D. Operating Reactors Branch 5 LSOS-83-06-045 83/06/21 FIEDLER, P. B. General Public Utilities GPU Service Corp 2pp 18926 060. 24X Fiche 50-219, 83/06/21:8306220074
- --8306220083 Safety evaluation re util response to Ceneric Technical Issue A-36. "Control of Heavy Loads " NUREG-0612 guidelines satisfied. Phase 1 acceptable # Office of Nuclear Reactor Regulation. Birector 83/06/21. 2pp
- --8306140424 TER-C5506-377
 "Control of Heavy Loads (C-10), JCF&L Gyster Creek Nuclear
 Power Plant," technical evaluation rept
 BOMBERGER, C. Franklin Institute/Franklin Research Center
 NRC-03-81-130 TAC 47128 83/06/10 8INOH, A NRC No Detailed
 Affiliation Given. 32pp 18926-064 24X Fiche: 50-219, 83/06/21,
 8306220074
- 8306230348 Forwards response to NRC 830428 request for add1 info re Mark I containment long-term program NUTECH rept "Mark I Containment Ring Girder Modelling & Stress Evaluation Utilizing Eccentric Beams" enct.
 MCGAUGHY, R. W. Towa Electric Light & Power Co NO-83-2093
 83/06/20 DENTON, H Office of Nuclear Reactor Regulation, Director.
 App. 18943 011. 24X Fiche: 50-331, 83/06/20, 8306230348.
- --8306230351 MK1-03-008

 "Mark I Containment Ring Girder Modelling & Stress
 Evaluation Utilizing Eccentric Beams,"
 (CHANG, D.K., STURKEY, J. J., BALLARD, T. A. NUTECH Engineers, Inc. NO-83-2093, 80/04/30 41pp. 18943 017. 24X
 Fiche: 50-331,83/04/20,8306230348.

- 8306230432 Forwards revised response to NUREG-0612, "Control of Heavy Loads " Rev Addresses NRC comments contained in draft technical evaluation rept dtd 821123 & supplemented by NRC 821228 ltr DEVINCENTIS, J Yankee Atomic Electric Co SBN-521 83/06/20 KNIGHTON, G W Licensing Branch 3 2pp 18941 001 24X Fiche 50-443.83/06/20.8306230452
- --8306230458 9763 006-8-N-5
 "Response to NRC Generic Request for Addl Info Re
 NUREO-0612.Control of Heavy Loads"

 ** United Engineers & Constructors, Inc. (subs. of Raytheon Co.)
 83/05/31 147pp 18941 004 24X Fiche 30-443,83/06/20,
 8306830452
- B306240270 Response to ASLB consultant P Amico rept re add1 t#stimony on Commission Question 1 No add1 testimony necessary for complete record
 MODRE J. MCGURREN.H J Hearing Branch ! ISSUANCES SP B3/06/20
 15pp 18979 241 24% Fiche 50-247.83/06/20.8306240290
- --B306240305 Affidavit of HW Woods re ASLB consultant PJ Amico B30601 rept Testimony on conditional probability of core melt & release due to pressurized thermal shock event unavailable W/prof qualifications & Certificate of Svc W00DS: HW NRC No Detailed Affiliation Given ISSUANCES SP 83/06/16 7pp 18979 272 24% Fiche 50~247,83/06/20,8306740270
- 8306270016 Reply to Dekalb Area Alliance for Responsible Energy/
 Sinnissippi Alliance for Environ proposed findings of fact & conclusions of law re water hammer Certificate of Svc encl
 GALLO, J. COPELAND, V. O. Commonwealth Edison Co. GALLO, J. Shan,
 Lincoln & Beale ISSUANCES DL. 83/06/21 11pp 19012 246 24X
 Fiche 50-454,83/06/21.8306270016
- --B306270020 Motion for leave to file out-of-time reply to proposed findings of fact & conclusions of law on waterhammer Addl time needed due to demands imposed by preparation of other documents

 COPELAND, V G Commonwealth Edison Co COPELAND, V G Isham, Lincoln & Beale ISSUANCES OL 83/06/21 Atomic Safety and Licensing Board Panel 2pp 19012 257 24X Fiche 30-454, 83/06/21.8305270016
- 8306270225 Forwards results of plant-unique calculations which form bases for mod program in response to Generic Ltr 83-08.

 "Mod of Mark I Containment Vacuum Breakers"

 ZIMMERMAN, S.R. Carolina Power & Light Co. GL-83-08. 83/06/23

 VASSALLO, D.B. Operating Reactors Branch 2. 85pp. 18788-273. 24X

 Fiche 50-324,83/06/23.8306270225
- --8306270230 82-31 R00
 Rev 0 to "Mark I Vacuum Breaker Improved Valve Dynamic Model Model Development & Validation "
 SULLIVAN, J M Continuum Dynamics, Inc. 82/08/31 40pp
 18989 043 24X Fiche 50-324,83/06/23,8306270225
- 8306270322 Provides add1 details re control of heavy loads during const when new fuel assemblies being stored in spent fuel pit Due to failure of reactor coolant pump at Byron 1, fuel handling bldg crane will be installed TRAMM.TR Commonwealth Edison Co 4794N 83/06/17 DENTON.HR Office of Nuclear Reactor Regulation, Director 1p 18994 073 24x Fiche 50-000.83/06/17, 8306270322
- 8306280003 Informs of progress made since 820719 meeting re Unresolved Safety Issue A-47, "Safety Implications of Control Sys "
 Task Action Plan for A-47 completed Sept 1982 & EQ&o
 contracted for plant design review List of info needed encl
 EISENHUT.D 0 Division of Licensing 83706/20 UTLEY.E E
 Carolina Power & Light Co 34pp 19044 043 24X
 Fiche 50-261.83706/20.8306280003
- B306280089 NUREO/CR-2789
 PREBSURE VESSEL THERMAL BHOCK AT U S PRESSURIZED-WATER
 REACTORS EVENTS AND PRECURSORS 1963-1981
 PHUNO, D L Oak Ridge National Laboratory FIN 8-0435
 ORNL/NBIC-210 B3/05/31 Division of Risk Analysis 201pp
- 8306280138 Forwards "Control of Heavy Loads, Philadelphia Electric Co. Peach Bottom Atomic Power Station, Units 2 % 3," draft technical evaluation rept STOLZ, J. F. Operating Reactors Branch 4 83/06/14 BAVER, E 9 Philadelphia Electric Co. 2pp 19043 357 24X Fiche 50-277, 83/06/14, 8306280138
- --8304040329 TER-C5504-379/380

 "Control of Heavy Loads, Peach Bottom Atomic Power Station, Units 2 t 3." draft technical evaluation rept BOMBERGER, C.R. Franklin Institute/Franklin Research Center NRC-03-81-130 TAC 08070 83/05/17 NRC No Detailed Affiliation Given 45pp 19043 361 24X Fiche 50-277,83/06/14,8304280138

- 8306280502 Forwards supplemental response to EG&G,Phase I,Apr 1983 rept re NUREO-0612. "Control of Heavy Loads," reflecting areas of concern addressed during 830614 telcon SWARTZ.E D Commonwealth Edison Co 83/06/22 DENTON,H R Office of Nuclear Reactor Regulation, Director 26pp 19019 236 24X Fiche 50-373,83/06/22,9306280502
- 8306300027 Forwards safety evaluation of util responses to NRC 781129
 lin re Generic Item B-24: "Containment Purging/Venting
 During Normal Operations" Radiological consequences of
 LOCA during purging acceptable Item closed
 CRUTCHFIELD.0 Operating Reactors Branch 5 83/06/28
 VANDEHALLE.D J Consumers Power Co Spp 19120 238 24X
 Fiche 50-155.83/06/28.8304300027
- --8306300034 Safety evaluation of util responses to NRC 781129 ltr re Generic Item B-24. "Containment Purging/Venting During Normal Operations " Issue of purge & vent valve operability resolved except for two open items a Office of Nuclear Reactor Regulation. Director 83/06/28 9pp 19120 243 24X Fiche 50-155.83/06/28.8306300027 83/06/28 900

INSPECTION AND ENFORCEMENT ILE

- 8304110279 PND-I-83-025A on 830404 Region I notified that 330 mCi Xe-133 package reported missing on 830401 % recovered 830402 by Delta Airlines in Miami.FL Package returned to Fort Lauderdale by Contract carrier DENNIB.N., JOYNER.J Region 1. Office of Director 83/04/05
- 8304110289 PNO-1-83-028 on 930327, radioactive shipment of 15 mCi Ti-201 reported lost when shipment did not arrive on direct-Flight to San Juan, PR State of NY & Region II notified DENNIS, N , JOYNER, J Region i, Office of Director 83/04/Q5 ip 17915 114
- 8305i10458 IE Info Notice 83-32, "Ruptured Am-241 Sources Contained in Well Logging Device " 8vc list encl TAYLOR, J M Division of Safeguards > Inspection Programs (Post 830103) 83/05/24 Consolidated Edison Co of New York, Inc 125pp 18831 043 24X Fiche 50-000,83/05/26,8305110458
- 8305(10460 IE Info Notice 83-34, "Event Notification Info Worksheet" Svc list encl JORDAN, E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/26 Consolidated Edison Co. of New York, Inc. 115pp 18732-085 24X Fiche 30-000,83/05/26,8305110460
- 8305110461 IE Info Natice 83-85, "Fuel Movement W/Control Rad Withdrawn at BWRs " Svc]1st encl
 JORDAN, E.L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/05/31 Consolidated Edison Co. of New
 York, Inc 116pp 18732 208 24X Fichs 50-000, 83/05/31,8305110461 116pp
- 8303110464 JE Info Notice 83-36, "Impact of Security Practices on Safe Operations" Byo list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/09 Consolidated Edison Co. of New York, Inc. 119pp 18830 280 24X Fiche 50-000,83/06/09,8305110464 119pp
- 8305110470 IE Info Notice 83-38, "Defective Heat Sink Adhesive & Seismically Induced Chatter in Relays Within Printed Circuit Cards" Svc list encl JORDAN, E. L. Division of Emergency Proparedness & Engineering Response (
- B305110475 JE Info Notice 83-40, "Need to Environmentally Qualify
 Epoxy Grouts & Sealers " Svc list and
 JORDAN, E. L. Division of Emergency Proparedness & Engineering
 Response (Post B30103) B3/06/22 Consolidated Edison Co of New
 York, Inc. 115pp 19021 179 24X Fiche 50-000,83/06/22,8305110475
- 8305110477 IE Info Notice 83-41, "Actuation of Fire Suppression Sys Causing Inoperability of Safety-Related Equipment " Svc list enc1 JOROAN, E.L. Division of Emergency Preparedness & Engineering Response (Post 830103), 83/06/22 Consolidated Edison Co. of New York, Inc. 120pp 18997 007 24X Fiche, 50-000, 83/06/22, 8305110477
- 8305110479 IE Info Notice 83-42, "Reactor Mode Buitch Malfunctions " Byc list encl

 Syc list encl

 SORDAN.E L. Division of Emergency Preparadness & Engineering

 Response (Post 830103) 83/06/23 Consolidated Edison Co of New

 York, Inc 116pp 18976.242 24X Fiche 50-000.83/06/23.8305110479

- 8305110483 IE Info Notice 83-43, "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints " Svc list encl JORDAN.E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/24 Consolidated Edison Co of N 03) 83/06/24 Consolidated Edison Co. of New 19046 297 24x Fiche 50-000,83/06/24,8305110483
- B3D6010066 EN-B3-037 on B3D601, notice of violation & proposed imposition of civil penalty in amount of \$40,000 to be issued Action based on failure to control access into protected area to properly handle intrusion alarms RDSAND.R . AXELRAD. J Director's Office, Office of Inspection and Enforcement B3/05/26 ip 18674 088 24X Fiche 50-219,83/05/26.
- 8306010183 EN-83-036 notice of violation & proposed imposition of civil penalty in amount of \$1,000 to be issued on 830602 for failure to secure licensed math from unauthorized removal during storage in unrestricted area FLACK,E, AKE,RAD,J Director's Office, Office of Inspection and Enforcement. 83/05/26 ip. 18673 002
- 8304010262 PND-IV-83-019A on 830517, licensee committed to perform insp of recirculation sys piping welds including RHR sys inlet & outlet T connections Four welds in need of repair due to intergranular stress corrosion cracking OUBOIS D , MESTEMAN, I.F. Region 4, Office of Director 83/05/27, 19 18672 288 24X Fiche 50-278, 83/05/27, 8304010262
- 8904010310 EN-83-038 notice of violation & proposed imposition of civil auctivistic EM-83-038 notice of violation & proposed imposition of civil penalties in amount of \$180,000 to be issued on \$30002 Action based on three Savarity Level III violations refailure to maintain primary containment integrity BARBER, 0. AKELRAD, J Director's Defice, Office of Inspection and Enforcement. 83/05/27 ip 18672 317 24X Fiche 50-269,83/05/27,8306010310
- 8904020179 EN-83-039 notice of violation & proposed imposition of civil penalty in amount of \$40,000 will be issued in May 1983 Proposed action based on licenses failure to ensure restoration of electrical cable tray sys
 BARBER.O , AXELRAD.J Director's Office Office of Inspection and
 Enforcement 83/05/31 1p 18691 092 24X Fiche: 50-321, 83/03/31,
 8306020179
- 8306070043 PNO-11-83-044: util announced scheduling of enforcement conference w/NRC for 830601 to discuss offloading of 130 fuel bundles into high density fuel rack not varified for boral content BUTCHER, R. C., CANTRELL, F. S., Region 2, Office of Director 83/0 2pp 18739 361 24X Fiche. 50-259, 83/06/02, 8306070043
- 83/04/02
- 8305070100 PND-I-83-053, on 830501 literase reported 225 uCi Ba-133 source lost Thorough search of facility conducted w/negative results Source & storage "Pig" missing since Nov 1982 Bearch afforts continuing.
 FRIEDMAN, L. F., GLENN, J. Region 1, Office of Director. 83/05/02 1p 19739 310
- 8304070191 PNO-II-83-043 on 830402.initial criticality achieved wastual parameters in close greement w/predicted conditions low power testing began immediately & scheduled to be completed within 3 days
 JULIANAC A, DANCE,# C Region 2, Dffice of Director. 83/06/02, 1p 18736 298 24X Fiche 50-389,83/06/02,8306070191
- 8306070254 PNO-V-B3-023 on B30527, executive board of util passed resolution delaying completion of Project 3 for 3 yrs if addl financing not obtained within 30 days Present employment at project is approx 3,000 STERNBERO, D.M., HAIBT, D.P. Region 5, Office of Director, 83/05/27 1p. 18740, 335 24X Fiche 50-508, 83/05/27, 8306070254,
- 8304090010 IE Info Notice 83-37, "Transformer Failure Resulting From Degraded Internal Connection Cables " Svc list encl JORDAN,E. L. Division of Emergency Preparedness & Engineering Response (Post 830103) B3/06/13 Consolidated Edison Co. of New York, Inc. 243pp, 19921.001 24X Fiche 50-000,83/06/13,8306090010.
- B306090174 PNO-V-83-020 on B30504.100 uC1 Cs-137 check source found missing from gas decay tank discharge monitor RE-22.Licensee believes source stalen. On B30413, 9 uC1 Cs-137 source found missing All sources removed from monitors OARCIA.E., WENSLAMSKI.F. Region 5, Office of Director 10CFR 020.4020, B3/05/04 ip. 18792 270 24% Fiche.50-275,83/05/04,B306090174
- 8304100176 PNO-11-83-045 on 830608 Cardox carbon dioxide fire protection sys in dissel room inadvertently activated Precautionary evacuation conducted. No serious injuries IGNATONIS, A , BROWNLEE, V. Region 2, Office of Director 2pp. 18805 262 24% Fichs. 50-413, 83/06/08, 8306100176 83/06/08.

- 8306130265 PNO-III-83-041 on 830608; personnel from NRC Ofc of State Programs informed Region III that well-logger in Council Bluffs, IA possessed 2 250 mCi scaled sources of Am-241/8s w/o license Meeting w/infividual scheduled for 830607 SRENIANSKI, D. MILLER, J. Region 3. Office of Director 83/06/09 ip 18824 190
- 8306130327 PNO-111-83-040. on 830605. licensee noticed increase in chloride concentration in reactor cooling water from leak or leaks in main condenser tubes Condenser tubes repaired or plugged. Chlorine level reduced.

 CLARDY, L. JORDAN, M. . SHAFER, W. Region 3, Office of Director 83/06/07 ip 18822 355 24x Fiche 50-331.83/06/07.8306130327
- 8306140022 PND-I-83-056. on B30606, chloring gas released into atmosphere for approx 15 minutes Caused by leak in 3/4-inch plastic pipe on outlet of chlorination evaporator All fuel removed from vessel & vessel drained COMOILL, CONNER Region 1. Office of Director 83/06/07 ip 18838 234 24% Fiche 50-219,83/06/07,8306140022
- 8306140080 PNO-I-83-057 on B30607, while preparing weld on 3-inch control rod drive (CRD) return header for ultrasonic exam, through wall crack found in weld 4 ft from reactor pressure vassel CRD return noizle. Header cut out KISTER. H. KEIMIO, R. Region i. Office of Director 83/06/08 ip 18838 346 24X Fiche 30-333,83/06/08,8306140080
- 8306140154 PNO-1-83-054 on 830604. ECCS actuation signal caused HPCI & RCIC sys to actuate but sys failed due to lack of steam (reactor temp at 185 F). Open RCIC & HPCI lines created depressurization MOLDEN. GALLO, KEIMIO Region 1. Office of Director 83/06/06 2pp 18839:029. 24X Fiche 50-271. 83/06/06.8306140154
- B306i40269 PND-I-83-055 on B30604, Region I received rept that five children in Philadelphia area had played w/viels labeled radioactive mat! found in vacant lot Assistance requested in determining whether children were contaminated KINNEMAN, J Region I, Office of Director B3/06/06. ip 18822 221
- 8305140415 EN-B3-042 on 830510, order to show cause & order temporarily suspending license issued to American Testing Labs, based on noncompliance w/MRC requirements & willful felse statements re use of licensed matl FLACK-E. AXELRAD, J. Director's Office, Office of Inspection and Enforcement 83/06/10 ip 18838 032
- 8306140476 PNO-I-83-058: on 830608, Yankee Atomic Electric Corpnatified licensee of two support problems w/ECGS suction piping attached to torus & svc water piping for cooling water to uninterruptible power supplies HOLDEN, K/STER Region 1, Office of Director 83/06/07, ip 18834 335. 24% Fiche. 50-271,83/06/07,8306140476
- 8306140690 PNO-I-83-059 on 830608, several trips experienced during startup Caused by feedwater flow inconsistency wisteam generator level demand Secondary boron soak performed. KENNY, T. COLLINS, S. Region 1. Office of Director, 83/06/09 191881:343. 24X Fiche: 30-286,83/06/09.8306140690
- 8306440696 EN-B3-041 on 830643 notice of violation & proposed imposition of civil penalty in amount of \$40,000 will be issued Action based on util failure to control access to vital area Licensee may respond within 30 days.
 RUSANGR AXELRAD. J. Director's Office, Office of Inspection and Enforcement 83/06/08. ip 18841:343 24X Fiche 50-416,83/06/08,8306140696,
- 8306160169 PND-III-83-043. on B30610, while removing filter from reactor water cleanup sample panel radiation protection technician received eye contamination from dry matl adhering to filter Eye flushing reduced contamination to 30,000 dpm. HUETER: I. MillER, J. Region 3, Office of Director. 83/06/10 ip. 18861;272 24X Fiche 50-373,83/06/10.8306160169
- B306160264 PNO-III-83-042: on B30608, unit shut down to investigate source of RCB leakage. Source of leakage determined to be from four steam generator manuays Repairs expected to take 3 to 5 days.

 JACKIW.I., BMAFER.W. Region 3, Office of Director 83/06/10 lp 18861;266 24X Fiche: 50-306, 83/06/10, 8306160264.
- 8306160317 PNO-IV-B3-020A. on 830609, reactor tripped Cause undetermined. Trip breaker AKZA failed to close due to personnel failure to follow precedure. Closing procedure revised & aperations parsonnel trained.

 HARNICUTT, D. H., CALLAN, L. J. Region 4, Office of Director. 83/06/10, 1p. 18866:143, 24% Fiche 50-313, 83/06/10, 8306160317

- 8306160644 PND-IV-83-020 on 830609, unit tripped from 99% power from unknown cause Reactor will remain in cold shutdown until cause determined On 830610, two ac-supplied reactor trip breakers failed to close Cause under investigation HUNNICUTT.D M . CALLAN.L J Region 4. Diffice of Director 83/06/10 ip 18866 100 24% Fiche 50-313.83/06/10.8306160644
- 8306170294 PND-II-83-047 on 830613, standby gas treatment sys train B declared inoperable due to problems w/filter heaters Cause not stated Event involved no equipment damage, no personnel error or injury & no radioactive releases BUTCHER, R C . VERRELLI, D M Region 2, Office of Director 83/06/15 2pp 18879 048 24X Fiche 50-260,83/06/15,8306170294
- 8306170332 PNO-1-83-061 on 830615, while conducting mod to reactor water level sensing lines false low reactor water & low-low reactor water level signals generated initiating ECCS & starting emergency diesel generators

 OALLO, KISTER Region 1, Office of Director 83/06/15 ip 18880 362 24X Fiche 50-271,83/06/15,8306170332
- B306170343 PND-1-83-060 on B30614 reactor tripped from 100% power due to high radiation signal sensed in main steam lines Caused by air pocket in steam lines Safety relief valve cycled & RGIC manually restarted RHDADS.G., GREENMAN.E. Region 1. Office of Director 83/06/14 |p. 18880 083 24% Fiche 50-387.83/06/14,8306170343
- 8306170345 PNO-II-83-046 on B30613, fire identified in high-enriched U incinerator ventilation duct Cause not determined No indications of personnel exposure or contamination noted Downwind radiation monitoring devices being analyzed WRAY, JR , BARR, K Region 2, Office of Director 83/06/14 ip 18880 273
- 8305200147 EN-B3-043 on B30521.notice of violation & proposed imposition of civil penalties in amount of \$150,000 will be issued re Becurity Level III violations concerning shutting down reactor by inserting control rods in reverse order BARBER.G. AXELRAD, J Director's Office. Office of Inspection and Enforcement 83/06/16 (p. 18903-120 24X Fiche 50-254,83/06/16.
- 8306200203 PNO-II-83-048 on 830615, facility automatically shut down due to turbine trip caused by loss of power to electro-hydraulic control sys Facility to be down until 830620 for replacement of safety relief valves RDQGE, J. DANCE, H. C. Region 2, Office of Director 83/06/16 2pp 18703 206 24X Fiche 50-321, 83/06/16, 8306200203
- 83062[0]3] EN-83-0]3A on 8303]8, notice of violation & proposed civil penalty in amount of \$2,000 to be issued to licensee Actions based on violation re unauthorized persons performing maint on hosp teletherapy unit FLACK, E. AXELRAD J. Director's Office, Office of Inspection and Enforcement EA-83-0]3A 83/06/17 ip 18714.204
- 8306210148 PNO-III-83-046 on 830610, contaminated water from Waldon Spring Chemical Plant appeared to be draining into site sawage sys due to dislodged mechanical plug Cause unknown Plug replaced NICHOLBONN N. SCHUMACHER, M. Region 3. Office of Director 83/06/15 2pp 18915 246
- B306210237 PNO-I-83-062 on B30607, extremity TLD ring badge, used by amployee during recovery of 40 Ci Ir-192 source from radiography device, indicated overexposure, Region I will review & evaluate incident on B30620 DAVIS, KINNEMAN, JOYNER Region I. Office of Director B3/06/16 2pp 18916 041.
- 9306210242 PNO-III-93-045 on 930614, bomb threat received from male caller complaining of increased electric rates & state & federal economic policies Sheriff & FBI notified CHRISTOFFER, 0 . CREED, J Region 3. Office of Director 83/06/15 fp. 18916 351 24X Fiche 50-331,83/06/15,8306210242
- 8306210249 PNS-I-89-014 on 830615, control room received low seal flow alarm & lost indication of seal leak-off flow on reactor coolant pump IC Valve CH210 found closed Licensee interviewing personnel working in containment area MCMEDHN.H. GDDY, JOYNER Region I, Defice of Director 83/06/16 2pp 18715 251 24X Fiche 50-334.83/06/06.8306210248
- 8306220060 PNO-III-63-044 on 830614, radiation chamistry lab foreman found shot twice No known connection exists between apparent murder & employment BDYD.D. 9HAFER, M. Region G. Office of Director 83/06/15. 1p 18930 174 24X Fiche: 50-295. 83/06/15, 8306220060

- 830623000! PNB-1-B3-015 on 830616.unannounced narcotics search of site Initiated & one marijuana cigarette found in pocketbook belonging to contract security watchperson Individuals amployment terminated HADDEN.H. GODY.A. JOYNER.J Region 1. Office of Director 83/06/17 1p 18947 077 24X Fiche 50-245.83/06/17.8306230001
- 8305230002 PNO-1-83-054 on 830518, electrical generator/turbine trip caused reactor to trip Investigation revealed fault criginated within main generator End turns on some windings aelited & portions of internals covered w/carbon GREENMAN, E @ Region i, Office of Director 83/05/20 lp (8947 078 24X Fiche 50-286, 83705/20, 8305623002
- 8306230246 PNO-III-83-047 on B30615, two radiography workers received apparent whole body overexposures to radiation Caused by failure of radiographers to adequately secure radiation source in shielded position SHENIANSKI, D., SLAMINSKI, W. Region 3, Office of Director 83/06/17 to 18945-230.
- 8306230248 PNO-II-B3-049 on 830616, licensee shut reactor down in compliance w/plant operating requirements because one of two emergency power fiess! generators was inoperable Caused by cooling water leak into cylinders

 JULIAN.C A , VERRELLI, D M Region 2. Office of Director 83/06/17
 2pp 18945 228 24% Fiche 50-339,83/06/17,8306230248
- 8306230263 PNO-1-83-063 on 830617, licensee reported that during iddination on 830610, approx 1 25 mcl 1-125 released from houd at Yale medical ctr All activities in affected iodination facility suspended No press release planned FREDMAN.L., JOYNER, J. Region 1, Office of Director 83/06/17 to 1894 075
- B306230330 PNO-III-83-050 on 830617. w/circuit breakers for core spray valves closed, core spray valves opened Approx 600 gallons lake water injected into reactor vessel, raising chloride concentration Event not reported within 1 h
 HOLZMER.M , JACKIW, I Region 3. Office of Director 83/06/17 ip 18742 274 24X Fiche 50-155.83/06/17.8306230330
- B305230334 PNO-1-B3-066 on B30520, fire discovered in 480-volt vital switchgear room Bource of fire was phase C of 2B 480 transformer fire extinguished Cause of fire under investigation EWMERER R. COLLINS.5 Region 1. Office of Director 83/06/20 ip 1842 348 248 Fiche 50-311.83/06/20.8305230334
- 8306230347 PNO-I-83-065 on B30617, contract between util & Util Workers of America Local 1-2 expired Union/mpt turnover conducted w/o incident Reverification of sys lineups & insp of equipment completed Media attention evident GREENMAN.E 0 Region 1. Office of Director 83/06/20 ip 16943.280 24X Fiche 50-247,83/06/20,8306230349
- 8306230398 PNO-V-83-024 on 830616, while increasing condenser vacuum to resetting trip setpoint, low vacuum tubine trip occurred followed by reactor trip from 100% power Gaused by low grimary plant pressure ECKMARDT. J H , KIRSCH D F Region 5, Office of Director 83/06/16 p 18943 075 24% Fiche 50-361.83/06/16.8306830398
- 830A230A3B PND-III-83-0AB on 830A15, contractor employee reentered plant unescorted after triggering contamination monitor on eisting plant Employee instructed to proceed to radiation protection pfc located in vital area for decontamination CREED, J. MILLER, J. HIND, J. Region 3, Diffice of Director 83/06/17 bp 18942 078 24X Fiche 50-295,83/06/17,8306230438.
- 8306230462 PNB-1-83-014A updates PNS-I-83-014 re possible equipment tampering on 830615 On 830617.FBI concluded no evidence of deliberate equipment tampering evident Valve probably inadversatently closed 8AILEY Region 1. Office of Director 83/06/20 ip 18941 328. 24% Fiche. 50-334. 83/06/20.8306230462
- B306270181 PNG-III-B3-051, on 830621, util authorized to proceed w/Installation of electrical penetration area temporary support beams & excayation under auxiliary bldg Workers laid off 830617 & 18 recalled LANDBMAN, R. HARRISON, J. Region 3, Office of Director 83/06/21, 1p. 18791 344. 24X Fichs 30-329,83/06/21,8306270181
- 830627024D PNO-II-83-050 on 830620, bimonthly inventory difference resulting from 830420 physical inventory reported inventory difference was accounting gain greater than calculated error limit investigation initiated by licenses MCALPINE, E. J. Region 2, Office of Director 83/06/21 in 18988-269.

- 8306270277 PNO-III-83-052 on 830620, electrical fire occurred in generator exciter, forcing shutdown of unit for 2-3 wks Stoning process caused short in rings/brush manifold assembly Damage extensive TONGUE, T. SHAFER, W. Region 3. Office of Director 83/06/21 ip 18796 172 24X Fiche 30-237.83/06/21.8306270279
- 8306280017 PNO-V-83-022A on 830622, personnel determined that RCS piping in areas of welds other than reported on 830510 may be less than win wall thickness eccurred during original preservice exam KIRSCH.D F Region 5. Office of Director 83/06/23 ip 19001 119 24X Fiche 50-275.83/06/23.8306280017
- 8306280203 PNG-I-83-067 on 830622. Tristate tractor trailer carrying radwaste struck near rear exle by passenger car five passengers in car injured. Truck driver not injured & radioactive mati not damaged Mati transferred to new truck KINNEMAN.J. BRENNEMAN.F. Region 1, Office of Director 83/06/23. ip 19013 073
- 8306280537 PND-I-83-063A on 83062i, licenses rept received that several hoods exhaust through same duct as one through which I-125 released Concentration estimated at 57.8 times may permissible concentration All activities suspended FRIEDMAN,L. JUYNER,J. Region i, Office of Director, 83/06/23 ip 17020 002
- 8306280582 PNS-I-83-016 on 830622, bomb threat by unidentified male caller received at plant site & TV station Reactor & turbine bldgs evacuated & search procedures initiated, per emergency & safeguards contingency plans. Results negative.

 MADDEN, W., QODY, A. Region i, Office of Director 83/06/23, 2pp. 19017-328 24X Ficher 50-387,83/06/23,8306280582
- 8306300026 PND-III-83-053 on 830621, one of two menual isolation valves for vacuum breakers D found closed, rendering vacuum breaker inoperable Cause being reviewed Appropriate enforcement action to be initiated JORGENSEN, BL. SHAFER, W D Region 3, Office of Director 83/06/24 2pp 19120-313 24X Fiche 50-373,83/06/24,8305300026
- 8306300105 EN-83-011A on 830218, notice of violation & proposed imposition of civil penalties will be issued in amount of #600,000 Action based on failure to perform Tech Byec surveillances on safety sys & components.

 BARBER, G., AXELRAD, J. Director's Office, Office of Inspection and Enforcement 83/06/28, ip 19048-216 24X Fiche 50-324,83/06/28, 8304300106
- 8306300115 EN-83-044 on 830701:notice of violation & proposed imposition of civil penalties will be issued based on licensee failure to adequately control access to high radiation area & to unlocked radiography device.

 FLACK, E., AXELRAD, J. Director's Office of Inspection and Enforcement 83/06/28 ip 19121 075

MISC PUBLIC DOCUMENT ROOM MISCELLANEOUS

- 8306030215 Responds to 830506 memo re followup on AEOD recommendations Formal tracking & followup sys acceptable, NRR contact designated as T Ippolito. DENTON, HR Diffice of Nuclear Reactor Regulation, Director, 83/05/24 HELTEMES, C J. Director's Office 1p 18733-345.
- 8306030348 Provides justification for removal of company name from list of companies receiving fraudulent maths from Ray Miller. Inc.
 KEMP.R.D PBI Industries. 83/05/26 JORDAN.E L. Director's Office of Inspection and Enforcement. 2pp. 18704:358.
- 8306070196 Responds to 830518 request for interpretation of 10GFR21 re supplier of commercial-grade product While manufacturer/ supplier not subj to Part 21 regulations manufacturer/ supplier must rept known defects or failures POTAPDVSJU Region 4. Office of Director. 83/06/02 HENGELI.8. Special-T-Metals Co., Inc. 2pp 18736 301
- --8306070187 Requests (OCFR2) interpretation for supplier of commercial-grade product, per 830517 telcon.
 HENGELI,8. Special-T-Metals Co., Inc. 83/05/18. PCTAPDY8,U
 Region 4, Office of Director 1p 18736,303
- 830607031B Forwards RH Brickley survey of GA procedures applied by BNL to computer code activities or NRC-funded programs Beries of natl Lab surveys complete BANGART, R L Division of Vendor & Technical Programs. 83/06/02. MATTSON, R J. Division of Systems Integration (post 811005). 2pp. 18746:057

- 830,6070466 Forwards rept on feasibility of one megawatt TRIGA Reactor at Univ of Colombo & summary of 830425 meeting w/Japanese Ministry of Intl Trade & Industry, Sri Lanka Atonic Energy Authority & utils in Tokyo, Japan TRIGMAB, C O Standardization & Special Projects Brench 83/05/25 DENTON HR , EISENHUT, D 0, MIRAGLIALF J NRC No Detailed Affiliation Given 2pp 18780 335
- ---8306070468 "Rept on Feasibility of One Megawatt TRIGA Reactor at Univ of Colombo Campus " THOMAS, C.D. Standardization & Special Projects Branch 83/05/25 7pp 18780 337
- B306080077 Concurs w/revised surveillance requirements for HEPA filters & charcoal adsorber units in STS on ESF cleanup sys per Generic Ltr 83-13 Use of ANSI/ASME N510 1978 edition questioned Updating ref will eliminate errors

 JACOX, J ff Nuclear Consulting Services, Inc. GL-83-13 63/06/01

 EISENHUT, D 9 Division of Licensing 1p 18773 263
- 8304080087 Approves priority ranking of medium for Omneric Issue 51, "Proposed Requirements for Improving Reliability of Open Cgcle Svc Water Sys " Schadule for completing issue should be consistent w/fYB4-96 NRR budget request DENTUM: HR Office of Nuclear Reactor Regulation, Director 83/06/03 MATESON, By Division of Systems Integration (post 811005) 10pp 18787 345
- 8304090200 Forwards users manual for dual porosity pipe flow code.

 QNET/DVM NRC received mod to GRET/DVM on 830531 from Sandia
 which permits use of dual porosities in first flow leg
 downstream of repository. W/o encl

 BELLM J High Level Waste Licensing Management Branch 83/06/01

 BROWNING, R E Division of Waste Management ip 18809 251
- 8304070323 Comments on proposed Commission paper re severe accident research program, per 830509 request Proposed outline should be modified to recognize early issuance of final severe accident policy statement EISENHUT. D 0 Division of Licensing 83/05/31 SPEIS, T P Division of Safety Technology 2pp 18797 111
- 8306090371 Responds to 830505 request NRR concurs w/proposed Commission paper re immediate notification requirement for operating nuclear power reactors (100FR30 72)
 DENTON.H R Defice of Nuclear Reactor Regulation, Director 83705/31 DEYDUNO,R C. Director's Office, Office of Inspection and Enforcement 1p 18815 138
- 8304090438 Responds to 830505 request to review proposed reportable scope for NPADS Comments on failure rate data submitted DENIGNHR Offsice of Nuclear Reactor Regulation, Director 83/04/03 HELTEMES.C J Director's Office 2pp 18809 138
- B306090474 Ack receipt of B30506 memo itemszing all ungoing studies being performed by AEDD Encl memo distributed throughout NRR to solicit comments W/o encl DENTON.HR Office of Nuclear Reactor Regulation, Director B3/05/31 HELTEMES.C J Director's Office 1p 18915 137
- 8306130353 Forwards fuel cycle & matls LER summary for Mar 1983 BROWN.9 D Region 4. Dffice of Director 83/06/07 DAVIS, J Q Dffice of Nuclear Material Safety & Safeguards, Director MICHELSON.C Director's Dffice 3pp 18822 317
- B306140202 Offers no comments in response to B30518 memo re draft NRC manual chapter on security of shared logic word processing sys

 THOMAS.C O. Standardization & Special Projects Branch 83/06/02
 WILLIAMS.M Division of Licensing ip 18844 212
- 8304140294 Submits followup to 830408 memo requesting review of proposed rules to implement hybrid hearing process required in Section 134 of Nuclear Haste Policy Act of 1982 DENTON-H R Office of Nuclear Reactor Regulation, Director 83/05/25 CUNNINGHAM, G H Office of the Executive Legal Director in 18844 200
- 8306140668 Responds to inquiry re color vision criteria for NRC operator license exams Applicant generally required to pass practical test in nuclear plant control room to determine ability to operate plant safely & competently OIBSONAF Region 2. Office of Director 83/04/08 HOLNES,K R Affiliation Unknown 1p 18841 262
- ---8305140675 Requests interpretation of color blindness requirement for sentor reactor operator license exam HRLHES: K Affiliation Unknown. 83/04/08 Region 2. Office of Director ip 18841-263

- B30A200435 Recommends integrated assessment of all access controls on plant safety for three facilities, to determine scope of potential safety problems he locked doors & barriers Response within 10 days requested EISENHUT, D. O. Division of Licensing B3/05/31 MATTSON, R. J. Division of Systems Integration (post B11005) THOMPSON, H. L. Division of Human Factors Safety VOLLMER, R. H. Division of Engineering 3pp 18920-014
- 8306210239 Comments on Commission B30413 memo denying issuance of proposed rulemaking on third-party accreditation of labs, per 10CFR50 49 (SECY-82-153) Clarification & enforcement of NRC responsibility recommended BANDART.R L. Division of Vendor & Technical Programs 83/06/17 TAYLOR,J M. Division of Safeguards & Inspection Programs (Post 830103) 7pp 18919 012
- 8306210251 Advises that status rept on GA reviews re change to 100FRSO will be issued on or about 15th of each month Summary of activities to date provided All Region IV licensee programs will be submitted by Jul 1783
 HALE, C. J. Division of Vendor & Technical Programs 83/06/17
 COLLINS, J. T. Region 4, Office of Director 2pp 18914 022
- 8306240264 Responds to 830606 request for opinion re criteria for employment as security personnel Past use of marijuana w/o evidence of current usage should not disqualify individual from consideration as security officer
 LIEBERMAN J Regional Operations & Enforcement Division 83/06/14
 PULCINI.R A National Labor Relations Board 2pp 18980 LO8
- 8306280125 Comments on AEOD Apr 1983 rept on failures of Class IE safety-related switchgear circuit breakers to close on demand Periodic testing & rigorous main procedures, instead of design changes recommended DENTON, HR Office of Nuclear Reactor Regulation, Director 83/06/17 HELTEMES, C J Director's Office 3pp 19056 292
- --8210270150 Disagrees w/conclusion in rept on failures of Class IE safety-related suitchgear circuit breakers to close on demand re need to make design changes in Class IE breaker surveillance circuits
 DENTON, HR Office of Nuclear Reactor Regulation, Director 82/09/23 MICHELSON, C Director's Office 3pp 66406 300
- NUREC NUREC REPORTS AND RELATED CORRESPONDENCE
- 8305170121 NUREG/CR-3173
 NEW MADRID BEISMOTECTONIC STUDY Summary Of Activities 19771981
 BUSCHBACH,T C St Louis Univ. St Louis, MO 83/03/31
 Division of Health, Siting & Waste Management 214pp Available at
 NRC \$7 00 18480 209
- 8305240436 Forwards additinfo on implementation of Revito NUREC-03[3, in response to NRC 830408 request W/two oversize drawings Aperture cards are available in PDR HARRINGTON W D Boston Edison Co 83-133 83/05/20 VASSALLQ.D B Operating Reactors Branch 2 Bpp 18573 224 24% Fiche 50-293,83/05/20,8305240436
- --8305240443 Rev 4 to Procedure 22 A 16, "Ultrasonic Exam of Piping Welds " DEEDS.P E Peabody International Corp 80/02/22 24pp 18573 232 24X Fiche 30-293,83/05/20,8305240436
- --8305240448 Rev 53 to Procedure SWRI-NDT-400-3. "Manual Ultrasonic Esas of Pressure Piping Welds " * Southwest Research Institute 79/07/31 41pp 18573 256 24X Fiche 50-293,83/05/20,8305240436
- ---B305240455 Rev 3 to Procedure SWRI-NDT-700-5, "Mechanized Exam of Vessel Components, Vessel Welds & Piping Welds " * Southwest Research Institute 79/09/30 20pp 18573 29/ 24x Fiche 50-293,83/05/20,8305240436
- --8305240461 Rev 6 to Procedure SWRI-NDT-700-5. "Mechanized Ultrasonic Exam of Vessel Components, Vassel Welds & Piping Welds " * Southwest Research Institute 81/02/28 28pp 18573 317 24X Fiche 50-293.83/05/20.8308240436
- B305310226 NUREQ/CR-3085 VOI
 INTERIM RELIABILITY EVALUATION PROGRAM ANALYSIS OF THE
 MILLSTONE POINT UNIT I NUCLEAR POWER PLANT Docket No
 50-245 (Northeast Utilities)
 CURRY, J J , GALLAGHER, D W , MODARRES, M Sandia Laboratories FIN
 A-1241 SAND82-7212 B3/04/30 Division of Risk Analysis
 201pp 18682 277 24X Fiche 50-245,83/04/30,8305310226

TARK

#UNLFACE SANDBU-, A-1060 SANDBU-, A-900 18687 024

FIN 8-0444

```
306010018 NUREG-0999
SEZEMELL B-ANALYSIS OF BRITISH APPLICATION OF US PWR
TECHNOLOGY
EDISON, 6 E Division of Licensing 83/05/31 95pp Available at
NRC $5 50 18684 226
13/14/01/01/19 NUREG-0999
306010039 NUREG/CR-3012 VOI
INTERACTIVE RAPID DOSE ASSESSMENT MODEL (IRDAM) Volume 1
  INTERACTIVE RAPID DUBE ASSESSMENT HUDGE (IRDAIN VOICED IN USER'S QUICE POETON, R H. MOELLER, M P., LAUCHLIN, O.J. Battelle Memorial Institute. Pacific Northwest Laboratory FIN 8-2311 PNL-4510 83/05/31 Division of Emergency Preparedness & Engineering Response (Post 830103) 14pp Available at NRC $3.25 18484 048
30A010041 NUREG/CR-2843 VO2
THERMAL/HYDRAULIC ANALYSIS RESEARCH PROGRAM QUARTERLY
REFORT APRIL - JUNE 1982
THOMPSON, S.L. Sandia Laboratories FIN A-1205 SAND82~1788
83/04/30 Division of Accident Evaluation 68pp 18687 10
30A010043 NUREG-0872 803
SAFETY EVALUATION REPORT RELATED TO THE DPERATION OF WPPSS
NUCLEAR PROJECT ND 2 Docket No 50-397 (Washington Public
Power Supply System)

* Division of Licensing 83/05/31 46pp Available at N
4 75 18684 082 24X Fiche 30-397,83/05/31,8304010043
                                                                                                                                Available at NRC
306010046 HUREG-0936 VO2 NO1
NRC REGULATORY AGENDA Quarterly Report January - February
             Division of Rules and Records 83/04/30 192pp 18685 060
≱Q&010032 NURE0/CR-3226
  STATION BLACKOUT ACCIDENT ANALYSES (PART OF NRC TASK ACTION
 STATION BLACKOOF ACCIDENT ANALYSES (PART OF RICE IASK NOTION
PLAN A-44)
KOLACZKOMSKI, A., PAYNE, A. C. Bandia Laboratoriss FIN A-1302
SAND82-2450 B3/05/31 Division of Bafety Technology 279pp
Available at NRC 48 00 18685 252
106010057 NUREG-0843 502
SAFETY EVALUATION REPORT RELATED TO THE OPERATION OF ST
 SAFETY EVALUATION REPORT RELATED TO THE OFTENTION OF 91
LUCIE PLANT.UNIT NO 2 Docket No 50-389 (Florida Power And
L(ght Company.And Orlando Utilities Commission Of The City
Off Orlando.Florida)

* Office of Nuclear Reactor Regulation, Director 82/09/30 95
Available at NRC $5 50 18684 321 24X Fiche 50-389.82/09/30,
8306010087
Odo10063 Submits clarification to 830425 response to Item 7 of Genetic Ltr 83-02 re NUREO-0737 Tech Specs Failures of valves to close & challenges to valves to be reported per Tech Spec & 9 2 & 6 9 16, respectively HANGAN.C V Niagara Mohauk Power Corp GL-83-02 83/05/26 VASSALLO, D B Operating Reactors Branch 2 1p 18674 087 2 Fichs 30-220, 83/05/26, 8306/010063
 HOBO$0065 Forwards "Control of Heavy Loads (C-10), Kewaunee Nuclear Power Plant," draft technical ovaluation rept for review & comment Conference call to discuss rept scheduled for wk of
 WARGA: S.A. Operating Reactors Branch | 83/05/16 | Wisconsin Public Service Corp 2pp 18695 332 24x Fiche 50-305,83/05/16,8306010065
                                                                                                                                                      GIESLER, C W
```

9305200714 TER-C3506-363 DRFT
"Control of Heavy Loads (C-10).Kewaunee Nuclear Power Flants" draft technical evaluation rept VGSBURY.F W. BOMBERGER, C. Franklin Institute/Franklin Research Center NRC-03-81-130 TAC 46747 83/04/29 SARGENT.I H NR No Detailed Affiliation Given 38pp 18696 001 24X Fiche 30-305,83/05/16,8306010065

Oh010067 NUREO/CR-3012 VO2
INTERACTIVE RAPID DOSE AGGESSMENT MODEL (IRDAM) Volume 2
Accident Assessment Methods
POSTONR W: MOELLER; M P : LAUGHLIN, G J Battelle Memorial
Enstitute, Pacific Northwest Laboratory FIN B-2311 PNL-4510
83/05/3) Division of Emergency Preparedness & Engineering
Response (Post 830103), 88pp Available at NRC 45 50 18684 138

OA010071 NUREO/CR-3012 VO3
INTERACTIVE RAPID DOBE ASSESSMENT MODEL (IRDAM) Volume 3
Scenarios For Comparing Dose Assessment Models
POETON,R.W. MOELLER.M.P., LAUGHLIN,Q.J. Battolle Memorial
Institute. Pacific Northwest Laboratory FIN B-2311 PNL-4510
B3/05/31 Division of Emergency Preparedness & Engineering
Response (Post 830103) 151pp Available at NRC \$6.50,
£8464 171

```
8306010088 NUREC/CR-2785
IRRADIATION OF ZECLITE ION-EXCHANGE MEDIA
SMYLER:K J , BARLETTA:R E Brookhaven National Laboratory FIN
A-3162 BNL-NUREC-51551 83/03/31 Division of Waste Management
68pp Available at NRC 65 00 16684 001
8306010094 NUREG/CR-3207
GEOLOGIC AND HYDROLLOGIC RESEARCH AT THE HESTERN NEW YORK
NUCLEAR SERVICE CENTER, MEST VALLEY, NEW YORK Annual Report
      August 1981 - July 1982
August 1981 - July 1982
ALBANESE, J R, ANDERSON, S L, DUNNE, L A New York, State of FIN
B-6350 B3/03/31 Division of Health, Siting & Waste Management
414pp Available at NRC $8 50 18687 304 24X
        Fiche 50-201, 83/03/31, 8306010094
8306010138 NUREC/BR-0015

DOCUMENT CONTROL SYSTEM NEWBLETTER

* Division of Technical Information & Document Control 83/04/29.

App 18686-332
8304010144 NUREG/CR-2747 ERR
X-RAY HEASUREMENTS OF WATER FOO DENSITY
                 1P.A.L. Sandia Laboratories FIN A-1246 SAND
Office of Nuclear Regulatory Research, Director
                                                                                                                                                            8AND82-1292
                                                                                                                                                                                                             83/09/91
                                                                                                                                                                                     200
830ADIO159 NUREG-0800 RO4 ERR
BTANDARD REVIEW PLAN Proposed Revision 4 To 6 2 2.
Containment Heat Removal Bystems
*** Office of Nuclear Reactor Regulation, Director 89/05/12 2pp
  B306010166 NUREG-0B67 FC ERR
USI A-43 RESOLUTION POSITIONS
BPEIB.T P Division of Safaty Technology, 83/03/12 5pp
1868 322
8304010234 Clarifies responses to NUREG-0612. "Control of Heavy Loads "
Turbine Crane MT-CRA-1 meets guidelines of NUREG
BDUCHEY. © D Washington Public Power Supply System 002-83-337
83/04/13 BCHHENGER. A Licensing Branch 2 ip 18673 001, 24X
Fiche 50-397,83/04/13,8306010236
  B306010266 NUREG/CR-3164
EUBBURFACE MONITORING PROGRAMS AT SITES FOR DISPOSAL OF
LOW-LEVEL RADIOACTIVE WASTE
LITTON, R J, SYROMM, W E, STRONG, A B Army, Dept of, Army Engineer
Materways Experiment Station FIM 8-7324 83/04/30 Division of
Waste Management 100pp Available at NRC $5.30 18695 232
 8304010314 Advisor that performance of load test in excess of 100% of max load unnecessary since crame operator training & safety programs ensure safest possible operations in response to 801222 ltr re control of heavy loads (NUREO-0612) WITHERS, 8 D Portland General Electric Co 83/05/24 EISENHUT, D G. Division of Licensing Spp 18482 139 24% Fiche 50-344, 83/05/24, 830603246
        E30401031A
  8306010331 Submits list of post-trip review procedures to be modified fallowing review of results of NUREO-0977 (Salem event) & discussion w/NRC Mods will be made within 30 days CLAYTON.F L. Alabama Power Co. 83/05/24 VAROA.S A. Office of Nuclear Reactor Regulation. Director ip 18681 278 24% Fiche 30-348.83/05/24.8306010331
 B30A010334 Submits response to Ceneric Ltr 83-02 re implementation of NUREO-0737 items No Tech Spec changes required for Items I A i i 3, I A i 3, II E 4 1, II E 4 2 5, II E 4 2.6, II E 4 2 7, II K, 3, 3, II K 3 12 1 K 3 22 4, II K 3 15 HARRINGTON, W D. Boston Edison Co QL-83-02 B3/05/24 ETSENHUT, D Q. Division of Licansing 2pp 18672 315 24X Fiche, 50-293, 83/05/24, 830A010334
 8306010399 Informs that addl clad swell & rupture model calculations in progress, per NUREO-0630 implementation schedule Final rept will be issued by 830620 RODRIGUEZ, R.J. Sacramento Municipal Utility District RJR 83-434 83/09/23 870LZ, J.F. Operating Reactors Branch 4 ip 18682;240 24X Fiche 50-312,83/05/23,8306010399
```

8304010081 NUREG/CR-3191
YARGET ASSIGNMENTS FOR SECURITY OFFICERS TO K TARGETS

8306010086 NUREC/CR-2839 SURVEY OF ERROR PROPAGATION IN SYSTEMS UPPULURI.V R , KUO.H Gat Ridge National Laboratory F ORN_C48D-TM-19D B3/04/30 Division of Risk Analysis

(185K) ROMLAND, J. R., SHELTON, K. W., STUNKEL, C. B. Dklahoma, Univ. of FIN A-1060 SAND83-7012 83/04/30 Division of Accident Evaluation

8306010400 Forwards proposed schedule re current status of emergency response capability per Region V 830301 meeting (Generic Ltr 82-33 & Sugpl 1 to NUREG-0737)
BBUCHEY.0 D Mashington Public Power Supply System 602-83-346

8306010413 Forwards descriptions of responsibilities of nuclear safety assurance group, in confirmation of 830209 meeting Encl provides revised response to THI Items I B I 2 & I C 5 BRICHER, 0 D Mashington Public Power Supply System GO2-83-345 83/04/15 SCHWENCER, A Licensing Branch 2 App 18674 244 24% Fiche 50-397,83/04/15,8306010413

B306010428 Advises of failure to complete installation & place in operation portions of radioactive monitoring equipment for compliance w/NUREO-0737, Item II F 1.1, "Noble das Monitoring "Completion expected by B30630 FAY.C W Wisconsin Electric Power Co 83/05/25 DENTON.H R Office of Nuclear Reactor Regulation, Director. CLARK.R A Operating Reactors Branch 3 Spp 18679-321 24% Fithe 50-266.83/05/25.8306010428

8305010441 Submits response to 10CFR50 49, "Environ Gualification of Electrical Equipment Important to Safety for Nuclear Power Plants " Master list of safety-related electrical equipment MUSGLF. D M Northern States Power Co IEB-79-018 83/05/19 Office of Nuclear Reactor Regulation, Director 30pp 18674:272 24x Fiche. 50-263,83/05/19,8306010441 MUSOLF, D M

B306010477 Informs that NUREO-0737. Item III A 2.1, "Emergine Preparedness Upgrade Emergency Plans to App R, 10CFR50, completed Item closed. CLARK.R.A Operating Reactors Branch 3 83/05/11 LUNDVALL.A E Baltimore Qas & Electric Co 3pp 18688 359 24X Fiche.50-317.83/05/11:8306010477.

8304020007 NUREO/CR-2841

LIGHT WATER REACTOR SAFETY RESEARCH PROGRAM SEMIANNUAL
REPORT, OCTOBER 1981 - MARCH 1982.
BERMAN, M Sandia Laboratories FIN A-1019 SAND82-1572. 89/05/31
Division of Accident Evaluation. 302pp 18700 014

8306020011 NUREG/CR-3210

JOSEPH TOTAL TOTAL STREET OF THE STREET OF T

8306020015 Requests performance or documentation of completion of load test of reactor vessel head lifting fixture for control of heavy loads, Phase 1 within 120 days Quidelines for response & tomplets draft technical evaluation rept encl.

CLARK, R & Operating Reactors Branch 3 83/05/24 GARRITY, J H Maine Yankee Atomic Power Co 16pp 18701 146 24X

Fichs, 50-309, 83/05/24, 8306020015.

--8306020037 TER-05506-365 DRFT "Control of Heavy Loads (C-10), Maine Yankes Atomic Power Co. Hain Yankes Nuclear Power Station, " fraft technical avaluation rept avaluation repr VITO.D. J. BOMBERGER.C., SARGENT.I H Franklin Institute/Franklin Research Center NRC-03-81-130 TAC-08059. 82/12/30 CLENENGON.F. NRC - No Detailed Affiliation Given 26pp. 18701 162. 24X Fiche 50-309.83/09/24.8306020015.

8306020016 NUREQ/CR-3189 LARGE SCALE EXPLORATORY TESTS OF SODIUM MAGNETITE CONCRETE INTERACTIONS,
RANDICH E ACTON R U Sandia Laboratories
SAND83-0354 B3/05/31. Office of Noclear 1 FIN A-1054 Office of Nuclear Regulatory Research: Director. 72pp. 18702:235.

8306020020 Informs that, based on review of BMR Owners Group 801230 response to NUREG-0737. Item II K 3 45. "Depressurization W/ Other Than Automatic Depressurization Sys." complete. VASSALLO, D. B. Operation Protoctors Branch 2 83705/18 UTLEY, E E 7pp. 18702 336 24%

IR EMERGENCY CONDITIONS AT

OETON, R H Battelle Memorial ratory FIN-84491 PNL-4491 y Preparedness & Engineering Available at NRC. 86 50

8306020056 Responds to 830414 ltr re Generic Ltr 82-33 requirements concerning Suppl I to NUREG-0737 Portion of response addressing detailed control room design review does not provide all info requested Response requested by 830331 KNIGHTON.O W Licensing Branch 3 GL-82-33 E3/05/10 VAN BRUNT.E E Aritons Public Service Co 6pp 18701 349 24% Fiche 50-528-83/05/10,8306020056

B306020066 NUREO/CR-2969
SOLIDIFICATION OF IRRADIATED EPICOR-II WASTE PRODUCTS
BARLETTA, R E , SWYLER, K J , CHAN, S F Brookhaven National
Laboratory FIN A-3162 BNL-NUREO-51590 B3/05/31 Divisional
Waste Management 141pp Available at NRC \$6.50 18699 052 Division of

8306020072 NUREG/CR-2006
MDDELING AND ANALYSIS OF LOW HEAT FLUX NATURAL CONVECTION
SODIUM DOILING IN LWFBRS
KHATIE-RAHDAR, CAZZOLI,E Ø Brookhaven National Laboratory
A-3015 BNL-NUREG-31541 83/05/31 Division of Accident
Evaluation 68pp 18698 105 Division of Accident

B3060200B0 NUREG/CR-3131 V01 CONTAINMENT INTEGRITY PROGRAM FYB2 ANNUAL REPORT BLEJWAS, T.E. , WOODFIN, R.L., DENNIS, A.B. Sandia Laboratories A-1249 SANDB3-0417 B3/05/31 Division of Engineering Technology, 55pp 18701 286

8306020112 NUREG-0987 306020112 NUREO-0987 ENVIRONMENTAL INFACT APPRAISAL FOR RENEMAL OF SPECIAL NUCLEAR MATERIAL LICENSE NO SNM-1168 Docket No 70-1201 (Babcock & Wilcox Company Commercial Nuclear Fuel Plant) * Office of Nuclear Material Safety & Safequards. Directo 83/05/31 141pp Available at NRC \$6 50 18698 271

8304020122 NUREG/CR-3245 METABOLIC DATA AND RETENTION FUNCTIONS FOR THE INTRACELLULAR ALKALI METALS LEGOETTR W Dak Ridge National Laboratory FIN 8-0480-2 GRNL/TM-8630 83/05/31 Division of Facility Operations 18701 188

8306020131 NUREG/CR-2800 801
GUIDELINES FOR NUCLEAR FOHER PLANT SAFETY ISSUE
PRIORITIZATION INFORMATION DEVELOPMENT
ANDREWS H B . GALLUCCI.R H . KONZEK, G J Battelle Memorial
Institute, Pacific Northwest Laboratory FIN B-2507 PNL-4297
83/09/31 Division of Safety Technology 235pp Available at
NRC W7 50. 18697 230

8306020134 NUREG/CR-2837 801 PNL TECHNICAL REVIEW OF PRESSURIZED THERMAL SHOCK ISSUES
Technical Critique Of The NRC Near-Term Screening Criteria
PEDERSON.L T., APLEY, W. J. BIAN, S. H. Battelle Membrial Institute,
Pacific Northwest Laboratory FIN 8-2510 PNL-4327 83/05/31
Division of Safety Technology 56pp Available at NRC 44 75
18678 168

830&020144 NUREG-0485 V05 N04 SYSTEMATIC EVALUATION PROGRAM STATUS SUMMARY REPORT Data As OF April 30,1983 (Buff Book) * Division of Data Automation & Management Information 83/05/31 70pp 18697 128

8305020146 Forwards info supporting post-implementation review of post-accident sampling sys Eleven criteria from NUREO-0737, Etem II B 3 addressed Description of reactor coolant & containment air post-accident sampling sys encl GARRITY. J H Mains Yankee Atomic Power Co MN-83-97 83/05/26 CLARK. R A Operating Reactors Branch 3 28pp 18694 I30 24x Fiche: 50-309, 83/05/26, 8305020146

B306020169 Requests deferral of responses to applicants motion for summary disposition of New England Coalition on Nuclear Pollution Contention I D 2 re reactor trip sys until 20 days after syc of NUREP-1000, Vol 2 PERLISIR & Hearing Branch 3. ISBUANCES OL 83/05/31, HOYT, H LUEBKE, E A , HARBOUR, J. Atomic Bafety and Licensing Board Panel 2pp 18690 361. 24X Fiche 50-443, 83/05/31, 8306020169

8304020188 Forwards Franklin Research Ctr draft technical evaluation rapt, "Control of Neavy Loads (C-10). Florida Power Co. Crystal River Unit 3 " Guidance document. "Synopsis of Issues Associated w/NURGEO-0612," also encl
STOLZ, J F Operating Reactors Branch 4 83/05/19 WILGUS, W B Florida Power Corp. 200 18701.072 24X Fiche 50-302, 83/05/19, 8304020188 6304020188

--B306020196 TER-C3506-347 DRFT
"Gontrol of Heavy Loads (C-iO), Florida Power Co, Crystal
River Unit 3," draft technical evaluation rept
BOMBERGER, C. VOBBURY, F. W. Franklin Institute/Franklin Research
Center NRC-03-B1-130 83/01/28 CLEMENSON, F. NRC - No Detailed
Affiliation Given 39pp 18701 074 24X Fiche 50-302, B3/05/19,
R406020188

- B306020193 NUREO/CR-2814 VO3
 NUCLEAR REACTOR SAFETY July October 1982
 STEVENSON, N.O. Los Alamos Scientific Laboratory FIN A-7420
 LA-9449-PR 83/04/30 Division of Accident Evaluation 31pp
 18697 199
- 8304020232 Forwards Rev O to Salem Generating Station Emergency Operating Procedures Generation Package, per Suppl 1 to NURSC-0737 (Generic Ltr 82-93) LIDEN.E A Public Service Electric & Ges Co of New Jersey GL-82-33 83/05/20 VARGA.S A Operating Reactors Branch 1 ip 18887 001 24% Fiche 50-272.83/05/20 8304020232
- --B306020240 Rev O to "Balem Generating Station Emergency Operating Procedures Generation Package"

 GUELLER.J. FRV.L. BERKLEY.J. Public Service Electric & Gas Co of New Jersey GL-B2-33 B3/04/20 166pp 18689 002 24X Fiche 50-272-83/05/20.8306020232
- 9306020281 Responds to B30510 ltr requesting addl info re status of MUREG-0737, Item II F 1 Installation of Unit 2 high range containment monitor trending & recording function completed Monitor operational HUNTER.R S Indiana & Michigan Electric Co HEP NRC 0678F 83/05/27 DENION, H R Office of Nuclear Reactor Regulation. Director 3pp 18670 315 24% Fiche 50-315,83/05/27,8304020281
- B366020283 Forwards rev to 801219 response to NUREQ-0737, Item I C 6. "Guidance on Procedures for Verifying Correct Performance of Operating Activities," per 821222 Tech Spec chango re shift technical advisor BDRDINE. I C Consumers Fower Co 83/05/25 CRUTCHFIELD.D Operating Reactors Branch 5 2pp 18690 318 24X Fiche 50-155,83/05/25,8306020283
- 8306020524 Discusses status of 920827 commitment to perform comprehensive stress analyses of reactor vessel closure head & internals lifting rigs to provide scope & schedule of effort Results scheduled for submittal by 830831 GARRITY. J H Maine Yankee Atomic Power Co. MN-83-115 83/05/27 CLARK, R A. Operating Reactors Branch 3 2pp 18693-241 24X Fichs 50~307,83/05/27,8306020524
- 8306020570 Comments on NUREO~0737, Item III A 2 1, "Emergency Preparedness, Upgrade Emergency Plans to App E. 10CFR50 " Unsite & offsite emergency preparedness adequate Item clased VAROA, S A Operating Reactors Branch 1 83/05/24 CLAYTON, F L Alabama Power Co 2pp 18715 066 24X Fiche 50~348,83/05/24, 8306070070
- 8306020598 Forwards draft SER.NUREO-0422, Suppl 7 & "Evaluation of AcQuire Units 1 & 2 Undervoltage Trip Attachment Failures," interim technical evaluation tept & draft full power OL amend NOVAK.T M Assistant Director for Licensing 83/05/24 TUCKER.H Duke Power Co 44pp 18718 001 24% Fiche 50-369.83/05/24, 8306020598
- 8306020603 Forwards briefing package for forthcoming Commission meeting to full power operation Package includes briefing slides.88ft Suppl 7. OL issued on 830303 ½ proposed amend DIRCKS,N J Diffice of the Executive Director for Operations 83/05/24 PALLADIND, N . GILINSKY, V . AHFARNE, J Commissioner 147pp 18717 158 24X Fiche 50-370,83/05/24,8306020603
- 9306020606 Confirms NRC caseload forecast panel findings resulting from 830302-04 site visit to assess const completion schedules Itsuance of suppl to SER (NUREO-0847) scheduled for Nov 1983 NOVAK.Th Assistant Director for Licensing 83/05/24 PARRIS.H 0 Tennesse Valley Authority 3pp 18715-050 24X Fiche 30-390.83/05/24.8306020606
- B306020676 Informs that NUREO-0737, Items II F 1 4. "Containment Pressure Monitor." & II F 1 5. "Containment Hydrogen Honstor" completed Items closed VAROA. B A Decreting Reactors Branch 1 B3/05/17 CAREY, J Duquesin Light Co. App 18716 249 24X Fiche 50~334,83/05/17, B306020676
- 8304020494 Bubmits rept re turbine missile issue Rept completes NRR action requested in ACRB 820713 ltr Results documented in Suppl 3 to SER (NUREO-0887) MOVAM.TM Assistant Director for Licensing 83/05/23 RAY.J J ACRS Advisory Committee on Reactor Safeguard 10pp 18/16 237 24X Fiche 50-440,83/05/23,8306020694

- 8304030009 NUREG/CR-3217
 NEAR-TERM IMPROVEMENTS FOR NUCLEAR POWER PLANT CONTROL ROOM
 ANNUNCLIATOR SYSTEMS
 RANKIN,W L . AMES.K R
 Northwest Laboratory
 Centers FIN B-2340
 PNL-4462 83704/30 Division of Muman
 Factors Safety 65pp Available at NRC \$5 00 18733 075
- 8306030020 Forwards "Control of Heavy Loads at Nuclear Power Plants. Washington Nuclear Project 2 (Phase II Interim)." technistal evaluation rept SCHMENCER,A Licensing Branch 2 83/05/24 FEROUSON.R L Washington Public Power Supply System 2pp 18733 146 24X Fishe 50-397.83/05/24.8306030020
- --8306030088 "Control of Heavy Loads at Nuclear Power Plants, Washington Nuclear Project 2 (Phase II - Interim), "draft technical evaluation rept DIXON.8 M . STICKLEY.T H EOMO, Inc FIN A-6457 83/05/24 NRC - No Detailed Affiliation Oiven 20pp 18733'148 24X Fichs 30-397.83/05/24.8306030020
- 8305030067 Forwards synopsis of issues to resolve conformance w/NUREO-0612 re control of heavy loads (Phase I) & draft technical evaluation rept technical evaluation rept CLARK, R A Operating Reactors Branch 3 83/05/17 STEWART, W L Virginia Electric & Power Co 13pp 18733 211 24X Fiche 50-338,83/05/17,8306030067
- --8006030070 TER-C5506-372/373 DR
 "Control of Heavy Loads (C-10), Virginia Electric Power Co,
 North Anna Power Station Units I & 2." draft technical
 systuation rept
 BOMBERGER. CR , VOSBURY, F W , BARDENT, I H Franklin
 Institute/Franklin Research Center NRC-03-B1-130 TAC 47112
 B3/02/22 NRC No Detailed Affiliation Given 25pp
 18733 224 24x Fiche 50-338.83/05/17,8306030067
- 8306030089 Informs that onsite & offsite emergency preparedness adequate & emergency plans upgraded per NUREG-0737. Item III A 2 i tem complete.

 CLARK, R A Operating Reactors Branch 3 83/03/20 GARRITY, J M Mains Yankes Atomic Power Co 3pp 18733 280 24X

 Fichs 50-309.83/03/20.8306030089
- 8305030096 Informs that NUREG-0737. Item III A 2 1, "Emergency Preparedness Upgrade Emergency Plans to App E. 10GFR50: "
 complete Item closed
 STOLZ, J F Uperating Reactors Branch 4 83/05/18 BAUER, E O
 Philadelphia Electric Co 3pp 18733 293 24X
 Fiche 50-277.83/05/18:8306030096
- 8304030110 Forwards safety evaluation re BWR Owners Group 801230 response to NUREO-0737. Item II K 3 45. "Depressurization W/Other Than Automatic Depressurization Sys." No mod to plant design or operation required BTOLZ, J F Operating Reactors Branch 4 93/05/18 BAUER, E G Philadelphia Electric Co 2pp 18733 297 24X Fiche 50-277.83/05/18,8304030110
- 8306030122 Forwards addl info to aid in completion of review re NUREG-0737; Items II F 1 4:II F 1 3 % II F 1 6.per 830110 1tr request % justification concerning Item II F 1 3 Amend to 8300318 confirmatory order requested TUCKER: H B Duke Power Co 83/05/31 DENTON. R Defice of Nuclear Reactor Regulation, Director 13pp 18704 302. 24X Fiche 30-269:83/05/31.8306030122
- 8304030132 Ack receipt of 830325 ltr requesting waiver of 3 month history between submittal of procedures generation package & initiation of training on upgraded emergency procedures Malver granted 87017, J F Degrating Reactors Branch 4 83/05/17 WILQUS, W S Florida Power Corp 2pp. 18733 304 24X Fiche 50-302:83/05/17, 8306030132
- 8306030157 Staff requirements memo informing of Commission 830513 briefing in Mashington, DC on NUREC-1000, "Generic Implications of ATMS Events at Balem Nucleur Power Plant" Operating criteria requested CHILK, S. J. Office of the Secretary of the Commission M830518 83/05/27 DIRCKS, W. J. Office of the Executive Director for Operations 1p 18733 313 24X Fiche, 30-272, 83/05/27, 8306030157
- 8306030253 Informs that NUREO-0737, Item III A 2 1. "Emergency Preparedness, Upgrade Emergency Plans to App E. 10CFR50." completed Item closed 87GL2.J F Operating Reactors Brench 4 83/05/17 WILOUS.W. 8 Florida Power Corp 3pp 18734 067 24X Fiche 50-302.83/05/17.

- B306030270 Forwards add1 guidance on acceptable solutions to open items re-control of heavy loads in compliance w/NUREG-0612 % draft "Control of Heavy Loads (C-10), Donald C Cook Nuclear Plant Units 1 & 2," technical evaluation rept VAROA,8 A Operating Reactors Branch 1 83/09/16 DOLAN, J Indiana & Michigan Electric Co 14pp 18734-086 24X Fiche 50-315,83/05/16,8306030270
- --8306030299 TER-C5506-344/345 DR

 Draft "Control of Heavy Loads (C-10), Donald C Cook Nuclear
 Power Plant Units i & 2," technical evaluation rept

 VOSBURY,F W Franklin institute/Franklin Research Center
 NRC-03-81-130 TAC 07980 83/02/24 CLEMENSON,F NRC No
 Detailed Affiliation Given 33pp 18734 100 24x

 Fiche 50-315,83/05/16,8306030270
- 8306030300 Forwards Vols 1 & 2 to Rev I to "Duke Power Co Response to Suppl 1 to NUREG-0737 for Catawba Nuclear Station " TUCKER,H B Duke Power Co 83/06/01 DENTON,H R Office of Nuclear Reactor Regulation, Director ADENSAME G Licensing Branch 4 215pp 18704 038 24X Fiche 50-413,83/06/01.8306030300
- B306030352 Advises that backup meteorological instrumentation will not be installed at facility, per NUREG-0737. Suppl 1 Software problems w/meteorological dispersion modeling unresolved Interim sys described in B20401 itr utilized LEMPGES.T E Niagara Mohauk Power Corp 83/05/27 VASSALLO.D B Operating Reactors Branch 2 1p 18706 126 24X Fiche 50~220.83/05/27.8306030352
- 8306030379 FOIA request for NUREC-0945. "Final EIS on 100FR61 'Licensing Requirements for Land Disposal of Radwaste'" JOHNSON.B J Minnesota Project B3/03/22 Division of Rules and Records 1p 18734-348
- 8306030382 Responds to FOIA request for NUREG-0945, "Final EIS on 10CFR61 'Licensing Requirements for Land Disposal of Radwaste '" Forwards NUREG-0945, Vols 1-3 W/o encls FELTON.JM Division of Rules and Records 83/04/01 JOHNSON.B J Minnesota Project 1p 18734 349
- 8304030412 Forwards final schedule for satisfying requirements of Generic Ltr 82-33.Buppl 1 to NUREG-0737 "Requirements for Emergency Response Capability " YOUNGELOOD.B.J Licensing Branch 1 GL-82-33 83/05/18 WILLIAMS.J Cincinnati Gas & Electric Co 4pp 18747 141 24X Fiche 30-358.83/05/18.830603012
- 8306030441 Forwards "Control of Heavy Loads (C-10), Surry Power Station Units 1 & 2," draft technical evaluation rept & summary of add1 info required to complete review Response requested within 60 days VAROA: B A Operating Reactors Branch 1 83/05/16 STEWART, I L Virginia Electric & Power Co 2pp 18735 287 24X Fiche 50-280,83/05/16,8306030441
- --8306030446 TER-C5506-395/396 DR
 "Control of Heavy Loads (C-10), Surry Power Station Units 1 & 2," draft technical evaluation rept VOBSURY, F W Franklin Institute/Franklin Research Center NRC-03-81-130 TAC 08085 83/01/14 NRC No Detailed Affiliation Given 40pp 18735 289 24X Fiche 50-280.83/05/16, 830803041
- 8306030485 NUREG/CR-3027 ERR

 OVERLAND EROSion OF URANIUM MILL TAILINGS IMPOUNDMENTS
 PHYSICAL PROCESSES AND COMPUTATIONAL METHODS

 * Battelle Memorial Institute. Pacific Northwest Laboratory *

 Division of Technical Information & Document Contro! PNL-4523
 83/05/04 Division of Health. Siting & Waste Management |p
- 8304030488 NUREQ-0304 VOB NOI REGULATORY AND TECHNICAL REPORTS Compilation For First Guarter 1983 * Division of Technical Information & Document Control 83/05/31 44pp 18735 067
- 8306030503 Forwards safety evaluation supporting response to TMJ Items I A 2 1 4 & 11 B 2 Requirements satisfied DEAOAIID.A Operating Reactors Branch 4 B3/05/13 CROUSE, R P Toledo Edison Co 4pp 18747 167 24X Fiche 50~346, B3/05/13, B306/30503
- --8209030325 SAI-186-029-28

 "Improvements In Training & Requalification Programs As Required By TMI Action Items I A 2 1 & II B 4 for Davis-Besse Nuclear Power Station," technical evaluation rept.

 * Science Applications. Inc. NRC-03-82-096 62/08/31 NRC -- No Datailed Affiliation Given 15pp 18747 172 24X Fiche 50-346,83/05/13,8306030503

- 8304030508 Forwards draft "Control of Heavy loads (** 10). Zion Station Units 1 * 2.1 pdr responses to NRC 800731 request for leview of provisions for handling & control of heavy loads in conformance w/NNCEG-0612 Add | guidance en: 1 VARGALS A Operating Reactors Blanch 1 83/05/19 FARRAR D Commonwealth Edison Co. 15pp. 18735-006 24% Fiche 50-295, 83/05/19. 8306030508
- --8306030512 TER-C5506-403/404 DR
 Draft "Control of Heavy Loads (C-10), Zion Station Units [, 2, " technical evaluation rept
 SARGENT, I H VITO. DJ Franklin Instituto/Franklin Research
 Center NRC-03-81-130 TAC 08092 82,11/30 CLEMENSON,F NRC
 NO Detailed Affiliation Given 30pp 18/35 021 24X
 Fiche 50-295.83/05/19.8306030508
- 8306060036 Specifies provisions incorporated into procedures re NRC positions for SEP Topic III-3 C. "Inservice losp of Water-Control Structures" Topic detailed in final integrated plant SAR, NUREG-OB21 MAIER, J E Rochester Gas & Electric Corp 83/05/26 CRUICHFIELD.D Operating Reactors Branch 5 2pp 18723 298 24X Fiche 50-244,83/05/26,8306060036
- B306060031 Add1 response to FDIA request for three categories of documents re PRA of reactor safety study methodology application program repts \$\tau\$ interior reliability evaluation program repts Forwards App A documents Search continuing FELTON, JM Division of Rules and Records 83/04/07 SHOLL/SC Union of Concerned Scientists 3pp 18/92 001 24% Fiche 50~000,83/04/07,8306060051
- --8109210318 Responds to 810820 memo re transmittal of NUREG/CR-1659, Vol 2.to licenses for comments Util comments on tept already requested BERNERD.R M Division of Risk Analysis 81/08/28 NGVAK,7 M Assistant Director for Operating Reactors 2pp 18752 018 244 Fiche 30-000,83/04/07.8306060051
- --8204120488 Piscusses results of Sandia Natl Labs Study, "Reactor Safei, Study Methodology Application Program Grand Gulf 1 BWR Power Plant (NUREG/CR-1659, Vol 4) "
 ERNST, M L Assistant Director for Technology Review 82/04/06 TEDESCO.R L Assistant Director for Licensing 2pp 18752 067 24X Fiche 50-000, 83/04/07, 8306060051
- --8207280024 Discusses NUREG/CR-2787. "Interim Reliability Evaluation Program Analysis of AR Nuclear One-Unit i Nuclear Power Plant," first final rept on four integrated reliability evaluation program Phase II studies

 BERNERO.R M Division of Risk Analysis 82/06/24 HANAUER.6 H
 Division of Human Factors Safety 5pp 18752 074 24X
 Fiche 50-000,83/04/07.8306060051
- 8304060092 Advises that requirements of NUREG-0737. Item II B 2 re plant shielding for vital areas will be not when mads described in encl safety evaluation implemented Review of corrective actions completed CLARK, R A Operating Reactors Branch 3 83/05/24 COUNSIL, W Q Northeast Nuclear Energy Co (subs of Northeast Vicilities) 5pp 18751 253 24x Fichs 50-236, 83/05/24, 8306060099
- 8306060099 Forwards Rev 4 to "Transport of Toxic Chemicals & Control Room Habitability Study." in response to NRC request & in conjunction w/Suppl 3 to SER HILLIAMS. J Cincinnati Gas & Electric Co 83/06/01 DENTON.H Office of Nuclear Reactor Regulation. Pirector 1p 18731 301 244 Fiche 50-358, 83/06/01 8306060090
- --B30Á0Á0Í01 Rev 4 to "Transport of Taxic Chemicals & Control Room Habitability Study " One oversize graph encl Aperture card is available in PDR BOCEN.P E Cincinnati Gas & Electric Co B3/05/18 liápp 18731 303 24X Fiche 50-358.83/06/01.8306060099
- 8306060121 Forwards evaluations submitted re NUREO-0612, "Control of Heavy Loads at Nuclear Power Flants" Handling shielded shipping casks over spent fuel pool will be prohibited until measures taken to reduce probability of cask drop BAYNE.JP Power Authority or the State of New York JPN-83-49 83/06/02 VASSALLO,D B Operating Reactors Branch 2 14pp 18722 275 24X Fiche 50-333,83/06/02,8306060121
- B306060200 Forwards IE Insp Rept 50-334/83-08 on 830405-0502 & notice of violation STAROBTECKI, R Division of Project & Resident Programs, 83/05/23 CAREY, J J Duquesne Light Co 2pp 18727 256 24X Fiche 50-334,83/05/23,8306060200

- --B304040214 IE Insp Rept 90-334/83-08 on 830405-0502 Noncompliance noted failure to demonstrate ECCS valve operability within specified surveillance interval TROSKOSKI, W.M., TRIPP, L.E. Region 1 Office of Director IEE*87-01 83/05/17 22pp 1872/259 24% Fiche 50-334, 83/05/23, 8304040200
- B30A060207 Notifies that Apr 1983 rept 'Shaking-Table Testing for Seismic Evaluation of Electrical Raceway Sys." applicable to facilities for SEP Topic III-6 re seismic design NUREG-0824 & NUREG-0826 commitments partially satisfied COUNSIL.W G Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL.W G Connecticut Yankee Atomic Power Co COUNSIL.W G Northeast Utilities 810798 83/05/26 CRUTCHFIELD.D Operating Reactors Branch 5 1p 18727 295 243 Fichs 50-000-83/05/26.8306060207
- 830A0&0236 Forwards qualification status & compliance summary on environ qualification of electrical equipment important to safety, per 10CFR50 49 DALE.L.F. Mississippi Power & Light Co. IEB-79 01R 83/05/20 DENION, H.R. Office of Nuclear Reactor Regulation, Director 62p 19728 278 24X Fiche 50-416,83/05/20.0306040236
- 0306080269 Forwards IE Insp Rept 50-322/63-14 on 830407-29 & 0506 No noncompliance noted STARBSTECKI, R Division of Project & Resident Programs 83/05/25 PDLLOCKI S Long Island Lighting Co Ppp 18727 033 24X Fiche 50-322.83/05/25.8306080265
- --B306060268 IE Insp Rept 50-322/83-14 on 830427-29 & 0506 No noncompliance noted Major areas inspected licensed actions taken to comply w/requirements in NUMEC-0737. Item II 8 2, "Design Review of Plant Shielding"

 KELLY.E Region 1, Office of Director GALLO,R M Division Project & Resident Programs 83/05/23 Bpp 18727-035 24* Fiche 50-322,83/05/23,8306060265
- B30A0A0303 Notification of CRGR Meeting 41 on 830A0B to review draft RNREG-OB01. "Evaluation Criteria for Detailed Control Room Dasign Reviews" & draft NUREG-OB35, "Human Factors Review Guidelines for Safety Parameter Display Sys "STELLO.V Regional Operations & Sys "STELLO.V Regional Operations & Grade Reactor Regulation, Director MATTSIN,R J. Diffice of Nuclear Reactor Regulation, Director JORDAN,E L. Director's Office, Office of Inspection and Enforcement CHMINGHAM,R E. Office of Nuclear Material Safety & Safeguards, Director 121pp 18727-202
- 830A0A0366 NUREG/CR-3228 VOI STRUCTURM INTEGRITY OF WATER REACTOR PRESSURE BOUNDARY COMPONENTS Annual Report For 1982 # Haterials Engineering Associates, Inc. # LNSA, Inc. FIN 8-8133 MEA-2012 83/04/30 Division of Engineering Technology 10App A/a(lable at NRC \$5.50 18747 187
- 8306060377 Advises that NUREG-0737. Items II F i 4, "Containment Pressure Monitor, II F i 5, "Containment Mater Leve) Honitor" % II F i 6, "Containment Hydrogen Monitor," resolved.per 821217 submittal Safety evaluation encl CLARK.R A Operating Reactors Branch 3 83/09/24 WITHERS.B D Partland Coneral Electric Co 9pp 18750 338 24X Fiche 50 344.83/05/24.8306060377
- 8306060410 NUREG/CR-3089

 SPECIMEN GEDMETRY AND EXTENDED CRACK GROWTH EFFECTS ON JI-R CURVL CHARACTERISTIGS FOR HY-130 AND ASTM ASSES

 STEELS

 DAVIS,D A, VASSILARDS,M Q, CUDAS,J P David W Taylor Naval Research & Development Center FIN 8-6290 83/03/31 Division of Engineering Technology 85pp Available at NRC \$4.75 18748 021
- 8306060412 NUREG-0853 SO2
 SAFETY LVALUATION REPORT ROLATED TO THE OPERATION OF CLINION POHER STATION UNIT NO 1 Docket No 50-461
 (Illinois Power Company et al)
 8 Division of Licensing 83/05/31 72pp Available at NRC 44 50 18747 321 24X Fiche 30-461,83/09/31.8306060412
- 63040403 NUREO-0727 FC
 EVALUATION OF WATER HAMMER EXPERIENCE IN NUCLEAR POWER
 PLANTS Tochnical Findings Relevant To Unresolved Safety
 Issue A-t
 SERKIZIA W Division of Safety Technology 83/05/31 78pp
 18748 076
- 8306060418 NUREG-0993 FC
 VALUE-IMPACT ANALYSIS FOR USI A-1. "WATER HAMMER "
 SERKILA W Division of Safety Technology 83/05/31 29pp
 18747 293

- 9304060419 NUREG-0540 V05 NO2 TITLE LIST OF DOCUMENTS MADE PUBLICLY AVAILABLE February 1903 * Division of Technical Information & Document Control 83/05/31 975pp 18749 001
- B306070013 Responds to request for environ qualification status of reactor bldg flood level alarms, per BER Den Item 41 reservan discharge vol (NUREG-0803) Testing program completed Documentation available for unsite review in approx 2 wks SHITH. J L Long Island Lighting Co SNRC-900 B3/06/03 DENTON, HR Diffice of Nuclear Reactor Regulation, Director 3pp 18736 359 24X Fiche 50-322, B3/06/03, B306070013
- 8305070015 Forwards IE Insp Rept 50-344/83-11 on 830328-0429 No noncompliance noted STERNBERG.D M Region 5, Office of Director 83/05/23 WITHERS.B D Portland Ceneral Electric Co 2pp 18737 339 24X Fiche 50-344,83/05/23,8306070015
- --83060/0017 IE Insp Rept 50-344/83-11 on 830328-0429 No noncompliance noted Major areas inspected plant operations surveillance testing security, maint refueling & followup on corrective action to NURES-0737 Items MALROS.M H. DODDS.R T. Region 5. Office of Director 83/05/19 6pp 18737 341 24X Fiche 50-344.83/05/23.8306070015
- 8306070016 NUREO-0748 VO3 NO4
 OPERATING REACTORS LICENSING ACTIONS SUMMARY Data As Of
 April 30,1983 (Orange Book)
 # Management Information Branch 83/03/31 319pp 18783 189
- 8306070045 Clarifies misconception in 830513 safety evaluation submitted in response to NUREQ-0737. Item II F 1-3 recontainment high-range radiation monitors High-range drywell radiation monitors & procedures in place when response sent HARRINGTON W D Boston Edison Co 83-141 83/06/01 VASSALLO, D B. Operating Reactors Branch 2 ip 18739 343 24X Fiche 50-293.83/06/01.8306070045
- BJ06070047 Discusses reactor coolant pump seal ability to perform adequately after extended loss of component cooling water, per NUREG-0737, Item II K 3 25 "Effect of Loss of Alternating Current Power on Pump Beals " Item resolution requested. OLSON, R C Baltimore Gas & Electric Co 83/03/25 CLARK, R A Operating Reactors Branch 3 2pp 18740 003 24X Fiche 50-317,83/05/25,8306070047
- B306070062 Forwards safety evaluation of proposed resolution of integrated plant BAR Section 4 27 re svc & cooling water sys Mods acceptable MAMBACH.TV Operating Reactors Branch 5 L905-93-05-070. B3/05/31 VANDEWALLE.D J Consumers Power Co 2pp 18740 100. 24X Fiche 50-255.83/05/31.8306070062
- --8306070063 Bafety evaluation on integrated plant SAR Section 4 27 re svc & cooling water 448 * Operating Reactors Branch 5 83/05/31 3pp 18740 102 24% Fichs 50-255,83/05/31,8306070062
- 8304070079 Forwards schedule for completion of full-term license SEP commitments contained in NUREG-0827 Three items resolved after issuance of draft NUREG-0827 listed LINDER; Dairyland Power Cooperative L-9124 83/06/02 CRUTCHFIELD, D. Operating Reactors Branch 5 10pp 18738-204 24: Fiche 50-409,83/06/02,8306070079
- 8306070086 Provides results of chlorine, boron & pH analyses performed for chemical test matrix, per NUREO-0737. Item II B 3, Criterion ID. to demonstrate analytical capabilities in presence of interfering ion concentrations FAY.C W Misconsin Electric Power Co 83/06/03 DENTON, H R Office of Nuclear Reactor Regulation, Director 2pp 18737-350-24X Fiche 50-266,83/06/03,8306070086
- B306070123 Submits revs to B3D525 augmented RCS leak detection submittal & inservice insp grogram commitment, incorporating surveillance frequencies per NUREG-0313. Rev 1 Insp &/or mod plans for recirculation & RHR sys piping forthcoming OUCHALT Georgia Power Co NED-83-320 B3/06/02 STGLZ, J F Operating Reactors Branch 4. 2pp 18739 266 24X Fiche 50-366, B3/06/02, B306070125
- B306070153 Responds to B21013 itr finding util position on NUREQ-0737, Item II K 3 25 re power on pump seels acceptable Addliatore component cooling water pumps B & C clarified.
 Both pumps automatically tripped by containment spray 4% ZIMMERMAN, B R Carolina Power & Light Co B3/05/31. VARGA, B A Operating Reactors Branch 1 2pp 18736 241 24X Fiche 50-261,83/05/31.8306070153

- B306070177 Requests 30-day extension for response to B30305 notice of violation & proposed imposition of civil penalties Delay due to complexity of issues & consideration of available options
 UDERITZ.R A Public Service Electric & Gas Co of New Jersey
 B3706/01 DEYOUNG, R C Director's Office. Office of Inspection and Enforcement 2pp 18736/327 24X Fiche 50-272,83/06/01.8306070177
- 8306070185 Forwards application to amend License DPR-64 to conform requirements of OL-82-16 concerning NUREO-0737 Tech Specs BAYNE, J P Power Authority of the State of New York IPN-83-49 B3/06/01 EISENHUT, D © Division of Licensing 2pp 18736 304 24X Fiche 50-286.83/06/01.8306070185
- --8306070197 Application to amend License DPR-64 changing Fech Specs in accordance w/requirements of Generic Ltr 82-16 re NUREO-0737 items
 BAYNES, J.P. Pawer Authority of the State of New York QL-82-16
 83/06/01 12pp 18736 306 24X Fiche 50-286,83/06/01,8306070185
- B306070193 Responds to B30322 ltr re open issues of NUREC-0737.

 Item II E 1 1. "Auxiliary Feedwater Bys Evaluation," Review of Recommendations GL-2 re environ qualification & OL-4 re flow test to be completed by B3073;

 MARSHALL,JR Arkansas Power & Light Co 1CANO58307 B3/05/31

 BTOLZ.JF Operating Reactors Branch 4 2pp 18736 296 24X Fiche 50-313,83/05/31.8306070193
- 8306070208 Responds to 830208 Generic Ltr 83-10D on plans & schedule for resolving NUREQ-0737. Item II & 3 5 na trip criteria for reactor coolant pumps Util will foilow guidance provided by Westinghouse & Westinghouse Comers Group ALEXICH. A P Indiana & Michigan Electric Co GL-83-10D 89/06/02 EISENMUT. D 9 Division of Licensing IIpp. 18747 034 24X Fiche: 50-315,83/06/02,8306070208
- 8306070237 Forwards revised draft response to Quastion 410 17 re CP application compliance w/NUREG-0800 per 830030 meeting w/NRC Changes will be incorporated in FEAR rev scheduled for June 1983
 BRADLEY,E J Philadelphia Electric Co 83/06/03 SCHWENCER, A Licensing Branch 2 3pp 18747 048 24% Fiche 50-352,83/06/03,8306070239
- 8306070300 Forwards proposed schedule for completing requirements of NUREO-0737. Suppl 1. "Emergency Response Capability." per 830810 meeting Commitments from 830418 ltr remain unchanged HILOUS; W S Florida Power Corp 3F-0583-24 83/05/31 STOL7, J.F Operating Reactors Branch 4 Bpp 18740 305 24X Fiche: 50-302: 93/05/31, 8306070300
- B306070303 Advises that individual program plan will be submitted by B31017 referencing BWR Quiners Oroup generic program glan re NRC B30417 Generic Ltr B3-18, Suppl 1 to NUREG-D737, Item I D 1. "Control Room Design Review "
 BAYNE, J P Power Authority of the State of New York QL-B3-18 B3/06/03 VABSALLO, D. B. Operating Reacture Branch 2 2pp 18740 301 24X Fiche 50-333, B3/06/03, B306070303
- 8306070343 Responds to Generic Ltr 82-16 re NUREO-0737 Tech Specs for listed TMI items Some Tech Specs incorporated some not applicable 1 some unnecessary.

 Q'TOOLE, J D Consolidated Edison Co of New York, Inc GL-82-16 83/05/31 EIBENHUT. D G. Division of Licensing opp 18742 031 24X Fiche. 50-247. 83/05/31. 8306070343
- 8306070363 Responds to 830202 request for add1 info re NUREQ-0737, Item II K 3 28, "Verify Qualification of Accumulators on Automatic Depressurization Sys Velves " W/one aversize drawing, Aperture card it avaitable in PRR. DALTROFF, 8 L. Philadelphia Electric Co 83/06/02 STOLZ, J F Operating Reactors Branch 4 11pp 18743 075 24X Fiche 30-277,83/06/02,8306070363
- 8306070437 NUREC-0800 FC
 PROPOSED REVISIONS TO STANDARD REVIEW PLAN.PSRP 3 4 6.Rev 3.
 PSRP 5 4 7.Rev 3:PSRP 6 3.Rev 2:PSRP 9.2 1.Rev 3:PSRP 9.2.2.
 Rev 2:PSRP 10 3.Rev 3 & PSRP 10 4 7.Rev 3
 + Office of Nuclear Reactor Regulation. Director 83/06/06 87pp
 18783 102
- 8306070444 Forwards Suppl 2 to SER (NUREO-0833). W/o encl 80HMENCER:A Licensing Branch 2 83/05/31 WULLER:O Illinois Power Go Ip. 18780.351 24X Fiche:30-461,83/05/31,8306070444
- --8306070446 Forwards Suppl 2 to May 1983 SER (NUREQ-0853). W/o encl * Office of Nuclear Reactor Regulation, Director 83/05/26 OTTINGER, R House of Rep : Energy & Commerce. ip 18780: 352 24X Fiche 30-461: 83/05/31.8306070444

- ~~83060/0447 Forwards Suppl 2 to Hay 1983 SER (NUREG-0853) W/o entl * Office of Nuclear Reactor Regulation, Director 83/05/26 SIMPSUN.A Senate, Environment & Public Works 1p 18780 353 24X Fiche 50-461,83/05/31,8306070444
- --8306070491 Forwards Suppl 2 to May 1983 SER (NUREC-0893) W/o encl * Office of Nuclear Reactor Regulation, Director 03/05/26 UDALL,M House of Rep. Interior b Insular Affairs ip 18780 354 24X Fiche 50-461,83/05/31.8306070444
- 8306070452 NUREG/CR-3290
 FEASABILITY STUDY ON THE DEVELOPMENT OF A NON-INVASIVE
 LIQUID LEVEL GAUGE FOR NUCLEAR POWER REACTORS
 BARATTALA J , JESTER.W A , INEL, O F Pennsylvania State Univ F.M
 G-1027 B3/05/31 Division of Accident Evaluation B4pp
 Available at NRC #4 50 18782 020
- B306070471 NUREG/CR-3248
 STUDIES OF FISSION PRODUCT SCRUBBING WITHIN ICE
 COMPARTMENTS
 WINEGARDNER, W. Battelle Memorial Institute, Pacific Northwest
 Laboratory POSTMA, A. K. Benton City Technology JANKOMSKI, H. H.
 Office of Nuclear Regulatory Research, Director FIN B-2444
 PNL-4691 BJ/05/31 Division of Engineering Technology 37pp
 Available at NRC 34 25 18782 103
- B306070473 NUREO/CR-3291 AN AMALYSIS OF BOILING WATER NUCLEAR REACTOR STABILITY MARGIN BALARAM, J. GHEN, C N., LAHEY, R T. Rensselder Polytechnic inst. FIN B-7270 B3705731 Division of Accident Evaluation 235pp Available at NRC \$7 50 18759 182
- 8304080125 Forwards SER open item response to Chemical Engineering Branch request for additinfore NUREG-0737. Item II 0 3. "Post-Accident Sampling Capability "Info suppls 821201 response & DL application Amend 48 DEVINCENTIS, J Yankee Atomic Electric Co DEVINCENTIS, J Public Barvice Co of New Hampshire 58N-514 83/05/31 KN10HTON. 0 W Licensing Branch 3 21pp 18772 333 24x Fiche 50-443.83/05/31, 8306080125
- 8306080137 Forwards "WH Zimmer Nuclear Power Station. Unit 1. Heavy Loads Rept." in response to supplemental SER (NUREG-0528, Suppl 3) & NUREG-0512 re control of heavy loads MILLIAMS, J. Cincinnati Gas & Electric Co. 83/06/02 DENTON. H. Deffice of Nuclear Reactor Regulation, Director. 87pp. 18768-275-24X Fiche 50-358,83/06/02,8306080137
- --8306080140 "WH Zimmer Nuclear Power Station, Unit 1. Heavy Loads Rept "
 * Cincinnati Gas & Electric Co 83/06/01 108pp 18768 277
 24X Fiche 50-358 83/06/02 8306080137
- 8306080146 NUREG-0704
 FINAL ENVIRONMENTAL STATEMENT RELATED TO THE DECOMMISSIONING
 OF THE RARE EARTHS FACILITY, MEST CHICAGO, ILLINOIS Docket
 No 40-2061
 * Division of Fuel Cycle & Material Safety 83/05/31 522pp
 Available at NRC \$10.00 18788 001
- B306080138 NUREQ-0880 RO1 FC BAFETY GOALS FOR NUCLEAR POWER PLANT OPERATION * Office of Policy Evaluations B3/05/31 116pp 18789 163
- B3D60B016B NUREG/CR-3174 VO1

 GEOPHYSICAL-GEOLOGICAL STUDIES OF POSSIBLE EXTENSIONS OF THE

 NEW MADRID FAULT ZONE Annual Report For 1982

 HINZE,W J , BRAILE,L W , KELLER, G R Purdue Univ FIN D-8077

 B3/05/31 Division of Health, Siting & Waste Management 101pp

 Available at NRC \$4 75 18790 001
- 8306080198 Informs that requirements of TMI Item II 8 2 2, "Design Review of Plant Shielding & Environ Qualification of Equipment for Spaces/Sys Which May Be Used in Post-Accident Operations," met CRUTCHFIELD.0 Operating Reactors Branch 5 L605-83-06-011 83/06/07 COUNSIL.W G Northeast Nuclear Energy Co (subs of Northeast Utilities) 6pp 18772 233 24X Fiche 50-243.83/06/07.8306080198
- B306080213 Informs that station blackout procedure approved & available for NRC review, per NUREQ-0528, Suppl 3, Subsection 8 i 2 WILL IAMS, J Cincinnati Qas & Electric Co 83/06/01 DENTON, H g Office of Nuclear Reactor Regulation, Director ip 18771 182 24% Fiche 50-358, 83/06/01, 8306080213
- 830608025! Forwards "Control of Heavy Loads (C-10) St Lucie Unit i," draft technical rept,per util response to Section 2 1 of 801222 generic ltr re NUREO-0612 Completion of review by 830617 requested CLARK,R A Operating Reactors Branch 2 83/05/24 UHRI9.R E Florida Power & Light Co 2pp 18787 137 24% Fiche 50-335.83/05/24.830608025!

- --8306080252 TER-C5506-394 DRFT
 "Control of Heavy Loads (C-10) St Lucie Unit 1, 'draft technical evaluation rept
 BQMBERGER, C. AHMED, N. Franklin Institute/Franklin Research
 Center NRC-03-81-130 TAC 08083 83/04/29 CLEMENSON, F. NRC -No Detailed Affiliation Given 36pp 18787 141 24X
 F160# 30-335,83/05/24,8306080251
- 8306080268 Responds to FOIA request for SCCY-83-22 Forwards publicly available portions of paper per telcon w/n Toms FELTON.# H Division of Rules and Records 83/04/11 KNIGHT.N L General Physics Corp 1p 18787 240
- --8306080770 "Statement of policy Further Commission Quidance on Energency Response Capability," draft 10CFR50 effective rule Suppl issued to NUREO-0737, "Clarification of IM1 Action Plan Requirements"

 CHILK I Office of the Secretary of the Commission B3/04/t1 3pp 18787 241
- 8305080375 Forwards review of "Reactor Sarety Study Methodology Applications Program Deonee 3 PWR Power Plant (NUREC/CR-1657, 2 of 4) " Review identified dominant core melt sequences & required licensing actions STOLZ.J F Operating Reactors Branch 4 83706/01 TUCKER.H B Duke Power Co 14pp 18787 279 24X Fiche 50-287.83/06/01. p306080375
- B306080437 Summary of B30526 meeting w/util in Bethesda, MD re present containment purge sys design, Outstanding Issue 10 in BER (NURCO-0887)
 STEFANG, J J Licensing Branch 1 B3/06/03 YOUNOBLOOD, B J Licensing Branch 1 12pp 18792 197 24X Fiche 50-440, B3/06/03, B306080437
- 8305090057 Forwards IE Insp Rept 50-322/63-10 on 830401-0509 & notice of violation STAROSTECKIR Division of Project & Resident Programs 83/05/27 FDLLOCK M S Long Island Lighting Co 2pp 18793 290 24X Fiche 50-322.83/05/27.8306090067
- --8306070076 IE Insp Rept 50-322/83-10 on 830401-0507 Noncompliance noted failure to assure that changes to emergency diesel generator test procedures distributed & used HIGGINS-J C , MCCARE, E C , KUNKLE, G L Region 1, Diffice of Director IEB-80-15 83/05/25 14pp 18793 273 24X Fiche 50-322,83/05/27,8306070067
- 8305090118 Advises of approval of emergency response plan for facility, judy to verification of adequacy of public alerting & natification sys
 MCLOUGHLIN,D Federal Emergency Management Agency 83/05/16
 DIRCKB.W.J Dffice of the Executive Director for Operations ip
 18793 329 24X Fiche 50-153,83/05/16.8306090118
- 8306090170 Forwards review of CESSAR-F against requirements of CP/ML rule 10CFR50 34(f) & selective sections of App B & Chapter 3 of CESSAR-F Only fraction of rule requirements within scape of CESSAR-F CESSAR-F camplies w/rule SCHERER, A E Cambustion Engineering, Inc LD-83-047 83/05/25 EISEMHUT, D Q Division of Licensing 103pp 18794 010 24X Fiche 30-470,83/05/25,8306090170
- 8306090194 Discusses util interpretation of 10CFR50 49, "Environ qualification of Electrical Equipment Important to Safety for Nuclear Power Plants " Intent of rulemaking is to require upgrade program for replacement equipment not parts FARRAR, D. L. Commonwealth Edison Co. 4702N 83/06/03 DENTON, H. R. Office of Nuclear Reactor Regulation, Director. 3pp. 18796-090-24X Fiche 50-000, 83/06/03, 8306090194
- 830A090229 Appraves State of MI emergency response plan & associated local plans w/condition that adequacy of public alerting & notification sys be verified per FEMA/NRC joint criteria ilsted in NUREO-0.654/FEMA-REP-1. Rev I. App 3 PAPERIELLO, C J Region 3, Office of Director 83/06/06 DEWITT.R B Consumers Power Co 2pp 18796 235 24X Fiche 50-155,83/06/06,8306090229
- 8364090232 Advises that NUREO-0824, Section 4 1 6 concerns resolved.

 **fased on util 830113 response, per SEP Topic II-9 B 1.

 **Capability of Operating Plant to Cope W/Design Basis

 **Floading Conditions " Procedure OP 5144 revised by 830727

 **COWNSILN G Northeast Nuclear Energy Co (subs of Northeast

 Utilities) COUNSILL O Northeast Utilities 810797 83706/03

 **CRUTCHFIELD. D Operating Reactors Branch 5 2pp 18795-344 243

 **Fiche 50-245,83704/03.8306090232
- 8204090233 Provides info for resolution of NUREG-0737, Item II E i i open items re review of upgraded auxiliary feedwater sys ROBRIGUEI, R J Sacramento Municipal Utility District 83/06/03 STOCLJ F Operating Reactors Branch 4 2pp 18795 342 24X Fighe 50-312,83/06/03.8306090233

- B306090237 Forwards "Emergency Operating Procedures Generation Package." in response to Generic Ltr B2-33 Suppl 1 to NUREG-0737 MUSDLF.D Northern States Power Co. GL-82-33 83/05/31 Office of Nuclear Reactor Regulation, Director 1p 18797 001 24X Fiche 50-282.83/05/31,8306070237
- 8304070267 Forwards safety evaluation of BNR Owners Group response to NUREO-0737. Item II K G 18. "Mod of Automatic Depressurization Sys Logic "Acceptable options Include elimination of high drywell pressure permissive CRUTCHFIELD.D Operating Reactors Branch 5 LSB5-83-06-016 B3/06/08 COUNSIL.W G Northeast Nuclear Energy Co (subs of Northeast Utilities) 2pp 18795 280 24% Fiche 50-245,83/06/08,8306090267
- ~~B306090272 Bafety evaluation of BHR Owners Group response to NUREG-0737. Item II K 3 18, "Mad of Automatic Depressurization Bys Logic "Acceptable options include elimination of high drywell pressure permissive Office of Nuclear Reactor Regulation. Director 83/06/08 5pp 18795 282 24X Fiche 50-245, 83/06/08. B306090267
- 8306090361 Forwards request for exemption from emergency operations facility (EDF) location requirements per Generic Ltt 82-33. Proposed EDF to be located 125 air miles from facility. W/ joint news ctr remaining in Oconee. NC TUCKER. H B Duke Power Co GL-82-33 B3/06/03 DENTON, H R. Office of Nuclear Reactor Regulation, Director 28pp 19795-039 24X fiche 50-269.83/06/03,8306090361
- B306090369 Forwards comments on CRGR review package re NUREG-0666.
 "Probabilistic Safety Analysis of DC Power Supply
 Requirements for Nuclear Power Plants " Assistance of lead
 project manager offered
 EISENHUI, D @ Division of Licensing B3/06/02 MATTBON.R J
 Division of Systems Integration (post 811003) 2pp 18814 016
- 8306090386 Forwards request for addl info re response to encl "Control of Heavy Loads at Nuclear Power Plants, Phase 1. Nebrasks Public Power District, Copper Nuclear Station " Draft technical evaluation rept encl Info requested in 60 days VASSALLQ, D B (Aperating Reactors Branch 2 83/09/26 PILANT, J M Nebraska Public Power District 13pp 18814 042 24X Fiche 50-278,83/05/26,8306090386
- --8306070388 TER-C5806-346 DRFT

 "Control of Heavy Loads (C-10). Nebraska Public Power
 District, Cooper Nuclear Station." draft technical evaluation
 rept
 VOSBURY, F., VITO, D., SARGENT, I. H. Franklin Institute/Franklin
 Research Center NRC-03-81-130 TAC 07782 82/12/30
 CLEMENSON.F. NRC No Detailed Affiliation Given 27pp
 18814-055 24X Fiche 50-278.83/05/26.8306090386
- 8304090393 Forwards request for add1 info re three open items concerning controls for handling heavy loads Franklin Research Ctr draft technical evaluation encl Response requested within 60 days of receipt of itr STGLZ.JF Operating Reactors Branch 4 83/05/31 RODRIQUEZ.R J Sacramento Municipal Utility District 13pp 18815 037 24X Fichs 50-312.63/05/31,8304090393
- --B306090397 TER-C5257-388 DRFT

 "Control of Heavy Loads, Bacramento Municipal Util District,
 Rancho Seco Nuclear Generating Station," draft technical
 evaluation rept
 VOSSURY,F W, VITO,D J, SARGENT,I H Franklin Institute/Franklin
 Research Center NRC-03-Bi-130 TAC 08079 83/01/13
 CLEMENSON,F NRC No Betailed Affiliation Given 28pp
 18815 050 24X Fiche 50-312,83/05/31,8306090393
- 8304090426 Forwards safety evaluation & technical avaluation rept.
 "Control of Heavy Loads " Guidelines of NUREO-0612
 satisfies
 CLARK: A Decrating Reactors Branch 3 83/05/27 LUNDVALL: A E
 Baltimore das & Electric Co 2pp 18809 107 24X
 Fichs 50-317.83/05/27,8306090426
- ---B306090492 Safety evaluation accepting util response to "Control of Heavy Loads Phase I " Item resolved * NRC No Detailed Affiliation Given. 83/05/27 2pp 18809 107 24X Fiche, 50-317, 83/03/27, 8306090426
- 8306100018 Requests route approval for irradiated fuel shipments from West Valley.NY to Two Rivers.WI DANESE.F L Nuclear Assurance Corp 22352 83/05/26 HILLMAN.C Division of Bafeguards 3pp 18815 306 24% Fiche 50-266.83/05/26.8306100018

- 8306100055 Describes integrated assessment of open issues & schedule for issue resolution & documents util response to environ equipment qualification & Generic Ltr 82-33 rs NUREG-0737 TOMER, K A Consumers Power Co GL-82-33 83/06/01 CRUTCHFIELD, D Operating Reactors Granch 5 113pp 18804 D48 244 Fiche 50-155,83/06/01.8306100055
- 8305100039 "Control Roam Design Review Plan.Prairie Island Nuclear Generating Plant:" response to Generic Ltr 82-33, Suppl 1 to NUREO-0737 M/830527 1tr NUSOLF, D Northern States Power Co OL-82-33 83/05/27 47pp 18802 123 24X Fiche 50-282,83/05/27,8305100059
- 8306100097 Forwards schedule implementation plan for emergency response capability & list of submittals required by NUREG-0737.

 Suppl 1.per Generic Ltr 82-33 Procedures generation package will be submitted by 840501

 HULLER.G E Illinois Power Co GL-82-33 83/06/06 SCHWENCER, A Licensing Branch 2 5pp 18804 043 24X Fiche 50-461,83/06/06.

 8306100097
- 8306100113 Forwards addl info re time frame for providing access to hydrogen recombiner panel area per 830213 commitment to NUREO-0737. Item II B 2. "Plant Shielding "Hydrogen recombiner panel access time of 5 days appropriate BAYNE.J P Power Authority of the State of New York FN-83-52 83/06/03 EISENHUT. D 0 Division of Licensing 5pp 18802 018 24% Fiche 50-286,83/06/03.8306100113
- 8306100114 Forwards listing of scheduled completion dates for BEP integrated assessment open issues requiring add1 action by util Each issue resolution documented in draft NUREG-0826 Tapte VI-7 C t resolution authined COUNSIL.W O Connecticut Yanke Atomic Power Co B10806 83/06/02 CRUTCHFIELD.D Operating Reactors Branch 5 15pp 18802/186 24) Fiche: 50-213,83/06/02,8306100114
- 830A100132 Forwards Rev O to "Design Rept for Weld Gverlay Repairs & Flaw Evaluations in Recipculation & RHR Sys " Sensor check will be performed every 4 hours in addition to interval required by Tach Specs, effective at restart GUCHA, L T Georgia Power Co NED-83-341 83/06/08 870LZ, J F Operating Reactors Branch 4 2pp 18801 262 24X Fiche 50-366,83/06/08,8306100132
- B306100147 Forwards revised draft versions of "Cultural Resources Mgt Plan for Residual Lands" & "Phase 1 Cultural Resources Survey & Assessment to Residual Lands" & responses to SHPO comments SCRNELL.D F Union Electric Co ULNRC-634 83/06/03 DENTON.H R Office of Nuclear Reactor Regulation. Director 44pp 18307 237 24X Fiche, 50-483,83/06/03,8306103147
- 8306100184 Forwards comments on draft NUREQ-0827, "Integrated Plant Safety Assessment:8EP," to help improve rept accuracy LINDER:F Dairyland Power Cooperative LAC-9126 83/06/02 CRUICHFIELD,D Operating Reactors Branch 5, 5pp 18206 024 24X Fiche 30-409,83/06/02,8306100184
- 8306100189 Restates previous commitment to install redundant radiation monitor in control room HVAC sys.per NUREG-0737. Item 111 D 3 4, "Control Room Habitability," in response to 830401 request QIESLER.C W Wisconsin Public Service Corp NRC-83-(16 83/06/06 VARQA.6 A Operating Reactors Branch | 3pp 18805 257 24% Fiche 50-305.83/06/06.8306100189
- B306130176 Forwards final response to NUREO-0612, "Control of Heavy Loads at Nuclear Power Plants"

 SCHMIDT, H C Texas Utilities Services, Inc TXX-3659 B3/06/08 YOUNOBLOOD, B J Licensing Branch 1 153pp 18828 031 24X

 Fiche 30-445,83/06/08.8306130176
- 8304130260 Comments on NUREO/CR-2337.Vois ; & A. "Aquatic Impacts From Operation of Three Midwestern Nuclear Power Stations "Author evaluation & conclusions differ from util understanding gained in studies Supporting info encl JONEBN C Obmaha Public Power District LIC-83-130 83/06/06 VOLLMER.R H Division of Engineering 40pp 18824 194 24X Fiche 50-285.83/06/06.8306130260
- B306130334 Forwards "Suppl 1 to NUREG-0737, Milestone Activity Submittal of Updated Detailed Control Room Design Review Program Plan "
 TONER, K. A. Consumers Power Co. B3/06/07 CRUIGHFIELD, D. Operating Reactors Branch 5. ip 18822 197, 24% Fiche 50-255,83/06/07, B306130334
- --8306130335 "Buppl 1 to NUREQ-0737. Wilestone Activities Submittal of Updated Datailed Control Room Design Review Program Plan "

 Consumers Power Co 83/06/07 12pp 18822 178 24X Fichs 50-255,83/06/07,8306130334.

- 8306130336 Forwards safety evaluation supporting util decision not to paroute reactor water cleanup sys return line per NUREG-0619 Decision based on value-impact analysis & sleeve leakage measurements SHEALJ J Operating Reactors Branch 5 LSOS-83-06-024 83/06/07 COUNSIL N O Northeast Nuclear Energy Co (subs of Northeast Utilities) 2pp 18822 153 24X Fiche 50-245.83/06/09.8306130355
- --8306130358 Safety evaluation supporting util decision not to rescute reactor water cleanup sys return line per NUMEG-0619
 Decision based on value-impact analysis & sleeve leakage measurements

 Uffice of Nuclear Reactor Regulation, Director TAC 08412
 83/06/09 2pp 18822 155 24% Ficho 50-245.83/06/09.8308130355
- 8304130362 Forwards revised response to NUREO-0737. Itom [1 f], committing to install GA Co Model RD-23 high-range gas monitars by fuel load MILLS, L. M. Tennessee Valley Authority 83/06/07 ADENSAM, E. Licensing Branch 4. App. 18822 157 24% Fiche 50-390.83/06/07, 8306130362
- 8304[30385 Advises of cancellation of CRGR Moeting 41 to permit NPR to reevaluate NUREG-0801. "Evaluation Criteria for Detailed Control Room Design " & NUREG-0835. "Human Factors Review Quidelines for Safety Parameter Display Bys " STELLO.V Regional Operations & Generic Requirements B3/04/09 MATTSON.R J Office of Nuclear Reactor Regulation. Director JORDAN.E L Director's Office Office of Inspection and Enforciagnt CUNNINGHAM.R E Office of Nuclear Material Safety & Safeguards. Director 1p 18822 215
- 8306130415 Requests exemption from 10CFR50 48(c) schedule requirements per 10CFR50 12 for completion of fire protection mods at fuel & auxiliary bldg 45-ft elevations Deferral requested due to const manpower commitment WITHERS B D Portland General Electric Co 83/06/07 CLANK, A Operating Reactors Branch 3 2pp 18823 136 24X Fiche 50-344,83/06/07,8306130415
- 8306130429 Application for amend to Licenses NPF-2 & NPF-B, changing Tech Space re operating personnel.per NUREG-0737.Item I A i 3 & Generic Ltre 82-02 & 82-12, to incorporate current practices
 CLAYTON, F L Alabama Power Co CL-82-02 83/06/06 VANGA, S A OFFice of Nuclear Reactor Regulation, Director 3pp 18821 223 24X Fiche 50-348,83/06/06.8306130429
- 8306130431 Forwards SER re compliance w/NUREG-0737, Item III A 1 2. "Min Staffing Levels for Emergency Situations " Provisions for onshift staffing & augmentation acceptable HIND, J A Division of Radiological & Materials Safety Programs 63/06/10 BURSTEIN.S Wisconsin Floctric Power Co Opp 18821 215 24X Fichs 50-266.83/06/10.8306130431
- 8306130432 Responds to 830328 request for add1 info re adequaty of electric distribution sys voltages per SER (NUREC-0897) Response re adequacy of util info requested within 2 wts VAN BRUNT, E. E. Arizona Public Service Co. ANPP-23991-ACR/83/06/07 KNIGHTON, G. Licensing Branch 3 6pp 18821 195 24x Fiche 50-528,83/06/07,8306130432
- 8306130495 Forwards synopsis of resolutions to open items re control of heavy loads at nuclear power plants.per NURCO-0612 guidelines Draft final technical evaluation rept & request for add info enci
 WASSALLO.D D Operating Reactors Branch 2 83/05/26 SINCLAIR.J B Vermont Yankes Nuclear Power Corp 13pp 18830 107 24X Fiche 50-271.83/05/26,8306130495
- 630614020B Application for amend to Licenses NPF-4 & NPF-7.adding aidlaccident monitoring instrumentation b instrumentation for detection of inadequate core cooling per requirements of NUREO-0737.Itams IIF i & IIF 2

 BYEMART, W L Virginia Electric & Power Co 333 83/06/03

 DENTON, H R Diffice of Nuclear Reactor Regulation, Director CLARK, R A Depeating Reactors Branch 3 4pp 18841 165 24X

 Fishe 50-338,83/06/03,8304140208
- --8306140222 Proposed changes to Tech Specs adding addl accident manitoring instrumentation & instrumentation for detection of inadequate core cooling per requirements of NUREG-0737. Items 11 F 1 & 11 F 2

 * Virginiz Electric & Power Co 83/06/03 22pp 18841 169 34t Fichs 50-338,83/06/03.8306140208
- 8306140277 Informs that analysis of inlet & discharge piping for reliff & safety valves refined to reflect more realistic conditions.per 830215 ltr & TMI Action Item II D I Listed options will be considered if overstress condition revealed BAYNE, J Power Authority of the State of New York IPN-83-85 83/06/08 VARGA,8 A Operating Reactors Branch 1 2pp 19832 23 24% Fiche 50-286,83/06/08,8306140277

```
8305140315 NUREG/CR-2766
       305140315 NUREG/CR-2786
DESIGN DASIS FOR THE NRC OPERATIONS CENTER
DESROSIERS, A E . MEITZLER, W D Battelle Memorial Institute, Pacific
Northwest Laboratory LINDELL, M K Battelle Human Affairs Research
Centers FIN D-2182 83/05/31 Division of Emergancy
Freparedness & Engineering Response (Post 830103) 108pp Available
at NRC 44 75 18852 166
```

8306140318 Informs that additinfo requested on 830511 re NUREG-0737.

Item II K 3 28, "Qualification of Automatic Depressurization

Sig Accumulators," will be provided by 830930

BAYNE, J P Power Authority of the State of New York JPN-83-53

83706/09 VASSALLO. D B Operating Reactors Branch 2 3pp

18832 207 24X Fiche 50-333.83/06/09,8306140318

8306140324 NUREG-0090 V05 N04 MEPORT TO CONGRESS ON ABNORMAL OCCURRENCES October - December 1982

• Director's Office 83/05/31 36pp 18854 080

0306140402 NUREQ/CR-3087 INCINERATION OF A TYPICAL LWR COMBUSTIBLE WASTE AND ANALYSIS OF THE RESULTING ASH OF THE RESULTING ASH
TREAT,R L , LOKKEN,R O , BCHLIEBE,M J Battelle Memorial Institute,
Pacific Northwest Laboratory FIN 8-2401 PNL-4563 B3/05/31
Division of Health. Siting & Waste Management 70pp Available at
NRC \$4 50 18845 248

8306140407 NUREG/CR-9219 VD2 DRAFT TECHNICAL POBITION Subtask i 2 Post Emplacement Honitoring PANNO.8 V Brookhaven National Laboratory FIN A-9168 BINL-NUREG-51658 93/05/31 Division of Waste Hanagement 121pp Available at NRC \$5 00 18845 061

6306140408 Forwards evaluation of BWR Umners Group generic response to NVREQ-0737. Item II K 3 18. "Hod of Automatic Depressorization Sys Logic-Feasibility for Increased Diversity for Some Event Sequences "Two options listed CRUICHFIELD-D Operating Reactors Branch 5 83/06/03 FARRAR.D L Commonwealth Edison Co 2pp 18837 354 24X Fichs 50-237.83/06/03, 270446009 8306140408

8305140414 Informs that interim plan to reduce blocked position from 50 to 140 degrees acceptable pending review of 830715 rept re out of plane upstream eldow SRP 6 2 4 & Positions 6 & 7 of TMI Action Item II E 4 2 closed CLARK.R A Operating Reactors Branch 3 83/05/27 UHRIO.R E Florida Power & Light Co 6pp 18854 072 24X Fichs 30-335.83/05/27,8306140414

8306140480 Forwards revised schedule for post-accident instrumentation transmitted by 830320 ltr re environ qualification of electrical equipment (10CFR50 47) Dato of referenced ltr corrected Original encl should be replaced MWKILL+H D General Public Utilities - OPU Service Corp 5211-83-173 83706/08 DENTON.HA Office of Nuclear Reactor Regulation, Director 2pp 18843 279 24X Fiche 50-287,83/06/08,8306140480 0305140480

0306140300 Forwards responses to 801222 ltr re NUREO-0612, "Control of Heavy Loads at Nuclear Power Plants " Info addresses overhead handling sys for fuel storage pool CROUSE.R P Toledo Edison Co 932 83/06/10 8TOLZ.J F Operating Reactors Branch 4 142pp 18843 076 24X Fichs 50-346:83/06/10.8306140300

8306140538 Forwards IE insp Repts 50-335/83-06 & 50-389/83-20 on 830314-18 No noncompliance noted DAVICE-H C Division of Project & Resident Programs 83/05/18 UMRIGNE Florida Power & Light Co 2pp 18834 145 24X Fischa 50-335,83/05/19,8304140538

--8306140541 IE Insp Repts 50-335/83-06 % 50-389/83-20 on 830314-18 No noncompliance noted Major areas inspected emergency

planning HUFFMAN, 9 N Region 2, Office of Director 50-389/83-20 83/05/17 App 18834:167 24X Fiche 50-335,83/05/18,8306140538

0306140362 Forwards IE Insp Repts 50-390/63-15 & 50-391/83-11 on 830321-0422 No noncompliance noted VERRELLI.D M Division of Project & Resident Programs 83/05/20 PARRISH 0 Tennessee Valley Authority 2pp 18844 129 24X Fiche 50-390 83/05/20 8306140562

-8304140580 IE Insp Repts 50-370/83-13 5 80-371/83-11 on 830321-0422
No noncompliance noted Major areas inspected plant tour,
operating, maint & smergency procedure inspected plant tour estate procedure review & observation of structural concrete
IMEATHERLY, T. L., SMAN, W. Region 2, Office of Director QUICK, D. R.
Division of Project & Resident Programs 50-371/83-11 83/05/20
18pp 18844 131 24X Ficher 50-370/83/05/20,8306140562

8306140631 Forwards IE Emergency Preparedness Appraisal Rept 50-382/83-08 on 830222-0304 No noncompliance noted Schedule for completing corrective actions for deficiency noted in App A requested within 30 days of receipt of ltr MADSEN, 0 L. Region 4, Office of Director 83/05/27 MAURIN, L. V. Louisiana Power & Light Co. 16pp. 18637 281 24X Fiche 50-382,83/05/27,8306140631

--8306140636 IE Emergency Preparedness Appraisal Rept 50-382/83-08 on 930222-0304 No noncompliance noted Major areas inspected administration emergency organization, training & retraining & emergency facilities HACKNEY.C A , PERROTTI.D J , WISNER.C E Region 4, Office of Director 83/05/21 37pg 18837 297 24X Fiche 30-382,83/05/27, 8306140631

B306140642 Forwards evaluation of BHR Owners Group generic response to NOREC-0737. Item II K 3 18, "Automatic Depressurization Sys Logic Mods " Two of seven BHR Owners Group alternatives acceptable Belection of option within 45 days requested CRUTCHFIELD.D Operating Reactors Branch 5 B3/06/03 FIEDLER,P B General Public Utilities - GPU Service Corp 2pp 18833 264 24X Fiche 50-217,83/06/03,8306140642

8306140691 NURE9/CR-9308 VOI EVALUATION OF ECOSYSTEM MODELS IN POWER PLANT IMPACT ASSESSMENT A CASE STUDY USING LAKE ONTARIO Description of Alternative Process Equations And Documentation of Parameter values KALUZNV.S P. ROSE.K A. SULLIVAN.P J. Washington, Univ. of. Geattle. WA FIN B-7018 83/05/3; Division of Health, Siting & Waste Management 68pp Available at NRC \$4.50 18845 182

B306140707 Forwards add1 info re NUREO-0737. Items II F. 1. 4, II.F. 1 5 & II F. 1 6 Due to small reactor size & low population density, existing equipment adequate for safe operation LINDER.F. Dairyland Power Cooperative LAC-9127 83/06/03 CRUTCHFIELD.D. Operating Reactors Branch 5 9pp 18841 279 24X Fichs 50-409, 83/06/03, 8306140707

B305140716 Submits followup response to 14 of 19 open items identified in NRC B30217 ltr re IE Emergency Preparedness Appraisal Ropt 30-299/82-34 on 821206-10 PILANT, J M Nebrasia Public Power District 50-298/82-34 83/05/13 MADSEN, C L Region 4, Office of Director 9pp 18841 323 24X Fiche 50-298,83/05/13,8306140716

8306140738 Forwards topical repts, "Boundary Analytical Assessment of NUREG-0630 on LCCA & Operating kH/Ft Limits," per 830602 request TUCKER: H B Duke Power Co 83/06/26 DENTON: H R D: Nuclear Reactor Regulation, Director 1p 18845-001 Fiche 50-269:83/06/06:8306140738

-B306140746 77-1141256-00 "Boundary Analytical Assessment of NUREO-0630 on LOCA & Operating kW/Ft Limits "

* Babcot & Wilcox Co 83/06/06 29pp 18845 002 : Fiche 50-269, 83/06/06, 8306140738 18845 002 24X

--8306140752 77-1140895-00 106140/32 //-1140945-00 "Bounding Analytical Assessment of NURE0-0630 on LOCA & Operating kW/Ft Limits " * Babtock & Wilcox Co 83/06/06 29pp 18845 032 2 Fichs 50-267, B3/06/06, B306140738 18845 032 24X

B306140774 NUREQ/CR-3239 COMPERN-A COMPUTER CODE FOR MODELING COMPARTMENT FIRES SIUN D California, Univ of Los Angeles FIN 8-0493 UCLA-ENG-8257 83/05/31 Division of Risk Analysis Available at NRC 44 75, 18853 115 Available at NRC

B306150011 Forwards detailed design description of implementation of NUREG-0737, Item II F 1 6. "Containment Atmospheric Monitor," per 830411 request Task to be completed by 840601 HARRINGTON.H D Boston Edison Co B3-143 B3/06/09 VASSALLO,D Operating Reactors Branch 2 14pp 18846 334 24X Fiche 50-293, 83/06/09, 8306150011 VASSALLO, D N

8304130064 NUREG/CR-2965
COPPER IN THE INTAKE AND DISCHARGE ZONES OF THE SURRY
AND SALEM NUCLEAR POWER STATIONS
HARRISON, Ft., KNEZOVICH, JF. Lawrence Livermore Laboratory, FIN
A-0119 UCRL-53325 83/05/31 Division of Health, Siting & Waste
Menagement 51pp Available at NRC. \$4 00 18869.221, 24X
Fiche 50-000,83/05/31,8306150064

- 830415008; NUREG/CP-0044 VO2
 PROCEEDINOS OF THE INTERNATIONAL ATOMIC ENERGY AGENCY
 SPECIALISTS' MERTING ON SUBGRITICAL CRACK GROWTH Sessions
 III, 19 And V Held At Freiburg, Federal Republic Of Germany,
 Nay 13-15,1981
 CULLEN, H Materials Engineering Associates, Inc. # ENSA, Inc
 FIN 8-8133 MEA-2014 83/05/31 Division of Engineering
 Technology 434pp Available at NRC \$9.00 18870 G97
- 8306130161 Requests extension of implementation date for torus mods to 90 days following startup from current refueling outage All internal mods & all torus-related mods complete Extension applies only to torus-attached piping HEIDER, L. H. Vermont Yankee Nuclear Power Corp. FVY 83-55 83/06/13 EISENHUT, D. 0 Division of Licensing 2pp. 18846-319 24X Fichs. 50-271. 83/06/13, 8306150161
- 8306150256 Forwards Suppl I to SER (NUREG-0896), addressing two outstanding issues to emergency preparedness & secondary water chemistry. Corrected page to NRC 820420 joint affidavit & HT LeFave 830511 affidavit e ncl W/O SER LES8Y, R P, PATTERSON, N F Hearing Branch 3 ISSUANCES OL 83/05/11 HOVT, H, LUEBKE, E A, HARBOUR, J Atomic Safety and Licensing Board Panel. 2pp 18849 191 24X Fiche 50-443, 83/05/11, 8306150236
- 8306150260 Forwards "Control of Heavy Loads (C-10). TVA. Browns Ferry Nuclear Power Station, Units 1,2 & 3," draft technical evaluation rept Conference call requested within 4 to 5 wis to discuss review results
 VABSALLO.D B Operating Reactors Branch 2 83/05/26 PARRIS. H G Tennesse Valley Authority 2pp 18869 322 24X
 Fiche 50-239, 83/05/26, 8306150260
- --8306150266 TER-C5506-337/338/33

 "Control of Heavy Loads (C-10), TVA, Browns Ferry Nuclear Power Station, Units 1,2 & 3," draft technical evaluation rept

 BUMBEROER, C Franklin Institute/Franklin Research Center NRC-03-81-130 TAC 07975 83/04/05 CLEMENSON, F NRC No Datailed Affiliation Given 25pp 18949 324 24X Fiche 50-259,83/05/26,8306150260
- --9306130272 "Synopsis of Issues Associated w/NUREQ-0612."

 * Operating Reactors Branch 2, 83/05/26 lipp 18869 349 24X
 Fishs 50-259,83/05/26,8306150260
- 8306130321 Forwards request for add1 info re FSAR Design Criteria Bummary, Item 260-36 reflecting requirements of NUREO-0737. "Clarification of TMI Action Plan Requirements." 8CHMENCER.A Licensing Branch 2 B3/06/07, BAUER.E 0. Philadelphia Electric Co 7pp 18870-010 24X Fichs 30-352.83/06/07, 8396130321
- 8304150391 Forwards supplemental SER, NUREG-0882 to NRC review of licenses emergency plan. W/o and lacenses emergency plan. W/o and lacenses emergency plan. H/o and lacensing Board Fanel ip 18847'028 24X Fiche 50-170,83/06/10,8304150391
- 8305150434 Releases public version of revised emergency plan administrative procedure. FELYON, J K Division of Rules and Records 83/06/06 Document Management Branch 1p 18869 148, 24X Fiche 50-483,83/06/06, 8306150434
- ---8306150455 Public version of Rev O to Emergency Plan Administrative Procedure APA-ZZ-O0102. "Emergency Operating Procedures Writers Ouide " Item numbers on encl correspond to numbers used in Generic Ltr 92-33 W/830511 ltr, SCOIT: W G : SCHNELL, D.F Union Electric Co ULNRC-627 83/04/07 DENTON: HR Office of Nuclear Reactor Regulation: Director 49pp. 19869 147 24X Fiche 50-483,83/06/06/8306150454
- 8306130466 Forwards safety evaluation of util submittals on NUREO-0737 leans 1 A 2 1 4, "Upgrading Reactor Operator & Senior Reactor Operator Training for Hitspating Core Damage." Items resolved VABBALLO: D B Operating Reactors Branch 2 83/06/03. MUSOLF. D M Northern States Power Co 5pp 18869 214. 24X Fiche 50-263.83/06/03.8306150466
- 8306150508 Forwards SER supporting B30128 submittel Te TM1 Action Plan Items II.F.1 4, "Containment Pressure Monitor," II F.1 5, "Gontainment Water Level Monitor," & II F 1 6, "Containment Hydrogen Honitor " Requirements met.
 BTOLI, J F Operating Reactors Branch 4 83/05/24 CROUSE, R P Toledo Edison Co 2pp 18866 313, 24X Fiche 50-346,83/05/24, 8306150508

- --8306130515 Safety evaluation supporting licensee 830128 submittel re NUREG-0737, Items II F i 4. "Containment Pressure Monitor," II F i 5. "Containment Water Level Monitor," & II F i 6. "Containment Hydrogen Monitor " Requirements met 4. Office of Nuclear Reactor Regulation. Director 83/05/24 app 18866 315 24% Fiche 50-346,83/05/24,8306150908
- 8306150352 Forwards assessment of "Quick Look" rept in response to 830304 & 30 ltrs re submittal of initial evaluation of safety relief valve in-plant test results Add1 info requested SCHWENCER. A Licensing Branch 2 83/06.07 FARRAR, D.C. Commonwealth Edison Co. 5pp. 18867-029 24X Fiche 30-373.83/QA/Q7, 8306150552
- 8306150574 NUREG/9R-0025 VO9 NS INFORMATION REPORT ON STATE LEGISLATION KERR, 0 W. LANDAU, M. Office of State Programs, Director 03/06/30 11pp. 18854 336
- 8306150976 Forwards safety evaluation of util submittals re NUREG-0/3).

 Item II B 2 on plant shielding mods Item resolved

 VASSALLO.D B Operating Reactors Branch 2 83/05/23 MySOLF.D M
 Northern States Power Co 4pp 18867 034 24X

 Fiche 50-263,83/05/23,8306150576
- 8305150584 NUREO/CR-3119 VO2
 NUCLEAR POWER SAFETY REPORTING SYSTEM Concept Description
 FINLAYSON F C Aerospace Corp FIN 8-8255 ATR-83(3818)-IN
 83/05/31 Division of Facility Operations 43pp Available a
 NRC 3 75 18854 321
- B30615059B NUREC-0910 R01
 NRC COMPREHENSIVE RECORDS DISPOSITION SCHEDULE

 * Division of Technical Information & Document Control 83/05/31
 147pp Available at NRC \$7 00 18867 062
- 8306150602 NUREQ/CR-2786
 BHR REFILL-MEFLOOD PROGRAM TASK 4 4 ~ CCFL/REFILL SYSTEM
 EFFECTS TEBTS (30 DEGREE SECTOR) EVALUATION OF ECCS MIXINO
 PHENOMENA
 FINDLAY.J A General Electric Co FIN B-3877 EPRI NP-2842
 83/05/31 Division of Accident Evaluation 69pp Available at
 NRC \$4 50 18854 249
- 0306150616 NUREO-0968 S02

 BAFETY EVALUATION REPORT RELATED TO THE CONSTRUCTION OF THE CLINCH RIVER BREEDER REACTOR PLANT Docket No. 50-537

 (U.S. Department of Energy, Tennessee Valley Authority And Project Nanagament Corporation)

 * Clinch River Breeder Reactor Program Office 83/05/31 19pp Available at NRC \$3.00 18854 231 24X Fichs 50-537.83/05/31, 8306150416
- 8306150619 NUREO/CR-3225

 DATA ANALYBIS OF THE LLNL HYDROGEN IONITER EYPERIMENTS

 ALTENBACH T J , DAVIS.B W , MARTIN.R W Lawrence Livermore
 Laboratory FIN A-0422 UCRL-53049 83/05/31 Division of
 Systems Integration (post 811005) 63pp Available at NRC \$4 30
 18854 \$64
- B306160009 Forwards S Hawley & H Bernard testimony.completing NRC testimony filing for Jul 1983 hearing MDDHEAD; P Hearing Branch 4 B3/06/14 FRYE.J H , BR10HT.G O , LUEBKE.E A Atomic Safety and Licensing Board Panel ip 18861 176 24X Fiche 50-142.B3/06/14.B306160009
- --8306160010 Testimony of SC Hawley explaining & clarifying analytical bases for conclusion in NUREO/CR-2079, "Analysis of Credible Accidents for Argonaut Reactors " Prof qualifications encl HAWLEY, S C NRC No Detailed Affiliation Given HAWLEY, B C Battalle Memorial Institute, Pacific Northwest Laboratory 83/06/14 20pp 18861 177 24X Fiche 50-142,83/06/14,8306180009
- --8306160017 Testimony of H Bernard explaining & clarifying bases & assumptions used in BER Section 14 re analysis of consequences of postulated accidents Prof qualifications encl
 BERNARD. H Standardization & Special Projects Branch 83/06/14
 14pp 18861 197 24X Fichs 50-142:83/06/14
- 8306160206 Advises recipients of comments on proposed rule re safety goal development program that two comments marked I received Comment docketed 830302 will be iA # Docketing & Services Branch 48FR10772 83/06/13 Docketing & Services Branch 1p 18861 359
- 8306:602:0 Comments on proposed rule re safety goals concerning evaluation plan for nuclear power plants Supports rule WERNER, Y.A. Energy, Dept of 48FR10772 005 83/06/08 CNJLK.9 J Office of the Secretary of the Commission 3pp 18861 267

- 8305160224 Package of three comments supporting proposed rule re safety goals development program, policy statement & evaluation plan RAME. P Westinghouse Electric Corp FARRAR, D L Commonwealth Edison Co EDELMAN, M Atomic Industrial Forum 48FR10772 B3/06/09 CMI(N,S J Office of the Secretary of the Commission 9pp 18961 241
- 8306160249 Suppl to application for amend to Licenses NPF-4 & NPF-7, providing Tech Specs for NUREG-0737. Item II B 1. "Reactor Vessel Head Vent " No add1 license amend for required SIEWART.W L. Virginia Electric & Power Co. 333A 83/06/09 DENTON H R. Office of Nuclear Reactor Regulation. Director CLARK.R A. Operating Reactors Branch 3. 2pp. 18861 211 24% Fiche 30-338, 83/06/09, 8306160249
- --8306160266 Tech Specs re NUREO-0737. Item II B 1. "Reactor Vessel Head Vent " Discussion of proposed Tech Spec change also encl + Virginia Electric & Power Co 83/06/09 lipp 18861 214 24x Fiche 30-338.83/06/09.8306160249
- 8305160277 Forwards synopsis of issues & Franklin Research Ctr draft technical evaluation rept re NUREG-0612, "Control of Heavy Loads, Phase I " W/o encis ADENSAM.E O Licensing Dranch 4 83/06/10 TUCKER, H B Duke Power Co 2pp 19872 170 24X Fiche 50~369.83/06/10.8306160277
- BJ06160284 Forwards Westinghouse Owners Group steam generator tube rupture (BOTR) emergency contingency guidance approved for high pressure version of emergency response guidaline set three SOTR guidalines ECA-7.8 & 9 provided SHEPPARD. J J Westinghouse Operating Plants Owners Oroup SHEPPARD. J Carolina Power & Light Co. 00-92 BJ70J/16 EIBENHUT.D Q Division of Licensing 4pp 18861 013
- 8306160310 Forwards final response to NUREG-0612, "Control of Heavy Loads at Nuclear Power Plants-Resolution of TAP A-36"
 Response includes analyses for loads handled over reactor vessel
 KEMPER.J S Philadelphia Electric Co 83/06/13 EISENHUT.D O Division of Licensing 126pp 18860 243 24X Fiche 30-352, 83/06/13,8306160310
- 8305160335 Forwards response to 830422 request for add) info re Criteria 2.10 & 11 of NUREG-0737. Item II B 3. "Post-Accident Sampling " Interim core damage estimate guidelines will be submitted by 830530 UNRIG.R C Florida Power & Light Co L-83-358 83/06/10 VARGA, S A Operating Reactors Branch 1 3pp 18861 171 24X Fiche 50-250.83/06/10.8306160335
- 8305160337 Comments on proposed rule 10CFR50 re NRC policy statement on severe accidents & proposed rule re safety goals development program UCS comments on proposed rules will be consolidated & filed in early Jul CURRAN. D. Harmon & Weiss 48FR16014-001-83/06/08-9TUCKY, S. Docketing & Gervices Branch 1p 18860-124
- 0306160347 Comments on NRC policy statement on evaluation plan for safety goals Supports statement Evaluation period should be extended beyond 2 yes Mechanism should be developed to allow public to assess progress
 BRADBURY: R D Stone & Webster Engineering Corp 4BFR10772 004
 B3/04/00 Docketing & Services Branch 3pp (8041 124
- B306160357 Forwards "Enrico Fermi Atomic Power Plant-Unit 2, Plant-Unique Analysis Rept for Torus Attached Piping & Suppression Chamber Penetrations "Submittal responds to B20526 thr & BER (NUMEO-0798) requirements TAUBER.H Detroit Edison Co EF2-63,929, 83/06/10 YOUNGBLOOD, IJ Licensing Branch i 2pp 18858 247 24X Fiche 30-041,83/06/10,8306160037
- --8306160366 DET-17-076-6 ROD
 Rav Q to "Enrico Fermi Atomic Power Plant,Unit 2,
 Plant-Unique Analysis Rept for Turus Attached Piping &
 Suppression Chamber Penetrations "
 HiogNNDTHAMA A. YOUHIDA:D K. NUTECH Engineers, Inc. 83/06/30
 192pp 18858 249 24X Fiche 50-341.83/06/10.8306160357
- 8306i60401 Package of two comments on NRC policy statement on evaluation plans for safety goals for nuclear power plant appraction BLAND.H M System Bafety Society CASTERLINO.R G Affiliation Uninown 4BFR10772, 83706/06 CHILK.B J Office of the Secretary of the Commission 7pp 18860 108
- B306160493 Forwards "Bounding Analytical Assessment of NUREO-0630 Models on LOCA MM/ft Limits," reflecting use of FLECBET heat transfer correlation as compensating model to reduce impact of NUREO-0630 models
 MARSHALL.J R Arkansas Power & Light Co 1CANO68301 B3/06/08 BT0LZ.J F Operating Reactors Branch 4 ip 18862 083 24x Fiche 50-313.83/06/08.8306160493

- --8306160497 77-1143707-00
 "Bounding Analytical Assessment of NUREQ-0630 Models on LOCA
 kW/ft Limits"
 * Babrock & Wilcor Co 83/06/08 20pp 18862 085 24X
 Fiche 50-313,83/06/08,8306160493
- B306160500 Advises that procedures indicating shutdown cooling relief valves armed by manually opening shutdown cooling systisolation valves will be utilized until openable low temp overpressure alarm available.per NUREG-0857. Suppl 1 VAN BRUNT.E E Arizona Public Service Co ANPP-24058-WFG/83706/13 KNIGHTON, 0 Licensing Branch 3 lp 18864 156 24X Fiche 50-528.83/06/13.8306160500
- 8306160837 Responds to 821025 IE Insp Repts 50-313/82-14 & 50-368/82-11, Item 8 re control room dose calculations item re NUREO-0737, Item 11 B 2, "Plant Shielding," closed MARSHALL J R Arkansas Power & Light Co BCAN038301 83/03/24 COLLINS. J T Region 4, Office of Director 2pp 18863 115 24X Fiche 50-313,83/03/24,8306160537
- 8306160630 Forwards draft "Control of Heavy Loads at Nuclear Power Plants.St Lucie Plant; Unit 2 (Phase I)" & synopsis of NRC interpretation of guidelines of NUREG-0612 for use in resolving open items
 KNIGHTON: 0 W Licansing Branch 3 TAC 47015 93/05/31 UMRIO, R E Florida Power & Light Co 14pp 18884 283 24X
 Fichs 50-389,83/05/31,8306160630
- --8306160641 E00-H8-6263 DRFT

 Draft "Control of Heavy Loads at Nuclear Power Plants, St
 Lucie Plant, Unit 2 (Phase 1)," technical evaluation rept
 SHABER, C R E080, Inc FIN A-6457 TAC 47015 83/04/30 NRC
 -- No Datailed Affiliation Given 16pp 18894 297 24X
 Fiche 50-389,83/05/31,8306160630
- 8306160665 NUREG-0422 807
 SAFETY EVALUATION REPORT RELATED TO OPERATION OF MCGUIRE NUCLEAR STATION.UNITS | AND 2 Docket Nos 30-369 And 50-370 (Duke Power Company)
 * Division of Licensing 83/05/31 100pp 18876 164 24X Fichs 30-369.83/05/31.8306160665
- 8306170053 Concurs w/findings contained in technical evaluation rept, "Control of Heavy Loads" Quidelines in NUREO-0612.8ection 5 i 1 satisfied.per util 810402.0715.0831 & 1209.820203 & 1108 \$ 330408 submittals CLARK.R A Deprating Reactors Branch 3 83/06/06 MUSDLF,D M Northern States Power Co 2pp 18706 314 24X Fichs 50-282.83/06/06.8306170033
- --8306170058 Safety evaluation supporting util Phase I actions recontrol of heavy loads NUREO-0612. Section 5 1 1 guidelines satisfied

 * Office of Nuclear Reactor Regulation, Director 83/06/06 1p. 18906 316 24X Fiche 50-282.83/06/06.8306170053
- --8303230021 TER-C5506-384/385
 "Gontrol of Heavy Loads (C-iO), Prairis Island Nuclear
 Generating Phant, Units 1 & 2," technical avaluation rept
 VOSBURY, F W Franklin Institute/Franklin Research Center,
 NRC-03-81-130 TAC 08075 83/05/17 NRC No Detailed
 Affiliation Given 31pp 66794 188 24X Fiche 50-282,83/06/06,
 8306170053
- 8306170202 Forwards add1 Info to justify 820701 10CFR50 48 & App R schedule exemption requests discussed at 830330 meeting Plan being developed to complete maint & design changes W/two oversize drawings Aperture cards available in FDR OUCHALL Toeorgis Power Co IEB-79-01B 83/06/14 STGLZ, J.F. Operating Reactors Branch 4 App 18882, 277 24% Fichs, 59-321, 83/06/14, 8306170202
- 8305170263 NUREG/CP-0044 VOI
 PROCEEDINGS OF THE INTERNATIONAL ATOMIC ENERGY AGENCY
 SPECIALISTS' MESTING ON SUBGRIFICAL CRACK OROMTH. Sessions 1
 And II Held At Freiburg, Federal Republic Of Germany, May
 13-13,1981
 CULLEN, H H Materials Engineering Associates, Inc. # ENSA. Inc
 FIN N-8133 MEA-2014 83/05/91 Division of Engineering
 Technology 328pp 18907 001
- 8306/7028/ Advises that 821227 commitment to complete installation & testing of post-accident sampling sys per NUREO-0737. Item II B 3 by 83060/ has been met Final procedures for sys will be complete by 83070/ BTEWART. H L. Virginia Electric & Power Co 332 83/06/14. BENTON. H R Office of Nuclear Reactor Regulation, Director EISENHUT. B. 2 Division of Licensing. 2pp 18877 023 24X Fichs. 50-280.83/06/14.8306/17028/

- 8306170302 Forwards App J to. Evaluation of Pressurized Thermal Shock Effects Due to Small Break LDCAs W/Loss of Feedwater for Pala Verde 1 & 2,2 & 3 Reactor Vessels "Rept applies to only Unit 1

 VAN BRUNT.E E Arizona Public Service Co ANPP-24608-WFG/
 83706/14 KNICHTON.G Licensing Branch 3 3pp 18878 197 24X Fiche 50-528.83/06/14,8306170302
- 8306170326 Forwards proposed amend to FSAR re CESSAR indine removal sys & responses to NRC 830422 ltr Proposed FSAR amend combined w/responses closes out sump pH issue in SER Bections 6.4 & 15.4.8 & TMI Item III D.3.4

 VAN BRUNTLE E Arizona Public Service Co ANPP-24059-WFG/83/06/13 KNIGHTON.0 Licensing Branch 3 Bpp 18879 040 24X Fiche 50-528.83/06/13,8306170326
- 8306170333 Comments on proposed rule re NRC policy statement on development program & evaluation of safety goals Supports statement TAYLOR/J J Electric Power Research Institute 45FR10772 008 83/06/i3 Docketing & Services Branch 12pp 18880 054
- 8306170334 Package of five comments on proposed rule re plan to evaluate safety goal policy statement REYNOLUSAN S , MCGARRYJ M Debevoise & Liberman FISHER.C R G, Technologies, Inc /General Atomic Co 48FR10772 83/06/13 C
- 8306170408 Documents commitment to administratively impose temporary restrictions on plant operating LDCA limits as result of NUREQ-0630, per 830608 telcon Review of FLFCSET data requested MARSHALL.JR Arkansas Power & Light Co 1CAN068309 83/06/10 870LZ.JF Operating Reactors Branch 4 3pp 18879 022 24X Fiche 50-313.83/05/10.8306170408
- B306170449 Forwards NRC rapt on AOs at licensed nuclear facilities (NUREG-0090; Vol. 5, Number 4), for Fourth Quarter CY82 H/o sncl AHEARNE, J. F. Commissioners B3/06/02 O'NEILL, T.P. House of Rep BUSH, Q. H. Senata . 3pp 18907 322
- --8306/70451 Forwards FR notice & ltr forwarding AO rept to Congress (NUREG-0070, Vol 5, Number 4) Medical misadministration event discussed in SECY-83-92, upgraded to App C Item M/a encis
 DIRCKS.W J Office of the Executive Director for Operations 83/06/02 CHILK.S J Office of the Secretary of the Commission ip 18907 325
- 8306170452 Forwards Suppl 2 to SER (NUREG-096B) re const of facility Suppl provides evaluation of addl info received on praviously identified outstanding review items W/o ancl ORACE_J N Clinch River Breeder Reactor Program Office 83/06/13 LONGENECKER, J Energy, Dept of Clinch River Breeder Reactor Plant 2pp 16894 303 24x Fiche 50-537.83/06/13,8306170452
- 8306170471 Forwards evaluation of BMR Cuners Group generic response to NUREO-0737. Item II K 3.18 "Automic Depressurization Sys Logic Mods " Two of seven alternatives acceptable Che alternative should be chosen for facility mod STCLZ. J F Operating Reactors Branch 4 E3/06/03 BAUER, E Q Philadelphia Electric Co 9pp 18894 338 24X Fiche 50-277, 83/06/03, 8306170471
- 830620001B Notification of 830624 meeting w/util in Bethesda,NO to discuss & schedule multi-plant actions.NuREG-0737 & plant-specific open items
 REGUA,G Operating Reactors Branch 1 83/06/14 VARGA,S A Operating Reactors Branch 1 3pp 18709 121 24X
 Fichs 50-241.83/06/14.8306200018
- 8306200059 Advises that NUREO-0737. Items II F 1 4.11 F 1 5 & II F 1 6 requirements resolved per 801219. 820726 & 830408 submittals Environ qualification of equipment will be reviewed separately. SER encl 8 FOLICY F Operating Reactors Branch 4 CLARK.R A Operating Reactors Branch 3 83/06/06 GRIFFIN.J M Arkansas Power & Light Go 7pp 18708 302 24% Fiche 50-313.83/06/06.8306200059
- B306200069 Responds to 830414 memo requesting decision under NRC

 olicy to need to perform review of
 am Review of plant should be consistent
 tow
 refitation & Special Projects Branch B3/06/14
 Assurance 1p, 18908 173 24X
 14.8306200069

- 8304200102 Submits schedule for resolution of TMI Action Plan [tem II K 3 5 "Automatic Trip of Reactor Coolant Pumps." in response to Generic Ltr 83-10D Pump trip setpoint procedures will be implemented by end of 1985 refuel outage GIESLER.C W Misconsin Public Service Corp QL-83-10D 83/06/19 EISENHUT.D Q Division of Licensing 4pp 18903 330 24X Fiche 50-305,83/06/15.8306200102
- 8306200108 Informs of change in design of control room ventilation sys smoke detection to isolation sys to upgrade control room ventilation sys to satisfy NUREG-0737.

 Item III D 3 4 requirements
 MUSDLF, D Noithern States Power Co 83/06/13 Office of Nuclear Reactor Regulation, Director 1p 18703 238 24X
 Fiche 50~263,83/06/13.8306200108
- 8306200119 Minutes of ACRS ECCS Subcommittee 830512 meeting in Washington, DC re proposed GE SAFER/GESTR ECCS licensing codes & status of other NRR licensing actions Schedules for completing Unresolved Safety Issues A-43 & A-1 encl

 * ACRS Advisory Committee on Reacton Safeguards 83/05/12
 ACRS Advisory Committee on Reactor Safeguards 29pp 18908 239
- 8306200169 Comments on NUREG-0963, Items 10 6 2 c & 10 6 2 d re waste mpt research program. In view of NRC request for clarification of ACRS recommendations per 830427 meeting Recommendations appropriate FOSTER, R F FOSTER, R F ACRS Advisory Committee on Reactor Safeguards 83/05/02 MORLLER, D . TANG, R C ACRS Advisory Committee on Reactor Safeguards 2pp 18707 124
- 8306200204 Submits steps taken to satisfy Items 1 C % 3 of License NFF-13 re control room envelope leak tightness tast Control room inleakage reduced Allowable inleakage increased & analysis performed verifying SRP (NUREC-0800) conformance DALE,L F Mississippi Power & Light Co AECM-83/0333 83/06/16, 058NTON:H R Office of Nuclear Reactor Regulation, Director App 18903 236 24% Fiche 50-416,83/06/16,8306200204
- B306200246 For Mards list of procedures reviewed, changed if appropriate & typical examples of controls that exist to assure equipment returned to svc. per NUREG-0606, Suppl 1 HUKILL: HD General Public Utilities GPU Service Corp 5211-63-090 63/06/01 Region 1. Office of Director 15pp 18901 187 24X Fiche 50-289, 83/06/01, 8306200246
- 8305200260 Informs of further delay in implementing post-TMI-related issues due to delay in shipment of auxiliary safety instrumentation panels from vendor, in response to 830314 order FAY.C W Wisconsin Electric Power Co 83/06/16 DENTON, H R Office of Nuclear Reactor Regulation, Director CLARK, R A Operating Reactors Branch 3 App 18901 173 24X Fiche 50-266, 83/06/16, 8306200260
- 8304200409 Forwards "Emergency Response Facilities Design Rept." per NUREO-0737, Suppl 1, in response to Generic Ltr 82-33 WULLER, G E Illinois Power Co U-0643 83/06/16 SCHWENCER, A Licensing Branch 2 1p 18904 325 24X Fiche 50-461, 83/06/16. 8306200409
- --8306200414 "Emergency Response Facilities Design Rept"

 * Illinois Power Co U-0643 83/06/16 38pp 18904 326 24%
 Fiche 30-461.83/06/16.8306200409
- 8306200427 Forwards Suppl 4 to SER. NUREG-0831 W/o encl SCHWENCER. A Licensing Branch 2 83/06/13 MCGAUGHY, J P Mississippi Power & Light Co App 18920 019 24X Fiche 50-416, 83/06/13, 8306200429
- 8306210025 Forwards GA Program Insp Rept 99900060/83-01 on 830314-18 No noncompliance noted POTAPOUSLU Region 4, Office of Director 83/05/27 PATTARINI, D N Farget Rock Corp 2pp t8911 249
- **-8306210031 @A Program Insp Rept 97900060/83-01 on 830314-18 No noncompliance noted Major areas inspected TVA Part 21 rept on safety relief valve failure at Browns Ferry Unit 2 KELLEY.W D , BARNES, I Region 4, Office of Director 83/05/26
- B306210058 Interim deficiency rept for Item 8-11 re inadequacy of structural steel bolting program to assure compliance widesign spec & FSAR criteria Initially reported on B30513 Followup rept expected by B30712 WILLIAMS, J. Cincinnati Gas & Electric Co. 10CFR 050 55E 83/06/10 KEPPLER, J. G. Region 3, Office of Director 2pp 18711 224 24% Fiche 50-358,83/06/10,8306210058

- 6305210073 Supple 830513 ltr re NUREC-0737, Item II F i 5, "Containment Mater Level Monitoring Sys " Lower value of transmitter error should be used for calculating of overall loop uncertainties
 - uncertainties LENTINE,F G Communwealth Edison Co 6743N 83/06/15 DENTON,H R Office of Nuclear Reactor Regulation. Director 1p 18912 291 24x Fiche 50-295,83/06/15,8306210073
- 8306210144 Suppls B21012 & B30510 responses to NUREG-0737, Item II B 3, "Post-Accident Sampling Sys ' Commitment to Criterion 9(b) re background radiation levels fulfills item requirement BAYNE, J P Rower Authority of the State of New York IPN-03-63 B3/06/17 EISEN/UT, D G Division of Elecaning App 18914 092 24x Fiche 50-286, B3/06/17, B306210144
- 8304210158 Forwards order confirming commitment to implement post-TMIrelated Items II B 3. "Post-Accident Sampling" & II E 4 2 7, "Isolate Purge & Vent Valves on Radiation Signal" CRUICHFIELD.D Operating Reactors Branch 5 LS05-83-06-039 83/06/17 FIELDER.P B General Public Utilities ~ GPU Service Corp Jpp 18916 392 24X Fiche 50-219.83/06/17.8306210158
- --8306210166 Order confirming licenses commitments on post-TMI-related Items II D 3. "Post Accident Sampling" & II E 4 2, "Isolate Purgs & Vent Valves on Radiation Signal"

 EIBENNUT, D 6 Division of Licensing GL-82-05 B3/06/17

 General Public Utilities GPU Service Corp 8pp 18916 355 24X

 Fichs 50-219,83706/17,8306210158
- 8306210287 Forwards program plan issues & areas for outstanding items re NUREG-0737. Item 1 D 1 re detailed control room dusign review per NUREG-0700 requirements & SER. NUREG-0857 Generic Ltr 82-33 issues addressed UAN BRUNT.E E Artrona Public Service Co GL-82-33 83/06/17 MICGITON.G Licewsing Branch 3 36pp 18914 038 24X Fichs 50-528.83/06/17.8306210287
- 8304210294 Interim deficiency rept. Item S-9 re soil structure compaction outside power area not per design spec & FSAR criteria initially reported on 830513 All safety-related structures & sys will be identified WILLIAMS, J Clincinnati Gas & Electric Co 100FR 050 555 B3/06/13 KEPPLER, J G Region 3, Office of Director 2pp 18915 147 24% Fiche 50-358, 83/06/13, 8306210294
- 8706210317 NUMERO-0982

 SAFETY EVALUATION REPORT RELATED TO RENEWAL OF THE OPERATINO LICENSE FOR THE RESEARCH REACTOR AT THE STATE UNIVERSITY OF NEW YORK AT BUFFALD Docket No 50-57

 Biviaion of Licensing 83/03/31 83pp Available at NRC 44 50 13924 282 24X Fiche 30-057,83/05/31,8306210317
- 6305210324 NUREG/CR-2044
 REACTOR OPERATING EXPERIENCES 1978 1980
 MAY9, 0 T. WINTON, M L. Oak Ridge National Laboratory FIN A-9135
 GRNL/NBIC-194 B3/05/31 Director's Office ip Available at
 NRC 46 00 18922 001
- 8306210331 NUREG-0831 S04
 SAFETY EVALUATION REPORT RELATED TO THE OPERATION OF GRAND GULF NUCLEAR STATION.UNITG 1 & 2 Dacket Nos 50-416 & 50-417 (Mississippi Power And Light Company)

 Division of Licensing 83/05/31 136pp Available at NRC 45 50 18742 177 24X Fiche 50-416.83/05/31.8306210331
- 8305210340 Responds to FOIA request for names & locations of various nuclear facilities licensed by NRC Forwards NUREO-0871.
 "Bummary Info Rept" W/o encl
 FELTON.JM Division of Rules and Records 83/04/08 THOMAS, D M
 Overseas Packing, Inc 10 18921 330
- 8306210350 NVREO/CR-3287
 A GUIDE FOR THE TACT III COMPUTER CODE Final Report
 KILLOUGH, 0 0 , BEGOVICH, C L , SJORECN, A L Oak Ridge National
 taboratory FIN D-0774 ORNL/IM-8763 83/09/31 Division of
 Systems integration (post Bil005) 290pp Available at NRC \$7 00
 10724 001
- B306210354 NUREO-0972
 REPORT OF THE COMMITTEE TO REVIEW BAIFGUARDS REQUIREMENTS
 AT POHER REACTORS
 HAYKEB,R C . DURNETT,R F , MIRAGLIA.F J Safety/Safeguards Review
 Group B3/05/31 184 Available at NRC \$6.00 18925 008
- B306210362 MUREG-0939
 EXAMPLE CALCULATIONS ILLUSTRATING METHODS FOR ANALYZING
 SUCTILE FLAW STABILITY IN NUCLEAR PRESSURE VESSELS
 MERKLE, J G , JOHNSON, R E Division of Safety Technology 83/05/31
 2109 Available at NRC \$3 50 18937 293

- 9306210378 NUREQ-0882 801
 SAFETY EVALUATION REPORT RELATED TO THE RENEWAL OF THE OPERATING LICENSE FOR THE RESEARCH REACTOR AT THE ARMED FORCES RADIOBIOLOGY RESEARCH INSTITUTE DOCKET No. 50-170
 * Division of Licensing 83/05/31 lipp Available at NRC \$3 00 18937 261 24X Fichs 50-170.83/05/31.8306210378
- B306210383 NUREO-0606 V05 NO2 UNRESOLVED SAFETY ISSUES SUMMARY Data As Of May 27,1783 (Aqua Book) * Management information Branch 83/06/30 49pp 18735 233
- 8306210401 NUREG-0020 V07 N02 LICENSED DPERATING REACTORS STATUS SUMMARY REPORT Data As Of January 31, 1931 (Grey Book) * Management Information Branch 83/06/30 391pp 18934 199
- 8306210433 Comments on Class 7 Accidents Subcommittee 830425 & 26 meetings NUREO-0900 fails to answer how regulatory needs for degraded core accidents could be mot by severe accident research plan LEE.J C Michigan, Univ of LEE.J C ACRS Advisory Committee on Reactor Safeguards 83/05/05 MANG.A ACRS Advisory Committee on Reactor Safeguards 2pp 18935 338
- B306210463 Forwards comments on draft AD rept to Congress for First Quarter CYG3 Comments in B30415 memo adequately addressed. Subj to resolution of comments concurs w/proposed Commission paper DENTON.H R Office of Nuclear Reactor Regulation. Director B3/04/07 HELTEMES.C J Director's Office 3pp. 18925 327
- --8306020498 Forwards draft Commission paper re AC rept to Congress for First Guarter CYB3 based on NRC response to AEOD 83031B mamo, for review.comments & concurrence HELTEMES, C J Director's Office 83/08/17 DENTON, H R Office of Nuclear Reactor Regulation, Director 46pp 18926 001
- 8304220005 Documents 830404 telcon re util 830209 response to NUREO-0737. Item II E I 2: "Auxiliary Feedwater Bys Automatic Initiation & Flow Indication " Bypass signals do not block indicator, annunciator or reactor trip signals ZIMMERMAN. 9 R Carolina Power & Light Co LAP-83-228 83/06/17 VAR9A.8 A Operating Reactors Sranch 1 2pp 18927 360 24X Fiche 50-261,83/06/17,8306220005
- 8306220033 Application to amend Licenses DPR-32 & DPR-37, changing Tech Bpecs by adding add1 accident monitoring instrumentation & reactor vessel head vents per NUREO-0737. Items II F 1 & II B irrespectively gareMART. W. L. Virginia Electric & Power Co 330 83/06/16 DENTON: H. P. Deflice of Nuclear Reactor Regulation, Director VARGA: B A Degrating Reactors Dranch 1 3pp 18727 233. 24X Fiche 30-280:83/06/16.8306220033
- --8306220047 Proposed Tech Specs adding add1 accident monitoring instrumentation & reactor vessel head vents, per NUREG-0737. Items II F I & II B 1, respectively * Virginia Electric & Power Co B3/06/14 23pp 18927 237 24X Fiche 50-280, 83/06/16, 8306220033
- 9306220040 Notifies of error in 930506 ltr re containment instrumentation upgrades per NUREO-0737. Items. II F 1 4. II F 1 9 & II F 1 6 Existing instrument display is indicator not recorder RODRIGUEZ.R J. Secremento Municipal Utility District RJR 83-504 83706/17 BTOLZ. J F. Operating Reactors Branch 4 2pp 18728 208 24X Fiche 50-312.83/06/17.8306220040
- 8306220049 Forwards Vols 3 & 4 to "Environ Qualification of Class IE Equipment" Data combined \(\text{W/830520} \) response to NRC 830111 SER, provides complete response to NURCG-0388; IE Bulletin 79-018 & recently published rule 10CFR50 49 MESTAFER: G R Fiorida Power Corp 3F-0883-07 83/06/15 STGLZ.J F Operating Reactors Branch 4 2pp 18928 231 24X Fiche 50-302,83/06/15,8306220049
- 8306220074 Forwards safety evaluation & technical evaluation rept re util response to 801222 generic ltr. "Control of Heavy Loads " Guidelines in NUREG-0612 satisfied & Phase acceptable CRUTCHFIELD, D Eperating Reactors Branch 5 LSG5-83-04-045 83/06/21 FIEDLER, P B General Public Utilities GPU Service Corp 2pp 18926-060 24X Fiche 50-219,83/06/21,8306220074
- --8306220083 Safety evaluation re util response to Generic Technical Issue A-36. "Control of Heavy Loads " NUREG-0612 guidelines satisfied Phase 1 acceptable " Office of Nuclear Reactor Regulation, Director. 83/06/21 2pp 18926 062 24X Fichs: 50-219:83/06/21:8306220074.

- --8306140424 TER-C5506-377

 "Control of Heavy Loads (C-10).JCP&L Dyster Creek Nuclear Power Plant," technical evaluation rept 80MBERGER, C Frantiin Institute/Franklin Research Center NRC-03-81-130 TAC 47128 83/06/10 SINOH, A NRC No Detailed Affiliation Given 32pp 18726-064 24X Fiche 50-219.83/06/25, 8306220074
- 8306220075 Clarifies info provided in 830502 ltr re NUREQ-0737, Item II 8 3 "Post-Accident Sampling Sys (PASS)," per 830526 request Equipment ordered to allow powering of analyzer & solenoid valves from reliable source within 3 h RODRIGUEZ,R J Sacramento Municipal Utility District ROR-83-512 83/06/17 SYGLZ,J F Operating Reactors Branch 4 bpp 18930 16-24x Fiche 50-312,83/06/17,8306220075
- 8306220087 Forwards description of program approved by Westinghouse Owners Group to address NUREG-0737. Item II 8 3 to post-accident core damage assessment, per 830420 meeting Project to be completed by end of yr SHEPPARD. J J Westinghouse Operating Plants Dwners Group SHEPPARD. J J Carolina Power & Light Co 83/06/16 NORRIS. J A Operating Reactors Branch 1 70p 18926 203
- 8306220098 Forwards Suppl 2 to SER (NUREG-0881) W/o encl YOUNG9LOOD, B J Licensing Branch 1 83/06/16 KOESTER, G L Kansas Gas & Electric Co 2pp. 18977 346 24% Fiche 50-482, 83/06/16, p30423089
- 8306220198 Forwards Vol 5.Number 4 to NUREG-0090, "Rept to Congress on AOs:" for Fourth Guarter CV82 One AO reported at NRC licensees re inoperability of containment spray sys Agreement states reported no AOs AHEARNE.J F Commissioners 83/06/02 D'NEILL.T P House of Rep 2pp 18940 024 24X Fiche 50-000.83/06/02.8306220198
- 8306220219 Presents alternatives to automatic depressurization syslogic to eliminate need for manual actuation for core coverage per TMI Item FI. K 18 implementation schedule & proposed Tech Specs requested within 45 days of itr receipt STOLZ, J.F. Operating Reactors Branch 4 83/06/03 BECKHAM. J.T. Georgia Power Co. 2pp 18951 001 24X Fiche 50-321,83/06/03, 8306220219
- 830622024 Forwards draft tables reflecting status of NUREO-0752, NUREG-0737, NUREO-0680 & NUREO-0746 restart certification items Meeting proposed for 8306/4 to discuss status of items listed in encl STOLZ, J F Operating Reactors Branch 4 83/06/09 HUKILL, H D Genaral Public Utilities GPU Service Corp 35pp 18950 312 24X Fiche 50-289, 93/06/09, 9306220224
- 8306220245 NUREO/CP-0043 ERR
 PROCEEDINGS OF THE JOINT NRC/ANS MEETING ON SASIC THERMAL
 HYDRAULIC MECHANISHS IN LWR ANALYSIS Held At Bethesda,
 Maryland, September 14-15, 1982
 * American Nuclear Society 83/06/02 Office of Nuclear
 Regulatory Research, Director 43pp. 18931 073
- 8306220275 Informs that 830310 proposed wide-range hot leg level/ reactor vessel head monitoring satisfactory Evaluation & addl info request re conformance of addl inadequate core cooling instrumentation sys components to NOREO-0737.encl STOLZ, J.F. Operating Reactors Branch 4 83/06/09 TUCKER.H B Duke Power Co. 10pp 18977 155 24X Fichs 50-269.83/06/09, 8306220275
- 8306230047 Forwards safety evaluation of emergency response guidelines Ouidelines acceptable for implementation & will provide improved guidance for emergency operating procedure development Response schedule requested within 90 days EISENMUT, D 0 Division of Licensing 83/06/01 SHEPPARD, J J Hestinghouse Operating Plants Owners Group 2pp 18982 109
- --830A230052 Safety evaluation re Westinghouse Owners Group generic emergency guidelines for mitigating transients & accidents, per NURSG-0737, item I.C. 1

 a Office of Nuclear Reactor Regulation, Director 83/06/01
- 8306230087 Interim deficiency rept re Item M-87, inadequacy of design control process to assure design output documents contain adequate erection & insp criteria. Initially reported on 830913, item not reportable under 10CFR00 55(e)
 HILLIAMS, J Cincinnati Gas & Electric Co. 10CFR 050 55E 83/06/15
 KEPPLER, J G Region 3, Office of Director 2pp 18947 074 24X
 Fiche 50-358, 83/06/15, 8306230089
- 8306230195 Forwards IE Insp Rept 30-244/83-11 on 830502-06 No noncompliance noted 8TAROSTECKIR Division of Project & Resident Programs 83/06/08 MAIER, J E Rochester Cas & Electric Corp. 2pp 18746 352 24X Fiche 50-244,83/06/08,8306230195

- --8306230199 IE Insp Rept 50-244/83-11 on 830902-06 No noncompliance noted Major areas inspected actions taken to comply w/ NUREO-0737. Item II 8 2 re design review of plant shielding BAUNACK. H H, EAPEN.P K Region 1. Office of Director KISTER.H 8 Division of Project 2 Resident Programs 83/06/07 7pp 18946 354 24X Fiche 50-244.83/06/08.8306230195
- 8306230203 Forwards IE Insp Rept 50-247/83-12 on 830503-31 No noncompliance noted 8TARGSTECKI.R Division of Project & Resident Programs 03/06/10 0/1006.5 J D Consolidated Edison Co of New York. Inc 2pp 18745 283 24X Fiche 50-247.83/06/10.8306230203
- --8306230212 IE losp Rept 50-247/83-12 on 830503-31 No noncompliance noted Major areas inspected licensee action on previously identified insp findings, facility operations review.plant trips, TMI action items & surveillance FOLEY, f Region I. Office of Director GL-82-12 83/06/0/14pp 18945 285 24X Fiche 30-247,83/06/10,8306230203
- B306230259 Forwards Rev O to "Detailed Control Room Design Review (DGRDR) Program Plan for Davis Besse Nuclear Power Plant: "in response to NRC B21217 ltr & commitments per util 830415 ltr CROUSE, R P Toledo Edison Co 959 B3/06/15 STOLZ, J F Operating Reactors Branch 4 lp 18945 021 24% Fiche 50-346, 83/06/15, 8306230259
- --8306230262 Rev O to "Detailed Control Room Design Review (DCRDR) Program Plan for Davis Besse Nuclear Power Plant " * Taledo Edison Ca 83/06/15 50pp 18945 022 24X Fiche 50-346,83/06/15,8306230259
- 8306230276 Responds to NRC 830523 request for proposed resolution to TMI Item II K 3 18. "Mod of Automatic Depressurization Systogic" Justification for bypass timer setting will be provided prior to implementation of mod KEMPER.J S Philadelphia Electric Co 83/06/20 SCHMENCER.A Licensing Branch 2 Spp 18945 135 24X Fiche 50-352.83/06/20, 8306230276
- 8306230342 Comments on proposed rule re safety goal development program SCHERER.A E Combustion Engineering. Inc. 48FR10772 016 (3706/1) Docketing & Services Branch 2pp. 18943 059
- B304230407 Comments on proposed rule re NRC policy statement on safety goals Policy inadequate for dealing w/safety problems PURPY.0 J Affiliation Unknown 48FR10772 017 83/06/16 MRC No Detailed Affiliation Oiven 2pp 16943 203
- B306230413 Supplements B30202 itr discussing alternative to automatic isolation of V-79 exhaust sys when radiation detected, per NUREG-0737, Item II F 1 Explenation of why alternatives to progressed mod investigated discussed JOHNSON B D Consumers Power Co 83/06/17 KEPPLER, J O Region) Office of Director 3pp 18941 340 24X Fiche 50-255,83/06/17. B306230413
- 8306230428 Advises recipients of comments on preposed rule re safety goal development program that two comments both numbered 7 received Comment docketed 830613 will be 14 e Docketing & Services Branch 48/R10772 83/06/21 Docketing & Services Branch 1p 18943 232
- 8306230432 Advises recipients of comments on proposed rule re-safety goal development program that two comments both numbered 6 received Comment docketed 830613 will be 13 * Docketing & Services Branch 48FR10772 83/06/21 Docketing & Services Branch 1p 18941 339
- B306230433 Advises recipients of comments on proposed rule re-safriy goal development program that two comments both numbered 5 received Comment dockated B30613 will be 12 + Dockating & Services Branch 48FR10772 83/06/21 Dockating & Services Branch 1p 18942 076
- B306230434 Advises recipients of comments on proposed rule re-safety goal development program that two comments both numbered 4 received Comment docksted B30613 will be 11 + Docketing & Services Branch 4BFR10772 B3/06/21 Docketing & Services Branch ip 18943 242
- 8306230436 Advises recipients of comments on proposed rule related goal development program that two comments both numbered 3 received Comment docketed 830613 will be 10 ** Docketing & Services Branch 48FR10772 83/06/21 Docketing & Services Branch ip 18942 087

8305230437 Forwards Rev 3 to "Corporate Operations Manual Part IV-Functional Manuals Section I Nuclear QA Manual ' Revs reflect organizational changes & clurify items modified in Rev 2 to SRP (NUREG-0800) RAUSCH.W P Burns & Roe Co 63/06/09 HAASS,W P Quality Assurance Branch 1p 18944 023

8306230437 Advises recipients of comments on proposed rule re-safety goal development program that two separate comments both indicate number 8 Comment docketed 830615 will be 15 # Docketing & Services Branch 49FR10772 83706721 Docketing Services Branch 1p 18944 022

8306230447 Responds to NRC 830603 & 10 tellon requests for addl infore NUREO-0737. Item II B 2, "Plant Shielding " District RJR 83-503 83/06/17 MARTIN. J & Region 5. Office of Director 4pp 18942 083 24% Fiche 50-312,83/06/17,8306230447

B306330452 Forwards revised response to NUREG-0612, "Control of Heavy Loads" Rev Addresses NRC comments contained in draft technical evaluation rept dtd B21123 & supplemented by NRC B21228 ltr
DEVINCENTIB, J Yankee Atomic Electric Co DEVINCENTIS, J Public Service Co of New Hampshire SBN-521 83/06/20 KN10HYON, G W Licensing Branch 3 2pp 18941 001 24X Fiche 50-443, 83/06/20, 8306230452

--8308230458 9763 006-5-N-5
"Response to NRC Generic Request for Addl Info Re
NREC-0612-Control of Heavy Loads"

** United Engineers & Constructors, Inc. (subs. of Raytheon Co.)
83/05/31 147pp 18941 004 24% Fiche 50-443,83/06/20,
8308230452

8306230474 Submits add1 info re radiation filtration sys for emergency control ctr (ECC), per NUREG-0737, Suppl 1 on emergency response Radiation filtration sys designed to be manually activated Sketch of ECC filtration sys encl MARBWALL, J. R. Arkansas Power & Light Co. OGANO68310 83/06/17 STOLZ, J. F. Operating Reactors Branch 4 3pp 18941 307 24X Fiche 30-313.83/06/17.8306230474

8308230517 NUREG 0750 VI6 NOI NUCLCAR REQULATORY COMMISSION ISSUANCES July 1782 • Division of Technical Information & Document Control 82/07/31 409p 18983 001

B306230521 Advises that mod of Model D2/D3 steam generators acceptable by modified steam generators can be operated at 100% of design capacity w/mod in place DIRCKS.W J Diffice of the Executive Director for Operations B3/06/14 PALLADINO.N J, GILINSKY.V, AHEARNE.J Commissioners 3pp 18991 39/ 24x Fiche 30-395.B3/06/14.B306230321

8305240004 Forwards vendor info rept. "Containment Water Level Monitoring," in response to 830415 request for additinfo re NUREO-0737, Items II F 1 4 & II F 1 5. "Containment Pressure Monitor" y "Containment Water Level Monitor" GODSONE, TC Consumers Power Co. 03/06/20 CRUTCHFIELD, D Operating Reactors Branch 5 16pp 18901 293 24X Fiche 50-155,83/06/20,8306240004

8305240048 NUREG-0580 VI2 NO5 REGULATORY LICENBING STATUS SUMMARY REPORT Data As OF May 31:1783 (Blue Book) * Management Information Branch 83/06/30 67pp 18986 352

8306240050 NUREO/CR-3047
CLOSEOUT OF LE INULETIN 80-16 POYENTIAL MISAPPLICATION OF
ROSEMOUNT PRESSURE TRANSMITTERS
OFAN,R S . FOLEY,W J . HENNICK,A Parameter. Inc. FIN 8-1013
PARAMETER IC-12 83/06/30 Division of Emergency Preparedness
(Pre 830103) 42pp Available at NRC \$3 75 (8986-307)

8305240052 NUREQ/CR-2640 EXERTMENT DEFRATION PLAN FOR THE TH-3 EXPERIMENT IN THE NRU REACTOR RUSSCHER, G E : WILSON, C L : PARCHEN, L J Battelle Memortal Institute, Pacific Northwest Laboratory FIN 8-2277 PNL-4232 63706/20 Division of Accident Evaluation 35pp Available at NRC 43 75 18986 272

8306240056 NUREG-0843 SO4

8AFETY EVALUATION REPORT RELATED TO THE OPERATION OF ST
LUCIE PLANT, NURT NO 2 Docket No 50-387 (Florida Power And
Light Company And Orlando Utilities Commission Of The City
Of Orlando-Florida)

• Division of Licensing 83/06/30 Répp 18986 245 24X
Fiche 50-387, 83/06/30, 8306240036

B306240058 NUREG/CR-3234
LICENSEC PROGRAMS FOR MAINTAINING OCCUPATIONAL EXPOSURE TO
RADIATION AS LOW AS IS REASONABLY ACHTEVABLE
MUNSON.L H Battelle Memorial Institute, Pacific Northwest
Laboratory FIN D-2427 PNL-4683 83/06/30 Division of
Facility Operations 39pp Available at NRC \$3.75 18986 203

8306240060 NUREG-0856
FINAL TECHNICAL POSITION ON DOCUMENTATION OF COMPUTER CODES
FOR HIGH-LEVEL WASTE MANAGEMENT
SILLING S A Division of Haste Management 83/06/30 20pp
Available at NRC \$3.00 (6986-192

8306240062 NUREG/CR-3274
FAT10UE CRACK GROWTH RATES OF A 508-2 STEEL IN PRESSURITED,
HIGH TEMPERATURE WATER
CULLEN-W H Haterials Engineering Associates, Inc. * ENBA, Inc.
FIN 8-8133 MEA-2016 93/06/30 Division of Engineering
Technology 35pp Available at NRC 43 75 18986 148

8306240043 NUREG-0986
RCSCKB REACTOR CODLANT SYSTEM LEAK RATE DETERMINATION FOR
PURE Vier's Quide
KIRKPATRICK, 0 . HODDRUFF, R W Division of Emergency Pregaredness
(Pre 830103) 83/06/30 103pp Available at NRC 84 75.
18786 045

8306240064 Notifies that add1 info re list of safety-related items in FSAR Table 3 2-1 (QA-list) acceptable Outstanding Issue 23 in Suppl 3 to SER (NURSO-0807) will be changed to confirmatory issue per FSAR.Amend 12 review YOUNOBLOOD, B J Licensing Branch i 83/06/21 EDELMAN, M R Cleveland Electric Illuminating Co 2pp 18987 134 24% Fiche 30-440,83/06/21,8306240064

8306240070 Requests add1 info re moisture separators of heaters in filter sys serving nonaccessible area & fuel handling bldg for SER review Info requested within 30 days to maintain review schedule YOUNDELOOD, E. J. Licensing Branch | 83/06/21 FARRAR, D. L. Commonwealth Edison Go. 3pp. 18985-028 24X Fiche 50-000, 83/06/21, 8306240070

8306240073 NUREO/CR-3183
LOCA SIMULATION IN ARU PROGRAM THE CONTINUOUS MEASUREMENT
OF COGLANT LIQUID LEVEL DURING THE MY-4 EXPERIMENT IN THE
NRU REACTOR
HARBHALL,R K , MOHR,C L , MCDUFFIE,P N Battelle Memorial Institute,
Pacific Northwest Laboratory FIN 8-2277 PNL-7650 B3/06/30
Division of Accident Evaluation 32pp Available at NRC 63 75
18986 016

8306240078 NURCO/CR-3174
IMPROVED BENEFIT-COBY TECHNIQUES IN THE U S NUCLEAR
REQULATORY COMMISSION
CRONIN-F J , NESSE, R J , VAETH.M Battelle Memorial Institute,
Pactific Northwest Laboratory FIN 3-2381 PNL-4653 83/06/30
Office of Nuclear Regulatory Research, Director 109pp. Available
at NRC \$3 00 18983 247

8306240145 Application to amend License DPR-71, changing Tech Specs re snubber listings, drywell sump instrumentation numbers, remote ehvidous panel instrumentation numbers & installation of NUREO-0737 mods for startup HOME,P W Carolina Power & Light Co LAP-83-236 83/06/20 DENTON,H R Office of Nuclear Reactor Regulation, Director 2pp. 1898; 041 24% Fiche 50-325,83/06/20,8306240145

--8306240149 Revised Tech Spec re snubber listings, drywell sump instrumentation numbers, remote shutdown panel instrumentation numbers & installation of NUREQ-0737 mods for startup # Carolina Power & Light Co 83/06/20 44pp 18981 043 24X Fithe 30-329, 83/06/20,8306240143

8306240177 Responds to SEP Topic III-5 B, "Pips Break Dutside Containment " Installation of jet impingement shields to protect main steam safety & relief valves not needed, Itam resolved MAIER.J E Rochester Gas & Electric Corp 83/06/16 CRUTCHFIELD.D Operating Reactors Branch 5 Jpp 18981 030 24X Fichs 30-244,83/06/16,8306240177

B308240256 Requests reconsideration of denial of stemption request in SECY-83-197 re primary energency operations facility (EOF) Current EOF location found acceptable by Region V.FEHA & state & local gavts
HITHERS. B D Portland General Electric Co 83/06/17. DENTON, H R Office of Nuclear Reactor Regulation. Director 4pp 18981 315 24X Fichs 80-344.83/06/17.8306240256

8306240274 Forwards response to criteria for resolution of NUREG-0737, Item II K 3 5, "Automatic Trip of Reactor Coolant Pumps." stated in NRC 832080 Generic Ltr 83-10C Mestinghouse Owners Group program addressing criteria will be evaluated FUSTER.D 0 Georgia Power Co FUSTER.D 0 Southern Co Services. Inc GL-83-10C 83/06/16 ADRISAME 6 Licensing Branch 4 5pp 18980 126 24x Fiche 50-424,83/06/16.8306240274

B306240288 Requests add1 info to resolve SER Confirmatory Issue 10 re fast scram hydrodynamic loads on control rod drive sys Response within 7 days of ltr receipt requested YOUNOBLOOD B J Licensing Branch 1 83/06/21 EDELMAN.M R Cleveland Electric Illuminating Co 3pp fB997 167 24X Fiche 50-440.83/06/21.8306240288

8306240373 NUREG/CR-2954

306240973 NUREG/CR-2954
RADIOLOGICAL SURVEYS OF PROPERTIES CONTAMINATED BY RESIDUAL
RADIOACTIVE MATERIAL FROM URANIUM PROCESSING SITES
YOUNG!Y A . JACKSON.P O . THOMAS.W V Battalle Memorial Institute.
Pacific Northwest Laboratory FIN B-2216 PNL-4264 83/06/30
Division of Waste Management 142pp Available at NRC \$5 50
16985 031

8306240384 NUREO/CR-3296
A REVIEW OF THE CURRENT DEFICIENCIES IN PERSONNEL BETA
DOSIMETRY, WITH RECOMMENDATIONS
SHERBINI.S., PORTER.S W Porter Consultants, inc. FIN B-6
PCI-TR-224 83/03/31 Division of Facility Operations
Available at NRC \$4 50 18985 179 FIN B-8094

8306240413 NUREG/CR-3281 INVESTIGATION OF THE SHELL CRACKING ON THE STEAM GENERATORS OF INDIAN POINT NO 3 Docket No 50-286 (Consolidated Edison OF INDIAN POLYMENT AND STREET AND SOURCES (CONDAIN)
CIAJIKOMSKI,C Brookhaven National Laboratory FIN A-3400
BNL/NUREO-51670 83/06/30 Division of Engineering 51pp
Available at NRC \$4 00 18998 273 24X Fiche 50-286,83/06/30,8306240413

8306270008 IE Insp Findings & Licensee Ack dtd 830614 of License 34-15654-01 Insp findings 48 h dose calibrator linearity tests not performed per NUREG-0338.App D.Section 2 & wipe tests not performed on incoming partages * Region 3. Office of Director 83/06/14 1p 18988 137

8306270133 Forwards add1 info re NUREC-0737. Item II E 1 1. "Auxiliary Feedwater Sys Upgrade Review." per 830502 & 0603 ltrs.in response to NRC 820407 ltr Condensate storage tank not damaged by wind loads generated by 175 mph winds RODRIGUEZ.R J Sacramento Municipal Utility District RJR 83-507 83/06/21 STOLZ.J R Operating Reactors Branch 4 3pp 18788 01 24% Fiche 50-312.83/06/21.8306270133 18788 011

8306270141 NUREC/CR-2962
THERMALLY STINULATED CURRENT CHARACTERIZATION OF THE
DEGRADATION OF POLY (VINLY CHLORIDE) CABLE MATERIAL IN
RADIATION AND THERMAL ENVIRONMENT
KURTZ, S R Sandis Laboratories FIN A-1051 6AND82-2164
83/05/31 Division of Engineering Technology 23pp 16

B306270143 Forwards schedule for submittal of info required for NRC review of FSAR Schedule covers submittal of revised security plan & add1 CESGRR interface requirements VAN BRUNT.E E Artiona Public Service Co ANPP 24126-HFG/B3/06/20 KNIGHTON.0 Licensing Branch 3 8pp 18988 001 24) Fiche 50-526.83/06/20.8306270143

18999 320

8306270146 NUREG/CR-2809 VO4
AEROSOL RELEASE AND TRANSPORT PROGRAM GUARTERLY PROGRESS
REPORT FOR OCTOBER-DECEMBER 1982
ADAMS, R E., TOBIAS, M L. Argonne National Leburatory FIN BDRNL/TM-8397 83/03/31 Division of Accident Evaluation

8306270151 NUREO/CR-3156
A SURVEY OF BTATE-OF-THE-ART IN ADING OF ELECTRONICS WITH APPLICATION TO NUCLEAR POHER PLANT INSTRUMENTATION JOHNSON, R T , THOME, F J , CRAFT, C M Sandia Laboratories A-1051 BANDB2-2559 B3/03/31 Division of Engineering Technology 67pp, 19021 072

8306270157 NUREQ/CR-1599 JOSEPH PROPERTY FOR A STATE OF THE PROPERTY OF

8306270260 Forwards "Bounding Analytical Assessment of NUREO-0630 Models on LDCA tW/Ft Limits " RODRIGUEZ, R J Sacramento Municipal Utility District RJR 83-83706/20 STOLZ, J F. Operating Reactors Branch 4 2pp 1899 24% Fichs 50-312,83/06/20,8306270260 RJR 83-505 18990 231 8306270285 Clarifies capabilities of hydrogen ignition sys circumstances, per Schwencer 811106 ltr ½ NUREG/CR-2486 Under worst case conditions, min vallage required would be 10 08 volts sus under all DALE.L C Mississippi Power 5 Light Co AECM-83/03J9 83/06/23 DENTON.H R Office of Nuclear Reactor Regulation, Director 2pp 18976 196 24X Fiche 50-416.83/06/23.0306270285

8306270306 Response opposing State of NH 830526 objections to ASLB 830511 memorandum % order ruling on motions for summary disposition No mods to ASLB conclusions warrinted Certificate of Svc encl LESSY,R P · PATTERSON,W F Hearing Branch 3 ISSUANCES OL 83/06/22 Atomic Safety and Licensing Board Panel 11pp 18975 208 24X Fiche 50-443.83/06/22.6306270306

8306270312 Forwards info re reactor vessel level instrumentation sys. in response to Generic Ltr 82-28 concerning inadequate corp cooling instrumentation in-core thermocouple sys will be upgraded to NURGE-0-737, Item II F 2 requirements HERING.R F Indiana & Michigan Ejectric Co GL-82-28 83/06/22 EISENNUT.D Q Division of Licensing 19pp 18993-393 24% Fiche 50-315,83/06/22,8306270312

B306270322 Provides add1 details re control of heavy loads during const when new fuel assemblies being stored in spent fuel pit Due to failure of reautor coolant pump at Byron i fuel handling bldg crane will be installed TRAMM.TR Commonwealth Edison Co 6794N 83/06/17 DENTON.H R Office of Nuclear Reactor Regulation, Director ip 18994 0/3 24x Fiche 50-000.83/06/17.8306270322

8306270360 Forwards add1 info requested 83040/ re containment pressure monitor, containment water level monitor is containment hydrogen monitors installed per requirements of TMI Items II F 1 4, II F 1 5 & II F 1 6, respectively MAIER, J E Rochester Gas & Electric Corp 83/06/20 CRUICHFIELD p Operating Reactors Branch 5 10pp 18793 176 24X Fiche 50-244,83/06/20,8306270360

B30627036B Forwards responses to SER, suppl 4. Sections 13 3 2 2 % 13 3 2 3 (NUREG-0857), re courses of action necessary in unlikely event of emergency at facilities Info will be included in Rev 3 to emergency plan VAN BRUNTIE E Arizona Public Service Co ANPP-24103-WFQ 83/06/15 KNIGHTON, 0 Licensing Branch 3 26pp 18973 214 Fiche 50-528, 83/06/15, 8306270369

8306270376 Submits addl info ro Generic Ltr 81-03 concerning implementation of NUREO-0313. "Intergranular Stress Carrosion Cracking of Pressure Boundary Piping & Safe Ends "per 830415 request Inservice lasp piogram not appropriate BORDINE.T C Consumers Power Co CL 81-03 83706/22 CRUICHFIELD.D Operating Reactors Branch 5 5pp 18973 30 Fiche 50-155,83/06/22,8306270376 18993 308

B306270413 Advises that util does not object to Limerick Ecology Artion position in B30610 ltr on contentions related to NUREG-0737 METTERHAHN, M J Conner & Wetterhahn METTERHAHN, M J Philadelphia Electric Co 83/06/23 BRENNER.L., MORRIS.P A., COLE.R F Atomic Safety and Licensing Board Panel 2pp 18994 146 24X Ficha 90-352,83/06/23,8306270413

830A280013 NUREG/CR-32A3 106280013 NUREGYCR-9263 A COMPARISON DF METHODS FOR UNCERTAINTY ANALYSIS OF NUCLEAR POWER PLANT SAFETY SYSTEM FAULT TREE MODELS MARTZ, H F , BECKMAN, R J , CAMPBELL, K Los Alamos Scientific Laboratory FIN A-7725 LA-9729~MS 83/06/30 Division Analysis 181pp 19044 101 Division of Rist

8306280033 NURE0/CR-2607 FIRE PROTECTION RESEARCH PROGRAM FOR THE U.S. NUCLEAR DUBE H Sandia Laboratories FIN A-1010 SAND82-0431 DUVISION of Engineering Technology 106pp 19042-087

8306280036 Forwards evaluation 5 request for add1 info on responses to 821210 order re NUREO-0737. Item II F 2. "Detection of Inadequate Core Cooling " Clarification requested within 30 days Digital indicators acceptable STOLZ.J F Operating Reactors Branch 4 83/06/14 HUXILL.H D Operat Public Utilities - 0PU Service Corp 8pp 19042 348 24X Fichs 50-289.83/06/14.8306280036

B306280044 NUREO/CR-2906
BENSITIVITY OF RISK PARAMETERS COMPONENT UNAVAILABILITY IN
REACTOR SAFETY STUDY (PBAP/PSAB COMPUTER CODES)
AZARM, H. FARAHZAD, P. TINGLE, A. Brockhaven National Laboratory
FIN A-3235 BNL-NUREO-51380 83/09/31 Division of Risk
Analysis 167pp 19044 284

- 8306280049 NUREG/CR-5163
 RELAPS ASSESSMENT LOFT SMALL BREAK L3-6/LB-1
 RMETYK, N Sandia Laboratories FIN A-1205 SAND83-0245
 B3/66/30 Division of Accident Evaluation 94pp 17045 070
- 8306280080 NUREG/CR-2973
 LOBS OF DIR SEQUENCES AT BROWNS FERRY UNIT ONE -- ACCIDENT
 SEQUENCE ANALYSIS
 COOK.D H . GREENE.S R , HARRINGTON, R M Dak Ridge National
 Laboratory FIN 8-0452 ORNL/TM-8532 83/06/30 Division of
 Accident Evaluation 180pp 19068 293 24X Fiche 50-259,83/06/30,8306280080
- 8306280083 NUREG/CR-3267
 SIMILARITY ANALYSIS AND SCALING CRITERIA FOR LWR'S UNDER
 SINGLE-PHASE AND TUG-PHASE NATURAL CIRCULATION
 ISHII-M . KATACKA. I Argonne National Laboratory FIN A-2026
 ANL-83-32 83/03/31 Division of Accident Evaluation 46p,
 17067 283
- B30-200089 NUREG/CR-2789
 PREGSURE VESSEL THERMAL SHOCK AT U S PRESSURIZED-WATER
 REACTORS EVENTS AND PRECURSORS 1763-1781
 PHUNG, D L. Dak Ridge National Laboratory FIN 8-0435
 DRNL/NSIC-210 B3/05/31 Division of Risk Analysis 2519
- B366280073 NUREO/CR-2874 V03

 HIGH-TEMPERATURE GAS-COOLED REACTOR SAFETY STUDIES FOR THE DIVISION OF ACCIDENT EVALUATION QUARTERLY PROGRESS REPORT, ULY 1 EEPTEMBER 30,1982

 BALL-J C . CLAPP,N E . CONKLIN,J C Oak Ridge National Laboratory FIN S-0122 ORNL/TH-B843/V3 83/06/J0 Division of Accident Evalvation 27pp 17069 331
- 8306280076 NUREG/CR-3272
 ENVIRONMENTAL ABSISTED CRACKING IN LIGHT WATER REACTORS
 Annual Report:October 1781 Septembor 1782
 SHACK:W J : MASSNER:T F : KUPPERMAN.D 8 Argoine National
 Laboratory FIN A-2212 ANL-83-27 83/06/30 Division of
 Engineering Fachnology 101pp 17042 176
- 8306280137 Forwards IE Insp Rept 50-528/83-12 on 830424-27 \$ 0512 No noncompliance noted 800K-H E Region 5, Office of Director 83/06/03 ANDOGNING C Arisona Public Service Co 2pp 19014 333 24X Fiche 50-528,63/06/03,8306280137
- --8306280145 IE Insp Rept 50-528/83-12 on 030424-29 % 0512 No nencompliance noted Major areas inspected followsp on IE info notices, organization & staffing, environ protection, rasolution 100FR50 95(e) & NUREQ-0737, Items II F i & II B 3 SHERMAN, C , NORTH, H 8 , WENSLAWSKI, F A Region 5, Office of Director 83/06/03 16pp 19014 335 24x Fiche 50-528,83/06/03,8306280137
- 8306280138 Forwards "Control of Heavy Loads. Philadelphia Electric Co. Peach Bottom Atomic Power Station, Units 2 % 3." deaft technical evaluation rept BTOLZ. J F Operating Reactors Branch 4 83/06/14 BAUER. E 9 Philadelphia Electric Co. 2pp. 19043-359 24X Fiche 30-277,83/06/14,8306280138
- --BJ06040329 TER-C5504-379/380

 "Control of Heavy Loads, Peach Bottom Atomic Power Station, Units 2 & 3," draft technical evaluation rept BOHBEROIR, C R Franklin Institute/Franklin Research Center NRC-03-81-130 TAC 08070 83/05/17 NRC No Detailed Affiliation Given 45pp 19043 361 24X Fiche 50-277, B3/06/14, 230-250-150
- 8306280155 informs that 830606 response to open item in integrated plant SAR (NUREG-0822) re flooding elevation acceptable resolves item Corrective actions re diesel generator bldg entrantes also acceptable CRUTCHFIELD.D Operating Reactors Branch 5 L805-83-06-054 83/06/23 FIEDLER.P B General Public Utilities GPU Service Corp 2pp. 19014 316. 24X Fiche 50-217, 83/06/23,8306280155
- 8301280190 NUREO/CR-3185 CRITICAL REVIEW OF THE REACTOR BAFETY STUDY RADIOLOGICAL MEALTH EFFECTS MODEL COOPER, D W , JACOB, N , KASE, K R Harvard Univ FIN A-1042 BANDOZ-7081. 63/05/31 180pp 19069 111
- 8306280197 Forwards safety evaluation of util design review of TMI Action I tem II B 2 2, "Plant Shielding " Plant shielding adaquate to assure post-accident access to vital areas CRUTCHFIELD, D. Operating Reactors Branch 5 L805-83-06-054 83/06/27 LINDER, F. Dairyland Power Cooperative Spp. 19015 07 24x Fiche 50-409.83/06/27.8306280197

- 8306280233 Forwards correct version of App A. "Mechanical Errors From NUREO/CR-2337,Vol 1.Aquatic Impacts From Operation of Three Midwestern Nuclear Power Plants " Draft version inadvertently attached to 830604 submittal UNES.W C Omaha Public Power District LIC-83-148 83/06/22 VOLLMER.R H Division of Engineering 10pp 17015 088 24% Fiche 50-285.83/06/22,0306280233
- B306280317 Submits required data to demonstrate that line voltage regulators perform as acceptable isolation device by limiting primary current under short circuit conditions to full-load primary current, per SER (NUREO-0857) VAN BRUNTLE E Arizona Public Service Co ANPP-24155-J79/B3/06/23 KNIGHTON, O Licansing Branch 3 19 19001 282 24X Fiche 50-528,83/06/23,8306280317
- 8306280321 Discusses impact of NUREG-0824, SEP Topic III-4 B. "Turbine Missiles." on control valve surveillance testing program No changes to current testing program warranted Item closed. CDUNSIL.N G. Northeast Nuclear Energy Co. (subs. of Northeast Utilities) CDUNSIL.N G. Northeast Utilities B10819 83/06/22 CRUTCHIELD.B Operating Reactors Branch S. 2pp. 19001.312 24X Fiche 50-245.83/06/22,8306280321
- 8306280371 Forwards IE Insp Rept 50-397/83-20 on \$30516-20. No noncompliance noted STERNBERGOD M Region 5. Office of Director, 83/06/15. CARLISLEC S Washington Public Power Supply System, 2pp 19001 323 24X Fiche 50-397.83/06/15.8306280371
- --8306280380 IE insp Rept 50-397/83-20 on 830516-20 No noncompliance noted Major areas inspected GA program TMI (NUREO-0737) activities including Confirmatory Issue 22 & Independent insp
 - inap WILLETT.D J. DODDS.R T Region 5. Office of Director IEB-79-05 B3/06/15 7pp 19001 325 24% Fiche 50-397.B3/06/15.B3062B0371
- 8304280386 Clarifies 830422 response to request for addl info re NUREG-0737, Item II B 3, "Post-Accident Sampling Sys." per NRC 830531 telcon In-core temp indicators not in use at plant per Reg Ouide i 97 % Generic Ltr 82-33 PILANT, J H Nebraske Public Power District LGA8300161 83/06/21 VASSALLD, D B Operating Reactors Branch 2, 2pp 19014 085, 24X Fiche 50-298.83/06/21,8304280386
- B306280412 Forwards response to B30422 request for add1 info re Rev I to NUREO-0313 concerning leakage detection sys GUNDBILL Of Northeast Nurthers Energy Co (subs of Northeast Utilities). COUNBILL ON Northeast Utilities A03200 B3706/21. CRUTCHFIELD D Operating Reactors Branch 5 93pp 19020-188 24) Fiche 30-245.83706/21.B306280412
- 8304280415 Supple B21220 response to NUREO-0313 request for additinfo Ferrite content of cast austenitic stainless steel ranges from 15 to 20% Valves highly resistant to intergranular stress corrosion cracking MILLS.L. M Tennessee Valley Authority 83/06/22 DENTON.H.R Office of Nuclear Reactor Regulation. Director. 2pp 19018.351 24% Fiche 50-239.83/06/22.8306280415
- 8306280436 Forwards Amend I to environ qualification rept.per 830314 request & NUREG-0588 requirements VAN BRUNTLE E Arizona Public Service Co ANPP-24107-HFG/83/06/24 KNIGHTON.Q Licensing Branch 3 120pp 19016:297 24X Fiche 50-528.83/06/24,8306280436
- 8306280442 Advises that based on review of 801217 submittal re NOREO-0727: Item II K 3 21: "Restart of Core Spray & EPCI 84s." I saue resolved CRUTCHFIELD.D. Operating Reactors Branch 5 L805-83-06-056 83/06/27 VANDEWALLE, D J Consumers Power Co 4pp 19020-184, 24X Fiche 50-155,83/06/27,8306280442
- 8306280444 Requests 60-day extension for responding to 830511 request for add1 info re NUREO-0737. Item II K 3 28. "Qualification of Automatic Depressurization Sys Accumulators " Extension due to personnel changes & add1 time needed by AE FILANT. J M Nebrasta Public Power District, LGA9300163 89/06/21, VASBALUG. D B Operating Reactors Branch 2 2pp 19020, 176 24X Fiche 50-298,83/06/21,8306280444
- 8306280445 Forwards General Physics Corp svaluation results of items in corporate scope of review Info should be sufficient to close SER open items
 EMITH.J.L. Leng Island Lighting Co. SNRC-912 83/06/23.
 DENTON.II R. Office of Nuclear Reactor Regulation, Director 6pp 19020 178 24% Fiche, 50-322, 83/06/23, 8306280445

- 8306280459 Informs that operational data for completion of HEPA filtration sys extended to B31001 due to difficulty in adopting ventilation sys to accommodate demands of HEPA filtration per Suppl i to NURES-0737 HUSDLF.D Northern States Power Co B3/06/20 Office of Nuclear Results Regulation, Director ip 19018 328 24X Fiche 50-000, B3/06/20, B306280459
- 8306280478 Provides info re SEP Topic VI-4. "Containment Isolation Bys." to resolve concern raised by NUREG-0824. "Integrated Plant Safety Assessment," for which NRC unable to determine adequacy of penetrations X-2114 & X-204 COUNSIL.W G Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL.W G Northeast Utilities B10816 B3/06/22 CRUTCHFIELD, D Operating Reactors Branch 5 2pp 19018 313 24X Fiche 50-245,83/06/28,8306280478
- 8306280487 Discusses problems w/post-accident sampling sys (PASS) microprocessor, on-line pH meter sample flow & ign chromatograph Proposed PASS completion per NUREG-0737. Item 11 B 3. scheduled for 830930 JONES. W C Omaha Public Power District LIC-83-147 83/06/23 CLARKR A Operating Reactors Branch 3 3pp 19017 186 24x Fiche 50-285. 83/06/23. 8306280487
- 8306280489 Lists commitments to implement add1 monitoring & restrictive limits on unidentified RCS leakage per NUREG-03/3 Rev 1. in response to IE Bulletin 83-02 Plans to be submitted to NRC 3 months prior to next refueling outage HOME, P W Carolina Power & Light Co IEB-83-02 83/06/24. VASSALU.D B Operating Reactors Branch 2 2pp 19018 311 24X Fiche 50-325,83/06/24,8306280489
- 8306280502 Forwards supplemental response to EGJG, Phase I.Apr 1783 rept re NUREO-0612, "Control of Heavy Loads," reflecting areas of concern addressed during 830614 telian
 8MARTI,E.D Commonwealth Edison Co 6773N. 83/06/22 DENTON, H R Office of Nuclear Results attion, Director 26pp 19019 236 24X Fiche 50-373,83/06/22,8306280502
- 8306280508 Forwards add1 info re compliance w/NUREG-073/. Items II F 1 4: "Containment Pressure Monitor" & II F 1 5: "Containment Water Level Monitor," per 830408 commitment 9AYNE.J P. Power Authority of the State of New York JPN-83-58 83706/23 VASSALLO,D 8 Operating Reactors Branch 2 7pp 19017.288 24X Fiche 50-333.83706/23.6306280508
- 8306280324 Supplemental application for amend to Licenses DPR-71 & DPR-62.revising Tech Specs re RCIC sys actuation instrumentation.per Generic Ltr 83-02 & NUREG-0737 (tems HOME,P.H. Carolina Power & Light Co. LAP-83-227 83/06/23 VASSALLO.D B Operating Reactors Branch 2 4pp 19019 290, 24x Fiche.30-324.83/06/23.8306280524
- --8306280544 Revised Tech Bpecs re RCIC sys actuation instrumentation + Carolina Power & Light Co GL-83-02 83/06/23 2ipp 19019 294 244 Fiche 50-324.83/06/23, 8306280324
- 8306280539 Forwards documents to assist w/evaluation of B30601 submittal re integrated assessment of open issues Results of primary conlant sys safety relief valve test in response to NUREO-0737. Item II D 1.provided in util B1001 Itr W/o enci BLANCHARD. D.P Carolina Power & Light Ca 83/06/20 RUBIN.M NRC No Datailed Affiliation Given 4pp 19017 310 24X Fiche: 50-155, 83/06/20, 8306280539
- 8306280583 Forwards, per request, Reg Guide 1 70 & NUREG-0800, Sections 2 3 1. M/o encls PERLIB. Regulation 3 83/06/27 BERWICK, B Texas, State of 1p. 19017 324 24% Fiche 50-498, 83/06/27, 8306280383
- 8306280585 Responds to Generic Ltr B2-33 (NUREG-0737, Suppl 1) re requirements for emergency response capability Proposed completion dates encl TAUBER.H. Betroit Edison Co EF2 - 62.262 83/06/23 YOUNGBLOOD, B J Licensing Branch 1 2pp 19018 026 24X Fiche 30-341,83/06/23,8306280585
- B3062900BR Forwards negative declaration & EIA (NUREO-0994) re renewal of License BNM-696 W/o EIA
 PAGE,R.Q. Uranium Fuel Licensing Branch B3/06/21 MQWRY,W R QA
 Technologies, Inc./General Atomic Co ip 19046 167
- 8306290131 NUREG/BR-0051 V04 N7
 POWER REACTOR EVENIS November-December 1982
 MASSARO,S.A./ TRENERY,S E Director's Office 83/06/30 35pp

- 8306270146 Informs that util response to NUREG-0737, Items II F 1 4, II F 1 5 % II F 1 6 acceptable re installation of containment pressure, water level % hydrogen monitoring sys SER encl
 CLARK, R A Operating Reactors Branch 3 83/06/21 FAY, C W Wisconsin Electric Power Co 8pp 19046 298 24x
 Fiche 50-266:83/06/21.8306270146
- 8306290158 Forwards safety evaluation concluding that requirements of TMI Items II F i 4.II F i 5.2 II F i 6 re containment pressure, water level & hydrogen monitors met Items resolved CLARKAR A Operating Reactors Branch 3 83/06/17 JONES, W C Omaha Public Power District 9pp 19046 271 24X Fiche 50-285.83/06/17,8306290158
- 8306290190 Requests proposed Tech Specs re limiting overtime for staff personnel which comply w/guidelines furnished in 820615 ltr Proposal dtd 830121 unacceptable CLARK, R A Operating Reactors Branch 3 83/06/21 GARRITY, J H Maine Yankee Atomic Power Co 3pp 19046 287 24x Fiche 50-309,83/06/21,8306290190
- 830629024! Forwards safety evaluation conditionally approving licensee 830310 request from relief from Generic Ltr 82-28 & NUREO-0737. Item II F 2 requirements to install reactor vescel level sys Addl info needed within 30 days CRUTCHFIELD. D Operating Reactors Branch 5 LSG5-83-06-058 83/06/27 KAY, J A Yankee Atomic Electric Co lipp 19036 247 24X Fiche 50-029.83/06/27.8306270241
- 8306270249 Advises that methodology used to calculate beta dose for radiation profile for equipment qualification not acceptable Resubmittal of beta analysis based upon methodology in NUREG-0588 required by 830630 CLARK, R A Operating Reactors Branch 3 83706/17 UHRIG, R E Florida Power & Light Co 2pp 19046 114 24X Fiche 50-335,83706/17,8306290249
- 8306290311 Forwards final seismic input for SEP Topic III-6, "Seismic Design Considerations "NUREG-0825 conclusions valid based on conservative structural analysis methods & linear elastic analysis CRUTCHFIELD, D Operating Reactors Branch 5 LSG5-83-04-047 83/06/22 KAY, J A Yankee Atomic Electric Co 35pp 19055 316 24X Fiche 50-029,83/06/22.8306290311
- 8306290323 Forwards safety evaluation of proposed resolution of classification of structures, sys & components issue in Section 4 5 of integrated plant safety assessment rept (NUREO-0820) Info acceptable to resolve open items WAMBACH. T Decrating Reactors Branch 5 LSO5-83-06-055 83/06/27 VANDEWALLE.D J Consumers Power Co 7pp 19055 306 24X Fiche 30-255.83/06/27,8306290323
- 8306290377 Forwards IE Insp Rept 50-302/83-19 on 830502-06 No noncompliance noted BANCE.H C Division of Project & Resident Programs 83/05/27 WILCOM.H S Florida Power Corp 2pp 19055 192 24X Fiche 50-302,83/05/27,8306290377
- --8306290380 IE Insp Rept 50-302/83-15 on 830502-06 No noncompliance noted Major areas inspected refueling outage radiation protection organization, procedures, advanced planning (ALARA), exposure control to respiratory protection program KAHLE, 18 Region 2, Office of Director DARR.K.P. Division of Engineering & Radiological Safety Programs 83/05/26 8pp 19055 194 24X Fiche 50-302.83/05/27,8306290377
- B306290400 Application to amend Licenses DPR-33, DPR-52 & DPR-68, changing Tech Specs to require annual rept of main steam safety/relief valve actuations, in response to NUREG-0737, Itam II K 3 3 & Generic Ltr 83-02
 MILLS,L M Tennessee Valley Authority QL-83-02 B3/06/20
 DENTON,H R Office of Nuclear Reactor Regulation, Director 2pp 19093 133 24X Fiche 50-259,83/06/20,8306270400
- --8306270408 Proposed Tech Spec revs.requiring annual rept of main/steam safety/relief valve actuations.in response to NUREO-0737. Item II K 3 3 & Generic Ltr 83-02 # Tennessee Valley Authority GL-83-02 83/06/20 5pp 17053 135 24X Fiche 50-257.83/06/20.8306270400
- 8306290406 Forwards safety evaluation of licensee compliance w/NUREG-0737. Item II B i, "RCS Vents." based on review of encl LLL technical evaluation rept High point vents on primary coolant side of isolation condenser not required CRUTCHFIELD. D Operating Reactors Branch 5 LSD5-83-06-057 83/06/27 CDUNSIL.W G Northeast Nuclear Energy Co (subs of Northeast Utilities) 6pp 19030 140 24X Fiche 50-245.83/06/27.8306290406

- --B306290413 TF-382/0823A

 "Selected Operating Reactor (ssues Program II RCS Vents
 (MVMCC 0737, Item II B 1)," final technical evaluation rept
 HELD, J T Energy Incorporated * Lawrence Livermore Laboratory
 FIN A-0230 TAC 44384 83/04/06 ALBERTHAI, G Division of
 Litensing 4pp 19093 146 84% Fiche 50-245,83/06/27,8306290406
- 8306290538 Requests methodology & acceptance criteria to be used in evaluating anchorage of 4.160-volt switchgear panels by 831130 Review will be included in integrated plant SAR suppl CPUTCHFIELD,D Operating Reactors Branch 5 LSGS-B3-06-053 B3/06/24 FIEDLER,P B General Public Utilities GPU Service Corp 2pp 17093 029 24X Fiche 50-217, 83/06/24, 8306290538
- 8305300128 Comments on NRC plan for evaluating safety goals Environ & gaalogical effects missing from design objective SACHROFF.S . HILLHOITE.B League of Women Voters 18FR10772 020 83/06/27 Office of the Secretary of the Commission 5pp 19120 008
- B3D6300131 Comments on NRC safety goal development program Vendor generally agrees w/safety goals SHERHOOD: 0 O General Electric Co 48FR10772 021 83/06/20 Doctating & Services Branch 2pp 19122 331
- 8306300133 forwards diaft revised response to TMI [tem I G I, "Training During Leu-Power Testing," per 830627 conforence call Info contained in draft revised response will be incorporated into FEAR rev scheduled for Aug 1983 SEADLEY, J Philadelphia Electric (o 83/06/28 SCHWENCER, A Licensing Branch 2 5pp 19122 311 24% Fiche 50-352.83/06/28, 8306300133
- B30630013H Forwards SER Suppl 2.(NURCG-0881) W/o enc)
 KARMAN, M Jearing Branch 1 ISSUANCES OL 81/06/28
 LAURENSON, J A. PAXTON, H C. ANDERSON, G C. Atomic Safety and
 Licensing Board Panel 1p 19168 118 P4X Fiche 50-482,83/06/28,
 \$3064300138
- B306300140 Informs that add1 nondegree personnel will be assigned to shift technical advisor position per NURFG-0737. Item
 | A 1 i Info re experience, college educ & current operator
 | Islaness enci
 | COUNSIL.W 0 | Northeast Nuclear Energy Co (subs of Northeast
 | UKILITIES | COUNSIL.W 0 | Northeast Utilities | BIOBP3 | B3/06/22
 | CRUICHFIELD, D Operating Reactors Dianch 5 | CLARK, R A Operating
 | Reactors Branch 3 | 3pp | 19127 320 | 24X Fiche 50-245,83/06/22,
- 8306300:46 Comments on safety goals policy statement & evaluation plan Supports plan VINCK.H Furopean Communities, Commission of 48FR10/72 018 83/06/10 LAFLEUR, J D Office of International Programs, Director 18pp 19119 321
- 8306300166 Forwards supplemental description of CE Dwhers Group program & schedule in response to Generic Ltr 83 104 is guidance for closing out NURCE-0737, Item II K 3 5, "Automatic Trip of Reactor Coptant Pumps" DRUMMEND, J Louisiana Power & Light Co MSP83-2115 83/06/27 YNIGHTON, 0 H 1 trensing Branch 3 /pp 19117 273 24X Fiche 20-382,83/06/27,8306300166
- 6306390172 Comments on NRC safety goal evaluation plan Supports plan Off BY.E V Gilby Associates 48FR10777 OP2 83706716 DIRCKS.W J Office of the Executive Director for Operations App 19148 111
- 6305300173 Comments on plan to evaluate Commission safety goal policy statement NRC should provide periodic updates of plant analyses HISEMBURG,M R. Houston Lighting & Power Co. 48FR10772-019 83706722 CHILKS J. Office of the Secretary of the Commission 2pp 17148-109
- 8306300213 Responds to 020730 ltr ne emergency preparedness appraisal rapt & 820630 notice of violation Adequate performance demonstrated during 821021 exercise Exam of alsepte exercise Exam of METPLER, J 0 Region 3, Office of Director GL 82-33 83/06/09 03C.AM.J C American Electric Power Gervice Corp 3pp 17122 101 24% Fiche 80 315,83/06/09,8306300213
- 8305309226 Forwards IE Insp Rept 50-409/83-07 on 030916-19 No noncompliance noted PAPERIELLO.C. J. Region 3. Office of Director 83/06/14 LINDER.F. W. Dairyland Power Cooperative 2pp 19119 173 24X Fiche 50-409.83/06/14.8306300226

- --830630023: IE Insp Rept 50-409/83-07 on 830516-18 No noncompliance noted Major areas inspected status of post-TMI requirements PAUL.R A , GREGER.L R Region 3, Office of Director 83/06/14 5ap 19119 175 24x Fithe 50-409.83/06/14.8306300226
- B306300241 Forwards diagram depicting proposed location of new training ctr per Suppl 1 to NUREO-0737 Ctr wilt house new emergency operations facility % is tentatively scheduled for completion in Spring 1784 MANOAMIC V Niagara Mohauk Power Corp B3/06/24 VASBALLO, D B Operating Reactors Branch 2 2pp 19122 309 24x Fiche 50-220.83/06/24.8306300241
- #306300251 Forwards IE Insp Rept 90-346/83-14 on 830524-26 No noncompliance noted LITTLE.W S Region 3. Office of Director 83/06/17 CROUSE.R P Toledo Edison Co 2pp 19119 343 24X Fiche 50-346.83/06/17, 8306300251
- --8306300252 IE Insp Rept 50-346/83-14 on 830524-26 No noncompliance noted Major areas inspected licensee action on previous insp findings MENDEZ.R. WILLIAMS.C C. Region 3. Office of Director 83/06/17 5pp 19117 345 24X Fiche 50-346.83/06/17.8306300251
- ORG CORRESPONDENCE WITH OTHER ORGANIZATIONS
- 8305110438 IE Info Notice 83-32. "Ruptured Am-241 Sources Contained in Mell Lagging Device" Svc list encl
 TAYLOR, J M Division of Safeguards & Inspection Programs (Post 830103) 83/05/26 Consolidated Edison Co of New York, Inc 125pp 18831 043 24X Fiche 50-000,83/05/26,8305110458
- 8305110460 IE Info Natice 83-34, "Event Notification Info Worksheet"
 Svc list encl
 JVCRPAN.F.L. Division of Emergency Preparedness & Engineering
 Response (Post 830103) 83/05/26 Consolidated Edison Co of New
 York, Inc 115pp 18732 085 24X Fiche 50-000,83/05/26,8305110460
- 830511046) IE Info Notice 83~35, "Fuel Movement W/Control Rods Withdrawn at BMRs " Svc list encl JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/31 Consolidated Edison Co of New York, Inc. 116pp 18732 208 24X Fiche 50-000,83/05/31,8305110461
- B305110464 IE Info Notice 83-36, "Impact of Security Practices on Safe Operations " Svc list enc! JORDAN E L. Division of Emergency Preparedness & Engineering Hespense (Post 830103) 83/06/09 Consolidated Editon Co of New York, Inc. 119pp 18830 280 24% Fiche 50-000,83/06/09,8305110464
- 8305110470 IE Info Notice B3-38, "Defective Heat Sink Adhesive & Seismically Induced Chatter in Relays Within Printed Circuit Cards " Svc list encl JORDAN, F. L. Division of Emergency Proparedness & Engineering Response (Past 830103) 83704/13 Consolidated Edison Co of New York, Inc. 118pp 18920-225 24X Fiche 50-000,83/06/13,8305110470
- B303:10475 IE Info Notice B3-40, "Need to Environmentatly Qualify Epoxy Grouts & Sealers " Svc list enc! URBDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) B3706/22 Consolidated Edison Co of New York, Inc. 115pp 17021 179 24X Fiche 50-000.83/06/22.8305110475
- 830511047/ IC Info Notice 83-41, "Actuation of Fire Suppression Sys Causing Inoperability of Safety-Related Equipment " Svc list enc! JORDAN, E. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/22 Conselidated Edison Co. of New York, Inc. 120pp 1897 007 24% Fiche 50-000, 83/06/22, 8303110477
- 0305110479 IE Info Notice 83-42. "Reactor Mode Switch Malfunctions " 8vc list encl JORDAN,E L Division of Emergency Preparedness & Engineering Response (Post 830103) 83/06/23 Consolidated Edison Co of New York, Inc 116pp 18996 242 24X Fiche 50-000,83/06/23,8305110479
- 8305110487 IE Info Natice 83-43, "Improper Settings of Intermediate Range (IR) High Flux Trip Setpoints " Svc list encl JORDAN, E. Division of Emergency Preparedness & Engineering Response (Post 830103) 83706/24 Consolidate Edison Co of New York, Inc 116pp 19046 277 24X Fiche 50-000,83706/24,8305110483
- B306010241 Provides add1 info re Yakıma Indian Nation, per verbal request State of MA utillies law enforcement teletype systo notify contitious counties of event w/potential offsite consequences Yakima County would notify tribal police DONOVAN, R W. Federal Emergency Management Agency B3/05/19 AULUCK, R Licensing Branch 2 lipe 18673 009 24X Fiche 50-397.83/05/19.8306010241

- 8306070233 "Zion Nuclear Generating Station." second evaluation * Institute of Nuclear Power Operations 83/04/30 38pp 18741 117 24% Fiche 50-295.83/04/30.8306070233
- 8306070475 Responds to approval request for info collection re generic clearance of IE bulletin. "Failure of Reactor Trip Breakers (Mestinghouse DB-30) to Open on Automatic Trip Signal"
 Request approved through 850430 under OMB Number 3150-0012
 SCURRYIN Office of Management & Budget OMB 3150-0012 83/05/26
 8COTT.S Document Management Branch 2pg 18776 333
- 8304090010 IE Info Notice 83-37. "Transformer Fathure Resulting from Degraded Internal Connection Cables" Svc list onel JORDAN,E L. Division of Emergency Preparedness & Engineering Response (Post 830103) 83/05/13 Consolidated Edison Co. of New York, Inc. 243pp 18721 001 24X Fishe 50-000,83/06/13,8304090010
- 8306090114 Forwards consolidated Regional Assistance Committee comments for five unrated planning elements Comments should be part of initial FEMA findings to determination of effectiveness of offsites emergency planning MCLGUGHLIN, D. Federal Emergency Management Agency 83/05/18 DIRCKS, W.J. Offsice of the Executive Director for Operations Spp. 18793-324 24X Fichs 50-329,83/05/18,8306090114
- 8306090118 Advises of approval of emergency response plan for facility, subj to verification of adequacy of public alerting & notification sys
 MCLDUGHLIN,D Federal Emergency Management Agency 83/05/16
 DIRCKS,W J. Office of the Executive Director for Operations 1p
 18793 327 24x Fichs 30-155,83/05/16,8306090118
- 8304090229 Approves State of MI emergency response plan b associated local plans w/condition that adequacy of public alerting b notification sys be verified per FEMA/NRC joint criteria listed in NUREG-0534/FEMA-REP-1. Rev i. App 3
 PAPERIELLO.C J Region 3. Office of Director B3/06/06
 DEWITT, B B Consumers Power Co. 2pp 18796 235 24X
 Fiche 50-155.83/06/06.8306090229
- 8306130294 Forwards FEMA final exercise evaluations of offsite emergency preparedness exercise conducted on 810729, 1007 & 830018 No major exercise deficiencies noted HIND J.A Region 3, Office of Director 83/06/09 REED, C Commonwealth Edison Co 2pp 18823 334 24X Fiche 50-295,83/06/09,8306130294
- 8306150081 NUREO/CP-0044 V02
 PROCEEDINGS OF THE INTERNATIONAL ATOMIC ENERGY AGENCY
 BRECIALISTS' MEETING ON SUBGRITICAL CRACK GROWTH Sessions
 III. IV And V Held At Freiburg, Federal Republic Of Germany.
 May 13-15,1981
 CULLEN, W Haterials Engineering Associates, Inc. * ENSA.
 FIN 8-8133. MEA-2014 83/05/31 Division of Engineering
 Technology 434pp Available at NRC 49 00 18870 097
- B306150263 Forwards State of ME plans to correct emergency preparedness deficiencies identified by FEMA.per B30511 site meeting Add1 info on radiological exposure control will be submitted to FEMA within 1 wk

 GARRITY.J H Maine Yankee Atomic Power Co MN-B3-118 B3/06/06

 ALLAN.J K Region 1. Office of Director 15pe 18849 176 24X

 Fiche 50-309.83/06/06.8306150263
- 8306160093 Addl response to FOIA request for documents to IAEA nuclear matt safeguards program Forwards App A documents App B Documents 1-B entirely withheld to Documents 9-16 partially withheld (ref FOIA Exemptions 1.3 & 5) FELTON, J H Division of Rules and Records 83/04/01 GREENBERG, E V Tuttle & Taylor 5pp 18892 011
- --8306160107 Forwards suggested questions & answers for 811202 hearing re IAEA safeguards.per request SHEA.JR Office of International Programs. Director 81/12/01 OILINGKY.V Commissioners 7pp 18892 018
- -8306160115 Draft Commission paper proposing ltr from Chairman thanking TE Shea for suggestions on improving IAEA safeguards & informing Commission that TE Shea ltr sent to State Dept DIRCKS, U.J. Office of the Executive Director for Operations 82/01/27. 16pp 18892 026
- --830616011B Forwards undisputed portion of response to Bill25 ltr re IAEA safequards sys, supplementing Commission 820302 ltr BRADFORD,P A Commissioners 82/03/04 OTTINGER,R L House of Rep. Energy & Commerce HART,G Senate DINGELL,J D House of Rep. 2pp. 18892 042

- -8306160125 Forwards G Hart.MB Pratzer (Schwinman,P Leventhal), HD Sololski testimonies ') prepared statements at 830303 Joint hearing of Committee on Foreign Affairs to IAEA Safeguards

 KAMMERER, C. Office of Congressional Attalis 82/03/09

 PALLADING N. J. GILINSKY, V. BRADFOND, C. A. Commissioners 4pp
- --8306160131 Testimony of G Haif before Subjemmitted on Intl Economic Policy & Trade, Committee on Foreign Affairs US House of Representatives re IAEA safequards Committee 820301 revised meeting notice encl HART, G Senate 83 62/03/03 4pp 18892 048
- --8304160134 Statement of MB Kratzer below Subcommittees on Intl Security & Scientific Affairs & Intl Economic Pulicy & Frade-Committee on Foreign Affairs US House of Representatives re IAEA safeguards KRATZER/M B International Energy Associates | Ltd | 82/03/03 | 33pp | 1887-052
- --8306160138 Prepared statement of L Scheimman before Subcommittee on Intl Economic Policy & Trade, Committee on Foreign Affairs, US House of Representatives re IAFA safeguards SCHEINMAN.L Cornell Univ 82/03/03 17pp 18892 087
- --830616014J Testimony of P Leventhal before Committee on Foreign Relations, US House of Representatives to IACA safeguards LEVENTHALP Nuclear Club, Inc., The 82/03/03 10pp 18892 110
- --8306160148 Prepared Statement of HD Sovolski before Subcommittee on Intl Security & Scientific Affairs & Subcommittee on Intl Economic Policy & Trade Committee on Foreign Affairs US House of Representatives re IACA safeguards SOKOLSVI-H D Heritage Foundation 82/03/03 10pp 18892 120
- --8306160153 Responds to 820420 ltr ie IAEA safeguards NRC actively examining effective ways & means to continue support for IAEA safeguards PALLADINGN N J Commissioners 82/06/10 BLIX, K International Atomic Energy Agency (Austria) 1p 18892 130
- --8306160156 Forwards summary of IACA safeguards sys US support for IAEA safeguards crucially important BLIX.H International Atomic Energy Agency (Austria) B2/04/26 PALLADING,N J Commissioners 4pp 16892 [J]
- --8306160190 Forwards revised draft safegualds analysis for Romanis for transmission to State Dept No sensitive foreign intelligence info employed W/a encl Partially deleted answers 5 questions of IREA safeguards encl DURNETT, R F Division of Safeguards 80/07/13 SHEA, J R Office of International Programs, Director 5pp 18892-141
- ---8306160193 SECV-82-025 304160193 SECY-82-029
 Forwards N Gruemm preliminary comments on Morgan memo re
 IAEA safeguards for 811119 press conference SECY title &
 other safeguards info deleted
 DIRCKS, M J Office of the Executive Director for Operations
 82/01/19 Spp 18892 146
- --8306160198 SECY-82 046 Informs Commission of existing interagency groups involved in UB efforts to upgrade IAEA safeguards & provides brief rept on status of activities W/o encl outline & status of action plan
 DIRCKS.W J Office of the Executive Director for Operations
 82/02/02 13pp 18892 154
- --8306160PO3 Discusses implications of R Richter testimony before Genete Foreign Relations Committee & House Foreign Affairs Committee re traqu nuclear program & weaknesses in IAFA safeguards Safeguards info deleted DIRCKS, N J Office of the Executive Directol for Operations 82/03/09 BRADFORD, P A Commissioners 3pp 18892 167
- --8306160208 BECY-82-210 Forwards summary of significant NRC & Executive Branch efforts to improve IAEA safeguards & estimate of expended resources Safeguards info deleted W/o encl rept on US assistance to IAEA & outline of areas needing improvements DIRCKB.W J. Office of the Executive Director for Operations 82/05/26 17pp 18892 170
- --83061602(1 Forwards partially released transcript of 820602 briefing or efforts to improve IAEA safeguards in Washington, BC Withhuld portions per 100FR9 104(a)(1) listed CHILK S J Office of the Secretary of the Commission 82/08/03 Office of the Secretary of the Commission 2pp 18892 19/

- --9306160222 Draft Commission paper recommending Commission approval of proposed responses to Senator Hait / Representatives Dingell & Ottinger 821125 & 30 ltrs re IACA safeguards Safeguards into deleted M/o encl proposed ltrs DIRCKS.W J Office of the Executive Director for Operations 81/12/J1 1p 10872 284
- 6305170396 Forwards FEMA 830608 ltr to NRC, providing current evaluation JOSE 10346 Interes : Each assess (it to Nat. provising curis) of plant offsite emergency planning UNICES SP 83.06/09 HASSELL.D F Hearing Branch 2 ISSUACES SP 83.06/09 GLEASCH.J P Atomic Safety and Licensing Board Panel 18877 333 24X Fiche 50-247 83/06/09.8306170396
- 8306220245 NURFO/CP-0043 ERR
 FROCEEDINGS OF THE JOINT NRC/ANS MELTING ON BASIC THERMAL
 HYDRAULIC MECHANISMS IN LWR ANALYSIS Held At Bethesda
 Maryland, September 14-15, 1982
 * American Nuclear Society 83/06/02 Office of Nuclear
 Regulatory Research, Director 43pp 18751 0/3
- 8306230523 Discusses AIF proposal detailing info in one-step license application Proposal in form of rewrite of Reg Quide 1 70, "Std Format & Content of SARs for Nuclear Power Plants" will illustrate level of design detail required DIRCMS.N J Office of the Elecutive Director for Operations #830311 83706716 CHILK.S J Office of the Secretary of the Commission 1p 18951 336
- 6305240309 Forwards "1982 Trojan Nuclear Power Plant Exercise" based on 821118 exercise State & local plans & preparedness
- --B304240310 "1982 Trojan Nuclear Power Plant Exercise " 4 Federal Emergency Management Agency 82/12/1/ 18979-076 24% Fiche 50-344/83/05/18/8306240308 82/12/10
- 8306270309 (arwards ANL rept. "Flement-By-Flement Review of LICO Transition Module of Shoroham Nuclear Power Station Offsite Radiological Emergency Response Plan." in response to 830601 request
 PRIME,R W Federal Emergency Management Agency 83/06/23
 JORGAN.E L Division of Emergency Proparedness & Engineering
 Response (Past 830103) 2pp 18795 266 24X Fiche 80-322,83/06/23,
- 6306280306 Forwards FFMA 630623 findings on util transition plan for offsite energency preparedness HEPMA.D.A. Hearing Branch 3 63/06/24 tAURENSON, J.A. LIVINGSIGN, M.S. K. KINE, J.R. Atomic Safety and Licensing Board Panel 22pp 19017 212 24X Fiche 50-322, 61/06/24, 8306260906
- PROPOSED RULE

830A270309

- 8503030423 Comments on proposed rules 10CFR2 & 50 ie gianting temporary OLs Commission should not utilize temporary OL as mechanism to avoid rapid & expeditious issuence of full-term Ol PARKYNJD Affiliation Unknown 48/814926 OOI 83/04/19 Docketing & Services Branch 1p 18306 264
- 830A0\$0091 Responds to B30415 request for acceptance of proposed LER rulemaking package 10CFR50 73 Concurrence submitted on B30216 Certification of arceptable NPRDS performance before rule becomes effective recommended DENTON.RR Office of Nuclear Reactor Regulation, Director 83/05/20 MELTEMES.C J Director's Office 3pp 18676-073
- --8305020355 Forwards draft Commission paper forwarding final 10CFR50 73
 "LER Sys." incorporating comments from previous review
 Requests concurrence on Commission paper by 830422 for
 submission to Commission no later than 830430
 H<EMES.C J Director's Office 87/04/15 DINION, H R Office
 of Nuclear Reactor Regulation, Director 7pp 18696 076
- 8306020424 Comments on proposed rule re NRC policy statement on regionalization Power reactor licensing should not be candidate for transfor SIEWARTN L. Virginia Electric & Power Co. 481R12619 060 83/05/20 Docketing & Services Branch 2pp. 18694 123
- 8308<mark>020449 Package of three comments on proposed rule re NRC policy</mark> statement on regionalization

 FARRAR: DL Commonwealth Edison Co MAIER, JE Rochester Gas >

 Electric Corp COUNSIL, W Q Northeast Utilities 48FR12619

 83/03/23 Docketing & Services Branch 10pp 18893 338

- B306020451 Package of four comments opposing proposed rule to NRC policy statement on regionalization JENKS-LL Affiliation Unknown FATTON-S D. Three Mile Island Alert NILSON-R Eison Muclear Co., Inc. (subs of Exxon Corp.) ABFRI2619 B3/05/13 Office of the Secretary of the Commission 7pp 18693 294
- 8306060226 Package of two comments opposing proposed rule 10CFR20 re elimination of licensee judgment in reporting theft or loss of licensed mati of licensed mat| MRIGHT.D J Geisinger Medical Center Danville,PA GCHIAGER,K J Utah, Univ of 48rR2O721 83/05/23 Docketing & Services Oranch 2pp 18727 254
- 8306060220 Advises recipients of comments on proposed rule 10CFR30 regroup licensing for certain medical uses that Comment 12 was miscoded b will not be used again a Docketing Bervices Branch 48FR13189 83/06/01 Docketing Services Branch tp 18728-291 Docketing &
- 830A0A0R29 Comments on proposed rule re planned studies of QA programs for const of nuclear power plants Existing regulatory framework should not be snowbared by mandating addl layers of overview or prescriptive criticaria KEARNEY. J J Edison Electric Institute 48FR9104 032 83/05/20 CHILK, 6 J Office of the Sacretary of the Commission 2pp
- B306060231 Package of two comments supporting proposed rules 10CFR2 to 50 rollissing temporary OLs COTTER, W D. New York, State of KUBINAK, R A. Long Island Lighting Co. 48FR14926 83/05/23 Docketing to Services Branch. 4pp
- 8304060233 Comments on proposed rule 10CFR50 re significant hazards considerations & on state notice & consultation Supports ruid COTTER.W D New York, State of 48FR14864 020 83/05/16 of the Secretary of the Commission 2pp 18728 296 Office.
- 8304040249 Comments on proposed rule re GA programs for const of nuclear power plants Supports rule Recommends comprehensive frequent NRC or NRC-contracted audits of licenses GA programs recommended BULLOCK, S. V. Affiliation Unknown 4HRF9 06 033 83/05/26 BULLOCK, S. V. Affiliation Unknown 40FR9106-033 83/05/26 Docketing & Services Branch 2pp 18727-233
- fi306080268 Responds to FDIA request for SECY-83-22 Forwards publicly available partions of paper per telcon w/N Toms
 FELTON.J M Division of Rules and Records 83/04/11 KNIGHT.N t.
 General Physics Corp ip 18787 240
- --8306080P/O "Biatement of policy Further Commission Ouidance on Emergency Response Capability," draft 10CFR30 effective rule Suppl issued to NUREG-0737, "Clarification of TMI Action Plan Requirements"

 CHILK: S J Office of the Secretary of the Commission 83/04/11 3pp 18787 241
- 830614071? Concurs w/830510 memo re insider safeguards rule package, subj to appropriate consideration of comments Encl comments also address concerns contained in RF Burnett B30414 memo re protection of vital areas/islands DENTON, HR Office of Nuclear Reactor Regulation, Director 83706701 BAVIS, J 0 Office of Nuclear Material Safety & Safeguards, Director 5pp 18852-274
- --8306140718 Forwards revised insider safeguards rule package containing encl action plan to implement recommendations of Committee to Review Safeguards Requirements at Power Reactors Concurrence requested by 830327

 DAVIS. J 0 Diffice of Nuclear Material Safety & Safeguards Director 83705/10 DENION. H R Office of Nuclear Reactor Regulation. Birector CUNNINGHM. G H Office of the Executive Legal Director MINOQUE.R B Diffice of Nuclear Regulatory Research. Director 196pp 18852 279
- 8306160201 Comments on proposed rule 100FR30 re lech Apecs for nuclear gower plants tech Spec rulemaking should be reapaned in light of restrictive interpretation to utils BAUSER N A R.N.A. Lowenstein, Newman, Reis, Azelrad & Toll. 486R14864 83/06/09 Docketing & Services Branch. 4pp. 18862 001. 4pp
- 8306(60245 Advises recipients of comments on proposed rule 10CFR50 restds for determining whether license amend involves no significant hazards considerations that two comments marked 18 received SF Flynn comment will be 18A a Docketing & Services Branch 48FR14864 83/06/13 Docketing Services Branch 19 18861 225 Docketing &

- 8306160334 Comments on proposed rule 100fR50 re NRC policy statement on severe accidents & related views on reactor regulation Supports statement REED.C Aboute Industrial Forum 48FR16014 002 83/06/07 Datketing & Services Branch 2pp 18860 090
- 8306(60337 Comments on proposed rule 10CFR50 re NRC policy statement on severe accidants & proposed rule re safety goals development program UCS comments on proposed rules will be consolidated & filed in early Jul CURRAN.D Harmon & Weiss 49FR160(4 001 83/06/08 STUCKY.5 Docketing & Services Branch 1p 18860 124

- 8306160467 Comments on proposed rule re planned studies of GA programs for const of nuclear power plants Present OA requirements adequate.but commitment, implementation & timeliness need addi emphasis WEINMAN-S A American Society of Mechanical Engineers 48F Docketing & Services Branch 3pp 18863 108 48FR910A 034
- 6306220285 Forwards results of Dive of Licensing. Sys Integration & Human Factors Safety review of insider safeguards rule package & rept by Committee to Review Safeguards Requirements at Power Reactors W/o encl
 EIGENHUT.D G Division of Licensing 83/05/31 DENT(
 of Nuclear Reactor Regulation, Director 3pp 18940 (DENTON, H.R. Office 18940 351
- 8306230323 Comments on proposed rule 10CFR53 re criteria & procedures for determining adequacy of available spent nuclear fuel storage capacity Opposes rule
 HITHERS.B D Portland General Electric Co. 4BFR19382 001
 B3/06/08 Office of the Secretary of the Commission ip
 18944 143
- 8304230328 Comments on proposed rule 10CFR53 recriteria & procedures for determining adequacy of available spent nuclear fue; storage capacity Supports rule
 MALSKE, C Atomic Industrial Forum 48FR19382 002 83/06/14
 Docksting & Services Branch 4pp 18942 270
- 830623033: Comments on proposed rule 10CFR40 re proposel to suspend certain regulations that could have significant cost impact on licensees if implemented before conformance to EPA stds Opposes rule
 FREUDENTHAL.N Wyoming, State of 48FR23649 CO! 83/06/17
 Doctating & Services Branch 1p 18942 275
- 8305230339 Comments on proposed rule IOCFR50 re severe accidents A related views on nuclear reactor regulation Focus must shift from std designs to std design processes Supporting repts encl. WHITE: H Surns : Services Branch Burns & Roe Co 48FR160:4 003 83/06/15 Branch 22pp 18742 35:
- 8305230340 Comments on proposed rule 100FR20 re elimination of licensed judgment in reporting theft or loss of licensed mati NRC should modify judgmental part of rule to define substantial WISSINK, R G 3M Co Minnesota Mining & Mfg Co 48FR207 Docksting & Services Branch 2pp 18941 151 48FR20721 003
- 8306230445 Comments on proposed rule 10CFR50 re stds for determining whether license amends involve no significant hazards consideration Opposes rule Comment period insufficient HITHERS, B D Partland General Electric Co 48FR14964 021 83/06/15 Docketing & Services Branch ip 18941 153
- 8305230450 Advises that ancl 820909 petition to extend time for public comments on proposed rule 10CFR50 re personnel se/unescorted access to protected areas not answered by NRC Response requested requested CODPER.J H Affiliation Unknown 47FR33980 83/05/26 the Secretary of the Commission Ep 18942 079 Office of
- 8306280047 Informs that proposed changes in reporting criteria re salection of madical misadministration events for AD reporting appear reasonable NRR not responsible for regulatory matters re medical misadministration events DENION, H R Office of Nuclear Reactor Regulation, Director 83/06/17 HELTEMES, C J Director's Office 2pp
- --8306280056 Proposes that future AO determinations be based primarily 306280036 Proposes that future AO determinations be based premarity on severe adverse health effects; regardiess of part of body involved, per review of guidelines requested on 830512 by Commission Draft Commission paper enc]
 HELTEMESS, C. J. Director's Office 83/06/01 DENTON, H. R. Office of Nuclear Reactor Regulation; Director DEVOUND, R. C. Director's Office, Office of Nuclear Reactor Regulation; Director DEVOUND, R. C. Director's Office, Office of Nuclear Material Safety & Safeguards, Director 12pp

- 830629024P Comments on proposed rule 10FRR90 related for detrice whether license amends involve no arguificant hazards consideration Opposes rule (ATMERS, B.D. Portland General Electric Co. 48FR14864 022 83/06/15 Docketing & Services Branch Jp. 19056 00%
- 8306290270 Advises recipients of comments on proposed rule 10 stds for determining whether license amends involve no significant hazards considerations that Comment 21 uses twice Postland General comment changed to 22 • Docketing / Services Branch 48FR14864 83/06/27 Services Branch 1p 19056 073
- 8306300103 Communits on proposed rule 100FR20 re repts of theft of licensed matl Opposes rule BHELLEY.N J Merr-McGee Corp 48FR20/21 004 83/06/21 Docketing & Services Branch 2pp 19(1) 070
- B306300110 Comments on proposed rule 100FR50 re qualification equipment important to safety in nuclear power plants Opposes rule

 MORIARTY. J M Colt Industries, Inc. 47FR2876 089

 Docketing & Services Branch 2pp. 19048 217
- 8306300124 Comments on proposed rule (OLFA53)e criteria & prov for determining adequacy of available spent nuclear Fuel storage capacity Definition of diligence unclear EDDLEMAN.W Eddleman, W 48F419382 OUA 83/06/22 Packe Services Branch 1p 19168 | 31
- 8306300137 Comments on proposed suspension of selected provisic 160FR40 re U mill tailings disposal Opposes suspension BERICK.D Environmental Policy Institute 48FR23649 603 & Office of the Secretary of the Commission 69p 19169 it
- 8306300142 Package of five comments on proposed rule 10CFR53 re criteria 2 procedures for determining adequacy of available spent nuclear fuel storage capacity RILEY.R W South Carolina, State of JURDAN.W S Harmon & YEAGER.B B Sterra Club 48FR17382 83/06/28 PALLADING > Commissioners 34pp 19119 214
- 8306300190 Comments on proposed ruly 10CFR53 re criteria & pro es e for determining adequacy of available spont nuclear fuel storage capacity Opposes rule LEMIS.M I Lewis, M 40FR19382 003 83/06/03 Office of , Socretary of the Commission 2pp 19119 318
- 8306300152 Comments on proposed jule 10/FR93 re criteria & pro #2 . for determining adequacy of available spent nuclear fuel storage capacity Opposes rule storage capacity Opposes rule SERNDT.J Snake Rivor Alliance 48FR19382 014 83/06/27 No Detailed Affiliation Given 2pp 19048 359
- B306300154 Comments on proposed rule tOCFR93 to procedures for determining adequacy of available spent nuclear fuel storage capacity Util agrees w/general approach of rule UHRIGAR E Florida Power & Light Co 46FR19382 005 81 Docketing & Services Branch 3pp 19048 351 B3:C1 ,
- 8306300139 Parkage of three comments on proposed rule 10CFR40 **
 suspension of selected provisions of NRC U mill tailings susponsion of selected provisions of NRC U mill tailings requirements

 EVERTON: J A American Mining Congless * Sierra Club

 SHELLEY: W J Kerr-McGee Chemical Curp (*ubs of Kerr-McGee
 49FR23649 83/06/27 Cflicks J Office of the Secretary

 Commission 26pp 19122 067
- B30630019/ Comments on proposed rule 10CFR53 re-criteria & prive / for determining adequacy of available spent nuclear fuel storage capacity Opposes rule ONCAVAGE.N P. Floridians United for Safe Energy 48FR1932 B3/06/26 NRC No Detailed Affiliation Given 6pp 17::
- 8306300138 Comments on proposed rule (OCFP33 re criteria & proce for determining adequacy of available spent nuclear fuel stanage capacity Proposed rule does not provide for public participation
 BIALIK, C. I. New York, State of 48FR193B2 004
 Docketing & Services Branch 2pp 19119 310
- 8306300161 Comments on proposed rule 10CFR50 re NRC policy statery on severe accidents & related views on nuclear reactor regulation Opposes rule
 ONCAVAGE.M P Floridians United for Safe Energy 48FR16014 (
 83/06/26 NRC ~ No Detailed Affiliation Given 2pp 1911) (4
- 8306300169 Comments on proposed rule 10CFR20 re kept of theft or of licensed math GE concurs b/NRC conclusions that reporting requirements need reevaluation 3 rev VAUGHAN.C M General Electric Co 4BFR20721 005 83/06/23 Docketing & Services Branch 5pp 19122 292

- 8306300176 Comments proposed rules 10CFR50 to 51 re requirements for litensee actions or disposition of spent fuel upon espiration of reactor Dis Opposes rules BIALIN.E to New York, State of 48FR22730 001 83,06/23 Doctating & Services Branch app 19168 125
- B3CA30018D Commants on proposed rule 10CFR2O reliopts of theft or loss of licensed math Conflict exists reliards of loss of 10,12 5 mc1 Cs-137 sources
 CGLSMANN,P Affiliation Unknown 48FR20721 006 83/04/23
 Doctating & Services Branch lp 19048 361
- B306300195 Comments on proposed suspension of 10CFR40. App A re-portions of regulations dealing w/disposal of () mill tailings Opposes suspension FRISCO.D (Coalition for Nuclear Power Plant Postponement 46FR23649 007 83/06/26 NRC No Detailed Affiliation Given lp 19168 108
- B306360209 Comments on proposed rule 100FRb3 re critoria & procedures for determining adequacy of available spont nuclear fuel storage capacity Recommended changes to Sections 53 11. 53 126 b 53 28 listed CAREN.J Duquesne Light Co 48FR19382 013 83/06/27 Dotteting & Services Branch ip 19122 11/
- 8305300219 Package of two comments on proposed suspension of 10CFR40, App A re portions of regulations dealing w/disposal of U mill taillings JACGBI.W Colorado, State of SHUCY.C., SOUSA.M Southwest Research and Information Center 48823649 83/06/29 Doctating Services Branch 10pp 19168 098
- 9305300223 Package of two comments on proposed rule 10CFR53 recriteria y procedures for determining adequacy of available teach nuclear fuel storage capacity at civilian nuclear power reactors Supports rule
 MOROAN.R L Energy, Dept of KEARNEY, J J Edison Electric Institute 48FR19382 83/06/29 CHILK.S J Office of the Secretary of the Commission 20pp 19119 125
- B305300227 Comments on proposed rules 10CFR90 ½ 51 re requirements for licensee actions on disposition of spent fuel upon application of reactor CLs Opposes rules OMCAVAGE.41 P Floridians United for Safe Energy 4BFR22730 002 B3705/27 NRC No Detailed Affiliation Given 4pp 1916B 094

PRH PETITION FOR RULEMAKING

- B306060246 Forwards motion to dismiss Union Carbide Carp petition for rulewaking PRM-40-24 BERICK DM Environmental Policy Institute 47FR53889 83/04/27 CMILK SJ Dffice of the Secretary of the Commission Ip 18727 240
- --B306050248 Motion to dismiss Union Carbide Corp petition for rulemaking FRM-40-24 Mods proposed contrary to requirements of U Mill Tallings Control Act & Atomic Energy Act BERICK, D.M. Environmental Policy Institute 47FR33887 83/04/27 Commissioners 8pp 18727 241
- 8306060313 Potition for rulemaking PRM-50-36 requesting NRC amend 10CFR30 94(p), 50 54(q), 50 95(e), 50 57(h), 50 72(a), Part 30. App E, Section V, Section 73 71 & NUREGS on STS re reporting requirements REYNOLDS, N S., COTTINGHAM, A. Debevoise & Liberman 83/04/20 RAPP 19729 137
- 8306160465 Comments on petition for rulemaking PRM-40-24 re operation of U mills & disposition of U mill tailings Recommends patition be denied or postponed SHUEY. C. Southwest Research and Information Center 47FR3889 010
- PROJ PROJECTS PREDOCKET LIGENSING
- 830A02047! Summary of 830513 meeting w/C~E,VCPCO & Stience Applications. Inc Silver Spring, MD to discuss submittal & rev to topical rept re dry cask spent fuel storage ISFSI ICEMPD-2701 ROBERTS, J P Advanced Fuel & Spent Fuel Licensing Branch 83/05/18 ROUSE, L C Advanced Fuel & Spent Fuel Licensing Branch 3pp
- 8306140210 Forwards copyright notices to be posted in Topical Rept *REA 2023 Dry Storage Cask for DMR Spent Fuel " W/o encl TRAPPLO Ridiologh, Eggers & Associates 22299 83/00/16 ROUSE.L Office of Nuclear Material Safety & Safeguards, Director 369 18844 224

- 8306150167 Forwards application for withholding & proprietary repts,
 "Westinghouse Advanced PWR General Design Description" &
 "Westinghouse Advanced PWR Preliminary Ref Btd Plant Primary
 Side Safeguards Sys "Repts withheld (ref 10CFR2 790)
 RAHE.E P Westinghouse Electric Corp NS-EPR-2778 83/06/13
 EISENHUT.D G Division of Licensing 3pp 18850 040
- --B306150172 Application for withholding proprietary "Westinghouse Advanced PWR Preliminary Ref Std Plant Primary Side Safeguards Sys Module" HIESEMANN.R A Westinghouse Electric Corp AH-83-46 83/06/13 EISENHUT.D G Division of Licensing ip 19850 043
- 8304150214 Trip rept of site visit to observe test equipment operation & discuss waste mgt techniques w/DDE personnel & Dupont Corp List of participants encl BOYLE: R High Level Maste Licensing Management Branch CLARK: A T NRC No Detailed Affiliation Given B3/05/25 ROUSE: L. C NRC No Detailed Affiliation Given BLL: N J High Level Waste Licensing Management Branch 9pp 18870 034 24X Fiche 50-201,83/05/25, 8304:50214
- 8304220165 Summarizes 830608 meeting w/DDE in West Valley,NY re methods used by Dames & Moore to develop realistic seismic basis for design of structures & equipment for solidification of high level wastes at site List of attendees & agenda encl.

 CLARKA T Advanced Fuel & Spent Fuel Licensing Branch 83/06/15 RDUSE,L C Advanced Fuel & Spent Fuel Licensing Branch 3pp 18937 322
- 8306230213 Notification of 830606-10 meetings w/Gesellschaft for Nuklear Svc in Essen.West Germany to discuss topical rept on Model CASTOR Ic (SPE) & to visit machining & foundry facilities for CASTOR-type casks ROBERTS.JP Advanced Fuel & Spent Fuel Licensing Branch. 83/06/15 ROUSE.L C Advanced Fuel & Spent Fuel Licensing Branch. 2pp 18934 359
- 8306240369 Forwards notice of withdrawal of application for CP for publication in FR REGAN,W H Siting Analysis Branch (SSUANCES A 83/06/15, COMBS,T Docksting & Services Branch ip 18799 136
- --8306240380 Notice of withdrawal of application for CP REGAN.W H Siting Analysis Dranch ISBUANCES A 83/06/15 ip 18999 138
- 8306240370 Withdraws applications for copyright registration of topical regts for BWR & PWR spent fuel per 830324 & 25 telcon requests
 TRAPP.D Ridihalgh, Eggers & Associates 1098/83/106 83/05/25
 ROBERTS.J P Office of Nuclear Material Safety & Safeguards.Director ip. 18999 134
- B306240443 Forwards GA plan for design & fabrication of Ridihalph Eggers & Assoc 2023 dry storage casks for spent fuel & Rev 1 to plan PARKER!P E Ridihalph, Eggers & Associates B3/06/03 ROUSE, L C Advanced Fuel & Spent Fuel Licensing Branch. 3pp 18999 001
- --8304240446 Rev 1 to GA plan for design & fabrication of Ridihalgh, Eggers & Assoc 2023 dry storage casks for spent fuel poel. * Ridihalgh, Eggers & Associates 22329 83/04/04 21pp
- --8306240450 GA plan for design & fabrication of Ridihalgh, Eggers & Assoc 2023 dry storage casks for spent fuel pool
 # Ridihalgh, Eggers & Associates 22329 82/05/06 76pp
- 8306270355 Forwards proprietary viewgraphs used at 830517 meeting w/NRC re-review of design process for advanced control room for Wastinghouse Advanced PWR Meeting agenda provided. Viewgraphs withheld RAHELE P Westinghouse Electric Corp NS-EPR-2776 83/06/03 EISENHUT, D Q Division of Licensing 2pp 18993 306
- 8306270434 Provides addl justification re proprietary classification of Hestinghouse Advanced PWR licensing control document Overall concept of licensing control decument considered Hestinghouse proprietary info WIESEMANN, R A Westinghouse Electric Corp NB-RAW-83-477 83706/21 NEYER, C C Standardization & Special Projects Branch, 2pp 18993 117
- 8306280132 Expresses appreciation for T Clark & R Boyle cooperation & assistance in reviewing & evaluating processing & disposal of high level waste under Hest Valley Demonstration Project Act
 DAVIS, J O Defice of Nuclear Haterial Safety & Safeguards, Director. 83/06/15 HINDHAN, T. B Energy, Dept of, Savannah River Operations ip 19036 291

- 8306290566 Advises that DOE has selected borosilicate glass as waste form for immobilising West Valley high level wastes Appropriate tests of wastes required HANNUM.H H Energy. Dept of 22337 83/06/17 GLARK.A T Advanced Fuel & Spent Fuel Licensing Branch 1p 19047 198 24X Fiche 50-201.83/06/17.8306290566
- 8306270620 Forwards "Analysis of Terminal Waste Form Selection For West Valley Demonstration Project " Rept discusses basis for selection of borosilicate glass COFFMAN F E Energy Dept of 22038 83/06/14 DAVIS, J G Office of Nuclear Material Safety & Safeguards Director 2pp 19047 035 24x Fichs 30-201.83/06/14.8306270620
- --8306290626 MVDP-100
 "Analysis of Terminal Waste Form Selection for West Valley
 Demonstration Project"
 # Energy, Dept of 22338 83/06/14 24pp 19047 037 24X
 Fiche 50-201,83/06/14,8306290620
- PT21 NONCOMPLIANCE REPORTS AND RELATED CORRESPONDENCE
- 8304010055 final Deficiency Rept 83-24 re diesel generator lube oil & jacket water heaters not maintaining required temp Initially reported on 830421 Design Change Packages 28M-D0-029 & 36M-D0-029 issued to install new heaters
 VAN BRUNT, E.E. Arizona Public Service Co. 10CFR 050-55E 83/05/18 STERNBERG, D.M. Repion 5. Office of Director 3pp 18673-330 24 fiche 50-528,83/05/18,8306010055
- B3060102iB Part 21 rept re screw-clamp type bugs which may not form adequate commection when used w/14 SIS stranded wire Defective lugs identified as ILSCO Corp SLUH-90 ILSCO lugs replaced w/proper sized crimped commection ring lugs KENYON.B D Pennsylvania Power & Light Co PTZI B3-BB0-000 B3/05/25 ALLAN.J M. Region I. Office of Director 2pp 18673 003 24X Fiche 50-387.89/05/25.83060102iB
- 8306010272 Rev 2 to Final Deficiency Rept BER 82-78 re improperly crimped termination lugs in control panels for water chillers supplied by Carrier revising panel numbers initially reported on 821217 Also reportable under Part 21 VAN BRUNT.E E Artiona Public Service Co DER 82-78 83/05/16 81ERNBERG.D M Region 5. Defice of Director 3pp 18672 246 24 Fiche 50-528.83/05/16.8306010272
- 8306010274 Third Interim deficiency rept re sheared motor pinion keys in Limitorque motor operators Initially reported on 820830 Field change notices issued to replace keys Next rept will be sent by 830722 Also reportable per Part 21 MILLS.L M Tennessee Valley Authority 100FR 050 55E 83/05/25 0'REILLY.J P Region 2. Office of Director 2pp 18474 322 24X Fiche 50-000-83/05/25.8306010274
- B304010341 Rev 1 to final Deficiency Rept DER B1-29 re failure of ASTM A490 bolts Initially reported on B10521 Detective bolts replaced Insp program implemented to verify bolt tension Also reportable per Part 21 VAN BRUNT.E E Arisona Public Service Co 10CFR 050 55E 83/05/11 STERNERG.D M Region 5. Office of Director 4pp 18681 287 243 Ficha 50-529.83/05/11.8306010341
- B306010405 Fourth interim deficiency rept re failure of BIF butterfly valve seats Initially reported on B20511 Valves returned to BIF & tested satisfactorfly Final rept by B30801 Also reportable per Part 21 MILLS.L M Tennesses Valley Authority B00FR 030 556 B3/05/25 O'REILLY.J P Region 2, Office of Director 2pp 18679 328 24x Fiche 50-438.83/05/25.8306010405
- 8308010422 Interim deficiency rept re Gould Inc Class IE 480-volt motor control ctr protective gromment Initially reported on 830425 Mort Underway to implement listed corrective actions Next rept by 831216 Also reportable per Part 21 PARSONSIR M Carolina Power & Light Co 100FR 050-55E 83/05/25 0'REILLY.JP Region 2. Office of Director 4pp 18679-324 24X Fiche 50-400,83/05/25,8306010422
- 8306030220 Final Part 21 rept re deficienty in DS-416 reactor trip switchgear undervoltage attachment (SDR-83-07). Initially reported on 830421 Attachments to be replaced Also reported by Westinghouse per Part 21 SEIKEN.S J. Standardized Nuclear Unit Power Plant System PT21 83-882-000, 83/05/23 KEPPLER.J Q Region 3 Office of Director COLLINS.J.T. Region 4, Office of Director 3pp 18703-287 24X Fiche. 50-000.83/05/23,8306030220

- 8306070069 Part 21 rept is defective Woodward governor/activator.lpps EGB-13C Pointer discs machined to remove 1/16 inch from diameter Activator overhauled Util will replace brushes when spare parts available RODRIGUEZ.R J Sacramento Municipal Utility District PT21 B3-897-000 83/05/27 MARTIN.J B Region 5. Office of Director 3pp 18776 175 24X Fiche 50-312.83/05/27,83060/0069
- 8306070148 Deficiency reptire narrow range lesistance temp detectors installed to meet license condition failing to operate Cause under investigation Detectors replaced Testing modified until design revised Also reportable per Part 21 STEWART,N L. Virginia Electric & Power Co. 10CFR 050-55E B3/05/27 DENTON,H R. Office of Nuclear Reactor Regulation, Director CLARK,R A. Operating Reactors Branch 3. 2pp. 18736-266-24X Fiche. 50~339,83/05/27,8306070148
- 8306070160 Fifth interim deficiency tept re defects in reactor gratection & ESF actuation sys modules supplied by Bailey Meter Co Initially reported on 820414 B&W investigating use of yellowish bonding agent Also reportable per Part 21 MILLS, L M Tennessee Valley Authority 10CFR 050 59E 83/05/26 D'REILLY.J P Region 2. Office of Director 3pp 18736 288 24x Fiche 50-438,83/05/26,8306070160
- 8306070225 Final Deficiency Rept DER 83-23 re failure of MSIV bypass valves to close in required time Initially reported on 830419 Solenoid valve replaced Problem investigation request issued by Bechtel Also reported per Part 21 VAN BRUNT. E E Arizona Public Service Co DER 83-23 83/05/19 STERNBERG, D M Region 5, Office of Director Spp 18744 217 24% Fiche 50-528.83/05/19.8306070225
- 8306070231 Interim deficiency rept re main reactor trip breakers design discrepancy Initially reported on 830427 Westinghouse will replace undervoltage attachments, to accommodate new retaining ring Also reportable per Part 21 PARSONS, R M Carolina Power & Light Co IOCFR 050 55E 83/05/26 0'REFLLY.J P Region 2, Office of Director 4pp 18746 105 24x Fiche 50-400, 83/05/26, 8306070231
- 8304090135 Second interim deficiency rept re Henry Pratt butterfly valve Initially reported on 821109 Valve air-operator yoke mod kits delivered & mod in progress Operators removed & returned to GH Bettis Co Also reported per Part 21 MILLS.L M Tennessee Valley Authority 10CFR 050 55E 83/06/02 0'REILLY.J P Region 2. Office of Director 1p 18795 297 24% Fiche 50-000. 83/06/02.8306090135
- 8306090180 Third interim deficiency rept re reactor protection sys failure following secondary high energy line rupture Initially reported on 800707 Insulation of steam generator ref leg underway Also reportable per Part 21 PARSONS.R M Carolina Power & Light Co 10CFR 050 55E 83/06/01 O'REILLY, J P Region 2, Office of Director 4pp 18792 271 24X Fiche 50-400.83/06/01.8306090180
- B306090191 Third interim deficiency rept re potential damage to safety injection charging pump following secondary side high energy line rupture (Item 38) Initially reported on 800707 Resolution under review Also reportable per Part 21 PARSONS.R N Carolina Power & Light Co 100FR 030 55E B3/05/01 0'REILLYJ.P Region 2. Office of Director 4pp 18796 084 24X Fiche 50-400.83/05/01.8305090191
- 830&070242 Second interim rept. Item 117, re welding deficiencies on Class IE & 9 kV circuit breakers Initially reported on 830211 All breakers returned to vendor for fabrication Also reportable under Part 21 PARSONS, R M Carolina Power & Light Co 10CFR 050 53E 83/05/31 0'REILLY.J P Region 2, Office of Director 4pp 18795 332 24x Fiche 50-400.83/05/31.8306090242
- 8306090306 Part 21 rept re defective Moodward Governor Co activator. Type EGB-13C Pointer discs machined to reduce disc diameter Commission notified of potential generic problem Brushes in 125-volt dc motor found worn after overhaul by manufacturer RODRIGUEZ.R J Sacramento Municipal Utility District RJR 83-465 83/03/27 MARTIN.J B Region 3, Office of Director 4pp 18795 187 24X Fiche 50-312,83/03/27,8306090306
- 8306090310 Second interim deficiency rept me tube leaks in component cooling water HXs Initially reported on 830218 Corrosion pitting revealed by metallurgical exam Allous investigated for replacement MILLS.L M Tennessee Valley Authority 10CFR 050 55E 83/06/03 0'REILLY.J P Region 2. Office of Director 3pp 18795 193 24X Fiche 50-438,83/06/03,8306090310

- 8384100090 Part 21 rept re abnormal indications in upper core barrel bolting identified during ultrasonic testing initially reported on 830328 Samples to be removed from internals & riamined IAYLOR, H. Babcock & Hilcox Co. PT21 83-872-000 83/04/11 DEYQUKS, R. C. Director's Office, Office of Inspection and Enforcement 5pp. 18802-095 P4X Fiche 50-312.83/04/11.8306100090
- 830A100092 Part 21 rept re potential incorrect interface w/reactor pressure vessel instrument piping Caused by error on four local instrument panel piping diagrams field deviation disposition requests issued No operating plants affected SHERNOOD, 0 General Electric Co PTPI 83-801-000 82/11/18 DEYQUNGLR C Director's Office Office of Inspection and Enforcement 3pp 18802 226 24% Fiche 50-352.82/11/18.8306100092
- B305[00121 Part 21 status summary rept re GE activities Defects identified in Rosemount instrumentation, electrical separation & CR2940 switch tandem blocks APERCN,C A General Electric Co MFN 085/83 B3/05/13 MILLS,W R Director's Office, Office of Inspection and Enforcement 3pp 16002 183
- 8306100122 Part 21 Rept 82-10 re path of in-leakage in MSIV leakage control sys Path exists because valve not powered from critical bus Valve MS-V-146 will be powered from critical bus to assure that MSIV-105 can perform intended function CONN,N 6 Burns & Roe Co PT21 83-888-000 82/11/09 ENGELEBIR N Region 9. Office of Director 4pp 18802 031 24% Fiche 50-397,82/11/09,8306100122
- B30A100125 Part 21 rept re incorrect assembly of Vitro Labs 125-volt battery monitor used at site Faulty Zener diode will cause spartar to issue battery failure indication DEXON.D J General Electric Co PT21 B7-055-000 83/06/06 DEYQUMO.R C Director's Office, Office of Inspection and Enforcement ip 18802 010 24X Fiche 50-482.83/06/06.8306100125
- 8305100203 Part 21 rept re deficiency in wix emergency standby diesel generator sets mfg by Cooper Energy Svcs Jacket water heater 2 lube oil heater will be replaced w/40 kM & 19 kM versions, respectively, to maintain 120 F standby temp STOLBA-F 0 Cooper Industries, Inc. GCG 332 83/05/20 Director's Office, Office of Inspection and Enforcement 2pp 18806 007 24% Fiche 50-528,83/05/20.8306100203
- 8306100219 Sixth Interim Deficiency Rept PRD-82/14 re sheared bolts on diesel generator rear trankcase cover Initially reported on 820322 Deficiency reportable under LOCER'90 55(e) & Part 21 for Unit L.Biv II diesel generator only MCGAUCHY.JP Mississippi Power & Light Co. LOCER 050 55E 83705/01 D'RETLLY.JP Region 2. Office of Director App 18805 193 24X Fiche 50-416,83/06/01,8306100219
- B305100231 Interim deficiency rept ro use of defective math for pinion beys in Limitorque motor operators Initially reported on B20827 Also reportable per Part 21 Rept contains no proprietary info FDSTER.0 O Georgia Power Co 100FR 050 550 83/06/01 0'REILLY.J P. Region 2. Office of Director 5pp 18807 187 24X Fiche 50 424.83/06/01.8304100231
- 8396100233 Final Deficiency Rept PRD-83/06 or failure to provide corresion-resistant math in carbon steel instrument air penetration initially reported on 830319 Util preparing design change package Also reportable per Part 21 MCGAUGH/. JP Mississippi Power & Light Co 10CFR 050 55E 83/06/06 0 (REILLY, JP Region 2, Office of Director 4pp 18607 158 24X Fiche 50-416,83/06/06,8306100235
- B306100238 Interim deficiency rept re Item 127, shop weld defects in ITT Hammel Dahl chilled water valve Item also reportable under Part 21 Valve returned to manufacturer Final rept expected by 830901 PARSONS:R M Carolina Power > Light Co 10CFR 050 55C 83/06/03 O'REILLY.J P Region 2, Office of Director 4pp 18807 154 24 Fiche 30-400.83/06/03.8306100238
- G30610023i Final Deficiency Rept PRD-BP/P7 re potential for plant flooding based on PMP flood level Watertight door seals, too plate & curb to be installed % two penetrations raised Also reportable under Part 21 MCGAUGHY, JP Mississippi Power & Light Co 10CFR 050 SSE B3/03/31 0/REILLY, JP Region 2. Dffice of Director Spp 18807 149 24X Fiche 50-416,83/05/31,8306100251
- B306130:30 Part R1 rept re solenoid activated valves. Models 77C-001 & 77C-003 Defects include incorrect valve assembly, significant missing parts, limited switch valve position indication failures & failure of valve to open & close PUTTARINI.D M Target Rock Corp PT21 83-901-000 B3/06/07 DEYQUING.R C Director's Dffice. Office of Inspection and Enforcement 9pp 18824 267 24X Fiche 50-528,83/06/07.8306130150

- 8306130376 Interim Part 2: Rept DR-95 re possible defect in plate & face plate gaskets for Morrison-Knudsen Co hydrogen ignitor. Model 6043 Initially reported on 830204 Evaluation not completed Next rept to be submitted by 830711

 BDOKER, J C Oulf States Utilities Co PT21 83-896-000 83/06/06 COLLINS. J T Region 4. Office of Director ip 18822 346 24% Fiche 50-458,83/06/06,8306130376
- B306140435 First interim deficiency rept re DB-16 reactor trip breaker design error identified by Hestinghouse Initially reported on B30505 Undervoltage attachments will be replaced Next rept by B30926 Also reported per Part 21 MILLG.L M Tennessee Vallay Authority 100FR 050 55E B3/06/06 G'REILLY.J P. Region 2. Office of Director 2pp. 18838 035 24X Fiche 50-390, 83/06/06, 8306140435
- 8306140683 Part 21 rept supplementing 830506 notification of potential significant safety hazard re mat) defects in stainless steel tubing pressure boundary component Ultrasonic exam shows assemblies acceptable per ASME Code, Section III SCHERER, A E. Combustion Engineering, Inc. PT21 83-911-000, 83/06/07 DEYBUNG, R C. Director's Office, Office of Inspection and Enforcement ip 18842 066 24X Fiche 50-335,83/06/07,8306140683
- 8306160433 Part 21 rept re heat sinks on NLP card & NTC card relay Heat sinks will be replaced per enc! drawing Replacement relay being developed & tested RAME.E P Westinghouse Electric Corp PT21 83-902-000. 83/06/01. DEYCUNG.R C Director's Office. Office of Inspection and Enforcement 9pp 18860 217
- 8306160454 Pt 21 rept re-potential defect in transmitter mfg by Rosemount. Inclused in control sys of components furnished to listed plants All components involved retrofitted w/new circuit boards Matter closed OTROUX.E J. Carrier Corp. PT21 83-878-000 83/05/23 STELLO.V. Director's Office, Office of Inspection and Enforcement ip 18863 094 24% Fichs 30-518,83/09/23,8306160454
- 8306160470 Part 21 rept re broken spring-steel bands on 60 amp fuse clips ILSCO Corp requested to determine cause of breakage OE metallurgically testing broken bands DMYER.P W General Electric Co PT21 83-893-000 83/05/10 DEYGUNG.R C Director's Office, Office of Inspection and Enforcement 7pp 18862 253 24X Fiche 50-070.83/05/10.8306160470
- B306160316 Part 21 rept re 60 ampere FLSCO fuse holders All fuse clips subjected to 1 wk stress test & followup insp prior to installation of equipment DMYER:P H General Electric Co PT21 B3-B74-000 B3/06/08 DEYOUNG.R Director's Office, Office of Inspection and Enforcement Bap 18864 164
- 8305170250 Interim deficiency rept re-potential excassive offsite dose concerning feedwater containment penetrations not maintaining water seal for 30 days post-LOCA Also reportable under Part 21 CURTISN W. Pennsylvania Power & Light Co (IOCFR 050 35E 83/05/31 ALLAN, J M Region 1. Office of Director 4pp 18878 276 24x Fiche 50-388,03/05/31,8305170250
- B306170279 Final deficiency & Part 21 Repts U-53 rs defective plastic molding utilized in circuit boards supplied by Foxhoro Co Initially reported on B30511 Components returned to vendor for rework/replacement BCHNELL.D F Union Electric Co iOCFR 050 55E B3/06/01 KEPPLER.J Q Region 3, Office of Director ip 18977.024 24X Fiche 50-483,83/06/01,8306170279
- 8306200133 Interim Deficiency Rept 3 re Natson stud failures on Type 86 embed plates Initially reported on 821221 Unit 1 embed plates replaced w/surface mounted plates Final rept to be submitted by 830705 Also reported per Part 21 MCGAVGHYJ F Mississippi Power & Light Co 100FR 050 53E, 83706/07 0'REILLYJ P Region 2, 0ffice of Director App. 18703 285 24X Fichs 50-416,83/06/07.8306200133
- 8306200141 Sixth interim deficiency rept re Viting flow control valves in fire protection sys Initially reported on 811124 Drawing rev review continuing Next rept to be submitted by 830809 Also reportable per Part 21 MILL9.L M Tennessee Valley Authority 100FR 050 55E 83/06/07 074EILLY.J.P Region 2. Office of Director ip. 18903.264, 24x Fiche 50-438.83/06/07,8306200141
- B306210005 First interim deficiency rept re max temp inside containment Initially reported on B30513. Util requested BMM to respond to nonconformance rept by B30715 Next rept to be submitted by 830826 Also reported per Part 21 MILLS.L.M. Tennesses Valley Authority 100FR 050 55E, B3/06/13. 0'REILLY.J.P. Region 2, Office of Director 2pp 18912 283 24% Fiche 50-438.83/06/13.8306210005

- 83062100/9 Interim deficiency rept re lack of movement in ITT Orinnell snubber brackets Initially reported on 830429 All snubbers will be reinspected & design & Installation processes under review Final rept due Oct 1983 Also reported per Part 21 CURTIG.N W Pennsylvania Power & Light Co 10CFR 050 55£ 83/05/31. ALLAN, J M Region 1. Office of Director 4pp 18911 241 24% Fiche 50-388,83/05/31.8306210079
- 8306210112 Interim Part 21 rept re adequacy of circulating water pump house structure Analysis & design of needed structural mods for svc water pump house being performed & will be completed by 830819
 SARSTEN.Q E United Engineers & Constructors, Inc (subs of Raytheon Co) PY21 93-907-000 83/06/17 Director's Office, Office of Inspection and Enforcement 3pp 18914 108 24X
 Fichs 30-443.83766/17.8306210112
- 8306210116 Final deficiency rept re-solid state protection sys test procedures. Initially reported on 820831 Procedural change initiating use of test probe w/indicator lamp connected to ground implemented Also reportable under Part 21 MILLS, L.M. Tennessee Valley Authority 100FR 050 586 83/06/15 O'REILLY, J.P. Ragion 2, Office of Director 4pp 18914 098 24: Fiche 50-390.83/06/15,8306210116
- 8306220007 Part 21 rept re adequacy of fittings supplied by Tube-Line Corp through Capitol Pipe & Steel Products Co for use on new auxiliary feedwater headers of steam generators Flanges not heat-treated as required by matl specs TAYLORJUH Babcock & Wilcox Co PT21 B3-906-000 83/06/17 DEYQUNG.R C Director's Office, Office of Inspection and Enforcement 4pp. 18927 354 24X Fiche 50-000.83/06/17.8306220007
- 8306220015 Interim deficiency rept re sensitivity & density variations in Borg-Marner valve radiographs Initially reported on 830411 Sampling plan to determine valve acceptability established Final rept by 830710 Also reported per Part 21 EDELMAN M R Cleveland Electric Illuminating Co 100FR 090 55E 83/06/10 KEPPLER.J C Region 3. Office of Director 2pp 18927 938 24X Fiche 50-440.83/06/10.8306220015
- 8306220058 Final deficiency rept re potentially inadequate cooling of RCIC room during LDCA Initially reported on 830513 AE reviewing RCIC pump/turbine automatic start Review will be completed by 830727 Also reported per Part 21 EDELMAN M R Cleveland Electric Illuminating Co 100FR 050 55E 83/06/10 KEPPLER, J G Region 3, Office of Director 2pp 18930 034 24X Fiche 50~440,83/06/10,8306220058
- 8306230139 Forwards data sheet for Part 21 Rept 80-256-000 re defect in spent fuel cask unloading procedures.per TI1105/2(Rev 1) FISHER.W L. Region 3. Chicago. Office of the Director 80/10/21 H1061N80THAM.L Region 3. Chicago. Fuel Facility & Materials Safety Branch 1p 18782-066
- --8306230144 Forwards data sheet for Part 21 Rept 80-256-000 re defect in spent fuel unloading procedures. Completed data sheet should be returned by 801001 Comments on Part 21 rept enci HIOQINBOTHAM. L. Region 3. Chicago. Fuel Facility & Materials Safety Branch 80/08/27 DAVIS.A S. Region 3. Chicago. Fuel Facility & Materials Safety Branch 4pp 18982-067
- --8305230137 Part 21 rept re employee receiving dose of 30 710 rems to right hand on 800720 while removing particulate cartridge from water filter subsequent to cask flushing operation TOY.H L Battelle Hemorial Institute, Pacific Northwest Laboratory 80/08/19 KEPPLER.J G Region 3. Chicago, Office of the Director 4pp 18982 060
- 8306230277 Part 21 rept re defect in hose assembly 77379 Assembly welded w/60-degree rather 30-degree elbow installed Condition reported to Sechtel SHAFER, J C Metal Bellows Corp PT21 83-903-000 83/05/09 COLLING, J T. Region 4, Office of Director 4pp 18945-138 24X Fiche: 50-000, 83/05/09, 8306230277
- 8306230372 Part 21 rept re Brand-Rex Co Type 3/C 12 wire cable deficiency initially reported on 830613 8ix suspect wire reals quarentined. Records researched to insure suspect cable not used in Glass I areas.

 RODRIGUEZ: R J Sacramento Municipal Utility District, PT21 83-905-000, 83/06/16 MARTIN, J B. Region 5, Office of Director 4pp. 18942:300, 24% Fiche 50-312,83/06/16-8306230372
- 8306240191 Part 2: Evaluation Rept 83-07 re improperly sized overcurrent fuses in dc motor feeders. Initially reported on 830603 Fuses sized for 235% of full load current will be provided for jogging pump.
 VANDERBER.J. J. Burns & Roe Co. PT2: 83-904-000, 83/06/06 COLLING.J.T. Region 4, Office uf Director 16pp 18981 003. 24% Fiche: 50-397,83/06/06,8306240191.

- B306240196 Ack receipt of B30124 0211.0322 & 0425 ltrs informing NRC of steps taken to correct nonconformance noted in 0A Program Insp Rept 99700377/B2-01 POTAPQVS.U Region 4. Office of Director B3/06/17 ASHE.J Victoreen
- --8306240,204 Agrees w/Victoreen Part 21 evaluation of deficiencies in radiation modules, per 830413 request Position does not reflect add1 discrepancies identified in CPC 10CFR50 35(e) rept
 BANCARI, R. L. Division of Vendor & Technical Programs 83/05/05
 HIND, J. A. Division of Radiological & Materials Safety Programs ip 18980 268
- --8306240219 Responds to NRC 830119 ltr re nonconformance noted in QA Program Insp Rept 99900377/82-01 Corrective actions all outstanding purchase orders for printed circuit boards will be reviewed for inclusion of Part 21 requirements ZIMMERMAN.R Victoreen, Inc (subs of Sheller-Globe Corp) 83/02/11 POTAPOVS, U Regian 4, Office of Director 4pp 18980 274
- --8306240224 Forwards add1 support & background info re Victoreen workmanship & Part 21 Review & evaluation by K Stafford revealed defect not apparent in workmanship & notification to NRC not required ZIMMERMAN, R Victoreen, Inc (subs of Sheller-Globe Corp.) 83702/11 POTAPOVS, U Region 4. Office of Director 83pp. 18980 278
- 8306270223 Interim deficiency & Part 21 repts re boric acid transfer pumps. Westinghouse Shop Order 205. Item 113 Initially reported on 830113 Support bolting will be replaced & gusset stiffener spot welds supplemented by 830901 PARSONS.R M Carolina Power & Light Co PT21 83-919-000 83/06/14 O'REILLY. J P Region 2. Office of Director 4pp 18990 227 24% Fiche 50-400.83/06/14.8306270223
- 8306270228 Part 21 rept re improper latching between control rod drive shefts & control rod cluster assemblies in reactor vessel Initially reported on 830620 insp underway COUNSILW G Northeast Nuclear Energy Co (subs of Northeast Utilities) PT21 83-913-000 837/06/22 DEYOUNG,R C Director's Office, Office of Inspection and Enforcement 3pp 18988 237 24x Fiche 50-213,83/06/22,8306270228
- 8306270235 Final Deficiency Rept U-54 & Part 21 rept re failure of closed limit switches to reset on containment isolation valves HV-7126 & HV-7150 Initially reported on 830516 Compensating spring installed on actuating arm SCHNECL. D F Union Electric Co 100FR 030 55E 83/06/16 KEPPLER, J O. Region 3, Office of Director 1p 18988 250 24% Fiche 50~483, 83/06/16, 8306270235
- 8306270282 Potential Part 21 rept is discrepancy in welding of turnbuckle assembly, turnbuckle-bolt interface & on top plate assembly variable springs SA307 Grade B bolts not ASHE Bection IX mat! Investigation underway KARAGIANISIJ A Elcen Metal Products Co P721 83-922-000 83/06/17 KEPPLER. J G Region 3, Office of Director 2pp 18996 207 24X Fichs 50-000.83/06/17.8306270282
- 930.6270289 Part 21 rept re heat sink adhesive bond failures & NTC care relay problems within Westinghouse 7300 process sys Investigation underway to determine number of cards requiring heat sink replacement DIXON-O W Bouth Carolina Electric & Gas Co PT21 83-912-000 83/06/17 O'REILLY. J P Region 2. Office of Director App 18796 178 24X Fiche 50-375.63/06/17.8306270289
- 8306270346 Final Deficiency Rept PRD-83/07 re two Div II cables improperly routed outside scheduled conduit Initially reported an 830412 Design change package issued to rework cables Also reportable per Part 21 for Unit 1
 MCGAUGHY, J P Mississippl Power & Light Co AECM-83/0352
 83/06/14 D'REILLV, J P Region 2, Office of Director App 18946 222 24X Fiche 50-416.83/06/14.8306270346
- B306270439 Second Interim Part 21 Rept PRD-B3/08 re inability to maintain pressurized water supply to RHR pumps & discharge piping initially reported on B30415 Final rept expected by B40201 MCGAUGHY. J P. Mississippi Power & Light Co. PT21 B3-917-000 B3/06/13 0'REILLY.J P. Region 2. Office of Director 5pp 18992 067 24X Fiche 50-416.83/06/13.8306270439
- 8306280222 Revised final deficiency rept re DHR valve, Initially reported on 820212 Lower stem valve plug & lock pin replaced Control valve design sold to company not qualified as nuclear industry supplier Also reportable per Part 21 MILLS, L M Tennesses Valley Authority 100FR 050 55E 83/06/20 0'REILLY, J P Region 2, Office of Director 2pp 19014 185 247 Fiche 50~439,83/06/20,8306280222

- 8305280417 Part 21 Deficiency Rept 80 re damaged insulation on MCC Powers Co shielded multiconductor cable on HVAC control panels Also reported by MCC Power MEMPER.J 9 Philadelphia Electric Co PT21 83-916-000 83/06/01 MURLEY.T E Region I. Office of Director 1p 19020 296 24X Fiche 90-352.83/06/01.8306280417
- 8305280429 Fourth interim deficiency rept is B&W design of RCS supports 5 restraints Initially reported on 820601 Majority of blocks installed Shear bar evaluation expected by 830801 Also reported per Part 21 MILLS.L M Tennesses Valley Authority 10CFR 050 55E 83/06/20 0748ELLY.J P Region 2. Office of Director 2pp 19020 300 24 Fiche 50-438.83/06/20.8306280425
- 8305280426 Supplemental deficiency rept re post-accident readings from containment sump level transmitters Initially reported on 820708 Fuel load date rescheduled to Jan 1784 Also reportable per Part 21 MILLS.L M Tennessee Vailey Authority 10CFR 050 55E 83/06/17 O'REILLY.J P Region 2. Office of Director 1p 19018 350 24X Fiche 50-390.83/06/17.8306280426
- 8304280463 Interim deficiency rept re Item 121, welding deficiencies in main steam/feedwater support frames Instially reported on 830318 Estension requested until 830715 to submit complete evaluation Also reportable per Part 21 par85085.R M Carolina Power & Light Co 10CFR 050 55E 83/06/17 O'RESILIY, J P. Region 2. Office of Director in 19018 294 24X Fiche 50-400.83/06/17.8306280463
- B306280479 Final deficiency rept re improperly welded chiller unit piping components Initially reported on 820111 Radiographic eram to be performed on all safety-related chiller piping Also raportable per Part 21 HILLS.I. M Tennessee Valley Authority 100FR 050 35E 83/06/17 0'FEILLY.J P Region 2. Office of Director 3pp 19020 116 24) Fiche 50-438.83/06/17.8306280479
- 8306300018 Final Part 21 evaluation rept re potential failure of Brown Boveri Model HPL-C speed switches for component cooling pump & syc water pump motors Initially reported on B30624 Failed motor replaced & defective motors repaired DIMON.D W South Carolina Electric & Gas Co B3/06/24 D'REILLY.J P Region 2, Office of Director 3pp 19120 234 24x Fiche 50-395, 03/06/24, 8306300018
- B306300051 Sixth interim deficiency rept re failure of Limitorque motor operators during valve closure Initially reported on B20126 Mestinghouse & Limitorque determining cause of failures Next rept expected by B30928 Also reportable per Part 21 MELSIL M Tennessee Valley Authority 100FR 030 35E B3/06/22 GTRECLY.J P. Region 2. Office of Director 2pp 19120 193 24X Fiche 50-390, B3/06/22, B306300031
- 83063G0159 Part 21 rept re spot welds in Bailey Controls Co cabinets w/smaller diameter than specified Cabinets strengthened by team & edge welding or bolting TAYLOR.J H Babcock & Wilcox Co 83/06/23 DEYBUNG,R C Director's Office, Office of Inspection and Enforcement 2pp 1919 308 24X Fiche 50-000.83/06/23.8306300159
- 8305300192 Final Part 21 rept on Item 133 re safety injection valves made of carbon steel instead of stainless steel Initially reported on 830524 Valves of correct mail reordered & incorrect valves retagged PARSONS.R M Carolina Power & Light Co PT21 83-920-000. 83/06/22 0FREILLY.J P Region 2. Office of Director 4pp 19122 187 24X Fichs 50-400.83/06/22,8306300192
- B306300202 Part 21 rept re short-term reliability problem w/position indicating mechanism in solenoid valve used to control PDRV 3750010 Magnet position indicating mechanism replaced on 830307 Corrective action in progress JOHNSON.V M Garrett Corp PT21 B3-891-000 B3/05/09 Director's Diffice, Diffice of Inspection and Enforcement 3pp 19122 123 24X Fiche 50-389.83/05/09.8306300202
- B306300220 Part RI rept re loose locking clips used to secure terminal boards to rear terminal panels of safety-related instrument cabinets initially reported on 821203 All B&W plants notified

 TAYLOR, J. H. Babcock & Wilcox Co. FT21 83-908-000 82/12/03

 DEYOUNG, R.C. Director's Office, Office of Inspection and Enforcement 4pp 19121 356 24X Fiche 50-269,82/12/03,8306300220

QAPPP QUALITY ASSURANCE INSPECTIONS

B306070108 Ack receipt of 830407 & 0519 ltrs informing NRC of steps taken to correct nonconformance noted in GA Program Insp #apt 99700793/B3-01.
P074P0V8.U Region 4, Office of Director B3/06/02 MACBRYDE.M & Unibrate Corp 1p 18739.158

- --8306070109 Submits revised response to NRC 830228 ltr re Section II, Item B nonconformance noted in GA Program Insp Rept 99900793/83-01 Corrective actions Section 4 4 2 of identification & verification manual rewritten MACBRYDE.M B Unitrare Corp 83/05/19 POTAPOVS.U Region 4, Office of Director 2pp 18739 159
- --B306070iiO Responds to NRC B30228 ltr re nonconformances noted in GA Program Insp Rept 99900793/83-01 Corrective actions 10CFR21 posted on employee bulletin board, new Procedure GCP-3-83-1 implemented & tags prepared for incoming welding matl MACBRYDE. N B Unibrate Corp B3/04/07 PQTAP6VS, U. Region 4, Office of Director 7pp 18739 161
- 8306070158 Ack receipt of 830512 ltr informing NRC of steps taken to correct nonconformances noted in QA Program Insp Rept 79790796/82-01
 PUTAPOVS.U Region 4, Office of Director 83/06/02 AMBIELLI.U Custom Alloy Corp ip 18736 211
- --B304070163 Responds to NRC B31223 ltr re nonconformances noted in GA Program Insp Rept 99900796/82-01 Corrective actions GA vendor audit rept files will be reviewed upon completion of audit & weekly audits of completes travelers conducted BAXTER.D Custom Alloy Corp B3/05/12 CDNMAY.J T Region 4, Office of Director 5pp 18736 212
- 8306070168 Ack receipt of 830421 ltr informing NRC of steps taken to correct monconformance noted in GA Program Insp Rept 99900403/83-01 POTAPOVS.U Division of Vendor & Technical Programs 83/06/02 BRUGGEMAN.W H General Electric Co 1p 18739-001.
- --B306070171 Responds to NRC B3032B itr re nonconformance noted in GA Program Insp Rept 97900403/83-01 Corrective actions: component procedure delineating requirements per design memo will be issued by B30601 CA neweletter will be issued BOHL.L B General Electric Co B3/04/21 POTAPOVS,U Region 4, Office of Director 2pp 18739 002
- 8306070288 Ack receipt of 830518 ltr informing NRC of steps taken to correct monconformance noted in GA Program Insp Rept 979700387/83-01
 PDIAPDVS.U Region 4, Diffice of Director 83/06/02 BISSDNNETTE, P.
- PDTAPDUS U Region 4, Dffice of Director 83/04/02 BISSONNETTE, P GA Technologies: Inc /General Atomic Co ip 18741 173
- --8304070274 Responds to NRC 830420 ltr re manconformance noted in QA Program Insp Rept 99900387/83-0i Corrective actions, product quality dept manager replaced Training, production & product quality operating procedures etrengthened BISSGNNETTE, P QA Technologies, Inc /Oeneral Atomic Co 83/05/18 COLLING, J T Region 4, Office of Director, 12pp 18741 174.
- 8306070305 Ack receipt of 830210 & 0301 ltrs informing NRC of steps taken to correct monconformance noted in QA Program Insp Rept 7990792/82-01 POTAPOVS, U. Region 4: Office of Director 83/06/02 HARRINGTON, Q W. Greeneville Metal Manufacturing, Inc. 1p.
- --B306070308 Responds to NRC B30110 ltr re nonconformance noted in GA Program Insp Rept 97900792/82-01 Addl info not available when B30210 response to notice of nonconformance formulated, HARRINGTON, 0 W Oreeneville Metal Hanufacturing, Inc. B3/03/01, POTAPOVB, U Region 4: Office of Director. 3pp. 18740-320,
- ---8306070312 Responds to NRC 830110 ltr re nonconformance noted in QA Program Insp Rept 99700792/82-01. Corrective actions: condition re induced shear wave angle not considered nonconformance based on insp findings HARRINGTON.0 W Greeneville Metal Manufacturing, Inc. 83/02/10 POTAPDVB.U Region 4. Office of Director 2pp 18740:323.
- 8306070331 Ack receipt of 830316 ltr informing NRC of steps taken to correct nonconformance noted in GA Program Insp Rept 97900002/83-01 PDTAPUVS.U Region 4. Office of Director 83/06/02 LICHTENBERGER Combustion Engineering. Inc. 1p. 18741 074.
- --8306070336 Responds to NRC 830421 ktr re nonconformance noted in 9A Frogram Insp Rept 97900002/83-01 Corrective actions: travelers will have math release numbers recorded prior to issuance & sign off individual reinstructed LICHTENBERGER Combustion Engineering, Inc. NGA 83-008 83/05/16 POTAPOVB, U. Region 4, Office of Director 2pp. 18741:075.
- 8304130113 Advises that inep results re significant corrections & changes to ADLPIPE computer code documented in encl QA Program Insp Rept 97700535/83-01, Paragraph D. 2. Item closed. W/o encl POTAPOVS, U Division of Vendor & Technical Programs. VITS 83-46-83/06/08. MERRILL, D. Events Analysis Branch ip 18824:278.

- B306:30194 Forwards GA Program Insp Rept 99900522/83-01 on B303:4-18 & notice of violation PdTAPQVS.U Region 4, Office of Director B3/05/23 STATTON.C D Becktel Corp 2pp 18826-274
- --8306/30216 Notice of violation from insp on 830314-18 * Division of Vendor & Technical Programs 83/05/23 ip 18826 276
- --8306130224 GA Program Insp Rept 99900322/83-01 on 830314-18
 Noncompliance noted Part 21 not specified on safety-related matl requisition to procurement agreement did not incorporate matl requisition requirement COSTELLO, J.R., BEAUX. D.G., INSERT. A.G., Program 4, Defice of Director 83/05/17 20pp 18826 277
- B306130397 Forwards QA Program Ins; Rept 99900535/83-01 on 830328-30 & notice of violation POTAFDVS,U Region 4, Office of Director B3/05/23 DINGWELL.I W DIB/ADLPIPE, Inc. 3pp IBB22 219
- --8306130402 Notice of violation from insp on 830328-30 * Region 4, Office of Director 83/05/23 tp 18822 222
- --8306130410 QA Program Insp Rept 99700535/83-Di on 830328-30 Noncempilance noted failure to notify users of ADLPIPE Code error yielding nonconservative stress values Noncempilance reported per Part 21 by B&R BRICKLEY,R H, HALE,C J Division of Vendor & Technical Programs 83/05/06 10pp 18822 223
- 8306130413 Forwards QA Program Insp Rept 99900906/83-01 on 830314-17 & notice of noncomformance POTAPOVS/U Region 4. Office of Director 83/05/23 MOLNAR, J American Environments Co 3pp 18823 II7
- --9306130416 Notice of nonconformance from insp on 830314-17 * Region 4, Office of Director 83/05/23, 1p 19823 120
- --8306130422 QA Program Insp Rept 99500906/83-01 on 830314-17
 Noncompliance noted QA procedures not type appropriate
 to fully or completaly describe activities affecting quality
 & duties of data manager not established
 BMITM A L . PHILLIPS H S Region 4. Office of Director 83/03/02
 15pp 18823 121.
- B306160548 Ack receipt of B30510 & 27 ltrs informing NRC of steps taken to correct nonconformance noted in GA Program Insp Rept 99900053/B3-01
 POTAPOVB.V Region 4. Office of Director B3/06/13 CAROD.A E Anchor/Darling Valve (subs Anchor/Darling Industries) ip 18865 060
- --8306160556 Responds to NRC 830412 itr re nonconformance noted in QA Program Insp Rept 9990053/83-01 Corrective actions tys being developed to insure qualification repts are reviewed for adequacy & completeness Sys to be implemented by 830601 KNIESER.O W Anchor/Darling Valve (subs Anchor/Darling Industries). 83/05/27 PDTAPDVS.U Region 4. Office of Director 1p. 18865-061
- --8306160578 Responds to NRC 830412 ltr re nanconformance moted in GA Program Insp Rept 97900053/83-01 Corrective actions waterford valves fitted W/shrouds & heaters to maintain actuator ambient temp & mods to feedwater valve reconciled KNIESER, G H Anchor/Darling Valve (subs Anchor/Darling Industries) 83/05/10 PUTAPOVS.V Region 4, Office of Director 2pp 18865 062
- 8306210001 Confirms QA program insp on 830620-24 at Waltham, MA plant per 830517 telcon POTAPDVS-U Region 4, Dffice of Director 83/05/26 SPRAGERS, C. Q Teledyne Engineering Bervices 1p 18711 359
- B306210013 Forwards QA Program Insp Rept 99900902/83-01 on 830330-0401 No noncompliance noted PGTAPONS.U. Region 4. Office of Director B3/05/27 HOLBROOK.W W Wyle Laboratories 2pp. 18910 337
- --8306210020 QA Program Insp Rept 99900902/83-01 on 830330-0401 No nontempliance noted Major areas inspected QA program manual, GA program implementation & action on previous insp items JOHNSON A R: PHILLIPS. H S Region 4. Office of Director SALAZAR. R A Sandia Laboratories 83/05/26 15pp 18910 339
- 3306210023 Ack receipt of 830510 ltr informing NRC of steps taken to correct nonconformances noted in GA Program Insp Rept 97900911/93-01, PGTAPOVS. U. Region 4, Office of Director 83/06/03 BRUGOEMAN. W. H. Oeneral Electric Co. ip 18711 245

- ---B30621002B Responds to NRC B30413 ltr re nonconformances noted in QA Program Insp Rept 99900911/B3-01 Corrective actions Engineering Nork Authorization EA/08-22 issued on B21101 & Engineering Review Memorandum DMD-4025 issued on B21222 B0NL.L S General Electric Co B3/03/10 POTAPOVS.U Region 4, Office of Director 3pp 18911 246
- 8306210025 Forwards GA Program Insp Rept 99900060/83-01 on 830314-18 No noncompliance noted PdTAPDV6.U Region 4. Office of Director 83/05/27 PATTARINI.D H Target Rock Corp 2pp 18911 249
- --8306210031 GA Program Insp Rept 99900060/83-01 on 830314-18 No noncompliance noted Major areas inspected TVA Part 21 rept on safety relief valve failure at Browns Ferry Unit 2 KELLEY.W D. BARNES.I Region 4. Office of Director 83/05/26 10pp 18911 251
- B304210030 Ack receipt of B30513 ltr informing NRC of steps taken to correct nonconformance noted in GA Program Insp Rept 99900793/83-01 POTAPOVS.U Region 4. Office of Director B3/04/17 LOTT.J & E.L. Manufacturing Peebles. Inc. Ip 18912 292
- --B306210033 Responds to NRC 830421 ltr re nonconformance noted in QA Program Insp Rept 99900799/83-01 Corrective actions 1006821 subscription ordered on 830510 Current issue, dtd 821230, posted on 830323 PLANK,R A EL Manufacturing Peebles, Inc 89/05/13 PUTAPDVS.U Region 4, Office of Director 3pp 18912 293
- B306210069 Confirms GA program insp on B30627-30 at Acton,MA facility, per B30512 telcon PDTAPOVS,U Region 4. Office of Director 83/06/06 COWDREY,R S Acton Environ Testing Corp ip 18912 310
- 8306210172 Confirms GA program insp on 830606-10 at Dradell, NJ plant. per 830429 telcon POTAPOVS,U Region 4. Office of Director 83/05/26 HENDRICKSON. r Burns & Roe Co 1p 18915 242
- 8306210185 Confirms GA program insp on 830620-24 at Canton, OH plant per 830831 telcon POTAPUS, U Region 4, Office of Director 83/06/03 O'DEAY, C A Nocley Manufacturing Div 1p 18914 130
- 8306210215 Provides status rept of open item identified in QA Program Insp Rept 99900060/83-01 Modified pilot valve must be tested & safety/relief valves must operate within design pressure tolerance W/o encl POTAPOVS.U Division of Vendor & Technical Programs F02700282 83/06/17 LEWIS.R C Division of Project & Resident Programs Ip 18918 119
- 8306210230 Forwards GA Program Insp Rept 99900104/83-01 on 830329-31 Ł notice of honconformance POTAPUB.U Region 4. Office of Director 83/05/27 MILLER, T D Hestinghouse Electric Corp 2pp 18915 218
- ---8306210233 Notice of hanconformance from insp on 830329-31 * Region 4, Office of Director 83/05/27 2pp 18915 220
- --8306210238 QA Program Insp Rept 99900104/83-01 on 830329-31 Noncompliance noted Inconel weld band detail for primary nozzle const not identified in technical manual & customer drawing OLLER.R E , POTAPDYB.U , BARNES,I Region 4, Office of Director 83/03/26 17pp 18915 222
- 8304210244 Discusses GA Program Insp Rept 99900104/83-0; on 830329-3; Failure to depict Income! weld band on steam generator norzies limited to technical manual & drawings furnished to specific facility W/o encl insp rept PDTAPDVS, U Division of Vendor & Technical Programs 83/06/17 MARTINIT T Division of Engineering & Technical Programs ip 18916 350
- B306210272 Forwards QA Program Insp Rept 99900921/83-01 on B30425-29 notices of violations & nonconformance POTAPOVS, U. Region 4, Office of Director B3/06/01 SA0010MO, A J Franklin Institute/Franklin Research Center 3pp 18914 280
- --8306210274 Notice of violation from insp on 830425-29
 * Region 4. Office of Director 83/06/01 lp 18914 283
- --8306210282 Notice of nonconformance from insp on 830428-29 * Region 4, Office of Director 83/06/01 3pp 18914 284

- --8306210286 GA Program Insp Rept 97900921/83-01 on 830425-29
 Noncompliance noted failure to develop procedures for
 training record maint GA responsibilities & identification
 of deviations from approved test procedures
 HUBBARD. © T . PHILLIPS. H S Region 4, Office of Director
 83/05/25 22pp 18914 287
- B306210278 Confirms GA program insplat Cleveland. OH plant on B30627-0701.ger B30531 telcon pOTAPOVS.V Region 4. Office of Director B3/06/08 ASHE. J Victoreen. Inc. (subs. of Sheller-Globe Corp.) ip 18914 309
- 8305230401 Responds to 830505 ltr re GA program Any changes to NRC approved topical rept GA program must be reported & approved prior to implementation PDTAPOVS.U Region 4. Office of Director 83/06/08 BOBTROM.D G Anacond
- --8306230404 Requests info ro NRC approved GA programs per 830405 maeting EDG#RDM.D O Anaconda Co (subs of Atlantic-Richfield Co) 83/05/06 BELKE.W Region 4. Office of Director 1p 18943 128
- B306240180 Submits findings of recent QA program insp of Sargent & Lundy design activities re mechanical snubber problems Raview of piping design criteria requested BANGARTR L Division of Vendor & Technical Programs B3/06/17 VOLLMER.R H Division of Engineering 2pp 18981 033
- 8305240196 Act receipt of 830124.0211.0322 & 0425 ltrs informing NRC of steps taken to correct nonconformance noted in QA Program Insp Rept 99900377/82-01
 PDTAPOUS U Region 4. Office of Director 83/06/17 ASHE, J
 Victoreen Inc (subs of Sheller-Globe Corp.) ip 18980 245
- --B306240201 Responds to NRC 830317 ltr re nonconformance noted in QA Program Insp Rept 9790037//02-01 Corrective actions std operating procedures rewritten re printed circuit boards & purchasing documents updated 2[MMERMAN.R D Victoreen, Inc (subs of Sheller-Globe Corp.) B3/04/25 POTAPOVS.U Region 4. Office of Director 2pp 18980-266
- --B306240204 Agrees w/Victoreen Part 21 evaluation of deficiencies in madiation modules, per B30413 request Position does not reflect add1 discrepancies identified in CPC 10CFR50 55(e) rept BANGART,R L. Division of Vendor & Technical Programs B3/05/05 H1ND.J A Division of Radiological & Materials Safety Programs 1p 18980 268
- ~-8306240207 Ack receipt of 830317 itr re QA Program Insp Rept 99900377/B2~01 R Zimmerman will respond to issues raised BTEMART.E C Victoreen, Inc (subs of Sheller-Clobe Corp) B3/03/22 POTAPOVB.U Region 4. Office of Director ip 18980 269
- --8306240209 Ack receipt of 830211 ltr informing NRC of steps taken to correct nonconformance noted in GA Program Insp Rept 79900377/82-01 Add1 info required re actions taken to prevent recurrence of obsolete documents on purchase orders FOTAPOVS.U Region 4. Office of Director 83/03/17 AGHE.U Victoreen, Inc. (subs. of Sheller-Globe Corp.) ip 18980-270
- --8306240214 Ack receipt of GA Program Insp Rept 99900377/82-01 No sproprietary info IthmerMAN.R Victoreen, Inc (subs of Sheller-Globa Corg.) 83/02/11 POTAPOVS.U Region 4. Office of Director in 18980-273
- --8305240219 Responds to NRC 830119 ltr re nonconformance noted in QA Program Insp Rept 99900377/82-01 Corrective actions all outstanding purchase orders for printed circuit boards will be reviewed for inclusion of Part 21 requirements ZIMMERMAN.R Victoreen, Inc (subs of Sheller-Olobe Corp.) 83/02/11 POTAPOVS.V Region 4, Office of Director 4pp 18980-274
- --8306240224 Forwards add1 support & background info re Victorean workmanship & Part 21 Review & evaluation by K Stafford revealed defect not apparent in workmanship & notification to NRC not required IMMERHANN R Victorean, Inc (subs of Sheller-Globe Corp) 83/02/11. POTAPOVS.V Region 4. Office of Director 85pp 18780 278
- --8306240227 Responds to NRC 830117 ltr re nonconformance noted in QA Program Insp Rept 97900377/82-01 Extension requested for response to permit review of data as to appropriateness of release of ltr to PDR
 ASHE, J. Victoreen, Inc. (subs of Sheller-Globe Corp.) 83/01/24
 POTAPOVS, U. Region 4, Office of Director. 1p. 18981,002

- 8306240237 Ack receipt of 830426 ltr informing NRC of steps taken to correct nonconformance noted in QA Program Insp Rept 979700510/83-01,
 POTAPOVS, U Region 4, Office of Director 83/05/26 CURRANE, R A United Engineers & Constructors. Inc (subs of Raytheon Co.) 1p 18780 178
- --8306240243 Responds to NRC 830331 ltr rs nonconformance noted in GA Program Insp Rept 99700510/83-01 Corrective actions procedures reviewed to ensure consistency & GA audit frequency increased CURNANE. R A United Engineers & Constructors. Inc (subs of Raytheon Co) 83/02/02 PQTAPOVS.U Region 4, Office of Director 2pp 18980 179
- --8304240245 Supple 830202 response to NRC 830331 ltr re nonconformance noted in GA Program Insp Rept 99700510/83-01 Corrective actions calculation review program instituted & procedures to be revised by 830527 CURMANE, R A United Engineers & Constructors, Inc (subs of Raytheon Co.) 83/04/26 COLLINS, J T Region 4, Office of Director 4pp 18780.181
- 8306240289 Ack receipt of 830516 ltr informing NRC of steps taken to correct nonconformance noted in QA Program Insp Regt 99900749/83-01 POTAPOVS.U Region 4, Office of Director. 83/06/03 HESB,L R. Pacific Air Products Co 19 18979 227
- --8306240293 Responds to NRC 830415 ltr re nonconformance noted in GA Program Insp Rept 99900769/83-01 Corrective actions tab folding problem resolves, dampers corrected & stricter insp processes instituted by Air Balance. Inc DBBSON. J P Patific Air Products Co B3/05/16 PDTAPDVS, U Region 4. Diffice of Director 13pp 18979 228
- B30627045R Forwards QA Program Insp Rept 99900356/83-01 on 830321-24 & O414 & notice of honconformance POTAPOVS, U Region 4. Office of Director 83/06/01. ROSS, P. Husky Products. Inc 2pp 18992 098
- --8306270453 Notice of nonconformance from insp on 830321-24 * Division of Vendor & Technical Programs 83/06/01 ip
- --8306270456 GA Program Insp Rept 99900356/83-01 on 830321-24 & 0414 Noncompliance noted current organization does not conform to requirements & engineering personnel performed insps on operations affecting quality on three Class IE jobs. SUTTON-J M., BARNES.I Ragion 4. Office of Director 83/05/26 12pp 18972 101
- 8306280127 Confirms QA program insp at Cakland.CA plant on 830711-15 per 830523 telcom. PDTAPGVB.U Region 4. Office of Director. 83/06/22 BDYER.R E. Transamerica Dalayal, Inc. 1p. 17018-184
- B306280404 Summary of B30502 Mgt meeting w/Intl Nutronics in Dover,NJ re NRC equipment qualification program PHILLIPG.H B Region 4, Office of Director B3/06/22 Region 4, Office of Director 2pp 19001 335
- 6306280577 Summary of 630525 mgt meeting & site tour w/ANCO Engineering in Culver City, CA re equipment qualification program PHILLEPS.H S Region 4, Office of Director 83/06/22 Region 4, Office of Director 2pp 17017 322

REGOD REGULATORY QUIDES

- 8306020420 Comments on draft Reg Ouide IC 127-5; "Griteria for Programmable Digital Computer Bys Software in Safety Sys of Nuclear Power Cenerating Stations," Option A & reg guide will benefit public VIVIRITO,M A Olibs & Hill; Inc (subs. of Dravo Corp.) 83/05/20, Docketing & Services Branch ip 18693-204
- 8306130004 Requests authorization to use encl ASME Code Case N=343, "Alternative Scope of Exam of Attachment Welds for Exam Categories D=NB=K-1 & CC Section XI. Div 1 " Rev 2 to Reg Ouide 1 147 will include code case w/no addl requirements. BDUGHEY, D Washington Public Power Supply System CD2-83-482 83/06/02 SCHMENCER. A Licensing Branch 2 2pp 18824-248. 24X Fiche: 50-397.83/06/02,8306130004.
- 8306140712 Concurs w/830510 mamo re insider sefequards rule package, sub; to appropriate consideration of comments. Encl comments also address concerns contained in RF Burnett 830414 memo re protection of vital areas/islands, DENTON-H R Defice of Nuclear Reactor Regulation, Director, 83/06/01 DAVIS.J O Office of Nuclear Material Safety & Safeguards, Director 5pp 18852-274

- --B306140718 Forwards revised insider safeguards rule package containing encl action plan to implement recommendations of Committee to Review Safeguards Requirements at Power Reactors Concurrence requested by B30927 DAVIS.J C Office of Nuclear Material Safety & Safeguards Director B3/05/10 DENTON.H R Office of Nuclear Reactor Regulation. Director CUNNINGHAM.O H Office of the Executive Legal Director HINDOUE.R B Office of Nuclear Regulatory Research, Director 196pp 18852 279
- 8306160443 Comments on draft Reg Guide IC 127-5. "Criteria for Programmable Digital Computer Sys Software in Safety Sys of Nuclear Generating Stations " Endorses use of IEEE Std 730 1 ANBI/IEEE-ANS-7-4 3 2 BUDZIK.D M Consumers Power Co DMD 24-83 83/06/09 Docketing & Services Branch Spp 18860 207
- B306160446 Comments on Reg Guide 1 36, "Chemical Analysis of Thermal Insulation Hatl for Leachable Chloride, Fluoride, Silicate & Bodium Ions " WHIFAKER, T.E., American Society for Testing & Materials 83/05/31 Office of the Secretary of the Commission 2pp 18863 113
- 8306160451 Comments on draft Reg Quide IC 127-5, "Criteria for Programmable Digital Computer Sys Software in Safety Sys of Nuclear Cenerating Stations " Suggests Option A be selected MALLAY.J F American Nuclear Society 83/08/01 Docketing & Bervices Branch 2pp 18863 111
- 8306i&04&0 Package of three comments on draft Reg Guide IC 127-5.
 "Criteria for Programmable Digital Computer Sys Software in
 Bafaty Sus of Nuclear Power Generating Stations"
 ELLIOTT, J. L., ROMLAND.O D. Duke Power Co. BURSIEIN, 8 Wisconsin
 Electric Power Co. 83/06/09. Docketing & Services Branch 7pp.
 18863.051
- 830616046B Package of two comments on draft Reg Guide IC 127-5, "Criteria for Programmable Digital Computer Sys Software in Safety Sys of Nuclear Generating Stations" BUDZIK, D.M. Consumers Power Co. ALLEN.R E. Power Engineering Boclety 83/06/13 Docketing & Services Branch Spp. 1886/3 234
- 8306170284 Package of two comments on draft Reg Ovide (C-127-5, "Criteria for Programmable Digital Computer Sys Software in Safety Sys of Nuclear Power Generating Sys "
 RAHE: E P Westinghouse Electric Corp NILSON.R Erkon Nuclear Co , Inc. (Subs of Erkon Corp) NB-EPR-2779 83/06/13 CHILK: S J Office of the Secretary of the Commission 3pp 18877 271
- 8306200334 Advises that implementation date for Reg Guide 1.137, "Fuel Dil Bys for Standby Diesel Generators," delayed until 840201 Revised schedule necessary due to excavation required to install new fuel oil tank, per DCP 390 CAREV. J J Duquesne Light Co 83/06/09 VAROA. 8 A Operating Reactors Branch 1 ip 18919-214 24X Fiche 50-334,83/06/09, 8306200334.
- 8306220143 Reg Quide A 18 Task WM 013-4, "Std Format & Content of Environ Repts for Near-Surface Disposal of Radwaste " # Office of Nuclear Regulatory Research, Director #3/06/30 40pp 18977:076
- --8306220148 Value/impact assessment of Reg Guide 4 18 Task HM 013-4, "8td Format & Content of Environ Repts for Near-Surface Disposal of Radwaste " a Office of Nuclear Regulatory Research, Director, 83/06/30 2pp 18977:136
- 8306220192 Draft Rev 2 to Reg Ouide MS 701-4 & value impact statement, "Identification of Valves for inclusion in Inservice Testing Programs"

 # Office of Nuclear Regulatory Research, Director 83/03/31 74pp
- B306230414 Comments on draft Reg Quide IC 127-5, "Criteria for Programmable Digital Computer Sys Software in Safety Sys of Nuclear Power Cenerating Sys " BROEMLAD J. Portland Ceneral Electric Co 83/06/10 Docketing & Services Branch 2pp 18743 188
- 8306230419 Comments on draft Reg Guide IC 127-5, "Criteria for Programmable Digital Computer Sys Softwars in Sefety Sys of Nuclear Power Generating Sys "Recommends Option B SCHEMERA.E. Combustion Engineering, Inc. LD-83-055 83/06/16, Docksting & Services Branch ip 18943.205
- 8306230425 Comments on draft Reg Quide IC 127-5. "Criteria for Programmable Digital Computer Sys Software in Safety Sys of Nuclear Power Generating Sys." Recommends Option A. FARRAR, D.L. Commonwealth Edison Co. 6728N 83/06/07. Docketing & Bervices Brench ip. 18943-214

- 8306230523 Discusses AIF proposal detailing info in one-step license application Proposal in form of rewrite of Reg Guide 1 70, "Std Format & Content of SARs for Nuclear Power Plants" will illustrate level of design detail required DIRCKS.W J Office of the Executive Director for Operations NB30311 B3706/16 CHILM.S J Office of the Secretary of the Commission 1p 18951 396
- B306240049 Reg Guide i 147.Rev 2, "Inservice Insp Code Case Acceptability, ASME Section XI. Div 1 " * Office of Nuclear Regulatory Research, Director 83/06/30 6pp 18785 173
- 8306240115 "For Comment" issue of draft Reg Guide ES 114-4, "Guidelinas for Groundwater Monitoring at In Situ U Solution Mines "
 • Office of Nuclear Regulatory Research, Director 83/06/30 33pp 18978-233
- --8306240118 Draft value/impact assessment of proposed Reg Guide E6 114-4, "Guidelines for Groundwater Monitoring at In Situ U Solution Mines " Reg Guide establishes technical guidance on hydrologic monitoring * Office of Nuclear Regulatory Research, Director 83/06/30 dap 18798 266
- 8306300100 Comments on draft Reg Guide IC 127-5, "Criteria for Programmable Digital Computer Sys Software in Safety Sys of Nuclear Power Generating Sys " Recommends use of ANSI/IEEE-ANS-7-4 3 2~1982 be limited KOESTER.G L Kansas Gas & Electric Co KMLNRC 83-075 83/06/17 Docketing & Services Branch ip 19121 072
- RES RESEARCH AND TECHNICAL ASSISTANCE REPORTS
- 8306010478 "Evaluation of Methods for Reducing Pressure Vessel Fluence," monthly rept for Mar 1983 ARCHBON-A L Battelle Memorial Institute, Pacific Northwest Laboratory CAREM.JF, COKINOS.D M Brookhaven National Laboratory BNL-NUREG-32876 83/03/31 LOIS,L, DUNENFELD.H Division of Systems Integration (post 811005) Sipp 18475 171
- 8306020048 "Reliability Assessment of Nuclear Structural Sys " REIGH, M. HWANG, H. Brookhaven National Laboratory BNL-NUREG-32748 B3/06/01 NRC - No Detailed Affiliation Given 14pp 18702 307
- 8306020683 "Seismic Qualification of Nuclear Plant Mechanics) & Electrica Equipment," Monthly Progress Ltr 16 for Apr 1983 KANA, D. D. Southwest Research Institute NRC-04-81-185 83/05/11 CAMPBELL, W. Gffice of Nuclear Regulatory Research, Director Opp
- 8306030435 "Ranking of Environs in Stress-Corrosion Cracking " NEMMAN,R C , BANDY,R Brookhaven National Laboratory BNL-NUREG-32824 83/05/31 NRC - No Detailed Affiliation Given 9pp 18735 350
- 8306070422 "Investigation of Accident-Induced Flow & Matl Transport in Nuclear Facilities." monthly progress rept for Apr 1983 MARTIN.R A., OREOORY, W.S. Los Alamos Scientific Laboratory FJN A-7029 83/05/27 Transportation & Materials Risk Branch Spp 18782 019
- 8306080229 "Matis Properties Data for Fusion Reactor Analysis." internal technical rept HAGRMAN.D.L. EG&O. Inc. 83/04/30 NRC - No Detailed Affiliation Oliven 219pp 18785 102
- 8306170205 "Ranking Safe Shutdown Readiness for FY83,84 & 85 Reactor Safe Shutdown Insps " THOMAS.H J, MACDOUGALL.E Brookhayen National Laboratory FIN A-3133 83/05/31 NRC - No Detailed Affiliation Given 96pp 18881 043
- 8306240241 "HAARM-3 Users Manual "
 OIESEKE, J A , LEE, K W , REED, L D Battelle Memorial Institute,
 Columbus Laboratories NRC-04-76-293-07 BMI-NUREO-1991 78/01/05
 Division of Reactor Safety Research 72pp Available at NT18
 18987 139.

REVIEW ORP NRC RESEARCH REVIEW GROUPS

8306030509 Informs that each LRG-II member must submit numerical value determined by GE for respective plants on fuel assembly lift off displacement, due to error in fuel assembly topical rept ra LRG-II Generic Issue 2-CPB NDVAK:T.M Assistant Director for Licensing 83/05/23 HOLIZSCHER.D L Licensing Review Group II 3pp 18735,051 24% Fichs 50-000,83/05/23,8304030509,

B306060303 Notification of CRGR Meeting 41 on 830608 to review draft MVREQ-0801. "Evaluation Criteria for Detailed Control Room Design Reviews" & draft NVREQ-0835. "Human Factors Review Quidelines for Safety Parameter Display Sys "
STELLO. V Regional Operations & Generic Requirements B3/06/02 MATTSON. R J Office of Nuclear Reactor Regulation. Director VORDAN. E L Director's Office. Office of Inspection and Enforcement CUNNINGHAM. R E Office of Nuclear Natural Safety & Safeguards. Director 121pp 18729 202

8306060373 Responds to B20903 ltr submitting position papers which included Licensing Review Group II proposed solution for Issue 4-MEB, intended to protect in-core instrument tubes from flow-induced vibration Issue unresolved YDUNGBLOOD, B J. Licensing Branch 1 83/05/26 HOLTZSCHER, D L Licensing Review Group II 4pp 18751 287 24X Fiche 50-000, 83/05/26, 8306060373

B305050414 Transcript of Ad Hoc Committee for Review of Nuclear Reactor Licensing Reform Proposals 830525 meeting in Washington,DC Pp 1-167 Supporting documentation encl * Commissioners B3/05/25 190pp 18748 159

B304070440 Requests concurrence w/encl package % comments re resolution of Generic Issue B-10."Behavior of BWR Mark III Centainment " ROVAK. T M Assistant Director for Operating Reactors B3/05/27 EIBENHUT, D 9 Division of Licensing 3pp 18780 312

BJ06080188 NUREG-0880 R01 FC 9AFETY QUALB FOR NUCLEAR POWER PLANT OPERATION • Office of Policy Evaluations B3/09/31 [16pp 18789 143

B3060B020/ Summary of CROR Meeting 3B on 83051B re presentation of proposed rule on pressurized thermal shock of reactor pressure vessels Committee supports proposed rule BEELLO. V Regional Operations & Generic Requirements 83/05/31 DRCKB-W J Office of the Executive Director for Operations 3pp 18771 269

8364130233 Forwards, "Shaking Table Testing for Seismic Evaluation of Electrical Raceway Sys," in response to BEP Topic III-06, "Seismic Design Considerations" Rept must be referenced on individual dockets to apply to specific plants KACICH, R M SEP Cluners Group KACICH, R M Northeast Utilities 83/04/29 RUSSELL, W.T Systematic Evaluation Program Branch ip 19837 288

---830543023B URB/JAB 8050

*Shaking Table Testing for Seismic Evaluation of Electrical Raceway Sys "

** URB Corp ** John A Blume & Associates, Engineers (subs URB Corp) 83/04/30 122pp 18827 269

8306130383 Advises of cancellation of CRGR Meeting 41 to permit NRR to resyaluate NUREO-0801. "Evaluation Criteria for Detailed Control Room Design " & NUREO-0835. "Human Factors Review Quidelines for Bafety Parameter Display Sys "
STELLO. V Regional Operations & Generic Requirements 83/06/09 MATISON: R J Office of Nuclear Reactor Regulation Director JORDAN, E L Director's Office Office of Inspection and Enforcement CUMNINGHAM, R E Office of Nuclear Material Safety & Bafeguards, Director ip 18822 215

8306160600 Clarifies 830516 article from Inside NRC, in response to 830516 request Views expressed in presentation considered views of author & not necessarily views of Commission TOURTELL OTTE: J Regulatory Reform Task Force 83/06/14 WEISS, E R Union of Concerned Scientists 2pp 18884 357

B305280370 Summary of CROR Meeting 39 on B30525 re proposed overall revito IOCFR71 on packaging of radioactive math for transport & transportation of radioactive math under certain conditions Attendance list end:

BTELLD, V Regional Operations & Generic Requirements 83/05/20, DIRCKB.V Office of the Executive Director for Operations 859 19001-232

B306270564 Responds to B30419 mamb to potential safety problems in use of health physics barriers integrated assessment of all access controls recommended DENTON, H R Defice of Nuclear Reactor Regulation, Director B3/06/07 DAVIS. J G Office of Nuclear Material Safety & Bafaguards, Director ip 19047 186

--8306290567 Discusses Committee to Review Bafeguards 830228 rept identifying use of barriers established for health physics & fire protection as potential safety problem Action requested DAVIS. J 9 Office of Nuclear Material Safety & Bafeguards, Director 83/04/19 DENTON, H R Office of Nuclear Reactor Regulation, Director ip 17047 187 SECY POSITION PAPERS GEFORE THE COMMISSION

B30A030366 Add1 response to FDIA request for BECY-82-36B, BECY-82-475 & BECY-82-36B SECY-82-475 available in PDR BECY-82-36B withheld entirely (ref FDIA Exemption 5) FELTON, J M Division of Rules and Recards B3/04/01 BUCKLEB,R Affiliation Uninown 2pp 18734 290

---8306030370 SECY-B2-475
Informs of resolution of reactor coolant pump trip issue
(TMI Action Plan Item II K 3 5)
DIRCKS.W J Office of the Executive Director for Operations
82/11/30 55pp 18734 292

8304030383 Responds to FDIA request for documents re exploration, mining or milling of U in specific areas In State of NE Forwards documents listed in app FELTON, J M Division of Rules and Records 83/04/01 REID, A B, Broken Plow Law Office 2pp 18747 149

--8204070018 SECY-82-127
Recommends Commission reassert regulatory authority over
State of NE U mining & milling activities to protect public
health & safety.per Governor Thone request
DIRCKE,W J Office of the Executive Director for Operations.
82/03/23 2pp 18747 153

B306060104 Responds to FDIA request for BECY-81-645, SECY-81-654 & SECY-82-162A SECY-81-645 & SECY-81-654 pertain to AGS noticed in 46F861020 Forwards SECY-82-162A FELTON, J K Division of Rules and Records 83/03/29 QRABER, L Affiliation Unknown ip. 18750 353

---8306060108 BECY-82-162A
Forwards integrated plan for development of rule for shift craw qualifications.
DIRCKG-W J Office of the Executive Director for Operations 82/08/26 7pp 18750 354

8306160093 Add) response to FOIA request for documents re IAEA nuclear mat1 safeguards program Forwards App A documents App B Documents I-8 entirely withheld & Documents 9-16 partially withheld (ref FOIA Exemptions 1.3 & 5) FELTON.J M Division of Rules and Records 83/04/01 OREENBERG.E V Tuttle & Taylor Spp 18892 011

---8306160193 BECY-82-025
Forwards H Orwann preliminary comments on Horgan memo re
IAEA safeguards for 811119 press conference SECY title &
other safeguards info deleted
DIRCKB.W J Office of the Executive Director for Operations
82/01/19 8pp 18892.146

--8306160198 BECY-82-046
Informs Commission of existing interagency groups involved in UB efforts to upgrade IAEA safeguards & provides brief rept on status of activities W/o encl outline & status of action plan DIRKGS W J. Office of the Executive Director for Operations 82/02/02 13pp 18892 134

--8306160208 SECY-82-210
Forwards summary of significant NRC & Executive Branch
efforts to improve IAEA safeguards & estimate of expended
resources Safeguards info deleted W/o encl rept on US
assistance to IAEA & outline of areas needing improvements
DIRGKS/W J Office of the Executive Director for Operations
82/05/26 17pp 18892 170

--8306160216 BECY-82-313
Informs Commission of receipt of Dept of State 820702 ltr
re classification of Morgan rept State agrees that rept
should be classified "secret " Bafeguards info deleted, H/o
listed encls
DIRCKS.W J. Office of the Executive Director for Operations,
82/07/26 2pp 18892 282

B306240403 BECY-B3-219
Provides status rapt on LWR accident source term
reassessment including revised schedule 3 milestones for
source term & severa accident research program
DIRCKS,M.J. Office of the Executive Director for Operations
83/06/06 14pp 18977 339

STATE PROG STATE PROGRAMS

- 8306020035 Speech entitled. "Rept on MRC Activities." presented at 5th Annual Natl Conference on Radiation Control in Reno.NV on 830516 KERR.O W Office of State Programs. Director 83/03/16 6pp 18702 326
- 830&0203&6 Confirms discussion W/JD Luberau. DA Nussbaumer & JW Hornor following review & evaluation of State of AZ radiation control program Significant problems re technical quality of licensing actions & status of regulations identified MARTIN. J B Region 5. Office of Director 83/05/25 TEDFORD. C E Arizona. State of 17pp 18694 331
- 8306020459 Notification of contract execution to "Radiation Monitoring Program Requirements" Contractor State of NE MCDERMOTT, D Technical Assistance Contracts Branch FIN D-8508 NRC-31-83-670 83/05/16 MEVERS, D M Region 4, Office of Director NICHOLAS, J B NRC - No Detailed Affiliation Given 1p 18715 234
- --8306020463 Contract "Radiation Monitoring Program Requirements," awarded to State of NE SMITH.H D Nebraska, State of MORTGN.K V Division of Contracts FIN 8-8508 NRC-31-83-670 63/05/16 10pp
- 8306020496 Speech entitled "Radiation & Regulation," presented at 830523 annual meeting of Assoc of State & Territorial Health Officials in Washington.DC KERR.O W Office of State Programs, Director 83/05/23 Sap 18715-184
- 8306030277 Notification of contract execution, Mod | to "Radiation Monitoring Program Requirements" Contractor State of AR MCDERMOTT, D Technical Assistance Contracts Branch FIN B-8500 NRC-31-83-667 83/05/20 MEYERS, D M Region 4, Office of Director NICHOLAS, J B NRC No Detailed Affiliation Given 1p 18733 324
- --8306030284 Mod 1.increasing funding to FY83 levels to "Radistion Monitoring Program Requirements" * Arkansas, State of MORTON.K V Division of Contracts FIN B-8300 NRC-31-83-667 83/05/20 ip 18703-325
- 8306030383 Responds to FDIA request for documents re exploration, mining or milling of U in specific areas in State of NE Forwards documents listed in app FELTON.JM Division of Rules and Records 83/04/D1 REID.A B Broten Plow Law Office 2pp 18747 149
- --8306030388 Approves encl draft FR natice re reassertion of certain regulatory authority in State of NE (SECY-82-127) CHILK.S J Office of the Secretary of the Commission 82/04/20 DIRCKS,W J Office of the Executive Director for Operations App 18747 157.
- --8306030390 Forwards notice of issuance b availability of reassertion of certain regulatory authority in State of NE KERR, O W. Office of State Programs. Director 82/04/26 COM88, T R Correspondence & Records Branch 1p 18747 163
- --8306030395 Notice of issuance & availability of reassertion of certain regulatory authority in State of NE KERR.G W Defice of State Programs, Director 82/04/26 3pp 18747 164
- B306040222 Requests 830722 meeting to discuss results of B30718-22 regulatory review of radiation control program Review will cover principal administrative & technical aspects of program ALLAN, J M Region 1, Office of Director 83/05/27 CANNON, J E Rhode Island, State of 1p 18728-012
- 8306060417 Forwards draft version of proposed SD/DQE cooperative agreement Agreement formally initiates efforts to implement remedial actions to stabilize & control U tailings RQMATOMENT, R © Energy Dept of 83/03/20 JANKLOW, W South Dakota, State of 45pp (875) 001
- 8306130336 Responds to 830505 ltr re radiation control program Staff reinstructed to dispatch enforcement ltrs within 2 wks of insp & radiation control section manager will review all insp rapts SPELL,M H Louisiana, State of 83/06/02 COLLINS,J T, Region 4, Office of Director 2pp 18822 361

- 8306140185 Summarizes 830105 discussion w/D Nussbaumer & K Schneider re Agreement State compatibility concerning financial assurance requirements for long-term care at low level radwaste burial sites Proposed criteria changes to be finalized LOHAUS.P H Low Level Waste Licensing Branch 83/05/18 MIOGINDOTHAM.L Low Level Waste Licensing Branch 2pp 18844 187
- 8306140331 Forwards Waste Mgt Group, Inc (WMG) response to 6 NRC 5 States of NV & SC comments on State of NV Consumer Health Sycs comments re WMG topical rept concerning RADMAN Code to document low level waste Input needed by 830327 W/o encl NUSSBAUMER. D Assistant Director for State Agreements Programs 83/03/12 VAPEN, J Nevada, State of 1p 18854 121
- 8304150485 Notification of contract execution "Radiation Monitoring Program Requirements," awarded to State of LA MCDERMOTT.D Technical Assistance Contracts Branch FIN 8-8502 NRC-31-83-649 83/06/01 MCVERS.D M Region 4. Office of Director NICHOLAS.J B NRC - No Detailed Affiliation Given ip 18868-00:
- --8306150488 Contract "Radiation Monitoring Program Requirements,"
 awarded to State of LA
 SIMONCAUX.F P Louisiana, State of MORTON.K V Administrative
 Contracts Branch FIN 8-8502 NRC-31-83-669 83/06/01 18pp
 18868 002
- 8306190574 NUREC/BR~0028 VOT N5 INFORMATION REPORT ON STATE LEGISLATION KERR, G W , LANDAU, M Office of State Programs, Director 83/06/30 11pp 18854 336
- B306160691 Forwards in-process OL amend requests currently being evaluated by NRC. in response to final rules, effective B30506. specifying that when licensees request amend to OL. licensee must notify appropriate State designae TOURIONY. E O Operating Reactors Branch 3 B3/06/06 SIMMONS, H E North Dalota, State of 2pp 18876 288 24X Fiche 50-285.83/06/06. B306140691
- B306200101 Requests B30902 meeting to discuss results of State of Mi radiation control program meeting scheduled for wk of B30B02 Adequacy & compatibility of program will be evaluated ALLANUM Region 1. Office of Director B3/06/10 WALLACE, W Y New Hampshire, State of 2pp 18903 334
- B304220166 Notification of contract execution "Radiation Monitoring Program Requirements," awarded to State of MD MCDERNOTT, D Technical Assistance Contracts Branch FIN 0-0353 NRC--28-93-608 83/06/16 MCDSCAR, J Region 1, Office of Director COSTELLO,F NRC No Detailed Affiliation Given ip 18737 309
- ---8306220168 Contrart "Radiation Monitoring Program Requirements," awarded to State of MD RESH.D L. Maryland, State of * NRC ~ Nd Detailed Affiliation Given FIN B-8353 NRC-28-83-608 83/06/16 13pp 18937 305
- 8306220244 Notification of contract execution, Mod [to "California Offshore Radiological Licensee Survey " Contractor State of CA MOYLE. A Administrative Contracts Branch FIN 8-8705 NRC-05-82-254 83/06/10 BLAHA. J L Program Support Branch YACZKO,C T NRC No Detailed Affiliation Given 1p 18951 [14
- --8306220246 Mod 1.extending period of performance to 830630.to
 "California Offshore Radiological Licensee Survey"
 * California, State of REBELLD.J E Division of Contracts FIN
 B-8705 NRC-05-82-254 83/06/10 ip 18951 (15
- 8306230485 Netification of contract execution.Mod 1 to "Radiation Monitoring Program Requirements" Contractor State of TX SILVIB.R M Technical Assistance Contracts Branch FIN 8-8504 NRC-31-83-671 83/66/14 MEYERS.D M Region 4. Office of Director NICCHROLAS.J B NRC No Detailed Affilsation Given 1p
- --8306230491 Mod 1.providing CY83 funding & changing B&R number to 94-19-30-02, to "Radiation Monitoring Program Requirements" MACLEAN.R Texas, State of GUSTAVE, R P Technical Assistance Contracts Branch FIN 8-8504 NRC-31-83-671 83/06/14 ip 18982 041
- B306230494 Notification of contract execution.Mod 2 to "Radiation Monitoring Program Requirements" Contractor State of NE SILVIS.R M Technical Assistance Contracts Branch FIN B-8503 NRC-31-83-670 B3/06/15 MEYERS.D M Region 4. Office of Director NICHOLAS.J B NRC No Detailed Affiliation Given ip 18982 03B

- --8306230496 Med 2, providing CY83 funds, to "Radiation Monitoring Program Requirements "
 BECK,R # Nebraska, State of GUSTAVE.R P Technical Assistance
 Contracts Branch FIN 8-8503 NRC-31-83-670 83/06/15 1p
- B305230507 Notification of contract execution, Mod 1 to "Radiation Monitoring Program Requirements" Contractor State of OR SILVIS.R M Technical Assistance Contracts Branch FIN 8-8554 MRC-32-83-685 83/06/15 ALEXANDER.I Office of Resource Management. Director HAMADA.G NRC No Detailed Affiliation Given 1p 18782 029
- --8306230509 Hod 1.providing funds for CYB3.to "Radiation Monitoring Program Requirements" Oregon, State of CUSTAVE.R P Division of Contracts FIN B-8554 NRC-32-83-685 83/06/15 ip 18982 030
- 8305270372 Responds to 830104 ltr expressing NRC concern over technical quality of State of NH licensing program for radioactive matls New comprehensive forms, associated licensing guides matis new comprehensive forms, associated licensing guides & checklists will make review process MALLACE.N T New Hampshire, State of 83/04/27 HAYNES,R C Region 1, Office of Director 2pp 18993 206
- 8304280242 Ack receipt of 830301 ltr & confirms RS Heyer 830511 discussions w/Graham & Simmons re State of NE radiation control program Significant compliance problems identified at Univ of NE at Lincoln COLLINS.J T Region 4. Office of Director 83/04/21 SMITH.H D Nebraska, State of 2pp 19014 195
- VENDOR REPORTS AND RELATED CORRESPONDENCE TOPREP
- 8304110936 Forwards financial info for Connecticut Light & Power Co & Western Massachusetts Electric Co for 1982 Rept for Northeast Nuclear Energy Co will be available on or about 830415 830415 BJBHDP,R W Northeast Utilitios 83/04/05 Office of Nuclear Reactor Regulation, Director 71pp 17916 P48 24X Fiche 50-245,83/04/05,8304110936
- B306010314 Submits update on B&W Owners Group plans to install shunt trip feature to reactor trip sys scram breakers Arkansas Power & Light Co will submit design info during wk of 830530 Owners group endorses facility shunt trip design WALLACE.E 0 Babcock & Wilcox Operating Plants Owners Oroup WALLACE.C G. General Public Utilities GPU Service Corp 83/05/27 EISCHNUT.D O Division of Licensing 1p 18672 310 24X Fiche 50-313.83/05/27.8304010314
- B306020364 Forwards Amend 2 to Rev 3 to "Ederer Nuclear Bafety-Related Extra-Safety & Monitoring (Y-SAM) Cranes " Rept withheld (ref 1007R2 790) CLARK,C W Ederer, Inc 83/05/27 THOMAS,C Standardization & Special Projects Branch 2pp 18693 185
- B3GAO20471 Summary of B3O513 meeting w/C-E,VEPCO & Science Applications, Inc Bilver Bpring, MD to discuss submittal & rev to topical rept re dry cask spent fuel storage IBFSI (CENPD-270) ROBERTS. J P
 - Advanced Fuel & Spent Fuel Licensing Branch 83.
 Advanced Fuel & Spent Fuel Licensing Branch 3pp 83/05/1B ROUSE, L. C.
- 8306020692 Requests payment for review of GA program Rev 6 Invoice will be sent MILLER, W.O. License Fee Management Branch 83/05/20 KCFARLAND, J.E. Bargent & Lundy, Inc. 1p. 18715-325
- --8306020696 Requests billing for review of GA program, Rev 6 BILLER, W.D. License Fee Management Branch 83/05/20 MANION, W.E. Financial Operations Branch 1p 18715-326
- 8306030338 Endorsament 62 to MAELU Policy MF-54

 # Nuclear Energy Liability Insurance Association
 Marsh & McLennan, Inc. 83/04/21 ip. 18705 020 HUGHES R J
- --8304030339 Endorsement 76 to NELIA Policy NF-187 * Nuclear Energy Liability Insurance Association Marsh & McLennan: Inc. 83/04/21 ip. 18705 021 HUGHES, R J
- 8396030476 Forwards draft Sections 1 & 2 of May 1983 revised RADMAN topical rept Views on Section 2 requested W/o encl TUITE.P T Waste Management Group. Inc 83/05/12 ROLES.O Low Level Waste Licensing Branch 1p 18735 247

- 8306030509 Informs that each LRG-II member must submit numerical value determined by GE for respective plants on fuel assembly 11ft off displacement, due to error in fuel assembly topical rept re LRG-II Generic Issue 2-CPB NOVAN.T M Assistant Director for Licensing 83/05/23 HOLTZSCHER, D.L. Licensing Review Group II 3pp 18735-051 24X Fiche 50-000,83/05/23,8306030509
- 8306060174 Summary of 830518 meeting w/Westinghouse re review of Mestinghouse generic safety parameter display sys concerning MCAP-10170, "Emergency Response Facility Design & V&V Process" Vendor will append man-in-the loop results DICK-0 F Operating Reactors Branch 5 LSO5-83-06-007 B3/02 CRUTCHFELD, D Operating Reactors Branch 5 170p 18728 164 Fiche 50-244,83/06/02,8306060174 83/04/02
- 8304070147 Application to amend License DPR-35, revising Tech Specs to expand operating region of power/flow map & provide associated changes in average power range monitor flux scram 5 rod block trip settings (Proposed Change 83-05) HARRINGTON, H D Boston Edison Co 83-139 83/05/31 VASSALLO, D Edison Co 83/05/81 VASSALLO, D E VASSALLO, D B
- --8304070174 NEDD-22198 "GE BHR Extended Load Line Limit Analysis for Pilgrim Nuclear Power Station Unit 1 Cycle 6 " FISCHER, D L , GRIDLEY.R L General Electric Co 82NEDO84 82/09/30 21pp 18739 016 24X Fiche 30-293,83/05/31.8306070167
- 8306070272 Forwards BAW-1784. "B&W Owners Group Bolting Task Force Bummary Rept of NRC/B&W Owners Group 830506 Meeting on Reactor Vossel Internals Bolting "Agrees w/overall findings.w/exception re neutron noise surveillance TUCKER.H B Duke Power Co 83/05/31 DENTON.H R Office of Nuclear Reactor Regulation. Director 2pp 18744 086 24X Fiche 30-269.83/05/31,8396070272
- --8306070280 Forwards BAH-1784, "B&H Owners Croup Bolting Task Force Summary Rept of NRC/B&H Owners Group 830506 Meeting on Reactor Vessel Internals Bolting "TAYLOR.J H Babcock & Hilcox Operating Plants Cwners Group 83/05/20 MiNER.S NRC No Detailed Affiliation Given ip 18744 088 24X Fiche 50-269.83/05/31.8306070272
- --8306070286 BAW-1784
 "B&W Cuners Group Bolting Task Force Summary Rept of NRC/BW Dumers Group 830506 Meeting on Reactor Vessel Internals Bolting"
 - Internals Bolting "

 * Babcock & Hilcox Co 83/05/31 124pp 18744 089 24X
 Fiche 30-269,83/05/31,8306070272
- 8306080105 Requests generic approval of NEDE-22290 "Safety Evaluation of QE Type I Hybrid Control Rod Assembly " Requests issuance of generic SER by 830727 KLAPPROTH, J F General Electric Co MFN 094-83 83/05/20, THOMAS.C NRC No Detailed Affiliation Given ip 18773 054
- 8306090045 Forwards proprietary Rev 1 to XN-NF-524(P), "Exxon Nuclear Critical Power Methodology for BWRs," per GF Clusiwy 800530 1tr CHANDLER, J.C. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.) JCC 067-83 63/06/06 THOMAS, C.O. Standardization & Special Projects Branch 1p 18792-345
- 8306090154 Forwards proprietary version of Suppl 2 to Rev 2 to "RODEX2 Fuel Rod Thermal Mechanical Response Evaluation Model" Rept provides sample calculation of BMR fuel performance garameters Rept withheld (ref 10CFR2 790) CHANDLERJ C Exxon Nuclear Co . Inc (subs of Exxon Corp) UCC 065 83 83706/02 THOMAS. C 0 Standardization & Special Projects Branch 1p 18792 344
- 8306070267 Forwards safety evaluation of BMR Owners Group response to NUREO-0737. Item II K 3 18. "Mod of Automatic Depressurization Sys Logic "Acceptable options include alimination of high drywall pressure permissive CRUTCHFIELD. D Operating Reactors Branch 5 LS05-83-06-016 B3/06/08 CDUNSIL-W 9 Northeast Nuclear Energy Co (subs. of Northeast Utilities) 2pp 18775 280 24% Fiche 50-245,83/06/08,830A070267 8304090247
- -8306090272 Safety evaluation of RMR Elemens Group response to NUREG-0737. Item II K 3 18, "Mod of Automatic Depressurfiation Sys Logic ." Acceptable options include elimination of high drywell pressure permissive 9 Office of Nuclear Reactor Regulation, Director 83/06/018795 282. 24X Fiche 50-245.83/06/08.8306090267 83/06/08

- 8304070363 Notification of 830407 meeting w/Westinghouse Dwners Group in BethesdayMD to discuss generic design incorporating shunt trip into automatic reactor protection function in reactor trip breakers
 IPPOLITORIA Operating Reactors Assessment Branch 83/05/27
 MIRRQLIAF J Assistant Director for Safety Assessment ip 83/05/27
- 8305090457 Forwards request for add1 info re MCAP-8575. "Augmented Startup & Cycle 1 Physics Program " Response requested by 830722
- Standardization & Special Projects Branch TAC 1882 AHE.E P Westinghouse Electric Corp 2pp 18815 152 83/06/02 RAHELE P
- 8306130444 Forwards mgt review committee const implementation overview observations re bulk hanger organization Review of documentation supporting established criteria needed BARANCHE Webster Inc 83/06/09 KEPPLER.J C Region 3, Office of Director 2pp 18821 201
- 8306140107 Confirms IE mgt 830405 meeting to discuss recent insp findings re nondestructive assay of waste matls & to review applicable regulatory requirements. 8TORR, J P Division of Emergency Preparedness & Materials Safety 83/04/20 ALTO,R A Babcock & Wilcox Go ip 18839 096
- 8306140377 Forwards revised Table D-f, "Preliminary Stress Level Comparison," showing value of stress concentration factor & higher calculated peak stresses. Higher peak stresses of not affect conclusions from 830306 meeting Meeting summary and TAYLOR. J H Babcock & Wilcor Go 83/06/07. MINER. S NRC No Detailed Affiliation Given 2pp 18844 001 24X Pfiche: 50-000, 83/06/07, 8306140377
- 8304140739 Forwards topical repts. "Boundary Analytical Assessment of NUREG-0630 on LOCA & Operating kW/Ft Limits." per 830602 request TUCKER,H B. Duke Power Co B3/06/26 DENTON:H R. Office of Nuclear Reactor Regulation, Director STOLZ,J F Operating Reactors Branch 4 Ip 18848 OOI 24X Fiche 50-269,83/06/06,8306140738
- ---8306140746 77-114125A-00 Roundary Analytical Assessment of NUREG-0630 on LOCA & Operating kH/Ft Limits."

 # Babcock & Hilcox Co. 83/06/06 29pp 18845 002 24X
 - Fich # 50-269, 83/06/06, 8306140738
- - 83/04/06 29pp 18845 032 24X
- 8306150121 Forwards SER of OE proprietary & nonproprietary
 NEDE-24284-P & NEDO-24284. "Assessment of Fuel Rod Bowing
 in GE BURs " Repts acceptable ref in license applications
 under delineated conditions
 THOMAS, C O. Standardization & Special Projects Branch 83/05/31
 QUIRK, J. F. General Electric Co. 2pp. 18870 068
- --8306150124 BER of QE proprietary & nonproprietary NEDE-24284-P & NEDD-24284, "Assessment of Fuel Rod Bowing in QE BWRs " Repts acceptable ref in license applications w/NRC supporting documentation # Standardisation & Special Projects Branch 83/05/31 9pp 18870:070
- ---8303220403 "Technical Evaluation of GE Fuel Rod Bowing Topical Rept
- NOSCA4884-P "
 CAREH.J F Brookhaven National Laboratory 82/08/31
 Detailed Affiliation Given 6pp 18870 079
- 8365140284 Forwards Hestinghouse Owners Oroup steam generator tube rupture (807R) emergency contingency guidance approved for high pressure version of amergency response guideline set Three 807R guidelines, ECA-7: 8 & 9 provided SHEPPARD, J. J. Westinghouse Operating Plants Owners Group SHEPPARD, J. J. Caroline Power & Light Co. DO-92 83/03/16 EISENHUT, D. 9 Division of Licensing 4pp 18861 013
- --8306160291 Procedure ECA-7:HP-Basic "Combined SOTE & LOCA"

 **Westinghouse Operating Plants Owners Group 83/04/18 83/04/18 23pp. 18861 017
- --8306160300 Procedure ECA-8 HP-Basic "Unisolatabl's SOTR "

 * Westinghouse Operating Plants Duners Group 83/04/18, 20pp 18861 040
- --8306160303 Procedure ECA-9 HP-Basic "SOTR W/O Pressure Pressure Control. Westinghouse Operating Plants Owners Group, 83/04/18 14pp 10861:060

- 8306160412 Forwards draft Rev 5 to "GA Program Topical Rept" COUNSIL W @ Northeast Utilities Service Co A03039 83/C MURLEY.T F Region I. Office of Director 6pp 18859 090 Fiche 30-000.83/06/09,8306160412 83/06/09
- --8306160424 Draft Rev 5 to "GA Program Topical Rept" * Northeast Utilities 83/06/07 135pp 19857 096 Fiche 50-000,83/06/07.8306160412 24¥
- 8306160493 Forwards "Bounding Analytical Assessment of NUREG-0630 Models on LGCA kW/ft Limits," reflecting use of FLECSEY heat transfer correlation as compensating model to reduce impact NUREG-0630 models or number value mødels MARSHALL, JR Arkansas Power & Light Co 1CANO68301 STOLZ, JF Operating Reactors Branch 4 ip 18862 OE Fiche 50-313,83/06/08,8306160493 83/06/08 18842 083
- --8306160497 77~1143707-00 306160497 77-1143707-00 "Bounding Analytical Assessment of NUREG-0630 Models on LOCA kW/ft Limits" + Babcock & Wilcox Co 83/06/08 20pp 18867 089 24x Fiche 30-313,83/06/08/8306160493
- 8304160541 Forwards GA Co Repts 706505, 706577 & GA-A16829 describing results of exams on fuel elements w/cracked webs Repts convey belief that cracks in fuel block graphite webbing do not intersect fuel holes
 BREY.H L. Public Service Co. of Colorado P-83169 83/06.
 COLLINS.J T. Region 4. Office of Director ip 18865 148
 Fiche. 30-267. 83/06/02. 8306160341
- --8306160564 QA-A16829
 "NDE of 54 Fuel & Reflector Elements From Fort St Vrain Core Segment 2"
 EAURHCINJ J GA Technologies, Inc /General Atomic Co
 82/10/31, 196pp 18865 179 24X Fiche 50-267, 83/06/02, 8306160541 UC-77
- B306170318 Forwards "Assessment of Conservatism in Mark I Downcomer Chugging Lateral Load," documenting presentation during B30311 meeting PFEFFERIEN.H C General Electric Co MFN-107-83 B3/06/08 VABSALLO.D B Operating Reactors Branch 2 ip 18877 237
- --8306170320 M1-LR-83-01 #Assessment of Conservatism in Mark I Downcomer Chugging Lateral Load " # EDS Nuclear, Inc # General Electric Co 83/05/31 33pp 18877 238
- 8306200019 Summary of B30331 meeting w/utils & Westinghouse in Bethesda,MD re Westinghouse analysis & evaluation of D4/D5/E steam generator mod MOPKINS.J B Licensing Branch 4 B3/06/14 Licensing Branch 4 22pp 18908 327 24X Fiche 50~000.83/06/14.8306200019
- 8306200255 Responds to HR Denton 830513 telcon re identification of plants using reactor steam condensation function in RHR sys Mark I owners accept generic response re Humphrey concerns on ECCS relief line discharge loads
 SHERHDOD, 0 0 General Electric Co MFN-106-83 83/06/08 EISENHUT, D 0 Division of Licensing 2pp 18901 184
- 8306210093 Provides update of three Salem-related issues previously discussed Broader range of Salem issues being addressed by B&W Owners Group, ATWS Standing Committee ⊅ will be discussed B&N Duners uroup; nive scenaring committees at 830630 meeting ENDS: JT Babcock & Hilcox Operating Plants Owners Group ENDS Arkansas Power & Light Co 10AN068310 83/06/14 MATT8ON: R. Division of Systems Integration (post 811005) 2pp 18714 237
- 8306210146 Forwards NEDO-22215, "Procedures for Determination of Extent of Core Damage Under Accident Conditions," & "Integration of Other Plant Parameters Into Core Damage Estimate," per NRC Tequest
 DENTE: T J BWR Owners Group
 Division of Licensing 20pp 9WR00-8324 83/04/17 EISENHUT, D 0
- --8306210153 NEDO-22215, "Procedures for Determination of Extent of Core Damage Under Accident Conditions " LIN.C C., COWAN,R L., KISG,E General Electric Co 82NED090 82/08/31 37pp. 18919 149
- 8306210165 Forwards license operator training segment (Pages 49~77) of revised Procedure N78A13. "Nuclear Operator Training Program: per 10CFR55.App A GREEN.H J Tennessee Valley Authority 83/06/17 THOMPSON.H L Division of Human Factors Safety 33pp 18915 257

- 8306210295 Informs of results of eram of steam generator internal auxiliary feedwater header dusigns & intentions to replace internal header 2009FA westernal headers. It completes informed feedings and all Both-designed headers.

 TAYLOR.J. II. Dabcock & Hilcor to 87/06/16 DEYOUNG.R C pirector's Office. Office of inspection and Enforcement Spp. 18914-010
- 8306220087 Forwards description of program approved by Westinghouse Owners Group to address NUREG-0737, Item II B 3 re post-accident care damage assessment: per 030428 meeting Project to be completed by end of yr SMEPPARD J J Westinghouse Operating Plants Owners Group SMEPPARD. J J Carolina Power & Light Co 63/06/16 NORRIS, J A Operating Reactors Branch I 7pp 18926 203
- 8306220250 Notification of 830627 meeting w/DWR-Hydrogen Control Owners Group in Bethesda. MD to discuss hydrogen control program HOUSTON.D Licensing Branch 2 83/04/09 SCHWENCER.A Licensing Branch 2 9pp 18951 054 24X Fiche 50-416.83/04/09.8306220258
- 8306220300 Notification of 830630 meeting w/REW Owners Group in Bethesda. MD to discuss organizational structure established to deal wigneric issues & group activities during last 6 months LAIMAS. G. Assistant Director for Operating Reactors 83/06/05 EISENIAT. D. Division of Licensing MATTSON. R. Division of Systems Integration (post 81009) VOLLMER. R. Division of Engineering 2pp 18940 301
- --B306220903 Designates & Lainas as licensing contact w/overail responsibility for staff interaction coordination & mgt Encl identifies technical contacts for each RAW Owners Group subtormittee Agenda for B30630 meeting encl DENTOW.H & Office of Nuclear Reactor Regulation, Director B3708701 CROUSE, R P Babcock & Wilcox Operating Plants Owners Group CROUSE, R P Toledo Edison Co 3pp 18740 303
- 63Q6230047 Forwards safety evaluation of emergency response guidelines Guidelines acceptable for implementation & will provide impraved guidence for emergency operating procedure davaispeent Response schedule requested within 90 days ETSERNUI.D & Division of Licensing 83/06/01 SHEPPARD.J J Hestinghouse Operating Plants Owners Group 3pp 18982 109
- --BJOA2J0052 Safety evaluation re Westinghouse Dwners Group generatements serious guidelines for mitigating transignts & accidents, per NNEG-0727, Item I C 1

 Giffice of Nuclear Reactor Regulation, Director GJ/06/01

 73pp [B787 11]
- 8306230167 Forwards addl info re Hydrogen Control Owners Group program, par NRC 830203 request Proprietary & nonproprietary versions of "Grand Gulf Diquell Break Sensitivity Summary" encl Proprietary rept withheld (ref 1001787 /90)

 DALE.L F. Hississippi Power & Light Co. AECM-83/0212 83/06/16 DENTON-H R. Office of Nuclear Reactor Regulation. Director 11pp 18745 299 24% Fiche 50-416.83/06/16.8306230167
- 8308230324 Forwards technical rept. "Genetic Control Red Drive Sys Study for BWR 2 Through BWR-9 Plant Designs " DENTE: I J BWR Owners Group BWRGG-8323 83/06/02 EIGENHUT, D & Division of Licensing ip 18942 225
- --BIGG210326 TR-5709-1
 "Generic Control Rod Drive Sys Study for BWR-2 Through
 BWR-5 Plant Designs." technical rept
 a Teledyne Engineering Services GJ/05/31 NRC -- No Detailed
 Affiliation Given 44pp 18942 226
- 8306230386 Forwards revised App E to WCAP-10170. "Application of Safety Parameter Display Evaluation Project to Design of Westinghouse Safety Parameter Display Sys " RAME: E P Westinghouse Electric Corp NS-EPR-2779 83/06/08 THOMAS: C Standardization & Special Projects Branch 1p 18943 061
- --8J06230391 WCAP-10170 APP E
 Revised App F to "Application of Safety Parameter Display
 Evaluation Project to Design of Westinghouse Safety
 Parameter Display Sys"
 WOODS.P D Westinghouse Electric Corp 42320 83/06/08 13pp
 £8943 062

- 830623043/ Forwards Rev 3 to "Corporate Operations Manual, Part IV-Functional Manuals, Section I Nuclear GA Manual " Revs reflect organizational changes & clarify Items modified in Rev 2 to SRP (NUREO-0800)
 RAUSCH, W P. Burns & Roe Co. 83/06/09 HAASS, W P. Quality Assurance Franch 1p 18744 023
- --8306230443 B&ROE-COM4-1-NP RO3
 Rev 3 to "Componate Operations Manual, Part IV-Functional Manuals, Section I Nuclear QA Manual"
 ROE.K A Burns & Roe Co 83/06/09 75pp 18944 024
- 8306240205 Provides info re DS-416 undervoltage trip attachments to be utilized in NRC evaluation of facility.per B Wright request RAHE.& P Westinghouse Electric Corp NS-EPR-2767 83/06/17 DENTON.H Office of Nuclear Reactor Regulation. Director 4pp 18780 246 24x Fiche 50-347.83/06/17.8306240205
- 8306240262 Forwards revised responses to RETRAN computer code review, per NRC 830202 request Draft SER requested prior to official release Also forwards "RETRAN-02 Program for Translent Thermal-Hydraulic Analysis of Complet Fluid Flow Sys "
 SCHNATZ.T W Middle South Services, Inc. 83/06/09 THOMAS.C O Standardization & Special Projects Branch 25pg 18978 009
- --8306240263 EPRI NP-1830-CCM VO4

 "RETRAN-02 Program for Transient Thermal-Hydraulic
 Analysis of Complex Fluid Flow Sys.Vol 4 Applications "
 PETERSON.C E , GOSE.9 C , MCFADDEN.J H Energy Incorporated
 83/01/31 250pp 18978 034
- 8306240313 Forwards proprietary & nonproprietary responses to NRC request for addl info on MCAP-8720, Addendum 2. "Revised PAD Code Thermal Safety Model" Proprietary response withheld (ref 10CFR2 790)
 RAHC. E.P. Westinghouse Electric Corp. NB-EPR-2773 83/06/02 TMCMAS.C.D. Standardization & Special Projects Branch. 2pp
- --8306240314 Requests withholding of proprietary response to NRC request for add1 info on NCAP-8720, Addendum 2. "Revised PAD Code Thermal Bafety Madel." per 10CFR2 790 Affidavit and HIESEMANN.R A Nestinghouse Electric Corp AN-83-45 83/06/02 THOMAS.C O Standardization & Special Projects Branch 9pp 18997 144
- ---8306240315 Nonproprietary response to NRC request for addl info on WCAP-8720 Addendum 2. "Ravised PAD Code Thermal Safety Model"

 * Westinghouse Electric Corp 83/06/02 10pp 18997 153
- 8306270260 Forwards "Bounding Analytical Assessment of NURE9-0830 Models on LOCA kW/Ft Limits " RODR:104E2F, J. Sacramento Municipal Utility District RdR 83-505 83/06/20 STOL2.U F Operating Reactors Branch 4 2pp 18990 231 24X Fiche 50-312.83/06/20.8306270260
- 8306270355 Forwards proprietary viewgraphs used at 830517 meeting w/NRC re-review of design process for advanced control room for Westinghouse Advanced PHR Meeting agenda provided Viewgraphs withheld RANE, E P Hestinghouse Electric Corp. NS-EPR-2776 83/06/03 EISENHUT.D 0 Bivision of Licensing 2p 18993 306
- 8306270434 Provides addi justification re proprietary classification of Westinghouse Advanced PWR licensing control document Overail concept of licensing control decument considered Westinghouse proprietary info MIESEMANN, A Westinghouse Electric Corp NS-RAW-83-477 83706/21 MEYER, 6 C Btandardization & Special Projects Branch. 2pp 18793 117
- 8306280240 Forwards proprietary Suppl 1 to "Stability Evaluation of BWR Cores Benchwork Analyses." Rept addresses addl generic issues of BWR stability & provides addl benchmarking calculations Rept withheld (ref 10CFR2 790) COPELAND, R A Exxon Nuclear Co. Inc. (subs of Exxon Corp.) RAG 024 B3 B3/06/21 THOMAS.C O Standardization & Special Projects Branch 1p 19015 029
- B306280337 Forwards responses to NRC B30331 questions on topical rept BAW-10153P, "Extended Burnup Evaluation " Conservatism in dose calculations sufficient to accommodate expected effects of jodine spiking TAYLOR.J H Babcock & Wilcor Co 83/06/21 MORAN, D H. Standard(zation & Special Projects Branch 11pp. 19001; 299.
- 8306280392 Advises that info submitted by util an 830610 re response to open items from Equipment Qualification Branch SQRT is nonproprietary RAHE, E P Hestinghouse Electric Corp NS-EPR-2791. 83/06/21 YOUNGBLOOD, B J Licensing Branch i p 19019 008 24X Fiche 50-445. 83/06/21.8306280392

- 8306280449 Discusses concerns be NRC consideration that diverse scram sys be required on Mestinghouse plants PMR inherent design characteristics adequately address performance criteria for ATMS events Meeting requested RAME, E P Mestinghouse Electric Corp NS-EPR-2787 83/06/22 DENTON, H R Office of Nuclear Reactor Regulation, Director 4pg 18018 179
- B306280534 Forwards proprietary Suppl 7 to "STR Bundle Submittal Millstone-i, Segmented Test Rod Bundle," updating 741003 rept.ger Reload 2 license amend GQ Sherwood affidavit encl Rept withheld (ref 10CFR2 790) COUNSIL,W Q Northeast Nuclear Energy Co (subs of Northeast Utilities) COUNSIL,W Q Northeast Utilities B10727 83/06/17 CRUCHFIELD,D Operating Reactors Branch 5 5pp 19016 292 24X Fiche 50-245,83/06/17,8306280534
- 8306300057 Forwards G-E repts, "Depressurtiation & DHR, Responses to NRC Questions." Supplito "PRA of Effects of PORVs on Depressurization & DHR" & "Responses to Plant-Specific Questions on Depressurization ." per 82027 request BASKINIX P Southern California Edison Co 83/06/22 KNIGHTON G W Licensing Branch 3 3pp 19117 062 24X Fiche 50-361.83/06/22.8306300057
- --8306300125 CEN-239
 "Depressurization & DHR, Responses to NRC Questions "
 * Combustion Engineering, Inc. 83/06/30 390pp 19117 065 24%
 Fiche 50-361, 83/06/22, 8306300057
- --B306300136 CEN-237 801
 Suppl 1 to CEN-237, "PRA of Effects of PORVs on
 Depressurfaction & DHR San Onofre Nuclear Generating
 Station.Units 2 & 3 "

 * Combustion Engineering, Inc 83/06/30 363pp 17118 083 24x
 Fiche 50-361,83/06/22,8306300057
- 8306300116 Endorsement 33 to MAELU Policy MF-96

 * Nuclear Energy Liability Insurance Association 83/06/01 2pp
- WASH REGULATORY PUBLICATIONS - PRE-NUREG SERIES
- 8306200037 Responds to FOIA request for blueprints & explanations of assorted power plants Forwards documents describing safety & NRC licensing process for reactors Drawings & design details available in listed LPDRs in NY assed Lrums In NY Division of Rules and Records 83/05/18 SPECTOR.B Unknown 2pp 18919-320 Affiliation Unknown
- --8306200040 WASH-1250 JUSZUDOGO WASH-1230, "Safety of Nuclear Power Reactors (Light Water-Cooled) & Related Facilities " * NRC - No Detailed Affiliation Given 83/05/18 39pp 18717 322
- WASTE MOT NUCLEAR WASTE MANAGEMENT
- 8306020192 Forwards updated EIS schedule for UMTRAP as of 830501 ARTHUR,J Energy. Dept of 83/05/01 MARTIN,A Low Level Waste Licensing Branch 2pp, 18701 071
- 8306020194 Forwards updated environ assessment schedule for UMTRAP as of 830510
 ARTHURN J Energy, Dept of 83/05/10 MARTIN, D NRC -- No Detailed Affiliation Given 2pp 18701 070
- B306020217 Forwards best available sorption info on Columbia Plateau baselt, alteration products & interbed met!
 SERNE,R J Battelle Hemorial Institute: Pacific Northwest Laboratory 83/05/i3 MILLER,A B Sandia Laboratories 33pp
- B304020220 Forwards proposed agenda for 830527 meeting re UMTRAP 30600220 Forwards proposed agence ...
 implementation
 PAGE.R G NRC - No Detailed Affiliation Given 83/05/18
 CUMNINGHAM.R E , BROWNING.R , \$1001M801MAM.L NRC - No Detailed
 Affiliation Given 3pp 18701 054
- 830&020228 Designates 24 contaminated Edgement vicinity properties for remedial action, identified in encl list of radiological assessment repts UMTRAF authorized to bring properties in conformance w/final EPA stds (40CFR192) COFFMAN,F E Energy, Dept of NE-24 83/05/04 ROMATOWSKI.P G Energy, Dept of 2pp 18701 012

- 830602023) Forwards into re U mill tailings remedial action virinity properties status, plans % schedules including data used in preparing project schedule % cost estimate rept BALL, D.M. Energy, Dept of 83/05/17 BRAZLEr, I.C. Energy, Dept of 3pp 18700-355
- 8306020257 Forwards 24 radiological Janus Smell repts for properties in Edgemont. SD where presence of residual radiological math detected Remedial action recommended for properties reporting residual math levels above FPA stds W/o encl MARTIN. D.C. Low Level Waste Licensing Branch FIN B-2217 83/04/21 BAUBLITZ. J. Energy, Dept. of 2pp. 18700-344 ch FIN 2pp
- 8306020257 Forwards, for comment, diait generic pictocol for identification, characterization, b inclusion/designation of vicinity properties proposed for remedial action under Public Law 95-604 83/05/13 HEGGENBOTHAM, L Low BAUBLICAN DEATH OF E3/05/13 HI Level Waste Licensing Branch 14pp 18/200 329
- B306030200 Summary of B30419 meeting w/Marline U Corp in Silver Spring, MD re status of proposed U project in Danville,VA KALMAN,K L. Uranium Recovery Licensing Dranch B3/05/06 HIGGINBOIHAM,L Law Level Waste Licensing Branch 2pp 18733 340
- 8306030210 Trip regt of attendance at Committee E-5 % tow Level Waste Mgt Committee 830514-15 meetings % Conference of Radiation Control Program Directors 830516-17 meeting HAMKING.E F Low Level Waste Licensing Branch 83/05/23 HIGGINBOTHAM.L Low Level Waste Licensing Branch 3pp 18731742
- 8306030244 Summary of 830511 DUE consultation meeting w/states,USGS & CEG at Dallas-FT Worth.TX airport is proposed siting ovidelines BOVLE,RR High Level Waste Licensing Management Branch 83/ BELL,M J High Level Waste Licensing Management Branch 29pp 18734-033 83/05/19
- 8306030273 Summary of 830516 meeting w/DDE in Gaithersburg.MD resiting guidelines DOE should make same version available to public by issuing FR notice of availability FFLUM.C G. High Level Waste Licensing Management Branch. BOYLE.R R. High Level Waste Licensing Management Branch. 2pp 89/05/20
- 8304030430 Comments on 830415 info re 20 properties in Grand Junction. CO to be included in UMTRAP Portions of Properties not scheduled for remedial action under site program should be be included
 MARTIN.D C Low Level Waste Licensing Branch 6
 DAUBLITZ.J E Energy, Dept of 1p 18747 116 83/05/06
- 8306030431 Requests steps vendor must take to deliver 1982 & 83 Jobson I requests steps vendor must care to deliver 192 0 83 radioactive shipping records data on magnetic computer tape for use in DOF low level waste data base JACKSON.K C Low Level Waste Licensing Branch 83/05/05 CRASE.H US Ecology. Inc (formerly Nuclear Engineering) 2pp 18735 348
- 8306030432 Comments on Apr 1983 rev of remodual action concept papers for Cunnison inactive U Mill Tailings Site Issuance of paper HIGGINBOTHAM.L Low Level Waste Licensing Branch 83/05/11 MORLEY, J.A. Energy, Dept of 1p 18735-362
- 8306030438 Requests assistance in establishing coordination procedure Subsuring Requests assistante in establishing coordination professore re NRC contractors requesting site-specific samples from high level radioactive sites Neeting requested BROWNING, R E Division of Waste Management 83/05/04 BENNETT, J H Energy, Dept of 4pp 18747 145
- 8306030442 Requests info re steps vendor must take to deliver 1982 & 83 radioactive shipping records data on magnetic computer tape for use in DDE law level waste data base JACKBON.K C Low Level Waste Licensing Branch 83/05/05 WHITTAKER.M Chem-Nuclear Systems. Inc 2pp 18735 285
- 8306030470 Forwards generic comments on 30 Durango & Salt Lake City property repts No generic protocol agreed on for designation of vicinity properties Plans for aerial or ground monitoring requested MART IN DE MARTIN.D E Low Level Waste Licensing Branch 8 BAUBLITZ, J E Energy, Dept of 4pp 18735 278
- 8306030476 Forwards draft Sections 1 % 2 of May 1983 revised RADMAN topical rept Views on Section 2 requested W/o encl TUITE,P T Waste Management Group, Inc. B3/05/12 ROLES.6 Low Level Waste Licensing Branch 1p 18735 247

- 8305030477 Act receipt of quarterly progress lept on hydrogeochemical studies at Riverton & Maybell sities Supports change in direction of project from field data gathering to modeling FENNIFILLR A Low Level Waste Licensing Branch 83/05/24 BARBER, W. Jacobs Engineering Group. Inc. 1p. 18735-267
- 83C6O6D417 Forwards draft version of proposed SD/DDE cooperative agreement Agreement formally initiates efforts to implement remediat actions to stabilize & control U tallings RCMATOMSKI.R © Energy, Dept of 83/05/20 JANKLOW Sour Datota. State of 43pp 18751 001
- 830508014B Forwards review draft of "Remedial Action Plan for Stabilization of Inactive V Mill Tailings Site at Canonsburg:PA" Comments requested by 830626 RORLEY, JA Energy, Dept of 83/05/26 NIXON,W A Office Nuclear Material Safety & Safeguards Director 1p 18790 102 Office of
- --8306080153 UMTRA-DOE/AL-140 DR
 *Remedial Action Plan for Stabilization of Inactive U Hill
 Tailings Site at Camonsburg.PA." review draft
 + Energy. Dept of. B3/05/31 147pp 18790 103
- B306090033 Summary of B30509 meeting w/DDE remedial action contractors in Silver Spring-MD re-preliminary sections of Canonsburg, PA remedial action plan & generic health & safety plan for
 - UNIRAP.
 FLORY.C.A Low Level Waste Licensing Branch 83/05/26
 MTGGINBOTHAM.L Low Level Waste Licensing Branch 2pp 200 18798 020
- 8306090353 Forwards seismic study rept for Salt Lake City prepared for inclusion in EIS Rept evaluates effects of probable seismic events on vitro tailings pile in South Salt Lake Rept will underego format changes & become App 1 to DLS & EIS MORLEY. J A Energy. Dept of 83/09/01 MARTIN.D NRC No Detailed Affiliation Given 44pp 18797 069
- 3305090357 "Edgement Remedial Action Program." Itr rept for Feb.Mar &
- Apr 1983 JACKSON.P O , PERKINS.R W , WOGMAN.N A Battollo Momorial Institute, Pacific Horthwest Laboratory FIN 8-2217 83/05/13 FLORY.C A Low Level Waste Licensing Branch 10pp 18797 046
- 308070372 Bubaits eighth status rept on Edgement offsite cleanup
- Action program FEORY, C A Low | HIGGINEOTHAM, L Low Level Waste Licensing Branch FIN B AM.L Low Level Waste Licensing Branch FIN 8-2217 83/06/01 anch 4pp 18814 031
- 306140185 Summarizes B30409 discussion w/D Nussbaumer & K Schneider re Agreement State compatibility concerning financial assurance requirements for long-term care at low level radwaste burial sites Proposed criteria changes to be finalized LOHAUS, P N Low Level Waste Licensing Branch 83/00/18 HIGGINBORNAMIL Low Level Waste Licensing Branch 2pp 18844 187
- 335140169 Trip rept of 830228-0301 visit to Tucson, AZ to attend waste agt conference, ASME radwaste committee meeting 5 ANS 40 39 vol reduction std committee meeting Meeting summaries encl JORNSON, FC Low Level Waste Licensing Branch 83705724 LOW Level Waste Licensing Branch 11pp 18844 189
- SOCIADICS Forwards comments on NRC WISP draft, "Study of Isolation Sqs far Geologic Disposal of Radwaste" re hydrology, geochemistry, design, waste package & performance assessment High Level Waste Licensing Management Branch 83/05/11 BELL. M J High Level Waste Licensing Management Branch 17pp 18844.164
- 83/05/11.
- KS140203 Submits specific questions & answers discussed by NRC.OAI & Geo Trans.Inc during 830307 & OB hydrogeology modeling mestings re implementation of SWIFT (Version 4 81) HEBERN F High Level Waste Licensing Management Branch 83/09/1 83/09/11
- 06140283 Forwards first 11 radiological assessment repts for OcidOcid3 Forwards first it radiological assessment report of properties in Edgement. 8D where presence of residual radiological matts detected NRC concurrence should be obtained on properties which DDE decides not to designate HAMKING. EF High Level Waste Licensing Management Branch 83/03/22 BAUBLITZ. J. Energy. Dept. of 2pp 18844 206
- 04140287 Comments on monthly rept for Feb-Apr 1982 for Edgemont Octoolly Comments on monthly rept on received since 830421 Repts
 sust be submitted as expeditiously as possible
 FLORY.C A Low Lavel Waste Licensing Branch FIN D-2217 83/06/03
 MDCRAN.N A Battelle Ammorial Institute, Pacific Northwest
 Laboratory 3pp 18844 203

- B3D6140325 Comments on draft UMTRAP technology development plan, received on B30504 Plan provides good general description of UMTRAP RAD program GNUGNOLI.G N Low Level Waste Licensing Branch B3/05/13 MATTHENS.M L Energy, Dept of 2pp 18854 116
- 8306140331 Forwards Waste Mgt Group Inc (MMG) response to & NRC & States of NV & SC comments on State of NV Consumer Health Svcs comments re WMG topical rept concerning RADMAN Code to document low level waste Input needed by 830927 W/o encl NUSSBAUMER, D Assistant Director for State Agreements Programs 83/05/12 VADEN, J Nevada, State of 1p 18834 121
- 8306140333 Forwards radiological assessment repts for 11 remedial action designated properties in Edgemont. ED per 830328 memo. Engineering design rapts available from ARIX. Inc M/o anci MARTIN.D E Low Level Waste Licensing Branch 83/05/19 TUCKER. M Energy. Dept of 1p 18854 122
- 8306140336 Forwards initial comments on Yuba City, AZ environ assessment of remedial actions on U mill tailings Addl info needed to demonstrate that EPA regulations re protection of demonstrace snor ern ingo-groundwater met MARTIN.D E Low Leval Waste Licensing Branch MORLEY.J A Energy, Dept of Opp 18834 123 83/05/20
- 8306140351 Forwards radiological assessment repts for 11 remedial action designated properties in Edgemont, SD per 830328 memo Engineering design repts available from ARIX. Inc. W/a encl MARTIN,D E Low Level Maste Licensing Branch 83/05/20. THEMELIS,J Energy, Dept of 1p 18844-357
- B306140364 Forwards comments on working copy of environ assessment of remedial action on U mill tailings at Naturita site Compliance w/EPA stds for groundwater impossible to assess MARTIND E Low Levyl Waste Licensing Branch. B3/05/20. MORLEY.J A Energy, Dept of opp 18854 152
- 8306140695 Responds to 830422 comments on Green River remedial action concept gaper Revised paper will be submitted MORLEY.J.A Energy, Dept of 83/05/25 MARTIN.D.E Low Level Waste Licensing Branch 3pp 18854 001
- 8306150227 Forwards 830525 ltr requesting determination of new technical & economic data significance & draft outline of DEB suppl for South Salt Lake tailings MATTHEMS.M L. Energy. Dept of 83705/26 MARTIN.D NRC No Datailed Affiliation Given 3pp 18870.055
- 8304/50233 Forwards comments on Apr 1983 draft. "Surface Qamma Ray Measurement Protocol for Small Parcels on Open Lands." Opportunity to review & concur w/final version grior to Opportunity to review a construction of the co
- 8306160642 Forwards environ assessment & action description memo for remodial action activities planned for vicinity properties in Edgemont 8D Proposed action will remove U mill tailings & return tailings to TVA milisite or disposal site TUCKER.M K Energy, Dept of 83/06/06 BAUBLITZ, J. E Energy, Dept of 7pp 18876 263
- 8306170446 Forwards radiological assessment repts for 15 properties in Edgement, SD where residual radiological mat1 detected Remedial action needed for properties w/residual mat1 levels above applicable EPA stds MARTIN, D E Low Level Waste Licensing Branch 00366, 83/06/06, BAUBLITZ, J Energy, Dept of 2pp 18707, 328
- B306200012 Forwards "Economic Impact of Remedial Action Options, Vitro Tailings Site, City of South Salt Lake, UT" Rept will be included in suppl to DES & FEE Comments requested by B30617 HATTHENS H L. Energy, Dept of B3706/08 MARTIN, D. NRC ~ No Detailed Affiliation Given ip 18909 001
- --8306200013 "Economic Impact of Remedial Action Options.Vitro Tailings Site,City of South Lake City.UT " 4 Jacobs Engineering Group, Inc 83/06/06 60pp 18909.002
- 8306200415 Notice of availability of draft technical position on "Solubility & Speciation of Radionuclide Compounds for High Level Waste Repository Safety Assessments "
 MILLER, H. J. High Level Waste Technical Development Branch 83/05/23. 2pp. 18919 268
- --8306200419 "Assessment of Radionuclide Solubilities by Conservative Estimation of Concentration NRC Technical Position " # High Level Waste Technical Development Branch. 83/05/28 33pp 18719 270

- 8306210423 Forwards K Hamili casework status summary rept on Rifle, CD UMTRAP site Removal of milestone for providing comments on DDE notice of intent to publish EIS requested W/o encl MARTIN, D E Low Level Maste Liconsing Branch 83/03/27 BRDWNING.R E. Division of Waste Management 1p 18936-362
- 8308210428 Discusses license amend & other documentation necessary to accommodate disposal of vicinity property matis
 TUCKER, M.K. Energy, Dept of 83/06/01 SMITH, D. Uranium Recovery
 Field Office 2pp 18737 031
- 8306220164 Forwards DOE 830517 response & 830503 request for clarification of DOE position on use of disposal sites by commerical waste generators BROWNING, R E Division of Waste Management 83/06/13 KERR, G W Office of State Programs. Director CUNNINGHAM, R Division of Fuel Cycle & Material Safety 1p 18937 325
- --8306220173 Responds to request for clarification of DDE position on use of disposal sites by commercial waste generators Details of testimony presented at Senate Judiciary Committee B30302 hearing submitted COFFKAN.F E Energy, Dept of 83/09/17 BROWNING.R E Division COFFMAN.F E Energy, Dept of 83/05/17 BROWNING.R E Division of Waste Management ip 18937 324
- --8306220176 Requests clarification of DOE position presented at Senate Judiciary Committee 830302 hearing or use of disposal sites by commercial waste generators BROWNING, R E Division of Waste Management 83/09/03 COFFMAN.F E Energy, Dept. of ip 18937-327
- 9304920149 Forwards info on six Grand Junction site properties 306/200169 Forwards info on six Grand Junction site properties designated for remedial action due to contamination w/ residual radioactive matl Properties outside Grand Junction site being identified & radiologically examined BAUBLITZ.JE Energy, Dept of 83/06/10 HIGGINBOTHAM.L Low Level Waste Licensing Branch 13pp 18937 292
- 8306220208 Forwards 830603 updated UMTRAP environ assessment schedule ARTHUR.J. Energy, Dept of 83/06/08 MARTIN.D NRC No Detailed Affiliation Given 2pp 18751 021
- 8306220211 Advises that NRC comments on draft remedial action concept paper (RACP) for Riverton Wy. Incorporated into revised RACP MORLEY, J A Energy, Dept of 83/06/08 MARTIN, D Low Level Waste Licensing Branch 10, 18951 020
- 8306220287 Forwards listing of UMTRAP documentation delivered to U Fuel Licensing Branch on 830606 KALMAN.K L Low Level Waste Licensing Branch 83/06/11 MARTIN.D E Low Level Waste Licensing Branch 9pp 18777 309 9рр
- 8306240179 Forwards, for review, Salt Lake City, UT EIS section on public & agancy comments & responses to comments Seismic, land value & hydrology addendum sections should receive review priority MATTHEWS. & L priority MATTHEWS, N L Energy, Dept of 83/06/17 i Detailed Affiliation Given 77pp 18999 241 MARTIN, D NRC - No
- 8306240277 Designates 15 Edgemont vicinity properties as contaminated areas needing remedial action Total number of Edgemont vicinity properties so designated is 50 Remedial action should be completed during 1983 const season COFFMAN.F E Energy, Dept of NE-24 83/06/15 ROMATOWSKI.R C Energy Dept of ip 1899 187
- 8306240385 Discusses requirements for waste classification & waste form published in FR Technical position papers on radwaste classification & waste form encl HigoInBOTHAML Low Level Waste Licensing Branch 83/05/ii Level Waste Licensing Branch 83/05/ii
- 8306240388 Concurs w/issuance of Mar 1983 versions of remedial action concept papers for Grand Junction & Rifle inactive U mill tailings sites
 HIGGINBOTHAM.L Low Level Waste Licensing Branch 83/04/21
 MORLEY.J A Energy, Dept of 1p. 18987 353
- 8306240482 Forwards 830601 updated schedule for UMTRAP EIB ARTHUR, J Energy, Dept of 83/06/15 MARTIN, D NRC No Detailed Affiliation Given 2pp 18998 069
- 8306240486 Trip rept of attendance at American Chemical Soc 830320-25 meetings in Seattle, WA re geochemical behavior of disposed radwaste STARMERR J., BROOKE,D.J. High Level Waste Technical Development Branch 83/04/20 JUSTUS.P.S. High Level Waste Technical Development Branch. 7pp 18998.075

- 8306280280 forwards notice of availability of NRC draft technical gosition. "Sulubility & Specification of Radionuclide Campounds for High Level Waste Repository Safety Assessments."
 MILLER.H J. High Level Waste Technicil Development Branch 83/05/26 FELTON, J.M. Division of Rules and Records. 1p. 19327-001
- --8306280291 "Solubility & Specification of Radionuclide Compounds for High Level Waste Repository Safety Assessments, draft technical position High Level Waste Technical Development Branch 83/06/30 21pp 19327 004
- XPORTLIC EXPORT AND IMPORT LICENSES
- 8306020590 Application to amend export license changing quantity to 705 047 kg U=235, contained in 26,007 kg U \pm 0 162 kg U=235, contained in 5 0 kg U \pm reflecting that mall is of Australian origin Australian drigin HANNCTF.B.A. Transnuclear, Inc. RBU-395 83/05/1/ Office of International Programs, Director Ip. 187 MOORE, N 18715 045
- 8306020593 Cicense for Transnuclear Inc to export 593 200 kg U-235, contained in 19,753 kg U & O 243 kg U-235, contained in 6 kg U to Sweden
 Zimmerran, J V Assistant Director for Export/Import & Internatio V Assistant Director for Export/Import & International RBU-433 83/05/23 2pp 18715 059 Safeouards
- 8306020597 Amend 2 to QA Co export lirense changing name of licenses to ultimate consignes & extending expiration date to 861201 ZIMMERMAN.J V Assistant Director for Export/Import & International Safeguards IEE-1013 83/09/24 Ip 18713 098
- 8306020615 Executive Branch position is Milco Intl. Inc application to export 440,000 lb greensalt to Israel Application should be returned w/o action DEVINE.J B State. Dept of 83/09/18 SHEA.J R Office of International Programs. Director 1p 18719-049
- 8306020623 Amend 2 to GA Co export license changing name of bicenses & ultimate consignee & extending expiration date to 861201 ZIMMERMAN.J V Assistant Director for Export/Import & International Safeguards IEC-780 83/05/25 ip 18702-356
- 8306020620 Amend 3 to Ediow Intl Co license, increasing quantity of bulk thitium gas exported to 40,000 Ci.for export to United Kingdom ZIMMERHAN, J V Assistant Director for Export/Import & International 83/05/23 18716 338 10
- B306020645 Executive Branch position re Reactor Experiments. Inc amend application to export 11 5 mg Pu-237, as metal disks encapsulated in nickel to Japan License should be granted DEVINE, J. B. State, Dept. of B3705/16 SHEA, J. R. Office of International Programs, Diructor 1p 18716-277
- HIG6020653 Forwards Exxon Nuclear Colp request for amond to export license increasing quantity of matl exported to West ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 83/05/19 RAYMOND, J Energy, Dept of 1p 18716-269
- -8304020659 Application to amend license, increasing quantity of U
 hexafluoride for export to West Germany
 KIEL,G R Exxon Nuclear Co., Inc. (subs. of Exxon Corp.)
 83/05/10 ZIMMERMAN,J V Assistant Director for Export/Import./
 International Safeguards ip 18716-270
- 8306020663 Informs that C Itoh & Co 630510 application for license to export 200 guide thimble tubes to Japan meets requirements of Abomic Energy Act License issued w/o 15 day waiting period ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards 83/05/13 Assistant Director for Export/Import & International Safeguards 1p 18716-255
- 8306020670 Application to amend export licenses extending expiration date to 861201 & changing ultimate consignee MOWRY, W R GA Technologies, Inc./General Atomic Co IEL-4078 B32/05/17 ZIMMERMAN, J Assistant Director for Export/Import & International Safeguards 2pp 18716 247

- 830602067" Requests formal action re issuance or denial of export license applications SCHIMMEL.R L. Monsanto Research Corp. RLS-2160 83/01/10 Office of Nuclear Material Safety & Safeguards, Director. 3pp 18713-340
- 8305020688 Informs that License XSNM-2028 may be issued No matl changed circumstances since issuance of License XSNM-1912 MOGRER N Assistant Director for Export/Import & International Bafeguards 83/05/19 Assistant Director for Export/Import & International Safeguards 1p 18715 327
- 830a030011 Executive Branch position re Edlow Intl Co application for agend to export license, increasing quantity of bulk tritium gas Amend should be issued DEVINE.J 8 State. Dept of Bureau of Oceans & Intl Environ & Scientific Affairs 83/05/16 SHEA.J R Office of International Programs. Director ip 18733 140
- B30A030051 Forwards application for license to export nuclear fuel aleaents to Taiwan
 KIEL, G R Exxon Nuclear Co . Inc (subs of Exxon Corp.) 83/05/06
 ZIMMERHAN.J V Assistant Director for Export/Import & International Safeguards ip 18733 197
- --830&0300&0 Application for license to export 3,163 to U-235, contained in 76,762 to U.in fuel assemblies, to Tolwan KIEL,C R Exxon Nuclear Co., inc. (subs. of Exxon Corp.) 83/05/06 lp 18733 178
- 830.6030083 Application to amend license to expert incorporating listed info & components & extending expiration date to 830.630 MILSON B D General Electric Co BOW-057-83 83/05/11 MRIGHT B L Assistant Director for Expert/Import & International Bafeguards 2pp 18733-267
- B305030117 Informs that Amend 2 to License XBNM-1977 may be issued No matt changed circumstances since issuance of Amend 1 to License XBNM-1912
 MOORE A N Assistant Director for Export/Import & International Safaguards 83/03/23 Assistant Director for Export/Import & International Safaguards 19 18733 303
- 8306030160 Application to amend export license, extending expiration date to 840610
 8RUSH, P N Hoke, Inc 83/05/23 HEMBY, E NRC No Detailed Affiliation Given ip 18733 314
- B3Q&030165 Application to amond export license, adding listed ultimate consignaes for Zircaloy 4 tube shells
 BLONICORE. J A Mitsui & Co (UBA), Inc (subs of Mitsui & Co, Ltd.) 83/05/20 NRC No Detailed Affiliation Given Ip 18733 315
- 8308030169 Telecopy application to amend export license, changing address of ultimate & intermediate consignees FOSTER. © M Edlow International Co 83/03/24 WRIGHT, D Assistant Director for Export/Import & International Safeguards in 18733 316
- 830.6030174 Amend 1 to 0E & 9E Technical Svcs Co.Inc export license, deleting two intermediate consignees, changing address of remaining intermediate consignee, adding two parties to export & extending expiration date to 860630
 ITMEERINAN.J V Assistant Director for Export/Import & International Safeguards BSW-059-83 83/05/26 ip 18733-317
- B306030217 License for M&T Chemical, Inc. to export 1000 kg natural thorium to Australia, Canada, France, Japan, The Netherlands, United Kingdom & West Germany ZipenenMinJ V Assistant Director for Export/Import & International Safeguards RGB B3/05/R6 ip 18733 346
- 8304030276 License for Exxon Nuclear Co.Inc to export miscellaneous parts & components for use in nuclear reactors to France ZIPPERMANJY Assistant Director for Export/Import & International Bafeguards 83/09/26, ip 18733 347
- 6306030247 Amend 1 to Exxon Nuclear Co.Inc license.increasing valve of export to West Germany IIIMERHAN.J V Assistant Director for Export/Import & International Safeguards 83/03/24 ip 18734-064
- B30A030474 Forwards FR notice re "Applications for Licenses to Import/ Export Nuclear Facilities or Matlu," for publication in FR IIMMERMANJY Assistant Director for Export/Import & International Safeguards B3/05/23 COMBS.T R Office of the Secretary of the Commission ip 18735 282

- ---8304030478 Notice of applications for Licenses to import/export nuclear facilities or matls
 ZIMMERMAN.J V Assistant Director for Export/Import &
 International Safeguards 83/05/23 2pp 18735 283
- 9306060354 Application for license to import 500,000 kg U,enriched to 4% U-235
 HARMON,D W Braunkohle Transport & Storage, Inc 83/05/10
 MDORC,R N Assistant Director for Export/Import & International
 Safeguards 1p 16748 355
- 8306090000 Amend | to Ediaw Intl Co export license, changing ultimate & intermediate consignee addresses ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards HSA-JA-2 (KLK-1 83/05/21 ip 18798 010
- 8305090009 Amend 1 to Westinghouse export license, adding intermediate consignee ZIMMERMAN.J V Assistant Director for Export/Import & International Bafeguards 2650257 83/03/26 ip 18798 009
- 8306090012 Application to amend export license increasing max U enrichment to 3 55% increasing U-235 to 2.944 kg.changing U hexaftuoride to U dioxide sintered pellets & adding party to export
 HERSCH,M M Westinghouse Electric Corp MMM-376. 83/05/25 ZIMBERMAN, J V Office of International Programs, Director 1 18798 008
- 8306090181 License for Westinghouse to export three electrical penetration feed-through assembly parts, including support math, to Suitzerland ZimmeRMAN.J V Assistant Director for Export/Import & International Safeguards ZE 10503 83/05/31 tp 18797 113
- 8306140260 Application for literse to export two Zircalog tube shelts to Japan End use statement encl BUGNOCORE, J A Mitsui & Co., Ltd 136300 83/05/25 3pp 18844 300
- 8306140267 Amend 8 to Edlow Intl Co erport license, authorizing retransfer of 200 uCl Cf-252 source from United Kingdom to Israel
 ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards TRC-4 83/06/01 ip 18844 303
- 8306140271 Amend 2 to Hoke, Inc export license, extending expiration fate until 840630 ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguards HNL-101 83/06/01 1p 18844.304
- 8306140274 License for Transnuclear Inc to import 17,000 kg U.enriched to 0 8% U-235. From France ZIMMERMAN. J V Assistant Director for Export/Import & International Bafeguards 83/05/31 ip 18844 305
- 8306140281 Advises that proposed import of 17,000 kg U.enriched to 0 8% U-235. From France conforms w/std shipping provisions & will not be inimical to common defense & security & does not constitute undue risk to public health & safety MOORE.R N Office of International Programs, Director 83/06/01 Director's Office, Office of Inspection and Enforcement 19 18844 309
- 8306140288 Application for license to import 52,000 kg U,enriched to 3 85% U-235,from France KIEL.G R Exxon Nuclear Co , Inc (subs of Exxon Corp), 83/05/20. IMMERMAN.J V Assistant Director for Export/Import & International Bafeguards 2pp 18844 313
- B306140270 Application for license to import test specimens, in form of solid exides or fluorides securely bonded to metal backings, from Belgium Fissionable deposits will be used for fission rate measurements to test nuclear data PEVEV.L. E. Commercs, Dept of. National Bureau of Standards B3/09/29 Assistant Director for Export/Import & International Bafeguards ip 18844.308
- 8306140298 Application for license to import test specimens in form of solid oxides or fluorides securely bonded to metal backings, from Belgium Fissionable deposits will be used for fission rate measurements to test nuclear data PEVEY-L E Commerce, Dept of National Sureau of Standards, 63/05/25 Assistant Director for Export/Import & International Safeguards ip 19844-332
- 830614030? Requests Executive Branch position re Westinghouse application for license to export ENM to Yugoslavia Westinghouse 830825 itr supersedes 830811 request ZIMMERMAN, J V Assistant Director for Export/Import & International Safeguerés 83/06/01 87018ER.C R State, Dept of, Bureau of Oceans & Intl Environ & Scientific Affairs ip 18954:079

- 8306140394 Application for license to import 19 9 kg U.enriched to 5/ U-235.from France STEVENSON.R L Ledoux & Co , Inc 83/05/24 WRIGHT, B L Assistant Director for Export/Import & International Safeguards 2pp 18844 353
- --8111040442 Amend 3 to License 29-01442-01.authorizing use of Pu & U-235 for instrument calibr & lab sample analysis WRIGHT.E G Division of Fuel Cycle & Material Safety 78/05/19 2pp 18844 355
- 8306150271 License for NBS to export Cf-252, as ceramic oxide pellets, to Peoples Republic of China ZIMMERMAN.J V Assistant Director for Export/Import & International Safeguards 83/06/02 ip 18869 361
- 8306150337 Application to amend export license changing ultimate consignee HANNETT.B A. Transnuclear, Inc. TNP-429 83/06/03 MODRE,N Office of International Programs, Director ip 18868-347
- B306150340 Application to amend export license increasing quantity of U-235 to 1.513 kg.contained in 44,500 total U.to West Germany MARCHAL.J European Communities, Commission of B3/06/01 ORIFFIN.J A Energy, Dept of 1p 18868 348
- B306150343 Application to amend export license extending license to B40701
 HOZNIAK. D R Carpenter Technology Corp B3/06/01 HEMBY, E
 Assistant Director for Export/Import & International Bafeguards ip 18868 349.
- B306150345 Application to amend export license extending license to 840630 BRUBH.P N Hoke, Inc 83/06/02 REMBY.E NRC - No Detailed Affiliation Given ip 18868 350
- B306130349 Application to amend license to export in-core detectors, control rod drive parts & miscellaneous unspecified parts for replacing existing items in Tarapur reactor to India WILSON, B D General Electric Co BDH-064-B3 B3706/03 HEMBY, E O NRC No Detailed Affiliation Given 2pp 18868 351
- 8306150426 Application for amend to import license, increasing quantity to 18.700 kg U, enriched to 1 10% U-235
 HANNETT.B A Transnuclear, Inc. INP-434 83/05/26 MOORE.N
 Office of International Programs, Director 1p 1886
- 8306:5045: Amend 1 to Nuclear Netals, Inc export license, increasing quantity of mail authorized to 40,000 kg depleted U for export to United Kingdom PETERSON'M R. Assistant Director for Export/Import & International Safeguards 83/06/07 tp 18868 358
- 8306150493 Application for license to export miscellaneous fuel hardware to West Germany * General Electric Co BDW-067-83 83/06/03 ip 18868 359
- 8306150457 Amend 1 to Mitsui & Co. Inc export license adding Ohi Unit 2 & Genkai Unit 2 as facilities authorized to receive Zircaloy 2 & 4 tube shells
 ZIMMERMAN.J.V Assistant Director for Export/Import & International Bafeguards 83/06/01 10 18868 360
- B306150458 Application for license to export two Zircaloy tube shells to Japan BUDNOCORE. J. A Mitsui & Co , Ltd 136300 B3/05/25 3pp 18869 001
- 8306150457 Application for license to export 803 kg U-235, contained in 26,185 kg U, to Japan OKADA,8. Mitsui & Co., Ltd MBK-01-R1 83/06/01 ip. 18868 361
- B306150462 Application for license to export proportional counter, Model RB-P1-0809-101 & compensated innization chamber, Model RB-C1-2514-115 to South Korea BKARUPALJ.D Reuter-Stakes, Inc. A-9507 B3/06/03 Spg. 18849 301
- 8306150463 Forwards application for license to export enriched U hexafluoride to Japan NEKLM Marubeni America Corp (subs of Harubeni Corp). 83/06/03 MRIGHT.B L Assistant Director for Export/Import & International Safeguards 1p 18869, 212
- --8306150465 Application for license to export 723 kg U-235.as U hexafluoride.to Japan « Marubani America Corp (subs of Marubeni Corp.), ZH0298-1W 83/06/03, ip. 18867-213

- 8306150467 Application for license to export Pu-242, contained in 5 g solution of 5 molar mitric acid, to Japan FOSTER, CM Edlow International Co SHIB-13 83/06/06 ip 18869 219
- 8306150468 Ltr of assurance re export of 695 kg U-235, contained in 23,714 kg U.to Japan GHIRAKANA, T Japan, Oovt of 83/05/25 GRIFFIN, J A Energy, Dapt of Ip 18869 220
- 8306/190470 Forwards FR notice of applications for licenses to export nuclear Facilities or matls PETERSON.M R Assistant Director for Export/Import & International Safeguards 83/06/08 COMBS,T R Correspondence & Records Branch ip 18854 333
- --8306150475 Notice of applications for licenses to export nuclear facilities or matls PITERBON.M R Assistant Director for Export/Import & International Safeguards 83/06/08 2pp 18894 334
- 8306160285 License for Exxon Nuclear Co to import 26,000 kg U.enriched to 3 30% U-235,from France ZIMMERKAN.J V Office of International Programs. Director 83/06/13 ip 18893 025
- 8306160270 Forwards applications for export licenses for minor nuclear export Ltr of assurance required W/o encl ZIMMERAN.JV Assistant Director for Export/Import & International Safeguards 83/06/13 RAYMUND.JJ Energy, Dept of 2pp 18802 341
- B306160624 Application for license to export 156 kg U-235, contained in 5,171 U. to Japan OKADA, S Mitsui & Co (USA). Inc (subs of Mitsui & Co , Ltd) MBK-HI-R7 (B) 83/06/07 ip 18884 314
- 8306160628 Application to amend license to export increasing quantity to 12 270 kg U-235 contained in 27 026 kg U to Japan MARCHAL.J European Communities, Commission of 83/06/01 ORIFFIN.J A Energy, Dept of 1p 18884 313
- B306160636 Amend 1 to Nuclear Metals.Inc export license, increasing quantity of matl to 1.000 kg deploted U.contained in U blanks
 PETERBON.M R Assistant Director for Export/Import & International Bafeguards 1-201-71 B3/06/10 1p 18884 349
- B306160640 Amend 1 to Carpenter Technology Corp export license. extending expiration date to B40701 PETERBON.M R Assistant Director for Export/Import & International Bafeguards CARTECH-BPD 102 B3/06/09 ip 18884 341
- 8306160646 Application for license to export 10 pieces Zircaloy-4 guide thimble tubes to Japan BANGERTER.D H Sandvik Special Metals Corp SSM-31014 83/06/09 ip 18884 282
- 8306160653 Application for license to export 790 pieces Zircaloy-4 guide thimble tubes to Japan BANGERTER.D H Sandvik Special Metals Corp SSM-31012 83/06/09 ip 18884 335
- B306160659 Application for license to export 10 pieces Zircaloy-4 guide thimble tubes to Japan BANGERTER.D H Bandvik Epscial Metals Corp SSM-31013 83/06/09 1p 18884 352
- 8306160661 Application for license to export 340 pieces Zircalov-4 guide thimble tubes to Japan BANGERTER,D H Bandvik Special Metals Corp 86M-31009 83/06/09 ip 18884 361
- B306160668 Application for license to export 300 pieces zirconium tubing to West Germany WILBON.B D General Electric Go BDW-068-B3 83/06/06 1p
- 8306160672 Application for license to export 1 68 g U.contained in 1 8065 g U-235, to Japan POCHAL. W F Westinghouse Electric Corp ZE-60272 83/06/10 1p 18884 359
- 8306160684 Forwards application for license to export enriched U hexaeluoride to Japan MEKI.M Marubeni America Corp (subs of Marubeni Corp) 83/06/03 WRIGHT.B i. Assistant Director for Export/Import & International Bafeguards ip 18876 291.

NONDOCKETED ITEMS

- --8306160685 Application for license to export 181 kg U-235 as enriched U heasfluoride to Japan NAKAMBA N Harubeni America Cosp (sub. a) Marubeni Cosp 1 ZHO298 NW 193706703 Ppp (1887676792)
 - Obi606님, mpolication for license to eign t two U-고객 calibr plates.
- H30616069; Application for licence to export two U-P38 calibr plates, contained in wood case to Peoples Republic of China * Teledyne Ladopes 83/06/07 ip 18876 290
- 8306160716 Application to amend export license, adding add1 ultimate consigner
 MARCHAL J European Communities, Commission of 83/06/07
 ORIFFIN.JA Energy, Dept of 1p 18876-28/
- G306160720 Application to amend license to export,increasing quantity to 25 049 kg U-235 contained in 55 174 kg U-to Japan MARCHAL, J. European Communities, Commission of 83/06/01 GRIFFIN J.A. Energy, Dept. of 1p 19876 286
- 8306160723 forwards application for export bicense for minor nuclear export the of assurance required PETERSON, MR Assistant Director for Export/Import & International Safepuards 83706/13 RAYMOND, J Friergy, Dept of 1p 18076-284
- --8306160774 Application for license to export 803 kg U-235, contained in 26.185 kg U. to Japan OKADA,5; Mitsul & Co (USA), Inc. (subs. of Mitsul & Co., [td.) MMR-01-Rl 83706701 ip 18876 205
- B306200063 forwards Transmulleur, Inc application for export license for minor mullear export Ltr of assimance required ZIMMERNAN JV Assistant Director for Export/Impurt & International Bafeguards B3/06/13 RAYMOND.JJ Energy, Dopt of 1p
- 8306210374 License for GE to expost one specially designed automatic pollet insp sys to West Germany PETERSON.M R Assistant Director for Export/Import & International Safeguards BDM-83-008 83/06/07 ip 18937-085
- 8306210380 license for GC to export one specially designed automatic pollot insp sys to Heligum
 PETERSON,M R Assistant Director for Export/Import & International Safeguards 8DM-83-007 B3/06/07 Ip 18937-084
- 8306210414 Amond 3 to Hake, fine export license, extending expiration date to 840630
 PETEREON, M R Assistant Director for Export/Import // International Safeguards 1126-81 83/06/09 1p 1893/ 069

- 8306210431 Etr of assurance correcting export license application number (icense number should be XU 8368 rather than XU 8868 LEE.5 T Korea. Republic of (South Korea) 83/06/01 GRIFFIN. J A Energy, Nept of 2pp 18936-360
- 8305220270 License for Reuter-Stakes, Inc. to export one proportional counter, Model R5-P1-0809-101 & one compensated ionization chamber, Model R5-C1-2514-115, to South Korea PETERSON M R Assistant Director for Export/Import & International Safeguards A-9507 83/06/09 ip 18951-049
- 8306230023 Advises of issuance of license for Reuter-Stokes, Inc to export two neutron monitoring devices to South Korea w/o iS-day waiting period PETERSON, It R. Assistant Director for Export/Import & International Safeguards 83/06/07 Assistant Director for Export/Import & International Safeguards Ip 18982-027
- 8306240019 Application for license to export two fulljet stainless steel norries to Japan SAITOLT Mitsubishi international Corp (subs of Mitsubishi Corp) 64-7764-83 83706/08 ip 18987-292
- 8306240061 Submits Ofc of Intl Programs findings re B&W 830415 application to import 25 2 kg U.enriched to 93 16% U-235, from Cahada License should be issued MOORE,R N Office of International Programs, Director 83/06/13 Office of International Programs, Director 1p 18999 190
- 8306240325 Requests Executive Branch position re GE 830603 application for license amend to export replacement components to India PETERSON R Assistant Director for Export/Import & International Safeguards 87/06/07 STOIDER: C State, Dept of Bureau of Oceans & Intl Environ & Scientific Affairs 1p 18999 206
- 8306240362 license for Transnuclear, Inc to import 18,700 kg U.enriched to 1 104 U-235, from France ZIMMERMAN, J V Office of International Programs, Director 83/06/13 ip 18998-361
- 830628029B forwards application for license to export 25,000 kg U depleted U tails, in form of U herafluoride, to Taiwan MACNABB.W V NUS Corp MP-WWH-83-050 83/06/10 HEMBY, E Office of International Programs. Director ip
- --8306280°61 Application for license to expert 25.000 kg U depleted U tails in form of U hexafluoride to Taiwan End use statement enci MCLEOD, N B NUS Corp NUS-2793 83/06/13 3pp

The subject category column in this index gives the docket number and the symbol for the category of information within that docket; for example, 50-320 P. The docket subject categories are defined in Appendix A.

Subject categories for nondocketed items are also entered in this column by symbol; for example, ACRS. These categories are defined in Appendix B and listed in the Contents. An asterisk following the accession number in this index indicates that the document is an enclosure to another document. To obtain the accession number of the principal document under which the enclosure is listed, refer to the index entitled "Cross Reference of Enclosures to Principal Documents."

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEOUR
			ALBANESE, J R	8304010094	50-201 P	ANDOGNINI.0 C	8306160064*	50-528
AAMODT, M	8304090297	50-289 G	ALDEN, W M	B306160379	50-277 R	ANDOGNINI.0 C	8306170356	50-526
AAMODT: M	8306150427	50 -289 A	ALDEN, W M	8306170163	50-277 R	ANDOGNINI.C C	#306170360*	50-528
M M T GOMAA	09104040190	50-289 G	ALDEN, W M	8306210076	50-27/ R	ANDOGNINI, C C	0306230252	50-528
AAMODT, M N	8304220048	50-289 G	ALEXANDER, I	B306140243*	50-206 G	ANDREWS, W B	8304020131	NUREO
M M TOOMAA	8304220147	50-209 G						
AAMANT NI M	8304070420	50-289 G	ALEXANDER, J F	#18E06160EB	50~322 0	ANDRUB, N J	8304200067	40-4492
AAMODT, N ()	8304220142	50-289 Q	ALEXICH M P	80\$07020B	50-315 P	ANO. H P	8306170023*	50-454
AAMODT,N O AARON,J	8306170423	50-29A B	ALEXICH, M P	8306170129	50-315 0	ANO. N. P.	8306270424*	50~389
ABELGON, H	8309050450	50-461 A	ALEXICH, M P	#84001S40EB	50-315 Q	ANTHONY, R C	830427003B	50-352
ABELSON, H	8306020420 8306240138	50-951 A	ALEXICH, M P	8306210167	50-315 P	ANTHONY, R C.	830627003B	50-352
NDEGGON II	00000-10100	DW 13411 /1		*************	50-915 F	APLEY, W J	8306020134	NUREO
ACTON, R U	B304020014	NUREG	ALEXICH M P	8304230333		ARAND, J	9306210089	50-373
ADAMETZ, J M	0304040057*	50-244 P	ALLAN, J. M	B309090555	State Prog 50-412 G	ARAND, J J	8306210007	50~373
ADAMONIS, D C	#40000140EB	50 445 ()	ALLAN, J M	8304040287	50-219 0	ARAND, J J	B306210263	50-373
ADAMB, L T	8306130370*	50 -331 B	ALLAN, J. M	8304090041	50-217 G 50-273 G	ARCHITZEL, R E	B306010324*	50-317
ADAMB, R E	8306270146	NUREQ	ALLAN, J M	8304140432	20-273 4	HIGHT TILLYIN E	D000100£4×	00 017
	,		41.44 1.44	B306140658	50-412 Q	ARIAS, J	8304210197	50-251
ADAMB,R H	8304140547*	50-324 G	ALLAN, J. M.	B306170008	50-244 F	ARIAS, J	8306270200	50-251
ADAMS, S R	8304020011	NURFO	ALLAN, J M	£306170008	50-333 F	ARIAB, J	830428014B	50-250
ADENBAM, C Q	8304020042	50-329 L	ALLAN J M	6306170036	50-309 F	ARLOTTI, M G.	8306140598	50~286
ADENSAM, E Q	8304020401	50-329 A	ALLAN V M	1010024068	State Prog	ARLOTTI, M G.	8306200402*	50-286
ADENBAM, E G	016050908	50-329 E	ALLAN, J M	\$300800101	State 1 Lpd	11125112711 01	000mm0010A.	00 1100
			ALLAN, J M	8305210145	50-219 0	ARNOLD, R. C	8304140600	50~320
ADENBAM, E C	8306070428	50-370 P	ALLAN, J M	8306210149*	50-219 0	J A NOBROSA	8304010478	RES
ADENBAM, E G	8306070433	50~369 F	ALLANIJ M	B306220149	50-410 0	ARTHUR, J	8306020192	WASTE MO
ADENBAM, E Q	8306070434*	50-370 P		8304220154*	50-410 G	ARTHUR, J	B306020194	HASTE MO
ADENBAM, E 0	8304140287	50-390 A	ALLAN, J M	8306220155	50-387 Q	ARTHUR, J	8304220208	OM STEAM
ADENSAM, E G	8304140299	50-328 P	ALLAN, J M	dittario133	50 007 0	***************************************		M.10 1 W 112
			ALLAN, J M	B304220157*	50-397 0	ARTHUR, J.	B306240482	WASTE MO
ADENSAM, E G	8306150510	50-327 F	ALLAN, J M	8306280473	70-364	ASHE, J	83042402274	QA797
ADENSAM, E Q	8306160277	50-369 P	ALLEN R E	8306160468	REGED	ABHTON, A M	8306220192*	CONTRACT
ADENBAM, E Q	B304210404	50~369 P	ALLING M E	#1810E040EB	50-271 P	ASSELBTINE	8306270278*	50-289
ADENBAM, C G	8306240017	50-460 A	ALTENBACH, T J	8306150617	NUREC	ATWOOD, M D	8306130243	40-8722
ADENBAM, C G	8306280029	50-369 P	ALIENDACHI I U	9300100017	Homew			
			AMADON, P W	8304080215	90-35B ¢	AU, T Y	8304010372	50-352
ADENBAM, E Q	8306280064	50-329 E	AMADON, P W	B3040B0250	50-358 P	AU, T Y	#08010380#	50-352
ADENBAM, C G	8306290135#	50-556 A	AMEB, K.R.	8306030007	NUREO	AUDIN, L	8304230123	50-14
ADLER, R W	8306070271	50-289 G	AMICO, P	8211220337*	50-245 P	AULUCK, R	8306070481	50~397
ADLER, R W	8304070407*	50-209 0	AMICO, P. J	830602044D*	50-247 0	O WITBUA	8306140412	50-295
ADLER,R W	0304220046	50-289 A	MITTER OF T	цировно гла				
			AMICO:P J	9306020452*	50-247 G	AUSTIN, M. A	8304200020	70-135
ADRAGNA, J M	8306160155	FBIA	AMOROSE, A A	8306230018*	FOIA	AUTIO, H A	8306170033	50-27
AFTERGOOD, 8	6306030457	LOIV	AMOROSE, M L	B306230016*	FOIA	AUTIO, H A	8306170418	50~29
AFTERGOOD, B	#906170379*	50-142 T	AMOROSI, A	8305240612*	COMMISSION	A H,DITUA	8306280107	50-29
AFTERGOOD, 5	B304170390*	50-142 7	AMORDSI.A	0305240624*	COMMISSION	AUTIO, H A	8306280144	50-29
AFTERGOOD, 9	8306170417*	50-142 T						
			AMSTUTZ, B	B304060095	50-155 R	AUTIO, H H	8304170339	50-29
AFTERGOOD, 9	8306170426*	50-1422 T	AMSTUTZ, S	0306160566	50-155 R	AXELRAD, J	8304010066 84001040EB	50-219
AGNIHOTRI,N K	8004030373	LOIV	ANANDAPPA, A	8306070279	50-249 8	AXELRAD, J	8304010183	1&E
AHEARNE, J	8304070021*	50-204 P	ANDER BEN, M	8304200223	50-331 R	A XELRAD, J	8304010310	50-249
AHEARNE, J	8306270281*	50-289 G	ANDERSON, A S	8304230144*	FOIA	A XELRAD, J	8304020179	50-321
AHEARNE, J F.	8306070020*	50-206 P						
			ANDERBON, A G	B304230166*	FOJA	AXELRAD, J	B306140416	16E
AHEARNE, J F.	B306170449	COMMISSION	ANDERSON, C.	8304020374*	50-354 G	AXELRAD, J.	8306140696	50-414
AHEARNE, J [8306220198	50-272 P	ANDERSON, C.	8304040170*	50~277 G	AXELRAD	B306200149	50-254
AHEARNE, J F	#44£05240E8	50-320 P	ANDERSON, C	#48000240EB	50-423 G	AXELRAD, J.	8309510131	IFE
AHMED, I	*846200190E8	50-374 0	ANDERSON, C R	·8306240302#	50-244 P	AXELRAD, J	9010059058	50-324
AHMED, N	83040B0252*	50-335 P				AUPL BAR I	B05/500// =	
	000/1500//*	90~259 P	ANDERSON D J	8306140426*	CONTRACT	AXELRAD, J	B306300115	16E
AHMED, N	9304150246¥	50~259 P	ANDERSON, R L	8306140583*	50-416 0	AXELRAD, J. A.	0306150270	50-367
AHRENB, P	8306090218	50-309 0	ANDERBON, B L	B304010094	50-201 P	AXELRAD, J A	8306210450	50-219
AHRENS, P	8306100193*	50-309 G	ANDOGNINI,0 C	8307010373	50-528 G	AXELRAD, J A	8306220135	50-298
AHRENS, P	8306100205*	50~309 W 50~335 P	ANDOGNINI.O C	0306070432	70-2784	AXELRAD, J A	8304220137	50-361
WEEB'D M'	1410804068	gurada r						

AUTHOR	ACCESSION NUMBER	SUBJECT	AUTHOR	ACCESSION NUMBER	SUBJEC1 CATEGORY	AUTHON	ACCESSION NUMBER	SUBJECT CATEGORY
AXELRAD, J A AXELRAD, J A AXELRAD, J A AXELRAD, J A	8306220144 8306220204 8306220218 8306220271 8306220274	50-313 (50-237 (40-8698 40-8681	9 BARRETT,L H 0 BARRETT,L H 9 BARRETT,L H DARRETT,L H BARRETT,L H	8304160443 8304160682 8304200031 8304200044 8304280220*	50-320 R 50-320 P 50-320 R 50-320 R 50-320 P	BAYNE, J P BAYNE, J P BAYNE, J P BAYNE, J P BAYNE, J P	8306210144 8306210178 8306230170 8306280508 8306090325	50-286 P 50-286 P 50-333 P 50-333 P 50-247 F
AXELBON, W AXELBON, W AZARH, M BACHMANN, R BACHMANN, R G	8306100212* 8306130412* 8306280044 8306080081 8306150391	50-254 (NUREQ 50-155 (BARRETT, L H BARRETT, P A BARRETT, P A BARRETT, P A BARTH, C A BARTH, C A	8304280458 8304030151* 8304040138* 8304200333 8304240267	50-320 R 50-440 G 50-358 G 50-358 G 50-358 G	BAYON, J P BAZIN, J P BEACH, A B BEACH, Q BEATY, W R	8306090340 8306170026 8306080224* 8306200425 8306160322*	50-247 F CONTRACT 50-445 G 40-8380 50-483 G
BACHMANNIR G BACKUS.R A BACKUS.R A BACKUS.R A BACKUS.R A	8306170363 #306010444 #306200291 #306200293* #306270521	50~155 (50-443 (FOIA FOIA 50-443 (BASKIN, K P BASKIN, K P BASKIN, K P BASKIN, K P BASKIN, K P	8304280090 8304070313 8304080020 8304090154 8304130384	50-400 6 50-361 P 50-361 P 50-361 P 50-206 P	BEATY, W R BEAUX, D G BEAVAN, L A BECHHOEFER, C BECHHOEFER, C	8306160322* 8306130224* 8306070106* 8306020487 8306130420	50~483
BACKUS,R A BACKUS,R A BACKUS,R A BADIA,A BADIA,A	8306270521 8306270532 8306270532 8306230020* 8306230025*	50-443 0 50-443 0 50-443 0 FOIA FOIA	RASKIN.K P	8306140444 8306140444 8306150303 8306200156 8306270362	50~361 P 50~361 P 50~206 P 50~206 P 50~206 P	BECHHOEFER, C BECK, G P BECK, R H BECKER, B D BECKER, M	8306270148 8306070023 8306230496# 8306070342 8306070473	50-498 0 50-151 0 CONTRACI 50-454 0 NUREQ
BADING,A BAER,R E BAILEY,R J BAIR,Q O	8304080307 8304080079* 8304230462 8304070044* 8304070071	50-358 A 50-382 0 50-334 8 50-219 0 50-344 9	BASKIN, K P BASS, G W BASS, L F	8306270415 8306380057 8306070159 8306010277 8306210046	50-204 P 50-361 P 50-259 6 50-317 9 50-318 5	BECKHAM, J T BECKHAM, J T BECKHAM, J T BECKHAM, J T BECKHAM, J T	8306010367 8306070351 8306140493* 8306140563 8306140743*	50-366 P 50-321 P 50-364 Q 50-321 Q
Bair, g g Bair, d g Bair, d Baker, t Balaram, J	B306170193 B306170317 B306210391 B306040309* B306070473	50-344 5 50-344 5 CONTRACT 70-25 NUREG		8306210086 8306210099 8306210101 8306210159 8306140575*	50-317 8 50-318 \$ 50-317 \$ 50-318 \$ 70-1113	DECKHAM, J T DECKHAM, J T DECKHAM, J T BECKHAM, J T BECKHAM, J T	8306220002 8306270120 8306270264 8306270265* 8306270455	50-321 P 50-346 P 50-321 0 50-321 0 50-321 0
BALL.D M BALL.J C BALLARD.T A BALLINGER.P.L BALLINGER.P.L	8306020231 8306280093 8306230351* 8306020148 8306130339	WASTE MOT NUREO 50-331 P 50-298 R 50-298 S	BATTERSON, S BATT, D	8306020139 8306020152 8306160382 8306160444 8306140604	50-29 R 50-309 R 50-29 R 50-309 R 50-272 H	BECKHAM, J T BECKMAN, R J BEGOVICH, C L BELANGER, J L BELANGER, J L	8304300085 8304280013 8304210350 8304103273* 8304130317*	50-321 Q NUMEO NUMEO 50-315 Q 50-346 Q
BALLINGER, P L BALLINGER, P L BALLINGER, P L BANDY, R BANGART, R L.	8306160477 8306160488 8306160494 8306030435 8306010107*	50-278 R 50-278 R 50-278 S RES 50-313 G	BAUBLITZ, J E BAUBLITZ, J E BAUER, E G BAUER, E G	8304010103 8304020255 8304220149 8304010239* 8304140404	40-84 Waste mgt Waste mgt 50-352 a 50-352 e	BELISLE.0 A BELL, J M BELL, L W BELL, M J BELL, M J	8306140471* 8306060266* 8306210390 8306090200 8306240011*	50-375 0 50-320 0 NUREO MISC FOIA
BANGART,R L. BANGART,R L. BANGART,R L BANGART,R L BANGART,R L,	8304010354* 8304070318 8304140634* 8306210239 8306240180	50-498 0 MISC 50-382 0 MISC GA999	BAUER, R H	8306270264* 8306300117 8306230501* 8306230199* 8306220108	50-277 P 50-373 F 50-320 P 50-244 Q 50-400 Q	BELL, M J BELL, M J BELL, M J BELL, M J BELL, M J	8306240016* 8306240020* 8306240024* 8306240160* 8306240168*	FDIA FDIA FDIA FDIA FDIA
BANGART.R L BANGERTER.D H BANGERTER.D H BANGERTER.D H BANGERTER.D H	B304240204* B304140646 B304140453 B304140459 B304140461	GA999 XPORTLIC XPORTLIC XPORTLIC XPORTLIC	BAUSER, D B BAUSER, D B BAUSER, D B BAUSER, D B BAUSER, D B	830422010B 8304220111* 8304220399 8306290399	50-400 G 50-400 G 50-400 G 50-289 G 50-289 G	BELL, N BELL, N BELL, N BELL, N BELLGITI, F X	8304010344 8304040308 8304140078 8304220127 8304280583	50-460 0 50-460 0 FOIA 50-50B 0 50-443 0
BARAN, R BARANOW, 9 W BARANOW, 9 W BARANOW, 9 W BARANOW, 9 W	8304020090 8304130308 8304130444 8304230121 8304270242	50-219 R 50-329 A TOPREP 50-329 A 50-329 A	BAXTER, H BAXTER, T A BAXTER, T A	8306160201 8306070163* 8306100091 8306100091 8306160314	PR 0A999 50-400 G 50-400 G 50-483 G	DELMORE,C I BELMORE,C I BEMIB.P DEMIB.P R BERGER,R H	8306060252 8306070235 8306140705* 8306140423* 8306080343*	50-217 R 50-219 R 50-324 G 50-324 G 50-410 A
BARANOW, S W BARANOW, S W BARATTA, A J BARBER, O BARBER, O	B304270271 B304270307 B304070452 B304010310 B304020179	50-329 V 50-329 A NUREG 50-269 G 50-321 G	BAXTER, T A	8306140314 8306220132 8306220132 8306220137# 8306230345	50-483 Q 50-483 Q 50-483 Q 50-483 Q 50-400 Q	BERICK, D BERICK, D BERICK, D M BERICK, D M BERKLEY, J	8304300137 8304300142 8304040244 8304040248* 8304020240*	PR PR PRM PRM 50-P72 F
BARBER.Q BARBER.Q BARHAM.C D BARHAM.C H BARLETTA.R E	B304200147 B304300104 B304210082 B304210107 B30401008B	50-254 Q 50-324 S 50-324 J 50-324 J NUREG	BAXTER, T A BAXTER, T. A BAXTER, T A BAXTER, T A BAYNE, J P	8306230345 8306290395 8306290395 8306300050 8306030224	50-400 G 50-400 G 50-400 G 50-289 G 50-286 P	BERLIN, K BERLIN, K BERLIN, K BERLIN, K BERLIN, K	8304030333 8304030334* 8304030335* 8304100078* 8304150398	50-529 6 50-529 6 50-529 6 50-529 6 50-529 6
BARLETTA, R. E. BARNES, C. BARNES, I. BARNES, I. BARNES, I.	8304020046 8304080309 8304210031* 8304210238* 8304270454*	NUREQ 50-148 P 0A999 0A999 0A999	9 C.3MYAB 9 C.3MYAB 9 C.3MYAB 9 C.3MYAB 9 C.3MYAB	8304040121 8304070185 8304070197* 8304070303 8304080034	50-333 P 50-284 P 50-284 P 50-333 P 50-284 P	BERLIN, X BERMAN, M BERNABEI, L BERNARD, H BERNDT, J	8306150398 8306020007 8306080284 8306160017* 8306300152	50-529 G NUREG 50-528 A 50-142 [PR
BARNES, P. L. BARNES, P. L. BARNETT, T. BARR, K.	8306100094 8306170380 8306280377 8306010458 8306150008*	50-237 Q 50-237 Q 50-304 Q 50-247 Q 50-289 Q	PAYNE, J P. Bayne, J P Bayne, J P Bayne, J P Bayne, J P	830 60 70 30 2 830 60 70 30 4 # 830 60 70 31 7 830 60 70 35 7 830 61 00 100	50-286 P 50-286 P 50-247 F 50-247 G 50-330 P	BERNERO,R M BERNERO,R M BERNERO,R M BERNHOFT,S BERSTLER,L R	8109210318* 8207280024* 8306240295* 8306270110 8306060018*	50-287 P 50-313 P 50-247 0 50-305 S 50-354 0
BARR, K, BARR, K P BARR, K P BARR, K P BARR, K P	9306170345 9306140357# 9306140477# 9306270229# 9306270244#	70-143 70-1113 50-348 G 50-259 G 50-414 G	BAYNE,J P BAYNE,J P Bayne,J P Bayne,J P Bayne,J P	8304100113 8304100253 8304130111 8304140277 8304140318	50-284 P 50-284 P 50-286 I 50-286 P 50-333 P	BESS, J E BETTENHAUSEN, L BETTENHAUSEN, L BETTENHAUSEN, L BETTENHAUSEN, L	8304140374* 8304010231* 8304070131* 8304200130* 8304200134*	50-445 Q 50-333 Q 50-322 Q 50-277 Q 50-367 Q
BARR, K. P. BARR, K. R. BARRETT, L. H. BARRETT, L. H	8304270297* 8304270380* 8304040264* 8304020408 8304020454	50-259 0 50-302 0 50-320 0 50-320 0 50-320 R	BAYNE, J P Bayne, J P Bayne, J P Bayne, J P Bayne, J P	8306140598 8306160450 8306170249 8306200401 8306210138	50-284 P 50-284 Q 50-286 P 50-286 P 50-286 P	BETTENHAUBEN,L BEVERLY,K P BEVERLY,K P. BIALIK,E I. BIALIK,E I	8304210103* 8304130374 8304130382 8304300158 8304300174	50-213 G 50-237 S 50-237 S PR PR

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT	AUTHOR	ACCESSION NUMBER	SUBJECT CATEODRY
BIAN, S H BIBB, H E BIBB, H E BIDEN, J R BIDINGER, G H	8304020134 8304290225* 8304290377* 8304150543* 8304080054*	NUREQ 50-389 Q 50-335 Q 50-272 U 70-2910	BOMBERGER, C BOMBERGER, C BOMBERGER, C BOMBERGER, C BOMBERGER, C	830 5200714* 830 6020037* 830 6020196* 830 6030310* 830 6080252*	50-305 P 50-309 P 50-302 P 50-317 P 50-335 P	BOUCHEY, G D BOUCHEY, G D BOUCHEY, G D	8304010413 8304080024 8304080037 8304090207 8304090207	50-397 70-2950 50-397 50-508 50-460
BIDINGER. © H BIDINGER. © H BIDINGER. © H BIDINGER. © H BIELAWSKI. A P.	8306080396* 8306150335* 8306210440* 8306290687* 8306060196*	70-2838 70-1257 70-143 70-2375 50-454 G	BOMBERGER, C BOMBERGER, C BOMBERGER, C BOMBERGER, C R BOOK, H	830 &140 424* 830 &150 2&&* 830 &030 070* 830 &0&0327* 830 &280 303	50~219 P 50~259 P 50~338 P 50~277 P 50~528 Q	BOUCHEY, Q D BOUCHEY, Q D BOUCHEY, Q D	8306100117 8306130004 8306140612 8306200243 8306210120	50-50B 50-397 50-460 50-397 50-397
BIELAWSKI,A P BIELAWSKI,A P BIELAWSKI,A P BIELAWSKI,A P	8306060176# 8306150402 8306150402 8306150420 8306150420	50-454 0 50-454 0 50-454 0 50-454 0	BOOK, H. BOOK, H. E BOOK, H. E BOOK, H. E BOOK, H. E	830 6280 507 * 830 601 01 59 830 607 000 9 830 607 001 1 * 830 607 01 76 *	50~397	BOUCHEY, Q D BOUCHEY, Q D BOUCHEY, Q D	8306210154 8306230373 8306240339 8306240460 8306270347	50-508 50-508 70-2950 70-2950 50-397
BIELAWSKI.A P BIELAWSKI.A P BIER.J BIER.J A BILEK.N L	8306270041 8306270041 8306080232 8306080235* 8306210293	50-454	BOOK, H E BOOK, H E BOOK, H E BOOK, H E	830 4070 285 830 4070 287* 830 4070 333 830 4070 337* 830 4280 137	50-243 Q 50-243 Q 50-206 Q 50-206 Q 50-528 Q	BOUCHEY, O D BOUKNIGHT, R J BOUKNIGHT, R J BOUKNIGHT, R J	8306280453 8306070202 8306100163 8306100261 8306210021	50-397 50-395 50-395 50-395 50-395
BINCHAM, W G BISBEE, G D BISBEE, G D BISBOP, D J BISBOP, L L	8306070107# 8306010342 8306010384 8306150064 8306010443*	50~529 8 50~443 0 50~443 0 50~272 P 50~443 0	BOOK, H E BOOK, H E BOOK, H E BOOK, H E	830 62801 45* 830 62801 71 830 62801 85* 830 6280310* 830 6280503	50-528	BOUKNIGHT,R J BOUKNIGHT,R J BOURNIA,A BOUTROS,F G. BOHMAKER,N J	8306210207 8306300156 8306240406 8306140737* 8306070227	50-395 50-395 50-373 50-289 50-317
BISHOP,R W BISHOP,T W BISHOP,T W BISHOP,T W BISHOP,T W	8304110734 8306070093 8306070240 8306070251 8306070360	50-245 I 50-275 G 50-206 Q 50-206 Q 50-275 Q	BOOK, H. E BOOK, H E BOOKER, J E BOOKER, J E BOOKER, J E	830 6280620 830 6280632* 830 6270080* 830 6010374 830 6010423	50~344	BOWHAKER, N J BOWHAN, M E BOWYER, J E BOWYER, J E, BOWYER, J E	8306280465* 8306070077 8306170155* 8306170167* 8306170170*	50-317 50-317 FOIA FOIA FOIA
BISHOP, T W BISHOP, T W BISHOP, T W BISHOP, T W BISHOP, T W	8304070341 8304270342* 8304280187 8304280477 8304280479	50-341 0 50-275 0 50-275 0 50-206 0 50-341 0	BOOKER, J E BOOKER, J E BOOKER, J E BOOKER, J E	830 60701 95 830 60701 96 830 6070265 830 6090038 830 6090365	50-458 8 50-458 9 50-458 8 50-458 8	BDHYER, J E BOHYER, J E BOHYER, J E BOHYER, J E BOHYER, J E	8306170174* 8306170178* 8306170185* 8306170190* 8306170198*	FOIA FOIA FOIA FOIA
BISHOP, T W BISHOP, T W BISSONNETTE, P BLACK, S A BLACKBURN, T A	8306280546 8306300083 8306070294* 8306020017 8306240208*	50-361 G 50-275 G 0A999 70-124 50-206 P	BOOKER, JE BOOKER, JE BOOKER, JE BOOKER, JE BOOKER, JE	830 6130317 830 6130376 830 6160353 830 6160439 830 6160520	50-458 B 50-458 B 50-458 S 50-458 B 50-458 B	BOWYER, J. E.	8304170203* 8304170208* 8304170212* 8304170220* 8304170225*	FDIA FOIA FOIA FOIA FOIA
BLAIR.C C BLAKE.E L BLAKE.E L BLAKE.E L BLAKE.E L	8306010073 8306010454 8306010454 8306030327 8306090211	50-344 8 50-889 9 50-289 0 50-289 0 50-289 0	BOOKER, JE BOOKER, JE BOOKER, JE BOOKER, JE	830 61 60 521 830 61 60 531 830 61 70 39 5 830 62 70 07 5 830 62 70 130	50-458 8 50-458 9 50-458 9 50-458 8 50-458 8	BOMYER.JE BOMYER.JE BOMYER.JE BOMYER.JE	8306170235* 8306170238* 8306170242* 8306170244* 8306170248*	FOIA FOIA FOIA FOIA FOIA
BLAKE, E L.	8304090211 8304130390 8304150410 8304150410 8306220071	50-289 0 50-289 0 50-289 0 50-289 0 50-209 0	BOOKER, JE BOOKER, JE BOOKER, JE BOOKER, JE BOOKER, JE	830 6270 1 56 830 6270 391 830 6280 328 830 6280 335 830 6300 1 21	50-458 B 50-458 S 50-458 A 50-458 S 50-458 S	BOHYER, J E BOHYER, J E BOHYER, J E BOHYER, J E, BOHYER, J E,	8304170252* 8304170258* 8304170262* 8304170247* 8306170267*	FOIA FOIA FOIA FOIA
BLAKE,E L BLAKE,E L BLAKE,J J BLAKE,J J	8306220071 8306300087 8306300087 8306140139* 8306140349*	50-289 0 50-289 0 50-289 0 50-438 0 50-335 0	BOOKER, J E BOOKER, J M BORCHERT, R BORDENICK, B M. BORDENICK, B M.	830 6300 1 48 830 62800 13 830 6280 430 830 6020 181 830 6060 3 12	50-458 8 NURE0 50-336 8 50-322 0 50-322 0	BOHYER, J E	8306170272* 8306170274* 8306170280* 8306170284* 8306170288*	FOIA FOIA FOIA FOIA
BLAKE, J J BLAKE, J J BLAKE, J J BLAKE, J J BLAKE, J J	B306140439# B306140511# B30614052# B306140652# B306270172#	50-424 Q 50-413 Q 50-321 Q 50-338 Q 50-413 Q	BORDENICK, B M. BORDENICK, B M. BORDENICK, B M. BORDENICK, B M. BORDENICK, B M.	830 6100240 830 6100242* 830 6130387 830 6150211 830 6150214*	50-322	BOYD, D BOYD, D C, BOYD, D C BOYER, V B, BOYER, V B	8306220060 8306060221* 8306300021* 8306060157 8306160607*	50-295 50-295 50-255 50-277 50-352
BLAKE, J J BLAKE, J J BLAKE, J J BLAKE, J, J BLANCHARD, D P.	8306270235* 8306270332* 8306270357* 8306270424* 8306280557	50-438 0 50-321 0 50-250 0 50-389 0 50-155 P	BORDENICK, B M. BORDENICK, B M. BORDENICK, B M BORDENICK, B M BORDENICK, B M.	830 61 50250 830 6230004 830 6240273 830 6240278 830 6240355	50-322 0 50-322 0 50-410 0 50-410 0 50-410 0	BDYLE,R BDYLE,R R BOYLE,R R BRADBURY,R. B, BRADFORD,P. A,	8306150216 8306030244 8306240116* 8306160347 8306160118*	50-201 HASTE MOT FOIA NUREO FOIA
BLAND. H BLEIMILLER, E S BLEJWAS, T. E BLETZACKER, R. H BLIX, H	B306160401 B306130378 B306020080 B306070352* B306160156*	NUREG 50-322 9 NUREG 50-413 F FOIA	BORDENICK, B M BORDINE, T BORDINE, T, C BORDINE, T, C BORDINE, T, C	830 6300070 830 6010362 830 5260226 830 5260265 830 6020283	50-322	BRADFORD, W. H BRADLEY, E. J. BRADLEY, E. J. BRADLEY, E. J. BRADLEY, E. J.	8306270222* 8306010232 8306010272 8306070237 8306070330	50-348 50-352 50-352 50-352 50-352
BLOCH, P B BLOCH, P B BLOUGH, A R BLOUGH, A R BLUBAUCH, R E	8306280552 8306280556 8306030312* 8306070226* 8306200107	50-155 0 50-445 0 50-277 0 50-277 0 40-3453	BORDINE, T C BORDINE, T C BORDINE, T, C BORDINE, T C BORDINE, T C	930 60601 44 930 61 50003 930 61 60380 930 6210173 930 6230241	50-155 P 50-155 P 50-155 P 50-155 P 50-155 B	BRADLEY, E. J. BRADLEY, E. J. BRADLEY, E. J. BRADLEY, E. J. BRADLEY, E. J.	8306100065 8306100107 8306100110 8306100241 8306140375	50-352 50-352 50-352 50-352
BDARDMAN, J. R BDARDMAN, J. R BDQART, D. B BDQDEN, Q. BOQDEN, Q.	83060600060# 8306060122# 8306230449 8306230074 8306230032	50-498	BORDINE, T C BORDINE, T C BORDINE, T C BORN, C, S BORYBIAK, M	830 6240004 830 62701 25 830 6270376 830 6230 282 830 6210084	50-155 P 50-155 P 50-155 0 50-182 8 50-346 8	BRADLEY, E.J. BRADLEY, E.J. BRADLEY, E.J. BRADLEY, E.J. BRADLEY, E.J.	8306140545 8306140624 8306160001 8306160371 8306160377	50-352 50-352 50-352 50-352 50-352
BOCEN, P. E. BOHL, L. S BOHL, L. S BOHNER, E. A BOLTZ, D. H	8306060101# 8306070171# 8306210028# 8306280382 8306100230#	50-358 E GA779 GA779 50-546 D 50-445 C	BOSTROM, D O BOUCHEY, G D BOUCHEY, G D BOUCHEY, G D BOUCHEY, G D.	830 5230 404* 830 5280 575 830 501 0235 830 501 0247 830 501 0400	9A999 50-397 A 50-397 A 50-397 A 50-397 F	BRADLEY, E. J. Bradley, E. J. Bradley, E. J. Bradley, E. J. Bradley, E. J.	8306160527 8306160572 8306170210 8306170309 8306170369	50-352 50-352 50-352 50-352 50-352

AUTHOR	ACCESSION	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
RADLEY,E J RADLEY,E J RADLEY,E J RADLEY,E J	8306200117 8306200183 8306200317 8306210283 8306270086	50-352 A 50-352 F 50-352 E 50-352 C 50-352 E	BROWN, G D BROWN, G D BROWN, G D BROWN, H H BROWN, H H	8306090172 8306130353 8306160362# 8306060184 8306060184	40-8643 MISC 90-298 0 50-322 0 50-322 0	CAIN, C L CAIN, C L CAIN, C L CAIN, C L CAIN, J M	8304070138* 8304070175* 8304140124* 8304140132* 8304040120*	40-8698 40-8084 FOIA FOIA 50-382 J
RADLEY, E J IRADLEY, E J IRADLEY, E J IRADLEY, E J	8306270212 8306270261 8306270264* 8306270340 8306270365	50-352 A 50-277 P 50-277 P 50-352 E 50-352 A	8ROWN, H H 8ROWN, H H 8ROWN, H H 8ROWN, H H	8304080169 8304080149 8304090216 8304090216 8306150397	50-322	CALDWELL, R A CALLAN, L J CALLAN, L J CALLAN, L J CALLAN, D	8306240148* 8306140363* 8306160317 8306160644 8306200274	50-274 0 50-313 0 50-313 8 50-313 8 50-454 0
IRADLEY, E J IRADLEY, E J IRADLEY, E J IRADLEY, E J	8306270423 8306270459 8306280589 8306300016 8306300024	50-352 A 50-352 A 50-352 A 50-352 E 50-352 A	BEOMN, H H BROWN, K J BROWN, K J BROWN, H H BROWN, P	B304150397 B004200484* B304130347 B304270281* B304010107*	40-8745 CONTRACT	CAMERON,C A CAMP,A L CAMPBELL,D R CAMPBELL,C D CAMPBELL,K	8304100121 8304010144 8304240312# 8304300139 8304280013	PT21 NUREG 50-244 P 50-259 S NUREG
IRADLEY, E J IRADLEY, E J, IRADLEY, E J IRADY, J A IRADY, R J	8305300133 8305300200 8305300221 8305220298* 8305150152*	50-352 A 50-352 E 50-352 A 50-289 F FOIA	BROWN,R L BROWN,S H BROWNING,R E BROWNING,R E BROWNING,R E	8306060073# 8306230038# 8306030438 8306220164 8306220174#	50-458 @ FOIA WASTE MOT WASTE MOT WASTE NOT	CAMPBELL, L D CANDIA, G R CANTRELL, F B CANTRELL, F B CANTRELL, F B	B306210277 B306280433* B306070043 B306140297* B306140583*	50-373 8 70-1402 50-259 8 50-259 0 50-416 0
IRAGO, J. 8. IRAILE: L H. IRAMLETT: L 8 IRAMLETT: L 8 IRANCH: M W	8304100084 8304080148 8304020150 8304140474 8304270389*	50-247	BROWNING, R. E BROWNING, R. E BROWNLEE, V. BROWNLEE, V. L BROWNLEE, V. L	6306240155* 6306240163* 6306100176 6306140467* 6306270273*	FOIA FOIA 50-413 8 50-302 0 50-321 0	CANTRELL.F S CANTWELL.P F CANTWELL.P F CAPHTON,D L CAREW,J F	8306270222* 8306210234 8306270168 8306070146* 8303220403*	50~34B 0 50~304 8 50~295 8 50~317 0 TOPRCP
IRAND, D. A. IRAND, D. A. IRANDENBURG, B. IRANDENBURG, B. IRANDENBURG, B. IRANDENBURG, B.	8304210080 8304210142 8304070414 8304150429 8304200342	50-133 Q 50-275 R 50-247 Q 50-247 Q 50-247 T	BROHNLEE, V. L BRUGGER: R BRUGH: P N BRUGH: P N BUCHANAN: C R	8306290305* 8306150165 8306030160 8306150345 8306170194*	50-413 G 50-186 F XPORTLIC XPORTLIC FOIA	CAREW, J F CAREY, J J CAREY, J J CAREY, J J CAREY, J J	8304010478 8304020218 8304030303* 8304070074 8304070264	RE8 50-334 R 50-334 D 50-334 F
IRANDENBURG, B. RANDENBURG, B. BRANDEN, C. T. BRANNEN, W. A. BRANNIN, J. F.	8306230376 8306270160 8306080241* 8306140737* 8306210081	50-247 0 50-247 0 50-445 0 50-289 F 50-389 S	BUCHANAN, C R BUDZIK, D M BUDZIK, D, M BUFE, J L BULLOCK, S V	8306170227# 8306160443 8306160468 8306070273 8306060249	FOIA REGOD REGOD 50-302 S PR	CAREY, J J CAREY, J J CAREY, J J CAREY, J J	8306090189 8306090368 8306140620 8306140639 8306160476	50-334 F 50-334 P 50-334 Q 50-334 P 50-334 R
RANNIN, J. P RANNIN, J. P RANNIN, J. P RANNIN, J. P RENIZER, J. B.	B304010114 B304070058 B304070181 B304220014 B304140005	50-389 8 50-389 8 50-389 8 50-389 8 50-42 8	C C.ONITHUE C C.ONITHUE A C.SRCCOHOUS A C.SRCCOHOUS A C.SRCCOHOUS A C.SRCCOHOUS	8306240039* 8306240047* 8306030165 8306140260 8306150458	FOIA FOIA XPORTLIC XPORTLIC XPORTLIC	CAREY, J J CAREY, J J CAREY, J J CARLISLE, C B	8306200334 8306280435 8306280475* 8306300207 8306010220	50-334 P 50-334 Q 50-334 O PR 50-397 S
IRENNEMAN, F. IRENNER, L. IRENNER, L. IRENNER, L. IRENNER, L.	8306280203 8306020351 8306030286 8306080151 8306080167	1&E 50-352 0 50-352 0 50-352 0	BURDDIN.J F BURDDIN.J F BURDDIN.J F BURGER,F J. BURKE,D J	9304070007# 9304070347# 9304280224# 9304170048 9304140427#	50-528	CARLIBLE: C 8 CARLIBLE: C 8 CARLIBLE: C 8 CARLIBLE: C 8 CARLBON: J D.	8306010368 8306020104* 8306070095 8306270353* 8306280174*	50-397 Q 50-397 Q 50-397 B 50-397 B 50-275 Q
IRENNER, L IRENNER, L IREY, H L IREY, H L IREY, H L	B306100195 B306270144 B306070103 B306160286 B306160341	50-352 0 50-382 0 50-267 P 50-267 0 50-247 P	BURNETT, PT, BURNETT, RF BURNETT, RF BURNETT, RF BURNS, JB	8306290519# 8306160178# 8306160190# 8306210354 8306080385	50-369 @ FOIA FOIA NUREQ ADVCM	CARLBON, R T CARPENTER, J H CARPENTER, J H CARPENTER, T CARPENTER, T	8304230147* 8304010437 8304220090 8304080218 8304080250	50-6 0 50-400 0 50-400 0 50-358 0 50-358 0
REY, H L HEY, H L, HICKLEY, R H HIDENBAUGH, D, HIGGS, J B,	8306210011 8306280354 8306130410* 8306220141* 830622011	50-267 G 50-247 P GA799 50-322 G NUREG	Burne, R Burne, B Q Burne, B Q Burrie, B E Burrie, C H	8306010237 8306240261 8306240422* 8306080294* 8306280541*	50-240 8 50-338 V 50-135 0 50-410 A 50-382 0	CARPENTER, T CARPENTER, T G CARR, A V CARR, A V CARR, A V	8306160046 8306160273* 8306100197 8306100197 8306220092	50-206 0 CONTRACT 50-413 0 50-413 0
IRIGHT, Q, Q, Q, IRIGHT, Q, Q Q, RIGHT, Q, Q Q, RIGHT, Q, Q Q RIGHT, Q, E RIGHT, D, J	8306010439 8306160616 8306220090 8306170011 8306080312*	50-400 0 50-142 0 50-400 0 50-317 5 50-410 A	BURBTEIN C H BURBTEIN B BURBTEIN B BURBTEIN B BURBTEIN B	8306280541 * 8305020208 8306130146 8306160460 8306210207	50-382	GARR, A V CARR, A V CARR, A V GARR, J C GARR, J C	8304270457 9304270461* 9306270464* 9306160223* 9306160276*	50-413 0 50-413 0 50-413 0 50-206 0 50-206 0
ROEHL, D. J. ROEHL, D. J. ROEHL, D. J. ROLIN, M. A.	8306070207 8306070211* 8306230414 8306280613 8306060008	50-344 P 50-344 P REGOD 50-344 P FOIA	BURSTEIN, 8 BURWELL, 8 BUSCHBACH, T. C. BUSH, S. H. BUSH, S. H	8306280397 8306220170 8305170121 8306200444 8306200444	50-266 P 50-445 A NUREG ACHS ACRS	CARR, J C CARROW, H CARRWEAN, A R GARTEAUX, P CARTEAUX, P	8306160301* 8306280125 8306140532* 8306060185* 8306060273*	50-204 0 50-400 0 50-329 A 50-315 8 50-314 8
IRONS, J C, RONS, J C IRONS, J C IRONS, J C	8306010346 8306020450 8306030345* 8306160385 8306200403	50-286 B 50-286 B 50-286 0 50-286 R 50-286 F	BUTCHERIR C. BUTCHERIR C BUTLERIB.D. BUTLERIB.D. BYRD.R	8306070043 8306170294 8306140162* 8306140390* 8306010244	50-259 8 50-240 8 50-327 0 50-327 0 50-414 8	CARTER, H L CARTER, R B CARTER, S. CARTER, S CARTER, S	8304070385* 8304020454 8304130143 8304300181 8304300224	50-312
IRONS, J, C, IRONS, J, C, IRONS, J, C, IROCKS, E, IROCKS, E, IROCKS, E	8305200411* 8305210058 8305240485 8305270212* 8305270511*	50-286 F 50-286 G WASTE MOT 50-250 Q 50-390 Q	BYRD, A. Byrd, R. Byrd, R. Byrd, R. Byrd, R.	8306070004 8306140046 8306140084 8306140384 8306140611	50-416 8 50-416 8 50-416 8 50-416 5 50-416 5	CARTHRIGHT, W B CARTHRIGHT, W, B CARTHRIGHT, W B CARTHRIGHT, W. B CARUSO, R	8306020467 8306200089 8306200118 8306200208	50-317 8 50-317 8 50-318 6 50-317 8 50-328 A
IROCHY, J. J. IROCHY, C. H. IROCHY, C. H. IROCHY, C. H. IROCHY, C. D. IROCHY, O. D.	6304080119	50-280 Q 50-72 F 50-263 Q FOIA 40-8722	BYRD, R. BYRD, R. BYRD, R. BYRNE, J. J BYRON, J. D	8306200142 8306280471 8306280555 8306280216# 8306080048#	50-416 B 50-416 B 50-416 B 50-320 P 50-440 A	CARUSO, R CARUSO, R CARUSO, R, CARUSO, R, CARUSO, A M	8306130418# 8306130477 8306140118 8306290673	50-922 Q 50-922 A 50-922 A 50-922 F 50-928 B
IROUNI, Q. D. IROUNI, Q. D. IROUNI, Q. D. IROUNI, Q. D.	8306090065 8306090129	40-8027 40-8681 70-2850 40-8698 40-8084	BYRON, J. D. Byron, P. H Cain, C. L. Gain, C. L Cain, C. L		50-329 A 50-34; G 40-8681 40-8698	CARVER, A M. CABANAVE, M. CABHATT, M. E CABHATT, M. E. CABHWELL, R J.	8306010020 8306080072# 8306140423# 8306140383#	50-327 B CONTRACT 50-324 G 50-416 G 50-156 G

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
CASTRO, G CASTRO, G CATTON, I CAUSEY, J C CAVANAGH, R	8306170259* 8306220305* 8306210422 8306270170 8306090234	CONTRACT CONTRACT ACRS 50-366 P 50-522 G	CHRISTEL, B CHRISTEL, B CHRISTENSEN, R CHRISTIANSON, W CHRISTMAN, J N	8306070246 8306130325 8306210375* 8306230359* 8306070405	50-237 8 50-249 8 CONTRACT 50-358 0 50-322 0	CLARK, R A CLARK, R A CLARK, R A CLARK, R I CLAYTON, F L	8306270247 8306270276 8306270302 8306060002 8306010331	50-335 P 50-339 P 50-339 P FOIA 50-348 P
CAZZOLI,E G CERNE.A C CERNE.A C CERNE.A C GERNE.A C	6306020072 6306060215* 6306060263* 6306080264* 6306080266*	NUREQ 50-322 Q 50-443 Q 50-443 Q 50-443 Q	CHR18TMAN, J N CHR18TMAN, J N CHR18TOFFER, G CHR18TOFFER, G CHR18TOFFER, G	8305150287 8305160287 8305160093* 8305100273* 8305210242	50-322 0 50-322 0 50-155 0 50-315 0 50-331 B	CLAYTON, F L CLAYTON, F L CLAYTON, F L CLAYTON, F L CLAYTON, F L	8304010424 8304030307 8304040115 8304040201 8304070324	50-364 P 50-348 P 50-364 P 50-364 P
CERNE.A C CHAFFEE.A CHAFFEE.A E CHAMBERS.G T CHAMBERS.G T	8306230405# 8306280561# 8306280511# 8306070084 8306100192	50~443 0 50~361 0 50~361 0 50~260 8 50~296 9	CHRIBTOPHER, R CHRISTOPHER, H CHUNG, J W. CHURCHILL, B W CHURCHILL, B W	B306060016# B306070266 B306200136# B306070419 B306070419	50-354 Q 50-276 S 50-367 Q 50-362 Q 50-362 Q	CLAYTON, F L CLAYTON, F L CLAYTON, F L CLAYTON, F L CLAYTON, F, L	8306070332* 8306100270 8306130429 8306140071 8306140593	50-348 Q 50-348 B 50-348 P 50-348 Q 50-348 P
CHAMBERS.0 T CHAN.S F CHAN.8 P CHANDLER.J C CHANDLER.J C	8304210134 8304020084 8304230024* 8304090045 8304090154	50-240 S NUREQ FDIA TOPREP TOPREP	CHUTE, M CIHI, J J CILLIB, M CILLIB, M CIPOLLA, A J	8306270256 8306240232* 8306070176* 8306280632* 8306080406	50-443	CLAYTON, F L CLAYTON, F L CLAYTON, F L CLAYTON, F L CLAYTON, F L	B306140610 B306140117 B306160278 B306160327 B306170357	50-348 P 50-344 R 50-348 P 50-348 R 50-348 Q
CHANDLER, L J CHANDLER, L J CHANDLER, L J CHANDLER, L J CHANEY, H D	8304150230 8304210288 8304240275 8304300044 8304080074*	50-275 0 50-361 0 50-275 0 50-275 0 50-382 0	CLAPP, N E CLARDY, L CLARK, A T. CLARK, A T. CLARK, C W.	8306280093 8306130327 8306150216 8306220165 8306020364	NUREG 50-331 5 50-201 P PROJ TOPREP	CLAYTON, F L CLAYTON, F L CLAYTON, F L CLAYTON, F L CLAYTON, F L	8305200215 8305200336 8305210193 8305230378 8305240040	50-348 8 50-348 P 50-348 P 50-348 P
CHANEY, H, D CHANEY, H D CHANEY, H D CHANG, D K CHARNLEY, J E	8306080133* 8306080238* 830609033 4* 8306230351* 8306100136*	50-498	CLARK, D CLARK, D CLARK, D CLARK, D CLARK, L	8304230201 8304240354 8304140255* 8304230238 8304200345*	50~259 F 50~259 P 50~97 G 50~97 F 50~358 Q	CLAYTON, F.L. CLAYTON, F.L. CLAYTON, T. N. CLEMENTS, B. R. CLEMENTS, B. R.	8305270227 8305270207# 8305280076 8305010277 8305070312	50-348 8 50-348 G NUREQ 50-445 F 50-445 V
CHARNLEY, J E CHARNOFF, O CHARNOFF, O CHARNOFF, O CHARTERINA, J	8306140547* 8212020236* 8306170476 8306200048* 8306020353	50-324 0 ADVCM ADVCM ADVCM 50-219 8	CLARK, L CLARK, L CLARK, P R CLARK, R A CLARK, R A	8304200359* 8304270551* 8304070271* 8304010003 8304010036	50-358 9 50-329 0 50-289 F 50-285 P 50-317 P	CLEMONB, P. CLEMONB, P. CLEMONB, P. CLEMONB, P. CLEVELAND, J C	6304020244* 8304040247* 8304070034* 8304230118* 8304280073	71-250 50-284 G 71-2 70-820 NUREO
CHAUDHARY, B K CHAUDHARY, B K CHAVEZ, D CHAVEZ, D CHAVEZ, D	8304070151* 8304150247* 8304080143 8304080143	50~352	CLARK, R. A. CLARK, R. A. CLARK, R. A. CLARK, R. A. CLARK, R. A.	8304010477 8304020015 8304020505 8304030012 8304030067	50-317 F 50-309 P 50-309 P 50-336 P 50-338 P	CLINE, W E. CLOSIUS, C. J CLOSIUS, C. J	8306140244* 830627046* 8306270361 8306160053 8306170051	50-416 Q 50-261 Q 50-213 S 50-213 F 50-213 B
CHAVEZ, D CHAVEZ, D CHAVEZ, D CHEN, C CHENG, T M	8306150436* 8306150442* 8306150442* 8306200316* 8306170478	50-454 0 50-454 0 50-454 0 50-244 P 50-409 P	CLARK,R,A GLARK,R,A CLARK,R,A GLARK,R,A GLARK,R,A	8306030073 8306030089 8306030231 8306030241 8306060092	50-313 F 50-309 F 50-309 P 50-344 P 50-336 P	Clobius, & J. Clobius, & J. Cochran, T. B Gochran, T. B Coen, R	8304170301 8304170347 8304220157* 8304270370 8304030218	50-213 B 50-213 B 50-337 Q 50-289 H 50-237 B
CHILK:8 J. CHILK:B J. CHILDB:V CHILDB:V	8306070251 8306280088 8306010312 8306020343 8306020441	50-400 5 50-400 8 50-333 8 40-2061 50-287 9	CLARK.R A GLARK.R A GLARK.R A GLARK.R A GLARK.R A	830&060357 830&060371 830&060377 830&080074 830&080249	50~344 P 50~317 0 50~344 P 50~335 P 50~285 P	COFFEY, J A COFFEY, J A COFFMAN, F E COFFMAN, F E COFFMAN, F E.	8304070039 8304140482 8304020228 8304020273* 8304240277	50-296 B 50-259 R WASTE MOT WASTE MOT WASTE MOT
CHILK.B J CHILK.B J CHILK.B J CHILK.B J	8305030045 8305030157 8305030259 8305030386* 8305030499	FDIA 50-272 8 50-370 A FDIA 10CFR	CLARK.R A CLARK.R A CLARK.R A CLARK.R A CLARK.R A	8304080251 8304080332 8304080431 8304090377 8304090424	50~335 P 50~344 P 50~336 P 50~309 P 50~317 P	COFFMAN, F.E. COHALAN, P.F. COHEN, I COHEN, I COHEN, I	8306270620 8306070258 8306010100* 8306010304* 8306020387*	50-201 P 50-322 P 50-29 G 50-271 G 50-244 G
CHILK, B J CHILK, B J CHILK, B J CHILK, B J	830A030501 830A0A0274 830A0A0287 830A0A0389 830A070350	10CFR 70-25 50-70 g 10CFR 50-445 g	CLARK, R A CLARK, R A CLARK, R A. GLARK, R. A CLARK, R A	8306130491 8306140352 8306140414 8306160159 8306160255	50-336 P 50-336 P 50-335 P 50-285 P 50-244 P	COMINGS,D M COLARULII,P F COLARULII,P F COLARULII,P F	8306010478 8306070414 8306070414 8306150429 8306150429	RES 50-247 9 50-247 9 50-247 9 50-247 9
CHILK, B J. CHILK, B J CHILK, B J. CHILK, B J CHILK, B J	8304070390 8304080137 8304080270* 8304080331 8304080439	50-289 9 50-361 9 FDIA 50-320 G 50-322 T	CLARK,R A CLARK,R A. CLARK,R A CLARK,R A	8306140283 8306160288 8306160645 8306170013 8306170019#	50-245 P 50-335 P 50-344 P 50-301 G 50-301 G	COLARULLI, P. F COLARULLI, P. F COLARULLI, P. F COLARULLI, P. F COLARULLI, P. F	8306200342 8306200342 8306230376 8306230376 8306270160	50-247 T 50-247 T 50-247 0 50-247 0 50-247 0
CHILK, B J. CHILK, B J CHILK, B J CHILK, B J	8306080442* 8306070278 8306070301 8306130427 8306130516	50-322 T 50-266 Q 50-352 G 50-478 G 10CFR	CLARK, R. A CLARK, R. A CLARK, R. A CLARK, R. A CLARK, R. A	8306170053 8306170469 8306200055 8306200059 8306200065	50~282 P 50~307 G 50~368 P 50~313 P 50~285 P	COLER F. COLE, R. F. COLE, R. F. COLEMAN, L. B. COLEMAN, R	8306270160 8306200274 8306230362 8306020047* 8306220073	50-454 0 50-454 0 50-320 H CONTRACT
CHICK'B 7 CHICK'B 7 CHICK'B 7 CHICK'B 7	8306150206 8306150278 8306160211* 8306160632 8306160635	50-247 F 50-309 G FOIA 50-358 G 50-361 G	Clark, R.A. Clark, R.A. Clark, R.A. Clark, R.A. Clark, R.A.	· 8306200278 8306200281 8306210311 8306220223 8306240347	50~334 P 50~282 P 50~335 P 50~309 P 50~285 P	COLEMAN, R. COLEMAN, R. COLLING, D. J. COLLING, D. J COLLING, J. T	8306270441 8306280115 8306020460# 8306230388# 8306010293	50-247 F
CHILK, B J. CHILK, B J CHILK, B J CHILK, B J. CHILK, B, J	8306200026 8306200030 8306230367 8306270265 8306270273	50-387 F 50-247 F 50-289 G 50-289 G 50-289 G	Clark, R. A. Clark, R. A. Clark, R. A Clark, R. A Clark, R. A	8306240469 8306280075* 8306290081 8306290086 8306290146	50-313 F 50-285 P 50-285 P 50-339 Q 50-266 P	COLLING, J. T COLLING, J. T. COLLING, B. COLLING, B. COLLING, S.	8304270208 8304280242 8304140490 8304230212* 8304230334	50-311 8
CHILK, B. J. CHILK, B. J. CHIN, R. Y CHOKBHI, N CHOULES, N. C.	8306270320 8306300143 8306130351 8306100036* 8306130273*	50-287 0 50-352 0 50-275 8 50-312 0 50-315 0	CLARK, R. A. CLARK, R. A. CLARK, R. A. GLARK, R. A. CLARK, R. A.	83062901 \$2 83062901 \$8 83062901 90 83062901 94 8306290202*	50-336 P 50-265 P 50-309 P 50-317 P 50-317 P	COLLING. G. J. COLLING. T. R COLOMBO. R. COLOMBO. R. W. COLOMBO. R. W.	93061 60006+ 8306270244+ 830621 0076 8306070067 83061 70290	

AUTHOR	ACCESSION NUMBER	BUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT
COLOMBO, R W. COLOMBO, R W. COLOMBO, R W. COLOMB, R W. COLOM, F. P. COLBHANN, P.	8304170358 8304230394 8304230410 8304010078* 8304300180	50-312	COPELAND, V C COPELAND, V C COPELAND, V C COPELAND, V C COPELAND, V C	8306270016 8306270016 8306270016 8306270020* 8306270020*	50-454 G 50-454 G 50-454 G 50-454 D 50-454 D	COUNSIL. H G	6306260321 6306260346 6306260346 8306260412 6306260412	50-245 P 50-423 S 50-423 S 50-245 P 50-245 P
COMES, F COMECLA, P A COMEC, E COMPTON, R M CONKLIN, J C	8306060041* 8306240051* 8306160149 8306060224* 8306280093	FOIA FOIA FOIA 50-445 9 NUREG	COPELAND, V G.	9306270041 9306270173 9306270173 8306270383 8306270383	50-454	COUNSIL, H C COUNSIL, H C COUNSIL, H C COUNSIL, H C	8306280414 8306280414 8306280478 8306280478 8306280482	50-336 0 50-336 0 50-245 P 50-245 P 50-423 8
CONLON CONLON, T. & CONLON, T. & CONLON, T. E CONLON, T. E	8306140671* 8306140180* 8306140375* 8306140474* 8306140520*	50~413	COPELAND, V Q. COPELAND, V Q CORBEGIA, D M CORE, M R. CORMIER, W H	830 <i>5</i> 280528 830 <i>5</i> 280528 830 <i>5</i> 240361 830 <i>5</i> 050299 830 <i>5</i> 070399	50-454 0 50-454 0 71-9135 50-285 8 50-142 0	COUNSIL, H G COUNSIL, H G COUNSIL, H G COUNSIL, H G	8304280482 8304280534 8304280534 8304300140 8304300140	50-423 B 50-245 P 50-245 P 50-245 P 50-245 P
CONLON, T. E CONLON, T. E CONLON, T. E CONLON, T. E CONLON, T. E.	8306140692* 8306160254* 8306290221* 8306290328* 9306290371*	50-257 0 50-440 0 50-335 0 50-390 0 50-416 0	CORMIER, W H CORMIER, W H CORRADINI, M CORRADINI, M CORT, G E.	830 6070 41 6 830 6280 525 830 6210 378 830 6210 378 830 6130 377*	50-142 0 50-142 0 ACRS ACRS 50-142 T	COUTURE, C. COMAN, K COMAN, R COMOTIL	9304170299* 9304140534* 8304210153* 8304140022 8304040220*	50-389 P 50-329 A TOPREP 50-219 S 50-219 G
ONLON, T. E ONN, W.G. ONNAUGHTON, K. ONNER ONNER, E. L.	8306300132* 8306100122 8306170364* 8306140022 8306130247*	50-440 G 50-397 B 50-454 G 50-217 B 50-352 G	CORT. C E. CORNIN. B. CORYELL. C P CORYELL. C P COSTELLO, J R	830 6130377# 830 6070299 830 6140529# 830 6140617# 830 6130224#	50-142 T 50-247 F 70-1201 70-824 0A999	COX. H T COX. H T COX. H T	B306070161 B306070182 B306200002 B306200109 B30620018B	50-261 8 50-261 8 50-261 5 50-261 5 50-261 8
'ONNER, T. B. ONNER, T. B. 'ONNER, T. B. ONNER, T. B. 'ONNER, T. B.	8306060322 8306060322 8306070373 8306070373 8306100206	50-352	COSTER, W F. COTTER, B P. COTTER, B P. COTTER, B P. COTTER, W D	8306130398 8306060325 8306080185 8306220070 8306060231	50-322 6 50-409 0 70-25 50-410 6 PR	CDX.N D CDYLE.L H GRAFT, C H GRAOIN, J G GRAOIN, J G	8304020011 8304040040 8304270151 8304170313 8304170328	NUREO 50-237 8 NUREO 50-275 P 50-275 P
ONNER, T.B. ONNER, T.B. ONNER, T.B. ONNER, T.B. ONSTABLE, Q.L.	B306100206 B306270294 B306270294 B306280550 B306130129*	50-458	COTTER.W D. COTTINGHAM.A COTTON.G D. COUNSIL.W G COUNSIL.W G	8306060233 8306060313 8306150002 8306010340 8306010340	PR PRM 50-361 K 50-213 P 50-213 P	CRANE.P A CRANE.P A CRANE.P.A CRANE.P A CRANE.P A	8304010347 8304280522 8304300041 8304300089* 8304300073*	50-275 R 50-275 G 50-275 G 50-275 G 50-275 G
DNTE,R ONWAY,J T. OOK,D OGK,D H OOK,J	830615000B# 8306090359 8306300043 8306280080 8306100017	50-289 0 50-247 6 50-254 8 50-259 P 50-333 R	COUNSIL, W G.	8306010340 8306020449 8306060090 8306060090 8306060090	50-213 P PR 50-213 H 50-213 H 50-213 H	CRAMSTON.A CRAMFORD,V A CRAMFORD,V A CREED,J CREED,J	8211160965# 8306150304 8306150304 8306210242 8306230438	50-206 U 50-529 0 50-529 0 50-331 8 50-295 8
00K, J. W 00K, J. W 00K, J. W 00K, J. W 00K, J. W	8306030172 8306060055* 8306070242 8306100268 8306130281	50-329 R 50-329 0 50-329 B 50-329 A 50-329 B	COUNBIL, W G. COUNSIL, W G. COUNSIL, W G. COUNSIL, W G. COUNSIL, W G.	8306060078 8306060078 8306060143 8306060143 8306060184	50-336 P 50-336 P 50-423 A 50-423 A 50-336 F	CREED, J R CREED, J R CREED, J R CREED, J R CRLENJAK, R. V	8304100093# 8304100273# 8304130319# 8304210075# 8304270293#	50-155 0 50-315 0 50-346 0 50-263 0 50-321 0
DOK; J. W. DOK; J. W DOK; J. W DOK; J. W DOK; L.	8306140524 8306150346* 8306210302 8306300105* 8306270343	50-329 A 50-329 F 50-329 B 50-329 A 70-25	COUNSIL, W G.	8306060154 8306060207 8306060207 8306060207 8306060243	50-236 F 50-213 P 50-213 P 50-213 P 50-213 P	CROCKER, H H CROCKER, H H CROCKER, H H CROCKER, H H CROCKER, H H	8306010100# 8306010304# 8306010306# 8306020389# 8306280210#	50-29 0 50-271 0 50-213 0 50-244 0 50-213 0
DOL: D A DONEY; M J DONEY; M, J, DONEY; M, J, DONEY; M, J	8306279611 8306010438 8306010445* 8306020277 8306020376	40-6940 50-278 S 50-278 S 50-277 S 50-277 S	COUNSIL.W G COUNSIL.W G COUNSIL.W G COUNSIL.W G COUNSIL.W G	830 4040243 830 4040243 830 4070134 830 4070136 830 4080058	50-245 R 50-245 R 50-245 F 50-245 F 50-245 P	CROFT, T L CROFT, T L CRONIN, F, J CROBBHAN, W A CROBSMAN, W A	9306230166# 9306230166# 9306240078 9306010356# 9306060060#	FOIA FOIA NUREO 50-498 Q 50-498 G
DONEY, M. J. DONEY, M. J. DONEY, M. J. DONEY, M. J. DONEY, M. J.	8306160379 8306170017 8306170278 8306200144 8306210076	50-277 R 50-277 S 50-277 B 50-277 S 50-277 R	COUNSIL.H. G. COUNSIL.H. G. COUNSIL.H. G. COUNSIL.H. G. COUNSIL.H. G. COUNSIL.H. G.	B304080058 B304090232 B304090232 B304100114 B304140341*	50-245 P 50-245 P 50-245 P 50-213 P 50-336 P	CROSSHAN, W A CROSSHAN, W A CROSSHAN, W A CROSSHAN, W A CROSSHAN, W A	8304040073* 8304040122* 8304040133* 8304080074* 8304080079*	50-458 0 50-458 0 50-112 0 50-302 0 50-382 0
DOPER, D. H DOPER, J. H DOPER, W. E. DOPER, W. E. DOPER, W. E.	8306280190 8306230450 8306010317 8306100130 8306170270	NUREG PR 50-275 R 50-275 R 50-275 R	COUNSIL, H. G. COUNSIL, H. G COUNSIL, H. G COUNSIL, H. G COUNSIL, H. G	8306140361# 8306150338# 8306160412 8306160412 8306170231	50-336 P 50-213 F 50-213 P 50-213 P 50-213 P	CROBBHAN, H A	8306080133* 8306130129* 8306140636* 8306210070* 8306070166*	50-478 0 50-382 0 50-382 0 50-382 0 50-346 0
COPER, W.E. COPER, W.E. COPER, W.E. COPER, W.E. COPER, W.E. COPER, W.E.	8306170293 8306170312 8306170313 8306170328 8306200249	50-275 R 50-276 R 50-275 P 50-275 P 50-275 R	COUNSIL, W 0 COUNSIL, W 0 COUNSIL, W 0 COUNSIL, W 0 COUNSIL, W 0	8306170391 8306170391 8306170391 8306200104 8306200104	50-213 0 50-213 0 50-213 0 50-336 8 50-336 8	CROUBE, R P CROUBE, R P CROUBE, R P CROUBE, R P CROUBE, R P	8306070397 8306140448 8306140500 8306170027 8306170075	50-344 0 50-346 0 50-346 P 50-346 P 50-346 F
KOPER: W. E. KOPER: W E. KOPER: W E KOPER: W E KOPELAND: J. E. KOPELAND: R A	8306270416 8306280469 8306280483 8306220100 8306280240	50-275 R 50-275 R 50-275 R 50-443 9 TOPREP	COUNSIL, W. G COUNSIL, W. G. COUNSIL, W. G. COUNSIL, W. G. COUNSIL, W. G.	830A200313* 830A200313* 830A200322* 830A200322*	50-245 0 50-245 0 50-245 0 50-245 0 50-213 0	CROUBE, R P CROUBE, R P CROUBE, R P CROUBE, R P CROUBE, R P	8306200393 8306210026 8306210170* 8306220257* 8306230259	50-346 P 50-346 P 50-346 Q 50-346 F 50-346 P
PELAND, V. 9 PELAND, V. 9. PELAND, V. 9. PELAND, V. 9. PELAND, V. 9.	8306010457 8306010457 8306020339 8306020339 8306060193	50-454 0 50-454 0 50-155 0 50-155 0 50-454 0	COUNBIL, H Q. COUNBIL, H Q. COUNBIL, H Q. COUNBIL, H Q.	8306230100* 8306230287 8306230426 8306240200 8306240200	50-213 F 50-245 P 50-213 F 50-213 P 50-213 P	CROUSE, R. P CROUSE, R. P CROW, W. T CROW, W. T. CROW, W. T.	8306270204 8306270379 8306060416 8306080396*	50-346 9 50-346 9 40-8035 70-2910 70-2838
PELAND, V. 9.	8304040173 8304040174* 8304200304 8304200304 8304200350	50-454 0 50-454 0 50-454 0 50-454 0 50-454 0	COUNSIL, H, O. COUNSIL, H O COUNSIL, H O COUNSIL, H O COUNSIL, H O	8306240200 8306270228 8306270255 8306270255 8306280321	50-213 P 50-213 B 50-336 P 50-336 P 50-245 P	CROW, W T CROW, W T CROW, W T CROW, W T CROW, W T	8306140446# 8306150335# 8306210434 8306210440# 8306210443	40~8794 70~1257 40~6264 70~143 50~329 0

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	FOSLEUZ CATEGORY	AUTHOR	ACCESSION NUMBER	EUBJECT CATEOURY
CROW, W T CROWLEY, B R CROWLEY, B R CRUTCHFIELD, D CRUTCHFIELD, D	8306290687* 8306140522* 8306290192* 8306010308 8306060044	70-2375 50-321 0 50-413 0 50-237 P 50-255 P	DALE, L F DALE, L F DALE, L F DALE, L F DALE, L F	8304010074 8304040056* 8304040079 8304040724	50-416 P 50-416 A 50-416 F 50-416 P 50-416 P	DAVIS, J G DAVIS, J G DAVIS, J G DAVIS, J G DAVIS, L K	8306160175* 8306160182* 8306280132 8306290547* 8306230053*	FOIA FOIA PROJ REVIEW OR FOIA
CAUTCHFIELD, D	8306040047*	50-255 P	DALE, L F	8306160271	50-416 P	DAVIS.M	8306200351*	50-358
CRUTCHFIELD, D	8306040276	50-244 P	DALE, L F	8306200204	50-416 P	DAVIS.M J.	8306140627*	50-280
CRUTCHFIELD, D	8306080178	50-245 P	DALE, L F	8306200412	50-416 R	DAVIS.P R.	8306200445	ACR8
CRUTCHFIELD, D	8306070267	50-245 P	DALE, L F	8306210140	50-416 F	DAVIS.P R	8306200445	ACR8
CRUTCHFIELD, D	8306070320	50-217 G	DALE, L F	8306230167	50-416 P	DAVIS.R E	8306020066	NUREQ
CRUTCHFIELD, D	8306100128	50-237 P	DALE,L F	8304270077	50-416 P	DAVIS.8	8306060085*	50-249
CRUTCHFIELD, D	8306100129	50-155 P	DALE,L F	8304270114	50-416 Q	DAVIS.8 M	8306020423	50-317
CRUTCHFIELD, D	8306140408	50-237 P	DALE,L F	8304270285	50-416 P	DAVIS.8 M.	8306020430	50-318
CRUTCHFIELD, D	8306140642	50-219 P	DALE,L F	8304280505	50-416 P	DAVIS.S M.	8306020433	50-317
CRUTCHFIELD, D	8306150013	50-244 0	DALRYMPLE,J T	8304090470*	CONTRACT	DAVIS.S M	8306200089	50-317
CRUTCHFIELD, D	8304150088	50-255 F	DALTROFF, B L DALTROFF, B L DALTROFF, B L DALTROFF, S L DALTROFF, S L	8306020299	50-277 P	DAVIS,W E	8305230030*	40-8681
CRUTCHFIELD, D	8304150218	50-155 Q		8306020378	50-277 P	DAWSON,D M	8306030426	70-1308
CRUTCHFIELD, D	8304150253	50-29 J		8306070363	50-277 P	DE LORENZO,R A	8306010105	50-513 1
CRUTCHFIELD, D	8304140549	50-155 P		8306070219	50-277 P	DE LORENZO,R A	8306070113	50-460 1
CRUTCHFIELD, D	8304140625	50-155 P		8306140391*	50-277 F	DEAGAZIO,A	8306030503	50-346 1
CRUTCHFIELD, D	8304200192	50-155 P	DALTROFF, B L	8306160340	50-352 A	DEAN, J.P. DEAN, R. S. DEANDORFF, D. DEBBAGE, A. G. DEBBEUX, R. B.	8306020415*	70-1224
CRUTCHFIELD, D	8304200197*	50-155 P	DALTROFF, B L	8306160486*	50-277 G		8306240050	NUREO
CRUTCHFIELD, D	8304200235	50-244 P	DALTROFF, B L	8306200165*	50-277 G		8306130453	50-358 (
CRUTCHFIELD, D	8304210138	50-219 P	DANG, J T	8306200273	FOIA		8306140471*	50-395 (
CRUTCHFIELD, D	8304210292	50-409 F	DANGE, H C	8306070050	50-250 G		8306070070	50-392 /
CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D CRUTCHFIELD, D	8306210424 8306220074 8306240254 8306280155 8306280176	50-111 P 50-219 P 50-219 P 50-219 P 50-219 P	DANCE, H C DANCE, H C DANCE, H C. DANCE, H C. DANCE, H C	8306070191 8306140127 8306140135 8306140174 8306140186	50-389 8 50-250 V 50-395 V 50-389 Q 50-389 Q	DEBS.B T DEBS.B T DEBS.B T DECKER.T R. DEEDS.P E	8306140477* 8306290228* 8306290297* 8306290426* 8305240443*	50-348 (50-259 (50-259 (50-261 (50-293 F
CRUTCHFIELD, D	8306280197	50-409 P	DANCE, H C	8306140190	50-335 Q	DEIGL.H.G	8306010389	50-128 F
CRUTCHFIELD, D	8306280442	50-195 P	DANCE, H C	8306140302	50-335 Q	DEIGL.H.G.	8306030045	71-5957
CRUTCHFIELD, D	8306280564	50-237 P	DANCE, H C	8306140343	50-335 Q	DELGAWRENGE.G.L	8306270004*	50-213 G
CRUTCHFIELD, D	8306290068	50-141 W	DANCE, H C	8306140346	50-347 V	DELLA RATTA.A	8306010339*	70-687
CRUTCHFIELD, D	8306290241	50-29 P	DANCE, H C	8306140347	50-302 V	DELLA RATTA.A	8306030324*	70-371
CRUTCHFIELD, D	8306290311	50-29 P	DANCE, H C	8306140353	50-302 V	DELLAVECCHIA, H. DELDATCH, V. DELGATCH, V. DELGATCH, V. DELGST, J.	8304130378	50-322 G
CRUTCHFIELD, D	8306290406	50-245 P	DANCE, H C	8306140397	50-280 G		8304010022	CONTRACT
CRUTCHFIELD, D	8306290538	50-217 P	DANCE, H C	8306140432	50-424 G		8304150540	CONTRACT
CRUTCHFIELD, D	8306300027	50-155 P	DANCE, H C	8306140447	50-302 G		8304270385	CONTRACT
CRY, K D	8306240266	50-341 0	DANCE, H C	8306140445	50-302 G		8304230058*	FOIA
COMMINGS' 7 Y CONTEN' M H COTTEN' M H COTTEN' M H	8304150081 8304170243 8304240042 8304080308# 8304080310#	NUREQ NUREQ NUREQ 50-478 Q 50-478 Q	DANGE, H C DANGE, H G DANGE, H G DANGE, H G DANGE, H G	8306140486 8306140497 8306140504 8306140506# 8306140515	50-321 V 50-413 G 50-389 G 50-413 G 50-321 G	DELOST, T. DENISON, E. DENNIS, A. W DENNIS, C. DENNIS, N.	8304230040# 830417030B 83040200B0 8304040309# 8304110279	FOIA 50-275 R NURE9 70-25 1&E
CONNINGHAM'S H CONNINGHAM'S H CONNINGHAM'S H COMMINGHAM'S H	8304230043# 8304140343# 8304150174 8306240281# 8306240157	50-373	DANCE, H C DANCE, H C DANCE, H C DANCE, H C DANCE, H C	8306140530 8306140538 8306140608 8306140621 8306140641	50~3A9 0 50~335 0 50~338 0 50~280 0 50~338 0	DENNIS, N DENNY, I DENTE, T DENTE, T DENTON, H R.	8304110287 8304080377 8304210144 8304230324 8210270150*	ile 40–2061 Toprep Toprep Hisc
CUDMO, M M CURNANE, R A CURNANE, R A CURRAN, D CURRAN, D	8304030174# 8304240243# 8304240245# 8304010382 8304010382	50-322 U GA779 GA779 50-443 Q 50-443 C	DANCE, H C DANCE, H C DANCE, H C DANCE, H C DANCE, H C	8306140664 8306170151 8306170285 8306200203 8306270186	50~413	DENTON, H. R.	8304010071 8304020043 8304030213 8304080087 8304090371	PR 50-320 H MIBC MIBC MIBC
Curran, D	8304010437	50-449 0	DANGE, H C	8304270204	50-250 G	DENTON, HR. DENTON, HR DENTON, HR DENTON, HR DENTON, HR.	8306070438	M18C
Curran, D	8304010444	50-449 0	DANGE, H C	8304270207	50-335 G		8306070474	M18C
Curran, D	8304030335	50-449 0	DANGE, H, C	8304270217	50-389 G		8306130455	50-272 &
Curran, D	8304030355	50-449 0	DANGE, H C	8304270227	50-537 G		8306140274	M18C
Curran, D	8304030359*	50-449 0	DANGE, H C	8304270300	50-413 G		8306140712	PR
CURRAN, D	8304030357*	50-443 0	DANCE, H C	8304270327	50-335 G	DENTON, H. R.	8306210463	NUREO
CURRAN, D	6304140337	PR	DANCE, H C	8304270347 *	50-250 G		8306220215	50-344 P
CURRAN, D	8304270354	50-443 0	DANCE, H C	8304270357 *	50-335 G		8306220303 *	TOPREP
CURRAN, D	8304270554	50-443 0	DANCE, H C	8304270377	50-302 G		8306240405	50-155 O
CURRIE, J H	8304240078	Nureo	DANCE, H C	8304270374	50-413 G		8306240410 *	50-155 O
CURRY, J, J	8305310226	50-245 P	DANCE, H C	8306270421	50-387 G	DENTON, H R. DENTON, H R DENTON, H R DENTON, H, R DENTON, H, R	8306240415*	50-155 Q
CURTIB, N W	8306010330	80-387 P	DANCE, H C	8306270517	50-369 G		8306240419*	50-155 Q
CURTIB, N W.	8306020429	50-387 P	DANESE, F L	8306020177	50-266 F		8306240421*	50-155 Q
CURTIB, N W.	8306070021#	50-387 F	DANESE, F, L	830602018	50-266 P		8306240452	50-272 B
CURTIB, N W	8306140648	50-387 E	DANIELBON, D H	8306030185*	50-483 G		8306280047	PR
CURTIE: N W.	8306170250	50-388 8	DANIELBON, D H	8306030213#	50-374 G	DENTON, H, R DENTON, H R DENTON, H, R. DENTON, H, R. DERKE, P. B.	8306280125	MISC
CURTIE: N W	8306210079	50-388 8	DANIELBON, D H	8306060138#	50-358 G		8306270128	50-556 A
CURTIE: N W	8306230297	50-387 P	DANIELBON, D, H	8306230271#	50-440 O		8306270144	50-440 H
CURTIE: N. W	8306230430	50-387 E	DANIELBON, D, H	8306230440#	50-155 G		8306270564	REVIEW ORP
CURTIE: N W	8306230466	50-387 E	DANIELBON, D H	8306300029#	50-346 G		8306020307	50-133 R
CALCHIV'N M CALLEN M' CALLEN M' M CALLEN M' M' CALLEN M' CALL	8306280368 8306300092 8306300185 8306010433 8306140706	50-387 P 50-387 F 50-387 P 50-440 G 50-440 G	DANIELSON, D. H DANIELSON, D. H DAVIB DAVIB, A. B. DAVIB, B. W.	9306300218* 9306300246* 9306210237 9306230019* 9306150619	50-358 0 50-237 0 1&E 50-373 0 Nureq	derks, p. 8. Deslandes, K. D. Deslandes, K. D Desrosters, A. Desrosters, A. E	8306160461 8306170042 8306170042 8306010071 8306010037	50-133 R 50-336 8 50-336 8 NUREQ NUREQ
CUTCHIN, J M	8306170399		DAVIB.D.A.	8306060410	NUREC	Degrobiers, A. E	830&0100&7	Nures
CUTCHIN, J M	8306290372		DAVIB.F.C	8306170157*	FOIA	Degrobiers, A. E.	830&020053	Nures
CZAJIKOWSKI, C	8306240413		DAVIB.F.C	8306170160*	FOIA	Degrobiers, A. E.	830&14031 \$	Nures
D'AMCRE, M	8306060118#		DAVIB.H H	8306230042*	FOIA	Devincentib, J.	830&010447*	50-443 g
D'ARCY, P F	8306150179*		DAVIS.J G	8306140718*	PR	Devincentib, J.	830&010447*	50-443 g

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	BUBJECT
DEVINCENTIS: J DEVINCENTIS: J DEVINCENTIS: J DEVINCENTIS: J	8304030177 8304030177 8304080125 8304080125 8304170149	50-443 E 50-443 E 50-443 E 50-443 E 50-443 E	DIETZ, C R DIETZ, C R DIETZ, C R DIETZ, C R DIETZ, C R	8306270199 8306270245 8306270277 8306270291 8306360012	50-324 S 50-324 S 50-324 S 50-324 S 50-325 S 50-324 S	DIXON, O W DIXON, O W DIXON, O W DIXON, O W	8304140388* 8306140457* 8304140670 8304140570 8304210021	50-395 0 50-395 0 50-395 8 50-395 R 50-395 8
DEVINCENTIS: J DEVINCENTIS: J DEVINCENTIS: J DEVINCENTIS: J	9306170169 9306200236 9306200236 9306200330 9306200330	50-443 B 50-443 E 50-443 E 50-443 E 50-443 E	DIETI.C.R DIETI.C.R DIETI.C.R DIETI.C.R DIGGS.R M	8304300031 8304300143 8304300203 8304300242 830430054	50-324 S 50-324 S 50-325 B 50-324 S 50-250 P	DIXON,O W DIXON,O W DIXON,O W DIXON,O W	8304210209 8304230084 8304270136 8304270289 8304270354	50-395
DEVINCENTIS, J DEVINCENTIS, J DEVINCENTIS, J DEVINCENTIS, J	8306200397 8306200397 8306230452 8306230452 8306230452	50-443 E 50-443 E 50-443 A 50-443 A 50-443 B	Diggs.r m Diggs.r m Diggs.r m Diggs.r m Diggs.r m	8306030285 8306070328 8306070344 8306200157 8306210315	50-369 P 50-369 F 50-267 P 50-219 P 50-298 P	DIXON.O W DIXON.O W DIXON.O W DIXON.O W DIXON.O W	8304280047 8304280504 8304270088 8304300018 8304300047	50-375 8 50-375 8 50-375 0 50-375 5 50-375 8
DEVINCENTIE: J DEVINE: B DEVINE: J B DEVINE: J B DEVINE: J B	8306280545 8306200284* 8306020615 8306020645 8306030011	50~443 B FOIA XPORTLIC XPORTLIC XPORTLIC	Digos.R M Digos.R M Digos.R M Digos.R M Digos.R M	8306230498 8304230512 8306230514 8306240038 8306280077	50-341 P 50-155 G 50-313 P 50-269 F 50-373 P	DIXON.O W DIXON.O W DIXON.O W DJEMAL.A DODDS,R T	8304300122 8304300154 8304300174 8304020318 8304070017*	50-395 S 50-395 S 50-395 S 50-247 J 50-344 0
DEVINE, R E DEVINE, T, DEWEY, L B DEWEY, L B	8304200287* 8304060075 8304090311 8304140429 8304150398	FOIA 50-358 0 50-529 0 50-528 0 50-529 0	DIGNAN, T G DIGNAN, T G DIGNAN, T G DIGNAN, T G DIGNAN, T G	8304040305 8304040332 8304040332 8304040332 8304070290	50-309 0 50-309 0 50-309 0 50-309 0 50-309 0	DODDS.R T DODDS.R T DODDS.R.T DODDS.R T DODDS.R T	8304070083* 8304210245* 8304280215* 8304280341* 8304280380*	50-344
DEWEY, L B DEWEY, L B DEWEY, L B. DEWITT, R. B DEYOUNG, R C.	8306210264 8306210268 8306240284 8306270473 8306070345	50-527 0 50-529 0 50-529 0 50-329 A 50-440 0	Dignan, T. G Dignan, T. G Dignan, T. G Dignan, T. G Dignan, T. G	8304070290 8304070294 8304070294 8304150387 8304150387	50-309 G 50-309 G 50-309 G 50-443 G 50-443 G	DODDS, R T DODDS, R. T DODSON, J P DOERFLEIN, L T DOERFLEIN, L T	8306280409* 8306280521* 8306240293* 8306040827* 8306060237*	50-508 0 50-397 0 GA999 50-220 0 50-333 0
EYOUNG, R. C. EYOUNG, R. C. EYOUNG, R. C. EYOUNG, R. C IBBLE, C. B	8306240044 8306240049* 8306300102 8306300108* 8306160183	50-272 0 50-272 0 50-324 G 50-324 0 FOIA	Dignam, T. G Dignam, T. G Dignam, T. G Dignam, T. G Dimaria, D	8304150388 8304150388 8304280543 8304280543 8304080194	50-443	DOIRON, D O DOLLANSKY, K W DOLLANSKY, K W DONOVAN, R W DOOLITTLE, E L,	8304010083* 8304010083* 8304010087* 8304010241 8304020049	CONTRACT 50-528 B 50-528 B 50-377 F 50-423 A
ICHARRY, R F ICK, O. F. ICK, O. F. ICKERSON, M. W. IECKAMP, H.	8306030057* 8306060174 8306060255 8306060126* 8306010351	71-9056 50-244 F 50-244 P 50-267 Q 50-289 Q	DIMEQLIO, A F DINITZ, I DIRCKS, W J DIRCKS, W J DIRCKS, W J	8306080329 8306220280 8204070018* 8205170474* 8208050024*	50-193 F 50-111 J FDIA 50-206 P 50-206 P	DOOLITTLE, E L DOOLITTLE, E L DOOLITTLE, E, L DOOLITTLE, E L DOROSHOW, J	8304080433 8304220147 8304230141 8304230145 8304020355	50-423 A 50-423 A 50-423 A 50-423 A 50-289 0
IECKAMP, H IEDERICH, Q. J IEDERICH, Q. J IEDERICH, Q. J IEDERICH, Q. J	8306130375* 8306040206 8306130347 8306130352 8306210045	50-289	DIRCKB.W.J DIRCKB.W.J DIRCKB.W.J DIRCKS.W.J DIRCKS.W.J	8209210553* 8306020603 8306030370* 8306060108* 8306060384	FOIA 50~370 P FOIA FOIA 50~440 A	DOROSEY, J. A A L, YSSROD A L, YSSROD A L, YSSROD A L, YSSROD	8306060279 8306300095 8306030280 8306030280 8306150362	50~269
EDERICH, O. J EDERICH, O. J EDERICH, O. J EDERICH, O. J EDERICH, O. J	8306210089 8306210192 8306210263 8306210277 8306210308	50-373 8 50-373 8 50-373 8 50-373 8 50-373 9	DIRCKS, W. J DIRCKS, W. J DIRCKS, W. J DIRCKS, W. J DIRCKS, W. J	8306070463 8306140316 8306140501 8306150330 8306150470	50-275 P 50-322 H COMMISSION 50-409 O 50-213 O	DORSEY, J A DORSEY, J A DORSEY, M DOUDNIKOFF, D DOUGHERTY, J H	8304150362 8306270297 8306280127 8306230048* 8306150379	50~352 0 50~352 0 CONTRACT CONTRACT 50~322 0
EDERICH, Q. J EDERICH, Q. J EDERICH, Q. J EDERICH, Q. J ETCH, R	8306220019 8306220064 8306270002 8306270302 8306140019	50-373 6 50-373 8 50-373 8 50-373 8 50-206 P	DIRCKB, W J DIRCKB, W J DIRCKB, W J DIRCKB, W J	8306160115* 8306160185* 8306160173* 8306160178* 8306160203*	FOIA FOIA FOIA FOIA	DOWNEY, T J DOWNING, Q DOYLE, J DOYLE, W E DRUGA, R J	8304020249* 8304140690* 8304150415* 8304020230 8304110827*	50-328 U 50-346 F 50-445 0 40-8794 50-334 S
ETCH, R, ETCH, R ETCH, R. ETRICH, J, ETZ, C, R	830 & 1 5000 2 830 & 2200 9 5 830 & 2400 0 2 830 & 130 3 9 8 830 & 0 10 10 5	50-361 K 50-206 P 50-362 G 50-322 G 50-324 B	DIRCKB, W J. DIRCKB, W J. DIRCKB, W J. DIRCKB, W J DIRCKB, W J	8306160208* 8306160222* 8306160222* 8306160606 8306170451*	FOIA FOIA FOIA 50~289 P COMMISSION	DENTANDOR E 7 DENTANDOR E 7 DENTANDOR E 7 DENTANDOR E 7 DENTANDOR E 7	8304010084 8304040117 8304070133 8304070149 8304070274	50-382 B 50-382 B 50-382 B 50-382 B
ETZ, C R ETZ, C, R. ETZ, C R ITZ, C, R. ITZ, C R.	8306010109 8306010118 8306010388 8306070053 8306070081	50-324 8 50-325 8 50-324 8 50-325 8 50-325 8	DIRCKS, W. J. DIRCKS, W. J. DIRCKS, W. J DIRCKS, W. J DIRCKS, W. J	8306230321 8306230321 8306230323 8306240279 8306240403	50-289 P 50-395 P REGOD 50-289 Ø SECY	DRUMMOND; F J DRUMMOND; F, J DRUMMOND; F J, DRUMMOND; F J DRUMMOND; F J	8304070307 8304070317 8304130280 8304140002 8304170248*	50-382 8 50-382 8 50-382 E 50-382 6 50-382 0
TZ, G R. :TZ, G, R 'TZ, G, R TZ, G R. TZ, C R	B306070097 B306070102 B306070141 B306070235 B306070342	50-324 8 50-324 8 50-324 8 50-324 8 50-324 8	DIRCKB.W.J DISE.D.P. DISE.D.P. DISE.D.P DISE.D.P	8306280008 8306140564* 8306210182 8306280255 8306280577	COMMISSION 50-410 G 50-410 B 50-410 S 50-410 S	DRUMMOND, F J DRUMMOND, F J DRUMMOND, F J DRUMMOND, F J DRUMMOND, F, J	8306210124 8306270052 8306270127 8306270206 8306270213	50-382 A 50-382 S 50-382 A 50-383 B
TZ, C, R TZ, C, R. TZ, C, R. TZ, C, R. TZ, C, P	8306090136 8306100127 8306100177 8306140214	50-325 S 50-325 S 50-324 S 50-324 R 50-324 Q	DIXON, B. W DIXON, D. J DIXON, D. W DIXON, D. W DIXON, O. W	8304030088* 8304100125 8304010325 8304020142 8304020385	50~397 A 50~462 6 50~395 0 50~395 R 50~395 P	DRUMMOND, F J DRUMMOND, F J DRUMMOND, F, J, DRUMMOND, F J, DRUMMOND, F J	8306270310 8306270330 8306300079 8306300166 8306300188	50-382 8 50-382 8 50-382 8 50-382 8
)	DIXON, O H. DIXON, O H. DIXON, O H. DIXON, O H.	8306070128 8306070202 8306070402 8306100142 8306100163	50-395 8 50-395 8 50-395 P 50-395 8 50-395 8	DUBE, H. DUBGIS, D L. DUBRY, N, E DUCE, S W.	8304280033 8304010242 8304210129* 8304270389* 8304080141	NUREQ 50-278 S 50-278 Q 50-407 G 50-335 P
		P	DIXON, Q W DIXON, O, W DIXON, O, W DIXON, O, W	8304100208 8304100213 8304100241 8304130417 8304140088	50-375 8 50-375 8 50-375 8 50-375 P 50-375 8	DUCK, J R DUCK, J R. DUGGIN, G E DUGGTAD, D. DUGGTAD, D.	8304010398 8304230125 8304230147 8304020147 8304140002	50-250 J 50-250 J 50-327 S 50-292 R 50-292 R

AUTHOR	ACCESSION NUMBER	BUBJECT CATEOURY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJE
DUNAWAY, F R DUNDAS, W J DUNLAP, J M DUNLAP, J M DUNN, D C	8304060221* 8304070404 8304020403* 8304030317* 8304230063*	50~295 a 50~264 J 50~244 a 70~371 FOIA	EDELMAN, M R EDELMAN, M R EDELMAN, M R EDELMAN, M R EDELMAN, M R	8306240269 8306240344 8306270115* 8306270287* 830627028161	50-440 E 70-2768 50-440 Q 50-440 A	ELSASSER.T C ELSASSER.T.C ELSASSER.T.C ELSASSER.T.C ELSASSER.T.C	8306060211* 8306090241* 8306160246* 8306200225* 8306230118*	50-423 50-245 50-193 70-114; 70-820
DUNN, R G DUNN, R E DUNN, R G DUNN, R W	8304230064* 8304230066* 8304270623* 8306230067* 8306230067*	FOIA FOIA CONTRACT FOIA FOIA	EDELMAN, M R EDGAR, G L EDISON, G E EDISON, G E EDISON, G E	8306300169 8306270317 8306010018 8306080321 8306080438	50-440 S 50-537 G NUREQ 50~482 A 50-483 A	ELY, J O ELY, J O ELY, J O EMBREY, B EMBREY, B	83040700B7 8304070241 8304300046 8304090203* 8304090287*	50-259 50-259 50-259 50-255 50-255
DUNN, W J DUNNE, L A DUNNING, T C DUPONT, D DUPONT, D	8306230071 * 8306010094 8306080227* 8306170379* 8306170390*	FOIA 50-201 P 50-445 G 50-142 T 50-142 T	EDLEHAN, M R EDSALL, J EFTHYHIOU, G C EGAN, G R EGAN, G R	8306140661 8306080174 8306160506* 8306080048* 8306290496*	50-440 A 50-322 H 50-445 Q 50-440 A 50-329 A	EMBREY, B EMCH, R L EMCH, R L EMCEL, W P. ENGELKEN, R H	8306140831# 8306100224 8306150152 8306010001	50-255 50-155 50-155 71-6400 50-275
DUPONT, D DUPONT, D DUPONT, S G DUPREE, D C DURAND, R J	8304170417* 8304170426* 8304100175* 8304020197 8304140539*	50-142 T 50-142 T 50-373 G 50-327 R 50-329 A	EICH, E EICH, E EICHENHOLZ, H EICHENHOLZ, H EISELE, P J	8304020274 8304140442 8304140004* 8304200144* 8304080351*	50-247 R 50-247 R 50-271 G 50-293 G 50-410 A	ENGELKEN, RH ENGELMANN, R ENGELMANN, R ENNIB, J END, M. B	8306160281* 8306200179 8306280106 8306170307* 8306100075	50-204 40-8584 40-8348 50-249 50-529
DURAND, R J DURAND, R J DURAND, R J DURAND, R J DURAND, R J	8306140540* 8306140544* 8306140546* 8306140548* 8306140552*	50-329 A 50-329 A 50-329 A 50-329 A 50-329 A	EISENHUT, D. EISENHUT, D. G EISENHUT, D. G EISENHUT, D. G EISENHUT, D. G	8306280181* 8208060366 8305110468 8305110471 8305110481	50-219 P 50-387 P 50-275 P 50-275 P 50-275 P	ENOB, J T ENOB, J T ENTHIBLE, E B ERICKBON, P ERICKBON, R W	8306210093 8306210093 8306060316 8306270318 8306150821#	TOPREP TOPREP 50-170 50-213 CONTRAC
DURAND, R L R JUNANUG L R JUNANUG R R JUNANUG R R JUNANUG	8306140573* 8306140579* 8306140587* 8306140597* 8306140605*	50-329 A 50-329 A 50-329 A 50-329 A 50-329 A	EISENHUT,D.C EISENHUT,D.C EISENHUT,D.C EISENHUT,D.C EISENHUT,D.C	8305110486 8305110488 8305110487 8305110472 8305110475	50-275 8 50-275 8 50-275 P 50-275 0 50-275 R	ERNST, M L ERNST, M L EURY, L W EURY, L W EURY, L W	8204120488 * 821122032 * 8304070101 8304080122 830427055 *	50-416 50-245 50-261 50-261 50-261
DURR.J P DUVERNOY.E G DWYER.P W DWYER.P W DYKERS.L G	8304210107* 8304030009 8304140470 8304140514 8304020500	50-322 Q NUREQ 50-70 B PT21 40-8584	EISENHUT, D Q EISENHUT, D Q EISENHUT, D Q EISENHUT, D Q EISENHUT, D Q	8305110498 8305110499 8305110500 8306060066* 8306070216	50-275 R 50-275 T 50-275 P FDIA 50-312 P	EVANS, J S EVANS, H, A EVERETT, R J EVERETT, R J. EVERETT, R J.	8304280170 830603038 8304080165* 8304080170*	NUREO 71-7133 40-8027 40-8661 40-8681
DYNNER, A R DYNNER, A R DYNNER, A R DYNNER, A R DYNNER, A R	8306130423 8306130423 8306150214* 8306200337 8306270480	50-322 0 50-322 0 50-322 0 50-322 0	EISENHUT, D Q EISENHUT, D Q EISENHUT, D Q EISENHUT, D Q EISENHUT, D Q	8304070431* 8304080199 8304080201* 8304090323 8304090349	50-370 P 50-275 P 50-275 P MISC NUREQ	EVERETT,R, J. EVERETT,R J. EVERETT,R, J. EVERETT,R, J. EVERETT,R J. FAIRTILE,H B.	8306090132* 8306090138* 8306090175* 8306090179* 8306010049	40-8698 40-8698 40-8663 50-302
DYNNER, A R DYNNER, A R DYNNER, A R DYNNER, A R DYNNER, A R	8304270480 8304270485* 8304270485* 8304270492* 8304300081	50-322 0 50-322 0 50-322 0 50-322 0	EIBENHUT.D Q EIBENHUT.D G EIBENHUT.D Q EIBENHUT.D Q EIBENHUT.D Q	8306130457 8306130457 8306150221 8306150285 8306150404	50-412 C 50-267 F 50-458 F 50-461 F 50-322 O	FALCONER, K. L. FALKENHEINER, D. FALKENHEINER, D. FARAHZAD, P. FARRAR, D. L.	8304020011 8304220117 8304220117 8304280044 8305240238	NURE9 50-458 50-458 NURE9 50-237
DYNNER, A R DYSON, J S EADEPESTO, A EAGLE, J EAPEN, P K	8306300081 8306130111 8306130398 8306130344 8306230199*	50-322 0 50-286 I 50-322 0 50-265 9 50-244 0	EISENHUT,D G EISENHUT,D G EISENHUT,D G EISENHUT,D G	8306170473 8306170475 8306200034 8306200435 8306210166*	50-483 F 50-289 P 50-390 F MIBC 50-219 P	FARRAR, D. L FARRAR, D. L FARRAR, D. L FARRAR, D. L FARRAR, D. L	8306020449 8306070392* 8306090194 8306100218 8306100250*	PR 50-454 50-237 50-10 50-373
EARLEY, A F EABTERLING, R O EBENHACK, D O EBENHACK, D G EBERBOLE, J C	8304150214* 8304160401 8304080345 8304240374 8306010199	50-322	EISENHUT, D Q EISENHUT, D Q EISENHUT, D Q EISENHUT, D Q	8306210299* 8306220288 8306230047 8306240027* 8306240474	50-409 F PR TOPREP 50-460 A 50-275 P	FARRAR, D. L. FARRAR, D. L. FARRAR, D. L. FARRAR, D. L. FARRAR, D. L.	8306160224 8306160225 8306160435* 8306230425 8306270071*	NUREQ 50-373 50-373 REGOD 50-456
EBERBOLE, J C EBERBOLE, J C EBERBOLE, J C ECKENRODE, R J ECKERT, E C	830601020B* 8306020095 8306020098 8306030009 8306280456*	50-213 0 50-213 0 ACRB NUREQ 50-397 E	EISENHUT,D Q EISENHUT,D Q EISENHUTH,F T EL-ASHRY,M T	8304280570# 8304280570# 8304290073# 8304280510 8304140524	50-261 P 50-297 P 50-141 W 50-387 S 50-327 R	FARRAR, D 1. FARRAR, D L FARRELL, E V FARRELL, R E FABANO, A	8304300073* 8304300214* 8304300044 8304300043* 8304040244*	50-373 50-295 50-317 50-346 50-320
ECKHARDT, J H ECONOMOB, N, EDDINOS, M EDDLEMAN, H EDDLEMAN, H	830 6230398 830 61 40652* 830 60201 97 830 601 0355 830 601 0359	50-361 B 50-338 Q 50-327 R 50-400 Q 50-400 Q	ELIN, J P ELLENBERGER, S ELLIDYT, J L ELLIS, J ELLIS, J	8306070304	50-397 Q 50-206 P RE00D 50-445 Q 50-445 Q	FAW,R E FAY,C W FAY,C W FAY,C W	8305020231* 8305020231* 8306010428 8306060078 8306060156	50-188 50-266 50-266 50-266 50-266
EDDLEMAN, W EDDLEMAN, W EDDLEMAN, W EDDLEMAN, W EDDLEMAN, W	8304030337 8304090222 8304270307 8304270313* 8304270402	50-400 G 50-400 G 50-400 G 50-400 G 50-400 G	ELLIB, J ELLIB, J ELLIB, J ELLIB, J ELLIB, J	8304100223 8304100227*	50-445 Q 50-445 Q 50-445 Q 50-445 Q 50-445 Q	FAY,C W FAY,C W, FAY,C W FAY,C,W FAY,C,W	8304070084 8304070185* 8304200137 8304200240 8304200247	50-266 50-266 50-266 50-266 50-266
EDDLEMAN, W EDDLEMAN, W EDDLEMAN, W. EDELMAN, M EDELMAN, M	8306270361 8306270381 8306300124 8306160224 8306010058	50-400 Q 80-400 Q PR NUREQ 50-440 E	ELLIS, J ELLIS, J ELLIS, T, S ELLIS, T, S	8304150404 8304150414 8304080171	50-445 Q 50-445 Q 50-445 Q 50-322 Q	FAY, C. W. FAY, C. W. FAY, C. W. FAY, C. W FAY, C. W	8306230356	50-266 50-301 50-266 50-266 50-266
EDELMAN, M. R EDELMAN, M. R EDELMAN, M. R EDELMAN, M. R EDELMAN, M. R	9306090044 9306100117 9306100190 9306130305* 9306200095	50-440 A 50-440 S 50-440 A 50-440 Q 50-440 E	ELLIS, T S ELLIS, T S ELLIS, T S ELLIS, T S, ELLIS, A	9304080177* 9304220017 9304220017	50-322 p 50-322 p 50-322 p 50-322 p 50-322 p	FAY.C.W FEARER.W.P. FEARER.W.P. FEDERICK.W.C FEIL.R.A	8304040302 #306170334#	50-246 50-454 50-454 50-390 50-397
EDELMAN, M R EDELMAN, M R EDELMAN, M R EDELMAN, M R EDELMAN, M, R	8306200120 6306220015 6306220039 8306220058 8306240186	50-440 S 50-440 B 50-440 B 50-440 S 50-440 S	ELMB, A ELROD, B A ELBASBER, T ELBASBER, T C. ELBASBER, T C.	8304290379# (8304200146# (8304040171# (50-213 R 50-335 Q 60-293 Q 50-245 Q 70-344	FEIL, R. A FEINBERG, J. D. FEINBERG, J. D FEITKNECHT, C. FEITKNECHT, C.	8304290393 8304290393 8304070120	50-397 50-322 50-322 50-334 50-334

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTROR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	BUBJECT CATEGORY
FELDMAN.8 A FELTON, J, M FELTON, J M FELTON, J M FELTON, J M	8304220233* 8304200277 8304030010 8304030344 8304030374	CONTRACT FOIA 50-320 Q FOIA FOIA	FELTON, J M	8306160043 8306160050 8306160052 8306160058 8306160058	50-305 F FOIA 50-206 G 50-528 F 50-206 G	FIELDS, J A FIELDS, J A FIELDS, J A FIELDS, J A FIELDS, J A	8304210370 8304210381 8304220238 8304220247 8304220277	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT
FELTON, J M FELTON, J M FELTON, J M FELTON, J M	8304030382 8304030383 8304030448 8304030450 8304030454	FOIA FOIA 50-148 G FOIA FOIA	FELTON, J M FELTON, J M FELTON, J M FELTON, J M FELTON, J M	8306160071 8306160072 8306160073 8306160081 8306160093	50-254 F 50-322 F FOIA 50-317 S FOIA	FIELDS, J A FIELDS, J A FIELDS, J A FIELDS, J A	8306220302 8306230054 8306230192 8306240055 8306240353	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT
FELTON, J M FELTON, J M FELTON, J M FELTON, J, M FELTON, J M	8304030461 8304040003 8304040011 8304040013 8304040032	FOIA FOIA FOIA 50-354 G FOIA	FELTON, J M FELTON, J M FELTON, J M FELTON, J M FELTON, J M	8306180096 8306160110 8306160151 8306160160 8306160171	50-322 F FOIA FOIA FOIA FOIA	FIELDS, J 8 FIELDS, J 8 FINAMORE, D A FINAMORE, B A FINAMORE, B A	8304270253* 8304280004 6304220144 8304220153* 8304270370	50-387 R 50-387 S 50-537 Q 50-537 Q 50-289 H
FELTON, J, M FELTON, J M FELTON, J M FELTON, J, M FELTON, J, M	8304040037 8304040051 8304040104 8304040373 83040404	FOIA 50-245 P FDIA FOIA 50-312 F	FELTON, J M FELTON, J M FELTON, J M FELTON, J M FELTON, J M	8306160177 8306160186 8306160189 8306160197 8306160200*	FOIA FOIA 50-72 F 50-206 Q 50-206 Q	FINDLAY, J A FINDLEY, D E FINDLEY, D E FINDLEY, D E FINDLEY, D E	8304150402 8304070452* 8304280057* 8304280118* 8304280147*	NUREG CONTRACT CONTRACT CONTRACT CONTRACT
FELTON, J. M.	8304070019 8304070020 8304070025 8304070439 8304080031	50-206 P FDIA POIA FDIA FDIA	FELTON, J M FELTON, J M FELTON, J M FELTON, J M FELTON, J M	8306160200* 8306160269 8306160346 8306160660 8306160676	50-206	FINKEL,A E FINLAYSON.F C FINNAN,C F FINNERAN,J C FINSTON.R	8306200086* 8306150584 8304290092* 8306080248* 8306170379*	50-423 G NUREG 50-409 P 50-445 G 50-142 T
FELTON, J. M FELTON, J. M FELTON, J. M FELTON, J. M FELTON, J. M.	9304080044 9304080255 9304080257 9304080257 9304080242	FOIA FOIA FOIA SD-443 G 50-320 G	FELTON, J M FELTON, J M FELTON, J M FELTON, J M FELTON, J M	8304140484 8304170089 8304200014 8304200037 8304200034	50-346 F FOIA 50-155 F FOIA 50-313 F	FINSTON, R FIORELLI.G FISCHER.D L FISCHER.W L FISHER.C R	8306170426* 8306280452* 8306070174* 8306230153* 8306170334	50-142 T 50-528 G 50-293 P 70-8 NUREG
FELTON, J M. FELTON, J M. FELTON, J M. FELTON, J M FELTON, J M	8304080248 8304080272 8304080275 8304080277 8304080281	FOIA FOIA FOIA 50-498 Q 50-528 A	FELTON, J M FELTON, J M FELTON, J M FELTON, J M FELTON, J M	8306200296 8306200299 8306200434 8306210289 8306210300	FOIA 50-341 A 50-289 G FOIA FOIA	FISHER,W L FITZGERALD,J A FJELDAL,O FLACK,E FLACK,E	B304230139* B304230348 B3040B0194 B3040101B3 B304140414	70~8 50-367 6 50-322 H I&E I&E
FELTON, J M FELTON, J M FELTON, J M FELTON, J M FELTON, J. M	8304080291 8304080297 8304080297 8304080305 8304080313	FOIA FOIA 40-2061 50-358 A 50-148 P	FELTON, J M FELTON, J M. FELTON, J M. FELTON, J M. FELTON, J M.	8306210306 8306210312 8306210320 8306210327 8306210340	50-10 F FOIA FOIA FOIA FOIA	FLACK, E FLACK, E FLANAGAN, D D FLANAGAN, D D FLEENOR, C	8306210131 8306300115 8306150370 8306150370 8306170480	1&F 1&E 50-322 0 50-322 0 CONTRACT
FELTON, J M FELTON, J M FELTON, J M FELTON, J M FELTON, J. M	8304080322 8304070018 8304070024 8304070027 8304070057	FOIA 50-387 F 50-219 F 50-285 F 50-346 F	FELTON, J M. FELTON, J M FELTON, J M FELTON, J M FELTON, J M	8304210355 8304210357 8304210343 8304210348 8304210382	50-10 F 50-285 F 50-348 F 50-267 F 50-389 F	FLEENOR, C FLEENOR, C FLEENOR, C FLEENOR, C FLEENOR, C	8306220220 8306220220 8306220249 8306220253 8306220262	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT
FELTON, J M FELTON, J M FELTON, J M FELTON, J M FELTON, J M	8304090201 8304090204 8304090254 8304090248 8304090273	50-255 F 50-348 F 50-282 F 50-289 F 50-528 F	FELTON, J M FELTON, J M. FELTON, J M. FELTON, J M. FELTON, J M.	8304220225 8304220252 8304220287 8304220273 8304220307	50-335 F 50-346 F 50-413 F 50-289 F 50-321 F	FLEENOR, C FLEENOR, C FLEESCHAKER, D FLEISCHMANN, R	8306220267 8306220316 8306240031 8305040415 8306170163	CONTRACT CONTRACT CONTRACT 50-275 0 50-277 R
FELTON, J M FELTON, J M FELTON, J M FELTON, J M	8304090281 8304090285 8304090289 8304090370 8304090374	50-346 F 50-255 F 50-27 F 50-346 F FOIA	FELTON, J M FELTON, J M. FELTON, J M FELTON, J M FELTON, J H	8304230005 8304230007 8304230073 8304230072 8304230127	50-373 Q FDIA 50-282 F 50-213 F 50-14 P	FLEIBHER,Z S FLIPPO,T A FLORY,C A FLORY,C A FLORY,C A.	8304080200 8304130127# 8304070033 8304070372 8304140287	50-247 C 50-382 Q WASTE MGT WASTE MGT WASTE MGT
FELTON, J M FELTON, J M FELTON, J M FELTON, J M	8304090381 8304090391 8304090404 8304100009 8304140023	FDIA 50-261 F 50-382 F 50-312 0 50-335 F	FELTON, J M FELTON, J M FELTON, J M FELTON, J M FELTON, J M	8306240007 8306240352 8306280034 8306280182 8306280190	F01A F01A 50-322 F F01A F01A	FLYNN, J, D FLYNN, J D FLYNN, J D FLYNN, M FLYNN, M	8306020312 8306210267 8306230435 8306070026# 8306220186	70-2892 50-358 H 50-358 H FOIA CONTRACT
FELTON, J M. FELTON, J M. FELTON, J M. FELTON, J M. FELTON, J M	8306140217 8306140237 8306140265 8306140381 8306140828	50-155 F 50-321 F 50-309 F 50-277 F 50-255 F	FELTON, J M. FELTON, J M FELTZ, D E FELTZ, D E FELTZ, D E	8306280206 8306280224 8306010298 8306010358 8306060213	50-320 P FDIA 50-128 H 50-128 P 50-128 P	FLYNN, M FLYNN, M FLYNN, M FLYNN, M FLYNN, M J	8306280050 8306280113 8306280141 8306090447 8306090467	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT
FELTON: J H 中間にTON: J, H, 中のにTON: J, H, FELTON: J H	8306150025 8306150032 8306150037 8306150082 8306150091	50-289 F 50-313 F 50-321 F 50-317 F 50-327 F	FERNANDEZ,S J FEY,F.L FIEDLER,P B FIEDLER,P B FIEDLER,P B	8306270157 8306090261* 8305020461 8306020090 8306020341	NUREO 50-282 F 50-219 I 50-219 R 50-219 O	FLYNN, M J FLYNN, B F FLYNN, B F FODERADO, A JI FOGARTY, D J	8306090484 8306080149 8306080160 8306070452 8306010164*	CONTRACT 50-400 0 50-400 0 NUREO 50-361 0
FELTON, J. M FELTON, J. M FELTON, J. M FELTON, J. M FELTON, J. M	8306150101 8306150133 8306150290 8306150334 8306150344	50-445 F 50-321 F 50-271 F 50-213 F 50-329 F	FIEDLER, P B FIEDLER, P B FIEDLER, P. B, FIEDLER, P, B FIEDLER, P B	8304020353 8306020398 8306090027* 8306090235 8306130384	50-219 8 50-219 8 50-219 F 50-219 R 50-219 P	LOTEA'M Y LOTEA'L LOTEA'L LOTEA'T LOTEA'T LOTEA'T LOTEA'N LOTE	8304200381* 8304140043* 8304010378* 8304230212* 8304240050	50-361 G 50-272 P 50-247 G 50-247 G NUREG
FELTON, J. H. FELTON, J. H. FELTON, J. H FELTON, J. H FELTON, J. M	8306150454 8306150482 8306150609 8306150632 8306160013	50-483 F 50-482 F 50-322 F 50-373 F FOIA	FIEDLER.P.B FIEDLER.P.B FIEDLER.P.B FIEDLER.P.B FIELD.H.C	8306160258* 8306200340 8306210065 8306280406 8306100208	50-219 0 50-219 F 50-219 0 50-219 P 50-395 8	FORAT,H FORCHT,K A FORD,D C FORD,E J FORD,E,J	8304280572 8304070210* 8304080224* 8304140162* 8304140370*	50-322 0 50-413 E 50-445 0 50-327 0 50-327 0
FELTON, J. N FRLTON, J. N FELTON, J. N. FELTON, J. N. FELTON, J. N.	9305160019 9306160025 9306160027 9305160031 9306160033	FDIA 50-146 P 50-348 F 50-329 A 50-329 A	FIELDS, J FIELDS, J A FIELDS, J A FIELDS, J A	8306230218 8306020506 8306160259 8306170253 8306210337	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT	FORD, J T FORD, J. T. FORNEY, W FORNEY, W L FORST, H	8306140674 8306270121 8306170364* 8306230290# 8306270390	70-1201 70-1201 50-484 0 50-454 0 50-322 0

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
FORTUNA,R A FORTUNA,R A FORTUNA,R A FOBTER,C M FOBTER,C M	8305040156	50-358 A	GAD.R K	6304150387	50-443 @	GIESLER.C W	8305170055	50-305 Q
	8306160218*	50-204 G	GAD.R K	6304150387	50-443 @	GIESLER.C W	8305200102	50-305 P
	8306160253*	50-204 G	GAD.R K	6304150388	50-443 @	GIESLER.C W	8305210041*	50-305 Q
	8306030169	XPORTLIC	GAD.R K	6304150388	50-443 @	GIESLER.C W	8305270110	50-305 S
	8306150467	XPORTLIC	GAD.R K	6304280543	50-443 @	GIESLER.C W	8305280373	50-305 P
FOSTER.D O FOSTER.D O FOSTER.D O FOSTER.D O FOSTER.D O	8306100221	50-424 S	GAD.R K	8306280543	50-443 0	GILBERT,L D	8304140374*	50-482 G
	8306100231	50-424 S	GAGE.K	8306160894	50-289 0	GILBERT.L D	8304140374*	50-445 G
	8306100259	50-424 S	GAGLIARDO.J E	8306140354	50-482 0	GILBY.E V	8304300172	NUREG
	8306100264	50-424 A	GAINES.T M	8306170461	71-9156	GILCHRIST,C W	8304220054	50-170 C
	8306100265*	50-424 A	GAJIC.Z	8306270221	50-304 8	GILCHRIST.J E	8304040318	40-8064
FOSTER.D O	8306100274	50-424 B	GALLAGHER, D W	8305310224	50-245 P	GILCHRIST, J E	8306200421	40-8064
FOSTER.D O	8306240274	50-424 A	GALLAGHER, J W	8306140262*	50-277 0	GILDENHORN, A	8306200224	CONTRACT
FOSTER.D O	8306240274	50-424 A	GALLAGHER, J W	8306280235	50-277 0	GILDNER, H L	8306300207*	50-440 G
FOSTER.D O	8306270166	50-424 S	GALLO	8306140154	50-271 6	GILINSKY, V	8306070337	50-289 G
FOSTER.D O	8306270166	50-424 S	GALLO	8306170332	50-271 6	GILINSKY, V	8306100237	50-289 H
FOSTER.E R	8306280353	50-994 S	GALLO, J	8306130452*	50~454 0	GILINSKY, V	8304240330*	COMMISSION
FOSTER.L	8306170379*	50-142 T	GALLO, J	8306130452*	50~454 0	GILINSKY, V	8304270323*	50-289 0
FOSTER.L	8306170426*	50-142 T	GALLO, J	8306150405	50~155 0	GILLEN, D M	8304020328*	40-8691
FOSTER.L E	8306140471*	50-395 Q	GALLO, J	8306150405	50~155 0	GILLEN, D M	8304070487	40-8681
FOSTER.R F	8306200160	ACRS	GALLO, J	8306220023	50~155 0	GIRARD, E H	8304270332*	50-321 0
FOSTER.R F FOX.C FOX.C FOX.E K FOXWELL.D Q	8306200168 8306130398 8306270390 8306170027* 8306220255*	ACR8 50~322 & 50~322 & CONTRACT CONTRACT	GALLO, J GALLO, J GALLO, J GALLO, J	8309550105 8309550092 8309550092 8309550053	50-155 0 50-155 0 50-155 0 50-155 0 50-155 0	OIROUX.E J OLEABON.J P OLEABON.J P OLEABON.J P	8304140454 8304020443 8304100209 8304130434 8304150287	50-518 8 50-247 0 50-247 0 50-247 0 50-483 0
FRAHM, R FRAHM, R FRAHM, R FRAHM, R FRAHM, R	8304020404 8304030188 8304030301 8304030344 8304170021	50-311 8 50-311 8 50-311 8 50-311 8 50-311 8	GALLO, J GALLO, J GALLO, J GALLO, J GALLO, R M	8304270014 8304270014 8304280535 8304280535 8304030314*	50~454 C 50~454 C 50~454 C 50~454 C 50~307 C	OLENN, J GLEAGON, J P GLEAGON, J P GLEAGON, J P	8304270137 8304270140 8304270247 8304060017* 8304070100	50-489 0 50-247 0 50-247 0 FOIA I&E
FRAHM.R	8306170144	50-272 B	GALLO,R M	8306060215*	50-322 0	GLENN.J E	8305060028*	FO1A
FRAHM.R	8306170153	50-311 S	GALLO,R M	8306060268*	50-322 0	GLENN.J E	8305170097*	FO1A
FRAHM.R	8306170207	50-311 S	GALLO,R M	8306070353*	50-271 0	GLOERSEN.N W	8305130412*	50-254 Q
FRAHM.R	8306170338	50-272 S	GALLO,R M	8306070076*	50-322 0	GNUGNOLI.G N	8305140325	WASTE MOT
FRAHM.R	8306170362	50-311 S	GALLO,R M	8306070366*	50-271 0	GODDARD.R J	8305080163	50-461 Q
FRAHM.R	8306170381	50~272 8	GALLO,R M	8306160006#	50-271 0	GODDARD,R J	8306090296	50-309 Q
FRAHM.R	8306210187	50~272 8	GALLO,R M	8306200181#	50-271 0	GODDARD,R J	8306100045	50-483 Q
FRAHM.R	8306270188	50~311 8	GALLOCI,R M	8306230405#	50-443 0	GODDARD,R J	8306150236	50-309 Q
FRAHM.R	8306270267	50~272 8	GALLUCCI,R H	8306020131	NUREO	GODDARD,R J	8306150241	50-309 Q
FRAHM.R	8306270343	50~272 8	GARCIA,E	8306070339#	50-204 0	GODDARD,R,J,	8306170363	50-155 Q
FRAHM.R	8304280254	50-272 8	GARCIA,E	830 40 90 1 7 4	50-275 9	GDDDARD,R.J	8304230007	50-155 0
FRAHM.R	8304280488	50-272 8	GARCIA,E M	830 40 70 2 8 7 *	50-243 G	GODDARD,R.J	8304230011	50-309 0
FRAZIER.J L	8304080348*	71-4909	GARCIA,P	830 42 00 43 7	40-3453	GODDARD,R.J	8304290504	50-155 0
FREMONT.S	8304080215	50-358 0	GARDE,B	830 41 40 03 5	50-329 A	GODY	8304210248	50-334 B
FREMONT.S	8304080250	50-358 0	GARDE,B	830 41 40 1 7 2	FOIA	GODY,A.	8304230001	50-245 B
FRENCH, J F FRENCH, L D FRENCH, L D FRESHLEY, M D FREUDENTHAL, N	8306080191 8306170339 8306280144 8306240032 8306020294	50-247 H 50-29 S 50-29 B NUREQ 40-8064	GARNEH.L W GARRETT.C A GARRICK.B J GARRITY.J H GARRITY.J H	8304140705* 8304280249 8304210334* 8304020146 8304020352	50-324 Q 50-400 D FOIA 50-309 P 50-309 R	QODY, A. F. QODY, A. T.	8306280582 8306010153* 8306010327* 8306010339* 8306020403*	50-397 8 70-371 50-334 Q 70-687 50-244 Q
FREUDENTHAL, N	8306210454	40~80&4	GARRITY, J H	8304020425	50-309 S	QDDY, A. T	8306030317*	70-371
FREUDENTHAL, N	8306220113	40~8584		8304020524	50-309 P	QODY, A. T	8306030324*	70-371
FREUDENTHAL, N	8306220121	40~2259		8304030341	50-309 S	QODY, A. T	8306090044*	50-219 0
FREUDENTHAL, N	8306220126	40~8728		8304040310	50-309 P	QODY, A. T	8306170245*	70-371
FREUDENTHAL, N	8306230331	PR		8304150263	50-309 F	QODY, A. T	8306230475*	50-272 0
FREUDENTHAL, N	8306240444	40-8748	GARRITY, J H	8306170166	50-309 F	QCLDBERO, J. H	8306070204	50-498 F
FRIEDMAN, L	8306230263	1&F		8306170186	50-309 S	GOLDBERO, J. H	8306140052	50-498 A
FRIEDMAN, L	8306280537	1&E		8306170430	50-309 S	GOLDBERO, J. R	8306230460	50-498 A
FRIEDMAN, L	8306070100	1&E		8306270295	50-309 S	GOLDBERO, J. R	8306090338	50-289 C
FRIEDBEE, D	8306200213*	50-344 I		8306010392	50-445 A	GOLDBERO, J. R	8306140702	50-275 D
FRIBCO.D C	8306300195	PR	GARY: R J	8306090043	50-445 B	COLDBERG, S C	8306150245	50-289 0
FROUNFELKER.R	8306210151	50-255 J	GARY: R J	8306130440	50-445 B	COLDBERG, S C	8306130361	50-454 0
FRUCGI.E L	8306150416	50-222 e	GARY: R J	8306300055	50-445 B	COLDBERG, S C	8306130318	50-454 0
FRY.L	8306020240*	50-272 F	GARY: R J	8306300074	50-445 B	COLDBERG, S, C,	8306170378	50-454 0
FRYE,J H	8306030321	50-358 e	GARY: R J	8306300088	50-445 B	COLDBERG, S C	8306210281	50-454 0
FRYE, J H	8306060282	50-142 0	GARY,R J.	8304300147	50-445 8	OOLDEN, J C	8306220086	50-237 R
FRYE, J, H	8306080162	50-358 0	Gauny,R D	8304240372	71-8601	OOLDENBERG, C	8306210314	50-10 F
FRYE, J H	8306160581	50-358 0	Gearb.G	8304020340	50-278 P	OOLDFEIN, H R	8306130445	50-454 Q
FRYE, J H	8306160616	50-142 0	Gerdeman,F W	8304130347	40-7869	OOLDFEIN, H R	8306130445	50-454 Q
FUHRMAN, Q R	8306020436	50-317 8	Gerdeman,F W	8304140384	40-8698	OOLDFEIN, H R	8306130452*	50-454 Q
FUJITA,N FULLER,C H FULTON,J.F FURR,B J FURR,B J	8306210024* 8306160434 8306200316* 8306140264 8306270247	50-29 P 50-267 R 50-244 P 50-261 G 50-261 G	GERDEMAN, F W GERRETS, T F. GERBTNER, W C GIBBONS, T. D. GIBBON, A F	.8306220311 8306130206 8306270321# 8306140375# 8306140668	40-8674 50-382 A 50-461 G 50-400 G MISC	GOLDFEIN, H R GOLDFEIN, H R GOLDBHITH, M W GOLDBHITH, M W	8306200300 8306200300 8306240375 8306060188* 8306060188*	50-454 9 50-454 9 71-7015 50-322 9 50-322 9
FURSE.M C FURSE.M C GAD.R K GAD.R K GAD.R K	8304280535 8304280535 8304040305 8304040305	50-454 @ 50-454 @ 50-309 @ 50-309 @	OIBBON, J OIBBON, R L OIBBEKE, J A. OIBBLER, C W. OIBBLER, C W	8306020077 8306270540 8306240241 8306020375 8306070070	50-336 R 50-413 0 RE9 50-305 P 50-305 J	GOLOSMITH, H W GOLDSMITH, M W GOLDSMITH, R. GONZALES, J C GOOD, R	8304070384* 8304070384* 8304170377 8304070107* 8304200335	50-322 0 50-322 0 50-289 H 50-529 8 50-358 0
GAD.R K GAD.R K GAD.R K GAD.R K GAD.R K	8304040332 8304070290 8304070290 8304070294 8304070294	50-307 G 50-309 G 50-309 G 50-309 G 50-309 G	GIEBLER.C W GIEBLER.C W GIEBLER.C W. GIEBLER.C W.	83061400187 8306140001 8306140048 8306160048* 8306160048*	50-305 P 50-305 R 50-305 P 50-305 F 50-306 Q	GDDD: R. GDDD: R. GDDD: ING: B GDDDMAN: L. S	8305200335 8305200341* 8305200341* 8305300075 8305300029	50-35B G 50-35B G 50-35B G 50-289 G 50-409 R

AUTHOR	ACCESSION NUMBER	BUBJE		AUTHOR	ACCESSION NUMBER	SUBJEC	YNC	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
GOODMAN, L S GOODMAN, L S GOODWIN, D C GOODWIN, D C	8306160378 8306170376 8306270337 8306070099 8306210226	50-409 50-409 50-409 50-260 50-260	ថ ទ ទ	GREENE, S. R. GREENMAN, E. G. GREENMAN, E. G. GREENMAN, E. G. GREENMAN, E. G.	B306280080 B306170343 B306030316* B306230002 B306230349	50-259 50-307 50-309 50-286 50-247	P 5 9 5	GUSTAVE,R P GUSTAVE,R P GUSTAVE,R P GUSTAVE,R P GUSTAVE,R P	83062201581 83062201921 83062202221 83062202271 83062202331	CONTRACT CONTRACT CONTRACT
ODADON, C ODADON, C ODAE, O C ODTZMEN, G GRABER, L	B304010100* B304010304* B304240243* B304040309*	50~271 TOPREP	Q 0	GREGER, L R GREGER, L R GREGER, L R GREGER, L R GREGER, L R	8306100220+ 8306100227+ 8306100258+ 8306130333+ 8306270167+	50 -151 50 -155 50-373 50-305 50-156	0 0 0	GUSTAVE,R P GUSTAVE,R P GUSTAVE,R P GUSTAVE,R P GUSTAVE,R P	8306220241* 8306220255* 8306220259* 8306220266* 8306220272*	CONTRACT CONTRACT CONTRACT
ORABER,L D ORACE,J N ORACE,R H ORACE,R H ORACE,R H	8304160030 8304140444 8304280009 8304280009	50-146 50-537 50-309 50-309 50-309	P R P P	GREGER, L R GREGER, L R GREGO, H I GREGORY, W D GREGORY, W S	B30427018/* B304300231* B304020374* B304030454 B304070422	50 -2 50-409 50-354 70-2982 RES	0 0 0	GUSTAVE,R P GUSTAVE,R P GUSTAVE,R P GUSTAVE,R P GUSTAVE,R P	8306220276* 8306220282* 8306220305* 8306220320* 8306220320*	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT
ORAEGSER, K L ORAEGSER, K L ORAEGSER, K L ORAEGSER, K L ORAEGSER, K L	8305060148 8306060250 8306100064 8306130307 8306130351	50-304 50-304 50-275 50-275 50-275	ទ គ គ គ គ គ គ	ORICE, J C GRIDLEY, R L GRIFFIN, B N GRIFFIN, J GRIMESEY, R A	8306170084 8306070174* 8306140315 8306130409 8306020011	FDIA 50-293 NUREG 50-313 NUREG	P S	GUSTAVE,R P GUSTAVE,R P GUSTAVE,R P GUSTAVE,R P GUSTAVE,R P	8304230059* 8304230198* 8304230491* 8304230494* 8304230509*	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT
ORAESSER.K L GRAESSER.K L GRAESSER.K L GRAESSER.K L GRAHAM.E T	8306140412 8306210234 8306270168 8306270221 8306010322	50-295 50-304 50-295 50-304 50-293	2 2 3 3 4	ORIMSLEY, D H ORIMSLEY, D H OROCE, R H OROCE, R H OROESCH, Q L	8306160204* 8306160207* 8306020152 8306230361 8306150368	FOIA 50-204 50-309 50-309 50-302	Q R F	GUSTAVE,R P GUSTAVE,R P GUSTAVE,R P GUSTAVE,R P GUSTAVE,R P	0304240034* 8304240057* 8304240358* 8304280057* 8304280118*	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT
GRAMM,R A GRANT,J GRANT,J M GRANT,W B GRANT,W B	8304230405* 6304040211* 8304150247* 830410022 0 * 8304130333*	50-443 50-423 50-352 50-151 50-305	G G G G	GROSS, P. J. GROSSMAN, H GROSSMAN, H GROSSMAN, H GROSSMAN, H	8306130403 8306160571 8306270254 8306270333 8306270348	50-537 50-244 50-460 50-460 50-460	A G G	GUSTAVE,R P GUSTAVE,R P GUSTAVE,R P GUSTAVE,R P GUSTIN,H L	8306280147* 8306280159* 8306270625* 8306270633* 8306100136*	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT FO-364 P
GRANT, W E GRAVES, R H GRAVES, R H GRAVES, R H GRAVES, R H	8306270187* 8306020248 8306160459 8306170381 8306170301	50-2 50-213 50-213 50-213	0 R R S	GROSSMAN.H GROTENHUIS,M GROUTAGE,T M GUCHA.L [GUCHA.L T	8306300127 8306020648 8306140161 8306030233 8306070123	50-440 50-305 50-456 50-321 50 321	9 А F I	GUYMON, R H GHYMN, T P HAABS, W P HACKNEY, C A GUYMON, R H	6306160631* 6306230359* 6306150400* 6306010107* 6306140636*	50-155 P 50-356 Q 50-445 p 50-313 Q 50-382 Q
ORAVES,R H ORAVES,R H ORAVES,R H ORAY,J,R GREEN,A M	8306270347 8306270301 8306270361 8306130408 8306010020	50-213 50-213 50-213 50-289 50-327	8 8 8	GUCHA,L T GUCHA,L T GUCHA,L T GUCHA,L T	8304070125 8304070127 8304070224 8304100132 8304140075	50-366 50-321 50-321 50-366 50 321	0 P P P	HAFER.D I HAFNER,B HADAN.T F HAGAN.T F HAGER.C	8306140737* 8306030039 8306020329* 8306020336* 8306020398	SO-289 (fdia contract contract 50-219 8
OREEN.H J OREEN.H J OREEN.H J OREEN.H J	8304010014 8304010149 8304010237 8304010394 8304070039	50-328 50-328 50-260 50-327 50-327	8 8 8 8	GUCWA,L T GUCWA,L T GUCWA,L T GUCWA,L T GUCWA,L T	83061\$0228 8306160267 8306160397 8306170202 8306290303#	50-346 50-346 50-321 50-321	Р Р Р Б	HAGRMAN, D L HAIRSTON, W O HAIRSTON, W G HAIRSTON, W G HAIRSTON, W G	8304080229 8304100270 8304140117 8304140327 8304200220#	RLS 50-340 B 50-364 R 50-340 R 50-340 S
OREEN, H J OREEN, H J OREEN, H J OREEN, H J	8306070084 8306070087 8306070092 8306070079 830607021 8	50-260 50-259 50-259 50-260 50-328	9 8 8 8	GUDAS, J. P OUELLER, J GUILD, R GUILD, R GUILD, R	8304040410 8304020240* 8304150383 8304150385 8304150385	NUMEQ 50-27P 50-413 50-413 50-413	F 0 0	HAIRSTON, W C	8304200227* 8304200233* 8304200334 8304270232* 8304270347*	50-348 8 50-348 8 50-348 8 50-348 8
OREEN.H.J OREEN.H.J OREEN.H.J OREEN.H.J OREEN.H.J	8306070241 8306070266 8306070284 8306070157 8306100173	50-259 50-296 50-327 50-259 50-328	5 8 8 8	QUIMOND.P J QUINN.F K QUINN.F K QUINN.F K QUINN.F K	830&210024* 830&030283 830&080381 830&1&0&58 830&290572	50-29 70-143 70-143 70-143 70-143	P	HAIST.D P HAIST.D P HALE.C J HALE.C J HALE.C J	8306280409* 8306280409* 8306130224* 8306130410* 8306210251	50 508 8 50-508 9 9A777 9A779 MISC
OREEN, H J GREEN, H J GREEN, H J GREEN, H J	8306100192 8306130163 8306130242 8306170423 8306200167	50-294 50-294 50-328 50-296 50-327	5 5 5 5 5	GUINN, PR GUINN, PR GUINN, PR GULDEMOND, W GULDEMOND, W	8007140084* 8304030455* 8304040055* 8304270222* 8304300141*	FD1A FD1A FD1A 50-373 50-373	9	HALL, B L HALL, B L HALL, D L HALL, D L HALL, D P	8306010333* 8306270436* 8306200280* 8306200282* 8306070287	50-34B 0 70-1151 FOIA FOIA 50 441 8
OREEN, H. J. OREEN, H. J. OREEN, H. J. OREEN, H. J.	070203032 0700124068 070124068 0710124068 0710124068	50-327 50-328 50-328 50-260 TOPREP	8 8 8	OUMBLE, F W QUMBLE, F W QUNDERSEN, O QUNDY, M L QUNTER, A D	8306010346 8306020430 8306170024 8306070452 8306230169*	50-286 70-1549 NUREQ	6 5 P	HALL.D.P HALL.D.P HALL.D.P HALL.D.P HALL.D.P	8306070338 8306070376 8306100060 8306100141 8304170370	50 -461 8 50 -461 K 50 -461 5 50 -461 6
OREEN.H J GREEN.H J GREEN.H J GREEN.H J GREEN,H,J	8304210218 8304210224 8304210270 8304210270 8304270070	50-327 50-260 50-259 50-328 50-260	8 8 8	GUSTAVE OUSTAVE,R P GUSTAVE,R P GUSTAVE,R P OUSTAVE,R P	8306170259* 8305040713* 8306010077* 8306020513* 8306030256*	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT		HALL.DP Mall.DP Mall.DP Mall.NM Mallen	0306170383 0306270117 0306270334 0306200134# 0306210392#	50-461 8 50-461 9 50-461 9 CONTRACT 50-389 F
GREEN, H. J GREEN, H. J GREEN, H. J OREEN, H. J	8304270250 8304270274 8304270327 8304270371 8304280192	50-296 50-260 50-296	8 8 8 8 8	GUSTAVE,R P GUSTAVE,R P GUSTAVE,R P GUSTAVE,R P GUSTAVE,R P	8306070465# 8306080427# 8306090452# 8306090470# 8306090488#	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT		HAMADA, G HAMADA, G H HAMADA, G H MAMADA, G H HAMEL, M A	8306280310# 8306070011# 8306070339# 8306280507# 8306240391	50-528 0 50-344 0 50-206 0 50-377 0
GREEN, H. J OREEN, H. J OREEN, H. J OREEN, H. J	8306300066 8306300139 8306300181 8306300208	50-259 50-259 50-260 50-259	9 9 8 9	GUSTAVE,R P GUSTAVE,R P GUSTAVE,R P GUSTAVE,R P GUSTAVE,R P	8306150570#	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT		HAMILTON, M HAND HANNETT, B A HANNETT, B A HANNETT, B A	9305200284* 8305150666* 83051808080 9305180837 9305180425	FOIA 50-389 F XPORTLIC XPORTLIC XPORTLIC
OREEN H J. OREENBERG, E, V OREENBERG, E, V. OREENBLATT, D OREENBLATT, D	8304220144 8304220144 8304070225	50-537 50-537 50-400	5 0 0 0 0	QUBTAVE.R P GUSTAVE.R P GUSTAVE.R P GUSTAVE.R P GUSTAVE.R P	8306210344# 8306210371# 8306210375#	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT		HANNUM.H H Hansen,W A Hansing.K J Hardordye.T W Harding.M R	8304270544 8304080224* 8304230039* 8304140234 8304010014	50-201 P 50-445 0 50-370 A 40-2259 50-326 S

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	BUBJECT	AUTHOR	ACCESSION	BUBJEC CATCOD
HARDING, M R	8304010020 8304010149 8304010396 8304070039 8306070218	50-327 S 50-328 S 50-327 S 50-327 S 50-328 9	HARVEY, P W HARVEY, S HARWARD, J & HASSE, R A HASSE, R A	8304210313 8304130372* 8304230141* 8304100147* 8306230279*	FOIA 50-329 A FOIA 50-483 G 50-246 G	HIATT, S L HIATT, S L HIATT, S L HICKEY, E E HICKEY, M	8306270017# 8306270536 8306270547# 8306140636# 8306080174	50-440 50-440 50-440 50-392 50-322
HARDING, M R HARDING, M R HARDING, M R HARDING, M R HARDING, M R	8304070284 8304100173 8304130242 8304200147 8304200332	50-327 8 50-328 9 50-328 8 50-327 5 50-327 6	HASSELL,D F HASSELL,D F HAUGHEY,M HAUGHEY,M F HAUS,A	8306010349 8306170396 8306090205 8306240367 8306060309*	50-P47 0 50-P47 0 50-410 A 50-350 A 70-25	HIETALA, J J HIGGINBOTHAM, L HIGGINBOTHAM, L HIGGINBOTHAM, L	8304040204 8304140344* 8304030432 8304230144* 8304240385	50-373 50-341 WABTE M 70-8 WABTE M
HARDING, M R HARDING, M R HARDING, M R HARDING, M R HARDING, M H	8304210090 8304210104 8304210218 8304210290 8304270250	50-326 S 50-328 S 50-327 S 50-328 S 50-327 S	HAVIAN.E HAVIAN.E HAWKINS.E F HAWKINS.F C	8306150314 8306150314 8306030210 8306140283 8306100169*	50-275 0 50-275 0 WASTE MOT WASTE MOT 50-403 0	HILL.B HIGOINS.J C HIGOINS.J C HIGOINS.J C	9306240388 8306070076* 8306130391* 8306080301 8306060122*	WASTE MO 50-022 50-022 FOIA 50-498
HARDING,M R HARDY, B L HARDY, R W HARMON, D W HARRAN, G	8306280192 8306200171 8306130331* 8306060354 8306020084	50-927 5 40-8084 50-920 F XPORTLIC 50-245 R	HAWKINB, FC HAWKINB, FC HAWKINB, FC HAWKINB, FC HAWLEY, SC	8304130273* 8304230277* 8304230423* 8304300063* 8304160010*	50-315 0 50-266 0 50-374 0 50-346 0 50-142 T	HILLMAN,R E HILLMAN,R E HILTUNEN,E HIND,J A	8306060252 8306090235 8306270110 8306230438 8306100210	50-219 50-219 50-205 50-295 50-341
HARRAN, G HARRELL, E W HARRELL, E W HARRELL, E W HARRELL, E W	8304140388 8304070173 8304070249 8304070274 8304070281	50-245 R 50-338 9 50-339 8 50-339 9 50-338 8	HAWLEY, 6 C HAYES, B B HAYES, D W HAYES, D W HAYES, D W	B304140010* B304040422 B306170364* B306220076* B306300184*	50-142 T 50-350 G 50-454 G 50-461 G 50-454 G	HIND.J A HIND.J A HIND.J A HIND.J A HIND.J A	8306130294 8306130298 8306130363 8306130431 8306130447	50-275 50-244 50-331 50-244 50-244
HARRELL,E W HARRELL,E W HARRELL,E W HARRELL,E W HARRELL,E W	8304070137 8304070158 8304070314 8304070318 8304200114	50-338 8 50-338 8 50-339 8 50-338 8 50-339 8	HAYNES, J G HAYNES, J G HAYNES, J C HAYNES, R C HAYNES, R C	830 6070029 830 6100111 830 6230211 830 6210354 830 6220181	50 -361 0 50-206 0 50-361 0 NUREG 50-277 0	HIND: J A HINMLE: L B HINMLE: L B HINMLE: L B	8306230477* 8306300184* 8306010277 8306280352 8306170405	50-403 50-454 50-318 50-318 50-247
HARRELL,E W HARRELL,E W HARRELL,E W HARRELL,E W HARRELL,E W	8306200209 8306200232 8306270104 8306270142 8306270163	50-339 8 50-338 8 50-338 8 50-339 8 50-339 8	HAYNEB,R C HEAD,J & HEATH,R C HEATHERLY,T L HEATHERLY,T L	8306220191* 8306010389 8306210297 8306140434* 8306140580*	50-27/ 0 50-128 R FOIA 50-390 Q 50-390 Q	Hinrichs, o Hinrichs, o Hinrichs, o Hinrichs, o Hinrichs, o	8306170044 8306170189 8306170197 8306170200 8306170271	50-247 50-247 50-247 50-247 50-247
HARRELL,E W HARRELL,E W HARRELL,E W HARRELL,E W HARRELL,E W	8306270316 8306270366 8306270430 8306280568 8306300020	50-339 8 50-338 8 50-338 9 50-338 5 50-338 5	HEBNER, M T HEHL, C W HEIDEL, C M HEIDER, L H	8306160137* 8306140423* 8306140563* 8306010174* 8306010165*	FD1A 50-324 0 50-416 0 50-341 8 50-27 0	HINRICHB.G HINZE.W J HIPSHER.W M HIRSCH.D HIRSCH.D	8306170410 8306080168 8306210435 8306150362 8306150392	50~247 NUREQ 27~48 50~142 50~142
HARRINGTON, Q W HARRINGTON, Q W HARRINGTON, R M HARRINGTON, R M HARRINGTON, W D	8306070308# 8306070312# 8306280080 8306280093 8305240436	0A979 0A999 DO-259 P NUREO 50-293 P	HEIDER, L H HEIDER, L H HEIDER, L H HEIDER, L H HEIDER, L H	8304010244 8304010379 8304010435 8304020139 8304020337	50-271 P 50-271 P 50-271 P 50-27 R 50-29 R	HIRSCH, D HIRSCH, D HIRSCH, D HIRSCH, D HIRSCH, D	8306170373 8306170379* 8306170390* 8306170417* 8306170426*	50-142 50-142 50-142 50-142 50-142
HARRINGTON, W D	8306010060 8306010157 8306010275 8306010322 8306010334	50-293 8 50-293 9 50-293 8 50-293 9 50-293 P	HEIDER, L H HEIDER, L H HEIDER, L H HEIDER, L H HEIDER, L H	B306070302 B306070303 B306150161 B3061603B2 B306200365*	50-27 Q 50-271 P 50-271 P 50-29 R 50-29 Q	HOCHENDONER, L. HODAS, D. R. HODODON, A. P. HODODON, A. P. HODODON, A. P.	8306160600 8306060010 8306140676 8306140718 8306140722	50-287 50-354 50-352 50-352 50-352
HARRINGTON, W D	8306010386 8306010373 8306020154 8306020417 8306020456	50-293 8 50-293 8 50-293 R 50-293 8 50-293 8	HEIDER, L H HEITNER, K L HELD, J T HELGESON, K A	8306200367* 8306210304 8306240357 8306270413* 8306130450	50-27 0 50-309 P 50-309 P 50-245 P 70-820	HODODON, A. P HODOE, 8 A HOFFMAN, D. P HOFFMAN, D. P HOFMANN, P	8306280586 8306280080 8306060095 8306160566 8306080306*	50-352 50-257 50-155 50-155 50-410
HARRINGTON, W D	8306070045 8306070167 8306070348 8306140613 8306140662*	50-293 P 50-293 P 50-293 P 50-293 P 50-293 0	HELTEMEB.C J HELTEMEB.C J HELTEMEB.C J HELGEBON.K A	8306270577 8306300021* 8305020555* 8306020478* 8306070461	70 -820 50 -255 & PR NUREO 50 -272 &	HOFMANN, P. HOFMANN, P HOGAN, J. P HOLDEN HOLDEN	8304080328* 8304080351* 8304090450 8304140154 8304140474	50-410 50-410 ADVCM 50-271 50-271
HARRINGTON, W D	8304150011 8304210184 8304210204 8304220003 8304240172	50-273 P 50-273 B 50-273 B 50-273 P 50-273 P	HELTEMES, C. J. HENDRICKS, M. HENDRICKSON, R. HENGELI, B. HENNICK, A.	8306280056* 8306150461* 8306100275 8306070189* 8306240050	PR 50-320 H 50-116 G MIBC NUREG	HOLDEN, C HOLDEN, C F HOLDEN, C F, HOLDER, E T HOLDER, E T	8306020037 8306140006# 8306200181# 8306070092 8306270274	50-440 50-271 50-271 50-259 50-296
DE CALIBRAH DE WOOTONIBRAH DE WOOTONIBRAH DE WOOTONIBRAH RESIDEN DE CALIBRAH DE CALIBRAH DE CALIBRAH	8306280379 8306280331 8306280358 8306270328* 8306270371*	50-293 8 50-293 P 50-293 B 50-390 0 50-416 0	HENRY, A HENRY, L. G HERBERT, R J HERBERT, R J HERBERT, R J	8306080194 8306170052* 8306010434 8306010434 8306020397	50-32P H 50-57 0 50-245 8 50-245 8 50-245 8	HDLBER.E T HOLLAND.P. HOLLAND.R A HOLLEY.W L HOLLEY.W L	8304270327 8304070234 8304040376* 8304010107* 8304080221*	50-249 50-249 FOIA 50-313 50-445
HARRIBON: F HARRIBON: F HARRIBON: J HARRIBON: J HARRIBON: J	8304140214 8304150044 8304270181 8304040189 8304040245#	50-324 R 50-272 P 50-329 B 50-329 A 50-329 G	HERBERTIR J HERINGIR.F HERNANIR HERNANIR W HERNANIR W	8304020397 8304270312 8304150282 8304030191 8304070449	50-245 S 80-315 P 50-302 P 50-329 A 50-329 A	HOLMEB.K R HOLMES-RAY.P HOLT.J HOLT.J. HOLT.J.	0306140675* 8306270273* 8306070421 8306070398 8306070350	M180 50-321 50-247 50-247
HARRISON.J J HARRISON.J J HARRISON.J J HARB.B HARBHAW.F	830 6270336 830 6270337 830 6270367 830 6060307* 830 6020032*	50-327 A 50-327 A 50-327 A 70-25 70-2953	HERNAN,R W HERNANDEZ,G H HERR,J C HERR,P,B. HERR,PB	8306070454 8306270350* 8306200314* 8306030363* 8306030363*	50-329 A 50-275 G 50-244 P 50-443 Q 00-443 Q	HOLT, J HOLTZ, J. L HOLTZ, J. L. HOLZMER, M HOOD, A. C	8305230345 8306020218 8306160476 8305230330 8305230028*	50-247 50-334 50-334 50-155 50-373
HART, Q HARTMANN, P. L HARTZMAN, R. M HARTZMAN, R. M HARTZMAN, R. M	8306160131* 8306060221* 8308160024 8306200324 8306200324	FDIA 50-295 Q 50-247 Q 50-247 Q 50-247 Q	HERRINGTON, W N HERRON, M M HERBOH, M M HIATT, B, L HIATT, B, L	8306140636* 8306230072* 8306070012 8306060381 8306270014	50-3BR Q FOIA XPORTLIG 50-440 A 50-440 C	HOOD, D HOOD, D. HOPCRAFT, C. P. HOPCRAFT, C. P HOPKINS, H. R.	8306070425 8306170477 8306060374 8306210305 8306030266*	50-329 50-329 71-210 71-9163 C'

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	EUBJI-0		AUTHOR	ACCESSION NUMBER	BUILUI CATEGO	
B C.SNIXAOH B C.SNIXAOH B C.SNIXAOH B C.SNIXAOH B C.SNIXAOH	8306020661 8306160279 8306160725 8306200019 8306220177	50-375 P 50-375 P 50-369 P 50-400 A 50-445 A	HUSEBY, D E HUTCHINS, G H HUANG, H IDEKER, R L IGNATONIS, A	8304210246 8304240331 8304020048 8304270588 8304100174	* COMMISS RES 71-6257		JOHNSON, C E JOHNSON, C R JOHNSON, G E JOHNSON, G E JOHNSON, G E	8304210070± 6304240457 8304040072 8304070041 8304070305	50-389 71-9016 50-413 50-415 50-415	0 0
B L, BRIJACH B L, BRIJACH A B. BIDROH A W. KI SOH	8304240351 8304290573 8304270177 8304170387 8304080243*	50~395 P 50~369 P 40~8584 50~352 H 50~445 G	IMEL, G R IPPOLITO, T A IRBY, B J IRVING, S M IRVIN, H R	9304070452 9304070343 8304300208 8304320117 9304020448	NUREC 10PREP 50-259 50-458 71-5796	s e	70HN2ON'F H 70HN2ON'G E 70HN2ON'G E 70HN2ON'G E	630714008 8304210294 8304210084 830420084 8304200224 830420229	50-413 50-413 50-413 50-293 50-440	0 0 0
HORIN.W A HORIN.W A HORIN.W A HORSCHEL, D S HOSEY, C M	630 4080243* 830 4150364 830 4150364 830 4020080 830 40357*	50-445 0 50-445 0 50-445 0 NUREG 70-1113	IRWIN, R ISHII. M ISRAEL, B H JABBOUR, K N JACKIW, I	83061601371 8306280085 83062403581 83062104271 8306160264	NUREQ CONTRAC	T P St	JDHNSON, L. H JGHNBON, R. E JOHNBON, R. M JOHNBON, R. T JOHNBON, R. U	8306270220* 8306210362 8306160506* 8306270151 8306170291*	50-440 NUREG 50-445 NUREG COLA	G G
HOUSTON, D HOUSTON, J C HOUSTON, R W HOUSTON, J B	B304140477* B30422025B B304140015 B304220044 B30424012G*	50-34B Q 50-416 P FQIA 50-373 B FQIA	JACKEON B M JACKIU I N JACKIU I N	8306230330 8306220050* 8306270341* 8306270389* 8306210326*	50~305 50~409	9 0 0	JOHNBON, T C JOHNBON, T L JOHNBON, V M JOHNBON, W JOHNBON, W D	8306140189 8306020334* 8306300202 8306080238* 8306010107*	00000000000000000000000000000000000000	
HOME, P. H HOME, P. H HOME, P. H HOME, P. H HOME, P. H	830 61 405 47 830 62 401 45 830 62 402 46 830 62 804 87 830 62 805 24	50-324 G 50-325 P 50-324 P 50-325 G 50-324 P	JACKBON, L H JACKBON, K C JACKBON, K C	8304030053 8304240438 8304030431 8304030442 8304140512#	71-9056 71-9006 WASTE MO WASTE MO 50-400	97 97 G	DOHNBON, W D JOHNBON, W D JOHNBON, W D JOHNBON, W D	8304080211* 8304090354* 8304140197* 8304140220* 8304140234*	50-205 50-205 50-407 50-482 50-72	0 0 0 0
HOYLE, J C HOYLE, A HOYLE, J C HOHE, P. W	830 6270402 830 6030048 830 6220244 830 6080092 830 6080096	50-324 0 CONTRACT CONTRACT ADVCM ADVCM	JACKBON, L H JACKBON, P D JACKBON, R L JACKBON, T J	8306270233* 8306070337 8306240373 8306080078 8306280484*	NASTE ME NUREQ 70-020	G G	ON TRANSCOLUCE THE TOWNSHIPS THE T	8306140247# 8306140363# 8306010448 8306010448 8306280452#	50 -482 50-313 50-443 50-443 50-528	9 A A Q
HOYLE, J C HOYLE, J C HOYT, H F HOYT, H F	8304080101 8304140517* 8304140734* 8304080144 8304080174	ADVCM ADVCM ADVCM 50-443 G 50-443 G	JACOB, N JACOBI, H JACOBSON, R JACOBSON, R JACOX, J H	8306280190 8306300219 8306270239* 8306270239* 8306080077	NUREQ PR 40-8410 40-8610 NISC		JOHNSTON, M M JONES, E E JONES, K C JONES, R A	8304200295 8304070247 8304140214 8304020385 8304020385	50-341 50-10 50-10 71-302 50-445	۸ ۲ ۷
HOYT, H F HOYT, H F HOYT, H F HUBBARD, G T HUBBARD, R B	830 6080 186 830 622007 9 830 627024 9 830 6210286 * 830 6220052 *	50-443 0 50-443 0 50-443 0 0A979 90-275 0	JAFFE.D H JAMIBON.J D JANO.J C JANO.J C JANXOWSKI,M W	83061 60083* 83061 40636* 83061 50413* 8306020407* 8306070471	50-317 50-382 50-155 50-317 Nureg	ម ឧ ឧ	JONEB, V JONEB, V JONEB, W C JONEB, W C JONEB, W C	* 03040201613 030404020 030404020 030404020 030404020 030404020	50 280 50 280 50-285 50-285 50-285	9 4 5 6
HUDSPETH, J B HUDSPETH, J B HUDSPETH, J B	830 6060227* 830 6090208* 830 6160032* 830 6210365* 830 6160169	50-220 0 50-348 F 50-348 F 50-348 F 50-373 S	JANUBKA: A G JAPE: F JAPE: F JAPE: F JAPE: F	8304270174# 8306140191# 8306140196# 8306140362# 8306140400#	50-135 50-397 50-335 50-370 50-290	0 0 0 0	JONES, W C JONES, W C JONES, W C JONES, W C	8304090032* 8304130130* 8304130240 8304130344	50-285 50-285 50-285	0 0 1
HUFFMAN, ON HUFFMAN, ON HIGHES, R JHUCKILL, H	8306140310* 8306140541* 8306030338 8306030339* 8306010404	50-335 0 50-335 0 TOPREP TOPREP 50-219 P	JAPE, F JAPE, F JAPE, F JAPE, F JAPE, F	830&140537* 830&170023* 830&270212* 830&270225* 830&270404*	50-369 50-454 50-250 50-389 50-413	0 0 0 0 0	JONES, W C JONES, W C JONES, W C JONES, W C	8306160354# 8306200350 8306210360# 8306210360# 8306280233	50 285 50-285 50-285 50-285 50-285	F R F P
HUKILL.H D HUKILL.H D HUKILL.H D HUKILL.H D HUKILL.H D	8305040487 8304010353 8304010407 8304040181 8304100120	50-289 P 50-289 S 50-289 R 50-289 P 50-289 F	JAPE, F JAPE, F JARRETT, R D JENKINS, G R JENKINS, G R	8306270511# 8306270517# 830607045£# 8306140244# 8306140310#	50 -390 50-369 71-91 <i>H2</i> 50-416 50-335	9 9 9	JONES, W C JONES, W C JONES, W C JORDAN, E D JORDAN, E L	8304280444 8304280487 830430049 8304280351# 8305110460	50-205 50-205 50-205 50-205 50-77 50-3	0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0
HUKILLIH D HUKILLIH D HUKILLIH D HUKILLIH D	8304140014 8304140480 8304140584 8304140623 8304140732	50-289 P 50-289 P 50-289 P 50-289 P 50-289 F	JENKINS. G R JENKINS. G R JENKINS. G R	8306140541# 8306140542# 8306140635# 8306270426# 8306020454	50-327 50-349	0 0 0	JORDAN, E L JORDAN, E L JORDAN, E L JORDAN, E L JORDAN, E L	0005110461 0305110464 0305110470 0305110475 0305110477	50 -3 50 -3 50 -3 50 -3 50 -3	" 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0
HUKILL, H D HUKILL, H D HUKILL, H D HUKILL, H D HUKILL, H D HUKILL, H D	8304170256 8304200127 8304200246 8304210247 8304270231	50-289 P 50-289 S 50-289 P 50-289 S 50-289 P	JENNINOB, F JENNINOB, R JENEEN, D JESTER, N JOHANSEN, E	8306010361# 8306170031 8306140681 8306070452 8306030293	50-317 ADVCM NUREQ	e S	JORDAN, E. L. JORDAN, E. L. JORDAN, E. L. JORDAN, M. JORDAN, M. H. JORDAN, M. H.	8305110477 8305110483 9304070010 8304130327 8304280554	50 · 9 80 · 7 50 · 3 50 · 331 50 · 44b	0 0 0
HUKILL, H D HUKILL, H D HUKILL, H D HUNNICUTT, D H	8305270233* 8305280365 8305280365 8305280078 8305050122*	50-289 P 50-289 B 50-289 G 50-289 G 50-498 G	JOHNSON, A R JOHNSON, B D JOHNSON, B D JOHNSON, B D	8304210020* 8304070048 8304070234 8304070248 8304070282	50-255 50-255	0 8 8	Jordan, W S Jordan, W S Jordan, W S Jordan, W S Jordan, W S	8304010382 8304010382 8304270554 8304270554 83042705142	50~443 50~443 50~443 50~443 PR	0000
HUNNICUTT, D H	8306140249x 8306140374x 8306160317 8306160644 8306210070x	50-482 Q 50-445 Q 50-313 S 50-313 S 50-382 Q	JOHNBON B D JOHNBON B D JOHNBON B D JOHNBON B D JOHNBON B D	8304100179 8304130394 8304170355 8304220013 8304220254	50-255 (50-155 (50-255 (7 3 5 3	Jorgenben, D L Jorgenben, B L Joyner Joyner Joyner	8304300021 * 6304300024 8304040297 8304210237 8304210249	50-255 50-373 50-413 7&F 50-334	8 8
HUNT, M D HUNT, M D HUNTER, D R HUNTER, D R HUNTER, D R,	8306280202 8306160254* 8306290221* 8306060138* 8306070042*	50-320 P 50-440 Q 50-335 Q 50-358 Q	JOHNBON B D. JOHNBON B D JOHNBON D D JOHNBON D D	8306230287 8306230374 8306230413 8306270063 8306270432	50-255 F 50-255 F 50-255 F 50-255 S	, ,	JOYNER, J JOYNER, J JOYNER, J JOYNER, J JOYNER, J	8304110279 8304110289 8304230001 8306230263 8306230263	1&E 1&F 50-245 1&E 1&E	er Gr
MINTER, R. S. HARFORD, W. J. HARBT, A. HUBERY, D. E	8306230359# 8306020281 8306220273 8306100311# 8306010273	50-358	JOHNBON, B D JOHNBON, C JOHNBON, C JOHNBON, C	8304270435 8304030377 8304070018 8304280230 8304140374 #	50-255 S FOIA FOIA FOIA 50-445 C		JULIAN, C JULIAN, C JULIAN, C JULIAN, C A JULIAN, C	8306140687* 8306140647* 8306070191 8306230248 8306290379*	50-280 50-338 50-339 50-339 50-335	0 0 0 0

AUTHOR	VCCEBB 10N	EUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEODRY
JUNGE, M A	8304010273	50-318 8	KEIBER, H W	8306020401	50-387 S	KERR, O W	B306030390*	FOIA
JUNGE, M A	8304010307	50-317 5	KEIBER, H W	8306070246	50-387 S	KERR, O W	B306030395*	FOIA
JUNGE, M A	8304170420	50-318 8	KEIBER, H W	8306170015	50-387 S	KERR, O W	B306150374	NUREO
JUNGE, M A	8304210159	50-318 9	KEIBER, H W	8306170191*	50-387 F	KETTEVER, J W	B306160560*	50-267
JUNGE, M A	83042804462	50-318 8	KEIBER, H W	8306170217	50-387 S	KEY, W J	B306030213*	50-374
KACICH, R M	8304130233	REVIEW GRP	KEISER, H W	8306170413	50-387 8	KHATIB-RAHBAR	8304020072	NUREO
KACICH, R M	8304130233	REVIEW GRP	KEISER, H W	8306210050	50-387 9	KIBLER, D R	8304040207	50-331 (
KADAMBI, N P	8304200017	50-400 A	KEISER, H W	8306210212	50-387 9	KIBLER, D R	8304270270	50-331 (
KADAMBI, N P	8304270012	50-400 A	KEISER, H W	8306280140	50-387 9	KIEL, O R	8304020457*	XPORTLIC
KAHLE, J D	8304270380*	50-302 Q	KEISER, H W	8306280348	50-387 9	KIEL, O R	8304030051	XPORTLIC
KAKU, M	8306170379*	50~142 T	KEISER, H W	8306280399	50-387 8	KIEL, O R	8304030040*	XPORTLIC
KAKU, M	8306170390*	50~142 T	KEISER, H W	8306280434	50-387 8	KIEL, O R	8304140288	XPORTLIC
KAKU, M	8306170417*	50~142 T	KEISER, H W	8306280510	50-387 8	KIESER, H H	8304170037	50-387 1
KAKU, M	8306170426*	50~142 T	KEISER, H W	8306280518	50-387 8	KILCOYNE, J J	8304200438	50-289 (
KACIVIANAKIS, N	8306130329	50~254 S	KEISER, H W	8306280548	50-387 8	KILLOUGH, O O	8304210350	NUREO
KALIVIANAKIS, N KALIVIANAKIS, N KALIVIANAKIS, N KALIVIANAKIS, N	8306130337 8306170314 8306170344 8306270252 8306300043	50~254 S 50~254 R 50~265 S 50~254 S 50~254 S	KELLER, OR KELLER, RM KELLEY, DL KELLEY, JL KELLEY, J. L	8304080148 8304020042 8304130241* 8304010439 8304070393	NUREQ 50-334 V 50-445 G 50-400 C 50-400 C	King, W Kinneman Kinneman, J Kinneman, J Kinneman, J	0305270390 0305210237 0306020392* 0306060172* 0306060177*	50-322 6 1&E 70-698 40-672 40-672
KALMAN, K L KALMAN, K L KALMON, K KALUZNY, B P KAMMER, D B	8304030200 8304220287 8304270302 8304140491 8304140041	WASTE MOT WASTE MOT 50-272 S NUREQ 50-260 O	KELLEY, J. L KELLEY, J. L KELLEY, H D KELLY, B	8306160612 8306220059 8306220070 8306210031* 8306080174	50-413 0 50-413 0 50-400 0 0A979 50-322 H	KINNEMAN, J KINNEMAN, J KINNEMAN, J, KINNEMAN, J, D KINNEMAN, J, D	8304040179* 8304140249 8304280203 8304010243 8304150143*	40-672 I &E I &E 40-86 70-2669
KAMMER, D 8	8306140266#	50~259 0	KELLY,E	8304040248#	50-322 0	KINNEY, W W	9304140246*	50-193 (
KAMMER, D 8	8306140420#	50~370 0	KELLY,JA	8304140342#	50-298 0	KINNEY, W W	8304200353*	50-77 (
KAMMER, D 8	8306150094#	90~327 F	KELLY,L	8304240148#	50-274 0	KINSTON, P B	9304200247*	50-397 (
KAMMER, D 8	8306210010	50~259 F	KELLY,L	8304140385	50-286 R	KIRK, W F	9304030502	70-37)
KAMMER, D 8	8306210217	50~390 E	KELLY,WJ	8304020214	50-275 R	KIRK, W F	9304080022	71-5641
KAMMER, D 8	8306290203*	50~259 G	KELLY, H J KELLY, H J KELLY, H J KELLY, H J	8304100067	50-275 8	KIRKLAND, H H	8306020234	70-754
KAMMERER, C	8306140521*	ADVCM		8304100082	50-275 8	KIRKPATRICK, D	8306240063	NUREQ
KAMMERER, C	8306160125*	FOIA		8304140535	50-275 R	KIRSCH, D F,	8306070098*	50-275
KAMMEYER, D J	8306020119	50-344 R		8304210044	50-275 S	KIRSCH, D F	8306070244*	50-206
KAMMEYER, D J	8306160392	50-344 R		8304210078	50-275 B	KIRSCH, D F	8306070255*	50-206
D D AAAAA B R GAAAA G QAAAA B G ABAAA A B ABAAAA	8306020683 8306280387 8306280226* 8306010327 8306020096	RES 50-179 H 50-309 P 50-320 B 50-320 P	KETTA'M Y KETTA'M Y KETTA'M Y KETTA'M Y	8306210164 8306230365 8306230422 8306280421 8306280523	50-275 B 50-275 B 50-275 B 50-275 B 50-275 B	Kirbch, D F Kirbch, D F. Kirbch, D F Kirbch, D F Kirbch, D F	8304070241* 8304070348* 8304230398 8304270344* 8304270350*	50-204 (50-341 (50-341 1 50-275 (50-275 (
KANGA.B K KANGA.B K KANGA.B K KANGA.B K	8306130137 8306170025 8306170282 8306200357 8306220035	50-320 G 50-320 B 50-320 P 50-320 P 50-320 P	KELLY, W J KELMERB, A D KEMPER, J B KEMPER, J S	8304280524 8304280073 8304030348 8304140310 8304230274	50-275 8 NUREO MISC 50-352 A 50-352 A	Kirbch, d f Kirbch, d f, Kirbch, d f Kirbch, d f Kirbch, d f,	8306280017 8306280194* 8306280480* 8306280511* 8306280551*	50-275 50-275 50-204 50-361
Kanga, B K Kappel, B Karagianib, J A Karman, M Karman, M	8304220054 8304280184 8304270282 8304140007 8304300138	50-320 P F01A 50-10 S 50-261 0 50-462 G	KEMPER, J 8 KEMPER, J 8 KENDALL, J M KENNEDY, D M	8306270315 8306280381 8306280417 8306210024* 8306130310	50-352 E 50-352 E 50-352 B 50-29 P 50-255 R	Kirech, D f Kirslis. 8 s Kish. J n. Kibs, E Kister	8306280561* 8306150262* 8306230423* 8306210153* 8306140476	50-341 50-443 50-374 TOPREP 50-271
KARR.J W	8306270478	50-329 0	KENT, E E KENNEY, E B KENNEY, E B	9304070452	NUREQ	KIBTER	8304170332	50-271
KARR.J W	8306270478	50-329 0		9304140470	50-286 6	Kibter, H.	8304070052*	50-28&
KARR.J W	8306270530	50-329 0		9304070052*	50-286 0	Kibter, H	8304140080	50-333
KASE.K R	8306280170	NUREO		9304040307*	70-25	Kibter, H. B	8304010378*	50-247
KABSNER.T F	8306280076	NUREO		9304140292*	FOIA	Kibter, H. B	8304020074	50-244
KATADKA,I KAY,J A KAY,J A KAY,J A	8304280085 8304220045 8304140039 8304140047 8304140047	NUREG 50-275 0 50-361 8 50-29 0 50-29 P	KENYON, B D KENYON, B D KENYON, B D KENYON, B D	8306200152 8306010153* 8306010177* 8306010218 8306020223	50-344 R 70-371 50-387 G 50-387 B 50-387 R	KISTER, H B KISTER, H B KISTER, H B KISTER, H B, KISTER, H B	830&0A0227* 830&0&0237* 830&1&0372* 830&230199* 830&230322*	50-220 50-333 50-244 50-244 50-244
KAY,JA	8306210017	50~27 P	KENYON, B D	8306020444#	50~387	KLAPPROTH, J F	8304080105	TOPREP
KEARNEY,JJ	8306070380*	50~307 P	KENYON, B D	8306070214		KLEINSOROE, W P	8304140349*	50-335
KEARNEY,JJ	8306060227	PR	KENYON, B D	8306140482		KLEINSORGE, W P	8304290357*	50-250
KEARNEY,JJ	8306300223	PR	KENYON, B D	8306160472		KLIMBERO, B B	8304220123	50-410
KEATING.DE	8306230271*	50~440 @	KENYON, B D,	8306170188		KLIMBERO, B R	8304150422	50-338
KEATINO, D E	8306230359#	50~358 0	KENYON, B D	8306210143	50-387 f	KLINO.C.L	9306070159*	50-317
KEATINO, L A	8306150615#	50~322 F	KENYON, B D,	8306270248	50-387 R	KLUOLEIN.J	9306080194	50-322
KEIMIO	8306140154	50~271 8	KENYON, T J	8306020604	50-390 A	KHETYK.L.N.	9306280049	NAREQ
KEIMIO, R	8306140080	50~333 8	KEPPLER, J Q	8306060127	50-358 G	KNAPIK.H	9306280193	FOIA
KEIMIO, R	8306150008#	50~289 0	KEPPLER, J Q	8306060132*	50-358 G	KNEZOYICH.J P	8306150064	50-272
KEIMIG,R R	B306060220*	50-219 0	KEPPLER.J Q	· 9306070033	50-350 0	Kniceley, J. R	9304210075*	50-269
KEIMIG,R R	B306070151*	50-352 0	KEPPLER.J Q	8306070074	50-407 0	Knieber, G. W	9304140554*	GAPPP
KEISER,H	B306070026*	50-367 F	KEPPLER.J Q	8306070125	50-295 0	Knieber, G. W	9304140579*	GAPPP
KEISER,H W	B306010061	50-367 S	KEPPLER.J Q	8306210006	50-546 0	Knight, N. L	9304080245	FOIA
KEISER,H W	B30601006B	50-367 S	KEPPLER.J Q	8306210177	50-263 0	Knighton, D. W	9304020013	50-412
KEISER, H W	8306010070	50-387 B	MEPPLER, J Q	8306220025	50-255 F	xnighton, o h	8306020024	50-498
KEISER, H W	8306010097	50-387 S	KEPPLER, J, Q	8306220028	50-254 Q	knighton, g h	8306020056	50-528
KEISER, H W	8306010150	50-387 S	KEPPLER, J, Q	8306230056*	50-373 Q	knighton, g, h	8306020687	50-382
KEISER, H W	8306010278	50-387 S	KEPPLER, J Q	8306230476	50-483 Q	knighton, g h	8306030062	50-341
KEISER, H W	8306010309	50-387 S	KEPPLER, J Q	8306270293	50-254 Q	knighton, g, h	8306080064	50-400
KEIBER, H W	8306010313	50~387 9	KEPPLER, J Q	8306270298*	50-254 0	KNIGHTON, G W	8306140784	50-335
KEIBER, H W	8306010323	50~387 8	KEPPLER, J Q	8306270311	50-461 0	KNIGHTON, G W	8306150149	50-412
KEIBER, H W	8306020369	50~387 5	KEPPLER, J Q	8306300213	50-315 0	KNIGHTON, G W	8306150150*	50-412
KEIBER, H W	8306020382	50~387 8	KERR, Q W	8306020035	State Prog	KNIGHTON, G, W	8306160011	50-206
KEIBER, H W	8306020394	50~387 8	KERR, Q W	8306020496	State Prog	KNIGHTON, G, W	8306160272	50-400

AUTHGR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATFGORY	AUTHOR	ACCESSION NUMBER	EDEUDECT CATEGORY
H 9 NOTHOINN	8304140430 8304140457 8304170079 8304220291 8304220294	50-387 P 50-400 A 50-508 E 50-206 F 50-206 F	KRUG, H E KRUZ1C, R W KUBINAK, R A KUCIYNSKI, L A KUCIYNSKI, L A	8306270225* 8306160637 8306060231 8306010150 8306010278	50-387 0 71-9141 PR 50-387 S 50-387 S	FEE'Y FEE'Y FEBDICK'E 8 FEBDICK'E 8	8306170296 8306170428* 8306130389 8306170385 8306210453	50-508 B 50-508 G 50-289 H 50-289 H ACRB
KNICHTON, O W KNICHTON, O W KNICHTON, O W KNICHTON, O W	8306230520 8306240463 8306240464 8306240465 8306240466	50-204 F 50-400 E 50-275 P 50-275 V 50-389 P	KUCZYNSKI, L. A KUCZYNSKI, L. A KUCZYNSKI, L. A KUCZYNSKI, L. A KUCZYNSKI, L. A	8306020223 8306020382 8306020394 8306160472 8306170217	50-387 R 50-307 S 50-387 S 50-387 R 50-387 S	LEE.J C LEE.K W LEE.O R LEC.O R	8306210453 8306240241 8306010335 8306010343 8306010344#	ACRS RES 50-267 P 50-267 P 50-267 P
KNIGHTON G H KNIGHTON G W KNIGHTON G W KNOP R C KNOP R C	8306240467 8306240468 8306240479* 8306060241 8306060242*	50-400 E 50-400 E 50-361 P 50-483 Q 50-483 Q	KUC ZYNSKI, L. A KUC ZYNSKI, L. A KUC ZYNSKI, L. A KUHELUM, W KUK IELKA, C	8306170413 8306210212 8306280348 8306060307* 8306160631*	50-387 8 50-387 8 50-387 8 70-25 50-155 P	LEE.O R LEE.O R LEE.O R LEE.S T	8306010411 8306010416* 8306280343 8306300104 8306210433	50-267 P 50-267 P 50-267 P 50-267 G XPORILIC
KNOP/R C KHOP/R C KNOP/R C KNOP/R C KNOP/R C	8306170047 8306210271 8306220066 8306270201 8306300084	50-341 Q 50-341 Q 50-461 Q 50-546 Q 50-483 Q	KULP.C J KUNIHIRO D M KUNITA, R K KUNKLE, O L KUO, H	8306140365 8306280081* 8306080083* 8306090076* 8306010086	50-412 C 50-204 G 50-324 P 50-322 G NUREG	LEECH,PH LEFAVE,WT LEFAVE,WT LEFAVE,WT LEGGETT,RW	0306020642 0306150259* 0306150262* 0306150437* 0306020122	50-336 P 50-443 Q 50-443 Q 50-443 Q NUREQ
KNOP, R. C. KNOP, R. C. KNOP, R. C. KNOP, R. C. KNOP, R. C.	8306300170 8306300178 8306300179 8306300182* 8306300184*	50-483	KUPPERMAN.D S KURTZ.S R KUZCYNSKI.L A LABAR.M P LABARGE.F	8306280096 8306270141 8306210050 8306210415* 8306220116	NUREO NUREO 50-387 8 71-6346 40-299	LEMPGEB, T E LEMPGEB, T E LEMPGEB, T E LEMPGEB, T E LEMPGEB, T E	8306010250 8306010412* 8306020074 8306030352 8306060177	50 -220 6 50 -220 6 50 -220 8 50 -220 6 50 -220 6
KNOP,R C KOEHL,K M KOESTER,G L KOESTER,G L KOESTER,G L	8306300201 6306170077 6306060191 8306070194 8306070262	50-440 Q 70-498 50-482 X 50-482 S 80-482 S	LABARGE, F LACEY, W S LACEY, W S LACEY, W S LACEY, W S	8304220118 8304110818 8304010295 8304010302 8304020324	40-299 50-334 8 50-334 8 50-334 8 50-334 8	LENAHAN, J J LENAHAN, J J LENAHAN, J J LENAHAN, J J	0306140180* 0306140474* 0306140520* 0306140692* 0306140323*	50-389 0 50-414 0 50-389 0 50-259 0 50-322 II
KOESTER, O L KOESTER, O L KOESTER, O L KOESTER, O L KOESTER, O L	8304080175 8304080188* 8304090231 8304130043 8304130138	50-482 A 50-482 Q 50-482 S 50-482 S 50-482 S	LACEY,W S LACEY,W S LACEY,W S LACEY,W S LACEY,W S	8306020383 8306020440 8306170030 8306200382 8306280139	50-334 8 50-334 5 50-334 8 50-334 8 50-334 8	LENTINE,F G LENTINE,F G LENTINE,F G LEONARD,M LERMAN,D H	8306210073 8306230217 8306290327 8306080194 8306160305	50-295 IF 50-295 P 50-295 O 50-322 IF 50-322 O
KDESTER, Q L KOESTER, Q L KOESTER, Q L KOESTER, Q L KOESTER, Q L	8306130393 8306140230 8306150487* 8306160415 8306160539	50-482	LAFLAMME'S J LAGIEWSKI.J B LAGIEWSKI.J S LAGIEWSKI.J S	8306170186 8306010277 8306010299 8306010300 8306200118	50-309 8 50-317 8 50-318 8 50-317 9 50-318 8	LESKYS.A C LESSOR.L C LESSY.R P LESSY.R P LESSY.R P	8304230059* 8306020140 8306080093 8306080080 8306090294	CONTRACT 50-270 R 50-449 0 50-449 0 50-209 0
KDEBTER: 0 L KDESTER: 0 L KDESTER: 0 L KDESTER: 0 L KDESTER: 0 L	8306160565 8306170386 8306270088 8306270352 8306280335	50-482	LAGIENSKI, J S LAGIENSKI, J S LAHEY, R T LAINAS, G C	8306200208 8306210108 8306210246 8306270473 8306220300	50-317 S 50-317 S 50-318 S NUREG TOPREP	LEGBY,R P LEGBY,R P LESBY,R P LETBCHE,K J	8306150238 8306150256 8306200173 8306270306 8306280601	0-443 0 50-443 0 50-443 0 50-322 0
KOESTER, G L KOHN, R KOHN, R KOHN, R KOHN, R	8304300100 8304170379* 8304170390* 8304170417* 8304170426*	REGGD 50-142 T 50-142 T 50-142 T 50-142 T	LAMASTRA, M A LAND, R J LANDAU, M LANDGRAF, L C LANDGRAF, L C	8010070140* 8306010387 8306150574 8306010168 8306010168	FOIA 50-128 R NUREO 50-341 K 50-341 K	LETSCHE, K J LETSCHE, K J LETSCHE, K J LEUTSCH, R LEVENTHAL, P	6306280601 8306300094 8306300094 8306130372* 8306060034	50-322 0 50-327 0 50-324 A FOIA
KOLACZKONSKI,A KOLE, L E KOLE, L E KOLTAY, P KOLTAY, P.	8306010052 8306280504 8306300049 8306010378* 8306230212*	NUREQ 50-395 5 50-395 5 50-247 Q 50-247 Q	LANDSMAN,R LANG,O E LANGE,G LANKSBURY,R D. LANPHER,L C	8306270181 8306070210* 8306210122* 8306100175* 8306060292	50-329 9 50-413 E 50-409 P 50-373 Q 50-322 0	LEVENTHAL,P LEVI,R LEVI,R P LEVI,R P LEVI,R P	8306160143* 8306140327 8306080337 8306140227 8306140270	FOIA ADVCH ADVCM ADVCM ADVCM
KONKLIN, JE KONKLIN, JE KONKLIN, JE KONKLIN, JE	8306060244* 8306170055* 8306210278* 8306270205* 8306300183*	50~483	LANPHER, L C LANPHER, L C LANPHER, L C LANPHER, L C LARIZZA, O F	8304040292 8304220134 8304220134 8304230337 8304210034	50-322 0 50-322 0 50-322 0 50-312 0 50-244 8	LEVI,R P LEVI,R P LEVI,R P LEVI,R P, LEVI,R P	8306140507 8306140726 8306140756 8306170310 8306220234	ADVCM ADVCM ADVCM ADVCM 50-45E F
KONKLIN, JE KONKLIN, JE KONZEK, OJ KOSLA, BM KOTTAN, JJ	8306300186* 8306300207* 8306020131 8306140767 8306020407*	50-483 Q 50-440 Q NUREQ 40-8027 50-317 Q	LARSEN, J LARSEN, J LARSON, C E LARSON, C E LARSON, C E	8304080303* 8304080343* 8305040453 8304170134 8304170232	50~410 A 50~410 A 50~263 0 50~263 0 50~282 0	LEVIN.H A LEVINE.J M LEVINE.J M LEVINEN,E D	8304270067 8304150034* 8304200060* 8304270192 8304240012*	50-029 R 50-313 F 50-313 F 50-348 B 50-324 P
KOTTAN.J J. Kramer, e n. Kramish.a Kratzer, m b Kraus, o	B304230397* B304140043* B304140041 B304140134* B304080203	50-293	LABGELLE,K E LATHAM,K L LAUFER-COVITZ LAUGHLIN,G J LAUGHLIN,G J	8306270399 8306130398 8306130398 8306010039 8306010067	50-322	LEWIS, DR LEWIS, DR LEWIS, FW LEWIS, MI LEWIS, MI	8306220077 8306220085 8306060225* 8306020380 8306220043	50-443 0 50-443 0 50-392 1 50-352 H 50-359 0
KRAUS, C. KRAUS, T KRAUS, T. KRAUSE, D.F. KRECHTING, J.E	9304080205* 9304080215 9304080250 9304270141 9304100148	50-358	LAUGHLIN, Q J LAURENSON, J A LAURENSON, J A. LAWTON, H D LAZARSKI, R F	8305010071 8305150292 8305150300 8305200285* 8305280211*	NURE9 50~322 0 50~322 0 40~8084 50~320 P	LEWIB.M I LEWIB.R C LEWIB.R C LEWIB.R C LEWIB.R C	8306300150 8306070317 8306070327 8306140045 8306140107	PR 50-348 Q 50-348 G 50-375 Q 50-259 F
KRECHTING, JE KRICH, R. M KRIEGER, RW KRIEGER, RW KRIEGER, RW	9304170350 9304220027 9304010142 9304220004 9304240203	50-275 R 50-255 8 50-206 F 50-204 P 50-204 P	LAZARUB, W J LAZO, L LAZO, R M LAZO, R M LAZO, R M	8306010027 8306020491 8306030034 8306160622 8306160627	50-410 A 50-412 A 50-412 A 50-529 9 50-529 6	LEWIB.R C LEWIB.R C. LEWIB.R C LEWIB.R C LEWIB.R C	8306140137 8306140145* 8306140159 8306140201* 8306140251	50~327 0 50~327 Q 50~424 A 50~324 0 50~259 0
MRIEGER, R W KRIMM, R W KRIMM, R W KRONZEK, A L KRUG, H E	8304280444 8304240308 8304270305 8304070441 8304140191*	50-206 P 50-344 F 50-322 F FOIA 50-389 Q	LE, H LEAGE, R S LEODICK, R S LEODICK, R S LEODICK, R S	8306130332* 8306020186 8306010376 8306170184 8306170222*	50~322 E 50~314 R 50~508 0 50~508 A 50~508 Q	LEWIS,R C, LEWIS,R C LEWIS,R C LEWIS,R C LEWIS,R C	8306140272 8306140276* 8306140303 8306140382 8306140397	50-389 0 50-259 0 50-414 8 50-395 0 50-261 0

AUTHOR	ACCESSION NUMBER	SUBJECT CATEODRY	AUTHOR	ACCESSION NUMBER	SUBJECT	AUTHOR	ACCESSION NUMBER	BUBJECT CATEGORY
LEWIS, R C LEWIS, R C LEWIS, R C LEWIS, R C LEWIS, R C	8306140415 6306140422 8306140425* 8306140452 6306140461*	50-390 Q 50-259 Q 50-390 Q 50-395 Q 50-395 Q	LINDER, F LINDHOLM, U S LINDHOLM, U S LINDHAN, J J LINDHAN, J J	8306270382 8306300006 8306270003* 8306020328* 8306020477	50-409 0 50-409 S 50-237 P 40-8681 40-8786	LYNCH, M D LYNCH, M D LYNDE, H V LYONS, J E LYDNS, P J	8304010321 8304080435 8304170334 8304270324 8304020178	50-341 F 50-341 A NUREQ 50-29 P 40-299
LEWIS,R C LEWIS,R C LEWIS,R C LEWIS,R C LEWIS,R C	8306140495# 8306140503* 8306140514* 8306140543 8306140556	50-400 Q 50-400 Q 50-387 Q 50-259 Q 50-200 Q	ribinaki'd s Findre'n m Findre'n m Findre'n m	8306210431 8306210091 8306270275 8306040237* 8306060171*	40-8084 50-266 P 50-266 P 50-333 G 50-245 O	LYONB,P J LYONB,P J LYONB,W T MACBRYDE,M B MACBRYDE,M B	830 6020201* 830 6070467 830 6010270 830 6070109* 830 6070110*	40-299 40-299 50-318 B GA999 GA999
LEWIS.R C LEWIS.R C LEWIS.R C LEWIS.R C LEWIS.R C	8304140559 8304140541 8304140569* 8304140418 8304140433	50-416	LIPINSKI.D R LIGENO.R T LITTELL.R LITTELL.R LITTLE.B H	8304070241* 8304010112 8304100004 8304130501 8304170055*	50-245 0 50-333 5 ADVCM ADVCM 50-341 0	MACDONALD, C E	8306020040 8306020498 8306020493 8306020528 8306020626	71-9111 71-5364 71-4909 71-9080 71-6574
LEWIS,R C LEWIS,R C LEWIS,R C LEWIS,R C LEWIS,R C	8306140634 8306140637 8306140650 8306140666 8306140698	50-416	LITTLE, W S LITTLE, W S LITTLE, W S LITTLE, W S LITTLE, W S	8306030137 8306030142 8306030144* 8306030146 8306030147	50-254 0 50-461 0 50-461 0 50-546 0 50-440 0	MACDONALD, C E	B306020635 B306020711 B306030022 B306030027* B306030041	71-9080 71-9152 71-6142 71-6142 71-9029
LEWIS.R C LEWIS.R C LEWIS.R C LEWIS.R C LEWIS.R C	8306140711 8306140717* 8306140721 8306210194 8306210213*	50-321	LITTLE, W S LITTLE, W B LITTLE, W S LITTLE, W B LITTLE, W B	8306030180 8306030198 8306030209 8306070175 8306100101	50-483	MACDONALD.C E MACDONALD.C E MACDONALD.C E MACDONALD.C E MACDONALD.C E	8304030087 8304030090* 8304030492* 8304080334* 8304080334*	71-6003 71-6003 71-9165 71-9017 71-9017
LEWIS.R C LEWIS.R C LEWIS.R C LEWIS.R C LEWIS.R C	B306290195 B306270198 B306290213* B306290218 B306290254	50-259	LITTLE, W S LITTLE, W S LITTLE, W S LITTLE, W S LITTLE, W S	8306100263 8306130277 8306130341 8306130343* 8306160242	50-374 Q 50-440 Q 50-454 Q 50-454 Q 50-440 Q	MACDONALD, C E	8304080337* 8304080382 8304080408 8304080411* 8304070001	71-9017 71-9070 71-9016 71-9016 71-9111
LEWIS,R C LEWIB,R C LEWIB,R C LEWIB,R C LEWIB,R C	8304290272 8304290277 8304290278* 8304290288* 8304290298	50-259	LITTLE, W S LITTLE, W S LITTLE, W S LITTLE, W S LITTLE, W S	8306160247* 8306230253 8306230267 8306230411 8306230431	50-440 Q 50-346 Q 50-440 Q 50-409 Q 50-155 Q	MACDONALD, C E	8306070002* 8306070004 8306070006* 8306070014 8306070017*	71-9111 71-6601 71-6601 71-5026 71-5026
LEWIS.R C LEWIS.R C LEWIS.R C LEWIS.R C LEWIS.R C	8306290312* 8306290341 8306290383 8306290490* 8306290531*	50-321 0 50-250 0 50-338 0 50-257 0 50-261 0	LITTLE, W 8 LITTLE, W 8 LITTLE, W 8 LITTLE, W 8 LITTLE, W 8	8306270283 8306300022 8306300053 8306300061* 8306300126	50-440 Q 50-346 Q 50-341 Q 50-341 Q 50-440 Q	MACDONALD, C E	8306090034 8306090037* 8306090070 8306090074* 8306090278	71-9010 71-9010 71-6244 71-6244 71-9015
LEWIB, 5 H LIANG, C LIANG, C LICHTENDERGER LICITRA, E A	8306270438 8306150262* 8306150431* 8306070336* 8306020627	50-329 A 50-443 G 80-443 G GA777 50-526 A	LITTLE, W B LITTLE, W S LITTLE, W S LITTLE, W S LITTON, R J	8304300212 8304300235 8304300238* 8304300251 8304010264	50-35B	MACDONALD, C E MACDONALD, C E MACDONALD, C E MACDONALD, C E, MACDONALD, C E	8304090279# 8304130177 8304140744 8304140750# 8304140787	71-9015 71-9089 71-4553 71-4553 71-4003
LICITRA,E A LICITRA,E A LICITRA,E A LICITRA,E A LIDEN,E A,	8304080097 8304200051 8304200053 8304240458 8304020232	50-528 A 50-528 A 50-528 A 50-528 A 50-272 F	LIU,W C LIVERMORE,H H LOCHBAUM,D LODGE,T J LODGE,T J	8306140139* 8306220076* 8306270090 8306030288 8306220080	50-43B	MACDONALD, C E	8306140790 8306150143 8306150239 8306150240# 8306150326	71-5641 71-9151 71-9017 71-9017 71-9508
LIDEN,E A LIDEN,E A LIDEN,E A LIDEN,E A LIDEN,E A	8306070150 8306070164 8306070047 8306140036 8306140043	50-272 F 50-272 F 50-272 F 50-272 V 50-272 H	LOOTUDICE, J M LOHAUS, P H LOKKEN, R O LONG, J LONGENECKER, J	8304210371* 8304140185 8304140402 8304040137 8304040203	CONTRACT WASTE HGT NUREO 50-346 S 50-837 A	MACDONALD, C E	8306170447 8306170455 8306170456* 8306170458 8306170464	71-5641 71-9110 71-9110 71-9111 71-9056
LIDEN.E A LIDEN.E A LIDEN.E A LIDEN.E A LIDEN.E A	8304140057 8304150247 8304150270* 8304140438 8304200240	50-272 P 50-272 R 50-272 R 50-272 P 50-272 R	TONE'S & TONGENECKER'D TONGENECKER'D TONGENECKER'D	8306200325 8306220048 8306240233 8306170018 8306030147*	50-537 E 50-537 A 50-537 A 50-317 R 50-461 0	MACDONALD, C E MACDONALD, C E MACDONALD, C E, MACDONALD, C E MACDONALD, C E	8304170465 8304210445 8304210447 8304220172 8304220178*	71-6550 71-5796 71-6346 71-498 71-498
LIDEN, E A LIDEN, E A LIDEN, E A LIDEN, E A LIDIAK, E Q	8304210174 8304270299 8304290313 8304300190 8304080148	50-272	LOVE.R S LOVELL,R M LOVENDALE,P C LUCIA,B	8304030202* 8304130345* 8304020405* 8304100227* 8304070276*	50-546 @ 50-454 @ 70-2548 50-155 @ 50-528 F	MACDONALD, C E MACDONALD, C E MACDONALD, C E MACDONALD, C E MACDONALD, C E,	8306220184 8306220185 8306220170* 8306220175 8306220179	71-5626 71-9174 71-5626 71-4909 71-9165
LIEBERMAN, J LIN, G C LINDBLAD, W J LINDELL, M K LINDEMER, T. D	9306240264 9306210153* 9306200210* 9306140315 9306280093	M18C TOPREP 80-344 I NUREO NUREO	FORMIG'M C FORMIG'M C FORMIG'M C FORMIG'M C	8304200302 8306270317 8304070039 8306070218 8306070284	50-537	MACDONALD, C. E MACDONALD, C. E MACDONALD, C. E MACDONALD, C. E MACDONALD, C. E.	8306220203 8306220231 8306240455 8306240456 8306240457	71-210 71-367 71-9132 71-9141 71-9100
LINDER, F LINDER, F LINDER, F LINDER, F LINDER, F	8306020291 8306070040 8306070079 8306070311 8306070332	50-409 R 50-409 B 50-409 P 50-409 F 50-409 G	LUDWIG, W.C LUDWIG, W.C LUEBKE, E.A. LUJANAG, P.L LUKZ, F.J	6306200332 6306210216 6306160616 6306300097* 6306010129*	50-327 8 50-327 8 50-142 0 50-289 0 CONTRACT	MACDONALD, C.E. MACDONALD, C.E. MACDONALD, C.E. MACDONALD, C.E. MACDONALD, C.E.	8306240485 8306240488 8306240489* 8306270601 8306270610	71-9132 71-86 71-86 71-9080 71-5607
LINDER, F LINDER, F LINDER, F LINDER, F LINDER, F	8306100184 8306190314* 8306140707 8306150277 8306160279*	50-409 P 50-409 0 50-409 P 50-409 P 50-409 F	LUKZ,F J LUKZ,F J LUNDVALL,A E LUNDVALL,A E LUNDVALL,A E	8306170482* 8306230505* 8306060105 8306070156 8306130001	CONTRACT CONTRACT 50-317 P 50-317 P 50-317 Q	MACDOUGALL, E MACDOUGALL, R D, MACLEAN, R MACLEOD, B, MACNABB, W V	8306170205* 8306240036* 8306230471* 8306280258	RES FOIA CONTRACT 50-322 H XPORTLIC
LINDER, F LINDER, F LINDER, F LINDER, F LINDER, F	8306160378 8306170376 8306210066 8306210132 8306270337	50-407 R 50-407 B 50-407 P 50-407 P 80-407 B	LUNDVALLIA E LUNDVALLIA E LUONIAIC K LURIAIN LUTKINIM H	8306160330* 8306210121 8306160048* 8306130331* 8306080350	50-317	MADDEN, W MADDEN, W. MADIBON, A MADIBON, A MADBEN, O. L.	9306230001 8306280582 8306270222* 8306300141* 8306010132	50-245 8 50-387 8 50-373 0 50-373 0 50-267 0

AUTHOR	ACCESSION NUMBER	SUBJECT	AUTHOR	ACCESSION NUMBER	BUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
MADSEN, G. L.	8304010152 8304010294 8304010350 8304040056 8304040049	50-382 G 50-128 H 50-498 G 50-498 G 50-458 G	MANNO.S F MANNO.S F MANSER.W C MARCHAL.J MARCHAL.J	830 421 0200 830 4280 405 830 41 50249* 830 41 50340 830 41 40 420	50-410 Q 50-410 S 70-143 XPDRTLIC XPORTLIC	MARTIN,R E MARTIN,R W MARTIN,T MARTIN,T MARTIN,T MARTIN,T T	8306240418 8306150617 8306060309* 8306280590* 8306280510	50~352 F NUREQ 70~25 50~354 Q 40~6940
MADSEN, O L	8306060111	50-498 G	MARCHAL, J	830&1&071&	XFORTLIC	MARTIN,T T	8304010094	50 -27 0
MADSEN, O L	8306060125	50-267 G	MARCHAL, J	830&1&0720	XFORTLIC	MARTIN,T T	8304010115	50 247 0
MADSEN, O L	8306060128	50-112 G	MARKEE, E	830&1&40&3&*	50-382 Q	MARTIN,T T	8304010148	70-371
MADSEN, O L	8306060139	50-267 P	MARKEY, E J	830&0&0392*	50-272 U	MARTIN,T T	8304010140	50 -27 0
MADSEN, O L	8306070317	50-267 P	MARKT, D	830&090291*	50-29 F	MARTIN,T T	8304010171	50-307 0
MADSEN, G L	9304080042	50-267	MARKT, D	8304150293*	50-271 F	MARTIN, T F	8304010227	50-333 Q
MADSEN, G L	8304080069		MARKT, D	8304150297*	50-271 F	MARTIN, T T	8304010301	50-271 Q
MADSEN, G L	8304080078		MARSHALL, C	8304160024	F0IA	MARTIN, T F	8304010303	50-213 Q
MADSEN, G L	8304080128		MARSHALL, J R	8304010024	50-313 P	MARTIN, T T	8304010324	50-334 Q
MADSEN, G L	8304080217		MARSHALL, J R	8304010267	50-313 P	MARTIN, T T	8304010337	50-309 P
MADBEN, O L	8306080220	50-445 Q	MARBHALL, J R	8304020081	50-313 R	MARTIN, T T	830&010338	70 487
MADBEN, O L	8306130118	50-382 Q	MARBHALL, J R	8304020135	50-313 P	MARTIN, T T	830&010402	50-220 q
MADBEN, C L	8306130255	50-445 Q	MARBHALL, J R	8304020150	50-348 R	MARTIN, T T	830&020025	70-2953
MADBEN, G L	8306140370	50-445 Q	MARBHALL, J R	8304020464	50-348 P	MARTIN, T T	830&020258	71-250
MADBEN, O L	8306140631	50-382 Q	MARBHALL, J R	8304030294	50-313 J	MARTIN, T T	830&020375	50-354 q
Madsen, Q L	8306160220	50-267 P	MARSHALL.J R	8306040067*	50-313	MARTIN, T T	8304020381	50-244 0
Madsen, Q L	8306160351	50-298 0	MARSHALL.J R	8306060253		MARTIN, T T	8304020387	70-698
Madsen, Q. L	8306170266	50-362 0	MARSHALL.J R	8306070054		MARTIN, T T	8304020399	70-2548
Madsen, Q. L	8306170346	50-362 0	MARSHALL.J R	8306070193		MARTIN, T T	8304020400	50-244 0
Madsen, Q L	8306210009	50-298 0	MARSHALL.J R	8306070298		MARTIN, T T	8304020402	50-317 0
MADSEN, O L	9304210061	50-382	MARSHALLIJ R.	9304070384*	50-313 G	MARTIN,T T	8304020408	70-1224
MADSEN, O L	9304210109		MARSHALLIJ R.	9304080012	50-313 F	MARTIN,T T	8304020407	50-277 q
MADSEN, O L	9304210114		MARSHALLIJ R.	9304070248	50-313 F	MARTIN,T T	8304020427	50-244 q
MADSEN, O L	9304240140		MARSHALLIJ R.	9304070313	50-313 P	MARTIN,T T	8304020442	50-307 q
MADSEN, O. L	9304270236		MARSHALLIJ R	9304130057	50-313 R	MARTIN,T T	8304020445	50-219 q
MADSEN, G L	9306300130	50~247 G	MARSHALL, J R	8306130222	50-313	MARTIN,T T	8306020458	50-241 0
MAIER, J. E	9306020079	50~244 P	MARSHALL, J, R	8306130270		MARTIN,T T	8306030238	70-371
MAIER, J E.	9306020449	PR	MARSHALL, J R	8306130421		MARTIN,T T	8306030314	70-371
MAIER, J E	9306020451	50~244 R	MARSHALL, J, R	8306140050		MARTIN,T T	8306030343	50-286 0
MAIER, J E	9306020453	50~244 R	MARSHALL, J R	8306140158		MARTIN,T T	8306060162	50-277 0
MAIER, J E	8305050036	50-244	MARSHALL, J R	8306160324	50-313 P	MARTIN.T T	8304040147	40-672
MAIER, J E	830506057		MARSHALL, J R	8306160355	50-368 S	MARTIN.T T	8304040244	50-286 g
MAIER, J E.	8305070258		MARSHALL, J R	8306160469	50-313 S	MARTIN.T T	8304070140	50-317 g
MAIER, J E	8305140025		MARSHALL, J R	8306160474	50-368 R	MARTIN.T T	8304070030	71-2
MAIER, J E	8306140410		MARSHALL, J, R	8306160479	50-368 S	MARTIN.T T	8304070128	50-322 g
MAIER, J E	8306140595	50-244 P	MARSHALL, J R	B306160493	50-313 P	MARTIN, T T	9306140258	50-277 0
MAIER, J E	8306150307	50-244 Q	HARSHALL, J R	B306160499	50-368 S		9306150156	70~2669
MAIER, J E	8306170032	50-244 P	MARSHALL, J R	B306160537	50-313 G		9306160313	70-1207
MAIER, J E	8306170201	50-244 S	MARSHALL, J R	B306160561	50-313 R		9306160323	50-317 0
MAIER, J E	8306200314	50-244 P	MARSHALL, J R	B306160577	50-368 B		9306160341	50-220 0
MAIER, J E	8306210015	50-244 0	MARSHALL, J. R.	B306160614	50-313 S	MARTIN.T T MARTIN.T T MARTIN.T T MARTIN.T T MARTIN.T T MARTIN.T T	8306160440	50-272 Q
MAIER, J E	8306210034	50-244 B	MARSHALL, J. R	B306170275	50-313 P		8306170050	50-57 Q
MAIER, J E	8306220022	50-244 G	MARSHALL, J. R	B30617040B	50-313 P		8306170204	50-219 F
MAIER, J E	8306240177	50-244 P	MARSHALL, J. R	B306210003	50-313 B		8306170241	70-371
MAIER, J E	8306240278	50-244 P	MARSHALL, J. R	B306210125	50-313 R		8306200082	50-423 Q
MAIER, JE HAIER, JE MAIER, JE MAIER, JE MAIYA, PB MALARDIE, PJ	8306240311	50-244 P	MARSHALL.J R	8304210181	50-348 8	MARTIN,T T	8306200125	50-277 0
	8306270257	50-244 P	MARSHALL.J R	8304210229	50-349 P	MARTIN,T T	8306200135	50-307 0
	8306270360	50-244 P	MARSHALL.J R	8304230424	50-313 V	MARTIN,T T	8306200157	50-277 0
	8306280076	NUREG	MARSHALL.J R	8304230474	50-313 F	MARTIN,T T	8306200307	50-245 0
	8306230074*	FOIA	MARSHALL.J R	8304230487	50-348 P	MARTIN,T T	8306200387	50-213 0
MALETESKOB, C J	8304280190	NUREQ	MARSHALL, J R	83064100133	50-313 G	MARTIN,T T	8304210098	50-213 Q
MALLAY, J F	8304140451	REGOD	MARSHALL, J S	8306070162	50-445 A	MARTIN,T T	8304210104	50-322 Q
MALLORY, C W	8304020533*	71-9080	MARSHALL, J S	8306100153	50-445 A	MARTIN,T T	8304230215	50-336 Q
MALLORY, C. H.	8304030185*	71-9089	MARSHALL, J S	8306130173	50-445 A	MARTIN,T T	8304230383	50-317 Q
MALMROS, M H	8304070017*	50-344 Q	MARSHALL, J S	8306160503	50-445 Q	MARTIN,T T	8304230389	50-273 Q
MALODY, C W	8304130500*	70-1257	MARSHALL, R K	8306240073	NUREQ	MARTIN,T T	8306230456	50~333 0
MALODY, C W	8306240376	70-1257	MARSHALL, H H	8306080206	50-329 0	MARTIN,T T	8306230457*	50~333 0
MANGINI, E A.	8306280157*	CONTRACT	MARSTON, R R	8306140542*	50-327 0	MARTIN,T T	8306230471	50~272 0
MANDIL, I H	8306020482*	CONTRACT	MARSTON, R R	8306140655*	50-348 0	MARTIN,T T	8306230473	71~2
MANDLER, J. W	8306080161	50-339 P	MARTIN, C.	8306080320	FGIA	MARTIN,T T	8306270238	40~8610
MANGAN, C. V. MANGAN, C. V. MANGAN, C. V. MANGAN, C. V MANGAN, C. V	8304010063 8304010340 8304070034 8304080273 8304100143	50-220 P 50-220 F 50-220 P 50-410 A 50-220 P	HARTIN, D E HARTIN, D E MARTIN, D.E HARTIN, D E HARTIN, D E	8304020252 8304030430 8304030470 8304140333 8304140334	WASTE MOT WASTE MOT WASTE MOT WASTE MOT WASTE MOT	MARTIN,T T MARTIN,T,T MARTIN,T T, MARTIN,T T MARTIN,T T	8304280204 8304280357 8304280429 8304280441 8304280472	50-210 0 50-290 0 70-1402 50-917 0 50-271 0
MANOAN, C. V, MANOAN, C. V, MANOAN, C. V MANOAN, C. V MANOAN, C. V	8306140440 8306140445* 8306200214 8306200258 8306220076	50-410 A 50-410 0 50-220 R 50-410 K 50-410 K	MARTIN, D E	8304140351 8304140344 8304150233 8304170444 8304210423	WASTE MOT WASTE MOT WASTE MOT WASTE MOT WASTE MOT WASTE MOT	MARTON, E. J MARTON, J MARTZ, H F MABON, C C. MABON, J M	8304230077* 8304230070* 8304280013 8304020197 8304130453	FOIA FOIA NUREG 50-32/ R 50-358 G
Hangan, C. V. Hangan, C. V Hangan, C. V Hann, J. Hanning, H. J	8306280422 8306280509 8306300241 8306010107# 8306240328	50-220 G 50-220 F 50-220 F 50-313 G COMMISSION	MARTIN, DE MARTIN, JB MARTIN, JB MARTIN, JB MARTIN, JB MARTIN, RA	8304280078 8304020344 8304100075 8304200378 8304070422	WASTE MOT State Prog 50-263 0 50-361 0 RES	MASSARO, B A HASSEY, F. K. MASTERSON, V V MATAKAS, R A MATCHETT, D L	8304270131 8304220127 8304130352 8304080249* 8304080338*	NUREQ 50-361 0 50-373 8 50-443 0 50-410 A
MANNO, B, F. MANNO, B, F. MANNO, B, F. MANNO, B F. MANNO, B F	8304010453 8304140558* 8304140544* 8304240242 8304210175	50-410 8 50-410 9 50-410 0 50-410 8 50-410 9	MARTIN,R E MARTIN,R.E MARTIN,R E MARTIN,R E. MARTIN,R E	8306020647 8306030086 8306090196 8306210418 8306240412	50-352 A 50-352 A 50-352 A 50-352 A	MATERB.B R. MATHEWS, J MATHIS, J. MATHIS, J. L MATLOCK, R. G	8304140414 8304150307 8304290511* 8304140342* 8304170215	50-341 A 50-445 0 50-370 0 50-370 0 50-397 8

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	BUBJECT CATEGORY
MATTHEWS D B	8306080216*	SO-361 G	MCFADDEN, J H	8306240263*	TOPREP	MCMURRAY, C M	8306150401*	50-322 0
MATTHEWS M L	8306150229	WASTE MGT	MCFARLAND, C R	8306140512*	50-400 G	MCMURRAY, C M	8306290533	50-322 0
MATTHEWS M L	8306200012	WASTE MGT	MCGARRY, J M	8306060301	50-413 Q	MCNAMARA, A E	8306020274	50-244 R
MATTHEWS M L	8306240179	WASTE MGT	MCGARRY, J M	8306060301	50-413 Q	MCNAMARA, A E	8306160485	50-244 R
MATTHEWS T P	9306200358	50-285 R	MCGARRY, J M	8306080170	50-413 Q	MCNAUGHTON, W P	8306080048*	50-440 A
MATTIA.M J	B304190510*	CONTRACT	MCGARRY, J M	8306080170	50-413 0	MCNEILL,C A MCNEILL,C A MCNEILL,C A MCNEILL,C A MCNEILL,C A	8306010112	50-333 B
MATTIA.M J	B306170029*	CONTRACT	MCGARRY, J M	8306100199*	50-413 0		8306010312	50-333 B
MATTIA.M J	B306220091*	CONTRACT	MCGARRY, J M	8306100199*	50-413 0		8306100017	50-333 R
MATTIA.M J	B306270446*	CONTRACT	MCGARRY, J M	6306170334	NUREO		8306140153*	50-333 G
MATTIA.M J	B3062B0122*	CONTRACT	MCGAUGHY, J P	8306010244	50-414 9		8306140169*	50-333 G
MAURA, FA MAURA, FA MAURIN, LV MAURIN, LV MAURIN, LV	830&0&0138* 830&3000&7* 830&010223 830&010227 830&070411*	50-35B	P C. YHDUADOM T L. YHDUADOM T L. YHDUADOM T L. YHDUADOM T L. YHDUADOM	8304010241 8304020284 8304070004 8304070089 8304070142	50-416 S 50-416 P 50-416 S 50-416 S 50-416 S	MCNEILL,C A MCNEILL,C A MCNEILL,C A MCNEILL,C A MCNEILL,C A	8306200139 8306200344* 8306200378 8306210156 8306280486	50-333 B 50-333 Q 50-333 B 50-333 G 50-333 B
MAURIN, L V	8306170349#	50-382 0	4 C'AHDRADH	8304070228	50-416 8	MCNERNEY, M J	8306100152*	50-483 A
MAURIN, L V	8306280342	50-382 R	A F'AHDRADH	8304070230	50-416 9	MEDFORD, M O	8306140178	50-361 P
MAXWELL, D	0306130437	50-237 S	A F'AHDRADH	8304070237	50-416 8	MEDFORD, M O	8306160275	50-361 K
MAXWELL, D C	8306170409	50-249 S	A F'AHDRADH	8304070410	50-416 8	MEHOLICK, J J	8306070026*	FOIA
MAY, E L	8306170033	50-29 S	A F'AHDRADH	8304100219	50-416 8	MEHOLICK, J J	8306070027*	FOIA
MAY.E L HAYBERRY.G B MAYS.G T MAYS.G T MAYWEATHER.L	8306280107 8306240441* 8306160631* 8306210324 8306160487	50-29 8 71-9006 50-155 P NUREG 50-361 R	4 C'AHONPODH A C'AHBONDOH HCONDHA'T B HCONDHA'T HCONDHA'T B HCONDHA'T B HCONDHA'T	8306100235 8306100251 8306140046 8306140084 8306140259	50-416 9 50-416 9 50-416 9 50-416 9 50-416 8	MEILTON, S.L. MEITZLER, W.D. MENDELSON, I.N. MENDEZ, R. MENDEZ, R.	8306280387 8306140315 8306170466* 8306230255* 8306300252*	50-320 0 NUREO CONTRACT 50-346 0
MCALLISTER B A MCALPINE E J MCALPINE E J MCALPINE E J MCALPINE E J	8306170430 8306140589# 8306140575# 8306140582# 8306140617#	50-309 8 70-1201 70-1113 70-1113 70-824	4 F'AHDINGOW A F'AHDINGOW A F'AHDINGOW A F'AHDINGOW	8306140384 8306140454* 8306140567* 8306140611 8306140669	50-416 S 50-416 0 50-416 0 50-416 S	MENDONCA: M M MENDONCA: M M MENIN ICK, J MERCIER: A. MERCIER: A	8304270350* 8304280174* 8304020225 8304080215 8304080250	50-275 0 50-275 0 27-48 50-358 0 50-358 0
MCALPINE,E J HCALPINE,E J MCBREARTY,R A MCBREARTY,R A MCBREARTY,R A	8306140713# 8306270240 8306060227# 8306070226# 8306160006#	70-143 70-143 50-220	P C.YHQUAGOM T C.YHQUAGOM T C.YHQUAGOM T C.YHQUAGOM T C.YHQUAGOM	8304200121 8304200133 8304200142 8304200184 8304200189*	50-416 B 50-416 B 50-416 B 50-416 K 50-416 K	MERKLE, J O MERRITT, B MERRITT, B MERRIWEATHER, N MERRIWEATHER, N	8306210362 8306130346 8306270111 8306030151* 8306160254*	NUREQ 50-249 8 50-249 8 50-440 0 50-440 0
MCDRIDE,M	8306060267*	50-284 0	MCGAUGHY, J P	8306200250	50-416 B	MERRIWEATHER, N	8304300132#	50-440 Q
MCBRIDE,M H	8306020447*	50-217 0	MCGAUGHY, J P	8306270126	50-416 B	MEYER, O	8304070144#	50-317 Q
MCBRIDE,M H	8306230469*	50-333 0	MCGAUGHY, J P	8306270132	50-416 B	MEYER, J F	8304240295#	50-247 Q
MCBRIDE,M H	8306280474*	50-271 0	MCGAUGHY, J P	8306270165	50-416 B	MEYER, T A	8304170201	50-244 B
MCCABE,E C	8306010134*	50-387 0	MCGAUGHY, J P	8306270346	50-416 B	MICHAELS, A	8304040307#	70-25
MCCABE, E C	8306010324#	50-317 0	PARPURADOM	8904270439	50-416 S	MIGHT, A	8304020111*	50-315 R
MCCABE, E C	8306020071	50-322 0		8304280168	50-416 S	MIGHT, A	8304020118*	50-315 R
MCCABE, E C	8306030312#	50-277 0		8304280287	50-416 S	MIGHT, A	8304020184	50-316 R
MCCABE, E C	8306070074#	50-322 0		8304280329	50-416 S	MIGHT, A	8304140358*	50-315 R
MCCANN, J	8306010134#	50-387 0		8304280471	50-416 S	MILEB, E B	8305040457	CONTRACT
MCCLERKEY, K F MCCLINTOCK, R O MCCLINTOCK, R O MCCLUNG, C E	8304090295 8304090295 8304040019* 8304140179* 8304080195	50-322 0 50-322 0 FOIA FOIA 50-361 0	MCGAUGHY, J P MCGAUGHY, J P MCGAUGHY, J P MCGAUGHY, R W MCGAUGHY, R W	8306280555 8306300163 8306300175 8306130375 8306140590	50-416 S 50-416 B 50-416 B 50-331 S 50-331 Q	MILLER.D MILLER.D B MILLER.D E MILLER.D 8 MILLER.D S	8304040309* 8304130348 8304100258* 8304010391 8304020358	70-25 50-329 A 50-373 Q 50-309 Q 50-309 Q
MCCLUNG, C E	8304080175	50-361 0	MCOAUGHY R W	830&1 &03B9	50-331 P	MILLER, D. W	8306270253*	50-387 R
MCCOLLOM, K A	8304280554	50-445 0	MCOAUGHY R W	830&1 &04&0	REGGD	MILLER, F. Q.	8306270550	50-247 9
MCCORKLE, G W	8304100037*	50-312 0	MCOAUGHY R W	830&230348	50-331 P	MILLER, Q. E	8306210186	50-326 S
MCCRORY, B L	8304130241*	50-445 0	MCOAUGHY R W	830&270420	50-331 P	MILLER, H. J	8306140175	WASTE MOT
MCDERMOTT, D	8304080459	Contract	MCOINTY D M	830&1 \$01&5	50-186 F	MILLER, H. J	8306200415	WASTE MOT
MCDERMOTT, D	8304030277	TANTHOD CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT	MCGRATH,R A	8306040252	50-217 R	MILLER, H. J	8306240028*	F01A
MCDERMOTT, D	8304040391		MCGUIRE,D R	8306010333*	50-348 G	HILLER, H. J	8306280280	WASTE MOT
MCDERMOTT, D	8304140228		MCGUIRE,D R	8306070061*	50-250 G	HILLER, J	8306130265	1&E
MCDERMOTT, D	8304150244		MCGUIRE,D.R	8306070324*	50-348 G	HILLER, J	8306160167	50-373 B
MCDERMOTT, D	8304150445		MCGUIRE,D R	8306170162*	50-349 G	HILLER, J	8306230438	50-295 B
MCDERMOTT, D MCDERMOTT, D MCDERMOTT, D K MCDUNALD, D D MCDUNALD, D D	8306210421 8306220166 8306150506 8306160098 8306160174	CONTRACT CONTRACT CONTRACT FOIA FOIA	MCGUIRE,DR MCGUIRE,DR MCGUIRE,DR MCGURREN,HJ MCINNEB,ID	8306170307* 8306210224* 8306290436* 8306240290 8306100136*	50-269 0 50-259 0 70-1151 50-247 0 50-366 P	MILLER, J H MILLER, J R MILLER, J R MILLER, J R	8304070130* 8304040270 8304100088 8304100271 8304210072	50-321 1 50-156 0 50-155 0 50-315 0 50-263 0
MCDONALD, J Y MCDOHELL-BOYER MCDUFFIE, M A MCDUFFIE, M A MCDUFFIE, M A	8304030402* 8304080041* 8304040152 8304040202 8304070122		MCKEE, P.F. MCKEBEN, J.G. MCKINNEY, G.J. MCKINNEY, C.J.	8306170221 8306210248 8306180165 8306100142 8306100213	50-302 R 50-334 B 50-194 F 50-395 B 50-395 B	MILLER, L MILLER, L MILLER, L F MILLER, L K MILLER, L K	8306070244* 8306280480* 8306280511* 8306200132 8306200226	50-206 0 50-204 0 50-361 0 50-311 R 50-272 R
MCDUFFIE, M A MCDUFFIE, M. A MCDUFFIE, M. A MCDUFFIE, M. A MCDUFFIE, M. A	8304080032 8304100189 8304140114 8304170224 8304200083	50-400 E 50-400 E 50-400 E 50-400 E 50-400 E	MCKINNEY, C. J MCKINNEY, C. J MCKINNEY, C J MCKERRN, T	•8306140088 8306270136 8306280067 8306300196 8306020327	50-395 9 50-395 9 50-395 9 50-395 8 CONTRACT	MILLER, L K MILLER, M MILLER, M. A MILLER, M. I MILLER, M. I	8306280542 8306240366 8306140060 8306060196* 8306060196*	50-272 R 50-390 A 50-390 A 50-454 G 50-454 G
MCDUFFIE, M. A.	8304200307	50-400 E	MCLEAREN, T	8306020333	CONTRACT	HILLER, H I,	8306270041	50-454 6
	8304210002	50-400 A	MCLEAREN, T.	8306090413	CONTRACT	HILLER, M I,	8306270041	50-454 6
	8304210204	50-400 E	MCLEAREN, T.	8306090282	CONTRACT	HILLER, M I	8306270393	50-454 6
	8304270100	50-400 E	MGLEOD, N B	8306280261*	XPORTLIC	HILLER, M I,	8306270393	50-454 6
	8304270113	80-400 A	MCLOUGHLIN, D	8306280261*	50-329 F	HILLER, H B	8306070381	50-322 6
MCDUFFIE.M A MCDUFFIE.M A MCDUFFIE.M A MCDUFFIE.M A MCDUFFIE.P N	8306270217	90-400 E	MCLOUGHLIN, D	8306090118	50-155 F	MILLER, M. B.	83040703B1	50-322
	8306270241	80-400 E	MCMASTER, I B	8306070452	NUREO	MILLER, R. I,	8304030029	71-5971
	8306270292	80-400 E	MCMURRAY, C M	8306150395	50-322 0	MILLER, W. J.	8304170337	50-331
	8306270448	80-400 E	MCMURRAY, C M	8306150395	50-322 0	MILLER, W. O	8304020030	50-364
	8306240073	NUREO	MCMURRAY, C, M	8306150401*	50-322 0	MILLER, W. O	8304020492	TOPREP

AUTHOR	ACCESSION NUMBER	SUBJ	ORY	AUTHOR	ACCESS I ON NUMBER	CATEGO		AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
MILLER, W O MILLER, W O MILLER, W O MILLER, W O	8306020696# 8306090498 8306090502 8306140279 8306150516	50~36 50~36 50~26 50~33	l P 1 P 7 P 9 P	MILLE, L M MILLE, L M MILLE, L M MILLE, L M MILLE, L M	8306280415 8306280425 8306280425 8306280475 8306280567	50-438 50-390 50-438	488894	MDORE, R N MOORE, T L MORAN, D H MORAN, D H MORAN, D H	8306240061 8306060059* 8306140305 8306140792 8306140797	XPORTLIC 50~244 P GEN TEC IS CEN TEC IS GEN TEC IS
MILLER, W D MILLI CAN, M H MILLE, L MILLE, L M	8305200279 830520011 8305010113 8305010113	50-390 50-390 50-390	2 A 3 E 3 5	MILLS, L M MILLS, L M MILLS, L M MILLS, L M MILLS, L M	8304280573 8304280578 8304280412 8304280417 8304270244	50-390 50-390 50-438	8 8 8 9	MORAN, DH MORAN, DH MORAN, DH MORAN, DH MORAN, DH	8306140814 8306150019 8306150022 8306150112 8306160034	GEN TEC IS GEN TEC IS GEN TEC IS GEN TEC IS GEN TEC IS
MILLS, L M MILLS, L M MILLS, L M MILLS, L M	8306010143 8306010251 <i>83060102</i> 79 8306010274 8306010283	50-390 50-438 50-259 50-390 50-390	5 5 6 8 6 5	MILLS, L M MILLS, L M MILLS, L M MILLS, L M MILLS, L M	8306290250 8306290275 8306290283 8306290316 8306290319	* 50~259 * 50~259 * 50~390	0 0 0 0	MORAN, DH MORAN, DM MORAN, DM MORGAN, DM MORGAN, RL	8306170453 8306270032 830627050B 8306270032 8306300223	GEN TEC 18 50-454 D 50-454 G 50 454 Q PR
MILLB, L, M MILLB, L M MILLB, L M MILLB, L, M	8304010405 8304010421 8304030504 8304040102 8304070049	50-436 50-390 70-296 50-259 50-390	6 0 7 X 5	MILLS, L M MILLS, L M MILLS, L M MILLS, L M MILLS, L M	8306270388 8306270400 8306270510 8306300008 8306300013	50~259	0 0 5 8	MORGENBTERN, M HORIARTY, J MORLEY, J A MORLEY, J MORLEY, J A	8304030009 8304300110 8304080148 8304090353 8304140495	NURCO PR FR WASTE MOT WASTE MOT WASTE MOT
MILLS, L M MILLS, L M MILLS, L M	8304070044 8304070072 8304070074 8304070121 8304070132	50-390 50-390 50-390 50-438 50-327	8 8 8 F	MILLS, E M MILLS, L M MILLS, L M MILLS, L M MILLS, L M	8306300033 8306300038 8306300051 8306300054 8306300082	50-390 50-390 50-390 50-390 50-390	8888	MORLEY, J A MORLIN, E M MORRILL, P J MORRISON, O B MORRISON, O B	8306020211 8306100152* 8306070098* 8306150166* 8306150169*	WASTE Mg1 50-483 A 50-275 G 70-2669 70-2669
MILLB, L, M, MILLB, L, M, MILLB, L, M, MILLB, L M,	8304070138 8304070140 8304070188 8304080004 8304080071	50-390 50-438 50-438 50-390 50-390	<i>5</i> 6 A	MILLS, L M MICLS, L, M MILLS, L, M MILLS, L, M MILLS, L, M	8304300177 8304300205 8304300214 8304300228 8304300245	50-259 50-390 50-390 50-390 50-438	P 6 8 8	MDRRIBON, P MORRIBON, P MORTON, K MORTON, K MORTON, K V	8306150436# 8306150442# 8306020081 8306010129# 8306020463#	50-454 p 6 454-06 70-319 R 60NTACT 60NTACT
MILLS, L. M MILLS, L. M MILLS, L. M MILLS, L. M	8306080208 8306080212 8306090135 8306090142 8306090310	50-327 50-327 50-390 50-390 50-438	8	HILLS, L. M HINECK, D L HINECK, D L HINECK, D L HINECK, D L	8304300254 8304040209 8304100103 8304170337 8304200223	50-438 50-331 50-331 50-331 50-331	8 9 8 8	HORTON, K V HORTON, K V HORTON, K V HORTON, K V HORTON, K V	8306020482* 8306030284* 8306060375* 8306060377* 8306140238*	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT
MILLS, L M.	8306090322 8306090331 8306100123 8306100239 8306130340	50~390 50-259 50-438 50~390 50-438	5 Q A D A	Mineck, D L Mineck, D L Miner, S, Minock, J R Minock, J R	8304270089 8304270290 8304220204 8304270218 8304270218	50~331 50~331 50~312 50~341 50~341	0 8 9 9	MORTON, K V MORTON, K V MORTON, K V MORTON, K V MORTON, K V	0304150251# 8304150488# 8304150721# 8304140541 8304210397#	CONTRACT CONTRACT CONTRACT 50-319 R CONTRACT
HILLB, L M HILLB, L M HILLB, L M HILLS, L M HILLS, L M	8306130362 8306140125* 8306140142* 8306140150* 8306140427	50-390 50-438 50-327 50-438 50-390	A Q Q B	HIRAGLIA,F J Hiraglia,F J Hiraglia,F J Higak, A Hitchell,D H	8306210157 8306210354 8306280296 8306170314 8306200423	50-244 Nureg 50-410 50-254 40-8584	P A R	MORTON, K V MORTON, K V MORTON, K V MOBLAK, T A MOTES, B Q	8306210432* 8306230220* 8306230505* 8306040264* 8306270157	CONTRACT CONTRACT CONTRACT 50-320 0 NURFO
MILLS, L M MILLS, L M MILLS, L M MILLS, L M	8306140465 8306140466 8306140656 8306150243 8306160453	50-390 50-390 50-259 50-259 50-240	6 6 8	MITTL-R L HIZELL-S A. HIZUNG, G. G HIZUNG, Q. S HIZUNG, Q. S	8304270407 8304020011 8304080222* 8304100118 8304150403*	50-354 NURE9 50-445 50-445 80-445	K G G	MROCZKA, E J MOWRY, W R MOWRY, W R MOWRY, W R	8306020670 8306020670 8306210408 8306210415* 8306010434	70-734 XPORTLIC 71-6346 71-6346 50-245 8
MILLS, L, M MILLS, L, M HILLS, L, M MILLS, L, M MILLS, L, M	8306160507 8306160533 8306170334 8306170335 8306200141	50-259 50-390 NUREQ 50-390 50-438	P A A B	HDCHIC, D HODARRES, M HOEGGENBERG, D HOEGGENBERG, D HOEGGENBERG, D	8904040309* 8905910224 8904190270 8904140355 8904140449	50-348 50-348	P £3 \$	MRDGZKA,E J MRDGZKA,E J MRDGZKA,E J MRDGZKA,E J MRDGZKA,E J	8306010434 8306020077 8306020077 8306020084 8306020084	50-245 g 50-336 g 50-336 g 50-245 g 50-245 g
HILLB, L M HILLB, L M HILLB, L M HILLB, L M	8306200143 8306200145 8306200155 8306200169 8306210004	50-438 50-390 40-1341 50-390 50-438	6 6 8	Moeggenberg, D Hoeggenberg, D, Hoeggenberg, D Moeggenberg, D Hoeller, M P	8306160479 8306160499 8306160577 8306160614 8306010039	50-348 50-348	8 8 8	MROCZKA.E J MROCZKA.E J MROCZKA.E J MROCZKA.E J MROCZKA.E J	8304020397 8304020397 8304030319 8304030319 8304030324	50-245 8 50-245 8 50-245 8 50-245 8 50-245 8
MILLS,L M MILLS,L M MILLS,L M	8306210005 8306210014 8306210018 8306210027 8306210027	50-438 50-259 50-438 50-327 50-390	8 P 8 P	MOELLER, M P MOELLER, M P MOHR, C L MONAGHAN, J A MONAGHAN, J A	8306010067 8306010071 8306240073 8306130446 8306130446		o 0	MROCZKA-E J MROCZKA-E J MROCZKA-E J MROCZKA-E J MROCZKA-E, J	8304030324 8304140388 8304140388 8304170042 8304170042	50-245 B 50-245 R 50-245 R 50-336 S 50-336 B
HILLS, L. M.	8306210042 8306210051 8306210087 8306210088 8306210115	50-438 50-390 50-390 50-390 50-327	\$ 6 8 P	MONTANGE, C H HOONEY, J A HOONEY, J A HOONEY, J A HOONEY, J A	8306230006 8306170415 8306060192* 8306090321 8306160235	50-329 50-329	B A A	MROCZKA.C J MROCZKA.E J MROCZKA.E.J MROCZKA.E.J HROCZKA.E.J	8306170044 8306170044 8306170300 8306170300 8306270129	50-245 8 50-245 B 50-245 B 50-245 B 50-245 B
MILLS, L. M. MILLS, L. M. MILLS, L. M. MILLS, L. M. MILLS, L. M.	8304210114 8304210150 8304210180 8304210203* 8304210252	50-390 50-390 50-327 50-259 50-438	8 F G	MOONEY, J A MOONEY, J A MOONEY, J A MOONEY, J A MOONEY, J P	8306230250 8306270242 8306270349* 8306300065 8306170323	50-329 / 50-329 / 50-329 / 50-329 / 50-247 6	\ \	MROCZKA.E J MROCZKA.E J MROCZKA.E J MROCZKA.E J MROCZKA.E J	8304280231 8304280353	50-245 B 50-336 B 50-336 B 50-336 B 50-336 B
MILLE, L. M.	8304230178 8304230272 8304230444 8304270007 8304270354	50-370 50-328 50-328 50-259 50-370	F P F B	MOONEY, J, P, HOORE, D, E HOORE, D, E HOORE, D, R HOORE, J,	8306170397 8306070324* 8306210224* 8306010357* 8306240290	50-247 8 50-348 0 50-259 0 50-375 0 50-247 0		HROCZKA, E J HROCZKA, E, J HULCAHEY, E HULLIKIN, R P HUNRO, J F	8304280430 8304280430 8304200375 8304140374#	50-334 8 50-334 8 50-333 8 50-445 0 50-324 0
HILLS, L, H HILLS, L, H. MILLS, E, M. MILLS, E, M.	8304270384 8304280092 8304280178 8304280222 8304280349	50-370 50-438 50-327 50-439 50-438	8 8 8 8	Modre, J. E. Hodre, R. L. Modre, R. N Modre, R. N Modre, R. N	8306170372 8306210415* 8306020688 8306030117 8306140281	50-247 ¢ 71-6346 XPORTLIC XPORTLIC XPORTLIC		HUNRD, J F HUNRD, J J HUNRD, J, J HUNBON, L H, HURLEY, T E	8304140883# 8304030487 8304240440 8304240058	50-416 0 71-7165 71-6613 NUMEQ 50-334 0

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHÖR	ACCESSION NUMBER	SUBJECT CATEGORY
MURPHY, C E MURPHY, J MURPHY, J A MURPHY, L G MURPHY, L 0	8306210284# 8306070325 8203070638# 8306030400 8306160040	50-215 S 50-247 F FOIA CONTRACT CONTRACT	NARDOCI,P B NARDOCI,P B NARDOCI,P B NARDOCI,P B NARDOCI,P B	8306070147 8306100136 8306100164 8306100165 8306100216	50-369 S 50-370 S 50-370 S 50-370 S 50-370 S	NIX.H C NIX.H C NIX.H C	8304200004 8304200202 8304200205 8304200241 8304200374	50-346 8 50-321 8 50-346 8 50-321 8 50-321 8
MURPHY, L G MURPHY, M E MURPHY, M E MURPHY, W P MURPHY, W P	8306200286* 8306140197* 8306140236* 8306080076 8306140489	FOIA 50~407	NARDOCI,P B NARDOCI,P B NARDOCI,P B NARDOCI,P B NARDDCI,P B	8306100243 8306130316 8306130342 8306130448 8306200212	50-370 S 50-370 S 50-387 S 50-389 S 50-369 S	MIX'H C MIX'H C MIX'H C MIX'H C	8306220310* 8306220313* 8306270328 8306280361 8306280468	50-321 F 50-321 F 50-344 B 50-321 B 50-366 B
MURPHY, W P	9306170068	50~271 R	NARDDCI,P B	8306200237	50-369 S	NIXON, W A	B304040347#	40-2061
MURPHY, W P	9306210388	50~271 0	NARDDCI,P B	8306200238	50-370 S	NOBLES, L M	B306150098#	50-327 F
MURPHY, W P	9306210118	50~271 0	NARDDCI,P B	8306200245	50-369 S	NORDERHAUG, L	B306280074	50-206 G
MURPHY, W P	9306210223	50~271 0	NARDDCI,P B	8306200264	50-369 S	NORDERHAUG, L R	B306100144	50-344 G
MURPHY, W P	9306210223	50~271 F	NARDDCI,P B	8306270227	50-369 S	NORDERHAUG, L R	B306170148	50-344 F
MURPHY, W P	8304280173*	50-271 0	NARDOCI,P B	8306270301	50-369 8	NDRDERHAUG, L. R	B306170196	50-275 F
MURRAY, B	8304080044*	50-267 0	NARDOCI,P B	8306280427	50-369 8	NORDERHAUG, L. R	B306170305	50-275 F
MURRAY, B	8304080074*	50-302 0	NARDOCI,P B	8306300114	50-370 8	NORDERHAUG, L. R	B306170375	50-312 F
MURRAY, B	8304080079*	50-382 0	NARDOCI,P B	8306300189	50-370 5	NORDERHAUG, L. R	B306200379	70-734
MURRAY, B	8304080133*	50-498 0	NARDOCI,P B	8306300198*	50-369 6	NORDERHAUG, L. R	B3062003B3*	70-734
MURRAY, B	8306080211*	50-285 0	NARDDCI,F B	8306300204*	50-367 8	NORDERHAUG, L. R	8306200406	70-1257
MURRAY, B	8306080221*	50-445 0	NARDDCI,F B	8306300232	50-370 8	NORDERHAUG, L. R	8306200410*	70-1257
MURRAY, B	8306080238*	50-313 0	NARROW,L	8306210167*	50-322 9	NORDERHAUG, L. R	8306230455	50-206 F
MURRAY, B	8306090354*	50-285 0	NEAL,T P	8306240401	71-7033	NORDERHAUG, L. R	8306280131	50-344 G
MURRAY, B	8306270237*	50-278 0	NEIGHBORS,D	8306200211	50-286 P	NORDERHAUG, L. R	8306280175	50-312 G
MURRAY, J D	8304100124	50-346 B	NEILL, J M	8306010369	50-352 G	NORELIUS, C.C. NORELIUS, C.E NORELIUS, C.E NORELIUS, C.E NORELIUS, C.E	83050700B2	50-341 q
MURRAY, T	8304220240*	50-346 F	NEILS, G H	8306060084	50-263 G		8305070154	50-331 q
MURRAY, T	8304220263*	50-346 F	NEISLER, J H	8306060244*	50-483 G		8305070324	50-266 q
MURRAY, T D	8304020127	50-346 R	NEISLER, J H	8306300186*	50-483 G		8305100145	50-407 q
MURRAY, T D	8304040137	50-346 B	NEKI, M	8306150463	XPORTLIC		8305130254	50-249 P
MURRAY, T D MURRAY, T D MURRAY, T D MURRAY, T D MURRAY, T D	8306070283* 8306070375* 8306160540 8306160677* 8306170142	50-346 F 50-346 F 50-346 R 50-346 F 50-346 B	NEKI:M NELSON.G B NELSON.M A NELSON.M A	8306160684 8306200383* 8306200410* 8306150030* 8306060006*	XPORTLIC 70-734 70-1257 50-289 F FOIA	NORELIUB, C E NORELIUB, C, E NORELIUB, C E NORELIUB, C E NORELIUB, C E	8306130338 8306170020 8306170359 8306170361* 8306210037	50-237 Q 50-454 Q 50-454 Q 50-454 Q 50-305 Q
MURRAY, T D	8306170276	50-346 R	NELBON, PR	8306060007 * 8306060015 * 8306060022 * 8306270341 * 8306130379 *	FOIA	NORELIUB, C E	8306220037	50-346 G
MURRAY, T D	8306170414	50-346 S	NELBON, PR		FOIA	NORELIUB, C E	8306220041*	50-346 G
MURRAY, T D	8306170427	50-346 S	NELBON, PR		FOIA	NORELIUB, C E	8306230051*	50-373 A
MURRAY, T D	8306210084	50-346 S	NELBON, RL		50-305 G	NORELIUB, C E	8306230063*	50-373 G
MURRAY, T D	8306210262	50-346 S	NEQGY, P		50-142 T	NORELIUB, C. E	8306230260	50-266 G
MUSELER, W J MUSOLF, D MUSOLF, D MUSOLF, D MUSOLF, D	8306140358* 8306020088 8306020167 8306090230 8306090237	50-322 0 50-243 R 50-282 R 50-202 P 50-282 F	NEGGY, P NESBE, R J NEUMANN, M R NEUVILLE, C L NEUMAN, B,	8306130377* 8306249078 8306070450 8306130372* 8306140505*	50-142 T NUREQ 40-8697 50-329 A COMMIBBION	NORELIUB, C E NORELIUB, C C NORELIUB, C C NORELIUB, C E NORELIUB, C E NOREHOLM, L J	8306270066 8306270327 8306270335* 8306300044 8306160144*	50-454 Q 50-305 Q 50-305 Q 50-346 Q 50-272 Q
MUSOLF, D MUSOLF, D MUSOLF, D MUSOLF, D MUSOLF, D	8306090263 8306100059 8306130438 8306140002 8306160430	50-282 F 50-282 F 50-263 S 50-282 R 50-263 F	NEWMAN, J R NEWMAN, J R NEWMAN, J R NEWMAN, K A	8306100200 8306100200 8306200308 8306200308 8306160067	50-498 0 50-498 0 50-498 0 50-498 0 FOIA	NORRIB, E. B NORRIB, H R NORRIG, H R NORTH, H NORTH, H S	B306270003* B306140405 B306160420 B306100044* B306280145*	50-237 P 50-261 R 50-261 R 50-312 G 50-528 G
MUBOLF, D MUBOLF, D MUSOLF, D MUBOLF, D MUBOLF, D.	8306200105 8306200105 8306200108 8306200390 8306210094	50-263 P 50-263 R 50-263 F 50-282 P 50-263 F	NEYLAN, A J NEYLAN, A J NEYLAN, A J NEYLAN, A J	8306030435 8306070354 8306070359 8306220078 8306230131	REB 50-358 R 50-358 A 50-358 A 50-358 R	NORTH, H E NORTON, B NORTON, B NORTON, B NORTON, B	8306280183# 8306060275 8306060275 8306160579 8306160579	50-312 G 50-275 G 50-275 G 50-275 G 50-275 G
MUBOLF, D MUBOLF, D MUBOLF, D MUBOLF, D MUBBALLI, Y O	8306280340 8306280457 8306010347 8306010441 8306080278*	50-282 G 50-263 F 50-282 P 50-263 P 50-410 A	Nicholas, H H Nicholas, H H Nicholas, J D. Nichols, F A Nicholson, N	8304070131* 8304070151* 8304080044* 8304280074 8304210148	50-322 @ 50-352 @ 50-247 @ NUREQ 40-8631	NORTON, B NORTON, B, NORTON, B NORTON, B NORTON, B	8306160584* 8306160584* 8306160595* 8306160595* 8306170379*	50-275 0 50-275 0 50-275 0 50-275 0 50-142 T
MUSBALLI,Y C	B3040B0303*	50-410 A	Nicolaras, H	8304020523	50-263 P	NORTON, B	8306170390*	50-142 T
MUSBALLI,Y G	B3040B0304*	50-410 A	Nicolaras, H	8304230034	50-263 P	NORTON, B,	8306170417*	50-142 T
MUSBALLI,Y G	B3040B032G*	50-410 A	Nicolosi, J	8304020392*	70-698	NORTON, D	8306170426*	50-142 T
MUSBALLI,Y G	B3040B0340*	50-410 A	Nicolosi, J	8304040172*	40-672	NORTON, B	8306280320	50-275 Q
MYERS,D D	B304140705*	50-324 G	Nicolosi, J	8304040177*	40-672	NORTON, J F	8306030143*	50-254 Q
MYRABO, A L	830620088	50-263 R	NICOLOSI, J	8304040179 *	40-672	NORTON, J. F	9305030148*	50-546 Q
MYRABO, A L	8306200105	50-263 R	NICOTERA, C	8304080194	50-322 H	NORTON, J. F	9305070190*	50-254 Q
NAAF, D E	8306170354*	50-263 P	NIEMCZYK, S J	8304080041 *	FOIA	NORTON, J. F	9305100105*	50-237 Q
NAIDU, K, R	8306030151*	50-440 G	NIOHTINGALE, E	8304230359 *	50-358 Q	NORTON, J. F	9305230420*	50-409 Q
NAIDU, K R	8306100266*	50-374 G	NILBON, R	8304020454	PR	NOVACHEK, F	9305300099	50-267 S
NAKAMURA, N	8306160685*	XFORTLIC	NILBON,R	8306170254	REGOD	NOVAK, T.M.	8306020045	50-423 C
NARBUT, P P	8306070007*	50-528 G	NIMITZ,R L	8306020434*	50-244 G	NOVAK, T.M.	8306020598	50-369 P
NARDACCI, G A	8306070217*	50-289 R	NIMITZ,R L	8306160348*	50-220 G	NOVAK, T.M.	8306020606	50-370 A
NARDACCI, G A	8306300164*	50-289 R	NIMITZ,R L	8306230216*	50-334 G	NOVAK, T.M.	8306020611	50-329 A
NARDI, A J	8306080021	70-1151	NIX,H C	8305310144	50-321 S	NOVAK, T.M.	8306020694	50-440 E
NARDI,A J	8304080327	71-4909	NIX,H C	8304030042	71-9176	NOVAK, T. M	8306030509	50-440 A
NARDOCI,P B	8304010015	50-370 S	NIX,H C	8304070080	50-321 S	NOVAK, T. M	8306030517	50-454 A
NARDOCI,P B	8304010078	50-369 S	NIX,H C	8304070259	50-366 S	NOVAK, T. M.	8306060349	50-322 A
NARDOCI,P B	8304010104	50-370 S	NIX,H C	8304070347	50-321 S	NOVAK, T. M	8306070460	REVIEW ORP
NARDOCI,P B	8304010123	50-369 S	NIX,H C	8304130244	50-366 S	NOVAK, T. M.	8306080378	50-508 A
NARDOCI,P.B NARDOCI,P.B NARDOCI,P.B NARDOCI,P.B NARDOCI,P.B	8304010254 8304010401 8304070143 8304070015 8304070040	50-369 \$ 50-369 \$ 50-369 \$ 50-370 \$ 50-370 \$	NIX.H C NIX.H C NIX.H C NIX.H C	8306140246* 8306150041* 8306150044* 8306150137* 8306170382	50-321 F 50-321 F 50-321 F 50-321 F 50-321 R	NOVAK.T.M NOVAK.T.M. NOVAK.T M, NOVAK.T M NOVAK.T M	8304080388 8304170448 8304220221 8304230482 8304240077	50-50B A 50-329 B 50-395 G 50-369 E 50-423 D

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
NOVAK, T M NOVAK, T M NOVAK, T M NUSBBAUMER, D O'BRIEN, J P	8306280070 8306290163 8306290595 8306140331 8306070385*	50-329 A 50-390 A 50-352 A WASTE MOT 50-312 G	GKADA, S GKADA, S OKYERE, E W OLLER, R E OLGEN, R M	8306160624 8306160724* 8306070452 8306210238* 8306090501	XPORTLIC XPORTLIC NUREQ QA999 ADVCM	PAGLING.R PAGLING.R PAGLING.R J PAPERIELLG.C J PAPERIELLG.C J	8306020376# 830615000B# 8306090151# 8306090177 8306090229	50-354 0 50-289 0 50-352 0 50-264 0 50-155 F
D'CONNOR, B O'CONNOR, D M O'DONNELL, E P O'NEILL, B O'NEILL, J	8306170142 8306210220 8306220266* 8306060266* 8306070372	50-346 S 50-322 A CONTRACT 50-320 G 50-155 Q	GLSHAN, L. N GLSHAN, L. N GLSHAN, L. N GLSGON, R. C GNCAVAGE, M. P	8304010017 8304010031 8304240379 8304070047 8304300157	50~454 A 50~454 A 50~454 A 50~317 P PR	PAPER IELLO, C. J. PAPER IELLO, C. J. PAPER IELLO, C. J. PAPER IELLO, C. J. PAPER IELLO, C. J.	8306100165 8306100212* 8306100217 8306100226 8306100252	50-483
O'NEILL, J H O'NEILL, J H O'NEILL, J H	8306070375* 8306070424 8306010390 8306010390 8306010395*	50-155 G 50-155 G 50-400 G 50-400 G 50-400 G	ONCAVAGE,M P ONCAVAGE,M P OPREA.G W OPREA.G W OPREA.G W	8304300161 8304300227 8304070112 8304130350 8304170388	PR PR 50~498 S 50~498 S 50~498 S	PAPERIELLO, C. J. PAPERIELLO, C. J. PAPERIELLO, C. J. PAPERIELLO, C. J. PAPERIELLO, C. J.	8306100255# 8306130285 8306130306 8306130311 8306130330	50-373
H L.JLISN'O H L.JIISN'O H L.JIISN'O H L.JIISN'O	8306010375* 8306030336 8306030336 8306070291 8306070291	50-400 G 50-400 G 50-400 G 50-400 G 50-400 G	OPREA.G W ORTH.D A OSTER.J OSTER.J OSTER.J	830 6200122 830 6200074 830 6020183 830 6130231 830 6140003	50-498 A ACRS 50-373 J 50-454 J 50-10 J	PAPERIELLO, C. J. PAPERIELLO, C. J. PAPERIELLO, C. J. PAPERIELLO, C. J. PAPERIELLO, C. J.	8306130396 8306130405 8306170277 8306210161 8306220026	50~255 0 50~254 0 50~275 0 50~346 0 50~275 0
O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P	8306060020* 8306060024* 8306060038* 8306060003	FOIA FOIA FOIA FOIA 50-250 Q	OSTER.J OSTER.J OTTINGER.R L OTTINGER.R L OTTINGER.R L	8304170283 8304270345 8304020248* 8304030158* 8304040380*	50-373 J 50-454 J 50-322 U 50-247 U COMMISSION	PAPERIELLO, C. J. PAPERIELLO, C. J. PAPERIELLO, C. J. PAPERIELLO, C. J. PAPERIELLO, C. J.	8306270162 8306270167 8306270185 8306300068 8306300226	50-156 0 50-155 0 50-2 0 50-370 0 50-409 0
O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P	9306140028 8306140040 8306140072 8306140078 8306140116	50-416 Q 50-302 Q 70-1113 50-261 Q 50-321 Q	OUBRE,R P. OVERTON,J A PACE,P L PACE,P L PAGE,R O	8304210054 8304300155 8304020214 8304140438 8304010479	50-312 R PR 50-250 R 50-250 R 40-4500	PARCHEN,L J PARIS.O H PARK,J Y PARKER,J E PARKER,M E	8306240052 8306280552 8306280076 8306280251 # 8306210278#	NUREQ 50-155 G NUREQ 50-397 E 50-341 Q
O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P	8306140194 8306140328 8306140366 8306140393 8306140487	50~324 Q 50~280 Q 50~389 A 80~250 Q 50~395 Q	PAGE-R O PAGE-R O PAGE-R O PAGE-R O, PAGE-R O	630 4020220 830 4030152 830 4030179* 830 4040342 830 4070430	WASTE MOT 70-1201 70-1201 40-2061 40-4500	PARKER, P E PARKS, B PARKYN, J D PARSONS, R M PARSONS, R M	8306240443 8306280476 8305030423 8306010128 8306010422	PROJ 50-309 6 PR 50-400 8 50-400 8
O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P	8306140519 8306140533 8306140550 8306140565 8306140570	50-416 G 50-324 V 50-280 F 50-413 G 50-438 G	PAGE, R G PAGE, R G PAGE, R G PAGE, R G PAGE, R G	8304070435 8304070442* 8304080052 8304080373 8304090255	40-2041 40-2041 70-2910 70-2838 70-2910	PARSONS, R N PARSONS, R M PARSONS, R M PARSONS, R M PARSONS, R M	B306070217 B306070231 B306070366 B306070389 B306070400	50~400 S 50 400 S 50~400 S 50~400 S 50~400 S
O'REILLY, J P D'REILLY, J P O'REILLY, J P O'REILLY, J P D'REILLY, J P	8306140577 8306140602 8306140622 8306140627 8306140640	50-250	PAGE.R G PAGE.R G PAGE.R G PAGE.R G PAGE.R G	830 60 90 25 9 % 830 60 90 26 5 830 60 90 26 9 % 830 61 40 17 9 830 61 40 44 2	70- 2910 70-2926 70-2926 70-1151 40-8774	PARSONS, R M PARSONS, R M PARSONS, R M PARSONS, R M PARSONS, R M	8306090046 8306090180 8306090191 8306090242 8306100238	50-400 B 50-400 B 50-400 B 50-400 B 50-400 B
O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P	8306140646 8306140659 8306140710 8306140735 9306210236	50-335 F 50-400 A 50-280 Q 50-324 Q 50-416 Q	PAGE.R O PAGE.R O PAGE.R O PAGE.R O PAGE.R O	8306170479 8306170479 8306210434 8306210436 8306210444	70-1257 40-6264 40-6264 70-143 70-1113	PARSONS, R M PARSONS, R M PARSONS, R M PARSONS, R M PARSONS, R M	8306100254 8306140470* 8306200116 8306200200 8306270223	50-400 S 50-400 S 50-400 S 50-400 S 50-400 S
O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J, P O'REILLY, J P	8305210240* 8305220171 8305220175* 8305240005 8305240014*	50-414 Q 50-269 Q 50-269 Q 50-321 Q 50-321 G	PAGE.R G PAGE.R G PAGE.R G PAGE.R G PAGE.R G	830 6280030 630 6290082 630 6290083* 630 6290101 830 6290682	40-6500 70-734 70-734 40-6500 70-2375	PARSONS,R M PARSONS,R M PARTLOW,J G PASCIAK,W PASCIAK,W	8306280463 8306300192 8306210354 8306230397# 8306280484#	50-400 G 50-400 B NUREO 50-293 G 50-293 G
O'REILLY, J P O'GHAUGHNESBY O'SULLIVAN E T O'SULLIVAN, E T	9306270483 9306270524 9306010451 9306060004* 9306060012*	50-257 Q 50-241 G 50-247 O FOIA FOIA	PALLADINO, N J	8305240405 8304020227 8304020242* 8304030156 8304030157	COMMISSION 50-322 U 50-322 U 50-247 U COMMISSION	PASCIAK, W J PASCOE, S PASQUA, M P PASTVA, M J PASTVA, M J	8306020407# 8306070280# 8306220276# 8306010105 8306010107	50-31/ Q CONTRACT CONTRACT 50-324 S 50-324 S
O LOOPE'N D O LOOPE'N D O LOOPE'N D O LOOPE'N D	8306040033* 8306010124* 8306020274 8306070343 8306160462	FOIA 50-247 G 50-247 R 50-247 P 50-247 R	PALLADIND, N J PALLADINO, N J PALLADINO, N J PALLADINO, N J PALLADINO, N J	830&0301&4 830&030170 830&0303&7 830&030375* 830&0&03&9	50-320 P 50-322 U COMMISSION COMMISSION	PASTVA, M J PASTVA, M J PASTVA, M J PASTVA, M J PASTVA, M J	8304010118 8304070081 8304070097 8304070102 8304070235	50-325 9 50-325 9 50-324 9 50-324 9
0 (.31001.0 0 (.31001.0 0 (.31001.0 0 (.31001.0 0 (.31001.0	8306170044 8306170189 8306170197 8306170200 8306170230*	50-247 S 50-247 S 50-247 S 50-247 S 50-247 S	PALLADINO, N J PALLADINO, N J PALLADINO, N J PALLADINO, N J PALLADINO, N J	8306060374* 8306060388 8306080429 8306140513* 8306150533	COMMIBSION 50-272 U ADVCM ADVCM 50-272 U	PATTVA, H J PATTVA, M J PAGTVA, M J PAGTVA, M J PAGTVA, M J PAGTVA, M J	B306100127 B306200003 B306210096 B306210174 B306270061	50-324 B 50-324 B 50-324 B 50-320 B 50-324 B
0.100FE'1 D 0.100FE'1 D 0.100FE'1 D 0.100FE'1 D	8306170271 8306170323 8306170397 8306170405 8306170410	50-247 8 50-247 8 50-247 8 50-247 8 50-247 8	PALLADINO,N J PALLADINO,N J PALMER,R A PALMER,R.A PALMER,R A	8306160153* 8306270270* 8306060186* 8306060271* 8306210134*	FOIA 50-287 0 50-315 \$ 50-316 \$ 50-315 \$	PASTVA, M J PASTVA, M J PASTVA, M J PASTVA, M J PATE, R J	8306270199 8306270277 8306300012 8306300203 8306070368*	50~324 S 50~324 S 50~324 F 50~325 B 50~361 Q
O'TOOLE, J D O'TOOLE, J D O'TOOLE, J D O'TOOLE, J D OBERG, C R.	8306170415 8306200257 8306240225 8306270171 8306210070*	50-247 S 50-247 P 50-247 Q 50-3 R 50-382 Q	PALMER, R A PALMER, R A PALMER, R, A PALMER, R, A PALMER, R, A	8306210142* 8306210267* 8306210273* 8306270158 8306270436*	50-915 S 50-915 S 50-915 S 50-914 S 50-915 S	PATE.R J PATTERSON, J P PATTERSON, W F PATTERSON, W F PATTERSON, W F	8304280511* 8304100212* 8304080088 8304150224 8304150230	50-36) Q 50-341 Q 50-449 Q 50-461 Q 50-443 Q
ODEGAARDEN, R. H ODEGARD, B J OEGTMANN, M J OEGTMANN, M, J OKADA, B	8306280101 8306020011 8306100167* 8306270174* 8306150459	71-9096 NUREQ 50-483 0 50-155 0 XPORTLIC	PALMER, RA PALMER, RA PANGBURN, GC PANGBURN, GC PANGBURN, GC PANNG, S. V.	8306270444* 8306270447* 8306070228* 8306210437 8306140407	50-915 B 50-915 B 40-8452 87-47 NUREO	PATTERSON, W F PATTERSON, W F PATTERSON, W F PATTON, S D PAUL, R A	8306150256 8306200173 8306270306 8306020454 8306130333*	50-443 0 50-443 0 50~443 0 PR 50~305 0

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT	AUTHOR	ACCESBION NUMBER	SUBJECT CATEODRY
PAUL: R A PAUL: R A PAULK, Ø L PAULSON: W A PAULSON: W A	8304270147# 8304300231# 8306140297# 8306070049 8306080209	50-156 G 50-409 G 50-259 G 50-206 P 50-206 P	PFLUM.C O PHILBRICK, S S PHILL IPS.H S PHILL IPS.H S PHILL IPS.H S	8306240151* 8306240112* 8306130422* 8306210020* 8306210286*	FOIA FOIA GA999 GA999 GA999	POTAPOVS, U POTAPOVS, U POTAPOVS, U POTAPOVS, U POTAPOVS, U	8304210023 8304210025 8304210030 8304210049 8304210172	0A779 0A779 0A777 0A779 0A779
PAULSON:W A PAULSON:W A PAVIS,G S PAVIS,G S PAWLIK,E T	8306210168* 8306240175 8306170072 8306210099 8306170392*	50-244 P - 50-206 P 50-318 S 50-318 S 50-454 G	PHILLIPS,H S PHILLIPS,H S PHILLIPS,M PHUNG,D L PIEMONTESE,A P	8304280404 8304280579 8304130412* 8304280089 8304010323	QA999 QA999 50-254 Q NUREQ 50-387 B	POTAPOVS. U POTAPOVS. U POTAPOVS. U POTAPOVS. U POTAPOVS. U	8304210185 8304210215 8304210230 8304210238* 8304210244	0A777 0A777 0A777 0A777
PAYNE, A C	8304010052	NUREO	PIEMONTESE, A P	8306020369	50-387	POTAPOVS. U	8306210272	GA979
PEARSON, D	8304210410	ACRE	PIEMONTESE, A P	8306020401		POTAPOVS. U	8306210278	GA979
PEARSON, D	8304210410	ACRE	PIEMONTESE, A P	8306170015		POTAPOVS. U	8306230401	GA979
PEOERSON, L T	8304020134	NUREO	PIEMONTESE, A P	8306170037		POTAPOVS. U	8306240176	GA979
PEEOLES, T A	8304220050#	50-346 0	PIEMONTESE, A P	8306280140		POTAPOVS. U	8306240209*	GA999
PELIZZA:M B	0304090020	40-8786	PIEMONTESE,A P	8304280518	50-387 S	POTAPOVS.U	B306240237	0A779
PELIZZA:M B	0304210425	40-8786	PIERCE,J W	8304220117	50-458 0	POTAPOVS.U	B306240289	0A779
PELIZZA:M B	0304210451	40-8786	PIERCE,R C	8304140238*	CONTRACT	POTAPOVS.U	B306270452	0A779
PELKE:P R	0304030151*	50-440 G	PIERINGER,P	6304170031	50-317 S	POTAPOVS.U	B306280129	0A799
PELKE:P R.	0304300103*	50-440 G	PIERINGER,P A	8304010270	50-318 S	POULK.R M	B306070053	50-325 B
PELLETIER, JP	8306170039	50-271 8	PIERINGER, PA	8306280172	50-316 S	POWELL,D C	8306020053	NUREO
PELLETIER, JP	8306170264	50-271 8	PIERINGER, PA	8306280352	50-316 S	POWELL,T	8306080203	50-358 Q
PELTZZA, MS	8306220130	40-8784	PIGOTT, DR	8306220084	50-341 G	POWELL,T	8306080205*	50-358 O
PELTO, PJ	8306020134	NURE9	PIGOTT, DR	8306220084	50-341 G	POYSER,R W	8306160656	40-2259
PEMDERTON, HR	8306160275	50-361 K	PILANT, JM	8306060261	50-296 J	PRELL,J	8306070146*	50-317 Q
PENNIFILL.R A PERCH.R PERCH.R L PERCIVAL.R M PERKING.R W	8306030477 8306170445 8306150275 8306020329* 8306090357	WASTE MCT 50-387 P 50-387 P CONTRACT WASTE MST	PILANT, J M PILANT, J M PILANT, J M PILANT, J M	8304080061 8304080219* 8306100133 8306140714 8304140464	50-278 F 50-278 Q 50-278 P 50-278 Q 50-278 P	PRESLER,H A PRESLER,H A PRICE,W PRICHARD,R P PRICHARD,R P	8306130437 8306270461* 8306130378 8306080341 8306160664	50-413 Q 50-413 Q 50-322 Q 71-4909 71-9134
PERLIS,R O PERLIS,R O PERLIS,R O PERLIS,R O PERLIS,R O	8304010144	50-483 0	PILANT, J M	8306160466	50-298 P	PRICHARD,R P	8306170462	71-9132
	8304020147	50-443 0	PILANT, J M	8306200106	50-298 F	PRICHARD,R P	8306200022	71-4960
	8304080033	50-443 0	PILANT, J M	8306280386	50-298 P	PROCTOR,S	8306220006	50-329
	8304200173	50-443 0	PILANT, J M	8306280444	50-298 P	PROCTOR,S D	8306060315	50-329
	8304210244	50-483 0	PIRTLE, G L	8306130317*	50-346 0	PROCTOR,S D	8306200306	50-329
PERLIS,R 0	8306210271*	50-463 G	PLAINE, H H	9304070343	50-289 G	PROCTOR: 8 D	8306220069	50-327 &
PERLIS,R 0	8306240355	50-410 G	PLAINE, H H	8304220043*	50-170 G	PROWITT, B M	8306230080*	FOIA
PERLIS,R 0	8306280583	50-478 G	PLAINE, H H	8304230340	50-289 G	PULIDO, M	8306060286	50-454 &
PERLMAN,J	8306030263	CONTRACT	PLANK, R A	8304210033*	6A979	PULIDO, M	8306170379*	50-142 T
PERLMAN,J	8306030268	CONTRACT	PLATT, W	8304150378	50-529 G	PULIDO, M	8306170390*	50-142 T
PERLMAN, J	8306170463	CONTRACT	PLATT,W	8306150398	50-529 C	PULIDO,M	9304170417*	50-142 T
PERLMAN, J	8306200128	CONTRACT	PLATT,W E	8306100078*	50-529 G	PULIDO,M	9304170424*	50-142 T
PERLMAN, J	8306220133	CONTRACT	PLATT,W E	8306100078*	50-529 G	PULLANI,S V	9304200130*	50-277 Q
PERLMAN, J	8306220284	CONTRACT	PLONIS,T R	8306070468*	CONTRACT	PURDY,O J	8304230409	NUREQ
PERROTTI, D J	8306140636*	50-382 0	PLOSKI,T	8306130412*	50-254 G	PURPLE,R A	8304150257*	50-29 J
PETERBON, C E PETERBON, D A PETERBON, M R PETERBON, M R	8306280486 8306240263* 8306130310 8306150451 8306150470	50-333	PLOTKIN, 8 PLOTKIN, 8 PLOTKIN, 8 PLUMLEG, 0 PLUMMER, D E	8306170379* 8306170417* 8306170426* 8306060126* 8306010085*	50-142 T 50-142 T 50-142 T 50-267 G 71-6400	PURPLE,R A PURPLE,R A PUTTARINI,D M GUICK,D P GUICK,D R	8306150628* 8306210426* 8306130150 8306210354 8306140162*	50-220 F 50-111 P 50-528 B NURES 50-327 Q
PETERSON: M R	B306150475*	XPORTLIC	POCHAL, W F	9306160672	XPORTLIC	GUICK, D R	8306140390*	50-327 Q
	B306160636	XPORTLIC	POETON, R W	9306010039	NUREO	GUICK, D R	8306140434*	50-390 Q
	B306160640	XPORTLIC	POETON, R W	9306010067	NUREO	GUICK, D R	8306140580*	50-390 Q
	B306160723	XPORTLIC	POETON, R, W	8306010071	NUREO	GUICK, D R	8306140583*	50-416 Q
	B306210374	XPORTLIC	POETON, R W	8306020053	NUREO	GUICK, D R	8306290334*	50-430 Q
PETERSON: MR PETERSON: MR PETERSON: MR PETERSON: MR PETERSON: MR	8306210380 8306210414 8306220270 8306230023 8306240325	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC	POLK, H POLK, H E POLLOCK, M S POMEROY, P W	8305230345* 8305230135* 8306140498* 8306140615* 8306200440	50-275 P 50-275 P 50-322 Q 50-322 Q ACRS	GUINTON,M D GUIRK,J F GUIRK,J F RABY,J RADDER,J A	8306010357* 8306290500* 8306290512* 8306060199 8305310226	50-395 G 50-447 K 50-447 K 50-220 B 50-245 P
PETIT, M R PETIT, M R. PETRICK, N. A PETRICK, N. A. PETRONE, C. D	8306130390	50-322 0	POMEROY,P W	8304200440	ACRS	RAE,R M	8305030449	FDIA
	8306130401	50-322 H	POPE,M A.	8304080083*	50-324 P	RAGLIN,K A	8305140423*	50-324 G
	8306100183	50-482 B	POPPE,L K	8304070202	71-9094	RAHE,E P	8305150157	PROJ
	8306220013	50-482 A	POPPE,L K	8304210250	71-9108	RAHE,E P	8305150224	NUREQ
	8306210103*	50-213 9	PORT,E A	8304010049	40-2061	RAHE,E P	8305150433	PTRI
PETROWSKI, 8 E PETTENGILL, H PETTENGILL, H J PETTENGILL, H J PETTENGILL, H J	8306060148	80-304 B	PORTER, S W.	8306240384	NUREQ	RAHE, E P	8304170254	REGOD
	8306200437	40-2453	PORTHEMORE, H	8306280538	50-287 0	RAHE, E P	8304230384	TOPREP
	8306020259	40-299	POSNER, P	8306060180	50-247 0	RAHE, E P	8304240205	50-349 P
	8306020308*	40-8681	POSNER, P.	8306090350	50-247 T	RAHE, E P	8304240313	TOPREP
	8306020334*	40-8586	POSTMA, A K	8306070471	NUREO	RAHE, E P	8304270355	PROJ
PETTENGILL, H J	8306020340	40-299	POTAPOVS: U	· 8306070066	50-413 S	RAHE, E P	8306280392	50-445 A
PETTENGILL, H J	8306070228*	40-8452	POTAPOVS: U	8306070108	GA999	RAHE, E P	8306280449	TOPREP
PETTENGILL, H J	8306070487	40-8681	POTAPOVS: U	8306070158	GA999	RAHE, E P	8306300120	50-445 A
PETTENGILL, H J	8306070475	40-8585	POTAPOVS: U.	8306070168	GA999	RAMADAB, E B	8306130328*	50-322 E
PETTENGILL, H J	8306130406	40-2259	POTAPOVS: U.	8306070186	MISC	RAMADELL, J V.	8306020053	NUREO
PETTIOREW.M. PETTIOREW.H PETTY,J.C PEVEY.L.C. PEVEY.L.E.	8306020592* 8306130212* 8306210190 8306140290 8306140298	71-9080 71-9089 50-207 8 XPORTLIC XPORTLIC	POTAPOVS, U POTAPOVS, U POTAPOVS, U POTAPOVS, U POTAPOVS, U	8306070268 8306070331 8306070331 8306130113 8306130174	GA999 GA999 GA999 GA999 GA999	RAMBEY, C B RANDAZZA, J B RANDAZZA, J B. RANDAZZA, J B RANDAZZA, J B	8304300047* 8304100274 8304210175 8304290484 8304020014	50-341 0 50-307 0 50-307 0 50-307 0 NUREO
PFEFFERLEN.H C.	8306170318	TOPREP	POTAPOVS, U	8304130397	GA999	RANGANATH.S	8304020379*	50-277 P NUREO CONTRACT CONTRACT 50-254 P
PFLUM.C Q.	8306030273	MASTE MOT	POTAPOVS, U	8304130413	GA999	RAMKIN.W.L	8304030009	
PFLUM.C Q.	8306240084*	FOIA	POTAPOVS, U	8304160548	GA999	RASILE.JA	8304020513*	
PFLUM.C Q.	8306240074*	FOIA	POTAPOVS, U	8304210001	GA999	RATCLIFF.WH	8305040713*	
PFLUM.C Q	8306240119*	FOIA	POTAPOVS, U	8304210013	GA999	RATHBUN.LA	8304270324	

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	MONDER ACCESSION	CATEGORY
RATTA, A D RAUHONDO, C RAUSCH, W F RAUSON, R J RAWSON, R J	8306170245* 830613039B 8306230437 8306230446 8306080173	70-371 50-322 0 TOPREP 50-322 0 50-289 0	Repka, D a Regua, G Regua, G Resh. D L Resnikoff, M	8304300071 8304170440 8304200018 8306220148 8304210322	50-322 G 50-261 P 50-261 P CONTRACT FDJA	RIDGWAY, D A RIDGWAY, D A RIDGWAY, D A RIDGWAY, D A RIEL, G L	8306220082 8306230358 8306230358 8306280514 8306280512	50~482 0 50~482 0 50~482 0 50~482 0 50~482 0
RAWSON, R. J RAY, H B RAY, H B RAY, H B RAY, H B	93061 \$0318 93061 00054 93061 00069 93061 00072 93061 00098	50-454 0 50-361 5 50-361 8 50-361 8 50-361 6	RESNIMOFF, M RESSLER, W C RESSLER, W C REUSCHAEFER, E REVELEY, W T	8306210330 8306070215 8306300162 8306170221 8306130404	FD1A 50-287 R 50-287 R 50-302 R 50-32P G	RICERT, J A RILEY, J L RILEY, R W RING, M A RING, M A	8306150373* 8306270284 8306300142 8306100247* 8306230290*	50~32P
HAYAH BAYAH BAYAH BAYAH BAYAH BAYAH B	93041400115 9304140007 9304140239 9304140250 9304140484	50-341 S 50-361 S 50-362 S 50-361 B 50-361 S	REVELEY, W T REVELEY, W T REVELEY, W T REVELEY, W T REVELEY, W T	9304130404 9304130411 9304130411 9304300147 9306300147	50-322 0 50-322 0 50-322 0 50-322 0	R IVENDARK, G R IVENBARK, G R IVENDARK, G R OBB INS, M C ROBERDS, M J	8306210335 8306030082 8306150470 8306030451 8306210070#	50-321 p 50-366 p 50-366 p FO1A 50-302 Q
RAY, H B RAY, H B RAY, H B RAY, H, B RAY, H B	8306160455 8306160489 8306210113 8306210352 8306230266	50-206 R 50-361 R 50-361 9 50-361 5 50-361 8	REYES,L A REYES,L A REYES,L A REYNOLDS,J R REYNOLDS,J R	8306100175* 8306100247* 8306230270* 8306010336 8306010336	50~454 G	8 A.RTRBOOR R H.RTRBOOR 9 L.RTRBOOR 9 L.RTRBOOR P.RTRBOOR	8306220158* 8306230027 8306020471 8306230213 8306240484	CONTRACT 40-8681 PROJ PROJ 70~1308
RAY,H B RAY,H B RAY,H B, RAY,H B RAY,H B	8304230369 8304230467 8304280252 8304280267 8304280273	50-362 8 50-362 8 50-361 8 50-361 5 50-361 8	REYNOLDS, J R REYNOLDS, J R REYNOLDS, J R REYNOLDS, J R	9306060182 9306060182 9306070406 9306150435 9306150435	50-275 0 50-275 0 50-275 0 50-275 0 50-275 0	ROBERTS, T M ROBERTS, T M ROBERTS, T M ROBERTSON, J B ROBINSON, D	8306240333 8306240335 8306240336* 8306280190 8306210279*	COMMISSION COMMISSION COMMISSION NUREO 50~315 8
RAY,H B. RAY,H,B RAY,J H RAY,J,J RAYMON,M R	8306280350 8306280410 8306100152* 8306290122* 8306060309*	50-361 5 50-361 8 50-483 A 50-447 0 70-25	REYNOLDS, J. R REYNOLDS, J. R REYNOLDS, J. R REYNOLDS, J. R REYNOLDS, J. R	8304220038 8304220038 8304280545 8304280545 8304270535	50-275 G 50-275 G 50-275 P 50-275 P 50-275 G	ROCCO.J RODAGAUGH.E C RODRIGUEZ.R J RODRIGUEZ.R J RODRIGUEZ.R J	B304270172 B304230031# B304010397 B304070047 8304070049	50~206 J 6 210~00 7 210~00 8 210~00 9 210~00
RAYMOND,W.J RAYMOND,W.J W.JONON,J.W.J RAYNON,J.W. W.L.SONON,J.W.	8305070353* 8305160005* 8305200161* 8305010300 8305010307	50-271 9 50-271 9 50-271 9 50-317 8 50-317 8	REYNOLDS, J R REYNOLDS, N J REYNOLDS, N J REYNOLDS, N S REYNOLDS, N S	6304270535 8304060237 8304080237 8304020345 8304020345	50~275 0 50~445 0 50~445 0 50~460 0 50~460 0	RDDRIGUEZ,R () RODRIGUEZ,R () RODRIGUEZ,R () RODRIGUEZ,R () RODRIGUEZ,R ()	8304070233 8304070306 8304140126 8304140571 8306170223	50-312 p 50-312 p 50-312 p 50-312 f 50-313 g
RAYNOR, J W REAVIS, J A REBELLO, J. REBELLO, J E	8306170420 8306170297 8306170311 8306160045* 8306030054*	50-318 S 50-269 R 50-369 R CONTRACT CONTRACT	REYNOLDS, N S	8306020431 8306030330 8306030330 8306030347 8306030347	50-508	RDDRIGUEZ.R J RODRIGUEZ.R J RODRIGUEZ.R J RODRIGUEZ.R J RODRIGUEZ.R J	8306170290 8306170358 8306170402 8306210048 8306220040	50~312 g 50~312 g 50~312 p 50~312 p 50~312 p
REBELLO, J, E REBELLO, J, E REBELLO, J, E REBELLOWSKI, T	8306210303* 8306220246* 8306230046* 8306270281* 8306060211*	FOIA CONTRACT CONTRACT CONTRACT 50-483 Q	REYNOLDS,N S REYNOLDS,N S REYNOLDS,N S REYNOLDS,N S REYNOLDS,N S	8304030353 8304030353 8304040313 8304080243# 8304080243*	50~460	RODRIGUEZ, R J	8306270075 8306230372 8306230373 8306230373	50-312 p 50-312 p 50-312 p 50-312 p 50-312 p
REDAND, R. T REDAND, R T REDAND, R T, REDWANZ, F J REED, C	8304010141* 8304040133* 8304210012* 8304170382 8304140334	50-247 0 50-112 0 50-298 0 50-321 R PR	REYNOLDS, N S	8306090337 8306090337 8306100190 8306150354 8306150354	50~440 0 50~440 0 50~460 0 50~508 0 50~508 0	RODRIGUEZ, R J RODRIGUEZ, R J RODRIGUEZ, R J RODRIGUEZ, R J RODRIGUEZ, R J	8306230410 8306230447 8306270133 8306270260 8306270325	50-312 B 50-312 P 50-312 P 50-312 P
REED, C REED, C. REED, J. Q REED, J. Q REED, L. D	9306220034* 9306230037* 9306030331 9306230344 9306240241	50-254 Q 50-373 A 50-463 Q 50-463 G RES	REYNOLDS,N S REYNOLDS,N S REYNOLDS,N S REYNOLDS,N S	8306150366 8306150366 8306150376 8306150376 8306150425	50~445 0 50~445 0 50~445 0 50~445 0 50~445 0	RODRIGUEZ,R J ROE.K A ROGAN.R E ROGERB,H R ROGERB,H R	8306300011* <i>8306230443*</i> 8306240317 <i>8306</i> 010167 8306010376	50-312 0 TOPREP 50-209 F 50-320 S 50-327 S
REEVES, P. E. REGAN, N. A. REGAN, W. H. REGAN, W. H. REGAN, W. H	8304140547* 8304220131 8304030242 8304030244* 8304140345	50~324 @ 70~824 50~329 M 50~329 M 50~329 M	REYNOLDS, N S. REYNOLDS, N S REYNOLDS, N S REYNOLDS, N S	83061 50425 83061 70334 83061 70406 83061 70406 8306230364	50~445 0 NUREQ 50~445 0 50~445 0 50~460 0	RDOERS, H R ROOERS, H R ROOERS, H R ROOERS, H R ROOERS, H R	8304100173 8304130242 8304210090 8304210104 8304210290	50-326 8 90-326 8 50-326 9 50-326 6 90-326 8
REGAN, W H REGAN, W H REGAN, W H REHFELDT, W R	8306140350* 8306140360 8306240369 8306240380* 8306240043*	50-329 M 50-329 M PROJ PROJ FOIA	REYNOLDS, N S. REYNOLDS, N S. REYNOLDS, N S RHQADS, Q RHQADS, Q	8306230364 8306300047 8306300047 8306010134* 8306170343	50~460 0 50~460 0 50~460 0 50~387 0 50~387 8	RDGERS, H R RDGERS, H R RDGERS, P RDGERS, P RDGERS, P	8306270250 8306280192 8306130421 8306210003 8306210181	50-327
REHFELDT, W R REHM, T, A REHM, T, A REHM, T, A REHM, T, A	8306240106* 8306020710 8306070426 8306080102 8306150146	Foia Commission Commission Gen Tec Is Commission	RHODES, M, J RHODES, M, J RHODES, M, J RHODES, M, J	8306170336* 8306020213 8306030186 8306030467 8306210447	50-390 A 40-8027 40-8027 40-7580 70-371	ROGERS, W G ROGERS, W H ROGERS, W H RDOGE, J ROHRER, M V	8306220050# 8306170485# 8306220310# 8306200203 8306070237	50-346 0 CONTRACT 50 321 F 50-321 E 50-416 B
REHM, T. A REHM, T. A. REICH, H REIMANN, F. W. REIMANN, F. W.	8306150112* 8306230221 8306020048 8306230022* 8306230061*	FOIA COMMISSION RES 50-373 G 50-373 G	RHODES,M J RHYNE,W R. RICE,D A RICE,D W RICHARD,J B	8306280095 8306220320# 8306170418 8306150064 8306090134	70-371 CONTRACT 50-27 8 50-272 P 50-416 5	ROHRER, M V ROLKIEOFF, M L ROMANINE, B J ROMAN, T W ROMAN, T W	8306140669 83060603099* 8306080194 8306020094 8306200214	50-416 8 70 25 50-322 H 50 220 N 50-220 N
REIMERS, Q. A REITER, R. REITER, R. REITTER, T. A. REKITO, W. A.	8306170354* 8306080215 8306080250 8306150619 8306010231*	50-243 P 50-358 e 50-358 e NUREQ 50-333 g	Richard, J. B Richarde, B Richarde, B Richardeon, C. Richardeon, J. D	8306290211 8306060170* 8306150008* 8306210029 8306200412	50-416 0 50-277 0 50-289 0 50-271 H 50-416 R	ROMANO,FR ROMANO,FR ROMAND,FR ROMANO,FR ROMATOWSKI,RG	8304270344 8304270507	50-352 0 50-320 0 50-352 0 50-352 0 WASTE HOT
Repka, D. A. Repka, D. A. Repka, D. A. Repka, D. A. Repka, D. A.	8305100041 8305130414 8305230003 8305230008 8305280505	50~458	RICHTER, L. RICHTER, L. RIDGHAY, D A RIDGHAY, D A RIDGHAY, D A	83062170429 8306210262 83062200312 83062200312 8306220082	50~346 B 50~346 B 50~492 D 50~492 O 50~492 Q	ROOD, H ROOT, L D ROPE, S K ROBANO, R ROBANO, R	8306070326# 8306020011 830601066	50-361 P 50-301 G NUREG 50-219 G 50-416 B

AUTHOR	ACCESSION NUMBER	SUBJECT	AUTHOR	ACCESSION NUMBER	SUBJEC CATEGO		AUTHOR	ACCESSION NUMBER		
ROSAVER, P J ROSE, K A ROSEN, R A ROSELIE, E ROSELIE, E	8306240342 8306140691 8306200290 8306150302 8306150306	71-9110 NUREQ 50-247 Q 50-460 Q 50-460 Q	Rybak, b Rybak, b Rybak, b Rybak, b Rybak, b	8306160233 8306200265 8306220067 8306240030 8306270108	50 -237 50-237 50-254 50-237 50-254	9 9 0 9	SCHROEDER, B A SCHROEDER, C SCHROEDER, C W SCHROEDER, C W SCHROEDER, C W	8306140086 8306100234 8305190370 8306060146 8306060238	50-237 50-374 50-373 50-373 50-373	7 R 1 S 3 P
ROSOLIE, E ROSOLIE, E ROSSBACH, L W ROSSBACH, L W ROTH, J	8306290370 8306290375# 8306290332# 8306070052# 8306060176#	50-460 Q 50-460 Q 50-321 Q 50-286 Q 70-364	Rybak. B Rybak. B Sadados, J H Sabados, J W Sachnoff, S	8306270247 8306300237 8306140582* 8306140713* 8306300128		b b	SCHROEDER, C W SCHROEDER, C W SCHROEDER, C W SCHROEDER, C W SCHROEDER, C W	8304070334 8304070355 8304190045 8304210205 8304280323	50-374 50-373 50-373 50-373 50-373	A F F
ROTH, J ROTH, J ROTHSCHILD, N U ROTHSCHILD, N U	8306150001 8306280225* 8306280118* 8306020175 8306150313	70-1143 70-1143 70-820 50-400 G 50-445 G	SALTO, T SALAZAR, E A SALTZMAN, J SALTZMAN, J SALTZMAN, J	8306240019 8306210020# 8306090022 8306090039 8306220286	XPBRTLIG GA979 50-16 50-16 50-0	ר ר י	SCHUELKE, D A SCHUM, W S SCHUMACHER, M SCHUMACHER, M C SCHUMACHER, M C	9306230097* 9306140220* 9306210148 9306100167* 9306270174*	50-282 50-482 40-863	F G
ROTHSCHILD, M U ROTHSCHILD, M U ROUSE, E A ROWLAND, G D ROWLAND, J R	8304230381 8304230381 8304270394 8304140460 8304010081	50-445 Q 50-445 Q 50-344 H REGGD NUREQ	Baltzman, J Baltzman, J Baltzman, J Baltzman, J Bampbon, M	8306230157* 8306270103 8306270128 8306270210 8306240101*	50-335 50-335 50-335	7	SCHUSTER, M D SCHUSTER, M D SCHUSTER, M D SCHUYLER, J O SCHUYLER, J O	83042800B1* 8304280134* 8304280183* 8304030142 8304040155	50-204 50-344 50-312 50-275 50-275	0 0 0 P
ROWLAND, M ROWSOME, F ROZAK, S RUBY, G RUDY, C RUDY, C	8306170414 8202090638* 8306100167* 8306130438 8306010095	50-346 B FDIA 50-483 G 50 263 B 40-6500	Sampson, M R Sandgutst. O M Sandry, W A Santoro, M P Sargent, I H	B306340096# B306140194# B3040B0070 B306240445# B306020037#	50 -7⊉ FOIA	F P	SCHUYLER, J. O SCHUYLER, J O SCHUYLER, J O SCHUYLER, J O SCHUYLER, J O	8304070034 8304070270 8304070275 8304070292 8304170031	50-133 50-275 50-275 50-275 50-275	г Н Р R Р
RUDY, C R RUDY, C R RUFF, A B RUITER, G FI RULAN, Y	8304030194 8304030304 8304140401 8304040309#	40 4500 40 -4500 50-413 9 50-305 R 70-25	Sargent, I H Sargent, I H Sargent, I H Sargent, I H Sargent, I H	8306030070# 8306030446# 8306030512# 8306070388# 8306070377#	50-33B 50-280 50-275 50-312	9 9 9	SCHUYLER, J O SCHUYLER, J O SCHUYLER, J O SCHUYLER, J O SCHUYLER, J O	6306160526 8306210111 8306240398 9306280332 6306280368	50-275 50-275 70-2375 50-275 50-275	R P
RULAND, W H RUSHMORE, J W RUSHMORE, J W RUSSCHER, Q C RUSSELL, J B	8306070228* 8306020138 8306020187 8306240052 8306270164	50-34B 0 50-220 J 50-220 J NURCO 50-317 F	SARGENT, I H SARSOUR, B SARSOUR, B SARSTEN, G E SATHER, A	8306150266# 8306020129 8306160540 8306210112 8306090245#	50~259 50~346 50~346 50~443 50~329	P R R S G	SCHWENCER, J O SCHWYLER, J O SCHWYLER, J O SCHWENCER, J O	8306280394* 8306280451 8306300041 8306300211 8306030220	50-275 50-275 50-275 50-275 50-275	P P 0 P
RUSSELL, J B RUSSELL, J E RUSSELL, L B RUSSELL, L B	8306270195 8306140168 8306010264 8306010270 8306010273	50-317 F 40 &&22 50-317 S 50-318 S 50-318 S	BAUER. J R BAURWEIN. J J BAURWEIN. J J BCALETTI.D C BCARAND, R A	8304150179# 8304140545# 8306140544# 8304080434 8304070152	50~267 50~267 50~267 50~447 50~312	H P A &	BCHWENCER, A BCHWENCER, A BGHWENCER, A BCHWENCER, A BCHWENCER, A	8304070440 8304070444 8304150227 8304150321 8304150352	50-322 50-461 50-458 50-352 50-373	G E A A
RUSSELL, L B RUSSELL, L B RUSSELL, L B RUSSELL, L B RUSSELL, L B	8304010277 8304010297 8304010300 8304010307 8304020374	50 317 9 50-318 8 50-317 8 50-317 8 50-318 8	SCARAND, R A SCARAND, R A SCHAPKER, J F SCHAPKER, J F SCHEJNMAN, L	8304280455 8304280455 8304230357* 8304270205* 8304140138*	50-312 70-115 50-358 50-546 FOIA	F 0 0	SCHWENCER, A SCHWENCER, A SCHWENCER, A SCHWENCER, A SCGGGIN, R A	8306150579 8306200429 8306220250 8306270559 8306240073	50-352 50-416 50-458 50-416 NUREQ	, EE+p
RUSSELL, L B RUSSELL, L B RUSSELL, L B RUSSELL, L B RUSSELL, L B	8304020423 8304020430 8304020433 8304020438 8304020448	50-317 8 50-318 8 50-317 8 50-318 8 50-317 8	SCHERER, A E BCHERER, A E BCHERER, A E BCHERER, A E BCHERER, A E	8306070170 8306130428 8306140683 8306200254 8306200392		∧ ₩ ₩	SCOTT.D J SCOTT.D J, SCOTT.D J, SCOTT.D J	8304030218 8304040040 8304040232 8304070234 8304070244	50-237 50-237 50-237 50-249 50-237	8 8 8
RUSSELL, L B RUSSELL, L B RUSSELL, L B RUSSELL, L B RUSSELL, L B	8304070077 8304150086# 8304170011 8304170031 8304170072	50-317 8 50-317 F 50-317 8 50-317 8 50-318 8	SCHERER, A E BCHERER, A E BCHERER, P R BCHERER, P R BCHERER, R W	8304230342 8304230419 8304200253* 8304280454* 8304070130*	50-397	E E	0 0.71038 C 0.71038 C 0.71038 C 0.71038 J. 0.71038	8305070279 8305130275 8305130325 8305130345 8305130346	50-249 50-10 50-249 50-249 50-237	8 R 8 8
RVSSELL, L B RVSSELL, L B RVSSELL, L B RVSSELL, L B	8304170420 8304200089 8304200118 8304200208 8304200248	50-318 8 50-317 8 50-317 8 50-317 8 50-317 5	SCHIAGER, K.J. SCHIERLING, H. SCHIERLING, H. SCHIERLING, H. SCHIMMEL, R. L.	630602026 8306020619 6306240473 8306290476# 6306020677	50~275	P T	SCOTT, D J SCOTT, D J SCOTT, D J SCOTT, D J	8304130374 8304130382 8304130439 8304140084 8304210357*	50-237 50-237 50-237 50-237 50-10	12888
RUSSELL, L B RUSSELL, L B RUSSELL, L B RUSSELL, L B	8306210046 8306210086 8306210099 8306210101 8306210108	50-318	SCHLIEBE, M J BCHMIDER, R BCHMIDT, G R BCHMIDT, H C BCHMIDT, H C	8306140402 8306060309* 8306070107* 8306130176 8306130279	50-445	5 A A	SCOTT, D J SCOTT, D J SCOTT, D J SCOTT, D J	8306270083 8306270111 8306270387 8306150455* 8306280519*	50-249 50-249 50-237 50-483 50-528	880F0
RUSSELL, L B RUSSELL, L B RUSSELL, L B RUSSELL, L B RUSSELL, L B	0306210157 6306210246 9306210172 9306280352 9306280447	50-318 8 50-318 8 50-318 8 50-318 5 50-317 8	SCHMIDT, H C SCHMIDT, H C SCHMIDT, H C SCHMITENDORF, 9, SCHMITENDORF, 6	8306130293 8306150102* 8306280400* 8306020092 8306160532	50~445 50~445 50~330	A F A R	SCOWN, K. M. SCUDDER, J SCULL, D. L SCURRY, N SEARS, C F	8306070261* 8306080276 8306220056 8306070475 8306010340	50-206 FOIA 50-170 ORG 50-213	0 0
RVSBELL, L B RVSTICK, R RUTENKROGER, F RUTHER, W E RUTLEDGE, C	8304280442 8304270252 83042800115 8304280096 8304130245	50-318 8 50-254 8 70-1739 NUREQ 40-8502	SCHMATZ.T W SCHMELL.D F SCHMELL.D F SCHMELL.D F	8306240053* 8306240262 8306010110 8306070145* 8306100147	FOIA TOPREP 70-2945 50-483 (50-483 /		SEARS,C F SEARS,C F SEARS,C F SEARS,C F, SEARS,C.F	8306010340 8306010340 8306060078 8306060243 8306080058	50-213 50-213 50-336 50-213 50-245	4444
RUTLEDGE, C RUTLEDGE, C RUTLEDGE, C RUZICKA, W G RYAN, R H	B306160215 B3062001B2 B306240436 B306070364 B306240034#	40-8502 40-8502 40-8502 50-54 CONTRACT	SCHNELL, D F SCHNELL, D F SCHNELL, D F SCHNELL, D F SCHNELL, D F,	8306150455# 8306170279 830621019G# 8306230481# 8306270235	50-483 F 50-483 E 50-483 G 50-483 G 50-483 E	3 } }	BEARB,C F BEARB,J,R BEIDLE,W C BEIDLE,W C BEIDLE,W C	6304080058 6304080057* 6304010101 6304040043 6304070380	50-245 50-443 50-313 50-313 50-313	, Б С С С
RYBAK.B RYBAK.B RYBAK,B RYBAK.B RYBAK,B	8304040212* 8304040227 8304100149 8304130224 8304130425	50-254 G 50-237 P 50-237 G 50-249 P 50-237 P	SCHNELL, D.F. SCHNELL, D.F SCHOENBERGER, I SCHROCK, V.E SCHROCK, V.E	8306270585 8306300070# 8306200078 8306220270 8306220270	70-8945 50-483 Q 50-247 H ACRS ACRS		Beidle, W C Beidle, W C Beidle, W C Beidle, W C	8304080109 8304080184 8304080192 8304080231 8304080234	50-285 50-482 50-313 50-285 50-285	 0 0

AUTHOR	ACCESSION NUMBER	T) JUBUP CATEOOR	Υ	AUTHOR	ACCESSION NUMBER	SUBUL CATEGO	Pey	нантиа	ACCESSION NUMBER	SUBULC! CATEGOAY
SEIDLE.W C SEIDLE.W C SEIDLE.W C SEIDLE.W C	8306130117 8306140188 8306140207 8306140226 8306140245	50 285 50 407 50~482 50~72 50~487	6 6 6 6	SHEFFEA'M Y SHEFFEA'M Y SHEFFEA'M Y SHEDFORKA'Y I	BJ06060171 k BJ06090241 * BJ06130344 BJ06220140 BJ06240343	50 -245 50-245 40 -8027 40 -8268 10-8047	0	SILBERG, J E SILBERG, J E SILBERG, J F SILBERT, E J SILDERT, E J	8304200318 8304270214 8304270211 8306140789 8304200045	50~4BP C 50 440 G 50-440 G ADVCH ADVCH
SEIDLE, W C SEIDLE, W C SEIFFERT, S G SEIKEN, S J	6304140359 8304140524 8304300075 8304220134 8304030220	50~313 50~313 50~313 40~1162 50~482	9 9 8	SHELLEY, W J SHELLEY, W J SHELTON, K W SHEN, C N SHEPHERD, R L	B106300103 B106300155 B306010081 B306070473 B306060016*	PR PR NUREG NUREG NO 354	U	SILLING, 5 A SILVIS, R M SILVIS, R M SILVIS, R II SILVIS, R II	8306240060 8706140421 8306140433 8306210364 8306220151	NUM 0 CONTRACT CONTRACT CONTRACT CONTRACT
SEIXEN, S J SELAN, J C SELLB, D E SEMINARA, C	8306070345 8304070100# 8306100135* 8306020046 8306070373	50~402 50 277 50-237 50-335 FOIA	9 p p	SHEPHERD, R. I. SHEPHERD, R. I. SHEPPARD, V. J. SHEPPARD, V. J. SHEPPARD, V. J.	8304040023* 8304040027* 8304080247* 8304140284 8304140284	50-354 F 01A F 01A F OPREP T OPREP	G	SILVIS.R M SILVIS.R M SILVIS.R M SILVIS.R M SILVIS.R M	8 30422021 7 8304230 165 8 304230494 8304230503 8304230503	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT
SEMMEL, H SEMMEL, H SERIMI, B SERKIL, A W	8306010450 8306240423* 8306240423* 8306070274* 8306060418	50-155 50-155 50-155 70-2926 NURLO	6 e e	Sheppard, J Sheppard, J Sherbin, W Sherbini, S Sherman, C	8304220687 8304220087 8304130331* 8304240384 8304280145*	1 OPREP TOPREP 50-329 NUREG 50-528	E G	SIMAN-TDV. I SIMCHUK, J D SIMON, J A SIMONEAUX, F P SIMONEN, E P	830&28009) 830&030135 830&090245* 830&150480* 830&020134	NUREG 71 9159 50-309 0 CONTRACT NUREG
SERKIZ.A W SERKIZ.A W SERWE.R J SERRAND.W SESTAK.F	9304040413 8304140198 8304020217 8304080141 8304100171*	NUREO GEN TEC 1 HASTE MO1 50-235 50-275		SHERR, T S SHERR, T S SHERR, T S SHERWOOD, G G SHERWOOD, G G	8304140218 8304140166* B306210348 8306070105 B306070111*	50~266 FOIA 50-199 50-44/ 50-44/	r K K	SIMONS, D B SIMPSON, J M SIMPSON, J M SINCLAIR, J D	8306210386* 8306080161 8306290522 8306290522 8306020174	(BNTRACT 50 335 P 50-482 C 50 271 P
Sestan.f Sestak.f Sestak.f Setka.g e Sewell.r b	8304290397 8304290401* 8304290545* 8304170354* 8112090561	50-275 50-275	R R R R P S	SHERWOOD, G G SHERWOOD, G G SHERWOOD, G G SHERWOOD, G G	6304070201 8304070234 8304100092 6304170214 8304200255	50-447 50-447 50-357 50-447 TOPREP	K A B A	BINGLAIR, J B BINGLAIR, J B SINGLAIR, J B BINGLAIR, J B SINGLAIR, J B	0306030)12 0306140205 0306200077 0306220044 0306240170	50 271 P 50 271 P 50 271 1 50-271 P 50 271 P
SHABER, C R SHACKLETON, B C SHACKLETON, D C SHACKLETON, D C	8306160641* 8306280096 8306100040* 8306160230* 8306160263*	NURFG 50-312 50-206	P G G	SHERMOOD. & G SHERMOOD. & G SHERMOOD. & G SHERMOOD. & G	830 6270481 830 6270475 830 6270507 830 6306131 830 6060037	50-447 50-447 50-447 NURFG 50-546	K K K	SINCLAIR, J R SINISI, J M SINKIN, L SINKIN, L SINKIN, L A	8/306080304# 8/306020128 8/306230287 8/306080150 8/306080155#	50-490 0 70-244 J 50-29 J 50-490 0 50-490 D
SHAFER, J C SHAFER, W SHAFER, W SHAFER, W SHAFER, W	8306230277 8306130327 8306160264 8306220060 8306270279	50-331 50-306 50-295	ម ទ ទ ទ	CHIEFOR'S M CHIEFOR'S M CHIEFOR'S M CHIEFOR'S M	8306070144# 8306070147# 8306070377 8306140596 8306170182	50-546 50-546 50-546 50-546 50-546	0 8 A U	SINKIN.L A SINKIN.L A SITLER.P SITLER.P SIU.N O	8306080157* 8706220057 8706220074 8706290526 8306140774	50-498 6 50-498 6 50-322 0 50-327 H NUREO
SHAFER.W D SHAFER.W D SHAFER.W D SHAFER.W D SHAFER.W D	8306060218 8306060217* 8306060247 8306090316 8306210057	50-275 50-263 50-331	0 0 0 0	SHIFLDS.8 W SHIFLDS.8 W SHIFFER.J D SHIFFER.J D	8304270138 8304270219 8304270375 8304100047 8304100082	50 546 50-546 50-546 50-275 50 275	R 6 8 8	BIU.N D BJOREEN.A L SKARITKA.J SKARITKA.J SKARUPA.J D	8306210334* 8306210390 8306200402* 8306200402* 8306150462	FGTA NURFG 50-/96 P 50-/96 P XPURTL1C
SHAFER, W D SHAFER, W D SHAFER, W D SHAFER, W D SHAFER, W D	8304210095 8304270215 8304270220* 8304270381 8304270385*	50-373 50-373 50-409	0 G G G	SHIFFER.J D SHIFFER.J D SHIFFER.J D SHIFFER.J D SHIFFER.J D	8306210044 8306210078 8306230365 8306230422 8306280421	50-275 50-275 50-275 50-275 50-275	6 6 6 6 6 6	SKINNER,P H SLAVINSKI,W SLOCUM,L SMEDIRA,C SMEDLEY,R	8306140471* 8306230246 8306040307* 8306240341 8306270388	50 395 - 0 1& 70 -25 71-5364 50~289 - 0
SHAFER, W D SHAFER, W D SHAFER, W D SHAFER, W D SHAFER, W D	8906300014 8306300026 8306300127 8306300135% 8306300197	50-37J 50-373 50-378	0 9 9 0	SHIFFER, J D SHIFFER, J D SHINGLETON, H SHINGLETON, D	8306280523 8306280524 8306210164 8306140046 8306200171	50-275 50-275 50-275 50-416 50-416	ម ១ ១ ម	SMITH.A L SMITH.B SMITH.D SMITH.D G SMITH.G C	B306130422* B306060307* B306060326 B306010190 B306010327*	0A979 70-25 40-8641 NUHEQ 50-334 Q
SHAFFER.J D SHAFFER.R SKANBAKY.M SHANBAKY.M SHANBAKY.M	8306240318* 8306200276 8306020264* 8306060267* 8306090036*	40-8380 71-250	3 9	SHINGLETON, I H SHIRAKAWA, T SHOEMAKER, B SHOEMAKER, C J SHOEMAKER, C J	8306140667 8306150468 8306080326 8306020361 8306060276	50-416 XPURTUIC 71-7017 50-443 50-341	0 0	SMITH, G C SMITH, G C SMITH, H D SMITH, I W SMITH, I W	8'+06030317* 8306230475* 8306230463* 8306230294 8306230332	70-371 50 273
SHANBAKY, M SHANBAKY, M SHANBAKY, M M SHANBAKY, M M SHANBAKY, M M	8306230467* 8306280474* 8306020416* 8306020447*	50-033 50-271 50-273 50-244 50-219	3 3 3	SHOEMAKER, C J SHOEMAKER, C J SHOEMAKER, C J SHOEMAKER, C J SHOEMAKER, C J	8304069330 8304070394 8306090307 8304270284 8306300052	50-357 5 <i>0-409</i> 50- <i>209</i> 50-209 50-275	6 C 0 0	W I.HTIMB U I.HTIMB U L.HTIMB J L.HTIMB J L.HTIMB	0306230355 0306230362 0306010011 0306010432 0306020455	50-454 6 50-454 0 50-320 8 50-322 8
SHANBAKY, M M SHANBAKY, M M SHANBAKY, M M SHANBAKY, M M SHANK, K E	8304020446* 8304140348* 6304230214* 8304230388* 8304270253*	50-244 (50-220 (50-334 (50-317 / 50-387 /) } }	SHOEMAKER, C J SHOLLY, S C SHOD, R J SHODP, P SHOPENN, N N	8306306134 8306080029 8306280552 8306080075 8306080165*	50 409 101A 50 155 ADVCM 40-8027	G Ø	L C'HILMS T C'HILMS T C'HILMS T C'HILMS T C'HILMS	8304070013 8304070038 8304070321 8304130324 8304130324	50 92P L 50 92P 0 50 92P 0 50 92P A 50 92P E
SHANNON, J B SHAPIRO, J SHAPIRO, R SHARP, I H	8304070454 8009030104# 8304170295# 8304150378 8304070023	40-8064 FOIA FOIA 50-329 G	,	SHORT, R H SHOTWELL, J A SHREVE, D B SHUEY, C SHUEY, C	9396209210* 8396970411 8396229327* 9396169465 9396399219	50-344 50-443 CONTRACT PRM PR	Ö	L HTIMB L HTIMB L HTIMB L HTIMB L HTIMB	0306140607 8306140737 8306140097# 8306160100% 8306240230	50-322 E
SHARP.1 M SHEA.J F SHEA.J J SHEA.J J SHEA.J R	8304210318 8304280408* 8304280406* 8304130354 8304140107*	FOIA 50-322 G 50-322 G 50-245 P FOIA		SHUTTLEWDRTINW SHYMLOCK, W D SIEBER, J D SILBERG, J C SILBERG, J E	B304210127 B304140447* B304100104 B304160593 B304160593	50~334	A G G G	THINB L CHITH'S T CHITH'S THINB THIN	8306240250 8306280042* 8306280265 8306280445	50-322 E 50-322 F 10-324 0 50-322 E 50-322 E
SHEALY, H G SHEARER, L N SHEARER, V M SHEARER, V M	8306030167 8306150251* 8306130349 8306080203 8306080205*	50-331 U CONTRACT 50-373 B 50-358 G 50-358 G		SILBERG, J E BILBERG, J E SILBERG, J E SILBERG, J E SILBERG, J F	8306160574 8306160576 830616061 830616061 8306800310	50-440 50-440 50-440	0 4 0 0	SMITH, M SMITH, M SMITH, N SMITH, P A SMITH, P A	8306020274 8306130412x 8306160670* 8306030266+ 8306030271*	40 8064 50-254 0 71-9134 CONTRACT CONTRACT

AUTHOR	ACCESSION NUMBER	SALE GUSA	AUTHOR	ACCESSION NUMBER	GUDJEC		AUTHOR	ACCESSION NUMBER	SUBJECT CATEOUR)
SMITH, PA SMITH, PA SMITH, PA SMITH, PA	8306080067 8306080072* 8306080417* 8306090277 8306090280*	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT	SPITZBERG, D N SPITZBERG, D N SPITZBERG, D N SPULAK, R G SQUIER, S	83060801654 83060901754 83060901794 82112203374 8306080194	40-8084 40-8663	1	STAROSTECKI, R STAROSTECKI, R STAROSTECKI, R STAROSTECKI, R STAROSTECKI, R	8306140617 8306140625 8306140628 8306140630 8306140635	50-309 50-199 50-170 50-134 50-223
SMITH, PA SMITH, PA SMITH, PA SMITH, PA SMITH, PA	8704070284* 8304170466* 8304200134* 8304200289* 8304210374	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT	SRENIAWSKI, D SRENIAWSKI, D STACK, D STAPLETON, B W STAPLETON, B W	8306130265 8306230246 8211220337* 8706108097* 8306218875*	50-155	P G O	STAROSTECKI, R STAROSTECKI, R STAROSTECKI, R STAROSTECKI, R STAROSTECKI, R	8306140651 8306140657 8306140663# 8306140665 8306140673	50-54 50-293 50-412 50-333
SMITH, PA SMITH, PA SMITH, PA SMITH, PA SMITH, PA	9306210384* 9306220130* 9306220280* 9306230497 9306230501*	CONTRACT CONTRACT CONTRACT 50-320 P 50-320 P	STARK, R N STARK, R M STARK, R M STARKCY, R B STARKEY, R D	8306070436 8306070462 8306290570 8306070161 8306070182	50~537 50~537 50~537 50~261 50~261	A A A 4 B	BTARDSTECKI, R STAROSTECKI, R STAROSTECKI, R STAROSTECKI, R STAROSTECKI, R	8306140697 8306140714 8306140741 8306150005 8306150237	50-423 50-220 50-317 50-57 50-289
SMITH, PA SMITH, PA SMITH, RD SMITH, RD SMITH, RD	8306280127 8306280133* 8306020305 8306020331 8306020330	CONTRACT CONTRACT 40-0381 40-0586 40-0502	STARKEY,R D STARKEY,R D STARKEY,R D STARKEY,R D STARKEY,R D	8306140405 8306160420 8306200002 8306200109 8306200188	50-261 50-261 50-261 50-261 50-261	R R S S	STAROBTECKI,R STAROBTECKI,R BTAROSTECKI,R STAROBTECKI,R STAROBTECKI,R	6304150349 6304140003 6304140130 6304140236 6304140236	50-352 50-412 50-271 50-272 50-193
SMITH, R D SMITH, R D SMITH, R D SMITH, R H SMITH, R H	0304020503 0304020515 0304170440 0304010304* 0304200210*	40 - 134 1 6 0585 0 - 3453 50 - 213 0 50 - 213	STARMER,R J STAROSTECKI.R STAROSTECKI.R STAROSTECKI.R STAROSTECKI.R	8306240486 8306010121 8306010310 8306010365 8306010442	WASTE MO 50-387 50-317 50-247 50-443	10 0 0 0	STAROSTECKI, R STAROSTECKI, R STAROSTECKI, R STAROSTECKI, R STAROSTECKI, R	8306160361 8306160483 8306170226 8306170325	50-219 50-244 50-277 50-247 50-293
SMITH,R O SMITH,W O SMITH,W O SMITH,W O SMITH,W O	8306090224 9010204018 4810204028 8306060183 8306060269	40-8452 50-315 R 50-316 R 50-315 S 50-316 S	STARDSTECKI.R STARDSTECKI.R STARDSTECKI.R STARDSTECKI.R STARDSTECKI.R	0304030282 0304030291 030404068 0410404068	50-309 50-27/ 50-334 50-245 70-364	0 0 0	STAROSTECKI.R STAROSTECKI,R STAROSTECKI,R STAROSTECKI,R	8304200138 8304200174 8304200221 8304200330 8304200343	50-271 70-1143 50-333 50-77
SMITH, W G SMITH, W G SMITH, W G SMITH, W G SMITH, W G	830616034() 8306160384 8306210038 8306210126 8306210259	50-315 R 50-316 R 50-315 S 50-315 S 50-315 S	STAROSTECKI.R STAROSTECKI.R STAROSTECKI.R STAROSTECKI.R STAROSTECKI.R	8306060200 8306060210 8306060217 8306060223	50~334 50~423 50~322 50~219 50~220	a a o a	STAROSTECKI, R STAROSTECKI, R STAROSTECKI, R STAROSTECKI, R STAROSTECKI, R STAROSTECKI, R	83042300361 8304230075 8304230114 8304230195 8304230203 8304230317	50-29 50-271 70-820 50-244 50-247
SMITH, W G SMITH, W G SMITH, W G SMITH, W G SMITH, W G	8306270150 0366270161 0366270437 8306270444* 0306300035	50-314 8 50 314 8 50 315 8 50 315 8 50-315 8	STARDSTECKI.R STARDSTECKI.R STARDSTECKI.R STARDSTECKI.R STARDSTECKI.R	8306060230 8306060257 8306060265 8306060265 8306070046	50-3/33 900-07 030-08 230-08 489-08	0 0 0 0	STAROSTECKI, R STAROSTECKI, R STAROSTECKI, R STAROSTECKI, R STAROSTECKI, R	8305230399 8305230415 8305280164 8305280170	50-244 50-443 50-412 50-271 50-271
BMITH.W P SNOW.B A SNOW.B A SNYDER.B J	8306080316# 8306130412# 8306080274 0306160485 0306030490	50-148 P 50-254 0 50-244 H 50-244 R 50-260 P	STAROSTECKI.R STAROSTECKI.R STAROSTECKI.R STAROSTECKI.R STAROSTECKI.R	8304070223 8304070344 8304090067 8304090140 8304090238	50-277 50-271 50-32 <i>p</i> 50-352 50-245	0 0 0 0	STARDSTECKI.R STARDSTECKI.R STECKEL.A STEED,L.S STEFANO,J J	8306280347 8306280492* 8306280586 8306080258 8306300210	50-77 50-334 50-354 FOIA 50-334
SNYDER, B J SNYDER, B J SNYDER, B J SNYDER, H L SNYDER, H L	8706150460 8306220161 8306280074 8306040415 8306140687	59-320 H 50-320 P 50-320 P 40-8584 40-8584	STAROSTECKI,R STAROSTECKI,R STAROSTECKI,R STAROSTECKI,R STAROSTECKI,R	8304090358 8304140017 0306140032 8304140044 8306140055	50-271 50-307 50-271 50-412 50-293	0 V V	STEIN, M H STEIN, M H STELLO, V STELLO, V STELLO, V	8306080437 8306060005* 8306060025* 8306060303 8306080207	FOIA FOIA FOIA REVIEW OR REVIEW OR
SOKOLSKI,H D SOMERVILLE,K G SOONG,A SOONG,A L SOONG,A L	8306140148# 8306210353 8306140446# 9306030175 8306170435	FD1A 40-8783 40-8794 70-143 70-120	STAROSTECKI.R STAROSTECKI.R STAROSTECKI.R STAROSTECKI.R STAROSTECKI.R	83061 40062 83061 40074 83061 40098 83061 40104 83061 40147		V V V 9	STEPLE, V STEMPLE, P J STEPHENS, T R STEPHENSON, C J STEPHENSON, C J	8304280370 8304280370 8304030254* 9304210038 93040353	REVIEW OR CONTRACT 50-315 50-289
SOUSA, M SOUTHERN, R L SPAISMAN, B II SPANG, J R SPECTOR, R	830430021*7 830414044*7 8304280133* 8304280532 8304200035	PR 71-86 CONTRAC (50-289 () 1014	STARDSTECKI,R STARDSTECKI,R STARDSTECKI,R STARDSTECKI,R	0'1061 401 40 83061 401 52 83061 401 58 83061 401 70 83061 40224	50−184 50−333 50−299	V V G V	STEPHENSON, C J STEPHENSON, C J STEPHENSON, C J STERN, P	8306200127 8306210254* 8306210258* 8306280365 8306100191 8306100192*	50-289 50-289 50-289 50-209
SPEER.M SPCIS.T P SPCIS.T P SPELL.W H SPELMAN.H J	8384460455 8112930545# 8386910166 8386138336 83861383273	50-206 R 50-498 A NURLG State Prog 40 2061	BTAROSTECKI.N STAROSTECKI.R STAROSTECKI.R STAROSTECKI.R STAROSTECKI.R	83061 40231 83061 40243 83061 40248 83061 40255 83061 40256	50 244 5077 50225	v v a v	STERN, P STERN, P STERNBERG, D STERNBERG, D STERNBERG, D	8304100204 8304180205* 8304020097 8304070005	50-309 50-309 50-397 50-328 50-344
SPELMAN, N J SPENGER, D SPENGER, D A SPENGER, M SPENGER, M	8304200042 8304220017 8304210045 8304080215 8304080250	40-P061 50-373 G 50-373 G 50-358 G 50-358 G	STAROSTECKI.R STAROSTECKI.R STAROSTECKI.R STAROSTECKI.R STAROSTECKI.R	0306140278 8306140291 8306140322 8306140332 8306140331	50-286 50-410 50-322	V V G	STERNDERO, D M STERNBERO, D M STERNBERO, D M STERNBERO, D M BTERNBERO, D M	8304070057 8304070075 8304070252 8304070254 8304070364	50-344 50-344 50-528 50-508 50-312
SPENCER, W C SPESBARD, R L SPESBARD, R L SPESBARD, R L SPESBARD, R L	8306300036 8306060208 8306070137 8306070139 8306070388	50-404 Λ 50-254 Θ 50-483 Θ 50-546 Ω 50-454 Θ	STAROSTECKI.R STAROSTECKI.R STAROSTECKI.R STAROSTECKI.R STAROSTECKI.R	8306140370 8306140403 8306140441 8306140443 8306140447	50-272 50-410 50-77	y v a v	STERNBERG.D M STERNBERG.D M STERNBERG.D M STERNBERG.D M	8304100032# 8304100036# 8304100047# 8304170216 8304170425	50-308 50-308 50-312 50-312
SPESSARD, R SPESSARD, R SPESSARD, R SPESSARD, R SPESSARD, R	1906160391 0306230016 030623608 03062368 0306230290#	50-373 0 50-403 0 50-341 0 50-454 0 50-454 0	STARDSTECKI, R STAROSTECKI, R STAROSTECKI, R STAROSTECKI, R STAROSTECKI, R	83061 40453 83061 40467 83061 40494 83061 40518 83061 40523	50-245 \ 50-5 \ 50-022 (50-443 \ 50-29 (, ,	STERNBERO, D M STERNBERO, D M STERNBERO, D M STERNBERO, D M	8306210240 8306280207 8306280218 8306280333 8306280334	50-397 50-397 50-397 50-312 50-344 50-397
SPESSARD, R I SPIELES, P R SPIELES, P R SPINOSA, E SPINOSA, I	8306270112 8306160327 8306160367 8306230084# 8306230085#	50-440 () 40-8497 40-8380 FDIA FDIA	STAROBTECKI, R STAROSTECKI, R STAROSTECKI, R STAROSTECKI, R STAROSTECKI, R	83061 40531 83061 40536 83061 40551 83061 40553 83061 40554	50 20 \ 50-277 \ 50-57 \ 50-97 \ 50-410 \	, ,	Sternberg, D M Sternberg, D M Sternberg, D M Sternberg, D M Sternberg, D M	8304280371 8304280405 8304280450 8304280515 8304280514	50-397 50-508 50-528 50-528 50-397

AUTHOR	ACCESSION NUMBER	CATEG		AUTHOR	ACCESSION NUMBER	SUBJE CATEG		AUTHOLE II CHETUA	ACCESSION NUMBER	SUBJE CATEG	
BTERNBERG, D M STETKA, T F STEVENS, D L STEVENS, J L STEVENS, J L	830630007 8306140469# 8306020134 8306020425 8306030341	50-312 50-302 NUREQ 50-307 50-309	9 9 8 9	STOLZ.J F STOLZ.J F STOLZ.J F STOLZ.J F STOLZ.J F	830422031E 8304240469 8304240474 8304280034 8304280034	50-313 50-278 50-289	р Р Р	TAYLOR, J H	8304210295 8304220007 8304280337 8304300159 8304300220	10PREP 50 .187 10PREP 50~438 50~269	; ; ; ;
STEVENSON, M Q STEVENSON, R L STEWART, E C STEWART, J P STEWART, P	9306020173 9306140374 9306240207* 9306280561*	NUREQ XPDRTL1 QA999 50-361 50-361	0 0	STOLZ.J F STRAUDE.M STREETER.J I STREETER.J I STREETER.J I	8304280156 8304220042 8304070155 8304100162 8304100172	50- <i>289</i> 50~346 50-483	9 9 9	TAYLOR, J J TAYLOR, J M TAYLOR, J M TAYLOR, J M TAYLOR, P A	8306170333 8305110458 8306240059 8306270295 8306140171*	NUBEG 50-3 50-498 50-309 50-389	Q A
STEWART, W L STEWART, W L STEWART, W L STEWART, W L	8304020072 8304020157 8304020424 8304070148 8304080225	50-338 50-280 PR 50-339 50-338	R R S P	STREETER, J T STREETER, J F STREETER, J F STREETER, J F STREETER, J F	8306100174 8306100244 8306100245 8306100247 8306130258	50~454 50-373	0 0 0 0	TAYLOR, P A TEDESCO, R L TEDFORD, C F TEKIN, J V TEMPLE, G	8306270404* 8204070017* 8306210432* 8306080256 8306280507*	50-417 50-508 (ONTRAC FOIA 50-39/	Ä
STEWART, W L	9306100170 9306140209 9306160247 9306160375 9306160379	50-280 50-338 50-338 50-280 50-338	p p R F	STREETER, J F STREETER, J F STREETER, J F STREETER, J F STREUTKER, G R	8306130263 8306230274 8306230418 830630006 8306070453	50-315 50-266 50-374 50-346 71-9182	a a a a	TEMPLE, G M TERC, N M TERMIN, A TERRELL, C W TETZLAFF, A I	B306070337* B3060203B7* B306270501 B306280569 B306160367*	50~206 50~244 50~322 50~112 50~315	0 H P
BTEHART, W L	B304140405 B30417013B B3041702B1 B304170327 B304200219	50-338 50-281 50-280 50-280 50-280	9 9 9 9	STROHM. WE STRONG. A B STRUCKMAYER. R STUCKY. S W STUNKEL. C B	830601 0266 830601 0266 8306280484* 8306060307 830601 0081	NUREQ NUREQ 50~273 70~25 NUREQ	q	TETZLAFT, A L THADANI, M THEEMAN, B A THIES, A C THOM, T	B3061603B4 B306030054* B306150177 B3061604B2	50-316 50-460 CONTRAC 50-369 50-259	R
STEWART, W L STEWART, W L STEWART, W L STEWART, W L STEWART, W L	9306220033 9306270214 9306270331 9306270397* 9306270561	50-280 50-338 50-280 50-338 71-5450	P G G	STURKEY: J J BUDIN, R BUERMANN, J I BUGARMAN, R J BUGARMAN, R J	8306230351* 8306200274 8306200185 8306220051 8306220051	50~331 40~8380 50~269 50~352 50~352	P G G	THOMAS.C 0 THOMAS.C 0 THOMAS.C 0 THOMAS.C 0 THOMAS.C 0	8306020612 8306020616 8306020702 8306070466 8306070460*	50-128 50-189 50-199 MISC MISC	p p f
STEWART, W L STEWART, W L STICKLEY, T H STIEDE, W L STIEDE, W L	8306300074 8306300147 8306300240 8306030086* 8306240252	50-338 50-280 50-338 50-397 50-374	Р К Р А	SUGARMAN, R. J. SULLIVAN, J. M. SULLIVAN, P. J. SUMMERS, R. SUMMERB, R. J.	6306220103 6306270230* 6306140691 6306230334 6306160144*	50~352 50~324 NUHEG 50~311 50~272	6 6 9	THOMAS, C O	8304090457 8304140202 8304150121 8304200049 8304200070	10PREP MISC 10PREP 50~456 50 -470	A L
STIMKROTH,T J STOETZEL,G A STOHR,J STOHR,J P	9306300032 9306270298 9306020053 8306270433 8306060114	50-374 50-322 NUREQ 70-1151 70-1151	A H	GUMNER.L SUNDAHL.J A SUNDIN.R E SURNER.J J SUTHIM.R N	8306150141# 830620036 8306200160 8306130303 8306130273#	50-321 40-8714 40-6697 50-410 50-315	f G	THOMAS.C O THOMAS.C O THOMAS.C O THOMAS.C O THOMAS.C O	8306200154* 8306210333 8306210333 8306220216 8406220230	50-07 50-166 50 <i>074</i> 50-131 50 42	ז ר ר
P、SHOTE P、SHOTE P、SHOTE P、SHOTE P、SHOTE P、SHOTE	8306040124* 8306140109 8306140317 8306140342* 8306140527	70-115J TOPREP 70-1113 70-1113 70-1201		N L, NOTTUB BYENSON, B A BYAN, W BYAN, C A BYAN, C BYAN, C A	8306270456* 8306020186 8306140434* 8306140580* 8306020238	9A999 50~314 50~390 50~390 40 6610	П О	THOMAS, C D	8306220240 8306220276 8306227007 8306270250 8306270403	50-87 50-224 50-147 50-116 50-192	Γ 6 0 Γ
4 C.SHOTE 4 C.SHOTE 5 C.SHOTE 4 C.SHOTE	8306140548 8306140574 8306140607 8306140700 8306150264	70-1113 70-1113 70-824 70-143 70-143		SWANSON,E A BWARTZ,E D SWARTZ,E D SWARTZ,E D SWARTZ,E D	8306020243* 8306030225 8306030227 8306100246 8306170045	40~8610 50~454 50~454 50~454 50~454	6 6 9	THOMAS, D. C.	8304020437 8304150408 8304150408 8304200320 8304200320	50-454 50-454 50-454 50-454 50-454	0 0 0
BTOLEA, F E STOLZ, J STOLZ, J. F STOLZ, J. F	8304040080# 8304040080# 8304010054 8304020103 8304020188	50-528 50-287 50-244 50-249 50-3 0 2	Б Р Р Р	GWARTZ, E D SWARTZ, E D SWARTZ, L L SWARTZ, L L SWARTZ, L L	8308230294 8308280502 8308170394 8308170394 8308220088		А Г С С С	THOMAS, D C	8306200327# 8306200327# 8306200327# 8306200327#	50~454 50~454 50~454 50~454	C C C C
STOLZ: J F STOLZ: J F STOLZ: J, F STOLZ: J, F	8306020317 8306020325 8306020543 8306030073 8306030096	50-312 50-277 50-302 50-313 50-277	P P F F	SWARTZ.L L SWARTZ.L L SWARTZ.L L SWARTZMAN.G I SWYLER.K J	B306270280 B306270280 B306270505 B306140691 B306016080	50-322	С С С	THOMAS.D C THOMAS.D C THOMAS.D C THOMAS.D C THOMAS.D C	8306200331# 8306200331# 8306200331* 8306200215	50 -454 50 -454 50 -454 50 -454	0 0 0
STOLZIJ F STOLZIJ F STOLZIJ F STOLZIJ F STOLZIJ F	8304030110 8304030127 8304030132 8304030239 8304030253	50-302 50-302 50-366 50-302	р Р Г Р	BWYLER,K J BZAHLEHICZ,B A BZUKIEWICZ,A J TAFT,E P TAFT,E P	8304020044 8304040395# 8304070427 8304080298# 8304080303#	50~410	ቦ ለ ለ	THOMAS, D M THOMAS, H J THOMAS, J THOMAS, M THOMAS, M	B306210342 B306170205# B306060220# B306140362# B306270511#	F D1A RES 50~2(9 50~390	¢ g g
STOLZ, J. F. STOLZ, J. F STOLZ, J. F STOLZ, J. F STOLZ, J. F	8306080234 8306080375 8306080402 8306070373 8306140703	50-207 50-269 50-312 50-346	ም ወ ም P	TAFT, E F TAFT, E P TAFT, E P TAFT, E P TAFT, E P	8306080306* 8306080320* 8306080343* 8306080351* 8306080360*	50-410 50-410 50-410	Λ Α Λ Λ	THOMAS, H THOMAS, R D THOMAS, W V THOMAS, W V THOMASON, P, V	8304270519* 8304280458* 8304280075 8304240373 8304240339	50-369 70-115 50-263 NURES	a o o
STOLZ, J, F STOLZ, J, F STOLZ, J, F STOLZ, J, F STOLZ, J, F	83041 407 51 83041 50286# 83041 50297 83041 50324 83041 50484#	50-302 50-289 50-289 50-366	P P O P	TAM.P. B. TAMO HEE.D. TAMO,R. C. TAUBER.H. TAUBER.H.	8304090190 8304040232 8304240109 x 8304030171 8304140357			THOMASON, P V THOME, F J	8306160477 8306160488 8306160494 8306270163	50-290 (50-290 (50-290 (50-290 (0 N N O B
STOLZ, J, F STOLZ, J, F STOLZ, J, F STOLZ, J, F STOLZ, J F	B306150499 B306150504 B306150508 B306150519 B306150621	50-287 50-344 50-313	ም የ የ የ የ	TAUBER, H TAUBER, H TAYLUR, II C TAYLUR, O J TAYLUR, O J	9305280438 9305280585 9305090165 9305020142 9305160570	50-341 A 50-341 F 50-302 S 50-375 R 50-375 R	<u>}</u>	THOMPSON, A F THOMPSON, D, THOMPSON, D THOMPSON, D THOMPSON, B	8306240057* 6306060030* 8306290546 8306290546	NUREG CONTRACT COIA 50-142 C	
STOLZ, J, F STOLZ, J, F STOLZ, J, F STOLZ, J, F STOLZ, J, F,	8306170471 8306200059 8306220219 8306220224 8306220275	50-313 (50-321 (p p p p	TAYLOR, J H TAYLOR, J H TAYLOR, J H TAYLOR, J H TAYLOR, J H	8304070280 x 8304070280 x 8304100090 8304140377 8304170192	50-269 P 50-269 P 50-312 S 50-269 P RE8		THONUS, L. THONUS, L. THORNBERRY, R (THORNBERRY, R C THORNBURGH, D	9306060266# 930615000B# 9306020214 9306160535	NUREO 50-320 0 50-289 0 50-275 R 50-289 6) ? }

Description	AUTHÜR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	BUBJECT CATEGORY	AUTHOR	ACCEBBION NUMBER	SUBJE CATEO
MALL 0	THORNTON, P THORBEN, E O	8306220105 8306270371 8306200098	50-155 g 50-296 g 50-247 H	TRAMM, T R TRAMM, T R TRAMM, T R TRAMM, T R	8306230385 8306230412 8306270322	50-454 G 50-454 F 50-454 A	TUCKER, H B TUCKER, H B TUCKER, H B TUCKER, H B	8306240183 8306270094 8306270118 8306270124	50-413 50-369 50-413 50-369
Internation Section	THULL, T S THULL, T S THULL, T S	8304030326 8304170046 8304270129	50-245 8 50-245 S 50-245 8	TRAPP,D TRAPP,D TRAVIS,W H	9306140210 9306240370 9306240033	PROJ PROJ 71-5595	TUCKER.H D TUCKER.H D TUCKER.H B	8306270301 8306270384 8306280427	50-369 50-369 50-413 50-369
Types	TIFFANY, J A TIMO, D P TIMO, D P	8306200215* 8306176307* 8306270220*	50-344 1 50-269 0 50-440 0	TREBY,S A TREBY.S A TREBY,S A	8304080218 8304080230 8304190118	50-445 G 50-445 G 50-445 G	TUCKER, H B TUCKER, H B TUCKER, H B	8304300002 8304300015 8304300114	50-349 50-287 50-370
TIPPE B B B B B B B B B	TIPPS, B B TIPPS, S B TIPPS, S B TIPPS, S B	8306070060 8306070257 8306070347 8306130264	50-321 8 50-364 9 50-321 8	TRENERY,8 E TRIMBLE.D C TRIPP,L E	8306270131 8306010324# 8306060021#	NUREG 50-317 G 50-354 G	TUCKER, H B TUCKER, H B TUCKER, H B	8306300189 8306300191 8306300232	50-370 50-369 50-370
Type: B	TIPPS,S B TIPPS,S D TIPPS,S D TIPPS,S D	8306200202 8306200205 8306200261 8306200374	50-321 S 50-366 S 50-321 B 50-321 S	TRIPP,L E TRIPP,L E TRIPP,L C	9306160054 ***********************************	50-277	TUCKER, M K TUITE, P T TULODIESKI, D	8306210428 8306030476 8306270069*	40-134 HABTE (50-329
TGRIN, IJ SELACYTOOLS SC-250 TURKER, I B SELACYTOOLS SC-250 SC-	TIPPS, B B TIPPS, B B TIBCHLER, L F TKACHYK, J W	8306280361 8306280468 8306280227* 8306270157	50-321 6 50-344 8 CONTRAC1 NUREG	TROTT, E TRULTT, M O TBAL, Y, J	8306220282* 8306200273 8306080294*	CONTRACT FOIA 50-410 A	TURK, B. E TURK, B. E TURK, B. E	8306100043 8306150311 8306150315	50-537 50-537 50-537
TOTAL AL J. SIGNAPOTO N. P. C. T. TOCKER, H. B. BOSCADOLA S. D. S.	LOBIN'M A LOBIN'M A LOBIN'M A	8306070061* 8306170162* 8306010068 8306010099	50-250 0 50-369 0 50-367 S	TUCKER, H B TUCKER, H B TUCKER, H D	8304010098 8304010104 8304010123	50~369 8 50~370 8 50~369 8	TURKETT, J TURNER, D TURNGDEST, L	6306010374* 6306200097 6306130346	50-395 50-546 50-237
TOMER IN 9. B A G306400328 50-299 0 TUCKER II B G30670313 50-265 P URITOR R E G30640077 30-267 P URITOR R E G3064007 30-267 P URITOR R E G30640007 30-267 P URITOR R E G3064000 30-267 P URITOR R E G306400 30-267 P URITOR R E	TOMAN.G J TOMECSKO.M TOMECSKO.P TOMLINSON,D P	8302250381* 8306230091* 8306230094* 8306060122*	50-336 P F01A F01A	TUCKER, H B TUCKER, H B TUCKER, H B	8306030300 8306030300 8306030300	70~2985 50~269 P 50~413 A	UDERITZ,R A UDERITZ,R A UDERITZ,R,A	8306030349 8306070177 8306140261#	50-272 50-272 50-272
TOMER, R. A	TOMPKINS.B A TOMPKINS.B A TOMPKINS.B A	83042200328 8304220077	50-289 G 50-443 G 50-443 G	TUCKER,H B TUCKER,H B TUCKER,H B	8306070091 8306070131 8306070143	50~269 P 50~369 P 50~369 S	UHRIG,RE UHRIG,RE UHRIG,RE	8306030074 8306060082 8306080004*	50-369 50-369 50-250
TONER, K. A. 6396.1309.31 50-155 P TUCKER, H. B. 6396.0700.13 50-270 B UNRIO, R. E. 8396.1400.17 50-280 TUKER, K. A. 6306.1303.34 50-255 F TUCKER, H. B. 6396.0701.47 50-270 B UNRIO, R. E. 8396.1400.17 50-280 TUKER, K. A. 6306.2003.27 50-155 P TUCKER, H. B. 6396.0701.47 50-270 B UNRIO, R. E. 8396.1400.17 50-280 TUKER, K. A. 6306.2003.27 50-155 P TUCKER, H. B. 6306.0701.47 50-280 F UNRIO, R. E. 8396.1400.17 50-280 TUKER, K. A. 6306.2302.17 50-155 P TUCKER, H. B. 6306.001.20 S 0-270 B UNRIO, R. E. 8396.1400.17 50-280 TUKER, K. A. 6306.2302.17 50-155 P TUCKER, H. B. 6306.1001.20 S 0-270 B UNRIO, R. E. 8396.1401.17 50-389 TUKER, K. A. 6306.2702.76 50-155 P TUCKER, H. B. 6306.1001.20 S 0-270 B UNRIO, R. E. 8396.1405.20 S 0-230 TUKER, K. A. 6306.2702.76 S 0-155 P TUCKER, H. B. 6306.1001.20 S 0-270 B UNRIO, R. E. 8396.1405.20 S 0-230 TUKER, K. A. 6306.2702.76 S 0-155 P TUCKER, H. B. 6306.1002.14 50-270 B UNRIO, R. E. 8396.1405.20 S 0-230 TUKER, K. A. 6306.2702.76 S 0-155 P TUCKER, H. B. 6306.1002.14 50-270 B UNRIO, R. E. 8396.1405.20 S 0-230 TUKER, K. A. 6306.2702.77 S 0-155 P TUCKER, H. B. 6306.1002.14 50-270 B UNRIO, R. E. 8396.1405.20 S 0-230 TUKER, K. A. 6306.2702.77 S 0-155 P TUCKER, H. B. 6306.1002.14 50-270 B UNRIO, R. E. 8396.1407.45 B 0-230 TUKER, K. A. 6306.2702.77 S 0-155 P TUCKER, H. B. 6306.1002.14 50-270 B UNRIO, R. E. 8396.1407.45 B 0-230 TUKER, K. B. 6306.1002.14 50-270 B UNRIO, R. E. 8396.1407.45 B 0-230 TUKER, H. B. 6306.1002.14 50-270 B UNRIO, R. E. 8396.1407.45 B 0-230 TUKER, H. B. 6306.1002.14 50-270 B UNRIO, R. E. 8396.1407.45 B 0-230 TUKER, H. B. 6306.1002.14 50-270 B UNRIO, R. E. 8396.1407.45 B 0-230 TUKER, H. B. 6306.1002.14 50-270 B UNRIO, R. E. 8396.1403.35 50-280 TUKER, H. B. 6306.1002.14 50-270 B UNRIO, R. E. 8396.1002.15 50-280 TUKER, H. B. 6306.1002.15 50-270 B UNRIO, R. E. 8396.1002.15 50-280 B TUKER, H. B. 6306.1002.15 50-240 B UNRIO, R. E. 8396.1002.15 50-280 B TUKER, H. B. 6306.1002.15 50-240 B UNRIO, R. E. 8396.1002.15 50-280 B TUKER, H. B. 6306.1002.15 50-240 B UNRIO, R. E. 8396.100	TONER,KA TONER,KA TONER,KA	8304040119 8304040145 8304080045 8304100055	50-155 P 50-255 P 50-155 P	TUCKER,H B TUCKER,H D TUCKER,H B	8306070269 8306070272 8306070283	50~369 F 50~269 P 50~369 P	UHRIG,RE UHRIG,RE UHRIG,RE	8306100140 8306130156 8306130268	50-389 50-389 50-389
TONER, K A	TONER,KA TONER,KA TONER,KA	8304130051 8304130334 830420230	50-155 P 50-255 F 50-155 P	TUCKER,H B TUCKER,H B TUCKER,H B	8304090015 8304090040 8304090147	50~370 B 50~370 B 50~369 B	UHRIGIRE UHRIGIRE UHRIGIRE	8306140007 8306140011 8306140097	50-369 50-369 50-369
TONGER, K. A. BJO6290412 50-189 P TOCKER, H. B. BJO6130316 50-370 B UHR10, R. E. BJO6160335 50-335 TOOLE, R. BJO6160304 50-289 F TUCKER, H. B. BJO6130316 50-369 B UHR10, R. E. BJO6200144 50-389 TOOLE, R. J. BJO6200140 50-289 F TUCKER, H. B. BJO6130348 50-369 B UHR10, R. E. BJO6200144 50-389 TOOLE, R. J. BJO6200140 50-289 B TUCKER, H. B. BJO6140018 50-349 B UHR10, R. E. BJO6200140 50-389 TOOLE, R. J. BJO6200140 50-389 TUCKER, H. B. BJO6140018 50-349 B UHR10, R. E. BJO6200140 50-389 TOOLE, R. J. BJO6200310 50-389 TUCKER, H. B. BJO6140018 50-3413 E UHR10, R. E. BJO6200310 50-389 TUCKER, H. B. BJO6140018 50-3413 E UHR10, R. E. BJO6200310 50-389 TUCKER, H. B. BJO6140018 50-413 E UHR10, R. E. BJO6200310 50-389 TUCKER, H. B. BJO6140018 50-413 E UHR10, R. E. BJO6200310 50-389 TUCKER, H. B. BJO6140018 50-413 E UHR10, R. E. BJO6200310 50-389 TUCKER, H. B. BJO6140018 50-413 E UHR10, R. E. BJO6200310 50-389 TUCKER, H. B. BJO6140018 50-413 E UHR10, R. E. BJO6200310 50-389 TUCKER, H. B. BJO6140018 50-413 E UHR10, R. E. BJO6200310 50-389 TUCKER, H. B. BJO6140018 50-413 E UHR10, R. E. BJO6200310 50-389 TUCKER, H. B. BJO6140018 50-413 E UHR10, R. E. BJO6200310 50-389 TUCKER, H. B. BJO6140018 50-413 E UHR10, R. E. BJO6200310 50-389 TUCKER, H. B. BJO6140018 50-413 E UHR10, R. E. BJO620036 50-335 TOWNLEY, E. L. BJO6240037 50-316 B TUCKER, H. B. BJO6140038 50-413 E UHR10, R. E. BJO626035 50-335 TOWNLEY, E. L. BJO6240037 50-316 B TUCKER, H. B. BJO6140038 50-249 R UHR10, R. E. BJO629036 50-335 TOWNLEY, E. L. BJO6240031 50-316 B TUCKER, H. B. BJO6140031 50-349 R UHR10, R. E. BJO629036 50-335 TOWNLEY, E. L. BJO620037 50-316 B TUCKER, H. B. BJO6140031 50-349 R UHR10, R. E. BJO629036 50-335 TOWNLEY, E. L. BJO629037 50-316 B TUCKER, H. B. BJO629037 50-349 R UHR10, R. E. BJO629036 50-335 TOWNLEY, E. BJO629036 50-335 TOWNLEY, E. BJO629037 50-349 B UHR10, R. E. BJO629036 50-335 TOWNLEY, E. BJO629037 50-349 B UPR10HIT, C. H. BJO629037 50-349 F UPR10HIT, C. H. BJO629037 50-349 F UPR10HIT, C. H. BJO629037 50-349 F UPR10HIT, C. H. BJO629037 50-3	TONER.K A TONER.K A TONER.K A TONER.K A	6304230270 6304240137 6304270074 6304270107	50-155 P 50-155 P 50-155 P 50-155 P	TUGKER, H B TUGKER, H B TUGKER, H, B	8306100164 8306100185 8306100216	50~370 £ 50~370 £ 50~370 £	UHRIGIRE UHRIGIRE UHRIGIRE	8306140572 8306140581 8306140638	50-335 50-367
TOTH, A D	TONER.K A TONQUE.T TOOLE.R TOOLE.R J	8306270412 8306270277 8306150030* 8306210040	50-155 P 50-237 B 50-289 F 50-289 B	TUCKER,H B TUCKER,H B TUCKER,H B	8306130316 8306130342 8306130448	50~370 S 50~369 S 50~369 B	UHRIGIRE UHRIGIRE UHRIGIRE	8304170319 8304200144 8304200194	50-335 50-369 50-369
TOWNLEY, E L 8306210329 50-316 B TUCKER, H. B. 8306170297 B 0-269 R UHRIG, R E 8306290348* 50-250 TOWNSEND, B L 830620041 CONTRACT TUCKER, H. B. 8306170311 50-369 R UHRIG, R E 8306290351* 50-335 TOWNSEND, B L 8306290341 CONTRACT TUCKER, H. B. 8306170311 50-369 R UHRIG, R E 8306290351* 50-335 TOWNSEND, B L 8306290317* TUCKER, H. B. 8306170312 50-369 S UHRIG, R E 8306290351* 50-335 TUCKER, H. B. 8306200212 50-369 S UHRIG, R E 8306300154 PR TUCKER, H. B. 8306200212 50-369 S UHRIG, R E 8306300154 PR TUCKER, H. B. 8306200212 50-369 S UWMLE, T. J. 8306300154 PR TUCKER, H. B. 8306200237 50-369 S UWMLE, T. J. 8306300154 PR TUCKER, H. B. 8306200237 50-369 S UWMLE, T. J. 8306210108 50-317 TRAMM, T. R. 8306300222 50-454 K TUCKER, H. B. 8306200245 50-369 S UPPULURIT, V. R. 830610086 NUREO TRAMM, T. R. 8306100178 50-454 F TUCKER, H. B. 8306200246 50-369 S UPPULURIT, V. R. 83061403122* 50-438 TUCKER, H. B. 8306200321 50-370 S UPRIGHT, C. M. 8306140312* 50-395 TRAMM, T. R. 8306100276 50-454 S TUCKER, H. B. 8306200321 50-370 S UPRIGHT, C. M. 8306140312* 50-395 TRAMM, T. R. 8306100276 50-454 S TUCKER, H. B. 8306200321 50-370 S UPRIGHT, C. M. 8306140371* 50-395 TRAMM, T. R. 8306100276 50-454 S TUCKER, H. B. 8306200321 50-370 S UPRIGHT, C. M. 8306140311 50-395 TRAMM, T. R. 830620021 50-454 S TUCKER, H. B. 8306200325 50-349 S UPRIGHT, C. M. 8306140311 50-395 TRAMM, T. R. 830620021 50-454 S TUCKER, H. B. 8306200325 50-369 S UPRIGHT, C. M. 830622033 50-335 F UPRIGHT	TOTH. A D TOURIGNY, E C TOURIGNY, E C TOURTELLOTTE, J	8306280341* 8306160691 8306280073 8306160680	50-377 G 50-285 P 50-285 P REVIEW ORP	TUCKER, H B. TUCKER, H, B TUCKER, H B	8306140123 8306140129 8306140502*	50-413 0 50-413 0 50-413 0	UHRIG.R E UHRIG.R.E UHRIG.R.E	8304210140 8304210241 8304210140	50-389 50-389 50-335
TRAMM, T R. B306400207 50-854 B TUCKER, H. B B30620032 50-369 B UPRIGHT, C M B30640027 50-897 TRAMM, T R. B306400207 50-454 B TUCKER, H. B B306200321 50-370 B UPRIGHT, C M B30640027 50-498 TUCKER, H. B B306200321 50-370 B UPRIGHT, C M B30640027 50-498 TUCKER, H. B B306200321 50-370 B UPRIGHT, C M B306440172* 50-498 TRAMM, T R. B306400207 50-454 B TUCKER, H. B B306200321 50-370 B UPRIGHT, C M B306400321 50-395 TRAMM, T R B306400207 50-454 B TUCKER, H. B B306200322 50-369 F UPRIGHT, C M B306400323 50-837 TRAMM, T R B30620031 50-454 B TUCKER, H. B B306210072 50-369 F UPRIGHT, C M B306400323 50-837 TRAMM, T R B30620031 50-454 B TUCKER, H. B B306210072 50-369 F UPRIGHT, C M B30640033 50-837 TRAMM, T R B30620031 50-454 B TUCKER, H. B B306210170 50-287 B UTKEY, E. B B30620031 50-327 TRAMM, T R B30620031 50-454 B TUCKER, H. B B30620035 50-413 F UTKEY, E. B B30660112 50-400	TOWNLEY, E L. TOWNSEND, B L. TOWNSEND, B L.	8306210074 8306210325 8306230041 8306290268	50-316 B 50-316 B CONTRACT	TUCKER, H. B. TUCKER, H. B TUCKER, H. B.	8306170297 8306170311 8306170316	50-249 R 50-349 R 50-413 E	UHRIG.R E UHRIG.R E UHRIG.R E	8306270351* 8306270351* 8306270378	50-250 50-335 50-250
TRAMM, T R	TRAINOR,A F TRAMM,T R. TRAMM,T R TRAMM,T R	8306270002 8306030272 8306070221 8306100178	50-973 8 50-454 K 50-454 F 50-454 9	TUCKER, H. B. TUCKER, H. B TUCKER, H. B	6304200238 8304200245 6304200244	50-370 \$ 50-369 \$ 50-369 \$	UNKLE, T. J. UPPULURI, V. R. UPRIGHT, C M	8306210108 8306010086 8306140172*	50-317 NUREQ 50-438
	TRAMM, T R TRAMM, T R TRAMM, T R	930422001 1 120134088 9304200234	50-454 B 50-454 K 50-454 E	TUCKER, H. D. TUCKER, H. B. TUCKER, H. B.	8306210072 8306210170 8306220275*	50-349 P 50-287 S 50-413 F	UTLEY, E, E UTLEY, E, E UTLEY, E, E	8306270233* 8306010311 8306060112	50-537 50-324 50-400

AUTHOR	NUMBER ACCESSION	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGURY	AUTHOR	ACCESSION NUMBER	GATEGD3Y
UTLEY, E E VAETH, M VALDES, S A VALDES, S A VALDES, S A	8306290553* 8306240078 8306010009 8306010252 8306200094	50-261 d NUREG 50-389 S 50-389 S 50-389 S	VASSALLO, D B VASSALLO, D B VASSALLO, D B VASSALLO, D B VASSALLO, D B	8306020290* 8306020568 8306020587* 8306020699 8306030032	50-324 0 50-278 0 50-278 0 50-325 P 50-333 P	VOIGT, H H VOIGT, H H VOLGENAU, F VORDERBRUEGGEN VORDERBRUEGGEN	8306280527 8306280530* 8306060035* 8306070253* 8306070256*	50-289 0 50-289 0 FOIA 50-528 0 50-528 0
VAN BRUNT,E E VAN BRUNT,E E VAN BRUNT,E F VAN BRUNT,E E VAN BRUNT,E E	8306010055 8306010072 8306010076 8306010119 8306010137	50-528 S 50-528 S 50-528 S 50-528 S 50-528 S	VASSALLO, D B	8306030119 8306030134* 8306090386 8306090430 8306130481	0-293 0 0-293 0 9-298 P 9-220 P 0-233 0	VOSBURY, F VOSBURY, F W VOSBURY, F W VOSBURY, F W VOSBURY, F W	8304090388* 8305200714* 8305230021* 8304020194* 8304030070*	50-278 p 50-305 p 50-202 p 50-302 p 50-338 p
VAN BRUNT.E E VAN BRUNT.E E VAN BRUNT.E E VAN BRUNT.E E VAN BRUNT.E E	8304010272 8304010289 8304010341 8304010375 8304030357	50-528	VASSALLO, D B VASSALLO, D B VASSALLO, D B VASSALLO, D B VASSALLO, D II	8306130495 8306150224 8306150260 8306150464 8306150466	50-271 P 50-133 F 50-259 P 50-324 P 50-263 P	VOSBURY, F W VOSBURY, F W VOSBURY, F W VOTH, M H WADE, L	B306030297* B306030446* B306090397* B306030064 B306170152*	50-315 p 50-280 p 50-312 p 70-687 / 0/A
VAN BRUNT,E E VAN BRUNT,E E VAN BRUNT,E E VAN BRUNT,E E	8304070078 8304070091 8304070104 8304070178 8304070221	50-528 \$ 50-528 A 50-529 \$ 50-528 \$ 50-528 \$	VASSALLO, D B	8304150574 8304150625 8304150624 8304150631 8304220194	50-263 P 50-259 0 50-220 F 50-220 P 50-290 P	WAGNER, G H WAGNER, G P WAGNER, H E WAGNER, H E	830623009D* 8306130454 8306130457* 8306020412 8306150245	FDIA 50-10 R 50-10 R 50-460 9 50-289 6
VAN BRUNT, E E VAN BRUNT, E E VAN BRUNT, E E VAN BRUNT, E E VAN BRUNT, E E	8304070225 8304070275 8304130432 8304140500 8304170180	50-528 S 50-528 F 50-528 E 50-528 E 50-528 S	VASSILAROS,M 6 VAUGHAN,C M VAUGHAN,C M VAUGHAN,C M VEGA,A	8306060410 8306140122 8306140338* 8306309165 8306080241*	NUREQ 70-1113 70-1113 PR 50-445 G	WAGNER, M E WAGNER, M E WAGNER, M E WAGNER, M C WAGNER, R M	830616000B 8306170411 8306240286 830629055B 8306230105*	50-289 G 50-460 G 50-460 G 50-269 G FOIA
VAN BRUNT,E E VAN BRUNT,E E VAN BRUNT,E E VAN BRUNT,E E	8306170240 8306170246 8306170265 8306170302 8306170326	50-528 S 50-528 S 50-528 A 50-528 A 50-528 E	VENDER, J VENDER, J VERRELLI, D VERRELLI, D	8304010275 8304010384 8304020484 8304010332 8304140102	50-293 5 50-293 8 50-293 8 50-348 0 50-416 V	WAGNER,W J WAGNER,W J WALKER,R D WALKER,R D WALKER,R D	8306070065* 8306280339* 8306060251* 8306270222* 8306300141*	50-312 q 50-344 q 50-263 q 50-373 q 50-373 q
VAN BRUNT, E E VAN BRUNT, E E VAN BRUNT, E E VAN BRUNT, E E	9304170341 9304170342 9304170351 9304170364 9304170367	50-529 S 50-520 B 50-528 A 50-528 S 50-528 S	VERRELLI, D M VERRELLI, D M VERRELLI, D M VERRELLI, D M VERRELLI, D M	8306140114 8306140131* 8306140132 8306140141 8306140143	50-438 0 50-438 0 50-400 V 50-324 V 50-438 0	WALL, O F WALLACE, E G WALLACE, E G WALLACE, W T WALLER, N K	8306270164 8306010314 8306010314 8306270372 8306030103	50-317 F 50-313 P 50-313 P State Prog 71-6679
VAN BRUNT, E E VAN BRUNT, E E VAN BRUNT, E E VAN BRUNT, E E VAN BRUNT, E E	8304170393 8304200371 8304200371 8304230245 8304230270	50-528 S 50-528 F 50-528 E 50-528 S 50~528 S	VERRELLI, D M	8306140157# 8306140235 8306140355 8306140368 8306140386	50-438	WALLING, G E WALSKE, C WALTON, G A WAMDACH, T	8306300153 8306230328 8306270303 8306270424* 8306270323	50-389 8 PR 50-289 H 50-412 Q 50-255 P
VAN BRUNT, E E	9304230318 9304230379 9304230408 8304270143 8304270348	50-529 S 50-529 B 50-528 S 50-528 A 50-528 E	VERRELLI, D M	8304140394 8304140413# 8304140450 8304140443# 8304140473	50~324 0 50~324 0 50~416 0 50~416 0 50~348 0	MAMBACH, T V WAMBACH, T V HAMBACH, T V WANG, C H	8306070062 8306070247 8306160396 8306280439 8306070044	50-255 P 50-255 P 50-255 P 50-255 P 50-243 S
VAN BRUNT, E E VAN BRUNT, E E VAN BRUNT, E E VAN VLIET, J VANDEL, T. E	8306270447 8306280317 8306280436 8306210361 8306230423*	50-528 F 50-529 E 50-528 A 50-289 P 50-374 G	VERRELLI, D M	8304140483 8304140492* 8304140535 8304140542 8304140424	50-400 0 50-395 0 50-327 0 50-390 0 50-259 V	HARD, E C HARD, E C WARD, K D WARD, K D WARD, K D	8304070257* 8304230077* 8304030185* 8304230271* 8304230440*	50-282 F 50-282 F 50-483 8 50-440 8 50-155 8
VANDERBER, J J VANDEWALLE, D J VANDEWALLE, D J VANDEWALLE, D J VANDEWALLE, D J	8306240191 8306030223 8306150409* 8306170218 8306210102*	50-397 S 50-155 P 50-155 G 50-155 F 50-155 G	VERRELLI, D M	8306140645 8306140653 8306140677 8306140685 8306140687	50-348	WARD, K D WARE, J T WAREMBOURG, D WAREMBOURG, D WAREMBOURG, D	8306300216* 8306220091* 8306060130 8306060134 8306160434	50-358 0 CONTRACT 50-267 P 50-267 8 50-267 R
VANDEHALLE, D J VANDEHALLE, D J VANDEDRN. P K VARELA, A A VARGA, B A.	8304230010# 8304240285 8304290305* 8304090131* 8304010045	50-155	VERRELLI, D M	8306140693* 8306140757 8306170294 8306210184 8306230248	50-324 0 50-438 0 50-260 5 50-273 5 50-337 8	WAREMBOURG, D WAREMBOURG, D WAREMBOURG, D WAREMBOURG, D WAREMBOURG, D WAREMBOURG, D	8304280217 8304300098 8304300187 8304070199 8304140733	50-267 8 50-267 8 50-267 8 50-267 0 50-267 P
VARGA, B. A VARGA, B. A VARGA, B. A VARGA, B. A VARGA, B. A	8304020034 8304020542 8304020570 8304020474 8304030243	50-348 P 50-272 P 50-348 F 50-334 P 50-334 P	VERRELLI.D M VERRELLI.D M VERRELLI.D M VERRELLI.D M	8304270231 8304270236 8304270237 8306270309 8306270309	50-438 0 50-416 0 50-438 0 50-390 0 50-438 0	WAREMBOURG, D W WAREMBOURG, D W WAREMBOURG, D W WARNICK, R F WARNICK, R F	8306210253 8306210373* 8306300099 8306060048 8306060071	50-267 0 00-267 F 50-267 F 50-329 0 50-358 A
VARQA, S A VARQA, S A VARQA, S A VARQA, S A	8304030247 8304030270 8304030441 8304030508 8304080073	50-334 P 50-215 P 50-295 P 50-295 P 50-334 P	VERRELLI, D M VERRELLI, D M VERRELLI, D, M VERRELLI, D, M VERRELLI, D M	8306270318# 8306270325# 8306270365 8306270420 8306270420	50-390 Q 50-438 Q 50-416 Q 50-261 Q 50-390 Q	WARNICK,R F HARNICK,R F HARNICK,R F HARNICK,R F WARNICK,R F	8306070042* 8306070243 8306070244* 8306210123 8306230353	50-358 0 50-329 8 50-329 0 50-356 9 50-356 0
VARCA, S A VARCA, S A VARCA, S A VARCA, S A	8304090052 8304150427 8304150430* 8304150438* 8304170481	50~311 F 50~286 P 50~286 P 50~286 P 50~272 F	VHAAD,E R VHAAD,E R VITO,D. VITO,D.	8306070299 8306070317 8306300146 8306070388* 8306020037*	50-247 F 50-247 F NUREQ 50-29B P 50-309 P	WARNICK,R F WARNICK,R F WARNICK,R F WARNICK,R F WARNICK,R F	8306230357* 8306270150 8306270374 8306280208 8306280537	50-358
VARCA, B A VARCA, B A. VARCA, B A. VARNADO, C. B. VARNER, D B VASSALLO, D B	8306220243 8306230371 8306240470 8306240301* 8306210206	50~286 F 50~250 F 50~261 0 50~247 0 50~293 8	VITO, D J. VITO, D J. VIVIERTO, M A VOCLER, B. H VOCLER, B H	9306030512* 8306070397* 8306020420 8306080214 8306130366	50-295 P 50-312 P REGOD 50-361 G 50-352 O	HARNICK,R F WASTLER,S L WATERS,J R WATKINS,L B WAYNE,L	8306300101 8306210431 8306060821* 8306820117 8306170379*	50-329 A 40-8084 50-275 G 50-458 Q 50-142 T
VASSALLO, D B VASSALLO, D, B VASSALLO, D B VASSALLO, D B.	8304010179 8304020020 8304020107 8304020180 8304020205	50-254 Q 50-324 Q 50-324 Q 50-259 P 50-331 P	VOGLER, B H VOGT, D K. VOGT-LOHELL, R VOGTLE, A W VOIGT, H H	8306230127 8306090488* 8306290225* 8306070127* 8306280527	50~445 M CDNTRACT 50~387 Q 50~321 I 50~207 Q	WAYNE,L WEBB,D WEBB,D F WEBER,M F. WEEKB,E D	8306170426* 8306220272* 8306270410 8306140205 8306020307	50-142 T CONTRACT 50-358 0 WASTE MOT 50-133 R

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUB CAT
WEEKB.E D WEGST.W F WEINFURTER.E WEINKAM.E WEINKAM.E J	8306160461 8306280595 8306170314 8306090205 8306130462	50-133 R 50-142 R 50-254 R 50-410 A 50-458 A	WESTERMAN, I F WESTERMAN, T F WESTERMAN, T F WESTERMAN, T F WESTERMAN, T F	8306160362* 8306210012* 8306210127* 8306240148* 8306270237*	50-278	WILCOX, J B WILCOX, J B WILCOX, W S WILLETT, D J WILLETT, D J	8306290334* 8306070300 8306140437 8306070083* 8306260380*	50-4 50-3 50-3 50-3 50-3
WEINKAM,E J WEINKAM,E J WEINMAN, 8 WEIR, B A WEIR, P J	8306140417 8306220254 8306160467 8306010094 8306020374	50-458 A 50-458 A PR NUREO 50-318 B	WETHY, C N WETHY, C N WETHY, C N WETHY, C M	8306140033* 8306160662* 8306170287 8306210388* 8306220230*	50-335 F 50-369 F 50-389 P 50-389 F 50-335 F	HILLHOITE, B HILLIAMS, C C HILLIAMS, C C HILLIAMS, C C	8306300128 8306030143* 8306030147* 8306030148* 8306030202*	NURE 50-2 50-4 50-5 50-5
WEIR, P J WEIR, P J WEIR, P J WEIR, P J WEIR, B M	8306020430 8306020433 8306020438 8306020438 8306020423	50-318 8 50-317 8 50-318 8 50-318 9 50-317 8	WETTERHAHN, M J WETTERHAHN, M J WETTERHAHN, M J WETTERHAHN, M J WETTERHAHN, M J	8306070295 8306070295 8306070299* 8306070299* 8306070301*	50-352	HILLIAMS, C C	8306070190> 8306100105* 8306100266* 8306130345* 8306830255*	50-2 50-2 50-3 50-4 50-3
WEISS, E R WEISS, E R WEISS, E R	8306130493 8306160297 8306030007 8306070418 8306150389	70-1257 50-289 0 50-380 0 50-289 0 50-247 0	WETTERHAHN, M J WETTERHAHN, M J WETTERHAHN, M J WETTERHAHN, M J WETTERHAHN, M J	8306070301* 8306080107* 8306090212 8306090212 8306090240	50-352	Hilliams, C C Hilliams, C C Hilliams, C C Hilliams, C C Hilliams, J	8306230420* 8306300067* 8306300262* 8306160667* 8306010151	50-4(50-3- 50-3- 71-9- 50-3(
WE168, E R WE168, E R WE168, E R WE168, E R	6306150387 6306160604 6306160604 6306220146	50-247 0 50-247 0 50-289 0 50-289 0 50-537 0	WETTERHAHN, M J WETTERHAHN, M J WETTERHAHN, M J WETTERHAHN, M J WETTERHAHN, M J	B306090240 B306140740* B306150393 B306150393 B306160603	50-352	Hilliams, J Villiams, J Villiams, J Williams, J Williams, J	8306060074* 8306060079 8306060197 8306060254 8306070135	50-3 50-3 50-3 50-3 50-3
WE168, E R WE168, E R WE188, E R WE188, E R	8304220144 8304220153* 8304220153* 8304220153* 8304230350	50-537 0 50-537 0 50-537 0 50-537 0 50-537 0 50-247 0	WETTERHAHN, M J WETTERHAHN, M J WETTERHAHN, M J WETTERHAHN, M J WETTERHAHN, M J	8306220036 8306220031 8306220036 830622036*	50-352	uraniliw Lamaijiw Lamaijiw Lamaijiw Lamaijiw Lamaijiw	8306070232 8306070267 8306070267 8306080137 8306080213	50-3! 50-3! 50-3! 50-3! 50-3!
WEISS.E R WEISS.E R WELLS.D A WELLS.D A	8306230390 8306270199 8306300037 8306060187 8306060245	50-247 0 50-247 0 50-289 0 50-341 8 50-341 6	WETTERHAHN, M J WETTERHAHN, M J WETTERHAHN, M J WETTERHAHN, M J WHALEN R J	8304270122 8304270122 8304270413 8304270413 8304270083	50-410 Q 50-410 Q 50-352 G 50-352 G 50-249 S	Hilliams, J Williams, J Williams, J Williams, J Williams, J	8306090084 8306090127 8306130381 8306170321 8306210054	50-3 50-3 50-3 50-3 50-3
WELLS.D A WELLS.D A WELLS.D A WELLS.D A WELLS.D A	8306070085# 8306130292# 8306170233 8306170419 8306220024#	50-341 Q 50-341 Q 50-341 S 50-341 S 50-341 Q	L.REJECHM M. C.REHOIHM M. C.REHOIHM M. C.REHOIHM M. C.REHOIHM	8306240462 8306100201 8306100201 8306100201 8306100201	50-443 A 50-454 O 50-454 G 50-454 G 50-454 O	Hilliams, J Hilliams, J Hilliams, J Hilliams, J Hilliams, J	8306210058 8306210274 8306230081 8306230087 8306230176	50-3! 50-3! 50-3! 50-3!
WELLS, D A WELLS, R WELLS, R WENDERLICH, R L WENDERLICH, R L	830622030# 8306010329 8306010329 8306020374 8306020433	50-341	MHICHER, J M WHICHER, J M WHICHER, J M WHICHER, J M WHICHER, J M	9306170371 8306170371 8306170371 8306170371 8306170384*	50-454 0 50-454 0 50-454 0 50-454 0	ullliams, J Williams, J Williams, J Williams, J	8306230268 8306230395 8306230442 8306230472 8306270180	50-35 50-35 50-35 50-35 50-35
WENDERLICH R L WENDERLICH R L WENSLAWSKI, F WENSLAWSKI, F WENSLAWSKI, I	B306020467 B306170072 B306280447 B306070011* B306070287*	50-317 9 50-318 9 50-317 5 50-344 0 50-249 0	WHICHER, J M WHICHER, J M WHITAKER, T E WHITE, A F WHITE, A F	8304170387* 8304230370* 8304140444 8304140875 8304140582*	50-454 Q 50-367 G REGGD 50-410 O 50-410 Q	Hilliams, J Hilliams, J Hilliams, J Hilliams, J Hilliams, J	8306270331 8306270332 8306270378* 8306280213* 8306280359	50-38 50-35 50-38 50-38 50-38
MENBLAWBKI, F WENBLAWBKI, F WENBLAWBKI, F WENBLAWBKI, F WENBLAWBKI, F WENBLAWBKI, F WENBLAWBKI, F WENBLAWBKI, F WENBLAWBKI, F	8306070337* 8306090174 8306280310* 8306280507* 8306070157*	50-206 Q 50-275 9 50-928 Q 50-927 Q 50-212 Q	WHITE, A F WHITE, J R WHITE, J R WHITE, W WHITEMAN, D. C	8306160582* 8306020416* 8306020447* 8306230339 8306280013	50-410 0 50-273 0 50-217 0 PR NUMEO	ulliamb, J G Lama, J G Lama, J H Lama, J W Lema, J, W	8304300140 8304040142 8304030312* 8304070224* 8304010007	50~35 50~28 50~27 50~27 50~38
MENSLAMSKI'L V MCNSLAMSKI'L V MCNSLAMSKI'L V MCNSLAMSKI'L V	8304070174* 8304280145* 8304280177* 8304280185* 8304280432*	50-312 0 50-528 0 50-09 0 50-69 0 50-2144 0	WHITENER, H L WHITENER, H L WHITENEY, G G WHITEY, G G WHITEY, G G	8306140196* 8306140537* 8306280358 8306010060 8306010157	50-335 0 50-369 0 50-293 8 50-293 8 50-293 8	W C,8MAILLIW W C,8MAILLIW W C,8MAILLIW W C,8MAILLIW W C,8MAILLIW	8304010114 8304010252 8304070214 8304070058 8304070181	50-38 50-38 50-25 50-38 50-38
WERNER, T A WEBCOTT, H M WEBT, D WEBT, D WEBT, D K	8306160210 8306210278# 8306200180 8306300025 8306060370	NUREQ 50-341 (4 90-397 (8 50-397 (8 FOIA	O O CHITHEN O CH	8306010393 8306020154 8306020419 8306280072 8306010077*	50-293 B 50-293 R 50-293 B 50-293 S CONTRACT	W C.BMAIJIN W C.BMAIJIN W C.BMAIJIN W C.BMAIJIN W C.BMAIJIN	9306160639 8306200094 8306200180 8306210081 8306210197	50-25 50-36 50-36 50-38 50-25
WEST, D. K WESTAFER, G R WESTAFER, G R WESTAFER, G R WESTAFER, G R	8304080288 8304030320 8304070273 8304070145 8304140481*	FD1A 50-302 1 50-302 8 50-302 8 50-302 0	WHITNEY, J W WIDMAYER, D A WIEBE, J 8, WIEBER, A V WIEBER, A V	8306270633* 8306210437 8306060266* 8306200410* 8306200383*	CONTRACT 27-47 50-320 0 70-1257 70-734	W C.BMAILLIW W C.BMAILLIW W C.BMAILLIW W C.BMAILLIW W C.BMAILLIW	B306220014 B306270200 B306280168 B306280476 B306300025	50-38 50-25 50-25 50-38 50-38
WESTAFER, O R WESTAFER, O R WESTAFER, G R WESTAFER, G R WESTAFER, G R	B306170221 B306200033 B306220049 B306230427 B306230447	50~302 R 50~302 P 50~302 P 50~302 P 50~302 R	WIEBEMANN, R. A WIEBEMANN, R. A WIEBEMANN, R. A WIEBEMANN, R. A WIGOINB, E.	8306070210# 8306150172# 8306240314# 8306270434 8306230218	50-413 E PROJ Toprep Proj Contract	WILLIAMB.J W WILLIAMB.R WILLIAMB.R C WILLIAMB.R E. WILLIAMB.R E	830 63001 73 830 622025 7* 830 602026 3 830 602026 7* 830 61 40 43 8*	50-38' CONTR: 40-22: 40-29' CONTR:
Westafer o r Westafer o r Westerman, t Westerman, t	8306230465 8306240259 8306300225 8306140374* 8306010141*	50-302 P 50-302 P 50-302 P 50-445 Q 50-267 Q	T L.enigolu Higolus, T T L.enigolu Higolus, D U.notnigolu	8304070353* 8304070344* 8304140004* 8304020007 8304210343	50-271 Q 50-271 Q 50-271 Q 50-271 Q 50-315 P 50-315 F	WILLIAMS, R. E WILLIAMS, R. E WILLIAMS, R. K WILLIAMS, V. S WILLIAMS, V. S	8306150570* 8306200111 8306060309* 8306100064 8306130307	CONTR/ 40-85(70-25 50-29(50-29)
WESTERMAN, T I- WESTERMAN, T I. WESTERMAN, T I WESTERMAN, T, I WESTERMAN, T I	8306010261 8306060133* 8306060133* 8306080221*	50-29B B 50-247 G 50-112 G 50-44B G 50-445 G	WILBORN, L, WILBORN, L WILBORN, L WILCOVE, M N WILCOVE, M N,	8304080211* 8304080238* 8304270237* 8304150220 8304150274	50-285 0 50-313 0 50-278 0 50-327 0 50-327 0	Will Lamson, B Wilson, B D Wilson, B D Wilson, B D Wilson, C L	8306210270 8306030083 8306150346 8306160668 8306240052	50-25' XPORTI XPORTI XPORTI NUREO

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT
MIF8ON'N F MIF8ON'N F MIF8ON'N F MIF8ON'N E	830602036* 8306020641 8306070220 8306070238 8306070243*	CONTRACT 50-382 A 50-280 S 50-281 S 50-281 S	HORTHAM, T R HOZNIAK, D R WRAY, J R HRAY, R HRAY, R HRIGHT, D J	8304280454 8304150343 8304170345 8304080068 8304080068		ZIMMERMAN, J V ZIMMERMAN, J V ZIMMERMAN, J V ZIMMERMAN, J V ZIMMERMAN, J V	8306030219 8306030226 8306030249 8306030474 8306030478*	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC
HILSON, J L HILSON, J L HILSON, J L HILSON, J L HILSON, J L	830 6070245* 830 6100 196 830 6210295 830 6270005 830 6270351	50-281 9 50-201 S 50-280 S 50-280 S 50-281 S	WRIGHT,E O WRIGHT,N A WRIGHT,N A WRIGHT,N A WRIGHT,N A WRIGHT,R W	8111040442 8306140660 8306140727 8306270154 8306140172	50-329 6 50-329 6 50-329 6	ZIMMERMAN, J V ZIMMERMAN, J V ZIMMERMAN, J V ZIMMERMAN, J V ZIMMERMAN, J V	8306070008 8306070007 8306070181 8306140267 8306140271	XPORTLIC XPORTLIC XPORTLIC XPORTLIC
MILSON, J L WILSON, J L WILSON, L O WILSON, W E	8306270357* 8306270364* 8306300199 8306130398 8306200151	50-281 6 50-281 8 50-281 8 50-382 0 50-27 F	WRIGHT, 5 V WRIGHT, 5 V WULLER, 0 E WULLER, 0 E WULLER, 0 E	8304020222 8304240487 8304020203 8304100097 8304200409	27-48 27-48 70-2947 50-461 F 50-461 F	ZIMMERMAN, J V ZIMMERMAN, J V ZIMMERMAN, J V ZIMMERMAN, J V ZIMMERMAN, J V	8304140274 8304140309 8304150271 8304150457 8304140285	XPORTLIC XPORTLIC XPORTLIC XPORTLIC
WILBON, W H WINEGARDNER, W WINGO, M D, WINBECK, B WINTON, M L	8306140225 8306070471 8306280375 8306230109* 8306210324	50-528 A NUREO 50-240 B FOIA NUREO	WULLER, O E WUSTERBARTH, A WYATT, J M YARIO, W R YEAGER, B B	8304210231 8304240078 8304040120* 8304300142 8304300142	50 441 A NUREG 50-302 1 PR PR	ZIMMERMAN, J V ZIMMERMAN, J V ZIMMERMAN, J V ZIMMERMAN, J V ZIMMERMAN, R	8306140290 8306200063 8306240362 8306280027 8306240214*	XPORTLIC XPORTLIC XPORTLIC XPORTLIC GA999
Hire, K r Hise, r. Hisenburg, M r Hisenburg, M r	8306270163 8306140315 8306080046* 8306300077 8306300173	50-298 S NUREO 50-267 G 50-498 K NUREO	YIN, I T YIN, I T YIN, I T YORK, J W YORK, J W	830404013B* 8304300027* 8304300244* 8304140139* 8304140437*	50-346 0 50-237 0 50-438 0	ZIMMERMAN, R ZIMMERMAN, R ZIMMERMAN, R D ZIMMERMAN, R D ZIMMERMAN, R P	8306240219* 8306240224* 8306240201* 8306160372* 8306230322*	0A999 0A999 0A999 50-244 0 50-244 0
Wisner, C e Wissink, R o Withers, B D Withers, B D Withers, B, D	8306140636* 8306230340 8306010316 8306070209 8306130415	50-382 Q PR 50-344 P 50-344 P 50-344 F	YORK, J H YORK, J W YOSHIDA, D K YOUNG, F YOUNG, M A	8306140511* 8306290235* 8306160366* 8306150008* 8306210276	50-413 G 50-438 G 50-341 A 50-289 G 50-440 G	ZIMMERMAN, S R	8304070035 8304070151 8304070153 8304070172 8304080080	50-324 P 50-400 E 50-261 P 50-261 B 50-324 P
WITHERBOD D WITHERBOD D WITHERBOD D WITHERBOD D WITHERBOD D	8306170303 8306170400 8306200191 8306200207 8306230323	50-344 P 50-344 G 50-344 F 50-344 I PR	YOUNG, M A YOUNG, M C YOUNG, T YOUNG, T	8306210301 8306210347 8306080284 8306070007* 8306070254*	50-440 © 50-440 0 50-528 A 50-528 Q 50-528 Q	ZIMMERMAN, BR ZIMMERMAN, BR ZIMMERMAN, BR ZIMMERMAN, BR ZIMMERMAN, BR ZUGKER, CR	B306070374* B306100260 B306220005 B306270225 B306010085*	50-261 F 50-261 P 50-261 P 50-324 P 71-6400
WITHERS, BD WITHERS, BD WITHERS, BD WITHERS, BD WODEK, DJ	8306230445 8306240236 8306240316 8306270242 8306170459	PR 50-344 F 50-344 G PR 40-8714	YDUNG, T YDUNG, T YDUNG, T YBUNG, T YDUNG, T E	8304070378* 8304070385* 8304280452* 8304280517* 8304080141	50-312	ZUDANB, Z ZUDKO, J M ZUPKO, J M ZUPKO, J M	B306210446 B306210446 B306010328 B306020406 B306030188	ACRS ACRS 50-311 S 50-311 S
HOGHAN,N A HOLF, J. F HOLFBEIN,S L WOLFE,R HOLFE,S J	8304070357 8304040285 8304200285* 8304100124 8304150422	WASTE MOT 50-522	YOUNG, Y YOUNG, Y A YOUNGILOOD, B J YOUNGBLOOD, B J YOUNGBLOOD, B J	8306070475 8306240373 8306010042 8306030066 8306030232	40-8580 NUREQ 50-358 A 50-456 A 50-456 C	ZUPKO,J M ZUPKO,J M ZUPKO,J M ZUPKO,J M ZUPKO,J M	9306030301 8306030344 8306170021 8306170144 8306170153	50-311 8 50-311 8 50-311 8 50-272 8 50-311 8
WOLFE, 9 J WOLLETT, 8 WOLLETT, 8 WOLLETT, 8 WOLLETT, 8	8306280536 8305040708 8306010117 8306020480 8306030252	50-382 Q CONTRACT CONTRACT CONTRACT CONTRACT	ADANGBFOOD'B 1 AOANGBFOOD'B 1 AOANGBFOOD'B 1 AOANGBFOOD'B 1 AOANGBFOOD'B 1 AOANGBFOOD'B 1	8306030237 8306030412 8306030417 8306060373 8306060383	50-456 A 50-358 F 50-454 A 50-440 A 50-482 A	SONKO'N W SONKO'N W SONKO'N W SONKO'N W	8304170207 8304170338 8304170362 8304170381 8304200132	50 311 9 50-27g B 50-311 B 50-27g B 50-311 R
HOLLETT, 8 HOLLETT, 8 HOLLETT, 8 HOLLETT, 8 HOLLETT, 8	8304030254 8304070464 8304080419 8304220229 8304280152	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT	YOUNGBLOOD, B J YOUNGBLOOD, B J YOUNGBLOOD, B J YOUNGBLOOD, B J	8306070459 8306080051 8306170470 8306210403 8306220090	50-423 A 50-482 A 50-544 D 50-445 A 50-482 F	ZUPKO, J M ZUPKO, J M ZUPKO, J M ZUPKO, J M	8304200224 8306210187 8306270188 8306270267 8306270343	50-272 R 50-272 8 50-272 9 50-272 9
WOLLETT, S WOLLETT, S A WOLLIN, J. WOLTNER, E WONG, T	8306270597 8306220324 8306060309* 8306170245* 8306020314	CONTRACT CONTRACT 70-25 70-371 40-279	YOUNOBLOOD, B J YOUNOBLOOD, B J YOUNOBLOOD, B J YOUNOBLOOD, B J	8304220101 8304220106 8306240064 8306240070 8306240288	50-546 A 50-341 A 50-440 E 50-454 E 50-440 E	ZUPKO.J M ZUPKO.J M. ZURAKOWEKI.P R ZWETZIG,G B ZWETZIG,G B	B306280256 B306280480 B306280136* B306070065* B306070367*	50-279 8 50-279 B 50-344 0 50-312 0 50-275 0
WDNO, T WOOD, E C WOODF IN, R L WOODHEAD, C P WOODHEAD, C P	8306020320# 8306010408 8306020080 8306020161 8306130371	40-279 50-309 S NUREO 50-142 G 50-142 T	YOUNGBLOOD, B J YOUNGBLOOD, B J YOUNGBLOOD, B J YOUNGE, T B	8304240370 8304270137 8304270142 8304080182* 8304170334	50-440 A 50-440 E 50-341 A 50-322 Q NUREQ	ZWETZ 10, G D ZWETZ 10, G, B ZWETZ 10, G B ZWETZ 10, G B ZWETZ 10, G B	8304280224* 8304280337* 8304270357* 8304280224* 8304280337*	50-312 0 50-344 0 50-275 0 50-312 p 50-344 0
HOODHEAD, C P HOODHEAD, C P HOODHEAD, C P HOODHEAD, C P	8306160009 8306210275 8306210280 8306230301	50-142 T 50-142 0 50-142 0 50-142 0	YUHAB.G P YUNDT.C P YUNDT.C P YUNDT.C P YUNDT.C P	8306280185# 8306010073 8306020119 8306070071	50-89			
		° ,	YUNDT, C P YUNDT, C P YUNDT, C P, YUNDT, C P ZEIDLER, Z,	8304140392 8306170193 8306170317 8306200152 8306060309*	50-344 R 50-341 8 50-344 8 50-344 R 70-25			
			ZIBULSKY, H ZIBULSKY, H ZIBULSKY, H ZIMMERMAN, J. V ZIMMERMAN, J. V	8304010153* 8304010337* 8304030324* 8304020573	70-371 70-687 70-371 XPORTLIC XPORTLIC			
			7 TMMERMAN. I U	0201020100	VERNET TA			

ZIMMERMAN, J. V 8304020423 8304020428 8304020453 8304020443 8304030174 XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC

The subject category column in this index gives the docket number and the symbol for the category of information within that docket; for example, 50-320 P. The docket subject categories are defined in Appendix A.

Subject categories for nondocketed items are also entered in this column by symbol; for example, ACRS. These categories are defined in Appendix B and listed in the Contents. An asterisk following the accession number in this in indicates that the document is an enclosure to another document. To obtain the accession number of the principle document under which the enclosure is listed, refer to index entitled "Cross Reference of Enclosures to Principle Documents."

AUTHÜR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGOR	Y	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEODR
SM Co , Minnesota Mining & Mfg Co ATC Medical Technology, Inc Aamodts, The	8306230340 8306020468 8306060190 8306070420 8306070297	PR 71-5796 50-289 50-289 50-289	 0 0		8306200336 8710193 87102014 8306210205 8306210365 8306230378	50-348 50-348 50-348 50-348 50-348
	8306150427	50-289	o.		9306230378	50-348
	8309550098	50-289	ő		*\$\$\$\$\$\$\$\$\$\$ *\$\$\$\$\$\$\$\$\$\$	50-348 50-348
	8306220142 8306220147	50-289 50-289	9		8306240040	50-348
Abington Memorial Hosp Abington, PA	#EEF408240EB	70-1402			8306240040	50~348
Advisory Council on Historic Preservation		40-9491			8306270229	50-348
Ampospace Corp	8306150584	NUREO			8306270232* 8306270369*	50-348 50-348
Agriculture, Dept of	8306070458* 8306210127	71-9182 50-546	A		8306290207*	50-348
	8306280269	50-400	D	Alabama, State of	8306280159*	CONTRACT
Air and Water Pollution Patrol	8306010464	50~352	G	Alden Research Laboratory	#E006080303#	50-410
	8306080261	50-320	G.	Alderson Reporting	8306070023 8306210318	FOIA FOIA
	8306290364 8306290364	50-352 50-352	G G	Allied Chemical Corp	8306080406	40-3372
	8306290509	50-352	Ğ	Alpha-Omega Services, inc	64999190EB	71-86
	8306290509	50-352	C C		8306160652*	71-86
Alabama Power Co	8306010331	50-349	P	American Group Co	8306060142	30-289
	920010459	50-364	P	American Mining Congress American Nuclear Insurers	8304300155 *1410624068	PR FDIA
	8304010427* 8304030307	50~364 50~348	Ь Ь	American Nuclear Society	8306160451	REGOD
	*11E0E040E8	50-348	р		8306220245	NUREO
	B306060115	50-364	р	American Resources Group, Ltd	8306100152*	50~483
	1020909068	50-348	P	American Society for Testing & Materials		REGOD
	8306060201 8306070326	50~348 50~364	р Р	American Society of Mechanical Engineers American Society of Utility Investors	8306160467 8306280532	PR 50~287
	#304090 2 08*	50-348	F	Amacanda Co (subs of Atlantic-Richfield	8305230404#	QA999
	8306070208#	50-348	G	Ca)		
	8306100270	50~348	9	Analysis & Technology, Inc	8306240356*	FOIA
	8306130427 8306130427	50-348 50-348	P P	Anchor/Darling Valve (subs Anchor/Darli ng Industries)	8306160336*	GATTT
				Anthony, A L	8306160576* 8306270038	9A979 50~352
	8306130442* 8306130442*	50-348 50-348	P	·	0000270000	00.00%
	8306140071	50-348	ĺ.	Antioch School of Law, Washington, DC	8305240423*	50-155
	8306140071	50-349	Q	Applied Risk Technology Corp	8304020448#	50-247
	6904140593	50-348	P		8306020448* 8306020452*	50-247 50-247
	000111000	** ***			8304020452*	50-247
	6306140593 6306140610	50-349 50-349	P P			
	8306140610	50-348	þ	Aptech Engineering Services	8306080048*	50-440
	8306160032*	50-348	F	Argonne National Laboratory	8306290496# 8305240612#	50-329 COMMISSI
	8306160119	50-364	R	Mildoune Menioner mappingons	8305240424*	COMMISSI
	8306160278	50-348	P		8306270146	NUREO
	8306160278	50-348	P			
	8306160327	50-348	Ŕ		8304270308¥ 8304280085	50-322
	B306170357	50-348	q		8304280085	NUREO NUREO
	B306170357	50-340	a	Arizona Public Service Co.	B304010055	50-528
	8309500519	50-348	A		8304010072	50-528
	6309500519	50~348	8			
	B306200220*	50-348	8		8304010074 8304010074	50-528 50-528
	8306200227#	50-348	s		8304010076	50-528 50-528
	8309500533*	50-348	8			-0 010

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGO	RY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8304010117 8304010119 8304010119 8304010137 8304010272	50-528 50-528 50-528 50-528 50-528	5 5 5 5 5 5		8306070054 8306070193 8306070298 8306070384* 8306070384*	50-348 p 50-313 p 50-313 q 50-313 q 50-313 q
	8306010372 8306010272 8306010289 8306010289 8306010341	50~528 50~528 50~528 50~528 50~529	S S S S		8306080012 8306080012 8306090248 8306090248 8306090313	50-313 F 50-313 F 50-313 F 50-313 F 50-313 P
	8306010341 8306010363 8306010375 8306030357 8306030357	50-529 50-528 50-528 50-528 50-528	5 0 5 F F		8304090313 8304130057 8304130057 8304130222 8304130222	50-313 P 50-313 R 50-313 R 50-313 O 50-313 O
	8305070078 8305070078 8305070078 8305070091 8305070104	50-528 50-528 50-528 50-528 50-529	5 5 9 4 5		8304130270 8304130407 8304130421 8304140050 8304140050	50-368 \$ 50-313 \$ 50-368 \$ 50-313 0
	8306070178 8306070221 8306070225 8306070432 8306070275*	50-528 50-528 50-528 70-2984 50-528	5 5 8 7		8306140155 8306140155 8306150034* 8306160324 8306160355	50-313 F 50-313 F 50-313 P 50-368 S
	830&090276* 830&130432 830&1&0064* 830&1&0500 830&1&0500	50-528 50-528 50-528 50-528 50-528	F E F E		8306160469 8306160474 8306160479 8306160493 8306160499	50-313 8 50-348 8 50-348 8 50-313 P 50-348 8
	8306160500 8306170180 8306170240 8306170246 8306170265	50-528 50-528 50-528 50-528 50-528	E 5 6 8 A		8306160537 8306160561 8306160577 8306160614 8306170275	50-313 Q 50-313 R 50-368 S 50-313 S 50-313 P
	8304170302 8304170302 8304170302 8304170326 8306170326	50-528 50-528 50-528 50-528 50-528	A A A E E		8306170275 8306170408 8306200060* 8306210003 8306210093	50-313 P 50-313 P 50-313 F 50-313 B TOPREP
	8306170326 8306170341 8306170342 8306170351 8306170351	50-528 50-529 50-528 50-528 50-528	E 9 8 A A		8306210125 8306210125 8306210181 8306210229	50-313 R 50-313 R 50-368 B 50-368 P 90-313 V
	8306170351 8306170356 8306170356 8306170356 8306170360*	50-528 50-528 50-528 50-528 50-528	A F F F		8304230474 8304230474 8304230487 8304270192 8304300079*	50-313 F 50-343 F 50-368 F 50-368 S 50-313 Q
	8306170360* 8306170360* 8306170366 8306170366 8306170367	50-528 50-528 50-528 50-528 50-528	F F S S S	Arkansas, State of Army, Dept of Army, Dept of, Army Engineer Waterways Experiment Station Army, Dept of, Corps of Engineers	8306240034*	CONTRACT CONTRACT NUREO CONTRACT
	8306170373 8306200371 8306200371 8306200371 8306210287	50-528 50-528 50-528 50-528 50-528	\$ F F E	Associated Piping & Engineering Corp (subs of Johnson Controls, Inc) Atlas Minerals Atomic Industrial Forum	8306020585 8306200107 8306160224 8306160334	71-302 40-3453 NUREO PR
	8305230245 8305230252 8305230270 8305230318 8305230318	50-528 50-528 50-528 50-528 50-528	8 9 8 8	Australia Automated Correspondence Systems, Inc Automation Industries, Inc	8306230328 8306270303 8305040713* 8306280133* 8306240441*	PR 50-289 H CONTRACT CONTRACT 71-7006
	8306230379 8306230408 8306270143 8306270368 8306270368	50-529 50-528 50-528 50-528 50-528	8 8 4 E E	BWR Cluners Group Babcock & Wilcox Co	8304240445* 8304210146 8304230324 8304070280* 8304070286*	71-7004 TOPAEP TOPAEP 50-269 P 50-269 P
Arkansas Power & Light Co	8306270368 8306270447 8306280317 8306280436 8306010024	50-528 50-528 50-528 50-528 50-313	E F A		8306100090 8306140377 8306140674 8306140746* 8306140782*	50-312 S 50-269 P 70-1201 50-269 P 50-269 P
•	8306010028* 8306010267 8306020081	50-313 50-313 50-313	P P R		8306160497* 8306200020	50-313 P 70-135
	9306020135 9306020150 9306020466	50-313 50-368 50-368	P R P		8306210295 8306220007 8306220131 8306270121 8306280337	TOPREP 50-287 9 70-824 70-1201 TOPREP
	8306030274 8306060067* 8306060067* 8306060253	50-313 50-313 50-313 50-313	J G R	Debcock & Wilcox Operating Plants Owners Group	8304300159 8304300220 8304010314	50-438 S 50-269 S 50-313 P

AUTHOR AFFILIATION	ACCESS LON NUMBER	SUBJEC! CATEQUR	RY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGOR'
Backus, Shea & Moyer	8306070280* 8306210093 8306200291 8306200293* 8306290521	50~269 TOPREP FOIA FOIA 50~443	 Р		8306200423 8306200444 8306230137* 8306240052 8306240058	40-8584 ACRB 70-8 NUREG NUREG
Baltimore Gas & Electric Co	8306290532 8306010264 8306010270 8306010273 8306010277	50-443 50-317 50-318 50-318 50-317	ច ទ ទ ទ	Battelle New England Marine Research Laboratory	8306240073 8306240078 8306240373 8306270324 8306060252	NUREO NUREO NUREO 50-254 50-219
	8306010299 8306010300 8306010307 8306020374 8306020423	50-318 50-317 50-317 50-316 50-317		Bechtel Corp	6304070235 6304070107* 6304130372* 6304140225 6304210220	50-219 50-529 50-329 50-528 50-322
	8306020430 8306020433 8306020436 8306020438 8306020467	50-318 50-317 50-317 50-318 50-317	ទទទ	Behrand, Aramson & Morraus Benton City Technology Berle: Butzel: Kass & Case Berlin, K	8304070018 8304280230 8304070471 8304210384# 8304150398	FOIA FOIA NUREO CONTRACT 50-529
	8304040105 8304040105 8304040107* 8304040109* 8304070047	50-317 50-317 50-317 50-317 50-317	P P P P	Binder, Elster, Mendelson & Wheeler, Inc Black & Veatch Boeing Computer Services, Inc (subs of Boeing Co)	8306170466* 8306080009* 8306030266*	CONTRACT 50-350 CONTRACT
	8304070047 8304070077 8304070154 8304070154 8304070229	50-317 50-317 50-317 50-317 50-317	P S P P	Book Mart International. Inc	8306200280# 8306200282# 8305240436 8306010060 8306010157	FOIA 50-293 50-293 50-293
	8306130001 8306130001 8306150086* 8306160330* 8306170011	50-317 50-317 50-317 50-317 50-317	Q Q F Q S		8304010275 8304010322 8304010334 8304010384 8304010393	50-273 50-273 50-273 50-273 50-273
	8304170018 8304170031 8304170072 8304170420	50-317 50-317 50-318 50-318	R 5 5		8304020154 8304020419 8304020454 8304070045 8304070147	50-293 50-293 50-293 50-293 50-293
	6304200089 6304200118 6304200208 6304200246 6304210044	50-317 50-318 50-317 50-317 50-318	S		8304070170# 8304070348 8304140413 8304140442#	50-293 50-293 50-293 50-293
	8306210086 8306210099 8306210101 8306210108	50-317 50-318 50-317 50-317 50-317	5 5 5 0		8306210184 8306210184 8306210206 8306220003 8306220009*	50-273 50-273 50-273 50-273 50-273
	6306210159 8306210246 8306270164 8306270195	50-318 50-318 50-317 50-317	8 8 F F	Braunkohl: Transport & Storage, Inc	6305240172 6305280072 6305280331 6305280358 6305050354	50-293 50-293 50-293 50-293 XPORTLIC
	9306280172 8306280352 8306280467 8306280462	50-318 50-319 50-317 50-319	8 8 8	Brookhaven National Laboratory	8303220403# 8304010089 8304010478 8304020048	TOPREP NUREO RES
Basic Enorgy Technology Associates	8304280465* 8304030351* 8304150185*	50-317 50-272 50-289	о В Н		8306020066 8306020072 8306030435 8306130377*	NUREO NUREO RES 50-142
Dattelle Human Affairs Research Centers Battelle Memorial Institute, Columbus Laboratories	8306030009 8306140315 8306010129* 8306170482* 8306230505*	NUREQ NUREQ CONTRAC CONTRAC	т		8306140407 8306170192 8306170205* 8306240413	NUREO RES RES 50-286
Battelle Memorial Institute, Pacific	8304240241 0303220042*	RES 50-309	Q	Brush Wellman, Inc Burns & Ros Co	8306280044 8306130243 8306100122	NUREO 40-8722 50-397
Northwest Laboratory	8304010 0 39 8304010047 8304010071	NUREO NUREO NUREO		SOUTH OF ROW SO	9304230337 9304230437 9304230443*	PR TOPREP TOPREP
	8306010478 8306020053 8306020131 8306020134 8306020217	REB NUREO NUREO NUREO WABTE M	IQT	Burstein, C H Businessmen for the Public Interest	8306240191 8306280541* 8306170371 8306170384* 8306170389*	50-397 50-382 50-454 50-454 50-454
	8306030009 8306030485 8306070471 8306070357 8306100095	NUREO NUREO NUREO WASTE M 50-263		California, State of California, Univ of, Berkeley	8304230370* 8304220045 8304220052* 8304220246* 8304220290	50-367 (50-275 (50-275 (CONTRACT ACRB
	8304140315 8304140402 8306160010*	NUREQ NUREQ 50-142	т	California, Univ of, Invine California, Univ of, Los Angeles	8306210186 8306070399 8306070416	50-326 50-142 50-142

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC		AUTHOR AFTILIATION	ACCESSION NUMBER	SUBJI CATE	
California, Univ of San Diego Capitol Stael Corp	8306140774 8306280525 8306280595 8306160045* 8306030038	NUREG 50-142 50-142 CONTRAC 71-9133	G R T		8306140404* 8306140404 8306140405 8306140490* 8306140547	50-324 50-241	4 (1 A 2 (
Caroline Environmental Study Group Carolina Power & Light Co	8304100194 8304150385 8304270284 8304010105 8304010107	50-413 50-413 50-413 50-324 50-324	8800		8306140682* 8306140682* 8306140688* 8306140688* 8306140708*	50~324 50~324	† a
	830A010118 831010A08 831003011 830A010311 830A010388	50-325 50-400 50-324 50-324 50-324	8 9 9 9		8306160116 8306160284 8306160420 8306170224	50-241 50-400 TOPREF 50-241 50-400) E
	8305010390 8305010390 8305010395* 8305010395* 8305010422	50~400 50~400 50~400 50~400 50~400	0 0 0 8		8304200002 8304200003 8304200083 8304200083 8304200109	50-261 50-324 50-400 50-400 50-261	S S
	8306030336 8306030336 8306060112 8306060152	50~400 50~400 50~400 50~400 50~400	0 F E		000200116 0110020028 0110020028 02002008 02002008	50-400 50-400 50-261 50-400 50-400	8 8
	8304040202 8304040202 8304070035 8304070053 8304070081	50-400 50-400 50-324 50-325 50-325	E P S		8306210082 8306210092 8306210092 8306203099	50~400 50~400 50~400 50~324 50~324	A
	8306070097 8306070101 8306070102 8306070122 8306070122	50-324 50-261 50-324 50-400 50-400	8 P 8 E E		8304210074 8306210109 8304210109 8304210174 8304210204	50-324 50-324 50-325 50-400	8 7 8 1
	8306070141 8306070151 8306070151 8306070153 8306070161	50-324 50-400 50-400 50-261 50-261	8 E P 8		8306210204 8306220005 8306220087 8306220108 8306220108	50-400 50-261 TOPREP 50-400 50-400	E P G G
	8306070172 8306070182 8306070217 8306070231 8306070231	50-261 50-261 50-400 50-400 50-400	G S S 6 B		8306220111* 8306220111* 8306220125 8306220125 8306220273	50-400 50-400 50-400 50-400 50-261	0 0 0 F
	8306070235 8306070271 8306070271 8306070342 8306070342	50-324 50-400 50-400 50-324 50-324	8 9 8 8		8306220273 8306220273 8306230345 8306230345 8306240008	50-261 50-261 50-400 50-400 50-324	F 0 0 P
	8306070366 8306070387 8306070400 8306080032 8306080032	50-400 50-400 50-400 50-400 50-400	8 8 8 E		8306240145 8306240149* 8306240246 8306240246 8306270061	50-325 50-325 50-324 50-324 50-324	9 9 9
	8306080080 8306080080 8306080093* 8306080122 8306080149	50-324 50-324 50-324 50-261 50-400	P P F 0		8306270078 8306270100 8306270113 8306270113	50~325 50~400 50~400 50~400 50~400	8 E A A
	8306080149 8306080160 8306080160 8306090046 8306090046	50-400 50-400 50-400 50-400 50-400	0 0 8 8		8306270119 8306270196 8306270199 8306270217	50-324 50-324 50-324 50-400 50-400	8 8 8 E
	8306070136 8306070180 8306070181 8306070191	50-400 50-400 50-400	8 8 8 8		8306270223 8306270223 8306270223 8306270225 8306270241	50-400 50-400 50-324 50-324 50-400	8 P P
	8306070242 8306070251 8306070374* 8306100091 8306100091	50-400 50-241 50-400 50-400	8 F 0		8304270241 8304270245 8304270277 8304270271 8304270291	50-400 50-324 50-324 50-325 50-400	E 8 8
	8304100127 8304100177 8304100188 8304100188 8306100238	50-324 50-400 50-400 50-400	B S E E		8306270292 8306270448 8306270448 8306280088 8306280463	50-400 50-400 50-400 50-400 50-400	E E 8
	8306100234 8306100256 8306100260 8306140214	50-400 (50-400 (50-241 (50-241 ({		8306280463 8306280489 8306280324 8306280324 8306280344*	50-400 50-325 50-324 50-324 50-324	В О Р Р

AUTHOR AFFILIATION	AGCESSION NUMBER	SUBJECT CATEGOR	?Y	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC:	
	8306280544* 8306280559 8306290247 8306290395 8306290402	50-324 50-155 50-261 50-400 50-324	P P G G	Citizens Association for Sound Energy	8306270378* 8306280213* 8306280359 8306300160 8306070304	50-358 50-358 50-358 50-358 50-445	4 4 4 B 0
	8306270553* 8306270553* 8306270553* 8306270555* 8306270555*	50-261 50-261 50-261 50-261 50-261	a a a a		8304070304 8304070304* 8304070306* 8304070382 8304070382	50-445 50-445 50-445 50-445 50-445	00000
	8306270555* 8306270555* 8306300012 8306300031 8306300172	50~261 50~261 50~324 50~324 50~400	០ ១ ទ ទ		8306070394# 8306070394# 8306100223 8306100223 8306100227#	50-445 50-445 50-445 50-445 50-445	00000
Carpenter Technology Corp	8306300193 8306300193 8306300203 8306300242 8306150343	50-324 50-325 50-325 50-324 XPDRTLIC	5 5 5 6		8304100227* 8304100230* 8304150310 8304150310 8304150380	50-445 50-445 50-445 50-445 50-445	00000
Carrier Corp Catholic Univ of America, Washington, DC Center for Law in the Public Interest	8304010336 8304040182 8304150314	50-518 50-77 50-275 50-275 50-275	5 G G		8306150380 8306150406 8306150406 8306150414 8306150414	50-445 50-445 50-445 50-445 50-445	00000
Charlotts-Mecklenberg Environmental Cualition	8306150435 8306220038 8306280565 8306270535 8306130437	50-275 50-275 50-275 50-275 50-413	0 0 P 6	Citizens Concerned About Nuclear Power, Inc	8304150415* 8304150415* 8304080150	50-445 50-445 50-498 50-498	0000
Charnoff, G	8306270461* 8306270461* 8306270464* 8306270464* 8306170476	50-413 50-413 50-413 50-413 ADVCM	0 0 0	Cititans for Energy & Employment	8304080155* 8304080159* 8304080159* 8304220057 8304270218	50-498 50-498 50-498 50-498 50-341	0 0000
Chem-Nuclear Systems, Inc	8306200048* 8306080345 8306090202 8306210250 8306210256*	ADVCM 71-9176 71-9096 71-9108 71-9108		Citizens for Nuclear Reactor Safety, Inc Cleveland Electric Illuminating Co	8304040314 8304010058 8304080044 8304080044 8304100119 8304100119	50-170 50-440 50-440 50-440 50-440 50-440	0 E 4 4 B 8
Cherne Contracting Corp Chicago Bridge & Iron Co Christa-Maria	8306240394 8306240381 8306160639 8306010450 8306080232	27-47 71-9135 71-9141 50-155 50-155	0 0		8306100180 8306130305* 8306130305* 8306140661 8306160611	50-440 50-440 50-440 50-440 50-440	. <00.0
Cincinnati Gas & Electric Co	8304080235* 8304240423* 8304010151 8304010154* 8304020312	50-155 50-155 50-356 50-358 70-2672	9 К К		8306220015 830620085 8306200120 8306200120	50-440 50-440 50-440 50-440 50-440	9 8 8 8 6
	8304040074* 8304040079 8304040101* 8304040177 8304040254	50-358 50-358 50-358 50-358 50-358	A E E B A		6306220039 6306220039 6306220038 6306220038	50-440 50-440 50-440 50-440 50-440	8888
	8306070135 8306070232 8306070267 8306070267 8306070373	50-358 50-358 50-358 50-358 50-358	8 8 9 9		8306240186 8306240186 8306240269 8306240344 8306270115#	50-440 50-440 50-440 70-2968 50-440	4 E G
	8304080137 8304080140* 8304080213 8304070084 8304070127	50-358 50-358 50-358 50-358 50-358	E E 8 8		8304270287* 8304280141 8304280141 8304270214 8304270214	50-440 50-440 50-440 50-440 50-440	9 4 4 9 9
	8306130381 8306170321 8306210054 8306210058 8306210269	50-358 50-358 50-358 50-358 50-358	K R 8 H	Cleveland-Cliffs from Co Coalition for Nuclear Power Plant Postponement	8306270240# 8306300169 8306300169 8306170459 8306300195	50-440 50-440 50-440 40-8714 PR	8
	8306210294 8306220031 8306220036* 8306230081 8306230089	50-358 50-358 50-358 50-358 50-358	8 9 9	Coalition for Safe Power	8306010364 8306060308 8306150302 8306150306 8306160078	50-460 50-460 50-460 50-460 FOIA	9000
	8306230176 8306230268 8306230375 8306230435 8306230442	50-358 50-358 50-358 50-358 50-358	\$ \$ H \$	Colorado, State of Colt Industries, Inc	8305220129 8305290370 8305290375* 8305300219 8305300110	50-508 50-460 50-460 PR	990
	8306230472 8306270180 8306270331 8306270332	50-35B 50-35B 50-35B 50-35B	6 9 9 A	Columbia Univ. Combustion Engineering, Inc	8304240358* 8304010078* 8304010083*	CONTRACT 50-528 50-528	-

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEOD		AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJ CATE	ECT GORY
	8304010087* 8304070159* 8304070336* 8304070170 8304130428	50-528 50-317 0A999 50-470 50-470	S P A A		8306090227 8306090227 8306090227 8306090342 8306090342	50-23 50-23 50-23 50-45 50-45	7 P 7 P 4 G
	8306140683 8306200254 8306200392 8306230342 8306230419	50-335 50-470 50-470 NUREO REGOD	S A E		8306100062 8306100062 8306100064 8306100094 8306100094	50~37; 50~37; 50~27; 50~23; 50~23;	3 P 5 S 7 Q
Commerce, Dept of, Commerce, Dept of, National Bureau of Standards	8306300125* 8306300136* 8306020454 8306220282* 8306140290	50-361 50-361 PR CONTRACT XPORTLIC			8306100094 8306100094 8306100094 8306100094 8306100094	50-23; 50-23; 50-23; 50-23;	7 G 7 G
Committee to Bridge the Gap	6305140298 8305220327* 8305030459 8305150362 8305150392	XPORTLIC CONTRACT FOIA 50-142 50-142			8306100094 8306100149 8306100149 8306100149	50~297 50~237 50~237 50~237 50~237	, G
	8306170373 8306170379* 8306170370* 8306170417* 8306170426*	50-142 50-142 50-142 50-142 50-142	T T T T		8306100149 8306100136* 8306100136* 8306100178 8306100178		' G G S
Commonwealth Edison Co	8306290546 8306290552* 8305190370 8305260238 8306010457	50~142 50~142 50~373 50~237 50~454	0 0 P 0 0		8306100207 8306100207 8306100207 8306100207 8306100218	50-454 50-454 50-454 50-454 50-10	S
	8304010457 8304020193 8304020449 6304030218 8304030225	50~454 50~373 PR 50~237 50~454	ម J ទ ទ		8306100218 8306100218 8306100236 8306100236 8306100236	50-10 50-10 50-374 50-454 50-454	0 6 8 6
	8304030229 8304030229 8304030229 8304030272	50~454 50~454 50~454 50~454 50~454	9 9 9 1 1 1 1 1		8306100236 8306100246 8306100246 8306100246 8306100246	50-454 50-454 50-454 50-454 50-454	5 5 5
	6306030272 8306030272 8306030272 8306030281* 8306030281*	50~454 50~454 50~454 50~454 50~454	К К К К		8306100246 8306100250* 8306100250* 8306130226 8306130230*	50-454 50-373 50-373 50-249 50-249	5 0 P P
	8306030281* 8306030281* 8306030281* 830603040 8306060146	50-454 50-454 50-454 50-237 50-373	K K S P		8306130231 8306130278 8306130307 8306130328 8306130329	50-454 50-10 50-295 50-249 50-254	J 8 8
	8306060146 8306060148 8306060193 8306060193 8306060196*	50-373 50-304 50-454 50-454 50-454	P B G G G		8306130337 8306130346 8306130348 8306130349 8306130351	50-254 50-249 50-237 50-373 50-295	8 8 8
	8304040196# 8304040206 8304040212# 8304040232 8304040238	50-373 50-254	G S G S P		8306130352 8306130374 8306130382 8306130425 8306130439	50-373 50-237 50-237 50-237 50-237	S S F S
	8306060238 8306060250 8306070234 8306070246 8306070277	50~304 50~249 50~237	P 8 8 8 8		8306130445 8306130445 8306130452* 8306130452* 8306130454	50-454 50-454 50-454 50-454 50-10	0 0 0 R
	8306070334 8306070355 8306070355 8306070392* 8306090194	50-373 50-373 50-454	Л F P Q P		8306130454 8306130454 8306130457* 8306130457* 8306130457*	50-10 50-10 50-10 50-10 50-10	R R A A
	8305070174 8305070174 8305070174 8305070174 8305070174	50-237 50-237 50-237	P P P P		8304130460* 8304130460* 8304130460* 8304140003 8304140086	50-10 50-10 50-10 50-10 50-237	R R J A
	8306070174 8306070174 8306070174 8306070174 8306070221	50-237 50-237 50-237	፡ የተ የ የ		8306140086 8306140412 8306150402 8306150402 8306150420	50-237 50-275 50-454 50-454 50-454	R R O O
	8306090221 8306090223* 8306090227 8306090227	50-454 F 50-237 F	F F P		8306150420 8306150636# 8306160077# 8306160224 8306160225	NUREQ	F F

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	Y	AUTHOR AFFILIATION	ACCESBIGN NUMBER	SUBJECT CATEGOR
	8306160233 8306160233 8306160233 8306160233	50-237 50-237 50-237 50-237	P P P P		8306270041 8306270041 8306270071* 8306270108 8306270111	50-454 50-454 50-454 50-254 50-249
	8306160435* 8306160596 8306170045 8306170045 8306170283	50-373 50-440 50-454 50-454 50-373	9 9 8 5 <i>J</i>		8306270168 8306270221 8306270247 8306270252 8306270302	50-275 50-304 50-237 50-254 50-373
	8304170314 8304170314 8304170344 8304170380 8304170380	50-254 50-254 50-265 50-237 50-237	R R G G		8306270322 8306270322 8306270322 8306270322 8306270322	50-454 50-454 50-454 50-454 50-454
	8304170380 8304170380 8304170380 8304170380 8304170380	50-237 50-237 50-237 50-237 50-237	0 0 0 0		8306270345 8306270345 8306270373 8306270373 8306270373	50-454 50-454 50-454 50-454 50-454
	8306170380 8306170407 8306200265 8306200300 8306200300	50-237 50-249 50-237 50-454 50-454	Q 5 P Q Q		8306270373 8306270383 8306270383 8306270387 8306270392*	50-454 50-454 50-454 50-237 50-237
	8306200304 8306200304 8306200350 8306200350 8306210045	50-454 50-454 50-454 50-454 50-373	0 0 0 0 9 5		8306270393 8306270431 8306270431 8306270431 8306270431	50-454 50-454 50-454 50-454 50-454
	8304210073 8304210089 8304210192 8304210205 8304210211	50-295 50-373 50-373 50-373 50-454	Р 5 Г К		8306270431 8306280323 8306280377 8306280302 8306280528	50-454 50-373 50-304 50-373 50-454
	8306210211 8306210211 8306210234 8306210263 8306210277	50-454 50-454 50-304 50-373 50-373	K K 8 8		830520035 8305300032 8305300032 8305300032 8305300032	50-454 50-374 50-374 50-374 50-374
	8306210308 8306210357* 8306220001 8306220019 8306220034*	50-373 50-10 50-454 50-373 50-254	8 F E B		8306300043 8306300073* 8306300216* 8306300216* 8306300237	50-254 50-373 50-295 50-295 50-254
	8306220034* 8306220064 8306220067 8306220086 8306230037*	50-254 50-373 50-254 50-237 50-373	G 8 G R A	Computer Data Bystems, Inc Conax Corp Conference of Radiation Control Program Directors, Inc Connecticut Yankee Atomic Power Co	8306090379* 8306170336* 8306130251*	FDIA 50-390 CONTRACT 50-213
	8306230039* 8306230219 8306230219 8306230237 8306230237	50-373 50-295 50-295 50-454 50-454	A P P A		8306020248 830606090 830606090 830606090 830606090	50-213 50-213 50-213 50-213 50-213 50-213
	9304230237 9304230237 9304230257 9304230257 9304230257	50-454 50-454 50-454 50-454 50-454	A A F F		8306060243 8306100114 8306150338* 8306150341* 8306160053	50-213 50-213 50-213 50-213 50-213
	8306230257 8306230257 8306230294 8306230294 8306230385	50-454 50-454 50-456 50-456 50-454	F A A G		8305150459 8305170051 8305170231 8305170301 8305170347	50-213 50-213 50-213 50-213
	8306230385 8306230412 8306230412 8306230412	50-454 50-454 50-454 50-454 50-454	f F		8306170391 8306170391 8306170391 8306200391* 8306230100*	50-213 50-213 50-213 50-213 50-213
	8306230412 8306230425 8306240030 8306240035 8306240035*	50-454 REGQD 50-237 50-237 50-237	P P		B306230102* B306230426 B306240200 B306240200 B306270001	50-213 50-213 50-213 50-213 50-213
	8306240035* 8306240252 8306240252 8306240252 8306240252	50-237 50-374 50-374 50-374 50-374	A	Connecticut, Univ of Conner & Wetterhahn	8306270004* 8306270361 8306020032* 8306060322	50-213 50-213 70-2953 50-352 50-352
	8304270002 8304270016 8306270016 8306270020* 8306270020*	50~373 50~454 50~454 50~454 50~454	0 0 0		8306070295 8306070299* 8306070299* 8306070301*	50-352 50-352 50-352 50-352

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC CATEGO	RY	AUTHOR AFFILTATION	ACCESSION NUMBER	SUBJECT CATEODRY
	8304070301* 8304070373 8304080107* 8304090212 8304090212	50-352 50-358 ADVCM 50-352 50-352	6 6 6		8304070248 9304070282 8304080045 8304090203# 8304090287#	50-255 S 50-255 S 50-155 P 50-255 F 50-255 F
	8306090240 8306090240 8306100206 8306140740* 8306150393	50-352 50-352 50-458 ADVCM 50-352	G G G		8304090321 8304100055 8304100179 8304100181* 8304100222	50-329 A 50-155 F 50-255 R 50-255 R 50-155 P
	8306160603 8306220031 8306220036* 8306270122 8306270274	50-352 50-358 50-358 50-410 50-410	6 6 6		6304100268 6304100268 8304100269* 8304100269* 6304100272*	A 75E-06 A 75E-06 A 75E-06 A 75E-06 A 75E-06
Consolidated Edison Co of New York, Inc	8306270413 8306010126* 8306020276 8306070343 8306070414	50-352 50-247 50-247 50-247 50-247	G G R P G		8304130051 8304130281 8304130281 8304130310 8304130334	30-155 P 30-329 6 30-329 8 50-255 R 50-255 F
	8304090299 8304090299 8304090317 8304090317 8304090325	50-247 50-247 50-247 50-247 50-247	F F F F		8304130335* 8304130348 8304130394 8304140223* 8304140227*	50-255 F 50-329 A 50-255 S 50-155 F 50-155 F
	8306070325 8306070340 8306070340 8306070357 8306150427	50-247 50-247 50-247 50-247 50-247	F F G G		8306140524 8306140524 8306140831* 8306150003 8306150346*	50-327 A 50-327 A 50-255 F 50-155 P 50-329 F
	8304160462 8304170044 8304170187 8304170197 8304170200	50-247 50-247 50-247 50-247 50-247	R 8 8 8		8306150346# 8306150351# 8306150351# 8306150405 8306150407#	50-329 F 50-329 F 50-329 F 50-155 0 50-155 0
	8306170230* 8306170271 8306170323 8306170397 8306170405	50-247 50-247 50-247 50-247 50-247	0 8 8 8 8		8304130413+ 8304140235 8304140380 8304140443 8304140448	50-155 q 50-329 A 50-155 P REOOD REOOD
	8306170410 8306170415 8306200297 8306200342 8306200342	50-247 50-247 50-247 50-247 50-247	6 6 P T		8306160566 8306170218 8306170355 8306200015* 8306200230	50-155 R 50-155 F 50-155 G 50-155 F 50-155 P
	8306200346* 8306200346* 6306230376 8306240223 8306240372	50-247 50-247 50-247 50-247 71-6601	T T G G		8306200367 8306210102* 8306210151 8306210173 8306210302	50-155 P 50-155 G 50-255 J 50-155 F 50-329 B
	8306270083 8306270160 8306270171 8306270171 8306270179*	50-249 50-247 50-3 50-3 50-3	5 0 R R R		8306210302 8306220013 8306220023 8306220029	50-327 8 50-255 8 50-255 P 50-155 9 50-255 8
	8304270179* 8304270184* 8304270184* 8304270327 8304270327	50-3 50-3 50-3 50-295 50-295	R R G G		8304530010* 8304550524 8304550105 8304550042	50-155 g 50-155 g 50-155 g 50-255 g 50-155 g
Consumers Power Co	8304290335* 8304290335* 8112090541 8305240224 8305240245	50-275 50-275 50-255 50-155 50-155	Q G S R R		8306230241 8306230250 8306230250 8306230278 8306230287	50-135 S 50-327 A 50-327 A 50-327 A 50-155 P 50-255 R
	8304010281 8304010342 8304020283 8304020337 8304030172	50-155 50-155 50-155	P P Q R		8306230374 8306230413 8306240004 <i>83062</i> 40137 8306240285	50-255 P 50-255 P 50-155 P 50-155 P 50-155 F
	8306030172 8306030223 8306030230* 8306030362 8306060035*	50-155 50-155 50-255	R P P P Q		8306240285 8306240285 8306240401 <i>8306270063</i> 8306270076	50-135 F 50-155 F 71-7033 50-255 S 50-155 P
	8306060095 8306060119 8306060144 8306060145 8306060149*	50-155 50-155 50-255	R 면 면 면 면 면		8306270079* 8306270107 8306270109* 8306270128 8306270173	50-155 P 50-155 P 50-155 P 50-155 P 50-155 Q
8 6 8	3304040172* 3304040172* 3304070068 3304070234 3304070242	50-327 50-255 50-255	A A G B B		8304270242 8304270349*	50-327 A 50-327 A 50-327 A 50-327 A 50-155 Q

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	Y	AUTHOR AFFILIATION	ACCESSION NUMBER	TOALBUB ROQUES	łY
	8306270432 8306270435 8306270391 8306270412 8306270493	50-255 50-255 50-155 50-155 50-229	S S P P A		8306100199* 8306100199* 8306130501 8306150354 8306150366	50-413 50-413 ADVCM 50-500 50-445	0 0 0
	B306300065 B306300105* B306300105* B306300109* B306300109*	50-329 50-329 50-329 50-329 50-329	A A A A		8306150376 8306150425 8306160069 8306170334 8306170406	50-445 50-445 Foia Nureg 50-445	0
Continuum Dynamics, Inc Converse, Ward, Davis, Dixon, Inc	8304300112* 8304300112* 8304270224* 8304270230* 8304230059*	50-329 50-329 50-324 50-324 Contract	^ А Р Р	Del-Aware Unlimited, Inc Detroit Edjson Co	8305230364 8306300047 8306010369 8306220051 8306010168	50-460 50-460 50-352 50-352 50-341	0 0 0 K
Cooper Industries. Inc Cornell Univ Council on Economic Priorities	8306100203 8306140253* 8306160138* 8306230238 8306210322	50-528 50-97 FOIA 50-97 FOIA	8 Q F		B306010174* B306010178* B306030171 B306060187 B306060245	50-341 50-341 50-341 50-341 50-341	K K 8 8
Covington & Burling Custom Alloy Garp Dairyland Power Conperative	8306210330 8306230006 8306070163* 8306020291 8306070040	FDIA FDIA GA979 50-409 50-409	R 9		8306070085* 8306130292* 8306140614 8306160357 8306170233	50-341 50-341 50-341 50-341 50-341	G G A A B
	8306070079 8306070311 8306070332 8306100184 8306130314#	50-407 50-407 50-409 50-409 50-409	P C G P G		8306170419 8306220024* 8306220030* 8306280438 8306280585	50-341 50-341 50-341 50-341 50-341	8 G A F
	8306140707 8306150277 8306150283* 8306160279* 8306160378	50-409 50-409 50-409 50-409 50-409	P P F R	Dolan & Dolan Dorsey, J A Dover General Hosp Dover,NJ	8304040002 8304030280 8304150342 8304270297 8304020405#	FOIA 50-352 50-352 50-352 70-2548	9
	B306170376 B306210066 B306210122* B306210132 B306270337	50-407 50-409 50-409 50-409 50-409	2 b b b	Duke Power Co	9306010015 9306010098 9306010104 9306010123 9306010256	50-370 50-369 50-370 50-369 50-369	8 8 8
Damans & Associates Data Consultants.Inc Data Stor, inc	6306270302 8306300006 8306060072* 8306220268* 6306210297	BO-409 BO-409 CONTRACT CONTRACT			9306010401 9306020639 9306020646* 9306030122 9306030122	50-369 70-2985 70-2985 50-269 50-269	8 P P
Dataflow Bystems, Inc Dauphin County, PA David W Taylor Noval Research & Development Center	8304230048* 8304140400 8304280538 8304040410	CONTRACT 50-289 50-289 NUREG	G G		8306030122 8306030300 8306030300 8306030315 8306030315	50-269 50-413 50-413 50-369 50-369	P ♠ P
DeGraff, Foy, Conway & Holt-Harris DeKalb Area Alliance for Responsible Energy	8306160578 8306160582* 8306080143	50-410 50-410 50-454	0 0 0		8306060076* 8306060301 8306070051 8306070131 8306070131	50-249 50-413 50-249 50-349 50-369	P P P
	8306080145* 8306080145* 8306100201 8306150436*	50-454 50-454 50-454 50-454	0 0 0 0 0		B306070134* B306070134* B306070143 B306070206 B306070210*	50-369 50-369 50-369 50-413 50-413	P 8 E E
	8306150442* 8306150442* 8306170371 8306200327* 8306200327*	50-454 50-454 50-454 50-454 50-454	0 0 0		8304070248 8304070249 8304070249 8304070272 8304070272	50-369 50-369 50-369 50-269 50-269	P F P P
Debevoise & Liberman	8306200331 * 8306200331 * 8306270022 8306020365 8306020431	50-454 50-454 50-454 50-460 50-508	• •		8306070272 8306070283 8306070283 8306070314 8306070314	50-269 50-369 50-369 50-413 50-413	P P E E
	8304030330 8304030347 8304030353 8304040301	50-445 50-460 50-460 50-413	0 0 0		8306070349 8306080170 8306080170 8306090015 8306090040	50-413 50-413 50-413 50-370 50-370	F 0 9
	8306080313 8306080170 8306080239 8306080239 8306080243*	PRM 50-413 50-445 50-445 50-445	9 9		8306090147 8306090361 8306100138 8306100164 8306100185	50-369 50-269 50-370 50-370 50-370	8 F 8 8
	8304080243* 8306070337 8306100004 8306100170	50-445 50-469 ADVCM 50-460	Q		8306100197 8306100197 8306100197* 8306100199*	50-413 50-413 50-413 50-413	0
	8306100197 8306100197	50-413 50-413	9		8304100216	50-370	8

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJE	ORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8306100243 8306130312 8306130316 8306130342 8306130448	50-370 50-370 50-370 50-369 50-369	8 8		8306070264 8306070187 8306070368 8306100104 8306140620	50-334 F 50-334 F 50-334 P 50-334 Q 50-334 Q
	8306140018 8306140018 8306140119 8306140123 8306140127	50-413 50-413 50-413 50-413	G G		8306140639 8306140643# 8306140672# 8306130355* 8306160476	50-334 P 50-334 P 50-412 Q 50-412 Q 50-334 R
	8306140502* 8306140680 8306140686* 8306140738 8306150177	50-413 50-370 50-370 50-269 50-369	P P F		8304170030 8306200334 8306200382 8306210141 8306280139	50-334 8 50-334 P 50-334 9 50-412 8 50-334 \$
	8304150177 8306160460 8306170297 8306170311 8306170311	50-369 Reggd 50-269 50-369 50-369	P R R	Dybell/Ware & Associates, Inc	8306280495 8306300495 8306300210 830630021 8306280091*	50-334 Q 50-334 Q PR 50-334 R CONTRACT
	6306170316 6306170316 6306200212 6306200237 6306200238	50-413 50-413 50-369 50-369 50-370		E C Rodabaugh Associates, Inc E K Fox & Associates, Ltd E L Manufacturing Peebles, Inc EOS Nuclear, Inc EGSQ, Inc	8304230031* 8304170029* 8304210033* 8304170320* 8304020011	A CCC-08 TOANTMOD PEPAB PENGUT OBNUM
	8306200245 8306200264 8306200321 8306200332 8306200352	50-349 50-369 50-370 50-369 50-369	6 5 5 1 1		8304030088* 8304080141 8304080229 8304140441* 8304140470*	50-397 A 50-335 P 866 50-389 P 71-9134
	8306200352 8306200352 8306210092 8306210097* 8306210190	50-349 50-349 50-349 50-349 50-287	1 P P S	ENGA, Inc Ebasco Services, Inc (subs of Engerch	8306060366 8306190081 8306170263 8306240062 8306020513*	NUREG NUREG NUREG NUREG CONTRACT
	8306220092 8306220092 8306220295* 8306220295* 8306240123	50-413 50-413 50-413 50-413 50-413	G F E	Corp) Eédleman, W	8306140115# 8306010355 8306010357 8306030337	50-387 P 50-400 8 50-400 0 50-400 0
	8306240183 8306270094 8306270094 8306270118 8306270124	50-413 50-369 50-369 50-413 50-369	8 8 8 8		8306070222 8306270307 8306270307 8306270313* 8306270313*	50-400 0 50-400 0 50-400 0 50-400 0
	8306270187 8306270227 8306270301 8306270384 8306280427	50-349 50-349 50-369 50-413 50-349	F 8 8	Ederer, Inc	8306270402 8306270361 8306270381 8306300124 8306020364	50-400 Q 50-400 Q FR TOPREP
	8306270245 8306270282 8306270457 8306270457 8306270461*	50-269 50-369 50-413 50-413 50-413	0 0 0	Edison Electric Institute Edlow International Co	8306160149 8306300223 8306030169 8306150467	PR FOIA PR KPORTLIC XPORTLIC
	8306270461# 8306270464# 8306270464# 8306270340 8306270340	50-413 50-413 50-413 50-413 50-413	G G G	Electric Power Research Institute Energy Fuels Nuclear, Inc Energy Incorporated	8306270282 8306230027 8306230027 8306240263* 8306270413*	50-10 8 NUREQ 40-8681 10PREP 50-245 P
	8306300002 8306300015 8306300114 8306300171 8306300174	50-369 50-267 50-370 50-370 50-287	6 8 8	Energy Research Group, Inc Energy, Dept of	8306040188* 8306070386* 8306020241* 8306010001 8306010085*	50~322 0 CONTRACT 71~6400 71~6400
	8306300189 8306300191 8306300191 8306300198# 8306300204#	50-370 50-369 50-369 50-369 50-369	5 6 6 8		8306010103 8306020192 8306020194 8306020228 8306020231	WASTE HOT WASTE HOT WASTE HOT WASTE HOT WASTE HOT
Duquesna Light Co	8306300232 8304110818 8304110827* 8306010072 8306010275	50-370 50-334 50-334 50-412 50-334	8888		8306040203 8306040203 8306060417 8306080148 8306080153#	A TEC-DE A TEC-DE TOM STEAM TOM STEAM
	8306010302 8306020218 8306020324 8306020383 8306020428	50-334 50-334 50-334 50-334 50-412	8 R 8 8		8306090333 8306130407* 8306130407* 8306140695 8306150229	SO-537 A 50-537 A HASTE HOT WASTE HOT
	8396920449 8396939393* 8396969293* 8396979076 8396979129	50-334 50-334 50-412 50-334 50-334	8 0 1 1		8306160210 8306160642 8306160664 8306160667* 8306170462	NUREO WASTE MOT 71-9134 71-9132

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEOOR	RY	AUTHOR AFFILLATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8309510301 8309500355 8309500355 8309500015	WASTE MG 71-4960 50-537 50-537 40-1341			8306130291 8306130435 8306130441* 8306140009 8306140011	50-387 50-250 50-250 50-369 50-369
	8306210428 8306220048 8306220169 8306220173# 8306220208	40-1341 50-537 WASTE MO WASTE MG WASTE MG	9T		B306140033* B30614003B* B306140097 B306140111 B306140510*	50-335 50-335 50-369 50-369 50-389
	8306240033 8306240044¤ 8306240044¤ 8306240179 8306240297	WASTE MG 71-5595 71-5595 WASTE MG WASTE MG	g t		8306140572 8306140581 8306140638 8306140745 8306160335	50-335 50-389 50-387 50-335 50-250
	8306240482 8306270317 8306270566 8306270620 8306270626*	WASTE MG 50-537 50-201 50-201 50-201	GT G P P		8306160638 8306160662* 8306160666* 8306170287 8306170292*	50-250 50-387 50-387 50-387 50-387
Energy, Dept of, Clinch River Breeder Reactor Plant Engineering Science	8304300119 8304300223 8304240233 8304220227*	50-373 PR 50-537 CONTRACT	Г А Т		8304170299* 8304170304* 8304170319 8304200094 8304200144	50-387 50-389 50-335 50-389 50-389
Environmental Policy Institute Environmental Surveillance Laboratory	8306060248* 8306060248* 8306300137 8306300142 8306210432*	PRM PR PR PR CONTRACT			8305200180 8305200174 8305200175* 8305200310 8305210071	50-387 50-389 50-389 50-387 50-250
Envirosphere Co Eugene Water & Electricity Board European Communities, Commission of	8306220246* 8306200215* 8306150340 8306160620 8306160716 8306160720	SO-344 XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC	t C C		8306210081 8306210160 8306210169* 8306210197 8306210261	50-389 50-389 50-389 50-251 50-389
Exxon Curp	8306300146 8306060318 8306070456 8306200421	NUREQ 40-8064 40-8064 40-8064			8306210388* 8306210372* 8306220014 8306220236* 8306220236*	50-367 50-387 50-389 50-335 50-335
Exxon Nuclear CO , Inc (subs of Fixon Corp)	######################################	RR XPORTLIC XPORTLIC XPORTLIC TOPRCP	C		8304270200 8304280168 8304280250 8304280354 8304280474	50-251 50-250 50-335 50-335 50-369
	8306090194 8306130500* 8306140288 8306170294 8306240396	TOPREP 70-1257 XPORTLIC REGOD 70-1257	C		8304290338* 8304290345* 8304290351* 8304290376 8304300025	50-335 50-250 50-335 50-250 50-387
FOI Services Fairness Committee Against Tax Funded Politics	8306280240 8306070441 8306160015	TOPREP FOIA FOIA		Florida Power Corp	8304300153 8304300154 8304030320 8304030322* 8304070273	50-389 PR 50-302 50-302 50-302
Falkenheiner, D Fearer & Nyc Federal American Partners Federal Emergancy Management Agenry	8306220117 8306060302 8306200067	50-458 50-454 40-4472 50-397	F		8304070300 8304090145 8304140437 8304140431*	50-302 50-302 50-302
	8306070114 8306070118 8306100086 8306240308	50 327 50-155 50-247 50-344	F Q F		8304170221 8304200033 8304220049 8304230429 8304230449	50-302 50-302 50-302 50-302 50-302
Fleischaker, D S Flemming, Anderson, McClung & Finch Florida Power & Light Co	83052403108 8305040415 8305080175 8305010007	30-344 30-382 30-273 30-361 30-387	r 0 0 5		8304230445 8304240259 8304300042* 83043000225	50-302 50-302 50-302 50-302
	8306010116 8306010272 8306020216 8306030074 8306060082	50~389 50~389 50~250 50~389 50~389	\$ \$ R P	Floridians United for Bafe Energy	8306300229# 8306300157 8306300161 8306300227	50-302 PR PR PR
	8304070078 8304070184 8304080004* 8304070352	50-367 50-369 50-250 50-250	\$ \$ Q	Foster, R Foundation for National Progress Franklin Institute/Franklin Research Center	8306200168 8306160024 8302250381*	ACRB FOIA 30-334
	8306090355* 8306090355* 8306100087	50-250 50-250 50-250 50-335	ն ե ե		8305200714# 8305230021# 8306020037# 8306020196# 8306030070#	50~305 50~282 50~309 50~302 50~338
	0306100140 0306100144* 0306130156 0306130260	50-389 50-389 50-389 50-387	P P		6304030299# 8304030310* 8304030444* 8304030512*	50-315 50-317 50-280 50-295

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY		AUTHOR AFFILIATION	ACCESSION NUMBER	CATEQUAY	,
	8305050329* 8305080252* 8305090388* 8305090397* 8305140424*	50-335 50-278 50-312	- Ե Ե		8306010407 8306020090 8306020096 8306020341 8306020353	50-219 50-320 50-219	R R P Q S
s of the Earth	0304150266* 0304210446 0304220192* 0305160024 0306200324	ACRS CONTRACT	Р 6 6		8306020378 8306060181 8306070215 8306070215 8306070027*	50-287 50-289 50-289	5 P R R
hnologies, Inc /Qeneral Atomic Co	8304270038 8304020470 8304070274* 8304070450 8304100005	50-352 XPORTLIC GA999 ADVCM 70-734	G		8306090031* 8306090235 8306090271* 8306100120 8306130137	50-219 50-219 50-289 50-289 50-320	F F G
	8306160545* 8306160560* 8306160564* 8306170334 8306210408	50-267 50-267 50-267 NUREO 71-6346	P P P		8306130384 8306130395* 8306140014 8306140480 8306140586	50-219 50-287 50-289 50-289 50-289	P G P P
tt Corp eart-Gwen Industries, Inc nger Hedical Center Danville,PA al Electric Co	8306210415# 8306300202 8306170077 8306060226 8306020234	71-6346 50-389 70-498 PR 70-754	s		8306140600 8306140623 8306140732 8306150030* 8306160258*	50-320 50-289 50-289 50-289 50-219	Q F F Q
	8304020303* 8304020379* 8304030083 8304070105 8304070111*	50-277 50-277 XPORTLIC 50-447 50-447	P P K		8304170025 8304170254 8304170282 8306200127 8306200244	50-320 50-289 50-320 50-289 50-289	9 P S
	8304070114* 8304070171* 8304070174* 8304070201 8304080105	50-447 0A999 50-293 50-447 TOPREP	к ₽ К		8304200340 8304200357 8304210040 8304210005 8304210247	50-217 50-320 50-287 50-217 50-287	F 6 9 8
	0304070236 930400072 1210014058 9304100125 9302130329*	50-447 50-352 PY21 50-482 50-322	8 8		8304210254* 8306210256* 8306220035 8306220054 8306220276*	50-289 50-289 50-320 50-320 50-289	\$ \$ P F
	8304130331* 8304130332* 8304140122 8304140238* 8304140338*	50-322 50-322 70-1113 CONTRAC 70-1113	T		8306240319 8306270231 8306270233* 8306270234* 8306280365	50-287 50-289 50-289 50-289 50-289	F P P S
	8306150348 8306150453 8306150602 8306160470 8306160516	XPORTLI XPORTLI NUREO 50-70 PT21	С		8306280366 8306280406 8306300078 8306300148 8306300162	50-207 50-219 50-209 50-450 50-209	Q P Q B R
	8306160648 8306170214 8306170318 8306170320* 8306200247*	XPORTL 1 50-447 TOPREP TOPREP 50-397	C A E	General Research Corp Georgia Power Co	8306140426* 8305310144 8306010367 8306010371* 8306030042	60NTRACT 50-321 50-366 50-366 71-7176	9 P P
	8304200253# 8304200255 8304210028# 8304210153# 8304240232#	50-397 TOPREP GA999 TOPREP 50-322	E		8306030233 8306070080 8306070123 8306070123 8306070123	50-321 50-321 50-321 50-321 50-321	F E I I
	9304280456# 6304290220# 8304290481 6304290495 6304290500#	50-397 50-440 50-447 50-447 50-447	E K K		8306070125 8306070129 8306070129 8306070130* 8306070224	50-366 50-321 50-321 50-321	0 P I P
	B304290504# B304290507 B304290512# B304290515# B304290525#	50-447 50-447 50-447 50-447 CONTRA	K K K K		8306070259 8306070347 8306070351 8306070351 8306070357*	50-366 50-321 50-321 50-321 50-321	ե 6 8
ral Electric Uranium Management Cor ral Physics Corp.	8306300131 8306300165	NUREG PR 70-130 CONTRA FOIA			83061007357 * 8306100132 8306100221 8306100221 8306100231	50-321 50-366 50-424 50-424 50-424	8 8 P
oral Public Utilities - OPU Bervice	83062400124 8306290633 8306020461	50-219	CT I		8306100231 8306100259 8306100259 8306100264 8306100264	50-424 50-424 50-424 50-424 50-424	9 8 8 A A
·p.	8305060487 8306010314 8306010329 8306010331	50-289 50-313 50-320 50-289 50-289	9 9 9		8306100265* 8306100265* 8306100267* 8306100267*	50-424 50-424 50-424 50-424	A A A
	8306010353 8306010404	50-219			6306100274	50-424	B

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGOR		AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8306100274 8306130264 8306140075 8306140075 8306140246#	50-424 50-366 50-321 50-321 50-321	9 9 P F		8306100206 8306130317 8306130376 8306160353 8306160439	50-458 1 50-458 1 50-458 50-458 50-458
	8306140246* 8306140254* 8306140254* 8306140473* 8306140563	50-321 50-321 50-321 50-321 50-366	F F V Q		8306160520 8306160521 8306160531 8306170395 8306270095	50-458 50-458 50-458 50-458 50-458
	B306140743* B306150041* B306150044* B306150137* B306150141*	50-321 50-321 50-321 50-321	요 F F F F		8306270130 8306270156 8306270391 8306280328 8306280355	50-458 50-458 50-458 50-458 50-458
	8306150228 8306150232* 8306160267 8306160267 8306160397	50-366 50-366 50-321 50-321 50-366		H&R Technical Associates, Inc HHB, Dept of UB Public Health Service Hall, N	8306200121 8306220320 + 8306060402 + 8306220138 + 8306200134 +	50-458 CONTRACT FOIA CONTRACT CONTRACT
	8306170202 8306170382 8306200004 8306200202 8306200205	50-321 50-321 50-366 50-321 50-366	F R S S S	Hamel, Park, McCabe & Saunders Harmon & Weiss	8306280186 8306010382 8306010446 8306150389 8306160337	FOIA 50-443 50-443 50-247 PR
	8305200251 8305200374 8305220002 8305220002 8305220010*	50-321 50-321 50-321 50-321 50-321	3 3 9		8306140604 8306220153# 8306230350 8306240003 8306290556	50-289 50-537 50-247 FOIA 50-443
	8306220310* 8306220310* 8306220313* 8306240274 8306270120	50-321 50-321 50-321 50-424 50-366	P F A P	Harold J Spelman & Associates Harvard Univ	8306300142 8306080273 8306200042 8007030104* 8306170271*	PR 40-2061 40-2061 FOIA FOIA
	8306270166 8306270170 8306270175* 8306270328 8306280361	50-424 50-366 50-366 50-366 50-321	8 6 6 6	Hepford, Swartz, Menaker & Morgan Heritage Foundation	8306170295+ 8306170296+ 8306280190 8306280387 8306160148+	FOIA FOIA NUREO 50-320 FOIA
	8306280468 8306290264 8306290264 8306290265* 8306290265*	50-366 50-321 50-321 50-321 50-321	5 Q Q Q	Hittman Nuclear & Development Corp (subs Hittman Corp)	8306020533* 8306020540* 8306020572* 8306080340* 8306080342*	71-9080 71-9080 71-9080 71-9017 71-9017
Geptechnic#l Engineers, Inc	8306290303* 8306290455 8306290455 8306300085 8306170259*	50-321 50-321 50-321 50-321 CONTRACT	G G G	Hoke, Inc	8306130185* 8306130198* 8306130212* 8306030160 8306150345	71-7087 71-7087 71-7087 71-9087 XPORTLI XPORTLI
Gibbs & Hill, Inc (subs of Drayo Corp) Gilbert/Commonwealth Cos	8306220305* 8306020420 8306060059* 8306140737* 8306200316*	CONTRACT REGOD 50~244 50~289 50~244	р F Р	House of Rep , Energy & Commerce	8306020248* 8306140323* 8306300074 8306030158* 8306060380*	50-322 50-322 50-287 50-247 COMMISS
Gilby Associates Godfrey & Sundahl Good, R P	8306220055* 8306240312* 8306300172 8306200036 8306200335	50~302 50~244 NUREO 40~8714 50~358	P P	House of Rep , Interior & Insular Affairs Houston Lighting & Power Co		50-272 50-289 50-498 50-498 50-498
Government Accountability Project	8304080284 8304140035 8304140172 8304200345* 8304200357*	50-528 50-327 FOIA 50-358 50-358	A A G G		8304130350 8304140052 8304170388 8304200122 8304200122	50-498 50-498 50-498 50-498 50-498
	8306290498 8306290498 8306290530 8306290530 8306290551#	50-329 50-329 50-329 50-329 50-329	0 0 0		8305200125* 8305200125* 8305230450 8305300077 8305300173	50-498 50-498 50-498 50-498 NUREQ
Oreater New York Council on Energy Oreanblatt: D Greeneville Metal Manufacturing: lnc Oulld: R	8304200270 8304090225 8304070308* 8304070312* 8304150385	50-247 50-400 04999 04999 50-413	G G	Hovis, Cockrill, Weaver & Sjur Human Design Group Hunton & Williams	8305240128# 8305230501* 8305010437 8305010443# 8305030355	FOIA 50~320 50~443 50~443
Gulf Nuclear, Inc Gulf States Utilities Co	8304040374 8304210305 8304010374 8304010423 8304070175	71-210 71-9163 50-458 50-458 50-458	ទ ទ ទ		8304030355 8304030357= 8304030359* 8304070405 8304080171	50~441 50~441 50~441 50~32, 50~321
	8306070176 8306070265 8306070038 8306070365 8306100206	50-458 50-458 50-458 50-458 50-458	8 5 8 6		8306080177* 8306090295 8306130404 8306130411	50-32; 50-32; 50-32 50-32

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC		AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8306130446 8306150370 8306160287 8306220017	50-322 50-322 50-322 50-322	o G	International Brotherhood of Electrical Workers International Energy Associates, Ltd	8306080095 8306160134*	ADVCM FOIA
IIT Research Inst	8306300147 8306070465*	50-322 CONTRAC	G	International Generation & Transmission Co .Inc Interstate Court Reporters, Inc	8306210375* 8306210323*	CONTRACT FOIA
Ichthyological Associates, Inc Idaho National Engineering Laboratory Illinois Institute of Technology	9304070217# 9304300144# 9304270157 9304020437	50-289 50-289 NUREO 50-454		Iowa Electric Light & Power Co	8306210326* 7020606028 8306090326*	FOIA 50-331 S 50-331 Q
Illinois Power Go	8306130408 8306020203	50-454 70-2947	G		8306100103 9306130375 8306130378*	50-331 S 50-331 S 50-331 S
	8306070289 8306070338 8306070396	50-461 50-461 50-461 50-461	5 K K		8306140590 8306160389 8306160460 8306170337	50-331 Q 50-331 P REGOD 50-331 S
	8306100060 8306100097 8306100141 8306170370	50-461 50-461 50-461 50-461	2 2 2 3		8306200223 8306230348 8306270089 8306270290	50-331 R 50-331 P 50-331 G 50-331 S
	8306170383 8306200409 8306200414* 8306210231 8306270117	50-461 50-461 50-461 50-461 50-461	S F P A Q	Iowa State Univ Isham, Lincoln & Beale	8306270420 8306270426* 8306100275 8306010457	50-331 P 50-331 P 50-116 G 50-454 G
	8306270321# 8306270334	50-461 50-461	0 5		8306020339 8306060193 8306060193	50-155 G 50-454 G 50-454 G
Illinois, State of Illinois, State of. Dept Nuc Safety (formerly Dept. Public Health) Illinois, Univ. of. Urbana-Champaign	8306070247 8306160214 8306240371	50-10 50-10 27-39 50-151	F F G		8306060176* 8306060315 8306080385 8306130445 8306130445	50-454 9 50-329 G ADVCM 50-454 G 50-454 G
Indiana & Michigan Electric Co	8306020107 8306020111* 8306020118*	50-315 50-315 50-315 50-316	R R R		8306130452* 8306130452* 8306150402 8306150402	50-454 G 50-454 G 50-454 G 50-454 G
	8306020281 8306020281 8306060183 8306060183 8306060185*	50-315 50-315 50-315 50-315 50-315	v v & & & & & & & & & & & & & & & & & &		8306150420 8306150420 8306150420 8306200300 8306200300	50-155 G 50-454 G 50-454 G 50-454 G 50-454 G
	8306060186* 8306060269 8306060271* 8306060273* 8306070208	50-315 50-316 50-316 50-316 50-315	ម ខ ខ ខ ខ ខ ខ ខ ខ ខ ខ ខ ខ ខ ខ ខ ខ ខ ខ ខ		8304200304 8304200304 8304200304 8304200350 8304220004	50-454 G 50-454 G 50-329 G 50-454 G 50-329 G
	8306160343 8306160358* 8306160367* 8306160384 8306170129	50-315 50-315 50-315 50-316 50-315	R R R R		8304220049 8304220023 8304220023	50-329 G 50-155 G 50-155 G 50-329 G
	8306210038 8306210065* 8306210065* 8306210074 8306210128	50-315 50-315 50-315 50-316 50-315	s a a s		8306220069 8306220102 8306220105 8306270016 8306270016	50-329 G 50-155 G 50-155 G 50-454 G 50-454 G
	8306210134* 8306210142*	50-315 50-315	9 9		8306270020# 8306270020#	50-454 G 50-454 G
	8304210147 8304210259 8304210247* 8304210273*	50-315 50-315 50-315	Р 5 8		8306270041 8306270173 8306270383 8306270393 8306280528	50-454 0 50-155 0 50-454 0 50-454 0 50-454 0
	8306210279* 8306210284* 8306210325 8306230333	50-315 50-315 50-316 50-315	8 8 8	Jacobs Enginearing Group, Inc Japan, Govt of Jarsey Central Power & Light Co	8306280535 8306200013# 8306150468 8306030269	50-454 G WASTE MGT XPORTLIC 50-219 S
	8304270158 8304270161 8304270312	50-316 50-316 50-315	S S P	John A Blume & Associates, Engineers (subs URS Corp)	8306130238*	REVIEW GRP
	8306270433 8306270436# 8306270444*	50-315 50-315 50-315	8 S	Joint Applicants-Palo Verde Joint Applicants-Bouth Texas Project Joint Intervenors-Diablo Cangon	8306100078* 8306150304 8306150398 8306200308 8306010336	50-529 0 50-529 0 50-529 0 50-498 0
Indiana, State of	8306270449* 8306300035 8306200097 8306280382	50-315 50-315 50-546 50-546	\$ 8 A D	Count intervenors-Discis Canyon	8306040182 8306060182 8306070406	50-275 H 50-275 Q 50-275 Q 50-275 Q
Industrial Nuclear Co Information Hendling Services Institute of Nuclear Power Operations Interior, Dept of	8305170461 8305280122* 8305070233 8305020327*	71-9156 CONTRACT 50-295 CONTRACT	T R		8306070406 8306150314 8306150435	50-275 Q 50-275 Q
Interior, Dept. of, Fish & Wildlife	8306020336* 8306140161	CONTRACT		total following of the con-	8306220038 8306280565 8306290535	50-275 G 50-275 P 50-275 G
Service International Atomic Energy Agency	8306140365 8306160156*	50-412 FOIA	c	Joint Intervenors-Waterford	8306150368 8306280541*	50-382 G 50-382 G
(Austria)				Justice, Dept of, Attorney General, Office of	B306090501	ADVCM

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEQUE		AUTHOR AFFILIATION	ACCESSION NUMBER	CATE
KLM Engineering, Inc Kaman Tempo Kansas Gas & Electric Co	8306140681 8306060008 8306220255* 8306060191 8306060194*	ADVCM FOLA CONTRACT 50~482 50~482	г к к		8306190442* 8306170371 8306200320 8306200320 8306200327*	50-454 50-454 50-454 50-454 50-454
	8304040195* 8304070194 8304070262 8304080175 8304080178*	50-482 50-482 50-482 50-482 50-482	F 5 5 A A		8306200327* 9306200331* 9306200331* 9306270022 8306300215	50-454 50-454 50-454 50-454
	8306080188* 8306070231 8306130043 8306130138 8306130373	50-482 50-482 50-482 50-482 50-482	9 8 8 8	Ledoux & Co . Inc Leads, Hill & Jewett, Inc Leasburg, FL Lewis, M	8305140394 8306230198* 8306030328* 8306020380 8306220043	XPORTL CONTRA 50-00: 50-05: 50-05:
	8306140230 8306140234* 8306150487* 8306160415 8306160539	50-482 50-482 50-482 50-482 50-482	A F S	Liberty Lines Transit, Inc Limerick Ecology Action	00000008 00000008 00000008 000000008 000000	PR 50-247 50-353 50-353 50-353
	6306160565 8306160593 8306170386 8306200312 8306200318	50-482 50-482 50-482 50-482 50-482	30 60 60 60 60 60 60 60 60 60 60 60 60 60	Literature Research Corp Lodge, T J Long Island Lighting Co	8306030271# 8306030288 8306010011 8306010432 8306020455	CONTRA 50-440 50-323 50-323 50-323
	8304220082 8304230358 8304270088 8304270352 8304280335	50-482 50-482 50-482 50-482 50-482	G G G S S		8306060231 8306060332* 8306070013 8306070038 8306070321	PR 50-321 50-321 50-321
Kansas State Univ Kansas, Univ of Karr & Lyons	B306300100 B306160227 B306080316* B306270478 B306270478	REGOD 50-189 50-148 50-327 50-327	H P G		8304080171 8304080177* 8304080182* 8304090295 8304130234	50-021 50-021 50-021 50-021
Kentucky, Univ of Kerr-McGee Chemical Corp (subs of Kerr-McGee Corp)	8306270530 8306270530 8306030402* 8306080377	50-329 50-329 CONTRACT 40-2041	G		8306130326 8306130404 8306130411 8306130446 8306140338*	50-321 50-321 50-321 50-321
,	8306130344 8306300155	40-8027			8306140498* 8306140607	50-322
Kerr-McGee Corp Keyboard Communications, Inc	8306220140 8306240343 8306300103 8306080417*	PR 40-8768 40-8027 PR CONTRACT	r		8306140615* 8306140739 8306130214*	20-355 20-355 20-355
Kilcoyne, J J Kirkpatrick, Lockhart, Hill. Christophor	9306200438 8306060184	50-287 50-322	Q G		8306150370 8306150373* 8306150381*	50-322 50-322 50-322
& Phillips	830A0A0292 830A0A0291	50-322 50-322	9		8304140087# 8304140089#	50~322 50~322
	8306080167 8306090216 8306130423 8306150395	50-322 50-322 50-322	9 9 9		8306160071* 8306160100* 8306160104* 8306160108* 8306160287	50-322 50-322 50-322 50-322
	8306150397 8306150401* 8306200337 8306220134 8306230337	50-322 50-322 50-322 50-312	0 0		8306220017 8306220094 8306240230 8306240250 8306280042*	50-322 50-322 50-322 50-322
	8306280601 8306290480	50-322 50-322	o e		8306280046* 8306280265	50-025 50-025
W-1	8306290485* 8306290533 8306300081 8306300094	50-322 50-322 50-322 50-322	0 0 0		8306280445 8306280547 8306290393	50-322 50-322 50-322
Kissimmes.FL Korea, Republic of (Eduth Korea) Laboratory of Clinical Medicine, Sioux	8306030327* 8306210433	50-302 XFORTLIC	I :	Los Alamos Scientific Laboratory	8306290526 8306300147 8306020193	50-325 50-325 NUREO
Falls, 6D Laular, Matusky & Skelly Engineers Laurance Livermore Laboratory	8306030449 8306080274* 8304070100*	FOIA 50-410 50-277	A P		8306070422 8306130377# 8306280013	REB 50-149
	8304100135* 8304150044 8304150417 8304270413*	50-237 50-272 NUREO 50-245	p p	Luvisiana Consumer's League, Inc Lovisiana Power & Light Co	8306220117 8306220117 8306010084 8306010223 8306010297	NUREO 50-456 50-362 50-362 50-362
teBoeuf, Lamb, Leiby & MacRae	8306010168 830616083	50-341 FOIA	ĸ		8306060117 8306060120* 8306070133	50-382 50-382 50-382
League of Women Voters League of Homen Voters of Rockford, IL	8306240158* 8306280527 8306300128 8306100201	FOIA 50-289 NUREQ 50-454	0		8306070169 8306070274 8306070307	20-381 20-381
gar an are a common or Honor will be	8306150436* 8306150436*	50-454 50-454	ō e		8306070317 8306070419 8306090411#	50~36; 50~36; 50~36; 50~36;
	6306150442*	50-454	0		8306090416#	50-38s

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC CATEGO	RY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGOR	
	8306130206 8306130280 8306160002 8306170268= 8306170349*	50-382 50-382 50-382 50-382 50-382	A E G		8306140597* 8306140592* 8306140592* 8306140597* 8306140597*	50-329 50-329 50-329 50-329 50-329	A A A A
	8306210124 8306270052 8306270127 8306270206 8306270213	50-382 50-382 50-382 50-382 50-382	A S A S	Marsh & McLennah, Inc	8306140605* 8306140605* 8306010398 8306020128 8306020318	50-327 50-327 50-250 50-244 50-247	C C V V
	8304270310 8304270330 8304280342 8304300077 8304300144	50-382 50-382 50-382 50-382 50-382	8 R 8		8304030338 8304030337* 8304230125 8304230283 8304150443	TOPREP TOPREP 50-250 50-29 XPORTLIC	J J
Louisiana, State of Louisianians for Safe Energy, Inc	8304300188 8304070090 8304130334 8304130488* 8304220117	50-382 50-382 State Pi CONTRACT 50-458		Maryland, State of	8306150465* 8306160684 8306160685* 8306070280* 8306220168*	XPORTLIC XPORTLIC XPORTLIC CONTRACT CONTRACT	:
Lowenstein, Newman, Reis, Axelrad & Toil	8306030167 8306100200 8306160201 8306200308 8306020482*	50-331 50-498 PR 50-498 CONTRACT	у 6 Т	Massachusetts Institute of Technology Massachusetts, Commonwealth of, Materials Engineering Associates, Inc	8306030363* 8306070411 8306060366 8306150081	50-443 50-443 NUREO NUREO	G G
Maine Yankee Atomic Power Co	8306010408 8306020146 8306020152 8306020352 8306020425	50-309 50-309 50-309 50-309 50-309	5 F R R	Maxima Corp Mayer, Brown & Platt McGraw-Hill Publications Co	8306240062 8306090284* 8306270239* 8306280193	NUREO CONTRACT 40-8410 FOIA	
	8304020524 8304030341 8304040305 8304040310 8304040332	50-309 50-309 50-309 50-309 50-309	P 6 9 0	Mentor, KY Metal Hellows Corp Metropolitan Edison Co	8306160273# 8306270410 8306230277 8306010434 8306090211 8306150410	CONTRACT 50-358 50-482 50-289 50-289 50-289	0 8 6 6
	8306070290 8306070296 8306100276 8306140273* 8306150263	50-309 50-309 50-309 50-309 50-309	41000		8306220071 8306290399 8306300050 8306300087 8306060075	50-289 50-289 50-289 50-289 50-358	
	8306140444 8306170166 8306170177* 8306170186 8306170430	50-309 50-309 50-309 50-309 50-309	R F 8 8	Michigan, Univ of Middle South Bervices, Inc	8304030254* 8304090470* 8304210453 8304240242 8304040225*	CONTRACT CONTRACT ACRB TOPREP	
	8306210175 8306230361 8306230366* 8306270295 8306280009	50-309 50-309 50-309 50-309 50-309	0 F 8 P	South Energy, Inc Minnesota Project Minock, J Hississippi Power & Light Co	8304030379 8304270218 8304010074 8304010244	FOIA 50-341 50-416 50-416	0 P 8
Maine, State of	8306290486 8306090218 8306100191 8306100193* 8306100204	50-309 50-309 50-309 50-309 50-309	0000		8306010261 8306020286 8306060038* 8306060079 8306060079	50-416 50-416 50-416 50-416	9 P A F F
Manhattan College Mapleton Intervenors Mark G Jones Engineering Consultants. Inc.	B306100205# B306280387 B306080206 B306140532#	50-309 50-199 50-329 50-329	O A A		8306060236 8306070004 8306070087 8306070142 8306070228	50-416 50-416 50-416	P 8 8 8
	8306140539# 8306140540# 8306140540# 8306140544# 8306140544#	50-327 50-327 50-327 50-327 50-327	A A A A		8306070230 8306070237 8306070410 8306070134 8306100217	50-416 50-416 50-416 50-416 50-416	8 8 8 8
	8306140546* 8306140546* 8306140548* 8306140548* 8306140552*	50-329 50-329 50-329 50-329 50-329	4444		8306100235 8306100235 8306100251 8306140046 8306140084	50-416 50-416 50-416 50-416	
	8306140552* 8306140555* 8306140555* 8306140557* 8306140557*	50-329 50-329 50-329 50-329 50-329	A A A A		8306140257 8306140257 8306140384 8306140454* 8306140567*	50-416 50-416 50-416 50-416	9 9 9 9
	8306140560* 8306140560* 8306140566* 8306140566* 8306140573*	50-329 50-329	A A A A		9306140669 9306140724 9306140729* 9306160271	50-414 50-416 50-416 50-416	5 S P P P
•	8306140573* 8306140577* 8306140579* 8306140587*	50-329 50-329	*		3304500133 3304500133	50-416 50-416	8

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGOR		AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEODR
	8306200142 8306200186 8306200186 8306200189* 8306200204	50-416 50-416 50-416 50-416 50-416	5 K K K		8306160474 8306200106 8306270163 8306280386 8306280444	50~298 50~298 50~298 50~298 50~298
	8306200250 8306200412 8306210140 8306210140 8306230167	50-416 50-416 50-416 50-416 50-416	8 R F F	Nebraska, State of Neutron Products, Inc New England Coalition on Nuclear Pollution	8306020463* 8306230494* 8306240341 8306010382	CONTRACT CONTRACT 71~5364 50~443
	8306230167 8306270077 8306270080* 8306270116 8306270126	50-416 50-416 50-416 50-416 50-416	P P G S		8306030355 8306030357* 8306030357* 8306030363* 8306270556	50~443 50~443 50~443 50~443 50~443
	8305270132 8305270165 8305270285 8305270346 8305270439	50-416 50-416 50-416 50-416 50-416	8 8 P 6 9	New Hampshire. State of	8306010342 8306010342 8306010384 8306010384 8306270372	50-443 50-443 50-443 50-443 State Pr
	8306270439 8306280188 8306280287 8306280329 8306280471	50-416 50-416 50-416 50-416 50-416	\$ \$ \$ \$ \$ \$	New Jersey, State of New York City Audubon Society New York, State Univ. of, Buffalo New York, State of	8304020047* 8304200324 8304170052* 8304010094 8304030174*	50-320 50-247 50-57 50-201 50-322
	8306280505 8306280555 8306270211 8306270211 8306300163	50-416 50-416 50-416 50-416 50-416	P S Q Q S	New York, State of, Energy Office	8304040231 8306040233 8306300158 8306300174 8310220123	PR PR PR PR 50-410
Missouri, State of Missouri, Univ of, Columbia Mitsubishi International Corp (subs of Mitsubishi Corp) Mitsubishi Corp) Mitsui & Co (USA), Inc (subs of Mitsui	8306300175 8306160322# 8306150165 8306240019	50-414 50-483 50-184 XPORTLIC		Newbury, MA Niagara Mohawk Power Corp	8304290393 8304280312 8304010043 8304010258 8304010340	50-322 50-443 50-120 50-220 50-220
& Co , Ltd)	8306160624 8306160724* 8306140260 8306150458	XPORTLIC XPORTLIC XPORTLIC XPORTLIC			8304010412* 8304010453 8304020094 8304020158 8304020189	50-220 50-410 50-220 50-220 50-220
Molycorp, Inc Monick Reporting Co Montento Co	8306150459 8306020230 8306070026* 8306070027* 8306010095	XPORTLIC 40-8794 FOIA FOIA 40-6500			8304030352 8304040199 8304070034 8304080273 8304100143	50-220 50-220 50-220 50-410 50-220
Monsanto Research Corp Montgomery County, MD Morgan Associates	8304030174 8304030506 8304220054 8304070414	XPORTLIC 40-4500 40-4500 50-170 50-247	0		8306130303 8306140440 8306140445* 8306140558*	50-410 50-410 50-410 50-410 50-410
Motor Dils Refining Co	8306200342 8306200342 8306230376 8306270160 8306060302	50-247 50-247 50-247 50-247 50-454	G T G G		8306200214 8306200258 8306200262 8306210182 8306210195	50-220 50-410 50-410 50-410 50-410
NUB Corp	8306160030 8306240347 8306280258 8306280261* 8306210344*	50-144 FOIA XPORTLIC XPORTLIC CONTRACT 50-346			8304210200 8304220074 8304220104* 8304220107* 8304270122	50-410 50-410 50-410 50-410 50-410
NUTECH Engineers, Inc National Lawyers Guild, Houston Chapter	8306140547* 8306160366* 8306160366* 8306170354* 8306230351* 8306160594	50-324 50-341 50-243 50-331 50-287	г А Р Р		8306270274 8306280255 8306280422 8306280424* 8306280507	50-410 50-410 50-220 50-220 50-220
Natural Resources Defense Council	8306180374 830620146 8306220153* 8306220157* 8306270370	50-522 50-537 50-537 50-537 50-289	9 9 9		8304280313* 8304280550 8304280597 8304280405 8304300241	50-220 50-410 50-410 50-410 50-220
Navy. Dept of Nebraska Public Power District	8304080324 8304220158* 8304020148 8304040241	71-9017 CONTRACT 50-298 50-298		North Carolina Municipal Power Agencies North Cerolina State Univ North Shore Committee Against Nuclear & Thermal Pollution Northeast Nuclear Energy Co. (subs of	8304200356* 8304210410 8304150378 8304010340	50-367 ACR8 50-322 50-213
	8304080041 8304080219# 8304100139 8304130339 8304140714 8304140444	50-278 50-278 50-278 50-278 50-278 50-278	G G B G G	Northeest Utilities)	8306010434 8306020077 8306020084 8306020397 8306030317	50-245 50-336 50-245 50-245 50-245
	8306160464 8306160477 8306160488	50-278 50-278 50-278 50-278	P R R		8309090040 8309090359	50-245 50-213 50-213

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT Category	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8306060070 8306060078 8306060143 8306060154 8306060207	50-213 H 50-336 P 50-423 A 50-336 F 50-213 P		8306280430 8306280478 8306280482 8306280534 8306300140	50-336 S 50-245 P 50-423 S 50-245 P 50-245 P
	B306060263 B306070136 B3060B0058 B306070232 B306140361#	50-245 R 50-245 F 50-245 P 50-245 P 50-336 P	Northeast Utilities Service Co Northern States Power Co	8306300140 8306160412 8305060453 8306010349 8306010441	50-245 P 50-213 P 50-263 Q 50-282 P 50-263 P
Northeast Utilities	8306160388 8306170042 8306170046 8306170300 8306170391	50-245 R 50-336 S 50-245 S 50-245 S 50-213 G		8304020088 8304020147 8304040084 8304040230 8304090230	50-263 R 50-263 R 50-263 G 50-282 P
	8306170391 8306170391 8306200104 8306200313* 8306200322*	50-213		8304090237 8304090237 8304090239* 8306090239* 8306090257*	50-282 F 50-282 F 50-282 F 50-282 F
	8306230289 8306240200 8306270129 8306270228 8306270255	50-245 P 50-213 P 50-245 S 50-213 S 50-336 P		8306090261* 8306090263 8306100059 8306100059 8306130438	50-282 F 50-282 F 50-282 F 50-282 F 50-263 5
	8306280231 8306280321 8306280346 8306280353 8306280412	50-336 S 50-248 P 50-423 S 50-336 S 50-245 P		8306140002 8306140002 8306160430 8306170134 8306170232	50-282 R 50-282 R 50-263 F 50-263 Q 50-262 Q
	8306280414 8306280430 8306280478 8306280482 8306280934	50-336		8304200105 8304200105 8304200108 8304200370 8304200370	50-243 P 50-243 R 50-243 F 50-282 P 50-282 P
	8304300140 8304300140 8304110736 8304010340 8304010434	50-245 P 50-245 P 50-245 I 50-213 P 50-245 S		8306210094 8306230079* 8306230087* 8306280340 8306280340	50-263 F 50-282 F 50-282 F 50-282 Q 50-282 Q
	8306020077 8306020084 8306020397 8306020449 8306030319	50-336 R 50-245 R 50-245 S PR 50-245 S	Norton, Burke, Berry & French	8306280345* 8306280345* 8306280459 8306060275 8306160579	50-282 0 50-282 0 50-263 F 50-275 0 50-275 0
	8304030324 8304040090 8304040090 8304040090 8304040098	50-245 \$ 50-213 H 50-213 H 50-213 H 50-334 P		8306160579 8306160584* 8306160584* 8306160595* 8306160595*	50-275 G 50-275 G 50-275 G 50-275 G 50-275 G
	8306060143 8306060154 8306060207 8306060263 8306070136	50-423 A 50-336 F 50-213 P 50-245 R 50-245 F	Nuclear Assurance Corp	8306280520 8306020199 8306100018 8306230166# 8306230220#	50-275 G 50-266 F 50-266 P F0IA CONTRACT
	8306080058 8306070232 8306130233 8306140361* 8306160388	50-245 P 50-245 P REVIEW GP 50-334 P 50-245 R	Nuclear Club, Inc., The Nuclear Consulting Services, Inc Nuclear Energy Liability Insurance Association	8305240457 8305060034 8305150143# 8305080077 8305030338	71-9010 FOIA FOIA MISC TOPREP
	8306160412 8306160412 8306160412 8306160424* 8306160424*	50-213 P 50-213 P 50-213 P 50-213 P 50-213 P	Nuclear Energy Service, Inc	8306030337* 8306300113 8306300116 8304270072* 8306020178*	TOPREP 50-280 J TOPREP 50-409 P 50-271 P
	8306160424* 8306170042 8306170046 8306170300	50-213 P 50-336 S 50-245 S 50-245 S	Nuclear Fuel Bervices, Inc (subs of Gesty Gil Co)	8306020184* 8306030283	50-271 P 70-143
	8306170391 8306170391 8306170391	50-213 Q 50-213 Q 50-213 Q		8304080381 8304150249* 8304140458	70-143 70-143 70-143
	8306200104 8306200313* 8306200322* 8306240200	50-336 8 50-245 Q 50-245 Q 50-213 P	Nuclear Law Center Nuclear Packaging, Inc	8306290572 8306290588 8306290546 8306030135 8306070453	70-143 71-6357 50-142 G 71-9159 71-9182
	8304270127 8304270255 8304270256* 8304280231	50-245 8 50-336 P 50-336 P 50-336 S 50-245 P	Nuclear Pharmacy, Inc Nuclear Plant Safety O'Brien-Kreitzberg & Associates, Inc	8306070455* 8306160098 8306160174 8306030373 8306060043*	71-9102 FOIA FOIA FOIA 50-546 A
	8304280344 8304280353 8304280412 8304280414	50-423 S 50-336 S 50-245 P 50-336 Q	O'Net11, J.	8306070372 8306070375* 8306070424	50-155 0 50-155 0 50-155 0

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJE	DRY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEODS
Oak Ridge National Laboratory	8306010086 8306020122 8306080041* 8306160631* 8306210324	NUREG NUREG FOIA 50-155 NUREG			8306210171* 8306230365 8306230422 8306240318* 8306240398	50-275 50-275 50-275 50-275 70-2375
Ocala, FL	8306210350 8306280089 8306280093 8306280093	NUREQ 50-259 NUREQ NUREQ 50-302	р 1		8306280332 8306280388 8306280394# 8306280396# 8306280421	50-275 50-275 50-275 50-275 50-275
Office of Management & Budget Offshore Power Systems (subs of Westinghouse Electric Corp) Ogle Petroleum, Inc Ohio Citizens for Responsible Energy	8306070475 8306230169* 8306130367	ORG 50-414 40-8745			8305280451 8305280520 8305280520 8305280522 8305280523	30-275 30-275 30-275 30-275 50-275
and distinct the responsible energy	8304040381 8304270014 8304270017# 8304270017* 8304270534 8304270534	50-440 50-440 50-440 50-440 50-440 50-440	40 00000		8306280525 8306300041 8306300089# 8306300093# 8306300211	50-275 50-275 50-275 50-275 50-275
Oklahoma, Univ of	8306290549# 8306270549# 8306010081 8306280569	50-440 50-440 NUREG 50-112	9 9 9	Pacific Legal Foundation	8305300217* 8305170374 8305220089 8305270280 8305270280	50-275 50-322 50-322 50-322 50-322
Omaha Public Power District	8304280581* 8304280594* 8304040153 8304040299 8304080236*	50-112 50-112 50-285 50-285 50-285	Р 6 0	Pacific Power & Light Co Palmetto Alliance Parameter, Inc	8306200213* 8306060297 8306100196 8306150385 8306240050	50-344 50-413 50-413 50-413 NUREQ
	8304070032* 8304100102 8304100104* 8304130130* 8304130240	50-285 50-285 50-285 50-285 50-285	Febab	Parents Concerned About Indian Point	8306060180 8306090300 8306090300 8306090347 8306090347	50-247 50-247 50-247 50-247 50-247
	8304140354# 8304200358 8304210340# 8304270105 8304280233	50-285 50-285 50-285 50-285 50-285 50-285	0 F F F P	Pathfinder Mines Corp	8306070350 8306070350 8306140168 8306160234 8306160656	50-247 50-247 40-6622 40-2259 40-2259
Grange County Alliance for Survival Oregon State Univ	8306280464 8306280487 8306300069 8306160046 8306070044	50-285 50-285 50-285 50-206 50-243	P P G	Paul, Weiss, Rifkind, Wharton & Garrison Peabody International Corp Pennsylvania Power & Light Co	8306210293 8305240443* 8306010061 8306010068 8306010070	FOIA 50-293 50-387 50-387 50-387
Oregon, State of Orrick, Herrington & Sutcliffe Overseas Packing, Inc PBI Industries Pacific Air Products Co	8306230507# 8306220084 8306210342 8306230348 8306240273#	CONTRAC 50-361 FOIA MISC GA999	T G		8306010099 8306010150 8306010177* 8306010218 8306010276	50-387 50-387 50-387 50-387 50-367
Pacific Gas & Electric Co	8304010347 8304020214 8304020309 8304030162 8304030142	50-275 50-275 50-133 50-275 50-275	R R R P		8306010309 8306010313 8306010323 8306010330 8306010330	50-367 50-367 50-367 50-367 50-367
	8304040135 8304060275 8304060275 8304070036 8304070270	50-275 50-275 50-275 50-133 50-275	F G G H P		9306020223 9306020369 9306020392 9306020394 9306020401	50-387 50-387 50-387 50-387 50-387
	8306070275# 8306070278# 8306070292 8306070297# 8306100067	50-275 50-275 50-275 50-275 50-275	P P R R		8305020429 8305020429 8305020444* 8305070214 8305090021*	50-387 50-387 50-387 50-387 50-387
	8304100082 8304140031 8304140031 83041400441 8304140524	50-275 50-275 50-275 50-275 50-133 50-275	8 P P R		8306090021* 8306090026* 8306090246 8306140482 8306140482	50-367 50-387 50-387 50-387 50-387
	8306160529# 8306160535 8306160579 8306160579 8306160584#	50-275 50-275 50-275 50-275	RROO		8306140648 8306140648 8306160472 8306170015 8306170037	50-367 50-387 50-387 50-387 50-387
	8306160384* 8306160395* 8306160395* 8306210044 8306210078	50-275 50-275 50-275 50-275 50-275 50-275	0 00000		8306170188 8306170191* 8306170217 8306170250 8306170413	50-367 50-367 50-367 50-368 50-367
	8304210080 8304210111 8304210142 8304210144	50-275 50-275 50-275 50-275	G P R B		8306210050 8306210079 8306210143 8306210212 8306230297	50-367 50-368 50-387 50-387 50-387

AUTMOR AFFILIATION	ACCESSION NUMBER	SUBJE CATEG		AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC	
	8304230430 8304230430 8304230444 8304230446 8304230446	50-387 50-387 50-387 50-387	7 & 7 E 7 &		6306100241 6306140262* 6306140262* 6306140391* 6306140395	50-352 50-277 50-277 50-277 50-277	A Q G F
	8306270253 * 8306280006 8306280140 8306280348 8306280368	50-387 50-387 50-387 50-387	7 8 7 8 7 8		8306140375 8306140378* 8306140545 8306140545 8306140606	50-352 50-277 50-352 50-352 50-352	F E E
	8306280377 8306280434 8306280510 8306280518 8306280548	50-397 50~387 50-387 50-387 50-397	' s ' s ' s		8306140606 8306140624 8306140624 8306150393 8306150393	50-352 50-352 50-352 50-352 50-352	E 6 0
Pannsylvania State Univ Pannsylvania, Commonwealth of,	8306300092 8306300183 8306070452 8306240157 8306010372	50-387 50-387 NUREQ 50-5 50-352	, b		8306180397 8306160001 8306160001 8306160310 8306160310	50-322 50-352 50-352 50-352 50-352	Q E A
	8306010372 8306010380* 8306010380* 8306070271 8306070277*	50-352 50-352 50-352 50-289 50-289	2 G 2 G 7 G		8304160340 8306140340 8306140371 8306140371 8306160377	50-352 50-352 50-352 50-352 50-352	A E E A
Pharmatopes, Inc Philadelphia Electric Co	8306070407* 8306220046 8306160139* 8306010233 8306010233	50-289 50-289 FOIA 50-352 50-352	'		8306160377 8306160379 8306160379 8306160486* 8306160327	50-352 50-277 50-277 50-277 50-352	A R R Q
	8305010237* 8305010240* 8305010240* 8305010243* 8305010243*	50-352 50-352 50-352 50-352 50-352	K K C		9306160527 9306160572 9306160572 9306160603 9306160603	50-352 50-352 50-352 50-352 50-352	E 6 0
	8304010292 8304010438 8304010445* 8304020277 8304020299	50-352 50-278 50-278 50-277 50-277	9 S 9 S 8 S		8306160609* 8306160609* 8306170017 8306170163 8306170210	50-352 50-352 50-277 50-277 50-352	0 9 5 R A
	8306020378 8306020396 8306060157 8306060158*	50-277 50-277 50-277 50-277 50-277	는 다 다		8306170210 8306170278 8306170309 8306170309 8306170369	50-352 50-277 50-352 50-352 50-352	A A A E
	8305060158* 8305060322 8306070237 8305070237 8305070275	50-277 50-352 50-352 50-352 50-352	A A		8306170369 8306200117 8306200117 8306200144 8306200165*	50-352 50-352 50-352 50-277 50-277	E A A B G
	8306070295 8306070299* 8306070299* 8306070301*	50-352 50-352 50-352 50-352 50-352			8304200183 8304200183 8304200317 8304200317 8304210074	50-352 50-352 50-352 50-352 50-277	F E E
	8306070330 8306070330 8306070363 8306070363 8306070374*	50-352 50-352 50-277 50-277 50-277	E E P		8306210076 8306210283 8306230276 8306270086 8306270086	50-277 50-352 50-352 50-352 50-352	R C A E E
	9306070376* 9306070379* 9306070383* 9306070383* 9306070387*	50-277 50-277 50-277 50-277 50-277	P P P P		9306270212 9306270212 9306270261 9306270261 9306270264#	50-352 50-352 50-277 50-277 50-277	A A P P
	8306070391* 8306070395* 8306070395* 8306070398* 8306070403*	50-277 50-277 50-277 50-277 50-277	ዮ የ የ የ		8306270264* 8306270268* 8306270268* 8306270315 8306270315	50-277 50-277 50-277 50-352 50-352	P P E E
	8306070212 8306070212 8306070217 8306070226*	50-352 50-352 50-277 50-277 50-277	6 9 P P		8304270340 8304270340 8304270345 8304270345 8304270413	50-352 50-352 50-352 50-352 50-352	E A A
	83060 90226* 83060 90240 83060 90240 8306100065 8306100065	50-277 50-352 50-352 50-352 50-352	P O G A A		8306270413 8306270423 8306270423 8306270459 8306270459	50-352 50-352 50-352 50-352 50-352	A A A A
	8306100107 8306100107 8306100110 8306100110 8306100241	50-352 50-352 50-352 50-352 50-352	A A E E E A		8306280235 8306280235 8306280381 8306280417 8306280589	50-277 50-277 50-352 50-352 50-352	G G E S A

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGOR		AUTHOR NOITALIATON	ACCESSION NUMBER	SUBJEC CATEGO	
	8304300014 8304300014 8304300024 8304300024 8304300133	50-352 50-352 50-352 50-352 50-352	E A A		8305150427 8305160385 8305160450 8305170247 8305200137	50-247 50-286 50-286 50-286 50-333	G R G P
	8304300133 8304300200 8304300221 8304300221	50~352 50~352 50~352 50~352 50~352	A E A A		8306200342 8306200342 8306200344* 8306200346* 8306200346*	50-247 50-247 50-333 50-247 50-247	T 0 T T
Philbrick,S S Pickerd, Lowe & Oarrick, Inc Plano Archaeological Consultants Plateau Resources, Ltd	8304240112* 8304210334* 8304230030* 8304130347 8304140354	FOIA FOIA 40-8681 40-7869 40-8699			8304200375 8304200401 8304200403 8304200411* 8306210068	50-333 50-286 50-286 50-286 50-286	89 F G
Porter Consultants, Inc. Portland General Electric Co	8306140367* 8306220311 8306240384 8306010073 8306010316	40-8698 40-8674 NUREQ 50-344 50-344	9 P		8304210138 8304210144 8304210154 8304210178 8304210188*	50-286 50-286 50-333 50-286 50-286	4404
	8306020119 8306030293 6306070071 8306070207 8306070209	50-344 50-344 50-344 50-344 50-344	R J 8 P P		8306230170 8306230174* 8306230376 8306270160 8306280486	50-333 50-333 50-247 50-247 50-333	P P G G S
	8306070211* 8306070212 8306070213* 8306130415 8306160392	50~344 50~344 50~344 50~344 50~344	면 명 F 유	Power Engineering Society Professional Reactor Operator Society Project Management Corp	8306280508 8306300142 8306160468 8306080070 8306270317	50-333 PR RECOD FOIA 50-337	P
	8306170173 8306170303 8306170317 8306170400 8306200152	50-344 50-344 50-344 50-344 50-344	8 8 9 8	Public Interest Research Group, New York	8306070421 8306070300 8306070300 8306070308 8306070308	50-247 50-247 50-247 50-247 50-247	00000
	B306200191 B306200207 B306200210* B306230323 B306230414	50-344 50-344 50-344 PR REGGD	I I	Public Bervice Co. of Colorado	8306090350 8306090350 8306150389 8306230346 8306010335	50-247 50-247 50-247 50-247 50-267	T 0 0 P
	8306230445 8306240256 8306240316 8306270394 8306280613	PR 50~344 50~344 50~344 50~344	F G H P		8304010343 8304010344* 8304010345* 8304010411 8304010414*	50-267 50-267 50-267 50-267 50-267	P P P
Potter & Carmine Pawer Authority of the State of New York	8306280617* 8306290242 8306060010 8306010112 8306010312	50~344 PR 50~354 50~333 50~333	P 9 8		8306010419* 8306060130 8306060134 8306070103 8306070106*	50-267 50-267 50-267 50-267 50-267	9 8 9 9
	8306010346 8306020450 8306030224 8306030345* 8306060121	50-284 50-284 50-284 50-284 50-333	5 9 9 9		8304070199 8304140733 8304140284 8304140434 8304140541	50-267 50-267 50-267 50-267 50-267	6 6 6
	8306070185 8306070197* 8306070303 8306070414 8306080034	50-266 50-266 50-333 50-247 50-264	Р Р С Р		8306210011 8306210253 8306210373* 8306280217 8306280228*	50-267 50-267 50-267 50-267 50-267	9 8 8
	8306070277 8306070277 8306070302 8306070304* 8306070307*	50-247 50-247 50-286 50-286 50-286	F P P		9306280236 # 9306280260 # 9306280260 # 9306280262 # 9306280266 #	50-267 50-267 50-267 50-267 50-267	99866
	8306090317 8306090317 8306090325 8306090325 8306090340	50-247 50-247 50-247 50-247 50-247	F F F F		8306280272* 8306280278* 8306280283* 8306280288* 8306280293*	50-267 50-267 50-267 50-267 50-267	8888
	8306090340 8306090359 8306100017 8306100100 8306100113	50-247 50-247 50-333 50-333 50-286	F R P P		6305280278* 6305280302* 6305280307* 6305280313* 6305280343	50-267 50-267 50-267 50-267 50-267	8 8 8 8
	8304100253 8304100256* 8304130111 8304130111	50-286 50-286 50-286 50-286 50-284	P I I I		8306280354 8306300059 8306300098 8306300104 8306300107*	50-247 50-247 50-247 50-247 50-247	P F 8 9
	8306140153* 8306140169* 8306140277 8306140318 8306140598	50-333 50-333 50-286 50-333 50-286	6 6 6	Public Service Co. of Indiana, Inc.	8304300111* 8304300187 8304040039 8304040039 8304070144*	50-267 50-267 50-346 50-346 50-347	

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJE CATEG	PDRY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC	RY
	8306070147 8306070377 8306140596 8306140596 8306170182		Q S A A		8304270304* 8304270343 8304280254 8304280488 8304280542	50-272 50-272 50-272 50-272 50-272	P S S R
	8306270138 8306270138 83062701494 83062701494 83062701524	50-546	, K		8306280542 8306280590* 8306290313 8306290409 8306290431*	50-272 50-354 50-272 50-354 50-354	R G P K K
Public Service Co of New Hampshire	8306270152+ 8306270219 8306270219 8306270375 8306010448	50-546 50-546 50-546 50-546 50-443	A A S		8306290432* 8306290435* 8306290444* 8306290448* 8306290449*	50-354 50-354 50-354 50-354 50-354	A C K K
	8306010449* 8306030177 8306030177 8306080125 8306080125	50-443 50-443 50-443 50-443	E		9306290451# 9306290454# 9306290456# 9306290458#	50-354 50-354 50-354 50-354 50-354	к к к к
	8306150387 8306150387 8306150388 8306150388 8306170167	50-443 50-443 50-443 50-443	0 0		8306290460* 8306290465* 8306290468* 8306290469* 8306290471*	50-354 50-354 50-354 50-354 50-354	Х К К К
	8306200236 8306200330 8306200397 8306200397	50-443 50-443 50-443 50-443 50-443	E		9306290473* 8306290474* 8306290477* 8306290478* 8306290479*	50-354 50-354 50-354 50-354 50-354	K K K K
Public Service Electric & Gas Co of New Jersey	8304230452 8304280543 8304280545 8304010328	50-443 50-443 50-443 50-311	A G B S		8306270482* 8306270484* 8306270487* 8306270489* 8306270491*	50-354 50-354 50-354 50-354 50-354	К К К К
	8306020232 8306020240* 8306020240* 8306020406 8306030141	50-272 50-272 50-272 50-311 50-272 50-272	F F F F F F		8306290494* 8306290497* 8306300190 8306300194* 8306080168	50-354 50-354 50-272 50-272 NUREG	K K P P
	8306030188 8306030301 8306030344 8306030349 8306070130	50-311 50-311 50-311 50-272 50-272	9 9	R E Williams & Associates, Inc	8304230282 8304020243 8304020269* 8304200111 8304040004*	50-182 40-2259 40-299 40-8584 FOTA	
	8306070164 8306070177 8306070177 8306090049 8306090049	50-272 50-272 50-272 50-272 50-272	F G G F		8304040005* 8304040012* 8304040025* 8304040033* 8304080254	FOIA FOIA FOIA FOIA FOIA	
	8306140036 8306140036 8306140043 8306140059	50-272 50-272 50-272 50-272 50-272	V	Radiation Safety Services, Inc Reed, J Ø	8306270251* 8306010067 8306030331 8306230344 8306070473	50-387 40-2061 50-483 50-483 NUREG	R 0 0
	8306140059 8306140063# 8306140063# 8306140261# 8306150267	50-272 50-272 50-272 50-272 50-272	P P Q R	Republic Steel Corp Reuter-Stokes, Inc Rhode Island, State of	8306210371* 8306030451 8306150462 8306080329 8306070352*	CONTRACT FOIA XPORTLIC 50-193 50-413	c
	8306150270# 8306150270# 8306160438 8306160438 8306160448#	50-272 50-272 50-272 50-272 50-272	R R P P		8306140210 8306210332* 8306240370 9306240443 8306240446*	PROJ POJA PROJ PROJ PROJ	
	8306170021 8306170144 8306170153 8306170207 8306170338	50-311 50-272 50-311 50-311 50-272	8 8 8 8	Ric Algom, Ltd	8306240450* 8306200171 8306200175* 8306200285* 8306090340	PROJ 40-8084 40-8084 40-8084 50-247	
	8306170362 8306170381 8306200132 8306200226 8306200240	50-311 50-272 50-311 50-272 50-272	8 R R R	Robert L. Cloud Associates, Inc Robert Packer Hosp Sayre.PA	8306080301 8306170308 8306150166* 8306150169* 8306020079	FO1A 50-275 70-2669 70-2669 50-244	
	8304200240 8304210174 8304210174 8304210189 8304270188	50-272 50-272 50-272 50-272 50-311	8 0 K		8306020274 8306020449 8306020451 8306020453 8306060036	50-244 PR 50-244 50-244 50-244	R R R
	8306270269 8306270299 8306270299 8306270304#	50-272 50-272	5 5 5 5 7		8306040057 B306070258 B306140025 B306140410 B306140595	50-244 50-244 50-244 50-244 50-244	P G G P

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGOR		AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGOR'
	9306150309 8306160485 8306170032 8306170201 8306200314	50-244 50-244 50-244 50-244 50-244	Q R P S P	Science Applications, Inc	8207030325* 8207200365* 8207200370* 8211220337* 8306020583*	50-346 50-254 50-273 50-245 50-298
	8306210015 8306210034 8306220022 8306240177 8306240298	50-244 50-244 50-244 50-244 50-244	0 9 9		8306090452* 8306130328* 8306160631* 8306220233* 8306220276*	CONTRACT 50-322 50-155 CONTRACT CONTRACT
Rochestar, Univ of,	8304240302* 8304240311 8304270257 8304270340 8304030454	50-244 50-244 50-244 50-244 70-2982	P P P	Science Management Corp Scripps-Howard Newspapers	8306280057# 8306280118# 8306280147# 8306090373 8306210314	CONTRACT CONTRACT CONTRACT FOIA 50-10
Rockland County, NY Rocky Mountain Energy Co	8306200078 8306070450 8306160327 8306160567 8306160576*	50-247 40-8697 40-8497 40-8380 40-8380	н	Seaccast Anti-Pollution League Senate	8306010444 8306270521 8306270532 8211160545* 8306150843*	50-443 50-443 50-443 50-204 50-272
Rondout Associates Ropes & Gray	8306200425 8306200440 8306060305 8306060332 8306070290	40-8380 ACRS 50-309 50-309 50-309	G G O	Senate, Labor & Human Resources Sensible Maine Power Shaw, Pittman, Potts & Trowbridge	8306160131* 8306140505* 8306020358 8306010390 8306010390	FDIA COMMISSIO 50-309 50-400 50-400
	8306070276 8306150387 8306150387 8306150388 8306150388	50-309 50-443 50-443 50-443 50-443	6 6 6 6		B306010395# B306010395# B306010454 B306030329 B306030336	50-400 50-400 50-287 50-287 50-400
Rothschild, G E Roy F Weston, Inc SEP Dumers Group SPS Yechnologies	8306280543 8306220117 8306240057* 8306130233 8306230028*	50-443 50-458 CDNTRACT REVIEW 6 50-373			8306070291 8306070419 8306090211 8306100091 8306130390	50-400 50-382 50-289 50-400 50-289
Sacramento Municipal Utility District	8306010379 8306030029 830607067 830607069 830607033	50-312 71-5971 50-312 50-312 50-312	P S S P		8306150410 8306160314 8306160573 8306160576 8306160611	50-289 50-483 50-482 50-440 50-440
	8304070304 8304140124 8304140591 8304170223 8304170290	50-312 50-312 50-312 50-312 50-312	9 P F 8 9		83042200312 83042200318 8304220082 8304220082	50-482 50-482 50-289 50-482 50-400
	8304170358 8304170402 8304170407* 8304210048 8304210054	50-312 50-312 50-312 50-312 50-312	B P P P R		8304220108 8304220111* 8304220111* 8304220132 8304230345	30-400 (50-400 (50-400 (50-483 (50-400 (
	8306220040 8306220075 8306220150 8306230372 8306230393	50-312 50-312 50-312 50-312 50-312	면 면 면 면 면		6306230358 8306280514 8306290214 8306290395 8306290399	50-482 (50-482 (50-440 (50-400 (50-289 (
	8304230374 8304230410 8304230447 8304270133 8304270260	50-312 50-312 50-312 50-312 50-312	S S P P P	Sheffield, Univ of Shoreham Opponents Coalition Sierra Club	8305300087 8305270281* 8305150379 8305150384 8305200335	50-287 (CONTRACT 50-322 (50-358 (50-358 (
San Diego Gas & Electric Co Sandia Laboratories	8306270325 8306300011* 8306150002 8305310226 8306010041	50-312 50-312 50-361 50-245 NUREG	J Q K P		8305200341* 8305200372* 8305220146 8305220153* 8305300142	50-358 G 50-358 G 50-337 G 50-537 G PR
	8304010052 8304010081 8304010144 8304020007 8304020014	NUREO NUREO NUREO NUREO NUREO		Simons. Li & Associates, Inc Simpson. J M Sinnissippi Alliance for the Environment (SAFE)	8306300155 8306210386* 8306290522 8306080143	PR CONTRACT 50~482 G 50~454 G
	8304020080 830421020* 8304240301* 8304270141 8304270151	NUREO GA797 50~247 NUREO NUREO	o		8306080143# 8306080145# 8306080145# 8306100201 8306150436# 8306150436#	50-454 G 50-454 G 50-454 G 50-454 G 50-454 G 50-454 G
Sandyik Special Metals Corp	8304280033 8304280049 8304280190 8304140444 8304140453	NUREG NUREG NUREG XPORTLIG XPORTLIG			8306150442* 8306150442* 8306170371 8306200327* 8306200327*	50-454 G 50-454 G 50-454 G 50-454 G
Sargent & Lundy, Inc Schwelb, Donnenfeld, Bray & Gilbert	8306160659 8306160661 8305190373* 8306140789 8306200045	XPORTLIC XPORTLIC 50-373 ADVCM ADVCM	G	Small Business Administration	8306200331* 8306200331* 8306270022 8306070284*	50-454 G 50-454 G 50-454 G CONTRACT

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC	RY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT	₹Y
Snake River Alliance Bneil & Wilmer Saurce Production & Equipment Co . Inc	8306300152 8306100078* 8306150304 8306150398 8306030057*	PR 50-529 50-529 50-529 71-9056	G G		8305220084 8305220095 8305220127 8305220127 8305230211	50-341 50-204 50-361 50-361 50-361	G P G G
South Carolina Electric & Gas Co	B306010325 B306010357* B306010366* B306010374* B306020142	50-375 50-375 50-375 50-375 50-375	0 0 0 R		8306230266 8306230369 8306230467 8306240002 8306240203	50-361 50-362 50-362 50-362 50-206	S S G P
	8304020385 8306070128 8306070202 8306070402 8306100142	50-395 50-395 50-395 50-395 50-395	P		8306240208* 8306270172 8306270172 8306270362 8306280252	50~204 50~204 50~361 50~361	9 9 9
	6305100153 6305100208 6305100213 6305100251 6305130417	50-395 50-395 50-395 50-395 50-395	9 9 9		8306280267 8306280273 8306280350 8306280410 8306280466	50-361 50-361 50-361 50-361 50-206	8 5 5 p
	6306140068 8306140386* 8306140457* 8306140670 8306160570	50-395 50-395 50-395 50-395 50-395	9 9 5 8	Southern Co Services, Inc	8306270415 8306300057 8306300144* 8306240274 8306270166	50-206 50-361 50-361 50-424 50-424	P P A S
	8306210021 8306210209 8306230086 8306270136 8306270289	50-395 50-395 50-395 50-395 50-395	\$ \$ \$ \$		B30524044B* B305240455* B305240461* B3060206B3 B306270003*	50-293 50-293 50-293 RES 50-237	P P
	8304270354 8304280067 8304280504 8304290088 8304300018	50-375 50-375 50-375 50-375 50-375	P 5 0 5	Special-T-Metals Co , Inc Spiegel & McDiarmid	8306160465 8306300219 8306070189* 8306160155 8305170121	PRM PR MISC FOIA NUREG	
South Carolina, State of	8306300049 8306300122 8306300156 8306300196 8306220299*	50-395 50-395 50-395 50-395 50-413	5 5 5 5 5 5	Stystem E S	8306030220 8306070345 8306100183 8306140240* 8306220018	50-482 50-482 50-482 50-482 50-482	8 8
Southern California Edison Co	8304300142 8304280408* 8304010142 8304010144* 8304070029	PR 50-322 50-204 50-361 50-361	0 6 0	State. Dept of	9304220018 9304020415 9304020445 9304030011	50-482 XPORTLIC XPORTLIC XPORTLIC	۸
	8306070029 8306070313 8306070313 8306080020 8306080020	50-361 50-361 50-361 50-361	0 P P P	Stepan Chemical Co 6 E Stone & Webster Engineering Corp 6	9306020238 9306020243* 9306270239* 9306060359* 9306060274*	40-8410 40-8410 40-8410 50-322 50-410	A
	8304080210* 9304090154 8304090164* 8304100054 8304100069	50-206 50-361 50-361 50-361	P P P S S C	E 6	9306080278* 9306080303* 9306080306* 9306080312* 9306080328*	50-410 50-410 50-410 50-410 50-410	A A A A
	8304100078 8304100078 8304100111 8304130384	50-361 50-361 50-206 50-361 50-206	8 9 9 8 P	E 6 6	*#BEE08040EE *#EE08040EE *12E08040EE *04E08040E8	50-410 50-410 50-410 50-410 50-329	A A A A
	8305130392* 8305140007 8305140019 8305140039	50-206 50-361 50-206 50-361	. P S P S	8 E E	3306170350 3306170350 3306270397 3306270401* 3306270345*	NUREG 50-275 50-275 50-275 50-275	R R R
	8304140237 8304140250 8304140444 8304140444	50-362 50-361 50-361 50-361	S S P P	5 6 8	3306100168 3306100171* 3306130444 3306230121 3306270262	50-275 50-275 TOPREP 50-329 50-329	R R A
	8306140684 8306150002 8306150002 8306150303	50-361 50-361 50-361 50-204	8 K F K	E E Buffolk County, NY E	3306270262 3306270271 3306270271 3306270309 3306060184 3306060188*	50-329 50-329 50-329 50-329 50-322	A VV & G C
	8304160275 8304160455 8304160487 8304200154	50-361 50-206 50-361 50-206	K R R P	6 6	3306060272 3306070381 3306070386# 3306080167	50-322 50-322 50-322 50-322	0 0000
	8306210113 8306210352 8306220004 8306220084	50-341 50-361 50-206 50-341	8 9 6	8	3306070216 3306070258 3306130423 3306150214*	50-322 50-322 50-322	0 0 0

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT		AUTHOR AFFILIATION	ACCEBSION NUMBER	SUBJECT CATEGORY	,
	8306150395 8306150401* 8306220134 8306220141* 8306280601	20-355 20-355 20-355 20-355 20-355	G G G G		8304040102 8304040102 8304070039 8304070048 8304070059	50-259 50-327 50-370	X X 8 9 8
	8306290480 8306290485* 8306290492* 8306300081 8306300094	20-355 20-355 20-355 30-355	© G G		8304070044 8304070044 8304070072 8304070072 8304070072	50-390 50-390 50-390	9 9 9
Sugarman, R J Sunflower Ailiance	8306220051 8306220103 8306220103 8306220103	50-352 50-352 50-352 50-352 50-440	6 G G		8306070072 8306070074 8306070074 8306070074 8306070074	50-390 50-390 50-390	8 9 9 9
System Bafety Society Szawiewicz, S A TERA Corp	B306160401 B306060395* B306270067 B306270067 B306270069*	NUREO CONTRACI 50-329 50-329 50-329	r R R		8306070084 8306070087 8306070092 8306070099 8306070121	50-259 50-259 50-260	9 9 9 8
Yallahasse.FL Target Rock Corp Yechnical Operations, Inc	8306270069* 8306030323* 8306130150 8306030489 8306240440	50-329 50-302 50-528 71-9145 71-6613	8 1 8		8304070132 8304070132 8304070138 8304070138 8304070138	50-327 50-390 50-390	F 8 8
Technical Specialties, Inc Teknekron Research, Inc Teledyne Engineering Services	8306270446* 8306090488* 8306010317 8306010317* 8306080068	CONTRACT CONTRACT 50-275 50-275 50-275			8304070138 8304070140 8304070140 8304070218 8304070218	50-438 50-438 50-438	9 8 8 8
	93Q61Q0130 93Q61Q0134* 93Q614Q616* 93Q615Q615* 93Q617Q27Q	50-275 50-275 50-273 50-322 50-275	R R P F R		8306070241 8306070266 8306070284 8306080006 8306080071	50-274 50-327 50-390	8 8 A A
	8304170293 8304170312 8304170313 8304170315* 8304170328	50-275 50-275 50-275 50-275 50-275	ድ የ የ		8306080071 8306080208 8306080208 8306080212 8306080212	50-327 50-327 50-327	A P P P
	8306200249 8306200252* 8306220053* 8306230326* 8306270416	50-275 50-275 50-271 TOPREP 50-275	R R P		8304090135 8304090135 8304090135 8304090135 8304090142	50-370 50-370 50-370	888
Teledyne Isotopes	8306270477* 8306280469 8306280470* 8306280483 8306020019	50-275 50-275 50-275 50-275 70-124	R R R		8306070142 8306070159 8306070310 8306070322 8306070331	50-257 50-438 50-390	9 8 8 Q
Teleflex, Inc Tennessee Valley Authority	8306160689 8306020415* 8306010014 8306010020 8306010113	XPDRTLI 70-1224 50-328 50-327 50-390			1660904068 1660904068 6210014068 6710014068 9210014068	50-259 50-438 50-328	G A S B
	8306010113 8306010136 8306010136 8306010143 8306010143	50-390 50-390 50-390 50-390 50-390	S S S S		8306100237 8306130163 8306130242 8306130340 8306130340	50-296	9 8 A A
	8306010169 8306010237 8306010251 8306010251 8306010269	50-328 50-260 50-438 50-438 50-259	8 8 8 8 9		8306140042 8306140041 8306140041 8306140128 8306140142	50-390 50-260 50-438	A G G
	8304010249 8304010249 8304010274 8304010274 8304010274	50-259 50-259 50-390 50-390 50-390	8 8 9 8		830&140150; 830&1402&6; 830&140420; 830&140427 830&140435	50-259 50-390 50-390	9 9 8
	8304010274 8304010274 8304010283 8304010283 8304010374	50-390 50-390 50-390 50-390 50-327	8 5 8 8 8		830&1404&4 830&1404&4 830&14032& 830&14052& 830&150094	50-390 50-390 50-327 50-259 50-327	8 8 8 9 F
	8306010405 8306010431 8306010431 8306010431 8306010431	50-438 50-370 50-370 50-370 50-370	9 9 9		8306150098 8306150243 8306150243 8306150243 8306150243	50-259 50-259 50-259	F P P P
	8306010431 8306020197 8306030504 8306060102 8306060102	50-390 50-327 70-2910 50-259 50-259	S R X X		83061502481 83061502481 8306160453 8306160453 8306160456	50-259 50-260 50-260	P P P

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC		AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGOR	
	8306160456* 8306160482 8306160507 8306160507 8306160507	50-260 50-259 50-259 50-259 50-259	P R P P		8306210218 8306210226 8306210252 8306210270 8306210270	50-327 50-260 50-438 50-259 50-328	S S S S S
	8306160523* 8306160523* 8306160523* 8306160533	50-259 50-259 50-259 50-390 50-390	P P P A A		8304220011 8304230011 8304230178 8304230178 8304230272	50-390 50-390 50-390 50-390 50-328	EEFF
	8306170334 8306170335 8306170335 8306170423 8306200141	NUREQ 50-390 50-390 90-294 50-438	A A S S		8306230444 8306230453* 8306270007 8306270007 8306270007	50-328 50-328 50-259 50-259 50-259	р Г Г
	8306200141 8306200143 8306200143 8306200145 8306200145	50~438 50~438 50~438 50~370 50~370	១ ត ភ ភ ភ ភ ភ ភ ភ ភ ភ ភ ភ ភ ភ ភ ភ ភ ភ ភ ភ		B306270090 B306270250 B306270274 B306270327 B306270354	50-260 50-327 50-296 50-260 50-390	8 8 8 8
	8306200155 8306200167 8306200169 8306200169 8306200332	40-1341 50-327 50-370 50-390 50-327	9 9 9		8306270354 8306270371 8306270386 8306280092 8306280178	50-390 50-296 50-390 50-438 50-327	\$ \$ \$ P
	8304210004 9304210005 8304210005 8306210010 8306210010	50-438 50-438 50-438 50-259 50-259	8 5 8 F F		8306280192 8306280222 8306280369 8306280369 8306280375	50-327 50-439 50-438 50-438 50-260	8 8 8 8
	8305210010 8305210010 8305210010 8305210010 8305210010	50-259 50-259 50-259 50-259 50-259	F F F F		8306280415 8306280415 8306280415 8306280425 8306280425	50-259 50-259 50-259 50-438 50-438	8 8 8 8
	8306210010 8306210010 8306210010 8306210014 8306210014	50-259 50-259 50-259 50-259 50-259	F F P P		8304280426 8306280426 8306280479 8306280479 8306280567	50-390 50-390 50-438 50-438 50-259	6 5 6 6 6 7
	8306210016* 8306210016* 8306210016* 8306210016* 8306210016*	50-259 50-259 50-259 50-259 50-259	F F F F		8306280967 8306280973 8306280878 8306280578 8306280578	50-259 50-390 50-390 50-390 50-390	P 55 55 55
	8306210016* 8306210016* 8306210016* 8306210016*	50-259 50-259 50-259 50-259 50-259	F F F		8306280578 8306280578 8306280612 8306280612 8306280617	50-390 50-390 50-390 80-390 50-438	55 Fr Fr 50
	8306210018 8306210018 8306210027 8306210027 8306210032*	50-438 50-438 50-327 50-327 50-327	8 8 P P		8306280619 8306290203# 8306290246# 8306290246# 8306290250	50-438 50-259 50-438 50-438 50-259	9
	8306210039 8306210039 8306210042 8306210051 8306210051	50-390 50-390 50-438 50-390 50-390	ទ ទ ទ ទ		8306270275* 8306270283* 8306270283* 8306270283* 8306270316*	50-259 50-259 50-259 50-259 50-390	G G G
	8306210051 8306210051 8306210051 8306210087 8306210087	50-390 50-390 50-390 50-390 50-390	S S S S S S S		8306290316* 8306290319* 8306290319* 8306290388 8306290400	50-390 50-438 50-438 50-327 50-259	9 9 9 9
	8304210115 8304210040 8304210088	50-390 50-390 50-328 50-328 50-327	S 8 8 8 8		8306270400 8306270400 8306270408* 8306270408*	50-259 50-259 50-259 50-259 50-259	6 5 5
	8306210115 8306210116 8306210116 8306210117* 8306210117*	50-327 50-390 50-390 50-327 50-327	F 6 6 6 6		8306290510* 8306300008 8306300013 8306300013	50-259 50-438 50-438 50-390 50-390	9 5 5
	8304510180 8304510180 8304510185 8304510134	50-260 50-390 TOPREP 50-327 50-327	5 6 P P		8304300033 8304300033 8304300038 8304300038 8304300051	50-370 50-370 50-370 50-370 50-370	9 9 9 9
	8306210203* 8306210203* 8306210203* 8306210217 8306210217	50-259 50-259 50-259 50-390 50-390	0 0 0 E E		8304300051 8304300054 8304300054 8304300046 8304300082	50-390 50-390 50-390 50-259 50-390	****

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGOR	IY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	8306300082 8306300139 8306300177 8306300181 8306300205	50-390 50-259 50-259 50-259 50-240 50-390	5 5 6 6 7 8 8		8304090283* 8304090375* 8304100124 8304140448 8304140500	50-346 50-346 50-346 50-346 50-346
	8306300205 8306300208 8306300214 8306300214 8306300214	50-390 50-259 50-390 50-390 50-390	\$ 5 6 5 5 S		8306160540 8306160679# 8306160690# 8306170027 8306170075	50-346 50-346 50-346 50-346 50-346
	8304300214 8304300224 8304300228 8304300228 8304300245	50-370 50-260 50-370 50-370 50-438			8306170142 8306170276 8306170414 8306170429 8306200393	50-346 50-346 50-346 50-346
Tennessee, State of Texas ASM Univ . College Station, TX	8306300245 8306300254 8306220222* 8306010278* 8306010358	50-438 50-438 CONTRACT 50-128 50-128	\$ 8 1 H P		8306200374* 8306210026 8306210084 8306210170* 8306210262	50-346 F 50-346 F 50-346 E 50-346 (
	8305010351* 8305010389 8305030045 8305050213 8305050216*	50-128 50-128 71-5957 50-128 50-128	P R P P		8306230257 * 8306230263 * 8306230259	50-346
Texas Utilities Generating Co	8304010279 8304010392 8304030330 8304080239 8304080239	50-445 50-445 50-445 50-445 50-445	F A G G	Torrey Pines Technology	8304270204 8304270379 8304070354 8304070359 8304220078	50-346 C 50-344 C 50-358 F 50-358 # 50-358 #
	8306080241* 8306080241* 8306080243* 8306080243*	50-445 50-445 50-445 50-445 50-445	G G G G	Transnuclear, inc	8305230131 8305230133* 8305020580 8305150337 8306150425	50-358 # 50-358 # XPORTLIC XPORTLIC XPORTLIC
	8306070043 830607031 <i>2</i> 8306070312 8306070315* 8306130440	50-445 50-445 50-445 50-445 50-445	s v v v s	Transportation, Dept of Trends Publishing, Inc Tri-State Motor Transit Co Twomey, Latham & Shea	8306240375 8306080341 8306160041 8306200115 8306280608#	71-9015 71-4909 FOJA 70-1739 50-322 G
	8306150366 8306150376 8306150425 8306170406	50~445 50~445 50~445 50~445	G G G	URB Corp US Ecology, Inc. (formerly Nuclear Engineering)	8306030222 8306020222 8306030105	REVIEW ORP 27-48 71-6679
	8306300055 8306300055	50-445 50-445	s s		8304210435 8304240487	27-48 27-48
	8306300074 8306300074 8306300088 8306300088	50-445 50-445 50-445 50-445	5 5 5 5 6 7	Underhill Range Committee Unibraze Corp Union 76 Minerals Exploration Co	8306210313 8306070107* 8306070110* 8306020300 8306140687	FDIA DA999 DA999 40-8584 40-8584
Yexas Utilities Bervices, Inc	B306300167 B306300167 B306090162 B306100153 B306100153	50-445 50-445 50-445 50-445 50-445	ସ କ A A A	Union Carbide Corp	8306270177 8306020198 8306020201* 8306020314 8306020320*	40-8584 40-247 40-247 40-247 40-247
	8306130176 8306130193 8306130193 8306130279 8306130279	50-445 50-445 50-445 50-445 50-445	A A A		8304030064 8304070467 8304070470* 8304080348* 8304080358*	70-487 40-299 40-299 71-4909 71-4909
	8304130293 8304130293 8304130102* 8304140503 8304140508*	50-445 50-445 50-445 50-445 50-445	A A F G Q	Union Electric Ca	8306070364 8306010110 8306070145* 8306100147 8306100148*	50-54 P 70-2745 50-483 G 50-483 A 50-483 A
Texas, State of The Southern Co	8306280400* 8306150307 8306230491* 8306280553 8306070127*	50-445 50-445 CONTRACT 50-443 50-321	e e		B306150455* B306160314 B306160322* B306170279 B306210198*	50-483 F 50-483 Q 50-483 Q 50-483 B 50-483 Q
Theeman, B A Thomas, D C Three Mile Island Alert	8304030054* 8304200320 8304300215 8304020355 8304020454	CONTRACT 50-454 50-454 50-289 PR	የ		8306220132 8306220137# 8306230481# 8306270235 8306270385	50-483 G 50-483 G 50-483 Q 50-483 8 70-2945
	8305050279 8305270388 8305280202 8305300075 8305300097*	50~287 50~287 50~320 50~287 50~289	G G F G	Union Minerals Union of Concerned Scientists	8306300090* 8306060415 8306030007 8306070418 8306080028	50-483 G 40-8584 50-320 G 50-287 Q FOIA
Toleda Edison Co	8306020129 8306040137 8306070166* 8306070397 8306090060*	50-346 50-346 50-346 50-346 50-346	R S Q G F		9304090258 9304150387 9304140297 9304140404	FOIA 50-247 G 50-287 G 50-287 G

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC	RY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC	RY
United Engineers & Constructors, Inc (subs of Raytheon Ca)	8306230350 8306270157 8306300037 8306200242*	50-247 50-247 50-289 50-443	G G E		8306140222* 8306160247 8306160247 8306160266* 8306160266*	50-338 50-338 50-338 50-338 50-338	P P P
(subs of Regiment Cu)	81101230008	50-443	S		9306160375 9306160399	50-280 50-338	R F
United Nuclear Corp	8304230458* 8304240243* 8304240245* 8304030502 8304080022	50-443 QA999 QA999 70-371 71~5641	A		8306160405 8306160532 8306170138	50-338 50-281	P R Q
Uraners USA, Inc Uranium Resources, Inc	8306130450 8306270577 8306210353 8306090028 8306090035#	70-820 70-820 40-8783 40-8786 40-8786	•		8306170281 8306170281 8306170327 8306170327 8306170331*	50-280 50-280 50-280 50-280 50-280	Р Р
Utah. Univ of	8306210425 8306210451 8306220130 8306060226 8306160194*	40-8786 40-8786 40-8786 PR 50-72	•		8304170331* 8304200114 8304200209 8304200219 8304200232	50-280 50-339 50-339 50-280 50-338	9 9 9 9
Vermont Yankee Decommissioning Allkance Vermont Yankee Nuclear Power Corp	8306210027 8306010246 8306010248* 8306010379 8306010383*	50-271 50-271 50-271 50-271 50-271	H P P P		8306210285 8306220033 8306220033 8306220047* 8306220047*	50-280 50-280 50-280 50-280 50-280	S P P P
	8306010435 8306010436* 8306020174 8306030112 8306080076	50-271 50-271 50-271 50-271 50-271	Р Р Р Ф		8306270005 8306270104 8306270142 8306270183 8306270214	50-280 50-338 50-339 50-339 50-338	5 5 6 6
	8306070303 8306140285 8306140487 8306150161 8306170037	50-271 50-271 50-271 50-271 50-271	P P Q P		8306270316 8306270351 8306270357* 8306270364* 8306270366	50-339 50-281 50-281 50-281 50-338	ង ន ន ន ន
	8306170068 8306170264 8306200073 8306200388 8306210118	50-271 50-271 50-271 50-271 50-271	R S I Q		8306270430 8306280568 8306290391 8306290387* 8306290387*	50-338 50-338 50-280 50-338 50-338	9 9 0 0
	8306210223 8306220044 8306240170 8306280112 8306280173*	50-271 50-271 50-271 50-271	Q р Р F		8305290551 8306300020 8306300036 8306300076 8306300149	71-5450 50-338 50-404 50-338 50-280	Б К
Versar, Inc	8305170485*	50-271 CONTRACT	Q T		8306300149 8306300151*	50-280 50-280	ĸ
Victoreen, Inc. (subs of Sheller-Globe Corp)	B306240201* B306240207*	0A999 0A999			8306300151* 8306300199 8306300240	50-260 50-261 50-336	Ж Б Р
	8306240214* 8306240219*	0A999 0A999		Virginia, Univ. of, Charlottesville, VA Vollen, R.J. & Whicher, J.M	8306140005 8306100201	50-42 50-454	S
Virginia Electric & Power Co	8306240224* 8306240227* 8306020092 8306020159 8306020159	0A999 0A999 50-338 50-280 50-280	R R R	Washington Public Power Supply System	8304010104 8304010220 8304010234	50~513 50~397 50~397 50~397	S A A
	8306020162# 8306020168* 8306020168* 8306020173*	50-280 50-280 50-280 50-280	R R R		8306010348 8306010376 8306010400 8306010413	50-397 50-508 50-397 50-397	0 F A
	8306020173* 8306020424 8306070148 8306070173 8306070220	50-280 PR 50-339 50-338 50-280	R S S S		8304020345 8304030347 8304030353 8304070095	50-460 50-460 50-460 50-397	9 6 9 5
	8304070238 8304070243* 8304070245* 8304070249	50-281 50-281 50-339	ត ទ ទ ទ		9306070113 8306080026 8306080039 8306090207 8306090262	50-460 70-2950 50-397 50-508 50-460	A C A
	8304070276 8304070281	50-339 50-338	5 6		8306090337 8306100117	50-460 50-508	Ģ A
	8304080225 8304080225 8304080228* 8304080228*	50-338 50-338 50-338 50-338 50-338	P P P S		8306100190 8306130004 8306140612 8306150354	50-460 50-397 50-460 50-508	G A A
	8304070137 8304070314 8304070318 8304100170	50-338 50-339 50-338 50-280	9 4 9		8306160048* 8306160147 8306170184 8306170215	50-305 50-397 50-508 50-397	F K A R
	98100190	50-281	9		8306170222* 8306170276 8306170428*	50~508 50~508	g s
	8306140208 8306140208 8306140222*	50-338 50-338 50-338	P P		8306170426* 8306200243 8306200251*	50-508 50-397 50-397	G E E

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT	RY	AUTHOR AFFILIATION	ACCESSION NUMBER	BUBJECT CATEGORY
	8306210120 8306210154 8306230364 8306230373 8306240337	50-397 50-508 50-460 50-508 70-2950	A A G A		9306200267 9306210091 9306210091 9306210100 9306210100	50-266 50-266 50-266 50-266 50-266
	8306240460 8306270347 8306270353* 8306280453 8306280596	70-2950 50-397 50-397 50-397 50-397	S S E A		8304210207 8304230261* 8304230261* 8304230354 8304230356	50-301 50-266 50-266 50-266 50-266
Washington State Univ Washington, Univ of, Seattle, WA Waste Management Group, Inc Water, Waste & Land, Inc	8306300047 8306200151 8306140691 8306030476 8306080350	50-460 50-27 NUREG WASTE MG 40-299	G F QT		8306270275 8306270275 8306280397 8306280443 8306300058	50-266 50-266 50-266 50-266 50-266
West Branch Conservation Association West Newbury. MA Hest Valley Agricultural Protection Council. Inc	8304080200 8304270254 8304030333	50-247 50-443 50-529	G G G	Hisconsin Public Service Corp	8304020375 8304070070 8304100189 8304140001	50-305 50-305 50-305 50-305
	8306030333 8306030334*	50-529 50-529	G G		8306140048 8306160619	50-305 / 50-305 (
	B305030334* B305030335* B305030335* B305100075 B305100075	50-529 50-529 50-529 50-529 50-529	G G G		8306170056 8306200102 8306210041* 8306270110	50-305 50-305 50-305 50-305
Nestchester County, NY	8306100078* 8306100078* 8306150378 8306150378 8306290550	50-529 50-529 50-529 50-529 50-247	G G G	Wisconsin, Univ of Madison	8304280373 8304280378* 8304040272* 8304150521* 8304210398	50-305 1 50-305 1 50-156 (CONTRACT ACRS
Western Nuclear, Inc. (subs of Phelps	8306200074	40-1142		Wolfbein,S L Wyoming Mineral Corp	8304200289* 8304130245	CONTRACT 40-8502
Dodge Corp) Westinghouse Electric Corp	8306060118#	40-8684 70-1151			8306160215 8306200182 8306240436	40-8502 40-8502 40-8502
	8309080053*	70-1151 70-1151		Wyoming, State of	8306020294 8306200160	40~8064 40~8697
	8306080327 8306090012 8306150167 8306150172* 8306160224	71-4909 XPORTLIC PROJ PROJ NUREG			8304200179 8304200274 8304210454 8304220113	40-8584 40-8380 40-8064 40-8584
	8306160433 8306160672 8306170254 8306200402* 8306230386	PT21 XPORTLIC RECOD 50-284 TOPREP	C F		8304220114 8304220121 8304220124	40-277 40-279 40-2259 40-8728
	8306230391* 8306240205 8306240313 8306240314*	TOPREP 50-369 TOPREP TOPREP	P	Yakima Indian Nation	8306220136 8306230331 8306240444 8306280106 8306020225	40-1162 PR 40-8768 40-8348 27-49
	8306240315* 8306270355 8306270434 8306280392 8306280392	TOPREP PROJ PROJ 50-445 50-445	A	Yankee Atomic Electric Co	8306240076* 8306240101* 8306240131* 8306010165* 8306010448	FOIA FOIA FOIA 50-29 50-443
Westinghouse Operating Plants Owners	8306280449 8306300120 8306300120 8306160284	TOPREP 50-445 50-445 TOPREP	A A		9306010449* 9306020139 9306020337 9306030177 9306030177	50-443 (50-29 (50-29 (50-443 (50-443 (
Group	*17509190EB	TOPREP TOPREP			8305070302 8305080125	50-29 50-443
Williams-Robinette & Associates, Inc	8306160303* 8306220087 8306140438*	TOPREP TOPREP CONTRACT			8304080125 8304090271* 8304140047	50-443 I 50-29 I
Wilner, Gutler & Pickering Wisconsin Electric Power Co	8306150570* 8306220259* 8306200273 8305020208	CONTRACT CONTRACT FOIA 50-266	r s		9306150273* 9306150277* 9306160392 9306170033 9306170167	50-271 50-271 50-27 50-27 50-443
	8305020231* 8306010428 8306010428 8306060078	50-266 50-266 50-266	5 P P		8306170339 8306170398 8306170418 8306200236	50-29 50-29 50-29 50-443
	8306040156 8306070086 8306070404	50-266 50-266 50-266	F F J		8306200330	50-443
	8306090185* 8306130146 8306130146	50-266 50-266 50-266	G G G		8306200330 8306200365* 8306200369* 8306200397 8306200397	50-443 50-27 50-27 50-443 50-443
	8306160460 8306200137 8306200137	50-246 50-266	R R		8306210017 8306210024*	50-29 50-29
	8304200240	50-599 50-599	P P		8306230452 8306280009 8306280011*	50-443 50-309 50-309

AUTHOR ACCESSION SUBJECT AUTHOR ACCESSION SUBJECT NUMBER CATEGORY AFFILIATION NUMBER CATEGORY

B306280107 50-29 S 8306280144 50-29 S 8306280545 50-443 S

REPORT NUMBER INDEX

The subject category column in this index gives the docket number and the symbol for the category of information within that docket; for example, 50-320 P. The docket subject categories are defined in Appendix A.

Subject categories for nondocketed items are also entered in this column by symbol; for example, ACRS. These categories are defined in Appendix B and listed in the Contents. An asterisk following the accession number in this index indicates that the document is an enclosure to another document. To obtain the accession number of the principal document under which the enclosure is listed, refer to the index entitled "Cross Reference of Enclosures to Principal Documents."

REPORT	ACCESSION	SUBJECT	OTHER REPORT
NUMBER	NUMBER	CATEGORY	NUMBER
029-GA-80-PA R02	8306130328#	50-322 E	
A3 E0-880	8306070107#	50-529 S	
15183	8306070235	50-219 R	
186-028-04	8306020583*	50-298 0	
22A7007	8306070114*	50-447 к	
2468 R00	8306140737*	50-289 F	04-4824-035
3572	8306240312*	50-244 P	
77-1140895-00	8306140752*	50-269 P	
77-1141256-00	8306140746*	50-269 P	
77-1143707-00	8306160497*	50-3(3 P	
82-31 R00 83-0002	8304270230* 8304010078*		DER 82-61
8306010478 8306020048 8306020683	8306010478 8306020048 8306020683	RES RES RES	BNL-NUREG-32676 BNL-NUREG-32746
8306030435	8306030435	RES	BML-NUREG-32824
8306070422	8306070422	RES	
8306080229	8306080229	res	DMI-NUREG-1991
8306170192	8306170205*	res	
8306240241	8306240241	res	
906505	8306160545*		PED-81-2200
906577	8306160560*		PED-81-2200
904624	8306070106*	50-267 P	
9743 006~8~N-5	8306230458*	50-443 A	
AEOD/N301	8306160057*	FOIA	
ARTECH-83-001 B&RDE-CDM4-1-NP RO3	8306020452* 8306230443*	50-247 G TOPREP 50-322 E	
B31-F031 R23	9304130332*	50-322 E	•
BAW-1784	8304070286*	50-269 P	
CEN-239	8304300125*	50-361 P	
CEN-239 801	8304300136*	90-361 P	
CPL-09-102 ROO	8306140549#	50-324 G	
DET-19-076-6 ROO	8306160366#	50-341 A	
EA-83-8RO-005	8306060149*	50-255 P	
EGG-HS-6263 DRFT	8306160641*	50-389 P	
EGG-PHYS-6241	8304080161	50-335 P	
EPRI NP-1850-CCM VO4	8306240263*	TOPREP	
GA-A16829	8306160564*	50-247 P	
GP-R-74002	8306240012*	50-324 P	
GPC-07~102 ROO	8306100136*	50-366 P	
IP8-701	8306170336*	50~390 A	22335
K/D-5400 RO1	8306080358*	71~4909	
K/TL/68-88	*84E08060E8	71-4709	22335
M1~LR~83~01	8306170320*	TOPRCP	NG-83-2093
MK1~03~008	8306230351*	50-331 P	
NEDO-22198 NF-1583 04 (NP)	8306070174* 8306080083*		92NED084
NSP-48-1103 RO1	8306170354*	50-263 F	EB2N4OD
NUREG 0750 V16 NO1	8306230517	NUREO	
NUREG-0020 V07 NO2	8306210401	NUREO	
NUREG-0090 VOS NO4	8306140324	NUREQ	
NUREG-0304 V08 NO:	8306030488	NURE@	,
NUREG-0422 507	8306160665	50~369 F	
NUREG-0485 V05 N04	8306020144	NUREQ	
NURE0-0540 V05 NO2	8306060419	NUREC	

REPORT NUMBER	ACCESSION NUMBER	SUBJECT CATEGORY	OTHER REPORT NUMBER
NUREG-0580 V12 NO5	8304240048	NUREG	
NUREG-0606 VOS NO2	8304210383	NUREO	
NUREG-0748 VO3 NO4	8304070014	NUREG	
NUREG-0800 FC	8306070437	NUREG	
NUREG-0800 RO4 ERR	8304010158	NUREG	
NUREQ-0831 804	6306210331	50-416 E	
NUREG-0843 502	8306010057	50-389 €	
NUREQ-0843 S04	B306240056	50-389 E	
NUREG-0853 502	8306060412	50-461 E	
NUREG~085&	8306240060	NUREC	
NUREG-0869 FC ERR	8306010166	NUREG	
NUREG-0880 RO1 FC	8304080158	NUREC	
NUREG-0882 SO1	8306210378	50-170 €	
NUREG-0892 \$03	8306010043	50-397 E	
NUREG-0904	8306080146	40-2061	
NUREG-0910 R01	8304150588	NUREG	
NUREQ-0927 FC	8304040413	NUREG	
NUREG-0736 VO2 NOI	B304010046	NUREG	
NUREG-0939	8306210362	NUREG	
NURE0-0948 802	8304150616	50-537 €	
NURE0-0982	8306210317	50~57 E	
NUREG-0986	8304240043	NUREG	
NUREO-0987	8306020112	70-1201	
NUREG-0992	B304210354	NUREG	
NUREG-0993 FC	8306060418	NUREG	
NUREO-0777	8304010018	NUREG	
NUREG/BR-GOL5	6309010138	NUREO	
NUREO/BR-0025 VO9 NS	8304150574	NUREO	
NUREO/BR-0051 VO4 N7	8304290131	NUREG	
NUREG/CP-0043 ERR	8306220245	NUREO	
NUREG/CP-0044 VO1	8304170243	NUREC	MEA-2014
NUREG/CP-0044 VO2	8306150081	MUREG	MEA-2014
NUREQ/CR-1579	8304270157	NUREG	ENI CO-1049
NUREG/CR-2006	8304020072		BNL-NUREG-51541
NUREG/CR-2044	8306210324	NUREG	ORNL/N61C-194
NURED/CR-2607	8304280033		SAND82-0431
NUREG/CR-2840	8306240052		PNL-4232
NUREG/CR-2766	8305140315	NUREG	
NUREG/CR-2767 ERR	8306010144		SAND82-1292
NUREO/CR-2785	8304010088	NUREG	BNL-NUREG-51551
NUREQ/CR-2786	8304150402		EPRI NP~2542
NUREO/CR-2789	8304280089		ORNL/NSIC-210
NUREG/CR-2800 801	8306020131	NUREG	PNL-4297
NURE0/CR-2009 VO4	8306270146	NUREG	0RNL/TM-8397
NUREG/CR-2814 VO3	8304020193	NUREC	LA-9649-PR
NURE9/CR-2837 801	8306020134		PNL-4327
NUREO/CR-2839	6304010084		URNL/CSD-TH-190
NUREO/CR-2841	8306020007		6AND82-1572
NUREQ/CR-2643 V02	140010041		8AND82-1788
NUREG/CR-2874 VO3	8306280073	NUREG	ORNL/TM-8443/V3
NUREO/CR-2906	9306280044		BNL-KUREG-31580
NUREG/CR-2954	8304240373		PNL-4264
NUREG/CR-2962	8306270141		8AND82-2164
NUREG/CR-2955	8306150064		UCRL-53325
NUREO/CR-2969	8304020066	NUREG	BNL-NUREG-51590

REPORT NUMBER	ACCESSION NUMBER	SUBJEC	R. NUMBER	REPORT NUMBER	ACCESS 10N NUMBER	SUBJECT CATEGORY	OTHER REPORT NUMBER
	8304580080	50-259	P DRNL/TM-8532		000400004		
NUREG/CP~2973		NUREG	PNL-4491	RMC~TR~83-02	8306270251*		R
MURE0/08~3011	B305020053		PNL-4510	RMC~TR-83-03	8304150270*		R
MUREQ/CR-3012 V01	8305010037	NUREG		SAI~186-028-30	8504500392*		Q
NURE0/08~3012 V02	B306010067	NUREG	PNL-4510	SAI~186-028-33	8209200370*		G
MOMEG. NO. 2015 AO. 3	8304010071	NUREG	PNL-4510	SA1~186-029-28	8209030325*	50-346	P
NUREO/CR-3027 ERR	8304030485	NUREG	PNL~4523	SAND82-2429	8211220337*	50-245	P
NUREO/CR-3047	8306240030	NUREC	PARAMETER (E-12	SCE-1-A A06	8306130392*		P
NUREQ/CR-3095 VOI	8305310226	50-245	P SANDB2-7212	SECY-85-052	*E7100160E8	FOIA	•
NUREG/CR-3097	8306140402	NUREG	PNL-4563	SECY-82-046	8306160178*	FOIA	
NUREG/CR-3089	8305060410	NUREG		SECY-82-127	8204070016*	FOIA	
NURE0/CR-3119 V02	8306150384	NUREG	ATR-83(3818)-1N				
	8306020080	NUREG	SAND93-0417	SECY-82-162A	*B010404018	FOIA	
10V 1E1E-83\03#UM			SAND92-2559	SECY-82-210	B304140208*	FOIA	
MUREQ/CR-3156	8304270151	NUREG		SECY-82-313	8306160216*	FOIA	
NUREG/CR-3163	8306280049	NUREG	SAND93-0245	SECY-82-475	B306030370*	FOIA	
NUREQ/CR-3164	8306010266	NUREC		6ECY-83-219	8306240403	SECY	
NUREG/CR-3173	8305170121	NUREG		STD-R-02-011 R00	8304020592*	71-9080	55557
NUREQ/CR~3174 VO1	BA108040EB	NUREG		STD-R-02-012 R00	B304130212*	71-9089	22286
NUREG/CR~3183	8306240073	NUREG	PNL-7650	SWRI-6901-002	8304270003*		P
NUREQ/CR~3185	8304280190	NUREG	1807-58DAR	TER~C5257~388 DRFT	B304090397*		P TAC 08079
NUREG/CR-3189	8306020016	NUREG	SANDE3-0356	TER~C5257-335 DAT 1	B302250381*		
				1EK~C3237-467	6705520761*	50-336	P TAC 42493
NVRE0/CR-3191	8306010091	NUREG	SAND83-7012	TER~C5506-337/338/33	#84506190E8	50~259	P TAC 07974
NUREG/CR-3194	8306240078	NUREG	PNL-4653	TER~C5506-342	#01C0E0A0E8		P TAC 079/8
NUREG/CR~3207	8306010094	50~201	P	TER-C5506-344/345 DR	8304030299*		P TAC 07980
AVREQ/CR-3210	8304020011	NUREG	EGG-2247	TER~C5506-346 DRFT	8304090388*		P TAC 07982
MWREQ/CR~3217	B304030009	NUREG	PNL-4662	TER-C5506-347 DRFT	8304020196*		P THE OTTER
NUREQ/CR~3219 V02	8306140407	NUREG	BNL-NUREG-5165B	TTS 7/8			
NUREG/CR~3225	8306150619	NUREG	UCRL-53049	TER~C5506-363 DRFT	B305200714*		P TAC 16747
NUREG/CR-3226	8306010052	NUREG	SANDB2-2450	TER-C5504-365 DRFT	8304020037*		P TAC-08059
MUREQ/CR-3228 VOI	B306060366	NUREG	MEA-2012	TER-C5506-372/373 DR	8306030070*	50-338	P TAC 47112
NAJREG/CR~3237	8306140774	NUREG	UCLA-ENG-8257	TER~C5506~377	*445404140E8	50-219	P TAC 47120
	0300140774	1101125	OUCH ENG-BEST	TER-C5504-379/380	8306060327*	50-277	P TAC 08070
MUREO/CR~3245	8304020122	NUREG	0EA8-MT\J/M90	TER~C5506~384/385	8305230021*		* T.C 0007F
MUREQ/CR~3248	B306070471	NUREG	PNL-4691				TAC 08075
NUREG/CR~3254	8306240058	NUREG	PNL-4683	TER-C5506-394 DRFT	8304080252*		P TAC 08083
NUREO/CR~3263	8304280013	NUREG	LA-9729-MS	TER-C5506-395/396 DR	*4440E040E8		P TAC 08084
NUREQ/CR~3267	8304280085	NUREO	ANL-83-32	TER-C5506-403/4D4 DR	#2160E090E8		P TAC 08092
				TF-382/0823A	8306290413*	50-245	P TAC 44384
NUREG/CR~3281	8306240413	50-286	P BNL/NUREG-51670				
NUREQ/CR-3287	8309510320	NUREG	DRNL/TM-8763	T9-5310-1 PC1	0001110111		
NUREG/CR~3290	8306070452	NUREG		TR-5310-1 R01	B306140616*	50-293 F	•
NUREG/CR-3291	B306070473	NUREG		TR-5709-1	8309530359*	TOPREP	
NUREQ/CR-3292	8306280076	NUREG	ANL-83-27	TR-MCM-112	8306010083#	50-528 8	i
				TR-V-MCM-003	8306010087*	50~528 €	3
NUREG/CR~3294	8306240062	NUREO	MEA-2016	UCID-19115 RO1	8304070100*	50-277 F	1
MUREQ/CR-3296	8306240384	NUREG	PC1-TR-224				
NUREQ/CR-3308 VO1	8304140691	NUREG		UC10-19705	8306100135*	50-237 P	ı
AR SBAPE-BAO	8306230169*	50-414	P	UMTRA-DOE/AL-140 DR	8306080153*	WASTE MOT	
ORNL/NSIC-202	8306160631*		P	URS/JAB 8050	820613023B#	REVIEW GRP	Ì
			•	UTEC ME 82-100	8306160174*	50-72 F	•
DRNL/TH-8275	83060800414		_	WAPD-LP(FE)-220 RO3	83060100B5*	71-6400	22304
DRQ-4207~15	8309010386	50~128	R	MARU-1750	DD0100000		
PLG-0207 DRFT	*9EE01290EB			WASH-1250	8306200040*	FOIA	
PR-T-79-012 ROL	8306160670*	71-9134		WCAP-10170 APP E	#19E0ES40EB	TOPREP	42320
PR0483-0014A-QL07 RI	8306100272*	50~329	A	WVDP-100	8304270424*		22338
				VAEC-1356	8306280011#	50-309 P	
				YAEC-1361	8306210024#	50-29 P	

ACCESSION NUMBER

Items listed as enclosures are those indicated by an asterisk following the accession number in the indexes. The second column gives the accession number of the principal document under which the enclosure is listed. Knowing the accession number of the principal document, the date issued, and the category enables locating the title listing of the enclosure.

The subject category column in this index gives the docinumber and the symbol for the category of informati within that docket; for example, 50-320 P. The docket subjecategories are defined in Appendix A.

Subject categories for nondocketed items are also enter in this column by symbol; for example, ACRS. These cagories are defined in Appendix B and listed in the Conten

ACCESSION	NUMBER
-----------	--------

7100200707	, 110112111		
	PRINCIPAL	DATE	BUBJECT
ENGLOSURE	DOCUMENT	ISSUED	CATEGORY
*			
8006200486	E0004040EB	83/03/21	FOIA
80071 60084	E0004040003	83/03/21	FOIA
B007030104	8306170089	83/04/14	FOIA
B010070140	830617008 <i>9</i>	83/04/14	FOIA
8107210318	8304040051	83/04/07	50-287 P
8111040442	8306140394	83/05/24	XPORTLIC
8112030545	8304020024	83/05/12	50-498 A
8203070438	18002140081	B3/04/19	FOIA
8204070018	6307030363	83/04/01	FOIA
8204090019	8304080388	83/05/24	50-50B A
			ED 447 4
8204120488	8306060051	83/04/07	50-416 A 50-206 P
8205170474	8306070019	83/04/05	
8207280024	8306060051	83/04/07	50-313 P
Ø208050024	8306070019	83/04/05	50-206 P
8207030325	8304030503	83/05/13	50~346 P
05055555	5551010100	DD (DH () ()	BO BEA O
8209200365	6309010125	83/05/19	50-254 G 50-253 G
8207200370	8306030119	83/05/19	
8209210553	8304140186	83/04/28	FOIA
8210270150	8304280129	83/06/17	HIBC
8211160565	8304140052	83/04/14	50-206 U
6211220332	8306060051	83/04/07	50-245 P
8211220337	8306060051	83/04/07	50~245 P
6212020236	B306200031	83/03/07	ADVCH
6302250361	8306140352	83/06/03	50-336 P
8303220042	8306170469	83/06/08	50-309 G
0202550045	02001/0407	937 097 00	30-307 0
0303220403	8306150121	83/05/31	TOPREP
8304070100	6306260156	83/06/14	50-277 P
0304110827	8304110818	83/03/10	50-334 B
8304190510	8305040657	83/04/28	CONTRACT
8304290092	8306210066	83/04/13	50-409 P
 (-1201)			
8305020231	8305020208	93/04/19	50~266 8
8305020555	8306010091	83/05/20	PR
8305040713	8305040708	83/04/20	CONTRACT
8305190373	8305170370	83/05/13	50-373 P
8305200714	8304010045	93/05/16	50-305 P
0305230021	B306170053	83/05/05	50-282 P
0303230135	B305110471	01/40/69	50-275 P
0305230345	B305110471	83/04/10	50-275 P
B305240443	8305240436	83/05/20	50-293 P
Ø305240448	8305240436	83/05/20	50-293 P
0305240455	8305240436	83/05/20	50-293 P
0305240441	8305240436	83/05/20	50-293 P
8305240612	8305240605	83/05/07	COMMIBBION
8305240624	8305240605	83/05/09	COMMIBBION
8304010028	8306010024	83/05/12	50-313 P
d201010022	000101000	00/08/05	CONTRACT
6304010077	8304010022	83/05/07	CONTRACT 50-528 B
630601007B	B306010072	83/05/18	
6304010083	B306010072	83/05/18 83/05/18	50-528 B
6304010065	1000109068	83/04/22	71-6400 50-528 8
8306010087	8306010072	83/05/1 8	50-528 8

ACCEBBION	NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUEP	SUBJECT CATEGOR	Υ
00101040EB	9309010039	83/05/17	50-29	æ
0306010100	10101040EB	83/05/12	50-313	G.
			50-313	ě
8306010124	8304010121	83/05/16	50-347	Ģ.
8304010124	8306010115	83/05/25		Œ
8304010129	B306010117	83/05/11	CONTRACT	
8306010134	8306010121	83/05/16	50-397	0
8304010135	8306010132	03/05/14	50-267	0
8306010141	6309010135	83/05/14	50-267	a
8304010153	8306010148	B3/05/17	70-371	
95101090E8	8304010151	83/05/31	50-358	K
8304010164	9306010159	83/05/25	50-341	a
8304010145	03101030EB	83/05/25	50-29	Q.
8306010174	8304010148	83/05/27	50-341	ĸ
8304010177	8306010171	83/05/26	50-387	G
8306010178	6306010148	83/05/27	50-341	ĸ
8304010182	B306010179	83/05/19	50-254	a
90501020E	B306150490	83/04/08	50-213	Ø
8306010229	8306010227	B3/05/16	50-333	ä
8306010231	B306010227	83/05/14	50-333	a
9306010239	8304010233	83/05/31	50-352	Α
8304010240	8304010233	63/05/31	50-352	к
8304010243	8306010233	83/05/31	50-352	C
8304010248	8306010246	83/05/26	50-271	P
8304010298	8306010296	83/05/27	50-128	н
8306010304	100010301	83/05/17	50-271	a
90E010308	E00010303	93/05/17	50-213	a
8306010319	8306010317	83/05/27	50-275	R
8306010320	8304010318	83/05/16	50-317	ä
8306010324	8304010318	83/05/16	50-317	ā
8306010327	8304010324	83/05/17	50-334	G
	2001512222	00 (00 (0)	50~348	a
8309010333	8306010332	83/05/24 83/05/17	70-697	u
8306010339	8306010338		50-267	ρ
8306010344	8306010343	83/05/20 83/05/20	50-267 50-267	þ
8306010345	6304010343 6304010350	83/05/25	50~267 50~478	6
6304010354	6309010330	03/03/63	30-470	
P306010357	B304010325	83/05/23	50-375	a
1400104058	8304010358	83/04/29	20-75B	P
8304010366	8304010325	83/05/23	50-375	g
07E01040E8	8304010345	83/05/16	50-247	G
17E01040E8	8304010367	93/05/26	50~366	P
8306010374	8304010325	83/05/23	50-395	Q
8306010378	8304010365	83/05/16	50-247	G
8304010380	8304010372	83/05/26	50-352	0
8304010383	8304010379	83/05/26	50-271	₽
8306010395	8306010390	83/05/27	50-400	e
8306010412	8306010402	83/05/25	50-220	a
8306010416	8304010411	B3/05/20	50-267	P
8306010419	B306010411	83/05/20	50-267	p
8306010429	B306010426	83/05/27	50-364	P
8306010436	8304010435	83/05/26	50-271	P

ACCES810	NUMBER				ACCEBBIO	ON NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEODR	Υ	ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGOR	
8304010443 8304010445 8304010449 8304020012 8304020032	B304010437 B304010438 B304010442 B304020009 B304020025	83/05/27 83/05/09 83/05/25 83/05/13 83/05/18	50-443 50-278 50-443 50-315 70-2953	0 5 0 P	8306030144 8306030147 8306030191 8306030191 8306030158	B306030142 B306030142 B306030146 B306030149 B306030156	83/05/16 83/05/16 83/05/17 83/05/16 83/05/12	50-441 50-441 50-546 50-440 50-247	0 0 0 0
8305020037 8305020047 8305020104 8305020111 8305020115	8304020015 8304020043 8304020079 8304020107 8304020107	83/05/24 83/05/24 83/05/27 83/04/12 83/05/17	50-309 50-320 50-397 50-315 50-324	P H 0 R 0	8306030174 8306030179 8306030185 8306030202 8306030213	8304030170 8304030152 8304030180 8304030178 8304030209	83/05/10 83/05/27 83/05/20 83/05/18 83/05/19	50-322 70-1201 50-483 50-544 50-374	0 0 0
8306020118 8306020162 8306020168 8306020173 8306020178	8306020109 8306020159 8306020159 8306020159 8306020174	83/04/12 83/04/14 83/04/14 83/04/14 83/05/26	50-315 50-280 50-280 50-280 50-271	R R R P	8306030230 8306030246 8306030256 8306030256	8304030223 8304030231 8304030242 8304030252 8304030263	83/05/27 83/05/20 83/05/24 83/04/06 83/05/25	50-155 50-309 50-329 CONTRACT	
8304020184 8304020187 8304020194 8304020201 8304020209	9306020174 9306020180 9306020188 9306020198 9306020205	83/05/26 83/05/19 83/05/19 83/05/09 83/05/20	50-271 50-259 50-302 40-299 50-331	Р Р	9306030271 8306030281 8306030284 8306030287 9306030303	8304030248 8304030272 8304030277 8304030290 8304030298	83/05/19 83/05/31 83/05/20 83/05/16 83/05/26	CONTRACT 50~454 CONTRACT 50~315 50~334	ĸ
8305020240 8305020242 8305020243 8305020249 8305020254	8304020232 8304020238 8304020238 8304020259	83/05/20 83/05/09 83/05/09 83/05/20	50-272 50-322 40-8410 50-322 71-250	F U U	8304030310 8304030311 8304030312 8304030314 8304030317	8306090426 8306030307 8306030291 8306030282 8306030314	83/05/27 83/05/27 83/05/20 83/05/27 83/05/20	50-317 50-348 50-277 50-309 70-371	P 0 0
8309050350 8309050308 8309050303 8309050540	8304020259 8304020107 8304020299 8304020303 8304020314	83/05/10 83/05/19 83/05/23 83/05/03 83/04/27	40-299 50-324 50-277 40-8681 40-299	0 P	8306030 <u>22</u> 8306030 <u>23</u> 8306030 <u>23</u> 8306030 <u>22</u> 8306030 <u>22</u>	8304030320 8304030320 8304030320 8304030320	83/05/26 83/05/20 83/05/20 83/05/26	50-302 50-302 70-371 50-302 50-302	I I I
8304020328 8304020329 8304020334 8304020334 8304020376	9304020324 9304020327 9304020331 9304020333 9304020375	83/05/11 83/05/26 83/04/29 83/05/26 83/05/20	40-8681 CONTRACT 40-8586 CONTRACT 50-354	G	8306030328 8306030334 8306030335 8306030345	8304030320 8304030333 8306030333 8306030338 8304030343	63/05/26 63/06/01 63/06/01 83/04/21 63/05/23	50-302 50-529 50-529 TOPREP 50-286	I G G
8306020379 8306020389 8306020391 8306020392 8306020403	8304020378 8304020381 8304020387 8304020387	83/05/26 83/05/20 83/05/20 83/05/20 83/05/20	50-277 50-244 70-698 70-698 50-244	P Q Q	8306030351 8306030359 8306030363 8306030370 8306030371	8306030349 8306030355 8306030355 8306030366 8306030369	83/05/31 83/04/01 83/04/01 83/04/01	50-272 50-443 50-443 FOIA COMMISBI	9 9 9
8304020404 8304020405 8304020407 8304020413 8304020415	8306020402 8306020379 8306020402 8306020409 8306020408	83/05/20 83/05/31 83/05/20 83/05/18 83/05/31	50-317 70-2548 50-317 50-293 70-1224	G G	8306030375 8306030388 8306030395 8306030395 8306030402	8304030349 8304030383 8304030383 8304030383 8304030400	83/05/11 83/04/01 83/04/01 83/04/01 83/05/27	COMMISBI FOIA FOIA FOIA CONTRACI	
8306020416 8306020434 8306020444 8306020447 8306020448	8304020409 8304020427 8304020442 8304020445 8304020443	03/05/18 03/05/20 03/05/20 03/05/20 03/05/31	50-293 50-244 50-387 50-219 50-247	G G G	8306030446 8306030455 8306030472 8306030472 8306030500	8306030441 8306030454 8306030474 8306030489 8306030498	83/05/14 83/04/19 83/05/12 83/05/12 83/05/19	50-280 FOIA XPORTLIG 71-9165 50-320	P
8306020452 8306020460 8306020463 8306020462 8306020498	6304020443 6304020458 6304020459 8304020450 6304210443	83/05/31 83/05/20 83/05/16 83/05/20 83/06/07	50-247 50-244 Contract Contract Nureg	e e	8304030512 8304040004 8304040005 8304040006 8304040007	8307070003 8307070003 8307070003 8307030208	83/03/21 83/03/21 83/03/21 83/03/21	50-295 FOIA FOIA FOIA FOIA	P
8306020309 8306020311 8306020313 830602033 8306020340	8304020503 8304020505 8304020504 8304020528 8304020528	83/04/04 83/05/25 83/05/20 83/05/13 83/05/13	40-1341 50-309 CONTRACT 71-9060 71-9080	P	830404009 8304040012 8304040015 830404015 830404016	830404003 83040408 110040468 83040408 83040408	83/03/21 83/03/21 83/04/19 83/03/21 83/04/15	FOIA FOIA FDIA FOIA 50-354	Q.
8304020572 8304020574 8304020583 8304020587 8304020592	8304020340 8304020548 8304020548 8304020548	83/05/19 83/05/19 83/05/19 83/05/19 83/05/13	50-278 50-298 50-298 50-298 71-9080	P 0 0	8306060017 8306060018 8306060019 8306060020 8306060021	E000A0A0B E0040A0A0B E000A0A0BB E000A0A0BB	83/03/21 83/04/15 83/03/21 83/03/21 83/04/15	FOIA 50-354 FOIA FOIA 50-354	Q Q
8306020646 8306020659 8306020696 8306030016 8306030027	8304030022 8304030012 8304030012	93/05/17 93/05/19 93/05/20 93/05/18 93/05/25	70-2985 XPORTLIC TOPREP 50-336 71-6142	P	8304040022 8304040023 8304040024 8304040024 8304040024	\$20000003 \$10000008 \$00000008 \$00000008 \$00000008	83/03/21 83/04/15 83/03/21 83/03/21 83/03/21	FOIA 50-354 FOIA FOIA FOIA	Q
8304030054 8304030057 8304030040 8304030070 8304030078	8304030048 8304030053 8304030051 8304030047 8304030073	83/05/17 83/05/05 83/05/06 83/05/17 83/05/13	CONTRACT 71-9086 XPORTLIC 50-338 50-313	P F	830606027 830606038 830606033 830606031 830606033	8304040013 630404003 830404003 830404003 830404003	83/04/15 83/03/21 83/03/21 83/03/21 83/03/21	FOIA FOIA FOIA FOIA FOIA	
8304030088 8304030090 8304030130 8304030134 8304030143	8304030020 8304030087 8304030119 8304030119 8304030139	83/05/24 83/05/25 83/05/19 83/05/19 83/05/17	50-397 71-6003 50-293 50-293 50-254	A G G	8304040035 8304040038 8304040041 8304040043 8304040047	8304040003 8304040003 8304040003 8304040037 8304040044	83/03/21 83/03/21 83/03/21 83/05/31 83/05/31	FOIA FOIA FOIA 50-546 50-255	A P

ACCESSION	NUMBER				ACCESS10				
ENCLOSURE	PRINCIPAL DOCUMENT	DATE 188UED	SUBJECT CATEGORY	Υ	ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGOR	
8304040053 8304040055 8304040058 8304040057 8304040040	8306060003 8306060048 8306060051 8306060057 8306060056	83/03/21 83/05/31 83/04/07 83/05/27 83/05/18	FOIA 50-329 50-416 50-244 50-498	G A B G	6306040375 8306060374 8306060376 8306060402 8306070007	8304040391 8304040393 8304040391 8304040400	83/04/28 83/04/05 83/04/28 83/04/06 83/05/24	CONTRACT FOIA CONTRACT FOIA 50-528	
B304040061 B304040066 B304040067 B304040073 B304040074	8306040051 8306040051 8306040063 8306040069 8306060071	83/04/07 83/04/07 83/05/31 83/05/17 83/05/31	50-245 FOIA 50-313 50-458 50-358	P G G A	8304070011 8304070017 8304070021 8304070024 8304070027	8306070009 8306070015 8306070019 8306070025	83/05/20 83/05/23 83/04/05 83/05/03 83/05/03	50-344 50-344 50-206 FOIA FOIA	0 0 P
8304040076 8304040080 8304040085 6304040101	8304040051 8304040051 8304040051 8304040099 8304040104	83/04/07 83/04/07 83/04/07 83/06/01 83/03/29	50-249 50-287 50-249 50-358 FOIA	Р Р Е	8305070028 8305070042 8305070092 8305070061 8305070063	8306070019 8306070033 8306070046 8306070050 8306070062	83/04/05 83/06/01 83/05/24 83/06/01 83/05/31	50-204 50-358 50-284 50-250 50-255	P G G Q
8304040114 8304040118 8304040120 8304040122	8304040105 8304060111 8304040114 8304040117	83/05/27 83/05/18 83/05/36 83/05/36 83/05/18	50-317 50-498 70-1151 50-382 50-498	P G I G	8305070065 8306070083 8306070096 8306070096 8306070106	8304070057 8304070075 8304070082 8304070093 8304070103	83/05/12 83/05/11 83/06/03 83/05/11 83/05/19	50-312 50-344 50-341 50-275 50-267	0 0 0 P
8306060124 8306060126 8306060131 8306060132 8306060133	8306060114 8306060125 8306060128 8306060129	83/04/04 83/05/20 83/05/17 83/05/23 83/05/17	70-1151 50-247 50-112 50-358 50-112	G G G	8305070107 8306070109 8306070110 8306070111 8306070114	8304070104 8304070108 8304070108 8304070105 8304070105	83/05/24 83/06/02 83/06/02 83/05/24 83/05/24	50-529 GA999 GA999 50-447 50-447	B K K
8304040138 8304040149 8304040158 8304040145 8304040146	8306060129 8306060145 8306060157 8306060160 8306060162	83/05/23 83/05/27 83/05/27 83/05/23 83/05/23	50-358 50-255 50-277 50-245 50-277	0 P F G	8306070127 8336070130 8306070134 8306070144 8306070145	8304070123 8304070123 8304070131 8304070139 8304070137	83/06/02 83/06/02 83/06/02 83/06/01 83/06/01	50-321 50-321 50-349 50-544 50-483	1 P 0 0
8306060169 8306060170 8306060171 8306060172 8306060173	8306060167 8306060162 8306060160 8306060167 8306060163	83/05/23 83/05/23 83/05/23 83/05/23	40-672 50-277 50-245 40-672 70~344	G G	830407014 <i>6</i> 8304070147 8304070157 8394070159 8304070143	8306070140 8306070139 8306070152 8306070156 8306070158	83/05/24 83/06/01 83/05/17 83/05/25 83/06/02	50-317 50-546 50-312 50-317 GA999	0 0 0
8304040176 8304040177 8304040179 8304040185 8304040184	8306060163 8306060167 8306060167 8306060183 8306060183	83/05/23 83/05/23 83/05/23 83/05/27	70-344 40-672 40-672 50-315 50-315	8	830607014 <i>6</i> 8306070170 8306070171 8306070171 830607017 <i>6</i>	8304070155 8304070147 8304070148 8304070147 8304070152	83/05/01 83/05/01 83/05/02 83/05/01 83/05/17	50~346 50-273 0A999 50~293 50-312	Q P Q
8306060188 8306060172 8306060174 8306060175 8306060176	8306060189 8306060191 8306060191 8306060191	83/05/31 83/05/27 83/05/31 83/05/31 83/05/31	50~322 50~329 50~402 50~462 50~454	Q K F Q	8306070189 8306070190 8306070197 8306070211	8304070184 8304070175 8304070185 8304070204 8304070207	83/06/02 83/06/03 83/06/01 83/05/27 83/06/03	M18C 50-254 50-286 50-413 50-344	Q P E P
8304040204 8304060211 8304040212 8304040214 8304040215	8307070510 8307070500 8307070508 8307070502 8307070500	63/05/29 63/65/29 63/65/29 63/65/29 63/65/29	50-334 50-423 50-254 50-334 50-322	() () () ()	8306070213 8306070219 8306070226 8306070243 8306070244	8304070207 8304070215 8304070223 8304070238 8304070240	83/06/03 83/06/01 83/05/24 83/05/27 83/05/13	50-344 50-289 50-277 50-281 50-206	P R O S
8306060216 8306060217 8306060220 8306060221 8306060224	8304040218 8304040218 8304040217 8304040218 8304040223	83/05/30 83/05/19 83/05/19 83/05/19 83/05/23	50-128 50-295 50-219 50-295 50-220	Р О О	8306070245 8306070250 8306070233 8306070259 8306070256	\$305070238 \$305070247 \$305070252 \$305070251 \$305070252	83/05/27 83/06/03 83/05/25 83/05/16 83/05/25	50-281 50-255 50-528 50-204 50-528	B G G
8304040225 8304040227 8304040234 8304040237 8304040242	8306060117 8306060223 8306060230 8306060230	83/05/30 83/05/23 83/05/23 83/05/23	50-382 50-220 50-333 50-333	1 0 0 0 0	8306070261 8306070275 8306070277 8306070278 8306070280	8306070251 8306070270 8306070271 8306070270 8306070272	83/05/16 83/05/27 83/06/02 83/05/27 83/05/31	50-206 50-275 50-209 50-275 50-289	6 6 0
8304040244 8304040248 8304040251 8304040258 8304040242	8306060241 8306060246 8306060247 8306060257 8306060260	83/05/20 83/04/27 83/05/19 83/05/23 83/05/23	50-403 PRM 50-263 50-309 50-320	0 0 0	8306070286 8306070287 8306070294 8306070297 8306070299	8306070272 8306070285 8306070288 8306070292 8306070295	83/05/31 83/05/20 83/05/27 83/05/27	50-249 50-243 94999 50-275 50-352	P G R O
8306060266 8306060267 8306060268 8306060271 8306060272	B306060260 B306060264 B306060265 B306060267 B306060270	83/05/23 83/05/23 83/05/25 83/05/27 83/06/01	50-320 50-206 50-322 50-316 50-156	0 0 8 0	8306070301 8306070306 8306070308 8306070312 8306070336	8304070295 8304070304 8304070305 8304070305 8304070331	83/06/03 83/06/04 83/06/02 83/06/02 83/06/02	50-352 50-445 0A999 0A999 0A999	0.0
8304040273 8304040273 8304040307 8304040327 8304040352	8304040247 8304040289 8304040307 8304280138 8304040349	83/05/27 83/05/26 83/06/03 83/06/14 83/05/19	50-316 50-412 70-25 50-277 50-322	9 0 P A	8306070339 8306070346 8306070353 8306070353 8306070357	8304070393 8304070344 8304070349 8304070344 8304070351	83/05/13 83/05/24 83/05/31 83/05/24 83/05/31	50-206 50-271 50-413 50-271 50-321	0 0 0 P
8304040359 8304040347 8304040374 8304040380 8304040392	8306060349 8306060369 8306060369 8306060369	83/05/19 83/05/14 83/05/14 83/05/14 83/05/14	50-322 40-2041 CDMMISBI CDMMISBI 50-272		8306070368 8306070369 8306070374 8306070375 8306070376	8304070361 8304070340 8304070363 8304070372 8304070343	83/05/13 83/05/03 83/05/30 83/05/30 83/06/02	50-361 50-275 50-277 50-185 50-277	0 0 P 0 P

ACCESS10)	NUMBER				ACCESSIO	N NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGOR	ŀΥ	ENCLOSURE	PRINCIPAL DOCUMENT	DATE IBBUED	SUBJECT CATEGORY	Υ
8306070378 8306070379 8306070383 8306070384 8306070385	8394070344 8394070343 8394070343 8394070380 8394070364	83/05/09 83/06/02 83/06/02 83/06/02 83/05/09	50-312 50-277 50-277 50-313 50-312	0 P 0	8306080267 8306080267 8306080270 8306080274 8306080274	8306080257 8306080257 8306080268 8306080273 8306080273	83/04/06 83/04/06 83/04/11 83/06/06 83/06/06	FOIA 50-443 FOIA 50-410 50-410	G A A
8306070384 8306070387 8306070371 8306070372 8306070374	8304070381 8304070343 8304070343 8304070388 8304070382	83/06/03 83/06/02 83/06/02 83/06/01 83/06/04	50-322 50-277 50-277 50-454 50-445	С Р О	8306080278 8306080302 8306080303 8306080304 8304080304	8304080273 8304080297 8304080273 8304080277 8304080273	83/04/06 83/04/06 83/04/06 83/04/12 83/06/06	50-410 40-2061 50-410 50-478 50-410	A Q A
8304070395 8306070398 8306070401 8306070403 8306070407	9306070363 9306070363 9306070396 9306070363 9306070271	83/06/02 83/06/02 83/06/02 83/06/02	50-277 50-277 50-461 50-277 50-289	Р К Р	6304080308 6304080312 6304080312 6304080314 6304080328	8306080277 8306080277 8306080273 8306080313 8306080273	83/04/12 83/04/12 83/06/06 83/04/06 83/06/06	50-498 50-478 50-410 50-148 50-410	G A P A
8306070431 8306070434 8306070442 8306070446 8306070447	8306070428 8306070428 8306070435 8306070444 8306070444	83/05/27 83/05/27 83/06/02 83/05/31 83/05/31	50-370 50-370 40-2061 50-461 50-461	P E E	8306080334 8306080336 8306080339 8306080339 8306080340	8306080326 8306080326 8306080273 8306080326 8306080326	83/05/03 83/05/03 83/05/04 83/05/03 83/05/03	71-9017 71-9017 50-410 71-9017 71-9017	٨
8306070451 8306070455 8306070458 8306070465 8306070468	8306070444 8306070453 8306070453 8306070464 8306070466	83/05/31 83/05/16 83/05/16 83/05/18 83/05/25	50~461 71-9182 71-9182 CONTRACT MISC	E	8306080342 8306080349 8306080348 8306080351 8306080358	8306080326 8306080273 8306080341 8306080273 8306080341	83/05/12 83/06/06 83/05/12 83/05/03	71-90J7 50-410 71-4909 50-410 71-4909	A
8306070470 8306080004 8306080007 8306080023 8306080041	8304070447 8304080003 8304080004 8304080021 8304080031	83/03/28 83/06/03 83/05/11 83/04/29 83/03/25	40-299 50-250 50-390 70-1151 FOIA	a A	8306080360 8306080376 8306080411 8306080417 8306080427	8306080273 8306080393 8306080408 8306080413 8306080419	83/05/06 83/05/31 83/06/03 83/06/01 83/05/24	50-410 70-2838 71-9016 CONTRACT CONTRACT	A
9304080046 9304080048 9304080054 9304080057 9304080072	8304080042 8304080044 8304080052 8304080053 8304080067	83/03/21 83/05/31 83/06/01 83/06/06 83/06/02	50-267 50-440 70-2910 50-443 CONTRACT	Q A	8306090442 8306090006 8306090017 8306090021	8306080439 8306070001 8306070004 8306070014 8306070018	83/05/18 83/05/31 83/05/31 83/05/31 83/06/06	50-322 71-9111 71-6601 71-5026 50-387	T F
8304080074 8304080079 8304080083 8304080107 8304080124	8304080049 8304080080 8304080101 8304080101	83/04/04 83/04/20 83/05/31 83/03/01 83/03/01	50~382 50~382 50~324 ADVCM 40~8722	Q Q P	8304090024 8304090027 8304090031 8304090032 8304090035	8304070018 8304070024 8304070024 8304070027 8304070028	83/06/06 83/06/06 83/06/06 83/06/01 83/04/28	50-387 50-219 50-219 50-205 40-8786	F F F
9304090127 9304090127 9304090133 9304090134 9304090140	8304080123 8304080109 8304080128 8304080109 8304080137	83/05/27 83/04/13 83/04/04 83/04/13 83/06/02	50-312 50-285 50-498 50-285 50-358	F G G E	8306090036 8306090037 8306090044 8306090060 8306090069	8304090030 8304090034 8304090041 8304090057 8304090047	83/05/25 83/05/27 83/05/26 83/06/01 83/05/27	71-2 71-9010 50-219 50-344 50-322	0 F 0
8306080145 8306080153 8306080155 8306080156 8306080159	8304080143 8304080148 8304080150 8304080152 8304080150	83/05/31 83/05/26 83/06/02 83/04/06 83/06/02	50-454 WASTE MG 50-498 40-8027 50-498	e 9 0	8306090074 8306090076 8306090131 8306090132 8306090132	8304070070 8304070067 8304070128 8304070129 8304070127	83/05/31 83/05/27 83/05/27 83/03/07 83/03/07	71-6244 50-322 50-322 40-8698 40-8698	G G
8304080145 8304080177 8304080178 8304080182 8304080188	8306080152 8306080171 8306080175 8306080171 8306080184	83/04/04 83/06/03 83/06/06 83/06/03 83/06/06	40-8027 50-322 50-482 50-322 50-482	e A O Q	8304070143 8306070151 8306070164 8306070147 8306070175	8304070140 8304070140 8304070154 8304070143 8304070163	83/05/26 83/05/26 93/06/07 83/02/02 83/02/02	50-352 50-352 50-361 40-8084 40-8084	G G P
8306080190 8306080193 8306080197 8306080201 8306080205	8306080181 8306080181 8306080199 8306080203	83/03/07 83/03/07 83/03/04 83/06/03 83/06/06	40-8481 40-8481 50-313 50-275 50-358	œ P	8306090179 8306090183 8306090193 8306090203 8306090208	8304090172 8304090177 8304090190 8304090201 8304090204	93/04/15 93/06/06 93/05/25 93/06/01 93/06/01	40-8663 50-266 50-334 50-255 50-348	G P F F
8304080210 8304080211 8304080214 8304080217 8304080221	8304080209 8304080109 8304080214 8304080217 8304080220	83/06/03 83/04/13 83/06/06 83/05/19 83/04/14	50-204 50-265 50-361 50-298 50-445	P Q Q Q	8306090223 8306090228 8306090228 8306090239 8306090241	8304090221 8304090219 8304090224 8304090237 8304090238	83/06/02 83/06/02 83/05/18 83/05/31 83/05/27	50-454 50-277 40-8452 50-282 50-245	F P G
8306080222 8306080224 8306080227 8306080228 8306080235	8304080232 8304080218 8304080218 8304080218	83/06/06 83/06/06 83/06/06 82/11/22 83/06/02	50-445 50-445 50-445 50-338 50-155	00000	8306090244 8306090245 8306090257 8306090257 8306090261	8306070243 8306070243 8306070254 8306070255 8306070254	83/05/27 83/05/27 83/06/01 83/06/01 83/06/01	50-329 50-329 50-292 70-2910 50-282	0 9 F
8304080234 8304080237 8304080238 8304080241 8304080243	8304080231 8304080234 8304080172 8304080237 8304080237	83/03/29 83/05/31 83/03/04 83/04/04 83/06/06	50-285 50-346 50-313 50-445 50-445	а Р а е	83060 70249 83060 70271 83060 7027 83060 70274 83060 70275	9306090265 9306090268 9306090267 9306090265 9306090273	83/05/31 83/06/01 83/06/08 83/05/31 83/06/03	70-2926 50-289 50-245 70-2926 50-528	F P
8306080248 8306080252 8306080263 8306080264 8306080266	8304080239 8304080231 8304080239 8304080239 8304080239	83/06/04 83/05/24 83/04/06 83/04/06 83/04/06	50-445 50-335 50-443 50-443	0 P Q Q	8306090276 8306090279 8306090280 8306090283 8306090283	8304090273 8304090278 8304090277 8304090281 8304090282	83/06/03 83/06/03 83/05/09 83/06/01 83/06/02	50-528 71-9015 CONTRACT 50-346 CONTRACT	F

ACCESSION						CESSION				
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	<u> </u>	ENCLO	BURE	PRINCIPAL DOCUMENT	DATE	SUBJECT CATEGOR	
8304070287 8304070271 8304070304 8304070307 8304070315	8306070285 8306070287 8306070302 8306070302 8306070312	83/06/01 83/06/01 83/06/03 83/06/03	50-255 50-27 50-286 50-286 50-445	F P P V	140EB 140EB 140EB 140EB	130230 130238 130261 130263	9304130224 9304130233 9304130255 9304130258 9304130258	83/04/07 83/04/29 83/05/25 83/06/01 83/06/01	50-249 REVIEH G 50-445 50-315	P RP G G
8306090324 8306090326 8306090332 8306090354 8306090355	8306090319 8306090316 8306090329 8306090349 8306090352	83/03/23 83/06/03 83/06/06 83/06/13 83/06/03	50-348 50-331 50-348 50-285 50-250	0 0 0 0 P	14068 14068 14068	130292 130305 130314 130319 130328	8304130285 8304130279 6304130311 8304130378 8304130324	83/04/10 83/04/08 83/04/10 83/04/10	50-341 50-440 50-409 50-346 50-322	0 0 0
8306090360 8306090366 8306090375 8306090379 8306090380	8304090358 8304090358 8304090370 8304090374 8304090377	83/05/26 83/05/26 83/06/06 83/04/13 83/05/31	50-271 50-271 50-346 FOIA 50-309	a F P	14068 14068 14068	130331 130332 130333 130335 130343	830 & 130 32 & 830 & 130 32 & 830 & 130 330 830 & 130 341 830 & 130 341	83/06/06 83/06/06 83/03/27 83/06/07 83/03/31	50-322 50-322 50-305 50-255 50-454	E G F Q
8306090388 8306090394 8306090397 8306090411 8306090416	8304090384 8304090391 8304090393 8304090404 8304090404	83/05/26 83/06/01 83/05/31 83/06/06 83/06/06	50-278 50-241 50-312 50-382 50-382	4 4 4 4	8306) 8306) 8306)	130345 130358 130372 130377 130378	8304130341 8304130354 8304130368 8304130371 8304130375	83/05/31 83/04/09 83/04/02 83/04/09 83/04/08	50-454 50-245 50-329 50-142 50-331	Q P A T 8
8304090432 8304090452 8304090470 8304090488 8304090492	8304090430 8304090447 8304090467 8304090484 8304090424	83/05/27 83/05/27 83/05/25 83/05/25 83/05/27	50-220 CONTRACT CONTRACT CONTRACT 50-317	P	14068 14068 14068	130379 130391 130392 130395 130402	8304130371 8304130387 8304130384 8304130390 8304130397	83/06/09 83/06/09 83/06/10 83/05/23	50-142 50-322 50-204 50-289 0A999	7 Q P Q
83061 0001 4 83061 00032 83061 00036 83061 00039	830410009 830410009 830410009 830410009	83/04/11 83/04/11 83/04/11 83/04/11 83/04/11	50-275 50-312 50-206 50-312 50-312	0 0 0 0	8306) 8306) 8306)	130407 130410 130412 130416 130418	8304130403 8304130397 8304130405 8304130413 8304130414	83/05/27 83/05/23 83/05/27 83/05/23 83/06/10	50-537 0A999 50-254 0A999 50-322	A G
8306100040 8306100044 8306100047 8306100078 8306100073	8306100009 8306100009 8306100075 8306100088	83/04/11 83/04/11 83/04/11 83/05/09 83/05/06	50-312 50-312 50-312 50-527 50-155	0 0 0 0	8304: 8304: 8304:	1 30422 1 30441 1 30442 1 30452 1 30457	8306130413 8306130435 8306130429 8306130445 8306130454	83/05/23 83/06/06 83/06/06 83/06/07 83/06/07	9A999 50-250 50-348 50-454 50-10	F P O R
8306100105 8306100106 8306100131 8306100134 8306100135	8306100101 8306100138 8306100130 8306100138	83/05/27 83/06/06 83/06/09 83/05/31 83/06/09	50~237 50~285 50~237 50~275 50~237	0 P P R P	8306 8306 8306	1 30440 1 30500 1 40033 1 40038 1 40043	8306130454 8306130493 8306140023 8306140023 8306140059	83/06/07 83/02/28 83/06/06 83/06/06 83/06/07	50-10 70-1257 50-335 50-335 50-272	我 ド ド
8306100136 8306100144 8306100148 8306100152 8306100156	B306100132 B306100140 B306100147 B306100147 B306100149	83/06/08 60/40/68 60/40/68 60/40/68	50-366 50-389 50-483 50-483 50-237	P P A Q	4306 4306 4306	140115 140125 140131 140134 140139	8306140111 8306140114 8306140114 8306140114 8306140114	83/05/24 83/05/27 83/05/27 83/05/27 83/05/27	50-389 50-438 50-438 50-438 50-438	P 0 0 0
8306100167 8306100169 8306100171 8306100174 8306100175	8306100165 8306100162 8306100168 8306100172 8306100172	83/05/25 83/05/23 83/06/02 83/05/24 83/05/24	50-483 50-483 50-276 50-373 50-373	0 R 0	8304 8304 8304	1 40142 1 40145 1 40149 1 40150 1 40153	8306140137 8306140137 8306140137 8306140143 8306140147	83/05/24 83/05/24 83/05/24 83/05/31	50-327 50-327 50-327 50-438 50-333	G G G
8304100181 8304100193 8304100199 8304100205 8304100212	8306100179 8306100191 8306100197 8306100204 8306100210	83/08/18 83/06/07 83/06/08 83/06/07 83/05/20	50-295 50-309 50-413 50-309 50-341	R G G	8304 8304 8304	1 40157 1 40162 1 40164 1 40169 1 40172	B306140143 B306140137 B306140143 B30614015B B306140143	83/05/26 83/05/26 83/05/26 83/05/26	50-438 50-327 50-438 50-333 50-438	Q Q Q
8306100220 8306100227 8306100229 8306100230 8306100242	8306100217 8306100226 8306100226 8306100223 8306100240	83/05/25 83/06/06 83/05/26 83/06/06 83/06/08	50-151 50-445 50-155 50-445 50-322	0 0 0 0	830& 830& 830&	i 40180 i 4019i i 40196 i 40197 i 4020i	8306140174 8306140186 8306140190 8306140188 8306140194	83/05/16 83/05/16 83/05/19 83/05/11 83/05/25	50-389 50-389 50-335 50-407 50-324	0 0 0
8306100247 8306100249 8306100250 8306100255 8306100256	8306100244 8306100244 8306100245 8306100252 8306100253	83/05/24 83/05/24 83/06/06 83/05/R0 83/06/06	50-454 50-454 50-373 50-373 50-286	9 9 9 9	9306 8306 8306	1 40212 1 40220 1 40222 1 40223 1 40227	B304140207 B304140207 B304140208 B304140217 B304140217	83/05/20 83/05/20 83/06/03 83/06/06 83/06/06	50-482 50-482 50-338 50-155 50-155	0 0 F F
83061 00258 83061 00265 83061 00266 83061 00267 83061 00269	8304100252 8304100244 8304100263 8304100264 8304100268	83/05/20 83/06/10 83/05/27 83/06/10 83/06/03	50-373 50-424 50-374 50-424 50-329	0 A Q A	40EB 40EB 40EB	1 40232 1 40234 1 40236 1 40238 1 40240	830&14022& 830&140230 830&14022& 830&140228 830&140230	83/05/11 83/06/10 83/05/11 83/05/18 83/06/10	50-72 50-482 50-72 CONTRACT 50-482	Q A Q
8306100272 8306100273 8306100311 8306130129 8306130130	8306100268 8306100271 8306100237 8306130118 8306130117	83/06/03 83/06/07 83/06/08 83/05/25 83/06/06	50-329 50-315 50-289 50-362 50-265	Л В Н О	8306 8306 8306	1 40244 1 40246 1 40247 1 40253 1 40254	8306140235 8306140237 8306140245 8306140248 8306140237	83/05/17 83/05/06 83/05/13 83/05/06 83/05/06	50-416 50-321 50-492 50-97 50-321	01 61 61 F
8304130185 8304130198 8304130212 8304130214 8304130224	8306130177 8306130177 8306130177 8306130174 8306130174	83/06/03 83/06/03 83/05/23 83/05/23	71-9089 71-9089 71-9089 9A999 9A999		8306 8306 8306	1 40261 1 40262 1 40266 1 40273 1 40276	8306140256 8306140258 8306140251 8306140265 8306140251	83/05/31 83/06/09 83/06/02 83/06/02	50-272 50-277 50-259 50-309 50-259	9 9 6 7

ACCE8810)	NUMBER			ACCES610				
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY	ENCLOSURE	PRINCIPAL DOCUMENT	DATE 188UED	SUBJECT CATEGOR	
83051 40264 83051 40297 83051 40310 83051 40323 83051 40327	8306140251 8306140251 8306140302 8306140316 8306140329	83/04/02 83/04/02 83/04/23 83/05/23 83/06/07	50-259 0 50-259 0 50-335 0 50-322 I	83061 40546 83061 40548 83061 40549 83061 40552 83061 40555	8306140524 8306140524 8306140547 8306140524 8306140524	83/06/07 83/06/07 83/05/16 83/06/07	50-329 50-329 50-324 50-329 50-329	A G A
8306140338 8306140342 8306140348 8306140349 8306140350	8306140317 8306140317 8306140317 8306140343 8306140345	83/05/26 83/05/26 83/05/26 83/05/17 83/05/24	70-1113 70-1113 70-1113 50-335 50-329	83061 40557 83061 40558 83061 40560 83061 40564 83061 40566	B306140524 B306140534 B306140524 B306140554 B306140524	83/06/07 83/06/02 83/06/07 83/06/02 83/06/07	50-329 50-410 50-329 50-410 50-329	A G A G A
83041 40357 83041 40358 83041 40341 83041 40342 83041 40343	8306140317 8306140332 8306140352 8306140355 8306140359	83/05/26 83/05/31 83/05/13 83/05/13	70-1113 50-322 50-336 50-390 50-313	83061 40567 83061 40569 83061 40571 83061 40573 83061 40574	8304140559 8304140559 8304140559 8306140524 8306140559	83/06/07 83/06/07 83/06/07 83/06/07 83/06/07	50-416 50-416 50-416 50-329 50-416	0 0 A 0
6305140357 8305140374 8305140375 8305140368 8305140370	8306140356 8306140370 8306140369 8306140382 8306140386	83/04/11 83/05/27 83/05/24 83/05/01 83/05/17	40-849B 50-445 50-400 50-375 50-327	83061 40575 83061 40579 83061 40580 83061 40582 83061 40583	8306140568 8306140524 8306140562 8306140576 8306140559	83/04/02 83/06/07 83/05/20 83/06/01 83/06/07	70-1113 50-329 50-390 70-1113 50-416	A Q Q
83061 40391 83061 40398 83061 40400 83061 40404	8306140381 8306140381 8306140397 8306140396	83/05/05 83/05/06 83/05/17 83/05/24 83/05/24	50-277 (50-277 (50-280 (50-324 (50-324 (83061 40587 83061 40592 83061 40597 83061 40605 83061 40615	8304140524 8304140524 8304140524 8304140524 8304140607	83/06/07 83/06/07 83/06/07 83/06/07 83/06/08	50-329 50-329 50-329 50-329 50-322	A A A G
83061 40420 83061 40423 83061 40424 83061 40425 83061 40426	8306140419 8306140396 8306220074 8306140415 8306140421	83/05/27 83/05/24 83/06/21 83/05/27 83/06/03	50-390 (50-324 (50-219 50-390 (CONTRACT	83061 40616 83061 40617 83061 40627 83061 40636 83061 40643	8306140613 8306140609 8306140621 8306140631	83/06/07 83/05/18 83/03/25 83/05/27 83/05/31	50-293 70-824 50-280 50-382 50-334	Р О О Р
83061 40428 83061 40434 83061 40438 83061 40439 83061 40445	8306140415 8306140415 8306140433 8306140432 8306140441	83/05/27 83/05/27 83/06/03 83/05/19 83/05/31	50-370 (50-370 (CONTRACT 50-424 (50-410 (83061 40647 83061 40652 83061 40655 83061 40662 83061 40663	8306140608 8306140641 8306140645 8306140657 8306140658	83/05/17 83/05/17 83/05/26 83/06/09 83/06/08	50-338 50-338 50-348 50-293 50-412	0 0 0
93061 40446 93061 40451 93061 40454 93061 40455 93061 40457	9306140442 9306140447 8306140450 8306140447 8306140452	83/04/04 83/05/27 83/04/07 83/05/27 83/05/25	40-8794 50-302 50-416 50-302 50-395	8306140667 8306140671 8306140672 8306140675 8306140682	8306140658 8306140664 8306140658 8306140668 8306140677	83/05/24 83/05/24 83/06/08 83/04/08 83/06/07	50-412 50-413 50-412 MISC 50-324	0 0 0
83061 40461 83061 40462 83061 40463 83061 40465 83061 40468	8306140452 8306140447 8306140450 8306140452 8306140450	83/03/25 83/05/27 83/06/07 83/05/25 83/06/07	50-375 50-302 50-416 50-375 50-416	83061 40686 83061 40688 83061 40692 83061 40693 83061 40699	8306140680 8306140677 8306140685 8306140677 8306140677	83/06/09 83/06/07 83/05/25 83/06/07 83/06/07	50-370 50-324 50-259 50-324 50-324	0 0 0
83061 40469 83061 40471 83061 40474 83061 40477 83061 40490	9306140447 9306140452 9306140450 9306140473 9306140483	83/05/27 83/05/25 83/06/07 83/05/16 83/06/02	50-302 50-375 50-416 50~348 50-400	83061 40705 83061 40708 83061 40713 83061 40718 83061 40719	8306140677 8306140698 8306140700 8306140712 8306140711	83/04/07 83/03/31 83/06/02 83/06/01 83/06/01	50-324 50-261 70-143 PR 50-321	Q G
8306140492 8306140493 8306140495 8306140498 8306140499	8306140487 8306140486 8306140483 8306140494 8306140483	83/05/24 83/05/24 83/06/02 83/06/03 83/06/02	50-375 50-321 50-400 50-322 50-400	83061 40729 83061 40730 83061 40734 83061 40737 83061 40740	8306140724 8306140711 8306140726 8306140732 8306140726	83/06/09 83/06/01 83/03/03 83/06/09 83/03/03	50-416 50-321 ADVCM 50-289 ADVCM	P G F
8306140502 8306140503 8306140505 8306140506 8306140507	8306140497 8306140483 8306140501 8306140497 8306140483	83/05/27 83/05/02 83/05/18 83/05/27 83/06/02	50-413 (50-400 (COMMIBSIO 50-413 (50-400 (83061 40745 83061 40746 83061 40750 83061 40752 83061 40831	8306140711 8306140738 8306140744 8306140738 8306140828	83/06/01 83/06/06 83/06/03 83/06/06 83/06/01	50-321 50-249 71-4553 50-249 50-255	Q P P F
8306140508 8306140510 8306140511 8306140512 6306140513	8305140497 8305140504 8305140497 8305140483 8305140509	83/05/27 83/05/25 83/05/27 83/06/02 83/02/28	50-413 50-389 50-413 50-400 ADVCM	83061 50008 83061 50014 83061 50030 83061 50034 83061 50041	8306150005 8306150013 8306150025 8306150032 8306150037	83/06/02 83/06/13 83/06/07 83/06/07 83/06/07	50-289 50-244 50-289 50-313 50-321	0 F F F
8304140514 8304140516 8304140517 8304140520 8304140521	9306140504 9306140504 9306140509 9306140504 9306140509	83/05/25 83/05/25 83/02/28 83/03/25 83/02/28	50-389 50-389 ADVCM 50-389 ADVCM	83061 50044 83061 50086 83061 50094 83061 50098 83061 50102	8304150037 8304150082 8304150071 8304150071 8304150101	93/06/07 93/06/01 93/06/06 93/06/06 93/06/06	50-321 50-317 50-327 50-327 50-445	4444
83061 40522 83061 40529 83061 40532 83061 40534 83061 40537	9306140515 9306140527 9306140524 9306140524 8306140530	83/05/25 83/05/25 83/06/07 83/06/07 83/05/17	50-321 70-1201 50-329 50-329 50-369	83061 50124 83061 50137 83061 50141 83061 50150 83061 50163	8306150121 8306150133 8306150133 8306150149 8306150156	83/05/31 83/06/01 83/06/01 83/05/19 83/06/08	TOPREP 50-321 50-321 50-412 70-2669	F A
83041 40539 83041 40540 83041 40541 83041 40542 83041 40544	8306140524 8306140524 8306140538 8306140535 8306140524	83/06/07 83/06/07 83/05/18 83/05/23 83/06/07	50-329 50-329 50-335 50-327 50-329	9306150166 9306150169 9306150172 9306150179 9306150195	8306150156 8306150156 8306150167 8306150174 8306150174	83/06/08 83/06/13 83/06/13 83/06/13	70-2669 70-2669 PROJ 50-289 50-289	H

		ACCESB10	N NUMBER			
PRINCIPAL DATE ENCLOSURE DOCUMENT ISSUED	SUBJECT CATEGORY	ENCLOSURE	PRINCIPAL BOCUMENT	DATE ISSUED	SUBJECT CATEODS	
8306150214 8306150211 83/05/26 8306150222 8306150218 83/06/16 8306150232 8306150228 83/06/05 8306150240 8306150239 83/06/05 8306150247 8306150237 83/06/05) 50-155 @ } 50-366 P } 71-9017	8306160125 8306160131 8306160132 8306160132 8306160137	830616093 830616093 8306160110 830616093 8306160130	83/04/01 83/04/01 83/04/14 83/04/01 83/05/31	FOIA FOIA FOIA FOIA 50-272	0
8306150248 8306150243 83/06/03 8306150251 8306150246 83/06/03 8306150257 8306150253 83/06/13 8306150257 8306150256 83/05/13 8306150252 8306150256 83/05/13	CONTRACT 50-29 J 50-443 G	83061 60138 83061 60139 83061 60143 83061 60144 83061 60148	CP004140CB 01104140CB 02104140CB 02104140CB 02104140CB	B3/04/01 B3/04/14 B3/04/01 B3/05/31 B3/04/01	FOIA FOIA FOIA 50-272 FOIA	a
8305150266 8306150260 83/05/26 8305150269 8306150264 83/05/06 8306150270 8306150267 83/06/06 8306150272 8306150260 83/05/26 8306150276 8305110471 83/06/16	! 70~143 ! 50~272 R 5 50~259 P	8306160153 8306160156 8306160162 8306160164 8306160166	9304140093 9004140093 9004140093 9004140093	83/04/01 83/04/01 83/04/01 83/06/01 83/04/01	FOIA FOIA FOIA 50-285 FOIA	þ
8306150281 8305110471 83/06/16 8306150283 8306150277 83/06/06 8306150286 8306150282 83/08/25 8306150293 8306150290 83/06/06 8306150299 8306150290 83/06/06	I 50-409 P 7 50-302 P 50-271 F	77.004.4008 77.104.14008 77.104.14008 77.104.14008 78.104.14008	1710313028 E900313028 E900313028 7710313028 E900313028	83/04/27 83/04/01 83/04/01 83/04/25 83/04/01	FOIA FOIA FOIA FOIA FOIA	
B306150335 B306150332 B306/07 B306150334 B306/150334 B306/06 B306150341 B306/150334 B306/06 B306150346 B306/150344 B306/06 B306150345 B306/06 B306/06	50-213 F 50-213 F 50-327 F	8304140185 8304140190 8304140193 8304140194 8304140198	6700414068 6700414068 6700414068 7810414068 6700414068	83/04/01 83/04/01 83/04/01 83/06/06 83/04/01	FOIA FOIA FOIA 50-72 FOIA	F
8306150355 8306150349 83/06/03 8306150373 8306150370 83/06/13 8306150381 8306150370 83/06/13 8306150386 8306150386 83/06/13 8306180400 8306150396 83/06/13) 50-322 0) 50-322 0) 50-358 0	830&1 &0200 830&1 &0200 830&1 &0203 830&1 &0204 830&1 &0204	8306160197 8306160197 8306160093 8306160197 8306160093	83/04/25 83/04/25 83/04/01 83/04/25 83/04/01	50-206 50-206 FDIA FOIA FOIA	Q Q
8306150401 8306150395 83/06/09 8306150403 8306150396 83/06/10 8306150409 8306150405 83/06/09 8306150413 8306150405 83/06/09 8306150414 83/06/09) 50-445 G P 50-155 G P 50-155 G	8306160209 8306160211 8306160216 8306160228 8306160222	8306160197 8306160093 8306160093 8306160197 8306160093	83/04/25 83/04/01 83/04/01 83/04/25 83/04/01	50-206 FOIA FOIA 50-206 FOIA	a a
8306150431 8306150238 83/05/24 8306150436 8306150420 83/06/0 8306180437 8306150238 83/05/24 8306150442 8306150420 83/06/04 8306150455 8306150454 83/06/04	/ 50-454	83051 60223 83051 60230 83051 60239 83051 60243 83051 60245	8306160197 8306160197 8306160238 8306160197 8306160238	83/04/25 83/04/25 83/05/27 83/04/25 83/05/27	50-206 50-206 50-193 50-206 50-193	0 0 0
8304150461 8304150460 83/04/07 8304150465 8304150462 83/04/07 8304150475 8304150470 83/04/07 8304150484 8304150478 83/05/07 8304150487 8304150482 83/04/07	N XPORTLIC N XPORTLIC N 50-366 P	63061 60247 83061 60253 83061 60224 83061 60258 83061 60263	B306160242 B306160197 B306160242 B306160250 B306160197	83/04/03 83/04/25 83/04/03 83/04/08 83/04/25	90-440 50-206 50-440 90-219 50-206	@ @ @
8304150488 8304150485 83/04/0 8304150501 8304150497 83/03/2 8304150515 8304150508 83/05/2 8304150521 8304150506 83/06/0 8304150543 8304150533 83/04/0	I 50~313 P I 50~346 P CONTRACT	83061 60266 83061 60273 83061 60274 83061 60276 83061 60279	830&1&0249 830&1&0259 830&1&0271 830&1&0197 830&1&0269	83/06/09 83/05/27 83/06/14 83/04/25 83/06/06	50-339 CONTRACT 50-416 50-206 50-409	P Q F
8304150570 8304150540 83/04/03 8304150415 8304150409 83/04/03 8304150428 8304150424 83/05/23 8304150430 8304150427 83/05/23 8304150434 8304150427 83/05/23	7 50-322 F 7 50-220 F 7 50-286 P	83061 60281 83061 60291 83061 60292 83061 6030 83061 60301	830&1&0197 830&1&0284 830&1&0197 830&1&0284 830&1&0197	83/04/25 83/03/16 83/04/25 83/03/16 83/04/25	50-206 TOPREP FOIA TOPREP 50-206	G G
8304150636 8304150632 83/06/03 8304150637 8304150627 83/05/2; 8304150638 8304150627 83/05/2; 8304160005 8304160003 83/06/03 8304160006 8304160003 83/06/03	7 50-206 P 7 50-206 P 1 50-271 Q	83061 60303 83061 60321 83061 60322 83061 60330 83061 60344	930&1&0284 930&1&0313 930&1&0314 930&1&0323 830&1&0341	83/03/16 83/06/13 83/06/14 83/06/01	TOPREP 70-1207 50-483 50-317 50-220	0 0
8304140010 8306160009 83/06/14 8306160017 8306160009 83/06/14 8306160032 8306160027 83/06/06 8306160045 83/06/00 83/06/06 8306160045 83/06/06 83/06/06	50-142 T 50-348 F CONTRACT	83061 6034B 83061 60354 83061 6035B 83061 60368 83061 60365	830&1&0341 830&1&0346 830&1&0343 830&1&0351 830&1&0361	83/06/01 83/06/06 83/06/10 83/06/10	50-220 50-295 50-315 50-298 50-244	G F R G
8306160057 8306160050 83/04/2 8306160064 8306160068 83/06/0 8306160077 8306160071 83/06/0 8306160063 83/06/0 83/06/0 8306160067 83/06/0 83/06/0	5 50-528 F 7 50-254 F 9 50-317 S	83061 60365 83061 60367 83061 60372 83061 60424 . 83061 60425	830&1&0357 830&1&0343 830&1&0361 830&1&0412 830&1&0371	83/06/10 83/05/31 83/05/39 83/06/09	50-341 50-315 50-244 50-213 50-378	A R G P G
8304140089 8304140072 83/04/0 8304140091 8304140072 83/04/0 8304140100 8304140094 83/04/0 8304140104 8304140094 83/04/0 8304140107 8304140093 83/04/0	7 50-322 F 7 50-322 F 7 50-322 F	830&1 &0 448 830&1 &0 45& 830&1 &0 48& 830&1 &0 49&7 830&1 &0 45	830&1&0440 830&1&0453 830&1&0483 830&1&0493 830&1&0503	83/04/07 83/04/02 83/04/10 83/04/08 83/04/13	50-272 50-240 50-277 50-313 50-445	0 Р О Р
8304140108 8304160094 83/04/06 8304140112 8304140093 83/04/06 8304140115 8304140093 83/04/06 8304140118 8304140093 83/04/06 8304140124 8304140110 83/04/16	FOIA FOIA FOIA	8306160523 8306160527 8306160545 8306160556 8306160560	830&1 &0507 830&1 &052& 830&1 &054 830&1 &0548 830&1 &0541	83/06/13 83/06/10 83/06/02 83/06/13 83/06/02	50-259 50-275 50-247 04999 50-247	P P P

ACCESSION	NUMBER				ACCESSION			
ENCLOSURE	PRINCIPAL DDCUMENT	DATE 1980ED	SUBJECT CATEGORY	r	ENCLOSURE	PRINCIPAL DOCUMENT	DATE 199UED	CATEGORY
8306160564 8306160576 8306160578 8306160582 8306160584	6304140541 8304140547 8304140548 8304140575	93/06/02 93/04/30 93/06/13 93/06/10 83/06/10	50-267 40-8380 64999 50-410 50-275	P 0 0	8306170349 8306170354 8306170360 8306170361 8306170364	8306170346 8306170353 8306170356 8306170359 8306170359	83/06/15 83/06/13 83/03/02 83/05/26 83/05/26	50-30P G 50-263 P 50-528 F 50-454 G 50-454 G
83061 60595 83061 60609 83061 60631 83061 60641 83061 60652	8306160579 8306160603 8306160625 8306160630 8306160649	83/06/10 83/06/02 83/06/13 83/05/31	50-275 50-352 50-155 50-369 71-86	9 9 P P	8306170379 8306170384 8306170399 8306170390 8306170392	8306170373 8306170378 8306170378 8306170373 8306170378	83/06/14 83/06/14 83/06/14 83/06/14	50-142 T 50-454 G 50-454 O 50-142 T 50-454 G
8306160662 8306160666 8306160667 8306160670 8306160679	8306160660 8306160660 8306160664 8306160676	83/04/01 83/04/05 83/04/05 83/04/04	50-389 50-389 71-9134 71-9134 50-346	F F	8306170407 8306170417 8306170426 8306170426 8306170451	8306170402 8306170373 8306170373 8306170425 8306170449	83/06/06 83/06/14 83/06/13 83/06/13	50-312 P 50-142 T 50-142 T 50-508 G COMMISSION
8304140485 8304140690 8304140724 8304170014 8304170019	8306160684 8306160686 8306160723 8306170013	B3/06/03 B3/06/06 B3/06/13 B3/06/01 B3/06/01	XPORTL1C 50-346 XPORTL1C 50-301 50-301	F Q Q	8306170456 8306170466 8306170472 8306170474 8306170482	8306170455 8306170463 8306170467 8306170469 8306170480	83/04/09 83/04/15 83/04/08 83/05/08 83/05/27	71-9110 CONTRACT 50-309 0 50-309 0 CONTRACT
8304170023 8304170029 8304170052 8304170055 8304170058	8306170020 8306170026 8306170050 8306170049 8306170053	83/05/27 83/04/08 83/06/01 83/05/27 83/06/06	50-454 CONTRACT 50-57 50-341 50-282	0 0 0 P	8304170483 8304170485 8304200013 8304200015 8304200040	8305170481 8305170484 8305200012 8305200014 8305200037	83/05/18 83/06/06 83/06/06 83/05/31	50-270 F CONTRACT WASTE NOT 50-155 F FOIA
8304170097 8304170099 8304170152 8304170155 8304170157	8306170089 8306170089 8306170089 8306170089 8306170089	83/04/14 83/04/14 83/04/14 83/04/14 83/04/14	FOIA FOIA FOIA FOIA FOIA		8305200041 8305200048 8305200060 830520085 8305200125	8306200037 8306200045 8306200056 8306200082 8306200122	83/05/18 83/03/07 83/06/07 83/06/06 83/05/18	FDIA ADVCM 50-313 F 50-423 G 50-498 A
8304170140 8304170142 8304170147 8304170170 8304170174	8306170089 8306170151 8306170089 8306170089 8306170089	83/04/14 83/06/14 83/04/14 83/04/14 83/04/14	FOIA 50-369 FOIA FOIA FOIA	Q	8304200130 8304200134 8304200134 8304200154 8306200141	8306200125 8306200128 8306200135 8306200151 8306200158	83/06/06 83/06/07 83/06/06 83/06/14 83/06/06	50-277 @ CONTRACT 50-387 @ 50-27 F 50-293 @
8304170177 8304170178 8304170185 8304170190 8304170191	8306170166 8306170089 8306170089 8306170089 8306170188	83/06/02 83/04/14 83/04/14 83/04/14 83/06/10	50-309 FDIA FDIA FDIA 50-387	F	8306200162 8306200165 8306200166 8306200175 8306200177	8304200158 8304200159 8304200158 8304200171 8304200174	83/06/06 83/06/14 83/06/06 83/05/04	50-293 0 50-277 0 50-293 0 40-8084 50-271 0
8306170194 8306170198 8306170203 8306170205 8306170208	8304170089 8304170089 8304170089 8304170192 8304170089	83/04/14 83/04/14 83/04/14 83/05/31 83/04/14	FOIA FOIA FOIA RES FOIA		8304200181 8304200189 8304200195 8306200197 8304200210	8305200174 8305200185 8305200194 8305200192 8305200207	83/06/06 83/06/17 83/06/16 83/06/14 83/06/07	50-271 0 50-414 K 50-389 P 50-155 P 50-344 I
8306170212 8306170220 8306170222 8306170225 8306170229	8304170089 8304170089 8304170214 8304170089 8304170089	83/04/14 83/04/14 83/06/13 83/04/14 83/04/14	FOIA FOIA 50-508 FOIA FOIA	a	8304200213 8304200215 8304200220 8304200222 8304200222	9304200207 9304200207 9304200214 9304200221 9304200221	83/06/07 83/06/07 83/06/10 83/06/06	50-344 I 50-344 I 50-348 S 70-1143 70-1143
8306170230 8306170235 8306170238 8306170242 8306170244	8306170226 8306170087 8306170087 8306170087 8306170087	83/06/10 83/04/14 83/04/14 83/04/14 83/04/14	50-247 FOIA FOIA FOIA FOIA	â	B304200227 8304200233 8304200242 8304200247 8304200251	8306200216 8306200216 8306200236 8306200243 8306200243	83/06/10 83/06/10 83/06/07 83/06/10 83/06/10	50-348 8 50-348 8 80-443 E 50-397 E 50-397 E
8306170245 8306170248 8306170252 8306170258 8306170259	8306170241 8306170089 8306170089 8306170089 8306170253	83/06/01 83/04/14 83/04/14 83/04/14 83/05/27	70-371 FOIA FOIA FOIA CONTRACT		8306200252 8306200253 8306200260 8306200262 8306200263	8304200249 8304200243 8304200277 8304200277 8304200281	83/06/15 83/06/10 83/04/28 83/04/28 83/06/03	50-2/5 R 50-39/ E FOIA FOIA 50-280 P
830&1702&2 830&1702&7 830&1702&8 830&1702&9 830&170272	8306170089 8306170089 8306170266 8306170089 8306170089	83/04/14 83/04/14 83/06/15 83/04/14 83/04/14	FOIA FOIA 50-382 FOIA FOIA	œ	8304200284 8304200285 8306200286 8304200287 8304200287	8306200277 8306200171 8306200277 8306200277 8306200224	83/04/28 83/05/04 83/04/28 83/04/28 83/06/06	FOIA 40-8084 FOIA FOIA CONTRACT
830&170274 830&170280 830&170284 830&170288 830&170291	8306170089 8306170089 8306170089 8306170089 8306170089	83/04/14 83/04/14 83/04/14 83/04/14 83/04/14	FOIA FOIA FOIA FOIA		8306200293 8306200313 8306200316 8306200322 8306200322	8304200291 8304200307 8304200314 8304200307 8306200320	83/05/06 83/06/15 83/06/13 83/06/15 83/06/14	FDIA 50-245 Q 50-244 P 50-245 Q 50-454 Q
8306170292 8306170298 8306170298 8306170299 8306170304	8304170287 8304170089 8304170089 8304170287 8304170287	83/05/08 83/04/14 83/04/14 83/05/08 83/05/08	50~3B9 F01A F01A 50~3B9 50~3B9	р Р	8304200331 8304200341 8304200344 8304200345 8304200345	8304200320 8304200335 8304200336 8304200335 8304200342	83/06/14 83/06/16 83/06/14 83/06/16 83/06/15	50-454 Q 50-358 Q 50-333 Q 50-358 Q 50-247 T
9306170307 9306170315 9306170320 9306170331 9306170336	8304170285 8304170312 8304170318 8304170327 8304170335	83/06/15 83/06/10 83/06/08 83/06/14 83/06/10	50-269 50-275 TOPREP 50-280 50-390	Ф R Р А	8306200347 8306200348 8306200351 8306200353 8306200356	8304200343 8304200335 8304200335 8304200343 8304200352	83/06/06 83/06/16 83/06/06 83/06/06	50-77 Q 50-358 C 50-358 C 50-77 Q 50-349 I

ACCESSIO				ACCESS10	N NUMBER		
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	BUDJECT CATEGORY	ENCLOSURE	PRINCIPAL DOCUMENT	DATE 188UED	SUBJECT CATEGORY
8304200357 8304200345 8304200347 8304200372 8304200381	8306200335 8306200361 8306200361 8306200335 8306200378	83/06/16 83/06/14 83/06/14 83/06/16 83/06/17	50-35B G 50-27 G 50-29 G 50-35B G 50-361 G	8306210375 8306210375 8306210384 8306210384 8306210386	8304210348 8304210370 8304210374 8304210381 8304210382	83/06/06 83/06/03 83/06/16 83/05/27 83/06/06	50-267 F CONTRACT CONTRACT CONTRACT CONTRACT 50-389 F
8306200383 8306200391 8306200394 8306200402 8306200410	8306200379 8306200387 8306200393 8306200401 8306200406	83/06/15 83/06/15 83/06/15 83/06/15	70-734 50-213 0 50-346 P 50-286 P 70-125/	8306210392 8306210397 6306210415 6306210426 8306210487	8305210382 8305210391 8305210408 8305210424 8305210404	83/06/06 83/06/10 83/05/18 83/06/13 83/06/09	50-389 F CONTRACT 71-6346 50-111 P 50-369 P
9306200411 9306200414 9306200419 9306200430 9306200431	B305200403 B305200409 B305200415 B305200429 B305200429	83/03/17 83/04/14 83/05/25 83/06/13 83/06/13	50-20A F 50-461 F WASTE MOT 50-416 E 50-416 E	8306210430 8306210432 8306210440 830622000 8306220010	8306210424 8306210421 8306210436 8306220003 8306220002	83/06/13 83/06/16 83/06/16 83/06/15	50-111 P CONTRACT 70-143 50-293 P 50-321 P
8304200432 8304210012 8304210014 8304210020 8304210024	8306200429 8306210009 8306210010 8306210013 8306210017	83/04/13 83/05/31 83/04/09 83/05/27 83/06/10	50-416 E 50-270 Q 50-259 F GA779 50-29 P	8305220024 8305220030 8305220034 8305220034 8305220041	8306220016 8306220016 8306220028 8306220031 8306220037	83/06/15 83/06/15 83/06/17 83/06/20 83/06/07	50-341 Q 50-341 Q 50-254 Q 50-358 Q 50-346 Q
B30621002B B306210031 B306210032 B306210033 B306210041	0306210023 8306210025 8306210027 8306210030 8306210037	83/04/03 83/08/27 83/04/15 83/04/17 83/04/14	GA999 GA999 50-327 P GA999 50-305 G	B306220047 B306220050 B306220052 B306220053 B306220055	8304220033 8309220037 8304220045 8304220044 8304220049	83/06/16 83/06/07 83/06/17 83/06/17	50-280 P 50-346 Q 50-275 Q 50-271 P 50-302 P
8306210064 8306210065 8306210070 8306210075 8306210097	B304210041 B304210057 B304210041 B304210072 B304210072	83/06/06 83/06/14 83/06/06 83/06/15	50~382 0 50~315 0 50~382 0 50~247 0 50~369 P	8306220063 8306220076 8306220093 8306220093	8306220056 8306220066 8306220074 8306220073 8306220088	83/06/14 83/06/06 83/06/21 83/06/02 83/06/16	50-170 Q 50-461 Q 50-219 P CONTRACT 50-322 Q
8306210102 8306210103 8306210107 8306210110 8306210117	8306210095 8306210098 8306210104 8306210105 8306210115	83/06/14 83/06/07 83/06/07 83/05/31 83/06/15	50-155 0 50-213 0 50-327 0 50-445 0 50-327 P	8306220104 8306220107 8306220111 8306220137 8306220138	9705280133 8010529058 8010529058 9010529058	83/06/06 83/06/06 83/06/17 83/06/20 83/06/06	50-410 X 50-410 C 50-400 Q 50-483 G CONTRACT
8306210122 8306210127 8306210134 8306210142 8306210147	B306210166 B306210114 B306210128 B306210128 B306210145	83/06/13 16/60/68 60/60/68 10/60/68	50-409 P 50-27H Q 50-315 S 50-315 S 50-219 Q	8306220141 8306220148 8306220153 6306220154 8306220157	8304220134 8304220143 8304220144 8304220149 8304220144	83/06/20 83/06/30 83/06/21 83/06/21	50-322 Q RE00B 50-537 Q 50-410 Q 50-537 Q
8306210153 8306210163 8306210166 8306210168 8306210169	8306210146 8306210157 8306210158 8306210157 8306210160	83/06/17 83/06/17 83/06/17 83/06/17	TOPREP 50-244 P 50-219 P 50-244 P 50-309 P	6306220156 6306220159 6306220160 6306220173 6306220173	8306220151 8306220155 8306220166 8306220164 8306220171	83/06/10 83/04/22 83/06/16 83/06/13 83/06/02	CONTRACT 50-387 G CONTRACT WASTE MOT 50-269 G
8306210170 8306210171 8306210188 8306210198 8306210201	8304210141 8304210142 8304210178 8304210187	83/06/15 83/06/13 83/06/17 83/06/14 83/06/17	50-346 0 50-275 R 50-286 P 50-483 Q 50-348 P	6305220176 8305220178 8305220190 8305220191 8305210192	8306220164 8306220172 8306220184 8306220181 8306220186	83/06/13 83/06/13 83/06/09 83/03/29 83/06/15	HABTE HOT 71-498 71-5828 50-277 G CONTRACT
8306210203 8306210213 8306210224 8306210233 8306210238	8305210174 8305210174 8305210174 8305210230 8305210230	83/06/17 83/06/17 83/06/17 83/05/27 83/05/27	50-259 G 50-259 G 50-259 G GA999 GA999	8306220222 8306220226 8306220227 8306220230 8306220233	8305220217 8305220223 8305220220 8305220225 8305220229	83/05/31 83/06/08 83/06/10 83/06/06 83/06/10	CONTRACT 50-307 P CONTRACT 50-335 F CONTRACT
6306210243 6306210245 6306210254 6306210256 6306210256	8306210236 8306210240 8306210247 8306210250 8306210247	83/06/13 83/06/17 83/06/06 83/05/31 83/06/06	50-416 0 50-397 0 50-209 8 71-9100 50-209 8	8306220236 8306220241 8306220246 8306220251 8306220255	8306220225 8306220238 8306220244 8306220243 8306220247	83/06/06 83/06/15 83/06/10 83/05/27	50-335 F CONTRACT CONTRACT 50-286 F CONTRACT
8308210267 8308210271 8308210273 8308210274 8308210279	8304210257 8304210244 8304210259 8304210272 8304210259	83/06/08 83/06/08 83/06/08 83/06/08	50-315 B 50-483 0 50-315 B 0A999 50-315 B	8306220257 8306220259 8306220260 8306220261 8306220263	8306220252 8306220253 8306220252 8306220243 8306220252	83/06/07 83/06/03 83/06/07 83/05/27 83/06/07	50-346 F CONTRACT 50-346 F 50-286 F 50-346 F
8306210282 8306210284 8306210286 8306210298	8306210272 8306210259 8306210272 8306210291 8306210292	83/06/01 83/06/08 83/06/01 83/05/23 83/06/20	0A999 50-315 8 9A999 50-341 0 50-409 F	B304220264 B304220266 B304220266 B304220272 B304220272	8306220178 8306220262 8306220178 8306220267 8306220267	83/06/10 83/06/10 83/06/03 83/06/03	50-320 P CONTRACT 50-289 P CONTRACT CONTRACT
83062 10303 83062 10323 83062 10326 83062 10332 83062 10336	8306210320 8306210320 8306210327 8306210327	83/04/11 83/04/07 83/04/07 83/04/22 83/04/22	FOIA FOIA FOIA FOIA	8304220282 8304220288 8304220275 8304220279 8304220279	8306220277 8306220284 8306220289 8306220293 8306220289	83/06/06 83/05/31 83/06/17 83/06/06 83/06/17	CONTRACT CONTRACT 50-413 F 50-289 F 50-413 F
8306210344 8306210357 8306210360 8306210365 8306210371	8304210339 8304210355 8304210359 8304210343 8304210344	83/06/03 83/06/06 83/06/06 83/06/06 83/05/31	CONTRACT 50-10 F 50-205 F 50-348 F CONTRACT	8306220303 8306220319 8306220319 8306220313	8304220300 8304220302 8304220307 8304220307 8304220314	83/05/09 83/05/03 83/05/07 83/05/07 83/05/03	TOPREP CONTRACT SO-321 F SO-321 F CONTRACT

ACCESSIO						ACCESSION	NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISBUED	SUBJECT CATEGOR	Y	ENC	LOSURE	PRINCIPAL DOCUMENT	DATC ISSUED	SUBJE(T	
8306220327 8306230010 8306230012	8306220324 8306230007 8306230005	83/05/27 83/04/20 83/03/25	CONTRACT 50~155 50~373	 G Q	830 830 830	6230359 6230366 6230370	6304230353 6304230341 6304230348	83/06/10 83/06/21 83/06/22	50-358 50-309 50-367	Q F
8304230015 8304230016	8306230005 8306230009 8306230009	93/03/25 93/05/04 93/05/04	50-375 FOIA FOIA	a	830	6230382 6230388	8304230378 8304230383	83/06/20 83/06/0 9	50-348 50-317	P 0
8306230017 8306230020 8306230022 8306230024	8304230005 8304230005 8304230005	83/03/25 83/05/06 83/03/25 83/03/25	50-373 FOIA 50-373 FOIA	a a	830: 830: 830:	6230391 6230392 6230397 6230404 6230405	8304230384 8304230389 8304230369 6304230401 8304230399	83/06/08 83/06/08 83/06/08 83/06/08	TOPRE# 50-273 50-273 GA999 50-443	0 0
8306230025 8306230028 8306230030 8306230031 8306230035	8304230009 8304230005 8304230027 8306230005 8304230009	83/05/06 83/03/25 83/06/01 83/03/25 83/05/06	FDIA 50-373 40-8681 50-373 FDIA	A A	830: 830:	6230417 6230420 6230423 6230424 6230440	8306230415 8306230411 8306230416 8306230415 8306230431	83/06/10 83/06/10 83/06/10 83/06/10	50-412 50-409 50-374 50-412 50-155	0 0 0
6306230037 8306230038 8306230039 8306230042 8306230043	8305230005 8305230009 8305230005 8305230009 8305230005	83/03/25 83/03/06 83/03/25 83/05/06 83/03/25	50-373 FOIA 50-373 FOIA 50-373	A A Q	830- 830- 830- 830-	6230443 6230453 6230458 6230459 6230463	8305230437 8305230444 8305230452 8305230455 8305230455	83/06/09 83/06/21 83/06/20 83/06/20	TOPREP 50-328 50-443 50-333 50-333	P A G
8306230048 8306230051 8306230052 8306230053 8306230056	8305230041 8305230005 8305230047 8305230009 8305230005	83/04/07 83/03/25 83/04/01 83/05/04 83/03/25	CONTRACT 50-373 TOPREP FOTA 50-373	A G	830 830 830 830	6230469 6230475 6230477 6230479 6230481	8306230456 8306230471 8306230476 8306230476 8306230476	83/04/20 83/04/08 83/04/20 83/04/20 83/06/20	50-333 50-272 50-483 50-483 50-483	9 9 9
6304230058 6304230059 6304230040 6304230041 6304230043	8304230009 8304230054 8304230009 8304230005 8304230009	83/05/06 83/05/27 83/05/06 83/03/25 83/05/06	FOIA CONTRACT FOIA 50-379 FOIA	a	830 830 830 830	6230491 6230496 6230501 6230505 6230509	8304230485 8304230494 8306230497 8306230503 8306230507	83/06/14 83/06/15 83/05/13 83/06/15 83/06/15	CONTRACT CONTRACT 50-320 CONTRACT CONTRACT	P
8306230064 8306230065 8306230066 8306230067 8306230069	8304230007 8304230007 8304230007 8304230007	83/05/06 83/03/25 83/05/06 83/05/06 83/05/06	FOIA 50-373 FOIA FOIA FOIA	G	930: 930: 930:	6240011 6240012 6240014 6240016 6240020	8306240007 8306240008 8306240006 8306240007 8306240007	83/04/25 83/06/21 83/06/02 83/04/25 83/04/25	FDIA 50-324 50-321 FDIA FOIA	P Q
8306230071 8306230072 8306230076 8306230077	8304230009 8304230009 8304230009 8304230009	83/05/06 83/05/06 83/05/06 83/05/06	FOIA FOIA FOIA FOIA FOIA		930: 930: 930:	6240024 6240025 6240027 6240028 6240034	8304240007 8304240017 8304240017 8304240007 8304240031	83/04/25 83/06/16 83/06/16 83/04/25 83/06/15	FDIA 50-460 50-460 FDIA CONTRACT	Λ Α
8305230079 8305230080 8305230084 8305230085 8305230087	8304230073 8304230007 8304230007 8304230007 8304230073	83/05/06 83/05/06 83/05/06 83/06/06	50-282 FOIA FOIA FOIA 50-282	F	8304 6304 6304	6240035 6240036 6240039 6240043 6240044	8306240030 8306240007 8306240007 8306240007 8306240033	83/06/13 83/04/25 83/04/25 83/04/25 83/06/10	50-237 FOIA FOIA FOIA 71-5595	Р
8306230091 8306230098 8306230100 8306230102	8304230009 8304230009 8304230009 8304230092	83/05/06 83/05/06 83/05/06 83/06/06 83/06/06	FOIA FOIA FOIA 50-213 50-213	F F	830a 830a 830a	6240047 6240049 6240051 6240053 6240057	8304240007 8304240044 6304240007 8304240007 8304240055	83/04/25 83/05/05 83/04/25 83/04/25 83/06/15	FOIA 50-272 FOIA FOIA CONTRACT	g.
8304230105 8304230107 8304230118 8304230133 8304230137	830&230007 830&230007 830&230114 830&230131 830&230127	83/05/06 83/05/06 83/06/09 83/06/10 83/04/13	FOIA FOIA 70-820 50-358 70-8	R	830 830 830	4800454 4200454 420076 4240101 4240104	8306240007 8306240007 8306240007 8306240007 8306240007	83/04/25 83/04/25 83/04/25 83/04/25 83/04/25	FOIA FOIA FOIA FOIA	
8306230139 8306230144 8306230149 8306230153 8306230157	8304230127 8304230127 8304230127 8304230127 8304230127	83/04/13 83/04/13 83/04/13 83/04/13	70-8 70-8 50-4 70-8 FOIA	o	830 <i>6</i> 830 <i>6</i> 830 <i>6</i>	6240109 6240112 6240116 6240118 6240119	8306240007 8306240007 8306240007 8306240115 8306240007	83/04/25 83/04/25 83/04/25 83/06/30 83/04/25	FOIA FOIA FOIA REGGD FOIA	
8304230161 8304230166 8304230169 8304230174 8304230178	8304230129 8304230129 8304230147 8304230170 8304230172	83/04/13 83/04/13 83/06/16 83/06/21 83/06/14	FDIA FOIA 50-416 50-333 CONTRACT	P P	8304 8304 8304	5240128 5240131 5240148 5240149 5240151	8306240007 8306240007 8306240140 8306240145 8306240007	83/04/25 83/04/25 83/06/20 83/06/20 83/04/25	FOIA FOIA 50-274 50-325 FOIA	() P
8304230199 8304230212 8304230216 8304230220 8304230225	8304230203 8304230203 8304230215 8304230216 8304230253	83/06/08 83/06/10 83/03/31 83/03/31	50-244 50-247 50-336 CONTRACT 50-346	0 0 0	9308 9308 9308	5240155 5240158 5240160 5240163 5240168	8304240007 8304240007 8304240007 8304240007 8304240007	83/04/25 83/04/25 83/04/25 83/04/25 83/04/28	FOIA FOIA FOIA FOIA FOIA	
8306230261 8306230262 8306230271 8306230279 8306230270	8305230250 8305230259 8305230257 8305230274 8305230275	83/06/20 83/06/15 83/06/08 83/06/10	50-266 50-346 50-440 50-266 50-454	G G G	8304 8304 8304	5240201 5240204 5240207 5240208 5240209	8306240196 8306240196 8306240196 8306240203 8306240196	83/06/17 83/06/17 83/06/17 83/06/17	0A797 0A797 0A797 50-206 0A797	Þ
8304230305 8304230322 8304230324 8304230351 8304230357	8308230303 8308230317 8308230324 8308230348 8308230353	83/06/20 83/06/21 83/06/02 83/06/20 83/06/10	50-142 50-244 TOPREP 50-331 50-358	e e p q	8308 8308 8308	5240214 5240217 5240224 5240227 5240232	8306240196 8306240196 8306240196 8306240196 8306240230	83/06/17 83/06/17 83/06/17 83/06/17 83/06/20	QA999 QA999 QA999 QA999 50~322	£

ACCESSION	I NUMBER				ACCESSION	NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGORY		ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISBUED	SUBJEC CATEROI	
8306240243 8306240245 8306240263 8306240281 8306240293	8306240237 8306240237 8306240262 8306240279 8306240289	83/05/26 83/05/26 83/05/09 83/06/22 83/06/03	0A997 0A999 TOPREP 50-209 0A997	G G	8304270342 8304270344 8304270349 8304270350 8304270353	8305110492 8305110492 8305110492 8305110492 8306270347	83/06/24 83/06/24 83/06/23 83/06/24 83/06/22	50-275 50-275 50-329 50-275 50-377	0 0 0 8
8306240295 8306240301 8306240302 8306240305 8306240310	8306240270 8306240270 8306240278 8306240270 8306240308	83/06/20 83/06/20 83/06/20 83/06/20 83/05/18	50-24/ 50-244 50-24/	G G P G F	8306270357 8306270364 8306270369 8306270378 8306270395	830 <i>6</i> 270351 830 <i>6</i> 270351 830 <i>6</i> 270229 830 <i>6</i> 270374 830 <i>6</i> 270381	83/06/13 83/06/13 83/06/16 83/06/22 83/06/17	50~281 50~281 50~348 50~358 50~409	8 9 8 A 0
8305240312 8305240314 8305240315 6305240318 8305240330	8306240311 8306240313 8306240313 8305110486 8306240328	83/04/14 83/04/02 83/04/20 83/04/13	TOPREP TOPREP	9 8 MI	83062703B9 8306270392 8306270426 8306270436 8306270444	8304270381 8304270387 8304270420 8304270433 8304270433	83/06/17 83/06/08 83/06/24 83/06/16 83/06/16	50-409 50-237 50-331 50-315 50-315	0 0 P 8
8306240331 8306240336 8306240337 8306240356 8306240358	8306240328 8306240335 8306240335 8306240335 8306240353	83/06/13 83/06/13 83/06/13 83/05/06 83/06/15	COMMISSIO COMMISSIO FOIA CONTRACT)N	8306270446 8306270449 8306270453 8306270456 8306270477	8306270441 8306270433 8306270452 8306270452 8306270416	83/06/03 83/06/16 83/06/01 83/06/22	CONTRACT 50-315 0A999 0A999 50-275	r B
8306240380 8306240410 8306240415 8306240419 8306240421	830&2403&9 830&240405 830&240405 830&240405 830&240405	83/06/15 83/06/16 83/06/16 83/06/16	50-155 50-155	G G G	8304280011 8304280042 8304280046 8304280054 8304280057	8304280009 8304280034 8304280034 8304280047 8304280050	83/06/24 83/06/23 83/06/23 83/06/17 83/05/27	50-309 50-322 50-322 PR GONTRACT	P F r
8306240422 8306240423 8306240441 8306240445 8306240446	8306240405 8306240405 8306240438 8306240438 8306240443	83/06/16 83/06/16 83/06/07 83/06/03		G	8306280175 8306280078 8306280118 8306280122	8306280073 8306280076 8306280076 8306280113	83/06/20 83/06/20 83/06/07 83/06/03	50-205 50-285 50-206 CONTRACT	
B306240450 B306240479 B306240489 B306270003 B306270004	8304240443 8304240477 8304240488 8304200245 8304270001	83/06/03 83/06/10 83/06/16 83/06/10	71-86 50-23/	P G	8306280133 8306280136 8306280145 8306280147 8306280159	8606280127 8306280131 8306280137 8306280141 8306280152	83/05/04 83/06/03 83/06/03 83/05/16	CONTRACT 50-244 50-528 CONTRACT CONTRACT	0 0 1
8306270017 8306270020 8306270069 8306270071 8306270079	8306270014 8306270016 8306270067 8306270066 8306270076	83/06/21 83/06/21 83/05/2/ 83/06/20 83/06/22	50~454 50-329 50~456	0 R 0 P	8304280142 8304280147 8304280173 8304280173	8306280156 8306280164 8306280156 8306280170 8306280171	83/06/14 83/06/21 83/06/14 83/06/21 83/05/27	50-277 50-271 50-277 50-271 50-89	P 0 P 0
8306270080 8306270109 8306270115 8306270149 8306270152	8305270077 8306270107 8305270112 8305270138 8305270138	83/04/23 83/04/22 83/04/22 83/06/24	50-155 50-440 50-546	ር 6 የ	8306280181 8306280183 8306280185 8306280174 8306280210	8305280175 9305280175 9305280171 8305280189 9305280204	83/06/24 83/05/27 83/05/27 83/05/26 83/06/13	50-219 50-312 50-87 50-275 50-213	P G G
8306270167 8306270174 8306270175 8306270179 8306270184	8304R70142 8304R70149 8304R70170 8304R70171 8304R70171	80/40/E8 01/40/E8 02/40/E8 41/40/E8	50-155 50-366 50-3	0 P R R	8304280211 8304280213 8304280215 8304280216 8304280220	8305280205 8305280208 8305280209 6305280206 8306280206	83/05/06 83/06/24 83/06/02 83/05/06 83/05/06	50-320 50-358 50-397 50-320 50-320	P 0 P P
8305270187 8305270205 8305270220 8305270222 8305270226	8304270185 8304270201 8304270215 8304270215 8304270225	83/06/10 83/06/23 83/06/23 83/06/23	50~546 50~370 50~370	0 0 0 0 P	8304280226 8304280236 8304280236 8304280246 8304280240	8306280218 8306280217 8306280217 8306280217 8306280217	83/06/10 83/06/06 83/06/06 83/06/06	50~312 50~247 50~247 50~267 50~247	0 9 9 9
9306270230 8306270232 8306270233 8306270234 8306270237	830 <i>5</i> 270225 830 <i>5</i> 270227 830 <i>5</i> 270231 830 <i>5</i> 270231 830 <i>5</i> 270235	83/06/23 63/06/16 63/06/20 63/06/20	50-348 50-289	Р В Р Р	8306280261 8306280262 8306280266 8306280272 8306280278	8305280258 8305280217 8305280217 8305280217 8306280217	83/05/10 83/05/05 83/05/05 83/05/05 83/06/05	XPORTLI 50-267 50-267 50-267 50-267	8 8 9
8305270237 8305270251 8305270253 8305270258 8305270264	8304270238 8304270248 8304270248 8304270255 8304270261	83/04/14 83/04/28 83/04/28 83/04/03 83/04/22	50-387 50-336	п п Р	8304280283 8304280288 8304280271 8304280273 8306280278	0304280217 8304280217 8304280280 8304280217 8304280217	83/06/06 83/05/26 83/05/06 83/06/06	50-267 50-267 WASTE M 50-267 50-267	8 8 8 8
8305270268 8305270270 8305270278 8305270281 8305270287	8306270261 8306270265 8306270273 8306270273 8306270283	83/04/23 83/04/23 83/04/23 83/04/23	50-289 50-289	6 0 0 0	8306280302 8306280309 8306280313 8306280313	830 62802 17 830 62802 17 830 6280303 830 62802 17 830 6280333	83/06/06 83/06/16 83/06/06 83/06/06	50-247 50-267 50-528 50-247 50-344	9 0 9
8304270278 8304270300 8304270304 8304270308 8304270313	8304270293 8304270297 8304270299 8304270305 8304270307	83/06/21 83/06/17 83/06/23 83/06/23		6 6 0	8305280341 8305280345 8305280351 8305280363 8305280378	8304280934 8304280340 8304280347 8304280357 8304280373	83/06/03 83/06/24 83/06/23 83/06/13 83/06/24	50~397 50~202 50~77 50~293 50~305	0 0 0 0 P
8306270314 8306270321 8306270323 8306270335 8306270341	8306270311 8306270311 8306270320 8306270329 8306270329	93/06/22 93/06/22 93/06/23 93/06/17 93/06/17	50~461 50~461 50~289 50~305 50~305	0 0 0 0	8306280380 8306280394 8306280396 8306280409	8304280371 8304280388 8304280388 8304280372 8304280405	83/06/15 83/06/23 83/06/21 83/06/21	50-397 50-275 50-275 50-445 50-508	0 P P A 0

ACCESS 10N	NUMBER					ON NUMBER		
ENCLOSURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT CATEGOR	Υ	ENCLOSURE	PRINCIPAL DOCUMENT	DATE 1 GBUED	SUBJECT CATEGORY
B304280424 B304280433 B304280452 B304280454 B304280458	8304280422 8304280429 8304280450 8304280453 8304280455	83/06/24 83/06/22 83/06/09 83/06/21 83/06/07	50-220 70-1402 50-528 50-397 70-115	9 9 E	8306290345 6306290349 6306290351 6306290351 8306290357	8304270341 8304270341 8304270327 8304270341 8304270341	83/06/16 83/06/16 83/06/17 83/06/16 83/06/16	50-250 0 50-250 0 50-335 0 50-250 0 50-250 0
8306280465 8306280470 8306280474 8306280460 8306280464	8306280461 8306280469 8306280472 8306280477 8306280357	83/06/22 83/06/24 83/06/13 83/06/14 83/06/13	50-317 50-275 50-271 50-206 50-293	0 R 0 0	8306290359 8306290368 8306290371 8306290375 8306290379	8304290327 8304290327 8304290345 8304290370 8306290327	83/06/17 83/06/17 83/06/03 83/06/22 83/06/17	50-335 Q 50-335 Q 50-416 Q 50-460 G 50-335 Q
8306280492 8306280495 8306280497 8306280507 8306280511	8304280470 8304280470 8304280470 8304280503 8304280478	83/06/23 83/06/23 83/06/23 83/05/27 83/06/15	50-334 50-334 50-334 50-397 50-361	0 0 0 0	8306270380 8306270387 830627040 8306270404 8306270408	8304290377 8304290383 8304290397 8304290394 8304290400	83/05/27 83/06/17 83/06/24 83/06/03 83/06/20	50-302 9 50-338 9 50-275 R 50-413 9 50-259 P
8304280513 8304280517 8304280521 8304280530 8304280541	8304280509 8304280515 8304280514 8304280527 8304280534	83/06/24 83/06/14 83/06/06 83/06/27 83/06/27	50-220 50-528 50-397 50-289 50-382	P G G G	8304290413 8304290424 830429043 8304290431 8304290432	8306290406 8306290421 8306290420 8306290409 8306290409	83/04/27 83/04/01 83/04/08 83/04/28 83/06/28	50-245 P 50-389 Q 50-241 Q 50-354 K 50-354 A
8304280544 8304280551 8304280541 8304280570 8304280575	8306280524 8306280546 8306280546 8306280564 8306280564	83/06/23 83/06/17 83/06/17 83/06/24 83/06/24	50-324 50-341 50-361 50-237 50-237	P G G P P	8306290435 8306290436 8306290444 8306290448 8306290449	8306270407 8306270433 8306270407 8306270407 8306270407	83/46/28 83/46/28 83/46/28 83/46/28	50-354 C 70-1151 50-354 K 50-354 K
8306280581 9306280590 8306280594 8306280608 8306280617	8305280559 8305280585 8305280559 8305280501 8305280513	83/06/20 83/06/20 83/06/23 83/06/23	50-11P 50-354 50-112 50-322 50-344	6 6 6 6	8306270451 8306270454 8306270454 8306270457 8306270458	8306290409 8306290409 8306290409 8306290409 8306290409	83/40\C8 83/40\C8 83/40\C8 83/40\C8	50-354 K 50-354 K 50-354 K 50-354 K
8306280632 8306290018 8306290073 8306290077 8306290080	8306280620 8306200154 8306290068 8306290068 8306290068	83/06/10 83/06/21 83/06/21 83/06/21	50-344 50-27 50-141 50-141 50-141	G ₩ ₩	8306290460 8306290461 830629046 8306290465 8306290465	8306270407 8306270457 8306270457 8306270407 8306270407	83/04/28 83/04/23 83/04/28 83/06/28	50~354 K 50-413 G 50-413 G 50~354 K 50-354 K
9306270093 9306270135 9306270172 9306270202	9306270082 8306270087 8306270126 8306270186 9306270174	83/06/21 83/06/23 83/06/22 83/06/03 83/06/07	70-734 50-447 50-556 50-413 50-317	D A O P	8306290469 8306290470 8306290471 8306290473 8306290473	8306290409 8305110499 8306290409 8306290409 8306290409	83/06/28 83/06/27 83/06/28 83/06/28 83/06/28	50-354 K 50-275 T 50-354 K 50-354 K
8306270203 8306270207 8306270212 8306270213 8306270216	8306270175 8306270178 8306270204 8306270178 8306270178	83/06/09 83/06/16 83/05/31 83/06/16 83/06/16	50-257 50-348 50-250 50-348 50-348	0 0 0 0	8304290476 8304290477 8304290477 8304290479 8304290479	8305110477 8304270409 8304270409 8304270409 8304270409	83/06/27 83/06/28 83/06/28 83/06/28 83/06/28	50-275 T 50-354 K 50-354 K 50-354 K
8306270220 8306270221 8306270222 8306270224 8306270225	8306270214 8306270207 8306270198 8306270218 8306270217	83/06/01 83/06/16 83/03/21 83/06/08	50-440 50-335 50-348 50-259 50-389	0 0 0 0	8304270484 8304270485 8304270487 8304270487 8306270470	8306290409 8306290480 8306290409 8306290409 8306290483	83/06/28 83/06/27 83/06/28 83/06/28 83/06/17	50-354 K 50-354 K 50-354 K 50-354 K
8306270228 8306270233 8306270235 8306270240 8306270244	8306270218 8306270227 8306270231 8306270214 8306270236	83/03/21 70/40/88 70/40/88 E0/40/88	50-259 50-537 50-438 50-440 50-416	0 0 0	6306290491 6306290492 6306290494 6306290496 6306290497	8306290407 8306290480 8306290409 8306290493 8306290409	83/06/28 83/06/27 83/06/28 83/06/29 83/06/28	50-354 K 50-320 G 50-354 K 50-329 A 50-354 K
8306270246 8306270265 8306270275 8306270278 8306270281	8306270237 8306270254 8306270254 8306270254 8306270268	83/06/20 83/06/16 83/06/16 83/06/20	50-438 50-321 50-259 50-321 CONTRACT	0 0 0	8306290500 8306290503 8306290510 8306290510 8306290511	8306290495 8306290483 8306290495 8306290483 8306290428	83/06/15 83/06/17 83/06/15 83/06/17 83/06/06	50-447 K 50-259 G 50-447 K 50-259 G 50-390 G
8306270283 8306270284 8306270288 8306270272 8306270273	8306270277 8306270254 8306270277 8306270277 8306270254	83/06/14 83/06/16 83/06/14 83/06/14 83/06/14	50-259 50-321 50-259 50-259 50-321	0 0 0	8306270512 8306270515 8306270515 9306270531 8306270537	8306290507 8306290507 8306290517 8306290524 8306290524	83/04/15 83/04/15 83/04/08 83/04/14 83/06/14	50-447 K 50-447 K 50-369 G 50-241 G
8304270277 8306270303 8306270305 8306270312 8306270314	8306270277 8306270278 8306270200 8306270278 8306270308	83/06/14 83/06/16 83/06/07 83/06/16 83/06/15	50-259 50-321 50-413 50-321 50-390	0 0 0	8304290545 8304290549 830429055 8304290552 8304290553	8304290397 8304290534 8304290530 8304290544 8304290524	83/06/24 83/06/23 83/06/27 83/06/23 83/06/14	50-275 R 50-440 e 50-327 e 50-142 e 50-261 e
8306290317 8306290318 8306290319 8306290324 8306290325	8304270278 8304270308 8304270307 8304270308 8304270307	83/06/15 83/06/15 83/06/15 83/06/15	50-321 50-390 50-438 50-390 50-438	0 0 0 0	8304270555 8304270547 8304270625 8304270426 6304270433	8306290524 8306290564 8306290597 8306290620 8306290385	83/06/14 83/06/07 83/06/15 83/06/14 83/06/15	50-261 G REVIEW GRP CONTRACT 50-201 P CONTRACT
8306270328 8306270332 8306270334 8306270335 8306270338	930627030B 9306270298 9306270307 9306270327 8306270327	83/06/15 83/06/16 83/06/15 83/06/27 83/06/17	50-390 50-321 50-438 50-295 50-335	0 0 0 0	8304270487 8304300011 8304300021 8304300029 8304300034	8304290482 8304300007 8304300014 8304300022 8304300027	83/06/16 83/06/24 83/06/16 83/06/17 83/06/29	70-2375 50-312 Q 50-255 Q 50-344 Q 50-155 P

ACCESSION N	JUMBER

ENCLOSURE	PRINCIPAL DOCUMENT	DATE I SSVED	SUBJECT CATEGOR			
ENCLIPAGE	TOUCHIEN!	100000	CHITCH			
B305300061	B306300057	83/06/14	50~341	a		
8306300062	8306200033	83/06/14	50-307	ř		
B306300063	8304300040	83/06/14	50-346	ø		
B306300003	8306300053	83/06/16	50-341	ä		
B306300073	830430004B	83/06/27	50-373	Ġ.		
0200200012	0100000000	00,00,E,	00 071			
@306300079	B304300075	83/06/27	50-313	a		
8306300089	E30A300083	83/06/24	50-275	a		
B30A300090	8306300084	83/05/27	50-403	a		
B306300073	6306300063	83/04/24	50-275	Ġ		
6306300097	8306300095	83/06/23	50~289	G		
B305300105	1010024028	B3/06/27	50 -3174	٨		
8306300107	8306300104	82/11/1/	50-24/	ø		
6304300108	8306300102	83/06/28	50-324	G		
B306300109	0306300101	83/06/27	50~327	٨		
111000500EB	8304300104	82/11/17	50~267	G		
8306300112	1010064068	83/06/27	50~329	A		
8306300125	8304300057	83/06/22	146-05	þ		
6304300132	8309300139	83/06/17	50-440	ø		
8206300135	8304300127	11/40/EB	50-37.:	G		
9E100E90E8	8306300057	83/06/25	50-361	P		

ACCESSION :	NUMBER
-------------	--------

~			
PRINCIPAL	DATE	SUBJEC	`T
DECUMENT	ISSUED	CATEGO	RY
0204200120	92/04/11	60-030	o
			-
			P
			K
			R
0306300170	83/06/20	50-400	0
B306300179	B3/06/15	50-440	G
871000240128	83/06/16	50-454	G
8306300170	83/06/20	50-403	0
8304300190	83/06/24		p
			9
w=v====		00 00,	•
8305300191	83706723	50-349	5
	83706714		G
			ä
			ņ
0200200515	03/00/10	20-350	G
020420022	00.486.486	to anti	Р
			G.
			a
			a
0309300521	11/40/08	50-346	0
	8306300129 8306300129 8306300057 8306300149 8306300162 8306300179 8306300179	B306300129 B3706711 B306300129 B3706720 B306300149 B3706720 B306300140 B3706720 B306300170 B3706720 B306300170 B3706720 B306300170 B3706720 B306300170 B3706721 B306300170 B3706721 B306300191 B3706721 B306300191 B3706721 B306300191 B3706721 B306300191 B3706721 B306300212 B3706721 B306300212 B3706721 B306300225 B3706721 B306500235 B3706721	B306300129 B3/06/24 S0-27/4

APPENDIX A

DEFINITIONS OF DOCKET 50 CATEGORIES

A APPLICATION/CONSTRUCTION STAGE DOCUMENTS AND CORRESPONDENCE

This category tollows the application from submission to the day preceding the issuance of an operating license. It includes all correspondence and documents with substantive technical content that do not fall into other specific categories. Included are

- 1 Application for construction permit
- 2. General Information submitted with construction permit application
- 3 Amendments and changes to items 1 and 2,
- 4. NRC questions, requests for additional information, and applicant responses.
- 5. Correspondence and documents relating to unresolved design and construction issues.
- 6. Meeting announcements and summaries of meeting discussions on issues of item 5.
- 7. Correspondence regarding the Preliminary Safety Analysis Report (PSAR).
- 8. Information on laws and changes in regulations or policy that affect the status of the application (NEPA, Water Quality Improvement Act, Water Pollution Control Act, etc.).
- 9. Construction Permit, amendments, and correspondence relating to the construction permit
- 10. Scheduling of license application submission or review.
- 11. Environmental review information.
- 12. Application for operating license.
- 13. General Information submitted with operating license application.
- 14. Amendments and changes to items 12 and 13.
- 15. Correspondence regarding the Final Safety Analysis Report (FSAR).
- 16. Correspondence and documentation on generic technical matters highlighted by an event at another facility which may affect the subject facility; not covered by an IE Bulletin.
- 17 Reports of site visits.
- 18. Backup technical documents (e.g., topical reports) submitted in support of the application.

B. UTILITY PRELIMINARY SAFETY ANALYSIS REPORT (PSAR) AND AMENDMENTS

This category is strictly limited to the items listed below. All related correspondence is filed in Category A.

- 1. Preliminary Safety Analysis Report (PSAR) submitted by utility (formerly called Hazards Summary Report or Safety Analysis Report).
- 2. Amendments and changes to the PSAR.

- 3 Transmittal and acknowledgement letters
- 4. Certificates of service to the PSAR

C UTILITY ENVIRONMENTAL REPORT (ER), AMENDMENTS AND CORRESPONDENCE

This category is strictly limited to the items listed below. Other environmental documents and correspondence are filed in Categories A. D. M. P or R

- I Environmental Report (ER) submitted by the utility
- 2 Amendments and supplements to the ER
- 3 Transmittal and acknowledgement letters
- 4. Information on scheduling of submittal or review of ER.
- 5. NRC questions, requests for additional information, and applicant responses
- 6. Federal register notices citing the availability of items 1 and 2
- 7. Correspondence relating to the review of ER
- 8. Meeting announcements or reports of meetings where the primary subject of discussion is the FR

D. NRC DRAFT AND FINAL ENVIRONMENTAL (IMPACT) STATEMENTS (DES AND FES), SUPPLEMENTS AND CORRESPONDENCE

Thus category is strictly limited to the items listed below. Other environmental documents and correspondence are in categories A, C, M, P or R.

- 1 Draft and Final Environmental (Impact) Statements (DES and FES) prepared by the NRC.
- 2 Supplements to the DES and FES.
- 3. Correspondence relating to the DES and FES.
- 4. Comments from other federal, state and local government agencies.
- 5 Transmittal and acknowledgement letters
- 6. Documents related to NRC review of environmental issues or of ER obtained for purposes of writing the environmental statements.
- 7. Backup technical documents submitted in connection with above.
- 8. Federal register notice citing availability of items 1 and 2.
- 9. Site visits to obtain information for DES or FES.
- Meeting announcements or reports of meetings where the primary subject of discussion is the DES or FES.

E. NRC SAFETY EVALUATION REPORT (SER), SUPPLEMENTS AND CORRESPONDENCE

This category is strictly limited to the items listed below. Other documents dealing with safety related issues are filed in categories A. P or W, depending on the phase of the licensing process.

- 1. Safety Evaluation Report (SER) prepared by the NRC (formerly called NRC-AEC Hazard Analysis Report)
- 2 Supplements to SER
- 3. Correspondence relating to SER
- 4 Federal register notices citing availability of items 1 and 2.
- 5. Information on scheduling of SER submittals and review.
- 6. Requests for additional information for use in preparing SER; responses to such requests.
- 7 Meeting announcements or reports of meetings where the primary subject of discussion is the SER
- 8. Transmittal and acknowledgement letters.

F. SECURITY, MEDICAL, EMERGENCY AND FIRE PROTECTION PLANS

All plans in this category are individual submissions. Information submitted as part of the PSAR or FSAR is excluded.

- 1. Fire Hazard Protection Plan and surveys.
- 2 Plant evacuation correspondence.
- 3. Safeguards Contingency Plans,
- 4. Review of Health Physics Program
- 5. Correspondence relating to aforementioned plans.
- 6. Supplements, changes and revisions to plans.

G. LEGAL AND ADJUDICATORY CORRESPONDENCE

This category contains all non-antitrust legal and adjudicatory documentation, except for transcripts, briefings and testimony, which are filed in category T.

- 1. Atomic Safety and Licensing Board (ASLB) and Atomic Safety and Licensing Appeal Board (ASLAB) hearing related documents.
- 2. Federal register notices regarding hearings.
- 3 Requests to make appearances at hearings.
- 4. Motions, briefs, arguments, statements and related correspondence filed by participants for hearings.
- 5. Transmittal of supporting documents (e.g., SER, FES) to the boards.
- Correspondence to and from intervenors.
- 7. Board orders and decisions.
- 8. Petitions for Commission action.
- 9. Legal filings and Commission orders and decisions resulting from item 8

H. GENERAL CORRESPONDENCE

This category includes documents with little or no bearing on the status of the application or license Items that have no substantive technical content or meaning for the status of the license or application are included

- 1. Change of address notifications
- 2. Changes in structure of organization
- 3. Changes in service lists.
- 4 NRC requests to applicant for additional copies of documents.
- 5. Correspondence from the public requesting information about the facility and NRC responses.
- 6. Correspondence on strictly administrative matters.
- 7. Letters of support, concern or opposition to the facility.
- 8. Correspondence regarding the Local Public Document Rooms (LPDRs)
- 9. Professional qualification statements not pertaining to the hearing process.

FINANCIAL INFORMATION

This category contains all financial information except that submitted as part of the application or its amendments or relating to the imposition of civil penalties.

- 1. Company annual reports.
- 2. Separately submitted financial information and related correspondence.

J. INSURANCE AND INDEMNITY INFORMATION

- 1. Indemnity agreements and amendments.
- 2. Endorsements insurance policies.
- 3. Other correspondence regarding indemnity and insurance matters.

K. UTILITY FINAL SAFETY ANALYSIS REPORT (FSAR) AND AMENDMENTS

This category is strictly limited to the items listed below. All related correspondence falls in category A or P.

- 1. Final Safety Analysis Report (FSAR) (formerly called Final Hazards Summary Report).
- 2. Amendments and changes to the FSAR.
- 3. Federal register notices citing availability of items 1 and 2.
- 4. Transmittal and acknowledgement letters.
- 5. Certificates of service to the FSAR.

L. LIMITED WORK AUTHORIZATION (LWA) AND RELATED CORRESPONDENCE

This category is limited to documents pertaining to Limited Work Authorizations (LWA) whereby applicants can carry out limited site preparation and construction prior to the granting of a construction permit

- Limited Work Authorizations (LWA) and amendments.
- 2 Correspondence pertaining to work performed under LWAs

M. ANTITRUST REVIEW AND ANTITRUST CORRESPONDENCE

- Document submitted as part of the applications for a construction permit and operating license entitled "Information Requested by the Attorney General for Antitiust Review"
- 2 Correspondence where the primary topic of discussion is antitrust matters.
- 3 All antitrust proceeding related documents except for hearing transcripts, testimony and briefings, which are filed in category N.

N. ANTITRUST HEARING TRANSCRIPTS, TESTIMONY AND BRIEFINGS

This category contains word-for-word transcripts of hearings, testimony and briefings in antitrust matters. Related correspondence falls in category M.

O. ADVISORY COMMITTEE ON REACTOR SAFEGUARDS (ACRS) REPORTS AND CORRESPONDENCE

- 1. Correspondence and letter reports relating to Advisory Committee on Reactor Safeguards (ACRS) reviews.
- 2. Correspondence from ACRS
- 3. Announcement of ACRS meetings.
- 4. Transmittal and acknowledgement letters.
- 5. ACRS reports.
- Statements and written testimony by ACRS members or presented by individuals at ACRS
 proceedings.
- 7. Minutes at ACRS Subcommittee Meetings.

P OPERATING LICENSE STAGE DOCUMENTS AND CORRESPONDENCE

This file assumes the position of the Application/Construction Stage (category A) file for general technical items dated from the issuance of the operating license to the application for termination of the license.

- 1. Operating license, amendments, proposed amendments, changes and related correspondence.
- 2. Technical specifications and changes.

- 3 Backup technical documents (e.g., topical reports) submitted in support of items 1 and 2.
- 4 Federal register notices citing availability of items 1 and 2
- 5. Correspondence regarding the Final Safety Analysis Report (FSAR)
- 6. All general technical correspondence, meeting announcements or meeting summaries relating to technical specifications, the operating license or technical issues arising after the issuance of the operating license.
- 7. Correspondence regarding codes (e.g., ASME), regulations, laws or changes in policy that may affect plant operation or bear on the operating license
- 8 Information on the Standard Review Plan (STP)
- 9 Results of surveys or tests conducted in accordance with the technical specifications (not periodic reports, which fall in category R).
- 10 Correspondence relating to NRC's Systematic Evaluation Program (SEP).
- 11. Owner's group meeting announcements and reports.
- 12 Quality assurance information.
- 13. Environmental matters (technical).
- 14. Emergency core cooling system documents.
- 15. Radioactive waste information.
- 16. Correspondence regarding expansion of spent fuel storage pool.
- 17. Start-up test reports
- 18 Correspondence and documentation on generic technical matters highlighted by an event at another facility which may affect the subject facility; not covered by an IE Bulletin.
- 19 Reports of site visits.

Q. INSPECTION REPORTS; IE BULLETINS, CIRCULARS AND INFORMATION NOTICES; CIVIL PENALTIES AND RELATED CORRESPONDENCE

- 1. Inspection reports.
- 2. IE Bulletins (formerly called Regulatory Operations (RO) Bulletins), Circulars and Information Notices.
- 3. Responses by applicant to IE correspondence.
- 4. Applicant's determination of proprietary nature of inspection reports.
- 5. Letters concerning areas of noncompliance.
- 6. Pre-service and in-service inspections and procedures.
- 7. Correspondence and orders relating to imposition and payment of civil penalties, including Notification of Significant Enforcement Actions (ENs).
- 8. Any correspondence relating to inspection and enforcements that does not specifically relate to incidents or events as defined in category S.

R. PERIODIC OPERATING REPORTS AND RELATED CORRESPONDENCE

This category includes periodic reports of a routine nature

- 1 Monthly, senuannual, or annual operating reports (other than financial).
- 2 Periodic environmental monitoring, effluent testing, or similar reports
- 3. Periodic personnel exposure reports.
- 4 Operational Logbooks.

Logbooks on Environmental Data Logbooks on Radiological Data Operations Log on Plant Systems Core Plant Status Summary Sheets

5 Correspondence or other documents relating to the above listed items

S. REPORTABLE OCCURRENCES, PNOs, PNSs AND RELATED CORRESPONDENCE

This category contains all materials relating to abnormal, unusual, reportable or nonroutine occurrences or events. This includes:

- 1. All 24-hour, 10-day, 30-day, interim and final Licensee Event Reports (LER's) and follow-up correspondence (also called incident reports, abnormal occurrence reports and reportable occurrences).
- 2. Potential or possible reportable deficiency reports and related correspondence.
- 3. Personnel exposure reports.
- 4 Construction deficiency reports submitted under 10 CFR 50 55e.
- 5. Preliminary Notification of Occurrence (PNOs) and Preliminary Notification of Safeguards Events (PNs).
- 6. Environmental Technical Specifications violation reports and Environmental Event reports.
- 7 Part 21 Reports of defects and noncompliance.
- 8. Correspondence or other documents relating to items 1-7.

T. TRANSCRIPTS, TESTIMONY AND BRIEFINGS ON NON-ANTITRUST MATTERS

This category contains all word-for-word transcripts, except for antitrust matters (category N), testimony and briefings, and congressional matters (category U).

- 1 Atomic Safety and Licensing Board (ASLB) and Atomic Safety and Licensing Appeal Board (ASLAB) transcripts.
- 2 Testimony and statements submitted to ASLB and ASLAB.
- 3. Commission meeting transcripts.
- 4. NRC staff briefings to the Commission.
- 5. Statements and written testimony submitted at Commission meeting or hearings.
- 6. Transcripts of utility briefs to NRC staff.
- 7. Advisory Committee on Reactor Safeguards (ACRS) meeting transcripts.
- 8. Corrections to above items.

U. CONGRESSIONAL/EXECUTIVE CORRESPONDENCE

This category contains correspondence on substantive matters. Routine responses to constituent inquiries are filed in category H

- Statements and testimony before Congress or before bodies/committees appointed by the Executive or Legislative Branches.
- 2 Preparatory and backup documents for item 1.
- 3. Correspondence to and from NRC Office of Congressional Affairs, Congress and the Executive Branch on other than constituent response matters

V. LICENSING OPERATORS AND RELATED CORRESPONDENCE

- 1 Operator licenses or administrative information bearing on licensing of operators.
- 2. NRC examination results
- 3 Power plant examination summary sheet.

W. DECOMMISSIONING STAGE DOCUMENTS AND CORRESPONDENCE

This file assumes the position of the Operating License Stage (category P) file for general technical items from the application for termination of the operating license onward

- 1. Application for authority to voluntarily surrender license.
- 2. Application to dismantle the facility and dispose of component parts.
- Technical documents submitted in support of items 1 and 2, such as: Decommissioning Plan, Dismantling Plan, Environmental Report on Dismantling, Safety Analysis Report on Decommissioning.
- 4 Documents relating to disposal of radioactive material and decontamination of the site.
- 5. Other correspondence relating to above items.
- 6. All documentation relating to the ongoing operation of the plan, formerly filed in category P.

X. ONSITE LOW-LEVEL WASTES STORAGE

This category contains items related to the onsite storage of low-level radioactive wastes generated onsite.

Y. INDEPENDENT SPENT FUEL STORAGE INSTALLATIONS (ISFSI)

This category contains documents with an NMSS license and/or a Docket-72 number. For installations on a reactor site, the associated Docket-50 number will also be identified.

- License applications, licenses, amendments and proposed amendments to possess power reactor spent
 fuel and other radioactive materials associated with spent storage in an independent spent fuel
 storage installation. (Such spent fuel storage installations may be on a reactor site or at a separate
 site.)
- All related correspondence and reports to the above.

APPENDIX B

DEFINITIONS OF NONDOCKETED CATEGORIES

10CFR - Commission Meeting Records

This category contains documentation pertaining to open and closed Commission meetings. It includes

- 1. Sunshine Act Federal Register notices.
- 2. Full, written explanation of closed meetings.
- 3. Certification of General Counsel on closed meetings.
- 4. Commission Determination Statements regarding the public disclosure of transcripts of Commission meetings.
- 5. Verbatim unofficial and official transcripts or portions of transcripts of open and closed Commission meetings made publicly available in accordance with provisions of 10CFR Part 9, the Sunshine Act, and Commission policies.
- 6. Enclosures to released transcripts, including applicable viewgraphs, staff papers, and staff correspondence.
- 7. Staff requirements memoranda for open meetings; memoranda to record; record of votes of Commissioners on items under consideration at meetings.

ACRS - Advisory Committee on Reactor Safeguards

This category contains documentation pertaining to the responsibilities of the Advisory Committee on Reactor Safeguards. ACRS serves as an independent advisory committee to the Commission in safety-related areas. The committee provides advice with respect to the hazards of new or existing nuclear facilities and the adequacy of related safety standards. The documents in this category are

- 1. Verbatim transcripts of ACRS subcommittee and full committee meetings relating to facility license applications and safety-related matters.
- 2. ACRS meeting announcements; description of meeting agendas.
- 3. ACRS-generated reports, memoranda and correspondence that are publicly available.
- 4. ACRS consultant reports, comments and related correspondence.
- 5. ACRS and NRC technical correspondence pertaining to safety matters under review by the Advisory Committee on Reactor Safeguards.

ADVCM - NRC Advisory Committees

This category contains documentation pertaining to the responsibilities of all NRC advisory committees, other than the Advisory Committee on Reactor Safeguards. The documents in this category are:

- 1. Charters of each advisory committee.
- 2. Verbatim transcripts of committee meetings.

- 3. Meeting announcements; description of meeting agendas.
- 4. Committee generated reports, memoranda, and correspondence that are publicly available.
- 5. Committee related correspondence.

COMMISSION - NRC Commissioners

This category contains documentation pertaining to the daily conduct of Commission business in the Office of the Commissioners, including

- 1. Incoming and outgoing correspondence to and from the Commissioners relating to official NRC business, including reports and other enclosures.
- 2. Travel vouchers, telephone logs and official appointment calendars of individual Commissioners.
- 3. Weekly Information Reports (SECY series number) prepared by the Executive Director for Operations (EDO) for the Commissioners, providing a summary of key events and items of interest undertaken by individual staff and program offices.

NOTE: For transcripts of Commission meetings, see 10CFR category. For all other staff papers with a SECY series designation prepared for Commission review, see SECY category.

CONTRACT - NRC Contracts and Modifications

This category contains documentation pertaining to AEC and NRC contracts and Interagency Agreements, including

- 1. Notifications of issuance of request for proposal (RFP) and invitations for bid (IFB).
- 2. Solicitations (RFP or IFB) issued by the NRC.
- 3. Notifications of contract execution, specifying contract number, project title, contractor name, contract type, funding, and period of performance.
- 4. Contractual documents and contract modifications, if any.

DISCLOSURE - Financial Disclosure Information

This category contains financial disclosure information in accordance with the Ethics in Government Act of 1978.

FOIA - Freedom of Information Act Requests and Releases

This category contains requests for agency records and records released in accordance with the provisions of the Freedom of Information Act (FOIA). Documents in this category include:

- 1. Requests made by any member of the public (assigned an identifying number YY-NNN for last two digits of the year numerical sequence) for NRC records made in accordance with the provisions of the Freedom of Information Act.
- 2. Correspondence between the NRC and the requester relevant to the processing, appeal, denial or granting of an FOIA request.
- 3. Records or portions of records released in response to specific requests made under FOIA.

GEN TECH IS - Generic Technical Issues

This category contains records pertaining to unresolved safety issues of a generic nature that are being analyzed by the Division of Nuclear Reactor Regulation.

- 1. Draft reports of action plans to accomplish generic tasks in the regulatory program.
- 2. Correspondence with industry and internal correspondence regarding the methodologies, analyses, and programmatic and technical aspects of issues.
- 3. Meeting notifications and minutes.
- 4. Interim findings and status reports on generic tasks addressing related aspects of generic technical issues.

I&E - Inspection and Enforcement

This category contains bulletins, circulars and information notices that are issued by the Office of Inspection and Enforcement. These issuances describe particular events that occur at a facility that may require some follow-up action on the part of licensees. Also included in this category are preliminary notifications of events (PNOs).

- 1. I&E Circulars, which describe an event at a licensed facility and are informational in nature.
- 2. I&E Information Notices, which are similar to circulars but are preliminary in nature and issued shortly after an event has occurred.
- 3. 1&E Bulletins, which describe an event at a licensed facility and request all recipients to perform certain actions as a result of this event.
- 4. Preliminary Notifications of Events (PNOs), which provide updated information of an event of safety or public interest significance.

NOTE: For letters forwarding the above issuances, utility responses to such issuances, and related correspondence, see Category Q of individual docket categories.

MISC - Public Document Room Miscellaneous

This category contains documents that do not fall into the scope of the other nondocketed categories.

NUREG - NUREG Reports and Related Correspondence

These documents are formal reports issued by the U.S. Nuclear Regulatory Commission which carry the NUREG series code and correspondence pertaining to those reports. NUREG reports are accounts of work performed either by the NRC staff or by NRC contractors.

- 1. These reports are normally final work products and are characterized by the following criteria:
 - They are predecisional documents which present information to be considered in Commission licensing and policy decisions.
 - b. They present the results of Commission licensing and policy decisions.
 - c. They present the results of technical research conducted for the Commission.
- 2. Correspondence from industry, government and interested members of the public commenting on reports or requesting clarification or interpretation.
- 3. Internal NRC memoranda summarizing meetings or discussions pertaining to the content of the reports.

ORG - Correspondence with Other Organizations

This category contains correspondence with professional organizations and associations; records other than Regulatory Guides that pertain to the activities of NRC's Office of Standards Development, and emergency petitions not assigned Petition for Rulemaking (PRM) numbers that request the Commission to take immediate action on some issue. Included are:

- 1. Meeting summaries and technical correspondence between NRC and professional associations and international bodies, such as the Atomic Industrial Forum and the International Atomic Energy Agency.
- 2. Correspondence between NRC's Office of Standards Development and other government agencies in which both parties have joint regulatory responsibility, e.g., EPA has authority to control all radioactive pollutants emitted into the air.
- 3. Internal memoranda, correspondence between NRC and Congress, and other technical correspondence dealing with the role and activities of the Office of Standards Development.
- 4. Statements, motions, orders and correspondence dealing with emergency petitions filed by parties on such topics as fire protection and re-analysis of the capacity of operating U.S. plants to withstand earthquakes.

NOTE For Regulatory Guides and comments to Regulatory Guides issued by the NRC Office of Standards Development, see the REGGD category.

For petitions for rule makings filed by the public to amend, rescind or change an NRC regulation, see the PRM category.

PR - Proposed Rule

This category contains records dealing with NRC staff proposals to adopt, amend or repeal a Commission regulation. Proposed Rules (PRs) are normally the result of a Commission determination that sufficient grounds exist for it to proceed with a petition for change in an NRC regulation (PRM) filed by an outside party or person. The documents in this category are:

- 1. Federal Register notices stating the terms or substance of the proposed rule or a specification of the subject and issues involved.
- 2. Text of the Proposed Rule (PR).
- 3. Comments, statements, information, opinions or arguments on the proposed change to a part of the Code of Federal Regulations, Title 10.
- 4. Requests from the nuclear industry, organizations and other parties for written interpretations of the PR.

PRM - Petition for Rulemaking

This category contains records dealing with petitions filed with the Commission by an outside party to issue, amend or rescind an NRC regulation. Included are:

- 1. Petitions filed by any interested person or party to issue, amend or rescind an NRC regulation.
- 2. Federal Register cause notices of the filing of the petition.

- 3. Correspondence between NRC and the petitioner regarding the status and substance of the petition.
- 4. Comments from the nuclear industry, professional associations, public interest groups and others in favor of or in opposition to the PRM.

NOTE: For staff recommendations to the Commissioners on whether the PRM should be denied or issued as a Proposed Rule, see the SECY category.

For Commission review of staff recommendations, see the 10CFR category.

PROJ - Projects-Predocket Licensing

This category contains records pertaining to two classes of projects (1) commercial nuclear power plants for which NRC has full licensing responsibilities, and (2) government-owned reactors for which NRC provides technical expertise and occasional review. Both classes are identified with a "P" prefix, followed by a series of numbers.

1. "Pre-docketed" commercial nuclear power plants

This category contains all documentation up until the time that the NRC considers the application and the Preliminary Safety Analysis Report (PSAR) is submitted by the utility for staff review. The unit is then assigned a docket number, and transferred to the Docket 50 category.

These documents are grouped together in categories, designated by alphabetic characters. These are the same categories as those used for the Docket 50 series.

- A. Application/Construction Stage
 - 1. Application submitted by the utility.
 - 2. Meeting notices, summaries and correspondence discussing the completeness and adequacy of the PSAR.
 - 3. Applicant's Quality Assurance Manual.
 - 4. Early site review information.
 - 5. Backup technical documents submitted in support of the application.
 - 6. Early site visits.
- B. Utility PSAR and Amendments
 - 1. PSARs submitted by the utility.
 - 2. Amendments and changes to the PSAR.
 - 3. Transmittal letters.
 - 4. Letters acknowledging receipt of the PSAR.
- G. Adjudicatory Correspondence
 - 1. Motions, briefs, orders, et al. pertaining to pre-hearing conferences, if any.
- M. Antitrust Correspondence
 - Submittals and related material pertaining to the antitrust review.

Q. Inspection Reports

- 1. Inspection reports of the applicant's quality assurance program.
- 2. Notices of deviations.
- 3. Follow-up correspondence resolving deviations cited.

2. Government-owned reactors

Meeting summaries and technical correspondence between NRC and other government technical personnel related to test reactors, critical experiments, and DOD reactors on navy ships and other sites.

PT21 - Noncompliance Reports and Related Correspondence

Deficiency reports are performed in compliance with Part 21 of Title 10 of the Code of Federal Regulations and include:

- 1. Reports by firms involved in the nuclear industry concerning noncompliance with NRC regulations or the existence of defects which could create a substantial safety hazard.
- 2. Correspondence pertaining to the NRC review of reports to assess the possibility of generic defects.
- 3. NRC inspection reports of defects cited.
- 4. Correspondence specifying appropriate follow-up actions taken by the Agency.

QA999 - Quality Assurance Inspections

This category contains inspection reports of vendors' quality assurance programs and follow-up correspondence. Each vendor facility is assigned a docket number and is part of the QA999 series.

Vendors are defined here as companies, both U.S. and foreign, that are engaged in the design or the manufacture of nuclear components for plants licensed by NRC. QA comprises all those planned and systematic actions necessary to provide adequate confidence that a structure, system or component being manufactured will perform satisfactorily once it is put in service. The controlling criteria are 10 CFR Part 50, Appendix B, vendor QA topical reports, and the PSAR and FSAR submitted by utilities for specific facilities. Documents in this category include:

- NRC inspection reports, conducted on a quarterly or semi-annual basis, of vendor sites. Inspections may cover the design, fabrication, construction and testing of structural systems and components.
- 2. Notices of deviations.
- 3. Vendor corrective actions and other follow-up correspondence associated with the resolution of inspection findings.

REGGD - Regulatory Guides

This category contains new and revised regulatory guides issued by the Commission and related correspondence. These guides describe for the industry and the public methods acceptable to the NRC staff for implementing specific parts of the NRC's regulations. They also delineate techniques used by the staff in evaluating specific problems or postulated accidents, or provide guidance to applicants. Included are:

- 1. Federal Register notices announcing the issuance and availability of a proposed regulatory guide.
- 2. Revised or newly issued Regulatory Guides.
- 3. NRC value/impact assessment and industry codes, when applicable, that pertain to the issuance of a specific Regulatory Guide.
- 4. Comments submitted by the nuclear industry and interested members of the public regarding a proposed Regulatory Guide.
- 5. Summary of meetings held in the NRC to discuss proposed Regulatory Guides.

NOTE: For documentation pertaining to other work products and activities of the NRC Office of Standards Development, see the Organization category.

RES - Research and Technical Assistance Reports

This category contains reports, generally of an interim nature, submitted by NRC contractors providing research and technical assistance to the Commission. It also includes documentation pertaining to research activities of the Commission. Included are:

- 1. Project description documents.
- 2. Letter reports of accomplishments and data reports; for example,
 - a. model documentation reports
 - b, code documentation reports
 - c. code verification reports
- 3. Pre-test prediction reports.
- 4, "Quick look" reports.
- 5. Informal experimental data reports and post-irradiation examination analyses.
- 6. Conceptual design descriptions.
- 7. Letter reports of foreign travel and site visits by contractors.
- 8. Letter, monthly, quarterly, interim or annual status or progress reports on other research projects contracted for by the NRC.
- Meeting summaries and correspondence dealing with technical matters relating to research and technical assistance contracts.
- 10. Staff Research Information Letters (RILs) transmitting the documented results from completed research programs.

NOTE: For final reports of research conducted by contractors, see also NUREG reports.

REVIEW GRP - NRC Research Review Groups

This category contains records pertaining to the activities of NRC Research Review Groups. Such groups provide a broad base of technical expertise to aid management in reviewing research in

defined technical areas. They review and comment on research plans and predicted results of major experiments, the validity and applicability of research results, the possible redirection of research projects, new research projects, and priorities within the technical areas covered by the research review group. Documents in this category are:

- 1. Agendas for quarterly review group meetings.
- Summary minutes of review group meetings representing views expressed, including dissenting views.
- 3. Research plans and predicted results of major experiments; presentations by research contractors.
- 4. Comments on meetings from attendees, including representatives from contractors, universities, vendors and other agencies.
- 5. Internal memoranda relating to topics under discussion.

RM - Rulemakings

This category contains records pertaining to public hearings held on proposed changes (PRs) to the Commission's regulations. Hearings are instituted at the discretion of the Commission based on the importance and the magnitude of the subject under consideration. Documents in this category include:

- Designations of the presiding officer and any special directions for the conduct of the hearing.
- 2. Notifications of hearing board meetings.
- 3. Petitions, motions, testimony and statements submitted by parties to the hearings.
- 4. Hearing board orders and rulings.
- 5. Technical reports submitted as evidence in the proceeding,
- 6. Reports, if any, of the special board to the Commission regarding a rulemaking proceeding.

SECY - Position Papers Before the Commission

This category consists of staff papers prepared for the information or approval of the Commissioners which are assigned a SECY report series code. Included are:

- 1. Commission Action papers, which normally include alternatives and recommendations by the staff on a given issue and require Commission action.
- 2. Consent Calendar items and Policy Session items.

NOTE: For Weekly Information Reports prepared by EDO to the Commissioners providing a summary of key events and items of interest undertaken by staff and program offices, see the NRC Commissioners category.

STATE PROG - State Programs

This category contains records that pertain to the Commission's activities and interaction with State governments. Areas covered include: (1) the State Agreements Program, whereby States may assume certain of the NRC's regulatory authority over nuclear materials; (2) the Agency's role in assisting

State and local governments in planning responses to radiological emergencies; and (3) a wide range of liaison and cooperative activities regarding such functions as licensing and siting. It includes:

- Correspondence between and among NRC Office of State Programs and State officials, mostly State liaison officers, regarding:
 - a. cooperative programs in such technical areas as radiation control, emergency response planning to radiological incidents, water quality and transportation surveillance.
 - b. technical assistance to Agreement States in reviewing applications, compliance actions, developing regulations, and other areas.
- 2. Agendas, reports and transcripts of regional workshops and training programs on current matters of policy and regulations; i.e. decommissioning and facility siting.
- 3. State Legislative Reports.
- 4. Agreement State Licensing Statistics Reports.

NOTE: For specific uranium milling and mining projects in which the Agency is providing technical assistance to States, see the Projects category.

TOPREP - Vendor Reports and Related Correspondence

This category contains topical reports, generally of a technical generic nature, submitted by vendors, and correspondence pertaining to the NRC review of these reports. General vendor related correspondence that is not docket specific is also included in this category.

- 1. Topical reports, dealing with such technical matters as specifications, testing and safety submitted by architect, engineers and other vendors.
- 2. Revisions, modifications and amendments to topical reports.
- 3. Correspondence between NRC and vendors pertaining to the review of submittals.
- 4. Meeting agendas, summaries, minutes and correspondence pertinent to vendor activities, programs, methodologies and design criteria.

NOTE: For reports submitted by utilities that are written by vendors on their behalf and that relate to docketed cases, see the categories for the Docket 50 series.

WASTE MGT - Nuclear Waste Management

This category is topical in nature and contains records dealing with the activities of the NRC Division of Waste Management. Each topic has been assigned a number, with the series designated by a WM prefix. These documents deal primarily with NRC's interaction with DOE and its future role in licensing and regulating DOE facilities designed for the disposal of high-level waste in geologic repositories. This category will be enlarged later to include records dealing with low-level waste issues and tasks. The documents in this category are:

- 1. Meeting agenda and minutes of DOE/NRC meetings in which DOE presents information on their geological exploration program to identify sites for nuclear waste repositories.
- 2. Briefings by DOE on research being conducted on spent fuel storage and nuclear waste management.

- 3. Correspondence pertaining to NRC's advisory role in providing DOE with technical assistance in the Waste Isolation Pilot Plan (WIPP) for burial of defense wastes.
- 4. NRC draft staff guides for developing positions on the content and format of environmental reports for geological repositories.

XPORTLIC - Export and Import Licenses

This category contains records relating to the issuance of licenses to export or import nuclear facilities and materials. Included are:

- 1. License applications and amendments to export or import special nuclear material, source material, byproduct material, reactors, nuclear facility components or reactor materials.
- Correspondence between NRC and applicant or licensee pertaining to the review or status
 of a pending application or license amendment.
- 3. Commission letters requesting Executive Branch views.
- 4. Review and findings of the Executive Branch on whether issuance of a license would be inimical to U.S. common defense and security.
- 5. Correspondence from foreign governments, international organizations, and members of the public.
- 6 Staff position papers (SECY series code) prepared for Commissioners review of import or export licenses.
- 7. Filings pursuant to hearing requests or intervention petitions, if any.
- 8. Hearing records and decisions.
- 9. Memoranda from the Office of the Secretary to the Executive Director for Operations regarding the Commission decision on issuance of a proposed license.
- 10. Licenses, license amendments and license renewals for types specified in item 1

NOTE. For transcripts of Commission meetings and papers submitted for Commissioner consideration or information, see 10CFR category.

NRC FORM 335 U.S. NUCLEAR REGULATORY COMMISSION		1 REPORT NUMI NUREG-054	BER (Assigned by DDC)
BIBLIOGRAPHIC DATA SHEET		Vol. 5, N	
4 TITLE AND SUBTITLE (Add Volume No., if appropriate)		2 (Leave blank)	
Title List of Documents Made Publicly Avai	lable		
June 1-30, 1983	3 RECIPIENT'S ACCESSION NO		
7. AUTHOR(S)		5 DATE REPORT	COMPLETED
		MONTH	YEAR
9. PERFORMING ORGANIZATION NAME AND MAILING ADDRESS (Inc.		DATE REPORT	
Division of Technical Information and Docum Office of Administration	ment Control	MONTH August	YEAR 1983
U.S. Nuclear Regulatory Commission		6 (Leave blank)	120.1
Washington, DC 20555		8 (Leave blank)	
12. SPONSORING ORGANIZATION NAME AND MAILING ADDRESS (Inc.	clude Zin Code!	8 (Leave trank)	
	the try code,	10 PROJECT/TAS	K/WORK UNIT NO
Same as 9, above.		11 FIN NO	
13. TYPE OF REPORT			
Monthly		ED (Inclusive dates)	
Pontity	, , , , , ,		
15. SUPPLEMENTARY NOTES		14. (Leave plank)	
This document is a monthly publication cont received and generated by the U.S. NRC. The material associated with civilian nuclear particles active materials, and (2) nondocketed mater pertinent to its role as a regulatory agency Personal Author Index, Corporate Source Index. Reference to Principal Documents Index.	is information ower plants and ial received a y. The follow	includes (1) d other uses nd generated ing indexes a) docketed of radio- by NRC are included:
17. KEY WORDS AND DOCUMENT ANALYSIS	17a DESCRIPTORS		
7b. IDENTIFIERS/OPEN-ENDED TERMS 8 AVAILABILITY STATEMENT		CLASS (This report)	21 NO OF PAGES
	Unclas	sified	22 PRICE
Unlimited	linclas	CLASS (This page) Sified	S S